AUG 1 3 1980
J 321-604
Cap. 188
431-A-5
TD4.36: 980
9336

SUMMARY OF
SUPPLEMENTAL TYPE CERTIFICATES

9/3/80

APRIL 1980

#2576201
CAT/REV
EB 4/15/81
7337509

DEPARTMENT OF TRANSPORTATION

FEDERAL AVIATION ADMINISTRATION

L
/98

SUMMARY OF
SUPPLEMENTAL TYPE CERTIFICATES

APRIL 1980

DEPARTMENT OF TRANSPORTATION

FEDERAL AVIATION ADMINISTRATION

Airplanes & Parts

PREFACE

Part 21 of the Federal Aviation Regulations provides for the issuance of supplemental type certificates to persons who make major changes in a previously approved type design when the change is not so extensive as to require a new type certificate. This summary lists those supplemental type certificates (STC) issued which the holders have indicated design rights, data, parts or kits will be made available to others. Information on any of the items listed can be obtained by contacting the supplemental type certificate holder or the certificating region's Engineering and Manufacturing office.

After a supplemental type certificate is issued for a particular change, others may duplicate the alteration provided it is done in accordance with the approved data. Supplemental type certificates listed herein as applicable to a given model aircraft may not be compatible with one another or with other approved alterations. Before duplicating an alteration on a previously altered aircraft, and when incorporating several alterations simultaneously, determine that the alterations are compatible with one another and will have no adverse affect on the airworthiness of the aircraft. Refer to FAR Part 43 Maintenance, Preventive Maintenance, Rebuilding and Alteration for rules governing the return to service and approval for return to service of products altered by incorporating an STC.

The publication contains three sections identified as: (1) Aircraft, (2) Engines, and (3) Propellers. These sections, arranged alphabetically by manufacturer's name, contain information on STC's approved for a specific make and model type certificated product. Some of the STC's are listed as applying to a series of aircraft, engine or propeller. In these cases, it is necessary to contact the STC holder or the certificating region to determine the exact models included. A fourth section, Miscellaneous, contains information on STC approval of appliances. This section is arranged by STC number in ascending order.

The page layout and content is arranged as follows:

Column 1 - Identifies the aircraft's model and type certificate number for which the supplemental type certificate (STC) was issued.

Column 2 - Lists the identifying number assigned the supplemental type certificate.

Column 3 - Provides a brief description of the modification.

Column 4 - and

Column 5 - Contains coded information necessary for ADP processing of the STC data. RG identifies the FAA certificating region, and the STC code is a special numeric designator assigned each STC holder.

Column 6 - Identifies the individual or organization to whom the STC was issued. Anyone desiring further information on the STC should contact the STC holder.

Addresses for the controlling regions in which the technical data are filed are as follows:

AL - Alaskan Region

Department of Transportation
Federal Aviation Administration
P. O. Box 14
Anchorage, Alaska 99513

CE - Central Region

Department of Transportation
Federal Aviation Administration
601 East 12th Street
Kansas City, Missouri 64106

EA - Eastern Region

Department of Transportion
Federal Aviation Administration
Regional Office, Federal Building
JFK International Airport
Jamaica, New York 11430

EU - European Region

Department of Transportation
Federal Aviation Administration
c/o American Embassy
APO New York 09667

GL - Great Lakes Region

Department of Transportation
Federal Aviation Administration
2300 East Devon Avenue
Des Plaines, Illinois 60018

NE - New England Region

Department of Transportation
Federal Aviation Administration
12 New England Executive Park
Burlington, Massachusetts 01803

NW - Northwest Region

Department of Transportation
Federal Aviation Administration
9010 East Marginal Way, South
Seattle, Washington 98108

PC - Pacific Region

Department of Transportation
Federal Aviation Administration
P. O. Box 50109
Honolulu, Hawaii 96850

RM - Rocky Mountain Region

Department of Transportation
Federal Aviation Administration
10455 East 25th Avenue
Aurora, Colorado 80010

SO - Southern Region

Department of Transportation
Federal Aviation Administration
P. O. Box 20636
Atlanta, Georgia 30320

SW - Southwest Region

Department of Transportation
Federal Aviation Administration
P. O. Box 1689
Fort Worth, Texas 76101

WE - Western Region

Department of Transportation
Federal Aviation Administration
P. O. Box 92007
World Way Postal Center
Los Angeles, California 90009

WA - Washington, D. C.

Department of Transportation
Federal Aviation Administration
800 Independence Avenue, S.W.
Washington, D.C. 20591

050-011-81002-1

43^{00}
53^{75}

AIRCRAFT

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AEROMERE S.A.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F8L; T.C. 7A11	SA308EA	Installation of A.P.P. Industries, Inc., carburetor ice detection system Model 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
F8L; T.C. 7A11	SA489EA	Installation of carburetor ice detection system Model 107AP-12 or 107AP-24 manufactured by A.P.P. Industries, Inc. in single and twin engine aircraft and single engine heliocpters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
AERONAUTICA MACCHI S.p.a.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AL 60; T.C. 7A12	SA38WE	Fluidyne 3000 nose ski and 4000 Mark II main skis.	WE	51975	Lockheed Aircraft Int'l., Inc. 510 W. 6th Street Los Angeles, CA 90052
AL 60; T.C. 7A12	SA224WE	Heated pitot head and larger capacity battery, new battery box, and external power receptacle.	WE	51975	Lockheed Aircraft Int'l., Inc. 510 W. 6th Street Los Angeles, CA 90052
AL 60; T.C. 7A12	SA591WE	Holes in bottom of aircraft for camera and driftmeter for aerial photography.	NW	11315	Angeles Flying Service RFD 3, Box 382 Port Angeles, WA 98362
AL60-C5, AL60-F5; T.C. 7A12	SA1864WE	Installation of Edo Model 4580 floats.	NW	46400	Jobmaster Company, Inc. 1005 W. Perimeter Road Renton, WA 98005
AL-60-F5; T.C. 7A12	SA2820SW	Operation with right door removed removed for parachute jumping. Issued 7/21/78.	SW	43457	Jack A. Hurst Route 1, Rockhill Road Hurst, TX 75069

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
AERONAUTICA MACCHI & AERFER-INDUSTRIE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AM-3; T.C. A19EU	SA2820SW	Operation with right door removed for parachute jumping. Issued 7/21/78.	SW	43457	Jack A. Hurst Route 1, Rockhill Road Hurst, TX 75069

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AERONCA, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C-2; T.C. 351	SA204EA	Continental A40-3 engine S/N 664.	EA	16755	Samuel P. Bigony 994 Hale Street Pottstown, PA 19464
C-2, C-3 Series; T.C. 351, 396	SA286WE	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
C-2 Standard, C-2 Scout, PC-2; C-3, PC-3; 60-TF; O-58B; 15AC, S15AC; ATC 351, 396, T.C. 728, 751, 802	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C-2 Standard, C-2 Scout, PC-2, PC-3, C-3, 60-TF, O-58B, 15AC, S15AC; T.C. 351, 396, 728, 751, 802	SA2666WE	Ceconite 102 material covering of: C-2 series - wings, elevators, horizontal stabilizer and rudder; C-3, PC-3 - complete aircraft; 60-TF - wings; O-58B - wings, fuselage, ailerons, elevators and rudder; 15AC, S15AC - fuselage, vertical fin, horizontal stabilizer, elevator, rudder, ailerons, and landing gear vees. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C-3, PC-3; T.C. 396	SA4-1409	Eonite covering of wings and fuselage.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
C-3, PC-3, 15AC, S15AC, 50TC, 60TF, 65TC, 65TF, 50TL, 65TL, 65TAC, 65TAF, 65TAL, YO58; T.C. 396, 802, 728	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
C-3, LC; T.C. A-396, ATC 614	SA1008WE	Installation of Poly-Fiber covering material (complete aircraft). Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
50TC, 50TL, YO50, 60TF, 65TAC, 65TAF, 65TAL, 65TC, 65TF, 65TL; 15AC, S15AC; T.C. 728, 802	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92509
50-TC, 60-TF, 65-TC, 15AC; T.C. 728, 802	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
50TC, 65TC, 60TC, 65TF, 60TF, 50TL, 65TL, 65TAC, 65TAF, 65TAL; 058A, B, SO-58B; 15AC, S15AC; T.C. A-728, A-751, A-802	SA308EA	Installation of carburetor ice detection system Model 105AP manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred P. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
50TC, 60TC, 65TC, 65TF, 60TF, 50TL, 65TL, 65TAC, 65TAF, 65TAL; O58A, B, SO-58B; 15AC, S15AC; T.C. A-728, A-751, A-802	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-25 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetor. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
t+1 50, 60, 65; 058; 15AC, S15AC; T.C. A-728, A-751, A-802	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

AERONCA, INC. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50, 60, 65T; 15AC: T.C. 728, 802	SA1350WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
60-TF; T.C. 728	SA4-1104	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
O-58B, S/N 058B1012 and up; T.C. A-751	SA132GL	Install metal wing ribs. Issued 8/13/76.	GL	18060	Eric J. Brown 2008 East 121st Street (#320) Burnsville, MN 55337
O-58B; T.C. 751	SA176WE	Ceconite 101 covering of wings, fuselage, ailerons, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
O-58B; T.C. 751	SA220EA	Removal of door for parachute jumping.	EA	73942	Bart Spadaro Montauk Highway East Moriches, NY 11940
15AC; T.C. 802	SA4-567	Glass cloth over fuselage, vertical and horizontal stabilizers.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
15AC; T.C. 802	SA4-1593	Removal of door for parachute jumping and aerial photography operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
15AC; T.C. 802	SA302NW	Install Lycoming O-360 engine and Hartzell prop engine mount and fiberglass cowling. Reissued 4/27/78.	NW	60096	Monohan Aircraft, Inc. 2311 East Lake Sammamish Pl., S.E. Issaquah, WA 98027
15AC Landplane or Seaplane; T.C. A-802	SA306GL	Installation of Lycoming O-360-A1F6D and Hartzell Model HC-C2YK-1BF/F7666A-2 propeller on aircraft previously modified in accordance with STC SA302NW, using the existing installation hardware and components. Issued 5/7/79.	GL	84890	Weber's Aero Repair, Inc. Municipal Airport Alexandria, MN 56308
15AC; T.C. 802	SA424AL	Installation of seat belt attachments. Issued 4/19/71.	AL	60185	Robert J. Morrison P.O. Box 356 Chugiak, AK 99567
15AC; T.C. 802	SH552NW	Install cargo hook electronic scale. Issued 1/4/78.	NW	73067	Marvin Smith 5503 West Flowing Lake Road Snohomish, WA 98290
15AC, S15AC; T.C. 802	SA3-423	CT-3000 tail ski on airplanes equipped with Scott Model 3200 or or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
15AC, S15AC; T.C. 802	SA3-725	Prentics Aircraft lift strut fitting 61-16-1.	GL	33248	Ellington Aircraft Salvage East Broadway Walbridge, OH 43465
15AC, S15AC; T.C. 802	SA3-731	Replacement part upper and lower wing strut fittings.	GL	49330	Lake of the Woods Flying Service Baudette, MN 56623
15AC, S15AC; T.C. A-802	SA4-1290	Ceconite 101 covering of fuselage vertical fin, horizontal stabilizer, elevator, rudder, ailerons and landing gear Vees.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
15AC, S15AC: T.C. A-802	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
15AC, S15AC: T.C. 802	SA548CE	Installation of Continental IO-346-B engine with Hartzell HC-C2YF-1A/7663 constant speed. Amended 7/15/76.	GL	46784	W.L. Johnson, Jr. 7721 Driftwood, S.E. Grand Rapids, MI 49506

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
AEROSPATIALE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Alouette III Series; T.C. H1IN	SH752NW	Installation of a weighing system. Issued 4/12/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SE.3160 Alouette III; T.C. H1IN	SH434AL	Installation of Alaskan Sky-Craft cargo baskets. Issued 6/10/71.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
SE.3160, SA.316B, SA.316C, SA319B; T.C. H1IN	SA1243SW	Eastern rotorcraft cargo hook AK25LT. Reissued 1/4/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SE.3160 Alouette III; T.C. H1IN	SH1791SW	Foxtronics/Tramm BTI-600 nickel cadmium battery temperature. Issued 1/30/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
SE 3160 Alouette III, SA 316B Alouette III; T.C. H1IN	SA1320SW	External cargo baskets. Issued 6/1/71.	SW	84300	Vought Helicopter, Inc. 1507 Pacific Avenue Dallas, TX 75201
SE.3160 Alouette III, SA.316B Alouette III; T.C. H1IN	SH1490SW	AiResearch 92757 environmental control system. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160 Alouette III, SA.316B Alouette III; T.C. H1IN	SH1800SW	Install reclining passenger seat in forward left hand position. Issued 2/1/74.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SE.3160, SA.315B, SA.316B; T.C. H1IN	SH1471SW	Engine inlet sound suppresors. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.315B, SE316 Series; T.C. H1IN	SH437NW	Incorporation of weighing system for external load operations. Amended 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
SE3160, SA316B, SA319B; T.C. H1IN	SH71NW	Installation of electric weighing system. Amended 11/7/75.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
SE.3160, SA.315B, SA.316B, SA.319B, SA316C; T.C. H1IN	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SE.3160, SA.316B, SA.316C; Alouette III; T.C. H1IN	SH1900SW	Non-stowable litter kit. Issued 7/24/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1307SW	Eastern Rotorcraft cargo hook and H-frame. Reissued 1/4/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1318SW	Removable cabin step. Issued 10/2/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1320SW	External cargo baskets. Reissued 7/1/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319C; T.C. H1IN	SH1385SW	Replace existing landing light and anti-collision light. Reissued 9/30/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA315B; T.C. H1IN	SH61NW	Installation of electric weighing system. Amended 5/5/76.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
SA315B; T.C. H1IN	SH267NW	Installation of Simplex Model 3400 3400 spray system. Issued 6/16/76.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
SA315B; T.C. H1IN	SH268NW	Installation of automatic flagman Model #5. Issued 3/18/76.	NW	03500	Air Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
SA315B; T.C. H1IN	SA429NW	Installation of Simplex Model 4206 4206 aerial spray system. Issued 4/11/77.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA315B; T.C. H1IN	SH540NW	Install onboard weighing system. Issued 1/9/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA.315B; T.C. H1IN	SH695NW	Installation of Model 2512 weighing system. Issued 12/14/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA.315B; T.C. H1IN	SH1735SW	H-frame external cargo hook. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.315B Alouette III; T.C. H1IN	SH1909SW	Replacement of existing landing light and anti-collision light. Reissued 9/30/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.315B; T.C. H1IN	SH2425SW	Installation of low range airspeed indicator and pitot pressure surge chamber. Issued 3/4/77.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
SA.316B Alouette III; T.C. H1IN	SH168WE	Installation of Nightsun SC-16C searchlight. Issued 8/28/74.	WE	74500	Spectrolab Division of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
SA.316B Alouette III; T.C. H1IN	SH647NW	Installation of cargo baskets. Issued 8/3/78.	NW	44032	Inland Helicopters 2660 Vine Street Grants Pass, OR 97526
SA.316B, SA.316C, SA319B; T.C. H1IN	SH223WE	Installation of tail rotor floodlight. Issued 9/12/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
SA-360C; T.C. H8EU	SH2962SW	Blade bolt balance pin adapter. Issued 3/23/79.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
SA360C; T.C. H8EU	SH4051SW	Modification of lower cabin plexiglass panels. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C, SA-365C; T.C. H8EU, H10EU	SH1179EA	Installation of DeVore tail floodlight on upper surfaces of horizontal stabilizer. Issued 1/8/80.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
SA.365C; T.C. H10EU	SH2987SW	External markings. Issued 4/23/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA-365C; T.C. H10EU	SH4050SW	Twelve-place interior with forward facing seats. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA365C; T.C. H10EU	SH4052SW	Modification of lower cabin plexiglass panels. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AIR & SPACE MANUFACTURING, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18A, T.C. 1H17	SH13CE	Change nose landing gear cylinder and piston. Reissued 3/8/74.	SC	34600	Farrington Aircraft Corporation P.O. Box 9 Paducah, KY 42001
18A; T.C. 1H17	SH14CE	Install variable pitch control system. Issued 12/8/71.	SC	34600	I.D. Farrington 1101 Broadway Paducah, KY 42001
18A, T.C. 1H17	SA104GL	Installation of 0.6 second time delay circuit in side-slip warning system. Issued 1/13/76.	SC	34600	Farrington Aircraft Corporation P.O. Box 9 Paducah, KY 42001
18A; T.C. 1H17	SH156GL	Installation of Hartzell HC-C3Y (K,R)-1BLF/FL7663()-4R propeller. Issued 3/7/77.	SO	34600	Farrington Aircraft Corp. P.O. Box 9 Paducah, KY 42001
18A; T.C. 1H17	SH293GL	Modification of rotor hub drag link. Issued 2/13/79.	GL	34602	Farrington Aircraft Corporation c/o Crown Tool Company 1990 Berwyck Dayton, OH 45414
18A; T.C. 1H17	SH317GL	Removal of cabin door for flight Reissued 9/12/79.	GI	34602	Farrington Aircraft Corporation 1990 Berwyck Avenue Dayton, OH 45414

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AIRCRAFT PARTS & DEVELOPMENT CORP.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A Series; T.C. 758	SA4-302	EN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
A Series; T.C. 758	SA4-1422	Ceconite 101 covering of entire airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
A Series; T.C. 758	SA4-1193	Continental C-145-2 engine and Sensenich 76JC48 or McCauley 1A170 propeller.	RM	59780	Missoula Aerial Service P.O. Box 1158 Missoula, MT 59801
A Series; T.C. 758	SA4-1493	Aluminum hopper.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1494	Fuselage tube structure modification and installation of new overturn structure.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1503	Increase maximum gross weight to 1,835 pounds with Continental W670-6A engine, Sensenich 90LA78 propeller and associated modifications.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1594	Wing fuel tanks. (Restricted category only.)	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1632	Wheels, brakes, rudder pedals and brake cylinders modification.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1633	Hopper.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A, A2, 3, 4, 5, 5T, 6, 9; A-9A T.C. A-758, A4WE	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system Model 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SP, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
A, A2, 3, 4, 5, 5T, 6, 9; T.C. A-758	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine FAR 23/CAR 3 aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
A, -2, -3, -4, -5, -6; T.C. 758	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A, A-2, A-3, A-4, A-5, A-6; T.C. 758	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A; A-9A; T.C. A-758, A4WE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
A-3; T.C. 758	SA1008WE	Poly-Fiber covering of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Coatings 43rd South Fort Drive Box 3084 Riverside, CA 92519

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A-9; T.C. A4WE	SA765SW	Modified McCauley 2D34CT69/84HF-0 propeller and governor installed.	SW	85700	Whiteface Aviation Company Drawer 433 Hereford, TX 79045
A-9, A-9A, T.C. A4WE	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
A-9, -9A, -9B; T.C. A758, A4WE	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	3350	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
A-9, -9A, -9B; T.C. A-758, A4WE	SA693CE	Install AC induction air filter type AAF-104. Amended 5/4/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
A-9, A-9B Series; T.C. A-758	SA1743WE	Installation of Automatic Flagman (Marker Dispensing Unit).	NW	03500	Air-Ag, Inc. Route 4 Walla Walla, WA 99362
A-9, A-9B (Restricted Category Only); T.C. A-758	SA2334WE	Installation of Jacobs R755-A2M or R755-SM engine, JAS engine mount, Grumman SR-5404/MA96F-2 propeller and associated equipment. Amended 5/19/72.	WE	46790	Johnston Aircraft Service P.O. Box 757 Tulare Air Park Tulare, CA 93274
A9B; T.C. A-758	SA98RM	Install a Hartzell Model HC-C3YR-1RF/F8468A-6R propeller per Hi-Country Aviation installation instructions, approved 5/10/77. Reissued 4/12/79.	SW	05765	Aircraft Parts & Development Corp. P.O. Box 1849 Laredo, TX 78041

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
AIR PARTS, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
FU-24; T.C. 4A12	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AIR TRACTOR, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AT-300; T.C. A9SW	SA265NW	Installation of automatic flagman Model #4. Issued 3/2/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
ALLIANCE AIRCRAFT CORP.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Alliance Argo A; ATC 178	SA213EA	Install new engine and propeller.	NE	23600	Edward W. Cochran 162 Whipple Road Esmond, RI 02917

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AMERICAN EAGLECRAFT COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
American Eaglet A-31-1B; T.C. 2-583	SA204WE	Continental A-65-8F engine and Sensenich M74CK-2 propeller.	NW	73940	John Spach 11015 Airport Road Everett, WA 98201
B-31: A.T.C. 450	SA1008WE	Poly-fiber covering of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Coatings 43rd South Fort Drive P.O. Box 3084 Riverside, CA 92519

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ANDERSON, GREENWOOD & COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
14; T.C. 4A1	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
14; T.C. 4A1	SA1379WE	Continental O-200-B engine.	WE	43245	Mr. L.W. Hubert P.O. Box 865 Shafter, CA 93263
51; T.C. A11SW	SA3226SW-D	Installation of Mitchell automatic flight system AK700 consisting of Century IV autopilot or AK700 FD consisting of Century IV flight director autopilot with remote annuciator. Issued 7/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ARCTIC AIRCRAFT COMPANY, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA-1A Series; T.C. 737, 754	SA4-289	EN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92509
SA-1A Series; T.C. 737, 754	SA4-1514	Ceconite 101 covering of entire airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SA-1A, A-1A-65F, -85F, -90F; T.C. 737	SA4-1210	Installation of Connex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Fonair, Inc. 417 Watts Drive Bakersfield, CA 93307
S-1A, S1A-65F; S-1B1; T.C. A-737, A-754	SA308EA	Installation of A.R.P. Industries, carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 10/31/75.	EA	65332	Alfred P. Puccinelli 3DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
S-1A, S1A-65F; S-1B1; T.C. A-737, A-754	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred P. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
S-1A, -1A-65F, -85F, -90F; T.C. 737	SA573AL	Install Cleveland wheel assembly 40-28 and Cleveland brake assembly 30-18. Issued 3/31/76.	AL	11610	Arctic Aircraft Company P.O. Box 6141 Anchorage, AK 99502
S-1A, S-1B1, -65F, -85F, -90F; T.C. 737	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Callair, Interstate) S-1A, S-1A-65F, -85F, -90F, S-1B1 (Army L-6, XL-6); T.C. 737, 754	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S-1B1; T.C. A-754	SA415AL	Application of dacron fabric as exterior covering material. Amended 6/4/71.	AL	11610	Arctic Aircraft Co., Inc. P.O. Box 6141 Anchorage, AL 99502
S-1B1; T.C. A-754	SA468AL	Installation of United Airmotive Inc. model 25-A skis. Issued 1/5/72.	AL	11610	Arctic Aircraft Co., Inc. P.O. Box 6141 Anchorage, AL 99502
S-1B1; T.C. A-754	SA574AL	Install Cleveland wheel assembly 40-28 and Cleveland brake assembly 30-18. Issued 3/31/76.	AL	11610	Arctic Aircraft Company P.O. Box 6141 ANchorage, AK 99502
S-1B1 (Army L-6); T.C. 754	SA1008WE	Installation of poly-fiber covering material of fuselage and empennage. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
ARMSTRONG WHITWORTH AIRCRAFT LTD., SIR W.G.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Argosy Type A.W. 650; T.C. 7A9	SA125EA	Smiths flight instrument system alteration.	EA	19846	Capitol Airways, Inc. P.O. Box 647 Manor Branch New Castle, DE 19720
Argosy Type A.W. 650; T.C. 7A9	SA239SO	Cargo pallet restraint system.	EA	19846	Capitol Airways, Inc. P.O. Box 647 Manor Branch New Castle, DE 19720
Argosy Type A.W. 650; T.C. 7A9	SA296SO	Mach overspeed aural warning device.	EA	19846	Capitol Airways, Inc. P.O. Box 647 Manor Branch New Castle, DE 19720
Argosy Type A.W. 650; T.C. 7A9	SA544EA	Inst. of Chamberlain Radome P/N 3080X. Amended 12/14/67.	GI	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company Aero Products Operations P.O. Box 1187 Akron, OH 44309

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
ARROW AIRCRAFT & MOTORS CORP.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Arrow Sport; T.C. 115	SA1073WE	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
Arrow Sport; T.C. 2-110, 115	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Arrow Sport; T.C. 2-110, 115	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AVIONS MARCEL DASSAULT (A.M.D.)

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon; T.C. A7EU	SA16GL	Incorporating AMF (Leland) inverter MGE-23-400. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
Fan Jet Falcon all models; T.C. A7EU	SA45GL	Install AMF inverter MGH 549-1. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
Fan Jet Falcon; T.C. A7EU	SA176GL	Addition of interior/exterior emergency lighting, flight compartment door, and baggage compartment smoke detector system. Issued 5/18/77.	GL	47630	K-C Aviation, Inc. Outagamie Airport Appleton, WI 54911
Fan Jet Falcon; T.C. A7EU	SA472CE	Install Twi. MK III supplementary lighting system using Model A wing tip and Model L tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
Fan Jet Falcon; T.C. A7EU	SA590EA	Installation of interior. Amended 3/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
Fan Jet Falcon; T.C. A7EU	SA598CE	Install cargo bulkhead and baggage rack. Reissued 7/10/78.	WE	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
Fan Jet Falcon; T.C. A7EU	SA653EA	Installation of partition and door blow out provisions. Amended 11/6/70.	EA	07498	AiResearch Aviation Company L.I. MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779
Fan Jet Falcon; T.C. A7EU	SA649SW	Interior modification. Reissued April 1973.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon; T.C. A7EU	SA677SW	Interior. Reissued April 1973.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon; T.C. A7EU	SA688SW	Angle of attack system. Reissued March 1977.	NE	26010	Continental Development Corp. Box 511 Ridgefield, CT 06877
Fan Jet Falcon; T.C. A7EU	SA691SW	Interior modification. Reissued April 1973.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon; T.C. A7EU	SA698CE	Install Woodward electronic engine synchronizer system. Amended 1/20/72.	GL	87250	Woodward Governor Company 5001 NOrth Second Street Rockford, IL 61101
Fan Jet Falcon; T.C. A7EU	SA704SW	PB-60 autopilot dual axis.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
Fan Jet Falcon; T.C. A7EU	SA730SW	Relocation and install inverters.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
Fan Jet Falcon; T.C. A7EU	SA740SW	Collins AP103F/FD108 Flight Director Systems and Sensors, equipment for Category II. Reissued 1/30/75.	SC	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA753SW	Class D baggage compartment.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
Fan Jet Falcon; T.C. A7EU	SA758SW	Jump seat. Reissued April 1973.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon; T.C. A7EU	SA770SW	Bendix Eclipse Pioneer PB-60 Flight Control System for Category II.	EA	16010	The Bendix Corporation Navigation & Controls Division Teterboro, NJ 07608
Fan Jet Falcon; T.C. A7EU	SA785SW	Collins AL-101 radio altimeter system.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon; T.C. A7EU	SA786SW	AP/ADN-153(V) Doppler System.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420
Fan Jet Falcon; T.C. A7EU	SA804SW	Collins AP-103F/FD-109G flight director system and associated sensors for 3-axis. Reissued 1/30/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA805SW	Collins AP-103F/FD-109G flight director system and associated sensors for 2-axis. Reissued 1/30/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA814EA	Installation of Fairchild Company voice recorder Model A100 and control unit A151 and Lockheed Corp. flight recorder Model 109C. Reissued 2/22/77.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 907 - Adams Field Little Rock, AR 72203
Fan Jet Falcon; T.C. A7EU	SA833SW	VOR antenna.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420
Fan Jet Falcon; T.C. A7EU	SA841SW	Dual FD-300 Flight Director Systems, AL-101 Radio Altimeter, G-1640 Cables Comparator.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
Fan Jet Falcon; T.C. A7EU	SA852SW	Rear mounted 2500VA inverter package. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA856SW	Bendix AIA-51A radio altimeter.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420
Fan Jet Falcon; T.C. A7EU	SA871SW	28 volt 4 amp hour nickle cadmium battery.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420
Fan Jet Falcon; T.C. A7EU	SA875SW	Jump seat. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA920SW	AP104/FD109H/FD109F Flight Director System.	SW	24252	Collins Radio Company Addison Airport Addison, TX 75001
Fan Jet Falcon; T.C. A7EU	SA927SW	Angle of attack system.	NE	26010	Continental Development Corp. P.O. Box 511 Ridgefield, CT 06877
Fan Jet Falcon; T.C. A7EU	ST933SO	Installation of Collins FPC-75 flight profile computer (ground proximity warning system). Issued 5/20/77.	SO	24262	Collins Radio Group Rockwell International 1591 Phoenix Boulevard, Suite 1 Atlanta, GA 30349
Fan Jet Falcon; T.C. A7EU	SA1016SW	Collins AL-101 Radio altimeter.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
Fan Jet Falcon; T.C. A7EU	SA1025WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1031WE	Executive interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1116WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1129WE	Executive interior, equipment and avionics.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1131WE	Collins AP-103E/AP-103F autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1136WE	GTCP 39-92, for ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon; T.C. A7EU	SA1139WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon; T.C. A7EU	SA1155EA	Installation of Solar T-62T-39, in lieu of Solar T-62T-29, gas turbine auxiliary power unit and removal of Freon air conditioning systems. Amended 8/15/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon; T.C. A7EU	SA1204WE	Integrated auxiliary power unit and air conditioning system using Solar T-62T-29A gas turbine. Reissued 12/20/77.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon; T.C. A7EU	SA1230WE	Storage box in rear compartment.	WE	62080	Pacific Airmotive Corporation Aircraft & Eng. Center 3000 N. Clybourn Avenue Burbank, CA 91502
Fan Jet Falcon; T.C. A7EU	SA1298WE	Emergency flight instrument system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1336WE	Flight data recorder and cockpit voice recorder.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1337WE	Emergency cabin lighting.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1357SW	Installation of inverter rack. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon; T.C. A7EU	SA1342WE	Installation of accumulator pressure gauges.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1374WE	Installation of Bendix DPA-12 doppler radar system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1436WE	Installation of Shoulder Harness for Pilot Seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1508WE	Installation of an Automated Specialties, Inc. angle of attach system. Amended 9/4/68.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1515SW	Replace existing 13 x 5.0-4 wheel and tire w/14.5 x 5.5-6 wheel and tire. Reissued 4/6/77.	SO	34808	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon; T.C. A7EU	SA1573WE	Installation of Lear Jet Type Air Conditioning System and Auxiliary Heater.	RM	37098	Gates Rubber Company 8601 Montview Boulevard Denver, CO 80220
Fan Jet Falcon; T.C. A7EU	SA1588SW	Foxtronics/TRAMM BT1 600 nickel cadmium battery temperature system. Issued 1/5/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
Fan Jet Falcon; T.C. A7EU	SA1595SW	Transequip cargo handling equipment. Issued 1/22/73.	SW	34810	Federal Express Corporation P.O. Box 493 - Adams Field Little Rock, AR 72203
Fan Jet Falcon; T.C. A7EU	SA1616WE	Installation of ladder and hand rail in aft compartment. Amended 5/23/68.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1621WE	Installation of inverters.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
t+1 Fan Jet Falcon; T.C. A7EU	SA1666SW	Nose wheel steering modification. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA1707WE	Installation of inverters.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon; T.C. A7EU	SA1737SW	WA402001 galley. Issued 10/9/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon; T.C. A7EU	SA1778WE	Installation of electric floor heater blankets	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	PG	STC Code	STC Holder
Fan Jet Falcon; T.C. A7EU	SA1818WE	Installation of Sperry SP-40 Automatic Flight Control System and SPI-73F Sperry Instrumentation System.	WE	74570	Sperry Flight System Division Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
Fan Jet Falcon; T.C. A7EU	SA2058WE	Installation of interior and equipment, including special remote sensing equipment (aerial prospecting). Amended 5/4/70.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA2159WE	Installation of General Precision Laboratories GPF-1000 doppler radar systems. Issued 5/22/70.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91503
Fan Jet Falcon; T.C. A7EU	SA2377SW	Install PH185P-289 EGT temperature indicator system. Issued 11/9/76.	SW	43075	Howell Instruments, Inc. 3479 West Vickery Boulevard Fort Worth, TX 76107
Fan Jet Falcon and Series C, D, F; T.C. A7EU	SA1398CE	Installation of Collins APS-80 2-axis automatic flight control system integrated with a (partial) ADS-80 air data system. Issued 2/11/78.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
Fan Jet Falcon and Series C, D, F; T.C. A7EU	SA1851WE	Installation of single point pressure fueling system. Amended 6/16/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
Fan Jet Falcon; Series C, D, E, F; T.C. A7EU	SA689SW	Revised autopilot static system for Collins AP103F autopilot. Reissued 1/30/75.	SC	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2568WE	Installation of engine thrust reversers. Amended 10/31/72.	GL	02400	Aeronca, Inc. 1712 Germantown Road Middletown, OH 45042
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2704WE	Installation of (1) engine pylon mounted vertical tail floodlights, (2) horizontal stabilizer mounted vertical tail floodlights or both systems. Amended 9/27/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2792WE	Installation of Dorne & Margolin antenna assembly (DMN 4-15) on the vertical tail cap. Reissued 12/20/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon and Series E, F; T.C. A7EU	SA2550WE	Installation of Flite-Tronics inverters Model PC-17A. Amended 2/20/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series C, D; T.C. A7EU	SA829EA	Installation of Teledyne Avionics auto throttle system. Reissued 1/7/72.	SW	78127	Teledyne Incorporated 3401 Shiloh Road Garland, TX 75040
Fan Jet Falcon, Fan Jet Falcon C, D, F; T.C. A7EU	SA1102EA	Installation of Teledyne Avionics angle of attack indicating system, P/N SL112B2300. Issued 5/31/78.	EA	78000	Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA1137SW	Installation of Teledyne Avionics normalized angle of attack indicating system. Amended 11/9/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA28NE	Installation of Canadian Marconi CMA-734 omega navigation system. Issued 12/14/78.	NE	74935	Stead Aviation Corporation Manchester Municipal Airport Manchester, NH 03103
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; F; T.C. A7EU	SA30NE	Installation of Global Navigation, Inc. loop antenna, P/N 11455-2, on horizontal stabilizer. Amended 1/17/80.	NE	74935	Stead Aviation Corporation Manchester Municipal Airport Manchester, NH 03103
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2[illegible]	Installation of equipment rack at fuselage station 00. Issued 7/9/73.	GL	02400	Aeronca, Inc. 1712 Germantown Road Middletown, OH 45042
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA57GL	Installation of passenger couch. Reissued 7/10/78.	WE	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA122GL	Installation of radome kit 4076X. Issued 8/16/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST849SO	PPG Industries windshields, Federal Express P/N's 111-0071, (L/H), 111-0072 (R/H), 111-0073 (center). Issued 8/4/75.	SO	34808	Federal Express Corporation 2839 Sprankel Road P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST882SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA891SW	Dorne & Margolin DMN4-15-5 antenna. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA894EA	Installation of Grimes three light strobe kit P/N 34-0302-1 as supplemental lighting. Issued 12/20/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST925SO	Manufacture of main landing gear door arm for Fan Jet Falcon Series airplane. Issued 2/24/77.	SO	05090	Aircraft Equipment Cert. Corp. P.O. Box 18850 Memphis, TN 38118
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	ST948SO	Installation of Aircraft Equipment Certification Corp. pilot/copilot/ center windshield panels. Amended 6/2/78.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	ST960SO	Manufacture and installation of Aircraft Equipment Certification Corp. (AECC) modular container and rack assembly. Issued 10/21/77.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	ST961SO	Replacement of the ball-bearing type right-hand engine throttle crossover cable with a reinforced wire type. Issued 11/15/77.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis International Airport Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST1001SO	Installation of Federal Express Corp. brake mount flange. Issued 6/6/78.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1163EA	Installation of Solar T-62T-40C APU. Amended 1/23/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1164EA	Installation of cabin air-conditioning flood duct. Amended 10/10/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1172EA	Installation of Hamilton Standard R72-3W air cycle machine, P/N 750660-5 and heat exchangers P/N 753355-5. Issued 10/15/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1213SW	Alteration for battery charging from ground power unit. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1435CE	Addition of improved autopilot static port systems. Issued 9/28/78.	CE	59270	MidCoast Aviation Service, Inc. Lambert Field P.O. Box 10254 St. Louis, MO 63145
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1461SW	Three Flite-Tronics PC-17A inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1462SW	Collins AP-105/FD-108/FD-109 autopilot/flight director system. Amended 9/28/78.	CE	24250	Rockwell International Collins Radio Group Collins Road Cedar Rapids, IA 52406
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1469SW	Fairchild stem system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1633SW	Three Avionics Instruments, Inc. 1A1000 inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1699SW	Solar T-62T-39 turbine APU. Issued 7/6/73.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1713SW	Couch installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1714SW	Galley installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1768SW	Gulton proximity switch system. Reissued 2/14/75.	SC	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1885SW	Solar T62T-39 turbine APU. Issued 6/14/74.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1893SW	Landing light installation, alternate position. Reissued 2/14/75.	SC	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1988SW	Jump seat. Issued 5/20/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1996SW	Installation of auxliliary landing lights. Issued 11/6/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2204SW	Installation of electronics rack. Issued 9/14/76.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2232SW	Install Collins dual NCS-31 RNAV system. Issued 8/15/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2474SW	Horn silence switch. Issued 6/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2485SW	Fabrication and installation of three-place couch. Issued 8/5/77.	SW	34280	Falcon Jet Corporation LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA907CE	Battery temperature indicating and over temperature warning system. Amended June 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 E. Lewis Street Wichita, KS 67202
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA1483SW	Avionics installation (VHF communications, VHF navigation, ADF's DME's, transponders, weather radar radio altimeter, third attitude gyro). Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F, Falcon 10; T.C. A7EU, A10EU	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
Fan Jet Falcon Series C, D, E, F, Mystere 20; T.C. A7EU	SA119GL	Electrical cable harness assemblies for left and right engines; each consisting of starter-generator cables, starter-generator ground cable, master junction cable and fan tach sensor cable. Amended 2/6/78.	GL	37379	General Electric Company Aviation Service Operation/Cincinnati 260 West Mitchell Avenue Cincinnati, OH 44232
Fan Jet Falcon Series D; T.C. A7EU	SA918EA	Installation of Canadian Marconi CMA-712 doppler navigation system. Reissued 11/9/72.	EA	47665	Farr Electronics Corporation 232 Wescott Drive Rahway, NJ 07065
Fan Jet Falcon Series D; T.C. A7EU	SA993SW	Collins AP-104 Autopilot and FD-109H/FD-109F Flight Directors for Category I and II. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1327WE	Installation of dual inverters. Amended 3/18/69.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon Series D; T.C. A7EU	SW1467SW	Cargo interior. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series D; T.C. A7EU	SA1468SW	Openable window in co-pilot's side and qualifying existing pilot's and new co-pilot's windows as emergency exits. Reissued 2/14/75.	SC	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1473SW	Replace passenger entrance door with wide cargo door. Amended 7/7/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA2640WE	Installation of a Garrett Model 75 area navigation system. Amended 9/18/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D; T.C. A7EU	SA3394WE	Replacement of cargo barrier net installed per STC SA1467SW with a rigid cargo barrier partition. Issued 7/11/77.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Blvd. Torrence, CA 92680
Fan Jet Falcon Series D, E; T.C. A7EU	SA1771SW	Installation of Sperry SPZ-200 autopilot/flight director control system. Reissued 2/14/75.	SC	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA1570SW	Collins AP105/FD108 autopilot/flight, flight director system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA1577WE	Installation of jump seat. Amended 10/19/70.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA2404SW	System to disable the take off out of trim warning system when high power is applied during operation of thrust reversers.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA2588AWE	Installation of a Hoskins Model Mk III (Twilighter) anticollision lighting system. Amended 12/21/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
Fan Jet Falcon Series D, F; T.C. A7EU	SA1495SW	Installation of Fairchild voice, recorder model A100 and Lockheed flight recorder model 109C. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series D, F; T.C. A7EU	SA1806SW	Co-pilot brake modification. Issued 2/6/74.	SW	34810	Federal Express Corporation P.O. Box 493 Little Rock, AR 72203
Fan Jet Falcon Series D, F: T.C. A7EU	SA2344SW	Hartman Systems Co. vertical scale engine instruments. Issued 8/11/76.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series E; T.C. A7EU	SA3714WE	Revise existing interior to include three place side facing divan, galley, storage cabinet, three folding tables, cockpit door, stereo/flitephone cabinet, T.V./recorder cabinet and shoulder harness restraint for divan. Amended 11/22/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 E. Spring Street Long Beach, CA 90806
Fan Jet Falcon Series F; T.C. A7EU	SA1381SW	Installation of Teledyne Avionics normalized angle of attach system, Model 112B500. Amended 2/8/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon Series F; T.C. A7EU	SA1499SW	Installation of inverter system. Reissued 5/30/79.	SW	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series F; T.C. A7EU	SA1692SW	Modification of control pedestal. Reissued 5/30/79.	SW	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series F; T.C. A7EU	SA1892SW	Collins ALT-50 radio altimeter. Issued 6/27/74.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series F; T.C. A7EU	SA2479SW	Wiring and antenna provisions, and radio rack for Litton LTN-201 omega system. Issued 7/15/77.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA142GL	Installation of radome kit 4128X. Issued 11/9/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Falcon 10; T.C. A33EU	ST9025SO	Installation of Collins ground proximity warning system. Issued 7/28/76.	SC	24262	Collins Radio Group Rockwell International 1591 Phoenix Boulevard, Suite 1 Atlanta, GA 30349
Falcon 10; T.C. A33EU	SA1002EA	Installation of Sperry SPZ-500/SPI-77D flight control instrument system. Reissued 1/7/80.	SW	07498	Falcon Jet Corporation P.O. Box 167 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA1012EA	Installation of Teledyne Avionics normalized angle of attack indicating system, P/N 112B1600. Issued 8/21/75.	EA	78000	Teledyne Avionics A Division of Teledyne, Inc. P.O. Box 6400 Charlottesville, VA 22906
Falcon 10; T.C. A33EU	SA1042EA	Installation of hydraulically actuated target type thrust reverser system. Amended 7/11/78.	EA	39540	Grumman Aerospace Corporation Bethpage, L.I., NY 11714
Falcon 10; T.C. A33EU	SA1223CE	Install King KFC-300 dual flight director flight control system (Category I configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1224CE	Install King KFC-300 dual flight director flight control system (Category II configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1294CE	Installation of Avcon Industries TSC-C39a stretcher, P/N 4001-105 or -106. Issued January 1977.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 North Wichita Station Wichita, KS 67204
Falcon 10; T.C. A33EU	SA1993SW	Install wing ice lights. Issued 6/9/75.	SW	26230	Cooper Airmotive, Inc. Executive Aircraft Division Redbird Airport Dallas, TX 75232
Falcon 10; T.C. A33EU	SA2225SW	Passenger compartment interior. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2226SW	Pressurization of nose cone to improve avionics reliability. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2846WE	Installation of Pulstar two-light supplemental lighting system. Issued 3/4/74.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92705
Falcon 10; T.C. A33EU	SA2857WE	Avionics modification and installations of an 8-passenger executive interior arrangement. Reissued 1/4/78.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2885SW	Install three place couch at Station 181.0 to 239.0 right side. Issued 12/11/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
Falcon 10; T.C. A33EU	SA2919WE	Installation of TFE731-2 engines S/N P73143 and S/N P79101, modified in accordance with STC SE66WE. Issued 8/21/74.	WE	07502	AiResearch Aviation Company 402 S. 36th Street Phoenix, AZ 85034
Falcon 10; T.C. A33EU	SA2983WE	Installation of a Garrett AirNAV 100 area navigation system. Issued 1/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3061WE	Installation of a Garrett AirNAV 100 or 200 navigation system. Amended 10/26/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3544WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 1/27/78	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3557WE	Installation of DeVore Aviation Corp. tail floodlights. Issued 1/5/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
Falcon 10; T.C. A33EU	SA3752WE	Installation of a communications components Ontrac III VLF/Omega navigation system. Issued 10/25/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA4015SW	Nose radio rack. Issued 7/12/79.	SW	34280	Falcon Jet Corporation P.O. Box 7001 Dallas, TX 75209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Falcon 10A; T.C. A33EU	ST153RM	Installation of Canadian Marconi CMA-734 Omega navigation system. Issued 9/11/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
Falcon 20; T.C. A7EU	ST823SO	Installation of SEMCA 14640-113 air conditioning valve. Reissued 7/23/75.	EA	42125	Hermetic Aircraft Instrument Corporation 200 Marine Street Farmingdale, L.I., NY 11735

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
AYRES CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S2A; T.C. 2A9	SA653WE	Ceconite 101 covering of fuselage and tail group.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
S-2A, S-2B, S-2C, 600 S-2C, S-2R, 600 S-2D; T.C. 2A9, 2A7, A3SW, A4SW	SA4-1210	All fabric surfaces. Issued 3/21/77.	WE	52090	William G. Lott Box 635, Minter Village Bakersfield, CA 93307
S2A; S2B, S2C, 600-S2C; T.C. 2A9, 2A7	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Snow) S2A, S2B, S2C, 600-S2C, (Aero Commander) 600-S2D, S2P; T.C. 2A9, 2A7, A3SW, A4SW	SA2666WE	Ceconite 102 material covering of: S2A - fuselage and tail group; S2B, S2C, 600-S2C - empennage; 600-S2D - vertical fin, left and right elevators, rudder; S2R - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S2B, S2C, 600-S2C; T.C. 2A7	SA550WE	Wing auxiliary fuel tanks.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S2P; T.C. 2A7	SA609WE	Pratt & Whitney R-1340 AN-1 engine (restricted category only).	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S2B, S2C, 600-S2C; T.C. 2A7	SA1164WE	Ceconite 101 covering of empennage.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
S2C; T.C. 2A7	SA398SW	Electrical system.	SW	19670	C.G. Campbell P.O. Box 605 Archer City, TX 76351
S2C; T.C. 2A7	SA1630WE	Installation of Serv-Aero Engineering vibrodamp engine mount, mount, P/N 2059.	WE	71000	Serv-Aero Engineering, Inc. Salinas Municipal Airport Salinas, CA 93901
S-2C, 600-S2C; T.C. 2A7	SA1650SW	Replace military surplus AT-6 seat with Snow seat assembly 10136-1. Issued 5/7/73.	SW	73400	Snow Engineering Company 3708 Cedar Elm Wichita Falls, TX 76308
S2C, S2D, S2R; T.C. A3SW, 2A7	SA465NW	Installation of EAC-12D40-AG-100-4S propellers on Pratt & Whitney R-1340-AN-1-SH1H-1. Issued 6/13/77.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
600-S2C, -S2D, -S2P, T.C. 2A7, A3SW, A4SW	SA1834WF	Modification and installation of 70 ampere Motorola Model SA-70N-24 alternator (Vasquez P/N FMM-1002) system.	WE	82560	Frank C. Vasquez 5888 East Parkside Drive Fresno, CA 93702
600S-2D, S-2P; T.C. A3SW	SA1651SW	Replace military surplus AT-6 seat with Snow seat assembly 10136-1. Issued 5/7/73.	SW	73400	Snow Engineering Company 3708 Cedar Elm Wichita Falls, TX 76308
600S-2D, S-24; T.C. A4SW	SA1652SW	Replace military surplus AT-6 seat with Snow seat assembly 10136-1. Issued 5/7/73.	SW	73400	Snow Engineering Company 3708 Cedar Elm Wichita Falls, TX 7638
600-S2C; T.C. 2A7	SA732WE	Replacement engine mount including vibration dampeners.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2C, 600-S2C, S2R, 600 S-2D; T.C. 2A7, A3SW	SA2440WF	Installation of automatic flagman Model No. 4. Issued 2/14/72.	NW	03500	Air-Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
S-2P Thrush; T.C. A4SW	SA24RM	Installation of electrically driven freon air-conditioning system. Amended 4/18/79.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
S-2P; T.C. A4SW	SA162GL	Install Cleveland Wheel and Brakes conversion kit, P/N 199-68A.	GL	23260	Cleveland Wheels and Brakes Div. Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S-2R; T.C. A4SW	SA834SO	Installation of Hamilton Standard Model 12D40/6101A-10S propeller approved under STC SP830SO on P&W R1340-AN-1, S1H1 or S3H1 engines listed in TDS A4SW. Issued 4/27/75.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
S-2R; T.C. A4SW	SA1008WE	Installation of poly-fiber covering material of horizontal and vertical stabilizer. Amended 8/21/79.	WE	75250	Stits Aircraft Coatings 43rd South Fort Drive P.O. Box 3084 Riverside, CA 92519
S2R; T.C. A3SW, A4SW	SA1103SO	Installation of a 400-gallon hopper window kit. Issued 9/21/79.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701
S-2R; T.C. A4SW	SA1165CE	Intallation of air conditioning system, restricted category. Issued 9/30/75.	CE	02950	Aero Space Controls Corp. 1050 North Mosley Wichita, KS 67214
S-2R; T.C. A4SW	SA1181CE	Installation of air conditioning system, normal category. Issued 11/21/75.	CE	02950	Aero Space Controls Corp. 1050 North Mosley Wichita, KS 67214
S-2R; T.C. A4SW	SA1638WE	Fabrication and installation of 400-gallon fiberglass hopper. Reissued 10/31/74.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
S-2R; T.C. A3SW	SA2807SW	P&W R1340-AN2 engine and Hamilton Standard 23D40/AG200-OS propeller. Issued 6/30/78.	SW	74946	STC Engineering Company 4410 Northwest 54th Street Oklahoma City, OK 73112
S-2R; T.C. A4SW	SA2901WE	Installation Serv-Aero vibrodamp engine mount in lieu of Aero Commander engine mount. Issued 6/18/74.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2 (R); T.C. A3SW	SA2969WE	Installation of Wright R-1300-1B engine and Hamilton Standard 3D40 or 23D40 constant speed propeller (normal or restricted category). Amended 2/27/75.	NW	47460	J & W Aircraft Company, Inc. P.O. Box 785 Warden, WA 98857
S-2R; T.C. A4SW	SA3227WE	Installation of an AiResearch TPE331-1-101Z, TPE331-25DA or TPE331-25FA turboprop engine. Amended 5/5/78.	WE	75210	Floyd D. Stilwell 5060 East Falcon Mesa, AZ 85205
S-2R; T.C. A4SW	SA3230WE	Installation of Hamilton Standard 3D40/6101A-18 constant speed propeler (restricted category). Issued 7/13/76.	WE	46770	Cliff Johnson 2000 South Union Avenue Bakersfield, CA 93307
S-2R; T.C. A3SW	SA3237WE	Installation of United Aircraft of Canada PT6A-27 or PT6A-34 engine. Amended 8/29/77.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2R; T.C. A3SW	SA3238WE	Installation of a United Aircraft of Canada PT6A-27 or PT6A-34 engine. Amended 8/29/77.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2R (Restricted Category); T.C. A4SW	SA3497WE	Installation of Wright R-1820-71 engine and Hamilton Standard 43D50 constant speed propeller. Amended 9/8/78.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93905
S-2R (Snow) (Restricted Category); T.C. A4SW	SA3595WE	Installation of dual controls and bench seat. Issued 2/16/78.	WE	55627	Marsh Aviation Company 5060 East Falcon Drive Mesa, AZ 85205
S-2R (Restricted Category); T.C. A4SW	SA3767WE	Installation of 500 gallon fiberglass hopper and relocated oil cooler. Issued 10/26/78.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (Normal Category); T.C. A3SW	SA3842WE	Installation of 500 gallon fiberglass hopper and relocated oil cooler and deletion of the alternate air inlet doors. Reissued 3/7/79.	SC	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R (as modified under STC SA3227WE); T.C. A4SW	SA3886WE	Installation of Aerospace Controls Corp. No. 1922 air conditioning air conditioning system. Issued 3/20/79.	WE	55627	Marsh Aviation Company 5060 East Falcon Drive Mesa, AZ 85205

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S-2R (Restricted Category); T.C. A4SW	SA3899WE	Installation of Goodyear brake assembly P/N 95-50377 or P/N 5308865, Goodyear wheel assembly P/N 50-00444 or P/N 530884, and 11.00-13, Type III, 8 P.R. tire. Amended 6/15/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90907
S-2R (Restricted Category); T.C. A4SW	SA3890WE	Installation of Wright R-1820-40, -60, -71, -87 engine and Hamilton Standard 33D50 or 43D50 constant speed propeller. Amended 5/18/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
S-2R (Restricted Category); T.C. A4SW	SA3897WE	Installation of Pezetel Model PZL-3S engine and Dowty Rotol model CR289/3-110-F/1 propeller. Issued 4/11/79.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93905
S-2R; T.C. A3SW	SA3927WE	Installation of an AiResearch TPE331-1-1012 turboprop engine. Issued 5/11/79.	WE	75210	Floyd D. Stilwell 5060 East Falcon Drive Mesa, AZ 85205
S-2R; T.C. A4SW	SA3961WE	Installation of extended engine mount, revised cowling and induction system, Hamilton Standard 22D40 or 12D40 constant speed propeller, and modified elevator trim tab system. Issued 5/23/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R; T.C. A4SW	SA4039SW	Lycoming LTP-101-600A1A turboprop. Issued 9/25/79.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
S-2R (S/N 2526R and up modified by STC SA3897WE), S-2R-R3S (S/N R3S-001 and up); T.C. A4SW	SA4038WE	Installation of second pilot's seat and dual controls. Issued 10/29/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category); T.C. A3SW	SA4045WE	Installation of second pilot's seat and dual controls. Issued 10/29/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up as modified by STC SA3897WE); T.C. A4SW	SA4046WE	Installation of passenger/cargo compartment. Issued 11/26/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category); T.C. A3SW	SA4047WE	Installation of passenger/cargo compartment. Issued 11/26/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
600 S2R, 800 S-2R; T.C. A4SW	SA266NW	Installation of automatic flagman Model No. 6. Amended 5/12/77.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362
S2R-T34 (Normal Category), S2R-T15 (Restricted Category); T.C. A3SW, A4SW	SA1073SO	Installation of a 500 gallon hopper vent blister kit. Issued 5/29/79.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

THE BALLOON WORKS

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Firefly 5, 6, 6B, 7, 8-24; T.C. A14SO	SB11WE	Installation of a digital readout balloon envelope temperature indicator. Issued 11/14/79.	WE	01450	Advanced Aircraft Components 1459 North Irving Avenue Glendale, CA 91201
Firefly 6, 7; T.C. A14SO	SI575SO	Installation of ABP-181 automatic balloon pilot (automatic temperature control). Reissued 11/5/74.	SW	23345	J. Donald Cline 807 Larkwood Drive Greensboro, NC 27410
Firefly 6, -6B, 17, 8-24; T.C. A14SO	SB2WE	Installation of digital readout balloon envelope temperature indicator. Issued 5/6/77.	WE	01450	Advanced Aircraft Components 1459 Irving Avenue Glendale, CA 91202

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BEECH AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AT-11; T.C. 2-582	SA1-50	Installation of Hartzell Propellers without and with unfeathering kit. amended 10/23/67.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
AT-11; T.C. 2-582	SA1-109	Floorboard.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
AT-11; T.C. 2-582	SA3-385	L-2C autopilot with or without automatic altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
AT-11; T.C. 2-582	SA3-441	Main landing gear.	GL	22790	John J. Clark 305 N. Owen Street Mt. Prospect, IL 60056
AT-11; T.C. 2-582	SA4-109	Seat track.	WE	82600	Vegas Airways, Inc. P.O. Box 347 Redondo Beach, CA 90277
AT-11; T.C. 2-582	SA4-833	Glass cloth on rudders, elevators, flaps and ailerons.	WE	38060	Glasco-Air Products 1125 First Street San Fernando, CA 91340
AT-11; T.C. 2-582	SA4-1238	Hamilton Standard full-feathering propellers, hubs 22D30-33 and blades 6531A-15; feathering pumps, Pesco 1E301 DE-3; Hamilton Standard 4B2-P6 governors.	RM	18380	Ken Burnham Aviation Service 1326 N. Prospect Street Colorado Springs, CO 80901
AT-11 (Army), SNB-1 (Navy), B17B, B17L, SB17L, B17T, C17B, C17L, SC17L, C17R, SC17R, D17A, D17R, D17S, SD17S, E17B, SE17B, E17L, F17D, SF17D, G17S, 18A, S18A, 18D, S18D, A18A, SA18A, A18D, SA18D, 18S, B18S, C18S, D18C, D18S, E18S, G18S, H18, C45G, TC45G, C45H, TC45H, TC45J, JRB6, SNB5; T.C. 2-582, 560, 579, 602, 604, 713, 638, 649, 641, 689, 779, 630, 684, 710, 737, 765	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
(Army) AT-11, (Navy) SNB-1, D17A, D17R, D17S, SD17S, E17B, F17D, C18S, D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45H, TC-45J, JRB-6; T.C. 2-582, 713, 638, 649, 641, 689, 757, 765	SA2666WE	Ceconite 102 material covering of: 2-582, C18S, D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J, JRB-6 - rudders, elevators, ailerons, and flaps; D17A, D17R, D17S, SD17S, E17B, F17D - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
AT-11; T.C. 2-582	SA4WE	Main cabin door and hinge pins removed.	WE	70310	Schaefer's Air Service 4627 Beverly Boulevard Los Angeles, CA 90052
AT-11, SNB-1; T.C. 2-582	SA1151CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
AT-11, SNB-1; T.C. 2-582	SA3021WE	Installation of wing spar reinforcement. Reissued 5/20/77.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue Hollywood, CA 91406
AT-11, 18 Series; T.C. 2-582, 757	SA4-108	Cabin door width increased by 10 or 14 inches.	WE	82600	Vegas Airways, Inc. P.O. Box 347 Redondo Beach, CA 90277
AT-11, 18 Series; T.C. 2-582, 757	SA4-128	Engines, propellers, revised nacelles, wheel-well doors, air-speed system, fuel system and elevator seal strips. Reissued 8/15/68.	FL	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AT-11, 18 Series; T.C. 2-582, 757	SA4-818	Ceconite 101 covering of rudders, elevators, ailerons and flaps.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
AT-11, 18 Series; T.C. 2-582, 757	SA112SO	Substitute control wheel.	SO	37086	Garcia Aviation Company 15801 S.W. 120th Avenue Miami, FL 33101
AT-11, 18 Series; T.C. 2-582, 757	SA249SO	Increase in takeoff weight to 10,200 lbs. and landing weight to 9,800 lbs. and extension of aft C.G. limit to (+120.5) at 10,200 lbs. (Model may also be designated as Conrad 10,200.) Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
AT-11, 18 Series; T.C. 2-582, 757, 765	SA3-86	Installation of RCA AVQ-50 radar antenna mount. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
AT-11, 18 Series; T.C. 2-582, 757, 765	SA4-1069	Left and right cowl flaps with electronic actuators, control switches, and indicator.	WE	62442	Paragon Tool Die & Engineering 11035 Sutter Avenue Pacoima, CA 91331
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA1-61	Auxiliary outboard wing tanks. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA1-236	Air stair door. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA4-34	Main landing gear door. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA4-120	Dual airspeed system. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA4-855	Windows in cabin.	WE	04000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA4-1030	Bonite covering on all control surfaces including flaps.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA4-1047	Fiberglas nose cone. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA4-1122	Interior card table, accordian door and indirect lighting. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA4-1198	Aft bulkhead removal.	WE	10360	American Turbine Engineering Co. 1150 Busch Gardens Court Pasadena, CA 91105
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA4-1427	Pratt & Whitney R-985 Series engines modified for fuel injection.	GL	15500	The Bendix Corporation 401 Bendix Drive South Bend, IN 46600
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA125SW	Hand operated cowl flap.	SW	14060	Avio Engineering Company, Inc. 11140 Pinocchio Drive Dallas, TX 75235
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA405WE	Metal covering on elevator, aileron, rudder and flap. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series; T.C. 2-582, 757, 765	SA565WE	Wing tips. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45; T.C. 2-582, 757, 765, 770	SA4-711	Power air step (retractable entrance step). Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series; T.C. 2-582, 765	SA3-232	Sonotone CA6 (24 M320) or one Sonotone CA7 (19 cell 12M120) battery.	GL	71520	George W. Sherwood 11107 Nashville Detroit, MI 48233
AT-11, 18, C45 Series; T.C. 2-582, 765	SA18WE	Redesign bulkhead 5 to accommodate an accordian door. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AT-11, 18, C45 Series; T.C. 2-582, 765	SA401WE	Wraparound windshield. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, C18S, D18S, D18C, E18S, G18S, H18, C45G, C-45H, TC-45G, TC-45H; T.C. 757, 765, 2-582	SA4-383	Metalized control surfaces replacing fabric covered surfaces. Amended 2/21/75.	EA	26833	Courtesy Air Service, Inc. Warren County Airport P.O. Box 561 Glens Falls, NY 12801
AT-11, C18S, D18S, E18S, C45G, C45H T.C. A2-582, A-757, A-765	SA4-1341	Installation of two-piece windshield. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
AT-11, C18S, C-45, -45A, -45G, 45H, D18C, D18S & 9700, G18S, AT-7, -7A, -7B, -7C, JRB-1, -2, -3, -4, -6, SNB-1, -2, -2C, -5, TC-45G, -45H, -45J, UC-45B, 45F; H18 Series BA680, -618 thru -710 & -712 thru -722; 2-582; T.C. 757, 765	SA643CE	Install center section spar reinforcement kit. Amended June 1973.	CE	47250	Ray M. Jourdan 11001 East 59th Street Raytown, MO 64133
AT-11, SNB-1; 18A, S18A; 18D, S18D, A18A, A18D, SA18A, SA18D; 18S, B18S; C18S, C-45, -45A, UC-45B, -45F, AT-7, -7A, -7B, -7C; JRB-1, -2, -3, -4, SNB-2, -2C; 3N, 3NM, JRB-6, D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), RC-45J (SNB-5P); D18C-T; T.C. A-2-52, 630, 684, 710, 757, 765, 770	SA962EA	Installation of Canadian Aerocon Limited fail-safe spar modification. Amended 6/26/74.	EA	19770	Canadian Aerocon Limited Suite 200, 280 Dorval Avenue Dorval 780, Quebec, Canada
AT-11, C18S, D18S, C-45G, H, SNB-5, 3N, 3NM, 3TM; T.C. 2-582, 757, 765	SA995WE	Cargo door installation. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91601
AT-11, AT-7, -7A, -7B, -7C, C18S, C-45, -45A, -C45G, 45H, D18C, D18S, E18S, E18S-9700, G18S, JRB-1, -2, -3, -4, -6, SNB-1, -2, -2C, -5, H18, TC-45G, -45H, -45J, UC-45B, -45F; T.C. 757, 765, 2-582	SA1206CE	Outer wing panel reinforcement. Issued April 1976.	CE	47250	Ray M. Jourdan 11001 East 59th Street Raytown, MO 64133
SNB-5; T.C. 765	SA22CE	Basic airworthiness certification kit. Reissued 4/28/77.	WE	39877	Gordon D. Hamilton d/b/a Hamilton Aviation P.O. Box 11746 Tucson, AZ 85734
17 Series; T.C. 602	SA4-319	Eonite covering of complete airplane.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
17 Series; T.C. 602	SA4-449	Laminate 514 applied to elevator and horizontal stabilizer.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
17 Series; T.C. 713, 638, 649	SA4-673	Eonite covering on rudder, wings and ailerons.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
17 Series; T.C. 713, 638, 649, 641, 689	SA4-1252	Ceconite 101 covering of entire aircraft. Amended 9/21/66.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
17 Series; T.C. 649	SA4-827	Glass cloth applied over wings, fuselage, vertical and horizontal stabilizers.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
17 Series; T.C. 649	SA285EA	Fuselage wood formers and fabric covering replaced with metal.	NE	61535	New England Aero-Tech, Inc. and/or Edmund J. Catallozzi Bowles Airport Agawam, MA 01001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
17 Series; T.C. 649	SA603SO	Main entrance door located on left side of cabin removed.	SO	16300	Lloyd H. Berry 7917 Henry Avenue West Melbourne, Fl 32904
17 Series; T.C. 649	SA1008WE	Poly-Fiber covering of fuselage and lower left-hand wing. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
17, 45 Series; T.C. 649, 765	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
17 Series; T.C. 689	SA4-83	Jacobs L4ME engine utilizing Cessna T-50 and locally fabricated components.	NW	52730	William G. McCelland 5502 N. 18th Tacoma, WA 98402
A17, B17B, B17L, B17R, C17B, C17L, C17R, D17A, D17R, D17S, E17B, E17L, F17D, G17S; ATC 560, 579, 602, 604 T.C. 713, 638, A-649, 641, 689, 779	SA555NW	Installation of landing truss assemblies. Issued 1/20/78.	NW	11337	Anything Antiques Route 1, Box 1567-C Yelm, WA 98597
B17L, SB17L, B17B, B17R, C17L, SC17L, C17B, C17R, SC17R, D17A, D17R, D17S, SD17S, E17B, E17L, SE17B, F17D, SF17D, G17S; T.C. 713, 638, 649, 641, 689, 779	SA131GL	Installation of Eastern Aircraft Corp. fuel quantity indicating system. Issued 8/4/76.	GL	31400	Eastern Aircraft Corp. Hangar #2 Grosse Isle Municipal Airport Grosse Isle, MI 48138
D17A; T.C. 713	SA3541WE	Installation of armour plate glass windshield. Issued 12/21/77.	WE	40265	Steven T. Hamilton P.O. Box 10030 Reno, NV 89510
D17A; D17R; D17S, SD17S; E17B; F17D; AT-11, SNB-1, C18S; D18C, S, E18S, -9700, G18S, H18, C-45G, TC-45G, C45H, TC-, -45J, JRB-6I; T.C. 713, 638, 649, 641, 689, 757, 765	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
17 Series; 18 Series; C-45A, B, S; 23, 33, 35, 36, 50, 55, 65 Series; T.C. A602, A604, A638, A673, A630, A684, A710, A765, A770, A757, A1CE, 3A15, 777, 5A4, 3A16, 3A20	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
D17A; T.C. 713	SA3541WE	Installation of Armour Plate Glass windshields. Reissued 3/20/79.	SO	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
D17R; T.C. 638	SA3545WE	Installation of Armour Plate Glass windshield. Reissued 3/20/79.	SO	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
D17S; T.C. 649	SA2378SW	Replace wheels, brake assembly and master cylinder. Issued 11/5/76.	SW	62520	Stephen H. Parker 414 East Hillmont Road Odessa, TX 79762
D17S, SD17S; T.C. 649	SA3546WE	Installation of Armour Plate Glass windshields. Reissued 3/20/79.	SO	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
D17S, SD17S; C45G; T.C. 649, 765	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
E17B, E17L, SE17B; T.C. 641	SA3542WE	Installation of Armour Plate Glass windshields. Reissued 3/20/79.	SO	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
F17D, SF17D; T.C. 689	SA3543WE	Installation of Armour Plate Glass windshields. Reissued 3/20/79.	SO	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
18 Series; T.C. A684, A757, A765	SA814SO	Installation of wing spar strap. Issued December 1974.	SO	08190	Airline Training, Inc. P.O. Box 22833 Fort Lauderdale, FL 33315

Aircraft Make, Model & T.C. No.	STC No.	Description	FG	STC Code	STC Holder
18 Series; T.C. 757	SA1-158	New engine baffle system for Pratt & Whitney R-985 engine.	GL	90150	Zelair Corporation P.O. Box 262 Memorial Airport Defiance, OH 43512
18 Series; T.C. 757	SA1-202	Nacelle modification.	GL	90150	Zelair Corporation P.O. Box 262 Memorial Airport Defiance, OH 43512
18 Series; T.C. 757	SA3-20	Warren McArthur seats 297 and 297D (new designation 297-ST) modified.	GL	77060	Supreme Aircraft Service P.O. Box 82 Elmhurst, IL 60126
18 Series; T.C. 757	SA3-21	Hardman 1200N seats (new designation 1200N-ST1) modified.	GL	77060	Supreme Aircraft Service P.O. Box 82 Elmhurst, IL 60126
18 Series; T.C. 757	SA3-383	Beech D18S Goodyear wheels and brake assembly. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, Fl 33315
18 Series; T.C. 757	SA3-388	Beech D18S Goodyear wheels and brake assembly.	GL	52560	E.P. Lunken P.O. Box 360 Cincinnati, OH 45202
18 Series; T.C. 757	SA4-21	Fuel system modified to provide dual wobble pumps and suction crossfeed and attendant plumbing. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18 Series; T.C. 757	SA408SO	Main entrance door and cabin window relocated and fuselage station 9A bulkhead web removed.	SO	00086	A & H Aircraft Parts, Inc. P.O. Box 48-1312 Miami, FL 33101
18 Series; T.C. 757	SA69CE	Cabin entry door removed.	GL	22205	James R. Chunn 2222 Fuller Ann Arbor, MI 48106
18 Series; T.C. 757	SA78SO	Gross weight increased to 8,240 lbs. and extended wing tips installed.	SO	55600	Marrs Aircraft Avon Park, FL 33825
18 Series; T.C. 757	SA138SO	D18S landing gear 404-180400 on C18S. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18 Series; T.C. 757	SA302SO	Landing gear and spot brakes D18.	SO	48536	K. Knight & H. Sellers 1250 N.W. 57th Avenue Miami, FL 33101
18 Series; T.C. 757, 765	SA1-225	Enlargement of top pilot window.	GL	05970	Aircraft Service, Inc. Cleveland Hopkins Airport Cleveland, OH 44101
18 Series; T.C. 757, 765	SA3-257	Fiberglas baggage door.	GL	78365	Television Associates of Indiana, Inc. East Baker Avenue Michigan City, IN 46360
18 Series; T.C. 757, 765	SA3-387	Air stair door installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18 Series; T.C. 757, 765	SA3-503	Fuel boost pumps.	RM	11740	M. Lee Arnold 5203 State Street Murray, UT 84107
18 Series; T.C. 757, 765	SA4-32	Internal combustion heaters. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, Fl 33315
18 Series; T.C. 765	SA1-74	Air step door.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-134	RCA AVQ-50 weather avoidance radar.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18 Series; T.C. 765	SA1-136	Replacement fiberglass nose cap 237.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-154	Fischer and Porter flowmeter system addition to the propeller anti-icer system.	EA	62180	Page Airways, Inc. Rochester Airport Rochester, NY 14603

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 765	SA1-161	Enlarged window on each side of fuselage.	EA	71915	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
18 Series; T.C. 765	SA1-174	Hartzell HC-93Z30-2C/10152-5 1/2 propellers.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-191	Fuel flow meter system.	GL	05970	Aircraft Service, Inc. Cleveland Hopkins Airport Cleveland, OH 44101
18 Series; T.C. 765	SA1-200	Oxygen system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18 Series; T.C. 765	SA1-226	18" AVQ-50 antenna mount.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-234	12" AVQ-50 antenna mount.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-243	Combination of following STC's: SA1-60 fiberglass nose bowl; SA1-61 auxiliary wing tanks; SA1-62 E18S wing tips; SA1-76 fiberglass tail gear door; SA1-118 three-blade Hartzell propellers; SA1-236 air step door; SA2-303 stabilizer angle of incidence change; SA4-34 main landing gear doors.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-270	Fiberglass clamshell-like parts attached to rear of tail wheel well enclosure doors.	EA	48528	Robert S. Klein and E. Reed Zimmerman Tuckerton Road & Maple Lane Reading, PA 19603
18 Series; T.C. 765	SA1-338	Underseat radar scope mounts for: RCA 5" AVQ-50, Collins 4" WP-103, and RCA 5" AVQ-55/AVQ-20.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-568	Bendix 75-ampere 1273-1A generators and modification B100 to new Model 1273-3 with cooling and electrical changes.	EA	64825	Plymouth Aviation Corporation P.O. Box 247 Forest Hills, NY 11375
18 Series; T.C. 765	SA1-597	Collins WP-103 antenna mounts for 12" WP-103 antenna and 18" WP-103 antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA3-1	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
18 Series; T.C. 765	SA3-91	Grimes D-7080 rotating beacon on belly of aircraft.	GL	38325	Gopher Aviation, Inc. Rochester, MN 55901
18 Series; T.C. 765	SA3-93	Carburetor and windshield fluid deicing systems.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
18 Series; T.C. 765	SA3-134	Installation of electric fuel boost pumps - AN4100. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18 Series; T.C. 765	SA3-177	Electric emergency fuel pumps (Thompson TFD 600-3 pumps with Delco A4949 motors).	GL	38325	Gopher Aviation, Inc. Rochester, MN 55901
18 Series; T.C. 765	SA3-184	Mounting bracket to antenna 137X-1.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
18 Series; T.C. 765	SA3-252	Radome installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18 Series; T.C. 765	SA3-323	Radio DF antenna 137A-2 on bottom of fuselage.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
18 Series; T.C. 765	SA3-410	L-2C autopilot with approach coupler and altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 765	SA3-417	AP-102 automatic pilot including FD-105 integrated flight system instruments.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
18 Series; T.C. 765	SA3-677	Two Delco motors with two Pesco AN 4100, 200 g.p.h. fuel boost pumps.	GL	78610	Toman Aircraft Service 12801 S. 82nd Avenue Palos Park, IL 60464
18 Series; T.C. 765	SA4-992	Ceconite 101 covering of rudders, elevators, flaps and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
18 Series; T.C. 765	SA4-6	Two Janitrol heaters of 25,000 B.t.u. capacity each, Mot. B15C54 in right and left wheel well.	WE	80925	United States Steel Corporation 235 Montgomery Street San Francisco, CA 94010
18 Series; T.C. 765	SA4-125	E18S powerpack for 450 hp. (Maximum continuous and takeoff).	GL	39125	Goodyear Tire & Rubber Company Flight Operations Municipal Airport Akron, OH 44309
18 Series; T.C. 765	SA4-126	One Southwind 940-B 20,000 B.t.u. TSO-C20 heater in each nacelle.	GL	39125	Goodyear Tire & Rubber Company Flight Operations Municipal Airport Akron, OH 44309
18 Series; T.C. 765	SA4-167	Full flow oil filter 1050-B-83 with element CP-1043-CO-1.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
18 Series; T.C. 765	SA4-509	Gross weight increased to 9,000 lbs. with powerpack STC SA4-125; Southwind heater STC SA4-126; and horizontal stabilizer STC SA2-120.	WE	67794	Richfield Oil Company 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA4-1076	Electrically-driven, mechanical, refrigerated air conditioner.	WE	08356	Airtransit, Inc. 3131 Monterosa Phoenix, AZ 85000
18 Series; T.C. 765	SA4-1102	Cabin window.	WE	67794	Richfield Oil Company 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA4-1110	Baggage compartment.	WE	67794	Richfield Oil Company 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA4-1378	R-985-APS Series engines. (Applies only to D18S aircraft modified per STC SA2-820.)	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91500
18 Series; T.C. 765	SA7EA	Koehler Air-lav Model 45.	GL	90065	Youngstown Airways, Inc. Municipal Airport Youngstown, OH 44501
18 Series; T.C. 765	SA52EA	Underseat radar scope mount 299-05 for RCA 5" AVQ-55/AVQ-20 radar	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA111EA	One-piece window on left side of pilot's cockpit.	NE	71780	Simsbury Flying Service, Inc. 94 Walcot Road Simsbury, CT 06070
18 Series; T.C. 765	SA111SO	Installation of wing and empennage surface de-icing system.	EA	25635	Commuter A/C Manufacturing Corp. Box 904, Broome County Airport Binghampton, NY 13902
18 Series; T.C. 765	SA116SW	Combustion monitor.	EA	60100	Monitair Corporation Ramapo Valley Airport Spring Valley, NY 10977
18 Series; T.C. 765	SA186CE	Cowl flap modification kit TYL-6.	GL	14500	Barber-Colman Company Aircraft & Missile Products 1300 Rock Street Rockford, IL 61101
18 Series; T.C. 765	SA206SO	Heater fuse test switch and standby heater fuel system.	SO	75117	J.P. Stevens & Company, Inc. P.O. Drawer 5457, Station B Greenville, SC 29602
18 Series; T.C. 765	SA207CE	Pratt & Whitney R-985-APS engines per STC SE4-864 in aircraft with Beech 9,900 lbs. gross weight kit 766-1.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67202
18 Series; T.C. 765	SA222SO	RCA AVQ-55 radar system and a Narco UDI-2 DME system.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102

Aircraft Make, Model & T.C. No.	STC No.	Description	RC	STC Code	STC Holder
18 Series; T.C. 765	SA240EA	Elevator trim tab servo as optional equipment with Sperry SP-3 automatic pilot system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18 Series; T.C. 765	SA276WE	Carburetor air filter and scoop.	WE	67794	Richfield Oil Corporation 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA297SO	Cabin picture window.	SO	43090	H.V. Howren P.O. Box 20711 Atlanta Airport Atlanta, GA 30304
18 Series; T.C. 765	SA303WE	Heater relocated.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18 Series; T.C. 765	SA335WE	107-gallon integral auxiliary fuel tank in each outer wing with or without fuel dumping provisions.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18 Series; T.C. 765	SA351CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
18 Series; T.C. 765	SA422CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation Marquette Division 1145 Galewood Drive Cleveland, OH 44110
18 Series; T.C. 765	SA473EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4855 Sawyer Road International Airport Columbus, OH 43219
18 Series; T.C. 765	SA468WE	Super 18 type window between bulkheads 9 and 10.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 94106
18 Series; T.C. 765	SA793SW	PT6A-20 (turbo-prop) engines, 2 Hartzell HC-B3TN-3X/T10173-5 props, power compensator and pitch stabilizer system, outer panel fuel tanks, modified wing tip, lengthened nose, increase in angle of incidence of horizontal stabilizer.	SW	29000	The Dee Howard Company 130 South Terminal Drive San Antonio, TX 78205
18 Series; T.C. 765	SA817SW	Modified wing tip.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
18 Series; T.C. 765	SA818SW	Outer wing panel.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
18 Series; T.C. 765	SA832SW	Main wing spar reinforcement.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
18 Series; T.C. 630, 684, 710, 757, 765	SA176SW	Aluminum sheet covering of elevator, rudders and ailerons.	SW	26600	Sherman V. Cornstubble 3707 N. Terry Street Fort Worth, TX 76101
18 Series; T.C. 630, 684, 710, 757, 765, 770	SA365SO	Remove fabric from ailerons, elevator, flap and rudder and replace with aluminum alclad. Amended 10/2/68.	SO	43300	Hudson Aircraft Service P.O. Box 2471 W.A.S. Tallahassee, FL 32300
18, C45; T.C. 757, 765	SA4-167	Aerofilter 1050-B-83 full flow filter with element 1A0094.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
18, C45; T.C. 757, 765	SA4-1387	Deluxe aircraft seat Model 18.	WE	84370	Vroom Aircraft Supply 3321 Burton Avenue Burbank, CA 91500
18, C45; T.C. 757, 765	SA4-1436	Chobert Model 202-406 rivets.	WE	53780	J.F. McRae's Aero-Crafts Building 708, Oakland Airport Oakland, CA 94615
18, C45; T.C. 757, 765	SA4-1510	Rectangular windows in cabin. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
18, C45; T.C. 757, 765	SA4-1584	Two-piece plexiglass windshield and attaching parts. Amended 10/23/68.	WE	39877	Hamilton Aircraft Company, Inc. 6501 S. Park Avenue Tucson, AZ 85706

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45; T.C. 757, 765	SA19SW	Aircraft seat frame.	SW	17600	Broadie's Aircraft and Engine Service Meacham Field Fort Worth, TX 76106
18, C45; T.C. 757, 765	SA53CE	Stewart-Warner heater 940B 24 in fuselage. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45; T.C. 757, 765	SA70WE	Automatic oil temperature regulator added to Beech oil coolers 94-189850 LH and 94-189840-1 RH. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
18, C45; T.C. 757, 765	SA145SO	Three additional windows.	SO	02470	Aero Products Engineering, Inc. P.O. Box 602 Miami, FL 33101
18, C45; T.C. 757, 765	SA192WE	Baggage compartment.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45; T.C. 757, 765	SA276SW	Folding door bulkhead 5.	SW	74125	Spartan Aircraft Company Aviation Service Division Municipal Airport Tulsa, OK 74115
18, C45; T.C. 757, 765	SA299SO	Aerial camera.	SO	43090	H.V. Howren Atlanta Airport Atlanta, GA 30304
18, C45; T.C. 757, 765	SA698WE	75-gallon outer wing fuel tanks.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 757, 765	SA813WE	Fiberglass wing tips 11048.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
18, C45 Series; T.C. 757, 765	SA1008WE	Poly-Fiber covering of elevator, rudders, ailerons and flaps. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
18, C45 Series; T.C. 757, 765, 770	SA3-732	Full-view passenger window. REissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 757, 765, 770	SA24CE	Oval passenger windows. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA1-45	Increase in window dimensions. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
18, C45 Series; T.C. 765	SA1-60	Fiberglass nose bowl assemblies 1005-01-100 through -800.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA1-62	E18S wing tips Beech 414-18, 1500-610 right and -609 left.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA1-76	Full contour tail gear doors 215.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA1-242	Enlarged window on each side of fuselage.	EA	71915	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
18, C45 Series; T.C. 765	SA1-244	Enlarged windows in cabin.	EA	71915	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
18, C45 Series; T.C. 765	SA1-302	Upper nacelle modification.	GL	90150	Zelair Corporation P.O. Box 262 Defiance, OH 43512
18, C45 Series; T.C. 765	SA1-355	Increase to 9,000 lbs. gross weight and 450 hp.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA1-398	Pratt & Whitney R-985 engine installation with Simmonds Accessories 580047 fuel injector per STC SE1-391. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series; T.C. 765	SA1-427	Pratt & Whitney R-985 engine installation with Simmonds Aerocessories 580047 fuel injector per STC SE1-391, and takeoff weight increase to 9,800 lbs. and landing weight to 9,400 lbs. per STC SA2-820. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA1-502	Electrothermal propeller deicing system.	GL	38500	B. F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
18, C45 Series; T.C. 765	SA3-81	Nose cap modification.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
18, C45 Series; T.C. 765	SA3-277	Rear cabin porthole window modification and two additional windows forward of bulkhead 11.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-278	Web removed from bulkheads 9 and 10 and baggage compartment installed between bulkheads 10 and 11 and 11 and 12.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-279	Nose section modification including E18S type nose cone and cover assembly installation of radar and radio racks.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-280	Type E18S tail wheel fork and truss assembly.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-313	New picture window between frames 5 and 7 on both sides of fuselage.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
18, C45 Series; T.C. 765	SA3-343	One standard cabin window between bulkheads 8 and 9 right side opposite cabin door.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-391	Cabin window and interior modification. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18, C45 Series; T.C. 765	SA3-409	Increase fuselage height, large windows, panorama windows, stair door, and emergency exit. Amended 1/1/67.	EA	05200	Aircraft Industries of Canada, Ltd. P.O. Box 100 St. Johns, Quebec, Canada
18, C45 Series; T.C. 765	SA3-476	L-2C autopilot with altitude control and approach coupler. (Eligible only on aircraft modified per STC SA2-820.)	GL	49860	Lear, Inc. 3714 Jefferson Avenue, S.E. Grand Rapids, MI 49501
18, C45 Series; T.C. 765	SA3-563	Cargo door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18, C45 Series; T.C. 765	SA3-629	Scott oxygen system.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
18, C45 Series; T.C. 765	SA3-630	Two each skylight windows enlarged in cockpit with Conrad one-piece windshield per STC SA2-204.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
18, C45 Series; T.C. 765	SA3-632	Beech Kit 581-1, except angle of incidence change (Item 602) and stall strips (Item 607c) of Spec. A-765; with STC SA2-383, with or without STC's SA2-204 and SA3-409; and wing spar modification. Maximum gross weight: takeoff 9,500 lbs., landing 9,400 lbs.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA3-697	Hydraulic unfeathering accumulator system in each nacelle on aircraft with Hartzell propellers.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
18, C45 Series; T.C. 765	SA3-738	M-4 flight control system. (Model may also be designated as Conrad 9800D, Conrad 10,200.)	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series; T.C. 765	SA4-113	Safety performance kit, increase gross weight to 9,000 lbs. takeoff and landing when Pratt & Whitney R-985-AN4, -AN10, or -AN14B is modified using Hamilton Standard 22D30/6531-15 propellers or Hartzell HC-93Z30-2G10152-5 1/2 per STC SA1-118. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA4-119	Revised horizontal stabilizer angle of incidence from -2 degrees to -1/2 degrees. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series T.C. 765	SA4-152	One Model 940 Stewart-Warner heater in each wheel well. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA4-569	54-, 63-, or 107-gallon integral auxiliary fuel tank in each outer wing with or without fuel dump provisions and landing light installation.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA4-595	Fillet installation wing-fuselage and wing nacelle. (Eligible with STC's SA2-204 one-piece windshield and flush cockpit side windows; SA4-34 main landing gear door; SA4-113 Pratt & Whitney R-985-AN14B or -AN4 engines, wheel well door and elevator sealing strip; SA4-119 revised horizontal stabilizer angle of incidence; SA4-152 Stewart-Warner 940 heaters.)	WE	17108	Vance Breese 621 N. Arden Beverly Hills, CA 91203
18, C45 Series; T.C. 765	SA4-718	Auxiliary nose fuel tanks.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA4-769	Cambridge fuel air ratio analyzers.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA4-882	Large windows.	WE	17108	Vance Breese 621 N. Arden Beverly Hills, CA 91203
18, C45 Series; T.C. 765	SA4-910	New window.	WE	19900	Carma Aircraft Company P.O. Box 11312 Municipal Airport Tucson, AZ 85700
18, C45 Series; T.C. 765	SA4-922	Left-hand baggage door and baggage compartment.	WE	17108	Vance Breese 621 N. Arden Beverly Hills, CA 91203
18, C45 Series; T.C. 765	SA4-1035	Door frame between cabin and cockpit modified for folding door.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA4-1116	Three additional windows.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA4-1185	Stair door.	WE	17108	Vance Breese 621 N. Arden Beverly Hills, CA 91203
18, C45 Series; T.C. 765	SA4-1368	Wing tips.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA4-1397	Tricycle landing gear and nose assembly.	WE	84000	Volpar, Inc. 11035 Sutter Avenue Pacoima, CA 91331
18, C45 Series; T.C. 765	SA4-1486	Additional seats.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Sries; T.C. 765	SA4-1531	Tricycle landing gear and nose assembly with optional radome.	WE	84000	Volpar, Inc. 11035 Sutter Avenue Pacoima, CA 91331
18, C45 Series; T.C. 765	SA4-1536	Picture window G18 type.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series; T.C. 765	SA4-1578	Main cabin entrance door replaced with stair door.	WE	83780	Volitan Aviation, Inc. 12820 Pierce Street Pacoima, CA 91331
18, C45 Series; T.C. 765	SA4-1595	Divan B-138.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA4-1596	Five TSO chairs.	WE	10360	American Turbine Engine Company 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA4-1624	Non-icing vent fairings.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series T.C. 765	SA4-1645	Stewart-Warner 8259A heater.	WE	83780	Volitan Aviation, Inc. 12820 Pierce Street Pacoima, CA 91331
18, C45 Series; T.C. 765	SA1EA	Full contour tail gear doors 312. (Eligible on Models D18S, C45C, C45H, TC45G and TC45H when tail wheel modified per item 608 of Aircraft Spec. A-765.)	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA27SO	Elevator door spring. (Model may also be designated as Conrad 9800D.) Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA31SO	Tricycle landing gear and revised nose assembly with optional radome. (Model may also be designated as Conrad 10,200.) Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station
18, C45 Series; T.C. 765	SA46SO	Carburetor air scoop and air filter screen using carburetor and fiberglass air intake duct.	SO	73065	Gene E. Smith 4030 Matheson Avenue Miami, FL 33101
18, C45 Series; T.C. 765	SA55SW	Electrical pitch trim system.	SW	78430	Pat Thayer Aviation Electronics, Inc. P.O. Box 16037 International Airport San Antonio, TX 78205
18, C45 Series; T.C. 765	SA61CE	ALS-10A maximum safety light system. (Eligible only on aircraft having item 603, Aircraft Spec. A-765 installed.)	GL	12488	Atkins Light Corporation 7636 Lyndale Avenue, South Minneapolis, MN 55401
18, C45 Series; T.C. 765	SA76WE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
18, C45 Series; T.C. 765	SA80SO	Fiberglass nose cone.	SO	73065	Gene E. Smith 4040 Metheson Avenue Miami, FL 33101
18, C45 Series; T.C. 765	SA84SO	Seat track.	SO	02470	Aero Products Engineering, Inc. P.O. Box 48-602 Miami, FL 33101
18, C45 Series; T.C. 765	SA86SW	Enlarged cabin windows, left and right side, and emergency exit relocated.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
18, C45 Series; T.C. 765	SA111WE	Mark IV tricycle landing gear.	WE	84000	Volpar, Inc. 11035 Sutter Avenue Pacoima, CA 91331
18, C45 Series; T.C. 765	SA114SO	Substitute control wheel.	SO	37086	Garcia Aviation Company 15801 S.W. 120th Avenue Miami, FL 33101
18, C45 Series; T.C. 765	SA145SW	Cabin door (hinged at the bottom).	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
18, C45 Series; T.C. 765	SA148WE	RCA AVQ-55 weather mapping radar system.	WE	62080	Pacific Airmotive Corporation Aircraft & Eng. Center 3000 N. Clybourn Avenue Burbank, CA 91502
18, C45 Series; T.C. 765	SA149SO	Cabin picture windows.	SO	02470	Aero Products Engineering, Inc. P.O. Box 602 Miami, FL 33101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series; T.C. 765	SA150SW	Southwind heater 8259A (45,000 (B.t.u.), one in each side of the center wing section.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
18, C45 Series; T.C. 765	SA151SW	Windshield anti-icer system and three-gallon tank.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
18, C45 Series; T.C. 765	SA155SW	Metal covering of flaps.	SW	26600	Sherman V. Cornstubble 3507 N. Terry Fort Worth, TX 76101
18, C45 Series; T.C. 765	SA158SW	Pilot and copilot tracking seats.	GL	61234	National Flight Service, Inc. 105 E. Alexis Road Toledo, OH 43601
18, C45 Series; T.C. 765	SA161SW	Cabin picture windows left and right sides.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
18, C45 Series; T.C. 765	SA174CE	Twin-engine electronic synchronizer for aircraft equipped with Hartzell propellers.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
18, C45 Series; T.C. 765	SA209SW	Nose heater. (Model may also be designated as Conrad 9800D, Conrad 9800E.)	SW	26780	Crest Conversions, Inc. Route 13, Box 490E San Antonio, TX 78205
18, C45 Series; T.C. 765	SA266EA	Installation of Chamberlain Engineering 2003K-B radome and antenna mount transmitter/receiver support bracket for use with 12 inch Bendix radar system No. RDR-100 or RDR-110. Amended 3/11/70.	GL	61750	Norton Company Plastics & Snythetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
18, C45 Series; T.C. 765	SA276CE	Picture window.	CE	65300	Product Development Group, Inc. P.O. Box 117 Rose Hill, KS 67133
18, C45 Series; T.C. 765	SA285WE	Nose strut snubber for aircraft with Volpar Trigear.	WE	84000	Volpar, Inc. 11035 Sutter Avenue Pacoima, CA 91331
18, C45 Series; T.C. 765	SA289WE	Carburetor air scoops.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA290WE	Main landing gear doors.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA305WE	Cabin modified to G18 configuration.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA321SW	Fuel system modified with STC SA459WE - 165-gallon wing fuel tanks.	SW	26780	Crest Conversions, Inc. Route 13, Box 490E San Antonio, TX 78205
18, C45 Series; T.C. 765	SA331WE	Baggage compartment. 107-gallon main fuel tank in each outboard wing panel required per STC SA333WE.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA332WE	Propeller spinners and increase in maximum continuous power to 450 hp.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA333WE	107-gallon main fuel tank in each outboard wing panel.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA356WE	A3A autopilot.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA420WE	Stewart-Warner Series 940 combustion heaters in nacelle turtlebacks.	WE	39877	Hamilton Aircraft Company, Inc. 6501 S. Park Avenue Tucson, AZ 85706
18, C45 Series; T.C. 765	SA548WE	Air stair door.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA554WE	Square topped stair cabin door.	WE	83780	Volitian Aviation, Inc. 12820 Pierce Street Pacoima, CA 91331
18, C45 Series; T.C. 765	SA564WE	Nine seats.	WE	09850	Al's Aircraft Interiors 2700 E. Wardlow Road Long Beach, CA 90806

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series; T.C. 765	SA728WE	Extension of tail wheel. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma AVenue North Hollywood, CA 91406
18, C45 Series; T.C. 765	SA1011WE	100-gallon auxiliary outerwing fuel tanks.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA1135WE	Auxiliary 45-gallon wing leading edge fuel tank.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA1226WE	M-4 automatic flight control system.	EA	16030	The Bendix Corporation East Joppa Road Towson, MD 21204
18, C45 Series; T.C. 765	SA1258WE	Baggage compartment in forward and rear auxiliary fuel tank area and 100 gallon auxiliary fuel tank in outer wing.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA1277WE	Baggage compartment in forward and rear auxiliary fuel tank area, and 165 gallon auxiliary fuel tank in outer wing.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 684, 757, 765	SA1276WE	Replacement of carbon pile voltage regulator for 28-volt DC generator with Leland Airborne Products Type CSV-1105-2 solid state voltage regulator. Reissued 7/25/68.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91500
18 Series, C-45A, B, S, 50, 55 Series, 56TC, 65 Series; T.C. A630, A684, A710, A765, A770, A-757, 5A4, 3A16, 3A20	SA1675WE	Installation of exhaust gas temperature monitoring systems Model EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
18 Series, C-45, B, S, 23, 35, 50, 55 Series; T.C. A630, A684, A710, A765, A770, A757, A1CE, 777, 5A4, 3A16	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm).	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
18S, B18S, C-45C, F-2; T.C. 710	SA1152CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
C18, D18; T.C. A757, A765	SA389SO	Install cargo door; metalized ailerons, elevator, rudders, wing flaps. Reissued 4/12/73.	GL	05390	Aircraft Maintenance Specialists Janesville, WI 53545
C18S; T.C. 765	SA4-713	Installation of Stewart-Warner Model 940B heater in engine nacelles. REissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
C18S; T.C. 765	SA4-714	Installation of stabilizer angle of incidence change. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
C18S, AT-11, D18C, D18S, E18S, C45G, H, TC-45J (SNB-5), 3N, 3NM, 3TM, TC-45G, H, JRB-6, E18S-9700, G18S, H18; T.C. A-765, A-757,	SA2000WE	Installation of wing spar reinforcement. Reissued and amended 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aviation P.O. Box 11427 Tucson, AZ 85734
C18S, D18S, C-45G, H, TC45G, TC-45H; T.C. 757, A-765	SA4-875	Installation of Stewart-Warner Model 940B or 940F or 940C heater. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
C18S, D18S, C-45G, H, TC-45G, H, E18S, SNB-5, JRB-6, 3N, 3NM, 3TM; T.C. 757, 765	SA4-1584	Installation of two-piece plexiglass windshield. Amended 1/6/69.	WE	39877	Hamilton Aircraft Company, Inc. P.O. Box 11427 Tucson, AZ 85706
C18S, D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A757, A765	SA151SO	Installation of three additional windows. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
C18S, D18S, C-45G, -45H, TC-45G, -45H; SNB-5, JRB-6, 3N, 3NM, 3TM; T.C. A-757, A-765	SA419WE	Installation of modified tail wheel fork and truss assembly. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C18S, D18S, C-45G, H, TC-45G, H, SNB-5, 3N, 3NM, 3TM; T.C. 757, 765	SA1448WE	Installation of cockpit entrance door. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
C18S, D18S, E18S, E18S-9700, C-45G, H, TC-45G, H, J, SNB-5, JRB-6; T.C. 765, 757 (for C18S)	SA459WE	Installation of 167-gallon main fuel tank in each outboard wing panel. Amended 8/2/68.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
C18S, E18S, E18S-9700, G18S, H18S, C45G, -H, TC45G, -H, -J (SNB-5), JRB-6; T.C. 765	SA895SW	Outer wing panel spar beef up.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78216
C18S, C-45, C-45A, B, C, F, UC-45B, F, AT-7, AT-7A, B, C, JRB-1, -2, -3, -4, SNB-2, -2C; T.C. 757	SA1153CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
C18S thru H18S, AT-7, -7A, -7B, -7C, C45, C45A, -45G & H, UC-45B & F, TC45G & H; T.C. A765	SA1744WE	Installation of various series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
C18S, D18S, C-45G, H, TC-45J; 3N, 3NM, 3TM, JRB-6; T.C. A-757, A-765	SA1905WE	Installation of cockpit exterior door on left side. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 International Airport Tucson, AZ 85706
C18S, C-45, -45A, UC-45B, -45F, AT-7, -7A, -7B, -7C, D18S, C45G, H, TC-45G, H, E18S, E18S-9700, G18S; T.C. 757, 765	SA199SO	Fabric attachment clips in place of rib lacing cord. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
C-18S, C-45, -45A, UC-45B, -45F, AT-7, -7A, -7B, -7C, JRB-1, -2, -3, -4, SNB-2, -2C; T.C. 757	SA3010WE	Installation of wing spar reinforcement. Reissued 4/24/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, JRB-6, SNB-5, C45G-H, TC45G, -H, 3N, 3NM, 3TM; T.C. A-765	SA4-1462	Gross weight modification. Amended 3/21/75	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, SNB-5, C45G, -H, TC45G, -H; T.C. A-765	SA4-1571	Gross weight increase modification; installation of tricycle landing gear, windshield, outer wing fuel tanks, picture window. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, SNB-5, C45G, -45H, TC-45G, -45H, JRB-6; T.C. A-765	SA360WE	"PAC Tradewind Modification" - (Gross weight modification, empennage modification, installation of tricycle gear, windshield, outer wing fuel tanks, M-4 autopilot, Bendix RS10B fuel injection system, and optional R-985 APS4 engines). Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, E18S, E18S-9700, C45-G, -H, TC45-G, -H, -J, SNB-5, JRB-6; T.C. 765	SA370WE	Installation of 167-gallon auxiliary outer wing fuel tanks. Amended 8/2/68.	WE	06750	Aircraft TAnk Service, Inc. 10201 Cohasset Street Burbank, CA 91504
D18C, D18S, SNB-5, C45G, -H, TC-45G, -H; T.C. A-765	SA398WE	Electrical wiring simplification and modernization to effect improvements in electrical load distribution and protection. Reissued 1/9/75.	WE	06750	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, JRB-6, SNB-5, C-45G, -45H, TC-45G, -H; T.C. A-765	SA543WE	Installation of L2-C autopilot. Reissued 1/9/75.	WE	06750	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, SNB-5, C45-G, -H, TC-45G, -H; T.C. A-765	SA547WE	Installation of cockpit lever control knobs. Reissued 1/9/75.	WE	06750	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, E18S, G18S, SNB-5, JRB-6, H18, C45G, C45H, TC45G, TC45H; T.C. A-765	SA567WE	Installation of South Wind Model 8259-A heater in nose assembly of aircraft modified for tricycle landing gear per STC SA4-1531 or SA111WE. Reissued 1/9/75.	WE	06750	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D18C, -S, E18S, -9700, G18S, H18, C45G, TC45G, C45H, TC45H-J, JRB-6, SNB-5 and STC-SA111WE; A-35, B- thru F, 35R; G-35, H-J-K-M-N-P, V35, 5A4 and STC SA76SW; 35-33, A33, B33, 50, 50A, B, C, D50A, D50B, C, D, E, F, G, H, J, F50, 56TC, 60, 65, A65, 65-80, -A80, B80, 70, 95, B95, B95A, D95, 95-55, -55A, D55; T.C. 765, A777, 3A20, 5A4, 3A15, A12CE, 3A20, 3A16	SA660WE	Installation of HRD-type fire extinguishing and detector system. Amended 7/11/77.	WE	43180	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
D18C, D18S, E18S, E18S-9700, G18S, H18, C45G, C45H, TC45G, TC-45H, TC-45J (SNB-5), JRB-6; T.C. 765	SA745SW	Mitchell automatic flight system AK235, Century III autopilot with optional pitch trim and/or radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6, 3N, 3NM, 3TM; T.C. 765	SA1016WE	Installation of United Aircraft of Canada Ltd. PT6 series engines. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, H, TC-45G, H, J, 3N, 3NM, 3TM, JRB-6, SNB-5, RC-45J, NSB-5P, UC-45J; T.C. 765	SA1154CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
D18C-5; T.C. 770	SA1155CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
D18C, D18S, E18S-9700, C45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6, G18S, H18, C-45J; T.C. A-765	SA1171WE	Installation of two AiResearch TPE 331 Series engines, tricycle landing gear, wing platform. Amended 1/22/69.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
D18C, D18S, C45G, C45H, E18S, TC-45G, -45H, JRB-6, SNB-5, 3N, 3NM, 3TM; T.C. A-765	SA1192WE	Modification of main spar. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, E18S, E18S-9700, G18S, H18, C45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6; T.C. 765	SA1636WE	Installation of AiResearch TPE 331 series engine, tricycle landing gear and ventral fin, extension of fuselage and related changes. Amended 4/20/72.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
D18C, D18S, E18S-9700, E18S, C-45G, -45H, TC-45G, -45H, -45J (SNB-5), JRB-6, G-18S, H18; T.C. A-765	SA1832WE	Installation of Volpar Tricycle Landing Gear. Amended 10/26/73.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
D18C, D18S, E18S-9700, C45G, H, J, 3N, 3NM, 3TM, TC-45G, H, J, JRB-6; T.C. A-765	SA1961WE	Cabin floor installation. Amended 10/19/77.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, -S, E18S-9700, C45G, -H, TC-45G, -H, -J, SNB-6, JRB-6; T.C. 765	SA2204WE	Installation of 2 AiResearch TPE 331-1 series turbo prop engines with Hartzell HCB3TN propellers: 8-1/2 inches extension of fuselage and ventral fin, tricycle landing gear installation and related modifications. Amended 8/27/71.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA2353WE	Installation of cargo pod. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D18C, D18S, E18S, E18S-9700, G18S, H18, 3N, 3NM, 3TM, C-45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6; T.C. A-765	SA2414WE	Modification for increase in maximum weights. Amended 8/26/76.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
D18C, D18S, E18S, G18S, E18S-9700, H18, 3N, 3NM, 3TM, JRB-6, C-45G, TC-45G, C-45H, TC-45H, TC45J (SNB-5); T.C. A-765	SA2437WE	Modifications for increase in maximum weights. Reissued 5/27/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18C, D18S, E18S, G18S, E18S-9700, H18; C-45G, H, TC-45G, H, J, RC-45J, 3N, 3NM, 3TM, JRB-6; 65, A65, 65-80, -A80, -B80, -88, -90, -A90, A65-8200, 65-A80-8800, 65-A90-1, -2, -3, 70; 60, A60; 56TC, A56TC; B90, C90, E90; 99, 99A, A99, 100, A100; T.C. A-765, A-765, 3A20, A12CE, 3A16, 3A20, A14CE	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, H, TC-45G, H, J, (SNB-5), JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA2794WE	A Bendix M-4C Autopilot System is installed. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18C, D18S, E18S-9700, G18S, H18, C45G, C45H, TC45G, TC45H, TC45J (SNB-5), JRB-6, 3N, 3NM, 3TM, E18S; T.C. A765	SA2815WE	Removal of fabric covering from the wing flaps, ailerons, rudders and elevators and replace and recover these surfaces with aluminum. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, -45H, TC-45G, -45H, TC-45J (SNB-5), RC-45J (SNB-5P), 3N, 3NM, 3TM, JRB-6; T.C. 765	SA3009WE	Installation of wing spar reinforcement. Reissued 4/14/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91601
D18C, D18S, E18S-9700, G18S, H18, RC45J, 3N, 3NM, 3TM, C45G, C45H, TC45G, TC-45H, TC-45J (SNB-5), JRB-6; T.C. A-765	SA3150SW-D	Mitchell automatic flight system AK607 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 7/26/76.	SW	6000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
D18C, D18S, E18S, E18S-9700, G18S, H18, C45G, H, TC45G, H, J(SNB-5), RC-45J (SNB-5P), 3N, 3NM, 3TM, JRB-6; T.C. A-765	SA3229WE	Installation of wing spar reinforcement. Issued 7/9/76.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91601
D18C, D18S, E18S, E18S-9700, C45G, H, TC45G, H, J(SNB-5), JRB-6, G18S, H18; T.C. 765	SA3385WE	Installation of AiResearch TPE 331-1-101B engines and increase gross weight to 11500 pounds. Amended 6/25/77.	WE	84000	Volpar, Inc. 7929 Hayvenhurst Ave. Van Nuys, CA 91406
D18C, D18S, E18S, E18S-9700, C-45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), RC-45J (SNB-5P), 3N, 3NM, 3TM, JRB-6; T.C. A-765	SA3765WE	Installation of a pilot cockpit door. Issued 10/26/78.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91601
D18S; T.C. A-765	SA249GL	Installation of P&W R985-AN1 engines modified in accordance with STC SE4-1136 in Beech D18S aircraft modified in accordance with STC SA4-1427 using existing installation procedures. Issued 6/21/78.	GL	65920	Rand J. Aviation Route 2, Box 335-BB Lake Geneva, WI 53147
D18S; T.C. 765	SA656CE	Install Sky-Ox oxygen system kit No. SK-1001-7.	CE	66460	Rawdon Engineering Company 10416 E. Central Avenue P.O. Box 1718 Wichita, KS 67201

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D18S; T.C. 765	SA659CE	Install Janitrol Model B3040 combustion heaters.	CE	66460	Rawdon Engineering Company 10416 E. Central Avenue P.O. Box 1718 Wichita, KS 67201
D18S, C-45G, TC-45G, C-45H, TC-45H; T.C. A-765	SA1-102	2000X and 2100X Series radomes. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
D18S, C-45G, -45H; T.C. 765	SA1-118	Installation of Hartzell Propellers with and without unfeathering kit. Reissued 5/12/76.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
D18S, E18S, G18, H18, C-45G, C-45H, TC-45G, TC-45H, TC-45J; T.C. A-765	SA1-467	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 alt. hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
D18S, C45G, C45H, TC-45G, TC45H; T.C. A765	SA2-938	Installation of cabin picture windows. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D18S, E18S, G18S, C45G, C45H; T.C. 765	SA3-635	Installation of Weston-Garwin Carruth Division Part Number 31-257 change letter "B" 100 ampere generator. Reissued 10/9/69.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
D18S, C-45G, C-45H, T.C. -45G, TC-45H; T.C. A-765	SA4-553	Gross weight increased to 9,000 pounds and maximum continuous power increased to 450 hp. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A-765	SA4-554	Installation of stabilizer angle of incidence change. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A-765	SA4-555	Main landing gear door installation. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A-765	SA4-556	Installation of Stewart-Warner Model 950B heater in engine nacelles. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, C45G, H, TC45G, H; T.C. 765	SA4-879	Installation of 37-gallon auxiliary fuel tank in each outboard wing. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aviation P.O. Box 11746 Tucson, AZ 85734
D18S, E18S, C45G and H Series; T.C. A-765	SA4-934	Installation of 100 amp generator.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91500
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. 765	SA4-981	Installation of R-985 series engine modified in accordance with STC SE4-864 in lieu of original engines. Reissued 5/25/73.	SO	34120	Export Airmotive, Inc. 4471 N.W. 36th Street Miami, FL 33166
D18S, C45G, H, TC-45G, H, SNB-5, JRB-6, 3N, 3NM, 3TM and C18S; T.C. A-765 and 757	SA4-1323	Installation of stair type entrance door, rectangular windows and outside opening baggage compartment. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, C45G, H, TC-45G, H, SNB-5, JRB-6, 3N, 3NM, 3TM; T.C. 765	SA34WE	Two 42.5-gallon auxiliary fuel tanks. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, C-45G, C-45H, TC-45G, TC-45H, TC-45J (SNB-5), JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA74WE	Modification of horizontal stabilizer and attachment to provide 1-1/2 degree angle of incidence increase and elevator down spring installation. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, C-45G, C-45H; T.C. A765	SA86SO	Modification of instrument panel and engine control pedestal modification. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A765	SA95SO	Installation of baggage loading door. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D18S, E18S, E18S-9700, G18S, H18S, C45G, C45H, TC45G, TC45H, SNB-5; T.C. A765	SA97CE	Model A or B high intensity wing tip lights, Model C or D tail light, with or without Model 1 or 2 fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
D18S, C-45G, C-45H, TC-45G, TC-45H;	SA107SO	Installation of modified baggage compartment between fuselage stations 257 and 313. Reissued 9/11/79.	SO	08170	Air-Life Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D18S, C45H, SNB-5; T.C. A765	SA120WE	Interior arrangements. Reissued 4/28/77.	WE	39877	Hamilton Aviation Company, Inc. P.O. Box 11427 Tucson, AZ 85706
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A765	SA128SO	Modification of control wheel. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D18S, C45G, TC45G, C45H, TC45H, SNB5, E18S, E18S-9700, G18S; 23, 23A; 35, A35, B35, C35, D35, E35, F35, G35; H35, J35, K35, M35, N35, P35, S35; 35-33, 35-A33, 35-B33; 65, 65-80; 95, B95, B95A, D95A, 95-55, 95-A55; T.C. A765, A1CE, A777, 3A15, 3A15, 3A20, 3A16	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
D18S, SNB-5 (TC-45J), C-45G, C-45H, TC-45G, TC-45H; T.C. A765	SA172SO	Installation of new modified dorsal fin. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D-18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A765	SA175SO	Picture window installation for Beech -18, 75 inch extended fuselage. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Duraham Airport Box 173 Morrisville, NC 27560
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A765	SA184SO	Installation of Hamilton Standard 22D30 propellers having B.F. Goodrich electric de-icers (STC SP185SO). Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A765	SA186SO	Installation of wing and empennage surface de-icing system (Goodrich lightweight pneumatic). Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D18S, SNG-5 (TC-45J), C-45G, C-45H, TC-45G, TC-45H and these models as previously modified under STC SA172SO	SA191SO	Installation of a battery box in the aft fuselage section. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D18S, E18S, E18S-9700, G18S, C45G/H; T.C. A765	SA192SO	Installation of seats. Amended 10/30/68.	SO	11900	Associated Aircraft Equipment, Inc. P.O. Box 542 Miami, FL 33101
D18S, E18S, C-45G, H, TC-45G, H, J, RC-45J, E18S-9700, G18S, H18, 3N, 3NM, 3TM; T.C. A-765	SA193GL	Installation of Norton radome Bit 4160X. Issued 9/14/77.	GL	61750	Norton Company Plastics and Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A765	SA198SO	Installation of a pneumatic surface de-icing system. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D18S, E18S, G18S, C45 Series, H18; 35-33 thru 35-C33A; A35 thru 33R, H35 thru M35; N35, P35, S35, V35; D50 thru D50C, E50 thru H50; 65; 95, B95, B95A, D95A, 95-55, -A55, -B55, -C55; T.C. A-765, 3A15, A-777, 3A15, 3A15, 5A1, 3A20, 3A16	SA232EA	Installation of Tactair omni lock model OL-1 and optional installation of Tactair localizer adapter model LA-1 (for use with Tactair model omni lock model CL-1). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A765	SA291SO	Installation of passenger door installation in Beech 18 type aircraft. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
D18S, E18S, E18S-9700, G18S, H18, C45G, C45H, TC45G, TC45H, SNB-5; T.C. A-765	SA407CE	Supplemental high intensity position light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
D18S, E18S, E18S-9700, G18S, H18, 3N, 3NM, 3TM, TC-45J (SNB-5), C45G, C45H, TC-45G, TC-45H; T.C. A-765	SA572WE	Increase in gross weight to 10,100 pounds. When aircraft has been modified, installation of nacelle vent manifold optional. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 International Airport Tucson, AZ 85706
D18S, C-45G, TC-45G, TC-45H; T.C. A-765	SA794EA	Installation of cockpit roof hatch.	EA	17300	Bristol Aerospace (1968) Limited P.O. Box 874 Winnipeg, Manitoba, Canada
D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A-765	SA795EA	Installation of Edo Model 56-7850A twin seaplane floats. Amended 4/21/75.	EA	17300	Bristol Aerospace (1968) Limited P.O. Box 874 Winnipeg, Manitoba, Canada
D18S, JRB-6, SNB-5, C-45G, C-45H, TC45G, TC45H; T.C. A-765	SA805WE	Modification of cowling. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, E18S, G18S, C45G, C45H, TC-45G, -45H; T.C. A-765	SA809WE	Collins WP-103 weather mapping radar system. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, E18S, G18S, C45G, C45H, TC-45G, -45H; T.C. A-765	SA810WE	Hoskins high intensity position light system. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, C-45G, H, TC-45G, H, SNB-5, 3N, 3NM, 3TC; T.C. A-765	SA842WE	Installation of Stewart-Warner 940-F24 Combustion Heater. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, E18S, G18S, H18, C-45G, C45H, TC-45G, -H, -J; T.C. A-765	SA921WE	Bendix RDR-100 weather mapping radar system. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, C45G, H, TC45G, H, 3N, 3NM, 3TM, SNB-5; T.C. A-765	SA980WE	Modification made per FAA sealed summary, Drawing 25600, Sheet 3. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, SNB-5, JRB-6, 3NM, 3TM, C-45G, C-45H, TC-45G, H; T.C. A-765	SA989WE	Installation of revised carburetor air mixing chamber and ram airscoop. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, D18C, SNB-5, JRB-6, C-45G, C-45H, TC-45G, TC-45H; T.C. A-765	SA1026WE	Installation of executive interior; removal of aft cabin bulkhead. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, C45G, H; TC-45G, H; SNB-5, JRB-6, 3N, 3NM, 3TM; T.C. 765	SA1059WE	Cargo door in fuselage. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 International Airport Tucson, AZ 85706
D18S, JRB-6, SNB-5, C-45G, C-45H, TC-45G, TC-45H; T.C. A-765	SA1074WE	Interior installation. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, SNB-5, JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA1533WE	Spar reinforcement. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, TC-45J (SNB-5), C-45G, TC-45G, C-45H, TC-45H, JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA1821WE	Installation of two AiResearch TPE 331-1-101B engines, tricycle landing gear, fuselage extension and related modifications. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, E18S, E18S-9700, G18S, H18, C-45G, C-45H, TC-45G and H; T.C. 765	SA1894WE	Installation of Hamilton Standard 22D30/6533-21S or -22S propellers. Amended 4/3/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North HOllywood, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D18S, TC-45J (SNB-5), C45, TC-45G, C45H, TC-45H, JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA1998WE	Installation of Bendix Model M-4C automatic flight control system. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, -C, E18S, E18S-9700, G18S, H18, C45G, -H, TC45G, -H, SNB-5, JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA1999WE	Installation of cargo floor. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, D18C, E18S, G18S, E18S-9700, H18, TC-45J, (SNB-5), C-45G, TC-45G, C-45H, TC-45H, JRB-6, 3N, 3NM, 3TM (These models must incorporate the provisions of STC SA2437WE to be eligible for modification); T.C. A-765	SA2494WE	Installation of extended nose section and modification to the elevator down spring system. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D-18S, E-18S, E-18S-9700, G18S, H18, TC-45J (SNB-5), C-45G, TC-45G, C-45H, TC-45H, JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA2523WE	Installation of extended nose section. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, E18S, E18S-9700, G18S, H18, C45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6; T.C. A-765	SA2737WE	Installation of spar strap extension to outboard wing panel. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18S, E18S, D18C, C45G, C45H, TC45G, TC-45J (SNB-5), JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA2781WE	Installation of pilot cockpit door. Amended 1/2/74.	WE	39877	Hamilton Aircraft Company, Inc. P.O. Box 11427 Tucson, AZ 85706
E18S, E18S-9700, G18S, H18 (& D18S, C45G, C45H when modified per STC SA3-279); T.C. A-765	SA1-135	Installation of 2003X series radome. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
E18S, E18S-9700, G18S, H18, C-45G, C-45H; T.C. A-765	SA1-232	Support assembly 2003X-R-03 for 12" RCA AVQ-50 antenna, transmitter-receiver and accessory box and 2103X-R-01 for 12" RCA AVQ-55 antenna and transmitter-receiver. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
E18S, E18S-9700, G18S, H18; T.C. A-765	SA1-276	Antenna mounts for 18" Bendix ANT-1G antenna and 15" RCA AVQ-55 or 15" RCA AVQ-20 antenna. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
E18S, E18S-9700, G18S, H18; T.C. A-765	SA1-608	Radome assemblies 2003X-C for Collins WP-103 12" antenna, 2003X-R for RCA 12" AVQ-20 antenna for 18" AVQ-55 antenna. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
E18S; T.C. 765	SA4-626	Powerplant modifications. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
E18S; T.C. 765	SA4-737	Main landing gear door installation. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
E18S; T.C. A-765	SA3828SO	Installation of fuel boost pump in accordance with STC SA1016WE.	SO	02387	Aeronautical Consultants - Atlanta 5659 Canyon Creek Trail N.E. Atlanta, GA 30305
t+1 E18S; T.C. A-765	SA1721WE	Installation of United Aircraft of Canada, Ltd. PT6A-27 turboprop engines and lengthening of fuselage. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
E18S; T.C. A-765	SA2782WE	Installation of pilot cockpit door. Issued 11/1/73.	WE	39877	Hamilton Aircraft Company, Inc. P.O. Box 11427 Tucson, AZ 85706
E18S; T.C. 765	SA3471WE	Modification for increase in maximum weight. Issued 8/17/77.	WE	10360	American Turbin Engine Co. 1150 Busch Garden Court Pasadena, CA 91105

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
E18S, E18S-9700; T.C. 765	SA836SW	UAC PT6A-20 (Turbo-prop) engines tricycle landing gear, power compensator, pitch stabilizer system and related modifications. Reissued.	EA	05200	Aircraft Industries of Canada, Ltd. Box 100 St. Johns, Quebec, Canada
E18S, E18S-9700, G18S, H18; T.C. A765	SA899EA	Installation of Grimes three-light strobe system as a supplemental light system. Issued 2/15/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
E18S, E18S-9700; T.C. A-765	SA1243WE	Combined installation of PT6A turboprop engines (per STC SA111WE), tri-gear (per STC SA1016WE), and "Tradewind" single tail. Reissued 9/22/75.	GL	84000	Volpar, Inc. 7929 Hayvenhurst Avenue Van Nuys, CA 91406
E18S, E18S-9700; T.C. 765	SA1391WE	Engine cowl and exhaust modifications. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
E18S, E18S-9700, G18S, H18; T.C. 765	SA1956WE	Installation of fuselage aft cargo door. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 International Airport Tucson, AZ 85706
E18S, E18S-9700, G18S, H18; T.C. 765	SA2493WE	Installation of cockpit exterior door. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
E18S, E18S-9700, G18S, H18; T.C. A-765	SA2736WE	Installation of pilot cockpit door. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
E18S, E18S-9700, G18S, H18; T.C. A-765	SA3126WE	Installation of pilot cockpit door. Issued 1/7/76.	WE	84000	Volpar, Inc. 7929 Hayvenhurst Avenue Van Nuys, CA 91406
E18S, G18S; T.C. 765	SA4-1090	Installation of R-985 series engines modified in accordance with STC SE4-865 in lieu of original engines. Reissued 5/25/73.	SO	34120	Export Airmotive, Inc. 4471 N.W. 36th Street Miami, FL 33166
G18S; T.C. 765	SA1242SW	Elongated fiberglass nose. Issued 1/15/71.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
H-18; T.C. A-765	SA1483CE	Installation of Tull microwave landing system. Issued 4/9/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
C45 Series; T.C. 765	SA1-279	Cabin windows enlarged and exit and original windows relocated.	EA	71915	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
C45 Series; T.C. 765	SA3-358	Airplane and powerplant modifications related to civil conversion.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
C45 Series; T.C. 765	SA3-375	L-2C autopilot with approach coupler and altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
C45 Series; T.C. 765	SA3-377	A3A autopilot. (Eligible on aircraft with 8,750 lbs. gross weight or less.)	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
C45 Series; T.C. 765	SA3-442	Hamilton Standard 22D30/6531-15, or Hartzell HC-93Z30-2D/10152-5 1/2, HCB3Z30-2D/10152-5 1/2, or HCB3Z30-2D/10160-6 propellers and related modifications.	WE	39877	Hamilton Aircraft Company, Inc. 6501 South Park Avenue Tucson, AZ 85706
C45 Series; T.C. 765	SA3-562	Certification kit.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
C45 Series; T.C. 765	SA3-653	Flite Line chair 275.	CE	84450	Williard F. Walpole 228 S. Wichita Wichita, KS 67202
C45 Series; T.C. 765	SA3-676	Rear baggage compartment.	CE	84450	Williard F. Walpole 228 S. Wichita Wichita, KS 67202

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C45 Series; T.C. 765	SA4-728	Nose tank.	WE	07600	Air Fleet, Inc. 323 S. 24th Street Phoenix, AZ 85000
C45 Series; T.C. 765	SA4-733	Fuel flow meter removed.	WE	07600	Air Fleet, Inc. 323 S. 24th Street Phoenix, AZ 85000
C45 Series; T.C. 765	SA4-872	Redesigned door with integral steps.	WE	42450	John H. Horrell 330 W. Oregon Phoenix, AZ 85000
C45 Series; T.C. 765	SA4-1256	Astrodome.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
C45 Series; T.C. 765	SA4-1299	Voltage regulators moved to front side of forward bulkhead.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
C45 Series; T.C. 765	SA4-1323	Stair type entrance door, rectangular windows, and outside opening baggage compartment.	WE	39877	Hamilton Aircraft Company, Inc. 6501 South Park Avenue Tucson, AZ 85706
C45 Series; T.C. 765	SA4-1377	Large window.	WE	46300	Jet Propulsion Laboratories 4800 Oak Grove Drive Pasadena, CA 91109
C45 Series; T.C. 765	SA4-1509	Baggage compartment relocated between stations 229 and 258. (Loading schedule required.)	WE	49365	Lancer Engineering 26927 Fond Du Lac Road Palos Verdes Estates, CA 90274
C45 Series; T.C. 765	SA6CE	E18S nose cone on C45G and C45H baggage door.	CE	84450	Williard F. Walpole 228 S. Wichita Wichita, KS 67202
C45 Series; T.C. 765	SA63SO	Modification of instrument panel installation and engine and engine control pedestal modification.	EA	25635	Commuter A/C Manufacturing Corp. Box 904 Broome County Airport Binghampton, NY 13902
C45 Series; T.C. 765	SA119EA	Sperry SP-3 autopilot.	GL	61234	National Flight Services, Inc. 105 E. Alexis Road Toledo, OH 43601
C45 Series; T.C. 765	SA142SW	AN155-8L turnbuckle barrels.	SW	19966	Carswell Aero Club Carswell Air Force Base Fort Worth, TX 76101
C45 Series; T.C. 765	SA147WE	Removal of main cabin door and hinge pins only.	WE	72120	Skylark Aviation Route 2, Box 501 Elsinore, CA 92330
C45 Series; T.C. 765	SA151WE	Five port fuel selector valves and electric emergency fuel boost pump.	WE	01720	Aero American Corporation Box 21Y, Ryan Field Tucson, AZ 85700
C45 Series; T.C. 765	SA151CE	Optional oil shutoff valve system. Eligible on aircraft modified per STC SA3-442.	WE	01720	Aero American Corporation Box 21Y, Ryan Field Tucson, AZ 85700
C45 Series; T.C. 765	SA177CE	Certification kit.	WE	01720	Aero American Corporation Box 21Y, Ryan Field Tucson, AZ 85700
C45 Series; T.C. 765	SA225WE	Electric emergency fuel pumps.	WE	01720	Aero American Corporation Box 21Y, Ryan Field Tucson, AZ 85700
C45 Series; T.C. 765	SA320SW	Whittaker valve substituted for Beech 414-189791-1.	SW	26780	Crest Conversions, Inc. Route 13, Box 490E San Antonio, TX 78205
C45 Series; T.C. 765	SA371WE	Enlarged door opening and door to facilitate parachuting and cargo dropping.	WA	03270	Chief, Forest Service U.S. Department of Agriculture 1210 Independence Avenue, S.W. Washington, D.C. 20250
C45 Series; T.C. 765	SA397CE	Standard size window between bulkheads 8 and 9.	EA	25860	Department of Conservation N. Ten Mile Drive Jefferson City, MO 65102
C45 Series; T.C. 765	SA426SW	Carburetor ram airscoop extension.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
C45 Series; T.C. 765	SA542EA	Installation of Janitrol Combustion Heater.	GL	42134	State of Ohio Department of Highways Flight Operations Bureau Columbus, OH 43216

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C45G, -H, 3N, 3NM, 3TM; T.C. A-765	SA4-1583	Installation of Beech 47-gallon nose fuel tank. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
C-45G, C-45H, TC-45G, TC-45H; T.C. A765	SA1418O	Installation of 75-inch fuselage extension. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
C45G; T.C. 765	SA272WE	AT-11 camera window cutout. (No passenger seats are to be between bulkheads 5 and 7.) Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
C-45G, C-45H, TC-45H, SNB-5, IRB-6; T.C. 765	SA435WE	Removal of large cargo door for special purpose operations as aerial photography, etc. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company 6501 South Park Avenue Tucson, AZ 85706
C-45G, C-45H, TC-45G, TC-45H, T.C. A765	SA605SO	Basic certification modification. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
C-45G, TC-45G, C-45H, TC-45H, TC-45J, SNB-5, RC-45J, SNB-5P, 3N, 3NM, 3TM, JRB-6; T.C. A-765	SA2966WE	Removal of emergency exit on right hind of fuselage for puspose of aerial photography. Issued 12/13/74.	WE	56860	Meadow-Lark Aviation Chino Airport, Merrill Avenue Chino, CA 91710
C-45H; T.C. A-765	SA1GL	Installation of wing tip boom to measure angle of attack, yaw, and slip. Issued 7/20/72.	GL	43670	University of Illinois Institute of Aviation U of I - Willard Airport Savoy, IL 61874
C45H; T.C. 765	SA159WE	Alcohol tank. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
C-45H; T.C. A-765	SA1641WE	Interior arrangement. Amended 6/7/68.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
C-45H; T.C. A-765	SA1752WE	Installation of AiResearch Air Conditioning system.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
C45H, 3N, 3NM, 3TM; T.C. A-765	SA952WE	Installation of exterior door on left side of aircraft. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
23 Series; T.C. A1CE	SA401SW	Full flow oil filter.	SW	77016	The Superior Flow Company P.O. Box 12504 Oklahoma City, OK 73112
23 Series; T.C. A1CE	SA449WE	Pneumatic pitch assist PC-1 and optional installation altitude hold AH-1. Reissued October 1973.	SW	17490	Britten Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
23 Series; T.C. A1CE	SA450WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
23 Series; T.C. A1CE	SA488WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
23 Series; T.C. A1CE	SA560WE	Flight control system B-4 including pitch assist PC-1, altitude hold AH-1, and navigational coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
23 Series; T.C. A1CE	SA812WE	BSA stability augmentation system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
23 Series; T.C. A1CE	SA1376WE	Installation of Brittain Industries BSA-3 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
23 Series; T.C. A1CE	SA1475WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
23 Series; T.C. A1CE	SA1724WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
23 Series; T.C. A1CE	SA2148WE	Installation of Brittain Industries, B-VII, NAV-2B, B2C and BSA-6 flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
23, 23A, A23A, A23-19, 19A, M19A, B19; T.C. A1CE	SA106GL	Installation of Gerdes Products wheels and brakes. Issued 2/13/76.	GL	37850	Gerdes Products Company, Inc. P.O. Box 217 Brookville Air-Park Brookville, OH 45309
23, A23-19, 19A, B23, C23, 95, B95; T.C. A1CE, 3A16	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
23, A23-19, 19A, B23, C23, 95, B95; T.C. A1CE, 3A16	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. single and twin engine and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
23, A23, A23A, A23-19, A23-24; T.C. A1CE	SA597EA	Installation of electronic voltage alarm, Drawing No. 80106.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
23; E35, F35; H35, J35, K35, M35, N35, P35, 35-33, -A33, -B33, -C33; 95, C-55; A45, D45; T.C. A1CE, A-777, 3A15, 3A16, 5A3	SA589WE	Installation of full-flow lube oil filters on the aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
23, A23, A23A, A23-19, -24, -19A, B19, M19A, B23, C23, A24, A24R; 35, A35, B35, C35, D35, E35, F35, G35, 35R; H35, J35, K35, M35, N35, P35, S35, V35, 35-33, 35-A33, -B33, -C33A, -C33, V35A, B, 36, A36, E33, E33A, E33C, F33, F33A, F33C; 50 (L23A), B50 (L-23D), C50, D50 (L-23E), D50A, D50B, D50C, D50E, E50 (L-23D, RL-23D), F50, G50, H50, J50; 95-55, 95-A55, 95-B55, (T-42A), 95-B55D, -C55, 95, B95, B95A, D95A, E95, D55, D55A, E55, E55A, 56TC, A56TC, 58; 65 (L23F), A65, A65-8200, 65-80, 65-A80, -A80-8800, 65-B80, 65-88, B90, C90, 65-90, 65-A90, 65-A90-1 (U-21A, RU-21A, RU-21D), 65-A90-2 (RU-21B), 65-A90-3 (RU-21C), 70; 60, A60; 99, 99A, 100; T.C. A1CE, A-777, 3A15, 5A4, 3A16, 3A20, A12CE, A14CE	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14(14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417

BEECH AIRCRAFT CORP. 26

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
23; A35 thru G35; H35 thru P-35, 35-33, -A33, -B33; 50, B50, C50, D50, D50A, D50B, C, E; 95, B95, B95A, D95A; 95-55, -A55, -B55; T.C. A1CE, 777, 3A15, 5A4, 3A16, 3A16	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
23, 35, 95; T.C. A1CE, 777, 3A16	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
23, A23, A23A, A23-19, -19A, -24, B23; T.C. A1CE On Models A65, 65-B80, 65-88, 70; T.C. 3A20	SA693CE	Install AC induction air filter Type AAF-104. Amended 8/20/70. Install AC induction air filter Type AAF-100. Amended 2/2/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
23; 33, 35; 45; 50; 60; 65, 65-80, -88, -90, -8200, 70, B90; 95-55, 55, 56, 95; T.C. A1CE, 3A15, A-777, 5A3, 5A4, A12CE, 3A20	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
23, A23, A23A, A23-19, -24, -19A, B19, M19A, B23, C23, A24, A24R; 35, A35, B35, C35, D35, E35, F35, G35, 35R: H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, 35-A33, -B33, -C33, -C33A, 36, A36, E33, E33A, E33C, F33, F33A, F33C; 50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; 95-55, 95-A55, -B55, (T42A) 95-B55D, -C55, 95, B95, B95A, D95A, E95, D55, D55A, E55, E55A, 56TC, A56TC, 58; 65 (L23F), A65, A65-8200, 65-80, 65-A80, -A80-8800, -B80, 65-88, B90, C90, 65-90, 65-A90, 65-A90-1 (U-21A, RU-21A, RU-21D),65-A90-2, (RU-21B), 65-A90-3 (RU-21C), 70; 60, A60; 99, 99A, 100; T.C. A1CE, A-777, 3A15, 5A4, 3A16, 3A20, A12CE, A14CE	SA800EA	Installation of aviation white anti-collision strobe lights, Whelen Models A429, A430, A434, A450, A408W or A470W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R; 35, A35, B35, C35, D35, E35, F35, G35, 35R; H35, J35, K35, M35,; N35, P35, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, G33, E33C, 36, F33A, F33C, A36, S35, V35, V35A, V35B; 50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; E55, E55A, 58, 58A, 56TC, A56TC; B55, A60, B-80, 65-A65, A65-8200, 65-80, 65-90, 65-A90, 65-A90-1, 65-A90-2, -3, B-90, C90, E90, 99, 99A, A-100; T.C. A1CE, 5A4, A-777, 3A15, 3A16, A12CE, 3A20, A14CE	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light system two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 11/30/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
23 (S/N M-555 and up), A23, A23A, A23-19, A23-24, B23, C23, 19A, B19, M19A, A24, A24R, B24R, C24R; T.C. A1CE	SA1147EA	Installation of DeVore "Tel-Tail" lights on upper surface of horizontal stabilator. Issued 5/8/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
23, A23, A23A, A23-19, -19A, -24, B23; 35, A35 thru G35; 35-33, -A33, -B33, -C33, -C33A, H35, J-, K-, M-, N-, P-, S-, V-; 95, B95, B95A, -55, -A55, B55, B55B, C-55; T.C. A1CE, A777, 3A15, 3A16	SA1262WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
23, A23, A23A, A23-19, A23-24; S35, V35, 35-33, 35-A33, B-33, -C33, 35-C33A; 50, B50, C, D, D50A, B, C, E, F50, F, G, H, J; 95, B95, -A, D95A, -55, -A55, -B55, C-55; T.C. A1CE, 3A15, 5A4, 3A16	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R; T.C. A1CE	SA1346SW	Mitchell automatic flight system AK341 cons. of Century I and opt. Omni Tracker. Issued 7/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R; T.C. A1CE	SA1348SW	Mitchell automatic flight system AK342 cons. of Century II autopilot with opt. radio coupler. Issued 7/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
23, A-23, A-23A, A23-19, A-23-24, 19A, B23; 35, A35, B35, C35, 35R, D35, E-, F-, G-; H35, J-K-M-, 35-33, N35, 35-A33-B33, P35, S35, 35-C33, E33, V35, V35A, 35-C33A, E33A; T.C. A1CE, 777, 3A15	SA1716WE	Installation of exhaust gas temperature system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R, B24R; T.C. A1CE	SA3214SW-D	Mitchell automatic flight system AK342 consisting of Century IIB autopilot with optional radio coupler. Issued 6/77/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
23, A23, A23A, A23-19, 19A, M19, M19A, A23-24 B23, C23, A24, A24R, B24R, C24R; T.C. A1CE	SA3223SW-D	Mitchell automatic flight system consisting of Century I autopilot and optional omni tracker. Issued 6/21/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A23-24; T.C. A1CE	SA3291WE	Installation of Pathfinder autopilot systems. Issued 11/9/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
B23; T.C. A1CE	SA664CE	Installation of Hoskins MK1B Light System. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
C23; T.C. A1CE	SA3331SW-D	Mitchell automatic flight system AK779, consisting of Century I autopilot with optional omni tracker. Issued 1/24/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C23; T.C. A1CE	SA3332SW-D	Mitchell automatic flight system AK780 consisting of Century IIB autopilot with optional radio couplers. Issued 1/24/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
Beech C23; T.C. A1CE	SA3799WE	Installation of flexible stainless steel oil cooler hoses. Issued 11/28/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
A24R, B24R, C24R; T.C. A1CE	SA4015WE	Installation of SDI model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 9/17/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B24R; T.C. A1CE	SA1701SW	Mitchell command electric trim system Model AK454. Issued 7/11/73.	SW	60000	Mitchell Industries, Inc. Box 610 Municipal Airport Mineral Wells, TX 76067
B24R; T.C. A1CE	SA3016SW-D	Mitchell AK544 cons. of Century III autopilot with opt. radio coupler and glide slope coupler. Issued 1/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
B24R; C24R; T.C. A1CE	SA3156WE	Installation of Pathfinder autopilot systems. Issued 3/16/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
B24R, C24R; T.C. A1CE	SA3160SW-D	Install Mitchell command electric trim system Model AK454. Issued 10/4/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C24R; T.C. A1CE	SA3313SW-D	Mitchell automatic flight system AK768, consisting of Century IIB autopilot with optional radio coupler. Issued 12/28/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C24R; T.C. A1CE	SA3314SW-D	Mitchell automatic flight system AK769 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 12/28/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C24R; T.C. A1CE	SA3315SW-D	Mitchell command electric trim, AK770. Issued 12/28/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral WElls, TX 76067
35 "Bonanza"; T.C. 777	SA1-460	Auxiliary wing tip fuel tanks. Reissued 2/14/75	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route #1, Box 172D Leesburg, FL 32738
35 Series; T.C. 777	SA222CE	Reinforce front lower carry-through section & wing attach fittings by the addition of steel plates and fittings. Amended 10/7/69.	CE	47250	R.M. Jourdan & James Flanagan 8801 East 40 Highway Kansas City, MO 64108
35 Series; T.C. 777	SA387SO	Installation of Aviation Elec. Omni bearing tester Model OBT-X in accordance with AET Drawing Nos. 1001, 1002, 1003.	SO	13250	Aviation Electronics, Inc. DeKalb-Peacntree Airport Chamblee, GA 30005
35 Series; T.C. 777	SA599EA	Installation electronic voltage alarm, Drawing No. 80105.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
35 Series; T.C. 777	SA800SW	AK245 Century II Autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777	SA1493WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777	SA1902SW	Automatic flight system AK348 cons. of Century I autopilot with optional omni tracker. Issued 7/19/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
35 Series; T.C. 777	SA2144WE	Installation of Madras Air Service Part No. MAS 102 wing tips.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
35 Series; T.C. 777	SA2208WE	Installation of Red-Q-Mark Signet A-MK-100 or A-MK-110 marker assembly. Amended 8/7/70.	WE	67500	Res-Q-Mark International, Inc. 44 West Stetson Drive Scottsdale, AZ 85251
35 Series; T.C. 777, 3A15	SA1-55	Federal F-200 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
35 Series; T.C. 777, 3A15	SA1-341	Oil-free vacuum pump PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
35 Series; T.C. 777, 3A15	SA1-343	Oil-free vacuum pump.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35 Series; T.C. 777, 3A15	SA1-377	Replacement of d.c. belt-driven generator and regulator with Leece-Neville belt-driven alternator with built-in silicon rectifier.	SO	33239	Ellingsworth Products Co., Inc. 1009 E. Broadway Louisville, KY 40201
35 Series; T.C. 777, 3A15	SA1-379	Lube oil filter PB55-1 on aircraft with Continental E-185-1 through -11 engines. Amended 9/11/67.	NE	36728	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
35 Series; T.C. 777, 3A15	SA1-478	Griswold lateralizer.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109
35 Series; T.C. 777, 3A15	SA1-491	Flare rack modification to include radio equipment mount.	NE	81400	Usher Aviation Radio Division Municipal Airport New Haven, CT 06510
35 Series; T.C. 777, 3A15	SA1-569	Continental IO-470-J engine (fuel injection) and Hartzell propeller BHC-92ZF-1D1/8447.	EA	74930	Glen Stauffer 1000 Susquehanna Avenue West Pittston, PA 18643
35 Series; T.C. 777, 3A15	SA1-584	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
35 Series; T.C. 777, 3A15	SA1-587	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
35 Series; T.C. 777, 3A15	SA1-628	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
35 Series; T.C. 777, 3A15	SA3-3	BC Chinook cabin heater.	RM	28500	Dakota Aviation Company P.O. Box 18 Huron, SD 57350
35 Series; T.C. 777, 3A15	SA3-8	L-2B automatic pilot including approach coupler and altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series; T.C. 777, 3A15	SA3-56	Oxygen equipment, Purtain Type E bottles and Scott #8800 console.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
35 Series; T.C. 777, 3A15	SA3-58	Grimes D-7080-2-12 rotating beacon.	GL	60135	Moody Bible Institute 820 N. LaSalle Street Chicago, IL 60607
35 Series; T.C. 777, 3A15	SA3-196	Lear ADF-12C kit complete and LTRA-5 with scope complete.	GL	17070	Louis J. Brandix, Sr. Southwest Airport Springfield, IL 62701
35 Series; T.C. 777, 3A15	SA3-241	Electric motor-driven AN4100 fuel pump.	GL	37076	C.W. Gaenzler Wayne Major Airport Inkster, MI 48141
35 Series; T.C. 777, 3A15	SA3-264	Radio rack aft of baggage compartment.	CE	44340	Interstate Airmotive, Inc. Lambert Field St. Louis, MO 63155
35 Seris; T.C. 777, 3A15	SA3-276	Scott 8800 oxygen console.	CE	78616	Topeka Aircraft Sales & Service Municipal Airport Topeka, KS 66603
35 Series; T.C. 777, 3A15	SA3-298	Electric motor-driven fuel booster pump.	GL	37076	Carl W. Gaenzler Wayne Major Airport Inkster, MI 48141
35 Series; T.C. 777, 3A15	SA3-317	Baggage compartment windows.	CE	40686	Gordon O. Harper 6070 Grant Street Omaha, NB 68108
35 Series; T.C. 777, 3A15	SA3-673	L-2B autopilot with or without altitude control and/or approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series; T.C. 777, 3A15	SA4-96	Manual-electric control for Beech 215-107/215-207-88 propeller.	WE	23426	C & M Plumbing & Heating 11667 Monte Vista Avenue Chino, CA 97170
35 Series; T.C. 777, 3A15	SA4-133	Automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35 Series; T.C. 777, 3A15	SA4-190	Automatic rudder control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series; T.C. 777, 3A15	SA4-191	L-2 automatic pilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series; T.C. 777, 3A15	SA4-238	Thompson TF 2800 engine-driven fuel pump installation on Continental O-470-G engine.	WE	33460	Engineering Modification Company 6850 Vineland Avenue North Hollywood, CA 91603
35 Series; T.C. 777, 3A15	SA4-280	Ceco CE-9136, AN-4100 or AN-4101 electric fuel pump.	WE	38200	Peter Gluckmann 61 Lick Place San Francisco, CA 94101
35 Series; T.C. 777, 3A15	SA4-282	Tactair T-3 automatic pilot.	WE	64708	Planeservice, Inc. 7250 Hayvenhurst Avenue Van Nuys, CA 91408
35 Series; T.C. 777, 3A15	SA4-344	'"B" arcon system.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
35 Series; T.C. 777, 3A15	SA4-393	Fiberglas reinforced plastic wing tips incorporating positions.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
35 Series; T.C. 777, 3A15	SA4-435	Automatic rudder control Model B.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series; T.C. 777, 3A15	SA4-436	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series; T.C. 777, 3A15	SA4-489	Automatic rudder control.	NW	35690	Flightcraft, Inc. 6200 N.E. Marine Drive Portland, OR 97208
35 Series; T.C. 777, 3A15	SA4-550	Continental E-225-8 engine with Hartzell HC-12X20-7C/8433 propeller and modification of fuel system.	WE	60178	D.H. Moreton 560 Marquette Street Pacific Palisades, CA 90272
35 Series; T.C. 777, 3A15	SA4-559	20-gallon auxiliary fuel tank.	WE	77260	Symons Engineering P.O. Box 45002 Airport Station Los Angeles, CA 90009
35 Series; T.C. 777, 3A15	SA4-562	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
35 Series; T.C. 777, 3A15	SA4-618	Right and left rear windows.	NW	61710	Northwest Air Service P.O. Box 20 Boeing Field Seattle, WA 98101
35 Series; T.C. 777, 3A15	SA4-651	Continental E-225-8 engine and Hartzell propeller.	WE	19945	Carson Airplane SErvice Gillespie Field Santee, CA 92071
35 Series; T.C. 777, 3A15	SA4-703	30409A lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corportation 4069 Hollis Street Oakland, CA 94608
35 Series; T.C. 777, 3A15	SA4-707	Aerofilter 30409A lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
35 Series; T.C. 777, 3A15	SA4-708	Aerofilter 30409A lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
35 Series; T.C. 777, 3A15	SA4-716	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA4-785	Hartzell HC-12X20-7D/8433-0 propeller.	WE	86300	R.K. Wilson 3808 Via La Selva Palos Verdes Estates, CA 90274
35 Series; T.C. 777, 3A15	SA4-819	Hartzell HC-12X20-7D/8433-0 propeller.	WE	78618	Torbet Aircraft, Inc. Orange County Airport Santa Ana, CA 92702

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35 Series; T.C. 777, 3A15	SA4-862	Wing tip modification to fiberglass construction.	WE	38235	C.E. Goetz 11665 Monte Vista Avenue Chino, CA 91710
35 Series; T.C. 777, 3A15	SA4-1146	Hartzell HC-12X20-7C/8433-0 propeller.	WE	09730	Alpha Aircraft P.O. Box 63 Bakersfield, CA 93300
35 Series; T.C. 777, 3A15	SA4-1239	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA4-1245	Ski bag compartment.	NW	35690	Flightcraft, Inc. 6200 N.E. Marine Drive Portland, OR 97208
35 Series; T.C. 777, 3A15	SA4-1260	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA4-1305	Hartzell HC-12X20-7E/8433-0 propeller.	WE	21400	Chandler Aircraft Service 151 W. Lambert Avenue El Monte, CA 91731
35 Series; T.C. 777, 3A15	SA4-1437	Leece-Neville alternator A001-2002AA and regulator A001-3533RA.	WE	82600	Vegas Airways, Inc. P.O. Box 347 Redondo Beech, CA 90277
35 Series; T.C. 777, 3A15	SA4-1538	Oil-air separator.	WE	81790	Vaeth Aircraft Repair 13 and Benson Streets Upland, CA 91786
35 Series; T.C. 777, 3A15	SA4-1611	Anticollision beacon Roto-Lite X5000, either 12 or 24-volt, on the top or bottom of fuselage.	WE	49690	The Norman Larson Company Van Nuys Airport Van Nuys, CA 91408
35 Series; T.C. 777, 3A15	SA4-1629	Installation of Brittain Industries Model M668 wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d.b.a. Osborne Tank & Supply Star Route, Box 12 Oro Grande, CA 92368
35 Series; T.C. 777, 3A15	SA13EA	Single-axis autopilot AF-510A, AF-512A or AF-512B.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005
35 Series; T.C. 777, 3A15	SA22SW	AK087, AK087E or AK087R automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA23CE	210419 governor.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
35 Series; T.C. 777, 3A15	SA33SW	Beech T-24 ailerons 45-135050-3 with servo attach fittings 45-115090.	SW	05070	Aircraft & Engine Enterprises P.O. Box 68 Moore, OK 73060
35 Series; T.C. 777, 3A15	SA41SW	Continental engine modified for fuel injection per STC SE23SW.	GL	15500	The Bendix Corporation 717 N. Bendix Drive South Bend, IN 46600
35 Series; T.C. 777, 3A15	SA57CE	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
35 Series; T.C. 777, 3A15	SA64SW	AK100 automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA90SW	AK101 automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA91SW	AK102 automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA109WE	M-4 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series; T.C. 777, 3A15	SA112EA	AF-510A, AF-512A or AF-512B autopilots.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35 Series; T.C. 777, 3A15	SA115CE	Turbo volt Model "Three-Five" emergency electrical and vacuum system.	GL	84500	Ward Aero, Inc. P.O. Box 219 Haines Airport Three Rivers, MI 49093
35 Series; T.C. 777, 3A15	SA115SW	Combustion monitor.	SW	77110	The Swearingen Company P.O. Box 6904 San Antonio, TX 78209
35 Series; T.C. 777, 3A15	SA130EA	AF-510A, AF-512A, or AF-512B autopilots.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005
35 Series; T.C. 777, 3A15	SA136WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA137WE	Beech wing tip kit 35-660.	WE	21400	Chandler Aircraft Service 151 W. Lambert Avenue El Monte, CA 91731
35 Series; T.C. 777, 3A15	SA147CE	Moni-Meters on aircraft equipped with King KY-90, KY-95, Narco Mark 4 or 12 transceivers.	GL	60086	Mobile Engineering 220 Southdale Center Minneapolis, MN 55435
35 Series; T.C. 777, 3A15	SA152CE	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
35 Series; T.C. 777, 3A15	SA165SW	Automatic pilot AK121.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA219EA	Installation of Katz Integrated Flight Indicator. Amended 5/21/69.	NE	36300	Forest City Aviation Service 749 Congress Street Portland, ME 04102
35 Series; T.C. 777, 3A15	SA265SO	Extension addition to nose landing gear doors.	SO	43504	Thomas E. Hutchinson P.O. Box 128 Morrisville, NC 27560
35 Series; T.C. 777, 3A15	SA269WE	Pneumatic pitch assist PC-1 and optional installation altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA292WE	Alternator A-14-0 or A-14-5 and voltage regulator A-20.	WE	14000	Aviation Specialities Company, Inc. 2410 E. Airline Way Phoenix, AZ 85000
35 Series; T.C. 777, 3A15	SA293CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Place Port Columbus Int'l Airport Columbus, OH 43219
35 Series; T.C. 777, 3A15	SA294CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Place Port Columbus Int'l Airport Columbus, OH 43219
35 Series; T.C. 777, 3A15	SA312WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA321SO	Tank type wing tip plates.	SO	26580	Corben Development Corporation P.O. Box 1603 Venice, FL 33595
35 Series; T.C. 777, 3A15	SA321WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA322WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA323WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA332EA	Electronic voltage alarm.	EA	53500	McKinley Engineering Company P.O. Box 275 Palisades Park, NJ 07650
35 Series; T.C. 777, 3A15	SA334SW	Alternator.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78205
35 Series; T.C. 777, 3A15	SA358SW	Carburetor air filter (dry type).	SW	77016	The Superior Flow Company P.O. Box 12504 Oklahoma City, OK 73112

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35 Series; T.C. 777, 3A15	SA358WE	One-piece windshield.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
35 Series; T.C. 777, 3A15	SA359WE	Supercharged Continental engine E225-8.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
35 Series; T.C. 777, 3A15	SA374SW	Automatic pilot AK131, AK131E and AK131E-3, pitch trim system AK132, and lateral guidance radio AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA380SW	A-C generator.	SW	06000	Aircraftsmen, Inc. Hangar 2, Will Rogers Field Oklahoma City, OK 73125
35 Series; T.C. 777, 3A15	SA396WE	Dual fuel flow and manifold pressure gage, Beech 35-380050.	WE	64708	Planeservice, Inc. 7240 Hayvenhurst Avenue Van Nuys, CA 91408
35 Series; T.C. 777, 3A15	SA431SW	Pitch trim system AK139.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA475EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
35 Series; T.C. 777, 3A15	SA477SW	Nose gear.	SW	05070	Aircraft & Engine Enterprises P.O. Box 68 Moore, OK 73060
35 Series; T.C. 777, 3A15	SA477WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Birttain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA519SW	Front spar center section beef up.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
35 Series; T.C. 777, 3A15	SA533WE	B-4 flight control system, including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigational coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA542WE	Engine cowl flap assembly.	WE	28300	Cutter Aviation, Inc. 2451 E. Buchanan Phoenix, AZ 85034
35 Series; T.C. 777, 3A15	SA609SW	Hartzell PHC-3AVF-4/8433-4 propeller.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
35 Series; T.C. 777, 3A15	SA626WE	Split rear seat.	WE	14010	Aviation Trim Company 16300 Stagg Street Van Nuys, CA 91408
35 Series; T.C. 777, 3A15	SA631WE	Flight control system B-4 including pitch assist PC-1, altitude hold AH-1 and navigational coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA638SW	AK202 with Century III autopilot, pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WEll s, TX 76067
35 Series; T.C. 777, 3A15	SA677WE	Flight control system B-4 including pitch assist PC-1 altitude hold AH-1 and navigational coupler NAV-1, optional hi-lo sensitivity adaptor. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA701SW	AK205 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA824SW	Model AK248 consisting of Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35 Series; T.C. 777, 3A15	SA888WE	G300BL bracket and mirror assembly to left wing tip and G300BR bracket and mirror assembly to right wing tip.	WE	69580	Safe-See, Inc. 16213 S. WEstern Avenue Gardena, CA 90247.
35 Series; T.C. 777, 3A15	SA893WE	Continental IO-470-N engine and Flottorp F12A-3/8400-2 propeller.	WE	28300	Cutter Aviation, Inc. 2451 E. Buchanan Phoenix, AZ 85034
35 Series; T.C. 777, 3A15	SA1035WE	Turbosupercharged Continental TSIO-520-D engine. Amended 11/18/69.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
35 Series; T.C. 777, 3A15	SA1056WE	BSA-2 stability augmentation system and optional rudder add-on kit. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA1113WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA1150WE	Gyro sense element relocated to remote position. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA1369WE	Installation of Brittain Industries, Inc. Model BSA-3 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA1476WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA1477WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA1530WE	Installation of Brittain Model B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA1531WE	Installation of Brittain Model BSA-4 Stability Augmentation System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA1736WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA1883WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 3A15	SA1269SW	Mitchell automatic flight system model AK328 cons. of Century I autopilot with omni tracking system. Issued 3/1/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 3A15	SA1379WE	Installation of Brittain Industries Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 3A15	SA1558WE	Installation of Brittain Industries Model B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 3A15	SA1644SW	Mitchell automatic flight system AK415, cons. of Century IIB autopilot with optional radio coupler. Issued 4/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 3A15	SA1762WE	Installation of Brittain Industries Models B-5, NAV-2B and B2C Flight Control Systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series, 95 Series; T.C. 777, 3A15, 3A16	SA1387WE	Installation of Brittain Industries Model NAV-2A Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35, A35, 35B, C, D, E, F, G; T.C. A-777	SA2700WE	Installation of Airborne Electronics solid state automatic propeller control Model 350A. Amended 6/24/76.	WE	03625	Airborne Electronics 899 Haddock Street Foster City, CA 94404
35, A35, B35; T.C. 777	SA2201SW	Ventral fin. Issued 6/23/75.	SW	78420	Texas Aviation Engineering Company Meacham Field Fort Worth, TX 76106

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA1-570	Installation of Hartzell Model HC-A2X20-4 or HC-A2V20-4 propeller equipped with 8433 or 8833-4 or V8433, V8833-4 blades respectively. Amended 6/29/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
35, A35 thru G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36; T.C. A-777, 3A15	SA11GL	Installation of Cleveland 6.00-6 wheels and brakes. Amended 9/23/74.	GL	23260	Cleveland Wheels & Brakes Division Van Sickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
35, A35 thru G35, H35, 35R, J35, K35, M35, N35, P35, S35, 45, A45, D45, 95, B95, B95A, D95A, E95, 95-55, -A55, -B55A, -B55B, -B55, -C55, -C55A, E55, D55A, E55, E55A; T.C. A-777, 3A15, 3A16	SA19GL	Install Cleveland 7.00-8 wheels and brakes. Amended 9/23/74.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
35, A35 thru H35, J35, M35, 35R, 95; T.C. A-777, 3A15	SA23EA	Installation of third cabin window on both sides of fuselage. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, J35, K35, M35, 35-33; T.C. A777, 3A15	SA28EA	Installation of 12-gallon fiberglass wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, J35, K35, M35, 35-33; T.C. A777, 3A15	SA30EA	Installation of 13.5 gallon fiberglass wing tip tank assembly. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, 35R, D35, E35, F35, G35; T.C. 777	SA41EA	Wet-to-dry vacuum pump conversion kit 300-2. Reissued and Amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
35, A35 thru P35, 35-33, -A33, -B33; T.C. A777, 3A15	SA80EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35, A35 thru H35, J35, K35, M35, N35, P35, S35, V35, 33, A33, B33, C33, C33A, E33, E33A, 55, A55, B55, B55A, B55B, C55, C55A, D55, D55A, 95, B95, B95A, D95A, E95; T.C. A-777, 3A15, 3A16	SA93GL	Install left hand side window, P/N W-2048 or W/T-2048. Amended 6/19/79.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
35, A35 thru H35, J35, K35, M35, N35, P35, S35, V35, 33, A33, B33, C33, C33A, E33, E33A, 55, A55, B55, B55A, B55B, C55, C55A, D55, D55A; T.C. A-777, 3A15, 3A16	SA94GL	Install right side door window, P/N W-2049 or W/T-2049. Amended 6/19/79.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
35, A35 thru H35, J35, K35, M35, N35, P35, S35, 33, A33, B33, 55, A55, B55, B55A, B55B, 95, B95, B95A, D95A, E95; T.C. A-777, 3A15, 3A16	SA95GL	Install one piece windshield (P/N W2050 or WT2050). Amended 6/19/79.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
35, A35, B35, C35, D35, E35, F35, G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. A-777, 3A15	SA152NW	Installation of deck and glare shield (with or without instrument lights). Issued 1/13/75.	NW	70384	R.J. Schroers 4479 139th Avenue, S.E. Bellview, WA 98006

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, A35 thru H35, J35, K35, M35, N35, 35R, 35-33, 35-A33; T.C. A-777, 3A15	SA177EA	Installation of Monitair angle of attach system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
35, A35, B35, C35, D35, E35, F35, G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33D, F33A, F33, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A; T.C. A-777, 3A15	SA197NW	Installation of Clark three-light gear position indicator system. Issued 7/17/75.	NW	22786	Harold M. Clark, Jr. 7703 Husky Loop S.E. Olympia, WA 98503
35, A35 thru H35, J35, K35, M35, 35-33, N35, P35; T.C. A777, 3A15	SA283EA	Alternate fiberglass fuel tip tanks. Reissued 2/6/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, 35R, J35, K35, M35, N35, P35, 35-33, S-35, 35B-33, V35, V35TC, 35-A33, -C33, -C33A, 95-55, -A55, -B55, -C55, 95, B95, B95A, D95; T.C. A777, 3A15	SA593WE	Installation of single-piece windshield. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B- thru H-, J-, K-, M-, N-, P-, S-, V-; 65-88; 95-55, -A55, -B55, B55B, -C55; T.C. 3A15/A-777, 3A20, 3A16	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs SA617SW, SA638SW, SA651SW, SA701SW, SA742SW, SA754SW, SA755SW.	SW	60000	EDO-AIRE Mitchell P.O. Box 610 Mineral Wells, TX 76067
35, A35 thru G35, R35, H35 thru S35, 35-33, -C33, E33, F33, F33A, F33C, G33, V35, V35A, B, 36, A36, A36TC; T.C. 3A15, A-777	SA808SO	Installation of Beryl D'Shannon fiberglass tip tanks (15 gallons each), and fuel transfer system. Amended 2/8/80.	SO	16505	Beryl D'Shannon Specialties, Inc. Suite 120 175 West Wieuca Road Atlanta, GA 30342
35, A35 thru G35, 35R, H35, J35, K35, M35, N35, P35, S35, V35; T.C. A-777, 3A15	SA838SO	Installation of Beryl D'Shannon fiberglass air scoops (inlet and exit). Amended 12/16/76.	SO	16505	Beryl D'Shannon Aviation P.O. Box 76155 Atlanta, GA 30328
35, A35 thru G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35 thru S35, V35, V35A, V35B, 36, 36A; T.C. A-777, 3A15	SA942SO	Installation of adjustable directional trim device on lower aft fuselage (ventral location) Issued 7/1/77.	SO	16505	Beryl D'Shannon Aviation Specialities, Inc. P.O. Box 76155 Atlanta, GA 30328
35 thru 35R, 35-33 thru A36; T.C. 3A15, A-777	SA995SO	Installation of a single-piece sloped windshield. Amended 5/7/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4530 Jettridge Drive, N.W. Atlanta, GA 30327
35 thru 35R, 35-33 thru A-36; T.C. 3A15, A-777	SA997SO	Installation of a single-piece sloped windshield. Amended 11/21/79.	SO	16505	Beryl D' Shannon Aviation Specialties, Inc. c/o F.K. Leddick & Associates, Inc. 175 W. Wieuca Rd., Suite 120 Atlanta, GA 30342
35, A35, B35, C35, D35, E35, F35, G35, 35R (S/N D-1 thru D-4865); T.C. 777	SA999WE	Installation of either Jasco #6340-1 (35A) alternator kit or Jasco #6555-1 (50A) alternator kit. Amended 10/28/76.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
35, 33, 36, 45 Series; T.C. A777, 3A15, 5A3	SA1000CE	Install cabin and engine compart- fire suppression system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
35, A35, B35, C35 (up to and including S.N. 2901); T.C. A-777	SA1375WE	Installation of Dukes Astronautics Model 4140-00-39 Auxiliary Fuel Pump into fuel system.	NW	24200	Collins Aviation Service 6660 Perimeter Road Boeing Field Seattle, WA 98108
35, 33, 95, 56 Series; T.C. 3A15, 3A16	SA1497SW	Sombra screen kit No. BE-6L, BE-6S, BE-4. Issued 8/11/72.	SW	73750	Sombra Corporation 1122 LaVista Drive McAllen, TX 78501
35, A35 thru G35, 35R, H35, J35, K35, M35, N35, P35; T.C. 777, 3A15	SA1722WE	Installation of Fiberglass tail fairing. Reissued 1/12/76.	WE	13300	Aviation Enterprises, Inc. 3900 E. Spring Street Long Beach, CA 90806

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, A35, B35, C35, D35, E35, G35, F35, 35R; T.C. 777	SA2000SW	Dual control wheel. Issued 8/15/75.	SW	42185	Ray Hollander Box 600 El Paso, TX 79944
35, A35, B35, C35, Serial D1 through D2900; T.C. A-777	SA2029WE	Installation of Delta Sigmatronix Emergency Electric Fuel Pump Kit, PK-2, in lieu of Beech hand pump P/N 35-924230 (on aircraft equipped with Beech P/N 35-921171 or P/N 35-924065 fuel unit).	WE	29500	Delta Sigmatronix, Inc. P.O. Box 6183 San Jose, CA 95150
35, A35 thru F35, 35R, 35-33, 35-A33, -B & C33, H35, J35, K35, M35, N35, P35; T.C. 3A15	SA2219WE	Installation of Filtrator Company engine crankcase breather and vacuum pump air-oil separator. Reissued 7/10/75.	SO	16505	Beryl D'Shannon Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru G35, R35, H35, J35, K35, M35, N35, P35; T.C. A-777, 3A15	SA2271WE	Installation of long fiberglass tailcone to replace the short factory installed tailcone. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, 35R; J35, K35, M35, N35, P35, S35, V35, V35A, V35 (turbo), 35-33, -A33, -B33, -C33, -C33A, E33, E33A; T.C. 777, 3A15	SA2470WE	Installation of anticollision lighting system. Issued 2/8/72.	WE	70500	Scientifico Scientific Components Company 350 Vista Bays Newport Beach, CA 92660
35, A35 thru H35, J35, K35, M35, N35, P35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, F33, F33A, F33C, G33; T.C. A-777, 3A15	SA2633WE	Installation of enlarged window and baggage compartment. Amended 8/16/78.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, D35, F35, G35, 35R, E35; H35, J35, K35, M35, N35, P35, 35-33, 35-A33, -B33, -C33, E33, F33, G33, V35, V35A, V35B, S35, 35-C33A, E33A, E33C, F33A, F33C, 36, A36; T.C. A-777, 3A15	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA2858WE	Installation of right and left hand cockpit side windows. Reissued 1/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA3020WE	Installation of exhaust silencer. Reissued 2/9/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, A35B, D, E, F, G, 35R; T.C. 777	SA3271SW-D	Mitchell yaw damper system YK631. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A777	SA3337WE	Installation of ventral air skeg. Amended 4/2/79.	WE	84396	Walker Engineering, Inc. 2240 Sawtelle Boulevard Los Angeles, CA 90064
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA3678WE	Installation of air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
35-33, -A33, -B33, -C33, -E33C, -C33A, E33, E33A, F33, F33A, F33C, G33, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; 36, A36; T.C. 3A15	SA1474CE	Installation of redundant engine fuel flow transmitter and cockpit indicator. Reissued 4/24/79.	WE	71740	Silver Instruments, Inc. 2436 Stanwell Drive Concord, CA 94520
35-A33, -B33, -C33, C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA3025SW-D	Automatic flight system AK497, cons. of Century IIB autopilot with optional radio coupler. Issued 9/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 (Normal or Utility Category), A35, B35, C35, D35, E35, F35, G35 (Utility Category); T.C. A-777	SA3191WE	Installation of wing tip fences. Issued 5/11/76.	WE	64690	John Pixton Enterprises P.O. Box 342 Santa Rosa, CA 95402

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, 35R; T.C. A-777	SA1423WE	Wing truss reinforcement, front spar, and change of hinge points for landing gear idler arm. Amended 6/14/76.	WE	59470	Fred J. Miller 355 Vista Bays Newport Beach, CA 92660
A35 thru F35, G35 and 35R, H35, J35, K35, M35; T.C. A-777, 3A15	SA1-27	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
A35 thru G35, H35; T.C. A77, 3A15	SA1-303	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35 thru G35, H35; T.C. A777, 3A15	SA1-368	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35, B35, C35, D35, E35, F35, G35, H35; T.C. A-777, 3A15	SA144EA	Increase to 200 pounds in maximum gross weight for takeoff and landing. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35 thru H35, J35, K35, M35, N35, P35; 35-33, -A33, -B33, C33A, E33A, E33C, F33A, F33C, S35, V35, V35A, V35B; T.C. A-777, 3A15	SA153EA	Installation of Beryl D'Shannon fiberglass tip tanks (15 gal. RB4-100, ref. STC's SA283EA and SA134EA) and fuel transfer system. Amended 9/28/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4530 Jettridge Drive, S.W. Atlanta, GA 30227
A35 thru H35, J35, K35, M35; T.C. A-777, 3A15	SA181EA	Increase of 200 pounds in maximum gross weight for takeoff and landing. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35, B35, C35, D35, E35, F35, G35, T.C. A-777	SA384WE	Adjustable pilot and copilot seat. Reissued 1/12/76.	WE	13300	Aviation Enterprises, Inc. 3900 E. Spring Street Long Beach, CA 90806
A35 thru G35, 35R, H35, J35; T.C. A-777, 3A15	SA507WE	Adjustable back rest. Reissued 1/12/76.	WE	13300	Aviation Enterprises, Inc. 3900 E. Spring Street Long Beach, CA 90806
A35, B thru E; T.C. 777	SA1270SW	Mitchell automatic flight system model AK328 cons. of Century I autopilot with omni tracking system. Issued 3/1/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35 thru H35, J35, K35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, F33, F33A, G33; T.C. A-777, 3A15	SA2081WE	Installation of Madras Air Service P/N MAS 102 wing tips. Amended 4/5/74.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
A35 thru H35; T.C. A-777, 3A15	SA2131WE	Installation of Delta Sigmatronix emergency electric fuel pump P/N 29000 in above models equipped with Beech P/N 35-924230 fuel unit.	WE	29500	Delta Sigmatronix, Inc. P.O. Box 6183 San Jose, CA 95150
A35 thru H35, J35, K35; T.C. 777, 3A15	SA2200SW	Continental IO-520-B or -BA engines. Issued 9/5/75.	SW	78420	Texas Aviation Engineering Company Meacham Field Fort Worth, TX 76106
A35, B35, C35, D35, E35, F35, G35; T.C. A-777	SA2546WE	Installation of Pathfinder Engineering Corp. Model P1-( ) autopilot system. Amended 11/13/74.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
A35, B35, C35, D35, E35, F35, G35; T.C. A-777	SA2547WE	Installation of Pathfinder Engineering Corporation Model P2-( ) autopilot system. Reissued 2/20/74.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
A35 thru H35, J35, K35, N35, M35, P35, S35, 35-33, -A33, -B33, -C33, G-33, V35, V35B, E33, E33A, V35A, 36, A36; T.C. A777, 3A15	SA2654WE	Installation of Pathfinder Model P2A autopilot system. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
A35, B35, C35, D35, E35, F35, G35; T.C. A777	SA3116SW-D	Mitchell automatic flight system AK328 cons. of Century I autopilot with optional omni tracker. Issued 3/16/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A35, B, C, D, E, F, G; T.C. 777	SA3113SW-D	Automatic flight system AK415 cons. of Century IIB autopilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35, A36TC; T.C. 3A15	SA3339SW	Installation of Mitchell automatic flight system Model AK809 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C35; T.C. A-777	SA236GL	Installation of a Continental O-470-G engine and McCauley propeller #2A36C23-11-DE/S-84B-0. Issued 5/4/78.	GL	74970	Robert Steffey 37344 Woodland New Baltimore, MI 48047
C35 thru H35, J35, K35, M35, N35, 35-33, 35-A33; T.C. A-777, 3A15	SA361EA	A. Installation of monitair angle of attack and stall warning kit number 92-107, and B. Installation of Monitair angle of attack and stall warning kit number 92-105. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
C35, D35, E35, F35, G35; T.C. A-777	SA604NW	Install Lycoming IO-540-K engine and Hartzell HC-E2YR-1BF/F8476D-4 propeller. Issued 7/6/78.	NW	52625	Machen, Inc. S.3608 Davison Boulevard Spokane, WA 99204
C35, D35, E35, F35, G35; T.C. 777	SA3267SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. 777	SA3268SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. A-777	SA4000WE	Installation of radome in wing leading edge. Issued 7/27/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
E-35; T.C. A-777	SA4043WE	Installation of Continental IO-520-BA engine and McCauley 3A32C propeller. Issued 10/26/79.	WE	06755	Aircraft Technical Service, Inc. 6701 Odessa Avenue Van Nuys, CA 91406
F35; T.C. 7777	SA173GL	Installation of Dukes fuel pump P/N 4140-00-39. Issued 5/27/77.	GL	01838	Aerodynamics, Inc. Oakland Pontiac Airport P.O. Box 508 Pontiac, MI 48056
H35, J35, K35, M35, N35, P35, S35, 35-33, -A33, -B33, -C33, -33A; T.C. 3A15	SA1-636	Install 300 Series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
H35 Series; T.C. 777	SA198NW	Installation of 3 bladed McCauley 3A34C76FM/S82NB-2 propeller with Woodward A210680 governor on Continental O-470-G engine. Issued 7/21/75.	NW	77570	Mel G. Taylor 20005 Northeast 13th Street Camas, WA 98607
H35 Series: T.C. 777	SA259NW	Installation of TCM continuous flow fuel injection system (EQ No. 5701) replacing carbureation system. Issued 2/17/76.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road South Seattle, WA 98108
35 Series H thru P; T.C. 3A15	SA470NW	Installation of Cessna oil filter. Issued 7/14/77.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road Seattle, WA 98108
H35, J35, K35, M-35, N-35, P35, 35-33, 35-A33, 35-B33, 35-C33, E33, F33; T.C. 3A15	SA695CE	Install Frantz oil filter. Amended 5/27/71.	GL	70360	Schmidt Aero Service Municipal Airport Worthington, MN 56187
H35, J35, K35, M35, N35, P35, S35, V35, V35B, 35-C33A, E33A, E33C, F33A, F33C, G33, 36, A36; T.C. 3A15	SA884SO	Installation of exhaust silencers. Issued 2/11/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, 35-33, E33, -A33, -C33; T.C. 3A15	SA975SW	Installation of cabin air conditioner. Reissued 5/7/79.	RM	01950	Aero Engineering Corporation 8C Garden Center Broomfield, CO 80020

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H35, J35, K35, M35, N35, P35, 35-33, 35-A33, -B33, -C33, E33, F33; T.C. 3A15	SA1252WE	Installation of Rajay turbocharged Continental O-470-G-C1 and/or IO-470-C, -J, -K, -N engines. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90807
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-33, -A33, -B33, -C33, -C33A, G33, -E33A, F33A, 35, A35; T.C. 3A15	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, M35, N35, P35, S35, V35, V35A, F33A, 35-33, -A33, -B33, -C33, -C33A, E33A, G33, 36, A36; T.C. 3A15	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33; T.C. 3A15	SA2870WE	Installation of right and left hand cockpit side windows. Reissued 2/2/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA3117SW-D	Mitchell automatic flight system AK328 cons. of Century I autopilot with optional omni tracker. Issued 3/16/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35; T.C. 3A15	SA3127SW-D	Mitchell automatic flight system AK415 cons. of Century IIB autopilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33C, F33A, G33, 36, A36; T.C. 3A15	SA3184WE	Installation of ventral air skeg. Amended 4/12/79.	WE	84396	Walker Engineering 2240 Sawtelle Boulevard Los Angeles, CA 90064
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B (Utility Category); T.C. 3A15	SA3190WE	Installation of wing tip fences. Issued 5/11/76.	WE	64690	JOhn Pixton Enterprises P.O. Box 342 Santa Rosa, CA 95402
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3269SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3270SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35; T.C. 3A15	SA3310WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/6/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, 35-33, -A33, -B33, -C33; T.C. 3A15	SA3523WE	Installation of an airfoil separator in the engine breather system. Issued 11/25/77.	WE	84396	Walker Engineering Co. 2240 Sawtelle Los Angeles, CA 90025
H35, J35, K35, M35, N35, P35, S35, V35, F33, E33A, E33C, F33, F33A, F33C, G33, V35A, V35B, 36, A36, A36TC; T.C. 3A15	SA3999WE	Installation of radome in wing leading edge. Amended 8/14/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
J35; T.C. 3A15	SA686CE	Install Continental IO-520-V engine derated to 250 H.P. and Hartzell HC-C3YF-1/8468A-8R propellers. Reissued March 1975.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
J35, K35, M35, 35-33; T.C. 3A15	SA1-354	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J35, V35, A35, B35, C35, D35, E35, F35, G35; T.C. 3A15, 777	SA754SW	Mitchell automatic aileron stabilizer AK203.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
J35, K35, M35, N35, P35, S35, V35, V35B, E33, E33A, F33, F33A, 36, A36, 35-33, -A33, -B33, -C33, E33C, F33C, -C33A, V35A; T.C. 3A15	SA1474CE	Installation of redundant engine fuel flow transmitter and cockpit indicator. Reissued 4/24/79.	WE	71740	Silver Instruments, Inc. 2436 Stanwell Drive Concord, CA 94520
J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2978WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA1140CE	Installation of King model KFC-200 2-axis (3 optional) autopilot system with a King KCS-55 (or -55A) compass with a King KI-255 (or KI-256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 7/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M35; T.C. 3A15	SA958EA	Installation of Teledyne Continental IO-520-Ba Engine and associated components in place of Teledyne Continental IO-470-C engine and associated components. Issued 7/30/73.	EA	41760	Helicopter & Airplane Service Corp. Montgomery County Airpark Gaithersburg, MD 20760
N35, P35, S35; T.C. 3A15	SA134EA	15-gallon fiberglass wing tip fuel tanks. Reissued 2/6/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
P35, 35-B33; T.C. 3A15	SA178EA	Installation of Monitair angle of attach system, Model AA-2. REissued.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, 35-B33; T.C. 3A15	SA260EA	Installation of Monitair angle of attack and stall warning kit number 92-110. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, V35, V35A, V35B; T.C. 3A15	SA3203WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/24/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
S35, V35, V35A, V35B, 35-B33, 35-C33, 35-C33A, E33, E33A, F33, F33A, G33, 36, A36, A36TC; T.C. 3A15	SA180GL	Install Norton Company radar pod P/N 4133X. Amended 8/22/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
S35, V35, V35A, V35B, 35-B33, -C33, -C33A, E33, E33A, F33, F33A, F33C, G33, 36, A36, A36TC; T.C. 3A15	SA328GL	Installation of radome kit No. 4222X. Amended 9/26/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
S35, V35; T.C. 3A15	SA352EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
S35, V35, V35A, V35B; T.C. 3A15	SA468SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and flight director indicator DH-841( ). Amended 11/14/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
S35, V35, V35B, 35-C33A, E33A, E33C, 36, A36, F33A, F33C;	SA785CE	Installation of Hartzell Propellers PHC-C3YF-1R/8468-6R and BHC-C2YF-1B/8468 and spinners A2295-1 and A2295. Amended 5/14/74.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
S35, V35, V35A, V35B; T.C. 3A15	SA1069SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director. Issued 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S35, V35, V35A, V35B; T.C. 3A15	SA1417CE	Install elevator tail cone fairings. Issued 5/17/78.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
S35 S/N D7482 thru D796, V35, V35A, V35B; T.C. 3A15	SA1744SW	Mitchell automatic flight system AK409 cons. of Century I autopilot with optional omni tracker. Issued 10/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2556WE	Installation of Rajay turbosupercharged Continental TSIO-520-D engine. Amended 11/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
S35, V35, V35A, V35B, 35-C33A, E33C, F33A, F33C, 36, A36; T.C. 3A15	SA2935WE	Installation of Model DFF-5000 fuel monitor. Issued 10/25/74.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545
S35, V35, V35A, V35B; T.C. 3A15	SA3159SW-D	Automatic flight system AK409, consisting of Century I autopilot with optional omni tracker. Issued 10/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3172SW-D	Yaw damper Model YK631. Issued 12/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3272SW-D	Mitchell automatic flight system AK501 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/10/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3292SW-D	Mitchell command electric trim AK726. Issued 7/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, B; T.C. 3A15	SA3310SW-D	Installation of Mitchell automatic flight system AK804 consisting of Century 41 autopilot or AK804FD consisting of Century 41 autopilot flight director. Issued 11/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, B; T.C. 3A15	SA3324SW-D	Installation of Mitchell automatic flight system AK803 consisting of Century 21 autopilot. Issued 12/6/78.	SW	60000	Mitchell Industries,Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3327SW	Installation of Mitchell automatic flight system AK805 consisting of Century 21 autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
SA35, V35, V35A, V35B; T.C. 3A15	SA3328SW	Installation of Mitchell automatic flight system AK806/FD consisting of Century 41/flight director autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35A, F33A, F33C, 36, A36; T.C. 3A15	SA3548WE	Installation of air/oil separator. Amended 4/28/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90025
S35, V35, V35A, V35B; T.C. 3A15	SA3668WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 7/13/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
V35; T.C. 3A15	SA503NW	Installation of Robertson STOL kit. Issued 9/7/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
V35; T.C. 3A15	SA707NW	Add RCA Primus weather radar. Issued 1/11/79.	NW	68500	Robertson Aircraft Corp. 839 West Perimeter Road Renton, WA 98055
V35, V35A; T.C. 3A15	SA925SW	Mitchell Automatic Flight System AK263 cons. of Century II autopilot with radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1185CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	NW	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
V35, V35A, V35B; T.C. 3A15	SA1186CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	MW	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
V35, V35A, V35B; T.C. 3A15	SA1500SW	Mitchell automatic flight system FD/AP282-382 cons. of flight director/autopilot with automatic command electric pitch trim. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1501SW	Mitchell automatic flight system AK383 cons. of Century III autopilot with optional automatic command electric trim, radio coupler, and glide slope coupler. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1722SW	Mitchell automatic flight system AK402, cons. of Century IIB autopilot with optional radio coupler. Issued 8/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3034SW-D	Mitchell automatic flight system AK503 or AK503FD cons. of Century IV autopilot or Century IV flight director autopilot with command/auto. electronic trim and annuciator panel. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3035SW-D	Mitchell automatic flight system AK501 cons. of Century III autopilot with optional command/auto. elec. pitch trim, radio, and glide slope coupler. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35A; T.C. 3A15	SA882SW	Mitchell automatic flight system AK260 consisting of Century III autopilot, optional radio coupler, automatic pitch trim, stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35A; T.C. 3A15	SA2030WE	Installation of Brittain B-VII, NAV-2B, B2C and BSA-4 Flight Control Systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, E33 and E33A; T.C. 3A15	SA1858WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, V35B, S35, F33A, A36; T.C. 3A15	SA3824WE	Installation of SDI Model CFS-1000-1001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714
V35B (Utility Category); T.C. 3A15	SA2947WE	Installation of Collins AP-107 autopilot and FD-106 PV flight director. Reissued 4/22/75.	MW	24250	Collins Radio Group Rockwell International Cedar Rapids Airport Cedar Rapis, IA 52406
V35B; T.C. 3A15	SA3215SW-D	Mitchell automatic flight system AK671 consisting of Century I autopilot with optional omni tracker. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3216SW-D	Mitchell automatic flight system AK672 consisting of Century IIB autopilot with optional radio coupler. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3217SW-D	Mitchell automatic flight system AK673 consisting of Century III autopilot with optional radio coupler and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3218SW-D	Mitchell automatic flight system AK674 consisting of Century IV autopilot or AK674FD consisting of Century IV flight director autopilot with remote annunciator. Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3219SW-D	Mitchell command electric trim system AK675. Issued 8/9/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
V35B; T.C. 3A15	SA3220SW-D	Mitchell yaw damper system YK676 Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
V35B, A36, F33; T.C. 3A15	SA3683WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
35-33 Series; T.C. 3A15	SA1808WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33 Series; T.C. 3A15	SA1886WE	Installation of Brittain Industries NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3098SW-D	Mitchell automatic flight system AK306 cons. of Century I autopilot with optional omni tracker. Issued 1/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3107WE	Installation of exhaust silencer. Reissued 2/9/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA1036EA	Installation of vertical tail floodlights on upper surfaces of the horizontal stabilizer. Amended 4/9/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
35-33, 35-A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36; T.C. 3A15	SA1416CE	Install flap and aileron fairings and seals. Amended 8/9/78.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
35-A33; T.C. 3A15	SA270EA	Installation of a stability augmentation safety system (with or without camera system installed). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-A33; T.C. 3A15	SA1310CE	Chrome-plated brake disc installation. Issued 6/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
35-B33, -C33A; T.C. 3A15	SA1289CE	Install King KFC-200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/21/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
35-C33, F33; T.C. 3A15	SA238GL	Installation of Continental IO-470-N engine and McCauley 2A36C23/84B-0 propeller. Amended 11/14/78.	GL	39517	Stewart Gross P.O. Box 634 Rochester, MN 55901
35-C33, 35-C33A; T.C. 3A15	SA394EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-C33; T.C. 3A15	SA896SW	Mitchell automatic flight system AK264 cons. of Century III autopilot with optional automatic aileron stabilizer, radio and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33, E33, F33; T.C. 3A15	SA1218SW	Automatic flight system AK306 cons. of Century I and optional tracking system. Issued 11/10/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33, E33, F33; T.C. 3A15	SA1365SW	Mitchell automatic flight system model AK347 cons. of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA1366SW	Mitchell automatic flight system model AK316, cons. of Century III autopilot with optional automatic pitch trim, radio coupler, glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3163SW-D	Install automatic flight system AK316 consisting of Century III autopilot with optional command automatic pitch trim system, radio coupler, and glide slope coupler. Issued 11/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3204WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 12/20/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3248SW-D	Mitchell automatic flight system AK716 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 10/3/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
E33, -A, -C; F33, -A, -C; T.C. 3A15	SA2057WE	Installation of Brittain Industries B-VII, NAV-2B, B2C and BSA4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
F33A; T.C. 3A15	SA1164CE	Installation of King KFC-200 two axis autopilot system with King KI-255 (or -256) flight command indicator or King KG-258 altitude horizon indicator with a KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
F33A; T.C. 3A15	SA3230SW-D	Mitchell automatic flight system AK660, consisting of Century IIB autopilot with optional radio coupler. Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3232SW-D	Mitchell automatic flight system AK662, consisting of Century IV autopilot or AK662FD consisting of Century IV flight director with optional remote annunicator. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3229SW-D	Mitchell automatic flight system AK659 consisting of Century I autopilot with optional omni tracker. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, Tx 76067
F33A; T.C. 3A15	SA3231SW-D	Mitchell automatic flight system AK661, consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3233SW-D	Mitchell command electric trim AK663. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3234SW-D	Mitchell yaw damper system K664 Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3348SW	Installation of Mitchell automatic flight system AK821/FD consisting of Century 41/flight director autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3349SW	Installation of Mitchell automatic flight system AK820 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, G33, 36, A36; T.C. 3A15	SA480SO	Installation of Bendix FCS-810 automatic flight control system, including manual electrim trim and flight director indicator DH-841( ). Amended 10/4/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
F33A, S/N CE-316 & up; T.C. 3A15	SA1232SW	Mitchell automatic flight system AK315 cons. of Century III with optional automatic pitch trim, radio and glide slope coupler. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F33A, E33A, 35-C33A, F33C; T.C. 3A15	SA1233SW	Mitchell automatic flight system AK317 cons. of Century I and optional tracking system. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1865SW	Mitchell automatic flight system AK448, Century IV autopilot and AK448FD, Century IV flight director with electronic command/automatic pitch trim. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1866SW	Mitchell automatic flight system AK452 cons. of Century III autopilot with optional electronic command/automatic pitch trim, radio coupler, and glide slope coupler. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA3087SW-D	Mitchell command electric trim AK563. Issued 12/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, 36A; T.C. 3A15	SA3193SW-D	Mitchell automatic flight system AK452 consisting of Century III autopilot with optional command automatic electronic pitch trim, radio, glide slope coupler. Issued 4/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G33; T.C. 3A15	SA571EA	Installation of Brittain Industries Models B7, NAV-2B, B2C and BSA4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
G33; T.C. 3A15	SA818CE	Install Hartzell propeller model BHC-I2YF-1BF/F8468AR with spinners A2295, or model PHC-L3YF-1RF/F8468A-6R with spinners A2295-1. Issued 1/14/72.	SW	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
35/36 Series; T.C. 3A15	SA1711WE	Installation of Brittain Industries B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35/36 Series; T.C. 3A15	SA1712WE	Installation of Brittain Industries BSA-4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
35, 33, 36, 45 Series; T.C. A777, 3A15, 5A3	SA1000CE	Installation of cabin and engine compartment fire suppression system. Issued March 1974.	CE	35335	Fike Metal Products Corporation P.O. Box 38 Blue Springs, MO 64015
35, 50 Series; T.C. 777, 3A15, 5A4	SA856WE	Glassfiber reinforced plastic wing tips.	WE	00450	ACKO P.O. Box 1431 Torrance, CA 90510
35, 50 Series; T.C. 777, 3A15, 5A4	SA998WE	Glass fiber reinforced plastic wing tips. Amended 6/13/69.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
35, 95 Series; T.C. 777, 3A15, 3A16	SA1-381	Installation of Fram Oil Filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
35, 95 Series; T.C. 777, 3A15, 3A16	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
36 Series; T.C. 3A15	SA961SW	Mitchell automatic flight system AK275 cons. of Century III autopilot with optional radio coupler, automatic pitch trim, aileron stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36 Series; T.C. 3A15	SA1916WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
36; T.C. 3A15	SA2068WE	Installation of Brittain Models B-VII, NAV-2B, B2C and BSA-4 flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
A36; T.C. 3A15	SA3206SW-D	Mitchell command electric trim model AK669. Issued 6/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
36, A36; T.C. 3A15	SA1145CE	Installation of King Model KFC-200, 2 axis (3 optional) or stand alone yaw damper for Beech Model A36 S/N E572 and later autopilot system with a King KI-255 (KI-256 optional) flight command indicator with the KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
36, A36; T.C. 3A15	SA1231SW	Mitchell automatic flight system model AK311, cons. of Century II autopilot with optional radio coupler. Issued 12/8/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1360SW	Mitchell automatic flight system Model AK346 cons. of Century III autopilot with optional pitch trim, radio coupler, and glide slope coupler. Issued 8/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1448CE	Installation of elevator tail cone fairing. Issued 10/6/78.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
36, A36; T.C. 3A15	SA1634SW	Mitchell AK423 cons. of 1C707 omni/localizer converter. Issued 3/27/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1635SW	Mitchell AK417/FD cons. of flight director/autopilot with command electric trim. Issued 3/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3118SW-D	Automatic flight system AK448, Century IV autopilot or AK448FD, Century IV autopilot flight director with optional remote annuciator. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3119SW-D	Automatic flight system AK452 cons. of Century III autopilot with optional command/automatic electronic elevator pitch trim, radio and glide slope couplers. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3244WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 8/11/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
A36, Serial No. E185 and up; T.C. 3A15	SA84RM	Installation of freon type air conditioning system. Amended 3/21/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
A36; T.C. 3A15	SA283GL	Installation of a Continental IO-520-B, -BA engine modified in in accordance with STC SA282GL and a Symbolic Displays fuel flow indicating system, Model CFS-1000. Issued 11/14/78.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport Rockford, IL 61109
A36; T.C. 3A15	SA1093CE	Installation of AP-107 (2 axis) autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	NW	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1095CE	Installation of AP-106 autopilot system and interface with Collins 329A-4V indicator. Amended July 1975.	NW	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1096CE	Installation of yaw damper system. Issued April 1975.	NW	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1097CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	NW	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1544CE	Installation of microwave landing system. Issued 1/22/80	SW	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A36; T.C. 3A15	SA3203SW-D	Mitchell yaw damper model YK670 Issued 5/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3204SW-D	Mitchell automatic flight system AK668 consisting of Century IV autopilot or AK668FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 5/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3205SW-D	Automatic flight system AK667 consisting of Century III autopilot with optional radio coupler and Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3207SW-D	Mitchell automatic flight system consisting of Century I autopilot with optional omni tracker. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3208SW-D	Mitchell automatic flight system AK666 consisting of Century IIB autopilot with optional radio coupler. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3340SO	Mitchell automatic flight system AK810 consisting of Century 41 flight director autopilot. Issued 7/25/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36, A36TC; T.C. 3A15	SA1106SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and option yaw damper and flight director. Issued 10/11/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
A36, A36TC; T.C. 3A15	SA1496CE	Installation of King KFC 200 automatic flight control system. Amended 7/18/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
A36, A36TC; T.C. 3A15	SA1527CE-D	Installation of King KAS 297 altitude selector option. Issued 2/13/80	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
A36TC; T.C. 3A15	SA3329SW-D	Mitchell automatic flight system AK754 consisting of Century IV autopilot or Model AK754FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 1/2/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36TC; T.C. 3A15	SA3330SW-D	Mitchell automatic flight system AK753, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/2/79.	SW	60000	Mitchel Industries, Inc. P.O. Box 610 Mineral Wells, TX 75056
45 Series; T.C. 5A3	SA366WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
45 Series; T.C. 5A3	SA425SW	Nose landing gear door removal.	SW	22700	Civil Air Patrol Corporation National Headquarters Ellington AFB, TX 77030
A-45 (T-34A, B-45); T.C. 5A3	SA876CE	Remove Continental C-470-13 or O-470-13A engine and propeller. Install Continental IO-470-N engine and Hartzell BHC-L2YF-FC846AR propeller. Issued December 1972.	CE	15250	Beech Aircraft Corporation 9709 East Central Wichita, KS 67206
A-45 (T-34A, B-45); T.C. 5A3	SA2211SW	Mitchell Century I Model AK409 autopilot with omni tracker. Issued 7/17/75.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA1864SW	Continental IO-520-B engine and McCauley 3A32C76/82NB-2 propeller. Issued 4/11/74.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA3191SW-D	Mitchell automatic flight system AK649 consisting of Century I autopilot with optional omni tracking system. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A45; T.C. 5A3	SA3192SW-D	Automatic flight system AK651 consisting of Century IIB autopilot with optional radio coupler. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D45; T.C. 5A3	SA183GL	Modification of basic aircraft for Restricted Category Airworthiness Certification by removing rudder-aileron bungee interconnect system, elevator down spring system and tail cone fairing. Issued 6/21/77.	GL	61302	Michigan Dept. of Natural Resource Stevens T. Mason Bldg. Lansing, MI 48926
50 Series; T.C. 5A4	SA1-262	Bendix Pioneer 9100-17-C1 fuel flow meter system.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series; T.C. 5A4	SA1-291	Radio shelves in nose baggage shelves.	EA	15210	Beckett Aviation Corporation Allegheny County Airport Dravosburg, PA 15034
50 Series; T.C. 5A4	SA1-357	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series; T.C. 5A4	SA1-443	2002X-R radome assembly.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
50 Series; T.C. 5A4	SA1-503	Electrothermal propeller deicing system. (Applicable to aircraft with two 50-amp. generators or greater.)	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series; T.C. 5A4	SA3-208	Acron B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA3-703	Accumulator for unfeathering Hartzell HC-83XF, HC-93Z20 or HC-B3Z20 propellers.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA4-51	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-221	Autopilot L-2.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-382	Radio rack.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
50 Series; T.C. 5A4	SA4-439	Fiberglass reinforced plastic wing tips.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
50 SEries; T.C. 5A4	SA4-462	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-549	Federal F-400 autopilot.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
50 Series; T.C. 5A4	SA4-758	Aerofilter 30690B full flow lube oil filter with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
50 Series; T.C. 5A4	SA4-807	Automatic rudder control Model B.	GL	49858	Lear, Inc. 3714 Jefferson Avenue, S.E. Grand Rapids, MI 49501
50 Series; T.C. 5A4	SA4-808	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-1417	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA3CE	Governor 210385. (Not eligible with accumulator unfeathering system.)	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50 Series; T.C. 5A4	SA5CE	Propeller governors incorporating unfeathering accumulator shutoff valves. (Eligible only on aircraft equipped with Beech unfeathering system.)	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA24SW	Cabin seats. (Seat tracks installation per STC SA2-1068 required.)	SW	83650	Vicars Custom Aircraft Interiors 3709 N. Main Fort Worth, TX 76101
50 Series; T.C. 5A4	SA25CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA31SW	Automatic pilot AK104.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA41CE	Governor 210159.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA75SW	Landing gear doors. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA76SW	Lycoming IGSO-540-B1A engines with associated powerplant changes, and landing gear doors; increase gross weight to 7,300 lbs. takeoff and 7,000 lbs. landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, Tx 78216
50 Series; T.C. 5A4	SA81SW	Automatic pilot AK119.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA158EA	Autopilot T-3 and altitude hold AH-1 as an accessory item.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series; T.C. 5A4	SA166CE	Twin-engine electronic synchronizer and unfeathering system.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA167CE	Electronic synchronizer kit.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA198SW	Three-place couch.	SW	85128	Westernair of Albuquerque, Inc. Route 6, Box 88 Albuquerque, NM 87101
50 Series; T.C. 5A4	SA207SW	Dual control. (Pilot's and copilot's seat installations per STC SA2-1068 required.) Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA213CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA242SW	Lycoming GO-480-G2D6 engines and increase in gross weight to 6,300 pounds. Reissued February 1973.	GL	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA323EA	7541K nose cap weather radome.	NE	53750	McMillan Radiation Labs, Inc. Brownville Avenue Ipswich, MA 01938
50 Series; T.C. 5A4	SA348SW	Radar nose. Reissued February 1973.	GL	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA360SW	GO-480-G2D6 or -G2F6 engines and increase in weight to 6,000 pounds. Reissued February 1973.	GL	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA370SW	Seven place seating capacity.	SW	80625	United Airmotive 1105 DeRidder Fort Worth, TX 76106
50 Series; T.C. 5A4	SA392WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50 Series; T.C. 5A4	SA430SW	Pilot and copilot cockpit seats.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
50 Series; T.C. 5A4	SA405WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA433SW	Cabin door and stair.	SW	27242	Cross Roads Aviation, Inc. Addison Airport Addison, TX 75001
50 Series; T.C. 5A4	SA514SW	Six place seat and/or hat shelf.	SW	36125	Flying V Interiors Meacham Field Fort Worth, TX 76106
50 Series; T.C. 5A4	SA517SW	Goodrich wheel and brake. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA587SW	Lycoming IO-720-A1A engines, increase gross weight 7,600 pounds, 7,240 pounds landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA655SW	Lycoming IGSO-480-A1A6 engine; wing, vertical tail, landing gear modified, control system increased gross weight to 7,300 pounds takeoff, and 7,000 pounds landing.	SW	27242	Cross Roads Aviation, Inc. P.O. Box 60464 AMF Houston, TX 77060
50 Series; T.C. 5A4	SA1013WE	Advanced Army Aircraft Instrumentation System (AAAIS) and associated aircraft modifications.	WE	30400	Douglas Aircraft Company, Inc. 3855 Lakewood Boulevard Long Beach, CA 90801
50 Series; T.C. 5A4	SA1324WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA1385WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA1-565	Installation of radome kit No. 2002X. Amended 2/24/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA99CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights Model 1 or 2. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGAw Avenue Irvine, CA 92705
50, B50, C50, D50, D50A, D50B, D50C, D50E-5990, D50E, E50E, F50, G50, H50, J50; T.C. 5A4	SA276GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 1/17/79.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA383CE	Installation of Hoskins Twi. III supplementary high intensity lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
50, B50 thru J50, D50A, B, C, D, E; 65, 65-80, 65-A8800, 65-B80 all; T.C. 5A4, 3A20	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA1644WE	Installation of a Torginol Special Product Co. KarBar.	RM	25250	Combs Aircraft, Inc. Stapleton International Airport Denver, CO 80207
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA2631WE	Installation of Bellon Concrete, Inc. single piece windshield or alternate single piece sloped windshield. Amended 3/20/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4550 Jettridge Drive Atlanta, GA 30327
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA2872WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B50, C50, D50; T.C. 5A4	SA2413WE	Modification of fuel vent outlet. Issued 9/3/71.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
C50; T.C. 5A4	SA3062SW-D	Mitchell AK370 cons. of Century III autopilot with command/automatic electronic pitch trim system, optional radio coupler, and glide slope coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C50; T.C. 5A4	SA3063SW-D	Mitchell automatic flight system AK542 cons. of Century IIB autopilot with optional radio coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, D50C, E50, F50, G50, H50; T.C. 5A4	SA1-453	Installation of Tactair T-3 automatic pilot and optional installation of Tactain AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
D50, D50A, B, C, E; T.C. 5A4	SA3138SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3139SW-D	Mitchell automatic flight system AK613, consisting of Century IIB autopilot with optional radio coupler. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3140SW-D	Mitchell automatic flight system AK606, consisting of Century I autopilot with optional omni tracker. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50 - modified - Excaliber STC SA587SW; 56TC, A56TC, 58, 58A, 58P, 58PA, 58TC, 58TCA, 60, A60, B60; 65, A65, 65-80, -A80, -A80-8800, -B80, -88, -70 modified - Excalibur STC SA444SW; 95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A (95-55, -A55, -B55 modified - Colemill STC SA432SO; T.C. 5A4, 3A16, A12CE, A23CE, 3A20, 3A16	SA20GL	Installation of Woodward Type III electronic propeller synchronizer or synchrophaser system. Amended 9/25/78.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
D50C, E; T.C. 5A3	SA1334SW	Mitchell automatic flight system AK337, cons. of Century II autopilot with optional radio coupler. Issued 7/1/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA31WE	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
D50E; T.C. 5A4	SA33WE	Autopilot M-4.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
D50E; T.C. 5A4	SA391WE	Installation of Brittain Model B2D Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D50E; T.C. 5A4	SA837SW	Mitchell AK255 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA974CE	Installation of KNR 665 digital area navigation system. Amended May 1974.	CE	48250	King Radio Corporation Box 106 Olathe, KS 66061
E50, F50, G50, H50, J50; 80, A80, 65; T.C. 5A4, 3A20	SA1686WE	Installation of Vibration Isolation Products engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50, 65 Series; T.C. 5A4, 3A20	SA15EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50, 65 Series; T.C. 5A4, 3A20	SA476EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
55, A55; B55, C55, D55, 56TC; 65-B80, A65-8200, 65-90, A90; 95, B95, B95A, D-95A, E95; T.C. 3A16, 3A20	SA1874WE	Installation of Brittain up-command signal adapter kit on certain airplanes equipped with Brittain models B-4A, B-4AP, B-5 and B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA681CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114
B55, C55; 95 Series; T.C. 3A16	SA1591WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1548WE	Installation of a Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1934WE	Installation of an approach speed control system. Reissued 12/4/69.	EA	69500	Safe Flight Instrument Corp. Box 550 White Plains, NY 10602
D55, E55, E55A, 56TC, A56TC, 58, 58A, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 58P, 58PA, 58TC; TC 3A16	SA453SO	Installation of Bendix Model FCS 810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 10/19/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
D-55, D55A, E55, E55A, 58, 58A, 56TC, A56TC, 95; T.C. 3A16	SA2048WE	Installation of Brittain Industries Model B-VII or NAV-2B or B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55, D55A, E55, E55A, 56TC, 58, 58A, 95, B95, B95A, D95A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A; T.C. 3A16	SA2871WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
E55; T.C. 3A16	SA126GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
E55; T.C. 3A16	SA896SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 4/22/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
E55; T.C. 3A16	SA3068WE	Installation of fuel flow instruments. Issued 8/8/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1126CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE982 and up); T.C. 3A16	SA1127CE	Installation of Collins AP-107 (2 axis) autopilot systems. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1128CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55, 58; T.C. 3A16	SA1008CE	Installation of an electric motor driven freon vapor cycle air conditioning system. Amended 10/9/74.	CE	02950	Aero Space Controls 1050 N. Mosley Wichita, KS 67214

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
E55, E55A, 58, D55, 95-A55, -B55, -C55; T.C. 3A16	SA1134CE	Installation of the King Model KFC-200, 2-axis (3 optional), flight control system with-- a. King Model KCS-55/55A compass system and b. a KI-255 (KI-256 optional) flight command indicator or a KG-258 attitude horizon indicator with the KC-292 mode controller. Amended 4/18/75.	CE	48250	King Redio Corporation 400 N. Rogers Blvd. Olathe, KS 66061
56TC; T.C. 3A16	SA383SO	Installation of Bendix M-4C autopilot flight control system. Amended 7/14/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33309
56TC; T.C. 3A16	SA632CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114
56TC; T.C. 3A16	SA713CE	Conversion of wing tips to integral fuel tanks.	CE	16292	Frank R. Berry and William T. McKay Route 1, Box 204A Augusta, KS 67010
56TC; T.C. 3A16	SA1770WE	Installation of Brittain Industries Models B-5 or NAV-2B or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
56TC, A56TC; T.C. 3A16	SA1041CE	Replace existing nickel-cadmium battery with lead-acid battery. Issued January 1975.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
56 TC; 95 Series; T.C. 3A15, 3A16	SA1585WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
58 Series; T.C. 3A16	SA860EA	Installation of Aircraft Radio Corp. AF-530A automatic pilot system and electric operated elevator trim system. Amended 1/18/71.	EA	05950	Aircraft Radio Corporation Rockaway Valley Road Boonton, NJ 07005
58 Series; T.C. 3A16	SA1174SW	Mitchell automatic flight system FD/AP282-303 cons. of flight director/autopilot, automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1175SW	Auto flight system AK303 cons. of Century III, autopilot, with optional auto pitch trim, radio, and glide slope couplers. Issued 7/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1192SW	LN2 air conditioner system. Issued 9/22/70.	SW	83100	Ves-Kol Inc. 2805 National Drive Garland, TX 75040
58 Series; T.C. 3A16	SA1199SW	Mitchell automatic flight system 305 cons. of Century II autopilot with optional stabilizer and radio coupler. Issued 10/2/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA3119WE	Installation of Pathfinder autopilot systems. Issued 12/16/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
58, 58A; T.C. 3A16	SA94RM	Installation of freon type air conditioning system. Issued 3/24/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
58, 58A; T.C. 3A16	SA1045CE	Installation of Collins Radio Co. AP-107 autopilot system (2 axis). Amended February 1975.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1106CE-D	Installation of Collins Radio Group AP-106 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1107CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
58, 58A; T.C. 3A16	SA1108CE-D	Installation of Collins Radio Group AP-107 axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1687SW	Mitchell automatic flight system Model YK428 cons. of yaw damper. Issued 6/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1786SW	Mitchell Automatic Flight System AK451 cons. of Century III Autopilot with Electronic Pitch Trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1787SW	Mitchell Automatic Flight System AK447 cons. of Century IV Autopilot or AK447FD cons. of Century IV/Flight Director with Electronic Command/Automatic Pitch trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3131SW-D	Mitchell automatic flight system AK447, Century IV autopilot or AK447FD Century IV flight director autopilot with remote annuciator. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3132SW-D	Mitchell automatic flight system AK451, consisting of Century III autopilot with optional command automatic electric pitch trim, radio and glide slope couplers. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3341SW	Mitchell yaw damper systems, YK781. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3342SW	Mitchell automatic flight system AK816/FD consisting of Century 41/flight director autopilot. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3350SW	Installation of Mitchell automatic flight system AK815 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A, 58P, 58PA, 58TC, 58TCA, 65-80, -A80, -B80, -88, 95-C55, -C55A, D55, D55A, E55, E55A; T.C. A23, 3A20, 3A16	SA300CE	Installation of Woodward propeller governor on single and twin engine airplanes. Amended 9/18/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
58, 58A, TH-1 and up; T.C. 3A16	SA863CE	Installation of Airborne/Goodyear pneumatic iceguard deicing system. Issued August 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
58, 58A, 95-B55, -B55A; T.C. 3A16	SA935SO	Installation of a Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Amended 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FI 33310
58, 58A, 95-B55, -B55A; T.C. 3A16	SA936SO	Installation of Bendix NP-2041A area navigation computer programmer. Amended 4/10/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
58P; T.C. A23CE	SA113GL	Installation of radome kit 4109X. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA978SO	Installation of NP-2041A area navigation computer programmer. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA979SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
58P, 58PA, 58TC, 58 TCA; T.C. A23CE	SA1123CE	Install AP-106 autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1124CE	Install AP-107 (2 axis) autopilot and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1125CE	Install AP-107 (3 axis) autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1524CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3038SW-D	Mitchell automatic flight system AK449 or AK449FD cons. of Century IV autopilot or Century IV flight director autopilot with command/ automatic electronic pitch trim and optional remote annuciator panel. Issued 1/17/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3039SW-D	Automatic flight system YK445 yaw damper system. Issued 1/17/75.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3040SW-D	Automatic flight system AK453 consisting of Century III autopilot optional command/automatic elecelectronic pitch trim system, radio and glide slope couplers. Issued 2/5/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3311SW-D	Mitchell automatic flight system AK453 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/22/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3338SW-D	Mitchell automatic flight system system AK813 consisting of Century 41 autopilot or AK813FD consisting 41 flight director autopilot with optional remote annunciator. Issued 4/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3344SW	Mitchell yaw damper system YK781. Issued 10/26/79	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3499WE	Installation of tail flood lights on horizontal stabilizer. Issued 9/30/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
58P, 58TC; T.C. A23CE	SA178GL	Install Cleveland conversion kit, P/N 199-73. Issued 5/23/77.	GL	23260	Cleveland Wheels and Brakes VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011
58P, 58TC; T.C. A23CE	SA3769WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
58P, 58TC, 58TCA; T.C. A23CE	SA4050WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 12/14/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
58TC; T.C. A23CE	SA124GL	Install Norton Company radome, P/N 4083X. Amended 2/21/79.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
60 Series; T.C. A12CE	SA1006SW	Mitchell Automatic Flight System AK291, cons. of Century III autopilot with optional pitch trim servo, radio and glide slope couplers.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
60, A60; T.C. A12CE	SA659SO	Installation of Bendix M-4C automatic flight control system, including manual electric trim, and/or installation of Bendix YD-4 yaw damper. Amended 11/10/72.	SO	15475	Bendix Avionics P.O. Box 9414 Ft. Lauderdale, FL 33310
60, A60; T.C. A12CE	SA945CE	Replacement of existing nickel-cadmium battery with lead-acid battery, Teledyne PS12-24. Amended October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133
60, A60; T.C. A12CE	SA1587SW	Mitchell automatic flight system YK380 consisting of yaw damper. Issued March 1973.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60; T.C. A12CE	SA1704SW	Mitchell automatic flight system AK429, cons. of Century IV autopilot with trim or AK429/FD cons. of Century IV autopilot/flight director with trim. Issued 7/20/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA154GL	Installation of Norton radome kit, No. 4132X. Issued 2/16/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
60, A60, B60; T.C. A12CE	SA179GL	Install Celveland conversion kit, P/N 199-73. Issued 5/23/77.	GL	23260	Cleveland Wheels and Brakes VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011
60, A60, B60; T.C. A12CE	SA539SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator and/or YD-4 yaw damper. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, Fl 33310
60, A60, B60; T.C. A12CE	SA1023CE	Installation of Collins Radio Co. AP-106 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1024CE	Installation of AP-107 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1025CE	Installation of yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A2CE	SA1741SW	Mitchell automatic flight system AK458 cons. of Century autopilot with optional radio coupler automatic/command pitch trim, glide slope coupler. Issued 10/12/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3151SW-D	Mitchell automatic flight system AK429 consisting of Century IV autopilot or AK429/FD consisting of Century IV flight director with optional remote annuciator. Issued 7/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A2CE	SA3162WE	Installation of recognition light assembly on the horizontal stabilizer. Issued 3/26/76.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
60, A60, B60; T.C. A12CE	SA3293SW-D	Yaw damper system YK380. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3605WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel indicating system. Amended 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
60, A60, B60; T.C. A12CE	SA3905WE	Installation of SDI Model CFS-200, -2001, or FT-200 fuel flow indicating system. Issued 4/13/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
60, 65-A80, B80, 65-88, 70; T.C. A12CE, 3A20	SA889EA	Installation of Grimes three light strobe Kit P/N 34-0116-1 and -2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
60, A60, B90, C90, E90, 65-90, -A90, 100, A100; T.C. A12CE, 3A20, A14CE	SA2638WE	Installation of CCC BWS 50-08 Nicad battery overheat warning system. Amended 9/18/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
A60; T.C. A12CE	SA85RM	Installation of Teledyne Avionics angle of attack indicating system. Issued 11/2/76.	RM	14127	Avionics Engineering of Denver, Inc. 8895 Montview Boulevard, Hangar B Denver, CO 80220
A60; T.C. A12CE	SA1029CE	Installation of AP-106 and AP-107 automatic flight control systems and yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
B60; T.C. A12CE	SA570SO	Installation of Bendix M-4D automatic flight control system, including optional manual electric trim and optional flight director indicator. Issued 12/6/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
B60; T.C. A12CE	SA1470CE	Installation of King KFC 250 flight control system (3 axis) using 3-inch or 4-inch indicators. Issued 2/5/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
65 Series; T.C. 3A20	SA1-643	Radar antenna mounts: 296-01 for 12" Collins WP-103 antenna; 296-03 12" RCA AVQ-55 antenna and 296-02 for 12" RCA AVQ-50 antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series; T.C. 3A20	SA3-516	Autopilot L-2C with or without 1350B approach coupler and 2203D2 altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA4CE	Propeller governors incorporating unfeathering accumulator shutoff valves.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
65 Series; T.C. 3A20	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
65 Series; T.C. 3A20	SA46WE	Full flow lube oil filter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
65 Series; T.C. 3A20	SA92CE	High intensity wing tip lights Model A, tail light Model C, with or without high intensity fuselage lights Model 1 or 2.	GL	42625	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
65 Series; T.C. 3A20	SA139SW	Buffet. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
65 Series; T.C. 3A20	SA161CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
65 Series; T.C. 3A20	SA185CE	Type OF-103-A oil filters P/N 6435565.	GL	00750	AC Spark Plug Division of GMC P.O. Box 1002 Flint, MI 48556
65 Series; T.C. 3A20	SA186EA	Throttle stop device.	EA	87118	Stephen J. Wisey, Jr. 8 Steamboat Road Great Neck, NY 11022
65 Series; T.C. 3A20	SA188CE	Twin-engine synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
65 Series; T.C. 3A20	SA201EA	Sperry SP 3 elevator trim drive servo and trim tab bracket.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
65 Series; T.C. 3A20	SA210SO	Radar system AVQ55.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65 Series; T.C. 3A20	SA218SW	Automatic pilot AK105.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA255CE	Oil tank heater blanket kit 65-42.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67206
65 Series; T.C. 3A20	SA269SW	Brushless generators, voltage regulators and control panels.	EA	37376	General Electric Company Specialty Controls Department Waynesboro, VA 22980
65 Series; T.C. 3A20	SA277EA	Installation of Chamberlain 2090K-B radome kit for Bendix 100 or RDR-110 radar systems with transmitter/receiver unit and 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
65 Series; T.C. 3A20	SA280EA	2011K-B Series radome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series; T.C. 3A20	SA296CE	M4B or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA307CE	GUARD system (gear up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612
65 Series; T.C. 3A20	SA336EA	PB-60 autopilot.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
65 Series; T.C. 3A20	SA393EA	Electronic voltage alarm.	EA	53500	McKinley Engineering Company P.O. Box 275 Palisades Park, NJ 07650
65 Series; T.C. 3A20	SA411CE	M4B or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA444SW	Lycoming IO-720A1A engines and increase in takeoff and loading weight. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65 Series; T.C. 3A20	SA470SW	Automatic pilot AK122 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA471SW	Automatic trim system AK149.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA505CE	Install entrance door.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65 Series; T.C. 3A20	SA528SW	Lear 164 electro-mechanical rotary actuator.	SW	42131	H & H Enterprises P.O. Box 75135 Oklahoma Ctiy, OK 73125
65 Series; T.C. 3A20	SA651SW	AK206 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA695SW	Engine induction system air filter removed.	SW	71800	Sinclair Oil & Gas Company Aviation Department 3505 N. Sheridan Road Tulsa, OK 74101
65 Series; T.C. 3A20	SA704CE	Installation of BUTLER VAC and ADD navigation system. Amended April 1974.	CE	19000	Butler National Corporation 8246 Nieman Road Lenexa, KS 66214
65 Series; T.C. 3A20	SA722SW	AP-103F/FD-108 autopilot flight director system and related electronics.	SW	24252	Collins Radio Company P.O. Box 98 Addison Airport Addison, TX 75001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65 Series; T.C. 3A20	SA767SW	Mitchell Model AK 239 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA1004WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
65 Series; T.C. 3A20	SA1022WE	B-4 flight control system (PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1453WE	Installation of a Brittain Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1511WE	Pacific Airmotive Corp. rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
65 Series; T.C. 3A20	SA1528WE	Installation of Brittain B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1556WE	Installation of Brittain Industries B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1714WE	Removal of emergency exit to permit aircraft to engage in special purpose operations, as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
65 Series; T.C. 3A20	SA1794WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA2069WE	Installation of Brittain B-VII Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65, A65, A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 70; T.C. 3A20	SA22GL	Installation of Hartzell synchrophaser. Reissued 8/27/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
65, A65, 65-80, 65-A80, 65-B80; T.C. 3A20	SA43CE	Installation of Bendix M-4B and M-4C flight control system. Amended 3/8/67.	EA	15480	The Bendix Corporation Avionics Products Bendix Radio Division Baltimore, MD 21204
65, 65-80, 65-A80, 65-90; T.C. 3A20	SA318EA	Installation of Monitair angle of attach and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
65-L23F, 65-80, 65-A80, 65-B80, -90, -A90; T.C. 3A20	SA394CE	Install Hoskins Twi. Mk III supplemental high intensity lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
65, 65-80; T.C. 3A20	SA1-642	2011X Series radome. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
65, 65-80; T.C. 3A20	SA506WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTL Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
65, 65-80; T.C. 3A20	SA518SW	Goodrich wheel and brake. Reissued Feburary 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65, A65, 65-80, A65-8200, 65-A80, -A80-8800, -B80, -88, -70; T.C. 3A20	SA277GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 12/21/78.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65, A65, -80, -A80, -A80-8800, A65-8200, -B8Q, 70; T.C. 3A20	SA1244SW	Mitchell automatic flight system FD/AP282-313 cons. of flight/director/autopilot and automatic pitch trim. Issued 1/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, A65, A65-8200, 65-80, -A80, -A80-8800, -B80, -88, -90, -A90, 70, B90, C90, E90; T.C. 3A20	SA1279CE	Installation of Avcon Ind. TSO-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
65, A65, 65-80; T.C. 3A20	SA1328SW	Replacement of existing alternators with 100 ampere Prestolite ALV-8042's. Reissued 10/20/72.	SW	61500	Nayak Aviation Corporation 206 E. Terminal Avenue San Antonio, TX 78216
65, A65, 65-80, 65-A80; T.C. 3A20	SA2349SW	3-place divan. Issued 8/13/76.	SW	36550	Foster-Edwards Aircraft Co., Inc. Box 574 Addison, TX 75001
65, A65, A65-8200, 70; T.C. 3A20	SA2365WE	Installation of Hartzell HC-3X20-2/9333C or HC-A3X20-2/9333C propellers. Reissued 7/14/71.	SW	37080	Bernard A. Gallaher 1400 Southwest Tower Houston, TX 77002
65, A65, A65-8200, 65-80, -A80, -A80-8800, -B80, -88, 70, 65-90, -A90, A90-1, -2, -3, -4, B90, C90 (S/N LJ502 thru 526); T.C. 3A20	SA3080WE	Installation of recognition light assembly on the horizontal stabilizer. Amended 2/3/76.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
65, A65, 65-80, -A80, -B80, -A80-8800; T.C. 3A20	SA3114SW-D	Automatic flight system AK548, cons. of Century III autopilot with optional radio and glide slope couplers. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, 65-80, -A80, -B80, -A80-8800, A65-8200, 70; T.C. 3A20	SA3115SW-D	Mitchell AK585, cons. of Century IV autopilot or AK585FD Century IV flight director autopilot. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65-80; T.C. 3A20	SA1009EA	Installation of Edo area navigation system Model TCE-71A. Reissued 12/19/78.	EA	32625	EDO-AIRE Div. of Edo Corporation 216 Passaic Avenue Fairfield, NJ 07006
65-80, -A80, -B80, -88, -90, -A90; T.C. 3A20	SA381EA	Installation of radome kit No. 2090X. Amended 12/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
65-80, -A80, -B80, -88, -90, -A90, B90, C90, E90, 100, A100, A100A, A100C, B100; T.C. 3A20, A14CE	SA37GL	Installation of Norton radome kit No. 2090XS. Amended 8/24/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
65-A80, -B80, -88, -90, -A90, -B90; T.C. 3A20	SA45GL	Install AMF inverter MGH 549-1. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
65-80, A-80, B-80; T.C. 3A20	SA228WE	Installation of oil lever indicator system. Issued 11/30/70.	WE	25600	Communications Components Corp. 1524 West 15th Street Long Beach, CA 90813
65-B80 Queen Air; T.C. 3A20	SA940SO	Removal of existing fuel flowmeter and associated components and installation of fuel flowmeter. Issued 6/24/77.	SO	02850	Aerosonic Corporation P.O. Box 4627 Clearwater, FL 33518
A65, 65-B80 & 70; T.C. 3A20	SA660CE	Installation of Bendix M4-C Flight Control System.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33310
65-90; T.C. 3A20	SA133GL	Install B.F. Goodrich thermally efficient propeller de-icers. Amended 9/15/76.	GL	38500	B.F. Goodrich 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA826SW	Elevator electric trim system.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 - Adams Field Little Rock, AR 72203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65-90; T.C. 3A20	SA897EA	Installation of B.F. Goodrich electrothermal propeller deicing system. Issued 2/7/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Company 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA1108SO	Installation of Pratt & Whitney engine model PT6A-20 replacing model PT6A-6. Issued 10/15/79.	SO	14213	B. R. Power Division Aztec Leasing, Inc. 20 Piney Mountain Road Greenville, SC 29607
65-90; T.C. 3A20	SA2740SW	Installation of P&W PT6A-135 engines and bleed air conditioning and pressurization system. Issued 3/24/78.	SW	77111	E.J. Swearingen P.O. Box 4640 Waco, TX 76705
65-90, -A90; T.C. 3A20	SA761SW	Mitchell AK238 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65-90, -A90; T.C. 3A20	SA822SO	Installation of P & W PT6A-28 engines. Amended 3/27/78.	SO	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
65-90, 65-A90, 65-B90; T.C. 3A20	SA526SO	Installation of the Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-90, -A90, -B90; T.C. 3A20	SA1177SW	Revised main landing gear doors.	SW	61500	Nayak Aviation Corporation 206 E. Terminal Drive San Antonio, TX 78216
65-90, -A90, B90, C90; T.C. 3A20	SA2693WE	Installation of inertial air separator scoops. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA810CE	Battery temperature sensing and over-temperature warning systems. Amended October 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA879SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA951CE	Installation of lead-acid battery. Issued October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, 99, A100; T.C. 3A20	SA1017SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA1194CE	Install Teledyne/Gill lead-acid battery, BB638/T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	78052	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, H90; T.C. 3A20	SA1451CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, 65-A90, B90 C90, E90, H90; T.C. 3A20	SA1452CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, A90, B90, C90, E90, 99, 99A, A99A, 100, A100; T.C. 3A20	SA2284SW	Ignition current monitor system. Issued 1/19/76.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
65-90, -90A, -A90-1, -2, -3, -4, B90, C90, E90, 99, 99A, A99, A99A, B99, 200, A200, 200T; T.C. 3A20, A14CE, A24CE	SA566NW	Installation of parachute deployment system. Issued 3/27/78.	NW	80915	U.S. Forest Service 3905 Vista Avenue Boise, ID 83705
65-90, -A90, -A90-1, -A90-2, -A90-3, B-90, C-90; 99, 99A; T.C. 3A20, A14CE	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65-90, -A90, -A90-1, -A90-2, -A90-3, -A90-4, B90, C90, E90; T.C. 3A20	SA2907WE	Installation of fuel tank boost pump. Amended 11/18/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
65-90, -A90, B90, C90; T.C. 3A20	SA3266SW-D	Mitchell automatic flight system AK725 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/24/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
65-A90; T.C. 3A20	SA691CE	Installation of fuel drain manifold tank.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65-A90; T.C. 3A20	SA729SW	Installation of Collins AP-103F/FD-108 autopilot/flight director system and related electronics. Amended 2/14/68.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-A90; T.C. 3A20	SA845CE	Installation of wing flap override switch and duplicate flap down limit switch. Issued May 1972.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65-A90; T.C. 3A20	SA1813SW	Battery temperature sensing and indicating system. Issued 3/8/74.	SW	02300	Aero Instrument Supply, Inc. 7515 Lemon Avenue Box 7481 Dallas, TX 75209
65-A90, -A90-1, B90; T.C. 3A20	SA418SO	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-A90, B90; T.C. 3A20	SA16GL	Install AMF inverter MGE 23-400. Reissued 11/17/78.	GL	50360	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
65-A90, B90, C90; T.C. 3A20	SA377GL	Addition of fourth cabin window on right hand side of fuselage. Issued 11/28/79.	GL	18320	Burlington Northern Airmotive International Airport Minneapolis, MN 55450
65-A90, -B90, -C90, E90; T.C. 3A20	SA3971WE	Installation of SDI Model CFS-2002, fuel flow indicating system. Amended 10/19/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
65-B90, -A90 with 90-4031 kit; T.C. 3A30	SA537CE	Installation of Collins AP-103F/FD108 and AP-103F/FD109G Autopilot and flight director. Amended 9/13/68.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-B90, -A90 with 90-4031 kit; T.C. 3A20	SA567CE	Installation of Collins AP-103F/FD108 and AP-103F/FS108G, AP-103F/FD109G autopilot and flight director. Amended 5/4/70.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA569CE	Installation of Collins AP104/FD109H Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA603CE	Installation of Collins AP-104/FD-109F Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA988CE	Installation of fuel dump valve; G.W. increase to 10,000 pounds. Amended 3/9/70.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
B-90; T.C. 3A2	SA1665SW	Fabricate and install bar assembly. Issued 5/29/73.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
B-90, C-90; T.C. 3A20	SA1454SW	Mitchell automatic flight system model FD/AP282-318 cons. of flight director/autopilot with optional command trim. Issued 4/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B-90, C-90; T.C. 3A20	SA1458SW	Mitchell automatic flight system AK318 cons. of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 4/24/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B90, C90; T.C. 3A20	SA1517SW	Automatic flight system YK384 cons. of yaw damper. Issued 9/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90; T.C. 3A20	SA1583SW	Foxtronics/TRAMM BT1 600 nickel-cadmium battery temperature system. Issued 1/3/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
65-B90, C90, E90; T.C. 3A20	SA547CE	Installation of Bendix M4C autopilot. Amended 8/1/72.	SO	15475	The Bendix Corporation Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FI 33310
65-B90, C90, E90; T.C. 3A20	SA1640SW	Mitchell automatic flight system AK422/FD cons. of Century IV autopilot/flight director with command electric trim. Issued 4/19/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90, E90; T.C. 3A20	SA3042SW-D	Mitchell automatic flight system AK456 or 456 FD cons. of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim system and optional remote annuciator panel. Issued 1/31/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90, E90; T.C. 3A20	SA3294SW-D	Yaw damper system YK384. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C90; T.C. 3A20	SA537SO	Installation of Bendix YD-4 yaw damper. Issued 5/15/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90; T.C. 3A20	SA541SO	Installation of Bendix FCS-810 automatic flight control system including optional flight director indicator DH-841. Amended 1/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90; T.C. 3A20	SA925EA	Installation of Collins AP-105 autopilot system. Issued 6/28/72.	NE	08160	AIRKAMAN, Inc. Bradley International Airport Windsor Locks, CT 06096
C90, E90; T.C. 3A20	SA546SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim system and optional flight director system. Amended 5/16/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90, E90; T.C. 3A20	SA3124WE	Installation of recognition light assembly on horizontal stabilizer. Issued 12/8/75.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
C90, E90, 99; T.C. 3A20, A14CE	SA1013SO	Replace existing nickel-cadmium battery with Gill BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road Suite 200 Atlanta, GA 30339
E90; T.C. 3A20	SA2667WE	Installation of Sperry SPZ-200 autopilot and Stars Instrument System or SPI-77C flight director system. Amended March 1974.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90; T.C. 3A20	SA2680WE	Category II approval of airborne instruments and equipment. Reissued 9/17/73.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90, 99, A100, 200; T.C. 3A20, A14CE, A24CE	SA920SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78052	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
76; T.C. A29CE	SA1153EA	Installation of DeVore "tel-tail" lights on lower surface of horizontal stabilizer. Reissued 7/24/79.	EA	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
76; T.C. A29CE	SA1455CE	Installation of DFC200 flight control system (2 axis). Issued 10/17/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
76; T.C. A29CE	SA3256SW-D	Mitchell automatic flight system AK694 consisting of Century IV autopilot or AK694FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3257SW-D	Mitchell automatic flight system AK693 consisting of Century III autopilot with optioanl radio and glide slope couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3258SW-D	Mitchell automatic flight system AK692 consisting of Century III autopilot with optional radio couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3259SW-D	Mitchell AK619 consisting of Century I autopilot with optional omni tracker. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3260SW-D	Mitchell command electric trim AK695. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
76; T.C. A29CE	SA3261SW-D	Yaw damper system AK696. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3317SW-D	Installation of Mitchell automatic flight system AK761 consisting of Century I autopilot with omni tracker. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3318SW-D	Installation of Mitchell automatic flight system AK762 consisting of Century IIB autopilot with optional radio couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3319SW-D	Installation of Mitchell automatic flight system AK763 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3320SW-D	Installation of Mitchell automatic flight system AK764 consisting of Century IV autopilot or AK764FD consisting of Century IV autopilot flight director with optional remote annunciator. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3321SW-D	Installation of Mitchell automatic flight system AK765 consisting of command electric trim system. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3322SW	Installation of Mitchell yaw damper YK766. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3345SW	Installation of Mitchell yaw damper YK838. Issued 1/28/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3346SW	Mitchell automatic flight system AK827/FD consisting of Century 41/FD flight director autopilot. Issued 12/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3356SW	Installation of Mitchell auromatic flight system AK826 consisting of Century 21 autopilot. Isse3 1/22/80.	SW	60000	Mitchell Industries, Incc. P.O. Box 610 Municipal Airport Mineral Wells, 76067
76; T.C. A29CE	SA4005WE	Removal of main landing gear door. Issued 7/25/79.	WE	71630	Sierra Academy of Aeronautics Oakland International Airort Oakland, CA 94614

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95 Series; T.C. 3A16	SA1-235	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
95 Series; T.C. 3A16	SA1-395	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-422	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-482	16" x 17" opening in lower surface of fuselage.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
95 Series; T.C. 3A16	SA1-588	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
95 Series; T.C. 3A16	SA3-262	Automatic pilot L-2 with or without approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-470	L-2C autopilot with or without approach coupler and altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-624	Winslow oil filter 30409A.	CE	80670	United Airplane Sales, Inc. Municipal Airport Wichita, KS 67202
95 Series; T.C. 3A16	SA3-633	Autopilot L-2C with or without approach coupler and/or altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA4-574	Radio rack in nose compartment.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
95 Series; T.C. 3A16	SA4-691	Oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
95 Series; T.C. 3A16	SA4-1052	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A16	SA4-1612	Anticollision beacon Roto-Lite X6000, either 12 or 24 volt, on vertical fin	WE	49690	The Norman Larson Company Van Nuys Airport Van Nuys, CA 91408
95 Series; T.C. 3A16	SA9SW	Aileron trimmer ATC35-107.	SW	06000	Aircraftsmen, Inc. Hangar 2, Will Rogers Field Oklahoma City, OK 73125
95 Series; T.C. 3A16	SA44EA	Wet pump pneumatic deicing.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA70SW	Vapor automatic temperature control system.	CE	82540	Vapor Heating Company 2522 E. Douglas Wichita, KS 67202
95 Series; T.C. 3A16	SA74CE	Federal F-400 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
95 Series; T.C. 3A16	SA92SW	Automatic pilot AK103 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA171WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oaklana, CA 94608
95 Series; T.C. 3A16	SA173EA	Beech 5D1048 air reservoir assembly relocated for wing and tail boot deicer.	NE	08160	AirKaman, Inc. Bradley Field Windsor Locks, CT 06096

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95 Series; T.C. 3A16	SA231EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA287CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA311WE	Beech pneumatic pitch assist PC-1 and optional installation altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA316EA	M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA360CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation Marquette Division 1145 Galewood Drive Cleveland, OH 44110
95 Series; T.C. 3A16	SA474EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA474WE	B4 flight control system including basic autopilot, pitch assist PC-1, altitude hold AH-1, and navigational coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA516SW	Automatic trim AK160.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA617SW	III autopilot, automatic pitch trim, stabilizer and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA742SW	AK196 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA831WE	Single-place windshield.	WE	69590	SAFE-SITE, Inc. 3511 W. Sixth Street Los Angeles, CA 90005
95 Series; T.C. 3A16	SA844WE	One-piece windshield.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
95 Series; T.C. 3A16	SA1494WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1532WE	Installation of Brittain Model B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1542WE	Installation of Brittain Model B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1559WE	Installation of Brittain Industries Model B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1587WE	Installation of Brittain Model B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1677WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1833WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, B95A, D95A and E95; T.C. 3A16	SA153SO	Installation of turbosupercharged Lycoming O-360-A1A, IO-360-B1A or IO-360-B1B engines. Amended 2/28/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95, B95, B95A, D95A, 95-55, 95-A55, 95-B55; T.C. 3A16	SA263CE	Supplemental Model A high intensity wing tip lights, Model C tail light, with or without Model 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
95, B95, B95A, D95A, 95-55, -A55, -B55, -C55, -D55, -56; T.C. 3A16	SA378CE	Installation of Hoskins Supp. Model A high intensity wing tip lights, Model D or E tail lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
95, B95, B95A, 95-A55, -55, D95A; T.C. 3A16	SA571WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTL Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
95, B95, B95A, 95-55, 95-A55, 95-B55, 95-B55B (T-42A), 95-C55; T.C. 3A16	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-3 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
95, B95, 95-55, 95-A55, B95A, D95A, E95, 95-B55, -B55A, -B55B, -C55, D55, 95-C55A, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA901SO	Installation of single-piece sloped windshield. Amended 11/21/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. c/o F.K. Leddick & Associates, Inc. 175 W. Wieuca Rd., Suite 120 Atlanta, GA 30342
95, B95, B95A, D95A, E95; T.C. 3A16	SA1409SW	Mitchell automatic flight system AK366, cons. of Century I autopilot with optional omni tracker. Issued 12/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D95A; T.C. 3A16	SA1760WE	Installation of Brittain Industries Model B-5 or NAV-2 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, 95-55, -A55, B95A, D95A, E95, -B55, -B55A, -B55B, -C55, D55, -C55A, D55A, E55, E55A; T.C. 3A16	SA2977WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
95, B95, D95A, E95; T.C. 3A16	SA3090SW-D	Automatic flight system AK562, cons. of Century IIB autopilot. Issued 12/15/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95, B95, B95A, D95, E95; T.C. 5A3	SA3179SW-D	Automatic flight system AK650 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 1/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D95, E95; T.C. 5A3	SA3187SW-D	Mitchell automatic flight system AK366 consisting of Century I autopilot with optional omni tracking system. Issued 2/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D59A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA3680WE	Installation of centerline external air skeg. Amended 4/2/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90065
95-55; T.C. 3A16	SA1820WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, -A55, -B55, -C55, -D55; T.C. 3A16	SA9CE	Installation of M4B or M4C flight control system. Amended 6/1/70.	SO	15475	Bendix Corporation Avionics Division 2100 N.W. 62nd Street P.O. Box 9414 Fort Lauderdale, FL 33310
95-55, -A55, -B55; T.C. 3A16	SA126CE	Install Hartzell Model HC-A3XF-2B/7636D or HC-A3VF-2B/V7636D or HC-A3VF-2B/V7636N or PHC-A3XF-2B/7636D or PHC-A3VF-2B/V7636D or PHC-A3VF-2B/V7636N propellers with Woodward Model 210355 or 210438 governors. Reissued 2/26/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-55, 95-A55; T.C. 3A16	SA136RM	Removal of existing nose cone, Beech P/N 95-410011-3 and replacement with later model nose cone, Beech P/N 95-410021-605. Issued 3/28/78.	RM	73948	Spanish Fork Flying Service, Inc. Box 48 Spanish Fork, UT 84660
95-55, A55; T.C. 3A16	SA447SW	Nose modification.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA448SW	Rear baggage compartment.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA540EA	Installation of radome kits No. 3063X-R-100 and -200. Reissued 3/12/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-55, 95-A55, -B55, -B55A, -B55B; T.C. 3A16	SA795CE	Install propeller Models BHC-C2YF-2CH/C8465-6 or BHC-2CHF/FC8465-6, DHC-C2YF-2CH/C8465-6 or DHC-C2YF-2CHF/FC8465-6 with spinner C-2285-1; or PHC-C3YF-2/FC7663-2R with spinner C-3567-1. Amended 8/30/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-55, -A55, -B55, -C55, D55; T.C. 3A16	SA886EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-011401. Issued 10/27/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
95-55, -A55, -B55, -B55A, B55B, C55, C55A, D55, D55A, E55, E55A, 58, 58A; 56TC, A56TC; T.C. 3A16	SA991EA	Installation of "Tel-Tail" logo lights. Reissued 3/18/76.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA1014SO	Installation of Symbolic Displays Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/30/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
95-55, A55, B55, B55B, C55, D55, E55; T.C. 3A16	SA1173SW	Mitchell automatic flight system AK292 cons. of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers. Issued 7/14/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1299SW	Mitchell automatic flight system Model 282-292 cons. of flight director/autopilot with optional automatic pitch trim. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, -D55, -D55A, E55, E55A; T.C. 3A16	SA1300SW	Mitchell automatic flight system AK330, cons. of Century I autopilot with optional omni tracker. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA1472CE	Installation of elevator tail cone fairing. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-55, -A55, -B55, -C55, D55, D55A, E55, E55A, 56TC, A56TC; T.C. 3A16	SA1565SW	Mitchell automatic flight system AK408 cons. of Century II autopilot with optional radio coupler. Issued 12/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1743SW	Mitchell automatic flight system AK401 cons. of Century IIB autopilot with optional radio coupler. Issued 10/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA1777SW	Mitchell automatic flight system AK450 cons. of Century III autopilot with optional command/electric trim radio coupler, and glide slope coupler. Issued 12/26/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A; T.C. 3A16	SA1808SW	Installation of automatic flight system AK446 Century IV autopilot and AK446FD Century IV flight director autopilot with electronic/command, and pitch trim. Issued 2/15/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-55, E95, A-55, B55, C55, B95A, D95A; T.C. 3A16	SA1958WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, 95-A55, -B55, -C55, D55, E55, 58; T.C. 3A16	SA2543WE	Installation of SDI/Hoskins Model 700801 anticollision light. Amended 12/19/72.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
95-55, 95-B55A; T.C. 3A16	SA2882WE	Installation of McCAuley 3AF32C75/82NB-6 full-feathering constant speed propellers and D3499 or D3605 spinner assemblies. Issued 5/13/74.	WE	17154	Dennis A. Praegitzer Bridgeford Flying and Propeller Service P.O. Box 6277 Stockton, CA 95206
95-55, A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3108SW-D	Mitchell AK446 or AK446FD cons. of Century IV flight director autopilot with optional remote annuciator. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3109SW-D	Mitchell AK450 cons. of Century III autopilot with optional command automatic electronic pitch trim system, radio and glide slope coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3295SW-D	Yaw damper system YK428. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A13	SA3333SW-D	Mitchell automatic flight system AK401 consisting of Century IIB autopilot with optional radio couplers. Issued 2/20/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3918WE	Installation of Silver Instruments Fueltron III digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3919WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-A55; T.C. 3A16	SA2690WE	Installation of manual pitch trim system and Lean P/N 800880 autopilot. Issued 6/19/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510
95-A55, -B55, -C55, -D55, E55, E55A, 58; T.C. 3A16	SA1134CE	Installation of King Model KFC-200 flight control system with King Model KC-55/55A compass system. Amended April 1977.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-A55, 95-B55, 95-C55; T.C. 3A16	SA1392WE	Modification of fuselage structure and control system to accommodate a camera installation between Stations 131 and 151.	WE	25971	Continental Airservice, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
95-A55, -B55, -C55, -D55, E55/E55A, 58; T.C. 3A16	SA1523CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-A55, -B55; T.C. 3A16	SA2964WE	Installation of Collins AP 107/FD 112C autopilot/flight director system. Reissued 1/14/75.	CE	24250	Collins Radio Group 5220 "C" Avenue, N.E. Station 120-120 Cedar Rapids, IA 52406
95-B55; T.C. 3A16	SA3179WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 7/27/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
95-B55; T.C. 3A16	SA3353SW	Installation of Mitchell automatic flight system AK841/FD consisting of Century 41/flight director autopilot. Issued 1/29/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-B55, -C55, D55, E55, 56TC, 58; T.C. 3A16	SA15GL	Installation of radome kit No. 3064X. Amended 9/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operation P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-B55, 95-C55, 56TC, D55, E55, 58; T.C. 3A16	SA40GL	Installation of Norton Company radome kit No. 3064X-R-500 for 10" RCA AVQ 45, 46, 47, and the 12" King KWX-40 radar antennas. Amended 4/11/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-B55, -B55A, E55, E55A, 58, 58A; T.C. 3A16	SA64GL	Installation of radome kit P/N 4083X. Amended 5/8/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-B55, -B55A, -C55, -C55A; T.C. 3A16	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
95-B55, -C55, 56TC, D55, E55, 58; T.C. 3A16	SA482EA	Installation of Radome Kit No. 3064X-R-500 for 10-inch RCA AVQ-45, AVQ-46, and AVQ-47 radar antenna. Amended 6/19/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
95-B55 & 95-B55A, T.C. 502 and up; 95-C55 & 95-C55A, TE-1 thru TE-451; 95-D55 & 95-D55A, TE-452 thru TE-767; 95-E55 & 95-E55A, TE768 and on; T.C. 3A16	SA799CE	Installation of Airborne/Goodyear iceguard. Issued April 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
95-B55, -B55A, E55, E55A, 58, 58A; T.C. 3A16	SA1471CE	Installation of flap and aileron seals. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-B55, 95-C55, 95-B55A, 95-C55A; T.C. 3A16	SA2031WE	Installation of Brittain Industries B-VII, NAV-2B, or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-B55, -B55A, -C55, -C55A, D55, D55A; T.C. 3A16	SA3657WE	Installation of a vapor cycle air conditioning system. Issued 6/28/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
95-C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA773CE	Installation of Hartzell BHC-C2Y, BHC-J2Y, PHC-C3Y or PHC-J3Y propellers in accordance with Hartzell Manual 115G.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1054CE	Installation of AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1055CE	Installation of AP-107 3-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1056CE	Installation of AP-107, 2-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, D55, E55, 56TC, A56TC, 58; T.C. 3A16	SA1345CE	Chrome plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
95-C55; T.C. 3A16	SA1713WE	Removal of emergency exit to permit aircraft to engage in special purpose operations such as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
95-C55, -C55A, D55, D55A, E55, E55A, 58 58A; T.C. 3A16	SA3840WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
B95; T.C. 3A16	SA1-463	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
B95; T.C. 3A16	SA3400WE	Installation of Pathfinder autopilot systems. Issued 7/5/77.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B95A, D95A, E95; T.C. 3A16	SA1672SW	Mitchell automatic flight system AK425, cons. of Century III autopilot with optional command automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/7/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
99; T.C. A14CE	SA298GL	Reduce number of passenger seats from 15 to 9. Issued 3/22/79.	GL	27760	Custom Air Service Willow Run Airport Ypsilanti, MI 48197
99; T.C. A14CE	SA366GL	Installation of microwave landing system airborne equipment. Issued 10/12/79.	GL	58150	Mesaba Aviation 2002 Airport Road Grand Rapids, MN 55744
99; T.C. A14CE	SA4030SW	Pratt & Whitney PT6A-27/28 engines. Issued 8/30/79.	SW	69214	Royale Turbines, Inc. Shreveport Regional Airport Shreveport, LA 71109
99, 99A; T.C. A14CE	SA717CE	Installation of M4C autopilot.	CE	15477	Bendix Avionics 3303 East Harry Street Wichita, KS 67218
99, 99A, 99A (FACH), A99, A99A, B99; T.C. A14CE	SA114GL	Installation of Norton Radome Kit 3097X. Issued 5/20/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
99, 99A, A99, A99A, B99; T.C. A14CE	SA143GL	Modification of existing B.F. Goodrich propeller de-icing system. Issued 11/23/76.	GL	38500	B.F. Goodrich Engineered Systems Company Div. of B.F. Goodrich Company Akron, OH 44318
99, 99A, 100, A100; T.C. A14CE	SA811CE	Battery temperature sensing and over-temperature warning systems. Issued February 1972.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
99, A99, 99A, A99A, 100, A100, A100A T.C. A14CE	SA894SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	SO	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
99, 99A, A99, A99A, B99; T.C. A14CE	SA1178CE	Install wing front spar reinforcement kit. Reissued 10/18/78.	CE	70261	David Saunders Apt. 211 1761 Fisher Drive Oxnard, CA 93030
99, 99A, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1280CE	Install Avcon Ind. TSO-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1453CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1454CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Reserach Corporation P.O. Box 222 Buffalo, NY 14225
99, 99A, A99, A99A, B99, 100, A100; T.C. A14CE	SA2908WE	Installation of fuel tank boost pump. Issued 7/23/74.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
99, 99A, 99A (FACH), A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA3106WE	Installation of recognition light assembly on horizontal stabilizer. Amended 10/24/78.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
99, 99A, A99, A99A, B99; T.C. A14CE	SA4013WE	Installation of a hydraulic landing gear retraction system. Issued 9/19/79.	WE	13177	Aviadesign, Inc. Suite 101, Bank of America Levy Building 5808 East Telephone Road Ventura, CA 93003
99A; T.C. A14CE	SA981EA	Installation of modified cargo door, airstair door, jump door in cargo door and external parachute's step. Amended 10/4/74.	EA	23450	C N C Industries, Inc. Hyde Field, Route 223 Clinton, MD 20735
100, A100; T.C. A14CE	SA1197CE	Install Teledyne/Gill lead-acid battery, BB638T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	65300	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
100, A100; T.C. A14CE	SA1573SW	Foxtronics/TRAMM BT1 600 nickel cadmium battery temperature system. Issued 12/19/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
A100; T.C. A14CE	SA256GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
A100; T.C. A14CE	SA476SO	Installation of M4C autopilot in accordance with Bendix drawing list AE-163, Rev. A. Issued 10/14/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
A100; T.C. A14CE	SA1058SO	Replace existing nickel-cadmium batteries with Teledyne Gill B6381T batteries. Issued 3/29/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
B100; T.C. A14CE	SA1018SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
B100, S/N's BE-21 and up; T.C. A14CE	SA3981WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200; T.C. A24CE	SA381GL	Installation of a single Canadian Marconi CMA-734 Omega/VLF navigation system. Issued 1/4/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
200; T.C. A24CE	SA1016SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 POwers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
200; T.C. A24CE	SA1189CE	Installation of Safe Flight speed command or speed command and auto-throttle (SCAT) system. Amended 6/8/77	EA	69500	Safe Flight Instrument Corp. (SFIC) P.O. Box 550 White Plains, NY 10602
200; T.C. A24CE	SA3339WE	Installation of Hydro-Aire power brake/skid control system. Issued 5/17/77.	WE	26725	Hydro-Aire Division Crane Company, Inc. P.O. Box 7722 Burbank, CA 91510
200; T.C. A24CE	SA3982WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200, A200; T.C. A24CE	SA1278CE	Installation of Avcon Industries TSO-C39a stretchers. Issued February 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
200, A200, 200T; T.C. A24CE	SA192GL	Installation of Norton radome kit No. 2090XS Amended 8/24/78.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operation P.O. Box 350 Akron, OH 44309
200, A200, 200T; T.C. A24CE	SA1449CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
200, A200, 200T; T.C. A24CE	SA1450CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
BELL HELICOPTER TEXTRON

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
(Texas Helicopter) OH-13E/M74, OH-13H/M74; T.C. H7SW	SH2994SW	Night working light kit. Issued 5/10/79.	SW	03240	Ag-King, Inc. P.O. Box 815 Paragould, AR 72450
47 Series; T.C. H-1, 2H3, 2H1	SH1-67	Franklin 6V-335-A engine.	EA	04546	Aircooled Motors, Inc. Liverpool Road Syracuse, NY 13201
47 Series; T.C. H-1, 2H3, 2H1	SH1-437	Stewart-Warner combustion heater F-24, relocation of aircraft junction box and special centrifugal blower SP-151.	NE	61770	Nutmeg Airways Corporation P.O. Box 18 New Britain, CT 06050
47 Series; T.C. H-1, 2H3, 2H1	SH1-509	Lube oil filter PB55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
47 Series; T.C. H-1, 2H3, 2H1	SH1-512	Aircooled Motors 6VS-335A turbo-supercharged engine (derated).	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Route 1, Box 94 Perkasie, PA 18944
47 Series; T.C. H-1, 2H3, 2H1	SH3-473	Heater.	GL	21700	Chicago Helicopter Airways, Inc. 5240 W. 63 Street Chicago, IL 60638
47 Series; T.C. H-1, 2H3, 2H1	SH3-517	Engine exhuast cabin heating system.	GL	72252	Skymotive, Inc. FAA Repair Station 3712 P.O. Box 448 Park Ridge, IL 60068
47 Series; T.C. H-1, 2H3, 2H1	SH3-561	Sunshade to reduce heat and glare in cockpit.	CE	59760	Mississippi Valley Helicopters, Inc. Lambert Field St. Louis, MO 63155
47 Series; T.C. H-1, 2H3, 2H1	SH4-235	Franklin 6V-335-A engine restricted to 200 hp.	WE	03180	Aetna Helicopters, Inc. Etna, CA 96027
47 Series; T.C. H-1, 2H3, 2H1	SH4-349	Fabrication and installation of adapter assembly for bomb shackle mounting. (When any load or device is carried on the bomb shackle, operation must be under restricted category.)	WE	03270	U.S. Department of Agriculture Forest Service 444 E. Bonita Avenue San Dimas, CA 91773
47 Series; T.C. H-1, 2H3, 2H1	SH4-494	Full flow lube oil filter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
47 Series; T.C. H-1, 2H3, 2H1	SH4-612	Conversion of Model 47G to Model 47G-2M.	WE	73894	Southwest Helicopters, Inc. 7646 Hayvenhurst Avenue Van Nuys, CA 91408
47 Series; T.C. H-1, 2H3, 2H1	SH4-619	Exhaust muffler.	WE	61646	Northrop Aircraft, Inc. 1001 E. Broadway Hawthorne, CA 90250
47 Series; T.C. H-1, 2H3, 2H1	SH4-693	Landing gear extended and electro-magnetic prospecting equipment installed.	SW	78424	Texas Gulf Sulphur Company 811 Rusk Avenue Houston, TX 77002
47 Series; T.C. H-1, 2H3, 2H1	SH4-742	Power takeoff unit at generator pad of Lycoming VO-435-A engine to drive centrifugal pump (Simplex ALCCS-1) for agricultural spraying operations.	WE	75425	Stockton Helicopters 1595 Lindbergh Street Stockton, CA 95204
47 Series; T.C. H-1, 2H3, 2H1	SH4-826	Franklin 6V-335-AIA engine.	NW	31775	Economy Helicopters 2108 W. Washington Avenue Yakima, WA 98901
47 Series; T.C. H-1, 2H3, 2H1	SH4-1161	Full flow lube oil filter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
47 Series; T.C. H-1, 2H3, 2H1	SH4-1162	Adapter assembly bomb shackle mounting fabrication and installation. (When any load or device is carried on the bomb shackle operation must be under restricted category.)	WE	03270	U.S. Department of Agriculture Forest Service 444 E. Bonita Avenue San Dimas, CA 91773

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47 Series; T.C. H-1, 2H3, 2H1	SH4-1315	Seeding accessory.	WE	69060	Bernard J. Rollinger 1017 Kendall Drive San Gabriel, CA 91776
47 Series; T.C. H-1, 2H3, 2H1	SH4-1332	Cargo sling and shackle. (When any load is carried on this shackle, operations must be under restricted category.)	RM	02370	U.S. Department of Agriculture Forest Service Missoula, MT 59801
47 Series; T.C. H-1, 2H3, 2H1	SH4-1340	Spray pump 1-1/4 inch. (Restricted category only.)	NW	71770	Simplex Manufacturing Company 5224 NE. 42 Avenue Portland, OR 97218
47 Series; T.C. H-1, 2H3, 2H1	SH4-1349	Spray pump 1-1/4 inch. (Restricted category only.)	NW	71770	Simplex Manufacturing Company 5224 NE. 42 Avenue Portland, OR 97218
47 Series; T.C. H-1, 2H3, 2H1	SH4-1392	Pesco 1P-677 hydraulic pump.	WE	25300	Comet Copters 7222 Hinds Avenue North Hollywood, CA 91603
47 Series; T.C. H-1, 2H3, 2H1	SH4-1419	Exhaust muffler.	WE	61646	Northrop Aircraft, Inc. 1001 E. Broadway Hawthorne, CA 90250
47 Series; T.C. H-1, 2H3, 2H1	SH4-1499	Exhaust mufflers.	WE	25300	Comet Copters 7222 Hinds Avenue North Hollywood, CA 91603
47 Series; T.C. H-1, 2H3, 2H1	SH4-1512	Installation of adapter assembly for bomb shackel, or cargo hook. Amended 5/9/69.	WE	69060	U.S. Department of Agriculture Forest Service Equipment Development Center 444 E. Bonita Avenue San Dimas, CA 91773
47 Series; T.C. H-1, 2H3, 2H1	SH4-1555	Spray equipment.	WE	03250	Agricultural Aviation Engineering Company 858 Scott Street Santa Clara, CA 95050
47 Series; T.C. H-1, 2H3, 2H1	SH4-1604	100-gallon borate tank.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
47 Series; T.C. H-1, 2H3, 2H1	SH4-1628	Full flow lube oil filter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
47 Series; T.C. H-1, 2H3, 2H1	SH4-1646	Full flow lube oil filter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
47 Series; T.C. H-1, 2H3, 2H1	SH4-1650	Engine cooling fan shrouds.	NW	04500	Air Carrier Interiors, Inc. 8167 Perimeter Road Boeing Field Seattle, WA 98101
47 Series; T.C. H-1, 2H3, 2H1	SA5-24	Additional seat belt fittings to provide individual belts.	AL	33650	ERA Helicopters, Inc. P.O. Box 762 Anchorage, AK 99501
47 Series; T.C. H-1, 2H3, 2H1	SH5-25	Installation of tundra snow shoes. Amended 7/14/70.	AL	33650	ERA Helicopters, Inc. P.O. Box 762 Anchorage, AK 99501
47 Series; T.C. H-1, 2H3, 2H1	SA5-34	Northern radio 414.	AL	33650	ERA Helicopters, Inc. P.O. Box 762 Anchorage, AK 99501
47 Series; T.C. H-1, 2H3, 2H1	SA5-35	Northern radio 414.	AL	33650	ERA Helicopters, Inc. P.O. Box 762 Anchorage, AK 99501
47 Series; T.C. H-1, 2H3, 2H1	SA5-38	Northern radio N412.	AL	33650	ERA Helicopters, Inc. P.O. Box 762 Anchorage, AK 99501
47 Series; T.C. H-1, 2H3, 2H1	SA1IN	Helicopter bubble Series A, P/N 500-B.	EA	64714	Plastal Manufacturing Ltd. 476 Edouard Street Granby, P.O., Canada
47 Series; T.C. H-1, 2H3, 2H1	SH5WE	Cargo cling 6162 and hook 1100.	WE	41770	Helicopter Mechanics Service 7408 Leescott Avenue Van Nuys, CA 91408
47 Series; T.C. H-1, 2H3, 2H1	SH6CE	Snow shoes.	RM	46782	Johnson Flying Service, Inc. Box 1366 Municipal Airport Missoula, MT 59801

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47 Series; T.C. H-1, 2H3, 2H1	SH7CE	Cargo carrier.	RM	46782	Johnson Flying Service, Inc. P.O. Box 1366 Municipal Airport Missoula, MT 59801
47 Series; T.C. H-1, 2H3, 2H1	SH17WE	Adapter bracket utilized as attachment for lifting a maximum external load of 928 lbs.	WE	52070	Los Angeles County Fire Department 1350 N. Eastern Los Angeles, CA 90052
47 Series; T.C. H-1, 2H3, 2H1	SH17AL	Tundra board.	AL	08486	Alaska Helicopters, Inc. P.O. Box 1023 Anchorage, AK 99501
47 Series; T.C. H-1, 2H3, 2H1	SH19AL	Cargo racks.	AL	44260	International Helicopters, Inc. Box 6227, Annex Anchorage, AK 99500
47 Series; T.C. H-1, 2H3, 2H1	SH21EA	Fabrication and installation of C-4 cabin kit. (Eligible only on helicopters modified per STC SH1-512.)	EA	19950	Carson Helicopters, Inc. R. 1, Box 94 Perkasie, PA 18944
47 Series; T.C. H-1, 2H3, 2H1	SH25SW	Transceivers KY90, KY90E, KY90H, KY95, KY95E, and KY95H.	CE	48250	King Radio Corporation 139 S. Brockway Olathe, KS 66061
47 Series; T.C. H-1, 2H3, 2H1	SH27WE	Jump-step.	WE	03270	U.S. Department of Agriculture Forest Service 444 E. Bonita Avenue San Dimas, CA 91773
47 Series; T.C. H-1, 2H3, 2H1	SH36AL	Tundra pads.	AL	44260	International Helicopters, Inc. Box 6227, Annex Anchorage, AK 99500
47 Series; T.C. H-1, 2H3, 2H1	SH48WE	Installation of turbosupercharged Lycoming TVO-435-B1A engine.	NW	46400	The Jobmaster Company, Inc. P.O. Box 274 Renton, WA 98055
47 Series; T.C. H-1, 2H3, 2H1	SH58WE	Three-view camera mount and Wild RC-8 camera.	WE	64450	Pictorial Crafts, Inc. 1037 Base Line San Bernardino, CA 92403
47 Series; T.C. H-1, 2H3, 2H1	SH59WE	Twin flow pump on Franklin engine lower generator drive pad and reroute of right-hand tail rotor cable.	NW	71770	Simplex Manufacturing Company 5224 NE. 42 Avenue Portland, OR 97218
47 Series; T.C. H-1, 2H3, 2H1	SH61WE	Bowles heli-tank on previously approved bomb shackle adapter assembly.	WE	03270	U.S. Department of Agriculture Forest Service Equipment Development Center 444 E. Bonita Avenue San Dimas, CA 91773
47 Series; T.C. H-1, 2H3, 2H1	SH62SW	Long range fuel tanks.	SW	64300	Petroleum Helicopters, Inc. P.O. Box T Lafayette, LA 70501
47 Series; T.C. H-1, 2H3, 2H1	SH73WE	Spray system with Simplex pump.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
47 Series; T.C. H-1, 2H3, 2H1	SH87SW	Dust, seeder, or spray kit 500.	SW	70285	Saylor Flying Service P.O. Box 665 Port Lavaca, TX 77979
47 Series; T.C. H-1, 2H3, 2H1	SH95SW	Bell 47G-2 floats.	SW	64300	Petroleum Helicopters, Inc. P.O. Box T Lafayette, LA 70501
47 Series; T.C. H-1, 2H3, 2H1	SH136SW	Provisions for use of stokes litter with left cabin door propped open 22.8 inches.	SW	19600	California Oil Company 1111 Tulane Avenue New Orleans, LA 70113
47 Series; T.C. H-1, 2H3, 2H1	SH163EA	Copilot seat assembly 47-5000-R.	EA	19950	Carson Helicopters, Inc. R. 1, Box 94 Perkasie, PA 18944
47 Series; T.C. H-1, 2H3, 2H1	SH165EA	Heater kit 50-1000 fabrication and installation.	EA	19950	Carson Helicopters, Inc. R. 1, Box 94 Perkasie, PA 18944
47 Series; T.C. H-1, 2H3, 2H1	SH176EA	Stewart-Warner heater. Amended 5/1/67.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
47 Series; T.C. H-1, 2H3, 2H1	SH184SW	Cargo sling, 800 lbs. capacity. (Restricted category only.)	SW	64300	Petroleum Helicopters, Inc. P.O. Box T Lafayette, LA 70501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47 Series; T.C. H-1, 2H3, 2H1	SH186SW	Lycoming VO-540-B1B3 engine, transmission, Bell 47-620-600-25 (or -23 modified to -25 by Bell Helicopter Co.) oil cooler, Bell 47-671-036-1, and associated changes. (Eligible on skiplane version of Bell 47G-2A only.)	SW	19660	Campbell Air Service, Inc. P.O. Box 7261 Shreveport, LA 71102
47 Series; T.C. H-1, 2H3, 2H1	SH210EA	Cabin modification kit C-4 and copilot's seat.	EA	19950	Carson Helicopters, Inc. R. 1, Box 94 Perkasie, PA 18944
47 Series; T.C. H-1, 2H3, 2H1	SH252SW	Bendix 100-ampere generator 30E16-11C. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
47 Series; T.C. H-1, 2H3, 2H1	SH307SW	Lycoming VO-540-B1B3 engine.	SW	64300	Petroleum Helicopters, Inc. P.O. Box T Lafayette, LA 70501
47 Series; T.C. H-1, 2H3, 2H1	SH479SW	6V350A engine. Amended 3/2/67.	EA	36750	Franklin Engine Company Old Liverpool Road Syracuse, NY 13201
47 Series; T.C. H-1, 2H3, 2H1	SH799SW	Water contact sensor.	SW	50306	Lek-Trol, Inc. Grapevine, TX 76051
47 Series; T.C. H-1, 2H3	SH77WE	Installation of Simplex Bi-Fluid Spray System. Amended 1/16/69.	NW	71770	Simplex Manufacturing Company 5224 NE. 42 Avenue Portland, OR 97218
47 Series; T.C. H-1, 2H3	SH95WE	Installation of low profile spray system.	NW	71770	Simplex Manufacturing Company 5224 NE. 42 Avenue Portland, OR 97218
47 Series; T.C. H-1, 2H3	SH101WE	Replacement of existing 50 ampere generator with 100 ampere RWS-985-1340 generator. Amended 9/5/68.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
47 Series; T.C. H-1, 2H3	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Company airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
47 Series; T.C. 2H1	SH64WE	Turbosupercharged Lycoming TVO-435-B1A engine.	WE	65328	Progressive Aviation Ltd. Reid Hillview Airport San Jose, CA 95122
47 Series; T.C. 2H3	SH75WE	Installation of Model BG5 agricultural spreader.	NW	33900	Evergreen Helicopter, Inc. P.O. Box 382 McMinnville, OR 97128
47 Series; T.C. 2H3	SH104WE	Installation of Nightsun SX-16 or SX-16C Searchlight. Amended 1/16/69.	WE	74500	Spectrolab Division of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
47 Series; T.C. 2H3	SH112WE	Installation of box ejector for Codling Moth Control.	NW	03270	U.S. Department of Agriculture Agricultural Research Service P.O. Box 278 Forest Grove, OR 97116
47, 47B, 47B3, 47D, 47D1, 47E, 47G, 47G-2, 47H-1; T.C. H-1	SH200WE	Installation of stirrup assemblies to directional control pedals for operation by handicapped pilot. Issued 4/14/77.	WE	28620	Barry C. Dallwig 113 East Elfin Green Port Hueneme, CA 93041
47, 47B, B3, 47D, D1, E, 47G, G-2, G-2A, -2A-1, -3, -3B, -3B-1, -3B-2, -3B-2A, -4, -4A, -5, -5A, 47H-1; T.C. H-1, 2H3	SH214NW	Installation of Model 4100 aerial dust system. Issued 9/9/75.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
47B, 47B-3, 47-D-1, 47E, 47G, 47G-2, 47H-1; T.C. H1	SH169WE	Installation of exhaust muffler assembly. Amended 1/31/75.	WE	49850	LearAvia Corporation P.O. Box 10825 Reno, NV 89510
47B, B3, D, D1, E, G, G-2, H-1; 47G-2, -2A-1, -3, -3B, -3B-1, -3B-27, -4, -4A, -5, -5A; 47J, K, J-2, J-2A; 206A, 206B; T.C. H-1, 2H3, 2H1, H2SW	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47B, B3, D, D1, E, G, G-2, H-1; 47G-2A, -2A-1, -3, -3B, -3B-1, -3B-27, -4, -4A, -5, -5A; 47J, K, J-2, J-2A; 206A, 206B; T.C. H-1, 2H3, 2H1, H2SW	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A450, A408W or A470W (white), A408R/W or A470 R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417
47B, B3, D, D1, E, G, G-2, H-1, G-2A, -2A-1, G3, -3B, -3B-1, -2, G-4, G-5, -5A, B-3B, -2A, G-4A-5; T.C. H-1, 2H3	SW2840SW	Chemical spray boom. Reissued 4/19/79.	SW	84614	Warnell Company Box 588 Atlanta, TX 75551
47D-1; T.C. H-1	SH13WE	Conversion of Bell Model 47D-1 to (1) Model 47G-2. Reissued 1/18/74.	SW	52800	Gifton McCreary 1921 W. 5th Street, Apt. #180 Irving, TX 75060
47D-1; T.C. H-1	SH283SW	Battery relocated and ballast installed. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D-1; T.C. H-1	SH397SW	Hydraulic boost kit. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D-1; T.C. H-1	SH529SW	Franklin 6V-350-A engine. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1; T.C. H1	SA2666WE	Ceconite 102 material covering of vertical fin. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
47D-1, 47G; T.C. H-1	SH213WE	Installation of exhaust muffler assembly. Issued 3/8/78.	WE	00100	A & H Welding Company 11230 Ilex Avenue Pacoima, CA 91331
47D1, 47G; T.C. H-1	SH752SW	Centerframe and Lycoming VO-435 engine.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G; T.C. H-1	SH888SW	Use of spacer in lieu of snap ring on tail rotor drive. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G-2; T.C. H-1	SH1007SW	Modify tail rotor pitch change mechanism to add duplex bearing. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G-2; T.C. H1	SH2772SW	Revise mast controls and remove stabilizer bar and install control system.	SW	78425	Texas Helicopter Corporation 1336 South Irving Heights Drive Irving, TX 75060
47D1, 47G-2; T.C. H-1	SH588SW	Conversion to single-place cabin without doors and revised controls. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G-2, 47G-3, 47G-4; T.C. H-1, 2H3	SH611SW	Left and right door with tinted sliding windows. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G2, G2A, G2A-1, G-3, -3B, -1, -4, -4A, -5, -3B-2; T.C. H-1, 2H3	SH972SW	Copilot's rudder pedals. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47E, 47G-2, -2A, -2A-1, 47G-3, -3B, -3B-1, -3B-2, 47G-4, -4A, 47G-5, 47J, 47J-2, -2A, 47K; T.C. H-1, 2H3, 2H1	SH102WE	Installation of automatic flagman model 5. Issued 2/17/71.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362
47G Series; T.C. H-1, 2H3, 2H1	SH5CE	Install 32 foot agricultural spray boom assembly. Issued 1/31/78.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G; T.C. 2H3	SH78WE	Installation of Calicopters Cabin Heater Kit CC 1000.	WE	19440	Calicopters, Inc. 1595 Lindbergh Street Stockton, CA 95206
47G; T.C. H-1	SH610EA	Following modifications are compatible with each other and may be incorporated simultaneously: STCs SA479SW, SH21EA, SH163EA.	EA	19950	Carson Helicopters, Inc. R.R. 1, Box 94 Perkasie, PA 18944

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47G Series; T.C. 2H3	SH657NW	Installation of Allison 250 series engines. Issued 9/7/78.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
47G Series; T.C. 2H3	SH787NW	Installation of model 5700 spray system. Issued 7/9/79.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47 Series (as modified by STC SH657NW); T.C. H-1, 2HE	SH828NW	Installation of weighing system. Issued 9/6/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
47G, 47G-2; T.C. H-1	SH165GL	Installation of low fuel warning system. Issued 4/27/77.	GL	49320	Lake Line Helicopters, Inc. 13601 Pioneer Trail Eden Prairie, MN 55343
47G, 47G2; T.C. H-1	SH191WE	Installation of Jasco alternator, P/N 7555-1, 24 volt system. Amended 4/19/79.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
47G-2; T.C. H-1	SA151GL	Installation of Lycoming VO-435-A1F engine modified in accordance with STC SE144GL. Amended 7/5/77.	GL	49320	Lake Line Helicopters, Inc. 13601 Pioneer Trail Eden Prairie, MN 55343
47G-2; T.C. H-1	SH159WE	Installation of a muffler. Amended 11/8/73.	WE	49850	LearAvia Corporation Avionics Division P.O. Box 10600 14505 Mt. Anderson Avenue Reno, NV 89510
47G-2; T.C. H-1	SA266CE	Installation of crane bar. Reissued 1/29/75.	EA	69232	G. Loren Ruhl 724 Thirteenth Avenue, Apt. #3 Huntington, WV 25701
47G-2, 47G-2A, -2A-1, 47G-3B, -3B-1, -3B-2, 47G-4, -4A, 47G-5; T.C. 2H3	SH141WE	Installation of aerial seeder. Amended 5/2/72.	NW	71770	Simplex Manufacturing Company 5224 NE. 42 Avenue Portland, OR 97218
47G-2, 47G-2A, 47G-2A-1, 47G-3B, 47G-1, 47G-3B-2, 47G-4, 47G-4A, 47G-5; T.C. 2H3	SH143WE	Installation of a 12 volt, 40 ampere alternator on auxiliary power take-off pad. Issued 5/9/72.	WE	03270	U.S. Department of Agriculture Forest Service 444 East Bonita Avenue San Dimas, CA 91773
47G-2, -2A, -2A1, -3, -3B, -3B1, -2, -4, -4A; T.C. H-1, 2H3	SH381AL	Installation of cargo baskets. Issued 8/18/70.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
47G-2, G-2A, G-2A-1, G-5; 47G-3, G-3B, G-3B-1, G-4, G-4A; 47J, J-2, J-2A, K; T.C. H-1, 2H3, 2H1	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
47G-2, 47G-2A-1; T.C. 2H3	SH960EA	Incorporation of AVCO Lycoming Model VO-435-A1F or VO-435-A1F engine modified in accordance with STC SE959EA. Amended and reissued 3/11/76.	EA	03300	AGROTORS, Inc. Box 578 Gettysburg, PA 17325
47G-2, -2A, -2A-1, 47G-3B, -3B-1, -3B-2, 47G-4, -4A; T.C. H-1	SH2348SW	Redesigned spray system. Issued 8/13/76.	SW	78425	Texas Helicopter Co., Inc. 1336 S. Irving Heights Drive Irving, TX 75060
47G-2, -2A, -2A1, 2H3, Texas Helicopter M74/OH, 13E; T.C. H-1, 2H3, H7SW	SH2397SW	Install Ag-King 500B spray system with two tanks (800 lbs. total allowable) 32 feet boom on end of skid tubes and engine driven pump. Issued 1/27/77.	SW	03240	Ag-King Manufacturing P.O. Box 815 Paragould, AR 72450
47G-2, 47G-5, 47G-5A,. -2A, -2A1; T.C. 2H3	SH161WE	Installation of exhaust muffler assembly. Amended 10/16/75.	WE	00100	A & H Welding Company 9317 Borden Avenue Sun Valley, CA 91352
47G-2A, -2A-1, G-3, G-3B, G-3B-1, G-3B-2, G-3B-2A, G-4, G-4A, G-5, G-5A; T.C. 2H3	SH166GL	Installation of low fuel warning system. Issued 4/27/77.	GL	49320	Lake Line Helicopters, Inc. 13601 Pioneer Trail Eden Prairie, MN 55343
47G-2A, 47G-2A1, 47G-5, 47G-5A; T.C. 2H3	SH170WE	Installation of exhaust muffler assembly. Issued 9/13/74.	WE	49850	LearAvia Corporation P.O. Box 10825 Reno, NV 89510
47G-2A, -2A-1, -3B, -3B-1, -3B-2, -3B-2A, -5, -5A, -4, -4A; T.C. 2H3	SH175WE	Removal of generator and installation of Ford-GPD alternator. Issued 1/8/75.	WE	78620	TORQAID 3190 Cherry Avenue Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47G-2A, -2A-1, 47G-3, -3B, -3B-1, -3B-2, -3B-2A, 47G-4, -4A, 47G-5, -5A; T.C. 2H3	SH193WE	Installation of Jasco alternator P/N 7555-1 volt system. Amended 7/3/79.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
47G-2A, -2A-1, -3-B, -3-B-1, -3-B-2, G-4; T.C. 2H3	SA357SW	Installation of Simplex spray kit. Amended 5/18/77.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G-2A, -2A-1, 47G-3, -3B, -3B-1, -3B-2, 47G-4, -4A, 47G-5; T.C. 2H3	SH370GL	Installation of Ni-Cad model No. 82164 engine lubrication system scavenge filter. Issued 11/2/79.	GL	61546	Ni-Cad, Inc. 24800 U.S. 20 South Bend, IN 46628
47G3, 47G-3B, 47G-3B-1, 47G-2A, 47G-4A, 47G-5; T.C. 2H3	SH88WE	Installation of cargo hook. Amended 5/10/71.	WE	63350	Thomas A. Patterson Helicopter Mechanics Service 7621 Tobias Avenue Van Nuys, CA 91405
47G-3B; T.C. 2H3	SH157GL	Installation of Lycoming VO-435-A1F engine. Issued 4/22/77.	GL	03280	Agri Helicopter, Inc. 840 Havana Road Owatonna, MN 55060
47G-3B; T.C. 2H3	SH173WE	Installation of derated Lycoming TVO-435-B1A or TVC-435-B1B engine in lieu of TVO-435-A1A engine using existing TVO-435-A1A installation components. Issued 11/11/74.	WE	85144	Western Helicopters, Inc. P.O. Box 579 1670 Airport Way Rialto, CA 92376
47G-3B; T.C. 2H3	SH986EA	Installation of Avco Lycoming engine Model TVO-435-B1A (O-435-25A) in lieu of model TVO-4350A1A. Issued 8/16/74.	EA	61188	Nassau County Police Department Air Bureau 1490 Franklin Avenue Mineola, NY 11501
47G-3B; T.C. 2H3	SH227GL	Installation of Lycoming VO-435-A1F engine. Issued 3/6/78.	GL	03280	Agri Helicopter, Inc. 840 Havana Road Owatonna, MN 55060
47G-3B-1; T.C. 2H3	SH86WE	Installation of cargo racks.	RM	65331	Provo Flying Service, Inc. P.O. Box 691 Provo, UT 84601
47G-3B-1; T.C. 2H3	SH93WE	Installation of supplemental exterior flashing lights.	RM	29250	Delta Products, Inc. P.O. Box 1147 Grand Junction, CO 81501
47G-3B-1; T.C. 2H3	SH226GL	Installation of Lycoming VO-435-A1F engine. Issued 3/6/78.	GL	03280	Agri Helicopter, Inc. 840 Havana Road Owatonna, MN 55060
47G-3B-1, 47G-3B-2, 47G-4, 47G-4A, 47G-5; T.C. 2H3	SH100WE	Installation of fiberglass baggage carriers.	WE	79300	Transland Aircraft, Inc. 24511 Frampton Avenue Harbor City, CA 90710
47G-3B-2A, 47G-5A; T.C. 2H3	SH153WE	Installation of Transland Model 54170 agricultural spray system. REissued 10/31/74.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
47G-4, 47G-4A; T.C. 2H3	SH162WE	Installation of exhaust muffler assembly. Issued 3/8/74.	WE	00100	A & H Welding Company 9317 Borden Avenue Sun Valley, CA 91352
47G-5; T.C. 2H3	SH15CE	Install Stewart Warner Model 940F combustion heater. Issued June 1972.	CE	33580	EPM Corporation P.O. Box 5978, Lambert Field St. Louis, MO 63134
47G-5; T.C. 2H3	SH204WE	Installation of AC-OF-104A oil filter at longtudinal station (-14.0). Amended 10/3/79.	WE	90115	Yuma Helicopters, Inc. P.O. Box 4935 Yuma, AZ 85364
47G-5 (Normal Category); T.C. 2H3	SH254WE	Installation of Gill Model PS-6-11 battery, together with an external power source. Issued 9/28/79.	WE	90115	Yuma Heliocpters, Inc. P.O. Box 4935 Yuma, AZ 85364
47H-1; T.C. TCH-1	SH909SW	Franklin 6V-350-A engine. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47J; T.C. 2H1	SH375AL	Installation of Airglas model L2700-47J skis. Issued 5/26/70.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
47J; T.C. 2H1	SH1422CE	Installation of engine exhaust muffler. Issued 6/12/78.	CE	36510	Fostaire Helicopters 400 North Wharf Street St. Louis, MO 63102

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47J, 47J2, 47J2A, 47K; T.C. 2H1	SH194WE	Installation of Jasco alternator P/N 7555-1 24-volt system. Amended 7/3/79.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
47J, 47J2, 47J2A, 47K; T.C. 2H1	SH199WE	Installation of stirrup assemblies to directional control pedals for operation by handicapped pilot. Issued 4/14/77.	WE	28620	Barry C. Dallwig 113 East Elfin Green Port Hueneme, CA 93041
47J-2, -2A; 47G-3B, 3B-1, 3B-2; T.C. 2H1, 2H3	SH12CE	Replace existing engine induction air filter with AC Spark Plug Filter - Type AAF-103.	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
204, 205, 212; T.C. H1SW, H4SW	SH611NW	Installation of onboard weighing system. Issued 6/16/78.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
204B; T.C. H1SW	SH984SO	Installation of Lycoming T5313A or B engines, replacing Lycoming T5311A engines, including minor installation changes. Issued 5/10/78.	SO	86080	Wilco Aviation bBlackwell Airport P.O. Box 506 Ozark, AL 36360
204B, 205A, 205A-1; T.C. H1SW	SH149WE	Installation of Chadwick electronic weighing system C47. Issued 6/1/72.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
204B, 205A, 205A-1; T.C. H1SW	SH172WE	Installation of A500 battery temperature monitor systems. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
204B, 205A, 205A-1; 206A, 206B, 206B-1, 206L, 212; T.C. H1SW, H2SW, H4SW	SH155WE	Installation of battery temperature monitor system. Amended 6/22/78.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
204B, UH1-B; T.C. H1SW	SH183AL	Installation of Airglas L7000 or L8500B skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
204B, 205A, 205A-1, 212; T.C. H1SW, H4SW	SH733NW	Installation of onboard weighing system. Issued 3/21/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
205A, 205A-1; T.C. H1SW	SH198AL	Installation of Airglas L8500 or L8500A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
205A, 205A-1; T.C. H1SW	SH255WE	Installation of emergency exit window. Reissued 1/11/80.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
205A, 205A-1; T.C. H1SW	SH462NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
205A, 205A-1; T.C. H1SW	SH1022SW	Interior arrangement for 7 passengerWE seats and 1 jump seat. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
205A, 205A-1; T.C. H1SW	SH1789SW	Foxtronics/Tramm BTI 600 nickel cadmium battery temperature system. Issued 1/29/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
205A, -1, 212; T.C. H1SW, H4SW	SH1700SW	Hard surface skid shoes. Issued 6/6/73.	SW	61650	Northrop Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
205A-1; T.C. H1SW	SH140GL	Installation of dual band (K/X) type weather radome. Issued 10/27/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
206; T.C. H2SW	SH329NW	Installation of automatic flagman. Issued 10/28/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362
206 Series; T.C. H2SW	SH1091SO	Replace existing battery with an Eagle-Picher magnum 13 battery. Issued 8/22/79.	SW	18190	BSI Manufacturing, Inc. 101 Space Park South Drive Nashville, TN 37211
206, 206A, 206B; T.C. H2SW	SH963EA	Installation of battery temperature alert system Model Bell B206-TA180 or B206D-TA180. Amended 6/28/74.	EA	25920	Consolidated Instrument Co., Inc. Teterboro Airport Teterboro, NJ 07608
206, 206A, 206A-1, 206B, 206B-1; T.C. H2SW	SH1018EA	Installation of Casey shroud type heater. Amended 11/14/79.	EA	20112	Casey Copter Accessories, Ltd. P.O. Box 121 Montreal International Airport Dorval, Quebec, Canada H4Y 1A5

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206, A, A-1, B, B-1, L, L-1; T.C. H2SW	SH2828SW	Sloping pedestal and instrument. Issued 8/4/78.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
206, A, A-1, B, B-1, L; T.C. H2SW	SH4061SW	Install ruggedized attitude gyro and related vacuum system components. Issued 11/27/79.	SW	40000	Hamilton Instruments, Inc. 106 Neuhaus Street Houston, TX 77061
206A; T.C. H2SW	SH10CE	Install Hoskins Twilighter Mk III lighting system consisting of P/N 60-0032-31 power supply and two of Model 2 P/N 30-0021-11 lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
206A; T.C. H2SW	SH117WE	Installation of cargo rack on one side or on both sides of skid gear. Amended 10/20/70.	WE	03270	U.S. Department of Agriculture Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
206A, 206B, 206L, 206L-1, Normal Category; T.C. H2SW	SH240WE	Installation of baggage compartment extension. Issued 7/12/79.	WE	50275	Ronald A. Leibin and Stephen H. Crowe 2761 Hollywood Way Burbank, CA 91505
206A; T.C. H2SW	SH411AL	Installation of mirror kit assembly. Issued 12/15/70.	AL	10650	Anchorage Helicopter Service, Inc. 1812 East Fifth Avenue Anchorage, AK 99501
206A; T.C. H2SW	SH635EA	Operate with one or both rear doors removed and both front doors installed on helicopters equipped with or without emergency float gear.	EA	65008	The Port of New York Authority 111 8th Avenue, Room 1601 New York, NY 10011
206A; T.C. H2SW	SH837EA	Installation of Airborne television and microwave transmission system. Amended 3/24/71.	EA	30992	Dynasciences Corporation Township Line Road Blue Bell, PA 19422
206A; T.C. H2SW	SH864EA	Installation of AACK-1R Optical Radiation Corporation Model B "Locator" search light plus relocation of landing lights. Installation of additional contact surfaces "bear paws" to standard skid gear. Issued 2/17/71.	EA	12495	Atlantic Aviation Corporation Bell Helicopter Service Center P.O. Box 2307 South Hackensack, NJ 07608
206A; T.C. H2SW	SH892EA	Installation of Grimes Manufacturing Company supplemental strobe lights. Issued 11/26/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
206A; T.C. H2SW	SH1164SW	Installation of dual battery system using the ship's original battery and one installed by Bell Service Instructions and Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
206A; T.C. H2SW	SH1675SW	Heater system for de-fog air. Issued 6/15/73.	SW	68768	Rockwell International Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
206A, A-1, 206B; T.C. H2SW	SH1534SW	Remove standard BHC short skid shoes and install full length hard surface skid shoes. Issued 11/8/72.	SW	61650	Northrop Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
206A, B; T.C. H2SW	SA116WE	Installation of Nightsun SX-16C Searchlight. Amended 4/25/72.	WE	74500	Spectrolab Division of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
206A, B; T.C. H2SW	SH122WE	Installation of JB Systems, Inc. airconditioning system. Amended 12/10/73.	RM	45750	JB Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
206A, 206B; T.C. H2SW	SH124NW	Installation of Simplex 2700 and 2700A spray system tank assembly. Issued 9/9/74.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206A, 206B; T.C. H2SW	SH126WE	Installation of cartridge boost electrical starter system. Reissued 5/15/72.	WE	77492	Talley Industries, Inc. 4551 E. McKellips Road P.O. Box 849 Mesa, AZ 85201
206A, 206B; T.C. H2SW	SH138WE	Installation of Chadwick cargo rack C-72. Issued 1/6/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206A, 206B; T.C. H2SW	SH139WE	Installation of Chadwick C-22 auxiliary fuel system and C-30 ferry kit. Issued 1/7/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH148WE	Installation of Chadwick electronic weighing system C-45. Issued 5/26/72.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH158WE	Installation of Silver Star I anticollision light. Issued 7/9/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
206A, 206B; T.C. H2SW	SH209WE	Installation of type design change covering the SFENA ministab flight control system in various model combinations. Reissued 9/7/79.	WE	71450	SFENA Corporation 385 Reed Street Santa Clara, CA 95050
206A, 206B; T.C. H2SW	SA244NW	Installation of HE-206-010 bleed air heater system. Issued 3/2/76.	EA	35777	J.E. Flippo Rural Route 1, Pritchard Lane Westbank, B.C., Canada VOB-2A9
206A, 206B; T.C. H2SW	SH278NW	Installation of an electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems Inter'l 619 Riverside Drive Seattle, WA 98108
206A, 206B; T.C. H2SW	SH309AL	Installation of cargo basket. Amended 7/26/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH332AL	Installation of Airglas model L2700-206A skis. Amended 3/3/73.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH380AL	Installation of cargo baskets. Amended 8/7/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH474AL	Installation of Alaskan Sky-Craft Company, Inc. cargo step. Amended 7/20/73.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH515AL	Installation of ASC transporter cargo step. Amended 4/4/75.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH543NW	Installation of Bell 205 series cyclic stick grip. Issued 12/9/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH544NW	Installation of 28 volt DC power outlet in cabin. Issued 11/10/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH625NW	Installation of collective torque tube actuated hour meter switch and an engine-out audible warning system. Issued 6/28/78.	NW	85330	Weyerhaueser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH690NW	Installation of cyclic operated counter system. Issued 11/27/78.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH702NW	Installation of weighing system. Issued 1/23/79.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
206A, 206B; T.C. H2SW	SH759NW	Installation of an onboard weighing system. Issued 5/3/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
206A, 206B; T.C. H2SW	SH791NW	Installation of a model 50 spray system. Issued 6/26/79.	NW	66340	Rambling Rotors, Inc. Route 2, Box 244 La Grande, OR 97850
206A, 206B; T.C. 42SW	SH848NW	Installation of a model 4900 spray system. Issued 10/22/79.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206A, 206B; T.C. H2SW	SH1062SO	Installation of fuel tank filler extension (increased fuel capacity).	SO	78475	Thoroughbred Helicopter Service, Inc. Route 3, Paris Pike Lexington, KY 40511
206A, 206B, 206L; T.C. H2SW	SH1125EA	Installation of Aircraft Parts Corp. starter-generator, P/N 150SG111Q. Amended 11/27/78.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206A, 206B; T.C. H2SW	SH1134SO	Installation of one-piece entrance step. Issued 2/19/80.	CE	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri City Airport Blountville, TN 37617
206A, 206B; T.C. H2SW	SH1753SW	Collapsible table and bar in passenger compartment. Issued 10/25/73.	SW	36550	Foster-Edward Aircraft Company 304 Fair Oaks Boulevard Euless, TX 76039
206A, 206B; T.C. H2SW	SH1754SW	Foxtronics/Tramm BTI 600 nickel-cadmium battery temperature system (single battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1755SW	Foxtronics/Tramm BTI 600 nickel-cadmium battery temperature system (dual battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1759SW	Ni-Cad battery overtemperature warning system. Issued 11/6/73.	SW	22280	Chrysler Corporation Space Division P.O. Box 29200 New Orleans, LA 70189
206A, 206B; T.C. H2SW	SH2889SW	Fuel filler neck.	SW	32758	Edwards & Associates, Inc. 13611 Heartside Place Dallas, TX 75234
206A, 206B, 206B-1; T.C. H2SW	SH164WE	Installation of A500 battery temperature monitor system. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
206A, B; 206L; T.C. H2SW	SA86GL	Installation of Marathon CA1700 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Co., Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48083
206A, 206B; 206L; T.C. H2SW	SH184WE	Installation of turbine over-temperature warning system. Amended 4/4/77.	WE	60425	MRSC Incorporated 10959 San Diego Mission Road San Diego, CA 92108
206A, 206B, 206L, 206L-1; T.C. H2SW	SH227WE	Installation of baggage compartment extension. Issued 11/3/78.	WE	50275	Ronald Leibin/Steve Crowe 2761 Hollywood Way Burbank, CA 91505
206A, 206B; 206L; T.C. H2SW	SH736SO	Installation of SAFT type 1656 nickel-cadmium electrical storage battery. Amended 11/19/76.	EA	69800	SAFT America, Inc. P.O. Box 1886 711 Industrial Boulevard Valdosta, GA 31601
206A, 206B, 206L; T.C. H2SW	SH1148EA	Installation of a modified Lear-Siegler starter-generator, P/N 23032-010. Amended 6/1/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
206A, 206B, 206L, 206L-1; T.C. H2SW	SH200GL	Installation of NI-CAD, Inc. Model No. 62239 engine lubrication system scavenge filter. Amended 6/22/79.	GL	61546	NI-CAD, Incorporated 24800 U.S. 20 South Bend, IN 46628
206A, 206B, 206L, 206L-1; T.C. H2SW Normal Category	SH244WE	Installation of cyclic support cover, P/N 2COS6C Issued 10/9/79.	WE	50275	Stephen H. Crowe and Ronald A. Leibin 2761 Hollywood Way Burbank, CA 91505
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH247WE	Installation of Silver Instruments fueltron IG or IP digital fuel flow and totalizer system. Issued 9/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH252WE	Installation of SDI model CFS-1002, fuel flow indicating system. Issued 9/14/79	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH253WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 9/17/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206A, 206B, 206L-1; T.C. H2SW	SH198WE	Installation of tail rotor flood lights on the upper surfaces of horizontal stabilizers. Amended 6/28/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
206B; T.C. H2SW	SH5NE	Installation of revised instrument panel and installation of pressure operated gyro instrument back-up system. Issued 12/14/73.	NE	26550	Copters Unlimited, Inc. T.F. Green State Airport Warwick, RI 02886

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206B; T.C. H2SW	SH134GL	Install Allison 250-C20B engine. Issued 9/10/76.	GL	14212	Aztec Aviation, Inc. Grissom Airport Bedford, IN 47421
206B; T.C. H2SW	SH174WE	Installation of Nightsun SX-16C searchlight. Issued 11/22/74.	WE	74500	Spectrolab Division of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
206B; T.C. H2SW	SH237WE	Installation of a "HCS-206" helicopter computer system. Issued 5/23/79.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
206B; T.C. H2SW	SH446NW	Installation of Simplex 5000 spray kit. Amended 6/30/78.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206B; T.C. H2SW	SH515NW	Installation of Pacific Forest Research Center Mark II aerial ignition system. Issued 9/13/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig HArbor, WA 98335
206B; T.C. H2SW	SH830NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705
206B; T.C. H2SW	SH1030CE	Installation of battery temperature monitor and over temperature warning system. Issued May 1974.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Wichita, KS 67202
206B Jet Ranger II and III; T.C. H2SW	SH1503CE	Installation of Collins APS-841 automatic flight control system. Amended 2/15/80.	CE	24250	Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
206L; T.C. H2SW	SH506AL	Install Airglas Model L2700-206L skis. Issued 6/10/76.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
212; T.C. H4SW	SH17NW	Installation of Chadwick Electronic weighing system C-47. Issued 2/16/73.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
212; T.C. H4SW	SH171WE	Installation of A500 battery temperature monitor systems. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
212; T.C. H4SW	SH205WE	Installation of tail/rotor flood lights on upper surface of the horizontal stabilizers. Issued 10/20/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
212; T.C. H4SW	SH256WE	Installation of emergency exit window. Reissued 1/11/80.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
212; T.C. H4SW	SH400NW	Installation of modified left hand door. Issued 1/20/77.	NW	33900	Evergreen Helicopters P.O. Box 358 McMinnville, OR 97128
212; T.C. H4SW	SH449AL	Installation of Airglas model L8500A skis. Amended 6/10/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
212; T.C. H4SW	SH463NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
212; T.C. H4SW	SH467NW	Cargo release switch wired in series with spare switch on pilot's cyclic control grip. Issued 6/15/77.	NW	85330	Weyerhouser Company 28801 Airport Road Eugene, OR 97401
212; T.C. H4SW	SH942EA	Installation of Tramm BTI-600 battery temperature indicating system. Issued 12/26/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
212; T.C. H4SW	SH1281SW	Interior installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1284SW	Installation of Norton Company's radome and radar antenna brackets. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1286SW	Installation of Butler VAC/ADD area navigation system for VFR operation only. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
212; T.C. H4SW	SH1288SW	Installation of dual PC-17-400 Hertz static inverters. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn AVenue Burbank, CA 91505
212; T.C. H4SW	SH1289SW	Extension of power feeds to allow power distribution from the aft pedestal area. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1290SW	Installation of an extended instrument panel. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1332SW	Installation of weather radar equipment. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH2281SW	Environmental control unit. Issued 1/6/76.	SW	11890	Associated Air Center 7011 Lemmon Avenue Dallas, TX 75209
212; T.C. H4SW	SH2338SW	Modification for IFR type of operation. Issued 7/28/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220
212; T.C. H4SW	SH2466SW	AC inverter power system. Issued 5/24/77.	SW	11890	Associated Air Center, Inc. P.O. Box 20718 Love Field Dallas, TX 75220
212; T.C. H4SW	SH2746SW	Modification of four emergency exit panels. Issued 4/4/78.	SW	64300	Petroleum Helicopters, Inc. P.O. Box T Lafayette, LA 70502
212; T.C. H4SW	SH2892SW	Install 150 or 180 gallon auxiliary fuel tanks; standard utility seats modified; optional seats. Issued 12/21/78.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75222
214; T.C. H6SW	SH464NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems Inter'l. 619 Riverside Drive Seattle, WA 98108
214B, 214B-1; T.C. H6SW	SH2298SW	Interior arrangement and installation. Issued 3/2/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BELLANCA AIRCRAFT CORPORATION, DELAWARE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
14-9, 14-12, 14-13 Series; T.C. 716, 745, 773	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
14-12, 14-13 Series; T.C. 773, 745	SA4-527	Ceconite 101 covering of airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13 Series; T.C. 773	SA1-104	McCauley 1A170 propeller.	EA	73728	Thomas L.R. Solt, Jr. 410 Woodlawn Avenue Bethlehem, PA 18016
14-13 Series; T.C. 773	SA1-431	Rerouting of fuel lines and substitution of Bendix 476087 fuel pump for original hand-operated emergency pump.	EA	22785	H.L. Clark Ashdown Road Ballston Lake, NY 12019
14-13 Series; T.C. 773	SA1-551	Fuselage and fin covered with metal skin.	EA	72100	Skycraft Design, Inc. P.O. Box 67 Mercer County Airport West Trenton, NJ 08628
14-13 Series; T.C. 773	SA3-48	Koppers F-200 hub with 00-74B blade.	CE	33242	Elliott Flying Service, Inc. P.O. Box 418 Davenport, IA 52802
14-13 Series; T.C. 773	SA4-169	Fiberglas cloth with resin over original fabric.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
14-13 Series; T.C. 773	SA4-302	BH-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
14-13 Series; T.C. 773	SA4-468	Flaps recovered.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13 Series; T.C. 773	SA4-604	Hydraulic landing gear retracting system.	WE	48230	Kidwell Aviation Company Municipal Airport Torrance, CA 90510
14-13 Series; T.C. 773	SA4-840	Fabric replaced with glass cloth on wings, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
14-13 Series; T.C. 773	SA4-1203	Ceconite 103 covering of plywood portions of the aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13 Series; T.C. 773	SA4-1421	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-13 Series; T.C. 773	SA29EA	Sensenich M74DR fixed pitch metal propeller (Pitch 60) on aircraft equipped with Franklin 6A4-165-B3 engine.	EA	73728	Thomas L.R. Solt, Jr. 410 Woodlawn Avenue Bethlehem, PA 18016
14-13 Series; T.C. 773	SA599WE	Franklin engine 6A-335-B, McCauley propeller 2A31C21/84S-8 with Woodward governor 201453, and Firestone DFA-180 wheel assembly and CFA-252 brake assembly or equivalent.	WE	28854	Debs Aircraft and Engine Company 1065 Arroyo Street San Fernando, CA 91340
14-13 Series; T.C. 773	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
14-13 Series; T.C. 773	SA846SW	Wing root fairings.	SW	02460	Aero Plastic Enterprises, Inc. 1315 Keller Lane Seguin, TX 78155
14-13 Series; T.C. 773	SA995SO	Installation of external reservoir brake system. Issued 5/27/76.	SO	63335	F.W. Patterson, Jr. 2153 Nancy Circle Smyrna, GA 30080
14-13 Series; T.C. 773	SA1008WE	Poly-Fiber covering of elevators, rudder and horizontal stabilizers. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502

BELLANCA AIRCRAFT CORP., DE 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
14-13 Series; T.C. 773	SA1029WE	McCauley 1A170/DM7654 propeller.	NW	56550	Kenneth Eddy Mathews Route 3, Box 500 Poulsbo, WA 98370
14-13 Series; T.C. 773	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
14-13 Series; T.C. 773	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm).	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
14-13, -13-2, -3, -3W; T.C. A-773	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
14-13, -13-2, -3, -3W; T.C. A-773	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
14-13, -13-2, -3, -3W; T.C. A-773	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, or Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetor. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
14-13, -13-2, -13-3, -13-3W; T.C. A-773	SA797WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 Wheel Assemblies in lieu of Firestone wheel assy No. CFA180. Firestone CFA252 brakes or Bodell BMI252 brakes are required with this installation. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
14-13, -13-2, -3, -3W; T.C. A-773	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
14-13, -13-2, -3, -3W; T.C. A-773	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
14-13, -2, -3, -3W; 14-12F-3; T.C. 773, 745	SA1351WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
14-13, 14-13-2, 14-13-3, 14-13-3W, 14-12F-3; T.C. 773, 745	SA2666WE	Ceconite 102 material covering complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BELLANCA AIRCRAFT CORPORATION, MINNESOTA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
7 Series; T.C. 759	SA1-319	Continental C85-12 engine.	SO	17068	Columbus D. Bradley 325 Pasadena Drive Lexington, KY 40507
7 Series; T.C. 759	SA3-6	Installation of Pee-Kay Model 1500 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-214	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-303	Reinforced plastic instrument panel (exact duplicate of 5-150).	RM	28500	Dakota Aviation Company P.O. Box 18 Huron, SD 57350
7 Series; T.C. 759	SA3-322	Door modified to seaplane door.	GL	48900	E.O. Kunde Personal Air Service Mahtomedi, MN 55115
7 Series; T.C. 759	SA3-361	C-2200 main ski and CTF-2200 tail wheel ski or AWT 2500 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-362	C-2200 main ski and CTF-2200 tail wheel ski or AWT tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-368	A2000A main wheel-replacement ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-432	Install two auxiliary fins, one ventral fin and Pee-Kay Model 1800 floats. (Reissued 11/13/70.)	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-496	Install two auxiliary fins, one ventral fin and Pee-Kay Model 1800 floats. (Reissued 11/13/70.)	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-515	Skis L-1500A on main gear and L-1200A on nose gear.	AL	08125	Airglas Engineering Company P.O. Box 1254 Anchorage, AK 99502
7 Series; T.C. 759	SA3-523	Install four auxiliary and one ventral fin and Pee-Kay Model 1800 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-628	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA4-97	Auxiliary five-gallon fuel tank in wing.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
7 Series; T.C. 759	SA4-276	BH-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
7 Series; T.C. 759	SA4-338	Addition of exhaust stacks with venturi, pump, control valve, and tank for insect control work.	WE	71910	Vern Skaggs 2301 Pacific Coast Highway Lomita, CA 90717
7 Series; T.C. 759	SA4-359	Glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
7 Series; T.C. 759	SA4-699	R003-232-72T propeller with Continental C-90-12 engine.	WE	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7 Series; T.C. 759	SA4-836	Ceconite 101 covering of entire airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
7 Series; T.C. 759	SA4-1009	Eonite covering on complete airplane.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
7 Series; T.C. 759	SA4-1636	Tri-cycle landing gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
7 Series; T.C. 759	SA5-49	Tires and tubes 25x11x4.	AL	21540	Chapman Air Taxi P.O. Box 829 Palmer, AK 99645
7 Series; T.C. 759	SA5-68	Airglass Engineering L1500A main and L1200A nose skis.	AL	11386	Louis M. Applegate P.O. Box 1047 Fairbanks, AK 99701
7 Series; T.C. 759	SA6AL	L-1500A, A1650A, or L-2000A main skis and L-1200A nose ski.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 1254 Anchorage, AK 99502
7 Series; T.C. 759	SA33CE	Removal of door.	GL	46778	Darryl F. Johnson Route 5 Mount Pleasant, MI 48858
7 Series; T.C. 759	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743
7 Series; T.C. 759	SA216SW	Conversion of aircraft to tri-cycle gear configuration.	SW	47610	K.C. Aircraft, Inc. P.O. Box 4248 Lucian Field Shreveport, LA 71102
7 Series; T.C. 759	SA217AL	Install L-1650A or L-2000A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7 Series; T.C. 759	SA220SO	Tow bar, releast mechanism, and safety tow link.	SO	37092	Gasser Banners, Inc. P.O. Box 3502 Metropolitan Airport Nashville, TN 37217
7 Series; T.C. 759	SA232SO	Change Model 7AC powerplant from Continental C65-8 to C85-12.	SO	74928	Star Aircraft P.O. Box 411 Hialeah, FL 33010
7 Series; T.C. 759	SA274WE	Fuel system modification.	WE	55100	Marks Aviation Torrance Airport Torrance, CA 90510
7 Series; T.C. 759	SA286EA	Edo 60-1320 floats.	EA	61622	North American Flying Service, Inc. LIttle Ferry, NJ 07643
7 Series; T.C. 759	SA513AL	Installation of Hartzell model HC-C2YL-1BF/F8468A-8R constant speed propeller. Issued 2/11/74.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
7 Series; T.C. 759	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
7AC; T.C. 759	SA2-227	Windshield manufactured in accordance with Luminous Plastics, Inc. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
7AC & 7AC CONV; T.C. A-759	SA3-372	Installation of Lycoming O-235-C or Lycoming O-235-C1 engine and appropriate propeller. Reissued and amended 11/27/70.	RM	84393	C.L. Wagner Wagner Aerial Service Clark, SD 57225
7 Series; 11AC; T.C. 759, 761	SA3-435	Continental A-75-8 or A-75-8F carburetor type engine.	GL	62029	John T. Ownes 2707 East Towers Drive, Apt. 203 Cincinnati, OH 45238
7 Series; 11AC; T.C. 759, 761	SA4-369	Lift strut assemblies.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7 Series, 11AC, 11BC, S11AC; T.C. 759, 761	SA3-215	Laminated plastic and fiberglass nose cowl D-576P.	RM	28500	Dakota Aviation Company P.O. Box 18 Huron, SD 57350
7 Series, 11CC, S11CC; T.C. 759, 796	SA3-424	CTF-2200 tail ski on airplanes equipped with Scott 3000 tail wheel.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series, 11AC, S11AC, 11BC; T.C. 759, 761	SA4-444	Carburetor and cabin hot air muff with replaceable air inlet and outlet.	WE	66600	Peter H. Raymen 5829 Deborah Street Long Beach, CA 90801
7 Series, 11AC, S11AC, 11BC; T.C. 759, 761	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
7 Series, 11 Series; T.C. A-759, A-761, A-796	SA2710WE	Installation of carburetor heat box bearings. Issued 6/15/73.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
(Aeronca Champion) 7AC, S7AC, 7BCM (Army L-16A), 7CCM (Army L-16B), S7CCM, 7DC, S7DC, 7EC, S7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCB, 7GCBA, 7HC, 7JC, 7KC, 7GCAA, 7GCBC, (Aeronca Trytek) 11AC, S11AC, 11BC, S11BC, 11CC, S11CC, 14-19 Series; T.C. 759, 761, 796, 1A3	SA2666WE	Ceconite 102 material covering: Models listed - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
7AC, S7AC, 7BCM, 7CCM, S7CCM, 7DC, S7DC, 7EC, S7EC, 7FC, 7GC, 7ACA, 7ECA, 7GCA, 7GCAA, 7KC, 7KCAB, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 11AC, S11AC, 11BC, S11BC; T.C. 759, 761	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
7AC, S7AC, 7BCM, 7CCM, S7CCM, 7EC, S7EC, 11AC, S11AC, 11BC, S11BC; T.C. A759, A761	SA19SO	Installation of left and/or right auxiliary fuel tank(s). Reissued 11/8/77.	GL	02250	Aero Fabricators, Inc. P.O. Box 181 1216 North Road Lyons, WI 53148
7AC, S7AC, 7EC, 7FC, 7BCM, 7CCM, S7CCM, 7DC, 7GCBA, S7DC, 7JC, 11AC, S11AC, 11BC, S11BC, 11CC, S11CC; T.C. 759, 761, 796	SA150SO	Surface fabric attachment clip. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
7; 11, S11; 11CC, S11CC; 14-19, 17-30, -31; T.C. A-759, A-761, A-796, 1A3	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
7 Series; 14-19; T.C. A-759, 1A3	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
7 Series; 14-19, 14-19-2, 14-19-3; T.C. 759, 1A3	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
7 Series; 14-19, 14-19-2, 14-19-3; T.C. 759, 1A3	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
7AC, 7BCM, 7CCM, 7DC; T.C. A-759	SA2309WE	Installation of Madras Air Service Part No. 104 wing tips. Amended 10/26/71.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
7AC, 7BCM, 7CCM, 7DC, S7AC, S7BC, S7CC, S7DC, 11AC, S11AC, 11BC; T.C. 759, 761	SA89AL	Installation of auxiliary fuel tanks. Amended 2/7/75	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
7AC, 7BCM, 7CCM, 7DC, 7EC, 7ECA, 7GC, 7GCA, 7GCB, 7GCBC, 7KCAB, 77GAA w/ oleo; T.C. A-759	SA754CE	Install Aero Model M1500, M1800 or M2000 main skis. Amended 1/13/72.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
7AC, BC, BCM, DC, EC, ECA, FC, GC, GCA, GCB, GCBA, HC, JC, KC, S7AC, S7EC, S7CCM, S7DC, 7GCAA, 7GCBC, 7CCM; 11AC, S11AC, 11BC, S11BC, 11CC, S11CC; 14-19, -2; 8GCBC; T.C. A-759, A-761, A-796, 1A3, A21CE	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
7AC, BC, BCM, DC, EC, ECA, FC, GC, GCA, GCB, GCBA, HC, JC, KC, S7AC, S7EC, S7CCM, S7DC, 7GCAA, 7GCBC, 7CCM; 11AC, S11AC, 11BC, S11BC, 11CC, S11CC; 14-19, -2; T.C. A-759, A-761, A-796, 1A3	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
7AC, S7AC, 7BCM, 7CCM, S7CCM, 7DC, S7DC, 7EC, S7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCB, 7GCBA, 7HC, 7JC, 7KC, 7GCAA, 7GGBC; 11AC, S11AC, 11BC, S11BC; 11CC, S11CC; 14-19 Series; T.C. 759, 761, 796, 1A3	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCAA, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 7KCAB; 14-19-3A, 17-30, -30A, -31A, -31ATC; T.C. A-759, 1A3	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417
7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCAA, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 7KCAB; 14-19-3A, 17-30, 17-30A, 17-31A; 17-31ATC; T.C. A-759, 1A3	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A450, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417
7ECA; T.C. 759	SA334CE	Installation of Pee-Kay Model 1800 or B1800 (TSO-C27-2) seaplane floats and two auxiliary fins. Amended 8/17/73.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7ECA (Seaplane); T.C. 759	SA483AL	Installation of McCauley 1B90-LCM-7534 propeller. Issued 7/17/72.	AL	42132	Martin (NMI) Hettinga 1138 I Street Anchorage, AK 99501
7 ECA; T.C. A-759	SA745EA	Installation of Edo Model 88-1650A floats. Amended 1/13/78.	GL	32625	Edo-Aire Seaplane Div. (Edo Corp.) c/o Air Aids of Dayton 3800 Clearview Drive Dayton, OH 45439
7ECA, 7KCA, 8KCAB; T.C. A759, A21CE	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Company airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
7ECA, 7KCAB land only; T.C. 759	SA608AL	Install leading edge cuff. Amended 8/31/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
7ECA, 7GCBC; T.C. A-759	SA261AL	Installation of Airglas Model L2000 and I-1650 wheel replacement skis. Amended 11/22/68.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7ECA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA442AL	Installation of 8.50x6 4- or 6-ply rated Goodyear or UniRoyal tires. Amended 11/7/73.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
7ECA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA3019WE	Installation of 8.50 x 6.00 4-ply rated, Type III aircraft tires. Issued 4/30/75.	WE	39580	Guardian Flying Service, Inc. 500 E. Highway 41 Las Vegas, NV 89119
7ECA, 7GCAA, 7GCBC, 7KCAB, 8KCAB; T.C. 759, A21CE	SA693CE	Install AC induction air filter type AAF-106. Amended 3/1/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
7ECA, 7GCAA, 7KCAB, 7GCBC w/ landing gear; T.C. A-759	SA755CE	Install Model M1500, M1800, or M2000 main skis. Amended 12/9/71.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
7FC; T.C. A-759	SA374GL	Remove tri-cycle landing gear and install main landing gear and tail wheel. Issued 12/16/79.	GL	48244	King Aero Services, Inc. 7170 East Main Street Reynoldsburg, OH 43068

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
7FC, 11AC; T.C. 759	SA1008WE	Installation of Poly-Fiber covering material (complete aircraft). Amended 8/21/79.	WE	75250	Stits Aircraft Coatings P.O. Box 3084 43rd South Fort Drive Riverside, CA 92519
7GC, 7GCB, 7GCBC, 7HC; T.C. 759	SA18CE	Installation of Pee-Kay Model 1800 or B1800 (TSO-C27-2) seaplane floats. Amended 8/17/73.	EA	29998	Pee-Kay Devore Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7GC, KC, GCB, GCA, GCAA, GCBC: T.C. 759	SA216AL	Install L-2500A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCA (landplane), 7GCB, 7GCBC (land and float plane); T.C. A-759	SA283AL	Installation of Hartzell HC 82XL-1, -2, or -6 propeller hub with 7636D-4 blades or HC-C2YL-1B hub with 7663-4 blades and appropriate Woodward governor. Amended 7/22/69.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
7GCA, 7GCB, 7KC, 7GCBA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
7GCAA, 7GCBC, 7KCAB; T.C. A-759	SA33GL	Installation of EDO Model 88A-1650 floats. Reissued 6/22/76.	GL	03480	Air-Ads-of-Dayton with Edo-Aire Seaplane Division 3800 Clearview Drive Dayton, OH 45439
7GCAA, 7GCBC, 7ECAB; T.C. A-759	SA1536WE	Installation of larger rudder. Reissued 6/5/69.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7GCB; T.C. 759	SA323AL	Installation of McCauley 1A175-GM8042 propeller.	AL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645
7GCBC; T.C. 759	SA266AL	Installation of L-2500 skis. Amended 6/21/68.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCBC; T.C. 759	SA520AL	Installation of leading edge cuff stall fences, tip fences. Amended 2/2/77.	AL	27250	Crosswinds, Inc. 2301-1/2 Merrill Field Drive Anchorage, AK 99507
7KCAB; T.C. A-759	SA25RM	Installation of Christen Model 801 Inverted Oil System. Issued 3/28/74.	RM	49369	Lloyd Land Star Route, Box 65A Hudson, CO 80642
8GCBC; T.C. A21CE	SA72GL	Installation of wheel replacement ski models M2000 and M3000. Issued 3/12/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
8GCBC; T.C. A21CE	SA530AL	Installation of Hartzell HC-C2YK-1BF/F7666A-0. Issued 10/21/74.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
8GCBC; T.C. A21CE	SA666AL	Installation of Fluidyne C3000A skis. Issued 7/17/79.	AL	35800	Flirite, Inc. P.O. Box 297 Kodiak, AK 99615
8GCBC; T.C. A21CE	SA741NW	Installation of EDO 689-2130 floats. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA742NW	Installation of Hartzell HC-C2YR-1BF/F7666A-O propeller on a Lycoming O-360-C1E engine. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA743NW	Installation of Bellanca 72 gallon fuel system. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA1001EA	Installation of Pee-Kay Model 2300 (TSO-C27-2) seaplane floats. Issued 4/11/75.	EA	29998	Pee-Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
11AC; T.C. 761	SA4-99	Fiberglass cloth with resin over muslin applied.	WE	46783	R.W. Johnson Route 2, Box 571-B Ojai, CA 93023
11AC; T.C. 761	SA4-789	McCauley 1B90-CM/7045 propeller on Continental A-65-8 engine.	NW	68536	Paul H. Robinson 604 S. 136 Street Seattle, WA 98101
11AC; T.C. 761	SA345CE	Remove right door.	CE	35650	Flanagan Aircraft 20224 R.D. Mize Road Independence, MO 64050

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
11AC, S11AC, 11BC; T.C. 761	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
11AC, S11AC, 11BC; T.C. 761	SA4-1276	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
11AC, S11AC, 11BC; T.C. 761	SA19SO	Left and/or right auxiliary fuel tanks.	SO	74928	Star Aircraft Company P.O. Box 411 Hialeah, FL 33010
11AC, S11AC, 11BC, S11BC, 11CC, S11CC; T.C. A-761, A-796	SA57RM	Installation of Lycoming O-235-C1 or O-235-C2C engine. Issued 6/19/75.	RM	84393	Colman L. Wagner 401 1st Street East Clark, SD 57225
11AC, 11BC; T.C. 761	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
11AC, 11BC, 11CC; T.C. 761, 796	SA217AL	Install L-1650A or L-2000A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
11AC, 11BC, 11CC; T.C. 761, 796	SA535AL	Installation of wing auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
11BC; T.C. 761	SA3-7	Installation of Pee-Kay Model 1500 floats with Edo struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC; T.C. 796	SA3-115	Model 3000 main ski and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
11CC; T.C. 796	SA3-670	Install Pee-Kay Model 1500 floats with Edo struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC; T.C. 796	SA69SO	Continental C85-12F Series engine less starter and generator.	SO	49720	C.W. Lasher 14100 NW. 62 Court Miami, FL 33012
11CC; T.C. 796	SA262CE	Manufacture parts and install 12-30A electrical system. (Requires alteration of engine per STC SE3CE.)	GL	67160	Kenneth L. Repke 7788 Auburn Detroit, MI 48233
11CC, S11CC; T.C. 796	SA4-1270	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13, 14-19, 14-19-2, -19-3, -19-3A, 17-30, -31, -31A, -31TC, -31ATC; T.C. 1A3, 773	SA846SW	Wing root fairings. Reissued 11/27/78.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
14-19 Series; T.C. 1A3	SA1-551	Fuselage and fin covered with metal skin.	EA	72100	Skycraft Design, Inc. Mercer County Airport West Trenton, NJ 08628
14-19 Series; T.C. 1A3	SA4-867	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series; T.C. 1A3	SA4-883	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series; T.C. 1A3	SA4-909	Autopilot. Reissued October 1973.	WE	17492	Brittain Industries, Inc. 12027 S. Prairie Avenue Hawthorne, CA 90250
14-19 Series; T.C. 1A3	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
14-19 Series; T.C. 1A3	SA4-1127	Ceconite 101 covering of entire aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-19 Series; T.C. 1A3	SA4-1269	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
14-19 Series; T.C. 1A3	SA4-1283	Ceconite 103 covering of plywood portions of the aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
14-19 Series; T.C. 1A3	SA486SW	Automatic pilot AK143, AK143E and AK143E-3.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
14-19 Series; T.C. 1A3	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court, P.O. Box 175B San Leandro, CA 94577
14-19 Series; T.C. 1A3	SA645SW	AK125 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19, 14-19-2; T.C. 1A3	SA294GL	Install Cleveland wheel 40-97A and brake 30-63A. Issued 3/22/79.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19, -A-2, -3, -3A, 17-30, -31, -31TC; T.C. 1A3	SA666NW	Installation of TEflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
14-19-2; T.C. 1A3	SA203GL	Installation of McCauley 2A34C66-N/S-90AT-12 propeller manufacturer's installation with instruction. Issued 12/8/77.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-2; T.C. 1A3	SA798WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 Wheel Assemblies in lieu of Firestone DFA180 wheel assembly. Firestone CFA252 brakes or Bodell BMI252 brakes required with this installation. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
14-19-3, 14-19-3A; T.C. 1A3	SA292GL	Install Cleveland wheel 40-75E and brake 30-52M on main gear. Issued 1/31/79.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-3, 14-19-3A, 17-30, -30A, -31, -31A, -31TC, -31ATC; T.C. 1A3, A18CE	SA847SW	Main landing wheel doors. Reissued 11/27/78.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
14-19-3, 14-19-3A; T.C. 1A3	SA874SW	Hartzell/Wren Beta System reverse pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
14-19-3A; T.C. 1A3	SA108GL	Installation of Continental IO-520D engine and McCauley D2A34C58/90AT-10 propeller. Issued 2/11/76.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-3A; T.C. 1A3	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STC - SA645SW.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19-3A, 17-30; T.C. 1A3	SA981SW	Manual Electric Trim AK276.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19-3A, 17-30, -31, -31TC; T.C. 1A3	SA1196SW	Mitchell automatic flight system model AK309 consisting of Century I, automatic aileron stabilizer with omni tracker. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30; T.C. 1A3	SA845SW	Nose gear doors. Reissued 1/24/79.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
17-30; T.C. 1A3	SA869SW	Mitchell automatic flight system AK233 consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio coupler, glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30; T.C. 1A3	SA3780WE	Installation of Continental IO-502-K engine, Hartzell HC-C3YF-1B/8468A-8R propellers, and associated installation components. Issued 11/29/78.	WE	08347	Air Repair P.O. Box 813 Santa Paula, CA 93060
17-30, -30A, -31, -31A; -31ATC; T.C. A18CE	SA903SO	Reposition of fuel pump. Issued 7/30/76.	SO	86295	Keith Wilson Aircraft, Inc. 2787 North Second Street Memphis, TN 38127

BELLANCA AIRCRAFT CORP., MN 8

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
17-30A; T.C. A18CE	SA1344CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 6103
17-30A; T.C. A18CE	SA3688WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
17-30A, -31A; T.C. A18CE	SA1118SW	Manual electric trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, -31, -31ATC; T.C. A18CE	SA1195SW	Mitchell automatic flight system AS309 consisting of Century I, automatic aileron stabilizer with omni tracker. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA574SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric pitch trim and optional flight director indicator DH-841. Issued 2/1/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1235SW	Automatic flight system AK215, consisting of Century II autopilot with optional automatic aileron stabilizer and radio coupler. Issued 12/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1236SW	Automatic flight system AK233, consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio, and glide couplers. Issued 12/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1257CE	Installation of the King KFC-200 2-axis, flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or stand alone electric trim. Amended 10/6/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1811SW	Mitchell automatic flight system AK466 and AK466FD consisting of Century IV autopilot and Century IV flight director with electronic command/automatic pitch trim. Issued 2/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1812SW	Mitchell automatic flight system AK465 consisting of Century III autopilot with optional electronic command/automatic pitch trim, radio coupler, and glide slope coupler. Issued 2/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3059SW-D	Mitchell AK466 and AK466FD consisting of Century IV autopilot and Century IV flight director with electronic command/automatic pitch trim. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3060SW-D	Mitchell AK465 consisting of Century III autopilot with optional electronic command/automatic pitch trim, optional radio coupler, and glide slope coupler. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3061SW-D	Mitchell AK495 consisting of Century I autopilot with optional omni tracker. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3071SW-D	Mitchell automatic flight system AK546 consisting of Century IIB autopilot with optional radio coupler. Issued 9/5/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3083SW-D	Mitchell command electric trim AK545. Issued 12/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, -31A, -31ATC; T.C. A18CE	SA3267WE	Modification of aileron control system by addition of aileron centering spring and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 10/1/76.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
BOEING COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B-17F, B-17G; L.T.C. 1	SA4-1088	Cargo door.	WE	34204	Fairchild Aerial Survey 2945 N. Hollywood Way Burbank, CA 91500
B-17F, B-17G; L.T.C. 1	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
B-17F, B-17G; L.T.C. 1	SA4-1520	Ceconite 101 covering of all fabric covered surfaces.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
B-17F, B-17G; L.T.C. -1	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Army) B-17F, B-17G, 377; LTC 1, T.C. 812	SA2666WE	Ceconite 102 material covering of: B-17F, B-17G - all fabric covered surfaces; 377 - ailerons, elevators and rudder. 4/19/78	WE	20250	Ceconite. Inc. 4677 Worth Street Los Angeles, CA 90063
377; T.C. 812	SA1-248	Radio equipment.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
377; T.C. 812	SA1-250	Incorporation of STC SA4-175 without weight increase.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
377; T.C. 812	SA1-323	Galley service door to emergency exit door.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
377; T.C. 812	SA3-34	Propeller reverse control circuit revision.	GL	61700	Northwest Airlines Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
377; T.C. 812	SA3-73	Revise Minneapolis-Honeywell turbo-supercharger control system.	GL	61700	Northwest Airlines Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
377; T.C. 812	SA4-175	Hamilton Standard 34E60/7015-2 propellers and increase in take-off and landing weights.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-384	Deterjet DJ-1015E valve between governor and nose cap mounting pad.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-416	Deterjet DJ-1015E valve between governor and nose case mounting pad.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-429	Full flow oil filter 31024A with element 1A0099.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
377; T.C. 812	SA4-709	Passenger cabin interior and weight reduction modification.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-717	Removal of No. 3 generator system and one refrigeration system.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-842	Conversion of British Overseas Airways Corp. Boeing 377, and communications and navigation equipment changes.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
377; T.C. 812	SA29SO	Cargo loading door in upper forward section of main cabin and relocation of lower forward cargo door.	SO	47100	Opal E. Jones 274 Palm Avenue Miami, FL 33101
377; T.C. 812	SA473WE	Front upper spar cap and rear upper and lower spar caps reinforcement.	SO	47100	Opal E. Jones 274 Palm Avenue Miami, FL 33101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
377; T.C. 812	SA501WE	Ceconite 101 covering of ailerons, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
377; 0t.c. 812	SA875WE	Cargo door added between fuselage stations 678 and 822 (left side aft of wing).	SO	47100	Opal E. Jones Box 48-625, Int'l Airport Miami, FL 33159
377; T.C. 812	SA916WE	Removal of galley door on right-hand side of fuselage between stations 1090 and 1120. Stringers extended across existing opening with additional "skin" to cover opening.	SO	47100	Opal E. Jones Box 48-625, Int'l Airport Miami, FL 33159
707 Series; T.C. 4A21	SA400EA	Installation and activation of Litton Model 502 Low Range Altimeter System. Activation of HZ6B Altitude Bars. Installed individually or concurrently.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21	SA420EA-D	Relocate the L.A.S.I. Flight Data Recorder to the aft fuselage area at Station 1462. Install new auxiliary pitot tube and static ports for the flight recorder.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21	SA494CE	Installation of dual doppler navigation systems with autopilot tie-in.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21	SA507CE	Installation of LAS 109CR flight recorder - aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21	SA507EA-D	Install lounge and beverage bar. Install electrical wiring. Install bar and galley structural tiedowns. Install buffets.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21	SA1867SW	Portable solid oxygen system for flight attendant/passenger first-aid use. Issued 4/15/74.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
707 Series; T.C. 4A21, 4A26	SA1-345	Canadian Marconi CMA-621 doppler system.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA1-473	ADF system modification. Reissued 3/20/74.	WE	52070	Lockheed Aircraft Service Company P.O. Box 33 Ontario, CA 91761
707 Series; T.C. 4A21, 4A26	SA1-529	Crimsco cargo container 600301.	EA	62300	Pan American World Airways, Inc. 135 E. 42 Street New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA1-530	Instrument failure and warning system.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA1-651	Instrument warning system - Gables Engineering amplifier G-1010A, annuciator panels G-1080, G-1081 and G1052 warning sounder.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA3-478	Pilot's and copilot's KIFIS computers modified to make them interchangeable with each other and with the computers used on 707-331 aircraft.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA3-572	Dual Bendix DRA-12 doppler radars and dual Bendix CPA-24 computers.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA4-690	Removable flight cradle assemblies on aft side of bulkheads.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
707 Series; T.C. 4A21, 4A26	SA4-1284	Wheel 150741-5, brake assemblies 151924-2, -3, -4, -5, or -6, and hydraulic adjuster 151826 or -2.	GL	15500	Bendix Aviation Corporation Bendix Products Division 401 N. Bendix Drive South Bend, IN 46600
707 Series; T.C. 4A21, 4A26	SA4-1418	Forward lounge.	WE	07500	AiResearch Aviation Service 6201 W. Imperial HIghway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707 Series; T.C. 4A21, 4A26	SA35EA	Brown-Line 21105-52 stretcher kit in the passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 E. 42 Street New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA45SO	LIfe rafts M6861-100. Amended 5/8/67.	SO	62300	Pan American World Airways, Inc. Pan American Building Miami, FL 33159
707 Series; T.C. 4A21, 4A26	SA48EA	Triple tray carrier stowage unit (auxiliary galley) in passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 E. 42 Street New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA52SO	Life rafts 6924-100.	SO	62300	Pan American World Airways, Inc. Pan American Building Miami, FL 33159
707 Series; T.C. 4A21, 4A26	SA76CE	Automatic engine power control system integrated with Safe Flight Corp. speed control approach/take-off system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA90EA	PB-20 autopilot modification.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA91EA	PB-20 autopilot modification.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA101CE	Doppler radar navigation system modification and installation of compass test receptacles.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA102CE	Coupler, Bendix DRA-12 doppler radar with CPA-24 computer to Bendix PB-20D automatic pilot.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA126EA	Unifreight Mark V Model A cargo handling system.	NE	10225	American Machine & Foundry Co. 737 Canal Street Stamford, CT 06904
707 Series; T.C. 4A21, 4A26	SA137EA	Unifreight Mark V Model B cargo handling system. (Original approval issued to American Machine & Foundry Co.)	NW	16876	The Boeing Company Renton, WA 98055
707 Series; T.C. 4A21, 4A26	SA138CE	Inflight maintenance and performance recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA146SO	Modified structure of aircraft to provide for inertial navigation system. Amended 6/19/67.	SO	62300	Pan American World Airways, Inc. Pan American Building Miami, FL 33159
707 Series; T.C. 4A21, 4A26	SA166EA	Unifreight Mark V Model C cargo handling system. (Original approval issued to American Machine & Foundry Co.)	NW	16876	The Boeing Company Renton, WA 98055
707 Series; T.C. 4A21, 4A26	SA195SO	Structural provisions to accommodate Litton navigation system.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707 Series; T.C. 4A21, 4A26	SA195CE	Autothrust system.	CE	79100	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA196CE	Autopilot modified for variable angle intercept and control panel for variable angle capture.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA198CE	Dual low range radio altimeter system provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA202CE	Modification of autopilot amplifiers and control panel to provide a variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA233CE	Coupler on Bendix DRA-12 doppler radar to Bendix PB-20D autopilot.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA237CE	Autopilot variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707 Series; T.C. 4A21, 4A26	SA242CE	Coupler on Bendix DRA-12 doppler radar with CPA-24 computer to Bendix PB-20E automatic pilot.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA247CE	Autopilot variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA248CE	Autopilot variable angle intercept. Amended 5/24/67.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA264CE	Second flight director system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA273CE	Second flight director system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA274CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA290CE	Installation of a single auto throttle system. Amended 2/20/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA290EA	Television-audio passenger entertainment system.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA297CE	Fairchild cockpit voice recorder recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA299CE	1-70071 auto thrust servo assembly provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA304CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA305CE	Ten channel audio system provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA309EA	50-ampere transformer-rectifier.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA313CE	Ten channel audio system provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA317SW	Magnetic shaft seal on input and output shafts of Sundstrand constant-speed-drives 40-AD-14, 40-AD-04, 40-AD-12 and 49-AD-06.	NE	54250	Magnetic Seal Corporation 166 Bay Spring Avenue West Barrington, RI 02890
707 Series; T.C. 4A21, 4A26	SA342CE	Autopilot variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA343CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA349EA	Oxygen system. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
707 Series; T.C. 4A21, 4A26	SA364EA	Pallet ID-650-4.	SO	44598	Irving Air Chute Company, Inc. 1315 Versailles Road Lexington, KY 40507
707 Series; T.C. 4A21, 4A26	SA365CE	Ten channel audio system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA366CE	Fairchild cockpit voice recorder system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA375CE	Autopilot amplifiers modified to incorporate variable angle intercept feature. Amended 5/24/67.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707 Series; T.C. 4A21, 4A26	SA376EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA376CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA378EA	Dual Sperry SGN-10-2 inertial navigation systems.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA379EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA381CE	Fairchild cockpit voice recorder equipment. Amended 4/27/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA389CE	Eclipse-Pioneer 15470, 15492 and 18729 autopilot amplifier.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA390CE	Eclipse-Pioneer 18729 autopilot amplifier.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA402EA	Single pressure operated check valve in hydraulic lines.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA404EA	Extended over water operation.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA406EA	19-man configuration.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA425CE	Installation of an auto thrust system. Amended 1/31/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA428CE	Installation of a single SCAT system. Amended 4/21/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA429CE	Installation of an auto thrust system. Amended 4/21/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA430CE	Passenger motion picture and tape player equipment.	EA	44000	InFlight Motion Pictures, Inc. 10 Rockefeller Plaza New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA435CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA436CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA437CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA439EA	Inertial navigation system.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA443EA	Litton 502 low range altimeter system.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA454EA	Crew galley. Amended 5/2/67.	EA	67030	REF Dynamics Corporation 393 Jericho Turnpike Mineola, NY 11501
707 Series; T.C. 4A21, 4A26	SA467CE	Safe Flight Corp. auto power servo kit K-102.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA726WE	Revise interior configurations.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707 Series; T.C. 4A21, 4A26	SA757WE	Three-class passenger interior.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA784CE	Installation of Bendix standby horizon indicator. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA847WE	Replace two rows of economy class seats with two rows of coach seats.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA972WE	Install one additional row of tourist triple class seats and remove one row of first class seats (without lounge).	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1057WE	Interior modification.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1110WE	Seating arrangement revised.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1151WE	Dual Collins AL-101 or dual Litton 502 low range radio altimeter. Amended 7/22/66.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1152WE	Stowage compartment in main deck cargo compartment.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
707 Series; T.C. 4A21, 4A26	SA1176WE	Interior arrangements.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
707 Series; T.C. 4A21, 4A26	SA1217WE	Cockpit voice recorder system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1224WE	Dual FD-109 flight director systems, dual low range radio altimeters, wiring provision, DME and navigation switching.	SW	24252	Collins Radio Company Avionics Systems Center P.O. Box 98 Addison, TX 75001
707 Series; T.C. 4A21, 4A26	SA1229WE	United Data Control V557 cockpit voice recorder.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
707 Series; T.C. 4A21, 4A26	SA1279WE	In-flight entertainment system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
707 Series; T.C. 4A21, 4A26	SA419EA-D	Install vertical remote accelerometer and adapter harness to permit interchangeable use with a modified or unmodified flight recorder in the existing location. Amended 9/8/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA200EA	Installation of SCAT and Auto Thrust Systems.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A26	SA423EA-D	Installation of Dorne and Margolin VHF antenna, DMA 33-2.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA492EA	Installation of Autonetics Air Turbulence Detection System.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A26	SA497CE	Installation of LAS 109CR flight recorder - aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A26	SA498CE	Installation of LAS 109CR flight recorder - aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A26	SA499CE	Installation of LAS 109CR flight recorder - aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A26	SA510EA-D	Installation of passenger seats and interior arrangement.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707 Series; T.C. 4A26	SA511CE	Autopilot variable angle intercept installation. Amended 7/1/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A26	SA511EA-D	Modification of life raft overhead stowage compartment.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA513EA-D	Install water tank assembly in forward baggage compartment.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA533EA	Installation of Dual Bendix DRA-12 Doppler and CPA-24 Computer Systems. Relocation of existing EDO Loran System to Cockpit Pedestal Area. Amended 11/27/67.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A26	SA1424WE	Installation of REA Express 7 Arts Transvision Inflight Motion Picture System.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
707 Series; T.C. 4A26	SA1442WE	Installation of inflight motion picture projection system.	WE	25917	Consolidated Electrodynamics Corp. 360 Sierra Madre Villa Pasadena, CA 91100
707 Series; T.C. 4A26	SA1499WE	Installation of Class Partition Assembly System.	EA	62300	Pan American World Airways, Inc. 200 Park Avenue New York, NY 10017
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA4-1559	Preloaded aluminum baggage container and base fabricated.	WE	36180	John Bean Division of Food Machinery & Chemical Corp. 1115 Coleman Avenue San Jose, CA 95125
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA166SO	Low range radar altimeter system.	SO	62300	Pan American World Airways, Inc. Pan American Building Miami, FL 33159
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA183EA	Mansfield aft and forward bar units in passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 E. 42 Street New York, NY 10001
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA240SW	Seat loaded cargo containers.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA402SW	Dual Collins FD-108 flight director system.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA509EA	Install a standby horizon system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA516EA-D	Install 30 cps chokes in Bendix Course Indicator P/N 7236.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA734WE	Closed-circuit television and stereo system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA1128WE	Cockpit voice recorder.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA1138WE	Electrical monitoring circuit. Reissued 1/28/70.	WE	85764	Whittaker Corporation Instrument Systems Division 12838 Saticoy Street North Hollywood, CA 91603
707, 720; T.C. 4A21, 4A26, 4A28	SA1221WE	Dual Collins AL-101 low range radio altimeter. Amended 12/29/66.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA1281WE	Fire detector system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 and 720 airplanes equipped with Boeing P/N 65-11685 and 65-68862 forward thrust reverser doors; T.C. 4A21, 4A26, 4A28	SA1388CE	Replace magnesium or aluminum forward thrust reverser blocker doors with nylon doors. Issued 12/8/77.	CE	65330	Progressive Manufacturing Co. 1101 S. Ninth Street Kansas City, KS 66105
707, 720 Series; T.C. 4A21, 4A28	SA502EA-D	Install a triple class cabin divider to partition the area between the economy and coach passengers. Amended 11/17/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707/720; T.C. 4A26, 4A28	SA2163WE	Installation of door mounted emergency light. Amended 9/28/70.	WE	44266	International Inflatables Company Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
707/720; T.C. 4A26, 4A28	SA2281WE	Installation of pneumatic butterfly-shutoff valve, P/N 397794-1-1. Issued 12/7/70.	WE	07502	AiResearch Manufacturing Company 402 South 36th Street Phoenix, AZ 85034
707/720; T.C. 4A26, 4A28	SA2282WE	Installation of fluid pressure regulating valve, P/N 898304-1-1. Issued 12/7/71.	WE	07502	AiResearch Manufacturing Company 402 South 36th Street Phoenix, AZ 85034
707/720; T.C. 4A26, 4A28	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans AVenue San Francisco, CA 94124
707, 720 Series; T.C. 4A21, 4A28	SA2637WE	Installation of aft thrust reverser lower latch hook bearings. Issued 1/3/73.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85281
707, 720, 727, 737; T.C. 4A21, 4A26, A3WE, A16WE, 4A28	SA2728WE	Incorporation of HI-LITE SYSTEM P/N 50-1001 for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation 857 Thornton Street San Leandro, CA 94577
707, 727; T.C. 4A26, A3WE	SA2451SW	Marathon Battery Co. part 85-0050 six cell magnesium emergency light pack. Issued 4/20/77.	SW	54810	Marathon Battery Company 8301 Imperial Drive Waco, TX 76710
707, 727; T.C. 4A26, A3WE	SA481EA	Installation of pallet nets. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707; 727; 737; T.C. 4A21, 4A26, 4A28, A3WE, A16WE	SA863EA	Incorporation of DME Corporation emergency evacuation slide lighting system, Model ESL-1, -6, -6-1. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FI 33060
707, 727, 747, 747SP; T.C. 4A26, A3WE, A2WE	SA1967SW	Model LD-8 liquor dispenser. Issued 4/4/75.	SW	16896	Booth, Inc. 1725 Bandy Lake Road Carrollton, TX 75006
707-100, -100B, -200; T.C. 4A21	SA172GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	CE	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
707-100, -100B, -200; T.C. 4A21	SA719CE	Installation of Kollsman altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City International Airport Kansas City, MO 64153
707-100 long body, -100B long body, -100B short body, -200; T.C. 4A21	SA3712WE	Installation of a 40" x 56" adjustable height, folding leaf table. Issued 8/17/78.	WE	28125	Custom Products Company 11626 Tuxford Street Sun Valley, CA 91352
707-100 long body, -100B long body, -100B short body, -200; T.C. 4A21	SA3713WE	Installation of a 40" x 67.25" adjustable height, folding leaf table. Issued 8/17/78.	WE	28125	Custom Products Company 11626 Tuxford Street Sun Valley, CA 91352
707-100, -100B, -200; T.C. 4A21	SA3756WE	Installation of stretcher carrier, P/N AM2003. Issued 10/11/78.	WE	08205	Air Medica, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
707-100, -102B (short-body); T.C. 4A21	SA4025SW	Structural provisions of mid-lavatory service pan. Issued 7/27/79.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
707-100, -200, -300, 720; T.C. 4A21, 4A26, 4A28	SA2EA	Replacement of universal type drive shaft P/N 204679 with Bendix flexible drive shaft model 19E40-1B between the P&W J3C or JT4A series engine mounted gearbox and Sundstrand constant speed drive. Amended 7/23/75.	EA	16000	Bendix Fluid Power Division The Bendix Corporation 211 Seward Avenue Utica, NY 13503

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-100, -100B Long Body, -100B Short Body, -200; 707-300, -400, -300B, -300C; 720, 720B; 727, 727C, 727-200; 737-100, -200, -200C; 747-100, -200B, -200F; T.C. 4A21, 4A26, 4A28, A3WE, A16WE, A20WE	SA10GL	Installation of Gayston Model 800LG and 800SG static dischargers on transport category airplanes. Issued 12/15/72.	GL	37125	Gayston Corporation 55 Janney Road Dayton, OH 45404
707-100, -200; 707-300; 720; 727, 727C, -200; 737; T.C. 4A21, 4A26, 4A28, A3WE, 4A27	SA2534SW-D	Replacement of Switch assembly International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707-100, -200; 707-300; 720; 727, 727C, 727-200; 737; T.C. 4A21, 4A26, 4A28, A3WE, A16WE	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, and EL-104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707-100, -100B, -200, -300, -400, 720, 720B; T.C. 4A21, 4A26, 4A28	SA2579WE	Modify airplanes by the installation of wing tip mounted emblem light. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
707-100/100B, -200, -300/300B/300C, 720/720B; T.C. 4A21, 4A26, 4A28	SA2605WE	Installation of turbine thrust reverser linkage. Amended 8/2/73.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
707-100B; T.C. 4A21	SA984CE-D	Increase maximum zero fuel weight. Issued 9/22/76.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-100B, -300B, 720; T.C. 4A21, 4A26, 4A28	SA2635WE	Installation of forward fan thrust reverser bearings. Issued 1/11/73.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85282
707-121, -139, -321, -321B, -331, -321C, 720-023B, -030B; T.C. 4A21, 4A28	SA311EA	Installation of Aerotherm Corp. Model 1003 stretcher. Reissued 12/5/72.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-121, -139, -321, -321B, -321C, -331, 720-023B, -030B, 737-100, -200; T.C. 4A21, 4A26, 4A28, A16WE	SA677CE	Installation of Crimsco cargo container, P/N 600301, in passenger compartment. Amended December 1974.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
707-121B Series; T.C. 4A21	SA531EA	Installation of EMCO autopilot monitoring system Model No. APMS-E. Amended 9/27/68.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707-121B, -123B, -139B, -227, -321, -321B, -321C, -323C, -327C, -331, -123, -155C, -295; 720-023B, -027, -030B, -048, -062, 727-21C, -21, -27, -27C, -81, -90C, -95; T.C. 4A28, 4A21, 4A26, A3WE, 4A25	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 12/10/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-121B, -139B; T.C. 4A21	ST655SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in forward passenger compartment.	SO	67030	Mace Unit of REF Dynamics, UOP 5846 Victor Street Jacksonville, FL 32207
707-121B, -139B; 707-321, -321B, -321C, -331; 720-023B, -030B; 727-21, -21C; 747-121; T.C. 4A21, 4A26, 4A28, A3WE, A20WE	ST706SO-D	Installation of Skydrol 500C hydraulic fluid. Reissued 9/7/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-121B, -139B; 707-321, -321B, -321C, -331; 720-023B, -030B; T.C. 4A21, 4A26, 4A28	ST708SO-D	Installation of an REF Dynamics carry-on baggage compartment. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-121B, -139B; 707-321, -321B, -321C; 707-331; 720-023B, -030B; T.C. 4A21, 4A26, 4A28	ST711SO-D	Installation of door mounted evacuation slide illumination lights. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-123B; T.C. 4A21	SA405EA-D	Convert all Boeing 707-123B aircraft to winter configuration. Amended 10/10/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 707-323B, 707-323C; T.C. 4A21, 4A26	SA401EA-D	Installation of door mounted evacuation slides on forward and aft entry doors and forward and aft galley service doors. Amended 9/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 707-323B and 707-323C; T.C. 4A21, 4A26	SA415EA-D	Installation of Bell & Howell projection system in 707-123B, install Bell & Howell projection system in 707-323C, install Bell & Howell projection system in 707-323B. Amended 4/21/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 720B-023; T.C. 4A21, 4A28	SA551EA-D	Installation of autopilot go-around unit. Amended 8/11/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, -323C, -323B, 720-023B, 727-23, -35, -95, -123, -223; T.C. A3WE, 4A28, 4A21	SA554EA-D	Install underseat luggage retention device.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707-123B, -138, -323CC, -023B; T.C. 4A21, 4A26, 4A28	SA555EA-D	To comply with FAR 25.812(e), a lever lock switch will be installed at a point accessible to the forward flight attendant seat. Amended 4/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B; T.C. 4A21	SA983CE-D	Cargo door and interior installation non-convertible air freighter. Issued 5/24/76.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-123B; T.C. 4A21	SA4053WE	Installation of an auxiliary fuel tank system consiting of two identical tank assemblies located in the forward cargo compartment and one located in the aft cargo compartment. Issued 10/30/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
707-123B, -138B; T.C. 4A21	SA3257WE	Installation of AiResearch GTCP 85-98CK auxiliary power unit in forward cargo compartment. Amended 8/18/78.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-123B, 707-138B; T.C. 4A21	SA3441WE	Installation of airstairs. Amended 3/15/79.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
707-124 Series; T.C. 4A21	SA582CE	Relocation of Lockheed Aircraft Service Model 109CR, flight recorder to aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA584CE	Autopilot modification to incorporate variable intercept feature.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA585CE	Installation of Fairchild Cockpit Voice Recorder System.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA586CE	Installation of Fenwall fuel vent surge tank protection system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA627CE	Installation of (1) dual radio altimeter provisions (2) single Bendix ALA-51 radio altimeter transmitter-receiver with dual indicators.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131; T.C. 4A21	SA439CE	Installation of logo lights on horizontal stabilizer. Amended 11/25/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131; T.C. 4A21	SA556CE	Installation of auto-thrust provisions. Amended 3/19/69.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-124/-131/-131B; 707-331/-331B/-331C/-373; T.C. 4A21, 4A26	SA577CE	Replace Bendix type 15866, 15897 and 19903 vertical gyros with Bendix type 19911 or 19912 vertical gyros.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, 131, -131B-331, -331B, -373C, -338C; T.C. 4A21, 4A26	SA680CE	Modify the A.C. essential bus power source circuitry to provide automatic transfer. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-124, -131, -131B, -331, -331B, -331C; T.C. 4A21, 4A26	SA682CE	Install Litton Model E-30 microwave oven.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131; T.C. 4A21	SA555CE	Installation of a single SCAT system. Amended 3/19/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131; T.C. 4A21	SA862CE	Addition of large cargo door in left hand side of fuselage. Issued August 1972.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-131, -131B; T.C. 4A21	SA607CE	Installation of provisions for dual radio altimeters and single Bendix Model ALA-51A equipment. Amended 4/29/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131, -131B, 331, 331B, 331C; T.C. 4A21, 4A26	SA3-708	Install motion picture projector and screen. Amended 12/27/67.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131, -131B, 720B; T.C. 4A21, 4A28	SA432CE	Installation of Fenwall fuel vent surge tank protection system. Amended 8/22/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA197CE	Installation of a single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA298CE	Installation of a single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA488CE	Relocation of LAS Model 109CR flight recorder.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA1052CE	Replacement of existing fire detection system with a Kidde dual loop fire detection system. Issued September 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA1520CE	Installation of a Growth Industries dual cavity oven. Issued 10/31/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-131B, -331B, 331, 331C, 373, 338C; T.C. 4A21, 4A26	SA519CE	Installation of logo lights in horizontal stabilizer. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131/-131B/-331/-331B/-331C/-373C, 338; T.C. 4A21, 4A27	SA827CE	Install Butler National Corp. flight recorder/communications interface unit. Amended April 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B, -331B, -331C; T.C. 4A26	SA1478CE	Installation of pitot heater failure indication system. Issued 3/22/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-138B; T.C. 4A21	SA797EA	Installation of inflight motion picture system. Reissued 2/26/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-138B; T.C. 4A21	SA1132EA	Installation of two Solar Model T-62T-40C2 APU's for ground use only. Amended 11/8/79.	EA	63275	PATS, Inc. 7190-8 Oakland MIlls Road Columbia, MD 21046
707-138B; T.C. 4A21	SA1136EA	Installation of an onboard passenger loading stairs. Amended 12/14/78.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
707-138B; T.C. 4A21	SA1403WE	Interior arrangements.	NW	74920	Standard Airways, Inc. Tower Building Seventh and Olive Streets Seattle, WA 98101
707-138B; T.C. 4A21	SA3320WE	Installation of radio altimeter system No. 1. Issued 1/17/77.	WE	13970	Aviation Service & Support Corp. 4150 Donald Douglas Drive Long Beach, CA 90801
707-139B Series; T.C. 4A21	SA687EA	Installation of Data Link System.	EA	62300	Pan American World Airways, Inc. JFK International Airport Hangar 17 - Room 2011 Jamaica, NY 11430

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-139B, -121B, 720-023B, -030B; T.C. 4A21, 4A28	SA1937WE	Installation of under-seat baggage restraint system. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-153B; T.C. 4A21	SA81NW	Minor modifications to pilot's instrument panel and relocation of autopilot accelerometer and rate gyros for improved performance. Amended 12/7/73.	SW	24252	Collins Radio Company Avionics Systems Center P.O. Box 98 Addison, TX 75001
707-153B; T.C. 4A21	SA856EA	Installation of a compartment bulkhead at fuselage station 978. Issued 12/22/70.	EA	80910	Department of the Air Force Hq. 89th Military Airlift Wing (SM)MAC Andrews Air Force Base Washington, D.C. 20331
707-153B; T.C. 4A21	SA1700WE	Installation of Dual Litton LTN-51 Inertial Navigation Systems. Amended 10/21/68.	WE	51500	Litton Systems, Inc. Guidance & Control Systems Div. 5500 Canoga Avenue Woodland Hills, CA 91364
707-153B, -353B; T.C. 4A21, 4A26	SA350EA	Passenger Berth Installations. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Company P.O. Box 33 Ontario, CA 91761
707-153B, -353B; T.C. 4A21, 4A26	SA648EA	Modification of Collins FD109G Flight Director.	EA	80910	Department of the Air Force Hq. 89th Military Wing (SM) MAC Andrews Air Force Base Washington, D.C. 20331
707-153B, -353B; T.C. 4A21, 4A26	SA858EA	Modification of rigid high pressure starter air lines on numbers 2 and 3 engines. Issued 12/29/70.	EA	80910	Department of the Air Force Hq. 89th Military Airlift Wing (SM)MAC Andrews Air Force Base Washington, D.C. 20331
707-227, 720-027; T.C. 4A21, 4A28	SA1138WE	Installation of fire warning monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Canoga Park, CA 91304
707-300; T.C. 4A26	SA208NW	Installation of Fairchild Stan (R) weight and balance system. Issued 10/21/75.	NW	08350	Air Repair, Inc. 811 West Perimeter Road Renton, WA 98055
707-300 Series; T.C. 4A26	SA3599WE	Installation of single or dual Litton LTN-201 Omega navigation as a means to update INS or doppler in the NAT MNPS airspace. Amended 5/8/78.	WE	51500	Litton Aero Products Division 6700 Eaton Avenue Canoga Park, CA 91303
707-300, -300B, -300C, -400; T.C. 4A26	SA171GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	CE	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
707-300, -300B, -300C, -400 Series; T.C. 4A26	ST661SO	Installation of dual band "C/X" type weather radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Company P.O. Box 350 Akron, OH 44309
707-300, -300B, -300C, -400 Series; T.C. 4A26	SA3167WE	Installation of dual Litton LTN-51 inertial navigation systems. Issued 4/5/76.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
707-300, -300B, -300C, -400, 338C; T.C. 4A26	SA726CE	Installation of Kollsman altitude alerting system. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-300, -300B, -300C, 707-400 Series; T.C. 4A26	SA3486WE	Installation of dual Litton LTN-51, or dual Litton LTN-72, or one Litton LTN-72 inertial navigation systems. Issued 11/3/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91364
707-300, -300B, -300C, -400; T.C. 4A26	SA3830WE	Installation of dual Delco C-IVA inertial navigation system. Amended 10/17/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
707-300 and 707-400 Series; T.C. 4A26	ST914SO	Installation of cargo floor - Model 707-300 series; 707-400 series installation of secondary main landing gear position lights.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-300, -400; T.C. 4A26	SA3331WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-300B, -300C; T.C. 4A26	SA817NW	Modification of cabin passenger interior, and forward storage units. Issued 8/8/79.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
707-300B, -300C; T.C. 4A26	SA2594WE	Modify 707-300B and -300C series airplanes by the installation of wing tip mounted emblem light. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406
707-300B, -300C; T.C. 4A26	SA2610WE	Installation of Bell & Howell movie projection system Nos. 478441 and 478440. Issued 1/11/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
707-300C, 727C; T.C. 4A26, A3WE	SA647SO	Installation of AIF partition class divider P/Ns 402-1, 402-2, 402-3, 402-4, and header assembly P/Ns 403-1 and 404-1. Amended 7/16/68.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33142
707-300C Series; T.C. 4A26	ST939SO	Installation of livestock pen. Issued 6/10/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-300C Series; T.C. 4A26	SA1443WE	Installation of tray carrier.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-320; T.C. 4A26	SA2374WE	Installation of an air filter to the cabin pressure limit control outflow safety valve, P/N 103430-3. Issued 6/24/71.	WE	07505	AiResearch Manufacturing Company 2525 W. 190th Street Torrance, CA 90509
707-320C; T.C. 4A26	SA251NW	Installation of cargo system. Issued 1/16/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
707-320C Series; T.C. 4A26	SA3539WE	Installation of single, palletized Litton LTN-51 or LTN-72 inertial navigation system. Issued 12/20/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
707-321; T.C. 4A26	ST710SO-D	Relocation of "B" galley approximately 10" forward of present location. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321; T.C. 4A26	SA778CE	Addition of large cargo door in left hand side of fuselage. Issued June 1971.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA852CE-D	Reduction of empty weight by removal of all passenger interior equipment and installation of fire resistant lining. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA1555WE	Installation of fire warning electrical monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Canoga Park, CA 91304
707-321, -321B; T.C. 4A26	SA344EA	Install inertial navigation system. Amended 4/1/66.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321, -321B, -321C, -331, -386C; T.C. 4A26	ST652SO-D	Installation of P&W JT8D engine and associated structural and fairing pod under L.H. wing between No. 2 engine and fuselage. Reissued 9/7/78.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
707-321, -321B, -331; T.C. 4A26	ST656SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in the forward passenger compartment. Amended 11/6/68.	SC	67030	Mace Unit of REF Dynamics, UOP 4856 Victor Street Jacksonville, FL 32207
707-321, -321B, -321C, -331; T.C. 4A26	ST712SO-D	Modification and installation of a Hardman Model 6747 seat. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321, -324C; T.C. 4A26	SA2238WE	Installation of Brownline Cargo net assembly #41412 used in conjunction with Brownline pallet assemblies #40160 and 40144. Amended 5/16/75.	WE	17740	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-321, -331, 720-040B; T.C. 4A26, 4A28	SA1-593	See Document No. Report No. 3078, dated January 30, 1969, concerning pallet assembly IR-3000 Rev. B. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-321, -400; T.C. 4A26	ST914SO	Installation of cargo floor. Amended 1/19/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-321B; T.C. 4A26	SA611EA	Installation of dual A.C. electronics navigation systems on R/N N435PA, S/N 5034. Amended 5/21/68.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B; T.C. 4A26	ST702SO-D	Installation of Bendix FINDS. Limited to aircraft N421PA S/N 19266. Issued 11/15/68.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST707SO-D	Modified aircraft to incorporate Emerson engine performance monitoring system, aircraft S/N 19363, N428PA. Issued 10/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST713SO-D	Installation of a coat closet between fuselage stations 373 and 414 L.B. side. Reissued 9/12/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B; T.C. 4A26	SA1067EA	Installation of stowage cabinets Issued 12/16/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
707-321B; T.C. 4A26	SA3549WE	Installation of Garrett GTCP85-98CK auxiliary power unit in forward baggage compartment. Issued 1/27/78.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-321B, 321C; T.C. 4A26	ST709SO-D	Installation of flight spares container in right hand main landing gear wheel well on fuselage station 960 bulkhead. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	SA700EA	Switches are installed on outboard thrust levers to disengage autothrottle system.	EA	62300	Pan American World Airways, Inc. Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	ST704SO-D	Installation of Bell & Howell forward projection movie system. Reissued 9/7/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321-B, -321C; T.C. 4A26	SA1076EA-D	Removal of Loran navigation system and installation of dual Omega navigation systems for updating doppler. Amended 8/13/79.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321C; T.C. 4A26	SA541NW	Installation of quick change interior. Issued 1/18/78.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98021
707-321C; T.C. 4A26	SA1134WE	Palletized cargo system installation 65-42629 or 65-43629 with Brownline pallet 22630-51, 26100-51 or -52 and Brownline net assy 23225-51, 23226-51, or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1143WE	Installation of Boeing palletized cargo system. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1293WE	Palletized cargo system installation 65-42629 with Brownline pallet 22630-51 and net assy 23225-51 or 23226-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1597WE	Installation of Heath Tecna Corporation pallet AC-10065 and Brownline Corporation Net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C; T.C. 4A26	SA2125WE	Installation of Ancra Cargo Net Assembly 40234-10 used in conjunction with either Brownline pallet assembly 22630-51 or Heath Tecna pallet assembly AC 10065-1.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 90245

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-321C; T.C. 4A26	SA2221WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp Net Assembly 40234-10 and net assemblies approved to NAS 3610-2A1N and NAS 3610-2A3N. Issued 8/19/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
707-321C; T.C. 4A26	SA3005WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-321C, -324C; T.C. 4A26	SA2238WE	The installation of Brownline cargo net assembly #41412 used in conjunction with Brownline pallet assemblies #40160 and 40144. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C, 727-21C; T.C. 4A26, A3WE	SA736EA	Installation of L. Marino forward cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-321C, 727-21C; T.C. 4A26, A3WE	SA1859WE	Installation of net assembly AC-10292-1 used in conjunction with pallet assembly AC-10065-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C, 727-21C; T.C. 4A26, A3WE	SA2045WE	Modification by installation of pallet assembly 40160 used in conjunction with net assemblies 23225-51, 23226-51, 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; 727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA849EA	Goodyear Aerospace Corporation cargo pallet (1.5 Fwd.) P/N 634A303-001-101 is eligible to be used only in combination(s) as shown in the following tables:	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315

BOEING COMPANY			CARGO NET	
AIRPLANE MODEL	CARGO RESTRAINT SYSTEM	WEIGHT & BALANCE CONTROL MANUAL (b)	MANUFACTURER & PART NO.	TIE-DOWN CONFIGURATION
707-321C (a)	65-42629 65-43629	D6-14083.6	Brownline 40510-101	88" x 125"
			22758-51	
			23225-51	
			Marino LM1500-100	88" x 125"
			Brownline 21970-51 (Chg. G)	88" x 108"
727-21C (a)	65-49102	D6-21000.17C	Brownline 40510-101	88" x 125"
			22758-51	
			23225-51	
			23226-51	
			Marino LM1500-100	88" x 125"
			Brownline 21970-51 (Chg. G)	88" x 108"
747-121	65B-60060 Lower Lobe Compartment Aft Hold ONLY	D6-13700	Brownline 22758-51	88" x 125"

(a) Barrier Net Installation per Boeing Drawing 65-34700-1 required for these model aircraft with this installation.

(b) The applicable Boeing Weight and Balance Control Manual must be used to obtain permissible compartment load, under conditions described therein, not to exceed the pallet-net combination(s) capacity of 13,300 lb. for the 88" x 125" tie down configuration or 8000 lb. for the 88" x 108" tie down configuration.

707-321C;727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA1902WE	Installation of Irvin cargo pallet assembly 125014 used in conjunction with net assembly 22758-51 (Brownline), net assembly 40234010 (ANCRA), and net assembly LMI-500-100 (Marino). Amended 8/25/70.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
707-321C, 727-21C; T.C. 4A26, A3WE	SA2103WE	Installation of Net Assembly 40510-101 used in conjunction with Brownline Pallet Assemblies 40160-101 thru -100, 22630-51 and Heath Pallet AC-10065-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-323, 707-385C; 707-323B; T.C. 4A26	SA517EA-D	Installation of dual Litton LTN-51 inertial navigation systems. Install No. 2 ship's battery (24 volts, 36 AH) to provide standby DC power for No. 2 inertial navigation system. Installation perforated filler panels fore and aft of both control/display units. Amended 1/22/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA556EA-D	Convert interior passenger arrangement to winter configuration of 4 first class lounge, 32 first class seats and 101 tourist class seats. Amended	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA561EA-D	Installation of automatic throttle/ speed control system. Amended 3/2/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA562EA-D	Installation of dual aileron and elevator surface servos to operate in a single servo configuration with the PB20 autopilot system. Amended 3/31/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA564EA-D	Modify the interior arrangement of the 707-323B aircraft from its present configuration to 32 F/C plus 102 T/C passencer. Install additional meal stowage. Issued 5/18/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA508EA-D	Install a single inertial navigation system (LTN-51E). Amended 1/5/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74116
707-323C; T.C. 4A26	SA525EA-D	Convert interior passenger arrangement to the summer configuration of four first class lounge, 26 first class, and 113 tourist class seats. Amended 4/15/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA559EA-D	Interior arrangement and configuration.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA565EA-D	Install emergency evacuation slide lights for station 990. Issued 6/17/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA1560WE	Installation of Aeronca cargo containers on Boeing 707-323C.	WE	02398	Aeronca, Inc. Aerocal Division 24751 S. Crenshaw Boulevard Torrance, CA 90505
707-323C; T.C. 4A26	SA1720WE	Installation of Heath Tecna structural igloo assembly AC-0123. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2008WE	Installation of structural cargo container AC-10260-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2401WE	Installation of Transequip structural igloo assembly P/N 245084 in conjunction with loading systems 65-42625, 65-42630, and 64-34899. Issued 8/26/71.	WE	79000	Transequip, Inc. 5438 W. 104th Street Los Angeles, CA 90045
707-323C; T.C. 4A26	SA2453WE	Installation of Transequip structural containers in position I13 (container 235111) and position I14 (container 235112). Amended 10/30/79.	WE	79000	Transequip, Inc. 5438 West 104th Street Los Angeles, CA 90045
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2022WE	Installation of pallet assembly 40122-101, -102, -103, -104, and -105 used in conjunction with net assemblies 22178-51, 23652-51, 22361-51c, 22780-51, 22780-52, 22656-51, 22656-52, and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2174WE	Installation of pallet assembly 40550-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22362-51 or AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -331C, 373C, 385C; 727-31C, -180C; T.C. 4A26, A3WE	SA1924WE	Installation of Irvin cargo pallet assembly 125001-501, -503, -505, -507 used in conjunction with net assembly 10-60934-1 (Boeing).	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
707-323C, -331C, -373C, 727-1A7C, -31C, -180C; T.C. 4A26, A3WE	SA2098WE	Installation of structural cargo container 40619-101, -103. Amended 5/16/75.	WE	17740	Brooks & Perkins 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA945WE	Installation of autopilot go-around unit. Amended 8/1/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C and 707-385C; T.C. 4A26	SA1524WE	Brownline Structural Containers 23885-51 may be used as optional cargo equipment either in place of or with cargo net assemblies. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA1939WE	Modify by installation of structural cargo container 24385-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA2234WE	Installation of Brownline Division structural container No. 41342-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -385C; 727-22C; T.C. 4A26	SA2278WE	Installation of Brownline cargo container model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division Torrance, CA 90505
707-326C; T.C. 4A26	ST70180-D	Installation of alternate inertial navigation system control display unit. Limited to aircraft N870PA, S/N 20016; N871PA, S/N 20017; N872PA, S/N 20018. Amended 6/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-327C; T.C. 4A26	SA739EA	Installation of Inflight Motion Picture System. Reissued 10/24/73.	EA	11434	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-327C, -330C, -338C, -351C, 727-25C, -27C, -30C, -51C, -62C; T.C. 4A26, A3WE	SA2026WE	Installation of pallet assembly 40134-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22364-51, 23215-51, 23618-51 or 23783-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-327C; T.C. 4A21	SA2748WE	Installation of weight and balance computer system. Issued 8/15/73.	WE	52010	Lockheed Aircraft Service Company Ontario International Airport P.O. Box 33 Ontario, CA 91764
707-330C, 727-30C; T.C. A3WE	SA1917WE	The type design change consists of installation of pallet assembly 24076-51 in conjunction with net assembly 22361-51, 22364-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-331; T.C. 4A26	SA420CE	Installation of single seat system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA489CE	Relocation of Lockheed Air Service Model 109CR flight recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA635CE	Installation of dual radio altimeter system provisions and single radio altimeter equipment. Amended 2/20/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA854CE-D	60,000 lbs. main deck allowable loading. Issued 12/7/73.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-331; T.C. 4A26	SA1551WE	Installation of fire warning monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Conoga Park, CA 91304
707-331, 707-331 (ADV); T.C. 4A26	SA291CE	Installation of single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331, -331B, -331C, -373C, -338C; T.C. 4A26	SA465CE	Installation of Fenwall fuel vent surge tank. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64108
707-331 (Advanced), -331C, -338C, -373C; T.C. 4A26	SA899CE	To permit autopilot coupled approaches at 40 degrees flp setting below 500 feet. Issued August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331, -331B, -331B(ADV), -331C, -373C; T.C. 4A26	SA1327CE	Installation of Bendix ONS-25-5 Omega navigation system for updating primary self-contained navigation system. Issued March 1977.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195
707-331, -373C, 727-31A, -180C; T.C. 4A26, A3WE	SA2290WE	Installation of Ancra pallet net assembly P/N 40452-10 used in conjunction with Boeing 9g pallet assemblies (88" x 125") numbers 10-60935-1, 10-60935-11, 10-60935-17, 10-60935-21, 10-60935-27 and 10-60935-37. Amended 2/22/71.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 990245
707-331B, -331C; T.C. 4A26	[illegible]	Installation of a Growth Industries dual cavity oven. Issued 12/10/70.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-331B, -331C, -338C, -373; T.C. 4A26	[illegible]	Replacement of existing fire detection system with a Fidde dual loop fire detection system. Issued September 1976.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C, T.C. 4A26		Installation of single SCAT system. Amended [illegible].	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C; T.C. 4A26	[illegible]	[illegible] auto throttle [illegible] system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, Mo 64153
707-331C; T.C. 4A26	[illegible]	[illegible] of dual radio altimeter [illegible] equipment.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331 (Convertible), 707-338C; T.C. 4A26	[illegible]	[illegible] variable angle intercept [illegible] system. [illegible] 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C, -338C; T.C. 4A26	[illegible]	[illegible] of single SCAT system. [illegible] July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C, -338C; T.C. 4A26	[illegible]	Installation of auto thrust system. Amended [illegible].	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C, -373C, -338C; T.C. 4A26	[illegible]	Installation of revised life raft and courier seat provisions. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA757EA	Goodyear Aerospace Corporation Cargo pallet with barrier net installation. Amended 3/17/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massilon Road Akron, OH 44315
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1866WE	Installation of Heathair AC-10113-1 net assembly in conjunction with pallet assemblies AC-10070-1 and AC-10347-1. Reissued 1/6/71.	NW	41625	Heath Techna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1963WE	Installation of pallet assembly 23250-52 used in conjunction with net assemblies 22178-51, 22780-52, 22656-51, 22656-52 and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2172WE	Installation of Irvin Industries Net Assembly 120012-501 used in conjunction with Cargo Pallet 125001-501, -503, -505, -507. Issued 8/19/70.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2412WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, 727-31C; T.C. 4A26, A3WE	SA2088WE	Installation of cargo pallet assemblies 1950-90-501 and 1950-90-1001 used in conjunction with net assembly 22758-51 (Brownline).	WE	19890	Cargo Systems, Inc. 1040 West Hoover Street Orange, CA 92667
707-338C; T.C. 4A26	SA730EA	9G 10,000 lb. maximum capacity Pallet Cargo Net P/N LM 1505-1 eligible as replacement for approved Brownline Net P/N 22361-51 or Boeing Net 10-60934-1 in combination with 125" x 88" pallets Brownline P/N 23223-51 or Phenrock P/N 22861-51 or Bruggermann & Brand P/N 2102. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-338C; T.C. 4A26	SA1230CE-D	Passenger cabin contemporary interior installation. Issued 2/1/77.	CE	16878	The Boeing Company 3802 South Oliver Wichita, KS 67210
707-338C; T.C. 4A26	SA2352WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargo pallet assembly P/N 24076-51. Issued 6/14/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-345C; T.C. 4A26	SA675EA	Installation of L. Marino cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-345C; T.C. 4A26	SA725EA	Pallet P/N LM1600 (1.5G Fwd). Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-347, 720-047B; T.C. 4A26, 4A28	SA2557WE	Replacement of existing girt on Air Cruiser evacuation slide P/Ns 15D22093-7, 15D22093-11, 15D22094-10 and 15D22454-2 with Sargent Industries/PICO Division girt P/N 6176105-103. Issued 6/30/72.	WE	70130	Sargent Industries Pico Division 2045 Evans Avenue San Francisco, CA 94124
707-347C; T.C. 4A26	SA979CE-D	Passenger interior arrangement modified to 5 pallet cargo/passenger configuration, per Boeing Dwg. 65-88752 & 65-88753, cargo conversion capability, Class "B" compartment with passengers, Class "E" compartment with no passengers. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-347C; T.C. 4A26	SA2975WE	Installation of shroud assembly, P/N 0350740068, in Universal Oil Products galley P/N 10870, to Weber Aircraft Company beverage cart, P/N 818620-411. Issued 1/6/75.	WE	48550	H. Koch & Sons 5410 E. LaPalma Anaheim, CA 92807
707-347C; T.C. 4A26	SA3601WE	Installation of a single Collins INS 61B inertial navigation system. Issued 3/10/78.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C; T.C. 4A26	SA3792WE	Installation of Litton LTN-211 omega navigation system. Amended 8/31/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C, -351C, 720-047B; T.C. 4A26, 4A28	SA808EA	Installation of inflight motion picture system. Amended 3/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-349C; T.C. 4A26	SA1596WE	Installation of Brownline Pallet 23997-51 and Net 22758-51 combination. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-349C; T.C. 4A26	SA1624WE	Installation of Decca Omni trac, Decca Doppler and Decca Loran. Amended 5/10/68.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-349C; T.C. 4A26	SA1650WE	Modification of co-pilot's C-11 compass system to a C-11B system by addition of remote compensator.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
707-351B/C; T.C. 4A26	SA87GL	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
707-351B; T.C. 4A26	SA1168EA	Installation of dual solar T-62T-40C2 gas turbine auxiliary power units, for ground use only. Amended 11/8/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
-707-351C, 727-51C, -25C; T.C. 4A26, A3WE	SA1888WE	Installation of pallet assembly AC-10359-1 used in conjunction with net assembly AC-10373-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-351C; T.C. 4A26	SA2526WE	Installation of Satco Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with assemblies conforming to NAS 3610-1A2N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
707-351C; T.C. 4A26	SA2528WE	Installation of Satco, Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with net assemblies conforming to NAS 3610-1A3N, 2A1N, 2A2N, 2A3N, 2A5N, and 2A6N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 9024⁵
707-351C; T.C. 4A26	SA2773WE	Installation of Tridair Industries 3G net assembly. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
707-351C, -384C; T.C. 4A26	SA855CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-353B; T.C. 4A26	SA83NW	Relocation of autopilot accelerometer and rate gyros. Issued 1/16/74.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
707-353B; T.C. 4A26	SA1596SW	Steel duct installation for APU according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
707-353B; T.C. 4A26	SA1927WE	Installation of dual Litton inertial navigation systems.	WE	51500	Litton Systems, Inc. 5500 Canoga Park Woodland Hills, CA 91364
707-355C; T.C. 4A26	ST654SO	Installation of liquor service galley.	SO	05356	Aircraft Interior FAbricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
707-359B; T.C. 4A26	SA2863WE	Passenger audio entertainment system installation. Issued 3/29/74.	WE	33223	Electronic Engineering Company of California 1441 E. Chestnut Avenue Santa Ana, CA 92701
707-365C, -372C, 727-172C; T.C. 4A26, A3WE	SA1795WE	Installation of Heath Tecna AC-015201 structural container. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
707-369C; T.C. 4A26	SA1234CE-D	Passenger cabin contemporary interior installation. Issued 1/24/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-372C and 707-365C; T.C. 4A26	SA1674WE	Installation of Heath Tecna Corporation AC-10160 pallet with AC-10069 net. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastic Division 19819 - 84th Avenue South Kent, WA 98031
707-373C; T.C. 4A26	SA426CE	Modify SCAT system circuit. Amended 3/9/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-373C; T.C. 4A26	SA714CE	Installation of dual Bendix ALA-51 radio altimeter provisions and equipment.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-373C; T.C. 4A26	SA2843WE	Modification by installation of horse stalls P/N 690069 on NAS 3610-2A4P pallet. Issued 3/15/74.	WE	87900	W.W. Industries, Inc. 12450 Inglewood Avenue Hawthorne, CA 90250

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-384B; T.C. 4A26	SA853CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-384B, 707-384C; T.C. 4A26	SA576CE	Installation of multi-channel audio entertainment system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-384B, 707-384C; T.C. 4A26	SA546CE	Installation of doppler autopilot tie-in Bendix DRA-12 doppler radar with CPA-24 computer to Bendix PB-20 autopilot. Amended 12/27/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-386C; T.C. 4A26	SA2808WE	Installation of dual Litton LTN-72 inertial navigation system. Issued 2/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Road Woodland Hills, CA 91364
707-387B; T.C. 4A26	SA1232CE-D	Installation of large cargo door in left hand side of forward fuselage. Issued 6/10/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-387B; T.C. 4A26	SA1233CE-D	Increase maximum zero fuel weight to 96,162 KG Issued 8/31/77.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-387B; T.C. 4A26	SA1236CE-D	Installation of auxiliary power unit. Issued 9/26/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-399C; T.C. 4A26	SA850CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aereos Portugeses. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-400, 720 Series; T.C. 4A26, 4A28	ST912SO	Installation of cargo barrier net. Amended 9/13/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
720 Series; T.C. 4A28	SA88NW	Optional interior seating arrangement. Issued 1/14/74.	NW	10174	American Aviation Services 777 Perimeter Road Boeing Field Seattle, WA 98108
720 Series; T.C. 4A28	SA95CE	Crimsco 600301 jet cargo containers in forward cabin.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
720 Series; T.C. 4A28	SA148SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA180NW	Installation for 149 passenger configuration. Issued 5/7/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720 Series; T.C. 4A28	SA182SO	Interior modifications.	SO	31429	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA302EA	Inflight motion picture system. Amended 6/9/67.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA369EA	Litton low range altimeter system.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430
720 Series; T.C. 4A28	SA371CE	Wheel 152051-4 and brake assembly 260997-1.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46620
720 Series; T.C. 4A28	SA380EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430
720 Series; T.C. 4A28	SA458WE	Crimsco jet cargo container 04-005--01, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA460CE	Wheel assembly 152051-5 and brake assembly 2600997-3.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46600

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
720 Series; T.C. 4A28	SA468EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
720 Series; T.C. 4A28	SA773WE	Closed circuit television entertainment system.	WE	25970	Continental Air Lines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
720 Series; T.C. 4A28	ST806SO	Installation of a cargo floor, smoke detector system and cargo restraint bulkhead. Amended 12/12/78.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
720 Series; T.C. 4A28	SA848CE-D	Additional overwing escape hatch installation interior configuration 2nd additional overwing escape hatch installation. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
720 Series; T.C. 4A28	SA1222WE	Boeing improved type engine thrust reverser forward pressure seal.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128
720 Series; T.C. 4A28	SA1245WE	Either single or dual Collins AL-101 radio altimeter system.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128
720, 720B; T.C. 4A28	SA177NW	Installation of container rack and six accompanying containers on forward right-hand coat closet. Reissued 5/29/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720, 720B; T.C. 4A28	ST564SO	Installation of HF antenna and associated hardware and structural provisions for mounting HF tuning unit. Issued 11/19/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
720, 720B; T.C. 4A28	ST662SO	Installation of nose cap "C/X" band weather radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
720, 720B; T.C. 4A28	ST931SO	Addition of smoke detector system for conversion to cargo carrier. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	ST932SO	Mechanical landing gear position indicator. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	SA3332WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
720B; T.C. 4A28	SA328NW	Installation of Fairchild weight and balance system (STAN). Issued 7/28/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
720B; T.C. 4A28	SA2806SW	Stewart-Davis, Inc. auxiliary power unit. Issued 6/30/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
720-22; T.C. 4A28	SA112NW	Installation of cabin interior arrangement. Issued 5/16/74.	NW	08480	Alaska Airlines, Inc. Seattle/Tacoma Int'l Airport Seattle, WA 98155
720-22; T.C. 4A28	SA278EA	See Document No. Report No. 3187, dated 4/18/67, Rev. 1/30/69, concerning Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
720-022; T.C. 4A28	SA1553WE	Installation of Fairchild P/N 13920-301 or 15630-601 Flight Data Recorder and Honeywell P/N 180 VI Central Data Computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2095WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2206WE	Installation of Bendix third attitude indicator. Issued 7/20/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720-022; T.C. 4A28	SA2744WE-D	Alternate 143 passenger seating configuration. Issued 3/28/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
720-022; T.C. 4A28	SA2746WE-D	Alternate 149 passenger seating configuration. Issued 5/3/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2834WE-D	Alternate 101 passenger seating configuration. Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2831WE-D	Couple EDO Loran system to ADF sense antenna instead of fin cap (no fin cap on UAL B720). Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2833WE-D	Installation of two HF communications systems. Issued 3/27/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022, -023, -025, -027, -048, -062, 720B-023B, -024B, -030B, -040B, -047B, -051B, -058B, -059B, -060B, -068B; T.C. 4A28	SA460CE	Replace main wheel and brake assemblies with Bendix wheel assembly P/N 152051-5 or P/N 152051-4 and Bendix brake assembly P/N 2600997-3. Reissued 5/1/79.	GL	15500	The Bendix Corporation Aircraft Brake & Strut Division 3520 West Westmoor Street P.O. Box 10 South Bend, IN 46624
720-022 and 727-22; T.C. 4A28 and A3WE	SA1396WE	Installation of McMillan Radome P/N 2406 as a replacement for Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720B-023; T.C. 4A28	SA412EA-D	Relocate the L.A.S.I. flight data recorder to the aft fuselage area at Station 1452 utilizing remote vertical accelerometer in left wheel well. Install new auxiliary pitot tube and static ports for the flight recorder.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
720-023B; T.C. 4A28	SA985CE-D	Side cargo door and interior installation. Issued 3/17/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-023B, -030B; T.C. 4A28	ST657SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in forward passenger compartment.	SO	67030	Mace Unit of REF Dynamics, UGP 4856 Victor Street Jacksonville, FL 32207
720-023B, -030B, 720-047B; T.C. 4A28	SA851CE-D	Increase maximum ramp weight to 235,000 lbs. and zero fuel weight to 156,000 lbs. Amended 11/21/78.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-024B; T.C. 4A28	SA1617WE	Rewiring of galley electrical power supply.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA1767WE	Installation of Galley Models CAG-10, -20, 30 and -40 manufactured by Dale Engineering & Development, Inc. Amended 10/10/68.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA2599WE	Installation of Bell & Howell movie system. Issued 9/29/72.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-025; T.C. 4A28	SA251GL	Installation of Canadian Marconi Model CMA-740 Omega/VLF navigation system. Amended 12/29/78.	GL	10340	American Trans-Air 2600 South High School Road Indianapolis, IN 46241
720-025; T.C. 4A28	ST668SO	Installation of International Inflatables Co. door-mounted inflatable evacuation slide, P/N 68040, and International Inflatables Co. door-mounted slide container, P/N 00800.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
720-027; T.C. 4A28	SA82NW	Installation of navigator's station. Issued 12/11/73.	NW	10174	American Aviation Services, Inc. 7777 Perimeter Road Boeing Field Seattle, WA 98108
720-047B; T.C. 4A28	SA194NW	Installation of new look interior arrangement. Issued 6/30/75.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
720-051B; T.C. 4A28	SA801CE	Install Mark II (Hytrol) anti-skid system. Issued December 1971.	CE	16878	The Boeing Company Wichita Division 3801 S. Oliver Wichita, KS 67210
727 Series; T.C. A3WE	SA103SO	Collins 54W-1 comparator warning system. Amended 8/10/66.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA121GL	Installation of bleed-air valve actuator, P/N G66, to replace Boeing P/N 10-60817, in various locations in anti-ice system. Issued 11/3/76.	GL	60350	MPC Products Corporation 4200 West Victoria Avenue Chicago, IL 60646
727 Series; T.C. A3WE	SA140SO	Manufacture and install coatroom and magazine rack.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33148
727 Series; T.C. A3WE	SA159SO	Aircraft integrated data systems (AIDS).	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA161SO	Dual radio altimeter system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA183SO	Crimsco cargo containers 6003 in main cabin. Amended 12/15/66.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
727 Series; T.C. A3WE	SA339CE	Fairchild cockpit voice recorder system. Amended 3/15/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA354CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA372CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA425EA-D	Install standby horizon system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA427CE	Flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64108
727 Series; T.C. A3WE	SA438CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA447EA	Vector analog computer system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727 Series; T.C. A3WE	SA469EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA490NW	Installation of PRIMUS-90 weather radar with standard black and white and also with color display.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188
727 Series; T.C. A3WE	SA535EA	Fabrication and installation of Marino Flex-Net P/N LM365. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA604SO	Dual Collins FD-109 integrated flight system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA625SO	Installation of main landing gear wheel assembly, P/N 3-1287 and brake assembly P/N 2-1147 or 2-1147-1, 2-1190.	GL	38504	B.F. Goodrich Engineered Systems Company Box 340 Troy, OH 45373
727 Series; T.C. A3WE	ST664SO	Modify door-mounted evacuation slide container, Boeing P/N 65-26998-1, from a two-point closure to a positive single-point closure. Amended 3/30/70.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
727 Series; T.C. A3WE	SA699WE	Crimsco jet cargo container 04-005-01-1, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60660

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727 Series; T.C. A3WE	SA1093WE	Power source for Captain's CDI select relay switch relocated.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1105WE	Dual Collins AL-101 radio altimeter systems.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727; T.C. A3WE	SA1128EA	Installation of coat closet. Amended 9/11/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
727 Series; T.C. A3WE	SA1154WE	Cockpit voice recorder.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1265WE	Brownline pallet 23118 or Douglas pallet 5776662-505 with Brownline net 23143.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727 Series; T.C. A3WE	SA1322WE	Engine mounted fire detector unit modified to provide continuous support. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety System Division 1440 Fourth Street Berkeley, CA 94710
727 Series; T.C. A3WE	SA1367WE	Use of Brownline Corp. Pallet Nos. 23640-51 and 23224-51 in place of Douglas Aircraft Co. Pallet No. 577662-505.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1451WE	Installation of constant speed drive, load controller, generator and voltage regulator.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1509WE	Revised interior arrangement.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727 Series; T.C. A3WE	SA1563WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1868SW	Portable solid oxygen system for first-aid use. Issued 4/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
727 Series; T.C. A3WE	SA2422WE	Installation of Valley Todeco bolt VAL 22016 to replace Boeing bolt BAC B30EK8-48 on 727 thrust reverser. Issued 9/23/71.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727, 727C; T.C. 2H3	SA800CE	Installation of three cell forward and three cell aft auxiliary fuel tanks in lower cargo compartment. Issued June 1972.	CE	16878	The Boeing Company 3801 South Oliver Street Wichita, KS 67210
727, 727-100, -22; T.C. A3WE	SA2563WE	Installation of garment bag module. Issued 8/23/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	SA169GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	GL	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	ST650BO	Installation of dual band (C/X) type weather radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
727, 727C, 727-200 Series; T.C. A3WE	SA1239CE-D	Grimes coffee maker and warmer unit installation. Issued 11/20/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727, 727-100, 727C, 727-200; T.C. A3WE	SA2668WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-50 autopilot as replacement for Sperry or Smiths rate gyros. Amended 6/20/73.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3130WE	Installation of dual Litton LTN-72 or a single or dual LTN-72R INS/RNAV navigation system. Amended 5/18/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3145WE	Installation of Sperry Model Block V SP-50 autopilot and Honeywell Air Data computer. Issued 3/12/76.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3153WE	Installation of forward coat closet on left hand side just aft of forward entry door. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3154WE	Installation of interior configuration consisting of 10 first class and 98 coach seats. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3654WE	Installation of interior configuration with 10 first class and 95 coach seats. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series T.C. A3WE	SA3665WE	Installation of a dual Collins 61B inertial navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3679WE	Installation of a Global GNS-500A VLF/Omega navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, 727-100C, 727-200; T.C. A3WE	SA3717WE	Installation of a cabin divider. Issued 8/29/78.	WE	25970	Continental Air Lines International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3755WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-211 omega navigation system and a true airspeed system. Amended 3/23/79.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3964WE	Installation of dual Litton LTN-211 omega navigation systems. Issued 5/23/79.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, -100C Series; 727-223, -225, -227, -228, -231, -235, -251, -264, -284, -295; T.C. A3WE	SA3220WE	Addition of filter to the cabin pressure limit control feature of P/N 103280 outflow valve. Issued 6/28/76.	WE	07505	AiResearch Manufacturig Company Garrett Corporation 2525 West 190th Street Torrance, CA 90509
727, 727C, 727-200, 737; T.C. A3WE	SA2348WE	Modify Boeing 727 Series airplanes by installation of emblem lights. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
727, 727C, 727-200, 737; T.C. A3WE	SA3292WE	Installation of thrust reverser short track. Issued 11/23/76.	WE	78475	Thrustair, Inc. 12990 Branford Avenue Arleta, CA 91331
727, 727C, 727-200, 737; T.C. A3WE	SA3306WE	Installation of thrust reverser cascades. Issued 12/3/76.	WE	41015	Hasko-Air, Inc. 9042 Owensmouth Avenue Canoga Park, CA 91304
727, 727-100, 727C, 727-100C, 727-200 Series; T.C. A3WE	SA3521WE	Installation of a cabin divider. Issued 11/8/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-200; T.C. A3WE	ST43680	Installation of thrust reverser deflector door drive. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727, 727C, 727-200; T.C. A3WE	ST45080	Modification of thrust reverser forward deflector door link. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727-1H2; T.C. A3WE	SA2480WE	Addition of INS attitude reference data to flight instruments. Issued 2/15/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-1H2; T.C. A3WE	SA2552WE	Install Litton P/N 451158 automatic data entry unit. Issued 8/17/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-2B7; T.C. A3WE	SA2168WE	Installation of Henry Engineering lounge tables No. 17701 and No. A17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-2B7; T.C. A3WE	SA2170WE	Installation of class divider. Issued 5/27/70.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-2J0; T.C. A3WE	SA1235CE-D	Forward auxiliary fuel tank removal and reinstallation. Issued 10/9/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-2M7; T.C. A3WE	SA3505WE	Installation of ground proximity warning system. Issued 10/27/77.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3564WE	Installation of auxiliary fuel tanks in the forward and aft belly cargo/baggage compartments. Issued 1/20/78.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3380WE	Installation of dual LTN-51 or dual LTN-72 or a mix of one LTN-71 and one LTN-72 inertial navigation system. Amended 9/5/79.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3967WE	Installation of coat room assembly No. RW2527036. Issued 5/29/79.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2L4; T.C. A3WE	SA3065WE	Installation of 3400 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 7/16/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-14; T.C. A3WE	SA1942WE	Revised interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14; T.C. A3WE	SA1986WE	Interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -35, -193, -214, -235; T.C. A3WE	SA1885WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727-14, -51; T.C. A3WE	SA1717WE	Revised interior arrangement. Amended 4/20/77.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
727-14, -51, -214, -254, -2J7, -2Q8; T.C. A3WE	SA3013WE	Installation of ground proximity warning system. Amended 12/19/78.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -51, -214, -254, -2Q8; T.C. A3WE	SA3939WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/11/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-17; T.C. A3WE	SA3674WE	Installation of 2700 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 6/30/78.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-17, -31, -31C, -180C, -231, -231A; T.C. A3WE	SA1488CE	Installation of a pitot heater failure indication system. Issued 5/4/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-21; T.C. A3WE	SA264NW	Interior arrangement. Issued 2/20/76.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188
727-21; T.C. A3WE	SA1078EA-D	Installation of two closets in rear of cabin to accommodate a bar or food cart and provisions for parking the carts in flight at two locations. Amended 11/8/79.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
727-21, 21C; T.C. A3WE	SA612SO-D	Installation of portable berth (aerotherm stretcher). Reissued 9/6/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727-21, -22, -81; T.C. A3WE	SA2660WE	Modification of cabin interior. Amended 12/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-21, -81; T.C. A3WE	SA3022WE-D	Installation of new seating arrangement. Amended 11/10/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-21C; T.C. A3WE	SA1292WE	Installation of Boeing palletized cargo system 65-49102 with Brownline pallet 22630-51 or 26100-52 Brownline net assembly 23225-51, 23226-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-21C; T.C. A3WE	SA1594WE	Installation of Heath Tecna Corp. pallet AC-10065 and Brownline Corp. net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-21C; T.C. A3WE	SA3006WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-21C; T.C. A3WE	SA3672WE	Installation of Brownline quick change pallets, P/N's 45881-101, 45882-101 and 46129-101. Issued 6/19/78.	WE	17740	Brooks & Perkins Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-21C, -22C, -25C, -27C, -30C, -31C; T.C. A3WE	SA696CE	Installation Aeroquip Corp. cargo tie-down net.	GL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203
727-22; T.C. A3WE	SA1788WE	Interior arrangement installation.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94125
727-22; T.C. A3WE	SA3323WE	Installation of forward facing flight attendant seat on forward galley. Issued 1/20/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-22; T.C. A3WE	SA3364WE-D	Revise cabin seating to accommodate 118 all-coach configuration. Issued 4/25/78.	WE	00500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C; T.C. A3WE	SA3023WE-D	Revise seating arrangement from 18 first class/78 coach to 12 first class/86 coach configuration and further revised to 10 first class/86 coach configuration. Amended 6/11/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-22, 727-22QC; T.C. A3WE	SA1687WE	Modify existing Collins Radio Company type FD-109 Flight Director installation to add "Steering", "Airspeed-Hold", and "Auto Approach" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3079WE	Installations of Collins FPC-75-P/N 622-2615-012 or P/N 622-2615-212, or P/N 622-2615-013, ground proximity warning system computer in airplanes. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3350WE-D	Air data system. Amended 7/20/79.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-22, -24C, -30, -76, -92C; T.C. A3WE	SA3655WE	Installation of Nordskog Company auxiliary galley Model 1-420. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727-22, -30, -76, 92C; T.C. A3WE	SA981CE-D	Reconfiguration of flight crew instrument panels, avionics and passenger cabin. Amended 8/28/78.	CE	16877	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-22C; T.C. A3WE	SA645CE	Make and install pallets in accordance with Brooks & Perkins Drawing Index No. 16987DI-E and Installation Instructions No. BPS 149. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA814CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA842CE	Installation of cargo pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA1622WE	Modification of type design to permit installation of Heath Tecna Corp. AC-10061 pallet with AC-10069 net.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-22C; T.C. A3WE	SA1816WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-22C; T.C. A3WE	SA1962WE	Modify by installation of pallet assemblies 40160101 thru 40160108 used in conjunction with net assemblies 22672-51, -52; 23143-51, 22758-51, -52; 22273-51, 7776967-1 (Douglas) and 3950020 (Aeroquip). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1, or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
727-22C; T.C. A3WE	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517, with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks & Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2255WE	Installation of Satco, Inc., pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-22C; T.C. A3WE	SA2274WE	Installation of Irvin 88" x 125" cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
727-22C; T.C. A3WE	SA2844WE	Installation of coat and luggage stowage unit. Issued 2/25/74.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-22C; T.C. A3WE	SA3359WE-D	Retrofit of Kollsman P/N A41869-10-021 altimeters on the captain's and first officer's instrument panel. Issued 1/11/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3577WE-D	Installs overhead stowage bin kit. Issued 8/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3673WE	Installation of cargo restraint system which meets the requirements of a NAS 3610 class IIA restraint system. Issued 6/21/78.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
727-22C; T.C. A3WE	SA3775WE	Installation of the Brownline 46000-101 cargo system. Issued 10/31/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-022; T.C. A3WE	SA2838WE-D	Installs barrier and tie-down fitting for using preloaded liquor service cart on-board aircraft. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-022; T.C. A3WE	SA3575WE-D	Remove all first class seats, the class divider, the carry-on baggage and garment bag modules and replace with all coach seats to increase seating capacity to 112 passengers. Issued 4/24/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-022;	SA3363WE-D	Installation of dual Collins FD-109A flight director systems. Issued 4/24/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-022, -022C, -222; T.C. A3WE	SA2201WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-22, -222, -22QC; T.C. A3WE	SA2096WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-23; T.C. A3WE	SA411EA-D	Relocate the flight data recorder Station 1120 on cabin floor, left hand side, aft of last row of seats to provide improved crash survivability. Amended 12/8/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23; T.C. A3WE	SA563EA	Installation of digital adaptive recording system (DARS) on one Boeing 727-23. Issued 4/7/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA501EA-D	Delete auxiliary vertical gyro on 727-23 and 727-123 and authorize use of either Sperry or Bendix gyros on 727-35 and 727-95. Amended 9/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA515EA-D	Install REF Dynamics beverage bar. Amended 2/16/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA523EA-D	Install overwing emergency lights. Amended 1/12/69.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA524EA-D	Change interior passenger seating arrangement.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA558EA-D	Modification of leading edge slat and flap position indication system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95 and 727-123; T.C. A3WE	SA866WE	Installation of ILS Back Course and Compass Switches. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA872WE	Installation of Collins P/N 54W-1 instrument comparator. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1195WE	Installation of dual Collins FS-108 flight director systems. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1575WE	Installation of dual Collins AL-101 radio altimeter system. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-95, 727-123; T.C. A3WE	SA804WE	Installation of Honeywell HG180 Modular Air Data Computer System. Amended 6/26/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -223; T.C. A3WE	SA552EA-D	Installation of autopilot go-around unit. Issued 4/24/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-24C, 727-116C; T.C. A3WE	SA1441CE-D	Change crew instrument panels and systems revisions. Reissued 9/19/79.	CE	16877	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-24C; T.C. A3WE	SA1661WE	Installation of Bendix Dual DRA 12 Doppler System.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2886WE	Interior arrangement. Issued 5/18/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2899WE	Installation of courier seat. Issued 6/15/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2942WE	Installation of Nordskog Galleys 1-289A and 1-290A. Amended 11/14/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, -92C; T.C. A3WE	SA3855WE	Installation of Brownline cargo/seat pallet system 45980, configuration -101. Issued 2/12/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-25; T.C. A3WE	ST588SO	Installation of 119 passenger interior and installation of two EAL 52-RA-7 four man life rafts. Issued 4/30/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST663SO	Installation of LORAN A navigation system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST740SO	Cabin interior arrangement and furnishings changes. Issued 6/3/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST426SO	Installation of Honeywell HG180V3 air data computer with electronic altimeters, altitude reporting digitizer and altitude alerting system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST741SO	Cabin interior configuration changes. Amended 1/24/75.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST751SO	Modification of main cabin passenger interior configuration from 14 first class and 89 tourist class to 12 first class and 95 tourist class accommodations. Issued 5/28/76.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, -25C; T.C. A3WE	ST954SO	Installation of Mansfield Aircraft Products model 1470 galley/coatroom. Issued 8/29/77.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C, -225; T.C. A3WE	ST510SO	Installation of dual HF communications system using vertical fin leading edge slotted antenna. Amended 1/13/78.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	ST534SO	Interior - two pallet cargo/65 passenger MAC configuration installed. Issued 4/13/73.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	SA2364WE	Installation of Satco, Inc. cargo pallet assembly P/N 31095-501, -503, -505, -507 in conjunction with net assemblies NAS 3610-2A1N, -2A2N, -2A3N, -2A5N, and -2A6N. Amended 5/18/72.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-30; T.C. A3WE	SA982CE-D	Interior arrangement installation. Amended June 1976.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-30; T.C. A3WE	SA3157WE	Installation of 1200 gallon auxiliary fuel tank in forward cargo compartment. Issued 3/26/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-30 T.C. A3WE	SA3319WE	Installation of auxiliary fuselage fuel tanks (1600 gallons) in forward and aft cargo compartment. Issued 12/28/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91406
727-30, -81; T.C. A3WE	SA2734WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 2/13/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-030, -224; T.C. A3WE	SA3408WE	Installation of Lermer Apparatebau GMBH beverage cart No. L15701. Issued 5/26/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 91406
727-31; T.C. A3WE	SA478CE	Modification to flap quadrant.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31; T.C. A3WE	SA570CE	Install Models 14801 or 14802 Henry Engineering Company bar unit. Amended 10/18/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C; T.C. A3WE	SA373CE	Installation of a single SCAT system. Amended 8/12/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C; T.C. A3WE	SA604CE	Installation of dual radio altimeter provision - single equipment driving dual indicators. Amended 2/3/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-31, -31C, -180C; T.C. A3WE	SA235CE	Installation of Kollsman Integrated Flight Instrument System (KIFIS). Amended 5/8/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C, -180C; T.C. A3WE	SA734CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, -31C, -180C; T.C. A3WE	SA779CE	Installation of Bendix gyro horizon and inverter. Issued June 1971.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA553CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA828CE	Install Butler National Corp. flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA1137CE	Installation of hydraulic interconnect override system. Issued June 1975.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180C, 727-231; T.C. A3WE	SA1542CE	Installation of a Growth Industries dual cavity oven. Issued 12/12/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-31, -31C, -231; T.C. A3WE	SA490CE	Installation of Safe Flight Corp. auto power servo kits. Amended 10/9/74.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31C, -180C; T.C. A3WE	SA741CE	Install Henry Engineering auxiliary bar model 15501A and one additional triple passenger seat.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-35; T.C. A3WE	SA639SO	Installation of hatrack assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA640SO	Installation of liquor service galley assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA1566WE	Installation of Sperry SP-50 Mod Block IV Single Channel Autopilot. Amended 5/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-35, 727-95, 727-123; T.C. A3WE	SA1576WE	Replacement of Captain's altimeter and First Officer's altimeter and and installation of third altimeter. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-35, -235; T.C. A3WE	ST738SO	Installation of Gulton Model EMBS 144 nickel-cadmium electrical storage battery and integral automatic control system. Issued 1/23/74.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami International Airport Jamaica, NY 11430
727-46; T.C. A3WE	SA847CE-D	Structural and system modification for installation of service door and retractable step. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-46; T.C. A3WE	SA2970WE	Installation of 300 gallon auxiliary fuel tank in aft cargo compartment. Issued 12/20/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-51, -51C, -151C, -251; T.C. A3WE	SA89GL	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
727-75, -232, -295; T.C. A3WE	ST855SO	Installation of Bendix ground proximity warning system. Issued 10/16/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-77; T.C. A3WE	SA3559WE	Installation of a 1932-gallon auxiliary fuel tank system in forward and aft cargo compartments. Issued 2/6/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-81; T.C. A3WE	SA2724WE	Installation of executive cabin interior. Amended 9/20/74.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-81, -100; T.C. A3WE	SA263NW	Garment bag module modification. Issued 2/25/76.	NW	47722	Kelley-Morrow Enterprises The Common Building 1200 - 112th N.E. Bellevue, WA 98004
727-81, -100; T.C. A3WE	SA2732WE	Installation of duel LTN-104 navigation systems. Amended 3/13/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-90, -90C; T.C. A3WE	SA2245WE	Interior arrangements. Issued 9/18/70.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98158
727-90C; T.C. A3WE	SA139NW	Installation of quick change interior arrangement. Amended 4/21/75.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98108
727-90C; T.C. A3WE	SA327NW	Interior arrangements 98 PAX and two cargo pallet/63. Issued 7/23/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA129NW	Installation of cabin interior arrangement. Issued 9/23/74.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA310NW	Interior arrangement. Issued 5/28/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, 737-202C, -210C; T.C. A3WE, A16WE	SA1823WE	Installation of "Heathair" AC-10360 cargo pallet assembly and AC-10374 cargo net assembly. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-92C; T.C. A3WE	SA1839WE	Stewardess seat installed on Nordskog 769 galley.	WE	61605	Nordskog Co., Inc. 16000 Strathern Street Van Nuys, CA 91406
727-95; T.C. A3WE	SA704EA	Installation of Henry Engineering Company Galleys Models Nos. 14001 and 14002. Reissued 12/8/72.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-100 Series Models type certificated as of 6/17/68; T.C. A3WE	SA587CE	Installation of Hoskins Twilighter Mark V high intensity light system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
727-100; T.C. A3WE	SA612NW	Installation of coat closet. Issued 5/26/78.	NW	48532	KME Manufacturing, Inc. The Commons Building 1200 112th Street, N.E. Renton, WA 98055
727-100; T.C. A3WE	SA643NW	Installation of six carry-on baggage modules. Issued 9/13/78.	NW	78672	Tramco, Inc. 1033 Thomas Avenue, S.W. Renton, WA 98055
727-100; T.C. A3WE	SA697NW	Install life raft stowage compartments. Issued 12/14/78.	NW	41625	Heath Tecna 19819 84th Avenue South Kent, WA 98031
727-100; T.C. A3WE	SA1130SO	Installation of an aft galley storage module. Issued 1/22/80.	SO	64500	Piedmont Airlines Smith-Reynolds Airport Winston-Salem, NC 27102
727-100; T.C. A3WE	SA2498SW	Collins FPC-75 ground proximity warning system. Issued 1/23/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
727-100 Series; T.C. A3WE	SA3501WE	Installation of Litton LTN-201 omega navigation system. Amended 12/29/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100 Series; T.C. A3WE	SA3810WE	Installation of a maximum of eight auxiliary fuel tanks in forward and aft cargo compartments. Amended 1/4/80.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-100 Series; T.C. A3WE	SA3851WE	Installation of Litton LTN-211 Omega Navigation System. Amended 4/19/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
707-100, -100B, -200; T.C. 4A21	ST660SO	Installation of "C/X" band nose radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-100, -100C Series; T.C. A3WE	SA3661WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-201 Omega navigation system and a true airspeed system. Issued 10/11/78.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
727-100, -200; T.C. A3WE	SA1050CE	Install Crimsco cargo container, P/N 600301. Issued November 1974.	CE	27000	Crimsco, Inc. 5001 E. 59th Street Kansas City, MO 64130
727-100, -200; T.C. A3WE	SA2240WE	Installation of door-mounted emergency light. Amended 9/23/70.	WE	44266	International Inflatables Company Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
727-100, -200; T.C. A3WE	SA3333WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
727-100, -200; T.C. A3WE	SA3374WE	Installation of bearing P/N VTB02220 as replacement for Boeing P/N 10-60545-113S in main landing gear lock system assembly. Issued 3/29/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200; T.C. A3WE	SA3379WE	Installation of bearing, P/N VTB02800 in lieu of Boeing bearing P/N 10-60545-143. Issued 4/20/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200 Series; T.C. A3WE	SA3508WE	Installation of Valley-Todeco bearings, P/Ns VTB-02900, VTB-02910, VTB-02920, VTB-02930. Issued 11/8/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, 727-200; T.C. A3WE	SA3716WE	Installation of a Dretloh Model 5002, P/N 121214-1 food carrier. Issued 8/25/78.	WE	30702	Dretloh Aircraft Supply, Inc. 980 North Lemon Orange, CA 92667
727-100, 100QC; 737; T.C. A3WE, A16WE	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
727-171C, 727-173C; T.C. A3WE	SA1693WE	Revised interior arrangement with Nordskog hostess seat 6734 and door 61246 and associated modifications added to Mapco Galley Model 680T-1.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-172C; T.C. A3WE	SA671EA	Installation of pallet net for use with Boeing pallets.	SO	44750	Irvin Industries, Inc. 1315 Versailles Road Lexington, KY 40501
727-172C; T.C. A3WE	SA849CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aeros Portugeses requirements. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-172C; T.C. A3WE	SA1662WE	Installation of Heath Tecna Corp. AC-10160 pallet with AC-10069 net on Boeing 707-172C. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-173C; T.C. A3WE	SA1907WE	Interior arrangement reflecting 122 passenger quick change conversion configuration. Amended 6/3/69.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
727-173C; T.C. A3WE	SA2385WE	Installation of interior arrangement. Amended 9/14/71.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
727-180C; T.C. A3WE	SA558CE	Installation of Kollsman integrated flight instrument system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-180C; T.C. A3WE	SA559CE	Installation of a single SCAT system. Amended 8/11/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-180C; T.C. A3WE	SA560CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-200; T.C. A3WE	SA349NW	Installation of wind screen in forward cabin RH side. Issued 8/27/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 832 Issaquah, WA 98027

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-200; T.C. A3WE	SA359NW	Installation of carry-on baggage unit. Issued 9/28/76.	NW	48532	KME Manufacturing, Inc. 1200 - 112th N.E. Bellevue, WA 98004
727-200; T.C. A3WE	SA547NW	Installation of Mark I interior kit. Issued 11/22/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue S. Kent, WA 98031
727-200; T.C. A3WE	ST742SO	Modification and installation of seat model 914-1. Issued 6/26/74.	SO	21560	Charlotte Aircraft Corporation P.O. Box 1225 Miami, FL 33148
727-200; T.C. A3WE	SA774SO	Installation of the Litton LTN-211 Omega Navigation System. Issued 11/30/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airlines Miami, FL 33148
727-200; T.C. A3WE	SA816NW	An interior installation. Issued 8/8/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
727-200; T.C. A3WE	SA2335SW	Modification to increase depth of Weber 808737-618-M pilot seat and 808737-619-M copilot seat. Issued 7/23/76.	SW	14222	B & H Parts Company Meacham Field Fort Worth, TX 76106
727-200; T.C. A3WE	SA2672WE	Installation of coat and luggage stowage unit. Issued 3/23/73.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
727-200; T.C. A3WE	SA3054WE	Installation of dual Litton LTN-72 inertial navigation system. Amended 6/22/76.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-200; T.C. A3WE	SA3081WE	Replacement of evacuation slide container latches with latches of a new design. Reissued 6/2/76.	WE	70130	Sargent Industries PICO Division Kahr Bearing Division 2045 Evans Avenue San Francisco, CA 94124
727-200; T.C. A3WE	SA3594WE-D	Removal of all first class seating and class divider. Relocate cabin seating to provide 14 rows at 38-inch pitch. Installation of additional furnishings. Amended 1/7/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-200 Series; T.C. A3WE	SA3882WE	Installation of aft cargo hold trash chute container assembly, P/N B-25-0256. Issued 4/4/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-200, 737; T.C. A3WE, A16WE	SA764NW	Inner window pane replacement. Issued 5/3/79.	NW	79672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
727-214; T.C. A3WE	SA1922WE	Interior arrangement. Amended 6/6/69.	RM	37015	Frontier Airlines 5900 East 39th Avenue Denver, CO 80207
727-214, -254, -2Q8; T.C. A3WE	SA3069WE	Installation of galley in forward passenger compartment. Amended 12/20/78.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3560WE	Installation of PSA galley P/N C-25-0085. Issued 1/18/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3625WE	Installation of 168 passenger interior arrangement. Issued 4/3/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3820WE	Installation of 165 passenger interior arrangement, and aft stowage closet. Issued 1/8/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor San Diego, CA 92101
727-222; T.C. A3WE	SA2448WE	Installation of McDonnell Douglas Eros II collision avoidance system. Issued 11/22/71.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2743WE-D	Installation "New Look" cabin interiors. Amended 6/10/77.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2826WE-D	Installations of provisions for ground proximity warning system. Issued 2/21/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-222; T.C. A3WE	SA2832WE-D	Installation of ground proximity warning system with cockpit annunciations deactivated and warning signals connected to digital recorder. Issued 3/13/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2841WE-D	Revise cabin seating configuration to accommodate 14 first class/112 coach configuration. Amended 8/20/76.	WE	80500	United Airlines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3037WE-D	Revise cabin seating configuration to accommodate 10 first class/118 coach configuration. Issued 2/24/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3353WE-D	This modification installs a retractable cart tie-down at the Sta. 350-50 and LBL 32.34. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3354WE-D	This modification installs modified seats in the first class compartment. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3355WE-D	Installation of carry-on baggage and garment bag modules just aft of forward entry door on left side of passenger cabin. Issued 10/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3362WE-D	Installation of a Safe Flight P/N 6500-2 windshear warning computer for in-service evaluation. Issued 3/15/78.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3578WE-D	Installation of arinc communications addressing reporting system (ACARS). Amended 2/9/79.	cWE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3589WE	Installation of passenger audio entertainment system. Issued 7/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3590WE-D	The cabin interior seating configuration will change from 10F/124Y to 14F/118Y. One row of coach seats will be removed and one row of first class seats added. The class divider will be moved accordingly. Issued 2/9/79.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3592WE-D	Replace the auxiliary galley/stowage compartment located in the RH aft passenger cabin between station 1101 and 1137 with a new stowage compartment. Amended 12/17/79.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA4063WE	Deletion of the pair of excess Type I emergency exits located at station 720 and 15. Issued 11/29/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-223; T.C. A3WE	SA521EA-D	Install single area navigation system. Amended 9/10/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74151
727-224; T.C. A3WE	SA3325WE	Installation of auxiliary bar unit No. 1-368. Issued 1/13/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-225; T.C. A3WE	ST593SO	Installation of 18 first class/116 tourist class passenger interior with modified coatroom and windscreen. Issued May 1974.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225; T.C. A3WE	ST753SO	Installation of main cabin equipment to provide accommodations for 137 passengers (12 first class and 125 tourist class). Issued 8/4/76.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225A; T.C. A3WE	SA775SO	Installation of a coatroom and class divider partition in the main cabin at B.S. 544. Issued 12/3/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-225; T.C. A3WE	SA1238CE-D	Interior conversion to 177 tourist class passengers. Issued 11/7/78.	EA	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-231; T.C. A3WE	SA561CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA562CE	Installation of single seat system. Amended June 1974.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA639CE	Modification of SCAT/Auto Throttle to include auto-land throttle closure feature.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA721CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA1287CE	Revision of engine fire detection circuit. Issued December 1976.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA1475CE	Installation of Simmonds Precision performance advisory system (fuel management). Issued 3/6/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-237; T.C. A3WE	SA2729WE	Installation of interior arrangement. Issued 7/23/73.	WE	62160	Pacific Southwest Airlines 3220 N. Harbor Drive San Diego, CA 92101
727-247; T.C. A3WE	SA469NW	Installation of coat closet unit on Western Airlines aircraft. Issued 6/24/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
727-247; T.C. A3WE	ST549SO	Manufacture and installation of P/N 10826-1 cart stowage unit. Amended 11/18/77.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
727-247; T.C. A3WE	ST550SO	Manufacture and installation of P/N 10825 coat closet unit. This STC is limited to Boeing 727-247 aircraft with wide body interiors. Issued 9/21/73.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
727-247; T.C. A3WE	SA3495WE	Conversion of UOP galley by installation of UOP oven, Grimes coffeemaker and overboard drain system. Issued 9/30/77.	WE	8130	Aerospace Division Universal Oil Products 4856 Victor Street Jacksonville, FL 32207
727-247; T.C . A3WE	SA3644WE	Installation of IPECO pilot and co-pilot crew seats. Issued 5/16/78.	WE	54860	MARCON Associates, Inc. Agents for IPECO Europe Ltd. 18436 Hawthorne Boulevard Suite 212 Torrance, CA 90504
727-247, -2Q8; T.C. A3WE	SA29NE	Installation of Aerospace Division galleys, P/Ns 190E1000-103, 190E2000-105, -106, and -107 in Western Airlines Boeing 727-247 and -2Q8 aircraft. Amended 5/4/79.	NE	81120	Aerospace Division Universal Oil Products Route 202 Bantam, CT 06750
727-248, -2Q8; T.C. A3WE	SA3929WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/3/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
727-281;737-281; T.C. A3WE, A16WE	SA33NW	Installation of class divider in constant section at station 500 on Model 727-281 and station 525 on Model 737-281. Issued 3/14/73.	NW	83765	Vinnedge and Associates P.O. Box 374 North Bend, WA 98045
727-291 and 727-295; T.C. A3WE	SA1602WE	Revised interior arrangement with Frontier Galley Models 13301, 13302, 13303, and 13304 installed. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727, 727C, 727-200; T.C. A3WE	ST731SO	Installation of automatic in-flight lock for ventral stair-door. Amended 5/18/73.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727, 727C, 727-200; T.C. A3WE	SA2315WE	Installation of thrust reverser adjustable offset links on above aircraft equipped with Boeing Thrust Reversers, BAC P/N 65-27800-1, 65-27800-3 and 65-27800 only. Issued 2/22/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2337WE	Installation of Triumph Corporation solid offset thrust reverser links. Issued 4/9/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2391WE	Modification of nose gear steering cylinder. Issued 7/30/71.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727, 727C, 727-200; T.C. A3WE	SA2471WE	Installation of Triumph Corporation 5026 series bearings and rod ends on thrust reversers. Issued 2/1/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T.C. A3WE	SA2487WE	Installation of main landing gear lock actuator bearing assembly. Issued 3/3/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2518WE	Installation of thrust reverser forward deflector door link. Issued 5/1/72.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727, 727C, 727-200; T.C. A3WE	SA2627WE	Installation of fuel control rod end bearings. Issued 1/4/73.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T.C. A3WE	SA2779WE	Installation of auxiliary power fire detector unit. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 Fourth Street Berkeley, CA 94710
727 Series, 737 Series; T.C. A3WE, A16WE	SA1052SO	Installation of GE battery P/N 43B022RB36 in place of Marathon P/N CA-727-7, CA-727-20, or CA-27-20 batteries or SAFT P/N 23180 batteries; or installation of GE battery P/N 43B020RB10 replacing Marathon P/N CA-727-7, CA-727-20 or CA-27-20 or SAFT P/N 23186 or 23180 batteries. Amended 5/11/79.	SO	37380	General Electric Company P.O. Box 114 GAinesville, FL 32602
727 Series; 737 Series; T.C. A3WE, A16WE	SA2501WE	Installation of replacement cooling turbine nozzle assembly. Reissued 1/5/79.	WE	67145	Repair Tech International 13900 Saticoy Street Van Nuys, CA 91402
737 Series; T.C. A16WE	SA270NW	Interior arrangement. Issued 3/11/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA353NW	Installation interior components consisting of 2 wind screens and 3 decorative panels on existing galleys. Issued 9/7/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA370NW	Removal of passenger interior, installation of cargo compartment liners and cargo tie down equipment. Issued 11/8/76.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	ST854SO	Installation of Bendix GPW-83 ground proximity warning system. Amended 1/21/76.	SO	64500	Piedmont Aviation, Inc. P.O. Box 2720 Smith Reynolds Airport Winston-Salem, NC 27102
737; T.C. A16WE	SA751NW	Installation of a coat closet/storage bin. Issued 4/12/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA781NW	Installation of a coat closet. Issued 6/7/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
737; T.C. A16WE	SA853NW	Installation of a coat closet. Issued 10/29/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA1401SW	Replace Marathon CA-737 battery with General Electric 43B022RB10 battery. Issued 12/9/71.	GL	37379	General Electric Company 206 W. Mitchell Avenue Cincinnati, OH 45232

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737; T.C. A16WE	SA1519SW	Coat closet. Issued 10/14/72.	SW	16750	BIDCO, Inc. 2732 Ludelle Fort Worth, TX 76105
737; T.C. A16WE	SA3983WE	Installation of storage unit, P/N 10165. Issued 6/26/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
737-2A1; T.C. A16WE	ST136RM	Installation of interior arrangement. Issued 4/25/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2A6; T.C. A16WE	SA2153WE	Installation of fuselage fuel tanks in forward and aft cargo compartments.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA6RM	Interior arrangement modification. Amended 3/10/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA66RM	Revision of aft coat closet capacity from 100 lbs. to 250 lbs. Issued 2/3/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA67RM	Installation of trash module in aft coat closet. Issued 3/12/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -222, -247, -291; T.C. A16WE	SA75RM	Installation of Mapco closet module, P/N 1345, under forward left side hatrack. Issued 5/26/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2CO, -2H4, -212, -217, -291, -222; T.C. A16WE	SA101RM	Install dual SELCAL system. Amended 6/2[illegible]/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-021; T.C. A16WE	SA523AL	Installation of ground proximity warning system. Reissued 6/19/75.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
737-T43A; T.C. A16WE	SA265GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500, and Harrowe barometric altitude rate computer P/N 4030-03-1. Issued 8/25/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
737-2S2C, -2Q8C; T.C. A16WE	SA4019WE	Installation of Brownline cargo pallet restraint system, P/N 46926-101, -102. Amended 11/21/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-100, -200, -200C Series; T.C. A16WE	SA2705WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-77 autopilot as a replacement for Sperry or Smiths rate gyros. Amended 7/15/74.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
737-100, 737-200; T.C. A16WE	SA2828WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-100, -200; T.C. A16WE	SA3334WE	Installation of stretcher carrier, AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
737-100/200/200C; T.C. A16WE	SA2267WE	Installation of door mounted emergency light. Issued 10/30/70.	WE	44266	International Inflatables Co. Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
737-100/200/200C; T.C. A16WE	SA2564WE	Installation of garment bag module. Amended 9/20/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
737-100, -200, -200C; T.C. A16WE	SA170GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-6, with Courter flap asumetry detector kit, P/N 298-1026-02. Reissued 12/21/78.	GL	26675	Courter, Incorporated 375 North Lake Street Boyne City, MI 49712
737-100, -200, -200C; T.C. A16WE	ST686SO	Installation of nose cap "C/X" band weather radar radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-100, -200, -200 Series; T.C. A16WE	SA887EA	Installation of structural provisions for tail logo lights. Amended 4/19/72.	EA	18750	Butler Aviation - Friendship, Inc. Sub. of Butler Aviation Int'l Friendship Int'l Airport Baltimore, MD 21240
737-100/200/200C; T.C. A16WE	SA2542WE	Installation of wing-tip mounted emblem lights. Amended 12/8/75.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
737-200; T.C. A16WE	SA53RM	Installation of Sundstrand Data Control ground proximity warning system and glide slope monitoring system. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA55RM	Installation of Universal Oil Products Co. galley tray cart. Amended 8/18/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA62RM	Installation of Universal Oil Products Co. beverage cart, P/N 11143-1. Issued 8/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA103NW	Installation of modified lower interior sidewall. Issued 4/12/74.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	SA178NW	Installation of perfume dispenser into three lavatories. Issued 5/12/75.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	ST430SO	Installation of unusual events recording system.	GL	77600	Technology, Inc. 7400 Colonel Glenn Highway Dayton, OH 45431
737-200; T.C. A16WE	ST875SO	Replacement of Monogram P/N 3299-1 or Leach P/N TD1514-1002 timer assemblies with Piedmont P/N 737D-81017 solid state timer. Amended 7/13/76.	SO	64500	Piedmont Aviation, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200 Series; T.C. A16WE	ST1020SO	Installation of 112 passenger interior arrangement. Issued 8/31/78.	SO	64500	Piedmont Aviation Smith-Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	ST1034SO	Fabrication and installation of an aft right hand windscreen. Issued 11/15/78.	SO	64500	Piedmont Airlines Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1113SO	Fabrication and installation of an aft left-hand windscreen. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1114SO	Fabrication and installation of a forward coat closet. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA2747WE-D	This modification provides an all coach seating configuration for 113 passengers. Issued 5/24/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
737-200; T.C. A16WE	SA3134WE	Installation of Collins ground proximity warning system. Issued 1/7/76.	WE	04080	Air California P.O. Box 2678 Hangar #6, Oakland Int'l Airport Oakland, CA 94614
737-200; T.C. A16WE	SA4042WE	Installation of new overhead enclosed stowage compartments, new fluorescent wash lighting and modified passenger service units. Issued 11/8/79.	WE	42150	HITCO 1600 West 135th Street Gardena, CA 90249
727-200, -200C; T.C. A16WE	SA3464WE	Installation of alternate Systron Donner lower engine fire/overheat detector system, P/N 1705-1, in place of approved P/N 1705 lower engine fire/overheat detector system. Issued 9/2/77.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 4th Street Berkeley, CA 94710
737-200C; T.C. A16WE	SA28NW	Interior modification consisting of installation of cargo/passenger partition and coat closet/service tray stowage. Amended 6/29/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-200C; T.C. A16WE	SA79NW	Seat pallets for Alaska Airlines. Issued 11/9/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA101NW	Interior modification consisting of installation of windscreens and aft coat closet. Issued 4/22/74.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA276NW	Installation of forward LH/RH wind screen in existing approved interior arrangement. Issued 5/13/76.	NW	83765	Vinnedge & Associates P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA337AL	Installation of palletized seating system on high profile cargo roller system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405
737-200C; T.C. A16WE	SA452AL	Installation of palletized cargo/ passenger system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405
737-200C; T.C. A16WE	SA492AL	Installation of BE-1006 landing aid system. Amended 12/11/73.	AL	85890	Wien Consolidated Airlines, Inc. 4100 Int'l Airport Road Anchorage, AK 99502
737-201, 737-214; T.C. A16WE	SA1899WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
737-210C; T.C. A16WE	SA3900WE	Installation of heavy duty cargo handling and quick change system, P/N 90045. Issued 4/10/79.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
737-214; T.C. A16WE	SA856CE-D	Installation of two Collins 618T-2 HF radio systems - installation of Bendix "X" band weather radar system - installation of Kollsman Air Data computer. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
737-214; T.C. A16WE	SA1825WE	Installation of Henry Engineering Co. Lounge Tables No. 17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90307
737-222; T.C. A16WE	SA1601WE	Modification of Collins FD109 flight director systems to add a "steering" and "airspeed-hold" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2097WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2182WE	Installation of Bendix Third Attitude Indicator (per requirements of FAR 121.305(j)). Issued 6/10/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2232WE	Replacement of nickel-cadmium battery with 2 lead-acid batteries. Amended 1/28/76.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2525WE	Installation of interior arrangement. Amended 12/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3034WE-D	Replace one first class seat assembly with carry-on baggage module, relocate existing garment bag module and remove LH and RH class divider allowing the two modules to serve as class dividers. Issued 1/26/77.	WE	80500	United Air Lines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3360WE-D	Conversion of passenger cabin from 8/85 dual class configuration to 103 seat all coach configuration. Issued 1/5/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3579WE-D	Installation of Arinc Communications Addressing and Reporting System (ACARS). Amended 8/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-242C; T.C. A16WE	SA2372WE	Installation of Satco, Inc. cargo pallet assembly P/N 31094-501 in conjunction with NAS 3610-2B2N, -2B5N, and 1B2N net assemblies. Issued 7/1/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
737-247; T.C. A16WE	SA191NW	Installation of modified two passenger seat and underseat baggage restraint. Issued 6/15/75.	NW	08350	Air Repair, Inc. 811 West Perimeter Road Renton, WA 98055
737-247; T.C. A16WE	ST551SO	Manufacture and installation of P/N 10816 coat closet unit. Issued May 1974.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST552SO	Manufacture and installation of P/N 10815 cart stowage unit. Issued May 1974.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST567SO	Manufacture and installation of P/N 10949-1 RH aft galley (FS 991.09-1023.25). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST568SO	Manufacture and installation of P/N 10948-1 RH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST569SO	Manufacture and installation of P/N 10950-1 LH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-248C; T.C. A16WE	SA2129WE	Installation of Brownline Division cargo pallet assembly 41121101 and cargo net assemtly 41119101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-248C; T.C. A16WE	SA2130WE	Installation of Brownline Division cargo pallet assembly 41120101 and cargo net assemtlies: Brownline 22361-51, 22178-51, 41122101, 41123101, AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-275C; T.C. A16WE	SA233NW	Installation of cargo handling equipment for three forward cargo pallet positions. Issued 10/24/75.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737-293; T.C. A16WE	SA2007WE	Installation of header and drape.	WE	62080	Pacific Airmotive Corporation, Inc. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91503
737-293; T.C. A16WE	SA2960WE	Installation of galley module in Nordskog galleys P/N's 897 and 898. Issued 12/31/74.	WE	61529	Neushul Corporation 1911 West 139th Street Gardena, CA 90249
737-293; T.C. A16WE	SA3197WE	Installation of auxiliary stowage compartment. Issued 8/17/76.	WE	04080	Air California P.O. Box 2678, Airport Station Oakland International Airport Oakland, CA 94614
747 Series; T.C. A20WE	SA41GL	Install Brooks & Perkins cargo container P/N 17609-E-100. Reissued 2/2/76.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA44NW	Installation of cargo containers. Amended 11/16/76.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747 Series; T.C. A20WE	SA47GL	Install cargo container P/N 17617-E-100. Amended 7/14/75.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA48GL	Install cargo container P/N 17630-E-100. Issued 4/19/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA108NW	Installation of Mark IV visual entertainment system. Issued 4/26/74.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
747 Series; T.C. A20WE	SA139GL	Install Brooks & Perkins cargo container, P/N 17701-E-100. Issued 10/21/76.	GL	17750	Brooks & Perkins 12633 Inkster Road Livonia, MI 48150

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747 Series; T.C. A20WE	SA255NW	Installation of Xenon light modification in visual entertainment system. Issued 1/26/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
747; T.C. A20WE	SA508NW	Installation of class divider/coat closet assembly. Issued 8/29/77.	NW	48532	KME Manufacturing Company 849 Seneca, S.W. Renton, WA 98055
747 Series; T.C. A20WE	SA689CE	Installation of Brooks & Perkins cargo container, P/N's 17026-100, Type A; 17026-100-1, Type A; and 17083-100, Type A. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA692CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA694CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA702CE	Installation of Bendix standby horizon indicator and inverter.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
747 Series; T.C. A20WE	SA711CE	Installation Brooks & Perkins cargo container.	GL	17750	Brooks & Perkins, Inc. 1950 West Fort Street Detroit, MI 48216
747 Series; T.C. A20WE	SA792CE	Make and install P/N 17455-100 cargo container. Issued August 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747; T.C. A20WE	SA835NW	Installation of storage units at station 617. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA836NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA837NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747 Series; T.C. A20WE	ST867SO	Installation of Bendix ground proximity warning system. Issued 11/4/75.	SO	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
747 Series; T.C. A20WE	SA1435SW	Refrigerated air cargo container for lower lobe. Issued 2/24/72.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA1780SW	Portable solid oxygen system. Issued 1/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
747 Series; T.C. A20WE	SA2334SW	LD-3 cargo container, P/N DCT 1250. Issued 7/20/76.	SW	04250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74115
747 Series; T.C. A20WE	SA2756WE	Modify aircraft by installation of Hermes refrigerated LD-3 cargo container, Koolflite P/N 1000. S/N 8-3-001 only. Issued 9/6/73.	WE	42120	Hermes Enterprises P.O. Box 5141 Sherman Oaks, CA 91413
747 Series; T.C. A20WE	SA2801SW	Install container baggage/freight LD-3 type. Issued 6/19/78.	SW	04250	Air Cargo Equipment Corp. P.O. Box 15630 Tulsa, OK 74112
747 Series; T.C. A20WE	SA3041WE-D	Replacement of NAS3610-2L1C cargo containers with L size pallets and nets. Issued 7/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747SP; T.C. A20WE	SA285GL	Install MAPCO Model 1550 low boy galley. Amended 1/10/79.	GL	54700	Mensfield Aircraft Products Co. Mansfield Lahm Airport Mansfield, OH 44901
747SP-21; T.C. A20WE	SA1079EA-D	Installation of flight attendant crew berth compartment in the main cabin, zone "B" aft end. Amended 4/17/79.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747SP-21; T.C. A20WE	SA1080EA-D	Installation of Delco F130A performance management system. Issued 1/23/80.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
747SP-27; T.C. A20WE	SA1174EA	Installation of 16mm movie system in zone B cabin. Issued 10/30/79.	EA	44000	Inflight Motion Pictures Division of Inflight Services, Inc. 175-28 148th Avenue Jamaica, NY 11434
747-2F6B; T.C. A20WE	SA4072WE	Installation of a video projection system. Issued 1/16/80.	WE	15375	Bell and Howell Company Avicom Division 360 Sierra Madre Villa Pasadena, CA 91109
747-E4A, -E4B; T.C. A20WE	SA307GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500. Issued 5/2/79.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
747-SP44, 747-244B; T.C. A20WE	SA3740WE	Installation of main dock cargo/baggage system. Issued 4/19/79.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-E4A, -E4B; T.C. A20WE	SA2951WE	Installation of Steward Davis Airstairs P/N 77004. Amended 3/23/78.	WE	33770	E - Systems, Inc. Greenville, Division P.O. Box 1056 Greenville, TX 75401
747-100; T.C. A20WE	SA817EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A300-001-101. Amended 3/9/71.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA824EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A400-001-101. Reissued 9/8/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA835EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A401-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA842EA	Installation of Goodyear Aerospace Corp. Universal lower deck baggage/cargo container P/N 625A402-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA2117WE	Installation of 747 lower deck modular and unitized baggage/cargo containers.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
747-100; T.C. A20WE	SA2222WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp. Net Assembly 40234-10, and net assemblies approved to NAS 3610-2AN and NAS 3610-2A3N. Issued 8/16/70.	WE	70250	Satco, Incorporated 1509 El Segundo Boulevard El Segundo, CA 90245
747-100; T.C. A20WE	SA2708WE	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-103. Issued 6/7/73.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747-100 Series; T.C. A20WE	SA3547WE	Installation of cargo container P/N 025-45571	WE	25970	Continential Airlines 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
747-100 Series; 747-200 Series; T.C. A20WE	SA976CE-D	Fuselage structure and related modification for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA977CE-D	Interior modifications for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA978CE-D	Cargo handling and power drive system. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA2646WE	Installation of lock assembly No. 41853-101, -102, -103, -201, -202, -203, -204, -301, -302, -303, -304. Amended 4/20/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200 Series; T.C. A20WE	SA3754WE	Installation of forward and aft lower cargo compartment door sill restraint fittings. Issued 10/9/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-100, 747-200 Series; T.C. A20WE	SA3813WE	Installation of Brownline side restraint, P/N 44981-101. Issued 12/20/78.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Boulevard Torrance, CA 90505
747-100, -200B; T.C. A20WE;	SA2446WE	Installation of Brownline single pallet lock assembly. Amended 1/3/75.	WE	79500	Tridair Industries Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200B; T.C. A20WE	SA2801WE	Installation of main deck cargo restraint system. Issued 1/16/74.	WE	79000	Transequip Inc. 180 N. Aviation Boulevard El Segundo, CA 90245
747-100, -200B; T.C. A20WE	SA3424WE	Installation of BMA main deck baggage container, P/N 302928. Issued 6/9/77.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-100, -200B, -200C, -200F; T.C. A20WE	SA2845WE	Installation of logo light assembly. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
747-100, -200B, -200C, -200F; T.C. A20WE	SA2895WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100, -200B, -200C, -200F; T.C. A20WE	SA2962WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 12/16/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100 Series, 747-200C, 200F Series; T.C. A20WE	SA3074WE	Installation of 96˜x 125 inch animal containers. Amended 11/30/77.	WE	72770	J.D. Smith Air Export, Inc. One World Trade Center Suite 2161 New York, NY 10048
747-100, -200B, -200C, 747SR, 747SP; T.C. A20WE	SA3480WE	Installation of Hughes passenger entertainment/passenger service multiplex system. Issued 11/3/77.	WE	43330	Hughes Aircraft Company Microelectronics Products Div. 500 Superior Avenue Newport Beach, CA 92663
747-100, -200B, -200C, 747SR, 747SP Series; T.C. A20WE	SA3511WE	Installation of stretcher carrier P/N AM2003. Issued 3/21/78.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
747-100, -200B, -200C, -200F; T.C. A20WE	SA3604WE	Installation of Transequip, Inc. auto transponder assembly, P/N 303500. Issued 3/2/78.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-121; T.C. A20WE	SA503EA-D	1) Add additional first class passenger seats and class divider. 2) Add two additional coat closets in Zone C. Issued 5/11/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
747-121; T.C. A20WE	ST714SO-D	Installation of NASA aircraft-to-satellite data acquisition relay (ASDAR) system. Amended 12/14/77.	WE	62300	Pan American World Airways, Inc. J.F.K. International Airport Jamaica, NY 11430
747-121; T.C. A20WE	SA809EA	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-121; T.C. A20WE	SA869EA	Installation of carry-on luggage containers. Issued 4/2/71.	NE	81120	Aerospace Division Universal Oil Products Company Bantam, CT 06750
747-121; T.C. A20WE	SA936EA	Installation of expanded digital flight data recorder system. Amended 4/13/73.	EA	62300	Pan American World Airways Pan Am Building New York, NY 10017
747-121; T.C. A20WE	SA1077EA-D	Installations of Delco F130A flight management system. Amended 8/14/79.	EA	62300	Pan American World Airways, Inc. J.F.K. International Airport Jamaica, NY 11430
747-121; T.C. A20WE	SA2466WE	Installation of AiResearch P/N 216001-401 and -402 class divider - bulkhead assembly. Issued 1/13/72.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121; T.C. A20WE	SA2706WE	Modification by installation of AiResearch coat closed P/N 2130091. Issued 5/30/73.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-121; T.C. A20WE	SA3494WE	Installation of Weber Aircraft auxiliary galley, P/N 822767. Issued 9/22/77.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-121, 747-123; T.C. A20WE	SA2444WE	Installation of tables without association with a seating arrangement. Amended 4/27/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
747-121, -122, -238B; T.C. A20WE	SA2823WE-D	Installation of equipment required to conduct NASA/UAL global air sampling program. Amended 11/25/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-121, -123, -273C; T.C. A20WE	SA3007WE	Installation of cargo pallet assembly, P/N 31250-521. Amended 11/19/75.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-121, -132; T.C. A20WE	SA2624WE	Interior arrangement modification. Amended 4/27/78.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121, 747-132; T.C. A20WE	SA3550WE	Installation of Weber auxiliary galley, P/N 822767 Amended 6/1/78.	WE	84900	Weber Aircraft Div. of Walter Kidde & Co., Inc. 2820 Ontario Street Burbank, CA 91510
747-122; T.C. A20WE	SA2193WE	Installation of entree cart 802000, tray cart 803000, liquor cart 804000, and waste cart 805000. Amended 9/2/71.	WE	34220	Fairchild Hiller Corporation Stratos-Western Division 1800 Rosecrans AVenue Manhattan Beach, CA 90266
747-122; T.C. A20WE	SA2658WE	Modification of lower deck cargo compartment restraint system. Issued 3/14/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2717WE	Installation of interior arrangement. Issued 6/26/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2750WE	Modification of aircraft for installation of spacer pallets. Issued 9/7/73.	WE	80500	United Air Lines, Inc. Maint. Base, Engineering Dept. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2821WE-D	Installation of additional service cart retractable tiedowns. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2822WE-D	Modified cabin interior configuration. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2829WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3352WE-D	Reduced first class seating to 26 seat places, relocated class divider, installed 10-across coach seating - 348 coach seat places. Issued 11/14/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3581WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 11/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-122, -123; T.C. A20WE	SA3066WE	Installation of lower lobe food service modules, P/Ns 818720 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-123; T.C. A20WE	SA2926WE	Modification to incorporate cargo restraint system P/N 43830, configuration -101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-123; T.C. A20WE	SA2928WE	Installation of carrier aircraft crew galley Model FTL 47-1 in the upper lounge. Issued 9/6/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-123; T.C. A20WE	SA3016WE	Installation of Brownline cargo systems 44297-101 and 44297-102. Issued 5/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-127; T.C. A20WE	SA2972WE	Modification of lower deck aft cargo compartment restraint system to accommodate NAS 3610 Size A aircraft unit load devices. Issued 12/27/74.	WE	17075	Braniff International Exchange Park Dallas, TX 75235
747-128; T.C. A20WE	SA3436WE	Installation of Brownline cargo system 45600-102. Issued 6/21/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-131; T.C. A20WE	SA715CE	Installation of aircraft integrated data system. Amended 12/12/77.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA728CE	Installation of Hamilton Standard TAT/EPRL System.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA877CE	Installation of expanded parameter flight recorder. Amended April 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA2411WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90248
747-131; T.C. A20WE	SA2755WE	Modification of aircraft for installation of 13-inch beverage carts. Issued 9/4/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-131; T.C. A20WE	SA3491WE	Installation of Brownline cargo system 45747-101. Issued 9/27/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-132; T.C. A20WE	SA3381WE	Installation of Brownline lower lobe cargo system, No. 45478-101. Issued 4/11/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-132; T.C. A20WE	SA3446WE	Installation of Browline cargo system 45600-101. Issued 7/5/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-135; T.C. A20WE	ST5058O	Manufacture of Nordskog storage units in accordance with Nordskog drawings 1-209, Rev. B and 1-210, Rev. B and their installation in accordance with NAL E.O. P-2350-01 and P-2350-00-06, Rev. B respectively. Issued 5/23/72.	SO	61220	National Airlines, Inc. Box 2055, Airport Mail Facility Miami, FL 33159
747-135, -151, -251B, -251F; T.C. A20WE	SA90GL	Installation of Bendix GPW-83 ground proximity warning system. Amended 6/8/76.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
747-136; T.C. A20WE	SA1144EA	Installation of movie screens in upper deck and 'B' cabin. Issued 4/27/79.	EA	4400	Inflight Motion Pictures, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-136; T.C. A20WE	SA1145EA	Installation of 16 mm movie pallet in 'B' cabin. Amended 1/15/80.	EA	44000	Inflight Motion Picutres, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-151, -251B; T.C. A20WE	SA2783WE	Installation of wheeled refrigerated module, P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-200 Series; T.C. A20WE	SA3659WE	Installation of Litton LTN-72R INS/RNAV and/or LTN-72 INS navigation systems in a triple configuration. Issued 6/21/78.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
747-200B, -200C; T.C. A20WE	SA983EA	Installation of Super 8mm IMPAK projector assemblies, P/N's 10304 ("A" Compartment) and 10306 ("C-D-E" Compartment). Issued 6/18/74.	EA	44000	Inflight Motion Pictures, Inc. 175-20 148th Avenue Jamaica, NY 11434

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-200F; T.C. A20WE	SA190NW	Installation of 29th position pallet/container kit. Issued 6/10/75.	NW	85142	Western Gear Corporation Flight Structures Division 2100 Norton Everett, WA 98201
747-221F, -246F, -249F; T.C. A20WE	SA3304WE	Installation of Brownline Cargo System No. 45102-101, -103 and -301. Amended 4/26/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-221F; T.C. A20WE	SA4001WE	Installation of Brownline pallet restraint system, P/N 46484-103 and -104. Issued 8/14/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-238B; T.C. A20WE	ST565SO	Lower lobe right hand module unit, P/N 10892-1 left hand module unit P/N 10893-1 and -101, and lower lobe cupboards unit P/N 68878-1 and -101. Amended 7/1/76.	SO	81130	Aerospace Division of UOP 4856 Victor Street Jacksonville, FL 32207
747-238B; T.C. A20WE	SA570EA	Installation of Universal Oil Products tray cart modules P/Ns 68878, 68879, 68880 in Boeing Model 747-238B. Issued 8/31/71.	NE	81120	Aerospace Division Universal Oil Products Company Bantam, CT 06750
747-238B; T.C. A20WE	SA2393WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargo pallet assembly P/N 24076-51 and NAS 3610-2A4P pallet. Issued 8/10/71.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-238B; T.C. A20WE	SA3868WE	Installation of Brownline cargo system 44297 configuration - 104. Issued 1/25/80.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 Lomita Boulevard Torrance, CA 90505
747-245F; T.C. A20WE	SA1032EA	Installation of Collins FPC-75 ground proximity warning system. Amended 3/20/76.	EA	70600	Seaboard World Airlines Seaboard World Building JFK International Airport Jamaica, NY 11430
747-246F; T.C. A20WE	SA3304WE	Installation of Brownline cargo system, No. 45102-101. Issued 11/30/76.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-249F; T.C. A20WE	SA4040WE	Installation of Brownline lower compartment cargo pallet restraint system, P/N 45478-102. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-249F; T.C. A20WE	SA4052WE	Installation of Brownline cargo system, 45600-103. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-257B; T.C. A20WE	SA2307WE	Installation of drink trolly 744000. Reissued 8/3/71.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-258B; T.C. A20WE	SA891EA	Installation of inflight motion picture system. Amended 1/11/72.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11424
747-284B; T.C. A20WE	SA2791WE	Modification of airplane lower deck aft cargo compartment restraint system. Issued 12/10/73.	EU	61797	Olympic Airways S.A. 96, Syngrov Avenue Athens, Greece
Miscellaneous	SA4-1210	Eonnex cover on aircraft surfaces.	WE	33500	Eonair, Inc. Route 1, Box 632 Bakersfield, CA 93308

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
BOEING COMPANY, VERTOL DIVISION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
107-II; T.C. 1H16	SH205NW	Installation improved aft transmission lower case, modification of aft transmission upper case. Issued 8/15/75.	NW	25000	Columbia Helicopters 5407 North Lagoon Avenue Portland, OR 97217
107-II; T.C. 1H16	SH269EA	Instruments for instrument flight (HIR). Amended 3/22/67.	EA	61542	New York Airways, Inc. P.O. Box 426 LaGuardia Airport Station Flushing, NY 11371
107-II; T.C. 1H16	SH422NW	Installation of electrical sensors on each main rotor blade to monitor blade integrity in flight. Issued 3/14/77.	NW	25000	Columbia Helicopters 5407 North Lagoon Avenue Portland, OR 97217
Vertol II; T.C. H8WE	SH593NW	Installation of in-flight blade monitoring system. Issued 4/27/78.	NW	25000	Columbia Helicopters P.O. Box 3500 Portland, OR 97208

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BOEING AIRPLANE COMPANY, WICHITA DIVISION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
75 Series; T.C. 743	SA3-600	**Fuselage** alteration. (Restricted category only.)	CE	17030	Boyde Aircraft Company P.O. Box 321 Caruthersville, MO 63830
75 Series; T.C. 743	SA4-144	Installation of R-985 engine converting airplane to duster.	EA	72570	Skyway Air Services Ltd. Abbotsford Airport Abbotsford, B.C. Canada
75 Series; T.C. 743	SA4-225	Removable metal fuselage panels.	WE	61194	National Aircraft Corporation 15001 Oxnard Street Van Nuys, CA 91408
75 Series; T.C. 743	SA4-227	Eonite covering on wings and ailerons.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
75 Series; T.C. 743	SA4-326	Aerial dust and spray equipment.	WE	79250	Transland Aircraft, Inc. 2823 190 Street Redondo Beach, CA 90277
75 Series; T.C. 743	SA4-347	Installation of modified BT-13 engine mount.	RM	15300	Ed Beegles Aircraft Service Co. 921-22nd Street Greeley, CO 80631
75 Series; T.C. 743	SA4-401	Tail wheel trunnion. (Restricted category only.)	WE	37078	Gail Aircraft Engineering Company Municipal Airport Sacramento, CA 95814
75 Series; T.C. 743	SA4-541	Eonite covering on elevators, rudder, and horizontal and vertical stabilizers.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
75 Series; T.C. 743	SA4-589	Installation of Swathmaster dispensing unit. Reissued 10/31/74.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
75 Series; T.C. 743	SA4-632	Tail wheel trunnion.	WE	30288	Don's Shop 3074 S. Elm Avenue Fresno, CA 93721
75 Series; T.C. 743	SA4-658	Replacement of wing compression members, Boeing 75-1134 and 75-1234.	WE	83000	Vern's Wing Shop Minter Field, Box 629 Bakersfield, CA 93308
75 Series; T.C. 743	SA4-667	Transland 3001 F.G. aerial dust and spray hopper installed. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
75 Series; T.C. 743	SA4-730	Impregnated glass cloth hopper-tank type PBC-F1, PBC-R1 or PBS-2.	WE	64430	Pickell & Bemis P.O. Box 1298 Brawley, CA 92227
75 Series; T.C. 743	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
75 Series; T.C. 743	SA4-889	Hydraulic spray rig retractable system. (Restricted category only.)	WE	03230	Agair, Inc. P.O. Box 335 Dos Palos, CA 93620
75 Series; T.C. 743	SA4-908	Pratt & Whitney R1340-AN1 engine and Hamilton Standard propeller 12D40-305/6101A-12 propeller. Amended 4/29/74.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA4-982	Quick-change clamping unit.	RM	22200	George Chisholm 317 13 Street Greeley, CO 80631
75 Series; T.C. 743	SA4-1089	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
75 Series; T.C. 743	SA4-1197	Control lock, locking rudder, elevator, and ailerons.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA4-1312	Hartzell HA-B3Z30-1/10160-6 ground adjustable propeller (on aircraft with Pratt & Whitney R-985 Series engines only).	WE	85124	West Coast Propeller Company 1101 Chestnut Street Burbank, CA 91500

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
75 Series; T.C. 743	SA4-1314	Combination hopper-tank.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA4-1326	Rudder modified.	WE	48534	Simon Kniff P.O. Box 907 Dos Palos, CA 93620
75 Series; T.C. 743	SA4-1391	Wings metal or fiberglas tip. (Restricted category only.)	WE	12550	Atwood Aviation, Inc. 236 Gail Street Salinas, CA 93901
75 Series; T.C. 743	SA4-1568	Carburetor air intake cleaner. (Eligible on aircraft equipped with Pratt & Whitney R-985 Series engines.)	WE	73946	Spain-Air, Inc. P.O. Box 236 Dos Palos, CA 93620
75 Series; T.C. 743	SA8SW	Fabrication and installation of engine mount for Pratt & Whitney R-985 and R-1340 engines. (Restricted category only.)	SW	37089	Gardner Flyers, Inc. P.O. Box 836 Crystal City, TX 78839
75 Series; T.C. 743	SA26WE	Removable aluminum fuselage panels. (Restricted category only.)	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA34SW	Metal wing ribs and new wood spar (same as original spar). Reissued 10/3/77.	SW	83760	Vincent Aeronautical Covington-Vincent Airport Route 1, Box 677-A Covington, LA 70433
75 Series; T.C. 743	SA35SW	Engine mount assembly, shroud and cowling, oil tank, heat valve to carburetor air intake, and air filter for Pratt & Whitney R-985 engine. (Restricted category only.)	SW	46460	Johnny's Repair Service 709 Indiana Weslaco, TX 78596
75 Series; T.C. 743	SA36SW	Engine mount assembly.	SW	46460	Johnny's Repair Service 709 Indiana Weslaco, TX 78596
75 Series; T.C. 743	SA38SW	Pratt & Whitney R-1340 engine mount.	SW	72595	Skyways, Inc. Kaplan, LA 70548
75 Series; T.C. 743	SA98WE	Modified wing panels. Amended 11/11/74.	WE	83000	Vern's Wing Shop 5032 Airport Drive Bakersfield, CA 93308
75 Series; T.C. 743	SA104SW	101 engine mount for installation of Pratt & Whitney R-985 or R-1340 engine.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
75 Series; T.C. 743	SA191SW	Upper and lower wing spans increased by 15-inch extension on each side. Reissued 10/3/77.	SW	83760	Vincent Aeronautical Covington-Vincent Airport Route 1, Box 677-A Covington, LA 70433
75 Series; T.C. 743	SA206SW	Molded fiberglas fuselage covering. (Restricted category only.)	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
75 Series; T.C. 743	SA210SW	Consolidated-Vultee BT-13 engine mount assembly modification by welding finger plates and gussets.	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
75 Series; T.C. 743	SA220SO	Tow bar, release mechanism, and safety tow link.	SO	37092	Gasser Banners, Inc. P.O. Box 3502 Metropolitan Airport Nashville, TN 37217
75 Series; T.C. 743	SA266SW	Engine mount M1 for Pratt & Whitney R-985 or R-1340 engine installation. Reissued.	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
75 Series; T.C. 743	SA275SO	Automotive type master cylinders.	SO	30360	Dothan Aviation Corporation Municipal Airport Dothan, AL 36301
75 Series; T.C. 743	SA284CE	Wheel fairings.	CE	59315	Mid-Continent Aerial Sprayers P.O. Box 307 Hayti, MO 63851
75 Series; T.C. 743	SA293SO	Wing modifications.	SO	59740	Mississippi State University Aerophysics Department State College, MS 39762
75 Series; T.C. 743	SA331NW	Installation of automatic flagman. Issued 10/6/76.	NW	03500	Air Ag, Inc. City-County Airport Walla Walla, WA 99362

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
75 Series; T.C. 743	SA353CE	DD985 engine mount for use with Pratt & Whitney R-985 engine or DD 1340 engine mount for use with Pratt & Whitney R-1340 engine.	CE	28400	D & D Aero Spraying, Inc. R.F.D. 1 Rantoul, KS 66079
75 Series; T.C. 743	SA365WE	Trim tab elevator cables and pulleys relocated.	WE	60162	Moore Aviation, Inc. P.O. Box 868 Tulare, CA 93274
75 Series; T.C. 743	SA409WE	Clean air filter assembly. (Restricted category only.)	WE	37091	Garriott Crop Dusting, Inc. 909 Mt. Lassen Lane Bakersfield, CA 93300
75 Series; T.C. 743	SA491CE	Install two Wagner FC-6086 brake system master cylinders.	SW	59315	Mid-Continent Aircraft Corp. Mid-Continent Maintenance Div. Drawer "L" Hayti, MO 63851
75 Series; T.C. 743	SA493CE	Install starter system for use with auxiliary power supply.	SW	59315	Mid-Continent Aircraft Corp. Mid-Continent Maintenance Div. Drawer "L" Hayti, MO 63851
75 Series; T.C. 743	SA575SW	Tail surface modified.	SW	34400	Farm Air Service P.O. Box 68 Nome, TX 77629
75 Series; T.C. 743	SA607WE	75-000 wings.	WE	08354	Airspray Manufacturing Corp. 11841 S. Henderson Caruthers, CA 93609
75 Series; T.C. 743	SA643SW	Engine mount assembly for Jacobs R-755 engines.	SW	77760	Tedder Aviation Corporation P.O. Box 5 Texarkana, TX 75501
75 Series; T.C. 743	SA720WE	Wings. Reissued 8/13/75.	NW	19620	J.W. Calley P.O. Box 156 Nezperce, ID 83543
75 Series; T.C. 743	SA733SW	Engine and oil cooler mounts.	SW	68380	Roane Flying Service P.O. Box 2397 West Helena, AR 72390
75 Series; T.C. 743	SA734SW	Center section mounted instrument panel.	SW	68380	Roane Flying Service P.O. Box 2397 West Helena, AR 72390
75 Series; T.C. 743	SA746SW	Fiberglas fuselage and fairings.	SW	68380	Roane Flying Service, Inc. P.O. Box 2397 West Helena, AR 72390
75 Series; T.C. 743	SA1073SW	Fiberglass fuselage skin. Issued 5/18/70.	SW	35200	Fiberglass Specialties 5845 Clementshire Houston, TX 77017
75 Series; T.C. 743	SA1208WE	Steel aileron actuating fitting replacement for Boeing P/N 75-1417.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA1269WE	Modified rudder.	WE	30288	Don's Shop 3074 S. Elm Avenue Fresno, CA 93706
75 Series; T.C. 743	SA1270WE	AGAR squared wings. Reissued 8/13/75.	NW	19620	J.W. Calley P.O. Box 156 Nezperce, ID 83543
75 Series; T.C. 743	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
75 Series (All 75 Series Models on T.C. A-743); A75N1; T.C. A-743, 743	SA2269WE	Installation of modified wheels and brakes. Issued 10/23/70.	WE	41640	Milton Heemstra P.O. Box 1061 Dos Palos, CA 93620
75 Series (All 75 Series Models on T.C. A-743); A75N1; T.C. A-743, 743	SA1008WE	Installation of Poly-Fiber covering material (wings). Amended 8/7/69.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92502
A75N1; T.C. A-743	SA4-144	Installation of Pratt & Whitney R-985 engine and conversion of airplane to duster. Reissued 3/11/70.	EA	25780	Conair Aviation, Ltd. P.O. Box 220 Abbotsford, British Columbia Canada

BOEING AIRPLANE CO., WICHITA DIV. 4

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A75N1; T.C. A-743	SA15NE	Installation of Curtiss-Reed Model 55501-5 propeller in accordance with Curtiss installation and maintenance instructions, Pub. S-120-647, on aircraft equipped with Continental W-670-6N engine. Issued 4/14/77.	EA	58635	Robert B. Meyersburg 6321 Tone Court Bethesda, MD 20034
75, A75, B75, A75N1, B75N1; T.C. 743	SA4-919	Modified wing. Amended 9/25/73.	WE	73000	Leo F. Smith & Company, Inc. 225 South Bent San Marcos, CA 92069
75, A75, B75, E75, A75J1, A75N1, B75N1, D75N1; T.C. 743	SA1053CE	Install spring steel landing gear. Issued November 1974.	CE	03160	Aero Wide Tract 1250 North Lakeview Derby, KS 67037
75, A75, B, E, A75J1, A75N1, B-, D-, IB75A, E75N1; 377; T.C. 743, 812	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A75L3, 75, A75, B75, E75, A75J1, B75N1, D75N1, IB75A, E75N1; T.C. 743	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
A75L3, 75, A75, B75, E75, A75J1, A75N1, B75N1; T.C. 743	SA4-1357	Sellers small Swathmaster dust and spray dispensing equipment. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
75, A75, B75, A75N1, B75N1; T.C. 743	SA4-1456	230-gallon hopper. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
A75L3, 75, A75, B75, E75, A75J1, A75N1, B75N1, D75N1; T.C. A-743	SA1703WE	Installation of Serv-Aero four aileron system. Issued 3/24/70.	WE	71000	Serv-Aero Engineering, Inc. Salinas Municipal Airport Salinas, CA 93901
A75L3, 75, A75, B75, E75, A75J1, A75N1, B75N1, D75N1; T.C. A-743	SA1540WE	Installation of Pratt & Whitney R-985-AN-1 engine, Hamilton Standard 2D30/6101A-12 propeller, modified fuel and oil systems.	WE	71000	Serv-Aero Engineering, Inc. Salinas Municipal Airport Salinas, CA 93901
A75L3, 75, A75, B75, E75, A75J1, A75N1, B75N1, D75N1; T.C. A-743	SA2188WE	Installation of JAS No. 1 moveable canopy on 75 series aircraft modified by FAA approved hopper installation in lieu of front seat and with Pratt & Whitney R-985 engine installed. Issued 7/9/70.	WE	46790	Johnston Aircraft Service P.O. Box 757 Tulare Airpark Tulare, CA 93274
A75L3, 75, A75, B75, E75, A75J1, A75L300, A75N1, B75N1, D75N1, IB75A, E75N1; T.C. 743	SA2666WE	Complete aircraft covering of Ceconite 102 material. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
E75 (Navy N2S-5); T.C. A-743	SA361GL	Installation of sheet metal skin on fuselage, BT-13 wheels and brakes, BT-13 wheels and brakes, fiberglass wheel fairings, D-18/C45 engine cowling and prop spinner, and electrical system. Issued 12/10/79.	GL	67018	Reed's Aircraft Restoration Peter B. Reed Box 38 West Chester, OH 45069
875; T.C. 743	SA575CE	Install Lycoming R-680-E3B engine and Hamilton Standard propeller 2B20/6135A-9.	GL	79590	Trim-A-Plane Service Detroit City Airport Detroit, MI 48213

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BOLKOW-APPARATEBAU GMBH

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Bolkow Jr.; T.C. A1EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Bolkow Jr.; T.C. A1EU	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Bolkow Jr.; T.C. A1EU	SA725WE	Brake control.	WE	64600	Pioneer Aero Service 923 S. San Fernando Boulevard Burbank, CA 91500
Bolkow Jr.; T.C. A1EU	SA768WE	Fuel pressure gage.	WE	64600	Pioneer Aero Service 923 S. San Fernando Boulevard Burbank, CA 91500

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BREWSTER AERONAUTICAL CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fleet 1, 2, 7, 8, 9, 10; A.T.C. 122, 131, 374, 2-562, 428	SA1242WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
Fleet 1; 2; 7, 7-C, 10; 8, 9; 7; ATC 122, 131, 374, 428, 2-562	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Fleet 1, 2, 7, 7-C, 7 Deluxe, 10, Fleet 8, 9, 16B, 7; T.C. 122, 131, 374, 428, 2-566, 2-562	SA2666WE	Complete aircraft covering of Ceconite 102 material. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Fleet 2; ATC 131	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Fleet 7; A.T.C. 374	SA326SO	Continental W-670-6N engine.	SO	69244	R.E. Rust Fayetteville, GA 30214
7, 7-C, 7 Deluxe, 10; T.C. 374	SA1008WE	Poly-fiber covering of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BRITISH AEROSPACE, AIRCRAFT GROUP

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH-125; T.C. A3EU	SA350NW	Installation of nose taxi lights. Issued 9/3/76.	NW	60181	Morrison-Knudson Company P.O. Box 7808 Boise, ID 83729
DH-125; T.C. A3EU	SA386NW	Modify all navigation to accept Grimes light mounted in Lord tail light bracket. Issued 12/14/76.	NW	60181	Morrison-Knudson Company P.O. Box 7808 Boise, ID 83729
DH.125, BH.125; T.C. A3EU	SA16GL	Incorporating AMF (Leland) inverters MGE 23-400 or MGE-23-413. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
DH.125, HS.125, BH.125; T.C. A3EU	ST1030SO	Replace existing lead-acid type battery with Teledyne Gill BP639/TE series lead-acid type batteries. Amended 1/18/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
DH.125-1A; T.C. A3EU	SA235EA	Interior bulkhead and door at fuselage station 260.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA236EA	Interior bulkhead and door at fuselage station 391.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA237EA	Two-place seat.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA238EA	Baggage compartment smoke detector system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA239EA	Automatic flight control system. Amended 6/27/67.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
DH.125-1A; T.C. A3EU	SA289EA	Bulkhead and door at fuselage station 391.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA341EA	Bulkheads and bulkhead door. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA342EA	Seat track extensions, inboard and outboard.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA354EA	Bulkheads and bulkhead door. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA366EA	Bulkhead and bulkhead door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA399EA	Bulkhead and door at fuselage station 258-260. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA432EA	Hydra-electric fuel filter differential pressure switch.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA434EA	Performance of Category II equipment and systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA435EA	Combined ASI/machmeter.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA601EA	Installation of Astek BO 200-81123 combined ASI/machmeter.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA958WE	Environmental control system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

BRITISH AEROSPACE, AIRCRAFT GROUP 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH.125-1A; T.C. A3EU	SA859WE	Air conditioning primary feed duct.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A; T.C. A3EU	SA860WE	Pressurization control system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A; T.C. A3EU	SA956WE	SP-40B automatic flight control system.	WE	74570	Sperry Phoenix Company P.O. Box 2529 Phoenix, AZ 85000
DH.125-1A; T.C. A3EU	SA958WE	Supplemental exterior lighting.	GL	42626	Donald E. Hoskins, Inc. 4980 Marine Drive Chicago, IL 60607
DH.125/1A; T.C. A3EU	SA1142WE	Jump seat. Amended 4/9/69.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125/1A; T.C. A3EU	SA1147SW	Main landing gear doors. Issued 5/25/70.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78216
DH.125/1A; T.C. A3EU	SA1166WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DH.125/1A; T.C. A3EU	SA1167WE	System installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH. 125-1A; T.C. A3EU	SA1176EA	Installation of Solar T-62T-40C when Garrett AiResearch TFE-731-3-1H engines are installed in accordance with STC SA3925WE. Issued 11/20/79.	EA	73275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH 125-1A/521, 522, DH 125-3A/522; T.C. A3EU	SA1358WE	Installation of combined airspeed and machmeter indicator. Amended 3/3/69.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH 125-1A/522; T.C. A3EU	SA487EA	Installation of bulkhead and door at fuselage station 263 13/16.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH 125-1A/522, -3A; T.C. A3EU	SA486EA	Installation of Bendix radio altimeter antennas.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA335EA	Installation of Collins Radio Altimeter Antennas P/N 437X-1. Amended 5/23/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA385EA	Installation of glide slope antenna at fuselage station 114. Amended 7/1/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA386EA	Installation of HF antenna. Amended 7/1/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA440EA	Installation of ADF sense antenna. Amended 4/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA442EA	Installation of bulkhead and bulkhead door at fuselage station 391.5. Amended 3/12/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA484EA	Installation of under seat deck avionics equipment shelf. Amended 5/25/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA536EA	Installation of Dorne & Margolin DMN 4-7 VOR/LOC antenna. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA543EA	Installation of Bendix PB-60 automatic flight control system. Amended 11/9/71.	EA	16010	The Bendix Corporation Navigation and Control Division Teterboro, NJ 07608
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA716EA	Installation of Sonotone CA9 Nickel Cadmium batteries. Amended 1/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH.125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -3A/RA, -1A/S-522, -400A, BH.125-400A, -600A; T.C. A3EU	SA717EA	Installation of Compudex, Inc. model automatic fuel range computer. Amended 10/3/75.	EA	25760	Compudex, Inc. P.O. Box 93 Norristown, PA 19404
DH.125-1A, -1A/522, -1/R-522, -3A, -3A/R, -1A/S-522, -400A; T.C. A3EU	SA826EA	Replacement of lead-acid batteries with sonotone nickel-cadmium batteries. Issued 6/3/70.	EA	13185	Aviation Aids and Technical Service Company P.O. Box 515 Montreal Int'l Airport Montreal 300, P.Q. Canada
DH.125-1A, -1A/522, -1A/R-522, -1A/S-522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, -600A; T.C. A3EU	SA866EA	Installation of Grimes three light strobe kit P/N 34-0301-1. Amended 5/24/74.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
DH.125-1A, -1A/522, DH.125-A/R-522, DH.125-3A, DH.125-1A/S-522, DH.125-3A/RA; T.C. A3EU	SA872EA	Replacement of existing Leland inverter type MGE-23-400. Issued 4/21/71.	EA	15800	The Bendix Corporation Electric Power Division Eatontown, NJ 07724
DH-125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -1A/S-522, -3A/RA, -400A; T.C. A3EU	SA740CE	Install three each single phase solid state inverters, a paralleling control, and a warning control unit. Reissued 1/9/78.	CE	24450	Colt Electronics Company 137 West 9th Avenue N. Kansas City, MO 64146
DH-125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -1A/S-522, -3A/RA, -400, HS-125-600A; T.C. A3EU	SA1466CE	Installation of Phoenix Aerospace VR-1010-24-2AD voltage regulators. Issued 12/22/78.	CE	24450	Colt Electronics Company 137 WEst 9th Avenue North Kansas City, MO 64116
DH 125-1A, 1A/522, -1A/R-522, 1A/R-522-3A, -3A/R, -1A/S-522, -3A/RA, -400A, BH 125-400A, -600A, HS 125-600A; T.C. A3EU	SA2927WE	Installation of logo light on lower surface of horizontal stabilizer. Amended 8/22/77.	WE	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH.125-1A, -1A/522, -1A/S-522, -3A, -400A; T.C. A3EU	SA3382WE	Installation of a single-point pressure refueling system. Amended 6/13/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
DH.125-1A, -1A/522, -1A/3-522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, HS.125-700; T.C. A3EU	SA3551WE	Installation of either a single or dual Global GNS-500A VLF/OMEGA navigation system. Amended 6/20/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, -600A, -700A; T.C. A3EU	SA327EA	Installation of retractable seat. Amended 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
DH.125-1A, 3A, 3A/R, 3A/RA, 400A, HS-125-700A; T.C. A3EU	SA857WE	Installation of GTCP30-92 or GTCP30-92C auxiliary power unit. Amended 1/11/78.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A/522, DH.125 Series 3A, 3A/RA, 400A; T.C. A3EU	SA929EA	Installation of No. 2 battery isolation circuit. Amended 1/31/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -3A, -3ARA, DH.125-400A, BH.125-400A; T.C. A3EU	SA1002CE	Relocation of warning cancel switch from instrument panel to #1 engine power lever. Issued March 1974.	CE	15250	Beech Aircraft Corporation P.O. Box 85 Wichita, KS 67201
DH.125-1A/S-522, Series 3A; T.C. A3EU	SA3925WE	Installation of Garrett AiResearch TFE-731-3-1H engines and related changes. Amended 11/21/79.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-1A/S-522; T.C. A3EU	SA4030WE	Installation of Collins APS-80 autopilot. Issued 11/9/79.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-3A/RA; T.C. A3EU	SA602EA	Installation of bulkhead door and bulkhead at fuselage station 263 13/16.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA674EA	Installation of forward and aft bulkheads and doors.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779

BRITISH AEROSPACE, AIRCRAFT GROUP 4

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH.125-3A/RA; T.C. A3EU	SA679EA	Installation of bulkhead and bulkhead door at fuselage station 260.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA710EA	Installation of dual Bendix CB-60B compass system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA711EA	Installation of dual Bendix FD-60 flight director system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA712EA	Installation of Bendix 1903718-1 flight director monitor warning system. Amended 7/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA713EA	Installation of Bendix MKA-28C marker beacon receiver system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA714EA	Installation of dual Bendix RNA-26C VHF navigation system with 8RNX-26A glide slope receiver.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA719EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA788EA	Installation of Bendix ALA-51A radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A, -3A/R, -3A/RA; T.C. A3EU	SA457EA	Installation of combined ASI/Machmeter. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A, -3A/R, -3A/RA; T.C. A3EU	SA539EA	Installation of Collins 37P-5 glide slope antenna at fuselage station 114. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125, DH-125-400A; T.C. A3EU	SA355CE	Installation of Hoskins Twilighter Mk III/Mk IIIB high intensity lighting system. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
DH-125, DH-125-400A; T.C. A3EU	SA2404WE	Consolidation of STCs SA355CE and STC 362CE into one STC having MASTER ELIGIBILITY LIST - amended to include improved power supply assembly and subchassis timer assembly for Twilighter MK III high intensity supplementary lighting system. Issued 8/16/71.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
DH-125-400A; T.C. A3EU	SA764EA	Installation of interior furnishings and avionics systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA765EA	Installation of bulkhead and door between fuselage station 249.86 and fuselage station 281.79.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA766EA	Incorporation of entrance area installation.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA767EA	Installation of forward cabin lavatory.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA768EA	Installation of a two place, side facing divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA769EA	Installation of Kollsman combined ASI/Machmeter A39469-10036.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA770EA	Installation of United Controls angle of attach system. Reissued 12/18/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA793EA	Installation of Litton skyphone system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH-125-400A; T.C. A3EU	SA831EA	Installation of three Flite-Tronics PC-17 static inverters and one Jet Electronics & Technology, Inc. emergency power supply, Model PS-800. Issued 6/24/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA833EA	Installation of electric elevator trim system. Amended 4/12/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA1981WE	Installation of Sperry Model SP-40C automatic flight control system (P/N 1782874-512). Amended 11/28/69.	WE	74570	Sperry Slight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 95027
DH-125-400A; T.C. A3EU	SA2066WE	Category II system and equipment approval of Sperry Models SP-40 automatic flight control system P/N 1782874-512, and SPI-60 integrated instrument system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 85027
DH. 125-400A, BH. 125-400A; T.C. A3EU	SA1173EA	Rework of Solar T-62T-39 APU installed by STC SA674CE when Garrett AiResearch TFE-731-3-1H engines are installed. Issued 10/25/79.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125-400A, BH.125-400A; T.C. A3EU	SA3870WE	Installation of Garrett AiResearch TFE-731-3-1H engines and related changes. Issued 2/28/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, BH.125-400A; T.C. A3EU	SA4009WE	Installation of Collins APS-80 autopilot. Issued 8/9/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, DH.125-3A/RA; BH.125-400A; T.C. A3EU	SA844EA	Installation of Teledyne Avionics angle of attack system. Reissued 7/1/76.	EA	78000	Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906
DH.125-400A, DH-125-3A/RA; BH.125-400A; T.C. A3EU	SA857EA	Installation of Microturbo, Inc. auxiliary power unit Model 024, type "Saphir 4." Amended 4/2/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; BH.125-400A, -600A, HS.125-700A; T.C. A3EU	SA674CE	Installation of Solar Model T-62T-39Y or -39 or -40C auxiliary power unit. Amended 1/18/80.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH. 125-1A, -3A, -400A, HS. 125-600A, -700A, BH. 125-400A, -600A; T.C. A3EU	SA1175EA	Installation of access doors. Issued 11/19/79.	EA	73275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125, HS.125 Beechcraft; T.S. A3EU	ST1003SO	Replace existing lead-acid batteries with Gill BB638/T1-E lead acid batteries, part numbers BSI 200 left and BSI 200 right Issued 6/23/78.	SC	15100	The Battery Shop, Inc. P.O. Box 17312 Nashville, TN 37127
DH-125-400A, HS 125-600A; T.C. A3EU	SA786EA	Installation of lavatory door and bulkhead at station 392. Amended 7/19/76.	EA	07498	AiResearch Aviation Company 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779
BH125-400A; T.C. A3EU	SA1413SW	Three Flite-Tronics static inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
DH-125-400A1; T.C. A3EU	SA3382WE	Installation of a single-point pressure refueling system. Issued 4/12/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
BH125-600A; T.C. A3EU	SA1888SW	Collins flight control system FCS-105. Issued 6/21/74.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
BH125-600A; T.C. A3EU	SA1923SW	Solar T62T-39 turbine auxiliary power unit. Issued 1/17/75.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
BH125-600A; T.C. A3EU	SA1948SW	Teledyne Avionics normalized angle of attach indicating system P/N 112B900. Amended 9/14/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
BH125-600A; T.C. A3EU	SA2271SW	Interior. Issued 10/27/76.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
HS.125-700A; T.C. A3EU	SA1074EA	Installation of bulkhead and door at F.S. 391.5 Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. 3EU	SA1075EA	Installation of forward baggage and avionics compartment. Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1101EA	Installation of GNS-500A VLF/ omega system. Amended 10/3/79.	EA	1500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1104EA	Installation of oxygen system. Issued 6/7/78.	EA	44035	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A3EU	SA1105EA	Installation of Collins VHF 251 standby communication. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A36EU	SA1106EA	Installation of baggage compartment structural entrance area for use with drawer jump seat. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1107EA	Installation of aft cabin bulkhead and door installation. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1108EA	Installation of avionic equipment rack - washroom. Amended 1/24/79.	EA	44034	Innotech Aviation Limited. P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1109EA	Installation of air distribution system. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1110EA	Installation of emergency lighting system to meet the retroactive requirements of FAR 25.2. Amended 10/25/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1111EA	Installation of Wulfsherg III B flitefone. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1112EA	Installation of nose gear taxi lights. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1113EA	Installation of general lighting. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1114EA	Installation of cabin lining. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1115EA	Installation of Jet AI-804 emeregency horizon. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1116EA	Installation of forward cabin bulkhead LHS and RHS. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
HS.125-700A; T.C. A3EU	SA1117EA	Installation of dual Collins ADS-80F air data system. Reissued 7/26/78.	EA	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1118EA	Installation of Collins FGS-80 flight director system with FD 109 instruments. Amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1119EA	Installation of a single Collins ADS-80F air data system. Reissued 7/26/78.	EA	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1120EA	Installation of a side facing single seat. Issued 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS,125-700A; T.C. A3EU	SA1140EA	Installation of a three place side facing divan, aft cabin left hand side. Issued 1/19/79.	EA	44034	Innstech Aviation Limited Montreal International Airport Dorval, Quebec Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1183EA	Installation of bar galley unit. Issued 2/8/80.	EA	44034	Innotech Aviaiton Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1184EA	Installation of Collins WXR-300 color radar system and structural and electrical provisions for the installation of the Collins RNS-300 radar navigation system. Issued 2/8/80.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
HS-125-700A; T.C. A3EU	SA1538CE	Modification of aircraft to incorporate a fuel management computer. Issued 12/4/79.	CE	24540	Colt Electronics Company 131 West Ninth Avenue North Kansas City, MO 64116
HS.125-700A; T.C. A3EU	SA3552WE	Installation of Delco C-IVA inertial navigation system. Issued 1/13/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS. 125-700A; T.C. A3EU	SA3663WE	Installation of Foxboro engine fuel flow and totalizer system. Issued 6/19/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS. 125-700A; T.C. A3EU	SA3690WE	Installation of a Garrett/ AiResearch GTCP36-100 APU in the tail compartment. Issued 6/30/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3878WE	Installation of Eldec engine fuel flow and totalizer system. Issued 3/8/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3885WE	Installation of dual Global GNS-500A VLF/Omega navigation system. Issued 4/16/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
HS.125-700A; T.C. A3EU	SA3984WE	Installation of dual Litton LTN-211 ONS. Issued 7/11/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
HS.125-700; T.C. A3EU	SA4021SW	BKM 100 PHM 700 pitot heat monitor system. Issued 7/24/79.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
HS. 125-700A; T.C. A3EU	SA4042SW	Relocation of center point pressure refueling system. Issued 9/26/79.	SW	11670	Arkansas Modification Center P.O. Box 3356 - Adams Field Little Rock, AR 72203
HS.125-600A, BH.125-600A, HS.125-700A; T.C. A3EU	SA3705WE	Installation of Garret AIRNAV 200 area navigation system. Amended 9/15/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
H.P. 137 Jetstream Mk1; T.C. A21EU	SA275GL	Modification of cabin and cockpit conditioned air and air distrubition system. Issued 11/6/78.	GL	08140	Air Illinois, Inc. Southern Illinois Airport P.O. Box 1224 Carbondale, IL 62901
H.P. 137 MK1 and H.P. 137 as modified STC SA3425WE; T.C. A21EU	SA440SO	Installation of Bendix Model M-4C automatic flight control system (AFCS) and installation of a Bendix M-4DAFCS. Amended 6/21/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
H.P. 137 MK1; T.C. A21EU	SA785EA	Installation of replacement radome P/N 3079KX. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H.P. 137 MK1; T.C. A21EU	SA815EA	Installation of Compudex, Inc. Model TJ10-HP automatic fuel range computer.	EA	25760	Compudex, Inc. P.O. Box 93 Morristown, PA 19404
H.P. 137 MK1; T.C. A21EU	SA827EA	Relocation of fire-wall fuel and hydraulic system shut-off valves. Amended 6/25/70.	EA	18750	Butler Aviation-Friendship, Inc. Subsidiary of Butler Aviation International, Inc. Friendship Int'l Airport, MD 21240
H.P. 137 MK1; T.C. A21EU	SA1707SW	Three-place side facing couch. Issued 8/1/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA1769SW	Single seat. Issued 12/6/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA2043WE	Installation of instrument panel for day VFR operation.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2074WE	Installation of 18-passenger cabin interior, instruments, and avionics system.	WE	74270	Spartan - Van Nuys 7929 Hayvenhurst Avenue Van Nuys, CA 91406
H.P. 137 MK1; T.C. A21EU	SA2076WE	Installation of Collins AP-104/ FD-109 autopilot - flight director system. Reissued 4/21/70.	CE	24250	Collins Radio Company 5225 "C" Avenue, NE Cedar Rapids, IA 52406
H.P. 137 MK1; T.C. A21EU	SA2115WE	Intallation of observer jump seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2250WE	Relocation of fuel and hydraulic shut-off valves (modification found to comply with requirement of AD 70-15-04, Amendment 39-1031). Reissued 10/24/72.	WE	49850	Lear Avia Corporation P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
H.P. 137 MK1; T.C. A21EU	SA2293SW	P & W AGL PT6A-34 engines. Issued 7/9/76.	SW	46340	Jetstream, Inc. Box 1132 Waco, TX 76705
H.P. 137 MK1; T.C. A21EU	SA3064WE	The installation of an alternate method of complying with AD 72-23-01 by equivalency. Amended 9/23/75.	WE	11354	Apollo Airways 404 William Moffet Road Goleta, CA 93017
H.P. 137 MK1; T.C. A21EU	SA3136WE	Installation of ice shield on fuselage. Issued 1/19/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017
H.P. 137 MK1; T.C. A21EU	SA3281WE	Modification of cabin and cockpit air distribution system. Issued 10/12/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017
H.P. 137 Mk 1; T.C. A21EU	SA3425WE	Installation of two AiResearch TPE331-3U-303V engines and related changes. Amended 2/2/78.	SW	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101
H.P. 137, MK-1; T.C. A21EU	SA3534WE	Installation of cabin interior arrangement. Reissued 1/16/78.	WE	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101
HP.137 MK1; T.C. A21EU	SA3598WE	Installation of Abex P/N 40161 Model AP05V-060 hydraulic pump in lieu of original Vickers hydraulic pump. No installation data required. Issued 6/12/78.	WE	71655	Sierra Pacific Airlines 703 Airport Road Bishop, CA 93514
H.P. 137; T.C. A21EU	SA3932WE	Installation of underseat baggage restraint bars. Issued 5/14/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
B-121 Series 1, 2, 3; T.C. A22EU	SA308EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B-121 Series 1, 2, 3; T.C. A22EU	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Beagle B.206 Series 2; A11EU	SA667SO	Installation of Bendix Model M-4C automatic flight control system.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
B206; T.C. A11EU	SA683SO	Installation of Goodrich wheels, brakes, and tires on main landing gears.	SO	58700	Miami Aviation Corporation Hangar 102, Opa Locka Airport Opa Locka, FL 33054

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
BRITISH AIRCRAFT CORPORATION, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BAC 1-11; T.C. A5EU	SA514EA-D	Install Butler Vector Analog Computer System to provide area navigation capability. Amended 11/17/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11; T.C. A5EU	SA279NW	Interior arrangement. Issued 4/30/76.	NW	01700	AeroAmerica, Inc. 7777 Perimeter Road Seattle, WA 98108
BAC 1-11; T.C. A5EU	SA634SW	Litton low range radio altimeter.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA660SW	Cockpit voice recorder A-100 and control panel A-152.	SW	17075	Braniff International P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA792SW	Relocation of LAS 109C flight recorder.	SW	17075	Braniff Airways Love Field Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA973WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
BAC 1-11; T.C. A5EU	SA1213WE	Fairchild A113 cockpit voice recorder and A152A control panel.	WE	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11; T.C. A5EU	SA1350SW	Installation of center wing tank fuel system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1432SW	Installation of Collins INS-61B inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1740SW	Install dual Delco Carousel IV or IVA inertial navigation systems. Amended 9/11/75.	GL	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11; T.C. A5EU	SA1761SW	Dual Collins INS 61B inertial navigation systems. Reissued 3/20/74.	GL	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11; T.C. A5EU	SA2365SW	Modification of Marston heat exchanger. Issued 10/5/76.	SW	52068	LORI 501 South Lansing Tulsa, OK 74120
BAC 1-11; T.C. A5EU	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, and EL-104B in emergency slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
BAC 1-11; T.C. A5EU	SA2709SW	Installation of heat exchanger. Issued 1/23/78.	SW	52068	LORI 510 South Lansing Tulsa, OK 74120
BAC 1-11, 200 Series; T.C. A5EU	SA1947WE	Installation of underseat baggage restraint system. REissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
BAC 1-11, 200 Series; T.C. A5EU	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
BAC 1-11, 200 Series; T.C. A5EU	SA3616WE	Installation of single LTN-51 or LTN-72 inertial navigation system. Issued 3/27/78.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2261WE	Installation of inflatable emergency evacuation slides at forward passenger and service doors. Amended 7/14/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2306WE	Installation of emergency exit lights at forward passenger door, at forward service door, and at both overwing emergency doors. Issued 1/15/71.	WE	44266	International Inflatables Company Div. Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2722WE	Modify aircraft by installation of wing mounted emblem lights. Amended 1/26/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2813WE	Structural modifications. Amended 7/15/74.	WE	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11 203/AE, 204/AF, 215/AU; T.C. A5EU	SA1021EA	Installation of Collins FPC-75 ground proximity warning system and Bendix ALA-51A radio altimeter system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
BAC 1-11 204/AF, 215/AU; T.C. A5EU	SA840EA	Installation of Technical Standard Order inflatable escape slides. Amended 2/17/71.	EA	07250	Air Cruisers Company Division of Garrett Corporation P.O. Box 180 Belmar, NJ 07719
BAC 1-11 400 Series equipped with Rolls Royce RB 163-25 Spey 511-14 engines; T.C. A5EU	ST846SO	Increase maximum ramp weight to 89,000 lbs., increase maximum take-off weight to 88,500 lbs. and decrease maximum landing weight to 77,200 lbs. Issued 7/1/75.	SO	37085	Bruce Gilman P.O. Box 1372 Vickksburg, MS 39180
BAC 1-11 400; T.C. A5EU	SA3439WE	Installation of single or dual Litton LTN-51 inertial navigation systems. Issued 7/22/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91367
BAC 1-11, 401/AK; T.C. A5EU	SA403EA-D	Interior configuration - change from 69 passenger all coach to 16 first class and 49 tourist class with class divider and curtain installation between two sections.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA408EA-D	Installation of maintenance/flight data recording system. Amended 7/19/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA422EA-D	Installation of dual Collins AL-101 low range radio altimeter.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA449EA	Cockpit voice recorder.	EA	60892	Mohawk Airlines, Inc. Oneida County Airport Utica, NY 13503
BAC 1-11, 401/AK; T.C. A5EU	SA553EA-D	Installation of autopilot go-around unit on BAC 1-11. Amended 10/6/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 410AK; T.C. A5EU	SA554EA-D	Install underseat luggage retention device. Amended 12/4/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11 410AK; T.C. A5EU	SA555EA-D	To comply with FAR 25.812(e), a lever lock switch will be installed at a point accessible seat. Amended 4/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA2868WE	Installation of executive interior. Amended 7/15/74.	WE	07500	AiResearch Aviation Corporation 6201 W. Imperial Highway Los Angeles, CA 90045
BAC 1-11, 401/AK; T.C. A5EU	SA2971WE	Installation of maximum 1565 gallon auxiliary fuel tanks in forward and aft cargo compartment. Reissued 2/23/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91505
BAC 1-11 401/AK; T.C. A5EU	SA3431WE	Installation of two couches in aft of aircraft. Issued 6/15/77.	WE	62083	Pacific American Airlines 2800 Clybourn Avenue Burbank, CA 91510
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB, 422/EQ; T.C. A5EU	SA1995WE	Installation of auxiliary fuel tanks in forward and aft cargo compartments. Amended 12/6/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB; T.C. A5EU	SA2776WE	Installation of dual Litton, LTN-51 inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BAC 1-11, 401AK, 410AQ, 412A/EB, 414EG, 419EB, 422EQ; T.C. A5EU	SA2873WE	Installation of a single or dual Litton, LTN-104, area navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EP; T.C. A5EU	SA3567WE	Installation of single or dual Litton LTN-51 or LTN-72 INS. Issued 3/17/78.	WE	51500	Litton Aero Products Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
BAC 1-11, 412A/EB Series, 422EQ; T.C. A5EU	SA2911WE	Installation of relocated engine water injection storage tank. Amended 2/20/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
BAC 1-11, 414EG; T.C. A5EU	SA3619WE	Installation of 1478 gallon auxiliary fuel tank system in the forward and aft cargo compartments. Issued 1/25/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BRITTEN NORMAN, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BN Series; T.C. A17EU	SA1842WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
BN-2 Series; T.C. A17EU	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K & Avionics 18145 Judy Street Castro Valley, CA 94546
BN-2 Series; T.C. A17EU	SA1675WE	Installation of K & Avionics EGT-2 exhaust gas monitoring system. Amended 8/28/74.	WE	48750	K & Avionics 18145 Judy Street Castro Valley, CA 94546
BN-2, BN-2A; T.C. A17EU	SA843EA	Replace existing wheel/brake assemblies. Issued 9/23/70.	GL	39125	Product Support Department Aviation Products Division The Goodyear Tire & Rubber Co. 1144 East Market Street Akron, OH 44315
BN-2, BN-2A; T.C. A17EU	SA874EA	Installation of Radome Kit No. 3082RX for 10 inch RCA AVQ-45, -46 or -47 radar antenna or a 12 inch Bendix RDR-100, -110 radar antenna. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
BN-2, BN-2A, BN-2A6; T.C. A17EU	SA474SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and flight director indicator DH-841( ). Issued 9/2/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
BN-2, BN-2A, BN-2A6; T.C. A17EU	SA1312SW	Automatic flight system AK336 consisting of Century III autopilot and command/automatic electric trim with optional radio and glide slope couplers. Issued 5/13/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2, BN-2A, BN-2A6; T.C. A17EU	SA1351SW	Mitchell automatic flight system AK 338, consisting of Century I with optional tracker. Issued 7/26/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2, BN-2A, BN-2A6; T.C. A17EU	SA2455WE	Installation of JB Systems, Inc. airconditioning system. Amended 5/16/72.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
BN-2, BN-2A, BN-2A-6, -2A-8, -2A-9; T.C. A17EU	SA2243WE	Installation of Rajay turbocharged Lycoming O-540-E4C5 engines. Amended 3/16/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
BN-2, -2A, -2A-6, -2A-8, -2A-9, -2AMKIII; T.C. A17EU, A29EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BN-2, -2A, -2A-6, -2A-8, -2A-9, -2AMKIII; T.C. A17EU, A29EU	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BN-2, -2A, -2A-2, -2A-6, -2A-8; BN-2A, MK.III; T.C. A17EU, A29EU	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BN-2, -2A, -2A-2, -2A-6, -2A-8; BN-2A, MK.III: T.C. A17EU, A29EU	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
BN-2, -2A, -2A-2, -2A-3, -2A-6, -2A-8, -2A-9, -2A-20, -2A-21, -2A-26, -2A-27; T.C. A17EU	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 10/15/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
BN-2, -2A, -2A-2, -2A-3, -2A-6, -2A-8, -2A-9, -2A-20, -2A-21, -2A-26, -2A-27; T.C. A17EU	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 10/15/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
BN-2A-3, -9, -21; T.C. A17EU	SA3041SW-D	Mitchell automatic flight system AK518 consisting of Century III autopilot with optional command/automatic electronic pitch trim, radio, and glide slope couplers. Issued 1/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2A Mk III; T.C. A29EU	SA3056SW-D	Mitchell automatic flight system AK533 consisting of Century III autopilot with command/automatic electronic pitch trim system and optional radio coupler and glide slope coupler. Issued 5/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2A Mk III; T.C. A29EU	SA3073SW-D	Mitchell command electric trim system. Issued 9/15/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2A-6; T.C. A17EU	SA73NW	Remove left rear cabin entrance door. Issued 3/27/74.	NW	49240	La Grande Air Service Route 2, Box 2546 La Grande, OR 97850
BN-2A-6; T.C. A17EU	SA693CE	Install AC induction air filter AAF-104. Amended 11/3/73.	GL	00750	A C Spark Plug Division General Motors Corporation Flint, MI 48556
BN-2A-21; T.C. A17EU	SA1053EA	Installation of air polution sampling and analysis equipment and doppler navigation system. Amended 12/20/78.	EA	29998	DeVore Aviation Corporation 206 Newton Road Plainview, NY 11803

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
BUHL AIRCRAFT COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
LA-1; T.C. 405	SA4-926	Ceconite 101 covering of wings, horizontal stabilizer, rudder and elevators.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
LA-1; ATC 405	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
LA-1; ATC 405	SA2666WE	Complete aircraft covering of Ceconite 102 material. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

CAMAIR AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
480; T.C. 2A2	SA1-396	Navion retract link assembly 143-33165-10.	EA	21100	Rudolph Chalow RD #1 Newfield, NJ 08344
480; T.C. 2A2	SA142SO	Control wheel.	SO	37086	Garcia Aviation Company 15801 SW. 120 AVenue Miami, FL 33101
480; T.C. 2A2	SA162EA	Navion retract link assembly 145-34106.	EA	21100	Rudolph Chalow RD #1 Newfield, NJ 08344
480; T.C. 2A2	SA200CE	Nose and main gear retracting link replacement.	GL	85148	Western Machine Repair Service 3315 E. Milham Avenue Kalamazoo, MI 49001
480; T.C. 2A2	SA219EA	Installation of Katz Integrated Flight Indicator Model KIFI-2 or KIFI-2A. Amended 5/21/69.	NE	36300	Forest City Aviation Service 749 Congress Street Portland, ME 04102
480; T.C. 2A2	SA262SO	24-volt starting system.	SO	12492	Atlanta Aero Service, Inc. DeKalb-Peachtree Airport Chambless, GA 30005
480; T.C. 2A2	SA278SO	Main and nose landing gear retract links.	SO	36765	William E. Freeman 570 Milligan Drive Stone Mountain, GA 30083
480; T.C. 2A2	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
480; T.C. 2A2	SA335SW	Rework of main and nose gear retract links.	SW	05968	Aircraft Service 6625 Greenspan Dallas, TX 75221
480; T.C. 2A2	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
480; T.C. 2A2	SA492WE	Full flow lube oil filter 40409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
480; T.C. 2A2	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. REissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
480; T.C. 2A2	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
480; T.C. 2A2	SA1675WE	Installation of KS Avionics EGT-2 exhaust gas monitoring system. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
480; T.C. 2A2	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

CANADAIR, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
CL-44D4; T.C. 1A20	SA4-1556	Installation of United Control, Data Division, F542 Flight Recorder.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
CL-44D4; T.C. 1A20	SA4-1557	Passenger interior.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA64EA	Unfreight Mark IV cargo handling system.	EA	10226	American Machine & Foundry Co. Whiteford & Eden Roads York, PA 17405
CL-44D4; T.C. 1A20	SA165WE	178 maximum passenger interior.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA196EA	Astek Mach airspeed warning switch.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA215EA	Airspeed aural warning system.	EA	70600	Seaboard World Airlines JFK International Airport Jamaica, NY 11430
CL-44D4; T.C. 1A20	SA291WE	Single Collins 860E-1 distance measuring equipment (DME) system.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA444EA	Cockpit voice recorder.	EA	70600	Seaboard World Airlines JFK International Airport Jamaica, NY 11430
CL-44D4; T.C. 1A20	SA457WE	Passenger interior.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA488EA	Install Bendix brushless generators and regulators.	EA	70600	Seaboard World Airlines JFK International Airport Jamaica, NY 11430
CL-44D4; T.C. 1A20	SA489WE	Dual Sperry C-12 compass system.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA518WE	Dual Collins (DN-101) doppler radar and dual Collins (NC-103) navigational computer system with optional connection to Eclipse Pioneer PB-20H autopilot.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA535WE	Passenger interior.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA569WE	Modification for deletion of up restraint requirement in lower cargo compartments and the use of 5,000-lb. cargo fittings.	WE	36100	The Flying Tiger LIne, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA576WE	Extruded aluminum plank floor.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA577WE	Aircraft Mechanics pilot and copilot seats.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA587EA	Relocation of Fairchild Model 5424-220 flight recorder.	EA	70600	Seaboard World Airlines Seaboard World Building JFK International Airport Jamaica, NY 11430
CL-44D4; T.C. 1A20	SA721WE	Modification of cockpit entrance door.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA777WE	Custom Products models pilot and copilot seats.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
CL-44D4; T.C. 1A20	SA887WE	166-passenger interior.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA937WE	Flap actuated gear warning system.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
CL-44D4; T.C. 1A20	SA1086WE	Escape chutes relocated.	WE	72740	Slick Airways International Airport San Francisco, CA 94119
CL-44D4; T.C. 1A20	SA1187WE	Either a Collins Radio Company or a United Data Control, Inc., cockpit voice recorder system.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
CL-44D4; T.C. 1A20	SA1236WE	Modification of elevators.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
CL-44D4; T.C. 1A20	SA1329WE	Collins 621A-3 air traffic control transponder system.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
CL-44D4; T.C. 1A20	SA1330WE	Class "E" cargo compartment reduced to accommodate crew rest area.	WE	3610	Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
CL-44D4; T.C. 1A20	SA1401WE	Structural modification of lower rudder.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
CL-44D4; T.C. 1A20	SA1639WE	Replacement of any of three original 40 KVA alternators with Westinghouse 40 KVA system consisting of alternator P/N 976J843-1 and regulator P/N 915F363-1.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
CL-44D4; T.C. 1A20	SA1761WE	Replacement of any of three original 60 KVA alternators and voltage regulators with Westinghouse 60 KVA system.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
CL-215-1A10; T.C. A14EA	SA2178WE	Installation of liquid spray system. Issued 6/25/70.	WE	14000	Aviation Specialties, Inc. 4930 East Falcon Drive Mesa, AZ 85205

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

CESSNA AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C-145, C-146; T.C. 701	SA4-1516	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
T-50; T.C. 722	SA1-196	Fiberglass application over fabric.	GL	62390	Anita M. Paner 7811 Hamilton Avenue Cincinnati, OH 45231
T-50; T.C. 722	SA4-161	Fiberglass fabric on fuselage, ailerons, flaps, empennage and wings.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
T-50; T.C. 722	SA4-1347	Ceconite 101 covering of entire airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
T50, 120, 140, 170, 170A, 170B; T.C. 722, 768, 799	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
T-50; 120, 140; C-145, -165; 170; T.C. 722, 768, 701, 799	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C-145, C-165, T-50, 120, 140, 170; T.C. 701, 722, 768, 799	SA2666WE	Ceconite 102 material covering of: C-145, C-165 - wings; T-50 - complete aircraft; 120, 140, 170 - wings. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
120; T.C. 768	SA1-39	Recovering of wings with metal skin, .020" 24ST alclad, except ailerons.	SO	16894	Boone County Aviation, Inc. P.O. Box 6 Erlanger, KY 41018
120, 140 Series; T.C. 768, 5A2	SA1-259	Wing covering of alclad panels.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047
120, 140 Series; T.C. 768, 5A2	SA1-436	Leading edge landing lights in left-hand wing.	EA	72100	Skycraft Design P.O. Box 67 West Trenton, NJ 08628
120, 140 Series; T.C. 768, 5A2	SA3-114	Instrument panel modification.	RM	84912	Weber Aviation Municipal Airport Rapid City, SD 57701
120, 140 Series; T.C. 768, 5A2	SA4-89	Recovering of wings with metal .020 alclad 2024T3 aluminum alloy.	WE	49380	J.E. Lane, Jr. 3504 Niblick Drive La Mesa, CA 92041
120, 140 Series; T.C. 768,5A2	SA4-95	Lycoming 0.235C-1 engine.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
120, 140 Series; T.C. 768, 5A2	SA4-174	Glass cloth application over muslin to wings only.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
120, 140 Series; T.C. 768, 5A2	SA4-341	Recovering of wings with .020 24ST alclad sheet.	WE	18275	Frank A. Burdick 43316 N. 20 Street West Lancaster, CA 93534
120, 140 Series; T.C. 768, 5A2	SA4-360	Recovering of wings with aluminum alloy sheet.	WE	19900	Carma Manufacturing Company P.O. Box 11312 Municipal Airport Tuscon, AZ 85700
120, 140 Series; T.C. 768, 5A2	SA4-581	Lycoming O-290-D engine and Sensenich M76AM-2 or CS3FM4 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
120, 140 Series; T.C. 768, 5A2	SA4-640	Lycoming O-290-D2 engine and Sensenich M76AM-2 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
120, 140 Series; T.C. 768, 5A2	SA4-674	Eonite covering on wings.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
120, 140 Series; T.C. 768, 5A2	SA4-803	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 94108
120, 140 Series; T.C. 768, 5A2	SA4-916	Tricycle gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
120, 140 Series; T.C. 768, 5A2	SA4-1200	Delco-Remy generator 1101879 and and regulator 1118384.	RM	81060	Universal Aircraft Industries P.O. Box 5306 Denver, CO 80217
120, 140 Series; T.C. 768, 5A2	SA4-1346	Fiberglas covering of airplane surfaces.	WE	49790	Quentin Laywell 5627 Laurette Street San Diego, CA 92100
120, 140 Series; T.C. 768, 5A2	SA54CE	Covering of wings with .020" 24ST aluminum.	CE	14223	B & W Aircraft Repair, Inc. St. Peters, MO 63376
120, 140 Series; T.C. 768, 5A2	SA99EA	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
120, 140 Series; T.C. 768, 5A2	SA295WE	Mounting bracket fabrication.	NW	43380	Glen Humphreys 2325 S.W. 116 Seattle, WA 98146
120, 140 Series; T.C. 768, 5A2	SA1008WE	Poly-Fiber covering of right and left wing. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
120/140; T.C. A768	SA388SO	Metalize wings, wing landing/taxi light installation. Amended 7/2/70.	SO	68550	W.F. Robison Valley Air Service P.O. Box 241 Lanett, AL 36863
120, 140 Series; T.C. A-768	SA1209WE	Replacement of wing drag wires in two outboard wing bays with 3/16 inch Stratton Aero Enterprises drag wires. Reissued 8/11/78.	WE	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
120, 140, 150; T.C. 768, 3A19	SA1143SW	Redesigned muffler assemblies. Issued 5/15/70.	SW	25350	Comisky Engineering Company, Inc. P.O. Box 268 Mena, AR 71953
120, 140, 170 Series; T.C. 768, 5A2, 799	SA331CE	New base instrument panel incorporating artificial horizon.	GL	74000	Spartacus Industries P.O. Box 634 Muskegon, MI 49443
120, 140, 170; T.C. 768, 3A12	SA4-207	Spar reworked to facilitate rigging of metalized wings.	RM	84394	Wagner Aircraft Service P.O. Box 267 Grand Junction, CO 81501
120, 140, 170; T.C. 768, 3A12	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
120, 140, 170; T.C. 768, 3A12	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
120, 140; 170, 170A, -B; T.C. 768, 799	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
120, 140, 170, 180; T.C. 768, 5A2, 799, 5A6	SA3-423	CT-300 tail ski on airplanes equipped with Scott 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
120, 140, A, 170, 170A, B, 172, 172A, B, C, D, E, 180, 180A, B, C, D, E, F, G, 182, 182A, B, C, D, E, F, G, 210, 210A, B, C, D, 210-5, -5A, 150, 150A, B, C, D, 305A, B; T.C. 768, 5A2, 799, 3A12, 5A6, 3A13, 3A21, 3A19, 3A14	SA4-394	Installation of George M. Adams DGA-2000 wheels and Bodell Manufacturing Model BMI-252 brakes. Amended 1/15/76.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torranca, CA 90501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
120, 140, 140 (S/N 8004 thru 13399), 140A (S/N 13400 and up), 170, 170A, 170B, 172, 172A thru 172E, 175, 175A, 175B, 175C, P172D, 180, 180A thru 180F, 182, 182A thru 182G; T.C. A-768, A-799, 3A12, 3A13, 3A17, 5A2, 5A6	SA13GL	Installation of wheel No. 40-97A and brake No. 30-63A. Reissued 7/24/74.	GL	23260	Cleveland Wheels & Brakes Div. Van Sickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
120, 140, 170, 305A, 305C, 305B; T.C. 768, 5A2, 799, 5A5, 3A14	SA34CE	Tow hitch assembly.	EA	73550	Soaring Society of American, Inc. Elmira, NY 14902
120, 140, 140A, 150, 150A, B, D, E, F, G, H, J, K, L, A150K, 170, 170A, B, 172, 172A, B, C, D, E, F, G, H, I, K, L, M; T.C. 768, 5A2, 3A19, 799, 3A12	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24115 116th S.E. Kent, WA 98031
120, 140; 140A, 150 to 150-L; 170, 170A, B; 172 to 172M; 175 to 175C; 177 to 177B; 180 to 180J; 182 to 182Q; T.C. 768, 5A2, 3A19, A799, 3A12, 3A17, A13CE, 5A6, 3A13	SA86NW	Installation of automatic carburetor alternate air control unit. Issued 12/28/73.	NW	01775	Aero-Deicers, Inc. 5407 S.E. 62nd Avenue Portland, OR 97206
120, 140, 170, 172, 175, 180, 182; T.C. 768, 5A2, 799, 3A12, 3A17, 5A6, 3A13	SA121CE	Nose and main gear wheel fairing (Jetstreams) using standard unaltered Cessna landing gear and nose gear fork for model and year using 500 x 5 nose and 600 x 6 main gear tires. Amended 3/1/77.		26750	Creative Designs 1338 Orkla Drive Minneapolis, MN 55427
120, 140, 150, 170, 172, 175, 180, 182, 185, 190, 195, 210, 310, 320; T.C. 768, 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, 790, 3A21, 3A10, 3A25	SA147CE	Moni-Meters on aircraft equipped with King KY-90, KY-95, Narco Mark 4 or Mark 12 transceivers.	GL	60086	Mobile Engineering 220 Southdale Center Minneapolis, MN 55435
120, 140, 170, 305A, 305C, 305B; T.C. 768, 5A2, 799, 5A5, 3A14	SA268CE	Tow hitch assembly.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
120, 140; 140A; 150, A thru L; 170, 170A, -B; A150K, A150L; 172, 172A thru L; 175, A, B, C, P172D; 180, A thru H; 182; 177, 177A, B; 182A thru H, J thru N, P, 188, 188A; 185, 190, 321; T.C. A-768, 5A2, 3A13, A-799, A-758, 3A17, 5A6, A-729, A13CE, A9CE, 3A11	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
120, 140; 140A; 150, A, B, C, D, E, L; 170, A, B; A150K, A150L; 172, 172A, B, C, D, E, F, G, H, J; 175, A, B, C, P172D; 180, A thru H; 177 177A, B; 188, 188A; 182, 182A thru P; 182; 321; T.C. A-768, 5A2, 3A19, A-799, A-758, 3A13, 3A17, 5A6, A13CE, A9CE, 3A11	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
120, 140, 150, 170, 172, 175, 177, 177RG, 180, 182; T.C. A-768, 3A19, A799, 3A12, 3A17, A13CE, A20CE, 5A6, 3A13	SA582NW	Fabrication of wire ropes. Issued 5/12/78.	NW	81180	University Swazing 7001 Perimeter Road Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
120, 140, 140A, 150, 170, 175, 180, 182, 310; T.C. A768, 5A2, 3A19, 3A17, 5A6, 3A13, 3A10	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
120, 140; 140; 150; 170; 172; 172, 175; 177; 180; 182; 185; 188, A188; 206; 207, T207; 210; 305; 310; 320; 321; 336; 337; 401, 401A, 402, 402A; 411, 411A, 421, 421A; T.C. A-768, 5A2, 3A19, A-799, 3A12, 3A17, A13CE, 5A6, 3A13, 3A24, A9CE, A4CE, A16CE, 3A21, 5A5, 3A14, 3A10, 3A25, 3A11, A2CE, A6CE, A7CE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
120, 140; 140A; 150, 150A thru H, J, K, L, M, A150K, L, M, 170, 170A, B; 172, 172A thru 172M; 175, 175A, B, D, P172D; 177RG; 177, 177A, 177B; 180, 180A thru J; 182, 182A thru 182P; 185, 185A thru 185E, -A185E, A185F; 188, A188,, 188A, 188B, A188A, A188B; 190, 195, 195A, B; 206, P206, P206A, B, C, D, E, TU206A thru TU206F, TP206A thru TP206E, U206, U206A, B, C, D, E, F; 207, T207, 207A, T207A; 210, 210A thru 210H, J, K, L, T210F, G, H, J, (205) 210-5, (205A), K, L, 210-5A; 310, 310A thru 310Q, E310H, -J-1, E310-J, -K, -L, -N, -P, T310P, T310Q; 320, A, B, C, D, E, 320F, 320-1; 337, -A thru -G, T337D, -E, -F, -G; 336; 340; 401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 421, 421A, B; T.C. A-768, 5A2, 3A19, A-799, 3A12, 3A17, A20CE, A13CE, 5A6, 3A13, 3A24, A9CE, A-790, A4CE, A16CE, 3A21, 3A10, 3A25, A6CE, A2CE, 3A25, A7CE	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W A408R/W or A470R/W (red/white) (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
120, 140, 150, 170, 180, 190, 195; T.C. 768, 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 790	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
120, 140; 150, A thru H; 170, -A, -B; 172, A thru I; 177; 180, A thru H; 182, A thru L; P206D, U206D, TP206D, TU206C; 207, T207; M337B; 310, A thru N, E310H, -J, 310J-1; 320, -1, A thru F; 401, 402, 411, 411A, 421; T.C. 768, 3A19, 799, 3A12, A13CE, 5A6, 3A13, A4CE, A16CE, A6CE, 3A10, 3A25, A7CE	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
140 Series; T.C. 768, 5A2	SA1-1	Recovering of wings with 24ST alclad skin.	EA	05972	Aircraftsmen, Inc. Zahn Airport Lindenhurst, L.I., NY 11757

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
140 Series; T.C. 768, 5A2	SA4-79	Recovering of wings with metal .020 aluminum 2024-T3 clad.	NW	61780	Francisco Ochoa 4836 E. Mercer Way Mercer Island, WA 98040
140 Series; T.C. 768, 5A2	SA4-376	Lycoming O-235-C1 engine.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
140 Series; T.C. 768, 5A2	SA105GL	Install a pitot-static tube. Issued 1/16/76.	RM	48529	Lowell Kleven P.O. Box 1279 Jackson, WY 83001
140 Series; T.C. 768, 5A2	SA175WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	70614	Seagull Aviation P.O. Box 104 Brigham City, UT 84302
140 Series; T.C. 768, 5A2	SA267SW	Continental O-200-A engine and a McCauley 1A100 MCM propeller.	SW	74850	S & S Pipeline Patrol P.O. Box 787 Dickinson, TX 77539
140, 170, 172, 175, 180; T.C. 768, 5A2, 799, 3A12, 3A17, 5A6	SA1-252	Safety gear Model A.	EA	37140	Geiss Gears, Inc. 3350 Tennyson Street, NW Washington, D.C. 20015
140, 150, 170, 172, 175, 180, 182, 185, 210; T.C. 768, 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21	SA12WE	Fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
140, 150, 172 Series; T.C. 768, 5A2, 3A19, 3A12	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
140, 150, 170, 172, 175, 180, 182, 210 Series; T.C. A768, 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A21	SA596EA	Installation of electronic voltage alarm Drawing No. 80104.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
140A; T.C. 5A2	SA323GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
140A; T.C. 5A2	SA547EA	Installation of Continental O-200-AEA engine and McCauley 1A100-MCM6952 propeller.		52542	John T. Lucas & M. David Emmett RD #2 Emporium, PA 15834
140A, 150, 170, 172, 175, 180, 182, 185, 206, 210, 207, 305; T.C. 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, A4CE, 3A21, A16CE, 5A5, 3A14	SA995SW	Increase wing leading edge radius wing tip fairings, and landing light lens. Reissued 2/13/75.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
140A, 150, 170, 172, 175, 177, 180, 182, 185, 206, 210, 207, 305 Series; T.C. 3A17, 5A6, 3A13, 3A24, A4CE, 3A21, A16CE, 5A2, 799, 5A5, 3A19, 3A12, 3A14	SA1371SW	Wing leading cuff, wing tips and upper surface flow fences. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
140A, 150, 170, 172, 175, 180, 182, 185, 206, 207, 210, 305 Series; T.C. 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, A4CE, A16CE, 3A21, 5A5	SA1474SW	Installation of "MASA" 1223000-7 and -8 wing tip. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
150 Series; T.C. 3A19	SA1-479	Aero control AP and heading lock GD.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109
150 Series; T.C. 3A19	SA1-630	Dry vacuum pump and instrument vacuum system 113A5.	GL	03760	Airborne Mechanisms Division Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
150 Series; T.C. 3A19	SA4-965	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
150 Series; T.C. 3A19	SA4-1342	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150 series; T.C. 3A19	SA4-1373	Brake blocks AB-6531 and AB-6532.	EA	46748	Johns-Manville Corporation 22 E. 40 Street New York, NY 10001
150 Series; T.C. 3A19	SA17WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	64275	Peterson Aviation 3100 Airport Avenue Santa Monica, CA 90406
150 Series; T.C. 3A19	SA164WE	Fuel filter PFF-100.	WE	64600	Pioneer Aero Service P.O. Box 227 Burbank, CA 91500
150 Series; T.C. 3A19	SA534CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
150 Series; T.C. 3A19	SA607SW	AK193 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
150 Series: T.C. 3A19	SA1433WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
150, 172, 175, 180, 182, 310; T.C. 3A19, 3A12, 3A17, 5A6, 3A13, 3A10	SA1-124	Lube oil filter BP55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
150, 170, 172, 175, 180, 182; T.C. 3A19, 799, 3A12, 3A17, 5A6, 3A13	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
150, 170, 172, 175, 180, 182, 185, 210; T.C. 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21	SA220SO	Tow bar, release mechanism, and safety tow link.	SO	37092	Gasser Banners, Inc. P.O. Box 3502 Metropolitan Airport Nashville, TN 37217
150, 180 Series; T.C. 3A19, 3A13	SA270SO	Water and ice detector in fuel gascolator and carburetor.	SO	71545	Charles B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
150, 170, 172, 177, 180, 182; T.C. 3A19, 3A12, 799, 5A6, 3A13, A13CE	SA316SO	Carburetor ice detector. Amended 8/31/66.	SO	71545	C.B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
150, 170, 172, 175; T.C. 3A19, 799, 3A12, 3A17	SA971WE	Installation of Jasco 76540 (35a.) alternator kit or Jasco #6555 (50a.) alternator kit. Amended 10/29/76.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M, 170B, 172, 172A, B, C, D, E, F, G, H, I, K, L, M, 175, 175A, B, C, P172D, 180, 180A, B, C, D, E, F, G, H, J, 182A thru P, 185, 185A, B, C, D, E, A185E, A185F, 210, 210A, B, C, D, 205, 205A; T.C. 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21	SA150NW	Installation of flap gap seals. Amended 9/16/75.	NW	16856	B & M Aviation P.O. Box 1563 Bellingham, WA 98225
150, 150A thru 150H, 150J, 150K, 150L, M, A150M, 170A, B, 172, 172A thru 172I, 172K, L, 175, 175A, B, C, 180, 180A, 180H, 182, 182A thru 182N, 185, 185A thru 185E, A185E, 188, 188A, A188, A188A, 206, P206 thru P206E, U206, U206A thru U206F, TP206A thru TP206E, TU206A thru TU206F, 210, 210A thru 210K, T210F, T210G, T210H, T210J, T210K, (205) 210-5, (205A) 210-5A; T.C. 3A19, A-799, 3A17, 5A6, 3A13, 3A24, A9CE, 3A12, A4CE, 3A21	SA172NW	Installation of drooped type wing tips. Issued 4/14/75.	NW	19830	Robert C. Cansdale 29511 9th Place S. Federal Way, WA 98002

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150, 150A, B, C, D, E, F, G, H, J, K, L, M, 152; T.C. 3A19	SA175GL	Convert to conventional landing gear. Amended 12/5/78.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 SW London, OH 43130
150, 150A thru H, 150J thru M, A150K, A150L, A150M, 152, A152; T.C. 3A19	SA223GL	The installation of the stall strips. Amended 4/24/79.	GL	52650	MacKenzie Aviation Company 3847 Bassett Road Rootstown, OH 44272
150, 150A thru H, J thru M, A150K thru A150M, 152, A152; T.C. 3A19	SA268GL	Installation per Bolen Drawing No. 8978 or wheel and ski adapters on Models 150F, G, H, J, K, L, M, 152 aircraft modified per STC SA175GL. Installation per Bolen Drawing 879, adapter, extension-landing gear gear Drawing No. 880 landing-gear extended-assembly on Models 150, 150A thru H, J thru M, A150K thru A150M, 152 thru H, J thru M, A150K thru A150M, 152, A152 aircraft modified per STC SA175GL. Amended 3/5/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
150, 150A, B, C, D, E; T.C. 3A19	SA318GL	Bolen wheel extenders on Cessna models modified per STC SA175GL and/or SA268GL. Issued 6/12/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M; T.C. 3A19	SA324GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
150, 150A, B, C, D, E, F, G, H; T.C. 3A19	SA326EA	Wet-to-dry vacuum pump conversion kit 300-3. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
150-150C, 1500# Gr. Wt., 150D-150K, 1600# Gr. Wt.; T.C. 3A19	SA403CE	Install FluiDyne A2000A main skis and NA800 nose ski. Amended 2/24/70.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
150 thru 150G; T.C. 3A19	SA527CE	Installation of Hoskins Twilighter Mark I high intensity light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
150 thru 150H, 150J, 150K, 150L, A150L, 150M, A150M Normal Category (landplanes), 150G and H, J, K (seaplanes) and A150K acrobatic category landplane; T.C. 3A19	SA572CE	Install Lycoming engine and Sensenich propeller on landplanes and on seaplanes. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
150; 172, 172, B; 175; 180, 180A, B, C, D; 182, 182A, B, D, D; 185, 185A; 210, 210-5; 195, 195A, 195B; 310, 310A, B, C, D, E, F, G; T337G; T.C. 3A19, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21, A790, 3A10, A6CE	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150, 150A thru 150M, A150K, L, M; 172, 172A thru M; 175, 175A thru C, P172D; 177, 177A, B; 177RG; 180, 180A thru 180J; 182, 182A thru 182P; 185, 185A thru 185E, A185E, A185F; 188, 188A, B, A188, A188A, A188B; 206, P206, P206A thru P206E, TU206A thru TU206F, TP206A thru TP206E, U206, U206A thru U206F; 207, T207, 207A, T207A; 210, 210A thru 210L, T210F, G, H, L, 210-5, 210-5A; 310, 310A thru 310J, 310J-1, E310J, 310K, L, N, P, 310Q, T310P, T310Q; 320, 320A thru 320F, 320-1, 340; 336; 337, 337A thru 337F, T337D, E, F, G; 401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 421, 421A, B; T.C. 3A19, 3A12, 3A17, A13CE, A20CE, 5A6, A-790, 3A13, 3A24, A9CE, 3A19, A4CE, A16CE, 3A21, 3A24, 3A10, 3A25, A2CE, A6CE, A7CE, A16CE	SA615EA	Installation of Whelen anti-collision strobe light system, models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
150, 150A thru G; 170, 170A, 170B; 172, 172A thru 172E; P172D, 175, 175A thru 175D; 180, 180A thru 180H; 182, 182A thru 182J; 185, 185A thru 185C; 195, 195A, 195B; 210, A thru I; 310, 310A thru 310H; T.C. 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A24, A-790, 3A21, 3A10	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
150, 150A thru L, A150K, 172I, 172K, 172L; T.C. 3A19, 3A12	SA695CE	Install Frantz oil filter. Amended 5/25/71.	GL	70360	Schmidt Aero Service Municipal Airport Worthington, MN 56187
150 thru 150H, 150J, 150K, A150K, A150L, 150M (landplanes), 150G, 150H, 150J, 150K (seaplanes) 150 hp only; T.C. 3A19	SA750CE	Installation of Lycoming 150 and 160 hp Model O-320-( ) engine and McCauley propeller 1C172/TM. Amended 10/10/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North Wichita, KS 67204
150, Serial Nos. 15061533 and up; T.C. 3A19	SA844CE	Installation of electro pneumatic stall warning system. Issued May 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
150, 172, 175, 177, 180, 182, 185, 206, 210 Series; T.C. 3A19, 3A12, 3A17, A13CE, 5A6, 3A13, 3A24, A4CE, 3A21	SA890SW	Medairco Automatic Fuel Alert F-2.	SW	57500	Medairco 3601 East Admiral Place Tulsa, OK 74150
150, 150A, B, C, D, E, F, G, H, J, K, L; T.C. 3A19	SA909CE	Install STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
150, 150A, B, C, D, E, F, G, H, J, K, L; T.C. 3A19	SA944CE	STOL kit installation. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150 thru 150M, A150K, L, M; 170, 170A, 170B; 172 thru 172N; 177B; 177RG; 180 thru 180J, K; 182 thru 182Q; 185 thru 185E, A185E; A185F, R172K; 206, P206 thru P206E, TP206A thru TP206E, TU206A thru TU206E, U206 thru U206G; TU206A thru TU206G, TP206A thru TP206E, 207, 207A, T207A, T207; 210 thru 210F; 210K, L, M, T210K, L, M, 336; 337 thru 337F; T337B thru T337F; T.C. 3A19, A-799, 3A12, A13CE, 5A6, 3A13, 3A24, A4CE, A16CE, 3A21, A2CE, A6CE, A20CE, 3A17	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 11/30/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
150, A thru G; 172, A thru H; 175, A, B, C; 177; 180, A thru H; 182, A thru K; 185, A A thru E, A185E; 190; 195 A & B; 206, P206, U206, P206A, U206A, TP206A, TU206A, P206B, TP206B, TU206A; U206B, TU206B, P206C, U206C, TP206C,206C; 210, A thru G, T210-F, -G, 210-5(205)-5A(205A); 336; 337 A, B, C, T337C; T.C. 3A19, 3A12, 3A17, A13CE, 5A6, 3A13, 3A24, 790, A4CE, 3A21, A2CE, A6CE	SA1261WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Subsidiary Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
150, 150A, B, C, D, E, F, G. H, J, K, A150K; T.C. 3A19	SA1346CE	Chrome plate brake disc installation. Amended 9/6/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
150, 170, 172, 175, 180, 182, 185 Series; T.C. 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A24	SA1455WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reid 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
150, 170, 175, 180, 182, 185 Series; T.C. 3A19, A-799, 3A17, 5A6, 3A13, 3A24	SA1473WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
150; 170; 172; 175; 177; 180; 182; 185; 190; 206; 195 Series; 210 Series; 310 Series; 320; 336; 337; 401, 401A, 402, 411, 411A, 421; T.C. 3A19, 799, 3A12, 3A17, A13CE, 5A6, 3A13, A9CE, 790, A4CE, 3A21, 3A10, 3A25, A2CE, A6CE, A7CE	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 6/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
150, 150A thru 150H, J; T.C. 3A19	SA1944WE	Installation of Madras wing tips. Amended 4/23/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
150 thru 150L; T.C. 3A19	SA1977WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
150, 150A thru 150E; T.C. 3A19	SA2053WE	An adjustable lateral trim capability through spring bungee control of aileron per Strato Engineering Company. Reissued 5/23/73.	WE	25940	Consulting Aerospace Engineers 1845 Empire Burbank, CA 91504
150, 150A, B, C, D, E, F, G, H, J, K, A150K, L, A150M; T.C. 3A19	SA2850SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150; 170; 172; 175; 177; 180; 182; 185; 190, 195; 206; 210; 310; 320; 336; 337; 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A19, 799, 3A12, 3A17, A13CE, 5A6, 3A13, A9CE, 790, A4CE, 3A21, 3A10, 3A25, A2CE, A6CE, A7CE	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm).	WE	48750	K S Avionics 18145 Judy Street Castro VAlley, CA 94546
150 thru 150K; T.C. 3A19	SA2119WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
150, 150A thru 150H; 150J, 150K, A150K, 150L, A150L; T.C. 3A19	SA2219WE	Installation of Filtrator Company engine crankcase breather and vacuum pump air-oil separator. Reissued 7/10/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route 1, Box 172D Leesburg, FL 32748
150, 150A thru 150H, 150J, K, L; T.C. 3A19	SA2790WE	Installation of angle of attack indicator. Issued 12/10/73.	WE	78470	Thompson Aircraft Company 8219 Billy Mitchell Drive Santee, CA 92071
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M, 152, L, M, 152, A152; T.C. 3A19	SA3112WE	Installation of flap slot closures. Amended 7/19/77.	WE	78450	Thermal Aircraft Company 56 - 850 Thermal Street Thermal, CA 92274
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M, 152, L, M, 152, A152; T.C. 3A19	SA3345WE	Recognition light installation on horizontal stabilizer. Amended 6/29/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
150, 150A, B, C, D, E, F, G, H, J, K, A150L, A150M, 150M, 152, A152; T.C. 3A19	SA4065SW	Metal chip detector in engine oil. Issued 12/4/79.	SW	02323	Aero Logistics International P.O. Box 34395 Dallas, TX 75234
150C, 150D, 15, 150F, 150G, 150H, 150J, 150K, 150L; T.C. 3A19	SA2687WE	Installation of protective device on fuel tank vent line. Issued 5/17/73.	WE	68516	S. Harry Robertson Research Engineers 8002 E. Cypress Street Scottsdale, AZ 85257
150D thru G; 172D thru H; 182A thru L; 206, P206, -A, -B, U206, -A, -B, TU206A, -B, TO206A, -B; 210, D thru F, T210F; 310 D thru P; 320 D, E, F; 337A; 411; T.C. 3A19, 3A12, 3A13, A4CE, 3A21, 3A10, 3A25, A6CE, A7CE	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs SA603SW, SA606SW, SA607SW, SA621SW, SA624SW, SA637SW, SA667SW, SA669SW, SA675SW, SA681SW, SA709SW, SA727SW, SA737SW, SA789SW, SA795SW, SA658SW, SA668SW.	SW	60000	EDO-AIRE Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
150D thru H, J, K, L, M, A150K, A150L; M; T.C. 3A19	SA1809WE	Installation of one twelve-gallon auxiliary fuel tank in each outboard wide panel. Amended 4/20/77.	WE	37580	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
150D thru 150K; T.C. 3A19	SA2191WE	Installation of recontoured wing leading edge, stall fences, and drooped ailerons in flaps down mode. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98004
150D thru H, J, K, L, M, A150K, A150L; M; T.C. 3A19	SA2192WE	Installation of recontoured wing leading edge, stall fences, and drooped ailerons in flaps down mode. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
150, 150D thru H, 150J, K, L, M; T.C. 3A19	SA3037SW-D	Automatic flight system AK457 consisting of Century I autopilot with optional omni tracker. Issued 1/17/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
150D, E, F, G, H, J, K, L utility category; T.C. 3A19	SA3733WE	Installation of a special door (right hand side only) to facilitate aerial photography. Issued 9/6/78.	WE	26718	Robert M. Craig 131 Burwell Road Highland, TX 77562
150E, F, G; 172 thru 172D, F, G, H, M; 175A, B, C; 177; 180A thru H; T.C. 3A19, 3A12, 3A17, A13CE, 5A6	SA1431WE	Installation of rudder trim system. Amended 4/2/78. tive flight control sealed drawings. Amended 3/15/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150F; T.C. 3A19	SA287GL	Installation of Lycoming O-320-D2B engine and McCauley Model 1C172/TM propeller using the existing installation hardward on an aircraft previously modified in accordance with STC SA572CE. Issued 12/15/78.	GL	71505	Max L. Shanklin 1769 Rooker Road Mooresville, IN 46158
150F, G, H, J; T.C. 3A19	SA221GL	Installation of wheel replacement type skis, FluiDyne all metal (TSO approved) Model A2000A main skis, FluiDyne Model AT2000A tail ski. Issued 2/14/78.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
150F thru K; T.C. 3A19	SA2035WE	Installation of Aerial photographic camera kit serial No. 101. Amended 7/17/70.	NW	34824	Federal Water Pollution Control Administration Pacific Northwest Water Laboratory 200 S.W. 35th Street Corvallis, OR 97330
150F, G, H, J, K; T.C. 3A19	SA2846SW	Conversion from trigear to conventional gear configuration and reconversion to trigear. Issued 9/8/78.	SW	28000	Custom Craft, Inc. 234 West Turbo Drive San Antonio, TX 78216
A150K, A150L; T.C. 3A19	SA1395SW	Revise fuel and oil system for inverted flight. Issued 11/24/71.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
A152; T.C. 3A19	SA1384CE	Install Lycoming 0-320-E2D engine and McCauley 1C172TM7458 propeller. Issued 11/11/77.	CE	12777	Avcon Industries 1006 W. 53rd Street N. Wichita, KS 67204
170 Series; T.C. 799	SA1-13	Recovering of wings with metal except ailerons and flaps.	GL	37182	General Aviation, Inc. P.O. Box 232 Lost Nation Airport Willoughby, OH 44094
170 Series; T.C. 799	SA1-107	69A103 gyro stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
170 Series; T.C. 799	SA1-240	Lycoming O-435-C engine and Hartzell HC-12X20-8D/8433-6 or HC-12X20-5C/8433-6 propellers.	NE	37050	Fulton Conversion Company Southbury, CT 06488
170 Series; T.C. 799	SA1-245	Lycoming O-340-A1A engine and Hartzell HC-82XL-1D/8433-12 propeller on aircraft with Edo 89-2000 floats.	NE	79952	Turner Aviation Company, Inc. Turner, ME 04282
170 Series; T.C. 799	SA1-316	Dart I-M turn control unit.	EA	61400	Navigation Devices, Inc. P.O. Box 1107 Binghamton, NY 13902
170 Series; T.C. 799	SA1-416	Lube oil filter. Amended 9/11/67.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
170 Series; T.C. 799	SA1-426	Auxiliary seat in baggage compartment.	NE	84950	William A. Welch Royce Road, RD-1 Danbury, CT 06810
170 Series; T.C. 799	SA1-647	Leading edge landing lights.	EA	72100	Skycraft Design, Inc. Mercer County Airport West Trenton, NJ 08628
170 Series; T.C. 799	SA3-53	Model 3000 main and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-159	C-3000 main and AWT 2500A or CT-3000 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-329	C-3000 main ski and AWT 2500A tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-339	C-3000 wheel ski on airplanes having a cross-wind wheel utilizing a 6.00-6 tire.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-451	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1504 Gretchen Wichita, KS 67202
170 Series; T.C. 799	SA3-695	Dacron fabric on wings.	GL	30518	Downer Aircraft Company Alexandria, MN 56308

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	S.C Holder
170 Series; T.C. 799	SA4-7	Recovering of wings with metal skin. Amended July 1973.	WE	73000	Leo F. Smith & Company, Inc. 225 South Bent San Marcos, CA 92069
T170 Series; T.C. 799	SA4-11	Recovering of wings with metal except flaps and ailerons.	WE	02620	Aero Sales & Service, Inc. Chandler Field Fresno, CA 93721
170 Series; T.C. 799	SA4-28	Conversion to tricycle gear type.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170 Series; T.C. 799	SA4-55	13-gallon auxiliary fuel systen.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170 Series; T.C. 799	SA4-226	Metal skin on wings.	WE	18275	Frank A. Burdick 43316 N. 20th Street, W. Lancaster, CA 93534
170 Series; T.C. 799	SA4-486	Glass cloth with resin applied.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
170 Series; T.C. 799	SA4-802	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
170 Series; fT.C. 799	SA4-993	Full flow filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
170 Series; T.C. 799	SA4-1062	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
170 Series; T.C. 799	SA4-1096	Eonite covering on wings.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
170 Series; T.C. 799	SA5-44	Conversion of aircraft for parachute jumping operations.	AL	14900	Barton Air Service 1700 E. Fifth Avenue Anchorage, AK 99500
170 Series; T.C. 799	SA15CE	Dry vacuum pump and vacuum system 113A6.	GL	03760	Airborne Mechanisms Division Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
170 Series; T.C. 799	SA235SO	Recovering of wings with .020 alclad 2024-T3 aluminum.	SO	43300	Hudson Aircraft Service P.O. Box 2471 W A S Tallahassee, FL 32302
170 Series; T.C. 799	SA236WE	Cessna 210 wing tips 12230000-1 and -2.	RM	84394	Donald H. Wagner P.O. Box 267 Grand Junction, CO 81501
170 Series; T.C. 799	SA351WE	Pneumatic pitch assist PC-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
170 Series; T.C. 799	SA544CE	Installation of Flight Systems Model 500B white strobe beacon.	GL	35727	Flight Systems P.O. Box 62 Wheeling, IL 60090
170 Series; T.C. 799	SA1008WE	Poly-Fiber covering of both wings. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
170, 170A, 170B; T.C. 799	SA2-224	Windshield manufactured in accordance with Luminous Plastics, Inc. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
170, 170A, 170B; T.C. 799	SA23GL	Installation of wheel replacement skis Model M2000, M3000. Reissued 1/13/76.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapid, MN 56470
170, 170A, 170B; T.C. 799	SA135CE	Lycoming O-320-A1A, -A1B, -A3A, -A3B, or O-320-B1A, -B1B, -B3A, or B3B engine, Hartzell HC-82X or -A2X Series propellers with 7636D-4 blades and Woodward 210080 governor. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170, 170A, 170B; T.C. 799	SA196NW	Installation of blown bubble, one-piece, clear plexiglass windshield. Issued 7/10/75.	NW	71506	Jack Shannon 8451 S.E. 39th Mercer Island, WA 98040

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170, 170A, 170B; T.C. 799	SA210GL	Installation of Great Lakes Aero Products windshield P/Ns W-2055, W/T-2055 or W/G-2055. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
170, 170A, 170B; T.C. 799	SA224AL	Installation of L-2500A or L-3000 skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
Cessna 170, 170A, 170B; T.C. 799	SA632AL	Install McCauley 1A1757DM80 propeller.	AL	08492	Alaska Propeller Specialists, Inc. 5251 Lakeshore Drive Anchorage, AK 99503
170, 170A, 170B, 172, 172A; T.C. A-799, 3A12	SA152NW	Installation of deck and glare shield (with and without instrument lights). Issued 1/13/75.	NW	70384	R.J. Schroers 4479 139th Avenue, S.E. Bellview, WA 98006
170 thru 170B, 172 thru 172K, P172D, R172E, R172F, 175 thru 175C, 180 thru 180H, 182 thru 182M, 185 thru 185E, A185E; T.C. 799, 3A12, 3A17, 5A6, 3A13, 3A24	SA605CE	Install O'Neill Model "Ultralite" 7G aircraft.	GL	61850	O'Neill Airplane Company 791 Livingston Carlyle, IL 62231
170, -A, -B; 172, -A thru -H; 175, -A, -B, -C, P172D, R172E (T41B); *177; 180, -A, -B, -C, -D, -E, -F, -G, -H; 182, -A, -B, -C, -D, -E, -F, -G, -H, -J, -K; 185, -A, -B, -C, -D, -E, A185E; 210, -A, -B, -C, -D, -E, -F, T-210F, 210G, T-210G, 210-5(205), 210-5A(205A); 401, 402, 411, 411A; T.C. A-799, 3A12, 3A17, A13CE, 3A13, 3A24, 3A21, A7CE *Approved anti-collision light system is required.	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
170, 170A, 170B; T.C. A-799	SA2472WE	Installation of strobe light systemNW with flashtube or rudder tip and power supply in fuselage. Issued 2/9/72.		70384	R.J. Schroers 4479 139th Avenue S.E. Bellevue, WA 98006
170, 170A, 170B; T.C. A-799	SA3715WE	Installation of vertical tail floodlight. Issued 9/27/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
170A; T.C. 799	SA1973WE	Installation of Hanna-Aero Corp. voltmeter P/N 1305.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
170A, 170B; T.C. 799	SA3-13	Install 170 hp Lycoming O-340-A1A engine and Hartzell HC-82XL-1DB/8433-12 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170A, 170B; T.C. 799	SA3-672	Lycoming O-360-A1A, A1D or B1B engine and McCauley 2D36C14-X/78KM-4 propeller or Lycoming O-360-A1A and A1D engines with Hartzell HC-C2YK-1A/7666A-2 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170A, 170B; T.C. A-799	SA325GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
170A, 170B (Landplane only); T.C. 799	SA421CE	Lycoming O-360-A1A or O-360-A1D 180 hp engine, O-360-B1B 168 hp engine and constant speed propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
170A, 170B; T.C. 799	SA749CE	Install Hartzell propeller model HC-C2YK-1A/7666A.	CE	12775	Avcon Industries, Inc. Route 1, Box 204A Augusta Municipal Airport Augusta, KS 67010
170A, 170B (landplanes, normal category only); T.C. A-799	SA806CE	Installation of Lycoming engine model O-360-A1A and McCauley propeller model HC-C2YK-1B/7666A-2. Amended September 1976.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170A, 170B; T.C. 799	SA989CE	Installation of STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
170A, 170B; T.C. A-799	SA1073CE	Installation of wing leading edge cuffs, Cessna drooped wing tips, stall fences, and aileron gap seals. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
170A, 170B (Normal Category); T.C. A-799	SA2454WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
170A, 170B (landplane only normal category); T.C. A-799	SA3797WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision, muffler in lieu of original Avcon muffler. Amended 1/11/80.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
170A, B, 172A thru 172M, 175, 175A thru 175D; T.C. A-799, 3A12, 3A17	SA115NW	Modification of R.H. Door and the addition of a jump seat. Issued 5/24/74.	NW	18260	Charles P. Bunch 1211 Donovan Avenue Bellingham, WA 98225
170A, B, 172, 172A thru 172I, K, L, M, N, 175 thru 175C; R172K; T.C. 799, 3A12, 3A17	SA1614WE	Installation of one 12-gallon auxiliary fuel tank in each outboard wing panel. Amended 2/15/79.	WE	35746	Flint Aero 8402-G N. Magnolia Gillespie Field Plaza Santee, CA 92071
170B; T.C. 799	SA111NW	Installation of McCauley 1A175-DM propeller with Cessna 0550162 spinner on Continental C-145 series and O-300 series engines. Reissued 6/28/74.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
170B; T.C. 799	SA602AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA602AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	AL	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA603AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA603AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	AK	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA604AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA604AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA1417SW	Mitchell automatic flight system AK358 consisting of Century I autopilot with optional omni tracker. Issued 1/10/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
170B; T.C. A-799	SA1490CE	Installation of flap and aileron gap seals.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
170B (Landplane only, Normal & Utility Category); T.C. A-799	SA2100WE	Installation of contoured wing leading edge and aileron gap cover. Reissued 1/18/77.	WE	65700	Marshall E. Quackenbush P.O. Box 235 Inyokern, CA 93527
170B; T.C. A-799	SA2851SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
170B (Landplane only, Normal & Utility Category); T.C. A-799	SA3318WE	Installation of flap gap closures. Issued 1/5/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
170B, 172 A, B, C, 175, A, B, C, 180, A, B, C, D, F, 182, A, B, C, D; T.C. A-799, 3A12, 3A17, 5A6, 3A13	SA1-612	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170B, 172, 172A, 172B, 172C, 172D; T.C. A-799, 3A12	SA93EA	Installation of Monitair angle of attack system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
170B; 172, 172A thru H, 175, 175A, B, C, 180, 180A thru H, 182, 182A thru D; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA175EA	Installation of wing struts modified to include Wings With Springs Model 200 hydraulic-pneumatic shock absorbers and associated airframe modifications. Amended 8/17/77.	EA	86500	Wings With Springs, Inc. Box 495, R.D. 3 Latrobe, PA 15650
170B, 172, 172A, B, C, D, E, F, G, H, I, K, L, M, 172M, 175, 175A, B, C; T.C. A-797, 3A12	SA293NW	Installation of Franklin 6A0350-Ce engine, McCauley 2A31C21/84S06 propeller using Kit No. 20690 as per STC SA360EA. In addition, installation of Hartzell HC-C2YF-1BF/F8459-4 to -8 conjunction with same engine. Issued 6/22/76.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98661
170B, 172, 172A; T.C. A-799, 3A12	SA360EA	Installation of Franklin Engine Co., Inc. Model 6A-335-B engine with McCauley 2A31C21/84S-8 propeller and new engine mount and associated components. Amended 6/19/70.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
170B, 172 thru 172L; T.C. A799, 3A12	SA499NW	Installation of Robertson Aircraft STOL kit with Robertson leading edge cuff, fence, Cessna wing flap filler panel. Issued 8/29/77.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98660
170B, 172B thru M, 175, 175A thru C; T.C. A797, 3A12, 3A17	SA637NW	Instllation of AC oil filter assembly OF-104A. Issued 7/13/78.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98661
170B; 180; 185; T.C. 799, 3A24, 5A16	SA1971WE	Installation of Model ARB-3 Automatic Downed Aircraft Marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue, Box 822 Fort Collins, CO 80521
170, 172 Series T.C. 799, 3A12	SA4-1404	Vacuum system 121 and 121A. (Eligible only on engines with dampened crankshafts).	WE	40685	Marlin and Myron Harms 10828 Burl Avenue
170, 172 Series; T.C. 799, 3A12	SA318WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
170, 172 Series; T.C. 799, 3A12	SA429WE	Exhaust pipe extensions LG-100.	WE	39463	Lloyd M. Green 619 W. Roses Road San Gabriel, CA 91776
170, 172 Series; T.C. 799, 3A12	SA672SW	Cessna 305(L-19) wings.	SW	76737	James A. Summersett, Jr. 418 Redcliff Drive San Antonio, TX 78216
170, 172 Series; T.C. 799, 3A12	SA733WE	12.7-gallon auxiliary fuel tank.	WE	05600	Aircraft Modification and Repair 20331 Hesperian Boulevard Hayward, CA 94541
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA1-426	Auxiliary seat in baggage compartment.	NE	84950	William A. Welch Boyce Road, RD-1 Danbury, CT 06810
170, 172, 175 Series; T.C. 799, 3A12, 3A17	SA1-516	Griswold lateralizer and heading lock.	NE	39800	Herbert Haer 80 Federal Street Boston, MA 02109
170, 172, 175 Series; T.C. 799, 3A12, 3A17	SA1-545	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
170, 172, 180, 182 Series; T.C. 799, 3A12, 5A6, 3A13	SA3-75	Grimes rotating anti-collision light D-7080-1-12.	GL	59360	Mid States Aviation Corporation Sky Harbor Airport Northbrook, IL 60062
170, 172, 175, 180 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA3-333	Installation of Doyn fiberglass wheel fairings. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170, 172, 175, 180 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA4-367	Super automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
170, 172, 175, 180 Series; T.C. 799, 3A12, 3A17, 5A6	SA4-620	Baggage door on left side of fuselage.	WE	08262	The Air Oasis 2601 E. Spring Street Long Beach, CA 90801

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170, 172, 180, 182; T.C. 799, 3A12, 5A6, 3A13	SA4-662	Camera pod.	WE	52710	Clifton G. McBride 620 Rollingwood Drive Vallejo, CA 94590
170, 172, 175, 180, 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA4-676	RDF-2 radio direction finder.	WE	70275	Savage Industries, Inc. 3125 N. 29 Avenue Phoenix, AZ 85000
170, 172, 175, 180, 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA5-12	Rear canvas hammock seat.	AL	05958	Aircraft Rebuilders 1803 Lake Otis Road Anchorage, AK 99500
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA81WE	Aileron and rudder trim controls.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA158CE	Cessna wing tips and attached lights 1223000-1 left, 1223000-2 right tips, and 1423006-12 left, 0423006-13 right lights, or an equivalent.	GL	70385	Schott Aviation, Inc. Baldwin Field Quincy, IL 62301
170, 172, 175, 180, 182, 185 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13, 3A24	SA238SW	Cargo door. Reissued 4/6/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA765WE	SP51463-1A speedplates.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
170, 172, 180, 182, 185 Series; T.C. 799, 3A12, 5A6, 3A21, 3A24	SA981WE	Two detachable folding rear	WE	59730	Missionary Aviation Fellowship P.O. Box 32 Fullerton, CA 92632
170, 180 Series; T.C. 799, 5A6	SA1-188	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
170, 180 Series; T.C. 799, 5A6	SA3-468	CF-3000 main wheel skis and AWT 2500A or CT-3000 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170, 180 Series; T.C. 799, 5A6	SA463WE	Jump door 62-500.	NW	72250	Skymotive, Inc. Route 1, Box 32 Snohomish, WA 98290
172 Series; T.C. 3A12	SA1-9	69A115 gyro-stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
172 Series; T.C. 3A12	SA1-116	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
172 Series; T.C. 3A12	SA1-438	Lycoming O-360-A1A engine and McCauley 2D36C14/78 KM-4 propeller with Woodward 210105 AA governor.	NE	90160	Albert E. Zotack 295 First Avenue Stratford, CT 06497
172 Series; T.C. 3A12	SA3-11	Propeller installations - Two-position controllable, hub 2B-36C7, blades 78K-2 or 78K-4.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45401
172 Series; T.C. 3A12	SA3-82	Retractable lifting handles Model H, P/N 50-9.	GL	87750	Woychik Aircraft Equipment Middleton, WI 53562
172 Series; T.C. 3A12	SA3-89	Equipment shelves and Grimes D-7080 rotating beacon.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
172 Series; T.C. 3A12	SA3-90	Lear ADF loop and housing.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
172 Series; T.C. 3A12	SA3-107	Rudder trim system.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
172 Series; T.C. 3A12	SA3-108	Single axis automatic pilot A-2 or A-3.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
172 Series; T.C. 3A12	SA3-126	Lycoming O-340-A1A engine and Hartzell HC-82XG-1DB/8433-12 propeller. Reissued 3/9/79.	29	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172 Series; T.C. 3A12	SA3-179	A3500A or A2500A main skis and NA1200A nose skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172 Series; T.C. 3A12	SA3-256	Main ski AWB2500A and nose wheel ski AWN1200.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-355	C3000 main ski and AWN1200 nose wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-614	Model 3000 main skis and Model 2000 nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-655	Wheel fairings.	RM	55700	Marsh Flying Club, Inc. 812 E. 34th Street Sioux Falls, SD 57101
172 Series; T.C. 3A12	SA3-690	Installation of Doyn swept-tail asembly kit 1400. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172 Series; T.C. 3A12	SA4-40	Automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
172 Series; T.C. 3A12	SA4-198	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
172 Series; T.C. 3A12	SA4-531	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
172 Series; T.C. 3A12	SA4-602	Autopilot. Reissued October 1973.	WE	17492	Brittain Industries, Inc. 12027 S. Prairie Avenue Hawthorne, CA 90250
172 Series; T.C. 3A12	SA4-686	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
172 Series; T.C. 3A12	SA44SO	Cessna L-19 wing conversion.	SO	55600	Marrs Aircraft Avon Park, FL 33825
172 Series; T.C. 3A12	SA64CE	Sky-lite B-100 beacon light.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
172 Series; T.C. 3A12	SA88CE	C-3000 main skis and AWN-1200A nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA94CE	Removal of right cabin door.	GL	72116	Skylane Flying Service, Inc. 2029 Allens Lane Evansville, IN 47708
172 Series; T.C. 3A12	SA117EA	Flow lube oil filter PB 55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
172 Series; T.C. 3A12	SA242EA	40-0040 and 40-0043 supplemental light system.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
172 Series; T.C. 3A12	SA313SO	Federal FS103 autopilot.	SO	00078	A & E Service McCollum Airport Marietta, GA 30060
172 Series; T.C. 3A12	SA414SW	Jump step or mud guard on right landing gear.	SW	73030	Curtis J. Smith, Jr. Route 2, Box 314 Breaux Bridge, LA 70517
172; T.C. 3A12	SA531NW	Installation of windshield. Issued 10/12/77.	NW	71506	Jack Shannon 215 Terminal Building Boeing Field Seattle, WA 98108
172 Series; T.C. 3A12	SA533CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
172; T.C. 3A12	SA584NW	Installation of EDO 698-2125 floats. Issued 4/5/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
172 Series; T.C. 3A12	SA603SW	AK191 Century II autopilot and AK192 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172 Series; T.C. 3A12	SA242EA	40-0040 and 40-0043 supplemental light system.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
172 Series; T.C. 3A12	SA313SO	Federal FS103 autopilot.	SO	00078	A & E Service McCollum Airport Marietta, GA 30060
172 Series; T.C. 3A12	SA414SW	Jump step or mud guard on right landing gear.	SW	73030	Curtis J. Smith, Jr. Route 2, Box 314 Breaux Bridge, LA 70517
172; T.C. 3A12	SA531NW	Installation of windshield. Issued 10/12/77.	NW	71506	Jack Shannon 215 Terminal Building Boeing Field Seattle, WA 98108
172 Series; T.C. 3A12	SA533CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
172 Series; T.C. 3A12	SA603SW	AK191 Century II autopilot and AK192 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172 Series; T.C. 3A12	SA792WE	Lycoming O-360 Series engines and Sensenich M67EMM propellers.	NW	53510	McKinzie Aircraft Repair, Inc. 1300 N. 26 Street Springfield, OR 97477
172 Series; T.C. 3A12	SA861WE	Pilot and passenger restraint harness.	WE	62125	Pacific Scientific Company 1346 S. State College Boulevard Anaheim, CA 92803
172 Series; T.C. 3A12	SA1078WE	Franklin 6A-335-B engine with McCAuley 2A31C/84S-6 propeller using EDO 89-2000 floats.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172 Series; T.C. 3A12	SA1308WE	Installation of Brittain Model CSA-1 stability Augmentation System.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
172 Series; T.C. 3A12	SA1468WE	Installation of Brittain Model B2C Autopilot System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172 Series; T.C. 3A12	SA1677SW	Wing leading edge cuff. Issued 6/20/73.	SW	73850	Southern Aircraft Corporation P.O. Box 78 Page, OK 74939
172 Series; T.C. 3A12	SA1806WE	Installation of Brittain Industries B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172 Series; T.C. 3A12	SA3072WE	Installation of emergency warning system. Issued 7/23/75.	WE	77274	Systems Management Associates, Inc. P.O. Box 957 Palo Alto, CA 94302
172, 172A, B, C, D, E, F, G, H; T.C. 3A12	SA3-571	Lycoming O-360-A1D engine, McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1A/7666-2 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172, 172A, B, C, D, E, F; T.C. 3A12	SA3-664	Install Model 113A6, 200CW-6 or 212CW-6 dry vacuum pump and instrument vacuum system. Amended 7/31/79.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
172, 172A thru 172I, K, L, M, N, P; 182, 182A thru 182N, P; T.C. 3A12, 3A13	SA21GL	Installation of Grimes multi-plexed anti-collision light system. Issued 5/9/73.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
172, 172A, B, C, 175, 175A, B, C, 182, 182A thru E; T.C. 3A13, 3A12, 3A17	SA43EA	Installation of Re-Vue Agency "nite-lite" electronic aerial advertising sign. REissued 3/15/71.	RM	67300	Re-Vue Agency, Inc. 616 East 4th Street Pueblo, CO 80204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172, 172A, 172B, 172C, 172D; 180, 180A, 180B, 180C, 180D, 180E, 180F; 182, 182A, 182B, 182C, 182D, 182E; 185, 185A, 185B, 185C, 185D; 210, 210-5, 210A, 210B, 210C; 310C, 310D, 310E, 310F, 310G, 310H; T.C. 3A12, 5A6, 3A13, 3A24, 3A21, 3A10 (310 Series thru 310H Riley conversion per STC SA212SO.)	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
172, 172A, 172B, 172C; T.C. 3A12	SA211GL	Installation of windshield P/N W-2055, W/T-2055 or W/G-2055 on Cessna 172 and 172A, and P/N W-2056, W/T-2056 or W/G-2056 on Cessna 172B and 172C. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
172, 172A, B, C, D, E, F, G, H, I, K, L, M, N; T.C. 3A12	SA296GL	Convert to conventional landing gear. Amended 11/19/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 172A, B, C, D, E, F, G, H, I, K, L, M, N; T.C. 3A12	SA315GL	Installation of Fluidyne skis. Amended 2/7/80.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 172A, B, C, D, E, F, G, H, I, K, L, M; T.C. 3A12	SA326GL	Installation of fuel tankcaps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
172, 172D, 172F; T.C. 3A12	SA340NW	Installation of Pee Kay Model 2300 floats. Issued 9/15/76.	NW	70620	Seaplane Flying, Inc. P.O. Box 2164 Vancouver, WA 98661
172, 172A, B, C, D, E, F, G, H Landplanes, 172D, E, F, G, H Floatplanes (EDO 89-2000 floats only.) T.C. 3A12	SA420CE	Lycoming O-360-A1A or A1D engine, McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1B/7666-2 propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172, A thru I; T.C. 3A12	SA729EA	Replacement of existing wheel/brake assemblies with Goodyear wheel/brake assemblies 9543679/95444295.	GL	39125	Aviation Products Division The Goodyear Tire & Rubber Company 1144 East Market Street Akron, OH 44315
172, 172A thru I, K, L, M, N (Landplanes, normal category only); T.C. 3A12	SA897CE	Install Lycoming 180 h.p. engine and constant speed propeller. Amended 1/31/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
172, S/N 17254893 and on; T.C. 3A12	SA864CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
172, 172A thru 172I, 172K, 172L, 172M (S/N 17260759 thru 17265684); T.C. 3A12	SA902CE	Install STOL kit. Amended 2/26/80.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
172 thru 172N; T.C. 3A12	SA910CE	Install STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Amended May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
172, 172A, B, C, D, E, F, G, H, I, K, M, N; T.C. 3A12	SA1484CE	Installation of flap and aileron seals. Issued 4/18/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
172, 172A thru 172G (landplanes and floatplanes), 172, 172H thru 172L (landplanes only); T.C. 3A12	SA1689WE	Installation of drooped ailerons contoured wing leading edge and wing stall fences. Amended 2/26/71.	NW	68510	Charyl C. Robertson 15209 N.E. 16th Place, Apt. #17 Bellevue, WA 98004
172 thru 172L; T.C. 3A12	SA2002WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
172, 172A thru 172L (normal category); T.C. 3A12	SA2075WE	Installation of Madras Air Service Inc. "Super Tips." Amended 8/16/72.	NW	54000	Madras Air Service, Inc. Route 2, Box 1225 Madras, OR 97741

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172A Seaplane; T.C. 3A12	SA181GL	Installation of McCauley 1A200/DFA propeller. Issued 6/16/77.	GL	77569	Les G. Taylor 1115 - 19th Street South St. Cloud, MN 56301
172A, B, C, D, E, F, G, H; T.C. 3A12, 3A17	SA18EA	Wet-to-dry vacuum pump conversion kit 300-1. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
172A thru 172M; T.C. 3A12	SA358NW	Installation of Pee Kay Model 2300 seaplane floats. Issued 8/24/76.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
172A - 172K; T.C. 3A12	SA650CE	Installation of Fleet Model 2500 floats. Reissued 12/21/71.	EA	79550	Trifield Associates 560 Daytona Drive Fort Erie, Ontario, Canada
172B, 172C, 172D, 172E, 172F, 172G; T.C. 3A12	SA116SO	Installation of Franklin Model 6A-335-B engine with 2A31C21/84S-8 propeller and new engine mount and new engine mount and associated components only on landplane models. Amended 9/9/68.	EA	36750	Franklin Engine Company, Inc. Subsidiary of Allied Aero Industries, Inc. Old Liverpool Road Syracuse, NY 13208
172B, 172C; 175 thru 175C; 180 thru 180F; 182 thru 182E; 185, 185A, 185B; 210, 210A, 210B, 210C, 210D, 210E; P206; 310 thru 310E; T.C. 3A12, 3A17, 5A6, 3A13, 3A24, 3A21, A4CE, 3A10	SA232EA	Installation of Tactair omni lock model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair model omni lock model OH-4). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
172B, G, 175A, B, C; T.C. 3A12	SA751EA	Installation of winterization kit. Issued 4/21/69.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
172B thru G; T.C. 3A12	SA1334WE	Installation of Franklin 6A-350-C2 engine and McCauley 2A31C/84S-6 propeller. Amended 9/26/68.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172B thru H; T.C. 3A12	SA1774WE	Installation of Lycoming O-320-E2D engine and McCauley 1C172/MTM7653 propeller.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172D, P172D, 182E, F, 185, 185A, 185B, 210, 210A; 210B, 210C, 210-5; T.C. 3A12, 3A17, 3A24, 3A21, 3A13	SA17EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
172D, E, F, G, H, I, K; T.C. 3A12	SA315GL	Installation of Fluidyne skis. Issued 5/31/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172D, E, F, G, H, I, K; T.C. 3A12	SA319GL	Bolen wheel extenders on Cessna models modified per STC SA296GL. Issued 6/12/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172D thru 172K; T.C. 3A12	SA365NW	Installation of Pee Kay Model 2300 seaplane floats. Approval is intended for installation in listed models with Franklin 6A0360-C2 engine installation IAW Seaplane Flying, Inc., STC SA340NW. Issued 10/5/76.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
172D, 172E (seaplane); T.C. 3A12	SA596WE	Installation of Doyn Aircraft Company kit per STC SA3-571. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172, E thru L; T.C. 3A12	SA1221SW	Mitchell automatic flight system AK312 consisting of Century I with optional omni tracker. Issued 11/18/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172D thru 172I, K, L; T.C. 3A12	SA1645SW	Mitchell automatic flight system AK403, consisting of Century IIB autopilot with optional radio coupler. Issued 4/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172D thru 172K Seaplane Versions; T.C. 3A12	SA1694WE	Installation of Franklin 6A-350-C2 engine, McCauley 2A31C/84S-6 propeller, and Aqua Float Corp., Model 2400, or EDO Corp. Model 248B-2440 floats (Columbia Marine, Inc. Kit #106) for operation on wheels, floats or skis @ 2400 lbs. g.w. (Fluidyne Model 3000 main and 2000 nose skis required for ski operations. Amended and reissued 5/1/70.	EA	36750	Franklin Engine Company, Inc. Sub. Allied Aero Industries, Inc. Old Liverpool Road Syracuse, NY 13208
172D, 172E; T.C. 3A12	SA2268WE	Installation of Brittain Industries B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172D, E, F, G, H; T.C. 3A12	SA2375SW	Install Lycoming O-320-D2G engine rated for 160 h.p. take-off and 150 METO. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
172D thru M, 177, 177A, B, 177RG, 182L, M, N, 206, C, U206, U206B, D, E, F, TP206A, B, P206A, B, TU206A, B, C, D, E, F, P206E, TP206E, 210D, E, F, L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE, A20CE, 3A12	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot system. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
172D thru L, 177, A, B, 182L, M, N, 206, U206, B, C, D, E, TU206B, C, D, E, P206A, B, TP206A, B, P206E, TP206E, 210E, D, F, L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE, 3A21	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot system. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
172D, E, F, G, H, I, K, L, M, 177, A, B, 182E thru N, U206C, D, E, F, TU206C, D, E, F, P206E, TP206E, 210, 210D, E, F, L, 210L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE	SA2654WE	Installation of Pathfinder Model P2A( ) autopilot. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Road Torrance, CA 90505
172D, E, F, G, H, I, K, L; T.C. 3A12	SA3046SW-D	Automaticght system AK524 consisting of Century IIB autopilot with optional radio coupler. Issued 3/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172F, G, H, I, K, L; T.C. 3A12	SA1311CE	Chrome plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
172G; T.C. 3A12	SA299GL	Installation of Cessna Nav-O-Matic 200A autopilot. Issued 4/2/79.	GL	37077	Galesburg, AP & L R.R. 2, Airport Galesburg, IL 61401
172H; T.C. 3A12	SA204GL	Installation of Avco Lycoming O-320-E2D engine. Issued 12/16/77.	GL	65326	Professional Aviation, Inc. Porter County Airport 3801 Murvihill Road Valparaiso, IN 46383
172H; T.C. 3A12	SA414NW	Installation of Lycoming O-360-A1F6D engine and McCauley propeller. Issued 3/15/77.	NW	70040	Salem Aviation 2680 Aerial Way S.E. Salem, OR 97302
172I, 172K, 172L; T.C. 3A12	SA87NW	Installation of Lycoming O-360-A1A 180 h.p. engine and Hartzell HC-C2YK-1A/7666A-0 propeller. Amended 12/12/74.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
172I, 172K, 172L, 172M seaplane (normal category only); T.C. 3A12	SA332GL	Installation of Lycmoming O-360-A4A engine and McCauley 1A200/DFA propeller. Issued 8/17/79.	GL	77569	Les G. Taylor 1115 - 19th Street South St. Cloud, MN 56301
172I and 172K landplanes and seaplanes EDO 89-2000 (floats only), 172L, 172M, 172N (landplanes) (12 volt only); T.C. 3A12	SA647CE	Install Lycoming O-360-A1A 180 h.p. engine and constant speed propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172I, K, M, R172K (floatplane configuration); T.C. 3A12, 3A17	SA665CE	Installation of Model 2400 Aqua floats. Amended 7/10/79.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
172I, 172K, 172L, 172M; T.C. 3A12	SA992CE	Installation of 10-inch diameter camera hole per Product Development Group, Inc. Issued February 1974.	CE	36000	Floair, Inc. Mid-Continent Airport Wichita, KS 67209
172I, 172K, 172L, 172M, 172N (Seaplane); T.C. 3A12	SA1000EA	Installation of Pee-Kay Model 2300 or B2300 (TSO-C27-2) seaplane floats. Amended 7/19/78.	EA	29998	Pee Kay Float Division Devore Aviation Corporation 206 Newton Road Plainview, NY 11803
172I, 172K, 172L, 172M (Landplane); T.C. 3A12	SA1225CE	Installation of Lycoming O-320-E2D/ STC SE1226CE or O-320-D2G engine and McCauley 1C160/CTM 7557 or 1C160/DTM 7557 propeller. Amended March 1977.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
172I, 172K thru 172N; T.C. 3A12	SA3777WE	Installation of flexible stainless steel oil cooler hoses. Issued 10/31/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
172I, 172K, 172L, 172M, 172N; T.C. 3A12	SA3858WE	Installation of an air/oil separator. Issued 3/2/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036.
R172K; T.C. 3A17	SA1491CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
172K; T.C. 3A17	SA3824SW-D	Mitchell automatic flight system AK730 consisting of Century I autopilot with optional omni tracking system. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172K, 172M (normal category landplane only); T.C. 3A12	SA2575WE	Installation of observer station in rear seat-baggage compartment area, searchlight and dual speakers in bottom of aft fuselage, windows in baggage compartment area (baggage was removed), and a muffler. Amended 1/4/73.	WE	87465	World Associates, Inc. 430 Wilshire Boulevard Suite 204 Santa Monica, CA 90401
172L; T.C. 3A12	SA494SO	Installation of radio equipment rack in instrument panel. Issued 2/18/72.	SO	18400	Burnside-Ott Aviation Training Center 12800 S.W. 137 Avenue Miami, FL 33156
172L, S/N 17259224 thru 17260758; T.C. 3A12	SA965CE	Installation of Model IU328-001 vacuum pump and IU292-003 suction relief valve. Issued November 1973.	CE	43600	EDO-AIRE Wichita Division 1326 S. Walnut Wichita, KS 67213
172M; T.C. 3A12	SA6NE	Installation of Whelen anti-collision strobe light power supplies, Models HS-41 and HD-42 as direct replacements for Models HS and HD installed in accordance with STC SA615EA or STC SA800EA. Issued 3/21/74.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
172M; T.C. 3A12	SA1798SW	Mitchell Automatic Flight System AK467 consisting of Century IIV Autopilot with optional Radio Coupler. Issued 1/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M; T.C. 3A12	SA1799SW	Mitchell Automatic Flight System AK472 consisting of Century I Autopilot with optional omni tracker. Issued 1/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M; T.C. 3A12	SA2671WE	Installation of upper wing surface stall fences and aileron gap sealing strips. Issued 3/19/73.	WE	39520	Group One 2915 Earhart Apron Torrance, CA 90505
172M, 172N; T.C. 3A12	SA146GL	Installation of EPA portable enviro pod. Amended 12/10/79.	GL	07696	AFAL/RWF Wright-Patterson AFB, OH 45433
172M, 172N; T.C. 3A12	SA380GL	Installation of Tull microwave landing system airborne equipment. Issued 12/21/79.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172M, 172N; T.C. 3A12	SA1402CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172M, 172N; T.C. 3A12	SA3200SW-D	Automaitc flight system AK467 consisting of Century II autopilot with optional radio coupler. Issued 4/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA3201SW-D	Automatic flight sytem AK472 consisting of Century I autopilot with optional omni tracker. Issued 4/7/77.	SW	6000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA4080SW	Stall fences, aileron seals. Issued 1/30/80.	SW	18600	Bush Conversions P.O. Box 61 Guthrie, OK 73044
172M, 180J, 182P, A185F, A188B, 188B, U206F; T.C. 3A12, 3A13, 5A6, 3A24, A4CE, A9CE	SA974EA	Installation of L/R wing tip transparent fairing and sensor mounting bracket. Issued 2/26/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
172N; T.C. 3A12	SA168GL	Install Heath Kit Model 01-1154 aircraft digital clock/timer. Issued 4/28/77.	GL	41610	The Heath Company Hilltop Road Benton Harbor, MI 49022
172N; T.C. 3A12	SA584NW	Installation of Edo 689-2130 seaplane floats. Amended 1/8/80.	NW	32625	Edo-Aire, Seaplane Division 65 Marcus Drive Melville, NY 11746
172N; T.C. 3A12	SA1324CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/7666A-2 propeller. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 North Wichita Station Wichita, KS 67204
172N; T.C. 3A12	SA3301SW-D	Mitchell automatic flight system AK730, consisting of Century I autopilot with optional omni tracking system. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A12	SA3302SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A17	SA3303SW-D	Mitchell automatic flight system AK/32 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P172D; 180D, 180F; 182A, 182A-F; 185, 185A, 185B; T.C. 3A12, 5A6, 3A13, 3A24	SA1686WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
P172D, R172E, R172F, R172G, R172H, R172J, R172K; T.C. 3A17	SA3487WE	Installation of tail flood light. Issued 10/18/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
R172K; T.C. 3A17	SA460NW	Installation of PeeKay model 2300 or B2300 seaplane floats. Amended 4/20/78.	EA	29998	PeeKay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
R172K Landplane only; T.C. 3A17	SA1437CE	Install rerated Continental IO-360-K engine. Issued 10/6/78.	CE	44802	Brad E. Isham 416 west Fourth Street Valley Center, KS 67147
R172K; T.C. 3A17	SA3227SW-D	Mitchell automatic flight system AK699 consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3228SW-D	Mitchell automatic flight system AK698 consisting of Century IIB autopilot with optional radio coupler. Issued 8/2/77.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3285SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
R172K; T.C. 3A17	SA3286SW-D	Mitchell automatic flight system AK732 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R172K; T.C. 3A17	SA4048WE	Installation of Silver Instruments fueltron IG or fueltron digital fuel flow and totalizer system. Issued 10/24/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
172, 175 Series; T.C. 3A12, 3A17	SA1-219	Gyro-stabilizer 69A122.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
172, 175 Series; T.C. 3A12, 3A17	SA3-576	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
172, 175 Series; T.C. 3A12, 3A17	SA4-1601	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175 Series; T.C. 3A12, 3A17	SA109SW	Automatic pilot AK106.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA393WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
172, 175 Series; T.C. 3A #A17	SA411SW	Automatic pitch trim AK 138.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA436EA	New engine, propeller and engine mount. Amended 9/21/67.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
172, 175 Series; T.C. 3A12, 3A17	SA610SW	Lycoming O-320 and O-360 Series engines with Hartzell HC-82XL-7636D-4; HC-C2YK-2R/7666 or HC-92Z-2B/8447-12A propeller.	SW	67650	R.F.B. Company Chandler Field Purcell, OK 73080
172, 175, 180, 182 Series; T.C. 3A12, 3A17, 5A6, 3A13	SA1-612	Autopilot T-101 and accessory kit T-201.	EA	77400	Tactair, Inc. Bridgeport Montgomery County, PA 17752
172, 175, 180, 182, 310 Series; T.C. 3A12, 3A17, 5A6, 3A13, 3A10	SA4-306	Roto-Nav bracket and Grimes D 7080 anti-collision light on vertical fin.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175, 182 Series; T.C. 3A12, 3A17, 3A13	SA4-893	Installation of wheel fenders on nose gear and main gear. Reissued 2/9/71.	NW	12565	Aurora Air Inc. d/b/a Madras Air Service Madras, OR 97741
172, 175, 180, 182 Series; T.C. 3A12 3A17, 5A6, 3A13	SA10WE	Arens Vernier type throttle control.	WE	82400	Van Nuys Skyways, Inc. 16700 Roscoe Boulevard Van Nuys, CA 91408
172, 175, 180 Series; T.C. 3A12, 3A17, 3A13	SA462WE	Jump door 62-508.	NW	72252	Skymotive, Inc. Route 1, Box 32 Snohomish, WA 98290
172, 175, 182 Series; T.C. 3A12, 3A13, 3A17	SA480CE	Nose and main gear wheel fairings. (Jetstreams) using standing unaltered Cessna landing gear and nose gear for model and year using 500 x 5 nose and 600 x 6 main gear tires.	GL	26750	Creative Designs 1338 Orkla Drive Minneapolis, MN 55427
172, 180; T.C. 3A12, 5A6, 3A13	SA2362WE	Installation of lure toxicant dispenser AEY 70, Model #1. Amended 9/27/73.	NW	03270	U S D A 3706 W. Nob Hill Boulevard Yakima, WA 98902
172, 180, 182 Series; T.C. 3A16, 5A6, 3A13	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Company airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
172, 180, 185; T.C. 3A17, 5A6, 3A24	SA271NW	Removal of paper air induction paper. Issued 3/16/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
172, 182 Series; T.C. 3A12, 3A13	SA1-193	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172, 182 Series; T.C. 3A12, 3A13	SA116EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/63.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
172, 182, 206, 210 Series; T.C. 3A12, 3A13, A4CE, 3A21	SA895WE	Kienzle 65 flight time recorder.	WE	18460	Burrows and Sons 1829 Bridgeport Avenue Claremont, CA 91711
175 Series; T.C. 3A17	SA3-285	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 1405 S. Oliver Wichita, KS 67207
175 Series; T.C. 3A17	SA3-611	Model 3000 main ski and Model 2000 nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
175 Series; T.C. 3A17	SA3-691	Installation of Doyn swept-tail assembly kit 1400. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
175 Series; T.C. 3A17	SA4-547	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
175 Series; T.C. 3A17	SA4-1406	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
175 Series; T.C. 3A17	SA3EA	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
175 Series; T.C. 3A17	SA5WE	Cowl flap.	WE	07473	Thompson International Aviation P.O. Box 68 Hereford, AZ 85615
175 Series; T.C. 3A17	SA11SO	Tank type end plates.	SO	26580	Corben Development Corporation P.O. Box 1603 Venice, FL 33595
175 Series; T.C. 3A17	SA12CE	Removal of right cabin door.	PC	96754	W.E. Avery 116 Kuulei Road Kailua, HI 96754
175 Series; T.C. 3A17	SA28WE	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
175 Series; T.C. 3A17	SA49CE	Conversion of aircraft for parachute jumping operations.	GL	41190	Haven Aviation Memorial Airpark Grand Haven, MI 49417
175 Series; T.C. 3A17	SA72CE	Sky-Lite B-100 beacon light.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
175 Series; T.C. 3A17	SA179NW	Installation of flap gap seals. Issued 1/25/75.	NW	78477	Thunderbird Aero Enterprise Paine Field Everett, WA 98204
175 Series; T.C. 3A17	SA221SO	Conversion of aircraft for parachute jumping and aerial photography.	SO	62490	Edward Richard Parker P.O. Box 578 Andrews Murphy AirPark Andrews, NC 28901
175; T.C. 3A17	SA586NW	Installation of a Franklin 6AS-350-A1 engine. Issued 7/28/78.	NW	70620	Seaplane Flying, Inc. P.O. Box 1264 Vancouver, WA 98661
175 Series; T.C. 3A17	SA948CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
175, 175A, 175B Landplane; T.C. 3A17	SA424CE	Install Lycoming O-360-A1A or O-360-A1D engine and Hartzell HC-C2YK-1A/7666-2, HC-922K-8D/8447-12A or McCauley 2D36C14/78KM-4 propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
175, 175A, B; T.C. 3A17	SA3-674	Lycoming O-360-A1D engine and McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1A/7666-2 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
175, 175A, B, C, P172D; T.C. 3A17	SA1-610	Wet-to-dry vacuum pump conversion kit 300-2. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
175, 175A, B, C; P172D; T.C. 3A17	SA122NW	Installation of Continental O-470 engine, McCauley 2A34C66N/90A-8 propeller, engine mount, cowling, baffles and associated parts. Issued 7/25/74.	NW	47646	Leslie L. Kammeyer Route 2, Box 38 Enumclaw, WA 98022
175, 175A, B, C; T.C. 3A17	SA161EA	Install new engine, propeller and engine mount. Amended 3/17/67.	EA	36750	Franklin Engine Company, Inc. Liverpool Road Syracuse, NY 13208
175, 175A, 175B, 175C; T.C. 3A17	SA212GL	Installation of windshield P/Ns W-2056, W/T-2056 or W/G-2056. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
175, 175A, 175B, 175C; T.C. 3A17	SA1492CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
175, 175A, B, C, P172D, T210F, G, H, J, K, L, M, 310, 310A, B, C, F thru L, N, P, Q, 310J-1, 310R, E310H, E310J, T310P, Q, 320D, E, F, 337, 337A, B, C, D, E, G, M337B, T337B, C, D, E, F, G, 340, 340A, 401, 401A, B, 402, 402A, B, 414, 421, 421A, B; T.C. 3A17, 3A10, 32A25, A6CE, A7CE	SA660WE	Installation of HRD-type fire-extinguishing and detector system. Amended 7/11/77.	WE	43180	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
175, 175A, B, C, P172D; T.C. 3A17	SA327GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
175, 175A, 175B, 175C, P172D (Landplane); T.C. 3A17	SA777CE	Install Lycoming O-360-A1A, 180 hp engine and Hartzell HC-C2YK-1A/7666A-2 propeller. Amended September 1976.	CE	12775	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 Wichita, KS 67204
175A, B, C, P172D (normal category); T.C. 3A17	SA2229WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
175, 175A, B, C; T.C. 3A17	SA2853SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
175, 175A, 175B, 175C (landplane only, normal category); T.C. 3A17	SA3795WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision, muffler in lieu of original Avcon muffler. Amended 1/11/80.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
175, 180, 182; T.C. 3A17, 5A6, 3A13	SA2716WE	Installation of carburetor heat box bearings. Issued 6/15/73.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
177; T.C. A13CE	SA466SO	Removal of right entrance door of cabin for aerial photography. Issued 5/20/71. Modified per STC SA545CE.	SO	25060	Columbus-Muscogee Aviation, Inc. P.O. Box 4608 Columbus, GA 31904
177; T.C. A13CE	SA545CE	Delete limitations pertinent to utility category operation. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
177; T.C. A13CE	SA602CE	Install shoulder harness.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67202
177; T.C. A13CE	SA906CE	Installation of Lycoming O-360-A1A 180 hp engine and Hartzell HC-C2YK-1B/7666A-2 or 7666-2 constant speed propeller. Issued 5/9/73.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 1006 W. 53 North Wichita, KS 67204
177; T.C. A13CE	SA1608WE	Installation of Brittain B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
177; T.C. A13CE	SA3861WE	Installation of an air/oil separator. Issued 3/2/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
177, 177A; T.C. A13CE	SA956CE	Installation of STOL kit (wing leading edge cuffs, drooped tips and vortex generators). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177, 177A, 177B; T.C. A13CE	SA1347CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
177, 177A, B; T.C. A13CE	SA3180SW-D	Automatic flight system AK420 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3181SW-D	Automatic flight system AK421 consisting of Century IIB autopilot with optional radio coupler. Issued 2/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3402WE	Installation of recognition lights on horizontal stabilizer. Issued 5/25/77.	SW	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
177, 177A, B, 177RG, 180C, D, E, F, G, H, I, J, K seaplane versions, 210A, B, C, D, E, 310F, G, H, I; T.C. A13CE A20CE, 5A6, 3A21, 3A10	SA71GL	Installation of: 177's P/N BA5710 filter assembly; 180's P/N BA8110 filter assembly; 210's P/N BA2110 filter assembly; 310's P/N BA2310 filter assembly. Issued 12/29/77.	WE	17062	Brackett Aircraft Specialties Co. 4910 East Falcon Drive Mesa, AZ 85205
177, 180, 182, 185, A185, 188, A188, 210-5 (205), 206, U206, TU206, P206, TP206, 207, T207, 210, T210; T.C. A13CE, 5A6, 3A13, 3A24, A9CE, 3A21, A4CE, A16CE	SA728NW	Installation of vented fuel cap. Issued 3/9/79.	NW	82675	Venting Engineering 5420 "A" Street Tacoma, WA 98408
177A; T.C. A13CE	SA601CE	Install Hartzell Model HC-C2YK-1B/7666A-2 constant speed propeller. Amended 2/28/69.	CE	56868	Galen D. Means 1818 North Edgemoor Drive Wichita, KS 67201
177B; T.C. A13CE	SA1060CE	Installation of wing leading edge cuffs and vortex generators on vertical stabilizer. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177B; T.C. A13CE	SA1607SW	Mitchell command/electric trim AK419. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SW1608SW	Mitchell AFS system AK420 consisting of Century I autopilot with optional omni tracker. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SA1609SW	Mitchell AFS system AK421 consisting of Century I autopilot with optional radio coupler. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RB; T.C. A20CE	SA3297SW-D	Mitchell automatic flight system AK759, consisting of Century IIB autopilot with optional radio coupler. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA1049CE	Installation of wing leading edge cuffs and vertical stabilizer vortex generators. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177RG; T.C. A20CE	SA1348CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
177RG; T.C. A20CE	SA1479SW	Mitchell automatic flight system AK378 consisting of Century I autopilot with optional omni tracker. Issued 8/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RG; T.C. A20CE	SA1510SW	Mitchell automatic flight system AK379 consisting of Century IIB autopilot with optional radio coupler. Issued 9/8/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
177RG; T.C. A20CE	SA3296SW-D	Mitchell automatic flight system AK758 consisting of Century I autopilot with optional omni tracking system. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3298SW-D	Mitchell automatic flight system AK760, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3307WE	Installation of recognition lights on horizontal stabilizer. Issued 4/15/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
177RG; T.C. A20CE	SA3860WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
177RG; T.C. A20CE	SA4024WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 9/10/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
180 Series; T.C. 5A6	SA1-7	Gyro-stabilizer 69A116 on aircraft with serial numbers 32151 and up.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-16	Federal F-300 autopilot.	GL	84750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA1-91	Modification to accommodate Robinson Aviation vertical mount NRIA.	EA	18756	Allen G. Butler 233 Front Street Phillipsburg, PA 16866
180 Series; T.C. 5A6	SA1-106	Gyro-stabilizer 69A107.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-212	Hole cut in lower skin and reinforced.	NE	44030	Inland Fisheries and Game Department Maine
180 Series; T.C. 5A6	SA1-221	Gyro-stabilizer 69A124.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA3-122	Model 3000 main ski and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-160	Conversion of electrical system, engine and aircraft to 24v and installation of additional battery box. (Aircraft with Continental O-470-J engine only).	GL	43342	Harvey M. Hughes Capital City Airport Lansing, MI 48924
180 Series; T.C. 5A6	SA3-161	C-3000 hydraulically-actuated main wheel skis with AWT-2500A or CT-3000 tail wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-292	Hydraulic landing gear actuating system with Edo 289-2700 amphibian gear.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA3-330	C-3000 manually-actuated main skis and AWT-2500A or CT-3000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-340	C-3000 main wheel skis on aircraft with crosswind gear.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-381	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
180 Series; T.C. 5A6	SA3-480	Change in airspeed and center of gravity limits with Edo 249-2870 floats and 2850 maximum weight.	AL	08483	Alaska Coastal Airlines 2 Marine Way Juneau, AK 99801
180 Series; T.C. 5A6	SA3-578	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
180 Series; T.C. 5A6	SA3-592	Structural reinforcement wires from center sectional spars to upper engine mount bolts rear of fire wall in windshield.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180 Series; T.C. 5A6	SA3-597	Engine driven hydraulic pump system for Federal C-3000 main ski.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA4-23	Conversion to tricycle gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-56	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-92	Folding type rear seat.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-117	Auxiliary fuel tank in baggage compartment.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-532	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA4-603	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA4-688	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
180 Series; T.C. 5A6	SA41WE	Two fabric rear seat assemblies supported by two steel tube beams.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA42EA	Floor viewing window.	EA	49730	Latrobe Aviation, Inc. P.O. Box 150 Latrobe, PA 15650
180 Series; T.C. 5A6	SA102AL	Shackle release at wing lift strut fittings right and left wings (seaplane only).	AL	03270	U.S. Department of Agriculture Forest Service P.O. Box 1631 Juneau, AK 99801
180 Series; T.C. 5A6	SA110SW	Removal of perforated cones from exhaust muffler.	SW	76850	Sun Oil Company P.O. Box 292 Patterson, LA 70392
180 Series; T.C. 5A6	SA168SW	Conversion of aircraft for parachute jumping operations.	SW	40684	John Hardy, Jr. 1105 St. John's Road El Paso, TX 79910
180 Series; T.C. 5A6	SA173RM	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401
180 Series; T.C. 5A6	SA214SW	Removal of perforated cones on cabin and carburetor heat-sides of muffler assembly with Continental O-470-K engine.	SW	52070	J. Ray McDermott & Company, Inc. Aviation Division P.O. Box 38 Harvey, LA 70058
180 Series; T.C. 5A6	SA221WE	Cleveland 30-21 wheel and brake assemblies 8:00 x 6 tires, Cessna heavy duty axles and 105 hose assemblies.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA289CE	Sky diving door.	GL	78474	Melvin J. Thompson 2406 Illinois Avenue New Holstein, WI 53061
180 Series; T.C. 5A6	SA312NW	Installation of Edo 628-2960 floats. Amended 6/6/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180 Series; T.C. 5A6	SA527WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
180 Series; T.C. 5A6	SA531AL	Installation of leading edge cuff stall fences, and flap and aileron gap seals. Issued 10/25/74.	AL	27250	Crosswinds, Inc. 6134 Lake Otis Parkway Anchorage, AK 99507
180 Series; T.C. 5A6	SA532CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180 Series; T.C. 5A6	SA702WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304, and optional Hi-Lo sensitivity adaptor.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
180 Series; T.C. 5A6	SA703WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold and NAV-1 navigation coupler and optional Hi-Lo sensitivity adaptor. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA939WE	Insertion into exhaust collector or exhaust stack of thermocoupled cylinder, a probe to read relative exhaust temperature.	WE	47746	Richard W. Kennedy 3352 Via Bartolo Street San Diego, CA 92101
180 Series; T.C. 5A6	SA983WE	Removal of right-hand door to permit parachute jumping and aerial photography operation (seaplane).	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
180 Series; T.C. 5A6	SA1373WE	Model 3000 floats.	EA	19800	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond, British Columbia, Canada
180 Series; T.C. 5A6	SA2630WE	Installation of SKI Model 10-202186 (Pulstar TM) combined position - anti-collision lighting system. Amended 5/11/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180F, 182, 182A thru 182D; T.C. 5A6, 3A13	SA1-37	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 46226
180, 180A, 180B; T.C. 5A6	SA1-363	Installation of Edo Model 439-2705 amphibious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, (seaplanes); T.C. 5A6	SA1-464	Installation of Edo models 439-2705 amphibious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, E, F, G, H, J, 182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P; T.C. 5A6, 3A16	SA1-611	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
180, 180A, B, C, D, E, (seaplanes); T.C. 5A6	SA1-622	Installation of Edo Model 249A-2870 seaplane floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180 thru 180F; T.C. 5A6	SA24GL	Installation of Model M-3000 wheel replacement skis. Issued 6/4/73.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapid, MN 56470
180, 180A thru 180F, H, J, 185, 185A, B, A185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA62GL	Install wheel and brake conversion kit P/N 199-60. Amended 10/25/74.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011
180, 180A thru 180F, H, J, 185, 185A, B, A185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA63GL	Install wheel and brake conversion kit P/N 199-62. Amended 10/25/74.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011
180, 180A thru 180J; T.C. 5A6	SA73GL	Installation of wheel replacement skis, Model M3000. Amended 7/16/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
180, 180A thru 180F, 182, 182A thru F; T.C. 5A6, 3A13	SA94EA	Installation of Monitair angle of attack system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
180, 180A thru 180F; T.C. 5A6	SA104CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180 thru 180H, J, 185 thru 185E, A185E, F; T.C. 3A24, 5A6	SA213AL	Installation of main tail gear skid, or main gear skis with two position wheel fittings. Amended 12/10/75.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180, 180A thru 180H, 185, 185E, A185E, 185F; T.C. 3A24	SA223AL	Installation of Model L3000 wheel replacement skis. Amended April 1974.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180 thru 180K; T.C. 5A6	SA286CE	Installation of Pee Kay Model 3500 or A3500 or B3500 floats, seaplane (TSO-C27-2) on Cessna Models 180 thru 180H airplanes. Amended and reissued 1/19/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
180, 180A thru 180H; T.C. 5A6	SA296AL	Installation of "quick-change" leading edge for horizontal stabilizer. Amended 12/15/71.	AL	05958	Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
180 Series 32015 and up, 180A thru 180K; T.C. 5A6	SA349CE	Installation of Aqua Model 180-85 floats. Amended and reissued 7/12/77.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
180 thru 180E; T.C. 5A6	SA367CE	Installation of floor level seat belt brackets to accommodate four occupants. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
180 thru 180H; 182 thru 182L; 185 thru 185E, A185E; 210 thru 210H, 210-5, -5A, T210F, G, H; 206, 206P, 206TP, 206TU, U206A, U206P, U206TP, U206TU, U206B, U206C; T.C. A4CE	SA453CE	Install Hoskins Twilighter Mk.III supplementary lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180H; T.C. 5A6	SA651AL	Fabricate canvas hammock rear seat and associated parts and install. Issued 8/23/78.	AL	61765	Nugget Aviation Route B, Box 188B Palmer, AK 99645
180, 180A thru 180H; T.C. 5A6	SA658AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180, 180A thru H; T.C. 5A6	SA745CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109
180A thru 180H; T.C. 5A6	SA787EA	Installation of Fleet-Line Floats 2900. Reissued 12/21/71.	EA	64630	Pioneer Airways P.O. Box 357 Atikokan, Ontario, Canada
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA816SW	Hartzell BHC-A2VF-3/V8833 reversible pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
180, S/N 18051824 and on; T.C. 5A6	SA865CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
180, 180A, B, C, D, E, F, G, H, 182, 182A, B, C, D, E, F, G, H, J, K, L, 185, 185A, B, C, D, E, A185E, 210, 210A, B, C, D, E, F, T210F, 206, P206, P206A, B, C, D, U206, U206A, B, C, D, TP206A, B, C, D, TU206A, B, C, D; T.C. 5A6, 3A13, 3A24, 3A21, A4CE	SA901SW	Increased wing leading edge radius. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 96133
180, 180A thru 180H, J, Landplanes, Seaplanes and Amphibians; T.C. 5A6	SA967CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
180, 180A thru 180H; T.C. 5A6	SA1004CE	Install STOL kit. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
180, 180A thru 180H, 180J; T.C. 5A6	SA1157WE	Turbocharged Continental O-470-A, J, K, L, or R engine. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180 thru 180H, 180J Landplane, Floatplane and Amphibian; T.C. 5A6	SA1435WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, except 180J, a flap actuated elevator trip system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA1493CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
180, 180A thru 180H, J; 180H Landplane and Floatplane; T.C. 5A6	SA1705WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 4/20/77.	WE	35780	William E. Flint 8402 North Magnolia, Suite G La Mesa, CA 92041
180, 180A thru H, A185E; T.C. 5A6, 3A24	SA1749WE	Installation of Canadian Aircraft Products, Ltd. Model 3000D floats.	EA	19800	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond, British Columbia, Canada
180 thru 180H; T.C. 5A6	SA2003WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A thru H; 205, 205A; T.C. 5A6, 3A21	SA2256WE	Installation of leading edge "Cap" on each wing. Amended 8/31/77.	WE	65700	Marshall E. Quackenbush P.O. Box 235 Inyokern, CA 93527
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA2854SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
180, 180A, B, C, D, E, F, G, H, J Landplanes Normal Category; T.C. 5A6	SA3313WE	Installation of flap gap closures. Issued 1/5/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA3419WE	Installation of recognition lights on horizontal stabilizer. Issued 6/10/77.	WE	30000	DeVore Aviation 16160 Stagg Street Van Nuys, CA 91406
180A; T.C. 5A6	SA388NW	Installation of McCauley 2A34C201/90DA-2 or -8 or McCauley 2A34C203/90DCA-2 or -8. Issued 12/23/76.	NW	61660	North Sound Aviation 1340 Peterson Road Burlington, WA 98233
180A thru 180H; T.C. 5A6	SA1943WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
180B; T.C. 3A24	SA155NW	Installation of baggage hatch with cover on EDO 249-3870 and 628-2960 floats. Issued 7/15/75.	NW	11780	Arts Aircraft Parts & Repair 4647 110th N.E. Kirkland, WA 98033
180B, 182 Normal Category; T.C. 3A13	SA3862WE	Shorten vertical leg of the control column 1-1/4 inches to provide clearance for additional avionics equipment in the instrument panel. Issued 2/6/79.	WE	16752	Big Bear Avionics P.O. Box 768 500 Meadow Lane Big Bear City, CA 92314
180F, G, H, J; T.C. 5A6	SA3146SW-D	Mitchell automatic flight system AK602 consisting of Century IIB autopilot with optional radio coupler. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180F, G, H, J; T.C. 5A6	SA3147SW-D	Mitchell automatic flight system AK603 consisting of Century I autopilot with optional omni tracker. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180G, 180H, 180J, 180K; T.C. 5A6	SA649NW	Installation of modification to increase gross weight of floatplane to 3190 lbs. when Edo 628-2960 floats are installed. Issued 8/8/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180G, 180H; T.C. 5A6	SA1349CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
180G, H, J (S/N 18051313 and Subs); T.C. 5A6	SA2979WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180H; T.C. 5A6	SA569EA	Installation of Tactair T-3 automatic pilot with A-651 horizon gyro and B-650 directional gyro. Issued 7/29/71.	GL	75200	George B. Stillwagon 546 Hathaway Road Dayton, OH 45419
180H, 180J; T.C. 5A6	SA262NW	Installation of 3-bladed McCauley D3A32C90/82NC-2 propeller, Cessna 1250809 spinner. Issued 2/27/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180J; T.C. 5A6	SA556NW	Installation of Continental O-470-Rengine. Issued 1/12/79.	NW	41520	Jim Hayton 1712 A Lakeview Boulevard Mount Vernon, WA 98273
180J; T.C. 5A6	SA3183WE	Installation of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
180J, 180K; T.C. 5A6	SA659AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20511	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180K; T.C. 5A6	SA3282SW-D	Mitchell automatic flight system AK751 consisting of Century I autopilot with optional omni tracker. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K; T.C. 5A6	SA3283SW-D	Mitchell automatic flight system AK752 consisting of Century IIB autopilot with optional radio couplers. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K, T207A, 210N, P210N, 337H, P337H, T337H, 340A, 404, 421C; T.C. 5A6, A6CE, A16CE, 3A21, 3A25, A25CE, A7CE	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 8/7/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
180, 182 Series; T.C. 5A6, 3A13	SA3-123	Heater-muffler assembly 430-10P.	EA	40350	Hanlon & Wilson, Inc. 321-325 Penwood Avenue Pittsburg, PA 15644
180, 182 Series; T.C. 5A6, 3A13	SA4-868	Shackle release at wing lift strut fittings, right and left wings (restricted category only).	RM	03270	U.S. Department of Agriculture Forest Service Missoula, MT 59801
180, 182 Series; T.C. 5A6, 3A13	SA4-1092	Seat belt and seat back to accommodate additional passenger on the rear seat.	RM	39464	Green River Aviation Company P.O. Box 606 Green River, UT 84525
180, 182 Series; T.C. 5A6, 3A13	SA4-1588	Cessna 210 wing tip assemblies.	WE	42130	H & H Flying Service, Inc. P.O. Box 742 Redding, CA 96001
180, 182 Series; T.C. 5A6, 3A13	SA5-19	Hammock seat in place of upholstered rear seat.	AL	08460	Alaska Aeronautical Ind. P.O. Box 4591 Spenard, AK 99503
180, 182 Series; T.C. 5A6, 3A13	SA108CE	Continental O-470 Series engines modified for Bendix RSA5 fuel injection system.	GL	15500	The Bendix Corporation 717 Bendix Drive South Bend, IN 46600
180, 182 Series; T.C. 5A6, 3A13	SA264SO	Cessna 210 wing tips 1223000-1 and -2.	SO	61180	Nashville Flying Service, Inc. Berry Field Nashville, TN 37202
180, 182 Series; T.C. 5A6, 3A13	SA561WE	12.7-gallon auxiliary fuel tank.	WE	05600	Aircraft Modification and Repair 20331 Hesperian Boulevard Hayward, CA 94541
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA1-519	Griswold lateralizer and heading lock.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA102SW	Automatic pilot AK109 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA1-576	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA334SW	Alternator.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180, 182, 210 Series; T.C. 5A6, 3A13, 3A21	SA96SW	Mixture control indicator kits SE-1.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216
180, 185; T.C. 5A6, 3A24	SA361NW	Installation of 8/50 x 6 main wheels with Cleveland brakes and Cleveland wheel assembly. Issued 10/15/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA701WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180, 185 Series; T.C. 5A6, 3A24	SA2273WE	Installation of Cessna Model 206 rear seats. Amended 10/18/74.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA2767WE	Installation of anti-collision lighting system. Issued 9/28/73.	WE	70500	Scientifico Scientific Components Company 350 Vista Baya Newport Beach, CA 92660
180, 185, 206; T.C. 5A6, 3A24, A4CE	SA754NW	Installation of Fernandez model 8001 and 8001A skis. Issued 4/27/79.	NW	46400	Jobmaster, Inc. 608 West Perimter Road Renton, WA 98055
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA65CE	Tow hitch assembly.	EA	73550	Soaring Society of America, Inc. Elmira, NY 14902
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA271CE	Tow hitch assembly.	CE	67207	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA1-8	Gyro-stabilizer 69A107.	GL	38175	Globe Industries, Inc. 1784 Stanley Avenue Dayton, OH 45404
182 Series; T.C. 3A13	SA1-36	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA3-18	Yaw axis stabilizer 8000B.	GL	20335	Cedar Engineering, Inc. 5806 W. 36th Street Minneapolis, MN 55401
182 Series; T.C. 3A13	SA3-44	Main ski AWB-2500A and nose wheel ski AWN-1200.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-109	Rudder trim system.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA3-110	Single axis automatic pilot A-2 or A-3.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA3-171	AWB2500A main and AWN1200 nose wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-286	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562
182 Series; T.C. 3A13	SA3-348	C-3000 main ski and AWN-1200 nose wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-452	Model 3000 main skis and Model 2000 nose skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-577	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
182 Series; T.C. 3A13	SA4-39	L-2B automatic pilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
182 Series; T.C. 3A13	SA4-132	Automatic rudder control B.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
182 Series; T.C. 3A13	SA4-199	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182 Series; T.C. 3A13	SA4-533	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA4-548	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA4-668	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
182 Series; T.C. 3A13	SA4-1359	Landing gear modified.	WE	70560	Scott Aero Service, Inc. Municipal Airport Long Beach, CA 90801
182 Series; T.C. 3A13	SA1SO	Wing tips.	SO	75880	Dale Stoughton 6408 S.W. 12 Street Hollywood, FL 33022
182 Series; T.C. 3A13	SA4EA	Single axis autopilot 510A.	EA	05950	Aircraft Radio Corporation P.O. Box 150 Boonton, NJ 07005
182 Series; T.C. 3A13	SA27SW	Automatic pilot AK088, AK088R or AK088E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA40CE	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Montorey, CA 93940
182 Series; T.C. 3A13	SA97WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA101SW	Automatic pilot AK110 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA129EA	HC-A2XF-G/8433-2 or BHC-A2XF-G/8433-2 propeller.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
182 Series; T.C. 3A13	SA183WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	90155	ZIV United Artists, Inc. 7324 Santa Monica Boulevard Hollywood, CA 90028
182 Series; T.C. 3A13	SA361WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA363WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA391CE	210 wing tips.	CE	42030	Carl H. Helms 701 Lou Holland Drive Kansas City, MO 64116
182 Series; T.C. 3A13	SA450SW	Automatic pitch trim system AK134.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA461NW	Installation of Continental IO-520-F engine and McCauley D2A34C58-LMN-90AT-8 propeller. Issued 6/13/77.	NW	85615	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
182 Series; T.C. 3A13	SA489SW	Automatic pilot AK154 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA502WE	Flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA516WE	Original Goodyear wheel and brake assembly replaced with Celveland wheel and brake assembly.	RM	39464	Green River Aviation Company, Inc. P.O. Box 606 Green River, UT 84525
182 Series; T.C. 3A13	SA525WE	B-4 flight control system, including pitch assist PC-1 altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182 Series; T.C. 3A13	SA535CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
182 Series; T.C. 3A13	SA585SO	Fuselage cutout and rerouting of rudder, elevator and trim cables. Amended 1/6/75.	SO	22787	Mr. Joel Clark P.O. Box 317 Bay Minette, AL 36507
182 Series; T.C. 3A13	SA60-SW	AK180 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA617SO	Installation of A or B of Continental O-470-M engines (per STC SE616SO).	SO	61644	North Perry Aviation, Inc. 8000 W. Pembroke Road Hollywood, FL 33023
182 Series; T.C. 3A13	SA624SW	AK197 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA658SW	AK199 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA707SW	AK243 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA709SW	AK229 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA795SW	Mitchell Century II autopilot AK241 with optional automatic aileron stabilizer and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA814WE	Modification to allow installation of camera through 15-inch diameter cutout in bottom of fuselage.	WE	08262	The Air Oasis Company 2361 Airlane San Diego, CA 92101
182; T.C. 3A13	SA1008SO	Installation of an adjustable trim tab on the left aileron. Issued 7/6/78.	SO	03110	Aero-Trim, Inc. 1150 100 Street Bay Harbor, FL 33154
182 Series; T.C. 3A13	SA1383WE	Installation of Brittain Pitch Assist Model PC-1 with Altitude Hold. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1384WE	Installation of Brittain Industries Model CSA-1 Stability Augmentation. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1474WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1671WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1673WE	Installation of Brittain Industries B-5 Flight Control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1706WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1871WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1872WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA2343WE	Installation of PHI controls Model 312 elapsed time indicator. Issued 4/27/71.	WE	64380	PHI Controls P.O. Box 6307 Torrance, CA 90504
182 Series; T.C. 3A13	SA2719WE	Installation of Symbolic Displays IFO-1A anti-collision lights. Amended 1/23/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182, 182A thru 182F; T.C. 3A13	SA103CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
182, 182A, B, C, D, E, F, G; T.C. 3A13	SA301GL	Installation of windshield P/Ns W-2071, W/T-2071, W/G-2071, W-2072, W/T-2072, W/G-2072, W-2073, W/T-2073, W/G-2073. Reissued 5/17/79.	GL	39450	Great LAkes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
182, 182A, B; T.C. 3A13	SA355NW	Convert a Cessna 182 aircraft to tailwheel configuration. Amended 1/31/78.	NW	47708	Keefer Aircraft Engineering 11457 Glendale Way S. Seattle, WA 98168
182, 182A thru 182H, 182J thru N, P, Q; T.C. 3A13	SA950CE	STOL kit installation (wing leading leading edge cuffs, drooped tips stall fences and aileron gap seals. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
182, 210, 310, 320 Series; T.C. 3A13 3A21, 3A10, 3A25	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
182 thru 182D; T.C. 3A13	SA874CE	Removal of right front seat, rear seat, and baggage shelf (if installed); installation of floor level seat belt brackets to accommodate four occupants in addition to the pilot. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
182, 182A, 182B, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M; T.C. 3A13	SA935SW	Installation of cabin air conditioning system. Amended 5/7/79.	RM	01950	Aero Engineering 8C Garden Center Broomfield, CO 80020
182, 182A thru 182H, J, K, L, M, N, P, Q (Thru S/N 18266590); T.C. 3A13	SA949CE	STOL kit installation. Amended 2/4/80.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
182, 182A thru H, J thru N, P; T.C. 3A13	SA1032WE	Installation of Rajay turbosupercharged Continental O-470-L or -R engine. Amended 10/1/75.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
182 thru 182P; T.C. 3A13	SA1382WE	Installation of flap actuated aileron droop system for all models; except 182P, recontoured wing leading edge, flap actuated elevator system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
182, 182A thru 182H, 182J thru 182N, 182P, Q, R182, TR182; T.C. 3A13	SA1494CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
182, A, B, C, D; T.C. 3A13	SA1579SW	Mitchell automatic flight system AK414, consisting of Century IIB autopilot with optional radio coupler. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. box 610 Municipal Airport Mineral Wells, TX 76067
182, A, B, C, D; T.C. 3A13	SA1580SW	Mitchell automatic flight system AK411, consisting of Century I autopilot with optional omni tracker. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182, 182A thru 182H, 182J thru 182Q; T.C. 3A13	SA1758WE	Installation of 12-gallon auxiliary fuel tank in each wing inboard of tip. Amended 3/15/79.	WE	35746	Flint Aero 8402-G Magnolia Avenue Gillespie Airport Plaza Santee, CA 92071
182, 182A thru 182H, 182J thru 182N; T.C. 3A13	SA1938WE	Installation of Madras Air Service "Super Tips." Amended 8/4/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
182 thru 182N; T.C. 3A13	SA2004WE	Installation of contoured wing leading edge and following options: stall fences, Robertson wing tips, positive aileron seals. Reissued 8/10/72.	NW	66175	Charyl C. Raisbeck 839 West Perimeter Road Renton Municipal Airport Renton, WA 98055
182, 182A thru 182H, 182J, 182K, 182L, 182M, 182N, 182P; T.C. 3A13	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182, 182A, B, C, D; T.C. 3A13	SA2888SW	Replacement of control wheel. Issued 12/18/78.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
182, 182A, B, C; T.C. 3A13	SA2890SW	Installation of Continental O-470-R engine. Issued 12/20/78.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3113WE	Installation of flap gap fairing. Amended 8/22/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, 182Q, R182, TR182; T.C. 3A13	SA3349WE	Installation of vertical tail flood lights on horizontal stabilizer. Amended 6/15/79.	WE	30000	DeVore Aviaiton Corporation 16160 Stagg Street Van Nuys, CA 91406
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3652WE	Installation of an air/oil separator. Amended 3/13/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
182A; T.C. 3A13	SA239GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 5/1/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
182A thru 182H, 182J thru 182N; T.C. 3A13	SA1006CE	Install landing gear speedpants. Amended 10/9/74.	CE	15230	Bede Aircraft, Inc. Newton Municipal Airport P.O. Box 706 Newton, KS 67114
182A thru P; T.C. 3A13	SA25NW	Installation of insect refrigeration release equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA26NW	Installation of twine dispenser equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA67NW	Installation of twine dispenser equipment. Issued 9/10/73.	NW	80914	U.S. Department of Agriculture 3706 W. Nob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA2371WE	Installation of lure-toxicant distributor. Amended March 1974.	NW	80914	U.S. Department of Agriculture Agricultural Research Service 3706 W. Nob Hill Boulevard Yakima, WA 98902
182A, B, C, D; T.C. 3A13	SA2761SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 4/24/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
182B; T.C. 3A13	SA198GL	Installation of Continental 0-470-R engine in lieu of Continental 0-470-L engine using original installation hardward & components. Issued 10/20/77.	GL	64285	Mark W. Peterson and Assoc. 2627 Springdale Road Duluth, MN 55811
182D thru P; T.C. 3A13	SA27NW	Installation of auxiliary crew seat in rear seat area. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182D; T.C. 3A13	SA1338SW	Cessna NAV-O-MATIC 400 autopilot. Issued 7/9/71.	SW	12630	Autopilots Central, Inc. 3260 North Sheridan Road Tulsa, OK 74131
182E, 182F, 210B, 210C, 210-5; T.C. 3A13, 2A21	SA36EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
182E, F, G, H; T.C. 3A13	SA513SW	Heavy duty brake kits. (Also eligible on Wren 460 and 460H aircraft). Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H; T.C. 3A13	SA626SW	Nose gear wheel and tire. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K, L, M; T.C. 3A13	SA692SW	Reverse pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K; T.C. 3A13	SA789SW	Automatic aileron stabilizer AK204.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182E, F, G, H, J, K, L, M; T.C. 3A13	SA923SW	Droop ailerons. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, K, L, M, 206, P206, U206, 210C, D, E, F, G (205), 210-5 (205A), 210-5A, 337, 337A, B, C, D, T337B, C, D; T.C. 3A13, 3A21, A4CE, A6CE	SA1021SW	Flap on switch on control wheel. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E thru N; T.C. 3A13	SA1211SW	Automatic flight system AK310 consisting of Century I and optional tracking system. Issued 11/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, F, G, H, J, K, L, M, N; T.C. 3A13	SA1594SW	Mitchell automatic flight system AK399 consisting of Century IIB autopilot with optional radio. Issued 1/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, 182F, 182G, 182H, 182J, 182K; T.C. 3A13	SA2546WE	Installation of Pathfinder Engineering Corp. Model P1-( ) autopilot. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA2908SW	Exhaust extension. Issued 2/2/79.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182E, F, G, H, J, K, L, M, N, P (S/N 18253599 and Subs); T.C. 3A13	SA2980WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2502 E. Wardlow Road Long Beach, CA 90807
182E thru 182H, 182H thru 182Q, NOTE; T.C. 3A13	SA3608WE	Installation of replacement flexible fuel cell in wings. Issued 3/15/78. NOTE: 182E S/N 18253599 thru 182H18256143 except aircraft modified by Cessna Service Kit SK182-41; 182H S/N 18256144 and subsequent thru 182Q S/Ns. Also 182E thru 182H aircraft which have been modified by Cessna SK182-41.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
182F; T.C. 3A13	SA198EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
182F; T.C. 3A13	SA933EA	Installation of wing struts modified to include Wings With Springs Model 300 hydraulic-pneumatic shock absorbers and associated airframe modifications. Amended 2/13/76.	EA	86500	Wings With Springs, Inc. Box 495, R.D. 3 Latrobe, PA 15650
182F, G; T.C. 3A13	SA403SW	Full span double slotted flaps, drooped wing leading edge, aileron actuated drag plates, Robertson U.L.S. nose control system, increased elevator aerodynamic balance, and relocated pilot head. Reissued March 1975.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
182H, J, K, L, M; T.C. 3A13	SA485SW	STOL operations modification. (Also eligible on Wren 460H aircraft.) Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182H, J, K, L, M, N; T.C. 3A13	SA1350CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
182H, 182J, 182K, 182L, 182M (Landplane only, normal category); T.C. 3A13	SA2662WE	Removal of nose control surface (which was installed as part of Wren 460 modification in accordance with STC SA485SW). Issued 3/9/73.	WE	17125	Breuner STOL Company 50 Melody Lane Orinda, CA 94563
182H, J, K, L, M, N, P206A, P206B, P206C, P206D, P206E (landplane only); T.C. 3A13, A4CE	SA2799WE	Installation of camera pod attached to bottom of fuselage by straps. Issued 1/8/74.	WE	15190	Bechtel Corporation 50 Beale Street San Francisco, CA 94119

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182K, L, M, N, P; 210G, H, J, K, L, T210G, H, J, K, L; T.C. 3A13, 3A21	SA6GL	Installation of Grimes strobe anti-collision lights. Issued 1/5/73.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
182K, L, M, N, P, Q; T.C. 3A13	SA2748SW	Streamlined nose gear kit. Issued 4/14/78.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182M Normal Category; T.C. 3A13	SA2723WE	Installation of external cargo pack (ski carrier). Issued 7/11/73.	WE	87114	Wirly Sales 7610 Owens Street Tujunga, CA 91042
182N, 182P; T.C. 3A13	SA2177WE	Installation of Brittain Ind. B-7, NAV-2B, B2C or BSS flight control system. Reissued 9/19/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182N (S/N 18260446 and up), 182P, 182Q; T.C. 3A13	SA1406CE	Install 25-gallon auxiliary fuel tank in fuselage baggage compartment. Amended 5/12/78.	CE	45250	Javelin Aircraft Company, Inc. 1978 Easy Street Wichita, KS 67230
182P; T.C. 3A13	SA1554SW	Mitchell automatic flight system AK396 consisting of Century I with optional omni tracker. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1555SW	Mitchell automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1556SW	Mitchell command/electric trim system. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA3063WE	Installation of Pathfinder auto-pilot system and/or electric pitch trim system. Amended 12/3/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182P; T.C. 3A13	SA3072SW-D	Mitchell automatic flight system AK540 consisting of Century III autopilot with optional radio and slope couplers. Issued 9/10/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA3190SW-D	Mitchell command electric trim AK410 Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, 182Q; T.C. 3A13	SA1296CE	Installation of King KFC-200 2-axis, flight control system with KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KX-292 mode controller. Amended 9/22/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
182P, 182Q; T.C. 3A13	SA1403CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
182P, 182Q; T.C. 3A13	SA3188SW-D	Install automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, 182Q; T.C. 3A13	SA3189SW-D	Automatic flight system AK396 consisting of Century 1 autopilot with optional omni tracker system. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, Q; T.C. 3A13	SA4079SW	Stall fences, aileron seals. Issued 1/30/80.	SW	18600	Bush Conversions P.O. Box 61 Guthrie, OK 73044
182Q; T.C. 3A13	SA255GL	Install a Pathfinder P2A autopilot. Issued 7/19/78.	GL	04543	Air Central Enterprises 44050 Russia Road Elyria, OH 44035
182Q; T.C. 3A13	SA3279SW-D	Mitchell automatic flight system AK744 consisting of Century I autopilot with optional omni tracker. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182Q; T.C. 3A13	SA3280SW-D	Mitchell automatic flight system AK745 consisting of Century IIB autopilot with optional radio coupler. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3281SW-D	Mitchell automatic flight system AK 746 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3763WE	Installation of Pathfinder autopilot systems. Issued 10/27/78.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
R182; T.C. 3A13	SA144RM	Installation of Pathfinder P2A single-axis autopilot. Issued 6/29/78.	RM	02454	Aeronics Jefferson County Airport Hangar B4A Broomfield, CO 80020
R182; T.C. 3A13	SA1433CE	Installation of KFC 200 flight control system with or without flight director. Amended 10/27/79.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
R182; T.C. 3A13	SA3273SW-D	Mitchell automatic flight system AK741 consisting of Century IIB autopilot with optional radio coupler. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3274SW-D	Mitchell automatic flight system AK742 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3275SW-D	Mitchell automatic flight system AK743 consisting of Century IV autopilot with optional remote annunciator. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A12	SA3316SW-D	Installation of Mitchell command electric trim system AK778. Issued 11/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3834WE	Installation of Pathfinder autopilot systems. Issued 2/13/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
185 Series; T.C. 3A24	SA4-1617	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
185 Series; T.C. 3A24	SA33SO	Conversion of aircraft for parachute jumping operations.	SO	34288	Falling Angels, Inc. 339 E. New York Avenue De Land, FL 32720
185 Series; T.C. 3A24	SA84CE	25-gallon auxiliary fuel system in cargo pack. (Aircraft equipped with 62-gallon usable main fuel tanks only.)	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
185 Series; T.C. 3A24	SA108SW	Edo 289-2700 and 439-2705 amphibious floats.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
185 Series; T.C. 3A24	SA111CE	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562
185 Series; T.C. 3A24	SA147SW	Edo 429-2705 or 289-2700 amphibious floats.	SW	27270	Cruse Aviation, Inc. 8501 Telephone Road Houston, TX 77002
185 Series; T.C. 3A24	SA172WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401
185 Series; T.C. 3A24	SA202WE	Cessna 210 wing tip assemblies 1223000-1, -2, and wing tip mounted navigation lights.	NW	49270	Lake Aero Service 9306 Veterans Drive, SW Tacoma, WA 98402
185 Series; T.C. 3A24	SA215SW	L-2 autopilot.	SW	03120	Aerotron Radio Company P.O. Box 8396 Tulsa, OK 74101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
185 Series; T.C. 3A24	SA213WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
185 Series; T.C. 3A24	SA261NW	Installation of automatic flagman. Issued 2/5/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362
185 Series; T.C. 3A24	SA343EA	Holes in floor of aircraft for use of viewfinder and camera.	NE	50780	Herbert P. Lindblad Mousam Road Springfield, ME 04487
185 Series; T.C. 3A24	SA417WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
185 Series; T.C. 3A24	SA1081WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
185 Series; T.C. 3A24	SA1568WE	Installation of emergency fuel system.	WE	59730	Missionary Aviation Fellowship P.O. Box 2828 Fullerton, CA 92632
185 Landplane; T.C. 3A24	SA943WE	Installation of Continental TSIO-470-B engine.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
185, 185A, B, C, D, 210, 210A, B, C, 210-5, 210-5A, 210E, F, G, H, J, K, L; T.C. 3A21, 3A24	SA1-629	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
185, A, B, C, D, E, A185E; T.C. 3A24	SA3-717	Ski installation: main gear Model 4000; tail gear Model 1500, CT-3600, CT-3200, CT-3400. Amended 2/19/76.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
185, 185A, 185B; T.C. 3A24	SA123CE	High intensity wing tip lights Model B and tail light Model C with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
185, 185A, B, C, D, E, A185E; T.C. 3A24 (Floatplane configuration)	SA169CE	Install Wipline Model 3700 or 3900 twin floats. Amended 7/22/76.	GL	86750	Wipline, Inc. South End Doane Train Inver Grove Heights, MN 55075
185 - 185D;	SA324AL	Installation of Continental IO-520-D engine. Revised 6/16/69.	AL	08472	Alaska Air Guides, Inc. P.O. Box 4165 Anchorage, AK 99503
185 thru 185E, A185E, A185F; T.C. 3A24	SA328CE	Install Model 180-85 aqua floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA445CE	Installation of Pee Kay 3500, A3500, B3500, C3500, 2950 or 3000 seaplane floats (TSO-C27-2). Amended and reissued 1/19/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
185, 185A, 185B, 185C, 185D, 185E, A185E; T.C. 3A24	SA480AL	Installation of EDO-AIRE Mitchell Century I autopilot and omni tracker. Issued 5/25/72.	AL	03124	Aerotronics of Alaska, Inc. Box 4-1582 Anchorage, AK 99509
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA525NW	Installation of Continental IO-520-D engine and McCauley D2A34C58/90AT-4 propeller. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA526NW	Installation of Edo Model 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA587NW	Installation of Hartzell HC-C3YF-1RF/F9587C-15 propeller on Continental IO-520-D engine. Issued 5/5/78.	AL	08492	Alaska Propeller Specialists, Inc. 5251 Lakeshore Drive Anchorage, AK 99503
185, 185A, 185B, 185C, 185D, 185E; T.C. 3A24	SA631AL	Install leading edge cuff. Issued 4/28/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA746CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
185, S/N 185-1201 and on; T.C. 3A24	SA866CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA954SW	Installation of droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
185, 185A thru 185E, A185E and F Landplanes, Seaplanes and Amphibians; T.C. 3A24	SA968CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
185, 185A, C, D, E, A185E; T.C. 3A24	SA1351CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
185, 185A thru 185E, A185E, A185F Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA1441WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge (except A185F) stall fence, flap actuated elevator trim system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA1495CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
185, 185A thru 185E; T.C. 3A24	SA2108WE	Installation of Madras Air Service wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
185, 185A thru 185E, A185E Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA2189WE	Installation of recontoured wing leading edge, stall fences, wing tips, and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, 185B, 185C, and 185D, 185E, A185E, A185F Landplane; T.C. 3A24	SA2529WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 9/20/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite G Santee, CA 92071
185 Series, 185A, B, C, D; T.C. 3A24	SA2802SW	Install leading edge cuffs, stall fences, aileron seals, and wing tips. Issued 6/19/78.	SW	18600	Bob Williams d/b/a Bush Conversions Box 61 Guthrie, OK 73044
185, A, B, C, D, E, A185E; T.C. 3A24	SA3084SW-D	Automatic flight system AK554, consisting of Century I autopilot with optional omni tracker. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
185, A, B, C, D, E, A185E; T.C. 3A24	SA3085SW-D	Automatic flight system AK555, consisting of Century IIB autopilot with optional radio coupler. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
185, 185A, B, C, D, E, A185E, F; T.C. 3A24	SA3383WE	Installation of recognition lights on horizontal stabilizer. Issued 4/19/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
185A, A185F (Seaplane Configuration only); T.C. 3A24	SA7GL	Installation of Model 3730 amphibious floats, Model 3700, 3800 or 3900 seaplane floats. Amended 7/20/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
185A, 185E, A185E, A185F, 206, P206, P206A, U206A, TP206A, TU206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E, U206F, TU206F, U206G; T.C. 3A24, A4CE	SA522NW	Installation of float hatch kits on Edo 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185B; T.C. 3A24	SA199EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
185E, A185, A185F; T.C. 3A24	SA240NW	Installation of McCauley D3A32C90/ propeller, Cessna spinner, governor, and associated systems on Continental IO-520-D engine. Amended 1/16/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A185E; T.C. 3A24	SA507NW	Installation of Edo floats and Cessna cargo pack, Issued 8/31/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
A185E; T.C. 3A24	SA587NW	Installation of Hartzell HC-C3YF-1RF/F9587C-15 propeller on Continental IO-520-D engine. Issued 5/5/78.	NW	08492	Alaska Propeller Specialists, Inc. 5251 Lake Shore Drive Anchorage, AK 99503
A185E; T.C. 3A24	SA592AL	Install leading edge cuff, stall fences, and flap and aileron gap seals. Issued 7/19/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
A185E; T.C. 3A24	SA930SW	Droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
A185E; T.C. 3A24	SA1148SW	Aileron drooping device. Reissued 2/13/75.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
A185E; T.C. 3A24	SA1990WE	Installation of Tritan Amphibious float model TA 3500. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
A185E (Floatplane Amphibian configuration only); T.C. 3A24	SA805CE	Installation of Wipline Model 3730 amphibious twin floats. Issued and amended 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
A185E, A185F; T.C. 3A24	SA501NW	Installation of McCauley D3A32C90/82NC-2 on Lycoming IO-520-D engine. Issued 8/29/77.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
A185E, A185F; T.C. 3A24	SA832EA	Installation of Edo Model 582-3430 seaplane floats. Amended 1/15/80.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185E, A185F; T.C. 3A24	SA877EA	Installation of Pee Kay Model 3500A (TSO C-27-2) amphibious floats. Amended 6/7/75.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
A185E, A185F (Floatplane and Amphibious Configurations; T.C. 3A24	SA985EA	Installation of McCauley Propeller Model D3A32C90/82NC-2. Amended 2/25/75.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
A185E, A185F; T.C. 3A24	SA2875WE	Installation of modified brake system. Issued 4/30/74.	WE	59730	Mission Aviation Fellowship P.O. Box 142 Ramona, CA 92065
A185F; T.C. 3A24	SA17NE	Installation of EDO Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Reissued and amended 9/5/79.	NE	32625	EDO-AIRE Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185F; T.C. 3A24	SA51NW	Installation of Cessna cargo pack. Issued 7/31/73.	NW	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA164NW	Installation of EDO-628-2960 seaplane floats with Cessna cargo pack kit No. AK-185-23D, cargo pack fairing, rudder non-linear centering spring and ventral fin. Issued 2/28/75.	WE	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA420NW	Installation of cargo pac and McCauley 3-bladed propeller. Issued 3/17/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA558NW	Installation of Edo Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Amended 1/15/80.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185F; T.C. 3A24	SA596NW	Install Cessna A185E wing panels. Issued 4/27/78.	NW	08215	Airmetal Northwest, Inc. P.O. Box 387 Arlington, WA 98223
A185F; T.C. 3A24	SA634AL	Install leading edge cuff. Issued 5/31/78.	AK	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A185F; T.C. 3A24	SA780NW	Installation of Edo 628-2960 floats on a A185F equipped with Cessna cargo pod (P/N 0700062-43) must include Cessna ventral fin (P/N 0712764-2) and linear rudder centering system. Issued 6/1/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
A185F; T.C. 3A24	SA3251SW-D	Mitchell automatic flight system AK703 consisting of Century IV autopilot or AK703FD consisting of Century IV flight director with optional remote annuciator. Issued 11/18/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
188, A188; T.C. A9CE	SA709CE	Install wing fence.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
188, A188; T.C. A9CE	SA1126SW	Alternate air filter.	SW	43500	Hutchinson Aircraft Box 1070 Borger, TX 79006
188, A188; T.C. A9CE	SA1352CE	Chrome-plated brake disc installation. Issued 3/2/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
188, A188; T.C. A9CE	SA1919WE	Installation of Madras Air Service wing tips. AMended 8/16/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
188, 188A, A188, A188A; T.C. A9CE	SA142NW	Normal and restricted category installation of recontoured wing leading edge and stall fences. Options: wing strut fillet or wing tips. Issued 12/11/74.	NW	68500	Robertson Aircraft Corporation 839 Perimeter Road Renton, WA 98055
188, 188A, A188, A188A, T.C. A9CE	SA1007CE	Installation of full spar leading edge cuffs and drooped wing tips. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
188, 188A, A188, A188A; T.C. A9CE	SA1355SW	Wing leading edge cuff to increase leading edge radius. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
188, 188A, A188, A188A; T.C. A9CE	SA1373SW	Fairing on wing strut intersection. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
188, 188A, A188, A188A; T.C. A9CE	SA1745WE	Installation of Automatic Flagman (Marker Dispensing Unit). Amended 8/10/73.	NW	03500	Air-Ag, Inc. Route 4, City County Airport Walla Walla, WA 99362
188, 188A, A188, A188A; T.C. A9CE	SA2340WE	Installation of recontoured wing leading edge, drooped ailerons, stall fences, new wing strut fillet; optional flap actuated elevator trim system, Robertson wing tips 10-105, Madras Air Services super tips. Issued 4/13/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
188, 188A, 188B, A188, A188A, A188B; T.C. A9CE	SA1179CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508, Renner Field Goodland, KS 67735
A188; T.C. A9CE	SA543SO	Extruded aluminum leading edge cuff. Issued 8/2/73.	SO	79820	Tunico P.O. Box 356 Tunica, MS 38676
A188, A188A, A188B; T.C. A9CE	SA99RM	Installation of freon type air conditioning system. Issued 7/12/77.	RM	32300	Dale Edlund Billings Aircraft, Logan Field Billings, MT 59102
A188, A188A, A188B; T.C. A9CE	SA900SO	Installation of cabin air conditioning. Issued 5/31/76.	SO	69228	Mr. Dwight Kerry Rudder Route 1, P.O. Box 11A Canton, MS 39046
A188B; T.C. A9CE	SA40RM	Installation of Freon air-conditioning system. Amended 3/22/76.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
A188B; T.C. A9CE	SA672NW	Installation of Hartzell HC-C3YF-1RF/F9587C-17S propeller on Continental IO-520-D engine. Issued 9/29/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
190 Series; T.C. 790	SA3-227	ARC L-11 loop and housing, ARC ADF receiver R-30A and power unit, and ARC control head.	CE	44340	Interstate Airmotive, Inc. Lambert Field St. Louis, MO 63155
190 Series; T.C. 790	SA4-1075	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
190 Series; T.C. 790	SA4-1275	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
190 Series; T.C. 790	SA42WE	Eclipse Aviation generator 790-1B.	WE	34292	Robert F. Fallon 1201 Deborah Drive Tustin, CA 92680
190 Series; T.C. 790	SA220WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	69245	Rusty's Flying Service 1041 W. Alondra Compton, CA 90220
190 Series; T.C. 790	SA354SW	Cargo conversion.	SW	33994	Executive Airlines, Inc. 206 E. Terminal Drive International Airport San Antonio, TX 78205
190, 195; T.C. 790	SA573CE	Installation of block swivel action of crosswing gear.	CE	47250	Ray M. Jourdan 11001 E. 59th Street Raytown, MO 64133
190, 195; T.C. 790	SA1492WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
190, 195, 195B; T.C. A-790	SA54GL	Install wheel and brake conversion kit P/N 199-61. Issued 6/10/74.	GL	23260	Cleveland Wheel and Brakes Div. of VanSickle Industries 1160 Avon Center Road Avon, OH 44011
190, 195, 195B; T.C. A-790	SA120NW	Installation of Hartzell HC-B3P20-4/P10160-12E propeller on Jacobs-Page R-755S engine. Amended 4/20/77.	NW	87008	William Wiprud 6443 Southwest Beaverton Hillsdale Airport Portland, OR 97221
190, 195, 195A, B; T.C. A-790	SA1284CE	Replacement axles. Issued 10/13/76.	CE	19020	Butterfly Aviation, Inc. P.O. Box 736 Renner Field Goodland, KS 67735
190, 195, 195A, B; T.C. A-790	SA2388WE	Removal of left-hand exit. Issued 7/26/71.	WE	67014	Everett A. Redding 18250 Grand Avenue Elsinore, CA 92330
195; T.C. A-790	SA199GL	Installation of oil filter between engine oil gallery and propeller governor/nose case tappet rocker arm supply. Issued 11/4/77.	GL	60093	Richard C. Moen 536 South 1st Street Dundee, IL 60118
195; T.C. 790	SA1268SW	Jacobs-Page R-755-S engine. Reissued 5/24/77.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
205, 205A; T.C. 3A21	SA3836WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Voulevard Los Angeles, CA 90064
206 Series; T.C. A4CE	SA65NW	Installation of fiberglass wing tips. Issued 9/20/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
206 Series; T.C. A4CE	SA635SW	McCauley DA3A32C90/82NC-2 propeller.	SW	84395	L.L. Walker Company P.O. Box 5158 Houston, TX 77012
206 Series; T.C. A4CE	SA669SW	AK218 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206 Series; T.C. A4CE	SA727SW	AK231 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206 Series; T.C. A4CE	SA1255WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	73760	Sonora Aviation, Inc. P.O. Box 1027 Carson City, NV 89701

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206 Series; T.C. A4CE	SA1893WE	Installation of Brittain Flight Control Systems Model B-5, NAV-2B or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
206 Series; T.C. A4CE	SA3837WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
206, P206, U206, P206A, U206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA332CE	Installation of Wipline Models 3700 and 3900 twin floats on Cessna Floatplane configuration. (Floatplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
*206, *P206, *P206A, *U206, *U206A, U206B, C, D, E, F, G (S/N U20603522 thru U20604649, U20604659 and up) (1979 models), TP206A, TU206A, B, C, D, E, F (S/N U20601701 thru U20602199); T.C. A4CE *These models are approved with a gross weight of 3500 lbs., all others approved with 3600 lbs. gross weight.	SA439NW	Installation of Edo-696M-3500 and/or 696-3500 amphibious floats. Reissued and amended 10/22/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
206, P206, U206, U206F, Floatplane configuration; T.C. A4CE	SA474CE	Install Aqua Model 3526 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
206, P206, P206A, TP206A, U206, U206A, thru G, TU206A thru TU206G; T.C. A4CE	SA512CE	Installation of Pee Kay Model 3500 or A3500 or B3500 seaplane floats. Amended and reissued 1/29/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newton Road Plainview, NY 11803
206, P206, U206, P206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206A, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA666CE	Install Wipline Model 3730 twin floats (amphibious). (Seaplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
206, P206, P206A, TP206A, U206, U206A thru G, TU206A thru G; T.C. A4CE	SA851EA	Installation of Pee Kay Model 3500A amphibious floats (TSO C-27). Amended and reissued 1/29/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newton Road Plainview, NY 11803
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA893CE	Camera hole cut-out in lower fuselage structure. Reissued 2/17/76.	GL	59452	Mr. Wayne B. Millard 4144 South Highway 101 Minneapolis, MN 55345
206, P206, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA908CE	Install STOL kit. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F landplanes only; T.C. A4CE	SA990CE	Install STOL kit (wing leading edge cuffs, drooped tips, and stall fences). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, TU206A, B, C, D, E, F; T.C. A4CE	SA1069CE	Enlargement of factory installed camera hole and installation of a view finder hole. Issued November 1974.	CE	36000	FloAir, Inc. Hangar #17 Mid-Continent Airport Wichita, KS 67209
206, U206A, B, D, E, TU206A, B, D, E, P206A, B, C, D, E; T.C. A4CE	SA1353CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F; T.C. A4CE	SA1513WE	Installation of flap actuated aileron droop system, recontoured wing leading edge (except TU206F and U206F), and flap actuated elevator trim system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, 210-5, 210-5A; T.C. A4CE, 3A21	SA1870WE	Installation of Brittain Model NAV-2B Flight Control. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
206, U206, P206 Landplane and Floatplane, P206B, TP206B, P206C, TP206C, P206D, TP206D, P206E, TP206E Landplane and Skiplane, P206A Landplane, U206A, U206B, U206C, U206D, TU206A, TU206B, TU206C, TU206D, TU206E Skiplane; T.C. A4CE	SA2326WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, P206A, B, C, D, E, F, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G; T.C. A4CE	SA2479WE	Installation of larger fuel containing wing tips. Amended 7/25/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite G Santee, CA 92071
206, P206, 206-A, -B, -C, -D, -E, TP206A, B, C, D, E, U206, A, B. C, D, E, F; T.C. A4CE	SA2855SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G: T.C. A4CE	SA3348WE	Recognition light installation on horizontal stabilizer. Issued 3/7/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, [illegible] T.C. A4CE	SA3462WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 8/19/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
206 (S/N 206-0001 thru 206-0137 except 206-0094, S/N 206-0094, 206-0138 thru 206-0275), U206 (S/N U206-04074), P206 (S/N P206-0001 thru P206-00647); T.C. A4CE	SA3825WE	Installation of replacement flexible fuel cell in wings. Issued 8/2/79.	WE	08357	Air-Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
P206A/B/C/D/E, U206A/B/C/D/E/F/G: T.C. A4CE	SA3686WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
P206C, P206D, U206C, U206D, U206E; T.C. A4CE	SA1431SW	Mitchell automatic flight system AK368 consisting of Century III autopilot with optional automatic electric pitch trim, radio, and glide slope couplers. Issued 2/25/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206; T.C. A4CE	SA652NW	Installation of McCauley D3A32C90/82NC-2 propeller on Continental IO-520-A engine. Issued 8/15/78.	NW	64790	Robert Plummer Bob's Aircraft Maintenance Challis, ID 83226
U206, TU206; T.C. A4CE	SA1037CE	Installation of 26 gallon auxiliary fuel tank in baggage compartment. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA2782SW	Installation of Continental TSIO-520-M. Issued 5/30/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F, TU206G; T.C. A4CE	SA3856WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1430SW	Mitchell automatic flight system AK350, consisting of Century I autopilot with omni tracker. Issued 2/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1449SW	Mitchell automatic flight system AK369, consisting of Century II autopilot with optional radio coupler. Issued 3/22/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Minerals Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1572SW	Mitchell automatic flight system AK405 consisting of Century IIB autopilot with optional radio coupler. Issued 12/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1846SW	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/electronic pitch trim, radio coupler, and glide slope coupler. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1887SW	Automatic flight system AK470, consisting of Century IIB autopilot with optional radio coupler. Issued 6/17/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA3097SW-D	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/electronic pitch trim, radio coupler and glide slope coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, -D, -E, -F, TU206C, -D, -E, -F, P206C, -D, -E, TP206C, -D, -E; T.C. A4CE	SA2164WE	Installation of Edo Model FD-3500A (TSO C-27-2) amphibious floats. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
U206F, TU206F, U206G, TU206G, T.C. A4CE	SA3GL	Installation of Bendix FCS-810 autopilot and flight director. Amended 2/13/78.	GL	66080	Russell Hammer Radio Ranch, Inc. Radio Ranch Airport Polo, IL 61064
U206F, G, TU206F, G (Seaplane configuration only); T.C. A4CE	SA18GL	Installation of Wipline Model 3730 floats. Amended 6/12/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
U206F, TU206F; T.C. A4CE	SA1845SW	Mitchell automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3177SW-D	Install Mitchell automatic flight system AK470 consisting of Century IIB with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3178SW-D	Install automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, U206G, TU206F, TU206G; T.C. A4CE	SA3262SW-D	Mitchell automatic flight system AK715 consisting of Century III autopilot with optional radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3263SW-D	Mitchell automatic flight system AK714 consisting of Century IIB autopilot with optional radio couplers. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3264SW-D	Mitchell automatic flight system AK713 consisting of Century I autopilot with optional omni tracker. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3265SW-D	Mitchell automatic flight system AK717/FD consisting of Century IV/flight director autopilot with optional remote annunciator. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
U206F, TU206F (Sea-plane configuration only); T.C. A4CE	SA3296WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/23/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
U206F, U206G, TU206F, TU206G;	SA3454WE	Installation of an emergency fuel system. Amended 2/7/78.	WE	59730	Mission Aviation Fellowship P.O. Box 2828 Fullerton, CA 92633
U206G, TU206G; T.C. A4CE	SA1480CE	Installation of King KFC200 automatic flight control system, two axis, with or without flight director. Issued 3/27/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
U206G, TU206G; T.C. A4CE	SA3739WE	Installation of Silver Instruments fueltron digital fuel flow and totalizer system. Issued 9/21/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
TU206C; T.C. A4CE	SA566CE	Install one or two blister windows.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
TU206C, TU206D; T.C. A4CE	SA935EA	Installation of window in bottom of fuselage at F. Station 35.5. Amended 4/18/73.	EA	52060	Long Island Airways Box 240 Ronkonkoma, NY 11779
TU206G; T.C. A4CE	SA831NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705
TU206G; T.C. A4CE	SA4004SW	Camera port. Issued 6/20/79.	SW	28490	Daily Tubbs Aero, Inc. 2115 Danbury Drive San Antonio, TX 78217
206, 207, 210 Series; T.C. A4CE, A16CE, 3A21	SA2809SW	Install Symbolic Displays CFS-1000 electronic fuel flow metering system. Issued 7/2/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206, 210 Series; T.C. 3A21, A4CE	SA149SW	Automatic pilot AK120, AK120E, AK1075-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206, 210 Series; T.C. 3A21, A4CE	SA245WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
206, 210 Series; T.C. 3A21, A4CE	SA526SW	Automatic trim AK171.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206, 210 Series; T.C. 3A21, A4CE	SA674WE	Flight control system B-4 including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
207; T.C. A16CE	SA1402SW	Mitchell automatic flight system AK357 consisting of Century II autopilot with optional radio coupler. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1403SW	Mitchell automatic flight model AK356 consisting of Century I autopilot with optional omni tracker. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1404SW	Mitchell automatic flight system Model AK361 consisting of command/electric trim system. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA2856SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
207, T207; T.C. A16CE	SA1354CE	Chrome-plated brake disc installation. Issued 8/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
207, T207; T.C. A16CE	SA2121WE	Installation of recontoured wing leading edge, drooped ailerons, in flaps down mode, stall fences, and elevator trim spring. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
207, T207; T.C. A16CE	SA2327WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
207, T207; T.C. A16CE	SA2676WE	Installation of larger fuel containing wing tips. Amended 5/23/77.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041
207, T207; T.C. A16CE	SA3427WE	Installation of tail flood light on horizontal stabilizer. Issued 6/22/77.	WE	30000	DeVore Aviation 16160 Stagg Street Van Nuys, CA 91406
210 Series; T.C. 3A21	SA1-625	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA3-503	L-2B autopilot with or without altitude controller and/or approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
210 Series; T.C. 3A21	SA4-1086	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
210 Series; T.C. 3A21	SA4-1372	Brake blocks AB-6526 and AB-6527.	EA	46748	Johns-Manville Corporation 22 E. 40 Street New York, NY 10001
210 Series; T.C. 3A21	SA4-1416	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA20SW	Automatic pilot AK086, AK086E or AK086R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA89SW	Automatic pilot AK112.	SW	60000	Mitchell Industries, INc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA89NW	Installation of King VOR Model KX 170B or KX 175B, King DME Model KN65 and King Area Navigation computer Model KN74. Issued 2/11/74.	NW	70040	Salem Aviation 2680 Aerial Way, S.E. Salem, OR 97302
210 Series; T.C. 3A21	SA103SW	Automatic pilot AK111.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA110EA	Removal of right front door and other modifications.	EA	72108	Sky Diving, Inc. Cameron Airpark Medford, NJ 08055
210 Series; T.C. 3A21	SA118EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA199WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	82270	V. Vincent Vandever, Inc. 6447 W. Reade Avenue Glendale, AZ 85301
210 Series; T.C. 3A21	SA330SW	Automatic pilot AK126 and lateral guidance/radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA420SW	Automatic pitch trim AK133.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA464EA	Propeller, spinner, and governor.	GL	73830	Southeastern Ohio Air Service, Inc. P.O. Box 863 Municipal Airport Zanesville, OH 43701

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210 Series; T.C. 3A21	SA469WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold (optional). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA531CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
210 Series; T.C. 3A21	SA618WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA627WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA637SW	AK209 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA675SW	AK212 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA1100SW	Increase wing leading edge radius. Reissued 2/13/75.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
210 Series; T.C. 3A21	SA1305WE	PCA-1 pitch assist with altitude hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1343WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1471WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1478WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1606WE	Installation of Brittain Industries B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1609WE	Installation of Brittain Industries Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1618WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1631WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1672WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1684WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1882WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1887WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA2720WE	Installation of Symbolic Displays IFO-1A anti-collision lights. Amended 3/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
210, 210A; T.C. 3A21	SA1527WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 8/7/73.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210, 210A; T.C. 3A21	SA3377WE	Installation of flap gap fairing. Issued 3/24/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
210, 210A; T.C. 3A21	SA3732WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 9/14/78.	WE	84542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
210, 210A, 210B, 210C, 210K, 210L, T210K, T210L; T.C. 3A21	SA52GL	Installation of wheel and brake conversion kit P/N 199-60. Issued 6/6/74.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Industries, Inc. 1660 Avon Center Road Avon, OH 44011
210, 210F, T210F (205), 210-5 (205A), 210-5A; T.C. 3A21	SA64NW	Installation of fiberglass wing tips. Issued 9/13/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
210, 210A, 210B, 210C, 210-5; T.C. 3A21	SA93CE	High intensity wing tip lights Model B, and tail light Model C, with or without fuselage lights. Reissued 10/17/74.	GL	42626	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
210, 210A, B, C, D, E, F, 210-5(205), 210-5A (205A), T-210F; T.C. 3A21	SA940CE	STOL Kit installation. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
210, 210A, 210B, 210C, 210D, 210E, 210F; T.C. 3A21	SA1048CE	Installation of STOL kit (wing leading edge cuffs, stall fences, aileron gap seals and droop wing tips). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
210, -A, -B, -C, 210-5 (205), 210-5A (205A); T.C. 3A21	SA1098WE	Installation of Rajay turbosupercharged Continental IO-470-E or IO-470-S engine. Amended 8/11/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
210, 210A thru 210H, 210J, K, L, T210F thru T210H, T210J, K, L; T.C. 3A21	SA1525WE	Installation of droop ailerons in flaps down mode, recontoured wing leading edge, and elevator trim spring (except on T210K, L, and 210K and L). Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
210 thru 210K, T210F thru T210K, 210-5 (205), 210-5A (205A); T.C. 3A21	SA2242WE	Installation of recontoured wing leading edge stall fences, and for 206, 205A, 210A, 210B and 210C positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
210, 210A, B, C, D, E, F, G, H, J, K, L, M, T210F, G, H, J, K, L, M, (205) 210-5, (205A), 210-5A, P210N; T.C. 3A21	SA3312WE	Installation of recognition lights on horizontal stabilizer. Amended 3/20/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
210, 210A, B, C, D, E, F, G, H, J, K, L, M, N; T.C. 3A21	SA3453WE	Installation of a cargo container. Reissued 2/2/79.	WE	02465	Aero Pod, Inc. 17202 Sandra Lee Lyn Huntington Beach, CA 92649
210A, B, C, D, E, F; T.C. 3A21	SA3649WE	Installation of replacement flexible fuel cell in the wings of the 210 Cessna aircraft. Issued 5/16/78.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
210B, C; T.C. 3A21	SA3144SW-D	Mitchell automatic flight system AK604 consisting of Century I autopilot with optional omni tracker. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B, C; T.C. 3A21	SA3145SW-D	Mitchell automatic flight system AK605 consisting of Century IIB autopilot with optional radio coupler. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B; 210-5(205), 210-5A(205A); T.C. 3221	SA3522WE	Installation of Knisley muffler in lieu of original Cessna mufflers. Issued 11/11/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
210C; T.C. 3A21	SA197EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210C, D, E, F, G, H, J, K, T210F, G, H, J, K, 210-5(205), 210-5A(205A); T.C. 3A21	SA1312CE	Chrome-plated brake disc installation. Amended 9/13/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
210D, E; T.C. 3A21	SA376NW	Installation of McCauley D3A32C88-XLM/S-82NC-2 propeller and Continental IO-520-A engine. Issued 11/15/76.	NW	34827	Felts Field Aviation 3100 North Division Spokane, WA 99207
210D, E, F, T210F; T.C. 3A21	SA906SW	Mitchell automatic aileron stabilizer AK211 and omni tracker AK246.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Cincinnati, OH 45226
210D, E, F, T210F; T.C. 3A21	SA1376SW	Mitchell automatic flight system AK349 consisting of Century I with optional omni tracker. Issued 10/4/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, E, F, T210F; T.C. 3A21	SA3141SW-D	Mitchell automatic flight system AK620 consisting of Century IIB autopilot with optional radio coupler. Issued 6/3/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, 210E, 210F, T210F; T.C. 3A21	SA2677WE	Installation of larger fuel containing wing tips. Amended 4/6/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210D, E, F, G, H, J, K, L, M, T210F, G, H, J, L, M, K, P210N; T.C. 3A21	SA3751WE	Installation of Fueltron IG digital fuel flow and totalizer system. Amended 11/22/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
210D, 210E, P206; T.C. 3A21, A4CE	SA693WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
210D, E, F, G, H, J, K; T.C. 3A21	SA790CE	Installation of engine condition monitor kit ECM-6. Issued August 1971.	GL	31750	ECM Corporation 412 North Weinbach Avenue Evansville, IN 47711
210E; T.C. 3A21	SA2784SW	Leading edge cuffs, stall fences, aileron seals, and wing tips. Issued 6/1/78.	SW	18600	Bob Williams d/b/a Bush Conversions Box 61 Guthrie, OK 73044
210G; T.C. 3A21	SA829SW	Automatic flight system AK254 Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G; T.C. 3A21	SA858SW	AK258 consisting of Century III autopilot with optional aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, T210G, 210H, T210H, 210J, T210J, 210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA966CE	Installation of leading edge cuffs, droop tips, aileron gap seals, and stall fences. Amended 5/25/78.	CE	42560	Horton STOL-Craft Wellington Airport Wellington, KS 67152
210G, H, J, K, L, M, T210G, T210H, T210J, T210K, T210L, T210M, 210N, P210N, T210N; T.C. 3A21	SA2862WE	Installation of larger fuel containing wing tips. Amended 7/23/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210G, H, J, T210G, H, J; T.C. 3A21	SA3168SW-D	Automatic flight system AK641 consisting of Century IV autopilot or AK641-FD consisting of Century IV flight director with optional remote annuciator. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J; T.C. 3A21	SA3169SW-D	Automatic flight system AK642 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J, K; T.C. 3A21	SA3170SW-D	Automatic flight system AK643 consisting of Century IIB autopilot with optional radio coupler. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210G, H, J, K, T210G, H, J; T.C. 3A21	SA3171SW-D	Automatic flight system AK644 consisting of Century I autopilot with optional omni tracker. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
T210F; T.C. 3A21	SA1042SW	Hartzell-Wren beta control system. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
T210F; T.C. 3A21	SA2277WE	Installation of Brittain Industries B2C flight control systems. Amended 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G; T.C. 3A21	SA1420WE	Installation of Brittain Industries B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G, H, J; T.C. 3A21	SA2689SW	Install TSIO-520-M engine. Issued 12/9/77.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
210H; T.C. 3A21	SA725CE	Installation of electric gyros and standby power source.	CE	43374	Humphrey, Incorporated 434 North Oliver Wichita, KS 67208
210J; T.C. 3A21	SA2249WE	Installation of Brittain Industries B-7, NAV-2B, B2C and BSS flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210J, T210J, 210K, T210K; T.C. 3A21	SA1326SW	Mitchell automatic flight system AK334, consisting of Century II autopilot with optional radio coupler, and automatic aileron stabilizer. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210J, T210J, 210K, T210K; T.C. 3A21	SA1327SW	Mitchell automatic flight system AK332, consisting of Century I autopilot with optional omni tracker. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA71RM	Installation of JB Systems air conditioning system. Amended 6/8/79.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA210NW	Collins AP-107 low profile 3 axis automatic flight control system. Amended 12/2/77.	NW	24250	Collins Radio Group 855 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA211NW	Installation of Collins AP-107 low profile two axis automatic flight control system. Amended 12/2/77.	CE	24250	Collins Radio Group 855 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA212NW	Installation of AP-107 low profile yaw damper system. Amended 12/2/77.	CE	24250	Collins Radio Group 355 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K; T.C. 3A21	SA1325SW	Mitchell automatic flight system AK331, consisting of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K; T.C. 3A21	SA2199WE	Installation of Brittain Industries B-7, NAV-2B, B2C, and BSS flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210K, T210K, 210L, T210L; T.C. 3A21	SA509SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 3/3/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210K, T210K, 210L, T210L, 210M, T210M, T210N; T.C. 3A21	SA1202CE	Installation of King Model KFC-200 two axis flight control system with or without flight director. Amended 11/28/78.	CE	48250	King Radio Corporation 400 North Robers Road Olathe, KS 66061
210L, T210L; T.C. 3A21	SA1506SW	Mitchell aytomatic flight system AK388, consisting of Century III autopilot with optional automatic pitch trim, radio and glide slope coupler. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210L, T210L; T.C. 3A21	SA1507SW	Mitchell automatic flight system AK386 consisting of Century I with optional omni tracker. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA1526SW	Mitchell automatic flight system AK387, consisting of Century IIB autopilot with optional radio coupler. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3001SW-D	Automatic flight system AK468, Century IV autopilot or AK468FD Century IV flight director with electronic command/automatic pitch trim and optional remote annuciator panel. Issued 4/26/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3112SW-D	Automatic flight system AK566 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/5/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3247WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder Autopilot Systems and/or Pitch Trim Systems. Issued 8/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
210L, T210L, 210M, T210M; T.C. 3A21	SA1006SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 6/30/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210L, 210M; T.C. 3A21	SA3685WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
210L, 210M, T210L, T210M; T.C. 3A21	SA3182SW-D	Mitchell automatic flight system AK387 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, 210M, T210L, T210M; T.C. 3A21	SA3183SW-D	Mitchell automatic flight system AK386 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210 S/N 21061040 and up, P210N, 210M, T210M, T210N; T.C. 3A21	SA3835WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow Amended 6/12/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714
210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA1005SO	Installation of Bendix FCS-870 automatic flight control system, or installation of Bendix FCS-870 automatic flight control system with reduced flap motor speed. Amended 4/4/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210N, P210N, T210N; T.C. 3A21	SA756NW	Installation of leading edge stall strips, change aileron droop. Issued 4/20/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N; T.C. 3A21	SA760NW	Installation of RCA digital weather radar system. Issued 5/3/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N, P210N; T.C. 3A21	SA1420CE	Install wing leading edge cuffs (with or without de-icer boots) and wing stall fences. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
P210N; T.C. 3A21	SA1487CE	Installation of King KFC200 AFCS, two axis, with or without flight director. Issued 5/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
P210N; T.C. 3A21	SA3289SW-D	Mitchell automatic flight system AK737 consisting of Century IIB autopilot with optional radio and glide slope couplers. Issued 6/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
P210N; T.C. 3A21	SA3290SW-D	Mitchell automatic flight system AK738 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P210N; T.C. 3A21	SA3291SW-D	Mitchell automatic flight system AK739 consisting of Century IV autopilot or AK739FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 210 Mineral Wells, TX 76067
210-5 (205), 210-5A (205A); T.C. 3A21	SA993CE	Install STOL kit (leading edge cuff, droop tips, stall fence and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
T210L, T210M; T.C. 3A21	SA3857WE	Installation of an air/oil separator. Issued 3/13/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
305 Series; T.C. 5A5	SA504SW	Rerouting of oil to oil cooler and addition of extra cooler.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA295SW	Three-place configuration.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA353SW	Conversion of aircraft for parachute jumping operations.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA505SW	McCauley 1A200PM propeller.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA568SW	Gross weight increased to 2,300 2,300 pounds.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA1201SW	Lycoming O-540-A4B5 engine. Reissued 3/19/75.	SO	34800	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
305A; T.C. 5A5	SA1620SW	Cessna 180 fuel cells. Issued 4/19/73.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA1702SW	20-gallon fuel cells. Issued 7/19/73.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A, 305D; T.C. 5A5, 3A14	SA3-370	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
305A, B, C, D, E; T.C. 5A5, 3A14	SA2857SW	Leading edge cuffs, stall fences, aileron seals, *wing tips*. Issued 9/22/78.	SW	10600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
310 Series; T.C. 3A10	SA1-21	Federal autopilot F-400.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
310 Series; T.C. 3A10	SA1-293	Lightweight reservoir pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-506	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-579	Taxi lamp in right outboard cowling.	GL	22400	Cincinnati Aircraft, Inc. Lunken Airport Cincinnati, OH 45202
310 Series; T.C. 3A10	SA3-55	Radio equipment.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
310 Series; T.C. 3A10	SA3-440	L-3 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310 Series; T.C. 3A10	SA3-475	Full feathering, constant speed propellers, hubs 2AF36C26, blades 90MF-10.	GL	52720	McCauley Industrial Corporation 1807 Howell Avenue Dayton, OH 45401
310 Series; T.C. 3A10	SA3-636	M-4 flight control system with altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA3-643	Transa-Strobe beacon B-7228.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
310 Series; T.C. 3A10	SA3-662	Hydraulic accumulator in each engine nacelle and new propeller governor C210355 or A210438.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
310 Series; T.C. 3A10	SA3-665	Cabin air temperature control system on Southwind (Stewart-Warner) 8240-A heater.	GL	82500	Vap-Air Division Vapor Corporation 6444 W. Howard Street Chicago, IL 60607
310 Series; T.C. 3A10	SA4-3	32-gallon auxiliary fuel tank in baggage compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-127	56-gallon auxiliary fuel tank in hat rack compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-239	Thompson TF2800 engine-driven fuel pump.	WE	33460	Engineering Modification Company 6850 Vineland Avenue North Hollywood, CA 91603
310 Series; T.C. 3A10	SA4-702	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
310 Series; T.C. 3A10	SA4-1217	Extension of augmenter tubes to trailing edge of wing.	WE	10116	AMC Augmenters 2648 N. Campbell Tucson, AZ 85700
310 Series; T.C. 3A10	SA4-1400	SP-3 autopilot.	WE	74570	Sperry Phoenix Company P.O. Box 2529 Phoenix, AZ 85000
310 Series; T.C. 3A10	SA4-1598	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA6SO	Window on each side of cabin between fuselage stations 89.25 and 109.375. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA37SO	Fuselage access holes in bottom skin of fuselage.	SO	76830	Sunny South Aircraft Service, Inc. 300 S.W. 41 Street County International Airport Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA44CE	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA58SO	Dual camera ports. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA59SO	One-piece windshield	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA60SO	Third window on each side of fuselage.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA61SO	Underwing exhaust system and nacelle fairings.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA77SO	Engines modified per STC SE73SO.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Fort Lauderdale, FL 33300
310 Series; T.C. 3A10	SA97SO	A, B, or C of turbocharged Continental IO-470-D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310 Series; T.C. 3A10	SA99SO	Auxiliary fuel tanks under nacelle fairing (4-tank and 6-tank systems).	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA109EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA119CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA202SW	Cessna 0895000-8, -9 aft cowling doors.	SW	08168	Airline Aviation, Inc. P.O. Box 1024 Roswell, NM 88201
310 Series; T.C. 3A10	SA248SO	Increase takeoff gross weight to 4,830 pounds. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA254SO	Swept vertical tail. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA303CE	Installation of Bendix Model M-4B/C autopilot flight control system. Amended 2/20/69.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA325CE	GUARD system (Gear Up Automatic Response Device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612
310 Series; T.C. 3A10	SA347SW	Cowling and exhaust system.	SW	60089	Modern Aero Sales, Inc. 4837 S. Hampton Road Dallas, TX 75221
310 Series; T.C. 3A10	SA348WE	Installation of air induction system. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2606 E. Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA385WE	Turbocharged Lycoming IO-540-A1A5 engines. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA390WE	Pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA444NW	Replace original split flaps with Fowler flaps. Issued 5/12/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
310 Series; T.C. 3A10	SA448EA	Electrothermal propeller deicing system.	GL	38500	The B.F. Goodrich Company Municipal Airport Akron, OH 44318
310 Series; T.C. 3A10	SA457SW	AK145 automatic pitch trim.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA477SO	Modify control wheel. Issued 10/27/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602 IAB Miami, FL 33148
310 Series; T.C. 3A10	SA517WE	Flight control system B-4, including pitch assist PC-1, altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA621SW	AK198 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA678SW	Lear or Motorola L-2C autopilot.	SW	03120	Aerotron Radio Company International Airport Tulsa, OK 74101
310 Series; T.C. 3A10	SA737SW	AK201 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310; T.C. 3A10	SA1359CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310 Series; T.C. 3A10	SA1490WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1799WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1896WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA2406SW	Addition of hydro seal fluid additive to nose and main gear shock strut. Issued 2/11/77.	SW	49722	Granville Lasseter 802 East Grant Street Morton, TX 79346
310, 310A thru 310J, 320, 320A, B, C, D; T.C. 3A10, 3A25	SA1-620	Kit No. 2014X for 12-inch RCA AVQ-45, AVQ-47, AVQ-50, AVQ-55 and 12-inch Collins WP-103 radar antenna. Amended 4/15/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310B, 310C; T.C. 3A10	SA1-185	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
310 thru 310Q, T310P, Q, E310H, J, T310R, 320 thru 320F, 340, 340A, 337G, 336, 337, 337B, C, D, E, F, G, T337B, C, D, E, F, G, 401, 401A, B, 402, 402A, B, 404, 411, 411A, 414, 414A, 421, 421A, B, C; T.C. 3A10, 3A25, A7CE, A6CE, A2CE	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 9/25/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
310, 310A thru 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P,, T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA111GL	Install Cleveland conversion kit P/N 199-64. Issued 6/30/76.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011
310-A thru 310-K, 320A thru 320-D, 320-1; T.C. 3A10, 3A25	SA302CE	Supplemental high intensity position light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
310, 310A thru H, E310H, 310J, J-1, E310J, 310K, L, N, 320, 320-1, 320-A, B, C, D, E, F, 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA362CE	Install Hoskins Twilighter Mk III and Mk IIIB light system. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
310, 310A thru J, 320, 320A thru D; T.C. 3A10	SA396EA	Installation of Radome Kit No. 2310X-R. Reissued 4/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310C; T.C. 3A10	SA814SW	Underwing exhaust.	SW	08168	Airlane Aviation, Inc. P.O. Box 1024 Roswell, NM 88204
310, 310A thru 310F; T.C. 3A10	SA574WE	Installation of leading gear position mirror on left wing tip tank. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
310, 310A, B, C, D, E, F, G, H, I, J, K, L, N, P, Q, E310H, 310J-1, E310J, T310P, T310Q; T.C. 3A10	SA3235WE	Installation of recognition light assembly on horizontal stabilizer. Issued 7/13/76.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
310, 310B; T.C. 3A10	SA26SO	Aerodynamic clean-up, cabin soundproofing, new interior and cooling duct changes. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310, 310B, 310C, 310P, 310Q; T.C. 3A10	SA74SO	Installation of seats and camera port. Reissued 9/10/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D; T.C. 3A10	SA76SO	Installation of two (2) R.H. and two (2) L.H. single seats and enlarged emergency exit. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B thru 310G; T.C. 3A10	SA212SO	Installation of Lycoming IO-540-A1A5 engines and Hartzell HCA3XK-2B/7636D propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D, 310F; T.C. 3A10	SA455SO	Installation of extended window modification. Issued 3/18/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
310, 310F thru N; 320, 320-1, 320A thru F; 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA240WE	Consolidation of STCs SA355CE and SA362CE into one STC having MASTER ELIGIBILITY LIST - amended to include improved power supply assembly and subchassis timer assembly for Twilighter MK III high intensity supplementary lighting system. Issued 8/16/71.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
310B, C, D, E, F, G, H, I, J, K, L, N, P, Q, T210P, T210Q: T.C. 3A10	SA3243WE	Installation of pilot's and co-pilot's side vent windows. Issued 8/13/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
310C thru 310G; T.C. 3A10	SA2383WE	Installation of turbo-charged Continental IO-470-D engine. Issued 8/18/71.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
310C, D, F, G, H, I, J, K, L, N, P, Q, T310P, T310Q, T310R; T.C. 3A10	SA3671WE	Installation of Fueltron IIIG or IIIP digital fuel flow indicating system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
310D thru 310L, 310N, 310P, 320, 320A thru 320F; T.C. 3A10, 3A25	SA2534WE	Installation of Cessna 310P-type fiberglass tail stinger and yaw reduction adapter. Amended 5/30/73.	WE	01750	Aerocessories Company 1779 Fitzgerald Road Simi, CA 93065
310D, G, H, I, J, K, L; T.C. 3A10	SA3078SW-D	Auto flight system AK556, Century IV autopilot or AK556FD Century IV flight director. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J; T.C. 3A10	SA3079SW-D	Mitchell yaw damper system YK 558. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J: T.C. 3A10	SA3082SW-D	Automatic flight system AK557, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, E, F, G, H, I, J, K, L, N, P, Q, R, T310P, T310Q, T310R, 320-1, 320C, D, E, F; T.C. 3A10, 3A25	SA3105SW-D	Mitchell automatic flight system AK584 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310F, 310G: T.C. 3A10	SA752EA	Installation of ground to air recovery equipment. Restricted Category. Amended 8/6/69.	EA	09500	All American Eng. Company Box 1247 Lancaster Pike & Center Road Wilmington, DE 19899
310G, H, I, J, K, L, N, P; T.C. 3A10	SA412SO	Installation of Continental IO-520-E engines. The engines are limited to 260 hp. Amended 12/16/71.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
310G, H thru Q, J-1: E310H, J; T310P, Q: 320A, B thru F; 402, A, B, 401, A, B; 411, A; 414; 421, A, B; T.C. 3A10, 3A25, A7CE	SA568EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-0107-1. Amended 11/7/75.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310G thru 310Q, 310R, 320A thru 320F, 340A, 401, 401A, B, 402, 402A, B, 411A, 414, 421, 421A, B; T.C. 3A10, 3A25, A7CE	SA574NW	Installation of forward facing recognition lights and clear plastic wing tip tank nose cone. Amended 4/13/78.	NW	28850	Robert M. DeBorde 20645 S.W. Clarion Aloha, OR 97005
310G, H, I, J, K, L, N, P, 310Q thru 310Q-0601; T.C. 3A10	SA3789WE	Installation of 36-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
310H; T.C. 3A10	SA294SO	Installation of turbocharged Continental IO-470-D engines. Reissued 12/5/74.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90801
310H thru 310L, 320 thru 320E, 401, 402; T.C. 3A10, 3A25, A7CE	SA1847WE	Installation of Brittain Up-Command Signal Adapter Kit. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310I, 310J; T.C. 3A10	SA181SO	Installation of turbosupercharged Continental IO-470-U engines. Amended 8/9/68.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
310I, J, K, L, N, P, Q, R, T310P, T310Q, T310R, 320A, B, C, D, E, F, 340, 401, 401A, B, 402, 402A, B, 414, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA107GL	Conversion of oil lubricated deice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
310I, J, K, L, N, P, R, Q, T310P, T310Q, T310R; T.C. 3A10	SA701CE	Install Airborne wing and tail pneumatic deice kit 703B. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
310I, L, N, P, Q, T310P, 320C, 320E; T.C. 3A10, 3A25	SA1883SW	Install Hartzell synchrophase system. Issued 6/11/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708
310I, J, K, L, M, P, Q; 320B, C, D, E, F; T.C. 3A10, 3A25	SA1904SW	Additional auxiliary transfer tanks. Issued 8/13/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708
310J, E310J, T310P, T310Q, 310K, 310L, 310N; 320D, 320E, 320F, 340; 401, 401A, 401B, 402, 402A, 402B, 414, 411, 411A, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA14GL	Installation of detachable lead strap propeller deicers. Issued 3/20/73.	GL	44318	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310J, K, L, N, P, Q, R, T310P, T310Q, T310R; T.C. 3A10	SA471SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 6/3/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
310K, 310L, 310N, 310P, 310Q, 320E, 320F; T.C. 3A10, 3A25	SA42GL	Install Norton Company radome kit No. 3060X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310K, 310L, 310N, 320E, 320F, 310P, 310Q; T.C. 3A10, 3A25	SA490EA	Installation of Chamberlain Radome Kit No. 3060K-B for Bendix radar RDR-100 or RDR-110 systems. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310K, L, N, P, Q, 320E, 320F; T.C. 3A10, 3A25	SA150GL	Install Norton Company radome Kit No. 4131X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310K, L, N, P, Q, 320F; T.C. 3A10, 3A25	SA537EA	Installation of Radome Kit No. 3060X-R. Amended 8/25/72.	GL	61750	Norton Company Plastics & SYnthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310L, N, P, Q; T.C. 3A10	SA2082WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Hartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68145	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310N; T.C. 3A10	SA2784WE	Installation of Ontrac II VLF 1000 very low frequency navigation system. Amended 12/3/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3266WE	Installation of ONTRAC III VLF/Omega navigation system. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway AVenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3287WE	Installation of Ontrac III VLF/Omega navigation system as a means of navigation (but not sole means) for EN ROUTE navigation. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3789WE	Installation of 36 gallon auxiliary fuel tanks in each wing. Issued 11/14/78.	WE	35320	Bob Fields 5673 Stanford Street Ventura, CA 93003
310N; T.C. 3A10	SA3924WE	Installation of ONTRAC IIIA VLF/Omega navigation system. Issued 5/25/79.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N, P, Q, T310Q; T.C. 3A10	SA3018SW-D	Automatic flight system AK442 consisting of Century III autopilot with optional command and auto. elec. elevator pitch trim, radio, and glide slope coupler. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, Q, T310P, Q; T.C. 3A10	SA3019SW-D	Automatic flight system AK443 and AK443FD consisting of Century IV autopilot and Century IV flight director autopilot with trim system and annuciator panel. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, T310P, T310Q; T.C. 3A10	SA3020SW-D	Automatic flight system YK444 consisting of yaw damper. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P, 310Q; T.C. 3A10	SA592NW	Installation of Fowler flaps. Issued 4/14/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
310P, 310Q, T310P, T310Q; T.C. 3A10	SA137NW	Installation of Collins AP-107 low profile automatic flight control system (FCS), including yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA138NW	Installation of Collins low profile yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA875EA	Installation of Brittain Industries, Inc. flight control system Model B-7 or NAV-2B or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310P, T310P, 310Q; T.C. 3A10	SA1142SW	Edo-Aire Mitchell automatic flight system, AK300 consisting of Century III with pitch trim, radio, and glide slope coupler. Issued 5/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P, Q, N, T310P, T310Q; T.C. 3A10	SA1190SW	Mitchell automatic flight FD/AP282-300 consisting of flight director/automatic pilot and automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P/T310P, 310Q/T310Q, 310R/T310R; T.C. 3A10	SA1273CE	Installation of King KFC 200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 4/14/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
310P, 310Q, 310R; T.C. 3A10	SA2203WE	Installation of air conditioning system. Amended 6/3/76.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
310P, T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA3602WE	Installation of vapor cycle airconditioning system. Issued 3/6/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
T-310; T.C. 3A10	SA192RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
T310, 320, 320A, B, C, D, E, F, 340, 401, A, 411, A, 414, 421, A, B; T.C. 3A10, 3A25	SA3RM	Modification of engine exhaust stacks by replacement of expansion joint with slip fit joint. Reissued.	RM	41750	Heliarc Welding Service, Inc. 3916 Niagara Street, Box 7301 Denver, CO 80207
T310 Series, 320A, B, C, D, E, F, 401, 401A, 402, 402A, B, 404, 414, 421C; T.C. 3A10, 3A25, A7CE	SA103RM	Installation of exhaust turbo connector, P/N 30477-3 Issued 8/17/77.	RM	41750	Heliare Welding Service, Inc. 3965 Newport Denver, CO 80207
T310 Series, 320, 320A, B, C, D, E, F, 340, 340A; T.C. 3A10, 3A25	SA110RM	Modify Cessna exhaust system by replacement of the inter-cylinder expansion joints with a slip fit joint.	RM	41750	Heliare Welding Service, Inc. 3965 Newport Denver, CO 80207
T310L;	SA530NW	Installation of McCauley D3A34C402/90DFA-10 propeller on Continental TSIO-520-H engine. Issued 10/4/77.	NW	67090	Keith L. Remington 253 S.W. 4th Avenue Ontario, OR 97914
T310P; T.C. 3A10	SA1018SW	Bendix M4-C autopilot.	SO	15475	Bendix Avionics P.O. Box 9414 Fort Lauderdale, FL 33310
T310P; T.C. 3A10	SA2292WE	Modification of waste gate controls. Issued 1/20/71.	WE	25400	Comp Air, Inc. 1285 Rollins Road Burlingame, CA 94010
T310P, T310Q, 320, 320-1, 320A thru 320F, 340, 411, 411A, 401, 401A, B, 402, 402A, B, 421, 421A, 414; T.C. 3A10, 3A25, A7CE	SA128GL	Replace existing asbestos or bellows exhaust seal with slip joint. Reissued 12/15/78.	GL	84915	Frank Webner 725 N. Hamilton Road Columbus, OH 43219
T310P, Q, 320D, E, F; T.C. 3A10, 3A25	SA2750SW	Install Continental TSIO-520-E engine. Issued 4/10/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
T310P, T310Q, T310R, 320D, 320F; T.C. 3A10, 3A25	SA2862SW	CFS-2000 electronic fuel 0 flow metering system. Issued 10/18/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
T310P, T310Q, T310R, 320D, E, F; T.C. 3A25	SA4011SW	Installation of TSIO-520-N, or TSIO-520-NB engine. Issued 7/9/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
310Q; T.C. 3A10	SA723CE	Incorporate openable windows and drop hole.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
310Q, T310Q; 310R, T310R; T.C. 3A10	SA775CE	Installation of janitrol Aero Division vapor cycle air conditioning system. Amended 12/9/74.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
T310Q; T.C. 3A10	SA2242SW	Continental TSIO-520-J engines. Issued 9/15/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
310R; T.C. 3A10	SA103GL	Install Norton Company radome Part No. 4096X. Amended 6/22/76.	GL	61750	Norton Company P.O. Box 350 Akron, OH 44309
310R/T310R; T.C. 3A10	SA1301CE	Installation of Enk Aviation fire suppression system. Amended 11/28/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
310, 320; T.C. 3A10, 3A25	SA99SW	Automatic pilot AK113 and lateral guidance radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320; T.C. 3A10, 3A25	SA234EA	Installation of Chamberlain 2310K-B series radome kit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309
310, 320; T.C. 3A10, 3A25	SA237SO	Control wheel modification. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310, 320 Series; T.C. 3A10, 3A25	SA272EA	Installation of Chamberlain 2014K-B radome kit as follows: Kit No. 2014K-B for Bendix RDR-100 or RDR-110 radar systems with 12" antenna and transmitter receiver unit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309
310, 320 Series; T.C. 3A10, 3A25	SA338SW	Automatic pilot AK125.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA409SW	Automatic pitch trim AK137.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA446CE	30-gallon auxiliary fuel tank in baggage compartment.	CE	36000	FloAir, Inc. Municipal Airport Newton, KS 67114
310, 320 Series; T.C. 3A10, 3A25	SA455WE	Single-piece windshield.	WE	20630	Cessna Components, Inc. P.O. Box 521 Long Beach, CA 90801
310, 320 Series; T.C. 3A10, 3A25	SA471EA	SAGA (Semi-automatic gear actuating) system.	GL	44010	In-Flight Services Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
310, 320 Series; T.C. 3A10, 3A25	SA521SW	Automatic pilot AK157 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA667SW	AK222 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA722WE	30-gallon wing leading edge fuel tanks. Amended 9/2/65.	WE	20630	Cessna Components, Inc. 3200 Airport Avenue Santa Monica, CA 90406
310, 320 Series; T.C. 3A10, 3A25	SA1175WE	One-piece windshield.	WE	14238	Cee Bailey's Aircraft Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
310, 320 Series; T.C. 3A10, 3A25	SA1452WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1604WE	Installation of Brittain B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1880WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; 320 Series; 336 Series; 337 Series; 401, 402, 411, 421 Series; T.C. 3A10, 3A25, A2CE, A6CE, A7CE	SA1675WE	Installation of exhaust gas temperature monitoring systems Model EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
320 Series; T.C. 3A25	SA3-737	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA101SO	One right-hand and two left-hand single seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320 Series; T.C. 3A25	SA104EA	L-2C autopilot slave cables around existing approved camera opening in lower surface of fuselage.	EA	20630	Aero Service Corporation North Philadelphia Airport Philadelphia, PA
320 Series; T.C. 3A25	SA117CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA119SO	Passenger seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
320 Series; T.C. 3A25	SA127SW	Auxiliary baggage compartment and adjustable seat modification.	SW	37154	Gen-Aero, Inc. P.O. Box 6767 San Antonio, TX 78205
320 Series; T.C. 3A25	SA130CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA306CE	GUARD System (gear up automatic response device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
320 Series; T.C. 3A25	SA492SW	Emergency alternate air door actuation.	SW	33270	El Paso Natural Gas Company P.O. Box 1492 El Paso, TX 79910
320 Series; T.C. 3A25	SA632WE	B-4 flight control system including pitch assist PC-1, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
320 Series; T.C. 3A25	SA744SW	M4B/C autopilot.	SO	15475	The Bendix Corporation Avionics Group P.O. Box 9414 Fort Lauderdale, FL 33310
320, 320-1; T.C. 3A25	SA285SO	Installation of Lycoming IO-540-A1A5 powerplants and Hartzell HCA3XK-2B/7636D propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320, 320-1, 320A, 320B, 320C; T.C. 3A25	SA518SO	Installation of Continental IO-520-E derated engines and McCauley D3AF32C87/82NC-6 or -8 propellers. Issued 8/28/72.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F (320 series S/N's 0001-D9999; 320E0001-F9999); T.C. 3A25	SA110GL	Install Cleveland conversion kit P/N 199-64. Issued 6/30/76.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
320, 320A, 320B, 320C, 320D, 320E, 320F S/N's 0001 and on; T.C. 3A25	SA808CE	Install Airborne wing and tail pneumatic deice kit 703C. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
320, 320-1, 320A, B, C, D, E, F, 340; T.C. 3A25	SA3231WE	Installation of recognition light assembly on horizontal stabilizer. Issued 7/8/76.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
320, 320A; T.C. 3A25	SA3239WE	Installation of nacelle baggage lockers. Issued 7/27/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, B, C, D, E, F; T.C. 3A25	SA3242WE	Installation of pilot's and co-pilot's side vent windows. Issued 7/30/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, 320B, 320C, 320D, 320E, 320F; T.C. 3A25	SA3822WE	Installation of 34-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
320, 320A thru 320F, 320-1, 340; T310P, T310Q; 401, 401A, B, 402, 402A, B; 411, 411A, 414, 421, 421A; T.C. 3A25, 3A10, A7CE, A7CE	SA1642WE	Modification of exhaust system components. Amended 12/7/73.	SW	87348	Wooley Tool & Manufacturing Div. Chromalloy American Corporation P.O. Box 3508 Odessa, TX 79760
320A, B, C, D, E, F, 340, 340A; T.C. 3A25	SA193RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welidng Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
320A, B, C, D, E, F, 320-1; T.C. 3A25	SA3164SW-D	Install automatic flight system AK584 consisting of Century IIB automatic pilot with optional radio coupler. Issued 11/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
320A thru 320D; T.C. 3A25	SA2339WE	Installation of exhaust bellows. Issued 4/12/71.	WE	01735	Aero Bellows Manufacturing Company 3211B Winona Avenue Burbank, CA 91504
320E, 320F; T.C. 3A25	SA4GL	Installation of Bendix FCS-810 autopilot flight director system. Issued 10/18/72.	GL	47767	Ralph Kerns Kerns Aircraft Electronics, Inc. Weir Cook Municipal Airport Indianapolis, IN 46206

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
320E, 320V; T.C. 3A25	SA2122WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Hartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
320F; T.C. 3A25	SA4012SW	Dual camera port. Issued 7/6/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
335, 340A; T.C. 3A25	SA1302CE	Install Enk Aviation fire suppression system. Amended 10/9/79.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
336; T.C. A2CE	SA203SW	Right front seat replaced with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72003
336; T.C. A2CE	SA286NW	Request for multiple STC on Model 336. Issued 4/23/76.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
336; T.C. A2CE	SA445SW	Automatic pilot AK140, pitch trim system AK141, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
336; T.C. A2CE	SA936CE	STOL Kit installation. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
336; T.C. A2CE	SA1260CE	Install FiQuench extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
336; T.C. A2CE	SA1355CE	Chrome-plated brake disc installation. Issued 8/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
336; T.C. A2CE	SA1875SW	Wing edge leading cuffs, wing tips, vortex generators on fuselage and fairing on vertical tails. Reissued 9/15/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
336, 337; T.C. A6CE, A2CE	SA1056SW	Revise wing contours leading edge and redesign landing light deflector plates. Reissued 2/13/75.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
336, 337, 337A thru C; T.C. A6CE, A2CE	SA406CE	Hoskins Supp. Position Light System includes Model A wing tip lights, Model 2 fuselage light used as tail light or Model L tail light. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
337; T.C. A6CE	SA491SW	Automatic pilot AK135, automatic pitch trim AK156, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA668SW	AK210 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA1473CE	Installation of Tull microwave landing system with modified King KX175B and KN 73 receivers. Issued 2/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
337; T.C. A6CE	SA2200WE	Installation of Brittain Industries B2C and BSS flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
337, 337A, B, C, D, E, F, G, M337B, T337B, C, D, E, F, G; T.C. A6CE	SA937CE	Installation of STOL kit (leading edge cuffs, stall fence, droop wing tips, and vortex generators on rear engine lower cowling). Amended 5/25/78.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
337, 337A, B, C, D, E, F, G, M337B, N337B, T337B, C, D, E, F, G; T.C. A6CE	SA1258CE	Installation of FIQUENCH fire extinguishing system in cabin and/or fire extinghishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
337, 337A, 337B, T337B, 337C, 337D, 337E, 337F, 337G; T.C. A6CE	SA1558SW	Vortex generators on fuselage, wing leading edge cuffs, wing tips, and fairings on vertical tail. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
337, 337A (USAF 02B), 337B, M337B (USAF 02A), 337C, T337B, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G; T.C. A6CE	SA1627WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, stall fences, aileron centering springs, conical cambered wing tips and flap actuated elevator trim spring. Also takeoff gross weight increase for all models except for T337G and 337G. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
337, 337A; T.C. A6CE	SA2335WE	Installation of one-piece windshield and relocation of compass. Reissued 5/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route 1, Box 127D Leesburg, FL 32748
337, 337A, B, C, D, E, F, G, M337B, T337B, T337C, T337D, T337E, T337F, T337G; T.C. A6CE	SA3056WE	Installation of fuel flow instruments. Issued 8/15/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
337, 337A, 337B, T377B, 337C, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G, T337P; T.C. A6CE	SA3818WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
337, T337, 337E, T337E; T.C. A6CE	SA1356CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
337, T377G; T.C. A6CE	SA478NW	Installation of RDR 160 weather radar. Issued 7/7/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
337A; T.C. A6CE	SA190SO	Cabin door removed and wind deflector installed.	SO	90106	Young, Isherwood & Marsh P.O. Box 982 Christiansted St. Croix, Virgin Islands
337A; T.C. A6CE	SA801SW	Mitchell AK244 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A thru 337H, T337B thru H, P337H; T.C. A6CE	SA32RM	Installation of electrically driven freon air-conditioning system. Amended 11/9/78.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA1922SW	Automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 10/11/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA3250SW-D	Mitchell automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 11/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337B; T.C. A6CE	SA842SW	AK252 consisting of Century III autopilot with optional pitch trim stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337D; T.C. A6CE	SA672CE	Install auxiliary fuel tank in baggage area.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
337D; T.C. A6CE	SA678CE	Install fuselage top emergency exit door.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
337D; T.C. A6CE	SA1038EA	Installation of recognition lights (LOGO) on trailing edge of Robertson wing tips. Issued 8/9/76.	EA	29998	DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
337D, T337D, 337G, T337G; T.C. A6CE	SA478NW	Installation of Bendix weather radar system. Amended 4/13/78.	NW	67135	Renton Aviation, Inc. 840 Perimeter Road Renton, WA 98055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
337D, 337E, 337F, 337G, T337D, T337E, T337F; T337G; T.C. A6CE	SA4828O	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and flight direcotr indicator. Amended 7/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
337E, F; T.C. A6CE	SA1359SW	Mitchell automatic flight system FD/AP282-345 consisting of flight director/autopilot with optional pitch trim. Issued 5/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F; T.C. A6CE	SA1478SW	Mitchell automatic flight system AK345 consisting of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 6/9/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067
337E, F,; T.C. A6CE	SA1520SW	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 10/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3148SW-D	Mitchell automatic flight system AK537 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3149SW-D	Mitchell automatic flight system AK536 consisting of Century IV autopilot or Model AK536FD flight director autopilot with optional remote annuciator. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3252SW-D	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 11/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337G; T.C. A6CE	SA1205CE	Installation of King KFC-200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/6/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
F337E, FT337E, F337F, FT337F, F337G, FT337GP; T.C. A23EU	SA1259CE	Install FiQuench fire extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
340 Series; T.C. 3A25	SA186NW	Installation of Continental TSIO-520-J engine. Issued 5/30/75.	NW	85165	Western Skyways Portland/Trourdale Airport Troutdale, OR 97060
340 Series; T.C. 3A25	SA474NW	Replace original split flaps with Fowler flaps.	NW	68500	Robertston Aircraft Corporation 939 West Perimeter Road Renton, WA 98055
340; T.C. 3A25	SA1357CE	Chrome-plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
340 Series; T.C. 3A25	SA1441SW	Mitchell automatic flight system AK367 consisting of Century III autopilot with optional automatic pitch trim, radio, and glide slope couplers. Issued 3/15/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA1442SW	Mitchell automatic flight system FD/AP282-367 consisting of flight director/autopilot with automatic electric trim. Issued 3/3/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA1881SW	Continental TSIO-520-J engine. Issued 5/23/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
340 Series; T.C. 3A25	SA1979SW	In-Line fuel pumps for auxiliary tanks. Issued 5/8/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340 Series; T.C. 3A25	SA2346SW	Teledyne Continental TSIO-520-N engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340; T.C. 3A25	SA2770SW	Cleveland heavy duty brakes. Issued 5/9/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
340 Series; T.C. 3A25	SA3043SW-D	Mitchell automatic flight system AK525 or AK525 FD consisting of Century IV autopilot with command/ automatic electric pitch trim system and optional remote annuciator panel. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA3044SW-D	Mitchell automatic flight system YK525 consisting of yaw damper system. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340; T.C. 3A25	SA3485WE	Installation of Continental TSIO-520-N engines and increase takeoff power to 310 h.p. Amended 11/18/77.	WE	68120	Riley Aircraft Corporation 2383 Palomar Airport Road Carlsbad, CA 92008
340, 340A; T.C. 3A25	SA16RM	Installation of freon type air conditioning system. Amended 10/6/77.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
340, 340A; T.C. 3A25	SA281GL	Install Cleveland conversion kit P/N 199-72. Issued 11/8/78	GL	23260	Cleveland Wheels and Brakes Van Sickle Div. of Parker Hannifin 1160 Center Road Avon, OH 44011
340, 340A; T.C. 3A25	SA502SO	Installation of Bendix FCS-810 automatic flight control system including manual eletric trim and optional flight director indicator DH-841. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340, 340A; T.C. 3A25	SA914EA	Installation of Radome kit P/N 4057KX. Amended 5/24/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
340, 340A; T.C. 3A25	SA1062CE	Installation of Collins AP-107 autopilot. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
340, 340A; T.C. 3A25	SA2483SW	Increase seating capacity on aft baggage shelf for a total of 7 occupants. Reissued 3/20/78.	SW	66300	RAM Aircraft Modification P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340, 340A; T.C. 3A25	SA2844SW	Installation of SDI Model CFS-2000, -2001, or FT-200 indicating fuel flow system. Amended 3/9/79.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
340, 340A; T.C. 3A25	SA3871WE	Installation of vapor cycle air conditioning system. Issued 1/15/80.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
340, 340A (S/Ns 340A0001 thru 340A0600); T.C. 3A25	SA3923WE	Installation of Lycoming TIO-540-R2AD engines. Issued 6/1/79.	WE	68120	Riley Aircraft Corporation 2016 Palomar Airport Road Carlsbad, CA 92008
340-0001 and on; T.C. 3A25	SA55GL	Install Airborne wing and tail pneumatic deice kit 710. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
340A; T.C. 3A25	SA1015SO	Installation of Bendix FCS-870 automatic flight control system, including manual electric trim and optional flight director system. Issued 8/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
340A; T.C. 3A25	SA1025SO	Installation of a Bendix NP-2041A area navigation computer programmer. Issued 10/4/78.	SO	15475	Bendix AVionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340A; T.C. 3A25	SA1276CE	Install King KFC 200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or KG-258 attitude horizon gyro and a KC-292 mode controller. Amended 5/8/78	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
340A; T.C. 3A25	SA3610WE	Installation of Silver Instruments Fueltron IIIG fuel indicating system. Issued 3/15/78.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, 421B, 421C; T.C. A7CE	SA197GL	Install Cleveland conversion kit P/N 199-76. Amended 8/28/78.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Ind., Inc. 1160 Center Road Avon, OH 44011
401, 401A, 401B, 402, 402A, 402B (normal category); T.C. A7CE	SA29NW	Installation of Fowler Flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 2/23/73.	NW	68500	Robertson Aircraft Corporation Renton Municipal Airport Renton, WA 98055
401, 401A, 402, 402A, 402B, 414; T.C. A7CE	SA109RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA117NW	Installation of Allison 250-B17 or 250-B17B engines and related changes. Reissued 1/6/77.	WE	25640	Commuter Investment and Development Corporation 2800 Clybourn Avenue Van Nuys, CA 91406
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA167GL	Install Cleveland conversion kit P/N 199-72. Issued 4/15/77.	GL	23260	Cleveland Wheels and Brakes Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011
401, 401A, 402, 402A, B, 414; T.C. A7CE	SA194RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
401, 402, 411, 411A, 401A, 401B; T.C. A7CE	SA346EA	Installation of Chamberlain radome kit No. 2022K-B for Bendix RDR-100 or RDR-110 series radar system. Amended 7/30/71.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A; T.C. A7CE	SA437EA	Installation of radome P/N 2022X. Amended 5/27/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A, 414, 421, 421A; T.C. A7CE	SA438EA	Installation of Norton radome kit No. 2022X-3. Amended 11/2/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
401A, 401B, 402A, B, 414, 421, 421A, 421B; T.C. A7CE	SA465SO	Installation of Bendix FCS-810 automatic flight control system including flight director indicator DH-841( ) and manual electric trim. Amended 6/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA618SO	Installation of M-4B or M-4C automatic flight control systems. Amended 4/27/73.	SO	15475	The Bendix Corporation Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA646CE	Install wing and tail pneumatic deice kit 702A on 401/402 aircraft (S/N 0135 and above), kit 702B on 414 aircraft and kit 702C on 401/402 aircraft (S/N 0001 through 0134 only). Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
401, 401A, B; T.C. A6CE	SA1158SW	Mitchell automatic flight system FD/AP282-302 consisting of flight director/automatic pilot and automatic pitch trim. Issued 6/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
401, 401A, 401B, 402, 402A; T.C. A7CE	SA1206SW	Edo-Aire Mitchell automatic flight system AK302, consisting of Century III autopilot with optional pitch trim, radio, and glide slope couplers. Issued 10/23/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, B, C; T.C. A7CE	SA1326CE	Installation of Avcon Industries TSO C39a stretcher. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
401, 401A, 402, 402A, 411, 411A, 414; T.C. A7CE	SA1350CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 414A, 421, 421A, 421B, 421C; T.C. A7CE	SA1393CE	Install forward baggage door warning system. Issued 1/3/78.	CE	84955	Wells Aircraft, Inc. Municipal Airport Hutchinson, KS 67501
401, 401A all S/N's, 402, 402A, 402B thru S/N 0300, 411, 411A all S/N's, 414 thru S/N 0350, 421, 421A, 421B thru 0300; T.C. A7CE	SA2091WE	Installation of air conditioning system. Amended 5/21/79.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
401, 401A, B, 402, 402A, B; T.C. A7CE	SA2845SW	Symbolic Displays CFS-2000 electronic fuel flow metering system. Issued 9/8/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
401*, 401A*, 401B*, 402*, 402A*, 402B*, 402C, 411, 411A, 414*, 414A, 421, 421A, 421B, 421C; *Includes those models modified per STC SA117NW.	SA3003WE	Installation of recognition light assembly on horizontal stabilizer. Amended 2/26/79.	WE	30000	Devore Aviation Corporation 16160 Stagg Street Van Nuys, CA 9[illegible]
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 421, 421A, 421B; T.C. A7CE	SA3017WE	Installation of fuel flow instruments.	WE	71780	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
401, A, B, 402, 402A; T.C. A7CE	SA3057SW-D	Mitchell automatic flight system AK538 or AK435FD consisting of Century IV autopilot or Century IV flight director autopilot with command/autopilot electric pitch trim and annuciator. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, B, 402; T.C. A7CE	SA3058SW-D	Mitchell flight system YK535 consisting of yaw damper system. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA3038WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box [illegible]151 Van Nuys, CA 91409
401, 401A, 401B, 402, 402A, 402B, 414 thru S/N 414-0350; T.C. A7CE	SA3930WE	Installation of 37.5 gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
401, 402; T.C. A7CE	SA784SW	Mitchell Model AK240 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 402; T.C. A6CE	SA1472WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402; T.C. A6CE	SA1599WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402, 411; T.C. A7CE	SA472EA	SAGA (Semi-automatic gear actuating) system. Amended 5/23/67.	GL	43750	In-Flight Devices Corporation 4805 Sawyer Road International Airport Columbus, OH 43219

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
401A; T.C. A7CE	SA3192WE	Installation of single global and dual global GNS-500A navigation system. Amended 3/23/79.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
402; T.C. A7CE	SA634CE	Install tenth seat and attach FAA approved AFMS.	CE	36000	FloAir, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
402; T.C. A7CE	SA1742SW	Vapor cycle air conditioning system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
402; T.C. A7CE	SA1863SW	Two cameras and navigation sight. Issued 5/7/74.	SW	42825	A.D. Howard, Jr. 6817 N.W. 43rd Street Bethany, OK 73008
402; T.C. A7CE	SA2424WE	Installation of Allison 250-B17 engines and related changes. Amended 9/21/73.	WE	10208	American Jet Industries 3021 Airport Avenue Santa Monica, CA 90405
402, 402A; T.C. A7CE	SA2333SW	Fiberglass tailcone for magnetometer. Issued 7/23/76.	SW	42825	A.D. Howard, Jr. 1911 Moulton Court Oklahoma City, OK 73127
402A, 402B, 421B, C, 414; T.C. A7CE	SA807EA	Installation of Norton Radome Kit No. 4009X. Amended 9/24/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
402B; T.C. A7CE	SA700CE	Install right-hand side rear window.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
402B; T.C. A7CE	SA1061CE	Installation of Collins Company AP-107 (3 axis) autopilot system. Issued January 1975.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1110CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1111CE-D	Installation of AP-107 autopilot (2 axis). Amended June 1976.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1501CE	Sierra utility flight inspection equipment rack installed in left hand side forward location. Issued 7/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
402B, 402C; T.C. A7CE	SA1303CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
402B (S/Ns 402B0301 and up), 414 (S/Ns 414-0351 and up), 414A (S/Ns 414A0001 and up), 421B (S/Ns 421B0001 and up); 421C (S/Ns 421C001 and up) (6, 7, 8, 9 or 10 place); T.C. A7CE	SA8RM	Installation of Freon type air-conditioning system. Amended 1/12/78.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
402B, 414, 421B; T.C. A7CE	SA547SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim and optional flight director system in serial numbers 402B0301 and up, 4140351 and up, and 421B0301 and up. Issued 8/17/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
402B, 414, 421B; T.C. A7CE	SA584SO	Installation of Bendix YD-4 yaw damper system. Issued 4/5/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
402C; T.C. A7CE	SA1502CE	Install King KFC200 automatic flight control system. Issued 7/11/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
402C, 414A, 421C; T.C. A7CE	SA1526CE-D	Installation of King KAS 297 altitude selector option. Issued 2/6/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404, S/N 404-0001 and up; T.C. A25CE	SA143RM	Installation of air conditioner system. Issued 6/2/78.	RM	45750	J B Systems, Inc. P.O. Box 800 Longmont, CO 80501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
404; T.C. A25CE	SA195GL	Installation of Norton radome kit 4009X.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
404; T.C. A25CE	SA195RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
404; T.C. A25CE	SA721NW	Installation of camera bays. Issued 2/23/79.	NW	85165	Western Skyways Portland-Troutdale Airport Troutdale, OR 97060
404; T.C. A25CE	SA1297CE	Installation of King KFC 200 2-axis (3 optional), flight control system with a KI-255 (or -256) flight command indicator, or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 5/11/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA1482CE	Installation of Tull microwave landing system. Issued 4/9/79.	CE	81650	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
404; T.C. A25CE	SA1304CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
404; T.C. A25CE	SA1528CE-D	Installation of King KAS 297 altitude selector option. Issued 2/18/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA3384WE	Removal of cargo doors and installation of P/N A770000 airstream deflector. Issued 6/8/77.	WE	07630	Airflite, Inc., South 2700 East Wardlow Road Long Beach, CA 90801
404; T.C. A25CE	SA3388WE	Installation of recognition lights on horizontal stabilizer. Issued 4/29/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
404; T.C. A25CE	SA4017WE	Installation of SDI model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 8/31/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
411 Series; T.C. A7CE	SA402CE	50-gallon auxiliary fuel tank.	CE	36000	Floair, Inc. Municipal Airport Newton, KS 67114
411 Series; T.C. A7CE	SA515SW	Automatic pilot AK158, lateral guidance radio coupler AK123 and automatic trim system AK159.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA681SW	AK221 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA839EA	Installation of Radome Kit P/N 4009K-B for Bendix RDR-100 and RDR-110 systems - 12" antenna. Amended 11/29/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
411 Series; T.C. A7CE	SA1227WE	Installation of Brittain Model B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
411 Series; T.C. A7CE	SA1467WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
411 Series; T.C. A7CE	SA2378WE	Installation of Global Navigation Model GNS-200 VLF navigation system. Amended 2/26/74.	WE	38090	Global Navigation, Inc. 2733 Pacific Coast Highway Torrance, CA 90505
411 Series; T.C. A7CE	SA2913WE	Installation of GNS-500 VLF navigation system. Amended 2/28/75.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
411 Series; T.C. A7CE	SA3138WE	Installation of GNS-500A VLF/OMAGE navigation system. Amended 1/17/77.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
411, 411A Series; T.C. A7CE	SA1120WE	Bendix automatic flight control system type M4B and M4C.	SO	15475	The Bendix Corporation Avionics Products Fort Lauderdale, FL 33310
400, 411A, 421, 421A; T.C. A7CE	SA102RM	Installation of exhaust turbo connector, P/N 042177-5. Issued 5/19/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street Denver, CO 80207
411, 411A, 421, 421A, 421B; T.C. A7CE	SA108RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless, sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
411, 421; T.C. A7CE	SA487CE	Install windshield wipers.	GL	27500	Marquette Metal Products Company Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
414; T.C. A7CE	SA48NW	Installation of fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 6/29/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
414; T.C. A7CE	SA433SO	Installation of Bendix Model M4C flight control system. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
414; T.C. A7CE	SA1040CE	Installation of AP-107 autopilot. Amended 10/2/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
414; T.C. A7CE	SA1219SW	Mitchell automatic flight system AK308 consisting of Century III with automatic pitch trim, radio, and glide slope couplers. Issued 11/18/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA1899SW	Freon air conditioning system. Issued 9/9/74.	SW	37154	Gen-Aero, Inc. P.O. Box 16278 San Antonio, TX 78246
414; T.C. A7CE	SA1220SW	Mitchell automatic flight system Model FD/AP282-308 consisting of flight director/autopilot, autopilot pitch trim. Issued 11/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA2354SW	Teledyne Continental TSIO-520-N, -J, engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
414; T.C. A7CE	SA2812SW	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
414; T.C. A7CE	SA3334SW-D	Mitchell automatic flight system AK624 consisting of Century IV autopilot or AK624FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3335SW-D	Mitchell yaw damper system, YK628. Issued 3/6/69.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3666WE	Installation of Silver Instruments Fueltron IIIG digital fuel flow and totalizer system. Issued 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
414; T.C. A7CE	SA3682WE	Installation of Continental TSIO-520-N engine and associated installation components. Issued 7/12/78.	WE	68120	Riley Aircraft Corporation 2386 Palomar Airport Road Carlsbad, CA 92008
414A T.C. A7CE	SA985SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director and optional yaw damper. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
414A; T.C. A7CE	SA986SO	Installation of Bendix NP-2041A NP-2041A area navigation computer programmer. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
414A; T.C. A7CE	SA1400CE	Install Enk Aviation fire suppression system. Issued 2/9/78.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
414A; T.C. A7CE	SA1431CE	Install King KFC-200 flight control system with or without flight director. Issued 8/31/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
414A; T.C. A7CE	SA1521CE-D	Installation of King KFC 250 flight control system. Issued 11/14/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathes, KS 66061
414A; T.C. A7CE	SA3304SW-D	Mitchell automatic flight system AK774/FD consisting of Century IV/ flight director autopilot with optional remote annunciator.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414, 421; T.C. A7CE	SA536CE	Install electrical connectors in pressure bulkhead(s) at Station(s) 100 and/or 273.94. Amended 12/4/70.	RM	05940	Charles O. Peacock Aircraft Radio & Accessory Co., Inc. Hangar #4, Stapleton Field Denver, CO 80207
414, 421A; T.C. A7CE	SA732EA	Installation of radome Part No. 4004X. Amended 5/12/75.	GL	61750	Norton Company Plastics & Synethetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
414, 421A; T.C. A7CE	SA780EA	Installation of Radome Kit No. 4004K-B for Bendix RDR-100 or RDR-110 series radar systems - 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
414, 421, 421A, B, C; T.C. A7CE	SA2440SW	Airstair door saver. Issued 3/23/77.	SW	00060	AAR of Oklahoma, Inc. P.O. Box 19508 Oklahoma City, OK 73119
421 Series; T.C. A7CE	SA574CE	Installation of toilet seat belt.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
421 Series; T.C. A7CE	SA591EA	Installation of Radome Part Part No. 3084X. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
421 Series; T.C. A7CE	SA661EA	Installation of Radome Kit No. 3084K for Bendix RDR-100 or RDR-110 series radar systems 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
421 Series; T.C. A7CE	SA662CE	Installation of Jet Electronics & Technology, Inc. Model FC120A autopilot.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street Grand Rapids, MI 49508
421 Series; T.C. A7CE	SA673CE	Install Hartzell HC-B3WF-2/9349-3 propellers.	GL	41000	Hartzell Propellers, Inc. 350 Washington Avenue P.O. Box 909 Piqua, OH
421 Series; T.C. A7CE	SA968SW	Mitchell automatic flight system AK279 consisting of Century II autopilot with optional automatic pitch trim, radio, and glide slope couplers, automatic aileron stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421 Series; T.C. A7CE	SA978SW	Collins FD108 flight director system.	SW	06000	Aircraftsmen, Inc. Box 82516 Oklahoma City, OK 73108
421 Series; T.C. A7CE	SA1776WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
421, 421A; T.C. A7CE	SA794CE	Install vapor cycle air conditioning system. Reissued 10/15/71.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
421, 421A; T.C. A7CE	SA1897WE	Installation of a seventh seat in aft baggage compartment.	RM	25250	Combs Aircraft, Inc. Stapleton Internacional Airport Denver, CO 80207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
421, 421A, 421B; T.C. A7CE	SA2RM	Installation of a seventh seat in aft baggage compartment. Reissued 4/6/73.	RM	25250	Combs - Gates Denver, Inc. Stapleton International Airport Denver, CO 80207
421, 421A, 421B; T.C. A7CE	SA18NW	Installation of Fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 4/13/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
421, 421A, 421B; T.C. A7CE	SA632SO	Installation of Bendix Model M-4C automatic flight control system, including manual electric trim. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33309
421, 421A, 421B; T.C. A7CE	SA1200CE	Installation of FiQuench cabin and/or engine fire extinguishant system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
421, 421A, 421B; T.C. A7CE	SA1210CE	Installation of Hanlon & Wilson exhaust systems, P/N 8108-59 and P/N 8109-59. Amended 1/3/80.	EA	40350	Hanlon & Wilson Company P.O. Box 641 Jeanette, PA 15644
421, 421A, 421B, 421C; T.C. A7CE	SA1343CE	Install Sierra data console on left hand seat rails. Reissued 9/15/77.	CE	71660	Sierra Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, 421B, 421C; T.C. A7CE	SA1375CE	Reduce height of existing survival seat. Reissued 10/3/77.	EA	71660	Sierra Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, B, C; T.C. A7CE	SA3228WE	Installation of Silver Instruments Fueltron IIIG fuel indicating system. Issued 3/14/78.	WE	71740	Silver Instruments 1096 National Avenue Hayward, CA 94545
421B; T.C. A7CE	SA135GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 10/26/76.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
421B; T.C. A7CE	SA952CE	Installation of King Radio Model KFC-300 automatic flight control system. Amended 12/19/75.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA986CE	Installation of Collins Radio Group AP-106 autopilot system. Amended January 1977.	CE	24250	Collins Radio Group Avionics Certification Center Cedar Rapids, IA 52406
421B; T.C. A7CE	SA987CE	Installation of Sperry SPZ-200/ STARS IVC automatic flight control system with optional Sperry AA-220/ RT-220 radar altimeter. Issued February 1974.	CE	90080	Yingling Aircraft, Inc. P.O. Box 1162 Wichita, KS 67201
421B; T.C. A7CE	SA1001CE	Installation of H-14 autopilot. Issued April 1974.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA1035CE	Installation of openable window aft of cabin door. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
421B; T.C. A7CE	SA1167CE	Installation of AP 107 autopilot (2 axis). Serials 301 and subsequent. Issued 3/29/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1667SW	Mitchell automatic flight system Model YK385 consisting of yaw damper. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421B; T.C. A7CE	SA1168CE	Installation of Collins Radio Group AP-107, 3 axis, autopilot system and interface with Collins 329A-4V indicator. Serials 301 and subsequent. Issued 10/20/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1668SW	Mitchell automatic flight system AK407, consisting of Century IV autopilot with trim; or AK407/FD consisting of Century IV autopilot/ flight director with trim. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
421B; T.C. A7CE	SA2749WE	Installation of Lear AFC-70 AP/FD steering computer system. Issued 8/23/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Reno, NV 89510
421B; T.C. A7CE	SA2810WE	Installation of Collins AP-105 autopilot and FD-108 flight director systems. Issued 1/30/74.	WE	78622	Tower Avionics Center Hangar 8, Oakland Int'l Airport Oakland, CA 94614
421B; T.C. A7CE	SA3881WE	Installation of dual elevator trim tab actuator. Issued 3/14/79.	WE	68120	Riley Aircraft Corporation 2386 Palomar Airport Road Carlsbad, CA 92008
421C; T.C. A7CE	SA196RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welidng Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
421C; T.C. A7CE	SA438NW	Replace original split flaps with Fowler flaps. Issued 4/22/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
421C; T.C. A7CE	SA886SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 2/26/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA890SO	Installation of Bendix FCS-810 automatic flight control system including manual electric pitch and optional flight director indicator. Amended 11/1/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA1120CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1121CE	Installation of Collins Radio Group AP-107 (2 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1122CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1246CE	Install King KFC-200 2 axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/4/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
421C; T.C. A7CE	SA1305CE	Install Enk Aviation fire suppression system. Issued 8/30/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
421C; T.C. A7CE	SA3110SW-D	Mitchell automatic flight system AK579, consisting of Century IV autopilot or AK579FD, consisting of Century IV flight director autopilot with remote annuciator. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3111SW-D	Mitchell yaw damper YK580. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3458WE	Modification of fuselage to install camera window. Issued 7/14/77.	WE	84000	Volpar, Inc. 7929 Hayvenhurst Avenue Van Nuys, CA 91406
441: T.C. A28CE	SA1424CE	Install Sierra Electronics consle. Reissued 7/3/78.	EA	71660	Sierra Research Corp. P.O. Box 222 Buffalo, NY 14225
441; T.C. A28CE	SA2818SW	Install three place side facing couch. Issued 7/19/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
441; T.C. A28CE	SA3498WE	Installation of tail flood light on horizontal stabilizer. Issued 10/18/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
500 Series; T.C. A22CE	SA8GL	Installation of engine synchronizer kit P/N 213522. Issued 4/18/73.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500 Series; T.C. A22CE	SA13RM	Installation of Branson cargo liner and retention system. Issued 7/23/73.	RM	09752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207
500 Series; T.C. A22CE	SA15RM	Installation of three-place couch with or without quick change aft divider. Amended 4/2/76.	RM	09752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207
500 Series; T.C. A22CE	SA18RM	Install beverage service buffet in baggage compartment. Issued 11/21/73.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA19RM	Install two lounge seats in rear of baggage compartment. Amended 11/8/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA23RM	Installation of aft beverage cabinet, P/N 90241-1. Amended 5/20/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA47RM	Installation of single seat in the center of aft baggage compartment. Reissued 3/10/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
500 Series; T.C. A22CE	SA51RM	Installation of tail cone ski rack. Reissued 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series; T.C. A22CE	SA52RM	Installation of stretcher. Amended 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series; T.C. A22CE	SA54RM	Installation of tail cone storage box and engine cover storage box. Amended 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA58RM	Installation of deluxe three-place aft couch. Amended 10/7/77.	RM	17085	Branson Engineering Company, Inc. 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA79RM	Installation of side-looking camera hatch. Reissued 7/29/77.	CE	20625	Cessna Aircraft Company Wichita Municipal Airport P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA83RM	Increased ramp and takeoff weights for restricted category operation. Issued 10/22/76.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA97RM	Installation of dual aft lounge seats. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA100RM	Installation of lounge seat toilet. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	ST131RM	Installation of Global Navigation, Inc. GNS-500A VLF/Omega navigation system. Issued 2/7/78.	RM	14127	Avionics Engineering of Denver, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
500; T.C. A22CE	ST174RM	Installation of extended width cabin door. Issued 5/4/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500; T.C. A22CE	SA645NW	Increased fuel and performance modifications. Issued 8/4/78.	NW	12270	Astec Engineering, Inc. 830 N. Riverside Drive Renton, WA 98055
500; T.C. A22CE	SA802NW	Installation of transponder identification switch on left hand control wheel. Issued 7/13/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
500 Series; T.C. A22CE	SA897SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement battery. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
500 (S/N 500-001 thru -0213); T.C. A22CE	SA991CE	Installation of KFC-300 automatic flight control system. Amended 4/10/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
500 Series; T.C. A22CE	SA1013CE	Installation of retractable aircraft recognition lights. Amended 7/26/78.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500 Series; T.C. A22CE	SA1059EA	Installation of an airways calibration system. Reissued 9/27/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 (S/N 350 and on); T.C. A22CE	SA1371CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 Series; T.C. A22CE	SA1574SW	Installation of hassock according to Qualitron Aero. Reissued 5/30/79.	RM	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1589SW	Installation of Singer Kearfott SKK-1000A doppler system; Collins INS-61B inertial navigation system; JET PS 823B emergency power system. Reissued 11/20/73.	CE	20225	Cessna Aircraft Company P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA1597SW	Stretcher installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 N. Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1619SW	Installation of emergency power supply according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1727SW	Jump seat. Issued 9/13/73.	SW	12250	Associated Radio Service Company Box 20718 Dallas, TX 75220
500 Series; T.C. A22CE	SA1945SW	Aft equipment bay storage unit. Issued 1/7/75.	SW	38242	William L. Goin, Jr. 7930 Airport Boulevard Houston, TX 77017
500 Series; T.C. A22CE	SA2383SW	Install refreshment bar and galley bulkhead. Issued 11/19/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
500 Series; T.C. A22CE	SA2925WE	Installation of power brake and skid control system. Issued 9/24/74.	WE	13230	Aviation Brake Systems, Ltd. 3535 West 5th Street Oxnard, CA 93030
500, 501; T.C. A22CE	SA2698SW	Freon air conditioning system. Issued 12/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
500, 501; T.C. A22CE, A27CE	SA2883SW	Installation of Ray Electronics Model 7507A battery current monitoring system. Issued 12/7/78.	SW	66500	Ray Electronics Company 11933 Warfield Drive San Antonio, TX 78216
500, 501, 550, 551; T.C. A22CE, A27CE	SA1051SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid battery. Issued 3/29/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
500, 501, 550, 551; T.C. A27CE, A22CE	SA2916SW	Installation of alternate gear horn switch. Issued 2/26/79.	SW	47720	Keith Products, Inc. 625 Opar Richardson, TX 75080
500, 501, 550, 551; T.C. A27CE, A22CE	SA4054SW	Installation of one, two, or three-place side facing seat, frame only. Issued 10/23/79.	SW	28000	Custom Aircraft Conversions 234 West Turbo Drive San Antonio, TX 78216
500, 550; T.C. A22CE	SA80RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Amended 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST151RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST166RM	Installation of three-place or single-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST174RM	Installation of extended width cabin door. Amended 5/18/79.	CE	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	SA1457CE	Install microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
500, 500; T.C. A22CE	SA1513CE	Installation of Avcon 4001-213 and -214 stretcher. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500, 550; T.C. A22CE	SA1534CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
500, 550; T.C. A22CE	SA2906WE	Installation of vertical tail floodlights on horizontal Amended 8/30/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
500, 550; T.C. A22CE	SA3000SW	Fabrication and installation of 3-place side facing couch and shoulder harness. Issued 5/25/79.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
501; T.C. A27CE	ST117RM	Installation of deluxe three-place aft couch. Issued 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	ST118RM	Installation of tail cone storage box and engine cover storage box. Issued 10/22/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	SA125RM	Installation of tail cone ski rack. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA126RM	Installation of stretcher. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA152RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Issued 9/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA177RM	Installation of a single seat in the center of aft baggage compartment. Issued 6/25/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA732NW	Installation of "Eagle" performance kit. Issued 5/10/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
501; T.C. A27CE	SA1372CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
501; T.C. A27CE	SA1423CE	Insalll King KFC-300 AFCS with duel flight director and transferable autopilot. Issued 6/21/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
501, 551; T.C. A27CE	SA150RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA171RM	Installation of three-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA1514CE	Installation of Avcon 4001-213 and -214 stretchers. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA1535CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA3409WE	Installation of vertical tail floodlights on horizontal stabilizer. Amended 8/30/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
550; T.C. A22CE	ST165RM	Installation of fiberglass tail cone in lieu of metal tail cone. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
CH-1C; T.C. 3H10	SH4WE	Fifth passenger seat and seat belt.	NW	84625	Washington Aircraft & Transport Co. Boeing Field Seattle, WA 98101
Miscellaneous	SA582NW	Replacement wire rope cable assemblies. Issued 5/12/78.	NW	81180	University Swedging 800 N.W. 46th Street Seattle, WA 98108

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
CHAMPION AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
402; T.C. A3CE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
DOYLE F. CHILD

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S2A; T.C. A8SO	SA2669WE	Installation of rear cockpit canopy. Reissued 1/27/76.	WE	70375	Universal Technology Div. of Art Scholl Aviation 4130 Mennes Riverside, CA 92509

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

COMMONWEALTH AIRCRAFT, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
175; T.C. A-729	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
175, 180, 180F, 185, 190F; T.C. 729	SA4-302	BH-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92505
175, 180, 180F, 185, 190F; T.C. 729	SA4-1208	Ceconite covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
175, 180, 180F, 185, 190F; T.C. 729	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
175, 180, F, 185, 190F; T.C. A-729	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
175, 180, F, 185, 190F; T.C. A-729	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
175, 180, -F, 185, 190F; 6000M; 9000; T.C. 729, 661, 624	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
175, 180, 180F, 185, 190F, 6000M, 9000, 9000 Deluxe; T.C. 729, 661, 624	SA2666WE	Ceconite 102 material covering of: 175, 180, 180F, 185, 190F - 4677 complete aircraft; 6000M - fuselage; 9000, 9000 Deluxe - wings, ailerons, horizontal stabilizer, elevators, vertical fins, rudder. 4/19/78	WE Worth Street	20250	Ceconite, Inc. Los Angeles, CA 90063
180; T.C. A-729	SA3976WE	Installation of McCauley 1B90CM7038 propeller on aircraft equipped with Continental A-80-9 engine. Issued 6/20/79.	WE	28798	John E. Daugherty 3066 East St. Louis Avenue Las Vegas, NV 89104
185; T.C. 729	SA4-901	Fiberglas covering on wings.	WE	38060	Glasco-Air Products Oxnard-Ventura County Airport Oxnard, CA 93030
185; T.C. 729	SA81GL	Installation of Continental C90-12F engine, McCauley 1B90CM7146 propeller, Maule tail wheel P/N SFS-1-4-P8. Issued 5/29/75.	GL	16890	Harvey Bolin Brandon, MN 56315
185; T.C. 729	SA1008WE	Installation of Poly-Fiber covering material. Amended 8/7/69.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92502
6000M; T.C. 661	SA441WE	Ceconite 101 covering of fuselage.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
7000, 9000L; T.C. 574, 591	SA519WE	Wheel adapters on Goodyear wheels 3LMBM.	WE	49345	Robert P. Lamb 2998 Daisy Avenue Long Beach, CA 90801
9000, 9000 Deluxe; T.C. 624	SA229WE	Ceconite 101 covering of wings, ailerons, horizontal stabilizer, elevators, vertical fin and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

CONSOLIDATED AERONAUTICS, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C-1; T.C. 1A13	SA1-198	Spray rails addition.	EA	76300	Jack Strayer, Inc. 137 Heights Drive Yonkers, NY 10701
C-1;	SA247EA	Extended wing tips.	NE	50780	Herbert P. Lindblad Mousam Road Springvale, ME 04487
C-1, 2; T.C. 1A13	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
C-1, 2; T.C. 1A13	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/75.	EA	65332	Alfred R. PUccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
C-1, C-2, LA-4; T.C. 1A13	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
C-1, C-2, LA-4, LA-4A, LA-4P; T.C. 1A13	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
LA-4; T.C. 1A13	SA222NW	Installation of nose bumper. Issued 10/16/75.	NW	66025	Rader Aircraft Sales & L.R.M. Products 3425 62nd S.W. Seattle, WA 98116
LA-4; T.C. 1A13	SA581CE	Install cargo door. Reissued 4/9/69.	SW	49260	Lake-4 Sales Corporation P.O. Box 399 Hooks Memorial Airport Tomball, TX 77375
LA-4; T.C. 1A13	SA590CE	Install louvers on hull exterior.	GL	77090	Swanson Engineering Route 1 Conover, WI 54519
LA-4; T.C. 1A13	SA631CE	Install Lycoming IO-360-A1B engine, Hartzell HC-C2YK-1BI/L7666A-2 propeller and remove wing fillets. Reissued 7/27/79.	SW	49260	Lake 4 Sales Corporation P.O. Box 399 David Wayne Hooks Memorial Airport Tomball, TX 77375
LA-4; T.C. 1A13	SA781EA	Conversion of Lake LA-4 Amphibian to LA-4 Seaplane. Amended 11/28/69.	NE	02100	Aerofab, Inc. One High Street Sanford, ME 04073
LA-4; T.C. 1A13	SA822EA	Eligible for increase in gross weight to 2600 pounds with 200 hp. engine installed per STC SA631CE. Issued 5/26/70.	NE	02100	Aerofab, Inc. One High Street Sanford, ME 04073
LA-4; T.C. 1A13	SA1139SW	Wing line mooring kit.	SW	35315	Field & Stream Aviation 1014 Land Elg. Shreveport, LA 71101
LA-4; T.C. 1A13	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
LA-4; T.C. 1A13	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546

CONSOLIDATED AERONAUTICS, INC. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
LA-4; T.C. 1A13	SA2270WE	Installation of Rajay turbosupercharged Lycoming O-360-A1A or A1D engines (previously modified per STC SE145SO). Issued 11/5/70.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
LA-4, 4-200; T.C. 1A13	SA855EA	Installation of cabin air heat exchanger on LA-4 and LA-4-200. Issued 11/24/70.	NE	02100	Aerofab, Inc. One High Street Sanford, ME 04073
LA-4, -4-200; T.C. 1A13	SA2352SW	Installation of BSS, B2C, NAV Flite II, B-5, B-11 systems. Issued 9/3/76.	SW	17490	Brittain Industries, Inc. Box 51370 Tulsa, OK 74151
LA-4, LA-4A, -4-200; T.C. 1A13	SA3198SW-D	Mitchell automatic flight system AK681 consisting of Century IIB autopilot with optional radio coupler. Issued 3/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
LA-4, LA-4A, -4-200; T.C. 1A13	SA3199SW-D	Mitchell automatic flight system AK680 consisting of Century I autopilot with optional omni tracker. Issued 3/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
LA-4, -4A, -4P, -4-200; T.C. 1A13	SA876EA	Installation of auxiliary fuel system. Model LA-4-200 increase of gross weight to 2690 pounds. Issued 6/24/71.	NE	02100	Aerofab, Inc. One High Street Sanford, ME 04073
LA-4, -4A, -4P, -4-200; T.C. 1A13	SA533SO	Installation of hull booster plates, booster fouler and stiffener plate, S/N 246 and subsequent. Amended 5/22/73.	SO	17069	Lawrence H. Bradway Caribbean Lakes Sales P.O. Box 1592 Christiansted, St. Croix, VI 00820
LA-4-200; T.C. 1A13	SA4NE	Installation of Hartzell HC-E2YR-1BLF/FL766A-2 or HC-E2YK-1BL/L7666A-2 extended hub propeller on aircraft equipped with Lycoming IO-360-A1B6 engine. Issued 10/24/73.	NE	02100	Aerofab, Inc. One High Street Sanford, ME 04073
LA-4-200; T.C. 1A13	SA7NE	Installation of 3-bladed Hartzell HC-C3YR-1 RLF/FL 7663-8R propeller on aircraft equipped with Lycoming IO-360-A1B6 engine and Hartzell hydraulic governor Model F-2. Issued 6/20/74.	NE	02100	Aerofab, Inc. One High Street Sanford, ME 04073
LA-4-200; T.C. 1A13	SA343NW	Installation of drooped wing tips. Issued 8/20/76.	NW	57665	Robert Karl Maves P.O. Box 3226 Federal Way, WA 98003
LA-4-200; T.C. 1A13	SA360GL	Installation of Hartzell HC-C2YK-1BL( )/( )L7666( )-4Q propeller using the original installation hardware and components. No installation data are required. Issued 8/30/79.	GL	39823	Robert W. Haldi 7211 Aldgate Lane Indianapolis, IN 46250
LA-4-200; T.C. 1A13	SA2990WE	Installation of turbosupercharged Lycoming IO-360-A1B engine. Issued 2/14/75.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90807

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

COSTRUZIONI AERONAUTICHE GIOVANNI AGUSTA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A109A; T.C. H7EU	SH1135EA	Installation of a Collins ANS-31A area navigation system. Collins DME-40 system and miscellaneous avionic modifications. Amended 12/19/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
A109A; T.C. H7EU	SH2699SW	Stability augmentation/avionics equipment and cockpit modification for certification of single and pilot day-night (IMC) operations. Issued 5/18/78.	SW	12496	Atlantic Aviation Wm. P. Hobby Airport P.O. Drawer 12782 Houston, TX 77017

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
CURTISS-WRIGHT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C-46 (all models); T.C. A-772, A-789, 3A2	SA12PC	Installation of foldable cabin troop seat interior arrangement for convertible passenger-cargo capability. Issued 4/28/72.	EA	03550	Air America, Inc. 1725 K Street Washington, D.C. 20006
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA4-33	Modification for airworthiness certification in Transport Category under SR-406A maximum takeoff weight: 47,400 lbs.	WE	36100	The Flying Tiger Line Lockheed Air Terminal Burbank, CA 91500
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA4-258	C-46A wings on C-46F aircraft.	WE	44190	International Aircraft Maintenance Company Hangar 3, Lockheed Air Terminal Burbank, CA 91500
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA4-466	C-46A or C-46D stabilizer modified to C-46F stabilizer.	WE	08352	Air Spares, Unlimited 10904 Vanowen Street North Hollywood, CA 91603
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA4-499	Engine mount core assemblies on aircraft with Pratt & Whitney R-2800-43, -51, -51M1 or -75 engines.	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA4-524	106-1 engine mount core.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA4-525	106-1F and 106-1J engine mount cores.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA4-535	C-O-Two smoke detector system.	WE	36100	Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA4-1339	Ceconite 103 covering of ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA43SO	Increase in wing flap extension speeds.	SO	78390	Tempo Design Corporation P.O. Box 456 Miami, FL 33148
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA71SO	Engine throttle control rod replacement.	SO	10160	American Airmotive Corporation P.O. Box 187 Miami, FL 33148
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA98SO	Hydraulic fluid shut-off system (aft of firewall) for engine cowl flaps.	EA	61190	National Air Carrier Association 1625 I Street, N.W. Washington, D.C. 20000
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA185AL	Installation of bulk fuel oil tanks. Amended 11/23/66.	AL	34202	Fairbanks Air Service P.O. Box 1027 Fairbanks, AK 99701
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA312CE	Landing gear aural warning system.	GL	90134	Zantop Air Transport, Inc. Metropolitan Airport Detroit, MI 48233
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA386WE	Removal of left and right cabin doors in flight.	WE	44186	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA410CE	Increase flap speeds.	GL	90134	Zantop Air Transport, Inc. Detroit Metropolitan Airport Inkster, MI 48141
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA497WE	Removal of left cargo door (aft half only) and right cabin entrance door.	WE	44186	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA1039WE	Four standby Aerojet General 15KS-1000-A1 rocket engines.	WE	44186	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238
C-46 Series; T.C. 3A2, 772, 786, 789, 808	SA1087WE	AiResearch ATR4125-16 or 86727 aluminum oil cooler.	WE	44186	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238
C-46, C-46/CW-20F, Super C-46; T.C. A772	SA1340WE	Cabin interior arrangement.	WE	44186	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238

CURTISS-WRIGHT CORPORATION 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C-46, C-46/CW-20F, Super C-46; T.C. A772	SA1341WE	Oxygen system.	WE	44186	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238
C-46, C-46/CW-20F, Super C-46; T.C. A772	SA1744WE	Installation of various series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
C-46, C-46/CW20-T, Super C-46/CW20-T; T.C. 2A5, 3A2, 772, 786, 789, 808	SA117SO	Bergstrom BS-040-2 oil separator DL-040.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
C-46, C-46/CW20-T; T.C. 2A5, 3A2, 772, 786, 789, 808	SA129AL	Flap actuated landing gear aural warning device.	AL	67017	Reeve Aleutian Airways, Inc. P.O. Box 6027 Anchorage, AK 99500
C46A, C46D, C46F, C46R, C46E, CW-1; T.C. 3A2, 772, 789, 786, 808, 397	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
C-46A, C46D, C46E, C-46F, C-46R; T.C. 3A2, 772, 786, 789, 808	SA249CE	Install supplementary lighting system using Model B or F wing tip lights and Model C tail light. Optionally, two Model 2 fuselage lights may be used with Model B wing tip lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
C46A, D, E, F; T.C. A-772	SA1620WE	Modification of floor deck.	NW	73820	Sorm Industries 7999 Perimeter Road South Seattle, WA 98108
C-46A, -46F; T.C. A-772	SA1380WE	Installation of four 500-gallon fuel oil tanks in fuselage. Reissued 5/31/77.	AL	08488	Alaska International Air, Inc. P.O. Box 60029 Fairbanks, AK 99701
C-46/CW20-T; T.C. 2A5, 3A2, 772, 786, 789, 808	SA4-115	Aerofilter 30816A.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
C-46/CW20-T; T.C. 2A5	SA4-568	Engine mount core assemblies DE1468.	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
C-46/CW20-T, Super C-46/CW20-T; T.C. 2A5	SA88SO	B-400 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
Robin J-1, J-1 De Luxe; T.C. 220	SA4-1561	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
J-1; 12-W; C-46A, -D, -E, -R, 4000; B-4000; B9-, C-; D-, E-, K-, L-, W-; ATC 220, 407, 32, 146, 149, 188, 205, 112	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C-46A, -46D, -46E, -46R (Robin) J-1, J-1 Deluxe, (Travel Air) 12-W, 4000, B-4000, B9-4000, C-4000, D4000, E4000, K-4000, L-4000 (Parks), W-4000; T.C. 3A2, 220, 407, 32, 146, 2-381, 149, 2-84, 188, 205, 2-560, 112	SA2666WE	Ceconite 102 material covering of: C-46A, -46D, -46F, -46R - ailerons; 4677 J-1, J-1 Deluxe - wings; 12-W - entire airframe; 4000, B-4000, B9-4000, C-4000, D-4000, E-4000, K-4000, L-4000, W-4000 - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. Worth Street Los Angeles, CA 90063
Travel Air 4000; T.C. 32	SA4-557	Wing center-section fittings (front and rear).	WE	27310	Dudley H. Cunningham 539 B Street Yuba City, CA 95991
Travel Air 4000; A.T.C. 32	SA1008WE	Installation of poly fiber covering material of fuselage, rudder and elevators. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
Travel Air 4000 Series; T.C. 2-381, 2-84, 2-560, 32, 146, 149, 188, 205, 112	SA700WE	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Travel Air S-6000B; T.C. 130	SA209WE	Conversion of airplane for parachute jumping and aerial photography operations.	RM	46782	Johnson Flying Service, Inc. P.O. Box 1366 Municipal Airport Missoula, MT 59801
Robin C-1; ATC 143	SA3277WE	Installation of wood truss type wing ribs in place of original aluminum ribs. Issued 10/5/76.	WE	79780	Walter Lane Tufts 4138 Santa Rosa Drive Moorpark, CA 93021

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

DART AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G Series; T.C. 674	SA4-885	Ceconite 101 covering of wings, fuselage, horizontal and vertical stabilizer, rudder and elevator.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
G Series; T.C. 674	SA519WE	Wheel adapters on Goodyear wheels 3LMBM.	WE	49345	Robert P. Lamb 2998 Daisy Avenue Long Beach, CA 90801
G Series; T.C. 674	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G Series; T.C. 674	SA2666WE	Covering of Ceconite 102 material on wings, fuselage, horizontal and vertical stabilizers, rudder, and elevator. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
GK; T.C. 674	SA202GL	Installation of Ken Royce Model 7G engine. Issued 12/6/77.	GL	84618	Lloyd D. Washburn 3958 East Washburn Drive Port Clinton, OH 43452

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
DAVIS AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D-1-K; ATC 256	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
D-1-K; ATC 272	SA706WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
D-1-K; A.T.C. 256	SA2666WE	Complete aircraft covering of Ceconite 102 material. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
DEHAVILLAND AIRCRAFT

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH82A; T.C. A8EU	SA1008WE	Installation of poly-fiber covering material of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
DH82A; T.C. A8EU	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 6/6/74.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Tiger Moth N-82DS; T.C. A8EU	SA2666WE	Covering of Ceconite 102 material on wings, fuselage and empennage. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Beaver DHC-2; T.C. 806	SA3-105	L2C automatic pilot with altitude control and approach coupler. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
Beaver DHC-2; T.C. 806	SA3-591	C5500 main ski and AWB4820 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
Beaver DHC-2; T.C. 806	SA4-182	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
Beaver DHC-2; T.C. 806	SA4-322	Full-flow oil filter 1050-B-83 with element 1A0094.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
Beaver DHC-2; T.C. 806	SA37EA	Removal of left rear cabin door for parachute jumping operations.	NE	85240	Westover SAC Aero Club Westover AFB, MA 01022
Beaver DHC-2; T.C. 806	SA115WE	Pratt & Whitney R-985-APS4 installation converted under STC SE4-864.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
Beaver DHC-2; T.C. 806	SA245AL	Relocation of wing tip fuel control valve.	AL	44050	U.S. Department of Interior Bureau of Commerical Fisheries P.O. Box 6088 Anchorage, AK 99500
Beaver DHC-2; T.C. 806	SA263SO	Removal of power plant extinguisher system and installation of firewall patches.	SO	74928	State Airlines, Inc. Municipal Airport Charlotte, NC 28208
Beaver DHC-2; T.C. 806	SA284NW	Installation of 3 place center seat in aircraft using original civilian or USA military floor fittings. Amended 6/17/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA305NW	Installation of EDO 5250 floats and stabilizer fins. Issued 6/15/76.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA306NW	Installation of EDO 4665 floats. Issued 6/15/76.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA309NW	Installation of auxiliary vertical stabilizer fins. Issued 6/15/76.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA356NW	Installation of EAC-2D30-425/AG-100-4S propeller on Pratt & Whitney R-985 series engines. Issued 9/13/76.	NW	62120	Pacific Propeller P.O. Box 946 Kent, WA 98031
Beaver DHC-2; T.C. 806	SA397NW	Remove transport battery and battery box and install Gill 12-GCAB-9 or equal battery and battery box relocated to firewall per II K-8784. Issued 1/21/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA398NW	Install Hartzell HC-B3R30-4 propeller with R10152-5 1/2 blades, Hartzell C-4 propeller governor and Hartzell 836-32SR propeller spinner per II K-8785. Issued 1/24/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA415NW	Installation of EDO Model Wb-5030 floats. Issued 3/10/77.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Beaver DHC-2; T.C. 806	SA416NW	Installation of EDO Model 61-5870 floats. Issued 3/10/77.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-2; T.C. A-806	SA417NW	Installation of EDO Model Ya-6235 floats. Issued 3/10/77.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-2; T.C. A-806	SA523NW	Installation of float hatch covers on Edo 58-4580, 348-4580 or 679-4930 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2; T.C. A-806	SA524NW	Remove left or right rear cabin entrance door. Issued 10/12/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2; T.C. A-806	SA547AL	Modification of elevator and horizontal stabilizer tips. Issued 4/7/75.	AL	44050	U.S. Department of Interior Office of the Secretary Office of Aircraft Services 1936 Merrill Field Drive Anchorage, AK 99501
DHC-2; T.C. A-806	SA590NW	Installation of Hartzell HC-B3R30-1/R10152-5-1/2 propeller on P & W R-985 series engine. Amended 6/9/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA622WE	Fuel injected Pratt & Whitney R-985-AN-1, -2, -3, -4, -6, -6B, -8, -10, -12B, -14B, -14B1 or Wasp Jr. SB-3 engine.	WE	13750	Aviation Power Supply, Inc. 3011 Kenwood Street Burbank, CA 91503
DHC-2; T.C. A-806	SA646NW	Modification of mail landing gear axles. Issued 11/1/78.	NW	37175	General Aircraft Supply 7149 Perimeter Road, S. Seattle, WA 98108
DHC-2; T.C. A-806	SA660WE	Installation of HRD-type fire extinguishing system. Amended 7/11/77.	WE	43180	HTL Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
DHC-2; T.C. A-806	SA703NW	Installation of enlarged side windows for aft cabin. Issued 1/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2; T.C. A-806	SA736NW	Installation of Cleveland 40-46 wheels and 30-31 brakes. Issued 4/6/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Beaver DHC-2; T.C. 806	SA1744WE	Installation of various series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
Beaver DHC-2; T.C. 806	SA1829WE	Installation of EDO Model 679-4930 floats.	NW	46400	Jobmaster Company, Inc. 1005 W. Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
DHC-2, MK 1; T.C. A-806	SA107NW	Installation of EDO Model Yd-6470 floats. Reissued 10/22/74.	GL	71516	Shawano Flying Service 248 Airport Road Shawano, WI 54166
DHC-2, MK1; T.C. A-806	SA425NW	Installation of 75 lb. capacity baggage compartment below the existing baggage compartment. Issued 3/28/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK1; T.C. A-806	SA426NW	Enlarged baggage compartment. Issued 3/23/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DH-2, MK1; T.C. A-806	SA427NW	Cabin access steps attached to float struts. Issued 3/28/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK1; T.C. A-806	SA428NW	Water rudder steering system. Issued 3/28/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DHC-2, MK1; T.C. A-806	SA456NW	Installation of auxiliary seaplane stabilizer fins. Issued 6/2/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK 1; T.C. A-806	SA527AL	Removal of left rear door for parachute jumping. Issued 8/9/74.	AL	19906	A. Dean Carrell 7100 Lake Otis Parkway Anchorage, AK 99507
Beaver DHC-2, MK 1; T.C. 806	SA1913WE	Installation of EDO Model 679-4930 floats. Amended and reissued 8/27/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
DHC-2, MK 1; T.C. A-806	SA2520WE	Batch installation in Bristol amphibious floats. Issued 4/28/72.	NW	61626	North Country, Inc. 2525 14th Avenue South Seattle, WA 98168
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14(14V) or -28(28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA800EA	Installation of Aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W (red/white), or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
Otter DHC-3; T.C. 815	SA4-183	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
Otter DHC-3; T.C. 815	SA135NW	Installation of Sorm Industries bulk cargo tank. Issued 11/15/74.	NW	73820	Sorm Industries 7999 Perimeter Road Seattle, WA 98108
Otter DHC-3; T.C. 815	SA336NW	Installation of Hamilton Standard 23D40-311/6601A-7 propeller. Issued 8/18/76.	NW	40517	Harold J. Hansen 20602 - 135th Avenue South Seattle, WA 98148
DHC-3; T.C. A-815	SA678NW	Installation of Edo Model 56-7850A floats. Issued 10/17/78.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-6; T.C. A9EA	SA106NW	Installation of emergency exit on each side of fuselage. Amended 5/17/74.	EA	71910	S K Aircraft Company 16 Shotgun Lane Levittown, NY 11756
DHC-6; T.C. A9EA	SA235NW	Modification of cabin compartment airstair door. Issued 11/5/75.	NW	08360	Air Transport Industry Jet Air Hangar, Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA570NW	Installation of new interior interior panel. Issued 2/28/78.	NW	08360	Air Transport Industries Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA841EA	Installation of radome and support bracketry for RCA AVQ-45 antenna and radar units. Issued 9/10/70.	EA	35300	Field Aviation Company Limited Toronto International Airport Malton, Ontario, Canada
DHC-6 T.C. A9EA	SA1837WE	Installation of freon air conditioning system. Amended 8/25/77.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
DHC-6; T.C. A9EA	SA2366WE	Installation of emblem lights at mid span of horizontal stabilizer. Issued 7/2/71.	WE	30000	DeVore Aviation Service Corp. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DHC-6; T.C. A9EA	SA3816WE	Installation of underseat baggage restraint bar. Amended 3/2/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
DHC-6-100, -200, -300; T.C. A9EA	SA207GL	Install airborne fuel booster pump Model 1D2-14. Issued 1/10/78.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
DHC-6-100, -200, -300; T.C. A9EA	SA357AL	Installation of bulk fluid cargo tanks. Amended 5/15/72.	NW	78820	Sorm Industries 7999 Perimeter Road South Seattle, WA 98108
DHC-6-100, -200, -300; T.C. A9EA	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DHC-6 Series 100, 200; 300; T.C. A9EA	SA943EA	Replacement of deHavilland wing bleed air ducting with alternate ducting. Amended 3/12/73.	EA	29998	DeVore Aviation Service Corp. 125 Mineola Avenue Roslyn Heights, NY 11577
DHC-6-100, -200, -300; T.C. A9EA	SA998EA	Installation of engine fuel drain recirculation system. Amended 5/2/75.	EA	29998	DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
DHC-6 Series 100, 200; 300; T.C. A9EA	SA2516WE	Installation of lightning arrestors on wing tips and vertical fin. Issued 9/19/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6-100, -200, -300; T.C. A9EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
DHC-6 Series 100, 200, 300; T.C. A9EA	SA2608WE	Installation of equivalent modifications to deHavilland modifications. Issued 11/3/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2553WE	Installation of Adel cannister fuel pumps. Reissued 8/24/72.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2898WE	Installation of a fuel tank boost pump. Issued 6/14/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, S/N 130, 210, 231 and subsequent; T.C. A9EA	SA1117CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
DHC-6-200; T.C. A9EA	SA771EA	Installation of Dual Mark 15 Decca Systems.	EA	61542	New York Airways, Inc. P.O. Box 426 LaGuardia Airport Station Flushing, NY 11371
DHC-6-200; T.C. A9EA	SA3103WE	Removal of left-hand cargo doors to permit aircraft to engage in special operations, i.e. parachute jumping, aerial photography, etc. Issued 10/24/75.	WE	38250	Golden West Airlines, Inc. 5801 W. Imperial Highway Los Angeles, CA 90045
DHC-6-300; T.C. A9EA	SA130RM	Installation of dual-SELCAL system. Issued 1/28/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA132RM	Change in Airplane Flight Manual operating limitations to permit landings with air-operable jump-door open. Issued 2/15/78.	RM	07701	Department of the Air Force Hq., Aerospace Defense Command Peterson AFB, CO 80914
DHC-6-300; T.C. A9EA	SA135RM	Installation of Leach P/N V110-D-032-AC overvoltage relays. Issued 3/3/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA170NW	Installation of bulk fluid cargo tank for carriage on non-flamable, non-corrosive, non-toxic liquids. Issued 4/3/75.	WE	73820	Sorm Industries 7999 Perimeter Road Seattle, WA 98108
DHC-6-300; T.C. A9EA	SA185RM	Installation of Bendix RDR-160 weather radar system. Issued 10/26/79.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-7-100; T.C. A20EA	ST127RM	Supplemental oxygen system installation. Issued 2/2/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
DHC-7-100; T.C. A20EA	ST128RM	Installation of ground proximity warning system, Collins FPC-75. Issued 1/23/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
D.H. 104 Dove Series; T.C. 807	SA1-72	Three-place seat.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
D.H. 104 Dove Series; T.C. 807	SA1-73	39-gallon auxiliary fuel tank in cabin with 3-place seat per STC SA1-72.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
D.H. 104 Dove Series; T.C. 807	SA1-321	Airstair door.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D.H. 104 Dove Series; T.C. 807	SA3-61	Sonotone battery (nickle cadmium) 19-24M320.	GL	18450	Burroughs Corporation 6071 Second Avenue Detroit, MI 48233
D.H. 104 Dove Series; T.C. 807	SA3-321	L-5B autopilot and integrated flight equipment CIS-100. Amended 5/4/67.	EA	52535	LSI Service Corporation Harrisburg Division 6700 Allentown Boulevard Harrisburg, PA 17112
D.H. 104 Dove Series; T.C. 807	SA3-472	Stewart Warner 940B combustion heater in forward lower baggage compartment.	GL	77430	Tag Airlines Div. of Miller Oil Company City Airport Detroit, MI 48233
D.H. 104 Dove Series; T.C. 807	SA4-496	Radio panel overhead installation including engine starting switches and instrument lighting switches.	WE	73883	Southern California Aircraft Corp. International Airport Ontario, CA 91761
D.H. 104 Dove Series; T.C. 807	SA4-1361	Ceconite 101 covering of fabric-covered surfaces.	WE	26240	Cooper Engineering Corporation P.O. Box 3428 Van Nuys, CA 91408
D.H. 104 Dove Series; T.C. 807	SA120SO	Instrument panel. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA121SO	Electrical circuit breaker panel and related electrical bus bars. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA122SO	Seats to accommodate 11 passengers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA165SO	Six single-place seats and one two-place couch. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA167SO	Electrically heated windshield left-hand side. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA168SO	Hartzell HC-A3VK-2/V8433-4R propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA170SO	Auxiliary fuel system and bladder type tanks in leading edges of the wings. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA171SO	B.F. Goodrich deicers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA303SO	Wing leading edge clean-up. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA319SO	A or B of turbocharged Lycoming IO-720-A1A engines and Hartzell propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
104 Series; T.C. A-807	SA399CE	Hoskins Supp. position light system, includes Model B (dual) wing tip light Model C, D, or K tail light with or without Model 2 fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
104 Series; T.C. A-807	SA620SO	Installation of Airstair door. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
104 Series; T.C. A-807	SA676SW	AK219 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
104 Series; T.C. A-807	SA1554WE	Installation of two AiResearch TPE331 series engines and increase in fuselage length.	WE	19150	C-Air, Inc. 3521 E. Spring Street Long Beach, CA 90806
DH-104 Series 1A, 2A, 5A, 6A; T.C. 807	SA164SO	Installation of swept vertical tail, wing tips and elevator (STC SA303SO is prerequisite to this STC); installation of Lycoming IO-720-A1A engines (STC SE163SO) and Hartzell HC-A3VK-2/V8433-4R propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH-104 Series 1A, 2A, 5A, 6A; T.C. 807	SA135SW	Fuselage nose-mounted radome and structure.	SW	81300	C.R. Ursell 109 Briarcliff Drive San Antonio, TX 78205
DH-104-1A thru 8AXC; T.C. 807	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
D.H. 104, 1A, 2A, 5A, 5BA, 6A, 6BA, 7A, 8A; T.C. 807	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C.H. 104 Dove Series 1A, 2A, 5A, 5BA, 6A, 6BA, 7A, 8A; T.C. 807	SA2666WE	Ceconite 102 material covering of control surfaces. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA1747WE	Installation of two AiResearch TPE 331 series engines, increase in fuselage length and related changes. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA1815WE	Installation of cabin interior. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA1924SW	Structural modification of horizontal tail. Issued 10/23/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. Box 575 Addison, TX 75001
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA2438WE	Installation of spar reinforcing steel straps, on aircraft previously modified per STC SA1747WE. Reissued 5/23/73.	WE	25940	Consulting Aerospace Engineers 1845 Empire Burbank, CA 91504
D.H. 104 Dove Series 7AXC, 8AXC; T.C. A-807	SA2005WE	Installation of cabin air conditioning. This installation approved only on aircraft modified per STC SA1747WE. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. 104 Dove Series 7AXC, 8AXC; T.C. A-807	SA2019WE	Installation of cabin heating system. This installation approved only on aircraft modified per STC SA1747WE. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. 104 Dove Series; D.H. 114 Heron Series; T.C. 807, 816	SA249SW	Airstair door.	SW	68768	North American Rockwell Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
114 Heron Series; T.C. 816	SA629SO	Installation of Hartzell propellers HC-A3VK-2/V8433-7 equipped with Goodyear deicing equipment. Reissued 7/29/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
114 Heron Series; T.C. 816	SA633SO	Installation of electrically heated windshield.	SW	68150	Riley International Corporation 6211 W. Northwest Highway Dallas, TX 75225
D.H. 114 Heron; T.C. 816	SA816WE	Hartzell HC-A3X21-2L/L7636D propellers.	WE	70298	Charles Schachle 3901 E. Spring Street Long Beach, CA 90801
D.H. 114 Heron; T.C. 816	SA1228WE	Ceconite 101 covering of flaps and control surfaces.	WE	26248	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
D.H. 114 Heron; T.C. 816	SA1323WE	Fabric on ailerons, elevators, flaps and rudder with "pop" rivets.	WE	06755	Aircraft Technical Service, Inc. 16300 Stagg Street Van Nuys, CA 91406
D.H. 114 Heron; T.C. 816	SA1535WE	Installation of combustion cabin heater.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
D.H. 114 Heron; T.C. 816	SA2805WE	Nickel Cadmium battery installation. Issued 1/25/74.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst AVenue Van Nuys, CA 91406
D.H. 114 Heron; T.C. 816	SA2806WE	Installation of additional emergency exits. Issued 1/25/74.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D.H. 114 Heron Series 2A; T.C. A-816	SA740EA	Installation substitution of Lycoming engine IO-540-K1C5 in place of Lycoming Model IO-540-G1A4.	GL	87800	Wright Airlines, Inc. 2649 Broadway Cleveland, OH 44115
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST744SO	Installation of smoke detection system for forward and aft holds. Issued 12/13/74.	SO	65333	Puerto Rican Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST745SO	Installation of windshield wiper for co-pilot's (R.H.) position. Issued 12/13/74.	SO	65333	Puerto Rico Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA757SO	Installation of emergency exit RH fuselage at F.S. 49-76, and permanent closure of three existing overhead exits. Issued 3/4/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST758SO	Metal covering of wing flaps. Issued 5/3/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA919SO	Airplane life extension. Amended 6/20/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Heron Series 2A, 2DA, 2X; T.C. A-816	ST957SO	Installation of Teledyne battery Model BB638/T-C replacing two Rebat R-35 batteries. Issued 9/22/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST965SO	Modification of cockpit direct vision window. Issued 12/7/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, -2DA, -2X; T.C. A-816	SA1089SO	Installation of shoulder harness for crew seats. Issued 7/19/75.	SO	65333	Puerto Rico Int'l Airlines, Inc. c/o Caribbean Aircraft Develop., Inc. Building 408-Opa Locka Airport Opa Locka, FL 33054
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1368WE	Installation of Lycoming IO-540 series engines. Amended 10/31/72.	SW	68150	Riley International Corporation P.O. Box 5247 Waco, TX 76708
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1545WE	Installation of cabin interior arrangement, air conditioning equipment, electrically operated air compressors. Amended 6/25/68.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1685WE	Installation of four Continental IO-520-E engines. Amended 8/22/68.	SO	65333	Puerto Rico Int'l Airlines, Inc. P.O. Box 1498 Bayamon, PR 00619
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1710WE	Installation of stair door.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1729WE	Installation of over wing emergency exits and rear windows. Amended 12/4/69.	SO	65333	Puerto Rico Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1826WE	Installation of 22 occupant interior.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA2067WE	Installation of Janitrol 8-200 cabin heater. Reissued 7/29/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA3125WE	Installation of lower wing skin straps, lower spar doubler straps and engine mount pickup strap doublers. Amended 4/1/76.	WE	86680	Winters Aircraft Engineering Co. 17100 Ventura Boulevard Encino, CA 91316
DH-114, 2X; T.C. 816	SA1371WE	Interior installation.	WE	06755	Aircraft Technical Service, Inc. 16300 Stagg Street Van Nuys, CA 91406
DH-114, 2X; T.C. 816	SA1534WE	Installation of engine fire detection and extinguishment systems.	WE	06755	Aircraft Technical Service, Inc. 7150 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114, 2X; T.C. 816	SA1544WE	Cockpit modification and generator control.	WE	06755	Aircraft Technical Service, Inc. 7150 Hayvenhurst Avenue Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

DORNIER-WERKE G.M.B.H.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DO-28; T.C. 7A13	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/12/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
DO-28A-1; T.C. 7A13	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
DO-28A-1; T.C. 7A13	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
DO-28D; T.C. A16EU	SA686EA	Installtation of a Dual Collins 860E-2 DME.	EA	18750	Butler Aviation Friendship, Inc. Friendship International Airport Baltimore, MD 21240
DO-28D-1; T.C. A16EU	SA656EA	Cabin and cockpit interior installation including seating for eleven passengers. Amended 9/30/71.	EA	18750	Butler Aviation Friendship, Inc. Friendship International Airport Baltimore, MD 21240

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

DOUGLAS AIRCRAFT COMPANY, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A-24B; A-26B, -C; L.T.C. 4, 3	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A-24B, SBD-5, A-26B, A-26C; L.T.C. 4, 3	SA2666WE	Ceconite 102 material covering of: A-24B, SBD-5 - fabric surfaces; A-26B, A-26C - ailerons, rudder and elevators. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A-24B, SBD-5; L.T.C. 4	SA4-1431	Ceconite 101 covering of fabric surfaces.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
A-26; B23; T.C. L-33, 2-576	SA1744WE	Installation of various series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
A-26B, A-26C; L.T.C. 3	SA3-534	Sperry 615150 engine analyzer.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-536	Deletion of carburetor air filter, closing of air filter door and installation of crankcase breather.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-538	95-gallon outboard wing fuel tanks in each wing.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-539	Oil tank modification.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-541	Oil cooler door position transmitter.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-542	Cockpit and cabin oxygen system (Only applicable to aircraft previously modified per STC SA4-1227.)	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-543	Forward Janitrol S-50 heater and ventilation system. (Only applicable to aircraft modified per STC SA4-1227.)	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-544	Functional cockpit assemblies.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-545	Grimes G8400A-8-24 rotating beacon (bottom fuselage).	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-546	Aft cockpit and cabin Janitrol S-50 heater and ventilating system.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-547	Eclipse Pioneer 6300 fuel flow meter.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-548	Rear deck seat mount for two passenger seats.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A-26B, A-26C; L.T.C. 3	SA3-549	Navigation light modification.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-588	Fenwal fire detection system.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA3-609	Modification of canopy.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA4-294	Nose gear steering system.	SO	78390	Tempo Design Corporation P.O. Box 456 Miami, FL 33148
A-26B, A-26C; L.T.C. 3	SA4-385	103-inch plastic and metal nose.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
A-26B, A-26C; L.T.C. 3	SA4-386	Jato installation in nacelles.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
A-26B, A-26C; L.T.C. 3	SA4-474	Collins AP101 automatic pilot system.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
A-26B, A-26C; L.T.C. 3	SA4-606	Air conditioner.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
A-26B, A-26C; L.T.C. 3	SA4-631	Eonite covering on ailerons, elevators, rudder and trim tabs.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
A-26B, A-26C; L.T.C. 3	SA4-788	Ceconite 101 covering of ailerons, elevators, and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
A-26B, A-26C; L.T.C. 3	SA4-1113	Installation of dual controls. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton Hamilton Aviation P.O. Box 11746 Tucson, AZ 85734
A-26B, A-26C; L.T.C. 3	SA4-1219	Fuselage pressurization, higher horsepower engines and nose wheel steering modification and autopilot installation.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
A-26B, A-26C; L.T.C. 3	SA4-1227	Fuselage modification.	CE	68750	Rock Island Oil & Refining Company, Inc. 321 West Douglas Wichita, KS 67202
A-26B, A-26C; L.T.C. 3	SA4-1577	Structural modification to enlarge fuselage.	WE	16291	F.R. Berry 903 Barrington Los Angeles, CA 90052
A-26B, A-26C; L.T.C. 3	SA73WE	Auxiliary power unit relocated to left nacelle.	WE	39877	Hamilton Aircraft Company, Inc. 6501 S. Park Avenue Tucson, AZ 85706
A-26B, A-26C; L.T.C. 3	SA261SW	Fabrication of new left and right axle assembly for landing gear struts.	SW	62295	Pan American Petroleum Company P.O. Box 591 Tulsa, OK 74101
A-26B, A-26C; L.T.C. 3	SA316CE	Airstair door and close bomb bay, nose compartment door latches, rear spar carry-through structure in cabin.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA367WE	Full flow lube oil filter J0816A with element 1A0097.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
A-26B, A-26C; L.T.C. 3	SA396CE	Goodyear brakes and wheels.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA458CE	Elevator down spring.	CE	56500	Matador Pipelines, Inc. Aircraft Division 1128 Airport Road Municipal Airport Hutchinson, KS 67501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A-26B, A-26C; L.T.C. 3	SA578WE	Cargo door in lower aft fuselage.	WE	44106	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238
A-26B, A-26C; L.T.C. 3	SA692WE	Modification consists of spar reinforcements.	WE	61070	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
A-26B, A-26C; L.T.C. 3	SA743WE	Sperry SP-40 autopilot and HZ4-R4A integrated flight system.	WE	44106	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238
A-26B, A-26C; L.T.C. 3	SA926WE	Spar reinforcements.	WE	06755	Aircraft Technical Service, Inc. 16021 Arminta Street Van Nuys, CA 91406
A-26B, A-26C; L.T.C. 3	SA1107WE	Wing spar reinforcements.	CE	68750	Rock Island Oil & Refining Company, Inc. 1128 Airport Road Hutchinson, KS 67501
A-26B, A-26C; L.T.C. 3	SA1552WE	Installation of stack assembly exhaust.	WE	61070	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
A-26C; T.C. L-3-3	SA873EA	Installation of General Precision GPK1000 doppler system and Collins 618T-3 H.F. communication system. Issued 4/28/71.	EA	39545	Grumman Ecosystems Corporation Bethpage, L.I., NY 11714
B-26, -26C, TB-26B, -26C; T.C. LTC3	SA44RM	Increase in gross weight. Issued 2/5/75.	RM	52600	Lynch Flying Service, Inc. Billings Logan Int'l Airport Billings, MT 59101
B-26B, -26C, TB-26B, -26C; T.C. LT3-3	ST129RM	Installation of Goodyear brakes, P/N 9530757, and wheels P/N 9540484. Issued 1/27/78.	RM	52600	Lynch Air Tankers, Inc. Billings Logan Int'l Airport Billings, MT 59101
B26C; T.C. LTC 3	SA28RM	Installation of stall fence and wing leading edge cuffs. Issued 5/31/74.	RM	52600	Lynch Air Tankers, Inc. Billings Logan Int'l Airport Billings, MT 59101
B-26B, -26C, TB-26B, -26C; T.C. LTC3	SA43RM	Installation of stall fence and wing leading edge cuffs. Issued 2/5/75.	RM	52600	Lynch Flying Service, Inc. Billings Logan Int'l Airport Billings, MT 59101
B18 Series; T.C. 2-577	SA4-8	Wright R1820-87 and -60 engines and Hamilton Standard 6353A-18 propellers and modification fuel system and exhaust system.	WE	74921	Standard Airways Lindbergh Field
B18 Series; T.C. 2-577	SA4-37	Cargo floors installation and modification of flap and flight controls.	NW	79311	Transocean Air Lines Northwest Division P.O. Box 29, Boeing Field Seattle, WA 98101
B18 Series; T.C. 2-577	SA4-214	Two Stewart-Warner 940-B heaters.	NW	79311	Transocean Air Lines Northwest Division P.O. Box 29, Boeing Field Seattle, WA 98101
B-23; T.C. 2-576	SA1-46	Fiberglas fuselage-to-wing fillet installation and fuel tank vent lines relocated.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
B-23; T.C. 2-576	SA1-75	1004-X radome assembly on aircraft using Bendix radar units.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
B-23; T.C. 2-576	SA1-130	Relocation of pitot and static source on aircraft with radome assembly.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
B-23; T.C. 2-576	SA1-175	Nose radio rack with nose extension per STC SA1-75.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
B-23; T.C. 2-576	SA1-180	Floor lowered between stations 283 and 476 (6" at station 283, 0" at station 473).	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
B-23; T.C. 2-576	SA1-188	Bendix red bank 30 E 20-11A generator with Curtiss-Wright 424010 gearing adapter on aircraft equipped with Wright R-2600 series engines.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
B-23; T.C. 2-576	SA4-202	Full flow oil filter 30610A with element CP-1558-OC.	WE	88625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B-23, UC-67; T.C. 2-576	SA4-529	Short engine exhaust stacks and modified nacelle and exhaust shroud on aircraft equipped with Wright R-2600-29 engines.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
DC-2; T.C. 540	SA4-31	Wright R1820-52 engines and Hamilton Standard 33D50/6511-9 propellers.	WE	57918	D.W. Mercer d/b/a Mercer Enterprises Lockheed Air Terminal Burbank, CA 91505

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

EAGLE BALLOONS, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Challenger; T.C. A13SO	SL329GL	Installation of Rego quick acting spring loaded valve, P/N 7553S, in lieu of Rego valve, P/N 2553, using original installation hardware and components. Issued 7/18/79.	GL	35360	Finn-Bilt, Ltd. 11602 Brier Hill Road Huntley, IL 60142

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

EIRIAVION OY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PIK-20, PIK-20B; T.C. G31EU	SG13WE	Installation of aircraft indicator, altimeter and compass. Issued 10/27/76.	WE	64560	PIK PACIFIC, Mike Adams 4935 West 121st Street Hawthorne, CA 90250

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
EMAIR, EMBROTH COMPANY (dba EMAIR)

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
(Murrayair) MA-1; T.C. A6PC	SA839SO	Installation of Hamilton Standard Model 12D40/6101A-10S propeller approved under STC SP830SO on Pratt & Whitney R1340-AN-1 on S3H1 engines. Issued 5/13/75.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ENSTROM HELICOPTER CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F-28A; T.C. H1CE	SH1074SO	Installation of an electric rotor engage system with engage and disengage indicators. Issued 9/6/79.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
F28C, 280C; T.C. H1CE	SA492NW	Installation of external load racks. Issued 11/14/77.	NW	60300	Dean H. Moyer Route 2, Box 156 Yamhill, OR 97148
F-28C, 280C; T.C. H1CE	SH1461CE	Installation of Nite Sign Model H47B-1 electronic aireal billboard. Issued 12/1/78.	CE	61580	Nite Sign Manufacturing, Inc. 3847 French Court St. Louis, MO 63116

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

EVANGEL MISSION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
4500-300, 4500-300 Series II; T.C. A17CE	SA2657WE	Installation of turbosupercharged Lycoming IO-540-K1B5 engines. Issued 3/8/73.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

FAIRCHILD INDUSTRIES, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
22C7D, 24C8, 24C8A, 24C8B, 24C8C, 24C8CS, 24C8D, 24C8DS, 24C8E, 24C8ES, 24C8F, 24C8FS, 24G, 24GS, 24H, 24HS, 24J, 24JS, 24K, 24KS, 24R-9, 24R-9S, 24R-40, 24R-40S, 24R-46, 24R-46S, 24W-9, 24W-9S, 24W-40, 24W-40S, 24W-41, 24W-41S, 24W-41A, 24W-41AS, 24W-46S, 24W-16; T.C. 503, 475, 497, 498, 535, 576, 600, 610, 633, 632, 663, 667, 706, 707, 503	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
22C7G, 24J, 24JS, 24R-9, 24R-40, -40S, 24R-46, -46A, -46S, M62A, M-62A-3, -4, M-62B, -62C, KR-21, F-45, C-82, KR-31; ATC 564, T.C. 663, 706, 724, 215, 603, AR-15, ATC-19	SA2666WE	Ceconite 102 material covering of: 22C7G - fuselage; 24J, 24JS, 24R-9, -40, -40S, -46, -46A, -46S - wings; M-62A, -62B, -62C - fuselage, ailerons, elevators and rudder; KR-21, KR-31 - complete aircraft; F-45 - rudder, elevators and ailerons; C-82 - control surfaces. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C-119C; T.C. A21WE	SA2915WE	Installation of a 2400 gallon fire retardant tank assembly. Issued 7/19/74.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
C-119C; T.C. A21WE	SA2996WE	Installation of a 2400 gallon fire retardant tank assembly. Issued 1/14/75.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
C-119C; T.C. A21WE	SA2997WE	Installation of a 2400 gallon fire retardant tank assembly. Issued 1/14/75.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
C-119C, C-119G; T.C. A21WE	SA20RM	Install Westinghouse J-34-WE36 jet engines on top of center line of fuselage. Issued 11/23/73.	RM	41360	Hawkins & Powers Aviation, Inc. P.O. Box 391 Greybull, WY 82426
C-119C, C-119G; T.C. A21WE	SA74RM	Modification of floor and bottom fuselage for water and chemical tank installation. Issued 5/21/76.	RM	41360	Hawkins & Powers Aviation, Inc. P.O. Box 391 Greybull, WY 82426
C-119G; T.C. A21WE	SA46RM	Operation with cargo door removed. Issued 2/26/75.	RM	41360	Hawkins & Powers Aviation, Inc. Box 391 Greybull, WY 82426
C-119G; T.C. A21WE	SA49RM	Operation with cargo door removed. Issued 2/28/75.	RM	41360	Hawkins & Powers Aviation, Inc. Box 391 Greybull, WI 82426
C-119G-3E; T.C. A24WE	SA48RM	Operation with cargo door removed. Issued 2/27/75.	RM	41360	Hawkins & Powers Aviation, Inc. Box 391 Greybull, WY 82426
C-82A; T.C. AR-15	SA20SO	Cargo compartment floor modification for special cargo.	SO	58690	Miami Aircraft Maintenance, Inc. P.O. Box 48-1273 Miami, FL 33101
C-82A; T.C. AR-15	SA22SO	Four Aerojet General rocket engines 15KS100A1 and static pressure source.	SO	58690	Miami Aircraft Maintenance, Inc. P.O. Box 48-1273 Miami, FL 33101
KR-21; A.T.C. 215	SA946WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
22, C7G; T.C. 564	SA783WE	Ceconite 101 covering of fuselage.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

FAIRCHILD INDUSTRIES, INC. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
22 C7G; 24J, 24JS; 24R-9, -40, -40S, -46, -46A; M-62A, -3, -4, M-62B, -C, 23-AE, -HO, -SL, -23A, -SL; KR-21; C-82 Jet Packet; KR-31; A.T.C. 564, T.C. 663, 706, 724, 603, AR-15, A.T.C. 19	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
24C8E, 24C83S; 24R Series; T.C. 600, 706	SA1008WE	Poly-Fiber covering of left and right elevators and top of horizontal stabilizer. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92519
24G, 24GS, 24W-46, M-62 Series; T.C. 633, 707, 724	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
24G, -GS; PT-19, -23, -26, M-62; 24W-46; A.T.C. 633, T.C. 724, 707	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
24J, 24JS, 24R Series; T.C. 663, 706	SA4-860	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
24R Series, 24W Series; T.C. 706, 707	SA4-863	Eonite covering of complete airplane.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
24R Series, 24W Series; T.C. 706, 707	SA4-985	Fiberglass covering on wings, ailerons, and fuselage.	WE	38060	Glasco-Air Products 1125 First Street San Fernando, CA 91340
24R46A; M62A-3, -4 (Army PT-26); T.C. A-706, A-724	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-7 and HA-6 series carburetors. Amended 11/20/75.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
24R46A; M62A-3, -4; T.C. A-706, A-724	SA489EA	Installation of A.R.P. Industries, 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 10/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
24W; T.C. 707	SA4-42	Engine mount for Jacobs R-755 engine.	WE	71000	Serv-Aero Engineering, Inc. P.O. Box 96 Dos Palos, CA 93620
24W; T.C. 707	SA4-45	Engine mount for Continental W670 engine.	WE	71000	Serv-Aero Engineering, Inc. P.O. Box 96 Dos Palos, CA 93620
F-27 Series; T.C. 7A1	SA1-429	Outer wing structure modification to provide additional fuel.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
F-27 Series; T.C. 7A1	SA1-574	Nose wheel steering actuator assembly. Amended 8/16/66.	EA	48000	Walter Kidde & Company, Inc. 675 Main Street Belleville, NJ 07109
F-27 Series; T.C. 7A1	SA3-610	F-542-L flight recorder.	WE	80700	United Data Control, Inc. 380 N. Halstead Street Pasadena, CA 91101
F-27 Series; T.C. 7A1	SA3-682	Three-place divan.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA3-683	Hardman 3045 swivel chair.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA3-684	Double stationary chair.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F-27 Series; T.C. 7A1	SA3-685	Burns 2DH1EM-2 swiver chair track.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA3-687	SP-20 amplifier.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA4-947	Floor structure for installation of seats and divans.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA4-1027	Aircraft interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA4-1209	Cabin air-conditioning modification and addition of inflight cabin air recirculation.	NW	85122	West Coast Airlines, Inc. Georgetown Station Seattle, WA 98108
F-27 Series; T.C. 7A1	SA4-1453	Cabin air-conditioning system modification.	WE	16892	Bonanza Air Lines P.O. Box 391 Las Vegas, NV 89114
F-27 Series; T.C. 7A1	SA4-1543	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA43SW	Collins 137Y-1 doppler antenna and 621C-1 transmitter-receiver.	SW	12250	Associated Radio Service Company 7515 Lemmon Dallas, TX 75220
F-27 Series; T.C. 7A1	SA54SW	Interior installation. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA56SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA119SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA120SW	Autopilot AP-101E with flight director computer 562A-6 or 562A-4A.	CE	24250	Collins Radio Company 855 35 Street, NE Cedar Rapids, IA 52401
F-27 Series; T.C. 7A1	SA142EA	Rewire nose gear steering system.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27 Series; T.C. 7A1	SA153WE	Nacelle tail cone of 2024T3 material.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
F-27 Series; T.C. 7A1	SA190SW	Automatic pilot AP-103.	CE	24250	Collins Radio Company 855 35 Street, NE Cedar Rapids, IA 52401
F-27 Series; T.C. 7A1	SA225CE	Independent military pneumatic system and compressor.	CE	62030	Ozark Air Lines, Inc. Box 6007, Lambert Field St. Louis, MO 63145
F-27 Series; T.C. 7A1	SA245SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA282SO	Replacement parts manufactured for Fairchild P/Ns 27-727930-3 and -7.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27 Series; T.C. 7A1	SA288CE	Aural speed warning system.	CE	62030	Ozark Air Lines, Inc. Box 6007, Lambert Field St. Louis, MO 63145
F-27 Series; T.C. 7A1	SA306SW	Aft cabin window. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA323SO	Solid state voltage regulator.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102

FAIRCHILD INDUSTRIES, INC. 4

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F-27 Series; T.C. 7A1	SA330SO	New cockpit door with electric lock device.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27 Series; T.C. 7A1	SA342SO	Cockpit voice recorder.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27 Series; T.C. 7A1	SA441EA	Automatic flight control and flight director system.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
F-27 Series; T.C. 7A1	SA446WE	GPT30-54 turbine APU.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA468CE	United Data Control V-557 cockpit voice recorder.	CE	62030	Ozark Airlines, Inc. Box 6007, Lambert Field St. Louis, MO 63145
F-27 Series; T.C. 7A1	SA487SW	Rotating beacon. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA591SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA619WE	18-passenger interior and equipment, including an oxygen system, inverter, and antennas.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA622SW	United Data F-542 recorder.	SW	63750	Qualitron Aero, Inc. 4401 N. Main Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA631SW	Fairchild A-100 voice recorder system.	WE	62070	Pacific Air Lines San Francisco Int'l Airport San Francisco, CA 94119
F-27 Series; T.C. 7A1	SA632SW	United Data F-542 recorder.	SW	63750	Qualitron Aero, Inc. 4401 N. Main Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA729WE	High Density interior arrangement.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 391 McCarran Field Las Vegas, NV 89114
F-27 Series; T.C. 7A1	SA750WE	Overspeed warning system.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 391 McCarran Field Las Vegas, NV 89114
F-27 Series; T.C. 7A1	SA790WE	Replacement of carbon pile voltage regulator for 30-volt DC generator with Leland Airborne Products Type CSV-1105-1 solid state voltage regulator.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
F-27 Series; T.C. 7A1	SA853WE	Bendix 4B39 solid state voltage and frequency control modification to Jack & Heintz F-35-5 rotary inverter.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
F-27 Series; T.C. 7A1	SA968WE	Two windows in aft fuselage.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA969WE	Two radar altimeter antennas. (This is a structural installation only and does not include the operational evaluation of the antennas or system.)	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA970WE	Doppler antenna. (This is a structural installation only and does not include the operational evaluation of the antenna or system.)	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA985WE	Wing flap actuated landing gear aural warning system.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 391 McCarren Field Las Vegas, NV 89114

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F-27 Series; T.C. 7A1	SA1133WE	Flight data recorder 5424.	WE	34213	Fairchild Camera and Instrument Corporation 5921 E. Sheila Street Los Angeles, CA 90022
F-27 Series; T.C. 7A1	SA1188WE	Collins Radio Company cockpit voice recorder system.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 12405 Phoenix, AZ 85034
F-27 Series; T.C. 7A1	SA1225WE	Emergency lighting system.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 12405 Phoenix, AZ 85034
F-27 Series; T.C. 7A1	SA1314WE	Installation of either United Control Data Division #V-557 or Fairchild #A-100 cockpit voice recorder system.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
F-27 Series; T.C. 7A1	SA1333WE	Northern Aero Industries, Ltd. cyclic deicing switch.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
F-27 Series; T.C. 7A1	SA1406WE	Relocation of Fairchild flight data recorder.	WE	16892	Bonanza Air Lines, Inc. 3737 E. Bonanza Way P.O. Box 12405 Phoenix, AZ 85034
F-27 Series; T.C. 7A1	SA1496WE	Installation of fire detection aural warning system.	WE	62070	Pacific Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94119
F-27 Series; T.C. 7A1	SA1537SW	Installation of a galley. Issued 11/10/72.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1538SW	Installation of a bar. Issued 11/10/72.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1539SW	Bulkhead and desk. Issued 11/10/72.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1540SW	Lavatory. Issued 11/10/72.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1571WE	Relocation of Fairchild Model F-542 flight data recorder.	NW	85122	West Coast Airlines, Inc. 1219 Westlake North Seattle, WA 98108
F-27 Series; T.C. 7A1	SA1629SW	Change seat to rigid back and relocate legs to accommodate installation with plush side panels for headrest for aft facing. Issued 3/20/73.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1734SW	LEAR AVIA battery temperature sensor system. Issued 9/27/73.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA3096WE	Installation of Collins Radio Co. Model FPC-75 ground proximity warning system. Amended 4/6/76.	WE	43340	Hughes Air West P.O. Box 2966 Phoenix, AZ 85036
F-27, -27A, -27B, -27F, -27G; T.C. 7A1	SA253CE	Supplemental Model E high intensity wing tip lights, Model C tail light, with or without Model 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
F-27, -27A, -27B, -27F; T.C. 7A1	SA302WE	Incorporation of Napier Spraymat deicing (as manufactured by applicanat) externally on Rotol propeller spinner as alternate to Dowty Rotol internal elements. Reissued 10/22/70.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
F-27, -27A, -27B, -27F; T.C. 7A1	SA384SW	Installation of radio racks with associated changes. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
F-27, -27A, -27B, -27F; T.C. 7A1	SA386SW	To fabricate wiring harness and make complete radio installation. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

FAIRCHILD INDUSTRIES, INC. 6

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F-27, -27A, -27F, -27J; T.C. 7A1	SA578SW	Fabrication and installation of rack for radar in nose wheel area. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
F27, F27A, -B, -F, -G, -J, FJ227; T.C. 7A1	SA392CE	Install Hoskins Twin Mk V supplementary lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
F-27, F-27A, F-27B, F-27F, F-27G, F-27J, F-27M; T.C. 7A1	SA1463CE	Installation of microwave landing system airborne equipment. Issued 12/12/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
F-27, -27A, -27B, -27F, -27G, -27J, -27M, FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2569WE	Installation of battery temperature monitor system. Amended 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
F-27, -27A, -27B, -27F, -27G, -27J, -27M, FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2916WE	Installation of emblem lights on tip of horizontal tail. Issued 8/6/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
F-27, F-27A, -27B, -27F, -27J; T.C. 7A1	SA364SW	Collins AP-103E autopilot on aircraft with gross weight up to and including 42,000 pounds. Reissued 1/18/78.	WE	78490	Tiger Air Service Center, Inc. 3000 N. Clybourn Avenue Burbank, CA 91505
F-27, FH-227; T.C. 7A1	SA2-889	McMillan radome 7141X. Amended 11/21/73.	SO	64500	Piedmont Aviation Smith-Reynolds Airport Winston-Salem, NC 27102
F-27, FH-227; T.C. 7A1	ST542SO	Installation of Tramm BTI 600 Nicad battery temperature indicating system. Amended 10/10/73.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27, FH-227; T.C. 7A1	SA1131CE	Replacement of Walter Kidde chemical air drier housing with Overland housing. Issued April 1975.	CE	62026	Overland Aviation Service Co. 10271 Bach Boulevard Overland, MO 63132
F-27, FH-227; T.C. 7A1	SA1144CE	Replacement of Walter Kidde Chemical air drier refillable cartridge P/N 891643 with Overland housing. Issued July 1975.	CE	62026	Overland Aviation Service Co. 10271 Bach Boulevard Overland, MO 63132
F-27, FH-227; T.C. 7A1	SA1458WE	Installation of rain repellent system.	WE	90405	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27A; T.C. 7A1	SA219AL	Installation of cockpit voice recorder. Reissued 2/12/74.	AL	85890	Wien Air Alaska, Inc. 4100 Int'l Airport Road Anchorage, AK 99502
F-27A, F-27B; T.C. 7A1	SA350AL	Installation of baggage restraint. Reissued 2/4/74.	AL	85890	Wien Air Alaska, Inc. 4100 Int'l Airport Road Anchorage, AK 99502
F-27A, F-27F, F-27J; T.C. 7A1	SA622SW	Relocation of United Data recorder Model F-542 to aft cabin area. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourne Avenue Burbank, CA 91505
F27A, F, G, J, FH-227; T.C. 7A1	SA1610SW	Installation of Safeway deicer overshoe P/N 5651 and/or Semsa lead P/N S.2002 in lieu of Dowty Rotol overshoe and/or leads on Dowty Rotol propeller model R193/4-30-5/50 with blades P/N R.A. 25907. Amended 12/7/73.	EA	70830	SEMSA, Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779
F-27F; T.C. 7A1	SA4EU	Installation of lateral freight net at fuselage station 600.394 forward of rear luggage compartment.	EU	43720	Industriemaatschappij AVIO-DIEPEN N.V. Vliegveld Iepenburg RIJSWIJK (Z-HOLLAND) THE NETHERLANDS
F-27F; T.C. 7A1	SA5EU	Installation of metal freight floor in forward cabin.	EU	43720	Industriemaatschappij AVIO-DIEPEN N.V. Vliegveld Iepenburg RIJSWIJK (Z-HOLLAND) THE NETHERLANDS
F-27F; T.C. 7A1	SA6EU	Installation of General Logistics tie down rails along LH and RH walls and forward extension of LH seat rails.	EU	43720	Industriemaatschappij AVIO-DIEPEN N.V. Vliegveld Iepenburg RIJSWIJK (Z-HOLLAND) THE NETHERLANDS

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F-27F; T.C. 7A1	SA2065WE	Installation of Bendix Model PB-60 flight control system.	EA	16010	The Bendix Corporation Teterboro, NJ 07608
F-27F, F-27G; T.C. 7A1	SA1179SW	Installation of Hartman vertical scale engine instruments. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourne Avenue Burbank, CA 91505
F-27J, -27M; T.C. 7A1	SA1030SW	Interior installation. Reissued 8/12/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
F-27J, -27M; T.C. 7A1	SA1031SW	Electronics system. Reissued 8/12/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
FH-227; T.C. 7A1	SA456EA	Interior. Amended 5/31/67.	EA	18750	Butler Aviation Friendship, Inc. Friendship Int'l Airport Baltimore, MD 21240
FH-227; T.C. 7A1	SA479EA	Manufacture and installation of buffet units.	EA	18750	Butler Aviation Friendship, Inc. Friendship Int'l Airport Baltimore, MD 21240
FH-227; T.C. 7A1	SA638CE	Installation of engine starter voltage control unit in starter system.	CE	62030	Ozark Airlines, Inc. P.O. Box 10007 Lambert Field St. Louis, MO 63145
FH-227; T.C. 7A1	SA685SW	Installation of provisions for SP-50F autopilot, includes wiring, cabling, brackets and racks only. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
FH-227; T.C. 7A1	SA705EA	Installation of Leland CSV1186-2 regulator on Jack & Heintz F45-10C inverter.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, L.I., NY 11735
FH-227; T.C. 7A1	SA739SW	Interior modification.	SW	42550	Horton & Horton Custom Works, Inc. Meacham Field Fort Worth, TX 76106
FH-227; T.C. 7A1	SA799EA	Installation of overvoltage and overfrequency protection for Lear Siegler Inverters Model F45-10.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA670SW	Electronic system. Reissued 9/12/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
FH-227, -227B, -227C; T.C. 7A1	SA748SW	Sperry SP-50F autopilot. Reissued 9/12/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
FH-227, FH-227B; T.C. 7A1	SA854SW	Attitude & directional gyro displays HF, VHF Communication, ADF and VHF Navigation Receivers; Weather Radar installation, and Audio System for crew and passengers. Reissued 5/20/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA902EA	Installation of Brownline cargo system. Issued 2/24/72.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA931SW	Interior modification in accordance with Horton & Horton Works, Inc., DL 5918 dated 18 June 1968. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2246WE	Installation of large cargo door. Amended 9/20/71.	EA	34249	Fairchild Hiller Corporation Fairchild Drive Germantown, MD 20767
FH-227, -227B, -227C, -227D, -227E;	SA2251WE	Installation of Fairchild cockpit voice recorder system and Sundstrand United Data Control flight recorder system. Amended 1/7/71.	EA	34249	Fairchild Hiller Corporation Fairchild Drive Germantown, MD 20767
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2363WE	Installation of interior arrangement. Reissued 6/3/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2954WE	Installation of convertible passenger-cargo cabin interior. Issued 10/21/74.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA735SW	Installation of Collins AP-103F automatic flight control system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA736SW	Electronics installation according to Collins DL 271-6224-000, or installation of United Data Control Model F-542 flight data recorder as an alternate for Fairchild 5424(502). Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
FH-227, -227B, -227D; T.C. 7A1	SA763SW	Complete electronics system including pilot's servo altimeter, antennas, flight data recorder, cockpit voice recorder. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
FH-227B; T.C. 7A1	SA971CE	Relocation and modification of existing hostess seat installation. Issued November 1973.	CE	62030	Ozark Airlines, Inc. Box 10007, Lambert Field St. Louis, MO 63145
FH-227B; T.C. 7A1	SA1059CE	New pilot and copilot seat belt - shoulder harness restraint system. Issued November 1974.	CE	62030	Ozark Airlines, Inc. Box 1007, Lambert Field St. Louis, MO 63145
FH-227B; T.C. 7A1	SA1946WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
FH-227B, -227C; T.C. 7A1	SA1176CE	Installation of Collins FPC-75 ground proximity warning system. Amended September 1976.	CE	62030	Ozark Air Lines, Inc. St. Louis International Airport Lambert Field St. Louis, MO 63145
FH-227B, -227C, -227D, -227E; T.C. 7A1	SA2945WE	Installation of convertible passenger-cargo cabin interior. Amended 10/29/74.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
FH-227C; T.C. 7A1	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 11/18/68.	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
FH-227C; T.C. 7A1	SA919EA	Installation of Collins AL 101 radio altimeter system. Reissued 12/23/75.	NE	08256	Air New England Logan International Airport East Boston, MA 02128
F-45; T.C. 603	SA306WE	Ceconite 101 covering of rudder, elevators and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
M-62 Series; T.C. 724	SA4-1082	Ceconite 101 covering of fuselage, ailerons, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
M-62 Series; T.C. 724	SA4-1362	Spraying and dusting modification.	WE	84834	Weatherly Aviation Company 2304 San Felipe Road Hollister, CA 95023
M-62 Series; T.C. 724	SH87WE	Installation of twin litters on left side of interior passenger compartment including supporting structure and movable center door post. Reissued 12/12/72.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
M-62 Series; T.C. 724	SH107WE	Installation of Nightsun SX-16C searchlight.	WE	74500	Spectrolab Div. of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
M-62 Series; T.C. 724	SH110WE	Installation of dual foldable/rigid internal litter on left side of passenger compartment. Reissued 10/8/74.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
M-62 Series; T.C. 724	SH111WE	Installation of step on either side or both sides of aircraft, attached to skid and torsion bar between Stations 60 and 100.	WE	03270	U.S.D.A. Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
M-62 Series; T.C. 724	SA180SW	Modification of aircraft to 1 PCLM Part 8 agricultural aircraft. Reissued 4/17/74.	SO	61796	Ernest Olsen Route 1 Rebecca, GA 31788
M-62 Series; T.C. 724	SA333SW	Part 8 agricultural aircraft modification. Reissued 4/17/74.	SO	61796	Ernest Olsen Route 1 Rebecca, GA 31788
M-62 Series; T.C. 724	SA612WE	Pratt & Whitney R-985-AN1 engine.	WE	84834	Weatherly Aviation Co., Inc. 2304 San Felipe Road Hollister, CA 95023

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M-62 Series; T.C. 724	SA648SW	Jacobs R755-9-B2M engine, propeller, revised aileron. Reissued 4/17/74.	SO	61796	Ernest Olsen Route 1 Rebecca, GA 31788
M-62 Series; T.C. 724	SA1008WE	Poly-Fiber covering of fuselage. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92519
FH-1100; T.C. H2WE	SH118WE	Installation of single, foldable emergency stretcher on left side of passenger compartment. Amended 10/7/70.	WE	65328	Progressive Aviation, Ltd. Reid - Hillview Airport San Jose, CA 95122
FH-1100; T.C. H2WE	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
FH-1100; T.C. H2WE	SH341AL	Installation of Airglas skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
FH-1100; T.C. H2WE	SH360AL	Installation of modified cargo racks.	AL	08486	Alaska Helicopters P.O. Box 6283, Airport Annex Anchorage, AK 99502
FH-1100; T.C. H2WE	SH367AL	Installation of Alaskan Sky-Craft Co. cargo baskets. Revised 5/20/70.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
FH-1100; T.C. H2WE	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/79.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
FH-1100; T.C. H2WE	SH646EA	Installation of provisions for radar antenna waveguide.	EA	34249	Fairchild Hiller Corporation Aircraft Division Hagerstown, MD 21740
FH-1100; T.C. H2WE	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
FH-1100; T.C. H2WE	SH975EA	Installation of Consolidated Instrument Co., Inc. B206-TA-180 and B206D-TA-180 temperature alert temperature monitoring. Issued 3/20/74.	EA	25920	Consolidated Instrument Co., Inc. Teterboro Airport Teterboro, NJ 07608
FH-1100; T.C. H2WE	SH1010SW	Sliding tinted glass window assembly for forward right and left cabin doors.	SW	54500	M & N Plastics, Inc. 300 S. Lake Street Fort Worth, TX 76104

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
FLEET AIRCRAFT, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
16B; T.C. 2-566	SA1008WE	Poly-Fiber covering of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
16B; T.C. 2-566	SA1242WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
16B; T.C. 2-566	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

FLUG-UND FAHRZEUGWERKE AG

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AS 202/15 "BRAVO"; T.C. A34EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
AS 202/15 "BRAVO"; T.C. A34EU	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

FOKKER - VFW B.V.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F27; T.C. A-817	SA302WE	Incorporation of Napier Spraymat de-icing (as manufactured by applicant) externally on Rotol propeller spinner as an alternate to Dowty Rotol internal elements. Reissued 10/22/70.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
F27 Mark 200, 400, 500, 600; T.C. 817	SA1610SW	Installation of Safeway de-icer overshoe P/N 5651 and/or Semsa lead P/N S.2002 in lieu of Dowty Rotol overshoes and/or leads on Dowty Rotol propeller model R193/4-30-4/50 with blades P/N R.C. 25907. Amended 12/7/73.	EA	70830	Semsa, Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779
F-28 Mark 1000; T.C. A20EU	SA2999WE	Installation of emblem lights on flap track fairings. Issued 1/27/75.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

FORD MOTOR COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
4-AT-E; T.C. 132	SA153CE	Removal of door on right side of fuselage.	CE	21430	Delbert Chaney Route 1 Eduora, KS 66025

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

FUJI HEAVY INDUSTRIES, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
FA-200-160, FA-200-180A0; T.C. A4PC	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
FA-200-160, FA-200-180A0; T.C. A4PC	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/75.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

HENRY S. GARCIA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A-2; T.C. 801	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
A-2; T.C. 801	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GATES LEARJET CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
23 Series; T.C. A5CE	SA148GL	Installation of radome kit 4088X. Issued 1/31/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
23 Series; T.C. A5CE	SA377AL	Installation of nose wheel guard. Issued 6/19/70.	AL	05958	Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
23 Series; T.C. A5CE	SA1019CE	Install lower cabin door designed to accommodate flare racks. Issued May 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1020CE	Install lower cabin door to accommodate aerial photography equipment. Issued May 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1098CE	Installation of drift (navigation) sight to be used in conjunction with aerial photography equipment. Issued February 1975.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1169CE	Stretcher installation in cabin area. Issued 10/21/75.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1171CE	Stretcher installation in baggage area. Issued 10/21/75.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
23 Series; T.C. A5CE	SA1299CE	Installation of provisions for infra-red scanning equipment. Amended July 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23 Series; T.C. A5CE	SA1321CE	Installation of dry ice dispenser. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23 Series; T.C. A5CE	SA1335CE	Installation of datum console rack. Issued 6/27/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23 Series; T.C. A5CE	SA1378CE	Install structural provisions on right hand side of airplane for removable camera door. Issued 10/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23 Series; T.C. A5CE	SA1381CE	Structural provisions for infra-red scanning equipment. Issued 10/26/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23; T.C. A5CE	SA1395CE	Install structural provision for Jelco infra-red scanner. Issued 1/5/78	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1396CE	Install lower cabin door designed to accept a carousel flare dispensing unit capable of being reloaded in flight. Issued 2/8/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1411CE	Install structural provision for a particle measuring probe. Issued 4/18/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1412CE	Install dry ice dispenser. Issued 4/19/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1548CE	Structural provision for NASA - Daedalus IR scanner. Issued 2/22/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204

GATES LEARJET CORP. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
23 Series; T.C. A5CE	SA2294WE	Modification of nose wheel steering system. Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
23 Series; T.C. A5CE	SA2992WE	Installation of logo lights on horizontal stabilizer lower surface. Amended 6/10/76.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
23, 24 Series; T.C. A5CE, A10CE	SA481CE	Modification of electrical system for compliance with AD 66-14-02.	GL	34020	Executive Jet Aviation, Inc. Port Columbus Int'l Airport Columbus, OH 43219
23, 24 Series; T.C. A5CE, A10CE	SA830SW	Heat static units.	SW	29232	Delta Aircraft P.O. Box 12182 San Antonio, TX 78205
23, 24, 24A, 24B, 24C, 24D, 25, 25B, 25C; T.C. A5CE, A10CE	SA21RM	Installation of cabin divider. Issued 12/5/73.	RM	25252	Combs Gates Denver, Inc. Hangar #7 Stapleton Int'l Airport Denver, CO 80207
23, 24, 24B, 24D, 25, 25B, 25C; T.C. A5CE, A10CE	SA412CE	Installation of Woodward Electronic Engine synchronizer system.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
23, 24, 24B, 24D, 25, 25B, 25C, 35, 36; T.C. A5CE, A10CE	SA871SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 25, 25A, 25B, 25C; 35, 36; T.C. A5CE, A10CE	SA996EA	Installation of Shaw Aero fuel filler cap P/N's 457-2, -266, 370, -431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A; T.C. A5CE, A10CE	SA2429WE	Installation of windshield rain repellent system. Issued 10/8/71.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
23, 24, 24A, 24B, 24C, 24B-A, 25, 25A; T.C. A5CE, A10CE	SA2447WE	Installation of Lear Ni-Cad safety unit. Reissued 10/24/72.	WE	49850	Lear Avia Corporation P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
23, 24, 25; T.C. A5CE, A10CE	SA175RM	Replacement of throttle knob, Model EP-004, for 20 series Learjet equipped with Dee Howard thrust reversers. Issued 6/18/79.	RM	45790	Jet Accessories, Inc. P.O. Box 38568 Stapleton Field Denver, CO 80238
23, 24, 25 Series; T.C. A5CE, A10CE	ST488SO	Installation of Butler National 6A VAC/10A ADD Area Navigation System with altitude alerting capabilities that meet requirements of FAR 91.51. Issued 1/28/72.	SO	73874	Southern Airways Company Hangar One Atlanta, GA 30320
23, 24, 25, 35, 36 Series; T.C. A5CE, A10CE	SA1033SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid batteries. Issued 11/21/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
24; T.C. A10CE	SA841NW	Performance improvement fairings to wing and nacelles. Issued 10/23/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road Seattle, WA 98108
24; A10CE	SA1065SO	Installation of support rack (incubator). Issued 4/18/79.	SO	64150	Personalized Interiors, Inc. 240 S.W. 34th Street Ft. Lauderdale, FL 33315
24 Series; T.C. A10CE	SA1874WE	Installation of Janco auxiliary cabin heater.	RM	37098	The Gates Rubber Company 8601 Montview Boulevard Denver, CO 80220
24 Series; T.C. A10CE	SA2329WE	Installation of Microcom, Inc. Lear AFC-70 autopilot (previous modification per STC SA2228WE - Microcom, Inc. nose wheel steering modification required). Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
24 Series; T.C. A10CE	SA2373WE	Installation of Microcom, Inc. Lear altitude alerter system, Microcom P/N 800074. Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
24, 24A, 24B; T.C. A10CE	SA1549CE	Installation of structural provisions for infra-red scanning equipment. Issued 2/26/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, B, BA, C, D, D-A, 25, 25A, B, C; T.C. A10CE	SA1RM	Installation of cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, D, E, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA14RM	Installation of Branson flight crew emergency exit. Amended 6/12/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, B, B-A, C, D, D-A, E, F, 25, 25A, B, BC, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA149GL	Installation of radome kit 4088X. Issued 1/31/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations Akron, OH 44309
24, 24A, 24B, 24C, 24D, 25, 25A, 25B, 25C; T.C. A10CE	SA960CE	Lower cabin door designed to accommodate four flare racks for cloud seeding. Issued February 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E, 24F, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA961CE	Installation of lower cabin door designed to accommodate aerial photography equipment. Amended 6/7/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E,, 25, 25A, 25B, 25C, 25D, 25F, 35, 36; T.C. A10CE	SA1091CE	Installation of drift (navigation) sight to be used in conjunction with aerial photography equipment. Amended 5/3/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A thru 24F, 25, 25A thru 25F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1170CE	Stretcher installation in cabin area. Amended 6/1/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A thru 24F, 25, 25A, B, D, F, 28, 35, 35A; T.C. A10CE	SA1172CE	Stretcher installation in baggage area. Amended 6/1/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E, 24F, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA1281CE	Lower cabin door designed to accommodate a flare rack capable of being reloaded in flight. Amended 6/22/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA1298CE	Installation of provisions for infra-red scanning equipment. Reissued July 1977.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
24, 24A thru 24D, 25, 25A thru 25F (S/N 25-229 or earlier), 35, 35A, 36, 36A; T.C. A10CE	SA1322CE	Installation of dry ice dispenser. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
24, 24A, B, C, D, 25, 25A, B,C, D, F; T.C. A10CE	SA1332CE	Install Litton digiprox ground proximity warning system (GPWS). Reissued 8/3/78.	WE	51500	Aero Products Division Litton Systems, Inc. 21050 Burbank Boulevard Woodland Hills, CA 91364
24, 24A, B, C, D, 25, 25A, B, C, D, 35, 35A, 36, 36A; T.C. A10CE	SA1336CE	Installation of datum console rack. Reissued 9/13/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1377CE	Install structural provisions on right hand side of airplane for removable camera door. Amended 6/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1382CE	Structural provisions for infra-red scanning equipment. Amended 6/4/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F; T.C. A10CE	SA1394CE	Install structural provision for Jelco infra-red scanner. Issued 1/5/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F; T.C. A10CE	SA1397CE	Install lower cabin door designed to accept a carousel flare dispensing unit capable of being reloaded in flight. Issued 2/8/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1410CE	Install structural provision for particle measuring probe. Amended 6/22/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1413CE	Installation of dry ice dispenser. Amended 6/4/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1477CE	Structural plug installation in right side of forward fuselage when camera door is removed. Issued 3/21/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA2876WE	Installation of vertical tail floodlights on the horizontal stabilizer. Amended 6/1/78.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3225WE	Installation of R.C.A. Primus 35 weather radar system. Issued 6/25/76.	WE	37095	Gates Learjet Modification & Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3226WE	Installation of Collins FD 112V flight director system. Issued 6/25/76.	WE	37095	Gates Learjet Modification & Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 24F; T.C. A10CE	SA3263WE	Installation of J.E.T. DAC 2000 RNAV system. Issued 11/29/76.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, 25, 25A, b, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3264WE	Installation of Global GNS-500A VLF navigation system. Reissued 3/3/78.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3326WE	Installation of Collins ALT-55 radio altimeter. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3327WE	Installation of Motorola Model NA135 Selcal system. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E,F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3328WE	Installation of flignt data recorder Sundstrand Model FA542. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3422WE	Installation of dual Collins MC-103 compass systems.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3426WE	Installation of R.C.A. Primus 400 weather radar system. Issued 6/29/77.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24C, 24D, 24D-1, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F; T.C. A10CE	SA3615WE	Installation of Collins NCS-31A area navigation system. Issued 4/7/78.	WE	37095	Gates Learjet-Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3647WE	Installation of dual Collins ALT-50 and ALT-55 radio altimeter system with comparator. Issued 6/5/78.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3677WE	Installation of Wulfsberg WT-200 communication transceiver system. Issued 8/31/78.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F; T.C. A10CE	SA3807WE	Installation of Jet Elec. & Tech. DAC-2000 R/NAV system with transfer switching for data from pilot to copilot panel. Issued 12/19/78.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA3735WE	Installation of optional single or dual H-field antenna (Global P/N 11455-1) for Global GNS-500A system. Amended 7/19/79.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3850WE	Installation of RCA Primus 300 color weather radar system. Issued 2/7/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3866WE	Installation of Wulfsberg Model AT-960 antenna. Issued 3/6/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29; T.C. A10CE	SA3899WE	Installation of Collins F1S-84 flight instrument system. Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3915WE	Installation of RCA Primus 400 check list (Data Nav I). Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA3975WE	Installation of Collins WXR-300 color radar. Issued 6/7/79.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4003WE	Installation of Bendix RDR-1200/ RDR-1300 color radar check list. Issued 7/26/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29; T.C. A10CE	SA4028WE	Installation of Sundstrand Mark II ground proximity warning system. Issued 9/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25B, D; T.C. A10CE	SA4054WE	Installation of SUNAIR ASB-850 high frequency radio communications system. Issued 1/16/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F; T.C. A10CE	SA4073WE	Installation of Sunair ASB-850 high frequency radio communication system. Issued 1/23/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24B; T.C. A10CE	ST485SO	Installation of Smiths Industries Type 3B series (WL/1101 AM/MS or 1103 AM/MS) servoed altimeter WL/ 504/CUF altitude alerting unit, and Smiths pressure error transducer (Type A108 for Model 24 and Type 104 for Model 24B). Issued 1/19/72.	SO	73075	Smiths Industries, Inc. St. Petersburg/Clearwater Airport St. Petersburg, FL 33732
24, 25; T.C. A10CE	SA117GL	Installation of cabin temperature control system. Issued 5/17/76.	GL	31640	Ned Wilkins Eaton Corp. Flight Operations Cuyahoga County Airport 355 Richmond Road Cleveland, OH 44143
24, 25; T.C. A10CE	SA891CE	Relocate optical window port. Amended May 1976.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 25; T.C. A10CE	SA1635WE	Modification of lower half of passenger entry door to accommodate camera installation. Amended 8/29/75.	WE	43450	Mark Hurd Aerial Surveys, Inc. Box 488 Goleta, CA 93017

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
24, 25; T.C. A10CE	SA1746SW	Model 7107 battery fault warning system. Issued 10/19/73.	SW	66500	Ray Electronics Company 107 Braniff Drive San Antonio, TX 78216
24, 25; T.C. A10CE	SA2228WE	Modification of nose wheel steering. Amended 5/12/75.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
24, 25, 35, 36 Series; T.C. A10CE	SA2788SW	Tail-stringer antenna housing. Issued 6/5/78.	SW	74965	Sted-Mac Co. Box 6123 A.T.S. Midland, TX 79701
24A as certified under STC SA7RM, 25, 25A, 25B modified per STC SA14RM; T.C. A10CE	SA9RM	Installation of cabin cargo retention nets. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24A as certified under STC SA7RM, 25, 25A, 25B modified per STC SA14RM; T.C. A10CE	SA10RM	Installation of cabin cargo liner. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24B, 24D; T.C. A10CE	SA136GL	Install Intercontinental Dynamics Corp.'s altimeter P/N 16007-703 or P/N 16007-803 in aircraft equipped with IDC altitude alerter. Issued 10/1/76.	GL	34020	Executive Jet Sales, Inc. Port Columbus Int'l Airport Columbus, OH 43219
24B, 24D, 25, 25B, 25C; T.C. A10CE	SA2675WE	Installation of sound suppressors. Reissued 11/12/75.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
24D; T.C. A10CE	SA31RM	Structural provisions for cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24D; T.C. A10CE	SA33RM	Quick change cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24D; T.C. A10CE	SA232NW	Installation of Mark II performance system. Issued 10/24/75.	NW	66175	The Raisbeck Group 2471 Perkins Lane West Seattle, WA 98199
24D; T.C. A10CE	SA639AL	Install EP-001 starter/generator decoupler system. Issued 6/28/78.	AL	45790	Jet Accessories, Inc. P.O. Box 38568 Stapleton Field Denver, CO 80238
24D; T.C. A10CE	SA1648SW	Stretcher installation according to Qualitron Aero. Reissued 5/20/59.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
25 Series; T.C. A10CE	SA3280WE	Installation of fuel filler well for fuselage tanks. Issued 10/27/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
25, 25A, 25B, 25D, 28; T.C. A10CE	SA3891WE	Installation of Sunair Model ASB-130 high frequency radio communication system. Issued 3/27/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1376CE	Andrea Radio Corp. (A-81) five station interphone system. Reissued 12/30/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1497CE	Structural provision for NASA - Daedalus IR scanner. Amended 12/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25, 25B; T.C. A10CE	ST147RM	Installation of Communications Components Corp. Ontrac III VLF/Omega navigation system. Issued 8/7/78.	RM	05940	Aircraft Radio & Accessory, Inc. Hangar 1 Stapleton Internationl Airport Denver, CO 80207
25, 25B, 25C; T.C. A10CE	SA30GL	Installation of electronic engine synchronizer system. Issued 7/12/73.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
25, 25B, 25C; T.C. A10CE	SA953CE	Installation of dual camera/intervalometer. Issued October 1973.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North Wichita, KS 67204
25, 25B, 25C; T.C. A10CE	SA3622WE	Modifications to add installation provisions for twin aerial survey cameras in the belly of the airplane. Issued 4/10/78.	WE	43450	Mark Hurd Aerial Surveys, Inc. P.O. Box 489 Goleta, CA 93017

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
25B; T.C. A10CE	SA29RM	Install mid-fuselage cargo compartment (500 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA30RM	Install tail cone cargo compartment (300 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA92GL	Install a Foster Airdata System, Inc. AD611/D area navigation system. Reissued and amended 2/20/79.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
25D; T.C. A10CE	SA4034WE	Installation of Canadian Marconi CMA-771 Omega/VLF navigation system. Issued 12/26/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
28, 29; T.C. A10CE	SA3926WE	Installation of Garrett Rescu 99 locator transmitter. Issued 5/9/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1489CE	Removal of 24-inch wide executive door and installation of 36-inch wide cargo door. Issued 5/8/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
29; T.C. A10CE	SA3928WE	Installation of Collins 718-U5 high frequency radio communications system. Issued 5/2/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35; T.C. A10CE	SA1195CE	Installation of dual Sperry C-12 gyro-compass system for use as navigational air. Issued 1/23/76.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35; T.C. A10CE	SA2288SW	Litton LTN-104 inertial navigation system. Issued March 1976.	SW	12250	Associated Radio Service 6911 Lemmon Avenue Dallas, TX 75220
35, 35A; T.C. A10CE	SA3633WE	Installation of AiResearch AiRNAV-200 RNAV and Global GNS-500A VLF navigation systems. Issued 4/27/78.	WE	37095	Gates Learjet-Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA3931WE	Installation of Litton LTN-72R inertial navigation system with DME/DME update. Issued 5/11/79.	WE	37094	Gates Learjet Corproation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA4075WE	Installation of Collins 718U-5M high frequency radio communications system. Issued 1/11/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA82RM	Installation of Sperry SP180/81 Flight Director System, interfaced with J.E.T. FC-200 Automatic Flight Control System. Issued 10/8/76.	RM	05940	Aircraft Radio and Accessory Company, Inc. Hangar #1 Stapleton Int'l Airport Denver, CO 80202
35, 35A, 36, 36A; T.C. A10CE	SA160GL	Install a J.E.T. DAC-2000 3-D RNAV system. Amended 4/15/77.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
35, 35A, 36, 36A; T.C. A10CE	SA405NW	Installation of an ONTRAC III VLF/Omega navigation system. Amended 9/27/77.	NW	16888	Boise Cascade Aviation 3565 South Owyhee Boise, ID 83705
35, 35A, 36, 36A; T.C. A10CE	SA1507CE	Installation of electronic consoles on cabin seat rails. Reissued 8/20/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1508CE	Installation of mounting plates in the tail cone for mounting of electrical inverters. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1509CE	Installation of instrumentation rack and inverter rack in baggage compartment. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1531CE	Installation of a pod aerodynamic fairing capable of accepting target towing equipment. Issued 10/31/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, 35A, 36, 36A; T.C. A10CE	SA1531CE	Installation of structural plug. Issued 10/31/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
35, 35A, 36, 36A; T.C. A10CE	SA1533CE	Installation of a Maritime Patrol surveillance system. Reissued 11/16/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA3198WE	Installation of Garrett TFE 731 engine synchronizer/EMI filter - engine speed. Issued 5/20/76.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. A10CE	SA3340WE	Installation of Communications Components Corp. CNTRAC III VLF/Omega navigation system. Issued 2/10/77.	WE	37094	Gates Learjet Modification and Service Center Tucson Int'l Airport Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3346WE	Installation of Collins Radio Co. flight profile comparator (ground proximity warning system - GPWS). Issued 2/18/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3375WE	Installation of Foster Airdata AD611D area navigation system. Amended 7/17/79.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3396WE	Installation of hydromechanical fuel controls, computers, and harnesses. Issued 5/5/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. aA10CE	SA3398WE	Installation of cold cathode cabin lighting system. Issued 5/6/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3411WE	Installation of AFCS heading select system. Issued 5/20/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3420WE	Installation of pitch trim tone system. Issued 6/29/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3421WE	Installation of modified control wheel and stick pusher cutout system. Issued 6/29/77	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3438WE	Installation of Garrett AirNav 100 or 200 navigation system. Amended 6/1/78.	WE	07500	AiResearch Manufacturing Company of California 2525 West 190th Street Torrance, CA 90509
35, 35A, 36, 36A; T.C. A10CE	SA3440WE	Installation of VOR/ILS compass and vertical gyro instrument switching system.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3442WE	Installation of AFCS heading and/or pitch maneuver transfer systems. Amended 1/27/78.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3509WE	Installation of Tracor 7640 omega navigation system. Issued 11/4/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3530WE	Installation of dual Collins 718U-5 HF system. Amended 10/31/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3531WE	Installation of Sundstrand MKII ground proximity warning system. Issued 12/12/77.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3532WE	Installation of Collins ANS-31A area navigation system. Issued 1/12/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3561WE	Installation of a fuel filter. Amended 3/13/78.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, 35A, 36, 36A; T.C. A10CE	SA3568WE	Installation of Delco Carousel IV-A inertial navigation system. Issued 2/17/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3808WE	Installation of Jet Elect. & Tech. DAC-2000 3-D R/NAV system. Issued 12/20/78.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3865WE	Installation of Sperry C-11B compass system. Issued 3/5/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3896WE	Installation of Collins FIS-84 flight instrument system. Issued 4/10/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3916WE	Installation of directional gyro and vertical gyro transfer switching system. Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3994WE	Installation of ONTRAC III Mod 6, Omega/VLF navigation system. Issued 7/17/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 36; T.C. A10CE	SA766NW	Installation of stall fences and removal of vortex generators. Issued 5/4/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road South Seattle, WA 98108
35A; T.C. A10CE	SA4060WE	Installation of Sunair ASB-500 high frequency radio communication system. Issued 1/17/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35A, 36A; T.C. A10CE	SA1240CE	Installation of Intercontinental Dynamics Corp. RAD/BAR altimeter without voice terrain advisory. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1241CE	Installation of dual IDC maximum allowable mach/airspeed indicators type 575, P/N 25850. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1306CE	Install copilot's IDC maximum allowable airspeed/mach indicator type 575, P/N 26320. Issued 3/14/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1340CE	Dual camera installation. Issued 7/14/77.	CE	37094	Gates Learjet Corporation 8220 West Harry Wichita, KS 67209
35A, 36A; T.C. A10CE	SA1505CE	Wing pylon external stores installation. Issued 9/28/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
36, 36A; T.C. A10CE	SA3529WE	Installation of Litton LTN-72 inertial navigation system. Issued 1/13/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
36, 36A; T.C. A10CE	SA3864WE	Installation of Litton LTN-72R inertial navigation/area navigation system. Issued 3/6/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
36, 36A; T.C. A10CE	SA4033WE	Installation of Litton LTN-72R (INS)/Global GNS-500A (VLF/Omega) interface. Issued 11/7/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GENERAL DYNAMICS CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BT-13 Series; T.C. 2-571	SA4-404	Glass cloth application on control surfaces.	WE	38060	Glasco-Air Products, Inc. Oxnard-Ventura County Airport Oxnard, CA 93030
BT-13 Series; T.C. 2-571	SA4-625	Flap lids.	WE	54660	E.H. Mann & E. Snow 13226 Hubbard Street Sylmar, CA 91332
BT-13 Series; BT-15; T.C. 2-571	SA4-592	Eonite covering on ailerons and rudder.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
BT-13 Series; BT-15; T.C. 2-571	SA4-848	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
BT-13, -13A, -13B, BT-31-15, PBY-6A; T.C. 2-571, AR-22, 785, 2-548	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
BT-13, -13A (Navy SNV-1), -13B, (Navy SNV-2), -15; T.C. 2-571	SA1008WE	Installation of Poly-Fiber covering material. Amended 8/7/69.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92502
BT-13 Series, BT-15, Navy SNV Series; T.C. 2-571	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BT-13, -13A, -13B, BT-15, L-13A, PBY-5, PBY-5A, PBY-6A, 28-5ACF, P4Y-2; T.C. 2-571, AR-10, AR-22, 785, aAR-29	SA2666WE	Ceconite 102 material covering of: BT-13, -13A, -13B, BT-15 - rudder, elevators, flaps, and ailerons; L-13A - ailerons, elevators and rudder; PBY-5, -5A, -6A, 28-5ACF - ailerons, wing trailing edges, rudder and elevators; P4Y-2 - ailerons, rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
L-13 Series; T.C. AR-10	SA4-510	Landing gear modification.	WE	62442	Paragon Tool Die & Engineering 11035 Sutter Avenue Pacoima, CA 91331
L-13 Series; T.C. AR-10	SA4-521	Glass cloth application on control surfaces.	WE	38060	Glasco-Air Products, Inc. Oxnard-Ventura County Airport Oxnard, CA 93030
L-13 Series; T.C. AR-10	SA4-1020	Dust-spray tank and stabilizer braces.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
L-13 Series; T.C. AR-10	SA201WE	Hamilton Standard propeller, hub 2820, and blades 6135A-9.	WE	40520	Archie Hanson, Jr. 24733 Long Valley Road Calabasas, CA 91302
L-13 Series; T.C. AR-10	SA640WE	Ceconite 101 covering of ailerons, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
L-13A; P4Y-2; BT-13, -13A, -13B, -15; PBY-5, -5A, -6A, 28-5ACF; T.C. AR-10, AR-29, 2-571, 785	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
P4Y-2; T.C. AR-29	SA4-1144	Ceconite 101 covering of ailerons and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
P4Y-2; T.C. AR-29	SA1900WE	Installation of Wright R2600-35 engines and Hamilton Standard 23E50-505/6359A-13 propellers. Amended 1/15/74.	RM	41360	Hawkins & Powers Aviation, Inc. P.O. Box 391 Greybull, WY 82426
PB4Y-2, P4Y-2; T.C. AR-29	SA27RM	Integral fuel tank installation. Issued 5/14/74.	RM	41360	Hawkins & Powers Aviation, Inc. P.O. Box 391 Greybull, WY 82426

GENERAL DYNAMICS CORP. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PBY-5, PBY-5A; T.C. 2-548	SA1480	Metal wing skin on trailing edge portion of wing.	SO	00082	A & G Aircraft Broward Co. Int'l Airport Fort Lauderdale, FL 33000
PBY-5, PBY-5A, PBY-6A, 28-5ACF; T.C. 2-548, AR22, 785	SA4-1066	Ceconite 101 covering of ailerons, wing trailing edges, rudder and elevators.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PBY-5A Series; T.C. 2-548	SA926SW	PBY-6A tail and retain blisters.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
PBY-5A, PBY-6A, 28-5ACF; T.C. 2-548, AR-22, 785	SA4-1056	Fabric covering attachment with screws instead of stitching. Reissued 2/19/71.	WE	42040	Hemet Valley Flying Service Co. P.O. Box 1678 Hemet, CA 92343
PBY-5A, 28-5ACF; T.C. 2-548, 785	SA4-493	104-1-B and 104-1-C engine mount cores on aircraft with Pratt & Whitney R-1830-92 or S1C3-G engine.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
PBY-5A, 28-5ACF; T.C. 2-548, 785	SA4-1470	Alclad sheet .020 2024-T3.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
PBY-6A; T.C. AR-22	SA2354WE	Installation of two (2) Wright R2600-35 engines and Hamilton Standard 23E50/6359A-18 propellers. Reissued 1/20/72.	CE	60180	Joseph E. Morris Box 10365, Lambert Field St. Louis, MO 63145
22; T.C. 4A27	SA1-562	CJ805-3B modified as an alternate to CJ805-3 engine.	NE	61628	Northeast Airlines, Inc. Logan International Airport East Boston, MA 02128
22; T.C. 4A27	SA918SO	Modification of rotating field element G.E. 291C777G1 of G.E. 400 cycle alternator 2CM211A1.	SO	63855	Peninsular Armature Works, Inc. 3525 N.W. 51 Street Miami, FL 33101
22; T.C. 4A27	SA214CE	Autothrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22; T.C. 4A27	SA215CE	Single SCAT system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22; T.C. 4A27	SA216CE	Autopilot variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22; T.C. 4A27	SA217CE	Second flight director system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22; T.C. 4A27	SA223CE	Dual low range radio altimeter system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22; T.C. 4A27	SA241EA	Nose cap weather radome shell.	NE	53750	McMillan Radiation Labs, Inc. Brownville Avenue Ipswich, MA 01938
22; T.C. 4A27	SA279CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA280CE	Autothrust system equipment.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA281CE	Single SCAT system provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA281WE	Engine-mounted fire detector system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA308WE	Voice interruption priority system.	WE	61648	Northrop Corporation 222 N. Prairie Avenue Hawthorne, CA 90250
22 Series; T.C. 4A27	SA336SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Atlanta Airport Atlanta, GA 30320
22 Series; T.C. 4A27	SA376SO	Relocation of LAS 109C flight recorder and installation of a remote accelerometer.	SO	29234	Delta Air Lines, Inc. Atlanta Airport Atlanta, GA 30320

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
22 Series; T.C. 4A27	SA389CE	Eclipse-Pioneer 15470, 15492 and 18729 autopilot amplifier.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA390CE	Eclipse-Pioneer 18729 autopilot amplifier.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	ST402SO	Modification of interior emergency lighting.	SO	29234	Delta Air Lines Atlanta Airport Atlanta, GA 30320
22 Series; T.C. 4A27	ST403SO	Installation of exterior emergency lighting system.	SO	29234	Delta Air Lines Atlanta Airport Atlanta, GA 30320
22 Series; T.C. 4A27	SA484CE	Relocation of Lockheed Aircraft Service Model 109CR flight recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA563CE	Installation of static port heater system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA594CE	Installation of dual low range radio altimeter system single equipment driving dual indicators. Amended 1/20/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA671CE	Install logo lights in upper leading edges of horizontal stabilizer.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA687SW	Nose cap weather radome shell.	NE	53750	McMillan Radiation Labs, Inc. Brownville Avenue Ipswich, MA 01938
22 Series; T.C. 4A27	SA727CE	Installation of Kollsman altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA772CE	Installation of Bendix P/N 1978128-1 indicator and P/N 1964771-3 inverter. Issued June 1971.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA830CE	Install Butler National Corporation flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA896WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
22 Series; T.C. 4A27	SA1282WE	Dual Collins AL101 radio altimeter system, 51RV-1 navigation receivers and all weather landing system wiring.	WE	37280	General Dynamics Convair Division P.O. Box 1950 San Diego, CA 92112
22 Series; T.C. 4A27	SA2462SW	Interior. Issued 5/18/77.	SW	36550	Foster-Edwards Aircraft Co., Inc. P.O. Box 574 Addison, TX 75001
22, 22M; T.C. 4A27	SA152GL	Installation of X band weather radome only on models with Convair 22-71001-1 support assembly (bulkhead assembly). Issued 2/16/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
22, 22M (880); T.C. 4A27	ST422SO	Installation of single radar altimeter system.	SO	29234	Delta Air Lines Atlanta Airport Atlanta, GA 30320
22, 22M; T.C. 4A27	ST768SO	Installation of cargo loading door (forward L.H. side of fuselage). Issued 10/26/78.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
22, 22M(880) T.C. 4A27	ST944SO	Installation of (1) Class "B" cargo compartment, (2) cargo restraining bulkhead, and (3) smoke detector system. STC ST906SO is a required part of this STC. Issued 7/21/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
22, 22M; T.C. 4A27	SA2341WE	Installation of battery-powered emergency exit lighting on forward and aft entry and service doors. Issued 4/13/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
22, 22M; T.C. 4A27	SA1093SO	Installation of class "B" or "E" cargo compartment. Issued 8/14/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33161
22, 22M; 30, 30A; 240; 440; 600 (240D); 640 (340D or 440D); T.C. 4A27, 4A30, A-793, 6A6, A-793 & SA1054WE, 6A6 & SA1096WE	SA863EA	Incorporation of DME Corporation ESL-1, ESL-6 or ESL-6-1 emergency slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
22, 22M; 30, 30A; T.C. 4A27, 4A30	SA2534SW-D	Replacement of Switch assembly, International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
22, 22M; 30, 30A; T.C. 4A27, 4A30	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A and EL-104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
22, 22M; 30, 30A; 240; 600; 440; 340/440; 640; T.C. 4A27, 4A30, A-793, A-793 and SA1054WE, 6A6 and SA4-1100, 6A6 and SA1096WE	SA2728WE	Incorporation of HI-LITE SYSTEM P/N 50-1001 for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
22M; T.C. 4A27	ST988SO	Fabrication and installation of a cargo rack/net assembly. Issued 5/31/78.	SO	62170	Page Air Services of Florida, Inc. 9809 Florida Road Orlando International Airport Orlando, FL 32809
22M; T.C. 4A27	SA1365WE	Modification of wiring and equipment installation.	WE	50100	Lear Siegler, Inc. Astronics Division 3171 South Bundy Drive Santa Monica, CA 90406
22-1 (880); T.C. 4A27	SA593CE	Modification of interior emergency lighting and installation of exterior emergency lighting system. Amended 9/19/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22-1 (880); T.C. 4A27	SA579EA	Replace Bendix type 15866, 15897 and 19903 Vertical Gyros with Bendix type 19911 or 19912 Vertical Gyros.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
CV 22 (CV-880); T.C. 4A27	SA2549WE	The installation of automatically deployable and automatically inflatable emergency exit slides. Issued 6/9/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352
28-5ACF; T.C. 785	SA3-150	Wright R2600-29 or -20 engines and modifications permitting 32,000 pounds maximum weight. Amended 5/22/67.	CE	60180	J.E. Morris #1 Lomond Drive Ferguson, MO 63135
28-5ACF; T.C. 785	SA3-153	Blister.	CE	65770	Edgar M. Queeny 9800 Olive Street Road St. Louis, MO 63155
28-5ACF; T.C. 785	SA3-154	Airstair.	CE	65770	Edgar M. Queeny 9800 Olive Street Road St. Louis, MO 63155
28-5ACF; T.C. 785	SA3-155	Bulkhead doors.	CE	65770	Edgar M. Queeny 9800 Olive Street Road St. Louis, MO 63155
28-5ACF; T.C. 785	SA3-156	Right hand cargo door.	CE	65770	Edgar M. Queeny 9800 Olive Street Road St. Louis, MO 63155
28-5ACF; T.C. 785	SA4-12	Removal of landing gear and installation of wheel well enclosures; bench type seats.	WE	73883	Southern California Aircraft Corporation Ontario, CA 91761
28-5ACF; T.C. 785	SA4-584	Couch structures.	WE	20180	Catalina Limited 5050 Arrow Highway Montclair, CA 91763
28-5ACF; T.C. 785	SA4-600	Windows.	WE	20180	Catalina Limited 5050 Arrow Highway Montclair, CA 91763

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
28-5ACF; T.C. 785	SA4-601	Forward double couch structure and aft double couch structure.	WE	20180	Catalina Limited 5050 Arrow Highway Montclair, CA 91763
28-5ACF; T.C. 785	SA4-617	A-12 automatic pilot.	CE	65770	Edgar M. Queeny 9800 Olive Street Road St. Louis, MO 63155
28-5ACF; T.C. 785	SA4-776	Replacement of fabric on trailing edge of wing with sheet metal.	AL	08600	Alcan Airways P.O. Box 2173 Anchorage, AK 99500
28-5ACF; T.C. 785	SA4-943	Window installation - STA 3.5 to 3.0 and STA 5.0 to 6.0. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
28-5ACF; T.C. 785	SA4-1045	Enlarged opening in airstair interior side panel.	AL	08483	Alaska Coastal Airlines Two Marine Way Juneau, AK 99801
28-5ACF; T.C. 785	SA4-1119	PBY-6A tail.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
28-5ACF; T.C. 785	SA4-1154	Cargo loading door.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
28-5ACF; T.C. 785	SA4-1287	60" x 72" opening in bulkhead 6.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
28-5ACF; T.C. 785	SA122AL	Separate metal and fabric covered sections of wing trailing edge and center section.	AL	08483	Alaska Coastal Ellis Airlines 2 Marine Way Juneau, AK 99801
28-5ACF; T.C. 785	SA1853WE	Installation of two Lycoming GSO 480 B2D6 engines and two Hartzell 83XF-3A reversing full feathering propellers.	WE	16815	Bird Corporation Mark 3 Respirator Lane Palm Springs Airport Palm Springs, CA 92262
30, 30A (990); T.C. 4A30	SA153GL	Installation of X band weather radome only on models with Convair 22-71001-1 support assembly (bulkhead assembly). Issued 2/16/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
30, 30A; T.C. 4A30	SA414EA-D	Modify interior cabin arrangement to accommodate 135 passengers in an all coach configuration. Amended 2/2/68.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
30, 30A; T.C. 4A30	SA416EA-D	Installation of life rafts. Amended 6/14/68.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
30, 30A; T.C. 4A30	SA417EA-D	Relocate flight data recorder to aft fuselage area.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
30A (CV-990); T.C. 4A30	ST121RM	Installation of dual Marconi Omega navigation systems (Model CMA-740). Amended 9/22/78.	RM	65016	Ports of Call Travel Club 2121 Valentia Denver, CO 80220
30A (CV-990); T.C. 4A30	ST124RM	Installation of cabin window at station 479.5 on right side. Issued 12/21/77.	RM	65016	Ports of Call Travel Club 2121 Valentia Street Denver, CO 80220
30A; T.C. 4A30	SA421EA-D	Modify interior cabin arrangement to accommodate 139 passengers in an all coach configuration. Amended 4/8/68.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
30A; T.C. 4A30	ST467SO	Installation of AiResearch auxiliary power unit GTCP85-129M in the No. 3 anti-shock body. This installation is limited to ground use only. Issued 5/19/71.	SO	60090	Modern Air Transport, Inc. P.O. Box 627 Miami, FL 33148
30A; T.C. 4A30	SA503WE	Rework of Freon compressor feeder wiring and connection to 100-ampere circuit breakers.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
30A; T.C. 4A30	SA504EA-D	Stowage compartment installation to house two life rafts plus miscellaneous items. Amended 6/10/68.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
30A; T.C. 4A30	SA505EA-D	Installation of beverage stowage compartment. Amended 12/4/68.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
30A; T.C. 4A30	SA506EA	Modify the interior cabin arrangement.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
30A; T.C. 4A30	SA513EA-D	Life rafts being installed to meet over-water emergency requirements.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
30A; T.C. 4A30	SA518EA-D	Cabin passenger seat tracks to F.S. 1363.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
30A; T.C. 4A30	SA638SO	Modification of interior to accommodate 139 passengers.	SO	60090	Modern Air Transport, Inc. P.O. Box 627 Miami, FL 33148
30A; T.C. 4A30	ST653SO	Installation of LORAN/ADF antenna switching system (utilizing ADF sense antennas). Amended 11/7/68.	SO	60090	Modern Air Transport, Inc. P.O. Box 6271 Miami, FL 33148
30A; T.C. 4A30	ST669SO	Increases passenger seating capacity from 139 to 149 passengers. Amended 7/22/70.	SO	60090	Modern Air Transport, Inc. P.O. Box 627 Miami, FL 33148
30A; T.C. 4A30	ST679SO	Installation of electrically heated washwater overboard drain system.	SO	60090	Modern Air Transport, Inc. P.O. Box 627 Miami, FL 33148
30A; T.C. 4A30	SA1061WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
30A; T.C. 4A30	SA1211WE	Fairchild cockpit voice recorder system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
30A; T.C. 4A30	SA1429WE	Installation of Sell Haus galleys, Model Nos. 66-1-1, 66-2-1, 66-3-1, 66-4-1 and 66-5-1.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
30A; T.C. 4A30	SA2482WE	Installation of Trans Com Model 1179 motion picture projectors and screen assemblies. Reissued 4/23/73.	NW	76800	Trans Com, A Div. of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
30A; T.C. 4A30	SA2510WE	Installation of dual Litton Model LTN-51 INS. Issued 5/2/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
30A; T.C. 4A30	SA2812WE	Emergency interior and exterior light installations; interior equipment and furnishings, underseat baggage restraints and overwing escape walkway and assist per rope installations for 121 passenger configuration. Amended 2/15/74.	WE	10210	American Jet Industries 2800 N. Clybourn Burbank, CA 91505
240; T.C. 793	SA1-392	2008X series radome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
240; T.C. 793	SA3-497	Equivalent means of compliance with AD 55-18-01 (Convair Service Bulletin 340-141A) - Throttle reverse lock mechanism. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-500	General interior arrangement #1 (16 passenger). General interior arrangement #2 (17 passenger). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-501	Typical divan installation (Divan P/N DC3-22021). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-506	Installation of weather radar antenna mount and radar nose. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-567	Chair and desk installation - Station 167. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-579	Rectangular exit exhaust muffler installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
240; T.C. 793	SA3-580	General interior configuration floor plan arrangement #2. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-582	General interior configuration floor plan arrangement #1. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-583	General interior configuration floor plan #4. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-584	Forward lavatory installation (STA 278). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-585	Rear galley installation (STA 644). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-589	Removal and closure of rear service door - STA 672. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-590	Installation Stewart-Warner 940-F24 cabin heater - STA 620. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793 T.C. 793	SA3-601	Typical swivel seat installation (Hardman Tool & Engineering Co. Seat Model 3004, TSO C-39). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-645	General interior configuration floor plan #5. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-646	Navigator chair and desk installation (STA 155). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-648	Flight observer jump seat installation - STA 109. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-710	Rear airstair door installation STA 628- 812. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-711	Closure installation L.H. entrance door (F.S. 638). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 72008
240; T.C. 793	SA3-712	Fabrication and installation of 360 degrees swivel seat. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-713	General interior configuration floor plan #6. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-714	Utility shower installation - aft cabin. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-734	Lavatory/vanity installation at station 644. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA3-735	General interior configuration floor plan #8. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA4-44	Hamilton Standard 43E60/6895-12 constant-speed controllable propellers.	WE	85126	Western Airlines, Inc. P.O. Box 45005 Los Angeles, CA 90052
240; T.C. 793	SA4-197	Window on left-hand side of station 676, bulkhead at fuselage station 194. Left and right-hand rack and stewardess seat.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-231	Installation of auxiliary power unit (Andover type D-2, Model V-32) and associated equipment in baggage compartment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
240; T.C. 793	SA4-271	Installation of Sperry A-12 autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
240; T.C. 793	SA4-335	Bulkhead and seats at station 194.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-358	Outer wing panels to incorporate a 275-gallon integral fuel tank.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
240; T.C. 793	SA4-470	ADF loop.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Van Nuys, CA 91408
240; T.C. 793	SA4-495	S-200 Janitrol ground heater.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
240; T.C. 793	SA4-518	General Dynamics 340 radome kit. (Approval does not cover radar installations.)	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
240; T.C. 793	SA4-634	Interior arrangement.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
240; T.C. 793	SA4-762	Weather mapping radar for aircraft with forward passenger loading door only.	WE	07500	AiResearch Aviation Service Co. 6201 W. IMperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-770	Auxiliary oil system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-771	General Dynamics 340 Sperry "on" "off" autopilot system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-837	Extension of fuel to outer wing panel.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-892	Cargo door 6 by 8 feet.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-929	Pitot system in conjunction with Chamberlain radome R2008X-R-01 (STC SA1-392).	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-946	Doppler antenna and radome.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-978	G.T.P. 70-17 auxiliary gas turbine.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1013	Interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
240; T.C. 793	SA4-1040	Ranger APU for ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1044	Pratt & Whitney R-2800-83AM7 engine.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
240; T.C. 793	SA4-1142	Stainless steel overlay 0.015. Compliance with AD 59-02-01 required.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
240; T.C. 793	SA4-1179	Outer wing fuel tank installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA4-1213	Interior modification. Amended 1/9/69.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport AVenue Santa Monica, CA 90405
240; T.C. 793	SA4-1214	17-passenger interior arrangement and radio equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
240; T.C. 793	SA4-1216	Andover Type D-2, Model V-32 APU and associated equipment for ground operation only.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
240; T.C. 793	SA4-1218	Maxim silencers.	WE	08172	Airlines Eng. Service Company 9586 Shirley Lane Beverly Hills, CA 90213

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
240; T.C. 793	SA4-1222	Doppler antenna at fuselage station 667.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1224	Autopilot AP-103.	CE	24250	Collins Radio Company 855 35 Street, N.E. Cedar Rapids, IA 52401
240; T.C. 793	SA4-1226	Janitrol S-50 cockpit heater.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1228	Shrouding of flammable fluid system valve required by AD 59-02-01.	WE	54600	Don Maier & Associates 6214 W. Manchester Avenue Los Angeles, CA 90052
240; T.C. 793	SA4-1236	Pressure bulkhead and support provisions for McMillan radome.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles,'CA 90045
240; T.C. 793	SA4-1241	AVQ-50 radar and equipment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1526	100,000 B.T.U. heater for ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1528	18-passenger cabin arrangement, APU installation and an aft baggage compartment smoke detector.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1558	CV-340 compressor.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA7CE	Cockpit auxiliary heater installation, Janco Model 8032. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA13SW	APU for ground operation only.	SW	34000	Executive Aircraft Service Redbird Airport Dallas, TX 75232
240; T.C. 793	SA16CE	Float type fuel gage installation - ground visual fuel. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA32CE	Interior general arrangement - floor plan #9. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA35CE	Installation of generator overheat indicator. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA63EA	General Dynamics rectangular exhaust exit mufflers on aircraft with Hamilton Standard 43E60/6895-12 propellers and Pratt & Whitney R-2800-CB-16/17 engines.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
240; T.C. 793	SA177WE	Distance measuring equipment and transponder, and relocation of inverter installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA252SO	Supporting structure for camera mount A-28.	SO	10160	American Airmotive Corp. P.O. Box 187 International Airport Miami, FL 33101
240; T.C. 793	SA274EA	Electromagnetometer transmitting coil, batteries, transmitter junction box, and receiving "Bird." Amended 8/15/66.	EA	35300	Field Aviation Company, Ltd. P.O. Box 1001 Toronto Int'l Airport Melton, Ontario, Canada
240; T.C. 793	SA275EA	Antenna, radome, gyro and compass.	EA	44179	U.S. Geological Survey Department of Interior 8300 Colesville Road Silver Springs, MD 20907
240; T.C. 793	SA320WE	Ground blower.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA442WE	Extendable boom, detection crystal support, antenna, inverters, converters, and window enlargement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
240; T.C. 793	SA696SW	Fairchild cockpit voice recorder and control unit A-152-2.	SW	20550	Central Airlines, Inc. P.O. Box 2554 Fort Worth, TX 76101
240; T.C. 793	SA1054WE	Rolls Royce RDa 10 542-4 engines and Dowty Rotol R.245/4-40-4.5/13 propellers, an AiResearch APU and two combustion heaters.	WE	37280	General Dynamics 3302 Pacific Highway San Diego, CA 92112
240; T.C. 793	SA1303WE	Two 15KS-1000A1 standby rocket engines in fuselage tail cone and an aft pressure bulkhead.	WE	02315	Aerojet-General Corporation P.O. Box 15847 Sacramento, CA 95813
240; T.C. 793	SA1316WE	Underwing pressure refueling system and Roylin "Magna Stick" fuel level indicator.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
240; T.C. 793	SA3099WE	Modification of cargo door and cargo floor and removal of cabin pressurization. Issued 11/26/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
240; T.C. A-793	SA3697WE	Installation of cargo door, cargo floor and entry door. Amended 9/26/78.	WE	39877	Hamilton Aviation Company P.O. Box 11427 Tucson, AZ 85734
240; T.C. A-793	SA3801WE	Instalaltion of cargo door and cargo floor. Issued 12/6/78.	WE	39877	Hamilton Aviation Company Tucson Aviation Center P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. 793	SA149EA	Conversion of military model B29B to model 240-27. Reissued 6/27/77.	WE	39877	Gordon B. Hamilton The Hamilton Aviation Co. P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. 793	SA150EA	Installation of: 19 passenger executive interior Solar T-350M2 turbine APU comm and navigational systems. Reissued 6/27/77.	WE	39877	Gordon B. Hamilton The Hamilton Aviation Co. P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. 793	SA777SO	Installation of a cargo barrier bulkhead. Issued 10/4/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
240-27 (T-29B); T.C. 793	SA1048SO	Conversion of USAF Model T-29B into the civil Model 240-27 with deviations to TCDS A-793. Amended 8/16/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
240-27 (T-29B); T.C. A-793	SA1100SO	Conversion of the USAF T-29B into the civil model 240-27 with deviations to Aircraft Spec. A-793. Issued 9/10/79.	SO	44320	International Transportation P.O. Box 1183 Ormond Beach, FL 32074
240-27 (T-29B); T.C. 793	SA1135SO	Installation of a Class "E" cargo compartment, cargo floor modification, large aft cargo door, and removal of certain components of the previously deactivated pressurization system. Issued 2/22/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
240-27; T.C. A-793	SA3831WE	Installation of King weather radar. Amended 11/7/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. A-793	SA4025WE	Installation of cargo door, cargo floor, class "E" cargo compartment provisions for weather radar installation. Issued 9/28/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. A-793	SA4026WE	Conversion of military T-29B to civil model 240-27. Issued 9/28/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. A-793	SA4027WE	Installation of a boarding ladder. Issued 9/28/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240, 340; T.C. 793, 6A6	SA4-861	Stainless steel overlay nacelle area required by AD 59-02-01.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240, 340; T.C. 6A6	SA426EA	Installation of Chamberlain replacement radome 3008 or 3008C. Amended 11/27/67.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company Aero Product Operations P.O. Box 1187 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
240, 340, 440; T.C. 793, 6A6	SA1-656	Radome assembly 3008.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
240, 340, 440; T.C. 793, 6A6	SA3-420	Main cabin seat installations (including divan and seat belts). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240, 340, 440; T.C. 793, 6A6	SA4-500	Engine mount core assemblies. (Parts manufactured under license from United Aircraft Corporation.)	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
240, 340, 440; T.C. 793, 6A6	SA4-525	Engine mount core 106-1F and 106-1J.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
240, 340, 440; T.C. 793, 6A6	SA4-568	Engine mount core assemblies DE1468.	WE	83500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
240, 340, 440; T.C. 793, 6A6	SA41SO	B-300B engine oil separator.	SO	04400	Air Carrier Engine Service, Inc. International Airport Miami, FL 33101
240, 340, 440; T.C. 793, 6A6	SA118SO	BS-040-2 oil separator.	SO	04400	Air Carrier Engine Service, Inc. International Airport Miami, FL 33101
240, 340, 440; T.C. 793, 6A6	SA125CE	High intensity wing tip lights Model B or F, tail lights Model C, with or without Model 2 fuselage lights, STC SA4-1100 modified aircraft. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
240, 340, 440; T.C. 793, 6A6	SA775SW	Airstep.	SW	85128	Westernair of Albuquerque, Inc. 4736 Isleta Boulevard, SW Albuquerque, NM 87101
240D, 340D, 440D; T.C. 793, 6A6	SA1927SW	Installation of Safeway De-Icer boot P/N 5660 and/or Semsa Lead P/N S2001 in lieu of Dowty Rotol boots and/or leads on Dowty Rotol propeller models R245/4-40-4.5/13 with blades P/N 6.6000.2301 or Model R259/4-40-4.5/17 with blades P/N 6.6000.4300. Amended 2/27/75.	EA	70830	SEMSA, Inc. 2125 Smithtown Avenue Ronkonkoma, NY 11779
240D (600): T.C. 793	SA1992SW	Aft cargo door between F.S. 549 and 658 between floorline and stringer and associated structural modifications. Issued 6/6/75.	SW	07740	Air Freighters International P.O. Box 2 15808 Addison Road Addison, TX 75001
340; T.C. 6A6	SA1-488	Various radio and modifications plus rearrangement of control head on pedestal and revised radio electrical circuitry.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
340; T.C. 6A6	SA3-419	General interior floor plan arrangement. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340; T.C. 6A6	SA3-421	Installation of auxiliary power unit. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340; T.C. 6A6	SA4-38	Two additional passenger windows and three double passenger seats forward of fuselage station 243.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340; T.C. 6A6	SA4-219	Vibration suppressor plates.	WE	52010	Lockheed Aircraft Service, Inc. P.O. Box 33 Ontario, CA 91761
340; T.C. 6A6	SA4-1164	Flammable fluid system valve shrouding required by AD 59-02-01.	WE	54600	Don Maier & Associates 6214 W. Manchester Avenue Los Angeles, CA 90052
340; T.C. 6A6	SA4-1211	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340; T.C. 6A6	SA4-1321	Interior modification including a 16-passenger executive type interior arrangement and baggage compartment smoke detector.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340; T.C. 6A6	SA4PC	Brownline cargo pallet and net assemblies.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340; T.C. 6A6	SA5PC	Conversion to an all cargo airplane.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA6PC	Cargo/passenger combination interior.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA7PC	Removable triple seat.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA83WE	Interior arrangement for 58 occupants.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340; T.C. 6A6	ST409SO	Rear service door hinge.	SO	29234	Delta Air LInes, INc. Atlanta Airport Atlanta, GA 30320
340; T.C. 6A6	SA506SW	Hydraulic system modification.	SW	34180	FAA Aeronautical Center Engineering Division Will Rogers Field Oklahoma City, OK 73101
340; T.C. 6A6	SA713WE	AiResearch GTP30-54 turbine APU.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
340; T.C. 6A6	SA952EA	Installation of Solar T-62T-39 gas turbine auxiliary power unit. Issued 4/11/73.	EA	18750	Butler Aviation Friendship, Inc. Sub. of Butler Aviation Int'l Friendship Int'l Airport Baltimore, MD 21240
340; T.C. 6A6	SA2702SW	Two Friedrich window air conditioners and three electrical heaters. Issued 12/22/77.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
340, 440; T.C. 6A6	SA1-471	Weather mapping radar.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
340, 440; T.C. 6A6	SA1-474	Installation of Chamberlain Aviation 2008X Series radomes. Reissued 9/12/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
340, 440; T.C. 6A6	SA1-500	Waste King flight data recorder 5424.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
340, 440 T.C. 6A6	SA3-486	Interior cabin configuration - general floor plan (20 passenger configuration). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340, 440; T.C. 6A6	SA3-487	Janitrol heater installation (100,000 BTU). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340, 440; T.C. 6A6	SA3-488	Installation of radar nose, Bendix ANT-1B antenna and pitot modification (including Radome fabrication). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340, 440; T.C. 6A6	SA3-511	Radome and airspeed indicator system.	SW	17075	Braniff Airways, Inc. Love Field Dallas, TX 75235
340, 440; T.C. 6A6	SA3-649	Maximum safety light system YG-766A or ALS9A-CV.	GL	59650	Minneapolis-Honeywell Regulator Company 2747 Fourth Avenue, South Minneapolis, MN 55401
340, 440; T.C. 6A6	SA4-36	General Dynamics 340 outer wing integral fuel tanks.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 400; T.C. 6A6	SA4-135	Oil tank and supporting structure rework (relocation of oil tank installation plumbing, oil tanks support rework, engine oil tank modification).	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-160	Andover type D-2, Model V-32 APU and associated equipment for ground operation only.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA4-194	Ranger APU for ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-247	AiResearch C-7500-1 divan.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-248	Cabin tables.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-249	Hardman 3048 and 3041 chairs.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-250	Galley and buffet.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-390	Radio and cargo compartment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Anglees, CA 90045
340, 440; T.C. 6A6	SA4-409	Interior for 52 passengers.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-418	Auxiliary A.D.I. tank in aft baggage compartment.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-582	Napier Eland 504 turboprop engines with deHavilland PD216/466 propellers with XPR5662950SA-124 or PPR626950SA-124 blades.	EU	61150	D. Napier & Son, Ltd. Acton London, W. 3, England
340, 440; T.C. 6A6	SA4-689	Napier Eland 504 turboprop engines with deHavilland PD216/466 propellers with XPR5662950SA-124 or PPR626950SA-124 blades.	EU	61150	D. Napier & Son, Ltd. Acton London, W. 3, England
340, 440; T.C. 6A6	SA4-914	Goodrich multidisc brakes and Westinghouse "Decelostat" anti-skid controller type AP-3 on aircraft modified per STC SA4-582.	EU	61150	D. Napier & Son, Ltd. Acton London, W. 3, England
340, 440; T.C. 6A6	SA4-1008	Seat track mounting floor structure.	SW	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1041	Alternate fuel source in aircraft with Pratt & Whitney R-2800 Series "C" engines and fuel flowmeters.	SW	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1100	Installation of Allison model 501-D13D or 501-D13H turbo propeller engines with Aero Products A6441FN-606A propeller, with associated modifications to engine mounting, nacelle, empennage, accessories and system. Amended 5/10/71.	GL	29750	Detroit Diesel Allison Division General Motors Corporation Indianapolis, IN 46206
340, 440; T.C. 6A6	SA4-1114	Fuel tank extension for 2,080-gallon turbine engine fuel on aircraft modified per SA4-1100.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA4-1120	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1152	Interior and equipment.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1191	17-passenger interior arrangement and smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1242	Extension of wing tank and oil tank rework. Fuel tank revised for use JP-4 fuel and kerosene.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1243	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA4-1249	Extension of fuel tank to station 29 (for JP-4 kerosene or gasoline) and provisions for a gravity flow fuel jettison system on aircraft modified per STC SA4-1100 only.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA4-1318	McMillan radome.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1343	Gas turbine in tail cone section.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1344	Modification to air-conditioning system and installation of an air start supply line.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1513	Interior and equipment on aircraft modified per STC SA4-1100.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1519	Air-driven alternator and vertical stabilizer omni navigational antenna and electrical system deviations on aircraft modified per STC SA4-1100.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1589	Interior modification including divans, swivel chairs and cabinets for a total of 13 passengers on aircraft modified per STC SA4-1100.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA2SW	Auxiliary power battery (emergency D.C. power and emergency feathering system).	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
340, 440; T.C. 6A6	SA23WE	United Data Control F-542 flight data recorder.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA24WE	RCA AVQ-50 weather avoidance radar system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA25WE	Seat track on aircraft modified per STC SA4-409.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA34RM	Installation of Sierra 7000 SANS-TACAN System. Amended 12/12/74.	RM	11870	Aspen Airways, Inc. Hangar 5 Stapleton Int'l Airport Denver, CO 80207
340, 440; T.C. 6A6	SA36WE	MOdification of fuel source for Ranger APU and Janitrol ground heater approved under STC's SA4-194 and SA4-195.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA42RM	Installation of two Sperry GH-14 gyro-horizon instruments. Reissued 1/20/75.	RM	37015	Frontier Airlines 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA50RM	Installation of additional anti-collision light system (white strobe lights). Issued 2/10/75.	RM	37015	Frontier Airlines 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA59RM	Installation of Collins type 331A-6P/6A course indicator and relocation of altitude alert control. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA60RM	Installation of Sundstrand ground proximity warning system, glide slope monitoring system and Honeywell low range radio altimeter system. Issued 7/11/75. Supplemental T.C. SA4-1100.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA71WE	Fuel source modification for Ranger APU approved under STC SA2-962.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA83GL	Install Bendix GPW-83 ground proximity warning system. Issued 9/5/75.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450
340, 440; T.C. 6A6	SA96GL	Installation of Collins FPC-590A ground proximity warning system. Issued 11/7/75.	GL	90135	Zantop International Airlines, Inc. Detroit-Willow Run Airport Ypsilanti, MI 48197

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA104RM	Install dual SELCAL system. Issued 6/22/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100); T.C. 6A6	ST133RM	Modification of turbine inlet temperature indicator Model BH183M to install precision potentionmeter in place of original tapot. Issued 2/17/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100); T.C. 6A6	ST134RM	Installation of coat closet at body station 230. Issued 2/22/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440: T.C. 6A6	SA151EA	Bendix doppler radar DRA-12.	EA	08196	Airmar Radio Service, Inc. 2177 Smithtown Avenue Ronkonkoma, NY 11779
340, 440: T.C. 6A6	SA184WE	Two 15KS-1000-A1 or two 15KS-1000-A1(B) standby rocket engines in fuselage tail cone. Amended 8/18/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
340, 440: T.C. 6A6	SA227EA	Nose cap weather radome. Amended 3/29/66.	EA	16600	Bethlehem Steel Corporation Aviation Service Division Bethlehem, PA 18016
340, 440; T.C. 6A6	SA232CE	Install aural mach warning system. Amended 2/27/67.	GL	37808	General Motors Corporation 3044 W. Grand Boulevard Detroit, MI 48202
340, 440; T.C. 6A6	SA264EA	Janitrol S-200 heater for ground operation only.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
340, 440; T.C. 6A6	SA279WE	Window emergency exit on right side of aircraft at station 651.5.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA379CE	Installation of Hoskins twilighter Mk V intensity STC SA4-1100 modified aircraft. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
340, 400; T.C. 6A6	SA423WE	Cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA427EA	All cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA428EA	Installation of FM #1, 2, and 3 Radiophone. Amended 5/26/67.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA429EA	Cabinet.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA443WE	Installation of cargo door, a cargo floor and an emergency exit, plus removal of original cargo door and forward passenger entrance door. Reissued 2/6/70.	NW	49350	Robert T. Lamson 7840 Southeast 20th Mercer Island, WA 98040
340, 440; T.C. 6A6	SA451EA	Cockpit voice recorder.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA454CE	Model CH 3002-3181 Hoover Aircraft Products evacuation chute.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
340, 440: T.C. 6A6	SA483EA	Installation of cabin window at F.S. 730.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440: T.C. 6A6	SA494EA	ADF-PA Interconnection.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440: T.C. 6A6	SA495EA	Installation of Flight Interphone System.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	ST519SO	Installation of underseat baggage restraint bars. Issued 11/1/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440; T.C. 6A6	SA542CE	Make and install horizontal stabilizer tips.	GL	12578	Auto-Craft Engineering 1904 N. Colorado Avenue Indianapolis, IN 46206
340, 440; T.C. 6A6	ST548SO	Installation of external induction ram air scoops. Issued 8/28/73.	SO	53788	Mackey International Airlines 500 S.W. 34 Street Fort Lauderdale, FL 33315
340, 440; T.C. 6A6	ST596SO	Installation of exhaust system bracket. Reissued 1/6/75.	SO	02394	Aeronautical Engineering, Inc. 342 N.E. 2nd Court Dania, FL 33004
340, 440; T.C. 6A6	SA604EA	Installation of United Control Model F542 Flight Data Recorder.	EA	09520	Allegheny Airlines Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA651EA	Installation of UHF/FM Secure System.	EA	52012	Lockheed Aircraft Service, Inc. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA695WE	Rain repellant system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA669WE	Smoke detector, flight data recorder, and oxygen breathing system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	ST700SO	Installation of exterior emergency lighting system. Amended 5/8/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440; T.C. 6A6	SA775WE	Interior.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505
340, 440; T.C. 6A6	SA780WE	Yoke assembly, pilot and copilot control.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA874WE	Shoulder harness installation. Amended 6/9/76.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90404
340, 440; T.C. 6A6	SA884EA	Installation of tail logo lights. Amended 10/19/71.	EA	18750	Butler Aviation Friendship, Inc. Sub. Butler Aviation International Friendship Int'l Airport Baltimore, MD 21240
340, 440; T.C. 6A6	SA896EA	Installation of Marshell interior kit assembly No. 96123. Amended 7/13/73.	EA	54200	Magee Plastics Company 6000 Babcock Boulevard Pittsburgh, PA 15237
340, 440; T.C. 6A6	SA908WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA925WE	Pitch servo of Sperry SP-20 autopilot system.	EA	16600	Bethlehem Steel Company 701 E. Third Street Bethlehem, PA 18016
340, 440; T.C. 6A6	ST926SO	Installation of cargo door and interior. Amended 7/18/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440; T.C. 6A6	ST927SO	Installation of cargo floor and a smoke detector system. Issued 5/5/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
340, 440; T.C. 6A6	SA1015WE	Modified fiberglass vertical stabilizer tip, and Grimes 9950-1 rotating beacon.	RM	37015	Frontier Airlines, Inc. Stapleton Int'lernational Airport Denver, CO 80207
340, 440; T.C. 6A6	SA1015EA	Installation of Atlantic Aviation Corp. (TSO C-39) attendant seat P/N 21.737. Issued 9/22/75.	EA	12500	Atlantic Aviation Corporation Greater Wilmington Airport Box 1709 Wilmington, DE 19899
340, 400 (580); T.C. 6A6	SA1027EA	Installation of Collins FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340/440 modified in accordance with STC SA4-1100; T.C. 6A6	ST1035SO	Installation of a combination passenger/cargo interior to include an all cargo, 44 passenger/cargo, 10 passenger/cargo, and 6 passenger/cargo configurations. Issued 12/4/78.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36302
340, 440; T.C. 6A6	SA1060WE	AP101E Collins autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA1096WE	Rolls Royce Dart 542-4 engines with Dowty Rotol (c) R245/4-40-4.5/13 or (c) R259/4-40-4.5/17 propellers and associated modifications. Amended 7/27/66.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1097SO	Installation of two (2) double seats to increase passenger configuration from 44 to 48. Issued 8/30/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
340, 440; T.C. 6A6	SA1119WE	Two additional emergency exits, and interior arrangement.	WE	37280	General Dynamics Conviar Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1132WE	Parker Aircraft, Inc. under-wing pressure refueling valve and Roylin "Magna-Stick" fuel indicator.	WE	06750	Aircraft Tack Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA1146WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA1174WE	Fuel jettison system.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA1218WE	Cargo floor, cargo door and forward service door.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1268WE	Interior and equipment.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505
340, 440; T.C. 6A6	SA1331WE	Installation of United Data Control, Inc. Model V-557 cockpit voice recorder system. Amended 3/28/67.	RM	37015	Frontier Airlines 5900 East 39th Street Denver, CO 80207
340, 440; T.C. 6A6	SA1338WE	Seat track, additional emergency exit and interior arrangement.	WE	37280	General Dynamics Corp. P.O. Box 1950 San Diego, CA 92112
340, 440; T.C. 6A6	SA1366WE	Installation of Collins Radio Company FD105 flight director system.	WE	37280	General Dynamics Convair Division P.O. Box 1950 San Diego, CA 92112
340, 440; T.C. 6A6	SA1407SW	Provide 52-passenger seat aircraft with cargo carrying capability by installing an aft cargo door and reinforcing the floor and fuselage shell. Amended 6/1/72.	WE	37280	General Dynamics Corporation Convair Aerospace Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1438WE	Installation of an Avionics System.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA1482WE	Installation of interior arrangement.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA1505WE	Installation of radio transformer rectifier for standby D.C. power.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA2302WE	Modification of pedestal flight idle stop and lift to reverse system. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA2697WE	Modification including those airplanes further modified per STC SA1096WE for turbo propeller power for installation of cargo door, cargo floor and cargo lining. Issued 5/25/73.	WE	10208	American Jet Industries, Inc. 2800 Clybourn Avenue Burbank, CA 90405
340, 440; T.C. 6A6	SA2733WE	Modification of Model 340/440 previously modified per STC SA4-1100 for turbo propeller power for installation of cargo door, cargo floor and cargo lining. Issued 9/5/73.	WE	10208	American Jet Industries, Inc. 2800 Clybourn Avenue Burbank, CA 91505
340,440; T.C. 6A6	SA2896SW	Conversion to an all-cargo configuration. Issued 1/15/79.	SW	08128	Airgo, Inc. LB-31 Love Field Terminal Bldg. Dallas, TX 75235
340,440; T.C. 6A6	SA2897SW	Composite flooring, one double seat, nonstructural bulkhead.	SW	08128	Airgo, Inc. LB-31 Love Field Terminal Bldg. Dallas, TX 75235
CV340/440; T.C. 6A6	SA3132WE	Installation of an alternate (printed circuits) ice protection system on the engine air intake. Amended 11/17/77. This installation is approved for use on airplanes modified in accordance with STC SA4-1100 only.	WE	71680	Sierracin/Thermal Systems 13920 South Broadway Los Angeles, CA 90061
340, 440; T.C. 6A6	SA3294WE	Modification by installation of dual mach/airspeed warning system. Reissued 1/20/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA3479WE	Modification by installation of an alternate pallet restraint system.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
340/440; T.C. 6A6	SA3574WE	Modification of Convair 340 or 440 which have been modified per STC SA4-1100. Issued 3/24/78.	WE	45500	Jay Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90904
340/440; T.C. 6A6	SA3758WE	Enlarge cargo door on aircraft modified per STC No. SA2733WE. Issued 10/17/78.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
340,440; T.C. 6A6	SA3772WE	Installation of cargo tie downs in aircraft modified per STC No. SA2733WE. Issued 11/1/78.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA
340, 440; T.C. 6A6	SA4075SW	BKM 100PHM-2 pitot head monitor system. Issued 1/17/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
440; T.C. 6A6	SA4-49	Two 250-gallon auxiliary fuel tanks in wing center section.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-195	Janitrol S-50 ground heater.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-196	Extended wing tank installation and oil tank rework.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-245	GTP-70-17 auxiliary gas turbine power plant.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-314	Cabin interior.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
440; T.C. 6A6	SA4-407	Andover Type D-2, Model V-32 APU for ground operation only.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-408	Interior arrangement installation (right hand forward cargo door made permanently inoperative as an exit by seating arrangement).	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-675	Oscillograph rack.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
440; T.C. 6A6	SA4-692	Interior equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-857	ARN-14 antenna.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-897	Window station 730 L.H.	WE	07500	AiResearch Aviation Service Co. 6021 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-930	Aircraft interior.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-1319	Bendix RDR-1D radar and equipment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-1428	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA195SW	Structural installation of Bendix ANA-12A-1 doppler antenna.	SW	12250	Associated Radio Service Co. 7515 Lemmon Avenue Dallas, TX 75220
440; T.C. 6A6	SA283WE	Interior and equipment installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA384EA	Two three-place couches.	EA	03100	Aero Trades, Inc. Long Island Airport Ronkonkoma, NY 11779
440; T.C. 6A6	ST929SO	Installation of a cargo door. Issued 5/10/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
ROY A. GOOD

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
8135 (Rearwin); T.C. 711	SA519WE	Wheel adapters on Goodyear wheels 3 LMBM.	WE	49345	Robert P. Lamb 2998 Daisy Avenue Long Beach, CA 90801
8135 (Rearwin); T.C. 711	SA784WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
8135 (Rearwin); T.C. 711	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
8135 (Rearwin); T.C. 711	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GOVERNMENT AIRCRAFT FACTORIES

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
N22B; T.C. A7PC	SA363GL	Convert the landplane to a seaplane by installing Wipline Model 9812 twin seaplane floats. Issued 9/12/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GREAT LAKES AIRCRAFT COMPANY, GEORGIA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
2T-1A; T.C. A18EA	SA941CE	Installation of engine, propeller and fuel system. Issued July 1973.	CE	39458	Great Lakes Aircraft Company P.O. Box 11132 Wichita, KS 67202
2T-1A, 2T-1A-1, 2T-1A-2; T.C. A18EA	SA1008WE	Installation of poly-fiber covering material of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GREAT LAKES AIRCRAFT COMPANY, OHIO

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
2T1 Series; T.C. A-167	SA1115WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
2T-1; 2T-1A; 2T-1E; ATC 167, 228, 354	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
2T-1, 2T-1A, 2T-1E; ATC 167, 228, 354	SA2666WE	Ceconite 102 material covering complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
2T-1A; T.C. 228	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GROUPEMENT d'INTERET ECONOMIQUE AIRBUS INDUSTRIE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Type A300 B2-1A, -1C, B2K-3C, B4-2C; T.C. A35EU	SA3721WE	Revision of Airbus Industrie A300 fire/overheat detection system to allow intermixing of Systron-Donner fire detectors with Edison fire detectors in the fan, core and pylon sections of CF6 engines. Issued 8/30/78.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
Type A300 B2-1A, -1C, B2K-3C, B4-2C; T.C. A35EU	SA3722WE	Installation of fire/overheat detection system. Issued 8/30/78.	WE	77300	Systron-Donner Corporation Safety Systems Division Berkeley, CA 94710

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GRUMMAN AIRCRAFT ENGINEERING CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F8F-2; T.C. AR-32	SA4-1447	Ceconite 101 covering of control surfaces and flaps.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
F8F-2; LTC 23, T.C. AR-32	SA49GL	Installation of reinforcement of wing center section lower spar cap. Issued 5/31/74.	GL	14300	G.W. Balz 4171 Lake Terrace Kalamazoo, MI 49008
F7F-3; T.C. AR-28	SA4-1439	Ceconite 101 covering of ailerons, elevators and rudder.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
F7F-3; F8F-2; T.C. AR-28, AR-32	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
F7F-3, F8F-2; T.C. AR-28, AR-32	SA2666WE	Ceconite 102 material covering of: F7F-3 - ailerons, elevators and rudder; F8F-2 - control surfaces and flaps; G-164A - vertical and horizontal tail and wings; G-164B - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
GRUMMAN AMERICAN AVIATION CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J2F Series; L.T.C. 17	SA1028WE	Ceconite 101 covering of wings, ailerons, rudder and elevators.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
J2F-3, -4, -5, -6, TBF-1-1C, -3, -3E, FM-2, G-21, -21A, G-44, -44A Scan Type 30; LTC-17, -8, -25, T.C. 654, 734	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Issued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J2F-3, -4, -5, -6, FM-2, G-21, -21A, G-44, -44A, SCAN Type 30, TBF-1, -1C, TBM-3, -3E; LTC 17, 25, T.C. 654, 734, LTC 8	SA2666WE	Ceconite 102 material covering of: J2F-3, -4, -5, -6 - wings, ailerons, rudder and elevators; FM-2 - all fabric-covered control surfaces; G-21, -21A - elevators, rudder, ailerons and wing trailing edge; G-44, -44A - rudder, elevators and ailerons; TBF-1, -1C, TBM-3, -3E - ailerons, rudder and elevators. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
TBF, TBM Series; LTC 8	SA4-911	Eonite covering on ailerons, rudder, elevators.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
TBF, TBM Series; LTC 8	SA4-1187	Ceconite 101 covering of ailerons, rudder and elevators.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
TBF, TBM Series; LTC 8	SA4-1504	Neoprene expander tube to replace piston brake seal.	WE	71640	Sierra Aviation Airport P.O. Box 21 Porterville, CA 93257
TBF, TBM, FM-2, G-21, G-21A; T.C. 654, LTC 8, LTC 25	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
FM-2; LTC 25	SA4-1613	Ceconite 101 covering of all fabric covered control surfaces.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
F8F-1; LTC 23	SA49GL	Installation of reinforcement of wing center section lower spar cap. Issued 5/31/74.	GL	14300	G.W. Balz 4171 Lake Terrace Kalamazoo, MI 49008
F8F-1; LTC 23	SA1008WE	Poly-Fiber covering of elevator and aileron. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
G-21 Series; T.C. 654	SA2317WE	Installation of dual brakes. Issued 2/24/71.	NW	53520	McKinnon Enterprises, Inc. Route 3, Box 690 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA1-3	Replacement of wing panel fabric by 025 aluminum, 24ST ALCLAD.	EA	56645	Mattituck Airbase Corporation Linden Airport Linden, NJ 07036
G-21, G-21A; T.C. 654	SA1-52	Installation of new propellers. Installation of emergency governor crossfeed system for unfeathering. Amended 10/23/67.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
G-21, G-21A; T.C. 654	SA4-591	Increased maximum weight capacity of bow compartment.	AL	08483	Alaska Coastal Airlines 2 Marine Way Juneau, AK 99801
G-21, G-21A; T.C. 654	SA4-677	Picture window.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-678	New nose.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-680	Windshield.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-21, G-21A; T.C. 654	SA4-681	Dorsal fin.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-682	Retractable float.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-683	Installation of auxiliary fuel tanks in outboard wing sections. Amended 6/25/68.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1055	Rotary beacon.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1109	Metqlizing of wings aft of spar.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1137	Ceconite 101 covering of elevators, rudder, ailerons and wing trailing edge.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
G-21, G-21A; T.C. 654	SA4-1467	Modification of increase maximum maximum weight to 9,200 lbs.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1550	Wing leading edge landing lights.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1551	Electric gear retract motor.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA99GL	Install Cleveland Wheel and Brake conversion kit P/N 199-65. Issued 12/3/75.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011
G-21, G-21A; T.C. 654	SA101WE	Picture window.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA108WE	Bulkhead station 26 flotation compartment.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA113SO	Replacement brake linings on Grumman G-29 main landing gear brake shoes. Amended 1/16/67.	SO	58708	Miami Brake & Clutch Service 3634 N.W. 36th Street Miami, FL 33101
G-21, G-21A; T.C. 654	SA138SW	Modifications to increase maximum weight to 9,000 pounds.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
G-21, G-21A; T.C. 654	SA355WE	Hull vents.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA551SW	Modification of Beech C18 cowl to fit Grumman G-21A.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
G-21, G-21A; T.C. 654	SA696WE	Aluminum skin on elevator control surface.	WE	49365	Lancer Engineering 26927 Fond Du Lac Road Palos Verdes Peninsula, CA 90274
G-21, G-21A; T.C. 654	SA1589WE	Installation of two United Aircraft of Canada, Ltd. Model PT6-20 engines.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21B; T.C. 654	SA96NW	Installation of Sorm Industries horizontal stabilizer forward support fitting. Issued 3/18/74.	NW	73820	Sorm Industries, Inc. 7999 West Perimeter Road Seattle, WA 98018
G-21A; T.C. 654	SA294AL	Installation of UACL model PT6A-20 engines.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
G-21A; T.C. 654	SA295AL	Installation of passenger seats. Amended 4/17/70.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-21A; T.C. 654	SA2298WE	Modification of Bendix master brake cylinder by installation of Griffco Aviation piston and O-rings in lieu of Bendix piston assembly P/N 52152. Issued 1/7/71.	NW	39492	Griffco Aviation 7580 Perimeter Road Boeing Field International Seattle, WA 98108
G-21A; T.C. 654	SA3630WE	Increase maximum weight to 8750 lbs. on aircraft equipped with Hartzell three bladed full feathering propellers (per STC SA1-52). Issued 4/5/78.	WE	20160	Catalina Airlines, Inc. Berth 95-95 P.O. Box 207 San Pedro, CA 90733

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GULFSTREAM AMERICAN CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-44, AA-1, AA-1A, AA-1B, AA-5, AA-5A; T.C. A-734, A11EA, A16EA	SA308EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 10/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
G-44; T.C. A-734	SA366AL	Installation of Cessna P/N 1223000-7 and -8 wing tips.	AL	05959	George Pappas Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
G-44; T.C. A-734	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines as equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/75.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
G-44; T.C. A-734	SA802EA	Installation of Win Air Service PT-T-4-1 rivets in Grumman Model 44 control surface ribs-elevator rudder and aileron, covered with Grade "A" cotton fabric.	EA	86420	Win Air Service Co., Inc. Hancock Airport Syracuse, NY 13211
G-44; T.C. A-734	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-44, G-44A, SCAN 30; T.C. 734	SA1-199	Fabrication and installation of rear picture windows change.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
G-44, G-44A, SCAN 30; T.C. 734	SA1-283	Stewart-Warner 940 Series heater.	EA	51040	Link Aeronautical Corporation Tri-Cities Airport Endicott, NY 13760
G-44, G-44A, SCAN 30; T.C. 734	SA1-566	Stewart-Warner, 940-F12 or 940F-24 heater in front compartment between stations 4 and 5.	EA	51040	Link Aeronautical Corporation Tri-Cities Airport Endicott, NY 13760
G-44, G-44A, SCAN 30; T.C. 734	SA4-2	Lycoming R-680-E Series engines and Hartzell 93Z propellers. Reissued 3/17/67.	SO	37084	Gander Aircraft 3923 N.W. 24th Street Miami, FL 33142
G-44, G-44A, SCAN 30; T.C. 734	SA4-53	Hull compartment modification. Reissued 3/17/67.	SO	37084	Gander Aircraft 3923 N.W. 24th Street Miami, FL 33142
G-44, G-44A, SCAN 30; T.C. 734	SA4-60	Landing gear modification. Reissued 3/17/67.	SO	37084	Gander Aircraft 3923 N.W. 24th Street Miami, FL 33142
G-44, G-44A, SCAN 30; T.C. 734	SA4-61	Hull compartment modification. Reissued 3/17/67.	SO	37084	Gander Aircraft 3923 N.W. 24th Street Miami, FL 33142
G-44, G-44A, SCAN 30; T.C. 734	SA4-62	Auxiliary wing fuel tanks.	WE	62068	Pacific Aircraft Eng. Corp. 10556 Keswick Street Sun Valley, CA 91352
G-44, G-44A, SCAN 30; T.C. 734	SA4-63	Emergency exit in right-hand side of hull.	WE	48508	Charles M. Kirk 1013 Orange El Rio, CA 93030
G-44, G-44A, SCAN 30; T.C. 734	SA4-64	Lycoming GO-435-C2B engines, and Hartzell HC-82X20-2A/9333C-3 or HC-83X20-2A/8433-0 propellers.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-65	Lycoming GO-480-B1B engines and Hartzell HC-83X20-2A/8433-0 propellers.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-44, G-44A, SCAN 30; T.C. 734	SA4-67	Window in right-hand side of hull.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-85	Manually operated landing gear locks.	NW	18180	F.K. Brunton 1416 148th NE Bellevue, WA 98004
G-44, G-44A, SCAN 30; T.C. 734	SA4-111	Lycoming GO-480-C1D6 engines, and Hartzell HC-83X20-2A/8433-0 propellers.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-297	Elevator trim tab setting changed to 22 degrees up and 17 degrees down.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-755	Ceconite 101 covering of rudder, elevators and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
G-44, G-44A, SCAN 30; T.C. 734	SA4-773	Metal skin aft of rear spar and fuel tank access door.	WE	62068	Pacific Aircraft Eng. Corp. 10556 Keswick Avenue Sun Valley, CA 91352
G-44, G-44A, SCAN 30; T.C. 734	SA4-774	Metal skin on flaps.	WE	62068	Pacific Aircraft Eng. Corp. 10556 Keswick Avenue Sun Valley, CA 91352
G-44, G-44A, SCAN 30; T.C. 734	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
G-44, G-44A, SCAN 30; T.C. 734	SA4-928	Retractable tip float.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-958	Increase in main fuel tank capacity to 88 gallons in each wing.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-959	Stewart-Warner heater.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-960	Metalizing of flaps.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-961	Metal cabin door and frame assembly.	NW	53520	McKinnon Enterprises, INc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-963	Rotary beacon.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-964	Landing light assembly.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-966	Rudder and elevator control cable reroute.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-967	Picture window and escape hatch.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-970	Four Teco TE-432 seats.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-1001	Spray rail.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA4-1031	Metalizing of wings aft of spar.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA5-51	Picture windows.	AL	05958	Aircraft Rebuilders 1803 Lake Otis Road Anchorage, AK 99501
G-44, G-44A, SCAN 30; T.C. 734	SA5-58	200 pound baggage compartment in bow.	AL	48558	Kodiak Airways, Inc. P.O. Box 1065 Kodiak, AK 99615

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G44, G44A, Modified -- Colemill STC 2-13; T.C. A-734	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 1/19/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
G-44, G-44A, SCAN 30; T.C. 734	SA618W	Horizontal stabilizer raised 5/8 inch per STC SA2-13.	SW	52870	J.R. McDermott & Company, Inc. Lakefront Airport New Orleans, LA 70113
G-44, G-44A, SCAN 30; T.C. 734	SA121EA	Wheel 40-46 and brake 30-31.	GL	23250	The Cleveland Aircraft Products Company P.O. Box 158 Avon, OH 44011
G-44, G-44A, SCAN 30; T.C. 734	SA380WE	Engine, propeller and associated modifications of nacelle, electrical oil, fuel and vacuum systems.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA603WE	Large aft door. Reissued 3/17/67.	SO	37084	Gander Aircraft 3923 N.W. 24th Street Miami, FL 33142
G-44, G-44A; T.C. 734	SA835SO	Installation of Lycoming GO-480-G2D6 engines with Hartzell HC-A3VF-5R/V9333CH-3 reversing propellers. Reissued 10/9/79.	SO	02330	AEROMAR, Inc. 317 North Coconut Lane Palm Island Miami, FL 33139
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3174SW-D	Automatic flight system AK645 consisting of Century I autopilot with optional omni tracker system. Issued 1/31/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3175SW-D	Mitchell automatic flight system AK646 consisting of Century IIB autopilot with optional radio coupler. Issued 1/31/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3176SW-D	Mitchell automatic flight system AK647 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/17/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3184SW-D	Automatic flight system AK656 consisting of Century I autopilot with optional omni tracker. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3185SW-D	Mitchell automatic flight system AK657 consisting of Century IIB with optional radio coupler. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3186SW-D	Automatic flight system AK658 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Scan Type 30; T.C. A734	SA3221SW-D	Mitchell automatic flight system AK706 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 6/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Scan Type 30; T.C. A734	SA3222SW-D	Mitchell automatic flight system AK705 consisting of Century IIB autopilot with optional radio couplers. Issued 7/8/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44, G-44A; T.C. A-734	SA3979WE	Installation of Silver Instruments fueltron 111G digital fuel flow and totalizer system. Issued 6/15/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
G-73; T.C. 783	SA1-490	Opening in leading edge of right-hand wing for passing light installation.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
G-73; T.C. 783	SA1-546	Type 21 pump type pneumatic deicer system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
G-73; T.C. 783	SA3-22	Hull step fairing.	GL	17190	Briggs Manufacturing Company 6600 East Outer Drive Warren, MI 48089

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-73; T.C. 783	SA3-165	Two 100-ampere Eclipse 30E16-1 generators.	GL	37808	General Motors Air Transport City Airport Detroit, MI 48202
G-73; T.C. 783	SA3-194	Sonotone sintered-plate Alkaline Nickel-Cadmium battery.	GL	71520	George W. Sherwood City Airport Detroit, MI 48233
G-73; T.C. 783	SA4-1554	Structure modification to improve access to fuel tanks for stripping and resealing.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-73; T.C. 783	SA292EA	Pump type pneumatic deicer system.	GL	38500	B.F. Goodrich Airport Operations Municipal Airport Akron, OH 44318
G-73; T.C. 783	SA310EA	Fabrication of new passenger seats and necessary cabin interior modifications. Amended 4/5/68.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
G-73; T.C. 783	SA319SW	Structural installation of McMillan 7501XM radome and RCA AVQ-55 antenna mount.	SW	12250	Associated Radio Service Company 7515 Lemmon Avenue Dallas, TX 75220
G-73; T.C. 783	SA614SO	Installation of nose wheel shimmy damper IAW Gander drawings GA-2055 Chg. A and GA-2056 Chg. A.	SO	37084	Gander Aircraft Corporation 3923 N.W. 24th Street Miami, FL 33142
G-73; T.C. 783	SA1008WE	POly-Fiber covering of rudder. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
G-73; T.C. 783	SA2323WE	Increase in gross weight and installation of United Aircraft of Canada, Ltd., PT6A-27 engines. Amended 12/18/73.	WE	36699	Frakes Aviation, Inc. P.O. Box 159 Angwin, CA 94508
G-164; T.C. 1A16	SA4-1017	Lycoming R680-13 engine and Hamilton Standard 2B20-329/6135A-9 propeller.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA4-1019	Pratt & Whitney R-985-ANI, -NAS, -AN-14BMI, -39 or -39A engines and Hamilton Standard 2D30-277/6101A-12 to -18 propellers. Amended 9/30/65.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA32NW	Installation of 15.5 gallon auxiliary fuel tank in each upper wing panel. Amended 6/30/77.	NW	52066	Russell Longnecker Box 77 Mt. Vernon, WA 98273
G-164; T.C. 1A16	SA39WE	Pratt & Whitney R985-AN-3 engine and Hamilton Stnadard 2D30-227/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164; T.C. 1A16	SA170SW	Sensenich 5404R/MA96K propeller.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA287SW	Jacobs R-755-L4MB or R-755-B2M engine.	SW	52610	Lyon Flying Service, Inc. P.O. Box 726 Welsh, LA 70591
G-164; T.C. 1A16	SA312SW	Jacobs R-755-B2MI, R-755-B2M, L4M Series, R-755-A2M, or R-755-A2MI engine with short mount A1681, carburetor air filter box, funnel A1667, and Sensenich J5404/MA96K propeller.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA326CE	25-gallon auxiliary fuel tank on wing.	CE	59315	Mid-Continent Aerial Sprayers, Inc. P.O. Box 307 Hayti, MO 63851
G-164; T.C. 1A16	SA507SW	Optional 46-gallon wing center section fuel tank and alternate right-hand or left-hand carburetor muffs equipped with Jacobs L4M and R-755 series engine.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA647WE	Modified landing gear.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA648WE	Additional flying wire.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-164; T.C. 1A16	SA651WE	Modified wheels and brakes.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA1278WE	Ceconite 101 covering of wings and ailerons.	WE	26240	Cooper Engineering Corporation P.O. Box 3428 Van Nuys, CA 91408
G-164; T.C. 1A16	SA1295WE	Automatic flagman marker dispensing unit.	NW	03500	Air-Ag, Inc. Route 4 Walla Walla, WA 99362
G-164; T.C. 1A16	SA1407WE	Installation of Pratt & Whitney R-985-AN-1 engine and Hamilton Standard 2D30/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164; T.C. 1A16	SA1586WE	Installation of Pratt & Whitney R-1340-AN-1 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164, G-164A; T.C. 1A16	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
G-164, G-164A; T.C. 1A16	SA270WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller. Amended 7/11/68.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164, G-164A; T.C. 1A16	SA406NW	Installation of wing span extension. Amended 5/23/77.	RM	02360	Aero Mod General, Inc. Box 68 Latah, UT
G-164, G-164A; T.C. 1A16	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
G-164, G-164A; T.C. 1A16	SA940SW	Installation of Micronair AU-3000 spray units. Reissued 10/2/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164, G-164A; T.C. 1A16	SA1282SW	Jacobs-Page R-755SM engine and Grumman 5404/M96K propeller. Reissued 5/24/77.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
G-164 (S/N 301-400), G164A (S/N 400 and up); T.C. 1A16	SA1312WE	Fabrication and installation of 285-gallon fiberglass hopper (replaces 245-gallon metal hopper). Reissued 6/12/75.	GL	39542	Grumman American Aviation 318 Bishop Road Cleveland, OH 44143
G-164, G-164A; T.C. 1A16	SA1319CE	Chrome plated brake disc installation. Issued 7/22/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
G-164, G-164A; T.C. 1A16	SA1777WE	Installation of Hamilton Standard 3D40/6101A-17 propeller.	WE	85125	Western Aircraft Sales P.O. Box 753 Long Beach, CA 90801
G-164, G-164A; T.C. 1A16	SA2012WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	17022	Bowles Flying Service Route 1, Box 124-B Live Oak, CA 95953
G-164, G-164A, G-164B; T.C. 1A16	SA832SO	Installation of Hamilton Standard Model 2D30/6101A-10S propeller. Amended 10/15/76.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164, G164a, G-164B; T.C. 1A16	SA1427CE	Install smoke generator for Part 137, agricultural aircraft operations, only. Issued 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508 Renner Field Goodland, KS 67735
G-164, G-164A, G164B; T.C. 1A16	SA3077WE	Installation of elevator servo-tab. Reissued 3/17/77.	WE	26540	Robert L. Copeland 171 West Shannon Chandler, AZ 85224
G-164, G-164A, G-164B, G-164C; T.C. 1A16	SA2747SW	Lockable full swivel tail wheel. Issued 4/6/78.	SW	36700	Frakes Aviation Cleburne Airport Rt. 3, Box 229-B Cleburne, TX 76031
G-164A; T.C. 1A16	SA99NW	Installation of HSP 3D40-401 hub with EAC-100-2 blades. Issued 3/29/74.	NW	33000	Efficiency Aircraft P.O. Box 37 Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-164A; T.C. 1A16	SA445NW	Installation of EAC-22D30-AG-200-4S prop or P&W R-985-AN-1 engine. Issued 5/9/77.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A; T.C. 1A16	SA809SW	Installation of 5-inch longer engine mount in S/N 401 and up. Reissued 9/25/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164A; T.C. 1A16	SA833SO	Installation of Hamilton Standard Model 12D40/6101A-10S propeller approved under STC SP830SO on Pratt & Whitney R1340-AN-1, S1H1 or S3H1 engines listed in TDS 1A16. Issued 4/28/75.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164A; T.C. 1A16	SA994SW	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101-12 propeller. Reissued 4/19/73.	GL	39542	Grumman American Aviation Corp. 318 Bishop Road Cleveland, OH 44143
G-164A, S/N 526 and up with a P & W R-1340-AN-1 engine and Hamilton Standard 12D40 propeller; T.C. 1A16	SA1077CE	Installation of Edo-Aire propeller governor. Issued January 1975.	CE	32500	Edo-Aire, Inc. Wichita Division 1326 S. Walnut Street Wichita, KS 67213
G-164A; T.C. 1A16	SA1222SW	64-gallon or 80-gallon fuel tanks. Issued 11/17/70.	EA	39540	Grumman Aerospace Corporation P.O. Box 147 Elmira, NY 14902
G-164A; T.C. 1A16	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 7/24/73.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-164A; T.C. 1A16	SA1422SW	Paper filter for engine induction. air. Issued 1/19/72.	SW	17260	Frank Brinster 2214 North Parkwood Harlingen, TX 78550
G-164A; T.C. 1A16	SA2015WE	The 12-volt or 24-volt D.C. electrical generating system is replaced by an alternator system. Amended 12/21/78.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
G-164A; T.C. 1A16	SA2356SW	Wing tip extension of 20 inches. Issued 9/14/76.	SW	34405	Fram & Ranch Aerial Service Wharton, TX 77055
G-164A; T.C. 1A16	SA2444SW	Install P&W ACL PT6A-34 engine. Issued 12/2/77.	SW	36700	Frakes Aviation, Inc. Route 2, Box 229-B Cleburne Airport Cleburne, TX 76031
G-164A; T.C. 1A16	SA2731SW	PZL-3S engine and Dowty-Rotol propeller CR 289/3-110-F/1. Issued 3/17/78.	SW	52610	Lyon Flying Service, Inc. P.O. Box 726 Welsh, LA 70591
G-164A, G-164B; T.C. 1A16	SA78RM	Installation of air conditioner system. Amended 6/21/77.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
G-164A, G-164B; T.C. 1A16	SA434NW	Installation of EAC-12D40-AG-100S-4S prop on Pratt & Whitney R-1340-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA436NW	Installation of WAC-2D30-425-AG-100-4A prop on Pratt & Whitney R-985-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA1129SO	Installation of a 320 gallon agricultural spary dispensing hopper. Issued 1/24/80.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701
G164A, G164B; T.C. 1A16	SA2666WE	Ceconite 102 material covering of: G-164A - vertical and horizontal tail and wings; G-164B - complete aircraft. Amended 4/19/78.	WE	20250 4677	Ceconite, Inc. Worth Street Los Angeles, CA 90063
G-164B; T.C. 1A16	SA1102SO	Manufacture and installation of a 360 gallon agricultural spray dispensing hopper. Issued 10/10/79.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701
G-164B (Restricted Category); T.C. 1A16	SA3876WE	Installation of Alvis Leonides engine and Dowty Rotol (c)R284/3-20-3/8 constant speed propeller. Issued 3/6/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Morteson Avenue Salinas, CA 93905

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-164C (Restricted Category); T.C. 1A16	SA3764WE	Installation of Wright R-1820-71 engine and Hamilton Standard 43D50 or 33D50 constant speed propeller. Amended 4/13/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Morteson Avenue Salinas, CA 93905
AA-1 Series; T.C. A11EA	SA809NW	Installation of fixed (flush) cowl flap, nose gear strut fairing and retainer. Issued 7/20/79.	NW	27241	Maynord C. Corsby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1 Series; T.C. A11EA	SA810NW	Installation of main landing gear fairings from the AA-5 series aircraft incorporating sheet metal covers over rubber in place of stock rubber parts. Issued 7/20/79.	NW	27241	Maynord C. Crosby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1; T.C. A11EA	SA1410SW	Mitchell automatic flight system AK301, consisting of Century I autopilot with optional omni tracker. Issued 12/28/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-1; T.C. A11EA	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
AA-1; T.C. A11EA	SA2104WE	Installation of Brittain Models B2C and BSS flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
AA-1; T.C. A11EA	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1010CE	Installation of wing leading edge cuffs. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1313CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-1, AA-1A, AA-1B; T.C. A11EA	SA3234WE	Installation of Piper oil cooler and associated installation components. Issued 7/8/76.	WE	05390	Aircraft Maintenance Service 7950B Joe Crosson Drive Santee, CA 92071
AA-1 (1969 and on), AA-1A (1969 and on), AA-1B (1969 and on), AA-5 (1972, 1973 and 1974 only); T.C. A16EA	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
AA-1, AA-1A, AA-1B, AA-5; T.C. A11EA, A16EA	SA71GL	Installation of P/N BA4210 filter assembly. Issued 12/29/77.	WE	17062	Brackett Specialties Company 4910 East Falcon Drive Mesa, AZ 85205
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
AA-1; AA-5; T.C. A11EA, A16EA	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1B; T.C. A11EA	SA10NW	Installation of VA-3 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-1B; T.C. A11EA	SA11NW	Installation of VA-2 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	VAn's Aircraft Route 2, Box 187 Forest Grove, OR 97116

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AA-1C Utility Category; T.C. A11EA	SA3695WE	Installation of Lycoming 0-235-C2C engine and McCauley 1A105/SCM7154 propeller. No installation data required. Placards required with this installation: At the fuel filler caps - "80/87 MIN OCTANE AVGAS" Issued 7/7/78	WE	03105	Aero-Training, Inc. 89 John Glenn Drive Concord, CA 94520
AA-5; T.C. A11EA	SA66NW	Installation of VA-4 fiberglass wheel fairings. Issued 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-5; T.C. A16EA	SA1472SW	Mitchell automatic flight system AK374 consisting of Century IIB autopilot with optional omni tracker. Issued 6/28/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5; T.C. A16EA	SA1486SW	Mitchell automatic flight system AK373 consisting of Century I autopilot with optional radio coupler. Issued 5/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5, -5A, -5B; T.C. A16EA	SA1314CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-5B; T.C. A16EA	SA3031SW-D	Mitchell automatic flight system AK514 consisting of Century I autopilot with omni tracking system. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5B; T.C. A16EA	SA3032SW-D	Mitchell automatic flight system AK515 consisting of Century IIB autopilot with optional radio coupler. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5B; T.C. A16EA	SA3301WE	Installation of Model EGT-1 exhaust gas temperature monitoring system. Issued 11/23/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
AA-5B; T.C. A16EA	SA3309WE	Modification of primary control system by addition of rudder-aileron interconnect and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/27/77.	WE	12250	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
G-159; T.C. 1A17	SA1-399	Forward and aft attacnment for HF antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-400	Bendix radar scanner attaching brakcets and electrical cable firewall plugs.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-401	Glide slope antenna mounting bracket.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-402	Installation of 37K-2 Marker Beacon Antenna. Amended 7/24/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-403	Fabrication of mounting blocks and installations of Lear sense antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-404	Fabrication and installation of adaptor for mounting Chance Vought seat 22-93597-B-2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-405	DL-1 loop assembly.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-406	Collins 37R-2 antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-407	AC Spark Plug Division FM telephone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-408	Radio equipment shelves.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA1-412	Bulkhead at station 193.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-413	Double-hinged door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-414	Bulkhead and door at station 232.5.	EA	23600	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-415	Bulkhead and door at station 485.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-417	Baggage compartment smoke detector system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-420	AC Spark Plug Division FM telephone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-421	Bendix LPA-70C loop antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-432	High frequency antenna. Amended 1/25/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-447	Bulkhead and door at station 251.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-448	Bulkheads at stations 183 and 239 and baggage shelf.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-449	Bulkhead and door at station 493.	EA	12500	Atlantic Aviation Corporation P.O. Bos 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-450	Partial bulkhead at station 223.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-465	Bulkhead at station 232.5.	EA	12500	Atlantic Aviation Corporation P.O. box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-466	Bulkhead at station 257.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-472	Installation of Atlantic Aviation Corporation's TSO-C39 seat model "Retractable Seat --G II." Amended 1/13/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-493	Telectro AT-134-A marker antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-494	Collins 013107800 transponder antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-495	Collins 537F-1 radar scanner.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-498	Automatic flight control systems.	CE	24250	Collins Radio Company 855 35 Street, N.E. Cedar Rapids, IA 52401
G-159; T.C. 1A17	SA1-505	Two internally-mounted Aerojet-General 15KS-1000 A1 aircraft rocket engines in rear wing fillet.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361
G-159; T.C. 1A17	SA4-931	Avionics racks.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-932	Jump seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA4-942	Cabin oxygen supply system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa MOnica, CA 90405
G-159; T.C. 1A17	SA4-968	Divan.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-969	Swivel seat, fuselage station 133.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-972	L-102B autopilot.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
G-159; T.C. 1A17	SA4-976	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-991	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1000	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1015	Interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1048	Avionics racks to fuselage station 193.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1049	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1051	Oxygen breathing system applicable to altitude up to 30,000 feet.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1057	Anti-collision light.	GL	12488	Atkins Light Corporation 7636 Lyndale Avenue, South Minneapolis, MN 55401
G-159; T.C. 1A17	SA4-1058	Interior and equipment.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1068	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1087	Cabin interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1098	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1115	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1123	Interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1125	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1168	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1267	Cabin interior furnishings and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1293	General Electric 20M63C8 generator.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1320	Interior modification including passenger oxygen system and baggage compartment smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA4-1379	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1381	Interior modification.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1445	Modification to Bendix DRA-12 doppler radar.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
G-159; T.C. 1A17	SA4-1481	Cabin interior furnishings and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1497	Ten-passenger interior arrangement, system, and aft baggage compartment smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1580	Auxiliary power unit modification (GTCP 85-91C and/or GTC 85-291C installation). Amended 6/2/66.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1581	Interior modification including three swivel seats for authorized crew members only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1582	Third crew member seat.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA11EA	Fabrication and installation of baggage compartment storage shelves.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA12EA	Bulkhead and door at station 251.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA16EA	Fabrication and installation of an Avionics bracket under the floor.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA16GL	Incorporating AMF (Leland) inverters MGE 23-3 or MGE 23-400. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
G-159; T.C. 1A17	SA56WE	Interior and distance measuring equipment system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA60EA	Collins 237Z-1 antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA66EA	Fabrication and installation of a two-place seat.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA72WE	Interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA81EA	Fabrication and installation of bracketry for mounting a Collins 537F-8 radar scanner.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA88EA	Installation of a bulkhead and door at station 392.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA96EA	Wilcox electric transponder antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA98EA	Antenna masts.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA101EA	Skyphone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA106EA	Bulkhead and door at station 244.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA110WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA122EA	Atkins anti-collision light system control wiring changes, per STC SA4-1057.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA122CE	Install Hoskins supplementary light system consisting of Model A wing tip lights, or Model C or 2 tail light optionally, two of Model fuselage lights with M-3 or M-5 power supply. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
G-159; T.C. 1A17	SA131EA	Modification of extraction section of Vickers-Armstrongs, Ltd. engine mount attachment pin, 60216.	EA	52064	Robert Long and Ray Williams 49 Champ Avenue Pearl River, NY 10965
G-159; T.C. 1A17	SA138EA	Collins 137A-4 ADF fixed loop antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA141WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA147EA	Bulkhead and door at Station 487 and fore and aft bulkhead at Station 525.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA148EA	Bulkhead and door at Station 232.5 to Station 242.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA150WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA156EA	Kollsman 1708-01 sextant mount in ditching hatch.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA168EA	Bulkhead and door at fuselage Station 192.375. Amended 3/17/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA174GL	Modification of floor support between stations 228.5 and 353 to eliminate decrease in allowable floor loading with increased zero fuel weight. Issued 5/12/77.	GL	90135	Zantop Airways, Inc. Detroit Metro Airport Detroit, MI 48242
G-159; T.C. 1A17	SA187EA	Bulkhead and door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA203EA	Two place seating capacity in cabin.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA218EA	Bulkhead and door at Station 232.5 - 226.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA267EA	Bulkhead and door at Station 487. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA282EA	Under-the-floor rework between fuselage stations 416 and 525 for divan installation.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA288EA	Executive interior and communication/navigation equipment.	EA	78510	Timmins Aviation, Ltd. Montreal International Airport Dorval, P.Q., Canada
G-159; T.C. 1A17	SA296WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA297GL	Installation of single Canadian Marconi CMA-734 Omega/VLF navigation system. Issued 3/21/79.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA302WE	Incorporation of Napier Spraymat de-icing (as manufactured by applicant) externally on Rotol propeller spinner as an alternate to Dowty Rotol internal elements. Reissued 10/22/70.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
G-159; T.C. 1A17	SA314EA	Door in bulkhead at Station 525.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA315EA	Bulkhead and door at Station 232.5 - 226.5. Amended 3/17/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA340EA	3051 replacement radome. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
G-159; T.C. 1A17	SA352WE	Interior.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA370EA	Main landing gear nutcracker microswitch assembly relocated.	EA	86200	George R. Williams 49 Champ Avenue Pearl River, NY 10965
G-159; T.C. 1A17	SA373EA	Two three-place couches and oxygen provisions.	EA	03100	Aero Trades, Inc. Long Island Airport Ronkonkoma, NY 11779
G-159; T.C. 1A17	SA376GL	Reduction of maximum zero fuel gross weight. Issued 11/26/79.	GL	91034	Zantop Airways, Inc. Detroit Metro Airport Detroit, MI 48242
G-159; T.C. 1A17	SA389WE	11-passenger interior and equipment installation including dual Collins DF-203 ADF receivers and dual Collins MC-102 gyrosyn compasses.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA394SW	HF-G overspeed warning system.	SW	40000	The Hamilton Company 106 Neunaus Street Houston, TX 77002
G-159; T.C. 1A17	SA399WE	Maximum allowable airspeed indicator.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA406SW	Engine breather drain extension with fairing.	SW	11604	Arco Sheet Metal Company 8346 Lockheed Houston, TX 77002
G-159; T.C. 1A17	SA427SW	To install brackets for the installation of 2 each ADF loops, 1 each marker antenna, 4 each cabin speakers, 2 each cockpit speakers, and to install 4 each ADF sense antenna mounting brackets. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91502
G-159; T.C. 1A17	SA435SW	To fabricate wiring harness and make complete radio, radar installation. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-159; T.C. 1A17	SA437SW	Fabrication and installation of radio rack. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-159; T.C. 1A17	SA448WE	Interior.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA486WE	11-passenger interior and equipment installation including Collins flight director system (dual), radio magnetic indicator switching, plus DME and ATC transponder systems.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	ST512SO	Installation of cargo door and nets. Reissued 9/20/74.	EA	18750	Butler Aviation Baltimore/Washington Int'l Airport Baltimore, MD 21240
G-159; T.C. 1A17	SA541EA	Installation of new nose section, new nose gear, cabin interior and AiResearch GTC Model No. 85-134.	EA	39540	Grumman Aircraft Engineering Corp. Bethpage, L.I., NY 11714

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA571SW	Collins radio altimeter system.	SW	12250	Associated Radio Service P.O. Box 20718 Dallas, TX 75221
G-159; T.C. 1A17	SA577EA	Installation of a 3-position fuel filter heat valve and control system for each engine.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA623WE	Eighteen-occupant interior with Atlantic Aviation jump seat for an additional crew member.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA636EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA637EA	Installation of Collins 621A-3 transponder.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA638EA	Installation of Collins 860E-2 DME.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA664EA	Installation of Sperry G-11B Gyro Compass System.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA665EA	Installation of Bendix DMA-29A DME System.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA666EA	Installation of Bendix TRA-61A transponder system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA667EA	Installation of Bendix MKA-28C marker beacon receiver.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA668EA	Installation of Frieden Type B-5 Driftmeter.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA723WE	12-passenger interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA730WE	12-passenger interior arrangement.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA735WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA761WE	13-passenger interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	ST762SO	Installation of main cabin floor support structure. Issued 8/19/77.	SO	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST763SO	Installation of courier seat and cockpit/main cabin partition. Issued 8/19/77.	SO	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST764SO	Enlarged passageway in FS525 main cabin bulkhead. Issued 8/19/77.	SO	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
G-159; T.C. 1A17	SA807SW	FD108/AP103E/F Flight Director-Autopilot combination for Category II operation.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA838WE	Shelf and webbing in baggage compartment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA839WE	Lavatory external service pen.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA879WE	Two radar altimeter antennas.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA886WE	Honeywell aircraft recognition light system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA888EA	Installation of Grimes three light strobe kit 34-0303-1 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
G-159; T.C. 1A17	ST889SO	Installation of Collins ground proximity warning system. Issued 3/16/76.	SO	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-159; T.C. 1A17	SA893SW	Dual FD-109 Flight Director/AP-104 Autopilot, 54W-1C Comparator Warning, AL-101 Radio Altimeter, MC-102 Compass, 51RV-1, VOR/ILS, 51Z-4 Marker, 860E-2 DME and DF-203 ADF systems.	SW	24252	Collins Radio Company Avionics System Center P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA998CE	Installation of battery temperature monitor and over temperature warning system.	CE	05250	Aircraft Instrument and and Development, Inc. 317 E. Lewis Wichita, KS 67202
G-159; T.C. 1A17	ST998SO	Installation of Bendix ground proximity warning system. Issued 6/24/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-159; T.C. 1A17	SA1034EA	Installation of Safeway de-icer overshoes P/N 5651 and/or Semsa leads P/N S.2002 on Dowty Rotol propeller model R184/4-30-4/50 with blades P/N R.A25907. Issued 3/22/76.	EA	70830	Semsa, Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779
G-159; T.C. 1A17	SA1050SO	Replace existing nickel cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
G-159; T.C. 1A17	SA1098WE	EGT and r.p.m. indicator for APU, Model GTC 85-37.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1137EA	Installation of the Global GNS-500A Omega navigation system. Issued 1/12/79.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-159; T.C. 1A17	SA1284WE	Kollsman MS28011-2 sextant.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1318WE	Lear Siegler, Inc. 510K autopilot system.	WE	07500	AiReserach Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1536SW	Foxtronics TRAMM BTI-600 nickel-cadmium battery temperature system. Issued 11/10/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
G-159; T.C. 1A17	SA1559SW	Semi-automatic fuel trim system. Issued 12/4/72.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159; T.C. 1A17	SA1678SW	Modification of Burns BH 1600 (P/N 908-2-1 and -2) double seats. Issued 6/20/73.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1709SW	Oxygen service installation. Issued 7/31/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-159; T.C. 1A17	SA1745SW	ANS-70A Area Navigation System. Issued 2/21/74.	SW	24252	Collins Radio Company 1200 N. Alma Road Richardson, TX 75207
G-159; T.C. 1A17	SA1763SW	Modification to Burns BH1600 double seats to aft facing. Issued 11/14/73.	SW	84600	Ward Int'l Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1964WE	Installation of jump seat.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA2629WE	Installation of single point refueling system. Issued 1/8/73.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA3044WE	Installation of fuel tank interconnect system. Issued 7/9/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-159; T.C. 1A17	SA3641WE	Installation of DeVore Aviation Corp. horizontal stabilizer mounted vertical tail flood lights. Issued 6/21/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
G-159, G-1159; T.C. 1A17, A12EA	SA10NE	Installation of a "back-up" passenger seat restraing system. Amended 3/30/78.	NE	69850	S.A.G.E. Corporation Burlington Int'l Airport Burlington, VT 05401
G-159, G-1159; T.C. 1A17, A12EA	SA1082SW	Revise nose gear steering cockpit control by installing BKM Guidemaster.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159, G-1159; T.C. 1A17, A12EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
G-1159; T.C. A12EA	SA23NE	Installation of aluminum grating on cargo door at fuselage station 539.75. Issued 3/27/78.	NE	69850	S.A.G.E. Corporation Burlington International Airport Burlington, VT 05401
G-1159; T.C. A12EA	ST222GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
G-1159; T.C. A12EA	SA272GL	Installation of Intercontinental Dynamics Corp. engine vertical scale instruments. Amended 12/5/78.	EA	44160	Intercontinental Dynamics Corp. 170 Coolidge Avenue Box 81 Englewood, NJ 07631
G-1159; T.C. A12EA	ST566SO	Installation of Bendix RNS-3400 area navigation system. Amended 5/23/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA579EA	Installation of a custom interior.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA606EA	Installation of shelf and bracketry at fuselage station 743.0 - 769.62, replace metal skins with fiberglass between fuselage station 813.31 and 855.00 and bracketry provisions between fuselage station 812.50 and 826.50.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA607EA	Manufacturing and installation of partition and door blow out provisions. Amended 12/29/69.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA608EA	Installation of dual Sperry SPI-73E flight director.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA618EA	Installation of Atlantic Aviation Corporation's TSO'd retractable seat, Type G11. Amended 6/17/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA623EA	Installation of bulkhead door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA624EA	Installation of bulkhead and bulkhead door at fuselage station 194.25.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA625EA	Installation of bulkhead and bulkhead door at fuselage station 503.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA626EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. Reissued 6/3/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA627EA	Installation of Collins 54W-1 comparator warning system. Amended 12/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA628EA	Installation of Collins AL-101 radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA629EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA630EA	Installation of Sperry C-11B gyro compass system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA631EA	Installation of dual Collins F.D. 109G flight director systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA632EA	Installation of Pyrotector smoke detector system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA633EA	Installation of constant flow passenger oxygen system. Amended 12/5/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA645EA	Installation of structural provisions for the Collins doppler DH-101.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA649EA	Installation of Litton LTN-51 inertial navigation system. Amended 12/11/68.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA654EA	Installation of Honeywell hi-intensity recognition lights. Reissued 11/12/68.	GL	42250	Honeywell, Inc. 2600 Ridgway Road Minneapolis, MN 55413
G-1159; T.C. A12EA	SA655EA	Installation of Collins flight directors.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA657EA	Installation of Sperry comparator warning unit.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA658EA	Installation of Sperry altitude preselect system. Amended 12/31/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA659EA	Installation of Bendix ALA-51A radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE19899
G-1159; T.C. A12EA	SA660EA	Installation of dual Sperry SPI-73E flight director system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA662EA	Installation of an Air-Lavatory Drain. Amended 12/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA663EA	Installation of EDO Loran System. Amended 1/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA669EA	Installation of bulkhead and bulkhead door at fuselage station 201.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA670EA	Installation of bulkheads at fuselage stations 467.5, 485.0 and 515.25; bulkhead doors at fuselage stations 485.0 and 515.25; and longitudinal bulkhead at buttline 4 between fuselage stations 467.5 and 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA680EA	Installation of conference table.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA681EA	Installation of bulkhead and bulkhead door at fuselage station 255.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA682EA	Installation of bulkhead and bulkhead door at fuselage station 495.0. Amended 9/10/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA683EA	Installation of sliding door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA684EA	Installation of intercostals between fuselage station 244-1/2 to fuselage station 257-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA685EA	Installation of intercostals between fuselage station 487 to fuselage station 498. Amended 10/22/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA688EA	Installation of Collins FD-109H and FD-109F flight director system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA689EA	Installation of IDC 17000-22 Air Data Computer. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA691EA	Installation of a dual Collins DF-203 ADF.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA692EA	Installation of intercostals between fuselage station 193 to fuselage station 206.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA693EA	Installation of bulkhead and bulkhead door at fuselage station 495 5/8.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA694EA	Installation of bulkhead and bulkhead door at fuselage station 200.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA699EA	Installation of intercostals between fuselage station 345 7/8 to fuselage station 355 1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA701EA	Installation of Hartman Systems Company vertical scale engine instruments. Reissued 11/29/68.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746
G-1159; T.C. A12EA	SA702EA	Installation of intercostals between fuselage station 452 1/2 to fuselage station 466.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA706EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. This STC does not apply to S/Ns 6, 11, 12, 14. Amended 12/27/73.	SO	15475	Bendix Corporation Bendix Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33309
G-1159; T.C. A12EA	SA718EA	Installation of intercostals between fuselage station 498 to fuselage station 512.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA721EA	Installation of swivel seat installation, fuselage stations 287 1/2 to fuselage station 379.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA722EA	Installation of Safe Flight SCAT/Autopower System. Amended 1/7/75.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
G-1159; T.C. A12EA	SA723EA	Installation of intercostals between fuselage station 43-1/2 and fuselage station 452-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA724EA	Installation of vertical scale full quantity indicators Model VS-2PE (639-) as replacement for original round dial indicators.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746
G-1159; T.C. A12EA	SA726EA	Installation of seat track reinforcement conference table grouping.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA733EA	installation of intercostals between fuselage station 297 to fuselage station 306-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA734EA	Long range under floor oxygen cylinder installation. Amended 7/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA735EA	Installation of divan base aft support/attachment at fuselage station 460-1/4.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA748EA	Installation of skyphone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA749EA	Installation of combined divan-bunk on right hand side of aircraft between fuselage station 183 and fuselage station 255. Issued 4/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA750EA	Installation of seat track extension. Issued 4/16/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA758EA	Installation of partial bulkhead and door at fuselage station 182. Amended 11/19/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA759EA	Installation of bulkhead attachment. Amended 8/22/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA760EA	Installation of bulkhead and bulkhead door at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA761EA	Installation of bulkhead at fuselage station 448. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA763EA	Installation of Litton LTN-51 inertial navigation system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA777EA	Installation of bulkhead at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA778EA	Installation of bulkhead at fuselage station 459.5. Amended 8/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA779EA	Installation of Custom Products Model 400-21 three place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA783EA	Installation of Electronic Resources Skyphone (UHF) antenna 10-222-04880.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA789EA	Installation of two-place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA790EA	Installation of bulkhead and door at fuselage station 507.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA806EA	Installation of Atlantic Aviation Corporation's retractable seat-GII and refreshment cabinet.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	ST874SO	Installation of Collins ground proximity warning system. Issued 12/15/75.	SO	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-1159; T.C. A12EA	ST888SO	Installation of Litton "Digiprox" ground proximity warning system. Issued 3/9/76.	SO	51502	Litton Systems, Inc. 6065 Roswell Road N.E. Suite 305B Atlanta, GA 30328
G-1159; T.C. A12EA	SA937SW	Crew jump seat.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA940SW	Micronair AU-3000 spray units.	EA	39540	Grumman Aircraft Engineering P.O. Box 147 Elmira, NY 14901
G-1159; T.C. A12EA	SA941SW	Collins HF communication system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA942SW	Collins AL-101 radio altimeter.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA943SW	Dual Sperry SPI-73 integrated flight system, Sperry instrumentation, comparator monitor and dual Sperry C11B compass system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA945SW	Litton LTN51 inertial navigation system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA946SW	Update Sperry 2587400-274 air data computer.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA948SW	Increase of DC output capabilities for APU TR unit.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA951SW	Passenger oxygen system and supplemental (long range) oxygen supply.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA957EA	Installation of modular berthable 1 or 2 place side-facing seat. Issued 7/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA970EA	Installation of Fairchild cockpit voice recorder Model A100 and A151 control unit. Issued 11/26/73.	EA	07498	AiResearch Aviation Company Islip MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA996EA	Installation of Shaw Aero fuel filler cap P/Ns 457-2, -266, -370, 431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
G-1159; T.C. A12EA	ST998SO	Installation of Bendix ground proximity warning system. Amended 8/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA1036SW	Bendix ALA-51A radio altimeter.	SW	12259	Associated RAdio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA1037SW	Emergency lights and battery.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1060EA	Installation of a single or dual Delco Electronics Carousel IV-A inertial navigation system with computer program, P/N 7881711-006. Reissued and amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1061EA	Installation of a dual Collins ALT-55B radio altimeter system. Amended 12/23/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA1062EA	Installation of a Sperry air data computer, Intercontinental Dynamics Co. (IDC) servo altimeters and mach. Amended 12/28/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA1063EA	Installation of a dual Collins flight director system, Model FD-109Y. Amended 1/23/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. 4/30/79	SA1068SO	Installation of Intercontinental Dynamics Corp. radio/barometric altimeter with voice terrain advisory and Sperry mini air data computer. Issued 4/30/79.	SO	39725	Gulfstream American Corporation P.O. Box 2206 Savannah, GA 31402
G-1159; T.C. A12EA	SA1070EA	Installation of dual Litton LTN-72R navigation system. Reissued and amended 4/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1093SW	Decca loran system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1139EA	Installation of a dual or single Global GNS-500A VLF/Omega navigation system. Amended 10/10/79.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1157EA	Replacement of Garrett AiResearch GTCP-36-6 APU with Solar T-62T-40C2 APU. Amended 10/5/79.	EA	73275	PATS, Inc. 7190-B Oakland Mills Road Columbia, MD 21046

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA1186EA	Installation of an Eldec Corp. digital fuel flowmeter and totalizer system. Issued 2/22/80.	EA	10135	Amerada Hess Corporation Mercer County Airport P.O. Box 7385 West Trenton, NJ 08628
G-1159; T.C. A12EA	SA1250SW	Decca type 72 doppler radar system. Issued 11/10/69.	EA	44[illegible]0	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1251SW	Decca omni-trac system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1336SW	Installation of pressure refueling control system. Issued 7/8/71.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1423SW	Electrical wiring feed thru Station 580. Issued 1/24/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1447SW	Battery fault warning system. Issued 9/18/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1480SW	Installation of FD-109F flight director, INS-61B inertial navigation system, Bendix ALA-51 radio altimeter. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-1159; T.C. A12EA	SA1481SW	Installation of cockpit control for center point refueling system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourne Avenue Burbank, CA 91505
G-1159; T.C. A12EA	SA1496SW	Tramm BTI-600 battery temperature indicating system. Issued 7/31/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA1553SW	Dual Collins INS-61B inertial navigation units. Issued 11/15/72.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1613SW	BKM master warning interface device between master warning control panel and aircraft inputs. Issued 3/1/73.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA1697SW	Avionics cooling fan. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1698SW	Oxygen service installation. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1633WE	Installation of jump seat in cockpit.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1634WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1654WE	Installation of passenger oxygen continuous flow system.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1683WE	Installation of passenger oxygen system.	WE	07500	AiResearch Aviation Company 6021 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1756WE	Installation of an aircraft integrated weight and balance system (STAN).	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1757WE	Installation of United Control flight data recorder.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1769WE	Installation of Sonotone Battery Model No. 989074-1 and battery container.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1771WE	Installation of SD1 Hoskins anti-collision light system. Amended 11/28/73.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
G-1159; T.C. A12EA	SA1772WE	Installation of United Control speed command system. Amended 6/19/70.	NW	80685	United Control Corporation Overlake Industrial Park Redmond, WA 98052

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA1800WE	Installation of radio rack and placards only for avionic components between fuselage stations 181-193 RH.	WE	63750	Qualitron Aero, Inc. Lockheed Air Terminal 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1814WE	Rain repellent system installation. Amended 10/25/73.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-1159; T.C. A12EA	SA1817WE	Installation of Sperry ATS-500 autothrottle system.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1819WE	Installation of doppler antenna and mount for doppler receiver and transmitter.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1848WE	Installation of Custom Products Model 1875 jump seat on radio rack.	WE	62105	Pacific General Corporation 3210A Winona Burbank, CA 91502
G-1159; T.C. A12EA	SA1868WE	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system.	SO	15475	Bendix Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA1889WE	Installation of Sperry SP-50G automatic flight control system, Sperry SPI-73E integrated instrument system and Sperry ATS-500 automatic throttle system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation P.O. Box 2529 Phoenix, AZ 85027
G-1159; T.C. A12EA	SA1898WE	Installation of Litton Model LTN-51 inertial navigation system. Amended 7/9/69.	WE	51500	Litton Systems, Inc. Guidance & Control Systems Division 5500 Canoga Avenue Woodland HIlls, GA 91364
G-1159; T.C. A12EA	SA1983WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2016WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2165WE	Installation of altitude preselect and alerting system (SP-50G Altitude Preselect System). Issued 7/8/70.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
G-1159; T.C. A12EA	SA2184WE	Installation of dual AC Carousel IV inertial navigation system. Amended 10/23/79.	GL	37810	General Motors Corporation A.C. Electronics Division Milwaukee, WI 53201
G-1159; T.C. A12EA	SA2234SW	Passenger continuous flow oxygen system. Issued 8/15/75.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2235SW	Dual Collins 61B inertial systems. Issued 8/15/75.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2237SW	BKM specific range computer. Issued 8/26/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2270SW	Manufacture and install a divan. Issued 11/7/75.	SW	11890	Associated Air Center Box 20718 - Love Field Dallas, TX 75220
G-1159; T.C. A12EA	SA2277SW	Continuous flow, low pressure oxygen system. Issued 12/10/75.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2366SW	Lighted speed brake handle. Issued 10/6/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2387SW	Dual Litton LTN-72R area navigation system. Issued 11/27/76.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2407SW	Install HF antenna on tail cone. Issued 2/11/77.	SW	36600	Foxtronics, Inc. P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA2430WE	Installation of dual Collins INS-61B inertial navigation system. Reissued 11/29/71.	CE	24250	Collins Radio Company 855 35th Street Cedar Rapids, IA 52406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA2512WE	Relocation of speed-logic control unit of GTCP36-6 turbine auxiliary power unit and mounting provisions for spare speed-logic unit. Issued 5/12/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2592WE	Installation of auxiliary taxi light system. Issued 9/1/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2593WE	Installation of Dorne and Margolin DMN 4-15 antenna (VOR/localizer) is installed in vertical stabilizer. Amended 11/9/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2757WE	Installation of crew oxygen regulator and mask assemblies. Issued 9/7/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2797WE	Installation of wing tip mounted emblem lights. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 91406
G-1159; T.C. A12EA	SA2807WE	Installation of dual GAMMA I (SKN-2610) inertial navigation systems. Amended 6/28/74.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2907SW	Pitot head indicating system. Issued 1/30/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2965WE	Installation of dual GAMMA I inertial navigation systems. Issued 1/16/75.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2995SW	Global GNS-500A VLF Omega navigation system. Issued 5/10/79.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA3089WE	Installation of 104006 computer program in LTN-104 ANS. Issued 10/1/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
G-1159; T.C. A12EA	SA3223WE	Installation of Garrett AirNAV 100 or 200 area navigation system. Amended 6/1/78.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3636WE	Installation of single Delco Carousel IVA inertial navigation system. Issued 6/22/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3288WE	Installation of Canadian Marconi vertical scale engine instruments. Issued 10/22/76.	WE	30000	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3302WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 9/17/76.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3370WE	Installation of dual ONTRAC III VLF/OMEGA navigation system. Issued 12/1/77.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3399WE	Installation of a single or dual Litton LTN-72R INS/RNAV navigation system. Amended 7/11/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3600WE	Installation of a single or a dual Delco C-IVA inertial navigation systems. Amended 1/30/80.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3629WE	Installation of either single LTN-51 or LTN-72. Issued 4/14/78.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
G-1159; T.C. A12EA	SA3635WE	Installation of IPECO pilot and co-pilot crew seats. Amended 6/26/79.	WE	54860	Marcon Associates, Inc. 18436 Hawthorne Blvd. Suite 212 Torrance, CA 90504
G-1159; T.C. A12EA	SA3691WE	Installation of DeVore Aviation wing tip tank tail cone mounted vertical tail floodlights. Issued 7/12/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA3973WE	Installation of equipment racks for the mounting of a radar system. Issued 6/15/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
GA-7; T.C. A17SO	SA1425CE	Install King KFC-200 automatic flight control system. Issued 7/14/78.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
GA-7; T.C. A17SO	SA3235SW-D	Mitchell automatic flight system AK634 consisting of Century IV autopilot or AK634FD consisting of Century IV flight director autopilot with remote annunciator. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3236SW-D	Mitchell automatic flight system AK634 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3238SW-D	Mitchell command electric trim AK637. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

HAMBURGER FLUGZEUBAU G.M.B.H.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
HFB 320 Hansa; T.C. A14EU	SA985SW	On-board ground air conditioner.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
HFB 320 Hansa; T.C. A14EU	SA1877WE	Installation of Fairchild A-100 voice recorder, A-152 control unit and Fairchild flight data recorder system. Amended 2/13/69.	EA	40515	Hansa Jet Corporation Hangar F Westchester County Airport White Plains, NY 10604
HFB 320 Hansa; T.C. A14EU	SA1921WE	Installation of folding observer's jump seat in lieu of Hansa jump seat.	EA	40515	American Hansa Jet Corporation Hangar F Westchester County Airport White Plains, NY 10604

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

HAWKER SIDDELEY AVIATION, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
748; T.C. A24EU	SA45GL	Install AMF inverter MGH 549-1. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
748 Series 2A; T.C. A24EU	SA125GL	Installation of Plessey Company P/N 612-1-39863 ground proximity warning system. Issued 7/12/76.	GL	08140	Air Illinois, Inc. Southern Illinois Airport Carbondale, IL 62901
748 Series 2A; T.C. A24EU	SA2944WE	Installation of DeVore emblem lights on horizontal stabilizer tips. Issued 11/1/74.	WE	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

HELIO AIRCRAFT, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H-250; T.C. 1A8	SA846EA	Installation of PeeKay Model 3500A amphibious floats. Issued 10/12/70.	EA	63626	PeeKay Aircraft Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
H-250; T.C. 1A8	SA867EA	Installation of Aerofab TSO C27 PeeKay Model B3500. Issued 3/19/71.	EA	29998	PeeKay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
H-250, H-295; T.C. 1A8	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
H-250, H-295; T.C. 1A8	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
H-250, H-295, H-391, H-391B, H-395, H-395B; T.C. 1A8	SA547SW	AK177 automatic pilot, AK123 lateral guidance radio coupler, and AK178 automatic trim.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-391, H-395; T.C. 1A8	SA354SO	Aft cabin door removed.	SO	27245	Vernon L. Crouch 2564 Alandale Drive Macon, GA 31201
H-250, H-295, H-391, H-395; T.C. 1A8	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
H-250, H-295, H-391, H-395; T.C. 1A8	SA1087SO	Installation of Brownline seat. Issued 7/6/79.	SO	47390	Jungle Aviation and Radio Service, Inc. P.O. Box 248 Waxhaw, NC 28173
H-250, H-295, H-391, H-395, H-395A; T.C. 1A8	SA1112WE	Sling-type passenger seat.	NW	75600	Stolairco, Inc. 6660 Perimeter Road S. Boeing Field Seattle, WA 98108
H-250, H-295, H-391, H-395, H-395A; T.C. 1A8	SA1491WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
H250, H295, H391B, H395; T.C. 1A8	SA916SO	Installation of Cessna seat rails and seats. Issued 1/13/77.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H250, H295, H391B, H395; T.C. 1A8	SA917SO	Installation of cargo door.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA179AL	Installation of Airglas wheel skis. Amended 4/28/67.	NW	75600	Stolairco, Inc. 6660 Perimeter Road S. Boeing Field Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA218AL	Main gear shock strut restrictor.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA234AL	Installation of Goodyear 30 x 13 x 6 main gear tires. Revised 6/30/69.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H250, H295, H395; T.C. 1A8	SA2381SW	Modification of main landing gear assembly, P/N 250-040-451, by addition of gussets at intersection of drag brace and main leg. Issued 11/15/76.	SW	30230	Dodd Engineering & Welding 3302 North Lewis Tulsa, OK 74110
H-250, H-295, H-395; T.C. 1A8	SA3247SW-D	Mitchell automatic flight system AK618 consisting of Century IIB autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-395, H-395A; T.C. 1A8	SA3244SW-D	Mitchell automatic flight system AK614, consisting of Century III autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H250, H-295, H-395, H-395A; T.C. 1A8	SA3245SW-D	Mitchell automatic flight system AK615, consisting of Century IIB autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-395, H-395A; T.C. 1A8	SA3246SW-D	Mitchell automatic flight system AK617 consisting of Century III autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-391, H-395A, H-391B; T.C. 1A8	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
H-250, H-391, H-395A, H-391B; T.C. 1A8	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 10/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
H-250, H-395A, H-395B; T.C. 1A8	SA1389CE	Install tailwheel yoke assembly to accommodate a Cleveland 600 x 6 wheel and either 600 x 6, 700 x 6 or 800 x 6 tires. Issued 12/15/77.	CE	90130	William G. Zaegel P.O. Box 3464 Anchorage, AK 99501
H-295; T.C. 1A8	SA860SW	Mitchell automatic flight system AK256 consisting of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76106
H-295; T.C. 1A8	SA1399SW	Installation of tricycle landing gear. Amended 5/17/78.	CE	42000	Helio Aircraft Limited Box 604 Pittsburg, KS 66762
H-295 (USAF U-10D); T.C. 1A8	SA2136WE	Installation of Tritan amphibious float Model TA 3500. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Box 464 Gardner Municipal Airport Gardner, MA 01440
H295, H-391, H395; T.C. 1A8	SA987SO	Removal of the Leece-Neville generator and voltage regulator and installation of a JASCO alternator kit 6565-1. Amended 11/8/79.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H-295, H-391, H-395; T.C. 1A8	SA1086SO	Installation of stowable co-pilot's rudder pedals. Amended 8/30/79.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H-295, -391B; T.C. 1A8	SA2666WE	Ceconite 102 material covering of ailerons. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
H-295, H-395; T.C. 1A8	SA900WE	Installation of turbosupercharged Lycoming GO-480-F2D6 engine. Amended 5/20/70.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
H-295, H-395; T.C. 1A8	SA1592WE	Installation of automatic fuel mixture control. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
HT-295; T.C. 1A8	SA35RM	Installation of Bendix FCS-810 autopilot, a trim adapter and Bendix HSD-830 compass. Amended 3/20/78.	RM	05940	Aircraft Radio & Accessory Company, Inc. Hangar No. 1 Stapleton Int'l Airport Denver, CO 80207
H-391, H-391B, H-395, H-395A; T.C. 1A8	SA284WE	B2D autopilot. Amended October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
H-391B; T.C. 1A8	SA709WE	Ceconite 101 covering of ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
H-391B; T.C. 1A8	SA731CE	Installation of Edo 582-3430 floats.	NE	47270	Frank Joy Cape Cod Aeromarine Box 398 Orleans, MA 02653
H-391B; T.C. 1A8	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
H-391B, H-395, H-395A; T.C. 1A8	SA235AL	Installation of modified oleo shock strut.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H-391B, H-395A; T.C. 1A8	SA152AL	L J 2800 floats.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 1254 Anchorage, AK 99502
H-395; T.C. 1A8	SA125SO	Turbocharger GO-480-G1D6 engine.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
H-395; T.C. 1A8	SA156SO	Turbocharged Lycoming GO-480-G1D6 engine.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
H-395; T.C. 1A8	SA393CE	Lycoming GO-480-G1D6 engine and Hartzell HC-B3Z-20-1/101510-5 propeller.	CE	42000	Helio Aircraft Limited P.O. Box 604 Pittsburg, KS 66762
H-395; T.C. 1A8	SA490SW	Turbocharger. Reissued 4/6/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
H-395; T.C. 1A8	SA1213CE	Installation of EDO 582-3430 floats. Issued May 1976.	AL	75095	Stephens Bros. Plumbing, Inc. 7339 Arctic Boulevard Anchorage, AK 99502
H-395; T.C. 1A8	SA1467CE	Increase in maximum gross weight from 3,000 lbs. to 3,300 lbs./ modification and kit installation instructions. Issued 12/28/78.	CE	17120	Clarence H. Brent P.O. Box 486 Pittsburg, KS 66762
H-395; T.C. 1A8	SA1696WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
500; T.C. A2EA	SA104SO	Swearingen combustion monitor. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
500; T.C. A2EA	SA305SO	Lycoming IO-540-C2C engines, 315A10 Rajay turbochargers and modified fuel system. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500; T.C. A2EA	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
500; T.C. A2EA	SA459CE	Models C4200A and 1800 skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
500; T.C. A2EA	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
500; T.C. A2EA	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
HST-550; T.C. A4EA	SA615SW	AK213 stabilizer and AK214 pitch trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
HST-550; T.C. A4EA	SA608SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by STC SA615SW.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

HILLER AVIATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH1-457	Aircooler Motors 6VS-335B turbo-supercharged engine (derated).	EA	19950	Carson Helicopters, Inc. RR-1, Box 98 Perkasie, PA 18944
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH4-178	Curved control stick.	WE	61772	Nystrom Aviation, Inc. 1901 Embarcadero Road Palo Alto, CA 94302
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH4-1071	Spray equipment kit.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH4-1101	Aerofilter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH9AL	Airglas tundra pads L-100.	AL	44260	International Helicopters P.O. Box 6227, Annex Anchorage, AK 99500
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH32WE	Fabricate and install jump-step.	WE	80912	USDA, Forest Service Arcadia Equipment Development and Test Center 701 N. Santa Anita Avenue Arcadia, CA 91006
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH83WE	Installation of modified air induction system.	WE	23170	Wayne Clevenger 785 Monterey Road Salinas, CA 93901
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH52WE	High volume fifty foot spray boom kit.	NW	71770	Simplex Manufacturing Company 5224 NE 42nd Avenue Portland, OR 97218
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH77AL	Tundra snow shoes.	AL	33650	ERA Helicopters, Inc. P.O. Box 762 Anchorage, AK 99501
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH80WE	IHstallation of Simplex thirty-two foot spray boom.	NW	71770	Simplex Manufacturing Company 5224 NE 42nd Avenue Portland, OR 97218
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH82WE	Installation of spray system and extended landing gear.	WE	23170	Wayne Clevenger 785 Monterey Road Salinas, CA 93901
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH160AL	Airborne control survey system.	EA	44049	U.S. Department of Interior Geological Survey Topographic Division Washington, D.C. 20000
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH446EA	Installation of Franklin engine Model 6V-350B in Fairchild Hiller UH-12A helicopter. Amended 6/30/70.	EA	36750	Franklin Engine Company, Inc. Liverpool Road Syracuse, NY 13208
UH-12, UH-12A, UH-12B, UH-12C, UH-12D, UH-12E; T.C. 6H1, 6H2, 4H10, 4H11	SH12CE	Installation of type AAF-102 AC filter. Amended 5/27/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
UH-12C; T.C. 6H2	SH141GL	Installation of Bell 47 canopy and one piece doors. Issued 11/8/76.	GL	74926	Stanley Tool & Die Company Route #1 Rock Falls, IL 61071
UH-12D; T.C. 4H10	SH177WE	Installation of Allison 250-C20 engine and related changes. Issued 4/10/75.	NW	73720	Soloy Conversions Limited 2209 E. 13th Street The Dalles, OR 97058
UH-12D; T.C. 4H10	SH247NW	Installation of ejector pump eng- oil cooler system on turbine pow UH-12D. Issued 1/20/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SA287NW	Installation of landing g [illegible] loat kit. Issued 4/23/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH295NW	Installation of two 20-g [illegible] auxiliary fuel tanks. Issued 5/18/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
UH-12D; T.C. 4H10	SH297NW	Installation of cabin heater kit for turbine powered helicopters. Issued 5/19/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH299NW	Installation of Soloy cargo racks. Issued 5/18/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH321NW	Installation of Bendix fuel control and power governor system. Issued 7/9/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH338NW	Installation of Harrison transmission oil cooler. Issued 8/12/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH359GL	Installation of NI-CAD Model No. 12367 engine lubrication system scavenge filter. Issued 8/13/79.	GL	61546	NI-CAD, Inc. 24800 U.S. 20 South Bend, IN 46628
UH-12D; T.C. 4H10	SH380NW	Installation of automatic reignition kit on Allison 250-C20. Issued 1/11/77.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH475NW	Agricultural spray pump system utilizing Simplex STCs. Installation will be made on turbine modified helicopters. Issued 7/13/77.	NW	73721	Soloy Conversions P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H11	SH505NW	Installation of cargo hook release pedal. Issued 8/23/77.	NW	73721	Soloy Conversions Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H11	SH559NW	Installation of inlet particle separator system on Allison 250-C20 powered helicopter. Issued 1/18/78.	NW	73721	Soloy Conversions Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D, UH-12E; T.C. 4H11	SH634NW	Installation of tundra pads. Issued 7/12/78.	NW	73721	Soloy Conversions P.O. Box 60 Chehalis, WA 98532
UH-12D, UH-12E; T.C. 4H10, 4H11	SH877SO	Installation of tail rotor guard assembly. Issued 2/2/76.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28677
UH-12E; T.C. 4H11	SH242GL	Installation of a General Electric 100 amp generator, P/N 2CM299H1,, and a distribution box. Issued 5/23/78.	GL	31570	East West Helicopter, Inc. 9005 Killey Road Harrison, OH 45030
UH-12E; T.C. 4H11	SH248NW	Installation of ejector pump engine oil cooler system on turbine powered UH-12E. Issued 1/20/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH288NW	Installation of landing gear float kit. Issued 4/23/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH296NW	Installation of auxiliary fuel tanks. Issued 5/18/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH298NW	Installation of cabin heater kit for turbine powered helicopters. Issued 5/19/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH300GL	Installation of NI-CAD, Inc. Model No. 12367 engine lubrication system scavenge filter. Amended 8/13/79.	GL	61546	NI-CAD, Inc. 24800 U.S. 20 South Bend, IN 46628
UH-12E; T.C. 4H11	SH300NW	Installation of Soloy cargo racks. Issued 5/18/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH322NW	Installation of Bendix fuel control and power governor system. Issued 7/9/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH339NW	Installation of Harrison transmission oil cooler. Issued 8/12/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH381NW	Installation of automatic reignition kit on Allison 250-C20. Issued 1/11/77.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
UH-12E; T.C. 4H11	SH476NW	Agricultural spray pump system utilizing Simplex STCs; installation will be made on turbine modified helicopters. Issued 7/13/77.	NW	73721	Soloy Conversions P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH506NW	Installation of cargo hook release pedal. Issued 8/23/77.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH560NW	Installation of inlet particle separator system on Allison 250-C20 powered helicopter. Issued 1/18/78.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E Series; T.C. 4H11	SH717NW	Installation of Simplex Model 4500 spray system. Issued 2/20/79.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
UH-12E (Restricted); T.C. 4H11	SH948NW	Installation of Model No. 5 automatic flagman. Issued 10/24/79.	NW	61619	North American Industries Route 4, City-County Airport Walla Walla, WA 99362
UH-12E; T.C. 4H11	SH951SO	Installation of removable center collective stick. Issued 8/17/77.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
UH-12E, -12E-1; T.C. 4H11	SH201WE	Installation of stirrup assemblies to directional control pedals for operation by handicapped pilot. Issued 4/14/77.	WE	28620	Barry C. Dallwig 113 East Elfin Green Port Hueneme, CA 93041
UH-12E, UH-12E-L, UH-12L, UH-12L4; T.C. 4H11, H1WE	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
UH-12E, -12E (4 place); T.C. 4H11	SH178WE	Installation of Allison 250-C20 engine and related changes. Amended 11/14/75.	NW	73720	Soloy Conversions Limited 2209 E. 13th Street The Dalles, OR 97058
UH-12E, -12E (4 place); T.C. 4H11	SH273NW	Installation of Simplex Model 3300 aerial spray system. Issued 3/16/76.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
UH-12E, UH-12E-4; T.C. 4H11	SH539NW	Installation of weighing system. Issued 10/31/77.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
UH-12E, UH-12E-L; T.C. 4H11	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
UH-12E, -12E-4, -12SL3, -12SL4; T.C. 4H11	SH165NW	Installation of Model 1620 and 1621 aerial seeders systems. Issued 3/17/75.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
UH-12E, -12E-4, -12SL3, -12SL4; T.C. 4H11	SH215NW	Installation of Model 4400 aerial dust system. Issued 9/9/75.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
UH-12E, -12E-4, UH-12L, UH-12L4; UH-12E and -12E4 as modified by STC SH178NW; T.C. 4H11, H1WE	SA618NW	Installation of onboard weighing system adapter for use with Eastern Rotorcraft cargo hook No. 2A15E. Issued 6/15/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

DEE HOWARD COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500; T.C. A1SW	SA98CE	Supplemental Model A, B, or E high intensity wing tip lights, Model C tail light, with or without Model 1 or 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
500; T.C. A1SW	SA451CE	Supplemental high intensity position light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
500; T.C. A1SW	SA546SW	Double action main landing gear.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
500; T.C. A1SW	SA723SW	F1002 windshield temperature control system.	SW	36004	M.R. Flores 175 Willee Street San Antonio, TX 78205
500; T.C. A1SW	SA738SW	Elevator torque tube flange.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
500; T.C. A1SW	SA743SW	Clamp, flap actuating cylinder H500 P/N 5-104268.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
500; T.C. A1SW	SA760SW	Flap actuating cylinder attach bracket.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

HUGHES HELICOPTERS

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
269 Series; T.C. 4H12	SH1WE	Two 30-gallon tanks and spraying equipment.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
269 Series; T.C. 4H12	SH3WE	Dust tanks and associated equipment (restricted category only).	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
269 Series; T.C. 4H12	SH6WE	Aluminum frame cargo rack on front and rear beam assembly.	NW	71770	Simplex Manufacturing Company 5224 NE 42nd Avenue Portland, OR 97218
269 Series; T.C. 4H12	SH7WE	Installation of Columbia Helicopters P/N 4747-1 cargo rack on left-hand side and P/N 4747-2 on right-hand side. Reissued 7/24/70.	NW	25000	Columbia-Construction Helicopters, Inc. 4747 N. Channel Avenue Portland, OR 97217
269 Series; T.C. 4H12	SH8WE	Luggage/cargo carrier.	NW	25000	Columbia Helicopters, Inc. Swan Island Portland, OR 97208
269 Series; T.C. 4H12	SH11WE	Overlay instrument panel to accommodate Motorola ADF T-128, Sperry Horizon, Schwien turn and bank.	WE	23400	Clover Field Radio Supply 3231 Airport Avenue Santa Monica, CA 90406
269 Series; T.C. 4H12	SH14WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
269 Series; T.C. 4H12	SH18WE	Cargo racks left and right sides.	WE	84635	Waters Helicopter Corporation International Airport Oakland, CA 94614
269 Series; T.C. 4H12	SH22WE	Landing gear conversion kit 100. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4H12	SH23WE	Cargo cling unit with release mechanism. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4H12	SH24WE	Modified spray system. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4H12	SH26WE	Cargo sling unit with release mechanism. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4H12	SH31WE	Spray equipment.	WE	03250	Agricultural Aviation Engineering Company 1040 Di Giulio Avenue Santa Clara, CA 95050
269 Series; T.C. 4H12	SH34WE	Installation of "Tote-All" luggage/cargo carrier. Reissued 7/27/70.	NW	25000	Columbia-Construction Helicopters, Inc. 4747 N. Channel Avenue Portland, OR 97217
269 Series; T.C. 4H12	SH35WE	Spray system. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4A12	SH37WE	Floats. Amended 5/11/66.	EA	07250	Air Cruisers Company Div. of Garrett Corporation P.O. Box 180 Belmar, NJ 07719
269 Series; T.C. 4A12	SH40WE	Dust dispensing equipment. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
269 Series; T.C. 4H12	SH41WE	HB64 spray equipment of HB 12CF seeding equipment.	WE	41755	Heli-Birds, Inc. 8103 Billy Mitchell Drive Santee, CA 92071
269 Series; T.C. 4H12	SH54AL	Tundra boards.	AL	60158	Bill Moore Air Service P.O. Box 3687 Anchorage, AK 99500
269 Series; T.C. 4H12	SH60WE	Lycoming HIO-460-B1B engine.	WE	62080	Pacific Airmotive Corporation Aviation Products Division 3411 Tulare Avenue Burbank, CA 91502
269 Series; T.C. 4H12	SH84AL	Cargo racks.	AL	60158	Bill Moore Air Service P.O. Box 3687 Anchorage, AK 99500
269, 269A-1, 269A-2, 269B, 269C; T.C. 4H12	SA586EA	Installation of Hartzell anti-overspeed kit. Amended 12/19/72.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 350 Washington Avenue Piqua, OH 45356
269A; T.C. 4H12	SH69WE	Installation of float kit, P/N 269A4300-7. Reissued 6/20/73.	WE	43344	Hughes Helicopters Div. of Summa Corporation Centinela & Teale Streets Culver City, CA 90230
269A Series; T.C. 4H12	SH74WE	Installation of Lycoming HIO-360-A1A engine. Issued 1/31/67.	RM	47758	Kensair Corporation Jefferson County Airport Broomfield, CO 80020
269A; T.C. 4H12	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1687 Abram Court P.O. Box 175B San Leandro, CA 94577
269A, 269A-1, 269B; T.C. 4H12	SH180WE	Installation of night advertising sign. Issued 5/16/75.	WE	64420	Edward L. Phipps 14404 Astoria Street Sylmar, CA 91342
269A, 269A-1, 269B; T.C. 4H12	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
269A, 269A-1, 269B; T.C. 4H12	SA1003CE	Replacement of Hughes P/N 269A5501 idler pulley with Hughes P/N 269A5414 idler pulley. Reissued April 1974.	SW	38086	Global Helicopters, Inc. P.O. Box 51112 Tulsa, OK 74101
269A, 269A-1, 269B, 269C; T.C. 4H12	SH12CE	Installation of type AAF-102 AC filter. Amended 5/25/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
269A, 269A-1, 269B, 269C; T.C. 4H12	SH749SW	Installation of Helemco Model A-2-Z quick change combination dispersal system for both wet xxxx Amended 4/29/74.	WE	43344	Hughes Helicopter Div. of Summa Corporation Centinela & Teale Streets Culver City, CA 90230
269A, 269A-1, 269B, 269C; T.C. 4H12	SA800EA	Installation of aviation white anti-collision strobe lights, Whelen Models A429, A430, A434, A450, A408W (white), A408R/W or A470R/W (red/white), A500 or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
269A, 269A-1, 269B, 269C; 369, A, H, HM, HS, HE; T.C. 4H12, H3WE	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
269A, 269A-1, 269B, 269C; T.C. 4H12	SH1017CE	Install miscellaneous plastic fairings. Amended June 1977.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052
269A, B; T.C. 4H12	SH1018CE	Install landing gear damper piston. Issued May 1974.	SW	48500	Kinzie Industries, Inc. P.O. Box 847 Alva, OK 73717
269A, B; T.C. 4H12	SH1047CE	Install modified landing gear damper. Reissued November 1974.	SW	48500	Kinzie Industries, Inc. P.O. Box 847 Alva, OK 73717

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
269A, B, C; T.C. 4H12	SH152AWE	Installation of SKI/Hoskins Model 700801 anti-collision light system. Issued 8/18/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
269A, 269B, 269C; T.C. 4H12	SH157WE	Installation of fiberglass/aluminum baggage compartment. Issued 7/6/73.	WE	39300	Gould Engineering, Inc. Falcon Field Airport 4600 E. McKellips Road Mesa, AZ 85205
269A, 269B, 269C; T.C. 4H12	SH249WE	Installation of a searchlight kit. Issued 9/5/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4H12	SH258WE	Installation of MCT-10 mounting rack. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4H12	SH259WE	Installation of utility compartment. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269B; T.C. 4H12	SA123WE	Installation of E.O.S. 1 KW searchlight and Technical Engineering & Manufacturing Co., Inc. Model TA-30 alternator.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH128WE	Installation of Nightsun SX-10 searchlight Kit No. 019600 when: A TA-30 dual voltage alternator is installed per STC SH131WE; the helicopter is equipped with a Dovsek Model 200C or 300B light mounts, the mount's indicator light conforms to Hughes Service Information Notice #N92. Amended 9/14/71.	WE	74500	Spectrolab Div. of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
269B, 269C; T.C. 4H12	SH131WE	Installation of EMPAC (U.S. Energy Corporation) Model TA-30 dual voltage alternator system (12 volts/60 amperes and 28 volts/68 amperes) in lieu of 12-volt alternator. Issued 7/7/71.	WE	80890	United State Energy Corporation 2780 Temple Avenue Long Beach, CA 90806
269B, 269C; T.C. 4H12	SH145WE	Installation of modified oil filler tube and dipstick. Issued 5/31/72.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH146WE	Installation of utility window. Issued 6/2/72.	WE	,65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH202WE	Installation of controls for pilot-in-command on right side. Issued 4/28/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
269B, 269C, Normal Category; T.C. 4H12	SH245WE	Installation of searchlight. Issued 7/31/79.	WE	19986	Carter Engineering Company, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
269B, 269C; T.C. 4H12 Only those rotorcraft having Hughes P/N 269A4593 or 269A8241, or 269A4593 muffler installed.	SH1138CE	Installation of engine exhaust tail pipe extension. Issued May 1975.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052
269C; T.C. 4H12	SH134WE	Installation of Spectrolab Nightsun SX-16C searchlight. Amended 3/3/75.	WE	65328	Progressive Aviaiton Limited Reid-Hillview Airport San Jose, CA 95122
269C; T.C. 4H12	SH224WE	Installation of heated pitot. Issued 9/13/78.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
269C; T.C. 4H12	SH1099CE	Installation of cabin heater and engine exhaust tail pipe extension. Issued March 1975.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052
300 Series (269C); T.C. 4H12	SH333NW	Installation of automatic flagman. Issued 10/28/76.	NW	03500	Air Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
369; T.C. H3WE	SH390NW	Installation of electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
369 Series; T.C. H3WE	SH598NW	Installation of load readout device. Issued 5/18/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
369 Series; T.C. H3WE	SH667NW	Installation of fiberglass fuel tanks under rear seat. Issued 9/15/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369 Series; T.C. H3WE	SH829NW	Installation of a weighing system. Issued 9/6/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
369, 369A, 369H, 369HM, 369HS, 369HE, 369D; T.C. H3WE	SH207WE	Installation or range extension fuel tank in cargo area of Hughes 369 series helicopters. Issued 1/10/78.	WE	68501	Robertson Aircraft, Inc. P.O. Box 968 Tempe, AZ 85281
369A, 369D, 369H; T.C. H3WE, 369HE, 369HM, 369HS	SH215WE	Installation of floodlights on fuselage. Amended 6/9/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
369A, H, HM, HE, HS; T.C. H3WE	SH358AL	Installation of Airglas L2700-369 skis. Amended 6/26/74.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369A, H, HS, HE; T.C. H3WE	SH1657SW	Full length, hard surface, skid shoes on standard skid landing gear. Issued 6/18/73.	SW	61650	Northrup Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
369D; T.C. H3WE	SH220WE	Installation of a "HCS-500D" helicopter computer system. Issued 7/28/78.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
369D; T.C. H3WE	SH246WE	Installation of ATI Model 13-0044, 13-0045 and 13-0046 speaker kits. Issued 8/17/79.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
369D; T.C. H3WE	SH654AL	Install Airglas Model L2700-369HD skis. Issued 10/24/78.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D; T.C. H3WE	SH678AL	Installation of Airglas skis. Issued 12/28/79.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D, 369H Series; T.C. H3WE	SH567NW	Installation of engine driven pump, tank hoses and spray nozzles for fire fighting. Issued 2/24/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369D, 369HE, 369HM, 369HS; T.C. H3WE	SH112GL	Installation of Marathon CA1700-1 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213
369D, 369HE, 369HM, 369HS; T.C. H3WE	SA123GL	Installation of SAFT 1656-1 nickel cadmium electrical storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213
369D, 369HE, 369HS; T.C. H3WE	SH236WE	Installation of searchlight. Issued 4/26/79.	WE	19986	Carter Engineering, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
369D, HE, HM, HS; T.C. H3WE	SH552NW	Installation of cargo hook electronic scale system. Issued 1/4/78.	NW	73067	Marvin A. Smith 5503 West Flowing Lake Road Snohomish, WA 98290
369D, 369H, 369HE, 369HM, 369HS; T.C. H3WE	SH183WE	Installation of turbine overtemperature warning system. Amended 4/4/77.	WE	60425	MRSC Incorporated 10959 San Diego Mission Road San Diego, CA 92108
369D, HE, HM, HS; T.C. H3WE	SH958SO	Installation of SAFT 16156 nickel cadmium battery. Amended 1/17/79.	SO	69800	SAFT America, Inc. P.O. Box 1886 Valdosta, GA 31601
369D, H, HM, HS, HE; T.C. H3WE	SH1142EA	Installation of APC starter-generator, P/N 150SG111Q. Issued 4/23/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
369D, 369HE, 369HS; T.C. H3WE	SH189WE	Installation of searchlight kit. Amended 3/16/79.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH190WE	Installation of P.A. speaker kit. Amended 4/14/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH250WE	Installation of a P.A. speaker kit. Issued 9/17/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
369D, 369HE, 369HS; T.C. H3WE	SH898EA	Installation of pod type cargo container kits. Amended 11/22/78.	EA	72263	Skypods Limited P.O. Box 221 Arnprior, Ontario, Canada
369D, 369HE, 369HS; T.C. H3WE	SH1134EA	Installation of external cargo container (POD) kit. Issued 11/13/78.	EA	83757	Viking Helicopters, Ltd. P.O. Box 5104 - Station "F" Ottawa, Ont. K4C3H4 Canada
369H; T.C. H3WE	SH184NW	Installation of Chadwick C-500 aerial spray system. Issued 5/23/75.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369H; T.C. H3WE	SH431NW	Installation of Model 500 spray system. Amended 5/9/77.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH1054EA	Installation of Garrett AiResearch environmental control system. Amended 9/8/77.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
369HE, 369HM, 369HS; T.C. H3WE	SH129WE	Installation of Chadwick C-20 auxiliary fuel systems. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH132WE	Installation of two side cargo racks P/N DMC-023-200-1. Issued 8/25/71.	NW	61798	Olympic Helicopters, Inc. 8241 Perimeter Road South Boeing Field Seattle, WA 98108
369HE, 369HM, 369HS; T.C. H3WE	SA133WE	Installation of C-75 cargo rack set, P/N 75-0000-00. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH516AL	Installation of Model L2700-369HS skis. Issued 5/1/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
369HS; T.C. H3WE	SH214WE	Installation of external neutron detector moduel and associated cockpit displays. Issued 4/18/78.	WE	31225	EG & G, Incorporated P.O. Box 1912 Las Vegas, NV 89101
369HS; T.C. H3WE	SH242NW	Installation of battery in Hughes 369HS helicopter to replace original. Issued 12/11/75.	NW	47708	Keefer Aircraft Engineer 11457 Glendale Way South Seattle, WA 98168
369HS; T.C. H3WE	SH690SO	Installation of SunAir Electronics Model ASB-60 or ASB-125 HF radio transceiver and associated system. Reissued 6/20/73.	WE	43344	Hughes Helicopters Div. of Summa Corporation Centinela & Teale Streets Culver City, CA 90230

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MICHAEL K. HYNES

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B-2; T.C. 2H2	SH155GL	Installation of a removal skin on each side of engine compartment. Issued 3/27/77.	GL	53580	F.C. McLaughlin c/o Byerly Aviation, Inc. Greater Peoria Airport Peoria, IL 61607
B-2, B-2A; T.C. 2H2	SH1-626	Lube oil filter PB55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
B-2B; T.C. 2H2	SH11CE	Installation of Hoskins Twilighter Mk II supplemental lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
B-2B; T.C. 2H2	SH12CE	Install type AAF-104, AC Spark Plug filter. Amended 2/1/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
INDUSTRIE AERONAUTICHE E MECCANICHE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
P.166; T.C. 7A4	SA239WE	M-4 autopilot.	WE	60200	Motorola Aviation Electronics, Inc. 10916 W. Washington Boulevard Culver City, CA 90230
P.166; T.C. 7A4	SA357WE	Goodrich brake assembly 2-878 and wheel assembly 3-1112.	WE	61648	Northrop Corporation 1001 E. Broadway Avenue Hawthorne, CA 90250
P.166; T.C. 7A4	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ISRAEL AIRCRAFT INDUSTRIES, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1121; T.C. A2SW	SA187SO	Bar cabinet and 2-place couch.	SO	18749	Butler Aviation Palm Beach, Inc. International Airport West Palm Beach, FL 33401
1121; T.C. A2SW	SA353SO	Two forward seats in cabin between Stations 115.78 and 134.78.	SO	68430	Robbins Airborne 2456 Winchester Memphis, TN 38101
1121; T.C. A2SW	SA387EA	Automatic flight control system.	GL	15210	Beckett Aviation Corporation Municipal Airport Youngstown, OH 44501
1121; T.C. A2SW	SA555SW	Seat tracks.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001 AND
1121; T.C. A2SW	SA555SW	Seat tracks.	SW	22792	Clark Engineering Service 6441 Happy Lane Dallas, TX 75221
1121; T.C. A2SW	SA620SW	Instrument standby 400 CPS static inverter and ground blower system.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA629SW	Angle of attack system.	NE	26010	Continental Development Corp. P.O. Box 511 Ridgefield, CT 06877
1121; T.C. A2SW	SA630SW	Installation of antenna for electronics system, and electronic equipment shelves. Reissued 5/30/79.	WE	70490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
1121; T.C. A2SW	SA640SW	Antenna system.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA664SW	Interior. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1121; T.C. A2SW	SA679SW	ADF sense antenna.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA702SW	Installation of electronic equipment for Category II operation. Reissued 5/30/79.	WE	70490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
1121; T.C. A2SW	SA724SW	Radome plastic nose cap.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA865SW	Antenna system.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA866SW	Standby AC power system.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA959SW	DA2001 quick release pin for nose gear torque train.	SW	29232	Delta Aircraft P.O. Box 12182 San Antonio, TX 78205
1121; T.C. A2SW	SA967EA	Installation of Tramm BTI-6000 dual battery temperature indicating system. Issued 11/13/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1121; T.C. A2SW	SA1246SW	Install equipment necessary to certify aircraft to 45,000 feet (crew only) and 41,000 feet (passenger). Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. Suite 115 2025 S. Nicklas Oklahoma City, OK 73128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1121; T.C. A2SW	SA1290WE*	Installation of "Quazar" high-intensity supplemental exterior flashing lights. *Approved anti-collision light system is required. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
1121; T.C. A2SW	SA1356WE	Gas turbine GTCP30-92 auxiliary power unit.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
1121; T.C. A2SW	SA1487SW	Replacement of existing cockpit light dimmers. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas , Suite 115 Oklahoma City, OK 73128
1121; T.C. A2SW	SA1775WE	Installation of nose wheel steering quick disconnect pin.	WE	71746	SIMCO 1660 - 18th Street Santa Monica, CA 90404
1121; T.C. A2SW	SA2013WE	Installation of single point pressure refueling system.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1121; T.C. A2SW	SA2408SW	Three-place couch side facing with toilet. Issued 2/14/77.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
1121; T.C. A2SW	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
1121; T.C. A2SW	SA2847SW	Forward cabin window, left and right side at fuselage station 115.78 to 134.78 and right side window at fuselage station 150.15. Issued 5/31/79.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A; T.C. A2SW	SA964CE	Installation of IAD battery temperature indicating and over temperature warning system. Issued October 1973.	CE	05250	Aircraft Instrument & Development, Inc. 317 E. Lewis Street Wichita, KS 67202
1121, 1121A; T.C. A2SW	SA1165SW	Installation of bleed air heated engine inlet ducts. Reissued 2/5/80.	SW	44860	Israel Aircraft Ind. Int'l, Inc. 2025 South Nicklas Oklahoma City, OK 73125
1121, 1121A, 1121B; T.C. A2SW	SA416CE	Install Hoskins supplementary Twilighter Mk III lighting system with Model A single wing tip lights and Model D (dual) tail light or tail light assembly. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
1121, 1121A, 1121B; T.C. A2SW	ST881SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
1121, 1121A, 1121B; T.C. A2SW	SA922SW	Drag chute as safety item. Reissued 2/14/75.	SO	34808	Federal Express Corporation AMF P.O. Box 30167 Memphis, TN 38130
1121, 1121A, 1121B; T.C. A2SW	SA934SW	Aft baggage compartment. Amended 8/12/75.	SO	34808	Federal Express Corporation AMF P.O. Box 30167 Memphis, TN 38130
1121, 1121A, 1121B; T.C. A2SW	SA948EA	Installation of battery isolation system. Issued 3/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1121, 1121A, 1121B; T.C. A2SW	SA1274SW	CA5 batteries. Reissued 2/28/73.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA1298SW	Teledyne Avionics normalized angle of attack indicating system 112B400 with optional input to slow/fast indicator of Collins 329B-8G flight director instrument. Issued 6/16/71.	SW	78127	Teledyne, Inc. 3401 Shiloh Road Garland, TX 75040
1121, 1121A, 1121B; T.C. A2SW	SA1311SW	Redesigned nose wheel corotating drive shaft. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128
1121, 1121A, 1121B; T.C. A2SW	SA1345SW	Gross weight increase to 18,500 lbs. takeoff with B.F. Goodrich wheels, brakes and anti-skid system. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1121, 1121A, 1121B; T.C. A2SW	SA1434SW	Increase maximum zero fuel weight from 12,000 lbs. to 12,340 lbs. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128
1121, 1121A, 1121B; T.C. A2SW	SA1513SW	Ground air conditioner. Reissued 2/28/73.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA1879SW	Engine thrust reversers. Issued 6/7/74.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
1121, 1121A, 1121B; T.C. A2SW	SA1947SW	Fuel drain collector. Issued 1/17/75.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2203SW	Install capacitance type fuel gaging system. Reissued 3/10/78.	SW	44860	Israel Aircraft International 2025 S. Nicklas Oklahoma City, OK 73128
1121, 1121A, 1121B; T.C. A2SW	SA2389SW	Install identification and recognition lights in wings. Issued 12/8/76.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2615WE	Installation of nose wheel steering control wheel unift. Reissued April 1973.	SW	04540	Air Center, Inc. Wiley Post Airport P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2695SW	Install aircraft taxi lights on main landing gears. Issued 12/15/77.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2712SW	Modify existing TSO three-place forward facing couch. Issued 1/24/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2713SW	Install two and three-place couches (TSO 39a) side facing at right side of cabin. Issued 1/26/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2716SW	Relocation of thrust reverser hydraulic accumulator pressure gage. Issued 2/1/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2745SW	Install aft baggage compartment. Issued 4/4/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2894SW	Installation of hydraulic accumulator. Issued 1/10/79.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B, 1122; T.C. A2SW	SA927EA	Installation of Grimes three light strobe kit P/N 34-0305-1 as supplemental lighting. Issued 7/7/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
1121, 1121A, 1121B, 1123; T.C. A2SW	SA2471SW	Fabrication and installation of aircraft cabin door retainer. Issued 6/9/77.	SW	04540	Air Center, Inc. P.O. Box 32168 Okahoma City, OK 73132
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA398EA	3065 replacement nose cap radome. Amended 7/16/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA791CE	Installation of either of the following electronic synchronizer kits P/N 213521 or P/N 213517. Amended 9/28/72.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA2396SW	Fabrication and installation of aircraft positive door latch. Issued 1/14/77.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA3000WE	Installation of logo light assembly. Amended 5/1/75.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
1121, 1121B; T.C. A2SW	SA1805WE	Installation of ground air conditioner. Amended 7/16/69.	WE	85135	Western Commander, Inc. 8029 Woodley Avenue Van Nuys, CA 91406
1121A, 1121B; T.C. A2SW	SA1820SW	Collins MC-103 dual compass system. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060

ISRAEL AIRCRAFT INDUSTRIES, LTD. 4

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1121A, 1121B; T.C. A2SW	SA1821SW	Bendix RDR-1200 weather radar. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1822SW	ADF installation - Collins DF206. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1823SW	Bendix MKA-28 marker beacon. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1824SW	Bendix RTA42A VHF communications. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1825SW	Bendix ALA-51 radio altimeter. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1826SW	Collins 621A-6 ATC transponder. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1827SW	UHF communication/ADF - Collins ARC159/DF301E. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1828SW	Bendix RNA-26F VOR/ILS system. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1829SW	Sierra tacan system. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1831SW	Pointer II emergency locator transmitter beacon. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1832SW	J.E.T. SI-2500 inverters. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 63074 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1833SW	Collins 346B-3 audio/interphone system. Issued 7/3/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1834SW	Radio racks. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1835SW	Flight inspection console structure. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1836SW	Pedestal extension. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1837SW	Seat modification. Issued 10/3/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1838SW	Standby gyro system. Issued 3/22/74.	SW	63750	Qualitron System, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1840SW	Emergency lighting. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1841SW	Ramp air conditioning. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1843SW	Interior lighting. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1844SW	Emergency locator receiver. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1849WE	Installation of United Control Speed Command System.	WE	85135	Western Commander, Inc. 8029 Woodley Avenue Van Nuys, CA 91406
1121A, 1121B; T.C. A2SW	SA2644WE	Installation of single point refueling system. Issued 2/7/73.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1121B; T.C. A2SW	SA1819SW	FCS-105 consisting of dual FD109 flight directors and AP105 autopilot. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121B; T.C. A2SW	SA1830SW	IDC altitude alerter/vertical navigation system. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121B; T.C. A2SW	SA1842SW	Electrical power system. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121B; T.C. A2SW	SA1877SW	Area navigation system. Issued 4/30/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1123; T.C. A2SW	SA956EA	Installation of Tramm battery temperature indicating system Model BT1600 and battery isolation system. Amended 8/21/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1123; T.C. A2SW	SA1566SW	Teledyne Avionics normalized angle of attack system. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128
1123; T.C. A2SW	SA2897WE	Installation of single point refueling system. Issued 6/11/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1124; T.C. A2SW	ST231GL	Installation of two Canadian Marconi CMA-734 omega navigation systems. Issued 3/24/78.	GL	02392	Aeronautical Systems, Inc. 4393 E. 17th Avenue Columbus, OH 43219
1124; T.C. A2SW	SA2858SW	Installation of Lear Siegler 23065-018-1 starter generator. Issued 11/3/78.	SW	44860	Israel Aircraft Ind. Int'l, Inc. 2025 South Nicklas Oklahoma City, OK 73128

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

C. ITOH AIRCRAFT MAINTENANCE & ENGINEERING COMPANY, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
N-62; T.C. A3PC	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Scnebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
N-62; T.C. A3PC	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

JOBMASTER COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Howard DGA-11, Howard DGA-15P, DGA-15J, DGA-15W; T.C. 672, 717	SA2646WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
DGA-15J, -15P; T.C. 717	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
DGA-15J, DGA-15P, DGA-15W; T.C. 717	SA4-876	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DGA-15J, -15P, -15W; T.C. 717	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
DGA-15P; T.C. 717	SA3-715	Remove cabin door.	CE	34625	Corbett B. Pasching 214 E. Colorado St. Joseph, MO 64501
DGA-15P; T.C. 717	SA3-716	Hartzell 3-bladed propeller HC-B3Z30-2E/10152-5-1/2 or HC-093Z30-2E/10152-5-1/2 with 836-16R spinner on aircraft with Pratt & Whitney R-985-AN-6 engine.	GL	56826	Maxwell Aircraft Service, Inc. Crystal Airport Minneapolis, MN 55428
DGA-15P; T.C. 717	SA4-20	BT-13 cowling and mounting brackets.	WE	84397	Jay Waldren 716 Arvin Street Bakersfield, CA 93300
DGA-15P; T.C. 717	SA4-887	Tricycle landing gear with either fixed or retractable nose gear and/or modified vertical stabilizer.	CE	77140	Elro M. Swindle 132 Denver Street Salina, KS 67401
DGA-15P; T.C. 717	SA4-1283	Ceconite 103 covering of plywood components.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DGA-15P; T.C. 717	SA1NW	Installation of EDO Xa5400 floats. Issued 7/18/72.	NW	48400	Jobmaster Company, Inc. 1005 West Perimeter Road Renton, WA 98055
DGA-15P; T.C. 717	SA27CE	Removal of door.	CE	77140	Elro M. Swindle 132 Denver Street Salina, KS 67401
DGA-15P; T.C. 717	SA170WE	Removal of cabin door for parachute jumping and aerial photography operations.	WE	14804	Homer J. Barry 826 Linda Vista Drive Banning, CA 92220
DGCA-15P; T.C. 717	SA1008WE	Poly-fiber covering of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Coatings 43rd South Fort Drive P.O. Box 3084 Riverside, CA 92519

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

JODEL, AVION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D-140-B, DR-1050, 150; T.C. A3IN, A4IN, A14IN	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
D-140-B, DR-1050, 150; T.C. A3IN, A4IN, A14IN	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
KAWASAKI HEAVY INDUSTRIES, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
KV107-II; T.C. H1PC	SH435NW	Install Boeing kit to increase the rotorcraft external load carrying capability from 19,000 to 22,000 pounds. Issued 4/12/77.	NW	25000	Columbia Helicopters P.O. Box 3500 Portland, OR 97218

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

KWAD COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Pine Air Super-V; T.C. 4A29	SA222CE	Reinforce front lower carry-through section and wing attach fittings by the addition of steel plates and fittings. Amended 10/7/69.	CE	47250	R.M. Jourdan & James Flanagan 8801 East 40 Hihway Kansas City, MO 64108
Super V; T.C. A-51N, 4A29	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Super V; T.C. A-51N, 4A29	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Bay Aviation Super V; T.C. 4A29	SA454WE	Pneumatic flight control. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
LAISTER-KAUFFMAN AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
LK-10A Series; G.T.C. 15	SG4-741	Bubble canopies over each cockpit and change in configuration of vertical and horizontal tail.	WE	86204	John W. Williams 1986 Galveston San Diego, CA 92101
LK-10A Series; G.T.C. 15	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
LK-10A Series; G.T.C. 15	SG4-1230	Ceconite 101 covering of complete glider.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
LK-10A Series; G.T.C. 15	SG4-1411	Ceconite 103 covering of glider.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
LK-10A Series; G.T.C. 15	SG10WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 103 material. Amended 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
LK-10A Series; G.T.C. 15	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
LK-10A; G.T.C. 15	SA2666WE	Ceconite 102 material covering complete glider. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
LK-10A, -10B; G.T.C. 15	SG4-1240	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
LK-10A, -10B; G.T.C. 15	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

LAISTER SAILPLANE PRODUCTS

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
LP-49; T.C. G2WE	SA171NW	Installation of adjustable rudder pedals. Issued 4/4/75.	NW	00285	Frank Abadi 215 Valley Street, #303 Seattle, WA 98101

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

LET, n.p.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Blanik L-13; T.C. G24EU	SG12WE	Removal of canopy and rear control stick. Issued 12/12/73.	WE	29830	Paul R. Deutsch 1436 East 6th Street Ontario, CA 91746
Blanik L-13; T.C. G24EU	SG228NW	Glider tail wheel. Issued 4/2/76.	NW	17790	Brown A/C Company 225 S.W. 196th Place Seattle, WA 98166
Blanik L-13; T.C. G24EU	SA1008WE	Poly-fiber covering of all control surfaces aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Coatings 43rd South Fort Drive P.O. Box 3084 Riverside, CA 92519
Blanik L-13; T.C. G24EU	SA2666WE	Ceconite 102 material covering of ailerons, flaps, rudder and elevators. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

LOCKHEED AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
(SP-2E) P2V-5F; T.C. A17EA	ST163RM	Installation of 3100 gallon tank for fire retardant material delivery.	RM	33899	Evergreen Air of Montana P.O. Box 4345 Missoula, MT 59801
Vega D-2; T.C. 2-377	SA4-1283	Ceconite 101 covering of plywood components.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
B-34, PV-1; L.T.C. 13	SA3-360	Oil separator assembly on Pratt & Whitney R2800-CB16 Series engines.	GL	02500	Aeroquip Corporation 300 S. East Avenue Jackson, MI 49203
B-34, PV-1; L.T.C. 13	SA4-323	Full Flow oil filter 30816A with element 1A0097.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
B-34, PV-1, 18; L.T.C. 13, T.C. 723	SA1744WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
PV-1; L.T.C. 13	SA4-465	Rudder spring tab assembly.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
PV-1; L.T.C. 13	SA4-497	Increase in flaps extended speed varying from an increase to 243 mph at 12.5% flaps to 145 mph at 100% flaps.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA4-524	106-1 engine mount core.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
PV-1; L.T.C. 13	SA4-1329	Alternate fuel source equipped with Pratt & Whitney R-2800 Series "C" engines and fuel flow meters.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
PV-1; L.T.C. 13	SA40SW	PV-1 oil tank modification to 24 U.S. gallons.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA46SW	Cockpit windows and windshield.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA47SW	Elevator and rudder control systems modification.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA48SW	Modification of aft fuselage to lower tail gear 9 inches.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA49SW	Vista Vision cabin windows and cabin emergency exit.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA52SW	Elevator nose down spring with electric actuator relief system.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA63SW	Pitot and static on wing tip boom.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA79SW	Goodyear six spot brake system on aircraft previously equipped with three spot brakes.	SW	81300	C.R. Ursell 109 Briarcliff Drive San Antonio, TX 78205
PV-1; L.T.C. 13	SA85SW	Elevator boost system.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA98CE	High intensity wing tip lights Model A, B, or E, tail light Model C, with or without Model 1 or 2 high-intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
PV-1; L.T.C. 13	SA123SW	Fiberglass horizontal stabilizer short tips.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205

LOCKHEED AIRCRAFT CORP. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PV-1; L.T.C. 13	SA126SW	Dual actuator rod modification on elevator trim control tab.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA205SW	Electric trim fail safe feature.	SW	68768	North American Rockwell Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
PV-1; L.T.C. 13	SA212SW	Ground air conditioner unit.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA228SW	Underwing exhaust system.	SW	29000	The Dee Howard Company P.O. Box 16216 SAn Antonio, TX 78205
PV-1; L.T.C. 13	SA232SW	Outer wing panel extension.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA286SW	Modification of aircraft.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA309SW	Elevator nose down spring and relief system.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA449SW	Pressurized fuselage and other modifications.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA545SW	Tail cone.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA714SW	Main cabin windows enlarged.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1; L.T.C. 13	SA715SW	Cockpit side windows.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1; L.T.C. 13	SA718SW	Lowering of tail gear trunnion.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA719SW	Wing tip extended.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1; L.T.C. 13	SA720SW	Aerodynamic smoothing of outer wing.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1; L.T.C. 13	SA738SW	Elevator torque tube flange.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1; L.T.C. 13	SA743SW	Clamp, flap actuating cylinder H500 P/N 5-104268-1.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1; L.T.C. 13	SA760SW	Flap actuating cylinder attach bracket.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1, PV-2; LTC-13	SA4-487	Radar nose for Bendix C-Band, Bendix X-Band, or RCA C-Band.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
PV-1, 18; L.T.C. 13, T.C. 723	SA220SW	Omni antenna. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
PV-1, 18 (Howard 250); L.T.C. 13, T.C. 723	SA285SW	Hydraulic windshield wipers. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
PV-1, 18 (Learstar): L.T.C. 13, T.C. 723	SA451CE	Supplemental high intensity position light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
PV-2; L.T.C. 13	SA4-381	Deletion of bat wings, new radar nose, and other modifications.	WE	61778	Oakland Airmotive Company International Airport Oakland, CA 94614

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PV-2; L.T.C. 13	SA4-525	Engine mount core 106-1F and 106-1J.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
PV-2; L.T.C. 13	SA1002WE	Removal of cabin door.	RM	72596	Skyways, Inc. P.O. Box 587 Cody, WY 82414
10-A; T.C. 551	SA78EA	Installation of modified Beech D18S engine cowl. Reissued 6/2/72.	GL	20108	Casement Aviation P.O. Box 231 Painesville, OH 44077
10-A; T.C. 551	SA171EA	Installation of Goodyear Model L12-HBM, Type III, 11.00-12 Wheel-Brake Assemblies with 11.00-128 Ply Tires. Reissued 6/7/72.	GL	20108	Casement Aviation P.O. Box 231 Painesville, OH 44077
10-A; T.C. 551	SA271SO	Installation of wheel well fairings. Reissued 6/2/72.	GL	20108	Casement Aviation P.O. Box 231 Painesville, OH 44077
12A; T.C. 616	SA1-139	Windshield from a four-place to a two-piece glass.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
12A; T.C. 616	SA4-33	Installation of Hartzell propellers and Hartzell C-3 governors. Amended 10/23/67.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
18 (Learstar); T.C. 723	SA1-17	Main landing gear upper cylinder assembly.	GL	01824	Aerodraulics Company 16134 Brookpart Road Cleveland, OH 44135
18; T.C. 723	SA1-58	Picture windows.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-66	1003-X radome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-87	South Wind cabin heater 940.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-95	Modification of three-place divan to four-place divan.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-121	Airspeed pitots on each wing tip and flush button static system located in nose of fuselage.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-138	Airspeed pitots and flush button static system.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-162	Westinghouse AH-4 and AH-5 decelostat anti-skid devices.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
18; T.C. 723	SA1-166	Two-piece windshield.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-168	Stabilizer tips 147 and bullet fairings 210.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-172	General Electric 2CM80B5 200-amper generators on aircraft with Wright 704C9GC1 engines.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-194	Picture windows on left and right sides of fuselage.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
18; T.C. 723	SA1-223	Radome assembly 2007X-R.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-264	Radome assembly 2006X-R for RCA AVQ-50 weather antenna system.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-334	Large window installation.	EA	71915	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18; T.C. 723	SA1-409	Sperry A-12 gyropilot.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-419	RCA 5" AVQ-50 indicator and underseat mount.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-514	Enrichment of auto lean mixture setting by installing auto lean jet 22244-3300cc injection.	EA	08375	Airwork Corporation Municipal Airport Millville, NJ 08332
18; T.C. 723	SA3-4	Seat in forward compartment stations 147 to 188.	CE	44054	Interstate Aircraft Company 3251 FAirfax Road Kansas City, KS 66115
18; T.C. 723	SA3-41	Short stack installation - Pratt & Whitney R-1830 or Wright R-1820 engines. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18; T.C. 723	SA3-42	Modification to Janitrol heater air inlet scoop. Installation of Janitrol heater overheat warning system. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18; T.C. 723	SA3-46	Nose heater installation - Stewart-Warner Model 940-B24. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18; T.C. 723	SA3-49	Two Eclipse 200-amphere generators (P-1), P/N 30E07-11.	GL	37808	General Motors Air Transport Section Bay 1, City Airport Detroit, MI 48202
18; T.C. 723	SA3-316	South Wind 8240 heater.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
18; T.C. 723	SA3-443	Curved glass, bird resistant windshield, and heating and ventilating system. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA3-444	Two ARDL-7A-115-29 relative danger lights under each wing tip.	GL	12488	Atkins Light Corporation 7636 Lyndale Avenue, South Minneapolis, MN 55401
18; T.C. 723	SA3-466	DC-3 exhaust collector ring and short stack installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18; T.C. 723	SA4-14	Windshield modification.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18; T.C. 723	SA4-15	Nose pitot tube.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91505
18; T.C. 723	SA4-16	Door modification.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91505
18; T.C. 723	SA4-17	Lodestar retractable fuel dump chute.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91505
18; T.C. 723	SA4-18	Seat supports.	WE	02308	Aero Interiors, Inc. 2945 N. Hollywood Way Burbank, CA 91502
18; T.C. 723	SA4-19	ADF antenna.	WE	63750	Qualitron, Inc. 2945 Hollywood Way Burbank, CA 91502
18 (Learstar); T.C. 723	SA4-29	Radar nose for Bendix C-Band, Bendix X-Band or RCA C-Band. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-37	Picture window.	WE	39877	Gordon B. Hamilton 1002 E. Valencia Tucson, AZ 85711
18; T.C. 723	SA4-52	Oil filters 1258-B86-A and element 1258-OC.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
18; T.C. 723	SA4-57	Rework of outer wing panel for 348 gallon integral fuel tank. Reissued 11/11/74.	SW	30300	D.H. Donahue 1016 W. Houghton Street Santa Fe, NM 87501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18; T.C. 723	SA4-58	Oil tank assembly for increased oil supply. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-59	Cockpit seats. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-69	Lockheed Model 18 modified to Learstar Mark II configuration. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-71	Rudder spring tab assembly. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-72	Radar nose for Bendix C-Band, Bendix X-Band, or RCA C-Band. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-130	Horizontal stabilizer incidence angle change to one degree. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-131	Drag reduction fairing addition. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-136	Wright R-1820-56A, -66, -72A engines, modified rudder spring mechanism and tab, elevator spring tab, retractable tail wheel assembly, stabilizer and tail-wheel, fairing-fuselage horizontal stabilizer tip, fairing installation - stabilizer intersection, modification Lodestar bat wing and flap seal. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-137	Installation of exhaust collector assembly including carburetor heater muff on Wright R1820-56A. Reissued 11/11/74.	SW	30300	D.H. Donahue 1016 W. Houghton Street Santa Fe, NM 87501
18 (Learstar); T.C. 723	SA4-155	Sperry Model A-12 automatic pilot installation modification. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-171	Approval to use 1,350 hp for takeoff with Wright R1820-56A, -66 and -72A engines and 1,300 hp, with Wright R-1820-56 and -72 engines with Hamilton Standard 33D50/6511-12 and -12S propellers.	SW	78465	Web Thomas aircraft Sales P.O. Box 575 Addison, TX 75001
18; T.C. 723	SA4-185	DC3 exhaust collector ring with modified short stack and new carburetor heat muff assembly on Wright R-1820-56 engine.	WE	65018	Potter Aircraft Service, Inc. Lockheed Air Terminal Burbank, CA 91500
18; T.C. 723	SA4-201	350-gallon outer wing tank and new fuel system.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18 (Learstar); T.C. 723	SA4-216	Picture window. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-217	Main cabin floor structure. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learjet); T.C. 723	SA4-223	Installation of exhaust collector assembly including carburetor heat muff. Reissued 11/11/74.	SW	30300	D.H. Donahue 1016 W. Houghton Street Santa Fe, NM 87501
18; T.C. 723	SA4-251	Fiberglass stabilizer fairing.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18; T.C. 723	SA4-256	Horizontal stabilizer angle of incidence change and modified stabilizer tips, wing and flap trailing edge. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-257	Picture window. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 (Learstar); T.C. 723	SA4-264	Two Jato motors 15KS-1000A1 in fuselage. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001
18; T.C. 723	SA4-273	Installation of heat-shroud, propeller anti-icing alcohol tank, and modified DC-3 exhaust system. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-274	Outer wing fuel tanks, revised fuel system, change in angle of incidence of horizontal stabilizer one degree and installation of fuselage horizontal stabilizer fairing. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-275	Installation of PacAero wing tip. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-281	Horizontal stabilizer angle of incidence change. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-283	60154 stabilizer tip. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-307	Lear L-102A automatic pilot. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001
18; T.C. 723	SA4-366	Horizontal stabilizer tip, rudder spring tab, Learstar tail cone, elevator spring tab, Goodyear wheels and brakes, modification of wing trailing edge and reducing flap travel, change of stabilizer incidence. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-368	Picture window. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001
18; T.C. 723	SA4-371	Repair for wrinkles at wing station 120.	WE	39877	Hamilton Aircraft Company 6501 S. Park Avenue Tucson, AZ 85706
18; T.C. 723	SA4-397	Structural installation of flight line 24 P-001 seat. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-425	Modification per STC SA4-69 except gross weight modification per Dwg. 600030B, engine per Dwg. 606399 and DCN-1, picture window per STC SA-368 and pilot seat per STC SA4-397. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-434	100,000 BTU (S-100) Janitrol heater in No. 1 baggage compartment.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91505
18; T.C. 723	SA4-534	Propeller spinners.	NW	59600	Miner's Aircraft and Engine Service, Inc. 8165 First Avenue, South Seattle, WA 98101
18 (Learstar); T.C. 723	SA4-644	Lear L-5B autopilot. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001
18; T.C. 723	SA4-653	Exhaust system and exhaust trough on aircraft equipped with Pratt & Whitney R-1830-94 engines.	WE	43000	Ben Howard & Associates, Inc. 4200 Lincoln Boulevard Venice, CA 90291
18; T.C. 723	SA4-654	Modification of nacelle aft of firewall to fair-in structure in exhaust trough area on aircraft with Pratt & Whitney R-1830-94 engines.	WE	65016	Potter Aircraft Service, Inc. Lockheed Air Terminal Burbank, CA 91500
18 (Learstar); T.C. 723	SA4-715	Westinghouse air brake AH-5 decelostat anti-skid unit. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 (Learstar); T.C. 723	SA4-732	Alternate fuel source on aircraft with Wright Cyclone engines with flow meter installation. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-738	Modification to "Learstar" (NOTE 12 of Aircraft Spec A-723) except installation of Wright R1820-56A, -66, or -72A engines as per Dwg. 606327 DCN B-15. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-838	Sperry A-12 autopilot. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-973	Pitot - static system. Reissued 11/11/74.	SW	30300	D.H. Donahue 1016 W. Houghton Street Santa Fe, NM 87501
18; T.C. 723	SA4-1010	Autolite generator 2CM70B9 on Wright engines R1820-56A, -66, and -72A. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-1014	Radio shelf structure No. 1 baggage. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-1138	Gross weight modification including: increase power, installation of Goodyear wheels and brakes, two JATO motors, removal of bat wing and other changes. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-1310	20C63-S100 Janitrol heater.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
18; T.C. 723	SA4-1317	Gross weight modification including: increase power, installation of two JATO motors, outer wing tank, and Goodyear wheels and brakes, removal of bat wing and other changes. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-1552	Pittsburgh Plate Glass Company electrically-heated windshield. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA16SW	Electric trim tab servo. Reissued 6/26/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA17SW	Electric trim tab servo. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18 (Learstar); T.C. 723	SA47WE	Interior and equipment installation. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA50SW	Extended wing tip. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18 (Howard 250); T.C. 723	SA51SW	Increase in gross weight to 22,500 pounds takeoff and 20,500 pounds landing. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18 (Howard 250); T.C. 723	SA69GL	Install emergency lighting system. Issued January 1975.	GL	65274	George J. Priester Aviation Service Pal-Waukee Airport Wheeling, IL 60090
18; T.C. 723	SA78SW	Enlarged lavatory window on right side of aft fuselage station 444. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA78GL	Install second static pressure system. Issued 4/18/75.	GL	65274	George J. Priester Aviation Service Pal-Waukee Airport Wheeling, IL 60090

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Loadstar, Learstar Conversion; T.C. 723	SA100CE	High intensity wing tip lights Model A or B, tail light Model C, with or without Model 1 or 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
18; T.C. 723	SA105SW	Landing gear doors. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA106SW	M-4 autopilot. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Airmotive 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA107SW	Alcohol deicing system.	SW	68768	North American Rockwell Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA129SW	Empennage saddle-back fairing. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA177SW	Tail cone. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA181SW	Oxygen system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA187SW	Firewall fluid shutoff v Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA188SW	Scene-A-Ramic cabin windows. Issued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18 (Howard 250); T.C. 723	SA192SW	Mighty Midget flap and gear hydraulic selector. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA194SW	Cockpit side windows. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA200SW	Electric trim system. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA201SW	Tail cone. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA211SW	Higher strength main landing gear drag strut anchor fitting. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA215WE	Pilot's seat and seat tracks.	WE	02315	Aerojet-General Corporation International Airport Ontario, CA 91761
18; T.C. 723	SA224EA	Electrically heated windshield.	EA	64686	Pittsburgh Plate Glass Company #1 Gateway Center Pittsburgh, PA 15222
18; T.C. 723	SA225SW	Centilevered pressure cowling on aircraft with Wright R-1820 engines. Reissued 6/28/78.	SW	34000	Executive Airdraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA248SW	Fiberglass propeller spinner on aircraft with Hamilton Standard 33D50 or 23E50 propeller hub. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA273SW	Cockpit seats. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18; T.C. 723	SA278SW	Exhaust stack.	SW	68768	North American Rockwell Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA301SW	Lower nacelle. Reissued 6/28/78.	SW	3400	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA306EA	Stewart-Warner south wind heater.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18; T.C. 723	SA308SW	Geneerco cabin floor.	SW	68768	North American Rockwell Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
18 (Learstar); T.C. 723	SA325EA	Southwind heater in No. 2 baggage compartment.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361
18; T.C. 723	SA327SW	Janitrol S-200 combustion heater below nose baggage bin floor. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Industries, Inc. 3300 Love Field Drive Dallas, TX 75235
18 (Howard 250); T.C. 723	SA352SW	Dual selector valves and boost pumps. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aviation Service 7515 Lemmon Avenue Dallas, TX 75209
18 (Howard 250); T.C. 723	SA361SW	Jet stack exhaust system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA389SW	Windshield with modified Learstar sliding side cockpit windows. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18 (Howard 250); T.C. 723	SA554SW	Single disc brakes.	SW	68768	North American Rockwell Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
18 (Howard 250); T.C. 723	SA567SW	Airspeed system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
Lockheed 18 (Learstar only); T.C. A-723	ST594SO	Installation of 19 passenger interior and Type III emergency. Issued May 1974.	SO	36012	Florida Airways International P.O. Box 22003 Fort Lauderdale, FL 33315
Lockheed 18 (Learstar only); T.C. A-723	SA614SW	Janitrol S-100 heater. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA1686WE	Installation of engine mounts P/N VIP 50525-1 and P/N 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
18 "Learstar"; T.C. 723	SA2718WE	Installation of intermixed engines, Wright R1820-76A and Wright 987C9HD1 engines. Issued 6/29/73.	WE	15130	Bay Aviation Services, Inc. P.O. Box 2545, Airport Station Int'l Airport, Hangar 4 Oakland, CA 94614
18, 18 (Howard); T.C. 723	SA146SW	Lear L-5 autopilot. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA183SW	Air conditioner. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA293SW	Two shot CO2 fire extinguisher. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA296SW	High pressure deicer boots. REissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA508SW	140-gallon outer panel fuel tank. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA509SW	Execulette side mounted lavatory. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, 18 (Howard); T.C. 723	SA510SW	Panoramic window. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18-56; T.C. A-723	ST868SO	Removal of main cabin door. Issued 11/6/75.	SO	31363	Eagle Aviation Corporation P.O. Box 1082 Zephyrhills, FL 33599
18-56; T.C. A-723	ST892SO	Removal of main cabin door. Issued 4/13/76.	SO	75118	Harold D. Stewart 13123 N.W. 39th Avenue Gainesville, FL 32601
49; T.C. 763	SA4-27	Stratus supercharger and air cycler.	SW	17075	Braniff Airways, Inc. Love Field Dallas, TX 75235
49; T.C. 763	SA4-1616	Nose radome.	WE	49724	Las Vegas Hacienda, Inc. 2680 E. Wardlow Road Long Beach, CA 90801
49; T.C. 763	SA3SO	Radome and radar provisions for up to 22-inch diameter antenna RCA AVQ-10 or Bendix RDR-1 (X/C Band).	SO	78390	Tempo Design Corporation P.O. Box 456 Miami, FL 33148
49; T.C. 763	SA112WE	Structural mounts in McMillan radome and in cockpit for WP-103 Collins all weather radar.	WE	19550	California Airmotive Corporation 7139 Vineland Avenue North Hollywood, CA 91603
49; T.C. 763	SA776WE	Collins DME in aircraft.	WE	32100	Edde Airlines, Inc. 2850 E. Wardlow Road Long Beach, CA 90801
49; T.C. 763	SA845WE	Military D-2 auxiliary power unit in Zone 3 of No. 1 nacelle.	WE	49724	Las Vegas Hacienda, Inc. 2680 E. Wardlow Road Long Beach, CA 90801
49; T.C. 763	SA1296WE	Seats at emergency exit incorporating a free folding back.	WE	52860	McCulloch Properties, Inc. 2733 E. Spring Street Long Beach, CA 90807
49-46; T.C. A-763	SA1319WE	Installation of Collins ATC transponder Model 621A-2 with antenna type 237Z-1.	WE	52860	McCulloch Properties, Inc. 2733 E. Spring Street Long Beach, CA 90807
49-46; T.C. A-763	SA1360WE	Installation of Collins Model 642C-1 cockpit voice recorder system. Amended 3/10/67.	WE	52860	McCulloch Properties, Inc. 2733 E. Spring Street Long Beach, CA 90807
49, 149, 649, 749, 1049, 1649; T.C. 763, 6A5, 4A17	SA83SO	Oil separator B-300-1.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
49, 149, 649, 649A, 749, 749A, 1049 Series, 1649; T.C. 763, 6A5, 4A17	SA546WE	Modification of crew entrance door window mechanism.	WE	37082	Gamco Precision 10021 La Tuna Canyon Sun Valley, CA 91352
649, 649A, 749, 749A; T.C. 763	SA1-605	2015 Series radomes.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
49, 649, 649A, 749, 749A; T.C. 763	SA4-1500	Interior modification for 98 passengers, maximum occupants including crew.	WE	39460	Great Lakes Airlines, Inc. Lockheed Air Terminal Burbank, CA 91500
49, 749; T.C. 763	SA3-203	Smoke detection for cargo compartment.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Parkville, MO 64152
649, 749; T.C. 763	SA642WE	Operation with mixed Hamilton Standard 43E60/6901 and 43E60/6903 propellers.	WE	19550	California Airmotive Corporation 7139 Vineland Avenue North Hollywood, CA 91603
749; T.C. 763	SA1-480	Smoke detector system in cargo compartments Class B.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749, 749A; T.C. 763	SA354WE	Observer's jump seat.	WE	19550	California Airmotive Corp. 7139 Vineland Avenue North Hollywood, CA 91603
749A; T.C. 763	SA1-145	Cabin interior modification for 74 to 80 seats, inclusive of galley and crew bunk area.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
749A; T.C. 763	SA1-146	Radio equipment.	NW	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749A; T.C. 763	SA1-147	Goodyear brake assembly 9540534 wheel assembly 9540753, and modification of brake control valve.	NW	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749A; T.C. 763	SA1-547	Modification of floor and support structure for cargo loading.	NW	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749A; T.C. 763	SA1-578	Cabin smoke detector system for cargo operation.	NW	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749A; T.C. 763	SA4-1634	Modification of interior to 81 through 85 and 90 passenger configurations.	WE	19550	California Airmotive Corp. 7139 Vineland Avenue North Hollywood, CA 91603
749A; T.C. 763	SA4-1657	Structural mounts in McMillan radome and in cockpit for WP-103 Collins all weather radar.	WE	19550	California Airmotive Corp. 7139 Vineland Avenue North Hollywood, CA 91603
749A; T.C. 763	SA464CE	Fairchild Model A-100 cockpit voice recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
749A; T.C. 763	SA24SO	Cargo loading door in forward section of main cabin and rework of main cabin floor structure.	SO	11326	Robert E. Anson and L.C. Callaway, Jr. 7211 S.W. 52nd Street Miami, FL 33101
749A; T.C. 763	SA66WE	Oversize cargo door on left side of fuselage aft of wing.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
749A; T.C. 763	SA326WE	Emergency safety equipment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
749A; T.C. 763	SA327WE	Cargo tie-down rings for retaining a 4,700 pound R 3350 QEC package.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
188; T.C. 4A22	SA562NW	Installation of liquid cargo tanks. Issued 1/20/70.	NW	73820	Sorm, Inc. 7999 Perimeter Road, S. Seattle, WA 98108
188; T.C. 4A22	ST508SO	Installation of lap/shoulder belts. Issued 6/8/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
188; T.C. 4A22	SA2324WE	Installation of spraymat ice protection system on L-188 propeller spinner, Hamilton Standard P/N 553546, replacing Hamilton Standard heater blanket. Issued 3/10/71.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
188A-08; T.C. 4A22	SA410EA-D	Relocate flight data recorder installation to aft fuselage area. Amended 1/26/68.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
188A-08; T.C. 4A22	SA418EA-D	Change interior arrangement of passenger compartment from existing configuration of tourist and first class to eighty passenger six lounge configuration.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
188A; T.C. 4A22	SA178SO	Cockpit voice recording system.	SO	61220	National Airlines, Inc. P.O. Box 2055 Airport Mail Facility Miami, FL 33159
188A; T.C. 4A22	SA228SO	Rewinding of rotating field element 291C671G1 for General Electric 400 cycle alternator Model 2CM 210 using a magnet wire insulated with Polythermaleze coating.	SO	63855	Peninsular Armature Works, Inc. 3525 NW 51 Street Miami, FL 33101
188A; T.C. 4A22	SA267SO	Aural Mach overspeed warning system to comply with Special Regulation SR450A.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
188A; T.C. 4A22	SA272SO	Overspeed warning system.	SO	61220	National Airlines, Inc. P.O. Box BAL Miami, FL 33159
188A; T.C. 4A22	SA335SW	Overspeed warning system.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
188A; T.C. 4A22	SA594WE	Audible mach airspeed warning system.	WE	85126	Western Air Lines, Inc. 6060 Avion Drive Los Angeles, CA 90052
188A; T.C. 4A22	ST672SO	Installation of encoding altimeter, ATC transponder, and associated system.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A; T.C. 4A22	SA1055WE	Cockpit voice recorder system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
188A; T.C. 4A22	SA1064SO	Increase in zero fuel weight from 82,500 lbs. to 90,800 lbs. Issued 4/13/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661087 Miami, FL 33166
188A; T.C. 4A22	SA1071SO	Increase in zero fuel weight from 86,000 pounds to 92,340 pounds. Issued 6/14/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661087 Miami, FL 33166
188A; T.C. 4A22	SA1090WE	Mach airspeed warning system.	SW	10150	American Airlines, Inc. Maintenance & Overhaul Center Tulsa, OK 74151
188A; T.C. 4A22	SA1104WE	Fairchild cockpit voice recorder system.	WE	85126	Western Air Lines, Inc. 6060 Avion Drive Los Angeles, CA 90052
188A; T.C. 4A22	SA1234WE	Essential power failure warning circuit modified.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
188A; T.C. 4A22	SA2162WE	Fabrication and installation of blanks in lieu of passenger compartment windows (glass fiber epoxy laminate reinforced with 0.080 x 7075T6 aluminum edge). Issued 5/27/70.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
188A; T.C. 4A22	SA2536WE	Modification and installation of: aft cargo door; cargo loading and retention system; strengthened floor support structure; increased zero fuel weight to 90,000 pounds; improved avionics and instrumentation. Amended 7/24/75.	WE	52010	Lockheed Aircraft Service Company Burbank, CA 91500
188A; T.C. 4A22	SA3700WE	The deletion of fueling valve indicator lights and test switch. Issued 7/25/78.	WE	33905	Evergreen Inter'l Airlines Marana Air Park Marana, AZ 85238
188A, 188C; T.C. 4A22	SA3-596	Waste-King 5424-200 flight recorder system. Amended 5/24/67.	GL	61700	Northwest Airlines, Inc. 1885 University Avenue, South St. Paul, MN 55111
188A, 188C; T.C. 4A22	SA1-403	Model 109C flight data recorder. Amended 10/13/66.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
188A, 188C; T.C. 4A22	SA97GL	Installation of Collins FPC-75/590A ground proximity warning system. Issued 11/7/75.	GL	90135	Zantop Int'l Airlines, Inc. Detroit-Willow Run Airport Ypsilanti, MI 48197
188A, 188C; T.C. 4A22	SA133SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	SA158SO	Overwing emergency escape ropes.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	SA218WE	GTC 85-90E or GTCP 85-291E turbine.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
188A, 188C; T.C. 4A22	SA240SO	Oil separator B500-2.	SO	04400	Air Carrier Engine Service P.O. Box 48-236 Miami, FL 33148
188A, 188C; T.C. 4A22	SA638WE	Liquor bar.	WE	85126	Western Air Lines, Inc. 6060 Avion Drive Los Angeles, CA 90052

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
188A, 188C; T.C. 4A22	SA678WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
188A, 188C; T.C. 4A22	SA685WE	Aural warning signal when Vmo/Mmo is exceeded.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
188A, 188C; T.C. 4A22	SA686WE	Aural warning signal when Vmo/Mmo is exceeded.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
188A, 188C; T.C. 4A22	ST733SO	Installation of exterior emergency lighting system. S/Ns 1001, 1002, 1004 thru 1148 and 2001 thru 2022 only. Issued 10/20/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
188A, 188C; T.C. 4A22	ST749SO	Installation of plug type metal panels to replace the original clear plastic main cabin windows. Issued 11/24/75.	SO	56838	MCA Leasing 7216 N.W. 25th Street Miami, FL 33122
188A, 188C; T.C. 4A22	ST754SO	Installation of remote control essential A-C bus normal and alternate electrical circuit breaker system. Amended 8/9/77	SO	56838	MCA Leasing Corporation 7216 Northwest 25th Street Miami, FL 33122
188A, 188C; T.C. 4A22	ST852SO	Installation of cargo door. Issued 9/25/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
188A, 188C; T.C. 4A22	ST853SO	Installation of Sundstrand ground proximity warning system. Issued 9/26/75.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	ST885SO	Modification to a cargo configuration. Amended 2/7/78.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661037 Miami, FL 33166
188A, 188C; T.C. 4A22	SA1178WE	Cockpit voice recorder.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
188A, 188C; T.C. 4A22	SA1206WE	Beta range override control switch.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
188A, 188C; T.C. 4A22	SA1754WE	Installation of cargo doors, cargo floor and other changes. Amended 1/22/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario Int'l Airport Ontario, CA 91761
188A, 188C; T.C. 4A22	SA1982WE	Installation of luggage barrier.	WE	52860	McCullagh Properties, Inc. 2733 East Spring Street Long Beach, CA 90807
188A, 188C; T.C. 4A22	SA1934WE	Installation of inflatable slide for right rear emergency exit and for left rear service door; also International Inflatables emergency light No. 68555. Amended 6/24/71.	WE	44266	International Inflatables Co. Div. of Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
188A, 188C; T.C. 4A22	SA2187WE	Modification of inflatable slide International Inflatables emergency escape chute kit #KP 684. Amended 7/7/70.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
188A, 188C; T.C. 4A22	SA2197WE	Installation of Brownline modified cargo restraint system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
188A, 188C; T.C. 4A22	SA2301WE	Installation of emblem light. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406
188A, 188C; T.C. 4A22	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
188A, 188C; T.C. 4A22	SA2456WE	Installation of Collins Model 860E-2 and dual DME system. Amended 1/5/72.	WE	30000	DeVore Aviation Service Corp. 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	FG	STC Code	STC Holder
188A, 188C; T.C. 4A22	SA2559WE	Installation of H. Koch & Sons beverage cart P/N 601-710315-1 on stowage mushroom plate assembly. Amended 11/9/72.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	SA2711WE	Modification of flight station temperature control. Reissued 10/2/73.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
188A (S/N 1035 and up), 188C; T.C. 4A22	SA2889WE	Conversion of Lockheed Model 188A and 188C into all cargo configuration by installation of cargo door, cargo floor and cargo lining. Amended 8/25/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA2963WE	Increase maximum zero fuel weight to 90,000 pounds by modifying aircraft. Issued 1/29/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA2974WE	Modification for installation of aft galley and forward galley rework. Issued 1/6/75.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA3059WE	Maximum landing weight substantiated to 98,102 pounds (from 95,650 pounds). Issued 10/23/75.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA3098WE	Structural modifications. Issued 10/31/75.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA3120WE	Modification consisting of installation of cargo pallet restraint system. Amended 8/12/77.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
188, 188C; T.C. 4A22	SA3141WE	Installation of AiResearch GTCP85-98, -98C or -98CK auxiliary power unit to supply starting air and 400 HZ power. Issued 4/30/76.	AL	67017	Reeve Aleutian Airways, Inc. P.O. Box 6027 Anchorage, AK 99502
188A, 188C; T.C. 4A22	SA3152WE	Installation of cargo door only. Issued 4/29/76.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA3159WE	Installation of cargo floor and interior. Issued 4/29/76.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A, 188C; T.C. 4A22	SA3675WE	Installation of Brownline cargo system P/N 46234-101. Amended 4/30/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 Lomita Blvd. Torrance, CA 90505
188B, A188B; T.C. A9CE	SA3088WE	Installation of CEDAD fender assemblies. Issued 9/5/75.	WE	20325	CEDAD Company 4700 Brooks Street Montclair, CA 91763
188C; T.C. 4A22	SA91GL	Installation of radio altimeter antenna opening and radio rack. Issued 10/29/75.	GL	65760	Quality Controlled Electronics, Inc. Willow Run Airport Ypsilanti, MI 48197
188C; T.C. 4A22	SA132CE	Overspeed warning system.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
188C; T.C. 4A22	SA707EA	Relocation of cabin window right-side from fuselage station 217-236 to fuselage station 333-352. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761.
188C; T.C. 4A22	SA708EA	Installation of opening in fuselage right hand for emergency exit between fuselage station 226 and fuselage station 253.4. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
188C; T.C. 4A22	SA709EA	Installation of floor structure and miscellaneous modifications. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
188C; T.C. 4A22	ST750SO	Installation of main cabin cargo crash barrier bulkhead. Issued 11/24/75.	SO	56838	MCA Leasing 7216 N.W. 25th Street Miami, FL 33122

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
188C; T.C. 4A22	SA796EA	Installation of six-seat pallet. Reissued 12/11/78.	WE	33905	Evergreen Inter'l Airlines, Inc. Marana Air Park Marana, AZ 85236
188C; T.C. 4A22	SA1081SO	Increase in fuel weight from 86,000 pounds to 92,340 pounds. Issued 6/14/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661087 Miami, FL 33166
188C; T.C. 4A22	SA1637WE	Installation of cargo door approximately 80 inches high by 144 inches long in left side of fuselage forebody.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91764
188C; T.C. 4A22	SA1779WE	Installation of Heathair AC-10194, AC-10195 pallets and Heathair AC-10196, AC-10197 nets on Lockheed electra model 188C cargo freighter. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
188C; T.C. 4A22	SA2092WE	Installation of Heath 54 x 88 inch cargo pallet AC-10528-1 and net AC-10657-101. As modified per STC SA1754WE. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
188C; T.C. 4A22	SA2152WE	Installation of Heath 88 x 108 inch cargo pallet AC-10527-1 and net AC-10196-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
188C; T.C. 4A22	SA2694WE	Modification for installation of: nose and wingtip instrumentation boom provisions; research apparatus mounting provisions; dropsonde dispenser; increased breathing oxygen provisions and research electrical system. Issued 5/30/73.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
188C; T.C. 4A22	SA2695WE	Modification for installation of: nose instrumentation boom and wingtip instrumentation boom. Modification per STC SA2694WE is required prior to this modification. Issued 5/30/73.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
188C; T.C. 4A22	SA2991WE	Installation of passenger compartment interior arrangement in aft fuselage. Issued 2/21/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188C; T.C. 4A22	SA3084WE	Installation of Collins FPC-75 ground proximity warning system computer. Amended 7/21/76.	WE	04080	Air California P.O. Box 2678 Oakland, CA 94614
188C; T.C. 4A22	SA3299WE	Modification of passenger compartment interior arrangement in aft fuselage and relocation of forward airstair to rear left-hand Type 1 exit. Issued 11/23/76.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
L-188C; T.C. 4A22	SA3618WE	Relocation of forward airstair to rear left hand type 1 exit. Issued 3/27/78.	WE	10210	American Jet Industries, Inc. 7701 Woodley Van Nuys, CA 91406
L-1011; T.C. A23WE	ST858SO	Installation of Bendix ground proximity warning system. Issued 10/20/75.	SO	29234	Delta Air Lines Atlanta Airport Atlanta, GA 30320
L-1011; T.C. A23WE	SA994CE	Installation of Inflight Motion Picture, Inc. 16 mm motion picture projection system. Amended May 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
L-1011; T.C. A23WE	SA1047SO	Installation of the Litton LTN-211 omega navigation system. Issued 2/7/79.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011; A23WE	SA1456CE	Installation of nine-abreast seating. Issued 10/31/78.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195
L-1011; T.C. A23WE	SA1540CE	Installation of a Growth Industries dual cavity oven. Issued 12/11/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
L-1011; T.C. A23WE	SA1664SW	First aid portable chemical oxygen system. Issued 6/25/73.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
L-1011; T.C. A23WE	SA1689SW	Cabin attendant portable chemical oxygen system. Issued 6/25/73.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
L-1011 (193E); T.C. A23WE	SA2647WE	Installation of cocktail table in first-class lounge. Issued	WE	18290	Burns Aero Seat Company 2820 N. Hollywood Way Burbank, CA 91502
L-1011-385 Series; T.C. A23WE	SA3527WE	Installation of single or dual Litton LTN-201 omega navigation systems. Amended 3/26/79.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
L-1011-385-1; T.C. A23WE	ST752SO	Modification of main cabin passenger seating arrangement. Amended 3/22/78.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	ST831SO	Installation of food and beverage cart stowage provisions. Issued 4/30/75.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	ST851SO	Installation of Sundstrand ground proximity warning system. Issued 8/7/75.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	SA857CE	Crimsco entree cart. Amended February 1975.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
L-1011-385-1; T.C. A23WE	SA1198CE	Deactivation of flap load relief system in accordance with TWA M.O. 98686. Issued 2/1/76.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
L-1011-385-1; T.C. A23WE	SA1286CE	Installation of additional aircraft integrated data system and digital flight data recorder parameters. Amended 11/22/77.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195
L-1011-385-1; T.C. A23WE	SA1325CE	Install food and beverage service center in aft passenger. Issued May 1977.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport P.O. Box 20126 Kansas City, MO 64195
L-1011-385-1; T.C. A23WE	SA2519WE	Installation of H. Koch & Sons, Inc., food, beverage and waste cart. Amended 9/14/72.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	SA2894WE	Installation of Hermes LD-3 Kool-flite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 130th Street Gardena, CA 90249
T.C. A23WE					
L-1011-385-1; T.C. A23WE	SA3087WE	Installations of ground proximity warning system. Amended 4/27/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
L-1011-385-1; T.C. A23WE	SA3474WE	Installation of aircraft video system. Issued 12/1/77.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
L-1011-385-1; T.C. A23WE	SA3512WE	Installation of stretcher carrier, P/N 2003. Issued 3/21/78.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
L-1011-385-1; T.C. A23WE	SA3809WE	Installation of a dual Delco C-IVA INS.	WE	29125	Delco Electronics Division General Motors Corporation 6767 Hollister Avenue Goleta, CA 93017
L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15; T.C. A23WE	SA3316WE	Installation of a 16-inch coach class serving cart Model 953000-249, 7805000-201, -203, -205, -207 in the passenger main deck coach areas and/or lower galley service areas. Amended 11/19/79.	WE	34226	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1, L-1011-385-1-14, -15; T.C. A23WE	SA3317WE	Installation of 13-inch waste cart Model 956000-231, -233, -235, -237, -239 in passenger main deck and/or lower galley service areas. Amended 11/2/79.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90265

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
L-1011-385-1, L-1011-385-1-14, -15; T.C. A23WE	SA3709WE	A bolt-on retract actuator fitting specified by FAA sealed Aviation Hydraulics (Stellar Canoga Ind.) installed on the main landing gear outer cylinder. Issued 1/22/79.	WE	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1-15; T.C. A23WE	SA1407CE	Install Fairchild auto-annunciator system. Issued 4/3/78.	CE	79400	Trans World Airlines, Inc. Room 1-422 Kansas City Int'l Airport Kansas City, MO 64153
L-1011-385-1-15; T.C. A23WE	SA1406CE	Install Delco electronics triple C-IV inertial navigation system. Issued 4/3/78.	CE	79400	Trans World Airlines, Inc. Room 1-422 Kansas City Int'l Airport Kansas City, MO 64153
L-1011-385-1-15 (193T-Cathay Pacific Ser.)	SA3076WE	Installation of a thirteen inch cool beverage cart. Amended 10/5/79.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1-15 (1935-Saudia Series); T.C. A23WE	SA3315WE	Installation of 16-inch beverage cart Model 954000-225 in passenger main deck and/or lower galley service area. Issued 12/15/76.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1 (193K); T.C. A23WE	SA2689WE	Installation of horizontal situation indicator. Issued 5/11/73.	EU	26700	Court Line Aviation Lutton Airport Lutton, England
L-1011-385-1-193A; T.C. A23WE	SA2793WE	Cart tiedown assembly. Issued 12/20/73.	WE	48550	H. Koch & Sons Koch Road Corte Madera, CA 94925
1049 Series; T.C. 6A5	SA1-312	Replacement of laminated Sierracin cabin windows with built-up sheet metal plug.	EA	70600	Seaboard & Western Airlines JFK International Airport Jamaica, NY 11430
1049 Series; T.C. 6A5	SA1-352	Aft facing, folding, stewardess seat TECO 527A-1 at fuselage station 338.	EA	70600	Seaboard & Western Airlines JFK International Airport Jamaica, NY 11430
1049 Series; T.C. 6A5	SA4-310	Emergency radio transmitter.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94616
1049 Series; T.C. 6A5	SA4-311	Interior seating change to provide 98 cabin places.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-312	Ten man life raft stowage provisions.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-316	Emergency equipment.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-351	Modification of airplane including removal of coat closet.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA4-352	101 cabin seats and four crewmember seats.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-377	112 and 116 cabin seats and four crewmember seats.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-514	Interior modification and installation of passenger interior.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-948	Overhead emergency exit hatch between fuselage station 278.4 and 296.8 in top centerline of aircraft.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1074	Seat track and other modifications.	WE	79956	Twentieth Century Aircraft 10800 Sherman Way Sun Valley, CA 91352
1049 Series; T.C. 6A5	SA4-1167	Interior modification.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1181	Passenger interior configuration.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1049 Series; T.C. 6A5	SA4-1322	Fire proofing of main landing gear doors to comply with Airworthiness Directive 60-05-02.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1371	Passenger interior for 105 occupants.	WE	30265	Dollar Lines, Ltd. 311 California Street San Francisco, CA 94101
1049 Series; T.C. 6A5	SA4-1396	Structural reinforcements.	WE	30265	Dollar Lines, Ltd. 311 California Street San Francisco, CA 94101
1049 Series; T.C. 6A5	SA4-1474	Weather radar.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series; T.C. 6A5	SA4-1498	Interior modification.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1565	Interior arrangement for 111 occupants.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series; T.C. 6A5	SA4-1649	Increase in zero fuel weight to 108,000 pounds.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA6EA	Pallets and rollers and guide rails.	EA	31500	Eastern Rotorcraft Corp. P.O. Box 110 Doylestown, PA 18901
1049 Series; T.C. 6A5	SA36SO	Cargo loading door, floor structure, fuselage reinforcements, cargo tie-down devices, etc.	SO	11326	Robert E. Anson and L.C. Callaway, Jr. 7211 SW 52 Court Miami, FL 33101
1049 Series; T.C. 6A5	SA186WE	Interior modification to 108 passenger configuration.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series; T.C. 6A5	SA188WE	Catenary cargo restraining net at fuselage station 710 on aircraft converted to cargo configurations.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA189WE	Modification of air conditioning system for Class E cargo compartment.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA200SO	Cockpit voice recording system.	SO	34126	Eastern Air Lines, Inc. International Airport Miami, FL 33148
1049 Series; T.C. 6A5	SA219WE	Modification of 1049 M.L.G. orifice plate.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA232WE	Structural reinforcement to wing to permit operation at higher weights.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA456WE	Modification to allow operation at the following weights: takeoff - 142,100 pounds; landing - 114,500 pounds; zero fuel - 109,500 pounds.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA635WE	Single Collins 860E-1 distance measuring equipment system.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA659WE	Wing skin change.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series; T.C. 6A5	SA717WE	Single Collins 860E-1 distance measuring equipment system.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA755WE	Three 1,800-gallon RC97 fuselage tanks for carriage of petroleum fuels as cargo.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA901WE	Emergency exit lighting modification deleting the impact switch.	WE	52010	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA1143WE	Four 1600-gallon tanks.	WE	52010	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1049 Series; T.C. 6A5	SA1289WE	United Control V-557 cockpit voice recorder system.	WE	36100	The Flying Tiger Lines, Inc. 7401 World Way West Los Angeles, CA 90009
1049 Series; T.C. 6A5	SA1362WE	Collins 642C-1 cockpit voice recorder system.	WE	08170	Airlift International, Inc. International Airport San Francisco, CA 94128
1049-G-82, 1049-H-82; T.C. 6A5	SA1843WE	Installation of RCA AVQ-50 weather radar with McMillan 7161X radome and Collins 37P-4 glide slope antenna.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
1049H; T.C. 6A5	ST489SO	Installation of cargo restraining bulkhead. Issued 2/1/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
1049, 1649 Series; T.C. 6A5, 4A17	SA4-608	Engine mount core assemblies DB-643-1 on Wright TC18 Series engines.	WE	30500	Dow-Elco 1313 W. Olympic Boulevard Montebello, CA 90640
1649A; T.C. 4A17	SA4-1402	Reinforcing structure.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1649A; T.C. 4A17	SA258WE	One Type III emergency exit.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1649A; T.C. 4A17	SA259WE	Interior installation.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1649A; T.C. 4A17	SA466CE	Fairchild A-100 cockpit voice recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
1649A; T.C. 4A17	SA836WE	Hydro-Aire Mark II anti-skid braking system to reduce required landing field length.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
1649A-98; T.C. 4A17	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
1649A-98; T.C. 4A17	SA2666WE	Ceconite 102 material covering rudders and trim tabs. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
LOCKHEED-GEORGIA COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329; T.C. 2A15	SA4-1656	Custom interior.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA5SW	Sperry SP-40 autopilot modification. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
1329; T.C. 2A15	SA12SW	Interior modification. Reissued April 1973..	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA14WE	Interior modification and zero fuel weight increases to 23,700 lbs.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA15WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA16GL	Install AMP inverter MGE 23-340 Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
1329; T.C. 2A15	SA19WE	Installation of third crewmember seat.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA20WE	Battery.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA21WE	Inverter compartment modification.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA22WE	Interior installation.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA31EA	Bulkhead and door at station 290.875.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA32EA	Bulkhead and door at station 527.5	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA32WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA35WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA44WE	Custom interior.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA45WE	Custom interior.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA57WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA58WE	Interior modification.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA114EA	Openings in fuselage and installation of emergency exit.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA146WE	Modification of pressurization outflow system.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045

LOCKHEED-GEORGIA CO. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329; T.C. 2A15	SA173SW	Battery relocation to inverter well and inverter relocation in compartment forward of nose. Reissued 4/73.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA187WE	Interior modification and zero fuel weight increase to 23,700 pounds.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA190WE	GTCP 30-56 auxiliary power unit. Ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Hwy. Los Angeles, CA 90045
1329; T.C. 2A15	SA205EA	Angle of attack system. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329; T.C. 2A15	SA209EA	Fabrication and installation of three-place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA212WE	Modification of interior.	WE	52010	Lockheed Aviation Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA217EA	Angle of attack system. Amended 12/14/67.	NE	26010	Continental Development Corp. P.O. Box 511 Ridgefield, CT 06877
1329; T.C. 2A15	SA230SW	Interior modification. Reissued 4/73.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA231WE	Interior installation.	WE	52010	Lockheed Aviation Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA237SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA241SW	Retractable jump seat. Reissued 4/73.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA243SW	Installation of United Data recorder model F542. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
1329; T.C. 2A15	SA244EA	Baggage compartment smoke detector system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA246EA	Interior bulkhead and door at fuselage station 310.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA253SW	Installation of auxiliary 250 VA inverter. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
1329; T.C. 2A15	SA254SW	Jump seat. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA255SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA287WE	Reserve hydraulic oil transfer system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA288WE	Interior modification and zero fuel weight increase to 23,700 pounds.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA295EA	Cabin flooring.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA296EA	Relocation of receiver/transmitter FT-556/APX-46 IFF. Amended 12/11/67.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329; T.C. 2A15	SA297EA	DMET system.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA298EA	FM radiophone and R/C communications.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA299EA	Stowage box assembly.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA299WE	Interior modification and zero fuel weight increase to 23,700 pounds.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA302SW	HF-1 and HF-LM overspeed warning system.	SW	40000	The Hamilton Company 106 Neuhaus St. Houston, TX 77002
1329; T.C. 2A15	SA307WE	Custom interior.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA310SW	Jump seat.	SW	34000	Executive Aircraft Serv., Inc. Redbird Airport Dallas, TX 75232 AND
1329; T.C. 2A15	SA310SW	Jump seat.	SW	22792	Clark Engineering Service 6441 Happy Lane Dallas, TX 75221
1329; T.C. 2A15	SA322SW	Crew baggage rack and fire proof stainless steel box between stations 619.0 and 655.25.	SW	77010	Superior Oil Company Houston, TX 77002
1329; T.C. 2A15	SA331EA	Electronic equipment.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA334WE	Interior modification and zero fuel weight increase to 23,700 pounds. Amended 11/10/65.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA336SW	Couch. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA345SW	Bendix Doppler radar navigation system.	SW	12250	Associated Radio Service Co. 7515 Lemmon Ave. Dallas, TX 75220
1329; T.C. 2A15	SA346SW	Koehler Air-Lav 45 with outside servicing.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232 AND
1329; T.C. 2A15	SA346SW	Koehler Air-Lav 45 with outside servicing.	SW	27792	Clark Engineering Service 6441 Happy Lane Dallas, TX 75221
1329; T.C. 2A15	SA357EA	Bulkhead and door at fuselage station 527.5. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA359EA	Bulkhead at fuselage station 310.2. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	ST4168O	Installation of a Collins AP-104, S/N 5136 and up.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
1329; T.C. 2A15	SA424SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA452EA	Bulkhead and door at fuselage station 329 13/32. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA496EA	Installation of Vis-Audio engine low RPM warning system Model 600J. Amended 5/13/69.	EA	51095	Martin Lipstein 97 Stoneybrook Drive Metuchin, NJ 08840
1329; T.C. 2A15	SA496SW	Cockpit jump seat.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232

LOCKHEED-GEORGIA CO. 4

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329; T.C. 2A15	SA499EA	Installation of bulkhead and door at F.S. 523.	EA	12500	Atlantic Aviation Service Co. P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA530EA	Electronics installation per Lockheed Report 3163. Interior installation per Lockheed Report 3164 and AFM Supplement No. 2.	EA	52012	Lockheed Aircraft Serv. Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA535SW	Relocation and use of miniature switches in fuel flow system.	SW	12250	Associated Radio Service Co. 7515 Lemmon Ave. Dallas, TX 75220
1329; T.C. 2A15	SA536SW	Litton low range radio altimeter system.	SW	12250	Associated Radio Service Co. 7515 Lemmon Ave. Dallas, TX 75220
1329; T.C. 2A15	SA548EA	Installation of spare tire storage provisions. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329; T.C. 2A15	SA549EA	Installation of stowage provisions for 4 metal containers and tools. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329; T.C. 2A15	SA549SW	Spare tire mount.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA576EA	Alteration of AC system control panel.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA592EA	Incorporation of systems and equipment complying with Category II performance standards.	EA	80910	United States Air Force Hq. 89th Military Airlift Wing (SM) MAC Andrews AFB Washington, D.C. 20331
1329; T.C. 2A15	SA602SW	Hinged instrument panel.	SW	12250	Associated Radio Service Co. 7515 Lemmon Ave. Dallas, TX 75220
1329; T.C. 2A15	SA616EA	Installation of UHF/FM secure system.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA616SW	Spare tire rack. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA618SW	Interior modifications. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, Tx 76106
1329; T.C. 2A15	SA623SW	Low oil pressure warning switch.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA647EA	Modification of Collins FD109G flight director.	EA	80910	Dept. of the Air Force Hq. 89th Military Wing (SM) MAC Andrews AFB Washington D.C. 20331
1329; T.C. 2A15	SA652SW	Auxiliary power unit.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA700SW	Audible fire warning system.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA703SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA762SW	Smith servo altimeter system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA769SW	Collins 329P-1D peripheral commander.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329; T.C. 2A15	SA780SW	Bendix PB-60 automatic flight control system.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
1329; T.C. 2A15	SA781SW	Bendix FD-300 flight director system.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
1329; T.C. 2A15	SA782SW	Bendix polar path compass system.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
1329; T.C. 2A15	SA782EA	Installation of Lamar, Inc. Model LSM-1 engine speed monitor. Amended 6/26/70.	EA	49339	Lamar, Incorporated Burlington Country Airport Medford, NJ 08055
1329; T.C. 2A15	SA783SW	Bar extension equipment shelf.	SW	12250	Associated Radio Service Co. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA789WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA797CE	Install Kollsman altimeter P/N B39049-10-226 and altitude alerting unit P/N B55471-41-180.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l. Airport Kansas City, MO 64153
1329; T.C. 2A15	SA798CE	Install Bendix standby horizon P/N 19787991-1 & inverter type PS-823A, P/N 501-1075-1.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l. Airport Kansas City, MO 64153
1329; T.C. 2A15	SA803WE	Battery relocation.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA827SW	Fairchild 5424-502 flight data recorder.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA828SW	Fairchild A100 cockpit voice recorder.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA837WE	Interior installation.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA851SW	Dual Bendix FD-60 flight director system.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
1329; T.C. 2A15	SA872SW	AP-104 autopilot, FD-109H/FD-109F flight director, comparator, AL-101 radio altimeter gyros, compass, and VHF/NAV interconnect for Category II operation.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
1329; T.C. 2A15	SA879SW	Hinged instrument panel and modification to control column.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA883SW	Mounting bracket antenna tuner.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 78420
1329; T.C. 2A15	SA884SW	Hoskins power supply support.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA885SW	Bulkhead coax fitting and VHF or FM antenna.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA887SW	L Band Antenna.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station, Dallas, TX 78420
1329; T.C. 2A15	SA900SW	Skyphone antenna	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420

Aircraft Make, Model & T.C. No.	STC No.	Description	FG	STC Code	STC Holder
1329; T.C. 2A15	SA902SW	Howell autotemp indicators.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA904SW	Relocation of mach airspeed warning switch.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA917SW	Master fire warning system, TVI system glare shield, instrument panel, and fuel management panel modification.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA919SW	Collins AL-101 radio altimeter system.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA928SW	Relocation of batteries and addition of third battery, AC inverters.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA952SW	Bendix doppler radar system.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA953SW	Bendix radio altimeter.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA955WE	Rain repellent system.	WE	45500	Jay-Dee Acft. Supply Co. Inc. 3021 Airport Avenue Santa Monica, CA 90405
1329; T.C. 2A15	SA990SW	Collins AF104 autopilot and FD109H/FD109P flight directors and IDC air data computer.	SW	3400	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA1005SW	General Precision GPK-1000/GPK-601 doppler radar navigation system.	EA	38518	General Precision Systems, Inc. 63 Bedford Road Pleasantville, NY 10570
1329; T.C. 2A15	SA1011SW	Relocation of inverters and batteries. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
1329 Series; T.C. 2A15	ST1032SO	Replacing existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 11/16/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
1329; T.C. 2A15	SA1104SW	Hartman vertical scale engine instruments and OAT instrument. Issued 12/4/69.	EA	40150	Hartman System Company, Inc. 360 Wolf Hill Road Huntington, NY 11746
1329; T.C. 2A15	SA1123WE	Kroehler Air-Lav Models 45 and 25.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1124WE	Assembly and installation of jump seat in cockpit doorway. Amended 3/19/68.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1125WE	Bendix doppler antenna.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1185SW	Litton LTN-51 inertial navigation system. Issued 8/24/70.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA1283WE	Interior furnishing and avionics equipment.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329; T.C. 2A15	SA1325WE	Two of three inverters relocated forward of the nose wheel well.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1326WE	Two batteries relocated to under the floor at front of cabin.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1359WE	United Control F-542 flight data recorder system.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329; T.C. 2A15	SA1428SW	Collins INS-61B inertial navigation system. Reissued 11/72.	CE	24250	Collins Radio Company 325 10th Avenue, S.E. Cedar Rapids, IA 52406
1329; T.C. 2A15	SA1483WE	Installation of a modified control column component.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1512SW	Model 7107 battery fault warning system. Issued 11/14/72.	SW	66500	Ray Electronics 107 Braniff Drive San Antonio, TX 78216
1329; T.C. 2A15	SA1525SW	TRAMM BT1 600 nickel cadmium battery temperature indicator. Issued 10/18/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
1329; T.C. 2A15	SA1533SW	Lear-Siegler 51528-000 solid state voltage regulator. Issued 10/31/72.	SW	17116	Kenneth J. Brenner 1124 Parkhave Drive Richardson, TX 75080
1329; T.C. 2A15	SA1537WE	Installation of control column.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Hwy. Los Angeles, CA 90045
1329; T.C. 2A15	SA1869SW	Two Hamilton Standard air cycle refrigeration units. Issued 4/18/74.	SW	34000	Executive Aircraft Service, Inc. Div. of Cooper Airmotive, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA1997SW	Continuous ignition control system. Issued 6/18/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329; T.C. 2A15	SA2978SW	Oxygen system. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329; T.C. 2A15	SA2984SW	Low oil pressure sensor switch. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329; T.C. 2A15	SA2985SW	Inverter relocation. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329; T.C. 2A15	SA2998SW	Litton LTN-72R INS/RNAV system. Issued 5/23/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329; T.C. 2A15	SA4018WE	Installation of on-board air stairs. Issued 12/6/79.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
1329; T.C. 2A15	SA4082SW	Pitot heat monitoring system. Issued 2/12/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329-23 (Jetstar); T.C. 2A15	SA1126SO	Deletion of empennage de-icing provisions - removal of empennage de-icing boots. Issued 1/9/80.	SO	52020	Lockheed - Georgia Company 86 South Cobb Drive Marietta, GA 30063
1329-23, -23A, -23D, -23E; T.C. 2A15	SA1043WE	Installation of GTCP30-92 or GTCP30-92C auxiliary power units Amended 8/13/76.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Hwy. Los Angeles, CA 90045
1329-23A; T.C. 2A15	ST240GL	Installation of Litton LTN-211 omega navigation system. Issued 5/2/78.	GL	47630	K-C Aviation, Inc. Outagamie Airport Appleton, WI 54911
1329-23A; T.C. 2A15	SA868EA	Modification of Sperry SP40C auto-pilot, installed per STC SA1664WE. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329-23A; T.C. 2A15	SA883EA	Installation of AIMS equipment. Issued 9/10/71	SO	07700	Department of the Air Force Warner Robbins Air Material Area (MMC) Robins AFB, GA 31093
1329-23A; T.C. 2A15	SA950EA	Installation of air-conditioning flood duct. Reissued 10/13/77.	EA	63275	PATS, Incorporated 9033-C Red Branch Road Columbia, MD 21045
1329-23A, -23D, -23E; T.C. 2A15	SA374CE	Installation of Symbolic Displays Twilighter Mk. III supplemental lighting system. Amended 5/29/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
1329-23A, -23D, -23E; T.C. 2A15	SA880EA	Installation of Solar T-62T-39 gas turbine auxiliary power unit. Amended 12/21/79.	EA	63275	PATS, Inc. 7190-B Oakland Mills Road Columbia, MD 21046

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329-23A, -23D, -23E; T.C. 2A15	SA898CE	Installation of AID battery temperature monitor and over-temperature warning system. Amended June 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Wichita, KS 67202
1329-23A, -23D, -23E, -25; T.C. 2A15	ST911SO	Installation of Bendix GPW-83 ground proximity warning system. Amended 8/3/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
1329-23A, -23D, -23E; T.D. 2A15	SA918SW	Installation of Teledyne avionics normalized angle of attack indicating system. Reissued 1/7/72.	SW	78127	Teledyne Inc. 3401 Shiloh Road Garland, TX 75040
1329-23A, -23D, -23E; T.C. 2A15	SA954EA	Installation of battery isolation system. Issued 5/4/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329-23A, -23D, -23E; T.C. 2A15	SA996EA	Installation of Shaw Aero fuel filler cap P/Ns 457-2, -266, -370, 431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
1329-23A, -23D, -23E, -25; T.C. 2A15	SA1459CE	Installation of mocrowave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
1329-23A, -23D, -23E; T.C. 2A15	SA1664WE	Installation of Sperry SP-40C auto flight control system and SPI-73B Sperry instrumentation system.	WE	74570	Sperry Flight Systems Div. Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
1329-23A, -23D, -23E; T.C. 2A15	SA1930WE	Installation of Collins Model WP-130G weather radar system. Reissued 8/4/69.	WE	24253	Collins Radio Company 9841 Airport Boulevard Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
1329-23A, -23D, -23E; T.C. 2A15	SA2603WE	Installation of single point refueling system. Amended 8/20/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-23A, -23D, -23E; T.C. 2A15	SA3207WE	Installation of Rosemount pitot/static probes. Issued 7/23/76.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3208WE	Installation of Litton LTN-104 navigation system. Issued 7/23/76.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3209WE	Installation of Collins AP-105 autopilot and FD-109 flight director. Issued 7/16/76.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3210WE	Installation of a Teledyne angle of attack system. Issued 11/19/76.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3221WE	Installation of a single point refueling system for Lockheed Jetstar airplane with AiResearch TFE731-3 engines. Amended 8/18/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-23A, -23D, -23E; T.C. 2A15	SA3268WE	Installation of a single or dual Collins 61B inertial navigation system. Amended 12/8/77.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
t) (					
1329-23A, -23D, -23E; T.C. 2A15	SA3365WE	Installation of Delco Carousel IVA inertial navigation system. Issued 6/7/77.	WE	85135	Western Commander, Inc. 16300 Dailey Drive Van Nuys, CA 91406
1329-23A, -23D, -23E; T.C. 2A15	SA3389WE	Installation of Delco C-IVA inertial navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3536WE	Installation of nickel-cadmium batteries in aircraft nose compartment. Issued 12/9/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3563WE	Installation of Eldec engine fuel flow and totalizer system. Issued 2/22/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329-23A, -23D, -23E; T.C. 2A15	SA3704WE	Installation of Litton LTN-211 Omega Navigation System. Amended 1/30/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA2943WE	Installation of recognition lights on horizontal stabilizer upper surface. Amended 3/11/77.	WE	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 91406
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3206WE	Installation of Garrett AirNav 100 area navigation system. Amended 6/1/78.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3372WE	Installation of single or dual ONTRAC III VLF/Omega navigation systems. Amended 5/13/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3390WE	Installation of Global Model GNS-500A VLF/Omega navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3391WE	Installation of Delco C-IVA inertial navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3572WE	Installation of Sperry TERN-100 area navigation system. Issued 2/14/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -25; T.C. 2A15	SA3520WE	Installation of Sperry SPZ-500 autopilot and Sperry SPI-80/81 flight directors. Issued 11/23/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23D; T.C. 2A15	SA928EA	Installation of battery isolation circuit. Issued 7/14/72.	EA	70580	Scott Paper Company Scott Plaza Philadelphia, PA 19113
1329-23D; T.C. 2A15	SA931EA	Installation of battery isolation system. Issued 8/24/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
L1329-23E; T.C. 2A15	SA116GL	Installation of Global GNS-500A VLF/OMEGA navigation system. Amended 3/2/78.	GL	61880	Onan Corporation 1400 - 73rd Avenue, Northeast Minneapolis, MN 55432
1329-23F; T.C. 2A15	SA1989WE	Installation of United Control approach speed system, computer P/N 965-0158-001. Reissued 8/26/70.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA1049EA	Installation of seat tracks and cabin decks. Issued 6/7/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329-25; T.C. 2A15	SA1052EA	Installation of Solar gas turbine auxiliary power unit T-62T-40C. Amended 3/12/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
1329-25; T.C. 2A15	SA1056EA	Installation of a speed command of attitude and thrust system (SCAT). Amended 7/19/79.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA2920SO	Installation of BKM pitot heat monitor system. Issued 2/28/79.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329-25;	SA2976SW	Floor plan arrangement, floorboards and seat track. Issued 4/13/79.	SW	47632	K-C Aviaiton, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2977SW	Pressurized water system lavatory, commissary, and bar. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2979SW	Flushing toilet with outside servicing capabilities. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2980SW	Galley component assembly. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2981SW	Baggage compartment modification aft cabin, station 547.5 to 567.0. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329-25; T.C. 2A15	SA2982SW	Baggage compartment modification, station 240.0 to 310.0, right side. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2983SW	Cabin entry ramp, center aisle, station 284.0 to 328.0.	SW	47632	K-C Aviation 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA3297WE	Installation of GTCP 30-92C auxiliary power unit. Issued 1/21/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-25; T.C. 2A15	SA3324WE	Installation of a single point refueling system for Lockheed Jetstar airplane. Issued 1/17/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-25; T.C. 2A15	SA3371WE	Installation of Teledyne angle of attack system. Issued 3/10/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
382; T.C. A1SO	SA3793WE	Installation of Tracor 7640A ONS. Issued 2/2/79.	WE	79200	Transinternational Airlines Engineering Department P.O. Box 2504 Oakland International Airport Oakland, CA 94164
382, 382B; T.C. A1SO	ST427SO	Installation of cargo rail system Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382, 382B, 382E; T.C. A1SO	SA733CE	Installation of cargo pallets.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382, 382B, 382E, 382F, 382G; T.C. A1SO	SA1625WE	Pallet assembly provisions per FAA Sealed L.A.S. Top Drawing 4035910 as modifying aircraft with four KC-97, 1800 gallon tanks installed in accordance with STC SA889WE. Amended 2/23/77.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
382, 382B, 382E, 382G; T.C. A1SO	ST400SO	Installation of palletized cargo loading and restraint system. Amended 11/25/74.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382, 382B, 382E, 382G; T.C. A1SO	ST407SO	Installation of palletized cargo loading and restraint system. Amended 4/7/72.	SO	52020	Lockheed-Georgie Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA303AL	Installation of 4000 gallon steel tank in the cargo compartment.	AL	44045	Interior Airways, Inc. P.O. Box 3029 Fairbanks, AK 99701
382B; T.C. A1SO	SA368SO	Palletized cargo loading system. Amended 7/10/67.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA374SO	Palletized cargo loading system per Lockheed Industrial Products top assy. dwg. 256-000. Amended 7/25/69.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA1274WE	Triple seat/bunk. Amended 7/10/67.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98109
382B, 382E, 382G; T.C. A1SO	ST401SO	Installation of palletized cargo loading and restraint Amended 11/25/74.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B, 382E, 382G; T.C. A1SO	ST527SO	Installation of inplane cargo system in accordance with Aeronautical Engineers, Inc. dwgs. AE2178 & AE2178, Change "C". Reissued 2/13/73.	SO	73870	Southern Air Transport, Inc. P.O. Box 1266 International Airport Miami, FL 33148
382B, 382E, 382G; T.C. A1SO	SA569AL	Installation Collins FPC-75 ground proximity warning system. Issued 11/25/75.	AL	08488	Alaska International Air, Inc. P.O. Box 60029 Fairbanks, AK 99701
382E; T.C. A1SO	SA2461WE	Installation of Sorm bulk liquid cargo tank assembly SI-3100. Issued 12/17/71.	NW	73820	Sorm Industries 7999 Perimeter Road, South Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
382E; T.C. A1SO	SA3171WE	The auxiliary power unit Model GTC 85-71 located in the forward end of the left hand main landing gear wheel well fairing has been replaced by an AiResearch Gas turbine compressor Model GTCP 85-98CK(A). Issued 4/9/76.	WE	87450	World Airways, Inc. Maintenance & Engrg. Center Oakland International Airport Oakland, CA 94614
382E, 382G; T.C. A1SO	SA2418WE	Installation of cargo loading system. Issued 9/29/71.	WE	70258	Saturn Airways, Inc. P.O. Box 2426 Oakland International Airport Oakland, CA 94614
382E, 382G; T.C. A1SO	SA3144WE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/9/76.	WE	68770	Rockwell International Corp. Collins Radio Group 750 S. Douglas Street El Segundo, CA 90245
382G; T.C. A1SO	ST913SO	Installation of six 24" x 36" plug type doors in cargo compartment walls. Issued 12/1/76.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G; T.C. A1SO	SA1056SO	Increase in zero fuel weight from 126,790 lbs. to 128,790 lbs. with pylon tanks on and 125,000 lbs. to 127,000 lbs. without pylon tanks. Issued 3/23/79.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G; T.C. A1SO	SA2912WE	Installation of palletized dual LTN-51 INS or dual LTN-72 INS or combination of either. Amended 9/26/74.	WE	51500	Litton Systems, Inc. Aero Product Division 21050 Burbank Blvd. Woodland Hills, CA 91364
382G; T.C. A1SO	SA2929WE	Installation of palletized dual LTN-51 or dual LTN-72 INS or combination of either. Issued 10/2/74	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91364

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
LOCKHEED AIRCRAFT INTERNATIONAL

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
402-2; T.C. 2A11	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

LUSCOMBE AIRCRAFT CORPORATION, GEORGIA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
8 Series; T.C. 694	SA1-271	Metal skin on wings.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047
8 Series; T.C. 694	SA4-173	Lycoming O-235-C1 or O-290-D engine in Model 8E or T8F landplane and Lycoming O-320 engine in Model 8E or 8F landplane.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
8 Series; T.C. 694	SA4-290	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
8 Series; T.C. 694	SA4-430	Metal wing covering.	WE	05600	Aircraft Modification and Repair Municipal Airport Hayward, CA 94541
8 Series; T.C. 694	SA4-463	New exhaust stack crossover tube with standard bend radius of 5.0 inches.	RM	81060	Universal Aircraft Ind. P.O. Box 5306 Terminal Annex Denver, CO 80217
8 Series; T.C. 694	SA4-503	New exhaust stacks.	RM	81060	Universal Aircraft Ind. P.O. Box 5306 Terminal Annex Denver, CO 80217
8 Series; T.C. 694	SA4-560	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. Oxnard-Ventura Airport Oxnard, CA 93030
8 Series; T.C. 694	SA4-642	Lycoming O-290-D2 engine and Sensenich M76AM-2 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
8 Series; T.C. 694	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
8 Series; T.C. 694	SA4-874	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Co. P.O. Box 3428 Van Nuys, CA 91408
8 Series; T.C. 694	SA4-1346	Fiberglass covering of aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
8 Series; T.C. 694	SA4-1443	Bonite covering of wings.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
8 Series; T.C. 694	SA4-1515	Retractable wheel fairings.	WE	30708	Duce Aircraft Co. Route 1, Box 711 Valley Center, CA 92082
8 Series; T.C. 694	SA87CE	Dorsal fin. Issued 6/24/70.	XX	67540	Kenneth Reuterskiold (Address Unknown)
8 Series; T.C. 694	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
8 Series; T.C. 694	SA150CE	Removal of right door, right control stick, and right door catch.	GL	84846	Carl C. Webb P.O. Box 217 Flora, IL 62839
8 Series; T.C. 694	SA317WE	Full flow filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
8 Series; T.C. 694	SA337SW	Door removed.	SW	26710	James E. Cox 2113 Bingle Road Houston, TX 77055
8 Series; T.C. 694	SA344CE	Lycoming O-320 or O-320-A1A engine, McCauley 1C172/MGM 7462 propeller and Prestolite ALK 5001 S4UO alternator. Reissued 8/13/69.	SO	52580	Luscombe Aircraft Corporation 3201 Cains Hill Place, N.W. Atlanta, GA 30305

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
8 Series; T.C. 694	SA509WE	Removal of door for parachute jumping and aerial photography operations.	WE	48512	Geza Kiss 9017 Birchleaf Avenue Downey, CA 90240
8 Series; T.C. 694	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
8 Series; T.C. 694	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
8 Series; T.C. 694	SA1008WE	Poly-Fiber covering of both wings. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92402
8 Series; T.C. 694	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
8 Series; T.C. 694	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
8, 8A, 8B, 8C, 8D, 8E, 8F; T.C. A-694	SA2715WE	Installation of carry-through spar beams. Amended 8/28/73	WE	39355	William J. Gratrix P.O. Box 8217 Airport Station San Francisco, CA 94128
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA69NW	Installation of Matney's engine charge air - air filter assembly. Amended 10/8/74.	NW	56600	D. H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA489EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
8, 8A, 8B, 8C, 8D, 8E, 8F, T-8F; T.C. 684	SA2666WE	Ceconite 102 material covering of wings. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
8, 8A, 8C, 8E, 8F, T8F; T.C. 694	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/30/70.	RM	40500	Hanna-Aero Corporation 5222 Holly Street Littleton, CO 80120
8B; T.C. 694	SA201GL	Installation of Sensenich 74CK propeller in lieu of original fixed pitch wood propeller using special bolts supplied by the propeller manufacturer. Issued 11/10/77.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
8E Landplane; T.C. A694	SA379GL	Installation of a Lycoming O-235-C2C engine, fiberglass cowling and miscellaneous modifications. Issued 1/4/80.	GL	61752	Dewey G. Norton 1351 Manton Boulevard Canton, MI 48187

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
8E or 8F Landplane; T.C. 694	SA229GL	Installation of Lycoming O-235-C1, O-235-C1C, O-235-C2A, O-235-C2B or O-235-C2C. Issued 3/16/78.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
8E or 8F; T.C. 694	SA230GL	Installation of single piece front and lower cowl. Amended 4/10/78.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

LUSCOMBE AIRPLANE CORPORATION, TEXAS

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Phantom 1; ATC 552	SA1-2	Tail wheel assembly.	EA	33896	Eveland Aircraft Service P.O. Box 575 Davis Edwards Airport Bayport, NY 11705
Phontom 1; ATC 552	SA193WE	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Co. P.O. Box 3428 Van Nuys, CA 91408
Phantom 1; ATC 552	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Phantom 1; ATC 552	SA2666WE	Ceconite 102 material covering of wings. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MARTIN-MARIETTA CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
202, 202A; T.C. 795	SA1-560	2010X Series readome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
202, 202A; T.C. 795	SA580	B-300 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
202, 202A; T.C. 795	SA174EA	Cabin interior modification for cargo configuration.	EA	09520	Allegheny Airlines Greater Pittsburgh Airport Pittsburgh, PA 15231
202, 202A, 404; T.C. A-795, 1A7	SA107CE	High intensity wing tip lights, tail light, with or without high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
202, 202A, 404; T.C. A-795, 1A7	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 North Street Los Angeles, CA 90063
202, 202A, 404; T.C. A-795, 1A7	SA1744WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
202, 202A, 404; T.C. 795, 1A7	SA2666WE	Ceconite 102 material covering on rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 North Street Los Angeles, CA 90063
202, 404; T.C. 795, 1A7	SA4-153	Oil filter 30816A with CP-1438-C element.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
202, 404; T.C. 795, 1A7	SA4-501	Engine mount core assemblies.	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
202, 404; T.C. 795, 1A7	SA4-525	Engine mount core 106-1F and 106-1J.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
202, 404; T.C. 795, 1A7	SA4-568	Engine mount core assemblies DE1468.	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
202, 404; T.C. 795, 1A7	SA375WE	Ceconite 101 covering of rudder.	WE	26240	Cooper Engineering Co. P.O. Box 3428 Van Nuys, CA 91408
404; T.C. 1A7	SA1-524	2010X Series radomes.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
404; T.C. 1A7	SA1-528	1010 Series radomes.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
404; T.C. 1A7	SA3-402	Floor modification, swivel seat installation, and divan seat belt installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
404; T.C. 1A7	SA3-403	Installation of Bendix RDR-1 weather radar system, radome and relocation of airspeed pitot. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
404; T.C. 1A7	SA3-404	Installation of Sperry SP20 autopilot. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
404; T.C. 1A7	SA3-405	Installation of APU - Lawrence Model 30D. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
404; T.C. 1A7	SA3-418	Installation of cockpit and general cabin arrangement and furnishings. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
404; T.C. 1A7	SA4-949	Auxiliary power plant.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
404; T.C. 1A7	SA4-950	Sperry A-12 autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
404; T.C. 1A7	SA4-951	Furniture.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
404; T.C. 1A7	SA4-952	Radome and structure.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
404; T.C. 1A7	SA4-953	Outer wings modified for integral type fuel tanks.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
404; T.C. 1A7	SA4-1042	Passenger seating capacity increased to 44.	WE	62070	Pacific Air Lines, Inc. San Francisco Inter'l. Airport San Francisco, CA 94119
404; T.C. 1A7	SA4-1124	Taran II demonstration weather radar system.	WE	43330	Hughes Aircraft Company Culver City, CA 90230
404; T.C. 1A7	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
404; T.C. 1A7	SA4-1220	Sperry A-12 autopilot system.	SO	78390	Tempo Design Corporation P.O. Box 456 Miami, FL 33148
404; T.C. 1A7	SA4-1221	Radome and radar antenna.	SO	78390	Tempo Design Corporation P.O. Box 456 Miami, FL 33148
404; T.C. 1A7	SA4-1229	Two 15KS-1000-A1 aircraft rocket engines.	WE	02315	Aerojet-General Corporation 6352 N. Irwindale Avenue Azusa, CA 91702
404; T.C. 1A7	SA4-1615	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
404; T.C. 1A7	SA64SO	B-300 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
404; T.C. 1A7	SA84WE	Sperry A-12 autopilot.	EA	61242	National Supply Company Allegheny County Airport Dravosburg, PA 15034
404; T.C. 1A7	SA97EA	Conversion to executive interior.	SO	31370	East Coast Flying Service, Inc. P.O. Box 18007 Imerson Airport Jacksonville, FL 32201
404; T.C. 1A7	SA258SO	Immersion heaters in oil tanks 404-2055010 for ground operation only.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA259SO	BMEP bleed system for R-2800CB-3 engines.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA260SO	Swivel seat intercostals at Station 616.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA261SO	Direct pressure actuated manifold pressure gage system.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA268SO	Manufacture replacement parts for Adel ADZ24278.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA276SO	J & H G-29-7BT generators.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA322SO	(1) Installation of 44-seat interior, (2) rearrange 44-seat interior. Aircraft may be modified under either option. Approval of option 2 requires implementation of option 1. Amended 5/10/68.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
404; T.C. 1A7	SA325SO	Interior changes in passenger and jump seats.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
404; T.C. 1A7	SA328SO	Repair of corrosion damaged wing spar scarf splices. Reissued 11/7/78.	SO	54635	Marco Island Airways, Inc. 3250 Island Airways Miami, FL 33125
404; T.C. 1A7	SA329SO	Replacement of cockpit door lock.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA349SO	Hydraulic regulator change.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
404; T.C. 1A7	SA355SO	Whittaker 2L333021 NLG hydraulic pressure reducer valve replaced with Hydraulics Research 42028180-001 valve.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
404; T.C. 1A7	SA392SO	Install Goodyear 9543138 wheels in place of Goodyear 9540512.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA395EA	Rear wing spar flange repaired.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	ST431SO	Installation of inflatable evacuation slide.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
404; T.C. 1A7	SA1122WE	Wing flap actuated landing gear aural warning system.	WE	62070	Pacific Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94119
404; T.C. 1A7	SA1428WE	Installation of cargo interior.	WE	62070	Pacific Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94119

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MAULE AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M-4; T.C. 3A23	SA316SO	Installation of carburetor ice detector.	SO	71545	Charles B. Shivers, Jr. 8929 Valleybrook Road Birmingham, AL 35206
M-4; T.C. 3A23	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
M-4; T.C. 3A23	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Bee Dee M-4, M-4; T.C. 3A23	SA273WE	Vacuum system 121A.	WE	40689	Harms Industries P.O. Box 3246 Inglewood, CA 90306
M-4, 4C, 4S, 4T, M-4-210, 210C, 210S, 210T; T.C. 3A23	SA222AL	Installation of L-2500A skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
M-4, M-4C, M-4S, M-4T, M-4-210, M-4-210C, -210S, -210T, M-4-220, -220C, -220S, -220T, M-4-180C, M-4-180S, M-4-180T; T.C. 3A23	SA433AL	Installation of Wilbur's tire-cushioned model 2300 skis. Amended 12/16/71.	AL	86070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4, -4C, -4S, -4T, M-4-210, -210S, -210T; T.C. 3A23	SA693SW	AK223 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
M-4, M-4-210; T.C. 3A23	SA258CE	Remove right rear door.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4, M-4-210; T.C. 3A23	SA486CE	Installation of Canadian Aircraft Products, Ltd. Model 62-2000 floats. Amended 7/20/67.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M4, M-4-210, M-4-210C; T.C. 3A23	SA690SW	Wing tips modified.	SW	34900	Harvey J. Ferguson Upper Valley Aviation, Inc. McAllen, TX 78501
M4-4C, -4S, -4T, M-4-210, -210C, -210S, -210T; T.C. 3A23 Applicable only to aircraft modified by STC SA963SW.	SA808SW	Installation of Mitchell Model AK246 omni-tracker.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M-4-210, -5-210C; T.C. 3A23	SA164AL	Installation of auxiliary cabin heater and cowl flaps. Amended 2/10/76.	AL	86070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA589CE	Installation of Fleet Manufacturing, Ltd. Model 2500 floats.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA609CE	Installation of Edo Corp. Model 248A-2440 or Model 248B440 floats. Amended.	SO	56750	Maule Aircraft Corp. Spence Air Force Base Moultrie, GA 31768
M-4-210, M-4-220, M-4; T.C. 3A23	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M-4-210C, -220C, M-5-210, -220C; T.C. 3A23	SA2931WE	Installation of plexiglas covering for two main cabin doors, right passenger door, and baggage door. Issued 9/17/74.	WE	36190	Foothill Aircraft Sales and Service 13th and Benson Upland, CA 91786
M4-220; T.C. 3A23	SA415SO	Installation of Mitchell Century II autopilot. Amended 6/26/69.	SO	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M4-220; T.C. 3A23	SA417SO	Installation of aileron stabilizer and tracker.	SC	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768
M-4-220, M-4-220C, M-4-220S, M-4-220T;	SA610CE	Installation of Edo Corp. Model 248A-2440 or Model 248B-2440 floats. Amended 9/19/69.	SO	56750	Maule Aircraft Corporation Spence Air Force Base Moultrie, GA 31768
M-5-210C, M-5-22C, M-5-235C; T.C. 3A23	SA937SO	Installation of aqua Model 2400 floats. Reissued and amended 7/20/77.	SO	22776	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
M-5-235C; T.C. 3A23	SA1008WE	Installation of poly-fiber covering material of fuselage and empennage. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
M-5-235C; T.C. 3A23	SA1099SO	Installation of Fiberfloat Model 2400 floats and modified wing tips. Issued 9/4/79.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

THOMAS H. McCLISH

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B, B75L, B85C; T.C. 715	SA4-1210	Installation of Bonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	BONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
B, B75L, B85C; T.C. 715	SA4-1231	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Co. P.O. Box 3428 Van Nuys, CA 91408
B, B75L, B85C; T.C. 715	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
B75L, B85C; T.C. 715	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
B75L, B85C; T.C. 715	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 10/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
B75L, B85C; T.C. 715	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
B85C; T.C. 715	SA4-302	BH-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

McCULLOCH MOTORS CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MC-4C; T.C. 6H3	SH10WE	Four-place configuration and related changes.	WE	47260	Jovair Corporation 11920 W. Jefferson Boulevard Culver City, CA 90230

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

McDONNELL DOUGLAS CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C54-DC Series; T.C. 762	SA4-163	Auxiliary fuselage oil tank modification.	WE	19570	California Eastern Aviation, Inc. Airways Division Hangar 27, International Airport Oakland, CA 94614
C54-DC Series; T.C. 762	SA4-446	Seat track and passenger seat.	WE	62028	Overseas National Airways, Inc. International Airport Oakland, CA 94614
C54-DC Series; T.C. 762	SA4-633	Bulkhead Station 858 relocated to Station 881.	WE	79310	Transocean Airlines Oakland Airport Oakland, CA 94614
C54-DC Series; T.C. 762	SA2IN	Carrying cargo modification.	EU	14008	Aviation Traders Ltd. Municipal Airport Southend on Sea Essex, England
C54-DC Series; T.C. 762	SA938WE	Aural warning device to sound at a 30 degree wing flap position, to be in operation when the landing gear is not down and locked.	RM	46782	Johnson Flying Service, Inc. P.O. Box 1366 Missoula, MT 59801
C54-DC Series; T.C. 762	SA1183WE	RCA AVQ-75 distance measuring equipment (DME).	RM	46782	Johnson Flying Service, Inc. P.O. Box 1366 Missoula, MT 59801
C54-DC, C54A-DC, C54D-DC, C54E-DC, C54G-DC, DC-4; T.C. A-762	SA3298WE	Bendix wheels and brakes installation. Issued 11/23/76.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
C54-DC Series, DC-4; T.C. 762	SA1-115	1012 Series radomes.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
C54-DC Series, DC-4; T.C. 762	SA1-140	Cockpit heater and air intake and blower mounting.	EA	18750	Butler Aviation LaGuardia Field Flushing, NY 11371
C54-DC Series, DC-4; T.C. 762	SA1-507	2012X Series radomes.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
C54-DC Series, DC-4; T.C. 762	SA3-258	C-O-Two visual smoke detector, Type A1-V, P/N 74800.	GL	61700	Northwest Airlines, Inc. 1885 University Avenue South St. Paul, MN 55111
C54-DC Series, DC-4; T.C. 762	SA4-47	Generator system changed from 100 ampere to 200 ampere.	WE	19570	California Eastern Airways Interantional Airport Oakland, CA 94614
C54-DC Series, DC-4; T.C. 762	SA4-213	Radio rack in crew compartment.	EU	11855	Asiatic Aeronautical Co., Ltd. Tainan Airfield Tainan, Taiwan
C54-DC Series, DC-4; T.C. 762	SA4-317	Auxiliary oil tank.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
C54-DC Series, DC-4; T.C. 762	SA4-365	Emergency inpact light.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
C54-DC Series, DC-4; T.C. 762	SA4-372	CO and smoke detection system in belly baggage compartments.	WE	79956	Twentieth Century Aircraft Co. 436 N. Roxbury Drive Beverly Hills, CA
C54-DC Series, DC-4; T.C. 762	SA4-414	Emergency lighting.	WE	19570	California Eastern Aviation, Inc. International Airport Oakland, CA 94614
C54-DC Series, DC-4; T.C. 762	SA4-488	Modification of bulkhead, Station 260.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
C54-DC Series, DC-4; T.C. 762	SA4-492	Engine mount cores V.I.P. P/N's 104-1-B and 104-1-C interchangeable with Pratt & Whitney 70639 and Lord MP-26-1B engine mount cores on aircraft with R-2000 Series engines.	WE	83500	Vibration Isolation Products, Inc. 212 West Magnolia Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C54-DC Series, DC-4; T.C. 762	SA4-498	Engine mount core assemblies.	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
C54-DC Series, DC-4; T.C. 762	SA4-540	C-O-Two smoke detector system in cargo pits.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
C54-DC Series, DC-4; T.C. 762	SA4-790	C-O-Two smoke detector system in main cargo compartment and forward baggage compartment.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
C54-DC Series, DC-4; T.C. 762	SA4-843	Cabin interior seating arrangement revised.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
C54-DC Series, DC-4; T.C. 762	SA4-1399	Ceconite 101 covering of all fabric-covered surfaces.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
C54-DC Series, DC-4; T.C. 762	SA53SO	B-500-1 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
C54-DC Series, DC-4; T.C. 762	SA108SO	B-600-1 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
C54-DC Series, DC-4; T.C. 762	SA196SO	Installation of Wright Military Cyclone R-2600-35 engines (as modified per STC SE610SO or R-2600-35 engines having WAD P/N 417916 or 424010 gear boxes). Amended 3/20/74.	SO	21560	Charlotte Aircraft Corporation P.O. Box 1225 Miami, FL 33148
C54-DC Series, DC-4; T.C. 762	SA1117WE	Wing flap operated aural warning system. Amended 7/19/66.	WE	65018	Potter Aircraft Service, Inc. Lockheed Air Terminal Burbank, CA 91502
C54-DC, C54A-DC, C54B-DC, C54D-DC, C54E-DC, C54G-DC, DC-4, DC3A Series, DC3C Series, DC3D-4-1830-90C, DC-6, -6A, -6B, DC-7B; T.C. 762, 669, 781, 6A3, 6A4, 4A10	SA2666WE	Ceconite 102 material covering of: C54-DC Series - all fabric-covered surfaces; DC3A, DC3C, DC3D Series - rudder, elevators and ailerons; DC-6, -6A, -6B, DC-7B - rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C54A-DC, DC-3, -3A; T.C. 762, A-618, A-669	SA1008WE	Poly-fiber covering of rudder. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
C54B-DC, C54D-DC, C54E-DC, C54G-DC, DC-4; T.C. A-762	SA3173WE	Installation of P&WA R-2000-6 engines in Douglas C54 airplanes. Issued 4/30/76.	WE	42010	Helitec Corporation 4930 E. Falcon Drive Mesa, AZ 85205
C54P-DC, C54D-DC, C54G-DC, DC-4; T.C. A-762	SA3199WE	Cargo handling system installation. Issued 5/19/76.	WE	63700	PEMCO Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
C54B-DC, C54D-DC, C54G-DC, DC-4; T.C. A-762	SA3254WE	Nose wheel installation. Issued 8/24/76.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
C54D-DC, C54E-DC, C54G-DC; T.C. A-762	SA3603WE	Installation of fire retardant tanks. Amended 3/5/79.	WE	84391	Waig Aircraft, Inc. P.O. Box 26339 Tucson, AZ 85726
C54-E; T.C. 762	SA1008WE	Installation of poly-fiber covering material of ailerons, elevator and rudder. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
C54E-DC; T.C. A-762	SA3417WE	Increase in height of rear cargo door. Issued 6/9/77.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
C54G-DC; T.C. A-762	SA3648WE	New enlarged 12 ft. cargo door, new cargo floor, structural cargo crash barrier, modified F.S. 260 bulkhead, relocated main electrical junction box, partially new D.C. electrical distribution and control system, DC-6 wheels and brakes and miscellaneous changes for cargo operations. Issued 6/23/78.	PC	04200	Air Cargo Enterprises, Inc. P.O. Box 29791 Honolulu, HI 96820

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-4; T.C. 762	SA4-9	Interior arrangement for track mounted pay loader seat and new buffet.	WE	52069	Los Angeles Air Service McCarren Field Las Vegas, NV 89114
DC-4; T.C. 762	SA4-84	Fiber gasket 4233666 in cowl flap actuating cylinder replaced with AN 6227-20 "O" ring.	NW	08480	Alaska Airlines, Inc. Paine Field Everett, WA 98201
DC-4; T.C. 762	SA4-203	Oil filter 1258-B86-C and element 1258-OC on aircraft without UD3785 oil temperature regulator.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
DC-4; T.C. 762	SA4-204	Oil filter 1258-B-86-D and element 1258-OC on aircraft with UD3785 oil temperature regulator.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
DC-4; T.C. 762	SA67SO	Seat track.	SO	08146	Air International P.O. Box 603 Miami, FL 33159
DC-4; T.C. 762	SA3423WE	Installation of 2000 gallon capacity external retardant tank under the fuselage at wing center section. Issued 6/10/77.	WE	19585	California National Air Services, Inc. 420 North Buchanan Circle Pacheco, CA 94553
dDC-4, DC-6, DC-7; T.C. 762, 781, 4A10	SA7SO	Radome and radar antennae mount provisions for up to 22" diameter antennae, RAC AVQ-10 or Bendix RDR-1 (X/C Band).	SO	78390	Tempo Design Corporation P.O. Box 456 Miami, FL 33148
DC-4; DC-6, -6A, -6B; DC-7, -7B, -7C; DC-8; DC-9; T.C. A-762, A-781, 6A3, 6A4, 4A10, 4A25, A6WE	SA863EA	Incorporation of DME Corporation emergency slide lighting ESL-1, ESL-6 or ESL-6-1 system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-3; T.C. 618	SA1-554	Side-mounted pitot and static vent air speed system.	EA	37580	General Foods Corporation 250 North Street White Plains, NY 10602
DC-3; T.C. 618	SA3-24	Modification of rear cargo compartment.	GL	65350	Purdue Aeronautics Corp. Purdue University Airport Lafayette, IN 47901
DC-3; T.C. 618	SA3-99	Collins 537F-1 radar scanner mount installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618	SA3-195	Bird-resistant glass.	GL	61625	North Central Airlines, Inc. 6201 34 Avenue, South Minneapolis, MN 55450
DC-3; T.C. 618	SA3-199	High pressure oxygen cylinders, lines and regulators within fire and explosion resistant containers.	GL	61732	Northwestern Aeronautical Co. 6801-34th Avenue, South Wold Chamberlain Field Minneapolis, MN 55401
DC-3; T.C. 618	SA3-393	Installation of Sperry D-3 engine analyzer. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618	SA3-394	24-volt electrical system.	GL	65350	Purdue Aeronautics Corp. Purdue University Airport Lafayette, IN 47901
DC-3; T.C. 618	SA3-460	Radio rack installation - STA 145. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618	SA301CE	Flap actuated landing gear warning horn system.	GL	61625	North Central Airlines, Inc. 6201 34th Avenue, South Minneapolis, MN 55450
DC-3; T.C. 618	SA1168WE	DME-29A distance measuring equipment.	RM	37015	Frontier Airlines, Inc. 5900 East 39th Avenue Denver, CO 80207
DC-3; T.C. 618, 669	SA1-35	Internally mounter Aerojet General engines. Amended 10/24/66.	EA	04515	Air Carrier Service Corp. 2233 Wisconsin Avenue, N.W. Washington, D.C. 20007
DC-3; T.C. 618, 669	SA1-49	Cockpit jump seat.	EA	62180	Page Airways, Inc. Rochester Airport Rochester, NY 14603
DC-3; T.C. 618, 669	SA1-54	Replacement of auxiliary hydraulic hand pump with 24 volt electrically driven gear type hydraulic pump. Reissued 11/4/77.	EA	59466	Dorothy M. Miller 2219 Main Street Bethlehem, PA 18017

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3; T.C. 618, 669	SA1-63	1002-CF radome. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Product Operations P.O. Box 350 Akron, OH 44309
DC-3; T.C. 618, 669	SA1-70	1002 Series radomes. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Product Operations P.O. Box 350 Akron, OH 44309
DC-3; T.C. 618, 669	SA1-97	Single pump hydraulic system converted to dual system.	EA	05972	Aircraftsmen, Inc. Zahn Airport Lindenhurst, L.I., NY 11757
DC-3; T.C. 618, 669	SA1-170	Antenna support structure and component trays for RCA AVQ-50 and Bendix RDR-1D radar system.	EA	67000	Reading Aviation Service P.O. Box 1201 Municipal Airport Reading, PA 19603
DC-3; T.C. 618, 669	SA1-257	Windows on both sides of fuselage.	EA	71915	S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
DC-3; T.C. 618, 669	SA1-260	1014C-C radome assembly for 22" Collins antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
DC-3; T.C. 618, 669	SA1-295	2005X Series and 2105X Series radomes. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Product Operations P.O. Box 350 Akron, OH 44309
DC-3; T.C. 618, 669	SA1-318	New windows and relocation of exits.	EA	71915	S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
DC-3; T.C. 618, 669	SA1-380	Hinge mounting support for RCA AVQ-50 radar equipment.	EA	67000	Reading Aviation Service P.O. Box 1201 Municipal Airport Reading, PA 19603
DC-3; T.C. 618, 669	SA3-2	Wheel well doors, revised oil cooler and fairings, revised exhaust system, revised carburetor scoop, engine cowling alternation, aileron gap closures and wing root fairings.	EA	37168	General Aircraft Company, Inc. Suite 55, Liberty Street New York, NY 10001
DC-3; T.C. 618, 669	SA3-15	Installation of wheel well enclosure doors. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-17	Pitot system.	EA	37168	General Aircraft Company, Inc. Suite 55, Liberty Street New York, NY 10001
DC-3; T.C. 618, 669	SA3-25	Installation of short exhaust stack (simplified version). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-52	Radome installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-59	Installation of cabin heater, Stewart-Warner 940-B24. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-72	15-gallon single alcohol tank and distribution system for engine carburetors, propellers and windshield.	GL	04770	Aircraft Conversion, Inc. Detroit Wayne Major Airport Inkster, MI 48141
DC-3; T.C. 618, 669	SA3-78	Alternate Tee-Bolt radome attachment for STC SA3-52 radome installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-121	Dual tank alcohol anti-icing system, 814-D.	GL	04770	Aircraft Conversion, Inc. Detroit Wayne Major Airport Inkster, MI 48141
DC-3; T.C. 618, 669	SA3-141	Installation of dual Stewart-Warner Model 940-B24 cabin heaters. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-142	Installation of Stewart-Warner Model 940-B24 cabin heater. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3; T.C. 618, 669	SA3-173	Installation of vacuum pump and vacuum system. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-240	Standard installation - swivel chair assembly SK10187. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-271	Installation of RCA Model AVQ-50 radar. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-272	Standard seat track installation for SK10187 swivel seat. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-282	Generator over-heat temperature indicator system. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-294	Installation of airstep door, safety chair, and release mechanism. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-302	Janitrol Series S-200 heater.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
DC-3; T.C. 618, 669	SA3-306	Dual pump alcohol system 814-DP.	GL	04770	Aircraft Conversion, Inc. Detroit Wayne Major Airport Inkster, MI 48141
DC-3; T.C. 618, 669	SA3-307	Installation of 145-gallon fuel tanks. Installation of 252-gallon fuel tanks. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-337	Nacelle modification and installation of short exhaust stacks. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-392	Passenger seat installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-412	MH-6-1 three-axis automatic pilot.	GL	59650	Minneapolis-Honeywell Regulator Company 2747 Fourth Avenue, South Minneapolis, MN 55401
DC-3; T.C. 618, 669	SA3-422	Installation of bird resistant windshield. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-425	One-piece windshield, electrically heated or bird-proof.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
DC-3; T.C. 618, 669	SA3-426	Engine fire control zones. Fire detectors installation. Dual fire bottle installation. Oil cooler installation. Propeller feathering system. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-429	Typical installation of Burns Aero seat, P/N 7D1-SLR. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-438	Picture window installation and standard window modification. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-448	Installation of Cockpit side windows. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-455	Short exhaust stacks.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
DC-3; T.C. 618, 669	SA3-461	Installation of electrically driven emergency hydraulic pump. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3; T.C. 618, 669	SA3-482	Stewart-Warner 940-F-24 cabin heater.	GL	61612	Herbert A. Normandy 2939 Lake Owasso Boulevard, West St. Paul, MN 55101 AND
DC-3; T.C. 618, 669	SA3-482	Stewart-Warner 940-F-24 cabin heater.	GL	61612	Northwestern Aeronautical Holman Field St. Paul, MN 55101
DC-3; T.C. 618, 669	SA3-493	Sierracin left and right hand electrically heater windshields, 220-1.	GL	12578	Auto Craft Engineering Company 1904 N. Colorado Street Indianapolis, IN 46206
DC-3; T.C. 618, 669	SA3-498	Three-place divan assembly and typical installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-522	Installation of a windshield-carburetor-propeller-alcohol system. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA3-659	Honeywell-Atkins maximum safety lights system ALS9A-DC-3 with or without PC-3 converter.	GL	12488	Atkins Light Corporation 7636 Lyndale Avenue, South Minneapolis, MN 55401
DC-3; T.C. 618, 669	SA4-1	Picture windows 12" x 54.75" and escape hatch.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-3; T.C. 618, 669	SA4-4	Jump seat added aft of pilot's seat.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-3; T.C. 618, 669	SA4-43	17" windows.	WE	39315	Grand Central Aircraft Company 1134 Air Way Glendale, CA 91209
DC-3; T.C. 618, 669	SA4-94	Outer wing tanks, fuel dumping provisions and additional baggage compartments in wing center section.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
DC-3; T.C. 618, 669	SA4-158	Installation (external) of two Aerojet-General 15KS-1000-A1 aircraft rocket engines (JATO) for standby thrust purposes (below fuselage directly aft of wing between fuselage Stations 360 and 400). Reissued 3/10/71.	WE	30000	DeVore Aviation Service Corp. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-3; T.C. 618, 669	SA4-159	Two outer wing integral fuel tanks, each capacity 550 gallons.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
DC-3; T.C. 618, 669	SA4-215	Oil filter 1258-B-86-A and element 1258-OC.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
DC-3; T.C. 618, 669	SA4-297	Overhead window in pilot's compartment.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-3; T.C. 618, 669	SA4-354	Janitrol S-200 surface combustion cabin heater.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-3; T.C. 618, 669	SA4-375	Janitrol S-200 surface combustion cabin heater with ground blower.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-3; T.C. 618, 669	SA4-545	Structural modification of antenna supporting structure of McMillan radome.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-3; T.C. 618, 669	SA4-767	Raised and panorama windows.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3; T.C. 618, 669	SA4-781	Aerotherm 320 J pilot and copilot seats.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-3; T.C. 618, 669	SA4-782	Electrical transmitter flap position indicator.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-3; T.C. 618, 669	SA4-794	Gap closures.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3; T.C. 618, 669	SA4-798	Bonite covering on elevators, rudder and ailerons.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
DC-3; T.C. 618, 669	SA4-1091	Panorama windows.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3; T.C. 618, 669	SA4-1093	Interior furnishings for 12 passengers.	WE	02308	Aero Interiors Company 2940 N. Hollywood Way Burbank, CA 91502
DC-3; T.C. 618, 669	SA4-1099	Panorama picture window.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3; T.C. 618, 669	SA4-1452	Installation of two Aerojet-General 15KS-1000-A1 aircraft rocket engines and certification per SR-426. Reissued 3/10/71.	WE	30000	DeVore Aviation Service Corp. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-3; T.C. 618, 669	SA4-1566	Electrically-heated replacement windshield. Reissued 3/22/74.	SO	65025	PPG Industries, Inc. P.O. Box 2200 Huntsville, AL 35804
DC-3; T.C. 618, 669	SAIR-1	Fiberglass landing gear doors.	EU	78705	Transair Limited Croydon Airport Croydon, Surrey, England
DC-3; T.C. 618, 669	SA1CE	Weather radar installation, Collins Model WP-103. Reissued 10/1/71.	WE	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA18SW	Carburetor adapter. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
DC-3; T.C. 618, 669	SA68SW	Positive stop in rudder system and geared rudder tab installation.	SW	34000	Executive Aircraft Service P.O. Box 7307 Redbird Airport Dallas, TX 75232
DC-3; T.C. 618, 669	SA111SW	200,000 B.T.U. Janitrol S-200 heater in tail section. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
DC-3; T.C. 618, 669	SA121SW	Jump seat. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
DC-3; T.C. 618, 669	SA127SO	Brownline 20276 seat track.	SO	11900	Associated Aircraft Equipment Company, Inc. P.O. Box 542 Miami, FL 33101
DC-3; T.C. 618, 669	SA130SO	Extension on heater exchanger.	SO	08146	Air International P.O. Box 603 Miami, FL 33159
DC-3; T.C. 618, 669	SA177SO	Fabric attachment clips. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
DC-3; T.C. 618, 669	SA211CE	A.P.U. installation (Ranger Andover Model V-32D-2-1). Reissued 10/1/71.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA231SW	Two Aerojet-General rocket engines (JATO) (15KS-1000-A1).	SW	44038	Inter-Continental Engine Service P.O. Box 1243 Brownsville, TX 78520
DC-3; T.C. 618, 669	SA340SW	Removal of main cabin passenger door.	SW	28600	Dallas Skydrivers, Inc. 3928 Bryn Mawr Dallas, TX 75225
DC-3; T.C. 618, 669	SA347WE	Aircraft modified for 41 occupants.	WE	57918	Mercer Enterprises Lockheed Air Terminal Burbank, CA 91505
DC-3; T.C. 618, 669	SA474SW	Chairs and floor structure. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aviation Service 7515 Lemmon Avenue Dallas, TX 75209
DC-3; T.C. 618, 669	SA794WE	Substitution of Chobert rivets for rib lacing on elevator.	WE	53780	J.F. McKae's Aero Crafts Building 708, Oakland Airport Oakland, CA 94615

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3; T.C. 618, 669	SA929WE	Wing flap landing gear aural warning installation.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
DC-3; T.C. 618, 669	SA933WE	Flap actuated gear warning system.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l. Airport Los Angeles, CA 90009
DC-3; T.C. 618, 669	SA1274WE	28-volt DC generator with Leland Airborne Products CVS-1105-2 solid state voltage regulator.	WE	69241	RWS Electrical Accessory Service, Inc. 3210 N. San Fernando Boulevard Burbank, CA 91504
DC-3; T.C. 618, 669	SA1275WE	Replacement of carbon pile voltage regulator for a 28-volt DC generator with Leland Airborne Products Type CSV-1105-2 solid state voltage regulator.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
DC-3 Series; T.C. 618, 669, 6A2	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
DC-3, Super DC-3; T.C. 618, 6A2	SA4-1002	Alternate fuel source installation in aircraft with approved fuel flow-meter and Wright R-1820 or C9 Series engines.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3; T.C. 669	SA1-265	JOhns-Manville brake lining Part AB-6512 in Goodrich 14 x 2-3/4 expander tube brake.	EA	46748	Johns-Mansville Sales Corp. 22 East 40 Street New York, NY 10001
DC-3; T.C. 669	SA1-281	12-volt electrical system revised to accept P1 200-ampere generators.	EA	80500	United Air Lines, Inc. National Airport Washington, D.C. 20090
DC-3; T.C. 669	SA1-346	Sierrocote windshield 220-1 and 220-2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DC-3; T.C. 669	SA1-375	Windows.	EA	71905	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
DC-3 Series; T.C. 669	SA1-513	Enrichment of auto lean mixture setting by installing auto lean jet P/N 22244-3000cc in PD-12F13 injection carburetor on Pratt & Whitney R-1830-75 engines.	EA	08375	Airwork Corporation Municipal Airport Millville, NJ 08332
DC-3 Series; T.C. 669	SA3-12	Reclassify aft cargo compartment from Class E to Class A.	GL	61700	Northwest Airlines, Inc. International Airport St. Paul, MN 55111
DC-3 Series; T.C. 669	SA3-23	Hydraulic system fluid reservoir modification.	CE	62030	Ozark Airlines, Inc. P.O. Box 6007 Lambert Field St. Louis, MO 63145
DC-3 Series; T.C. 669	SA3-26	Buffet modification.	GL	49300	Lake Central Airlines Weir Cook Airport Indianapolis, IN 46241
DC-3 SEries; T.C. 669	SA3-45	Two Eclipse 30E-07-11 200-ampere generators and 1589-1D regulators.	GL	37808	General Motors Air Transport Section City Airport, Bay #1 Detroit, MI 48202
DC-3 Series; T.C. 669	SA3-50	Modification of Stewart-Warner Model 940-B24 heater installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-65	Bendix RDR-1 radar antenna ANT-1C installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-68	Alternate landing light installation (Westinghouse 600W seal beam). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-79	Cowl flap auxiliary actuator and cable assembly.	GL	61732	Northwestern Aeronautical Co. 6801-34th Avenue, South Wold Chamberlain Field Minneapolis, MN 55401
DC-3 Series; T.C. 669	SA3-84	Two Micro Switch 51SA1 lights.	GL	49300	Lake Central Airlines, Inc. Weir Cook Municipal Airport Indianapolis, IN 46241

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3 Series; T.C. 669	SA3-85	Sweeney inertia light and bracket assembly SWE 10001.	GL	90134	Zantop Air Transport, Inc. Detroit-Wayne Major Airport Inkster, MI 48141
DC-3 Series; T.C. 669	SA3-104	Installation of Curtis-Wright C-46 pilot and copilot seats, P/N 20-561-3005. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-113	Installation of RCA Model AVQ-10 radar antenna swingaway mount SK10136 (SA3-65). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-139	Installation of standard C-47 cargo door. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-260	Bird resistant single pane two-piece windshield.	CE	62030	Ozark Air Lines, Inc. P.O. Box 60007 Lambert Field St. Louis, MO 63145
DC-3 Series; T.C. 669	SA3-344	Control system (propeller governor) modification.	GL	49300	Lake Central Airlines Weir Cook Airport Indianapolis, IN 46241
DC-3 Series; T.C. 669	SA3-353	Oil separator assembly on aircraft with Pratt & Whitney R-1830-75, R-1830-92 or R-1830-94 engines.	GL	02500	Aeroquip Corporation 300 South East Avenue Jackson, MI 49203
DC-3 Series; T.C. 669	SA3-436	AiResearch cowling vent doors.	GL	22790	John J. Clark 305 N. Owen Street Mt. Prospect, IL 60056
DC-3 Series; T.C. 669	SA3-445	Installation of AiResearch oil cooler, P/N 86140. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-462	Installation of Janitrol heater (200,000 BTU) - forward compartment. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-469	200-ampere generator system in aircraft with Pratt & Whitney R-1830-75 and R-1830-94 engines.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
DC-3 Series; T.C. 669	SA3-490	L2C autopilot with automatic altitude control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
DC-3 Series; T.C. 669	SA4-5	1258-B-86A and -86B oil filters.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3 Series; T.C. 669	SA4-10	Janitrol S-200 heater.	WE	70632	Sears Roebuck & Company 2650 East Olympic Boulevard Los Anglees, CA 90052
DC-3 Series; T.C. 669	SA4-13	Folding double seat.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-3 Series; T.C. 669	SA4-75	Modified Convair B24 exhaust manifold (Pratt & Whitney R-1830).	WE	86250	Wilpac Manufacturing Company 135 North Johnson Avenue El Cajon, CA 92020
DC-3 Series; T.C. 669	SA4-76	New engine ring cowls on aircraft with Pratt & Whitney R-1830 engines.	NW	59600	Milner's Aircraft and Engine Service, Inc. 8165 First Avenue, South Seattle, WA 98101
DC-3 Series; T.C. 669	SA4-80	Cowl flap linkage system.	NW	59600	Milner's Aircraft and Engine Service, Inc. 8165 First Avenue, South Seattle, WA 98101
DC-3 Series; T.C. 669	SA4-104	Incorporation of C-47 type cargo door and floors.	WE	39315	Grand Central Aircraft Company 1134 Air Way Glendale, CA 91209
DC-3 Series; T.C. 669	SA4-105	Radio rack and radio compartment chair.	WE	39315	Grand Central Aircraft Company 1134 Air Way Glendale, CA 91209
DC-3 Series; T.C. 669	SA4-134	AN 3150 battery rack between fuselage Stations 117 and 136 below floor left side of companion way.	NW	79311	Transocean Airlines P.O. Box 29 Boeing Field Seattle, WA 98101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3 Series; T.C. 669	SA4-168	Full flow oil filter 30618A and element CP-1558-OC.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
DC-3 Series; T.C. 669	SA4-278	Propeller spinners.	NW	59600	Milner's Aircraft and Engine Service, Inc. 8165 First Avenue, South Seattle, WA 98101
DC-3 Series; T.C. 669	SA4-327	Hydraulic main cabin door lift adapted for use on both Temco and Metropolitan air stair doors.	NW	85122	West Coast Airlines, Inc. Georgetown Station Seattle, WA 98108
DC-3 Series; T.C. 669	SA4-389	Cabin emergency lighting.	NW	85122	West Coast Airlines, Inc. Georgetown Station Seattle, WA 98108
DC-3 Series; T.C. 669	SA4-704	Carburetor air scoop and fairing assembly for aircraft with Pratt & Whitney R-1830-94 engines.	SW	62299	Pan American World Airways, Inc. R.G.V. International Airport Brownsville, TX 78520
DC-3 Series; T.C. 669	SA4-731	Modified cowl flap actuating system on aircraft with Pratt & Whitney R-1830 series engines.	AL	20200	Phil D. Caulfield P.O. Box 4522 Spenard, AK 99503
DC-3 Series; T.C. 669	SA4-817	Propeller spinners on aircraft with Pratt & Whitney R-1830-92 engines.	NW	59600	Milner's Aircraft and Engine Service, Inc. 8165 First Avenue, South Seattle, WA 98101
DC-3 Series; T.C. 669	SA4-832	Ceconite 101 covering of rudder, elevators and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC-3 Series; T.C. 669	SA3SW	Propeller governor bracket on aircraft with Pratt & Whitney R-1830-94 engines.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
DC-3 Series; T.C. 669	SA78CE	Cabin heater installation, Stewart-Warner Model 940-B24. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA92SO	B-600 or B-600-1 oil separator.	SO	04400	Air Carrier Engine Services Box 48-236 International Airport Miami, FL 33148
DC-3 Series; T.C. 669	SA104NW	Replacement of rib stitching with AD 42 ABS-LF aluminum pop rivet. Issued 4/15/74.	NW	01860	Aero-Dyne Corporation 300 Airport Way Renton, WA 98055
DC-3 Series; T.C. 669	SA112SW	Short stack exhaust and nacelle enclosure.	SW	42550	Horton & Horton Custom Works, Inc. Meacham Field Fort Worth, TX 76106
DC-3 Series; T.C. 669	SA206EA	Interior modification for Type IV exit, radio rack, 4 couches and 8 seats.	EA	74930	Starflite, Inc. Hangar D Westchester County Airport White Plains, NY 10602
DC-3 Series; T.C. 669	SA219EA	Installation of Katz Integrated Flight Indicator Model KIFI-2 or KIFI-2A. Amended 5/21/69.	NE	36300	Forest City Aviation Service, Inc. 749 Congress Street Portland, ME 04102
DC-3 Series; T.C. 669	SA243SO	Mosquito adulticiding equipment.	SO	50256	Lee County Mosquito Control District P.O. Box 1711 Fort Meyers, FL 33902
DC-3 Series; T.C. 669	SA247SW	Bendix Aviation fuel flow transmitter 9100-5, indicator 6300 on aircraft with Pratt & Whitney R-1830 engines.	SW	34000	Executive Aircraft Service, Inc. P.O. Box 7307 Redbird Airport Dallas, TX 75232
DC-3 Series; T.C. 669	SA262EA	Hydraulic hand pump removed and Bendix electric hydraulic pump 389-3A installed.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
DC-3 Series; T.C. 669	SA312SO	32-passenger cabin interior.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
DC-3 Series; T.C. 669	SA315NW	Emergency exit window hold open device. Issued 6/10/76.	NW	01860	Aero-Dyne Corporation 300 Airport Way Renton, WA 98055
DC-3 Series; T.C. 669	SA317SO	Deactivate rear center wing fuel tank.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3 Series; T.C. 669	SA323SO	Solid state voltage regulator.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
DC-3 Series; T.C. 669	SA324SO	Wing flap actuated switch.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
DC-3 Series; T.C. 669	SA334EA	Janitrol heater and APU.	NE	08160	AIRKAMAN, Inc. Bradley International Airport Windsor Locks, CT 06096
DC-3 Series; T.C. 669	SA358EA	Increased capacity of divans and seat.	GL	73884	Southern Ohio Aviation Company 10600 Springboro Pike Miamisburg, OH 45342
DC-3 Series; T.C. 669	SA431EA	Stewart-Warner southwind heater.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
DC-3 Series; T.C. 669	SA604SW	Fuel flow system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
DC-3 Series; T.C. 669	ST746SO	Installation of short engine stacks. Issued 1/8/75.	SO	69242	R.W.D., Inc. P.O. Box 165 Miami, FL 33148
DC-3 Series; T.C. 669	SA881WE	Two air mixing baffles in carburetor air scoop.	WE	70632	Sears Roebuck & Company 2650 East Olympic Boulevard Los Angeles, CA 90054
DC-3 Series; T.C. 669	SA961WE	Seats and bulkhead for interior arrangement of 33 occupants.	WE	44225	International Aviation Development Corporation 542 San Ramon Valley Boulevard Danville, CA 94526
DC-3 Series; T.C. 669	SA1158WE	AVQ-75 distance measuring equipment.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
DC-3 Series; T.C. A-669	SA1485CE	Installation of fire extinguisher system for engines and/or cabin heater and/or aft fuselage baggage compartment. Issued 5/10/79.	CE	78621	Total Flood Corporation P.O. Box 12183 Overland Park, KS 66212
DC-3 Series; T.C. 669	SA1593WE	Installation of cargo containers.	NE	18200	Buker Airways, Inc. Hartness Municipal Airport Springfield, VT 05150
DC3/C-47; T.C. A-669	ST140RM	Installation of internal spray tank and wing booms. Issued 5/3/78.	RM	22220	Christler Flying Service, Inc. P.O. Box 231 Thermopolis, WY 82443
DC-3, DC-4/47; T.C. A-618, A-669	SA70GL	Installation of Norton radome kit 4067X. Amended 5/21/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
DC-3, -3A; T.C. 618, 669	SA106CE	Hoskins Model F or B wing tip and Model C or X tail lights with or without two Model 1 or 2 fuselage lights. Amended 6/20/68.	GL	42625	Hoskins, Inc. 34 North Bennett Street GEneva, IL 60134
DC-3, -3A, -3C, -3D; T.C. A-618, A-669	SA4-220	Tail wheel cover and fairing. Reissued 9/12/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3, -3A, -3C, -3D; T.C. A-618, A-669	SA4-230	Aileron gap closures. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3A, -3C, -3D; T.C. A-669	SA4-138	Engine cowling, baffles, siamese type exhaust system and modification cowl flaps for aircraft with Pratt & Whitney R-1830-92 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-151	Siamese type exhaust system. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3A, -3C, -3D; T.C. A-669	SA4-228	Main landing gear doors, actuating system, main landing gear assist bungee, oil cooler fairing and oil cooler fixed section for aircraft with Pratt & Whitney R-1830-75, -92 or -94 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-272	Engine cowling and baffles for aircraft with Pratt & Whitney R-1830-75 or -94 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-279	Engine cowling and baffles for aircraft with Pratt & Whitney R-1830-92 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-309	Engine cowling and baffles for aircraft with Pratt & Whitney R-1830-92 engines incorporating R-1830-75 or -94 cylinders. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-780	Engine baffles on aircraft with Pratt & Whitney R-1830-92 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-816	Engine baffles on aircraft with Pratt & Whitney R-1830-75 or R-1830-94 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -C-S3C4G; T.C. A-669	SA133AL	Installation of flap actuated landing gear aural warning device.	AL	67017	Reeve Aleutian Airways, Inc. P.O. Box 6027 Anchorage, AK 99502
DC-3A, -3C, -3D; T.C. A-669	SA494WE	Exhaust heat exchanger for cabin heating system. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, DC-3C; T.C. A-669	ST540SO	Installation includes: four interior overhead emergency lights powered by power supply located in forward fuselage; exterior overwing emergency light in wing fillet, one on each side, powered by power supply in aft fuselage; emergency light control switches installed in both flight and passenger compartments. Issued 6/15/73.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
DC-3A, -3C, -3D; DC-4, C54-DC, C54A, B, D, E, G; DC-6, -6A, -6B; DC-7B; T.C. 669, 762, 6A4, 6A10	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
DC-3A, -3C, -3D; DC-4; DC-6A; T.C. 669, A762, 6A3	SA1744WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
DC-3C; T.C. 669	SA1-324	Installation of autosyn fuel flowmeter transmitter (Eclipse Type 9054-5A). Reissued 11/14/77.	EA	59466	Dorothy A. Miller 2219 Main Street Bethlehem, PA 18017
Super DC-3; T.C. 6A2	SA1-14	Relocation of airspeed pitot head.	EA	67600	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
DC-3C; T.C. 669	SA1066EA	Modification of cabin to all cargo configuration. Amended 9/11/78.	EA	09735	Alpha Airlines, Inc. JFK International Airport Hangar 14 Jamaica, NY 11430
Super DC-3; T.C. 6A2	SA3241WE	Installation of turbopropeller Rolls-Royce Dart 510 engines, Dowty Rotol (c)R-130/4-20-4/12E propellers, and associated system and equipment modifications. Issued 8/18/76.	NE	64580	Pilgrim Aviation & Airlines, Inc. Box 1743 New London, CT 06320
DC-6; T.C. A-781	SA2761WE	Interior arrangement. Issued 9/24/73.	WE	57900	Mercer Airlines 2777 Hollywood Way Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-6 Series; T.C. 781, 6A3, 6A4	SA1-580	Television broadcasting equipment. Amended 2/8/66.	GL	59380	Midwest Program on Airborne Television Instruction, Inc. Memorial Center Purdue University Lafayette, IN 47901
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-41	Structure, power plant, systems and equipment modification.	GL	61700	Northwest Airlines, Inc. 1885 University Avenue St. Paul, MN 55111
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-202	Oil filter 30816A with CP-1430-6 element.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-218	Windows in fuselage.	SO	62300	Pan American World Airways, Inc. P.O. Box 817 Miami, FL 33159
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-502	Engine mount core assemblies.	WE	30500	Dow-Elco, Inc. 1313 West Olympic Boulevard Montebello, CA 90640
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-508	Bulkhead and cabin attendant seat.	WE	35723	Flight-Line Engineering 500 Densmore Encino, CA 91316
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-523	Interior modification for 85 passengers (93 total occupants).	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-525	Engine mount core 106-1F and 106-1J.	WE	83500	Vibration Isolation Products, Inc. 212 West Magnolia Burbank, CA 91505
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-543	112-passenger seating arrangement.	WE	39460	Great Lakes Airlines, Inc. Lockheed Air Terminal Burbank, CA 91500
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-568	Engine mount core assemblies DE1468.	WE	30500	Dow-Elco, Inc. 1313 West Olympic Boulevard Montebello, CA 90640
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-577	Aileron trim control gearing modification.	GL	80500	United Air Lines, Inc. 5959 S. Cicero Avenue Chicago, IL 60650
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-1169	Interior modifications.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-1311	Ceconite 101 covering of rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC-6 Series; T.C. 781, 6A3, 6A4	SA1PC	DC-7 increased power cabin superchargers.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
DC-6 Series; T.C. 781, 6A3, 6A4	SA12SO	Altimeter vibrators.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-6 Series; T.C. 781, 6A3, 6A4	SA21SO	Modified zero reader system.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-6 Series; T.C. 781, 6A3, 6A4	SA100NW	Installation of cargo door, 6g barrier bulkhead, and a class E cargo compartment. Issued 4/5/74.	NW	69204	Rosenbalm Aviation P.O. Box 1524 Medford, OR 97501
DC-6 Series; T.C. 781, 6A3, 6A4	SA140EA	AMF "Unifreight MARK VI" cargo handling system.	EA	10226	American Machine & Foundry Co. Whiteford & Eden Roads York, PA 17405
DC-6 Series; T.C. 781, 6A3, 6A4	SA197SO	Cockpit voice recorder.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-6 Series; T.C. 781, 6A3, 6A4	SA229SO	B-400 oil separator.	SO	00400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
DC-6 Series; T.C. 781, 6A3, 6A4	SA363SO	Cockpit voice recorder.	SO	29230	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-6 Series; T.C. 781, 6A3, 6A4	SA424WE	Single Federal (ITT) Type AFN3544 distance measuring equipment system.	SW	10150	American Airlines, Inc. Service Engineering Division Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-6 Series; T.C. 781, 6A3, 6A4	SA426WE	Single Federal (ITT) Type AFN3544 distance measuring equipment.	SW	10150	American Airlines, Inc. Service Engineering Division Tulsa, OK 74151
DC-6 Series; T.C. 781, 6A3, 6A4	ST528SO	Installation of cargo restraining bulkhead. Issued 2/20/74.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6 Series; T.C. 781, 6A3, 6A4	SA815WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-6 Series; T.C. 781, 6A3, 6A4	SA911WE	Interior arrangement for 87 occupants and installation of seat tracks and bulkhead.	WE	61238	National Interests, Inc. Municipal Airport Reno, NV 89501
DC-6 Series; CT.C. 781, 6A3, 6A4	SA932WE	ADI system components on Pratt & Whitney AM 83-3 and -4 engines.	WE	61237	National Interest, Inc. of Carson City, Nevada c/o Lamm Associates, Inc. International Airport Oakland, CA 94614
DC-6 Series; T.C. 781, 6A3, 6A4	SA1045WE	Door-mounted inflatable evacuation slides.	GL	80500	United Air Lines, Inc. P.O. Box 8000 O'Hare International Airport Chicago, IL 60666
DC-6 SEries; T.C. 781, 6A3, 6A4	SA1082WE	Interior arrangements.	WE	07500	AiResearch Aviation Service 6201 West Imperial Highway Los Angeles, CA 90045
DC-6 Series; T.C. 781, 6A3, 6A4	SA1148WE	Interior modifications.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-6 Series; T.C. 781, 6A3, 6A4	SA1302WE	Fairchild A100 voice recorder.	WE	85126	Western Air Lines, Inc. 6060 Avion Drive Los Angeles, CA 90052
DC-6 Series; T.C. 781, 6A3, 6A4	SA1311WE	United Data Control V557 voice recorder.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-6 Series; T.C. 781, 6A3, 6A4	SA1517WE	Interior arrangement for 97 occupants, DME installation, interior emergency lighting installation.	WE	57918	Mercer Enterprises Hollywood-Burbank Airport 2777 Hollywood Way Burbank, CA 91505
DC-6; T.C. 781	ST807SO	Installation of cargo interior and extension of lower aft cargo compartment. Reissued 1/3/75.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 480756 Miami, FL 33148
DC-6; T.C. 781	SA2994WE	Deactivation of high blower on CB-16 engines. Issued 1/4/75.	WE	57918	Mercer Enterprises Hollywood-Burbank Airport 2777 Hollywood Way Burbank, CA 91505
DC-6; T.C. 6A3, 6A4	SA1313WE	Fairchild A100 voice recorder.	WE	87430	World Air Center Oakland International Airport Oakland, CA 94614
DC-6, DC-6A (USAF C-118A), DC-6B, DC-7, -7B, -7C; T.C. 6A4, 4A10, 6A3, 785	ST484SO	Installation of cargo restraining bulkhead. Amended 2/12/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-6, DC-6A (C-118A), DC-6B; T.C. A-781, 6A3, 6A4	SA1066SO	Alternate installation of hydraulic pump utilizing existing engine drive. Issued 4/23/79.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 Northwest 57th Avenue Miami, FL 33152
DC-6, -6A (C-118A), -6B; T.C. A-791, 6A3, 6A4	SA1083SO	Installation of four Pratt & Whitney R-2800-99W engines and Hamilton Standard propellers. Issued 7/3/79.	SC	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 28426 Atlanta, GA 30328
DC-6, -6B; T.C. 781, 6A4	ST456SO	Installation of cargo restraining bulkhead. A clean and unobstructed passageway between the crew compartment and cargo compartment on the side of the bulkhead is required. Issued 4/9/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST463SO	Installation of cargo door. Issued 5/4/71.	SO	58700	Miami Aviation Corporation Hangar 102, Opa Locka Airport Opa Locka, FL 33054

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-6, -6B; T.C. 781, 6A4	ST4708SO	Installation of aft cargo door. Issued 6/22/71.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST4959SO	Installation of aft cargo door. Issued 2/28/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST5358SO	Installation of cargo floor. Amended 6/4/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST5368SO	Installation of aft cargo door. Amended 6/16/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6; -6B; T.C. 781, 6A4	ST5558SO	Installation of rear cargo door. Issued 9/28/73.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33152
DC-6, -6B; T.C. 781, 6A4	ST5958SO	Installation of exhaust system bracket. Reissued 1/6/75.	SO	02394	Aeronautical Engineering, Inc. 342 N.W. 2nd Court Dania, FL 33004
DC-6, -6B; T.C. 781, 6A4	ST5978SO	Installation of aft cargo door. Amended and reissued 6/16/75.	SO	02394	Aeronautique Engineering, Inc. 342 N.E. 2nd Court Dania, FL 33004
DC-6, -6B; T.C. 781, 6A4	ST8438SO	Installation of aft cargo door. Amended 6/3/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6 Series, DC-7 Series; T.C. 781, 6A3, 6A4, 4A10	SA4-328	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-329	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-330	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA76EA	Radome assembly 3016.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
DC-6A, DC-7B, -7BF, -7C, -7CF; T.C. 6A3, 4A10	SA470CE	Installation of Fairchild cockpit voice recorder Model A-100. Amended 3/1/67.	GL	81064	Universal Airlines, Inc. Detroit-Metropolitan Airport Inkster, MI 48141
DC-6A; T.C. 6A3	ST6716SO	Installation of cargo loading/ restraint system for palletized cargo. Amended 6/24/69.	SO	46000	Jet Avion Corporation 950 S.E. 8th Street Hialeah, FL 33010
DC-6A, DC-6B; T.C. 6A3	ST34GL	Remove cabin pressurization system, modify cabin air heating and ventilating system. Issued 9/24/73.	GL	90135	Zantop International Airlines, Inc. Willow Run Airport Ypsilanti, MI 48197
DC-6A (C-118A), DC-6B; T.C. 6A3, 6A4	ST9648SO	Installation of cargo interior, installation of cargo restraint and modification of pressurization system. Amended 10/17/78.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 480756 Miami, FL 33148
DC-6A, DC-6B, USAF C-118A (DC-6A); T.C. 6A4, 6A3	ST9743SO	Installation of extra crew seating and air distribution system. Issued 3/29/78.	SO	15410	Bellomy - Lawson Aviation, Inc. P.O. Box 522760 Miami, FL 33152
DC-6A, USAF C-118A, Navy R6D-1, DC-63, R6D-1Z; T.C. 6A3	ST9816SO	Deactivation of the cabin pressurization system, conversion of the cargo compartment to a class "E" compartment, and modification of the ventilation. Amended 10/10/79.	SO	41864	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
DC-6A, DC-6B; T.C. 6A3	SA1363WE	Installation of Fairchild Industrial Products Model A100 cockpit voice recorder system. Amended 4/30/68.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 2426 Oakland International Airport Oakland, CA 94614
C-118A; T.C. 6A3	SA770SO	Installation of cargo pallet and container loading and restraint system. Issued 4/12/79.	SO	02390	Aeronautica Engineers, Inc. P.O. Box 661027 Miami, FL 33166

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
R6D-1; T.C. 6A3	SA3406WE	Modification of oxygen system including addition of supply bottle, pressure relief valve, and microphone in smoke masks. Issued 5/19/77.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-6B; T.C. 6A4	ST454SO	Installation of aft cargo door. Issued 3/1/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST514SO	Installation of forward cargo door. Amended 2/12/75.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6B; T.C. 6A4	ST523SO	Installation of forward cargo door. Amended 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST529SO	Installation of cargo floor. Reissued 3/12/73.	SO	08368	Airtech Service, Inc. P.O. Box 516 Miami, FL 33148
DC-6B; T.C. 6A4	ST532SO	Installation of main cabin compartment. Issued 3/27/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST553SO	Installation of cargo floor. Issued 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST729SO	Removal of pressurization and cabin cooling systems. Issued 7/10/72.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6B; T.C. 6A4	SA1434WE	Installation of modified DC-7 type cargo loading system.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 426 Oakland International Airport Oakland, CA 94914
DC-6B; T.C. 6A4	SA1457WE	Installation on auxiliary power unit in fuselage.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport AVenue Santa Monica, CA 90405
DC-6B; T.C. 6A4	SA1510CE	Engine driven cabin air compressors and associated cabin pressurization controls removed. Issued 8/23/79.	CE	64292	Petroleum Air Transport, Inc. P.O. Box 187 Hazelwood, MO 63042
DC-6B; T.C. 6A4	SA1604SW	Aft cargo door between F.S. 661 and F.S. 801. Issued 2/13/73.	SW	08351	Air Services, Inc. P.O. Box 2 Addison, TX 75001
DC-6B Cargo; T.C. 6A4	SA1663WE	MOdification of DC-6B cargo aircraft to incorporate passenger or combination passenger/cargo arrangements.	WE	25970	Continental Airlines Los Angeles International Airport Los Angeles, CA 90009
DC-6B Cargo; T.C. 6A4	SA1765WE	Installation of cargo bulkhead, crew lavatory, vanity, galley and bunk.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-6B; T.C. 6A4	SA2721WE	Install external retardant tank. Amended 10/5/77.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
DC-6B; T.C. 6A4	SA2861WE	Installation of rear cargo door system GA61104. Issued 4/4/74.	SW	37093	Gary Aircraft Corporation P.O. Box 3486 San Antonio, TX 78211
DC-7 Series; T.C. 4A10	SA1-25	Substitution of rotating discs 9531691 and 9531704 in 9560285 and 9560286 brake assemblies.	GL	39011	Goodyear Aircraft Corporation Akron, OH 44309
DC-7 Series; T.C. 4A10	SA3-311	Wheels 150741-1 and/or 150741-5 and brake assembly 150835-5.	GL	15500	Bendix Aviation Corporation 401 North Bendix Drive South Bend, IN 46600
DC-7 Series; T.C. 4A10	SA4-54	Passenger/cargo interior arrangement configurations.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-91	One 4-piece divan left-hand side inboard facing and one 2-place divan right-hand side aft facing from Station 891 aft to pressure dome.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-124	Station 122 bulkhead.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-7 Series; T.C. 4A10	SA4-255	Aft cabin lounge.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-355	Interior modification coach to mixed class.	WE	07500	AiResearch AVviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-405	Interior modification to mixed class.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-442	Modification of communication equipment to provide navigator station.	SW	10150	American Airlines, Inc. Municipal Airport Tulsa, OK 74101
DC-7 Series; T.C. 4A10	SA4-507	Deterjet DJ1025 valve in place of Wright torquemeter booster pump upper housing per STC SEW-10.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-608	Engine mount core assemblies DE-643-1 on Wright TC18 series engines.	WE	30500	Dow-Elco, Inc. 1313 West Olympic Boulevard Montebello, CA 90640
DC-7 Series; T.C. 4A10	SA10SO	Provisioned for installation of 10,000 pound military pallet.	SC	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-7 Series; T.C. 4A10	A23SO	Observer's seat fuselage Station 55.	SO	68130	Riddle Airlines P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA30SO	Two emergency exits at stations 437.9 - 460.5 from Type IV to Type III modified.	SO	68130	Riddle Airlines, Inc. P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA35SO	Access hole in horizontal stabilizer.	SO	68130	Riddle Airlines, Inc. P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA89SO	Oil separator B-300-1.	SC	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
DC-7 Series; T.C. 4A10	SA103WE	Interior arrangement for 104 passengers.	EA	19640	Camaero, Inc. Room 2004 27 Wall Street New York, NY 10005
DC-7 Series; T.C. 4A10	SA176NW	Installation of Fairchild Andover Model 204 auxiliary power unit for ground use only.	NW	18700	Butler Aircraft Company P.O. Box 338 Redmond, OR 97756
DC-7 Series; T.C. 4A10	SA188EA	Cabin interior modifications.	EA	80923	United States Overseas Airlines P.O. Box 234 Wildwood, NJ 06260
DC-7 Series; T.C. 4A10	SA214WE	Passenger interior arrangements and cargo interior.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. California Avenue Burbank, CA 91505
DC-7 Series; T.C. 4A10	SA294WE	Door in floor for cabin access.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA314WE	Passenger interior arrangements and cargo interior for operation of aircraft at 106,400 pounds zero fuel weight.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 North Clybourn Avenue Burbank, CA 91505
DC-7 Series; T.C. 4A10	SA364SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l. Airport Atlanta, GA 30320
DC-7 Series; T.C. 4A10	SA365EA	All weather landing system.	EA	74574	Sperry Gyroscope Company 2221 Smithtown Avenue Ronkonkoma, NY 11779
DC-7 Series; T.C. 4A10	SA425WE	Single Federal (ITT) Type AFN3544 distance measuring equipment system.	SW	10150	American Airlines, Inc. Service Engineering Division Tulsa, OK 74151
DC-7 Series; T.C. 4A10	SA493SW	104-passenger interior arrangement.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-7 Series; T.C. 4A10	SA500EA	Installation of microvision operational all-weather landing system.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
DC-7 Series; T.C. 4A10	SA588WE	Ceconite 101 covering of rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC-7 Series; T.C. 4A10	SA600SO	Cockpit voice recording system.	SO	08170	Airlift International, Inc. P.O. Box 335 Miami, FL 33148
DC-7 Series; T.C. 4A10	SA602WE	99-passenger interior arrangement modification including floor structure.	WE	05370	Aircraft Investors Hangar 28, Oakland Airport Oakland, CA 94614
DC-7 Series; T.C. 4A10	SA656WE	Interior modification for 98 occupants.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA724WE	Interior arrangement modification for 89 and 99 passengers and installation of modified navigator's seat.	WE	44188	International Aerodyne, Inc. 11319 Vanowen Street North Hollywood, CA 91603
DC-7 Series; T.C. 4A10	SA796WE	Wing flap attachments modification.	WE	30400	Douglas Aircraft Company, Inc. 3855 Lakewood Boulevard Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1068WE	Interior arrangement.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1075WE	AVQ9 radar altimeter, APN9 Loran receiver, AT144 HF transmitter and AR144 HF receiver.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1361WE	Fairchild Industrial Products Model A100, cockpit voice recorder system.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 2426 Oakland International Airport Oakland, CA 94614
DC-7, -7B, -7C; T.C. 4A10	SA2709WE	Installation of 3,000 gallon external retardant tanks under fuselage at wing center section. Amended 6/17/75.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-7, -7B, -7C; T.C. 4A10	SA3015WE	Installation of LH and RH upper viewing windows above side cockpit windows. Amended 6/17/75.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-7B; T.C. 4A10	ST631SO	Installation of loading and restraint system for palletized cargo. Amended 9/12/68.	SO	46000	Jet Avion Corporation 950 SE 8th Street Hialeah, FL 33010
DC-7B; T.C. 4A10	ST651SO	Installation of cargo transportation pallet and new assemblies (Heath Techna P/N AC-10195) pallet w/AC 10197 net, or AC-10194 pallet w/AC-10196 net.	NW	41625	Heath Techna Corporation 19819 84th Avenue Kent, WA 98031
DC-7CF; T.C. 4A10	SA469CE	Fairchild A-100 cockpit voice recorder.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul International Airport St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA1-599	Gables Engineering G-1010A instrument failure warning system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA1-601	Crimsco cargo container 6003 utilizing 6004 adapter in passenger compartment. Amended 5/3/67.	EA	62300	Pan American World Airways, Inc. 135 East 42nd Street New York, NY 10001
DC-8 Series; T.C. 4A25	SA3-603	Equipment furnishings, cargo provisions, forward cargo cabin DC-8.	GL	61700	Northwest Airlines, Inc. 1885 University Avenue St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA3-666	Aft cabin bin substituted for three 3-place left-hand tourist passenger seats between Stations 1253 to 1360.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul International Airport St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA4-918	Waste King flight data recorder 5424.	GL	80500	United Air Lines, Inc. 5959 South Cicero Avenue Chicago, IL 60650

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8 Series; T.C. 4A25	SA4-1026	Forward lounge.	WE	18390	Burns Aero Seat Company, Inc. 3900 Cohasset Street Burbank, CA 91502
DC-8 Series; T.C. 4A25	SA45SO	M6861-100 life rafts. Amended 5/8/67.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA52SO	6924-100 life rafts.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA55SO	B-500-2 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
DC-8 Series; T.C. 4A25	SA69EA	Brown line 21105-51 stretcher kit in passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 East 42nd Street New York, NY 10001
DC-8 Series; T.C. 4A25	SA70SO	Deactivation of center wing and forward auxiliary fuel tanks.	SO	61220	National Airlines, Inc. International Airport Miami, FL 33159
DC-8 Series; T.C. 4A25	SA77EA	SP-30 autopilot modification to allow manual pitch operation while maintaining automatic roll and yaw control.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA94SO	WM233-102 and WM333-101 passenger seats.	SO	02800	Aerosmith Products Corporation 6940 SW 12th Street Miami, FL 33144
DC-8 Series; T.C. 4A25	SA155SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA176SO	Auxiliary galley.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA194SO	Passenger seating and cabin interior.	SO	61220	National Airlines P.O. Box 2055 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA222EA	Bendix DRA-12/CPA-24 doppler computer system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA286SO	Gables G-1340B instrument warning system.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA293EA	Tray carrier.	EA	62300	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA305EA	Inflight motion picture system provisions. Amended 10/5/67.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA306SO	Forward lounge compartment configuration change.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA312EA	Aerotherm 1003 stretcher.	EA	62300	Pan American World Airways, Inc. Pan Am Building New York, NY 10017
DC-8 Series; T.C. 4A25	SA324EA	Litton LN-12 inertial navigation system and Bendix navigational computer.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, L.I., NY 11430
DC-8 Series; T.C. 4A25	SA333EA	Litton low range altimeter system and activation of altitude bar.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, L.I., NY 11430
DC-8 Series; T.C. 4A25	SA343SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l. Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA350SO	Galleys 1 and 4.	SO	19846	Capitol Airways, Inc. Berry Field Nashville, TN 37202
DC-8 Series; T.C. 4A25	SA359SO	Seat belt attachment.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8 Series; T.C. 4A25	SA370SO	Single radio altimeter.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA373SO	Installation of remote accelerometer and mount assy for DC-8 flight recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA377EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways, Inc. JFK International Airlines Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA380SO	Installation of stretcher assembly.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA445EA	Installation of cockpit voice recorder. Amended 2/27/67.	EA	62300	Seaboard World Airlines Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA479WE	Cargo bins and adapters in passenger cabin.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA497EA	Installation of Inflight Motion Picture Provisions.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA543EA	Cockpit voice recorder.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA544WE	Interior arrangements.	WE	79200	Trans International Airlines Box 2306, Airport Station Oakland, CA 94614
DC-8 Series; T.C. 4A25	SA545WE	Interior arrangements.	WE	79200	Trans International Airlines Box 2306, Airport Station Oakland, CA 94614
DC-8 Series; T.C. 4A25	SA582WE	Aileron power system modification to incorporate a flexible hose.	SO	62300	Pan American World Airways, Inc. Pan Am Building Miami, FL 33159
DC-8 Series; T.C. 4A25	SA602SO	Dual Collins AL-101 radio altimeter system.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA613SO	Installation of Collins FD-109 FD-109 flight director system. Amended 12/28/67.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA833WE	Two triple seats in main cabin and associated changes.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA855WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA994WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-8 Series; T.C. 4A25	SA1184WE	United Data Control cockpit voice recorder.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1220WE	Brownline pallet 23118-51 and Brownline pallet net 22672-51.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1347WE	GAlley 100 and 200 at fuselage stations 447.75 to 490, and 1385.5 to 1416.	WE	28560	Dale Engineering Company 12243 Branford Street Sun Valley, CA 91352
DC-8 Series; T.C. 4A25	SA1349WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1522WE	Substitution of Brownline cargo container assembly P/N 24026-51 for Douglas pallet assembly P/N 5776662-505 and net P/N 7778335.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airlines San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8 Series; T.C. 4A25	SA1538WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder and Honeywell P/N 180 VI central air data computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA1796WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8 Series; T.C. 4A25	SA2318WE	Installation of emergency exit lights. Issued 3/2/71.	WE	44266	International Inflatables Company 9800 San Fernando Road Pacoima, CA 91331
DC-8 and DC-8F Series; T.C. 4A25	SA1783WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8; DC-9; T.C. 4A25, A6WE	SA2534SW-D	Replacement of switch assembly, International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-8; DC-9; T.C. 4A25, A6WE	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, 104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-8, DC-9, DC-10; T.C. 4A25, A6WE, A22WE	SA2728WE	Incorporation of Holcombe Industries HI_LITE SYSTEM P/N 50-1001 for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -8F-54, -8F-55, -61, -61F, -62, -62F, -63, -63F; DC-9-11, -12, -13, -14, -15, -15F, -21, -31, -32, -32F, -41; DC-10-10; T.C. 4A25, A6WE, A22WE	SA10GL	Installation of Gayston Model 800LG and 800SC static dischargers on transport category airplanes. Issued 12/15/72.	GL	37125	Gayston Corporation 55 Janney Road Dayton, OH 45404
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, -61, -61F, -62, -62F, -63, -63F, DC-8F-54, -55; T.C. 4A25	SA928WE	Installation of replacement safety belt assemblies. Amended 10/9/74.	WE	68725	Rocket Jet/ARD Division American Safety Flight Systems, Inc. 1311 Grand Central Avenue Glendale, CA 91201
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, F-54, F-55; T.C. 4A25	SA1063SO	Installation of forward cargo door. Issued 4/6/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -61, -61F, -62, -62F, -63, -63F, DC8F-54/55; T.C. 4A25	SA2539WE	Installation of emblem light. Reissued 11/8/74.	EA	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-8-12, -21, -33, -51, -52; T.C. 4A25	SA228EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 - 148th Avenue Jamaica, NY 11434
DC-8, -12, -21, -31, -32, -33, -52; T.C. 4A25	SA676CE	Installation of Crimsco cargo container, P/N 600301, utilizing Model 6004 adapter in passenger compartment.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
DC-8-20, -30, -40, -50 Series; T.C. 4A25	SA266GL	Installation of Litton LTN-211 Omega navigation system. Amended 4/26/79.	GL	61788	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-20/50; T.C. 4A25	SA3030WE-D	Install a carry-on baggage module. Issued 9/7/76.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Airport San Francisco, CA 94128
DC-8-21; T.C. 4A25	SA3869WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 2/20/79.	WE	66405	G. S. Rasmussen P. O. Box 10519 Glendale, CA 91209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-21, DC-8-51; T.C. 4A25	ST4499SO	Installation of air data computer with altitude display, altitude reporting, and altitude alerting capabilities. Issued 12/30/70.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, DC-8-51; T.C. 4A25	ST670SO	Installation of International Inflatables Co. P/N 68035 door-mounted emergency evacuation slide at forward entrance door and service door and International Inflatables Co. P/N 68085-3 door mounted emergency evacuation slide at aft entrance and service doors. Amended 10/6/69.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, -32, -51; T.C. 4A25	ST680SO	Installation of Pan Avion Model LSR-210 and LSR-273 emergency evacuation slides and Pan Avion slide pack containers P/N 017-33 and P/N 017-34 at forward and aft passenger entry and service doors.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, . -53, -54, -55; T.C. 4A25	ST844SO	Installation of cargo interior. Amended 5/8/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55. DC-8F-54, -55; T.C. 4A25	SA915SW	Installation of Bendix P/N 19E138-2A flexible drive shaft in lieu of Dana P/N 26567 universal joint shaft on Pratt & Whitney Model JT3D-1 engine gear box and C.S.D. Amended 10/1/71.	EA	16000	The Bendix Corporation Fluid Power Division 211 Seward Avenue Utica, NY 13503
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1033WE	Either single or dual Collins AL-101 radio altimeter systems. Amended 11/19/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airlines San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1034WE	Installation control and annuciation circuitry to implement Flight Director "Go-Around" command modes. Amended 4/1/68.	WE	80500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -54, -55; T.C. 4A25	SA1088SO	Installation of a cargo interior. Issued 7/11/79.	SW	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1405WE	Structural installation of Dorne and Margolin DMC 33-2 Satcom VHF radio antenna.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -32, -51, -61; T.C. 4A25	SA1980WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8, -8-21, -31, -33, -51, -52, -54F, -61, -62; T.C. 4A25	SA2211WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-21, -52; T.C. 4A25	SA2316WE	Revised interior arrangement to an all-tourist, 149-passenger configuration. Amended 5/23/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -51, DC-9 Series; T.C. 4A25, A6WE	SA2405WE	Installation of PICO Division pressure regulator P/N 3001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
DC-8-21, -31, -33, -51, -52; T.C. 4A25	SA2573WE	Installation of interior modifications. Amended 3/6/74.	WE	80500	United Air Lines, Inc. Maintenance Base Engineering Department San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -8F-54, -8-61, -61F, -62, -63, -63F; T.C. 4A25	SA2827WE-D	Installation of Collins FPC-75 P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	FG	STC Code	STC Holder
DC-8-21, -51, -52; T.C. 4A25	SA3033WE-D	Revise interior arrangement to increase coach seating. Amended 6/3/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -33, -51, -52, -61, -62, DC-8F-54; T.C. 4A25	SA3189WE	Installation of UAL NLG orifice support tube assembly, P/N 6F13548-501 and -502. Issued 10/4/77.	WE	80500	United Air Lines San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-33; T.C. 4A25	SA260NW	Modification of pax airplane configuration to cargo configuration (bulk). Issued 2/17/76.	NW	69204	Rosenbaim Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	ST266GL	Installation of a Litton LTN 211 Omega navigation system. Issued 8/25/78.	GL	61788	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA289GL	Load palletized livestock as bulk cargo. Issued 12/22/78.	GL	44036	InterContinental Airways, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA421NW	Cargo modification as done under STC's SA207NW and SA260NW and SA324NW. Issued 3/15/77.	NW	69204	Rosenbaim Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	SA2036WE	Installation of Henry Windscreen Model No. 48102. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8-33; T.C. 4A25	SA2625WE-D	Revise interior arrangement to accommodate all coach, 186 passenger overwater configuration. Amended 4/3/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-33; T.C. 4A25	SA3403WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo handling system, and increasing maximum landing and zero fuel weight. Amended 6/14/78.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846
DC-8-33; T.C. 4A25	SA3611WE	Modification to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3804WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/13/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3907WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3910WE	Modifications to permit an increase in maximum allowable zero fuel weight.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3612WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3749WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo floor, and increasing maximum landing and zero fuel weight. Issued 9/28/78.	WE	52995	McDonnell Douglas Corp. 3855 Lakewood Boulevard Long Beach, CA 90846
DC-8-43; T.C. 4A25	SA3805WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3880WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 3/28/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3911WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-43, -51; T.C. 4A25	SA2681WE	Installation of enclosed overhead stowage bins, sculptured ceiling panels, with integral lighting, improved sidewall lighting, and revised passenger service units. Issued 4/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-50, -60; T.C. 4A25	SA3963WE	Installation of dual Global GNS-500A VLF/Omega navigation systems. Issued 5/23/79.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
DC-8-51; T.C. 4A25	SA1768WE	Installation of stewardess seat Model 6878 on Nordskog galley Model 305A.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-51, -52; T.C. 4A25	SA2835WE-D	Installation of enclosed overhead stowage compartments, improved ceiling and sidewall lighting, relocation of motion picture projector compartments and complete cabin refurbishment. Issued 4/30/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-51, -52, -8F-54, -8-61; T.C. 4A25	SA3357WE-D	Retrofit of fuel quantity indicators and totalizers, Gull Airborne Instruments, Inc. P/Ns 206-009 and 206-016 series. Issued 1/30/78.	WE	80500	United Air Lines San Francisco Int'l Airport San Francisco, CA 91406
DC-8-51, -61; T.C. 4A25	ST857SO	Installation of Bendix ground proximity warning system. Amended 11/14/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8-52; T.C. 4A25	SA448NW	Installation of new look interior conversion kit for Aviaco Air Lines.	NW	41625	Heath Tecna Corporation 19819 - 84th Avenue, South Kent, WA 98031
DC-8-53; T.C. 4A25	SA3613WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3806WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3908WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3909WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3912WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8F; T.C. 4A25	SA605EA	Installation of pallet P/N 6524 incorporating Douglas cargo loading system or pallet P/N 6524 must use nets and be loaded in accordance with Douglas pallet P/N 5776662-505 instructions.	EA	66470	Ray, Daisley Co., Inc. 585 West Hoffman Avenue Lindenhurst, NY 11757
DC-8F-54; T.C. 4A25	SA633CE	Make and install cargo pallets in accordance with Brooks & Perkins Drawing List No. 16987. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	ST677SO	Installation of Nordskog galley Models 376, 377, 378 and 379 at right hand galley positions 1, 2, 3, and 4	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST684SO	Interior conversion of passenger cabin to accommodate 24 first class and 105 tourist class passengers. Amended 1/8/70.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST747SO	Installation of livestock transportation pens. Issued 1/31/75.	SO	21560	Carco Division Charlotte Aircraft Corporation P.O. Box 481225 Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8F-54; T.C. 4A25	SA804EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8F-54; T.C. 4A25	SA813CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA843CE	Installation of cargo-pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA1793WE	Installation of Heathair AC-0152-1 structural container in DC-8F-54 aircraft equipped with cargo loading system No. 7778202-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19815 - 84th Avenue South Kent, WA 98031
DC-8F-54; T.C. 4A25	SA1991WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, -52; 22672-51, -52; or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54; T.C. 4A25	SA1997WE	Installation of Brownline pallet assembly P/N 40309 and net assembly Brownline P/N 21350-51, 21710-51, -52, Douglas P/N 7776431-1 or 7776431-501. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54; T.C. 4A25	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1 or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
DC-8F-54; T.C. 4A25	SA2255WE	Installation of Satco, Inc. pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8F-54; T.C. 4A25	SA2274WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
DC-8F-54; T.C. 4A25	SA2745WE-D	This modification provides seats, oxygen, cockpit communications, emergency equipment and other items necessary to carry six couriers or other persons authorized aft of Station 1370. Issued 4/22/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54; T.C. 4A25	SA3586WE-D	Installation of a removable dual Delco C-IV inertial navigation system for navigation only. Issued 10/27/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54, -55; T.C. 4A25	SA697CE	Installation of Aeroquip Corp. cargo tie-down net.	GL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203
DC-8F-54, -55; T.C. 4A25	SA1623WE	Installation of Heath 88 x 125-inch cargo pallet P/N AC-10061-1 and cargo net P/N AC-10069-1 on subject models equipped with McDonnell Douglas cargo loading system No. 7776939. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1665WE	Installation of Heath Tecna 88 x 125-inch cargo pallet, P/N AC-10160 and net P/N AC-10069. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1875WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8F-54, -55; T.C. 4A25	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517 with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks and Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2234WE	Installation of Brownline Division Division structural container 41342-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2278WE	Installation of Brownline cargo container Model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-F54, -8-55 Series; T.C. 4A25	SA2137WE	Installation of Litton inertial navigation system(s) LTN51 (dual or single) or LTN72 (dual or single). Amended 12/14/78.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
DC-8F-54, -8-55; T.C. 4A25	SA4088WE	Installation of single or dual Litton LTN-72 INS. Issued 1/30/80.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
DC-8F-54, -8F-55, -8-61F, -62F, -63F; T.C. 4A25	SA1807WE	Installation of Brownline pallets and nets. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-61F, -8-63F; T.C. 4A25	SA2098WE	Modification by installation of structural cargo container 40619-101 and -102. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA1812WE	Installation of Heath Tecna 88 x 125-inch cargo pallets P/N AC-10355-1 and AC-10366-1 and net P/N AC-10357-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA2114WE	Installation of Brownline cargo container Model 40622. Amended 5/16/75.	WE	79500	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F, -9-32F, -33F; T.C. 4A25, A6WE	SA2152WE	Installation of Heath 88 x 108-inch cargo pallet AC-10527-1 and net AC-10196-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
DC-8F-54, -8-62F; T.C. 4A25	SA1974WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and Brownline net assembly P/N 22672-51, 22672-52, 23143-51, 40657, 40850, 40517, 22273-51, 22758-51, 22758-52; Douglas net assembly P/N 7776967-1 or Aeroquip net assembly P/N 3950020. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55; T.C. 4A25	SA672EA	Installation of two place courier seat, lavatory compartment and smoke curtain.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8F-55; T.C. 4A25	SA1395WE	Substitution of Brownline pallet P/N 23640-51 and P/N 23224-51 for Douglas pallet P/N 5776662-505.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-55, -8-61F; T.C. 4A25	SA1764WE	Installation of Heathair pallet Model AC10194 and net Model AC-10196. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8F-55, -61F, -63F; T.C. 4A25	SA1028EA	Installation of Collins FPC-75 ground proximity warning system. Amended 6/22/76.	EA	70600	Seaboard World Airlines, Inc. Seaboard World Building JFK International Airport Jamaica, NY 11430

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8F-55, -8-62F; T.C. 4A25	SA2059WE	Installation of 88 x 125-inch cargo pallet P/N 24076-51, 88 x 108-inch pallets P/N 40309101 and 40309102, and 88 x 53-inch pallets P/N 40464101 and 40464102 with net assemblies 22361-51, 22364-51, 22758-51, 22273-51, 21530-51, 21710-51, -52, and 21869-51. Amended 10/12/70.	WE	17749	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55, -8-63F; T.C. 4A25	SA589EA	Installation of dual omnitrac navigation system. Amended 7/19/68.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8F-55, -8-63F; T.C. 4A25	SA675EA	Installation of L. Marino cargo net. Amended 3/31/70.	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
DC-8F-55, -8-63F; T.C. 4A25	SA725EA	DC-8F pallet P/N LM1600 (1.50 Fwd), DC-8-63F pallet P/N LM1600 (1.50 Fwd).	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
DC-8F-55, -8-63F; T.C. 4A25	SA2218WE	Installation of Satco cargo pallet P/N 31 80-501, NAS classification 3610-2A3P and P/N 31076-501, NAS classification 3610-2A1P with cargo nets Brownline P/N 22758-51, -52, -54, 22672-52, 22273-51, 23226-51, 40517-101; Heath Tecna P/N AC 10292-1; Marino P/N LM 1500-100; and ANCRA Corp. P/N 40178-10. Amended 10/12/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8-61; T.C. 4A25	SA467EA	Inflight Motion Picture provisions. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-61; T.C. 4A25	SA1400WE	Installation of 198-passenger interior arrangement. Amended 4/17/74.	GL	80500	United Air Lines, Inc. Executive Offices 1200 Algonquin Road Elk Grove Township, IL 60007
DC-8-61; T.C. 4A25	SA1926WE	Dual installation of A.C. Electronics Carousel IV INS units. Amended 1/16/70.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2128WE	Installation of RCA Model AVQ-30C weather radar system.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2558WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other interior changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2674WE	Revised interior arrangement. Issued 3/23/73.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94158
DC-8-61; T.C. 4A25	SA2739WE-D	Revised seating configuration. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2741WE-D	Installation of equipment to provide guidance to flight director and SP-30AL autopilot to conduct two-segment approaches. Amended 4/7/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2804WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 3/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61; T.C. 4A25	SA2824WE-D	Installation of dual Delco C-IV inertial navigation systems. Issued 1/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3032WE-D	Install carry-on baggage module in place of one first class seat assembly. Amended 12/27/76.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3038WE-D	Installation of dual Collins FD-109 flight director system. Issued 5/24/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-61; T.C. 4A25	SA3039WE-D	Installs galley units and all supporting structure including plumbing and wiring at three locations. Amended 8/19/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3040WE-D	Installation of cabin new look, cabin refurbishment, inflight entertainment installation, passenger seat procurement and rework, and internal partitions and stowage cabinet. Issued 6/11/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61;	SA3356WE-D	Revise interior arrangement to accommodate dual class, 12 first class and 177 coach passenger configuration. Issued 11/4/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3582WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3587WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 12/14/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3588WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 1/5/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3593WE-D	Seat mix change from 26 F/C and 156 coach passenger configuration to 26 F/C and 164 coach passenger configuration. Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA4091WE	Deletion of a pair of excess Type 1 exits at station 1124. Issued 1/22/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61, -61F, DC-8-63, -63F; T.C. 4A25	SA1873WE	Installation of Litton Systems dual LTN-51 or LTN-52 inertial navigation systems. Amended 1/4/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61, -62, -62F; T.C. 4A25	SA1006EA	Installation of cabin interior furnishings. Amended 8/26/77.	EA	12500	Atlantic Aviation Corporation Greater Wilmington Airport P.O. Box 1709 Wilmington, DE 19899
DC-8-61, -63; T.C. 4A25	SA1096SO	Installation of Dual Tracor, Inc. omega navigation systems, Model 7640A. Issued 8/23/79.	SO	19848	Capitol International Airways, Inc. Smyrna Airport Smyrna, TN 37167
DC-8-61F; T.C. 4A25	ST687SO	Installation of AIF class divider partitions, left hand and right hand assembly, P/N 32012 with header assembly, P/N 32013.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-61F; T.C. 4A25	SA2157WE	Installation of 242 passenger seating arrangement. Issued 6/5/70.	WE	81064	Universal Airlines 401 McCormick Street San Leandro, CA 94577
DC-8-61F; T.C. 4A25	SA2481WE	Installation of Trans Com Model 1357 movie projector and screen assemblies. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
DC-8-61F; T.C. 4A25	SA3279WE	Installation of Litton ground proximity warning system computer P/N 456300-01, -202 in the provisions under STC SA1028EA. Issued 10/28/76.	WE	51500	Litton Systems, Inc. 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F; T.C. 4A25	SA2800WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Amended 3/12/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F, DC-8-63F; T.C. 4A25	SA630CE	Installation of cargo pallets. Amended 11/1/79.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-61F, -8-63F; T.C. 4A25	SA1733WE	Installation of Nordskog seat assembly P/N 61247 with certain interior arrangements. Amended 4/12/71.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-62; T.C. 4A25	SA1959WE	Installation of movie projection system.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-8-62; T.C. 4A25	SA2299WE	Installation of third AC electronics carousel IV inertial navigation system. Issued 12/31/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2310SW	Install wheel and brake advisory system. Issued 5/17/76.	SW	17075	Braniff Airways, Inc. P.O. box 35001 Dallas, TX 75235
DC-8-62; T.C. 4A25	SA2377WE	Installation of Collins Radio Company INS - 61B inertial navigation system. Amended 12/7/71.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2533WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other architectural changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2581WE	Installation of Collins Radio Company inertial navigation systems. Issued 8/23/72.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
DC-8-62; T.C. 4A25	SA2738WE-D	Revise seating arrangement to 154 passenger configuration; revise passenger service unit locations to comply with seating configuration; install class dividers and curtains. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2742WE-D	Install dual class seating arrangement (4 and 6 across). Amended 5/2/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2818WE-D	Installation of triple Delco Electronics carousel IV-A inertial navigation system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2819WE-D	Installation of Atlantic Aviation wide body kit. Issued 11/8/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2820WE-D	Installation of passenger entertainment and automatic announce system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2840WE-D	Install an alternate all tourist seating and galley configuration. Galley configuration was previously approved under STC SA2296WE. Amended 6/8/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2904WE	Installation of GAMMA inertial navigation system. Issued 7/2/74.	WE	71838	The Singer Company Kearfott Division 5730 West Manchester Avenue Los Angeles, CA 90045
DC-8-62; T.C. 4A25	SA3351WE-D	Installs a 181 passenger all coach cabin seating configuration.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3361WE-D	Installs a 16 first class/123 coach dual class seating configuration. Issued 1/16/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3576WE-D	Revise interior arrangement to accommodate 162 coach passenger configuration. Issued 6/2/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-62; T.C. 4A25	SA3584WE-D	Seat mix change from 162 passenger all coach configuration to 18F/129Y-147 passenger configuration. Amended 11/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62, -62F; T.C. 4A25	SA993EA	Installation of Inflight Motion Pictures, Inc. 16 mm. movie projection system IR4000 and screen assemblies. Amended 8/26/77.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-62F; T.C. 4A25	SA2308WE	Installation of cargo barrier net. Issued 1/27/71.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-8-62F; T.C. 4A25	SA2785WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 11/20/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-62F, DC-9-31; T.C. 4A25, A6WE	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 12/10/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
DC-8-63; T.C. 4A25	SA649SO	Installation of lounge table AIF P/N 31538-101.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-63; T.C. 4A25	ST681SO	Installation of class divider partition assembly P/N 31929-100 left hand and 31929-200 right hand at fuselage station 2900.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST682SO	Installation of lounge table assembly P/N 31928/100 right hand and P/N 31928-101 left hand at fuselage station 338.0.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST728SO	Interior modification and installation of 251 passenger service units and galley attachments to provide for 251 passenger arrangement (less seats and galleys). Issued 4/28/72.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-8-63; T.C. 4A25	ST737SO	Main cabin interior modifications. Issued 3/28/73.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-8-63; T.C. 4A25	SA750NW	Installation of Mark I interior kit. Issued 4/12/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
DC-8-63; T.C. 4A25	SA1730WE	Installation of cockpit voice recorder, seat lights, passenger service outlets, communication panel relocation, galley wiring changes, flight data recorder and vertical accelerometer, pitot tube with heater circuit, marker beacon.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA1738WE	Modification of interior arrangement to 221 passenger Military Airlift Command configuration. Amended 11/7/68.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA1909WE	Modification of interior arrangement to provide automatic folding attendant seats at the four jet escape exits.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA2704WE-D	Installation of enclosed overhead stowage bins, sculptured ceiling panels with integral lighting, cabin refurbishment. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-63; T.C. 4A25	SA3854WE	Installation of Tracor 7640A ONS. Issued 3/21/79.	WE	79200	Transinternational Airlines P.O. Box 2504 Oakland International Airport Oakland, CA 94614
DC-8-63, -63F; T.C. 4A25	SA2154WE	Installation of triple Litton LTN-51 inertial navigation system. Amended 4/23/71.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
DC-8-63F; T.C. 4A25	SA652EA	Installation of dual Decca doppler systems, Type 72. Reissued 7/2/69.	EA	44900	I.T.T. Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-63F; T.C. 4A25	ST766SO	Installation of double deck livestock transportation pens. Issued 11/1/77.	SO	11320	Animal Air Services, Inc. 14441 Northwest 13 Court Miami, FL 33162
DC-8-63F; T.C. 4A25	SA1039EA	Installation of animal restraint system for air shipment of livestock. Reissued 11/9/78.	EA	79304	Transmeridian Air Cargo Ltd. Stansted Airport Stansted, Essex, England
DC-8-63F; T.C. 4A25	SA1731WE	Install single Decca Model 72 doppler radar (ground speed and drift angle only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA1928WE	Installation of Heath Tecna 88 x 125-inch cargo pallet P/N AC-10065-1 with Heath Tecna net P/N AC-10292-1 or Brownline net P/N 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1950WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and net assembly P/N 22672-51, 22672-52, 22758-51, 22758-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1955WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, 22758-52, 22672-51, 22672-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1978WE	Installation of underseat baggage restraint system with certain specified seat models. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1987WE	Installation of Edo Model 144 ADF-Loran antenna splitter.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2017WE	Installation of Decca Model 72 doppler radar (ground speed and drift meter only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2018WE	Installation of Decca Model ADL-21 Loran.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2087WE	Installation of Cargo Systems, Inc. 88 x 125-inch cargo pallet assembly 1950-90-1 with Brownline net P/N 22758-51.	WE	19890	Cargo Systems, Inc. 1040 West Hoover Orange, CA 92667
DC-8-63F; T.C. 4A25	SA2113WE	Installation of two Decca Type 05 Omnitrac 2B Doppler/Loran navigation computer systems with pictorial displays.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2247WE	Installation of Lockheed Aircraft Services Company Model 250-A weight and balance computer system. Issued 10/9/70.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2259WE	Installation of Brownline pallet assembly P/N 41339 and Brownline net assembly P/N 41344. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA2287WE	Installation of Henry Engineering cargo container Model 52501. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8-63F; T.C. 4A25	SA2313WE	Installation of Kollsman "Slim Pac" altitude alerting system. 3/1/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2314WE	Revised seating arrangement to 244 passenger all tourist configuration. Issued 2/18/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2427WE	Installation of a third attitude indicator. Issued 10/15/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-63F; T.C. 4A25	SA2465WE	Installation of dual Delco Carousel IV inertial navigation system. Issued 12/30/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2522WE	Installation of Nordskog tray carrier storage unit Model 798P. Issued 5/17/72.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-63F; T.C. 4A25	SA2604WE	Installation of Custom Products passenger type seat and flight crew glare protection curtain. Issued 10/24/72.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2616WE	Installation of Trans Com Model 1144 movie projector, screen assemblies and sound system. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
DC-8-63F; T.C. 4A25	SA2632WE	Modification of airplane to provide attitude information from INS in lieu of two vertical gyros (this modification pertains only to aircraft previously modified by STC SA2465WE). Issued 1/9/73.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2634WE	Installation of three Litton LTN-72 inertial navigation systems. Issued 1/9/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-63F; T.C. 4A25	SA2957WE	Installation of separate differential oil pressure system and associated warning light indication. Issued 12/23/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA3082WE	Installation of Satco, Inc. cargo pallet assembly, P/N 31250-521. Issued 9/3/75.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8-63F; T.C. 4A25	SA3123WE	Installation of cargo container P/N 10-1000. Amended 4/19/76.	WE	25955	Container Development 2636 North Ontario Burbank, CA 91504
DC-8-63F; T.C. 4A25	SA3176WE	Installation of Litton Aero Products digital ground proximity warning system. Issued 4/21/76.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-9 Series; T.C. A6WE	SA333SO	Beverage bar.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA335NW	Modified cabin interior kit. Issued 8/13/76.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
DC-9 Series; T.C. A6WE	ST399SO	Addition of underseat luggage restraint.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA457CE	Lockheed Aircraft service 109D flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA508CE	Installation of Safe Flight P/N 1300-33 SCAT computer in lieu of P/N 1300-32.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA520CE	Installation of airborne engine vibration monitoring system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA580EA	Installation of Collins Radio CLC Type 560F-3 area navigation system.	EA	31420	Eastern Airlines, Inc. 10 Rockefeller Plaza New York, NY 10020
DC-9 Series; T.C. A6WE	ST626SO	Removal of complete passenger accommodations; installation of cargo interior. Amended 5/13/69.	SO	34220	Fairchild Hiller Corporation Aircraft Service Division St. Augustine, FL 32084
DC-9 Series; T.C. A6WE	ST627SO	Installation of cargo accommodations. Amended 5/13/69.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
DC-9 Series; T.C. A6WE	SA640NW	Installation of deep interior rack kits. Issued 7/21/78.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9 Series; T.C. A6WE	SA727NW	Delete L.H. galley, add coatroom, add 2 auxiliary galley units at forward left and right side of cabin. Issued 2/27/79.	NW	78672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
DC-9 Series; T.C. A6WE	SA730CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA752CE	Install Bendix gyro horizon, P/N 1978130-2, and Bendix inverter, P/N 1964771-2.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA829CE	Install Butler National Corporation flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA1003SW	Modify 721B galley to 721B-1 and install.	SW	84250	Vought Aircraft Service Co. Div. of LTV Aerospace Corp. 4100 North Main Street Fort Worth, TX 76107
DC-9 Series; T.C. A6WE	SA1459WE	Interior configuration modification.	WE	16892	Bonanza Air Lines 3737 East Bonanza Way P.O. Box 12405 Phoenix, AZ 85034
DC-9 Series; T.C. A6WE	SA1784WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-9 Series; T.C. A6WE	SA1797WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-9 Series; T.C. A6WE	SA2330WE	Installation of battery-powered emergency exit lighting in tail-cone. Issued 3/29/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331
DC-9 Series; T.C. A6WE	SA2451SW	Marathon Battery Co. P/N 85-0050 six cell magnesium emergency light pack. Issued 4/20/77.	SW	54810	Marathon Battery Company 8301 Imperial Drive Waco, TX 76710
DC-9 Series; T.C. A6WE	SA2541WE	Installation of tail cone slide cover. Issued 6/2/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352
DC-9 Series; T.C. A6WE	SA3623WE	Installation of stretcher carrier P/N 2003. Issued 4/13/78.	WE	08205	Air Medic, Inc. 12517 Chandler Blvd. No. Hollywood, CA 91607
DC-9-10; T.C. A6WE	ST498SO	Modification of main landing gear brake stud. Issued 4/19/72.	SO	84470	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-9-10-20, -30, -40 Series; T.C. A6WE	ST699SO	Installation of International Inflatable Company Model 68090 emergency evacuation slide modified with Pan Avion valve assembly P/N 526-43. Issued 11/9/71.	SO	62384	Pan Avion P.O. Box 213 Miami, FL 33101
DC-9-10, -20, -30, -40 Series; T.C. A6WE	SA2223WE	Installation of door mounted battery-powered emergency lights. Amended 5/6/71.	WE	44266	International Inflatables Company 9880 San Fernando Boulevard Pacoima, CA 91331
DC-9-10, -30; T.C. A6WE	ST870SO	Installation of Collins FPC 75 ground proximity warning system. Issued 11/25/75.	SO	73874	Southern Airways, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-10, -30; T.C. A6WE	SA1177CE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/11/79.	CE	62030	Ozark Air Lines, Inc. St. Louis International Airport Lambert Field St. Louis, MO 63145
DC-9-10, -30; T.C. A6WE	SA3097WE	Installation of Collins Radio Co. Model FPC-75 ground proximity warning system. Amended 4/6/76.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-11, -12, -13, -14, -15, -31, -32; T.C. A6WE	ST735SO	Installation of protective rigid cover over tail cone emergency evacuation slide (installation of International Inflatables Model 68090 slide per STC ST676SO or equivalent required with this STC). Issued 12/4/72.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-11, -12, -13, -14, -15, -15F; T.C. A6WE	SA2233WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-9-11, -12, -13, -14, -15, -15F, -21; T.C. A6WE	SA2503WE	Installation of replacement cooling turbine nozzle assembly. Issued 4/20/72.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91503
DC-9-11, -12, -13, -14, -15, -15F; T.C. A6WE	SA2645WE	Installation of dual Litton LTN-51 inertial navigation system. Issued 2/2/73.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
DC-9-11, -14, -15F, -31; T.C. A6WE	SA1933WE	Installation of under seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-14, -15; T.C. A6WE	SA527CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2981WE	Modification of No. 1 galley, Hughes Airwest P/N RW2530045 or Nordskog P/N 742A Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2982WE	MOdification of No. 2 galley, Hughes Airwest P/N RW2530051 or Nordskog P/N 645A. Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-14, -31; T.C. A6WE	ST676SO	Installation of International Inflatables Company emergency evacuation slide, Model 68090, at tail cone exit.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-9-14, -9-31, -9-32; T.C. A6WE	SA2765WE	Installation of altitude alerting and reporting capabilities. Issued 10/10/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15; T.C. A6WE	SA1511CE	Increase the passenger capacity from 83 to 90. Issued 9/6/79.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9-15; T.C. A6WE	SA1728WE	Installation of Bendix Model DRA 12 Doppler navigation system and relocation of ATC transponder antenna and marker beacon antenna. Amended 2/6/70.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-9-15; T.C. A6WE	SA2587WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 3/18/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
DC-9-15; T.C. A6WE	SA2764WE	Altitude alerting and reporting capabilities are provided by installation of Harowe P/N 2031-01-1 altitude alert system, replacement of captain's barometric altimeter with a Harowe P/N 2050-01-1 servo actuated altimeter and two existing air data computers are replaced by Sperry P/N 2587400-176 air data computer. Issued 9/28/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15; T.C. A6WE	SA3051WE	Change seating configuration to 80 economy class, and installation of two auxiliary galleys at fuselage stations 764.5 to 784. Issued 5/29/75.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846
DC-9-15F; T.C. A6WE	SA2028WE	Replacement of V.H.F. 7533483 SAU polyethylene dielectric coaxial cables with Type RG115 A/U PTFE dielectric coaxial cables and addition of head-shield between APU exhaust shroud and wiring conduits.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
DC-9-15F; T.C. A6WE	SA2763WE	The captain's altimeter is replaced by Harowe P/N 2050-01-1 servo actuated altimeter and existing altitude alert system is replaced by Harowe P/N 2031-01-1 altitude alert system. Issued 9/19/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-15F; T.C. A6WE	SA2788WE	Installation of galley assembly, P/N RW2530045. Issued 12/6/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA2789WE	Installation of Hughes Airwest galley assembly, P/N RW2530051. Issued 12/10/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA3558WE	Installation of 535-gallon auxiliary fuel tank system in forward cargo compartment. Issued 3/8/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
DC-9-21, -31, -32F (USAF C-9A), -32, -33F, -41; T.C. A6WE	SA862EA	Addition of airspeed select function to speed command/autothrottle system. Amended 6/27/78.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
DC-9-21, -31, -32, -32F, -33F, -41, -51; T.C. A6WE	SA2212WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 8/24/75.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-9 Series 30; T.C. A6WE	SA130GL	Installation of Systron-Donner Model 8160-20-P10 angular rate sensor in lieu of presently installed rate gyros in pitch-axis computer, roll-axis computer, and stability augmentation computers. Issued 7/23/76.	GL	61625	North Central Airlines, Inc. 7500 Northliner Drive Minneapolis, MN 55450
DC-9-30; T.C. A6WE	SA3642WE	A speed comman system, safe flight P/N 1312-25B installed. Issued 5/16/78.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-30, -9-31; T.C. A6WE	SA294NW	Interior arrangement, coatroom installation. Issued 5/14/76.	NW	48532	KME Manufacturing 800 North 6th Street Renton, WA 98055
DC-9 Series 30; T.C. A6WE	ST499SO	Modification of main landing gear brake stud. Issued 4/19/72.	SO	84770	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-9 Series 30; T.C. A6WE	SA1658WE	Installation of Airborne vibration monitoring system equipment.	WE	25917	Consolidated Electrodynamics Corp. Transducer Products Division 1400 South Shamrock Avenue Morovia, CA 91016
DC-9 Series 30; T.C. A6WE	SA2473WE	Installation of AiResearch cooling turbine P/N 204950-5-3 in lieu of P/N 204950-5-2. Issued 2/18/72.	WE	07505	AiResearch Manufacturing Company Division of Garrett Corporation 9851 Sepulveda Boulevard Los Angeles, CA 90009
DC-9 Series 30; T.C. A6WE	SA2803WE	Replacement of splined end on DC-9 nose gear cylinder, Douglas P/N 5920602. Amended 2/1/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9 Series 30; T.C. A6WE	SA2805WE	Replacement of splined end of DC-9 nose gear cylinder. Issued 1/18/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9-30; T.C. A6WE	SA3887WE	Installation of two Howell Model H900 solid state exhaust gas temperature indicators. Issued 3/29/79.	WE	43340	Hughes Airwest 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-30; T.C. A6WE	SA4059WE	Installation of ground proximity warning system (GPWS) and altitude alert system. Issued 12/13/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
DC-9-30, -32F, -33F, -51; T.C. A6WE	SA3115WE	Installation of Collins ground proximity warning system. Amended 4/7/76.	PC	41260	Hawaiian Airlines Honolulu International Airport Honolulu, HI 96820
DC-9-30, -50; T.C. A6WE	SA84GL	Install Bendix GPW-83 ground proximity warning system. Amended 8/10/76.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450
DC-9-31; T.C. A6WE	ST464SO	Installation of Decca IIB 06 omnitrac area navigation system. Operations will not be predicated on use of vertical guidance information of area navigation system. Amended 6/29/71.	SO	31420	Eastern Airlines International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	ST557SO	Installation of 99 passenger interior arrangement. Issued 10/6/73.	SO	31420	Eastern Airlines International Airport Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-31; T.C. A6WE	SA878EA	Installation of SFENA standby horizon indicating system. Reissued 12/22/75.	CE	62030	Ozark Air Lines Box 10007, Lambert Field St. Louis, MO 63145
DC-9-31, -32; T.C. A6WE	SA3888WE	Installation of an auxiliary fuel tank system in the forward baggage compartment. Amended 5/25/79.	WE	43340	Hughes Air West, Inc. 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-31, -32, -32F, -33F, -41; T.C. A6WE	SA2502WE	Installation of replacement cooling turbine nozzle assembly. Amended 11/13/73.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91504
DC-9-31, -9-51; T.C. A6WE	SA1019EA	Installation of Collins Model FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
DC-9-31/-51; T.C. A6WE	SA3455WE	Installation of tourist and first class interiors. Amended 10/12/79.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-9-32; T.C. A6WE	ST856SO	Installation of Bendix ground proximity warning system. Issued 10/21/75.	SO	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	ST921SO	Fabrication and installation of baggage stowage rack, P/N 325100. Issued 1/28/77.	SO	29234	Delta Airlines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	SA1895WE	Installation of a second observer seat in flight crew compartment.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-9-32; T.C. A6WE	SA2106WE	Modification consists of interior arrangement, various passenger entertainment systems and avionics equipment. Reissued 8/20/73.	GL	64730	Playboy Enterprises, Inc. 919 North Michigan Avenue Chicago, IL 60611
DC-9-32 (VC-9C), DC-9-32F(C-9A); T.C. A6WE	ST248GL	Installation of Collins Model FPC flight profile comparator, P/N 622-2615-500, and Harowe barometric altitude rate computer, P/N 4030-03-1. Amended 7/19/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
DC-9-32F; T.C. A6WE	SA1043EA	Installation of structural provisions for executive interior. Issued 11/24/76.	EA	12500	Atlantic Aviation Corporation Box 1709 Wilmington, DE 19899
DC-9-32F; T.C. A6WE	SA2598WE	Installation of passenger pallet system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA697EA	Installation of (4) Aerojet-General Corp. 15 KS-1000-A1 or Bristol Aerospace (1968) Ltd. 15 KS-1000-A1(B) rocket engines and fairings. Amended 2/29/72.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-9-32F, -33F; T.C. A6WE	SA1970WE	Installation of 88 x 108-inch cargo pallet P/N 24545-51, -52, or -53 with net P/N 24550-51, -52, or -53 and 88 x 54-inch cargo pallet P/N 24546-51, -52, or -53 with net P/N 24551-51 or -52. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2021WE	Installation of various cargo pallets and nets (per Tridair "Loading Instructions Drawing No. 40414). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2092WE	Installation of Heath 54 x 88-inch cargo pallet AC-10528-1 and net AC-10657-101. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-9-41; T.C. A6WE	SA3366WE	Modification of cabin interior. Installation includes all or part of the following overhead storage compartments, sculptured ceiling and sidewall panels, flourescent cabin lighting, standby lighting, emergency lighting, and an overwing exit locator sign. Amended 3/31/78.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-51; T.C. A6WE	SA3660WE	Installation of Carrier Aircraft coat closet Model EAL951-1. Issued 6/6/78.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-51; T.C. A6WE	SA3800WE	Installation of a 130 passenger seating arrangement, two galleys, and associated water drain mast. Issued 12/6/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
DC-9-51; T.C. A6WE	SA4002SW	In-place cargo system. Issued 7/31/79.	CE	04250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74112
DC-9, DC-10-30; T.C. A6WE	SA1068EA	Replacement of Fairchild Burns seats by Magee Plastics Co. seat trim kit P/N 67203. Issued 2/14/78.	EA	53200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15237
DC-10; T.C. A22WE	SA285NW	Installation of Trans Com System. Issued 4/15/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
DC-10; T.C. A22WE	SA419NW	Class divider installation. Issued 3/10/77.	NW	48532	KME Manufacturing 800 North 6th Street Renton, WA 98055
DC-10; T.C. A22WE	SA713NW	Installation of class divider. Issued 1/30/79.	NW	48532	KME Manufacturing Company The Commons Building 1200 112th N.E. Bellevue, WA 98004
DC-10; T.C. A22WE	SA3892WE	Installation of Stowe Corp. service carts. Issued 3/23/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-10; T.C. A22WE	SA2611WE	Installation of three Litton LTN-51 inertial navigation systems, an inertial navigation switching unit and two Sperry horizontal situation indicators. Amended 3/5/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10;	SA2816WE	Modification of DC-10-10 aircraft for the installation of spacer pallets. Issued 2/8/74.	WE	80500	United Air Lines, Inc. Engineering Department San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2836WE-D	Installation of Bell and Howell video entertainment system in A, B and C zones of passenger cabin. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2837WE-D	Install new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 12/9/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2888WE	Installation of three Litton LTN-51 or LTN-72 inertial navigation systems. Issued 2/28/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10; T.C. A22WE	SA3025WE-D	Installation of refrigeration cooling for DME interrogators. Amended 3/12/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3031WE-D	Installation of four additional serving cart tie downs on main deck. Amended 9/13/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3035WE-D	Install slide-raft assembly at each LH and RH cabin door exit. Issued 2/17/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3036WE-D	Modifies aircraft to install dual Delco C-IV inertial navigation systems (INS) for attitude and direction reference, navigation, and autopilot steering. Issued 3/22/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3127WE	Installation of first class passenger seats incorporating unitized oxygen systems. Issued 12/11/75.	WE	85126	Western Airlines, Inc. 6060 Avion Drive Los Angeles, CA 90052

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-10; T.C. A22WE	SA3358WE-D	Reduces first class seating to 16 seat places, installs 9-across coach seating - 243 seat places, installs class divider, lounge table, PSF, and closets in zone A, closet in zone C. Issued 11/15/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3510WE	Replace primary thrust reverser with conical nozzle and plug; modify pylon aft fairing; and remove upper and lower actuators and drive cables. Issued 10/31/77.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012
DC-10-10; T.C. A22WE	SA3580WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 4/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3591WE-D	Installs new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 9/11/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3696WE	Training requirements, special limitations, and installation of required provisions, including communications and equipment to permit occupancy of the lower galley during taxi. Issued 7/12/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3815WE	Installation of a video projection system. Amended 2/28/79.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10; T.C. A22WE	SA4041WE	Installation of Litton LTN-211 Omega navigation system. Issued 11/30/79.	WE	85126	Western Airlines, Inc. 6060 Avion Drive Los Angeles, CA 90052
DC-10-10, -10-10F; T.C. A22WE	SA2524WE	Installation of lounge seats, four-place divan, L-shaped bar, and cocktail tables. Amended 3/8/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2770WE	Installation of visual entertainment system. Issued 10/2/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10, -10-10F; T.C. A22WE	SA2924WE	Installation of wheeled refrigerated module, P/N 73011000. Issued 8/27/74.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-10F; T.C. A22WE	SA2948WE	Installation of buffet/bar and bustle assembly. Issued 1/22/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA2985WE	Modification of installed G1 and G1A galleys (Dale P/Ns CAG-11000, CF-10-1, CAG-10000, CF-7000). Issued 1/22/75.	WE	25970	Continental Airlines 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2987WE	Installation of cabin lounge swivel seats and adjustable table with removable top. Issued 1/23/75.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3014WE	Installation of floor game table assembly. Amended 1/20/76.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91100
DC-10-10, -10-10F; T.C. A22WE	SA3212WE	Installation of forward cargo compartment positive vent sump drain. Issued 6/15/76.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3367WE	Installation of nine-abreast coach seating and associated oxygen and electrical system modification. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3368WE	Installation of eight-abreast coach seating in forward cabin behind the first class section, and associated oxygen and electrical system modifications. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-10, -10-10F; T.C. A22WE	SA3827WE	Installation of folding leaf table. Issued 1/31/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA3843WE	Installation of Nordskog Ind. galley 1-419. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3844WE	Installation of composites, unlimited coat closet, P/N 225-46103. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Aicport Los Angeles, CA 90009
DC10-10, -10-10F; T.C. A22WE	SA3845WE	Installation of buffet/bar unit, P/N 2142396. Amended 7/11/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
DC-10-10, -10-10F; T.C. A22WE	SA3847WE	Installation of a new lounge and first class accommodations. Amended 7/12/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3848WE	Installation of HITCO refrigerated galley module. Amended 3/16/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-10-10, -10-10F; T.C. A22WE	SA3875WE	Installation of Continental Air Lines flight attendant seat, P/N 225-46317. Issued 3/16/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3937WE	Installation of HITCO storage galley module. Issued 5/18/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-10-10, -10-10F; T.C. A22WE	SA3996WE	Installation of Litton LTN-2110NS. Issued 7/18/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA4058WE	Installation of folding leaf table. Issued 11/8/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3432WE	Installation of fire/overheat detection system. Amended 2/14/78.	WE	77300	Systron Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3626WE	Revision of DC-10 fire overheat detection system to allow intermixing of Systron-Donner fire detectors with Edison detectors in the fan, core, and pylon sections of the CF6 engines. Issued 4/11/78.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10CF; T.C. A22WE	SA3407WE	Installation of Lermer Apparatebau GMBH beverage cart No. L15701. Issued 5/20/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 91406
DC-10-10, -10-30; T.C. A22WE	SA776SO	Installation of SICMA tray carts at the fixed (non-retractable) fitting locations. Issued 12/13/79.	SO	71600	SICMA Aero Seats, Inc. 6929 N.W. 40th Street Miami, FL 33166
DC-10-10, -10-30; T.C. A22WE	ST734SO	Installation of NAL Val-Pack coatroom, P/N 10621-1. Amended 3/30/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-10-10, -10-30; T.C. A22WE	SA2853WE	Retractable tiedown assemblies. Amended 3/23/78.	WE	48550	H. Koch & Sons Koch Road Corte Madera, CA 94925
DC-10-10, -10-30; T.C. A22WE	SA3067WE	Installation of lower lobe food service modules, P/Ns 818720, 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
DC-10-10, -10-30; -10-30F; T.C. A22WE	SA2395WE	Installation of coffee bar cart, P/N 801000. Amended 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2774WE	Installation of wing tip mounted emblem lights. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2893WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1704-C West 134th Street Gardena, CA 90249

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-10, -10-30, -10-40; T.C. A22WE	SA930EA	Installation of Inflight Motion Pictures, Inc. projection unit assembly DC-10 16mm Tri-Jet system 10300 or light weight Tri-Jet projection system, DC-10 P/N 10307. Amended 9/14/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA947EA	Installation of Inflight Motion Pictures, Inc. screen assemblies. Amended 8/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, New York 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA969EA	Installation of Inflight movie projection assembly P/N 10270, Super 8mm IMPAK system. Issued 11/21/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA990EA	Installation of 16mm projection unit assembly and center stowage bins, P/N 10310. Issued 10/3/74.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA3335WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
DC-10-10, -10-30F; T.C. A22WE	SA2817WE-D	Installation of provisions for ground proximity warning system. Amended 6/26/75.	WE	80500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-10-10, -10-30F; T.C. A22WE	SA2830WE-D	Installation of Collins FPC-75 ground proximity warning system computer. Amended 3/30/76.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10F; T.C. A22WE	SA4006WE	Installation of a 3-place courier seat. Issued 7/31/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-30; T.C. A22WE	SA2663WE	Installation of Trans Com movie and projector entertainment system, Model 2420. Issued 3/19/73.	WE	76800	Trans Com A Division of Sundstrand Data Control, Inc. 3100 Pullman Avenue Costa Mesa, CA 92626
DC-10-30; T.C. A22WE	SA2684WE	Installation of Tridair Industries main deck baggage container system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-10-30; T.C. A22WE	SA2707WE	Installation of cabin lounge seats, folding tables, cart stowage unit, and class divider partition. Issued 6/6/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Airport Mail Facility Miami, FL 33159
DC-10-30; T.C. A22WE	SA3194WE	Installation of Airborne video-cassette system. Issued 5/12/76.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA3344WE	Installation of dual Litton LTN-72R INS/RNAV navigation systems. Issued 2/23/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-30; T.C. A22WE	SA3393WE	Installation of Airborne Video-cassette system.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA3569WE	Installation of aircraft video system. Amended 6/5/79.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10; T.C. A22WE	SA4010WE	Installation of video projection system. Issued 10/5/79.	WE	15375	Bell and Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30, -10-30F; T.C. A22WE	SA2775WE	Installation of Fairchild Stratos tray carrier rack assembly. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2777WE	Installation of service center (G 1) and coffee bar G-2 assemblies. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2780WE	Installation of serving cart pallets, P/N 989200 and 990100. Issued 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-30F; T.C. A22WE	SA2938WE	Carts and pallet assembly installation. Issued 10/9/74.	WE	28560	Dale Engineering & Development, Inc. 12243 Branford Street Sun Valley, CA 91352
DC-10-30F; T.C. A22WE	SA2949WE	Installation of passenger entertainment/service system. Amended 12/6/74.	WE	33223	Electronic Engineering Company of California 1441 East Chestnut Avenue Santa Ana, CA 92701
DC-10-30F; T.C. A22WE	SA2950WE	Installation of ballast assembly. Issued 11/18/74.	WE	79200	Trans International Airlines Oakland International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA3128WE	Installation of 376 passenger interior arrangement and associated oxygen system modifications. Issued 12/15/75.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA3137WE	Installation of courier seat module assembly. Issued 1/21/76.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-40; T.C. A22WE	SA88GL	Installation of Bendix GPW-83 ground proximity warning systems. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40; T.C. A22WE	SA372GL	Installation of Honeywell P/N HG280BD80 digital airdata computer in the number three position per NWA project 1-34-40300 in place of the Honeywell P/N HG280D5 presently used in this position for data collection purposes only. Issued 10/26/79.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40; T.C. A22WE	SA2782WE	Installation of wheeled refrigerated module P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-40, -10-40F; T.C. A22WE	SA3139WE	Installation of wing and tail engine pods. Amended 3/15/79.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

McKINNON ENTERPRISES, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-21C, GD-21D; T.C. 4A24	SA1320WE	Installation of two United Aircraft of Canada, Ltd., Model PT6A-20 engines. Amended 4/22/68.	WE	53520	A. G. McKinnon McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21C, GD-21D; T.C. 4A24	SA1751WE	Increase in main fuel tank capacity to 336 gallons.	WE	53520	McKinnon Enterprises, Inc. Route 1, Box 520 SAndy, OR 97055
G-21G; T.C. 4A24	SA2809WE	Installation of AiResearch TPE331-2UA-203D engines, increase in fuselage length. Issued 11/7/75.	WE	53520	McKinnon Enterprises, Inc. Route 1, Box 690 Sandy, OR 97055

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MESSERSCHMITT - BOLKOW - BLOHM - GMBH

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BO-105A, BO-105C; T.C. H3EU	SA26RM	Installation of JB Systems air-conditioning system. Issued 6/14/74.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
BO-105A, BO-105C; T.C. H3EU	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
BO-105A, BO-105C; T.C. H3EU	SH978EA	Installation of Consolidated Instrument Co., Inc. battery temperature alert system, Models B206-TA180 or B206D-TA180. Issued 4/4/74.	EA	25920	Consolidated Instrument Company Teterboro Airport Teterboro, NJ 07608
BO-105A, BO-105C, BO-105S; T.C. H3EU	SH1065EA	Installation of DeVore tail floodlight on upper surfaces of horizontal stabilizer. Reissued and amended 3/17/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
BO-105C; T.C. H3EU	SH218NW	Installation and maintenance of Allison 250-C20 engine equipment with Bendix fuel control system. Issued 9/10/75.	NW	98124	The Boeing Company P.O. Box 3707 Seattle, WA 98124
BO-105C; T.C. H3EU	SH239WE	Installation of Chandler Evans (CECO) Model 104900-A3-A2 fuel controllers and Model 104500-A governors. Issued 6/11/79.	WE	08353	Air Services International 7300 East Evans Drive Scottsdale, AZ 85026
BO-105C; T.C. H3EU	SH971EA	Installation of cabin door post and door latching mechanism Model Kit No. SK212-10415. Amended 6/10/74.	EA	16880	Boeing Vertol Company Division of Boeing Company P.O. Box 16858 Philadelphia, PA 19142
BO-105C; T.C. H3EU	SH1025EA	Installation of ten inch cabin extension, modification of cabin doors, relocation of battery and structural modification of tail-boom to fuselage splice. Amended 1/9/78.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C; T.C. H3EU	SH1031EA	Installation of AiResearch Manufacturing Co. environmental control unit. Amended 9/8/77.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C; T.C. H3EU	SH1041EA	Relocation of battery to a position just aft of No. 2 engine. Issued 10/12/76.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1069EA	Installation of cabin door post and door latch assembly in accordance with data. Issued 2/23/78.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1073EA	Installation of electric chip directors in main transmission and intermediate and tail rotor gear boxes. Issued 5/19/78.	EA	47790	Keystone Helicopter Corporation 1420 Phoenixville Pike West Chester, PA 19380
BO-105C, BO-105S; T.C. H3EU	SH1182EA	Installation of emergency float kit, F105-85189. Issued 2/4/80.	EA	16880	Boeing Vertol Company A Division of the Boeing Co. P.O. Box 16858 Philadelphia, PA 19142
BO-209-150 FV and RV, BO-209-150FF; T.C. A27EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

MESSERSCHMITT - BOLKOW - BLOHM - GMBH 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BO-209-150 FV and RV, BO-209-150FF; T.C. A27EU	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MEYERS INDUSTRIES, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
OTW, OTW145, OTW-KR, OTW160; T.C. A736	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
OTW-145; T.C. A736	SA742CE	Install Warner Super Scarab 165 hp engine and increase gross weight to 1910 pounds.	GL	77750	Tecumseh Aviation Tecumseh, MI 49286
MAC-125C, MAC-145; T.C. 3A1	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
MAC-125C, MAC-145; T.C. 3A1	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
MAC-125C, MAC-145; T.C. 3A1	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
MAC-145; T.C. 3A1	SA269GL	Installation of Continental O-300-A engine in lieu of Continental C145-2 using original installation hardware and components. No installation data are required. Issued 9/21/78.	GL	41190	Ralph E. Haven Route No. 1 Sherwood, OH 43556

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MITCHELL TRIMOTOR AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
101 (Longren L-13); T.C. 4A15	SA4-900	Oil tank.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
101; T.C. 4A15	SA66SO	Removal of forward right-hand and aft left and right-hand cabin doors or any combination thereof.	SO	02313	Aeroist's International, Inc. 755 West 43rd Place Hialeah, FL 33010

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MITSUBISHI AIRCRAFT INTERNATIONAL, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B, -2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, -40, -60; T.C. A10SW	SA1042SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638T series lead-acid type batteries. Issued 1/15/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Atlanta, GA 30339
MU-2B, MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A10SW	SA1460CE	Installation of microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
MU-2B, -2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, -40, -60; T.C. A10SW	SA3524WE	Installation of vertical tail flood lights on horizontal stabilizer. Amended 4/13/79.	WE	30000	DeVore Aviation Corporation 15160 Stagg Street Van Nuys, CA 91406
MU-2B-25, -2B-26, -2B-35, -2B-36; T.C. A10SW	SA304GL	Installation of Hartzell HC-B3TN-5C/T10178B-13Q propellers in lieu of HC-B3TN-5C/T10178B-11 or 11R propellers using original installation hardware and components. No installation data are required. Amended 12/29/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-36A, -2B-60; T.C. A10SW	SA215GL	Installation of two 25-gallon auxiliary fuel tanks in nose section of main landing gear wheel fairings. Amended 12/26/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62707
MU-2B-36A; T.C. A10SW	SA216GL	Installation of right side fuselage window at station 6335. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-36A; T.C. A10SW	SA217GL	Installation of right side fuselage window at station 6897. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MITSUBISHI HEAVY INDUSTRIES, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B; T.C. A2PC	SA588EA	Installation of Norton replacement nose cap radome, P/N 3077X. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Division P.O. Box 350 Akron, OH 44309
MU-2B; T.C. A2PC	SA595EA	Installation of replacement radome, P/N 3077X.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company Aero Products Operations P.O. Box 1187 Akron, OH 44309
MU-2B; T.C. A2PC	SA633SW	Heading selector and Omni/ILS coupler for Minneapolis-Honeywell H-14 automatic pilot.	SW	60152	Mooney Southwest, Inc. P.O. Box 6127 Midland, TX 79701
MU-2B; T.C. A2PC	SA726SW	Heading select, pitch trim and VOR/ILS coupling modes to Honeywell H-14 autopilot.	SW	60152	Mooney Southwest, Inc. P.O. Box 6127 Midland, TX 79701
MU-2B; T.C. A2PC	SA747CE	Installation of AiResearch TPE331-1-151A engines. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B; T.C. A2PC	SA907SW	AiResearch TPE331-25AA engines.	SW	60150	Mooney Aircraft, Inc. Route 1, Box 544 San Angelo, TX 76901
MU-2B; T.C. A2PC	SA1310WE	M-4C automatic flight control system.	SC	15475	The Bendix Corporation P.O. Box 23433 Fort Lauderdale, FL 33309
MU-2B, MU-2B-10, MU-2B-15, MU-2B-20; T.C. A2PC	SA996SW	Move air conditioning unit 20-inches aft and enlarge luggage compartment.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, MU-2B-10, MU-2B-15, MU-2B-20; T.C. A2PC	SA1029SW	Additional pitot system.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, MU-2B-10, MU-1B-15, MU-2B-20; T.C. A2PC t+1	SA1045SW	Two-place side facing seat.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, MU-2B-10, MU-2B-15, MU-2B-20; T.C. A2PC	SA1048SW	Replacement of Mitsubishi seats.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35; T.C. A2PC	SA582SO	Installation of Bendix RNS-3400 area navigation system. Amended 2/12/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 3331
MU-2B, MU-2B-10, -15, -20, -30; T.C. A2PC	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	65500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
MU-2B, -10, -15, -20, -25, -30, -35; T.C. A2PC	SA1411SW	Emergency locator transmitter. Issued 12/30/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA39GL	Installation of tip tank lights. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA98GL	Installation of engine ignition cut-out override system. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B, 2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA880SO	Installation of Teledyne P/N 88638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	70030	Teledyne Battery Products P.O. Box 431 840 West Brookton Avenue Redlands, CA 92373
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1587SW	Aerosonic altimeter P/N A35-MA-10L1 to replace McCleod altimeter. Issued 1/5/73.	SW	60073	Mitsubishi Aircraft Int'l Inc. P.O. Box 3848 San Angelo, TX 76901

MITSUBISHI HEAVY INDUSTRIES, LTD. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA3490WE	Installation of fuel boost pump. Issued 9/23/77.	WE	26725	Hydro-Aire Division of the Crane Company 3000 Winona Avenue P.O. Box 7722 Burbank, CA 91510
MU-2B, MU-2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, 40, 60; T.C. A2PC	SA3524WE	Installation of vertical tail flood lights on horizontal stabilizer. Amended 4/13/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA32GL	Installation of oil filler access door. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA38GL	Installation of electrically heated glass windshield on pilot's side of aircraft. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA43GL	Installation of wing tip tank fuel dumping system (93 gallon tip tanks only). Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25,, -26, -30, -35, -36; T.C. A2PC	SA58GL	Modification of forward windshield center divider. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -30, -35; T.C. A2PC	SA68GL	Installation of engine fuel drain return line. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1586SW	Alternate oil pressure transmitter. Issued 1/5/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1729SW	Adding weight of 60 pounds for ramp operation. Issued 9/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1857SW	B.F. Goodrich type 25S de-ice boots. Issued 3/19/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-10,-20, -25, -26, -30, -35, -36; T.C. A2PC	SA2266SW	Fabrication and installation of wing panel flap actuator access. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-15, -20; T.C. A2PC	SA955SW	M4C automatic flight control.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-15, -20; T.C. A2PC	SA1354SW	Bendix manual electric trim system. Issued 7/27/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-15, -20; T.C. A2PC	SA1874SW	Battery temperature warning system. Issued 4/24/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20; T.C. A2PC	SA291GL	Installation of auxiliary fuel tank in aft baggage compartment. Issued 1/12/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62707
MU-2B-20; T.C. A2PC	SA1313SW	Interior installation. Issued 5/21/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20; T.C. A2PC	SA1482SW	Hartman series parallel battery relay. Issued 6/14/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25; T.C. A2PC	SA1488SW	Avionics support shelving. Issued 7/6/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25; T.C. A2PC	SA1762SW	Single PC-17 inverter. Issued 11/9/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25; T.C. A2PC	SA1775SW	Flight system AK391 and AK391FD consisting of Century IV autopilot and Century IV autopilot flight director with command electric trim and yaw damper with rudder trim. Issued 12/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-20, -25, -26; T.C. A2PC	SA561SO	Installation of Bendix M-4D automatic flight control system including optional yaw trim, optional manual electric pitch trim and optional flight director system. Amended 1/24/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-20, -25, -26, -30, -35, -36; T.C. A2PC	SA2238SW	Tip tanks lights. Issued 6/8/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35; T.C. A2PC	SA1489SW	Antennas. Issued 7/6/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35; T.C. A2PC	SA1805SW	Foxboro fuel flow signal conditioning unit PC-620. Issued 2/7/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35, -36; T.C. A2PC	SA1940SW	Goulton GB40 cell batteries. Issued 12/12/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -35; T.C. A2PC	SA1776SW	Lear Siegler starter generator, P/N 23046-007M. Issued 1/4/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San angelo, TX 76901
MU-2B-20, -25, -35; T.C. A2PC	SA1814SW	Dual baro scale altimeter. Issued March 1974.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -30; T.C. A2PC	SA161GL	Install Garrett AiResearch TPE331-6-252M engines. Amended 6/15/77.	GL	07503	AiResearch Capitol Aviation Co. Capital Airport Springfield, IL 62705
MU-2B-20, -30; T.C. A2PC	SA1316SW	Series/parallel selector switch for battery start selection. Issued 5/26/71.	SW	60073	Mitsubishi Aircraft Int'l, INc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -30; T.C. A2PC	SA1547SW	Dual PC-17 static inverters. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1465SW	Interior. Issued 8/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1541SW	King basic avionics package. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1546SW	Basic King avionics package. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1548SW	Area NAV KCN 610. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1549SW	AVQ-55 weather radar. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1564SW	Collins basic avionics package. Issued 12/15/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1628SW	RCA AVQ-21 weather radar. Issued 3/15/73.	SO	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1646SW	Sunair ASB-100 HF system. Issued 4/27/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1647SW	Sperry stars IVB flight director. Issued 4/27/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1710SW	Bendix RDR-1200 weathervision system. Issued 8/2/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1711SW	RCA AVQ-47 weather radar. Issued 8/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1733SW	Battery temperature warning system. Issued 9/21/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-25; T.C. A2PC	SA1752SW	Sperry AA-20 radio altimeter. Issued 10/29/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1817SW	Collins ALT-50 radar altimeter. Issued 3/6/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1859SW	RDR-100 weather radar. Issued 3/26/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1793SW	Install Collins FDS-112 C/V flight director. Issued 11/20/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1818SW	Aerosonics encoding altimeter and alerter. Issued 9/13/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1925SW	Basic King gold crown avionics. Issued 2/14/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA2268SW	Installation of #2 VHF comm antenna. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -2B-26, -2B-35, -2B-36; T.C. A10SW	SA304GL	Installation of Hartzell HC-B3TN-5C/T10178B-13Q propellers in lieu of HC-B3TN-5C/T10178B-11 or 11R propellers using original installation hardwarde and components. No installation data are required. Issued 5/7/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1882SW	Chart holder. Issued December 1974.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1912SW	Instrument panel modification. Issued 9/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1914SW	Cooling air inlet screen. Issued 10/15/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1928SW	Sperry GH-14 flight director. Issued 1/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1929SW	United Instruments encoding altimeter. Issued 1/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1964SW	Cooling air inlet modification. Issued 9/25/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1990SW	Pressure relief overboard vent line and restrictor fitting to EPA fuel purge system. Issued 5/21/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2233SW	Rewiring of auto-manual air conditioning switch. Issued 8/15/75.	SW	60073	Mitsubishi Aircraft International P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2263SW	Modification of ECS mixing chamber. Issued 10/9/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2487SW	Outside air temperature indicator. Issued 8/6/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A10SW	SA3489WE	Installation of fuel boost pump. Issued 9/23/77.	WE	26725	Hydro-Aire Division of the Crane Company 3000 Winona Avenue P.O. Box 7722 Burbank, CA 91510
MU-2B-25, -35; T.C. A2PC	SA1614SW	IDC 570-24929-002 encoding altimeter; or Smith's WL-1350 AM/MS-1(-2) encoding altimeter. Issued 6/6/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1615SW	Encoding altimeter/alerting system. Issued 3/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-25, -35; T.C. A2PC	SA1627SW	Collins FDS-112B flight director system. Issued 5/25/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
•t•1 MU-2B-25, -35; T.C. A2PC	SA1703SW	5V light source. Issued 7/18/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1712SW	Oil pressure indicator. Issued 8/10/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1732SW	Kratos 124.102 torque indicator. Issued 9/19/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1736SW	Ametek oil pressure transmitter, P/N 935A-5002. Issued 10/3/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1751SW	Shoulder harness. Issued 10/30/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1764SW	Smith's 1400 encoding altimeter-alerter. Issued 11/16/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1778SW	R.C. Allen gyro. Issued 1/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1779SW	Kollsman dual Baro scale altimeter. Issued 1/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1781SW	Revised ground and air starting procedures with bleed air heat to orifice in fuel control. Issued 1/17/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1816SW	King flight phone. Issued 3/26/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1872SW	Hamilton Standard temperature control system. Issued 4/22/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2315SW	Dual FDS-112B flight director system. Issued 5/21/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2316SW	ONTRAC II VLF system. Issued 5/14/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2317SW	Install IDC RAD/BAR encoding altimeter with altitude alerting. Issued 5/21/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2342WE	Installation of Sperry AA-100 radar altimeter. Issued 9/2/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2208SW	Continuous ignition system. Issued 7/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2247SW	Oxygen cylinder, P/N 6350 A20 00B. Issued 10/1/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2274SW	Heated windshield. Issued 3/18/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2295SW	Install alternate interstage turbine temperature indicator, P/N 935A-6012.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2314SW	Digital clock. Issued 5/20/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2343SW	Alternate aileron trim actuator. Issued 8/5/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-26A, -36A; T.C. A10SW	SA218GL	Installation of oil filler access door. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-26A, -36A; T.C. A10SW	SA219GL	Installation of tip tank lights. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-26A, -36A; T.C. A10SW	SA220GL	Modification of forward windshield center divider. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-26A, -36A, -40, -60; T.C. A10SW	SA214GL	Installation of wing tip tank fuel dumping system. Amended 5/29/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30; T.C. A2PC	SA115GL	Install Garrett AiResearch TPE 331-6-251M (P/N 896160-1) engines. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30; T.C. A2PC	SA1069SW	Mooney AB1001, TSO C-39 seats.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1085SW	Air conditioning system.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1146SW	Interior installation. Issued 5/15/70.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1198SW	11-place interior. Issued 9/30/70.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1214SW	Radio racks. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1215SW	Modify instrument panel. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1216SW	Battery relocation. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1257SW	Seat arrangement and interior. Issued 2/17/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
t+1 MU-2B-30; T.C. A2PC	SA1266SW	Drawer type toilet and across the back baggage shelf. Issued 2/19/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1275SW	Modify air-conditioning system. Issued 3/12/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1295SW	Installation of stretch headliner. Issued 4/30/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1304SW	Portable two-place jump seat. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
MU-2B-30; T.C. A2PC	SA1309SW	Portable one-place jump seat. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
MU-2B-30; T.C. A2PC	SA1317SW	Revised battery installation. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1324SW	Bendix manual electric trim system. Issued 6/10/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-30; T.C. A2PC	SA1448SW	Divan and one-place jump seat. Issued 3/21/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-30; T.C. A2PC	SA1484SW	Hartman series-parallel battery relay. Issued 6/22/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA27GL	Installation of right side fuselage window at station 6335. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30, -35; T.C. A2PC	SA28GL	Installation of right side fuselage window at station 6897. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30, -35; T.C. A2PC	SA1180SW	Chair installation. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30, -35; T.C. A2PC	SA1419SW	Replace Gulton GE40A or CA5 Sonotone batteries with type 4076 saft batteries. Issued 1/12/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA1443SW	Modify pilot and copilot seats. Issued 3/9/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA1456SW	Installation of antennas. Issued 5/12/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA1470SW	Avionics support shelving. Issued 5/16/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35, -36; T.C. A2PC	SA60GL	Installation of two 25-gallon auxiliary fuel tanks in nose section of main landing gear wheel fairings. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-35; T.C. A2PC	SA947CE	Installation of KFC-300 automatic flight control system (integrated flight director and autopilot). Amended 1/14/76.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
MU-2B-35; T.C. A2PC	SA1352SW	Interior installation. Issued 8/20/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1511SW	PC-17 600 VA main inverter and PC-17 standby inverter. Issued 11/2/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1542SW	King KNC 610 area navigation computer. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1543SW	Sperry RA-220 radar altimeter. Issued 11/10/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1544SW	AVQ-55 weather radar. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1545SW	Sperry Stars IVB flight director. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1563SW	Bonzer radar altimeter TRN-71. Issued 12/21/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1616SW	Sperry AA-210 radar altimeter system. Issued 3/7/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1636SW	Collins ALT-50 radar altimeter system. Issued 3/6/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1641SW	Sperrry SPZ-200 autopilot and Stars IVC flight director system. Reissued 4/18/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1674SW	Smith's encoding altimeter and alerting system. Issued 6/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San ANgelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-35; T.C. A2PC	SA1693SW	Bendix M-4D autopilot system. Issued 6/28/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1708SW	ASB 125P/SAC-69 HF Comm. Issued 7/31/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1750SW	Battery temperature warning system. Issued 10/30/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1765SW	RDR-1200 weather radar. Issued 11/16/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 SAn Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1784SW	Flite phone III. Issued 1/24/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1785SW	Collins FDS-112 C/V flight director. Issued 1/28/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1804SW	Installation of 110 V outlet and wiring. Issued 2/7/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1849SW	Dual ASB 100A high frequency radios. Issued 3/14/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1851SW	Install -501 single encoding altimeter and alerter system. Issued 3/14/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1560SW	Avionics basic Collins package. Issued 3/21/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1561SW	AVQ-21 weather radar. Issued 12/20/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1941SW	Basic King gold crown avionics. Issued 12/13/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1944SW	Bendix RDR-140 weather radar. Issued 1/8/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1954SW	Jump seat. Issued 5/8/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA2246SW	Inverter relocation in forward equipment shelves and windshield anti-icing system panel changes. Issued 10/1/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA2269SW	King KRA 405 radar altimeter. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA2427SW	Optional VHF #2 Comm antenna. Issued 3/11/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36, -36A; T.C. A2PC	SA2489SW	Addition of baggage compartment in main landing gear wheel pods. Issued 8/17/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2309SW	Install Sperry TR114B transponder. Issued 6/17/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2399SW	Installation of Primus-40 weather radar. Issued 2/2/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2413SW	Install AiResearch TPE331-5-252M engines and Hartzell Propeller HC-B4TN-5DL/LT10282B-5.3R. Issued 2/18/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2414SW	Install Bendix RNS-3500 area NAV system. Issued 2/24/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MONOCOUPE OF PRINCETON, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
90 Series; T.C. 306	SA4-1024	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
90AF, 90AF-100, 90AL-115; T.C. A-306	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
90AF, 90AF-100, 90AL-115; T.C. A-306	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
90, -A, -F, AF-100, AL-115; T.C. 306	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
90, 90A, 90F, 90AF-100, 90AL-115; T.C. 306	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
90AL-115; T.C. 306	SA1071CE	Installation of Lycoming IO-320-E1A engine modified per STC SE7CE and Hartzell propeller HC-C2YL-4 with modification of existing fuel system by addition of header tank and associated fuel system changes. Issued January 1975.	CE	73069	Murlin Gene Smith 1231 Woodward Avenue Topeka, KS 66604

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MOONEY AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20 Series; T.C. 2A3	SA1-585	External electrical power receptacle.	EA	41500	Haynes Equipment Co., Inc. 62 Voorhis Lane Hackensack, NJ 07601
M20 Series; T.C. 2A3	SA1-615	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 75 School Street Pawtucket, RI 02860
M20 Series; T.C. 2A3	SA4-607	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA4-768	Fuel flow filter 30409A with element 1A0235 and adapter 2A0083.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
t+1 M20 Series; T.C. 2A3	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
M20 Series; T.C. 2A3	SA4-1022	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA4-1277	Installation of Firestone DFA-180 wheel assemblies with CFA-252 brake assemblies.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
•t) (					
M20 Series; T.C. 2A3	SA4-1426	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA4-1542	Ceconite 101 covering of rudder, elevators, ailerons, and flaps.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
M20 Series; T.C. 2A3	SA10SW	External power plug.	SW	05969	Aircraft Service Company P.O. Box 931 Municipal Airport Kerrville, TX 78028
M20 Series; T.C. 2A3	SA42SO	A-100 burglar alarm system.	SO	47654	Kapu Alarms, Inc. 7349 Southwest 41st Street Miami, FL 33101
M20 Series; T.C. 2A3	SA179SW	Nose wheel well doors 8367-1 and 8367-2.	SW	20115	Ralph E. Cash 1601 South Birch Avenue Broken Arrow, OK 74012
M20 Series; T.C. 2A3	SA241SO	Mooney dorsal fin 4175-51.	SO	12492	Atlanta Aero Service, Inc. DeKalb-Peachtree Airport Chamblee, GA 30005
M20 Series; T.C. 2A3	SA224SW	Automatic pilot AK117.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20 Series; T.C. 2A3	SA331SW	Electric landing gear system.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
M20 Series; T.C. 2A3	SA406WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA666NW	Installation of teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
M20 Series; T.C. 2A3	SA684WE	Autopilot B2D.	EA	17500	Brittain Industries, Inc. Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
M20 Series; T.C. 2A3	SA705SW	AK182 automatic aileron stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20 Series; T.C. 2A3	SA732SW	AK232 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20 Series; T.C. 2A3	SA739WE	Lateral stability augmentation system LSA-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA742WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA785WE	Flight control system B-6 including pitch assist PC-1, altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA841WE	Flight control system NAV-2 including navigation coupling and magnetic heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA848WE	"Air-Guard" anti-collision light.	WE	78485	Tibbetts Aircraft Radio Cable Airport Upland, CA 91786
M20 Series; T.C. 2A3	SA979WE	Lateral stability augmentation system LSA-2. Reissued October 1973.	SW	17940	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA990WE	NAV-2 flight control system including navigation coupling and magnetic heading lock.	EA	17500	Brittain Industries, Inc. Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
M20 Series; T.C. 2A3	SA991WE	Dynertial pitch assist PCA-1 with altitude hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA992WE	B-6 flight control system including PC-1 pitch assist, AH-1 altitude hold and NAV-2 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1172WE	Lateral stability augmentation system, LSA-4. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
M20 Series; T.C. 2A3	SA1198WE	NAV-2 flight control system or B-6 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1258SW	Porta-cool Model PC70 portable air conditioner. Issued 2/1/71.	SW	31358	Eagle, Inc. P.O. Box 13007 Fort Worth, TX 76118
t+1 M20 Series; T.C. 2A3	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M20 Series; T.C. 2A3	SA1489WE	Installation of Brittain Model B2C flight control system.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1550WE	Installation of Brittain LSA-4 flight control system.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1570WE	Installation of Brittain NAV-2 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1584WE	Installation of Brittain Model B-6 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1780WE	Installation of Brittain Industries LSA-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1785WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20 Series; T.C. 2A3	SA1786WE	Installation of Brittain Industries B-6 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1787WE	Installation of Brittain NAV-2B flight control. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20, M22 Series; T.C. 2A3, A6SW	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
Mark 20, 20A; T.C. 2A3	SA2666WE	Ceconite 102 material covering of rudder, elevators, ailerons and flaps. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M20, M20A; T.C. 2A3	SA2823SW	Reinforcement of vertical tail spar. Issued 7/31/78.	SW	64407	Harry L. Phillips Route 3, Box 420F Fort Worth, TX 76067
M20, M20A, M20B; T.C. 2A3	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amneded 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
M20 thru M20F; T.C. 2A3	SA600EA	Installation of electronic voltage alarm.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
M20, M20A thru M20E; T.C. 2A3	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
M20, M20A thru M20E; T.C. 2A3	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs: SA705SW, SA732SW.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M20, -A, -B, -C, -D, -E, -F, -G; T.C. 2A3	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 South Curtice Street Littleton, CO 80120
M20, M20A, M20B, M20C, -D, -E, -F; T.C. 2A3	SA1462WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	80120	Hanna-Aero Corporation 5222 South HOlly Street Littleton, CO 80120
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1932SW	Chrome plated disc brakes. Issued 11/27/74.	SW	29580	W.A. DeMaine Route 3, Box 62 Pine Bluff, AR 71601

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA3275WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell Mfrg. BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
M20A, M20B, M20C, M20D, M20G; T.C. 2A3	SA1156WE	Installation of Rajay turbosupercharged Lycoming O-360-A1A or -A1D engine. Amended 8/2/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA738EA	Installation of Whelen Engineering Co., Inc. Model HD-14 anti-collision strobe light system.	NE	85500	Whelen Engineering Co., Inc. 3 Winter Avenue Deep River, CT 06417
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light systems. Amended 10/4/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
M20B, C, D, E, F, G; T.C. 2A3	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
M20B, M20C, M20D, M20E, M20F, M20G, Normal Category; T.C. 2A3	SA3938WE	INstallation of flap gap seal. Issued 5/21/79.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA4023WE	Installation of flap gap fairings, flap hinge fairings, fuselage fairing at the tail cone, and a plexiglass landing light fairing. Amended 1/17/80.	WE	65015	John A. Porter 29 Walnut Via 501 E. Orangethorpe Avenue Anaheim, CA 92801
M20C, M20D; T.C. 2A3	SA77CE	Installation of McCauley 2D34C53/74E-0 or B2D34C53/74E-0 propeller with D-2809 spinner. Amended 5/24/68.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
M20C, M20D; T.C. 2A3	SA3859WE	Installation of an air/oil separator. Issued 3/12/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
Mooney M20C, M20D, M20E; T.C. 2A3	SA138WE	Installation of Grimes Model D-7080. Rotating beacon on vertical fin. Reissued 3/8/76.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
M20C, M20D, M20G; T.C. 2A3	SA375GL	Installation of Lycoming O-360-A1F6 or O-360-A1F6D in lieu of Lycoming O-360-A1D. Issued 11/26/79.	GL	90152	Louis M. Zeller, Jr. Route 1, Box 298-B Mount Vernon, IN 47620
M20C (S/N 20-0011 and on - 1974), (S/N 20-1147 and on - 1975), M20E (S/N 21-0025 and on - 1974), (S/N 21-1161 and on - 1975); T.C. 2A3	SA2993WE	Installation of Pathfinder autopilot systems and/or electric pitch trim systems. Issued 2/21/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C (S/N 20-0011 and on), M20E (S/N 21-0025 and on); T.C. 2A3	SA3222WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 11/15/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, E, F; T.C. 2A3	SA1938SW	Brittain LSA-6 lateral stability augmentation system (positive control). Issued 1/7/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20C, E, F, G; T.C. 2A3	SA2207SW	NAV-FLITE II and B-5 flight control systems. Issued 7/23/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20C, E, F, G; T.C. 2A3	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, E, F, G; T.C. 2A3	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, M20E, M20F; T.C. 2A3	SA2654WE	Installation of Pathfinder P2A autopilot system. Amended 4/14/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20E/Super 21; T.C. 2A3	SA999CE	Installation of ERC battery monitor. Issued March 1974.	CE	33229	Electronic Research Company P.O. Box 913 Shawnee Mission, KS 66201
M20E, M20F; T.C. 2A3	SA250GL	Installation of Lycoming IO-360-A1B6 engine in lieu of Lycoming IO-360-A1A engine using original installation hardware and components. No installation data are required. Issued 6/30/78.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA320GL	Installation of Hartzell Model HC-C2YK-1( )F/F7666A-4Q propeller in lieu of Hartzell Model HC-C2YK-1/7666-2 propeller using original installation hardware and components on aircraft previously modified in accordance with STC No. SA250GL. No installation data are required. Issued 6/28/79.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA1411WE	Installation of Rajay turbocharged Lycoming IO-360-A1A engine. Amended 5/9/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20E, M20F; T.C. 2A3	SA2968WE	Installation of manifold pressure gage/fuel flow meter (fuel pressure gage) in lieu of original gage/meter. Issued 1/29/75.	WE	65015	John A. Porter 29 Walnut Via 501 East Orangethorpe Avenue Anaheim, CA 92801
M20E, M20F, M20J; T.C. 2A3	SA3728WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
M20E, M20F, M20J; T.C. 2A3	SA4065WE	Installation of Silver Instruments fueltron 1G or IP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20F, S/N 22-1179 and up; M20J, S/N 24-0001 and up; T.C. 2A3	SA1212CE	Installation of King KFC 200 2 axis (3 optional) flight control system with KCS 55/55A compass and King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or third axis (yaw damper) only, or manual electric trim only. Amended 9/8/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20F, S/N 22-0013 and on (1974 models), S/N 22-1179 and on (1975 models); T.C. 2A3	SA2986WE	Installation of Pathfinder autopilot systems. Issued 2/19/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20F; T.C. 2A3	SA3047SW-D	Automatic flight system AK523 consisting of Century III autopilot with command automatic electronic pitch trim system and optional radio and glide slope couplers. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3048SW-D	Automatic flight system AK476 consisting of Century IIB autopilot with optional radio coupler. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3049SW-D	Automatic flight system AK475 consisting of Century I autopilot with optional omni tracker. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport MIneral Wells, TX 76067
M20F; T.C. 2A3	SA3064SW-D	MItchell command electric trim AK541. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3186WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20J; T.C. 2A3	SA1300CE	Installation of Edo-Aire propeller governor Model 34-826-014-11. Amended 1/9/78.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20J; T.C. 2A3	SA3307SW-D	Installation of Mitchell automatic flight system AK801 consisting of Century 41 autopilot or Model AK801FD consisting of Century 41 flight director autopilot. Issued 10/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3308SW-D	Installation of Mitchell automatic flight system AK802 consisting of Century 21 autopilot. Issued 10/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3555WE	Installation of Rajay turbocharged Lycoming IO-360-A3B6D and/or IO-360-A1D6D engines. Issued 12/30/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90801
M20J, M20K; T.C. 2A3	SA1525CE-D	Installation of King KNS 81 digital area navigation system. Issued 1/23/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20K; T.C. 2A3	SA378GL	Installation of Silver Instruments fueltron IG digital fuel flow meter. Reissued 1/3/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20K; T.C. 2A3	SA1464CE	Installation of KFC 200 two axis (three optional) flight control system. Issued 12/4/78.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M20K; T.C. 2A3	SA3325SW-D	Mitchell automatic flight system AK807 consisting of Century 41 autopilot flight director autopilot. Issued 1/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MOONEY MITE AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 803	SA1-353	Delco Remy generator 1101899 and associated plastic cowling.	EA	76100	George W. Strattner 6217 Hedgerow Drive Norfolk, VA 23501
18 Series; T.C. 803	SA3-483	Continental C85-12 engine. Revised April 1973.	CE	16786	W.P. Bilquist Rural Route #2, Box 113 Blue Springs, MO 64015
18 Series; T.C. 803	SA4-1106	Ceconite 101 covering of wings, ailerons, rudder, elevators, horizontal and vertical stabilizers.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
18 Series; T.C. 803	SA1044WE	Continental A75-8 65 hp engine and McCauley 1B90-CM/6753 propeller.	WE	03016	Aero-Spec. 240 North Dale Fullerton, CA 92631
18 Series; T.C. 803	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
18 Series; T.C. 803	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
18 Series; T.C. 803	SA1-615	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
18 Series; T.C. 803	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
18 Series; T.C. 803	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
18 Series; T.C. 803	SA1008WE	Poly-fiber covering of wings, fuselage, elevators, ailerons, stabilizers, and rudder. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
M-18C; T.C. A-803	SA71GL	Installation of P/N BA5110 filter assembly. Issued 12/29/77.	WE	17062	Brackett Aircraft Specialties Co. 4910 East Falcon Drive Mesa, AZ 85205
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA4-121[illegible]	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M-18C, -18C-55, -18L, -18LA;	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M-18C, M-18C55, M-18L, M-18LA; T.C. 803	SA2666WE	Ceconite 102 material covering of wings, ailerons, rudder, elevators, horizontal and vertical stabilizers. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MORANE-SAULNIER

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
760; T.C. 7A3	SA1-632	Radome 2017, P/N 2017X-R for 12-inch AVQ-50 antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
760, 760A, 760B; T.C. 7A3	SA2537WE	Installation of modified fuel system. Reissued 7/3/74.	WE	13800	Aviation Research Corporation 3535 West 5th Street Oxnard, CA 93030
760, 760A, 760B; T.C. 7A3	SA2554WE	Installation of anti-skid power brake system, new main landing gear legs and Goodyear wheels and brakes. Reissued 7/3/74.	WE	13800	Aviation Research Corporation 3535 West 5th Street Oxnard, CA 93030
760, 760A, 760B; T.C. 7A3	SA2751WE	Installation of rear seat assembly, P/N N76091. Reissued 7/3/74.	WE	13800	Aviation Research Corporation 3535 West 5th Street Oxnard, CA 93030

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MORRISEY AVIATION, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
2000C; T.C. 4A14	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
MOTH AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Moth 60-GM; ATC 197	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
60-GM; ATC 197	SA2666WE	Ceconite 102 material covering of complete airframe. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Moth 60-GM, -GMW; ATC 197	SA1008WE	Poly-fiber covering of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MULTITECH ENGINEERING CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D-16; T.C. 2A1	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
D-16, D-16A; T.C. 2A1	SA1-396	Navion retract link assembly, 143-33165-10.	EA	21100	Rudolph Chalow RD #1 Newfield, NJ 08344
D-16, D-16A; T.C. 2A1	SA4-920	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
D-16, D-16A; T.C. 2A1	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
D-16, D-16A; T.C. 2A1	SA4-1007	Installation of balance weights (Brittain Aircraft P/N 3010) on leading edge of Navion ailerons. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
D-16, D-16A; T.C. 2A1	SA4-1028	Installation of Brittain Industries 20-gallon wing tip tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
D-16, D-16A; T.C. 2A1	SA4-1165	Installation of Firestone Model DFA-180 or Bodell BMI-2000 wheel in lieu of Firestone 6C5 or Goodrich 613MD wheel (on nose gear). Amended 8/8/79.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
D-16, D-16A; T.C. 2A1	SA54WE	Installation of single-piece windshield. Reissued 8/1/73.	WE	19200	Cal Aero Industries, Inc. 3521 East Spring Street Long Beach, CA 90806
D-16, D-16A; T.C. 2A1	SA144SO	Control wheel.	SO	37066	Garcia Aviation Company 15801 Southwest 120 Avenue Miami, FL 33101
D-16, D-16A; T.C. 2A1	SA162EA	Navion retract link assembly, 145-34106.	EA	21100	Rudolph Chalow RD #1 Newfield, NJ 08344
D-16, D-16A; T.C. 2A1	SA200CE	Nose and main gear retracting link.	GL	85147	Western Michigan Repair Service 3315 East Milnam Avenue Kalamazoo, MI 49001
D-16, D-16A; T.C. 2A1	SA268SW	Automatic pilot AK116.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D-16, D-16A; T.C. 2A1	SA278SO	Main and nose landing gear retract links.	SO	36765	William E. Freeman 570 Milligan Drive Stone Mountain, GA 30083
D-16, D-16A; T.C. 2A1	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
D-16, D-16A; T.C. 2A1	SA335SW	Rework of main and nose gear retract links.	SW	05968	Aircraft Service 6625 Greenspan Dallas, TX 75221
D-16, D-16A; T.C. 2A1	SA353EA	Nose section modified.	NE	50450	John Liebolt 184 Fillow Street Norwalk, CT 06854

MULTITECH ENGINEERING CORP. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D-16, D-16A; T.C. 2A1	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, twin engine aircraft and single MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
D-16, D-16A; T.C. 2A1	SA605WE	B-4 flight control system including PC-1 pitch assit, AH-1 altitude hold and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D-16, D-16A; T.C. 2A1	SA644WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D-16, D-16A; T.C. 2A1	SA662WE	Hi-Lo sensitivity adaptor BI-400, and autopilot with NAV-1 navigation coupler and heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NARDI S.A.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
FN-333; T.C. 7A5	SA538CE	Extend spray rails 29 1/2" rearward.	GL	47754	Kenosha Aviation Service, Inc. Route 3, Box 543 Kenosha, WI 53140
FN-333; T.C. 7A5	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NAVAL AIRCRAFT FACTORY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Navy N3N-1, N3N-3; T.C. AR-2, 2-569	SA4-1568	Carburetor air intake cleaner on aircraft equipped with Pratt & Whitney R-985 series engines.	WE	73946	Spain-Air, Inc. P.O. Box 263 Dos Palos, CA 93620
Navy N3N-1, N3N-3; T.C. AR-2, 2-569	SA2477WE	Installation of automatic flagman model number 4. Issued 2/14/72.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362
Navy N3N-3; T.C. 2-569	SA4-346	Installation of modified B-13 engine mount.	RM	15300	Ed Beegles Aircraft Service Co. 921 - 22nd Street Greeley, CO 80631
Navy N3N-3; T.C. 2-569	SA4-779	Bonite covering on rudder.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
Navy N3N-3; T.C. 2-569	SA4-983	Quick-change clamping unit.	RM	22200	George Chisholm 317 - 13th Street Greeley, CO 80631
Navy N3N-3; T.C. 2-569	SA4-1210	Installation on Bonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
Navy N3N-3; T.C. 2-569	SA4-1232	Ceconite 101 covering of wings, ailerons, rudder, elevators and horizontal and vertical stabilizers.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
Navy N3N-3; T.C. 2-569	SA4-1313	Hartzell HA-B3230-1/10160-6 ground adjustable propeller on aircraft with Pratt & Whitney R985 series engines.	WE	85124	West Coast Propeller Company 1101 Chestnut Street Burbank, CA 91500
Navy N3N-3; T.C. 2-569	SA1008WE	Installation of poly-fiber covering material of lower wings, ailerons, horizontal stabilizer, elevator, rudder. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
Navy N3N-3; T.C. 2-569	SA1135CE	Installation of center float and two outrigger floats. Issued May 1975.	CE	61554	Fred Miedner and Thomas Anlers No. 1 Westbury Drive St. Charles, MO 63301
Navy N3N-3; T.C. 2-569	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Navy N3N-3; T.C. 2-569	SA1515WE	Installation of Hamilton Standard 3D40/6101A-20 propeller.	WE	85125	Western Aircraft Sales P.O. Box 753 Long Beach, CA 90801
Navy N3N-3; [illegible]	SA2666WE	Ceconite 102 material covering of [illegible] horizontal and vertical stabilizers. 4/19/78	[illegible]	[illegible]	[illegible] Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NAVION RANGEMASTER AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Navion Series; T.C. 782	SA1-88	Elimination of carburetor heater muff on aircraft with downdraft cooling systm and Bendix PS5BD carburetor.	EA	21100	Rudolph Chalow RD #1 Newfield, NJ 08344
Navion Series; T.C. 782	SA1-396	Navion retract links 143-33165 and 143-33165-10 modified.	EA	21100	Rudolph Chalow RD #1 Newfield, NJ 08344
Navion Series; T.C. 782	SA1-575	External electrical power receptacle.	EA	41500	Haynes Equipment Co., Inc. 62 Voorhis Lane Hackensack, NJ 07601
Navion Series; T.C. 782	SA1-635	HC-A2x20-4/8433 propeller.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
Navion Series; T.C. 782	SA3-31	Alternate repair parts for bulkhead.	GL	42860	Howard Aviation, Inc. P.O. Box 1287 Peoria, IL 61601
Navion Series; T.C. 782	SA3-60	Bushin in attachment plate hole of Palo Alto it alteration of angle of incidence of horizontal stabilizer.	GL	53580	F.C. McLaughlin P.O. Box 1287 Peoria, IL 61601
Navion Series; T.C. 782	SA3-176	Electric remote compass.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
Navion Series; T.C. 782	SA3-191	Arcon B automatic rudder control. Amended 4/26/66	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
Navion Series; T.C. 782	SA3-492	Window and windshield.	GL	60250	Mt. Hawley Aviation, Inc. Municipal Airport Peoria, IL 61601
Navion Series; T.C. 782	SA3-532	Fabriction and installation of rotating beacon brackets on aircraft with Grimes D-7080-1 light.	GL	60250	Mt. Hawley Aviation, INC. Municipal airport Peoria, IL 61601
Navion Series; T.C. 782	SA4-35	Wing root-fuselage fiberglass contoured fairings at leading edge of wing, and aluminum fairings contoured to existing fillet at inboard end of wing flaps extending aft to station 226.	WE	10235	American Navion Society P.O. Box 2503 Airport STATION Oakland, CA 94614
Navion Series; T.C. 782	SA4-118	Hartzell HC-12X20-7C/8433-0 propeller including governor kit.	WE	30450	Robert Douthit P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA4-146	Globe gyro-stabilizer.	RM	50258	G.J. Lee, Jr. c/o Boulder Aircraft Boulder, CO 80302
Navion Series; T.C. 782	SA4-229	Retractable step and handle.	WE	30450	Robert Douthit P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA4-241	Chnge in incidence angle of horizontal stabilizer for Symons Engineering kit.	WE	77262	M.W. Symons Engineering Company 490 Nort Prairie Avenue Hawthorne, CA 90250
Navion Series; T.C. 782	SA4-313	Toe brake kit and parking brake.	WE	30450	Robert Douthit P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA4-363	Autopilot and optional "add-on" coupler BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA4-685	Aerofilter 30409A witn element 1A0235.	WE	86625	Winslow Aerofilter Crporation 4069 Hollis Street Oakland, CA 94608
Navion Series; T.C. 782	SA4-915	Installation of Brittain Mark II 20-gallon wing tip tanks (P/N 2009). Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank & Supply Star Route, Box 12 Oro Grande, CA 92368

NAVION RANGEMASTER AIRCRAFT CORP. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Navion Series; T.C. 782	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
Navion Series; T.C. 782	SA4-1007	Installation of balance weights (Brittain Aircraft P/N 3010) on leading edge of Navion ailerons. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank & Supply Star Route, Box 12 Oro Grande, CA 92368
Navion Series; T.C. 782	SA4-1432	Fiberglass vertical stabilizer tip assembly ANS 0001 and Grimes rotating beacon G-8400A-8-12 or D-7080-1-12.	WE	10235	American Navion Society P.O. Box 2503 Airport Station Oakland, CA 94614
Navion Series; T.C. 782	SA4-1483	Fiberglass vertical fin tip and Grimes rotating beacon F-7080-1-12 or G-8400A-8-12.	WE	30450	Robert Doutnit P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA4-1626	Fiberglass nose wheel streamlined fairing.	WE	30450	Robert Douthit & J.H. Ellis P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA36CE	Zip tip wing tips.	GL	79954	Tuscola Flying Service Route 2 Tuscola, IL 61953
Navion Series; T.C. 782	SA143SO	Control wheel.	SO	37086	Garcia Aviation Company 15801 Southwest 120th Avenue Miami, FL 33101
Navion Series; T.C. 782	SA162EA	Navion retract link assembly 145-34106.	EA	21100	Rudolph Chalow RD #1 Newfield, NJ 08344
Navion Series; T.C. 782	SA179WE	Main landing gear retract link assembly ANS 0003.	WE	10235	American Navion Society P.O. Box 2503 Airport Station Oakland, CA 94614
Navion Series; T.C. 782	SA200CE	Nose and main gear retracting link replacement.	GL	85147	Western Michigan Repair Service 3315 East Milham Avenue Kalamazoo, MI 49001
Navion Series; T.C. 782	SA249EA	Airborne mechanisms dry vacuum pump and regulator.	EA	85600	Edward J. White 207 Stephen Drive Cinnaminson, NJ 08077
Navion Series; T.C. 782	SA252WE	Nose landing gear retract link assembly ANS 0004.	WE	10235	American Navion Society P.O. Box 2503 Airport Station Oakland, CA 94614
Navion Series; T.C. 762	SA268SW	Automatic pilot AK116.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion Series; T.C. 782	SA278SO	Main and nose landing gear retract links.	SO	36765	William E. Freeman 570 Milligan Drive Stone Mountain, GA 30083
Navion Series; T.C. 782	SA292CE	Nose gear shimy damper.	GL	50370	Libersky Aero Service Municipal Airport Worthington, MN 56187
Navion Series; T.C. 782	SA298SW	Autopilot AF-512A or AF-512B.	EA	05950	Aircraft Radio Corporation Rockaway Valley Road P.O. Box 150 Boonton, NJ 07005
Navion Series; T.C. 782	SA299SW	Autopilot AF-510A.	EA	05950	Aircraft Radio Corporation Rockaway Valley Road P.O. Box 150 Boonton, NJ 07005
Navion Series; T.C. 782	SA334SW	Alternator.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216
Navion Series; T.C. 782	SA374WE	Modified carburetor air intake system.	WE	37875	Donald G. Gifford P.O. Box 474 Lodi, CA 95240
Navion Series; T.C. 782	SA543SW	Turbosupercharger.	SW	09250	Alcor Aviation, Inc. 2905 Bandera Road San Antonio, TX 78216
Navion Series; T.C. 782	SA570WE	Exhaust system. 0	WE	74927	Ted Stanke Municipal Airport Banning, CA 92220

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Navion Series; T.C. 782	SA604WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold and NAV-1 navigation. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA644WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA750SW	Tip tank fairings and drain cover.	SW	70000	Sagefield Aircraft Service 1433 Northwest 7th Street Grand Prairie, TX 75050
Navion Series; T.C. 782	SA751SW	Nose gear doors and fixed main gear wheel fairings.	SW	70000	Sagefield Aircraft Service 1433 Northwest 7th Street Grand Prairie, TX 75050
Navion Series; T.C. 782	SA752WE	Lycoming GO-480-BID engine and Hartzell HC-82X20/9333C-3 propeller.	WE	51800	Bart N. Locanthi 2180 Pinecrest Drive Altadena, CA 91001
Navion Series; T.C. 782	SA758WE	Navion main landing gear wheel and axle modification.	WE	61990	H. Sanford Osborne Star Route, Box 12 Oro Grande, CA 92368
Navion Series; T.C. 782	SA769WE	Lear Romec fuel pump R6-15980 on Continental E-185-3 engine.	WE	87805	Wright Brothers, Inc. 401 Newnall Street San Jose, CA 95110
Navion Series; T.C. 782	SA878WE	N-2 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
Navion Series; T.C. 782	SA1488WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA1512WE	Installation of exhaust gas temperature monitoring system, Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Navion Series; T.C. 782	SA1579WE	Installation of Brittain Industries B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA1678WE	Installation of Brittain B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tuls, OK 74151
Navion Series; T.C. 782	SA2120WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion, Navion A, B, D; T.C. 782	SA4-1165	Installation of Firestone Model DFA-180 or Bodell BMI-2000 wheel in lieu of Firestone 6C5 or Goodrich 613MD wheel on nose gear. Amended 8/8/79.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
Navion (L-17A), Navion A, B, D, E, F, G, H; T.C. A-782	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
Navion (L-17A), Navion A (L-17B), (L-17C); T.C. A-782	SA3935WE	Installation of an air/oil separator. Issued 5/15/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
Navion, Navion A, B; T.C. 782	SA4022WE	Installation of toe brakes and revised rudder pedals at pilot station. Issued 8/30/79.	WE	50259	Eugene Leedy P.O. Box 816 Benning, CA 92220
Navion A; T.C. A-782	SA253GL	Installation of a Continental E-225-4 engine modified in accordance with STC SE23SW, in lieu of a Continental E-225-4 which was installed. Issued 7/21/78.	GL	37079	Montie Gainey 1407 South Kitley Avenue Indianapolis, IN 46203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Navion A; T.C. A782	SA695CE	Install Frantz oil filter.	GL	70360	Donald R. Schmidt Schmidt Aero Service Worthington, MN 56187
Navion A; T.C. A782	SA1246WE	Alternator kit 6555-2 and 6555-2-2, "Jasco". Amended 10/28/76.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
Navion A; T.C. A782	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
Navion A; T.C. A782	SA2946WE	Istallation of new design cabin air valve. Issued 10/25/74.	WE	50250	Eugene Leedy 1011 DeGarmo Street San Fernando, CA 91340
Navion A; T.C. A782	SA3077SW-D	Mitchell auto flight system AK553 consisting of Century I autopilot with omni tracker. Issued 10/20/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion A, B; T.C. 782	SA1124SW	Modified wing tips.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
Navion A, B, C, D, E, F, G, H; T.C. A-782	SA54WE	Installation of single-piece windshield and side windows. Reissued 8/1/73.	WE	19200	Cal Aero Industries, Inc. 3521 East Spring Street Long Beach, CA 90806
Navion A, B, D, E, F, G (A & B with optional engine); T.C. A-782	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
Navion A, B, D, E, F, G; T.C. A-782	SA1582WE	Installation of control position indicator (CPI) system. Reissued 3/12/70.	NW	80685	United Control Corporation Overlake Industrial Park Redmond, WA 98052
Navion A, B, D, E, F, G, H; T.C. A-782	SA36GL	Install wheel and brake conversion kit, P/N 199-52. Reissued 7/23/74.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
Navion A, B, D, E, F, G, H; T.C. A-782	SA46GL	Install wheel and brake conversion kit, P/N 199-5A. Reissued 7/23/74.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Avon Center ROAD Avon, OH 44011
Navion A, B, D, E, F, G, H; T.C. A-782	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
Navion A, D, E, F, G; T.C. A-782	SA589WE	Installation of full flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
Navion A, D, E, F, G, H; T.C. A-782	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly treet Littleton, CO 80120
Navion A, B, D, E, F, G, H; T.C. A-782	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot. Amended 5/9/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Road Torrance, CA 90505
Navion A, B, D, E, F, G, H; T.C. A-782	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot. Amended 5/9/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Road Torrance, CA 90505
Navion A,B, D, E, F, G. H normal and utility category; T.C. A-782	SA3638WE	Installation of new air induction system with a filter on the alternate air source. Issued 5/3/78.	WE	30450	Robert Douthitt P.O. Box 795 El Centro, CA 92243
Navion A, B, D, E, F, G, H; T.C. A-782	SA3639WE	Installation of warning light intended to prevent inadvertent operation of the aircraft on the aircraft on the tip tank fuel system while in the landing or take-off configuration, i.e., gear down. Issued 5/3/78.	WE	30450	Robert Douthitt P.O. Box 795 El Centro, CA 92243
Navion A, B, D, E, G, H; T.C. A-782	SA3640WE	Installation of flap lower close out strip. Issued 5/3/78.	WE	30450	Robert Douthitt P.O. Box 795 El Centro, CA 92243

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Navion A, B, D, E, F, G, H; T.C. A-782	SA3786WE	. Installation of tubular engine mount, cowling cooling baffles, air induction system and cowl flap mechanism. Issued 12/4/78.	WE	37081	GAMA Enterprises P.O. Box 55 Fawnskin, CA 92333
Navion A, B, C, D, E, F, G, H; T.C. A-782	SA3936WE	Installation of an air/oil separator. Issued 6/1/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
Navion B; T.C. A-782	SA4-1121	Increase in allowable gross weight from 2850 to 3100 pounds per STC SA4-915 when equipped with 20 gallon wing-tip tanks (Brittain Aircraft P/N 1000). Reissued 2/2/71.	WE	62000	H. S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
Navion B; T.C. A-782	SA308EA	Istallation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Navion B; T.C. A-782	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Navion B; T.C. A-782	SA3447WE	Installation of steel engine mounting brackets. Issued 7/1/77.	WE	50250	Eugene Leedy P.O. Box 816 Banning, CA 92220
Navion G, H; T.C. A-782	SA2654WE	Installation of Pathfinder Model P2A autopilot. Amended 5/31/74.	WE	12380	Astronautics Crp. of America 2416 Amsler Road Torrance, CA 90505
Navion G, H; T.C. A-782	SA2961WE	Installation of Pathfinder autopilot systems and/or electric pitch trim systems. Issued 2/24/75.	WE	12380	Astronautics Corp. of America 2416 Asler Road Torrance, CA 90505
Navion G, H; T.C. A782	SA3224SW-D	Mitchell automatic flight system AK701 consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion G, H; T.C. A782	SA3225SW-D	Mitchell automatic flight system AK704 consisting of Century IIB autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion H; T.C. A-782	SA1190CE	Installation of King KFC 200 flight control system (2 axis). Issued April 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NELSON AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BB-1; GTC 19	SG4-1240	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Wats Drive Bkersfield, CA 93307

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NIHON AEROPLANE MANUFACTURING COMPANY, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
YS-11, -11A: T.C. A1PC	ST424SO	Installation of replacement radome assembly.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11, -11A; T.C. A1PC	SA863EA	Incorporation of Chromalloy Electronics Division ESL-1 or ESL-6 emergency slide lighting system. Reissued 3/6/73.	SO	22225	Chromalloy Electronics Div. of Chromalloy American Corp. 3901 North 29th Avenue Hollywood, FL 33020
YS-11, -11A; T.C. A1PC	SA2728WE	Incorporation of Holcombe Industries Hi-Lite system (P/N 50-1001) for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
YS-11A Series; T.C. A1PC	SA393SO	Install Goodyear 9540512 wheels in place of Goodyear 9543138 wheels.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11-A200; T.C. A1PC	SA1949WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach,CA 90807
YS-11A-200, -300, -500, -600; T.C. A1PC	ST487SO	Installation of P.P.G. manufactured main windshields, P/Ns 5613-00001 (L/H) and 5613-00002 (R/H) and Barber Colman P/N HYLZ 8882 temperture controller. Amended 2/22/74.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500; T.C. A1PC	ST486SO	Installation of external APU control panel. Amended 2/16/72.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500; T.C. A1PC	ST866SO	Installation of Bendix ground proximity warning system. Amended 11/20/75.	SO	64500	Piedmont Aviaton, Inc. P.O. Box 2720 Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A, -500; T.C. A1PC	SA2910SW	Unpressurized cargo door in rear left hand portion of fuselage. Amended 5/9/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A Series 500; T.C. A1PC	SA3873WE	Installation of bleed air heating system. Amended 8/17/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A-600; T.C. A1PC	SA3047WE	Installation of provisions only for ground proximity warning system. Issued 5/28/75.	WE	87450	World Airways, Inc. Maintenance & Engineering Center Oakland International Airport Oakland, CA 94614
YS-11A-626; T.C. A1PC	SA78NW	Cabin modification. Issued October 1973.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MEYERS INDUSTRIES, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
OTW, OTW145, OTW-KR, OTW160; T.C. A736	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
OTW-145; T.C. A736	SA742CE	Install Warner Super Scarab 165 hp engine and increase gross weight to 1910 pounds.	GL	77750	Tecumseh Aviation Tecumseh, MI 49286
MAC-125C, MAC-145; T.C. 3A1	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
MAC-125C, MAC-145; T.C. 3A1	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
MAC-125C, MAC-145; T.C. 3A1	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
MAC-145; T.C. 3A1	SA269GL	Installation of Continental O-300-A engine in lieu of Continental C145-2 using original installation hardware and components. No installation data are required. Issued 9/21/78.	GL	41190	Ralph E. Haven Route No. 1 Sherwood, OH 43556

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MITCHELL TRIMOTOR AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
101 (Longren L-13); T.C. 4A15	SA4-980	Oil tank.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
101; T.C. 4A15	SA66SO	Removal of forward right-hand and aft left and right-hand cabin doors or any combination thereof.	SO	02313	Aeroist's International, Inc. 755 West 43rd Place Hialeah, FL 33010

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MITSUBISHI AIRCRAFT INTERNATIONAL, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B, -2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, -40, -60; T.C. A10SW	SA1042SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638T series lead-acid type batteries. Issued 1/15/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Atlanta, GA 30339
MU-2B, MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A10SW	SA1460CE	Installation of microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
MU-2B, -2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, -40, -60; T.C. A10SW	SA3524WE	Installation of vertical tail flood lights on horizontal stabilizer. Amended 4/13/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
MU-2B-25, -2B-26, -2B-35, -2B-36; T.C. A10SW	SA304GL	Installation of Hartzell HC-B3TN-5C/T10178B-13Q propellers in lieu of HC-B3TN-5C/T10178B-11 or 11R propellers using original installation hardware and components. No installation data are required. Amended 12/29/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-36A, -2B-60; T.C. A10SW	SA215GL	Installation of two 25-gallon auxiliary fuel tanks in nose section of main landing gear wheel fairings. Amended 12/26/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62707
MU-2B-36A; T.C. A10SW	SA216GL	Installation of right side fuselage window at station 6335. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-36A; T.C. A10SW	SA217GL	Installation of right side fuselage window at station 6897. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MITSUBISHI HEAVY INDUSTRIES, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B; T.C. A2PC	SA588EA	Installation of Norton replacement nose cap radome, P/N 3077X. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Division P.O. Box 350 Akron, OH 44309
MU-2B; T.C. A2PC	SA595EA	Installation of replacement radome, P/N 3077X.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company Aero Products Operations P.O. Box 1187 Akron, OH 44309
MU-2B; T.C. A2PC	SA633SW	Heading selector and Omni/ILS coupler for Minneapolis-Honeywell H-14 automatic pilot.	SW	60152	Mooney Southwest, Inc. P.O. Box 6127 Midland, TX 79701
MU-2B; T.C. A2PC	SA726SW	Heading select, pitch trim and VOR/ILS coupling modes to Honeywell H-14 autopilot.	SW	60152	Mooney Southwest, Inc. P.O. Box 6127 Midland, TX 79701
MU-2B; T.C. A2PC	SA747CE	Installation of AiResearch TPE331-1-151A engines. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B; T.C. A2PC	SA907SW	AiResearch TPE331-25AA engines.	SW	60150	Mooney Aircraft, Inc. Route 1, Box 544 San Angelo, TX 76901
MU-2B; T.C. A2PC	SA1310WE	M-4C automatic flight control system.	SC	15475	The Bendix Corporation P.O. Box 23430 Fort Lauderdale, FL 33309
MU-2B, MU-2B-10, MU-2B-15, MU-2B-20; T.C. A2PC	SA996SW	Move air conditioning unit 20-inches aft and enlarge luggage compartment.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, MU-2B-10, MU-2B-15, MU-2B-20; T.C. A2PC	SA1029SW	Additional pitot system.	SE	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, MU-2B-10, MU-1B-15, MU-2B-20; T.C. A2PC	SA1045SW	Two-place side facing seat.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
t+1 MU-2B, MU-2B-10, MU-2B-15, MU-2B-20; T.C. A2PC	SA1048SW	Replacement of Mitsubishi seats.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35; T.C. A2PC	SA582SO	Installation of Bendix RNS-3400 area navigation system. Amended 2/12/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 3331
MU-2B, MU-2B-10, -15, -20, -30; T.C. A2PC	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
MU-2B, -10, -15, -20, -25, -30, -35; T.C. A2PC	SA1411SW	Emergency locator transmitter. Issued 12/30/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA39GL	Installation of tip tank lights. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA98GL	Installation of engine ignition cut-out override system. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B, 2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA880SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1587SW	Aerosonic altimeter P/N A35-MA-10L1 to replace McCleod altimeter. Issued 1/5/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA3490WE	Installation of fuel boost pump. Issued 9/23/77.	WE	26725	Hydro-Aire Division of the Crane Company 3000 Winona Avenue P.O. Box 7722 Burbank, CA 91510
MU-2B, MU-2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, 40, 60; T.C. A2PC	SA3524WE	Installation of vertical tail flood lights on horizontal stabilizer. Amended 4/13/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA32GL	Installation of oil filler access door. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA38GL	Installation of electrically heated glass windshield on pilot's side of aircraft. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA43GL	Installation of wing tip tank fuel dumping system (93 gallon tip tanks only). Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25,, -26, -30, -35, -36; T.C. A2PC	SA58GL	Modification of forward windshield center divider. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -30, -35; T.C. A2PC	SA68GL	Installation of engine fuel drain return line. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1506SW	Alternate oil pressure transmitter. Issued 1/5/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1729SW	Adding weight of 60 pounds for ramp operation. Issued 9/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1857SW	B.F. Goodrich type 258 de-ice boots. Issued 3/19/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-10,-20, -25, -26, -30, -35, -36; T.C. A2PC	SA2266SW	Fabrication and installation of wing panel flap actuator access. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-15, -20; T.C. A2PC	SA955SW	M4C automatic flight control.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-15, -20; T.C. A2PC	SA1354SW	Bendix manual electric trim system. Issued 7/27/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-15, -20; T.C. A2PC	SA1874SW	Battery temperature warning system. Issued 4/24/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20; T.C. A2PC	SA291GL	Installation of auxiliary fuel tank in aft baggage compartment. Issued 1/12/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62707
MU-2B-20; T.C. A2PC	SA1313SW	Interior installation. Issued 5/21/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20; T.C. A2PC	SA1402SW	Hartman series parallel battery relay. Issued 6/14/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25; T.C. A2PC	SA1408SW	Avionics support shelving. Issued 7/6/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25; T.C. A2PC	SA1762SW	Single PC-17 inverter. Issued 11/9/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25; T.C. A2PC	SA1775SW	Flight system AK391 and AK391FD consisting of Century IV autopilot and Century IV autopilot flight director with command electric trim and yaw damper with rudder trim. Issued 12/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-20, -25, -26; T.C. A2PC	SA5618O	Installation of Bendix M-4D automatic flight control system including optional yaw trim, optional manual electric pitch trim and optional flight director system. Amended 1/24/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-20, -25, -26, -30, -35, -36; T.C. A2PC	SA2238SW	Tip tanks lights. Issued 6/8/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35; T.C. A2PC	SA1489SW	Antennas. Issued 7/6/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35; T.C. A2PC	SA1805SW	Foxboro fuel flow signal conditioning unit PC-620. Issued 2/7/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35, -36; T.C. A2PC	SA1940SW	Goulton GB40 cell batteries. Issued 12/12/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -35; T.C. A2PC	SA1776SW	Lear Siegler starter generator, P/N 23046-007M. Issued 1/4/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San angelo, TX 76901
MU-2B-20, -25, -35; T.C. A2PC	SA1814SW	Dual baro scale altimeter. Issued March 1974.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -30; T.C. A2PC	SA161GL	Install Garrett AiResearch TPE331-6-252M engines. Amended 6/15/77.	GL	07503	AiResearch Capitol Aviation Co. Capital Airport Springfield, IL 62705
MU-2B-20, -30; T.C. A2PC	SA1316SW	Series/parallel selector switch for battery start selection. Issued 5/26/71.	SW	60073	Mitsubishi Aircraft Int'l, INc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -30; T.C. A2PC	SA1547SW	Dual PC-17 static inverters. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1465SW	Interior. Issued 8/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1541SW	King basic avionics package. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1546SW	Basic King avionics package. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1548SW	Area NAV KCN 610. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1549SW	AVQ-55 weather radar. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1564SW	Collins basic avionics package. Issued 12/15/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1628SW	RCA AVQ-21 weather radar. Issued 3/15/73.	SO	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1646SW	Sunair ASB-100 HF system. Issued 4/27/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1647SW	Sperry stars IVB flight director. Issued 4/27/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1710SW	Bendix RDR-1200 weathervision system. Issued 8/2/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1711SW	RCA AVQ-47 weather radar. Issued 8/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1733SW	Battery temperature warning system. Issued 9/21/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

MITSUBISHI HEAVY INDUSTRIES, LTD. 4

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-25; T.C. A2PC	SA1752SW	Sperry AA-20 radio altimeter. Issued 10/29/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1817SW	Collins ALT-50 radar altimeter. Issued 3/6/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1859SW	RDR-100 weather radar. Issued 3/26/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1793SW	Install Collins FDS-112 C/V flight director. Issued 11/20/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1818SW	Aerosonics encoding altimeter and alerter. Issued 9/13/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1925SW	Basic King gold crown avionics. Issued 2/14/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA2268SW	Installation of #2 VHF comm antenna. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -2B-26, -2B-35, -2B-36; T.C. A10SW	SA304GL	Installation of Hartzell HC-B3TN-5C/T10178B-13Q propellers in lieu of HC-B3TN-5C/T10178B-11 or 11R propellers using original installation hardwarde and components. No installation data are required. Issued 5/7/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1882SW	Chart holder. Issued December 1974.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1912SW	Instrument panel modification. Issued 9/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1914SW	Cooling air inlet screen. Issued 10/15/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1928SW	Sperry GH-14 flight director. Issued 1/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1929SW	United Instruments encoding altimeter. Issued 1/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1964SW	Cooling air inlet modification. Issued 9/25/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1990SW	Pressure relief overboard vent line and restrictor fitting to EPA fuel purge system. Issued 5/21/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2233SW	Rewiring of auto-manual air conditioning switch. Issued 8/15/75.	SW	60073	Mitsubishi Aircraft International P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2263SW	Modification of ECS mixing chamber. Issued 10/9/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2487SW	Outside air temperature indicator. Issued 8/6/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A10SW	SA3489WE	Installation of fuel boost pump. Issued 9/23/77.	WE	26725	Hydro-Aire Division of the Crane Company 3000 Winona Avenue P.O. Box 7722 Burbank, CA 91510
MU-2B-25, -35; T.C. A2PC	SA1614SW	IDC 570-24929-002 encoding altimeter; or Smith's WL-350 AM/MS-1(-2) encoding altimeter. Issued 6/6/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1615SW	Encoding altimeter/alerting system. Issued 3/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-25, -35; T.C. A2PC	SA1627SW	Collins FDS-112B flight director system. Issued 5/25/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
•t•1 MU-2B-25, -35; T.C. A2PC	SA1703SW	5V light source. Issued 7/18/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1712SW	Oil pressure indicator. Issued 8/10/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1732SW	Kratos 124.102 torque indicator. Issued 9/19/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1736SW	Ametek oil pressure transmitter, P/N 935A-5002. Issued 10/3/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1751SW	Shoulder harness. Issued 10/30/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1764SW	Smith's 1400 encoding altimeter-alerter. Issued 11/16/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1778SW	R.C. Allen gyro. Issued 1/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1779SW	Kollsman dual Baro scale altimeter. Issued 1/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1781SW	Revised ground and air starting procedures with bleed air heat to orifice in fuel control. Issued 1/17/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1816SW	King flight phone. Issued 3/26/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1872SW	Hamilton Standard temperature control system. Issued 4/22/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2315SW	Dual FDS-112B flight director system. Issued 5/21/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2316SW	ONTRAC II VLF system. Issued 5/14/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2317SW	Install IDC RAD/BAR encoding altimeter with altitude alerting. Issued 5/21/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2342WE	Installation of Sperry AA-100 radar altimeter. Issued 9/2/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2208SW	Continuous ignition system. Issued 7/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2247SW	Oxygen cylinder, P/N 6350 A20 00B. Issued 10/1/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2274SW	Heated windshield. Issued 3/18/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2295SW	Install alternate interstage turbine temperature indicator, P/N 935A-6012.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2314SW	Digital clock. Issued 5/20/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2343SW	Alternate aileron trim actuator. Issued 8/5/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-26A, -36A; T.C. A10SW	SA218GL	Installation of oil filler access door. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-26A, -36A; T.C. A10SW	SA219GL	Installation of tip tank lights. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-26A, -36A; T.C. A10SW	SA220GL	Modification of forward windshield center divider. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-26A, -36A, -40, -60; T.C. A10SW	SA214GL	Installation of wing tip tank fuel dumping system. Amended 5/29/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30; T.C. A2PC	SA115GL	Install Garrett AiResearch TPE 331-6-251M (P/N 896160-1) engines. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30; T.C. A2PC	SA1069SW	Mooney AB1001, TSO C-39 seats.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1085SW	Air conditioning system.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1146SW	Interior installation. Issued 5/15/70.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1198SW	11-place interior. Issued 9/30/70.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1214SW	Radio racks. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1215SW	Modify instrument panel. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1216SW	Battery relocation. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1257SW	Seat arrangement and interior. Issued 2/17/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
t+1 MU-2B-30; T.C. A2PC	SA1266SW	Drawer type toilet and across the back baggage shelf. Issued 2/19/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1275SW	Modify air-conditioning system. Issued 3/12/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1295SW	Installation of stretch headliner. Issued 4/30/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1304SW	Portable two-place jump seat. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
MU-2B-30; T.C. A2PC	SA1309SW	Portable one-place jump seat. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
MU-2B-30; T.C. A2PC	SA1317SW	Revised battery installation. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1324SW	Bendix manual electric trim system. Issued 6/10/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-30; T.C. A2PC	SA1448SW	Divan and one-place jump seat. Issued 3/21/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-30; T.C. A2PC	SA1484SW	Hartman series-parallel battery relay. Issued 6/22/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA27GL	Installation of right side fuselage window at station 6335. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30, -35; T.C. A2PC	SA28GL	Installation of right side fuselage window at station 6897. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30, -35; T.C. A2PC	SA1180SW	Chair installation. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30, -35; T.C. A2PC	SA1419SW	Replace Gulton GE40A or CA5 Sonotone batteries with type 4076 saft batteries. Issued 1/12/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA1443SW	Modify pilot and copilot seats. Issued 3/9/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA1456SW	Installation of antennas. Issued 5/12/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA1470SW	Avionics support shelving. Issued 5/16/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35, -36; T.C. A2PC	SA60GL	Installation of two 25-gallon auxiliary fuel tanks in nose section of main landing gear wheel fairings. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-35; T.C. A2PC	SA947CE	Installation of KFC-300 automatic flight control system (integrated flight director and autopilot). Amended 1/14/76.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
MU-2B-35; T.C. A2PC	SA1352SW	Interior installation. Issued 8/20/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1511SW	PC-17 600 VA main inverter and PC-17 standby inverter. Issued 11/2/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1542SW	King KNC 610 area navigation computer. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1543SW	Sperry RA-220 radar altimeter. Issued 11/10/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1544SW	AVQ-55 weather radar. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1545SW	Sperry Stars IVB flight director. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1563SW	Bonzer radar altimeter TRN-71. Issued 12/21/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1616SW	Sperry AA-210 radar altimeter system. Issued 3/7/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1636SW	Collins ALT-50 radar altimeter system. Issued 3/6/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1641SW	Sperrry SPZ-200 autopilot and Stars IVC flight director system. Reissued 4/18/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1674SW	Smith's encoding altimeter and alerting system. Issued 6/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San ANgelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-35; T.C. A2PC	SA1693SW	Bendix M-4D autopilot system. Issued 6/28/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1708SW	ASB 125P/SAC-69 HF Comm. Issued 7/31/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1750SW	Battery temperature warning system. Issued 10/30/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1765SW	RDR-1200 weather radar. Issued 11/16/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 SAn Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1784SW	Flite phone III. Issued 1/24/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1785SW	Collins FDS-112 C/V flight director. Issued 1/28/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1804SW	Installation of 110 V outlet and wiring. Issued 2/[illegible]/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1849SW	Dual ASB 100A high frequency radios. Issued 3/14/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1851SW	Install -501 single encoding altimeter and alerter system. Issued 3/14/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1560SW	Avionics basic Collins package. Issued 3/21/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1561SW	AVQ-21 weather radar. Issued 12/20/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1941SW	Basic King gold crown avionics. Issued 12/13/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1944SW	Bendix RDR-140 weather radar. Issued 1/8/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1954SW	Jump seat. Issued 5/8/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA2246SW	Inverter relocation in forward equipment shelves and windshield anti-icing system panel changes. Issued 10/1/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA2269SW	King KRA 405 radar altimeter. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA2427SW	Optional VHF #2 Comm antenna. Issued 3/11/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36, -36A; T.C. A2PC	SA2489SW	Addition of baggage compartment in main landing gear wheel pods. Issued 8/17/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2309SW	Install Sperry TP[illegible]14B transponder. Issued 6/17/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2399SW	Installation of Primus-40 weather radar. Issued 2/2/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2413SW	Install AiResearch TPE331-5-252M engines and Hartzell Propeller HC-B4TN-5DL/LT10282B-5.3R. Issued 2/18/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2418SW	Install Bendix RNS-3500 area NAV system. Issued 2/24/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MONOCOUPE OF PRINCETON, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
90 Series; T.C. 306	SA4-1024	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
90AF, 90AF-100, 90AL-115; T.C. A-306	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
90AF, 90AF-100, 90AL-115; T.C. A-306	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
90, -A, -F, AF-100, AL-115; T.C. 306	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
90, 90A, 90F, 90AF-100, 90AL-115; T.C. 306	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
90AL-115; T.C. 306	SA1071CE	Installation of Lycoming IO-320-E1A engine modified per STC SE7CE and Hartzell propeller HC-C2YL-4 with modification of existing fuel system by addition of header tank and associated fuel system changes. Issued January 1975.	CE	73069	Murlin Gene Smith 1231 Woodward Avenue Topeka, KS 66604

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MOONEY AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20 Series; T.C. 2A3	SA1-585	External electrical power receptacle.	EA	41500	Haynes Equipment Co., Inc. 62 Voorhis Lane Hackensack, NJ 07601
M20 Series; T.C. 2A3	SA1-615	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 75 School Street Pawtucket, RI 02860
M20 Series; T.C. 2A3	SA4-607	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA4-768	Fuel flow filter 30409A with element 1A0235 and adapter 2A0083.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
M20 Series; T.C. 2A3	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
M20 Series; T.C. 2A3	SA4-1022	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA4-1277	Installation of Firestone DFA-180 wheel assemblies with CFA-252 brake assemblies.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
M20 Series; T.C. 2A3	SA4-1426	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA4-1542	Ceconite 101 covering of rudder, elevators, ailerons, and flaps.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
M20 Series; T.C. 2A3	SA10SW	External power plug.	SW	05969	Aircraft Service Company P.O. Box 931 Municipal Airport Kerrville, TX 78028
M20 Series; T.C. 2A3	SA42SO	A-100 burglar alarm system.	SO	47654	Kapu Alarms, Inc. 7349 Southwest 41st Street Miami, FL 33101
M20 Series; T.C. 2A3	SA179SW	Nose wheel well doors 8367-1 and 8367-2.	SW	20115	Ralph E. Cash 1601 South Birch Avenue Broken Arrow, OK 74012
M20 Series; T.C. 2A3	SA241SO	Mooney dorsal fin 4175-51.	SO	12492	Atlanta Aero Service, Inc. DeKalb-Peachtree Airport Chamblee, GA 30005
M20 Series; T.C. 2A3	SA224SW	Automatic pilot AK117.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20 Series; T.C. 2A3	SA331SW	Electric landing gear system.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
M20 Series; T.C. 2A3	SA406WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA666NW	Installation of teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
M20 Series; T.C. 2A3	SA684WE	Autopilot B2D.	EA	17500	Brittain Industries, Inc. Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
M20 Series; T.C. 2A3	SA705SW	AK182 automatic aileron stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20 Series; T.C. 2A3	SA73[illegible]SW	AK232 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20 Series; T.C. 2A3	SA739WE	Lateral stability augmentation system LSA-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA742WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA785WE	Flight control system B-6 including pitch assist PC-1, altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA841WE	Flight control system NAV-2 including navigation coupling and magnetic heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA848WE	"Air-Guard" anti-collision light.	WE	78485	Tibbetts Aircraft Radio Cable Airport Upland, CA 91786
M20 Series; T.C. 2A3	SA979WE	Lateral stability augmentation system LSA-2. Reissued October 1973.	SW	17940	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA9[illegible]0WE	NAV-2 flight control system including navigation coupling and magnetic heading lock.	EA	17500	Brittain Industries, Inc. Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
M20 Series; T.C. 2A3	SA991WE	Dynertial pitch assist PCA-1 with altitude hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA992WE	B-6 flight control system including PC-1 pitch assist, AH-1 altitude hold and NAV-2 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1172WE	Lateral stability augmentation system, LSA-4. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
M20 Series; T.C. 2A3	SA1198WE	NAV-2 flight control system or B-6 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1258SW	Porta-cool Model PC70 portable air conditioner. Issued 2/1/71.	SW	31358	Eagle, Inc. P.O. Box 13007 Fort Worth, TX 76118
t•1 M20 Series; T.C. 2A3	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M20 Series; T.C. 2A3	SA1489WE	Installation of Brittain Model B2C flight control system.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1550WE	Installation of Brittain LSA-4 flight control system.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1570WE	Installation of Brittain NAV-2 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1584WE	Installation of Brittain Model B-6 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1780WE	Installation of Brittain Industries LSA-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1785WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20 Series; T.C. 2A3	SA1786WE	Installation of Brittain Industries B-6 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1787WE	Installation of Brittain NAV-2B flight control. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20, M22 Series; T.C. 2A3, A6SW	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
Mark 20, 20A; T.C. 2A3	SA2666WE	Ceconite 102 material covering of rudder, elevators, ailerons and flaps. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M20, M20A; T.C. 2A3	SA2823SW	Reinforcement of vertical tail spar. Issued 7/31/78.	SW	64407	Harry L. Phillips Route 3, Box 420F Fort Worth, TX 76067
M20, M20A, M20B; T.C. 2A3	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amneded 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
M20 thru M20F; T.C. 2A3	SA600EA	Installation of electronic voltage alarm.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
M20, M20A thru M20E; T.C. 2A3	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
M20, M20A thru M20E; T.C. 2A3	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs: SA705SW, SA732SW.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M20, -A, -B, -C, -D, -E, -F, -G; T.C. 2A3	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 South Curtice Street Littleton, CO 80120
M20, M20A, M20B, M20C, -D, -E, -F; T.C. 2A3	SA1462WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	80120	Hanna-Aero Corporation 5222 South HOlly Street Littleton, CO 80120
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1932SW	Chrome plated disc brakes. Issued 11/27/74.	SW	29580	W.A. DeMaine Route 3, Box 62 Pine Bluff, AR 71601

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA3275WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell Mfrg. BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
M20A, M20B, M20C, M20D, M20G; T.C. 2A3	SA1156WE	Installation of Rajay turbosupercharged Lycoming O-360-A1A or -A1D engine. Amended 8/2/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA738EA	Installation of Whelen Engineering Co., Inc. Model HD-14 anti-collision strobe light system.	NE	85500	Whelen Engineering Co., Inc. 3 Winter Avenue Deep River, CT 06417
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light systems. Amended 10/4/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
M20B, C, D, E, F, G; T.C. 2A3	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
M20B, M20C, M20D, M20E, M20F, M20G, Normal Category; T.C. 2A3	SA3938WE	INstallation of flap gap seal. Issued 5/21/79.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA4023WE	Installation of flap gap fairings, flap hinge fairings, fuselage fairing at the tail cone, and a plexiglass landing light fairing. Amended 1/17/80.	WE	65015	John A. Porter 29 Walnut Via 501 E. Orangethorpe Avenue Anaheim, CA 92801
M20C, M20D; T.C. 2A3	SA77CE	Installation of McCauley 2D34C53/74E-0 or B2D34C53/74E-0 propeller with D-2809 spinner. Amended 5/24/68.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
M20C, M20D; T.C. 2A3	SA3859WE	Installation of an air/oil separator. Issued 3/12/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
Mooney M20C, M20D, M20E; T.C. 2A3	SA138WE	Installation of Grimes Model D-7080. Rotating beacon on vertical fin. Reissued 3/8/76.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
M20C, M20D, M20G; T.C. 2A3	SA375GL	Installation of Lycoming O-360-A1F6 or O-360-A1F6D in lieu of Lycoming O-360-A1D. Issued 11/26/79.	GL	90152	Louis M. Zeller, Jr. Route 1, Box 298-B Mount Vernon, IN 47620
M20C (S/N 20-0011 and on - 1974), (S/N 20-1147 and on - 1975), M20E (S/N 21-0025 and on - 1974), (S/N 21-1161 and on - 1975); T.C. 2A3	SA2993WE	Installation of Pathfinder autopilot systems and/or electric pitch trim systems. Issued 2/21/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C (S/N 20-0011 and on), M20E (S/N 21-0025 and on); T.C. 2A3	SA3222WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 11/15/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, E, F; T.C. 2A3	SA1938SW	Brittain LSA-6 lateral stability augmentation system (positive control). Issued 1/7/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20C, E, F, G; T.C. 2A3	SA2207SW	NAV-FLITE II and B-5 flight control systems. Issued 7/23/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20C, E, F, G; T.C. 2A3	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, E, F, G; T.C. 2A3	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, M20E, M20F; T.C. 2A3	SA2654WE	Installation of Pathfinder P2A autopilot system. Amended 4/14/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20E/Super 21; T.C. 2A3	SA999CE	Installation of ERC battery monitor. Issued March 1974.	CE	33229	Electronic Research Company P.O. Box 913 Shawnee Mission, KS 66201
M20E, M20F; T.C. 2A3	SA250GL	Installation of Lycoming IO-360-A1B6 engine in lieu of Lycoming IO-360-A1A engine using original installation hardware and components. No installation data are required. Issued 6/30/78.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA320GL	Installation of Hartzell Model HC-C2YK-1( )F/F7666A-4Q propeller in lieu of Hartzell Model HC-C2YK-1/7666-2 propeller using original installation hardware and components on aircraft previously modified in accordance with STC No. SA250GL. No installation data are required. Issued 6/28/79.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA1411WE	Installation of Rajay turbocharged Lycoming IO-360-A1A engine. Amended 5/9/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20E, M20F; T.C. 2A3	SA2968WE	Installation of manifold pressure gage/fuel flow meter (fuel pressure gage) in lieu of original gage/meter. Issued 1/29/75.	WE	65015	John A. Porter 29 Walnut Via 501 East Orangethorpe Avenue Anaheim, CA 92801
M20E, M20F, M20J; T.C. 2A3	SA3728WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
M20E, M20F, M20J; T.C. 2A3	SA4065WE	Installation of Silver Instruments fueltron 1G or IP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20F, S/N 22-1179 and up; M20J, S/N 24-0001 and up; T.C. 2A3	SA1212CE	Installation of King KFC 200 2 axis (3 optional) flight control system with KCS 55/55A compass and King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or third axis (yaw damper) only, or manual electric trim only. Amended 9/8/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20F, S/N 22-0013 and on (1974 models), S/N 22-1179 and on (1975 models); T.C. 2A3	SA2986WE	Installation of Pathfinder autopilot systems. Issued 2/19/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20F; T.C. 2A3	SA3047SW-D	Automatic flight system AK523 consisting of Century III autopilot with command automatic electronic pitch trim system and optional radio and glide slope couplers. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3048SW-D	Automatic flight system AK476 consisting of Century IIB autopilot with optional radio coupler. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3049SW-D	Automatic flight system AK475 consisting of Century I autopilot with optional omni tracker. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport MIneral Wells, TX 76067
M20F; T.C. 2A3	SA3064SW-D	MItchell command electric trim AK541. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3186WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20J; T.C. 2A3	SA1300CE	Installation of Edo-Aire propeller governor Model 34-826-014-11. Amended 1/9/78.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20J; T.C. 2A3	SA3307SW-D	Installation of Mitchell automatic flight system AK801 consisting of Century 41 autopilot or Model AK801FD consisting of Century 41 flight director autopilot. Issued 10/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3308SW-D	Installation of Mitchell automatic flight system AK802 consisting of Century 21 autopilot. Issued 10/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3555WE	Installation of Rajay turbocharged Lycoming IO-360-A3B6D and/or IO-360-A1D6D engines. Issued 12/30/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90801
M20J, M20K; T.C. 2A3	SA1525CE-D	Installation of King KNS 81 digital area navigation system. Issued 1/23/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20K; T.C. 2A3	SA378GL	Installation of Silver Instruments fueltron IG digital fuel flow meter. Reissued 1/3/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20K; T.C. 2A3	SA1464CE	Installation of KFC 200 two axis (three optional) flight control system. Issued 12/4/78.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M20K; T.C. 2A3	SA3325SW-D	Mitchell automatic flight system AK807 consisting of Century 41 autopilot flight director autopilot. Issued 1/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NOORDUYN NORSEMAN AIRCRAFT, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
UC-64 Series; T.C. 2-578	SA53EA	Removal of left rear cabin door and installation of parachuting step, static line anchor cable, pilot and jumpmaster signal system panels for the purpose of parachute jumping.	NE	62438	Parachutes, Inc. P.O. Box 96 Orange, MA 01364
UC-64 Series; T.C. 2-578	SA200WE	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
UC-64 Series; T.C. 2-578	SA223WE	Removal of right and left-hand main cabin doors to permit parachute jumping, aerial photography, etc.	WE	67012	Robert D. Reddick Route 1, Box 295 Santa Paula, CA 93060
UC-64 Series; T.C. 2-578	SA650SW	All metal structure and integral fuel tanks. Reissued 6/19/75.	EA	42700	J.W. Hosteller P.O. Box 325 Red Lake. Ontario, Canada
UC-64, -64A, -64B, -64AS; T.C. 2-578	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
UC-64, -64A, -64B, -64AS; T.C. 2-578	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
UC-64A; T.C. A-2-578	SA2298WE	Modification of Bendix master brake cylinder by instalation of Griffco Aviation piston and O-rings in lieu of Bendix piston assembly P/N 52152. Issued 1/7/71.	NW	39492	Griffco Aviation 7580 Perimeter Road Boeing Field International Seattle, WA 98108

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NORTH AMERICAN AVIATION, INC., CALIFORNIA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B-25 Series; L.T.C. 2	SA4-573	Closed bomb bay, enlarged rear entrance, added six windows installed bunk and seats, removed tail turrent.	WE	70560	Scott Aero Service, Inc. 2901 East Spring Street Long Beach, CA 90801
B-25 Series; L.T.C. 2	SA4-656	Aerofilter 30816A with element 1A0097.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
B-25 Series; L.T.C. 2	SA4-663	Cargo floor in bomb bay.	WE	70560	Scott Aero Service, Inc. 2901 East Spring Street Long Beach, CA 90801
B-25 Series; L.T.C. 2	SA4-804	Ceconite 101 covering of rudders, elevators and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
B-25 Series; L.T.C. 2	SA4-811	Fibergass nose.	WE	70560	Scott Aero Service, Inc. 2901 East Spring Street Long Beach, CA 90801
B-25 Series; L.T.C. 2	SA4-1429	1,200-gallon tank with hydraulically actuated doors for use in forest fire control operation.	WE	26660	Court Aircraft 851 East Water Street Tucson, AZ 85700
B25C, G, H, J, RB-25; L.T.C. 2	SA1744WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
B-25J, -25N, P-51C, D, K; LTC 2, 11	SA2666WE	Ceconite 102 material covering of: B-25J, -25N - rudders, elevators, and ailerons; P-51C, D, K - rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
P-51 Series; L.T.C. 11	SA3-413	Radio navigational system, Omni/ILS, glide slope and marker	GL	56610	M.A.R.S. Electronic Division Chicagoland Airport, Inc. Wheeling, IL 60090
P-51 Series; L.T.C. 11	SA4-647	Application of glass cloth to rudder.	WE	38060	Glasco-Air Products, Inc. Oxnard-Ventura Airport Oxnard, CA 93030
P-51 Series; L.T.C. 11	SA4-1529	Ceconite 101 covering of rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
P-51 Series; L.T.C. 11	SA1008WE	Poly-Fiber covering of rudder. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
P-51 Series; L.T.C. 11	SA1182WE	Rolls Royce V-1650-9A engine and Aeroproducts A542/H20-162-29M5 propeller.	WE	14770	Vern Baker 2860 East Wardlow Road Long Beach, CA 90807
B-25J, -25N; P-51C, D, K; T.C. LTN 2, T.C. LTC 11	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
P-51D; T.C. 11	SA179SO	Baggage compartment door, left side, stations 168 to 200.	SO	20220	Cavalier Aircraft Corporation Box 1719 Sarasota, FL 33578
P-51D; T.C. 11	SA180SO	60-gallon wing bladder tanks.	SO	20220	Cavalier Aircraft Corporation P.O. Box 1719 Sarasota, FL 33578
P-51D; T.C. 11	SA621SO	Vertical stabilizer extended upward approximately 13 inches.	SO	20220	Cavalier Aircraft Corporation P.O. Box 1719 Sarasota, FL 33578
P-51D; T.C. 11	SA726SO	Installation of Bendix M4C automatic flight control system (autopilot). Subsequent installation on other aircraft of the same model shall require flight tests to show compliance with LTC specification No. L-11-3 and CAR 9.3(a). Issued 4/21/72.	SO	72450	Skytel Aviation, Inc. 2100 West Commercial Boulevard Ft. Lauderdale, FL 33310

NORTH AMERICAN AVIATION, INC., CA 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
P-51D; T.C. 11	SA1129SW	Mitchell Century II autopilot and radio coupler.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, OK 73109
P-51D; T.C. 11	SA1748WE	Installation of Packard-built Rolls Royce V-1650-9A engine.	WE	03019	Aero Sports, Inc. Hangar No. 2, Chino Airport Chino, CA 91710
P51D, K, (F51, D); T.C. LTC-11	SA3125SW-D	Automatic flight system AK595 consisting of Century IIB autopilot with optional radio coupler. Issued 3/30/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
P51D, K, (F51D, K); LTC-11	SA3126SW-D	Automatic flight system AK596 consisting of Century I autopilot with optional omni tracker. Issued 3/30/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
T-28A; T.C. AR-30	SA4-736	Modification of lower aft access door and installation of brakets and mounts for K-25 camera.	WE	19900	Carma Manufacturing Company P.O. Box 11312 Municipal Airport Tucson, AZ 85700
T-28A; T.C. AR-30	SA4-744	Camera.	WE	13180	Avia Union P.O. Box 1344 Santa Ana, CA 92702
T-28A; T.C. AR-30	SA4-775	Mark AN-3 camera in left wing.	WE	40295	Hammon Aircraft Corporation 2237 North 8th Street Phoenix, AZ 85000
T-28A; T.C. AR-30	SA4-797	Fabrication and installation of camera mount and K-25 camra.	WE	39877	Hamilton Aircraft Company, Inc. 6501 South Park Avenue Tucson, AZ 85706
T-28A; T.C. AR-30	SA91WE	Camera.	WE	07550	Air-Fab 1078 North Parker Orange, CA 92666

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NORTH AMERICAN AVIATION, INC., OHIO

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BC-1A, AT-6 Series; TT-6G; T.C. 2-575	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennge and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena,CA 91001
BC-1A, AT-6 Series; T-6G; T.C. 2-575	SA1008WE	Poly-Fiber covering of left elevator and right aileron. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
BC-1A, AT-6, -6A, -6B, -6D, -6F, SNJ-7, -6G; T.C. 2-575	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
BC-1A, AT-6, SNJ Series, T-66; T.C. 2-575	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC-1A, AT-6, -6A, -6B, -6C, -6D, -6F, T-6G; T.C. 2-575	SA1351WE	Replace existing fabric on wings, fuelage, empennage, and/or control surface with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC-1A, AT-6, -6A, -6B, -6C, -6D, -6F, T-6G; T.C. 2-575	SA2666WE	Ceconite 102 material covering of rudder, elevators and ailerons. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
AT-6 Series; T.C. 2-575	SA4-764	Application of glass cloth to ailerons and elevators.	WE	38060	Glasco-Air Products Oxnard-Ventura Airport Oxnard, CA 93030
AT-6 Series; T.C. 2-575	SA4-859	Ceconite 101 covering of rudder, elevators and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
AT-6 Series; T.C. 2-575	SA283SO	Glass-cloth wing tip caps.	SO	26580	Corben Development Corp. P.O. Box 1603 Venice, FL 33595
AT-6, -6A, -6B, -6C, -6D, -6F, T-6G; T.C. A-2-575	SA1521WE	Installation of metal covering on ailerons, elevators and rudder. Reissued 6/8/79.	WE	47732	Ken Aero 6960 Curran Street Brownfield Int'l Airport San Diego, CA 92173
AT-6, -6A, -6B, -6C, -6D, -6F, SNJ-7, T-6G; T.C. A-2-575	SA2814WE	Installation of Hamilton Standard 3D40 225/6101A-18 propeller. Issued 2/5/74.	WE	70100	Santa Monica Propeler Service 3025 Airport Boulevard Santa Monica, CA 90405
AT-6D (SNJ-5); AT-6F (SNJ-6), T-6G, SNJ-7, AT-6C (SNJ-4); T.C. A-2-575	SA3091SW-D	Mitchell automatic flight system AK520 consisting of Century III autopilot with optional radio coupler. Issued 12/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AT-6D (SNJ-5), AT-F (SNJ-5), AT-6F (SNJ-6), T-6G, SNJ-7, AT-6C (SNJ-4); T.C. A-2-575	SA3092SW-D	Mitchell automatic flight system, AK464, consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PARTENAVIA COSTRUZIONI AERONAUTICHE S.p.A.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
P68B; T.C. A31EU	SA3067SW-D	Mitchell automatic flight system AK511, consisting of Century III autopilot with command automatic electronic pitch trim and optional radio coupler and glide slope coupler. Issued 8/18/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
P68B; T.C. A31EU	SA3068SW-D	Mitchell automatic flight system AK510 consisting of Century IIB autopilot with optional radio coupler. Issued 8/18/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
P68B; T.C. A31EU	SA3069SW-D	Mitchell automatic flight system AK539 or AK539FD consisting of Century IV flight director autopilot. Issued 9/15/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
P68B; T.C. A31EU	SA3070SW-D	Mitchell automatic flight system AK427 consisting of Century I autopilot with optional omni tracker. Issued 9/16/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PERTH-AMBOY TITLE COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Bird, B.W.; ATC 382	SA1008WE	Poly-Fiber covering of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PIAGGIO & C.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
P.136 Series; T.C. 813	SA3-489	L2C autopilot with altitude control and approach coupler. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Dviion East Joppa Road Towson, MD 21204
P.136 Series; T.C. 813	SA61WE	Full flow oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
P136L; A-813	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
P136L; A-813	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
P.136-L, P.136-L1, P.136-L2; T.C. A-813	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P.136-L1, -L2; T.C. 813	SA1686WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

DONALD L. PICCARD

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Piccard Balloon AX6; T.C. A18WE	SB3WE	Installation of digital readout balloon envelope temperature indicator. Issued 5/6/77.	WE	01450	Advanced Aircraft Components 1459 Irving Avenue Glendale, CA 91201
Paccard Balloon AX6; T.C. A18WE	SB10WE	Installation of a digital readout balloon envelope temperature indicator.. Issued 11/14/79.	WE	01450	Advanced Aircraft Components 1459 Irving Avenue Glendale, CA 91201
iccard Balloon AX6; .C. A18WE	SL575SO	Installation of ABP-181 automatic balloon pilot (automatic temperature control). Reissued 11/5/74.	SO	23345	J. Donald Cline 807 Larkwood Drive Greensboro, NC 27410
Piccard Balloon AX6; T.C. A18WE	SA2327SW	Install locking "Carabiner" in the suspension system. Issued 6/9/76.	SW	56850	J.C. Meador 218 East Edgebrook Houston, TX 77034

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PILATUS AIRCRAFT, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PC-6; T.C. 7A15	SA77NW	Removal of landing gear and installation of seaplane conversation. Reissued 7/20/78.	EA	34270	Fairchild Republic Division Hagerstown, MD 21740
PC-6; T.C. 7A15	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PC-6; T.C. 7A15	SA1460WE	Instllation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PC-6; T.C. 7A15	SA1518WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PC-6, -6-H1, -6-H2, -6/350, -6/350-H1, -6/350-H2, -6/A, -6/A-H1, -6/A-H2, -6/B-H2 -6/B1-H2, -6/B2-H2, -6/A-H2; T.C. 7A15	SA307EA	Removal of either or both of the right and cabin door and/or opening of the fuselage bottom hatch in flight. Amended and reissued 5/13/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2, /B2-H2; T.C. 7A15	SA433EA	Installation of dual brake valves. Amended 11/14/78.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6, -6-H1, -H2, -6/350, /350-H1, /350-H2, -6/A, /A-H1, /A-H2, -6/B-H2, /B1-H2, /B2-H2, -6/C-H2, /C1-H2; T.C. 7A15	SA465EA	Installation of UAT-1 transponder, MBT-R marker beacon, KN-60 DME, KX-160 and KX-160-1 Nav/Comm, KR-80ADF, headset microphone and speaker. Reissued 6/19/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6, PC-6-H1, -H2, 6/350, -6/350-H1, -H2, -6/A, -6/A-H1, -H2, -6/B-H2, 6/B1-H2, 6/C-H2, -6/B2-H2; T.C. 7A15	SA743EA	Installation of a sliding door on the left side of fuselage. Amended and reissued 5/13/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6, -H1, -H2; 6/350, /350-H1, -H2; 6/A, -H1, -H2; -6/B-H2, /B1-H2, 6/C-H2; T.C. 7A15	SA830EA	Installation of fiberglass protective boot on leading edge of horizontal stabilizer. Amended and ressued 5/13/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/A-H2; T.C. 7A15	SA273EA	UAC engine PT6A-6P and Hartzell propeller HC-B3TN-3/10173 combination. Reissued 4/2/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 2076
PC-6/A, /A-H1, /A-H2, /B-H2, /B1-H1, /B2-H2, /C-He; T.C. 7A15	SA397EA	Fuel collector tank vent line. Reissued 4/2/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/A, /A-H1, /A-H2, /B-H2, /B1-H2, /C-2, /B2-H2; T.C. 7A15	SA498EA	Installation of Zep Aero oxygen system. Reissued 6/19/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard ermantown, MD 20767
PC-6/A, /A-H1, /A-H2, /B-H2, /B1-H2, /C-H2, /B2-H2; T.C. 7A15	SA526EA	Installation of pilot's and co-pilot's shoulder harness. Reissued 6/19/74.	EA	34249	Fairchild Industies, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/A-H2, PC-6/C-H2; T.C. 7A15	SA368EA	Installation of AiResearch engine Model TPE 331-25D, TPE 331-25DA, TPE-25DB, or TPE 331-71 and Hartzell propeller Model HC-B3TN-5C/T10178C. Reissued 1/31/73.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
PC-6/A-H2, /B-H2, /B1-H2, /B2-H2, /C-H2; T.C. 7A15	SA528EA	Installation of KX-160 NAV/COM, 618M-1A, VHF COM., T-10-R HF COMM ARC Type 21A ADF headsets, microphones and speakers. Reissued 6/19/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
t+1 PC-6/B-H2, PC-6/B1-H2; T.C. 7A15	SA264AL	Installation of B.F. Goodrich electric propeller de-icing system. Reissued 2/12/74.	EA	85890	Wien Air Alaska, Inc. 4100 International Airport Road Anchorage, AK 99502

PILATUS AIRCRAFT, LTD. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PC-6/B-H2, /B1-H2, C-H2, /B2-H2; T.C. 7A15	SA493EA	Installation of Randolph Mfg. Co. Model 133 vacuum regulator. Reissued 6/19/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, -B1-H2; T.C. 7A15	SA614EA	Installation of UACL engine Model PT6A-27 with Hartzell propeller Model HC-B3TN-3D/T10178C(H) on aircraft configured with cockpit doors. Reissued 4/2/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2, PC-6/B2-H2; T.C. 7A15	SA747EA	Installation of two external fuel tanks of fifty gallons capacity each, mounted. Reissued 4/2/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA753EA	Installation of (2) ARC 21A ADF's, (2) ARC 131B VHF's and (1) SA14RA HF avionics equipment. Amended 1/30/73.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA755EA	Installation of Polyurethane reticulatd foam in aircraft's integral and collector fuel tanks in addition to check valves in fuel lines between integral tanks and collector and sediment tanks. Amended 11/9/73.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Gemantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2, PC-6/B2-H2; T.C. 7A15 t) (	SA906EA	Elevator reinforcement. Amended 10/31/75.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, /B1-H2, /B2-H2, /C-H2; T.C. 7A15	SA970EA	Installation of outboard aileron reinforcements. Amended 10/24/75.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, /B1-H2, /B2-H2, /C-H2; T.C. 7A15	SA908EA	Installation of rudder reinforcement. Amended 10/31/75.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard ermantown, MD 20767
PC-6/B-H2, /B1-H2, /B2-H2, /C-H2; T.C. 7A15	SA909EA	Installation of vertical stabilizer reinforcement. Amended 10/22/75.	EA	34249	Fairchild Indutries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, /B1-H2, /B2-H2, /C-H2; T.C. 7A15	SA910EA	Installation of horizontal stabilizer reinforcement. Amended 10/31/75.	EA	34249	Fairchild Industries Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, /B1-H2, /B2-H2, /C-H2, T.C. 7A15	SA911EA	Installation of bulkhead 12A reinforcement. Reissued 4/4/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA937EA	Cabin floor, special installation structural provisions Issued 12/21/72.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA938EA	Wing flap and aileron reinforcement. Issued 12/21/72.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
PC-6/BH2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA939EA	Substitution on AN hardware in lieu of metric hardware. Issued 12/21/72.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA940EA	Left wing reinforcement. Issued 12/21/72.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA941EA	Wing hard point modification. Issued 12/21/72.	EA	34249	Fairchild Industies, Inc. Fairchild Drive Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA944EA	Installation of improved pitot-static system drain. Amended 4/25/73.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germanton, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2, PC-6/B2-H2; T.C. 7A15	SA945EA	Installation of longitudinal out of trim warning system. Reissued 7/3/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA946EA	Relocation of wing landing light between left wing rib stations 11 and 12 to left wing rib stations 21 and 22. Issued 1/30/73.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
PC-6/B-H2, PC-6/B1-H2, PC-6/C-H2; T.C. 7A15	SA961EA	Installation of battery over-temperature warning system. Amended 12/10/73.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/A-H2; T.C. 7A15	SA986WE	Removal of landing gear and installation of seaplane conversion. Reissued 4/1/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, /B1-H2, /B2-H2; T.C. 7A15	SA1005EA	Installation of fuel collector tank - engine shutdown fuel discharge. Issued 5/27/75.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/B-H2, /B1-H2, /C-H2; T.C. 7A15	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	EA	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
PC-6/B1-H2; T.C. 7A15	SA545EA	Installation of Hartzell propeller Model HC-B3TN-3D/T10178C(H). Reissued 4/2/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/C-H2; T.C. 7A15	SA10PC	Interior seating arrangement to provide convertible passenger-cargo capability.	EA	03550	Air America, Inc. 815 Connecticut Avenue, N.W. Washington, D.C. 20006
PC-6/C-H2; T.C. 7A15	SA612EA	Installation of EDO-58-4580 floats. Amended 8/1/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
PC-6/C-H2; T.C. 7A15	SA912EA	Nose ballast installation. Reissued 4/474.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 2067
PC-6/C-H2; T.C. 7A15	SA1004EA	Instalation of engine fuel purge system - engine shutdown. Issued 5/27/75.	EA	34249	Fairchild Industries, Inc. 20301 Cenury Boulevard Germantown, MD 20767
PC-6/B-H2, -6/B1-H2, -6/B2-H2, -6/C-H2; T.C. 7A15	SA1022EA	Installation of Aerosmith C-129-65 pilot's and copilot's seats and modified control sticks. Issued 11/14/75.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PIPER AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J-2, J3, J4, PA-16, -18, -19, -22 Series; T.C. 595, 692, 703, 1A1, 1A2, 1A6	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
J2, J3, J4, J5A, PA-12; ATC 595, 660, T.C. A-703, A-725, A-780	SA582NW	Fabrication of wire ropes. Issued 5/12/78.	NW	81180	University Swedging 7001 Perimeter Road Seattle, WA 98108
J2, J3C-40, -50, -50S, -65, -65S, PA-11, -11S, J3F-50, -50S, -60, -60S, -65, -65S, J3L, -S, -65, -65S, J4, J4A, J4A-S, J4B, J4E, J4F, J5A, J5A-80, J5B, J5C, AE-1, HE-1, PA-12, -12S, PA-14, PA-15, PA-17, PA-16, -16S, PA-18, -18A, -18S, -18-105, -18S-105, -18-125, -18AS-125, -18S-125, -18-135, -18A-135, -18AS-135, -18S-135, -18-150, -18AS-150, -18S-150, PA-19, -19S, Restricted Category PA-18A, -18A-135, -150, PA-20, -20S, -20-115, -20S-115, -20-135, -20S-135, PA-22, -22-108, -22-135, -22S-135, -22-150, -22S-150, -22-160, -22S-160, PA-25, -25-235; ATC 595, T.C. 691, 692, 698, 703, 708, 740, 724, 725, 780, 797, 800, 805, 1A1, 1A2, AR-7, 1A4, 1A6, 2A8, 2A10	SA2666WE	Ceconite 102 material covering of: J3C, J3F, PA-11, J3L Series - wings, fuselage, ailerons, elevator, rudder, horizontal and vertical stabilizer; PA-12, -12S, -15, -17, PA-18 Series, PA-19, -19S, PA-20 Series, PA-25 Series, J4 Series, J5 Series, J2 - complete aircraft; PA-14 - wings, fuselage and vertical fin; PA-16, -16S - wings, fuselage, ailerons, elevator and rudder; PA-22 Series - fuselage, wings, horizontal and vertical stabilizer, ailerons, flaps, rudder and elevator. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J3 Series; T.C. 691	SA1-423	Sensenich M74CK-2 fixed pitch metal propeller.	EA	39486	Robert A. Greimel 2571 Iverson Street, SE Washington, D.C. 20003
J3 Series; T.C. 691	SA1-497	Franklin 4AC-176-F3 engine.	GL	73330	Jimmie Snodgrass and William H. Cross P.O. Box 158 Racine, OH 45771
J3 Series; T.C. 691	SA3-111	Wing modification.	CE	36754	Roy M. Frazier Route 1 Chillicothe, MO 64601
J3 Series; T.C. 691	SA3-514	Modification to exhaust and carburetor air preheater muff systems and installation of exhaust stack shields on cowling.	GL	41170	George F. Haveman Home Acres Sky Ranch Lake City, MI 49651
J3 Series; T.C. 691	SA187AL	Install Continental C-90 and PA-18-95 cowl and baffles.	AL	08325	Air Power Overhaul P.O. Box 6025 Airport Annex Anchorage, AK 99502
J3 Series; T.C. 691	SA254CE	Model A fiberglass floats.	GL	39480	Greenwood Fiberglass Company Manitou Beach, MI 49253
J3 Series; T.C. 691	SA322CE	Manufacture hitch and bracket. Install tow hitch. Amended 5/6/71.	CE	76500	Stubben-McCandless South Omaha Airport Route 1 Papillion, NE 68046
J-3 Series; A.T.C. 660	SA309GL	Installation of Continental A65-8 engine and Sensenich module 72CK propeller (wood). Issued 5/18/79.	GL	14870	Bartlet Avaition, Inc. 5600 Portage Road Kalamazoo, MI 49002

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J3 Series; T.C. 691	SA357CE	Model B fiberglass floats.	GL	39480	Greenwood Fiberglass Company 2690 Geneva Highway Manitou Beach, MI 49253
J3 Series; T.C. 691	SA811SW	Clip wings and install Continental A-75-8 engine.	SW	66450	Keith P. Rawe 418 Willow Lane Baytown, TX 77520
J3 Series; T.C. 691	SA1251WE	Belt-driven 35A or 55A alternator on Continental A-65-8 engines.	WE	37877	Gifford-Sherman Company 2000 Hawkins Way Spring Valley, CA 92077
J-3, J3 Series; T.C. 660, 691, 692, 698, 695	SA4-469	Application of glass cloth with resin.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
J-3, J3C-40, 50, 50S, 65, 65S, PA-11, -11S, J3F-50, 50S, 60, 60S, 65, 65S, J3L, -S, -65, -65S, J3P, J4, J4A, J4AS, J4B, E, F, J5A, -80, J5B, J5C, AE-1, HE-1, PA-12, -12S, PA-14, PA-15, PA-16, -16S, PA-18, -18A, -18S, -18"105", -"105S", -"125", PA-18AS"125", -18S"125", -18A"135", -18AS"135", -18S"135", -18"150", -18AS"150", -18S"150", PA-19, -19S, PA-20, -20S, -20"115", -20S"115", -20-"135", -20S"135", PA-22, -22-108, -22-135, -22S"135", -22"150", -22S"150", -22"160", -22S"160", PA-25, -25-235, -260; T.C. 660, 691, 692, 698, 695, 703, 708, 740, 721, 725, 780, 800, A797, 1A1, 1A2, AR-7, 1A4, 1A6, 2A8, 2A10	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
J-3, J3, J4, J5, PA-11, -12, -14, -15, -17, -18, -19 Series; T.C. 660, 691, 692, 698, 695, 703, 708, 740, 721, 725, 780, 797, 800, 805, 1A2	SA5-9	25x11x4 tires and tubes with Airglass Engineering Company adapters LWA 950.	AL	69740	Safeway Airways P.O. Box 1062 Anchorage, AK 99500
J-3, PA-11, -12, -14, -16, -18, -20, -22 Series; T.C. 660, 691, 692, 698, 780, 797, 1A1, 1A2, 1A4, 1A6	SA5-13	Installation of 8.50x6 tires and tubes with Hayes 6-inch wheels. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622
J-3, PA-11, PA-12, -14, -16, -18, -20, -22 Series; T.C. 660, 691, 692, 698, 780, 797, 1A1, 1A2, 1A4, 1A6	SA5-13	Installation of 8.50x6 tires and tubes with Hayes 6-inch wheels. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
J3, J3C-65, -65S, PA-11, -11S, J4A, J4AS, J5A, J5A-80, PA-17, PA-18, PA-19; T.C. 703, 725, 805, 1A2	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
J-3, J3, J4, J5A, PA-11, -12, -14, -15, -16, -17, -18, -20 Series; T.C. 660, 691, 703, 725, 780, 797, 800, 1A1, 805, 1A2, 1A4	SA95AL	Maule SFS-1-4-P8 tail wheel; Hayes D-15-26 brake assembly using Kennedy Air Service adapter 64-1; Hayes wheel assembly D3-105MD; and 800x6, 850x6 or 900x6 4-ply tires and tubes.	AL	47744	Kennedy Air Service P.O. Box 94 Valdez, AK 99686
J3, J4, J5, PA-11, -12, -14, -15, -16, -17, -18, -19, -20 Series; T.C. 691, 692, 698, 703, 740, 725, 780, 797, 800, 1A1, 805, 1A2, 1A4	SA99AL	Six-inch wheels and brakes.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J-3, J3, J4, PA-11, -12, -14, -15, -16, -18, -19, -20, -22, -25 Series; T.C. A-691, -703, -780, -797, -800, -805, 1A1, 1A2, 1A4, 1A6, 1A8	SA126SO	Wing fabric attachment clips. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
J3, J-3-C, -F, -L, PA-11, -12, -14, -18, -18-105, -18-135, -18-150, -18A-135, -18A-150; T.C. 660, 691, 692, 698, 780, 797, 1A2	SA214AL	Install L1650A and L-2000A wheel replacement skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
J3, J4, J5, PA-11, -12, -18, -22 Series; T.C. 691, 692, 698, 703, 725, 780, 1A2, 1A6	SA220SO	Tow bar, release mechanism and safety tow link. Transfer 2/9/71.	SO	37092	Gasser Banners, Inc. P.O. Box 3502 Metropolitan Airport Nashville, TN 37217
J-3, J-4, J-5, PA-11, PA-12, PA-14, PA-18; T.C. 660, 691, 692, 698, 703, 708, 740, 721, 725, 780, 797, 1A2	SA262AL	Install 6x6x44 fish pole tube.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
J3, J4, J5, PA-11, -12, -14, -15, -16, -17, -18, -19, -20; T.C. 691, 692, 698, 703, 725, 740, 780, 797, 800, 805, 1A1, 1A2, 1A4	SA293AL	Install Stoddard improved brake system.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J3, J5, PA-11, -12, -14 Series; T.C. 691, 725, 780, 797	SA5-33	Balanced tail surfaces; elevators Piper 12789-00 and 12789-01; and stabilizers Piper 12790-00 and 12790-01.	AL	86070	Wilbur Repair Service 1740 East Fifth Anchorage, AK 99507
J3, J5, PA-11, -12, -14, -18, -18A Series; T.C. 691, 692, 698, 695, 725, 780, 797, 1A2	SA3AL	Installation of Fred A. Shaw tundra-bird Model 2500 skis. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
J3, J5, PA-11, -12, -14, -18, -18A Series; T.C. 691, 692, 698, 695, 725, 780, 797, 1A2	SA3AL	Installation of Fred A. Shaw tundra-bird Model 2500 skis. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
J3, J5, PA-12, -14, -15, -16, -17, -18, -20, -22 Series; T.C. 691, 725, 780, 797, 800, 1A1, 805, 1A2, 1A4, 1A6	SA144AL	Remote compass bracket.	AL	30250	F.A. Dodge P.O. Box 6409 Anchorage, AK 99506
J3, J5, AE-1, HE-1, PA-12, -15, -16, -20, -22; T.C. 691, 725, 800, 1A1, 1A4, 1A6	SA1008WE	Poly-Fiber covering of airplane. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
J3, PA-11 Series; T.C. 691	SA3-35	Beech controllable propeller R003-100 hub with R003-232-72T blades in airplanes with Continental C85 engines.	CE	17305	Bristow Aircraft Bristow, IA 50611
J3, PA-11 Series; T.C. 691	SA338CE	Continental C-90-12-F engine.	GL	41170	George F. Haveman Home Acres Sky Ranch Lake City, MI 49651
J3, PA-11 Series; T.C. 691, 692, 698, 695	SA3-356	C2200 main hydraulically actuated and AWT2500 or AWT2500A tail wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
J3, PA-11 Series; T.C. 691, 692, 698, 695	SA3-357	C2200 main (manually actuated) and AWT2500 or AWT2500A tail wheel-skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
J3, PA-11; T.C. 691, 692, 698	SA4-907	Ceconite 101 covering of wings, fuselage, ailerons, elevator, rudder, and horizontal and vertical stabilizer.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
J3, PA-11 Series; T.C. 691, 692, 698	SA333CE	Omni view window.	GL	41170	George F. Haveman Home Acres Sky Ranch Lake City, MI 49651
J3, PA-11, -12, -15, -18, -19; T.C. 691, 780, 800, 1A2	SA3-424	CTF-2200 tail ski on airplanes equipped with Scott Model 3000 tail wheel.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J3, PA-11, -12, -14, -18, -19, -20, -22; T.C. 691, 780, 797, 1A2, 1A4, 1A6	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
J3, PA-11, -12, -14, -18; T.C. 691, 780, 797, 1A2	SA5-39	Large horizontal stabilizers and elevators.	AL	17000	M.R. Boter 1307 West 39th Place Spenard, AK 99503
J3, PA-11, -12, -14, -18, -20; T.C. 691, 692, 698, 703, 725, 740, 780, 797, 1A2, 1A4	SA5-65	25x11x4 tires on Goodrich 4-inch wheels 841696 using rim adapter A-1.	AL	08496	Alaskan Aircraft Equipment Supply, Inc. 4707 Spenard Drive Anchorage, AK 99503
J-3; PA-11, -12, -14, -16, -18, -20; T.C. A-691, 692, 698, A-780, A-797, 1A-1, 1A-2, AR-7, 1A-4	SA11RM	Installation of modified axles Cleveland P/N 40-84 wheels and P/N 30-41 brakes or McCauley P/N D-30291 wheels and P/N D-30118 brakes or Cleveland P/N 040-06000 wheels and P/N 030-06000 brakes. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
J3, PA-11, -18 Series; T.C. 691, 1A2	SA3-202	Fabrication and installation of wing splate.	RM	48670	L.A. Kraemer 2302 38th Street Rapid City, SD 57701
J3, PA-11, -18 Series; T.C. 691, 1A2	SA683SW	Convert from monoplane to biplane.	SW	02356	Aeromod, Inc. North Little Rock, AR 72114
J3C; T.C. A-691	SA507AL	Installation of alternate crankcase breather. Issued 11/12/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J3C, PA-11; T.C. 691	SA111AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Amended 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
J3C-40, -50, -65, PA-11; T.C. A-691	SA820CE	Install Aero Model M1500, M1800 or M2000 main skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
J3C-40, -50, -65, PA-11; T.C. A-691	SA835CE	Installation of wing tip splates. Issued August 1972.	CE	73270	Smitty's Aircraft Service, Inc. Box 567 O'Neill, NE 68763
J3C-65 with Reed Wing Conversion; T.C. A-691	SA107RM	Install Continental O-200-A engine and McCauley 1A101/DCM or Univair aeromatic F200/00-73E propeller with 18-gallon wing fuel tank. Issued 7/26/77.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
J3C-65; T.C. 691	SA525CE	Concurrently incorporate the following items of Aircraft Specifications No. A-691; 625 - clipped wing installation except operating limitations are not changed; 617 - wing tip spill plates. Incorporation of this item only is optional; 311(c)(9) - Continental C85-8 or -12 engine. Amended 4/22/69.	CE	38062	Alfred C. Glaser P.O. Box 87 Spalding, NE 68665
J3C-65, J3C-65S; T.C. A-691	SA455AL	Installation of PA-18 fuel system. Issued 11/19/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, J3C-65S; T.C. A-691	SA457AL	Forward fuselage structural changes to PA-11 configuration. Approval is limited to those Piper J3C-65 and J3C-65S aircraft which have FAA approved PA-18 fuel system installed. Issued 11/22/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, J3C-65S; T.C. A-691	SA459AL	Installation of PA-18 baggage compartment. Approval is limited to those Piper J3C-65 and -65S aircraft which have FAA approved PA-18 elevator control system installed. Issued 11/23/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, J3C-65S; T.C. A-691	SA464AL	Installation of PA-18 rear seat. Approval limited to those Piper J3C-65 and J3C-65S aircraft which have FAA approved PA-18. Issued 12/1/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J3C-65, J3C-65S; T.C. A-691	SA465AL	Installation of PA-18 boot cowl and windshield. Issued 12/15/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, J3C-65S; T.C. 691	SA1038SO	Installation of Aqua Model 1500 floats. Issued 12/20/78.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA68AL	Installation of wing tank. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA456AL	Installation of PA-18 wing lift struts. Issued 11/22/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA458AL	Installation of PA-18 horizontal stabilizer trim system. Issued 11/23/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA460AL	Installation of PA-18 pitot-static system. Issued 11/24/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, 65S, PA-11, PA-11S;	SA462AL	Installation of PA-18 front seat. Issued 11/24/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA463AL	Installation of PA-18 elevator control system. Issued 11/24/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J-3C; J-3F; J-3L; J-4, -4A; J-4E; J-5A, -5B, -5C; PA-11; PA-12; PA-14; PA-15; PA-16; PA-17; PA-18, -18A; PA-20; T.C. A-691, A-692, A-698, A-753, A-740, A-725, A-780, A-797, A-800, 1A1, A-805, 1A2, AR-7, 1A4	SA2NE	Installation of Cleveland wheels and brakes on several models of Piper aircraft. Issued 4/5/73.	NE	70320	Mr. William V. Scherbon Hadley Road Merrimac, MA 01860
J-3C, -3F, -3L; PA-11; T.C. A-691, A-692, A-698	SA302AL	Installation of AD 2500x10.5 wheel replacement skis and rigging. Amended 1/30/70.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99501
J3C, J3C-65, -65S, J3F, J3F-50, -50S, -60, -60S, -65, -65S, J3L, J3L-S, J3L-65, -65S, J4, J4A, J4A-2, J4E, PA-12, PA-14, PA-15, PA-16, PA-17, PA-18, PA-18A, -18S, -125, -135, -150, PA-19, PA-19S, PA-20, PA-20S, -115, -135, PA-22, -108, -135, -150, -160, -22S, -135, -160, -150, PA-23-160, -235, -250, PA-24, -250, -260, PA-25, -235, PA-28, -140, -150, -160, -180, -235, PA-28S, -160, -180, PA-32-260; T.C. 691, A-692, A-698, A-703, A-740, A-780, A797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 1A10, 1A15, 2A8, 2A13, A3SO	SA306EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J3C, J3C-65, -65S, PA-11, J3F, J3F-50, -50S, -60, -60S, -65, -65S, J3L, J3L-S, -65, -65S, J4, J4A, J4A-3, J4E, PA-12, PA-14, PA-15, PA-16, PA-17, PA-18, -18A, -18S, -125, -135, -150, PA-20, -20S, -115, -135, PA-19, -19S, PA-22, -22-108, -135, -150, -160, PA-22S, -135, -150, -160, PA-23, PA-23-160, -235, -250, PA-24, PA-24-250, -260, PA-25, -25-235, PA-28, -28-140, -150, -160, -180, -235, PA-28S, -28S-160, -180, PA-32, -32-260; T.C. A-691, A-692, A-698, A-703, A-740, A-780, A-797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 1A10, 1A15, 2A10, 2A13, A3SO	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
J3C, PA-11; J3F; J3L; J4; J4E; J5; PA-12, -12S; PA-14; PA-15; PA-17, PA-30, PA-31, -31-300; PA-32; PA-16; PA-18; PA-20; PA-22; PA-23; PA-24; PA-25; T.C. A-691, A-692, A-698, A-703, A-725, A-740, A-780, A-797, A-800, A-805, A1EA, A8EA, A3SO, 1A1, 1A2, 1A4, 1A6, 1A10, 1A15, 2A8, 2A10	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
J3C-40, -50, -65 (Army L-4A, -4B, -4J; Navy NE-1, -2), PA-11; T.C. A-691	SA3284WE	Installation of Geroge M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Rodell 23804 Pennsylvania Avenue Torrance, CA 90501
Piper J3C-65; T.C. 691	SA158GL	Installation of engine fiberglass cowling. Issued 3/10/77.	GL	02250	Aero Fabricators, Inc. P.O. Box 181 Lyons, WI 53148
Piper J3C-65; T.C. A-691	SA196GL	Replacement of main wheels and brakes with Gerdes Products wheel A-1780 and A-1870-4 brake. Issued 10/27/77.	GL	43080	Robert L. Howell Rural Route #2 Lewisburg, OH 45338
J3C-65; PA-11; T.C. A-691	SA461AL	Installation of PA-18 landing gear cabane. Issued 11/24/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3-C, PA-11; PA-12; PA-14, PA-18, -19; T.C. 691, 780, 797, 1A2	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J3F; T.C. 692	SA394AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
J3F-50, -60, -65; T.C. A-692	SA821CE	Install Aero Model M1500, M1800, or M2000 main skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
J3F-60; T.C. 692	SA1008WE	Installation of poly-fiber covering material of fuselage and wing. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
J3L; T.C. 698	SA395AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
J3L, -65; T.C. A-698	SA822CE	Install Aero Model M1500, M1800 or M2000 main skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J3L, -S, -65, -65S; PA-12, -12S; PA-14; PA-15; PA-17; J4, J4A, -S; J4B; J5A, -80, J5B, J5C, AE-1, HE-1; PA-11, -11S, J3C-40, -50, -50S, -65, -65S; J3F-50, -50S, -60, -60S, -65, -65S; PA-16, -16S; PA-18, -18A, -18S, -18-105 and -18S-105 (Special), -18-125, 18AS-125, -18S-125, -18-135, -18A-135, 18AS-135, -18-150, -18AS-150, -18S-150, PA-19, -19S; Restricted Category: PA-18A, -18A-135, -18A-150; AR-7, PA-20, -20S, -20-115, -20S-115, -20-135, -20S-135; PA-22, -22-108-135, -150, -160, -22S-135, 22S-150, 22S-160; PA-25, -25-235; T.C. 698, 780, 797, 800, 805, 703, 721, 725, 691, 692, 1A1, 1A2, AR-7, 1A4, 1A6, 2A8, 2A10	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J4, J5, AH-1, HE-1, PA-11, -12, -14, -16, -18, -20, -22 Series; T.C. 691, 740, 725, 780, 797, 1A1, 1A2, 1A4, 1A6	SA1-510	Sur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
J4 Series; T.C. 703	SA4-1130	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
J4 Series; T.C. 703	SA4-1401	McCauley 1A90-CF propeller.	WE	78492	Arthur R. Tillesen 8101 Larsen Street Garden Grove, CA 92600
J4 Series; T.C. 703	SA297WE	McCauley 1A90-CF propeller on Continental C-85-12 engine.	WE	01350	Dwight R. Addigton 409 Serenade Way San Jose, CA 95125
J5 Series; T.C. 725	SA11SW	Removal of outer wing tip bow.	SW	42127	Herring Aircraft Service P.O. Box 1082 Cedar Hill, TX 75104
J5 Series; T.C. 725	SA176CE	Removal of door and installation of placard.	CE	82380	Russell Van Dyke Marceline, MO 64658
J5 Series; T.C. 725	SA320CE	Lycoming O-290-D2 engine and Sensenich M76A-M2/7452 propeller.	CE	05967	Aircraft Service Company 7134 Booth Drive Prairie Village, KS
J5, AE-1, HE-1 Series; T.C. 725	SA4-1080	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
J5A; T.C. A-725	SA305AL	Installation of 13-gallon auxiliary fuel tank. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J5A; T.C. A-725	SA495AL	Installation of Lycoming O-290-D and -D2 engine using Stoddard Model 501 engine mount. Amended 6/27/75.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J5A; T.C. A-725	SA819CE	Install Aero Model M1500, M1800 or M2000 main skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
J5A, J5C; T.C. 725	SA396AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
J5A (Army L-4F), J5A-80, J5B (Army L-4G), J5C, AE-1, HE-1; T.C. A-725	SA3285WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J-5C; T.C. A-725	SA354AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-11; T.C. 691	SA3-47	Extra 17-gallon right wing fuel tank.	CE	17305	Bristow Aircraft Company Bristow, IA 50611
PA-11; T.C. 691	SA4-479	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-11; T.C. 691	SA35AL	Installation of PA-18 flaps. Amended 3/7/67.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-11; T.C. 691	SA323CE	Manufacture hitch and bracket. Install tow hitch. Amneded 5/6/71.	CE	76500	Stubben-McCandless South Omaha Airport, Route 1 Pipillion, NE 68046
PA-11, -11S; T.C. 691	SA501AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-11, -11S; T.C. 691	SA501AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-11, -12, -14, -15, -16, -17, -18, -19, -20, -22, -25; T.C. 691, 780, 797, 800, 1A6, 1A1, 805, 1A2, 1A4, 2A8	SA4-977	Fiberglass rudder post mount for either Grimes or Whelen WRM rotating beacons.	NW	85751	Art Whitaker Pearson Airpark Vancouver, WA 98660
PA-11, -12, -14, -16, -20, -22; T.C. 691, 780, 797, 1A1, 1A4, 1A6	SA573SW	Booster wing tip kit 101-101-250.	SW	81250	Upper Valley Aviation, Inc. P.O. Box 541 McAllen, TX 78501
PA-11; PA-12; PA-14; PA-15; PA-16; PA-17; PA-18, PA-19; PA-20; PA-22, PA-25; PA-23, 23-160, 23-235, 23-250, E23-250; PA-24, -24-250, -24-260, -24-400; PA-28-140, 28-150, -28-160, -28-S-180, -28R-180, -28-180, -28-235, -28-S-160, -28R-200; PA-30, PA-39; PA-31, -31-300, -30P; PA-32-260, -300, -32S-300; T.C. A-691, A-780, A-797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 2A8, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA615EA	Installation of Whelen anti-collision strobe light system. Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
PA-11; PA-12; PA-14; PA-15; PA-16; PA-17; PA-18, PA-19; PA-20; PA-22; PA-25; PA-23, -23-160, -23-235, -23-250, -E23-250; PA-24, -24-250, -24-260, -24-400; PA-28-140, -28-150, -28-160, -28-S-180, -28R-180, -28-180, -28-235, -28-S-160, -28R-200; PA-30, PA-39; PA-31, -31-300, -31P; PA-32-260, -32-300, -32S-300; T.C. A-691, A-780, A-797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 2A8, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
PA-11, -12, -14, -16, -18, -20, -22, -25; T.C. A-691, A-780, A-797, 1A1, 1A2, 1A4, 1A6, 2A8, 2A10	SA2127WE	Installation of Madras Air Service Model 104 wing tips. Amended 3/22/74.	NW	54000	Madras Air Service Route 2, Box 1225 Madra, OR 97741

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-12 Series; T.C. 780	SA1-297	Lycoming O-290-D2 or O-290-D2A engine and Sensenich M76AM-2 fixed pitch metal propeller, diameter 74", pitch 50". Reissued and amended 10/17/77.	NE	20560	Central Maine Flying Service, Inc. DeWitt Field P.O. Box 558 Old Town, ME 04468
PA-12 Series; T.C. 780	SA1-373	Lycoming O-290-D or O-290-D2 engine, Sensenish propeller, PA-18 engine baffles and Harrison oil cooler.	EA	77082	Susquehanna Aero Marine R. 513 Washington Boulevard Williamsport, PA 17701
PA-12 Series; T.C. 780	SA1-522	2024T3 alclad.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-12 Series; T.C. 780	SA4-419	Application of glass cloth over unbleached muslin to all but control surfaces.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
PA-12 Series; T.C. 780	SA4-456	Lycoming C-320 engine and accessories.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
PA-12 Series; T.C. 780	SA4-519	Installation of Lycoming O-320 engine. Reissued 1/12/78.	NW	53250	McKenzie Flying Service 90600 Greenhill Road Eugene, OR 97402
PA-12 Series; T.C. 780	SA4-937	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-12 Series; T.C. 780	SA10EA	Metal covering of fabric wings and optional metallizing of ailerons.	EA	72100	Skycraft Design, Inc. P.O. Box 67 West Trenton, NJ 08628
PA-12 Series; T.C. 780	SA120AL	Installation of auxiliary fuel tank. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12 Series; T.C. 780	SA161WE	Door on left side of airplane.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
PA-12 Series; T.C. 780	SA217WE	Conversion of airplane for parachute jumping and aerial photography operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
PA-12 Series; T.C. 780	SA231AL	Installation of Piper PA-14 wing flaps. Amended 1/15/76.	CE	70308	Rodney E. Schaeffer 1253 Cramer Street Wichita, KS 67212
PA-12 Series; T.C. 780	SA270SO	Water and ice detector in fuel gascolator and carburetor.	SO	71545	Charles B. Shivers, Jr. 8929 Valleybrook Road Birmingham, AL 35206
PA-12 Series; T.C. 780	SA272AL	Installation of a removable structural assembly to replace like structure removed from behind rear seat.	AL	37887	Gil's Aircraft Service P.O. Box 3-4058 Anchorage, AK 99501
PA-12 Series; T.C. 780	SA355AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-12 Series; T.C. 780	SA397AL	Conversion of 4" wheels and brakes to 6" wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99502
PA-12 Series; T.C. 780	SA491AL	Replacement of hammock type seat back rest with removable horizontal tube. Amended 12/6/72.	AL	68250	Kenneth S. Rivard 949 West 72nd Avenue Anchorage, AK 99502
PA-12 Series; T.C. 780	SA493AL	Install leading edge cuff. Amended 3/4/77.	AL	20512	Clinton C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12 Series; T.C. 780	SA543AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12 Series; T.C. 780	SA543AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series; T.C. 780	SA550EA	Installation of Lycoming O-360-D2A engine (168 hp.) and McCauley propeller 1A170-SFA7850.	NE	17071	Lawrence H. Bradway North Windham, ME 04062

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-12 Series; T.C. 780	SA550AL	Installation of modified landing gear (PA-18 type) with main gear legs lengthened 6 inches. Issued 4/30/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. Box 1729C, SRA Anchorage, AK 99507
PA-12 Series; T.C. 780	SA553AL	Installation of O-360 Lycoming engine. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12 Series; T.C. 780	SA555AL	Installation of welded steel rear float fittings. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12 Series; T.C. 780	SA563AL	Installation of Day & Night 2-4 fiberglass and aluminum engine cowling. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
PA-12 Series; T.C. 780	SA563AL	Installation of Day & Night 2-4 fiberglass and aluminum engine cowling. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series (Landplanes Only); T.C. 780	SA564AL	Modification of PA-12 elevator control system forward of fuselage station 181. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622
PA-12 Series (Landplanes Only); T.C. 780	SA564AL	Modification of PA-12 elevator control system forward of fuselage station 181. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series (Landplanes Only); T.C. 780	SA565AL	Installation of aft baggage compartment in PA-12 airplanes. Reissued 5/7/79.	CE	42051	Daivd M. Hendrick Star Route, Box 207B Buffalo, MO 64622
PA-12 Series (Landplanes Only); T.C. 780	SA565AL	Installation of aft baggage compartment in PA-12 airplanes. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series (Normal Category Only); T.C. 780	SA568AL	Installation of a winterization kit. Amended 12/2/75.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12 Series (Normal Category Only); T.C. 780	SA570AL	Installation of square horizontal stabilizer, elevator and rudder. Issued 1/16/76.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12 Series; T.C. 780	SA577AL	Modification of standard pilot seat. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
PA-12 Series; T.C. 780	SA577AL	Modification of standard pilot seat. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series; T.C. 780	SA578AL	Install PA-18 wing flaps on PA-12. Issued 3/26/76.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12; T.C. A780	SA644AL	Install Avco Lycoming O-320-D2A or O-320-B2B engine and McCauley 1A175/GM8246 prop. Issued 7/31/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12; T.C. A780	SA646AL	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12; T.C. 780	SA656AL	Install Avco Lycoming O-320-A2B or O-320-E2D engine and McCauley 1A175/GM 8246 propeller. Issued 11/27/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12; T.C. 780	SA660AL	Installation of extended flaps, flap control system and modified ailerons. Issued 1/9/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
PA-12; T.C. 780	SA660AL	Installation of extended flaps, flap control system and modified ailerons. Issued 1/9/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99501
PA-12 Series; T.C. 780	SA815CE	Installation of skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-12 Series; T.C. 780	SA2038WE	Installation of Lycoming O-320 engine, McCauley 1A170/1C172 and Sensenich M74DM propellers and associated alternator systems. Amended 3/7/74.	NW	61526	Harold G. Nelson 3005 Southwest Marshall Street Pendleton, OR 97801
PA-12 Series; T.C. 780	SA3283WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-12, PA-12S; T.C. 780	SA202EA	Installation of either a Lycoming engine O-290-D (125 HP) or O-290-D2 (135 HP) with Sensenich propeller M74RM. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181, 1216 North Road Lyons, WI 53148
PA-12, -12S; T.C. A-780	SA444AL	Installation of McCauley 1A175/GM propeller. Issued 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-12, -12S; T.C. A-780	SA476AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12, -12S; T.C. A-780	SA476AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA494AL	Installation of electric fuel gauges. Issued 5/1/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -12S; T.C. A-780	SA517AL	Installation of plexiglass skylight on top of cabin. Issued 5/17/74.	AL	27250	Crosswinds, Inc. 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, PA-12S; T.C. 780	SA537AL	Installation of Day & Night 4-1 fiberglass propeller spinner.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12, PA-12S; T.C. 780	SA537AL	Installation of Day & Night 4-1 fiberglass propeller spinner.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA566AL	Installation of Lycoming O-320 engine. Amended 11/25/75.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12, -12S; T.C. 780	SA629AL	Install fiberglass wing tip assembly.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA653AL	Install Avco Lycoming O-320-A2B or C-320-C2B engine and Sensenich 74M6-0-52 propeller. Issued 9/8/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12, -14 Series; T.C. 780, 797	SA5-48	Structure approval only of engine mount assembly on aircraft for use with engines of not more than 363 pounds total installed weight and 170 hp (4 cylinder).	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA5-66	Structural approval only of Fred A. Shaw engine mount and forward fuselage modification for installation of 150 hp engine. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
PA-12, -14 Series; T.C. 780, 797	SA5-66	Structural approval only of Fred A. Shaw engine mount and forward fuselage modification for installation of 150 hp engine. Reissued 5/7/79.	AL	42051	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -14 Series; T.C. 780, 797	SA83AL	Lycoming O-320 Series (150 hp models only) engines and Sensenich M74DM propeller, using Stoddard engine mount 501. Amended 6/12/69.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA148AL	PA-18 main landing gear and installation of EDO 2000 floats. Amended 3/3/69.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA148AL	PA-18 main landing gear and installation of EDO 2000 floats. Amended 3/3/69.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-12, -14 Series; T.C. 780, 797	SA149AL	Installation of auxiliary baggage compartment.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-12, -14 Series; T.C. 780, 797	SA189AL	Install left side cabin door.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA189AL	Install left side cabin door.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA190AL	Increased gross weight to 1935 pounds.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA190AL	Increased gross weight to 1935 pounds.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA213SO	Electric fuel quantity indicator. indicator.	SO	54615	Obed L. Malpass 1502 Morris Road Wilmington, NC 28401
PA-12, -14 Series; T.C. 780, 797	SA289AL	Install rudder centering device.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th PPlace Anchorage, AK 99503
PA-12, -14 Series; T.C. 780, 797	SA2313SW	Install 22-1/2 gallon fuel tank. Issued 5/20/77.	SW	75498	W.L. Stoddard Stoddard Aero Service c/o Plane Booster, Inc. Box 541 McAllen, TX 78501
PA-12, -14, -16, -18, -10; T.C. 780, 797, 1A1, 1A2, 1A4	SA147AL	Electric fuel quantity gauge system.	AL	42158	C.D. Hogan 1831 Lake Otis Parkway Anchorage, AK 99501
PA-12, PA-14, PA-16, PA-18, PA-20, PA-22; T.C. 780, 797, 1A1, 1A2, 1A4, 1A6, AR-7	SA22RM	Manufacture of exact replacement parts, front and rear lift strut assembly. Amended 3/13/79.	RM	50500	Light Plane Components, Inc. 509 Buckley Road Aurora, CO 80011
PA-12, -14, -18; T.C. 780, 797, 1A2	SA215AL	Install L-2500A wheel replacement skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99501
PA-12, PA-14, PA-20, PA-22 Series; T.C. 780, 797, 1A4, 1A6	SA5-60	Installation of Russ Simpson sea fins.	AL	71774	Simpson Airservice, Inc. P.O. Box 2226 Ketchikan, AK 99901
PA-12; PA-22; T.C. A780, 1A6	SA388SO	Metalize wings, wing landing/taxi light installation. Amended 7/2/70.	SO	68550	W.F. Robison Valley Air Service P.O. Box 241 Lanett, AL 36863
PA-12, PA-22, PA-23, PA-28; T.C. 780, 1A6 2A13, 1A10	SA316SO	Carburetor ice detector. Amended 10/5/66.	SO	71545	C.B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
PA-12S; T.C. 780	SA610AL	Install Avco Lycoming O-360-A2A engine. Amended 2/25/77.	AL	20514	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14 Series; T.C. 797	SA1-51	Lycoming O-290-D2 engine with Edo 89-2000 floats, water rudder and seaplane fin.	EA	14775	Arthur E. Barr 387 Eldred Street Williamsport, PA 17701
PA-14 Series; T.C. 797	SA1-573	Lycoming O-320 engine with PA-18A-150 cylinder baffles, Sensenich M74DM propeller and Harrison AP13-SJ03-01 oil cooler.	EA	77082	Susquehanna Aero Marine 378 Eldred Street Williamsport, PA 17701
PA-14 Series; T.C. 797	SA3-106	Edo 89-2000 floats, water rudder and auxiliary tail fin.	GL	61515	Henry E. Neils 2637 27th Avenue South Minneapolis, MN 55401
PA-14 Series; T.C. 797	SA4-78	Lycoming O-320 engine, Sensenich M74DM59 propeller, Piper PA-18A-150 engine cooling baffles modified, Harrison AP13-SJ03-01 oil cooler.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-14 Series; T.C. 797	SA4-81	Lycoming O-290-D2 engine and Sensenich M76AM-2/74-52 propeller.	NW	50900	Marine Air, Inc. Friday Harbor, WA 98250
PA-14 Series; T.C. 797	SA4-410	Lycoming 150 hp engine O-320-A2A.	WE	14960	Bates Aviation, Inc. 940 East 120th Street Hawthorne, CA 90250

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-14 Series; T.C. 797	SA4-411	Modification of fuel system to PA-18 to facilitate takeoff either tank.	WE	14960	Bates Aviation, Inc. 940 East 120th Street Hawthorne, CA 90250
PA-14 Series; T.C. 797	SA4-412	Large PA-18 tail surfaces.	WE	14960	Bates Aviation, Inc. 940 East 120th Street Hawthorne, CA 90250
PA-14 Series; T.C. 797	SA4-561	Application of glass cloth to fuselage and to horizontal and vertical stabilizer.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-14 Series; T.C. 797	SA4-913	Ceconite 101 covering of wings, fuselage and vertical fin.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-14 Series; T.C. 797	SA57NW	Installation of Lycoming O-320-E2D engine, McCauley TM7653 propeller and Lycoming alternator. Issued 3/6/74.	NW	61526	Harold G. Nelson 3005 Southwest Marshall Street Pendleton, OR 97801
PA-14 Series; T.C. 797	SA192AL	Flap handle installation and adjustable fore and aft pilot and co-pilot's seat.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-14 Series; T.C. 797	SA196SW	Hartzell HC-82XL-6F/7636D-4 propeller, Woodward 210080P governor, and Piper 14-733-00 propeller control	SW	71776	J.B. Simpson P.O. Box 126 Gilliam, LA 71029
PA-14 Series; T.C. 797	SA253AL	Installation of McCauley 1A175/GM propeller. Amended 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-14 Series; T.C. 797	SA356AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-14 Series; T.C. 797	SA368AL	Installation of McCauley 1A175/GM8242, GM8244, or GM8246 propellers. Amended 8/18/72.	AL	28660	Daniels & Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-14 Series; T.C. 797	SA378SW	Lycoming O-320 engine, -6-inch wheels, and Piper PA-18 horizontal tail surfaces.	SW	01575	Aerial Repairing P.O. Box 909 Ponca City, OK 74601
PA-14 Series; T.C. 797	SA398AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-14 Series; T.C. 797	SA469AL	Installation of electric fuel gauges. Amended 5/1/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-14 Series; T.C. 797	SA477AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-14 Series; T.C. 797	SA477AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14 and Seaplane Versions; T.C. 797	SA496AL	Installation of leading edge cuff. Amended 3/4/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA502AL	Installation of cargo door in right side of aircraft. Amended 10/31/73.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-14; T.C. 797	SA505AL	Installation of landing gear safety cables. Issued 10/1/73.	AL	30250	F. Atlee Dodge Aircraft Maintenance 2301-1/2 Merrill Field Drive Anchorage; AK 99502
PA-14; T.C. 797	SA528AL	Installation of welded steel rear float fittings. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA534AL	Installation of auxiliary fuel tank. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99503
PA-14; T.C. 797	SA538AL	Installation of modified landing gear (PA-18 type) with main landing gear legs lengthened 6 inches. Issued 1/30/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. 1729C, SRA Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
t+1 PA-14; T.C. 797	SA541AL	Installation of O-360-A2A Lycoming engine and McCauley 1A200 DFA 82-45 propeller. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA546AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-14; T.C. 797	SA546AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA548AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-14; T.C. 797	SA548AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA562AL	Installation of Day & Night 2-4 aluminum engine cowling. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-14; T.C. 797	SA562AL	Installation of Day & Night 2-4 aluminum engine cowling. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA567AL	Installation of O-320-A2B Lycoming engine. Issued 11/21/75.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-14; T.C. A-797	SA598AL	Installation of Day & Night modified flap control system.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-14; T.C. A-797	SA598AL	Installation of Day & Night modified flap control system.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA630AL	Install fiberglass wing tip assembly. Issued 4/28/78.	AL	20512	Cnarles C. Center 8134 LAke Otis Parkway Anchorage, AK 99507
PA-14; T.C. A797	SA645AL	Install Avco Lycoming O-320-D2A or O-320-B2B engine and McCauley 1A175/GM8246 prop. Issued 7/31/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. A797	SA647WE	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA657AL	Install Avco Lycoming O-320-A2B or O-320-E2D engine and McCauley 1A175/GM 8246 propeller. Issued 11/27/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA3213WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avneue Torrance, CA 90501
PA-14, PA-18, PA-20; T.C. 797, 1A2, 1A4	SA41AL	Six inch wheels and brakes.	GL	56570	Wesley W. Mathias 154 North Broad Street Bremen, OH 43107
PA-15; T.C. 800	SA1-619	Continental A-65-8F engine and McCauley 1A90CF-7147 propeller.	NE	39514	Griswold Air Service Griswold Airport Madison, CT 06443
PA-15; T.C. 800	SA4-1225	Eonite covering on complete aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-15; T.C. 800	SA69AL	Installation of fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-15; T.C. 800	SA3214WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-15, PA-17; T.C. 800, 805	SA4-1025	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-16 Series; T.C. 1A1	SA1-577	Installation of Sensenich controllable pitch propeller Model CS3FM4/C374E. Amended 6/24/70.	EA	64268	Theodore J. Peters County Line Road, RD 3 Sommerville, NJ 08876
PA-16 Series; T.C. 1A1	SA4-900	Ceconite 101 covering of wings, fuselage, ailerons, elevator and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-16 Series; T.C. 1A1	SA399AL	Conversion of 4" wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-16 Series; T.C. 1A1	SA412NW	Replace original equipment expander-tube brakes with new Cleveland wheels and brakes. Issued 3/3/77.	NW	00300	Michael J. Abdo 9415 Lexington Avenue, S.W. Tacoma, WA 98498
PA-16 Series; T.C. 1A1	SA3215WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-16, -16S; T.C. 1A1	SA447AL	Installation of auxiliary fuel tanks in right wing. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-16, -16A; PA-18, PA-18S, "105", "125", "135", "150"; "PA-18A"135", "150:"; PA-18AS"125", "135", "150"; PA-19S; PA-23, -23-160, -235, -23-250; PA-24, -24-250, -260; PA-28-140, 150, 160, 180, -235, PA-28-S-160, -S-180; PA-30; T.C. 1A1, 1A2, 1A10, 1A15, A1EA, 2A13	SA630WE	Installation of Coast Winslow Filter Corporation 409 series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-282	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-327	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16S; T.C. 1A1	SA384AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/17/70.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-17 Series; T.C. 805	SA4-483	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-17 Series; T.C. 805	SA446AL	Installation of fuel tanks. Amended 2/7/75.	AL	17000	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-17 Series; T.C. 805	SA3216WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-18 Series; T.C. 1A2	SA388EA	Lycoming O-320 engine.	EA	61075	J. Arlington Myers 228 East Keller Street Castanea, PA 17726
PA-18 Series; T.C. 1A2	SA425AL	Installation of removable seat back support. Issued 4/23/71.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99503
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18 Series; T.C. 1A2	SA526AL	Build up 1-1/4" axle to 1-1/2" axle to install Celveland wheel and brake. Issued 8/7/74.	AL	68436	Bill Robek Box 10-214 Klatt Station ANchorage, AK 99502
PA-18 Series; T.C. 1A2	SA540AL	Installation of modified landing gear with main gear legs lengthened 6 inches. Issued 2/19/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18 Series; T.C. 1A2, AR-7	SA1-32	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
t+1 PA-18 Series; T.C. 1A2, AR-7	SA1-41	McCauley fixed pitch MET-L-PROP 1A170/GM7450, 1A170/GM7452 and 1A170/GM7454 propellers with Lycoming O-320-A1A engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-59	McCauley fixed pitch MET-L-PROP 1A170/GM7448 and 1A170/GM7450 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-155	McCauley fixed pitch MET-L-PROP 1A170/GM7448 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell AVenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-156	McCauley fixed pitch MET-L-PROP 1A170/GM7446 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-349	Glider tow. Amended 5/12/67.	EA	70400	Schweizer Aircraft Corporation Box 147, County Airport Elmira, NY 14902
PA-18 Series; T.C. 1A2, AR-7	SA4-254	Hartzell HC82XG-6/7636D-4 propeller Lycoming 70385 dual drive assembly, Woodward 210115 single acting governor and J-6230-1 lord mount assembly.	WE	15415	Ellen Belotti 1208 East Charleston Road Las Vegas, NV 89114
PA-18 Series; T.C. 1A2, AR-7	SA4-364	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-18 Series; T.C. 1A2, AR-7	SA4-1644	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-18 Series; T.C. 1A2, AR-7	SA5-31	Auxiliary baggage tube.	AL	17000	M.R. Borer 1307 West 39th Place Spenard, AK
PA-18 Series; T.C. 1A2, AR-7	SA4AL	Installation of auxiliary wing fuel tanks. Amended 5/20/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
PA-18 Series; T.C. 1A2, AR-7	SA4RM	Installation of modified landing gear, Cleveland P/N 40-84 wheels and P/N 30-41 brakes. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-18 Series; T.C. 1A2, AR-7	SA17RM	Replace landing gear vee for PA-18 series P/N 10033. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-18 Series; T.C. 1A2, AR-7	SA24EA	Conversion of aircraft for parachute jumping and aerial photography operations.	EA	61075	J. Arlington Myers 331 North Water Street Mill Hall, PA 17751
PA-18 Series; T.C. 1A2, AR-7	SA44AL	Auxiliary wing fuel tanks.	AL	86070	Joseph Wilbur P.O. Box 931 Anchorage, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA50AL	Cowl flaps.	AL	05960	Aircraft Repair & Maintenance Co. P.O. Box 6207 Anchorage, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA70EA	Edo 339JHS amphibious floats.	EA	61622	North American Flying Service, Inc. Bergen Turnpike Little Ferry, NJ 07643
PA-18 Series; T.C. 1A2, AR-7	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Co. airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18 Series; T.C. 1A2, AR-7	SA141AL	Removal of agricultural hatch.	AL	45000	Jake's Aircraft Salvage 3906 Barbara Drive Spenard, AK 99503
PA-18 Series; T.C. 1A2, AR-7	SA143AL	Enlarged instrument panel.	AL	30250	F.A. Dodge P.O. Box 6409 Anchorage, AK 99506
PA-18 Series; T.C. 1A2, AR-7	SA150AL	Installation of cockpit operated cowl flap winterization kit. Reivsed 7/29/69.	AL	39400	Charles L. Gray 319 Slater Street Fairbanks, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA230EA	Flottorp controllable pitch propeller.	EA	11730	Arnold Air Service Dale & Mackey Road, RD 2 Gasport, NY 14067
PA-18 Series; T.C. 1A2, AR-7	SA234SW	Alteration of method of attaching spray plates and dust spreader to spray tank and alteration of emergency dump cable hookups.	SW	42480	John L. Horne, Jr. P.O. Box 218 Webbers Falls, OK 74470
PA-18 Series; T.C. 1A2, AR-7	SA284SW	Landplane lower cowl on aircraft with Edo 89-2000 floats.	SW	72752	Slidell Aviation Services Route 2, Box 99 Slidell, LA 70458
PA-18 Series; T.C. 1A2, AR-7	SA324CE	Manufacture hitch and bracket. Install tow hitch. Amended 5/6/71.	CE	76500	Stubben-McCandless South Omaha Airport Route 1 Papillion, NE 68046
PA-18 Series; T.C. 1A2, AR-7	SA569SW	Cessna 172 landing gear.	SW	61100	Myhand and Deam Aircraft Route 5, Box 505 Pine Bluff, AR 71601
PA-18 Series; T.C. 1A2	SA894WE	Lycoming O-320-A2B engine and Sensenich M74DM-56 propeller.	RM	35770	Sam B. Flint P.O. Box 332 Holly, CO 81047
PA-18, PA-18A; T.C. 1A2, AR-7	SA4-1430	125-gallon hopper and small swathmaster. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-18, PA-18A; T.C. 1A2	SA1243CE	Install Cleveland wheels and brakes and optional wheel fenders. Amended 9/29/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, -18A; T.C. 1A2	SA1244CE	Replace landing gear components. Issued July 1976.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, PA-19; T.C. 1A2, AR-7	SA3-180	C2200 main (hydraulically actuated) and CTF2200 or CT3000 tail skis.	GL	36030	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA3-328	C-2200 main (manually actuated) and AWT2500 or AWT2500A tail wheel-skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA3-352	Model 3000 main skis and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA4-823	Eonite covering on entire aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-18, PA-19; T.C. 1A2, AR-7	SA4-986	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-18, PA-19, PA-20; T.C. 1A2, 1A4	SA3-423	CT-3000 tail ski on airplanes with Scott 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-20, PA-22; T.C. 1A2, AR-7, 1A4, 1A6	SA3-654	Laminated plastic and fiberglass nose.	RM	28500	Dakota Aviation Company P.B. Box 18 Huron, SD 57350
PA-18, PA-22, PA-23, PA-24 Series; T.C. 1A2, 1A6, 1A10, 1A15	SA1-383	Lube oil filter PB 55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
PA-18, -22, -23, -24, -25, -28 Series; T.C. 1A6, 1A2, AR-7, 1A10, 1A15, 2A13	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace AVenue Torrance, CA 90510

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18, PA-25; T.C. 1A2, AR-7, 2A8	SA673SW	All metal covering of aileron.	SW	60168	Luther W. Moore 1110 West 29th Street Plainview, TX 79072
PA-18, 90 thru 150; T.C. 1A2	SA753CE	Installation of skis.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
PA-18, -18A, -105, -125, -135, -150, 18A-135, -150; T.C. 1A2	SA400AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	GL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-18, -18"105", -18A, -18"125", -18"135", -18A-"135", -18"150", -18A-150, -19 and seaplane versions; T.C. 1A2	SA427AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65662
PA-18, -18"105", -18A, -18"125", -18"135", -18A-"125", -18"150", -18A-150, -19 and seaplane versions; T.C. 1A2	SA427AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18, -18A, -18-105, -18-125, -18-135, -18A-135, -18-150, and seaplane versions; T.C. 1A2	SA489AL	Installation of modified dog leg brace baggage compartment. Issued 10/24/72.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-18, -18-105, -125, -135, -150, PA-18S, -18S-105, -125, -135, -150, PA-18A, -18A-135, -150, PA-18AS-125, -135, -150, PA-19, PA-19S; T.C. 1A2	SA624AL	Install fiberglass wing tip assembly. Issued 3/21/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, PA-18-105, -125, -135, -150, PA-18S, PA-18S-105, -125, -135, -150, PA-18A, -18A-135, -150, PA-18AS-125, -135, PA-19, PA-19S; T.C. 1A2	SA638AL	Fabricate rudder mounted strobe light support bracket. Issued 6/14/78.	AL	30250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18, -18-105, -125, -135, -150, PA-18, -18-105, -125, -135, -150, PA-18A, -18A-125, -18A-135, -150, PA-18AS-125, -135, -150; T.C. 1A2	SA641AL	Fabricate front wing spar butt attachment repair fitting. Issued 7/10/78.	AL	20514	Clinton C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, -18"105" Special, -18A, -18"125", -18"135", -18A"135", -18"150", -18A"150", -19; T.C. 1A2	SA900CE	Replace round wing tips with constant-chord, square tips and wing splates. Amended February 1975.	CE	35650	James W. Flanagan and Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18, -18A, PA-19; T.C. 1A2	SA1245CE	Installation of Scott master cylinder having Flanagan Aircraft conversion. Amended 6/22/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, -18A, -18-105, -18-125, -18-135, -18-150, -18A-150, PA-19; T.C. 1A2	SA2478WE	Installation of automatic flagman Model 5. Issued 2/14/72.	NW	03500	Air-Ag, Inc. Route 4, City County Airport Walla Walla, WA 99362
PA-18, -105, -125, -135, -150; T.C. 1A2	SA5-7	Install framing and seat in baggage compartment. Amended 7/25/68.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99501
PA-18, -18-105, -125, -135, -150, PA-18A-125, -135, -150; PA-19; T.C. 1A2	SA301AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99501
PA-18, -18"105", -18A, -18"125", -18"135", -18A"135", -18"150", -18A"150", PA-19 (Army L-18C); T.C. 1A2	SA3282WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18, -18S, -18-135, -18S-135, -18A-135, PA-18-105 (Special), PA-18S-105 (Special), PA-18-150, -18A-150, -18S-150; T.C. 1A2	SA490AL	Installation of leading edge cuff. Reissued 2/20/76.	AL	24512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, -18S, -18"105", "125", "135", "150", -18A, "135", "150", -18S"105", "125", "135", "150", PA-19, -19S, PA-22, -22-108, -135, -150, -160, -22S-135, -150, PA-24, -24-250, -260; T.C. 1A2, 1A6, 1A15	SA1033EA	Replace steel oil cooler lines with Aeroquip type 303-8 hose using AN-823-8D elbows, AN-816-8D nipples and AN-321-8 hose fittings. Issued 1/29/76.	EA	76472	Walter Thompson, Sr. 32 High View Avenue Florida, NY 10921
PA-18, -18-125, -18-135, -18-150; PA-19; T.C. 1A2	SA2468WE	Use of GCA-600 axle adapter assembly for installation of Cleveland Model 40-84A wheels and Model 30-41 brakes. Issued 1/20/72.	WE	15435	Ken Bemis Brawley Municipal Airport P.O. Box 1293 Brawley, CA 92227
PA-18A; T.C. 1A2	SA681AL	Installation of removable crossbar. Issued 1/10/80.	AL	30250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18A; T.C. 1A2	SA886CE	Metalize bottom of fuselage per Flanagan Aircraft Drawing List No. 2. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A; T.C. 1A2	SA887CE	Removal of hopper cover and installation of Lexan skylight and side windows. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A; T.C. 1A2	SA888CE	Relocation of battery box and/or installation of an external power receptacle. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A, -18A-135, -18A-150; T.C. 1A2	SA5-29	Install third seat in baggage compartment and relocate battery aft of baggage compartment. Amended 7/25/68.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99503
PA-18A, PA-18A"135"; -18A"150"; T.C. 1A2	SA1369CE	Electrical system and instrument panel modification. Issued 9/28/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18S, -19S, -18S"105" (Special), -18S"125" -18S"135"; T.C. 1A2	SA3-96	Install Pee-Kay Model 1500 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-105, 18S-105, -125, 18S-125, -18AS-125, 18-135, 18S-135, 18A-135, -18AS-135; T.C. 1A2	SA136AL	Installation of Lycoming O-320 engine. Amended 5/14/68.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-105, -18S-105, -18-125, -18A-125, -18AS-125, -18A-135, -18S-135, -18AS-135; T.C. 1A2	SA292AL	Increased gross weights to PA-18-150 weights and C.G. envelope. Note: Airplanes must have Lycoming O-320 engine installed, except the PA-18-135 or PA-18-135 for which the engine change is optional. Amended 5/5/72.	AL	17000	W.T. Ellis and M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-105, -125, -135, -150, -18S, -105, -125, -135, -150, -18A-135, -150, -18AS-125, -135, -150, PA-16, PA-16S, PA-19S, PA-22, -108, -125, -150, -160; PA-23, -160, -250; PA-24, -250; PA-24-400; PA-28-160, -235; PA-30; T.C. 1A6, 1A10, 1A15, 2A13, A1EA	SA589WE	Installation of full-flow lube oil filters on the aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court San Leandro, CA 94577
PA-18S, PA-18S"105", -18S"125", -18AS"125", -18S"135", -18AS"135", PA-19S; T.C. 1A2	SA159CE	Installation of Pee-Kay Model 1800 floats. Reissued 6/12/74.	EA	29998	Pee-Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18-125; T.C. 1A2	SA669CE	Install Aqua Model 1900 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Reserach and Engineering, Inc. 805 Geiger Road Zephyrhills Hills, FL 33599
PA-18-125, -18A, -18-135, -18A-135, -18-150, -18A-150, 18S-125, -18AS, -18S-135, -18AS-135, -18S-150, -18AS-150, T.C. 1A2	SA98AL	Installation of two auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-18-125, -135, -150, -18S-125, -135, -150, 18A-135, -150, 18AS-135, -150; T.C. 1A2	SA117AL	Installation of Cunningham auxiliary fuel belly tank. Amended 9/16/68.	AL	08472	Airglas Engineering Co., Inc. P.O. Box 4165 Anchorage, AK 99502
PA-18-125, PA-18-135, PA-18A-135; T.C. 1A2	SA388EA	Installation of Lycoming O-320, O-320-A2A or O-320-A2B engine (150 hp) and Sensenich propeller M74DM-56 configuration I. Increase in maximum allowable gross weight and C.G. limits as per Model PA-18-150 values - configuration II. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-18S-125; T.C. 1A2	SA2397WE	Installation of McCauley Model 1A175-GM/8240 propeller. Issued 10/27/71.	NW	09300	Kenneth R. Alexander 1732 Northwest 64th Seattle, WA 98107
PA-18S"125", PA-18S-135, 18S-150; T.C. 1A2	SA879EA	Installation of Edo Model 88A-1650 seaplane floats with Edo Model 088A21 attachment gear. Reissued 4/1/76.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
PA-18S-125, -150; T.C. 1A2	SA1099WE	Install fiberglass reinforced plastic floats. Reissued 9/20/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
PA-18-135; T.C. 1A2, AR-7	SA1-33	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine. Amended 9/5/75.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-18-135, -18A-135, -18S-135, -18AS-135, -18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA279AL	Installation of McCauley 1A175/GM propeller on -135 models listed and installation of McCauley 1A175/GM 8241 through GM 8244 on the -150 models listed. Amended 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-135, -18A-135, -18-150; T.C. 1A2	SA518CE	Install Aqua Model 1900 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research and Engineering, Inc. 805 Geiger Road Zephryhills, FL 33599
PA-18"135", -18A"135", -18S-"135", -18AS"125", -18"150", -18A-"150", -18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622
PA-18"135", -18A"135", -18S-"135", -18AS"135", -18"150", -18A-"150", '18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1333CE	Installation of replacement engine mount. Issued June 1977.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1366CE	Installation of a third seat, removable cross member, and reinforced baggage compartment floor. Issued 8/26/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18-135, -150, PA-20, PA-22, PA-23, PA-24 less 24-180, -24-280, -24-400, PA-25, PA-28 less -28-140, PA-28-180, -235, PA-30, PA-31, PA-32, PA-34, PA-39; T.C. 1A2, 1A4, 1A6, 1A10, 1A15, 2A8, 2A10, 2A13, A1EA, A8EA, A3SO, 1A10, A1EA	SA1512WE	Installation of exhaust gas temperature monitoring system Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18-135, -150, PA-22, PA-23, PA-24, -24-400, PA-28, -28-235, PA-30, PA-31, PA-32; T.C. 1A2, 1A6, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18A-135, PA-18A-150; T.C. 1A2	SA1368CE	Cabin metalization; installation of new boot cowl, firewall, swing up side windows, larger baggage door, and inspection access in aft fuselage. Issued 9/12/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18S-135; T.C. 1A2	SA288AL	Install McCauley 1A175-GM8040 or 1A175-GM8044 propeller. Amended 4/2/69.	GL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645
PA-18-150; T.C. 1A2	SA36RM	Installation of Lycoming O-360-C2A or O-360-A3A 180 hp engine. Issued 11/22/74.	RM	46780	David C. Johnson 10850 Thomas Road Colorado Springs, CO 80908
PA-18-150; T.C. 1A2	SA532AL	Installation of Lycoming O-360-A2A engine. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150"; T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-18"150"; T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18-150; T.C. 1A2	SA590AL	Install extended baggage compartment. Issued 7/2/76.	AL	39250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18-150; T.C. 1A2	SA596AL	Install Hartzell propeller Model HC-C2YL-1BF/F8468-8R. Issued 3/4/77.	AL	30250	Atlee R. Dodge P.O. Box 6409 Anchorage, AK 99509
PA-18-150; T.C. 1A2	SA612AL	Extended ailerons. Issued 5/25/77.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18"150", -18A"150", -18S"150", -18AS"150"; T.C. 1A2	SA4-1143	Installation of Lycoming O-320-A3B engine and Hartzell HC-82XL-6B/7636D-2 propeller. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
PA-18"150", -18A"150"; T.C. 1A2	SA92NW	Installation of Lycoming O-360-A2D engine, McCauley 1A200-FA8241 propeller, and associated sub-systems. Issued 3/1/74.	NW	32756	Ed's Aviation Service P.O. Box 156 Arlington, WA 98223
PA-18"150", -18A"150"; T.C. 1A2	SA109CE	Installation of Pee-Kay Model 1800 flcats. Reissued 6/12/74.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-150, -18A-150; T.C. 1A2	SA349AL	Installation of McCauley 1A175-GM 8242, GM8244, or GM8246 propeller. Amended 4/10/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-18-150, -18A-150; T.C. 1A2	SA353AL	Installation of Sorensen Aircraft Co. 60-gallon belly tank. Revised 2/12/71.	AL	76900	Superior Airmotive of Alaska, Inc. 2301 Merrill Field Drive Anchorage, AK 99501
PA"18"150", PA"18A"150"; T.C. 1A2, AR-7	SA575WE	Belly master spray system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-18-150, -18A-150; T.C. 1A2	SA589AL	Install square horizontal stabilizers, elevators, and rudder. Issued 6/28/76.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA284AL	Installation of Hartzell propeller with Woodward 2100-80-RS governor. Amended 10/30/75.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA510AL	Installation of "Summer-all defroster valve". Issued 1/10/74.	AL	76738	Sumrall & Tears 3001 Yale Drive Anchorage, AK 99504
PA-18"150", PA-18S"150"; T.C. 1A2	SA648AL	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150", PA-18A"150", PA-18S"150", PA-18AS"150"; T.C. ·1A2	SA649AL	Fabricate 30.5 gallon wing fuel tanks. Issued 8/17/78.	AL	30250	F. Atlee Dodge Box 4609 Anchorage, AK 99502
PA-18A-150; T.C. 1A2	SA623AL	Install wing tip assembly.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18A"150"; T.C. 1A2	SA1370CE	Revised fuel gaging and dual fuel feed line installation from both tanks. Two wing fuel tanks standard. Issued 11/18/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18S-150, 18AS-150; T.C. 1A2	SA392AL	Installation of McCauley 1A175 GM8242, 8244, or 8246 propeller. Amended 9/24/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-20 Series; T.C. 1A4	SA1-89	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engines.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-20 Series; T.C. 1A4	SA1-157	McCauley fixed pitch MET-L-PROP 1A170/GM7450 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-20 Series; T.C. 1A4	SA1-167	Lycoming O-320 150 hp engine, Sensenich M-74DM propeller, Piper PA-22-150 engine baffles, and and Harrison AP13SJ03-01 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamsport, PA 17701
PA-20 Series; T.C. 1A4	SA4-564	Eonite covering on wings, fuselage and control surfaces.	WE	52090	William C. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
t+1 PA-20 Series; T.C. 1A4	SA4-778	Ceconite covering.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-20 Series; T.C. 1A4	SA12RM	Installation of Light Plane Components landing gear vee assembly, P/N LPC 1012. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-20 Series; T.C. 1A4	SA31CE	Removal of rear left door and installation of placard.	CE	50725	Lincoln Sport Parachute Club, Inc. 929 Furnas Avenue Lincoln, NE 68501
PA-20 Series; T.C. 1A4	SA73CE	Covering with dacron of wings, fuselage, tail group, flaps, all control surfaces, or any of these individually.	GL	30518	Downer Aircraft Company P.O. Box 46 Alexandria, MN 56308
PA-20 Series; T.C. 1A4	SA211WE	Removal of left-hand cabin door for parachute jumping and aerial photography operations.	RM	38040	Glacier View Skyways, Inc. P.O. Box 252 Kalispell, MT 59901
PA-20; T.C. 1A4	SA224GL	Install Gerdes control wheels, Model No. A-1561-C and A-1562-C utilizing AN3-12 bolts (2), AN3-65 self-locking nuts (2) and AC-940-316 washers(2). Issued 2/15/78.	GL	64950	Matthew C. Poleski 25 Immelman Lane Hampshire, IL 60140
PA-20 Series; T.C. 1A4	SA278WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-20 Series; T.C. 1A4	SA509AL	addition of crankcase relief valve. Issued 11/16/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-20 Series; T.C. 1A4	SA542AL	Installation of leading edge cuff. Amended 3/4/77.	AL	27250	Crosswinds, Inc. 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20 Series; T.C. 1A4	SA671WE	BN-1 propeller spinner.	WE	75250	Raymond M. Stits 3665 Rubidoux Boulevard Riverside, CA 92502
PA-20 Series; T.C. 1A4	SA3217WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-20, PA-20-115, -20-135; T.C. 1A4	SA12AL	Installation of auxiliary fuel tank(s). Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2350 East Fifth Avenue Anchorage, AK 99501
PA-20 Landplane, -20-115, -135; T.C. 1A4	SA25EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lycons, WI 53148
PA-20, -20S; T.C. 1A4	SA125AL	Installation of squared off wing tips and end plates. Amended 12/1/65.	AL	61640	Northland Aviation P.O. Box 3143 Fairbanks, AK 99702
PA-20-115, -135; T.C. 1A4	SA401AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-20, -20S, -20"115". -20S-"115", -20-"135", -20S-"135"; T.C. 1A4	SA479AL	Installation of fiberglass wing tips. Issued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-20, -20S, -20"115", -20S-"115", -20-"135", -20S-"135"; T.C. 1A4	SA479AL	Installation of fiberglass wing tips. Issued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-20, -20-115, -135, PA-20S, -20S-115, -135; T.C. 1A4	SA626AL	Install fiberglass wing tip assembly. Issued 3/21/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20, -115, -20S, -20S-115, -135, -20S-135; PA-22, -135, 22S-135, -150, 22S-150, -160, 22S-160, -108; PA-24, -250, -400, -260; PA28-140, -150, -160, -180, -235, S-160, S-180, R-180; PA-30; PA-32-260, -300, 32S-300; T.C. 1A4, 1A6, 1A15, 2A13, A1EA, A3SO	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
PA-20, PA-20"115", -"135", PA-20S"115", -"135", PA-22, 22-108, -135, -150, -160, 22S-135, -150, -160; T.C. 1A6	SA2142WE	Installation of DASCO heated pitot tube kit No. 2022-12.	WE	30129	Diversified Aviation Service Co. 20499 Santa Maria Avenue Castro Valley, CA 94546
PA-20, PA-20-"135"; T.C. 1A4	SA635AL	Install Avco Lycoming O-320-A2B engine and Sensenich propeller. Issued 6/6/78.	EA	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20-115, -20-135; T.C. 1A4	SA71GL	Installation of P/N BA4106 filter assembly. Issued 12/29/77.	WE	17062	Brackett Aircraft Specialties Co. 4910 East Falcon Drive Mesa, AZ 85205
PA-20-135; T.C. 1A4	SA1-24	McCauley fixed pitch MET-L-PROP Models 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine. Reissued 8/5/77.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-20S, PA-20-115, -22-135; T.C. 1A4	SA118GL	Installation of Huron Aviation Products alternator, P/N 10346 and regulator, P/N 10316. Amended 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-20S, 20S-115, 20S-135, PA-20S*; T.C. 1A4	SA385AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/21/70. *This approval includes PA20S models with Lycoming O-320, 150 hp engine installed per an appropriate STC.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-20S, -20S*, -115*, -135*; T.C. 1A4	SA387AL	Installation of McCauley 1A175GM8241 propeller. Issued 7/23/70. *Aircraft must be equipped with Edo 88-1650 floats and modified in accordance with STC SA1-167.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20S-115, -125; T.C. 1A4	SA388AL	Installation of Edo 88-1650 floats (Spec item 209(a)) when modified per STC SA1-167 and SA387AL. Issued 8/3/70.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20, PA-22 Series; T.C. 1A6	SA1-132	24ST alclad on wings.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-20, PA-22 Series; T.C. 1A6	SA1-133	24ST alclad skin on flaps.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-20, PA-22 Series; T.C. 1A6	SA1-325	Replacement of fabric covering with metal skins, ailerons and flaps.	EA	72100	Skycraft Design, Inc. P.O. Box 67 West Trenton, NJ 08628
PA-20, PA-22 Series; T.C. 1A6	SA1-492	Metallizing of wing panel excluding aileron and flap.	NE	27770	Custom Aircraft Industries 30 Broad Street Pascoag, RI 02859
PA-20, PA-22; T.C. 1A4, 1A6	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
PA-20, PA-22 Series; T.C. 1A6	SA1487WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA1-22	McCauley fixed pitch propellers 1A170/GM7459 and 1A170/GM7457 with Lycoming O-320 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-23	McCauley fixed pitch propellers 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-90	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-108	69A110 gyro stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
PA-22 Series; T.C. 1A6	SA1-128	Dry vacuum pump 113A1 for counter-clockwise engine accessory drive and 113A2 for clockwise drive, or 10-113-1 and 10-113-2.	GL	66380	Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
PA-22 Series; T.C. 1A6	SA1-131	Dural angles and 24ST alclad skin on fuselage.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-22 Series; T.C. 1A6	SA1-255	Dart I-M turn control unit.	EA	61400	Navigation Devices, Inc. P.O. Box 1107 Binghamton, NY 13902
PA-22 Series; T.C. 1A6	SA1-275	Lycoming O-320 150 hp engine and Sensenich M74DM propeller, Piper PA-22-150 engine baffles, Harrison AP138J03 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamport, PA 17701
PA-22 Series; T.C. 1A6	SA1-337	Oil-free vacuum pump PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-22 Series; T.C. 1A6	SA1-386	Installation of heated pitot tube.	EA	34180	Federal Aviation Administration Engineering & Manufacturing Branch Federal Building, EA-210 JFK International Airport Jamaica, NY 11430
PA-22 Series; T.C. 1A6	SA3-77	Vertical fin plates attached to tip ribs of horizontal stabilizer for seaplane operation only.	GL	60092	Modern Die & Tool Company 227 Iron Street Detroit, MI 48233
PA-22 Series; T.C. 1A6	SA3-143	Grimes D7080-12 rotating beacon on fuselage access panel.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22 Series; T.C. 1A6	SA3-363	Installation of Doyn fiberglass wheel fairings. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
PA-22 Series; T.C. 1A6	SA3-382	Manually operated oil cooler shutter assembly.	CE	65020	Ken L. Potter 13831 Botts Road Grandview, MO 64030
PA-22 Series; T.C. 1A6	SA3-477	C2200 (hydraulically actuated) main and AWN1200A nose wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-22 Series; T.C. 1A6	SA3-494	C2200 (manually actuated) main and AWN1200A nose wheel -skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-22 Series; T.C. 1A6	SA3-631	Dacron cover.	GL	30518	Downer Aircraft Industries, Inc. Municipal Airport Alexandria, MN 56308
PA-22 Series; T.C. 1A6	SA3-639	Removal of rear door, operation with door removed, and reinstallation of door.	CE	50715	Lincoln Aviation Inst., Inc. P.O. Box 4168, Havelock Station Lincoln, NE 68529
PA-22 Series; T.C. 1A6	SA4-114	Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-22 Series; T.C. 1A6	SA4-222	Fiberglass covering.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
PA-22 Series; T.C. 1A6	SA4-298	Fuselage structural alterations and additions to provide for the installation of Fairchild Aviation aerial camera A5A or similar.	WE	62063	Pacific Aero Industries Municipal Airport San Jose, CA 95125
PA-22 Series; T.C. 1A6	SA4-343	"B" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-22 Series; T.C. 1A6	SA4-391	Fiberglass wheel fenders.	NW	85550	Art Whitaker Pearson Field Vancouver, WA 98660
PA-22 Series; T.C. 1A6	SA4-423	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA4-815	Lycoming O-320 engine and Sensenich M74DM propeller.	NW	53200	McKenzie Aircraft Repair 1300 North 27th Street Springfield, OR 97477
PA-22 Series; T.C. 1A6	SA4-871	Aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-22 Series; T.C. 1A6	SA4-903	Ceconite 101 covering of fuselage, wings, horizontal and vertical stabilizer, ailerons, flaps, rudder and elevator.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-22 Series; T.C. 1A6	SA4-938	Eonite covering on entire aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-22 Series; T.C. 1A6	SA4-998	Installation of wheel fairings. Reissued 2/9/71.	NW	12565	Aurora Air, Inc. d/b/a Madras Air Service Madras, OR 97741
PA-22 Series; T.C. 1A6	SA4-1346	Fiberglass cover on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
PA-22 Series; T.C. 1A6	SA4-1502	AB-6564 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-22 Series; T.C. 1A6	SA4-1587	Retractable wheel fairing on main landing gear.	WE	30708	Duce Aircraft Company R.R. 4, Box 711 Valley Center, CA 92082
PA-22 Series; T.C. 1A6	SA4-1621	Removal of left-hand door for parachute jumping and aerial photography.	WE	19856	Capitol Sky Park, Inc. Municipal Airport Sacramento, CA 95855
PA-22 Series; T.C. 1A6	SA5-30	Rear door removed.	AL	69740	Safeway Airways P.O. Box 1062, Merrill Field Anchorage, AK 99500

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22 Series; T.C. 1A6	SA48AL	L1650A or L2000A skis.	AL	08125	Airglas Engineering P.O. Box 1254 Anchorage, AK 99502
PA-22 Series; T.C. 1A6	SA60CE	Model 1800 floats installed, Pee-Kay. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-22 Series; T.C. 1A6	SA91AL	Change of brake system to disc type as used on PA-22-108 by changing brake parts.	AL	75500	Stoddard Aero SErvice 2550 East Fifth Avenue Anchorage, AK 99501
PA-22 Series; T.C. 1A6	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743
PA-22 Series; T.C. 1A6	SA143EA	Univair Aeromatic F-200H/0074E propeller on aircraft utilizing Lycoming O-320 or O-320-A1A engine.	EA	53160	George A. McIntosh 435 Van Cortlandt Park Avenue Yonkers, NY 10705
PA-22 Series; T.C. 1A6	SA145CE	APU receptacle under the right front seat to the right of battery box.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis, MO 63155
PA-22 Series; T.C. 1A6	SA157CE	Jump seat baggage compartments.	CE	14270	Baker's Flying Service, Inc. 1025 Lou Holland Drive Municipal Airport Kansas City, MO 64108
PA-22 Series; T.C. 1A6	SA247SO	Removal of door during operation of aircraft.	SO	43260	W.E. Huckabee, Jr. 424 South Green Street Thomaston, GA 30286
PA-22 Series; T.C. 1A6	SA314SO	Lycoming O-290-D engine.	SO	54450	M & M Flyers Bessemer, AL 35020
PA-22 Series; T.C. 1A6	SA447WE	Torsc tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
PA-22 Series; T.C. 1A6	SA448CE	Prestolite ALX-5000 alternator.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
PA-22 Series; T.C. 1A6	SA461WE	Removal of right-hand door for parachute jumping and aerial photography operations.	NW	42138	Hillsboro Aviation Hillsboro, OR 97123
PA-22 Series; T.C. 1A6	SA481WE	Lycoming O-320-A1A engine and Sensenich M74DM propeller.	RM	47758	Kensair Corporation P.O. Box 332 County Airport Broomfield, CO 80020
PA-22 series; T.C. 1A6	SA666WE	Edo 88-1650 floats with Harrison oil cooler AP13SJ03-01 or AP12CU03-01, bottom engine cowl assembly 13159-8, side engine cowl 14237, reinforced fuselage 12480 and Sensenich M74DM or M76AM-2 propellers.	NW	36002	Floathaven Seaplane Base 2095 South Lake Whatcom Boulevard Bellingham, WA 98225
PA-22 Series; T.C. 1A6	SA819SW	Extended wing and fuselage.	SW	71776	Simpson Aviation Company P.O. Box 126 Gilliam, LA 71029
PA-22 Series; T.C. 1A6	SA1360CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, MO 66103
PA-22, PA-22-108, -135, -150, -22S-150, -22-160, -22S-160; T.C. 1A6 t+1	SA1-604	Installation of Aerostat external power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-22, -22-108 (Normal Category Only - All Models), -22-135, -150, -160; T.C. 1A6	SA45RM	Conversion from tri-cycle landing gear (nose wheel) to conventional landing gear (tail wheel). Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-22, PA-22-108, -135, -150, -160; T.C. 1A6	SA232GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA625AL	Install fiberglass wing tip assembly. Issued 3/27/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22, -22-135; T.C. 1A6	SA1-274	Installation of Lycoming O-320 (150 hp) series engine and Sensenich M74DM propeller. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22, -22-108, -22-135, -22-150, -22-160, -22S-150, -22S-160; T.C. 2A6	SA536AL	Installation of auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-22, -22-135, -150, -160; T.C. 1A6	SA26EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-108, -135, -22S-135, -22-150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA40EA	Wet-to-dry vacuum pump conversion kit 300-1. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-22, -22-108 (Normal Category only - all models), -22-135, -22-150, -22-160; T.C. 1A6	SA181RM	Installation of Lycoming Model O-360-A4A engine and Sensenich Model 76EM8-60 propeller. Issued 8/2/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-108; T.C. 1A6	SA847EA	Installation of Lycoming O-320-A (150 hp) or O-320-B (160 hp) engine. Amended 4/7/78.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-108, -135, -150, PA-23, -23-250, PA-24, -24-250, -260, -400, PA-28-140, -150, -160, -180, -235, PA-30; T.C. 1A6, 1A10, 1A15, 2A13, A1EA	SA1202WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
PA-22-135; T.C. 1A6	SA3-709	Install Piper control modification kit, P/N 754-174.	GL	51770	Richard E. Lloyd Lloyd Flying Service Schaumburg Airport, Box 79B Roselle, IL 60172
PA-22-108, -135, -150, -160 (landplane only - normal category only); T.C. 1A6	SA4-1263	Installation of conventional landing gear. Reissued and amended 12/4/79.	WE	52543	Lucas Aircraft 1125 Terrace Drive Napa, CA 94558
PA-22-150; T.C. 1A6	SA545AL	Installation of leading edge cuff. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-150; T.C. 1A6	SA703CE	Install aileron and wing fences and booster tips per STC SA573SW. Issued 5/19/70.	GL	22210	Dr. Edward W. Chrencik 29 9th Avenue North Hopkins, MN 55343
PA-22S-150; T.C. 1A6	SA297AL	Installation of McCauley 1A175 GM8241 propeller.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-22-160; T.C. 1A6	SA95NW	Installation of Lycoming O-360-A1A engine, McCauley 1A200-FA8248 propeller, and associates subsystems. Issued 3/11/74.	NW	61680	Northwest Aero Aircraft Services 2036 West Bakerview Road Bellingham, WA 98225
PA-22, PA-23, PA-24 Series; T.C. 1A6, 1A10, 1A15	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ 85642
PA-23 Series; T.C. 1A10	SA1-5	Unfeathering system change to HC-82XL-2/7636D-4 or HC-A2XL-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA1-6	Unfeathering system change to HC-82XG-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
PA-23 Series; T.C. 1A10	SA1-28	Radio rack limited to 30 pounds of radio equipment.	GL	03600	Airborne Communications, Inc. Lunken Airport Cincinnati, OH 45275
PA-23 Series; T.C. 1A10	SA1-53	Conversion to Goodyear 6.50-8 wheels (9531319) and brakes (9531779).	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-103	Radio-shelf.	GL	72494	Skyways, Inc. P.O. Box 175 Vandalia, OH 45377
PA-23 Series; T.C. 1A10	SA1-117	Propeller anti-icing kit.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA1-120	F-300 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
PA-23 Series; T.C. 1A10	SA1-137	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA1-169	Reinforcement of floor structure between fuselage station 91-1/2 and 123-3/4 and provision for tie-down facilities.	GL	60485	A.E. Muhlhauser 1602 Emerson Avenue (N.C.H.) Cincinnati, OH 45275
PA-23 Series; T.C. 1A10	SA1-177	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-399	Oil-free vacuum PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-23 Series; T.C. 1A10	SA1-468	Six or 13 quart propeller anti-icing kit WAP-101A, revision 2.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA1-484	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-485	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-534	Lightweight reservoir type deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-548	SP-3 autopilot EB2597034.	EA	74590	Sperry Rand Corporation MacArthur Field Ronkonkoma, NY 11779
PA-23 Series; T.C. 1A10	SA1-586	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-23 Series; T.C. 1A10	SA3-94	Narco 1016 antenna and/or remote compass transmitter, equipment shelf, oxygen bottle mounting.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705
PA-23 Series; T.C. 1A10	SA3-158	Radio power pack on bulkhead forward of instrument panel.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705
PA-23 Series; T.C. 1A10	SA3-334	Installation of aerial camera provisions. Reissued 1/31/80.	SW	26230	Cooper Airmotive Aircraft Services 3300 Love Field Drive Dallas, TX 75235

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-handy hydrotrim aileron trim device.	GL	30465	Kingsley A. Doutt 115 West Maple Street Alpena, MI 49707 AND
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-hand hydrotrim aileron trim device.	GL	64262	Charles L. Petch Hubbard Lake, MI 49747
PA-23 Series; T.C. 1A10	SA3-509	L-2B autopilot with or without altitude control and approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-23 Series; T.C. 1A10	SA3-564	Propeller unfeathering accumulator.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA3-641	Cabin air temperature control system.	GL	82500	Vap-Air Division Vapor Corporation 6444 West Howard Street Chicago, IL 60607
PA-23 Series; T.C. 1A10	SA3-644	Adams Rite 2302 rev. C-2 handle on inside of cabin door.	CE	65301	Product Development Group 2522 East Douglas Wichita, KS 67202
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers and increase gross weight to 3,684 lbs.	CE	56868	Galen D. Means 847 Watson Lane Wichita, KS 67201
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers and increase gross weight to 3,684 lbs.	SW	67016	AND Jackson M. Reed 607 North Peters Norman, OK 73069
PA-23 Series; T.C. 1A10	SA4-299	Windows at station 144.	WE	39877	Hamilton Aircraft Company, Inc. 6501 South Park Avenue Tucson, AZ 85706
PA-23 Series; T.C. 1A10	SA4-345	"B" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-23 Series; T.C. 1A10	SA4-522	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA4-652	Full flow aerofilter kit 3-1A101.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-23 Series; T.C. 1A10	SA4-783	Lycoming 150 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-23 Series; T.C. 1A10	SA4-994	Installation of Firestone Model DFA-233 wheel assemblies, Model CFA-299 brake assemblies and 6.50x8 6-ply tires.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1016	Lycoming 160 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-23 Series; T.C. 1A10	SA4-1131	SP-3 autopilot, less altitude and navigation hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85000
PA-23 Series; T.C. 1A10	SA4-1166	Installation of Firestone Model DFA-180 wheel.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1602	Dorsal fin.	RM	60280	Mountain States Aviation, Inc. Stapleton Field Denver, CO 80202
PA-23 Series; T.C. 1A10	SA2WE	Fuel pressure warning lights.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
PA-23 Series; T.C. 1A10	SA47CE	Governor 210413.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA65EA	One Aerojet-General 15NS-250 aircraft rocket engine on underside of fuselage on airplane centerline aft of main spar wing and relocation of cabin air intake scoop assembly.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA69SW	Extended nose with baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA100SW	Automatic pilot AK114.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA114SW	Combustion monitor.	EA	60100	Monitair Corporation Ramapo Valley Airport Spring Valley, NY 10977
PA-23 Series; T.C. 1A10	SA140SW	Cabin window addition.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA172EA	Reinforcement of rearmost seat and installation of additional safety belt.	EA	16804	Walter E. Hoffman, Jr. Birchwood Lodges & Cottages East Stroudsburg, PA 18301
PA-23 Series; T.C. 1A10	SA202SO	Fyr-Fyter 23-4, 2 1/2 lb., dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA219EA	Installation of Katz integrated flight indicator Model KIFI-2 or KIFI-2A. Amended 5/21/69.	NE	36300	Forest City Aviation Services, Inc. 749 Congress Street Portland, ME 04102
PA-23 Series; T.C. 1A10	SA226EA	Added structure aft of cabin area.	EA	67000	Reding Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23 Series; T.C. 1A10	SA232EA	Installation of Tactair omni lock Model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair model omni lock Model OL-1). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA242SO	Two-place couch.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA243EA	13-quart propeller anti-icing kit WAP-102.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA244SO	PA-23-250 wing root and nacelle fairings.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA250WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA266SO	Modification of fuel cap 16097-00 by making a new cover and enlarging the lower vent hole. Rework fuel cell filler neck door 19049-06 by putting a spring loading vent in the door to be used as auxiliary vent during icing conditions.	SO	12700	Avco Corporation Aerospace Structures Division Nashville, TN 37202
PA-23 Series; T.C. 1A10	SA268WE	Sixth seat and emergency exit.	WE	60095	Monarch Aviation Associates P.O. Box 527 Monterey, CA 93940
PA-23 Series; T.C. 1A10	SA280SW	Forward fuselage section and long nose 30542-02.	SW	79794	Tulsa Airmotive, Inc. P.O. Box 176 Broken Arrow, OK 74012
PA-23 Series; T.C. 1A10	SA309WE	Non-icing fuel tank vents.	WE	06750	Aircraft Tank Service, Inc. 1201 Cohasset Street Burbank, CA 91504
PA-23 Series; T.C. 1A10	SA311SW	Alternate static source.	SW	71800	Sinclair Oil & Gas Company Aviation Department, Box 521 Tulsa, OK 74101
PA-23 Series; T.C. 1A10	SA319EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA337EA	Conversion of aircraft electrical system to 24 volt.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA339SW	Electrical hydraulic pump. Reissued 9/20/77.	SW	90142	The Zee Company, Inc. 123 Braniff Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA363SW	Pitch trim system AK128.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA371SW	Fiberglass nose cone.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA372EA	Automatic flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-23 Series; T.C. 1A10	SA376WE	Left and right third window.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA387WE	Sixth seat and escape hatch.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA394WE	Replacement engine nose cowls.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA395WE	Lycoming O-360-A1A engines and Hartzell HC-C2YK-2R/7666-2 propellers.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA412WE	One-piece windshield.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA417SW	Rear baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA423SW	Fiberglass landing gear doors.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA461SW	Ramshorn type control wheel.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA462SW	One-piece windshield.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA463SW	Landing gear wheel well doors.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA465SW	Pitch trim system AK148.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA471CE	Dorsal fin.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23 Series; T.C. 1A10	SA476SW	Pitch trim system AK151.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA484SW	Large baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA497SW	Fiberglass engine nose cowl.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA498SW	Dual brakes.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA499SW	Engine nacelle and fuselage wing root fairings.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA504WE	11016 fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA523SW	Automatic trim system AK165.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA539WE	Turbosupercharged Lycoming IO-540-C1B5 or -C1C5 engine. Amended 6/14/66.	WE	66250	Rajay Corporation 2062 East Wardlow Raod Long Beach, CA 90807
PA-23 Series; T.C. 1A10	SA540SW	Piper auto-control III Model AK162 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA551WE	Installation of Brittain Model B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA557SW	Fiberglass nose cone.	SW	44930	J & G Aero Company P.O. Box 3031 Tyler, TX 75701
PA-23 Series; T.C. 1A10	SA566SW	AK184 automatic flight system, AK185 stabilizer, and AK188 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA574SW	Rear baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA580SW	Modified engine mounts.	SW	67650	RFB Company, Inc. Chandler Field Purcell, OK 73080
PA-23 Series; T.C. 1A10	SA590SW	Gross weight increased.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA597SW	Extended nose with baggage compartment. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA598SW	Wheel well doors. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA599SW	Fiberglass engine nose cowls.	SW	59500	James W. Miller 6517 Moss Oak San Antonio, TX 78229
PA-23 Series; T.C. 1A10	SA600SW	Nacelle and wing root fairings. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA605SW	Rear baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA612SW	Square wing tips. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA613SW	Dorsal fin and square tip fin and rudder. Amended 7/31/68.	SW	50500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA614WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA615WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A0	SA616WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA617WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA636SW	MOdified nose, gear doors, nacelle fairings, and wing tips.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA671SW	Dorsal fin and square rudder.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA697SW	One-piece windshield. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA698SW	Rear picture window.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78114
PA-23 Series; T.C. 1A10	SA747SW	Pitch trim AK228 (manual).	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA764WE	Aztec "B" nose section.	RM	08315	Airport Development Corp. 5120 West Rowland Avenue Littleton, CO 80120
PA-23 Series; T.C. 1A10	SA774SW	Franklin 6A-350-C1 engines, McCauley 2AF31C10/84SF-8 propeller increase gross weight 3675 lbs. takeoff, 3500 lbs. landing. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA803SW	Dual brakes. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA824WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA852WE	Turbosupercharged Lycoming O-540-A1B5, -A1D5, or -A3D5 engines (S/N's 27-1 thru 27-2504).	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA867SW	Lycoming O-540-A1D5 engines.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA882EA	Installation of supplemental strobe light Grimes P/N 30-0437-100. Amended 5/2/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23 Series; T.C. 1A10	SA909WE	Turbosupercharged Lycoming IO-540-J4A5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA953SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23 Series; T.C. 1A10	SA978WE	Turbosupercharged Lycoming IO-540-C4B5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA1076CE	Installation of Halon 1301 cabin fire extinguishing system and engine nacelle fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64105
PA-23 Series; T.C. 1A10	SA1348WE	B-4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA1480WE	Installation of an integral 24 gallon auxiliary fuel tank in each wing tip.	WE	58500	Met-Co-Aire 3848 Campus Drive Newport Beach, CA 92660
PA-23 Series; T.C. 1A10	SA1486WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA2914WE	Installation of improved rudder trim tab actuating rod. Issued 8/13/74.	WE	13800	Aviation Research Corporation P.O. Box 718 Santa Ynez, CA 93460
PA-23, -23-160; T.C. 1A10	SA4-1637	Installation of turbosupercharged Lycoming O-320-A or -B series engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23, -23-160; T.C. 1A10	SA2CE	Installation of Doyn Model 1600 dorsal fin. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23, PA-23-160; T.C. 1A10	SA285CE	Lycoming IO-360-B1B engines and Hartzell HC-C2YK-2RA/7666A-2 propellers. Gross weight increase to 3,684 lbs. on PA-23 and to 4,000 lbs. on PA-23-160. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23, -23-160; T.C. 1A10	SA802CE	Alter tip of vertical fin and rudder. Amended August 1976.	CE	60174	J.J. Morelli Route 1, Box 138 Platte City, MO 64079
PA-23, -23-160; T.C. 1A10	SA897SW	Fiberglass propeller spinners. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA898SW	Revised engine cowling. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA1260WE	Installation of turbosupercharged Lycoming O-360-A1A or A1D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23, -23-160; T.C. 1A10	SA1306SW	Lycoming IO-360-C1C engines with Hartzell HC-C2YK-2/C7666A-4 propellers with gross weight increase. Issued 5/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23, -23-160; T.C. 1A10	SA2793SW	Rudder hinge reinforcing bracket. Issued 6/7/78.	SW	70750	Seguin Aviation, Inc. 2075 Highway 46 Seguin, TX 78155
PA-23, -23-160; T.C. 1A10	SA3099SW-D	Mitchell automatic flight system AK587 consisting of Century I autopilot with optional omni tracker. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3100SW-D	Mitchell automatic flight system AK588 consisting of Century III with optional radio coupler and glide slope coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3101SW-D	Mitchell automatic flight system AK586 consisting of Century IIB autopilot with optional radio coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160, -23-235, -23-250, PA-24, -24-250, -24-400, PA-28-150, -28-160, -28-180, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, PA-23-235, PA-23-250; T.C. 1A10	SA136EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, -235, -250; T.C. 1A10	SA236CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-23, -23-160, -23-235; T.C. 1A10	SA317EA	Radome kit No. 2025K-B for Bendix RDR-100 or RDR-110 series radar systems with 12-inch antenna per Chamberlain installation. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23, -23-160, -235, PA-25; T.C. 1A10	SA362SW	Rear baggage compartment. Reissued 4/24/79.	SW	70750	Seguin Aviation 2075 Highway 46 Seguin, TX 78155
PA-23, -160, -235; T.C. 1A10	SA398CE	Install Hoskins twilighter Mk III supplemental lighting system consisting of Model F wing lights with Model P or K (dual) tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23, 23-160, 23-235, 23-250; PA-24, -24-250, -260, -400; PA-31, -31P; T.C. A8EA, 1A10, 1A15	SA660WE	Installation of HRD-type fire extinguishing system. Amended 7/11/77.	WE	43190	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91015
PA-23, -160, -235; T.C. 1A10	SA894SW	Nacelle saddleback. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23-160, -235, -250; PA-30, PA-39; T.C. 1A10, A1EA	SA890EA	Installation of Grimes three light strobe kit P/N 34-0101-2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23, -23-160, -23-235, -23-250, -E23-250, PA-24, -24-250, -24-260, -24-400, PA-28-140, -28-150, -28-160, -28-180, -28-235, -28S-160, -28S-180, -28R-180, -28R-200, PA-30, PA-39, PA-32-260, -32-300, -32S-300, PA-30, PA-39; T.C. 1A10, 1A15, 2A13, A1EA, A3SO	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light system two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 11/30/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23, -160, -235, -250; PA-24-180, -250, -400; *PA-28-140, -150, -160, -180, -235; *PA-31; T.C. 1A10, 2A13, A8EA	SA1290WE	Installation of "Quazar" high intensity supplemental exterior flashing lights. Amended 11/25/69. *Approved anti-collision light system is required.	RM	66000	Radair, Inc. 5665 South Curtis Street Littleton, CO 80120
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SW	67016	AND Jackson M. Reed 607 North Peters Street Norman, OK 73069
PA-23-160; T.C. 1A10	SA47SO	Installation of one-piece instrument panel.	SW	68145	Riley International Corporation 6211 West Northwest Highway Dallas, TX 75225
PA-23-160; T.C. 1A10	SA68NW	Installation of cargo door on right side of fuselage. Issued 10/30/73.	SO	70280	Elbridge P. Sawyer P.O. Box 148 Dayton, OH 37321
PA-23-160, -235, -250; T.C. 1A10	SA162SW	Cabin emergency exit window and sixth seat. Reissued 10/3/78.	SW	70750	Seguin Aviation, Inc. 2075 Highway 46 Seguin, TX 78155
PA-23-160; T.C. 1A10	SA272CE	Installation of Lycoming IO-360-B1A engines and Hartzell HC-C2YK-2RA/7666A-2 propellers. Gross weight increase to 4000 lbs. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-235; T.C. 2A10	SA1136SW	Fiberglass fuselage shell.	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
PA-23-235; T.C. 2A10	SA1205SW	Manual electric trim AK268. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235; T.C. 2A10	SA1746WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23-235; T.C. 2A10	SA1847WE	Installation of Brittain up-command signal adapter kit. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23-235, -250; T.C. 1A10	SA495CE	Installation of Hartzell Model HC-A3XK-2B/7636D-4 three-bladed propellers.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23-235, PA-23-250; T.C. 1A10	SA530WE	Installation of Rajay turbosupercharged Lycoming IO-540-C1B5 or C1C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-235, -23-250; T.C. 1A10	SA1315SW	Dorsal fin. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-235, -23-250; T.C. 1A10	SA1361CE	Chrome plated brake disc installation. Issued 3/6/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA155EA	Install B.F. Goodrich pneumatic de-icing system. Amended 8/10/79.	GL	38500	B.F. Goodrich Engineered Systems Company 500 South Main Street Akron, OH 44318
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA921SW	Mitchell automatic flight system AK242 consisting of Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1091SW	Mitchell automatic flight director system FD/AP 282-184 consisting of flight director, automatic pilot, auto-flite AK 185.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport
PA-23-235, -23-250, -E23-50, Serial Nos. 27-1 thru 27-4573; T.C. 1A10	SA1124EA	Installation of enlarged cargo door. Reissued 8/25/78.	EA	26683	Courtesy Air Service, Inc. P.O. Box 561 Warren County Airport Glen Falls, NY 12801
PA-23-235, -23-250 (S/N 271 thru 27-7554172), PA-E23-250 (S/N 27-2505 thru 27-7554172), PA-23-250 (Model "F") (S/N 27-7654001 and up); T.C. 1A10	SA1126EA	Installation of DeVore tel-tail lights on upper surface of stabilator. Reissued 9/28/78.	EA	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1262SW	Mitchell automatic flight system FD282-242 consisting of flight director/autopilot, and automatic pitch trim. Issued 2/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1276SW	Mitchell automatic flight system AK332, consisting of Piper autoflite II and omni tracker system. Issued 3/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1377SW	Mitchell automatic flight system AK340, consisting of Century I and optional tracker. Issued 10/14/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA2442WE	Installation of dual hydraulic pump (New Eastern Industries hydraulic pump 1233-HnG Type 311 on right engine; pump 1233-HnG Type 311 in lieu of existing pump on left engine). Amended 3/29/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, 23-250, PA-E23-250;	SA2445WE	Installation of recontoured inboard wing leading edge, stall fences, drooped ailerons in flaps down mode, rudder anti-servo tab system, and optional raked wing tips. Issued 11/16/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA3133SW-D	Mitchell automatic flight system AK599, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/7/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA3137SW-D	Mitchell automatic flight system AK611 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, -250; PA-24, -24-250, -260; PA-25, -25-235, -25-260; PA-28-150, -28-160, -28-180, -28-235; T.C. 1A10, 1A15, 2A8, 2A13	SA693CE	Replace existing engine induction air filter with AC Spark Plug Division filter.	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250; T.C. 1A10	SA11NE	Installation of laser sensor system. Issued 10/31/75.	NE	33485	Environmental Research and Technology, Inc. 696 Virginia Road Concord, MA 01742
PA-23-250; T.C. 1A10	SA39RM	Installation of freon air-conditioning system. Issued 4/23/75.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-23-250; T.C. 1A10	SA164CE	Installation of Hartzell HC-A3XK-2B/7636D-4 propellers and C-2513-2P spinners. Reissued 3/9/78.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-250; T.C. 1A10	SA179CE	Installation of the following: Lycoming IO-540-A1A5 or IO-540-G1A5 engines, Hartzell HC-A3XK-2C/8433-10 or HC-A3XK-2B/7636D-4 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-250; T.C. 1A10	SA205GL	Installation of Aerosonic totalize fuel flow indication system in lieu of fuel pressure gages. Issued 12/19/77.	GL	73190	Roger Smith Aircraft Sales, Inc. Aurora Municipal Airport Sugar Grove, IL 60554
PA-23-250; T.C. 1A10	SA335CE	Installation of Honeywell H-14 YG-391 autopilot. Amended 9/9/66.	GL	42250	Honeywell, Inc. East 70th & 34th Avenue South Wold-Chamberlain Field Minneapolis, MN 55450
PA-23-250; T.C. 1A10	SA429SO	Installation of Bendix Model FCS-80 automatic flight control system with manual electric pitch trim and flight director indicator. Amended 6/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA441NW	Installation of 3-bladed propeller and Piper Navajo spinner. Amended 1/12/78.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
PA-23-250; T.C. 1A10	SA480EA	Installation of photographic equipment.	NE	71400	James W. Sewall Company 147 Center Street Old Town, ME 04468
PA-23-250; T.C. 1A10	SA497SO	Installation of Bendix WLS-880 wings leveler system with and without Bendix FCS-810 automatic flight control system. Issued 11/8/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA590SO	Installation of M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA591SO	Installation of Bendix RNS-3400 area navigation system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250 (S/N 27-2505 and up); T.C. 1A10	SA621EA	Installation of a U.S. mail cargo kit. Amended 4/15/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23-250 (Aztec C, I, E); T.C. 1A10	SA663CE	Installation of Goodyear ice-guard de-icing kit Nos. 320-642. Reissued 4/17/72.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA667CE	Installation of wing and empennage deicing boot. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA668CE	Installation of wing and empennage deicing all weather antenna. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA688CE	Installation of propeller unfeathering system. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capitol Airport Springfield, IL 62705
PA-23-250; T.C. 1A10	SA850EA	Installation of radome kit 4025KX. Amended 9/12/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250; T.C. 1A10	SA922SO	Installation of Piper PA-23-250 "E" model fuselage nose. Amended 6/30/77.	SO	41400	Hawthorne Aviation Municipal Airport P.O. Box 10005 Charleston, SC 29411

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250 (Aztec F) defined by item VI in TCDS 1A10; T.C. 1A10	SA952SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA1022CE	Installation of King Model KGS-55 pictorial navigation system (compass), with optional KA-52 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1027CE	Installation of KCS-55 pictorial navigation system (compass), with optional KA-57 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250 (Landplanes) (S/Ns 27-2505 thru 27-74-05471); T.C. 1A10	SA1063CE	installation of two Hartzell HC-E3YR-2AF/FC7663-2R propellers and C-3269A or 82D3273P spinners. Reissued August 1976.	SW	03034	AeroStol Company 5104 Rector Fort Worth, TX 76133
PA-23-250; T.C. 1A10	SA1102CE	Installation of AP-107, 2-axis autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250; T.C. 1A10	SA1103CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250, S/N 27-2000 and up thru 1979 versions, with normally aspirated engines; T.C. 1A10	SA1162EA	Installation of Silver Instruments fueltron IIIG digital fuel flow and totalizer system. Reissued 1/8/80.	WE	71740	Silver Instruments 2346 Stanwell Drive Concord, CA 94520
PA-23-250; T.C. 1A10	SA1163CE	Installation of KFC-200 automatic flight control system. Amended 6/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1314SW	Fiberglass extended nose. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-250; T.C. 1A10	SA1390CE	Install 1/4-inch plywood flooring over existing floor, remove 4 passenger seats, install reinforcement tubing. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250; T.C. 1A10	SA1391CE	Cutting and reattaching the left and right lower engine cowling with AN 2700-4 cam locks. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250 (S/N 27-2505 and up); T.C. 1A10	SA1444WE	Installation of Edo Model 679-4930 floats and addition of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663
PA-23-250; T.C. 1A10	SA1810WE	Installation of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663
PA-23-250; T.C. 1A10	SA3209SW-D	Mitchell automatic flight system, Piper altimatic X autopilot, AK684 or AK684FD, Piper altimatic X flight director autopilot with remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, Serial Nos. 27-2000 and up; T.C. 1A10	SA3823WE	Installation of SD1 Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-23-250 (S/Ns 27-2000 and up), -E23-250; T.C. 1A10	SA619EA	Installation of radome kit 3061K for Bendix RDR-100 or RDR-110. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-23-250, -E23-250; T.C. 1A10	SA20GL	Installation of Woodward electronic propeller synchronizer system. Amended 11/6/75.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250, -E23-250; T.C. 1A10	SA25GL	Installation of propeller unfeathering accumulator system on light twin-engine airplanes. Issued 6/26/73.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA51GL	Install Foster Airdata Systems, Inc. AD611/D area navigation system per STC. Reissued and amended 2/20/79.	GL	36520	Foster Airdata, Inc. 7020 Huntley Road Columbus, OH 43229
PA-23-250, -E23-250; T.C. 1A10	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 40355
PA-23-250, -E23-250 with counterweighted props, PA-31, PA-32-260, -31-325, -31-350, T.C. 1A10, A20SO, A3SO	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 1/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA430EA	Installtion of radome kit No. 3061X. Amended 11/12/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250, -E23-250; T.C. 1A10	SW1524SW	Mitchell automatic flight system AK371 consisting of altimatic IIIB-1 autopilot with optional command/electric trim system with radio and glide slope couplers. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1571SW	Mitchell automatic flight system AK382 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 12/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1653SW	Mitchell automatic flight system AK372 consisting of AutoFlite II with optional tracking system. Issued 5/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3002SW-D	Automatic flight system AK479 consisting of Piper altimatic IIIC autopilot with optional command/automatic electric elevator trim servo altimeter, radio coupler, and glide slope coupler. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3003SW-D	Automatic flight system AK477 and AK477FD consisting of Century IV autopilot and Century IV flight director autopilot with command/automatic electric trim, and optional annunciator panel and servoed altimeter. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3005SW-D	Automatic flight system AK508 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3006SW-D	Automatic flight system AK494 and AK494FD consisting of Century IV autopilot and Century IV director autopilot and command/automatic electric elevator trim and optional annuciator panel. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3007SW-D	Automatic flight system AK504 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim, radio coupler, glide slope coupler. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3027SW-D	Mitchell command/electric trim system AK562. Issued 10/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250, -E23-250; T.C. 1A10	SA3104SW-D	Mitchell automatic flight system AK583, consisting of Century IIB autopilot with optional radio coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3290WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/8/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA195EA	Installation of Goodrich Electrothermal propeller de-icing system kit 77-170. Amended 10/27/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Co. 500 South Main Street Akron, OH 44318
PA-23-250 (S/N 27-2000 and up), PA-E23-250; T.C. 1A10	SA430EA	Installation of radome kit 3061X. Reissued 4/21/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA840WE	Installation of Rajay Turbosupercharged Lycoming IO-540-C4B5 or -C4C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23 Series, PA-24 Series; T.C. 1A10, 1A15	SA230CE	Airspeed indicator landing gear warning system.	CE	74923	Standard Precision, Inc. 4105 West Pawnee Wichita, KS 67202
PA-23, PA-24, PA-28 Series; T.C. 1A10, 1A15, 2A13	SA148SW	Replacement of right front seat with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72003
PA-23, PA-24, PA-28, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA662WE	Hi-Lo sensitivity adaptor BI-400, and autopilot with NAV-1 navigation coupler and heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23, PA-24, PA-30 Series; T.C. 1A10, 1A15, A1EA	SA188SO	Flight control wheel.	SO	37086	Garcia Aviation Company 13010 SW 82nd Avenue Road Miami, FL 33156
PA-23, PA-25, PA-26 Series; T.C. 1A10, 1A15, 2A8, 2A10	SA4-1501	AB-6562 and AB-6563 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-23, PA-30, PA-31, PA-34, PA-39 Series; T.C. 1A10, A1EA, A8EA, 1E10	SA1675WE	Installation of exhaust gas temperature monitoring systems EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-24 Series; T.C. 1A15	SA1-340	Oil-free vacuum pump PA-201.	GL	11880	Associated Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-24 Series; T.C. 1A15	SA1-544	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-24 Series; T.C. 1A15	SA3-309	L2-B autopilot with or without altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA3-315	Arcon B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA3-351	L-2B autopilot with optional altitude control and automatic approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA4-572	Autopilot and optional navigation coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA4-666	Grimes D-7080-1-12 rotating beacon.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-24 Series; T.C. 1A15	SA4-852	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24 Series; T.C. 1A15	SA4-955	Fiberglass vertical fin mount for either Grimes or Whelen WRM rotating beacons.	NW	85550	Art Whitaker Pearson Airpark Vancouver, WA 98660
PA-24 Series; T.C. 1A15	SA4-956	Three seat belts to accommodate three persons or rear seat.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-971	20-gallon auxiliary fuel tank in baggage compartment.	WE	77260	Symons Engineering P.O. Box 90002 Airport Station Los Angeles, CA 90009
PA-24 Series; T.C. 1A15	SA4-1032	Aerofilter 30409A full flow lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-24 Series; T.C. 1A15	SA4-1132	SP-3 autopilot, less altitude and navigation-hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85027
PA-24 Series; T.C. 1A15	SA4-1235	Installation of Brittain 15-gallon wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA4-1248	Fuel drain modified to incorporate a handle extending forward through front bulkhead.	WE	14960	Bates Aviation, Inc. 1026 East 120th Street Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-1351	Installation of wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA2SO	Fifth passenger seat.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA18SO	Cockpit operated fuel drain valve.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA48WE	Belly-mounted rotating anti-collision light to supplement top fuselage-mounted standard rotating light.	WE	75250	Stits Aircraft Company P.O. Box 3084 Riverside, CA 92502
PA-24 Series; T.C. 1A15	SA59SW	Piper altimatic pilot AK089 or AK089R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24 Series; T.C. 1A15	SA74SW	Quick door release mechanism.	SW	69207	Ross Aviation, Inc. R.F.D. 5, Riverside Airport Tulsa, OK 74101
PA-24 Series; T.C. 1A15	SA112CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155
PA-24 Series; T.C. 1A15	SA113CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155
PA-24 Series; T.C. 1A15	SA160SW	Automatic pilot AK115, AK115E or AK115E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24 Series; T.C. 1A15	SA203SO	Fyr-Fyter 23-4, 2-1/2 pound, dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-24 Series; T.C. 1A15	SA315SW	Fabrication and installation of split rear seat back.	SW	71365	Seven Bar Flying Service, Inc. 10001 Coors Road, NW Albuquerque, NM 87101
PA-24 Series; T.C. 1A15	SA341CE	SAGA (semi-automatic gear actuator) control system. Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
PA-24 Series; T.C. 1A15	SA362WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA478EA	SAGA (semi-automatic gear actuator) system.	GL	43750	In-Flight Devices Corporatin 4885 Sawyer Road International Airport Columbus, OH 43219

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24 Series; T.C. 1A15	SA482WE	Plastic wing tips replaced with "Speedplates".	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
PA-24 Series; T.C. 1A15	SA510CE	Modify electrical system to combination 12/24 volt system for starting engine.	EA	12700	Avco Lycoming Division Avco Corporation Williamsport, PA 17701
PA-24 Series; T.C. 1A15	SA511WE	Lycoming O-540-B1B5 engine, Hartzell HC-A2XK-1/8433-7 propeller required.	WE	46790	Johnston Aircraft Service P.O. Box 757 Tulare, CA 93274
PA-24 Series; T.C. 1A15	SA553WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA598EA	Installation electronic voltage alarm, Drawing No. 80107.	EA	53500	McKinley Engineering Corp. P.O. Box 275 Palisades Park, NJ 07650
PA-24 Series; T.C. 1A15	SA871WE	Fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-24 Series; T.C. 1A15	SA881EA	Installation of Grimes 30-0437-1 anti-collision strobe light kit, P/N 34-0200-1. Amended 5/2/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-24 Series; T.C. 1A15	SA891WE	Toe brakes.	RM	12540	Atlas AViation, Inc. 8505 Montview Boulevard Denver, CO 80202
PA-24 Series; T.C. 1A15	SA904WE	Hanlon and Wilson exhaust system, 637-129.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA1109WE	Hanlon and Wilson exhaust system.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA1605WE	Installation of Brittain B-4A flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24-180; T.C. 1A15	SA4-3151	Wing tip fuel tanks installed. Amended 1/10/69.	WE	17492	Brittain Industries, Inc. 2700 Skypark Drive Torrance, CA 90505
PA-24-180; T.C. 1A15	SA127EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-24(-180), -24-250, -24-260, -24-400; T.C. 1A15	SA208GL	Installation of one piece windshield. Issued 1/23/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-24, PA-24-250, -260, -400; T.C. 1A15	SA270GL	Installation of forward windows, P/N's W-, W/T-, WG-2058-187 or -250 and W-, W/T-, W/G-2059-187 or -250. Issued 10/2/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-24, -24-250; T.C. 1A15	SA3074SW-D	Mitchell automatic flight system AK547 consisting of Century I autopilot with optional omni tracker. Issued 10/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, 24-250, -260; PA-28, 28-140, -150, -160, -180, -235; PA-30; PA-32-260, -300; T.C. 1A15, 2A13, A1EA, A3SO	SA808SW	Installation of Mitchell Model AK246 omni tracker. Applicable only to aircraft modified by STCs SA511SW, SA532SW, SA581SW, SA662SW, SA707SW.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -260, -400; T.C. 1A15	SA891SO	Remove existing windshield and install single piece windshield. Amended 4/27/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260; T.C. 1A15	SA1315CE	Chrome-plated brake disc installations. Issued June 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA1706SW	Portable solid oxygen system. Issued 7/27/73.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3070WE	Installation of single piece windshield. Issued 7/23/75.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-24, -24-250, -24-400; T.C. 1A15	SA2495WE	Installation of recontoured wing leading edge, stall fences, drooped ailerons in flaps-down mode, flap-actuated stabilator trim system, optional new wing tips, optional SC-100 stall warning system. Issued 3/27/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250; PA-28-180; T.C. 1A15, 2A13	SA2654WE	Installation of Pathfinder P2A autopilot system. Reissued 5/31/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; T.C. 1A15	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260, PA-30; T.C. 1A15, A1EA	SA3045SW-D	Automatic flight system AK519 consisting of Century IIB autopilot with optional radio coupler. Issued 3/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3565WE	Installation of single piece windshield. Issued 1/20/78.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-24, -24-250, -24-260; T.C. 1A15	SA3776WE	Installation of flexible stainless steel oil cooler hoses. Issued 11/1/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-24-250; T.C. 1A15	SA5-27	Remove Lycoming O-540-A1A5 (250 hp) engine and install Lycoming O-540-B1B5 (235 hp) engine. Revised 3/3/62.	AL	63845	Peninsula Airways, Inc. P.O. Box 110 Naknek, AK 99633
PA-24-250; T.C. 1A15	SA811WE	Installation of turbosupercharged Lycoming IO-540-C1B5 or C1C5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-250; T.C. 1A15	SA3451WE	Installation of Hartzell HC-A3VK4/V7636D-0 constant speed propeller. Issued 7/13/77.	WE	00270	A & P Propeller and Parts Gillespie Airport Plaza 8404 Magnolia Avenue Santee, CA 92071
PA-24-250, -24-260; T.C. 1A15	SA3684WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
*PA-24-250, *-24-260; T.C. 1A15	SA3773WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79. *This installation limited to those aircraft with fuel injected engines.	WE	71740	Silver Instruments, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-24-250, 24-260, PA-30; T.C. 1A15, A1EA	SA1027SW	Manual electric pitch trim AK267.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA893SO	Installation of exhaust silencers. Issued 4/22/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24-260 (S/Ns 24-4783 and 24-4804 and up); T.C. 1A15	SA1026SW	Piper automatic flight system Model AK186 consisting of altimatic IIIB autopilot, auto-flite, electric pitch trim, radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260 (S/N 24-4783, 24-4804 and up with IO-540 series normally aspirated engines; T.C. 1A15	SA1178EA	Installation of Silver Instruments fueltron IG digital fuel flow and totalizer system. Reissued 2/26/80.	EA	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24-260; T.C. 1A15	SA1331SW	Mitchell automatic flight system AK326 consisting of Piper autoflite II and optional tracking system. Issued 6/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA1521SW	Mitchell automatic flight system AK393, consisting of Century I autopilot with optional omni tracker. Issued 10/17/72.	SW	60000	Mitchell Industries, INc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA2062WE	Installation of Lycoming IO-540-R1A5 engine and Rajay turbosuperchargers.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-260, -24-400; T.C. 1A15	SA31NW	Installation of Madras wing tips. Issued 3/13/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
PA-24-400; T.C. 1A15	SA2359WE	Installation of turbosupercharged Lycoming IO-720-A1A engine. Issued 6/1/71.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-400; T.C. 1A15	SA3134SW-D	Mitchell automatic flight system AK593 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-400; T.C. 1A15	SA3135SW-D	Mitchell automatic flight system AK597 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
PA-24-400; T.C. 1A15	SA3136SW-D	Mitchell automatic flight system AK609 consisting of Century I autopilot with optional omni tracker. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-28; T.C. 1A15, 2A13	SA1485WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24, PA-30; T.C. 1A15, A1EA	SA313SW	Pitch trim system AK124.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA331SO	External power supply plug.	SO	60120	Montgomery Aviation Corporation P.O. Box 92 Montgomery, AL 36100
PA-24, PA-30; T.C. 1A15, A1EA	SA466SW	Pitch trim system AK147.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA475SW	Pitch trim system AK152.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA524SW	Pitch trim system AK164.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA525SW	Piper autocontrol III, Mitchell AK161 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA581SW	Stabilizer AK179.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A15EA	SA662SW	Automatic flight system 220.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA756SW	AK236 automatic flight system with Century II autopilot, optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-25 Series; T.C. 2A8, 2A10	SA4-1592	Spray equipment.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA157SO	Air-oil type main landing gear shock absorber.	SO	64665	Piper Aircraft Corporation Vero Beach, FL 32960
PA-25 Series; T.C. 2A8, 2A10	SA168WE	Installation of Agavenco P/N 1826 15-gallon additional capacity cell to Piper fiberglass spray tank. Amended 3/18/68.	WE	03250	Agricultural Aviation Engineering Company McCarran Airport Las Vegas, NV 89109
PA-25 Series; T.C. 2A8, 2A10	SA185WE	Electrical spray control valve.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Crive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA292SO	FrigiKing JC-1 air conditioner.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-25 Series; T.C. 2A8, 2A10	SA300SO	Auxiliary oil radiator.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-25 Series; T.C. 2A8, 2A10	SA512SW	Metal ribs and metal covering of wings.	SW	60168	Luther W. Moore 1110 West 29th Street Plainview, TX 79072
PA-25 Series; T.C. 2A8, 2A10	SA829WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-25, -25-235, -260; T.C. 2A10	SA915SO	Lower forward longeron reinforcement by adding tubing in trangle shape outboard between fore and aft wing spar root attach fittings and modifying wing root rib to fit over modified longeron. Issued 1/6/77.	SO	05966	Aircraft Service Center, Inc. Route 2, Tifton Airport Tifton, GA 31794
PA-25, -25-235, -260; T.C. 2A10	SA1180CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Gox 508 Renner Field Goodland, KS 67735
PA-25, -25-235, -260; T.C. 2A10	SA1294WE	Installation of automatic flagman. Amended 4/17/72.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362
PA-25, -25-235, -260; T.C. 2A10	SA1417WE	Installation of fiberglass wing tips. Amended 3/26/69.	NW	74750	Sportsman Airpark, Inc. P.O. Box 248 Newberg, OR 97132
PA-25-235; T.C. 2A8	SA41RM	Installation of freon air-conditioning system. Issued 1/9/75.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-25-235; T.C. 2A8, 2A10	SA521WE	Swathmaster dust and spray attachment.	WE	79250	Transland Aircraft, Inc. 2923 190th Street Redondo Beach, CA 90277
PA-25-235; T.C. 2A8, 2A10	SA710CE	Install Compro Aviation rudder horn extension.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
PA-25-235; T.C. 2A8, 2A10	SA997WE	Installation of 180-gallon hopper tank. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-25-235; T.C. 2A10	SA1399WE	Installation of Shell B1-Flon spray system. amended 7/19/68.	NW	71770	Simplex Manufacturing Company 4224 Northeast 42nd Avenue Portland, OR 97218
PA-25-235; T.C. 2A10	SA1630SW	Revised exhaust system. Issued 5/5/73.	SW	53784	Karl D. McWilliams d/b/a K & C Aircraft Service Municipal Building Airport Frederick, OK 73542
PA-25-235, -25-260; T.C. 2A8	SA1316CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-25-235, -25-260; T.C. 2A8	SA1892WE	Installation of hydraulic system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton AVenue Harbor City, CA 90710

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-25-235, -25-260; T.C. 2A8	SA368NW	Installation of outboard wing fuel tank with modified fuel pump system. Issued 10/19/76.	NW	03270	U.S.D.A. 3706 West Nob Hill Boulevard Yakima, WA 98902
PA-25, PA28-140, PA32-260; T.C. 2A8, 2A13, A3SO	SA693WE	Install AC induction air filter type AAF-104. Amended 4/26/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
PA-28 Series; T.C. 2A13	SA1-649	Lube oil filter PB55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
PA-28 Series; T.C. 2A13	SA8PC	Installation of baggage compartment kit IFC-BC-001 behind rear seats in the cabin.	PC	44810	Island Flight Center, Inc. 203 Lagoon Drive Honolulu, HI 96819
PA-28 Series; T.C. 2A13	SA100EA	AF-510, AF-512A or AF-512B autopilots.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005
PA-28 Series; T.C. 2A13	SA110SO	Electric pitch trim system.	SO	54665	Piper Aircraft Corporation Vero Beach, FL 32960
PA-28 Series; T.C. 2A13	SA180EA	Geared starter.	EA	79953	Turner Field, Inc. Prospectville, PA 19077
PA-28 Series; T.C. 2A13	SA164SW	Automatic pilot AK092E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA178WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-28 Series; T.C. 2A13	SA222SW	Hartzell HC-82XL-6N/7636D-4 propeller and cowl rework.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA224CE	A3000 main and NB1200 nose skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA236SW	Piper auto-control II automatic pilot AK085E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA246SW	Nose cowling modified.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA263EA	Modification of engine mount to permit use of Lord mounting kit J-10778-4.	EA	12700	Lycoming Division Avco Corporation Williamsport, PA 17701
PA-28 Series; T.C. 2A13	SA319CE	Model 2500 wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA369SW	Automatic pilot AK129, pitch trim system AK130, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA481SW	Removal of door for parachute jumping.	SW	37055	Ervin J. Fusilier 9617 Fulton Street Houston, TX 77002
PA-28 Series; T.C. 2A13	SA511SW	Stabilizer AK153.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA530SW	Automatic pitch trim system AK166.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA556SW	Constant speed propeller.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA601WE	Flight control system B-4 including pitch assist PC-1, altitude hold AH-1, and	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28 Series; T.C. 2A13	SA645WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA646WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA707SW	AD127 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA708SW	Plane booster safe flight wing tips 101-28.	SW	81250	Upper Valley Aviation, Inc. Harvey J. Ferguson McAllen, TX 78501
PA-28 Series; T.C. 2A13	SA880WE	New design fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-28 Series; T.C. 2A13	SA1191WE	Removal of baggage door for aerial photography operations.	RM	47725	Kelsey Ellis Air Service, Inc. Municipal Airport Salt Lake City, UT 84101
PA-28 Series; T.C. 2A13	SA1354WE	PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1469WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1470WE	Installation of Brittain Model PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28-140; T.C. 2A13	SA578EA	Installation of Monitair angle of attack/stall warning kit, P/N 9-92-1000. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140; T.C. 2A13	SA687SO	Installation of flight attitude alerting system. Amended 6/1/70.	SO	05350	Aircraft Instruments, Inc. 420 Lincoln Road, Suite 206 Miami Beach, FL 33139
PA-28-140; T.C. 2A13	SA913EA	Installation of Elano Corporation heater-muffler system. Issued 5/11/72.	GL	33200	Elano Corporation 2455 Dayton - Xenia Road Xenia, OH 45385
PA-28-140; T.C. 2A13	SA1189SW	Air circulator. Issued 9/15/70.	SW	83100	Ves-Kol 2805 National Drive Garland, TX 75040
PA-28-140; T.C. 2A13	SA2052WE	Installation of Hartzell HC82XL-6F/8433-12 propeller (after conversion of engine to Lycoming O-320-E1A model).	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-140; T.C. 2A13	SA2325WE	Replacement of Station 140.6 vinyl bulkhead panel with fiberglass baggage compartment. Issued 3/19/71.	WE	21000	Chaffee Aircraft Service Corp. 2105 Valley Boulevard Colton, CA 92324
PA-28-140; T.C. 2A13	SA2706SW	Lycoming O-320-D3G engine. Issued 1/20/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-140; T.C. 2A13	SA2842WE	Installation of Novastar anti-collision lighting system. Issued 2/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28-140; T.C. 2A13	SA3071WE	Installation of Bendix P/N 480543 electric auxiliary fuel pump. Issued 8/7/75.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
PA-28-140 (Normal and utility category); T.C. 2A13	SA3415WE	Installation of Lycoming O-320-D2A engine and Sensenich M74DM6-0-60 propeller. Reissued 5/1/79.	NE	30310	Arthur M. D'Onofrio, Jr. 206 Winthrop Boulevard Cromwell, CT 06416
PA-28-140, -28-150 and PA-28-151 landplanes; T.C. 2A13	SA1331CE	Installation of 160 hp Lycoming engine and repitched Sensenich Amended 10/27/77.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
PA-28-140, -150, -160, -180, -235; T.C. 2A13	SA2NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 7/31/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-140, -28-150, -28-160, -28-180, -28S-180, -28-235; T.C. 2A13	SA363EA	Installation of Monitair angle of attack and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140, -150, -160, -180; T.C. 2A13	SA549NW	Installation of Deemers wing tips. Issued 12/5/77.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
PA-28-140, -140B, -140C, -140D, -140E, -150, -160, -160B, -160C, -160D, -160E, -160F, -180, -232, -235B thru F, PA-32-260, -300, -32R-300; T.C. 2A13, A3SO	SA600NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. NOTE: Installation does not apply to those models with tapered wings. Issued 10/25/78.	NW	19830	Robert C. Cansdale Bob's Aircraft Supply Thun Field Puyallup, WA 98371
PA-28-140, -150, -151, -160; T.C. 2A13	SA793CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/7666A-2 propeller. Amended 6/29/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
PA-28-140, -150, -160, -180, -235, 28-S-160, S-180, 28R-180, -200; T.C. 2A13	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-1 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-28-140, -150, -160, -180, -235, -S-160, -S-180, -R-180; T.C. 2A13	SA822SW	Mitchell automatic flight system AK217 consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -200, PA-34-200; T.C. 2A13, A7SO	SA979EA	Installation of L/R wing tip transparent fairings and sensor mounting bracketry. Issued 4/5/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1072CE	Installation of wing leading edge cuffs and droop tips, dorsal fin and vertical stabilizer vortex generators. Amended January 1975.	CE	75800	Stol-Craft, Inc. Wellington Municipal Airport wellington, KS 67152
PA-28-140, -150, -160, -180, -235, -28S-160, -28S-180, -28R-180, -28R-200, -28-151, -28-161, -28-181, -28R-201, -28R-201T, PA-32-260, -300, -32S-300, -32R-300; T.C. 2A13, A3SO	SA1123EA	Installation of DeVore "Tel-Tail" lights on upper surface of horizontal stabilator. Reissued 8/16/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1227CE	Installation of dorsal fin. Amended December 1976.	CE	44800	Isham Aircraft P.O. Box 12172 Wichita, KS 67212
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1228CE	Installation of wing tip extension. Amended June 1976.	CE	44800	Isham Aircraft 416 West Fourth Street Valley Center, KS 67147
PA-28-140, -150, -160, -180, -235; PA-28R-180; T.C. 2A13	SA1157SW	Mitchell flight system AK295 consisting of Piper AutoFlite II, automatic aileron stabilizer and optional tracking system. Issued 6/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -235, -200; T.C. 2A13	SA1272SW	Automatic flight system AK307, consisting of Century I and omni tracker. Issued 3/9/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1317CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-28-140, -150, -160, -180 (S/Ns 28-1 thru 28-4377), PA-28-235 (S/N 28-10003 thru 28-11039); T.C. 2A13	SA1373CE	Install third window. Amended 11/17/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1741WE	Installation of hand control for rudder system. Amended 6/13/73.	WE	16854	William Henry Blackwood Route 3, Box 744B3 Escondido, CA 92025

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1898SW	Installation of wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-28-140, -150, -160, -180; T.C. 2A13	SA2179WE	Installation of leading edge cuff, drooped ailerons, wing stall fences, raked wing tips, fuselage flaps, stabilator trim-spring and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98007
PA-28-140, -150, -160, -180, PA-28R-180, -200, -235, PA-32-260, -300; T.C. 2A13	SA3026SW-D	Mitchell auto flight system AK463 consisting of Century IIB autopilot with optional radio coupler. Issued 10/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, -28R-200, -235; T.C. 2A13	SA3165SW-D	Automatic flight system AK174 consisting of auto-control IIB autopilot with optional radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -160, -160, -235, -28R-180, -200; T.C. 2A13	SA3166SW-D	Automatic flight system AK295 consisting of Piper autoflite II. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -151, -160, -180, -181, -28R-180, -28R-200, -28-235; T.C. 2A13	SA3435WE	Installation of flexible oil hose assembly. Amended 1/11/79.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-28-140, -150, -160, -180, -151, -181, PA-28S-160, -180, PA-28R-180-200; T.C. 2A13	SA3687WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
PA-28-151; T.C. 2A13	SA220GL	Installation of Lycoming O-320-D3G engine in lieu of Lycoming O-320-E3D engine using original installation hardware and components. No installation data required. Issued 3/3/78.	GL	90108	W. Irvine Young 54 Atomic Avenue Toronto, Ontario M8Z-5L4 Canada
PA-28-151; T.C. 2A13	SA1716SW	Mitchell automatic flight system AK430 consisting of AutoFlite II with optional omni tracker. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA1717SW	Mitchell automatic flight system AK431 consisting of auto-control III with optional radio coupler. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA2969SW	Lycoming O-320-D3G engine. Issued 4/5/79.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-151; T.C. 2A13	SA3012WE	Installation of Pathfinder autopilot systems. Issued 4/24/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-151, -161, -181, PA-28R-200, -201, PA-28-235, -28R-201T; T.C. 2A13	SA1075SO	"Wing-Ding" door stop to be installed using existing screws (Piper P/N 415 309, MS27039-0809) on leading edge of right wing at inboard side of fuel cell (W.S. 57.00). Issued 5/18/79.	SO	65327	William J. Stephenson Pro-Flite of Vero, Inc. P.O. Box 998 Vero Beach, FL 32960
PA-28-151, -181; T.C. 2A13	SA3065SW-D	Mitchell automatic flight system AK431 consisting of autocontrol IIIB with optional radio coupler. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3066SW-D	Mitchell automatic flight system AK430 consisting of autoflite II with optional omni tracker. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3095SW-D	Mitchell automatic flight system AK575 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-151, -181; T.C. 2A13	SA3096SW-D	Mitchell automatic flight system AK576 consisting of Century IIB autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067
PA28-160; T.C. 2A13	SA1971WE	Installation of Model ARB-3 automatic downed aircraft marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue Box 822 Fort Collins, CO 80521
PA-28-160, -28-180, -28-235; T.C. 2A13	SA1484WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28-161, -181, -201T, -236; T.C. 2A13	SA3352SW	Installation of Mitchell automatic flight system AK851 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TS 76067
PA-28-180; T.C. 2A13	SA1789WE	Installation of Brittain lateral stability augmentation system and super venturi. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-180; T.C. 2A13	SA1792WE	Installation of Morse protection system.	WE	60190	Morse Products Manufacturing 12960 Bradley Avenue Sylmar, CA 91342
PA-28-180; T.C. 2A13	SA2213WE	Conversion of Lycoming O-360-A3A engine to Model O-360-A1A engine and installation of Hartzell HC-C2YK1-B/7666A-0 propeller. Issued 9/8/70.	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-180; T.C. 2A13	SA3233WE	Installation of Symbolic Displays "Novastar" anti-collision light. Issued 7/22/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28R-180; T.C. 2A13	SA962SW	Piper automatic flight system AK271 consisting of altimatic with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180; T.C. 2A13	SA1237SW	Mitchell automatic flight system Model AK314 consisting of altimatic IIIB-1 with optional automatic pitch trim and radio coupler. Issued 12/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA1406SW	Mitchell flight system Model AK269 consisting of Piper autocontrol III autopilot with optional radio coupler. Issued 12/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180; -200; T.C. 2A13	SA2202WE	Installation of contoured leading edge, drooped ailerons, fuselage flap, stabilator trim spring, wing stall fences, raked wing tips, and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98004
PA-28R-180, -200; T.C. 2A13	SA2490SW	Wing tip extension and dorsal fin. Reissued 10/6/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28R-180, -200; T.C. 2A13	SA3004SW-D	Automatic flight system AK436 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA3093SW-D	Mitchell automatic flight system AK577 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA3094SW-D	Mitchell automatic flight system AK578 consisting of Century IIB autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200, -201; T.C. 2A13	SA3841WE	Installation of SDI Model CFS-1000, -1001, or F1-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 MCGaw Avenue Irvine, CA 92714

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28R-200; T.C. 2A13	SA194GL	Installation of Lycoming IO-360-C1C6 engine in lieu of Lycoming IO-360-C1C engine using original installation hardware and components. Issued 11/11/77.	GL	71517	Shelby Aircraft Engine Parts, Inc. P.O. Box 454 Shelbyville, IL 62565
PA-28R-200 (S/N 28R-7235001 and up), -28R-201T, -28R-201 (S/N 28R-7737002 and up); T.C. 2A13	SA1183CE	Installation of a two-axis King Model KFC200 flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 1/26/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-28R-201, -201T; T.C. 2A13	SA3161SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -201T; T.C. 2A13	SA3162SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3194SW-D	Automatic flight system AK638 consisting of Piper altimatic IIIC autopilot with optional radio coupler and glide slope coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3195SW-D	Install automatic flight system AK652 consisting of Century III autopilot with optional radio coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-200, -28R-201T; T.C. 2A13	SA3196SW-D	Install automatic flight system AK653 consisting of Century IIB autopilot with optional radio coupler. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-200, -28R-201T; T.C. 2A13	SA3197SW-D	Install automatic flight system AK654 consisting of Century I autopilot with optional omni tracker. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201T; T.C. 2A13	SA148RM	Install Model CFS-1000 fuel flow meter and related systems. Issued 8/15/78.	RM	77248	Symbolic Displays, Inc. 8095 Montview Boulevard Hangar B Denver, CO 80220
PA-28R-201T; T.C. 2A13	SA1383CE	Installation of Edo-Aire propeller governor Model 34-828-014-12. Issued 10/28/77.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
PA-28R-201T; T.C. 2A13	SA3771WE	Installation of Fueltron IG digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-28RT-201, -28RT-201T; T.C. 2A13	SA1498CE	Installation of King KFC 200 automatic flight control system. Issued 6/18/79.	CE	48250	King Radio Corporation 400 NOrth Rogers Road Olathe, KS 66061
PA-28RT-201, -28RT-201T; T.C. 2A13	SA3323SW-D	Mitchell automatic flight system AK755 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 11/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3336SW-D	Mitchell automatic flight system AK777 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/21/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28-235; T.C. 2A13	SA1131EA	Installation of a radome pod SERP-1001 or -1002 on right wing. Amended 12/1/78.	EA	08332	David L. Stanislaw d/b/a Airquip Horsham Road Ambler, PA 19002
PA-28-235; T.C. 2A13	SA2143WE	Installation of drooped leading edge, drooped ailerons, wing stall fences, fuselage flap, drooped wing tips and elevator trim spring. Amended 12/30/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
PA-28-235; T.C. 2A13	SA2147WE	Installation of Brittain Industries B-7 flight control system. Reissued 11/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-235; T.C. 2A13	SA3187WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-235, PA-32-260, -300; T.C. A3SO, 2A13	SA1156EA	Installation of radome pod SERP-1021 or -1022 on right wing. Issued 6/26/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002
PA-28, PA-32; T.C. 2A13, A3SO	SA281AL	Installation of large nose gear fork and 8.00-6 nose gear tire. Amended 6/20/68.	AL	78487	Tibbetts-Herre Airmotive P.O. Box 110 Naknek, AK 99633
PA-28, PA-32; T.C. 2A13, A3SO	SA472SO	Installation of hand control for rudder pedal operation. Amended 6/27/74.	SO	85450	The Wheelchair Pilots Association 4211 Fourth Avenue South St. Petersburg, FL 33711
PA-28, PA-32; T.C. 2A13, A3SO	SA757SW	AK234 automatic flight system with Century II autopilot optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; PA-32-260; T.C. 2A13, A3SO	SA788SW	Piper auto-control II automatic pilot AK172E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA72RM	Installation of camera wells. Amended 12/9/76.	RM	42420	Horizons, Inc. P.O. Box 3134 Rapid City, SD 57701
PA-30 Series; T.C. A1EA	SA184EA	Installation of 13-quart alcohol propeller anti-icing kit utilizing either a Weldon pump (P/N 100B-6) or a Bendix pump (P/N 478360). Amended 10/15/71.	NE	86000	Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA225EA	Installation of Monitair angle of attack and stall warning system. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-30 Series; T.C. A1EA	SA233EA	Reservoir-type pneumatic wing and tail deicing system. Amended 10/7/70.	NE	86000	R.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA282CE	GUART System (Gear-up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 West Walnut Street Chicago, IL 60612
PA-30 Series; T.C. A1EA	SA343SW	Automatic pilot AK127, AK127E or AK127E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA477EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
PA-30 Series; T.C. A1EA	SA520SO	Installation of Bendix FCS-810 (Piper Altimatic V/F/D) automatic flight control including manual electric trim and optional flight director indicator. Amended 8/13/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-30 Series; T.C. A1EA	SA531SW	Fifth seat.	SW	61500	Mayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-30; T.C. A1EA	SA533NW	Installation of aileron trim. Issued 10/19/77.	NW	73160	Robert Smith Box 43 Okanagan Mission Kelowna, B.C., Canada
PA-30 Series; T.C. A1EA	SA534EA	Replacement of existing stall warning detector Safe Flight P/N C-52207 with pre-stall warning and speed control transducer, Safe Flight P/N 792 and speed control indicator, P/N 571.	EA	69500	Safe Flight Instruments Corp. New King Street White Plains, NY 10601
PA-30 Series; T.C. A1EA	SA559WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-30 Series; T.C. A1EA	SA576SW	AK186 altimatic III autopilot, AK179 stabilizer, and AK189 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA591CE	Install Alco XW20101-PA-30-L windshield wiper system.	CE	08750	Alco Controls Corporation P.O. Box 12700 St. Louis, MO 63141
PA-30 Series; T.C. A1EA	SA727WE	Installation of Brittain Industries Model TT-5 wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-30 Series; T.C. A1EA	SA738CE	Install King Radio KNC 610 area navigation computer. Amended May 1974.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA766WE	Plastic wing tips replaced with "Speedplates" SP51463.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
PA-30 Series; T.C. A1EA	SA767WE	Modification to include three pair of seat belts on rear seat to accommodate three passengers.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-30 Series; T.C. A1EA	SA776CE	Installation of King Radio KN-74 area navigation computer. Issued June 1971.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA789CE	Install Woodward propeller unfeathering accumulator system. Issued July 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-30 Series; T.C. A1EA	SA1111SW	Outer wing integral auxiliary fuel tanks and increase gross weight of 180 pounds.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1112SW	Dorsal fin.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1113SW	Extended nose with baggage compartment.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1114SW	Nacelle baggage compartments.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1115SW	Dual brakes.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1151SW	Lycoming IO-360-C1C engines (200 hp) with Hartzell HC-C2YK-2/C7666A-4 propeller. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1152SW	One-piece windshield. Issued 6/8/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1153SW	Square wing tips with dual navigation lights. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1154SW	Rudder and aileron interconnect system. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1337SW	Pneumatic de-icing system. Issued 7/8/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246
PA-30; T.C. A1EA	SA1401CE	Install King Model KNS 80 digital area navigation system. Issued 2/16/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olather, KS 66061

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-30 Series; T.C. A1EA	SA1935WE	Installation of Brittain flight control system Model B-5, NAV-2B, or B2C. Reissued 10/20/72.	SW	17400	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30; T.C. A1EA	SA3707WE	Installation of single piece windshield. Issued 8/7/78.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-30; T.C. A1EA	SA3729WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-30; T.C. A1EA	SA4066WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-30, PA-39; T.C. A1EA	SA209GL	Installation of one piece windshield. Issued 1/23/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-30, PA-39; T.C. A1EA	SA673EA	Installation of radome kit 3058X. Amended 5/26/76.	SW	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-30, PA-39; T.C. A1EA	SA676EA	Installation of Norton Company radome kit 3058-B. Amended 3/24/71.	SW	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-30, PA-39; T.C. A1EA	SA787WE	Installation of turbosupercharged Lycoming IO-320-B1A, IO-320-C1A or LIO-320-C1A engines. Amended 3/10/70.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA848EA	Installation of pneumatic pump operated wing and tail de-icing boot system. Issued 10/22/70.	NE	86000	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-30, PA-39; T.C. A1EA	SA1239SW	Turbosupercharged Lycoming IO-360-C1C engines. Issued 1/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30, PA-39; T.C. A1EA	SA1254SW	Electrothermal propeller de-icing system. Issued 1/27/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30, PA-39; T.C. A1EA	SA1320CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-30, PA-39; T.C. A1EA	SA1341SW	Nose taxi light. Issued 7/20/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246
PA-30, PA-39; T.C. A1EA	SA2312WE	Installation of leading edge cuffs, stall fences, stall strips drooped ailerons, flap actuated stabilator trim system, raked wing tips (optional) and dorsal fin. Amended 4/2/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-30, PA-39; T.C. A1EA	SA2849WE	Installation of oxygen system. Amended 10/3/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA3128SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional command automatic trim, readio, and glide slope couplers. Issued 5/6/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA3336WE	Installation of single piece windshield. Issued 2/2/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-31 (S/N 31-2 and up); T.C. A8EA	SA142RM	Install Model CFS-2000 fuel flow meter and related systems. Issued 5/12/78.	EA	77250	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31; T.C. A8EA	SA191GL	Installation of microwave landing airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31 Series; T.C. A20SO	SA367GL	Installation of Norton radome kit No. 2032X Issued 10/9/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA529EA	Installation of kit for radar antenna.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company P.O. Box 1187 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA541CE	Installation of Hoskins Twilighter Mk III supplemental lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-31 Series; T.C. A8EA	SA546EA	Incorporation of opening in lower surface of fuselage aft of front spar.	NE	86000	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-31 Series; T.C. A8EA	SA613EA	Installation of nine seats. Amended 6/6/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31 Series; T.C. A8EA	SA622EA	Incorporation of camera hatch and mountings to accommodate Zeiss RMK A15/23 camera.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
PA-31 Series; T.C. A8EA	SA741EA	Installation of co-pilot door. Amended 11/3/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31 Series; T.C. A8EA	SA865EA	Installation of radome kit 2031KX. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA908SW	Air conditioner.	SW	64410	R.D. Philpot Industries, Inc. Box 47062 Dallas, TX 75247
PA-31 Series; T.C. A8EA	SA986SW	Baggage lockers in revised aft nacelle fairings.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1000SW	Nine place seating arrangement.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1054SW	Stretcher.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1055SW	Baggage retaining net.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1065SW	Mitchell flight director and autopilot Model 282-187 with slaved directional gyro. Issued 9/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA1120SO	Installation of single camera and camera aperature on starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31, T.C. A20SO	SA1121SO	Installation of supply dropping aperature and sliding shutter and antenna fairing. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31; T.C. A20SO	SA1123SO	Installation of navigation sight and transparent plastic dome on the lower fuselage station 128. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31 Series; T.C. A8EA	SA1155SW	Three-place couch. Reissued 6/20/78.	SO	28380	Cypress Aviation, Inc. 3840 Drone Field road Lakeland Airport Lakeland, FL 33803
PA-31 Series; T.C. A8EA	SA1204SW	Manual electric trim AK281. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31 Series; T.C. A8EA	SA1234SW	Mitchell automatic flight system FD/AF282-273, consisting of flight director /autopilot with optional automatic aileron stabilizer AK273. Issued 12/21/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31 Series; T.C. A8EA	SA1305SW	Auxiliary fuel tank. Issued 5/10/71.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1340SW	Four-place couch. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 WEst, Meacham Field Fort Worth, TX 76106
PA-31 Series; T.C. A8EA	SA1569WE	Installation of windshield wiper system.	CE	08750	Alco Controls Corporation Box 12700 St. Louis, MO 63141
PA-31 Series; T.C. A8EA	SA1651WE	Installation of ski carrying pod under fuselage at wing root.	NW	57700	Melridge Aviation Company 1901 East Fifth Street Vancouver, WA 98661
PA-31 Series; T.C. A8EA	SA2124WE	Installation of air conditioning system.	RM	45750	J.B. Systems 120 South Bowen Circle Longmont, CO 80501
PA-31 Series; T.C. A8EA	SA3130SW-D	Mitchell automatic flight system AK589 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA3768WE	Installation of Fueltron digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-31, PA-31-300; T.C. A8EA	SA603EA	Addition of a 32-inch high door on L.H. side of fuselage between fuselage stations 244-261. Reissued 6/21/78.	SO	28380	Cypress Aviation, Inc. 3480 Drone Field Road Lakeland Airport Lakeland, FL 33803
PA-31, -300; T.C. A8EA	SA744EA	Modification of toilet seat hassock and installation of safety belt. Issued 4/4/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31, -300; T.C. A8EA	SA1255SW	Mitchell automatic flight system Model AK324 consisting of Piper autoflite II and tracking system. Issued 1/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA1522SW	Mitchell automatic flight system AK394, consisting of Century I autopilot with optional omni tracker. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3008SW-D	Automatic flight system AK483 consisting of Piper altimatic IIIC autopilot with optional command/ automatic electronic pitch trim, radio, and glide slope couplers. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3009SW-D	Automatic flight system AK496 and AK496FD consisting of Century IV autopilot and Century IV flight director with command/automatic electric elevator pitch trim and opticnal annuciator panel. Issued 7/12/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -31-300; T.C. A8EA	SA3010SW-D	Automatic flight system YK491 consisting of yaw damper. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -31-300, -325, -350; T.C. A8EA	SA1318CE	Chrome-plated brake disc installation. Issued May 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-31 (S/N 31-712 and up), PA-31-325, -350; T.C. A8EA	SA1529CE-D	Installation of King KAS 297 altitude selector option. Issued 2/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, -31-300, -325, -350; T.C. A8EA	SA3401WE	Installation of single piece windshield. Issued 5/10/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31, 31-300, PA-31P; T.C. A8EA	SA852EA	Installation of Grimes 555 Series three light strobe kit P/N 34-0100-1. Amended 5/10/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-31, -31P, -31-325, -31-350; T.C. A8EA	SA437SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and optional flight director indicator. Amended 4/4/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31, -31P, -31T, -31-300, -325, -350, -31T1; T.C. A8EA	SA1008EA	Installation of single lamp logo light in horizontal tail. Amended 11/16/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
PA-31, -31P, -31-300, -325, -350; T.C. A8EA	SA1187CE	Installation of King Model KCS 55A pictorial navigation (compass) with optional KS 52 autopilot adapter. Issued 12/10/75.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31-350, -31-325; T.C. A8EA	SA1166CE	Installation of King KFC-200, 2 axis (3 optional) flight control system, autopilot only or autopilot with flight director. Amended 1/4/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31T; T.C. A8EA	SA578NW	Install redesigned 7th seat (toilet). Issued 5/12/78.	NW	70640	Seattle Flight Service, Inc. 7001 Perimeter Road Seattle, WA 98108
PA-31-300; T.C. A8EA	SA184GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31-300, -310, -325, -350; T.C. A8CE	SA1136CE	Installation of Fiquench cabin fire extinguisher and engine fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
PA-31-325; T.C. A8EA	SA3017SW-D	Automatic flight system AK485 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim system, radio, and glide slope couplers. Issued 9/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3021SW-D	Automatic flight system AK500 and AK500FD consisting of Century IV autopilot and Century IV flight director autopilot with electronic command/automatic pitch trim system and optional annuciator panel. Issued 10/4/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3129SW-D	Automatic flight system AK590 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3211SW-D	Mitchell automatic flight system AK686 or AK686FD, Piper altimatic X flight director autopilot with optional remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA8NE	Installation of Collins AP-107 2-axis or 3-axis autopilot including yaw damper system. Reissued 12/19/74.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, NE Cedar Rapids, IA 52406
PA-31-350; T.C. A20SO	SA295GL	Install Cleveland conversion kit, P/N 199-83. Issued 3/15/79.	GL	23260	Cleveland Wheels & Brakes Vansickle Division of Parker Hannifin 1160 Center Road Avon, OH 44011
PA-31-350; T.C. A8EA	SA923SO	Installation of Bendix FCS-870 automatic flight control system. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31-350; T.C. A8EA	SA924SO	Installation of Bendix NP-2041A area navigation computer. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31-350; T.C. A20SO	SA1119SO	Installation of twin cameras and two camera aperatures on starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31-350; T.C. A20SO	SA1122SO	Installation of single camera and camera aperature on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1124SO	Installation of a single camera and camera aperature and antenna fairing on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1125SO	Installation of twin cameras and two camera aperatures plus camera sights on starboard side of lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A8EA	SA1611SW	Mitcheil automatic flight system AK413 consisting of altimatic IIIB-1 with optional automatic pitch trim, radio coupler, and glide slope couplers. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA1612SW	Mitchell automatic flight system AK416 consisting of autoflite II with optional tracking system. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA1807SW	AP106 2-axis or 3-axis autopilot including yaw damper and FD-108 flight director. Issued 2/14/74.	SW	24252	Collins Radio Company Box 98 Addison, TX 75001
PA-31-350; T.C. A8EA	SA3015SW-D	Automatic flight system AK-498, cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio, and glide slope coupler. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3016SW-D	Automatic flignt system AK499 and AK499FD cons. of Century IV flight director autopilot w/command automatic electric elevator pitch trim and opt. annunciator panel. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3086SW-D	Automatic flight system AK560 cons. of Century III autopilot w/ opt. radio & glide slope couplers. Issued 11/27/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3212SW-S	Mitchell automatic flight system Piper altimatic X autopilot, AK687 or AK687FD Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350, S/N 31-7405479 and up (S/N 31-5001 thru 7405478 when modified per Piper SL722); T.C. A20SO	SA4037WE	Installation of Siler Instruments fueltron IIIG or IIIP digital fuel and totalizer system. Amended 12/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-31P-425; T.C. A8EA	SA284GL	Install Cleveland conversion kit, P/N 199-83. Amended 2/28/79.	GL	23260	Cleveland Wheels & Brakes VanSickle Division of Parker Hannifin 1160 Center Road Avon, OH 44011
PA-31P; T.C. A8EA	SA483SO	Installation of Bendix YD4 yaw damper system. Issued 12/23/71.	SO	15475	Bendix Avionics Division P.O. Box 8414 Ft. Lauderdale, FL 33310
PA-31P; T.C. A8EA	SA782CE	Installation of King Radio H-14 autopilot. Issued 6/71.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
PA-31P; T.C. A8EA	SA1265SW	Mitchell automatic flight system model AK323 cons. of Piper Autoflite II and Omni tracking system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA1523SW	Mitchell automatic flight system AK395, cons. of Century autopilot w/opt. omni tracker. Issued 10/17/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31P; T.C. A8EA	SA3012SW-D	Automatic flight system AK484 cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 8/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3013SW-D	Automatic flight system AK492 & AK492FD cons. of Century IV autopilot and Century IV flight director w/command automatic electric pitch trim and opt. annunciator panel. Issued 8/9/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3014SW-D	Automatic flight system YK493 cons. of yaw damper. Issued 8/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3213SW-D	Mitchell automatic flight system Piper altimatic X autopilot, AK688 or AK688FD, Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31T; T.C. A8EA	SA190GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 8/16/77.	GL	46250	Jet Electronics and Technology, Inc. 5353 52nd Street N.E. Grand Rapids, MI 49508
PA-31T; T.C. A1EA	SA213GL	Installation of storm window in right hand cockpit window duplicating storm window now installed in left hand cockpit window. Issued 2/2/78.	GL	61629	Northern Airmotive, Inc. 3600 East 70th Street Minneapolis, MN 55450
PA-31T; T.C. A8EA	SA578SO	Instl. of a Bendix M-4D automatic flight control system, including optional manual electric pitch trim and flight director system. Amended 10/1/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
PA-31T; T.C. A8EA	SA665NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. Issued 9/14/78.	NW	28850	Robert M. DeBorde 20645 S.W. Clarion Aloha, OR 97005
PA-31T; T.C. A8EA	SA1188CE	Intallation of King KFC 300 automatic flight control system. Amended 1/20/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31T; T.C. A8EA	SA4016WE	Installation of SDI model CFS-2002, fuel flow indicating system. Issued 8/31/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-31T; T.C. A8EA	SA4066SW	Auto-feather system 1. Issued 12/4/79.	EA	64665	Piper Aircraft Corporation 820 East Bald Eagle Drive Lockhaven, PA 17745
PA-31T1; T.C. A8EA	SA1053SO	Installation of FCS-870 automatic flight control system, including manual electric trim, optional yaw damper system, and optional flight director. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31T1; T.C. A8EA	SA1054SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31T1; T.C. A8EA	SA1405CE	Install King KFC-250 autopilot/flight director. Amended 9/28/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32; T.C. A3SO	SA311NW	Installation of flap extension, spoiler L/E cuff and optional cambered wing tips. Issued 5/28/76.	NW	68500	Robertson Aircraft 839 W. Perimeter Road Renton, WA 98055
PA-32; T.C. A3SO	SA532SW	AK173 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32; T.C. A3SO	SA1523WE	Inst'l. of Brittain Model B 4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-32; T.C. A3SO	SA1607WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-32-260; T.C. A3SO	SA371EA	Zeiss aerial camera and intervalometer.	NE	71400	James W. Sewall Co. 147 Center Street Old Town, ME 00468
PA-32-260; T.C. A3SO	SA533SW	Auto-Control III AK174.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA538SW	Piper Altimatic II autopilot and/or radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA1310SW	Stretcher in lieu of rear seats. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72203
PA-32-260; T.C. A3SO	SA1557WE	Installation of turbosupercharged Lycoming 0-540-E4B5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
PA-32-260, -32-300; T.C. A3SO	SA3NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 8/1/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
PA-32-260, -32-300; T.C. A3SO	SA530CE	Install FluiDyne Model 4000 & 2500A skis.	GL	36060	FluiDyne Engr. Corp. 5900 Olson Memorial Hwy. Minneapolis, MN 55422
PA-32-260, -32-300; T.C. A3SO	SA939SW	Mitchell Manual Electric Pitch Trim System AK272.	SW	76067	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300; T.C. A3SO	SA1362CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-32-260, -32-300; T.C. A3SO	SA1568SW	Wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-32-260, -32-300; T.C. A3SO	SA2217WE	Installation of recontoured wing leading edge, raked wing tips, fuselage flap, stall fences, droop ailerons and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 1540 Sunset Highway Bellevue, WA 98007
PA-32-260, -32-300; T.C. A3SO	SA2933WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 Wardlow Road Long Beach, CA 90807
PA-32-260, -32-300; T.C. A3SO	SA3173SW-D	Automatic flight system AK174 cons. of Piper autocontrol IIIB autopilot w/opt radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32S-300; T.C. A3SO	SA1172SW	Mitchell flight system AK304 cons. of Piper autoflite II with optional auto aileron stabilizer and tracking system. Issued 7/17/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32S-300; T.C. A3SO	SA1378SW	Mitchell automatic flight system AK320, cons. of Century I and opt. tracker. Issued 10/26/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300 -32S-300; T.C. A3SO	SA3011SW-D	Automatic flight system AK488 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -300, -32R-300;	SA3736WE	Installation of an engine oil cooler hose. Issued 9/22/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-32-260, -300, -32S-300, -32R-300; T.C. A3SO	SA3839WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
PA-32-300; T.C. A3SO	SA893EA	Installation of 8-quart alcohol propeller anti-icing kit WAP-800A. Issued 12/15/71.	NE	86000	E. W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-32-300; T.C. A3SO	SA3305SW-D	Mitchell automatic flight system AK775 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 9/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300; T.C. A3SO	SA3306SW-D	Mitchell automatic flight system AK776, consisting of Century III autopilot with optional and glide slope couplers. Issued 9/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300, -32R-300, -32RT-300, -32RT-300T; T.C. A3SO	SA364GL	For "T" tail configuration - installation of Norton radome kit No. 4229X. For conventional tail configuration - installation of Norton radome kit No. 4229XC. Amended 1/17/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Oeprations P.O. Box 350 Akron, OH 44309
PA-32-300, -32R-300; T.C. A3SO	SA1154EA	Installation of radome pod SERP-1011 or -1012 on right wing. Amended 12/6/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002
PA-32-300, -32R-300; T.C. A3SO	SA3670WE	Installation of Silver Instruments Fueltron IG digital fuel flow indicating system. Issued 6/23/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-32-300, -32R-300, -32S-300, -32RT-300; T.C. A3SO	SA3774WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-32R; T.C. A3SO	SA21NE	Installation of Whelen A600-PR and A600-PG anti-collision strobe with forward and tail position light assemblies as replacements for wing tip lights. Issued 3/1/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
PA-32R-200; T.C. A3SO	SA-3102SW-D	Mitchell AK591, consisting of Century IIB autopilot w/opt radio coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-200; T.C. A3SO	SA3103SW-D	Mitchell AK592 cons. of Century III autopilot w/opt. radio coupler and glide slope coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA260GL	Install a Foster Airdata RNAV 511 area navigation system with 51ASA (Alpha) or 51DSA (Delta) steering adapter, or without either adapter. Amended 6/29/79.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
PA-32R-300; T.C. A3SO	SA975SO	Installation of two 15-gallon auxiliary fuel tanks, one in each wing. Issued 4/5/78.	SO	28380	Cypress Aviation, Inc. 3480 Drane Field Road Lakeland Municipal Airport Lakeland, FL 33803
PA32R-300 S/N 32R-7680001 and up; T.C. A3SO	SA1201CE	Installation of King KFC 200, 2 axis, flight control system with a King KCS-55 (or -55A) compass and a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 9/9/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32R-300; T.C. A3SO	SA3052SW-D	Mitchell automatic flight system AK529 cons. of Piper altimetric IIIC w/command/auto. elec. pitch trim, opt. radio coupler and glide slope coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3053SW-D	Installation of Mitchell automatic flight system AK530 cons. of Piper autocontrol IIIB autopilot with opt. radio coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3054SW-D	Mitchell automatic flight system AK531 cons. of Piper autoflite II w/opt. omni tracker. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3055SW-D	Mitchell command/electric trim system Model AK532. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-32R-300; T.C. A3SO	SA3513WE	Installation of Rajay turbocharged Lycoming IO-540-K1G5D engine. Issued 11/8/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
PA-32RT-300, -32RT-300T;	SA1159EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
PA-32RT-300, PA-32RT-300T; T.C. A3SO	SA1430CE	Install King KFC-200 automatic flight control system. Issued 8/9/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32RT-300; T.C. A3SO	SA3253SW-D	Mitchell automatic flight system AK677 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3254SW-D	Mitchell command electric trim system AK 678. Issued 2/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3255SW-D	Mitchell automatic flight system AK 679 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300T; T.C. A3SO	SA3309SW-D	Installation of Mitchell automatic flight system consisting of Century IV autopilot or AK771 consisting of flight director autopilot with optional remote annunciator. Issued 10/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32S-300; T.C. A3SO	SA932EA	Installation of Pee Kay Model B3500 seaplane floats and Pee Kay Model 3500A amphibious floats. Issued 9/22/72.	EA	29998	Pee Kay DeVore Inc. 125 Mineola Avenue Roselyn Heights, NY 11577
PA-32S-300; T.C. A3SO	SA2253WE	Installation of Edo Model FD-3500-21 amphibious floats. Reissued 5/24/76.	NE	23370	T. M. Close Corporation Gardner Municipal Arpt. Box 464 Gardner, MA 01440
PA-32R-301, -32R-301T; T.C. A3SO	SA1522CE-D	Installation of King KFC 200 flight control system. Issued 12/17/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-34; T.C. A7SO	SA1363CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-34; T.C. A7SO	SA2285SW	Camera and viewfinder installation. Issued 1/22/76.	SW	42825	A. D. Howard, Jr. 1911 Moulton Ct. Oklahoma City, OK 73127
PA-34-200; T.C. A7SO	SA154NW	Installation of full span flaps by removing aileron and changing deployment route of all flaps, spoilers mounted above flap, conical cambered wing tips, anti-balance rudder tab and optional dorsal fin. Issued 1/28/75.	NW	68500	Robertson Aircraft Corp. 839 W. Perimeter Road Renton, WA 98055
PA-34-200; T.C. A7SO	SA292NW	Installation of cooling louvers on top of both nacelle accessory sections. Issued 5/13/76.	NW	01530	Advanced Aviation 4911 S. 290th Place Auburn, WA 98002
PA-34-200; T.C. A7SO	SA493SO	Installation of Bendix FCS-810 (Piper altimatic V/FD) automatic flight control system including manual electric trim and optional flight director indicator. Issued 2/17/72.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
PA-34-200; T.C. A7SO	SA900EA	Installation of electrothermal propeller de-icer system. Amended 1/14/74.	GL	38500	B. F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200; T.C. A7SO	SA901EA	Installation of wing ice light kit. Amended 12/6/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-34-200; T.C. A7SO	SA1321SW	Mitchell automatic flight system AK298 cons. of altimatic IIIB-1 autopilot w/opt automatic command electric pitch trim, radio coupler and glide slope coupler. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA1322SW	Mitchell automatic flight system Model AK335 cons. of Piper autocontrol III w/opt. radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA1323SW	Mitchell command electric pitch trim Model AK321. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA2932WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA2937WE	Installation of turbosupercharged Lycoming IO/LIO-360-C1E6 engine. Amended 3/31/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA3002WE	Installation of wing tip fuel tanks of 17 gal capacity (each). Reissued 5/14/76.	WE	68501	Robertson Aircraft Corp. 2301 E. Utopia Rd. Phoenix, AZ 85024
PA-34-200, S/N 34-E4, S/N 34-7250001 and up; T.C. A7SO	SA903EA	Installation of B.F. Goodrich pneumatic de-icing system. Amended 11/1/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200, -34-200T; T.C. A7SO	SA50GL	Installation of Norton Radome Kit No. 4011KX Amended 3/15/79.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Product Division P.O. Box 350 Akron, OH 44309
PA-34-200, -34-200T; T.C. A7SO	SA510NW	Installation of Cessna fuel tank assembly. Issued 8/20/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
PA-34-200, -34-200T; T.C. A7SO	SA3554WE	Installation of vertical tail floodlights on horizontal stabilizer. Issued 1/11/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
PA-34-200T; T.C. A7SO	SA106RM	Installation of freon type air conditioning system. Issued 8/3/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-34-200T; T.C. A7SO	SA154RM	Install Symbolic Displays TSO'd Model CFS-2000 fuel flow meter and related systems. Issued 9/22/78.	RM	77248	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-34-200T; T.C. A7SO	SA968SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 1/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7SO	SA969SO	Installation of NP-2041A area navigation computer programmer. Issued 1/9/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7DO	SA1118SO	Installation of Hartzell 3-bladed propellers, Models - PHC-C3YF-2( )UF/FC-7663-2R and PHC-C3YF-2L( )UF/FJC-7663-2R or PHC-C3YF--( )UF/FC-7663B-2R and PHC-C3YF-2L( )UF/FJC-7663B-2R. Issued 12/21/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
PA-34-200T; T.C. A7SO	SA1147CE	Installation of King Model KFC 200 flight control system, with King KCS 55 or 55A compass and a King KI-255 (or -256) flight command indicator on a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 9/13/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
PA-34-200T; T.C. A7SO	SA3023SW-D	Automatic flight system AK487 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electronic elevator pitch trim, radio, and glide coupler. Issued 9/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-34-200T; T.C. A7SO	SA3024SW-D	Automatic flight system AK505 cons. of Piper auto-control IIIB autopilot w/opt. radio coupler. Issued 10/24/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3089SW-D	Mitchell automatic flight system AK561 cons. of Century III Autopilot w/opt radio coupler and glide slope coupler. Issued 12/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3669WE	Installation of FUELTRON IIIG digital fuel flow indicating system. Issued 6/21/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-36; T.C. A9SO	SA277NW	Installation of automatic flagman. Issued 3/30/76.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362
PA-36; T.C. A9SO	SA1364CE	Chrome-plated brake disc installaticn. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas Citym KS 66103
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	SA1291CE	Installation of Lycoming IO-720-A1B engine. Amended 4/17/79.	CE	11003	Mr. Clinton Anderson Nehawka, NB 68413
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	SA3452WE	Installation of Lycoming IO-720-A1B engine and Hartzell HC-C3YR-1RF/F8475R constant speed propeller. Amended 2/5/79.	WE	46790	Johnston Aircraft Service, Inc. P.O. Box 1457 Tulare Municipal Airport Tulare, CA 93274
PA-36-375; T.C. A10SO	SA3535WE	Installation of hydraulic system to power spray dispersal system. Issued 12/21/77.	WE	03290	Agrinautics 1333 Patrick Lane Las Vegas, NV 89119
PA-36-375; T.C. A10SO	SA3703WE	Installation of hydraulic power spray pump. Issued 7/27/78.	WE	03290	Agrinautics 1333 Patrick Lane Las Vegas, NV 89119
PA-39 Series; T.C. A1EA	SA816EA	Installation of 13 quart alcohol propeller anti-icing kit WAP-500B. Amended 10/15/71.	NE	86000	Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-39 Series; T.C. A1EA	SA1342SW	Mitchell automatic flight system AK296 cons. of Piper altimatic IIIB-1 autopilot w/opt. automatic pitch trim, radio, and glide slope couplers. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1343SW	Mitchell automatic flight system AK325 cons. of Piper autoflite II w/opt. tracking system. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1344SW	Mitchell command electric trim AK267. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1386SW	Mitchell automatic flight system model AK339, cons. of Piper autocontrol III autopilot with optional radio coupler. Issued 11/16/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1638SW	Mithcell automatic flight system AK355, consisting of Century I with omni tracker. Issued 4/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-40; T.C. A1EA	SA3028SW-D	Mitchell auto. flight system AK481, consisting of Piper altimatic IIIC autopilot with command automatic electric pitch trim system, optional radio, and glide slope couplers. Issued 10/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-40; T.C. A1EA	SA3036SW-D	Automatic flight system AK506 consisting of Piper autocontrol IIIB autopilot with optional radio coupler. Issued 12/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA1158EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-44-180; T.C. A19SO	SA1504CE	Installation of King KFC 200 FCS (2 axis) with or without flight director. Issued 8/2/79.	SW	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-44-180; T.C. A19SO	SA3276SW-D	Installation of Mitchell automatic flight system AK 723 consisting of Piper autocontrol IIIB with optional radio couplers. Issued 4/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA44-180; T.C. A19SO	SA3277SW-D	Mitchell automatic flight system AK719 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 4/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3278SW-D	Mitchell command electric trim AK718.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3287SW-D	Mitchell automatic flight system AK756 consisting of Century IIB autopilot with optional radio coupler. Issued 5/26/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3288SW-D	Mitchell automatic flight system AK757 consisting of Century III autopilot with optional radio and and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell INdustries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MISCELLANEOUS	SA788WE	Mixture monitor (exhaust gas temperature probe and gage). See FAA-approved eligibility list for models.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PIPER AIRCRAFT CORPORATION, CALIFORNIA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
600; T.C. A17WE	SA1347SW	Alternate vent for fuel pressure gages. Issued 7/22/71.	SW	84250	Vought Aircraft Service Company Meacham Field Fort Worth, TX 76106
600; T.C. A17WE	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
600; T.C. A17WE	SA1675WE	Installation of K S Avionics EGT-2 exhaust gas monitoring system. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
600 (S/N 60-0266-XX and up, and those aircraft with previously installed option #108); T.C. A17WE	SA3770WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 6/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
600, 601; T.C. A17WE	SA20GL	Installation of Woodward electronic propeller synchronizer system. Amended 11/6/75.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601; T.C. A17WE	SA35GL	Install wheel and brake conversion kit P/N 199-51. Reissued 7/23/74.	GL	23260	Cleveland Wheels & Brakes Div. Van Sickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
600, 601; T.C. A17WE	SA443SO	Instllation of Bendix RDR-110 weather radar system per Bendix drawing 4009700, Rev. B. Installation of Norton AD4059KX-5 radome approved per STC SA845EA. Issued 9/25/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601; T.C. A17WE	SA771CE	Installation of Woodward propeller unfeathering accumulator system. Issued June 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601; T.C. A17WE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
600, 601; T.C. A17WE	SA845EA	Installation of radome kit P/N 4059KX or 4059X. Reissued 9/29/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
600, 601; T.C. A17WE	SA1308SW	Addition of toilet provision. Issued 5/7/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1356SW	Fabricate and install rib-wing fairing-inboard (flap attachment bracket). Issued 8/13/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1362SW	Storage drawers under cabin seats. Issued 9/3/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76067
600, 601; T.C. A17WE	SA1363SW	Installation of pressure relief valves in fuel tanks. Issued 9/3/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1382SW	Modify two passenger seats to face aft. Issued 10/29/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1391SW	Dual hydraulic pump. Issued 11/12/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1452SW	Modfy Ted Smith control tube P/N A600128-3. Issued 3/30/72.	GL	84250	Vought Aircraft Services Compay Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1797SW	Mitchell automatic flight system AK459 consisting of Century autopilot with optional omni tracker. Issued 1/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
600, 601; T.C. A17WE	SA2357WE	Installation of auxiliary hydraulic pump. Issued 5/28/71.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
600, 601; T.C. A17WE	SA3884WE	Installation of cabin door pneumatic spring counter-balance. Issued 4/5/79.	WE	64423	Physical Systems, Inc. 7049 Vineland Avenue North Hollywood, CA 91605
600, 601, 601P; T.C. A17WE	SA444SO	Intallation of Bendix Model FCS 810 flight control system, including flight director indicator DH 841( ). Amended 6/3/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601, 601P; T.C. A17WE	SA1089CE-D	Installation of Collins Radio Group AP-106 autopilot system and interface with Collins FD-112 flight director. Amended 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1090CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1104CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1174CE	Installation of Aero Space Controls Corp. 100 AMP alternator. Issued 10/31/75.	CE	02950	Aero Space controls Corporation 1050 North Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1175CE	Installation of Aero Space Controls Corp. air conditioning system. Issued 10/31/75.	CE	02950	Aero Space Controls Corporation 1050 Nort Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1184CE	Install King Model KFC-200 2-axis (3 optional) flight control system with King KCS-55 (or -55A) compass and a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 9/1/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
600, 601, 601P; T.C. A17WE	SA1277CE	Installation of Avcon Industries TSO-C39a stretcher, P/N 4001-101 or 4001-102. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
600, 601, 601P; T.C. A17WE	SA2207WE	Installation of JB Systems air conditioning system. Amended 5/21/76.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
600, 601, 601P; T.C. A17WE	SA2336WE	Installation of Prestolite 70 amp alternators (Avco Lycoming P/N 78314) in lieu of existing 50 amp alternators. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA2367WE	Installaton of Prestolite 70 amp alternators (Avco Lycoming P/N 78314). Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA2655WE	Installation of auxiliary hydraulic pump option. Reissued 4/11/78.	WE	64666	Piper Aircraft corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA3029SW-D	Mitchell automatic flight system AK521 consisting of Century III autopilot with command automatic electric pitch trim system, radio, and glide slope couplers. Issued 11/27/74.	SW	60000	Mitchell Indusries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3030SW-D	Mitchell automatic flight system AK522 or AK522FD consisting of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim and optional annuciator panel. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
600, 601, 601P; T.C. A17WE	SA3033SW-D	Automatic flight system AK455 consisting of Century I autopilot with optional omni tracker. Issued 1/9/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3643WE	Installation of vertical tail floodlight. Issued 5/24/78.	WE	30000	DeVore Aviation 16160 Stagg Street Van Nuys, CA 91406
600, 601, 601P (S/N 60-0266-XX and up and those aircraft with previously installed option #108); T.C. A17WE	SA3370WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 6/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
600, 601, 601P S/N 266 and up and aircraft with option 108 previously installed; T.C. A17WE	SA4029WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 9/21/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
601; T.C. A17WE	SA2346WE	Installation of turbocharger overboost protection. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601; T.C. A17WE	SA2664WE	Modification of fuselage structure for pressurization to 3.20 psi operating pressure, and installation of pressurization system. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601P; T.C. A17WE	SA61GL	Installation of radome kit P/N 4079KX or 4079X. Reissued 8/29/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

J.C. PIRTLE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
185; T.C. 776	SA4-22	Hartzell HC12X20-8D, B8428-6 propeller assembly.	WE	59710	Albert J. Misevic 317 East Broad Street Port Hueneme, CA 93041

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
PRATT, READ & COMPANY, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PR-G1; G.T.C. 12	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
PR-G1; G.T.C. 12	SG4-1411	Ceconite 103 covering of glider.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PR-G1; G.T.C. 12	SG10WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 103 material. Amended 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
PR-G1; G.T.C. 12	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PRCCAER S.P.A.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F15/B; T.C. A1IN	SA308EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
F15/B; T.C. A1IN	SA489EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
PROP-JETS, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
(Interceptor) 200 Series; T.C. 3A18	SA4-891	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
(Interceptor) 200 Series; T.C. 3A18	SA423CE	Wing tips.	SO	26580	Corben Development Corporation P.O. Box 1603 Venice, FL 33595
(Interceptor) 200 Series; T.C. 3A18	SA798EA	Installation of Monitair exhaust gas combination monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
(Interceptor) 200 Series; T.C. 3A18	SA1300WE	Installation of Brittain Model ACS-1 stability augmentation system.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
(Interceptor) 200 Series; T.C. 3A18	SA1500WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
(Interceptor) 200 Series; T.C. 3A18	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
(Interceptor) 200, 200A; T.C. 3A18	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
(Interceptor) 200, 200A, B, C, D; T.C. 3A18	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
(Interceptor) 200B; T.C. 3A18	SA1686WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
(Interceptor) 200B, C, D; T.C. 3A18	SA3240SW-D	Mitchell automatic flight system AK710, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 9/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
(Interceptor) 200B, C, D; T.C. 3A18	SA3242SW-D	Mitchell automatic flight system AK708, consisting of Century I autopilot with optional omni tracker. Issued 9/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
(Interceptor) 220B, C, D; T.C. 3A18	SA3243SW-D	Mitchell yaw damper system YK712. Issued 9/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

JOE RANKIN

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
(Porterfield) 35, 35-70; ATC 567	SA4-1095	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
(Porterfield) 35, -70, LP-65; ATC 567, T.C. 720	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Porterfield) 35, 35-70, LP-65; ATC 567, T.C. 720	SA2666WE	Ceconite 102 material covering of: 35, 35-70 - complete aircraft; LP-65 - fuselage and vertical tip. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Porterfield) CP-55, CP-65, CS-65, FP-65, LP-65; T.C. 720	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
(Porterfield) CP-55, CP-65, LP-65, FP-65, CS-65; T.C. A-720	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powee y Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
(Porterfield) CP-55, CP-65, LP-65, FP-65, CS-65; T.C. A-720	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
(Porterfield) LP-65; T.C. 720	SA4-1564	Ceconite 101 covering of fuselage and vertical fin.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

RAVEN INDUSTRIES, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S-40A; T.C. A15CE	SB1WE	Replacement of Raven single burner system P/N 09645 with Raven two burner system P/N 10118 on Raven S-40 model balloon. Amended 10/2/75.	WE	70550	Scorpion Productions 246 Lomita Drive P.O. Box 1147
S-40A, S-50A, S-55A; T.C. A15CE	SL163GL	Modification: move the velcro 4 to 6 inches back away from the lip of the deflation port. Enlarge deflation panel. Issued 4/22/77.	GL	85870	Matt H. Wiederkehr 1604 Euclid Street St. Paul, MN 55106
S-40A, S-50A, S-60A; T.C. A15CE	SL575SO	Installation of ABP-181 automatic balloon pilot (automatic temperature control). Reissued 11/5/74.	SO	23345	J. Donald Cline 807 Larkwood Drive Greensboro, NC 27410
S-40A, -50A, -60A; T.C. A15CE	SL575SO	Installation of ABP-181 automatic balloon pilot (automatic temperature control). Reissued 11/5/74.	SO	23345	J. Donald Cline 807 Larkwood Drive Greensboro, NC 27410
S-40A, -50A, -60A; T.C. A15CE	SA1720SW	Install four burner can assembly. Issued 8/28/73.	SW	28308	Cutter Flying Service, Inc. P.O. Box 274 Albuquerque, NM 87108
S-40A, S-50A, S-55A, S-60A, RX-6; T.C. A15CE	SB4WE	Installation of digital readout balloon envelope temperature indicator. Issued 5/6/77.	WE	01450	Advanced Aircraft Components 1459 Irving Avenue Glendale, CA 91201
S-40A, -50A, -55A, -60A, RX-6, -7; T.C. A15CE	SB9WE	Installation of a digital readout balloon envelope temperature indicator. Issued 11/14/79.	WE	01450	Advanced Aircraft Components 1459 Irving Avenue Glendale, CA 91201
S-50A, S-55A, S-60A; T.C. A15CE	SL962SO	Installation of ball lock pins, MS 17985-545 or MS 17984-545. Amended 6/26/78.	SO	14285	Balloons, Inc. 1978 East Roxboro Road, N.E. Atlanta, GA 30324
S-60A; A15CE	SL164GL	Modification: Move the velcro 4 to 6 inches back away from the lip deflation panel. Issued 4/22/77.	GL	85870	Matt H. Wiederkehr 1604 Euclid Street St. Paul, MN 55106

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
REIMS AVIATION S.A.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F150G, H, J, K, FA150K, F150L, FA150L, FRA150L, F172F, G, H, K, L, M; T.C. A13EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AF in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
F150G, H, J, K, FA150K, F150L, FA150L, FRA150L, F172F, G, H, K, L, M; T.C. A13EU	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
F150G; F172; T.C. A13EU, A4EU	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
F150G, H, J, K, L, FA150K, FA150L, F150L; T.C. A13EU	SA1809WE	Installation of one 12-gallon auxiliary fuel tank in each outboard wing panel. Amended 2/22/74.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041
F172F, G, H, K, L, M, N, FR172E, F, G, H, J, K; T.C. A4EU	SA1614WE	Installation of one 12-gallon auxiliary fuel tank in each outboard wing panel. Amended 2/15/79.	WE	35746	Flint Aero 8402-G North Magnolia Gillespie Field Plaza Santee, CA 92071
F177RG; T.C. A26EU	SA71GL	Installation of P/N BA 5710 filter assembly. Issued 12/29/77.	WE	17062	Brackett Aircraft Specialties Co. 4910 East Falcon Drive Mesa, AZ 85205
F182P; T.C. A42EU	SA1758WE	Installation of 12-gallon auxiliary fuel tank in each wing inboard of tip. Amended 2/15/79.	WE	35780	Flint Aero 8402-G Magnolia Avenue Gillespie Airport Plaza Santee, CA 92071
F337E, F, G, FT337E, F, G; T.C. A23EU	SA20GL	Installation of Woodward electronic propeller synchronizer system. Amended 10/30/75.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ROBERTS AIRCRAFT COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
(Chase) YC-122C; T.C. AR-25	SA114WE	Ceconite 101 covering of ailerons, rudder and elevators.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
(Chase) YC-122C; T.C. AR-25	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Chase) YC-122C; T.C. AR-25	SA2666WE	Ceconite 102 material covering of ailerons, rudder and elevators. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ROCKWELL INTERNATIONAL CORPORATION, CALIFORNIA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265; T.C. A2WE	SA16GL	Incorporating AMF (Leland) inverters MGE 23-400. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
NA-265; T.C. A2WE	SA687NW	Installation of Mark II system, increased take-off weight, wing modifications, modified A-O-A system, landing gear beef-up. Issued 11/15/78.	NW	66175	The Raisbeck Group 7777 Perimeter Road, South Seattle, WA 98108
NA-265 Series; T.C. A2WE	ST1031SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 11/16/78.	SO	78053	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
NA-265; T.C. A2WE	SA1569SW	Battery temperature sensor warning system. Issued 12/14/72.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
NA-265; T.C. A2WE	SA1854WE	Installation of aft ballast, optional large capacity batteries, heavy duty landing gear assemblies, and extended center of gravity limits. Reissued 7/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Capham Street El Segundo, CA 90245
NA-265, NA-265-20, -30, -40, -60, -70, -80; T.C. A2WE	SA1290CE	Installation of Avcon Industries TSC-C39a stretcher P/N 4006-103 and/or 4006-104. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street Wichita, KS 67204
NA-265, NA-265-20, -30, -40, -60, -70, -80; T.C. A2WE	SA3052WE	Installation of recognition light on horizontal stabilizer upper surfaces. Amended 10/14/75.	WE	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 94106
NA-265-40; T.C. A2WE	SA139CE	General interior configuration, 7 place. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA140CE	Reclining passenger seat installation (Tpy). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA141CE	Swivel reclining passenger seat installation (Typ). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA142CE	Two place passenger couch installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA143CE	Crew and passenger oxygen system installation. Amended 8/22/77.	CE	28765	Sabreliner Completion Center Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-40; T.C. A2WE	SA171CE	General interior configuration, 8 place - version #2. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA172CE	Two place passenger seat installation (typ). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA181CE	Two place passenger/baggage seat. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5501 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA204CE	General interior configuration, 9 place - version #4. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA205CE	Hand baggage rack installation, stations 147 - 206. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA206CE	Auxiliary passenger seat installation, station 194. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-40; T.C. A2WE	SA219CE	Electronics components package version E. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA220CE	Electronic components package version D. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA221CE	General interior configuration, 9 place version #5. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA243CE	Electronics components package version G. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA244CE	Electronics components package version F. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA245CE	Auxiliary hand baggage rack installation, station 186. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA246CE	General interior configuration, 8 place - version #6. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	ST267GL	Installation of dual Marconi CMA-734 Omega navigation system. Amended 6/1/79.	WE	18752	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
NA-265-40; T.C. A2WE	SA277CE	Electronic components package version H. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA314CE	Electronic components package version J. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA352CE	Engine vibration monitor installation, Airborne JT-12A6A engine. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA384CE	Electronic components package version K. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA401CE	Electronic components package version L. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA409CE	Electronics components package version M. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA431CE	Install Hoskins Twilighter Mk III supplemental lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
NA-265-40; T.C. A2WE	SA449CE	Installation of H.F. transceiver, Sun Air Model T22-RA. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-40; T.C. A2WE	SA450CE	Installation of electronics components package version N, Option A. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA475CE	Install 11 place interior, version #7. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA476CE	Passenger seat. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA477CE	Three place passenger seat. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA509CE	Install ten-place interior, version #8. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-40; T.C. A2WE	SA521CE	Installation of HF radio, SunAir Model ASB100. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA628CE	Installation of oxygen system pressure diluter demand crew members - constant flow - passengers. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA637CE	Installation of electronics components package, version R. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA640CE	Installation of yaw damper control switch. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA648CE	Installation of doppler/computer navigation system, Bendix DRA-12/CPA-24. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA699CE	Installation of electronic component package, version T. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA743CE	Installation of United Control Model P-542M flight data recorder system.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA846CE	Interior arrangement - installation of an aislewise divan. Issued August 1972.	CE	33580	EPM Corporation P.O. Box 5970 St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA860CE	Installation of electronics components package, version V. Amended May 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-40; T.C. A2WE	SA871CE	Electronic components package version W installation. Amended May 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-40; T.C. A2WE	SA875CE	Install eight-place interior, version #10. Issued December 1972.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA885CA	Installation of electronic components package, version Y. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-40; T.C. A2WE	SA1057CE	Installation of electronic components package, version Z. Issued January 1975.	CE	68765	Sabreliner Division Rockwell International Lambert-St. Louis Int'l Airport St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA1460SW	Modification of 2-place aft couch installed under SA172CE to 3-place and add one oxygen dropout mask. Issued 5/5/72.	SW	29000	The Dee Howard Company P.O. Box 16216 San ANtonio, TX 78246
NA-265-40; T.C. A2WE	SA1232WE	Replacement of carbon pile voltage regulator for 30-volt DC generator with Leland Airborne Products Type CSV-11-5-2 solid state voltage regulator.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
NA-265-40; T.C. A2WE	SA2596WE	Installation of Collins Model ALT-50 radio altimeter. Reissued 7/23/73.	WE	68770	North American Rockwell Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-40; T.C. A2WE	SA2597WE	Category II approval of airborne instruments and equipment when modified in accordance with STC SA860CE and SA2596WE. Reissued 7/23/73.	WE	68770	North American Rockwell Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-40, -40A; T.C. A2WE	SA1663SW	Teledyne avionics normalized angle of attack indicating system, P/N 1122600. Amended 8/27/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906

ROCKWELL INTERNATIONAL CORP., CA 4

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-40, -60; T.C. A2WE	SA67GL	Install B.F. Goodrich pneumatic de-icer system listed on Master Drawing List Report No. 74-04-047B, 11/6/74. Issued 11/22/74.	GL	38500	B.F. Goodrich Engineered Systems 500 South Main Street Akron, OH 44318
NA-265-40, -60; T.C. A2WE	SA718CE	Installation of hydraulic system fail audible warning system. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60; T.C. A2WE	SA859CE	Installation of twin Hamilton Standard R70-3W refrigeration unit. Issued August 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-40, -60; T.C. A2WE	SA882CE	Installation of TRAMM BTI-600 battery temperature indicator and aircraft services division isolation system. Issued March 1973.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-365-40, -60; T.C. A2WE	SA926EA	Installation of Grimes three light strobe kit, P/N 34-0300-1, as supplemental lighting. Issued 7/7/72.	GL	39500	Grimes Manufacturing Company 515 NOrth Russell Street Urbana, OH 43078
NA-265-40, -60; T.C. A2WE	SA970CE	Installation of Sperry Model AA-220 radio altimeter. Issued March 1974.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63145
NA-265-40, -60; T.C. A2WE	SA1013SW	Phoenix Aerospace, Inc. voltage regulator, VR-1010-24-1A. Issued 3/24/69.	SW	79650	Trio Aviation and Manufacturing Company, Inc. P.O. Box 20596 Dallas, TX 75220
NA-265-40, -60; T.C. A2WE	SA1266WE	Installation of rain repellant system. Amended 11/21/75.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
NA-265-40, -60; T.C. A2WE	SA1365CE	Install compensated pitot static heads (Rosemount Engineering). Amended 12/27/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA265-40, -60; T.C. A2WE	SA1409CE	Rewire battery isolation relay system. Issued 4/14/78.	CE	84995	Wells Aircraft, Inc. Municipal Airport Hutichinson, KS 67501
NA265-40, -60; T.C. A2WE	SA1429CE	Removal of fuel jettisoning provisions. Issued 8/4/78.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60; T.C. A2WE	SA1725SW	Foxtronics/TRAMM BTI-600 nickel cadmium battery temperature indicator and optional TRAMM R-600 voltage control. Issued 11/7/73.	SW	36600	Foxtronics Box 7031 Dallas, TX 76901
NA-265-40, -60; T.C. A2WE	SA1726SW	Foxtronics/TRAMM SRL 66 battery isolation system. Issued 11/7/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
NA-265-40, -60; T.C. A2WE	SA1915SW	Emergency lighting. Issued 9/24/74.	SW	68768	Rockwell International Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
NA-265-40, -60; T.C. A2WE	SA1960SW	Install engine oil pressure low caution light cutoff switches. Issued 3/24/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-40, -60; T.C. A2WE	SA2229SW	Foxtronics/TRAMM RG 100RF guard. Issued 8/8/75.	SW	36600	Foxtronics, Inc. P.O. Box 7031 Dallas, TX 75209
NA-265-40, -60; T.C. A2WE	SA2787SW	Foxtronics external power overvoltage and control system. Issued 6/2/78	SW	36600	Foxtronics, Inc. P.O. Box 7031 Dallas, TX 75209
NA-265-40, -60; T.C. A2WE	SA3095WE	Installation of engine fuel drain sump tank. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
NA-265-40, -60; T.C. A2WE	SA4024SW	BKM anti-skid brake monitor system. Issued 7/27/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-40, -60, -65, -70, -80; T.C. A2WE	SA1545CE	Installation of protective cover No. DLC-2 on main landing gear down lock cylinders. Issued 1/23/80.	CE	44933	J & H Manufacturing Co., Inc. 511 East locus Carter Lake, IA 68110
t+1 NA-265-40, -60, -70; T.C. A2WE	SA756CE	Install Woodward engine synchronizer system. Amended 4/10/74.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
NA-265-40, -60, -70; T.C. A2WE	SA1162CE	Installation of P & D valve fuel reservoir. Issued February 1976.	CE	68765	Rockwell International Corp. Sabreliner Division Missouri Completion Center Route 3 Perryville, MO 63775
NA-265-40, -60, -70; T.C. A2WE	SA1946SW	Engine fuel shut down system. Issued 1/17/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70; T.C. A2WE	SA1972SW	BKM 100-265 nose wheel steering control. Issued 4/9/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA265-40, -60, -70; T.C. A2WE	SA2789SW	Foxboro fuel management system. Issued 6/2/78.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA746EA	Installation of Norton radome kit numbers, P/N 3090X-1, 3090X-10, 3090X-15, 3090X-20 or 3090X-30. Amended 5/18/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
NA265-40, -60, -70, -80; T.C. A2WE	SA1338CE	Installation of Global GNS-500A VLF/Omega navigation system. Issued 6/27/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60, -70, -80; T.C. A2WE	SA1458CE	Installation of microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
NA-265-40, -60, -70, -80; T.C. A2WE	SA1961SW	Entrance door counterbalance system. Issued 4/22/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2382SW	Change nose gear linkage and stop assembly to provide increased steering capability from 35 degrees to 45 degrees. Issued 11/16/76.	SW	16850	The BKM Company P.O. Box 7001 P.O. Box 7001
NA-265-40, -60, -70, -80; T.C. A2WE	SA2388SW	Install diode across coil of hydraulic pump relay. Issued 11/24/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, 0-70, -80; T.C. A2WE	SA2701SW	Relocation of hydraulic pressure. Issued 12/22/77.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA265-40, -60, -70, -80; T.C. A2WE	SA2838SW	Installation of recognition lgihts. Issued 8/21/78.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2933SW	BKM pitot heat monitor system. Issued 3/16/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -80; T.C. A2WE	ST996SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
NA-265-40, -60, -80; T.C. A2WE	SA1957SW	Additional hydraulic pressure switch. Issued 3/3/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-60; T.C. A2WE	SA500CE	Installation of oxygen system. Amended 11/10/75.	CE	68765	Sabreliner Division Rockwell International St. Louis Int'l Airport 6161 Aviation Drive St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA501CE	Installation of portable SunAir H.F. transceiver Model SA-14DA. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-60; T.C. A2WE	SA502CE	Install a nine-place version No. 1 version No. 1-3 interior. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA503CE	Installation of electronic components package version A. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA522CE	Install 12-place interior. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA540CE	Installation of electronics components package version B. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA549CE	Installation of electronics components package version D. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA565CE	Install 8-place version 3 interior. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA596CE	Installation of electronics components package, version E. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA597CE	Installation of dual RCA AVQ-75 DME with hold feature. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA654CE	Installation of electronics components package, version F. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA685CE	Install a ten-place interior, version No. 4. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA705CE	Installation of electronics components package, version G. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA804CE	Installation of electronic components package, version H. Issued May 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA817CE	Install aislewise divan.	CE	33580	EPM Corporation P.O. Box 5978 Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA818NW	Installation of Goodyear brake assembly, P/N 9550338-1. Issued 8/1/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road South Seattle, WA 98108
NA-265-60; T.C. A2WE	SA838CE	Installation of electronics components package, version J. Issued August 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA839CE	Installation of ten-place interior, version No. 5. Issued August 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA896CE	Installation of electronic components package, version K. Amended 12/1/75.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA265-60; T.C. A2WE	SA958CE	Installation of 12-place interior Version No. 7. Amended 11/20/78.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA996CE	Installation of electronic components package, version L. Amended March 1974.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63134

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-60; T.C. A2WE	SA1012CE	Install interior, version No. 8. Issued April 1974.	CE	68765	Aviation Services Division Rockwell International Corp. Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1014CE	Cockpit voice and flight data recorder, altitude alerter system and encoding and weather radar. Amended November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1075CE	Aft lavatory auxiliary seat installation. Issued January 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1078CE	Aft lavatory and auxiliary L.H. installation. Issued February 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1092CE	Installation of electronic components package, version M. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1139CE	Install aft facing forward L.H. seat installation. Issued May 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1146CE	Interior installation, version No. 9. Issued July 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1148CE	Installation of electronic components package, version N. Issued 7/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1149CE	Installation of electronic components package, version P. Issued 7/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1182CE	Auxiliary seat and baggage area installation. Issued 11/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1191CE	Aisle facing seat and baggage area. Issued 1/6/76.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1221CE	Install interior, version No. 10. Issued May 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1242CE	Install Collins ADF-60A automatic direction finding and Intercontinental Dynamics Corp. RAD/BAR with voice terrain advisory system. Amended September 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1247CE	Forward lavatory L.H. installation. Issued July 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1339CE	Aft lavatory installation. Issued 7/6/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1367CE	Interior installation, Version No. 11. Issued 9/15/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1379CE	Install Collins FPC-75 GPWS, IDC SAT/TAS Collins ALT-55B radio altimeter and Wulfsberg Flitefone III provisions. Issued 10/18/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1385CE	Install electronic components package Version "R". Issued 11/15/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-60; T.C. A2WE	SA1386CE	Install electronics components package Version "Q". Issued 11/23/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1392CE	Install Global GNS-500A VLF/OMEGA navigation system. Issued 12/29/77.	CE	59270	Midcoast Aviation Services, Inc. Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1421CE	Install convertible baggage, aisle facing seat. Issued 6/12/78.	CE	59270	Midcoast Aviation Services Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1434CE	Interior installation Version No. 12. Issued 9/19/78.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63775
NA-265-60; T.C. A2WE	SA1476SW	Normalized angle of attack indicating system. Amended 8/27/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
NA-265-60; T.C. A2WE	SA1811WE	Installation of reinforced structure and certain components in partial provision for UCAR configuration. Reissued 7/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60; T.C. A2WE	SA1912WE	Installation of nose boom extension and/or doppler radome and fairing. Amended 5/8/69.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
NA-265-60; T.C. A2WE	SA2878SW	Install two two-place side facing couches. Issued 12/5/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
NA-265-60, Serial No. 306-23 and subsequent; T.C. A2WE	SA3042WE	Installation of engine fuel drain sump tank. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
NA-265-60, -70; T.C. A2WE	SA737CE	Installation of Solar APU Model T-62T-39 and T-62T-39Y. Reissued 6/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60, -80; T.C. A2WE	SA1129CE	Installation of IFR delivery package. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International Corp. 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60, -80; T.C. A2WE	SA1479CE	Installation of forward auxiliary fuel cell (56 gallons). Amended 4/30/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-65; T.C. A2WE	SA1537CE	Installation of Solar Model T-62T-40C auxiliary power unit (APU). Issued 12/29/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA816CE	H.F. antenna installation. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA824CE	Audible hydraulic pressure warning system. Issued February 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA868CE	Installation of Tramm BTI-600 battery temperature indicator system. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA869CE	Installation of RCA AVQ-21 weather radar. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA870CE	Installation of Collins ALT-50 radio altimeter. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA969CE	Installation of 7-passenger interior. Issued November 1973.	CE	68765	North American Rockwell Aviation Services Division Lambert Field St. Louis, MO 63145

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-70; T.C. A2WE	SA1248CE	Installation of Collins AP104/FD109H automatic flight control system. Issued November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA2766WE	Replacement of existing engines with GE CF700-2D-2 fan jet engines. Issued 10/31/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-80; T.C. A2WE	SA995CE	Install electronic components package, version A. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA997CE	Install interior, version No. 2. Issued February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1015CE	Installation of electronic components package Version "C". Amended 12/22/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1026CE	Install interior, version No. 3. Issued May 1974.	CE	68765	Aviation Services Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1028CE	Installation of electronic components package, version B. Issued 1/20/75.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1043CE	Installation of electronic components package, version D. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1065CE	Installation of electronic components package, version E. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1066CE	Installation of Teledyne angle of attack indicating system SL112B1400. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1067CE	Auxiliary seat installation aft lavatory. Issued November 1974.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1074CE	Auxiliary seat installation. Issued January 1975.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1100CE	Interior installation No. 4. Issued March 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1101CE	Installation of cockpit voice recorder and flight data recorder. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1132CE	Install aft lavatory auxiliary seat. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1133CE	Interior installation, FAA Airways Checker. Issued July 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1142CE	Interior installation, version No. 5. Issued June 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1249CE	Interior installation, version No. 6 (wide body). Issued August 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134

ROCKWELL INTERNATIONAL CORP., CA 10

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-80; T.C. A2WE	SA1272CE	Interior installation, version No. 7.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1274CE	Installation of electronic components package, Version "F". Amended 6/21/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C, A2WE	SA1275CE	Interior installation, version No. 8.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1288CE	Interior installation, version No. 9. Issued November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1293CE	Commode installation - aft lavatory. Issued January 1977.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1323CE	Interior installation, No. 10. Issued May 1977.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1329CE	Installation of Collins NCS-31A navigation control system with dual control heads, HI-350 remote compass and Collins 728U-5 HF transceiver system. Issued 5/20/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1337CE	Installation of Intercontinental Dynamics cCorp. vertical navigation system. Issued 5/21/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1342CE	Install electronics components package, Version "G". Issued 8/9/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1374CE	Installation of 800 VA and 2500 VA static inverters. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA265-80; T.C. A2WE	SA1387CE	Passenger compartment wiring provisions installation. Issued 11/30/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA3974WE	Installation of Litton LTN-72R area navigation system. Issued 7/6/79.	WE	11620	Area Equipment Company, Inc. 7707-1/2 Woodley Avenue Building 901 Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ROCKWELL INTERNATIONAL CORPORATION, OKLAHOMA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500 Series; T.C. 6A1	SA1-541	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500 Series; T.C. 6A1	SA1-555	ANC-3A computer and ANC-C2 or ANC-D2 controller.	EA	31050	Dynavia Corporation 3021 West Clay Street Richmond, VA 23219
500 Series; T.C. 6A1	SA1-607	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500 Series; T.C. 6A1	SA3-525	37R-2 antenna.	CE	24250	Collins Radio Company 855 35th Street, NE Cedar Rapids, IA 52406
500 Series; T.C. 6A1	SA4-904	Installation of mufflers and modification of carburetor heat system. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500 Series; T.C. 6A1	SA4-1309	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
500 Series; T.C. 6A1	SA30CE	210405 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
500 Series; T.C. 6A1	SA70CE	Federal F-500 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
500 Series; T.C. 6A1	SA166WE	Removal of main cabin door and hinge pins.	WE	42129	Herpolsheimer Enterprises 12345 VEntura Boulevard Studio City, CA
500 Series; T.C. 6A1	SA168CE	Twin engine synchronizer.	GL	87250	Woodward Governor Company 5001 NOrth Second Street Rockford, IL 61101
500 Series; T.C. 6A1	SA257CE	Turbocharged Lycoming engines, IO-540-A1A5 with Hartzell HC-A3VK-2/V7636D propellers. Reissued 12/5/74.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90801
500 Series; T.C. 6A1	SA340SO	Continental IO-520E engines and Hartzell 3-bladed propellers.	SO	23700	Colemill Enterprises, Inc. P.O. Box 5221 Nashville, IN 37206
500 Series; T.C. 6A1	SA366SO	Gross weight increased to 6530 pounds.	SO	23700	Colemill Enterprises, Inc. Cornelia Fort Air Park Nashville, TN 37202
500 Series; T.C. 6A1	SA459EA	Conversion to Model 500B.	GL	73885	Southern Ohio Aviation Sales Co. Box 97 Montgomery County Airport West Carrollton, OH 44615
500 Series; T.C. 6A1	SA476WE	Nacelle mounted fuel booster pump. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500 Series; T.C. 6A1	SA680SW	AK221 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500 Series; T.C. 6A1	SA683WE	Turbosupercharged Continental IO-470-M engines. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
500 Series; T.C. 6A1	SA1106WE	Mounting provisions for Reconofax XI infrared scanner unit.	EA	03270	U.S. Forest Service Department of Agriculture 1210 Independence Avenue, SW Washington, D.C. 20250
500, 500A, B, 520, 560, 560A, B, E; T.C. 6A1, 2A4	SA90CE	High intensity wing tip lights, tail light and fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500, 500A, B, 560A, E, 680, 680F, FL, F(P), T, 720; T.C. 6A1, 2A4	SA92EA	Install wheels P/N's 3-1112 and/or 311-58 and P/N's 2-878 and/or 2-971 and/or 2-1087. Reissued 9/4/74.	GL	38504	B.F. Goodrich Engineered Systems Company P.O. Box 340 Troy, OH 45373
500, 500-A, B, S, U, 560A, E; T.C. 6A1	SA303GL	Install Cleveland conversion kit No. 199-74 on models which use MIL-H-5606 brake fluid (red oil) or install conversion kit No. 199-74A on models which use Skydrol brake fluid (nonpetroleum base). Issued 4/13/79.	GL	23260	Cleveland Wheels & Brakes VanSickle Division of Parker Hannifin 1160 Center Road Avon, OH 44011
500, 500A, B, 560A, E, F, 680, 680E, F, FL, F(P), FL(P), T, 720; T.C. 6A1, 2A4	SA321EA	Install wheels P/N 301174, P/N's 2-993 and/or 2-1107. Reissued 9/4/74.	GL	38504	B.F. Goodrich Engineered Systems Company P.O. Box 340 Troy, OH 45373
500, 500A, B, U, 560, 560A, E, F, 680, 680F, 680FL, 680FL(P), 680T, 680W, 720; T.C. 6A1, 2A4	SA404CE	Installation of Hoskins supplemental position light system which includes Model A wing tip lights and Model D or K (dual) tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
500, 500A, B, S, U, 560, 560A, E, F, 680, E, F, FL, FL(P), V, W, 720; T.C. 6A1, 2A4	SA527EA	Installation of Collier Model 1AC internally mounted ADF sense antenna. Amended 11/21/68.	GL	24000	Collier Aero Products Company Box 509 Municipal Airport Mansfield, OH 44901
500, 500A, 520, 560; T.C. 6A1	SA589WE	Installation of full-flow lube oil filters on the aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
500, 500-A, -B, -S, -U, 520, 560, 560-A, -E, F, 680, 680-E, -F, FL, FL(P), T, V, W, 681, 685, 690, 720, 111, 112; T.C. 6A1, 2A4, A11SO, A12SO	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14(14V) or -28(28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
500, 500-A, -B, 520, 560; T.C. 6A1	SA630WE	Installation of Coast Winslow Filter Corporation 409 series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
500, 500-A, -B, -S, -U, 520, 560, 560-A, -E, F, 680, 680-E, -F, FL, 680FL(P), T, V, W, 681, 685, 690, 720, 111, 112; T.C. 6A1, 2A4, A11SO, A12SO	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/White), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
500, 500-A, -B, -S, -U, 520, 560, 560-A, -E, -F, 680-E, -F, FL(P); T.C. 6A1, 2A4	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
500, 500A, -B, -S, -U, 520, 560, 560-A, -E, -F, 680, -E, -F, FL, FL(P), T, V, W, 681, 685, 690, 690A, B, 720; T.C. 2A4, 6A1 Includes Pressurized Versions	SA1017EA	Installation of "Tel-Tail" recognition lights. Amended 12/15/76.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
500, 500A, B, S, U, 560A, 680E, F; T.C. 6A1, 2A4	SA1135SW	Modification of fuselage for installation of Bendix ANA-12 doppler antenna. Issued 3/30/70.	SW	47770	Kerr Aviation Services, Inc. P.O. Box 399 Bethany, OK 73008
500, 500-A, B, U, 560, 560A, E, F, 680, E, F, FL; T.C. 6A1, 2A4	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 South Curtis Street Littleton, CO 80120
500, 500A, 500B, 500S, 500U, 520, 560, 560A, 560E; T.C. 6A1	SA3476WE	Replacement installation of tail cone assembly. Issued 9/7/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500, 500A, 500B, 500U, 500S, 520, 560, 560A, 560E; T.C. 6A1	SA3492WE	Replacement installation of vertical tip assembly. Issued 10/26/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
500A, B, U, 560A, E, 680, E, F, F(P), FL, FL(P), T, 720; T.C. 6A1, 2A4	SA1-143	Installation of Chamberlain 2001X series radome kits. Amended 8/17/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
500A - modified -- Colemill STC SA340SO; 500B, 500S, 500U, 700; 500S, 500U - modified -- Mr. RPM STC SA2478SW; 685; T.C. 6A1, 2A4, A12SW	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 11/30/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
500A, B, 560B, 680FL; T.C. 6A1, 2A4	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
500-A, -B, -S, -U; T.C. 6A1	SA447SO	Installation of Bendix Model FCS810 flight control system, including manual electric trim and flight director indicator DH 841( ). Amended 6/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
500A, B, U, 560A, F, 680, 680E, F, FL, FL(P), T, 720; T.C. 6A1, 2A4	SA458EA	Installation of nose cap radome kit No. 3066X-R. Amended 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
500A, B, U; T.C. 6A1	SA802SW	Bendix M4-B/C autopilot flight control system.	SO	15475	Bendix Avionics P.O. Box 9414 Fort Lauderdale, FL 33310
500A, B, U; T.C. 6A1	SA1662SW	Outboard fuel system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
500-A, -B, -S, -U, 560A, 560E; T.C. 6A1	SA1072SW	Universal camera.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
500A, B, S, U, 560A, E, F, 680, E, F; T.C. 6A1, 2A4	SA1122SW	Dual cameras and navigation sights.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
500A, B, S, U, 560A, E, F, 680, E, F; T.C. 6A1, 2A4	SA1332SW	Modify fuselage for camera and navigation sight. Issued 6/24/71.	SW	42825	A.D. Howard, Jr. 6817 NOrthwest 43rd Street Bethany, OK 73008
500A, B, S, U, 560A, E, F, 680, E, F; T.C. 6A1, 2A4	SA1393SW	Mitchell automatic flight system FD/AP282-353 consisting of flight director/autopilot with automatic command trim system. Issued 11/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500A, B, S, U; T.C. 6A1	SA1394SW	Mitchell automatic flight system Model AK353 consisting of Century III autopilot with optional automatic/command trim, radio coupler, glide slope coupler. Issued 11/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500A, B, S, U; T.C. 6A1	SA1445SW	Modification of MItchell automatic flight system AK221 installed per STC SA680SW. Issued 3/13/72.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
500A, B, S, U; T.C. 6A1	SA3142SW-D	Mitchell automatic flight system AK600 consisting of Century IV autopilot or Model AK600FD consisting of Century IV flight director autopilot with remote annunciator. Issued 6/1/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500A, B, S, U; T.C. 6A1	SA3143SW-D	Mitchell automatic flight system AK601 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 6/1/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500A, B, S, U, 520, 560A; T.C. 6A1	SA3516WE	Installation of cockpit overhead windows. Issued 12/1/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500A, 560, 560A, 560E; T.C. 6A1	SA1686WE	Installation of engine mounts P/N VIP 50525-1 and 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
500A, B, S, U, 560A, E, 680, E, F; T.C. 6A1, 2A4	SA1847WE	Installation of Brittain up-command signal adapter kit on certain airplanes equipped with Brittain Models B-4A, B-4AP, B-5 and B-5P flight control system. Amended 12/4/70.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
500B; T.C. 6A1	SA1138SW	Fiberglass tail cone. Issued 4/8/70.	SW	47770	Kerr Aviation Services, Inc. P.O. Box 399 Bethany, OK 73008
500B; T.C. 6A1	SA1971WE	Installation of Model ARB-3 automatic downed aircraft marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue Box 822 Fort Collins, CO 80521
500B; T.C. 6A1	SA3867WE	Installation of SDI model CFS-1000, -2001 or FT-200 fuel indicating system. Issued 2/16/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
500B, 500B (with STC SA529WE); T.C. 6A1	SA111RM	Modify exhaust stacks by installing straight slip joint. Issued 3/27/78.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
500-B, -S, -U; T.C. 6A1	SA529WE	Installation of turbosupercharged Lycoming IO-540 Series engine. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
500-B, -S, -U; T.C. 6A1	SA973SW	Auxiliary outboard wing tanks.	SW	66250	A.D. Howard, Jr. 6817 NOrthwest 43rd Street Bethany, OK 73008
500B, U, S; T.C. 6A1	SA2826SW	Auxiliary fuel tank. Issued 8/2/78.	SW	66250	A.D. Howard, Jr. 1911 Moulton Court Oklahoma City, OK 73127
500B, 500U; T.C. 6A1	SA1-606	Installation of electrothermal propeller deicing system. Amended 3/24/67.	GL	38500	The B.F. Goodrich Company 500 South Main Street Akron, OH 44318
500S; T.C. 6A1	SA66GL	Install Collins AP-106 autopilot consisting of Collins 913K-1 two each 334C-9 (662-0964-001, -002), 334C-6 (622-0965-002), 590A-6, 614E-1, 339T-1, 161H-1, 590B-3, and 390B-18 units. Reissued 2/11/76.	CE	24250	Collins Radio Group 5225 "C" Avenue, NE Cedar Rapids, IA 52406
500S; T.C. 6A1	SA101GL	Installation of Collins AP-107 autopilot. Reissued 2/11/76.	CE	24250	Collins Radio Group 5225 "C" Avenue, NE Cedar Rapids, IA 52406
500S modified - Mr. RPM per STC SA2478SW, 112TC, 112TCA, 114; T.C. 6A1, A12SO	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 3/1/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
500S; T.C. 6A1	SA854EA	Installation of Radome Kit No. 4022KX. Amended 12/16/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
500S; T.C. 6A1	SA2478SW	Installation of Lycoming IO-720-B1B engine and increase take-off and landing weight to 7800 lbs. Issued 7/15/77.	SW	69218	Mr. R.P.M., Inc. P.O. Box 4580 Waco, TX 76705
500, 111 Series; T.C. 6A1, A11SO	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500, 111 Series; T.C. 6A1, A11SO	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
500, 520, 560 Series: T.C. 6A1, 2A4	SA1-64	Federal F-400 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
500, 520, 560 Series; T.C. 6A1, 2A4	SA4-777	Aerofilter 30409A-12 or full flow filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
500, 520, 560 Series; T.C. 6A1, 2A4	SA4-1414	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
500, 520, 560, 680; T.C. 6A1, 2A4	SA1-385	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500, 520, 560, 680; T.C. 6A1, 2A4	SA3-259	Collins glide slope, VOR, navigation and VHF communications antenna; Aircraft Radio Corp. ADF antenna; and Grimes rotating beacons.	GL	59635	Minnesota Airmotive, Inc. Wold-Chamberlain Field Minneapolis, MN 55401
500, 520, 560, 680; T.C. 6A1, 2A4	SA3-721	Cabin temperature control system with Janitrol S-25 heater.	GL	82540	Vapor Heating Corp. 6444 West Howard Street Chicago, IL 60607
500, 520, 560, 680; T.C. 6A1, 2A4	SA102EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500, 520, 560, 680; T.C. 6A1, 2A4	SA133CE	Windshield wiper.	GL	27500	Marquette Division Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
500, 520, 560, 680, 720; T.C. 6A1, 2A4	SA256WE	Control wheel replacement.	WE	34030	Executive Radio and Aircraft Service, Inc. 3011 Airport Avenue Santa Monica, CA 90406
500, 520, 560, 680, 720; T.C. 6A1, 2A4	SA260SW	Protective device in ground side of battery and external power relays.	SW	61623	Commander Service Center Airframe #2082 Aero Commander Division Bethany, OK 73008
500, 520, 560 Series; T.C. 6A1, 2A4	SA559SW	Aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
500, 520, 560, 680, 681, 720; T.C. 6A1, 2A4	SA798EA	Installation of Monitair exhaust gas combination monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
500, 560, 680; T.C. 6A1, 2A4	SA1-93	RCA AVQ-50 radar equipment and AVQ-50 antenna mounting bracket.	EA	67000	Reading Aviation Services, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
500, 560, 680; T.C. 6A1, 2A4	SA1-142	Modified ARC A13-B antenna.	GL	73884	Southern Ohio Aviation Company P.O. Box 367 Vandalia, OH 45377
500, 560, 680; T.C. 6A1, 2A4	SA1-445	ARC Type A13-B VHF navigational antenna on vertical fin.	GL	73884	Southern Ohio Aviation Company 10600 Springboro Pike Miamisburg, OH 45342
500, 560, 680; T.C. 6A1, 2A4	SA1-525	ARC A13-B antenna on vertical fin with rotating beacon.	EA	02273	Aero Industries P.O. Box T Byrd Airport Sandston, VA 23150
500, 560, 680; T.C. 6A1, 2A4	SA1-624	Oxygen system.	EA	35600	The Firewel Company, Inc. 3695 Broadway Buffalo, NY 14240
500, 560, 680; T.C. 6A1, 2A4	SA13WE	M-4 autopilot. Amended 2/24/67.	SO	15475	The Bendix Corporation P.O. Box 9414 Fort Lauderdale, FL 33310

ROCKWELL INTERNATIONAL CORP., OK 6

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500, 560, 680; T.C. 6A1, 2A4	SA84SW	Automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500, 560, 680; T.C. 6A1, 2A4	SA114CE	Windshield anti-ice system.	GL	25390	Commander Aviation, Inc. Municipal Airport Pontiac, MI 48053
500, 560, 680; T.C. 6A1, 2A4	SA115EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500, 560, 680; T.C. 6A1, 2A4	SA120CE	Windshield anti-ice system.	GL	38500	Commander Aviation, Inc. Municipal Airport Pontiac, MI 48053
500, 560, 680 Series; T.C. 6A1, 2A4	SA137CE	Lower window line in cabin area.	CE	47650	Kansas City Flying Service Municipal Airport Kansas City, MO 64108
500, 560, 680 Series; T.C. 6A1, 2A4	SA258SW	Camera and camera view finder opening in main cabin floor of 30" x 39" maximum dimension.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
500, 560, 680 Series; T.C. 6A1, 2A4	SA396SW	Automatic pilot AK118, lateral guidance radio coupler AK123, and pitch trim AD135.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500, 560, 680 Series; T.C. 6A1, 2A4	SA491EA	Incorporation of B.F. Goodrich ice protection systems.	GL	38500	B.F. Goodrich Aerospace and Defense Products Div. of B.F. Goodrich Company 500 South Main Street Akron, OH 44318
500, 560, 680 Series; T.C. 6A1, 2A4	SA666SW	Forward cabin door.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, OK 73109
500, 560, 680 Series; T.C. 6A1, 2A4	SA1064SW	Wild RC-8 aerial survey camera. Issued 8/8/69.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
500, 560, 680 Series; T.C. 6A1, 2A4	SA1125SW	Aerial survey camera and navigation. Issued 3/2/70.	SW	47770	Kerr Aviation Services, Inc. P.O. Box 399 Bethany, OK 73008
500, 560, 560A, 560E, 680, 680E; T.C. 6A1, 2A4	SA4-454	Installation of fiberglass vertical stabilizer cap in lieu of metal; repositioning of rotating beacon mounting to leading edge; reduction of length of the two spar extensions to facilitate VHF antenna installation inside stabilizer cap area. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500, 560, 680, 720; T.C. 6A1, 2A4	SA4-443	Fiberglas wing tips. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500, 560, 680, 720; T.C. 6A1, 2A4	SA4-1234	Installation of electrical low fuel warning device to indicate last 25 gallons of useable fuel in main (center) tank. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500, 600 Series; T.C. 6A1, 2A4	SA1454WE	Installation of Brittain Model B-4A flight control system.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
500, 600 Series; T.C. 6A1, 2A4	SA1580WE	Installation of Brittain Model B-5 flight control system.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
500, 680 Series; T.C. 6A1, 2A4	SA798SW	Radome nose extension. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
500, 680 Series; T.C. 6A1, 2A4	SA863SW	Modified instrument panel. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
500, 600 Series; T.C. 6A1, 2A4	SA1182SW	Dual camera and navigation sight. Issued 8/19/70.	SW	47770	Kerr Aviation Services, Inc. P.O. Box 399 Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500, 680, 720 Series; T.C. 6A1, 2A4	SA265EA	Installation of Chamberlain radome kit #2001K-B for use with Bendix radar RDR-100 or RDR-110. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1[illegible]87 Akron, OH 44309
520; T.C. 6A1	SA315SO	Nose weather radar and radome.	SO	34010	Executive Aviation Peachtree-DeKalb Airport Chamblee, GA 3000[illegible]
520; T.C. 6A1	SA2279WE	Removal of main cabin door. Issued 11/23/70.	RM	74760	Sportsman International, Ltd. 3559 Brighton Boulevard Denver, CO 80216
520, 560 Series; T.C. 6A1	SA50CE	C210310 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
520, 560 Series; T.C. 6A1	SA51CE	C210403 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
520, 560, 680 Series; T.C. 6A1, 2A4	SA3-118	ARC Type A-13B VHF navigational antenna.	GL	72252	Skymotive, Inc. FAA Repair Station 3712 P.O. Box 448 Park Ridge, IL 60068
520, 560, 680 Series; T.C. 6A1, 2A4	SA4-447	Fiberglass wing tips. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
560 Series; T.C. 6A1	SA1-46	Bendix A1313 Omni antenna on top of fuselage.	SO	78390	Tempo Design Company P.O. Box 456 Miami, FL 33148
560 Series; T.C. 6A1	SA1-92	Fuselage to accommodate aerial photographic equipment.	EA	67000	Reading Aviation Service. Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
560 Series; T.C. 6A1	SA1-342	Oil-free vacuum pump.	GL	11880	Associate Aircraft Tool & Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
560 Series; T.C. 6A1	SA1-455	ANC-3A computer and ANC-C2 or ANC-D2 controller in conjunction with Lear L2C autopilot.	EA	30150	Dynavia Corporation 3021 West Clay Street Richmond, VA 23219
560 Series; T.C. 6A1	SA1-652	Dry vacuum pump and instrument vacuum system.	GL	03760	Airborne Mechanisms Division Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
560 Series; T.C. 6A1	SA118CE	Hydraulic unfeathering accumulators 210320 and new propeller governors.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
560 Series; T.C. 6A1	SA193SO	Turbocharged Lycoming GO-480C1B6 or GO-480-C1B6 engines, per STC SE124SO. Reissued 1/14/69.	WE	66250	Rajay Industries 2602 East Wardlow Road Long Beach, CA 90807
560 Series; T.C. 6A1	SA367EA	Opening in lower surface fuselage to accommodate cameras.	EA	52060	Long Island Airways, Inc. P.O. Box 248 Ronkonkoma, NY 11779
560 Series; T.C. 6A1	SA585SW	Nose cone. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
560, 560A; T.C. 6A1	SA136SO	Turbocharged Lycoming GO-480-D1A engine. Reissued 1/14/69.	WE	66250	Rajay Industries 2602 East Wardlow Road Long Beach, CA 90807
560, 680; T.C. 6A1, 2A4	SA1-653	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
560, 680; T.C. 6A1, 2A4	SA3-406	RCA AVQ-50 weather avoidance radar.	GL	72252	Skymotive, Inc. FAA Repair Station 3712 P.O. Box 448 Park Ridge, IL 60068
560, 680; T.C. 6A1, 2A4	SA4-1382	L2-C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
560, 680; T.C. 6A1, 2A4	SA4-1442	AP-102 autopilot.	CE	24250	Collins Radio Company 855 34th Street, NE Cedar Rapids, IA 52401
560, 680; T.C. 6A1, 2A4	SA4-1579	Aerofilter 30690B full flow lube oil filter with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
560, 680 Series; T.C. 6A1, 2A4	SA29SW	Auxiliary outboard fuel tank.	SW	08235	Air-Mod Engineering Company P.O. Box 201-W Oklahoma City, OK 73125
560, 680 Series; T.C. 6A1, 2A4	SA38CE	B21043 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
560, 680 Series; T.C. 6A1, 2A4	SA199SW	Four auxiliary fuel cells in each outer wing panel between wing stations 127 and 163.	SW	08235	Air-Mod Engineering Company Hangar #2, Wiley Post Airport Bethany, OK 73008
560, 680 Series; T.C. 6A1, 2A4	SA231CE	Twin engine synchronizer.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
560, 680 Series; T.C. 6A1, 2A4	SA1512WE	Installation of exhaust gas temperature monitoring system, Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Vally, CA 94546
560, 680 Series; T.C. 6A1, 2A4	SA1675WE	Installation of KS Avionics EGT-2 monitorng system. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
560, 680 Series; T.C. 6A1, 2A4	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
560 Series, 680FL, FL(P); T.C. 6A1, 2A4	SA179EA	Installation of electrothermal propeller deicing system. Amended 3/24/67.	GL	38500	The B.F. Goodrich Company 500 South Main Street Akron, OH 44318
560, 680, 720; T.C. 6A1, 2A4	SA1-520	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
560, 680, 720; T.C. 6A1, 2A4	SA4-455	Hamilton Standard governors IM12-G5.	WE	34030	Executive Radio and Aircraft Service, Inc. 3011 Airport Avenue Santa Monica, CA 90406
560, 680, 720; T.C. 6A1, 2A4	SA4-969	Aerofiter 30690B full flow lube oil filter with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
560, 680, 720; T.C. 6A1, 2A4	SA4-1655	Outer wing non-icing fuel tank vent fairings.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
560, 680, 720; T.C. 6A1, 2A4	SA91CE	Hoskins high intensity wing tip lights, tail light and high intensity fuselage lights.	GL	41626	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
560, 680, 720; T.C. 6A1, 2A4	SA132EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
560, 680, 720; T.C. 6A1, 2A4	SA600WE	Brittain flight control system B-4, including pitch assist PC-1, altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
560A, E, F, 680, E, F; T.C. 2A4, 6A1	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
560E; T.C. 6A1	SA1966WE	Removal of main cabin door.	RM	16780	Steve Biljanic Box 133 Midvale, UT 84047
560F; T.C. 2A4	SA1080CE	Installation of Collins Radio Group AP-107 autopilot system. Issued March 1975.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
560F; T.C. 2A4	SA1130CE	Installation of Collins Radio Group electric trim system. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
560-F, 680, 680-E, 680F, 720; T.C. 2A4	SA290GL	Install Cleveland conversion kit No. 199-74 on listed models which use MIL-H-5606 brake fluid (red oil) or kit No. 199-74A on listed models which use Skydrol brake fluid (nonpetroleum base). Issued 12/26/78.	GL	23260	Cleveland Wheels & Brakes Parker Hannifin Corp. 1160 Center Road Avon, OH 44011
560F, 680, 680F; T.C. 2A4	SA3405WE	Installation of fuselage fuel tank. Issued 5/24/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
560F, 680E, 680F, 680FL, 680FLP, 680W; T.C. 2A4	SA3477WE	Replacement installation of tail cone assembly. Issued 9/7/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
560F, 680, 680E, 680F, 680FL, 680FLP, 680W; T.C. 2A4	SA3493WE	Replacement installation of vertical tip assembly. Issued 10/3/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
560F, 680F; T.C. 2A4	SA3517WE	Installation of cockpit overhead windows. Issued 12/23/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhusrt Avenue Van Nuys, CA 91406
600 Series; T.C. 2A4	SA1-83	Camera in fuselage tail section.	GL	73884	Southern Ohio Aviation Company P.O. Box 367 Vandalia, OH 45371
600, S2D; T.C. A3SW, A4SW	SA113NW	Installation of EAC 3D40-401 AG-100-2 propeller with 4M121-1 propeller governor. Issued 5/24/74.	NW	33000	Efficiency Aircraft P.O. Box 37 Kent, WA 98031
680 Series; T.C. 2A4	SA1-68	Dual Wilcox ADF radio loop antenna.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
680 Series; T.C. 2A4	SA1-231	Bendix fuel flow indicating system.	GL	37830	General Tire & Rubber Company 1708 Englewood Avenue Akron, OH 44309
680 Series;	SA1-249	Fuel flow indicating system.	NE	61240	National Lead Company P.O. Box 365 Stratford, CT 06497
680 Series; T.C. 2A4	SA1-300	Bendix fuel flow indicating system.	EA	12700	Lycoming Division Avco Manufacturing Company Service Hangar Montoursville, PA 17754
680 Series; T.C. 2A4	SA1-442	ANC-3A computer and ANO-C2 or ANC-D2 controller with Lear L2C autopilot.	EA	31050	Dynavia Corporation 3021 West Clay Street Richmond, VA 23219
680 Series; T.C. 2A4	SA1-476	SP-3 autopilot EB2597034.	EA	74574	Sperry Gyroscope Company Division of Sperry Rand Corp. MacArthur Field Ronkonkoma, NY 11779
680 Series; T.C. 2A4	SA1-552	Pesco 2 P-R400-BRD fuel pumps.	SW	28590	Island Service Division Dallas Airmotive, Inc. Galveston, TX 77550
680 Series; T.C. 2A4	SA3-32	AP-101 automatic pilot.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA3-112	Oil separators in vacuum pump outlet lines.	GL	16886	Bohling Aircraft Corporation 5324 West 63rd Street Chicago, IL 60607
680 Series; T.C. 2A4	SA3-120	Relocation of aircraft battery to home station 8. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
680 Series; T.C. 2A4	SA3-145	AP-101 automatic pilot.	GL	59635	Minnesota Airmotive, Inc. Wold-Chamberlain Field Minneapolis, MN 55450
680 Series; T.C. 2A4	SA3-301	Hand-operated hydraulic pump deactivated or removed and replaced with electric-driven equivalent.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
680 Series; T.C. 2A4	SA3-349	Bendix fuel flow indicator system.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
680 Series; T.C. 2A4	SA3-350	AP-11 automatic pilot.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
680 Series; T.C. 2A4	SA4-240	Electric hydraulic pump.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
680 Series; T.C. 2A4	SA4-530	Radio rack aft of baggage compartment.	RM	05940	Aircraft Radio and Accessory Company, Inc. Stapleton Airfield Denver, CO 80202
680 Series; T.C. 2A4	SA4-551	L-102B automatic pilot.	WE	49858	Lear, Inc. 3171 South Bundy Drive Santa Monica, CA 90406
680 Series; T.C. 2A4	SA65SW	Support and opening in bottom of fuselage for Aeropath camera.	EA	02700	Aero Service Corporation 210 East Courtland Street Philadelphia, PA 19104
680 Series; T.C. 2A4	SA155CE	H-14 adaptive autopilot.	GL	42245	Honeywell Flight Operations Wold-Chamberlain Field Minneapolis, MN 55450
680 Series; T.C. 2A4	SA164EA	Airborne profile recorder probe on nose of fuselage.	EA	02700	Aero Service Corporation 210 East Courtland Street Philadelphia, PA 19104
680 Series; T.C. 2A4	SA240CE	Unfeathering accumulator.	GL	67250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
680 Series; T.C. 2A4	SA290SW	RC-9 aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA391EA	Turbine bleed type pneumatic deicer system.	GL	18500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
680 Series; T.C. 2A4	SA403SW	RC-8 aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA418SW	Seat-passenger lavatory combination.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA439SW	TC-8 aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA439WE	Lycoming IGSO-480-A1D6 engines in lieu of original GSO-480-B1A6. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monca, CA 90405
680 Series; T.C. 2A4	SA455EA	Propeller deicing system.	NE	80385	United Aircraft Corporation Hamilton Standard Division Windsor Locks, CT 06096
680 Series; T.C. 2A4	SA473SW	AP-103E/FD108 automatic flight control system.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA478SW	RC-7, -9 aerial survey cameras.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA520SW	Autopilot M-4C.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
680 Series; T.C. 2A4	SA523WE	Motorola L-2C autopilot with M-4 autopilot servo clutches and without approach coupler.	WE	70098	Santa Monica Aviation, Inc. 3011 Airport Avenue Santa Monica, CA 90405
680 Series; T.C. 2A4	SA577SW	Conversion of RC-8 camera to RMK-A-15/23.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA606SO	Installation of extended window L.H. and R.H. side of cabin. Amended 10/22/68.	SO	05580	Aircraft Modification Engineering Company P.O. Box 945 Vero Beach, FL 32960

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
680 Series; T.C. 2A4	SA633WE	Reroute powerplant and aileron control cables.	WE	70098	Santa Monica Aviation, Inc. 3011 Airport Avenue Santa Monica, CA 90405
680 Series; T.C. 2A4	SA662WE	Hi-Io sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock.	EA	17500	Brittain Industries, Inc. Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
680 Series; T.C. 2A4	SA665SW	deHavilland airborne profile recorder in aft fuselage.	EA	04515	Air Carrier Service Corp. 2233 Wisconsin Avenue, NW Washington, D.C. 20007
680 Series; T.C. 2A4	SA684SW	AP103F/FD-108 automatic flight control system.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA710SW	PT6A-20 engine.	SW	77110	Swearingen Aircraft P.O. Box 6904 San Antonio, TX 78209
680 Series; T.C. 2A4	SA1155WE	Camera.	NW	85123	Western Aerial Contractors, Inc. Route 1, Box 740 Eugene, OR 97401
680, 680E, 720; T.C. 2A4	SA660WE	Installation of HRD type fire extinguishing system. Amended 7/11/77.	WE	43190	HTL Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
680, 680-E, -F, -FL, -FL(P), T, V, W, 681, 685, 690, 720; T.C. 2A4	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Ic. 18145 Judy Street Castro Valley, CA 94546
680E; T.C. 2A4	SA450EA	Modification to lower surface of fuselage to accommodate Wild Camera Model RC5 or RC8. Amended 2/9/68.	EA	52060	Long Island Airways P.O. Box 828 Ronkonkoma, NY 11779
680E; T.C. 2A4	SA1782WE	Installation of drooped ailerons drooped wing leading edge, stall fence and rudder seal. Reissued 1/5/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
680F; T.C. 2A4	SA2691WE	Installation of Lycoming IO-720-BIB turbocharged engine. Reissued 7/22/74.	WE	69220	Mr. R P M Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680F; T.C. 2A4	SA3299SW-D	Mitchell automatic flight system AK772, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/21/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F; T.C. 2A4	SA3300SW-D	Mitchell automatic flight system AK773, consisting of Century IV autopilot, consisting of Century IV flight director autopilot with optional remote annunciator. Issued 8/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F, 680FL; T.C. 2A4	SA155CE	Intallation of Honeywell H-14 adaptive autopilot.	CE	48250	King Radio Corpratin 400 North Rogers Road Olathe, KS 66061
680FL; T.C. 2A4	SA2EU	Cargo door modification	EU	08440	ALAR-Empresa Iberica de Material Aeronautico Ld Lisbon, Portugal
680FL; T.C. 2A4	SA102GL	Installation of baggage compartment. Issued 12/29/75.	GL	31362	Eagle Aviation, Inc. Bishop Airport Flint, MI 48507
680FL; T.C. 2A4	SA929SW	Automatic flight system AK270 consisting of Century III autopilot with optional automatic pitch trim. radio and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
680FL; T.C. 2A4	SA1089SW	59-gallon wing auxiliary fuel tank.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680FL; T.C. 2A4	SA1094SW	RD-8, RC-9, and RMK-A-15/23 camera.	SW	47770	Kerr Aviation Service, Inc. Box 399 Bethany, OK 73008
680FL; T.C. 2A4	SA1095SW	Installation of Bendix ANA-12A.	SW	47770	Kerr Aviation Service,Inc. Box 399 Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
680FL; T.C. 2A4	SA1358SW	Dual or single camera installation and navigation sights. Issued 8/25/71.	SW	42825	A.D. Howard, Jr. 6817 Northwest 23rd Street Bethany, OK 73008
680FL; T.C. 2A4	SA2448SW	Extension of baggage area to F.S. 308, encompassing re-routing of powerplant and aileron control cables in baggage compartment area. Issued 4/7/77.	SW	25260	Harry B. Combs, Jr. P.O. Box 4580 Waco, TX 76101
680FL, FL(P); T.C. 2A4	SA806SW	Flap close-out strips.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
680FL, 680FL(P), 680(F); T.C. 2A4	SA2891WE	Installation of Lycoming IO-720-B1B turbocharged engine. Reissued 8/2/74.	WE	69220	Mr. RPM, Inc. Suite 321 7120 Hayvenhurst venue Van Nuys, CA 91406
680FL, 680FL(P): T.C. 2A4	SA2903SW	Installation of wing flap gap seals. Issued 1/25/79.	SW	69218	Mr. R.P.M., Inc. P.O. Box 40414 Everman Branch Fort Worth, TX 76140
680FL(P): T.C. 2A4	SA3322WE	Installation of cockpit overhead windows. Issued 1/18/77.	WE	69220	Mr. RPM, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680FL(P), T, V, W, 681; T.C. 2A4	SA1261SW	Camera installation. Issued 3/11/71.	SW	30530	Downtown Airpark, Inc. Box 94846 Bethany, OK 73109
680FL(P), 680T, V, W, 681, 690; T.C. 2A4	SA1584SW	Aerial survey camera. Issued 1/3/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 6#))*
680FL, 685; T.C. 2A4	SA1649SW	Camera installation. Issued 5/1/73.	SW	42825	A.D. Howard, Jr. 817 Northwest 43rd Street Bethany, OK 73008
680FL, 680FL(P), 680T, V, W, 681, 685A, 690, 690A; T.C. 2A4	SA1977SW	Modification of fuselage for installation of doppler antenna. Issued 5/6/75.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Oklahoma City, OK 73008
680T, V, W; T.C. 2A4	SA887SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
680T, 680V, 680W, 681; T.C. 2A4	SA895EA	Installation of Grimes three light strobe kit. Issued 1/20/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
680T, V, W, 681; T.C. 2A4	SA1926SW	Fuel purge system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681; T.C. 2A4	SA1962SW	Generator over-voltage/over-current protection. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681, 690; T.C. 2A4	SA1705SW	Freon air conditioning system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680V, W; T.C. 2A4	SA1529SW	Modification of hydraulic system and air conditioning pressurization system. Issued 7/25/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680V, W; T.C. 2A4	SA1530SW	Modify existing 3000 psi hydraulic system to 1000 psi hydraulic system. Issued 12/23/72.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680W; T.C. 2A4	SA3469WE	Installation of AiResearch TPE 331-6-252M engines. Amended 2/27/78.	WE	07502	AiResearch Manufacturing Co. of Arizona 402 South 36th Street P.O. Box 5217 Phoenix, AZ 85010
680, 720 Series; T.C. 2A4	SA37CE	C210403 governor.	SW	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
680, 720 Series; T.C. 2A4	SA39CE	C210310 governor.	SW	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
681; T.C. 2A4	SA1005CE	Installation of IAD battery temperature monitor and over-temperature warning system. Issued March 1974.	CE	05250	Aircraft Instrument & Development, Inc. 317 East Lewis Wichita, KS 67202
685 Series; T.C. 2A4	SA17GL	Installation of Bendix FCS-810 autopilot. Issued 4/12/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
685 Series; T.C. 2A4	SA56GL	Install wheel assembly P/N 3-1174 and brake assembly P/N 2-993-1. Issued 7/23/74.	GL	38504	B.F. Goodrich Engineered Systems Company Division of B.F. Goodrich Co. P.O. Box 340 Troy, OH 45373
685; T.C. 2A4	SA155RM	Installation of Singer SKK-1000 doppler navigation system, SKQ-601 dead reckoning computer, and Sperry C-12 compass system. Issued 10/4/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
685 Series; T.C. 2A4	SA878SO	Installation of Silver Instruments Fueltron III, fuel flow gages. Issued 1/21/76.	SO	12493	Atlantic Aero, Inc. P.O. Box 8946 Grensboro, NC 27410
685; T.C. 2A4	SA3849WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 1/30/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
690 Series; T.C. 2A4	SA26GL	Installation of Bendix M-4C autopilot. Issued 7/2/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O.Box 1060 Rockford, IL 61109
690 Series; T.C. 2A4	SA530SO	Installaton of manual electric trim system. Issued 2/28/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
690 Series; T.C. 2A4	SA2606WE	Installation of Lear AFC-70 autopilot. Amended 7/20/73.	WE	49850	LearAvia Corporation Avioncs Division 14505 Mt. Anderson Avenue Reno, NV 89510
690 Series; T.C. 2A6	SA2727WE	Installation of LearAvia electric pitch trim system. Issued 7/20/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510
690, 690A; T.C. 2A4	SA74GL	Install wing tip recognition lights. Issued 3/21/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
690, 690A; T.C. 2A4	SA85SW	Installation of auxiliary bleed air shut-off and fuselage temperature monitoring system. Reissued 1/30/78.	GL	68768	Rockwell Aviation Service Division 3300 Love Field Drive Dallas, TX 75235
690, 690A; T.C. 2A4	SA1059SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid batteries. Issued 3/29/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
690, 690A, 690B; T.C. 2A4	SA2577WE	Installation of flight FCS-105 flight control system. Amended 8/14/78.	CE	24250	Collins Radio Group Rockwell International 400 Collins Raod, N.E. Cedar Rapids, IA 52406
690A; T.C. 2A4	SA79GL	Instal Bendix M4D autopilot system. Issued 4/18/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61101
690A; T.C. 2A4	SA1009CE	Install Model KFC-300 automatic flight control system (autopilot and flight director). Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
690A; T.C. 2A4	SA1011CE	Install Model KVN-395 vertical navigation computer for operation with Model KFC-300 automatic flight control system. Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
690A; T.C. 2A4	SA1873SW	Sperry SPZ-200/STARS IVC. Issued 5/1/74.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, OK 73109

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
690A; T.C. 2A4	SA1876SW	AP-106 autopilot and manual electric trim. Issued 4/29/74.	SW	24752	Collins Radio Company Addison Airport Addison, TX 75001
690A, 690B; T.C. 2A4	SA1024SO	Installation of AiResearch TPE331-5-252K engines in Model 690A replacing AiResearch TPE331-5-251K engines; installation of TPE331-5-252K engines in Model 690B. Amended 1/9/79.	SO	37087	The Garrett Corporation Route 1, Box 60 Bush Field Agusta, GA 30906
720; T.C. 2A4	SA1-553	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace ad Defense Products 500 South Main Street Akron, OH 45373
720; T.C. 2A4	SA395SW	Four-place seating capacity.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
111, 112; T.C. A11SO, A12SO	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
111, 112; T.C. A11SO, A12SO	SA1502SW	Mitchell automatic flight system AK364 consisting of Century I autopilot with optional omni tracker. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1503SW	Mitchell automatic flight system AK 363 consisting of Century IIB autopilot with optional radio coupler. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1504SW	Mitchell automatic flight system AK362 consisting of Century III with optional command/electric pitch trim, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1505SW	Mitchell command/electric pitch trim. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1728SW	Cabin air scoop. Issued 9/13/73.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
112; T.C. A12SO	SA243NW	Installation of Lycoming IO-540 engine with 3-bladed Hoffman, 3-bladed Hartzell, or 2-bladed Hartzell propeller. Amended 5/26/78.	NW	52625	Machen, Inc. S. 3408 Davison Boulevard Spokane, WA 99204
112; T.C. A11SO, A12SO	SA2900WE	Installation of Pathfinder autopilots. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Asler Street Torrance, CA 90505
112; T.C. A12SO	SA3155WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 4/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torranc, CA 90505
112, 112B, 112TC, 112TCA, 114; T.C. A12SO	SA237GL	Install leading edge landing lights. Issued 4/20/78.	GL	37182	General Aviation, Inc. Lost Nation Airport Willoughby, OH 44094
112, 112B, 112TC, 112TCA, 114; T.C. A12SO	SA1229CE	Install King Model KFC-200 2-axis (3 optional) flight control system with KCS 55/55A compass and a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller; or stand alone electric trim. Amended 1/18/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
112, 114; T.C. A12SO	SA3120SW-D	Automatic flight system AK572 consisting of Century I autopilot with optional omni tracker. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A12SO	SA3121SW-D	Automatic flight system AK573 consisting of Century IIB autopilot with optional radio coupler. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
112, 114; T.C. A12SO	SA3122SW-D	Automatic flight system AK574 consisting of Century III autopilot with optional radio and glide slope Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A1SO	SA3123SW-D	Mitchel command electric trim AK582. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112B, 112TC, 112TCA, 114; T.C. A12SO	SA3778WE	Installation of retractable landing lights. Issued 11/8/78.	WE	47070	Fred W. Jones 2901 East Spring Street Long Beach, CA 90806
112TC, 112TCA; T.C. A12SO	SA3787WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
112TC, 112TCA; T.C. A12SO	SA3920WE	Installation of fueltron IG or IP digital fuel flow and totalizer system. Amended 1/9/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
114; T.C. A12SO	SA3727WE	Installation of SDI Model CFS-1000, -1001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
114; T.C. A12SO	SA3308WE	Modification of aileron control system by addition of aileron centering spring and installation of Pathfinder autopilot system and/or pitch trim systems. Issued 1/7/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
114; T.C. A12SO	SA3727WE	Installation of SDI Model CFS-1000 fuel flow indicator. Issued 9/6/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
VICTOR H. ROOS AIRCRAFT COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
American Eagle A-1, 101; T.C. 17	SA275WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
American Eagle A-1, 101; T.C. 17	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(American Eagle) A-1, 101; ATC 17	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ROBERT E. RUST

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
(DeHavilland) DH.C1, Chipmunk 21, 22, 22A; T.C. A44EU	SA1010SO	Installation of Scott Model 2600 tailwheel assembly, replacing original equipment Dunlop tailwheel assembly. Issued 7/13/78.	SO	69239	Rust Airstrip, Inc. RFD 3 (Highway 92 S.) Fayetteville, GA 30214
DeHavilland DH.C1, Chipmunk 21, 22, 22A; T.C. A44EU	SA1011SO	Installation of Cleveland wheels, P/N 40-97(c) and brakes P/N 30-63(P), replacing original equipment Dunlop wheel and brake assemblies. TSC tube type tires to be used are size 6.00-6 or as an alternate 7.00-6, both 4 or 6 ply rating. Issued 7/13/78.	SO	69239	Rust Airstrip, Inc. RFD 3 (Highway 92 S.) Fayetteville, GA 30214

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

RYAN AERONAUTICAL COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SCW-145; T.C. 658	SA4-339	Curtiss metal propeller 55518 and replacement of .080 windshield with bubble .125 (grade I) plexiglass.	WE	70262	Walter B. Saunders Gillespie Field Santee,CA 92071
SCW-145; T.C. 658	SA988WE	Ceconite 101 covering of ailerons, fin rudder, stabilizer and elevators.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SCW-145; ST-3KR; T.C. 658, 749	SA1351WE	Replace existing fabric on wings, fuselage, empennage,and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
SCW-145, ST-3KR; T.C. 658, 749	SA2666WE	Ceconite 102 material covering of: SCW-145 - complete aircraft; SCW-145 - ailerons, fin, rudder, stabilizer and elevators; ST-3KR - wings, flaps, horizontal stabilizer, elevator. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
ST-3KR; T.C. 749	SA4-822	Ceconite 101 covering of wings, flaps, ailerons, horizontal stabilizer and elevators.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
ST-3KR; T.C. 749	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
ST-3KR; T.C. 749	SA4-1210	Installation of Bonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Bonair, Inc. 417 Watts Drive Bakersfield, CA 93307
ST-3KR; T.C. 749	SA1008WE	Installatin of Poly-Fiber covering material (complete aircraft). Amended 8/7/69.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
ST-3KR (Army PT-22, -22A); T.C. 749	SA1350WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
ST-3KR; T.C. A-749	SA2921WE	Reduce size of cockpit openings, install rounded windshields, flush rivet and increase fuselage skin gages, install internal top longerons, remove external top longerons and install internal aileron balance weight. Issued 8/14/74.	WE	25760	Component Air, Inc. P.O. Bx 946 Santa Paula, CA 93060

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
SCHEIBE-FLUGZEUGBAU G.M.B.H.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Bergfalke 2-55; T.C. 7G9	SA1008WE	Poly-Fiber covering of both wings. Amended 9/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
SCHEMPP-HIRTH K.G.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
(Standard Austria) S; T.C. G1IN	SA2666WE	Ceconite 102 material covering of wings and ailerons. 4/19/78	WE	26250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
SCHLEICHER, ALEXANDER, SEGELFLUGZEUGBAU

Aircraft Make, Model & T.C. No.	STC No.	Description	PG	STC Code	STC Holder
Ka 6 CR; T.C. 7G1	SG5WE	Ceconite 103 covering of complete wing assembly.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
Ka 6 CR; T.C. 7G1	SG10WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 103 material. Amended 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
K7, K8B; T.C. 7G3, 7G4	SA2666WE	Ceconite 102 material covering of: K7 - complete aircraft; K8B - fuselage only. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
K8, K-8B; T.C. 7G4	SA1008WE	Installation of poly-fiber covering material of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
SCHWEIZER AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SGS 1-26 Series; T.C. 1G10	SG4WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SGS-1-26C; SGU-2-22E, SGU-1-19, -19A; T.C. 1G10, GTC G-18, G-17	SA1008WE	Installation of Poly-Fiber dovering material (fuselage and control surfaces SGS-1-26C, SGU-2-22E) (complete aircraft SGU-1-19, -19A). Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
SGS 1-26, SGU 2-22 Series; T: T.C. 1G10, G-18	SG4-1240	Eonnex cover on complete glider.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
SGS 2-8A; T.C. 5	SG4-1156	Ceconite 101 covering of complete glider.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SGS 2-8A, SGU 2-22CK; T.C. 5, 18	SG4-1411	Ceconite 103 covering of glider.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SGS 2-8A; SGS-126, -A, -C; SGU 2-22CK, 22E; SGU 1-19; GTC 5, 18, 17, 1G10	SG10WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 103 material. Amended 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
SGS 2-8A; TG-3A, SGU-1-19; SGS-126, -26A, -26B, -26C; SGU 2-22, -22A, -22B, -22C, -22CK, -22E, -22EK; GTC 5, 17, T.C. 1G10, GTC 18	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or ontrol surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
SGS 2-8A, TG-3A, SGU-1-19, SGS 1-26, -26A, -26B, -26C, SGU 2-22, -22A, -22B, -22C, -22CK, -22E, -22EK; GTC 5, 17, 18, T.C. 1G10, 2-11	SA2666WE	Ceconite 102 material covering of: SGU-1-19, 1-26, -26A, -26B SGU 2-22 series - complete glider; SGS 2-8A, TG-3A complete glider; SGS 1-26C - control surfaces. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
SGU 1-19; T.C. G-17	SG7WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SGS1-26, -26A, B, C, SGS2-8, -8A, SGU-1-19, -1-19A, SGU-2-22, -22A, -22B, -22C, -22CK, -22E, -22KK; T.C. GTC 1G10, GTC 5, GTC G-17, GTC G-18	SG4-1240	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
2-33, 2-33A, 2-33AK; T.C. G2EA	SG305GL	Install full swivel tail wheel, Cronig P/N SK-1, utilizing existing mounting points, bolts and hardware. Issued 6/5/79.	GL	27237	Alvin Cronig 18708 Lomond Boulevard Shaker Heights, IL 44122

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

H.A. SESSLER

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
110; T.C. 327	SA9EA	Warner 145 hp engine SS-50A and Hamilton Standard 5B1-12 propellers utilizing Fairchild 24J exhaust collector, engine ring cowl, and carburetor.	EA	52715	John E. McCarthy 2108 32nd Place, S.E. Washington, D.C. 20000

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SHORT BROTHERS, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SD3-30; T.C. A41EU	SA371GL	Installation of Norton radome kit No. 4064X. Issued 10/26/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Productions Operations P.O. Box 350 Akron, OH 44309

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SIAI-MARCHETTI, S.P.A.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S205-18F, -18R, S205-22/R, S208, S208A, F.260, F.260B; T.C. A9EU, A10EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
S205-18F, -18R, S205-22/R, S208, S208A, F.260, F.260B; T.C. A9EU, A10EU	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
S.205-18/F, S.205-18/R; S.205-20/F, S.205-20R, S.205-22/R; T.C. A9EU	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	RM	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
S.205-18R, -20R, -22R; T.C. A9EU	SA3080SW-D	Automatic flight system AK551 consisting of Century I autopilot with omni tracker. Issued 10/31/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S.205-18R, -20R, -22R; T.C. A9EU	SA3081SW-D	Automatic flight system AK552 consisting of Century IIB autopilot with optional radio coupler. Issued 10/31/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S.205-22/R; T.C. A9EU	SA594EA	Relocation of instrument group. Revised limit and range markings on vacuum gauge and cylinder temperature gauge.	EA	84385	Waco Aircraft Company P.O. Box 398 Pottstown, PA 19464
S.205-22/R; T.C. A9EU	SA650EA	Revison to wiring system to incorporate switch/circuit breakers with accompanying changes to panels and identification.	EA	84385	Waco Aircraft Company P.O. Box 398 Pottstown, PA 1944
S.205-22/R; T.C. A9EU	SA720EA	Installation of winterization kit.	EA	84385	Waco Aircraft Company P.O. Box 398 Pottstown, PA 1944
S.205-22/R; T.C. A9EU	SA731EA	Installation of Stewart-Warner tachometer P/N 551-WM and flexible drive shaft P/N 446642.	EA	84385	Waco Aircraft Company P.O. Box 398 Pottstown, PA 19464
S.205-22/R; T.C. A9EU	SA737EA	Installation of engine primer kit.	EA	84385	Waco Aircraft Company P.O. Box 398 Pottstown, PA 19464
S.205-22/R; T.C. A9eu	SA936SW	Swept vertical tail.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
S.205-22/R; T.C. A9EU	SA1014SW	One piece windshield to replace two piece windshield and center post.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
S.205-22/R; T.C. A9EU	SA1564WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. of Sundstrand Corporation Ovrlake Industrial Park Redmond, WA 98052
S.205 Series; T.C. A9EU	SA1652WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
S220 Series; T.C. A9EU	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S220 Series; T.C. A9EU	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
F.260; T.C. A10EU	SA302GL	Installation of Lycoming IO-540-D4A5 engine, Christen 801 series inverted oil system and an inverted fuel system.	GL	37010	Gary L. Fritzler 12700 Lake Avenue, #1911 Lakewood, OH 44107
F.260, F.260B; T.C. A10EU	SA3075SW-D	Mitchell automatic flight system AK549 consisting of Century I autopilot with optional omni tracker. Issued 10/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F.260, F.260B; T.C. A10EU	SA3076SW-D	Mitchell automatic flight system AK550 consisting of Century IIB with optional omni tracker. Issued 10/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SIKORSKY AIRCRAFT

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
VS-44-A; T.C. 752	SA4-1105	Ceconite 101 covering of ailerons and flaps.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
VS-44-A; T.C. 752	SA1351WE	Replae exsting fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
VS-44-A; T.C. 752	SA2666WE	Ceconite 102 material covering of ailerons and flaps. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S-51; T.C. H-2	SA4-100	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 West Magnolia Burbank, CA 91505
S-55; T.C. 1H4	SH4-101	Pratt & Whitney 101-79 engine mount replaced.	WE	83500	Vibration Isolation Products, Inc. 212 West Magnolia Burbank, CA 91505
S-55; T.C. 1H4	SH449NW	Incorporation of a weighing system for external load operations. Issued 5/19/77.	NW	56890	Measurement Systems International 619 South Riverside Drive Seattle, WA 98108
S-55, S-55B, S-55C; T.C. 1H4	SH127WE	Installation of AiResearch TSE-331-3U-303N engine and related changes. Reissued 1/30/74.	WE	42010	Helitec Corporation 4930 East Falcon Drive Mesa, AZ 85205
S-55, S-55B, S-55C, H-19; T.C. 1H4, HR1SO	SH1072SO	Installation of dust boot retainer rings (in rotor head dampers). Issued 5/18/79.	SO	61890	Orlando Helicopter Airways, Inc. P.O. Box 2802 Orlando, FL 32802
S-55, S-55C; T.C. 1H4	SH51WE	Installation of George M. Adams Model DGA-2000 wheel assembly.	WE	16860	Malcolm E. Bodell 2304 Pennsylvania Avenue Torrance, CA 90501
S-55, S-55C; T.C. 1H4	SH71EA	South Wind heater 8259-A.	NE	49200	Laboratory for Electronics, Inc. 1079 Commonwealth Avenue Boston, MA 02109
S-55, S-55C; T.C. 1H4	SH150WE	Installation of Chadwick electronic weighing system C-46. Issued 6/1/72.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
S-55 Series, S-58 Series; T.C. 1H4, 1H11	SH770NW	Installation of a weighing system. Issued 5/15/79.	NW	61842	Onboard Weighin System P.O. Box 03413 Portland, OR 97203
S55B; T.C. 1H4	SH125WE	Installation of AiResearch TSE-331-3U-303N engine and related changes. (Limited to serial number 55607). Amended 6/25/71.	WE	14000	Aviation Specialties, Inc 4930 East Falcon Drive Mesa, AZ 85205
S-58; T.C. 1H11	SH453NW	Incorporation of a weighing system for external load operations. Issued 6/7/77.	NW	56890	Measurement Systems International 601 South Riverside Drive Seattle, WA 98108
S-58A thru S-58J, S-58B/T, S-58D/T, S-58E/T; T.C. 1H11	SH142WE	Installation of electronic weighing system c-40. Issued 3/20/72.	NW	20750	Chadwick, Inc 4375 Southwest 142nd Avenue Beaverton, OR 97005
S-58BT, S-58DT, S-58ET, S-58FT, S-58HT, S-58JT; T.C. 1H11	SH3NE	Norton AC3093K radome installation and Bendix RDR 110 radar system installation. Issued 3/5/74.	NE	62031	Oxford Avionics, Inc. 288 Christian Street Oxford Airport Oxford, CT 06483
S-58BT, -58DT, -58ET, -58FT, -58HT, -58JT; T.C. 1H11	SA77GL	Installation of Bendix weather radar RDR-1200. Amended 5/15/75.	GL	21700	Chicago Helicopter Airways, Inc. 5315 West 63rd Street Chicago, IL 60638
S-58D; T.C. 1H11	SH206GL	Installation of HUS-1 titanium firewall with intumescent coating. Issued 12/30/77.	GL	59370	Midwest Helicopter Airways, Inc. P.O. Box 255 Lyons, IL 60534
S-58E; T.C. 1H11	SH109GL	Installation of CH-34A titanium firewall with intumescent coating. Issued 2/17/76.	GL	49320	Lake Line Helicopters, Inc. Southport Airport Rosemount, MN 55068
S-61; T.C. 1H15	SH413NW	Installation of Model SI-150-16 system. Reissued 4/19/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S-61L; T.C. 1H15	SH33WE	Radio navigation equipment.	WE	52071	Los Angeles Airways, Inc. 5901 West Imperial Highway Los Angeles, CA 90009
S-61L; T.C. 1H15	SH49WE	Dual radic navigation system.	WE	52071	Los Angeles Airways, Inc. 5901 West Imperial Highway Los Angeles, CA 9009
S-61L; T.C. 1H15	SH91WE	Electrical system modification. Amended 4/23/69.	WE	52071	Los Angeles Airways, Inc. 5901 West Imperial Highway Los Angeles, CA 90009
S-61L, -61N; T.C. 1H15	SH151WE	Installation of Chadwick electronic weighing system C-43. Issued 6/26/72.	NW	20750	Chadwick, Inc. 435 Southwest 142nd Avenue Beaverton, OR 97005
S-61L, -61N; T.C. 1H15	SA836EA	Installation of engine air inlet screens. Issued 8/13/70.	NE	71730	Sikorsky Aircraft Div. United Aircraft Corporation Stratford, CT 06602
S-61L, -61N, S-62A; T.C. 1H15, 1H13	SH155WE	Installation of battery temperature monitor system. Amended 11/2/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
S-61N; T.C. 1H15	SH81WE	Installation of engine air inlet screens. Reissued 11/9/77.	WE	44262	International Helicopter Parts, Inc. P.O. Box 2449 Oakland, CA 94614
S-61N; T.C. 1H15	SH593EA	Installation of Sperry C14A gyrosyn compass system.	NE	07498	AiResearch Aviation MacArthur Airport 3332 Smithtown Avenue Ronkonkoma, L.I., NY 11779
S-62A; T.C. 1H13	SH196WE	Installation of 10 (ten) passenger interior arrangement. Issued 12/7/76.	WE	17200	Briles Wing & Helicopter, Inc. 3011 Airport Avenue Santa Monica, CA 90405
S-62A; T.C. 1H13	SH1790SW	Foxtronics/Tramm BTI-600 nickel cadmium battery temperature. Issued 1/29/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
S-64 Series; T.C. H6EA	SH546NW	Installation of load cell monitor system. Issued 12/28/77.	NW	56890	Measurement Systems International 619 South Riverside Drive Seattle, WA 98108
S-64 Series; T.C. H6EA	SH607NW	Installation of mechanical release system for external cargo hook. Issued 5/31/78.	NW	52685	McCallister Engineering Enterprises 9739 South 208th Street Kent, WA 98031
S-64E; T.C. H6EA	SH579NW	Install Vickers hoist pump, APU starter motor and handpump for rotor brake system. Issued 3/24/78.	NW	33670	Erickson Air-Crane Company P.O. Box 3247 Central Point, OR 97502
S-64E; T.C. H6EA	SH580NW	Install Vickers hoist pump, APU starter motor and handpump for rotor brake system. Issued 3/24/78.	NW	33670	Erickson Air-Crane Company P.O. Box 3247 Central Point, OR 97502
S-64E; T.C. H6EA	SH581NW	Install Vickers hoist pump, APU starter motor and handpump for rotor brake system. Issued 3/24/78.	NW	33670	Erickson Air-Crane Company P.O. Box 3247 Central POint, OR 97520
S-64E; T.C. H6EA	SH606NW	Install AiResearch motor driven fan for transmission cooling system. Issued 6/22/78.	NW	33670	Erickson Air Crane Company P.O. Box 3247 Central Point, OR 97502
S-64 Series; T.C. H6EA	SH607NW	Install mechanical release system for external cargo hook. Issued 5/31/78.	NW	52685	McAllister Engineering Enterprises 9739 South 208th Kent, WA 98031
S-64E; T.C. H6EA	SA3894WE	Installation of hoist pump (yoke type), P/N ACH60552L6. Issued 4/2/79.	WE	01770	Aero-Craft Hydraulics, Inc. 2428 West Carson Street Torrance, CA 90501
S-64E; T.C. H6EA	SA3895WE	Installation of auxiliary power unit (APU) starter motor, P/N ACH-3911-205SPCL. Issued 4/2/79.	WE	01770	Aero-Craft Hydraulics, Inc. 2428 West Carson Street Torrance, CA 90501
S-76A; T.C. H1NE	SH286GL	Install Norton Co. radome P/N AD-4082X-2 (Sikorsky P/N 76600-02110-101) or Norton radome P/N AD-4082X-10 (Sikorsky P/N 76600-02110-102). Amended 12/20/79.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

S.L. INDUSTRIES

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B-1, B-1A; T.C. A7WE, A8WE	SA4-1210	Installation of Eonnex cover on aircraft surfaces Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
B-1, B-1A; 10, 100; T.C. A7WE, 1A21	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
10, 10A, 100, 100A, 100-180; T.C. 1A21	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
10, 10A, 100, 100A, 100-180; T.C. 1A21	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
10, 10A (Volaire); 100, -A, -180; T.C. 1A21	SA1716WE	INstallation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
100 Series; T.C. 1A21	SA1398WE	Removal of right-hand door to permit aircraft to engage in special operations such as aerial photography, parachute jumping, etc.	WE	81150	University Air Service University Airport Davis, CA 95616
100; T.C. 1A21	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
100 Series; T.C. 1A21	SA2040WE	Installation of Brittain Industries B2C or ACS-1 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
100 Series; T.C. 1A21	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
100, 100-180; T.C. 1A21	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14 14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avnue Deep River, CT 06417
100, 100-180; T.C. 1A21	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W or A470W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
100-180; T.C. 1A21	SA1080SW	Mitchell automatic flight system AK293 consisting of Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
100-180; T.C. 1A21	SA1081SW	Mitchell automatic flight system AK294 consisting of automatic stabilizer and optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

TED SMITH AEROSTAR CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
360, 400; T.C. A11WE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SOCIETE NATIONALE INDUSTRIELLE AEROSPATIALE (S.N.I.A.S.)

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SE 3130 Alouette II; T.C. 7H1	SH1-175	American type rate of climb, altimeter, air speed and outside air temperature indicators.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-253	Goodyear floats and United States hardware.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-315	Modification of rotor swash plate.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-461	Engine air inlet duct screens.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-475	Purolator fuel filter element type EP-173 P/N 6656561 and gasket 6656574.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-504	Cabin heating system utilizing Stewart-Warner 940F24 heater.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-527	Transmission gears in transmission box assembly SE 3130 62-30-00; 81P740009 first stage sun gear, one; 81P740006 second stage sun gear, one; 81P740007 satellite gear, twelve.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-563	Tail light modification.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-592	American manufactured instrument panel and cabin dome lighting.	EA	67170	Republic Aviaiton Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-614	Anti-collision rotating beacon light.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-616	Marginal weather instrument group consisting of directional gyro, gyro horizon and turn-slip indicators.	EA	67170	Republic Aviation Corp. Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-617	Grimes eyebrow instrument lights.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-618	Shoulder harness for pilot and copilot.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-623	American type folding 3-man troop seat.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH159EA	Raybestos-Manhatten Ray-Bond (R) R8001 adhesive as an alternate bond for bonding of Alouette.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. 7H1	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K & Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. 7H1	SH1870SW	Install 315A-22-11-2[illegible] protection assembly for tail drive shaft. Issued 4/17/74.	SW	84300	Vought Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. 7H1	SH1913SW	External cargo carrier. Reissued 0/31/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Irving, TX 75050
SE.313 Series, SA318C; T.C. 7H1	SH437NW	Incorporation of a weighing system for external load operations. Amended 6/10/77.	NW	56890	Measurement Systems Inter'l 619 Riverside Drive Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA-318C; T.C. 7H1	SH130WE	Installation of Nightsun SX-16C searchlight (an SEB Type 505 DC starter-generator per STC SH125SW is required. Issued 7/12/71.	WE	74500	Spectrolab Division of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
SA-318C; T.C. 7H1	SH406AL	Installation of L2700 SA 318 skis. Reivsed 2/2/71.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
SA318C; T.C. 7H1	SH440AL	Installation of cargo baskets. Issued 7/16/71.	AL	08500	Alaskan Sky-Craft Company P.O. Box 6206 Anchorage, AK 99502
SA-318C; T.C. 7H1	SH475AL	Installation of ASC-3 maintenance platform, -4 maintenance platform step, and -5 personnel step. Issued 4/3/72.	AL	08500	Alaskan Sky-Craft Company P.O. Box 6206 Anchorage, AK 99502
SA-318C; T.C. 7H1	SH540NW	Install onboard weighing system. Issued 1/9/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA-318C; T.C. 7H1	SH694NW	Installation of Model 2512 weighing system. Issued 12/14/78.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SA-318C; T.C. 7H1	SA1249SW	Eastern rotorcraft cargo hook 2A15E. Reissued 10/7/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-318C; T.C. 7H1	SH1253SW	S.E.B. 505 starter-generator to replace Labinal starter-generator. Reissued 9/30/77.	SW	84300	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-318C; T.C. 7H1	SH1277SW	Eastern Rotorcraft cargo hook and "H" frame 17080-1. Issued 3/17/71.	SW	84300	Vought Helicopter, Inc. 1701 West Marshall Drive Grand Prairie, TX 75050
SA-318C; T.C. 7H1	SH1384SW	Replace existing landing light and anti-collision light. Reissued 9/30/77.	SW	84300	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-318C; T.C. 7H1	SH1792SW	Foxtronics/Tramm BTI 600 nickel cadmium battery temperature system. Issued 1/29/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
SA330F, G, J; T.C. H4EU	SH2963SW	Seat belt assembly. Issued 3/23/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA330G; T.C. H4EU	SH1983SW	Utility interior arrangement. Reissued 11/8/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA330G; T.C. H4EU	SH1985SW	Supplementary strobe lights and replacement of existing power position lights on sponson. Reissued 11/8/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA330G; T.C. H4EU	SA1986SW	Fixed position retractable landing lights. Reissued 11/8/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH529AL	Installation of L2700 SA341HS skis. Amended 11/26/74.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
SA. 341G; T.C. H6EU	SH734NW	Installation of an Onboard Weighing System. Issued 3/21/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SA.341G; T.C. H6EU	SH1621SW	Eastern Rotorcraft cargo hook. Reissued 6/30/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1654SW	Environmental control unit. Reissued 1/22/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1770SW	Modified cockpit instrument panel. Reissued 6/30/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1858SW	Tail rotor drive shaft cover. Issued 3/20/74.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA.341G; T.C. H6EU	SH1894SW	Grimes Manufacturing Co. landing light Model G-3600 A-3. Issued 7/22/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA.341G; T.C. H6EU	SA1903SW	Single/dual stowable litter kit. Reissued 6/7/77.	SW	03010	Aerospatiale Helicopter Corp. 1707 W. Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1956SW	Install 341-78-3D-036 hour meter kit. Reissued 3/5/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1989SW	Replace main rotor blade L.E. protection strip. Issued 5/21/75.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1991SW	Installation of instruments. Issued 5/26/75.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2264SW	Alternate main gear box shaft input seal. Issued 10/17/75.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2272SW	Strobe lights. Issued 11/18/75.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2278SW	Installation of coffee bar. Issued 12/11/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA.341G; T.C. H6EU	SH2291SW	Motorola stereo Model TD204S. Issued 2/12/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2292SW	Flitephone III system. Issued 2/12/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G;	SH2306SW	Relocation of emergency float inflation bottles and quick removal provisions for emergency floats. Issued 4/28/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2347SW	Install Nightsun searchlight. Issued 8/12/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2371SW	Installation of main rotor head. Issued 10/21/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2379SW	Extend cabin section 200mm just forward of rear bulkhead. Issued 11/3/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2400SW	Installation of ATC SH1975 configurations -5, -6, IFR Category II certification. Issued 2/2/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2453SW	Installation of cabin floor extension. Issued 4/22/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA341G; T.C. H6EU	SH2472SW	Installation of exterior markings. Amended 4/24/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA341G; T.C. H6EU	SH2497SW	Structural provisions and installation of aft ballast. Issue 8/24/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA341G; T.C. H6EU	SH2664SW	Install right hand maintenance step. Issued 10/12/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-341G; T.C. H6EU	SH2931SW	Toe weights in skid gear. Issued 3/12/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
262A Series; T.C. A6EU	SA2367SW	Install complete interior including lavatory, galley and seating. Reissued 1/12/77.	SW	36700	Frakes AViation, Inc. Route 3, Box 229-B Cleburne, TX 76031
262A Series; T.C. A6EU	SA2369SW	Install P&W ACL PT6A-45A engine. Issued 10/19/76.	SW	36700	Frakes Aviation, Inc. Route 3, Box 229-B Cleburne, TX 76031
Nord 262A; T.C. A6EU	SA3596WE	Replace existing one-piece entry door with a two-piece door with integral steps in the lower half. Issued 3/15/78.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
262A-12; T.C. A6EU	SA370CE	MP-5 autostereo magnetic tape player unit.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
262A-12; T.C. A6EU	SA388CE	U.S. manufactured aircraft control cable substituted to AN standards.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
262A-12; T.C. A6EU	SA482CE	Installation of cockpit voice recorder.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
262A-12; T.C. A6EU	SA987EA	Installation of forward facing modified double seat on right hand side of aircraft cabin at Station 503 including incorporation of associated seat supporting structure. Reissued 8/4/74.	EA	66390	Ransome Airlines North Philadelphia Airport Grant Avenue & Ashton Road Philadelphia, PA 19114
262A-12; T.C. A6EU	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 3/21/72.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Nord) 262 A-12; T.C. A6EU	SA2666WE	Ceconite 102 material covering of upper rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
"Corvette" SN601; T.C. A37EU	SA2230SW	Interior and associated modifications. Reissued 6/22/76.	EU	73645	Societe Nationale Indus. Aerospatiale 37 Blvd. de Montmorency Paris 16, France
SA-360C; T.C. H8EU	SH2319SW	Seat modification. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2320SW	Installation of bar. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2321SW	Install folding table. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2322SW	Installation of coat closet. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2323SW	Installation of trash container. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2324SW	Inner-window assembly. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. A8EU	SH2402SW	Emergency lighting system. Issued 2/3/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA360C; T.C. H8EU	SH2441SW	Soundproofing. Issued 3/29/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C; T.C. H8EU	SH2445SW	Installation of exterior markings. Amended 4/24/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C; T.C. H8EU	SH2708SW	Alternate anti-collision/strobe lights. Issued 1/23/78.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C; T.C. H8EU	SH4019SW	Installation of RCA Primus 50 radar. Issued 7/18/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350, D, D-1; T.C. H9EU	SH2825SW	Air Cruisers Model D24724 emergency flotation gear. Issued 8/25/78.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2934SW	Supplemental strobe lights. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2935SW	Standard interior. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2936SW	Reversible dual bunch seat. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AS-350B; T.C. H9EU	SH2937SW	Dual non-stowable litter kit. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2938SW	Electric gyro instruments. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2972SW	Net assemblies in side baggage compartment. Issued 4/11/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2973SW	Minimum required external markings. Issued 4/11/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4016SW	Installation of hourmeter. Issued 7/13/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 76067
AS-350B; T.C. H9EU	SH4032SW	Air Cruisers Model D24724 emergency flotation gear. Issued 8/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4044SW	Patient supplemental oxygen supply. Issued 1/18/80.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4048SW	Installation of a storage pouch. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B, AS-350C, AS-350D; T.C. H9EU	SH183RM	Installation of electric driven air-conditioner system. Issued 9/5/79.	RM	45750	J B Systems 120 Bowen Circle Longmont, CO 80501
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH189RM	Installation of belt driven air-conditioner system. Amended 1/10/80.	RM	01950	Aero Engineering Corporation 2678 Delta Drive Colorado Springs, CO 80910
AS-350C; T.C. H9EU	SH748NW	Installation of a weighing system. Issued 4/12/79.	NW	52685	McAllister Engineering Enterprises 9739 South 208th Street Kent, WA 98031
AS-350C; T.C. H9EU	SH2814SW	Chip detectors. Issued 7/14/78.	SW	03010	Aerospatiale Helicopters, Inc. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH2817SW	Install net assemblies in side baggage compartments. Issued 7/18/78.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH2819SW	Minimum required external markings. Issued 7/19/78.	SW	03010	Aerospatiale Helicopters, Inc. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-305C, D, D-1; T.C. H9EU	SH740NW	Installation of a weighing system. Issued 4/6/79.	NW	56890	Measurement Systems International 580 South Lucille Street Seattle, WA 98108
AS-350C, D, D-1; T.C. H9EU	SH771NW	Installation of a weighing system. Issued 5/15/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
AS-350C, D, D-1; T.C. H9EU	SH2866SW	Installation of hourmeter. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2886SW	Installation of supplemental strobe lights. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2895SW	Installation of standard interior. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2913SW	Installation of reversible dual bench seat. Issued 2/21/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9Eu	SH2914SW	Installation of dual non-stowable litter kit. Issued 2/21/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D1; T.C. H9EU	SH2915SW	Modify damping capacity accumulator, P/N 350A54.1006.00. Issued 2/22/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2917SW	Install electric gyro instruments. Issued 2/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AS-350C, D, D-1; T.C. H9EU	SH2929SW	Install TEDECO fuel flow chip detector. Issued 3/9/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4043SW	Patient supplemental oxygen supply. Issued 1/18/80.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4049SW	Installation of a storage pouch. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

S.O.C.A.T.A. - GROUPE AEROSPATIALE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
880, 885, 894; T.C. 7A14	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
MS880B, MS892A-150, MS892E-150, MS894A, MS894E, MS893A, MS893E, MS895; T.C. 7A14	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
MS880B, MS892A-150, MS892E-150, MS894A, MS894E, MS893A, MS893E, MS895; T.C. 7A14	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
MS880B, MS885, MS892A-150, MS892E-150 (Rallye 150GT), MS893A, MS893E (Rallye 180GT), MS894A, MS894E (Rallye 220 and 220GT), Rallye 100S, 150T, 150ST, 235E (235GT); T.C. 7A14	SA1130EA	Installation of DeVore "Tel-Tail" lights on upper surface of horizontal stabilizer. Reissued and amended 1/12/79.	EA	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
MS892A-150, MS893A, MS894A; T.C. 7A14	SA3050SW-D	Automatic flight system AK527 consisting of Century I autopilot with optional omni tracker. Issued 3/20/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
MS892A-150, MS893A, MS894A; T.C. 7A14	SA3051SW-D	Automatic flight system AK528 consisting of Century IIB autopilot with optional radio coupler. Issued 3/20/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
(Rallye) 235E; T.C. 7A14	SA3249SW-D	Mitchell yaw damper YK724. Issued 10/14/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SPARTAN AIRCRAFT COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
7W; T.C. 628	SA4-1408	Hartzell HCB3Z30-1E/10152-5 1/2 propeller and C-3 governor.	WE	85124	West Coast Propeller Company 1101 Chestnut Street Burbank, CA 91500
7W; T.C. 628	SA4-1475	Ceconite 101 covering of all fabric-covered surfaces.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
7W; T.C. 628	SA122SW	Fibergalss square wing tip.	SW	81300	C.R. Ursell 109 Briarcliff Drive San Antonio, TX 78205
7W; T.C. 628	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
7W; T.C. 628	SA2666WE	Ceconite 102 material covering of all fabric-covered control surfaces. 4/19/78.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SPINKS INDUSTRIES, M.H. SPINKS, SR.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Rawdon T-1; T.C. 794	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
Rawdon T-1; T.C. 794	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler 4A-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Rawdon T-1; T.C. 794	SA444CE	Conversion of Goodyear L6H/MBD wheel to Rawdon Brothers T2A-2650 wheel. Reissued 4/7/78.	CE	74600	Spinks Industries P.O. Box 11099 Ft. Worth, TX 76110
Rawdon T-1; T.C. 794	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

STEARMAN AIRCRAFT COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
4-CM-1; T.C. 2-155	SA2666WE	Cedconite 102 material covering of rudder and fuselage. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
STERLING AIRCRAFT INDUSTRIES, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Piasecki (Navy) HUP-2; T.C. H7WE	SH160WE	Installation of agricultural spray system. Issued 8/14/73.	WE	75108	Sterling Aircraft Industries 6721 Whispering Hills Scottsdale, AZ 85251

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

STINSON DIVISION
CONSOLIDATED VULTEE AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
L-1, L-5, -5B, -5C, -5D, -5E, -5E-1, -5G, SM-8-8A, SR-7A, -7B, -7C, SR-8A, -8B, -8C, -8D, -8E, SR-9A, -9B, -9C, -9D, -9DM, -9E, -9E(M), -9F, HW-75, 10, 10A, 10B, V-77; LTC-26, T.C. 764, 295, ATC 594, 608, 609, 621, 625, 640, T.C. 709, 738, 774	SA2666WE	Ceconite 102 material covering of: L-1, L-5 Series, SM-8-8A, SR-8A Series, SR-9A Series, HW-75, 10, 10A, B - complete aircraft; SR-7A Series - horizontal stabilizer, elevators and rudder; V-77 - fuselage and vertical stabilizer. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
L-5 Series; T.C. 764	SA4-763	Glass cloth applies to wings, fuselage, and ailerons.	WE	30860	Glasco-Air Products County Airport Oxnard, CA 93030
L-5 Series; T.C. 764	SA4-1036	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
L-5 Series; T.C. 764	SA2PC	Air to ground public address system.	PC	41274	Hawaii Wing, Civil Air Patrol P.O. Box 2722 Honolulu, HI 96820
L-5 Series; T.C. 764	SA340WE	Engine mount 2028 (restricted category only).	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
L-5, -5B, -5C, -5D, -5E-1, -5G, SM-8A, IR-S, V77, HW75, 10A, 10B; T.C. 764, 295, 423, 774, A709, 738	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
L-5; HW-75; 10A, 10B; T.C. A-764, A-709, A-738	SA798EA	Installation of MOnitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
L-5, -5B, -5C, -5D, -5E, -5E-1, -5C; SR-7A, -7B, -7C; SR-8A, -8B, -8C; SR-8D, -8E; SR9A, -9B, -9C; SR-9D, -9DM, -9E, -9E(M), SR-9F; HW-75, 10; 10A, 10B; V-77; L-1; T.C. 764, ATC 594, 608, 609, 621, 640, T.C. 709, 738, 774, LTC 26	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
JR. S; T.C. 423	SA4-890	Glass cloth applied on fuselage.	WE	30860	Glasco-Air Products 1125 First Street San Fernando, CA 93030
Jr. SR-4; T.C. 519	SA207WE	Removal of cabin doors for parachute jumping and aerial photography operations.	NW	16400	Marvin L. Bertram 1034 West Oregon Street Moses Lake, WA 98837
SR-6; T.C. 580	SA4-374	Glass cloth applied to wings, fuselage, flaps, and tail surfaces.	WE	30860	Glasco-Air Products County Airport Oxnard, CA 93030
SR-7 Series; T.C. 594	SA499WE	Ceconite 101 covering of horizontal stabilizer, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SR-8 Series; T.C. 608	SA4-665	Glass cloth applied over fuselage, wings, and horizontal and vertical stabilizers.	WE	30860	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
SR-8 Series; T.C. 608	SA320SO	Conversion of airplane for parachute jumping.	SO	52547	Luke's Flying Service Moncks Corner, SC 29461
SR-8 Series; T.C. 608, 609	SA707WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SR-9 Series; T.C. 621, 625, 640	SA4-1388	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SR-9F; T.C. 640	SA4-1202	Glass cloth applied over fuselage, wings, empennage and control surfaces.	WE	30860	Glasco-Air Products 1125 First Street San Fernando, CA 93030
SR-10D, SR-10E; T.C. 679	SA4-50	Increased gross weight to 4,650 pounds, modified fuselage, and replacement of horizontal surfaces from SR-10F.	WE	84610	Wardlow Aircraft Company 611 14th Street Huntington Beach, CA 92646
SR-10F; T.C. 685	SA4-504	Swing-out type engine mount, carburetor air heat, engine cowl, oil cooler, carburetor air scoop, and fabrication and installation of oil tank.	WE	84611	Floyd M. Wardlow 1717 Park Street Huntington Beach, CA 92646
SR-10F; T.C. 685	SA4-505	Metalizing of wigngs, fuselage, horizontal and vertical stabilizers; installation of cargo door and fuselage truss, cockpit door, engine firewall, Stewart Warner 940-B heater, and Widgit seat fastener.	WE	84611	Floyd M. Wardlow 1717 Park Street Huntington Beach, CA 92646
SR-10F; T.C. 685	SA4-506	Cessna T-50 tail wheel assembly.	WE	84611	Floyd M. Wardlow 1717 Park Street Huntington Beach, CA 92646
V-77; T.C. 774	SA1-34	Modification for camera installation.	EA	77568	L.S. Taylor Engineering Clarion, PA 16214
V-77; T.C. 774	SA4-428	Glass cloth with resin applied to all fabric surfaces except movable controls.	WE	30860	Glasco-Air Products County Airport Oxnard, CA 93030
V-77; T.C. 774	SA4-478	Ceconite 101 covering of fuselage and vertical stabilizer.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
t+1 V-77; T.C. 774	SA4-1620	Removal of cabin door for parachute jumping and aerial photography operations.	WE	62550	Lawrence Parks 2880 Kistake Lane Reno, NV 89501
V-77; T.C. 774	SA368CE	Replace wing rib stitches with P-K screws. Reissued 8/30/72.	SW	68440	William Roberts 326 Hawthorne Lane Grand Prairie, TX 75050
V-77 (Landplane only, normal category); T.C. A-774	SA2622WE	Installation of Pratt & Whitney R-985-39, -39A, -AN-1, -AN-3, or -AN14BM1 engine and Hamilton Standard 2D30/6101A-15 or -21 propeller. Issued 12/13/72.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
HW-75; T.C. 709	SA1008WE	Poly-fiber covering of airplane. Amended 2/1/67.	WE	75250	Stits Aviation Corporation Box 3084 Riverside, CA 92502
HW-75, 10; T.C. 709	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
HW-75, 10; T.C. 709	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
HW-75, 10; T.C. 709	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
HW-75, 10, 10A, 10B; T.C. 709, 738	SA4-1575	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
10; T.C. 709	SA4-184	Continental C-85-12F engine.	WE	21402	W.H. Chandler 1005 East Mariposa Street Altadena, CA 91001
10; T.C. 709	SA342SW	Lycoming O-235-C1 engine with Sensenich M76AM-2 propeller, associated powerplant changes and electrical changes.	SW	70386	James A. Schultze 1009 Edinburgh Lane Denton, TX 76201
10A; T.C. 738	SA3-63	Replacement of original center elevator hinge and bearing assembly by split bearing and split housing hinge assembly.	GL	35660	Vern E. Flanders 1018 East Olive Street Bloomington, IL 61701
10A; T.C. 738	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT

STOL AMPHIBIAN CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
RC-3; T.C. 769	SA1-18	Increasing the wing span 16 inches and incorporating wing tip spill plates.	NE	67725	Ned C. Rice 470 Silver Lane East Hartford, CT 06108
RC-3; T.C. 769	SA1-26	Six-volt battery in bow compartment.	EA	55740	The Glenn L. Martin Company Baltimore, MD 21233
RC-3; T.C. 769	SA3-28	J.F. Hamilton modified wing tips.	GL	47715	Archie Keith Route 3 Ottawa, IL 61350
RC-3; T.C. 769	SA3-30	Modified spray rail with four foot addition to wing span.	GL	59468	Miller Flying Service North Benton, OH 44449
RC-3; T.C. 769	SA3-88	Hartzell propeller HC-13X20-54 installation. Amended 1/7/75.	GL	14210	John E. Ayer 405 South Third Street Le Sueur, MN 56058
RC-3; T.C. 769	SA3-365	Republic RC-3 starter system.	GL	70925	Sentas Skyways Service City Airport Detroit, MI 48233
RC-3; T.C. 769	SA3-380	Fuel filler door assembly installation. Amended 1/7/75.	GL	14210	John E. Ayer 405 South Third Street Le Sueur, MN 56058
RC-3; T.C. 769	SA17CE	Extension of each wing tip 24-inches.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
RC-3; T.C. 769	SA215SO	Extended wing tips.	SO	39700	Gulf Airways, Inc. P.O. Box 1126 Fort Myers, FL 33902
RC-3; T.C. 769	SA282NW	Installation of Lycoming GO-480-B1D engine and Hartzell HC83X20-2CL propeller. Issued 4/13/76.	NW	74941	S.T.C. Bee 10900 Rainier Avenue, South Seattle, WA 98178
RC-3; T.C. 769	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
RC-3; T.C. A-769	SA374NW	Installation of S.T.C. Bee, Inc. Model 1-TP-1 model instrument panel kit. Issued 11/1/76.	NW	74942	S.T.C. Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA392NW	Installation of flush fuel fill. Issued 12/28/76.	NW	74942	S.T.C. Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA393NW	Rework of main step gusset. Issued 12/28/76.	NW	74942	S.T.C. Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA394NW	Installation of Model 2-DT droop wing tips. Issued 12/28/76.	NW	74942	S.T.C Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA395NW	Reshape rear cabin windows. Issued 12/28/76.	NW	79942	S.T.C. Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
RC-3; T.C. A-769	SA575NW	Installation of longitudinal step kit. Issued 3/16/78.	NW	74942	S.T.C. Bee, Inc. 10900 Rainier Avenue Seattle, WA 98178
RC-3; T.C. A-769	SA576NW	Install disc brake system. Issued 3/14/78.	NW	74942	S.T.C. Bee, Inc. 10900 Rainier Avenue S. Seattle, WA 98178
RC-3; T.C. A-769	SA613NW	Install 28-volt electrical system. Issued 6/1/78.	NW	74942	S.T.C. Bee, Inc. 10900 Rainier Avenue S. Seattle, WA 98178
RC-3; T.C. A-769	SA615NW	Installation of Lycoming GO-435-C2b, GSO-IGSO-480, and GO-IGO-480 series engine with Hartzell HC-A2V20 and HC-A3VF series propellers with other miscellaneous models. Issued 12/28/77.	NW	71790	Simuflight, Seattle 6727 Perimeter Road, S. Seattle, WA 98108
RC-3; T.C. A-769	SA815NW	Installation of Cleveland disc type brakes. Issued 7/25/79.	NW	71790	Simuflight, Seattle 6727 Perimeter Road South Seattle, WA 98108
RC-3; T.C. A-769	SA821EA	Installation of Stol Aircraft Corporation fuel cell. Issued 5/19/70.	NE	75745	Stol Aircraft Corporation P.O. Box 175, Norwood Airport Norwood, MA 02062
RC-3; T.C. A-769	SA853EA	Installation of Stol Aircraft Corporation electric hydraulic pump system. Issued 11/19/70.	NE	75745	Stol Aircraft Corporation P.O. Box 175, Norwood Airport Norwood, MA 02062
RC-3; T.C. A-769	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
RC-3; T.C. A-769	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
RC-3; T.C. A-769	SA2386WE	Installation of Daubenspeck Model "D-1" fiberglass droop wing tips. Issued 7/28/71.	NW	28795	John A. Daubenspeck 11913 - 140th Place, N.E. Kirkland, WA 98033

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SUD AVIATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SE210 Series; T.C. 7A6	SA863EA	Incorporation of Chromalloy Electronics Division ESL-1 or ESL-6 emergency slide lighting system. Reissued 3/6/73.	SO	22225	Chromalloy Electronics Div. of Chromalloy American Corp. 3901 North 29th Avenue Hollywood, FL 33020
SE 210 Model VIR; T.C. 7A6	SA1583WE	Installation of Fairchild Model 13920-301 or 15830-601 flight data recorder and Honeywell P/N 180 VI central air data computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
SE 210 Model VIR; T.C. 7A6	SA2728WE	Incorporation of Holcombe Industries Hi-Lite System (P/N 50-1001) for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
GY.80-150, GY.80-160, GY.80-180; T.C. A12IN	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
GY.80-150, GY.80-160, GY.80-180; T.C. A12IN	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SUPERIOR AIRCRAFT COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
LCA; T.C. 730	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
LCA, LFA; T.C. 730	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
LCA, LFA; T.C. 730	SA162WE	Coconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
Culver LFA; T.C. A-730	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Culver LFA; T.C. A-730	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
V; T.C. 778	SA4-1283	Ceconite 103 covering of plywood components of the aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
V; T.C. 778	SA1NE	Installation of McCauley 1B90/ECM7151 propeller on aircraft equipped with Continental C85-12FHJ engine in accordance with Butterworth Report 1000 dated 9/13/72. Issued 11/15/72.	NE	19030	Gerald N. Butterworth 3034 Post Road Warwick, RI 02886
V; T.C. 778	SA163WE	Ceconite 103 covering of fuselage and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
SWEARINGEN AVIATION CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA26T; T.C. A5SW	SA418SO	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C. A5SW	SA461SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C. A5SW	SA571SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation each engine is limited to a maximum of 550 SHP. Issued 12/14/73.	SO	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
SA26T; T.C. A5SW	SA600WE	Install Hoskins Twilighter Mk IIIq supplemental lighting system with Model P wing tip and Model K tail light.	GL	42625	Hoskins, Inc. 34 North Bennett Geneva, IL 60134
SA26T; T.C. A5SW	SA764SW	Bendix M4C autopilot flight control system.	SO	15475	The Bendix Corporation P.O. Box 23430 Fort Lauderdale, FL 33309
SA26T; T.C. A5SW	SA1464WE	Installation of supporting structure and placards only for avionic components in the aft compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26T; T.C. A5SW	SA1465WE	Installation of supporting structure and placards only for avionic components in forward compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26-T, SA26-AT, (Merlin II); T.C. A5SW	SA600CE	Install Hoskins Twilighter Mk III supplemental lighting system with Model P wing tip and Model K tail light. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
SA26-T, SA26-AT, (Merlin II); T.C. A5SW	SA3057WE	Installation of fuel tank boost pump. Issued 7/17/75.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA26-T, SA26-AT, Merlin II; T.C. A5SW	SA3465WE	Installation of recognition light assembly on the horizontal stabilizer. Issued 8/8/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
SA26-T, 26-AT, 226-T, 226-AT; T.C. A5SW	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SA226T; T.C. A5SW	SA1078SO	Installation of Bendix FCS-8700 automatic flight control system. Issued 6/5/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-T, SA226-AT; T.C. A5SW	SA254GL	Installation of emergency/continuous water-alcohol injection system. Amended 10/3/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
SA226-T, SA226-AT; T.C. A5SW	SA273GL	Installation of a Scenic exhaust assembly, P/N YR-12013 in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-T, SA226-AT; T.C. A5SW	SA613AL	Install nose wheel steering lock system. Issued 6/3/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502
SA226-T, SA226-AT; T.C. A5SW	SA2909WE	Installation of fuel tank boost pump. Amended 8/12/75.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA226-T, SA226-AT; T.C. A5SW	SA3481WE	Installation of recognition light on the horizontal stabilizer. Issued 9/14/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406

SWEARINGEN AVIATION CORP. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA226-TC; T.C. A8SW	SA279GL	Installation of emergency/continuous water-alcohol injection system. Issued 11/1/78.	GL	07503	AiReserach Aviation Company Capital Airport Springfield, IL 62705
SA226-TC; T.C. A8SW	SA189GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA615AL	Install nose wheel steering lock system. Issued 6/21/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502
SA226-TC; T.C. A8SW	SA1068CE	Installation of Collins Radio Co. AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-TC; T.C. A8SW	SA2910WE	Installation of fuel tank boost pump. Issued 7/23/74.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA226-TC; T.C. A8SW	SA3482WE	Installation of recognition light assembly on the horizontal stabilizer. Issued 9/14/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
SA226T (S/N T-201 and up), SA226AT (S/N AT-001 and up); T.C. A5SW	SA972CE	Installation of AID battery temperature sensing and over temperature warning system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT; T.C. A5SW	SA188GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA274GL	Installation of a Scenic exhaust assembly, P/N YR-12013, in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-AT; T.C. A5SW	SA1051CE	Installation of Collins Radio Co. AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-AT; T.C. A5SW	SA1575SW	Battery isolation system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1576SW	Ray Electronics Model 7107 battery fault warning system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1577SW	Collins FCS-105 automatic/flight director system with Sperry dual flight director system. Issued 1/26/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1673SW	Battery isolation system. Issued 6/11/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA2344WE	Installation of Collins Radio Co. Model FCS-10583 autopilot flight flight director systems. Reissued 8/20/71.	CE	24250	Collins Radio Company 855 - 35th Street, N.E. Cedar Rapids, IA 52406
SA226-AT; T.C. A5SW	SA2860WE	Installation of AiResearch TPE 331-3U-307G engines and propeller synchrophasing. Issued 3/21/74.	WE	07502	AiResearch Manufacturing Company of Arizona 402 South 36th Street Phoenix, AZ 85034
SA226-AT; T.C. A5SW	SA3075WE	Installation of Garrett AirNav 100 area navigation system. Issued 10/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1238SW	Bendix M-4C automatic flight control system. Issued 12/22/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-T; T.C. A5SW	SA1241SW	Installation of supporting structure, avionics components and systems. Issued 1/6/71.	WE	07500	AiResearch Aviaiton Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1271SW	Collins AP105 automatic flight control system. Issued 3/16/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA226-T; T.C. A5SW	SA1600SW	Battery isolation system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1601SW	Ray Electronics Model 7107 battery fault warning system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1602SW	Collins AP105 automatic flight control system with dual Sperry Stars flight directors. Issued 2/6/73.	WE	07500	AiResearch Aviation Company 6201 WEst Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA2864WE	Modification to install electrical and structural provisions for Texas Instrument, Inc. infra-red scanner system. Issued 4/25/74.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T, SA226-T(B); T.C. A5SW	SA804SO	Installation of Bendix M-4D automatic flight control system, including integration into the existing Swearingen pitch trim and yaw damping systems. Amended 12/14/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226T, SA226AT; T.C. A5SW	SA2428WE	Installation of Hoskins/SDI Twilighter MK III supplemental lighting system. Issued 10/50/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226TC (S/N TC-201 and up); T.C. A8SW	SA973CE	Installation of AID battery temperature sensing and over-temperature sensing system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA821SO	Installation of Bendix M-4D automatic flight control system including optional flight director system and integration into existing Swearingen pitch trim system. Issued 1/29/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA1247SW	Bendix M-4C autopilot. Reissued 8/2/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

TAYLORCRAFT AVIATION CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BC Series; T.C. 696	SA1-217	Replacing original lacing for securing fabric to wings with screws and washers.	EA	19836	Capital Air Service, Inc. P.O. Box 467 Dover, DE 19901
BC Series; T.C. 696	SA4-294	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
BC Series; T.C. 696	SA4-613	Fiberglass wheel pants and mounting brackets of metal.	NW	82390	Richard Van Grunsven Route 2, Box 187 Forest Grove, OR 97116
BC Series; T.C. 696	SA4-830	Fiberglass covering on wings.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
BC Series; T.C. 696	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
BC Series; T.C. 696	SA4-906	Ceconite 101 covering of complete airframe. Amended 12/15/66.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
BC Series; T.C. 696	SA4-1346	Fiberglass covering on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
BC Series; T.C. 696	SA4-1438	Eronite covering of fuselage.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
BC Series; T.C. 696	SA208WE	Removal of right cabin door for parachute jumping and aerial photography operations.	RM	38040	Glacier View Skyways, Inc. P.O. Box 252 Kalispell, MT 59901
BC Series; T.C. 696	SA1008WE	Poly-Fiber covering of wings and ailerons. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
BC, BC12D; T.C. A-696	SA1-210	Conversion of Taylorcraft Model BC or Model BC12D to the equivalent of the following aircraft models: Model BC12D85 and Model BC12D-4-85 or Model 19. Amended 6/14/71.	EA	37882	Gilberti Aviation P.O. Box 246 Aliquippa, PA 15001
BC, BC-65, -12-65, -12D, -12D1, -12D-85, BCS, BCS-65, -12-65, -12D, -12D1, -12D-85, -12D-4, 85; T.C. 696	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
BC, -65, 12-65, -D, -D1, 12D-84, -4-85; BCS, -65, -12-65-D, -D1, -4-85; BC Series (Army L-2H); T.C. 696	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC, BCS, BC-65, S-65, 12-65, S12-65, 12D, S12-D, 12-D1, S12-D1, 12D-85, 12D-4-85; T.C. 696	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC, BCS, BC-65, BCS-65, BC12-65, BCS12-65, BC12D, BCS12-D, BC12-D1, BC12D-85, BC12D-4-85, BC12DS-4-85; T.C. 696	SA2666WE	Ceconite 102 material covering on complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC Series, 19; T.C. 696, 1A9	SA1-95	Wing lift struts to include a hydraulic-pneumatic shock absorber.	EA	86500	Wings With Springs, Inc. R.D. 3, Box 495 Latrobe, PA 15650
BC Series, 19; T.C. 696, 1A9	SA4-1200	Delco-Remy generator 1101879 and regulator 1118384.	RM	81060	Universal Aircraft Industries P.O. Box 5306 Denver, CO 80217

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BC Series, 19; T.C. 696, 1A9	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
BC-65, BCS-65, BC12-65, BCS12-65, BC12-D, BC12-D1, BC12D-85, BCS12D-85, BC12D-4-85, BCS12D-4-85, DC-65, DCO-65; T.C. A696	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
BC, BC-65, -12D, -12D1, BC12D-85, BCS12D-85, BC12D-4-85, 19; T.C. A-696, 1A9	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BC, BC-65, -12D, -12D1, BC12D-85, BCS12D-85, BC12D-4-85, 19; T.C. A-696, 1A9	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BC-12D; T.C. 696	SA2-225	Windshield manufactured in accordance with Luminous Plastics, Drawing No. LP-650. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
BC12D; T.C. 696	SA661AL	Installation of plexiglass skylight in fuselage cabin. Issued 1/10/79.	AL	23130	Gregory H. Clayton Box 73204 Fairbanks, AK 99707
BC12D; T.C. 696	SA1901SW	Clipped wings, revised control system, added aileron, and elevator servo tabs. Issued 8/20/74.	SW	77125	Michael Swick Route 1, Box 163 Plano, TX 75074
BC12D; T.C. A696	SA2891SW	Installation of stick type control system. Issued 12/20/78.	SW	77124	Swick Aircraft Route 3, Box 163B Lewisville, TX 75067
19; T.C. 1A9	SA90NW	Installation of Continental O-200-A engine, McCauley propeller IA100MCM/6950, and sub-systems. Issued 2/26/74.	NW	35740	Ronald W. Flinchbaugh 8265 Custer Road Tacoma, WA 98499
F19; T.C. 1A9	SA1070SO	Installation of Aqua Model 1500 floats. Issued 5/3/79.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
F19; T.C. 1A9	SA1129EA	Installation of PK Model 1800 or B1800 (TSO-C27) seaplane floats. Issued 9/7/78.	EA	29998	DeVore Aviation Corporation PK Floats 206 Newton Road Plainview, NY 11803

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

TAYLORCRAFT, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC Series; T.C. 746	SA1-86	McCauley metal fixed-pitch propeller 1B90-CM on aircraft powered by Continental A-65 engine.	EA	16575	Beth-Air Consulting 8618 Garfield Street Bethesda, MD 20014
DC Series; T.C. 746	SA3-43	Fiberglass fabric application to fuselage, wings and fixed tail surfaces.	CE	42330	Elmer Hopson 2451 Chelsea Kansas City, MO 64108
DC Series; T.C. 746	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
DC Series; T.C. 746	SA4-856	Glass cloth applied over wings and horizontal stabilizer.	WE	38060	Glasco-Air Products 1125 First Street San Fernando, CA 93030
DC Series; T.C. 746	SA4-1527	Ceconite 101 covering of wings and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC Series; T.C. 746	SA391SO	Installation of glass fabric covering on entire aircraft.	SO	55775	K.R. Martin Route 2 Ellenwood, GA 30049
DC, DCO, DF, DL (Army L-2); T.C. 746	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BF Series; T.C. A-699	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46775	George O. Johnson 10015 South Meridian Puyallup, WA 98371
Model A; T.C. 643	SA1008WE	Installation of poly-fiber covering material of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
A, BF, BL Series; T.C. 643, 699, 700	SA4-906	Ceconite 101 covering of complete airframe. Amended 12/15/66.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC-65, DCO-65, DF-65, DL-65, A, BL, BLS, BL-65, BLS-65, BL-12-65, BLS-12-65; T.C. 746, 643, 700	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
DCO-65, 15A, 20, BF, BFS, BF-60, -65, BFS-60, -65, BF12-65, BFS12-65, BL, BLS, BL-65, BLS-65, BL12-65, BLS12-65; T.C. 746, 3A3, 699, 700	SA2666WE	Ceconite 102 material covering of: DCO-65 - wings and ailerons; 20 - wings; 15A, BF Series, BL Series - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
15A, 20; T.C. 3A3	SA3-423	CT-3000 tail ski on airplanes equipped with Scott Model 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
15A, 20; BF, BF-60, -65, BFS, BFS60, BF-12; BL, BL-65, BS12-65, BLS-65, BLS12-65; DC-65, DF-65, DCO-65; T.C. A-699, A-700, A-746	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
15A, 20; BF, BF-60, -65, BFS, BFS60, BF-12; BL, BL-65 BL12-65, BLS-65, BLS12-65; DC-65, DF-65, DCO-65; T.C. A-699, A-700, A-746	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

TAYLORCRAFT, INC. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
15A, 20; A; BF; BL; DC-65, DCO-65; FA-111; T.C. 3A3, A-699, A-700, A-746, 1A11	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
15A, 20, BL12-65, S12-65, BL, BLS, B1-65, BLS-65, BF, BFS, -60, -65, BFS-60, -65, 12-65, S12-65; DCO-65; T.C. 3A3, 700, 699, 746	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
20; T.C. 3A3	SA257WE	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
BF, BL Series; T.C. 699, 700	SA4-1346	Fiberglass covering on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
BF, BL Series; T.C. 699, 700	SA4-1438	Econite covering of fuselage.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
BL Series; T.C. 700	SA4-162	Glass cloth applied over old fabric with the exception of all flight control surfaces.	WE	85720	Whitehall Pacific Aviation, Inc. P.O. Box 3174 Ventura, CA 93001
BL, DC Series; T.C. 700, 746	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

TEAL AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
TSC-1A, -1A1, -1A2; T.C. A15EA	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
TSC-1A, -1A1, -1A2; T.C. A15EA	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
TSC-1A, -1A1, -1A2; T.C. A15EA	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

TEMCO AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
11A; T.C. 804	SA3-71	Continental E-165 engine with Hartzell HC12X20-7/8428-1 propeller.	CE	39310	Graham Flying Service Box 26, Boulevard Station Sioux City, IA 51101
11A; T.C. 804	SA4-74	McCauley 1A200 fixed pitch metal propeller.	WE	64405	Phillips Electric Company P.O. Box 85 Wofford Heights, CA 93285
11A; T.C. 804	SA4-1259	McCauley 1A200FM propeller with Continental E185-2 engine.	WE	17113	Andrew J. Brennan 944 21st Street Hermosa Beach, CA 90254
11A; T.C. 804	SA55CE	Removal of right cabin door and right front seat.	GL	61531	Max Newton Route 2 Crawfordsville, IN 47933
11A; T.C. 804	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
11A; T.C. 804	SA392EA	Glider tow hitch.	EA	73942	Bart Spadaro Montauk Highway East Moriches, NY 11940
11A; T.C. 804	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
11A; T.C. 804	SA538WE	McCauley 1A300-FM8378 propeller.	WE	56846	David M. Meade 2526 Terrace Road Tempe, AZ 85281
11A; T.C. 804	SA708WE	Removal of door for parachute jumping and aerial photography operations.	NW	26225	Nyal Collins Route 2, Box 391 Albany, OR 97321
11A; T.C. 804	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69220	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

E.J. TRYTEK

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
K; T.C. 634	SA519WE	Wheel adapters on Goodyear wheels 3L4BM.	WE	49345	Robert P. Lamb 2998 Daisy Avenue Long Beach, CA 90801

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

UNIVAIR AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
108 Series; T.C. 767	SA1-10	Replacement of wing fabric with 24 ST. alclad skin.	EA	05972	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
108 Series; T.C. 767	SA1-48	Edo 249-2870 floats.	EA	16857	James R. Blakely P.O. Box 53 Westchester Station Bronx, NY 10461
108 Series; T.C. 767	SA1-374	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
108 Series; T.C. 767	SA1-258	Conversion of aileron covering from fabric to alclad panels.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047
108 Series; T.C. 767	SA3-27	Covering of wings .020-inch 24 ST. alclad.	GL	42860	Howard Aviation, Inc. P.O. Box 1287 Peoria, IL 61601
108 Series; T.C. 767	SA3-398	Fiberglass plastic covering of all fabric surfaces.	GL	34291	John H. Fallon 601 Woodward Heights Boulevard Ferndale, MI 48220
108 Series; T.C. 767	SA3-423	Model CT-3000 tail ski on airplanes equipped with Scott Model 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
108 Series; T.C. 767	SA3-606	Complete recover of all fabric surfaces with dacron fabric.	GL	30518	Downer Aircraft Industries, Inc. Alexandria, MN 56308
108 Series; T.C. 767	SA4-46	Lycoming O-435-1 engine, accessories, and Hartzell HC-12X20-8D propeller.	WE	71000	Serv-Aero Engineering, Inc. P.O. Box 96 Dos Palos, CA 93620
108 Series; T.C. 767	SA4-148	Conversion of aircraft electrical system to 24 volts and/or installation of Franklin 6A4-165-B3 engine. Reissued 10/5/79.	WE	18125	Dean D. Brubaker P.O. Box 84409 861 South Bringham Avenue Los Angeles, CA 90073
108 Series; T.C. 767	SA4-224	Application of fiberglass covering.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
108 Series; T.C. 767	SA4-284	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
108 Series; T.C. 767	SA4-630	Eonite covering of wings, fuselage and ailerons.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
108 Series; T.C. 767	SA4-760	Ceconite 101 covering of wings, fuselage and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
108 Series; T.C. 767	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage, and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
108 Series; T.C. 767	SA4-1195	Metalized wings.	WE	08223	Air-Mod 11379 Playa Street Culver City, CA 90230
108 Series; T.C. 767	SA4-1415	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
108 Series; T.C. 767	SA4-1484	Sheet metal on wings.	WE	33910	Robert B. Everitt 2134 Xavier Santa Clara, CA 95050
108 Series; T.C. 767	SA58EA	Conversion of airplane for parachute jumping and aerial photography operations.	NE	31368	East Coast Aviation Corp. Hanscom Field Lexington, MA 02173
108 Series; T.C. 767	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
108 Series; T.C. 767	SA224SO	Removal of right door for parachute jumping and aerial photography operations.	SO	14760	Robert V. Barnam 1984 Capri Drive Decatur, GA 30030
108 Series; T.C. 767	SA228WE	Removal of right cabin door for parachute jumping and aerial photography operations.	WE	40690	John C. Harrison 2535 Garfield Avenue Carmichael, CA 95608
108 Series; T.C. 767	SA327SO	Tricycle landing gear and Lycoming O-435 engine.	SO	68550	W.F. Robinson P.O. Box 241 Lanett, AL 36863
108 Series; T.C. 767	SA343WE	8:50X6 4-ply aircraft tires and 8:50X6 tubes.	NW	60172	Rex H. Morehouse 4922 Summers Lane Klamath Falls, OR 97601
108 Series; T.C. 767	SA463CE	Metal fuselage covering.	CE	84399	David Z. Waldemer Flying W Ranch Fairdealing, MO 63939
108 Series; T.C. 767	SA515CE	Install metal wing covering.	CE	84399	David Z. Waldemer Flying W Ranch Fairdealing, MO 63936
108 Series; T.C. A-767	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
108 Series; T.C. 767	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
108 Series; T.C. 767	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
108, 108-1, -2, -3; T.C. 767	SA3-366	Installation of FluiDyne (Fli-lite) Model 3000 main skis and Model 1000 tail skis. Reissued 7/22/79.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
t+1 108, 108-1, -2, -3; T.C. 767	SA615SO	Surface fabric attachment clips. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
108, 108-1, -2, -3; T.C. 767	SA859SO	Replacement of generator P/N 1101877 installed in Franklin 6A-150 and -165 engines with a modified Motorola RA12N550 alternator. Issued 10/20/75.	SO	15240	Stanley C. Bedford 2396 Santa Cruz Drive Clearwater, FL 33516
108, 108-1, -2, -3, -4, -5; T.C. A-767	SA800EA	Installation of aviation white anti-collision strobe lights, Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
108 Series, 415C, 415CD, 415D, E, G; T.C. 767, 718, 787	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
(Stinson) 108-1, -2, -3, -4, -5, (Erco, Alon) 415-C, -CD, 415-D, -E, -G; T.C. 767, 718, 787	SA2666WE	Ceconite 102 material covering of: 108 Series - wings, fuselage and ailerons; 415 Series - wings. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
108, 108-1, -2, -3, -4, -5, 415C, -CD, 415-D, E, G; T.C. A-767, 718, 787	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
108, 108-1, -2, -3, -5; T.C. 767	SA799WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheel assemblies in lieu of Firestone wheel assembly No. DFA 180. (DGA-2000 wheel approved under TSC-C26a.) Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
108 Series, A-2, A-2A, 415D, E, G, F-1, F-1A, M-10; T.C. 767, A-787	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
108 Series, 415; T.C. 767, 718, 787	SA1008WE	Poly-Fiber covering of left and right-hand aileron. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
108 Series, F-1, F-1A; T.C. 767, 787	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Av Torrance, CA 90510
108 Series, 415C; T.C. 767, 718	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
108-1, -2, -3, 415C, -CD, F-1, F-1A, 415D, E, G, A-2, A-2A; T.C. 767, 718, 787	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
108, -1, -2, -3, -5, 415-C, -CD, A-2, A-2A, 415D, E, G, F-1, -1A, M10; T.C. 767, 718, 787	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
108, -1, -2, -3, -5, 415-C, -CD, A-2, A-2A, 415D, E, G, F-1, -1A, M10; T.C. 767, 718, 787	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
108-2, 108-3 (Landplane): T.C. 767	SA4-398	Installation of Lycoming O-435-C engine. Amended 7/10/75.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
108-2, 108-3; Land and Seaplanes; T.C. A-767	SA1199WE	Installation of Continental O-470-A, -J, -K, -L or -R engine and McCauley 2A34C/90A or 2A36C/90M propellers; or O-470A, -J, -K, or -L engine and Hartzell HC-A2XF-1/8433 or BHC-A2XF-1/8433 propellers, or O-470-R engine and Hartzell BHC-C2Y/8468 propeller. Amended 1/12/73.	NW	63500	PDX Aircraft Corporation 1906 Northeast Liberty Street Portland, OR 97211
108-3; T.C. A767	SA74NW	Install floats Edo. Issued October 1973.	NW	63500	PDX Aircraft Corporation 1906 Northeast Liberty Street Portland, OR 97211
108-3; T.C. A767	SA91NW	Installation of strobe light system with flashtube on rudder tip and power supply in fuselage. Amended 3/11/74.	NW	70384	R.J. Schroers 4479 139th Avenue SE Bellevue, WA 98006
108-3; T.C. A-767	SA238NW	Installation of Madras Air Service super tips. Issued 11/25/75.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
108-3; T.C. A-767	SA313NW	Installation of Franklin 6A-350-C1 engine and Hartzell HC-C2YF-1BF/F8459-4 to -8 propeller; also, McCauley 2A31C21/8456.	NW	70620	Seaplane Flying, Inc. 1111 S. E. Fifth Street Vancouver, WA 98661
108-3; T.C. A-767	SA637NW	Installation of oil filter assembly OF-104A. Issued 7/13/78.	NW	70620	Seaplane Flying, Inc. P.O. Box 2164 Vancouver, WA 98661
415 Series; T.C. 718, 787	SA1-4	Metal covering of outer wing panels.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047
415 Series; T.C. 718, 787	SA1-78	Metal skin replacement on wing surfaces.	EA	78623	George Townson P.O. Box 541 Meadowbrook, PA 19046
415 Series; T.C. 718, 787	SA1-208	Two 4595 100-watt General Electric sealed beam landing lights in nose cowling.	EA	08340	Air Service, Inc. P.O. Box 189 New Castle, DE 19720

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
415 Series; T.C. 718, 787	SA1-336	Continental C-90-14F engine and McCauley 1B90-CM7152 propeller.	EA	84925	Richard W. Weitley Skyport, P.O. Box 1229 Harrisburg, PA 17105
415 Series; T.C. 718, 787	SA1-440	Continental C90-12F engine.	EA	84925	Richard W. Weitley Skyport, P.O. Box 1229 Harrisburg, PA 17105
415 Series; T.C. 718, 787	SA3-19	Steel tube and aluminum covered hatch doors fabricated with plexiglass windows.	GL	01865	Aerodyne Products 2004 South 29th Street Milwaukee, WI 53202
415 Series; T.C. 718, 787	SA3-342	Metal 0.020-inch 20 24 ST 3 or 20 24 ST 4 alclad aluminum.	CE	60174	John J. Morelli Route 6, Box 428 Parkville, MO
415 Series; T.C. 718, 787	SA3-512	Aluminum alloy skin.	GL	26565	Robert B. Dale 30030 Minglewood Lane Farmington, MI 48024
415 Series; T.C. 718, 787	SA3-598	Metal 0.020 24ST aluminum on wings.	GL	86202	Harvey A. Williams 1446 North Lockwood Avenue Chicago, IL 60607
415 Series; T.C. 787	SA4-73	Metal skins 0.020 24ST and/or 75ST aluminum alloy.	WE	29160	Vern Dell Aircraft Metal Work Co. P.O. Box 42 Chula Vista, CA 92010
415 Series; T.C. 718, 787	SA4-139	Glass cloth over old fabric.	WE	85720	Whitehall Pacific Aviation, Inc. P.O. Box 31174 Ventura, CA 93001
415 Series; T.C. 718, 787	SA4-179	Fabric covering replaced with metal 0.020 24ST and/or 75ST aluminum alloy covering.	WE	29160	Vern Dell Aircraft Metal Work Co. P.O. Box 42 Chula Vista, CA 92010
415 Series; T.C. 718, 787	SA4-285	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
415 Series; T.C. 718, 787	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
415 Series; T.C. 718, 787	SA4-361	Aluminum alloy sheet on wings.	WE	19900	Carma Manufacturing Company P.O. Box 11312 Tucson, AZ 85700
415 Series; T.C. 718, 787	SA4-399	Metallizing of wings.	WE	77520	L.J. Tarnay 9314 Glasgow Place Los Angele, CA 90052
415 Series; T.C. 718, 787	SA4-441	New lower engine cowl made of fiberglass with Hetron #92 resin.	WE	78471	Wilbur Thompson 10617 South Prairie Avenue Inglewood, CA 90306
415 Series; T.C. 718, 787	SA4-448	New nose cowl made of fiberglass reinforced with Hetron #92 resin.	WE	78471	Wilbur Thompson 10617 South Prairie Avenue Inglewood, CA 90306
415 Series; T.C. 718, 787	SA4-729	Mounting brackets, flush window, and wiring to operate automotive type sealed-beam headlamp as a dual purpose landing and taxi light.	WE	01804	Aero Development Corporation P.O. Box 11201 Tucson, AZ 85706
415 Series; T.C. 718, 787	SA4-801	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
415 Series; T.C. 718, 787	SA4-839	Metal covering of wings.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series; T.C. 718, 787	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
415 Series; T.C. 718, 787	SA4-1652	Tapered roller bearing and plate on right-hand wheel half.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series; T.C. 718, 787	SA117WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
415 Series; T.C. 718, 787	SA162SO	Aileron trim system.	SO	03122	Aerotronics, Inc. Miami Beach, FL 33139
415 Series; T.C. 718, 787	SA341WE	Engine mount to remove down thrust and change horizontal tail incident.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
415 Series; T.C. 718, 787	SA465WE	Continental C-90-12F engine and McCauley 1B90-CM propeller.	WE	22218	R.B. Christianson 10510-1/2 Mather Avenue Sunland, CA 91040
415 Series, F-1; T.C. 718, 787	SA4-638	Single arm nose wheel fork with conventional double arm fabricated fork U415-34090-1-A and B.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
415 Series, F-1, F-1A; T.C. 718, 787	SA4-1254	Main gear wheel fairings, nose gear wheel fairing.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90275
415 Series, F-1, -1A; T.C. 718, 787	SA4-1606	Wing root fillets change from aluminum 3S and 24ST3 to fiberglass.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series, F-1, -1A; T.C. 718, 787	SA1WE	Fiberglass tail cone.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series, F-1, -1A; T.C. 718, 787	SA3WE	Fiberglass reinforced plastic engine cowl.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415-C, 415-CD, S/N 813 and up; T.C. A-718	SA120GL	Install Cleveland Wheel and Brakes conversion kit, P/N 199-69. Amended 7/7/76.	GL	23250	Cleveland Wheels and Brakes Div. VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011
415-C, 415-CD; T.C. A-718	SA330GL	Installation of Skyport Model SMK-15, 9-cu.ft. baggage compartment. Issued 7/18/79.	GL	36566	Skyport Aircoupe Services Division Fox Engineering Company 1340 Francis Street Jackson, MI 49203
415C, S/N 113 thru 812; T.C. A-718	SA2185WE	Installation of main gear wheel fairings and/or nose gear wheel fairing (nose gear fork P/N 415-34096 required for latter installation). (These fairings eligible for installation separately or in conjunction.) Issued 6/9/70.	WE	47750	Kenney Engineering 4120 Via Solano Pales Verdes Estates, CA 90274
415C, S/N 113 thru 812; T.C. A-718	SA3293WE	Installation of McCauley 1B90CM7351 propeller on aircraft equipped with Continental C-75-12 engine. Issued 11/15/76.	WE	39820	Ronald T. Hagerman
(Erco) 415-C, 415-CD; T.C. A-718	SA3502WE	Installation of fiberglass nose bowl. Issued 10/7/77.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
415C, -CD, -D, -E, -G, F-1, F-1A; T.C. A-718, A-787	SA319WE	Metal cover of wings in accordance with Air Fab Drawing No. 104, Rev. No. 1. Reissued 7/29/71.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80010
415C, -CD, -D, -E, -G, F-1, F-1A; T.C. A-718, A-787	SA437WE	Installation of leading edge landing light in accordance with Air Fab Drawing No. 1011. Reissued 7/29/71.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80010
415C, 415CD, 415D, E, G; F-1, F-1A; A-2, A2-A, M10; T.C. A-718, A-787	SA2462WE	(1) Installation of main gear wheel fairings; (2) installation of nose gear wheel fairings. (These items eligible for installation separately or in conjunction with each other.) Issued 3/3/72.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
415D; T.C. A-787	SA5GL	Removal of fuselage fuel tank. Issued 10/3/72.	GL	28790	Norvel O. Dasher Route 1, Box 61 Elgin, IL 60120
415D; T.C. A787	SA381SO	Revised (1) brake handle per Drawing 9R, (2) seat belt anchor straps to seat per Drawing 10R, (3) rudder control system springs per Drawing 11R. Amended 3/14/68.	SO	68550	W.F. Robinson P.O. Box 241 Lanett, AL 36863
415D; T.C. A787	SA2628WE	Installation of Continental O-200-A engine, McCauley 1A101/DCM 6948 propeller, electric fuel transfer pump and associated changes. Amended 2/25/74.	WE	78624	Towns Aviation Service, Inc. 1800 West Deer Valley Road Phoenix, AZ 85027
415-D, E, G, (Erco) (Forney) F-1, F-1A; T.C. A-787	SA127GL	Install Cleveland Wheel and Brakes conversion kit, P/N 199-69. Issued 7/7/76.	GL	23250	Cleveland Wheels and Brakes Div. VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
415-D, E, G, F-1, F-1A; T.C. A-787	SA331GL	Install Skyport Model SMK-15, 9-cu.ft. baggage compartment. Issued 7/18/79.	GL	36566	Skyport Aircoupe Services Division Fox Engineering Company 1340 Francis Street Jackson, MI 49203
(Erco) 415-D, E, G, F-1, F-1A, A-2, A2-A, MI0; T.C. A-787 t+1	SA3503WE	Installation of fiberglass nose bowl.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
A-2; T.C. 787	SA1126WE	B2S autopilot.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
A-2; T.C. 787	SA1495WE	Installation of Brittain Model B2C flight control system.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
A-2, A2-A, M-10; T.C. A-787	SA2230WE	Installation of main gear wheel fairings on models equipped with "spring gear" main landing gear assemblies; also installation of nose gear wheel fairings. (These items eligible for installation separately or in conjunction with each other.) Amended 3/17/72.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
F-1, F-1A; T.C. 787	SA4-1590	Riveted fuel tanks changed to welded wing and nose tank assemblies and gauge from mechanical to electric float type.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

UNIVERSAL AIRCRAFT INDUSTRIES

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
GC-1 Series; T.C. 766	SA1512WE	Installation of gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
GC-1 Series; T.C. 766	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
GC-1A, GC-1B; T.C. 766	SA2-226	Windshield manufactured in accordance with Luminous Plastics. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
GC-1A, GC-1B; T.C. 766	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Blvd. Riverside, CA 92502
GC-1A, GC-1B; T.C. 766	SA4-403	GC 1-1 heavy duty "bubble" windshield. Reissued 6/4/73.	WE	07000	Aircraft Windshield Company 3842 Catalina Street Los Alamitos, CA 90720
GC-1A, GC-1B; T.C. 766	SA4-761	GC-1-3 heavy duty "bubble" windshield. REissued 6/4/73.	WE	0700	Aircraft Windshield Company 3842 Catalina Street Los Alamitos, CA 90720
GC-1A, GC-1B; T.C. 766	SA4-1200	Delco-Remy generator 1101879 and regulator 1118384.	RM	81060	Universal Aircraft Ind. P.O. Box 5306 Denver, CO 80217
GC-1A, GC-1B; T.C. 766	SA2GL	Installation of wheel and brake assemblies and axle spacer. Reissued 7/23/74.	GL	23250	Cleveland Wheels & Brakes Div. Van Sickle Ind., Inc. 1160 Avon Center Rd. Avon, OH 44011
GC-1A, GC-1B T.C. 766	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	5660	D. H. Matney d/b/a Matney's Acft. Ser. 24415 116th S. E. Kent, WA 98031
GC-1A, GC-1B; T.C. 766	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
GC-1A, GC-1B; T.C. 766	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
GC-1A, GC-1B: T.C. 766	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21328 Grace Ave. Torrance, CA 90510
GC-1A, -1B; T.C. A-766	SA2321WE	Installation of smooth skins with internal chordwise stringers for outboard wing panel in lieu of beaded skins. Issued 3/15/71.	WE	58630	Jess H. Meyers 8427 Lilienthal Ave. Los Angeles, CA 90045
GC-1A, -1B; T.C. A-766	SA2996SW	Brittain Model BSS stability augmentation system. Issued 5/16/79.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
GC-1A, -1B; T.C. A-766	SA3088SW-D	Mitchell automatic flight system AK564 cons. of Century I autopilot w/opt. omni tracker. Issued 12/3/75.	SW	6000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

UNIVERSAL AIRCRAFT INDUSTRIES 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
GC-1A, GC-1B; T.C. A-766	SA4011WE	Installation of extended length gear door fairings. Issued 8/24/79.	WE	51096	Charles F. Lischer, Jr. 1732 Ano Nuevo Diamond Bar, CA 91765
GC-1B; T.C. 766	SA1-326	Continential 0-300-A engine with McCauley 1A170-DM7359 propeller and Cessna AK7053-3 spinner.	EA	64500	Piedmont Aviation, Inc. Route 2, Woodrun Field Roanoke, VA 24001
GC-1B;	SA1-335	Sensenich 62-inch pitch propeller M74DR-1 on aircraft equipped with Continental C-145-2 engine.	EA	21100	Rudolph Chalow R.D. 1 Newfield, N.J. 08344
GC-1B; T.C. 766	SA3-267	Narco Omnigator with (VIR-1) transmitter-receiver unit and (V12 MP-2) power unit.	CE	16858	Delmar G. Blodgett 3 Pan Drive St. Charles, MO. 63301
GC-1B; T.C. 766	SA4-145	Continental C-145-2, 0-300-A, or -B engine & Universal F200/0073-E, F200-H/0073-E, or McCauley 1A170DM/7361 propeller. Amended 9/24/75.	WE	16860	M. E. Bodell 23804 Pennsylvania Ave. Torrance, CA 90501
GC-1B; T.C. 766	SA4-156	Slightly modified Bonanza wing tips.	WE	16860	M. E. Bodell 23804 Pennsylvania Ave. Torrance, CA 90501
GC-1B; T.C. 766	SA4-157	Relocation of trim control handle to left side of fuselage about 9 inches below window & about 9 inches to rear of instrument panel.	WE	16860	M. E. Bodell 23804 Pennsylvania Ave. Torrance, CA 90501
GC-1B; T.C. 766	SA4-395	Fiberglas wing tips.	WE	79955	Wendell Willard Tweed 5726 Buffalo Ave. Van Nuys, CA 91408
GC-1B; T.C. 766	SA53NW	Installation of Continental IO-360-C engine with McCauley propeller. Issued 6/20/73.	NW	52625	MACHen, Inc. Box 412 Spokane, WA 99211
GC-1B; T.C. 766	SA60WE	Continental 0-300-A engine.	WE	81790	Vaeth Aircraft Repair 13th and Benson Streets Upland, CA 91786
GC-1B; T.C. 766	SA68SO	Down-draft cowling and baffles. Amended 11/22/78.	WE	77127	Swift Alturair 1780 Joe Crosson Drive El Cajon, CA 92026
GC-1B; T.C. 766	SA124CE	Rear seat and/or instrument panel.	CE	76615	Charles L. Stutesman Wheeler Rd., Route 31 Kansas City, MO 64108
GC-1B; T.C. 766	SA149CE	Relocation of battery and removal of tail ballast.	GL	16857	Ernest R. Blatchley 132 Seminole Dr. West Lafayette, IN 47906
GC-1B; T.C. 766	SA167NW	Installation of access door aft of luggage compartment. Issued 3/25/75.	NW	52625	MACHen, Inc. South 3410 Davidson Blvd. Spokane, WA 99204
GC-1B; T.C. 766	SA169NW	Installation of modifield Bosch 4 pole electric motor & adapter plate as a replacement drive motor to the hydraulic system. Issued 3/28/75.	NW	52625	MACHen, Inc. South 3410 Davidson Blvd. Spokane, WA 99204
GC-1B; T.C. 766	SA203NW	Installation of Franklin 6A-350-C1 engine and McCauley 2A34C22/SF84-10 propeller. Issued 9/16/75.	NW	52625	MACHen, Inc. South 3410 Davidson Boulevard Spokane, WA 99204
GC-1B; T.C. 766	SA255SO	Auxiliary fuel tanks. Reissued 6/73.	WE	77130	Swift Tech Co. P.O. Box "P" Santee, CA 92071
GC-1B; T.C. A-766	SA275NW	Installation of Continental IO-360-D engine and McCauley D2A34C67/76C-2 propeller.	NW	52625	MACHen, Inc. South 3410 Davidson Boulevard Spokane, WA 99204
GC-1B; T.C. 766	SA313WE	Dowty Equipment Co. hand pump.	WE	67115	Rendco 1021 W. Holguin Lancaster, CA 93534
GC-1B; T.C. 766	SA345SO	Electric fuel pump Piper P/N 48-666; cockpit hatch & side glasses with fiberglas canopy. Reissued 3/1/73.	EA	49220	Paul B. Lacy III Route 1 Covington, VA 24426

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
GC-1B; T.C. 766	SA382NW	Installation of Continental 145 engine, and gross weight increase to 1835 lbs. Issued 12/18/76.	NW	52625	MACHen, Inc. South 3410 Davidson Boulevard Spokane, WA 99204
GC-1B; T.C. 766	SA389NW	Installation of Continental IO-360-D engine and McCauley D2A34C67/76C-2 propeller and a gross weight increase. Issued 12/28/77.	NW	52625	MACHen, Inc. South 3410 Davidson Boulevard Spokane, WA 99204
GC-1B; T.C. A-766	SA563NW	Install swift alturair rudder cap. Issued 1/31/78.	NW	52625	Machen, Inc. S.3608 Davison Boulevard Spokane, WA 99204
GC-1B; T.C. 766	SA803SO	Installation of Lycoming 0-360-A1A engine equipped with a McCauley Model 2D34C53-A/74E-0. Issued 8/30/74.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602 Miami, FL 33148
GC-1B; T.C. 766	SA2358WE	Installation of fiberglas wing tips. Issued 5/26/71.	WE	77130	Swift Tech Co. 503 Murray Drive El Cajon, CA 92020
GC-1B; T.C. A-766	SA4061WE	Installation of dual control sticks. Issued 11/20/79.	WE	51096	Charles F. Lischer, Jr. 1732 Ano Nuevo Diamond Bar, CA 91765

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

UNIVERSAL MOULDED PRODUCTS CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
125; T.C. 359	SA4-580	Fiberglas covering on fuselage and horizontal and vertical stabilizers.	WE	38060	Glasco-Air Products Oxnard-Ventura Airport Oxnard, CA 93030

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

VARGA AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
2150; T.C. 4A19	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Co. 12201 West 78th St. Eden Prairie, MN 55343

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

VICKERS-ARMSTRONGS (AIRCRAFT), LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
700 Series; T.C. 814	SA1-241	U.S. Rubber Co. fuel cells of US-566R construction, P/N's FCR 38507 through FCR 38526.	EA	80500	United Air Lines, Inc. National Airport Washington, D.C. 20090
700 Series; T.C. 814	SA1-411	Goodyear SK306-1204 revision E propeller blade iceguard on Rotol propeller R130/4-20-4/12E with blades RA25842.	EA	80500	United Air Lines, Inc. National Airport Washington, D.C. 20090
700 Series; T.C. 814	SA4-357	Two Aircraft Radio Corp. ADF loops and sense antenna masts and lead-in insulators.	WE	15125	Bayaire Avionics, Inc. P.O. Box 2301 Int'l. Airport Oakland, CA 94614
700 Series; T.C. 814	SA83EA	Distance measuring equipment. (Applicable to aircraft which have incorporated Vickers-Armstrong Modification D.1236.)	EA	80500	United Air Lines, Inc. National Airport Washington, D.C. 20090
700 Series; T.C. 814	SA261EA	New cabin-to-cockpit door.	EA	80500	United Air Lines, Inc. National Airport Washington, D.C. 20090
700 Series; T.C. 814	SA320EA	Carbon dioxide fire extinguishers.	EA	80500	United Air Lines, Inc. National Airport Washington, D.C. 20090
700 Series; T.C. 814	SA328EA	Gables navigation warning system G1340C.	EA	80500	United Air Lines, Inc. National Airport Washington, D.C. 20090
700 Series; T.C. 814	SA376SW	Interior modification. Reissued 4/73.	SW	84600	Ward International Aircraft Serv., Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
700 Series; T.C. 814	SA407SW	Aural overspeed warning system HF-100VM.	SW	40000	The Hamilton Co. 106 Neuhaus St. Houston, TX 77002
700 Series; T.C. 814	SA416SW	Interior modification. Reissued 4/73.	SW	84600	Ward International Aircraft Serv., Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
700 Series; T.C. 814	SA657WE	AiResearch GTP30-54 auxiliary turbine power unit for ground operation only.	WE	65750	Qualitron-Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
700 Series; T.C. 814	SA661WE	Fuselage fuel tank, 755 gallon.	WE	06750	Aircraft Tank Service 10201 Cohasset Burbank, CA 91504
700, 800 Series; T.C. 814	SA356EA	Cockpit voice recorder. Amended 6/15/67.	EA	80500	United Air Lines, Inc. National Airport Washington, D.C. 20090
700, 800 Series; T.C. 814	SA905WE	Flexible hose assembly.	WE	67250	Resistoflex Corp. 301 N. Crescent Way Anaheim, CA 92803
744, 745D; T.C. A-814	SA863EA	Incorporation of DME Corp. emergency slide lighting system ESL-1, ESL-6 or ESL-6-1. Reissued 10/20/76.	SO	30200	DME Corporation 1631 S. Old Dixie Highway Building E Pompano Beach FL 33060
745D; T.C. A-814	SA1-571	Installation of flight data recorder. Amended 3/10/67.	EA	80500	United Air Lines, Inc. National Airport Hangar No. 4 Washington, D.C. 20001
745D, 810; T.C. A-814	SA192CE	Suppl. Model A high intensity wing tip lights, Model C tail light, with or without Model 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Ave. Irvine, CA 92705
745D, 810; T.C. A-814	SA302WE	Incorporation of Napier Spraymat de-icing (as mfg. by applicant) externally on Rotol propeller spinner as an alternate to Dowty Rotol internal elements. Reissued 10/22/70.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660

VICKERS-ARMSTRONGS (AIRCRAFT), LTD. 2

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
800 Series; T.C. 814	SA-1394	Doppler navigation antenna.	WE	07500	AiResearch Aivation Service Co. 6201 W. Imperial Hwy. Los Angeles, CA 90045
800 Series; T.C. 814	SA4-1395	Modification of interior.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Hwy. Los Angeles, CA 90045
800 Series; T.C. 814	SA-1506	Flight Recorder 109C.	WE	52010	Lockheed A/C Service, Inc. P.O. Box 33 Int'l. Airport Ontario, CA 91761
800 Series; T.C. 814	SA379SW	HF-V overspeed warning system.	SW	4000	The Hamilton Co. 106 Newhaus St. Houston, TX 77002
800 Series; T.C. 814	SA592WE	Mach warning system.	WE	25970	Continental Air Lines Inc. Int'l. Airport Los Angeles, CA 90009

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

WACC AIRCRAFT COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
UPF-7, VPF-7, ARE, HRE, SRE; T.C. 642, 714	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
ARE, HRE, SRE: T.C. 714	SA4-1212	Eonite covering on elevators, rudder and vertical stabilizer.	WE	52090	William C. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
EGC-8; T.C. 665	SA317CE	Remove left or right or both cabin doors.	CE	75116	Joseph B. Stevinson 5905 Locust St. Kansas City, MO 64110
RNF; T.C. 311	SA4-1289	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
RNF; UBF; UPF-7, VPF-7; UEC, UIC, YKS-7, ZKS-7; ATC 311, 473, T.C. 642, 626	SA1352WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
RNF, UBF, UEC, UIC, VPF-7, ZKS-7; ATC 311, 473, 467, 499, T.C. 642, 626	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/76	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
UBF; T.C. 473	SA628WE	Ceconite 101 covering of entire airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
UEC, UIC, YKS-7, ZKS-7; T.C. 467, 499, 626	SA4-1053	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
UPF-7, VPF-7; T.C. 642	SA4-1567	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
UPF-7, VPF-7, ASO; T.C. 642, ATC 41	SA1008WE	Installation of Poly-Fiber covering material (complete aircraft). Amended 8/21/79.	WE	75250	Stits Aircraft Corp. P.O. Box 3084 Riverside, CA 92509
YKS-7; T.C. 626	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglas cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

F.H. WAGNER

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50-C, 65-C, 65-CA, S-50-C, S-65-C, S-65-CA, KCA; T.C. 675	SA4-288	BN-1 propeller spinner.	WE	75250	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
50L; T.C. 702	SA4-1572	Application of glass cloth to fuselage, wings, horizontal and vertical stabilizer.	WE	38060	Glasco-Air Products 13703 Woodcock Avenue San Fernando, CA 91340
50, 65; T.C. A-702	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
50-L, -LA, 65-LA, -LB; T.C. 702	SA1301WE	Ceconite 101 covering of entire airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
(Aeronca, Trytek) 50-L, -LA, 65-LA, -LB, 65-C, -CA, KCA, S-65-C, S-65-CA; T.C. 702, 675	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
65-C-CA, S-65-C, KCA, S-65-CA; T.C. 675	SA1351WE	Replace existing fabric on wings fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S-65-CA; T.C. 675	SA1-150	Continental C-85-8 engine, Sensenich 75GK-50 propeller, and Harrison HE431-9 engine oil cooler.	EA	61622	North American Flying Service Ludwig Hasibeck Little Ferry, NJ 07643
65-CA; T.C. 675	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
65-C; T.C. 675	SA1-583	Continental A-65-8 engine and Sensenich 72GK42 propeller.	EA	61795	A.H. Oldfield 308 West Main Street Waterloo, NY 13165
65-C, 65-CA, S-65-C, S-65-CA, KCA; T.C. 675	SA4-1298	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

WEATHERLY AVIATION COMPANY, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
201B, 201C; T.C. A10WE	SA73RM	Installation of Harzell HC-B3 (2, P,R or W) 30-1 hubs with corresponding Hartzell 10160-6, 10152-5 1/2 or 10152-7 1/2 prop. blades. Issued 5/7/76.	RM	69136	Ron's Air Service, Inc. Box 12 Two buttes, CO 81084
201B, 201C; T.C. A10WE	SA330NW	Installation of automatic flagman Issued 10/20/76	NW	03500	Air Ag, Inc. City-County Airport Walla Walla, WA 99362

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

WING AIRCRAFT COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D-1; T.C. A9WE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Co. 12001 West 79th St. Eden Prairie, MN 55343
D-1; T.C. A9WE	SA1688WE	Installation of Brittain Industries Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

ENGINES

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

AIRESEARCH MANUFACTURING COMPANY OF ARIZONA

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
TPE 331-6-251M; T.C. E4WE	SE68WE	Deletion of fireshield installation kit. Issued 1/21/75.	WE	10360	American Turbine Engine Company 1150 Busch Garden Court Pasadena, CA 93662
TFE 731-2, 731-3; T.C. E6WE	SE1040EA	Installation of hydraulically actuated target type thrust thrust reverser system. Amended 7/11/78.	EA	39540	Grumman Aerospace Corporation Bethpage, L.I., NY 11714

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

AVCO CORPORATION, LYCOMING DIVISION

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
O-145, O-235, O-350, O-435, GO-435, O-290, O-320, O-340, VO-435, O-360, HO-360-A1A, VO-360, TO-360, LTO-360, VO-540-B & C, TVO-540-A1A, O-540 Series; T.C. 199, 210, 233, 227, 228, 229, 274, 277, 279, 286, 295, 1E1, E26EA, 304, 1E14	SE1-201	Installation of Richter B-4 or B-5 probes in Marvel-Schebler MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6, MA-9 and Bendix NA-S3B and NA-S3A1 carburetors. Amended 9/20/77.	EA	68000	Richter Aero Equipment, Inc. Essex, NY 12936
O-145-A; O-145-B, -C, GO-145; O-233-A1; O-235; O-290; O-320; IO-320; O-340; O-350; O-360, HO-360; IO-360; VO-360; O-435-1, -4, -5, -11, -13, O-435-2, GO-435, -6, -17; GSO-435, -B, -B2; VO-435, -21-23; TVO-435; GO-480; TSO-480-1, IGSO-480, -2; O-540; IO-540; IGO-540; IGSO-540; VO-540; TVO-540; GSO-580; SO-580, VSO-580; IO-720-A1a; T.C. 199, 210, 223, 229, 274, 1E12, 277, 227, 286, 1E10, 1E1, 228, 276, 279, 1E13, 275, 284, 295, 1E4, 1E11, 1E7, 304, 1E14, 256, 285, 1E15	SE44WE	Use of Kling Aviation Oil, Specifications KL-100, KL-200 and KL-300 in Continental and Lycoming engines.	WE	48530	Kling Oil Company 1492 Oddstad Drive Redwood City, CA 94063
O-235-L2C; T.C. E-223	SE792NW	Modification of engine to increase HP rating from 115 HP at 2700 rpm to a continuous 125 HP at 2800 rpm. Issued 6/28/79.	NW	16351	Ken Blackman 7305 97th Avenue, S.E. Snokomish, WA 98290
O-235, O-290, O-320 Series; T.C. 223, 229, 274	SE5CE	Prestolite ALK-5001 alternator.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
O-235, O-290, O-320, O-540, O-360 Series; T.C. E-233, E-229, E-274, E-295, E-286 w/Marvel-Schebler MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6	SE208SO	Installation of ice indicator in the carburetor.	SO	71545	Charles E. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
O-320 Series; T.C. 274	SE2-7	Carburetor air temperature bulb in Marvel-Schebler MA-4-5 carburetor.	GL	53125	Lynn McElroy Westervelt, IL 62574
O-320 Series; T.C. 274	SE508AL	Addition of crankcase release valve. Issued 11/12/73.	AL	75500	Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
O-320 or O-320-A1A; T.C. 274	SE2392SW	Conversion to fuel injection configuration equivalent IO-320-E2A. Issued 12/10/76.	SW	77124	Swick Aircraft Corporation Route 3, Box 163B Lewisville, TX 75067
O-320-A, -B; T.C. 274	SE4-1638	Installation of one Rajay Turbocharger. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
O-320-A2B, -A2D, -E2A, -E2B, -2C, -E2D, -E2G, -E2D: T.C. E-274	SE1226CE	Modify engines for a 160 horsepower rating on 100/130 minimum grade fuel. Amended March 1977.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
IO-320-A1A, -B1A, -B1B, -C1A: LIO-320-B1A, -C1A: T.C. 1E12	SE14WE	Installation of one Rajay Turbocharger P/N RJ 0325, RJ 0326, RJ 0326-1 or RJ 0326-2. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
IO-320-E2A, IO-320-E2B, IO-320-E1A; T.C. 1E12	SE7CE	Modification of oil sump in accordance with Champion Drawing No. 7-1312E. Amended 7/18/75.	GL	15405	Bellanca Aircraft Corporation Box 624, Municipal Airport Alexandria, MN 56308
O-360-A1A T.C. E-286	SE2887SW	Install Bendix PS-5C carburetor. Issued 12/14/78.	SW	77124	Swick Aircraft Route 3, Box 163B Lewisville, TX 75067
O-360-A1A, -A1D; T.C. 286	SE154SO	Installation of one Rajay Turbo-supercharger Model RJ 0325, RJ 0326, RJ 0326-1 or RJ 0326-2 Amended 2/20/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
HO-360; T.C. 286	SE30WE	Conversion to Lycoming HIO-360-B1B engines.	WE	62080	Pacific Airmotive Corporation 3411 Tulare Avenue Burbank, CA 91502
HIO-360-E1AD; T.C. 1E10	SE100GL	Installation of Rajay 301E10-2 turbocharger. Issued 12/5/75.	GL	33475	Enstrom Helicopter Corporation P.O. Box 277 Menominee, MI 49858
IO-360-A1A, A1B, A1C, A2A, A2B, A2C, B1A, B1B, B1C, B1D, B1E, B1F, B2E, B2F, B4A, C1E6, C1A, C1B, C1C, D1A, E1A, AIO-360-A1A, A1B, A2A, A2B, B1B, LIO-360-C1E6; T.C. 1E10	SE32WE	Installation of one turbosuper-charger, Rajay turbocharger, P/N RJ 0325, RJ 0326, RJ 0326-1, RJ 032602 and RJ 0329. Amended 3/31/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
IO-360-A1D6D, IO-360-A3D6D; T.C. 1E10	SE90WE	Installation of Rajay Turbochargers Model 325E10-1, P/N RJ0331-1, on Lycoming engine models listed. Issued 12/22/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
GO-435-C2, -C2A, -C2B, -C2B1, C2B6; T.C. 288	SE579SO	Installation of Bendix magneto models S6LN-20 and S6LN-21. Issued 2/21/74.	SC	53790	Mack's Aircraft Engine Service P.O. Box 336 Wetumpka, AL 36092
VO-435 Series; T.C. 279	SE2-856	American Bosch Induction vibrator VJR24B56X.	SW	15350	Bell Helicopter Corporation P.O. Box 482 Fort Worth, TX 76101
VO-435-A1E, -A1F; T.C. E-279	SE959EA	Modification to higher compression ration. Reissued 3/16/76.	EA	03300	Agrotors, INC. Box 576 Gettysburg, PA 17325
VO-435-A1E, -A1F; T.C. 279	SE2733SW	Modification to higher compression ratio. Issued 3/21/78.	SW	26000	Continental Copters, Inc. P.O. Box 13284 Fort Worth, TX 76118
VO-435-A1F; T.C. E-279	SE144GL	Modify engine to increase compression ratio to 8.7:1. Amended 2/17/77.	GL	49320	Lake Line Helicopters, Inc. 13601 Pioneer Trail Eden Prairie, MN 55343
GO-480 Series; T.C. 275	SE124SO	Two Rajay turbochargers 315A10. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
GO-480 Series; T.C. 275	SE135SO	Two Rajay turbochargers 315A10. Reissued 1/14/69.	WE	66250	Rajay Industries 2602 E. Wardlow Road Long Beach, CA 90807
GO-480-B1B, -C266, F4B6, -F6, -F3B6; T.C. E275	SE580SO	Installation of Bendix magneto models S6LN-20 and S6LN-21. Issued 2/21/74.	SC	53790	Mack's Aircraft Engine Service P.O. Box 336 Watumpka, AL 36092
GO-480-F2D6; T.C. E-275	SE18WE	Installation of AiResearch T-1112 turbosupercharger. Reissued 4/27/70.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
O-540 Series; T.C. 295	SE17WE	Turbosupercharger 406330.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
O-540 Series; T.C. 295	SE40WE	Installation of two Rajay Turbo-chargers. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
IO-540 Series; T.C. 1E4	SE21WE	Turbosupercharger 40661O-2.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
IO-540 Series; T.C. 1E4	SE22WE	Turbosupercharger 40661O-2.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
IO-540-A1A5; T.C. 1E4	SE201SO	Modification of engine oil dip stick to provide 10.5 quart useable oil capacity in lieu of 9.25 quart capacity.	SW	68145	Riley International Corporation 6211 W. Northwest Highway Dallas, TX 75225
IO-540-A1A5, B1A5, B1B5, B1C5, C1B5, C1C5, C2C, C4B5, C4C5, C2C, C4B5, C4C5, E1A5, E1B5, G1A5, G1B5, G1C5, G1D5, G1E5, J4A5, K1A5, K1B5, L1A5, M1A5, P1A5, K1C5; K1F5, S1A5, K1E5; T.C. 1E4	SE6WE	Installation of two Rajay turbochargers P/N 0080-100, or -102. Amended 10/7/74.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
IO-540-A1A5, B1A5, B1B5, B1C5, E1A5, E1B5, E1C5, G1A5, G1B5, G1C5, G1D5, G1E5, P1A5, G1F5, S1A5; T.C. 1E4	SE60WE	Installation of two Rajay turbochargers P/N RJ 0327-1 or -2 and and 9 lb. ± 1 sonic nozzle. Amended 9/19/73.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
IO-540-K1G5D; T.C. 1E4	SE85WE	Installation of two Rajay turbochargers Model 315F10-2, P/N RJ 0080-102, on Lycoming engine. Issued 11/8/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
IO-540-S1A5 T.C. 1E4	SE81WE	Installation of two Rajay turbochargers, Model 325EF80, P/N 0330-1 and -2, and 9 lb. ± 1 lb. sonic nozzle on Lycoming engine Model IO-540-S1A5. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
R-680-D6 (89-2000); T.C. 173	SA291SW	Revised cover plates.	SW	05752	Aircraft Parts 6037 Cameron Boulevard New Orleans, LA 64822
IO-720-A1A; T.C. 1E15	SE163SO	Two Rajay turbochargers 325E10.	SW	68145	Riley International Corporation 6211 W. Northwest Highway Dallas, TX 75225
IO-720-A1A; T.C. 1E15	SE205SO	Two Rajay turbochargers 325H10.	SW	68145	Riley International Corporation 6211 W. Northwest Highway Dallas, Texas 75225
t+1 IO-720-A1A, -A1B; T.C. 1E15	SE51WE	Installation of two (2) Rajay P/N RJ0326, RJ0326-1 or RJ0326-2 (or any combination thereof) turbochargers on Avco Lycoming Model IO-720-A1A and IO-720-A1B engines. Amended 1/18/74.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90801
IO-720-A1A, -A1B; T.C. 1E15	SE63WE	Installation of starter ring gear support assembly. Issued 12/12/73.	WE	01390	Neil J. Adler 2870 Sugarman Court La Jolla, CA 92037
IO-720-B1B; T.C. 1E15	SE62WE	Installation of two Rajay turbochargers, P/N RJ 0326 cr -1 or -2. Amended 8/19/75.	WE	69220	Mr. RPM Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

DETROIT DIESEL ALLISON DIVISION
GENERAL MOTORS CORPORATION

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
250-C20, -C20B; T.C. E4CE	SE769NW	Modification of fuel and pneumatic system on Bendix controlled Allison engines. Issued 7/26/79.	NW	73721	Soloy Conversions P.O. Box 60 Chehalis, WA 98532
501-D13D, H; T.C. E-282	SE1161EA	Manufacture of magnetic plugs with self-closing valve. Issued 7/26/79.	EA	77590	Technical Development Corp. 24 East Glenolden Avenue Glenolden, PA 19036

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

FAIRCHILD ENGINE DIVISION
FAIRCHILD ENGINE & AIRPLANE CORPORATION

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Ranger 6-440-C5; T.C. 216	SE1-201	Installation of Richter B4 or B5 probes in Marvel-Schebler carburetors MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6, HA-6 Series and Bendix NA-S3B and NA-S3A1. Amended 9/20/77.	EA	68000	Richter Aero Equipment, Inc. Essex, NY 12936
Ranger 6-440-C5; T.C. E-216	SE519AL	Installation of Ramsey Corporation piston rings. Issued 4/30/74.	AL	05958	Aircraft Rebuilders. Inc. P.O. Box 3567 Anchorage, AK 99501

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

FRANKLIN ENGINE COMPANY

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
4AC, 6AC, 6AL, 6AG4, 6VS, 4A, 6V, 6A, 6AS, 2A, 6A4, 6A8, 6V4 Series; T.C. 238, 242, 244, 194, 206, 225, 234, 1E2, E6EA, E9EA, E18EA, E24EA	SE1-201	Installation of Richter B-4 or B-5 probes in Marvel-Schebler carburetors MA-2, -3, -4, and -4-5, MA-6, HA-6 and Bendix NA-S3B and NA-S3A1. Amended 9/20/77.	EA	68000	Richter Aero Equipment Essex, NY 12936
6A4 Series; T.C. 238	SE4-1192	Adapter to permit Bendix Scintilla magneto installation, Type SF6LN-8, and modification of carburetor-manifold adapter box.	WE	82370	Van De Water Development Company 24832B Norbonne Avenue Lomita, CA 90717
6A-350; T.C. 9EA	SE208SO	Installation of ice indicator in carburetor.	SC	71545	Charles B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
6A-350; T.C. 9EA	SE634SO	Installation external oil supply routing and vent system to permit maintaining oil pressure in inverted position.	SC	28770	John J. D'Arcy 13740 S.W. 79th Court Miami, Fl 33158
6A-350-C1, -C1A, -C2; T.C. E9EA	SE78WE	Install two locking pins in Franklin Part Number 21014J oil transfer collar, 180 degrees apart, to prevent rotation of oil seal in collar. Issued 8/11/76.	WE	90065	Yehnert Helicopter 1049 Airport Drive Upland, CA 91786

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
ENGINE
GENERAL ELECTRIC COMPANY AIRCRAFT ENGINE GROUP

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
CJ610-1, -4, -5, -6; T.C. 1E16	SE6CE	Installation of slotted disc magnetic pickup on overspeed fuel control. Amended 9/22/70.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
CJ610, CF700; T.C. 1E16, E7EA	SE1057SO	Installation of capacitance type probe with oil quantity indicating system in oil tank. Issued 3/23/79.	SC	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
CJ610-1, -2, -3, -4, -5, -6, -7, -8, -9, CF700-2C, -2D, -2D-2; T.C. 1E16, E7EA	SE949SO	Installation of an oil level sight gauge. Issued 8/12/77.	SC	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 28118
CJ610, CJ700; T.C. 1E16, E7EA	SE976SO	Installation of an oil tank sight gauge on a G.E. oil tank, P/N 6003T09P04. Issued 4/13/78.	SC	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
CF6-6D, -6D1, -50A, -50C, -50C1, -50D, -50H; T.C. E23EA	SE91WE	Removal of General Electric "EGT cable and conduit assembly," P/N 9037M17P03 or 9037M17P04, and replacement with Co-Operative Industries P/N 66615. Issued 8/1/78.	WE	52995	McDonnell Douglas Corp. 3855 Lakewood Boulevard Long Beach, CA 90846
CF700-2C, -2D, -2D-2; T.C. E7EA	SE996SO	Manufacture and installation of axis "C" gearshaft plugs. Issued 12/23/77.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis International Airport Memphis, TN 38130

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

GLADDEN PRODUCTS CORPORATION

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
R-55, R-56; T.C. 153	SE53WE	Modify Kinner R-55 and R-56 to incorporate Component Air, Inc., rocker arm axle kit, CAI-46009 to provide external rocker arm lubrication fittings. Issued 7/3/72.	WE	25700	Component Air, Inc. P.O. Box 946 Santa Paula, CA 93060

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

PAGE INDUSTRIES OF OKLAHOMA, INC.

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
R-755 Series; T.C. 237	SE639SW	Continental W-670 link rods.	SW	05084	Aircraft ENGINE Service, Inc. 5414 North Rockwell Avenue Bethany, OK 73008

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

PRATT & WHITNEY AIRCRAFT

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE1-391	Pratt & Whitney R-985 engine and ATI fuel injection.	SC	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Fort Lauderdale, FL 33315
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE3-612	Beech fuel injection system with Bendix RS-10DD-1 regulator.	CE	15250	Beech Aircraft Corporation 9709 East Central Wichita, KS 67206
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE4-864	Increase in impeller drive ratio from 10:1 to 12:1. Reissued 5/25/73.	SC	34120	Export Airmotive, Inc. 4471 Northwest 36th Street Miami, FL 33166
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE4-1136	Fuel injection system.	GL	15500	The Bendix Corporation 401 Bendix Drive South Bend, IN 46600
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE4-1268	3-200 fuel injection unit incorporating Bendix RS-10B2 servo-regulator and 367605 nozzle assembly.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE7WE	Replace Pratt & Whitney engine adapter 16487 and Bendix body adapter 2642-727.	NW	46400	Jobmaster Company 1016 First Avenue, South Seattle, WA 98055
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE10WE	Bendix fuel injection system, RS-10B2.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SEW-11	Manufacture of piston pin A-56009, and piston pin and plug assembly.	WE	37005	Fresno Airmotive Company Chandler Field Fresno, CA 93721
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE11WE	Bendix fuel injection system, RS 10B2.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE27WE	Two Bendix-Stromberg PS-5C carburetors.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE31WE	Piston rings 251822, 251824, and 251825 on Pratt & Whitney R-985 piston 27056.	WE	23219	Electro-Coatings, Inc. 1401 Park Avenue Emeryville, CA 94608
R-985 Series; T.C. 5E-1	SE178RM	Increase fuel pump and vacuum pump accessory pod maximum overhang moments to 150 in.lbs. each. Issued 7/9/79.	RM	32300	Dale Edlund Edlund Engineering Logan Field Billings, MT 59102
Wasp Jr., R-985 Series; T.C. 123, 5E-1	SE297SW	Modification of exhaust valve 71166.	SW	70617	Seale Aviation Supply Co., Inc. 3110 Love Field Drive Dallas, TX 75235
Wasp Jr., R-985 Series; T.C. 123, 5E1	SE483SW	Modification to R-985 cam assembly and cam drive gears.	SW	74125	Spartan Aircraft Company Aviation Service Division Municipal Airport Tulsa, OK 74115
Wasp Jr., R-985 Series; T.C. 123, 5E1	SE563SW	R-985 cylinders modified to accept R-1830 Series rocker shaft bushings and R-1830 rocker shaft.	SW	74125	Spartan Aircraft Company Aviation Service Division International Airport Tulsa, OK 74115
R-985 Series engines utilizing Bendix NA-R9C2 carburetors; T.C. 5E-1	SE825SO	Replacement of brass carburetor float P/K P-13770 with Bendix plastic float P/N 2538554. Issued 3/11/75.	SC	65038	Precision Air, Inc. 3610 Northwest 41st Street Miami, FL 33142
Wasp Jr. B-4, B-5, S1H1, S1H2, S3H1, S3H1-G, R-985, R-1340; T.C. 123, 291, 143, 142, 5E-1, 5E-2	SE741SW	R-1830 rockershaft assemblies.	SW	73890	Southwest Airmotive Company 7515 Lemmon Avenue Dallas, TX 75221
B-5; T.C. 123	SE1210SW	Bronze bushings. Issued 10/30/70.	SW	05084	Aircraft Engine Service, Inc. 5414 North Rockwell Avenue Bethany, OK 73008

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S1H2, S3H1, S3H2, R-1340 Series; T.C. 129, 143, 5E-2	SE41N	Increase in compression ratio to 6.75:1, substitution of 12:1 impeller ratio and other modifications to R-1340 engines, equivalent to S1H2, S3H1 and S3H2 (not equipped with reduction gear).	EU	27235	C.R.M.A. 6, Rue Marceau Issy-les-Moulineaux Seine, France
R-1340 Series; T.C. 5E-2	SE179RM	Increase fuel pump and vacuum pump accessory pod maximum overhang moments to 150 in.lbs. each. Issued 7/9/79.	RM	32[illegible]00	Dale Edlund Edlund Engineering Logan Field Billings, MT 59102
R-1340-AN-1, S1H1, S3H1; T.C. 109, 143, 5E-2	SE966EA	Modification of Bendix Model NAY9E1 carburetor for use with 1 p.s.i. fuel inlet pressure. Issued 10/11/73.	GL	39542	Grumman American Aviation Corp. 318 Bishop Road Cleveland, OH 44143
R-1340-AN1, -AN2; T.C. 5E-2	SE48WE	Modification of thrust bearing cover P/N 37970 to incorporate National Seal P/N 55831. Amended 12/31/69.	WE	01808	Aero-Engines, Inc. 3033 Coolidge Avenue Los Angeles, CA 90039
Twin Wasp S1C3-G; T.C. 186	SE157EA	Modification of AS-5999 to incorporate the use of flat sides.	EA	06500	Aircraft Supplies 44 Park Avenue Nutley, NJ 07110
Twin Wasp, R-1830 Ser.; T.C. 186, 5E4	SEW-5	Ni-resist valve guide LGL 4700.	SW	61205	National Aircraft Sales,Inc. 2425 Burbank Street Dallas, TX 75221
Twin Wasp C, R-1830, Double Wasp CA, CB, R-2800 Series; T.C. 186, 5E-4, 231, 5E-8	SEW-8	Modification to push rod housing assemblies.	SW	61205	National Aircraft Sales, Inc. 2425 Burbank Street Dallas, TX 75221
R-1830 Series; T.C. 5E-4	SE3-1	Installation of fuel flow meter, Bendix Model 9054-5A. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
R-1830 Series; T.C. 5E-4	SE3-566	Oil transfer bearing seal, P/N SK-110341. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
R-1830; T.C. 5E-4	SE54SO	Rework of R-1830-94 crankcase sections 82862, 91667 and 91845 for R-1830-92 engines.	SO	04400	Air Carrier Engine Service, Inc. International Airport Miami, FL 33101
R-1830; T.C. 5E-4	SE217SW	Conversion of crankcase 82862 to R-1830-92 configuration.	SW	61205	National Aircraft Sales, Inc. 2425 Burbank Street Dallas, TX 75221
R-1830-R-2000 Series; T.C. 5E-4, 5E-5	SE300SW	Conversion of Pratt & Whitney gear 47669 or gear 96669 to LHL88738.	SW	61205	National Aircraft Sales, Inc. 2425 Burbank Street Dallas, TX 75221
R-1830, R-2000; T.C. 5E-4, 5E-5	SE381SW	3001-3 bushing.	SW	05084	Aircraft Engine Service 5414 North Rockwell Avenue Bethany, OK 73008
R-1830-92; T.C. 5E-4	SE694SW	R-1830-94 crankcase sections. Reissued January 1973.	SW	62196	Page Industries of Oklahoma, Inc. P.O. Box 191 Yukon, OK 73099
R-1830, R-2000, Twin Wasp 25D Series; T.C. 5E-4, 5E-5, 230	SE1-344	Redesigned propeller shaft oil transfer pipe seals.	EA	08375	Airwork Corporation Municipal Airport Millville, NJ 08332
R-2000 Series; T.C. 5E-5	SE4-944	Modification of Pratt & Whitney 18394 pinion assembly to the equivalent of Pratt & Whitney 57612 designated as Wasmuth W-1.	WE	84630	The Wasmuth Company 7331 Varna Building 10 North Hollywood, CA 91603
R-2000 Series; T.C. 5E-5	SEW-6	Modification of Pratt & Whitney 47669 and 96669 gear assemblies to the equivalent of Pratt & Whitney 88738 designates as Wasmuth W-2.	WE	84630	The Wasmuth Company 7331 Varna Building 10 North Hollywood, CA 91603
Double Wasp CA, Double Wasp CB, R-2800 Series; T.C. 231, 264, 5E-8	SEW-3	Modification of crankshafts and reidentification according to their respective counterweight dampers.	SW	61205	National Aircraft Sales, Inc. 2425 Burbank Street Dallas, TX 75221
Double Wasp CB; T.C. E264	SE904EA	Installation of ignition harness parts numbers as alternate parts. Issued 3/30/72.	SW	26250	Co-Operative Industries, Inc. 100 Oakdale Road Chester, NJ 07930
Double Wasp CB, R-2800 Series; T.C. 264, 5E-8	SE32SW	Oil pump housing.	SW	61205	National Aircraft Sales, Inc. 2425 Burbank Street Dallas, TX 75221

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Turbo Wasp JT3C Series; T.C. 290	SE2CE	Transducer in-flight maintenance and performance recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
JT3C; T.C. 290	SE106SO	Alternate engine thermocouple fire seal on B-720 engine firewalls.	SC	31420	Eastern Airlines International Airport Miami, Fl 33148
Turbo Wasp JT3D Series; T.C. 1E8	SE1WE	Valve assembly 126495. Limited to those engines having serial number suffix "E".	WE	77785	Telecomputing Corporation 915 North Citrus Avenue Los Angeles, CA 90052
JT3D-1, -3, -3B, -1-MC-6, -1-MC7, -7; T.C. 1E8	SE87WE	Replace the airfoils on P&WA P/Ns 505351, 536751, 665951, and 665851 first stage turbine nozzle guide vanes on P&WA engine models listed. Issued 12/21/77.	WE	22227	Chromizing Company Div. of Chromalloy American Corp. 2100 West 139th Street Gardena, CA 90249
JT8D; T.C. E2EA	SE67WE	Installation of fuel control rod end bearings. Amended 11/13/74.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85281
JT8D Series; T.C. E2EA	SE79WE	Installation of CADC bleed valve support brackets, P/N B10001 or RB10006, as a replacement part for P&W P/N 493317 used on JT8D-1-5-7--9-9A-15 and -17 engines. Issued 8/11/77.	WE	19500	California Aero Dynamics Corp. 8630 Tamarack Avenue Sun Valley, CA 91352
JT8D Series; T.C. E2EA	SE83WE	Installation of heat shield assembly P/N 408-007 as a replacement part for P&W P/N 499941 or 749609 used on JT8D-1, -5, -7, -9, -9A, -15 and -17 engines. Issued 11/15/77.	WE	43344	Hughes Helicopter Div. of Summa Corporation Centinela and Teale Streets Culver City, CA 90230
JT8D Series T.C. E2EA	SE84WE	Installation of heat shield assembly 408-008 as a replacement part for P&W No. 586918 used on JT8D-1, -5, -7, -9, -9A, -15, and -17 engines. Issued 11/15/77.	WE	43344	Hughes Helicopter Div. of Summa Corporation Centinela and Teale Streets Culver City, CA 90230
JT8D Series; T.C. E2EA	SE97WE	Installation of heat shield assembly 408-020 as a replacement part for P&W P/N 468559 used on JT8D-1, -5, -7, -9, -9A, -15, -17 engines. Issued 6/25/79.	WE	43344	Hughes Helicopter Division of Summa Corporation Centinela and Teale Streets Culver City, CA 90230
JT8D; T.C. E2EA	SA2627WE	Installation of fuel control rod end bearings. Amended 8/2/73.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85281
JT8D-1, -1A, -1B, -7, -7A, -7B, -9, -9A, -11, -15, -17, -17R; T.C. E2EA	SE86WE	Replace the airfoils on P&WA P/Ns 495051, 478351, 583751, 653851, 653951, 572451, 583351, 653751, 653151, 676951, 728951, 709951, 710751, 627751, 737271 first stage turbine nozzle guide vanes on P&WA engine models listed. Amended 6/22/78.	WE	22227	Chromizing Company Div. of Chromalloy American Corp. 2100 West 139th Street Gardena, CA 90249
JT8D-1, -1A, -7, -7A, -9, -11, -15; T.C. E2EA	SE59GL	Replacement of accessory drive gearbox seals. Amended 2/26/75.	GL	67600	Rexnord, Inc. Seal Division 634 Glenn Avenue Wheeling, IL 60090
JT9D-3, -4; T.C. E20EA	SE11CE	Installation of aircraft integrated data system components on engine. Issued August 1971.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
JT9D-7AH; T.C. E20EA	SE1141CE	Removal of 15th stage bleeds and surge detector system. Issued July 1975.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

PRATT & WHITNEY AIRCRAFT OF CANADA

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PT6A-6, -6A, -6/C20, -20, -20A, -20B, -21, -27, -28, -34, -34AG; T.C. E4EA, E2NE	SE1165EA	Assembly and installation of AW10262 unit spline starter gear seal. Issued 9/14/79.	EA	08375	Airwork Service Division Pacific Airmotive Corp., Inc. Millville Municipal Airport Millville, NJ 08332
PT6A-20, -27, -28; T.C. A4EA	SE12CE	Installation of Gits Brothers Manufacturing Company dipstick filler cap assembly P/N 02297-2000. Issued June 1971.	GL	38000	Gits Brothers Manufacturing Co. 1846 South Kilbourn Avenue Chicago, IL 66623
PT6A-27, -28; T.C. E4EA, E2NE	SE1122EA	Installation of rim-inner exit duct. Amended 8/1/78.	EA	08375	Airwork Service Division Pacific Airmotive Corp. Millville Municipal Airport Millville, NJ 08332

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

ROLLS-ROYCE, LTD.

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C90, O-300, O-240-A; T.C. E3IN, E4IN, E11EU	SE1-201	Installation of Richter B-4 or B-5 probes in Marvel Schebler carburetors MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6, HA-6 Series and Bendix NA-S3B and NA-S3A1. Amended 9/20/77.	EA	68000	Richter Aero Equipment, Inc. Essex, NY 12936
Dart 506, 510, 511, 514, 514-7; T.C. 283	SE13WE	Flexible hose fuel manifold assembly.	WE	67250	Resistoflex Corporation 301 North Crescent Way Anaheim, CA 92803
Dart 506, 510, 511, 514; T.C. 283	SE20WE	Flxible hose assemblies.	WE	67250	Resistoflex Corporation 301 North Crescent Way Anaheim, CA 92803
Dart 506, 510, 511, 511-7E, 514, 514-7; 525, 525D, 525F, 526, 527, 528, 528-7E, 528D-7E, 529, 529D, 529-7E, 529D-7E, 529-7H, 529-8E, 529D-8E, 529-8H, 529D-8H, 529-8X, 529D-8X, 531, 532-7, 532-7L; 542-4, 542-10, 542-10J, 542-10K; T.C. E-283, E-297, E5EU Avon 522, 524B, 525B, 526, 527, 531, 532R, 533R, 533R-11A; T.C. E-307 Conway 505, 508, 508A, 509, 509A; T.C. E-308 Tyne 506, 512, 515; T.C. E-311 Spey 506-14, 506-14C, 510-14, 511-8, 511-14, 555-15; T.C. E2EU	SE748EA	Installation of GLA ignition exciter.	EA	37750	General Laboratory Association, Inc. Norwich, NY 13815
Dart 506, 510, 511, 511-7E, 514, 514-7; 525, 525D, 525F, 526, 527, 528, 528-7E, 528D-7E, 529, 529D, 529-7E, 529D-7E, 529-7H, 529D-7H, 529-8E, 529D-8E, 529-8H, 529D-8H, 529-8X, 529D-8X, 531, 532-7, 532-7L, 532-7 , 532-7P; 542-10, 542-10J, 542-10K, 542-4, 542-4K; T.C. E-283, E-297, E5EU	SE905EA	Repair and modification of compresor outlet and interstage cases. Amended 10/24/74.	EA	08375	Airwork Service Division Purex Corporation, Ltd. Municipal Airport Millville, NJ 08332
506-14, -14A, 511-8, -14, -14W; T.C. E2EU	SE994EA	Manufacture of oil tank sight gage float. Amended 6/13/75.	EA	08375	Airwork Service Division Purex Corporation, Ltd. Municipal Airport Millville, NJ 08332
Dart 511; T.C. 283	SE203SO	Variations in Rolls-Royce modification 636.	SC	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
515; T.C. 311	SE23WE	Improved junction box 77-20-1.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
Dart 525, 526, 527, 528, 529; T.C. 297	SE12WE	Flexible hose fuel manifold assembly.	WE	67250	Resistoflex Corporation 301 North Crescent Way Anaheim, CA 92803
Dart 525, 526, 527, 528, 529; T.C. 297	SE19WE	Flexible hose assemblies.	WE	67250	Resistoflex Corporation 301 North Crescent Way Anaheim, CA 92803
Dart 525, 526, 527, 528, 529; T.C. 297	SE206SO	Replacement of accessory gear box oil pressure warning switch.	SC	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Gypsy Queen 30 MK 2; T.C. E-294-5	SE3PC	Installation of AC LA47 spark plugs as replacements for AC SR47P.	PC	41270	Hawaiian Air Tour Service 201 Aokea Street Honolulu, HI 96819
Gypsy Queen 30 MK.2; T.C. 294	SE9WE	Bendix S6LN-201 (L.H.) and S6LN-205 (R.H.) magnetos, Bendix 10-87999-1 vibrator for engine starting, and AC SR47P spark plugs.	WE	35670	Fleetair 20925 Roscoe Boulevard Canoga Park, CA 91303
Gypsy Queen 30 MK.2, 70MK2; T.C. 294, 310	SE24WE	Bendix ignition system and AC SR-47P spark plugs.	WE	70298	Charles Schachle 1941 Page Avenue Fullerton, CA 92631
Gq 30 MK2, Gq 70 MK2; T.C. E-294, E-310	SE36WE	Change from present partial chrome to full length chrome on cylinder walls.	WE	11340	Apache Airlies, Inc. Sky Harbor Airport Phoenix, AZ 85000
Gypsy Queen 70MK2; T.C. 310	SE1PC	AC spark plug SR47P.	PC	13865	Aviation Services, Inc. 2355 Kalakaua Avenue Honolulu, HI 96815
Gypsy Queen 70MK2; T.C. 310	SE2PC	Installation of Hawaiian Air Tour Service ignition conversion kit No. 70 for the Gypsy Queen 70 Series aero engines.	PC	13865	Aviation Services, Inc. 2355 Kalakaua Avenue Honolulu, HI 96815
Gypsy Queen 70MK2; T.C. 310	SE15WE	Modification of engine ignition system.	WE	39410	Graymar Aviation P.O. Box 335 Goleta, CA 93017
Gypsy Queen 70 MK 2; T.C. E-310	SA4PC	Installation of AC LA47 spark plugs as replacements for AC SR47P.	PC	41270	Hawaiian Air Tour Service 201 Aokea Street Honolulu, HI 96819
RB211-22B/-524; T.C. E12EU	SE1516CE	Modification of lower fuel control box assembly to incorporate vibration isolators. Issued 10/5/75.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City, MO 64195

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

TELEDYNE CONTINENTAL MOTORS

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A-40, -2, -3, -4; A-40-5; A-50; A-65; A-70, -2; A-75; A-80; A-100; C-75, C-85; C-90; C-115, -125; C-145; E-165, E-185; E-225, -2, -4, -8, -9; O-200-A; O-300; GO-300-A thru F; IO-346-A, -B; IO-360-A thru D; O-470-4, -11, -11-C1, -13-13A, -15; O-470-A, B, E, G, H, J, K, L, M, N, P, R; GIO-470-A; IO-470-A, -C; O-470-D thru U; FSO-470-A, -2; TSIO-470-B, -C, -D; IO-520-A, -B, -C; FSO-526-A, -C; GSO-526-A; GTSIO-520-C; TSIO-520; ATC 72, 174, T.C. 190, 205, ATC 32, T.C. 213, 217, 241, 233, 236, 246, 252, 253, 267, 298, E3CE, E1CE, 269, 273, E2CE, 3E1, 281, 3E3, E5CE, 292, 303, E7CE, E8CE-2	SE44WE	Use of Kling Aviation oil, specifications KL-100, KL-200, and KL-300 in Continental and Lycoming engines.	WE	48530	Kling Oil Company 1492 Cddstad Drive Redwood City, CA 94063
A-50, A-65, A-70, A-80, C-85, C-90, O-200, C-75, C-115, C-125, C-145, O-300, E-165-2, E-185-2, O-470, GO-300; T.C. 190, 205, 213, 217, 233, 252, 236, 253, 246, 273, 298	SE1-201	Installation of Richter B-4 or B-5 probes in Marvel-Schebler carburetors MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6, HA-6 series and Bendix NA-S3B and NA-S3A1. Amended 9/20/77.	EA	68000	Richter Aero Equipment Essex, NY 12936
A-50, A-65, A-70, A-80, C-85, C-90, O-200, C-115, C-125, C-145, O-300, E-165, E-185, O-470, GO-300; T.C. 190, 205, 213, 217, 233, 252, 236,	SE208SO	Installation of ice indicator in the carburetor.	SC	71545	Charles E. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
A-65 Series: T.C. E-205	SE64WE	Installation of oil screen and oil cooler adapter. Issued 5/24/74.	WE	42137	Laurence E. Hill 336 South Parish Place Burbank, CA 91506
A65, A75, C75, C85 Suffix "F" Series; T.C. 205, 213, 233	SE4CE	Motorola alternator A12NK451. Amended 1/20/78.	CE	15404	Steven E./Robert F. Bell R.R. #1, Box 5 Lawrence, KS 66044
A65, A75, C75, C85 Suffix "F" Series; T.C. 205, 213, 233	SE984SW	Delco 55A ampere alternator.	SW	84396	Lee A. Waldrop 7624 Palomar Fort Worth, TX 76118
C-85; T.C. 233	SE3CE	R-30-A alternator.	GL	67160	Kenneth J. Repke 7788 Auburn Detroit, MI 48233
C-145, O-300 Series: T.C. 253	SE3-663	Install dry vacuum pump drive. Reissued 7/15/69.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
D-185, E-225 Series; T.C. 246, 267	SE419SW	Full flow oil filter. Amended 3/1/67.	GL	77017	The Superior Flow Company Div. of A & E Manufacturing, Inc. 11300 Schaefer Highway Detroit, MI 48233
E-185 Series: T.C. 246	SE248EA	MOdification of Hartzell C-192-2 "T-Drive" for use with Airborne Mechanisms dry vacuum pump.	EA	85600	Edward J. White 207 Stephen Drive Cinnaminson, NJ 08077
E-185, E-225, O-470 Series; T.C. 246, 267, 269	SE23SW	R5-5BD1 fuel injection system.	GL	15500	Bendix Products Aerospace Div. 717 Bendix Drive South Bend, IN 46600
O-200 Series: T.C. E-252	SE2791SW	Revised starter clutch. Issued 6/6/78	SW	14214	B C & J Enterprises P.O. Box 19676 Oklahoma City, OK 73144

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
O-200-A; T.C. 252	SE8WE	Alternate oil sump.	WE	78476	Thorp Aircraft Company 909 East Magnolia Boulevard Burbank, CA 91500
O-200-A; T.C. E-252	SE82WE	Closing off of the oil outlet port of the main thrust bearing; installation of an O-200-B crankshaft; modifying the front oil seal slinger flange; machining an already existing molded pad on the crankshaft to receive a side mounted fuel pump. Issued 10/11/77.	WE	48527	Harvey J. Klein 1736 S. Bedford Street Los Angeles, CA 90035
O-200-A; T.C. 252	SE1396SW	Revise engine oil pick up system. Issued 11/24/71.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
E-225; T.C. 267	SE3WE	T-1106 turbocharger.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
O-300-A, -B, -C, -D, -E; IO-360-A, -B, -C, -D; IO-470-D thru -H, -J, -K, -L, -M, -R, -S, -U, -V; O-470-J, -R, IO-470-C; O-470-4, -11, -13, -15; IO-520-A, -D, -E, -F, -J, -K, -L; TSIO-520-C, -G, -H; GTSIO-520-C, -D, -F, -H; T.C. 253, E1CE, 3E1, 273, 269, E5CE, E8CE, E7CE	SE12GL	Installation of oil filler cap. Issued 7/11/73.	GL	05850	Ray Whyte Electric Products Co. 30201 Harper Avenue St. Clair Shores, MI 48083
IO-346 and IO-520; T.C. E3WE, E5CE	SE34WE	Installation of Electro-Coatings, Inc. piston rings P/N 252501 and 252509 on Continental piston 631475 for use in Channel-cromium plated Continental IO-346 and IO-520 engine cylinder.	WE	33219	Electro-Coatings, Inc. 1401 Park Avenue Emeryville, CA
IO-360-A, -B, -C, -D, -G, -H, -J, -K; T.C. E1CE	SE234GL	Installation of a steel pin in Continental fuel pump, P/N 638157. Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
IO-360-K; T.C. E1CE	SE1436CE	Modify engine to obtain 210 hp, 2800 rpm for 5 minutes at takeoff and 195 hp 2600 rpm continuous (new designation IO-360-KC/STC SE1436CE). Issued 10/6/78.	CE	44802	Brad E. Isham 416 West Fourth Street Valley Center, KS 67147
TSIO-360-A, -B, -C, -D, -E, -F, LTSIO-360-E; T.C. E9CE	SE235GL	Installation of a steel pin in Continental fuel pump P/N 634263 (TSIO 360-A, -B), 639508 (TSIO-360-C, -D, -E, -F), and 639508 (LTSIO-360-E). Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
O-470 Series; T.C. 269	SE264SW	Marvel-Schebler MA-4-5 carburetor.	SW	32000	Ector Aircraft Company 1703 West Crescent Drive Odessa, TX 79760
O-470 Series; T.C. 273	SE1CE	RSA-5 fuel injection system.	GL	15500	Bendix Products Aerospace Div. 717 Bendix Drive South Bend, IN 46600
O-470 Series; T.C. 273	SE141SW	Rework crankcase in area of starter drive needle bearing.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
O-470 Series; T.C. 273	SE616SO	Installation of O-470-R parts in lieu of normal O-470-M parts.	SC	61644	North Perry Aviation, Inc. 8000 West Pembroke Road Hollywood, FL 33023
O-470, IO-470 Series; T.C. 273	SE325SW	Full flow oil filter. Amended 3/1/67.	GL	77017	The Superior Flow Company Div. of A & E Manufacturing, Inc. 11300 Schaefer Highway Detroit, MI 48233
O-470, IO-470 Series; T.C. 273, 3E1	SE73SO	Continental GIO-470 engine oil sump assembly 628943 and oil pump suction tube assembly 628660.	SC	05580	Aircraft Modification Engineering Company P.O. Box 48-1314 Miami, FL 32960
O-470, IO-470, TSIO-470 Series; T.C. 269, 273, 3E1, 3E3	SE16WE	Bendix S-600 low tension ignition system.	WE	70055	Salinas Engine Works Municipal Airport Salinas, CA 93901

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
O-470, IO-470, TSIO-470 Series; T.C. 269, 273, 3E1, 3E3	SE26WE	Piston ring 250000, 250000+2W and 250000+10W on Continental E Series piston 534895, O-470 piston 534895, 626992 and 537883 and IO-470 piston 534895.	SW	21500	Electro-Coatings, Inc. Channelcromium Division P.O. Box 428 Grapevine, TX 76051
O-470-A, J, K, L, R, G-C1, IO-470-C, -J, -K; T.C. 273, 3E1	SE25WE	Installation of two Rajay turbochargers Model 315F10, P/N RJ0080-102. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
O-470-B, -G, -H, -K, -L, -M, -N, -S, -T, -U, O-470-B-C1, G-C1, K-C1, L-C1, M-C1, IO-470-A, -C; T.C. E-273	SE95WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-470 Series; T.C. 273, 3E1	SE82SO	Engine sump reworked to provide 15 1/8-quart total oil capacity.	SC	68140	Riley Aeronautics Corporation 2100 Northwest 50th Street Fort Lauderdale, FL 33300
IO-470 Series; T.C. 273, 3E1	SE387SW	Modification of ring grooves on Continental Motors pistons 539814 (3 ring) and 627738 (4 ring).	SW	82250	Van Der Horst Corporation of America P.O. Box 428 Terrell, TX 75160
IO-470 Series; T.C. 3E1	SE2-984	Modification of Continental IO-470 piston 6277338 for piston ring used in Continental O-470 piston 537883.	SW	21500	Pennington Channelcromium Company Division of Electro-Coatings, Inc. 319 Dakota Street San Antonio, TX 78205
IO-470 Series; T.C. 3E1	SE94SW	Modification of Continental IO-470 pistons 627738 and 539814 compression ring grooves.	SW	22250	Chrome Plate, Inc. 2805 South Flores Street San Antonio, TX 78205
IO-470 Series; T.C. 3E1	SE152SO	Modification of throttle body location.	SC	37084	Gander Aircraft Corporation 3923 Northwest 24th Street Miami, FL 33142
IO-470-C; T.C. E273	SE994SO	Installation of fuel line filters into individual fuel injector lines. Issued 5/25/76.	SC	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-470-D, -E, -F, -H, -L, -M, -N, -S, -U, -V, -VO; T.C. 3E1	SE69WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	SC	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-470-D, -E, -F, -G, -H, -L, -LO, -N, -P, -R, -S, -T, -U, -V, -VO, LIO-470-A; T.C. 3E1	SE92WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-470-D, E, M, N, S, U, V; T.C. 3E1	SE96SO	Installation of two (2) Rajay turbochargers Model 315F10, P/N RJ0080-102. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
IO-470-J, -K, -N, L; T.C. 3E1	SE992SO	Installation of fuel line filters into individual fuel injector lines. Amended 9/17/76.	SC	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-470, IO-520, TSIO-520 Series; T.C. E-273, 3E1, 3E3, E5CE, E8CE	SE55WE	Modification of fuel injection manifold valve P/N 626547 to the P/N 631427 or P/N 636326 configuration. Issued 2/10/72.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
GIO-470-A; T.C. E2CE	SE70WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
TSIO-470 Series; T.C. 3E3	SE166SW	Modification of Continental TSIO-470 Series piston 629185 for piston rings used in Continental O-470 Series piston 537883.	SW	21500	Pennington Channelcromium Co. Div. of Electro-Coatings, Inc. 319 Dakota Street San Antonio, TX 78205
TSIO-470 Series; T.C. 3E3	SE271SW	Modification of Continental TSIO-470 piston 629185 compression ring grooves.	SW	22250	Chrome Plate, Inc. 2805 South Flores Street San Antonio, TX 78205
TSIO-470-B, -C, -D; T.C. 3E3	SE71WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
TSIO-470B, C, D; T.C. 3E3	SE93WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-520, TSIO-520 Series: T.C. E5CE	SE70RM	Installation of JB Systems compressor brackets P/N 21-052-19. Amended 6/6/79.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
GTSIO-520-C, -D; T.C. E7CE	SE74WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-520-A, -B, -BA, -C, -D, -E, -F, -J, -K, -L, -M; T.C. E5CE	SE72WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-520-A, -B, -BA, -C, -D, -E, -F, -J, -K, -L, -M; T.C. E-273	SE94WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-520-B, -BA; T.C. E5CE	SE282GL	Installation of a fuel flow transducer, Symbolic Displays P/N 201B. Issued 11/14/78.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport Rockford, IL 61109
IO-520-B, -BA, C; T.C. E5CE	SE993SO	Installation of fuel line filters into the individual fuel injector lines. Amended 9/17/76.	SC	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-520-D; T.C. E5CE	SE75WE	Installation of emergency fuel system. Issued 9/9/75.	WE	59730	Mission Aviation Fellowship Box 2828 3519 West Commonwealth Fullerton, CA 92633
IO-520-E; T.C. E5CE	SE451SO	Installation of air compressor gear box drive. Amended 4/6/71.	SC	65333	Puerto Rico Int'l Airlines P.O. Box 1498 Bayamon, PR 00619
IO-520-F; T.C. E5CE	SE80WE	Installation of an emergency fuel system. Issued 9/13/77.	WE	59730	Mission Aviaiton Fellowship P.O. Box 2828 Fullerton, CA 92633
IO-520-G; T.C. E7CE	SE1004SW	Install alternator braces. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
TSIO-520-A, -B, -C, -D, -E, -G, -H, -J, -K, -L; T.C. E8CE	SE73WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
TSIO-520-A, -B, -C, -D, -E, -F, -G, -H, -J, -K, -L, -M, -N, -P, -R; T.C. E8CE	SE96WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
TSIO-520-C, M; T.C. E8CE	SE88WE	Installation of emergency fuel system. Issued 2/7/78.	WE	59730	Mission Aviation Fellowship Box 2828 Fullerton, CA 92633
TSIO-520-D; T.C. E8CE	SE57WE	Installation of two (2) Rajay P/N RJ0080-100, -101 or -102 turbo-superchargers on Continental Teledyne engine. Amended 11/17/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
TSIO-520-D; T.C. E8CE	SE233GL	Installation of a steel pin in Continental fuel pump P/N's 639508 and 632637. Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
TSIO-520-K; T.C. E5CE	SE1908SW	Conversion of TSIO-520-K to TSIO-520-J. Issued 8/29/74.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
TSIO-520-N; T.C. E8CE	SE2831SW	Bendix S6RN-1251 and S6RN-1255 magnetos. Issued 8/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
TSIO-520-T; T.C. E8CE	SE1462CE	Installation of SSP Products heater core and shroud. Issued 12/4/78.	CE	20625	Cessna Aircraft Company Pawnee Division 5800 East Pawnee Wichita, KS 67201

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Miscellaneous	SE34WE	Installation of Electro-Coatings, Inc., piston rings on Continental pistons. Amended 3/14/68.	SW	21500	Electro-Coatings, Inc. Channelcromium Division P.O. Box 428 Grapevine, TX 76051
Miscellaneous	SE41WE	Installation of emergency fuel system.	WE	59730	Missionary Aviation Fellowship P.O. Box 2828 Fullerton, CA 92633
Miscellaneous	SE43WE	Installation of an additional dowel in crankshaft accessory gear.	WE	16853	Willard S. Blackinton 9333 Edgewood Drive La Mesa, CA 92041

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

WRIGHT AERONAUTICAL DIVISION
CURTISS-WRIGHT CORPORATION

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
R-1820 Series Group 5E-10; T.C. E-219	SE3-2	Installation of fuel flow meter, Bendix Model 9054-5A. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 N. Rockwell Avenue Bethany, OK 73008
C9HD, Military R-1820 Series; T.C. 219, 243	SEW-1	Adapters and oil seals on the dual accessory housing assemblies.	WE	75119	Steward-Davis, Inc. 13501 S. Western Avenue Gardena, CA 90247
Military R-1820 Series; T.C. 5E-10	SE105SO	Modification of piston 138727.	SO	01815	Aerodex, Inc. International Airport Miami, FL 33148
Military R-1820 Series; T.C. 5E-10	SE565SW	Seal adapter kit and dual accessory drive. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
C18 Series; T.C. 218	SE202SO	Wright cylinder assembly with accommodation for fuel injection nozzles.	SC	29225	Delta A & E Sales Company 2461 N. Main Steeet East Point, GA 30344
C18, TC18 Series; T.C. 218, 270, 272, 287	SEW-10	Torquemeter booster pump housing.	WE	29690	Deterjet Corporation 1062 S. Claremont Steeet San Mateo, CA 94402
TC18DA, TC18EA Series; T.C. 272, 287	SEW-2	Fabrication of engine exhaust system clamps M-7540, M-7541 and M-7544.	SC	34060	Exhaust Parts, Inc. 950 S.E. 8th Steeet Hialeah, FL 33010
TC18DA, TC18EA Series; T.C. 272, 287	SEW-4	Exhaust system parts.	SC	34060	Exhaust Parts, Inc. 950 S.E. 8th Steeet Hialeah, FL 33010
TC18DA, TC18EA Series; T.C. 272, 287	SE204SO	Rework of cylinder assembly.	SC	29225	Delta A & E Sales Company 2461 N. Main Steeet East Point, GA 30344
TC18DA, TC18EA Series; T.C. 272, 287	SE2WE	Cylinder and intercylinder cooling baffles.	WE	16291	Frank R. Berry 8465 Melrose Place Los Angeles, CA 90052
TC18DA, TC18EA, Military R-3350 Series; T.C. 272, 287	SE207SO	Modification of PRT cooling cap.	SC	29225	Delta A & E Sales Company 2462 N. Main Steeet East Point, GA 30344
Wright R-2600-35 T.C. 5E-9	SE610SO	Generator drive modifications in accordance with Report CAC-R2600-42 & Dwg. 1221200.	SC	21560	Charlotte Aircraft Corporation 496 West 18th Street Hialeah, FL 33010

PROPELLERS

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
PROPELLER
BEECH AIRCRAFT CORPORATION

Propeller Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
278/100/278-208-84 107/278-208-84; T.C. 882	SP2WE	Installation of Univair 8405-0 propeller blades in lieu of Beech 278-208-84 blades.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80010
278-100/278-214-82; 278-107/278-214-82; T.C. 882	SP3WE	Installation of Univair 8405-2 propeller blades in lieu of Beech 278-214-82 blades.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80010

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
PROPELLER
DOWTY ROTOL, LTD.

Propeller Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
R245/4-40-4.5/13, R259/4-40-4.5/17, R209/4-40-4.5/2; T.C. P2EU	SP1016EA	Replacement of Dowty Rotol top and bottom roller bearing cages with SEMSA, Inc. P/Ns 601023258-S and 601023257-S respectively in the above model propellers. Issued 10/1/75.	EA	70830	SEMSA, Incorporated Aviation Support Division 2125 Smithtown Avenue Ronkonkoma, NY 11779
R257/4-30-4/60; T.C. P-899	SP1051EA	Installation of Safeway de-icer overshoe P/N 5938 and Sensa lead P/N S2002. Issued 6/14/77.	EA	70830	Sensa Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

PROPELLER

HAMILTON STANDARD DIVISION

Propeller Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
22D Series; T.C. 736	SP185SO	B.F. Goodrich electric deicers.	EA	25635	Commuter A/C Manufacturing Corp. Box 904, Broome County Airport Binghampton, NY 13902
2D30 Series; T.C. 736	SP790SW	Seal carrier and "O" ring seals.	SW	73880	Southern Aviation Corporation P.O. Box 7224 Shreveport, LA 71102
2B20-61359; T.C. P-255	SP250NW	Installation of Hamilton propeller 2B20 hub with 6135-9 blades modified by adding blade cuffs and EAC-20-204 seal to replace HSP P/Ns 50287, 50116, 50015.	NW	62120	Pacific Propeller P.O. Box 946 Kent, WA 98031
2D30, 12D40, 22D30, 22D40; T.C. 206, 257, 736, 719	SP7WE	Installation of AG-100-2 and AG-200-2 propeller blades in Hamilton Standard hub. Amended 7/6/73.	NW	33000	Efficiency Aircraft Components, Inc. 5802 S. 222 Street Kent, WA 98031
22D30/6531A-15/ 6533-21; T.C. 736	SA185SO	Installation of B.F. Goodrich electric de-icers. Reissued 9/11/79.	SO	08169	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
2D30, AG-100-4S; T.C. P-206	SP245NW	Manufacture AG-100-4S blades and CF AG-100-4S blades with cooling fairing and use thereof in Hamilton 2D30 hubs of P&W R-985, 450 h.p. engine. Issued 12/23/75.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
2D30, 12D40, 22D30, 22D40, 23D40, 33D50, 24D50; T.C. P-206, P-257, P-736, P-719, P-749, P-784	SP362NW	Propeller blade chaffing ring.	NW	62120	Pacific Propeller P.O. Box 946 Kent, WA 98031
2D30/6101A-10S; T.C. P-206	SP829SO	Vibration approval for single engine tractor installations only, on P & W Model P985-AN-1, -AN-3, -AN-14B, -25, -27, -39A, T1B2 and T1B3 engines. Amended 2/20/76.	SC	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Nortrook Drive Memphis, TN 38116
3D40, 23D40; T.C. P-719, 249	SP148NW	Installation of EAC propeller blades in Hamilton Standard hubs (blades AG100-OS and AG200-OS). Amended 2/28/75.	NW	33000	Efficiency Aircraft Components, Inc. 5802 S. 222 Street Kent, WA 98031
3D40; T.C. 249	SA195NW	Installation of "O" ring seals in place of Hamilton Standard leather seals. Issued 7/2/75.	NW	62120	Pacific Propeller, Inc. P.O. Box 946 5892 S. 228th Street Kent, WA 98031
23D40; T.C. P-719	SP161NW	Installation of rear spider seal (limited to Wright R-1300-1B engines). Issued 2/28/75.	NW	62120	Pacific Propeller, Inc. P.O. Box 946 5892 South 228th Street Kent, WA 98031
12D40; T.C. P-257	SP725NW	"O" ring seal in place of crush gasket or cylinder head. Issued 2/26/79.	NW	62120	Pacific Propellers, Inc. P.O. Box 946 Kent, WA 98031
12D40; T.C. P-257	SP755NW	Barrell support blocks for reworked propeller blades. Issued 4/19/79.	NW	62120	Pacific Propellers, Inc. P.O. Box 946 Kent, WA 98031
12D40/6101A-10S; T.C. P-257	SP830SO	Vibration approval for single engine tractor installation only, on P & W Model R1340-AN-1 (S3H1 or S1H1 commercial designation engines. Amended 2/20/76.	SC	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Nortrook Drive Memphis, TN 38116

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
PROPELLER
HARTZELL PROPELLER, INC.

Propeller Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
HC-A3V; T.C. P6EA	SP169SO	Goodyear electro-thermal deicing equipment. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
HC-A3V; T.C. P6EA	SP630SO	Installation of Goodyear electro-thermal deicing equipment. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
HC-B3Z; T.C. 907	SPW-3	Modification of Hamilton Standard 4A2-V5 propeller governor to NWP-D18 on aircraft with Pratt & Whitney R-985 engines.	NW	61718	Northwest Propeller, Inc. Boeing Field Box 28 (FAA Building) Seattle, WA 98101
HC-93Z; T.C. 891	SPW-2	Modification of Hamilton Standard 4A2-V5 propeller governor to NWP-D18 on aircraft with Pratt & Whitney R-985 engines.	NW	61718	Northwest Propeller, Inc. Boeing Field Box 28 (FAA Building) Seattle, WA 98101

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

PROPELLER

HAWKER SIDDELEY DYNAMICS, LTD.

Propeller Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PD-/476/2; T.C. 7P3	SP4WE	Propeller blade heaters relocation.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

PROPELLER

McCAULEY ACCESSORY DIVISION

Propeller Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
McCauley 2D34CT69; P18EA	SP766SW	Modify from two position to constant speed.	SW	85700	Whiteface Aviation Company Drawer 433 Hereford, TX 79045

MISCELLANEOUS

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

MISCELLANEOUS

MISCELLANEOUS

Miscellaneous Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Miscellaneous	SA4-302	EN-1 propeller spinner.	WE	75252	Raymond F. Stits 3665 Bloomington Blvd. Riverside, CA 92509
Miscellaneous	SA4-396	Installation of Firestone Model DFA-207 wheels and brakes.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Ave. Torrance, CA 90501
Miscellaneous	SA4-1200	Installation of Delco-Remy Generator Part No. 1101879 in lieu of P/N 1101876 and Regulator No. 1118384.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
Miscellaneous	SA4-1210	Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
Miscellaneous	SG4-1240	Eonnex cover installation of glider surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
Miscellaneous	SE1-201	Approval of WAC line FLDX-N20350 temperature indicator as an alternate instrument.	EA	68000	Richter Aero Equipment, Inc. Essex, NY 12936
Miscellaneous	SP5WE	Installation of Little Giant Propeller Seal. Reissued 8/26/70.	NW	33000	Efficiency Aircraft Components, Inc. 5802 S. 228th Street Kent, WA 98031
Miscellaneous	SH12CE	Replace existing engine induction air filter with AC Spark Plug Div. filter in accordance with Approved AC Fliter List(s).	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
Miscellaneous	SA69NW	Installation of carburetor air filter. All aircraft with standard carburetors. Issued 9/19/73.	NW	56600	D. H. Matneys d.b.a. Matneys Aircraft Service 24415 118th Ave. SE Kent, WA 98031
Miscellaneous	SA96SW	Mixture control indicator kits. Reissued 4/8/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
Miscellaneous	SA199CE	Exhaust gas temperature measuring systems.	CE	74923	Standard Precision, Inc. 4105 W. Pawnee Wichita, KS 67202
Miscellaneous	SA204SW	Genitron MKII trickle battery charger.	SW	86180	John Willet III 127 Miami Drive San Antonio, TX 78216
Miscellaneous	SA214EA	Fiberglas method.	NE	30790	Dutton Flying Service 239 Newton Rd. Haverhill, MA 01830
Miscellaneous	SA232EA	Tactair Omni Lock Model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair Model omni lock model CL-1). Reissued 8/7/72.	GL	14125	Avionics, Inc. Terminal Bldg., Lunken Airport Cincinnati, OH 45226
Miscellaneous	SA239SW	Exhaust gas temperature indicator. Reissued 4/8/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
Miscellaneous	SA250CE	Twin-engine electronic propeller synchronizer system.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
Miscellaneous	SA274SW	Lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Miscellaneous	SA292SW	F-4 central air filter in all single and multi-engine aircraft with incorporated instrument vacuum systems.	SW	13500	Aviation Instrument Manufacturing Corporation 9033 Monroe Road Houston, TX 77017

Miscellaneous Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Miscellaneous - Normal, Utility and Acrobatic Category airplanes and helicopters equipped with engines and carburetors as described	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system Model 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Miscellaneous	SA348CE	SP-5300-1 or -2 TACOR (Turn and Attitude Coordinator).	CE	74923	Standard Precision, Inc. 4105 W. Pawnee Wichita, KS 67202
Miscellaneous	SA358CE	Electronic tachometer kits.	EA	16031	The Bendix Corporation Scintilla Division Sidney, NY 13838
Miscellaneous	SA359CE	Electronic synchroscope kits.	EA	16031	The Bendix Corporation Scintilla Division Sidney, NY 13838
Miscellaneous - Normal, Utility and Acrobatic Category airplanes and helicopters equipped with engines and carburetors as described	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system Models 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Miscellaneous	SA522SW	Ekonomix EGT indicator kit SE35 or TE36. Reissued 4/8/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
Miscellaneous	SA589WE	Full flow oil filter F-94056 and F-94056-12 with element E-3560 MEL 800. Reissued 10/5/76.	WE	87505	Worldwide Filter Corporation P.O. Box 1129 Oakland, CA 94611
Miscellaneous	SA641WE	Full flow oil filter F-116090 with element E-5080, MEL 900. Reissued 10/5/76.	WE	87505	Worldwide Filter Corporation P.O. Box 1129 Oakland, CA 94611
Miscellaneous	SA660WE	HRD-type fire extinguishing system.	WE	10327	HTL Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
Miscellaneous	SA693CE	Replace existing engine induction air filter with AC Spark Plug Div. filter in accordance with Approved Model List(s).	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
Miscellaneous	SA695CE	Install oil filter in accordance with Approved Model List(s).	GL	70360	Donald R. Schmidt Schmidt Aero Service Worthington, MN 56187
Miscellaneous	SA788WE	Mixture monitor (exhaust gas temperature probe and gage).	RM	82394	Robert G. Van Houten P.O. Box 974 Grand Junction, CO 82394
Miscellaneous	SA808SW	Installation of Mitchell Model AK246 omni-tracker.	SW	60000	EDO-AIRE Mitchell P.O. Box 610 Mineral Wells, TX 76067
Miscellaneous	SA830SW	Mitchell Glide Slope Coupler 1C493.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
Miscellaneous See MEL C-110 for list of approved airplane models and applicable airworthiness regulations	SA868WE	Incorporate exhaust temperature measuring systems per Radair Div. of Dynair Electronics, Inc. MEL C-110 on reciprocating internal combustion engines powering aircraft, locating the indicator in the aircraft cockpit. To be used as an aid to manual leaning by visual observation of exhaust temperature(s). System is for both single and multi-engine aircraft. Reissued 8/8/78.	WE	78405	Terra Corporation 3520 Pan American Freeway, NE Albuquerque, NM 87107

Miscellaneous Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Miscellaneous	SA899WE	Installation of Model 110 or 111 mixture indicator on single engine aircraft and Model 210 or 211 mixture indictor on twin engine aircraft.	WE	32050	Ectron Corporation 8070 Engineer Blvd. San Diego, CA 92111
Miscellaneous	SA1008WE	Application of Poly-Fiber cover on aircraft.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
Miscellaneous	SA1064WE	Ice detection probe in carburetors.	RM	66000	Radair, Inc. 3385 S. Bannock Street Englewood, CO 80110
Miscellaneous	SA1290WE	Installation of supplemental exterior flashing lights.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
Miscellaneous	SA1335WE	Supplemental exterior flashing lights.	WE	18250	Bullock Magnetics Corporation 2818A Metropolitan Place Pomona, CA 91767
Miscellaneous	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglas cloth. (See Aircraft & Model for individual listing). Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Miscellaneous	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. (See Aircraft & Model for individual listing). Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Miscellaneous	SA1427WE	Installation of A.I.R. Corp. Fuel-Water Detector.	WE	04550	A.I.R. Corporation P.O. Box 2421 Oakland Int'l. Airport Oakland, CA 94614
Miscellaneous	SA1446WE	Inst'l. of supplemental exterior flashing lights.	WE	86540	Ray Winn c/o Winn Avionics 4641 Corral Place Las Vegas, NV 89109
Miscellaneous	SA1462WE	Installation of Control Postion Indicator (CPI) System.	NW	65017	Positive Flight Control 14220 Sunset Highway Bellevue, WA 98004
Miscellaneous	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 6/26/68.	WE	48750	KS Avionics 18145 Judy Street Castro Valley, CA 94546
Miscellaneous	SA1582WE	Installation of Control Position Indicator (CPI) System.	NW	65017	Positive Flight Control 14220 Sunset Highway Bellevue, WA 98004
Miscellaneous	SA1588WE	Installation of supplemental exterior flashing lights.	RM	29250	Delta Products, Inc. P.O. Box 1147 Grand Junction, CO 81501
Miscellaneous	SA1632WE	Installation of supplemental exterior flashing lights.	WE	70500	Scientifico Scientific Components Company 350 Vista Baya Newport Beach, CA 92660
Miscellaneous	SA1686WE	Installation of Vibration Isolation Products engine mount P/N VIP 50545-1	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Blvd. Burbank, CA 91505
Miscellaneous	SA1716WE	Installation of exhaust gas temperature system.	RM	40500	Hanna-Aero Company 5222 S. Holly Street Littleton, CO 80120
Miscellaneous	SA2336SW	Brittain B-12 Accu-Flite System. Issued 7/23/76.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Miscellaneous	SA2386SW	S.A.F.E., EGT, CHT Systems. Issued 1/25/77.	SW	14040	Avicon Development Corporation 701 N. Central Expressway Richardson, TX 75080
Miscellaneous	SA2905SW	AVICON TZ1 fuel flow totalizer. Issued 1/30/79.	SW	14040	Avicon Development Corporation 701 North Central Expressway Richardson, TX 75080

Miscellaneous Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Miscellaneous	SA2906SW	AVICON AF1 fuel flow processor. Issued 1/30/79.	SW	14040	Avicon Development Corporation 701 North Central Expressway Richardson, TX 75080
Miscellaneous Engines	SE2932SW	Install carburetor air temperature indicator. Issued 3/14/79.	SW	09250	Alcor, Inc. P.O. Box 32516 San Antonio, TX 78284

AUG 27 1980
Jacket # 627-758
C-200
Item 431-A-5
contin
TD 4.36:980/supp.-1

DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

SUMMARY OF SUPPLEMENTAL TYPE CERTIFICATES

9336

This contains revisions to Summary of Supplemental Type Certificates issued for April, May, June 1980

PAGE CONTROL CHART

Remove Pages	Insert Pages
Aerospatiale 1-2	Aerospatiale 1-2
Avions Marcel Dassault 5 thru 9	Avions Marcel Dassault 5 thru 9
Ayres 3	Ayres 3-4
Beech 39 thru 73	Beech 39 thru 74
Bell 7 thru 13	Bell 7 thru 13
Bellanca MN 5-6	Bellanca MN 5-6
Boeing 7 thru 48	Boeing 7 thru 48
British Aerospace 3 thru 9	British Aerospace 3 thru 9
British Aircraft 1 thru 3	British Aircraft 1 thru 3
Cessna 5 thru 8, 11 thru 81	Cessna 5 thru 8, 11 thru 83
Costruzioni Aero. Agusta 1	Costruzioni Aero. Agusta 1
DeHavilland 3-4, 7	DeHavilland 3-4, 7-8
- - -	Empressa Brasileira Embraer 1
Gates 7 thru 9	Gates 7 thru 9
General Dynamics 9 thru 19	General Dynamics 9 thru 19
Gulfstream 5 thru 24	Gulfstream 5 thru 24
Hughes 3 thru 5	Hughes 3 thru 5
Lockheed GA 9 thru 11	Lockheed GA 9 thru 11

PAGE CONTROL CHART

Remove Pages	Insert Pages
Martin 3	Martin 3
Maule 1-2	Maule 1-2
McDonnell Douglas 15 thru 41	McDonnell Douglas 15 thru 42
Messerschmitt 1-2	Messerschmitt 1-2
Mooney 3 thru 6	Mooney 3 thru 6
Mooney Mite 1-2	Mooney Mite 1-2
Navion 5	Navion 5
Nihon 1	Nihon 1
Piper 7 thru 65	Piper 7 thru 66
Piper Aerostar 1 thru 3	Piper Aerostar 1 thru 3
Rockwell Int'l CA 5 thru 10	Rockwell Int'l CA 5 thru 10
Rockwell Int'l OK 9 thru 15	Rockwell Int'l OK 9 thru 15
Sikorsky 1-2	Sikorsky 1 thru 3
SNIAS 5-6	SNIAS 5-6
Swearingen 1 thru 3	Swearingen 1 thru 3
Taylorcraft Aviation 1-2	Taylorcraft Aviation 1-2
Univair 5-6	Univair 5-6
ENGINES	
Avco Lycoming 1-2	Avco Lycoming 1-2
Pratt & Whitney 3	Pratt & Whitney 3
PROPELLERS None Received	
MISCELLANEOUS None Received	

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
AEROSPATIALE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Alouette III Series; T.C. H1IN	SH752NW	Installation of a weighing system. Issued 4/12/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SE.3160 Alouette III; T.C. H1IN	SH434AL	Installation of Alaskan Sky-Craft cargo baskets. Issued 6/10/71.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
SE.3160, SA.316B, SA.316C, SA319B; T.C. H1IN	SA1243SW	Eastern rotorcraft cargo hook AK251T. Reissued 1/4/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SE.3160 Alouette III; T.C. H1IN	SH1791SW	Foxtronics/Tramm BTI-600 nickel cadmium battery temperature. Issued 1/30/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
SE 3160 Alouette III, SA 316B Alouette III; T.C. H1IN	SA1320SW	External cargo baskets. Issued 6/1/71.	SW	84300	Vought Helicopter, Inc. 1507 Pacific Avenue Dallas, TX 75201
SE.3160 Alouette III, SA.316B Alouette III; T.C. H1IN	SH1490SW	AiResearch 92757 environmental control system. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160 Alouette III, SA.316B Alouette III; T.C. H1IN	SH1800SW	Install reclining passenger seat in forward left hand position. Issued 2/1/74.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SE.3160, SA.315B, SA.316B; T.C. H1IN	SH1471SW	Engine inlet sound suppresors. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.315B, SE316 Series; T.C. H1IN	SH437NW	Incorporation of weighing system for external load operations. Amended 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
SE3160, SA316B, SA319B; T.C. H1IN	SH71NW	Installation of electric weighing system. Amended 11/7/75.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
SE.3160, SA.315B, SA.316B, SA.319B, SA316C; T.C. H1IN	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SE.3160, SA.316B, SA.316C; Alouette III; T.C. H1IN	SH1900SW	Non-stowable litter kit. Issued 7/24/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1307SW	Eastern Rotorcraft cargo hook and H-frame. Reissued 1/4/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1318SW	Removable cabin step. Issued 10/2/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1320SW	External cargo baskets. Reissued 7/1/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319C; T.C. H1IN	SH1385SW	Replace existing landing light and anti-collision light. Reissued 9/30/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA315B; T.C. H1IN	SH61NW	Installation of electric weighing system. Amended 5/5/76.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
SA315B; T.C. H1IN	SH267NW	Installation of Simplex Model 3400 3400 spray system. Issued 6/16/76.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
SA315B; T.C. H1IN	SH268NW	Installation of automatic flagman Model #5. Issued 3/18/76.	NW	03500	Air Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
SA315B; T.C. H1IN	SA429NW	Installation of Simplex Model 4206 4206 aerial spray system. Issued 4/11/77.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA315B; T.C. H1IN	SH540NW	Install onboard weighing system. Issued 1/9/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA.315B; T.C. H1IN	SH695NW	Installation of Model 2512 weighing system. Issued 12/14/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA.315B; T.C. H1IN	SH1735SW	H-frame external cargo hook. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.315B Alouette III; T.C. H1IN	SH1909SW	Replacement of existing landing light and anti-collision light. Reissued 9/30/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.315B; T.C. H1IN	SH2425SW	Installation of low range airspeed indicator and pitot pressure surge chamber. Issued 3/4/77.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
SA.316B Alouette III; T.C. H1IN	SH168WE	Installation of Nightsun SC-16C searchlight. Issued 8/28/74.	WE	74500	Spectrolab Division of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
SA.316B Alouette III; T.C. H1IN	SH647NW	Installation of cargo baskets. Issued 8/3/78.	NW	44032	Inland Helicopters 2660 Vine Street Grants Pass, OR 97526
SA.316B, SA.316C, SA319B; T.C. H1IN	SH223WE	Installation of tail rotor floodlight. Issued 9/12/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
SA-360C; T.C. H8EU	SH2962SW	Blade bolt balance pin adapter. Issued 3/23/79.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
SA360C; T.C. H8EU	SH4051SW	Modification of lower cabin plexiglass panels. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C, SA-365C; T.C. H8EU, H10EU	SH1179EA	Installation of DeVore tail floodlight on upper surfaces of horizontal stabilizer. Reissued and amended 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
SA-365C; T.C. H10EU	SH2987SW	External markings. Issued 4/23/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA-365C; T.C. H10EU	SH4050SW	Twelve-place interior with forward facing seats. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-365C; T.C. H10EU	SH4052SW	Modification of lower cabin plexiglass panels. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-365C; T.C. H10EU	SH4072SW	Interior installation. Issued 1/11/80.	SW	41780	Heliflight Systems, Inc. P.O. Box 90879 Houston, TX 77090
SA-365C; T.C. H10EU	SH4073SW	Equipment shelf in upper baggage area. Issued 1/11/80.	SW	41780	Heliflight Systems, Inc. P.O. Box 90879 Houston, TX 77090

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST849SO	PPG Industries windshields, Federal Express P/N's 111-0071, (L/H), 111-0072 (R/H), 111-0073 (center). Issued 8/4/75.	SO	34808	Federal Express Corporation 2839 Sprankel Road P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST882SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA891SW	Dorne & Margolin DMN4-15-5 antenna. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA894EA	Installation of Grimes three light strobe kit P/N 34-0302-1 as supplemental lighting. Issued 12/20/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST925SO	Manufacture of main landing gear door arm for Fan Jet Falcon Series airplane. Issued 2/24/77.	SO	05090	Aircraft Equipment Cert. Corp. P.O. Box 18850 Memphis, TN 38118
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	ST948SO	Installation of Aircraft Equipment Certification Corp. pilot/copilot/ center windshield panels. Amended 6/2/78.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C,D,E,F: T.C. A7EU	ST960SO	Manufacture and installation of Aircraft Equipment Certification Corp. (ABCC) modular container and rack assembly. Issued 10/21/77.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	ST961SO	Replacement of the ball-bearing type right-hand engine throttle crossover cable with a reinforced wire type. Issued 11/15/77.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis International Airport Memphis, TN 38138
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST1001SO	Installation of Federal Express Corp. brake mount flange. Issued 6/6/78.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1163EA	Installation of Solar T-62T-40C APU. Amended 1/23/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1164EA	Installation of cabin air-conditioning flood duct. Amended 10/10/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1172EA	Installation of Hamilton Standard R72-3W air cycle machine, P/N 750660 Model 7/10 heat exchangers P/N 753355. Amended 3/20/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1213SW	Alteration for battery charging from ground power unit. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1435CE	Addition of improved autopilot static port systems. Issued 9/28/78.	CE	59270	MidCoast Aviation Service, Inc. Lambert Field P.O. Box 10254 St. Louis, MO 63145
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1461SW	Three Flite-Tronics PC-17A inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1462SW	Collins AP-105/FD-108/FD-109 autopilot/flight director system. Amended 9/28/78.	CE	24250	Rockwell International Collins Radio Group Collins Road Cedar Rapids, IA 52406
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1469SW	Fairchild stem system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1633SW	Three Avionics Instruments, Inc. 1A1000 inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1699SW	Solar T-62T-39 turbine APU. Issued 7/6/73.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1713SW	Couch installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1714SW	Galley installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1768SW	Gultcn proximity switch system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1885SW	Solar T62T-39 turbine APU. Issued 6/14/74.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1893SW	Landing light installation, alternate position. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1988SW	Jump seat. Issued 5/20/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1996SW	Installation of auxliliary landing lights. Issued 11/6/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2204SW	Installation of electronics rack. Issued 9/14/76.	SW	34280	Fancon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2232SW	Install Collins dual NCS-31 RNAV system. Issued 8/15/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2474SW	Horn silence switch. Issued 6/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2485SW	Fabrication and installation of three-place couch. Issued 8/5/77.	SW	34280	Falcon Jet Corporation LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C,D, E, F; T.C. A7EU	SH4095SW	Radio master system. Issued 3/4/80	SW	34280	Falcon Jet Corporation P.O. Box 6156 Little Rock, AR 72216
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA907CE	Battery temperature indicating and over temperature warning system. Amended June 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 E. Lewis Street Wichita, KS 67202
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA1483SW	Avionics installation (VHF communications, VHF navigation, ADF's DME's, transponders, weather radar radio altimeter, third attitude gyro). Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F, Falcon 10; T.C. A7EU, A10EU	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
Fan Jet Falcon Series C, D, E, F, Mystere 20; T.C. A7EU	SA119GL	Electrical cable harness assemblies for left and right engines; each consisting of starter-generator cables, starter-generator ground cable, master junction cable and fan tach sensor cable. Amended 2/6/78.	GL	37379	General Electric Company Aviation Service Operation/Cincinnati 260 West Mitchell Avenue Cincinnati, OH 44232
Fan Jet Falcon Series D; T.C. A7EU	SA918EA	Installation of Canadian Marconi CMA-712 doppler navigation system. Reissued 11/9/72.	EA	47665	Karr Electronics Corporation 232 Wescott Drive Rahway, NJ 07065
Fan Jet Falcon Series D; T.C. A7EU	SA993SW	Collins AP-104 Autopilot and FD-109H/FD-109F Flight Directors for Category I and II. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1327WE	Installation of dual inverters. Amended 3/18/69.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series D; T.C. A7EU	SW1467SW	Cargo interior. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1468SW	Openable window in co-pilot's side and qualifying existing pilot's and new co-pilot's windows as emergency exits. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1473SW	Replace passenger entrance door with wide cargo door. Amended 7/7/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA2640WE	Installation of a Garrett Model 75 area navigation system. Amended 9/18/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D; T.C. A7EU	SA3394WE	Replacement of cargo barrier net installed per STC SA1467SW with a rigid cargo barrier partition. Issued 7/11/77.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Blvd. Torrence, CA 92680
Fan Jet Falcon Series D, E; T.C. A7EU	SA1771SW	Installation of Sperry SPZ-200 autopilot/flight director control system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA1570SW	Collins AP105/FD108 autopilot/flight, flight director system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA1577WE	Installation of jump seat. Amended 10/19/70.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA2404SW	System to disable the take off out of trim warning system when hign power is applied during operation of thrust reversers.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA2588AWE	Installation of a Hoskins Model Mk III (Twilighter) anticollision lighting system. Amended 12/21/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
Fan Jet Falcon Series D, F; T.C. A7EU	SA1495SW	Installation of Fairchild voice, recorder model A100 and Lockheed flight recorder model 109C. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series D, F; T.C. A7EU	SA1806SW	Co-pilot brake modification. Issued 2/6/74.	SW	34810	Federal Express Corporation P.O. Box 493 Little Rock, AR 72203
Fan Jet Falcon Series D, F; T.C. A7EU	SA2344SW	Hartman Systems Co. vertical scale engine instruments. Issued 8/11/76.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series E; T.C. A7EU	SA3714WE	Revise existing interior to include three place side facing divan, galley, storage cabinet, three folding tables, cockpit door, stereo/flitephone cabinet, T.V./recorder cabinet and shoulder harness restraint for divan. Amended 11/22/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 E. Spring Street Long Beach, CA 90806
Fan Jet Falcon Series F; T.C. A7EU	SA1381SW	Installation of Teledyne Avionics normalized angle of attach system, Model 112B500. Amended 2/8/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon Series F; T.C. A7EU	SA1499SW	Installation of inverter system. Reissued 5/30/79.	SW	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series F; T.C. A7EU	SA1692SW	Modification of control pedestal. Reissued 5/30/79.	SW	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series F; T.C. A7EU	SA1892SW	Collins ALT-50 radio altimeter. Issued 6/27/74.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series F; T.C. A7EU	SA2479SW	Wiring and antenna provisions, and radio rack for Litton LTN-201 omega system. Issued 7/15/77.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Falcon 10; T.C. A33EU	SA142GL	Installation of radome kit 4128X. Issued 11/9/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, Oh 44309
Falcon 10; T.C. A33EU	ST902SO	Installation of Collins ground proximity warning system. Issued 7/28/76.	SO	24262	Collins Radio Group Rockwell International 1591 Phoenix Boulevard, Suite 1 Atlanta, GA 30349
Falcon 10; T.C. A33EU	SA1002EA	Installation of Sperry SPZ-500/SPI-77D flight control instrument system. Reissued 1/7/80.	SW	07498	Falcon Jet Corporation P.O. Box 167 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA1012EA	Installation of Teledyne Avionics normalized angle of attack indicating system, P/N 112B1600. Issued 8/21/75.	EA	78000	Teledyne Avionics A Division of Teledyne, Inc. P.O. Box 6400 Charlottesville, VA 22906
Falcon 10; T.C. A33EU	SA1042EA	Installation of hydraulically actuated target type thrust reverser system. Amended 7/11/78.	EA	39540	Grumman Aerospace Corporation Bethpage, L.I., NY 11714
Falcon 10; T.C. A33EU	SA1223CE	Install King KFC-300 dual flight director flight control system (Category I configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1224CE	Install King KFC-300 dual flight director flight control system (Category II configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1294CE	Installation of Avcon Industries TSC-C39a stretcher, P/N 4001-105 or -106. Issued January 1977.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 North Wichita Station Wichita, KS 67204
Falcon 10; T.C. A33EU	SA1993SW	Install wing ice lights. Issued 6/9/75.	SW	26230	Cooper Airmotive, Inc. Executive Aircraft Division Redbird Airport Dallas, TX 75232
Falcon 10; T.C. A33EU	SA2225SW	Passenger compartment interior. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2226SW	Pressurization of nose cone to improve avionics reliability. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2846WE	Installation of Pulstar two-light supplemental lighting system. Issued 3/4/74.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92705
Falcon 10; T.C. A33EU	SA2857WE	Avionics modification and installations of an 8-passenger executive interior arrangement. Reissued 1/4/78.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2885SW	Install three place couch at Station 181.0 to 239.0 right side. Issued 12/11/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
Falcon 10; T.C. A33EU	SA2919WE	Installation of TFE731-2 engines S/N P73143 and S/N P79101, modified in accordance with STC SE66WE. Issued 8/21/74.	WE	07502	AiResearch Aviation Company 402 S. 36th Street Phoenix, AZ 85034
Falcon 10; T.C. A33EU	SA2983WE	Installation of a Garrett AirNAV 100 area navigation system. Issued 1/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3061WE	Installation of a Garrett AirNAV 100 or 200 navigation system. Amended 10/26/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3544WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 1/27/78	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3557WE	Installation of DeVore Aviation Corp. tail floodlights. Issued 1/5/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Falcon 10; T.C. A33EU	SA3752WE	Installation of a communications components Ontrac III VLF/Omega navigation system. Issued 10/25/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA4015SW	Nose radio rack. Issued 7/12/79.	SW	34280	Falcon Jet Corporation P.O. Box 7001 Dallas, TX 75209
Falcon 10A; T.C. A33EU	ST153RM	Installation of Canadian Marconi CMA-734 Omega navigation system. Issued 9/11/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
Falcon 20; T.C. A7EU	ST823SO	Installation of SEMCA 14640-113 air conditioning valve. Reissued 7/23/75.	EA	42125	Hermetic Aircraft Instrument Corporation 200 Marine Street Farmingdale, L.I., NY 11735

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
S-2R (Restricted Category); T.C. A4SW	SA3899WE	Installation of Goodyear brake assembly P/N 95-50377 or P/N 5308865, Goodyear wheel assembly P/N 50-00444 or P/N 530884, and 11.00-13, Type III, 8 P.R. tire. Amended 6/15/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90907
S-2R (Restricted Category); T.C. A4SW	SA3890WE	Installation of Wright R-1820-40, -60, -71, -87 engine and Hamilton Standard 33D50 or 43D50 constant speed propeller. Amended 5/18/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
S-2R (Restricted Category); T.C. A4SW	SA3897WE	Installation of Pezetel Model PZL-3S engine and Dowty Rotol model CR289/3-110-F/1 propeller. Issued 4/11/79.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93905
S-2R; T.C. A3SW	SA3927WE	Installation of an AiResearch TPE331-1-1012 turboprop engine. Issued 5/11/79.	WE	75210	Floyd D. Stilwell 5060 East Falcon Drive Mexa, AZ 85205
S-2R; T.C. A4SW	SA3961WE	Installation of extended engine mount, revised cowling and induction system, Hamilton Standard 22D40 or 12D40 constant speed propeller, and modified elevator trim tab system. Issued 5/23/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R; T.C. A4SW	SA4039SW	Lycoming LTP-101-600A1A turboprop. Issued 9/25/79.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
S-2R; T.C. A4SW	SA4109WE	Installation of cockpit canopy/ fuselage fairing. Issued 3/7/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R; T.C. A4SW	SA4110WE	Installation of spring-type tail wheel strut assembly. Issued 3/7/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R (Restricted Category); T.C. A4SW	SA4111WE	Installation of Wright R-1820-71, -60; GR1820G-202A; 702C9GC1, 2, 3, 4; 704C9G1, 2, 3, 4 engines and Hamilton Standard 43D50 constant speed propeller. Issued 3/7/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R (S/N 2526R and up modified by STC SA3897WE), S-2R-R3S (S/N R3S-001 and up); T.C. A4SW	SA4038WE	Installation of second pilot's seat and dual controls. Issued 10/29/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category); T.C. A3SW	SA4045WE	Installation of second pilot's seat and dual controls. Issued 10/29/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up as modified by STC SA3897WE); T.C. A4SW	SA4046WE	Installation of passenger/cargo compartment. Issued 11/26/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category); T.C. A3SW	SA4047WE	Installation of passenger/cargo compartment. Issued 11/26/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R, S/N 2526R and up modified by STC SA3238WE, S-2R-T34 S/N 6009-6049, S/N T34-001 and up; T.C. A4SW	SA4107WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Issued 3/17/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R S/N 2526R and up modified by STC SA3237WE, S-2R-T34 S/N 6009-6049, S/N T34-001 and up (normal category); T.C. A3SW	SA4108WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Issued 3/17/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
600 S2SR, 800 S-2R; T.C. A4SW	SA266NW	Installation of automatic flagman Model No. 6. Amended 5/12/77.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S2R-T34 (Normal Category), S2R-T15 (Restricted Category); T.C. A3SW, A4SW	SA1073SO	Installation of a 500 gallon hopper vent blister kit. Issued 5/29/79.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
A35, B, C, D, E, F, G; T.C. 777	SA3113SW-D	Automatic flight system AK415 cons. of Century IIB autopilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35, A36TC; T.C. 3A15	SA3339SW	Installation of Mitchell automatic flight system Model AK809 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C35; T.C. A-777	SA236GL	Installation of a Continental O-470-G engine and McCauley propeller #2A36C23-11-DE/S-84B-0. Issued 5/4/78.	GL	74970	Robert Steffey 37344 Woodland New Baltimore, MI 48047
C35 thru H35, J35, K35, M35, N35, 35-33, 35-A33; T.C. A-777, 3A15	SA361EA	A. Installation of monitair angle of attack and stall warning kit number 92-107, and B. Installation of Monitair angle of attack and stall warning kit number 92-105. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
C35, D35, E35, F35, G35; T.C. A-777	SA604NW	Install Lycoming IO-540-K engine and Hartzell HC-E2YR-1BF/F8476D-4 propeller. Issued 7/6/78.	NW	52625	Machen, Inc. S.3608 Davison Boulevard Spokane, WA 99204
C35, D35, E35, F35, G35; T.C. A-777	SA1584CE	Installation of elevator tail cone fairing. Issued 4/15/80.	CE	73220	Smith Speed Conversions, Inc. P.O. Box 430 Johnson, KS 67855
C35, D35, E35, F35, G35; T.C. 777	SA3267SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. 777	SA3268SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. A-777	SA4000WE	Installation of radome in wing leading edge. Issued 7/27/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
E35; T.C. A-777	SA4043WE	Installation of Continental IO-520-BA engine and McCauley 3A32C propeller. Issued 10/26/79.	WE	06755	Aircraft Technical Service, Inc. 6701 Odessa Avenue Van Nuys, CA 91406
F35; T.C. 7777	SA173GL	Installation of Dukes fuel pump P/N 4140-00-39. Issued 5/27/77.	GL	01838	Aerodynamics, Inc. Oakland Pontiac Airport P.O. Box 508 Pontiac, MI 48056
H35, J35, K35, M35, N35, P35, S35, 35-33, -A33, -B33, -C33, -33A; T.C. 3A15	SA1-636	Install 300 Series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
H35 Series; T.C. 777	SA198NW	Installation of 3 bladed McCauley 3A34C76FM/S82NB-2 propeller with Woodward A210680 governor on Continental C-470-G engine. Issued 7/21/75.	NW	77570	Mel G. Taylor 20005 Northeast 13th Street Camas, WA 98607
H35 Series; T.C. 777	SA259NW	Installation of TCM continuous flow fuel injection system (EQ No. 5701) replacing carbureation system. Issued 2/17/76.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road South Seattle, WA 98108
35 Series H thru P; T.C. 3A15	SA470NW	Installation of Cessna oil filter. Issued 7/14/77.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road Seattle, WA 98108
H35, J35, K35, M-35, N-35, P35, 35-33, 35-A33, 35-B33, 35-C33, E33, F33; T.C. 3A15	SA695CE	Install Frantz oil filter. Amended 5/27/71.	GL	70360	Schmidt Aero Service Municipal Airport Worthington, MN 56187
H35, J35, K35, M35, N35, P35, S35, V35, V35B, 35-C33A, E33A, E33C, F33A, F33C, G33, 36, A36; T.C. 3A15	SA884SO	Installation of exhaust silencers. Issued 2/11/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, 35-33, E33, -A33, -C33; T.C. 3A15	SA975SW	Installation of cabin air conditioner. Reissued 5/7/79.	RM	01950	Aero Engineering Corporation 8C Garden Center Broomfield, CO 80020

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H35, J35, K35, M35, N35, P35, 35-33, 35-A33, -B33, -C33, E33, F33; T.C. 3A15	SA1252WE	Installation of Rajay turbocharged Continental O-470-G-C1 and/or IO-470-C, -J, -K, -N engines. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90807
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA1585CE	Installation of elevator tail cone fairing. Issued 4/15/80.	CE	73220	Smith Speed Conversions, Inc. Box 430 Johnson, KS 67855
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-33, -A33, -B33, -C33, -C33A, G33, -E33A, F33A, 35, A35; T.C. 3A15	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, M35, N35, P35, S35, V35, V35A, F33A, 35-33, -A33, -B33, -C33, -C33A, E33A, G33, 36, A36; T.C. 3A15	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33; T.C. 3A15	SA2870WE	Installation of right and left hand cockpit side windows. Reissued 2/2/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA3117SW-D	Mitchell automatic flight system AK328 cons. of Century I autopilot with optional omni tracker. Issued 3/16/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35; T.C. 3A15	SA3127SW-D	Mitchell automatic flight system AK415 cons. of Century IIB autopilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33C, F33A, G33, 36, A36; T.C. 3A15	SA3184WE	Installation of ventral air skeg. Amended 4/12/79.	WE	84396	Walker Engineering 2240 Sawtelle Boulevard Los Angeles, CA 90064
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B (Utility Category); T.C. 3A15	SA3190WE	Installation of wing tip fences. Issued 5/11/76.	WE	64690	JOhn Pixton Enterprises P.O. Box 342 Santa Rosa, CA 95402
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3269SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3270SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35; T.C. 3A15	SA3310WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/6/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, 35-33, -A33, -B33, -C33; T.C. 3A15	SA3523WE	Installation of an airfoil separator in the engine breather system. Issued 11/25/77.	WE	84396	Walker Engineering Co. 2240 Sawtelle Los Angeles, CA 90025
H35, J35, K35, M35, N35, P35, S35, V35, E33, E33A, E33C, F33, F33A, F33C, G33, V35A, V35B, 36, A36, A36TC; T.C. 3A15	SA3999WE	Installation of radome in wing leading edge. Amended 8/14/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA4100WE	Installation of DIL-1000, -1001 and/or -1002/3 cautopilot adapters for the Edo-Aire Mitchell Century III autopilot. Issued 2/12/80.	WE	47775	Douglas L. Kettler 1212 North Broadway, Apt. B Escondido, CA 92026

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J35; T.C. 3A15	SA686CE	Install Continental IO-520-V engine derated to 250 H.P. and Hartzell HC-C3YF-1/8468A-8R propellers. Reissued March 1975.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
J35, K35, M35, 35-33; T.C. 3A15	SA1-354	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
J35, V35, A35, B35, C35, D35, E35, F35, G35; T.C. 3A15, 777	SA754SW	Mitchell automatic aileron stabilizer AK203.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
J35, K35, M35, N35, P35, S35, V35, V35B, E33, E33A, F33, F33A, 36, A36, 35-33, -A33, -B33, -C33, E33C, F33C, -C33A, V35A; T.C. 3A15	SA1474CE	Installation of redundant engine fuel flow transmitter and cockpit indicator. Reissued 4/24/79.	WE	71740	Silver Instruments, Inc. 2436 Stanwell Drive Concord, CA 94520
J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2978WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA1140CE	Installation of King model KFC-200 2-axis (3 optional) autopilot system with a King KCS-55 (or -55A) compass with a King KI-255 (or KI-256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 7/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M35; T.C. 3A15	SA958EA	Installation of Teledyne Continental IO-520-Ba Engine and associated components in place of Teledyne Continental IO-470-C engine and associated components. Issued 7/30/73.	EA	41760	Helicopter & Airplane Service Corp. Montgomery County Airpark Gaithersburg, MD 20760
N35, P35, S35; T.C. 3A15	SA134EA	15-gallon fiberglass wing tip fuel tanks. Reissued 2/6/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
P35, 35-B33; T.C. 3A15	SA178EA	Installation of Monitair angle of attach system, Model AA-2. REissued.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, 35-B33; T.C. 3A15	SA260EA	Installation of Monitair angle of attack and stall warning kit number 92-110. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, V35, V35A, V35B; T.C. 3A15	SA3203WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/24/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
S35, V35, V35A, V35B, 35-B33, 35-C33, 35-C33A, E33, E33A, F33, F33A, G33, 36, A36, A36TC; T.C. 3A15	SA180GL	Install Norton Company radar pod P/N 4133X. Amended 8/22/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
S35, V35, V35A, V35B, 35-B33, -C33, -C33A, E33, E33A, F33, F33A, F33C, G33, 36, A36, A36TC; T.C. 3A15	SA328GL	Installation of radome kit No. 4222X. Amended 9/26/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
S35, V35; T.C. 3A15	SA352EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
S35, V35, V35A, V35B; T.C. 3A15	SA468SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and flight director indicator DH-841( ). Amended 11/14/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S35, V35, V35B, 35-C33A, E33A, E33C, 36, A36, F33A, F33C;	SA785CE	Installation of Hartzell Propellers PHC-C3YF-1R/8468-6R, 8468A-6R, PHC-C3YF-1RF/F8468A-6R and BHC-C2YF-1B/8468AR, BHC-C2YF-1BF/F8468AR and spinners A2295-1 and A2295. Amended 3/5/80.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, Oh 45356
S35, V35, V35A, V35B; T.C. 3A15	SA1069SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director. Issued 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
S35, V35, V35A, V35B; T.C. 3A15	SA1417CE	Install elevator tail cone fairings. Issued 5/17/78.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
S35 S/N D7482 thru D796, V35, V35A, V35B; T.C. 3A15	SA1744SW	Mitchell automatic flight system AK409 cons. of Century I autopilot with optional omni tracker. Issued 10/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2556WE	Installation of Rajay turbosupercharged Continental TSIO-520-D engine. Amended 11/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
S35, V35, V35A, V35B, 35-C33A, E33C, F33A, F33C, 36, A36; T.C. 3A15	SA2935WE	Installation of Model DFF-5000 fuel monitor. Issued 10/25/74.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545
S35, V35, V35A, V35B; T.C. 3A15	SA3159SW-D	Automatic flight system AK409, consisting of Century I autopilot with opticnal omni tracker. Issued 10/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3172SW-D	Yaw damper Model YK631. Issued 12/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3272SW-D	Mitchell automatic flight system AK501 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/10/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3292SW-D	Mitchell command electric trim AK726. Issued 7/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, B; T.C. 3A15	SA3310SW-D	Installation of Mitchell automatic flight system AK804 consisting of Century 41 autopilot or AK804FD consisting of Century 41 autopilot flight director. Issued 11/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, B; T.C. 3A15	SA3324SW-D	Installation of Mitchell automatic flight system AK803 consisting of Century 21 autopilot. Issued 12/6/78.	SW	60000	Mitchell Industries,Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3327SW	Installation of Mitchell automatic flight system AK805 consisting of Century 21 autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
SA-35, V35, V35A, V35B; T.C. 3A15	SA3328SW	Installation of Mitchell automatic flight system AK806/FD consisting of Century 41/flight director autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35A, F33A, F33C, 36, A36; T.C. 3A15	SA3548WE	Installation of air/oil separator. Amended 4/28/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90025
S35, V35, V35A, V35B; T.C. 3A15	SA3668WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 7/13/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
V35; T.C. 3A15	SA503NW	Installation of Robertson STOL kit. Issued 9/7/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
V35; T.C. 3A15	SA707NW	Add RCA Primus weather radar. Issued 1/11/79.	NW	68500	Robertson Aircraft Corp. 839 West Perimeter Road Renton, WA 98055
V35, V35A; T.C. 3A15	SA925SW	Mitchell Automatic Flight System AK263 cons. of Century II autopilot with radic coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1185CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	NW	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
V35, V35A, V35B; T.C. 3A15	SA1186CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	NW	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
V35, V35A, V35B; T.C. 3A15	SA1500SW	Mitchell automatic flight system FD/AF282-382 cons. of flight director/autopilot with automatic command electric pitch trim. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1501SW	Mitchell automatic flight system AK383 cons. of Century III autopilot with optional automatic command electric trim, radio coupler, and glide slope coupler. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1722SW	Mitchell automatic flight system AK402, cons. of Century IIB autopilot with optional radio coupler. Issued 8/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3034SW-D	Mitchell automatic flight system AK503 or AK503FD cons. of Century IV autopilot or Century IV flight director autopilot with command/auto. electronic trim and annuciator panel. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3035SW-D	Mitchell automatic flight system AK501 cons. of Century III autopilot with optional command/auto. elec. pitch trim, radio, and glide slope coupler. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA4085SW	S-TEC System 60 (single axis) flight guidance system model ST-001. Issued 2/22/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Walters Industrial Complex Mineral Wells, TX 76067
V35A; T.C. 3A15	SA882SW	Mitchell automatic flight system AK260 consisting of Century III autopilot, optional radio coupler, automatic pitch trim, stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35A; T.C. 3A15	SA2030WE	Installation of Brittain B-VII, NAV-2B, B2C and BSA-4 Flight Control Systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, E33 and E33A; T.C. 3A15	SA1858WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, V35B, S35, F33A, A36; T.C. 3A15	SA3824WE	Installation of SDI Model CFS-1000-1001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714
V35B (Utility Category); T.C. 3A15	SA2947WE	Installation of Collins AP-107 autopilot and FD-106 PV flight director. Reissued 4/22/75.	NW	24250	Collins Radio Group Rockwell International Cedar Rapids Airport Cedar Rapis, IA 32406
V35B; T.C. 3A15	SA3215SW-D	Mitchell automatic flight system AK671 consisting of Century I autopilot with optional omni tracker. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
V35B; T.C. 3A15	SA3216SW-D	Mitchell automatic flight system AK672 consisting of Century IIB autopilot with optional radio coupler. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3217SW-D	Mitchell automatic flight system AK673 consisting of Century III autopilot with optional radio coupler and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3218SW-D	Mitchell automatic flight system AK674 consisting of Century IV autopilot or AK674FD consisting of Century IV flight director autopilot with remote annunciator. Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3219SW-D	Mitchell command electric trim system AK675. Issued 8/9/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3220SW-D	Mitchell yaw damper system YK676 Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
V35B, A36, F33; T.C. 3A15	SA3683WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
35-33 Series; T.C. 3A15	SA1808WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33 Series; T.C. 3A15	SA1886WE	Installation of Brittain Industries NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3098SW-D	Mitchell automatic flight system AK306 cons. of Century I autopilot with optional omni tracker. Issued 1/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3107WE	Installation of exhaust silencer. Reissued 2/9/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA1036EA	Installation of vertical tail floodlights on upper surfaces of the horizontal stabilizer. Amended 4/9/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
35-33, 35-A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A36TC; T.C. 3A15	SA1416CE	Install flap and aileron fairings and seals. Amended 3/24/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
35-A33; T.C. 3A15	SA270EA	Installation of a stability augmentation safety system (with or without camera system installed). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-A33; T.C. 3A15	SA1310CE	Chrome-plated brake disc installation. Issued 6/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
35-B33, -C33A; T.C. 3A15	SA1289CE	Install King KFC-200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/21/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
35-C33, F33; T.C. 3A15	SA238GL	Installation of Continental IO-470-N engine and McCauley 2A36C23/84B-0 propeller. Amended 11/14/78.	GL	39517	Stewart Gross P.O. Box 634 Rochester, MN 55901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35-C33, 35-C33A; T.C. 3A15	SA394EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-C33; T.C. 3A15	SA896SW	Mitchell automatic flight system AK264 cons. of Century III autopilot with optional automatic aileron stabilizer, radio and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33, E33, F33; T.C. 3A15	SA1218SW	Automatic flight system AK306 cons. of Century I and optional tracking system. Issued 11/10/70.	SW	60000	Mitchell Industries, Inc. P.O. box 610 Municipal Airport Mineral Wells, TX 76067
35-C33, E33, F33; T.C. 3A15	SA1365SW	Mitchell automatic flight system model AK347 cons. of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA1366SW	Mitchell automatic flight system model AK316, cons. of Century III autopilot with optional automatic pitch trim, radio coupler, glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3163SW-D	Install automatic flight system AK316 consisting of Century III autopilot with optional command automatic pitch trim system, radio coupler, and glide slope coupler. Issued 11/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3204WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 12/20/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3248SW-D	Mitchell automatic flight system AK716 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 10/3/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
E33, E33A, E33C, F33, F33A, F33C; T.C. 3A15	SA1550CE	Installation of elevator and rudder tail cone fairings. Issued 2/29/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 61 Johnson, KS 67855
E33, -A, -C; F33, -A, -C; T.C. 3A15	SA2057WE	Installation of Brittain Industries B-VII, HAV-2B, B2C and BSA4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
F33A; T.C. 3A15	SA1164CE	Installation of King KFC-200 two axis autopilot system with King KI-255 (or -256) flight command indicator or King KG-258 altitude horizon indicator with a KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
F33A; T.C. 3A15	SA3230SW-D	Mitchell automatic flight system AK660, consisting of Century IIB autopilot with optional radio coupler. Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3232SW-D	Mitchell automatic flight system AK662, consisting of Century IV autopilot or AK662FD consisting of Century IV flight director with optional remote annunicator. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3229SW-D	Mitchell automatic flight system AK659 consisting of Century I autopilot with optional omni tracker. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. box 610 Mineral Wells, Tx 76067
F33A; T.C. 3A15	SA3231SW-D	Mitchell automatic flight system AK661, consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F33A; T.C. 3A15	SA3233SW-D	Mitchell command electric trim AK663. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3234SW-D	Mitchell yaw damper system K664 Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3348SW	Installation of Mitchell automatic flight system AK821/FD consisting of Century 41/flight director autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3349SW	Installation of Mitchell automatic flight system AK820 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, G33, 36, A36; T.C. 3A15	SA480SO	Installation of Bendix FCS-810 automatic flight control system, including manual electrim trim and flight director indicator DH-841( ). Amended 10/4/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
F33A, S/N CE-316 & up; T.C. 3A15	SA1232SW	Mitchell automatic flight system AK315 cons. of Century III with optional automatic pitch trim, radio and glide slope coupler. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, E33A, 35-C33A, F33C; T.C. 3A15	SA1233SW	Mitchell automatic flight system AK317 cons. of Century I and optional tracking system. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1865SW	Mitchell automatic flight system AK448, Century IV autopilot and AK448FD, Century IV flight director with electronic command/automatic pitch trim. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1866SW	Mitchell automatic flight system AK452 cons. of Century III autopilot with optional electronic command/automatic pitch trim, radio coupler, and glide slope coupler. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA3087SW-D	Mitchell command electric trim AK563. Issued 12/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, 36A; T.C. 3A15	SA3193SW-D	Mitchell automatic flight system AK452 consisting of Century III autopilot with optional command automatic electronic pitch trim, radio, glide slope coupler. Issued 4/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G33; T.C. 3A15	SA571EA	Installation of Brittain Industries Models B7, NAV-2B, B2C and BSA4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
G33; T.C. 3A15	SA818CE	Install Hartzell propeller model BHC-I2YF-1BF/F8468AR with spinners A2295, or model PHC-L3YF-1RF/F8468A-6R with spinners A2295-1. Issued 1/14/72.	SW	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
35/36 Series; T.C. 3A15	SA1711WE	Installation of Brittain Industries B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35/36 Series; T.C. 3A15	SA1712WE	Installation of Brittain Industries BSA-4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
35, 50 Series; T.C. 777, 3A15, 5A4	SA856WE	Glassfiber reinforced plastic wing tips.	WE	00450	ACKO P.O. Box 1431 Torrance, CA 90510
35, 50 Series; T.C. 777, 3A15, 5A4	SA998WE	Glass fiber reinforced plastic wing tips. Amended 6/13/69.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, 95 Series; T.C. 777, 3A15, 3A16	SA1-381	Installation of Fram Oil Filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
35, 95 Series; T.C. 777, 3A15, 3A16	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
36 Series; T.C. 3A15	SA961SW	Mitchell automatic flight system AK275 cons. of Century III autopilot with optional radio coupler, automatic pitch trim, aileron stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36 Series; T.C. 3A15	SA1916WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
36; T.C. 3A15	SA2068WE	Installation of Brittain Models B-VII, NAV-2B, B2C and BSA-4 flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
A36; T.C. 3A15	SA3206SW-D	Mitchell command electric trim model AK669. Issued 6/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1145CE	Installation of King Model KFC-200, 2 axis (3 optional) or stand alone yaw damper for Beech Model A36 S/N E572 and later autopilot system with a King KI-255 (KI-256 optional) flight command indicator with the KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
36, A36; T.C. 3A15	SA1231SW	Mitchell automatic flight system model AK311, cons. of Century II autopilot with optional radio coupler. Issued 12/8/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1360SW	Mitchell automatic flight system Model AK346 cons. of Century III autopilot with optional pitch trim, radio coupler, and glide slope coupler. Issued 8/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1634SW	Mitchell AK423 cons. of 1C707 omni/localizer converter. Issued 3/27/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1635SW	Mitchell AK417/FD cons. of flight director/autopilot with command electric trim. Issued 3/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3118SW-D	Automatic flight system AK448, Century IV autopilot or AK448FD, Century IV autopilot flight director with optional remote annuciator. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3119SW-D	Automatic flight system AK452 cons. of Century III autopilot with optional command/automatic electronic elevator pitch trim, radio and glide slope couplers. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3244WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 8/11/76.	WE	12380	Astronautics Corp. of America 2416 Ameler Street Torrance, CA 90505
36, A36, A36TC; T.C. 3A15	SA1448CE	Installation of elevator tail cone fairing. Amended 3/24/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
A36, Serial No. E185 and up; T.C. 3A15	SA84RM	Installation of freon type air conditioning system. Amended 3/21/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A36; T.C. 3A15	SA283GL	Installation of a Continental IO-520-B, -BA engine modified in in accordance with STC SA282GL and a Symbolic Displays fuel flow indicating system, Model CFS-1000. Issued 11/14/78.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport Rockford, IL 61109
A36; T.C. 3A15	SA1093CE	Installation of AP-107 (2 axis) autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	NW	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1095CE	Installation of AP-106 autopilot system and interface with Collins 329A-4V indicator. Amended July 1975.	NW	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1096CE	Installation of yaw damper system. Issued April 1975.	NW	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1097CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	NW	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1544CE	Installation of microwave landing system. Issued 1/22/80.	SW	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
A36; T.C. 3A15	SA3203SW-D	Mitchell yaw damper model YK670 Issued 5/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3204SW-D	Mitchell automatic flight system AK668 consisting of Century IV autopilot or AK668FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 5/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3205SW-D	Automatic flight system AK667 consisting of Century III autopilot with optional radio coupler and Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3207SW-D	Mitchell automatic flight system consisting of Century I autopilot with optional omni tracker. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3208SW-D	Mitchell automatic flight system AK666 consisting of Century IIB autopilot with optional radio coupler. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3340SO	Mitchell automatic flight system AK810 consisting of Century 41 flight director autopilot. Issued 7/25/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36; T.C. 3A15	SA4106WE	Modification of the rudder and brake systems to provide hand controls in addition to the conventional systems. Issued 3/25/80.	WE	05225	Aircraft Inspection & Maintenance, Inc. 2680 East Wardlaw Road Long Beach, CA 90807
A36, A36TC; T.C. 3A15	SA1106SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and option yaw damper and flight director. Issued 10/11/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
A36, A36TC; T.C. 3A15	SA1496CE	Installation of King KFC 200 automatic flight control system. Amended 7/18/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
A36, A36TC; T.C. 3A15	SA1527CE-D	Installation of King KAS 297 altitude selector option. Issued 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
A36TC; T.C. 3A15	SA3329SW-D	Mitchell automatic flight system AK754 consisting of Century IV autopilot or Model AK754FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 1/2/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A36TC; T.C. 3A15	SA3330SW-D	Mitchell automatic flight system AK753, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/2/79.	SW	60000	Mitchel Industries, Inc. P.O. Box 610 Mineral Wells, TX 75056
A36TC; T.C. 3A15	SA4114WE	Installation of Silver Instruments Fueltron IG or IP digital fuel flow and totalizer system. Issued 2/26/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
45 Series; T.C. 5A3	SA366WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
45 Series; T.C. 5A3	SA425SW	Nose landing gear door removal.	SW	22700	Civil Air Patrol Corporation National Headquarters Ellington AFB, TX 77030
A-45 (T-34A, B-45); T.C. 5A3	SA876CE	Remove Continental O-470-13 or O-470-13A engine and propeller. Install Continental IO-470-N engine and Hartzell BHC-L2YF-FC846AR propeller. Issued December 1972.	CE	15250	Beech Aircraft Corporation 9709 East Central Wichita, KS 67206
A-45 (T-34A, B-45); T.C. 5A3	SA2211SW	Mitchell Century I Model AK409 autopilot with omni tracker. Issued 7/17/75.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA1864SW	Continental IO-520-B engine and McCauley 3A32C76/82NB-2 propeller. Issued 4/11/74.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA3191SW-D	Mitchell automatic flight system AK649 consisting of Century I autopilot with optional omni tracking system. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A45; T.C. 5A3	SA3192SW-D	Automatic flight system AK651 consisting of Century IIB autopilot with optional radio coupler. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D45; T.C. 5A3	SA183GL	Modification of basic aircraft for Restricted Category Airworthiness Certification by removing rudder-aileron bungee interconnect system, elevator down spring system and tail cone fairing. Issued 6/21/77.	GL	61302	Michigan Dept. of Natural Resource Stevens T. Mason Bldg. Lansing, MI 48926
50 Series; T.C. 5A4	SA1-262	Bendix Pioneer 9100-17-C1 fuel flow meter system.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series; T.C. 5A4	SA1-291	Radio shelves in nose baggage shelves.	EA	15210	Beckett Aviation Corporation Allegheny County Airport Dravosburg, PA 15034
50 Series; T.C. 5A4	SA1-357	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series; T.C. 5A4	SA1-443	2002X-R radome assembly.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
50 Series; T.C. 5A4	SA1-503	Electrothermal propeller deicing system. (Applicable to aircraft with two 50-amp. generators or greater.)	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series; T.C. 5A4	SA3-208	Acron B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA3-703	Accumulator for unfeathering Hartzell HC-83XF, HC-93Z20 or HC-B3Z20 propellers.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA4-51	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50 Series; T.C. 5A4	SA4-221	Autopilot L-2.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-382	Radio rack.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
50 Series; T.C. 5A4	SA4-439	Fiberglass reinforced plastic wing tips.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
50 Series; T.C. 5A4	SA4-462	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-549	Federal F-400 autopilot.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
50 Series; T.C. 5A4	SA4-758	Aerofilter 30690B full flow lube oil filter with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
50 Series; T.C. 5A4	SA4-807	Automatic rudder control Model B.	GL	49858	Lear, Inc. 3714 Jefferson Avenue, S.E. Grand Rapids, MI 49501
50 Series; T.C. 5A4	SA4-808	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-1417	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA3CE	Governor 210385. (Not eligible with accumulator unfeathering system.)	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA5CE	Propeller governors incorporating unfeathering accumulator shutoff valves. (Eligible only on aircraft equipped with Beech unfeathering system.)	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA24SW	Cabin seats. (Seat tracks installation per STC SA2-1068 required.)	SW	83650	Vicars Custom Aircraft Interiors 3709 N. Main Fort Worth, TX 76101
50 Series; T.C. 5A4	SA25CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA31SW	Automatic pilot AK104.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA41CE	Governor 210159.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA75SW	Landing gear doors. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA76SW	Lycoming IGSO-540-B1A engines with associated powerplant changes, and landing gear doors; increase gross weight to 7,300 lbs. takeoff and 7,000 lbs. landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, Tx 78216
50 Series; T.C. 5A4	SA81SW	Automatic pilot AK119.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA158EA	Autopilot T-3 and altitude hold AH-1 as an accessory item.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series; T.C. 5A4	SA166CE	Twin-engine electronic synchronizer and unfeathering system.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50 Series; T.C. 5A4	SA167CE	Electronic synchronizer kit.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA198SW	Three-place couch.	SW	85128	Westernair of Albuquerque, Inc. Route 6, Box 88 Albuquerque, NM 87101
50 Series; T.C. 5A4	SA207SW	Dual control. (Pilot's and co-copilot's seat installations per STC SA2-1066 required.) Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA213CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA242SW	Lycoming GO-480-G2D6 engines and increase in gross weight to 6,300 pounds. Reissued February 1973.	GL	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA323EA	7541K nose cap weather radome.	NE	53750	McMillan Radiation Labs, Inc. Brownville Avenue Ipswich, MA 01938
50 Series; T.C. 5A4	SA348SW	Radar nose. Reissued February 1973.	GL	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA360SW	GO-480-G2D6 or -G2F6 engines and increase in weight to 6,000 pounds. Reissued February 1973.	GL	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA370SW	Seven place seating capacity.	SW	80625	United Airmotive 1105 DeRidder Fort Worth, TX 76106
50 Series; T.C. 5A4	SA392WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA430SW	Pilot and copilot cockpit seats.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
50 Series; T.C. 5A4	SA405WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA433SW	Cabin door and stair.	SW	27242	Cross Roads Aviation, Inc. Addison Airport Addison, TX 75001
50 Series; T.C. 5A4	SA514SW	Six place seat and/or hat sheif.	SW	36125	Flying V Interiors Meacham Field Fort Worth, TX 76106
50 Series; T.C. 5A4	SA517SW	Goodrich wheel and brake. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA587SW	Lycoming IO-720-A1A engines, increase gross weight 7,600 pounds, 7,240 pounds landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA655SW	Lycoming IGSO-480-A1A6 engine; wing, vertical tail, landing gear modified, control system increased gross weight to 7,300 pounds takeoff, and 7,000 pounds landing.	SW	27242	Cross Roads Aviation, Inc. P.O. Box 60464 AMF Houston, TX 77060
50 Series; T.C. 5A4	SA1013WE	Advanced Army Aircraft Instrumentation System (AAAIS) and associated aircraft modifications.	WE	30400	Douglas Aircraft Company, Inc. 3855 Lakewood Boulevard Long Beach, CA 90801
50 Series; T.C. 5A4	SA1324WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA1385WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA1-565	Installation of radome kit No. 2002X. Amended 2/24/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA99CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights Model 1 or 2. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGAw Avenue Irvine, CA 92705
50, B50, C50, D50, D50A, D50B, D50C, D50E-5990, D50E, E50E, F50, G50, H50, J50; T.C. 5A4	SA276GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 1/17/79.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA383CE	Installation of Hoskins Twi. III supplementary high intensity lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
50, B50 thru J50, D50A, B, C, D, E; 65, 65-80, 65-A8800, 65-B80 all; T.C. 5A4, 3A20	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA1644WE	Installation of a Torginol Special Product Co. KarBar.	RM	25250	Combs Aircraft, Inc. Stapleton International Airport Denver, CO 80207
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA2631WE	Installation of Bellon Concrete, Inc. single piece windshield or alternate single piece sloped windshield. Amended 3/20/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4550 Jettridge Drive Atlanta, GA 30327
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA2872WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
B50, C50, D50; T.C. 5A4	SA2413WE	Modification of fuel vent outlet. Issued 9/3/71.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
C50; T.C. 5A4	SA3062SW-D	Mitchell AK370 cons. of Century III autopilot with command/automatic electronic pitch trim system, optional radio coupler, and glide slope coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C50; T.C. 5A4	SA3063SW-D	Mitchell automatic flight system AK542 cons. of Century IIB autopilot with optional radio coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, D50C, E50, F50, G50, H50; T.C. 5A4	SA1-453	Installation of Tactair T-3 automatic pilot and optional installation of Tactain AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
D50, D50A, B, C, E; T.C. 5A4	SA3138SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3139SW-D	Mitchell automatic flight system AK613, consisting of Century IIB autopilot with optional radio coupler. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3140SW-D	Mitchell automatic flight system AK606, consisting of Century I autopilot with optional omni tracker. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50 - modified - Excaliber STC SA5878W; 56TC, A56TC, 58, 58A, 58P, 58PA, 58TC, 58TCA, 60, A60, B60; 65, A65, 65-80, -A80, -A80-8800, -B80, -88, -70 modified - Excalibur STC SA444SW; 95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A (95-55, -A55, -B55 modified - Colemill STC SA4328O; T.C. 5A4, 3A16, A12CE, A23CE, 3A20, 3A16	SA20GL	Installation of Woodward Type III electronic propeller synchronizer or synchrophaser system. Amended 9/25/78.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
D50C, E; T.C. 5A3	SA1334SW	Mitchell automatic flight system AK337, cons. of Century II autopilot with optional radio coupler. Issued 7/1/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA31WE	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
D50E; T.C. 5A4	SA33WE	Autopilot M-4.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
D50E; T.C. 5A4	SA391WE	Installation of Brittain Model B2D Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D50E; T.C. 5A4	SA837SW	Mitchell AK255 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA974CE	Installation of KNR 665 digital area navigation system. Amended May 1974.	CE	48250	King Radio Corporation Box 106 Olathe, KS 66061
E50, F50, G50, H50, J50; 80, A80, 65; T.C. 5A4, 3A20	SA1686WE	Installation of Vibration Isolation Products engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
50, 65 Series; T.C. 5A4, 3A20	SA15EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50, 65 Series; T.C. 5A4, 3A20	SA476EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
55, A55; B55, C55, D55, 56TC; 65-B80, A65-8200, 65-90, A90; 95, B95, B95A, D-95A, E95; T.C. 3A16, 3A20	SA1874WE	Installation of Brittain up-command signal adapter kit on certain airplanes equipped with Brittain models B-4A, B-4AP, B-5 and B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA681CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114
B55, C55; 95 Series; T.C. 3A16	SA1591WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1548WE	Installation of a Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1934WE	Installation of an approach speed control system. Reissued 12/4/69.	EA	69500	Safe Flight Instrument Corp. Box 550 White Plains, NY 10602
D55, E55, E55A, 56TC, A56TC, 58, 58A, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 58P, 58PA, 58TC; TC 3A16	SA453SO	Installation of Bendix Model FCS 810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 10/19/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D-55, D55A, E55, E55A, 58, 58A, 56TC, A56TC, 95; T.C. 3A16	SA2048WE	Installation of Brittain Industries Model B-VII or NAV-2B or B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55, D55A, E55, E55A, 56TC, 58, 58A, 95, B95, B95A, D95A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A; T.C. 3A16	SA2871WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
E55; T.C. 3A16	SA126GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
E55; T.C. 3A16	SA896SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 4/22/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, Fl 33310
E55; T.C. 3A16	SA3068WE	Installation of fuel flow instruments. Issued 8/8/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1126CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE982 and up); T.C. 3A16	SA1127CE	Installation of Collins AP-107 (2 axis) autopilot systems. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1128CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55, 58; T.C. 3A16	SA1008CE	Installation of an electric motor driven freon vapor cycle air conditioning system. Amended 10/9/74.	CE	02950	Aero Space Controls 1050 N. Mosley Wichita, KS 67214
56TC; T.C. 3A16	SA383SO	Installation of Bendix M-4C autopilot flight control system. Amended 7/14/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, Fl 33309
56TC; T.C. 3A16	SA632CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114
56TC; T.C. 3A16	SA713CE	Conversion of wing tips to integral fuel tanks.	CE	16292	Frank R. Berry and William T. McKay Route 1, Box 204A Augusta, KS 67010
56TC; T.C. 3A16	SA1770WE	Installation of Brittain Industries Models B-5 or NAV-2B or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
56TC, A56TC; T.C. 3A16	SA1041CE	Replace existing nickel-cadmium battery with lead-acid battery. Issued January 1975.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
56 TC; 95 Series; T.C. 3A15, 3A16	SA1585WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
58 Series; T.C. 3A16	SA860EA	Installation of Aircraft Radio Corp. AF-530A automatic pilot system and electric operated elevator trim system. Amended 1/18/71.	EA	05950	Aircraft Radio Corporation Rockaway Valley Road Boonton, NJ 07005
58 Series; T.C. 3A16	SA1174SW	Mitchell automatic flight system FD/AF282-303 cons. of flight director/autopilot, automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1175SW	Auto flight system AK303 cons. of Century III, autopilot, with optional auto pitch trim, radio, and glide slope couplers. Issued 7/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1192SW	LN2 air conditioner system. Issued 9/22/70.	SW	83100	Ves-Kol Inc. 2805 National Drive Garland, TX 75040

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
58 Series; T.C. 3A16	SA1199SW	Mitchell automatic flight system 305 cons. of Century II autopilot with optional stabilizer and radio coupler. Issued 10/2/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA3119WE	Installation of Pathfinder autopilot systems. Issued 12/16/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
58, 58A; T.C. 3A16	SA94RM	Installation of freon type air conditioning system. Issued 3/24/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
58, 58A; T.C. 3A16	SA1045CE	Installation of Collins Radio Co. AP-107 autopilot system (2 axis). Amended February 1975.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1106CE-D	Installation of Collins Radio Group AP-106 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1107CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1108CE-D	Installation of Collins Radio Group AP-107 axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1687SW	Mitchell automatic flight system Model YK428 cons. of yaw damper. Issued 6/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1786SW	Mitchell Automatic Flight System AK451 cons. of Century III Autopilot with Electronic Pitch Trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1787SW	Mitchell Automatic Flight System AK447 cons. of Century IV Autopilot or AK447FD cons. of Century IV/Flight Director with Electronic Command/Automatic Pitch trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3131SW-D	Mitchell automatic flight system AK447, Century IV autopilot or AK447FD Century IV flight director autopilot with remote annuciator. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3132SW-D	Mitchell automatic flight system AK451, consisting of Century III autopilot with optional command automatic electric pitch trim, radio and glide slope couplers. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3341SW	Mitchell yaw damper systems, YK781. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3342SW	Mitchell automatic flight system AK816/FD consisting of Century 41/flight director autopilot. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3350SW	Installation of Mitchell automatic flight system AK815 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A, 58P, 58PA, 58TC, 58TCA, 65-80, -A80, -B80, -88, 95-C55, -C55A, D55, D55A, E55, E55A; T.C. A23, 3A20, 3A16	SA300CE	Installation of Woodward propeller governor on single and twin engine airplanes. Amended 9/18/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
58, 58A, TH-1 and up; T.C. 3A16	SA863CE	Installation of Airborne/Goodyear pneumatic iceguard deicing system. Issued August 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
58, 58A, 95-B55, -B55A; T.C. 3A16	SA935SO	Installation of a Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Amended 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
58, 58A, 95-B55, -B55A; T.C. 3A16	SA936SO	Installation of Bendix NP-2041A area navigation computer programmer. Amended 4/10/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
58P; T.C. A23CE	SA113GL	Installation of radome kit 4109X. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA978SO	Installation of NP-2041A area navigation computer programmer. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA979SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
58P, 58PA, 58TC, 58 TCA; T.C. A23CE	SA1123CE	Install AP-106 autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1124CE	Install AP-107 (2 axis) autopilot and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1125CE	Install AP-107 (3 axis) autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1524CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3038SW-D	Mitchell automatic flight system AK449 or AK449FD cons. of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim and optional remote annuciator panel. Issued 1/17/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3039SW-D	Automatic flight system YK445 yaw damper system. Issued 1/17/75.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3040SW-D	Automatic flight system AK453 consisting of Century III autopilot optional command/automatic elecelectronic pitch trim system, radio and glide slope couplers. Issued 2/5/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3311SW-D	Mitchell automatic flight system AK453 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/22/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3338SW-D	Mitchell automatic flight system system AK813 consisting of Century 41 autopilot or AK813FD consisting 41 flight director autopilot with optional remote annunciator. Issued 4/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3344SW	Mitchell yaw damper system YK781. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3499WE	Installation of tail flood lights on horizontal stabilizer. Issued 9/30/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
58P, 58TC; T.C. A23CE	SA178GL	Install Cleveland conversion kit, P/N 199-73. Issued 5/23/77.	GL	23260	Cleveland Wheels and Brakes VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011
58P, 58TC; T.C. A23CE	SA3769WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
58P, 58TC, 58TCA; T.C. A23CE	SA4050WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Reissued 3/25/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
58TC; T.C. A23CE	SA124GL	Install Norton Company radome, P/N 4083X. Amended 2/21/79.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
60 Series; T.C. A12CE	SA1006SW	Mitchell Automatic Flight System AK291, cons. of Century III autopilot with optional pitch trim servo, radio and glide slope couplers.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60; T.C. A12CE	SA659SO	Installation of Bendix M-4C automatic flight control system, including manual electric trim, and/or installation of Bendix YD-4 yaw damper. Amended 11/10/72.	SO	15475	Bendix Avionics P.O. Box 9414 Ft. Lauderdale, FL 33310
60, A60; T.C. A12CE	SA945CE	Replacement of existing nickel-cadmium battery with lead-acid battery, Teledyne PS12-24. Amended October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133
60, A60; T.C. A12CE	SA1587SW	Mitchell automatic flight system YK380 consisting of yaw damper. Issued March 1973.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60; T.C. A12CE	SA1704SW	Mitchell automatic flight system AK429, cons. of Century IV autopilot with trim or AK429/FD cons. of Century IV autopilot/flight director with trim. Issued 7/20/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA154GL	Installation of Norton radome kit, No. 4132X. Issued 2/16/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
60, A60, B60; T.C. A12CE	SA179GL	Install Celveland conversion kit, P/N 199-73. Issued 5/23/77.	GL	23260	Cleveland Wheels and Brakes VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011
60, A60, B60; T.C. A12CE	SA539SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator and/or YD-4 yaw damper. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
60, A60, B60; T.C. A12CE	SA1023CE	Installation of Collins Radio Co. AP-106 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1024CE	Installation of AP-107 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1025CE	Installation of yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A2CE	SA1741SW	Mitchell automatic flight system AK458 cons. of Century autopilot with optional radio coupler automatic/command pitch trim, glide slope coupler. Issued 10/12/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
60, A60, B60; T.C. A12CE	SA3151SW-D	Mitchell automatic flight system AK429 consisting of Century IV autopilot or AK429/FD consisting of Century IV flight director with optional remote annuciator. Issued 7/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A2CE	SA3162WE	Installation of recognition light assembly on the horizontal stabilizer. Issued 3/26/76.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
60, A60, B60; T.C. A12CE	SA3293SW-D	Yaw damper system YK380. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3605WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel indicating system. Amended 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
60, A60, B60; T.C. A12CE	SA3905WE	Installation of SDI Model CFS-200, -2001, or FT-200 fuel flow indicating system. Issued 4/13/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
60, 65-A80, B80, 65-88, 70; T.C. A12CE, 3A20	SA889EA	Installation of Grimes three light strobe Kit P/N 34-0116-1 and -2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
60, A60, B90, C90, E90, 65-90, -A90, 100, A100; T.C. A12CE, 3A20, A14CE	SA2638WE	Installation of CCC BWS 50-08 Nicad battery overheat warning system. Amended 9/18/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
A60; T.C. A12CE	SA85RM	Installation of Teledyne Avionics angle of attack indicating system. Issued 11/2/76.	RM	14127	Avionics Engineering of Denver, Inc. 8895 Montview Boulevard, Hangar B Denver, CO 80220
A60; T.C. A12CE	SA1029CE	Installation of AP-106 and AP-107 automatic flight control systems and yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
B60; T.C. A12CE	SA570SO	Installation of Bendix M-4D automatic flight control system, including optional manual electric trim and optional flight director indicator. Issued 12/6/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, Fl 33310
B60; T.C. A12CE	SA1470CE	Installation of King KFC 250 flight control system (3 axis) using 3-inch or 4-inch indicators. Issued 2/5/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
65 Series; T.C. 3A20	SA1-643	Radar antenna mounts: 296-01 for 12" Collins WP-103 antenna; 296-03 12" RCA AVQ-55 antenna and 296-02 for 12" RCA AVQ-50 antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series; T.C. 3A20	SA3-516	Autopilot L-2C with or without 1350B approach coupler and 2203D2 altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA4CE	Propeller governors incorporating unfeathering accumulator shutoff valves.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
65 Series; T.C. 3A20	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
65 Series; T.C. 3A20	SA46WE	Full flow lube oil filter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
65 Series; T.C. 3A20	SA92CE	High intensity wing tip lights Model A, tail light Model C, with or without high intensity fuselage lights Model 1 or 2.	GL	42625	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
65 Series; T.C. 3A20	SA139SW	Buffet. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65 Series; T.C. 3A20	SA161CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
65 Series; T.C. 3A20	SA185CE	Type OF-103-A oil filters P/N 6435565.	GL	00750	AC Spark Plug Division of GMC P.O. Box 1002 Flint, MI 48556
65 Series; T.C. 3A20	SA186EA	Throttle stop device.	EA	87118	Stephen J. Wisey, Jr. 8 Steamboat Road Great Neck, NY 11022
65 Series; T.C. 3A20	SA188CE	Twin-engine synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
65 Series; T.C. 3A20	SA201EA	Sperry SP 3 elevator trim drive servo and trim tab bracket.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
65 Series; T.C. 3A20	SA210SO	Radar system AVQ55.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
65 Series; T.C. 3A20	SA218SW	Automatic pilot AK105.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA255CE	Oil tank heater blanket kit 65-42.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67206
65 Series; T.C. 3A20	SA269SW	Brushless generators, voltage regulators and control panels.	EA	37376	General Electric Company Specialty Controls Department Waynesboro, VA 22980
65 Series; T.C. 3A20	SA277EA	Installation of Chamberlain 2090K-B radome kit for Bendix 100 or RDR-110 radar systems with transmitter/ receiver unit and 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
65 Series; T.C. 3A20	SA280EA	2011K-B Series radome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series; T.C. 3A20	SA296CE	M4B or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA307CE	GUARD system (gear up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612
65 Series; T.C. 3A20	SA336EA	PB-60 autopilot.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
65 Series; T.C. 3A20	SA393EA	Electronic voltage alarm.	EA	53500	McKinley Engineering Company P.O. Box 275 Palisades Park, NJ 07650
65 Series; T.C. 3A20	SA411CE	M4B or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA444SW	Lycoming IO-720A1A engines and increase in takeoff and loading weight. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65 Series; T.C. 3A20	SA470SW	Automatic pilot AK122 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA471SW	Automatic trim system AK149.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA505CE	Install entrance door.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65 Series; T.C. 3A20	SA528SW	Lear 164 electro-mechanical rotary actuator.	SW	42131	H & H Enterprises P.O. Box 75135 Oklahoma Ctiy, OK 73125
65 Series; T.C. 3A20	SA651SW	AK206 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA695SW	Engine induction system air filter removed.	SW	71800	Sinclair Oil & Gas Company Aviation Department 3505 N. Sheridan Road Tulsa, OK 74101
65 Series; T.C. 3A20	SA704CE	Installation of BUTLER VAC and ADD navigation system. Amended April 1974.	CE	19000	Butler National Corporation 8246 Nieman Road Lenexa, KS 66214
65 Series; T.C. 3A20	SA722SW	AP-103F/FD-108 autopilot flight director system and related electronics.	SW	24252	Collins Radio Company P.O. Box 98 Addison Airport Addison, TX 75001
65 Series; T.C. 3A20	SA767SW	Mitchell Model AK 239 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA1004WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
65 Series; T.C. 3A20	SA1022WE	B-4 flight control system (PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1453WE	Installation of a Brittain Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1511WE	Pacific Airmotive Corp. rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
65 Series; T.C. 3A20	SA1528WE	Installation of Brittain B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1556WE	Installation of Brittain Industries B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1714WE	Removal of emergency exit to permit aircraft to engage in special purpose operations, as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
65 Series; T.C. 3A20	SA1794WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA2069WE	Installation of Brittain B-VII Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65, A65, A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 70; T.C. 3A20	SA22GL	Installation of Hartzell synchrophaser. Reissued 8/27/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
65, A65, 65-80, 65-A80, 65-B80; T.C. 3A20	SA43CE	Installation of Bendix M-4B and M-4C flight control system. Amended 3/8/67.	EA	15480	The Bendix Corporation Avionics Products Bendix Radio Division Baltimore, MD 21204
65, 65-80, 65-A80, 65-90; T.C. 3A20	SA318EA	Installation of Monitair angle of attach and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
65-L23F, 65-80, 65-A80, 65-B80, -90, -A90; T.C. 3A20	SA394CE	Install Hoskins Twi. Mk III supplemental high intensity lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65, 65-80; T.C. 3A20	SA1-642	2011X Series radome. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
65, 65-80; T.C. 3A20	SA506WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTL Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
65, 65-80; T.C. 3A20	SA518SW	Goodrich wheel and brake. Reissued Feburary 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65, A65, 65-80, A65-8200, 65-A80, -A80-8800, -B80, -88, -70; T.C. 3A20	SA277GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 12/21/78.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
65, A65, -80, -A80, -A80-8800, A65-8200, -B8Q, 70; T.C. 3A20	SA1244SW	Mitchell automatic flight system FD/AF282-313 cons. of flight/director/autopilot and automatic pitch trim. Issued 1/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, A65, A65-8200, 65-80, -A80, -A80-8800, -B80, -88, -90, -A90, 70, B90, C90, E90; T.C. 3A20	SA1279CE	Installation of Avcon Ind. TSO-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
65, A65, 65-80; T.C. 3A20	SA1328SW	Replacement of existing alternators with 100 ampere Prestolite ALV-8042's. Reissued 10/20/72.	SW	61500	Nayak Aviation Corporation 206 E. Terminal Avenue San Antonio, TX 78216
65, A65, A65-8200, 65-80, -A80, -A80-880, -B80, -88, -90, -A90, -A90-1, -A90-2, -A90-3, -A90-4, 70, B90, C90, E90; T.C. 3A20	SA1583CE	Install wing front spar reinforcement kit. Issued 4/11/80.	CE	13177	Aviadesign, Inc. Suite 101, Bank of America, Levy Building 5808 E. Telephone Road Ventura, CA 93003
65, A65, 65-80, 65-A80; T.C. 3A20	SA2349SW	3-place divan. Issued 8/13/76.	SW	36550	Foster-Edwards Aircraft Co., Inc. Box 574 Addison, TX 75001
65, A65, A65-8200, 70; T.C. 3A20	SA2365WE	Installation of Hartzell HC-3X20-2/9333C or HC-A3X20-2/9333C propellers. Reissued 7/14/71.	SW	37080	Bernard A. Gallaher 1400 Southwest Tower Houston, TX 77002
65, A65, A65-8200, 65-80, -A80, -A80-8800, -B80, -88, 70, 65-90, -A90, A90-1, -2, -3, -4, B90, C90 (S/N LJ502 thru 526); T.C. 3A20	SA3080WE	Installation of recognition light assembly on the horizontal stabilizer. Amended 2/3/76.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
65, A65, 65-80, -A80, -B80, -A80-8800; T.C. 3A20	SA3114SW-D	Automatic flight system AK548, cons. of Century III autopilot with optional radio and glide slope couplers. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, 65-80, -A80, -B80, -A80-8800, A65-8200, 70; T.C. 3A20	SA3115SW-D	Mitchell AK585, cons. of Century IV autopilot or AK585FD Century IV flight director autopilot. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65-80; T.C. 3A20	SA1009EA	Installation of Edo area navigation system Model TCE-71A. Reissued 12/19/78.	EA	32625	EDO-AIRE Div. of Edo Corporation 216 Passaic Avenue Fairfield, NJ 07006
65-80, -A80, -B80, -88, -90, -A90; T.C. 3A20	SA381EA	Installation of radome kit No. 2090X. Amended 12/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44305
65-80, -A80, -B80, -88, -90, -A90, B90, C90, E90, 100, A100, A100A, A100C, B100; T.C. 3A20, A14CE	SA37GL	Installation of Norton radome kit No. 2090XS. Amended 8/24/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65-A80, -B80, -88, -90, -A90, -B90; T.C. 3A20	SA45GL	Install AMF inverter MGH 549-1. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
65-80, A-80, B-80; T.C. 3A20	SA2283WE	Installation of oil lever indicator system. Issued 11/30/70.	WE	25600	Communications Components Corp. 1524 West 15th Street Long Beach, CA 90813
65-B80 Queen Air; T.C. 3A20	SA940SO	Removal of existing fuel flowmeter and associated components and installation of fuel flowmeter. Issued 6/24/77.	SO	02850	Aerosonic Corporation P.O. Box 4627 Clearwater, FL 33518
A65, 65-B80 & 70; T.C. 3A20	SA660CE	Installation of Bendix M4-C Flight Control System.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33310
65-90; T.C. 3A20	SA133GL	Install B.F. Goodrich thermally efficient propeller de-icers. Amended 9/15/76.	GL	38500	B.F. Goodrich 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA826SW	Elevator electric trim system.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 - Adams Field Little Rock, AR 72203
65-90; T.C. 3A20	SA897EA	Installation of B.F. Goodrich electrothermal propeller deicing system. Issued 2/7/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Company 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA1108SO	Installation of Pratt & Whitney engine model PT6A-20 replacing model PT6A-6. Issued 10/15/79.	SO	14213	B. R. Power Division Aztec Leasing, Inc. 20 Piney Mountain Road Greenville, SC 29607
65-90; T.C. 3A20	SA2740SW	Installation of P&W PT6A-135 engines and bleed air conditioning and pressurization system. Issued 3/24/78.	SW	77111	E.J. Swearingen P.O. Box 4640 Waco, TX 76705
65-90, -A90; T.C. 3A20	SA761SW	Mitchell AK238 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65-90, -A90; T.C. 3A20	SA822SO	Installation of P & W PT6A-28 engines. Amended 3/27/78.	SO	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
65-90, 65-A90, 65-B90; T.C. 3A20	SA526SO	Installation of the Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-90, -A90, B90, C90, E90; T.C. 3A20	SA546SO	Instllation of Bendix M-4D automatic flight control system including optional manual electric trim system and optional flight director system. Issued April 1980.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Launderdale, FL 33310
65-90, -A90, -B90; T.C. 3A20	SA1177SW	Revised main landing gear doors.	SW	61500	Nayak Aviation Corporation 206 E. Terminal Drive San Antonio, TX 78216
65-90, -A90, B90, C90; T.C. 3A20	SA2693WE	Installation of inertial air separator scoops. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA810CE	Battery temperature sensing and over-temperature warning systems. Amended October 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA879SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA951CE	Installation of lead-acid battery. Issued October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, 99, A100; T.C. 3A20	SA1017SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA1194CE	Install Teledyne/Gill lead-acid battery, BB638/T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	78052	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, H90; T.C. 3A20	SA1451CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, 65-A90, B90 C90, E90, H90; T.C. 3A20	SA1452CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, A90, B90, C90, E90, 99, 99A, A99A, 100, A100; T.C. 3A20	SA2284SW	Ignition current monitor system. Issued 1/19/76.	SW	16850	The EKM Company Box 7001 Dallas, TX 75209
65-90, -90A, -A90-1, -2, -3, -4, B90, C90, E90, 99, 99A, A99, A99A, B99, 200, A200, 200T; T.C. 3A20, A14CE, A24CE	SA566NW	Installation of parachute deployment system. Issued 3/27/78.	NW	80915	U.S. Forest Service 3905 Vista Avenue Boise, ID 83705
65-90, -A90, -A90-1, -A90-2, -A90-3, B-90, C-90; 99, 99A; T.C. 3A20, A14CE	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457
65-90, -A90, -A90-1, -A90-2, -A90-3, -A90-4, B90, C90, E90; T.C. 3A20	SA2907WE	Installation of fuel tank boost pump. Amended 11/18/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
65-90, -A90, B90, C90; T.C. 3A20	SA3266SW-D	Mitchell automatic flight system AK725 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/24/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
65-A90; T.C. 3A20	SA691CE	Installation of fuel drain manifold tank.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65-A90; T.C. 3A20	SA729SW	Installation of Collins AP-103F/FD-108 autopilot/flight director system and related electronics. Amended 2/14/68.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-A90; T.C. 3A20	SA845CE	Installation of wing flap override switch and duplicate flap down limit switch. Issued May 1972.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65-A90; T.C. 3A20	SA1813SW	Battery temperature sensing and indicating system. Issued 3/8/74.	SW	02300	Aero Instrument Supply, Inc. 7515 Lemon Avenue Box 7481 Dallas, TX 75209
65-A90, -A90-1, B90; T.C. 3A20	SA418SO	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-A90, B90; T.C. 3A20	SA16GL	Install AMF inverter MGE 23-400. Reissued 11/17/78.	GL	50360	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
65-A90, B90, C90; T.C. 3A20	SA377GL	Addition of fourth cabin window on right hand side of fuselage. Issued 11/28/79.	GL	18320	Burlington Northern Airmotive International Airport Minneapolis, MN 55450
65-A90, -B90, -C90, E90; T.C. 3A20	SA3971WE	Installation of SDI Model CFS-2002, fuel flow indicating system. Amended 10/19/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
65-B90, -A90 with 90-4031 kit; T.C. 3A30	SA537CE	Installation of Collins AP-103F/FD108 and AP-103F/FD109G Autopilot and flight director. Amended 9/13/68.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-B90, -A90 with 90-4031 kit; T.C. 3A20	SA567CE	Installation of Collins AP-103F/FD108 and AP-103F/FS108G, AP-103F/FD109G autopilot and flight director. Amended 5/4/70.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA569CE	Installation of Collins AP104/FD109H Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B90; T.C. 3A20	SA603CE	Installation of Collins AP-104/ FD-109F Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA988CE	Installation of fuel dump valve; G.W. increase to 10,000 pounds. Amended 3/9/70.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
B-90; T.C. 3A2	SA1665SW	Fabricate and install bar assembly. Issued 5/29/73.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
B-90, C-90; T.C. 3A20	SA1454SW	Mitchell automatic flight system model FD/AP282-318 cons. of flight director/autopilot with optional command trim. Issued 4/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B-90, C-90; T.C. 3A20	SA1458SW	Mitchell automatic flight system AK318 cons. of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 4/24/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90; T.C. 3A20	SA1517SW	Automatic flight system YK384 cons. of yaw damper. Issued 9/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90; T.C. 3A20	SA1583SW	Foxtronics/TRAMM BT1 600 nickel-cadmium battery temperature system. Issued 1/3/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
65-B90, C90, E90; T.C. 3A20	SA547CE	Installation of Bendix M4C autopilot. Amended 8/1/72.	SO	15475	The Bendix Corporation Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
65-B90, C90, E90; T.C. 3A20	SA1640SW	Mitchell automatic flight system AK422/FD cons. of Century IV autopilot/flight director with command electric trim. Issued 4/19/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90, E90; T.C. 3A20	SA3042SW-D	Mitchell automatic flight system AK456 or 456 FD cons. of Century IV autopilot or Century IV flight director autopilot with command/ automatic electronic pitch trim system and optional remote annuciator panel. Issued 1/31/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90, E90; T.C. 3A20	SA3294SW-D	Yaw damper system YK384. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C90; T.C. 3A20	SA537SO	Installation of Bendix YD-4 yaw damper. Issued 5/15/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90; T.C. 3A20	SA541SO	Installation of Bendix FCS-810 automatic flight control system including optional flight director indicator DH-841. Amended 1/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90; T.C. 3A20	SA925EA	Installation of Collins AP-105 autopilot system. Issued 6/28/72.	NE	08160	AIRKAMAN, Inc. Bradley International Airport Windsor Locks, CT 06096
C90, E90; T.C. 3A20	SA546SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim system and optional flight director system. Amended 5/16/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90, E90; T.C. 3A20	SA3124WE	Installation of recognition light assembly on horizontal stabilizer. Issued 12/8/75.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
C90, E90, 99; T.C. 3A20, A14CE	SA1013SO	Replace existing nickel-cadmium battery with Gill BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road Suite 200 Atlanta, GA 30339

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
E90; T.C. 3A20	SA2667WE	Installation of Sperry SPZ-200 autopilot and Stars Instrument System or SPI-77C flight director system. Amended March 1974.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90; T.C. 3A20	SA2680WE	Category II approval of airborne instruments and equipment. Reissued 9/17/73.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90, 99, A100, 200; T.C. 3A20, A14CE, A24CE	SA920SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78052	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
76; T.C. A29CE	SA1153EA	Installation of DeVore "tel-tail" lights on lower surface of horizontal stabilizer. Reissued 7/24/79.	EA	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
76; T.C. A29CE	SA1455CE	Installation of DFC200 flight control system (2 axis). Issued 10/17/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
76; T.C. A29CE	SA3256SW-D	Mitchell automatic flight system AK694 consisting of Century IV autopilot or AK694FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3257SW-D	Mitchell automatic flight system AK693 consisting of Century III autopilot with optioanl radio and glide slope couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3258SW-D	Mitchell automatic flight system AK692 consisting of Century III autopilot with optional radio couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3259SW-D	Mitchell AK619 consisting of Century I autopilot with optional omni tracker. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3260SW-D	Mitchell command electric trim AK695. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
76; T.C. A29CE	SA3261SW-D	Yaw damper system AK696. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3317SW-D	Installation of Mitchell automatic flight system AK761 consisting of Century I autopilot with omni tracker. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3318SW-D	Installation of Mitchell automatic flight system AK762 consisting of Century IIB autopilot with optional radio couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3319SW-D	Installation of Mitchell automatic flight system AK763 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3320SW-D	Installation of Mitchell automatic flight system AK764 consisting of Century IV autopilot or AK764FD consisting of Century IV autopilot flight director with optional remote annunciator. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3321SW-D	Installation of Mitchell automatic flight system AK765 consisting of command electric trim system. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3322SW	Installation of Mitchell yaw damper YK766. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
76; T.C. A29CE	SA3345SW	Installation of Mitchell yaw damper YK838. Issued 1/28/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3346SW	Mitchell automatic flight system AK827/FD consisting of Century 41/FD flight director autopilot. Issued 12/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3356SW	Installation of Mitchell automatic flight system AK826 consisting of Century 21 autopilot. Isse3 1/22/80.	SW	60000	Mitchell Industries, Incc. P.O. Box 610 Municipal Airport Mineral Wells, 76067
76; T.C. A29CE	SA4005WE	Removal of main landing gear door. Issued 7/25/79.	WE	71630	Sierra Academy of Aeronautics Oakland International Airort Oakland, CA 94614
95 Series; T.C. 3A16	SA1-235	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
95 Series; T.C. 3A16	SA1-395	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-422	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-482	16" x 17" opening in lower surface of fuselage.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
95 Series; T.C. 3A16	SA1-588	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
95 Series; T.C. 3A16	SA3-262	Automatic pilot L-2 with or without approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-470	L-2C autopilot with or without approach coupler and altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-624	Winslow oil filter 30409A.	CE	80670	United Airplane Sales, Inc. Municipal Airport Wichita, KS 67202
95 Series; T.C. 3A16	SA3-633	Autopilot L-2C with or without approach coupler and/or altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA4-574	Radio rack in nose compartment.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
95 Series; T.C. 3A16	SA4-691	Oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
95 Series; T.C. 3A16	SA4-1052	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A16	SA4-1612	Anticollision beacon Roto-Lite X6000, either 12 or 24 volt, on vertical fin	WE	49690	The Norman Larson Company Van Nuys Airport Van Nuys, CA 91408
95 Series; T.C. 3A16	SA9SW	Aileron trimmer ATC35-107.	SW	06000	Aircraftsmen, Inc. Hangar 2, Will Rogers Field Oklahoma City, OK 73125
95 Series; T.C. 3A16	SA44EA	Wet pump pneumatic deicing.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95 Series; T.C. 3A16	SA70SW	Vapor automatic temperature control system.	CE	82540	Vapor Heating Company 2522 E. Douglas Wichita, KS 67202
95 Series; T.C. 3A16	SA74CE	Federal F-400 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
95 Series; T.C. 3A16	SA92SW	Automatic pilot AK103 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA171WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oaklana, CA 94608
95 Series; T.C. 3A16	SA173EA	Beech 5D1048 air reservoir assembly relocated for wing and tail boot deicer.	NE	08160	AirKaman, Inc. Bradley Field Windsor Locks, CT 06096
95 Series; T.C. 3A16	SA231EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA287CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA311WE	Beech pneumatic pitch assist PC-1 and optional installation altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA316EA	M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA360CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation Marquette Division 1145 Galewood Drive Cleveland, OH 44110
95 Series; T.C. 3A16	SA474EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA474WE	B4 flight control system including basic autopilot, pitch assist PC-1, altitude hold AH-1, and navigational coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA516SW	Automatic trim AK160.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA617SW	III autopilot, automatic pitch trim, stabilizer and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA742SW	AK196 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA831WE	Single-place windshield.	WE	69590	SAFE-SITE, Inc. 3511 W. Sixth Street Los Angeles, CA 90005
95 Series; T.C. 3A16	SA844WE	One-piece windshield.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
95 Series; T.C. 3A16	SA1494WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1532WE	Installation of Brittain Model B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1542WE	Installation of Brittain Model B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95 Series; T.C. 3A16	SA1559WE	Installation of Brittain Industries Model B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1587WE	Installation of Brittain Model B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1677WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1833WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, B95A, D95A and E95; T.C. 3A16	SA153SO	Installation of turbosupercharged Lycoming O-360-A1A, IO-360-B1A or IO-360-B1B engines. Amended 2/28/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
95, B95, B95A, D95A, 95-55, 95-A55, 95-B55; T.C. 3A16	SA263CE	Supplemental Model A high intensity wing tip lights, Model C tail light, with or without Model 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
95, B95, B95A, D95A, 95-55, -A55, -B55, -C55, -D55, -56; T.C. 3A16	SA370CE	Installation of Boskins Supp. Model A high intensity wing tip lights, Model D or E tail lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
95, B95, B95A, 95-A55, -55, D95A; T.C. 3A16	SA571WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTL Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
95, B95, B95A, 95-55, 95-A55, 95-B55, 95-B55B (T-42A), 95-C55; T.C. 3A16	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-3 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
95, B95, 95-55, 95-A55, B95A, D95A, E95, 95-B55, -B55A, -B55B, -C55, D55, 95-C55A, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA901SO	Installation of single-piece sloped windshield. Amended 11/21/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. c/o F.E. Leddick & Associates, Inc 175 W. Wieuca Rd., Suite 120 Atlanta, GA 30342
95, B95, B95A, D95A, E95; T.C. 3A16	SA1409SW	Mitchell automatic flight system AK366, cons. of Century I autopilot with optional omni tracker. Issued 12/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D95A; T.C. 3A16	SA1760WE	Installation of Brittain Industries Model B-5 or NAV-2 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, 95-55, -A55, B95A, D95A, E95, -B55, -B55A, -B55B, -C55, D55, -C55A, D55A, E55, E55A; T.C. 3A16	SA2977WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
95, B95, D95A, E95; T.C. 3A16	SA3090SW-D	Automatic flight system AK562, cons. of Century IIB autopilot. Issued 12/15/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95, B95, B95A, D95, E95; T.C. 5A3	SA3179SW-D	Automatic flight system AK650 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 1/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D95, E95; T.C. 5A3	SA3187SW-D	Mitchell automatic flight system AK366 consisting of Century I autopilot with optional omni tracking system. Issued 2/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D59A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA3680WE	Installation of centerline external air skeg. Amended 4/2/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90065

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-55; T.C. 3A16	SA1820WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, -A55, -B55, -C55, -D55; T.C. 3A16	SA9CE	Installation of M4B or M4C flight control system. Amended 6/1/70.	SO	15475	Bendix Corporation Avionics Division 2100 N.W. 62nd Street P.O. Box 9414 Fort Lauderdale, Fl 33310
95-55, -A55, -B55; *T.C. A23CE*	SA71GL	Install P/N BA7610 filter assembly. *Reissued 9/22/79.*	GL	17060	Brackett Aircraft Specialities, Inc. 9600 West 52nd Street Kenosha, WI 53140
95-55, -A55, -B55; T.C. 3A16	SA126CE	Install Hartzell Model HC-A3XF-2B/7636D or HC-A3VF-2B/V7636D or HC-A3VF-2B/V7636N or PHC-A3XF-2B/7636D or PHC-A3VF-2B/V7636D or PHC-A3VF-2B/V7636N propellers with Woodward Model 210355 or 210438 governors. Reissued 2/26/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-55, 95-A55; T.C. 3A16	SA136RM	Removal of existing nose cone, Beech P/N 95-410011-3 and replacement with later model nose cone, Beech P/N 95-410021-605. Issued 3/28/78.	RM	73940	Spanish Fork Flying Service, Inc. Box 48 Spanish Fork, UT 84660
95-55, -A55; T.C. 3A16	SA387GL	Installation of Norton radome kit No. 4150X-100 and -200. Issued 2/8/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-55, A55; T.C. 3A16	SA447SW	Nose modification.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA448SW	Rear baggage compartment.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA540EA	Installation of radome kits No. 3063X-R-100 and -200. Reissued 3/12/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-55, 95-A55, -B55, -B55A, -B55B; T.C. 3A16	SA795CE	Install propeller Models BHC-C2YF-2CH/C8465-6 or BHC-2CHF/FC8465-6, DHC-C2YF-2CH/C8465-6 or DHC-C2YF-2CHF/FC8465-6 with spinner C-2285-1; or PHC-C3YF-2/FC7663-2R with spinner C-3567-1. Amended 8/30/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-55, -A55, -B55, -C55, D55; T.C. 3A16	SA886EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-011401. Issued 10/27/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
95-55, -A55, -B55, -B55A, B55B, C55, C55A, D55, D55A, E55, E55A, 58, 58A; 56TC, A56TC; T.C. 3A16	SA991EA	Installation of "Tel-Tail" logo lights. Reissued 3/18/76.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA1014SO	Installation of Symbolic Displays Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/30/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
95-55, 95-A55, -B55, -C55, -D55, E55, E55A, 58; T.C. 3A16	SA1134CE	Installation of 2-axis (3 optional), flight control system. Amended 2/12/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-55, A55, B55, B55B, C55, D55, E55; T.C. 3A16	SA1173SW	Mitchell automatic flight system AK292 cons. of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers. Issued 7/14/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1299SW	Mitchell automatic flight system Model 282-292 cons. of flight director/autopilot with optional automatic pitch trim. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-55, -A55, -B55, -B55B, -C55, -D55, -D55A, E55, E55A; T.C. 3A16	SA1300SW	Mitchell automatic flight system AK330, cons. of Century I autopilot with optional omni tracker. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA1472CE	Installation of elevator tail cone fairing. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-55, -A55, -B55, -C55, D55, D55A, E55, E55A, 56TC, A56TC; T.C. 3A16	SA1565SW	Mitchell automatic flight system AK408 cons. of Century II autopilot with optional radio coupler. Issued 12/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1743SW	Mitchell automatic flight system AK401 cons. of Century IIB autopilot with optional radio coupler. Issued 10/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA1777SW	Mitchell automatic flight system AK450 cons. of Century III autopilot with optical command/electric trim radio coupler, and glide slope coupler. Issued 12/26/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A; T.C. 3A16	SA1808SW	Installation of automatic flight system AK446 Century IV autopilot and AK446FD Century IV flight director autopilot with electronic/command, and pitch trim. Issued 2/15/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, E95, A-55, B55, C55, B95A, D95A; T.C. 3A16	SA1958WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, 95-A55, -B55, -C55, D55, E55, 58; T.C. 3A16	SA2543WE	Installation of SDI/Hoskins Model 700801 anticollision light. Amended 12/19/72.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
95-55, 95-B55A; T.C. 3A16	SA2882WE	Installation of McCAuley 3AF32C75/82NB-6 full-feathering constant speed propellers and D3499 or D3605 spinner assemblies. Issued 5/13/74.	WE	17154	Dennis A. Praegitzer Bridgeford Flying and Propeller Service P.O. Box 6277 Stockton, CA 95206
95-55, A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3108SW-D	Mitchell AK446 or AK446FD cons. of Century IV flight director autopilot with optional remote annuciator. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3109SW-D	Mitchell AK450 cons. of Century III autopilot with optional command automatic electronic pitch trim system, radio and glide slope coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3295SW-D	Yaw damper system YK428. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A13	SA3333SW-D	Mitchell automatic flight system AK401 consisting of Century IIB autopilot with optional radio couplers. Issued 2/20/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3918WE	Installation of Silver Instruments Fueltron III digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3919WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-A55; T.C. 3A16	SA2690WE	Installation of manual pitch trim system and Lean P/N 800880 autopilot. Issued 6/19/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-A55, 95-B55, 95-C55; T.C. 3A16	SA1392WE	Modification of fuselage structure and control system to accommodate a camera installation between Stations 131 and 151.	WE	25971	Continental Airservice, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
95-A55, -B55, -C55, -D55, E55/E55A, 58; T.C. 3A16	SA1523CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-A55, -B55; T.C. 3A16	SA2964WE	Installation of Collins AP 107/FD 112C autopilot/flight director system. Reissued 1/14/75.	CE	24250	Collins Radio Group 5220 "C" Avenue, N.E. Station 120-120 Cedar Rapids, IA 52406
95-B55; T.C. 3A16	SA3179WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 7/27/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
95-B55; T.C. 3A16	SA3353SW	Installation of Mitchell automatic flight system AK841/FD consisting of Century 41/flight director autopilot. Issued 1/29/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-B55, -C55, D55, E55, 56TC, 58; T.C. 3A16	SA15GL	Installation of radome kit No. 3064X. Amended 9/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operation P.O. Box 350 Akron, OH 44309
95-B55, 95-C55, 56TC, D55, E55, 58; T.C. 3A16	SA40GL	Installation of Norton Company radome kit No. 3064X-R-500 for 10" RCA AVQ 45, 46, 47, and the 12" King KWX-40 radar antennas. Amended 4/11/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-B55, -B55A, E55, E55A, 58, 58A; T.C. 3A16	SA64GL	Installation of radome kit P/N 4083X. Amended 5/8/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-B55, -B55A, -C55, -C55A; T.C. 3A16	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
95-B55, -C55, 56TC, D55, E55, 58; T.C. 3A16	SA482EA	Installation of Radome Kit No. 3064X-R-500 for 10-inch RCA AVQ-45, AVQ-46, and AVQ-47 radar antenna. Amended 6/19/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
95-B55 & 95-B55A, T.C. 502 and up; 95-C55 & 95-C55A, TE-1 thru TE-451; 95-D55 & 95-D55A, TE-452 thru TE-767; 95-E55 & 95-E55A, TE768 and on; T.C. 3A16	SA799CE	Installation of Airborne/Goodyear iceguard. Issued April 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
95-B55, -B55A, E55, E55A, 58, 58A; T.C. 3A16	SA1471CE	Installation of flap and aileron seals. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-B55, 95-C55, 95-B55A, 95-C55A; T.C. 3A16	SA2031WE	Installation of Brittain Industries B-VII, NAV-2B, or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-B55, -B55A, -C55, -C55A, D55, D55A; T.C. 3A16	SA3657WE	Installation of a vapor cycle air conditioning system. Issued 6/28/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
95-C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA773CE	Installation of Hartzell BHC-C2Y, BHC-J2Y, PHC-C3Y or PHC-J3Y propellers in accordance with Hartzell Manual 115G. Amended 2/1/80.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1054CE	Installation of AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1055CE	Installation of AP-107 3-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1056CE	Installation of AP-107, 2-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, D55, E55, 56TC, A56TC, 58; T.C. 3A16	SA1345CE	Chrome plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
95-C55; T.C. 3A16	SA1713WE	Removal of emergency exit to permit aircraft to engage in special purpose operations such as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
95-C55, -C55A, D55, D55A, E55, E55A, 58 58A; T.C. 3A16	SA3840WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
B95; T.C. 3A16	SA1-463	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
B95; T.C. 3A16	SA3406WE	Installation of Pathfinder autopilot systems. Issued 7/5/77.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
B95A, D95A, E95; T.C. 3A16	SA1672SW	Mitchell automatic flight system AK425, cons. of Century III autopilot with optional command automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/7/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
99; T.C. A14CE	SA298GL	Reduce number of passenger seats from 15 to 9. Issued 3/22/79.	GL	27760	Custom Air Service Willow Run Airport Ypsilanti, MI 48197
99; T.C. A14CE	SA366GL	Installation of microwave landing system airborne equipment. Issued 10/12/79.	GL	58150	Mesaba Aviation 2002 Airport Road Grand Rapids, MN 55744
99; T.C. A14CE	SA4030SW	Pratt & Whitney PT6A-27/28 engines. Issued 8/30/79.	SW	69214	Royale Turbines, Inc. Shreveport Regional Airport Shreveport, LA 71109
99, 99A; T.C. A14CE	SA717CE	Installation of M4C autopilot.	CE	15477	Bendix Avionics 3303 East Harry Street Wichita, KS 67218
99, 99A, 99A (FACH), A99, A99A, B99; T.C. A14CE	SA114GL	Installation of Norton Radome Kit 3097X. Issued 5/20/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
99, 99A, A99, A99A, B99; T.C. A14CE	SA143GL	Modification of existing B.F. Goodrich propeller de-icing system. Issued 11/23/76.	GL	38500	B.F. Goodrich Engineered Systems Company Div. of B.F. Goodrich Company Akron, OH 44318
99, 99A, 100, A100; T.C. A14CE	SA811CE	Battery temperature sensing and over-temperature warning systems. Issued February 1972.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
99, A99, 99A, A99A, 100, A100, A100A T.C. A14CE	SA894SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	SO	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
99, 99A, 99A (FACH), A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1178CE	Install wing front spar reinforcement kit. Reissued 5/9/80.	CE	13177	Aviadesign, Inc. Suite 101, Bank of A., Levy Bldg. 5808 E. Telephone Road Ventura, CA 93003
99, 99A, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1280CE	Install Avcon Ind. TSO-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1453CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1454CE	Installation of Sierra electronic console. Reissued 10/16/78.	CE	71660	Sierra Reserach Corporation P.O. Box 222 Buffalo, NY 14225
99, 99A, A99, A99A, B99, 100, A100; T.C. A14CE	SA2908WE	Installation of fuel tank boost pump. Issued 7/23/74.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
99, 99A, 99A (FACH), A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA3106WE	Installation of recognition light assembly on horizontal stabilizer. Amended 10/24/78.	WE	30000	DeVore Aviation Corporation 7120 Hayvennurst Avenue Suite 108 Van Nuys, CA 91406
99, 99A, A99, A99A, B99; T.C. A14CE	SA4013WE	Installation of a hydraulic landing gear retraction system. Issued 9/19/79.	WE	13177	Aviadesign, Inc. Suite 101, Bank of America Levy Building 5808 East Telephone Road Ventura, CA 93003
99A; T.C. A14CE	SA981EA	Installation of modified cargo door, airstair door, jump door in cargo door and external parachute's step. Amended 10/4/74.	EA	23450	C N C Industries, Inc. Hyde Field, Route 223 Clinton, MD 20735
100, A100; T.C. A14CE	SA1197CE	Install Teledyne/Gill lead-acid battery, BB638T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	65300	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133
100, A100; T.C. A14CE	SA1573SW	Foxtronics/TRAMM BT1 600 nickel cadmium battery temperature system. Issued 12/19/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
A100; T.C. A14CE	SA256GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
A100; T.C. A14CE	SA476SO	Installation of M4C autopilot in accordance with Bendix drawing list AE-163, Rev. A. Issued 10/14/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
A100; T.C. A14CE	SA1058SO	Replace existing nickel-cadmium batteries with Teledyne Gill B6381T batteries. Issued 3/29/79.	SO	78054.	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
B100; T.C. A14CE	SA1018SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
B100, S/N's BE-21 and up; T.C. A14CE	SA3981WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200; T.C. A24CE	SA381GL	Installation of a single Canadian Marconi CMA-734 Omega/VLF navigation system. Issued 1/4/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
200; T.C. A24CE	SA1016SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 POwers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
200; T.C. A24CE	SA1189CE	Installation of Safe Flight speed command or speed command and autothrottle (SCAT) system. Amended 6/8/77	EA	69500	Safe Flight Instrument Corp. (SFIC) P.O. Box 550 White Plains, NY 10602
200; T.C. A24CE	SA3339WE	Installation of Hydro-Aire power brake/skid control system. Issued 5/17/77.	WE	26725	Hydro-Aire Division Crane Company, Inc. P.O. Box 7722 Burbank, CA 91510
200; T.C. A24CE	SA3982WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200, A200; T.C. A24CE	SA1278CE	Installation of Avcon Industries TSO-C39a stretchers. Issued February 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47G-2A, -2A-1, 47G-3, -3B, -3B-1, -3B-2, -3B-2A, 47G-4, -4A, 47G-5, -5A; T.C. 2H3	SH193WE	Installation of Jasco alternator P/N 7555-1 volt system. Amended 7/3/79.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
47G-2A, -2A-1, -3-B, -3-B-1, -3-B-2, G-4; T.C. 2H3	SA357SW	Installation of Simplex spray kit. Amended 5/18/77.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G-2A, -2A-1, 47G-3, -3B, -3B-1, -3B-2, 47G-4, -4A, 47G-5; T.C. 2H3	SH370GL	Installation of Ni-Cad model No. 82164 engine lubrication system scavenge filter. Issued 11/2/79.	GL	61546	Ni-Cad, Inc. 24800 U.S. 20 South Bend, IN 46628
47G3, 47G-3B, 47G-3B-1, 47G-2A, 47G-4A, 47G-5; T.C. 2H3	SH88WE	Installation of cargo hook. Amended 5/10/71.	WE	63350	Thomas A. Patterson Helicopter Mechanics Service 7621 Tobias Avenue Van Nuys, CA 91405
47G-3B; T.C. 2H3	SH157GL	Installation of Lycoming VO-435-A1F engine. Issued 4/22/77.	GL	03280	Agri Helicopter, Inc. 840 Havana Road Owatonna, MN 55060
47G-3B; T.C. 2H3	SH173WE	Installation of derated Lycoming TVO-435-B1A or TVO-435-B1B engine in lieu of TVC-435-A1A engine using existing TVC-435-A1A installation components. Issued 11/11/74.	WE	85144	Western Helicopters, Inc. P.O. Box 579 1670 Airport Way Rialto, CA 92376
47G-3B; T.C. 2H3	SH404GL	Installation of Lycoming VO-435-A1 engine. Issued 5/9/80.	GL	03280	Agri Helicopter, Inc. Route #1, Box 7G Ouatonna, MN 55060
47G-3B; T.C. 2H3	SH986EA	Installation of Avco Lycoming engine Model TVC-435-B1A (O-435-25A) in lieu of model TVC-4350A1A. Issued 8/16/74.	EA	61188	Nassau County Police Department Air Bureau 1490 Franklin Avenue Mineola, NY 11501
47G-3B; T.C. 2H3	SH227GL	Installation of Lycoming VO-435-A1F engine. Issued 3/6/78.	GL	03280	Agri Helicopter, Inc. 840 Havana Road Owatonna, MN 55060
47G-3B-1; T.C. 2H3	SH86WE	Installation of cargo racks.	RM	65331	Provo Flying Service, Inc. P.O. Box 691 Provo, UT 84601
47G-3B-1; T.C. 2H3	SH93WE	Installation of supplemental exterior flashing lights.	RM	29250	Delta Products, Inc. P.O. Box 1147 Grand Junction, CO 81501
47G-3B-1; T.C. 2H3	SH226GL	Installation of Lycoming VO-435-A1F engine. Issued 3/6/78.	GL	03280	Agri Helicopter, Inc. 840 Havana Road Owatonna, MN 55060
47G-3B-1, 47G-3B-2, 47G-4, 47G-4A, 47G-5; T.C. 2H3	SH100WE	Installation of fiberglass baggage carriers.	WE	79300	Transland Aircraft, Inc. 24511 Frampton Avenue Harbor City, CA 90710
47G-3B-2A, 47G-5A; T.C. 2H3	SH153WE	Installation of Transland Model 54170 agricultural spray system. REissued 10/31/74.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
47G-4, 47G-4A; T.C. 2H3	SH162WE	Installation of exhaust muffler assembly. Issued 3/8/74.	WE	00100	A & B Welding Company 9317 Borden Avenue Sun Valley, CA 91352
47G-5; T.C. 2H3	SH15CE	Install Stewart Warner Model 940F combustion heater. Issued June 1972.	CE	33580	EPM Corporation P.O. Box 5978, Lambert Field St. Louis, MO 63134
47G-5; T.C. 2H3	SH204WE	Installation of AC-OF-104A oil filter at longtudinal station (-14.0). Amended 10/3/79.	WE	90115	Yuma Helicopters, Inc. P.O. Box 4935 Yuma, AZ 85364
47G-5 (Normal Category); T.C. 2H3	SH254WE	Installation of Gill Model PS-6-11 battery, together with an external power source. Issued 9/28/79.	WE	90115	Yuma Heliocpters, Inc. P.O. Box 4935 Yuma, AZ 85364
47H-1; T.C. TCH-1	SH909SW	Franklin 6V-350-A engine. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47J; T.C. 2H1	SH375AL	Installation of Airglas model L2700-47J skis. Issued 5/26/70.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47J; T.C. 2H1	SH1422CE	Installation of engine exhaust muffler. Issued 6/12/78.	CE	36510	Fostaire Helicopters 400 North Wharf Street St. Louis, MO 63102
47J, 47J2, 47J2A, 47K; T.C. 2H1	SH194WE	Installation of Jasco alternator P/N 7555-1 24-volt system. Amended 7/3/79.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
47J, 47J2, 47J2A, 47K; T.C. 2H1	SH199WE	Installation of stirrup assemblies to directional control pedals for operation by handicapped pilot. Issued 4/14/77.	WE	28620	Barry C. Dallwig 113 East Elfin Green Port Hueneme, CA 93041
47J-2, -2A; 47G-3B, 3B-1, 3B-2; T.C. 2H1, 2H3	SH12CE	Replace existing engine induction air filter with AC Spark Plug Filter - Type AAF-103.	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
204, 205, 212; T.C. H1SW, H4SW	SH611NW	Installation of onboard weighing system. Issued 6/16/78.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
204B; T.C. H1SW	SH984SO	Installation of Lycoming T5313A or B engines, replacing Lycoming T5311A engines, including minor installation changes. Issued 5/10/78.	SO	86080	Wilco Aviation bBlackwell Airport P.O. Box 506 Ozark, AL 36360
204B, 205A, 205A-1; T.C. H1SW	SH149WE	Installation of Chadwick electronic weighing system C47. Issued 6/1/72.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
204B, 205A, 205A-1; T.C. H1SW	SH172WE	Installation of A500 battery temperature monitor systems. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
204B, 205A, 205A-1; 206A, 206B, 206B-1, 206L, 212; T.C. H1SW, H2SW, H4SW	SH155WE	Installation of battery temperature monitor system. Amended 6/22/78.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
204B, UH1-B; T.C. H1SW	SH183AL	Installation of Airglas L7000 or L8500B skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
204B, 205A, 205A-1, 212; T.C. H1SW, H4SW	SH733NW	Installation of onboard weighing system. Issued 3/21/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
205A, 205A-1; T.C. H1SW	SH198AL	Installation of Airglas L8500 or L8500A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
205A, 205A-1; T.C. H1SW	SH255WE	Installation of emergency exit window. Reissued 1/11/80.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
205A, 205A-1; T.C. H1SW	SH462NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
205A, 205A-1; T.C. H1SW	SH1022SW	Interior arrangement for 7 passenger seats and 1 jump seat. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
205A, 205A-1; T.C. H1SW	SH1789SW	Foxtronics/Tramm BTI 600 nickel cadmium battery temperature system. Issued 1/29/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
205A, -1, 212; T.C. H1SW, H4SW	SH1700SW	Hard surface skid shoes. Issued 6/6/73.	SW	61650	Northrop Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
205A-1; T.C. H1SW	SH140GL	Installation of dual band (K/X) type weather radome. Issued 10/27/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
206; T.C. H2SW	SH329NW	Installation of automatic flagman. Issued 10/28/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362
206 Series; T.C. H2SW	SH1091SO	Replace existing battery with an Eagle-Picher magnum 13 battery. Issued 8/22/79.	SW	18190	BSI Manufacturing, Inc. 101 Space Park South Drive Nashville, TN 37211
206; T.C. H2SW	SH1137SO	Install Utah Research and Development Co. model 124BC101 battery charging system. Issued 3/11/80.	SO	18190	BSI Manufacturing, Inc. 101A Space Park South Drive Nashville, TN 37211

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206, 206A, 206B; T.C. H2SW	SH963EA	Installation of battery temperature alert system Model Bell B206-TA180 or B206D-TA180. Amended 6/28/74.	EA	25920	Consolidated Instrument Co., Inc. Teterboro Airport Teterboro, NJ 07608
206, 206A, 206A-1, 206B, 206B-1; T.C. H2SW	SH1018EA	Installation of Casey shroud type heater. Amended 11/14/79.	EA	20112	Casey Copter Accessories, Ltd. P.O. Box 121 Montreal International Airport Dorval, Quebec, Canada H4Y 1A5
206, A, A-1, B, B-1, L, L-1; T.C. H2SW	SH2828SW	Sloping pedestal and instrument. Issued 8/4/78.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
206, A, A-1, B, B-1, L; T.C. H2SW	SH4061SW	Install ruggedized attitude gyro and related vacuum system components. Issued 11/27/79.	SW	40000	Hamilton Instruments, Inc. 106 Neuhaus Street Houston, TX 77061
206A; T.C. H2SW	SH10CE	Install Hoskins Twilighter Mk III lighting system consisting of P/N 60-0032-31 power supply and two of Model 2 P/N 30-0021-11 lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
206A; T.C. H2SW	SH117WE	Installation of cargo rack on one side or on both sides of skid gear. Amended 10/20/70.	WE	03270	U.S. Department of Agriculture Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
206A, 206B, 206L, 206L-1, Normal Category; T.C. H2SW	SH240WE	Installation of baggage compartment extension. Issued 7/12/79.	WE	50275	Ronald A. Leibin and Stephen H. Crowe 2761 Hollywood Way Burbank, CA 91505
206A; T.C. H2SW	SH411AL	Installation of mirror kit assembly. Issued 12/15/70.	AL	10650	Anchorage Helicopter Service, Inc. 1812 East Fifth Avenue Anchorage, AK 99501
206A; T.C. H2SW	SH635EA	Operate with one or both rear doors removed and both front doors installed on helicopters equipped with or without emergency float gear.	EA	65008	The Port of New York Authority 111 8th Avenue, Room 1601 New York, NY 10011
206A; T.C. H2SW	SH837EA	Installation of Airborne television and microwave transmission system. Amended 3/24/71.	EA	30992	Dynasciences Corporation Township Line Road Blue Bell, PA 19422
206A; T.C. H2SW	SH864EA	Installation of AACK-1R Optical Radiation Corporation Model B "Locator" search light plus relocation of landing lights. Installation of additional contact surfaces "bear paws" to standard skid gear. Issued 2/17/71.	EA	12495	Atlantic Aviation Corporation Bell Helicopter Service Center P.O. Box 2307 South Hackensack, NJ 07608
206A; T.C. H2SW	SH892EA	Installation of Grimes Manufacturing Company supplemental strobe lights. Issued 11/26/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
206A; T.C. H2SW	SH1164SW	Installation of dual battery system using the ship's original battery and one installed by Bell Service Instructions and Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
206A; T.C. H2SW	SH1675SW	Heater system for de-fog air. Issued 6/15/73.	SW	68768	Rockwell International Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
206A, A-1, 206B; T.C. H2SW	SH1534SW	Remove standard BHC short skid shoes and install full length hard surface skid shoes. Issued 11/8/72.	SW	61650	Northrop Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
206A, B; T.C. H2SW	SA116WE	Installation of Nightsun SX-16C Searchlight. Amended 4/25/72.	WE	74500	Spectrolab Division of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
206A, B; T.C. H2SW	SH122WE	Installation of JB Systems, Inc. airconditioning system. Amended 12/10/73.	RM	45750	JB Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
206A, 206B; T.C. H2SW	SH124NW	Installation of Simplex 2700 and 2700A spray system tank assembly. Issued 9/9/74.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206A, 206B; T.C. H2SW	SH126WE	Installation of cartridge boost electrical starter system. Reissued 5/15/72.	WE	77492	Talley Industries, Inc. 4551 E. McKellips Road P.O. Box 849 Mesa, AZ 85201
206A, 206B; T.C. H2SW	SH138WE	Installation of Chadwick cargo rack C-72. Issued 1/6/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH139WE	Installation of Chadwick C-22 auxiliary fuel system and C-30 ferry kit. Issued 1/7/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH148WE	Installation of Chadwick electronic weighing system C-45. Issued 5/26/72.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH158WE	Installation of Silver Star I anticollision light. Issued 7/9/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
206A, 206B; T.C. H2SW	SH209WE	Installation of type design change covering the SFENA ministab flight control system in various model combinations. Reissued 9/7/79.	WE	71450	SFENA Corporation 385 Reed Street Santa Clara, CA 95050
206A, 206B; T.C. H2SW	SA244NW	Installation of HE-206-010 bleed air heater system. Issued 3/2/76.	EA	35777	J.E. Flippo Rural Route 1, Pritchard Lane Westbank, B.C., Canada VCH-2A9
206A, 206B normal category; T.C. H2SW	SH266WE	Installation of Carter Engineering Model CEI 450-206 searchlight. Issued 2/8/80.	WE	19986	Carter Engineering Company 232 South Glasgow Avenue Inglewood, CA 90301
206A, 206B; T.C. H2SW	SH278NW	Installation of an electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems Inter'l 619 Riverside Drive Seattle, WA 98108
206A, 206B; T.C. H2SW	SH309AL	Installation of cargo basket. Amended 7/26/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH332AL	Installation of Airglas model L2700-206A skis. Amended 3/3/73.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH380AL	Installation of cargo baskets. Amended 8/7/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH474AL	Installation of Alaskan Sky-Craft Company, Inc. cargo step. Amended 7/20/73.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH515AL	Installation of ASC transporter cargo step. Amended 4/4/75.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH543NW	Installation of Bell 205 series cyclic stick grip. Issued 12/9/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH544NW	Installation of 28 volt DC power outlet in cabin. Issued 11/10/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH625NW	Installation of collective torque tube actuated hour meter switch and an engine-out audible warning system. Issued 6/28/78.	NW	85330	Weyerhaueser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH690NW	Installation of cyclic operated counter system. Issued 11/27/78.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH702NW	Installation of weighing system. Issued 1/23/79.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
206A, 206B; T.C. H2SW	SH759NW	Installation of an onboard weighing system. Issued 5/3/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
206A, 206B; T.C. H2SW	SH791NW	Installation of a model 50 spray system. Issued 6/26/79.	NW	66340	Rambling Rotors, Inc. Route 2, Box 244 La Grande, OR 97850

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206A, 206B; T.C. 42SW	SH848NW	Installation of a model 4900 spray system. Issued 10/22/79.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206A, 206B; T.C. H2SW	SH1062SO	Installation of fuel tank filler extension (increased fuel capacity).	SO	78475	Thoroughbred Helicopter Service, Inc. Route 3, Paris Pike Lexington, KY 40511
206A, 206B, 206L; T.C. H2SW	SH1125EA	Installation of Aircraft Parts Corp. starter-generator, P/N 150SG111C. Amended 11/27/78.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
206A, 206B; T.C. H2SW	SH1134SO	Installation of one-piece entrance step. Issued 2/19/80.	CE	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri City Airport Blountville, TN 37617
206A, 206B; T.C. H2SW	SH1753SW	Collapsible table and bar in passenger compartment. Issued 10/25/73.	SW	36550	Foster-Edward Aircraft Company 304 Fair Oaks Boulevard Euless, TX 76039
206A, 206B; T.C. H2SW	SH1754SW	Foxtronics/Tramm BTI 600 nickel-cadmium battery temperature system (single battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1755SW	Foxtronics/Tramm BTI 600 nickel-cadmium battery temperature system (dual battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1759SW	Ni-Cad battery overtemperature warning system. Issued 11/6/73.	SW	22280	Chrysler Corporation Space Division P.O. Box 29200 New Orleans, LA 70189
206A, 206B; T.C. H2SW	SH2889SW	Fuel filler neck.	SW	32758	Edwards & Associates, Inc. 13611 Heartside Place Dallas, TX 75234
206A, 206B; T.C. H2SW	SH4083SW	Install wire strike protection system. Issued 2/16/80.	SW	75234	Bristol Aerospace, Limited P.O. Box 340283 Dallas, TX 75234
206A, 206B, 206B-1; T.C. H2SW	SH164WE	Installation of A500 battery temperature monitor system. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
206A, B; 206L; T.C. H2SW	SA86GL	Installation of Marathon CA1700 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Co., Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48083
206A, 206B; 206L; T.C. H2SW	SH184WE	Installation of turbine over-temperature warning system. Amended 4/4/77.	WE	60425	MRSC Incorporated 10959 San Diego Mission Road San Diego, CA 92108
206A, 206B, 206L, 206L-1; T.C. H2SW	SH227WE	Installation of baggage compartment extension. Issued 11/3/78.	WE	50275	Ronald Leibin/Steve Crowe 2761 Hollywood Way Burbank, CA 91505
206A, 206B; 206L; T.C. H2SW	SH736SO	Installation of SAFT type 1656 nickel-cadmium electrical storage battery. Amended 11/19/76.	EA	69800	SAFT America, Inc. P.O. Box 1886 711 Industrial Boulevard Valdosta, GA 31601
206A, 206B, 206L; T.C. H2SW	SH1148EA	Installation of a modified Lear-Siegler starter-generator, P/N 23032-010. Amended 6/1/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
206A, 206B, 206L, 206L-1; T.C. H2SW	SH200GL	Installation of NI-CAD, Inc. Model No. 62239 engine lubrication system scavenge filter. Amended 6/22/79.	GL	61546	NI-CAD, Incorporated 24800 U.S. 20 South Bend, IN 46628
206A, 206B, 206L, 206L-1; T.C. H2SW Normal Category	SH244WE	Installation of cyclic support cover, P/N 2C086C Issued 10/9/79.	WE	50275	Stephen H. Crowe and Ronald A. Leibin 2761 Hollywood Way Burbank, CA 91505
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH247WE	Installation of Silver Instruments fueltron IG or IP digital fuel flow and totalizer system. Issued 9/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH252WE	Installation of SDI model CFS-1002, fuel flow indicating system. Issued 9/14/79	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH253WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 9/17/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206A, 206B, 206L-1; T.C. H2SW	SH198WE	Installation of tail rotor flood lights on the upper surfaces of horizontal stabilizers. Amended 6/28/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
206B; T.C. H2SW	SH5NE	Installation of revised instrument panel and installation of pressure operated gyro instrument back-up system. Issued 12/14/73.	NE	26550	Copters Unlimited, Inc. T.F. Green State Airport Warwick, RI 02886
206B; T.C. H2SW	SH134GL	Install Allison 250-C20B engine. Issued 9/10/76.	GL	14212	Aztec Aviation, Inc. Grissom Airport Bedford, IN 47421
206B; T.C. H2SW	SH174WE	Installation of Nightsun SX-16C searchlight. Issued 11/22/74.	WE	74500	Spectrolab Division of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
206B; T.C. H2SW	SH237WE	Installation of a "HCS-206" helicopter computer system. Issued 5/23/79.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
206B; T.C. H2SW	SH384GL	Installation of Tayburn Electronics, Inc. airborne television and microwave transmission system (electronic news gathering). Issued 1/31/80.	GL	02392	Aeronautical Systems, Inc. Lane Air Terminal P.O. Box 19824 Port Columbus Int'l. Airport Columbus, OH 43219
206B; T.C. H2SW	SH446NW	Installation of Simplex 5000 spray kit. Amended 6/30/78.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206B; T.C. H2SW	SH515NW	Installation of Pacific Forest Research Center Mark II aerial ignition system. Issued 9/13/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig HArbor, WA 98335
206B; T.C. H2SW	SH830NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705
206B; T.C. H2SW	SH1030CE	Installation of battery temperature monitor and over temperature warning system. Issued May 1974.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Wichita, KS 67202
206B Jet Ranger II and III; T.C. H2SW	SH1503CE	Installation of Collins APS-841H automatic flight control system. Amended 4/10/80.	CE	24250	Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
206B; T.C. H2SW	SH4076SW	Installation of public address system. Issued 1/18/80.	SW	11890	Associated Air Center 8201 Lemmon Avenue Dallas, TX 75220
206L; T.C. H2SW	SH586AL	Install Airglas Model L2700-206L skis. Issued 6/10/76.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
206L, 206L-1; T.C. H2SW	SH1541CE	Installation of Collins APS-841H helicopter automatic flight control system. Issued 4/21/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
212; T.C. H4SW	SH17NW	Installation of Chadwick Electronic weighing system C-47. Issued 2/16/73.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
212; T.C. H4SW	SH171WE	Installation of A500 battery temperature monitor systems. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
212; T.C. H4SW	SH205WE	Installation of tail/rotor flood lights on upper surface of the horizontal stabilizers. Issued 10/20/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
212; T.C. H4SW	SH256WE	Installation of emergency exit window. Reissued 1/11/80.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
212; T.C. H4SW	SH400NW	Installation of modified left hand door. Issued 1/20/77.	NW	33900	Evergreen Helicopters P.O. Box 358 McMinnville, OR 97128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
212; T.C. H4SW	SH449AL	Installation of Airglas model L8500A skis. Amended 6/10/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
212; T.C. H4SW	SH463NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
212; T.C. H4SW	SH467NW	Cargo release switch wired in series with spare switch on pilot's cyclic control grip. Issued 6/15/77.	NW	85330	Weyerhouser Company 28801 Airport Road Eugene, OR 97401
212; T.C. H4SW	SH942EA	Installation of Tramm BTI-600 battery temperature indicating system. Issued 12/26/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
212; T.C. H4SW	SH1281SW	Interior installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1284SW	Installation of Norton Company's radome and radar antenna brackets. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1286SW	Installation of Butler VAC/ADD area navigation system for VFR operation only. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1288SW	Installation of dual PC-17-400 Hertz static inverters. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn AVenue Burbank, CA 91505
212; T.C. H4SW	SH1289SW	Extension of power feeds to allow power distribution from the aft pedestal area. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1290SW	Installation of an extended instrument panel. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1333SW	Installation of weather radar equipment. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH2281SW	Environmental control unit. Issued 1/6/76.	SW	11890	Associated Air Center 7011 Lemmon Avenue Dallas, TX 75209
212; T.C. H4SW	SH2338SW	Modification for IFR type of operation. Issued 7/28/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220
212; T.C. H4SW	SH2466SW	AC inverter power system. Issued 5/24/77.	SW	11890	Associated Air Center, Inc. P.O. Box 20718 Love Field Dallas, TX 75220
212; T.C. H4SW	SH2746SW	Modification of four emergency exit panels. Issued 4/4/78.	SW	64300	Petroleum Helicopters, Inc. P.O. Box T Lafayette, LA 70502
212; T.C. H4SW	SH2892SW	Install 150 or 180 gallon auxiliary fuel tanks; standard utility seats modified; optional seats. Issued 12/21/78.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75222
214; T.C. H6SW	SH464NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems Inter'l. 619 Riverside Drive Seattle, WA 98108
214B, 214B-1; T.C. H6SW	SH2298SW	Interior arrangement and installation. Issued 3/2/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
7FC, 11AC; T.C. 759	SA1008WE	Installation of Poly-Fiber covering material (complete aircraft). Amended 8/21/79.	WE	75250	Stits Aircraft Coatings P.O. Box 3084 43rd South Fort Drive Riverside, CA 92519
7GC, 7GCB, 7GCBC, 7HC; T.C. 759	SA18CE	Installation of Pee-Kay Model 1800 or B1800 (TSO-C27-2) seaplane floats. Amended 8/17/73.	EA	29998	Pee-Kay Devore Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7GC, KC, GCB, GCA, GCAA, GCBC: T.C. 759	SA216AL	Install L-2500A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCA (landplane), 7GCB, 7GCBC (land and float plane); T.C. A-759	SA283AL	Installation of Hartzell HC 82XL-1, -2, or -6 propeller hub with 7636D-4 blades or HC-C2YL-1B hub with 7663-4 blades and appropriate Woodward governor. Amended 7/22/69.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
7GCA, 7GCB, 7KC, 7GCBA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
7GCAA, 7GCBC, 7KCAB; T.C. A-759	SA33GL	Installation of EDO Model 88A-1650 floats. Reissued 6/22/76.	GL	03480	Air-Ads-of-Dayton with Edo-Aire Seaplane Division 3800 Clearview Drive Dayton, OH 45439
7GCAA, 7GCBC, 7KCAB; T.C. A-759	SA1536WE	Installation of larger rudder. Reissued 6/5/69.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7GCAA, 7GCBC, 7KCAB, 14-19-3A, 17-30; T.C. 1A3, A-759	SA71GL	Install P/N SA8110 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities, Inc. 9600 West 52nd Street Kenosha, WI 53140
7GCB; T.C. 759	SA323AL	Installation of McCauley 1A175-GM8042 propeller.	AL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645
7GCBC; T.C. 759	SA266AL	Installation of L-2500 skis. Amended 6/21/68.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCBC; T.C. 759	SA520AL	Installation of leading edge cuff stall fences, tip fences. Amended 2/2/77.	AL	27250	Crosswinds, Inc. 2301-1/2 Merrill Field Drive Anchorage, AK 99507
7KCAB; T.C. A-759	SA25RM	Installation of Christen Model 801 Inverted Oil System. Issued 3/28/74.	RM	49369	Lloyd Land Star Route, Box 65A Hudson, CO 80642
8GCBC; T.C. A21CE	SA72GL	Installation of wheel replacement ski models M2000 and M3000. Issued 3/12/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
8GCBC; T.C. A21CE	SA530AL	Installation of Hartzell HC-C2YK-1BF/F7666A-0. Issued 10/21/74.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
8GCBC; T.C. A21CE	SA666AL	Installation of Fluidyne C3000A skis. Issued 7/17/79.	AL	35800	Flirite, Inc. P.O. Box 297 Kodiak, AK 99615
8GCBC; T.C. A21CE	SA741NW	Installation of EDO 689-2130 floats. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA742NW	Installation of Hartzell HC-C2YR-1BF/F7666A-0 propeller on a Lycoming O-360-C1E engine. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA743NW	Installation of Bellanca 72 gallon fuel system. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA1001EA	Installation of Pee-Kay Model 2300 (TSO-C27-2) seaplane floats. Issued 4/11/75.	EA	29998	Pee-Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
11AC; T.C. 761	SA4-95	Fiberglass cloth with resin over muslin applied.	WE	46783	R.W. Johnson Route 2, Box 571-B Ojai, CA 93023
11AC; T.C. 761	SA4-789	McCauley 1B90-CM/7045 propeller on Continental A-65-8 engine.	NW	68536	Paul H. Robinson 604 S. 136 Street Seattle, WA 98101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
11AC; T.C. 761	SA345CE	Remove right door.	CE	35650	Flanagan Aircraft 20224 R.D. Mize Road Independence, MO 64050
11AC, S11AC, 11BC; T.C. 761	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
11AC, S11AC, 11BC; T.C. 761	SA4-1276	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
11AC, S11AC, 11BC, S11BC, 11CC, S11CC; T.C. A-761, A-796	SA57RM	Installation of Lycoming O-235-C1 or O-235-C2C engine. Issued 6/19/75.	RM	84393	Colman L. Wagner 401 1st Street East Clark, SD 57225
11AC, 11BC; T.C. 761	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
11AC, 11BC, 11CC; T.C. 761, 796	SA217AL	Install L-1650A or L-2000A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
11AC, 11BC, 11CC; T.C. 761, 796	SA535AL	Installation of wing auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
11BC; T.C. 761	SA3-7	Installation of Pee-Kay Model 1500 floats with Edo struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC; T.C. 796	SA3-115	Model 3000 main ski and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
11CC; T.C. 796	SA3-670	Install Pee-Kay Model 1500 floats with Edo struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC; T.C. 796	SA69SO	Continental C85-12F Series engine less starter and generator.	SO	45720	C.W. Lasher 14100 NW. 62 Court Miami, FL 33012
11CC; T.C. 796	SA262CE	Manufacture parts and install 12-30A electrical system. (Requires alteration of engine per STC SE3CE.)	GL	67160	Kenneth L. Repke 7788 Auburn Detroit, MI 48233
11CC, S11CC; T.C. 796	SA4-1270	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13, 14-19, 14-19-2, -19-3, -19-3A, 17-30, -31, -31A, -31TC, -31ATC; T.C. 1A3, 773	SA846SW	Wing root fairings. Reissued 11/27/78.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
14-19 Series; T.C. 1A3	SA1-551	Fuselage and fin covered with metal skin.	EA	72100	Skycraft Design, Inc. Mercer County Airport West Trenton, NJ 08628
14-19 Series; T.C. 1A3	SA4-867	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series; T.C. 1A3	SA4-883	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series; T.C. 1A3	SA4-909	Autopilot. Reissued October 1973.	WE	17492	Brittain Industries, Inc. 12027 S. Prairie Avenue Hawthorne, CA 90250
14-19 Series; T.C. 1A3	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
14-19 Series; T.C. 1A3	SA4-1127	Ceconite 101 covering of entire aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-19 Series; T.C. 1A3	SA4-1269	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
14-19 Series; T.C. 1A3	SA4-1283	Ceconite 103 covering of plywood portions of the aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707 Series; T.C. 4A26	SA511CE	Autopilot variable angle intercept installation. Amended 7/1/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A26	SA511EA-D	Modification of life raft overhead stowage compartment.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA513EA-D	Install water tank assembly in forward baggage compartment.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA533EA	Installation of Dual Bendix DRA-12 Doppler and CPA-24 Computer Systems. Relocation of existing EDO Loran System to Cockpit Pedestal Area. Amended 11/27/67.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A26	SA1424WE	Installation of REA Express 7 Arts Transvision Inflight Motion Picture System.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
707 Series; T.C. 4A26	SA1442WE	Installation of inflight motion picture projection system.	WE	25917	Consolidated Electrodynamics Corp. 360 Sierra Madre Villa Pasadena, CA 91100
707 Series; T.C. 4A26	SA1499WE	Installation of Class Partition Assembly System.	EA	62300	Pan American World Airways, Inc. 200 Park Avenue New York, NY 10017
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA4-1559	Preloaded aluminum baggage container and base fabricated.	WE	36180	John Bean Division of Food Machinery & Chemical Corp. 1115 Coleman Avenue San Jose, CA 95125
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA166SO	Low range radar altimeter system.	SO	62300	Pan American World Airways, Inc. Pan American Building Miami, FL 33159
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA183EA	Mansfield aft and forward bar units in passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 E. 42 Street New York, NY 10001
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA240SW	Seat loaded cargo containers.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA402SW	Dual Collins FD-108 flight director system.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA509EA	Install a standby horizon system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA516EA-D	Install 30 cps chokes in Bendix Course Indicator P/N 7236.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA734WE	Closed-circuit television and stereo system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA1128WE	Cockpit voice recorder.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA1221WE	Dual Collins AL-101 low range radio altimeter. Amended 12/29/66.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA1281WE	Fire detector system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 and 720 airplanes equipped with Boeing P/N 65-11685 and 65-68862 forward thrust reverser doors; T.C. 4A21, 4A26, 4A28	SA1388CE	Replace magnesium or aluminum forward thrust reverser blocker doors with nylon doors. Issued 12/8/77.	CE	65330	Progressive Manufacturing Co. 1101 S. Ninth Street Kansas City, KS 66105
707, 720 Series; T.C. 4A21, 4A28	SA502EA-D	Install a triple class cabin divider to partition the area between the economy and coach passengers. Amended 11/17/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707/720; T.C. 4A26, 4A28	SA2163WE	Installation of door mounted emergency light. Amended 9/28/70.	WE	44266	International Inflatables Company Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707/720; T.C. 4A26, 4A28	SA2281WE	Installation of pneumatic butterfly-shutoff valve, P/N 397794-1-1. Issued 12/7/70.	WE	07502	AiResearch Manufacturing Company 402 South 36th Street Phoenix, AZ 85034
707/720; T.C. 4A26, 4A28	SA2282WE	Installation of fluid pressure regulating valve, P/N 898304-1-1. Issued 12/7/71.	WE	07502	AiResearch Manufacturing Company 402 South 36th Street Phoenix, AZ 85034
707/720; T.C. 4A26, 4A28	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans AVenue San Francisco, CA 94124
707, 720 Series; T.C. 4A21, 4A28	SA2637WE	Installation of aft thrust reverser lower latch hook bearings. Issued 1/3/73.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85281
707, 720, 727, 737; T.C. 4A21, 4A26, A3WE, A16WE, 4A28	SA2728WE	Incorporation of HI-LITE SYSTEM P/N 50-1001 for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation 857 Thornton Street San Leandro, CA 94577
707, 727; T.C. 4A26, A3WE	SA2451SW	Marathon Battery Co. part 85-0050 six cell magnesium emergency light pack. Issued 4/20/77.	SW	54810	Marathon Battery Company 8301 Imperial Drive Waco, TX 76710
707, 727; T.C. 4A26, A3WE	SA481EA	Installation of pallet nets. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707; 727; 737; T.C. 4A21, 4A26, 4A28, A3WE, A16WE	SA863EA	Incorporation of DME Corporation emergency evacuation slide lighting system, Model ESL-1, -6, -6-1. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707, 727, 747, 747SP; T.C. 4A26, A3WE, A2WE	SA1967SW	Model LD-8 liquor dispenser. Issued 4/4/75.	SW	16896	Booth, Inc. 1725 Bandy Lake Road Carrollton, TX 75006
707-100, -100B, -200; T.C. 4A21	SA172GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	CE	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
707-100, -100B, -200; T.C. 4A21	SA719CE	Installation of Kollsman altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City International Airport Kansas City, MO 64153
707-100 long body, -100B long body, -100B short body, -200; T.C. 4A21	SA3712WE	Installation of a 40" x 56" adjustable height, folding leaf table. Issued 8/17/78.	WE	28125	Custom Products Company 11626 Tuxford Street Sun Valley, CA 91352
707-100 long body, -100B long body, -100B short body, -200; T.C. 4A21	SA3713WE	Installation of a 40" x 67.25" adjustable height, folding leaf table. Issued 8/17/78.	WE	28125	Custom Products Company 11626 Tuxford Street Sun Valley, CA 91352
707-100, -100B, -200; T.C. 4A21	SA3756WE	Installation of stretcher carrier, P/N AM2003. Issued 10/11/78.	WE	08205	Air Medica, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
707-100, -102B (short-body); T.C. 4A21	SA4025SW	Structural provisions of mid-lavatory service pan. Issued 7/27/79.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
707-100, -200, -300, 720; T.C. 4A21, 4A26, 4A28	SA2EA	Replacement of universal type drive shaft P/N 204679 with Bendix flexible drive shaft model 19E40-1B between the P&W J3C or JT4A series engine mounted gearbox and Sundstrand constant speed drive. Amended 7/23/75.	EA	16000	Bendix Fluid Power Division The Bendix Corporation 211 Seward Avenue Utica, NY 13503
707-100, -100B Long Body, -100B Short Body, -200; 707-300, -400, -300B, -300C; 720, 720B; 727, 727C, 727-200; 737-100, -200, -200C; 747-100, -200B, -200F; T.C. 4A21, 4A26, 4A28, A3WE, A16WE, A20WE	SA10GL	Installation of Gayston Model 800LG and 800SG static dischargers on transport category airplanes. Issued 12/15/72.	GL	37125	Gayston Corporation 55 Janney Road Dayton, OH 45404

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-100, -200; 707-300; 720; 727, 727C, -200; 737; T.C. 4A21, 4A26, 4A28, A3WE, 4A27	SA2534SW-D	Replacement of Switch assembly International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707-100, -200; 707-300; 720; 727, 727C, 727-200; 737; T.C. 4A21, 4A26, 4A28, A3WE, A16WE	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, and EL-104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707-100, -100B, -200, -300, -400, 720, 720B; T.C. 4A21, 4A26, 4A28	SA2579WE	Modify airplanes by the installation of wing tip mounted emblem light. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
707-100/100B, -200, -300/300B/300C, 720/720B; T.C. 4A21, 4A26, 4A28	SA2605WE	Installation of turbine thrust reverser linkage. Amended 8/2/73.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
707-100B; T.C. 4A21	SA984CE-D	Increase maximum zero fuel weight. Issued 9/22/76.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-100B, -300B, 720; T.C. 4A21, 4A26, 4A28	SA2635WE	Installation of forward fan thrust reverser bearings. Issued 1/11/73.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85282
707-121, -139, -321, -321B, -331, -321C, 720-023B, -030B; T.C. 4A21, 4A28	SA311EA	Installation of Aerotherm Corp. Model 1003 stretcher. Reissued 12/5/72.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-121, -139, -321, -321B, -321C, -331, 720-023B, -030B, 737- 100, -200; T.C. 4A21, 4A26, 4A28, A16WE	SA677CE	Installation of Crimsco cargo container, P/N 600301, in passenger compartment. Amended December 1974.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
707-121B Series; T.C. 4A21	SA531EA	Installation of EMCC autopilot monitoring system Model No. APMS-E. Amended 9/27/68.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707-121B, -123B, -139B, -227, -321, -321B, -321C, -323C, -327C, -331, -123, -155C, -295; 720-023B, -027, -030B, -048, -062, 727-21C, -21, -27, -27C, -81, -90C, -95; T.C. 4A28, 4A21, 4A26, A3WE, 4A25	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 12/10/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-121B, -139B; T.C. 4A21	ST655SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in forward passenger compartment.	SO	67030	Mace Unit of REF Dynamics, UCP 5846 Victor Street Jacksonville, FL 32207
707-121B, -139B; 707- 321, -321B, -321C, -331; 720-023B, -030B; 727-21, -21C; 747-121; T.C. 4A21, 4A26, 4A28, A3WE, A20WE	ST706SO-D	Installation of Skydrol 500C hydraulic fluid. Reissued 9/7/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-121B, -139B; 707- 321, -321B, -321C, -331; 720-023B, -030B; T.C. 4A21, 4A26, 4A28	ST708SO-D	Installation of an REF Dynamics carry-on baggage compartment. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-121B, -139B; 707- 321, -321B, -321C; 707-331; 720-023B, -030B; T.C. 4A21, 4A26, 4A28	ST711SO-D	Installation of door mounted evacuation slide illumination lights. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-123B; T.C. 4A21	SA405EA-D	Convert all Boeing 707-123B aircraft to winter configuration. Amended 10/10/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 707-323B, 707-323C; T.C. 4A21, 4A26	SA401EA-D	Installation of door mounted evacuation slides on forward and aft entry doors and forward and aft galley service doors. Amended 9/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-123B, 707-323B and 707-323C; T.C. 4A21, 4A26	SA415EA-D	Installation of Bell & Howell projection system in 707-123B, install Bell & Howell projection system in 707-323C, install Bell & Howell projection system in 707-323B. Amended 4/21/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 720B-023; T.C. 4A21, 4A28	SA551EA-D	Installation of autopilot go-around unit. Amended 8/11/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, -323C, -323B, 720-023B, 727-23, -35, -95, -123, -223; T.C. A3WE, 4A28, 4A21	SA554EA-D	Install underseat luggage retention device.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707-123B, -138, -323CC, -023B; T.C. 4A21, 4A26, 4A28	SA555EA-D	To comply with FAR 25.812(e), a lever lock switch will be installed at a point accessible to the forward flight attendant seat. Amended 4/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B; T.C. 4A21	SA983CE-D	Cargo door and interior installation non-convertible air freighter. Issued 5/24/76.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-123B; T.C. 4A21	SA4053WE	Installation of an auxiliary fuel tank system consiting of two identical tank assemblies located in the forward cargo compartment and one located in the aft cargo compartment. Issued 10/30/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
707-123B, -138B; T.C. 4A21	SA3257WE	Installation of AiResearch GTCP 85-98CK auxiliary power unit in forward cargo compartment. Amended 8/18/78.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-123B, 707-138B; T.C. 4A21	SA3441WE	Installation of airstairs. Amended 3/15/79.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
707-124 Series; T.C. 4A21	SA582CE	Relocation of Lockheed Aircraft Service Model 109CR, flight recorder to aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA584CE	Autopilot modification to incorporate variable intercept feature.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA585CE	Installation of Fairchild Cockpit Voice Recorder System.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA586CE	Installation of Fenwall fuel vent surge tank protection system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA627CE	Installation of (1) dual radio altimeter provisions (2) single Bendix ALA-51 radio altimeter transmitter-receiver with dual indicators.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131; T.C. 4A21	SA439CE	Installation of logo lights on horizontal stabilizer. Amended 11/25/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131; T.C. 4A21	SA556CE	Installation of auto-thrust provisions. Amended 3/19/69.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-124/-131/-131B; 707-331/-331B/-331C/ -373; T.C. 4A21, 4A26	SA577CE	Replace Bendix type 15866, 15897 and 19903 vertical gyros with Bendix type 19911 or 19912 vertical gyros.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, 131, -131B- -331, -331B, -373C, -338C; T.C. 4A21, 4A26	SA680CE	Modify the A.C. essential bus power source circuitry to provide automatic transfer. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131, -131B, -331, -331B, -331C; T.C. 4A21, 4A26	SA682CE	Install Litton Model E-30 microwave oven.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131; T.C. 4A21	SA555CE	Installation of a single SCAT system. Amended 3/19/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

Rev. 6/30/80

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-131; T.C. 4A21	SA862CE	Addition of large cargo door in left hand side of fuselage. Issued August 1972.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-131, -131B; T.C. 4A21	SA607CE	Installation of provisions for dual radio altimeters and single Bendix Model ALA-51A equipment. Amended 4/29/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131, -131B, 331, 331B, 331C; T.C. 4A21, 4A26	SA3-708	Install motion picture projector and screen. Amended 12/27/67.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131, -131B, 720B; T.C. 4A21, 4A28	SA432CE	Installation of Fenwall fuel vent surge tank protection system. Amended 8/22/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA197CE	Installation of a single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA298CE	Installation of a single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA488CE	Relocation of LAS Model 109CR flight recorder.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA1052CE	Replacement of existing fire detection system with a Kidde dual loop fire detection system. Issued September 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA1520CE	Installation of a Growth Industries dual cavity oven. Issued 10/31/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-131B, -331B, 331, 331C, 373, 338C; T.C. 4A21, 4A26	SA519CE	Installation of logo lights in horizontal stabilizer. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131/-131B/-331/-331B/-331C/-373C, 338; T.C. 4A21, 4A27	SA827CE	Install Butler National Corp. flight recorder/communications interface unit. Amended April 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B, -331B, -331C; T.C. 4A26	SA1478CE	Installation of pitot heater failure indication system. Issued 3/22/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-138B; T.C. 4A21	SA797EA	Installation of inflight motion picture system. Reissued 2/26/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-138B; T.C. 4A21	SA1132EA	Installation of two Solar Model T-62T-40C2 APU's for ground use only. Amended 11/8/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
707-138B; T.C. 4A21	SA1136EA	Installation of an onboard passenger loading stairs. Amended 12/14/78.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
707-138B; T.C. 4A21	SA1403WE	Interior arrangements.	NW	74920	Standard Airways, Inc. Tower Building Seventh and Olive Streets Seattle, WA 98101
707-138B; T.C. 4A21	SA3320WE	Installation of radio altimeter system No. 1. Issued 1/17/77.	WE	13970	Aviation Service & Support Corp. 4150 Donald Douglas Drive Long Beach, CA 90801
707-139B Series; T.C. 4A21	SA687EA	Installation of Data Link System.	EA	62300	Pan American World Airways, Inc. JFK International Airport Hangar 17 - Room 2011 Jamaica, NY 11430
707-139B, -121B, 720-023B, -030B; T.C. 4A21, 4A28	SA1937WE	Installation of under-seat baggage restraint system. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-153B; T.C. 4A21	SA81NW	Minor modifications to pilot's instrument panel and relocation of autopilot accelerometer and rate gyros for improved performance. Amended 12/7/73.	SW	24252	Collins Radio Company Avionics Systems Center P.O. Box 98 Addison, TX 75001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-153B; T.C. 4A21	SA856EA	Installation of a compartment bulkhead at fuselage station 978. Issued 12/22/70.	EA	80910	Department of the Air Force Hq. 89th Military Airlift Wing (SM)MAC Andrews Air Force Base Washington, D.C. 20331
707-153B; T.C. 4A21	SA1700WE	Installation of Dual Litton LTN-51 Inertial Navigation Systems. Amended 10/21/68.	WE	51500	Litton Systems, Inc. Guidance & Control Systems Div. 5500 Canoga Avenue Woodland Hills, CA 91364
707-153B, -353B; T.C. 4A21, 4A26	SA350EA	Passenger Berth Installations. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Company P.O. Box 33 Ontario, CA 91761
707-153B, -353B; T.C. 4A21, 4A26	SA648EA	Modification of Collins FD109G Flight Director.	EA	80910	Department of the Air Force Hq. 89th Military Wing (SM) MAC Andrews Air Force Base Washington, D.C. 20331
707-153B, -353B; T.C. 4A21, 4A26	SA858EA	Modification of rigid high pressure starter air lines on numbers 2 and 3 engines. Issued 12/29/70.	EA	80910	Department of the Air Force Hq. 89th Military Airlift Wing (SM)MAC Andrews Air Force Base Washington, D.C. 20331
707-227, 720-027; T.C. 4A21, 4A28	SA1138WE	Installation of fire warning monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Canoga Park, CA 91304
707-300; T.C. 4A26	SA208NW	Installation of Fairchild Stan (R) weight and balance system. Issued 10/21/75.	NW	08350	Air Repair, Inc. 811 West Perimeter Road Renton, WA 98055
707-300 Series; T.C. 4A26	SA3599WE	Installation of single or dual Litton LTN-201 Omega navigation as a means to update INS or doppler in the NAT MNPS airspace. Amended 5/8/78.	WE	51500	Litton Aero Products Division 6700 Eaton Avenue Canoga Park, CA 91303
707-300, -300B, -300C, -400; T.C. 4A26	SA171GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	CE	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
707-300, -300B, -300C, -400 Series; T.C. 4A26	ST661SO	Installation of dual band "C/X" type weather radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Company P.O. Box 350 Akron, OH 44309
707-300, -300B, -300C, -400 Series; T.C. 4A26	SA3167WE	Installation of dual Litton LTN-51 inertial navigation systems. Issued 4/5/76.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
707-300, -300B, -300C, -400, 338C; T.C. 4A26	SA726CE	Installation of Kollsman altitude alerting system. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-300, -300B, -300C, 707-400 Series; T.C. 4A26	SA3486WE	Installation of dual Litton LTN-51, or dual Litton LTN-72, or one Litton LTN-72 inertial navigation systems. Issued 11/3/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91364
707-300, -300B, -300C, -400; T.C. 4A26	SA3830WE	Installation of dual Delco C-IVA inertial navigation system. Amended 10/17/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
707-300, -300B, -300C; T.C. 4A26	SA4097WE	Installation of forward entrance airstair. Issued 2/5/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanover Street Van Nuys, CA 91406
707-300 and 707-400 Series; T.C. 4A26	ST914SO	Installation of cargo floor - Model 707-300 series; 707-400 series installation of secondary main landing gear position lights.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-300, -400; T.C. 4A26	SA3331WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
707-300B, -300C; T.C. 4A26	SA817NW	Modification of cabin passenger interior, and forward storage units. Issued 8/8/79.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
707-300B, -300C; T.C. 4A26	SA2594WE	Modify 707-300B and -300C series airplanes by the installation of wing tip mounted emblem light. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-300B, -300C; T.C. 4A26	SA2610WE	Installation of Bell & Howell movie projection system Nos. 478441 and 478440. Issued 1/11/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
707-300C, 727C; T.C. 4A26, A3WE	SA647SO	Installation of AIF partition class divider P/Ns 402-1, 402-2, 402-3, 402-4, and header assembly P/Ns 403-1 and 404-1. Amended 7/16/68.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33142
707-300C Series; T.C. 4A26	ST939SO	Installation of livestock pen. Issued 6/10/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-300C Series; T.C. 4A26	SA1443WE	Installation of tray carrier.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-320; T.C. 4A26	SA2374WE	Installation of an air filter to the cabin pressure limit control outflow safety valve, P/N 103430-3. Issued 6/24/71.	WE	07505	AiResearch Manufacturing Company 2525 W. 190th Street Torrance, CA 90509
707-320C; T.C. 4A26	SA251NW	Installation of cargo system. Issued 1/16/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
707-320C Series; T.C. 4A26	SA3539WE	Installation of single, palletized Litton LTN-51 or LTN-72 inertial navigation system. Issued 12/20/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
707-321; T.C. 4A26	ST710SO-D	Relocation of "E" galley approximately 10" forward of present location. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321; T.C. 4A26	SA778CE	Addition of large cargo door in left hand side of fuselage. Issued June 1971.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA852CE-D	Reduction of empty weight by removal of all passenger interior equipment and installation of fire resistant lining. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA1555WE	Installation of fire warning electrical monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Canoga Park, CA 91304
707-321, -321B; T.C. 4A26	SA344EA	Install inertial navigation system. Amended 4/1/66.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321, -321B, -321C, -331, -386C; T.C. 4A26	ST652SO-D	Installation of P&W JT8D engine and associated structural and fairing pod under L.H. wing between No. 2 engine and fuselage. Reissued 9/7/78.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
707-321, -321B, -331; T.C. 4A26	ST656SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in the forward passenger compartment. Amended 11/6/68.	SO	67030	Mace Unit of REF Dynamics, UOP 4856 Victor Street Jacksonville, Fl 32207
707-321, -321B, -321C, -331; T.C. 4A26	ST712SO-D	Modification and installation of a Hardman Model 6747 seat. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321, -324C; T.C. 4A26	SA2238WE	Installation of Brownline Cargo net assembly #41412 used in conjunction with Brownline pallet assemblies #40160 and 40144. Amended 5/16/75.	WE	17740	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321, -331, 720-040B; T.C. 4A26, 4A28	SA1-593	See Document No. Report No. 3078, dated January 30, 1969, concerning pallet assembly IR-3000 Rev. B. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-321, -400; T.C. 4A26	ST914SO	Installation of cargo floor. Amended 1/19/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-321B; T.C. 4A26	SA611EA	Installation of dual A.C. electronics navigation systems on R/N N435PA, S/N 5034. Amended 5/21/68.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B; T.C. 4A26	ST702SO-D	Installation of Bendix FINDS. Limited to aircraft N421PA S/N 19266. Issued 11/15/68.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST707SO-D	Modified aircraft to incorporate Emerson engine performance monitoring system, aircraft S/N 19363, N428PA. Issued 10/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST713SO-D	Installation of a coat closet between fuselage stations 373 and 414 L.H. side. Reissued 9/12/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B; T.C. 4A26	SA1067EA	Installation of stowage cabinets Issued 12/16/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
707-321B; T.C. 4A26	SA3549WE	Installation of Garrett GTCP85-58CK auxiliary power unit in forward baggage compartment. Issued 1/27/78.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-321B, 321C; T.C. 4A26	ST709SO-D	Installation of flight spares container in right hand main landing gear wheel well on fuselage station 960 bulkhead. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	SA700EA	Switches are installed on outboard thrust levers to disengage autothrottle system.	EA	62300	Pan American World Airways, Inc. Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	ST704SO-D	Installation of Bell & Howell forward projection movie system. Reissued 9/7/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321-B, -321C; T.C. 4A26	SA1076EA-D	Removal of Loran navigation system and installation of dual Omega navigation systems for updating doppler. Amended 8/13/79.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321C; T.C. 4A26	SA541NW	Installation of quick change interior. Issued 1/18/78.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98021
707-321C; T.C. 4A26	SA1134WE	Palletized cargo system installation 65-42629 or 65-43629 with Brownline pallet 22630-51, 26100-51 or -52 and Brownline net assy 23225-51, 23226-51, or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1143WE	Installation of Boeing palletized cargo system. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1293WE	Palletized cargo system installation 65-42629 with Brownline pallet 22630-51 and net assy 23225-51 or 23226-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1597WE	Installation of Heath Tecna Corporation pallet AC-10065 and Brownline Corporation Net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C; T.C. 4A26	SA2125WE	Installation of Ancra Cargo Net Assembly 40234-10 used in conjunction with either Brownline pallet assembly 22630-51 or Heath Tecna pallet assembly AC 10065-1.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 90245
707-321C; T.C. 4A26	SA2221WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp Net Assembly 40234-10 and net assemblies approved to NAS 3610-2A1N and NAS 3610-2A3N. Issued 8/19/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-321C; T.C. 4A26	SA3005WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-321C, 727-21C; T.C. 4A26, A3WE	SA736EA	Installation of L. Marino forward cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-321C, 727-21C; T.C. 4A26, A3WE	SA1859WE	Installation of net assembly AC-10292-1 used in conjunction with pallet assembly AC-10065-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C, 727-21C; T.C. 4A26, A3WE	SA2045WE	Modification by installation of pallet assembly 40160 used in conjunction with net assemblies 23225-51, 23226-51, 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; 727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA849EA	Goodyear Aerospace Corporation cargo pallet (1.5 Fwd.) P/N 634A303-001-101 is eligible to be used only in combination(s) as shown in the following tables:	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315

BOEING COMPANY			CARGO NET	
AIRPLANE MODEL	CARGO RESTRAINT SYSTEM	WEIGHT & BALANCE CONTROL MANUAL (b)	MANUFACTURER & PART NO.	TIE-DOWN CONFIGURATION
707-321C (a)	65-42629 65-43629	D6-14083.6	Brownline 40510-101 22758-51 23225-51	88" x 125"
			Marino LM1500-100	88" x 125"
			Brownline 21970-51 (Chg. G)	88" x 108"
727-21C (a)	65-49102	D6-21000.17C	Brownline 40510-101 22758-51 23225-51 23226-51	88" x 125"
			Marino LM1500-100	88" x 125"
			Brownline 21970-51 (Chg. G)	88" x 108"
747-121	65B-60060 Lower Lobe Compartment Aft Hold ONLY	D6-13700	Brownline 22758-51	88" x 125"

(a) Barrier Net Installation per Boeing Drawing 65-34700-1 required for these model aircraft with this installation.

(b) The applicable Boeing Weight and Balance Control Manual must be used to obtain permissible compartment load, under conditions described therein, not to exceed the pallet-net combination(s) capacity of 13,300 lb. for the 88" x 125" tie down configuration or 8000 lb. for the 88" x 108" tie down configuration.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-321C;727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA1902WE	Installation of Irvin cargo pallet assembly 125014 used in conjunction with net assembly 22758-51 (Brownline), net assembly 40234010 (ANCRA), and net assembly LMI-500-100 (Marino). Amended 8/25/70.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
707-321C, 727-21C; T.C. 4A26, A3WE	SA2103WE	Installation of Net Assembly 40510-101 used in conjunction with Brownline Pallet Assemblies 40160-101 thru -100, 22630-51 and Heath Pallet AC-10065-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323, 707-385C; 707-323B; T.C. 4A26	SA517EA-D	Installation of dual Litton LTN-51 inertial navigation systems. Install No. 2 ship's battery (24 volts, 36 AH) to provide standby DC power for No. 2 inertial navigation system. Installation perforated filler panels fore and aft of both control/display units. Amended 1/22/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA556EA-D	Convert interior passenger arrangement to winter configuration of 4 first class lounge, 32 first class seats and 101 tourist class seats. Amended	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-323B; T.C. 4A26	SA561EA-D	Installation of automatic throttle/ speed control system. Amended 3/2/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA562EA-D	Installation of dual aileron and elevator surface servos to operate in a single servo configuration with the PB20 autopilot system. Amended 3/31/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA564EA-D	Modify the interior arrangement of the 707-323B aircraft from its present configuration to 32 F/C plus 102 T/C passencer. Install additional meal stowage. Issued 5/18/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA508EA-D	Install a single inertial navigation system (LTN-51E). Amended 1/5/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74116
707-323C; T.C. 4A26	SA525EA-D	Convert interior passenger arrangement to the summer configuration of four first class lounge, 26 first class, and 113 tourist class seats. Amended 4/15/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA559EA-D	Interior arrangement and configuration.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA565EA-D	Install emergency evacuation slide lights for station 990. Issued 6/17/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA1560WE	Installation of Aeronca cargo containers on Boeing 707-323C.	WE	02398	Aeronca, Inc. Aerocal Division 24751 S. Crenshaw Boulevard Torrance, CA 90505
707-323C; T.C. 4A26	SA1720WE	Installation of Heath Tecna structural igloo assembly AC-0123. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2008WE	Installation of structural cargo container AC-10260-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2401WE	Installation of Transequip structural igloo assembly P/N 245084 in conjunction with loading systems 65-42625, 65-42630, and 64-34899. Issued 8/26/71.	WE	79000	Transequip, Inc. 5438 W. 104th Street Los Angeles, CA 90045
707-323C; T.C. 4A26	SA2453WE	Installation of Transequip structural containers in position I13 (container 235111) and position I14 (container 235112). Amended 10/30/79.	WE	79000	Transequip, Inc. 5438 West 104th Street Los Angeles, CA 90045
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2022WE	Installation of pallet assembly 40122-101, -102, -103, -104, and -105 used in conjunction with net assemblies 22178-51, 23652-51, 22361-51c, 22780-51, 22780-52, 22656-51, 22656-52, and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2174WE	Installation of pallet assembly 40550-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22362-51 or AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -331C, 373C, 385C; 727-31C, -180C; T.C. 4A26, A3WE	SA1924WE	Installation of Irvin cargo pallet assembly 125001-501, -503, -505, -507 used in conjunction with net assembly 10-60934-1 (Boeing).	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
707-323C, -331C, -373C, 727-1A7C, -31C, -180C; T.C. 4A26, A3WE	SA2098WE	Installation of structural cargo container 40619-101, -103. Amended 5/16/75.	WE	17740	Brooks & Perkins 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA945WE	Installation of autopilot go-around unit. Amended 8/1/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-323C and 707-385C; T.C. 4A26	SA1524WE	Brownline Structural Containers 23885-51 may be used as optional cargo equipment either in place of or with cargo net assemblies. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA1939WE	Modify by installation of structural cargo container 24385-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA2234WE	Installation of Brownline Division structural container No. 41342-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -385C; 727-22C; T.C. 4A26	SA2278WE	Installation of Brownline cargo container model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division Torrance, CA 90505
707-326C; T.C. 4A26	ST701SO-D	Installation of alternate inertial navigation system control display unit. Limited to aircraft N870PA, S/N 20016; N871PA, S/N 20017; N872PA, S/N 20018. Amended 6/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-327C; T.C. 4A26	SA739EA	Installation of Inflight Motion Picture System. Reissued 10/24/73.	EA	11434	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-327C, -330C, -338C, -351C, 727-25C, -27C, -30C, -51C, -62C; T.C. 4A26, A3WE	SA2026WE	Installation of pallet assembly 40134-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22364-51, 23215-51, 23618-51 or 23783-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-327C; T.C. 4A21	SA2748WE	Installation of weight and balance computer system. Issued 8/15/73.	WE	52010	Lockheed Aircraft Service Company Ontario International Airport P.O. Box 33 Ontario, CA 91764
707-330C, 727-30C; T.C. A3WE	SA1917WE	The type design change consists of installation of pallet assembly 24076-51 in conjunction with net assembly 22361-51, 22364-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-331; T.C. 4A26	SA428CE	Installation of single scat system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA489CE	Relocation of Lockheed Air Service Model 109CR flight recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA635CE	Installation of dual radio altimeter system provisions and single radio altimeter equipment. Amended 2/20/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA854CE-D	60,000 lbs. main deck allowable loading. Issued 12/7/73.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-331; T.C. 4A26	SA1551WE	Installation of fire warning monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Conoga Park, CA 91304
707-331, 707-331 (ADV); T.C. 4A26	SA291CE	Installation of single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331, -331B, -331C, -373C, -338C; T.C. 4A26	SA465CE	Installation of Fenwall fuel vent surge tank. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64108
707-331 (Advanced), -331C, -338C, -373C; T.C. 4A26	SA899CE	To permit autopilot coupled approaches at 40 degrees flp setting below 500 feet. Issued August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331, -331B, -331B(ADV), -331C, -373C; T.C. 4A26	SA1327CE	Installation of Bendix ONS-25-5 Omega navigation system for updating primary self-contained navigation system. Issued March 1977.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-331, -373C, 727-31A, -180C; T.C. 4A26, A3WE	SA2290WE	Installation of Ancra pallet net assembly P/N 40452-10 used in conjunction with Boeing 9g pallet assemblies (88" x 125") numbers 10-60935-1, 10-60935-11, 10-60935-17, 10-60935-21, 10-60935-27 and 10-60935-37. Amended 2/22/71.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 990245
707-331B, -331C; T.C. 4A26	SA1518CE	Installation of a Growth Industries dual cavity oven. Issued 10/18/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-331B, -331C, -338C, -373; T.C. 4A26	SA1039CE	Replacement of existing fire detection system with a Kidde dual loop fire detection system. Issued September 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C; T.C. 4A26	SA523CE	Installation of single SCAT system. Amended 7/31/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C; T.C. 4A26	SA524CE	Installation of auto throttle system. Amended 7/1/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C; T.C. 4A26	SA658CE	Installation of dual radio altimeter provisions single equipment.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331 (Convertible), 707-338C; T.C. 4A26	SA234CE	Autopilot variable angle intercept installation. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C, -338C; T.C. 4A26	SA385CE	Installation of single SCAT system. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C, -338C; T.C. 4A26	SA386CE	Installation of auto thrust system. Amended 8/7/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C, -373C, -338C; T.C. 4A26	SA783CE	Installation of revised life raft and courier seat provisions. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA757EA	Goodyear Aerospace Corporation Cargo pallet with barrier net installation. Amended 3/17/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massilon Road Akron, OH 44315
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1866WE	Installation of Heathair AC-10113-1 net assembly in conjunction with pallet assemblies AC-10070-1 and AC-10347-1. Reissued 1/6/71.	NW	41625	Heath Techna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1963WE	Installation of pallet assembly 23250-52 used in conjunction with net assemblies 22178-51, 22780-52, 22656-51, 22656-52 and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2172WE	Installation of Irvin Industries Net Assembly 120012-501 used in conjunction with Cargo Pallet 125001-501, -503, -505, -507. Issued 8/19/70.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2412WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, 727-31C; T.C. 4A26, A3WE	SA2088WE	Installation of cargo pallet assemblies 1950-90-501 and 1950-90-1001 used in conjunction with net assembly 22758-51 (Brownline).	WE	19890	Cargo Systems, Inc. 1040 West Hoover Street Orange, CA 92667
707-338C; T.C. 4A26	SA730EA	9G 10,000 lb. maximum capacity Pallet Cargo Net P/N LM 1505-1 eligible as replacement for approved Brownline Net P/N 22361-51 or Boeing Net 10-60934-1 in combination with 125" x 88" pallets Brownline P/N 23223-51 or Phenrock P/N 22861-51 or Bruggermann & Brand P/N 2102. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-338C; T.C. 4A26	SA1230CE-D	Passenger cabin contemporary interior installation. Issued 2/1/77.	CE	16878	The Boeing Company 3802 South Oliver Wichita, KS 67210
707-338C; T.C. 4A26	SA2352WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargo pallet assembly P/N 24076-51. Issued 6/14/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-345C; T.C. 4A26	SA675EA	Installation of L. Marino cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-345C; T.C. 4A26	SA725EA	Pallet P/N LM1600 (1.5G Fwd). Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-347, 720-047B; T.C. 4A26, 4A28	SA2557WE	Replacement of existing girt on Air Cruiser evacuation slide P/Ns 15D22093-7, 15D22093-11, 15D22094-10 and 15D22454-2 with Sargent Industries/PICO Division girt P/N 6176105-103. Issued 6/30/72.	WE	70130	Sargent Industries Pico Division 2045 Evans Avenue San Francisco, CA 94124
707-347C; T.C. 4A26	SA979CE-D	Passenger interior arrangement modified to 5 pallet cargo/passenger configuration, per Boeing Dwg. 65-88752 & 65-88753, cargo conversion capability, Class "B" compartment with passengers, Class "E" compartment with no passengers. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-347C; T.C. 4A26	SA2975WE	Installation of shroud assembly, P/N 0350740068, in Universal Oil Products galley P/N 10870, to Weber Aircraft Company beverage cart, P/N 818620-411. Issued 1/6/75.	WE	48550	H. Koch & Sons 5410 E. LaPalma Anaheim, CA 92807
707-347C; T.C. 4A26	SA3601WE	Installation of a single Collins INS 61B inertial navigation system. Issued 3/10/78.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C; T.C. 4A26	SA3792WE	Installation of Litton LTN-211 omega navigation system. Amended 8/31/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C, -351C, 720-047B; T.C. 4A26, 4A28	SA808EA	Installation of inflight motion picture system. Amended 3/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-349C; T.C. 4A26	SA1596WE	Installation of Brownline Pallet 23997-51 and Net 22758-51 combination. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-349C; T.C. 4A26	SA1624WE	Installation of Decca Omni trac, Decca Doppler and Decca Loran. Amended 5/10/68.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
707-349C; T.C. 4A26	SA1650WE	Modification of co-pilot's C-11 compass system to a C-11B system by addition of remote compensator.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
707-351B/C; T.C. 4A26	SA87GL	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
707-351B; T.C. 4A26	SA1168EA	Installation of dual solar T-62T-40C2 gas turbine auxiliary power units, for ground use only. Amended 11/8/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
707-351C, 727-51C, -25C; T.C. 4A26, A3WE	SA1888WE	Installation of pallet assembly AC-10359-1 used in conjunction with net assembly AC-10373-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-351C; T.C. 4A26	SA2526WE	Installation of Satco Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with assemblies conforming to NAS 3610-1A2N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-351C; T.C. 4A26	SA2528WE	Installation of Satco, Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with net assemblies conforming to NAS 3610-1A3N, 2A1N, 2A2N, 2A3N, 2A5N, and 2A6N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
707-351C; T.C. 4A26	SA2773WE	Installation of Tridair Industries 3G net assembly. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
707-351C, -384C; T.C. 4A26	SA855CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-353B; T.C. 4A26	SA83NW	Relocation of autopilot accelerometer and rate gyros. Issued 1/16/74.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
707-353B; T.C. 4A26	SA1596SW	Steel duct installation for APU according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
707-353B; T.C. 4A26	SA1927WE	Installation of dual Litton inertial navigation systems.	WE	51500	Litton Systems, Inc. 5500 Canoga Park Woodland Hills, CA 91364
707-355C; T.C. 4A26	ST654SO	Installation of liquor service galley.	SO	05356	Aircraft Interior FAbricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
707-359B; T.C. 4A26	SA2863WE	Passenger audio entertainment system installation. Issued 3/29/74.	WE	33223	Electronic Engineering Company of California 1441 E. Chestnut Avenue Santa Ana, CA 92701
707-365C, -372C, 727-172C; T.C. 4A26, A3WE	SA1795WE	Installation of Heath Tecna AC-015201 structural container. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
707-369C; T.C. 4A26	SA1234CE-D	Passenger cabin contemporary interior installation. Issued 1/24/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-372C and 707-365C; T.C. 4A26	SA1674WE	Installation of Heath Tecna Corporation AC-10160 pallet with AC-10069 net. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastic Division 19819 - 84th Avenue South Kent, WA 98031
707-373C; T.C. 4A26	SA426CE	Modify SCAT system circuit. Amended 9/9/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-373C; T.C. 4A26	SA714CE	Installation of dual Bendix ALA-51 radio altimeter provisions and equipment.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-373C; T.C. 4A26	SA2843WE	Modification by installation of horse stalls P/N 690069 on NAS 3610-2A4P pallet. Issued 3/15/74.	WE	87900	W.W. Industries, Inc. 12450 Inglewood Avenue Hawthorne, CA 90250
707-384B; T.C. 4A26	SA853CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-384B, 707-384C; T.C. 4A26	SA576CE	Installation of multi-channel audio entertainment system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-384B, 707-384C; T.C. 4A26	SA546CE	Installation of doppler autopilot tie-in Bendix DRA-12 doppler radar with CPA-24 computer to Bendix PB-20 autopilot. Amended 12/27/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-386C; T.C. 4A26	SA2808WE	Installation of dual Litton LTN-72 inertial navigation system. Issued 2/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Road Woodland Hills, CA 91364
707-387B; T.C. 4A26	SA1232CE-D	Installation of large cargo door in left hand side of forward fuselage. Issued 6/10/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-387B; T.C. 4A26	SA1233CE-D	Increase maximum zero fuel weight to 96,162 KG Issued 8/31/77.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-387B; T.C. 4A26	SA1236CE-D	Installation of auxiliary power unit. Issued 9/26/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-399C; T.C. 4A26	SA850CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aereos Portugeses. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-400, 720 Series; T.C. 4A26, 4A28	ST912SO	Installation of cargo barrier net. Amended 9/13/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
720 Series; T.C. 4A28	SA88NW	Optional interior seating arrangement. Issued 1/14/74.	NW	10174	American Aviation Services 777 Perimeter Road Boeing Field Seattle, WA 98108
720 Series; T.C. 4A28	SA95CE	Crimsco 600301 jet cargo containers in forward cabin.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
720 Series; T.C. 4A28	SA148SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA180NW	Installation for 149 passenger configuration. Issued 5/7/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720 Series; T.C. 4A28	SA182SO	Interior modifications.	SO	31429	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA302EA	Inflight motion picture system. Amended 6/9/67.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA369EA	Litton low range altimeter system.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430
720 Series; T.C. 4A28	SA371CE	Wheel 152051-4 and brake assembly 260997-1.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46620
720 Series; T.C. 4A28	SA380EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430
720 Series; T.C. 4A28	SA458WE	Crimsco jet cargo container 04-005--01, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA460CE	Wheel assembly 152051-5 and brake assembly 2600997-3.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46600
720 Series; T.C. 4A28	SA468EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
720 Series; T.C. 4A28	SA773WE	Closed circuit television entertainment system.	WE	25970	Continental Air Lines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
720 Series; T.C. 4A28	ST806SO	Installation of a cargo floor, smoke detector system and cargo restraint bulkhead. Amended 12/12/78.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
720 Series; T.C. 4A28	SA848CE-D	Additional overwing escape hatch installation interior configuration 2nd additional overwing escape hatch installation. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
720 Series; T.C. 4A28	SA1222WE	Boeing improved type engine thrust reverser forward pressure seal.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128
720 Series; T.C. 4A28	SA1245WE	Either single or dual Collins AL-101 radio altimeter system.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
720, 720B; T.C. 4A28	SA177NW	Installation of container rack and six accompanying containers on forward right-hand coat closet. Reissued 5/29/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720, 720B; T.C. 4A28	ST564SO	Installation of HF antenna and associated hardware and structural provisions for mounting HF tuning unit. Issued 11/19/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
720, 720B; T.C. 4A28	ST662SO	Installation of nose cap "C/X" band weather radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
720, 720B; T.C. 4A28	ST931SO	Addition of smoke detector system for conversion to cargo carrier. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	ST932SO	Mechanical landing gear position indicator. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	SA3332WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
720B; T.C. 4A28	SA328NW	Installation of Fairchild weight and balance system (STAN). Issued 7/28/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
720B; T.C. 4A28	SA2806SW	Stewart-Davis, Inc. auxiliary power unit. Issued 6/30/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
720-22; T.C. 4A28	SA112NW	Installation of cabin interior arrangement. Issued 5/16/74.	NW	08480	Alaska Airlines, Inc. Seattle/Tacoma Int'l Airport Seattle, WA 98155
720-22; T.C. 4A28	SA278EA	See Document No. Report No. 3187, dated 4/18/67, Rev. 1/30/69, concerning Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
720-022; T.C. 4A28	SA1553WE	Installation of Fairchild P/N 13920-301 or 15630-601 Flight Data Recorder and Honeywell P/N 180 VI Central Data Computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2095WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2206WE	Installation of Bendix third attitude indicator. Issued 7/20/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720-022; T.C. 4A28	SA2744WE-D	Alternate 143 passenger seating configuration. Issued 3/28/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2746WE-D	Alternate 149 passenger seating configuration. Issued 5/3/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2834WE-D	Alternate 101 passenger seating configuration. Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2831WE-D	Couple EDC Loran system to ADF sense antenna instead of fin cap (no fin cap on UAL B720). Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2833WE-D	Installation of two HF communications systems. Issued 3/27/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022, -023, -025, -027, -048, -062, 720B-023B, -024B, -030B, -040B, -047B, -051B, -058B, -059B, -060B, -068B; T.C. 4A28	SA460CE	Replace main wheel and brake assemblies with Bendix wheel assembly P/N 152051-5 or P/N 152051-4 and Bendix brake assembly P/N 2600997-3. Reissued 5/1/79.	GL	15500	The Bendix Corporation Aircraft Brake & Strut Division 3520 West Westmoor Street P.O. Box 10 South Bend, IN 46624

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
720-022 and 727-22; T.C. 4A28 and A3WE	SA1396WE	Installation of McMillan Radome P/N 2406 as a replacement for Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720B-023; T.C. 4A28	SA412EA-D	Relocate the L.A.S.I. flight data recorder to the aft fuselage area at Station 1452 utilizing remote vertical accelerometer in left wheel well. Install new auxiliary pitot tube and static ports for the flight recorder.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
720-023B; T.C. 4A28	SA985CE-D	Side cargo door and interior installation. Issued 3/17/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-023B, -030B; T.C. 4A28	ST657SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in forward passenger compartment.	SO	67030	Mace Unit of REF Dynamics, UCP 4856 Victor Street Jacksonville, FL 32207
720-023B, -030B, 720-047B; T.C. 4A28	SA851CE-D	Increase maximum ramp weight to 235,000 lbs. and zero fuel weight to 156,000 lbs. Amended 11/21/78.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-024B; T.C. 4A28	SA1617WE	Rewiring of galley electrical power supply.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA1767WE	Installation of Galley Models CAG-10, -20, 30 and -40 manufactured by Dale Engineering & Development, Inc. Amended 10/10/68.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA2599WE	Installation of Bell & Howell movie system. Issued 9/29/72.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-025; T.C. 4A28	SA251GL	Installation of Canadian Marconi Model CMA-740 Omega/VLF navigation system. Amended 12/29/78.	GL	10340	American Trans-Air 2600 South High School Road Indianapolis, IN 46241
720-025; T.C. 4A28	ST668SO	Installation of International Inflatables Co. door-mounted inflatable evacuation slide, P/N 68040, and International Inflatables Co. door-mounted slide container, P/N 00800.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
720-027; T.C. 4A28	SA82NW	Installation of navigator's station. Issued 12/11/73.	NW	10174	American Aviation Services, Inc. 7777 Perimeter Road Boeing Field Seattle, WA 98108
720-047B; T.C. 4A28	SA194NW	Installation of new look interior arrangement. Issued 6/30/75.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
720-051B; T.C. 4A28	SA801CE	Install Mark II (Hytrol) anti-skid system. Issued December 1971.	CE	16878	The Boeing Company Wichita Division 3801 S. Oliver Wichita, KS 67210
727 Series; T.C. A3WE	SA103SO	Collins 54W-1 comparator warning system. Amended 8/10/66.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA121GL	Installation of bleed-air valve actuator, P/N G66, to replace Boeing P/N 10-60817, in various locations in anti-ice system. Issued 11/3/76.	GL	60350	MPC Products Corporation 4200 West Victoria Avenue Chicago, IL 60646
727 Series; T.C. A3WE	SA140SO	Manufacture and install coatroom and magazine rack.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33148
727 Series; T.C. A3WE	SA159SO	Aircraft integrated data systems (AIDS).	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA161SO	Dual radio altimeter system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727 Series; T.C. A3WE	SA183SO	Crimsco cargo containers 6003 in main cabin. Amended 12/15/66.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
727 Series; T.C. A3WE	SA339CE	Fairchild cockpit voice recorder system. Amended 3/15/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA354CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA372CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA425EA-D	Install standby horizon system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA427CE	Flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64108
727 Series; T.C. A3WE	SA438CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA447EA	Vector analog computer system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727 Series; T.C. A3WE	SA469EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA490NW	Installation of PRIMUS-90 weather radar with standard black and white and also with color display.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188
727 Series; T.C. A3WE	SA535EA	Fabrication and installation of Marino Flex-Net P/N LM365. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA604SO	Dual Collins FD-109 integrated flight system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA625SO	Installation of main landing gear wheel assembly, P/N 3-1287 and brake assembly P/N 2-1147 or 2-1147-1, 2-1190.	GL	38504	B.F. Goodrich Engineered Systems Company Box 340 Troy, OH 45373
727 Series; T.C. A3WE	ST664SO	Modify door-mounted evacuation slide container, Boeing P/N 65-26998-1, from a two-point closure to a positive single-point closure. Amended 3/30/70.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
727 Series; T.C. A3WE	SA699WE	Crimsco jet cargo container 04-005-01-1, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60660
727 Series; T.C. A3WE	SA1093WE	Power source for Captain's CDI select relay switch relocated.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1105WE	Dual Collins AL-101 radio altimeter systems.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727; T.C. A3WE	SA1128EA	Installation of coat closet. Amended 9/11/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
727 Series; T.C. A3WE	SA1154WE	Cockpit voice recorder.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1265WE	Brownline pallet 23118 or Douglas pallet 5776662-505 with Brownline net 23143.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727 Series; T.C. A3WE	SA1322WE	Engine mounted fire detector unit modified to provide continuous support. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety System Division 1440 Fourth Street Berkeley, CA 94710

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727 Series; T.C. A3WE	SA1367WE	Use of Brownline Corp. Pallet Nos. 23640-51 and 23224-51 in place of Douglas Aircraft Co. Pallet No. 577662-505.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1451WE	Installation of constant speed drive, load controller, generator and voltage regulator.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1509WE	Revised interior arrangement.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727 Series; T.C. A3WE	SA1563WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1868SW	Portable solid oxygen system for first-aid use. Issued 4/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
727 Series; T.C. A3WE	SA2422WE	Installation of Valley Todeco bolt VAL 22016 to replace Boeing bolt BAC B30EK8-48 on 727 thrust reverser. Issued 9/23/71.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727, 727C; T.C. 2H3	SA800CE	Installation of three cell forward and three cell aft auxiliary fuel tanks in lower cargo compartment. Issued June 1972.	CE	16878	The Boeing Company 3801 South Oliver Street Wichita, KS 67210
727, 727-100, -22; T.C. A3WE	SA2563WE	Installation of garment bag module. Issued 8/23/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	SA169GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	GL	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	ST65030	Installation of dual band (C/X) type weather radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
727, 727C, 727-200 Series; T.C. A3WE	SA1239CE-D	Grimes coffee maker and warmer unit installation. Issued 11/20/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727, 727-100, 727C, 727-200; T.C. A3WE	SA2668WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-50 autopilot as replacement for Sperry or Smiths rate gyros. Amended 6/20/73.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3130WE	Installation of dual Litton LTN-72 or a single or dual LTN-72R INS/RNAV navigation system. Amended 5/18/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3145WE	Installation of Sperry Model Block V SP-50 autopilot and Honeywell Air Data computer. Issued 3/12/76.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3153WE	Installation of forward coat closet on left hand side just aft of forward entry door. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3154WE	Installation of interior configuration consisting of 10 first class and 98 coach seats. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3654WE	Installation of interior configuration with 10 first class and 95 coach seats. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series T.C. A3WE	SA3665WE	Installation of a dual Collins 61E inertial navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3679WE	Installation of a Global GNS-500A VLF/Omega navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727, 727C, 727-100, 727-100C, 727-200; T.C. A3WE	SA3717WE	Installation of a cabin divider. Issued 8/29/78.	WE	25970	Continental Air Lines International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3755WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-211 omega navigation system and a true airspeed system. Amended 3/23/79.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3964WE	Installation of dual Litton LTN-211 omega navigation systems. Issued 5/23/79.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, -100C Series; 727-223, -225, -227, -228, -231, -235, -251, -264, -284, -295; T.C. A3WE	SA3220WE	Addition of filter to the cabin pressure limit control feature of P/N 103280 outflow valve. Issued 6/24/76.	WE	07505	AiResearch Manufacturing Company Garrett Corporation 2525 West 190th Street Torrance, CA 90509
727, 727C, 727-200, 737; T.C. A3WE	SA2348WE	Modify Boeing 727 Series airplanes by installation of emblem lights. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
727, 727C, 727-200, 737; T.C. A3WE	SA3292WE	Installation of thrust reverser short track. Issued 11/23/76.	WE	78475	Thrustair, Inc. 12990 Branford Avenue Arleta, CA 91331
727, 727C, 727-200, 737; T.C. A3WE	SA3306WE	Installation of thrust reverser cascades. Issued 12/3/76.	WE	41015	Hasko-Air, Inc. 9042 Owensmouth Avenue Canoga Park, CA 91304
727, 727-100, 727C, 727-100C, 727-200 Series; T.C. A3WE	SA3521WE	Installation of a cabin divider. Issued 11/8/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-200; T.C. A3WE	ST4368O	Installation of thrust reverser deflector door drive. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727, 727C, 727-200; T.C. A3WE	ST4508O	Modification of thrust reverser forward deflector door link. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727-1H2; T.C. A3WE	SA2480WE	Addition of INS attitude reference data to flight instruments. Issued 2/15/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-1H2; T.C. A3WE	SA2552WE	Install Litton P/N 451158 automatic data entry unit. Issued 8/17/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-2B7; T.C. A3WE	SA2168WE	Installation of Henry Engineering lounge tables No. 17701 and No. A17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727-2B7; T.C. A3WE	SA2170WE	Installation of class divider. Issued 5/27/70.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-2J0; T.C. A3WE	SA1235CE-D	Forward auxiliary fuel tank removal and reinstallation. Issued 10/9/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-2M7; T.C. A3WE	SA3505WE	Installation of ground proximity warning system. Issued 10/27/77.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3564WE	Installation of auxiliary fuel tanks in the forward and aft belly cargo/baggage compartments. Issued 1/20/78.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3380WE	Installation of dual LTN-51, or dual LTN-72, or dual LTN-72R, or one LTN-51 and either one LTN-72 or one LTN-72R inertial navigation system. Amended 4/29/80.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3967WE	Installation of coat room assembly No. PW2527036. Issued 5/29/79.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-2L4; T.C. A3WE	SA3065WE	Installation of 3400 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 7/16/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-14; T.C. A3WE	SA1942WE	Revised interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14; T.C. A3WE	SA1986WE	Interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -35, -193, -214, -235; T.C. A3WE	SA1885WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727-14, -51; T.C. A3WE	SA1717WE	Revised interior arrangement. Amended 4/20/77.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
727-14, -51, -214, -254, -2J7, -2Q8; T.C. A3WE	SA3013WE	Installation of ground proximity warning system. Amended 12/19/78.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -51, -214, -254, -2Q8; T.C. A3WE	SA3939WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/11/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-17; T.C. A3WE	SA3674WE	Installation of 2700 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 6/30/78.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-17, -31, -31C, -180C, -231, -231A; T.C. A3WE	SA1488CE	Installation of a pitot heater failure indication system. Issued 5/4/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-21; T.C. A3WE	SA264NW	Interior arrangement. Issued 2/20/76.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188
727-21; T.C. A3WE	SA1078EA-D	Installation of two closets in rear of cabin to accommodate a bar or food cart and provisions for parking the carts in flight at two locations. Amended 11/8/79.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
727-21, 21C; T.C. A3WE	SA612SO-D	Installation of portable berth (aerotherm stretcher). Reissued 9/6/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727-21, -22, -81; T.C. A3WE	SA2660WE	Modification of cabin interior. Amended 12/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-21, -81; T.C. A3WE	SA3022WE-D	Installation of new seating arrangement. Amended 11/10/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-21C; T.C. A3WE	SA1292WE	Installation of Boeing palletized cargo system 65-49102 with Brownline pallet 22630-51 or 26100-52 Brownline net assembly 23225-51, 23226-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-21C; T.C. A3WE	SA1594WE	Installation of Heath Tecna Corp. pallet AC-10065 and Brownline Corp. net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-21C; T.C. A3WE	SA3006WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-21C; T.C. A3WE	SA3672WE	Installation of Brownline quick change pallets, P/N's 45881-101, 45882-101 and 46129-101. Issued 6/19/78.	WE	17740	Brooks & Perkins Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-21C, -22C, -25C, -27C, -30C, -31C; T.C. A3WE	SA696CE	Installation Aeroquip Corp. cargo tie-down net.	GL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-22; T.C. A3WE	SA1788WE	Interior arrangement installation.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94125
727-22; T.C. A3WE	SA3323WE	Installation of forward facing flight attendant seat on forward galley. Issued 1/20/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-22; T.C. A3WE	SA3364WE-D	Revise cabin seating to accommodate 118 all-coach configuration. Issued 4/25/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C; T.C. A3WE	SA3023WE-D	Revise seating arrangement from 18 first class/78 coach to 12 first class/86 coach configuration and further revised to 10 first class/ 86 coach configuration. Amended 6/11/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-22, 727-22QC; T.C. A3WE	SA1687WE	Modify existing Collins Radio Company type FD-109 Flight Director installation to add "Steering", "Airspeed-Hold", and "Auto Approach" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3079WE	Installations of Collins FPC-75-P/N 622-2615-012 or P/N 622-2615-212, or P/N 622-2615-013, ground proximity warning system computer in airplanes. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3350WE-D	Air data system. Amended 7/20/79.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-22, -24C, -30, -76, -92C; T.C. A3WE	SA3655WE	Installation of Nordskog Company auxiliary galley Model 1-420. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727-22, -30, -76, 92C; T.C. A3WE	SA981CE-D	Reconfiguration of flight crew instrument panels, avionics and passenger cabin. Amended 8/28/78.	CE	16877	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-22C; T.C. A3WE	SA645CE	Make and install pallets in accordance with Brooks & Perkins Drawing Index No. 16987DL-E and Installation Instructions No. BPS 149. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA814CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA842CE	Installation of cargo pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA1622WE	Modification of type design to permit installation of Heath Tecna Corp. AC-10061 pallet with AC-10069 net.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-22C; T.C. A3WE	SA1816WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/8/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-22C; T.C. A3WE	SA1962WE	Modify by installation of pallet assemblies 40160101 thru 40160108 used in conjunction with net assemblies 22672-51, -52; 23143-51, 22758-51, -52; 22273-51, 7776967-1 (Douglas) and 3950020 (Aeroquip). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1, or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247

Aircraft Make, Model & T.C. No.	STC No.	Description	FG	STC Code	STC Holder
727-22C; T.C. A3WE	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517, with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks & Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2255WE	Installation of Satco, Inc., pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-22C; T.C. A3WE	SA2274WE	Installation of Irvin 88" x 125" cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
727-22C; T.C. A3WE	SA2844WE	Installation of coat and luggage stowage unit. Issued 2/25/74.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-22C; T.C. A3WE	SA3359WE-D	Retrofit of Kollsman P/N A41869-10-021 altimeters on the captain's and first officer's instrument panel. Issued 1/11/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3577WE-D	Installs overhead stowage bin kit. Issued 8/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3673WE	Installation of cargo restraint system which meets the requirements of a NAS 3610 class IIA restraint system. Issued 6/21/78.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
727-22C; T.C. A3WE	SA3775WE	Installation of the Brownline 46000-101 cargo system. Issued 10/31/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-22C, -24C, -25C, -116C; T.C. A3WE	SA4098WE	Installation of cargo system, P/N 47270-101. Issued 3/10/80.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-022; T.C. A3WE	SA2838WE-D	Installs barrier and tie-down fitting for using preloaded liquor service cart on-board aircraft. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-022; T.C. A3WE	SA3575WE-D	Remove all first class seats, the class divider, the carry-on baggage and garment bag modules and replace with all coach seats to increase seating capacity to 112 passengers. Issued 4/24/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-022;	SA3363WE-D	Installation of dual Collins FD-109A flight director systems. Issued 4/24/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-022, -022C, -222; T.C. A3WE	SA2201WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727-22, -222, -22QC; T.C. A3WE	SA2096WE	Installation of McMilian Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-23; T.C. A3WE	SA411EA-D	Relocate the flight data recorder Station 1120 on cabin floor, left hand side, aft of last row of seats to provide improved crash survivability. Amended 12/8/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23; T.C. A3WE	SA563EA	Installation of digital adaptive recording system (DARS) on one Boeing 727-23. Issued 4/7/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA501EA-D	Delete auxiliary vertical gyro on 727-23 and 727-123 and authorize use of either Sperry or Bendix gyros on 727-35 and 727-95. Amended 9/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA515EA-D	Install REF Dynamics beverage bar. Amended 2/16/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA523EA-D	Install overwing emergency lights. Amended 1/12/69.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA524EA-D	Change interior passenger seating arrangement.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA558EA-D	Modification of leading edge slat and flap position indication system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95 and 727-123; T.C. A3WE	SA866WE	Installation of ILS Back Course and Compass Switches. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA872WE	Installation of Collins P/N 54W-1 instrument comparator. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1195WE	Installation of dual Collins FS-108 flight director systems. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1575WE	Installation of dual Collins AL-101 radio altimeter system. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-95, 727-123; T.C. A3WE	SA804WE	Installation of Honeywell HG180 Modular Air Data Computer System. Amended 6/26/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -223; T.C. A3WE	SA552EA-D	Installation of autopilot go-around unit. Issued 4/24/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-24C, 727-116C; T.C. A3WE	SA1441CE-D	Change crew instrument panels and systems revisions. Reissued 9/19/79.	CE	16877	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-24C; T.C. A3WE	SA1661WE	Installation of Bendix Dual DRA 12 Doppler System.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2886WE	Interior arrangement. Issued 5/18/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2899WE	Installation of courier seat. Issued 6/15/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2942WE	Installation of Nordskog Galleys 1-289A and 1-290A. Amended 11/14/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, -92C; T.C. A3WE	SA3855WE	Installation of Brownline cargo/seat pallet system 45980, configuration -101. Issued 2/12/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
727-25; T.C. A3WE	ST588SO	Installation of 119 passenger interior and installation of two EAL 52-RA-7 four man life rafts. Issued 4/30/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST663SO	Installation of LORAN A navigation system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST740SO	Cabin interior arrangement and furnishings changes. Issued 6/3/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-25, 25C; T.C. A3WE	ST426SO	Installation of Honeywell HG180V3 air data computer with electronic altimeters, altitude reporting digitizer and altitude alerting system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST741SO	Cabin interior configuration changes. Amended 1/24/75.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST751SO	Modification of main cabin passenger interior configuration from 14 first class and 89 tourist class to 12 first class and 95 tourist class accommodations. Issued 5/28/76.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, -25C; T.C. A3WE	ST954SO	Installation of Mansfield Aircraft Products model 1470 galley/coatroom. Issued 8/29/77.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C, -225; T.C. A3WE	ST510SO	Installation of dual HF communications system using vertical fin leading edge slotted antenna. Amended 1/13/78.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	ST534SO	Interior - two pallet cargo/65 passenger MAC configuration installed. Issued 4/13/73.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	SA2364WE	Installation of Satco, Inc. cargo pallet assembly P/N 31095-501, -503, -505, -507 in conjunction with net assemblies NAS 3610-2A1N, -2A2N, -2A3N, -2A5N, and -2A6N. Amended 5/18/72.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-30; T.C. A3WE	SA982CE-D	Interior arrangement installation. Amended June 1976.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-30; T.C. A3WE	SA3157WE	Installation of 1200 gallon auxiliary fuel tank in forward cargo compartment. Issued 3/26/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-30 T.C. A3WE	SA3319WE	Installation of auxiliary fuselage fuel tanks (1600 gallons) in forward and aft cargo compartment. Issued 12/28/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91406
727-30, -81; T.C. A3WE	SA2734WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 2/13/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-030, -224; T.C. A3WE	SA3408WE	Installation of Lermer Apparatebau GMBH beverage cart No. L15701. Issued 5/26/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 91406
727-31; T.C. A3WE	SA478CE	Modification to flap quadrant.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31; T.C. A3WE	SA570CE	Install Models 14801 or 14802 Henry Engineering Company bar unit. Amended 10/18/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C; T.C. A3WE	SA373CE	Installation of a single SCAT system. Amended 8/12/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C; T.C. A3WE	SA604CE	Installation of dual radio altimeter provision - single equipment driving dual indicators. Amended 2/3/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C, -100C; T.C. A3WE	SA235CE	Installation of Kollsman Integrated Flight Instrument System (KIFIS). Amended 5/8/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C, -100C; T.C. A3WE	SA734CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, -31C, -100C; T.C. A3WE	SA779CE	Installation of Bendix gyro horizon and inverter. Issued June 1971.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA553CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA828CE	Install Butler National Corp. flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA1137CE	Installation of hydraulic interconnect override system. Issued June 1975.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180C, 727-231; T.C. A3WE	SA1542CE	Installation of a Growth Industries dual cavity oven. Issued 12/12/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-31, -31C, -231; T.C. A3WE	SA490CE	Installation of Safe Flight Corp. auto power servo kits. Amended 10/9/74.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31C, -180C; T.C. A3WE	SA741CE	Install Henry Engineering auxiliary bar model 15501A and one additional triple passenger seat.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-35; T.C. A3WE	SA639SO	Installation of hatrack assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA640SO	Installation of liquor service galley assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA1566WE	Installation of Sperry SP-50 Mod Block IV Single Channel Autopilot. Amended 5/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-35, 727-95, 727-123; T.C. A3WE	SA1576WE	Replacement of Captain's altimeter and First Officer's altimeter and and installation of third altimeter. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-35, -235; T.C. A3WE	ST738SO	Installation of Gulton Model EMBS 144 nickel-cadmium electrical storage battery and integral automatic control system. Issued 1/23/74.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami International Airport Jamaica, NY 11430
727-46; T.C. A3WE	SA847CE-D	Structural and system modification for installation of service door and retractable step. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-46; T.C. A3WE	SA2970WE	Installation of 300 gallon auxiliary fuel tank in aft cargo compartment. Issued 12/20/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-51, -51C, -151C, -251; T.C. A3WE	SA89GL	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
727-75, -232, -295; T.C. A3WE	ST855SO	Installation of Bendix ground proximity warning system. Issued 10/16/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-77; T.C. A3WE	SA3559WE	Installation of a 1932-gallon auxiliary fuel tank system in forward and aft cargo compartments. Issued 2/6/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-81; T.C. A3WE	SA2724WE	Installation of executive cabin interior. Amended 9/20/74.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727-81, -100; T.C. A3WE	SA263NW	Garment bag module modification. Issued 2/25/76.	NW	47722	Kelley-Morrow Enterprises The Common Building 1200 - 112th N.E. Bellevue, WA 98004
727-81, -100; T.C. A3WE	SA2732WE	Installation of duel LTN-104 navigation systems. Amended 3/13/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-90, -90C; T.C. A3WE	SA2245WE	Interior arrangements. Issued 9/18/70.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98158

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-90C; T.C. A3WE	SA139NW	Installation of quick change interior arrangement. Amended 4/21/75.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98108
727-90C; T.C. A3WE	SA327NW	Interior arrangements 98 PAX and two cargo pallet/63. Issued 7/23/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA129NW	Installation of cabin interior arrangement. Issued 9/23/74.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA310NW	Interior arrangement. Issued 5/28/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, 737-202C, -210C; T.C. A3WE, A16WE	SA1823WE	Installation of "Heathair" AC-10360 cargo pallet assembly and AC-10374 cargo net assembly. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-92C; T.C. A3WE	SA1839WE	Stewardess seat installed on Nordskog 769 galley.	WE	61605	Nordskog Co., Inc. 16000 Strathern Street Van Nuys, CA 91406
727-95; T.C. A3WE	SA704EA	Installation of Henry Engineering Company Galleys Models Nos. 14001 and 14002. Reissued 12/8/72.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-100 Series Models type certificated as of 6/17/68; T.C. A3WE	SA587CE	Installation of Hoskins Twilighter Mark V high intensity light system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
727-100; T.C. A3WE	SA612NW	Installation of coat closet. Issued 5/26/78.	NW	48532	KME Manufacturing, Inc. The Commons Building 1200 112th Street, N.E. Renton, WA 98055
727-100; T.C. A3WE	SA643NW	Installation of six carry-on baggage modules. Issued 9/13/78.	NW	78672	Tramco, Inc. 1033 Thomas Avenue, S.W. Renton, WA 98055
727-100; T.C. A3WE	SA697NW	Install life raft stowage compartments. Issued 12/14/78.	NW	41625	Heath Tecna 19819 84th Avenue South Kent, WA 98031
727-100; T.C. A3WE	SA1130SO	Installation of an aft galley storage module. Issued 1/22/80.	SO	64500	Piedmont Airlines Smith-Reynolds Airport Winston-Salem, NC 27102
727-100; T.C. A3WE	SA2498SW	Collins FPC-75 ground proximity warning system. Issued 1/23/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
727-100 Series; T.C. A3WE	SA3501WE	Installation of Litton LTN-201 omega navigation system. Amended 12/29/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100 Series; T.C. A3WE	SA3810WE	Installation of a maximum of eight auxiliary fuel tanks in forward and aft cargo compartments. Amended 1/4/80.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-100 Series; T.C. A3WZ	SA3851WE	Installation of Litton LTN-211 Omega Navigation System. Amended 4/19/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
707-100, -100B, -200; T.C. 4A21	ST660SO	Installation of "C/X" band nose radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
727-100, -100C Series; T.C. A3WE	SA3661WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-201 Omega navigation system and a true airspeed system. Issued 10/11/78.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
727-100, -200; T.C. A3WE	SA1050CE	Install Crimsco cargo container, P/N 600301. Issued November 1974.	CE	27000	Crimsco, Inc. 5001 E. 59th Street Kansas City, MO 64130
727-100, -200; T.C. A3WE	SA2240WE	Installation of door-mounted emergency light. Amended 9/23/70.	WE	44266	International Inflatables Company Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-100, -200; T.C. A3WE	SA3333WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
727-100, -200; T.C. A3WE	SA3374WE	Installation of bearing P/N VTB02220 as replacement for Boeing P/N 10-60545-113S in main landing gear lock system assembly. Issued 3/29/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200; T.C. A3WE	SA3379WE	Installation of bearing, P/N VTB02800 in lieu of Boeing bearing P/N 10-60545-143. Issued 4/20/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200 Series; T.C. A3WE	SA3508WE	Installation of Valley-Todeco bearings, P/Ns VTB-02900, VTB-02910, VTB-02920, VTB-02930. Issued 11/8/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, 727-200; T.C. A3WE	SA3716WE	Installation of a Dretloh Model 5002, P/N 121214-1 food carrier. Issued 8/25/78.	WE	30702	Dretloh Aircraft Supply, Inc. 980 North Lemon Orange, CA 92667
727-100, -200; T.C. A3WE	SA4133WE	Installation of an ARINC communications addressing and reporting system (ACARS). Issued 4/24/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100, 100QC; 737; T.C. A3WE, A16WE	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
727-171C, 727-173C; T.C. A3WE	SA1693WE	Revised interior arrangement with Nordskog hostess seat 6734 and door 61246 and associated modifications added to Mapco Galley Model 680T-1.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-172C; T.C. A3WE	SA671EA	Installation of pallet net for use with Boeing pallets.	SC	44750	Irvin Industries, Inc. 1315 Versailles Road Lexington, KY 40501
727-172C; T.C. A3WE	SA849CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aeros Portugeses requirements. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-172C; T.C. A3WE	SA1662WE	Installation of Heath Tecna Corp. AC-10160 pallet with AC-10069 net on Boeing 707-172C. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-173C; T.C. A3WE	SA1907WE	Interior arrangement reflecting 122 passenger quick change conversion configuration. Amended 6/3/69.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
727-173C; T.C. A3WE	SA2385WE	Installation of interior arrangement. Amended 9/14/71.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
727-180C; T.C. A3WE	SA558CE	Installation of Kollsman integrated flight instrument system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-180C; T.C. A3WE	SA559CE	Installation of a single SCAT system. Amended 8/11/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-180C; T.C. A3WE	SA560CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-200; T.C. A3WE	SA349NW	Installation of wind screen in forward cabin RH side. Issued 8/27/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 832 Issaquah, WA 98027
727-200; T.C. A3WE	SA359NW	Installation of carry-on baggage unit. Issued 9/28/76.	NW	48532	KME Manufacturing, Inc. 1200 - 112th N.E. Bellevue, WA 98004
727-200; T.C. A3WE	SA547NW	Installation of Marx I interior kit. Issued 11/22/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue S. Kent, WA 98031
727-200; T.C. A3WE	ST742SO	Modification and installation of seat model 914-1. Issued 6/26/74.	SO	21560	Charlotte Aircraft Corporation P.O. Box 1225 Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-200; T.C. A3WE	SA774SO	Installation of the Litton LTN-211 Omega Navigation System. Issued 11/30/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airlines Miami, FL 33148
727-200; T.C. A3WE	SA816NW	An interior installation. Issued 8/8/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
727-200; T.C. A3WE	SA2335SW	Modification to increase depth of Weber 808737-618-M pilot seat and 808737-619-M copilot seat. Issued 7/23/76.	SW	14222	B & H Parts Company Meacham Field Fort Worth, TX 76106
727-200; T.C. A3WE	SA2672WE	Installation of coat and luggage stowage unit. Issued 3/23/73.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
727-200; T.C. A3WE	SA3054WE	Installation of dual Litton LTN-72 inertial navigation system. Amended 6/22/76.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-200; T.C. A3WE	SA3081WE	Replacement of evacuation slide container latches with latches of a new design. Reissued 6/2/76.	WE	70130	Sargent Industries PICO Division Kahr Bearing Division 2045 Evans Avenue San Francisco, CA 94124
727-200; T.C. A3WE	SA3594WE-D	Removal of all first class seating and class divider. Relocate cabin seating to provide 14 rows at 38-inch pitch. Installation of additional furnishings. Amended 1/7/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-200 Series; T.C. A3WE	SA3882WE	Installation of aft cargo hold trash chute container assembly, P/N E-25-0256. Amended 2/12/80.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-200, 737; T.C. A3WE, A16WE	SA764NW	Inner window pane replacement. Issued 5/3/79.	NW	79672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
727-214; T.C. A3WE	SA1922WE	Interior arrangement. Amended 6/6/69.	RM	37015	Frontier Airlines 5900 East 39th Avenue Denver, CO 80207
727-214, -254, -208; T.C. A3WE	SA3069WE	Installation of galley in forward passenger compartment. Amended 2/12/80.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3560WE	Installation of PSA galley P/N C-25-0085. Issued 1/18/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3625WE	Installation of 168 passenger interior arrangement. Issued 4/3/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3820WE	Installation of 165 passenger interior arrangement, and aft stowage closet. Issued 1/8/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor San Diego, CA 92101
727-222; T.C. A3WE	SA2448WE	Installation of McDonnell Douglas Eros II collision avoidance system. Issued 11/22/71.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2743WE-D	Installation "New Look" cabin interiors. Amended 6/10/77.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2826WE-D	Installations of provisions for ground proximity warning system. Issued 2/21/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2832WE-D	Installation of ground proximity warning system with cockpit annunciations deactivated and warning signals connected to digital recorder. Issued 3/13/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2841WE-D	Revise cabin seating configuration to accommodate 14 first class/112 coach configuration. Amended 8/20/76.	WE	80500	United Airlines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-222; T.C. A3WE	SA3037WE-D	Revise cabin seating configuration to accommodate 10 first class/118 coach configuration. Issued 2/24/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3353WE-D	This modification installs a retractable cart tie-down at the Sta. 350-50 and LBL 32.34. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3354WE-D	This modification installs modified seats in the first class compartment. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3355WE-D	Installation of carry-on baggage and garment bag modules just aft of forward entry door on left side of passenger cabin. Issued 10/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3362WE-D	Installation of a Safe Flight P/N 6500-2 windshear warning computer for in-service evaluation. Issued 3/15/78.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3578WE-D	Installation of arinc communications addressing reporting system (ACARS). Amended 2/9/79.	cWE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3589WE	Installation of passenger audio entertainment system. Issued 7/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3590WE-D	The cabin interior seating configuration will change from 10F/124Y to 14F/118Y. One row of coach seats will be removed and one row of first class seats added. The class divider will be moved accordingly. Issued 2/9/79.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3592WE-D	Replace the auxiliary galley/stowage compartment located in the RH aft passenger cabin between station 1101 and 1137 with a new stowage compartment. Amended 12/17/79.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA4063WE	Deletion of the pair of excess Type I emergency exits located at station 720 and 15. Issued 11/29/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-223; T.C. A3WE	SA521EA-D	Install single area navigation system. Amended 9/10/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74151
727-224; T.C. A3WE	SA3325WE	Installation of auxiliary bar unit No. 1-368. Issued 1/13/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-225; T.C. A3WE	ST593SO	Installation of 18 first class/116 tourist class passenger interior with modified coatroom and windscreen. Issued May 1974.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225; T.C. A3WE	ST753SO	Installation of main cabin equipment to provide accommodations for 137 passengers (12 first class and 125 tourist class). Issued 8/4/76.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225A; T.C. A3WE	SA775SO	Installation of a coatroom and class divider partition in the main cabin at B.S. 544. Issued 12/3/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-225; T.C. A3WE	SA1238CE-D	Interior conversion to 177 tourist class passengers. Issued 11/7/78.	EA	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-231; T.C. A3WE	SA561CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA562CE	Installation of single seat system. Amended June 1974.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-231; T.C. A3WE	SA639CE	Modification of SCAT/Auto Throttle to include auto-land throttle closure feature.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA721CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA1287CE	Revision of engine fire detection circuit. Issued December 1976.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA1475CE	Installation of Simmonds Precision performance advisory system (fuel management). Issued 3/6/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-237; T.C. A3WE	SA2729WE	Installation of interior arrangement. Issued 7/23/73.	WE	62160	Pacific Southwest Airlines 3220 N. Harbor Drive San Diego, CA 92101
727-247; T.C. A3WE	SA469NW	Installation of coat closet unit on Western Airlines aircraft. Issued 6/24/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
727-247; T.C. A3WE	ST549SO	Manufacture and installation of P/N 10826-1 cart stowage unit. Amended 11/18/77.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
727-247; T.C. A3WE	ST550SO	Manufacture and installation of P/N 10825 coat closet unit. This STC is limited to Boeing 727-247 aircraft with wide body interiors. Issued 9/21/73.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
727-247; T.C. A3WE	SA3495WE	Conversion of UOP galley by installation of UOP oven, Grimes coffeemaker and overboard drain system. Issued 9/30/77.	WE	8130	Aerospace Division Universal Oil Products 4856 Victor Street Jacksonville, FL 32207
727-247; T.C . A3WE	SA3644WE	Installation of IPECO pilot and co-pilot crew seats. Issued 5/16/78.	WE	54860	MARCON Associates, Inc. Agents for IPECO Europe Ltd. 18436 Hawthorne Boulevard Suite 212 Torrance, CA 90504
727-247, -2Q8; T.C. A3WE	SA29NE	Installation of Aerospace Division galleys, P/Ns 190E1000-103, 190E2000-105, -106, and -107 in Western Airlines Boeing 727-247 and -2Q8 aircraft. Amended 5/4/79.	NE	81120	Aerospace Division Universal Oil Products Route 202 Bantam, CT 06750
727-248, -2Q8; T.C. A3WE	SA3929WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/3/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
727-281;737-281; T.C. A3WE, A16WE	SA33NW	Installation of class divider in constant section at station 500 on Model 727-281 and station 525 on Model 737-281. Issued 3/14/73.	NW	83765	Vinnedge and Associates P.O. Box 374 North Bend, WA 98045
727-291 and 727-295; T.C. A3WE	SA1602WE	Revised interior arrangement with Frontier Galley Models 13301, 13302, 13303, and 13304 installed. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727, 727C, 727-200; T.C. A3WE	ST731SO	Installation of automatic in-flight lock for ventral stair-door. Amended 5/18/73.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727, 727C, 727-200; T.C. A3WE	SA2315WE	Installation of thrust reverser adjustable offset links on above aircraft equipped with Boeing Thrust Reversers, BAC P/N 65-27800-1, 65-27800-3 and 65-27800 only. Issued 2/22/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2337WE	Installation of Triumph Corporation solid offset thrust reverser links. Issued 4/9/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2391WE	Modification of nose gear steering cylinder. Issued 7/30/71.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727, 727C, 727-200; T.C. A3WE	SA2471WE	Installation of Triumph Corporation 5026 series bearings and rod ends on thrust reversers. Issued 2/1/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T.C. A3WE	SA2487WE	Installation of main landing gear lock actuator bearing assembly. Issued 3/3/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2518WE	Installation of thrust reverser forward deflector door link. Issued 5/1/72.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727, 727C, 727-200; T.C. A3WE	SA2627WE	Installation of fuel control rod end bearings. Issued 1/4/73.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T.C. A3WE	SA2779WE	Installation of auxiliary power fire detector unit. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 Fourth Street Berkeley, CA 94710
727 Series, 737 Series; T.C. A3WE, A16WE	SA1052SO	Installation of GE battery P/N 43B022RB36 in place of Marathon P/N CA-727-7, CA-727-20, or CA-27-20 batteries or SAFT P/N 23180 batteries; or installation of GE battery P/N 43B020RB10 replacing Marathon P/N CA-727-7, CA-727-20 or CA-27-20 or SAFT P/N 23186 or 23180 batteries. Amended 5/11/79.	SO	37380	General Electric Company P.O. Box 114 GAinesville, FL 32602
727 Series; 737 Series; T.C. A3WE, A16WE	SA2501WE	Installation of replacement cooling turbine nozzle assembly. Reissued 1/5/79.	WE	67145	Repair Tech International 13900 Saticoy Street Van Nuys, CA 91402
737 Series; T.C. A16WE	SA270NW	Interior arrangement. Issued 3/11/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA353NW	Installation interior components consisting of 2 wind screens and 3 decorative panels on existing galleys. Issued 9/7/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA370NW	Removal of passenger interior, installation of cargo compartment liners and cargo tie down equipment. Issued 11/8/76.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	ST854SO	Installation of Bendix GPW-83 ground proximity warning system. Amended 1/21/76.	SO	64500	Piedmont Aviation, Inc. P.O. Box 2720 Smith Reynolds Airport Winston-Salem, NC 27102
737; T.C. A16WE	SA751NW	Installation of a coat closet/ storage bin. Issued 4/12/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA781NW	Installation of a coat closet. Issued 6/7/79.	NW	48532	KAE The Commons Building 1200 112th N.E. Bellevue, WA 98055
737; T.C. A16WE	SA853NW	Installation of a coat closet. Issued 10/29/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA1401SW	Replace Marathon CA-737 battery with General Electric 43B022RB10 battery. Issued 12/9/71.	GL	37379	General Electric Company 206 W. Mitchell Avenue Cincinnati, OH 45232
737; T.C. A16WE	SA1519SW	Coat closet. Issued 10/14/72.	SW	16750	BIDCO, Inc. 2732 Ludelle Fort Worth, TX 76105
737; T.C. A16WE	SA3983WE	Installation of storage unit, P/N 10165. Issued 6/26/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
737-2A1; T.C. A16WE	ST136RM	Installation of interior arrangement. Issued 4/25/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2A6; T.C. A16WE	SA2153WE	Installation of fuselage fuel tanks in forward and aft cargo compartments.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA6RM	Interior arrangement modification. Amended 3/10/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA66RM	Revision of aft coat closet capacity from 100 lbs. to 250 lbs. Issued 2/3/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA67RM	Installation of trash module in aft coat closet. Issued 3/12/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -222, -247, -291; T.C. A16WE	SA75RM	Installation of Mapco closet module, P/N 1345, under forward left side hatrack. Issued 5/26/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -217, -291, -222; T.C. A16WE	SA101RM	Install dual SEICAL system. Amended 6/22/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-021; T.C. A16WE	SA523AL	Installation of ground proximity warning system. Reissued 6/19/75.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
737-T43A; T.C. A16WE	SA265GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500, and Harrowe barometric altitude rate computer P/N 4030-03-1. Issued 8/25/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
737-2S2C, -2Q8C; T.C. A16WE	SA4019WE	Installation of Brownline cargo pallet restraint system, P/N 46926-101, -102. Amended 11/21/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-100, -200, -200C Series; T.C. A16WE	SA2705WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-77 autopilot as a replacement for Sperry or Smiths rate gyros. Amended 7/15/74.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
737-100, 737-200; T.C. A16WE	SA2828WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-100, -200; T.C. A16WE	SA3334WE	Installation of stretcher carrier, AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
737-100/200/200C; T.C. A16WE	SA2267WE	Installation of door mounted emergency light. Issued 10/30/70.	WE	44266	International Inflatables Co. Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
737-100/200/200C; T.C. A16WE	SA2564WE	Installation of garment bag module. Amended 9/20/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
737-100, -200, -200C; T.C. A16WE	SA170GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-6, with Courter flap asumetry detector kit, P/N 298-1026-02. Reissued 12/21/78.	GL	26675	Courter, Incorporated 375 North Lake Street Boyne City, MI 49712
737-100, -200, -200C; T.C. A16WE	ST686SO	Installation of nose cap "C/X" band weather radar radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
737-100, -200, -200 Series; T.C. A16WE	SA887EA	Installation of structural provisions for tail logo lights. Amended 4/19/72.	EA	18750	Butler Aviation - Friendship, Inc. Sub. of Butler Aviation Int'l Friendship Int'l Airport Baltimore, MD 21240
737-100/200/200C; T.C. A16WE	SA2542WE	Installation of wing-tip mounted emblem lights. Amended 12/8/75.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
737-200; T.C. A16WE	SA53RM	Installation of Sundstrand Data Control ground proximity warning system and glide slope monitoring system. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-200; T.C. A16WE	SA55RM	Installation of Universal Oil Products Co. galley tray cart. Amended 8/18/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA62RM	Installation of Universal Oil Products Co. beverage cart, P/N 11143-1. Issued 8/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA103NW	Installation of modified lower interior sidewall. Issued 4/12/74.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	SA178NW	Installation of perfume dispenser into three lavatories. Issued 5/12/75.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	ST430SO	Installation of unusual events recording system.	GL	77600	Technology, Inc. 7400 Colonel Glenn Highway Dayton, OH 45431
737-200; T.C. A16WE	ST875SO	Replacement of Monogram P/N 3299-1 or Leach P/N TD1514-1002 timer assemblies with Piedmont P/N 737D-81017 solid state timer. Amended 7/13/76.	SO	64500	Piedmont Aviation, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200 Series; T.C. A16WE	ST1020SO	Installation of 112 passenger interior arrangement. Issued 8/31/78.	SO	64500	Piedmont Aviation Smith-Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	ST1034SO	Fabrication and installation of an aft right hand windscreen. Issued 11/15/78.	SO	64500	Piedmont Airlines Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1113SO	Fabrication and installation of an aft left-hand windscreen. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1114SO	Fabrication and installation of a forward coat closet. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA2747WE-D	This modification provides an all coach seating configuration for 113 passengers. Issued 5/24/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
737-200; T.C. A16WE	SA3134WE	Installation of Collins ground proximity warning system. Issued 1/7/76.	WE	04080	Air California P.O. Box 2678 Hangar #6, Oakland Int'l Airport Oakland, CA 94614
737-200; T.C. A16WE	SA4042WE	Installation of new overhead enclosed stowage compartments, new fluorescent wash lighting and modified passenger service units. Amended 3/20/80.	WE	42150	HITCO 1600 West 135th Street Gardena, CA 90249
727-200, -200C; T.C. A16WE	SA3464WE	Installation of alternate Systron Donner lower engine fire/overheat detector system, P/N 1705-1, in place of approved P/N 1705 lower engine fire/overheat detector system. Issued 9/2/77.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 4th Street Berkeley, CA 94710
737-200C; T.C. A16WE	SA28NW	Interior modification consisting of installation of cargo/passenger partition and coat closet/service tray stowage. Amended 6/29/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA79NW	Seat pallets for Alaska Airlines. Issued 11/9/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA101NW	Interior modification consisting of installation of windscreens and aft coat closet. Issued 4/22/74.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA276NW	Installation of forward LH/RH wind screen in existing approved interior arrangement. Issued 5/13/76.	NW	83765	Vinnedge & Associates P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA337AL	Installation of palletized seating system on high profile cargo roller system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-200C; T.C. A16WE	SA452AL	Installation of palletized cargo/passenger system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405
737-200C; T.C. A16WE	SA492AL	Installation of BE-1006 landing aid system. Amended 12/11/73.	AL	85890	Wien Consolidated Airlines, Inc. 4100 Int'l Airport Road Anchorage, AK 99502
737-201, 737-214; T.C. A16WE	SA1899WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
737-210C; T.C. A16WE	SA3900WE	Installation of heavy duty cargo handling and quick change system, P/N 90045. Issued 4/10/79.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
737-214; T.C. A16WE	SA856CE-D	Installation of two Collins 618T-2 HF radio systems - installation of Bendix "X" band weather radar system - installation of Kollsman Air Data computer. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
737-214; T.C. A16WE	SA1825WE	Installation of Henry Engineering Co. Lounge Tables No. 17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90307
737-222; T.C. A16WE	SA1601WE	Modification of Collins FD109 flight director systems to add a "steering" and "airspeed-hold" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2097WE	Installation of McMilian Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2182WE	Installation of Bendix Third Attitude Indicator (per requirements of FAR 121.305(j)). Issued 6/10/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2232WE	Replacement of nickel-cadmium battery with 2 lead-acid batteries. Amended 1/28/76.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2525WE	Installation of interior arrangement. Amended 12/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3034WE-D	Replace one first class seat assembly with carry-on baggage module, relocate existing garment bag module and remove LH and RH class divider allowing the two modules to serve as class dividers. Issued 1/26/77.	WE	80500	United Air Lines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3360WE-D	Conversion of passenger cabin from 8/85 dual class configuration to 103 seat all coach configuration. Issued 1/5/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3579WE-D	Installation of Arinc Communications Addressing and Reporting System (ACARS). Amended 8/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-242C; T.C. A16WE	SA2372WE	Installation of Satco, Inc. cargo pallet assembly P/N 31094-501 in conjunction with NAS 3610-2B2N, -2B5N, and 1B2N net assemblies. Issued 7/1/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
737-247; T.C. A16WE	SA191NW	Installation of modified two passenger seat and underseat baggage restraint. Issued 6/15/75.	NW	08350	Air Repair, Inc. 811 West Perimeter Road Renton, WA 98055
737-247; T.C. A16WE	ST551SO	Manufacture and installation of P/N 10816 coat closet unit. Issued May 1974.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST552SO	Manufacture and installation of P/N 10815 cart stowage unit. Issued May 1974.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-247; T.C. A16WE	ST567SO	Manufacture and installation of P/N 10949-1 RH aft galley (FS 991.09-1023.25). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST568SO	Manufacture and installation of P/N 10948-1 RH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST569SO	Manufacture and installation of P/N 10950-1 LH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-248C; T.C. A16WE	SA2129WE	Installation of Brownline Division cargo pallet assembly 41121101 and cargo net assembly 41119101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-248C; T.C. A16WE	SA2130WE	Installation of Brownline Division cargo pallet assembly 41120101 and cargo net assemblies: Brownline 22361-51, 22178-51, 41122101, 41123101, AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-275C; T.C. A16WE	SA233NW	Installation of cargo handling equipment for three forward cargo pallet positions. Issued 10/24/75.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737-293; T.C. A16WE	SA2007WE	Installation of header and drape.	WE	62080	Pacific Airmotive Corporation, Inc. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91503
737-293; T.C. A16WE	SA2960WE	Installation of galley module in Nordskog galleys P/N's 897 and 898. Issued 12/31/74.	WE	61529	Neushul Corporation 1911 West 139th Street Gardena, CA 90249
737-293; T.C. A16WE	SA3197WE	Installation of auxiliary stowage compartment. Issued 8/17/76.	WE	04080	Air California P.O. Box 2678, Airport Station Oakland International Airport Oakland, CA 94614
747 Series; T.C. A20WE	SA41GL	Install Brooks & Perkins cargo container P/N 17609-E-100. Reissued 2/2/76.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA44NW	Installation of cargo containers. Amended 11/16/76.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747 Series; T.C. A20WE	SA47GL	Install cargo container P/N 17617-E-100. Amended 7/14/75.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA48GL	Install cargo container P/N 17630-E-100. Issued 4/19/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA108NW	Installation of Mark IV visual entertainment system. Issued 4/26/74.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
747 Series; T.C. A20WE	SA139GL	Install Brooks & Perkins cargo container, P/N 17701-E-100. Issued 10/21/76.	GL	17750	Brooks & Perkins 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA255NW	Installation of Xenon light modification in visual entertainment system. Issued 1/26/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
747; T.C. A20WE	SA508NW	Installation of class divider/coat closet assembly. Issued 8/29/77.	NW	48532	KME Manufacturing Company 849 Seneca, S.W. Renton, WA 98055
747 Series; T.C. A20WE	SA689CE	Installation of Brooks & Perkins cargo container, P/N's 17026-100, Type A; 17026-100-1, Type A; and 17083-100, Type A. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA692CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747 Series; T.C. A20WE	SA694CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA702CE	Installation of Bendix standby horizon indicator and inverter.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
747 Series; T.C. A20WE	SA711CE	Installation Brooks & Perkins cargo container.	GL	17750	Brooks & Perkins, Inc. 1950 West Fort Street Detroit, MI 48216
747 Series; T.C. A20WE	SA792CE	Make and install P/N 17455-100 cargo container. Issued August 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747; T.C. A20WE	SA835NW	Installation of storage units at station 617. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA836NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA837NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747 Series; T.C. A20WE	ST867SO	Installation of Bendix ground proximity warning system. Issued 11/4/75.	SO	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
747 Series; T.C. A20WE	SA1435SW	Refrigerated air cargo container for lower lobe. Issued 2/24/72.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA1780SW	Portable solid oxygen system. Issued 1/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
747 Series; T.C. A20WE	SA2334SW	LD-3 cargo container, P/N DCT 1250. Issued 7/20/76.	SW	04250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74115
747 Series; T.C. A20WE	SA2756WE	Modify aircraft by installation of Hermes refrigerated LD-3 cargo container, Koolflite P/N 1000. S/N 8-3-001 only. Issued 9/6/73.	WE	42120	Hermes Enterprises P.O. Box 5141 Sherman Oaks, CA 91413
747 Series; T.C. A20WE	SA2801SW	Install container baggage/freight LD-3 type. Issued 6/19/78.	SW	04250	Air Cargo Equipment Corp. P.O. Box 15630 Tulsa, OK 74112
747 Series; T.C. A20WE	SA3041WE-D	Replacement of NAS3610-2L1C cargo containers with L size pallets and nets. Issued 7/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747SP; T.C. A20WE	SA285GL	Install MAPCC Model 1550 low boy galley. Amended 1/10/79.	GL	54700	Mensfield Aircraft Products Co. Mansfield Lahm Airport Mansfield, OH 44901
747-21; T.C. A20WE	SA34NE	Installation of Aerospace Div. U.O.P. Inc., main deck closet assembly, P/N 402490-1. Issued 4/18/80.	NE	81120	U.O.P., Inc. Aerospace Division Route 202 Bantam, CT 06750
747SP-21; T.C. A20WE	SA1079EA-D	Installation of flight attendant crew berth compartment in the main cabin, zone "B" aft end. Amended 4/17/79.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
747SP-21; T.C. A20WE	SA1080EA-D	Installation of Delco F130A performance management system. Issued 1/23/80.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
747SP-27; T.C. A20WE	SA1174EA	Installation of 16mm movie system in zone B cabin. Issued 10/30/79.	EA	44000	Inflight Motion Pictures Division of Inflight Services, Inc. 175-28 148th Avenue Jamaica, NY 11434
747-2F6B; T.C. A20WE	SA4072WE	Installation of a video projection system. Issued 1/16/80.	WE	15375	Bell and Howell Company Avicom Division 360 Sierra Madre Villa Pasadena, CA 91109

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-E4A, -E4B; T.C. A20WE	SA307GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500. Issued 5/2/79.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
747-SP44, 747-244B; T.C. A20WE	SA3740WE	Installation of main dock cargo/baggage system. Issued 4/19/79.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-E4A, -E4B; T.C. A20WE	SA2951WE	Installation of Steward Davis Airstairs P/N 77004. Amended 3/23/78.	WE	33770	E - Systems, Inc. Greenville, Division P.O. Box 1056 Greenville, TX 75401
747-100; T.C. A20WE	SA817EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A300-001-101. Amended 3/9/71.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA824EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A400-001-101. Reissued 9/8/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA835EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A401-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA842EA	Installation of Goodyear Aerospace Corp. Universal lower deck baggage/cargo container P/N 625A402-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA2117WE	Installation of 747 lower deck modular and unitized baggage/cargo containers.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
747-100; T.C. A20WE	SA2222WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp. Net Assembly 40234-10, and net assemblies approved to NAS 3610-2AN and NAS 3610-2A3N. Issued 8/16/70.	WE	70250	Satco, Incorporated 1509 El Segundo Boulevard El Segundo, CA 90245
747-100; T.C. A20WE	SA2708WE	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-103. Issued 6/7/73.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747-100 Series; T.C. A20WE	SA3547WE	Installation of cargo container P/N 025-45571	WE	25970	Continential Airlines 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
747-100 Series; 747-200 Series; T.C. A20WE	SA976CE-D	Fuselage structure and related modification for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA977CE-D	Interior modifications for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA978CE-D	Cargo handling and power drive system. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA2646WE	Installation of lock assembly No. 41853-101, -102, -103, -201, -202, -203, -204, -301, -302, -303, -304. Amended 4/20/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200 Series; T.C. A20WE	SA3754WE	Installation of forward and aft lower cargo compartment door sill restraint fittings. Issued 10/9/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, 747-200 Series; T.C. A20WE	SA3813WE	Installation of Brownline side restraint, P/N 44981-101. Issued 12/20/78.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Boulevard Torrance, CA 90505
747-100, -200B; T.C. A20WE;	SA2446WE	Installation of Brownline single pallet lock assembly. Amended 1/3/75.	WE	79500	Tridair Industries Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200B; T.C. A20WE	SA2801WE	Installation of main deck cargo restraint system. Issued 1/16/74.	WE	79000	Transequip Inc. 180 N. Aviation Boulevard El Segundo, CA 90245

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-100, -200B; T.C. A20WE	SA3424WE	Installation of BMA main deck baggage container, P/N 302928. Issued 6/9/77.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-100, -200B, -200C, -200F; T.C. A20WE	SA2845WE	Installation of logo light assembly. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
747-100, -200B, -200C, -200F; T.C. A20WE	SA2895WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100, -200B, -200C, -200F; T.C. A20WE	SA2962WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 12/16/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100 Series, 747-200C, 200F Series; T.C. A20WE	SA3074WE	Installation of 96 x 125 inch animal containers. Amended 11/30/77.	WE	72770	J.D. Smith Air Export, Inc. One World Trade Center Suite 2161 New York, NY 10048
747-100, -200B, -200C, 747SR, 747SP; T.C. A20WE	SA3480WE	Installation of Hughes passenger entertainment/passenger service multiplex system. Issued 11/3/77.	WE	43330	Hughes Aircraft Company Microelectronics Products Div. 500 Superior Avenue Newport Beach, CA 92663
747-100, -200B, -200C, 747SR, 747SP Series; T.C. A20WE	SA3511WE	Installation of stretcher carrier P/N AM2003. Issued 3/21/78.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
747-100, -200B, -200C, -200F; T.C. A20WE	SA3604WE	Installation of Transequip, Inc. auto transponder assembly, P/N 303500. Issued 3/2/78.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-121; T.C. A20WE	SA503EA-D	1) Add additional first class passenger seats and class divider. 2) Add two additional coat closets in Zone C. Issued 5/11/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
747-121; T.C. A20WE	ST714SO-D	Installation of NASA aircraft-to-satellite data acquisition relay (ASDAR) system. Amended 12/14/77.	WE	62300	Pan American World Airways, Inc. J.F.K. International Airport Jamaica, NY 11430
747-121; T.C. A20WE	SA809EA	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-121; T.C. A20WE	SA869EA	Installation of carry-on luggage containers. Issued 4/2/71.	NE	81120	Aerospace Division Universal Oil Products Company Bantam, CT 06750
747-121; T.C. A20WE	SA936EA	Installation of expanded digital flight data recorder system. Amended 4/13/73.	EA	62300	Pan American World Airways Pan Am Building New York, NY 10017
747-121; T.C. A20WE	SA1077EA-D	Installations of Delco F130A flight management system. Amended 8/14/79.	EA	62300	Pan American World Airways, Inc. J.F.K. International Airport Jamaica, NY 11430
747-121; T.C. A20WE	SA2466WE	Installation of AiResearch P/N 216001-401 and -402 class divider - bulkhead assembly. Issued 1/13/72.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121; T.C. A20WE	SA2706WE	Modification by installation of AiResearch coat closed P/N 2130091. Issued 5/30/73.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121; T.C. A20WE	SA3494WE	Installation of Weber Aircraft auxiliary galley, P/N 822767. Issued 9/22/77.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-121, 747-123; T.C. A20WE	SA2444WE	Installation of cables without association with a seating arrangement. Amended 4/27/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
747-121, -122, -238B; T.C. A20WE	SA2823WE-D	Installation of equipment required to conduct NASA/UAL global air sampling program. Amended 11/25/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-121, -123, -273C; T.C. A20WE	SA3007WE	Installation of cargo pallet assembly, P/N 31250-521. Amended 11/19/75.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-121, -132; T.C. A20WE	SA2624WE	Interior arrangement modification. Amended 4/27/78.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121, 747-132; T.C. A20WE	SA3550WE	Installation of Weber auxiliary galley, P/N 822767 Amended 6/1/78.	WE	84900	Weber Aircraft Div. of Walter Kidde & Co., Inc. 2820 Ontario Street Burbank, CA 91510
747-122; T.C. A20WE	SA2193WE	Installation of entree cart 802000, tray cart 803000, liquor cart 804000, and waste cart 805000. Amended 9/2/71.	WE	34220	Fairchild Hiller Corporation Stratos-Western Division 1800 Rosecrans AVenue Manhattan Beach, CA 90266
747-122; T.C. A20WE	SA2658WE	Modification of lower deck cargo compartment restraint system. Issued 3/14/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2717WE	Installation of interior arrangement. Issued 6/26/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2750WE	Modification of aircraft for installation of spacer pallets. Issued 9/7/73.	WE	80500	United Air Lines, Inc. Maint. Base, Engineering Dept. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2821WE-D	Installation of additional service cart retractable tiedowns. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2822WE-D	Modified cabin interior configuration. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2829WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3352WE-D	Reduced first class seating to 26 seat places, relocated class divider, installed 10-across coach seating - 348 coach seat places. Issued 11/14/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3581WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 11/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3942WE-D	Rework of high frequency communications system to install single-sideband capability. Issued 3/27/80.	WE	80500	United Airlines, Inc. San Francisco Int'l. Airport San Francisco, CA 94128
747-122, -123; T.C. A20WE	SA3066WE	Installation of lower lobe food service modules, P/Ns 818720 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-123; T.C. A20WE	SA2926WE	Modification to incorporate cargo restraint system P/N 43830, configuration -101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-123; T.C. A20WE	SA2928WE	Installation of carrier aircraft crew galley Model FTL 47-1 in the upper lounge. Issued 9/6/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
747-123; T.C. A20WE	SA3016WE	Installation of Brownline cargo systems 44297-101 and 44297-102. Issued 5/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-127; T.C. A20WE	SA2972WE	Modification of lower deck aft cargo compartment restraint system to accommodate NAS 3610 Size A aircraft unit load devices. Issued 12/27/74.	WE	17075	Braniff International Exchange Park Dallas, TX 75235

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-128; T.C. A20WE	SA3436WE	Installation of Brownline cargo system 45600-102. Issued 6/21/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-131; T.C. A20WE	SA715CE	Installation of aircraft integrated data system. Amended 12/12/77.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA728CE	Installation of Hamilton Standard TAT/EPRL System.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA877CE	Installation of expanded parameter flight recorder. Amended April 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA2411WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90248
747-131; T.C. A20WE	SA2755WE	Modification of aircraft for installation of 13-inch beverage carts. Issued 9/4/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-131; T.C. A20WE	SA3491WE	Installation of Brownline cargo system 45747-101. Issued 9/27/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-132; T.C. A20WE	SA3381WE	Installation of Brownline lower lobe cargo system, No. 45478-101. Issued 4/11/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-132; T.C. A20WE	SA3446WE	Installation of Browline cargo system 45600-101. Issued 7/5/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-135; T.C. A20WE	ST505SO	Manufacture of Nordskog storage units in accordance with Nordskog drawings 1-209, Rev. B and 1-210, Rev. B and their installation in accordance with NAL E.O. P-2350-01 and P-2350-00-06, Rev. B respectively. Issued 5/23/72.	SO	61220	National Airlines, Inc. Box 2055, Airport Mail Facility Miami, FL 33159
747-135, -151, -251B, -251F; T.C. A20WE	SA90GL	Installation of Bendix GPW-83 ground proximity warning system. Amended 6/8/76.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
747-136; T.C. A20WE	SA1144EA	Installation of movie screens in upper deck and 'B' cabin. Issued 4/27/79.	EA	4400	Inflight Motion Pictures, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-136; T.C. A20WE	SA1145EA	Installation of 16 mm movie pallet in 'B' cabin. Amended 3/31/80.	EA	44000	Inflight Motion Picutres, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-136; T.C. A20WE	SA1438CE-D	Installation of a Type I door in the left-hand side of the upper deck fuselage. Amended 11/9/79.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-151, -251B; T.C. A20WE	SA2703WE	Installation of wheeled refrigerated module, P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-200 Series; T.C. A20WE	SA3659WE	Installation of Litton LTN-72R INS/RNAV and/or LTN-72 INS navigation systems in a triple configuration. Issued 6/21/78.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
747-200B, -200C; T.C. A20WE	SA983EA	Installation of Super 8mm IMPAK projector assemblies, P/N's 10304 ("A" Compartment) and 10306 ("C-D-E" Compartment). Issued 6/18/74.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
747-200F; T.C. A20WE	SA190NW	Installation of 29th position pallet/container kit. Issued 6/10/75.	NW	85142	Western Gear Corporation Flight Structures Division 2100 Norton Everett, WA 98201

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
747-206B; T.C. A20WE	SA1442CE-D	Installation of Type I door, left side, upper deck fuselage. Issued 10/25/79.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-212B; T.C. A20WE	SA4093WE	Installation of a 458, 490, and 514 passenger interior arrangements. Amended 3/28/80.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
747-221F, -246F, -249F; T.C. A20WE	SA3304WE	Installation of Brownline Cargo System No. 45102-101, -103 and -301. Amended 4/26/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-221F; T.C. A20WE	SA4001WE	Installation of Brownline pallet restraint system, P/N 46484-103 and -104. Issued 8/14/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-238B; T.C. A20WE	ST565SO	Lower lobe right hand module unit, P/N 10892-1 left hand module unit P/N 10893-1 and -101, and lower lobe cupboards unit P/N 68878-1 and -101. Amended 7/1/76.	SO	81130	Aerospace Division of UOP 4856 Victor Street Jacksonville, FL 32207
747-238B; T.C. A20WE	SA570EA	Installation of Universal Oil Products tray cart modules P/Ns 68878, 68879, 68880 in Boeing Model 747-238B. Issued 8/31/71.	NE	81120	Aerospace Division Universal Oil Products Company Bantam, CT 06750
747-238B; T.C. A20WE	SA2393WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargo pallet assembly P/N 24076-51 and NAS 3610-2A4P pallet. Issued 8/10/71.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-238B; T.C. A20WE	SA3868WE	Installation of Brownline cargo system 44297 configuration - 104. Issued 1/25/80.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 Lomita Boulevard Torrance, CA 90505
747-245F; T.C. A20WE	SA1032EA	Installation of Collins FPC-75 ground proximity warning system. Amended 3/20/76.	EA	70600	Seaboard World Airlines Seaboard World Building JFK International Airport Jamaica, NY 11430
747-246F; T.C. A20WE	SA3304WE	Installation of Brownline cargo system, No. 45102-101. Issued 11/30/76.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-249F; T.C. A20WE	SA4040WE	Installation of Brownline lower compartment cargo pallet restraint system, P/N 45478-102. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-249F; T.C. A20WE	SA4052WE	Installation of Brownline cargo system, 45600-103. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-257B; T.C. A20WE	SA2307WE	Installation of drink trolly 744000. Reissued 8/3/71.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-258B; T.C. A20WE	SA891EA	Installation of inflight motion picture system. Amended 1/11/72.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11424
747-284B; T.C. A20WE	SA2791WE	Modification of airplane lower deck aft cargo compartment restraint system. Issued 12/10/73.	EU	61797	Olympic Airways S.A. 96, Syngrov Avenue Athens, Greece
Miscellaneous	SA4-1210	Bonnex cover on aircraft surfaces.	WE	33500	Bonair, Inc. Route 1, Box 632 Bakersfield, CA 93308

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH.125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -3A/RA, -1A/S-522, -400A, BH.125-400A, -600A; T.C. A3EU	SA717EA	Installation of Compudex, Inc. model automatic fuel range computer. Amended 10/3/75.	EA	25760	Compudex, Inc. P.O. Box 93 Norristown, PA 19404
DH.125-1A, -1A/522, -1/R-522, -3A, -3A/R, -1A/S-522, -400A; T.C. A3EU	SA826EA	Replacement of lead-acid batteries with sonotone nickel-cadmium batteries. Issued 6/3/70.	EA	13185	Aviation Aids and Technical Service Company P.O. Box 515 Montreal Int'l Airport Montreal 300, P.Q. Canada
DH.125-1A, -1A/522, -1A/R-522, -1A/S-522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, -600A; T.C. A3EU	SA866EA	Installation of Grimes three light strobe kit P/N 34-0301-1. Amended 5/24/74.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
DH.125-1A, -1A/522, DH.125-A/R-522, DH.125-3A, DH.125-1A/S-522, DH.125-3A/RA; T.C. A3EU	SA872EA	Replacement of existing Leland inverter type MGE-23-400. Issued 4/21/71.	EA	15800	The Bendix Corporation Electric Power Division Eatontown, NJ 07724
DH-125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -1A/S-522, -3A/RA, -400A; T.C. A3EU	SA740CE	Install three each single phase solid state inverters, a paralleling control, and a warning control unit. Reissued 1/9/78.	CE	24450	Colt Electronics Company 137 West 9th Avenue N. Kansas City, MO 64146
DH-125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -1A/S-522, -3A/RA, -400, HS-125-600A; T.C. A3EU	SA1466CE	Installation of Phoenix Aerospace VR-1010-24-2AD voltage regulators. Issued 12/22/78.	CE	24450	Colt Electronics Company 137 WEst 9th Avenue North Kansas City, MO 64116
DH 125-1A, 1A/522, -1A/R-522, 1A/R-522-3A, -3A/R, -1A/S-522, -3A/RA, -400A, BH 125-400A, -600A, HS 125-600A; T.C. A3EU	SA2927WE	Installation of logo light on lower surface of horizontal stabilizer. Amended 8/22/77.	WE	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH.125-1A, -1A/522, -1A/S-522, -3A, -400A; T.C. A3EU	SA3382WE	Installation of a single-point pressure refueling system. Amended 6/13/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
DH.125-1A, -1A/522, -1A/3-522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, HS.125-700; T.C. A3EU	SA3551WE	Installation of either a single or dual Global GNS-500A VLF/OMEGA navigation system. Amended 6/20/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, -600A, -700A; T.C. A3EU	SA327EA	Installation of retractable seat. Amended 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
DH.125-1A, 3A, 3A/R, 3A/RA, 400A, HS-125-700A; T.C. A3EU	SA857WE	Installation of GTCP30-92 or GTCP30-92C auxiliary power unit. Amended 1/11/78.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A/522, DH.125 Series 3A, 3A/RA, 400A; T.C. A3EU	SA929EA	Installation of No. 2 battery isolation circuit. Amended 1/31/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -3A, -3ARA, DH.125-400A, BH.125-400A; T.C. A3EU	SA1002CE	Relocation of warning cancel switch from instrument panel to #1 engine power lever. Issued March 1974.	CE	15250	Beech Aircraft Corporation P.O. Box 85 Wichita, KS 67201
DH.125-1A/S-522, Series 3A; T.C. A3EU	SA3925WE	Installation of Garrett AiResearch TFE-731-3-1H engines and related changes. Amended 11/21/79.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-1A/S-522; T.C. A3EU	SA4030WE	Installation of Collins APS-80 autopilot. Issued 11/9/79.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
DH 125-1A, -3A, -400A, BH-125-400A; T.C. A3EU	SA4084SW	Pitot heat monitor system. Issued 2/20/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
DH.125-3A/RA; T.C. A3EU	SA602EA	Installation of bulkhead door and bulkhead at fuselage station 263 13/16.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH.125-3A/RA; T.C. A3EU	SA674EA	Installation of forward and aft bulkheads and doors.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779
DH.125-3A/RA; T.C. A3EU	SA679EA	Installation of bulkhead and bulkhead door at fuselage station 260.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA710EA	Installation of dual Bendix CB-60B compass system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA711EA	Installation of dual Bendix FD-60 flight director system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA712EA	Installation of Bendix 1903718-1 flight director monitor warning system. Amended 7/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA713EA	Installation of Bendix MKA-28C marker beacon receiver system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA714EA	Installation of dual Bendix RNA-26C VHF navigation system with 8RNX-26A glide slope receiver.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA719EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA788EA	Installation of Bendix ALA-51A radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A, -3A/R, -3A/RA; T.C. A3EU	SA457EA	Installation of combined ASI/Machmeter. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A, -3A/R, -3A/RA; T.C. A3EU	SA539EA	Installation of Collins 37P-5 glide slope antenna at fuselage station 114. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125, DH-125-400A; T.C. A3EU	SA355CE	Installation of Hoskins Twilighter Mk III/Mk IIIB high intensity lighting system. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
DH-125, DH-125-400A; T.C. A3EU	SA2404WE	Consolidation of STCs SA355CE and STC 362CE into one STC having MASTER ELIGIBILITY LIST - amended to include improved power supply assembly and subchassis timer assembly for Twilighter MK III high intensity supplementary lighting system. Issued 8/16/71.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
DH-125-400A; T.C. A3EU	SA764EA	Installation of interior furnishings and avionics systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA765EA	Installation of bulkhead and door between fuselage station 249.86 and fuselage station 281.79.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA766EA	Incorporation of entrance area installation.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA767EA	Installation of forward cabin lavatory.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA768EA	Installation of a two place, side facing divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA769EA	Installation of Kollsman combined ASI/Machmeter A39469-10036.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA770EA	Installation of United Controls angle of attach system. Reissued 12/18/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH-125-400A; T.C. A3EU	SA793EA	Installation of Litton skyphone system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA831EA	Installation of three Flite-Tronics PC-17 static inverters and one Jet Electronics & Technology, Inc. emergency power supply, Model PS-800. Issued 6/24/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA833EA	Installation of electric elevator trim system. Amended 4/12/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA1981WE	Installation of Sperry Model SP-40C automatic flight control system (P/N 1782874-512). Amended 11/28/69.	WE	74570	Sperry Slight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 95027
DH-125-400A; T.C. A3EU	SA2066WE	Category II system and equipment approval of Sperry Models SP-40 automatic flight control system P/N 1782874-512, and SPI-60 integrated instrument system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 85027
DH. 125-400A, BH. 125-400A; T.C. A3EU	SA1173EA	Rework of Solar T-62T-39 APU installed by STC SA674CE when Garrett AiResearch TFE-731-3-1H engines are installed. Issued 10/25/79.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125-400A, BH.125-400A; T.C. A3EU	SA3870WE	Installation of Garrett AiResearch TFE-731-3-1H engines and related changes. Issued 2/28/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, BH.125-400A; T.C. A3EU	SA4009WE	Installation of Collins APS-80 autopilot. Issued 8/9/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH 125 Series 400A, BH 125 Series 400A; T.C. A3EU	SA4116WE	Modification of a previously approved Microturbo APU Model 024 type "Saphir4" installation. Issued 3/10/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH-125-400A, BH-125-400A, DH125-1A/S-522; T.C. A3EU	SA4115WE	Installation of light dump baulk system. Issued 3/11/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, DH.125-3A/RA; BH.125-400A; T.C. A3EU	SA844EA	Installation of Teledyne Avionics angle of attack system. Reissued 7/1/76.	EA	78000	Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906
DH.125-400A, DH-125-3A/RA; BH.125-400A; T.C. A3EU	SA857EA	Installation of Microturbo, Inc. auxiliary power unit Model 024, type "Saphir 4." Amended 4/2/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; BH.125-400A, -600A, HS.125-700A; T.C. A3EU	SA674CE	Installation of Solar Model T-62T-39Y or -39 or -40C auxiliary power unit modifications. Amended 5/23/80.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH. 125-1A, -3A, -400A, HS. 125-600A, -700A, BH. 125-400A, -600A; T.C. A3EU	SA1175EA	Installation of access doors. Issued 11/19/79.	EA	73275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125, HS.125 Beechcraft; T.S. A3EU	ST100380	Replace existing lead-acid batteries with Gill BB638/T1-E lead acid batteries, part numbers BSI 200 left and BSI 200 right Issued 6/23/78.	SO	15100	The Battery Shop, Inc. P.O. Box 17312 Nashville, TN 37127
DH-125-400A, HS 125-600A; T.C. A3EU	SA786EA	Installation of lavatory door and bulkhead at station 392. Amended 7/19/76.	EA	07498	AiResearch Aviation Company 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779
BH125-400A; T.C. A3EU	SA1413SW	Three Flite-Tronics static inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
DH-125-400A1; T.C. A3EU	SA3382WE	Installation of a single-point pressure refueling system. Issued 4/12/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
BH125-600A; T.C. A3EU	SA1888SW	Collins flight control system FCS-105. Issued 6/21/74.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BH125-600A; T.C. A3EU	SA1923SW	Solar T62T-39 turbine auxiliary power unit. Issued 1/17/75.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
BH125-600A; T.C. A3EU	SA1948SW	Teledyne Avionics normalized angle of attach indicating system P/N 112B900. Amended 9/14/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
BH125-600A; T.C. A3EU	SA2271SW	Interior. Issued 10/27/76.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203
HBH/HS.125-600A, HS.125-700A; T.C. A3EU	SA1101EA	Installation of GNS-500A VLF/Omega system. Amended 5/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS.125-600A, BH.125-600A, HS.125-700A; T.C. A3EU	SA3705WE	Installation of Garret AIRNAV 200 or an AirNav 300 area navigation system. Amended 3/5/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA1074EA	Installation of bulkhead and door at F.S. 391.5 Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. 3EU	SA1075EA	Installation of forward baggage and avionics compartment. Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1104EA	Installation of oxygen system. Issued 6/7/78.	EA	44035	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A3EU	SA1105EA	Installation of Collins VHF 251 standby communication. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A36EU	SA1106EA	Installation of baggage compartment structural entrance area for use with drawer jump seat. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1107EA	Installation of aft cabin bulkhead and door installation. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1108EA	Installation of avionic equipment rack - washroom. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1109EA	Installation of air distribution system. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1110EA	Installation of emergency lighting system to meet the retroactive requirements of FAR 25.2. Amended 10/25/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1111EA	Installation of Wulfsberg III B flitefone. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1112EA	Installation of nose gear taxi lights. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1113EA	Installation of general lighting. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
HS. 125-700A; T.C. A3EU	SA1114EA	Installation of cabin lining. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1115EA	Installation of Jet AI-804 emeregency horizon. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1116EA	Installation of forward cabin bulkhead LHS and RHS. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A3EU	SA1117EA	Installation of dual Collins ADS-80F air data system. Reissued 7/26/78.	EA	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1118EA	Installation of Collins FGS-80 flight director system with FD 109 instruments. Amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1119EA	Installation of a single Collins ADS-80F air data system. Reissued 7/26/78.	EA	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1120EA	Installation of a side facing single seat. Issued 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS.125-700A; T.C. A3EU	SA1140EA	Installation of a three place side facing divan, aft cabin left hand side. Issued 1/19/79.	EA	44034	Innotech Aviation Limited Montreal International Airport Dorval, Quebec Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1183EA	Installation of bar galley unit. Issued 2/8/80.	EA	44034	Innotech Aviaiton Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1184EA	Installation of Collins WXR-300 color radar system and the Collins RNS-300 radar navigation system. Amended 4/25/80.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
HS 125-700A; T.C. A3EU	SA1196EA	Installation of solar T-62T-40C APU with 400 ampere starter-generator. Issued 5/29/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
HS-125-700A; T.C. A3EU	SA1538CE	Modification of aircraft to incorporate a fuel management computer. Issued 12/4/79.	CE	24540	Colt Electronics Company 131 West Ninth Avenue North Kansas City, MO 64116
HS.125-700A; T.C. A3EU	SA3552WE	Installation of Delco C-IVA inertial navigation system. Issued 1/13/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS. 125-700A; T.C. A3EU	SA3663WE	Installation of Foxboro engine fuel flow and totalizer system. Issued 6/19/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS. 125-700A; T.C. A3EU	SA3690WE	Installation of a Garrett/ AiResearch GTCP36-100 APU in the tail compartment. Issued 6/30/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3878WE	Installation of Eldec engine fuel flow and totalizer system. Issued 3/8/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3885WE	Installation of dual Global GNS-500A VLF/Omega navigation system. Issued 4/16/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
HS.125-700A; T.C. A3EU	SA3984WE	Installation of dual Litton LTN-211 CNS. Issued 7/11/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
HS.125-700; T.C. A3EU	SA4021SW	BKM 100 PHM 700 pitot heat monitor system. Issued 7/24/79.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
HS. 125-700A; T.C. A3EU	SA4042SW	Relocation of center point pressure refueling system. Issued 9/26/79.	SW	11670	Arkansas Modification Center P.O. Box 3356 - Adams Field Little Rock, AR 72203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
HS 125-700A; T.C. A3EU	SA4078SW	Install BKM specific range computer system (SRCS). Issued 1/25/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75234
H.P. 137 Jetstream Mk1; T.C. A21EU	SA275GL	Modification of cabin and cockpit conditioned air and air distrubition system. Issued 11/6/78.	GL	08140	Air Illinois, Inc. Southern Illinois Airport P.O. Box 1224 Carbondale, IL 62901
H.P. 137 MK1 and H.P. 137 as modified STC SA3425WE; T.C. A21EU	SA440SO	Installation of Bendix Model M-4C automatic flight control system (AFCS) and installation of a Bendix M-4DAFCS. Amended 6/21/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, Fl 33310
H.P. 137 MK1; T.C. A21EU	SA785EA	Installation of replacement radome P/N 3079KX. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
H.P. 137 MK1; T.C. A21EU	SA815EA	Installation of Compudex, Inc. Model TJ10-HP automatic fuel range computer.	EA	25760	Compudex, Inc. P.O. Box 93 Morristown, PA 19404
H.P. 137 MK1; T.C. A21EU	SA827EA	Relocation of fire-wall fuel and hydraulic system shut-off valves. Amended 6/25/70.	EA	18750	Butler Aviation-Friendship, Inc. Subsidiary of Butler Aviation International, Inc. Friendship Int'l Airport, MD 21240
H.P. 137 MK1; T.C. A21EU	SA1707SW	Three-place side facing couch. Issued 8/1/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA1769SW	Single seat. Issued 12/6/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA2043WE	Installation of instrument panel for day VFR operation.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2074WE	Installation of 18-passenger cabin interior, instruments, and avionics system.	WE	74270	Spartan - Van Nuys 7929 Hayvennurst Avenue Van Nuys, CA 91406
H.P. 137 MK1; T.C. A21EU	SA2076WE	Installation of Collins AP-104/ FD-109 autopilot - flight director system. Reissued 4/21/70.	CE	24250	Collins Radio Company 5225 "C" Avenue, NE Cedar Rapids, IA 52406
H.P. 137 MK1; T.C. A21EU	SA2115WE	Intallation of observer jump seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2250WE	Relocation of fuel and hydraulic shut-off valves (modification found to comply with requirement of AD 70-15-04, Amendment 39-1031). Reissued 10/24/72.	WE	49850	Lear Avia Corporation P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
H.P. 137 MK1; T.C. A21EU	SA2293SW	P & W AGL PT6A-34 engines. Issued 7/9/76.	SW	46340	Jetstream, Inc. Box 1132 Waco, TX 76705
H.P. 137 MK1; T.C. A21EU	SA3064WE	The installation of an alternate method of complying with AD 72-23-01 by equivalency. Amended 9/23/75.	WE	11354	Apollo Airways 404 William Moffet Road Goleta, CA 93017
H.P. 137 MK1; T.C. A21EU	SA3136WE	Installation of ice shield on fuselage. Issued 1/19/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017
H.P. 137 MK1; T.C. A21EU	SA3281WE	Modification of cabin and cockpit air distribution system. Issued 10/12/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017
H.P. 137 Mk 1; T.C. A21EU	SA3425WE	Installation of two AiResearch TPE331-3U-303V engines and related changes. Amended 2/2/78.	SW	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101
H.P. 137, MK-1; T.C. A21EU	SA3534WE	Installation of cabin interior arrangement. Reissued 1/16/78.	WE	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
HP.137 MK1; T.C. A21EU	SA3598WE	Installation of Abex P/N 40161 Model AP05V-060 hydraulic pump in lieu of original Vickers hydraulic pump. No installation data required. Issued 6/12/78.	WE	71655	Sierra Pacific Airlines 703 Airport Road Bishop, CA 93514
H.P. 137; T.C. A21EU	SA3932WE	Installation of underseat baggage restraint bars. Issued 5/14/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
B-121 Series 1, 2, 3; T.C. A22EU	SA308EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
B-121 Series 1, 2, 3; T.C. A22EU	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Beagle B.206 Series 2; A11EU	SA667SO	Installation of Bendix Model M-4C automatic flight control system.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
B206; T.C. A11EU	SA683SO	Installation of Goodrich wheels, brakes, and tires on main landing gears.	SO	58700	Miami Aviation Corporation Hangar 102, Opa Locka Airport Opa Locka, FL 33054

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BRITISH AIRCRAFT CORPORATION, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BAC 1-11; T.C. A5EU	SA514EA-D	Install Butler Vector Analog Computer System to provide area navigation capability. Amended 11/17/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11; T.C. A5EU	SA279NW	Interior arrangement. Issued 4/30/76.	NW	01700	AeroAmerica, Inc. 7777 Perimeter Road Seattle, WA 98108
BAC 1-11; T.C. A5EU	SA634SW	Litton low range radio altimeter.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA660SW	Cockpit voice recorder A-100 and control panel A-152.	SW	17075	Braniff International P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA792SW	Relocation of LAS 109C flight recorder.	SW	17075	Braniff Airways Love Field Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA973WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
BAC 1-11; T.C. A5EU	SA1213WE	Fairchild A113 cockpit voice recorder and A152A control panel.	WE	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11; T.C. A5EU	SA1350SW	Installation of center wing tank fuel system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1432SW	Installation of Collins INS-61B inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1740SW	Install dual Delco Carousel IV or IVA inertial navigation systems. Reissued 4/10/80.	WE	78490	Tiger Air, Inc. 1888 Century Park East Los Angeles, CA 90067
BAC 1-11; T.C. A5EU	SA1761SW	Dual Collins INS 61B inertial navigation systems. Reissued 3/20/74.	GL	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11; T.C. A5EU	SA2365SW	Modification of Marston heat exchanger. Issued 10/5/76.	SW	52068	LORI 501 South Lansing Tulsa, OK 74120
BAC 1-11; T.C. A5EU	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, and EL-104B in emergency slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
BAC 1-11; T.C. A5EU	SA2709SW	Installation of heat exchanger. Issued 1/23/78.	SW	52068	LORI 510 South Lansing Tulsa, OK 74120
BAC 1-11, 200 Series; T.C. A5EU	SA1947WE	Installation of underseat baggage restraint system. REissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
BAC 1-11, 200 Series; T.C. A5EU	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
BAC 1-11, 200 Series; T.C. A5EU	SA3616WE	Installation of single LTN-51 or LTN-72 inertial navigation system. Issued 3/27/78.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2261WE	Installation of inflatable emergency evacuation slides at forward passenger and service doors. Amended 7/14/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2306WE	Installation of emergency exit lights at forward passenger door, at forward service door, and at both overwing emergency doors. Issued 1/15/71.	WE	44266	International Inflatables Company Div. Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2722WE	Modify aircraft by installation of wing mounted emblem lights. Amended 1/26/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2813WE	Structural modifications. Amended 7/15/74.	WE	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11 203/AE, 204/AF, 215/AU; T.C. A5EU	SA1021EA	Installation of Collins FPC-75 ground proximity warning system and Bendix ALA-51A radio altimeter system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
BAC 1-11 204/AF, 215/AU; T.C. A5EU	SA840EA	Installation of Technical Standard Order inflatable escape slides. Amended 2/17/71.	EA	07250	Air Cruisers Company Division of Garrett Corporation P.O. Box 180 Belmar, NJ 07719
BAC 1-11 400 Series equipped with Rolls Royce RB 163-25 Spey 511-14 engines; T.C. A5EU	ST846SO	Increase maximum ramp weight to 89,000 lbs., increase maximum take-off weight to 88,500 lbs. and decrease maximum landing weight to 77,200 lbs. Issued 7/1/75.	SO	37885	Bruce Gilman P.O. Box 1372 Vickksburg, MS 39180
BAC 1-11 400; T.C. A5EU	SA3439WE	Installation of single or dual Litton LTN-51 inertial navigation systems. Issued 7/22/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91367
BAC 1-11, 401/AK; T.C. A5EU	SA403EA-D	Interior configuration - change from 69 passenger all coach to 16 first class and 49 tourist class with class divider and curtain installation between two sections.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA408EA-D	Installation of maintenance/flight data recording system. Amended 7/19/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA422EA-D	Installation of dual Collins AL-101 low range radio altimeter.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA449EA	Cockpit voice recorder.	EA	60092	Mohawk Airlines, Inc. Oneida County Airport Utica, NY 13503
BAC 1-11, 401/AK; T.C. A5EU	SA553EA-D	Installation of autopilot go-around unit on BAC 1-11. Amended 10/6/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 410AK; T.C. A5EU	SA554EA-D	Install underseat luggage retention device. Amended 12/4/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11 410AK; T.C. A5EU	SA555EA-D	To comply with FAR 25.812(e), a lever lock switch will be installed at a point accessible seat. Amended 4/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA2868WE	Installation of executive interior. Amended 7/15/74.	WE	07500	AiResearch Aviation Corporation 6201 W. Imperial Highway Los Angeles, CA 90045
BAC 1-11, 401/AK; T.C. A5EU	SA2971WE	Installation of maximum 1565 gallon auxiliary fuel tanks in forward and aft cargo compartment. Amended 2/12/80.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91505
BAC 1-11 401/AK; T.C. A5EU	SA3431WE	Installation of two couches in aft of aircraft. Issued 6/15/77.	WE	62083	Pacific American Airlines 2800 Clybourn Avenue Burbank, CA 91510
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB, 422/EQ; T.C. A5EU	SA1995WE	Installation of auxiliary fuel tanks in forward and aft cargo compartments. Amended 12/6/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB; T.C. A5EU	SA2776WE	Installation of dual Litton, LTN-51 inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BAC 1-11, 401AK, 410AQ, 412A/EB, 414EG, 419EB, 422EQ; T.C. A5EU	SA2873WE	Installation of a single or dual Litton, LTN-104, area navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EP; T.C. A5EU	SA3567WE	Installation of single or dual Litton LTN-51 or LTN-72 INS. Issued 3/17/78.	WE	51500	Litton Aero Products Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
BAC 1-11, 412A/EB Series, 422EQ; T.C. A5EU	SA2911WE	Installation of relocated engine water injection storage tank. Amended 2/20/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
BAC 1-11, 414EG; T.C. A5EU	SA3819WE	Installation of 1478 gallon auxiliary fuel tank system in the forward and aft cargo compartments. Issued 1/25/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
140 Series; T.C. 768, 5A2	SA4-79	Recovering of wings with metal .020 aluminum 2024-T3 clad.	NW	61780	Francisco Ochoa 4836 E. Mercer Way Mercer Island, WA 98040
140 Series; T.C. 768, 5A2	SA4-376	Lycoming C-235-C1 engine.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
140 Series; T.C. 768, 5A2	SA105GL	Install a pitot-static tube. Issued 1/16/76.	RM	48529	Lowell Kleven P.O. Box 1279 Jackson, WY 83001
140 Series; T.C. 768, 5A2	SA175WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	70614	Seagull Aviation P.O. Box 104 Brigham City, UT 84302
140 Series; T.C. 768, 5A2	SA267SW	Continental O-200-A engine and a McCauley 1A100 MCM propeller.	SW	74850	S & S Pipeline Patrol P.O. Box 787 Dickinson, TX 77539
140, 170, 172, 175, 180; T.C. 768, 5A2, 799, 3A12, 3A17, 5A6	SA1-252	Safety gear Model A.	EA	37140	Geiss Gears, Inc. 3350 Tennyson Street, NW Washington, D.C. 20015
140, 150, 170, 172, 175, 180, 182, 185, 210; T.C. 768, 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21	SA12WE	Fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
140, 150, 172 Series; T.C. 768, 5A2, 3A19, 3A12	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
140, 150, 170, 172, 175, 180, 182, 210 Series; T.C. A768, 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A21	SA596EA	Installation of electronic voltage alarm Drawing No. 80104.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
140A; T.C. 5A2	SA323GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
140A; T.C. 5A2	SA547EA	Installation of Continental O-200-A engine and McCauley 1A100-MCM6952 or 1A101/DCM6952 propeller. Amended 3/12/80.	EA	52542	John T. Lucas & M. David Emmett RD #2 Emporium, PA 15834
140A, 150, 170, 172, 175, 180, 182, 185, 206, 210, 207, 305; T.C. 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, A4CE, 3A21, A16CE, 5A5, 3A14	SA995SW	Increase wing leading edge radius wing tip fairings, and landing light lens. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
140A, 150, 170, 172, 175, 177, 180, 182, 165, 206, 210, 207, 305 Series; T.C. 3A17, 5A6, 3A13, 3A24, A4CE, 3A21, A16CE, 5A2, 799, 5A5, 3A19, 3A12, 3A14	SA1371SW	Wing leading cuff, wing tips and upper surface flow fences. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
140A, 150, 170, 172, 175, 180, 182, 185, 206, 207, 210, 305 Series; T.C. 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, A4CE, A16CE, 3A21, 5A5	SA1478SW	Installation of "NASA" 1223000-7 and -8 wing tip. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
150 Series; T.C. 3A19	SA1-479	Aero control AP and heading lock GD.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109
150 Series; T.C. 3A19	SA1-630	Dry vacuum pump and instrument vacuum system 113A5.	GL	03760	Airborne Mechanisms Division Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
150 Series; T.C. 3A19	SA4-965	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150 Series; T.C. 3A19	SA4-1342	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
150 series; T.C. 3A19	SA4-1373	Brake blocks AB-6531 and AB-6532.	EA	46748	Johns-Manville Corporation 22 E. 40 Street New York, NY 10001
150 Series; T.C. 3A19	SA17WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	64275	Peterson Aviation 3100 Airport Avenue Santa Monica, CA 90406
150 Series; T.C. 3A19	SA164WE	Fuel filter FFF-100.	WE	64600	Pioneer Aero Service P.O. Box 227 Burbank, CA 91500
150 Series; T.C. 3A19	SA534CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
150 Series; T.C. 3A19	SA607SW	AK193 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
150 Series; T.C. 3A19	SA1433WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
150, 172, 175, 180, 182, 310; T.C. 3A19, 3A12, 3A17, 5A6, 3A13, 3A10	SA1-124	Lube oil filter BF55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
150, 170, 172, 175, 180, 182; T.C. 3A19, 799, 3A12, 3A17, 5A6, 3A13	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
150, 170, 172, 175, 180, 182, 185, 210; T.C. 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21	SA2208SO	Tow bar, release mechanism, and safety tow link.	SO	37092	Gasser Banners, Inc. P.O. Box 3502 Metropolitan Airport Nashville, TN 37217
150, 180 Series; T.C. 3A19, 3A13	SA2708SO	Water and ice detector in fuel gascolator and carburetor.	SO	71545	Charles B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
150, 170, 172, 177, 180, 182; T.C. 3A19, 3A12, 799, 5A6, 3A13, A13CE	SA3168SO	Carburetor ice detector. Amended 8/31/66.	SO	71545	C.B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
150, 170, 172, 175; T.C. 3A19, 799, 3A12, 3A17	SA971WE	Installation of Jasco 76540 (35a.) alternator kit or Jasco #6555 (50a.) alternator kit. Amended 10/29/76.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M, 170B, 172, 172A, B, C, D, E, F, G, H, I, K, L, M, 175, 175A, B, C, P172D, 180, 180A, B, C, D, E, F, G, H, J, 182A thru P, 185, 185A, B, C, D, E, A185E, A185F, 210, 210A, B, C, D, 205, 205A; T.C. 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21	SA150NW	Installation of flap gap seals. Amended 9/16/75.	NW	16856	B & M Aviation P.O. Box 1563 Bellingham, WA 98225

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150, 150A thru 150H, 150J, 150K, 150L, M, A150M, 170A, B, 172, 172A thru 172I, 172K, L, 175, 175A, B, C, 180, 180A, 180H, 182, 182A thru 182N, 185, 185A thru 185E, A185E, 188, 188A, A188, A188A, 206, P206 thru P206E, U206, U206A thru U206F, TP206A thru TP206E, TU206A thru TU206F, 210, 210A thru 210K, T210F, T210G, T210H, T210J, T210K, (205) 210-5, (205A) 210-5A; T.C. 3A19, A-799, 3A17, 5A6, 3A13, 3A24, A9CE, 3A12, A4CE, 3A21	SA172NW	Installation of drooped type wing tips. Issued 4/18/75.	NW	19830	Robert C. Cansdale 29511 9th Place S. Federal Way, WA 98002
150, 150A, B, C, D, E, F, G, H, J, K, L, M, 152; T.C. 3A19	SA175GL	Convert to conventional landing gear. Amended 12/5/78.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 SW London, OH 43130
150, 150A thru H, 150J thru M, A150K, A150L, A150M, 152, A152; T.C. 3A19	SA223GL	The installation of the stall strips. Amended 4/24/79.	GL	52650	MacKenzie Aviation Company 3847 Bassett Road Rootstown, OH 44272
150, 150A thru H, J thru M, A150K thru A150M, 152, A152; T.C. 3A19	SA268GL	Installation per Bolen Drawing No. 8978 or wheel and ski adapters on Models 150F, G, H, J, K, L, M, 152 aircraft modified per STC SA175GL. Installation per Bolen Drawing 879, adapter, extension-landing gear gear Drawing No. 880 landing-gear extended-assembly on Models 150, 150A thru H, J thru M, A150K thru A150M, 152 thru H, J thru M, A150K thru A150M, 152, A152 aircraft modified per STC SA175GL. Amended 3/5/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
150, 150A, B, C, D, E; T.C. 3A19	SA318GL	Bolen wheel extenders on Cessna models modified per STC SA175GL and/or SA268GL. Issued 6/12/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M; T.C. 3A19	SA324GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
150, 150A, B, C, D, E, F, G, H; T.C. 3A19	SA326EA	Wet-to-dry vacuum pump conversion kit 300-3. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
150-150C, 1500# Gr. Wt., 150D-150K, 1600# Gr. Wt.; T.C. 3A19	SA403CE	Install FluiDyne A2000A main skis and NA800 nose ski. Amended 2/24/70.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
150 thru 150G; T.C. 3A19	SA527CE	Installation of Hoskins Twilighter Mark-I high intensity light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
150 thru 150H, 150J, 150K, 150L, A150L, 150M, A150M Normal Category (landplanes), 150G and H, J, K (seaplanes) and A150K acrobatic category landplane; T.C. 3A19	SA572CE	Install Lycoming engine and Sensenich propeller on landplanes and on seaplanes. Reissued 5/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
150; 172, 172, B; 175; 180, 180A, B, C, D; 182, 182A, B, D, D; 185, 185A; 210, 210-5; 195, 195A, 195B; 310, 310A, B, C, D, E, F, G; T337G; T.C. 3A19, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21, A790, 3A10, A6CE	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 1758 San Leandro, CA 94577

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150, 150A thru 150M, A150K, L, M; 172, 172A thru M; 175, 175A thru C, P172D; 177, 177A, B; 177RG; 180, 180A thru 180J; 182, 182A thru 182P; 185, 185A thru 185E, A185E, A185F; 188, 188A, B, A188, A188A, A188B; 206, P206, P206A thru P206E, TU206A thru TU206F, TP206A thru TP206E, U206, U206A thru U206F; 207, T207, 207A, T207A; 210, 210A thru 210L, T210F, G, H, L, 210-5, 210-5A; 310, 310A thru 310J, 310J-1, E310J, 310K, L, N, P, 310Q, T310P, T310Q; 320, 320A thru 320F, 320-1, 340; 336; 337, 337A thru 337F, T337D, E, F, G; 401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 421, 421A, B; T.C. 3A19, 3A12, 3A17, A13CE, A20CE, 5A6, A-790, 3A13, 3A24, A9CE, 3A15, A4CE, A16CE, 3A21, 3A24, 3A10, 3A25, A2CE, A6CE, A7CE, A16CE	SA615EA	Installation of Whelen anti-collision strobe light system, models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
150, 150A thru G; 170, 170A, 170B; 172, 172A thru 172E; P172D, 175, 175A thru 175D; 180, 180A thru 180E; 182, 182A thru 182D; 185, 185A thru 185C; 195, 195A, 195B; 210, A thru I; 310, 310A thru 310H; T.C. 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A24, A-790, 3A21, 3A10	SA630NE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
150, 150A thru L, A150K, 172I, 172K, 172L; T.C. 3A19, 3A12	SA695CE	Install Frantz oil filter. Amended 5/25/71.	GL	70360	Schmidt Aero Service Municipal Airport Worthington, MN 56187
150 thru 150H, 150J, 150K, A150K, A150L, 150M (landplanes), 150G, 150H, 150J, 150K (seaplanes) 150 hp only; T.C. 3A19	SA750CE	Installation of Lycoming 150 and 160 hp Model O-320-( ) engine and McCauley propeller 1C172/TM. Amended 10/10/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North Wichita, KS 67204
150, Serial Nos. 15061533 and up; T.C. 3A19	SA844CE	Installation of electro pneumatic stall warning system. Issued May 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
150, 172, 175, 177, 180, 182, 185, 206, 210 Series; T.C. 3A19, 3A12, 3A17, A13CE, 5A6, 3A13, 3A24, A4CE, 3A21	SA890SW	Medairco Automatic Fuel Alert F-2.	SW	57500	Medairco 3601 East Admiral Place Tulsa, OK 74150
150, 150A, B, C, D, E, F, G, H, J, K, L; T.C. 3A19	SA909CE	Install STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
150, 150A, B, C, D, E, F, G, H, J, K, L; T.C. 3A19	SA944CE	STOL kit installation. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150L; T.C. 3A19	SA287GL	Installation of Lycoming O-320-D2B engine and McCauley Model 1C172/TM propeller using the existing installation hardware on an aircraft previously modified in accordance with STC SA572CE. Issued 12/15/78.	GL	71505	Max L. Shanklin 1769 Rooker Road Mooresville, IN 46158
150F, G, H, J; T.C. 3A19	SA221GL	Installation of wheel replacement type skis, FluiDyne all metal (TSO approved) Model A2000A main skis, FluiDyne Model AT2000A tail ski. Issued 2/14/78.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
150F thru K; T.C. 3A19	SA2035WE	Installation of Aerial photographic camera kit serial No. 101. Amended 7/17/70.	NW	34824	Federal Water Pollution Control Administration Pacific Northwest Water Laboratory 200 S.W. 35th Street Corvallis, OR 97330
150F, G, H, J, K; T.C. 3A19	SA2846SW	Conversion from trigear to conventional gear configuration and reconversion to trigear. Issued 9/8/78.	SW	28000	Custom Craft, Inc. 234 West Turbo Drive San Antonio, TX 78216
A150K, A150L; T.C. 3A19	SA1395SW	Revise fuel and oil system for inverted flight. Issued 11/24/71.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
A152; T.C. 3A19	SA1384CE	Install Lycoming O-320-E2D engine and McCauley 1C172TM7458 propeller. Issued 11/11/77.	CE	12777	Avcon Industries 1006 W. 53rd Street N. Wichita, KS 67204
170 Series; T.C. 799	SA1-13	Recovering of wings with metal except ailerons and flaps.	GL	37182	General Aviation, Inc. P.O. Box 232 Lost Nation Airport Willoughby, OH 44094
170 Series; T.C. 799	SA1-107	69A103 gyro stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
170 Series; T.C. 799	SA1-240	Lycoming O-435-C engine and Hartzell HC-12X20-8D/8433-6 or HC-12X20-5C/8433-6 propellers.	NE	37050	Fulton Conversion Company Southbury, CT 06488
170 Series; T.C. 799	SA1-245	Lycoming O-340-A1A engine and Hartzell HC-82XL-1D/8433-12 propeller on aircraft with Edo 89-2000 floats.	NE	79952	Turner Aviation Company, Inc. Turner, ME 04282
170 Series; T.C. 799	SA1-316	Dart I-M turn control unit.	EA	61400	Navigation Devices, Inc. P.O. Box 1107 Binghamton, NY 13902
170 Series; T.C. 799	SA1-416	Lube oil filter. Amended 9/11/67.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
170 Series; T.C. 799	SA1-647	Leading edge landing lights.	EA	72100	Skycraft Design, Inc. Mercer County Airport West Trenton, NJ 08628
170 Series; T.C. 799	SA3-53	Model 3000 main and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-159	C-3000 main and AWT 2500A or CT-3000 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-329	C-3000 main ski and AWT 2500A tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-335	C-3000 wheel ski on airplanes having a cross-wind wheel utilizing a 6.00-6 tire.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-451	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1504 Gretchen Wichita, KS 67202
170 Series; T.C. 799	SA3-695	Dacron fabric on wings.	GL	30518	Downer Aircraft Company Alexandria, MN 56308
170 Series; T.C. 799	SA4-7	Recovering of wings with metal skin. Amended July 1973.	WE	73000	Leo F. Smith & Company, Inc. 225 South Bent San Marcos, CA 92069

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
T170 Series; T.C. 799	SA4-11	Recovering of wings with metal except flaps and ailerons.	WE	02620	Aero Sales & Service, Inc. Chandler Field Fresno, CA 93721
170 Series; T.C. 799	SA4-28	Conversion to tricycle gear type.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170 Series; T.C. 799	SA4-55	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170 Series; T.C. 799	SA4-226	Metal skin on wings.	WE	18275	Frank A. Burdick 43316 N. 20th Street, W. Lancaster, CA 93534
170 Series; T.C. 799	SA4-486	Glass cloth with resin applied.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
170 Series; T.C. 799	SA4-802	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
170 Series; T.C. 799	SA4-993	Full flow filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
170 Series; T.C. 799	SA4-1062	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
170 Series; T.C. 799	SA4-1096	Eonite covering on wings.	WE	52090	William G. Lott P.O. Box 652 Shafter Airport Bakersfield, CA 93300
170 Series; T.C. 799	SA5-44	Conversion of aircraft for parachute jumping operations.	AL	14900	Barton Air Service 1700 E. Fifth Avenue Anchorage, AK 99500
170 Series; T.C. 799	SA15CE	Dry vacuum pump and vacuum system 113A6.	GL	03760	Airborne Mechanisms Division Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
170 Series; T.C. 799	SA235SO	Recovering of wings with .020 alclad 2024-T3 aluminum.	SO	43300	Hudson Aircraft Service P.O. Box 2471 W A S Tallahassee, FL 32302
170 Series; T.C. 799	SA236WE	Cessna 210 wing tips 12230000-1 and -2.	RM	84394	Donald H. Wagner P.O. Box 267 Grand Junction, CO 81501
170 Series; T.C. 799	SA351WE	Pneumatic pitch assist PC-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
170 Series; T.C. 799	SA544CE	Installation of Flight Systems Model 500B white strobe beacon.	GL	35727	Flight Systems P.O. Box 62 Wheeling, IL 60090
170 Series; T.C. 799	SA1008WE	Poly-Fiber covering of both wings. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
170, 170A, 170B; T.C. 799	SA2-224	Windshield manufactured in accordance with Luminous Plastics, Inc. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
170, 170A, 170B; T.C. 799	SA23GL	Installation of wheel replacement skis Model M2000, M3000. Reissued 1/13/76.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapid, MN 56470
170, 170A, 170B; T.C. 799	SA135CE	Lycoming O-320-A1A, -A1B, -A3A, -A3B, or O-320-B1A, -B1B, -B3A, or B3B engine, Hartzell HC-82X or -A2X Series propellers with 7636D-4 blades and Woodward 210080 governor. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170, 170A, 170B; T.C. 799	SA196NW	Installation of blown bubble, one-piece, clear plexiglass windshield. Issued 7/10/75.	NW	71506	Jack Shannon 8451 S.E. 39th Mercer Island, WA 98040
170, 170A, 170B; T.C. 799	SA210GL	Installation of Great Lakes Aero Products windshield P/Ns W-2055, W/T-2055 or W/G-2055. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170, 170A, 170B; T.C. 799	SA224AL	Installation of L-2500A or L-3000 skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
Cessna 170, 170A, 170B; T.C. 799	SA632AL	Install McCauley 1A175TDM80 propeller.	AL	08492	Alaska Propeller Specialists, Inc. 5251 Lakeshore Drive Anchorage, AK 99503
170, 170A, 170B, 172, 172A; T.C. A-799, 3A12	SA152NW	Installation of deck and glare shield (with and without instrument lights). Issued 1/13/75.	NW	70384	R.J. Schroers 4479 139th Avenue, S.E. Bellview, WA 98006
170 thru 170B, 172 thru 172K, P172D, R172E, R172F, 175 thru 175C, 180 thru 180H, 182 thru 182M, 185 thru 185E, A185E; T.C. 799, 3A12, 3A17, 5A6, 3A13, 3A24	SA605CE	Install O'Neill Model "Ultralite" 7G aircraft.	GL	61850	O'Neill Airplane Company 791 Livingston Carlyle, IL 62231
170, -A, -B; 172, -A thru -H; 175, -A, -B, -C, P172D, R172E (141E); *177; 180, -A, -B, -C, -D, -E, -F, -G, -H; 182, -A, -B, -C, -D, -E, -F, -G, -H, -J, -K; 185, -A, -B, -C, -D, -E, A185E; 210, -A, -B, -C, -D, -E, -F, T-210F, 210G, T-210G, 210-5(205), 210-5A(205A); 401, 402, 411, 411A; T.C. A-799, 3A12, 3A17, A13CE, 3A13, 3A24, 3A21, A7CE *Approved anti-collision light system is required.	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
170, 170A, 170B; T.C. A-799	SA2472WE	Installation of strobe light systemNW with flashtube on rudder tip and power supply in fuselage. Issued 2/9/72.		70384	R.J. Schroers 4479 139th Avenue S.E. Bellevue, WA 98006
170, 170A, 170B; T.C. A-799	SA3715WE	Installation of vertical tail floodlight. Issued 9/27/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
170A; T.C. 799	SA1973WE	Installation of Hanna-Aero Corp. voltmeter P/N 1305.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
170A, 170B; T.C. 799	SA3-13	Install 170 hp Lycoming O-340-A1A engine and Hartzell HC-82XL-1DB/8433-12 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170A, 170B; T.C. 799	SA3-672	Lycoming O-360-A1A, A1D or B1B engine and McCauley 2D36C14-X/78KM-4 propeller or Lycoming O-360-A1A and A1D engines with Hartzell HC-C2YK-1A/7666A-2 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170A, 170B; T.C. A-799	SA325GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
170A, 170B (Landplane only); T.C. 799	SA421CE	Lycoming O-360-A1A or O-360-A1D 180 hp engine, O-360-B1B 168 hp engine and constant speed propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
170A, 170B; T.C. 799	SA749CE	Install Hartzell propeller model HC-C2YK-1A/7666A.	CE	12775	Avcon Industries, Inc. Route 1, Box 204A Augusta Municipal Airport Augusta, KS 67010
170A, 170B (landplanes, normal category only); T.C. A-799	SA806CE	Installation of Lycoming engine model O-360-A1A and McCauley propeller model HC-C2YK-1B/7666A-2. Amended September 1976.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 Wichita, KS 67204
170A, 170B; T.C. 799	SA989CE	Installation of STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170A, 170B; T.C. A-799	SA1073CE	Installation of wing leading edge cuffs, Cessna drooped wing tips, stall fences, and aileron gap seals. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 606 Udall, KS 67146
170A, 170B (Normal Category); T.C. A-799	SA2454WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
170A, 170B (landplane only normal category); T.C. A-799	SA3797WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision, muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29675	Del-Air P.O. Box 746 Strathmore, CA 93267
170A, B, 172A thru 172M, 175, 175A thru 175D; T.C. A-799, 3A12, 3A17	SA115NW	Modification of R.H. Door and the addition of a jump seat. Issued 5/24/74.	NW	18260	Charles P. Bunch 1211 Donovan Avenue Bellingham, WA 98225
170A, B, 172, 172A thru 172I, K, L, M, N, 175 thru 175C; R172K; T.C. 799, 3A12, 3A17	SA1614WE	Installation of one 12-gallon auxiliary fuel tank in each outboard wing panel. Amended 2/15/79.	WE	35746	Flint Aero 8402-G N. Magnolia Gillespie Field Plaza Santee, CA 92071
170B; T.C. 799	SA111NW	Installation of McCauley 1A175-DM propeller with Cessna 0550162 spinner on Continental C-145 series and O-300 series engines. Reissued 6/28/74.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
170B; T.C. 799	SA602AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA602AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	AL	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA603AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA603AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	AK	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA604AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA604AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA1417SW	Mitchell automatic flight system AK358 consisting of Century I autopilot with optional omni tracker. Issued 1/10/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
170B; T.C. A-799	SA1490CE	Installation of flap and aileron gap seals.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
170B (Landplane only, Normal & Utility Category); T.C. A-799	SA2100WE	Installation of contoured wing leading edge and aileron gap cover. Reissued 1/18/77.	WE	65700	Marshall E. Quackenbush P.O. Box 235 Inyokern, CA 93527
170B; T.C. A-799	SA2851SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
170B (Landplane only, Normal & Utility Category); T.C. A-799	SA3318WE	Installation of flap gap closures. Issued 1/5/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
170B, 172 A, B, C, 175, A, B, C, 180, A, B, C, D, F, 182, A, B, C, D; T.C. A-799, 3A12, 3A17, 5A6, 3A13	SA1-612	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
170B, 172, 172A, 172B, 172C, 172D; T.C. A-799, 3A12	SA93EA	Installation of Monitair angle of attack system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170B; 172, 172A thru H, 175, 175A, B, C, 180, 180A thru H, 182, 182A thru D; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA175EA	Installation of wing struts modified to include Wings With Springs Model 200 hydraulic-pneumatic shock absorbers and associated airframe modifications. Amended 8/17/77.	EA	86500	Wings With Springs, Inc. Box 495, R.D. 3 Latrobe, PA 15650
170B, 172, 172A, B, C, D, E, F, G, H, I, K, L, M, 172A, 175, 175A, B, C; T.C. A-797, 3A12	SA293NW	Installation of Franklin 6A0350-C6 engine, McCauley 2A31C21/84S06 propeller using Kit No. 20690 as per STC SA360EA. In addition, installation of Hartzell HC-C2YF-1BF/F8459-4 to -8 conjunction with same engine. Issued 6/22/76.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98661
170B, 172, 172A; T.C. A-799, 3A12	SA360EA	Installation of Franklin Engine Co., Inc. Model 6A-335-B engine with McCauley 2A31C21/84S-8 propeller and new engine mount and associated components. Amended 6/19/70.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
170B, 172 thru 172L; T.C. A799, 3A12	SA499NW	Installation of Robertson Aircraft STOL kit with Robertson leading edge cuff, fence, Cessna wing flap filler panel. Issued 8/29/77.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98660
170B, 172B thru M, 175, 175A thru C; T.C. A797, 3A12, 3A17	SA637NW	Instllation of AC oil filter assembly CF-104A. Issued 7/13/78.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98661
170B; 180; 185; T.C. 799, 3A24, 5A16	SA1971WE	Installation of Model ARB-3 Automatic Downed Aircraft Marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue, Box 622 Fort Collins, CO 80521
170, 172 Series T.C. 799, 3A12	SA4-1404	Vacuum system 121 and 121A. (Eligible only on engines with dampened crankshafts).	WE	40685	Marlin and Myron Harms 10828 Burl Avenue
170, 172 Series; T.C. 799, 3A12	SA318WE	Torsc tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
170, 172 Series; T.C. 799, 3A12	SA429WE	Exhaust pipe extensions LG-100.	WE	39463	Lloyd M. Green 619 W. Roses Road San Gabriel, CA 91776
170, 172 Series; T.C. 799, 3A12	SA672SW	Cessna 305(L-19) wings.	SW	76737	James A. Summersett, Jr. 418 Redcliff Drive San Antonio, TX 78216
170, 172 Series; T.C. 799, 3A12	SA733WE	12.7-gallon auxiliary fuel tank.	WE	05600	Aircraft Modification and Repair 20331 Hesperian Boulevard Hayward, CA 94541
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA1-426	Auxiliary seat in baggage compartment.	NE	84950	William A. Welch Boyce Road, RD-1 Danbury, CT 06810
170, 172, 175 Series; T.C. 799, 3A12, 3A17	SA1-516	Griswold lateralizer and heading lock.	NE	39800	Herbert Baer 80 Federal Street Boston, MA 02109
170, 172, 175 Series; T.C. 799, 3A12, 3A17	SA1-545	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
170, 172, 180, 182 Series; T.C. 799, 3A12, 5A6, 3A13	SA3-75	Grimes rotating anti-collision light D-7080-1-12.	GL	59360	Mid States Aviation Corporation Sky Harbor Airport Northbrook, IL 60062
170, 172, 175, 180 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA3-333	Installation of Doyn fiberglass wheel fairings. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170, 172, 175, 180 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA4-367	Super automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
170, 172, 175, 180 Series; T.C. 799, 3A12, 3A17, 5A6	SA4-620	Baggage door on left side of fuselage.	WE	08262	The Air Oasis 2601 E. Spring Street Long Beach, CA 90801
170, 172, 180, 182; T.C. 799, 3A12, 5A6, 3A13	SA4-662	Camera pod.	WE	52710	Clifton G. McBride 620 Rollingwood Drive Vallejo, CA 94590

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170, 172, 175, 180, 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA4-676	RDF-2 radio direction finder.	WE	70275	Savage Industries, Inc. 3125 N. 29 Avenue Phoenix, AZ 85000
170, 172, 175, 180, 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA5-12	Rear canvas hammock seat.	AL	05958	Aircraft Rebuilders 1803 Lake Otis Road Anchorage, AK 99500
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA81WE	Aileron and rudder trim controls.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA158CE	Cessna wing tips and attached lights 1223000-1 left, 1223000-2 right tips, and 1423006-12 left, 0423006-13 right lights, or an equivalent.	GL	70385	Schott Aviation, Inc. Baldwin Field Quincy, IL 62301
170, 172, 175, 180, 182, 185 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13, 3A24	SA236SW	Cargo door. Reissued 4/6/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA765WE	SP51463-1A speedplates.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
170, 172, 180, 182, 185 Series; T.C. 799, 3A12, 5A6, 3A21, 3A24	SA981WE	Two detachable folding rear	WE	59730	Missionary Aviation Fellowship P.O. Box 32 Fullerton, CA 92632
170, 180 Series; T.C. 799, 5A6	SA1-188	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
170, 180 Series; T.C. 799, 5A6	SA3-468	CF-3000 main wheel skis and AWT 2500A or CT-3000 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170, 180 Series; T.C. 799, 5A6	SA463WE	Jump door 62-500.	NW	72250	Skymotive, Inc. Route 1, Box 32 Snohomish, WA 98290
172 Series; T.C. 3A12	SA1-9	69A115 gyro-stabilizer.	GL	36175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
172 Series; T.C. 3A12	SA1-116	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
172 Series; T.C. 3A12	SA1-438	Lycoming C-360-A1A engine and McCauley 2D36C14/78 KM-4 propeller with Woodward 210105 AA governor.	NE	90160	Albert E. Motack 295 First Avenue Stratford, CT 06497
172 Series; T.C. 3A12	SA3-11	Propeller installations - Two-position controllable, hub 2B-36C7, blades 78K-2 or 78K-4.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45401
172 Series; T.C. 3A12	SA3-82	Retractable lifting handles Model H, P/N 50-9.	GL	87750	Woychik Aircraft Equipment Middleton, WI 53562
172 Series; T.C. 3A12	SA3-89	Equipment shelves and Grimes D-7080 rotating beacon.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
172 Series; T.C. 3A12	SA3-90	Lear ADF loop and housing.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
172 Series; T.C. 3A12	SA3-107	Rudder trim system.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
172 Series; T.C. 3A12	SA3-108	Single axis automatic pilot A-2 or A-3.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
172 Series; T.C. 3A12	SA3-126	Lycoming C-340-A1A engine and Hartzell HC-82XG-1DB/8433-12 propeller. Reissued 3/9/79.	SO	47599	K&AD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172 Series; T.C. 3A12	SA3-179	A3500A or A2500A main skis and NA1200A nose skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-256	Main ski AWB2500A and nose wheel ski AWN1200.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172 Series; T.C. 3A12	SA3-355	C3000 main ski and AWN1200 nose wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-614	Model 3000 main skis and Model 2000 nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-655	Wheel fairings.	RM	55700	Marsh Flying Club, Inc. 812 E. 34th Street Sioux Falls, SD 57101
172 Series; T.C. 3A12	SA3-690	Installation of Doyn swept-tail asembly kit 1400. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172 Series; T.C. 3A12	SA4-40	Automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
172 Series; T.C. 3A12	SA4-196	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
172 Series; T.C. 3A12	SA4-531	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
172 Series; T.C. 3A12	SA4-602	Autopilot. Reissued October 1973.	WE	17492	Brittain Industries, Inc. 12027 S. Prairie Avenue Hawthorne, CA 90250
172 Series; T.C. 3A12	SA4-686	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
172 Series; T.C. 3A12	SA44SO	Cessna L-19 wing conversion.	SO	55600	Marrs Aircraft Avon Park, FL 33825
172 Series; T.C. 3A12	SA64CE	Sky-lite B-100 beacon light.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
172 Series; T.C. 3A12	SA86CE	C-3000 main skis and AWN-1200A nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA94CE	Removal of right cabin door.	GL	72116	Skylane Flying Service, Inc. 2029 Allens Lane Evansville, IN 47708
172 Series; T.C. 3A12	SA117EA	Flow lube oil filter PB 55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
172 Series; T.C. 3A12	SA242EA	40-0040 and 40-0043 supplemental light system.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
172 Series; T.C. 3A12	SA313SO	Federal FS103 autopilot.	SO	00078	A & E Service McCollum Airport Marietta, GA 30060
172 Series; T.C. 3A12	SA414SW	Jump step or mud guard on right landing gear.	SW	73030	Curtis J. Smith, Jr. Route 2, Box 314 Breaux Bridge, LA 70517
172; T.C. 3A12	SA531NW	Installation of windshield. Issued 10/12/77.	NW	71506	Jack Shannon 215 Terminal Building Boeing Field Seattle, WA 98108
172 Series; T.C. 3A12	SA533CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
172; T.C. 3A12	SA584NW	Installation of EDO 698-2125 floats. Issued 4/5/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
172 Series; T.C. 3A12	SA603SW	AK191 Century II autopilot and AK192 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172 Series; T.C. 3A12	SA792WE	Lycoming C-360 Series engines and Sensenich M67EMM propellers.	NW	53510	McKinzie Aircraft Repair, Inc. 1300 N. 26 Street Springfield, OR 97477

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172 Series; T.C. 3A12	SA861WE	Pilot and passenger restraint harness.	WE	62125	Pacific Scientific Company 1346 S. State College Boulevard Anaheim, CA 92803
172 Series; T.C. 3A12	SA1078WE	Franklin 6A-335-B engine with McCAuley 2A31C/848-6 propeller using EDO 89-2000 floats.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172 Series; T.C. 3A12	SA1308WE	Installation of Brittain Model CSA-1 Stability Augmentation System.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
172 Series; T.C. 3A12	SA1468WE	Installation of Brittain Model B2C Autopilot System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172 Series; T.C. 3A12	SA1677SW	Wing leading edge cuff. Issued 6/20/73.	SW	73850	Southern Aircraft Corporation P.O. Box 78 Page, OK 74939
172 Series; T.C. 3A12	SA1806WE	Installation of Brittain Industries B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172 Series; T.C. 3A12	SA3072WE	Installation of emergency warning system. Issued 7/23/75.	WE	77274	Systems Management Associates, Inc. P.O. Box 557 Palo Alto, CA 94302
172, 172A, B, C, D, E, F, G, H; T.C. 3A12	SA3-571	Lycoming C-360-A1D engine, McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1A/7666-2 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172, 172A, B, C, D, E, F; T.C. 3A12	SA3-664	Install Model 113A6, 200CW-6 or 212CW-6 dry vacuum pump and instrument vacuum system. Amended 7/31/79.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
172, 172A thru 172I, K, L, M, N, P; 182, 182A thru 182N, P; T.C. 3A12, 3A13	SA21GL	Installation of Grimes multi-plexed anti-collision light system. Issued 5/9/73.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
172, 172A, B, C, 175, 175A, B, C, 182, 182A thru E; T.C. 3A13, 3A12, 3A17	SA43EA	Installation of Re-Vue Agency "nite-lite" electronic aerial advertising sign. REissued 3/15/71.	RM	67300	Re-Vue Agency, Inc. 616 East 4th Street Pueblo, CO 80204
172, 172A, 172B, 172C, 172D; 180, 180A, 180B, 180C, 180D, 180E, 180F; 182, 182A, 182B, 182C, 182D, 182E; 185, 185A, 185B, 185C, 185D; 210, 210-5, 210A, 210B, 210C; 310C, 310D, 310E, 310F, 310G, 310H; T.C. 3A12, 5A6, 3A13, 3A24, 3A21, 3A10 (310 Series thru 310H Riley conversion per STC SA212SO.)	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
172, 172A, 172B, 172C; T.C. 3A12	SA211GL	Installation of windshield P/N W-2055, W/T-2055 or W/G-2055 on Cessna 172 and 172A, and P/N W-2056, W/T-2056 or W/G-2056 on Cessna 172B and 172C. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
172, 172A, B, C, D, E, F, G, H, I, K, L, M, N; T.C. 3A12	SA296GL	Convert to conventional landing gear. Amended 11/19/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 172A, B, C, D, E, F, G, H. I, K, L, M, N; T.C. 3A12	SA315GL	Installation of Fluidyne skis. Amended 2/7/80.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 172A, B, C, D, E, F, G, H, I, K, L, M; T.C. 3A12	SA326GL	installation of fuel tankcaps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
172, 172D, 172K; T.C. 3A12	SA340NW	Installation of Pee Kay Model 2300 floats. Issued 9/15/76.	NW	70620	Seaplane Flying, Inc. P.O. Box 2164 Vancouver, WA 98661

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172, 172A, B, C, D, E, F, G, H Landplanes, 172D, E, F, G, H Floatplanes (EDO 89-2000 floats only.) T.C. 3A12	SA420CE	Lycoming O-360-A1A or A1D engine, McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1B/7666-2 propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172, A thru I; T.C. 3A12	SA729EA	Replacement of existing wheel/brake assemblies with Goodyear wheel/brake assemblies 9543679/95444295.	GL	39125	Aviation Products Division The Goodyear Tire & Rubber Company 1144 East Market Street Akron, OH 44315
172, 172A thru I, K, L, M, N (Landplanes, normal category only); T.C. 3A12	SA807CE	Install Lycoming 180 h.p. engine and constant speed propeller. Amended 1/31/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
172, S/N 17254693 and on; T.C. 3A12	SA864CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
172, 172A thru 172I, 172K, 172L, 172M (S/N 17260759 thru 17265684); T.C. 3A12	SA902CE	Install STOL kit. Amended 2/26/80.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
172 thru 172N; T.C. 3A12	SA910CE	Install STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Amended May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
172, 172A, B, C, D, E, F, G, H, I, K, M, N; T.C. 3A12	SA1484CE	Installation of flap and aileron seals. Issued 4/18/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
172, 172A thru 172G (landplanes and floatplanes), 172, 172H thru 172L (landplanes only); T.C. 3A12	SA1689WE	Installation of drooped ailerons contoured wing leading edge and wing stall fences. Amended 2/26/71.	NW	68510	Charyl C. Robertson 15209 N.E. 16th Place, Apt. #17 Bellevue, WA 98004
172 thru 172L; T.C. 3A12	SA2002WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
172, 172A thru 172L (normal category); T.C. 3A12	SA2075WE	Installation of Madras Air Service Inc. "Super Tips." Amended 8/16/72.	NW	54000	Madras Air Service, Inc. Route 2, Box 1225 Madras, OR 97741
172, 172A thru 172L, 175, 175A, 180, 180A 180H, 205, 205A; T.C. 3A12, 3A17, 5A6, 3A21	SA2256WE	Installation of leading edge "cuff" on each wing. Amended 4/29/80.	WE	65700	Marshall E. Quackenbush P.O. Box 2421 California City, CA 93505
172, 172A thru 172G; 182A thru 182N, 206, U206, U206B thru U206E; 210 thru T210F; TU206A, D, E; T.C. 3A12, 3A13, 3A21, A4CE	SA2286WE	Installation of wing leading edge cuff. Amended 3/16/72.	RM	09750	Alpine Aircraft Corporation Route 4, Box 173A Greeley, CO 80631
172, 172A, B, C, D, E, F, G, H, I, K, L; T.C. 3A12	SA2852SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
172, 172A, B, C, D, E, F, G, H, I, K, L, M, N (normal and utility categories); T.C. 3A12	SA3105WE	Installation of flapgap fairing. Amended 8/22/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
172, 172A, B, C, D, E, F (T-41), G, H (T-41A), I, K, L, M, N; T.C. 3A12	SA3338WE	Recognition light installation on horizontal stabilizer. Issued 2/4/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
172, 172A, B, C, D, E, F, G, H, I, K, L; T.C. 3A12	SA3788WE	Installation of the "liftrol" wing spoiler system. Issued 1/17/79.	WE	23145	Mr. Prentice Cleaves 4542 Norma Drive San Diego, CA 92115
172, 172A thru H (landplane only, normal category); T.C. 3A12	SA3796WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29075	Del-Air P.O. Box 746 Strathmore, CA 93267

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172, F172; T.C. 3A12	SA3418WE	Installation of SDI Novastar II combined position/anticollision lighting system. Issued 6/22/77.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
172A Seaplane; T.C. 3A12	SA1010GL	Installation of McCauley 1A200/DFA propeller. Issued 6/16/77.	GL	77569	Lee G. Taylor 1115 - 19th Street South St. Cloud, MN 56301
172A, B, C, D, E, F, G, H; T.C. 3A12, 3A17	SA164A	Wet-to-dry vacuum pump conversion kit 380-1. Reissued and amended 8/6/73.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
172A thru 17[illegible]; T.C. 3A12	SA356NW	Installation of Pee Kay Model 2300 seaplane floats. Issued 8/24/76.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
172A - 172K; T.C. 3A12	SA650CE	Installation of Fleet model 2500 floats. Reissued 12/21/71.	EA	79550	Trifield Associates 560 Daytona Drive Fort Erie, Ontario, Canada
172B, 172C, 172D, 172E, 172F, 172G; T.C. 3A12	SA116EA	Installation of Franklin Model 6A-335-B engine with 2A31C41/848-6 propeller and new engine mount and new engine mount and associated components only on landplane models. Amended 9/9/68.	EA	36750	Franklin Engine Company, Inc. Subsidiary of Allied Aero Industries, Inc. Old Liverpool Road Syracuse, NY 13208
172B, 172C; 175 thru 175C; 180 thru 180F; 182 thru 182E; 185, 185A, 185B; 210, 210A, 210B, 210C, 210D, 210E; P206; 310 thru 310E; T.C. 3A12, 3A17, 5A6, 3A13, 3A24, 3A21, A4CE, 3A10	SA232EA	Installation of Tactair omni lock model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair model omni lock model CH-4). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
172B, G, 175A, B, C; T.C. 3A12	SA751EA	Installation of winterization kit. Issued 4/21/69.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
172B thru G; T.C. 3A12	SA1330WE	Installation of Franklin 6A-350-C2 engine and McCauley 2A31C/848-6 propeller. Amended 9/26/68.	WE	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 99663
172B thru H; T.C. 3A12	SA1774WE	Installation of Lycoming O-320-E2D engine and McCauley 1C172/MTM7653 propeller.	WE	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172D, P172D, 182E, F, 185, 185A, 185B, 210, 210A; 210B, 210C, 210-5; T.C. 3A12, 3A17, 3A24, 3A21, 3A13	SA17EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
172D, E, F, G, H, I, K; T.C. 3A12	SA319GL	Bolen wheel extenders on Cessna models modified per STC SA296GL. Issued 6/12/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172D thru 172K; T.C. 3A12	SA365NW	Installation of Pee Kay model 2300 seaplane floats. Approval is intended for installation in listed models with Franklin 6A0360-C2 engine installation IAW Seaplane Flying, Inc., STC SA340NW. Issued 10/5/76.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
172D, 172E (seaplane): T.C. 3A12	SA596WE	Installation of Doyn Aircraft Company kit per STC SA3-571. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172, E thru L; T.C. 3A12	SA1221SW	Mitchell automatic flight system AK312 consisting of Century I with optional omni tracker. Issued 11/18/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172D thru 172I, K, L; T.C. 3A12	SA1645SW	Mitchell automatic flight system AK403, consisting of Century IIB autopilot with optional radio coupler. Issued 4/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172D thru 172K Seaplane Versions; T.C. 3A12	SA1694WE	Installation of Franklin 6A-350-C2 engine, McCauley 2A31C/84S-6 propeller, and Aqua Float Corp., Model 2400, or EDO Corp. Model 248B-2440 floats (Columbia Marine, Inc. Kit #106) for operation on wheels, floats or skis @ 2400 lbs. g.w. (Fluidyne Model 3000 main and 2000 nose skis required for ski operations. Amended and reissued 5/1/70.	EA	36750	Franklin Engine Company, Inc. Sub. Allied Aero Industries, Inc. Old Liverpool Road Syracuse, NY 13208
172D, 172E; T.C. 3A12	SA2268WE	Installation of Brittain Industries B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172D, E, F, G, H; T.C. 3A12	SA2375SW	Install Lycoming O-320-D2G engine rated for 160 h.p. take-off and 150 METO. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76706
172D thru M, 177, 177A, B, 177RG, 182L, M, N, 206, C, U206, U206B, D, E, F, TP206A, B, P206A, D, TU206A, B, C, D, E, F, P206E, TP206E, 210D, E, F, L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE, A20CE, 3A14	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot system. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
172D thru L, 177, A, B, 182L, M, N, 206, U206, B, C, D, E, TU206B, C, D, E, P206A, B, TP206A, B, P206E, TP206E, 210E, D, F, L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE, 3A21	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot system. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
172D, E, F, G, H, I, K, L, M, 177, A, B, 182E thru M, U206C, D, E, F, TU206C, D, E, F, P206E, TP206E, 210, 210D, E, F, L, 210L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE	SA2654WE	Installation of Pathfinder Model P2A( ) autopilot. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Road Torrance, CA 90505
172D, E, F, G, H, I, K, L; T.C. 3A12	SA3046SW-D	Automaticght system AK528 consisting of Century IIB autopilot with optional radio coupler. Issued 3/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172F, G, H, I, K, L; T.C. 3A12	SA1311CE	Chrome plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
172G; T.C. 3A12	SA299GL	Installation of Cessna Nav-O-Matic 200A autopilot. Issued 4/2/79.	GL	37077	Galesburg, AP & I R.R. 2, Airport Galesburg, IL 61401
172H; T.C. 3A12	SA204GL	Installation of Avco Lycoming O-320-E2D engine. Issued 12/16/77.	GL	65326	Professional Aviation, Inc. Porter County Airport 3801 Murvihill Road Valparaiso, IN 46383
172E; T.C. 3A12	SA414NW	Installation of Lycoming O-360-A1F6D engine and McCauley propeller. Issued 3/15/77.	NW	70040	Salem Aviation 2680 Aerial Way S.E. Salem, OR 97302
172I, 172K, 172L; T.C. 3A12	SA87NW	Installation of Lycoming O-360-A1A 180 h.p. engine and Hartzell HC-C2YK-1A/7666A-0 propeller. Amended 12/12/74.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
172I, 172K, 172L, 172M seaplane (normal category only); T.C. 3A12	SA332GL	Installation of Lycoming O-360-A4A engine and McCauley 1A200/DFA propeller. Issued 8/17/79.	GL	77569	Lee G. Taylor 1115 - 19th Street South St. Cloud, MN 56301
172I and 172K landplanes and seaplanes EDO 89-2000 (floats only), 172L, 172M, 172N (landplanes) (12 volt only); T.C. 3A12	SA647CE	Install Lycoming O-360-A1A 180 h.p. engine and constant speed propeller. Reissued 9/5/79.	CE	66195	Barbara or Bob Williams Box 431, 215 North Clark Udall, KS 67146

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172I, K, M, R172K (floatplane configuration); T.C. 3A12, 3A17	SA665CE	Installation of Model 2400 Aqua floats. Amended 7/10/79.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
172I, 172K, 172L, 172M; T.C. 3A12	SA992CE	Installation of 10-inch diameter camera hole per Product Development Group, Inc. Issued February 1974.	CE	36000	Floair, Inc. Mid-Continent Airport Wichita, KS 67209
172I, 172K, 172L, 172M, 172N (Seaplane); T.C. 3A12	SA1000EA	Installation of Pee-Kay Model 2300 or B2300 (TSO-C27-2) seaplane floats. Amended 7/19/78.	EA	29996	Pee Kay Float Division Devore Aviation Corporation 206 Newton Road Plainview, NY 11803
172I, 172K, 172L, 172M (Landplane); T.C. 3A12	SA1225CE	Installation of Lycoming O-320-E2D/STC SE1226CE or O-320-D2G engine and McCauley 1C160/CTM 7557 or 1C160/DTM 7557 propeller. Amended March 1977.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
172I, 172K thru 172M; T.C. 3A12	SA3777WE	Installation of flexible stainless steel oil cooler hoses. Issued 10/31/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
172I, 172K, 172L, 172M, 172N; T.C. 3A12	SA3858WE	Installation of an air/oil separator. Issued 3/2/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036.
F172K; T.C. 3A17	SA1491CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
172K; T.C. 3A17	SA3824SW-D	Mitchell automatic flight system AK730 consisting of Century I autopilot with optional omni tracking system. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172K, 172M (normal category landplane only); T.C. 3A12	SA2575WE	Installation of observer station in rear seat-baggage compartment area, searchlight and dual speakers in bottom of aft fuselage, windows in baggage compartment area (baggage was removed), and a muffler. Amended 1/4/73.	WE	87465	World Associates, Inc. 430 Wilshire Boulevard Suite 204 Santa Monica, CA 90401
172L; T.C. 3A12	SA494SO	Installation of radio equipment rack in instrument panel. Issued 2/18/72.	SO	18400	Burnside-Ott Aviation Training Center 12800 S.W. 137 Avenue Miami, FL 33156
172L, S/N 17259224 thru 17260758; T.C. 3A12	SA965CE	Installation of Model IU328-001 vacuum pump and IU292-003 suction relief valve. Issued November 1973.	CE	43600	EDO-AIRE Wichita Division 1326 S. Walnut Wichita, KS 67213
172M; T.C. 3A12	SA6NE	Installation of Whelen anti-collision strobe light power supplies, Models HS-41 and HD-42 as direct replacements for Models HS and HD installed in accordance with STC SA615EA or STC SA800EA. Issued 3/21/74.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
172M; T.C. 3A12	SA1758SW	Mitchell Automatic Flight System AK467 consisting of Century IIB Autopilot with optional Radio Coupler. Issued 1/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M; T.C. 3A12	SA1799SW	Mitchell Automatic Flight System AK472 consisting of Century I Autopilot with optional omni tracker. Issued 1/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M; T.C. 3A12	SA1671WE	Installation of upper wing surface face stall fences and aileron gap sealing strips. Issued 3/19/73.	WE	39520	Group One 2915 Earhart Apron Torrance, CA 90505
172M, 172N; T.C. 3A12	SA146GL	Installation of EPA portable enviro pod. Amended 12/10/79.	GL	07696	AFAL/RWI Wright-Patterson AFB, OH 45433
172M, 172N; T.C. 3A12	SA360GL	Installation of Tull microwave landing system airborne equipment. Amended 5/12/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
172M, 172N; T.C. 3A12	SA1402CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	66195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172M, 172N; T.C. 3A12	SA3200SW-D	Automaitc flight system AK467 consisting of Century II autopilot with optional radio coupler. Issued 4/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA3201SW-D	Automatic flight sytem AK472 consisting of Century I autopilot with optional omni tracker. Issued 4/7/77.	SW	6000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA4080SW	Stall fences, aileron seals. Issued 1/30/80.	SW	18600	Bush Conversions P.O. Box 61 Guthrie, OK 73044
172M, 180J, 182P, A185F, A188B, 188B, U206F; T.C. 3A12, 3A13, 5A6, 3A24, A4CE, A9CE	SA974EA	Installation of L/R wing tip transparent fairing and sensor mounting bracket. Issued 2/26/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
172N; T.C. 3A12	SA168GL	Install Heath Kit Model 01-1154 aircraft digital clock/timer. Issued 4/28/77.	GL	41610	The Heath Company Hilltop Road Benton Harbor, MI 49022
172N; T.C. 3A12	SA584EA	Installation of Edo 689-2130 seaplane floats. Amended 1/8/80.	EA	32625	Edo-Aire, Seaplane Division 65 Marcus Drive Melville, NY 11746
172N; T.C. 3A12	SA1324CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/7666A-2 propeller. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 North Wichita Station Wichita, KS 67204
172N; T.C. 3A12	SA3301SW-D	Mitchell automatic flight system AK730, consisting of Century I autopilot with optional omni tracking system. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A12	SA3302SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A17	SA3303SW-D	Mitchell automatic flight system AK732 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172RG; T.C. 3A17	SA3363SW	Mitchell automatic flight system AK861 consisting of Century 21 autopilot. Issued 3/14/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P172D; 180D, 180F; 182A, 182A-F; 185, 185A, 185B; T.C. 3A12, 5A6, 3A13, 3A24	SA1686WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	63500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
R172D, R172E, R172F, R172G, R172H, R172J, R172K; T.C. 3A17	SA3487WE	Installation of tail flood light. Issued 10/18/77.	WE	30066	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
R172K; T.C. 3A17	SA460NE	Installation of PeeKay model A2300 or B2360 seaplane floats. Amended 4/20/78.	EA	29998	PeeKay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
R172K Landplane only; T.C. 3A17	SA1437CE	Install derated Continental IO-360-K engine. Issued 10/6/78.	CE	44802	Brad E. Isham 416 West Fourth Street Valley Center, KS 67147
R172K; T.C. 3A17	SA3227SW-D	Mitchell automatic flight system AK699 consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3228SW-D	Mitchell automatic flight system AK698 consisting of Century IIB autopilot with optional radio coupler. Issued 8/2/77.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
R172K; T.C. 3A17	SA3285SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3286SW-D	Mitchell automatic flight system AK732 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R172K; T.C. 3A17	SA4048WE	Installation of Silver Instruments fueltron IG or fueltron digital fuel flow and totalizer system. Issued 10/24/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
R172K, 175, 175A, 175B, 175C; T.C. 3A17	SA383GL	Convert to conventional landing gear. Issued 1/31/80.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 175 Series; T.C. 3A12, 3A17	SA1-219	Gyro-stabilizer 69A122.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
172, 175 Series; T.C. 3A12, 3A17	SA3-576	Speed kit.	CE	65900	R & B Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
172, 175 Series; T.C. 3A12, 3A17	SA4-1601	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175 Series; T.C. 3A12, 3A17	SA109SW	Automatic pilot AK106.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA393WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
172, 175 Series; T.C. 3A #A17	SA411SW	Automatic pitch trim AK 130.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA436EA	New engine, propeller and engine mount. Amended 9/21/67.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
172, 175 Series; T.C. 3A12, 3A17	SA610SW	Lycoming O-320 and O-360 Series engines with Hartzell HC-82XL-7636D-4; HC-C2YK-2R/7666 or HC-92Z-2B/8447-12A propeller.	SW	67650	R.F.B. Company Chandler Field Purcell, OK 73080
172, 175, 180, 182, 310 Series; T.C. 3A12, 3A17, 5A6, 3A13, 3A10	SA4-306	Roto-Nav bracket and Grimes D 7080 anti-collision light on vertical fin.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175, 182 Series; T.C. 3A12, 3A17, 3A13	SA4-893	Installation of wheel fenders on nose gear and main gear. Reissued 2/9/71.	NW	12565	Aurora Air Inc. d/b/a Madras Air Service Madras, OR 97741
172, 175, 180, 182 Series; T.C. 3A12 3A17, 5A6, 3A13	SA10WE	Arens Vernier type throttle control.	WE	82400	Van Nuys Skyways, Inc. 16700 Roscoe Boulevard Van Nuys, CA 91408
172, 175, 180 Series; T.C. 3A12, 3A17, 3A13	SA462WE	Jump door 62-500.	NW	72252	Skymotive, Inc. Route 1, Box 32 Snohomish, WA 98290
172, 175, 182 Series; T.C. 3A12, 3A13, 3A17	SA480CE	Nose and main gear wheel fairings. (Jetstreams) using standing unaltered Cessna landing gear and nose gear for model and year using 500 x 5 nose and 600 x 6 main gear tires.	GL	26750	Creative Designs 1338 Orkla Drive Minneapolis, MN 55427
172, 180; T.C. 3A12, 5A6, 3A13	SA2362WE	Installation of lure toxicant dispenser AEY 70, Model #1. Amended 9/27/73.	NW	03270	U S D A 3706 W. Nob Hill Boulevard Yakima, WA 98902
172, 180, 182 Series; T.C. 3A16, 5A6, 3A13	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Company airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172, 180, 185: T.C. 3A17, 5A6, 3A24	SA271NW	Removal of paper air induction paper. Issued 3/16/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
172, 182 Series; T.C. 3A12, 3A13	SA1-193	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
172, 182 Series; T.C. 3A12, 3A13	SA116EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/63.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
172, 182, 206, 210 Series; T.C. 3A12, 3A13, A4CE, 3A21	SA895WE	Kienzle 65 flight time recorder.	WE	18460	Burrows and Sons 1829 Bridgeport Avenue Claremont, CA 91711
175 Series; T.C. 3A17	SA3-285	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 1405 S. Oliver Wichita, KS 67207
175 Series; T.C. 3A17	SA3-611	Model 3000 main ski and Model 2060 nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
175 Series; T.C. 3A17	SA3-691	Installation of Doyn swept-tail assembly kit 1400. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
175 Series; T.C. 3A17	SA4-547	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
175 Series; T.C. 3A17	SA4-1406	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
175 Series; T.C. 3A17	SA3EA	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
175 Series; T.C. 3A17	SA5WE	Cowl flap.	WE	87473	Thompson International Aviation P.O. Box 68 Hereford, AZ 85615
175 Series; T.C. 3A17	SA11SO	Tank type end plates.	SO	26580	Corben Development Corporation P.O. Box 1603 Venice, FL 33595
175 Series; T.C. 3A17	SA12CE	Removal of right cabin door.	PC	96754	W.E. Avery 116 Kuulei Road Kailua, HI 96754
175 Series; T.C. 3A17	SA20WE	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
175 Series; T.C. 3A17	SA49CE	Conversion of aircraft for parachute jumping operations.	GL	41190	Haven Aviation Memorial Airpark Grand Haven, MI 49417
175 Series; T.C. 3A17	SA72CE	Sky-Lite B-100 beacon light.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
175 Series; T.C. 3A17	SA179NW	Installation of flap gap seals. Issued 1/25/75.	NW	78477	Thunderbird Aero Enterprise Paine Field Everett, WA 98204
175 Series; T.C. 3A17	SA221SO	Conversion of aircraft for parachute jumping and aerial photography.	SO	62490	Edward Richard Parker P.O. Box 578 Andrews Murphy AirPark Andrews, NC 28901
175; T.C. 3A17	SA506NW	Installation of a Franklin 6AS-350-A1 engine. Issued 7/28/78.	NW	70620	Seaplane Flying, Inc. P.O. Box 1264 Vancouver, WA 98661
175, 175A, 175B Landplane; T.C. 3A17	SA424CE	Install Lycoming O-360-A1A or O-360-A1D engine and Hartzell HC-C2YK-1A/7666-2, HC-92ZK-8A/8447-12A or McCauley 2D36C14/78KM-4 propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
175, 175A, B; T.C. 3A17	SA3-674	Lycoming O-360-A1D engine and McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1A/7666-2 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
175, 175A, B, C, P172D; T.C. 3A17	SA1-610	Wet-to-dry vacuum pump conversion kit 300-2. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
175, 175A, B, C; P172D; T.C. 3A17	SA122NW	Installation of Continental O-470 engine, McCauley 2A34C66N/90A-8 propeller, engine mount, cowling, baffles and associated parts. Issued 7/25/74.	NW	47646	Leslie L. Kammeyer Route 2, Box 38 Enumclaw, WA 98022
175, 175A, B, C; T.C. 3A17	SA161EA	Install new engine, propeller and engine mount. Amended 3/17/67.	EA	36750	Franklin Engine Company, Inc. Liverpool Road Syracuse, NY 13208
175, 175A, 175B, 175C; T.C. 3A17	SA212GL	Installation of windshield P/Ns W-2056, W/T-2056 or W/G-2056. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
175, 175A, 175B, 175C; T.C. 3A17	SA1492CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
175, 175A, B, C, P172D, T210F, G, H, J, K, L, M, 310, 310A, B, C, F thru L, N, P, Q, 310J-1, 310K, E310H, E310J, T310P, Q, 320D, E, F, 337, 337A, B, C, D, E, G, M337B, T337B, C, D, E, F, G, 340, 340A, 401, 401A, B, 402, 402A, B, 414, 421, 421A, B; T.C. 3A17, 3A10, 32A25, A6CE, A7CE	SA660WE	Installation of HRD-type fire-extinguishing and detector system. Amended 7/11/77.	WE	43180	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
175, 175A, B, C, P172D; T.C. 3A17	SA327GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francisken 426 Pleasant Drive Roselle, IL 60172
175, 175A, 175B, 175C, P172D (Landplane); T.C. 3A17	SA777CE	Install Lycoming O-360-A1A, 180 hp engine and Hartzell HC-C2YK-1A/ 766A-2 propeller. Amended September 1976.	CE	12775	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 Wichita, KS 67204
175, 175A, 175B, 175C, P172D, R172E, R172F, R172G, R172H, R172J; T.C. 3A17	SA948CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Amended 5/6/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
175A, B, C, P172D (normal category); T.C. 3A17	SA2229WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
175, 175A, B, C; T.C. 3A17	SA2853SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
175, 175A, 175B, 175C (Landplane only, normal category); T.C. 3A17	SA3795WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision, muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29075	Del-Air P.O. Box 746 Strathmore, CA 93267
175, 180, 182; T.C. 3A17, 5A6, 3A13	SA2710WE	Installation of carburetor heat box bearings. Issued 6/15/73.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
177; T.C. A13CE	SA466SO	Removal of right entrance door of cabin for aerial photography. Issued 5/20/71. Modified per STC SA545CE.	SO	25060	Columbus-Muscogee Aviation, Inc. P.O. Box 4608 Columbus, GA 31904
177; T.C. A13CE	SA545CE	Installation of Lycoming O-360-A1A (180 h.p.) engine and new Hartzell propellers. Reissued 9/5/79.	CE	66195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
177; T.C. A13CE	SA602CE	Install shoulder harness.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67202
177; T.C. A13CE	SA906CE	Installation of Lycoming O-360-A1A 180 hp engine and Hartzell HC-C2YK-1B/766A-2 or 7666-2 constant speed propeller. Issued 5/9/73.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 1006 W. 53 North Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	FG	STC Code	STC Holder
177; T.C. A13CE	SA1608WE	Installation of Brittain B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
177; T.C. A13CE	SA3861WE	Installation of an air/oil separator. Issued 3/2/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
177, 177A; T.C. A13CE	SA956CE	Installation of STOL kit (wing leading edge cuffs, drooped tips and vortex generators). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177, 177A, 177B; T.C. A13CE	SA1347CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
177, 177A, B; T.C. A13CE	SA3180SW-D	Automatic flight system AK420 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3181SW-D	Automatic flight system AK421 consisting of Century IIB autopilot with optional radio coupler. Issued 2/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3402WE	Installation of recognition lights on horizontal stabilizer. Issued 5/25/77.	SW	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
152, A152, 177, 177A, B, 177RG, 180 landplane and seaplane, 180A, B, C, D, E, F, G, H, I, J, K seaplane versions, 182, 182A, 210A, B, C, D, E, 310F, G, H, I; T.C. A13CE, 3A19, A20CE, 5A6, 3A21, 3A10	SA71GL	Installation of: 152's P/N BA4106 filter assembly; 177's P/N BA5710 filter assembly; 180's & 182's P/N BA8110 filter assembly; 210's P/N BA2110 filter assembly; 310's P/N BA2310 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140
177, 180, 182, 185, A185, 188, A188, 210-5 (205), 206, U206, TU206, P206, TP206, 207, T207, 210, T210; T.C. A13CE, 5A6, 3A13, 3A24, A9CE, 3A21, A4CE, A16CE	SA728NW	Installation of vented fuel cap. Issued 3/5/79.	NW	82675	Venting Engineering 5420 "A" Street Tacoma, WA 98408
177A; T.C. A13CE	SA601CE	Install Hartzell Model HC-C2YK-1B/7666A-2 constant speed propeller. Amended 2/28/69.	CE	56868	Galen D. Means 1818 North Edgemoor Drive Wichita, KS 67201
177B; T.C. A13CE	SA1060CE	Installation of wing leading edge cuffs and vortex generators on vertical stabilizer. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177B; T.C. A13CE	SA1607SW	Mitchell command/electric trim AK419. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SW1608SW	Mitchell AFS system AK420 consisting of Century I autopilot with optional omni tracker. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SA1609SW	Mitchell AFS system AK421 consisting of Century I autopilot with optional radio coupler. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RB; T.C. A20CE	SA3297SW-D	Mitchell automatic flight system AK759, consisting of Century IIB autopilot with optional radio coupler. Issued 6/30/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA1049CE	Installation of wing leading edge cuffs and vertical stabilizer vortex generators. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177RG; T.C. A20CE	SA1348CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
177RG; T.C. A20CE	SA1479SW	Mitchell automatic flight system AK378 consisting of Century I autopilot with optional omni tracker. Issued 8/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RG; T.C. A20CE	SA1510SW	Mitchell automatic flight system AK379 consisting of Century IIB autopilot with optional radio coupler. Issued 9/6/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3296SW-D	Mitchell automatic flight system AK758 consisting of Century I autopilot with optional omni tracking system. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3298SW-D	Mitchell automatic flight system AK760, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3387WE	Installation of recognition lights on horizontal stabilizer. Issued 4/15/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
177RG; T.C. A20CE	SA3860WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
177RG; T.C. A20CE	SA4024WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 9/10/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
180 Series; T.C. 5A6	SA1-7	Gyro-stabilizer 69A116 on aircraft with serial numbers 32151 and up.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-16	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA1-91	Modification to accommodate Robinson Aviation vertical mount NRIA.	EA	18756	Allen G. Butler 233 Front Street Phillipsburg, PA 16866
180 Series; T.C. 5A6	SA1-106	Gyro-stabilizer 69A107.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-212	Hole cut in lower skin and reinforced.	NE	44030	Inland Fisheries and Game Department Maine
180 Series; T.C. 5A6	SA1-221	Gyro-stabilizer 69A124.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA3-122	Model 3000 main ski and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-160	Conversion of electrical system, engine and aircraft to 24v and installation of additional battery box. (Aircraft with Continental O-470-J engine only).	GL	43342	Harvey M. Hughes Capital City Airport Lansing, MI 48924
180 Series; T.C. 5A6	SA3-161	C-3000 hydraulically-actuated main wheel skis with AWT-2500A or CT-3000 tail wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-292	Hydraulic landing gear actuating system with Edo 289-2700 amphibian gear.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA3-330	C-3000 manually-actuated main skis and AWT-2500A or CT-3000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-340	C-3000 main wheel skis on aircraft with crosswind gear.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-381	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180 Series; T.C. 5A6	SA3-480	Change in airspeed and center of gravity limits with Edo 249-2870 floats and 2850 maximum weight.	AL	08483	Alaska Coastal Airlines 2 Marine Way Juneau, AK 99801
180 Series; T.C. 5A6	SA3-578	Speed kit.	CE	65900	B & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
180 Series; T.C. 5A6	SA3-592	Structural reinforcement wires from center sectional spars to upper engine mount bolts rear of fire wall in windshield.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA3-597	Engine driven hydraulic pump system for Federal C-3000 main ski.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA4-23	Conversion to tricycle gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-56	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-92	Folding type rear seat.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-117	Auxiliary fuel tank in baggage compartment.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-532	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA4-603	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA4-688	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
180 Series; T.C. 5A6	SA41WE	Two fabric rear seat assemblies supported by two steel tube beams.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA42EA	Floor viewing window.	EA	49730	Latrobe Aviation, Inc. P.O. Box 150 Latrobe, PA 15650
180 Series; T.C. 5A6	SA102AL	Shackle release at wing lift strut fittings right and left wings (seaplane only).	AL	03270	U.S. Department of Agriculture Forest Service P.O. Box 1631 Juneau, AK 99801
180 Series; T.C. 5A6	SA110SW	Removal of perforated cones from exhaust muffler.	SW	76850	Sun Oil Company P.O. Box 292 Patterson, LA 70392
180 Series; T.C. 5A6	SA168SW	Conversion of aircraft for parachute jumping operations.	SW	40684	John Hardy, Jr. 1105 St. John's Road El Paso, TX 79910
180 Series; T.C. 5A6	SA173WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401
180 Series; T.C. 5A6	SA200RM	Installation of flight strobe light, Model 4400. Issued 4/22/80.	RM	79760	Tri Star Corporation P.O. Box 1727 730 Independent Avenue Grand Junction, CO 81501
180 Series; T.C. 5A6	SA214SW	Removal of perforated cones on cabin and carburetor heat-sides of muffler assembly with Continental O-470-K engine.	SW	52870	J. Ray McDermott & Company, Inc. Aviation Division P.O. Box 38 Harvey, LA 70058
180 Series; T.C. 5A6	SA221WE	Cleveland 30-21 wheel and brake assemblies 8:00 x 6 tires, Cessna heavy duty axles and 185 hose assemblies.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA289CE	Sky diving door.	GL	78474	Melvin J. Thompson 2408 Illinois Avenue New Holstein, WI 53061

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180 Series; T.C. 5A6	SA312NW	Installation of Edo 628-2960 floats. Amended 6/6/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180 Series; T.C. 5A6	SA527WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
180 Series; T.C. 5A6	SA531AL	Installation of leading edge cuff stall fences, and flap and aileron gap seals. Issued 10/25/74.	AL	27250	Crosswinds, Inc. 8134 Lake Otis Parkway Anchorage, AK 99507
180 Series; T.C. 5A6	SA532CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
180 Series; T.C. 5A6	SA702WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304, and optional Hi-Lo sensitivity adaptor.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
180 Series; T.C. 5A6	SA703WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold and NAV-1 navigation coupler and optional Hi-Lo sensitivity adaptor. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA939WE	Insertion into exhaust collector or exhaust stack of thermocoupled cylinder, a probe to read relative exhaust temperature.	WE	47746	Richard W. Kennedy 3352 Via Bartolo Street San Diego, CA 92101
180 Series; T.C. 5A6	SA983WE	Removal of right-hand door to permit parachute jumping and aerial photography operation (seaplane).	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
180 Series; T.C. 5A6	SA1373WE	Model 3000 floats.	EA	19600	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond, British Columbia, Canada
180 Series; T.C. 5A6	SA2630WE	Installation of SKI Model 10-202186 (Pulstar TM) combined position - anti-collision lighting system. Amended 5/11/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180F, 182, 182A thru 182D; T.C. 5A6, 3A13	SA1-37	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 46226
180, 180A, 180B; T.C. 5A6	SA1-363	Installation of Edo Model 439-2705 amphibious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, (seaplanes); T.C. 5A6	SA1-464	Installation of Edo models 439-2705 amphibious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, E, F, G, H, J, 182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P; T.C. 5A6, 3A16	SA1-611	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
180, 180A, B, C, D, E, (seaplanes); T.C. 5A6	SA1-622	Installation of Edo Model 249A-2870 seaplane floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180 thru 180F; T.C. 5A6	SA24GL	Installation of Model A-3000 wheel replacement skis. Issued 6/4/73.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapid, MN 56470
180, 180A thru 180F, H, J, 185, 185A, B, A185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA62GL	Install wheel and brake conversion kit P/N 199-60. Amended 10/25/74.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011
180, 180A thru 180F, H, J, 185, 185A, B, A185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA63GL	Install wheel and brake conversion kit P/N 199-62. Amended 10/25/74.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011

Rev. 6/30/80

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180, 180A thru 180J; T.C. 5A6	SA73GL	Installation of wheel replacement skis, Model M3000. Amended 7/16/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
180, 180A thru 180F, 182, 182A thru F; T.C. 5A6, 3A13	SA94EA	Installation of Monitair angle of attack system, Model AA-2. Reissued 2/14/72.	GL	69260	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
180, 180A thru 180F; T.C. 5A6	SA104CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180 thru 180H, J, 185 thru 185E, A185E, F; T.C. 3A24, 5A6	SA213AL	Installation of main tail gear skid, or main gear skis with two position wheel fittings. Amended 12/10/75.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180, 180A thru 180H, 185, 185E, A185E, 185F; T.C. 3A24	SA223AL	Installation of Model L3000 wheel replacement skis. Amended April 1974.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180 thru 180K; T.C. 5A6	SA286CE	Installation of Pee Kay Model 3500 or A3500 or B3500 floats, seaplane (TSO-C27-2) on Cessna Models 180 thru 180H airplanes. Amended and reissued 1/19/79.	EA	29558	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
180, 180A thru 180H; T.C. 5A6	SA296AL	Installation of "quick-change" leading edge for horizontal stabilizer. Amended 12/15/71.	AL	05958	Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
180 Series 32015 and up, 180A thru 180K; T.C. 5A6	SA349CE	Installation of Aqua Model 160-85 floats. Amended and reissued 7/12/77.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
180 thru 180E; T.C. 5A6	SA367CE	Installation of floor level seat belt brackets to accommodate four occupants. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
180 thru 180H; 182 thru 182L; 185 thru 185E, A185E; 210 thru 210H, 210-5, -5A, T210F, G, H; 206, 206P, 206TP, 206TU, U206A, U206P, U206TP, U206TU, U206B, U206C; T.C. A4CE	SA453CE	Install Hoskins Twilighter Mk.III supplementary lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180H; T.C. 5A6	SA651AL	Fabricate canvas hammock rear seat and associated parts and install. Issued 8/23/78.	AL	61765	Nugget Aviation Route B, Box 188B Palmer, AK 99645
180, 180A thru 180H; T.C. 5A6	SA658AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180, 180A thru H; T.C. 5A6	SA745CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109
180A thru 180H; T.C. 5A6	SA787EA	Installation of Fleet-Line Floats 2900. Reissued 12/21/71.	EA	64630	Pioneer Airways P.O. Box 357 Atikokan, Ontario, Canada
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA816SW	Hartzell BHC-A2VF-3/V8833 reversible pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
180, S/N 18051824 and on; T.C. 5A6	SA865CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
180, 180A, B, C, D, E, F, G, H, 182, 182A, B, C, D, E, F, G, H, J, K, L, 185, 185A, B, C, D, E, A185E, 210, 210A, B, C, D, E, F, T210F, 206, P206, P206A, B, C, D, U206, U206A, B, C, D, TP206A, B, C, D, TU206A, B, C, D; T.C. 5A6, 3A13, 3A24, 3A21, A4CE	SA901SW	Increased wing leading edge radius. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 96133

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
180, 180A thru 180H, J, 180K, Landplanes, Seaplanes and Amphibians; T.C. 5A6	SA967CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Amended 5/8/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
180, 180A thru 180H; T.C. 5A6	SA1004CE	Install STOL kit. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
180, 180A thru 180H, 180J; T.C. 5A6	SA1157WE	Turbocharged Continental O-470-A, J, K, L, or R engine. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90607
180 thru 180H, 180J Landplane, Floatplane and Amphibian; T.C. 5A6	SA1435WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, except 180J, a flap actuated elevator trip system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA1493CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
180, 180A thru 180H, J; 180H Landplane and Floatplane; T.C. 5A6	SA1705WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 4/20/77.	WE	35780	William E. Flint 8402 North Magnolia, Suite G La Mesa, CA 92041
180, 180A thru H, A185E; T.C. 5A6, 3A24	SA1749WE	Installation of Canadian Aircraft Products, Ltd. Model 3000D floats.	EA	19800	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond, British Columbia, Canada
180 thru 180H; T.C. 5A6	SA2003WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA2854SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
180, 180A, B, C, D, E, F, G, H, J Landplanes Normal Category; T.C. 5A6	SA3313WE	Installation of flap gap closures. Issued 1/5/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA3419WE	Installation of recognition lights on horizontal stabilizer. Issued 6/10/77.	WE	30000	DeVore Aviation 16160 Stagg Street Van Nuys, CA 91406
180A; T.C. 5A6	SA388NW	Installation of McCauley 2A34C201/ 90DA-2 or -8 or McCauley 2A34C203/ 90DCA-2 or -8. Issued 12/23/76.	NW	61660	North Sound Aviation 1340 Peterson Road Burlington, WA 98233
180A thru 180H; T.C. 5A6	SA1943WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
180B; T.C. 3A24	SA155NW	Installation of baggage hatch with cover on EDO 249-3870 and 628-2960 floats. Issued 7/15/75.	NW	11780	Arts Aircraft Parts & Repair 4647 110th N.E. Kirkland, WA 98033
180B, 182 Normal Category; T.C. 3A13	SA3862WE	Shorten vertical leg of the control column 1-1/4 inches to provide clearance for additional avionics equipment in the instrument panel. Issued 2/6/79.	WE	16752	Big Bear Avionics P.O. Box 768 500 Meadow Lane Big Bear City, CA 92314
180F, G, H, J; T.C. 5A6	SA3146SW-D	Mitchell automatic flight system AK602 consisting of Century IIB autopilot with optional radio coupler. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180F, G, H, J; T.C. 5A6	SA3147SW-D	Mitchell automatic flight system AK603 consisting of Century I autopilot with optional omni tracker. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180G, 180H, 180J, 180K; T.C. 5A6	SA649NW	Installation of modification to increase gross weight of floatplane to 3190 lbs. when Edo 628-2960 floats are installed. Issued 8/8/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180G, 180H; T.C. 5A6	SA1349CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
180G, H, J (S/N 18051313 and Subs); T.C. 5A6	SA2979WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
180H; T.C. 5A6	SA569EA	Installation of Tactair T-3 automatic pilot with A-651 horizon gyro and B-650 directional gyro. Issued 7/29/71.	GL	75200	George B. Stillwagon 546 Hathaway Road Dayton, OH 45419
180H, 180J; T.C. 5A6	SA262NW	Installation of 3-bladed McCauley D3A32C90/82NC-2 propeller, Cessna 1250809 spinner. Issued 2/27/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180J; T.C. 5A6	SA556NW	Installation of Continental O-470-Rengine. Issued 1/12/79.	NW	41520	Jim Hayton 1712 A Lakeview Boulevard Mount Vernon, WA 98273
180J; T.C. 5A6	SA3183WE	Installation of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
180J, 180K; T.C. 5A6	SA659AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20511	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180K; T.C. 5A6	SA3282SW-D	Mitchell automatic flight system AK751 consisting of Century I autopilot with optional omni tracker. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K; T.C. 5A6	SA3283SW-D	Mitchell automatic flight system AK752 consisting of Century IIB autopilot with optional radio couplers. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K, T207A, 210N, P210N, 337H, P337H, T337H, 340A, 404, 421C; T.C. 5A6, A6CE, A16CE, 3A21, 3A25, A25CE, A7CE	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 8/7/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
180, 182 Series; T.C. 5A6, 3A13	SA3-123	Heater-muffler assembly 430-10P.	EA	40350	Hanlon & Wilson, Inc. 321-325 Penwood Avenue Pittsburg, PA 15644
180, 182 Series; T.C. 5A6, 3A13	SA4-868	Shackle release at wing lift strut fittings, right and left wings (restricted category only).	RM	03270	U.S. Department of Agriculture Forest Service Missoula, MT 59801
180, 182 Series; T.C. 5A6, 3A13	SA4-1092	Seat belt and seat back to accommodate additional passenger on the rear seat.	RM	39464	Green River Aviation Company P.O. Box 606 Green River, UT 84525
180, 182 Series; T.C. 5A6, 3A13	SA4-1588	Cessna 210 wing tip assemblies.	WE	42130	H & H Flying Service, Inc. P.O. Box 74 Redding, CA 96001
180, 182 Series; T.C. 5A6, 3A13	SA5-19	Hammock seat in place of upholstered rear seat.	AL	08460	Alaska Aeronautical Ind. P.O. Box 4591 Spenard, AK 99503
180, 182 Series; T.C. 5A6, 3A13	SA108CE	Continental O-470 Series engines modified for Bendix RSA5 fuel injection system.	GL	15500	The Bendix Corporation 717 Bendix Drive South Bend, IN 46600
180, 182 Series; T.C. 5A6, 3A13	SA264SO	Cessna 210 wing tips 1223000-1 and -2.	SO	61180	Nashville Flying Service, Inc. Berry Field Nashville, TN 37202
180, 182 Series; T.C. 5A6, 3A13	SA561WE	12.7-gallon auxiliary fuel tank.	WE	05600	Aircraft Modification and Repair 20331 Hesperian Boulevard Hayward, CA 94541
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA1-515	Griswold lateralizer and heading lock.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA102SW	Automatic pilot AK109 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA1-576	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA334SW	Alternator.	SW	09250	Aicor, Inc. 2905 Bandera Road San Antonio, TX 78216
180, 182, 210 Series; T.C. 5A6, 3A13, 3A21	SA96SW	Mixture control indicator kits SE-1.	SW	09250	Aicor, Inc. 2905 Bandera Road San Antonio, TX 78216
180, 185; T.C. 5A6, 3A24	SA361NW	Installation of 8/50 x 6 main wheels with Cleveland brakes and Cleveland wheel assembly. Issued 10/15/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA701WE	Pneumatic pitch assist PC-1 and optical altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180, 185 Series; T.C. 5A6, 3A24	SA2273WE	Installation of Cessna Model 206 rear seats. Amended 10/18/74.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA2767WE	Installation of anti-collision lighting system. Issued 9/28/73.	WE	70500	Scientifico Scientific Components Company 350 Vista Baya Newport Beach, CA 92660
180, 185, 206; T.C. 5A6, 3A24, A4CE	SA754NW	Installation of Fernandez model 8001 and 8001A skis. Issued 4/27/79.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA65CE	Tow hitch assembly.	EA	73550	Soaring Society of America, Inc. Elmira, NY 14902
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA271CE	Tow hitch assembly.	CE	67207	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA1-8	Gyro-stabilizer 69A107.	GL	30175	Globe Industries, Inc. 1784 Stanley Avenue Dayton, OH 45404
182 Series; T.C. 3A13	SA1-36	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA3-18	Yaw axis stabilizer 8000B.	GL	20335	Cedar Engineering, Inc. 5806 W. 36th Street Minneapolis, MN 55401
182 Series; T.C. 3A13	SA3-44	Main ski AWB-2500A and nose wheel ski AWN-1200.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-109	Rudder trim system.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA3-110	Single axis automatic pilot A-2 or A-3.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA3-171	AWB2500A main and AWN1200 nose wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-286	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562
182 Series; T.C. 3A13	SA3-348	C-3000 main ski and AWN-1200 nose wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-452	Model 3000 main skis and Model 2000 nose skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-577	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182 Series; T.C. 3A13	SA4-39	L-2E automatic pilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
182 Series; T.C. 3A13	SA4-132	Automatic rudder control B.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
182 Series; T.C. 3A13	SA4-199	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
182 Series; T.C. 3A13	SA4-533	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA4-548	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA4-668	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
182 Series; T.C. 3A13	SA4-1359	Landing gear modified.	WE	70560	Scott Aero Service, Inc. Municipal Airport Long Beach, CA 90801
182 Series; T.C. 3A13	SA1SO	Wing tips.	SO	75680	Dale Stoughton 6408 S.W. 12 Street Hollywood, FL 33022
182 Series; T.C. 3A13	SA4EA	Single axis autopilot 510A.	EA	05950	Aircraft Radio Corporation P.O. Box 150 Boonton, NJ 07005
182 Series; T.C. 3A13	SA27SW	Automatic pilot AK088, AK088R or AK088E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA40CE	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Montorey, CA 93940
182 Series; T.C. 3A13	SA97WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA101SW	Automatic pilot AK110 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA129EA	HC-A2XF-G/8433-2 or BHC-A2XF-G/8433-2 propeller.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
182 Series; T.C. 3A13	SA183WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	90155	ZIV United Artists, Inc. 7324 Santa Monica Boulevard Hollywood, CA 90028
182 Series; T.C. 3A13	SA361WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA363WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA391CE	210 wing tips.	CE	42030	Carl H. Heims 701 Lou Holland Drive Kansas City, MO 64116
182 Series; T.C. 3A13	SA450SW	Automatic pitch trim system AK134.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA461NW	Installation of Continental IO-520-F engine and McCauley D2A34C58-LNM-90AT-8 propeller. Issued 6/13/77.	NW	85615	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
182 Series; T.C. 3A13	SA489SW	Automatic pilot AK154 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182 Series; T.C. 3A13	SA502WE	Flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA516WE	Original Goodyear wheel and brake assembly replaced with Celveland wheel and brake assembly.	RM	39464	Green River Aviation Company, Inc. P.O. Box 606 Green River, UT 84525
182 Series; T.C. 3A13	SA525WE	B-4 flight control system, including pitch assist PC-1 altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA535CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
182 Series; T.C. 3A13	SA585SO	Fuselage cutout and rerouting of rudder, elevator and trim cables. Amended 1/6/75.	SO	22787	Mr. Joel Clark P.O. Box 317 Bay Minette, AL 36507
182 Series; T.C. 3A13	SA60-SW	AK180 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA617SO	Installation of A or B of Continental O-470-M engines (per STC SE616SO).	SO	61644	North Perry Aviation, Inc. 8000 W. Pembroke Road Hollywood, FL 33023
182 Series; T.C. 3A13	SA624SW	AK197 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA658SW	AK199 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA707SW	AK243 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA709SW	AK229 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA795SW	Mitchell Century II autopilot AK241 with optional automatic aileron stabilizer and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA814WE	Modification to allow installation of camera through 15-inch diameter cutout in bottom of fuselage.	WE	08262	The Air Oasis Company 2361 Airlane San Diego, CA 92101
182; T.C. 3A13	SA1008SO	Installation of an adjustable trim tab on the left aileron. Issued 7/6/78.	SO	03110	Aero-Trim, Inc. 1150 100 Street Bay Harbor, FL 33154
182 Series; T.C. 3A13	SA1383WE	Installation of Brittain Pitch Assist Model PC-1 with Altitude Hold. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1384WE	Installation of Brittain Industries Model CSA-1 Stability Augmentation. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1474WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1671WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1673WE	Installation of Brittain Industries B-5 Flight Control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1706WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1871WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182 Series; T.C. 3A13	SA1872WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA2343WE	Installation of PHI controls Model 312 elapsed time indicator. Issued 4/27/71.	WE	64380	PHI Controls P.O. Box 6307 Torrance, CA 90504
182 Series; T.C. 3A13	SA2719WE	Installation of Symbolic Displays IFO-1A anti-collision lights. Amended 1/23/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
182, 182A thru 182F; T.C. 3A13	SA103CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
182, 182A, B, C, D, E, F, G; T.C. 3A13	SA301GL	Installation of windshield P/Ns W-2071, W/T-2071, W/G-2071, W-2072, W/T-2072, W/G-2072, W-2073, W/T-2073, W/G-2073. Reissued 5/17/79.	GL	39450	Great LAkes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
182, 182A, B; T.C. 3A13	SA355NW	Convert a Cessna 182 aircraft to tailwheel configuration. Amended 1/31/78.	NW	47708	Keefer Aircraft Engineering 11457 Glendale Way S. Seattle, WA 98168
182, 182A thru 182H, 182J thru N, P, Q; T.C. 3A13	SA950CE	STOL kit installation (wing leading leading edge cuffs, drooped tips stall fences and aileron gap seals. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
182, 210, 310, 320 Series; T.C. 3A13 3A21, 3A10, 3A25	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
182 thru 182D; T.C. 3A13	SA874CE	Removal of right front seat, rear seat, and baggage shelf (if installed); installation of floor level seat belt brackets to accommodate four occupants in addition to the pilot. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
182, 182A, 182B, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M; T.C. 3A13	SA935SW	Installation of cabin air conditioning system. Amended 5/7/79.	RM	01950	Aero Engineering 8C Garden Center Broomfield, CO 80020
182, 182A thru 182H, J, K, L, M, N, P, Q (Thru S/N 18266590); T.C. 3A13	SA949CE	STOL kit installation. Amended 2/4/80.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
182, 182A thru H, J thru N, P; T.C. 3A13	SA1032WE	Installation of Rajay turbosupercharged Continental O-470-L or -R engine. Amended 10/1/75.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
182 thru 182P; T.C. 3A13	SA1382WE	Installation of flap actuated aileron droop system for all models; except 182P, recontoured wing leading edge, flap actuated elevator system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
182, 182A thru 182H, 182J thru 182N, 182P, Q, F182, TR182; T.C. 3A13	SA1494CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
182, A, B, C, D; T.C. 3A13	SA1579SW	Mitchell automatic flight system AK414, consisting of Century IIB autopilot with optional radio coupler. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. box 610 Municipal Airport Mineral Wells, TX 76067
182, A, B, C, D; T.C. 3A13	SA1580SW	Mitchell automatic flight system AK411, consisting of Century I autopilot with optional omni tracker. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. box 610 Municipal Airport Mineral Wells, TX 76067
182, 182A thru 182H, 182J thru 182Q; T.C. 3A13	SA1758WE	Installation of 12-gallon auxiliary fuel tank in each wing inboard of tip. Amended 3/15/79.	WE	35746	Flint Aero 8402-G Magnolia Avenue Gillespie Airport Plaza Santee, CA 92071

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182, 182A thru 182H, 182J thru 182N; T.C. 3A13	SA1938WE	Installation of Madras Air Service "Super Tips." Amended 8/4/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
182 thru 182N; T.C. 3A13	SA2004WE	Installation of contoured wing leading edge and following options: stall fences, Robertson wing tips, positive aileron seals. Reissued 8/10/72.	NW	66175	Charyl C. Raisbeck 839 West Perimeter Road Renton Municipal Airport Renton, WA 98055
182, 182A thru 182H, 182J, 182K, 182L, 182M, 182N, 182P; T.C. 3A13	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
182, 182A, B, C, D; T.C. 3A13	SA2888SW	Replacement of control wheel. Issued 12/18/78.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
182, 182A, B, C; T.C. 3A13	SA2890SW	Installation of Continental O-470-R engine. Issued 12/20/78.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3113WE	Installation of flap gap fairing. Amended 8/22/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, 182Q, R182, TR182; T.C. 3A13	SA3349WE	Installation of vertical tail flood lights on horizontal stabilizer. Amended 6/15/79.	WE	30000	DeVore Aviaiton Corporation 16160 Stagg Street Van Nuys, CA 91406
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3652WE	Installation of an air/oil separator. Amended 3/13/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
182A; T.C. 3A13	SA239GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 5/1/78.	GL	62270	Robert L. Pampe 301 Forest Hills Drive Huron, OH 44839
182A thru 182H, 182J thru 182N; T.C. 3A13	SA1006CE	Install landing gear speedpants. Amended 10/9/74.	CE	15230	Bede Aircraft, Inc. Newton Municipal Airport P.O. Box 706 Newton, KS 67114
182A thru P; T.C. 3A13	SA25NW	Installation of insect refrigeration release equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA26NW	Installation of twine dispenser equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA67NW	Installation of twine dispenser equipment. Issued 9/10/73.	NW	80914	U.S. Department of Agriculture 3706 W. Nob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA2371WE	Installation of lure-toxicant distributor. Amended March 1974.	NW	80914	U.S. Department of Agriculture Agricultural Research Service 3706 W. Nob Hill Boulevard Yakima, WA 98902
182A, B, C, D; T.C. 3A13	SA2761SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 4/24/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
182B; T.C. 3A13	SA198GL	Installation of Continental 0-470-R engine in lieu of Continental 0-470-L engine using original installation hardward & components. Issued 10/20/77.	GL	64285	Mark W. Peterson and Assoc. 2627 Springdale Road Duluth, MN 55811
182D thru P; T.C. 3A13	SA27NW	Installation of auxiliary crew seat in rear seat area. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182D; T.C. 3A13	SA1338SW	Cessna NAV-O-MATIC 400 autopilot. Issued 7/9/71.	SW	12630	Autopilots Central, Inc. 3260 North Sheridan Road Tulsa, OK 74131
182E, 182F, 210B, 210C, 210-5; T.C. 3A13, 2A21	SA36EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182E, F, G, H; T.C. 3A13	SA513SW	Heavy duty brake kits. (Also eligible on Wren 460 and 460H aircraft). Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H; T.C. 3A13	SA626SW	Nose gear wheel and tire. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K, L, M; T.C. 3A13	SA692SW	Reverse pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K; T.C. 3A13	SA789SW	Automatic aileron stabilizer AK204.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, F, G, H, J, K, L, M; T.C. 3A13	SA923SW	Droop ailerons. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, K, L, M, 206, P206, U206, 210C, D, E, F, G (205), 210-5 (205A), 210-5A, 337, 337A, B, C, D, T337B, C, D; T.C. 3A13, 3A21, A4CE, A6CE	SA1021SW	Flap on switch on control wheel. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E thru H; T.C. 3A13	SA1211SW	Automatic flight system AK310 consisting of Century I and optional tracking system. Issued 11/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, F, G, H, J, K, L, M, N; T.C. 3A13	SA1594SW	Mitchell automatic flight system AK399 consisting of Century IIB autopilot with optional radio. Issued 1/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, 182F, 182G, 182H, 182J, 182K; T.C. 3A13	SA2546WE	Installation of Pathfinder Engineering Corp. Model P1-( ) autopilot. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA2908SW	Exhaust extension. Issued 2/2/79.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182E, F, G, H, J, K, L, M, N, P (S/N 18253599 and Subs); T.C. 3A13	SA2980WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2502 E. Wardlow Road Long Beach, CA 90807
182E thru 182H, 182H thru 182Q, NOTE; T.C. 3A13	SA3608WE	Installation of replacement flexible fuel cell in wings. Issued 3/15/78. NOTE: 182E S/N 18253599 thru 182H18256143 except aircraft modified by Cessna Service Kit SK182-41; 182H S/N 18256144 and subsequent thru 182Q S/Ns. Also 182E thru 182H aircraft which have been modified by Cessna SK182-41.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
182F; T.C. 3A13	SA198EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
182F; T.C. 3A13	SA933EA	Installation of wing struts modified to include Wings With Springs Model 300 hydraulic-pneumatic shock absorbers and associated airframe modifications. Amended 2/13/76.	EA	86500	Wings With Springs, Inc. Box 495, R.D. 3 Latrobe, PA 15650
182F, G; T.C. 3A13	SA403SW	Full span double slotted flaps, drooped wing leading edge, aileron actuated drag plates, Robertson U.I.S. nose control system, increased elevator aerodynamic balance, and relocated pilot head. Reissued 4/22/80.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182H, J, K, L, M; T.C. 3A13	SA485SW	STOL operations modification. (Also eligible on Wren 460H aircraft.) Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182H, J, K, L, M, N; T.C. 3A13	SA1350CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
182H, 182J, 182K, 182L, 182M (Landplane only, normal category); T.C. 3A13	SA2662WE	Removal of nose control surface (which was installed as part of Wren 460 modification in accordance with STC SA485SW). Issued 3/9/73.	WE	17125	Breuner STOL Company 50 Melody Lane Orinda, CA 94563
182H, J, K, L, M, N, P206A, P206B, P206C, P206D, P206E (landplane only); T.C. 3A13, A4CE	SA2799WE	Installation of camera pod attached to bottom of fuselage by straps. Issued 1/8/74.	WE	15190	Bechtel Corporation 50 Beale Street San Francisco, CA 94119
182K, L, M, N, P; 210G, H, J, K, L, T210G, H, J, K, L; T.C. 3A13, 3A21	SA6GL	Installation of Grimes strobe anti-collision lights. Issued 1/5/73.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
182K, L, M, N, P, Q; T.C. 3A13	SA2748SW	Streamlined nose gear kit. Issued 4/14/78.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182M Normal Category; T.C. 3A13	SA2723WE	Installation of external cargo pack (ski carrier). Issued 7/11/73.	WE	87114	Wirly Sales 7610 Owens Street Tujunga, CA 91042
182N, 182P; T.C. 3A13	SA2177WE	Installation of Brittain Ind. B-7, NAV-2B, B2C or B8S flight control system. Reissued 9/19/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182N (S/N 18260446 and up), 182P, 182Q; T.C. 3A13	SA1406CE	Install 25-gallon auxiliary fuel tank in fuselage baggage compartment. Amended 5/12/78.	CE	45250	Javelin Aircraft Company, Inc. 1978 Easy Street Wichita, KS 67230
182P; T.C. 3A13	SA1554SW	Mitchell automatic flight system AK396 consisting of Century I with optional omni tracker. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1555SW	Mitchell automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1556SW	Mitchell command/electric trim system. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA3063WE	Installation of Pathfinder autopilot system and/or electric pitch trim system. Amended 12/3/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182P; T.C. 3A13	SA3072SW-D	Mitchell automatic flight system AK540 consisting of Century III autopilot with optional radio and slope couplers. Issued 9/10/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA3190SW-D	Mitchell command electric trim AK410 Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, 182Q; T.C. 3A13	SA1296CE	Installation of King KFC-200 2-axis, flight control system with KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KX-292 mode controller. Amended 9/22/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
182P, 182Q; T.C. 3A13	SA1403CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
182P, 182Q; T.C. 3A13	SA3188SW-D	Install automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182P, 182Q; T.C. 3A13	SA3189SW-D	Automatic flight system AK396 consisting of Century 1 autopilot with optional omni tracker system. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, Q; T.C. 3A13	SA4079SW	Stall fences, aileron seals. Issued 1/30/80.	SW	18600	Bush Conversions P.O. Box 61 Guthrie, OK 73044
182Q; T.C. 3A13	SA255GL	Install a Pathfinder P2A autopilot. Issued 7/19/78.	GL	04543	Air Central Enterprises 44050 Russia Road Elyria, OH 44035
182Q; T.C. 3A13	SA3279SW-D	Mitchell automatic flight system AK744 consisting of Century I autopilot with optional omni tracker. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3280SW-D	Mitchell automatic flight system AK745 consisting of Century IIB autopilot with optional radio coupler. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3281SW-D	Mitchell automatic flight system AK 746 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3763WE	Installation of Pathfinder autopilot systems. Issued 10/27/78.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
R182; T.C. 3A13	SA144RM	Installation of Pathfinder P2A single-axis autopilot. Issued 6/29/78.	RM	02454	Aeronics Jefferson County Airport Hangar B4A Broomfield, CO 80020
R182; T.C. 3A13	SA1433CE	Installation of KFC 200 flight control system with or without flight director. Amended 10/27/79.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
R182; T.C. 3A13	SA3273SW-D	Mitchell automatic flight system AK741 consisting of Century IIB autopilot with optional radio coupler. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3274SW-D	Mitchell automatic flight system AK742 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3275SW-D	Mitchell automatic flight system AK743 consisting of Century IV autopilot with optional remote annunciator. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A12	SA3316SW-D	Installation of Mitchell command electric trim system AK778. Issued 11/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3834WE	Installation of Pathfinder autopilot systems. Issued 2/13/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
185 Series; T.C. 3A24	SA4-1617	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
185 Series; T.C. 3A24	SA33SO	Conversion of aircraft for parachute jumping operations.	SO	34288	Falling Angels, Inc. 339 E. New York Avenue De Land, FL 32720
185 Series; T.C. 3A24	SA84CE	25-gallon auxiliary fuel system in cargo pack. (Aircraft equipped with 62-gallon usable main fuel tanks only.)	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
185 Series; T.C. 3A24	SA108SW	Edo 289-2700 and 439-2705 amphibious floats.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
185 Series; T.C. 3A24	SA111CE	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
185 Series; T.C. 3A24	SA147SW	Edo 429-2705 or 289-2700 amphibious floats.	SW	27270	Cruse Aviation, Inc. 8501 Telephone Road Houston, TX 77002
185 Series; T.C. 3A24	SA172WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401
185 Series; T.C. 3A24	SA202WE	Cessna 210 wing tip assemblies 1223000-1, -2, and wing tip mounted navigation lights.	NW	49270	Lake Aero Service 9306 Veterans Drive, SW Tacoma, WA 98402
185 Series; T.C. 3A24	SA215SW	L-2 autopilot.	SW	03120	Aerotron Radio Company P.O. Box 8396 Tulsa, OK 74101
185 Series; T.C. 3A24	SA213WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
185 Series; T.C. 3A24	SA261NW	Installation of automatic flagman. Issued 2/5/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362
185 Series; T.C. 3A24	SA343EA	Holes in floor of aircraft for use of viewfinder and camera.	NE	50780	Herbert P. Lindblad Mousam Road Springfield, ME 04487
185 Series; T.C. 3A24	SA417WE	Torsc tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
185 Series; T.C. 3A24	SA1081WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
185 Series; T.C. 3A24	SA1568WE	Installation of emergency fuel system.	WE	59730	Missionary Aviation Fellowship P.O. Box 2828 Fullerton, CA 92632
185 Landplane; T.C. 3A24	SA943WE	Installation of Continental TSIO-470-B engine.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
185, 185A, B, C, D, 210, 210A, B, C, 210-5, 210-5A, 210E, F, G, H, J, K, L; T.C. 3A21, 3A24	SA1-629	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
185, A, B, C, D, E, A185E; T.C. 3A24	SA3-717	Ski installation: main gear Model 4000; tail gear Model 1500, CT-3600, CT-3200, CT-3400. Amended 2/19/76.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
185, 185A, 185B; T.C. 3A24	SA123CE	High intensity wing tip lights Model B and tail light Model C with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
185, 185A, B, C, D, E, A185E; T.C. 3A24 (Floatplane configuration)	SA169CE	Install Wipline Model 3700 or 3900 twin floats. Amended 7/22/76.	GL	86750	Wipline, Inc. South End Doane Train Inver Grove Heights, MN 55075
185 - 185D;	SA324AL	Installation of Continental IO-520-D engine. Revised 6/16/69.	AL	08472	Alaska Air Guides, Inc. P.O. Box 4165 Anchorage, AK 99503
185 thru 185E, A185E, A185F; T.C. 3A24	SA328CE	Install Model 180-85 aqua floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA445CE	Installation of Pee Kay 3500, A3500, B3500, C3500, 2950 or 3000 seaplane floats (TSC-C27-2). Amended and reissued 1/19/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
185, 185A, 185B, 185C, 185D, 185E, A185E; T.C. 3A24	SA480AL	Installation of EDO-AIRE Mitchell Century I autopilot and omni tracker. Issued 5/25/72.	AL	03124	Aerotronics of Alaska, Inc. Box 4-1582 Anchorage, AK 99509
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA525NW	Installation of Continental IO-520-D engine and McCauley D2A34C58/90AT-4 propeller. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA526NW	Installation of Edo Model 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA587NW	Installation of Hartzell HC-C3YF-1RF/F9587C-15 propeller on Continental IO-520-D engine. Issued 5/5/78.	AL	08492	Alaska Propeller Specialists, Inc. 5251 Lakeshore Drive Anchorage, AK 99503
185, 185A, 185B, 185C, 185D, 185E; T.C. 3A24	SA631AL	Install leading edge cuff. Issued 4/28/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA746CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109
185, S/N 185-1201 and on; T.C. 3A24	SA866CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA954SW	Installation of droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
185, 185A thru 185E, A185E and F Landplanes, Seaplanes and Amphibians; T.C. 3A24	SA968CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
185, 185A, C, D, E, A185E; T.C. 3A24	SA1351CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
185, 185A thru 185E, A185E, A185F Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA1441WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge (except A185F) stall fence, flap actuated elevator trim system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA1495CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
185, 185A thru 185E; T.C. 3A24	SA2108WE	Installation of Madras Air Service wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
185, 185A thru 185E, A185E Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA2189WE	Installation of recontoured wing leading edge, stall fences, wing tips, and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, 185B, 185C, and 185D, 185E, A185E, A185F Landplane; T.C. 3A24	SA2529WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 9/20/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite G Santee, CA 92071
185 Series, 185A, B, C, D; T.C. 3A24	SA2802SW	Install leading edge cuffs, stall fences, aileron seals, and wing tips. Issued 6/19/78.	SW	18600	Bob Williams d/b/a Bush Conversions Box 61 Guthrie, OK 73044
185, A, B, C, D, E, A185E; T.C. 3A24	SA3084SW-D	Automatic flight system AK554, consisting of Century I autopilot with optional omni tracker. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
185, A, B, C, D, E, A185E; T.C. 3A24	SA3085SW-D	Automatic flight system AK555, consisting of Century IIB autopilot with optional radio coupler. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
185, 185A, B, C, D, E, A185E, F; T.C. 3A24	SA3383WE	Installation of recognition lights on horizontal stabilizer. Issued 4/19/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
185A, A185F (Seaplane Configuration only); T.C. 3A24	SA7GL	Installation of Model 3730 amphibious floats, Model 3700, 3800 or 3900 seaplane floats. Amended 7/20/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
185A, 185E, A185E, A185F, 206, P206, P206A, U206A, TP206A, TU206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E, U206F, TU206F, U206G; T.C. 3A24, A4CE	SA522NW	Installation of float hatch kits on Edo 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185B; T.C. 3A24	SA199EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal building Lunken Airport Cincinnati, OH 45226
185E, A185, A185F; T.C. 3A24	SA240NW	Installation of McCauley D3A32C90/ propeller, Cessna spinner, governor, and associated systems on Continental IO-520-D engine. Amended 1/16/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
A185E; T.C. 3A24	SA507NW	Installation of Edo floats and Cessna cargo pack, Issued 8/31/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
A185E; T.C. 3A24	SA587NW	Installation of Hartzell HC-C3YF-1RF/F9587C-15 propeller on Continental IO-520-D engine. Issued 5/5/78.	NW	08492	Alaska Propeller Specialists, Inc. 5251 Lake Shore Drive Anchorage, AK 99503
A185E; T.C. 3A24	SA592AL	Install leading edge cuff, stall fences, and flap and aileron gap seals. Issued 7/19/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
A185E; T.C. 3A24	SA930SW	Droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
A185E; T.C. 3A24	SA1148SW	Aileron drooping device. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
A185E; T.C. 3A24	SA1990WE	Installation of Tritan Amphibious float model TA 3500. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
A185E (Floatplane Amphibian configuration only); T.C. 3A24	SA805CE	Installation of Wipline Model 3730 amphibious twin floats. Issued and amended 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
A185E, A185F; T.C. 3A24	SA501NW	Installation of McCauley D3A32C90/82NC-2 on Lycoming IO-520-D engine. Issued 8/29/77.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
A185E, A185F; T.C. 3A24	SA832EA	Installation of Edo Model 582-3430 seaplane floats. Amended 1/15/80.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185E, A185F; T.C. 3A24	SA877EA	Installation of Pee Kay Model 3500A (TSO C-27-2) amphibious floats. Amended 6/7/75.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
A185E, A185F (Floatplane and Amphibious Configurations; T.C. 3A24	SA985EA	Installation of McCauley Propeller Model D3A32C90/82NC-2. Amended 2/25/75.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
A185E, A185F; T.C. 3A24	SA2875WE	Installation of modified brake system. Issued 4/30/74.	WE	59730	Mission Aviation Fellowship P.O. Box 142 Ramona, CA 92065
A185F; T.C. 3A24	SA17NE	Installation of EDO Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Reissued and amended 9/5/79.	NE	32625	EDO-AIRE Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185F; T.C. 3A24	SA51NW	Installation of Cessna cargo pack. Issued 7/31/73.	NW	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A185F; T.C. 3A24	SA164NW	Installation of EDO-628-2960 seaplane floats with Cessna cargo pack kit No. AK-185-23D, cargo pack fairing, rudder non-linear centering spring and ventral fin. Issued 2/28/75.	WE	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA420NW	Installation of cargo pac and McCauley 3-bladed propeller. Issued 3/17/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA558NW	Installation of Edo Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Amended 1/15/80.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185F; T.C. 3A24	SA596NW	Install Cessna A185E wing panels. Issued 4/27/78.	NW	08215	Airmetal Northwest, Inc. P.O. Box 387 Arlington, WA 98223
A185F; T.C. 3A24	SA634AL	Install leading edge cuff. Issued 5/31/78.	AK	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
A185F; T.C. 3A24	SA780NW	Installation of Edo 628-2960 floats on a A185F equipped with Cessna cargo pod (P/N 0700062-43) must include Cessna ventral fin (P/N 0712764-2) and linear rudder centering system. Issued 6/1/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
A185F; T.C. 3A24	SA3251SW-D	Mitchell automatic flight system AK703 consisting of Century IV autopilot or AK703FD consisting of Century IV flight director with optional remote annuciator. Issued 11/18/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
188, A188; T.C. A9CE	SA709CE	Install wing fence.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
188, A188; T.C. A9CE	SA1126SW	Alternate air filter.	SW	43500	Hutchinson Aircraft Box 1070 Borger, TX 79006
188, A188; T.C. A9CE	SA1352CE	Chrome-plated brake disc installation. Issued 3/2/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
188, A188; T.C. A9CE	SA1919WE	Installation of Madras Air Service wing tips. Amended 8/16/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
188, 188A, A188, A188A; T.C. A9CE	SA142NW	Normal and restricted category installation of recontoured wing leading edge and stall fences. Options: wing strut fillet or wing tips. Issued 12/11/74.	NW	68500	Robertson Aircraft Corporation 839 Perimeter Road Renton, WA 98055
188, 188A, A188, A188A, T.C. A9CE	SA1007CE	Installation of full spar leading edge cuffs and drooped wing tips. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
188, 188A, A188, A188A; T.C. A9CE	SA1355SW	Wing leading edge cuff to increase leading edge radius. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
188, 188A, A188, A188A; T.C. A9CE	SA1373SW	Fairing on wing strut intersection. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
188, 188A, A188, A188A; T.C. A9CE	SA1745WE	Installation of Automatic Flagman (Marker Dispensing Unit). Amended 8/10/73.	NW	03500	Air-Ag, Inc. Route 4, City County Airport Walla Walla, WA 99362
188, 188A, A188, A188A; T.C. A9CE	SA2340WE	Installation of recontoured wing leading edge, drooped ailerons, stall fences, new wing strut fillet; optional flap actuated elevator trim system, Robertson wing tips 10-105, Madras Air Services super tips. Issued 4/13/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
188, 188A, 188B, A188, A188A, A188B; T.C. A9CE	SA1179CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508, Renner Field Goodland, KS 67735

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
188, 188A, 188B, A188, A188A, A188B; T.C. A9CE	SA4099WE	Installation of two Conrel dispensing pads, drawing No. 21940. Issued 3/17/80.	WE	25830	Conrel-An Albany Int'l. Co. P.O. Box 537 Buckeye, AZ 85326
A188; T.C. A9CE	SA543SO	Extruded aluminum leading edge cuff. Issued 8/2/73.	SO	79820	Tunico P.O. Box 356 Tunica, MS 38676
A188, A188A, A188B; T.C. A9CE	SA99RM	Installation of freon type air conditioning system. Issued 7/12/77.	RM	32300	Dale Edlund Billings Aircraft, Logan Field Billings, MT 59102
A188, A188A, A188B; T.C. A9CE	SA900SO	Installation of cabin air conditioning. Issued 5/31/76.	SO	69228	Mr. Dwight Kerry Rudder Route 1, P.O. Box 11A Canton, MS 39046
A188B; T.C. A9CE	SA40RM	Installation of Freon air-conditioning system. Amended 3/22/76.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
A188B; T.C. A9CE	SA672NW	Installation of Hartzell HC-C3YF-1RF/F9587C-17B propeller on Continental IO-520-D engine. Issued 9/29/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
190 Series; T.C. 790	SA3-227	ARC L-11 loop and housing, ARC ADF receiver R-30A and power unit, and ARC control head.	CE	44340	Interstate Airmotive, Inc. Lambert Field St. Louis, MO 63155
190 Series; T.C. 790	SA4-1075	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
190 Series; T.C. 790	SA4-1275	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
190 Series; T.C. 790	SA42WE	Eclipse Aviation generator 790-1B.	WE	34292	Robert F. Falion 1201 Deboran Drive Tustin, CA 92680
190 Series; T.C. 790	SA220WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	69245	Rusty's Flying Service 1041 W. Alondra Compton, CA 90220
190 Series; T.C. 790	SA354SW	Cargo conversion.	SW	33994	Executive Airlines, Inc. 206 E. Terminal Drive International Airport San Antonio, TX 78205
190, 195; T.C. 790	SA573CE	Installation of block swivel action of crosswind gear.	CE	47250	Ray M. Jourdan 11001 E. 59th Street Raytown, MO 64133
190, 195; T.C. 790	SA1492WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
190, 195, 195B; T.C. A-790	SA54GL	Install wheel and brake conversion kit P/N 199-61. Issued 6/10/74.	GL	23260	Cleveland Wheel and Brakes Div. of VanSickle Industries 1160 Avon Center Road Avon, OH 44011
190, 195, 195B; T.C. A-790	SA120NW	Installation of Hartzell HC-B3P20-4/P10160-12E propeller on Jacobs-Page R-755S engine. Amended 4/20/77.	NW	87068	William Wiprud 6443 Southwest Beaverton Hillsdale Airport Portland, OR 97221
190, 195, 195A, B; T.C. A-790	SA1284CE	Replacement axles. Issued 10/13/76.	CE	19020	Butterfly Aviation, Inc. P.O. Box 736 Renner Field Goodland, KS 67735
190, 195, 195A, B; T.C. A-790	SA2388WE	Removal of left-hand exit. Issued 7/26/71.	WE	67014	Everett A. Redding 18250 Grand Avenue Elsinore, CA 92330
195; T.C. A-790	SA199GL	Installation of oil filter between engine oil gallery and propeller governor/nose case tappet rocker arm supply. Issued 11/4/77.	GL	60093	Richard C. Moen 536 South 1st Street Dundee, IL 60118
195; T.C. 790	SA1268SW	Jacobs-Page R-755-S engine. Reissued 5/24/77.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
205, 205A; T.C. 3A21	SA3836WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Voulevard Los Angeles, CA 90064

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206 Series; T.C. A4CE	SA65NW	Installation of fiberglass wing tips. Issued 9/20/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
206 Series; T.C. A4CE	SA635SW	McCauley DA3A32C90/82NC-2 propeller.	SW	84395	L.L. Walker Company P.O. Box 5158 Houston, TX 77012
206 Series; T.C. A4CE	SA669SW	AK218 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206; T.C. A4CE	SA685AL	Installation of Hartzell and blade propeller. Issued 5/16/80.	AL	08492	Alaska Propeller Specialists 5251 Lakeshore Drive Anchorage, AK 99503
206 Series; T.C. A4CE	SA727SW	AK231 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206 Series; T.C. A4CE	SA1255WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	73760	Sonora Aviation, Inc. P.O. Box 1027 Carson City, NV 89701
206 Series; T.C. A4CE	SA1893WE	Installation of Brittain Flight Control Systems Model B-5, NAV-2B or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
206 Series; T.C. A4CE	SA3837WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
206, P206, U206, P206A, U206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA332CE	Installation of Wipline Models 3700 and 3900 twin floats on Cessna Floatplane configuration. (Floatplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
206, P206, U206; T.C. A4CE	SA392GL	Installation of Great Lakes Aero Products windsheild P/Ns W-2065, W/T-2065 and W/G-2065. Issued 3/10/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
*206, *P206, *P206A, *U206, *U206A, U206B, C, D, E, F, G (S/N U20603522 thru U20604649, U20604659 and up) (1979 models), TP206A, TU206A, B, C, D, E, F (S/N U20601701 thru U20602199); T.C. A4CE *These models are approved with a gross weight of 3500 lbs., all others approved with 3600 lbs. gross weight.	SA439NW	Installation of Edo-696M-3500 and/or 696-3500 amphibious floats. Reissued and amended 10/22/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
206, P206, U206, U206F, Floatplane configuration; T.C. A4CE	SA474CE	Install Aqua Model 3526 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
206, P206, P206A, TP206A, U206, U206A, thru G, TU206A thru TU206G; T.C. A4CE	SA512CE	Installation of Pee Kay Model 3500 or A3500 or B3500 seaplane floats. Amended and reissued 1/29/79.	EA	29598	P K Floats DeVore Aviation Corporation 206 Newton Road Plainview, NY 11803
206, P206, U206, P206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206A, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA666CE	Install Wipline Model 3730 twin floats (amphibious). (Seaplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
206, P206, P206A, TP206A, U206, U206A thru G, TU206A thru G; T.C. A4CE	SA851EA	Installation of Pee Kay Model 3500A amphibious floats (TSO C-27). Amended and reissued 1/29/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newton Road Plainview, NY 11803
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA893CE	Camera hole cut-out in lower fuselage structure. Reissued 2/17/76.	GL	59452	Mr. Wayne B. Hillard 4144 South Highway 101 Minneapolis, MN 55345

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206, P206, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA908CE	Install STOL kit. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F landplanes only; T.C. A4CE	SA990CE	Install STOL kit (wing leading edge cuffs, drooped tips, and stall fences). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, TU206A, B, C, D, E, F; T.C. A4CE	SA1069CE	Enlargement of factory installed camera hole and installation of a view finder hole. Issued November 1974.	CE	36000	FloAir, Inc. Hangar #17 Mid-Continent Airport Wichita, KS 67209
206, U206A, B, D, E, TU206A, B, D, E, P206A, B, C, D, E; T.C. A4CE	SA1353CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F; T.C. A4CE	SA1513WE	Installation of flap actuated aileron droop system, recontoured wing leading edge (except TU206F and U206F), and flap actuated elevator trim system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, 210-5, 210-5A; T.C. A4CE, 3A21	SA1870WE	Installation of Brittain Model NAV-2B Flight Control. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
206, U206, P206 Landplane and Floatplane, P206B, TP206B, P206C, TP206C, P206D, TP206D, P206E, TP206E Landplane and Skiplane, P206A Landplane, U206A, U206B, U206C, U206D, TU206A, TU206B, TU206C, TU206D, TU206E Skiplane; T.C. A4CE	SA2326WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, P206A, B, C, D, E, F, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G; T.C. A4CE	SA2479WE	Installation of larger fuel containing wing tips. Amended 7/25/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite 3 Santee, CA 92071
206, P206, 206-A, -B, -C, -D, -E, TP206A, B, C, D, E, U206, A, B. C, D, E, F; T.C. A4CE	SA2855SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G; T.C. A4CE	SA3348WE	Recognition light installation on horizontal stabilizer. Issued 3/7/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F; T.C. A4CE	SA3462WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 8/19/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
206, P206, A, B, C, D, E, TP206, A, B, C, D, E, U206, A, B, C, D, E, F, G, TU206A, B, C, D, E, F, G; T.C. A4CE	SA3739WE	Installation of Silver Instruments' fueltron IG or fueltron IP digital fuel flow and totalizer system. Amended 4/2/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206 (S/N 206-0001 thru 206-0137 except 206-0094, S/N 206-0094, 206-0138 thru 206-0275), U206 (S/N U206-04074), P206 (S/N P206-0001 thru P206-00647); T.C. A4CE	SA3825WE	Installation of replacement flexible fuel cell in wings. Issued 8/2/79.	WE	08357	Air-Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
P206A/B/C/D/E, U206A/B/C/D/E/F/G; T.C. A4CE	SA3686WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
P206C, P206D, U206C, U206D, U206E; T.C. A4CE	SA1431SW	Mitchell automatic flight system AK368 consisting of Century III autopilot with optional automatic electric pitch trim, radio, and glide slope couplers. Issued 2/25/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206; T.C. A4CE	SA652NW	Installation of McCauley D3A32C90/82NC-2 propeller on Continental IO-520-A engine. Issued 8/15/78.	NW	64750	Robert Plummer Bob's Aircraft Maintenance Challis, ID 83226
U206, TU206; T.C. A4CE	SA1037CE	Installation of 26 gallon auxiliary fuel tank in baggage compartment. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA2782SW	Installation of Continental TSIO-520-M. Issued 5/30/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F, TU206G; T.C. A4CE	SA3856WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1430SW	Mitchell automatic flight system AK350, consisting of Century I autopilot with omni tracker. Issued 2/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1449SW	Mitchell automatic flight system AK369, consisting of Century II autopilot with optional radio coupler. Issued 3/22/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Minerals Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1572SW	Mitchell automatic flight system AK405 consisting of Century IIB autopilot with optional radio coupler. Issued 12/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1846SW	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/ electronic pitch trim, radio coupler, and glide slope coupler. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1887SW	Automatic flight system AK470, consisting of Century IIB autopilot with optional radio coupler. Issued 6/17/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA3097SW-D	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/ electronic pitch trim, radio coupler and glide slope coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, -D, -E, -F, TU206C, -D, -E, -F, P206C, -D, -E, TP206C, -D, -E; T.C. A4CE	SA2164WE	Installation of Edo Model FD-3500A (TSO C-27-2) amphibious floats. Reissued 5/24/76.	NE	23370	T.H. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
U206F, TU206F, U206G, TU206G, T.C. A4CE	SA3GL	Installation of Bendix FCS-810 autopilot and flight director. Amended 2/13/78.	GL	66080	Russell Hammer Radio Ranch, Inc. Radio Ranch Airport Polo, IL 61064
U206F, G, TU206F, G (Seaplane configuration only); T.C. A4CE	SA18GL	Installation of Wipline Model 3730 floats. Amended 6/12/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
U206F, TU206F; T.C. A4CE	SA1845SW	Mitchell automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3177SW-D	Install Mitchell automatic flight system AK470 consisting of Century IIB with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3178SW-D	Install automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, U206G, TU206F, TU206G; T.C. A4CE	SA3262SW-D	Mitchell automatic flight system AK715 consisting of Century III autopilot with optional radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3263SW-D	Mitchell automatic flight system AK714 consisting of Century IIB autopilot with optional radio couplers. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3264SW-D	Mitchell automatic flight system AK713 consisting of Century I autopilot with optional omni tracker. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3265SW-D	Mitchell automatic flight system AK717/FD consisting or Century IV/flight director autopilot with optional remote annunciator. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F (Seaplane configuration only); T.C. A4CE	SA3296WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/23/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
U206F, U206G, TU206F, TU206G;	SA3454WE	Installation of an emergency fuel system. Amended 2/7/78.	WE	59730	Mission Aviation Fellowship P.O. Box 2826 Fullerton, CA 92633
U206G, TU206G; T.C. A4CE	SA1480CE	Installation of King KFC200 automatic flight control system, two axis, with or without flight director. Issued 3/27/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
TU206C; T.C. A4CE	SA566CE	Install one or two blister windows.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
TU206C, TU206D; T.C. A4CE	SA935EA	Installation of window in bottom of fuselage at F. Station 35.5. Amended 4/18/73.	EA	52060	Long Island Airways Box 248 Ronkonkoma, NY 11779
TU206G; T.C. A4CE	SA831NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705
TU206G; T.C. A4CE	SA4004SW	Camera port. Issued 6/20/79.	SW	28490	Daily Tubbs Aero, Inc. 2115 Danbury Drive San Antonio, TX 78217
206, 207, 210 Series; T.C. A4CE, A16CE, 3A21	SA2809SW	Install Symbolic Displays CFS-1000 electronic fuel flow metering system. Issued 7/2/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206, 210 Series; T.C. 3A21, A4CE	SA149SW	Automatic pilot AK120, AK120E, AK102E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206, 210 Series; T.C. 3A21, A4CE	SA245WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
206, 210 Series; T.C. 3A21, A4CE	SA526SW	Automatic trim AK171.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206, 210 Series; T.C. 3A21, A4CE	SA674WE	Flight control system B-4 including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
207; T.C. A16CE	SA1402SW	Mitchell automatic flight system AK357 consisting of Century II autopilot with optional radio coupler. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1403SW	Mitchell automatic flight model AK356 consisting of Century I autopilot with optional omni tracker. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1404SW	Mitchell automatic flight system Model AK361 consisting of command/electric trim system. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA2856SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
207, T207; T.C. A16CE	SA1354CE	Chrome-plated brake disc installation. Issued 8/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
207, T207; T.C. A16CE	SA2121WE	Installation of recontoured wing leading edge, drooped ailerons, in flaps down mode, stall fences, and elevator trim spring. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
207, T207; T.C. A16CE	SA2327WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
207, T207; T.C. A16CE	SA2676WE	Installation of larger fuel containing wing tips. Amended 5/23/77.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041
207, T207; T.C. A16CE	SA3427WE	Installation of tail flood light on horizontal stabilizer. Issued 6/22/77.	WE	30000	DeVore Aviation 16160 Stagg Street Van Nuys, CA 91406
210 Series; T.C. 3A21	SA1-625	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA3-503	L-2B autopilot with or without altitude controller and/or approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
210 Series; T.C. 3A21	SA4-1086	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
210 Series; T.C. 3A21	SA4-1372	Brake blocks AB-6526 and AB-6527.	EA	46748	Johns-Manville Corporation 22 E. 40 Street New York, NY 10001
210 Series; T.C. 3A21	SA4-1416	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA20SW	Automatic pilot AK086, AK086E or AK086R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA89SW	Automatic pilot AK112.	SW	60000	Mitchell Industries, INc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA89NW	Installation of King VOR Model KX 170B or KX 175B, King DME Model KN65 and King Area Navigation computer Model KN74. Issued 2/11/74.	NW	70040	Salem Aviation 2680 Aerial Way, S.E. Salem, OR 97302

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210 Series; T.C. 3A21	SA103SW	Automatic pilot AK111.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA110EA	Removal of right front door and other modifications.	EA	72108	Sky Diving, Inc. Cameron Airpark Medford, NJ 08055
210 Series; T.C. 3A21	SA118EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA199WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	82270	V. Vincent Vandever, Inc. 6447 W. Reade Avenue Glendale, AZ 85301
210 Series; T.C. 3A21	SA330SW	Automatic pilot AK126 and lateral guidance/radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA420SW	Automatic pitch trim AK133.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA464EA	Propeller, spinner, and governor.	GL	73830	Southeastern Ohio Air Service, Inc. P.O. Box 863 Municipal Airport Zanesville, OH 43701
210 Series; T.C. 3A21	SA469WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold (optional). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA531CE	Installation of Canairco 1214 WB supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
210 Series; T.C. 3A21	SA618WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA627WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA637SW	AK209 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA675SW	AK212 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA1100SW	Increase wing leading edge radius. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
210 Series; T.C. 3A21	SA1305WE	PCA-1 pitch assist with altitude hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1343WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1471WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1478WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1606WE	Installation of Brittain Industries B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1609WE	Installation of Brittain Industries Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210 Series; T.C. 3A21	SA1618WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1631WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1672WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1684WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1882WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1887WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA2720WE	Installation of Symbolic Displays IFC-1A anti-collision lights. Amended 3/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
210, 210A; T.C. 3A21	SA1527WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 8/7/73.	WE	35780	William E. Flint 7745 Kopalt Street La Mesa, CA 92041
210, 210A; T.C. 3A21	SA3377WE	Installation of flap gap fairing. Issued 3/24/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
210, 210A; T.C. 3A21	SA3732WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 9/14/78.	WE	84542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
210, 210A, 210B, 210C, 210K, 210L, T210K, T210L; T.C. 3A21	SA52GL	Installation of wheel and brake conversion kit P/N 199-60. Issued 6/6/74.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Industries, Inc. 1660 Avon Center Road Avon, OH 44011
210, 210F, T210F (205), 210-5 (205A), 210-5A; T.C. 3A21	SA64NW	Installation of fiberglass wing tips. Issued 9/13/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
210, 210A, 210B, 210C, 210-5; T.C. 3A21	SA93CE	High intensity wing tip lights Model B, and tail light Model C, with or without fuselage lights. Reissued 10/17/74.	GL	42626	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
210, 210A, B, C, D, E, F, 210-5(205), 210-5A (205A), T-210F; T.C. 3A21	SA940CE	STOL Kit installation. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
210, 210A, 210B, 210C, 210D, 210E, 210F; T.C. 3A21	SA1048CE	Installation of STOL kit (wing leading edge cuffs, stall fences, aileron gap seals and droop wing tips). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
210, -A, -B, -C, 210-5 (205), 210-5A (205A); T.C. 3A21	SA1090WE	Installation of Rajay turbosupercharged Continental IO-470-E or IO-470-S engine. Amended 8/11/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
210, 210A thru 210H, 210J, K, L, T210F thru T210H, T210J, K, L; T.C. 3A21	SA1525WE	Installation of droop ailerons in flaps down mode, recontoured wing leading edge, and elevator trim spring (except on T210K, L, and 210K and L). Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
210 thru 210K, T210F thru T210K, 210-5 (205), 210-5A (205A); T.C. 3A21	SA2242WE	Installation of recontoured wing leading edge stall fences, and for 205, 205A, 210A, 210B and 210C positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
210, 210A, B, C, D, E, F, G, H, J, K, L, M, T210F, G, H, J, K, L, M, (205) 210-5, (205A), 210-5A, P210N; T.C. 3A21	SA3312WE	Installation of recognition lights on horizontal stabilizer. Amended 3/20/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210, 210A, B, C, D, E, F, G, H, J, K, L, M, N, P210; T.C. 3A21	SA3453WE	Installation of a cargo container. Amended 4/25/80.	WE	02465	Aero Pod, Inc. 17262 Sandra Lee Lyn Huntington Beach, CA 92649
210A, B, C, D, E, F; T.C. 3A21	SA3649WE	Installation of replacement flexible fuel cell in the wings of the 210 Cessna aircraft. Issued 5/16/78.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
210B, C; T.C. 3A21	SA3144SW-D	Mitchell automatic flight system AK604 consisting of Century I autopilot with optional omni tracker. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B, C; T.C. 3A21	SA3145SW-D	Mitchell automatic flight system AK605 consisting of Century IIB autopilot with optional radio coupler. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B; 210-5(205), 210-5A(205A); T.C. 3221	SA3522WE	Installation of Knisley muffler in lieu of original Cessna mufflers. Issued 11/11/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
210B, 210C, 210E, 210-5(205, 210-5A (205A); T.C. 3A21	SA393GL	Installation of Great Lakes Aero Products windshield, P/N W-2065, W/T-2065, W/G-2065. Issued 3/10/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
210C; T.C. 3A21	SA197EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
210C, D, E, F, G, H, J, K, T210F, G, H, J, K, 210-5(205), 210-5A(205A); T.C. 3A21	SA1312CE	Chrome-plated brake disc installation. Amended 9/13/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
210D, E; T.C. 3A21	SA376NW	Installation of McCauley D3A32C88-XLM/S-82NC-2 propeller and Continental IO-520-A engine. Issued 11/15/76.	NW	34827	Felts Field Aviation 3100 North Division Spokane, WA 99207
210D, E, F, T210F; T.C. 3A21	SA906SW	Mitchell automatic aileron stabilizer AK211 and omni tracker AK246.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Cincinnati, OH 45226
210D, E, F, T210F; T.C. 3A21	SA1376SW	Mitchell automatic flight system AK349 consisting of Century I with optional omni tracker. Issued 10/4/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, E, F, T210F; T.C. 3A21	SA3141SW-D	Mitchell automatic flight system AK620 consisting of Century IIB autopilot with optional radio coupler. Issued 6/3/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, 210E, 210F, T210F; T.C. 3A21	SA2677WE	Installation of larger fuel containing wing tips. Amended 4/6/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210D, E, F, G, H, J, K, L, M, T210F, G, H, J, L, M, K, P210N; T.C. 3A21	SA3751WE	Installation of Fueltron IC digital fuel flow and totalizer system. Amended 11/22/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
210D, 210E, P206; T.C. 3A21, A4CE	SA693WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	18124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
210D, E, F, G, H, J, K; T.C. 3A21	SA790CE	Installation of engine condition monitor kit ECM-6. Issued August 1971.	GL	31750	ECM Corporation 412 North Weinbach Avenue Evansville, IN 47711
210E; T.C. 3A21	SA2784SW	Leading edge cuffs, stall fences, aileron seals, and wing tips. Issued 6/1/78.	SW	10600	Bob Williams d/b/a Bush Conversions Box 61 Guthrie, OK 73044

Aircraft Make, Model & T.C. No.	STC No.	Description	PG	STC Code	STC Holder
210G; T.C. 3A21	SA829SW	Automatic flight system AK254 Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G; T.C. 3A21	SA850SW	AK258 consisting of Century III autopilot with optional aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, T210G, 210H, T210H, 210J, T210J, 210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N; T.C. 3A21	SA966CE	Installation of leading edge cuffs, droop tips, aileron gap seals, and stall fences. Amended 4/25/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
210G, H, J, K, L, M, T210G, T210H, T210J, T210K, T210L, T210M, 210N, P210N, T210N; T.C. 3A21	SA2862WE	Installation of larger fuel containing wing tips. Amended 7/23/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210G, H, J, T210G, H, J; T.C. 3A21	SA3168SW-D	Automatic flight system AK641 consisting of Century IV autopilot or AK641-FD consisting of Century IV flight director with optional remote annunciator. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J; T.C. 3A21	SA3169SW-D	Automatic flight system AK642 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J, K; T.C. 3A21	SA3170SW-D	Automatic flight system AK643 consisting of Century IIB autopilot with optional radio coupler. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, K, T210G, H, J; T.C. 3A21	SA3171SW-D	Automatic flight system AK644 consisting of Century I autopilot with optional omni tracker. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
T210F; T.C. 3A21	SA1042SW	Hartzell-Wren beta control system. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
T210F; T.C. 3A21	SA2277WE	Installation of Brittain Industries B2C flight control systems. Amended 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G; T.C. 3A21	SA1420WE	Installation of Brittain Industries B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G, H, J; T.C. 3A21	SA2689SW	Install TSIO-520-M engine. Issued 12/9/77.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
210H; T.C. 3A21	SA725CE	Installation of electric gyros and standby power source.	CE	43374	Humphrey, Incorporated 434 North Oliver Wichita, KS 67208
210J; T.C. 3A21	SA2249WE	Installation of Brittain Industries B-7, NAV-2B, B2C and B8S flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210J, T210J, 210K, T210K; T.C. 3A21	SA1326SW	Mitchell automatic flight system AK334, consisting of Century II autopilot with optional radio coupler, and automatic aileron stabilizer. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210J, T210J, 210K, T210K; T.C. 3A21	SA1327SW	Mitchell automatic flight system AK332, consisting of Century I auto- pilot with optional omni tracker. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA71RM	Installation of JB Systems air conditioning system. Amended 6/8/79.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA210NW	Collins AP-107 low profile 3 axis automatic flight control system. Amended 12/2/77.	NW	24250	Collins Radio Group 855 35th Street, N.E. Cedar Rapids, IA 52406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA211NW	Installation of Collins AP-107 low profile two axis automatic flight control system. Amended 12/2/77.	CE	24250	Collins Radio Group 855 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA212NW	Installation of AP-107 low profile yaw damper system. Amended 12/2/77.	CE	24250	Collins Radio Group 355 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K; T.C. 3A21	SA1325SW	Mitchell automatic flight system AK331, consisting of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K; T.C. 3A21	SA2199WE	Installation of Brittain Industries B-7, NAV-2B, B2C, and B5B flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210K, T210K, 210L, T210L; T.C. 3A21	SA509SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 3/3/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210K, T210K, 210L, T210L, 210M, T210M, T210N; T.C. 3A21	SA1202CE	Installation of King Model KFC-200 two axis flight control system with or without flight director. Amended 11/28/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
210L, T210L; T.C. 3A21	SA1506SW	Mitchell aytomatic flight system AK388, consisting of Century III autopilot with optional automatic pitch trim, radio and glide slope coupler. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA1507SW	Mitchell automatic flight system AK386 consisting of Century I with optional omni tracker. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA1526SW	Mitchell automatic flight system AK387, consisting of Century IIB autopilot with optional radio coupler. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3001SW-D	Automatic flight system AK468, Century IV autopilot or AK468FD Century IV flight director with electronic command/automatic pitch trim and optional remote annuciator panel. Issued 4/26/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3112SW-D	Automatic flight system AK566 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/5/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3247WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder Autopilot Systems and/or Pitch Trim Systems. Issued 8/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, Ca 90505
210L, T210L, 210M, T210M; T.C. 3A21	SA1006SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 6/30/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210L, 210M; T.C. 3A21	SA3685WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
210L, 210M, T210L, T210M; T.C. 3A21	SA3182SW-D	Mitchell automatic flight system AK387 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, 210M, T210L, T210M; T.C. 3A21	SA3183SW-D	Mitchell automatic flight system AK386 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210L, T210 S/N 21061040 and up, P210N, 210M, T210M, T210N; T.C. 3A21	SA3835WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow Amended 6/12/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714
210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA1005SO	Installation of Bendix FCS-870 automatic flight control system, or installation of Bendix FCS-870 automatic flight control system with reduced flap motor speed. Amended 12/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210N, P210N, T210N; T.C. 3A21	SA756NW	Installation of leading edge stall strips, change aileron droop. Issued 4/20/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N; T.C. 3A21	SA760NW	Installation of RCA digital weather radar system. Issued 5/3/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N, P210N; T.C. 3A21	SA1420CE	Install wing leading edge cuffs (with or without de-icer boots) and wing stall fences. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
P210N; T.C. 3A21	SA1487CE	Installation of King KFC200 AFCS, two axis, with or without flight director. Issued 5/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
P210N; T.C. 3A21	SA1552CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
P210N; T.C. 3A21	SA3289SW-D	Mitchell automatic flight system AK737 consisting of Century IIB autopilot with optional radio and glide slope couplers. Issued 6/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P210N; T.C. 3A21	SA3290SW-D	Mitchell automatic flight system AK738 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P210N; T.C. 3A21	SA3291SW-D	Mitchell automatic flight system AK739 consisting of Century IV autopilot or AK739FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 210 Mineral Wells, TX 76067
210-5 (205), 210-5A (205A); T.C. 3A21	SA993CE	Install STOL kit (leading edge cuff, droop tips, stall fence and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
T210L, T210M; T.C. 3A21	SA3857WE	Installation of an air/oil separator. Issued 3/13/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
305 Series; T.C. 5A5	SA504SW	Rerouting of oil to oil cooler and addition of extra cooler.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA295SW	Three-place configuration.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA353SW	Conversion of aircraft for parachute jumping operations.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA505SW	McCauley 1A200FM propeller.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA568SW	Gross weight increased to 2,300 2,300 pounds.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA1201SW	Lycoming O-540-A4B5 engine. Reissued 3/19/75.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
305A; T.C. 5A5	SA1620SW	Cessna 180 fuel cells. Issued 4/19/73.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
305A; T.C. 5A5	SA1702SW	20-gallon fuel cells. Issued 7/19/73.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A, 305B; T.C. 5A5, 3A14	SA3-370	Model 3000 main skis and Model 1000 tail ski.	GL	36060	Fluidyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
305A, B, C, D, E; T.C. 5A5, 3A14	SA2857SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Issued 9/22/78.	SW	18600	Bob Williams d/b/a Bush Conversions P.O. Box 61 Guthrie, OK 73044
310 Series; T.C. 3A10	SA1-21	Federal autopilot F-400.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
310 Series; T.C. 3A10	SA1-293	Lightweight reservoir pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-506	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-579	Taxi lamp in right outboard cowling.	GL	22460	Cincinnati Aircraft, Inc. Lunken Airport Cincinnati, OH 45202
310 Series; T.C. 3A10	SA3-55	Radio equipment.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
310 Series; T.C. 3A10	SA3-440	L-3 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA3-475	Full feathering, constant speed propellers, hubs 2AF36C26, blades 90MF-10.	GL	52720	McCauley Industrial Corporation 1807 Howell Avenue Dayton, OH 45401
310 Series; T.C. 3A10	SA3-636	M-4 flight control system with altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA3-643	Transa-Stroke beacon B-7220.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
310 Series; T.C. 3A10	SA3-662	Hydraulic accumulator in each engine nacelle and new propeller governor C210355 or A210438.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
310 Series; T.C. 3A10	SA3-665	Cabin air temperature control system on Southwind (Stewart-Warner) 8240-A heater.	GL	82500	Vap-Air Division Vapor Corporation 6444 W. Howard Street Chicago, IL 60607
310 Series; T.C. 3A10	SA4-3	32-gallon auxiliary fuel tank in baggage compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-127	56-gallon auxiliary fuel tank in hat rack compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-239	Thompson TF2800 engine-driven fuel pump.	WE	33460	Engineering Modification Company 6850 Vineland Avenue North Hollywood, CA 91603
310 Series; T.C. 3A10	SA4-702	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
310 Series; T.C. 3A10	SA4-1217	Extension of augmenter tubes to trailing edge of wing.	WE	10116	AMC Augmenters 2648 N. Campbell Tucson, AZ 85700
310 Series; T.C. 3A10	SA4-1400	SP-3 autopilot.	WE	74570	Sperry Phoenix Company P.O. Box 2529 Phoenix, AZ 85000
310 Series; T.C. 3A10	SA4-1588	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310 Series; T.C. 3A10	SA6SC	Window on each side of cabin between fuselage stations 89.25 and 109.375. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA37SO	Fuselage access holes in bottom skin of fuselage.	SO	76830	Sunny South Aircraft Service, Inc. 300 S.W. 41 Street County International Airport Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA44CE	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA56SO	Dual camera ports. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA59SO	One-piece windshield	SC	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33306
310 Series; T.C. 3A10	SA60SO	Third window on each side of fuselage.	SC	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33306
310 Series; T.C. 3A10	SA61SO	Underwing exhaust system and nacelle fairings.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA77SO	Engines modified per STC SE73SO.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Fort Lauderdale, FL 33300
310 Series; T.C. 3A10	SA97SO	A, B, or C of turbocharged Continental IO-470-D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA99SO	Auxiliary fuel tanks under nacelle fairing (4-tank and 6-tank systems).	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA109EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA119CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA102SW	Cessna 6895000-8, -9 aft cowling doors.	SW	08168	Airline Aviation, Inc. P.O. Box 1024 Roswell, NM 88201
310 Series; T.C. 3A10	SA248SO	Increase takeoff gross weight to 4,830 pounds. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA254SO	Swept vertical tail. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA303CE	Installation of Bendix Model M-4E/C autopilot flight control system. Amended 2/20/69.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33306
310 Series; T.C. 3A10	SA325CE	GUARD system (Gear Up Automatic Response Device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612
310 Series; T.C. 3A10	SA347SW	Cowling and exhaust system.	SW	60089	Modern Aero Sales, Inc. 4837 W. Hampton Road Dallas, TX 75221
310 Series; T.C. 3A10	SA348WE	Installation of air induction system. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2606 E. Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA385WE	Turbocharged Lycoming IO-540-A1A5 engines. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA390WE	Pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310 Series; T.C. 3A10	SA444NW	Replace original split flaps with Fowler flaps. Issued 5/12/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
310 Series; T.C. 3A10	SA448EA	Electrothermal propeller deicing system.	GL	38500	The B.F. Goodrich Company Municipal Airport Akron, OH 44318
310 Series; T.C. 3A10	SA457SW	AK145 automatic pitch trim.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA477SO	Modify control wheel. Issued 10/27/71.	SO	02350	Aeronautical Engineers, Inc. P.O. Box 602 IAP Miami, FL 33148
310 Series; T.C. 3A10	SA517WE	Flight control system B-4, including pitch assist PC-1, altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA621SW	AK198 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA678SW	Lear or Motorola 1-2C autopilot.	SW	031[illegible]0	Aerotron Radio Company International Airport Tulsa, OK 74131
310 Series; T.C. 3A10	SA737SW	AK201 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310; T.C. 3A10	SA1359CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33466	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
310 Series; T.C. 3A10	SA1490WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1799WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1896WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA2406SW	Addition of hydro seal fluid additive to nose and main gear shock strut. Issued 2/11/77.	SW	45722	Granville Lasseter 802 East Grant Street Morton, TX 79346
310, 310A thru 310J, 320, 320A, B, C, D; T.C. 3A10, 3A25	SA1-620	Kit No. 2014X for 12-inch RCA AVQ-45, AVQ-47, AVQ-50, AVQ-55 and 12-inch Collins WP-103 radar antenna. Amended 4/15/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310B, 310C; T.C. 3A10	SA1-185	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	141[illegible]4	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
310 thru 310Q, T310P, Q, E310H, J, T310R, 320 thru 320F, 340, 340A, 335, 336, 337, 337B, C, D, E, F, G, T337B, C, D, E, F, G, 401, 401A, B, 402, 402A, B, 404, 411, 411A, 414, 414A, 421, 421A, B, C; T.C. 3A10, 3A25, A7CE, A6CE, A2CE	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 9/25/78.	GL	67256	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
310, 310A thru 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA111GL	Install Cleveland conversion kit P/N 199-64. Issued 6/30/76.	GL	23[illegible]	Cleveland Wheels and Brakes Div. of [illegible] Industries, Inc. 1160 Center Road Avon, OH 44011

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
310-A thru 310-K, 320A thru 320-D, 320-T; T.C. 3A10, 3A25	SA302CE	Supplemental high intensity position light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
310, 310A thru H, E310H, 310J, J-1, E310J, 310K, L, N, 320, 320-1, 320-A, B, C, D, E, F, 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA362CE	Install Hoskins Twilighter Mk III and Mk IIIB light system. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
310, 310A thru J, 320, 320A thru D; T.C. 3A10	SA396EA	Installation of Radome Kit No. 2310X-R. Reissued 4/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310C; T.C. 3A10	SA814SW	Underwing exhaust.	SW	08168	Airlane Aviation, Inc. P.O. Box 1024 Roswell, NM 88204
310, 310A thru 310F; T.C. 3A10	SA574WE	Installation of landing gear position mirror on left wing tip tank. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
310, 310A, B, C, D, E, F, G, H, I, J, K, L, N, P, Q, E310H, 310J-1, E310J, T310P, T310Q; T.C. 3A10	SA3235WE	Installation of recognition light assembly on horizontal stabilizer. Issued 7/13/76.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 106 Van Nuys, CA 91406
310, 310A, B, C, D, E, F, G, H, I, J, K, L, N, P, Q, R, T310P, T310Q, T310R; T.C. 3A10	SA4136WE	Installation of inflatable door seal. Issued 4/20/80.	WE	36320	Bob Fields Aerocessories 340 "E" East Santa Maria St. San Paula, CA 93060
310, 310B; T.C. 3A10	SA26SO	Aerodynamic clean-up, cabin soundproofing, new interior and cooling duct changes. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310F, 310Q; T.C. 3A10	SA74SO	Installation of seats and camera port. Reissued 9/10/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D; T.C. 3A10	SA76SO	Installation of two (2) R.H. and two (2) L.H. single seats and enlarged emergency exit. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B thru 310G; T.C. 3A10	SA212SW	Installation of Lycoming IO-540-A1A5 engines and Hartzell HCA3XK-2B/7636D propellers. Reissued 6/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D, 310F; T.C. 3A10	SA455SO	Installation of extended window modification. Issued 3/18/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
310, 310F thru H; 320, 320-1, 320A thru F; 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA240WE	Consolidation of STCs SA355CE and SA362CE into one STC having MASTER ELIGIBILITY LIST - amended to include improved power supply assembly and subchassis timer assembly for Twilighter MK III high intensity supplementary lighting system. Issued 8/16/71.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
310B, C, D, E, F, G, H, I, J, K, L, N, P, Q, T210P, T210Q; T.C. 3A10	SA3243WE	Installation of pilot's and co-pilot's side vent windows. Issued 8/13/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
310C thru 310G; T.C. 3A10	SA2363WE	Installation of turbo-charged Continental IO-470-D engine. Issued 8/18/71.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
310C, D, F, G, H, I, J, K, L, N, P, Q, T310P, T310Q, T310R; T.C. 3A10	SA3671WE	Installation of Fueltron IIIG or IIIP digital fuel flow indicating system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
310D; T.C. 3A10	SA391GL	Installation of Great Lakes Aero Products windshield P/Ns W-2070, W/T-2070 or W/G-2070. Issued 3/3/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310D thru 310L, 310N, 310P, 320, 320A thru 320F; T.C. 3A10, 3A25	SA2534WE	Installation of Cessna 310P-type fiberglass tail stinger and yaw reduction adapter. Amended 5/30/73.	WE	01750	Aerocessories Company 1779 Fitzgerald Road Simi, CA 93065
310D, G, H, I, J, K, L; T.C. 3A10	SA3078SW-D	Auto flight system AK556, Century IV autopilot or AK556FD Century IV flight director. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J; T.C. 3A10	SA3079SW-D	Mitchell yaw damper system YK 558. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J; T.C. 3A10	SA3082SW-D	Automatic flight system AK557, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, E, F, G, H, I, J, K, L, N, P, Q, R, T310P, T310Q, T310R, 320-1, 320C, D, E, F; T.C. 3A10, 3A25	SA3105SW-D	Mitchell automatic flight system AK584 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310F, 310G; T.C. 3A10	SA752EA	Installation of ground to air recovery equipment. Restricted Category. Amended 8/6/69.	EA	09500	All American Eng. Company Box 1247 Lancaster Pike & Center Road Wilmington, DE 19899
310G, H, I, J, K, L, N, P; T.C. 3A10	SA412SO	Installation of Continental IO-520-E engines. The engines are limited to 260 hp. Amended 12/16/71.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
310G, H thru Q, J-1; E310H, J; T310P, Q; 320A, B thru F; 402, A, B, 401, A, B; 411, A; 414; 421, A, B; T.C. 3A10, 3A25, A7CE	SA568EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-0107-1. Amended 11/7/75.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
310G thru 310Q, 310R, 320A thru 320F, 340A, 401, 401A, B, 402, 402A, B, 411A, 414, 421, 421A, B; T.C. 3A10, 3A25, A7CE	SA574NW	Installation of forward facing recognition lights and clear plastic wing tip tank nose cone. Amended 4/13/78.	NW	28850	Robert R. DeBorde 20645 S.W. Clarion Aloha, OR 97005
310G, H, I, J, K, L, N, P, 310Q thru 310Q-0601; T.C. 3A10	SA3789WE	Installation of 36-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
310H; T.C. 3A10	SA294SO	Installation of turbocharged Continental IO-470-D engines. Reissued 12/5/74.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90801
310H thru 310L, 320 thru 320E, 401, 402; T.C. 3A10, 3A25, A7CE	SA1847WE	Installation of Brittain Up-Command Signal Adapter Kit. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310I, 310J; T.C. 3A10	SA181SO	Installation of turbosupercharged Continental IO-470-U engines. Amended 8/9/68.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
310I, J, K, L, N, P, Q, R, T310P, T310Q, T310R, 320A, B, C, D, E, F, 340, 401, 401A, B, 402, 402A, B, 414, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA107GL	Conversion of oil lubricated deice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
310I, J, K, L, N, P, R, Q, T310P, T310Q, T310R; T.C. 3A10	SA701CE	Install Airborne wing and tail pneumatic deice kit 703B. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
310I, L, N, P, Q, T310P, 320C, 320E; T.C. 3A10, 3A25	SA1883SW	Install Hartzell synchrophase system. Issued 6/11/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708
310I, J, K, L, N, P, Q; 320B, C, D, E, F; T.C. 3A10, 3A25	SA1904SW	Additional auxiliary transfer tanks. Issued 8/13/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310J, E310J, T310P, T310Q, 310K, 310L, 310N; 320D, 320E, 320F, 340; 401, 401A, 401B, 402, 402A, 402B, 414, 411, 411A, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA14GL	Installation of detachable lead strap propeller deicers. Issued 3/20/73.	GL	44318	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310J, K, L, N, P, Q, R, T310P, T310Q, T310R; T.C. 3A10	SA4718SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 6/3/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
310K, 310L, 310N, 310P, 310Q, 320E, 320F; T.C. 3A10, 3A25	SA42GL	Install Norton Company radome kit No. 3060X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310K, 310L, 310N, 320E, 320F, 310P, 310Q; T.C. 3A10, 3A25	SA490EA	Installation of Chamberlain Radome Kit No. 3060R-B for Bendix radar RDR-100 or RDR-110 systems. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310K, L, N, P, Q, 320E, 320F; T.C. 3A10, 3A25	SA150GL	Install Norton Company radome Kit No. 4131X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310K, L, N, P, Q, 320F; T.C. 3A10, 3A25	SA537EA	Installation of Radome Kit No. 3060X-R. Amended 8/25/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310L, N, P, Q; T.C. 3A10	SA2082WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Hartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68145	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
310N; T.C. 3A10	SA2784WE	Installation of Ontrac II VLF 1000 very low frequency navigation system. Amended 12/3/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3266WE	Installation of ONTRAC III VLF/Omega navigation system. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway AVenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3287WE	Installation of Ontrac III VLF/Omega navigation system as a means of navigation (but not sole means) for EN ROUTE navigation. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3789WE	Installation of 36 gallon auxiliary fuel tanks in each wing. Issued 11/14/78.	WE	35320	Bob Fields 5673 Stanford Street Ventura, CA 93003
310N; T.C. 3A10	SA3924WE	Installation of ONTRAC IIIA VLF/Omega navigation system. Issued 5/25/79.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N, P, Q, T310Q; T.C. 3A10	SA3018SW-D	Automatic flight system AK442 consisting of Century III autopilot with optional command and auto. elec. elevator pitch trim, radio, and glide slope coupler. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, Q, T310P, Q; T.C. 3A10	SA3019SW-D	Automatic flight system AK443 and AK443FD consisting of Century IV autopilot and Century IV flight director autopilot with trim system and annuciator panel. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, T310P, T310Q; T.C. 3A10	SA3020SW-D	Automatic flight system YK444 consisting of yaw damper. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P, 310Q; T.C. 3A10	SA592NW	Installation of Fowler flaps. Issued 4/14/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310P, 310Q, T310P, T310Q; T.C. 3A10	SA137NW	Installation of Collins AP-107 low profile automatic flight control system (FCS), including yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA138NW	Installation of Collins low profile yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA875EA	Installation of Brittain Industries, Inc. flight control system Model B-7 or NAV-2B or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310P, T310P, 310Q; T.C. 3A10	SA1142SW	Edo-Aire Mitchell automatic flight system, AK300 consisting of Century III with pitch trim, radio, and glide slope coupler. Issued 5/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P, Q, R, T310P, T310Q; T.C. 3A10	SA1190SW	Mitchell automatic flight FD/AP282-300 consisting of flight director/automatic pilot and automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P/T310P, 310Q/T310Q, 310R/T310R; T.C. 3A10	SA1273CE	Installation of King KFC 200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 4/14/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
310 P/T 310P, 310Q/T310Q, 310R/T310R; T.C. 3A10	SA1555CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
310P, 310Q, 310R; T.C. 3A10	SA2203WE	Installation of air conditioning system. Amended 6/3/76.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
310P, T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA3602WE	Installation of vapor cycle airconditioning system. Issued 3/6/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
T-310; T.C. 3A10	SA192RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
T310, 320, 320A, B, C, D, E, F, 340, 401, A, 411, A, 414, 421, A, B; T.C. 3A10, 3A25	SA3RM	Modification of engine exhaust stacks by replacement of expansion joint with slip fit joint. Reissued.	RM	41750	Heliarc Welding Service, Inc. 3916 Niagara Street, Box 7301 Denver, CO 80207
T310 Series, 320A, B, C, D, E, F, 401, 401A, 402, 402A, B, 404, 414, 421C; T.C. 3A10, 3A25, A7CE	SA103RM	Installation of exhaust turbo connector, P/N 30477-3 Issued 8/17/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
T310 Series, 320, 320A, B, C, D, E, F, 340, 340A; T.C. 3A10, 3A25	SA110RM	Modify Cessna exhaust system by replacement of the inter-cylinder expansion joints with a slip fit joint.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
T310L;	SA530NW	Installation of McCauley D3A34C402/90DFA-10 propeller on Continental TSIO-520-H engine. Issued 10/4/77.	NW	67090	Keith L. Remington 253 S.W. 4th Avenue Ontario, OR 97914
T310P; T.C. 3A10	SA1016SW	Bendix M4-C autopilot.	SC	15475	Bendix Avionics P.O. Box 9414 Fort Lauderdale, FL 33310
T310P; T.C. 3A10	SA2292WE	Modification of waste gate controls. Issued 1/20/71.	WE	25400	Comp Air, Inc. 1285 Rollins Road Burlingame, CA 94010
T310P, T310Q, 320, 320-1, 320A thru 320F, 340, 411, 411A, 401, 401A, B, 402, 402A, B, 421, 421A, 414; T.C. 3A10, 3A25, A7CE	SA128GL	Replace existing asbestos or bellows exhaust seal with slip joint. Reissued 12/15/78.	GL	84915	Frank Wetner 725 N. Hamilton Road Columbus, OH 43219

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
T310P, Q, 320D, E, F; T.C. 3A10, 3A25	SA2750SW	Install Continental TSIO-520-E engine. Issued 4/10/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
T310P, T310Q, T310R, 320D, 320F; T.C. 3A10, 3A25	SA2862SW	CFS-2000 electronic fuel flow metering system. Issued 10/18/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
T310P, T310Q, T310R, 320D, E, F; T.C. 3A25	SA4011SW	Installation of TSIO-520-N, or TSIO-520-NB engine. Issued 7/9/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
310Q; T.C. 3A10	SA723CE	Incorporate openable windows and drop hole.	CE	36000	Flcair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
310Q, T310Q; 310R, T310R; T.C. 3A10	SA775CE	Installation of Janitrol Aero Division vapor cycle air conditioning system. Amended 12/9/74.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
T310Q; T.C. 3A10	SA2242SW	Continental TSIO-520-J engines. Issued 9/15/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
310R; T.C. 3A10	SA103GL	Install Norton Company radome Part No. 4096X. Amended 6/22/76.	GL	61750	Norton Company P.O. Box 350 Akron, OH 44309
310R; T.C. 3A10	SA1081CE-D	Installation of Collins Radio Group AP-106, 3-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1082CE-D	Installation of Collins Radio Group AP-107, 3-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1083CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1084CE-D	Installation of Collins Radio yaw damper system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R/T310R; T.C. 3A10	SA1301CE	Installation of Enk Aviation fire suppression system. Amended 11/28/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
310, 320; T.C. 3A10, 3A25	SA99SW	Automatic pilot AK113 and lateral guidance radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320; T.C. 3A10, 3A25	SA234EA	Installation of Chamberlain 2310K-E series radome kit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309
310, 320; T.C. 3A10, 3A25	SA237SO	Control wheel modification. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 320 Series; T.C. 3A10, 3A25	SA272EA	Installation of Chamberlain 2014K-B radome kit as follows: Kit No. 2014K-E for Bendix RDR-100 or RDR-110 radar systems with 12" antenna and transmitter receiver unit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309
310, 320 Series; T.C. 3A10, 3A25	SA338SW	Automatic pilot AK125.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA409SW	Automatic pitch trim AK137.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA446CE	30-gallon auxiliary fuel tank in baggage compartment.	CE	36000	FloAir, Inc. Municipal Airport Newton, KS 67114
310, 320 Series; T.C. 3A10, 3A25	SA455WE	Single-piece windshield.	WE	20630	Cessna Components, Inc. P.O. Box 521 Long Beach, CA 90801

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310, 320 Series; T.C. 3A10, 3A25	SA471EA	SAGA (Semi-automatic gear actuating) system.	GL	44010	In-Flight Services Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
310, 320 Series; T.C. 3A10, 3A25	SA521SW	Automatic pilot AK157 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA667SW	AK222 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA722WE	30-gallon wing leading edge fuel tanks. Amended 9/2/65.	WE	20630	Cessna Components, Inc. 3200 Airport Avenue Santa Monica, CA 90406
310, 320 Series; T.C. 3A10, 3A25	SA1175WE	One-piece windshield.	WE	14238	Cee Bailey's Aircraft Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
310, 320 Series; T.C. 3A10, 3A25	SA1452WE	Installation of Brittain model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1604WE	Installation of Brittain B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1680WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; 320 Series; 336 Series; 337 Series; 401, 402, 411, 421 Series; T.C. 3A10, 3A25, A2CE, A6CE, A7CE	SA1675WE	Installation of exhaust gas temperature monitoring systems Model EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
320 Series; T.C. 3A25	SA3-737	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA101SO	One right-hand and two left-hand single seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320 Series; T.C. 3A25	SA104EA	L-2C autopilot slave cables around existing approved camera opening in lower surface of fuselage.	EA	20630	Aero Service Corporation North Philadelphia Airport Philadelphia, PA
320 Series; T.C. 3A25	SA117CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA119SO	Passenger seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320 Series; T.C. 3A25	SA127SW	Auxiliary baggage compartment and adjustable seat modification.	SW	37154	Gen-Aero, Inc. P.O. Box 6767 San Antonio, TX 78205
320 Series; T.C. 3A25	SA130CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA306CE	GUARD System (gear up automatic response device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
320 Series; T.C. 3A25	SA492SW	Emergency alternate air door actuation.	SW	35270	El Paso Natural Gas Company P.O. Box 1492 El Paso, TX 79910
320 Series; T.C. 3A25	SA632WE	B-4 flight control system including pitch assist PC-1, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
320 Series; T.C. 3A25	SA744SW	M4E/C autopilot.	SO	15475	The Bendix Corporation Avionics Group P.O. Box 9414 Fort Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
320, 320-1; T.C. 3A25	SA285SO	Installation of Lycoming IO-540-A1A5 powerplants and Hartzell HCA3XK-2B/7636D propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320, 320-1, 320A, 320B, 320C; T.C. 3A25	SA518SO	Installation of Continental IO-520-E derated engines and McCauley D3AF32C87/82NC-6 or -8 propellers. Issued 8/28/72.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F (320 series S/N's 0001-D9999; 320E0001-F9999); T.C. 3A25	SA110GL	Install Cleveland conversion kit P/N 199-64. Issued 6/30/76.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
320, 320A, 320B, 320C, 320D, 320E, 320F S/N's 0001 and on; T.C. 3A25	SA808CE	Install Airborne wing and tail pneumatic deice kit 703C. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
320, 320-1, 320A, B, C, D, E, F, 340; T.C. 3A25	SA3231WE	Installation of recognition light assembly on horizontal stabilizer. Issued 7/8/76.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
320, 320A; T.C. 3A25	SA3239WE	Installation of nacelle baggage lockers. Issued 7/27/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, B, C, D, E, F; T.C. 3A25	SA3242WE	Installation of pilot's and co-pilot's side vent windows. Issued 7/30/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, 320B, 320C, 320D, 320E, 320F; T.C. 3A25	SA3822WE	Installation of 34-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
320, 320A thru 320F, 320-1, 340; T310P, T310Q; 401, 401A, B, 402, 402A, B; 411, 411A, 414, 421, 421A; T.C. 3A25, 3A10, A7CE, A7CE	SA1642WE	Modification of exhaust system components. Amended 12/7/73.	SW	87348	Wooley Tool & Manufacturing Div. Chromalloy American Corporation P.O. Box 3506 Odessa, TX 79760
320A, B, C, D, E, F, 340, 340A; T.C. 3A25	SA193RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Bellaire Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
320A, B, C, D, E, F, 320-1; T.C. 3A25	SA3164SW-D	Install automatic flight system AK584 consisting of Century IIB automatic pilot with optional radio coupler. Issued 11/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
320A thru 320D; T.C. 3A25	SA2339WE	Installation of exhaust bellows. Issued 4/12/71.	WE	01735	Aero Bellows Manufacturing Company 3211B Winona Avenue Burbank, CA 91504
320E, 320F; T.C. 3A25	SA4GL	Installation of Bendix FCS-810 autopilot flight director system. Issued 10/18/72.	GL	47767	Ralph Kerns Kerns Aircraft Electronics, Inc. Weir Cook Municipal Airport Indianapolis, IN 46206
320E, 320F; T.C. 3A25	SA2122WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Hartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76706
320F; T.C. 3A25	SA4012SW	Dual camera port. Issued 7/6/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
335, 340A; T.C. 3A25	SA1302CE	Install Enk Aviation fire suppression system. Amended 10/9/79.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
336; T.C. A2CE	SA203SW	Right front seat replaced with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, AR 72003
336; T.C. A2CE	SA286NW	Request for multiple STC on Model 336. Issued 4/23/76.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
336; T.C. A2CE	SA445SW	Automatic pilot AK140, pitch trim system AK141, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
336; T.C. A2CE	SA936CE	STOL Kit installation. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
336; T.C. A2CE	SA1260CE	Install FiQuench extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
336; T.C. A2CE	SA1355CE	Chrome-plated brake disc installation. Issued 6/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
336; T.C. A2CE	SA1875SW	Wing edge leading cuffs, wing tips, vortex generators on fuselage and fairing on vertical tails. Reissued 9/15/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
336, 337; T.C. A6CE, A2CE	SA1056SW	Revise wing contours leading edge and redesign landing light deflector plates. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
336, 337, 337A thru C; T.C. A6CE, A2CE	SA406CE	Hoskins Supp. Position Light System includes Model A wing tip lights, Model 2 fuselage light used as tail light or Model L tail light. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
337; T.C. A6CE	SA491SW	Automatic pilot AK135, automatic pitch trim AK156, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA668SW	AK210 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA1473CE	Installation of full microwave landing system with modified King KX175B and KN 73 receivers. Issued 2/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
337; T.C. A6CE	SA2200WE	Installation of Brittain Industries B2C and B5S flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
337, 337A, B, C, D, E, F, G, H, T337B, C, D, E, F, G, H, P337H; T.C. A6CE	SA385GL	Installation of Norton radome kit No. 4231X. Issued 2/1/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
337, 337A, B, C, D, E, F, G, M337B, T337B, C, D, E, F, G; T.C. A6CE	SA937CE	Installation of STOL kit (leading edge cuffs, stall fence, droop wing tips, and vortex generators on rear engine lower cowling). Amended 5/25/78.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
337, 337A, B, C, D, E, F, G, M337B, N337B, T337B, C, D, E, F, G; T.C. A6CE	SA1258CE	Installation of FIQUENCH fire extinguishing system in cabin and/or fire extinghishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
337, 337A, 337B, T337B, 337C, 337D, 337E, 337F, 337G; T.C. A6CE	SA1558SW	Vortex generators on fuselage, wing leading edge cuffs, wing tips, and fairings on vertical tail. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
337, 337A (USAF O2B), 337B, M337B (USAF O2A), 337C, T337B, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G; T.C. A6CE	SA1627WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, stall fences, aileron centering springs, conical cambered wing tips and flap actuated elevator trim spring. Also takeoff gross weight increase for all models except for T337G and 337G. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
337, 337A; T.C. A6CE	SA2335WE	Installation of one-piece windshield and relocation of compass. Reissued 5/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route 1, Box 127D Leesburg, FL 32748

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
337, 337A, B, C, D, E, F, G, M337B, T337B, T337C, T337D, T337E, T337F, T337G; T.C. A6CE	SA3056WE	Installation of fuel flow instruments. Issued 8/15/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
337, 337A, 337B, T377B, 337C, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G, T337P; T.C. A6CE	SA3818WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
337, T337, 337E, T337E; T.C. A6CE	SA1356CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
337, T377G; T.C. A6CE	SA478NW	Installation of RDR 160 weather radar. Issued 7/7/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
337A; T.C. A6CE	SA190SO	Cabin door removed and wind deflector installed.	SO	90106	Young, Isherwood & Marsh P.O. Box 982 Christiansted St. Croix, Virgin Islands
337A; T.C. A6CE	SA8018W	Mitchell AK244 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A thru 337H, T337B thru H, P337H; T.C. A6CE	SA32RM	Installation of electrically driven freon air-conditioning system. Amended 11/9/78.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA1922SW	Automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 10/11/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA3250SW-D	Mitchell automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 11/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337B; T.C. A6CE	SA842SW	AK252 consisting of Century III autopilot with optional pitch trim stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337D; T.C. A6CE	SA672CE	Install auxiliary fuel tank in baggage area.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
337D; T.C. A6CE	SA678CE	Install fuselage top emergency exit door.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
337D; T.C. A6CE	SA1038EA	Installation of recognition lights (ICGC) on trailing edge of Robertson wing tips. Issued 8/9/76.	EA	29998	DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
337D, T337D, 337G, T337G; T.C. A6CE	SA478NW	Installation of Bendix weather radar system. Amended 4/13/78.	NW	67135	Renton Aviation, Inc. 840 Perimeter Road Renton, WA 98055
337D, 337E, 337F, 337G, T337D, T337E, T337F; T337G; T.C. A6CE	SA482SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and flight direcotr indicator. Amended 7/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
337E, F; T.C. A6CE	SA1359SW	Mitchell automatic flight system FD/AP262-345 consisting of flight director/autopilot with optional pitch trim. Issued 5/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F; T.C. A6CE	SA1478SW	Mitchell automatic flight system AK345 consisting of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 6/9/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
337E, F,; T.C. A6CE	SA1520SW	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 10/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3148SW-D	Mitchell automatic flight system AK537 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3149SW-D	Mitchell automatic flight system AK536 consisting of Century IV autopilot or Model AK536FD flight director autopilot with optional remote annuciator. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3252SW-D	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 11/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337G; T.C. A6CE	SA1205CE	Installation of King KFC-200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/6/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
F337E, FT337E, F337F, FT337F, F337G, FT337GP; T.C. A23EU	SA1259CE	Install FiQuench fire extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
340 Series; T.C. 3A25	SA186NW	Installation of Continental TSIO-520-J engine. Issued 5/30/75.	NW	85165	Western Skyways Portland/Troutdale Airport Troutdale, OR 97060
340 Series; T.C. 3A25	SA474NW	Replace original split flaps with Fowler flaps.	NW	68500	Robertston Aircraft Corporation 939 West Perimeter Road Renton, WA 98055
340; T.C. 3A25	SA1357CE	Chrome-plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
340 Series; T.C. 3A25	SA1441SW	Mitchell automatic flight system AK367 consisting of Century III autopilot with optional automatic pitch trim, radio, and glide slope couplers. Issued 3/15/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA1442SW	Mitchell automatic flight system FD/AP282-367 consisting of flight director/autopilot with automatic electric trim. Issued 3/3/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA1881SW	Continental TSIO-520-J engine. Issued 5/23/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
340 Series; T.C. 3A25	SA1979SW	In-line fuel pumps for auxiliary tanks. Issued 5/8/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
340 Series; T.C. 3A25	SA2346SW	Teledyne Continental TSIO-520-N engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340; T.C. 3A25	SA2770SW	Cleveland heavy duty brakes. Issued 5/9/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
340 Series; T.C. 3A25	SA3043SW-D	Mitchell automatic flight system AK525 or AK525 FD consisting of Century IV autopilot with command/automatic electric pitch trim system and optional remote annuciator panel. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340 Series; T.C. 3A25	SA3044SW-D	Mitchell automatic flight system YK525 consisting of yaw damper system. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340; T.C. 3A25	SA3485WE	Installation of Continental TSIO-520-K engines and increase takeoff power to 310 h.p. Amended 11/18/77.	WE	68120	Riley Aircraft Corporation 2383 Palomar Airport Road Carlsbad, CA 92008
340, 340A; T.C. 3A25	SA16RM	Installation of freon type air conditioning system. Amended 10/6/77.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
340, 340A; T.C. 3A25	SA281GL	Install Cleveland conversion kit P/N 199-72. Issued 11/8/78	GL	23260	Cleveland Wheels and Brakes Van Sickle Div. of Parker Hannifin 1160 Center Road Avon, OH 44011
340, 340A; T.C. 3A25	SA502SO	Installation of Bendix FCS-810 automatic flight control system including manual eletric trim and optional flight director indicator DB-841. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340, 340A; T.C. 3A25	SA914EA	Installation of Radome kit P/N 4057KX. Amended 5/24/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
340, 340A; T.C. 3A25	SA1062CE	Installation of Collins AP-107 autopilot. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
340, 340A; T.C. 3A25	SA2483SW	Increase seating capacity on aft baggage shelf for a total of 7 occupants. Reissued 3/20/78.	SW	66300	RAM Aircraft Modification P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340, 340A; T.C. 3A25	SA2844SW	Installation of SDI Model CFS-2000, -2001, or FT-200 indicating fuel flow system. Amended 3/5/79.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
340, 340A; T.C. 3A25	SA3871WE	Installation of vapor cycle air conditioning system. Issued 1/15/80.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
340, 340A (S/Ns 340A0001 thru 340A0600); T.C. 3A25	SA3923WE	Installation of Lycoming TIO-540-R2AD engines. Issued 6/1/79.	WE	68120	Riley Aircraft Corporation 2016 Palomar Airport Road Carlsbad, CA 92008
340-0001 and on; T.C. 3A25	SA55GL	Install Airborne wing and tail pneumatic deice kit 710. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
340A; T.C. 3A25	SA1015SO	Installation of Bendix FCS-870 automatic flight control system, including manual electric trim and optional flight director system. Issued 8/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340A; T.C. 3A25	SA1025SO	Installation of a Bendix NP-2041A area navigation computer programmer. Issued 10/4/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340A; T.C. 3A25	SA1276CE	Install King KFC 200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or KG-258 attitude horizon gyro and a KC-292 mode controller. Amended 5/8/78	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
304A; T.C. 3A25	SA1551CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
340A; T.C. 3A25	SA3610WE	Installation of Silver Instruments Fueltron IIIS fuel indicating system. Issued 3/15/78.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, 421B, 421C; T.C. A7CE	SA197GL	Install Cleveland conversion kit P/N 199-76. Amended 8/28/78.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Ind., Inc. 1160 Center Road Avon, OH 44011
401, 401A, 401B, 402, 402A, 402B (normal category); T.C. A7CE	SA29NW	Installation of Fowler Flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 2/23/73.	NW	68500	Robertson Aircraft Corporation Renton Municipal Airport Renton, WA 98055
401, 401A, 402, 402A, 402B, 414; T.C. A7CE	SA109RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA117NW	Installation of Allison 250-B17 or 250-B17B engines and related changes. Reissued 1/6/77.	WE	25640	Commuter Investment and Development Corporation 2800 Clybourn Avenue Van Nuys, CA 91406
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA167GL	Install Cleveland conversion kit P/N 199-72. Issued 4/15/77.	GL	23260	Cleveland Wheels and Brakes Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011
401, 401A, 402, 402A, B, 414; T.C. A7CE	SA194RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
401, 402, 411, 411A, 401A, 401B; T.C. A7CE	SA346EA	Installation of Chamberlain radome kit No. 2022X-B for Bendix RDR-100 or RDR-110 series radar system. Amended 7/30/71.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A; T.C. A7CE	SA437EA	Installation of radome P/N 2022X. Amended 5/27/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A, 414, 421, 421A; T.C. A7CE	SA438EA	Installation of Norton radome kit No. 2022X-3. Amended 11/2/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
401A, 401B, 402A, B, 414, 421, 421A, 421B; T.C. A7CE	SA465SO	Installation of Bendix FCS-810 automatic flight control system including flight director indicator DH-841( ) and manual electric trim. Amended 6/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA618SO	Installation of M-4B or M-4C automatic flight control systems. Amended 4/27/73.	SO	15475	The Bendix Corporation Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA646CE	Install wing and tail pneumatic deice kit 702A on 401/402 aircraft (S/N 0135 and above), kit 702B on 414 aircraft and kit 702C on 401/402 aircraft (S/N 0001 through 0134 only). Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
401, 401A, B; T.C. A6CE	SA1158SW	Mitchell automatic flight system FD/AP282-302 consisting of flight director/automatic pilot and automatic pitch trim. Issued 6/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, 401B, 402, 402A; T.C. A7CE	SA1206SW	Edo-Aire Mitchell automatic flight system AK302, consisting of Century III autopilot with optional pitch trim, radio, and glide slope couplers. Issued 10/23/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, B, C; T.C. A7CE	SA1326CE	Installation of Avcon Industries TSO C39a stretcher. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
401, 401A, 402, 402A, 411, 411A, 414; T.C. A7CE	SA1358CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 414A, 421, 421A, 421B, 421C; T.C. A7CE	SA1393CE	Install forward baggage door warning system. Issued 1/3/78.	CE	84955	Wells Aircraft, Inc. Municipal Airport Hutchinson, KS 67501
401, 401A all S/N's, 402, 402A, 402B thru S/N 0300, 411, 411A all S/N's, 414 thru S/N 0350, 421, 421A, 421B thru 0300; T.C. A7CE	SA2091WE	Installation of air conditioning system. Amended 5/21/79.	PM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
401, 401A, B, 402, 402A, B; T.C. A7CE	SA2845SW	Symbolic Displays CFS-2000 electronic fuel flow metering system. Issued 9/8/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
401*, 401A*, 401B*, 402*, 402A*, 402B*, 402C, 411, 411A, 414*, 414A, 421, 421A, 421B, 421C; *Includes those models modified per STC SA117NW.	SA3003WE	Installation of recognition light assembly on horizontal stabilizer. Amended 2/26/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 94665
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 421, 421A, 421B; T.C. A7CE	SA3017WE	Installation of fuel flow instruments.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
401, A, B, 402, 402A; T.C. A7CE	SA3057SW-D	Mitchell automatic flight system AK538 or AK435FD consisting of Century IV autopilot or Century IV flight director autopilot with command/autopilot electric pitch trim and annuciator. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, B, 402; T.C. A7CE	SA3058SW-D	Mitchell flight system YK535 consisting of yaw damper system. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA3838WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box 6151 Van Nuys, CA 91409
401, 401A, 401B, 402, 402A, 402B, 414 thru S/N 414-0350;	SA3930WE	Installation of 37.5 gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA4117WE	Installation of Silver Instruments fueltron 111G or fueltron 111P digital fuel flow and totalizer system. Issued 3/13/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
T.C. A7CE					
401, 402; T.C. A7CE	SA784SW	Mitchell Model AK240 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 402; T.C. A6CE	SA1472WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402; T.C. A6CE	SA1599WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402, 411; T.C. A7CE	SA472EA	SAGA (Semi-automatic gear actuating) system. Amended 5/23/67.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
401A; T.C. A7CE	SA3192WE	Installation of single global and dual global GNS-500A navigation system. Amended 3/23/79.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
402; T.C. A7CE	SA634CE	Install tenth seat and attach FAA approved AFMS.	CE	36000	FloAir, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
402; T.C. A7CE	SA1742SW	Vapor cycle air conditioning system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
402; T.C. A7CE	SA1863SW	Two cameras and navigation sight. Issued 5/7/74.	SW	42825	A.D. Howard, Jr. 6817 N.W. 43rd Street Bethany, OK 73008
402; T.C. A7CE	SA2424WE	Installation of Allison 250-B17 engines and related changes. Amended 9/21/73.	WE	10208	American Jet Industries 3021 Airport Avenue Santa Monica, CA 90405
402, 402A; T.C. A7CE	SA2333SW	Fiberglass tailcone for magnetometer. Issued 7/23/76.	SW	42825	A.D. Howard, Jr. 1911 Moulton Court Oklahoma City, OK 73127
402A, B, C, 421B, C, 414A; T.C. A7CE	SA807EA	Installation of Norton Radome Kit No. 4009X. Reissued 5/6/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
402B; T.C. A7CE	SA700CE	Install right-hand side rear window.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
402B; T.C. A7CE	SA1061CE	Installation of Collins Company AP-107 (3 axis) autopilot system. Issued January 1975.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1110CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1111CE-D	Installation of AP-107 autopilot (2 axis). Amended June 1976.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1501CE	Sierra utility flight inspection equipment rack installed in left hand side forward location. Issued 7/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
402B, 402C; T.C. A7CE	SA1303CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
402B (S/Ns 402B0301 and up), 414 (S/Ns 414-0351 and up), 414A (S/Ns 414A0001 and up), 421B (S/Ns 421B0001 and up); 421C (S/Ns 421C001 and up) (6, 7, 8, 9 or 10 place); T.C. A7CE	SA8RM	Installation of Freon type air-conditioning system. Amended 1/12/78.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
402B, 414, 421B; T.C. A7CE	SA547SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim and optional flight director system in serial numbers 402B0301 and up, 4140351 and up, and 421B0301 and up. Issued 8/17/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
402B, 414, 421B; T.C. A7CE	SA584SO	Installation of Bendix YD-4 yaw damper system. Issued 4/5/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
402C; T.C. A7CE	SA1502CE	Install King KFC200 automatic flight control system. Issued 7/11/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
402C, 414A, 421C; T.C. A7CE	SA1526CE-D	Installation of King KAS 297 altitude selector option. Issued 2/6/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404, S/N 404-0001 and up; T.C. A25CE	SA143RM	Installation of air conditioner system. Issued 6/2/78.	RM	45750	J B Systems, Inc. P.O. Box 800 Longmont, CO 80501
404; T.C. A25CE	SA195GL	Installation of Norton radome kit 4009X.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
404; T.C. A25CE	SA195RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
404; T.C. A25CE	SA721NW	Installation of camera bays. Issued 2/23/79.	NW	85165	Western Skyways Portland-Troutdale Airport Troutdale, OR 97060
404; T.C. A25CE	SA1297CE	Installation of King KFC 200 2-axis (3 optional), flight control system with a KI-255 (or -256) flight command indicator, or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 5/11/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA1482CE	Installation of Tull microwave landing system. Issued 4/9/79.	CE	81650	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
404; T.C. A25CE	SA1304CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
404; T.C. A25CE	SA1528CE-D	Installation of King KAS 297 altitude selector option. Issued 2/18/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA3384WE	Removal of cargo doors and installation of P/N A770000 airstream deflector. Issued 6/8/77.	WE	07630	Airflite, Inc., South 2700 East Wardlow Road Long Beach, CA 90801
404; T.C. A25CE	SA3388WE	Installation of recognition lights on horizontal stabilizer. Issued 4/29/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
404; T.C. A25CE	SA4017WE	Installation of SDI model CFS-2000, -2001, or FI-200 fuel flow indicating system. Issued 8/31/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
404; T.C. A25CE	SA4105WE	Installation of tail stinger and/or nose stinger. Issued 2/21/80.	WE	77500	Tallmantz Aviation, Inc. 19711 South Airport Way Santa Ana, CA 92707
411 Series; T.C. A7CE	SA402CE	50-gallon auxiliary fuel tank.	CE	36000	Floair, Inc. Municipal Airport Newton, KS 67114
411 Series; T.C. A7CE	SA515SW	Automatic pilot AK158, lateral guidance radio coupler AK123 and automatic trim system AK159.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA681SW	AK221 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA839EA	Installation of Radome Kit P/N 4009X-B for Bendix RDR-100 and RDR-110 systems - 12" antenna. Amended 11/29/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
411 Series; T.C. A7CE	SA1227WA	Installation of Brittain Model B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
411 Series; T.C. A7CE	SA1467WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
411 Series; T.C. A7CE	SA2378WE	Installation of Global Navigation Model GNS-200 VLF navigation system. Amended 2/26/74.	WE	38090	Global Navigation, Inc. 2733 Pacific Coast Highway Torrance, CA 90505
411 Series; T.C. A7CE	SA2913WE	Installation of GNS-500 VLF navigation system. Amended 2/28/75.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
411 Series; T.C. A7CE	SA3138WE	Installation of GNS-500A VLF/OMAGE navigation system. Amended 1/17/77.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
411, 411A Series; T.C. A7CE	SA1120WE	Bendix automatic flight control system type M4B and M4C.	SO	15475	The Bendix Corporation Avionics Products Fort Lauderdale, FL 33310
400, 411A, 421, 421A; T.C. A7CE	SA102RM	Installation of exhaust turbo connector, P/N 042177-5. Issued 5/19/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street Denver, CO 80207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
411, 411A, 421, 421A, 421B; T.C. A7CE	SA108RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless, sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
411, 421; T.C. A7CE	SA487CE	Install windshield wipers.	GL	27500	Marquette Metal Products Company Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
414; T.C. A7CE	SA48NW	Installation of fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 6/29/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
414; T.C. A7CE	SA433SO	Installation of Bendix Model M4C flight control system. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
414; T.C. A7CE	SA1040CE	Installation of AP-107 autopilot. Amended 10/2/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
414; T.C. A7CE	SA1219SW	Mitchell automatic flight system AK308 consisting of Century III with automatic pitch trim, radio, and glide slope couplers. Issued 11/18/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA1899SW	Freon air conditioning system. Issued 9/9/74.	SW	37154	Gen-Aero, Inc. P.O. Box 16278 San Antonio, TX 78246
414; T.C. A7CE	SA1220SW	Mitchell automatic flight system Model FD/AP282-308 consisting of flight director/autopilot, autopilot pitch trim. Issued 11/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA2354SW	Teledyne Continental TSIO-520-N, -J, engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
414; T.C. A7CE	SA2812SW	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
414; T.C. A7CE	SA3334SW-D	Mitchell automatic flight system AK624 consisting of Century IV autopilot or AK624FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3335SW-D	Mitchell yaw damper system, YK628. Issued 3/6/69.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3666WE	Installation of Silver Instruments Fueltron IIIG digital fuel flow and totalizer system. Issued 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
414; T.C. A7CE	SA3682WE	Installation of Continental TSIO-520-N engine and associated installation components. Issued 7/12/78.	WE	68120	Riley Aircraft Corporation 2386 Palomar Airport Road Carlsbad, CA 92008
414A T.C. A7CE	SA985SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director and optional yaw damper. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
414A; T.C. A7CE	SA986SO	Installation of Bendix NP-2041A NP-2041A area navigation computer programmer. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
414A; T.C. A7CE	SA1400CE	Install Enk Aviation fire suppression system. Issued 2/9/78.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
414A; T.C. A7CE	SA1431CE	Install King KFC-200 flight control system with or without flight director. Issued 8/31/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
414A; T.C. A7CE	SA1521CE-D	Installation of King KFC 250 flight control system. Issued 11/14/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathes, KS 66061
414A; T.C. A7CE	SA3304SW-D	Mitchell automatic flight system AK774/FD consisting of Century IV/ flight director autopilot with optional remote annunciator.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414, 421; T.C. A7CE	SA536CE	Install electrical connectors in pressure bulkhead(s) at Station(s) 100 and/or 273.94. Amended 12/4/70.	RM	05940	Charles C. Peacock Aircraft Radio & Accessory Co., Inc. Hangar #4, Stapleton Field Denver, CO 80207
414, 421A; T.C. A7CE	SA732EA	Installation of radome Part No. 4004X. Amended 5/12/75.	GL	61750	Norton Company Plastics & Synethetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
414, 421A; T.C. A7CE	SA780EA	Installation of Radome Kit No. 4004X-B for Bendix RDR-100 or RDR-110 series radar systems - 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
414, 421, 421A, B, C; T.C. A7CE	SA2440SW	Airstair door saver. Issued 3/23/77.	SW	00060	AAR of Oklahoma, Inc. P.O. Box 19508 Oklahoma City, OK 73119
421 Series; T.C. A7CE	SA574CE	Installation of toilet seat belt.	CE	36000	Proair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
421 Series; T.C. A7CE	SA591EA	Installation of Radome Part Part No. 3084X. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
421 Series; T.C. A7CE	SA661EA	Installation of Radome Kit No. 3084X for Bendix RDR-100 or RDR-110 series radar systems 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
421 Series; T.C. A7CE	SA662CE	Installation of Jet Electronics & Technology, Inc. Model FC120A autopilot.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street Grand Rapids, MI 49508
421 Series; T.C. A7CE	SA673CE	Install Hartzell HC-E3WF-2/9349-3 propellers.	GL	41000	Hartzell Propellers, Inc. 350 Washington Avenue P.O. Box 909 Piqua, OH
421 Series; T.C. A7CE	SA968SW	Mitchell automatic flight system AK279 consisting of Century II autopilot with optional automatic pitch trim, radio, and glide slope couplers, automatic aileron stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421 Series; T.C. A7CE	SA976SW	Collins FD108 flight director system.	SW	06000	Aircraftsmen, Inc. Box 82516 Oklahoma City, OK 73108
421 Series; T.C. A7CE	SA1776WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
421, 421A; T.C. A7CE	SA794CE	Install vapor cycle air conditioning system. Reissued 10/15/71.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
421, 421A; T.C. A7CE	SA1897WE	Installation of a seventh seat in aft baggage compartment.	RM	25250	Combs Aircraft, Inc. Stapleton International Airport Denver, CO 80207
421, 421A, 421B; T.C. A7CE	SA2RM	Installation of a seventh seat in aft baggage compartment. Reissued 4/6/73.	RM	25250	Combs - Gates Denver, Inc. Stapleton International Airport Denver, CO 80207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
421, 421A, 421B; T.C. A7CE	SA18NW	Installation of Fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 4/13/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
421, 421A, 421B; T.C. A7CE	SA632SO	Installation of Bendix model M-4C automatic flight control system, including manual electric trim. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33309
421, 421A, 421B; T.C. A7CE	SA1200CE	Installation of FiQuench cabin and/or engine fire extinguishant system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
421, 421A, 421B; T.C. A7CE	SA1210CE	Installation of Banion & Wilson exhaust systems, P/N 8108-59 and P/N 8109-59 or P/N 8108-159 and 8109-159. Amended 3/19/80.	EA	40350	Hanlon & Wilson Company P.O. Box 641 Jeanette, PA 15644
421, 421A, 421B, 421C; T.C. A7CE	SA1343CE	Install Sierra data console on left hand seat rails. Reissued 9/15/77.	CE	71660	Sierra Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, 421B, 421C; T.C. A7CE	SA1375CE	Reduce height of existing survival seat. Reissued 10/3/77.	EA	71660	Sierra Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, B, C; T.C. A7CE	SA3228WE	Installation of Silver Instruments Fueltron IIIG or IIIP fuel indicating system. Amended 1/11/80.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545
421B; T.C. A7CE	SA135GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 10/26/76.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
421B; T.C. A7CE	SA952CE	Installation of King Radio Model KFC-300 automatic flight control system. Amended 12/19/75.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA986CE	Installation of Collins Radio Group AP-106 autopilot system. Amended January 1977.	CE	24250	Collins Radio Group Avionics Certification Center Cedar Rapids, IA 52406
421B; T.C. A7CE	SA987CE	Installation of Sperry SPZ-200/ STARS IVC automatic flight control system with optional Sperry AA-220/ RT-220 radar altimeter. Issued February 1974.	CE	90080	Yingling Aircraft, Inc. P.O. Box 1162 Wichita, KS 67201
421B; T.C. A7CE	SA1001CE	Installation of H-14 autopilot. Issued April 1974.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA1035CE	Installation of openable window aft of cabin door. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
421B; T.C. A7CE	SA1167CE	Installation of AP 107 autopilot (2 axis). Serials 301 and subsequent. Issued 3/29/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1667SW	Mitchell automatic flight system Model YK385 consisting of yaw damper. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421B; T.C. A7CE	SA1168CE	Installation of Collins Radio Group AP-107, 3 axis, autopilot system and interface with Collins 329A-4V indicator. Serials 301 and subsequent. Issued 10/20/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1668SW	Mitchell automatic flight system AK407, consisting of Century IV autopilot with trim; or AK407/FD consisting of Century IV autopilot/ flight director with trim. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421B; T.C. A7CE	SA2749WE	Installation of Lear AFC-70 AP/FD steering computer system. Issued 8/23/73.	WE	49650	LearAvia Corporation Avionics Division 14505 Mt. Anderson Reno, NV 89510

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
421B; T.C. A7CE	SA2810WE	Installation of Collins AP-105 autopilot and FD-108 flight director systems. Issued 1/30/74.	WE	78622	Tower Avionics Center Hangar 8, Oakland Int'l Airport Oakland, CA 94614
421B; T.C. A7CE	SA3881WE	Installation of dual elevator trim tab actuator. Issued 3/14/79.	WE	68120	Riley Aircraft Corporation 2386 Palomar Airport Road Carlsbad, CA 92008
421C; T.C. A7CE	SA196RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welidng Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
421C; T.C. A7CE	SA438NW	Replace original split flaps with Fowler flaps. Issued 4/22/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
421C; T.C. A7CE	SA886SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 2/26/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA890SO	Installation of Bendix FCS-810 automatic flight control system including manual electric pitch and optional flight director indicator. Amended 11/1/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA1120CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1121CE	Installation of Collins Radio Group AP-107 (2 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1122CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1191EA	Installation of Hanlon & Wilson exhaust system P/N 8294-1(L.H) and 8294-2(R.H.) Issued 4/2/80.	EA	40350	Hanlon & Wilson Company P.O. Box 641 Jeanette, PA 15644
421C; T.C. A7CE	SA1246CE	Install King KFC-200 2 axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/4/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
421C; T.C. A7CE	SA1305CE	Install Enk Aviation fire suppression system. Issued 8/30/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
421C; T.C. A7CE	SA3110SW-D	Mitchell automatic flight system AK579, consisting of Century IV autopilot or AK579FD, consisting of Century IV flight director autopilot with remote annuciator. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3111SW-D	Mitchell yaw damper YK580. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3456WE	Modification of fuselage to install camera window. Issued 7/14/77.	WE	84000	Volpar, Inc. 7929 Hayvenhurst Avenue Van Nuys, CA 91406
441; T.C. A28CE	SA1424CE	Install Sierra Electronics console. Reissued 7/3/78.	EA	71660	Sierra Research Corp. P.O. Box 222 Buffalo, NY 14225
441; T.C. A28CE	SA2818SW	Install three place side facing couch. Issued 7/19/78.	SW	08540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
441; T.C. A28CE	SA3498WE	Installation of tail flood light on horizontal stabilizer. Issued 10/18/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
500 Series; T.C. A22CE	SA8GL	Installation of engine synchronizer kit P/N 213522. Issued 4/18/73.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500 Series; T.C. A22CE	SA13RM	Installation of Branson cargo liner and retention system. Issued 7/23/73.	RM	05752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207
500 Series; T.C. A22CE	SA15RM	Installation of three-place couch with or without quick change aft divider. Amended 4/2/76.	RM	05752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207
500 Series; T.C. A22CE	SA18RM	Install beverage service buffet in baggage compartment. Issued 11/21/73.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA19RM	Install two lounge seats in rear of baggage compartment. Amended 11/8/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA23RM	Installation of aft beverage cabinet, P/N 90241-1. Amended 5/20/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA47RM	Installation of single seat in the center of aft baggage compartment. Reissued 3/10/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
500 Series; T.C. A22CE	SA51RM	Installation of tail cone ski rack. Reissued 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series T.C. A22C	SA52RM	Installation of stretcher. Amended 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series; T.C. A22CE	SA54RM	Installation of tail cone storage box and engine cover storage box. Amended 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA58RM	Installation of deluxe three-place aft couch. Amended 10/7/77.	RM	17085	Branson Engineering Company, Inc. 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA79RM	Installation of side-looking camera hatch. Reissued 7/29/77.	CE	20625	Cessna Aircraft Company Wichita Municipal Airport P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA83RM	Increased ramp and takeoff weights for restricted category operation. Issued 10/22/76.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA97RM	Installation of dual aft lounge seats. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA100RM	Installation of lounge seat toilet. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 46th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	ST131RM	Installation of Global Navigation, Inc. GNS-500A VLF/Omega navigation system. Issued 2/7/78.	RM	14127	Avionics Engineering of Denver, Inc. 8695 Montview Boulevard Hangar B Denver, CO 80220
500; T.C. A22CE	ST174RM	Installation of extended width cabin door. Issued 5/4/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500; T.C. A22CE	SA645NW	Increased fuel and performance modifications. Issued 8/4/78.	NW	12270	Astec Engineering, Inc. 830 N. Riverside Drive Renton, WA 98055
500; T.C. A22CE	SA802NW	Installation of transponder identification switch on left hand control wheel. Issued 7/13/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
500 Series; T.C. A22CE	SA897SO	Installation of Teledyne P/N EB638/T- Series lead-acid replacement battery. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
500 (S/N 500-001 thru -0213); T.C. A22CE	SA991CE	Installation of KFC-300 automatic flight control system. Amended 4/10/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
500 Series; T.C. A22CE	SA1013CE	Installation of retractable aircraft recognition lights. Amended 7/26/78.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500 Series; T.C. A22CE	SA1059EA	Installation of an airways calibration system. Reissued 9/27/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 (S/N 350 and on); T.C. A22CE	SA1371CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 Series; T.C. A22CE	SA1574SW	Installation of hassock according to Qualitron Aero. Reissued 5/30/79.	RM	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500; T.C. A22CE	SA1579CE	Installation of tail-cone baggage compartment. Issued 3/7/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
500 Series; T.C. A22CE	SA1589SW	Installation of Singer Kearfott SKK-1000A doppler system; Collins INS-61B inertial navigation system; JET PS 823B emergency power system. Reissued 11/20/73.	CE	20225	Cessna Aircraft Company P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA1597SW	Stretcher installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 N. Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1619SW	Installation of emergency power supply according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1727SW	Jump seat. Issued 9/13/73.	SW	12250	Associated Radio Service Company Box 20718 Dallas, TX 75220
500 Series; T.C. A22CE	SA1945SW	Aft equipment bay storage unit. Issued 1/7/75.	SW	38242	William L. Goin, Jr. 7930 Airport Boulevard Houston, TX 77017
500 Series; T.C. A22CE	SA2383SW	Install refreshment bar and galley bulkhead. Issued 11/19/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
500 Series; T.C. A22CE	SA2925WE	Installation of power brake and skid control system. Issued 9/24/74.	WE	13230	Aviation Brake Systems, Ltd. 3535 West 5th Street Oxnard, CA 93030
500, 501; T.C. A22CE	SA2698SW	Freon air conditioning system. Issued 12/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
500, 501; T.C. A22CE, A27CE	SA2883SW	Installation of Ray Electronics Model 7507A battery current monitoring system. Issued 12/7/78.	SW	66500	Ray Electronics Company 11933 Warfield Drive San Antonio, TX 78216
500, 501, 550, 551; T.C. A22CE, A27CE	SA105180	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid battery. Issued 3/29/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
500, 501, 550, 551; T.C. A27CE, A22CE	SA2916SW	Installation of alternate gear horn switch. Issued 2/26/79.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
500, 501, 550, 551; T.C. A27CE, A22CE	SA4054SW	Installation of one, two, or three-place side facing seat, frame only. Issued 10/23/79.	SW	28000	Custom Aircraft Conversions 234 West Turbo Drive San Antonio, TX 78216
500, 550; T.C. A22CE	SA808RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Amended 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST151RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST166RM	Installation of three-place or single-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST174RM	Installation of extended width cabin door. Amended 5/18/79.	CE	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	SA1457CE	Install microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127

Aircraft Make, Model & T.C. No.	STC No.	Description	Rg	STC Code	STC Holder
500, 550; T.C. A22CE	SA1513CE	Installation of Avcon 4001-213 and -214 stretcher. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
500, 550; T.C. A22CE	SA1534CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
500, 550; T.C. A22CE	SA2906WE	Installation of vertical tail floodlights on horizontal Amended 8/30/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
500, 550; T.C. A22CE	SA3000SW	Fabrication and installation of 3-place side facing couch and shoulder harness. Issued 5/25/79.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
501; T.C. A27CE	ST117RM	Installation of deluxe three-place aft couch. Issued 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	ST118RM	Installation of tail cone storage box and engine cover storage box. Issued 10/22/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	SA125RM	Installation of tail cone ski rack. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit E Denver, CO 80216
501; T.C. A27CE	SA126RM	Installation of stretcher. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit E Denver, CO 80216
501; T.C. A27CE	SA152RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Issued 9/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit E Denver, CO 80216
501; T.C. A27CE	SA177RM	Installation of a single seat in the center of aft baggage compartment. Issued 6/25/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit E Denver, CO 80216
501; T.C. A27CE	SA732NW	Installation of "Eagle" performance kit. Issued 5/10/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
501; T.C. A27CE	SA1372CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
501; T.C. A27CE	SA1423CE	Insalll King KFC-300 AFCS with duel flight director and transferable autopilot. Issued 6/21/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
501; T.C. A27CE	SA1560CE	Installation of tail-cone baggage compartment. Issued 3/7/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
501, 551; T.C. A27CE	SA150RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA171RM	Installation of three-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA1514CE	Installation of Avcon 4001-213 and -214 stretchers. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA1535CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA3409WE	Installation of vertical tail floodlights on horizontal stabilizer. Amended 8/30/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
550; T.C. A22CE	ST165RM	Installation of fiberglass tail cone in lieu of metal tail cone. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
550; T.C. A22CE	SA1499CE	Installation of Total Flood (TFC) Halon 1301 fuselage flood system. Issued 7/11/79.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
551; T.C. A27CE	SA1500CE	Installation of Total Flood (TFC) Halon 1301 fuselage flood system. Issued 7/11/79.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
CH-1C; T.C. 3H10	SH4WE	Fifth passenger seat and seat belt.	NW	84625	Washington Aircraft & Transport Co. Boeing Field Seattle, WA 98101
Miscellaneous	SA582NW	Replacement wire rope cable assemblies. Issued 5/12/78.	NW	81180	University Swedging 800 N.W. 46th Street Seattle, WA 98108

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

COSTRUZIONI AERONAUTICHE GIOVANNI AGUSTA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A109, A109A; T.C. H7EU	SH1190EA	Installation of Aircraft Parts Corp. (APC) starter-generator, P/N 150SG1110. Issued 4/1/80.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
A109A; T.C. H7EU	SH1135EA	Installation of a Collins ANS-31A area navigation system. Collins DME-40 system and miscellaneous avionic modifications. Amended 12/19/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15003 Wilmington, DE [illegible]9356
A109A; T.C. H7EU	SH2699SW	Stability augmentation/avionics equipment and cockpit modification for certification of single and pilot day-night (IMC) operations. Issued 5/18/78.	SW	12496	Atlantic Aviation Wm. P. Hobby Airport P.O. Drawer 1278[illegible] Houston, TX 77017

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DHC-2, MK1; T.C. A-606	SA456NW	Installation of auxiliary seaplane stabilizer fins. Issued 6/2/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK 1; T.C. A-806	SA527AL	Removal of left rear door for parachute jumping. Issued 8/9/74.	AL	19906	A. Dean Carreil 7100 Lake Otis Parkway Anchorage, AK 99507
Beaver DHC-2, MK 1; T.C. 806	SA1913WE	Installation of EDO Model 679-4930 floats. Amended and reissued 8/27/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
DHC-2, MK 1; T.C. A-806	SA2520WE	Hatch installation in Bristol amphibious floats. Issued 4/28/72.	NW	61626	North Country, Inc. 2525 14th Avenue South Seattle, WA 98168
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14(14V) or -28(28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA800EA	Installation of Aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W (red/white), or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
Otter DHC-3; T.C. 815	SA4-183	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
Otter DHC-3; T.C. 815	SA135NW	Installation of Sorm Industries bulk cargo tank. Issued 11/15/74.	NW	73820	Sorm Industries 7999 Perimeter Road Seattle, WA 98108
Otter DHC-3; T.C. 815	SA336NW	Installation of Hamilton Standard 23D40-311/6601A-7 propeller. Issued 8/18/76.	NW	40517	Harold J. Hansen 20602 - 135th Avenue South Seattle, WA 98148
DHC-3; T.C. A-815	SA678NW	Installation of Edo Model 56-7850A floats. Issued 10/17/78.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-6; T.C. A9EA	SA106NW	Installation of emergency exit on each side of fuselage. Amended 5/17/74.	EA	71910	S K Aircraft Company 16 Shotgun Lane Levittown, NY 11756
DHC-6; T.C. A9EA	SA235NW	Modification of cabin compartment airstair door. Issued 11/5/75.	NW	08360	Air Transport Industry Jet Air Hangar, Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA570NW	Installation of new interior interior panel. Issued 2/28/78.	NW	08360	Air Transport Industries Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA841EA	Installation of radome and support bracketry for RCA AVQ-45 antenna and radar units. Issued 9/10/70.	EA	35300	Field Aviation Company Limited Toronto International Airport Malton, Ontario, Canada
DHC-6 T.C. A9EA	SA1837WE	Installation of freon air conditioning system. Amended 8/25/77.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
DHC-6; T.C. A9EA	SA2366WE	Installation of emblem lights at mid span of horizontal stabilizer. Issued 7/2/71.	WE	30000	DeVore Aviation Service Corp. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DHC-6; T.C. A9EA	SA3816WE	Installation of underseat baggage restraint bar. Amended 3/2/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
DHC-6-100, -200, -300; T.C. A9EA	SA207GL	Install airborne fuel booster pump Model 1D2-14. Issued 1/10/78.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
DHC-6-100, -200, -300; T.C. A9EA	SA357AL	Installation of bulk fluid cargo tanks. Amended 5/15/72.	NW	78820	Sorm Industries 7999 Perimeter Road South Seattle, WA 98108
DHC-6-100, -200, -300; T.C. A9EA	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DHC-6 Series 100, 200; 300; T.C. A9EA	SA943EA	Replacement of deHavilland wing bleed air ducting with alternate ducting. Reissued 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
DHC-6-100, -200, -300; T.C. A9EA	SA998EA	Installation of engine fuel drain recirculation system. Reissued 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
DHC-6 Series 100, 200; 300; T.C. A9EA	SA2516WE	Installation of lightning arrestors on wing tips and vertical fin. Issued 9/19/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6-100, -200, -300; T.C. A9EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
DHC-6 Series 100, 200, 300; T.C. A9EA	SA2608WE	Installation of equivalent modifications to deHavilland modifications. Issued 11/3/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2553WE	Installation of Adel cannister fuel pumps. Reissued 8/24/72.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2898WE	Installation of a fuel tank boost pump. Issued 6/14/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, S/N 130, 210, 231 and subsequent; T.C. A9EA	SA1117CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
DHC-6-200; T.C. A9EA	SA771EA	Installation of Dual Mark 15 Decca Systems.	EA	61542	New York Airways, Inc. P.O. Box 426 LaGuardia Airport Station Flushing, NY 11371
DHC-6-200; T.C. A9EA	SA3103WE	Removal of left-hand cargo doors to permit aircraft to engage in special operations, i.e. parachute jumping, aerial photography, etc. Issued 10/24/75.	WE	38250	Golden West Airlines, Inc. 5801 W. Imperial Highway Los Angeles, CA 90045
DHC-6-300; T.C. A9EA	SA130RM	Installation of dual-SELCAL system. Issued 1/28/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA132RM	Change in Airplane Flight Manual operating limitations to permit landings with air-operable jump-door open. Issued 2/15/78.	RM	07701	Department of the Air Force Hq., Aerospace Defense Command Peterson AFB, CO 80914
DHC-6-300; T.C. A9EA	SA135RM	Installation of Leach P/N V110-D-032-AC overvoltage relays. Issued 3/3/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA170NW	Installation of bulk fluid cargo tank for carriage on non-flamable, non-corrosive, non-toxic liquids. Issued 4/3/75.	WE	73820	Sorm Industries 7999 Perimeter Road Seattle, WA 98106
DHC-6-300; T.C. A9EA	SA185RM	Installation of Bendix RDR-160 weather radar system. Issued 10/26/79.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-7-100; T.C. A20EA	ST127RM	Supplemental oxygen system installation. Issued 2/2/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
DHC-7-100; T.C. A20EA	ST128RM	Installation of ground proximity warning system, Collins FPC-75. Issued 1/23/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
D.H. 104 Dove Series; T.C. 807	SA1-72	Three-place seat.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, Oh 45377
D.H. 104 Dove Series; T.C. 807	SA1-73	39-gallon auxiliary fuel tank in cabin with 3-place seat per STC SA1-72.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, Oh 45377
D.H. 104 Dove Series; T.C. 807	SA1-321	Airstair door.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D.H. 114 Heron Series 2A; T.C. A-816	SA740EA	Installation substitution of Lycoming engine IO-540-K1C5 in place of Lycoming Model IO-540-G1A4.	GL	87800	Wright Airlines, Inc. 2649 Broadway Cleveland, OH 44115
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST744SO	Installation of smoke detection system for forward and aft holds. Issued 12/13/74.	SO	65333	Puerto Rican Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST745SO	Installation of windshield wiper for co-pilot's (R.H.) position. Issued 12/13/74.	SO	65333	Puerto Rico Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA757SO	Installation of emergency exit RH fuselage at F.S. 49-76, and permanent closure of three existing overhead exits. Issued 3/4/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST758SO	Metal covering of wing flaps. Issued 5/3/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA919SO	Airplane life extension. Amended 6/20/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Heron Series 2A, 2DA, 2X; T.C. A-816	ST957SO	Installation of Teledyne battery Model BB638/T-C replacing two Rebat R-35 batteries. Issued 9/22/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST965SO	Modification of cockpit direct vision window. Issued 12/7/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, -2DA, -2X; T.C. A-816	SA1089SO	Installation of shoulder harness for crew seats. Issued 7/19/75.	SO	65333	Puerto Rico Int'l Airlines, Inc. c/o Caribbean Aircraft Develop., Inc. Building 408-Opa Locka Airport Opa Locka, FL 33054
DH-114-2A, -2DA, -2X; T.C. A-816	SA1138SO	Installation of Bendix RDR 160B weather radar system. Issued 3/4/80.	SO	65333	Puerto Rico Int'l Airlines, Inc. c/o Caribbean Aircraft Develop., Inc. Building 408-Opa Locka Airport Opa Locka, FL 33054
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1368WE	Installation of Lycoming IO-540 series engines. Amended 10/31/72.	SW	68150	Riley International Corporation P.O. Box 5247 Waco, TX 76708
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1545WE	Installation of cabin interior arrangement, air conditioning equipment, electrically operated air compressors. Amended 6/25/68.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1685WE	Installation of four Continental IO-520-E engines. Amended 8/22/68.	SO	65333	Puerto Rico Int'l Airlines, Inc. P.O. Box 1498 Bayamon, PR 00619
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1710WE	Installation of stair door.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1729WE	Installation of over wing emergency exits and rear windows. Amended 12/4/69.	SO	65333	Puerto Rico Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1826WE	Installation of 22 occupant interior.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA2067WE	Installation of Janitrol 8-200 cabin heater. Reissued 7/29/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA3125WE	Installation of lower wing skin straps, lower spar doubler straps and engine mount pickup strap doublers. Amended 4/1/76.	WE	86680	Winters Aircraft Engineering Co. 17100 Ventura Boulevard Encino, CA 91316
DH-114, 2X; T.C. 816	SA1371WE	Interior installation.	WE	06755	Aircraft Technical Service, Inc. 16300 Stagg Street Van Nuys, CA 91406
DH-114, 2X; T.C. 816	SA1534WE	Installation of engine fire detection and extinguishment systems.	WE	06755	Aircraft Technical Service, Inc. 7150 Hayvenhurst Avenue Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH-114, 2X; T.C. 816	SA1544WE	Cockpit modification and generator control.	WE	06755	Aircraft Technical Service, Inc. 7150 Hayvenhurst Avenue Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

EMPRESA BRASILEIRA DE AERONAUTICA S/A

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Embraer EMB-110P1; T.C. A21SO	SA1576CE	Installation of Collins ANS-351 area navigation system. Issued 3/6/80.	CE	24250	Collins Avionics Division 400 Collins Road, NE Cedar Rapids, IA 52406
Embraer EMB-110P1; T.C. A21SO	SA1577CE	Installation of Collins AP-106/FD-112 automatic flight control system. Issued 3/6/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
Embraer EMB-110P1; T.C. A21SO	SA1578CE	Installation of Collins electrical elevator trim system. Issued 3/6/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
25B; T.C. A10CE	SA29RM	Install mid-fuselage cargo compartment (500 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA30RM	Install tail cone cargo compartment (300 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA92GL	Install a Foster Airdata System, Inc. AD611/D area navigation system. Reissued and amended 2/20/79.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
25D; T.C. A10CE	SA4034WE	Installation of Canadian Marconi CMA-771 Omega/VLF navigation system. Issued 12/26/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
28, 29; T.C. A10CE	SA3926WE	Installation of Garrett Rescu 99 locator transmitter. Issued 5/9/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1489CE	Removal of 24-inch wide executive door and installation of 36-inch wide cargo door. Issued 5/8/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
29; T.C. A10CE	SA3928WE	Installation of Collins 718-U5 high frequency radio communications system. Issued 5/2/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35; T.C. A10CE	SA1195CE	Installation of dual Sperry C-12 gyro-compass system for use as navigational air. Issued 1/23/76.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35; T.C. A10CE	SA2288SW	Litton LTN-104 inertial navigation system. Issued March 1976.	SW	12250	Associated Radio Service 6911 Lemmon Avenue Dallas, TX 75220
35, 35A; T.C. A10CE	SA3633WE	Installation of AiResearch AirNAV-200 RNAV and Global GNS-500A VLF navigation systems. Issued 4/27/78.	WE	37095	Gates Learjet-Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA3931WE	Installation of Litton LTN-72R inertial navigation system with DME/DME update. Issued 5/11/79.	WE	37094	Gates Learjet Corproation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA4075WE	Installation of Collins 718U-5M high frequency radio communications system. Issued 1/11/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA4086WE	Installation of Sperry SPI-80 flight director system. Issued 2/26/80.	WE	37094	Gates Learjet Corporation P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA82RM	Installation of Sperry SP180/81 Flight Director System, interfaced with J.E.T. FC-200 Automatic Flight Control System. Issued 10/8/76.	RM	05940	Aircraft Radio and Accessory Company, Inc. Hangar #1 Stapleton Int'l Airport Denver, CO 80202
35, 35A, 36, 36A; T.C. A10CE	SA160GL	Install a J.E.T. DAC-2000 3-D RNAV system. Amended 4/15/77.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
35, 35A, 36, 36A; T.C. A10CE	SA405NW	Installation of an ONTRAC III VLF/Omega navigation system. Amended 9/27/77.	NW	16888	Boise Cascade Aviation 3565 South Owyhee Boise, ID 83705
35, 35A, 36, 36A; T.C. A10CE	SA1507CE	Installation of electronic consoles on cabin seat rails. Reissued 8/20/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1508CE	Installation of mounting plates in the tail cone for mounting of electrical inverters. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1509CE	Installation of instrumentation rack and inverter rack in baggage compartment. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, 35A, 36, 36A; T.C. A10CE	SA1531CE	Installation of a pod aerodynamic fairing capable of accepting target towing equipment. Issued 10/31/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
35, 35A, 36, 36A; T.C. A10CE	SA1533CE	Installation of a Maritime Patrol surveillance system. Reissued 11/16/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA3198WE	Installation of Garrett TFE 731 engine synchronizer/EMI filter - engine speed. Issued 5/20/76.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. A10CE	SA3340WE	Installation of Communications Components Corp. CNIRAC III VLF/ Omega navigation system. Issued 2/10/77.	WE	37094	Gates Learjet Modification and Service Center Tucson Int'l Airport Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3346WE	Installation of Collins Radio Co. flight profile comparator (ground proximity warning system - GPWS). Issued 2/18/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3375WE	Installation of Foster Airdata AD611D area navigation system. Amended 7/17/79.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3396WE	Installation of hydromechanical fuel controls, computers, and harnesses. Issued 5/5/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. aA10CE	SA3398WE	Installation of cold cathode cabin lighting system. Issued 5/6/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3411WE	Installation of AFCS heading select system. Issued 5/20/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3420WE	Installation of pitch trim tone system. Issued 6/29/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3421WE	Installation of modified control wheel and stick pusher cutout system. Issued 6/29/77	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3438WE	Installation of Garrett AirNav 100 or 200 navigation system. Amended 6/1/78.	WE	07500	AiResearch Manufacturing Company of California 2525 West 190th Street Torrance, CA 90509
35, 35A, 36, 36A; T.C. A10CE	SA3440WE	Installation of VOR/ILS compass and vertical gyro instrument switching system.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 65734
35, 35A, 36, 36A; T.C. A10CE	SA3442WE	Installation of AFCS heading and/or pitch maneuver transfer systems. Amended 1/27/78.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 65734
35, 35A, 36, 36A; T.C. A10CE	SA3509WE	Installation of Tracor 7640 omega navigation system. Issued 11/4/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3530WE	Installation of dual Collins 718U-5 HF system. Amended 10/31/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3531WE	Installation of Sundstrand MKII ground proximity warning system. Issued 12/12/77.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3532WE	Installation of Collins ANS-31A area navigation system. Issued 1/12/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, 35A, 36, 36A; T.C. A10CE	SA3561WE	Installation of a fuel filter. Amended 3/13/78.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
35, 35A, 36, 36A; T.C. A10CE	SA3568WE	Installation of Delco Carousel IV-A inertial navigation system. Issued 2/17/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3808WE	Installation of Jet Elect. & Tech. DAC-2000 3-D R/NAV system. Issued 12/20/78.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3865WE	Installation of Sperry C-11B compass system. Issued 3/5/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3896WE	Installation of Collins FIS-84 flight instrument system. Issued 4/10/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3916WE	Installation of directional gyro and vertical gyro transfer switching system. Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3994WE	Installation of ONTRAC III Mod 6, Omega/VLF navigation system. Issued 7/17/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 36; T.C. A10CE	SA766NW	Installation of stall fences and removal of vortex generators. Issued 5/4/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road South Seattle, WA 98108
35A; T.C. A10CE	SA4060WE	Installation of Sunair ASB-500 high frequency radio communication system. Issued 1/17/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35A, 36A; T.C. A10CE	SA1240CE	Installation of Intercontinental Dynamics Corp. RAD/BAR altimeter without voice terrain advisory. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1241CE	Installation of dual IDC maximum allowable mach/airspeed indicators type 575, P/N 25850. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1306CE	Install copilot's IDC maximum allowable airspeed/mach indicator type 575, P/N 26320. Issued 3/14/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1340CE	Dual camera installation. Issued 7/14/77.	CE	37094	Gates Learjet Corporation 8220 West Harry Wichita, KS 67209
35A, 36A; T.C. A10CE	SA1505CE	Wing pylon external stores installation. Issued 9/28/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
36, 36A; T.C. A10CE	SA3529WE	Installation of Litton LTN-72 inertial navigation system. Issued 1/13/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
36, 36A; T.C. A10CE	SA3864WE	Installation of Litton LTN-72R inertial navigation/area navigation system. Issued 3/6/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
36, 36A; T.C. A10CE	SA4033WE	Installation of Litton LTN-72 (INS)/Global GNS-500A (VLF/Omega) or Litton LTN-72R (INS)/Global GNS-500A (VLF/Omega) interface. Amended 5/25/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
240; T.C. 793	SA4-1222	Doppler antenna at fuselage station 667.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1224	Autopilot AP-103.	CE	24250	Collins Radio Company 855 35 Street, N.E. Cedar Rapids, IA 52401
240; T.C. 793	SA4-1226	Janitrol B-50 cockpit heater.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1228	Shrouding of flammable fluid system valve required by AD 59-02-01.	WE	54600	Don Maier & Associates 6214 W. Manchester Avenue Los Angeles, CA 90052
240; T.C. 793	SA4-1236	Pressure bulkhead and support provisions for McMillan radome.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1241	AVQ-50 radar and equipment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1526	100,000 B.T.U. heater for ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1528	18-passenger cabin arrangement, APU installation and an aft baggage compartment smoke detector.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1558	CV-340 compressor.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA7CE	Cockpit auxiliary heater installation, Janco Model 6032. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA13SW	APU for ground operation only.	SW	34000	Executive Aircraft Service Redbird Airport Dallas, TX 75232
240; T.C. 793	SA16CE	Float type fuel gage installation - ground visual fuel. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA32CE	Interior general arrangement - floor plan #9. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA35CE	Installation of generator overheat indicator. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA63EA	General Dynamics rectangular exhaust exit mufflers on aircraft with Hamilton Standard 43E60/6895-12 propellers and Pratt & Whitney R-2800-CB-16/17 engines.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
240; T.C. 793	SA177WE	Distance measuring equipment and transponder, and relocation of inverter installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA252SO	Supporting structure for camera mount A-28.	SO	10160	American Airmotive Corp. P.O. Box 187 International Airport Miami, FL 33101
240; T.C. 793	SA274EA	Electromagnetometer transmitting coil, batteries, transmitter junction box, and receiving "Bird." Amended 8/15/66.	EA	35300	Field Aviation Company, Ltd. P.O. Box 1001 Toronto Int'l Airport Melton, Ontario, Canada
240; T.C. 793	SA275EA	Antenna, radome, gyro and compass.	EA	44179	U.S. Geological Survey Department of Interior 8300 Colesville Road Silver Springs, MD 20907
240; T.C. 793	SA320WE	Ground blower.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA442WE	Extendable boom, detection crystal support, antenna, inverters, converters, and window enlargement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	EG	STC Code	STC Holder
240; T.C. 793	SA696SW	Fairchild cockpit voice recorder and control unit A-152-2.	SW	20550	Central Airlines, Inc. P.O. Box 2554 Fort Worth, TX 76101
240; T.C. 793	SA1054WE	Rolls Royce RDa 10 542-4 engines and Dowty Rotol R.245/4-40-4.5/13 propellers, an AiResearch APU and two combustion heaters.	WE	37280	General Dynamics 3302 Pacific Highway San Diego, CA 92112
240; T.C. 793	SA1303WE	Two 15KS-1000A1 standby rocket engines in fuselage tail cone and an aft pressure bulkhead.	WE	02315	Aerojet-General Corporation P.O. Box 15847 Sacramento, CA 95813
240; T.C. 793	SA1316WE	Underwing pressure refueling system and Roylin "Magna Stick" fuel level indicator.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
240; T.C. 793	SA3099WE	Modification of cargo door and cargo floor and removal of cabin pressurization. Issued 11/26/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
240; T.C. A-793	SA3697WE	Installation of cargo door, cargo floor and entry door. Amended 9/26/78.	WE	39877	Hamilton Aviation Company P.O. Box 11427 Tucson, AZ 85734
240; T.C. A-793	SA3801WE	Instalaltion of cargo door and cargo floor. Issued 12/6/78.	WE	39877	Hamilton Aviation Company Tucson Aviation Center P.O. Box 11746 Tucson, AZ 85734
240-17; T.C. A-793	SA4077WE	Conversion of military model T-29A to model 240-17. Issued 3/28/80.	WE	10360	American Turbine Engine Company 1150 Busch Garden Court Pasadena, CA 91105
240-27; T.C. 793	SA149EA	Conversion of military model B29B to model 240-27. Reissued 6/27/77.	WE	39877	Gordon B. Hamilton The Hamilton Aviation Co. P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. 793	SA150EA	Installation of: 19 passenger executive interior Solar T-350M2 turbine APU comm and navigational systems. Reissued 6/27/77.	WE	39877	Gordon B. Hamilton The Hamilton Aviation Co. P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. 793	SA777SO	Installation of a cargo barrier bulkhead. Issued 10/4/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
240-27 (T-29B); T.C. 793	SA1048SO	Conversion of USAF Model T-29B into the civil Model 240-27 with deviations to TCDS A-793. Amended 8/16/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
240-27 (T-29B); T.C. A-793	SA1100SO	Conversion of the USAF T-29B into the civil model 240-27 with deviations to Aircraft Spec. A-793. Issued 9/10/79.	SO	44320	International Transportation P.O. Box 1183 Ormond Beach, FL 32074
240-27 (T-29B); T.C. 793	SA1135SO	Installation of a Class "E" cargo compartment, cargo floor modification, large aft cargo door, and removal of certain components of the previously deactivated pressurization system. Issued 2/22/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
240-27; T.C. A-793	SA3831WE	Installation of King weather radar. Amended 11/7/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. A-793	SA4025WE	Installation of cargo door, cargo floor, class "E" cargo compartment provisions for weather radar installation. Issued 9/28/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. A-793	SA4026WE	Conversion of military T-29B to civil model 240-27. Issued 9/28/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. A-793	SA4027WE	Installation of a boarding ladder. Issued 9/28/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240, 340; T.C. 793, 6A6	SA4-861	Stainless steel overlay nacelle area required by AD 59-02-01.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
240, 340; T.C. 6A6	SA426EA	Installation of Chamberlain replacement radome 3008 or 3008C. Amended 11/27/67.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company Aero Product Operations P.O. Box 1187 Akron, OH 44309
240, 340, 440; T.C. 793, 6A6	SA1-656	Radome assembly 3008.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
240, 340, 440; T.C. 793, 6A6	SA3-420	Main cabin seat installations (including divan and seat belts). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240, 340, 440; T.C. 793, 6A6	SA4-500	Engine mount core assemblies. (Parts manufactured under license from United Aircraft Corporation.)	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
240, 340, 440; T.C. 793, 6A6	SA4-525	Engine mount core 106-1F and 106-1J.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
240, 340, 440; T.C. 793, 6A6	SA4-568	Engine mount core assemblies DL1468.	WE	83500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
240, 340, 440; T.C. 793, 6A6	SA41SO	B-300B engine oil separator.	SO	04400	Air Carrier Engine Service, Inc. International Airport Miami, FL 33101
240, 340, 440; T.C. 793, 6A6	SA118SO	BS-040-2 oil separator.	SO	04400	Air Carrier Engine Service, Inc. International Airport Miami, FL 33101
240, 340, 440; T.C. 793, 6A6	SA125CE	High intensity wing tip lights Model B or F, tail lights Model C, with or without Model 2 fuselage lights, STC SA4-1100 modified aircraft. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
240, 340, 440; T.C. 793, 6A6	SA775SW	Airstep.	SW	85128	Westernair of Albuquerque, Inc. 4736 Isleta Boulevard, SW Albuquerque, NM 87101
240D, 340D, 440D; T.C. 793, 6A6	SA1927SW	Installation of Safeway De-Icer boot P/N 5660 and/or Semsa Lead P/N S2001 in lieu of Dowty Rotol boots and/or leads on Dowty Rotol propeller models R245/4-40-4.5/13 with blades P/N 6.6000.2301 or Model R259/4-40-4.5/17 with blades P/N 6.6000.4300. Amended 2/27/75.	EA	70830	SEMSA, Inc. 2125 Smithtown Avenue Ronkonkoma, NY 11779
240D (600); T.C. 793	SA1992SW	Aft cargo door between F.S. 549 and 658 between floorline and stringer and associated structural modifications. Issued 6/6/75.	SW	07740	Air Freighters International P.O. Box 2 15808 Addison Road Addison, TX 75001
340; T.C. 6A6	SA1-488	Various radio and modifications plus rearrangement of control head on pedestal and revised radio electrical circuitry.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
340; T.C. 6A6	SA3-419	General interior floor plan arrangement. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340; T.C. 6A6	SA3-421	Installation of auxiliary power unit. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340; T.C. 6A6	SA4-38	Two additional passenger windows and three double passenger seats forward of fuselage station 243.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340; T.C. 6A6	SA4-219	Vibration suppressor plates.	WE	52010	Lockheed Aircraft Service, Inc. P.O. Box 33 Ontario, CA 91761
340; T.C. 6A6	SA4-1164	Flammable fluid system valve shrouding required by AD 59-02-01.	WE	54600	Don Maier & Associates 6214 W. Manchester Avenue Los Angeles, CA 90052
340; T.C. 6A6	SA4-1211	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340; T.C. 6A6	SA4-1321	Interior modification including a 16-passenger executive type interior arrangement and baggage compartment smoke detector.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340; T.C. 6A6	SA4PC	Brownline cargo pallet and net assemblies.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA5PC	Conversion to an all cargo airplane.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA6PC	Cargo/passenger combination interior.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA7PC	Removable triple seat.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA83WE	Interior arrangement for 58 occupants.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340 with STC SA4-110 incorporated; T.C. 6A6	SA406GL	Installation of a Canadian Marconi CMA734 omega navigation system. Issued 5/16/80.	GL	84642	The Way International Box 328 New Knoxville, OH 45871
340; T.C. 6A6	ST409SO	Rear service door hinge.	SO	29234	Delta Air Lines, Inc. Atlanta Airport Atlanta, GA 30320
340; T.C. 6A6	SA506SW	Hydraulic system modification.	SW	34180	FAA Aeronautical Center Engineering Division Will Rogers Field Oklahoma City, OK 73101
340; T.C. 6A6	SA713WE	AiResearch GTP30-54 turbine APU.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
340; T.C. 6A6	SA952EA	Installation of Solar T-62T-39 gas turbine auxiliary power unit. Issued 4/11/73.	EA	18750	Butler Aviation Friendship, Inc. Sub. of Butler Aviation Int'l Friendship Int'l Airport Baltimore, MD 21240
340; T.C. 6A6	SA2702SW	Two Friedrich window air conditioners and three electrical heaters. Issued 12/22/77.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
340, 440; T.C. 6A6	SA1-471	Weather mapping radar.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
340, 440; T.C. 6A6	SA1-474	Installation of Chamberlain Aviation 2008X Series radomes. Reissued 9/12/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
340, 440; T.C. 6A6	SA1-500	Waste King flight data recorder 5424.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
340, 440; T.C. 6A6	SA3-486	Interior cabin configuration - general floor plan (20 passenger configuration). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340, 440; T.C. 6A6	SA3-487	Janitrol heater installation (100,000 BTU). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340, 440; T.C. 6A6	SA3-488	Installation of radar nose, Bendix ANT-1B antenna and pitot modification (including Radome fabrication). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340, 440; T.C. 6A6	SA3-511	Radome and airspeed indicator system.	SW	17075	Braniff Airways, Inc. Love Field Dallas, TX 75235
340, 440; T.C. 6A6	SA3-649	Maximum safety light system YG-766A or ALS9A-CV.	GL	59650	Minneapolis-Honeywell Regulator Company 2747 Fourth Avenue, South Minneapolis, MN 55401

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA4-36	General Dynamics 340 outer wing integral fuel tanks.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 400; T.C. 6A6	SA4-135	Oil tank and supporting structure rework (relocation of oil tank installation plumbing, oil tanks support rework, engine oil tank modification).	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-160	Andover type D-2, Model V-32 APU and associated equipment for ground operation only.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-194	Ranger APU for ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-247	AiResearch C-7500-1 divan.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-248	Cabin tables.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-249	Hardman 3048 and 3041 chairs.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-250	Galley and buffet.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-390	Radio and cargo compartment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Anglees, CA 90045
340, 440; T.C. 6A6	SA4-409	Interior for 52 passengers.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-418	Auxiliary A.D.I. tank in aft baggage compartment.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-582	Napier Eland 504 turboprop engines with deHavilland PD216/466 propellers with XPR5662950SA-124 or PPR626950SA-124 blades.	EU	61150	D. Napier & Son, Ltd. Acton London, W. 3, England
340, 440; T.C. 6A6	SA4-689	Napier Eland 504 turboprop engines with deHavilland PD216/466 propellers with XPR5662950SA-124 or PPR626950SA-124 blades.	EU	61150	D. Napier & Son, Ltd. Acton London, W. 3, England
340, 440; T.C. 6A6	SA4-914	Goodrich multidisc brakes and Westinghouse "Decelostat" anti-skid controller type AP-3 on aircraft modified per STC SA4-582.	EU	61150	D. Napier & Son, Ltd. Acton London, W. 3, England
340, 440; T.C. 6A6	SA4-1008	Seat track mounting floor structure.	SW	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1041	Alternate fuel source in aircraft with Pratt & Whitney R-2800 Series "C" engines and fuel flowmeters.	SW	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1100	Installation of Allison model 501-D13D or 501-D13H turbo propeller engines with Aero Products A6441FN-606A propeller, with associated modifications to engine mounting, nacelle, empennage, accessories and system. Amended 5/10/71.	GL	29750	Detroit Diesel Allison Division General Motors Corporation Indianapolis, IN 46206
340, 440; T.C. 6A6	SA4-1114	Fuel tank extension for 2,080-gallon turbine engine fuel on aircraft modified per SA4-1100.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA4-1120	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1152	Interior and equipment.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA4-1191	17-passenger interior arrangement and smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1242	Extension of wing tank and oil tank rework. Fuel tank revised for use JP-4 fuel and kerosene.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1243	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1249	Extension of fuel tank to station 29 (for JP-4 kerosene or gasoline) and provisions for a gravity flow fuel jettison system on aircraft modified per STC SA4-1100 only.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA4-1318	McMillan radome.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1343	Gas turbine in tail cone section.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1344	Modification to air-conditioning system and installation of an air start supply line.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1513	Interior and equipment on aircraft modified per STC SA4-1100.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1519	Air-driven alternator and vertical stabilizer omni navigational antenna and electrical system deviations on aircraft modified per STC SA4-1100.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1589	Interior modification including divans, swivel chairs and cabinets for a total of 13 passengers on aircraft modified per STC SA4-1100.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA2SW	Auxiliary power battery (emergency D.C. power and emergency feathering system).	SW	34600	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
340, 440; T.C. 6A6	SA23WE	United Data Control F-542 flight data recorder.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA24WE	RCA AVQ-50 weather avoidance radar system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA25WE	Seat track on aircraft modified per STC SA4-409.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA34RM	Installation of Sierra 7000 SANS-TACAN System. Amended 12/12/74.	RM	11870	Aspen Airways, Inc. Hangar 5 Stapleton Int'l Airport Denver, CO 80207
340, 440; T.C. 6A6	SA36WE	Modification of fuel source for Ranger APU and Janitrol ground heater approved under STC's SA4-194 and SA4-195.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA42RM	Installation of two Sperry GH-14 gyro-horizon instruments. Reissued 1/20/75.	RM	37015	Frontier Airlines 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA50RM	Installation of additional anti-collision light system (white strobe lights). Issued 2/10/75.	RM	37015	Frontier Airlines 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA59RM	Installation of Collins type 331A-6P/6A course indicator and relocation of altitude alert control. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA60RM	Installation of Sundstrand ground proximity warning system, glide slope monitoring system and Honeywell low range radio altimeter system. Issued 7/11/75. Supplemental T.C. SA4-1100.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA71WE	Fuel source modification for Ranger APU approved under STC SA2-962.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA83GL	Install Bendix GPW-83 ground proximity warning system. Issued 9/5/75.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450
340, 440; T.C. 6A6	SA96GL	Installation of Collins FPC-590A ground proximity warning system. Issued 11/7/75.	GL	90135	Zantop International Airlines, Inc. Detroit-Willow Run Airport Ypsilanti, MI 48197
340, 440; T.C. 6A6	SA104RM	Install dual SELCAL system. Issued 6/22/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100); T.C. 6A6	ST133RM	Modification of turbine inlet temperature indicator Model BH183M to install precision potentionmeter in place of original tapot. Issued 2/17/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100); T.C. 6A6	ST134RM	Installation of coat closet at body station 230. Issued 2/22/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA151EA	Bendix doppler radar DRA-12.	EA	08196	Airmar Radio Service, Inc. 2177 Smithtown Avenue Ronkonkoma, NY 11779
340, 440; T.C. 6A6	SA184WE	Two 15KS-1000-A1 or two 15KS-1000-A1(B) standby rocket engines in fuselage tail cone. Amended 8/18/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
340, 440; T.C. 6A6	SA227EA	Nose cap weather radome. Amended 3/29/66.	EA	16600	Bethlehem Steel Corporation Aviation Service Division Bethlehem, PA 18016
340, 440; T.C. 6A6	SA232CE	Install aural mach warning system. Amended 2/27/67.	GL	37808	General Motors Corporation 3044 W. Grand Boulevard Detroit, MI 48202
340, 440; T.C. 6A6	SA264EA	Janitrol S-200 heater for ground operation only.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
340, 440; T.C. 6A6	SA279WE	Window emergency exit on right side of aircraft at station 651.5.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA379CE	Installation of Hoskins twilighter Mk V intensity STC SA4-1100 modified aircraft. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1186 N. Batavia Orange, CA 92667
340, 400; T.C. 6A6	SA423WE	Cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA427EA	All cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA428EA	Installation of FM #1, 2, and 3 Radiophone. Amended 5/26/67.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA429EA	Cabinet.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA443WE	Installation of cargo door, a cargo floor and an emergency exit, plus removal of original cargo door and forward passenger entrance door. Reissued 2/6/70.	NW	49350	Robert T. Lamson 7840 Southeast 20th Mercer Island, WA 98040
340, 440; T.C. 6A6	SA451EA	Cockpit voice recorder.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA454CE	Model CH 3002-3181 Hoover Aircraft Products evacuation chute.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
340, 440; T.C. 6A6	SA483EA	Installation of cabin window at F.S. 730.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA494EA	ADF-FA Interconnection.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA495EA	Installation of Flight Interphone System.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	ST519SO	Installation of underseat baggage restraint bars. Issued 11/1/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440; T.C. 6A6	SA542CE	Make and install horizontal stabilizer tips.	GL	12578	Auto-Craft Engineering 1904 N. Colorado Avenue Indianapolis, IN 46206
340, 440; T.C. 6A6	ST548SO	Installation of external induction ram air scoops. Issued 8/28/73.	SO	53788	Mackey International Airlines 500 S.W. 34 Street Fort Lauderdale, FL 33315
340, 440; T.C. 6A6	ST596SO	Installation of exhaust system bracket. Reissued 1/6/75.	SO	02394	Aeronautical Engineering, Inc. 342 N.E. 2nd Court Dania, FL 33004
340, 440; T.C. 6A6	SA604EA	Installation of United Control Model F542 Flight Data Recorder.	EA	09520	Allegheny Airlines Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA651EA	Installation of UHF/FM Secure System.	EA	52012	Lockheed Aircraft Service, Inc. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA695WE	Rain repellant system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA669WE	Smoke detector, flight data recorder, and oxygen breathing system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	ST700SO	Installation of exterior emergency lighting system. Amended 5/8/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440; T.C. 6A6	SA775WE	Interior.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505
340, 440; T.C. 6A6	SA786WE	Yoke assembly, pilot and copilot control.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA874WE	Shoulder harness installation. Amended 6/9/76.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90404
340, 440; T.C. 6A6	SA884EA	Installation of tail logo lights. Amended 10/19/71.	EA	10750	Butler Aviation Friendship, Inc. Sub. Butler Aviation International Friendship Int'l Airport Baltimore, MD 21240
340, 440; T.C. 6A6	SA896EA	Installation of Marshall interior kit assembly No. 96123. Amended 7/13/73.	EA	54200	Magee Plastics Company 6000 Babcock Boulevard Pittsburgh, PA 15237
340, 440; T.C. 6A6	SA908WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA925WE	Pitch servo of Sperry SP-20 autopilot system.	EA	10660	Bethlehem Steel Company 701 E. Third Street Bethlehem, PA 18016
340, 440; T.C. 6A6	ST926SO	Installation of cargo door and interior. Amended 7/18/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440; T.C. 6A6	ST927SO	Installation of cargo floor and a smoke detector system. Issued 5/5/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
340, 440; T.C. 6A6	SA1015WE	Modified fiberglass vertical stabilizer tip, and Grimes 9950-1 rotating beacon.	RM	37015	Frontier Airlines, Inc. Stapleton Int'lernational Airport Denver, CO 80207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA1015EA	Installation of Atlantic Aviation Corp. (ISO C-39) attendant seat P/N 21.737. Issued 9/22/75.	EA	12500	Atlantic Aviation Corporation Greater Wilmington Airport Box 1709 Wilmington, DE 19899
340, 400 (580); T.C. 6A6	SA1027EA	Installation of Collins FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340/440 modified in accordance with STC SA4-1100; T.C. 6A6	ST1035SO	Installation of a combination passenger/cargo interior to include an all cargo, 44 passenger/cargo, 10 passenger/cargo, and 6 passenger/cargo configurations. Issued 12/4/78.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36302
340, 440; T.C. 6A6	SA1060WE	AP101E Collins autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440: T.C. 6A6	SA1096WE	Rolls Royce Dart 542-4 engines with Dowty Rotol (c) R245/4-40-4.5/13 or (c) R259/4-40-4.5/17 propellers and associated modifications. Amended 7/27/66.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1097SO	Installation of two (2) double seats to increase passenger configuration from 44 to 48. Issued 8/30/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
340, 440; T.C. 6A6	SA1119WE	Two additional emergency exits, and interior arrangement.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1132WE	Parker Aircraft, Inc. under-wing pressure refueling valve and Boylin "Magna-Stick" fuel indicator.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA1146WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA1174WE	Fuel jettison system.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA1218WE	Cargo floor, cargo door and forward service door.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1268WE	Interior and equipment.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505
340, 440; T.C. 6A6	SA1331WE	Installation of United Data Control, Inc. Model V-557 cockpit voice recorder system. Amended 3/28/67.	RM	37015	Frontier Airlines 5900 East 39th Street Denver, CO 80207
340, 440; T.C. 6A6	SA1338WE	Seat track, additional emergency exit and interior arrangement.	WE	37280	General Dynamics Corp. P.O. Box 1950 San Diego, CA 92112
340, 440; T.C. 6A6	SA1366WE	Installation of Collins Radio Company FD105 flight director system.	WE	37280	General Dynamics Convair Division P.O. Box 1950 San Diego, CA 92112
340, 440; T.C. 6A6	SA1407SW	Provide 52-passenger seat aircraft with cargo carrying capability by installing an aft cargo door and reinforcing the floor and fuselage shell. Amended 6/1/72.	WE	37280	General Dynamics Corporation Convair Aerospace Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1438WE	Installation of an Avionics System.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA1482WE	Installation of interior arrangement.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA1505WE	Installation of radio transformer rectifier for standby D.C. power.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA2302WE	Modification of pedestal flight idle stop and lift to reverse system. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
340, 440; T.C. 6A6	SA2697WE	Modification including those airplanes further modified per STC SA1096WE for turbo propeller power for installation of cargo door, cargo floor and cargo lining. Issued 5/25/73.	WE	10208	American Jet Industries, Inc. 2800 Clybourn Avenue Burbank, CA 90405
340, 440; T.C. 6A6	SA2733WE	Modification of Model 340/440 previously modified per STC SA4-1100 for turbo propeller power for installation of cargo door, cargo floor and cargo lining. Issued 9/5/73.	WE	10208	American Jet Industries, Inc. 2800 Clybourn Avenue Burbank, CA 91505
340,440; T.C. 6A6	SA2896SW	Conversion to an all-cargo configuration. Issued 1/15/79.	SW	08126	Airgo, Inc. LB-31 Love Field Terminal Bldg. Dallas, TX 75235
340,440; T.C. 6A6	SA2897SW	Composite flooring, one double seat, nonstructural bulkhead.	SW	08128	Airgo, Inc. LB-31 Love Field Terminal Bldg. Dallas, TX 75235
CV340/440; T.C. 6A6	SA3132WE	Installation of an alternate (printed circuits) ice protection system on the engine air intake. Amended 11/17/77. This installation is approved for use on airplanes modified in accordance with STC SA4-1100 only.	WE	71680	Sierracin/Thermal Systems 13920 South Broadway Los Angeles, CA 90061
340, 440; T.C. 6A6	SA3294WE	Modification by installation of dual mach/airspeed warning system. Reissued 1/20/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA3479WE	Modification by installation of an alternate pallet restraint system.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
340/440; T.C. 6A6	SA3574WE	Modification of Convair 340 or 440 which have been modified per STC SA4-1100. Issued 3/24/78.	WE	45500	Jay Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90904
340/440; T.C. 6A6	SA3758WE	Enlarge cargo door on aircraft modified per STC No. SA2733WE. Issued 10/17/78.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
340,440; T.C. 6A6	SA3772WE	Installation of cargo tie downs in aircraft modified per STC No. SA2733WE. Issued 11/1/78.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA
340, 440; T.C. 6A6	SA4075SW	BKM 100PHM-2 pitot head monitor system. Issued 1/17/80.	SW	16652	The BKM Company P.O. Box 7001 Dallas, TX 75209
440; T.C. 6A6	SA4-49	Two 250-gallon auxiliary fuel tanks in wing center section.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-195	Janitrol S-50 ground heater.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-196	Extended wing tank installation and oil tank rework.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-245	GTP-70-17 auxiliary gas turbine power plant.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-314	Cabin interior.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
440; T.C. 6A6	SA4-407	Andover Type D-2, Model V-32 APU for ground operation only.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
440; T.C. 6A6	SA4-408	Interior arrangement installation (right hand forward cargo door made permanently inoperative as an exit by seating arrangement).	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-675	Oscillograph rack.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-692	Interior equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-857	ARN-14 antenna.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-897	Window station 730 L.H.	WE	07500	AiResearch Aviation Service Co. 6021 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-930	Aircraft interior.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-1319	Bendix RDR-1D radar and equipment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-1428	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA195SW	Structural installation of Bendix AMA-12A-1 doppler antenna.	SW	12250	Associated Radio Service Co. 7515 Lemmon Avenue Dallas, TX 75220
440; T.C. 6A6	SA283WE	Interior and equipment installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA384EA	Two three-place couches.	EA	03100	Aero Trades, Inc. Long Island Airport Ronkonkoma, NY 11779
440; T.C. 6A6	ST925SO	Installation of a cargo door. Issued 5/10/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-164; T.C. 1A16	SA651WE	Modified wheels and brakes.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA1278WE	Ceconite 101 covering of wings and ailerons.	WE	26240	Cooper Engineering Corporation P.O. Box 3428 Van Nuys, CA 91408
G-164; T.C. 1A16	SA1295WE	Automatic flagman marker dispensing unit.	NW	03500	Air-Ag, Inc. Route 4 Walla Walla, WA 99362
G-164; T.C. 1A16	SA1407WE	Installation of Pratt & Whitney R-985-AN-1 engine and Hamilton Standard 2D30/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164; T.C. 1A16	SA1586WE	Installation of Pratt & Whitney R-1340-AN-1 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164, G-164A; T.C. 1A16	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
G-164, G-164A; T.C. 1A16	SA270WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller. Amended 7/11/68.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164, G-164A; T.C. 1A16	SA406RM	Installation of wing span extension. Amended 5/23/77.	RM	02360	Aero Mod General, Inc. Box 68 Latah, UT
G-164, G-164A; T.C. 1A16	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
G-164, G-164A; T.C. 1A16	SA940SW	Installation of Micronair AU-3000 spray units. Reissued 10/2/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164, G-164A; T.C. 1A16	SA1282SW	Jacobs-Page R-755SM engine and Grumman 5404/M96K propeller. Reissued 5/24/77.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
G-164 (S/N 301-400), G164A (S/N 400 and up); T.C. 1A16	SA1312WE	Fabrication and installation of 285-gallon fiberglass hopper (replaces 245-gallon metal hopper). Reissued 6/12/75.	GL	39542	Grumman American Aviation 318 Bishop Road Cleveland, OH 44143
G-164, G-164A; T.C. 1A16	SA1319CE	Chrome plated brake disc installation. Issued 7/22/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
G-164, G-164A; T.C. 1A16	SA1777WE	Installation of Hamilton Standard 3D40/6101A-17 propeller.	WE	85125	Western Aircraft Sales P.O. Box 753 Long Beach, CA 90801
G-164, G-164A; T.C. 1A16	SA2012WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	17022	Bowles Flying Service Route 1, Box 124-B Live Oak, CA 95953
G-164, G-164A, G-164B; T.C. 1A16	SA832SO	Installation of Hamilton Standard Model 2D30/6101A-10S propeller. Amended 10/15/76.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164, G164A, G-164B; T.C. 1A16	SA1427CE	Install smoke generator for Part 137, agricultural aircraft operations, only. Issued 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508 Renner Field Goodland, KS 67735
G-164, G-164A, G164B; T.C. 1A16	SA3077WE	Installation of elevator servo-tab. Reissued 3/17/77.	WE	26540	Robert L. Copeland 171 West Shannon Chandler, AZ 85224
G-164, G-164A, G-164B; T.C. 1A16	SA4101WE	Installation of locking tail wheel. Issued 2/14/80	WE	11470	APS Products, Inc. 6751 Airport Road Redding, CA 96001
G-164, G-164A, G-164B, G-164C; T.C. 1A16	SA2747SW	Lockable full swivel tail wheel. Issued 4/6/78.	SW	36700	Frakes Aviation Cleburne Airport Rt. 3, Box 229-B Cleburne, TX 76031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-164, G-164A, AA-1, AA-1A, AA-1B, AA-5; T.C. 1A16, A11EA, A16EA	SA71GL	G-164's install P/N BA8210 filter assembly; AA-1, AA-5 install P/N BA 4210 filter assembly. Reissued 9/22/79.	WE	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140
G-164A; T.C. 1A16	SA99NW	Installation of HSP 3D40-401 hub with EAC-100-2 blades. Issued 3/29/74.	NW	33000	Efficiency Aircraft P.O. Box 37 Kent, WA 98031
G-164A; T.C. 1A16	SA445NW	Installation of EAC-22D30-AG-200-4S prop or P&W R-985-AN-1 engine. Issued 5/9/77.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A; T.C. 1A16	SA809SW	Installation of 5-inch longer engine mount in S/N 401 and up. Reissued 9/25/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164A; T.C. 1A16	SA833SO	Installation of Hamilton Standard Model 12D40/6101A-10S propeller approved under STC SP830SO on Pratt & Whitney R1340-AN-1, S1H1 or S3H1 engines listed in TDS 1A16. Issued 4/28/75.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164A; T.C. 1A16	SA994SW	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101-12 propeller. Reissued 4/19/73.	GL	39542	Grumman American Aviation Corp. 318 Bishop Road Cleveland, OH 44143
G-164A, S/N 526 and up with a P & W R-1340-AN-1 engine and Hamilton Standard 12D40 propeller; T.C. 1A16	SA1077CE	Installation of Edo-Aire propeller governor. Issued January 1975.	CE	32500	Edo-Aire, Inc. Wichita Division 1326 S. Walnut Street Wichita, KS 67213
G-164A; T.C. 1A16	SA1222SW	64-gallon or 80-gallon fuel tanks. Issued 11/17/70.	EA	39540	Grumman Aerospace Corporation P.O. Box 147 Elmira, NY 14902
G-164A; T.C. 1A16	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 7/24/73.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-164A; T.C. 1A16	SA1422SW	Paper filter for engine induction air. Issued 1/19/72.	SW	17260	Frank Brinster 2214 North Parkwood Harlingen, TX 78550
G-164A; T.C. 1A16	SA2015WE	The 12-volt or 24-volt D.C. electrical generating system is replaced by an alternator system. Amended 12/21/78.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
G-164A; T.C. 1A16	SA2356SW	Wing tip extension of 20 inches. Issued 9/14/76.	SW	38405	Fram & Ranch Aerial Service Wharton, TX 77055
G-164A; T.C. 1A16	SA2444SW	Install P&W ACL PT6A-34 engine. Issued 12/2/77.	SW	36700	Frakes Aviation, Inc. Route 2, Box 229-B Cleburne Airport Cleburne, TX 76031
G-164A; T.C. 1A16	SA2731SW	P&L-38 engine and Dowty-Rotol propeller CR 289/3-110-F/1. Issued 3/17/78.	SW	52610	Lyon Flying Service, Inc. P.O. Box 726 Welsh, LA 70591
G-164A, G-164B; T.C. 1A16	SA78RM	Installation of air conditioner system. Amended 6/21/77.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
G-164A, G-164B; T.C. 1A16	SA434NW	Installation of EAC-12D40-AG-100S-4S prop on Pratt & Whitney R-1340-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA436NW	Installation of WAC-2D30-425-AG-100-4A prop on Pratt & Whitney R-985-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA1102SO	Manufacture and installation of a 360 gallon agricultural spray dispensing hopper. Amended 3/6/80.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701
G-164A, G-164B; T.C. 1A16	SA1129SO	Installation of a 320 gallon agricultural spary dispensing hopper. Issued 3/24/80.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701
G-164A, G-164B; T.C. 1A16	SA1131SO	Installation of replacement fiberglass fuselage skin panels. Issued 3/13/80.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G164A, G164B; T.C. 1A16	SA2666WE	Ceconite 102 material covering of: G-164A - vertical and horizontal tail and wings; G-164B - complete aircraft. Amended 4/19/78.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-164B; T.C. 1A16	SA199RM	Oil temperature controlled system. Issued 4/17/80.	RM	18268	Vincent E. Buraas P.O. Box 176 Northwood, ND 58267
G-164B (Restricted Category); T.C. 1A16	SA3876WE	Installation of Alvis Leonides engine and Dowty Rotol (c)R284/3-20-3/8 constant speed propeller. Issued 3/6/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Morteson Avenue Salinas, CA 93905
G-164C (Restricted Category); T.C. 1A16	SA3764WE	Installation of Wright R-1820-71, -60; GR1820G-202A, 702C9GC1, 2, 3, 4, 704C9GC1, 2, 3, 4 engine and Hamilton Standard 43D50 or 33D50 constant speed propeller. Amended 3/27/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Morteson Avenue Salinas, CA 93905
G-164C; T.C. 1A16	SA4127WE	Installation of an AiResearch TPE331-1-101Z turboprop engine. Issued 4/18/80.	WE	75210	Floyd D. Stilwell Marsh Aviation 5060 E. Falcon Drive Mesa, AZ 85205
AA-1 Series; T.C. A11EA	SA809NW	Installation of fixed (flush) cowl flap, nose gear strut fairing and retainer. Issued 7/20/79.	NW	27241	Maynord C. Corsby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1 Series; T.C. A11EA	SA810NW	Installation of main landing gear fairings from the AA-5 series aircraft incorporating sheet metal covers over rubber in place of stock rubber parts. Issued 7/20/79.	NW	27241	Maynord C. Crosby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1; T.C. A11EA	SA1410SW	Mitchell automatic flight system AK301, consisting of Century I autopilot with optional omni tracker. Issued 12/28/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-1; T.C. A11EA	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
AA-1; T.C. A11EA	SA2104WE	Installation of Brittain Models B4C and B5B flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
AA-1; T.C. A11EA	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1010CE	Installation of wing leading edge cuffs. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1313CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-1, AA-1A, AA-1B; T.C. A11EA	SA3234WE	Installation of Piper oil cooler and associated installation components. Issued 7/8/76.	WE	05390	Aircraft Maintenance Service 7950B Joe Crosson Drive Santee, CA 92071
AA-1, AA-1A, AA-1B; T.C. A11EA	SA4106SW	Increase gross weight to 1560 lbs. for AA-1, 1560 lbs. for AA-1A, and 1600 lbs. for AA-1B. Issued 3/26/80.	SW	24100	James E. Collier Route 4, Box 610 Jefferson, TX 75657
AA-1 (1969 and on), AA-1A (1969 and on), AA-1B (1969 and on), AA-5 (1972, 1973 and 1974 only); T.C. A16EA	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
AA-1; AA-5; T.C. A11EA, A16EA	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1B; T.C. A11EA	SA10NW	Installation of VA-3 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-1B; T.C. A11EA	SA11NW	Installation of VA-2 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-1C Utility Category; T.C. A11EA	SA3695WE	Installation of Lycoming 0-235-C2C engine and McCauley 1A105/SCM7154 propeller. No installation data required. Placards required with this installation: At the fuel filler caps - "80/87 MIN OCTANE AVGAS" Issued 7/7/78	WE	03105	Aero-Training, Inc. 89 John Glenn Drive Concord, CA 94520
AA-5; T.C. A11EA	SA66NW	Installation of VA-4 fiberglass wheel fairings. Issued 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-5; T.C. A16EA	SA1472SW	Mitchell automatic flight system AK374 consisting of Century IIB autopilot with optional omni tracker. Issued 6/28/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5; T.C. A16EA	SA1486SW	Mitchell automatic flight system AK373 consisting of Century I autopilot with optional radio coupler. Issued 5/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5, -5A, -5B; T.C. A16EA	SA1314CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-5B; T.C. A16EA	SA3031SW-D	Mitchell automatic flight system AK514 consisting of Century I autopilot with omni tracking system. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5B; T.C. A16EA	SA3032SW-D	Mitchell automatic flight system AK515 consisting of Century IIB autopilot with optional radio coupler. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5B; T.C. A16EA	SA3301WE	Installation of Model EGT-1 exhaust gas temperature monitoring system. Issued 11/23/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
AA-5B; T.C. A16EA	SA3309WE	Modification of primary control system by addition of rudder-aileron interconnect and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/27/77.	WE	12250	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
G-159; T.C. 1A17	SA1-399	Forward and aft attachment for HF antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-400	Bendix radar scanner attaching brakcets and electrical cable firewall plugs.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-401	Glide slope antenna mounting bracket.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-402	Installation of 37X-2 Marker Beacon Antenna. Amended 7/24/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA1-403	Fabrication of mounting blocks and installations of Lear sense antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-404	Fabrication and installation of adaptor for mounting Chance Vought seat 22-93597-B-2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-405	DL-1 loop assembly.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-406	Collins 37R-2 antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-407	AC Spark Plug Division FM telephone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-408	Radio equipment shelves.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-412	Bulkhead at station 193.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-413	Double-hinged door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-414	Bulkhead and door at station 232.5.	EA	23600	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-415	Bulkhead and door at station 485.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-417	Baggage compartment smoke detector system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-420	AC Spark Plug Division FM telephone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-421	Bendix LPA-70C loop antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-432	High frequency antenna. Amended 7/25/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-447	Bulkhead and door at station 251.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-448	Bulkheads at stations 183 and 239 and baggage shelf.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-449	Bulkhead and door at station 493.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-450	Partial bulkhead at station 223.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-465	Bulkhead at station 232.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-466	Bulkhead at station 257.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-472	Installation of Atlantic Aviation Corporation's T80-C39 seat model "Retractable Seat --G II." Amended 1/13/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-493	Telectro AT-138-A marker antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA1-494	Collins 013107800 transponder antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-495	Collins 537F-1 radar scanner.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-498	Automatic flight control systems.	CE	24250	Collins Radio Company 855 35 Street, N.E. Cedar Rapids, IA 52401
G-159; T.C. 1A17	SA1-505	Two internally-mounted Aerojet-General 15KS-1000 A1 aircraft rocket engines in rear wing fillet.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361
G-159; T.C. 1A17	SA4-931	Avionics racks.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-932	Jump seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-942	Cabin oxygen supply system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-968	Divan.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-969	Swivel seat, fuselage station 133.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-972	L-102B autopilot.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
G-159; T.C. 1A17	SA4-976	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-991	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1000	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1015	Interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1048	Avionics racks to fuselage station 193.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1049	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1051	Oxygen breathing system applicable to altitude up to 30,000 feet.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1057	Anti-collision light.	GL	12488	Atkins Light Corporation 7636 Lyndale Avenue, South Minneapolis, MN 55401
G-159; T.C. 1A17	SA4-1058	Interior and equipment.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1068	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1087	Cabin interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1098	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1115	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA4-1123	Interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1125	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1168	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1267	Cabin interior furnishings and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1293	General Electric 20M63C8 generator.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1320	Interior modification including passenger oxygen system and baggage compartment smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1379	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1381	Interior modification.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1445	Modification to Bendix DRA-12 doppler radar.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
G-159; T.C. 1A17	SA4-1481	Cabin interior furnishings and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1497	Ten-passenger interior arrangement, system, and aft baggage compartment smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1580	Auxiliary power unit modification (GTCP 85-91C and/or GTC 85-291C installation). Amended 6/2/66.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1581	Interior modification including three swivel seats for authorized crew members only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1582	Third crew member seat.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA11EA	Fabrication and installation of baggage compartment storage shelves.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA12EA	Bulkhead and door at station 251.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA16EA	Fabrication and installation of an Avionics bracket under the floor.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA16GL	Incorporating AMF (Leland) inverters MGE 23-3 or MGE 23-400. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
G-159; T.C. 1A17	SA56WE	Interior and distance measuring equipment system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA60EA	Collins 237Z-1 antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA66EA	Fabrication and installation of a two-place seat.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA72WE	Interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA81EA	Fabrication and installation of bracketry for mounting a Collins 537F-8 radar scanner.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA88EA	Installation of a bulkhead and door at station 392.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA96EA	Wilcox electric transponder antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA98EA	Antenna masts.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA101EA	Skyphone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA106EA	Bulkhead and door at station 244.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA110WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA122EA	Atkins anti-collision light system control wiring changes, per STC SA4-1057.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA122CE	Install Hoskins supplementary light system consisting of Model A wing tip lights, or Model C or 2 tail light optionally, two of Model fuselage lights with M-3 or M-5 power supply. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
G-159; T.C. 1A17	SA131EA	Modification of extraction section of Vickers-Armstrongs, Ltd. engine mount attachment pin, 60216.	EA	52064	Robert Long and Ray Williams 49 Champ Avenue Pearl River, NY 10965
G-159; T.C. 1A17	SA138EA	Collins 137A-4 ADF fixed loop antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA141WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA147EA	Bulkhead and door at Station 487 and fore and aft bulkhead at Station 525.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA148EA	Bulkhead and door at Station 232.5 to Station 242.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA150WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA156EA	Kollsman 1708-01 sextant mount in ditching hatch.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA168EA	Bulkhead and door at fuselage Station 192.375. Amended 3/17/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA174GL	Modification of floor support between stations 228.5 and 353 to eliminate decrease in allowable floor loading with increased zero fuel weight. Issued 5/12/77.	GL	90135	Zantop Airways, Inc. Detroit Metro Airport Detroit, MI 48242
G-159; T.C. 1A17	SA187EA	Bulkhead and door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA203EA	Two place seating capacity in cabin.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA218EA	Bulkhead and door at Station 232.5 - 226.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA267EA	Bulkhead and door at Station 487. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA282EA	Under-the-floor rework between fuselage stations 416 and 525 for divan installation.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA288EA	Executive interior and communication/navigation equipment.	EA	78510	Timmins Aviation, Ltd. Montreal International Airport Dorval, P.Q., Canada
G-159; T.C. 1A17	SA296WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA297GL	Installation of single Canadian Marconi CMA-734 Omega/VLF navigation system. Issued 3/21/79.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
G-159; T.C. 1A17	SA302WE	Incorporation of Napier Spraymat de-icing (as manufactured by applicant) externally on Rotol propeller spinner as an alternate to Dowty Rotol internal elements. Reissued 10/22/70.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
G-159; T.C. 1A17	SA314EA	Door in bulkhead at Station 525.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA315EA	Bulkhead and door at Station 232.5 - 226.5. Amended 3/17/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA340EA	3051 replacement radome. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
G-159; T.C. 1A17	SA352WE	Interior.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA370EA	Main landing gear nutcracker microswitch assembly relocated.	EA	86200	George R. Williams 49 Champ Avenue Pearl River, NY 10965
G-159; T.C. 1A17	SA373EA	Two three-place couches and oxygen provisions.	EA	03100	Aero Trades, Inc. Long Island Airport Ronkonkoma, NY 11779
G-159; T.C. 1A17	SA376GL	Reduction of maximum zero fuel gross weight. Issued 11/26/79.	GL	91034	Zantop Airways, Inc. Detroit Metro Airport Detroit, MI 48242
G-159; T.C. 1A17	SA389WE	11-passenger interior and equipment installation including dual Collins DF-203 ADF receivers and dual Collins MC-102 gyrosyn compasses.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA394SW	HF-G overspeed warning system.	SW	40000	The Hamilton Company 106 Neuhaus Street Houston, TX 77002
G-159; T.C. 1A17	SA399WE	Maximum allowable airspeed indicator.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA406SW	Engine breather drain extension with fairing.	SW	11604	Arco Sheet Metal Company 8346 Lockheed Houston, TX 77002
G-159; T.C. 1A17	SA427SW	To install brackets for the installation of 2 each ADF loops, 1 each marker antenna, 4 each cabin speakers, 2 each cockpit speakers, and to install 4 each ADF sense antenna mounting brackets. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91502
G-159; T.C. 1A17	SA435SW	To fabricate wiring harness and make complete radio, radar installation. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-159; T.C. 1A17	SA437SW	Fabrication and installation of radio rack. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA448WE	Interior.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA486WE	11-passenger interior and equipment installation including Collins flight director system (dual), radio magnetic indicator switching, plus DME and ATC transponder systems.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	ST512SO	Installation of cargo door and nets. Reissued 9/20/74.	EA	18750	Butler Aviation Baltimore/Washington Int'l Airport Baltimore, MD 21240
G-159; T.C. 1A17	SA541EA	Installation of new nose section, new nose gear, cabin interior and AiResearch GTC Model No. 85-134.	EA	39540	Grumman Aircraft Engineering Corp. Bethpage, L.I., NY 11714
G-159; T.C. 1A17	SA571SW	Collins radio altimeter system.	SW	12250	Associated Radio Service P.O. Box 20718 Dallas, TX 75221
G-159; T.C. 1A17	SA577EA	Installation of a 3-position fuel filter heat valve and control system for each engine.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA623WE	Eighteen-occupant interior with Atlantic Aviation jump seat for an additional crew member.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA636EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA637EA	Installation of Collins 621A-3 transponder.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA638EA	Installation of Collins 860E-2 DME.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA664EA	Installation of Sperry G-11B Gyro Compass System.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA665EA	Installation of Bendix DMA-29A DME System.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA666EA	Installation of Bendix TRA-61A transponder system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA667EA	Installation of Bendix MKA-28C marker beacon receiver.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA668EA	Installation of Frieden Type B-5 Driftmeter.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA723WE	12-passenger interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA730WE	12-passenger interior arrangement.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA735WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA761WE	13-passenger interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	ST762SO	Installation of main cabin floor support structure. Issued 8/19/77.	SO	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST763SO	Installation of courier seat and cockpit/main cabin partition. Issued 8/19/77.	SO	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST764SO	Enlarged passageway in FS525 main cabin bulkhead. Issued 8/19/77.	SO	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242

Aircraft Make, Model & T.C. No.	STC No.	Description	FG	STC Code	STC Holder
G-159; T.C. 1A17	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
G-159; T.C. 1A17	SA807SW	FD108/AP103E/F Flight Director-Autopilot combination for Category II operation.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA838WE	Shelf and webbing in baggage compartment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA839WE	Lavatory external service pen.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA879WE	Two radar altimeter antennas.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA886WE	Honeywell aircraft recognition light system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA888EA	Installation of Grimes three light strobe kit 34-0303-1 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
G-159; T.C. 1A17	ST889SO	Installation of Collins ground proximity warning system. Issued 3/16/76.	SO	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-159; T.C. 1A17	SA893SW	Dual FD-109 Flight Director/AP-104 Autopilot, 54W-1C Comparator Warning, AL-101 Radio Altimeter, MC-102 Compass, 51RV-1, VOR/ILS, 51Z-4 Marker, 860E-2 DME and DF-203 ADF systems.	SW	24252	Collins Radio Company Avionics System Center P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA998CE	Installation of battery temperature monitor and over temperature warning system.	CE	05250	Aircraft Instrument and and Development, Inc. 317 E. Lewis Wichita, KS 67202
G-159; T.C. 1A17	ST999SO	Installation of Bendix ground proximity warning system. Issued 6/24/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-159; T.C. 1A17	SA1034EA	Installation of Safeway de-icer overshoes P/N 5651 and/or Semsa leads P/N S.2002 on Dowty Rotol propeller model R184/4-30-4/50 with blades P/N R.A25907. Issued 3/22/76.	EA	70830	Semsa, Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779
G-159; T.C. 1A17	SA1050SO	Replace existing nickel cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
G-159; T.C. 1A17	SA1098WE	EGT and r.p.m. indicator for APU, Model GTC 85-37.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1137EA	Installation of the Global GNS-500A Omega navigation system. Issued 1/12/79.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-159; T.C. 1A17	SA1284WE	Kollsman MS28011-2 sextant.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1318WE	Lear Siegler, Inc. 510K autopilot system.	WE	07500	AiReserach Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1341CE	Installation of Collins Radio Group FPS-80 flight control system including electric trim. Amended 5/16/80.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, NE Cedar Rapids, IA 52406
G-159; T.C. 1A17	SA1536SW	Foxtronics TRAMM BII-600 nickel-cadmium battery temperature system. Issued 11/10/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA1559SW	Semi-automatic fuel trim system. Issued 12/4/72.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159; T.C. 1A17	SA1678SW	Modification of Burns BH 1600 (P/N 908-2-1 and -2) double seats. Issued 6/20/73.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1709SW	Oxygen service installation. Issued 7/31/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-159; T.C. 1A17	SA1745SW	ANS-70A Area Navigation System. Issued 2/21/74.	SW	24252	Collins Radio Company 1200 N. Alma Road Richardson, TX 75207
G-159; T.C. 1A17	SA1763SW	Modification to Burns BH1600 double seats to aft facing. Issued 11/14/73.	SW	84600	Ward Int'l Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1964WE	Installation of jump seat.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1955SW	Installation of Collins AP-105 autopilot for Category I operation. Amended 5/5/80.	CE	24250	Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
G-159; T.C. 1A17	SA2629WE	Installation of single point refueling system. Issued 1/8/73.	WE	06750	Aircraft Tank Service, Inc. 10201 Conasset Street Burbank, CA 91504
G-159; T.C. 1A17	SA3044WE	Installation of fuel tank interconnect system. Issued 7/9/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-159; T.C. 1A17	SA3641WE	Installation of DeVore Aviation Corp. horizontal stabilizer mounted vertical tail flood lights. Issued 6/21/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
G-159, G-1159; T.C. 1A17, A12EA	SA10NE	Installation of a "back-up" passenger seat restraing system. Amended 3/30/78.	NE	69850	S.A.G.E. Corporation Burlington Int'l Airport Burlington, VT 05401
G-159, G-1159; T.C. 1A17, A12EA	SA1082SW	Revise nose gear steering cockpit control by installing BKM Guidemaster.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159, G-1159; T.C. 1A17, A12EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
G-1159; T.C. A12EA	SA23NE	Installation of aluminum grating on cargo door at fuselage station 539.75. Issued 3/27/78.	NE	69850	S.A.G.E. Corporation Burlington International Airport Burlington, VT 05401
G-1159; T.C. A12EA	ST222GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
G-1159; T.C. A12EA	SA272GL	Installation of Intercontinental Dynamics Corp. engine vertical scale instruments. Amended 12/5/78.	EA	44160	Intercontinental Dynamics Corp. 170 Coolidge Avenue Box 81 Englewood, NJ 07631
G-1159; T.C. A12EA	ST566SO	Installation of Bendix RNS-3400 area navigation system. Amended 5/23/74.	SO	15475	Bendix Avionics Division P.O. Box 5414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA579EA	Installation of a custom interior.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA606EA	Installation of shelf and bracketry at fuselage station 743.0 - 769.62, replace metal skins with fiberglass between fuselage station 813.31 and 855.00 and bracketry provisions between fuselage station 812.50 and 826.50.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA607EA	Manufacturing and installation of partition and door blow out provisions. Amended 12/29/69.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA608EA	Installation of dual Sperry SPI-73E flight director.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA618EA	Installation of Atlantic Aviation Corporation's TSO'd retractable seat, Type G11. Amended 6/17/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA623EA	Installation of bulkhead door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA624EA	Installation of bulkhead and bulkhead door at fuselage station 194.25.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA625EA	Installation of bulkhead and bulkhead door at fuselage station 503.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA626EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. Reissued 6/3/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA627EA	Installation of Collins 54W-1 comparator warning system. Amended 12/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA628EA	Installation of Collins AL-101 radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA629EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA630EA	Installation of Sperry C-11B gyro compass system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA631EA	Installation of dual Collins F.D. 109G flight director systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA632EA	Installation of Pyrotector smoke detector system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA633EA	Installation of constant flow passenger oxygen system. Amended 12/5/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA645EA	Installation of structural provisions for the Collins doppler DN-101.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA649EA	Installation of Litton LTN-51 inertial navigation system. Amended 12/11/68.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA654EA	Installation of Honeywell hi-intensity recognition lights. Reissued 11/12/68.	GL	42250	Honeywell, Inc. 2600 Ridgway Road Minneapolis, MN 55413
G-1159; T.C. A12EA	SA655EA	Installation of Collins flight directors.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA657EA	Installation of Sperry comparator warning unit.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA658EA	Installation of Sperry altitude preselect system. Amended 12/31/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA659EA	Installation of Bendix ALA-51A radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE19899
G-1159; T.C. A12EA	SA660EA	Installation of dual Sperry SPI-73E flight director system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA662EA	Installation of an Air-Lavatory Drain. Amended 12/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA663EA	Installation of EDO Loran System. Amended 1/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA669EA	Installation of bulkhead and bulkhead door at fuselage station 201.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA670EA	Installation of bulkheads at fuselage stations 467.5, 485.0 and 515.25; bulkhead doors at fuselage stations 485.0 and 515.25; and longitudinal bulkhead at buttline 4 between fuselage stations 467.5 and 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA680EA	Installation of conference table.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA681EA	Installation of bulkhead and bulkhead door at fuselage station 255.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA682EA	Installation of bulkhead and bulkhead door at fuselage station 495.0. Amended 9/10/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA683EA	Installation of sliding door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA684EA	Installation of intercostals between fuselage station 244-1/4 to fuselage station 257-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA685EA	Installation of intercostals between fuselage station 487 to fuselage station 498. Amended 10/22/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA688EA	Installation of Collins FD-109H and FD-109F flight director system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA689EA	Installation of IDC 17000-22 Air Data Computer. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA691EA	Installation of a dual Collins DF-203 ADF.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA692EA	Installation of intercostals between fuselage station 193 to fuselage station 206.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA693EA	Installation of bulkhead and bulkhead door at fuselage station 495 5/8.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA694EA	Installation of bulkhead and bulkhead door at fuselage station 200.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA699EA	Installation of intercostals between fuselage station 345 7/8 to fuselage station 355 1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA701EA	Installation of Hartman Systems Company vertical scale engine instruments. Reissued 11/29/68.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746
G-1159; T.C. A12EA	SA702EA	Installation of intercostals between fuselage station 452 1/2 to fuselage station 466.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA706EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. This STC does not apply to S/Ns 6, 11, 12, 14. Amended 12/27/73.	SO	15475	Bendix Corporation Bendix Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA718EA	Installation of intercostals between fuselage station 498 to fuselage station 512.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA721EA	Installation of swivel seat installation, fuselage stations 287 1/2 to fuselage station 379.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA722EA	Installation of Safe Flight SCAT/ Autopower System. Amended 1/7/75.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
G-1159; T.C. A12EA	SA723EA	Installation of intercostals between fuselage station 43-1/2 and fuselage station 452-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA724EA	Installation of vertical scale full quantity indicators Model VS-2PE (639-) as replacement for original round dial indicators.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746
G-1159; T.C. A12EA	SA726EA	Installation of seat track reinforcement conference table grouping.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA733EA	installation of intercostals between fuselage station 297 to fuselage station 306-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA734EA	Long range under floor oxygen cylinder installation. Amended 7/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA735EA	Installation of divan base aft support/attachment at fuselage station 460-1/4.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA748EA	Installation of skyphone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA749EA	Installation of combined divan-bunk on right hand side of aircraft between fuselage station 183 and fuselage station 255. Issued 4/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA750EA	Installation of seat track extension. Issued 4/16/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA758EA	Installation of partial bulkhead and door at fuselage station 182. Amended 11/19/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA759EA	Installation of bulkhead attachment. Amended 8/22/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA760EA	Installation of bulkhead and bulkhead door at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA761EA	Installation of bulkhead at fuselage station 448. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA763EA	Installation of Litton LTN-51 inertial navigation system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA777EA	Installation of bulkhead at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA778EA	Installation of bulkhead at fuselage station 459.5. Amended 8/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA779EA	Installation of Custom Products Model 400-21 three place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA783EA	Installation of Electronic Resources Skyphone (UHF) antenna 10-222-04880.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA789EA	Installation of two-place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA790EA	Installation of bulkhead and door at fuselage station 507.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA806EA	Installation of Atlantic Aviation Corporation's retractable seat-GII and refreshment cabinet.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	ST874SO	Installation of Collins ground proximity warning system. Issued 12/15/75.	SO	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-1159; T.C. A12EA	ST888SO	Installation of Litton "Digiprox" ground proximity warning system. Issued 3/9/76.	SO	51502	Litton Systems, Inc. 6065 Roswell Road N.E. Suite 305B Atlanta, GA 30328
G-1159; T.C. A12EA	SA937SW	Crew jump seat.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA940SW	Micronair AU-3000 spray units.	EA	39540	Grumman Aircraft Engineering P.O. Box 147 Elmira, NY 14901
G-1159; T.C. A12EA	SA941SW	Collins HF communication system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA942SW	Collins AL-101 radio altimeter.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA943SW	Dual Sperry SPI-73 integrated flight system, Sperry instrumentation, comparator monitor and dual Sperry C11B compass system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA945SW	Litton LTN51 inertial navigation system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA946SW	Update Sperry 2587400-274 air data computer.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA948SW	Increase of DC output capabilities for APU TR unit.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA951SW	Passenger oxygen system and supplemental (long range) oxygen supply.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA957EA	Installation of modular berthable 1 or 2 place side-facing seat. Issued 7/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA970EA	Installation of Fairchild cockpit voice recorder Model A100 and A151 control unit. Issued 11/26/73.	EA	07498	AiResearch Aviation Company Islip MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA996EA	Installation of Shaw Aero fuel filler cap P/Ns 457-2, -266, -370, 431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
G-1159; T.C. A12EA	ST998SO	Installation of Bendix ground proximity warning system. Amended 8/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA1036SW	Bendix ALA-51A radio altimeter.	SW	12259	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA1037SW	Emergency lights and battery.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1060EA	Installation of a single or dual Delco Electronics Carousel IV-A inertial navigation system with computer program, P/N 7881711-006. Reissued and amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1061EA	Installation of a dual Collins ALT-55B radio altimeter system. Amended 12/23/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA1062EA	Installation of a Sperry air data computer, Intercontinental Dynamics Co. (IDC) servo altimeters and mach. Amended 12/28/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA1063EA	Installation of a dual Collins flight director system, Model FD-109Y. Amended 1/23/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. 4/30/79	SA1068SO	Installation of Intercontinental Dynamics Corp. radio/barometric altimeter with voice terrain advisory and Sperry mini air data computer. Issued 4/30/79.	SO	39725	Gulfstream American Corporation P.O. Box 2206 Savannah, GA 31402
G-1159; T.C. A12EA	SA1070EA	Installation of dual Litton LTN-72R navigation system. Reissued and amended 4/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1093SW	Decca loran system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1139EA	Installation of a dual or single Global GNS-500A VLF/Omega navigation system. Amended 10/10/79.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1157EA	Replacement of Garrett AiResearch GTCP-36-6 APU with Solar T-62T-40C2 APU. Amended 10/5/79.	EA	73275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
G-1159; T.C. A12EA	SA1186EA	Installation of an Eldec Corp. digital fuel flowmeter and totalizer system. Issued 2/22/80.	EA	10135	Amerada Hess Corporation Mercer County Airport P.O. Box 7385 West Trenton, NJ 08628
G-1159; T.C. A12EA	SA1187EA	Installation of a single Litton LTN-211 Omega/VLF navigation system. Issued 3/17/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1197EA	Installation of a single Litton LTN-72 inertial navigation system. Issued 5/30/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1250SW	Decca type 72 doppler radar system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1251SW	Decca omni-trac system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1336SW	Installation of pressure refueling control system. Issued 7/8/71.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1423SW	Electrical wiring feed thru Station 580. Issued 1/24/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1447SW	Battery fault warning system. Issued 9/18/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1480SW	Installation of FD-109F flight director, INS-61B inertial navigation system, Bendix ALA-51 radio altimeter. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-1159; T.C. A12EA	SA1481SW	Installation of cockpit control for center point refueling system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourne Avenue Burbank, CA 91505
G-1159; T.C. A12EA	SA1496SW	Trasm BTI-600 battery temperature indicating system. Issued 7/31/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA1553SW	Dual Collins INS-61B inertial navigation units. Issued 11/15/72.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1613SW	BKM master warning interface device between master warning control panel and aircraft inputs. Issued 3/1/73.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA1697SW	Avionics cooling fan. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1698SW	Oxygen service installation. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1633WE	Installation of jump seat in cockpit.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1634WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1654WE	Installation of passenger oxygen continuous flow system.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1683WE	Installation of passenger oxygen system.	WE	07500	AiResearch Aviation Company 6021 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1756WE	Installation of an aircraft integrated weight and balance system (STAN).	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1757WE	Installation of United Control flight data recorder.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1769WE	Installation of Sonotone Battery Model No. 989074-1 and battery container.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1771WE	Installation of SD1 Hoskins anti-collision light system. Amended 11/28/73.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
G-1159; T.C. A12EA	SA1772WE	Installation of United Control speed command system. Amended 6/19/70.	NW	80685	United Control Corporation Overlake Industrial Park Redmond, WA 98052
G-1159; T.C. A12EA	SA1800WE	Installation of radio rack and placards only for avionic components between fuselage stations 181-193 RH.	WE	63750	Qualitron Aero, Inc. Lockheed Air Terminal 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1814WE	Rain repellent system installation. Amended 10/25/73.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-1159; T.C. A12EA	SA1817WE	Installation of Sperry ATS-500 autothrottle system.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1819WE	Installation of doppler antenna and mount for doppler receiver and transmitter.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1848WE	Installation of Custom Products Model 1875 jump seat on radio rack.	WE	62105	Pacific General Corporation 3210A Winona Burbank, CA 91502
G-1159; T.C. A12EA	SA1868WE	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system.	SO	15475	Bendix Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA1889WE	Installation of Sperry SP-50G automatic flight control system, Sperry SPI-73E integrated instrument system and Sperry ATS-500 automatic throttle system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation P.O. Box 2529 Phoenix, AZ 85027
G-1159; T.C. A12EA	SA1898WE	Installation of Litton Model LTN-51 inertial navigation system. Amended 7/9/69.	WE	51500	Litton Systems, Inc. Guidance & Control Systems Division 5500 Canoga Avenue Woodland Hills, GA 91364
G-1159; T.C. A12EA	SA1983WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2016WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA2165WE	Installation of altitude preselect and alerting system (SP-50G Altitude Preselect System). Issued 7/8/70.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
G-1159; T.C. A12EA	SA2184WE	Installation of dual AC Carousel IV inertial navigation system. Amended 10/23/79.	GL	37810	General Motors Corporation A.C. Electronics Division Milwaukee, WI 53201
G-1159; T.C. A12EA	SA2234SW	Passenger continuous flow oxygen system. Issued 8/15/75.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2235SW	Dual Collins 61B inertial systems. Issued 8/15/75.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2237SW	BKM specific range computer. Issued 8/26/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2270SW	Manufacture and install a divan. Issued 11/7/75.	SW	11890	Associated Air Center Box 20718 - Love Field Dallas, TX 75220
G-1159; T.C. A12EA	SA2277SW	Continuous flow, low pressure oxygen system. Issued 12/10/75.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2366SW	Lighted speed brake handle. Issued 10/6/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2387SW	Dual Litton LTN-72R area navigation system. Issued 11/27/76.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2407SW	Install HF antenna on tail cone. Issued 2/11/77.	SW	36600	Foxtronics, Inc. P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA2430WE	Installation of dual Collins INS-61B inertial navigation system. Reissued 11/29/71.	CE	24250	Collins Radio Company 855 35th Street Cedar Rapids, IA 52406
G-1159; T.C. A12EA	SA2512WE	Relocation of speed-logic control unit of GTCP36-6 turbine auxiliary power unit and mounting provisions for spare speed-logic unit. Issued 5/12/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2592WE	Installation of auxiliary taxi light system. Issued 9/1/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2593WE	Installation of Dorne and Margolin DMN 4-15 antenna (VOR/localizer) is installed in vertical stabilizer. Amended 11/9/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2757WE	Installation of crew oxygen regulator and mask assemblies. Issued 9/7/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2797WE	Installation of wing tip mounted emblem lights. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 91406
G-1159; T.C. A12EA	SA2807WE	Installation of dual GAMMA I (SKN-2610) inertial navigation systems. Amended 6/28/74.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2907SW	Pitot head indicating system. Issued 1/30/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2965WE	Installation of dual GAMMA I inertial navigation systems. Issued 1/16/75.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2995SW	Global GNS-500A VLF Omega navigation system. Issued 5/10/79.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA3089WE	Installation of 104006 computer program in LTN-104 ANS. Issued 10/1/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA3223WE	Installation of Garrett AirNAV 100 or 200 area navigation system. Amended 6/1/78.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3288WE	Installation of Canadian Marconi vertical scale engine instruments. Issued 10/22/76.	WE	30000	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3302WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 9/17/76.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3370WE	Installation of dual ONTRAC III VLF/OMEGA navigation system. Issued 12/1/77.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3399WE	Installation of a single or dual Litton LTN-72R INS/RNAV navigation system. Amended 7/11/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3600WE	Installation of a single or a dual Delco C-IVA inertial navigation systems. Amended 1/30/80.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3629WE	Installation of either single LTN-51 or LTN-72. Issued 4/14/78.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
G-1159; T.C. A12EA	SA3635WE	Installation of IPECO pilot and co-pilot crew seats. Amended 6/26/79.	WE	54860	Marcon Associates, Inc. 18436 Hawthorne Blvd. Suite 212 Torrance, CA 90504
G-1159; T.C. A12EA	SA3636WE	Installation of single Delco Carousel IVA inertial navigation system. Issued 6/22/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3691WE	Installation of DeVore Aviation wing tip tank tail cone mounted vertical tail floodlights. Issued 7/12/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3973WE	Installation of equipment racks for the mounting of a radar system. Issued 6/15/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
GA-7; T.C. A17SO	SA1425CE	Install King KFC-200 automatic flight control system. Issued 7/14/78.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
GA-7; T.C. A17SO	SA3235SW-D	Mitchell automatic flight system AK634 consisting of Century IV autopilot or AK634FD consisting of Century IV flight director autopilot with remote annunciator. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3236SW-D	Mitchell automatic flight system AK634 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3238SW-D	Mitchell command electric trim AK637. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
269A, B, C; T.C. 4H12	SH152AWE	Installation of SKI/Boskins Model 700801 anti-collision light system. Issued 8/18/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
269A, 269B, 269C; T.C. 4H12	SH157WE	Installation of fiberglass/aluminum baggage compartment. Issued 7/6/73.	WE	39300	Gould Engineering, Inc. Falcon Field Airport 4600 E. McKellips Road Mesa, AZ 85205
269A, 269B, 269C; T.C. 4H12	SH249WE	Installation of a searchlight kit. Issued 9/5/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4H12	SH258WE	Installation of MCT-10 mounting rack. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4H12	SH259WE	Installation of utility compartment. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269B; T.C. 4H12	SA123WE	Installation of E.O.S. 1 KW searchlight and Technical Engineering & Manufacturing Co., Inc. Model TA-30 alternator.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH128WE	Installation of Nightsun SX-10 searchlight Kit No. 019600 when: A TA-30 dual voltage alternator is installed per STC SH131WE; the helicopter is equipped with a Dovsek Model 200C or 300B light mounts, the mount's indicator light conforms to Hughes Service Information Notice #N92. Amended 9/14/71.	WE	74500	Spectrolab Div. of Textron, Inc. 12484 Gladstone Avenue Sylmar, CA 91342
269B, 269C; T.C. 4H12	SH131WE	Installation of EMPAC (U.S. Energy Corporation) Model TA-30 dual voltage alternator system (12 volts/60 amperes and 28 volts/68 amperes) in lieu of 12-volt alternator. Issued 7/7/71.	WE	80890	United State Energy Corporation 2780 Temple Avenue Long Beach, CA 90806
269B, 269C; T.C. 4H12	SH145WE	Installation of modified oil filler tube and dipstick. Issued 5/31/72.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH146WE	Installation of utility window. Issued 6/2/72.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH202WE	Installation of controls for pilot-in-command on right side. Issued 4/28/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
269B, 269C, Normal Category; T.C. 4H12	SH245WE	Installation of searchlight. Issued 7/31/79.	WE	19986	Carter Engineering Company, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
269B, 269C; T.C. 4H12 Only those rotorcraft having Hughes P/N 269A4593 or 269A8241, or 269A4593 muffler installed.	SH1138CE	Installation of engine exhaust tail pipe extension. Issued May 1975.	CE	59460	Milair, Inc. Route #1 Goddard, KS 67052
269C; T.C. 4H12	SH134WE	Installation of Spectrolab Nightsun SX-16C searchlight. Amended 3/3/75.	WE	65328	Progressive Aviaiton Limited Reid-Hillview Airport San Jose, CA 95122
269C; T.C. 4H12	SH224WE	Installation of heated pitot. Issued 9/13/78.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
269C; T.C. 4H12	SH1099CE	Installation of cabin heater and engine exhaust tail pipe extension. Issued March 1975.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052
300 Series (269C); T.C. 4H12	SH333NW	Installation of automatic flagman. Issued 10/28/76.	NW	03500	Air Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
369; T.C. H3WE	SH390NW	Installation of electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
369 Series; T.C. H3WE	SH598NW	Installation of load readout device. Issued 5/18/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
369 Series; T.C. H3WE	SH667NW	Installation of fiberglass fuel tanks under rear seat. Issued 9/15/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369 Series; T.C. H3WE	SH829NW	Installation of a weighing system. Issued 9/6/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
369, 369A, 369H, 369HM, 369HS, 369HE, 369D; T.C. H3WE	SH207WE	Installation of range extension fuel tank in cargo area of Hughes 369 series helicopters. Issued 1/10/78.	WE	68501	Robertson Aircraft, Inc. P.O. Box 968 Tempe, AZ 85281
369A, 369D, 369H; T.C. H3WE, 369HE, 369HM, 369HS	SH215WE	Installation of floodlights on fuselage. Amended 6/9/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
369A, H, HM, HE, HS; T.C. H3WE	SH358AL	Installation of Airglas L2700-369 skis. Amended 6/26/74.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369A, H, HS, HE; T.C. H3WE	SH1657SW	Full length, hard surface, skid shoes on standard skid landing gear. Issued 6/18/73.	SW	61650	Northrup Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
369D; T.C. H3WE	SH220WE	Installation of a "BCS-500D" helicopter computer system. Issued 7/28/78.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
369D; T.C. H3WE	SH246WE	Installation of ATI Model 13-0044, 13-0045 and 13-0046 speaker kits. Issued 8/17/79.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
369D; T.C. H3WE	SH654AL	Install Airglas Model L2700-369HD skis. Issued 10/24/78.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D; T.C. H3WE	SH678AL	Installation of Airglas skis. Issued 12/28/79.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D, 369H Series; T.C. H3WE	SH567NW	Installation of engine driven pump, tank hoses and spray nozzles for fire fighting. Issued 2/24/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369D, 369HE, 369HM, 369HS; T.C. H3WE	SH112GL	Installation of Marathon CA1700-1 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213
369D, 369HE, 369HM, 369HS; T.C. H3WE	SA123GL	Installation of SAFT 1656-1 nickel cadmium electrical storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213
369D, 369HE, 369HS; T.C. H3WE	SH236WE	Installation of searchlight. Issued 4/26/79.	WE	15986	Carter Engineering, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
369D, HE, HM, HS; T.C. H3WE	SH552NW	Installation of cargo hook electronic scale system. Issued 1/4/78.	NW	73067	Marvin A. Smith 5503 West Flowing Lake Road Snohomish, WA 98290
369D, 369H, 369HE, 369HM, 369HS; T.C. H3WE	SH183WE	Installation of turbine overtemperature warning system. Amended 4/4/77.	WE	60425	MRSC Incorporated 10959 San Diego Mission Road San Diego, CA 92108
369D, 369HE, 369HM, 369HS; T.C. H3WE	SH401GL	Installation of Ni-Cad Model No. 72639 engine lubrication system scavenge filter. Issued 4/18/80.	GL	61546	Ni-Cad, Incorporated 24800 U.S. 20 West South Bend, IN 46628
369D, HE, HM, HS; T.C. H3WE	SH958SO	Installation of SAFT 1615e nickel cadmium battery. Amended 1/17/79.	SO	69800	SAFT America, Inc. P.O. Box 1886 Valdosta, GA 31601
369D, H, HM, HS, HE; T.C. H3WE	SH1142EA	Installation of APC starter-generator, P/N 150SG111Q. Issued 4/23/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
369D, 369HE, 369HS; T.C. H3WE	SH189WE	Installation of searchlight kit. Amended 3/16/79.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH190WE	Installation of P.A. speaker kit. Amended 4/14/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
369D, 369HE, 369HS; T.C. H3WE	SH250WE	Installation of a P.A. speaker kit. Issued 9/17/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH098EA	Installation of pod type cargo container kits. Amended 11/22/78.	EA	72263	Skypods Limited P.C. Box 221 Arnprior, Ontario, Canada
369D, 369HE, 369HS; T.C. H3WE	SH1134EA	Installation of external cargo container (POD) kit. Amended 4/11/80.	EA	83757	Viking Helicopters, Ltd. P.O. Box 5104 - Station "F" Ottawa, Ontario, K2C3H4 Canada
369H; T.C. H3WE	SH184NW	Installation of Chadwick C-500 aerial spray system. Issued 5/23/75.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369H; T.C. H3WE	SH431NW	Installation of Model 500 spray system. Amended 5/9/77.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH1054EA	Installation of Garrett AiResearch environmental control system. Amended 9/8/77.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
369HE, 369HM, 369HS; T.C. H3WE	SH129WE	Installation of Chadwick C-20 auxiliary fuel systems. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH132WE	Installation of two side cargo racks P/N DMC-023-200-1. Issued 8/25/71.	NW	61798	Olympic Helicopters, Inc. 8241 Perimeter Road South Boeing Field Seattle, WA 98108
369HE, 369HM, 369HS; T.C. H3WE	SA133WE	Installation of C-75 cargo rack set, P/N 75-0000-00. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH516AL	Installation of Model L2700-369HS skis. Issued 5/1/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
369HS; T.C. H3WE	SH214WE	Installation of external neutron detector moduel and associated cockpit displays. Issued 4/18/78.	WE	31225	EG & G, Incorporated P.O. Box 1912 Las Vegas, NV 89101
369HS; T.C. H3WE	SH242NW	Installation of battery in Hughes 369HS helicopter to replace original. Issued 12/11/75.	NW	47708	Keefer Aircraft Engineer 11457 Glendale Way South Seattle, WA 98168
369HS; T.C. H3WE	SH690SO	Installation of SunAir Electronics Model ASB-60 or ASB-125 HF radio transceiver and associated system. Reissued 6/20/73.	WE	43344	Hughes Helicopters Div. of Summa Corporation Centinela & Teale Streets Culver City, CA 90230

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329-23A, -23D, -23E; T.C. 2A15	SA3704WE	Installation of Litton LTN-211 Omega Navigation System. Amended 1/30/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA2943WE	Installation of recognition lights on horizontal stabilizer upper surface. Amended 3/11/77.	WE	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 91406
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3206WE	Installation of Garrett AirNav 100 area navigation system. Amended 6/1/78.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3372WE	Installation of single or dual ONTRAC III VLF/Omega navigation systems. Amended 5/13/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3390WE	Installation of Global Model GNS-500A VLF/Omega navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3391WE	Installation of Delco C-IVA inertial navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3572WE	Installation of Sperry TERN-100 area navigation system. Issued 2/14/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -25; T.C. 2A15	SA3520WE	Installation of Sperry SPZ-500 autopilot and Sperry SPI-80/81 flight directors. Issued 11/23/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23D; T.C. 2A15	SA928EA	Installation of battery isolation circuit. Issued 7/14/72.	EA	70580	Scott Paper Company Scott Plaza Philadelphia, PA 19113
1329-23D; T.C. 2A15	SA931EA	Installation of battery isolation system. Issued 8/24/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
E1329-23E; T.C. 2A15	SA116GL	Installation of Global GNS-500A VLF/OMEGA navigation system. Amended 3/2/78.	GL	61880	Onan Corporation 1400 - 73rd Avenue, Northeast Minneapolis, MN 55432
1329-23F; T.C. 2A15	SA1989WE	Installation of United Control approach speed system, computer P/N 965-0158-001. Reissued 8/26/70.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA1049EA	Installation of seat tracks and cabin decks. Issued 6/7/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329-25; T.C. 2A15	SA1052EA	Installation of Solar gas turbine auxiliary power unit T-62T-40C. Amended 3/12/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
1329-25; T.C. 2A15	SA1056EA	Installation of a speed command of attitude and thrust system (SCAT). Amended 7/19/79.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA1581CE	Modification of aircraft to incorporate a fuel management computer. Issued 4/1/80.	CE	24540	Colt Electronics Company 15301 West 109th Street Lenexa, KS 66219
1329-25; T.C. 2A15	SA2920SO	Installation of BKM pitot heat monitor system. Issued 2/28/79.	SW	16652	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329-25;	SA2976SW	Floor plan arrangement, floorboards and seat track. Issued 4/13/79.	SW	47632	K-C Aviaiton, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2977SW	Pressurised water system lavatory, commissary, and bar. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2979SW	Flushing toilet with outside servicing capabilities. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2980SW	Galley component assembly. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329-25; T.C. 2A15	SA2981SW	Baggage compartment modification aft cabin, station 547.5 to 567.0. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2982SW	Baggage compartment modification, station 240.0 to 310.0, right side. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2983SW	Cabin entry ramp, center aisle, station 284.0 to 328.0.	SW	47632	K-C Aviation 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA3297WE	Installation of GTCP 30-92C auxiliary power unit. Issued 1/21/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-25; T.C. 2A15	SA3324WE	Installation of a single point refueling system for Lockheed Jetstar airplane. Issued 1/17/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-25; T.C. 2A15	SA3371WE	Installation of Teledyne angle of attack system. Issued 3/10/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
382; T.C. A1SO	SA3793WE	Installation of Tracor 7640A ONS. Issued 2/2/79.	WE	79200	Transinternational Airlines Engineering Department P.O. Box 2504 Oakland International Airport Oakland, CA 94164
382, 382B; T.C. A1SO	ST427SO	Installation of cargo rail system Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382, 382B, 382E; T.C. A1SO	SA733CE	Installation of cargo pallets.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382, 382B, 382E, 382F, 382G; T.C. A1SO	SA1625WE	Pallet assembly provisions per FAA Sealed L.A.S. Top Drawing 4035910 as modifying aircraft with four KC-97, 1800 gallon tanks installed in accordance with STC SA869WE. Amended 2/23/77.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
382, 382B, 382E, 382G; T.C. A1SO	ST400SO	Installation of palletized cargo loading and restraint system. Amended 11/25/74.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382, 382B, 382E, 382G; T.C. A1SO	ST407SO	Installation of palletized cargo loading and restraint system. Amended 4/7/72.	SO	52020	Lockheed-Georgie Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA303AL	Installation of 4000 gallon steel tank in the cargo compartment.	AL	44045	Interior Airways, Inc. P.O. Box 3029 Fairbanks, AK 99701
382B; T.C. A1SO	SA368SO	Palletized cargo loading system. Amended 7/10/67.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA374SO	Palletized cargo loading system per Lockheed Industrial Products top assy. dwg. 256-000. Amended 7/25/69.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA1274WE	Triple seat/bunk. Amended 7/10/67.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98109
382B, 382E, 382G; T.C. A1SO	ST401SO	Installation of palletized cargo loading and restraint Amended 11/25/74.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B, 382E, 382G; T.C. A1SO	ST527SO	Installation of inplane cargo system in accordance with Aeronautical Engineers, Inc. dwgs. AE2178 & AE2178, Change "C". Reissued 2/13/73.	SO	73670	Southern Air Transport, Inc. P.O. Box 1266 International Airport Miami, FL 33148
382B, 382E, 382G; T.C. A1SO	SA569AL	Installation Collins FPC-75 ground proximity warning system. Issued 11/25/75.	AL	08488	Alaska International Air, Inc. P.O. Box 60029 Fairbanks, AK 99701
382E; T.C. A1SO	SA2461WE	Installation of Sorm bulk liquid cargo tank assembly SI-3100. Issued 12/17/71.	NW	73820	Sorm Industries 7999 Perimeter Road, South Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
382E; T.C. A1SO	SA3171WE	The auxiliary power unit Model GTC 85-71 located in the forward end of the left hand main landing gear wheel well fairing has been replaced by an AiResearch Gas turbine compressor Model GTCP 85-98CK(A). Issued 4/9/76.	WE	87450	World Airways, Inc. Maintenance & Engrg. Center Oakland International Airport Oakland, CA 94614
382E, 382G; T.C. A1SO	SA2418WE	Installation of cargo loading system. Issued 9/29/71.	WE	70258	Saturn Airways, Inc. P.O. Box 2426 Oakland International Airport Oakland, CA 94614
382E, 382G; T.C. A1SO	SA3144WE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/9/76.	WE	68770	Rockwell International Corp. Collins Radio Group 750 S. Douglas Street El Segundo, CA 90245
382G; T.C. A1SO	ST913SO	Installation of six 24" x 36" plug type doors in cargo compartment walls. Issued 12/1/76.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G; T.C. A1SO	SA1056SO	Increase in zero fuel weight from 126,790 lbs. to 128,790 lbs. with pylon tanks on and 125,000 lbs. to 127,000 lbs. without pylon tanks. Issued 3/23/79.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G; T.C. A1SO	SA2912WE	Installation of palletized dual LTN-51 INS or dual LTN-72 INS or combination of either. Amended 9/26/74.	WE	51500	Litton Systems, Inc. Aero Product Division 21050 Burbank Blvd. Woodland Hills, CA 91364
382G; T.C. A1SO	SA2929WE	Installation of palletized dual LTN-51 or dual LTN-72 INS or combination of either. Issued 10/2/74	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91364

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
404; T.C. 1A7	SA325SO	Interior changes in passenger and jump seats.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
404; T.C. 1A7	SA328SO	Repair of corrosion damaged wing spar scarf splices. Reissued 11/7/78.	SO	54835	Marco Island Airways, Inc. 3250 Island Airways Miami, FL 33125
404; T.C. 1A7	SA329SO	Replacement of cockpit door lock.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA349SO	Hydraulic regulator change.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
404; T.C. 1A7	SA355SO	Whittaker 2L333021 NLG hydraulic pressure reducer valve replaced with Hydraulics Research #2028180-001 valve.	SO	73674	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
404; T.C. 1A7	SA392SO	Install Goodyear 9543138 wheels in place of Goodyear 9540512.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA395EA	Rear wing spar flange repaired.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	ST431SO	Installation of inflatable evacuation slide.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
404; T.C. 1A7	SA1122WE	Wing flap actuated landing gear aural warning system.	WE	62070	Pacific Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94119
404; T.C. 1A7	SA1428WE	Installation of cargo interior.	WE	62070	Pacific Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94119
404; T.C. 1A7	SA4142WE	Removal of rear air stair door. No installation data required. Issued 4/16/80.	WE	70375	Art Scholl Aviation 1700 West Miro Way Rialto, CA 92376

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MAULE AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M-4; T.C. 3A23	SA316SO	Installation of carburetor ice detector.	SO	71545	Charles B. Shivers, Jr. 8929 Valleybrook Road Birmingham, AL 35206
M-4; T.C. 3A23	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
M-4; T.C. 3A23	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Bee Dee M-4, M-4; T.C. 3A23	SA273WE	Vacuum system 121A.	WE	40689	Harms Industries P.O. Box 3246 Inglewood, CA 90306
M-4, 4C, 4S, 4T, M-4-210, 210C, 210S, 210T; T.C. 3A23	SA222AL	Installation of L-2500A skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
M-4, M-4C, M-4S, M-4T, M-4-210, M-4-210C, -210S, -210T, M-4-220, -220C, -220S, -220T, M-4-180C, M-4-180S, M-4-180T; T.C. 3A23	SA433AL	Installation of Wilbur's tire-cushioned model 2300 skis. Amended 12/16/71.	AL	86070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4, -4C, -4S, -4T, M-4-210, -210S, -210T; T.C. 3A23	SA693SW	AK223 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
M-4, M-4-210; T.C. 3A23	SA258CE	Remove right rear door.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4, M-4-210; T.C. 3A23	SA486CE	Installation of Canadian Aircraft Products, Ltd. Model 62-2000 floats. Amended 7/20/67.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M4, M-4-210, M-4-210C; T.C. 3A23	SA690SW	Wing tips modified.	SW	34900	Harvey J. Ferguson Upper Valley Aviation, Inc. McAllen, TX 78501
M4-4C, -4S, -4T, M-4-210, -210C, -210S, -210T; T.C. 3A23 Applicable only to aircraft modified by STC SA963SW.	SA808SW	Installation of Mitchell Model AK246 omni-tracker.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M-4-210, -5-210C; T.C. 3A23	SA164AL	Installation of auxiliary cabin heater and cowl flaps. Amended 2/10/76.	AL	86070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA589CE	Installation of Fleet Manufacturing, Ltd. Model 2500 floats.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA609CE	Installation of Edo Corp. Model 248A-2440 or Model 248B440 floats. Amended.	SO	56750	Maule Aircraft Corp. Spence Air Force Base Moultrie, GA 31768
M-4-210, M-4-220, M-4; T.C. 3A23	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M-4-210C, -220C, M-5-210, -220C; T.C. 3A23	SA2931WE	Installation of plexiglas covering for two main cabin doors, right passenger door, and baggage door. Issued 9/17/74.	WE	36190	Foothill Aircraft Sales and Service 13th and Benson Upland, CA 91786
M4-220; T.C. 3A23	SA415SO	Installation of Mitchell Century II autopilot. Amended 6/26/69.	SO	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M4-220; T.C. 3A23	SA417SO	Installation of aileron stabilizer and tracker.	SO	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768
M-4-220, M-4-220C, M-4-220S, M-4-220T;	SA610CE	Installation of Edo Corp. Model 248A-2440 or Model 248B-2440 floats. Amended 9/19/69.	SO	56750	Maule Aircraft Corporation Spence Air Force Base Moultrie, GA 31768
M-5-210C, M-5-22C, M-5-235C; T.C. 3A23	SA937SO	Installation of aqua Model 2400 floats. Reissued and amended 7/20/77.	SO	22776	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
M-5-210C, M-5-235; T.C. 3A23	SA1099SO	Installation of Fiberfloat model 2400 or 2400A floats and modified wing tips. Issued May 1980.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830
M-5-235C; T.C. 3A23	SA1008WE	Installation of poly-fiber covering material of fuselage and empennage. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
M-5-235C; T.C. 3A23	SA1099SO	Installation of Fiberfloat Model 2400 floats and modified wing tips. Issued 9/4/79.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-6, -6B; T.C. 781, 6A4	ST470SO	Installation of aft cargo door. Issued 6/22/71.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST495SO	Installation of aft cargo door. Issued 2/28/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST535SO	Installation of cargo floor. Amended 6/4/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST536SO	Installation of aft cargo door. Amended 6/16/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST555SO	Installation of rear cargo door. Issued 9/28/73.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33152
DC-6, -6B; T.C. 781, 6A4	ST595SO	Installation of exhaust system bracket. Reissued 1/6/75.	SO	02394	Aeronautical Engineering, Inc. 342 N.W. 2nd Court Dania, FL 33004
DC-6, -6B; T.C. 781, 6A4	ST597SO	Installation of aft cargo door. Amended and reissued 6/16/75.	SO	02394	Aeronautique Engineering, Inc. 342 N.E. 2nd Court Dania, FL 33004
DC-6, -6B; T.C. 781, 6A4	ST843SO	Installation of aft cargo door. Amended 6/3/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6 Series, DC-7 Series; T.C. 781, 6A3, 6A4, 4A10	SA4-328	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-329	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-330	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA76EA	Radome assembly 3016.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
DC-6A, DC-7B, -7BF, -7C, -7CF; T.C. 6A3, 4A10	SA470CE	Installation of Fairchild cockpit voice recorder Model A-100. Amended 3/1/67.	GL	81064	Universal Airlines, Inc. Detroit-Metropolitan Airport Inkster, MI 48141
DC-6A; T.C. 6A3	ST671SO	Installation of cargo loading/ restraint system for palletized cargo. Amended 6/24/69.	SO	46000	Jet Avion Corporation 950 S.E. 8th Street Hialeah, FL 33010
DC-6A, DC-6B; T.C. 6A3	ST34GL	Remove cabin pressurization system, modify cabin air heating and ventilating system. Issued 9/24/73.	GL	90135	Zantop International Airlines, Inc. Willow Run Airport Ypsilanti, MI 48197
DC-6A (C-118A), DC-6B; T.C. 6A3, 6A4	ST964SO	Installation of cargo interior, installation of cargo restraint and modification of pressurization system. Amended 10/17/78.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 480756 Miami, FL 33148
DC-6A, DC-6B, USAF C-118A (DC-6A); T.C. 6A4, 6A3	ST974SO	Installation of extra crew seating and air distribution system. Issued 3/29/78.	SO	15410	Bellomy - Lawson Aviation, Inc. P.O. Box 522760 Miami, FL 33152
DC-6A, USAF C-118A, Navy R6D-1, DC-63, R6D-1Z; T.C. 6A3	ST981SO	Deactivation of the cabin pressurization system, conversion of the cargo compartment to a class "E" compartment, and modification of the ventilation. Amended 10/10/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
DC-6A/C-118A; T.C. 6A3	SA1506CE	Engine driven cabin air compressors and associated cabin pressurization controls removed. Amended 4/8/80.	CE	64292	Petroleum Air Transport, Inc. P.O. Box 187 Hazlewood, MO 63042
DC-6A, DC-6B; T.C. 6A3	SA1363WE	Installation of Fairchild Industrial Products Model A100 cockpit voice recorder system. Amended 4/30/68.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 2426 Oakland International Airport Oakland, CA 94614

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C-118A; T.C. 6A3	SA770SO	Installation of cargo pallet and container loading and restraint system. Issued 4/12/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
R6D-1; T.C. 6A3	SA3406WE	Modification of oxygen system including addition of supply bottle, pressure relief valve, and microphone in smoke masks. Issued 5/19/77.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-6B; T.C. 6A4	ST454SO	Installation of aft cargo door. Issued 3/1/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST514SO	Installation of forward cargo door. Amended 2/12/75.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33146
DC-6B; T.C. 6A4	ST523SO	Installation of forward cargo door. Amended 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33146
DC-6B; T.C. 6A4	ST529SO	Installation of cargo floor. Reissued 3/12/73.	SO	08366	Airtech Service, Inc. P.O. Box 516 Miami, FL 33148
DC-6B; T.C. 6A4	ST532SO	Installation of main cabin compartment. Issued 3/27/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST553SO	Installation of cargo floor. Issued 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST729SO	Removal of pressurization and cabin cooling systems. Issued 7/10/72.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6B; T.C. 6A4	SA1434WE	Installation of modified DC-7 type cargo loading system.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 426 Oakland International Airport Oakland, CA 94914
DC-6B; T.C. 6A4	SA1457WE	Installation on auxiliary power unit in fuselage.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport AVenue Santa Monica, CA 90405
DC-6B; T.C. 6A4	SA1510CE	Engine driven cabin air compressors and associated cabin pressurization controls removed. Amended 4/8/80.	CE	64292	Petroleum Air Transport, Inc. P.O. Box 187 Hazelwood, MO 63042
DC-6B; T.C. 6A4	SA1604SW	Aft cargo door between F.S. 661 and F.S. 801. Issued 2/13/73.	SW	08351	Air Services, Inc. P.O. Box 2 Addison, TX 75001
DC-6B Cargo; T.C. 6A4	SA1663WE	Modification of DC-6B cargo aircraft to incorporate passenger or combination passenger/cargo arrangements.	WE	25970	Continental Airlines Los Angeles International Airport Los Angeles, CA 90009
DC-6B Cargo; T.C. 6A4	SA1765WE	Installation of cargo bulkhead, crew lavatory, vanity, galley and bunk.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-6B; T.C. 6A4	SA2721WE	Install external retardant tank. Amended 10/5/77.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
DC-6B; T.C. 6A4	SA2861WE	Installation of rear cargo door system GA61104. Issued 4/4/74.	SW	37093	Gary Aircraft Corporation P.O. Box 3486 San Antonio, TX 78211
DC-7 Series; T.C. 4A10	SA1-25	Substitution of rotating discs 9531691 and 9531704 in 9560285 and 9560286 brake assemblies.	GL	39011	Goodyear Aircraft Corporation Akron, OH 44309
DC-7 Series; T.C. 4A10	SA3-311	Wheels 150741-1 and/or 150741-5 and brake assembly 150835-5.	GL	15500	Bendix Aviation Corporation 401 North Bendix Drive South Bend, IN 46600
DC-7 Series; T.C. 4A10	SA4-54	Passenger/cargo interior arrangement configurations.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-7 Series; T.C. 4A10	SA4-91	One 4-piece divan left-hand side inboard facing and one 2-place divan right-hand side aft facing from Station 891 aft to pressure dome.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-124	Station 122 bulkhead.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-255	Aft cabin lounge.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-355	Interior modification coach to mixed class.	WE	07500	AiResearch AVviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-405	Interior modification to mixed class.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-442	Modification of communication equipment to provide navigator station.	SW	10150	American Airlines, Inc. Municipal Airport Tulsa, OK 74101
DC-7 Series; T.C. 4A10	SA4-507	Deterjet DJ1025 valve in place of Wright torquemeter booster pump upper housing per STC SEW-10.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-608	Engine mount core assemblies DE-643-1 on Wright TC18 series engines.	WE	30500	Dow-Elco, Inc. 1313 West Olympic Boulevard Montebello, CA 90640
DC-7 Series; T.C. 4A10	SA10SO	Provisioned for installation of 10,000 pound military pallet.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-7 Series; T.C. 4A10	SA23SO	Observer's seat fuselage Station 55.	SO	68130	Riddle Airlines P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA30SO	Two emergency exits at stations 437.9 - 460.5 from Type IV to Type III modified.	SO	68130	Riddle Airlines, Inc. P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA35SO	Access hole in horizontal stabilizer.	SO	68130	Riddle Airlines, Inc. P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA89SO	Oil separator B-300-1.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
DC-7 Series; T.C. 4A10	SA103WE	Interior arrangement for 104 passengers.	EA	19640	Camaero, Inc. Room 2004 27 Wall Street New York, NY 10005
DC-7 Series; T.C. 4A10	SA176NW	Installation of Faircaild Andover Model 204 auxiliary power unit for ground use only.	NW	18700	Butler Aircraft Company P.O. Box 338 Redmond, OR 97756
DC-7 Series; T.C. 4A10	SA188EA	Cabin interior modifications.	EA	80923	United States Overseas Airlines P.O. Box 234 Wildwood, NJ 08260
DC-7 Series; T.C. 4A10	SA214WE	Passenger interior arrangements and cargo interior.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. California Avenue Burbank, CA 91505
DC-7 Series; T.C. 4A10	SA294WE	Door in floor for cabin access.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA314WE	Passenger interior arrangements and cargo interior for operation of aircraft at 106,400 pounds zero fuel weight.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 North Clybourn Avenue Burbank, CA 91505
DC-7 Series; T.C. 4A10	SA364SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l. Airport Atlanta, GA 30320
DC-7 Series; T.C. 4A10	SA365EA	All weather landing system.	EA	74574	Sperry Gyroscope Company 2221 Smithtown Avenue Ronkonkoma, NY 11779

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-7 Series; T.C. 4A10	SA425WE	Single Federal (ITT) Type AFN3544 distance measuring equipment system.	SW	10150	American Airlines, Inc. Service Engineering Division Tulsa, OK 74151
DC-7 Series; T.C. 4A10	SA493SW	104-passenger interior arrangement.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
DC-7 Series; T.C. 4A10	SA500EA	Installation of microvision operational all-weather landing system.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
DC-7 Series; T.C. 4A10	SA588WE	Ceconite 101 covering of rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC-7 Series; T.C. 4A10	SA600SO	Cockpit voice recording system.	SO	08170	Airlift International, Inc. P.O. Box 335 Miami, FL 33148
DC-7 Series; T.C. 4A10	SA602WE	99-passenger interior arrangement modification including floor structure.	WE	05370	Aircraft Investors Hangar 28, Oakland Airport Oakland, CA 94614
DC-7 Series; T.C. 4A10	SA656WE	Interior modification for 98 occupants.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA724WE	Interior arrangement modification for 89 and 99 passengers and installation of modified navigator's seat.	WE	44188	International Aerodyne, Inc. 11319 Vanowen Street North Hollywood, CA 91603
DC-7 Series; T.C. 4A10	SA796WE	Wing flap attachments modification.	WE	30400	Douglas Aircraft Company, Inc. 3855 Lakewood Boulevard Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1068WE	Interior arrangement.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1075WE	AVQ9 radar altimeter, APN9 Loran receiver, AT144 HF transmitter and AR144 HF receiver.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1361WE	Fairchild Industrial Products Model A100, cockpit voice recorder system.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 2426 Oakland International Airport Oakland, CA 94614
DC-7, -7B, -7C; T.C. 4A10	SA2709WE	Installation of 3,000 gallon external retardant tanks under fuselage at wing center section. Amended 6/17/75.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-7, -7B, -7C; T.C. 4A10	SA3015WE	Installation of LH and RH upper viewing windows above side cockpit windows. Amended 6/17/75.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-7B; T.C. 4A10	ST631SO	Installation of loading and restraint system for palletized cargo. Amended 9/12/68.	SO	46000	Jet Avion Corporation 950 SE 8th Street Hialeah, FL 33010
DC-7B; T.C. 4A10	ST651SO	Installation of cargo transportation pallet and new assemblies (Heath Techna P/N AC-10195) pallet w/AC 10197 net, or AC-10194 pallet w/AC-10196 net.	NW	41625	Heath Techna Corporation 19819 84th Avenue Kent, WA 98031
DC-7CF; T.C. 4A10	SA469CE	Fairchild A-100 cockpit voice recorder.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul International Airport St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA1-599	Gables Engineering G-1010A instrument failure warning system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA1-601	Crimsco cargo container 6003 utilizing 6004 adapter in passenger compartment. Amended 5/3/67.	EA	62300	Pan American World Airways, Inc. 135 East 42nd Street New York, NY 10001
DC-8 Series; T.C. 4A25	SA3-603	Equipment furnishings, cargo provisions, forward cargo cabin DC-8.	GL	61700	Northwest Airlines, Inc. 1885 University Avenue St. Paul, MN 55111

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8 Series; T.C. 4A25	SA3-666	Aft cabin bin substituted for three 3-place left-hand tourist passenger seats between Stations 1253 to 1360.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul International Airport St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA4-918	Waste King flight data recorder 5424.	GL	80500	United Air Lines, Inc. 5959 South Cicero Avenue Chicago, IL 60650
DC-8 Series; T.C. 4A25	SA4-1026	Forward lounge.	WE	18390	Burns Aero Seat Company, Inc. 3900 Cohasset Street Burbank, CA 91502
DC-8 Series; T.C. 4A25	SA45SO	M6861-100 life rafts. Amended 5/8/67.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA52SO	6924-100 life rafts.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA55SO	B-500-2 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
DC-8 Series; T.C. 4A25	SA69EA	Brown line 21105-51 stretcher kit in passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 East 42nd Street New York, NY 10001
DC-8 Series; T.C. 4A25	SA70SO	Deactivation of center wing and forward auxiliary fuel tanks.	SO	61220	National Airlines, Inc. International Airport Miami, FL 33159
DC-8 Series; T.C. 4A25	SA77EA	SP-30 autopilot modification to allow manual pitch operation while maintaining automatic roll and yaw control.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA94SO	WN233-102 and WN333-101 passenger seats.	SO	02800	Aerosmith Products Corporation 6940 SW 12th Street Miami, FL 33144
DC-8 Series; T.C. 4A25	SA155SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA176SO	Auxiliary galley.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA194SO	Passenger seating and cabin interior.	SO	61220	National Airlines P.O. Box 2055 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA222EA	Bendix DRA-12/CPA-24 doppler computer system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA286SO	Gables G-1340B instrument warning system.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA293EA	Tray carrier.	EA	62300	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA305EA	Inflight motion picture system provisions. Amended 10/5/67.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA306SO	Forward lounge compartment configuration change.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA312EA	Aerotherm 1003 stretcher.	EA	62300	Pan American World Airways, Inc. Pan Am Building New York, NY 10017
DC-8 Series; T.C. 4A25	SA324EA	Litton LN-12 inertial navigation system and Bendix navigational computer.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, L.I., NY 11430
DC-8 Series; T.C. 4A25	SA333EA	Litton low range altimeter system and activation of altitude bar.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, L.I., NY 11430
DC-8 Series; T.C. 4A25	SA343SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l. Airport Atlanta, GA 30320

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8 Series; T.C. 4A25	SA350SO	Galleys 1 and 4.	SO	19846	Capitol Airways, Inc. Berry Field Nashville, TN 37202
DC-8 Series; T.C. 4A25	SA359SO	Seat belt attachment.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA370SO	Single radio altimeter.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA373SO	Installation of remote accelerometer and mount assy for DC-8 flight recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA377EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways, Inc. JFK International Airlines Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA380SO	Installation of stretcher assembly.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA445EA	Installation of cockpit voice recorder. Amended 2/27/67.	EA	62300	Seaboard World Airlines Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA479WE	Cargo bins and adapters in passenger cabin.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA497EA	Installation of Inflight Motion Picture Provisions.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA543EA	Cockpit voice recorder.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA544WE	Interior arrangements.	WE	79200	Trans International Airlines Box 2306, Airport Station Oakland, CA 94614
DC-8 Series; T.C. 4A25	SA545WE	Interior arrangements.	WE	79200	Trans International Airlines Box 2306, Airport Station Oakland, CA 94614
DC-8 Series; T.C. 4A25	SA582WE	Aileron power system modification to incorporate a flexible hose.	SO	62300	Pan American World Airways, Inc. Pan Am Building Miami, FL 33159
DC-8 Series; T.C. 4A25	SA602SO	Dual Collins AL-101 radio altimeter system.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA613SO	Installation of Collins FD-109 FD-109 flight director system. Amended 12/28/67.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA833WE	Two triple seats in main cabin and associated changes.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA855WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA994WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-8 Series; T.C. 4A25	SA1184WE	United Data Control cockpit voice recorder.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1220WE	Brownline pallet 23118-51 and Brownline pallet net 22672-51.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1347WE	GAlley 100 and 200 at fuselage stations 447.75 to 490, and 1385.5 to 1416.	WE	28560	Dale Engineering Company 12243 Branford Street Sun Valley, CA 91352

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8 Series; T.C. 4A25	SA1349WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1522WE	Substitution of Brownline cargo container assembly P/N 24026-51 for Douglas pallet assembly P/N 5776662-505 and net P/N 7778335.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airlines San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA1538WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder and Honeywell P/N 180 VI central air data computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA1796WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8 Series; T.C. 4A25	SA2318WE	Installation of emergency exit lights. Issued 3/2/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331
DC-8 and DC-8F Series; T.C. 4A25	SA1783WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8; DC-9; T.C. 4A25, A6WE	SA2534SW-D	Replacement of switch assembly, International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-8; DC-9; T.C. 4A25, A6WE	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, 104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-8, DC-9, DC-10; T.C. 4A25, A6WE, A22WE	SA2728WE	Incorporation of Holcombe Industries HI_LITE SYSTEM P/N 50-1001 for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -8F-54, -8F-55, -61, -61F, -62, -62F, -63, -63F; DC-9-11, -12, -13, -14, -15, -15F, -21, -31, -32, -32F, -41; DC-10-10; T.C. 4A25, A6WE, A22WE	SA10GL	Installation of Gayston Model 800LG and 800SC static dischargers on transport category airplanes. Issued 12/15/72.	GL	37125	Gayston Corporation 55 Janney Road Dayton, OH 45404
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, -61, -61F, -62, -62F, -63, -63F, DC-8F-54, -55; T.C. 4A25	SA928WE	Installation of replacement safety belt assemblies. Amended 10/9/74.	WE	68725	Rocket Jet/ARD Division American Safety Flight Systems, Inc. 1311 Grand Central Avenue Glendale, CA 91201
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, F-54, F-55; T.C. 4A25	SA1063SO	Installation of forward cargo door. Issued 4/6/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -61, -61F, -62, -62F, -63, -63F, DC8F-54/55; T.C. 4A25	SA2539WE	Installation of emblem light. Reissued 11/8/74.	EA	30000	DeVore Aviation Corporation Suite 108 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-8-12, -21, -33, -51, -52; T.C. 4A25	SA228EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 - 148th Avenue Jamaica, NY 11434
DC-8, -12, -21, -31, -32, -33, -52; T.C. 4A25	SA676CE	Installation of Crimsco cargo container, P/N 600301, utilizing Model 6004 adapter in passenger compartment.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
DC-8-20, -30, -40, -50 Series; T.C. 4A25	SA266GL	Installation of Litton LTN-211 Omega navigation system. Amended 4/26/79.	GL	61788	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
DC-8-20/50; T.C. 4A25	SA3030WE-D	Install a carry-on baggage module. Issued 9/7/76.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Airport San Francisco, CA 94128
DC-8-21; T.C. 4A25	SA3869WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 2/20/79.	WE	66405	G. S. Rasmussen P. O. Box 10519 Glendale, CA 91209
DC-8-21, DC-8-51; T.C. 4A25	ST449SO	Installation of air data computer with altitude display, altitude reporting, and altitude alerting capabilities. Issued 12/30/70.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, DC-8-51; T.C. 4A25	ST670SO	Installation of International Inflatables Co. P/N 68035 door-mounted emergency evacuation slide at forward entrance door and service door and International Inflatables Co. P/N 68085-3 door mounted emergency evacuation slide at aft entrance and service doors. Amended 10/6/69.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, -32, -51; T.C. 4A25	ST680SO	Installation of Pan Avion Model LSR-210 and LSR-273 emergency evacuation slides and Pan Avion slide pack containers P/N 017-33 and P/N 017-34 at forward and aft passenger entry and service doors.	SC	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -54, -55; T.C. 4A25	ST844SO	Installation of cargo interior. Amended 5/8/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, DC-8F-54, -55; T.C. 4A25	SA915SW	Installation of Bendix P/N 19E138-2A flexible drive shaft in lieu of Dana P/N 26567 universal joint shaft on Pratt & Whitney Model JT3D-1 engine gear box and C.S.D. Amended 10/1/71.	EA	16000	The Bendix Corporation Fluid Power Division 211 Seward Avenue Utica, NY 13503
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1033WE	Either single or dual Collins AL-101 radio altimeter systems. Amended 11/19/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airlines San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1034WE	Installation control and annuciation circuitry to implement Flight Director "Go-Around" command modes. Amended 4/1/68.	WE	80500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -54, -55; T.C. 4A25	SA1088SO	Installation of a cargo interior. Issued 7/11/79.	SW	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1405WE	Structural installation of Dorne and Margolin DMC 33-2 Satcom VHF radio antenna.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -32, -51, -61; T.C. 4A25	SA1980WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8, -8-21, -31, -33, -51, -52, -54F, -61, -62; T.C. 4A25	SA2211WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-21, -52; T.C. 4A25	SA2316WE	Revised interior arrangement to an all-tourist, 149-passenger configuration. Amended 5/23/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -51, DC-9 Series; T.C. 4A25, A6WE	SA2405WE	Installation of PICO Division pressure regulator P/N 3001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-21, -31, -33, -51, -52; T.C. 4A25	SA2573WE	Installation of interior modifications. Amended 3/6/74.	WE	80500	United Air Lines, Inc. Maintenance Base Engineering Department San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -8F-54, -8-61, -61F, -62, -63, -63F; T.C. 4A25	SA2827WE-D	Installation of Collins FPC-75 P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -52; T.C. 4A25	SA3033WE-D	Revise interior arrangement to increase coach seating. Amended 6/3/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -33, -51, -52, -61, -62, DC-8F-54; T.C. 4A25	SA3189WE	Installation of UAL NLG orifice support tube assembly, P/N 6F13548-501 and -502. Issued 10/4/77.	WE	80500	United Air Lines San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-33; T.C. 4A25	SA260NW	Modification of pax airplane configuration to cargo configuration (bulk). Issued 2/17/76.	NW	69204	Rosenbaim Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	ST266GL	Installation of a Litton LTN 211 Omega navigation system. Issued 8/25/78.	GL	61788	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA289GL	Load palletized livestock as bulk cargo. Issued 12/22/78.	GL	44036	InterContinental Airways, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA421NW	Cargo modification as done under STC's SA207NW and SA260NW and SA324NW. Issued 3/15/77.	NW	69204	Rosenbaim Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	SA2036WE	Installation of Henry Windscreen Model No. 48102. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8-33; T.C. 4A25	SA2825WE-D	Revise interior arrangement to accommodate all coach, 186 passenger overwater configuration. Amended 4/3/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-33; T.C. 4A25	SA3403WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo handling system, and increasing maximum landing and zero fuel weight. Amended 6/14/78.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846
DC-8-33; T.C. 4A25	SA3611WE	Modification to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3804WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/13/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3907WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3910WE	Modifications to permit an increase in maximum allowable zero fuel weight.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3612WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3749WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo floor, and increasing maximum landing and zero fuel weight. Issued 9/28/78.	WE	52995	McDonnell Douglas Corp. 3855 Lakewood Boulevard Long Beach, CA 90846

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-43; T.C. 4A25	SA3805WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3880WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 3/28/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3911WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43, -53; T.C. 4A25	SA2681WE	Installation of enclosed overhead stowage bins, sculptured ceiling panels, with integral lighting, improved sidewall lighting, and revised passenger service units. Issued 4/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-50, -60; T.C. 4A25	SA3963WE	Installation of dual Global GNS-500A VLF/Omega navigation systems. Issued 5/23/79.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
DC-8-51; T.C. 4A2	SA1768WE	Installation of stewardess seat Model 6878 on Nordskog galley Model 305A.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-51; T.C. 4A25	SA4078WE	Modificatons to permit an increase in maximum allowable zero fuel weight. Issued 2/6/80.	WE	66405	G. S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-51, -52; T.C. 4A25	SA2835WE-D	Installation of enclosed overhead stowage compartments, improved ceiling and sidewall lighting, relocation of motion picture projector compartments and complete cabin refurbishment. Issued 4/30/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-51, -52, -8F-54, -8-61; T.C. 4A25	SA3357WE-D	Retrofit of fuel quantity indicators and totalizers, Gull Airborne Instruments, Inc. P/Ns 206-009 and 206-016 series. Issued 1/30/78.	WE	80500	United Air Lines San Francisco Int'l Airport San Francisco, CA 91406
DC-8-51, -61; T.C. 4A25	ST857SO	Installation of Bendix ground proximity warning system. Amended 11/14/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8-52; T.C. 4A25	SA448NW	Installation of new look interior conversion kit for Aviaco Air Lines.	NW	41625	Heath Tecna Corporation 19819 - 84th Avenue, South Kent, WA 98031
DC-8-53; T.C. 4A25	SA3613WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3806WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3908WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3909WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3912WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8F; T.C. 4A25	SA605EA	Installation of pallet P/N 6524 incorporating Douglas cargo loading system or pallet P/N 6524 must use nets and be loaded in accordance with Douglas pallet P/N 5776662-505 instructions.	EA	66470	Ray, Daisley Co., Inc. 585 West Hoffman Avenue Lindenhurst, NY 11757

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8F-54; T.C. 4A25	SA633CE	Make and install cargo pallets in accordance with Brooks & Perkins Drawing List No. 16987. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	ST677SO	Installation of Nordskog galley Models 376, 377, 378 and 379 at right hand galley positions 1, 2, 3, and 4.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST684SO	Interior conversion of passenger cabin to accommodate 24 first class and 105 tourist class passengers. Amended 1/8/70.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST747SO	Installation of livestock transportation pens. Issued 1/31/75.	SO	21560	Casco Division Charlotte Aircraft Corporation P.O. Box 481225 Miami, FL 33148
DC-8F-54; T.C. 4A25	SA804EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8F-54; T.C. 4A25	SA813CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA843CE	Installation of cargo-pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA1793WE	Installation of Heathair AC-0152-1 structural container in DC-8F-54 aircraft equipped with cargo loading system No. 7778202-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19619 - 84th Avenue South Kent, WA 98031
DC-8F-54; T.C. 4A25	SA1991WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, -52; 22672-51, -52; or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54; T.C. 4A25	SA1997WE	Installation of Brownline pallet assembly P/N 40309 and net assembly Brownline P/N 21350-51, 21710-51, -52, Douglas P/N 7776431-1 or 7776431-501. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54; T.C. 4A25	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1 or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
DC-8F-54; T.C. 4A25	SA2255WE	Installation of Satco, Inc. pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8F-54; T.C. 4A25	SA2274WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
DC-8F-54; T.C. 4A25	SA2745WE-D	This modification provides seats, oxygen, cockpit communications, emergency equipment and other items necessary to carry six couriers or other persons authorized aft of Station 1370. Issued 4/22/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54; T.C. 4A25	SA3586WE-D	Installation of a removable dual Delco C-IV inertial navigation system for navigation only. Issued 10/27/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54, -55; T.C. 4A25	SA697CE	Installation of Aeroquip Corp. cargo tie-down net.	GL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8F-54, -55; T.C. 4A25	SA1623WE	Installation of Heath 88 x 125-inch cargo pallet P/N AC-10061-1 and cargo net P/N AC-10069-1 on subject models equipped with McDonnell Douglas cargo loading system No. 7776939. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1665WE	Installation of Heath Tecna 88 x 125-inch cargo pallet, P/N AC-10160 and net P/N AC-10069. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1875WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517 with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks and Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2234WE	Installation of Brownline Division Division structural container 41342-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2278WE	Installation of Brownline cargo container Model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-F54, -8-55 Series; T.C. 4A25	SA2137WE	Installation of Litton inertial navigation system(s) LTN51 (dual or single) or LTN72 (dual or single). Amended 12/14/78.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
DC-8F-54, -8-55; T.C. 4A25	SA4088WE	Installation of single or dual Litton LTN-72 INS. Issued 1/30/80.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
DC-8F-54, -8F-55, -8-61F, -62F, -63F; T.C. 4A25	SA1807WE	Installation of Brownline pallets and nets. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-61F, -8-63F; T.C. 4A25	SA2098WE	Modification by installation of structural cargo container 40619-101 and -102. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA1812WE	Installation of Heath Tecna 88 x 125-inch cargo pallets P/N AC-10355-1 and AC-10366-1 and net P/N AC-10357-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA2114WE	Installation of Brownline cargo container Model 40622. Amended 5/16/75.	WE	79500	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F, -9-32F, -33F; T.C. 4A25, A6WE	SA2152WE	Installation of Heath 88 x 108-inch cargo pallet AC-10527-1 and net AC-10196-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
DC-8F-54, -8-62F; T.C. 4A25	SA1974WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and Brownline net assembly P/N 22672-51, 22672-52, 23143-51, 40657, 40850, 40517, 22273-51, 22758-51, 22758-52; Douglas net assembly P/N 7776967-1 or Aeroquip net assembly P/N 3950020. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55; T.C. 4A25	SA672EA	Installation of two place courier seat, lavatory compartment and smoke curtain.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8F-55; T.C. 4A25	SA1395WE	Substitution of Brownline pallet P/N 23640-51 and P/N 23224-51 for Douglas pallet P/N 5776662-505.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-55, -8-61F; T.C. 4A25	SA1764WE	Installation of Heathair pallet Model AC10194 and net Model AC-10196. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8F-55, -61F, -63F; T.C. 4A25	SA1028EA	Installation of Collins FPC-75 ground proximity warning system. Amended 6/22/76.	EA	70600	Seaboard World Airlines, Inc. Seaboard World Building JFK International Airport Jamaica, NY 11430
DC-8F-55, -8-62F; T.C. 4A25	SA2059WE	Installation of 88 x 125-inch cargo pallet P/N 24076-51, 88 x 108-inch pallets P/N 40309101 and 40309102, and 88 x 53-inch pallets P/N 40464101 and 40464102 with net assemblies 22361-51, 22364-51, 22758-51, 22273-51, 21530-51, 21710-51, -52, and 21869-51. Amended 10/12/70.	WE	17749	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55, -8-63F; T.C. 4A25	SA589EA	Installation of dual omnitrac navigation system. Amended 7/19/68.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8F-55, -8-63F; T.C. 4A25	SA675EA	Installation of L. Marino cargo net. Amended 3/31/70.	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
DC-8F-55, -8-63F; T.C. 4A25	SA725EA	DC-8F pallet P/N LM1600 (1.50 Fwd), DC-8-63F pallet P/N LM1600 (1.50 Fwd).	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
DC-8F-55, -8-63F; T.C. 4A25	SA2218WE	Installation of Satco cargo pallet P/N 31 80-501, NAS classification 3610-2A3P and P/N 31076-501, NAS classification 3610-2A1P with cargo nets Brownline P/N 22758-51, -52, -54, 22672-52, 22273-51, 23226-51, 40517-101; Heath Tecna P/N AC 10292-1; Marino P/N LM 1500-100; and ANCRA Corp. P/N 40178-10. Amended 10/12/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8-61; T.C. 4A25	SA467EA	Inflight Motion Picture provisions. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-61; T.C. 4A25	SA1400WE	Installation of 198-passenger interior arrangement. Amended 4/17/74.	GL	80500	United Air Lines, Inc. Executive Offices 1200 Algonquin Road Elk Grove Township, IL 60007
DC-8-61; T.C. 4A25	SA1926WE	Dual installation of A.C. Electronics Carousel IV INS units. Amended 1/16/70.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2128WE	Installation of RCA Model AVQ-30C weather radar system.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2558WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other interior changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2674WE	Revised interior arrangement. Issued 3/23/73.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94158
DC-8-61; T.C. 4A25	SA2739WE-D	Revised seating configuration. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2741WE-D	Installation of equipment to provide guidance to flight director and SP-30AL autopilot to conduct two-segment approaches. Amended 4/7/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2804WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 3/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-61; T.C. 4A25	SA2824WE-D	Installation of dual Delco C-IV inertial navigation systems. Issued 1/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3032WE-D	Install carry-on baggage module in place of one first class seat assembly. Amended 12/27/76.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3038WE-D	Installation of dual Collins FD-109 flight director system. Issued 5/24/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3039WE-D	Installs galley units and all supporting structure including plumbing and wiring at three locations. Amended 8/19/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3040WE-D	Installation of cabin new look, cabin refurbishment, inflight entertainment installation, passenger seat procurement and rework, and internal partitions and stowage cabinet. Issued 6/11/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61;	SA3356WE-D	Revise interior arrangement to accommodate dual class, 12 first class and 177 coach passenger configuration. Issued 11/4/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3582WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3587WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 12/14/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3588WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 1/5/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3593WE-D	Seat mix change from 26 F/C and 156 coach passenger configuration to 26 F/C and 164 coach passenger configuration. Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA4091WE	Deletion of a pair of excess Type 1 exits at station 1124. Issued 1/22/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61, -61F, DC-8-63, -63F; T.C. 4A25	SA1873WE	Installation of Litton Systems dual LTN-51 or LTN-52 inertial navigation systems. Amended 1/4/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61, -62, -62F; T.C. 4A25	SA1006EA	Installation of cabin interior furnishings. Amended 8/26/77.	EA	12500	Atlantic Aviation Corporation Greater Wilmington Airport P.O. Box 1709 Wilmington, DE 19899
DC-8-61, -63; T.C. 4A25	SA1096SO	Installation of Tracor, Inc. omega navigation systems. Issued 8/23/79.	SO	19848	Capitol International Airways, Inc. P.O. Box 325 Smyrna, TN 37167
DC-8-61F; T.C. 4A25	ST687SO	Installation of AIF class divider partitions, left hand and right hand assembly, P/N 32012 with header assembly, P/N 32013.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-61F; T.C. 4A25	SA2157WE	Installation of 242 passenger seating arrangement. Issued 6/5/70.	WE	81064	Universal Airlines 401 McCormick Street San Leandro, CA 94577
DC-8-61F; T.C. 4A25	SA2481WE	Installation of Trans Com Model 1357 movie projector and screen assemblies. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-61F; T.C. 4A25	SA3279WE	Installation of Litton ground proximity warning system computer P/N 456300-01, -202 in the provisions under STC SA1028EA. Issued 10/28/76.	WE	51500	Litton Systems, Inc. 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F; T.C. 4A25	SA2800WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Amended 3/12/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F, DC-8-63F; T.C. 4A25	SA630CE	Installation of cargo pallets. Amended 11/1/79.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8-61F, -8-63F; T.C. 4A25	SA1733WE	Installation of Nordskog seat assembly P/N 61247 with certain interior arrangements. Amended 4/12/71.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-62; T.C. 4A25	SA1959WE	Installation of movie projection system.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-8-62; T.C. 4A25	SA2299WE	Installation of third AC electronics carousel IV inertial navigation system. Issued 12/31/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2310SW	Install wheel and brake advisory system. Issued 5/17/76.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
DC-8-62; T.C. 4A25	SA2377WE	Installation of Collins Radio Company INS - 61B inertial navigation system. Amended 12/7/71.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2533WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other architectural changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2581WE	Installation of Collins Radio Company inertial navigation systems. Issued 8/23/72.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
DC-8-62; T.C. 4A25	SA2738WE-D	Revise seating arrangement to 154 passenger configuration; revise passenger service unit locations to comply with seating configuration; install class dividers and curtains. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2742WE-D	Install dual class seating arrangement (4 and 6 across). Amended 5/2/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2818WE-D	Installation of triple Delco Electronics carousel IV-A inertial navigation system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2819WE-D	Installation of Atlantic Aviation wide body kit. Issued 11/8/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2820WE-D	Installation of passenger entertainment and automatic announce system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2840WE-D	Install an alternate all tourist seating and galley configuration. Galley configuration was previously approved under STC SA2296WE. Amended 6/8/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2904WE	Installation of GAMMA inertial navigation system. Issued 7/2/74.	WE	71838	The Singer Company Kearfott Division 5730 West Manchester Avenue Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-62; T.C. 4A25	SA3351WE-D	Installs a 181 passenger all coach cabin seating configuration.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3361WE-D	Installs a 16 first class/123 coach dual class seating configuration. Issued 1/16/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3576WE-D	Revise interior arrangement to accommodate 162 coach passenger configuration. Issued 6/2/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3584WE-D	Seat mix change from 162 passenger all coach configuration to 18F/129Y-147 passenger configuration. Amended 11/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62, -62F; T.C. 4A25	SA993EA	Installation of Inflight Motion Pictures, Inc. 16 mm. movie projection system IR4000 and screen assemblies. Amended 8/26/77.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-62F; T.C. 4A25	SA2308WE	Installation of cargo barrier net. Issued 1/27/71.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-8-62F; T.C. 4A25	SA2785WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 11/20/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-62F, DC-9-31; T.C. 4A25, A6WE	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 12/10/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
DC-8-63; T.C. 4A25	SA649SO	Installation of lounge table AIF P/N 31538-101.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-63; T.C. 4A25	ST681SO	Installation of class divider partition assembly P/N 31929-100 left hand and 31929-200 right hand at fuselage station 2900.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST682SO	Installation of lounge table assembly P/N 31928/100 right hand and P/N 31928-101 left hand at fuselage station 338.0.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST728SO	Interior modification and installation of 251 passenger service units and galley attachments to provide for 251 passenger arrangement (less seats and galleys). Issued 4/28/72.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-8-63; T.C. 4A25	ST737SO	Main cabin interior modifications. Issued 3/28/73.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-8-63; T.C. 4A25	SA750NW	Installation of Mark I interior kit. Issued 4/12/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
DC-8-63; T.C. 4A25	SA1730WE	Installation of cockpit voice recorder, seat lights, passenger service outlets, communication panel relocation, galley wiring changes, flight data recorder and vertical accelerometer, pitot tube with heater circuit, marker beacon.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA1738WE	Modification of interior arrangement to 221 passenger Military Airlift Command configuration. Amended 11/7/68.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA1909WE	Modification of interior arrangement to provide automatic folding attendant seats at the four jet escape exits.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA2704WE-D	Installation of enclosed overhead stowage bins, sculptured ceiling panels with integral lighting, cabin refurbishment. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-63; T.C. 4A25	SA3854WE	Installation of Tracor 7640A ONS. Issued 3/21/79.	WE	79200	Transinternational Airlines P.O. Box 2504 Oakland International Airport Oakland, CA 94614
DC-8-63, -63F; T.C. 4A25	SA2154WE	Installation of triple Litton LTN-51 inertial navigation system. Amended 4/23/71.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
DC-8-63F; T.C. 4A25	SA652EA	Installation of dual Decca doppler systems, Type 72. Reissued 7/2/69.	EA	44900	I.T.T. Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
DC-8-63F; T.C. 4A25	ST766SO	Installation of double deck livestock transportation pens. Issued 11/1/77.	SO	11320	Animal Air Services, Inc. 14441 Northwest 13 Court Miami, FL 33162
DC-8-63F; T.C. 4A25	SA1039EA	Installation of animal restraint system for air shipment of livestock. Reissued 11/9/78.	EA	79304	Transmeridian Air Cargo Ltd. Stansted Airport Stansted, Essex, England
DC-8-63F; T.C. 4A25	SA1731WE	Install single Decca Model 72 doppler radar (ground speed and drift angle only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA1928WE	Installation of Heath Tecna 88 x 125-inch cargo pallet P/N AC-10065-1 with Heath Tecna net P/N AC-10292-1 or Brownline net P/N 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1950WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and net assembly P/N 22672-51, 22672-52, 22758-51, 22758-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1955WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, 22758-52, 22672-51, 22672-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1978WE	Installation of underseat baggage restraint system with certain specified seat models. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1987WE	Installation of Edo Model 144 ADF-Loran antenna splitter.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2017WE	Installation of Decca Model 72 doppler radar (ground speed and drift meter only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2018WE	Installation of Decca Model ADL-21 Loran.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2087WE	Installation of Cargo Systems, Inc. 88 x 125-inch cargo pallet assembly 1950-90-1 with Brownline net P/N 22758-51.	WE	19890	Cargo Systems, Inc. 1040 West Hoover Orange, CA 92667
DC-8-63F; T.C. 4A25	SA2113WE	Installation of two Decca Type 05 Omnitrac 2B Doppler/Loran navigation computer systems with pictorial displays.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2247WE	Installation of Lockheed Aircraft Services Company Model 250-A weight and balance computer system. Issued 10/9/70.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2259WE	Installation of Brownline pallet assembly P/N 41339 and Brownline net assembly P/N 41344. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA2287WE	Installation of Henry Engineering cargo container Model 52501. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-63F; T.C. 4A25	SA2313WE	Installation of Kollsman "Slim Pac" altitude alerting system. 3/1/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8=63F; T.C. 4A25	SA2314WE	Revised seating arrangement to 244 passenger all tourist configuration. Issued 2/18/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2427WE	Installation of a third attitude indicator. Issued 10/15/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2465WE	Installation of dual Delco Carousel IV inertial navigation system. Issued 12/30/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2522WE	Installation of Nordskog tray carrier storage unit Model 798P. Issued 5/17/72.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-63F; T.C. 4A25	SA2604WE	Installation of Custom Products passenger type seat and flight crew glare protection curtain. Issued 10/24/72.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2616WE	Installation of Trans Com Model 1144 movie projector, screen assemblies and sound system. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
DC-8-63F; T.C. 4A25	SA2632WE	Modification of airplane to provide attitude information from INS in lieu of two vertical gyros (this modification pertains only to aircraft previously modified by STC SA2465WE). Issued 1/9/73.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2634WE	Installation of three Litton LTN-72 inertial navigation systems. Issued 1/9/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-63F; T.C. 4A25	SA2957WE	Installation of separate differential oil pressure system and associated warning light indication. Issued 12/23/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA3082WE	Installation of Satco, Inc. cargo pallet assembly, P/N 31250-521. Issued 9/3/75.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8-63F; T.C. 4A25	SA3123WE	Installation of cargo container P/N 10-1000. Amended 4/19/76.	WE	25955	Container Development 2636 North Ontario Burbank, CA 91504
DC-8-63F; T.C. 4A25	SA3176WE	Installation of Litton Aero Products digital ground proximity warning system. Issued 4/21/76.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-9 Series; T.C. A6WE	SA333SO	Beverage bar.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA335NW	Modified cabin interior kit. Issued 8/13/76.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
DC-9 Series; T.C. A6WE	ST399SO	Addition of underseat luggage restraint.	SO	73674	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA457CE	Lockheed Aircraft service 109D flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA508CE	Installation of Safe Flight P/N 1300-33 SCAT computer in lieu of P/N 1300-32.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA520CE	Installation of airborne engine vibration monitoring system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9 Series; T.C. A6WE	SA580EA	Installation of Collins Radio CLC Type 560F-3 area navigation system.	EA	31420	Eastern Airlines, Inc. 10 Rockefeller Plaza New York, NY 10020
DC-9 Series; T.C. A6WE	ST626SO	Removal of complete passenger accommodations; installation of cargo interior. Amended 5/13/69.	SO	34220	Fairchild Hiller Corporation Aircraft Service Division St. Augustine, FL 32084
DC-9 Series; T.C. A6WE	ST627SO	Installation of cargo accommodations. Amended 5/13/69.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
DC-9 Series; T.C. A6WE	SA640NW	Installation of deep interior rack kits. Issued 7/21/78.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
DC-9 Series; T.C. A6WE	SA727NW	Delete L.H. galley, add coatroom, add 2 auxiliary galley units at forward left and right side of cabin. Issued 2/27/79.	NW	78672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
DC-9 Series; T.C. A6WE	SA730CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA752CE	Install Bendix gyro horizon, P/N 1978130-2, and Bendix inverter, P/N 1964771-2.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA829CE	Install Butler National Corporation flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA1003SW	Modify 721B galley to 721B-1 and install.	SW	84250	Vought Aircraft Service Co. Div. of LTV Aerospace Corp. 4100 North Main Street Fort Worth, TX 76107
DC-9 Series; T.C. A6WE	SA1455WE	Interior configuration modification.	WE	16892	Bonanza Air Lines 3737 East Bonanza Way P.O. Box 12405 Phoenix, AZ 85034
DC-9 Series; T.C. A6WE	SA1784WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-9 Series; T.C. A6WE	SA1797WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-9 Series; T.C. A6WE	SA2330WE	Installation of battery-powered emergency exit lighting in tail-cone. Issued 3/29/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331
DC-9 Series; T.C. A6WE	SA2451SW	Marathon Battery Co. P/N 85-0050 six cell magnesium emergency light pack. Issued 4/20/77.	SW	54810	Marathon Battery Company 8301 Imperial Drive Waco, TX 76710
DC-9 Series; T.C. A6WE	SA2541WE	Installation of tail cone slide cover. Issued 6/2/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352
DC-9 Series; T.C. A6WE	SA3623WE	Installation of stretcher carrier P/N 2003. Issued 4/13/78.	WE	08205	Air Medic, Inc. 12517 Chandler Blvd. No. Hollywood, CA 91607
DC-9-10; T.C. A6WE	ST498SO	Modification of main landing gear brake stud. Issued 4/19/72.	SO	84470	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-9-10-20, -30, -40 Series; T.C. A6WE	ST699SO	Installation of International Inflatable Company Model 68090 emergency evacuation slide modified with Pan Avion valve assembly P/N 526-43. Issued 11/9/71.	SO	62384	Pan Avion P.O. Box 213 Miami, FL 33101
DC-9-10, -20, -30, -40 Series; T.C. A6WE	SA2223WE	Installation of door mounted battery-powered emergency lights. Amended 5/6/71.	WE	44266	International Inflatables Company 9880 San Fernando Boulevard Pacoima, CA 91331
DC-9-10, -30; T.C. A6WE	ST870SO	Installation of Collins FPC 75 ground proximity warning system. Issued 11/25/75.	SO	73874	Southern Airways, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-10, -30; T.C. A6WE	SA1177CE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/11/79.	CE	62030	Ozark Air Lines, Inc. St. Louis International Airport Lambert Field St. Louis, MO 63145
DC-9-10, -30; T.C. A6WE	SA3097WE	Installation of Collins Radio Co. Model FPC-75 ground proximity warning system. Amended 4/6/76.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-11, -12, -13, -14, -15, -31, -32; T.C. A6WE	ST735SO	Installation of protective rigid cover over tail cone emergency evacuation slide (installation of International Inflatables Model 68090 slide per STC ST676SO or equivalent required with this STC). Issued 12/4/72.	SC	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
DC-9-11, -12, -13, -14, -15, -15F; T.C. A6WE	SA2233WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-9-11, -12, -13, -14, -15, -15F, -21; T.C. A6WE	SA2503WE	Installation of replacement cooling turbine nozzle assembly. Issued 4/20/72.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91503
DC-9-11, -12, -13, -14, -15, -15F; T.C. A6WE	SA2645WE	Installation of dual Litton LTN-51 inertial navigation system. Issued 2/2/73.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
DC-9-11, -14, -15F, -31; T.C. A6WE	SA1933WE	Installation of under seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-11, -31; T.C. A6WE	SA1195EA	Installation of Magee Plastics passenger service units (PSU's) in lieu of original manufacturer's PSU's. Issued 5/19/80.	EA	54200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15237
DC-9-14, -15; T.C. A6WE	SA527CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2981WE	Modification of No. 1 galley, Hughes Airwest P/N RW2530045 or Nordskog P/N 742A Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2982WE	Modification of No. 2 galley, Hughes Airwest P/N RW2530051 or Nordskog P/N 645A. Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-14, -31; T.C. A6WE	ST676SO	Installation of International Inflatables Company emergency evacuation slide, Model 68090, at tail cone exit.	SC	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-9-14, -9-31, -9-32; T.C. A6WE	SA2765WE	Installation of altitude alerting and reporting capabilities. Issued 10/10/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15; T.C. A6WE	SA1511CE	Increase the passenger capacity from 83 to 90. Issued 9/6/79.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9-15; T.C. A6WE	SA1728WE	Installation of Bendix Model DRA 12 Doppler navigation system and relocation of ATC transponder antenna and marker beacon antenna. Amended 2/6/70.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-9-15; T.C. A6WE	SA2587WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 3/18/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
DC-9-15; T.C. A6WE	SA2764WE	Altitude alerting and reporting capabilities are provided by installation of Harowe P/N 2031-01-1 altitude alert system, replacement of captain's barometric altimeter with a Harowe P/N 2050-01-1 servo actuated altimeter and two existing air data computers are replaced by Sperry P/N 2587400-176 air data computer. Issued 9/28/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-15; T.C. A6WE	SA3051WE	Change seating configuration to 80 economy class, and installation of two auxiliary galleys at fuselage stations 764.5 to 784. Issued 5/29/75.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846
DC-9-15F; T.C. A6WE	SA2028WE	Replacement of V.H.F. 7533483 SAU polyethylene dielectric coaxial cables with Type RG115 A/U PTFE dielectric coaxial cables and addition of head-shield between APU exhaust shroud and wiring conduits.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
DC-9-15F; T.C. A6WE	SA2763WE	The captain's altimeter is replaced by Harowe P/N 2050-01-1 servo actuated altimeter and existing altitude alert system is replaced by Harowe P/N 2031-01-1 altitude alert system. Issued 9/19/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15F; T.C. A6WE	SA2788WE	Installation of galley assembly, P/N RW2530045. Issued 12/6/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA2789WE	Installation of Hughes Airwest galley assembly, P/N RW2530051. Issued 12/10/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA3558WE	Installation of 535-gallon auxiliary fuel tank system in forward cargo compartment. Issued 3/8/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
DC-9-21, -31, -32F (USAF C-9A), -32, -33F, -41; T.C. A6WE	SA862EA	Addition of airspeed select function to speed command/autothrottle system. Amended 6/27/78.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
DC-9-21, -31, -32, -32F, -33F, -41, -51; T.C. A6WE	SA2212WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 8/24/75.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-9 Series 30; T.C. A6WE	SA130GL	Installation of Systron-Donner Model 8160-20-P10 angular rate sensor in lieu of presently installed rate gyros in pitch-axis computer, roll-axis computer, and stability augmentation computers. Issued 7/23/76.	GL	61625	North Central Airlines, Inc. 7500 Northliner Drive Minneapolis, MN 55450
DC-9-30; T.C. A6WE	SA3642WE	A speed comman system, safe flight P/N 1312-25B installed. Issued 5/16/78.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-30, -9-31; T.C. A6WE	SA294NW	Interior arrangement, coatroom installation. Issued 5/14/76.	NW	48532	AME Manufacturing 800 North 6th Street Renton, WA 98055
DC-9 Series 30; T.C. A6WE	ST4998SO	Modification of main landing gear brake stud. Issued 4/19/72.	SO	84770	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-9 Series 30; T.C. A6WE	SA1658WE	Installation of Airborne vibration monitoring system equipment.	WE	25917	Consolidated Electrodynamics Corp. Transducer Products Division 1400 South Shamrock Avenue Morovia, CA 91016
DC-9 Series 30; T.C. A6WE	SA2473WE	Installation of AiResearch cooling turbine P/N 204950-5-3 in lieu of P/N 204950-5-2. Issued 2/18/72.	WE	07505	AiResearch Manufacturing Company Division of Garrett Corporation 9851 Sepulveda Boulevard Los Angeles, CA 90009
DC-9 Series 30; T.C. A6WE	SA2803WE	Replacement of splined end on DC-9 nose gear cylinder, Douglas P/N 5920602. Amended 2/1/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9 Series 30; T.C. A6WE	SA2805WE	Replacement of splined end of DC-9 nose gear cylinder. Issued 1/18/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9-30; T.C. A6WE	SA3887WE	Installation of two Howell Model H900 solid state exhaust gas temperature indicators. Issued 3/29/79.	WE	43340	Hughes Airwest 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-30; T.C. A6WE	SA4059WE	Installation of ground proximity warning system (GPWS) and altitude alert system. Issued 12/13/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-30, -32F, -33F, -51; T.C. A6WE	SA3115WE	Installation or Collins ground proximity warning system. Amended 4/7/76.	PC	41260	Hawaiian Airlines Honolulu International Airport Honolulu, HI 96820
DC-9-30, -50; T.C. A6WE	SA84GL	Install Bendix GPW-83 ground proximity warning system. Amended 8/10/76.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450
DC-9-31; T.C. A6WE	ST464SO	Installation of Decca IIB 06 omnitrac area navigation system. Operations will not be predicated on use of vertical guidance information of area navigation system. Amended 6/29/71.	SO	31420	Eastern Airlines International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	ST557SO	Installation of 99 passenger interior arrangement. Issued 10/6/73.	SO	31420	Eastern Airlines International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	SA878EA	Installation of SFENA standby horizon indicating system. Reissued 12/22/75.	CE	62030	Ozark Air Lines Box 10007, Lambert Field St. Louis, MO 63145
DC-9-31, -32; T.C. A6WE	SA3888WE	Installation of an auxiliary fuel tank system in the forward baggage compartment. Amended 5/25/79.	WE	43340	Hughes Air West, Inc. 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-31, -32, -32F, -33F, -41; T.C. A6WE	SA2502WE	Installation of replacement cooling turbine nozzle assembly. Amended 11/13/73.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91504
DC-9-31, -9-51; T.C. A6WE	SA1019EA	Installation of Collins Model FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
DC-9-31/-51; T.C. A6WE	SA3455WE	Installation of tourist and first class interiors. Amended 10/12/79.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-9-32; T.C. A6WE	ST856SO	Installation of Bendix ground proximity warning system. Issued 10/21/75.	SO	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	ST921SO	Fabrication and installation of baggage stowage rack, P/N 325100. Issued 1/28/77.	SO	29234	Delta Airlines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	SA1895WE	Installation of a second observer seat in flight crew compartment.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-9-32; T.C. A6WE	SA2106WE	Modification consists of interior arrangement, various passenger entertainment systems and avionics equipment. Reissued 8/20/73.	GL	64730	Playboy Enterprises, Inc. 919 North Michigan Avenue Chicago, IL 60611
DC-9-32 (VC-9C), DC-9-32F (C-9A); T.C. A6WE	ST248GL	Installation of Collins Model FPC flight profile comparator, P/N 622-2615-500, and Harowe barometric altitude rate computer, P/N 4030-03-1. Amended 7/19/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
DC-9-32F; T.C. A6WE	SA1043EA	Installation of structural provisions for executive interior. Issued 11/24/76.	EA	12500	Atlantic Aviation Corporation Box 1709 Wilmington, DE 19899
DC-9-32F; T.C. A6WE	SA2598WE	Installation of passenger pallet system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA697EA	Installation of (4) Aerojet-General Corp. 15 KS-1000-A1 or Bristol Aerospace (1968) Ltd. 15 KS-1000-A1(B) rocket engines and fairings. Amended 2/29/72.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-9-32F, -9-33F; T.C. A6WE	SA1193EA	Installation of ceiling panel kits. Issued 4/16/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-32F, -33F; T.C. A6WE	SA1970WE	Installation of 88 x 108-inch cargo pallet P/N 24545-51, -52, or -53 with net P/N 24550-51, -52, or -53 and 88 x 54-inch cargo pallet P/N 24546-51, -52, or -53 with net P/N 24551-51 or -52. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2021WE	Installation of various cargo pallets and nets (per Tridair "Loading Instructions Drawing No. 40414). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2092WE	Installation of Heath 54 x 88-inch cargo pallet AC-10526-1 and net AC-10657-101. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-9-41; T.C. A6WE	SA3366WE	Modification of cabin interior. Installation includes all or part of the following overhead storage compartments, sculptured ceiling and sidewall panels, flourescent cabin lighting, standby lighting, emergency lighting, and an overwing exit locator sign. Amended 3/31/78.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-9-51; T.C. A6WE	SA3660WE	Installation of Carrier Aircraft coat closet Model EAL951-1. Issued 6/6/78.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-51; T.C. A6WE	SA3800WE	Installation of a 130 passenger seating arrangement, two galleys, and associated water drain mast. Issued 12/6/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
DC-9-51; T.C. A6WE	SA4002SW	In-place cargo system. Issued 7/31/79.	CE	04250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74112
DC-9, DC-10-30; T.C. A6WE	SA1068EA	Replacement of Fairchild Burns seats by Magee Plastics Co. seat trim kit P/N 67203. Issued 2/14/78.	EA	53200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15237
DC-10; T.C. A22WE	SA285NW	Installation of Trans Com System. Issued 4/15/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
DC-10; T.C. A22WE	SA419NW	Class divider installation. Issued 3/10/77.	NW	48532	KME Manufacturing 800 North 6th Street Renton, WA 98055
DC-10; T.C. A22WE	SA713NW	Installation of class divider. Issued 1/30/79.	NW	48532	KME Manufacturing Company The Commons Building 1200 112th N.E. Bellevue, WA 98004
DC-10; T.C. A22WE	SA3892WE	Installation of Stowe Corp. service carts. Issued 3/23/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-10; T.C. A22WE	SA2611WE	Installation of three Litton LTN-51 inertial navigation systems, an inertial navigation switching unit and two Sperry horizontal situation indicators. Amended 3/5/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10;	SA2816WE	Modification of DC-10-10 aircraft for the installation of spacer pallets. Issued 2/8/74.	WE	80500	United Air Lines, Inc. Engineering Department San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2836WE-D	Installation of Bell and Howell video entertainment system in A, B and C zones of passenger cabin. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2837WE-D	Install new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 12/9/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-10; T.C. A22WE	SA2888WE	Installation of three Litton LTN-51 or LTN-72 inertial navigation systems. Issued 2/28/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10; T.C. A22WE	SA3025WE-D	Installation of refrigeration cooling for DME interrogators. Amended 3/12/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3031WE-D	Installation of four additional serving cart tie downs on main deck. Amended 9/13/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3035WE-D	Install slide-raft assembly at each LH and RH cabin door exit. Issued 2/17/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3036WE-D	Modifies aircraft to install dual Delco C-IV inertial navigation systems (INS) for attitude and direction reference, navigation, and autopilot steering. Issued 3/22/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3127WE	Installation of first class passenger seats incorporating unitized oxygen systems. Issued 12/11/75.	WE	85126	Western Airlines, Inc. 6060 Avion Drive Los Angeles, CA 90052
DC-10-10; T.C. A22WE	SA3358WE-D	Reduces first class seating to 16 seat places, installs 9-across coach seating - 243 seat places, installs class divider, lounge table, PSF, and closets in zone A, closet in zone C. Issued 11/15/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3510WE	Replace primary thrust reverser with conical nozzle and plug; modify pylon aft fairing; and remove upper and lower actuators and drive cables. Issued 10/31/77.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012
DC-10-10; T.C. A22WE	SA3580WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 4/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3591WE-D	Installs new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 9/11/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3696WE	Training requirements, special limitations, and installation of required provisions, including communications and equipment to permit occupancy of the lower galley during taxi. Issued 7/12/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3815WE	Installation of a video projection system. Amended 2/28/79.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10; T.C. A22WE	SA4041WE	Installation of Litton LTN-211 Omega navigation system. Issued 11/30/79.	WE	85126	Western Airlines, Inc. 6060 Avion Drive Los Angeles, CA 90052
DC-10-10; T.C. A22WE	SA4126WE	Installation of Stowe Corp. entree cart, P/N 10074. Issued 4/9/80.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-10, -10-10F; T.C. A22WE	SA2524WE	Installation of lounge seats, four-place divan, L-shaped bar, and cocktail tables. Amended 3/8/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2770WE	Installation of visual entertainment system. Issued 10/2/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-10, -10-10F; T.C. A22WE	SA2924WE	Installation of wheeled refrigerated module, P/N 73011000. Issued 8/27/74.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-10F; T.C. A22WE	SA2948WE	Installation of buffet/bar and bustle assembly. Issued 1/22/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA2985WE	Modification of installed G1 and G1A galleys (Dale P/Ns CAG-11000, CF-10-1, CAG-10000, CF-7000). Issued 1/22/75.	WE	25970	Continental Airlines 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2987WE	Installation of cabin lounge swivel seats and adjustable table with removable top. Issued 1/23/75.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3014WE	Installation of floor game table assembly. Amended 1/20/76.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91100
DC-10-10, -10-10F; T.C. A22WE	SA3212WE	Installation of forward cargo compartment positive vent sump drain. Issued 6/15/76.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3367WE	Installation of nine-abreast coach seating and associated oxygen and electrical system modification. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3368WE	Installation of eight-abreast coach seating in forward cabin behind the first class section, and associated oxygen and electrical system modifications. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3827WE	Installation of folding leaf table. Issued 1/31/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA3843WE	Installation of Nordskog Ind. galley 1-419. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3844WE	Installation of composites, unlimited coat closet, P/N 225-46103. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC10-10, -10-10F; T.C. A22WE	SA3845WE	Installation of buffet/bar unit, P/N 2142396. Amended 7/11/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
DC-10-10, -10-10F; T.C. A22WE	SA3847WE	Installation of a new lounge and first class accommodations. Amended 7/12/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3848WE	Installation of HITCO refrigerated galley module. Amended 3/16/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-10-10, -10-10F; T.C. A22WE	SA3875WE	Installation of Continental Air Lines flight attendant seat, P/N 225-46317. Issued 3/16/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3937WE	Installation of HITCO storage galley module. Issued 5/18/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-10-10, -10-10F; T.C. A22WE	SA3996WE	Installation of Litton LTN-2110NS. Issued 7/18/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA4058WE	Installation of folding leaf table. Issued 11/8/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
DC-10-10, -10-10F; T.C. A22WE	SA4122WE	Installation of aluminum cabin window assembly to replace outer acrylic cabin window pane. Issued 3/24/80.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3432WE	Installation of fire/overheat detection system. Amended 2/14/78.	WE	77300	Systron Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3626WE	Revision of DC-10 fire overheat detection system to allow intermixing of Systron-Donner fire detectors with Edison detectors in the fan, core, and pylon sections of the CF6 engines. Issued 4/11/78.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10F, -10-30, -10-30F, -10-40; T.C. A22WE	SA4138WE	Installation of cabin window plug assembly.	WE	32760	Edwards Enterprises 230 Constitution Drive Menlo Park, CA 94025
DC-10-10, -10-10CF; T.C. A22WE	SA3407WE	Installation of Lermer Apparatebau GMBH beverage cart No. L15701. Issued 5/20/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 91406
DC-10-10, -10-30; T.C. A22WE	SA776SO	Installation of SICMA food tray stowage carts. Amended 3/14/80.	SO	71600	SICMA Aero Seats, Inc. 6929 N.W. 46th Street Miami, FL 33166
DC-10-10, -10-30; T.C. A22WE	ST734SO	Installation of NAL Val-Pack coatroom, P/N 10621-1. Amended 3/30/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-10-10, -10-30; T.C. A22WE	SA2853WE	Retractable tiedown assemblies. Amended 3/23/78.	WE	48550	H. Koch & Sons Koch Road Corte Madera, CA 94925
DC-10-10, -10-30; T.C. A22WE	SA3067WE	Installation of lower lobe food service modules, P/Ns 818720, 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
DC-10-10, -10-30; -10-30F; T.C. A22WE	SA2395WE	Installation of coffee bar cart, P/N 801000. Amended 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2774WE	Installation of wing tip mounted emblem lights. Reissued 11/8/74.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2893WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1704-C West 134th Street Gardena, CA 90249
DC-10-10, -10-30, -10-40; T.C. A22WE	SA930EA	Installation of Inflight Motion Pictures, Inc. projection unit assembly DC-10 16mm Tri-Jet system 10300 or light weight Tri-Jet projection system, DC-10 P/N 10307. Amended 9/14/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA947EA	Installation of Inflight Motion Pictures, Inc. screen assemblies. Amended 8/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, New York 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA969EA	Installation of Inflight movie projection assembly P/N 10270, Super 8mm IMPAX system. Issued 11/21/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA990EA	Installation of 16mm projection unit assembly and center stowage bins, P/N 10310. Issued 10/3/74.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA3335WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
DC-10-10, -10-30F; T.C. A22WE	SA2817WE-D	Installation of provisions for ground proximity warning system. Amended 6/26/75.	WE	80500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-10-10, -10-30F; T.C. A22WE	SA2830WE-D	Installation of Collins FPC-75 ground proximity warning system computer. Amended 3/30/76.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10F; T.C. A22WE	SA4006WE	Installation of a 3-place courier seat. Issued 7/31/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-30; T.C. A22WE	SA2663WE	Installation of Trans Com movie and projector entertainment system, Model 2420. Issued 3/19/73.	WE	76800	Trans Com A Division of Sundstrand Data Control, Inc. 3100 Pullman Avenue Costa Mesa, CA 92626
DC-10-30; T.C. A22WE	SA2684WE	Installation of Tridair Industries main deck baggage container system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-10-30; T.C. A22WE	SA2707WE	Installation of cabin lounge seats, folding tables, cart stowage unit, and class divider partition. Issued 6/6/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Airport Mail Facility Miami, FL 33159
DC-10-30; T.C. A22WE	SA3194WE	Installation of Airborne video-cassette system. Issued 5/12/76.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA3344WE	Installation of dual Litton LTN-72R INS/RNAV navigation systems. Issued 2/23/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-30; T.C. A22WE	SA3393WE	Installation of Airborne Video-cassette system.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA3569WE	Installation of aircraft video system. Amended 6/5/79.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10; T.C. A22WE	SA4010WE	Installation of video projection system. Issued 10/5/79.	WE	15375	Bell and Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30, -10-30F; T.C. A22WE	SA2775WE	Installation of Fairchild Stratos tray carrier rack assembly. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2777WE	Installation of service center (G 1) and coffee bar G-2 assemblies. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2780WE	Installation of serving cart pallets, P/N 989200 and 990100. Issued 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-30F; T.C. A22WE	SA2938WE	Carts and pallet assembly installation. Issued 10/9/74.	WE	28560	Dale Engineering & Development, Inc. 12243 Branford Street Sun Valley, CA 91352
DC-10-30F; T.C. A22WE	SA2949WE	Installation of passenger entertainment/service system. Amended 12/6/74.	WE	33223	Electronic Engineering Company of California 1441 East Chestnut Avenue Santa Ana, CA 92701
DC-10-30F; T.C. A22WE	SA2950WE	Installation of ballast assembly. Issued 11/18/74.	WE	79200	Trans International Airlines Oakland International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA3128WE	Installation of 376 passenger interior arrangement and associated oxygen system modifications. Issued 12/15/75.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA3137WE	Installation of courier seat module assembly. Issued 1/21/76.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-40; T.C. A22WE	SA88GL	Installation of Bendix GPW-83 ground proximity warning systems. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40; T.C. A22WE	SA372GL	Installation of Honeywell P/N HG280BD80 digital airdata computer in the number three position per NWA project 1-34-40300 in place of the Honeywell P/N HG280D5 presently used in this position for data collection purposes only. Issued 10/26/79.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40; T.C. A22WE	SA2782WE	Installation of wheeled refrigerated module P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-40, -10-40F; T.C. A22WE	SA3139WE	Installation of wing and tail engine pods. Amended 3/15/79.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
MESSERSCHMITT - BOLKOW - BLOHM - GMBH

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BO-105A, BO-105C; T.C. H3EU	SA26RM	Installation of JB Systems air-conditioning system. Issued 6/14/74.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
BO-105A, BO-105C; T.C. H3EU	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
BO-105A, BO-105C; T.C. H3EU	SH978EA	Installation of Consolidated Instrument Co., Inc. battery temperature alert system, Models B206-TA180 or B206D-TA180. Issued 4/4/74.	EA	25920	Consolidated Instrument Company Teterboro Airport Teterboro, NJ 07608
BO-105A, BO-105C, BO-105S; T.C. H3EU	SH1065EA	Installation of DeVore tail floodlight on upper surfaces of horizontal stabilizer. Reissued and amended 3/17/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
BO-105C; T.C. H3EU	SH218NW	Installation and maintenance of Allison 250-C20 engine equipment with Bendix fuel control system. Issued 9/10/75.	NW	98124	The Boeing Company P.O. Box 3707 Seattle, WA 98124
BO-105C; T.C. H3EU	SH239WE	Installation of Chandler Evans (CECO) Model 104900-A3-A2 fuel controllers and Model 104500-A governors. Issued 6/11/79.	WE	08353	Air Services International 7300 East Evans Drive Scottsdale, AZ 85026
BO-105C; T.C. H3EU	SH971EA	Installation of cabin door post and door latching mechanism Model Kit No. SK212-10415. Amended 6/10/74.	EA	16880	Boeing Vertol Company Division of Boeing Company P.O. Box 16858 Philadelphia, PA 19142
BO-105C; T.C. H3EU	SH1025EA	Installation of ten inch cabin extension, modification of cabin doors, relocation of battery and structural modification of tail-boom to fuselage splice. Amended 1/9/78.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1031EA	Installation of AiResearch Manufacturing Co. environmental control unit, P/N 2200850-1 (Carson P/N C-105-20-5000-29). Reissued 5/21/80.	EA	56833	MBB Helicopter Corporation Weston Way - P.O. Box 514 West Chester, PA 19380
BO-105C; T.C. H3EU	SH1041EA	Relocation of battery to a position just aft of No. 2 engine. Issued 10/12/76.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1069EA	Installation of cabin door post and door latch assembly in accordance with data. Issued 2/23/78.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1073EA	Installation of electric chip directors in main transmission and intermediate and tail rotor gear boxes. Issued 5/19/78.	EA	47790	Keystone Helicopter Corporation 1420 Phoenixville Pike West Chester, PA 19380
BO-105C, BO-105S; T.C. H3EU	SH1182EA	Installation of emergency float kit, F105-85185. Amended 5/6/80.	EA	56832	MBB Helicopter Corporation Weston Way - P.O. Box 514 West Chester, PA 19380
BO-209-150 FV and RV, BO-209-150FF; T.C. A27EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Piccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BO-209-150 FV and RV, BO-209-150FF; T.C. A27EU	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20 Series; T.C. 2A3	SA1786WE	Installation of Brittain Industries B-6 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1787WE	Installation of Brittain NAV-2B flight control. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20, M22 Series; T.C. 2A3, A6SW	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
Mark 20, 20A; T.C. 2A3	SA2666WE	Ceconite 102 material covering of rudder, elevators, ailerons and flaps. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M20, M20A; T.C. 2A3	SA2823SW	Reinforcement of vertical tail spar. Issued 7/31/78.	SW	64407	Harry L. Phillips Route 3, Box 420F Fort Worth, TX 76067
M20, M20A, M20B; T.C. 2A3	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amneded 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
M20 thru M20F; T.C. 2A3	SA600EA	Installation of electronic voltage alarm.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
M20, M20A thru M20E; T.C. 2A3	SA630WE	Installation of oil filter assemblies. Reissued 6/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
M20, M20A thru M20E; T.C. 2A3	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs: SA705SW, SA732SW.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M20, -A, -B, -C, -D, -E, -F, -G; T.C. 2A3	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 South Curtice Street Littleton, CO 80120
M20, M20A, M20B, M20C, -D, -E, -F; T.C. 2A3	SA1462WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	80120	Hanna-Aero Corporation 5222 South HOlly Street Littleton, CO 80120
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1932SW	Chrome plated disc brakes. Issued 11/27/74.	SW	29580	W.A. DeMaine Route 3, Box 62 Pine Bluff, AR 71601

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA3275WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell Mfrg. BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
M20A, M20B, M20C, M20D, M20G; T.C. 2A3	SA1156WE	Installation of Rajay turbosuper-charged Lycoming O-360-A1A or -A1D engine. Amended 8/2/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA738EA	Installation of Whelen Engineering Co., Inc. Model HD-14 anti-collision strobe light system.	NE	85500	Whelen Engineering Co., Inc. 3 Winter Avenue Deep River, CT 06417
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light systems. Amended 10/4/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
M20B, C, D, E, F, G; T.C. 2A3	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
M20B, M20C, M20D, M20E, M20F, M20G, Normal Category; T.C. 2A3	SA3938WE	INstallation of flap gap seal. Issued 5/21/79.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA4023WE	Installation of flap gap fairings, flap hinge fairings, fuselage fairing at the tail cone, and a plexiglass landing light fairing. Amended 1/17/80.	WE	65015	John A. Porter 29 Walnut Via 501 E. Orangethorpe Avenue Anaheim, CA 92801
M20C, M20D; T.C. 2A3	SA77CE	Installation of McCauley 2D34C53/74E-0 or B2D34C53/74E-0 propeller with D-2809 spinner. Amended 5/24/68.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
M20C, M20D; T.C. 2A3	SA3859WE	Installation of an air/oil separator. Issued 3/12/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
Mooney M20C, M20D, M20E; T.C. 2A3	SA138WE	Installation of Grimes Model D-7080. Rotating beacon on vertical fin. Reissued 3/8/76.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
M20C, M20D, M20G; T.C. 2A3	SA375GL	Installation of Lycoming O-360-A1F6 or O-360-A1F6D in lieu of Lycoming O-360-A1D. Amended 4/18/80.	GL	90152	Louis M. Zeller, Jr. Route 1, Box 298-B Mount Vernon, IN 47620
M20C, M20D, M20G; T.C. 2A3	SA386GL	Installation of McCauley Propellers B2D34C212/78CDA-4, B2D34C212/78CDA-4E, B2D34C214/90DHB-16, B2D34C214/90DHB-16E, using original hardware and components. No installation data are required. Reissued 4/22/80.	GL	90152	Louis M. Zeller, Jr. Route 1, Box 298-B Mount Vernon, IN 47620
M20C (S/N 20-0011 and on - 1974), (S/N 20-1147 and on - 1975), M20E (S/N 21-0025 and on - 1974), (S/N 21-1161 and on - 1975); T.C. 2A3	SA2993WE	Installation of Pathfinder autopilot systems and/or electric pitch trim systems. Issued 2/21/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C (S/N 20-0011 and on), M20E (S/N 21-0025 and on); T.C. 2A3	SA3222WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 11/15/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, E, F; T.C. 2A3	SA1938SW	Brittain LSA-6 lateral stability augmentation system (positive control). Issued 1/7/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20C, E, F, G; T.C. 2A3	SA2207SW	NAV-FLITE II and B-5 flight control systems. Issued 7/23/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20C, E, F, G; T.C. 2A3	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20C, E, F, G; T.C. 2A3	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, M20E, M20F; T.C. 2A3	SA2654WE	Installation of Pathfinder P2A autopilot system. Amended 4/14/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20E/Super 21; T.C. 2A3	SA999CE	Installation of ERC battery monitor. Issued March 1974.	CE	33229	Electronic Research Company P.O. Box 913 Shawnee Mission, KS 66201
M20E, M20F; T.C. 2A3	SA250GL	Installation of Lycoming IO-360-A1B6 engine in lieu of Lycoming IO-360- A1A engine using original installation hardware and components. No installation data are required. Issued 6/30/78.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA320GL	Installation of Hartzell Model HC-C2YK-1( )F/F7666A-4Q propeller in lieu of Hartzell Model HC-C2YK-1/7666-2 propeller using original installation hardware and components on aircraft previously modified in accordance with STC No. SA250GL. No installation data are required. Issued 6/28/79.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA1411WE	Installation of Rajay turbocharged Lycoming IO-360-A1A engine. Amended 5/9/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20E, M20F, M20J; T.C. 2A3	SA2968WE	Installation of manifold pressure gage/fuel flow meter (fuel pressure gage) in lieu of original gage/ meter. Amended 11/20/79.	WE	65015	John A. Porter 29 Walnut Via 501 East Orangethorpe Avenue Anaheim, CA 92801
M20E, M20F, M20J; T.C. 2A3	SA3728WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
M20E, M20F, M20J; T.C. 2A3	SA4065WE	Installation of Silver Instruments fueltron 1G or IP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20F, S/N 22-1179 and up; M20J, S/N 24-0001 and up; T.C. 2A3	SA1212CE	Installation of King KFC 200 2 axis (3 optional) flight control system with KCS 55/55A compass and King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or third axis (yaw damper) only, or manual electric trim only. Amended 9/8/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20F, S/N 22-0013 and on (1974 models), S/N 22-1179 and on (1975 models); T.C. 2A3	SA2986WE	Installation of Pathfinder autopilot systems. Issued 2/19/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20F; T.C. 2A3	SA3047SW-D	Automatic flight system AK523 consisting of Century III autopilot with command automatic electronic pitch trim system and optional radio and glide slope couplers. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3048SW-D	Automatic flight system AK476 consisting of Century IIB autopilot with optional radio coupler. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3049SW-D	Automatic flight system AK475 consisting of Century I autopilot with optional omni tracker. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport MIneral Wells, TX 76067
M20F; T.C. 2A3	SA3064SW-D	MItchell command electric trim AK541. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3186WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20F; T.C. 2A3	SA4087WE	Installation of Hartzell HC-C2YK-1B/ 7666A-4Q constant speed propeller. No installation data required. Issued 1/9/80.	WE	52025	Paul E. Loewen P.O. Box 545 Lakeport, CA 95453
M20J; T.C. 2A3	SA1300CE	Installation of Edo-Aire propeller governor Model 34-826-014-11. Amended 1/9/78.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
M20J; T.C. 2A3	SA3307SW-D	Installation of Mitchell automatic flight system AK801 consisting of Century 41 autopilot or Model AK801FD consisting of Century 41 flight director autopilot. Issued 10/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3308SW-D	Installation of Mitchell automatic flight system AK802 consisting of Century 21 autopilot. Issued 10/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3555WE	Installation of Rajay turbocharged Lycoming IO-360-A3B6D and/or IO-360-A1D6D engines. Issued 12/30/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90801
M20J, M20K; T.C. 2A3	SA300CE	Installation of propeller governors on single and twin engine aircraft, P/N M20J E210490, M20K E210760. Issued 2/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
M20J (24-0939 and up), M20K; T.C. 2A3	SA1464CE	Installation of KFC 200 two axis (three optional) flight control system. Amended 3/3/80.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M20J, M20K; T.C. 2A3	SA1525CE-D	Installation of King KNS 81 digital area navigation system. Issued 1/23/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20K; T.C. 2A3	SA378GL	Installation of Silver Instruments fueltron IG digital fuel flow meter. Reissued 1/3/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20K; T.C. 2A3	SA3325SW-D	Mitchell automatic flight system AK807 consisting of Century 41 autopilot flight director autopilot. Issued 1/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT

MOONEY MITE AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 803	SA1-353	Delco Remy generator 1101899 and associated plastic cowling.	EA	76100	George W. Strattner 6217 Hedgerow Drive Norfolk, VA 23501
18 Series; T.C. 803	SA3-483	Continental C85-12 engine. Revised April 1973.	CE	16786	W.P. Bilquist Rural Route #2, Box 113 Blue Springs, MO 64015
18 Series; T.C. 803	SA4-1106	Ceconite 101 covering of wings, ailerons, rudder, elevators, horizontal and vertical stabilizers.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
18 Series; T.C. 803	SA1044WE	Continental A75-8 65 hp engine and McCauley 1B90-CM/6753 propeller.	WE	03016	Aero-Spec. 240 North Dale Fullerton, CA 92631
18 Series; T.C. 803	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
18 Series; T.C. 803	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
18 Series; T.C. 803	SA1-615	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
18 Series; T.C. 803	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
18 Series; T.C. 803	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
18 Series; T.C. 803	SA1008WE	Poly-fiber covering of wings, fuselage, elevators, ailerons, stabilizers, and rudder. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
M-18C; T.C. A-803	SA71GL	Installation of P/N BA5110 filter assembly. Issued 12/29/77.	CE	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M-18C, -18C-55, -18L, -18LA;	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M-18C, M-18C55, M-18L, M-18LA; T.C. 803	SA2666WE	Ceconite 102 material covering of wings, ailerons, rudder, elevators, horizontal and vertical stabilizers. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
Navion A, B, D, E, F, G, H; T.C. A-782	SA3786WE	Installation of tubular engine mount, cowling cooling baffles, air induction system and cowl flap mechanism. Issued 12/4/78.	WE	37081	GAMA Enterprises P.O. Box 55 Fawnskin, CA 92333
Navion, Navion A thru F;	SA3821WE	Installation of single piece windshield, canopy side and rear windows. Issued 2/29/80.	WE	50259	Leedy Aviation P.O. Box 816 Banning, CA 92228
Navion A, B, C, D, E, F, G, H; T.C. A-782	SA3936WE	Installation of an air/oil separator. Issued 6/1/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
Navion B; T.C. A-782	SA4-1121	Increase in allowable gross weight from 2850 to 3100 pounds per STC SA4-915 when equipped with 20 gallon wing-tip tanks (Brittain Aircraft P/N 1000). Reissued 2/2/71.	WE	62000	H. S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
Navion B; T.C. A-782	SA308EA	Istallation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Navion B; T.C. A-782	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Navion E; T.C. A-782	SA3447WE	Installation of steel engine mounting brackets. Issued 7/1/77.	WE	50250	Eugene Leedy P.O. Box 816 Banning, CA 92220
Navion G, H; T.C. A-782	SA2654WE	Installation of Pathfinder Model P2A autopilot. Amended 5/31/74.	WE	12380	Astronautics Crp. of America 2416 Amsler Road Torrance, CA 90505
Navion G, H; T.C. A-782	SA2961WE	Installation of Pathfinder autopilot systems and/or electric pitch trim systems. Issued 2/24/75.	WE	12380	Astronautics Corp. of America 2416 Asler Road Torrance, CA 90505
Navion G, H; T.C. A782	SA3224SW-D	Mitchell automatic flight system AK701 consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion G, H; T.C. A782	SA3225SW-D	Mitchell automatic flight system AK704 consisting of Century IIB autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion H; T.C. A-782	SA1190CE	Installation of King KFC 200 flight control system (2 axis). Issued April 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NIHON AEROPLANE MANUFACTURING COMPANY, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
YS-11, -11A: T.C. A1PC	ST424SO	Installation of replacement radome assembly.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11, -11A; T.C. A1PC	SA863EA	Incorporation of Chromalloy Electronics Division ESL-1 or ESL-6 emergency slide lighting system. Reissued 3/6/73.	SO	22225	Chromalloy Electronics Div. of Chromalloy American Corp. 3901 North 29th Avenue Hollywood, FL 33020
YS-11, -11A; T.C. A1PC	SA2728WE	Incorporation of Holcombe Industries Hi-Lite system (P/N 50-1001) for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
YS-11A Series; T.C. A1PC	SA393SO	Install Goodyear 9540512 wheels in place of Goodyear 9543138 wheels.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11-A200; T.C. A1PC	SA1949WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach,CA 90807
YS-11A-200, -300, -500, -600; T.C. A1PC	ST487SO	Installation of P.P.G. manufactured main windshields, P/Ns 5613-00001 (L/H) and 5613-00002 (R/H) and Barber Colman P/N HYLZ 8882 temperture controller. Amended 2/22/74.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500; T.C. A1PC	ST486SO	Installation of external APU control panel. Amended 2/16/72.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500; T.C. A1PC	ST866SO	Installation of Bendix ground proximity warning system. Amended 11/20/75.	SO	64500	Piedmont Aviaton, Inc. P.O. Box 2720 Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A, -500; T.C. A1PC	SA2910SW	Unpressurized cargo door in rear left hand portion of fuselage. Amended 5/9/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A Series 500; T.C. A1PC	SA3873WE	Installation of bleed air heating system. Amended 8/17/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A-500; T.C. A1PC	SA4094SW	Aft cargo door between F.S. 636.2 and 758.9 between floorline and stringer 27 and associated structural changes. Issued 3/3/80.	SW	07740	Air Freighters Int'l, Inc. P.O. Box 2 Addison, TX 75001
YS-11A-600; T.C. A1PC	SA3047WE	Installation of provisions only for ground proximity warning system. Issued 5/28/75.	WE	87450	World Airways, Inc. Maintenance & Engineering Center Oakland International Airport Oakland, CA 94614
YS-11A-626; T.C. A1PC	SA78NW	Cabin modiication. Issued October 1973.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J3L, -S, -65, -65S; PA-12, -12S; PA-14; PA-15; PA-17; J4, J4A, -6; J4B; J5A, -80, J5B, J5C, AE-1, HE-1; PA-11, -11S, J3C-40, -50, -50S, -65, -65S; J3F-50, -50S, -60, -60S, -65, -65S; PA-16, -16S; PA-18, -18A, -18S, -18-105 and -18S-105 (Special), -18-125, 18AS-125, -18S-125, -18-135, -18A-135, 18AS-135, -18-150, -18AS-150, -18S-150, PA-19, -19S; Restricted Category: PA-18A, -18A-135, -18A-150; AR-7, PA-20, -20S, -20-115, -20S-115, -20-135, -20S-135; PA-22, -22-108-135, -150, -160, -22S-135, 22S-150, 22S-160; PA-25, -25-235; T.C. 698, 780, 797, 800, 805, 703, 721, 725, 691, 692, 1A1, 1A2, AR-7, 1A4, 1A6, 2A8, 2A10	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J4, J5, AH-1, HE-1, PA-11, -12, -14, -16, -18, -20, -22 Series; T.C. 691, 740, 725, 780, 797, 1A1, 1A2, 1A4, 1A6	SA1-510	Sur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
J4 Series; T.C. 703	SA4-1130	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
J4 Series; T.C. 703	SA4-1401	McCauley 1A90-CF propeller.	WE	78492	Arthur R. Tillesen 8101 Larsen Street Garden Grove, CA 92600
J4 Series; T.C. 703	SA297WE	McCauley 1A90-CF propeller on Continental C-85-12 engine.	WE	01350	Dwight R. Addigton 409 Serenade Way San Jose, CA 95125
J5 Series; T.C. 725	SA11SW	Removal of outer wing tip bow.	SW	42127	Herring Aircraft Service P.O. Box 1082 Cedar Hill, TX 75104
J5 Series; T.C. 725	SA176CE	Removal of door and installation of placard.	CE	82380	Russell Van Dyke Marceline, MO 64658
J5 Series; T.C. 725	SA320CE	Lycoming O-290-D2 engine and Sensenich M76A-M2/7452 propeller.	CE	05967	Aircraft Service Company 7134 Booth Drive Prairie Village, KS
J5, AE-1, HE-1 Series; T.C. 725	SA4-1080	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
J5A; T.C. A-725	SA305AL	Installation of 13-gallon auxiliary fuel tank. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J5A; T.C. A-725	SA495AL	Installation of Lycoming O-290-D and -D2 engine using Stoddard Model 501 engine mount. Amended 6/27/75.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J5A; T.C. A-725	SA819CE	Install Aero Model M1500, M1800 or M2000 main skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
J5A, J5C; T.C. 725	SA396AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
J5A, J5A-80, J5B, J5C; T.C. A-725	SA1144SO	Removal of cabin entrance door and installation of placards. Issued 5/80.	SO	17012	Thomas A. Boswell P.O. Box 176 Elmore, AL 36025

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
J5A (Army L-4F), J5A-80, J5B (Army L-4G), J5C, AE-1, HE-1; T.C. A-725	SA3285WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
J-5C; T.C. A-725	SA354AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-11; T.C. 691	SA3-47	Extra 17-gallon right wing fuel tank.	CE	17305	Bristow Aircraft Company Bristow, IA 50611
PA-11; T.C. 691	SA4-479	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-11; T.C. 691	SA35AL	Installation of PA-18 flaps. Amended 3/7/67.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-11; T.C. 691	SA323CE	Manufacture hitch and bracket. Install tow hitch. Amneded 5/6/71.	CE	76500	Stubben-McCandless South Omaha Airport, Route 1 Pipillion, NE 68046
PA-11, -11S; T.C. 691	SA501AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-11, -11S; T.C. 691	SA501AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-11, -12, -14, -15, -16, -17, -18, -19, -20, -22, -25; T.C. 691, 780, 797, 800, 1A6, 1A1, 805, 1A2, 1A4, 2A8	SA4-977	Fiberglass rudder post mount for either Grimes or Whelen WRM rotating beacons.	NW	65751	Art Whitaker Pearson Airpark Vancouver, WA 98660
PA-11, -12, -14, -16, -20, -22; T.C. 691, 780, 797, 1A1, 1A4, 1A6	SA573SW	Booster wing tip kit 101-101-250.	SW	81250	Upper Valley Aviation, Inc. P.O. Box 541 McAllen, TX 78501
PA-11; PA-12; PA-14; PA-15; PA-16; PA-17; PA-18, PA-19; PA-20; PA-22, PA-25; PA-23, 23-160, 23-235, 23-250, E23-250; PA-24, -24-250, -24-260, -24-400; PA-28-140, 28-150, -28-160, -28-S-180, -28R-180, -28-180, -28-235, -28-S-160, -28R-200; PA-30, PA-39; PA-31, -31-300, -30P; PA-32-260, -300, -32S-300; T.C. A-691, A-780, A-797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 2A8, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA615EA	Installation of Whelen anti-collision strobe light system. Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
PA-11; PA-12; PA-14; PA-15; PA-16; PA-17; PA-18, PA-19; PA-20; PA-22; PA-25; PA-23, -23-160, -23-235, -23-250, -E23-250; PA-24, -24-250, -24-260, -24-400; PA-28-140, -28-150, -28-160, -28-S-180, -28R-180, -28-180, -28-235, -28-S-160, -28R-200; PA-30, PA-39; PA-31, -31-300, -31P; PA-32-260, -32-300, -32S-300; T.C. A-691, A-780, A-797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 2A8, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-11, -12, -14, -16, -18, -20, -22, -25; T.C. A-691, A-780, A-797, 1A1, 1A2, 1A4, 1A6, 2A8, 2A10	SA2127WE	Installation of Madras Air Service Model 104 wing tips. Amended 3/22/74.	NW	54000	Madras Air Service Route 2, Box 1225 Madra, OR 97741
PA-12 Series; T.C. 780	SA1-297	Lycoming O-290-D2 or O-290-D2A engine and Sensenich M76AM-2 fixed pitch metal propeller, diameter 74", pitch 50". Reissued and amended 10/17/77.	NE	20560	Central Maine Flying Service, Inc. DeWitt Field P.O. Box 558 Old Town, ME 04468
PA-12 Series; T.C. 780	SA1-373	Lycoming O-290-D or O-290-D2 engine, Sensenish propeller, PA-18 engine baffles and Harrison oil cooler.	EA	77082	Susquehanna Aero Marine R. 513 Washington Boulevard Williamsport, PA 17701
PA-12 Series; T.C. 780	SA1-522	2024T3 alclad.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-12 Series; T.C. 780	SA4-419	Application of glass cloth over unbleached muslin to all but control surfaces.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
PA-12 Series; T.C. 780	SA4-456	Lycoming O-320 engine and accessories.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
PA-12 Series; T.C. 780	SA4-519	Installation of Lycoming O-320 engine. Reissued 1/12/78.	NW	53250	McKenzie Flying Service 90600 Greenhill Road Eugene, OR 97402
PA-12 Series; T.C. 780	SA4-937	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-12 Series; T.C. 780	SA10EA	Metal covering of fabric wings and optional metallizing of ailerons.	EA	72100	Skycraft Design, Inc. P.O. Box 67 West Trenton, NJ 08628
PA-12 Series; T.C. 780	SA120AL	Installation of auxiliary fuel tank. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12 Series; T.C. 780	SA161WE	Door on left side of airplane.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
PA-12 Series; T.C. 780	SA217WE	Conversion of airplane for parachute jumping and aerial photography operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
PA-12 Series; T.C. 780	SA231AL	Installation of Piper PA-14 wing flaps. Amended 1/15/76.	CE	70308	Rodney E. Schaeffer 1253 Cramer Street Wichita, KS 67212
PA-12 Series; T.C. 780	SA270SO	Water and ice detector in fuel gascolator and carburetor.	SO	71545	Charles B. Shivers, Jr. 8929 Valleybrook Road Birmingham, AL 35206
PA-12 Series; T.C. 780	SA272AL	Installation of a removable structural assembly to replace like structure removed from behind rear seat.	AL	37887	Gil's Aircraft Service P.O. Box 3-4058 Anchorage, AK 99501
PA-12 Series; T.C. 780	SA355AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-12 Series; T.C. 780	SA397AL	Conversion of 4" wheels and brakes to 6" wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99502
PA-12 Series; T.C. 780	SA491AL	Replacement of hammock type seat back rest with removable horizontal tube. Amended 12/6/72.	AL	68250	Kenneth S. Rivard 949 West 72nd Avenue Anchorage, AK 99502
PA-12 Series; T.C. 780	SA493AL	Install leading edge cuff. Amended 3/4/77.	AL	20512	Clinton C. Center 8134 Lake Otis Parkway Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-12 Series; T.C. 780	SA543AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12 Series; T.C. 780	SA543AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series; T.C. 780	SA550EA	Installation of Lycoming O-360-D2A engine (168 hp.) and McCauley propeller 1A170-SFA7850.	NE	17071	Lawrence H. Bradway North Windham, ME 04062
PA-12 Series; T.C. 780	SA550AL	Installation of modified landing gear (PA-18 type) with main gear legs lengthened 6 inches. Issued 4/30/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. Box 1729C, SRA Anchorage, AK 99507
PA-12 Series; T.C. 780	SA553AL	Installation of O-360 Lycoming engine. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12 Series; T.C. 780	SA555AL	Installation of welded steel rear float fittings. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12 Series; T.C. 780	SA563AL	Installation of Day & Night 2-4 fiberglass and aluminum engine cowling. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12 Series; T.C. 780	SA563AL	Installation of Day & Night 2-4 fiberglass and aluminum engine cowling. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series (Landplanes Only); T.C. 780	SA564AL	Modification of PA-12 elevator control system forward of fuselage station 181. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-12 Series (Landplanes Only); T.C. 780	SA564AL	Modification of PA-12 elevator control system forward of fuselage station 181. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series (Landplanes Only); T.C. 780	SA565AL	Installation of aft baggage compartment in PA-12 airplanes. Reissued 5/7/79.	CE	42051	Daivd M. Hendrick Star Route, Box 207B Buffalo, mO 64622 AND
PA-12 Series (Landplanes Only); T.C. 780	SA565AL	Installation of aft baggage compartment in PA-12 airplanes. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series (Normal Category Only); T.C. 780	SA568AL	Installation of a winterization kit. Amended 12/2/75.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12 Series (Normal Category Only); T.C. 780	SA570AL	Installation of square horizontal stabilizer, elevator and rudder. Issued 1/16/76.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12 Series; T.C. 780	SA577AL	Modification of standard pilot seat. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12 Series; T.C. 780	SA577AL	Modification of standard pilot seat. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12 Series; T.C. 780	SA578AL	Install PA-18 wing flaps on PA-12. Issued 3/26/76.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12; T.C. A780	SA644AL	Install Avco Lycoming o-320-D2A or O-320-B2B engine and McCauley 1A175/GM8246 prop. Issued 7/31/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12; T.C. A780	SA646AL	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12; T.C. 780	SA656AL	Install Avco Lycoming O-320-A2B or O-320-E2D engine and McCauley 1A175/GM 8246 propeller. Issued 11/27/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-12; T.C. 780	SA660AL	Installation of extended flaps, flap control system and modified ailerons. Issued 1/9/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
PA-12; T.C. 780	SA660AL	Installation of extended flaps, flap control system and modified ailerons. Issued 1/9/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99501
PA-12 Series; T.C. 780	SA815CE	Installation of skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
PA-12 Series; T.C. 780	SA2038WE	Installation of Lycoming O-320 engine, McCauley 1A170/1C172 and Sensenich M74DM propellers and associated alternator systems. Amended 3/7/74.	NW	61526	Harold G. Nelson 3005 Southwest Marshall Street Pendleton, OR 97801
PA-12 Series; T.C. 780	SA3283WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-12, PA-12S; T.C. 780	SA202EA	Installation of either a Lycoming engine O-290-D (125 HP) or O-290-D2 (135 HP) with Sensenich propeller M74RM. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181, 1216 North Road Lyons, WI 53148
PA-12, -12S; T.C. A-780	SA444AL	Installation of McCauley 1A175/GM propeller. Issued 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-12, -12S; T.C. A-780	SA476AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
PA-12, -12S; T.C. A-780	SA476AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA494AL	Installation of electric fuel gauges. Issued 5/1/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -12S; T.C. A-780	SA517AL	Installation of plexiglass skylight on top of cabin. Issued 5/17/74.	AL	27250	Crosswinds, Inc. 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, PA-12S; T.C. 780	SA537AL	Installation of Day & Night 4-1 fiberglass propeller spinner.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
PA-12, PA-12S; T.C. 780	SA537AL	Installation of Day & Night 4-1 fiberglass propeller spinner.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA566AL	Installation of Lycoming O-320 engine. Amended 11/25/75.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12, -12S; T.C. 780	SA629AL	Install fiberglass wing tip assembly.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA653AL	Install Avco Lycoming O-320-A2B or O-320-C2B engine and Sensenich 74M6-0-52 propeller. Issued 9/8/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12, -14 Series; T.C. 780, 797	SA5-48	Structure approval only of engine mount assembly on aircraft for use with engines of not more than 363 pounds total installed weight and 170 hp (4 cylinder).	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA5-66	Structural approval only of Fred A. Shaw engine mount and forward fuselage modification for installation of 150 hp engine. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
PA-12, -14 Series; T.C. 780, 797	SA5-66	Structural approval only of Fred A. Shaw engine mount and forward fuselage modification for installation of 150 hp engine. Reissued 5/7/79.	AL	42051	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-12, -14 Series; T.C. 780, 797	SA83AL	Lycoming O-320 Series (150 hp models only) engines and Sensenich M74DM propeller, using Stoddard engine mount 501. Amended 6/12/69.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA148AL	PA-18 main landing gear and installation of EDO 2000 floats. Amended 3/3/69.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA148AL	PA-18 main landing gear and installation of EDO 2000 floats. Amended 3/3/69.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA149AL	Installation of auxiliary baggage compartment.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-12, -14 Series; T.C. 780, 797	SA189AL	Install left side cabin door.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA189AL	Install left side cabin door.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA190AL	Increased gross weight to 1935 pounds.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA190AL	Increased gross weight to 1935 pounds.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA213SO	Electric fuel quantity indicator. indicator.	SO	54615	Obed L. Malpass 1502 Morris Road Wilmington, NC 28401
PA-12, -14 Series; T.C. 780, 797	SA289AL	Install rudder centering device.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th PPlace Anchorage, AK 99503
PA-12, -14 Series; T.C. 780, 797	SA2313SW	Install 22-1/2 gallon fuel tank. Issued 5/20/77.	SW	75498	W.L. Stoddard Stoddard Aero Service c/o Plane Booster, Inc. Box 541 McAllen, TX 78501
PA-12, -14, -16, -18, -10; T.C. 780, 797, 1A1, 1A2, 1A4	SA147AL	Electric fuel quantity gauge system.	AL	42158	C.D. Hogan 1831 Lake Otis Parkway Anchorage, AK 99501
PA-12, PA-14, PA-16, PA-18, PA-20, PA-22; T.C. 780, 797, 1A1, 1A2, 1A4, 1A6, AR-7	SA22RM	Manufacture of exact replacement parts, front and rear lift strut assembly. Amended 3/13/79.	RM	50500	Light Plane Components, Inc. 509 Buckley Road Aurora, CO 80011
PA-12, -14, -18; T.C. 780, 797, 1A2	SA215AL	Install L-2500A wheel replacement skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99501
PA-12, PA-14, PA-20, PA-22 Series; T.C. 780, 797, 1A4, 1A6	SA5-60	Installation of Russ Simpson sea fins.	AL	71774	Simpson Airservice, Inc. P.O. Box 2226 Ketchikan, AK 99901
PA-12; PA-22; T.C. A780, 1A6	SA388SO	Metalize wings, wing landing/taxi light installation. Amended 7/2/70.	SO	68550	W.F. Robison Valley Air Service P.O. Box 241 Lanett, AL 36863
PA-12, PA-22, PA-23, PA-28; T.C. 780, 1A6 2A13, 1A10	SA316SO	Carburetor ice detector. Amended 10/5/66.	SO	71545	C.B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
PA-12S; T.C. 780	SA610AL	Install Avco Lycoming O-360-A2A engine. Amended 2/25/77.	AL	20514	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14 Series; T.C. 797	SA1-51	Lycoming O-290-D2 engine with Edo 89-2000 floats, water rudder and seaplane fin.	EA	14775	Arthur E. Barr 387 Eldred Street Williamsport, PA 17701
PA-14 Series; T.C. 797	SA1-573	Lycoming O-320 engine with PA-18A-150 cylinder baffles, Sensenich M74DM propeller and Harrison AP13-SJ03-01 oil cooler.	EA	77082	Susquehanna Aero Marine 378 Eldred Street Williamsport, PA 17701
PA-14 Series; T.C. 797	SA3-106	Edo 89-2000 floats, water rudder and auxiliary tail fin.	GL	61515	Henry E. Neils 2637 27th Avenue South Minneapolis, MN 55401

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-14 Series; T.C. 797	SA4-78	Lycoming O-320 engine, Sensenich M74DM59 propeller, Piper PA-18A-150 engine cooling baffles modified, Harrison AP13-SJ03-01 oil cooler.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-14 Series; T.C. 797	SA4-81	Lycoming O-290-D2 engine and Sensenich M76AM-2/74-52 propeller.	NW	50900	Marine Air, Inc. Friday Harbor, WA 98250
PA-14 Series; T.C. 797	SA4-410	Lycoming 150 hp engine O-320-A2A.	WE	14960	Bates Aviation, Inc. 940 East 120th Street Hawthorne, CA 90250
PA-14 Series; T.C. 797	SA4-411	Modification of fuel system to PA-18 to facilitate takeoff either tank.	WE	14960	Bates Aviation, Inc. 940 East 120th Street Hawthorne, CA 90250
PA-14 Series; T.C. 797	SA4-412	Large PA-18 tail surfaces.	WE	14960	Bates Aviation, Inc. 940 East 120th Street Hawthorne, CA 90250
PA-14 Series; T.C. 797	SA4-561	Application of glass cloth to fuselage and to horizontal and vertical stabilizer.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-14 Series; T.C. 797	SA4-913	Ceconite 101 covering of wings, fuselage and vertical fin.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-14 Series; T.C. 797	SA57NW	Installation of Lycoming O-320-E2D engine, McCauley TM7653 propeller and Lycoming alternator. Issued 3/6/74.	NW	61526	Harold G. Nelson 3005 Southwest Marshall Street Pendleton, OR 97801
PA-14 Series; T.C. 797	SA192AL	Flap handle installation and adjustable fore and aft pilot and co-pilot's seat.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-14 Series; T.C. 797	SA196SW	Hartzell HC-82XL-6F/7636D-4 propeller, Woodward 210080P governor, and Piper 14-733-00 propeller control	SW	71776	J.B. Simpson P.O. Box 126 Gilliam, LA 71029
PA-14 Series; T.C. 797	SA253AL	Installation of McCauley 1A175/GM propeller. Amended 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-14 Series; T.C. 797	SA356AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-14 Series; T.C. 797	SA368AL	Installation of McCauley 1A175/GM8242, GM8244, or GM8246 propellers. Amended 8/18/72.	AL	28660	Daniels & Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-14 Series; T.C. 797	SA378SW	Lycoming O-320 engine, -6-inch wheels, and Piper PA-18 horizontal tail surfaces.	SW	01575	Aerial Repairing P.O. Box 909 Ponca City, OK 74601
PA-14 Series; T.C. 797	SA398AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-14 Series; T.C. 797	SA469AL	Installation of electric fuel gauges. Amended 5/1/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-14 Series; T.C. 797	SA477AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-14 Series; T.C. 797	SA477AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14 and Seaplane Versions; T.C. 797	SA496AL	Installation of leading edge cuff. Amended 3/4/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA502AL	Installation of cargo door in right side of aircraft. Amended 10/31/73.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-14; T.C. 797	SA505AL	Installation of landing gear safety cables. Issued 10/1/73.	AL	30250	F. Atlee Dodge Aircraft Maintenance 2301-1/2 Merrill Field Drive Anchorage, AK 99502

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-14; T.C. 797	SA528AL	Installation of welded steel rear float fittings. Reissued 1/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA534AL	Installation of auxiliary fuel tank. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99503
PA-14; T.C. 797	SA538AL	Installation of modified landing gear (PA-18 type) with main landing gear legs lengthened 6 inches. Issued 1/30/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
±1 PA-14; T.C. 797	SA541AL	Installation of *O-360-A2A Lycoming* engine and McCauley 1A200 DFA 82-45 propeller. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA546AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-14; T.C. 797	SA546AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA548AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-14; T.C. 797	SA548AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA562AL	Installation of Day & Night 2-4 aluminum engine cowling. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-14; T.C. 797	SA562AL	Installation of Day & Night 2-4 aluminum engine cowling. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA567AL	Installation of O-320-A2B Lycoming engine. Issued 11/21/75.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-14; T.C. A-797	SA598AL	Installation of Day & Night modified flap control system.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-14; T.C. A-797	SA598AL	Installation of Day & Night modified flap control system.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA630AL	Install fiberglass wing tip assembly. Issued 4/28/78.	AL	20512	Charles C. Center 8134 LAke Otis Parkway Anchorage, AK 99507
PA-14; T.C. A797	SA645AL	Install Avco Lycoming O-320-D2A or O-320-B2B engine and McCauley 1A175/GM8246 prop. Issued 7/31/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. A797	SA647WE	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA657AL	Install Avco Lycoming O-320-A2B or O-320-E2D engine and McCauley 1A175/GM 8246 propeller. Issued 11/27/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA3413WE	Installation of George M. Adams DMA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avneue Torrance, CA 90501
PA-14, PA-18, PA-20; T.C. 797, 1A2, 1A4	SA41AL	Six inch wheels and brakes.	GL	56570	Wesley W. Mathias 154 North Broad Street Bremen, OH 43107
PA-15; T.C. 800	SA1-619	Continental A-65-8F engine and McCauley 1A90CF-7147 propeller.	NE	39514	Griswold Air Service Griswold Airport Madison, CT 06443
PA-15; T.C. 800	SA4-1225	Ronite covering on complete aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93308

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-15; T.C. 800	SA69AL	Installation of fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-15; T.C. 800	SA3214WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-15, PA-17; T.C. 800, 805	SA4-1025	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-16 Series; T.C. 1A1	SA1-577	Installation of Sensenich controllable pitch propeller Model CS3FM4/C374E. Amended 6/24/70.	EA	64268	Theodore J. Peters County Line Road, RD 3 Sommerville, NJ 08876
PA-16 Series; T.C. 1A1	SA4-900	Ceconite 101 covering of wings, fuselage, ailerons, elevator and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-16 Series; T.C. 1A1	SA399AL	Conversion of 4" wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-16 Series; T.C. 1A1	SA412NW	Replace original equipment expander-tube brakes with new Cleveland wheels and brakes. Issued 3/3/77.	NW	00300	Michael J. Abdo 9415 Lexington Avenue, S.W. Tacoma, WA 98498
PA-16 Series; T.C. 1A1	SA3215WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-16, -16S; T.C. 1A1	SA447AL	Installation of auxiliary fuel tanks in right wing. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-16, -16A; PA-18, PA-18S, "105", "125", "135", "150"; "PA-18A"135", "150:"; PA-18AS"125", "135", "150"; PA-19S; PA-23, -23-160, -235, -23-250; PA-24, -24-250, -260; PA-28-140, 150, 160, 180, -235, PA-28-S-160, -S-180; PA-30; T.C. 1A1, 1A2, 1A10, 1A15, A1EA, 2A13	SA630WE	Installation of Coast Winslow Filter Corporation 409 series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-282	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-327	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16S; T.C. 1A1	SA384AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/17/70.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-17 Series; T.C. 805	SA4-483	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-17 Series; T.C. 805	SA446AL	Installation of fuel tanks. Amended 2/7/75.	AL	17000	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-17 Series; T.C. 805	SA3216WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18 Series; T.C. 1A2	SA388EA	Lycoming O-320 engine.	EA	61075	J. Arlington Myers 228 East Keller Street Castanea, PA 17726
PA-18 Series; T.C. 1A2	SA425AL	Installation of removable seat back support. Issued 4/23/71.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99503
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18 Series; T.C. 1A2	SA526AL	Build up 1-1/4" axle to 1-1/2" axle to install Celveland wheel and brake. Issued 8/7/74.	AL	68436	Bill Robek Box 10-214 Klatt Station ANchorage, AK 99502
PA-18 Series; T.C. 1A2	SA540AL	Installation of modified landing gear with main gear legs lengthened 6 inches. Issued 2/19/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18; T.C. 1A2	SA1586CE	Modified brake master cylinder. Issued 5/9/80.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-18 Series; T.C. 1A2, AR-7	SA1-32	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
t+1 PA-18 Series; T.C. 1A2, AR-7	SA1-41	McCauley fixed pitch MET-L-PROP 1A170/GM7450, 1A170/GM7452 and 1A170/GM7454 propellers with Lycoming O-320-A1A engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-59	McCauley fixed pitch MET-L-PROP 1A170/GM7448 and 1A170/GM7450 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-155	McCauley fixed pitch MET-L-PROP 1A170/GM7448 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell AVenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-156	McCauley fixed pitch MET-L-PROP 1A170/GM7446 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-349	Glider tow. Amended 5/12/67.	EA	70400	Schweizer Aircraft Corporation Box 147, County Airport Elmira, NY 14902
PA-18 Series; T.C. 1A2, AR-7	SA4-254	Hartzell HC82XG-6/7636D-4 propeller Lycoming 70385 dual drive assembly, Woodward 210115 single acting governor and J-6230-1 lord mount assembly.	WE	15415	Ellen Belotti 1208 East Charleston Road Las Vegas, NV 89114
PA-18 Series; T.C. 1A2, AR-7	SA4-364	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-18 Series; T.C. 1A2, AR-7	SA4-1644	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-18 Series; T.C. 1A2, AR-7	SA5-31	Auxiliary baggage tube.	AL	17000	M.R. Borer 1307 West 39th Place Spenard, AK
PA-18 Series; T.C. 1A2, AR-7	SA4AL	Installation of auxiliary wing fuel tanks. Amended 5/20/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
PA-18 Series; T.C. 1A2, AR-7	SA4RM	Installation of modified landing gear, Cleveland P/N 40-84 wheels and P/N 30-41 brakes. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-18 Series; T.C. 1A2, AR-7	SA17RM	Replace landing gear vee for PA-18 series P/N 10033. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-18 Series; T.C. 1A2, AR-7	SA24EA	Conversion of aircraft for parachute jumping and aerial photography operations.	EA	61075	J. Arlington Myers 331 North Water Street Mill Hall, PA 17751

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18 Series; T.C. 1A2, AR-7	SA44AL	Auxiliary wing fuel tanks.	AL	86070	Joseph Wilbur P.O. Box 931 Anchorage, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA50AL	Cowl flaps.	AL	05960	Aircraft Repair & Maintenance Co. P.O. Box 6207 Anchorage, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA70EA	Edo 339JHS amphibious floats.	EA	61622	North American Flying Service, Inc. Bergen Turnpike Little Ferry, NJ 07643
PA-18 Series; T.C. 1A2, AR-7	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Co. airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
PA-18 Series; T.C. 1A2, AR-7	SA141AL	Removal of agricultural hatch.	AL	45000	Jake's Aircraft Salvage 3906 Barbara Drive Spenard, AK 99503
PA-18 Series; T.C. 1A2, AR-7	SA143AL	Enlarged instrument panel.	AL	30250	F.A. Dodge P.O. Box 6409 Anchorage, AK 99506
PA-18 Series; T.C. 1A2, AR-7	SA150AL	Installation of cockpit operated cowl flap winterization kit. Reivsed 7/29/69.	AL	39400	Charles L. Gray 319 Slater Street Fairbanks, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA230EA	Flottorp controllable pitch propeller.	EA	11730	Arnold Air Service Dale & Mackey Road, RD 2 Gasport, NY 14067
PA-18 Series; T.C. 1A2, AR-7	SA234SW	Alteration of method of attaching spray plates and dust spreader to spray tank and alteration of emergency dump cable hookups.	SW	42480	John L. Borne, Jr. P.O. Box 218 Webbers Falls, OK 74470
PA-18 Series; T.C. 1A2, AR-7	SA284SW	Landplane lower cowl on aircraft with Edo 89-2000 floats.	SW	72752	Slidell Aviation Services Route 2, Box 99 Slidell, LA 70458
PA-18 Series; T.C. 1A2, AR-7	SA324CE	Manufacture hitch and bracket. Install tow hitch. Amended 5/6/71.	CE	76500	Stubben-McCandless South Omaha Airport Route 1 Papillion, NE 68046
PA-18 Series; T.C. 1A2, AR-7	SA569SW	Cessna 172 landing gear.	SW	61100	Myband and Deam Aircraft Route 5, Box 505 Pine Bluff, AR 71601
PA-18 Series; T.C. 1A2	SA894WE	Lycoming O-320-A2B engine and Sensenich M74DM-56 propeller.	RM	35770	Sam B. Flint P.O. Box 332 Holly, CO 81047
PA-18, PA-18A; T.C. 1A2, AR-7	SA4-1430	125-gallon hopper and small swathmaster. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-18, PA-18A; T.C. 1A2	SA1243CE	Install Cleveland wheels and brakes and optional wheel fenders. Amended 9/29/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, -18A; T.C. 1A2	SA1244CE	Replace landing gear components. Issued July 1976.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, PA-19; T.C. 1A2, AR-7	SA3-180	C2200 main (hydraulically actuated) and CTF2200 or CT3000 tail skis.	GL	36030	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA3-328	C-2200 main (manually actuated) and AWT2500 or AWT2500A tail wheel-skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA3-352	Model 3000 main skis and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA4-823	Sonite covering on entire aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-18, PA-19; T.C. 1A2, AR-7	SA4-986	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18, PA-19, PA-20; T.C. 1A2, 1A4	SA3-423	CT-3000 tail ski on airplanes with Scott 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-20, PA-22; T.C. 1A2, AR-7, 1A4, 1A6	SA3-654	Laminated plastic and fiberglass nose.	RM	28500	Dakota Aviation Company P.B. Box 18 Huron, SD 57350
PA-18, PA-22, PA-23, PA-24 Series; T.C. 1A2, 1A6, 1A10, 1A15	SA1-383	Lube oil filter PB 55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
PA-18, -22, -23, -24, -25, -28 Series; T.C. 1A6, 1A2, AR-7 1A10, 1A15, 2A13	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace AVenue Torrance, CA 90510
PA-18, PA-25; T.C. 1A2, AR-7, 2A8	SA673SW	All metal covering of aileron.	SW	60168	Luther W. Moore 1110 West 29th Street Plainview, TX 79072
PA-18, 90 thru 150; T.C. 1A2	SA753CE	Installation of skis.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
PA-18, -18A, -105, -125, -135, -150, 18A-135, -150; T.C. 1A2	SA400AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	GL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-18, -18"105", -18A, -18"125", -18"135", -18A-"135", -18"150", -18A-150, -19 and seaplane versions; T.C. 1A2	SA427AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 2078 Buffalo, MO 65662
PA-18, -18"105", -18A, -18"125", -18"135", -18A-"125", -18"150", -18A-150, -19 and seaplane versions; T.C. 1A2	SA427AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18, -18A, -18-105, -18-125, -18-135, -18A-135, -18-150, and seaplane versions; T.C. 1A2	SA489AL	Installation of modified dog leg brace baggage compartment. Issued 10/24/72.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-18, -18-105, -125, -135, -150, PA-18S, -18S-105, -125, -135, -150, PA-18A, -18A-135, -150, PA-18AS-125, -135, -150, PA-19, PA-19S; T.C. 1A2	SA624AL	Install fiberglass wing tip assembly. Issued 3/21/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, PA-18-105, -125, -135, -150, PA-18S, PA-18S-105, -125, -135, -150, PA-18A, -18A-135, -150, PA-18AS-125, -135, PA-19, PA-19S; T.C. 1A2	SA638AL	Fabricate rudder mounted strobe light support bracket. Issued 6/14/78.	AL	30250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18, -18-105, -125, -135, -150, PA-18, -18-105, -125, -135, -150, PA-18A, -18A-125, -18A-135, -150, PA-18AS-125, -135, -150; T.C. 1A2	SA641AL	Fabricate front wing spar butt attachment repair fitting. Issued 7/10/78.	AL	20514	Clinton C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, -18"105" Special, -18A, -18"125", -18"135", -18A"135", -18"150", -18A"150", -19; T.C. 1A2	SA900CE	Replace round wing tips with constant-chord, square tips and wing splates. Amended February 1975.	CE	35650	James W. Flanagan and Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18, -18A, PA-19; T.C. 1A2	SA1245CE	Installation of Scott master cylinder having Flanagan Aircraft conversion. Amended 6/22/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, -18A, -18-105, -18-125, -18-135, -18-150, -18A-150, PA-19; T.C. 1A2	SA2478WE	Installation of automatic flagman Model 5. Issued 2/14/72.	NW	03500	Air-Ag, Inc. Route 4, City County Airport Walla Walla, WA 99362

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18, -105, -125, -135, -150; T.C. 1A2	SA5-7	Install framing and seat in baggage compartment. Amended 7/25/68.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99501
PA-18, -18-105, -125, -135, -150, PA-18A-125, -135, -150; PA-19; T.C. 1A2	SA301AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99501
PA-18, -18"105", -18A, -18"125", -18"135", -18A"135", -18"150", -18A"150", PA-19 (Army L-18C); T.C. 1A2	SA3282WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-18, -18S, -18-135, -18S-135, -18A-135, PA-18-105 (Special), PA-18S-105 (Special), PA-18-150, -18A-150, -18S-150; T.C. 1A2	SA490AL	Installation of leading edge cuff. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, -18S, -18"105", "125", "135", "150", -18A, "135", "150", -18S"105", "125", "135", "150", PA-19, -19S, PA-22, -22-108, -135, -150, -160, -22S-135, -150, PA-24, -24-250, -260; T.C. 1A2, 1A6, 1A15	SA1033EA	Replace steel oil cooler lines with Aeroquip type 303-8 hose using AN-823-8D elbows, AN-816-8D nipples and AN-321-8 hose fittings. Issued 1/29/76.	EA	78472	Walter Thompson, Sr. 32 High View Avenue Florida, NY 10921
PA-18, -18-125, -18-135, -18-150; PA-19; T.C. 1A2	SA2468WE	Use of GCA-600 axle adapter assembly for installation of Cleveland Model 40-84A wheels and Model 30-41 brakes. Issued 1/20/72.	WE	15435	Ken Bemis Brawley Municipal Airport P.O. Box 1293 Brawley, CA 92227
PA-18A; T.C. 1A2	SA681AL	Installation of removable crossbar. Issued 1/10/80.	AL	30250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18A; T.C. 1A2	SA886CE	Metalize bottom of fuselage per Flanagan Aircraft Drawing List No. 2. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A; T.C. 1A2	SA887CE	Removal of hopper cover and installation of Lexan skylight and side windows. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A; T.C. 1A2	SA888CE	Relocation of battery box and/or installation of an external power receptacle. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A, -18A-135, -18A-150; T.C. 1A2	SA5-29	Install third seat in baggage compartment and relocate battery aft of baggage compartment. Amended 7/25/68.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99503
PA-18A, PA-18A"135"; -18A"150"; T.C. 1A2	SA1369CE	Electrical system and instrument panel modification. Issued 9/28/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18S, -19S, -18S"105" (Special), -18S"125" -18S"135"; T.C. 1A2	SA3-96	Install Pee-Kay Model 1500 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-105, 18S-105, -125, 18S-125, -18AS-125, 18-135, 18S-135, 18A-135, -18AS-135; T.C. 1A2	SA136AL	Installation of Lycoming O-320 engine. Amended 5/14/68.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-105, -18S-105, -18-125, -18A-125, -18AS-125, -18A-135, -18S-135, -18AS-135; T.C. 1A2	SA292AL	Increased gross weights to PA-18-150 weights and C.G. envelope. Note: Airplanes must have Lycoming O-320 engine installed, except the PA-18-135 or PA-18-135 for which the engine change is optional. Amended 5/5/72.	AL	17000	W.T. Ellis and M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18-105, -125, -135, -150, -18S, -105, -125, -135, -150, -18A-135, -150, -18AS-125, -135, -150, PA-16, PA-16S, PA-19S, PA-22, -108, -125, -150, -160; PA-23, -160, -250; PA-24, -250; PA-24-400; PA-28-160, -235; PA-30; T.C. 1A6, 1A10, 1A15, 2A13, A1EA	SA589WE	Installation of full-flow lube oil filters on the aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court San Leandro, CA 94577
PA-18S, PA-18S"105", -18S"125", -18AS"125", -18S"135", -18AS"135", PA-19S; T.C. 1A2	SA159CE	Installation of Pee-Kay Model 1800 floats. Reissued 6/12/74.	EA	29998	Pee-Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-125; T.C. 1A2	SA669CE	Install Aqua Model 1900 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Reserach and Engineering, Inc. 805 Geiger Road Zephyrhills Hills, FL 33599
PA-18-125, -18A, -18-135, -18A-135, -18-150, -18A-150, 18S-125, -18AS, -18S-135, -18AS-135, -18S-150, -18AS-150, T.C. 1A2	SA98AL	Installation of two auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-18-125, -135, -150, -18S-125, -135, -150, 18A-135, -150, 18AS-135, -150; T.C. 1A2	SA117AL	Installation of Cunningham auxiliary fuel belly tank. Amended 9/16/68.	AL	08472	Airglas Engineering Co., Inc. P.O. Box 4165 Anchorage, AK 99502
PA-18-125, PA-18-135, PA-18A-135; T.C. 1A2	SA388EA	Installation of Lycoming O-320, O-320-A2A or O-320-A2B engine (150 hp) and Sensenich propeller M74DM-56 configuration I. Increase in maximum allowable gross weight and C.G. limits as per Model PA-18-150 values - configuration II. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-18S-125; T.C. 1A2	SA2397WE	Installation of McCauley Model 1A175-GM/8240 propeller. Issued 10/27/71.	NW	09300	Kenneth R. Alexander 1732 Northwest 64th Seattle, WA 98107
PA-18S"125", PA-18S-135, 18S-150; T.C. 1A2	SA879EA	Installation of Edo Model 88A-1650 seaplane floats with Edo Model 088A21 attachment gear. Reissued 4/1/76.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
PA-18S-125, -150; T.C. 1A2	SA1099WE	Install fiberglass reinforced plastic floats. Reissued 9/20/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
PA-18-135; T.C. 1A2, AR-7	SA1-33	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine. Amended 9/5/75.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-18-135, -18A-135, -18S-135, -18AS-135, -18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA279AL	Installation of McCauley 1A175/GM propeller on -135 models listed and installation of McCauley 1A175/GM 8241 through GM 8244 on the -150 models listed. Amended 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-135, -18A-135, -18-150; T.C. 1A2	SA518CE	Install Aqua Model 1900 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research and Engineering, Inc. 805 Geiger Road Zephryhills, FL 33599
PA-18"135", -18A"135", -18S-"135", -18AS"125", -18"150", -18A-"150", -18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622
PA-18"135", -18A"135", -18S-"135", -18AS"135", -18"150", -18A-"150", '18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1333CE	Installation of replacement engine mount. Issued June 1977.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1366CE	Installation of a third seat, removable cross member, and reinforced baggage compartment floor. Issued 8/26/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18-135, -150, PA-20, PA-22, PA-23, PA-24 less 24-180, -24-280, -24-400, PA-25, PA-28 less -28-140, PA-28-180, -235, PA-30, PA-31, PA-32, PA-34, PA-39; T.C. 1A2, 1A4, 1A6, 1A10, 1A15, 2A8, 2A10, 2A13, A1EA, A8EA, A3SO, 1A10, A1EA	SA1512WE	Installation of exhaust gas temperature monitoring system Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18-135, -150, PA-22, PA-23, PA-24, -24-400, PA-28, -28-235, PA-30, PA-31, PA-32; T.C. 1A2, 1A6, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18A-135, PA-18A-150; T.C. 1A2	SA1368CE	Cabin metalization; installation of new boot cowl, firewall, swing up side windows, larger baggage door, and inspection access in aft fuselage. Issued 9/12/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18S-135; T.C. 1A2	SA288AL	Install McCauley 1A175-GM8040 or 1A175-GM8044 propeller. Amended 4/2/69.	GL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645
PA-18-150; T.C. 1A2	SA36RM	Installation of Lycoming O-360-C2A or O-360-A3A 180 hp engine. Issued 11/22/74.	RM	46780	David C. Johnson 10850 Thomas Road Colorado Springs, CO 80908
PA-18-150; T.C. 1A2	SA532AL	Installation of Lycoming O-360-A2A engine. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150"; T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-18"150"; T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18-150; T.C. 1A2	SA590AL	Install extended baggage compartment. Issued 7/2/76.	AL	39250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18-150; T.C. 1A2	SA596AL	Install Hartzell propeller Model HC-C2YL-1BF/F8468-8R. Issued 3/4/77.	AL	30250	Atlee R. Dodge P.O. Box 6409 Anchorage, AK 99509
PA-18-150; T.C. 1A2	SA612AL	Extended ailerons. Issued 5/25/77.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18"150", -18A"150", -18S"150", -18AS"150"; T.C. 1A2	SA4-1143	Installation of Lycoming O-320-A3B engine and Hartzell HC-82XL-6B/7636D-2 propeller. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
PA-18"150", -18A"150"; T.C. 1A2	SA92NW	Installation of Lycoming O-360-A2D engine, McCauley 1A200-FA8241 propeller, and associated sub-systems. Issued 3/1/74.	NW	32756	Ed's Aviation Service P.O. Box 156 Arlington, WA 98223
PA-18"150", -18A"150"; T.C. 1A2	SA109CE	Installation of Pee-Kay Model 1800 floats. Reissued 6/12/74.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-150, -18A-150; T.C. 1A2	SA349AL	Installation of McCauley 1A175-GM 8242, GM8244, or GM8246 propeller. Amended 4/10/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18-150, -18A-150; T.C. 1A2	SA353AL	Installation of Sorensen Aircraft Co. 60-gallon belly tank. Revised 2/12/71.	AL	76900	Superior Airmotive of Alaska, Inc. 2301 Merrill Field Drive Anchorage, AK 99501
PA"18"150", PA"18A"150"; T.C. 1A2, AR-7	SA575WE	Belly master spray system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-18-150, -18A-150; T.C. 1A2	SA589AL	Install square horizontal stabilizers, elevators, and rudder. Issued 6/28/76.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA284AL	Installation of Hartzell propeller with Woodward 2100-80-RS governor. Amended 10/30/75.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA510AL	Installation of "Summer-all defroster valve". Issued 1/10/74.	AL	76738	Sumrall & Tears 3001 Yale Drive Anchorage, AK 99504
PA-18"150", PA-18S"150"; T.C. 1A2	SA648AL	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150", PA-18A"150", PA-18S"150", PA-18AS"150"; T.C. 1A2	SA649AL	Fabricate 30.5 gallon wing fuel tanks. Issued 8/17/78.	AL	30250	F. Atlee Dodge Box 4609 Anchorage, AK 99502
PA-18A-150; T.C. 1A2	SA623AL	Install wing tip assembly.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18A"150"; T.C. 1A2	SA1370CE	Revised fuel gaging and dual fuel feed line installation from both tanks. Two wing fuel tanks standard. Issued 11/18/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18S-150, 18AS-150; T.C. 1A2	SA392AL	Installation of McCauley 1A175 GM8242, 8244, or 8246 propeller. Amended 5/28/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-20 Series; T.C. 1A4	SA1-89	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engines.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-20 Series; T.C. 1A4	SA1-157	McCauley fixed pitch MET-L-PROP 1A170/GM7450 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-20 Series; T.C. 1A4	SA1-167	Lycoming O-320 150 hp engine, Sensenich M-74DM propeller, Piper PA-22-150 engine baffles, and and Harrison AP13SJ03-01 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamsport, PA 17701
PA-20 Series; T.C. 1A4	SA4-564	Bonite covering on wings, fuselage and control surfaces.	WE	52090	William C. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
t+1 PA-20 Series; T.C. 1A4	SA4-778	Ceconite covering.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-20 Series; T.C. 1A4	SA12RM	Installation of Light Plane Components landing gear vee assembly, P/N LPC 1012. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-20 Series; T.C. 1A4	SA31CE	Removal of rear left door and installation of placard.	CE	50725	Lincoln Sport Parachute Club, Inc. 929 Furnas Avenue Lincoln, NE 68501
PA-20 Series; T.C. 1A4	SA73CE	Covering with dacron of wings, fuselage, tail group, flaps, all control surfaces, or any of these individually.	GL	30518	Downer Aircraft Company P.O. Box 46 Alexandria, MN 56308
PA-20 Series; T.C. 1A4	SA211WE	Removal of left-hand cabin door for parachute jumping and aerial photography operations.	RM	38040	Glacier View Skyways, Inc. P.O. Box 252 Kalispell, MT 59901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-20; T.C. 1A4	SA224GL	Install Gerdes control wheels, Model No. A-1561-C and A-1562-C utilizing AN3-12 bolts (2), AN3-65 self-locking nuts (2) and AC-940-316 washers(2). Issued 2/15/78.	GL	64950	Matthew C. Poleski 25 Immelman Lane Hampshire, IL 60140
PA-20 Series; T.C. 1A4	SA278WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-20 Series; T.C. 1A4	SA509AL	addition of crankcase relief valve. Issued 11/16/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-20 Series; T.C. 1A4	SA542AL	Installation of leading edge cuff. Amended 3/4/77.	AL	27250	Crosswinds, Inc. 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20 Series; T.C. 1A4	SA671WE	BN-1 propeller spinner.	WE	75250	Raymond M. Stits 3665 Rubidoux Boulevard Riverside, CA 92502
PA-20 Series; T.C. 1A4	SA3217WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm L. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-20, PA-20-115, -20-135; T.C. 1A4	SA12AL	Installation of auxiliary fuel tank(s). Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2350 East Fifth Avenue Anchorage, AK 99501
PA-20 Landplane, -20-115, -135; T.C. 1A4	SA25EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lycons, WI 53148
PA-20, -20S; T.C. 1A4	SA125AL	Installation of squared off wing tips and end plates. Amended 12/1/65.	AL	61640	Northland Aviation P.O. Box 3143 Fairbanks, AK 99702
PA-20-115, -135; T.C. 1A4	SA401AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-20, PA-20S, -20-115, -20S-115, -20-135, -20S-135, and these models modified by STC SA1-167 (150 HP Lycoming O-320 engine); T.C. 1A4	SA396GL	Installation of Aero Ski wheel replacement skis in accordance with the following: 1) Model M1800 and M2000 skis, 2) Model M3000H skis. Issued 4/18/80.	GL	02750	Aero Ski Manufacturing Co., Inc. Box 346 Park Rapids, MN 56470
PA-20, -20S, -20"115", -20S-"115", -20-"135", -20S-"135"; T.C. 1A4	SA479AL	Installation of fiberglass wing tips. Issued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-20, -20S, -20"115", -20S-"115", -20-"135", -20S-"135"; T.C. 1A4	SA479AL	Installation of fiberglass wing tips. Issued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-20, -20-115, -135, PA-20S, -20S-115, -135; T.C. 1A4	SA626AL	Install fiberglass wing tip assembly. Issued 3/21/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20, -115, -20S, -20S-115, -135, -20S-135; PA-22, -135, 22S-135, -150, 22S-150, -160, 22S-160, -108; PA-24, -250, -400, -260; PA28-140, -150, -160, -180, -235, S-160, S-180, R-180; PA-30; PA-32-260, -300, 32S-300; T.C. 1A4, 1A6, 1A15, 2A13, A1EA, A3SO	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
PA-20, PA-20"115", -"135", PA-20S"115", -"135", PA-22, 22-108, -135, -150, -160, 22S-135, -150, -160; T.C. 1A6	SA2142WE	Installation of DASCO heated pitot tube kit No. 2022-12.	WE	30129	Diversified Aviation Service Co. 20499 Santa Maria Avenue Castro Valley, CA 94546
PA-20, PA-20-"135"; T.C. 1A4	SA635AL	Install Avco Lycoming O-320-A2B engine and Sensenich propeller. Issued 6/6/78.	EA	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-20-115, -20-135, PA-22, -22-135, -150, -160, -108, PA-23, -23-160, PA-24 S/N 1 thru 1476, PA24-250 S/N 1 thru 1476; T.C. 1A4	SA71GL	PA-20's install BA4106 filter assembly, PA-22's install BA4016 filter assembly, PA-23's, -24 install BA-3110 filter assembly, PA-24-250 install BA-3210 Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities Co. 9600 West 52nd Street Kenoska, WI 53140
PA-20-135; T.C. 1A4	SA1-24	McCauley fixed pitch MET-L-PROP Models 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine. Reissued 8/5/77.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-20S, PA-20-115, -22-135; T.C. 1A4	SA118GL	Installation of Huron Aviation Products alternator, P/N 10346 and regulator, P/N 10316. Amended 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-20S, 20S-115, 20S-135, PA-20S*; T.C. 1A4	SA385AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/21/70. *This approval includes PA20S models with Lycoming O-320, 150 hp engine installed per an appropriate STC.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20S, -20S*, -115*, -135*; T.C. 1A4	SA387AL	Installation of McCauley 1A175GM8241 propeller. Issued 7/23/70. *Aircraft must be equipped with Edo 88-1650 floats and modified in accordance with STC SA1-167.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20S-115, -125; T.C. 1A4	SA388AL	Installation of Edo 88-1650 floats (Spec item 209(a)) when modified per STC SA1-167 and SA387AL. Issued 8/3/70.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20, PA-22 Series; T.C. 1A6	SA1-132	24ST alclad on wings.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-20, PA-22 Series; T.C. 1A6	SA1-133	24ST alclad skin on flaps.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-20, PA-22 Series; T.C. 1A6	SA1-325	Replacement of fabric covering with metal skins, ailerons and flaps.	EA	72100	Skycraft Design, Inc. P.O. Box 67 West Trenton, NJ 08628
PA-20, PA-22 Series; T.C. 1A6	SA1-492	Metallizing of wing panel excluding aileron and flap.	NE	27770	Custom Aircraft Industries 30 Broad Street Pascoag, RI 02859
PA-20, PA-22; T.C. 1A4, 1A6	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
PA-20, PA-22 Series; T.C. 1A6	SA1487WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA1-22	McCauley fixed pitch propellers 1A170/GM7459 and 1A170/GM7457 with Lycoming O-320 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-23	McCauley fixed pitch propellers 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-90	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-108	69A110 gyro stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
PA-22 Series; T.C. 1A6	SA1-128	Dry vacuum pump 113A1 for counter-clockwise engine accessory drive and 113A2 for clockwise drive, or 10-113-1 and 10-113-2.	GL	66380	Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
PA-22 Series; T.C. 1A6	SA1-131	Dural angles and 24ST alclad skin on fuselage.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-22 Series; T.C. 1A6	SA1-255	Dart I-M turn control unit.	EA	61400	Navigation Devices, Inc. P.O. Box 1107 Binghamton, NY 13902

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22 Series; T.C. 1A6	SA1-275	Lycoming O-320 150 hp engine and Sensenich M74DM propeller, Piper PA-22-150 engine baffles, Harrison AP13SJ03 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamsport, PA 17701
PA-22 Series; T.C. 1A6	SA1-337	Oil-free vacuum pump PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-22 Series; T.C. 1A6	SA1-386	Installation of heated pitot tube.	EA	34180	Federal Aviation Administration Engineering & Manufacturing Branch Federal Building, EA-210 JFK International Airport Jamaica, NY 11430
PA-22 Series; T.C. 1A6	SA3-77	Vertical fin plates attached to tip ribs of horizontal stabilizer for seaplane operation only.	GL	60092	Modern Die & Tool Company 227 Iron Street Detroit, MI 48233
PA-22 Series; T.C. 1A6	SA3-143	Grimes D7080-12 rotating beacon on fuselage access panel.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
PA-22 Series; T.C. 1A6	SA3-363	Installation of Doyn fiberglass wheel fairings. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
PA-22 Series; T.C. 1A6	SA3-382	Manually operated oil cooler shutter assembly.	CE	65020	Ken L. Potter 13831 Botts Road Grandview, MO 64030
PA-22 Series; T.C. 1A6	SA3-477	C2200 (hydraulically actuated) main and AWN1200A nose wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-22 Series; T.C. 1A6	SA3-494	C2200 (manually actuated) main and AWN1200A nose wheel -skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-22 Series; T.C. 1A6	SA3-631	Dacron cover.	GL	30518	Downer Aircraft Industries, Inc. Municipal Airport Alexandria, MN 56308
PA-22 Series; T.C. 1A6	SA3-639	Removal of rear door, operation with door removed, and reinstallation of door.	CE	50715	Lincoln Aviation Inst., Inc. P.O. Box 4168, Havelock Station Lincoln, NE 68529
PA-22 Series; T.C. 1A6	SA4-114	Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-22 Series; T.C. 1A6	SA4-222	Fiberglass covering.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
PA-22 Series; T.C. 1A6	SA4-298	Fuselage structural alterations and additions to provide for the installation of Fairchild Aviation aerial camera A5A or similar.	WE	62063	Pacific Aero Industries Municipal Airport San Jose, CA 95125
PA-22 Series; T.C. 1A6	SA4-343	"B" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-22 Series; T.C. 1A6	SA4-391	Fiberglass wheel fenders.	NW	85550	Art Whitaker Pearson Field Vancouver, WA 98660
PA-22 Series; T.C. 1A6	SA4-423	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA4-815	Lycoming O-320 engine and Sensenich M74DM propeller.	NW	53200	McKenzie Aircraft Repair 1300 North 27th Street Springfield, OR 97477
PA-22 Series; T.C. 1A6	SA4-871	Aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-22 Series; T.C. 1A6	SA4-903	Ceconite 101 covering of fuselage, wings, horizontal and vertical stabilizer, ailerons, flaps, rudder and elevator.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-22 Series; T.C. 1A6	SA4-938	Eonite covering on entire aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22 Series; T.C. 1A6	SA4-998	Installation of wheel fairings. Reissued 2/9/71.	NW	12565	Aurora Air, Inc. d/b/a Madras Air Service Madras, OR 97741
PA-22 Series; T.C. 1A6	SA4-1346	Fiberglass cover on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
PA-22 Series; T.C. 1A6	SA4-1502	AB-6564 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-22 Series; T.C. 1A6	SA4-1587	Retractable wheel fairing on main landing gear.	WE	30708	Duce Aircraft Company R.R. 4, Box 711 Valley Center, CA 92082
PA-22 Series; T.C. 1A6	SA4-1621	Removal of left-hand door for parachute jumping and aerial photography.	WE	19856	Capitol Sky Park, Inc. Municipal Airport Sacramento, CA 95855
PA-22 Series; T.C. 1A6	SA5-30	Rear door removed.	AL	69740	Safeway Airways P.O. Box 1062, Merrill Field Anchorage, AK 99500
PA-22 Series; T.C. 1A6	SA48AL	L1650A or L2000A skis.	AL	08125	Airglas Engineering P.O. Box 1254 Anchorage, AK 99502
PA-22 Series; T.C. 1A6	SA60CE	Model 1800 floats installed, Pee-Kay. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-22 Series; T.C. 1A6	SA91AL	Change of brake system to disc type as used on PA-22-108 by changing brake parts.	AL	75500	Stoddard Aero SErvice 2550 East Fifth Avenue Anchorage, AK 99501
PA-22 Series; T.C. 1A6	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred H. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743
PA-22 Series; T.C. 1A6	SA143EA	Univair Aeromatic F-200H/0074E propeller on aircraft utilizing Lycoming O-320 or O-320-A1A engine.	EA	53160	George A. McIntosh 435 Van Cortlandt Park Avenue Yonkers, NY 10705
PA-22 Series; T.C. 1A6	SA145CE	APU receptacle under the right front seat to the right of battery box.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis, MO 63155
PA-22 Series; T.C. 1A6	SA157CE	Jump seat baggage compartments.	CE	14270	Baker's Flying Service, Inc. 1025 Lou Holland Drive Municipal Airport Kansas City, MO 64108
PA-22 Series; T.C. 1A6	SA247SO	Removal of door during operation of aircraft.	SO	43260	W.E. Huckabee, Jr. 424 South Green Street Thomaston, GA 30286
PA-22 Series; T.C. 1A6	SA314SO	Lycoming O-290-D engine.	SO	54450	M & M Flyers Bessemer, AL 35020
PA-22 Series; T.C. 1A6	SA447WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
PA-22 Series; T.C. 1A6	SA448CE	Prestolite ALK-5000 alternator.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
PA-22 Series; T.C. 1A6	SA461WE	Removal of right-hand door for parachute jumping and aerial photography operations.	NW	42138	Hillsboro Aviation Hillsboro, OR 97123
PA-22 Series; T.C. 1A6	SA481WE	Lycoming O-320-A1A engine and Sensenich M74DM propeller.	RM	47758	Kensair Corporation P.O. Box 332 County Airport Broomfield, CO 80020
PA-22 series; T.C. 1A6	SA666WE	Edo 88-1650 floats with Harrison oil cooler AP13SJ03-01 or AP12CU03-01, bottom engine cowl assembly 13159-8, side engine cowl 14237, reinforced fuselage 12480 and Sensenich M74DM or M76AM-2 propellers.	NW	36002	Floathaven Seaplane Base 2095 South Lake Whatcom Boulevard Bellingham, WA 98225
PA-22 Series; T.C. 1A6	SA819SW	Extended wing and fuselage.	SW	71776	Simpson Aviation Company P.O. Box 126 Gilliam, LA 71029

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22 Series; T.C. 1A6	SA1360CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, MO 66103
PA-22, PA-22-108, -135, -150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA1-604	Installation of Aerostat external power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
t+1 PA-22, -22-108 (Normal Category Only - All Models), -22-135, -150, -160; T.C. 1A6	SA45RM	Conversion from tri-cycle landing gear (nose wheel) to conventional landing gear (tail wheel). Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-22, PA-22-108, -135, -150, -160; T.C. 1A6	SA232GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-22, -22-108, -22-135, -22S-135, -22-150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA395GL	Installation of Aero Ski wheel in accordance with the following: 1) Model M180 and M2000 skis 2) Model M3000H skis. Issued 4/18/80.	GL	02750	Aero Ski Manufacturing Co., Inc. Box 346 Park Rapids, MN 56470
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA625AL	Install fiberglass wing tip assembly. Issued 3/27/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-22, -22-108, -22-135, -22-150, -22-160, -22S-150, -22S-160; T.C. 2A6	SA536AL	Installation of auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-22, -22-135, -150, -160; T.C. 1A6	SA26EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-108, -135, -22S-135, -22-150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA40EA	Wet-to-dry vacuum pump conversion kit 300-1. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-22, -22-108 (Normal Category only - all models), -22-135, -22-150, -22-160; T.C. 1A6	SA181RM	Installation of Lycoming Model O-360-A4A engine and Sensenich Model 76EM8-60 propeller. Issued 8/2/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-108; T.C. 1A6	SA847EA	Installation of Lycoming O-320-A (150 hp) or O-320-B (160 hp) engine. Amended 4/7/78.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-108, -135, -150, PA-23, -23-250, PA-24, -24-250, -260, -400, PA-28-140, -150, -160, -180, -235, PA-30; T.C. 1A6, 1A10, 1A15, 2A13, A1EA	SA1202WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
PA-22, -22-135; T.C. 1A6	SA1-274	Installation of Lycoming O-320 (150 hp) series engine and Sensenich M74DM propeller. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-135; T.C. 1A6	SA3-709	Install Piper control modification kit, P/N 754-174.	GL	51770	Richard E. Lloyd Lloyd Flying Service Schaumburg Airport, Box 79B Roselle, IL 60172
PA-22-108, -135, -150, -160 (landplane only - normal category only); T.C. 1A6	SA4-1263	Installation of conventional landing gear. Reissued and amended 12/4/79.	WE	52543	Lucas Aircraft 1125 Terrace Drive Napa, CA 94558
PA-22-150; T.C. 1A6	SA545AL	Installation of leading edge cuff. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-150; T.C. 1A6	SA703CE	Install aileron and wing fences and booster tips per STC SA573SW. Issued 5/19/70.	GL	22210	Dr. Edward W. Chrencik 29 9th Avenue North Hopkins, MN 55343
PA-22S-150; T.C. 1A6	SA297AL	Installation of McCauley 1A175 GM8241 propeller.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-22-160; T.C. 1A6	SA95NW	Installation of Lycoming O-360-A1A engine, McCauley 1A200-FA8248 propeller, and associates subsystems. Issued 3/11/74.	NW	61680	Northwest Aero Aircraft Services 2036 West Bakerview Road Bellingham, WA 98225
PA-22, PA-23, PA-24 Series; T.C. 1A6, 1A10, 1A15	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ 85642
PA-23 Series; T.C. 1A10	SA1-5	Unfeathering system change to HC-82XL-2/7636D-4 or HC-A2XL-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
PA-23 Series; T.C. 1A10	SA1-6	Unfeathering system change to HC-82XG-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
PA-23 Series; T.C. 1A10	SA1-28	Radio rack limited to 30 pounds of radio equipment.	GL	03600	Airborne Communications, Inc. Lunken Airport Cincinnati, OH 45275
PA-23 Series; T.C. 1A10	SA1-53	Conversion to Goodyear 6.50-8 wheels (9531319) and brakes (9531779).	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-103	Radio-shelf.	GL	72494	Skyways, Inc. P.O. Box 175 Vandalia, OH 45377
PA-23 Series; T.C. 1A10	SA1-117	Propeller anti-icing kit.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA1-120	F-300 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
PA-23 Series; T.C. 1A10	SA1-137	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA1-169	Reinforcement of floor structure between fuselage station 91-1/2 and 123-3/4 and provision for tie-down facilities.	GL	60485	A.E. Muhlhauser 1602 Emerson Avenue (N.C.H.) Cincinnati, OH 45275
PA-23 Series; T.C. 1A10	SA1-177	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-399	Oil-free vacuum PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-23 Series; T.C. 1A10	SA1-468	Six or 13 quart propeller anti-icing kit WAP-101A, revision 2.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA1-484	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-485	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA1-534	Lightweight reservoir type deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-548	SP-3 autopilot EB2597034.	EA	74590	Sperry Rand Corporation MacArthur Field Ronkonkoma, NY 11779
PA-23 Series; T.C. 1A10	SA1-586	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-23 Series; T.C. 1A10	SA3-94	Narco 1016 antenna and/or remote compass transmitter, equipment shelf, oxygen bottle mounting.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705
PA-23 Series; T.C. 1A10	SA3-158	Radio power pack on bulkhead forward of instrument panel.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705
PA-23 Series; T.C. 1A10	SA3-334	Installation of aerial camera provisions. Reissued 1/31/80.	SW	28230	Cooper Airmotive Aircraft Services 3300 Love Field Drive Dallas, TX 75235
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-handy hydrotrim aileron trim device.	GL	30465	Kingsley A. Doutt 115 West Maple Street Alpena, MI 49707 AND
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-hand hydrotrim aileron trim device.	GL	64262	Charles L. Petch Hubbard Lake, MI 49747
PA-23 Series; T.C. 1A10	SA3-509	L-2B autopilot with or without altitude control and approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-23 Series; T.C. 1A10	SA3-564	Propeller unfeathering accumulator.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA3-641	Cabin air temperature control system.	GL	82500	Vap-Air Division Vapor Corporation 6444 West Howard Street Chicago, IL 60607
PA-23 Series; T.C. 1A10	SA3-644	Adams Rite 2302 rev. C-2 handle on inside of cabin door.	CE	65301	Product Development Group 2522 East Douglas Wichita, KS 67202
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers and increase gross weight to 3,684 lbs.	CE	56868	Galen D. Means 847 Watson Lane Wichita, KS 67201
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers and increase gross weight to 3,684 lbs.	SW	67016	AND Jackson M. Reed 607 North Peters Norman, OK 73069
PA-23 Series; T.C. 1A10	SA4-299	Windows at station 144.	WE	39877	Hamilton Aircraft Company, Inc. 6501 South Park Avenue Tucson, AZ 85706
PA-23 Series; T.C. 1A10	SA4-345	"B" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-23 Series; T.C. 1A10	SA4-522	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA4-652	Full flow aerofilter kit 3-1A101.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-23 Series; T.C. 1A10	SA4-783	Lycoming 150 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-23 Series; T.C. 1A10	SA4-994	Installation of Firestone Model DPA-233 wheel assemblies, Model CPA-299 brake assemblies and 6.50x6 6-ply tires.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1016	Lycoming 160 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA4-1131	SP-3 autopilot, less altitude and navigation hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85000
PA-23 Series; T.C. 1A10	SA4-1166	Installation of Firestone Model DFA-180 wheel.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1602	Dorsal fin.	RM	60280	Mountain States Aviation, Inc. Stapleton Field Denver, CO 80202
PA-23 Series; T.C. 1A10	SA2WE	Fuel pressure warning lights.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
PA-23 Series; T.C. 1A10	SA47CE	Governor 210413.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA65EA	One Aerojet-General 15NS-250 aircraft rocket engine on underside of fuselage on airplane centerline aft of main spar wing and relocation of cabin air intake scoop assembly.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361
PA-23 Series; T.C. 1A10	SA69SW	Extended nose with baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA100SW	Automatic pilot AK114.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA114SW	Combustion monitor.	EA	60100	Monitair Corporation Ramapo Valley Airport Spring Valley, NY 10977
PA-23 Series; T.C. 1A10	SA140SW	Cabin window addition.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA172EA	Reinforcement of rearmost seat and installation of additional safety belt.	EA	16804	Walter E. Hoffman, Jr. Birchwood Lodges & Cottages East Stroudsburg, PA 18301
PA-23 Series; T.C. 1A10	SA202SO	Fyr-Fyter 23-4, 2 1/2 lb., dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA219EA	Installation of Katz integrated flight indicator Model KIFI-2 or KIFI-2A. Amended 5/21/69.	NE	36300	Forest City Aviation Services, Inc. 749 Congress Street Portland, ME 04102
PA-23 Series; T.C. 1A10	SA226EA	Added structure aft of cabin area.	EA	67000	Reding Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23 Series; T.C. 1A10	SA232EA	Installation of Tactair omni lock Model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair model omni lock Model OL-1). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA242SO	Two-place couch.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA243EA	13-quart propeller anti-icing kit WAP-102.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA244SO	PA-23-250 wing root and nacelle fairings.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA250WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA266SO	Modification of fuel cap 16097-00 by making a new cover and enlarging the lower vent hole. Rework fuel cell filler neck door 19049-06 by putting a spring loading vent in the door to be used as auxiliary vent during icing conditions.	SO	12700	Avco Corporation Aerospace Structures Division Nashville, TN 37202
PA-23 Series; T.C. 1A10	SA268WE	Sixth seat and emergency exit.	WE	60095	Monarch Aviation Associates P.O. Box 527 Monterey, CA 93940
PA-23 Series; T.C. 1A10	SA260SW	Forward fuselage section and long nose 30542-02.	SW	79794	Tulsa Airmotive, Inc. P.O. Box 176 Broken Arrow, OK 74012
PA-23 Series; T.C. 1A10	SA309WE	Non-icing fuel tank vents.	WE	06750	Aircraft Tank Service, Inc. 1201 Cohasset Street Burbank, CA 91504
PA-23 Series; T.C. 1A10	SA311SW	Alternate static source.	SW	71800	Sinclair Oil & Gas Company Aviation Department, Box 521 Tulsa, OK 74101
PA-23 Series; T.C. 1A10	SA319EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA337EA	Conversion of aircraft electrical system to 24 volt.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23 Series; T.C. 1A10	SA339SW	Electrical hydraulic pump. Reissued 9/20/77.	SW	90142	The Zee Company, Inc. 123 Braniff Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA363SW	Pitch trim system AK128.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA371SW	Fiberglass nose cone.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA372EA	Automatic flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-23 Series; T.C. 1A10	SA376WE	Left and right third window.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA387WE	Sixth seat and escape hatch.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA394WE	Replacement engine nose cowls.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA395WE	Lycoming O-360-A1A engines and Hartzell HC-C2YK-2R/7666-2 propellers.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA412WE	One-piece windshield.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA417SW	Rear baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA423SW	Fiberglass landing gear doors.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA461SW	Ramshorn type control wheel.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA462SW	One-piece windshield.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA463SW	Landing gear wheel well doors.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA465SW	Pitch trim system AK148.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA471CE	Dorsal fin.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23 Series; T.C. 1A10	SA476SW	Pitch trim system AK151.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA484SW	Large baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA497SW	Fiberglass engine nose cowl.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA498SW	Dual brakes.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA499SW	Engine nacelle and fuselage wing root fairings.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA504WE	11016 fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA523SW	Automatic trim system AK165.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA539WE	Turbosupercharged Lycoming IO-540-C1B5 or -C1C5 engine. Amended 6/14/66.	WE	66250	Rajay Corporation 2062 East Wardlow Raod Long Beach, CA 90807
PA-23 Series; T.C. 1A10	SA540SW	Piper auto-control III Model AK162 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA551WE	Installation of Brittain Model B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA557SW	Fiberglass nose cone.	SW	44930	J & G Aero Company P.O. Box 3031 Tyler, TX 75701
PA-23 Series; T.C. 1A10	SA566SW	AK184 automatic flight system, AK185 stabilizer, and AK188 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA574SW	Rear baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA580SW	Modified engine mounts.	SW	67650	RFB Company, Inc. Chandler Field Purcell, OK 73080
PA-23 Series; T.C. 1A10	SA590SW	Gross weight increased.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA597SW	Extended nose with baggage compartment. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA598SW	Wheel well doors. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA599SW	Fiberglass engine nose cowls.	SW	59500	James W. Miller 6517 Moss Oak San Antonio, TX 78229

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA600SW	Nacelle and wing root fairings. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA605SW	Rear baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA612SW	Square wing tips. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA613SW	Dorsal fin and square tip fin and rudder. Amended 7/31/68.	SW	50500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA614WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA615WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A0	SA616WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA617WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA636SW	Modified nose, gear doors, nacelle fairings, and wing tips.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA671SW	Dorsal fin and square rudder.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA697SW	One-piece windshield. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA698SW	Rear picture window.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78114
PA-23 Series; T.C. 1A10	SA747SW	Pitch trim AK228 (manual).	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA764WE	Aztec "B" nose section.	RM	08315	Airport Development Corp. 5120 West Rowland Avenue Littleton, CO 80120
PA-23 Series; T.C. 1A10	SA774SW	Franklin 64-350-C1 engines, McCauley 2AF31C10/84SF-8 propeller increase gross weight 3675 lbs. takeoff, 3500 lbs. landing. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA803SW	Dual brakes. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA824WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA852WE	Turbosupercharged Lycoming O-540-A1B5, -A1D5, or -A3D5 engines (S/N's 27-1 thru 27-2504).	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA867SW	Lycoming O-540-A1D5 engines.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA882EA	Installation of supplemental strobe light Grimes P/N 30-0437-100. Amended 5/2/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23 Series; T.C. 1A10	SA909WE	Turbosupercharged Lycoming IO-540-J4A5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA953SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23 Series; T.C. 1A10	SA978WE	Turbosupercharged Lycoming IO-540-C4B5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA1076CE	Installation of Halon 1301 cabin fire extinguishing system and engine nacelle fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64105
PA-23 Series; T.C. 1A10	SA1348WE	B-4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA1480WE	Installation of an integral 24 gallon auxiliary fuel tank in each wing tip.	WE	58500	Met-Co-Aire 3848 Campus Drive Newport Beach, CA 92660
PA-23 Series; T.C. 1A10	SA1486WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA2914WE	Installation of improved rudder trim tab actuating rod. Issued 8/13/74.	WE	13800	Aviation Research Corporation P.O. Box 718 Santa Ynez, CA 93460
PA-23, -23-160; T.C. 1A10	SA4-1637	Installation of turbosupercharged Lycoming O-320-A or -B series engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23, -23-160; T.C. 1A10	SA2CE	Installation of Doyn Model 1600 dorsal fin. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23, PA-23-160; T.C. 1A10	SA285CE	Lycoming IO-360-B1B engines and Hartzell HC-C2YK-2RA/7666A-2 propellers. Gross weight increase to 3,684 lbs. on PA-23 and to 4,000 lbs. on PA-23-160. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23, -23-160; T.C. 1A10	SA802CE	Alter tip of vertical fin and rudder. Amended August 1976.	CE	60174	J.J. Morelli Route 1, Box 138 Platte City, MO 64079
PA-23, -23-160; T.C. 1A10	SA897SW	Fiberglass propeller spinners. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA898SW	Revised engine cowling. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA1260WE	Installation of turbosupercharged Lycoming O-360-A1A or A1D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23, -23-160; T.C. 1A10	SA1306SW	Lycoming IO-360-C1C engines with Hartzell HC-C2YK-2/C7666A-4 propellers with gross weight increase. Issued 5/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23, -23-160; T.C. 1A10	SA2793SW	Rudder hinge reinforcing bracket. Issued 6/7/78.	SW	70750	Seguin Aviation, Inc. 2075 Highway 46 Seguin, TX 78155
PA-23, -23-160; T.C. 1A10	SA3099SW-D	Mitchell automatic flight system AK587 consisting of Century I autopilot with optional omni tracker. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3100SW-D	Mitchell automatic flight system AK588 consisting of Century III with optional radio coupler and glide slope coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3101SW-D	Mitchell automatic flight system AK586 consisting of Century IIB autopilot with optional radio coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23, -23-160, -23-235, -23-250, PA-24, -24-250, -24-400, PA-28-150, -28-160, -28-180, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, PA-23-235, PA-23-250; T.C. 1A10	SA136EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, -235, -250; T.C. 1A10	SA236CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-23, -23-160, -23-235; T.C. 1A10	SA317EA	Radome kit No. 2025K-B for Bendix RDR-100 or RDR-110 series radar systems with 12-inch antenna per Chamberlain installation. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23, -23-160, -235, PA-25; T.C. 1A10	SA362SW	Rear baggage compartment. Reissued 4/24/79.	SW	70750	Seguin Aviation 2075 Highway 46 Seguin, TX 78155
PA-23, -160, -235; T.C. 1A10	SA398CE	Install Hoskins twilighter Mk III supplemental lighting system consisting of Model F wing lights with Model P or K (dual) tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
PA-23, 23-160, 23-235, 23-250; PA-24, -24-250, -260, -400; PA-31, -31P; T.C. A8EA, 1A10, 1A15	SA660WE	Installation of HRD-type fire extinguishing system. Amended 7/11/77.	WE	43190	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91015
PA-23, -160, -235; T.C. 1A10	SA894SW	Nacelle saddleback. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23-160, -235, -250; PA-30, PA-39; T.C. 1A10, A1EA	SA890EA	Installation of Grimes three light strobe kit P/N 34-0101-2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23, -23-160, -23-235, -23-250, -E23-250, PA-24, -24-250, -24-260, -24-400, PA-28-140, -28-150, -28-160, -28-180, -28-235, -28S-160, -28S-180, -28R-160, -28R-200, PA-30, PA-39, PA-32-260, -32-300, -32S-300, PA-30, PA-39; T.C. 1A10, 1A15, 2A13, A1EA, A3SO	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light system two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 11/30/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23, -160, -235, -250; PA-24-180, -250, -400; *PA-28-140, -150, -160, -180, -235; *PA-31; T.C. 1A10, 2A13, A8EA	SA1290WE	Installation of "Quazar" high intensity supplemental exterior flashing lights. Amended 11/25/69. *Approved anti-collision light system is required.	RM	66000	Radair, Inc. 5665 South Curtis Street Littleton, CO 80120
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327 AND
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SW	67016	Jackson M. Reed 607 North Peters Street Norman, OK 73069
PA-23-160; T.C. 1A10	SA47SO	Installation of one-piece instrument panel.	SW	68145	Riley International Corporation 6211 West Northwest Highway Dallas, TX 75225
PA-23-160; T.C. 1A10	SA68NW	Installation of cargo door on right side of fuselage. Issued 10/30/73.	SO	70280	Elbridge P. Sawyer P.O. Box 148 Dayton, OH 37321
PA-23-160, -235, -250; T.C. 1A10	SA162SW	Cabin emergency exit window and sixth seat. Reissued 10/3/78.	SW	70750	Seguin Aviation, Inc. 2075 Highway 46 Seguin, TX 78155

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-160; T.C. 1A10	SA272CE	Installation of Lycoming IO-360-B1A engines and Hartzell HC-C2YK-2RA/7666A-2 propellers. Gross weight increase to 4000 lbs. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-235; T.C. 2A10	SA1136SW	Fiberglass fuselage shell.	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
PA-23-235; T.C. 2A10	SA1205SW	Manual electric trim AK268. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235; T.C. 2A10	SA1746WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23-235; T.C. 2A10	SA1847WE	Installation of Brittain up-command signal adapter kit. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23-235, -250; T.C. 1A10	SA495CE	Installation of Hartzell Model HC-A3XK-2B/7636D-4 three-bladed propellers.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23-235, PA-23-250; T.C. 1A10	SA530WE	Installation of Rajay turbosupercharged Lycoming IO-540-C1E5 or C1C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23-235, -23-250; T.C. 1A10	SA1315SW	Dorsal fin. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-235, -23-250; T.C. 1A10	SA1361CE	Chrome plated brake disc installation. Issued 3/6/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA155EA	Install B.F. Goodrich pneumatic de-icing system. Amended 8/10/79.	GL	38500	B.F. Goodrich Engineered Systems Company 500 South Main Street Akron, OH 44318
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA921SW	Mitchell automatic flight system AK242 consisting of Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1091SW	Mitchell automatic flight director system FD/AP 282-184 consisting of flight director, automatic pilot, auto-flite AK 185.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport
PA-23-235, -23-250, -E23-50, Serial Nos. 27-1 thru 27-4573; T.C. 1A10	SA1124EA	Installation of enlarged cargo door. Reissued 8/25/78.	EA	26683	Courtesy Air Service, Inc. P.O. Box 561 Warren County Airport Glen Falls, NY 12801
PA-23-235, -23-250 (S/N 271 thru 27-7554172), PA-E23-250 (S/N 27-2505 thru 27-7554172), PA-23-250 (Model "F") (S/N 27-7654001 and up); T.C. 1A10	SA1126EA	Installation of DeVore tel-tail lights on upper surface of stabilator. Reissued 9/28/78.	EA	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1262SW	Mitchell automatic flight system FD282-242 consisting of flight director/autopilot, and automatic pitch trim. Issued 2/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1276SW	Mitchell automatic flight system AK332, consisting of Piper autoflite II and omni tracker system. Issued 3/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1377SW	Mitchell automatic flight system AK340, consisting of Century I and optional tracker. Issued 10/14/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA2442WE	Installation of dual hydraulic pump (New Eastern Industries hydraulic pump 1233-HnG Type 311 on right engine; pump 1233-HnG Type 311 in lieu of existing pump on left engine). Amended 3/29/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, 23-250, PA-E23-250;	SA2445WE	Installation of recontoured inboard wing leading edge, stall fences, drooped ailerons in flaps down mode, rudder anti-servo tab system, and optional raked wing tips. Issued 11/16/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA3133SW-D	Mitchell automatic flight system AK599, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/7/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA3137SW-D	Mitchell automatic flight system AK611 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, -250; PA-24, -24-250, -260; PA-25, -25-235, -25-260; PA-28-150, -28-160, -28-180, -28-235; T.C. 1A10, 1A15, 2A8, 2A13	SA693CE	Replace existing engine induction air filter with AC Spark Plug Division filter.	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
PA-23-250; T.C. 1A10	SA11NE	Installation of laser sensor system. Issued 10/31/75.	NE	33485	Environmental Research and Technology, Inc. 696 Virginia Road Concord, MA 01742
PA-23-250; T.C. 1A10	SA39RM	Installation of freon air-conditioning system. Issued 4/23/75.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-23-250; T.C. 1A10	SA164CE	Installation of Hartzell HC-A3XK-2B/7636D-4 propellers and C-2513-2P spinners. Reissued 3/9/78.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-250; T.C. 1A10	SA179CE	Installation of the following: Lycoming IO-540-A1A5 or IO-540-G1A5 engines, Hartzell HC-A3XK-2C/8433-10 or HC-A3XK-2B/7636D-4 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-250; T.C. 1A10	SA205GL	Installation of Aerosonic totalize fuel flow indication system in lieu of fuel pressure gages. Issued 12/19/77.	GL	73190	Roger Smith Aircraft Sales, Inc. Aurora Municipal Airport Sugar Grove, IL 60554
PA-23-250; T.C. 1A10	SA335CE	Installation of Honeywell H-14 YG-391 autopilot. Amended 9/9/66.	GL	42250	Honeywell, Inc. East 70th & 34th Avenue South Wold-Chamberlain Field Minneapolis, MN 55450
PA-23-250; T.C. 1A10	SA429SO	Installation of Bendix Model FCS-80 automatic flight control system with manual electric pitch trim and flight director indicator. Amended 6/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA441NW	Installation of 3-bladed propeller and Piper Navajo spinner. Amended 1/12/78.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
PA-23-250; T.C. 1A10	SA480EA	Installation of photographic equipment.	NE	71400	James W. Sewall Company 147 Center Street Old Town, ME 04468
PA-23-250; T.C. 1A10	SA497SO	Installation of Bendix WLS-880 wings leveler system with and without Bendix FCS-810 automatic flight control system. Issued 11/8/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA590SO	Installation of M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250; T.C. 1A10	SA591SO	Installation of Bendix RNS-3400 area navigation system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250 (S/N 27-2505 and up): T.C. 1A10	SA621EA	Installation of a U.S. mail cargo kit. Amended 4/15/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23-250 (Aztec C, I, E): T.C. 1A10	SA663CE	Installation of Goodyear ice-guard de-icing kit Nos. 320-642. Reissued 4/17/72.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA667CE	Installation of wing and empennage deicing boot. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA668CE	Installation of wing and empennage deicing all weather antenna. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA688CE	Installation of propeller unfeathering system. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capitol Airport Springfield, IL 62705
PA-23-250; T.C. 1A10	SA850EA	Installation of radome kit 4025KX. Amended 9/12/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250; T.C. 1A10	SA922SO	Installation of Piper PA-23-250 "E" model fuselage nose. Amended 6/30/77.	SO	41400	Hawthorne Aviation Municipal Airport P.O. Box 10005 Charleston, SC 29411
PA-23-250 (Aztec F) defined by item VI in TCDS 1A10; T.C. 1A10	SA952SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA1022CE	Installation of King Model KGS-55 pictorial navigation system (compass), with optional KA-52 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1027CE	Installation of KCS-55 pictorial navigation system (compass), with optional KA-57 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250 (Landplanes) (S/Ns 27-2505 thru 27-74-05471); T.C. 1A10	SA1063CE	installation of two Hartzell HC-E3YR-2AF/FC7663-2R propellers and C-3269A or 82D3273P spinners. Reissued August 1976.	SW	03034	AeroStol Company 5104 Rector Fort Worth, TX 76133
PA-23-250; T.C. 1A10	SA1102CE	Installation of AP-107, 2-axis autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250; T.C. 1A10	SA1103CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250; T.C. 1A10	SA1163CE	Installation of KFC-200 automatic flight control system. Amended 6/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1314SW	Fiberglass extended nose. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-250; T.C. 1A10	SA1390CE	Install 1/4-inch plywood flooring over existing floor, remove 4 passenger seats, install reinforcement tubing. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250; T.C. 1A10	SA1391CE	Cutting and reattaching the left and right lower engine cowling with AN 2700-4 cam locks. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250 (S/N 27-2505 and up): T.C. 1A10	SA1444WE	Installation of Edo Model 679-4930 floats and addition of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250; T.C. 1A10	SA1554CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1810WE	Installation of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663
PA-23-250; T.C. 1A10	SA3209SW-D	Mitchell automatic flight system, Piper altimatic X autopilot, AK684 or AK684FD, Piper altimatic X flight director autopilot with remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, Serial Nos. 27-2000 and up; T.C. 1A10	SA3823WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-23-250 (S/Ns 27-2000 and up), -E23-250; T.C. 1A10	SA619EA	Installation of radome kit 3061K for Bendix RDR-100 or RDR-110. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-23-250, -E23-250; T.C. 1A10	SA20GL	Installation of Woodward electronic propeller synchronizer system. Amended 11/6/75.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA25GL	Installation of propeller unfeathering accumulator system on light twin-engine airplanes. Issued 6/26/73.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA51GL	Install Foster Airdata Systems, Inc. AD611/D area navigation system per STC. Reissued and amended 2/20/79.	GL	36520	Foster Airdata, Inc. 7020 Huntley Road Columbus, OH 43229
PA-23-250, -E23-250; T.C. 1A10	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 40355
PA-23-250, -E23-250 with counterweighted props, PA-31, PA-32-260, -31-325, -31-350, T.C. 1A10, A20SO, A3SO	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 1/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA430EA	Installtion of radome kit No. 3061X. Amended 11/12/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250, S/N 27-2000 and up, -E23-250; T.C. 1A10	SA1162EA	Installation of Silver Instruments fueltron IIIG or IIID digital fuel flow and totalizer system. Amended 4/2/80.	WE	71740	Silver Instruments 2346 Stanwell Drive Concord, CA 94520
PA-23-250, -E23-250; T.C. 1A10	SW1524SW	Mitchell automatic flight system AK371 consisting of altimatic IIIB-1 autopilot with optional command/electric trim system with radio and glide slope couplers. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1571SW	Mitchell automatic flight system AK382 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 12/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1653SW	Mitchell automatic flight system AK372 consisting of AutoFlite II with optional tracking system. Issued 5/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3002SW-D	Automatic flight system AK479 consisting of Piper altimatic IIIC autopilot with optional command/automatic electric elevator trim servo altimeter, radio coupler, and glide slope coupler. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250, -E23-250; T.C. 1A10	SA3003SW-D	Automatic flight system AK477 and AK477FD consisting of Century IV autopilot and Century IV flight director autopilot with command/automatic electric trim, and optional annunciator panel and servoed altimeter. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3005SW-D	Automatic flight system AK506 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3006SW-D	Automatic flight system AK494 and AK494FD consisting of Century IV autopilot and Century IV director autopilot and command/automatic electric elevator trim and optional annuciator panel. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3007SW-D	Automatic flight system AK504 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim, radio coupler, glide slope coupler. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3027SW-D	Mitchell command/electric trim system AK562. Issued 10/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3104SW-D	Mitchell automatic flight system AK583, consisting of Century IIB autopilot with optional radio coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3290WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/8/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA195EA	Installation of Goodrich Electrothermal propeller de-icing system kit 77-170. Amended 10/27/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Co. 500 South Main Street Akron, OH 44318
PA-23-250 (S/N 27-2000 and up), PA-E23-250; T.C. 1A10	SA430EA	Installation of radome kit 3061X. Reissued 4/21/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA840WE	Installation of Rajay Turbosupercharged Lycoming IO-540-C4B5 or -C4C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23 Series, PA-24 Series; T.C. 1A10, 1A15	SA230CE	Airspeed indicator landing gear warning system.	CE	74923	Standard Precision, Inc. 4105 West Pawnee Wichita, KS 67202
PA-23, PA-24, PA-28 Series; T.C. 1A10, 1A15, 2A13	SA148SW	Replacement of right front seat with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, AR 72003
PA-23, PA-24, PA-28, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA662WE	Hi-Lo sensitivity adaptor BI-400, and autopilot with NAV-1 navigation coupler and heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23, PA-24, PA-30 Series; T.C. 1A10, 1A15, A1EA	SA188SO	Flight control wheel.	SO	37086	Garcia Aviation Company 13010 SW 82nd Avenue Road Miami, FL 33156
PA-23, PA-25, PA-26 Series; T.C. 1A10, 1A15, 2A8, 2A10	SA4-1501	AB-6562 and AB-6563 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-23, PA-30, PA-31, PA-34, PA-39 Series; T.C. 1A10, A1EA, A8EA, 1E10	SA1675WE	Installation of exhaust gas temperature monitoring systems EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24 Series; T.C. 1A15	SA1-340	Oil-free vacuum pump PA-201.	GL	11880	Associated Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-24 Series; T.C. 1A15	SA1-544	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voornis Lane Hackensack, NJ 07601
PA-24 Series; T.C. 1A15	SA3-309	L2-B autopilot with or without altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA3-315	Arcon B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA3-351	L-2B autopilot with optional altitude control and automatic approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA4-572	Autopilot and optional navigation coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA4-666	Grimes D-7080-1-12 rotating beacon.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-24 Series; T.C. 1A15	SA4-852	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-24 Series; T.C. 1A15	SA4-955	Fiberglass vertical fin mount for either Grimes or Whelen WRM rotating beacons.	NW	85550	Art Whitaker Pearson Airpark Vancouver, WA 98660
PA-24 Series; T.C. 1A15	SA4-956	Three seat belts to accommodate three persons or rear seat.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-971	20-gallon auxiliary fuel tank in baggage compartment.	WE	77260	Symons Engineering P.O. Box 90002 Airport Station Los Angeles, CA 90009
PA-24 Series; T.C. 1A15	SA4-1032	Aerofilter 30409A full flow lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-24 Series; T.C. 1A15	SA4-1132	SP-3 autopilot, less altitude and navigation-hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85027
PA-24 Series; T.C. 1A15	SA4-1235	Installation of Brittain 15-gallon wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA4-1248	Fuel drain modified to incorporate a handle extending forward through front bulkhead.	WE	14960	Bates Aviation, Inc. 1026 East 120th Street Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-1351	Installation of wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA2SO	Fifth passenger seat.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA18SO	Cockpit operated fuel drain valve.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA48WE	Belly-mounted rotating anti-collision light to supplement top fuselage-mounted standard rotating light.	WE	75250	Stits Aircraft Company P.O. Box 3084 Riverside, CA 92502
PA-24 Series; T.C. 1A15	SA59SW	Piper altimatic pilot AK089 or AK089R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24 Series; T.C. 1A15	SA74SW	Quick door release mechanism.	SW	69207	Ross Aviation, Inc. R.F.D. 5, Riverside Airport Tulsa, OK 74101
PA-24 Series; T.C. 1A15	SA112CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155
PA-24 Series; T.C. 1A15	SA113CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155
PA-24 Series; T.C. 1A15	SA160SW	Automatic pilot AK115, AK115E or AK115E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24 Series; T.C. 1A15	SA203SO	Fyr-Fyter 23-4, 2-1/2 pound, dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-24 Series; T.C. 1A15	SA315SW	Fabrication and installation of split rear seat back.	SW	71365	Seven Bar Flying Service, Inc. 10001 Coors Road, NW Albuquerque, NM 87101
PA-24 Series, T.C. 1A15	SA341CE	SAGA (semi-automatic gear actuator) control system. Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
PA-24 Series; T.C. 1A15	SA362WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA478EA	SAGA (semi-automatic gear actuator) system.	GL	43750	In-Flight Devices Corporatin 4885 Sawyer Road International Airport Columbus, OH 43219
PA-24 Series; T.C. 1A15	SA482WE	Plastic wing tips replaced with "Speedplates".	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
PA-24 Series; T.C. 1A15	SA510CE	Modify electrical system to combination 12/24 volt system for starting engine.	EA	12700	Avco Lycoming Division Avco Corporation Williamsport, PA 17701
PA-24 Series; T.C. 1A15	SA511WE	Lycoming O-540-B1B5 engine, Hartzell HC-A2XK-1/8433-7 propeller required.	WE	46790	Johnston Aircraft Service P.O. Box 757 Tulare, CA 93274
PA-24 Series; T.C. 1A15	SA553WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA598EA	Installation electronic voltage alarm, Drawing No. 80107.	EA	53500	McKinley Engineering Corp. P.O. Box 275 Palisades Park, NJ 07650
PA-24 Series; T.C. 1A15	SA871WE	Fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-24 Series; T.C. 1A15	SA881EA	Installation of Grimes 30-0437-1 anti-collision strobe light kit, P/N 34-0200-1. Amended 5/2/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-24 Series; T.C. 1A15	SA891WE	Toe brakes.	RM	12540	Atlas Aviation, Inc. 8505 Montview Boulevard Denver, CO 80202
PA-24 Series; T.C. 1A15	SA904WE	Hanlon and Wilson exhaust system, 637-129.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA1109WE	Hanlon and Wilson exhaust system.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA1605WE	Installation of Brittain B-4A flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24-180; T.C. 1A15	SA4-3151	Wing tip fuel tanks installed. Amended 1/10/69.	WE	17492	Brittain Industries, Inc. 2700 Skypark Drive Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24-160; T.C. 1A15	SA127EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-24(-180), -24-250, -24-260, -24-400; T.C. 1A15	SA208GL	Installation of one piece windshield. Issued 1/23/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-24, PA-24-250, -260, -400; T.C. 1A15	SA270GL	Installation of forward windows, P/N's W-, W/T-, WG-2058-187 or -250 and W-, W/T-, W/G-2059-187 or -250. Issued 10/2/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-24, -24-250; T.C. 1A15	SA3074SW-D	Mitchell automatic flight system AK547 consisting of Century I autopilot with optional omni tracker. Issued 10/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, 24-250, -260; PA-28, 28-140, -150, -160, -180, -235; PA-30; PA-32-260, -300; T.C. 1A15, 2A13, A1EA, A3SO	SA808SW	Installation of Mitchell Model AK246 omni tracker. Applicable only to aircraft modified by STCs SA511SW, SA532SW, SA581SW, SA662SW, SA707SW.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -260, -400; T.C. 1A15	SA891SO	Remove existing windshield and install single piece windshield. Amended 4/27/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260; T.C. 1A15	SA1315CE	Chrome-plated brake disc installations. Issued June 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA1706SW	Portable solid oxygen system. Issued 7/27/73.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3070WE	Installation of single piece windshield. Issued 7/23/75.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-24, -24-250, -24-400; T.C. 1A15	SA2495WE	Installation of recontoured wing leading edge, stall fences, drooped ailerons in flaps-down mode, flap-actuated stabilator trim system, optional new wing tips, optional SC-100 stall warning system. Issued 3/27/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250; PA-28-160; T.C. 1A15, 2A13	SA2654WE	Installation of Pathfinder P2A autopilot system. Reissued 5/31/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; T.C. 1A15	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260, PA-30; T.C. 1A15, A1EA	SA3045SW-D	Automatic flight system AK519 consisting of Century IIB autopilot with optional radio coupler. Issued 3/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3565WE	Installation of single piece windshield. Issued 1/20/76.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-24, -24-250, -24-260; T.C. 1A15	SA3776WE	Installation of flexible stainless steel oil cooler hoses. Issued 11/1/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-24-250; T.C. 1A15	SA5-27	Remove Lycoming O-540-A1A5 (250 hp) engine and install Lycoming O-540-B1B5 (235 hp) engine. Revised 3/3/62.	AL	63845	Peninsula Airways, Inc. P.O. Box 110 Naknek, AK 99633
PA-24-250; T.C. 1A15	SA811WE	Installation of turbosupercharged Lycoming IO-540-C1B5 or C1C5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24-250; T.C. 1A15	SA3451WE	Installation of Hartzell HC-A3VK4/V7636D-0 constant speed propeller. Issued 7/13/77.	WE	00270	A & P Propeller and Parts Gillespie Airport Plaza 8404 Magnolia Avenue Santee, CA 92071
PA-24-250, -24-260; T.C. 1A15	SA3684WE	Installation of an air/oil separator. Issued 7/19/78.	WE	80396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
*PA-24-250, *-24-260; T.C. 1A15	SA3773WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79. *This installation limited to those aircraft with fuel injected engines.	WE	71740	Silver Instruments, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-24-250, 24-260, PA-30; T.C. 1A15, A1EA	SA1027SW	Manual electric pitch trim AK267.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA893SO	Installation of exhaust silencers. Issued 4/22/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24-260 (S/Ns 24-4783 and 24-4804 and up); T.C. 1A15	SA1026SW	Piper automatic flight system Model AK186 consisting of altimatic IIIB autopilot, auto-flite, electric pitch trim, radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260 (S/N 24-4783, 24-4804 and up with IO-540 series normally aspirated engines; T.C. 1A15	SA1178EA	Installation of Silver Instruments fueltron IG digital fuel flow and totalizer system. Reissued 2/26/80.	EA	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-24-260; T.C. 1A15	SA1331SW	Mitchell automatic flight system AK326 consisting of Piper autoflite II and optional tracking system. Issued 6/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA1521SW	Mitchell automatic flight system AK393, consisting of Century I autopilot with optional omni tracker. Issued 10/17/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA2062WE	Installation of Lycoming IO-540-R1A5 engine and Rajay turbosuperchargers.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-260, -24-400; T.C. 1A15	SA31NW	Installation of Madras wing tips. Issued 3/13/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
PA-24-400; T.C. 1A15	SA2359WE	Installation of turbosupercharged Lycoming IO-720-A1A engine. Issued 6/1/71.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-400; T.C. 1A15	SA3134SW-D	Mitchell automatic flight system AK593 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-400; T.C. 1A15	SA3135SW-D	Mitchell automatic flight system AK597 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-400; T.C. 1A15	SA3136SW-D	Mitchell automatic flight system AK609 consisting of Century I auto- pilot with optional omni tracker. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-28; T.C. 1A15, 2A13	SA1485WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24, PA-30; T.C. 1A15, A1EA	SA313SW	Pitch trim system AK124.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA331SO	External power supply plug.	SO	60120	Montgomery Aviation Corporation P.O. Box 92 Montgomery, AL 36100

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24, PA-30; T.C. 1A15, A1EA	SA466SW	Pitch trim system AK147.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA475SW	Pitch trim system AK152.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA524SW	Pitch trim system AK168.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA525SW	Piper autocontrol III, Mitchell AK161 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA581SW	Stabilizer AK179.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A15EA	SA662SW	Automatic flight system 220.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA756SW	AK236 automatic flight system with Century II autopilot, optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-25 Series; T.C. 2A8, 2A10	SA4-1592	Spray equipment.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA157SO	Air-oil type main landing gear shock absorber.	SO	64665	Piper Aircraft Corporation Vero Beach, FL 32960
PA-25 Series; T.C. 2A8, 2A10	SA168WE	Installation of Agavenco P/N 1826 15-gallon additional capacity cell to Piper fiberglass spray tank. Amended 3/18/68.	WE	03250	Agricultural Aviation Engineering Company McCarran Airport Las Vegas, NV 89109
-25 Series; C. 2A8, 2A10	SA185WE	Electrical spray control valve.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA292SO	FrigiKing JC-1 air conditioner.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-25 Series; T.C. 2A8, 2A10	SA300SO	Auxiliary oil radiator.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-25 Series; T.C. 2A8, 2A10	SA512SW	Metal ribs and metal covering of wings.	SW	60168	Luther W. Moore 1110 West 29th Street Plainview, TX 79072
PA-25 Series; T.C. 2A8, 2A10	SA829WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-25, -25-235, -260; T.C. 2A10	SA915SO	Lower forward longeron reinforcement by adding tubing in trangle shape outboard between fore and aft wing spar root attach fittings and modifying wing root rib to fit over modified longeron. Issued 1/6/77.	SO	05966	Aircraft Service Center, Inc. Route 2, Tifton Airport Tifton, GA 31794
PA-25, -25-235, -260; T.C. 2A10	SA1180CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Gox 508 Renner Field Goodland, KS 67735
PA-25, -25-235, -260; T.C. 2A10	SA1294WE	Installation of automatic flagman. Amended 4/17/72.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362
PA-25, -25-235, -260; T.C. 2A10	SA1417WE	Installation of fiberglass wing tips. Amended 3/26/69.	NW	74750	Sportsman Airpark, Inc. P.O. Box 248 Newberg, OR 97132

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-25-235; T.C. 2A8	SA41RM	Installation of freon air-conditioning system. Issued 1/9/75.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-25-235; T.C. 2A8, 2A10	SA521WE	Swathmaster dust and spray attachment.	WE	79250	Transland Aircraft, Inc. 2923 190th Street Redondo Beach, CA 90277
PA-25-235; T.C. 2A8, 2A10	SA710CE	Install Compro Aviation rudder horn extension.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
PA-25-235; T.C. 2A8, 2A10	SA997WE	Installation of 180-gallon hopper tank. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-25-235; T.C. 2A10	SA1399WE	Installation of Shell 81-Flon spray system. amended 7/19/68.	NW	71770	Simplex Manufacturing Company 4224 Northeast 42nd Avenue Portland, OR 97218
PA-25-235; T.C. 2A10	SA1630SW	Revised exhaust system. Issued 5/5/73.	SW	53784	Karl D. McWilliams d/b/a K & C Aircraft Service Municipal Building Airport Frederick, OK 73542
PA-25-235, -25-260; T.C. 2A8	SA1316CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-25-235, -25-260; T.C. 2A8	SA1892WE	Installation of hydraulic system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton AVenue Harbor City, CA 90710
PA-25-235, -25-260; T.C. 2A8	SA368NW	Installation of outboard wing fuel tank with modified fuel pump system. Issued 10/19/76.	NW	03270	U.S.D.A. 3706 West Nob Hill Boulevard Yakima, WA 98902
PA-25, PA28-140, PA32-260; T.C. 2A8, 2A13, A3SO	SA693WE	Install AC induction air filter type AAF-104. Amended 4/26/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
PA-28 Series; T.C. 2A13	SA1-649	Lube oil filter PB55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
PA-28 Series; T.C. 2A13	SA8PC	Installation of baggage compartment kit IFC-BC-001 behind rear seats in the cabin.	PC	44810	Island Flight Center, Inc. 203 Lagoon Drive Honolulu, HI 96819
PA-28 Series; T.C. 2A13	SA100EA	AF-510, AF-512A or AF-512B autopilots.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005
PA-28 Series; T.C. 2A13	SA110SO	Electric pitch trim system.	SO	64665	Piper Aircraft Corporation Vero Beach, FL 32960
PA-28 Series; T.C. 2A13	SA180EA	Geared starter.	EA	79953	Turner Field, Inc. Prospectville, PA 19077
PA-28 Series; T.C. 2A13	SA164SW	Automatic pilot AK092E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA178WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-28 Series; T.C. 2A13	SA222SW	Hartzell HC-82XL-6N/7636D-4 propeller and cowl rework.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA224CE	A3000 main and NB1200 nose skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA236SW	Piper auto-control II automatic pilot AK085E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA246SW	Nose cowling modified.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA263EA	Modification of engine mount to permit use of Lord mounting kit J-10778-4.	EA	12700	Lycoming Division Avco Corporation Williamsport, PA 17701

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28 Series; T.C. 2A13	SA319CE	Model 2500 wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA369SW	Automatic pilot AK129, pitch trim system AK130, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA481SW	Removal of door for parachute jumping.	SW	37055	Ervin J. Fusilier 9617 Fulton Street Houston, TX 77002
PA-28 Series; T.C. 2A13	SA511SW	Stabilizer AK153.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA530SW	Automatic pitch trim system AK166.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA556SW	Constant speed propeller.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA601WE	Flight control system B-4 including pitch assist PC-1, altitude hold AH-1, and	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
PA-28 Series; T.C. 2A13	SA645WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA646WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA707SW	AD127 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA708SW	Plane booster safe flight wing tips 101-28.	SW	81250	Upper Valley Aviation, Inc. Harvey J. Ferguson McAllen, TX 78501
PA-28 Series; T.C. 2A13	SA880WE	New design fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-28 Series; T.C. 2A13	SA1191WE	Removal of baggage door for aerial photography operations.	RM	47725	Kelsey Ellis Air Service, Inc. Municipal Airport Salt Lake City, UT 84101
PA-28 Series; T.C. 2A13	SA1354WE	PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1469WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1470WE	Installation of Brittain Model PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28-140; T.C. 2A13	SA578EA	Installation of Monitair angle of attack/stall warning kit, P/N 9-92-1000. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140; T.C. 2A13	SA687SO	Installation of flight attitude alerting system. Amended 6/1/70.	SO	05350	Aircraft Instruments, Inc. 420 Lincoln Road, Suite 206 Miami Beach, FL 33139
PA-28-140; T.C. 2A13	SA913EA	Installation of Elano Corporation heater-muffler system. Issued 5/11/72.	GL	33200	Elano Corporation 2455 Dayton - Xenia Road Xenia, OH 45385
PA-28-140; T.C. 2A13	SA1189SW	Air circulator. Issued 9/15/70.	SW	83100	Ves-Kol 2805 National Drive Garland, TX 75040
PA-28-140; T.C. 2A13	SA1192EA	Instalation of Safe Flight (SFIC) SC-150 speed control system. Issued 4/15/80.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-140; T.C. 2A13	SA2052WE	Installation of Hartzell HC82XL-6F/8433-12 propeller (after conversion of engine to Lycoming O-320-E1A model).	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-140; T.C. 2A13	SA2325WE	Replacement of Station 140.6 vinyl bulkhead panel with fiberglass baggage compartment. Issued 3/19/71.	WE	21000	Chaffee Aircraft Service Corp. 2105 Valley Boulevard Colton, CA 92324
PA-28-140; T.C. 2A13	SA2706SW	Lycoming O-320-D3G engine. Issued 1/20/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-140; T.C. 2A13	SA2842WE	Installation of Novastar anti-collision lighting system. Issued 2/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28-140; T.C. 2A13	SA3071WE	Installation of Bendix P/N 480543 electric auxiliary fuel pump. Issued 8/7/75.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
PA-28-140 (Normal and utility category); T.C. 2A13	SA3415WE	Installation of Lycoming O-320-D2A engine and Sensenich M74DM6-0-60 propeller. Reissued 5/1/79.	NE	30310	Arthur M. D'Onofrio, Jr. 206 Winthrop Boulevard Cromwell, CT 06416
PA-28-140, -28-150 and PA-28-151 landplanes; T.C. 2A13	SA1331CE	Installation of 160 hp Lycoming engine and repitched Sensenich Amended 10/27/77.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
PA-28-140, -150, -160, -180, -235; T.C. 2A13	SA2NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 7/31/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
PA-28-140, -28-150, -28-160, -28-180, -28S-180, -28-235; T.C. 2A13	SA363EA	Installation of Monitair angle of attack and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140, -150, -160, -180; T.C. 2A13	SA549NW	Installation of Deemers wing tips. Issued 12/5/77.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
PA-28-140, -140B, -140C, -140D, -140E, -150, -160, -160B, -160C, -160D, -160E, -160F, -180, -232, -235B thru F, PA-32-260, -300, -32R-300; T.C. 2A13, A3SO	SA600NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. NOTE: Installation does not apply to those models with tapered wings. Issued 10/25/78.	NW	19830	Robert C. Cansdale Bob's Aircraft Supply Thun Field Puyallup, WA 98371
PA-28-140, -150, -151, -160; T.C. 2A13	SA793CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/7666A-2 propeller. Amended 6/29/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
PA-28-140, -150, -160, -180, -235, 28-S-160, S-180, 28R-180, -200; T.C. 2A13	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-1 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-28-140, -150, -160, -180, -235, -S-160, -S-180, -R-180; T.C. 2A13	SA822SW	Mitchell automatic flight system AK217 consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -200, PA-34-200; T.C. 2A13, A7SO	SA979EA	Installation of L/R wing tip transparent fairings and sensor mounting bracketry. Issued 4/5/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
PA-28-140, -28-150, -28-160, -28-180, -28R-200 (S/N 28R-35001 thru 28R-7135329; T.C. 2A13	SA1072CE	Installation of wing leading edge cuffs and droop tips, dorsal fin and vertical stabilizer vortex Amended 5/1/80.	CE	42560	Horton Stol-Craft, Inc. Wellington Municipal Airport Wellington, KS 67152

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-140, -150, -160, -180, -235, -28S-160, -28S-180, -28R-180, -28R-200, -28-151, -28-161, -28-181, -28R-201, -28R-201T, PA-32-260, -300, -32S-300, -32R-300; T.C. 2A13, A3SO	SA1123EA	Installation of DeVore "Tel-Tail" lights on upper surface of horizontal stabilator. Reissued 8/16/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1227CE	Installation of dorsal fin. Amended December 1976.	CE	44800	Isham Aircraft P.O. Box 12172 Wichita, KS 67212
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1228CE	Installation of wing tip extension. Amended June 1976.	CE	44800	Isham Aircraft 416 West Fourth Street Valley Center, KS 67147
PA-28-140, -150, -160, -180, -235; PA-28R-180; T.C. 2A13	SA1157SW	Mitchell flight system AK295 consisting of Piper AutoFlite II, automatic aileron stabilizer and optional tracking system. Issued 6/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -235, -200; T.C. 2A13	SA1272SW	Automatic flight system AK307, consisting of Century I and omni tracker. Issued 3/9/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 3A12	SA1317CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-28-140, -150, -160, -180 (S/Ns 28-1 thru 28-4377), PA-28-235 (S/N 28-10003 thru 28-11039); T.C. 2A13	SA1373CE	Install third window. Amended 11/17/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1741WE	Installation of hand control for rudder system. Amended 6/13/73.	WE	16854	William Henry Blackwood Route 3, Box 744B3 Escondido, CA 92025
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1898SW	Installation of wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-28-140, -150, -160, -180; T.C. 2A13	SA2179WE	Installation of leading edge cuff, drooped ailerons, wing stall fences, raked wing tips, fuselage flaps, stabilator trim-spring and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98007
PA-28-140, -150, -160, -180, PA-28R-180, -200, -235, PA-32-260, -300; T.C. 2A13	SA3026SW-D	Mitchell auto flight system AK463 consisting of Century IIB autopilot with optional radio coupler. Issued 10/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, -28R-200, -235; T.C. 2A13	SA3165SW-D	Automatic flight system AK174 consisting of auto-control IIB autopilot with optional radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -160, -180, -235, -28R-180, -200; T.C. 2A13	SA3166SW-D	Automatic flight system AK295 consisting of Piper autoflite II. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -151, -160, -180, -181, -28R-180, -28R-200, -28-235; T.C. 2A13	SA3435WE	Installation of flexible oil hose assembly. Amended 1/11/79.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-28-140, -150, -160, -180, -151, -161, PA-28S-160, -180, PA-28R-180-200; T.C. 2A13	SA3687WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
PA-28-151; T.C. 2A13	SA228GL	Installation of Lycoming O-320-D3G engine in lieu of Lycoming O-320-E3D engine using original installation hardware and components. No installation data required. Issued 3/3/78.	GL	90108	W. Irvine Young 54 Atomic Avenue Toronto, Ontario M8Z-5L4 Canada

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-151; T.C. 2A13	SA1716SW	Mitchell automatic flight system AK430 consisting of AutoFlite II with optional omni tracker. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA1717SW	Mitchell automatic flight system AK431 consisting of auto-control III with optional radio coupler. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA2969SW	Lycoming O-320-D3G engine. Issued 4/5/79.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-151; T.C. 2A13	SA3012WE	Installation of Pathfinder autopilot systems. Issued 4/24/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-151, -161, -181, PA-28R-200, -201, PA-28-235, -28R-201T; T.C. 2A13	SA1075SO	"Wing-Ding" door stop to be installed using existing screws (Piper P/N 415 309, MS27039-0809) on leading edge of right wing at inboard side of fuel cell (W.S. 57.00). Issued 5/18/79.	SO	65327	William J. Stephenson Pro-Flite of Vero, Inc. P.O. Box 998 Vero Beach, FL 32960
PA-28-151, -181; T.C. 2A13	SA3065SW-D	Mitchell automatic flight system AK431 consisting of autocontrol IIIB with optional radio coupler. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3066SW-D	Mitchell automatic flight system AK430 consisting of autoflite II with optional omni tracker. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3095SW-D	Mitchell automatic flight system AK575 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3096SW-D	Mitchell automatic flight system AK576 consisting of Century IIb autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067
PA28-160; T.C. 2A13	SA1971WE	Installation of Model ARB-3 automatic downed aircraft marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue Box 822 Fort Collins, CO 80521
PA-28-160, -28-180, -28-235; T.C. 2A13	SA1484WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28-161, -181, -201T, -236; T.C. 2A13	SA3352SW	Installation of Mitchell automatic flight system AK851 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TS 76067
PA-28-180; T.C. 2A13	SA1789WE	Installation of Brittain lateral stability augmentation system and super venturi. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-180; T.C. 2A13	SA1792WE	Installation of Morse protection system.	WE	60190	Morse Products Manufacturing 12960 Bradley Avenue Sylmar, CA 91342
PA-28-180; T.C. 2A13	SA2213WE	Conversion of Lycoming O-360-A3A engine to Model O-360-A1A engine and installation of Hartzell HC-C2YK1-B/7666A-0 propeller. Issued 9/8/70.	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-180; T.C. 2A13	SA3233WE	Installation of Symbolic Displays "Novastar" anti-collision light. Issued 7/22/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28R-180; T.C. 2A13	SA962SW	Piper automatic flight system AK271 consisting of altimatic with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC holder
PA-28R-180; T.C. 2A13	SA1237SW	Mitchell automatic flight system Model AK314 consisting of altimatic IIIB-1 with optional automatic pitch trim and radio coupler. Issued 12/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA1406SW	Mitchell flight system Model AK269 consisting of Piper autocontrol III autopilot with optional radio coupler. Issued 12/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180; -200; T.C. 2A13	SA2202WE	Installation of contoured leading edge, drooped ailerons, fuselage flap, stabilator trim spring, wing stall fences, raked wing tips, and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98004
PA-28R-180, -200; T.C. 2A13	SA2490SW	Wing tip extension and dorsal fin. Reissued 10/6/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28R-180, -200; T.C. 2A13	SA3004SW-D	Automatic flight system AK436 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA3093SW-D	Mitchell automatic flight system AK577 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA3094SW-D	Mitchell automatic flight system AK578 consisting of Century IIB autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200, -201; T.C. 2A13	SA3841WE	Installation of SDI Model CFS-1000, -1001, or F1-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-28R-200; T.C. 2A13	SA194GL	Installation of Lycoming IO-360-C1C6 engine in lieu of Lycoming IO-360-C1C engine using original installation hardware and components. Issued 11/11/77.	GL	71517	Shelby Aircraft Engine Parts, Inc. P.O. Box 454 Shelbyville, IL 62565
PA-28R-200 (S/N 28R-7235001 and up), -28R-201T, -28R-201 (S/N 28R-7737002 and up); T.C. 2A13	SA1183CE	Installation of a two-axis King Model KFC200 flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 1/26/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-28R-201, -201T; T.C. 2A13	SA3161SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -201T; T.C. 2A13	SA3162SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3194SW-D	Automatic flight system AK638 consisting of Piper altimatic IIIC autopilot with optional radio coupler and glide slope coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3195SW-D	Install automatic flight system AK652 consisting of Century III autopilot with optional radio coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-200, -28R-201T; T.C. 2A13	SA3196SW-D	Install automatic flight system AK653 consisting of Century IIB autopilot with optional radio coupler. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28R-200, -28R-201T; T.C. 2A13	SA3197SW-D	Install automatic flight system AK654 consisting of Century I autopilot with optional omni tracker. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201T; T.C. 2A13	SA148RM	Install Model CFS-1000 fuel flow meter and related systems. Issued 8/15/78.	RM	77248	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-28R-201T; T.C. 2A13	SA1383CE	Installation of Edo-Aire propeller governor Model 34-826-014-12. Issued 10/26/77.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
PA-28R-201T; T.C. 2A13	SA3771WE	Installation of Fueltron IG digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-28RT-201, -28RT-201T; T.C. 2A13	SA1498CE	Installation of King KFC 200 automatic flight control system. Issued 6/18/79.	CE	48250	King Radio Corporation 400 NOrth Rogers Road Olathe, KS 66061
PA-28RT-201, -28RT-201T; T.C. 2A13	SA3323SW-D	Mitchell automatic flight system AK755 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 11/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3336SW-D	Mitchell automatic flight system AK777 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/21/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28-235; T.C. 2A13	SA1131EA	Installation of a radome pod SERP-1001 or -1002 on right wing. Amended 3/28/80.	EA	08332	David L. Stanislaw d/b/a Airquip Horsham Road Ambler, PA 19002
PA-28-235; T.C. 2A13	SA2143WE	Installation of drooped leading edge, drooped ailerons, wing stall fences, fuselage flap, drooped wing tips and elevator trim spring. Amended 12/30/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
PA-28-235; T.C. 2A13	SA2147WE	Installation of Brittain Industries B-7 flight control system. Reissued 11/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-235; T.C. 2A13	SA3187WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-235, PA-32-260, -300; T.C. A3SO, 2A13	SA1156EA	Installation of radome pod SERP-1021 or -1022 on right wing. Issued 6/26/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002
PA-28, PA-32; T.C. 2A13, A3SO	SA281AL	Installation of large nose gear fork and 8.00-6 nose gear tire. Amended 6/20/68.	AL	78487	Tibbetts-Herre Airmotive P.O. Box 110 Naknek, AK 99633
PA-28, PA-32; T.C. 2A13, A3SO	SA472SO	Installation of hand control for rudder pedal operation. Amended 6/27/74.	SO	85450	The Wheelchair Pilots Association 4211 Fourth Avenue South St. Petersburg, FL 33711
PA-28, PA-32; T.C. 2A13, A3SO	SA757SW	AK234 automatic flight system with Century II autopilot optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; PA-32-260; T.C. 2A13, A3SO	SA788SW	Piper auto-control II automatic pilot AK172E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA72RM	Installation of camera wells. Amended 12/9/76.	RM	42420	Horizons, Inc. P.O. Box 3134 Rapid City, SD 57701
PA-30 Series; T.C. A1EA	SA184EA	Installation of 13-quart alcohol propeller anti-icing kit utilizing either a Weldon pump (P/N 100B-6) or a Bendix pump (P/N 478360). Amended 10/15/71.	NE	86000	Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-30 Series; T.C. A1EA	SA225EA	Installation of Monitair angle of attack and stall warning system. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-30 Series; T.C. A1EA	SA233EA	Reservoir-type pneumatic wing and tail deicing system. Amended 10/7/70.	NE	86000	R.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA282CE	GUART System (Gear-up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 West Walnut Street Chicago, IL 60612
PA-30 Series; T.C. A1EA	SA343SW	Automatic pilot AK127, AK127E or AK127E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA477EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
PA-30 Series; T.C. A1EA	SA520SO	Installation of Bendix FCS-810 (Piper Altimatic V/F/D) automatic flight control including manual electric trim and optional flight director indicator. Amended 8/13/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-30 Series; T.C. A1EA	SA531SW	Fifth seat.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-30; T.C. A1EA	SA533NW	Installation of aileron trim. Issued 10/19/77.	NW	73160	Robert Smith Box 43 Okanagan Mission Kelowna, B.C., Canada
PA-30 Series; T.C. A1EA	SA534EA	Replacement of existing stall warning detector Safe Flight P/N C-52207 with pre-stall warning and speed control transducer, Safe Flight P/N 792 and speed control indicator, P/N 571.	EA	69500	Safe Flight Instruments Corp. New King Street White Plains, NY 10601
PA-30 Series; T.C. A1EA	SA559WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30 Series; T.C. A1EA	SA576SW	AK186 altimatic III autopilot, AK179 stabilizer, and AK189 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA591CE	Install Alco EW20101-PA-30-L windshield wiper system.	CE	08750	Alco Controls Corporation P.O. Box 12700 St. Louis, MO 63141
PA-30 Series; T.C. A1EA	SA727WE	Installation of Brittain Industries Model TT-5 wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-30 Series; T.C. A1EA	SA738CE	Install King Radio KNC 610 area navigation computer. Amended May 1974.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA766WE	Plastic wing tips replaced with "Speedplates" SP5146J.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
PA-30 Series; T.C. A1EA	SA767WE	Modification to include three pair of seat belts on rear seat to accommodate three passengers.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-30 Series; T.C. A1EA	SA776CE	Installation of King Radio KN-74 area navigation computer. Issued June 1971.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA789CE	Install Woodward propeller unfeathering accumulator system. Issued July 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-30 Series; T.C. A1EA	SA1111SW	Outer wing integral auxiliary fuel tanks and increase gross weight of 180 pounds.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1112SW	Dorsal fin.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1113SW	Extended nose with baggage compartment.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1114SW	Nacelle baggage compartments.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1115SW	Dual brakes.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1151SW	Lycoming IO-360-C1C engines (200 hp) with Hartzell HC-C2YK-2/C7666A-4 propeller. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1152SW	One-piece windshield. Issued 6/8/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1153SW	Square wing tips with dual navigation lights. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1154SW	Rudder and aileron interconnect system. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1337SW	Pneumatic de-icing system. Issued 7/8/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246
PA-30; T.C. A1EA	SA1401CE	Install King Model KNS 80 digital area navigation system. Issued 2/16/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA1935WE	Installation of Brittain flight control system Model B-5, NAV-2B, or B2C. Reissued 10/20/72.	SW	17400	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30; T.C. A1EA	SA3707WE	Installation of single piece windshield. Issued 8/7/78.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-30; T.C. A1EA	SA3729WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-30; T.C. A1EA	SA4066WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-30, PA-39; T.C. A1EA	SA209GL	Installation of one piece windshield. Issued 1/23/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-30, PA-39; T.C. A1EA	SA673EA	Installation of radome kit 3058X. Amended 5/26/76.	SW	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-30, PA-39; T.C. A1EA	SA676EA	Installation of Norton Company radome kit 3058-B. Amended 3/24/71.	SW	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1167 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-30, PA-39; T.C. A1EA	SA787WE	Installation of turbosupercharged Lycoming IO-320-B1A, IO-320-C1A or LIO-320-C1A engines. Amended 3/10/70.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA848EA	Installation of pneumatic pump operated wing and tail de-icing boot system. Issued 10/22/70.	NE	86400	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-30, PA-39; T.C. A1EA	SA1239SW	Turbosupercharged Lycoming IO-360-C1C engines. Issued 1/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30, PA-39; T.C. A1EA	SA1254SW	Electrothermal propeller de-icing system. Issued 1/27/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30, PA-39; T.C. A1EA	SA1320CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-30, PA-39; T.C. A1EA	SA1341SW	Nose taxi light. Issued 7/20/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246
PA-30, PA-39; T.C. A1EA	SA2312WE	Installation of leading edge cuffs, stall fences, stall strips drooped ailerons, flap actuated stabilator trim system, raked wing tips (optional) and dorsal fin. Amended 4/2/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-30, PA-39; T.C. A1EA	SA2849WE	Installation of oxygen system. Amended 10/3/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA3128SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional command automatic trim, readio, and glide slope couplers. Issued 5/6/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA3336WE	Installation of single piece windshield. Issued 2/2/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-31 (S/N 31-2 and up); T.C. A8EA	SA142RM	Install Model CFS-2000 fuel flow meter and related systems. Issued 5/12/78.	EA	77250	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-31; T.C. A8EA	SA191GL	Installation of microwave landing airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31 Series; T.C. A20SO	SA367GL	Installation of Norton radome kit No. 2032K Issued 10/9/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA529EA	Installation of kit for radar antenna.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company P.O. Box 1187 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA541CE	Installation of Hoskins Twilighter MK III supplemental lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-31 Series; T.C. A8EA	SA546EA	Incorporation of opening in lower surface of fuselage aft of front spar.	NE	86000	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-31 Series; T.C. A8EA	SA613EA	Installation of nine seats. Amended 6/6/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31 Series; T.C. A8EA	SA622EA	Incorporation of camera hatch and mountings to accommodate Zeiss RMK A15/23 camera.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
PA-31 Series; T.C. A8EA	SA741EA	Installation of co-pilot door. Amended 11/3/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31 Series; T.C. A8EA	SA865EA	Installation of radome kit 2031KX. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA908SW	Air conditioner.	SW	64410	R.D. Philpot Industries, Inc. Box 47062 Dallas, TX 75247
PA-31 Series; T.C. A8EA	SA986SW	Baggage lockers in revised aft nacelle fairings.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1000SW	Nine place seating arrangement.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C, A8EA	SA1054SW	Stretcher.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1055SW	Baggage retaining net.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1065SW	Mitchell flight director and autopilot Model 282-187 with slaved directional gyro. Issued 9/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA1120SO	Installation of single camera and camera aperature on starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31; T.C. A20SO	SA1121SO	Installation of supply dropping aperature and sliding shutter and antenna fairing. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31; T.C. A20SO	SA1123SO	Installation of navigation sight and transperent plastic dome on the lower fuselage station 128. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31 Series; T.C. A8EA	SA1155SW	Three-place couch. Reissued 6/20/78.	SO	28380	Cypress Aviation, Inc. 3840 Drone Field road Lakeland Airport Lakeland, FL 33603
PA-31 Series; T.C. A8EA	SA1204SW	Manual electric trim AK281. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31 Series; T.C. A8EA	SA1234SW	Mitchell automatic flight system FD/AP282-273, consisting of flight director /autopilot with optional automatic aileron stabilizer AK273. Issued 12/21/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31 Series; T.C. A8EA	SA1305SW	Auxiliary fuel tank. Issued 5/10/71.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1340SW	Four-place couch. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 WEst, Meacham Field Fort Worth, TX 76106
PA-31 Series; T.C. A8EA	SA1569WE	Installation of windshield wiper system.	CE	08750	Alco Controls Corporation Box 12700 St. Louis, MO 63141
PA-31 Series; T.C. A8EA	SA1651WE	Installation of ski carrying pod under fuselage at wing root.	NW	57700	Melridge Aviation Company 1901 East Fifth Street Vancouver, WA 98661
PA-31 Series; T.C. A8EA	SA2124WE	Installation of air conditioning system.	RM	45750	J.B. Systems 120 South Bowen Circle Longmont, CO 80501
PA-31 Series; T.C. A8EA	SA3130SW-D	Mitchell automatic flight system AK589 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31; T.C. A20SO	SA3355SW	Mitchell automatic flight system AK846/FD consisting of Century IV/flight director autopilot with optional remote annunciator. Issued 2/19/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA3768WE	Installation of Fueltron digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-31, PA-31-300; T.C. A8EA	SA603EA	Addition of a 32-inch high door on L.H. side of fuselage between fuselage stations 244-261. Reissued 6/21/78.	SO	28380	Cypress Aviation, Inc. 3480 Drone Field Road Lakeland Airport Lakeland, FL 33803
PA-31, -300; T.C. A8EA	SA748EA	Modification of toilet seat hassock and installation of safety belt. Issued 4/4/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31, -300; T.C. A8EA	SA1255SW	Mitchell automatic flight system Model AK324 consisting of Piper autoflite II and tracking system. Issued 1/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA1522SW	Mitchell automatic flight system AK394, consisting of Century I autopilot with optional omni tracker. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3008SW-D	Automatic flight system AK483 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim, radio, and glide slope couplers. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3009SW-D	Automatic flight system AK496 and AK496FD consisting of Century IV autopilot and Century IV flight director with command/automatic electric elevator pitch trim and optional annuciator panel. Issued 7/12/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -31-300; T.C. A8EA	SA3010SW-D	Automatic flight system YK491 consisting of yaw damper. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -31-300, -325, -350; T.C. A8EA	SA1318CE	Chrome-plated brake disc installation. Issued May 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-31 (S/N 31-712 and up), PA-31-325, -350; T.C. A8EA	SA1529CE-D	Installation of King KAS 297 altitude selector option. Issued 2/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, -31-300, -325, -350; T.C. A8EA	SA3401WE	Installation of single piece windshield. Issued 5/10/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-31, 31-300, PA-31P; T.C. A8EA	SA852EA	Installation of Grimes 555 Series three light strobe kit P/N 34-0100-1. Amended 5/10/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-31, -31P, -31-325, -31-350; T.C. A8EA	SA437SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and optional flight director indicator. Amended 4/4/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31, -31P, -31T, -31-300, -325, -350, -31T1; T.C. A8EA	SA1008EA	Installation of single lamp logo light in horizontal tail. Amended 11/16/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
PA-31, -31P, -31-300, -325, -350; T.C. A8EA	SA1187CE	Installation of King Model KCS 55A pictorial navigation (compass) with optional KS 52 autopilot adapter. Issued 12/10/75.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31-350, -31-325; T.C. A8EA	SA1166CE	Installation of King KFC-200, 2 axis (3 optional) flight control system, autopilot only or autopilot with flight director. Amended 1/4/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31T; T.C. A8EA	SA578NW	Install redesigned 7th seat (toilet). Issued 5/12/78.	NW	70640	Seattle Flight Service, Inc. 7001 Perimeter Road Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31-300; T.C. A8EA	SA184GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31-300, -310, -325, -350; T.C. A8CE	SA1136CE	Installation of Fiquench cabin fire extinguisher and engine fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
PA-31-325; T.C. A8EA	SA1085CE-D	Installation of Collins Radio Group AP-106, 3-axis autopilot system. Amended 6/25/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1086CE-D	Installation of Collins Radio Group AP-107, 3-axis autopilot system. Amended 6/26/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1087CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system. Amended 6/26/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1088CE-D	Installation of Collins Radio Group yaw damper system. Amended 4/25/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA3017SW-D	Automatic flight system AK485 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim system, radio, and glide slope couplers. Issued 9/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3021SW-D	Automatic flight system AK500 and AK500FD consisting of Century IV autopilot and Century IV flight director autopilot with electronic command/automatic pitch trim system and optional annuciator panel. Issued 10/4/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3129SW-D	Automatic flight system AK590 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3211SW-D	Mitchell automatic flight system AK686 or AK686FD, Piper altimatic X flight director autopilot with optional remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325, -31-350; T.C. A20SO	SA300CE	Installation of propeller governors on single and twin engine aircraft: P/N L210571 left engine, R210571 right engine. Issued 1/2/80. P/N L210721 left engine, R210721 right engine. Issued 2/2/80. P/N L210573 left engine, R210573 right engine. Issued 5/7/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-31-325, PA-31-350 S/N 31-7405479 and up (S/N 31-5001 thru 7405478 when modified per Piper SL722); T.C. A20SO	SA4037WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel and totalizer system. Amended 3/13/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-31-350; T.C. A8EA	SA8NE	Installation of Collins AP-107 2-axis or 3-axis autopilot including yaw damper system. Reissued 12/19/74.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, NE Cedar Rapids, IA 52406
PA-31-350; T.C. A20SO	SA295GL	Install Cleveland conversion kit, P/N 199-83. Issued 3/15/79.	GL	23260	Cleveland Wheels & Brakes Vansickle Division of Parker Hannifin 1160 Center Road Avon, OH 44011
PA-31-350; T.C. A8EA	SA923SO	Installation of Bendix FCS-870 automatic flight control system. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31-350; T.C. A8EA	SA924SO	Installation of Bendix NP-2041A area navigation computer. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31-350; T.C. A20SO	SA1119SO	Installation of twin cameras and two camera aperatures on starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1122SO	Installation of single camera and camera aperature on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1124SO	Installation of a single camera and camera aperature and antenna fairing on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1125SO	Installation of twin cameras and two camera aperatures plus camera sights on starboard side of lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
t) (					
PA-31-350; T.C. A8EA	SA1611SW	Mitchell automatic flight system AK413 consisting of altimatic IIIB-1 with optional automatic pitch trim, radio coupler, and glide slope couplers. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA1612SW	Mitchell automatic flight system AK416 consisting of autoflite II with optional tracking system. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA1807SW	AP106 2-axis or 3-axis autopilot including yaw damper and FD-108 flight director. Issued 2/14/74.	SW	24252	Collins Radio Company Box 98 Addison, TX 75001
PA-31-350; T.C. A8EA	SA3015SW-D	Automatic flight system AK-498, cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio, and glide slope coupler. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3016SW-D	Automatic flight system AK499 and AK499FD cons. of Century IV flight director autopilot w/command automatic electric elevator pitch trim and opt. annunciator panel. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3086SW-D	Automatic flight system AK560 cons. of Century III autopilot w/ opt. radio & glide slope couplers. Issued 11/27/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3212SW-S	Mitchell automatic flight system Piper altimatic X autopilot, AK687 or AK687FD Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P-425; T.C. A8EA	SA284GL	Install Cleveland conversion kit, P/N 199-83. Amended 2/28/79.	GL	23260	Cleveland Wheels & Brakes VanSickle Division of Parker Hannifin 1160 Center Road Avon, OH 44011
PA-31P; T.C. A8EA	SA483SO	Installation of Bendix YD4 yaw damper system. Issued 12/23/71.	SO	15475	Bendix Avionics Division P.O. Box 8414 Ft. Lauderdale, FL 33310
PA-31P; T.C. A8EA	SA782CE	Installation of King Radio H-14 autopilot. Issued 6/71.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
PA-31P; T.C. A8EA	SA1265SW	Mitchell automatic flight system model AK323 cons. of Piper Autoflite II and Omni tracking system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA1523SW	Mitchell automatic flight system AK395, cons. of Century autopilot w/opt. omni tracker. Issued 10/17/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31P; T.C. A8EA	SA3012SW-D	Automatic flight system AK484 cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 8/8/74.	SW	60000	Kitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3013SW-D	Automatic flight system AK492 & AK492FD cons. of Century IV autopilot and Century IV flight director w/command automatic electric pitch trim and opt. annunciator panel. Issued 8/9/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3014SW-D	Automatic flight system YK493 cons. of yaw damper. Issued 8/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3213SW-D	Mitchell automatic flight system Piper altimatic X autopilot, AK688 or AK688FD, Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31T; T.C. A8EA	SA190GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 8/16/77.	GL	46250	Jet Electronics and Technology, Inc. 5353 52nd Street N.E. Grand Rapids, MI 49508
PA-31T; T.C. A1EA	SA213GL	Installation of storm window in right hand cockpit window duplicating storm window now installed in left hand cockpit window. Issued 2/2/78.	GL	61629	Northern Airmotive, Inc. 3600 East 70th Street Minneapolis, MN 55450
PA-31T; T.C. A8EA	SA578SO	Instl. of a Bendix M-4D automatic flight control system, including optional manual electric pitch trim and flight director system. Amended 10/1/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
PA-31T; T.C. A8EA	SA665NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. Issued 9/14/78.	NW	28850	Robert M. DeBorde 20645 S.W. Clarion Aloha, OR 97005
PA-31T; T.C. A8EA	SA1188CE	Intallation of King KFC 300 automatic flight control system. Amended 4/15/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31T; T.C. A8EA	SA4016WE	Installation of SDI model CFS-2002, fuel flow indicating system. Issued 8/31/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-31T; T.C. A8EA	SA4066SW	Auto-feather system 1. Issued 12/4/79.	EA	64665	Piper Aircraft Corporation 820 East Bald Eagle Drive Lockhaven, PA 17745
PA-31T1; T.C. A8EA	SA1053SO	Installation of FCS-870 automatic flight control system, including manual electric trim, optional yaw damper system, and optional flight director. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31T1; T.C. A8EA	SA1054SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31T1; T.C. A8EA	SA1405CE	Install King KFC-250 autopilot/flight director. Amended 3/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32; T.C. A3SO	SA311NW	Installation of flap extension, spoiler L/E cuff and optional cambered wing tips. Issued 5/28/76.	NW	68500	Robertson Aircraft 839 W. Perimeter Road Renton, WA 98055
PA-32; T.C. A3SO	SA532SW	AK173 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32; T.C. A3SO	SA1523WE	Inst'l. of Brittain Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-32; T.C. A3SO	SA1607WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-32-260; T.C. A3SO	SA371EA	Zeiss aerial camera and intervalometer.	NE	71400	James W. Sewall Co. 147 Center Street Old Town, ME 00468
PA-32-260; T.C. A3SO	SA409GL	Installation of a Lycoming IO-540-K1A5 engine, Hartzell propeller and associated components. Issued 5/23/80.	GL	60179	Melvin C. Morkert 915 Montclair Drive Racine, WI 53402
PA-32-260; T.C. A3SO	SA533SW	Auto-Control III AK174.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA538SW	Piper Altimatic II autopilot and/or radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA1310SW	Stretcher in lieu of rear seats. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72203
PA-32-260; T.C. A3SO	SA1557WE	Installation of turbosupercharged Lycoming 0-540-E4B5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
PA-32-260, -32-300; T.C. A3SO	SA3NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 8/1/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
PA-32-260, -32-300; T.C. A3SO	SA530CE	Install FluiDyne Model 4000 & 2500A skis.	GL	36060	FluiDyne Engr. Corp. 5900 Olson Memorial Hwy. Minneapolis, MN 55422
PA-32-260, -32-300; T.C. A3SO	SA939SW	Mitchell Manual Electric Pitch Trim System AK272.	SW	76067	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300; T.C. A3SO	SA1362CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-32-260, -32-300; T.C. A3SO	SA1568SW	Wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-32-260, -32-300; T.C. A3SO	SA2217WE	Installation of recontoured wing leading edge, raked wing tips, fuselage flap, stall fences, droop ailerons and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 1540 Sunset Highway Bellevue, WA 98007
PA-32-260, -32-300; T.C. A3SO	SA2933WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 Wardlow Road Long Beach, CA 90807
PA-32-260, -32-300; T.C. A3SO	SA3173SW-D	Automatic flight system AK174 cons. of Piper autocontrol IIIB autopilot w/opt radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32S-300; T.C. A3SO	SA1172SW	Mitchell flight system AK304 cons. of Piper autoflite II with optional auto aileron stabilizer and tracking system. Issued 7/17/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32S-300; T.C. A3SO	SA1378SW	Mitchell automatic flight system AK320, cons. of Century I and opt. tracker. Issued 10/26/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300 -32S-300; T.C. A3SO	SA3011SW-D	Automatic flight system AK488 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -300, -32R-300;	SA3736WE	Installation of an engine oil cooler hose. Issued 9/22/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-32-260, -300, -32S-300, -32R-300; T.C. A3SO	SA3839WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-32-300; T.C. A3SO	SA893EA	Installation of 8-quart alcohol propeller anti-icing kit WAP-800A. Issued 12/15/71.	NE	86000	E. W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-32-300; T.C. A3SO	SA3305SW-D	Mitchell automatic flight system AK775 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 9/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300; T.C. A3SO	SA3306SW-D	Mitchell automatic flight system AK776, consisting of Century III autopilot with optional and glide slope couplers. Issued 9/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300, -32R-300, -32RT-300, -32RT-300T; T.C. A3SO	SA364GL	For "T" tail configuration - installation of Norton radome kit No. 4229X. For conventional tail configuration - installation of Norton radome kit No. 4229XC. Amended 1/17/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Oeprations P.O. Box 350 Akron, OH 44309
PA-32-300, -32R-300; T.C. A3SO	SA1154EA	Installation of radome pod SERP-1011 or -1012 on right wing. Amended 12/6/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002
PA-32-300, -32R-300; T.C. A3SO	SA3670WE	Installation of Silver Instruments Fueltron IG digital fuel flow indicating system. Issued 6/23/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-32-300, -32R-300, -32S-300, -32RT-300; T.C. A3SO	SA3774WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-32R; T.C. A3SO	SA21NE	Installation of Whelen A600-PR and A600-PG anti-collision strobe with forward and tail position light assemblies as replacements for wing tip lights. Issued 3/1/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
PA-32R-200; T.C. A3SO	SA3102SW-D	Mitchell AK591, consisting of Century IIB autopilot w/opt radio coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-200; T.C. A3SO	SA3103SW-D	Mitchell AK592 cons. of Century III autopilot w/opt. radio coupler and glide slope coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA260GL	Install a Foster Airdata RNAV 511 area navigation system with 51ASA (Alpha) or 51DSA (Delta) steering adapter, or without either adapter. Amended 6/29/79.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
PA-32R-300; T.C. A3SO	SA975SO	Installation of two 15-gallon auxiliary fuel tanks, one in each wing. Issued 4/5/78.	SO	28380	Cypress Aviation, Inc. 3480 Drane Field Road Lakeland Municipal Airport Lakeland, FL 33803
PA32R-300 S/N 32R-7680001 and up; T.C. A3SO	SA1201CE	Installation of King KFC 200, 2 axis, flight control system with a King KCS-55 (or -55A) compass and a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 9/9/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32R-300; T.C. A3SO	SA3052SW-D	Mitchell automatic flight system AK529 cons. of Piper altimetric IIIC w/command/auto. elec. pitch trim, opt. radio coupler and glide slope coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3053SW-D	Installation of Mitchell automatic flight system AK530 cons. of Piper autocontrol IIIB autopilot with opt. radio coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3054SW-D	Mitchell automatic flight system AK531 cons. of Piper autoflite II w/opt. omni tracker. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-32R-300; T.C. A3SO	SA3055SW-D	Mitchell command/electric trim system Model AK532. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3513WE	Installation of Rajay turbocharged Lycoming IO-540-K1G5D engine. Issued 11/8/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
PA-32RT-300, -32RT-300T;	SA1159EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
PA-32RT-300, PA-32RT-300T; T.C. A3SO	SA1430CE	Install King KFC-200 automatic flight control system. Issued 8/9/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32RT-300; T.C. A3SO	SA3253SW-D	Mitchell automatic flight system AK677 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3254SW-D	Mitchell command electric trim system AK 678. Issued 2/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3255SW-D	Mitchell automatic flight system AK 679 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300T; T.C. A3SO	SA3309SW-D	Installation of Mitchell automatic flight system consisting of Century IV autopilot or AK771 consisting of flight director autopilot with optional remote annunciator. Issued 10/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32S-300; T.C. A3SO	SA932EA	Installation of Pee Kay Model B3500 seaplane floats and Pee Kay Model 3500A amphibious floats. Issued 9/22/72.	EA	29998	Pee Kay DeVore Inc. 125 Mineola Avenue Roselyn Heights, NY 11577
PA-32S-300; T.C. A3SO	SA2253WE	Installation of Edo Model FD-3500-21 amphibious floats. Reissued 5/24/76.	NE	23370	T. M. Close Corporation Gardner Municipal Arpt. Box 464 Gardner, MA 01440
PA-32R-301, -32R-301T; T.C. A3SO	SA1522CE-D	Installation of King KFC 200 flight control system. Issued 12/17/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-34; T.C. A7SO	SA1363CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-34; T.C. A7SO	SA2285SW	Camera and viewfinder installation. Issued 1/22/76.	SW	42825	A. D. Howard, Jr. 1911 Moulton Ct. Oklahoma City, OK 73127
PA-34-200; T.C. A7SO	SA154NW	Installation of full span flaps by removing aileron and changing deployment route of all flaps, spoilers mounted above flap, conical cambered wing tips, anti-balance rudder tab and optional dorsal fin. Issued 1/28/75.	NW	68500	Robertson Aircraft Corp. 839 W. Perimeter Road Renton, WA 98055
PA-34-200; T.C. A7SO	SA292NW	Installation of cooling louvers on top of both nacelle accessory sections. Issued 5/13/76.	NW	01530	Advanced Aviation 4911 S. 290th Place Auburn, WA 98002
PA-34-200; T.C. A7SO	SA493SO	Installation of Bendix FCS-810 (Piper altimatic V/FD) automatic flight control system including manual electric trim and optional flight director indicator. Issued 2/17/72.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
PA-34-200; T.C. A7SO	SA900EA	Installation of electrothermal propeller de-icer system. Amended 1/14/74.	GL	38500	B. F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-34-200; T.C. A7SO	SA901EA	Installation of wing ice light kit. Amended 12/6/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200; T.C. A7SO	SA1321SW	Mitchell automatic flight system AK298 cons. of altimatic IIIB-1 autopilot w/opt automatic command electric pitch trim, radio coupler and glide slope coupler. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA1322SW	Mitchell automatic flight system Model AK335 cons. of Piper auto-control III w/opt. radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA1323SW	Mitchell command electric pitch trim Model AK321. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA2932WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA2937WE	Installation of turbosupercharged Lycoming IO/LIO-360-C1E6 engine. Amended 3/31/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA3002WE	Installation of wing tip fuel tanks of 17 gal capacity (each). Reissued 5/14/76.	WE	68501	Robertson Aircraft Corp. 2301 E. Utopia Rd. Phoenix, AZ 85024
PA-34-200, S/N 34-E4, S/N 34-7250001 and up; T.C. A7SO	SA903EA	Installation of B.F. Goodrich pneumatic de-icing system. Amended 11/1/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200, -34-200T; T.C. A7SO	SA50GL	Installation of Norton Radome Kit No. 4011KX Amended 3/15/79.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Product Division P.O. Box 350 Akron, OH 44309
PA-34-200, -34-200T; T.C. A7SO	SA510NW	Installation of Cessna fuel tank assembly. Issued 8/20/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
PA-34-200, -34-200T; T.C. A7SO	SA3554WE	Installation of vertical tail floodlights on horizontal stabilizer. Issued 1/11/78.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
PA-34-200T; T.C. A7SO	SA106RM	Installation of freon type air conditioning system. Issued 8/3/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-34-200T; T.C. A7SO	SA154RM	Install Symbolic Displays TSO'd Model CFS-2000 fuel flow meter and related systems. Issued 9/22/78.	RM	77248	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-34-200T; T.C. A7SO	SA968SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 1/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7SO	SA969SO	Installation of NP-2041A area navigation computer programmer. Issued 1/9/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7DO	SA1118SO	Installation of Hartzell 3-bladed propellers, Models - PHC-C3YF-2( )UF/FC-7663-2R and PHC-C3YF-2L( )UF/FJC-7663-2R or PHC-C3YF--( )UF/FC-7663B-2R and PHC-C3YF-2L( )UF/FJC-7663B-2R. Issued 12/21/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
PA-34-200T; T.C. A7SO	SA1147CE	Installation of King Model KFC 200 flight control system, with King KCS 55 or 55A compass and a King KI-255 (or -256) flight command indicator on a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 9/13/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-34-200T; T.C. A7SO	SA1553CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-34-200T; T.C. A7SO	SA3023SW-D	Automatic flight system AK487 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electronic elevator pitch trim, radio, and glide coupler. Issued 9/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3024SW-D	Automatic flight system AK505 cons. of Piper auto-control IIIB autopilot w/opt. radio coupler. Issued 10/24/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3089SW-D	Mitchell automatic flight system AK561 cons. of Century III Autopilot w/opt radio coupler and glide slope coupler. Issued 12/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3669WE	Installation of FUELTRON IIIG digital fuel flow indicating system. Issued 6/21/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-36; T.C. A9SO	SA277NW	Installation of automatic flagman. Issued 3/30/76.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362
PA-36; T.C. A9SO	SA1364CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas Citym KS 66103
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	SA1291CE	Installation of Lycoming IO-720-A1B engine. Amended 4/17/79.	CE	11003	Mr. Clinton Anderson Nehawka, NB 68413
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	SA3452WE	Installation of Lycoming IO-720-A1B engine and Hartzell HC-C3YR-1RF/F8475R constant speed propeller. Amended 2/5/79.	WE	46790	Johnston Aircraft Service, Inc. P.O. Box 1457 Tulare Municipal Airport Tulare, CA 93274
PA-36-375; T.C. A10SO	SA3535WE	Installation of hydraulic system to power spray dispersal system. Issued 12/21/77.	WE	03290	Agrinautics 1333 Patrick Lane Las Vegas, NV 89119
PA-36-375; T.C. A10SO	SA3703WE	Installation of hydraulic power spray pump. Issued 7/27/78.	WE	03290	Agrinautics 1333 Patrick Lane Las Vegas, NV 89119
PA-39 Series; T.C. A1EA	SA816EA	Installation of 13 quart alcohol propeller anti-icing kit WAP-500B. Amended 10/15/71.	NE	86000	Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-39 Series; T.C. A1EA	SA1342SW	Mitchell automatic flight system AK296 cons. of Piper altimatic IIIB-1 autopilot w/opt. automatic pitch trim, radio, and glide slope couplers. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1343SW	Mitchell automatic flight system AK325 cons. of Piper autoflite II w/opt. tracking system. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1344SW	Mitchell command electric trim AK267. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1386SW	Mitchell automatic flight system model AK339, cons. of Piper auto-control III autopilot with optional radio coupler. Issued 11/16/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1638SW	Mithcell automatic flight system AK355, consisting of Century I with omni tracker. Issued 4/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-40; T.C. A1EA	SA3028SW-D	Mitchell auto. flight system AK481, consisting of Piper altimatic IIIC autopilot with command automatic electric pitch trim system, optional radio, and glide slope couplers. Issued 10/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-40; T.C. A1EA	SA3036SW-D	Automatic flight system AK506 consisting of Piper autocontrol IIIB autopilot with optional radio coupler. Issued 12/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA1158EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
PA-44-180; T.C. A19SO	SA1504CE	Installation of King KFC 200 FCS (2 axis) with or without flight director. Issued 8/2/79.	SW	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-44-180; T.C. A19SO	SA3276SW-D	Installation of Mitchell automatic flight system AK 723 consisting of Piper autocontrol IIIB with optional radio couplers. Issued 4/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA44-180; T.C. A19SO	SA3277SW-D	Mitchell automatic flight system AK719 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 4/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3278SW-D	Mitchell command electric trim AK718.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3287SW-D	Mitchell automatic flight system AK756 consisting of Century IIB autopilot with optional radio coupler. Issued 5/26/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3288SW-D	Mitchell automatic flight system AK757 consisting of Century III autopilot with optional radio and and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell INdustries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MISCELLANEOUS	SA788WE	Mixture monitor (exhaust gas temperature probe and gage). See FAA-approved eligibility list for models.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PIPER AIRCRAFT CORPORATION, CALIFORNIA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
600; T.C. A17WE	SA1347SW	Alternate vent for fuel pressure gages. Issued 7/22/71.	SW	84250	Vought Aircraft Service Company Meacham Field Fort Worth, TX 76106
600; T.C. A17WE	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
600; T.C. A17WE	SA1675WE	Installation of K S Avionics EGT-2 exhaust gas monitoring system. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
600 (S/N 60-0266-XX and up, and those aircraft with previously installed option #108); T.C. A17WE	SA3770WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 6/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
600, 601; T.C. A17WE	SA20GL	Installation of Woodward electronic propeller synchronizer system. Amended 11/6/75.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601; T.C. A17WE	SA35GL	Install wheel and brake conversion kit P/N 199-51. Reissued 7/23/74.	GL	23260	Cleveland Wheels & Brakes Div. Van Sickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
600, 601; T.C. A17WE	SA443SO	Instllation of Bendix RDR-110 weather radar system per Bendix drawing 4009700, Rev. B. Installation of Norton AD4059KX-5 radome approved per STC SA845EA. Issued 9/25/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601; T.C. A17WE	SA771CE	Installation of Woodward propeller unfeathering accumulator system. Issued June 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601; T.C. A17WE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
600, 601; T.C. A17WE	SA845EA	Installation of radome kit P/N 4059KX or 4059X. Reissued 9/29/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
600, 601; T.C. A17WE	SA1308SW	Addition of toilet provision. Issued 5/7/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1356SW	Fabricate and install rib-wing fairing-inboard (flap attachment bracket). Issued 8/13/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1362SW	Storage drawers under cabin seats. Issued 9/3/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76067
600, 601; T.C. A17WE	SA1363SW	Installation of pressure relief valves in fuel tanks. Issued 9/3/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1382SW	Modify two passenger seats to face aft. Issued 10/29/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1391SW	Dual hydrauic pump. Issued 11/12/71.	GL	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1452SW	Modfy Ted Smith control tube P/N A600128-3. Issued 3/30/72.	GL	84250	Vought Aircraft Services Compay Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1797SW	Mitchell automatic flight system AK459 consisting of Century autopilot with optional omni tracker. Issued 1/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
600, 601; T.C. A17WE	SA2357WE	Installation of auxiliary hydraulic pump. Issued 5/28/71.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
600, 601; T.C. A17WE	SA3884WE	Installation of cabin door pneumatic spring counter-balance. Issued 4/5/79.	WE	64423	Physical Systems, Inc. 7049 Vineland Avenue North Hollywood, CA 91605
600, 601, 601P; T.C. A17WE	SA444SO	Intallation of Bendix Model FCS 810 flight control system, including flight director indicator DH 841( ). Amended 6/3/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601, 601P; T.C. A17WE	SA1089CE-D	Installation of Collins Radio Group AP-106 autopilot system and interface with Collins FD-112 flight director. Amended 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1090CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1104CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1139SO	Installation of a Bendix FCS-870 automatic flight control system. The following options are included: preselect altitude, yaw damper and flight director system. Issued 3/13/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601, 601P; T.C. A17WE	SA1174CE	Installation of Aero Space Controls Corp. 100 AMP alternator. Issued 10/31/75.	CE	02950	Aero Space controls Corporation 1050 North Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1175CE	Installation of Aero Space Controls Corp. air conditioning system. Issued 10/31/75.	CE	02950	Aero Space Controls Corporation 1050 Nort Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1184CE	Install King Model KFC-200 2-axis (3 optional) flight control system with King KCS-55 (or -55A) compass and a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 9/1/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
600, 601, 601P; T.C. A17WE	SA1277CE	Installation of Avcon Industries TSO-C39a stretcher, P/N 4001-101 or 4001-102. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
600, 601, 601P; T.C. A17WE	SA1530CE-D	Installation of King KAS 297 altitude selector option. Issued 2/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
600, 601, 601P; T.C. A17WE	SA2207WE	Installation of JB Systems air conditioning system. Amended 5/21/76.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
600, 601, 601P; T.C. A17WE	SA2336WE	Installation of Prestolite 70 amp alternators (Avco Lycoming P/N 78314) in lieu of existing 50 amp alternators. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA2367WE	Installaton of Prestolite 70 amp alternators (Avco Lycoming P/N 78314). Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA2655WE	Installation of auxiliary hydraulic pump option. Reissued 4/11/78.	WE	64666	Piper Aircraft corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA3029SW-D	Mitchell automatic flight system AK521 consisting of Century III autopilot with command automatic electric pitch trim system, radio, and glide slope couplers. Issued 11/27/74.	SW	60000	Mitchell Indusries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
600, 601, 601P; T.C. A17WE	SA3030SW-D	Mitchell automatic flight system AK522 or AK522FD consisting of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim and optional annuciator panel. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3033SW-D	Automatic flight system AK455 consisting of Century I autopilot with optional omni tracker. Issued 1/9/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3643WE	Installation of vertical tail floodlight. Issued 5/24/78.	WE	30000	DeVore Aviation 16160 Stagg Street Van Nuys, CA 91406
600, 601, 601P (S/N 60-0266-XX and up and those aircraft with previously installed option #108); T.C. A17WE	SA3370WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 6/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
600, 601, 601P S/N 266 and up and aircraft with option 108 previously installed; T.C. A17WE	SA4029WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 9/21/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
601; T.C. A17WE	SA2346WE	Installation of turbocharger overboost protection. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601; T.C. A17WE	SA2664WE	Modification of fuselage structure for pressurization to 3.20 psi operating pressure, and installation of pressurization system. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601P; T.C. A17WE	SA61GL	Installation of radome kit P/N 4079RX or 4079X. Reissued 8/29/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-40, -60, -65, -70, -80; T.C. A2WE	SA1545CE	Installation of protective cover No. DLC-2. Amended 3/10/80.	CE	44933	J & H Manufacturing Co., Inc. 511 East locus Carter Lake, IA 68110
t+1 NA-265-40, -60, -70; T.C. A2WE	SA756CE	Install Woodward engine synchronizer system. Amended 4/10/74.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
NA-265-40, -60, -70; T.C. A2WE	SA1162CE	Installation of P & D valve fuel reservoir. Issued February 1976.	CE	68765	Rockwell International Corp. Sabreliner Division Missouri Completion Center Route 3 Perryville, MO 63775
NA-265-40, -60, -70; T.C. A2WE	SA1946SW	Engine fuel shut down system. Issued 1/17/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70; T.C. A2WE	SA1972SW	BKM 100-265 nose wheel steering control. Issued 4/9/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA265-40, -60, -70; T.C. A2WE	SA2789SW	Foxboro fuel management system. Issued 6/2/78.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70; T.C. A2WE	SA4096SW	Bleed air engine fuel manifold purge system. Issued 3/12/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA746EA	Installation of Norton radome kit numbers, P/N 3090X-1, 3090X-10, 3090X-15, 3090X-20 or 3090X-30. Amended 5/18/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
NA265-40, -60, -70, -80; T.C. A2WE	SA1338CE	Installation of Global GNS-500A VLF/Omega navigation system. Issued 6/27/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60, -70, -80; T.C. A2WE	SA1458CE	Installation of microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
NA-265-40, -60, -70, -80; T.C. A2WE	SA1961SW	Entrance door counterbalance system. Issued 4/22/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2382SW	Change nose gear linkage and stop assembly to provide increased steering capability from 35 degrees to 45 degrees. Issued 11/16/76.	SW	16850	The BKM Company P.O. Box 7001 P.O. Box 7001
NA-265-40, -60, -70, -80; T.C. A2WE	SA2388SW	Install diode across coil of hydraulic pump relay. Issued 11/24/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, 0-70, -80; T.C. A2WE	SA2701SW	Relocation of hydraulic pressure. Issued 12/22/77.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA265-40, -60, -70, -80; T.C. A2WE	SA2838SW	Installation of recognition lgihts. Issued 8/21/78.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2933SW	BKM pitot heat monitor system. Issued 3/16/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -80; T.C. A2WE	ST996SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
NA-265-40, -60, -80; T.C. A2WE	SA1957SW	Additional hydraulic pressure switch. Issued 3/3/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-60; T.C. A2WE	SA500CE	Installation of oxygen system. Amended 11/10/75.	CE	68765	Sabreliner Division Rockwell International St. Louis Int'l Airport 6161 Aviation Drive St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA501CE	Installation of portable SunAir H.F. transceiver Model SA-14DA. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-60; T.C. A2WE	SA502CE	Install a nine-place version No. 1 version No. 1-3 interior. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA503CE	Installation of electronic components package version A. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA522CE	Install 12-place interior. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA540CE	Installation of electronics components package version B. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA549CE	Installation of electronics components package version D. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA565CE	Install 8-place version 3 interior. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA596CE	Installation of electronics components package, version E. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA597CE	Installation of dual RCA AVQ-75 DME with hold feature. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA654CE	Installation of electronics components package, version F. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA685CE	Install a ten-place interior, version No. 4. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA705CE	Installation of electronics components package, version G. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA804CE	Installation of electronic components package, version H. Issued May 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA817CE	Install aislewise divan.	CE	33580	EPM Corporation P.O. Box 5978 Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA818NW	Installation of Goodyear brake assembly, P/N 9550338-1. Issued 8/1/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road South Seattle, WA 98108
NA-265-60; T.C. A2WE	SA838CE	Installation of electronics components package, version J. Issued August 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA839CE	Installation of ten-place interior, version No. 5. Issued August 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA896CE	Installation of electronic components package, version K. Amended 12/1/75.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA265-60; T.C. A2WE	SA958CE	Installation of 12-place interior Version No. 7. Amended 11/20/78.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA996CE	Installation of electronic components package, version L. Amended March 1974.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63134

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-60; T.C. A2WE	SA1012CE	Install interior, version No. 8. Issued April 1974.	CE	68765	Aviation Services Division Rockwell International Corp. Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1014CE	Cockpit voice and flight data recorder, altitude alerter system and encoding and weather radar. Amended November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1075CE	Aft lavatory auxiliary seat installation. Issued January 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1078CE	Aft lavatory and auxiliary L.H. installation. Issued February 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1092CE	Installation of electronic components package, version M. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1139CE	Install aft facing forward L.H. seat installation. Issued May 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1146CE	Interior installation, version No. 9. Issued July 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1148CE	Installation of electronic components package, version N. Issued 7/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1149CE	Installation of electronic components package, version P. Issued 7/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1182CE	Auxiliary seat and baggage area installation. Issued 11/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1191CE	Aisle facing seat and baggage area. Issued 1/6/76.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1221CE	Install interior, version No. 10. Issued May 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1242CE	Install Collins ADF-60A automatic direction finding and Intercontinental Dynamics Corp. RAD/BAR with voice terrain advisory system. Amended September 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1247CE	Forward lavatory L.H. installation. Issued July 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1339CE	Aft lavatory installation. Issued 7/6/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1367CE	Interior installation, Version No. 11. Issued 9/15/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1379CE	Install Collins FPC-75 GPWS, IDC SAT/TAS Collins ALT-55B radio altimeter and Wulfsberg Flitefone III provisions. Issued 10/18/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1385CE	Install electronic components package Version "R". Issued 11/15/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-60; T.C. A2WE	SA1386CE	Install electronics components package Version "Q". Issued 11/23/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1392CE	Install Global GNS-500A VLF/OMEGA navigation system. Issued 12/29/77.	CE	59270	Midcoast Aviation Services, Inc. Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1421CE	Install convertible baggage, aisle facing seat. Issued 6/12/78.	CE	59270	Midcoast Aviation Services Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1434CE	Interior installation Version No. 12. Issued 9/19/78.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63775
NA-265-60; T.C. A2WE	SA1476SW	Normalized angle of attack indicating system. Amended 8/27/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
NA-265-60; T.C. A2WE	SA1811WE	Installation of reinforced structure and certain components in partial provision for UCAR configuration. Reissued 7/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60; T.C. A2WE	SA1912WE	Installation of nose boom extension and/or doppler radome and fairing. Amended 5/8/69.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
NA-265-60; T.C. A2WE	SA2878SW	Install two two-place side facing couches. Issued 12/5/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
NA-265-60, Serial No. 306-23 and subsequent; T.C. A2WE	SA3042WE	Installation of engine fuel drain sump tank. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
NA-265-60, -70; T.C. A2WE	SA737CE	Installation of Solar APU Model T-62T-39 and T-62T-39Y. Reissued 6/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60, -80; T.C. A2WE	SA1129CE	Installation of IFR delivery package. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International Corp. 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60, -80; T.C. A2WE	SA1479CE	Installation of forward auxiliary fuel cell (56 gallons). Amended 4/30/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-65; T.C. A2WE	SA1537CE	Installation of Solar Model T-62T-40C auxiliary power unit (APU). Issued 12/29/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA816CE	H.F. antenna installation. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA824CE	Audible hydraulic pressure warning system. Issued February 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA868CE	Installation of Trams BTI-600 battery temperature indicator system. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA869CE	Installation of RCA AVQ-21 weather radar. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA870CE	Installation of Collins ALT-50 radio altimeter. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA969CE	Installation of 7-passenger interior. Issued November 1973.	CE	68765	North American Rockwell Aviation Services Division Lambert Field St. Louis, MO 63145

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-70; T.C. A2WE	SA1248CE	Installation of Collins AP104/FD109H automatic flight control system. Issued November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA2766WE	Replacement of existing engines with GE CF700-2D-2 fan jet engines. Issued 10/31/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-80; T.C. A2WE	SA995CE	Install electronic components package, version A. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA997CE	Install interior, version No. 2. Issued February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1015CE	Installation of electronic components package Version "C". Amended 12/22/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1026CE	Install interior, version No. 3. Issued May 1974.	CE	68765	Aviation Services Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1028CE	Installation of electronic components package, version B. Issued 1/20/75.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1043CE	Installation of electronic components package, version D. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1065CE	Installation of electronic components package, version E. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1066CE	Installation of Teledyne angle of attack indicating system SL112B1400. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1067CE	Auxiliary seat installation aft lavatory. Issued November 1974.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1074CE	Auxiliary seat installation. Issued January 1975.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1100CE	Interior installation No. 4. Issued March 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1101CE	Installation of cockpit voice recorder and flight data recorder. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1132CE	Install aft lavatory auxiliary seat. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1133CE	Interior installation, FAA Airways Checker. Issued July 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1142CE	Interior installation, version No. 5. Issued June 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1249CE	Interior installation, version No. 6 (wide body). Issued August 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-80; T.C. A2WE	SA1272CE	Interior installation, version No. 7.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1274CE	Installation of electronic components package, Version "F". Amended 6/21/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1275CE	Interior installation, version No. 8.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1288CE	Interior installation, version No. 9. Issued November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1293CE	Commode installation - aft lavatory. Issued January 1977.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1323CE	Interior installation, No. 10. Issued May 1977.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1329CE	Installation of Collins NCS-31A navigation control system with dual control heads, HI-350 remote compass and Collins 728D-5 HF transceiver system. Issued 5/20/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1337CE	Installation of Intercontinental Dynamics cCorp. vertical navigation system. Issued 5/21/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1342CE	Install electronics components package, Version "G". Issued 8/9/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1374CE	Installation of 800 VA and 2500 VA static inverters. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA265-80; T.C. A2WE	SA1387CE	Passenger compartment wiring provisions installation. Issued 11/30/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA3974WE	Installation of Litton LTN-72R area navigation system. Issued 7/6/79.	WE	11620	Area Equipment Company, Inc. 7707-1/2 Woodley Avenue Building 901 Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
560F; T.C. 2A4	SA1130CE	Installation of Collins Radio Group electric trim system. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
560-F, 680, 680-E, 680F, 720; T.C. 2A4	SA290GL	Install Cleveland conversion kit No. 199-74 on listed models which use MIL-H-5606 brake fluid (red oil) or kit No. 199-74A on listed models which use Skydrol brake fluid (nonpetroleum base). Issued 12/26/78.	GL	23260	Cleveland Wheels & Brakes Parker Hannifin Corp. 1160 Center Road Avon, OH 44011
560F, 680, 680F; T.C. 2A4	SA3405WE	Installation of fuselage fuel tank. Issued 5/24/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
560F, 680E, 680F, 680FL, 680FLP, 680W; T.C. 2A4	SA3477WE	Replacement installation of tail cone assembly. Issued 9/7/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
560F, 680, 680E, 680F, 680FL, 680FLP, 680W; T.C. 2A4	SA3493WE	Replacement installation of vertical tip assembly. Issued 10/3/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
560F, 680F; T.C. 2A4	SA3517WE	Installation of cockpit overhead windows. Issued 12/23/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
600 Series; T.C. 2A4	SA1-83	Camera in fuselage tail section.	GL	73884	Southern Ohio Aviation Company P.O. Box 367 Vandalia, OH 45371
600, S2D; T.C. A3SW, A4SW	SA113NW	Installation of EAC 3D40-401 AG-100-2 propeller with 4M121-1 propeller governor. Issued 5/24/74.	NW	33000	Efficiency Aircraft P.O. Box 37 Kent, WA 98031
680 Series; T.C. 2A4	SA1-68	Dual Wilcox ADF radio loop antenna.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
680 Series; T.C. 2A4	SA1-231	Bendix fuel flow indicating system.	GL	37830	General Tire & Rubber Company 1708 Englewood Avenue Akron, OH 44309
680 Series;	SA1-249	Fuel flow indicating system.	NE	61240	National Lead Company P.O. Box 365 Stratford, CT 06497
680 Series; T.C. 2A4	SA1-300	Bendix fuel flow indicating system.	EA	12700	Lycoming Division Avco Manufacturing Company Service Hangar Montoursville, PA 17754
680 Series; T.C. 2A4	SA1-442	ANC-3A computer and ANO-C2 or ANC-D2 controller with Lear L2C autopilot.	EA	31050	Dynavia Corporation 3021 West Clay Street Richmond, VA 23219
680 Series; T.C. 2A4	SA1-476	SP-3 autopilot EB2597034.	EA	74574	Sperry Gyroscope Company Division of Sperry Rand Corp. MacArthur Field Ronkonkoma, NY 11779
680 Series; T.C. 2A4	SA1-552	Pesco 2 P-R400-BRD fuel pumps.	SW	28590	Island Service Division Dallas Airmotive, Inc. Galveston, TX 77550
680 Series; T.C. 2A4	SA3-32	AP-101 automatic pilot.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA3-112	Oil separators in vacuum pump outlet lines.	GL	16886	Bohling Aircraft Corporation 5324 West 63rd Street Chicago, IL 60607
680 Series; T.C. 2A4	SA3-120	Relocation of aircraft battery to hose station 8. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
680 Series; T.C. 2A4	SA3-145	AP-101 automatic pilot.	GL	59635	Minnesota Airmotive, Inc. Wold-Chamberlain Field Minneapolis, MN 55450
680 Series; T.C. 2A4	SA3-301	Hand-operated hydraulic pump deactivated or removed and replaced with electric-driven equivalent.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
680 Series; T.C. 2A4	SA3-349	Bendix fuel flow indicator system.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
680 Series; T.C. 2A4	SA3-350	AP-11 automatic pilot.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
680 Series; T.C. 2A4	SA4-240	Electric hydraulic pump.	WE	61670	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
680 Series; T.C. 2A4	SA4-530	Radio rack aft of baggage compartment.	RM	05940	Aircraft Radio and Accessory Company, Inc. Stapleton Airfield Denver, CO 80202
680 Series; T.C. 2A4	SA4-551	L-102B automatic pilot.	WE	49858	Lear, Inc. 3171 South Bundy Drive Santa Monica, CA 90406
680 Series; T.C. 2A4	SA65SW	Support and opening in bottom of fuselage for Aeropath camera.	EA	02700	Aero Service Corporation 210 East Courtland Street Philadelphia, PA 19104
680 Series; T.C. 2A4	SA164EA	Airborne profile recorder probe on nose of fuselage.	EA	02700	Aero Service Corporation 210 East Courtland Street Philadelphia, PA 19104
680 Series; T.C. 2A4	SA240CE	Unfeathering accumulator.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
680 Series; T.C. 2A4	SA290SW	RC-9 aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA391EA	Turbine bleed type pneumatic deicer system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
680 Series; T.C. 2A4	SA408SW	RC-8 aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA418SW	Seat-passenger lavatory combination.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA439SW	TC-8 aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA439WE	Lycoming IGSO-480-A1D6 engines in lieu of original GSO-480-B1A6. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monca, CA 90405
680 Series; T.C. 2A4	SA455EA	Propeller deicing system.	NE	80385	United Aircraft Corporation Hamilton Standard Division Windsor Locks, CT 06096
680 Series; T.C. 2A4	SA473SW	AP-103E/FD108 automatic flight control system.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA478SW	RC-7, -9 aerial survey cameras.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA520SW	Autopilot M-4C.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
680 Series; T.C. 2A4	SA523WE	Motorola L-2C autopilot with M-4 autopilot servo clutches and without approach coupler.	WE	70098	Santa Monica Aviation, Inc. 3011 Airport Avenue Santa Monica, CA 90405
680 Series; T.C. 2A4	SA577SW	Conversion of RC-8 camera to RMK-A-15/23.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA606SO	Installation of extended window L.H. and R.H. side of cabin. Amended 10/22/68.	SO	05580	Aircraft Modification Engineering Company P.O. Box 945 Vero Beach, FL 32960
680 Series; T.C. 2A4	SA633WE	Reroute powerplant and aileron control cables.	WE	70098	Santa Monica Aviation, Inc. 3011 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
680 Series; T.C. 2A4	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock.	EA	17500	Brittain Industries, Inc. Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
680 Series; T.C. 2A4	SA665SW	deHavilland airborne profile recorder in aft fuselage.	EA	04515	Air Carrier Service Corp. 2233 Wisconsin Avenue, NW Washington, D.C. 20007
680 Series; T.C. 2A4	SA684SW	AP103F/FD-108 automatic flight control system.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA710SW	PT6A-20 engine.	SW	77110	Swearingen Aircraft P.O. Box 6904 San Antonio, TX 78209
680 Series; T.C. 2A4	SA1155WE	Camera.	NW	85123	Western Aerial Contractors, Inc. Route 1, Box 740 Eugene, OR 97401
680, 680E, 720; T.C. 2A4	SA660WE	Installation of HRD type fire extinguishing system. Amended 7/11/77.	WE	43190	HTL Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
680, 680-E, -F, -FL, -FL(P), T, V, W, 681, 685, 690, 720; T.C. 2A4	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Ic. 18145 Judy Street Castro Valley, CA 94546
680E; T.C. 2A4	SA450EA	Modification to lower surface of fuselage to accommodate Wild Camera Model RC5 or RC8. Amended 2/9/68.	EA	52060	Long Island Airways P.O. Box 828 Ronkonkoma, NY 11779
680E; T.C. 2A4	SA1782WE	Installation of drooped ailerons drooped wing leading edge, stall fence and rudder seal. Reissued 1/5/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
680F; T.C. 2A4	SA2691WE	Installation ofLycoming IO-720-B1B turbocharged engine. Reissued 7/22/74.	WE	69220	Mr. R P M Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680F; T.C. 2A4	SA3299SW-D	Mitchell automatic flight system AK772, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/21/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F; T.C. 2A4	SA3300SW-D	Mitchell automatic flight system AK773, consisting of Century IV autopilot, consisting of Century IV flight director autopilot with optional remote annunciator. Issued 8/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F, 680FL; T.C. 2A4	SA155CE	Intallation of Honeywell H-14 adaptive autopilot.	CE	48250	King Radio Corpratin 400 North Rogers Road Olathe, KS 66061
680FL; T.C. 2A4	SA2EU	Cargo door modification	EU	08440	ALAR-Empresa Iberica de Material Aeronautico Ld Lisbon, Portugal
680FL; T.C. 2A4	SA102GL	Installation of baggage compartment. Issued 12/29/75.	GL	31362	Eagle Aviation, Inc. Bishop Airport Flint, MI 48507
680FL; T.C. 2A4	SA929SW	Automatic flight system AK270 consisting of Century III autopilot with optional automatic pitch trim. radio and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
680FL; T.C. 2A4	SA1089SW	59-gallon wing auxiliary fuel tank.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680FL; T.C. 2A4	SA1094SW	RD-8, RC-9, and RMK-A-15/23 camera.	SW	47770	Kerr Aviation Service, Inc. Box 399 Bethany, OK 73008
680FL; T.C. 2A4	SA1095SW	installation of Bendix ANA-12A.	SW	47770	Kerr Aviation Service,Inc. Box 399 Bethany, OK 73008
680FL; T.C. 2A4	SA1358SW	Dual or single camera installation and navigation sights. Issued 8/25/71.	SW	42825	A.D. Howard, Jr. 6817 Northwest 23rd Street Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
680FL; T.C. 2A4	SA2448SW	Extension of baggage area to F.S. 308, encompassing re-routing of powerplant and aileron control cables in baggage compartment area. Issued 4/7/77.	SW	25260	Harry B. Combs, Jr. P.O. Box 4580 Waco, TX 76101
680FL, FL(P); T.C. 2A4	SA806SW	Flap close-out strips.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
680FL, 680FL(P), 680(F); T.C. 2A4	SA2891WE	Installation of Lycoming IO-720-B1B turbocharged engine. Reissued 8/2/74.	WE	69220	Mr. RPM, Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680FL, 680FL(P); T.C. 2A4	SA2903SW	Installation of wing flap gap seals. Issued 1/25/79.	SW	69218	Mr. R.P.M., Inc. P.O. Box 40414 Everman Branch Fort Worth, TX 76140
680FL(P); T.C. 2A4	SA3322WE	Installation of cockpit overhead windows. Issued 1/18/77.	WE	69220	Mr. RPM, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680FL(P), T, V, W, 681; T.C. 2A4	SA1261SW	Camera installation. Issued 3/11/71.	SW	30530	Downtown Airpark, Inc. Box 94846 Bethany, OK 73109
680FL(P), 680T, V, W, 681, 690; T.C. 2A4	SA1584SW	Aerial survey camera. Issued 1/3/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 68))*
680FL, 685; T.C. 2A4	SA1649SW	Camera installation. Issued 5/1/73.	SW	42825	A.D. Howard, Jr. 817 Northwest 43rd Street Bethany, OK 73008
680FL, 680FL(P), 680T, V, W, 681, 685A, 690, 690A; T.C. 2A4	SA1977SW	Modification of fuselage for installation of doppler antenna. Issued 5/6/75.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Oklahoma City, OK 73008
680T, V, W; T.C. 2A4	SA887SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
680T, 680V, 680W, 681; T.C. 2A4	SA895GL	Installation of Grimes three light strobe kit. Issued 1/20/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
680T, V, W, 681; T.C. 2A4	SA1926SW	Fuel purge system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681; T.C. 2A4	SA1962SW	Generator over-voltage/over-current protection. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681, 690; T.C. 2A4	SA1705SW	Freon air conditioning system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680V, W; T.C. 2A4	SA1529SW	Modification of hydraulic system and air conditioning pressurization system. Issued 7/25/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680V, W; T.C. 2A4	SA1530SW	Modify existing 3000 psi hydraulic system to 1000 psi hydraulic system. Issued 12/23/72.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680W; T.C. 2A4	SA3469WE	Installation of AiResearch TPE 331-6-252M engines. Amended 2/27/78.	WE	07502	AiResearch Manufacturing Co. of Arizona 402 South 36th Street P.O. Box 5217 Phoenix, AZ 85010
680, 720 Series; T.C. 2A4	SA37CE	C210403 governor.	SW	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
680, 720 Series; T.C. 2A4	SA39CE	C210310 governor.	SW	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
681; T.C. 2A4	SA1005CE	Installation of IAD battery temperature monitor and over-temperature warning system. Issued March 1974.	CE	05250	Aircraft Instrument & Development, Inc. 317 East Lewis Wichita, KS 67202

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
685 Series; T.C. 2A4	SA17GL	Installation of Bendix FCS-810 autopilot. Issued 4/12/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
685 Series; T.C. 2A4	SA56GL	Install wheel assembly P/N 3-1174 and brake assembly P/N 2-993-1. Issued 7/23/74.	GL	38504	B.F. Goodrich Engineered Systems Company Division of B.F. Goodrich Co. P.O. Box 340 Troy, OH 45373
685; T.C. 2A4	SA155RM	Installation of Singer SKK-1000 doppler navigation system, SKQ-601 dead reckoning computer, and Sperry C-12 compass system. Issued 10/4/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
685 Series; T.C. 2A4	SA878SO	Installation of Silver Instruments Fueltron III, fuel flow gages. Issued 1/21/76.	SO	12493	Atlantic Aero, Inc. P.O. Box 8946 Grensboro, NC 27410
685; T.C. 2A4	SA3849WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 1/30/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
690 Series; T.C. 2A4	SA26GL	Installation of Bendix M-4C autopilot. Issued 7/2/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O.Box 1060 Rockford, IL 61109
690 Series; T.C. 2A4	SA530SO	Installaton of manual electric trim system. Issued 2/28/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
690 Series; T.C. 2A4	SA2606WE	Installation of Lear AFC-70 autopilot. Amended 7/20/73.	WE	49850	LearAvia Corporation Avionce Division 14505 Mt. Anderson Avenue Reno, NV 89510
690 Series; T.C. 2A6	SA2727WE	Installation of LearAvia electric pitch trim system. Issued 7/20/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510
690, 690A; T.C. 2A4	SA74GL	Install wing tip recognition lights. Issued 3/21/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
690, 690A; T.C. 2A4	SA85SW	Installation of auxiliary bleed air shut-off and fuselage temperature monitoring system. Reissued 1/30/78.	GL	68768	Rockwell Aviation Service Division 3300 Love Field Drive Dallas, TX 75235
690, 690A; T.C. 2A4	SA1059SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid batteries. Issued 3/29/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
690, 690A, 690B; T.C. 2A4	SA2577WE	Installation of flight FCS-105 flight control system. Amended 8/14/78.	CE	24250	Collins Radio Group Rockwell International 400 Collins Raod, N.E. Cedar Rapids, IA 52406
690A; T.C. 2A4	SA79GL	Instal Bendix M4D autopilot system. Issued 4/18/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61101
690A; T.C. 2A4	SA1009CE	Install Model KFC-300 automatic flight control system (autopilot and flight director). Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
690A; T.C. 2A4	SA1011CE	Install Model KVN-395 vertical navigation computer for operation with Model KFC-300 automatic flight control system. Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
690A; T.C. 2A4	SA1873SW	Sperry SPZ-200/STARS IVC. Issued 5/1/74.	SW	30530	Downtown Airpark, Inc. P.O. Box 94646 Oklahoma City, OK 73109
690A; T.C. 2A4	SA1876SW	AP-106 autopilot and manual electric trim. Issued 4/29/74.	SW	24252	Collins Radio Company Addison Airport Addison, TX 75001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
690A, 690B; T.C. 2A4	SA1024SO	Installation of AiResearch TPE331-5-252K engines in Model 690A replacing AiResearch TPE331-5-251K engines; installation of TPE331-5-252K engines in Model 690B. Amended 1/9/79.	SO	37087	The Garrett Corporation Route 1, Box 60 Bush Field Agusta, GA 30906
690C; T.C. 2A4	SA405GL	Installation of a Collins LRN 70 omega navigation system. Issued 5/13/80.	GL	33231	Electrosonics Division AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
720; T.C. 2A4	SA1-553	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace ad Defense Products 500 South Main Street Akron, OH 45373
720; T.C. 2A4	SA395SW	Four-place seating capacity.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
111, 112; T.C. A11SO, A12SO	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
111, 112; T.C. A11SO, A12SO	SA1502SW	Mitchell automatic flight system AK364 consisting of Century I autopilot with optional omni tracker. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1503SW	Mitchell automatic flight system AK 363 consisting of Century IIB autopilot with optional radio coupler. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1504SW	Mitchell automatic flight system AK362 consisting of Century III with optional command/electric pitch trim, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1505SW	Mitchell command/electric pitch trim. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1728SW	Cabin air scoop. Issued 9/13/73.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
112; T.C. A12SO	SA243NW	Installation of Lycoming IO-540 engine with 3-bladed Hoffman, 3-bladed Hartzell, or 2-bladed Hartzell propeller. Amended 5/26/78.	NW	52625	Machen, Inc. S. 3408 Davison Boulevard Spokane, WA 99204
112; T.C. A11SO, A12SO	SA2900WE	Installation of Pathfinder autopilots. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Asler Street Torrance, CA 90505
112; T.C. A12SO	SA3155WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 4/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torranc, CA 90505
112, 112B, 112TC, 112TCA, 114, 114A; T.C. A12SO	SA237GL	Install leading edge landing lights. Amended 1/24/80.	GL	37182	General Aviation, Inc. Lost Nation Airport Willoughby, OH 44094
112, 112B, 112TC, 112TCA, 114; T.C. A12SO	SA1229CE	Install King Model KFC-200 2-axis (3 optional) flight control system with KCS 55/55A compass and a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller; or stand alone electric trim. Amended 1/18/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
112, 114; T.C. A12SO	SA3120SW-D	Automatic flight system AK572 consisting of Century I autopilot with optional omni tracker. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A12SO	SA3121SW-D	Automatic flight system AK573 consisting of Century IIB autopilot with optional radio coupler. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
112, 114; T.C. A1280	SA3122SW-D	Automatic flight system AK574 consisting of Century III autopilot with optional radio and glide slope Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A180	SA3[illegible]SW-D	Mitchel command electric trim AK582. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112B, 112TC, 112TCA, 114; T.C. A1280	SA3778WE	Installation of retractable landing lights. Issued 11/8/78.	WE	47070	Fred W. Jones 2901 East Spring Street Long Beach, CA 90806
112TC, 112TCA; T.C. A1280	SA3787WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
112TC, 112TCA; T.C. A1280	SA3920WE	Installation of fueltron IG or IP digital fuel flow and totalizer system. Amended 1/9/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
114; T.C. A1280	SA300CE	Installation of propeller governors on single and twin engine aircraft P/N J210345. Issued 5/7/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
114; T.C. A1280	SA3727WE	Installation of SDI Model CFS-1000, -1001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
114; T.C. A1280	SA3308WE	Modification of aileron control system by addition of aileron centering spring and installation of Pathfinder autopilot system and/or pitch trim systems. Issued 1/7/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
114; T.C. A1280	SA3727WE	Installation of SDI Model CFS-1000 fuel flow indicator. Issued 9/6/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SIKORSKY AIRCRAFT

Aircraft Make, Model & T.C. No.	STC No.	Description	IG	STC Code	STC Holder
VS-44-A; T.C. 752	SA4-1105	Ceconite 101 covering of ailerons and flaps.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
VS-44-A; T.C. 752	SA1351WE	Replae exsting fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
VS-44-A; T.C. 752	SA2666WE	Ceconite 102 material covering of ailerons and flaps. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S-51; T.C. H-2	SA4-180	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 West Magnolia Burbank, CA 91505
S-55; T.C. 1H4	SH4-161	Pratt & Whitney 101-79 engine mount replaced.	WE	83500	Vibration Isolation Products, Inc. 212 West Magnolia Burbank, CA 91505
S-55; T.C. 1H4	SH449NW	Incorporation of a weighing system for external load operations. Issued 5/19/77.	NW	56890	Measurement Systems International 619 South Riverside Drive Seattle, WA 98108
S-55, S-55B, S-55C; T.C. 1H4	SH127WE	Installation of AiResearch TSE-331-3U-303N engine and related changes. Reissued 1/30/74.	WE	42010	Helitec Corporation 4930 East Falcon Drive Mesa, AZ 85205
S-55, S-55B, S-55C; T.C. 1H4	SH271WE	Installation of cabin-mounted spray tank and external spray booms for agricultural purposes. Issued 4/29/80.	WE	42010	Helitec Corporation 4930 East Falcon Drive Mesa, AZ 85205
S-55, S-55B, S-55C, H-19; T.C. 1H4, HR1SO	SH1072SO	Installation of dust boot retainer rings (in rotor head dampers). Issued 5/18/79.	SO	61890	Orlando Helicopter Airways, Inc. P.O. Box 2802 Orlando, FL 32802
S-55, S-55C; T.C. 1H4	SH51WE	Installation of George M. Adams Model DGA-2000 wheel assembly.	WE	16860	Malcolm E. Bodell 2304 Pennsylvania Avenue Torrance, CA 90501
S-55, S-55C; T.C. 1H4	SH71EA	South Wind heater 8259-A.	NE	49200	Laboratory for Electronics, Inc. 1079 Commonwealth Avenue Boston, MA 02109
S-55, S-55C; T.C. 1H4	SH150WE	Installation of Chadwick electronic weighing system C-46. Issued 6/1/72.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
S-55 Series, S-58 Series; T.C. 1H4, 1H11	SH770NW	Installation of a weighing system. Issued 5/15/79.	NW	61842	Onboard Weighin System P.O. Box 03413 Portland, OR 97203
S55B; T.C. 1H4	SH125WE	Installation of AiResearch TSE-331-3U-303N engine and related changes. (Limited to serial number 55607). Amended 6/25/71.	WE	14000	Aviation Specialties, Inc 4930 East Falcon Drive Mesa, AZ 85205
S-58 (Military Versions HSS, HUS, H-34); T.C. 1H11	SH268WE	Installation of stainless steel fire shields around aluminum engine mount fittings (P/N S1620-61435) of HSS, HUS, H-34 military series helicopters. Issued 3/26/80.	WE	77578	T.B.M. Incorporated P.O. Box 668 Tulare, CA 93274
S-58; T.C. 1H11	SH453NW	Incorporation of a weighing system for external load operations. Issued 6/7/77.	NW	56890	Measurement Systems International 601 South Riverside Drive Seattle, WA 98108
S-58A thru S-58J, S-58B/T, S-58D/T, S-58E/T; T.C. 1H11	SH142WE	Installation of electronic weighing system C-40. Issued 3/20/72.	NW	20750	Chadwick, Inc 4375 Southwest 142nd Avenue Beaverton, OR 97005
S-58BT, S-58DT, S-58ET, S-58FT, S-58HT, S-58JT; T.C. 1H11	SH3NE	Norton AC3093X radome installation and Bendix RDR 110 radar system installation. Issued 3/5/74.	NE	62031	Oxford Avionics, Inc. 288 Christian Street Oxford Airport Oxford, CT 06483
S-58BT, -58DT, -58ET, -58FT, -58HT, -58JT; T.C. 1H11	SA77GL	Installation of Bendix weather radar RDR-1200. Amended 5/15/75.	GL	21700	Chicago Helicopter Airways, Inc. 5315 West 63rd Street Chicago, IL 60638

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S58BT, S58DT, S58ET; T.C. 1H11	SH1194EA	Conversion from original 12 passenger configuration to a 9 passenger configuration. Issued 4/22/80.	EA	11950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
S-58D; T.C. 1H11	SH206GL	Installation of HUS-1 titanium firewall with intumescent coating. Issued 12/30/77.	GL	59370	Midwest Helicopter Airways, Inc. P.O. Box 255 Lyons, IL 60534
S-58E; T.C. 1H11	SH109GL	Installation of CH-34A titanium firewall with intumescent coating. Issued 2/17/76.	GL	49320	Lake Line Helicopters, Inc. Southport Airport Rosemount, MN 55068
S-61; T.C. 1H15	SH413NW	Installation of Model SI-150-16 system. Reissued 4/19/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
S-61L; T.C. 1H15	SH33WE	Radio navigation equipment.	WE	52071	Los Angeles Airways, Inc. 5901 West Imperial Highway Los Angeles, CA 90009
S-61L; T.C. 1H15	SH49WE	Dual radio navigation system.	WE	52071	Los Angeles Airways, Inc. 5901 West Imperial Highway Los Angeles, CA 9009
S-61L; T.C. 1H15	SH91WE	Electrical system modification. Amended 4/29/69.	WE	52071	Los Angeles Airways, Inc. 5901 West Imperial Highway Los Angeles, CA 90009
S-61L, -61N; T.C. 1H15	SH151WE	Installation of Chadwick electronic weighing system C-43. Issued 6/26/72.	NW	20750	Chadwick, Inc. 435 Southwest 142nd Avenue Beaverton, OR 97005
S-61L, -61N; T.C. 1H15	SA836EA	Installation of engine air inlet screens. Issued 8/13/70.	NE	71730	Sikorsky Aircraft Div. United Aircraft Corporation Stratford, CT 06602
S-61L, -61N, S-62A; T.C. 1H15, 1H13	SH155WE	Installation of battery temperature monitor system. Amended 11/2/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
S-61N; T.C. 1H15	SH81WE	Installation of engine air inlet screens. Reissued 11/9/77.	WE	44262	International Helicopter Parts, Inc. P.O. Box 2449 Oakland, CA 94614
S-61N; T.C. 1H15	SH593EA	Installation of Sperry C14A gyrosyn compass system.	NE	07498	AiResearch Aviation MacArthur Airport 3332 Smithtown Avenue Ronkonkoma, L.I., NY 11779
S-62A; T.C. 1H13	SH196WE	Installation of 10 (ten) passenger interior arrangement. Issued 12/7/76.	WE	17200	Briles Wing & Helicopter, Inc. 3011 Airport Avenue Santa Monica, CA 90405
S-62A; T.C. 1H13	SH1790SW	Foxtronics/Tramm BTI-600 nickel cadmium battery temperature. Issued 1/29/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
S-64 Series; T.C. H6EA	SH546NW	Installation of load cell monitor system. Issued 12/28/77.	NW	56890	Measurement Systems International 619 South Riverside Drive Seattle, WA 98108
S-64 Series; T.C. H6EA	SH607NW	Installation of mechanical release system for external cargo hook. Issued 5/31/78.	NW	52685	McCallister Engineering Enterprises 9739 South 208th Street Kent, WA 98031
S-64E; T.C. H6EA	SH579NW	Install Vickers hoist pump, APU starter motor and handpump for rotor brake system. Issued 3/24/78.	NW	33670	Erickson Air-Crane Company P.O. Box 3247 Central Point, OR 97502
S-64E; T.C. H6EA	SH580NW	Install Vickers hoist pump, APU starter motor and handpump for rotor brake system. Issued 3/24/78.	NW	33670	Erickson Air-Crane Company P.O. Box 3247 Central Point, OR 97502
S-64E; T.C. H6EA	SH581NW	Install Vickers hoist pump, APU starter motor and handpump for rotor brake system. Issued 3/24/78.	NW	33670	Erickson Air-Crane Company P.O. Box 3247 Central POint, OR 97520
S-64E; T.C. H6EA	SH606NW	Install AiResearch motor driven fan for transmission cooling system. Issued 6/22/78.	NW	33670	Erickson Air Crane Company P.O. Box 3247 Central Point, OR 97502
S-64 Series; T.C. H6EA	SH607NW	Install mechanical release system for external cargo hook. Issued 5/31/78.	NW	52685	McAllister Engineering Enterprises 9739 South 208th Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S-64E; T.C. H6EA	SA3894WE	Installation of hoist pump (yoke type), P/N ACH60552L6. Issued 4/2/79.	WE	01770	Aero-Craft Hydraulics, Inc. 2428 West Carson Street Torrance, CA 90501
S-64E; T.C. H6EA	SA3895WE	Installation of auxiliary power unit (APU) starter motor, P/N ACH-3911-205SPCL. Issued 4/2/79.	WE	01770	Aero-Craft Hydraulics, Inc. 2428 West Carson Street Torrance, CA 90501
S-76A; T.C. H1NE	SH270WE	Installation of a Collins LRN-80 VLF/Omega navigation system as a means of navigation for enroute navigation within the 48 contiguous U.S. and D.C. Issued 4/4/80.	WE	24205	Collins General Aviation Division 3000 Airway Avenue Costa Mesa, AZ 92626
S-76A; T.C. H1NE	SH286GL	Install Norton Co. radome P/N AD-4082X-2 (Sikorsky P/N 76600-02110-101) or Norton radome P/N AD-4082X-10 (Sikorsky P/N 76600-02110-102). Amended 12/20/79.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AS-350B; T.C. H9EU	SH2937SW	Dual non-stowable litter kit. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2938SW	Electric gyro instruments. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2972SW	Net assemblies in side baggage compartment. Issued 4/11/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2973SW	Minimum required external markings. Issued 4/11/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4016SW	Installation of hourmeter. Issued 7/13/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 76067
AS-350B; T.C. H9EU	SH4032SW	Air Cruisers Model D24724 emergency flotation gear. Issued 8/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4044SW	Patient supplemental oxygen supply. Issued 1/18/80.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4048SW	Installation of a storage pouch. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B, AS-350C, AS-350D; T.C. H9EU	SH183RM	Installation of electric driven air-conditioner system. Issued 9/5/79.	RM	45750	J B Systems 120 Bowen Circle Longmont, CO 80501
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH189RM	Installation of belt driven air-conditioner system. Amended 1/10/80.	RM	01950	Aero Engineering Corporation 2678 Delta Drive Colorado Springs, CO 80910
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH2875SW	Electric turn and slip indicator. Issued 4/23/80.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH4086SW	Cabin ventilation system. Issued 2/27/80.	SW	03010	Aerospataile Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH748NW	Installation of a weighing system. Issued 4/12/79.	NW	52685	McAllister Engineering Enterprises 9739 South 208th Street Kent, WA 98031
AS-350C; T.C. H9EU	SH2814SW	Chip detectors. Issued 7/14/78.	SW	03010	Aerospatiale Helicopters, Inc. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH2817SW	Install net assemblies in side baggage compartments. Issued 7/18/78.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH2819SW	Minimum required external markings. Issued 7/19/78.	SW	03010	Aerospatiale Helicopters, Inc. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-305C, D, D-1; T.C. H9EU	SH740NW	Installation of a weighing system. Issued 4/6/79.	NW	56890	Measurement Systems International 580 South Lucille Street Seattle, WA 98108
AS-350C, D, D-1; T.C. H9EU	SH771NW	Installation of a weighing system. Issued 5/15/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
AS-350C, D, D-1; T.C. H9EU	SH2866SW	Installation of hourmeter. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2886SW	Installation of supplemental strobe lights. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2895SW	Installation of standard interior. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2913SW	Installation of reversible dual bench seat. Issued 2/21/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2914SW	Installation of dual non-stowable litter kit. Issued 2/21/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AS-350C, D, D1; T.C. H9EU	SH2915SW	Modify damping capacity accumulator, P/N 350A54.1006.00. Issued 2/22/79	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2917SW	Install electric gyro instruments. Issued 2/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2929SW	Install TEDECO fuel flow chip detector. Issued 3/9/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4043SW	Patient supplemental oxygen supply. Issued 1/18/80.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4049SW	Installation of a storage pouch. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350D; T.C. H9EU	SH1543CE	Installation of Collins APS-841H helicopter automatic flight control systems. Amended 4/22/80.	CE	24250	Collins Avionic Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
AS-350D, -350D1; T.C. H9EU	SH1189EA	Installation of Aircraft Parts (APC) starter-generator, P/N 150SG114Q. Issued 3/26/80.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SWEARINGEN AVIATION CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA26T; T.C. A5SW	SA418SO	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C. A5SW	SA461SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C, A5SW	SA571SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation each engine is limited to a maximum of 550 SHP. Issued 12/14/73.	SO	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
SA26T; T.C. A5SW	SA600WE	Install Hoskins Twilighter Mk IIIq supplemental lighting system with Model P wing tip and Model K tail light.	GL	42625	Hoskins, Inc. 34 North Bennett Geneva, IL 60134
SA26T; T.C. A5SW	SA764SW	Bendix M4C autopilot flight control system.	SO	15475	The Bendix Corporation P.O. Box 23430 Fort Lauderdale, FL 33309
SA26T; T.C. A5SW	SA1464WE	Installation of supporting structure and placards only for avionic components in the aft compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26T; T.C. A5SW	SA1465WE	Installation of supporting structure and placards only for avionic components in forward compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26-T, SA26-AT, (Merlin II); T.C. A5SW	SA600CE	Install Hoskins Twilighter Mk III supplemental lighting system with Model P wing tip and Model K tail light. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
SA26-T, SA26-AT, (Merlin II); T.C. A5SW	SA3057WE	Installation of fuel tank boost pump. Issued 7/17/75.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA26-T, SA26-AT, Merlin II; T.C. A5SW	SA3465WE	Installation of recognition light assembly on the horizontal stabilizer. Issued 8/8/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
SA26-T, 26-AT, 226-T, 226-AT; T.C. A5SW	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SA226T; T.C. A5SW	SA1078SO	Installation of Bendix FCS-8700 automatic flight control system. Issued 6/5/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-T, SA226-AT; T.C. A5SW	SA254GL	Installation of emergency/continuous water-alcohol injection system. Amended 10/3/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
SA226-T, SA226-AT; T.C. A5SW	SA273GL	Installation of a Scenic exhaust assembly, P/N YR-12013 in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-T, SA226-AT; T.C. A5SW	SA613AL	Install nose wheel steering lock system. Issued 6/3/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502
SA226-T, SA226-AT; T.C. A5SW	SA2909WE	Installation of fuel tank boost pump. Amended 8/12/75.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA226-T, SA226-AT; T.C. A5SW	SA3481WE	Installation of recognition light on the horizontal stabilizer. Issued 9/14/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA226-TC; T.C. A8SW	SA279GL	Installation of emergency/continuous water-alcohol injection system. Issued 11/1/78.	GL	07503	AiReserach Aviation Company Capital Airport Springfield, IL 62705
SA226-TC; T.C. A8SW	SA189GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA615AL	Install nose wheel steering lock system. Issued 6/21/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502
SA226-TC; T.C. A8SW	SA1068CE	Installation of Collins Radio Co. AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-TC; T.C. A8SW	SA1582CE	Installation of Collins FCS-150 automatic flight control system. Issued 4/2/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
SA226-TC; T.C. A8SW	SA2910WE	Installation of fuel tank boost pump. Issued 7/23/74.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA226-TC; T.C. A8SW	SA3482WE	Installation of recognition light assembly on the horizontal stabilizer. Issued 9/14/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
SA226T (S/N T-201 and up), SA226AT (S/N AT-001 and up); T.C. A5SW	SA972CE	Installation of AID battery temperature sensing and over temperature warning system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT; T.C. A5SW	SA188GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA274GL	Installation of a Scenic exhaust assembly, P/N YK-12013, in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-AT; T.C. A5SW	SA1051CE	Installation of Collins Radio Co., AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-AT; T.C. A5SW	SA1575SW	Battery isolation system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1576SW	Ray Electronics Model 7107 battery fault warning system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1577SW	Collins FCS-105 automatic/flight director system with Sperry dual flight director system. Issued 1/26/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1673SW	Battery isolation system. Issued 6/11/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA2344WE	Installation of Collins Radio Co. Model FCS-105B3 autopilot flight flight director systems. Reissued 8/20/71.	CE	24250	Collins Radio Company 855 - 35th Street, N.E. Cedar Rapids, IA 52406
SA226-AT; T.C. A5SW	SA2860WE	Installation of AiResearch TPE 331-3U-307G engines and propeller synchrophasing. Issued 3/21/74.	WE	07502	AiResearch Manufacturing Company of Arizona 402 South 36th Street Phoenix, AZ 85034
SA226-AT; T.C. A5SW	SA3075WE	Installation of Garrett AirNav 100 area navigation system. Issued 10/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T(B); T.C. A5SW	SA1166EA	Installation of Litton LTN-211 Omega navigation system. Amended 4/15/80.	EA	78412	Teterboro Aircraft Service, Inc. 401 Industrial Avenue Teterboro, NJ 07608
SA226-T(B); T.C. A5SW	SA1167EA	Installation of Collins ADS-80 air data system. Amended 4/15/80.	EA	78412	Teterboro Aircraft Service, Inc. 401 Industrial Avenue Teterboro, NJ 07608

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA226-T; T.C. A5SW	SA1238SW	Bendix M-4C automatic flight control system. Issued 12/22/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-T; T.C. A5SW	SA1241SW	Installation of supporting structure, avionics components and systems. Issued 1/6/71.	WE	07500	AiResearch Aviaiton Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1271SW	Collins AP105 automatic flight control system. Issued 3/16/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1600SW	Battery isolation system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1601SW	Ray Electronics Model 7107 battery fault warning system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1602SW	Collins AP105 automatic flight control system with dual Sperry Stars flight directors. Issued 2/6/73.	WE	07500	AiResearch Aviation Company 6201 WEst Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA2864WE	Modification to install electrical and structural provisions for Texas Instrument, Inc. infra-red scanner system. Issued 4/25/74.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T, SA226-T(B); T.C. A5SW	SA804SO	Installation of Bendix M-4D automatic flight control system, including integration into the existing Swearingen pitch trim and yaw damping systems. Amended 12/14/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226T, SA226AT; T.C. A5SW	SA2428WE	Installation of Hoskins/SDI Twilighter MK III supplemental lighting system. Issued 10/50/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226TC (S/N TC-201 and up); T.C. A8SW	SA973CE	Installation of AID battery temperature sensing and over-temperature sensing system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA821SO	Installation of Bendix M-4D automatic flight control system including optional flight director system and integration into existing Swearingen pitch trim system. Issued 1/29/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA1247SW	Bendix M-4C autopilot. Reissued 8/2/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

TAYLORCRAFT AVIATION CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BC Series; T.C. 696	SA1-217	Replacing original lacing for securing fabric to wings with screws and washers.	EA	19836	Capital Air Service, Inc. P.O. Box 467 Dover, DE 19901
BC Series; T.C. 696	SA4-294	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
BC Series; T.C. 696	SA4-613	Fiberglass wheel pants and mounting brackets of metal.	NW	82390	Richard Van Grunsven Route 2, Box 187 Forest Grove, OR 97116
BC Series; T.C. 696	SA4-830	Fiberglass covering on wings.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
BC Series; T.C. 696	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
BC Series; T.C. 696	SA4-906	Ceconite 101 covering of complete airframe. Amended 12/15/66.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
BC Series; T.C. 696	SA4-1346	Fiberglass covering on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
BC Series; T.C. 696	SA4-1438	Eronite covering of fuselage.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
BC Series; T.C. 696	SA208WE	Removal of right cabin door for parachute jumping and aerial photography operations.	RM	38040	Glacier View Skyways, Inc. P.O. Box 252 Kalispell, MT 59901
BC Series; T.C. 696	SA1008WE	Poly-Fiber covering of wings and ailerons. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
BC, BC12D; T.C. A-696	SA1-210	Conversion of Taylorcraft Model BC or Model BC12D to the equivalent of the following aircraft models: Model BC12D85 and Model BC12D-4-85 or Model 19. Amended 6/14/71.	EA	37882	Gilberti Aviation P.O. Box 246 Aliquippa, PA 15001
BC, BC-65, -12-65, -12D, -12D1, -12D-85, BCS, BCS-65, -12-65, -12D, -12D1, -12D-85, -12D-4, 85; T.C. 696	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	Eonair, Inc. 417 Watts Drive Bakersfield, CA 93307
BC, -65, 12-65, -D, -D1, 12D-84, -4-85; BCS, -65, -12-65-D, -D1, -4-85; BC Series (Army L-2H); T.C. 696	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC, BCS, BC-65, S-65, 12-65, S12-65, 12D, S12-D, 12-D1, S12-D1, 12D-85, 12D-4-85; T.C. 696	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC, BCS, BC-65, BCS-65, BC12-65, BCS12-65, BC12D, BCS12-D, BC12-D1, BC12D-85, BC12D-4-85, BC12DS-4-85; T.C. 696	SA2666WE	Ceconite 102 material covering on complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC Series, 19; T.C. 696, 1A9	SA1-95	Wing lift struts to include a hydraulic-pneumatic shock absorber.	EA	86500	Wings With Springs, Inc. R.D. 3, Box 495 Latrobe, PA 15650
BC Series, 19; T.C. 696, 1A9	SA4-1200	Delco-Remy generator 1101879 and regulator 1118384.	RM	81060	Universal Aircraft Industries P.O. Box 5306 Denver, CO 80217

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BC Series, 19; T.C. 696, 1A9	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
BC-65, BCS-65, BC12-65, BCS12-65, BC12-D, BC12-D1, BC12D-85, BCS12D-85, BC12D-4-85, BCS12D-4-85, DC-65, DCO-65; T.C. A696	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
BC, BC-65, -12D, -12D1, BC12D-85, BCS12D-85, BC12D-4-85, 19; T.C. A-696, 1A9	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred F. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BC, BC-65, -12D, -12D1, BC12D-85, BCS12D-85, BC12D-4-85, 19; T.C. A-696, 1A9	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BC-12D; T.C. 696	SA2-225	Windshield manufactured in accordance with Luminous Plastics, Drawing No. LP-650. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
BC12D; T.C. 696	SA661AL	Installation of plexiglass skylight in fuselage cabin. Issued 1/10/79.	AL	23130	Gregory H. Clayton Box 73204 Fairbanks, AK 99707
BC12D; T.C. 696	SA1901SW	Clipped wings, revised control system, added aileron, and elevator servo tabs. Issued 8/20/74.	SW	77125	Michael Swick Route 1, Box 163 Plano, TX 75074
BC12D; T.C. A696	SA2891SW	Installation of stick type control system. Issued 12/20/78.	SW	77124	Swick Aircraft Route 3, Box 163B Lewisville, TX 75067
BC12D; T.C. A-696	SA4108SW	Use of Piper metal spars to replace original wood spars. Issued 3/13/80.	SW	77125	Swick Aircraft Route 1, Box 128B McKinney, TX 75069
19; T.C. 1A9	SA90NW	Installation of Continental O-200-A engine, McCauley propeller IA100MCM/6950, and sub-systems. Issued 2/26/74.	NW	35740	Ronald W. Flinchbaugh 8265 Custer Road Tacoma, WA 98499
F19; T.C. 1A9	SA1070SO	Installation of Aqua Model 1500 floats. Issued 5/3/79.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
F19; T.C. 1A9	SA1129EA	Installation of PK Model 1800 or B1800 (TSO-C27) seaplane floats. Issued 9/7/78.	EA	29998	DeVore Aviation Corporation PK Floats 206 Newton Road Plainview, NY 11803

Aircraft Nake, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
415 Series; T.C. 718, 787	SA465WE	Continental C-90-12F engine and McCauley 1B90-CM propeller.	WE	22218	R.B. Christianson 10510-1/2 Mather Avenue Sunland, CA 91040
415 Series, F-1; T.C. 718, 787	SA4-638	Single arm nose wheel fork with conventional double arm fabricated fork U415-34090-1-A and B.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
415 Series, F-1, F-1A; T.C. 718, 787	SA4-1254	Main gear wheel fairings, nose gear wheel fairing.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90275
415 Series, F-1, -1A; T.C. 718, 787	SA4-1606	Wing root fillets change from aluminum 3S and 24ST3 to fiberglass.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series, F-1, -1A; T.C. 718, 787	SA1WE	Fiberglass tail cone.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series, F-1, -1A; T.C. 718, 787	SA3WE	Fiberglass reinforced plastic engine cowl.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415-C, 415-CD, S/N 813 and up; T.C. A-718	SA120GL	Install Cleveland Wheel and Brakes conversion kit, P/N 199-69. Amended 7/7/76.	GL	23250	Cleveland Wheels and Brakes Div. VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011
415-C, 415-CD; T.C. A-718	SA330GL	Installation of Skyport Model SMK-15, 9-cu.ft. baggage compartment. Issued 7/18/79.	GL	36566	Skyport Aircoupe Services Division Fox Engineering Company 1340 Francis Street Jackson, MI 49203
415C, S/N 113 thru 812; T.C. A-718	SA2185WE	Installation of main gear wheel fairings and/or nose gear wheel fairing (nose gear fork P/N 415-34096 required for latter installation). (These fairings eligible for installation separately or in conjunction.) Issued 6/9/70.	WE	47750	Kenney Engineering 4120 Via Solano Pales Verdes Estates, CA 90274
415C, S/N 113 thru 812; T.C. A-718	SA3293WE	Installation of McCauley 1B90CM7351 propeller on aircraft equipped with Continental C-75-12 engine. Issued 11/15/76.	WE	39820	Ronald T. Hagerman
(Erco) 415-C, 415-CD; T.C. A-718	SA3502WE	Installation of fiberglass nose bowl. Issued 10/7/77.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
415C, -CD, -D, -E, -G, F-1, F-1A; T.C. A-718, A-787	SA319WE	Metal cover of wings in accordance with Air Fab Drawing No. 104, Rev. No. 1. Reissued 7/29/71.	RM	81000	Univair Aircraft Corporation Route 3, box 59 Aurora, CO 80010
415C, -CD, -D, -E, -G, F-1, F-1A; T.C. A-718, A-787	SA437WE	Installation of leading edge landing light in accordance with Air Fab Drawing No. 1011. Reissued 7/29/71.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80010
415C, 415CD, 415D, E, G; F-1, F-1A; A-2, A2-A, M10; T.C. A-718, A-787	SA2462WE	(1) Installation of main gear wheel fairings; (2) installation of nose gear wheel fairings. (These items eligible for installation separately or in conjunction with each other.) Issued 3/3/72.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
415D; T.C. A-787	SA5GL	Removal of fuselage fuel tank. Issued 10/3/72.	GL	28790	Norvel O. Dasher Route 1, box 61 Elgin, IL 60120
415D; T.C. A787	SA381SO	Revised (1) brake handle per Drawing 9R, (2) seat belt anchor straps to seat per Drawing 10R, (3) rudder control system springs per Drawing 11R. Amended 3/14/68.	SO	68550	W.F. Robinson P.O. Box 241 Lanett, AL 36863
415D; T.C. A787	SA2628WE	Installation of Continental O-200-A engine, McCauley 1A101/DCM 6948 propeller, electric fuel transfer pump and associated changes. Amended 2/25/74.	WE	78624	Towns Aviation Service, Inc. 1800 West Deer Valley Road Phoenix, AZ 85027
415-D, E, G, (Erco) (Forney) F-1, F-1A; T.C. A-787	SA127GL	Install Cleveland Wheel and Brakes conversion kit, P/N 199-69. Issued 7/7/76.	GL	23250	Cleveland Wheels and Brakes Div. VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
415-D, E, G, F-1, F-1A; T.C. A-787	SA331GL	Install Skyport Model SMX-15, 9-cu.ft. baggage compartment. Issued 7/18/79.	GL	36566	Skyport Aircoupe Services Division Fox Engineering Company 1340 Francis Street Jackson, MI 49203
(Erco) 415-D, E, G, F-1, F-1A, A-2, A2-A, M10; T.C. A-787	SA3503WE	Installation of fiberglass nose bowl.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
t+1 A-2; T.C. 787	SA1126WE	B2S autopilot.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
A-2; T.C. 787	SA1495WE	Installation of Brittain Model B2C flight control system.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
A-2, A2-A, M-10; T.C. A-787	SA2230WE	Installation of main gear wheel fairings on models equipped with "spring gear" main landing gear assemblies; also installation of nose gear wheel fairings. (These items eligible for installation separately or in conjunction with each other.) Amended 3/17/72.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
F-1, F-1A; T.C. 787	SA4-1590	Riveted fuel tanks changed to welded wing and nose tank assemblies and gauge from mechanical to electric float type.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
(Alon) A-2, A-2A, (Forney) F1, F-1A, (Mooney) M10; T.C. A-787	SA71GL	Install BA-4106 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

AVCO CORPORATION, LYCOMING DIVISION

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
O-145, O-235, O-350, O-435, GO-435, O-290, O-320, O-340, VO-435, O-360, HO-360-A1A, VO-360, TO-360, LIO-360, VO-540-B & C, TVO-540-A1A, O-540 Series; T.C. 199, 210, 233, 227, 228, 229, 274, 277, 279, 286, 295, 1E1, E26EA, 304, 1E14	SE1-201	Installation of Richter B-4 or B-5 probes in Marvel-Schebler MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6, HA-9 and Bendix NA-S3B and NA-S3A1 carburetors. Amended 9/20/77.	EA	68000	Richter Aero Equipment, Inc. Essex, NY 12936
O-145-A; O-145-B, -C, GO-145; O-233-A1; O-235; O-290; O-320; IO-320; O-340; O-350; O-360, HO-360; IO-360; VO-360; O-435-1, -4, -5, -11, -13, O-435-2, GO-435, -6, -17; GSO-435, -B, -B2; VO-435, -21-23; TVO-435; GO-480; TSO-480-1, IGSO-480, -2; O-540; IO-540; IGO-540; IGSO-540; VO-540; TVO-540; GSO-580; SO-580, VSO-580; IO-720-A1a; T.C. 199, 210, 223, 225, 274, 1E12, 277, 227, 286, 1E10, 1E1, 228, 276, 279, 1E13, 275, 284, 295, 1E4, 1E11, 1E7, 304, 1E14, 256, 285, 1E15	SE44WE	Use of Kling Aviation Oil, Specifications KL-100, KL-200 and KL-300 in Continental and Lycoming engines.	WE	48530	Kling Oil Company 1492 Oddstad Drive Redwood City, CA 94063
O-235-L2C; T.C. E-223	SE792NW	Modification of engine to increase HP rating from 115 HP at 2700 rpm to a continuous 125 HP at 2800 rpm. Issued 6/28/79.	NW	16851	Ken Blackman 7305 97th Avenue, S.E. Snokomish, WA 98290
O-235, O-290, O-320 Series; T.C. 223, 229, 274	SA5CE	Prestolite ALX-5001 alternator.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
O-235, O-290, O-320, O-540, O-360 Series; T.C. E-233, E-229, E-274, E-295, E-286 w/Marvel-Schebler MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6	SA2088SO	Installation of ice indicator in the carburetor.	SO	71545	Charles B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
O-320 Series; T.C. 274	SE2-7	Carburetor air temperature bulb in Marvel-Schebler MA-4-5 carburetor.	GL	53125	Lynn McElroy Westervelt, IL 62574
O-320 Series; T.C. 274	SE508AL	Addition of crankcase release valve. Issued 11/12/73.	AL	75500	Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
O-320 or O-320-A1A; T.C. 274	SE2392SW	Conversion to fuel injection configuration equivalent IO-320-E2A. Issued 12/10/76.	SW	77124	Swick Aircraft Corporation Route 3, Box 163B Lewisville, TX 75067
O-320-A, -B; T.C. 274	SE4-1638	Installation of one Rajay Turbo-charger. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
O-320-A2B, -A2D, -E2A, -E2B, -E2C, -E2D, -E2G, -E2D; T.C. E-274	SE1226CE	Modify engines for a 160 horsepower rating on 100/130 minimum grade fuel. Amended March 1977.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
IO-320-A1A, -B1A, -B1B, -C1A; LIO-320-B1A, -C1A; T.C. 1E12	SE14WE	Installation of one Rajay Turbo-charger P/N RJ 0325, RJ 0326, RJ 0326-1 or RJ 0326-2. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
IO-320-E2A, IO-320-E2B, IO-320-E1A; T.C. 1E12	SE7CE	Modification of oil sump in accordance with Champion Drawing No. 7-1312E. Amended 7/18/75.	GL	15405	Bellanca Aircraft Corporation Box 624, Municipal Airport Alexandria, MN 56308
O-360-A1A T.C. E-286	SE2887SW	Install Bendix PS-5C carburetor. Issued 12/14/78.	SW	77124	Swick Aircraft Route 3, Box 163B Lewisville, TX 75067
O-360-A1A, -A1D; T.C. 286	SE154SO	Installation of one Rajay Turbo-supercharger Model RJ 0325, RJ 0326, RJ 0326-1 or RJ 0326-2 Amended 2/20/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
HO-360; T.C. 286	SE30WE	Conversion to Lycoming HIO-360-B1B engines.	WE	62080	Pacific Airmotive Corporation 3411 Tulare Avenue Burbank, CA 91502
HIO-360-E1AD, -E1BD; T.C. 1E10	SE100GL	Installation of Rajay 301E10-2 turbocharger. Amended 3/19/80.	GL	33875	Enstrom Helicopter Corporation P.O. Box 277 Menominee, MI 49858
IO-360-A1A, A1B, A1C, A2A, A2B, A2C, B1A, B1B, B1C, B1D, B1E, B1F, B2E, B2F, B4A, C1E6, C1A, C1B, C1C, D1A, E1A, AIO-360-A1A, A1B, A2A, A2B, B1B, LIO-360-C1E6; T.C. 1E10	SE32WE	Installation of one turbosupercharger, Rajay turbocharger, P/N RJ 0325, RJ 0326, RJ 0326-1, RJ 0326-2 and RJ 0329. Amended 3/31/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
IO-360-A1D6D, IO-360-A3D6D; T.C. 1E10	SE90WE	Installation of Rajay Turbochargers Model 325E10-1, P/N RJ0331-1, on Lycoming engine models listed. Issued 12/22/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
GO-435-C2, -C2A, -C2B, -C2B1, C2B6; T.C. 288	SE579SO	Installation of Bendix magneto models S6LN-20 and S6LN-21. Issued 2/21/74.	SO	53790	Mack's Aircraft Engine Service P.O. Box 336 Wetumpka, AL 36092
VO-435 Series; T.C. 279	SE2-856	American Bosch Induction vibrator VJR24B56X.	SW	15350	Bell Helicopter Corporation P.O. Box 482 Fort Worth, TX 76101
VO-435-A1E, -A1F; T.C. E-279	SE959EA	Modification to higher compression ration. Reissued 3/16/76.	EA	03300	Agrotors, INC. Box 578 Gettysburg, PA 17325
VO-435-A1E, -A1F; T.C. 279	SE2733SW	Modification to higher compression ratio. Issued 3/21/78.	SW	26000	Continental Copters, Inc. P.O. Box 13284 Fort Worth, TX 76118
VO-435-A1F; T.C. E-279	SE144GL	Modify engine to increase compression ratio to 8.7:1. Amended 2/17/77.	GL	49320	Lake Line Helicopters, Inc. 13601 Pioneer Trail Eden Prairie, MN 55343
GO-480 Series; T.C. 275	SE124SO	Two Rajay turbochargers 315A10. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
t+1 GO-480 Series; T.C. 275	SE135SO	Two Rajay turbochargers 315A10. Reissued 1/14/69.	WE	66250	Rajay Industries 2602 E. Wardlow Road Long Beach, CA 90807
GO-480-B1B, -C2B6, F4B6, -F6, -F3B6; T.C. E275	SE580SO	Installation of Bendix magneto models S6LN-20 and S6LN-21. Issued 2/21/74.	SO	53790	Mack's Aircraft Engine Service P.O. Box 336 Wetumpka, AL 36092
GO-480-F2D6; T.C. E-275	SE18WE	Installation of AiResearch T-1112 turbosupercharger. Reissued 4/27/70.	WE	85135	Western Commander, Inc. 16360 Daily Drive Van Nuys, CA 91406
O-540 Series; T.C. 295	SE17WE	Turbosupercharger 406330.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
O-540 Series; T.C. 295	SE40WE	Installation of two Rajay Turbochargers. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
IO-540 Series; T.C. 1E4	SE21WE	Turbosupercharger 406610-2.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
IO-540 Series; T.C. 1E4	SE22WE	Turbosupercharger 406610-2.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Turbo Wasp JT3C Series; T.C. 290	SE2CE	Transducer in-flight maintenance and performance recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
JT3C; T.C. 290	SE106SO	Alternate engine thermocouple fire seal on B-720 engine firewalls.	SO	31420	Eastern Airlines International Airport Miami, FL 33148
Turbo Wasp JT3D Series; T.C. 1E8	SE1WE	Valve assembly 126495. Limited to those engines having serial number suffix "B".	WE	77785	Telecomputing Corporation 915 North Citrus Avenue Los Angeles, CA 90052
JT3D-1, -3, -3B, -1-MC-6, -1-MC7, -7; T.C. 1E8	SE87WE	Replace the airfoils on P&WA P/Ns 505351, 536751, 665951, and 665851 first stage turbine nozzle guide vanes on P&WA engine models listed. Issued 12/21/77.	WE	22227	Chromizing Company Div. of Chromalloy American Corp. 2100 West 139th Street Gardena, CA 90249
JT8D; T.C. E2EA	SE67WE	Installation of fuel control rod end bearings. Amended 11/13/74.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85281
JT8D Series; T.C. E2EA	SE79WE	Installation of CADC bleed valve support brackets, P/N B10001 or RB10006, as a replacement part for P&W P/N 493317 used on JT8D-1-5-7-9-9A-15 and -17 engines. Issued 8/11/77.	WE	19500	California Aero Dynamics Corp. 8630 Tamarack Avenue Sun Valley, CA 91352
JT8D Series; T.C. E2EA	SE83WE	Installation of heat shield assembly P/N 408-007 as a replacement part for P&W P/N 499941 or 749609 used on JT8D-1, -5, -7, -9, -9A, -15 and -17 engines. Issued 11/15/77.	WE	43344	Hughes Helicopter Div. of Summa Corporation Centinela and Teale Streets Culver City, CA 90230
JT8D Series T.C. E2EA	SE84WE	Installation of heat shield assembly 408-008 as a replacement part for P&W No. 586918 used on JT8D-1, -5, -7, -9, -9A, -15, and -17 engines. Issued 11/15/77.	WE	43344	[illegible] Helicopter [illegible] Corporation [illegible] Teale Streets [illegible] 90230
JT8D Series; T.C. E2EA	SE97WE	Installation of heat shield assembly 408-020 as a replacement part for P&W P/N 468559 used on JT8D-1, -5, -7, -9, -9A, -15, -17 engines. Issued 6/25/79.	WE	43344	[illegible] copter Div. [illegible] Summa Corporation Centinela and Teale Streets Culver City, CA 90230
JT8D; T.C. E2EA	SA2627WE	Installation of fuel control rod end bearings. Amended 8/2/73.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85281
JT8D-1, -1A, -1B, -7, -7A, -7B, -9, -9A, -11, -15, -17, -17R; T.C. E2EA	SE86WE	Replace the airfoils on P&WA P/Ns 495051, 478351, 583751, 653851, 653951, 572451, 583351, 653751, 653151, 676951, 728951, 709951, 710751, 627751, 737271 first stage turbine nozzle guide vanes on P&WA engine models listed. Amended 6/22/78.	WE	22227	Chromizing Company Div. of Chromalloy American Corp. 2100 West 139th Street Gardena, CA 90249
JT8D-1, -1A, -7, -7A, -9, -11, -15; T.C. E2EA	SE59GL	Replacement of accessory drive gearbox seals. Amended 2/26/75.	GL	67600	Rexnord, Inc. Seal Division 634 Glenn Avenue Wheeling, IL 60090
JT9D-3, -4; T.C. E20EA	SE11CE	Installation of aircraft integrated data system components on engine. Issued August 1971.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
JT9D-7A, JT9D-7AH; T.C. E20EA	SE1181CE	Removal of 15th stage bleeds and surge detector system. Amended 4/9/80.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
JT9D-7F; T.C. A20EA	SE33NE	Incorporation of improved combustor and turbine components which permit operation at increased EGT limits. Issued 3/14/80.	NE	65030	Pratt & Whitney Aircraft Group United Technologies Corporation Commercial Products Division East Hartford, CT 06108

Item 431-A-5 TD 4.36:980/supp.-2
DEC 8 1980
5721-630
200
contin
9336

DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

SUMMARY OF SUPPLEMENTAL TYPE CERTIFICATES

This contains revisions to Summary of Supplemental Type Certificates issued for July, August, September 1980

PAGE CONTROL CHART

Remove Pages	Insert Pages
Aerospatiale 1-2	Aerospatiale 1-2
Avions Marcel Dassault 1 thru 9	Avions Marcel Dassault 1 thru 9
Ayres Corporation 3-4	Ayres Corporation 3-4
Beech 3 thru 16, 27-28, 39 thru 74	Beech 3 thru 16, 27-28, 39 thru 74
Bell 5 thru 13	Bell 5 thru 14
Bellanca MN 5 thru 8	Bellanca MN 5 thru 8
Boeing 9 thru 48	Boeing 9 thru 49
British Aerospace 1 thru 9	British Aerospace 1 thru 9
British Aircraft 1 thru 3	British Aircraft 1 thru 3
Cessna 5-6, 9 thru 83	Cessna 5-6, 9 thru 83
DeHavilland 3-4	DeHavilland 3-4
Eagle Balloons 1	Eagle Balloons 1
Fairchild Industries 3 thru 9	Fairchild Industries 3 thru 9
Fokker 1	Fokker 1
Gates Learjet 1 thru 9	Gates Learjet 1 thru 10
General Dynamics 9 thru 19	General Dynamics 9 thru 19
Gulfstream 3 thru 24	Gulfstream 3 thru 24
Hawker Siddeley 1	Hawker Siddeley 1

PAGE CONTROL CHART

Remove Pages	Insert Pages
Helio 1 thru 4	Helio 1 thru 4
Hughes 3 thru 5	Hughes 3 thru 5
Israel Aircraft 3 thru 5	Israel Aircraft 3 thru 5
KWAD 1	KWAD 1
Lockheed 13 thru 19	Lockheed 13 thru 19
Lockheed GA 7 thru 11	Lockheed GA 7 thru 11
Maule 1-2	Maule 1-2
McDonnell Douglas 11 thru 42	McDonnell Douglas 11 thru 42
Messerschmitt 1-2	Messerschmitt 1-2
Mitsubishi Aircraft 1	Mitsubishi 1
Mitsubishi Heavy Ind. 3-4	Mitsubishi Heavy Ind. 3-4
Mooney 3 thru 6	Mooney 3 thru 6
Nihon 1	Nihon 1
Piper 11 thru 66	Piper 11 thru 67
Piper Aircraft CA 1 thru 3	Piper Aircraft CA 1 thru 3
Raven 1	Raven 1
Reims 1	Reims 1
Rockwell Int. CA 1-2, 5 thru 10	Rockwell Int. CA 1-2, 5 thru 10
Rockwell Int. OK 1-2, 11 thru 15	Rockwell Int. OK 1-2, 11 thru 15
Sikorsky 3	Sikorsky 3
SNIAS 1 thru 6	SNIAS 1 thru 6
SOCATA 1	SOCATA 1
Swearingen 1 thru 3	Swearingen 1 thru 3
ENGINE	
Teledyne 1 thru 5	Teledyne 1 thru 5
MISCELLANEOUS	
Misc. 3-4	Misc. 3-4

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AEROSPATIALE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Alouette III Series; T.C. H1IN	SH752NW	Installation of a weighing system. Issued 4/12/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SE.3160 Alouette III; T.C. H1IN	SH434AL	Installation of Alaskan Sky-Craft cargo baskets. Issued 6/10/71.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
SE.3160, SA.316B, SA.316C, SA319B; T.C. H1IN	SA1243SW	Eastern rotorcraft cargo hook AK25LT. Reissued 1/4/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SE.3160 Alouette III; T.C. H1IN	SH1791SW	Foxtronics/Tramm BTI-600 nickel cadmium battery temperature. Issued 1/30/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
SE 3160 Alouette III, SA 316B Alouette III; T.C. H1IN	SA1320SW	External cargo baskets. Issued 6/1/71.	SW	84300	Vought Helicopter, Inc. 1507 Pacific Avenue Dallas, TX 75201
SE.3160 Alouette III, SA.316B Alouette III; T.C. H1IN	SH1490SW	AiResearch 92757 environmental control system. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160 Alouette III, SA.316B Alouette III; T.C. H1IN	SH1800SW	Install reclining passenger seat in forward left hand position. Issued 2/1/74.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SE.3160, SA.315B, SA.316B; T.C. H1IN	SH1471SW	Engine inlet sound suppressors. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.315B, SE316 Series; T.C. H1IN	SH437NW	Incorporation of weighing system for external load operations. Amended 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
SE3160, SA316B, SA319B; T.C. H1IN	SH71NW	Installation of electric weighing system. Amended 11/7/75.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
SE.3160, SA.315B, SA.316B, SA.319B, SA316C; T.C. H1IN	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SE.3160, SA.316B, SA.316C; Alouette III; T.C. H1IN	SH1900SW	Non-stowable litter kit. Issued 7/24/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1307SW	Eastern Rotorcraft cargo hook and H-frame. Reissued 1/4/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1318SW	Removable cabin step. Issued 10/2/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1320SW	External cargo baskets. Reissued 7/1/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319C; T.C. H1IN	SH1385SW	Replace existing landing light and anti-collision light. Reissued 9/30/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA315B; T.C. H1IN	SH61NW	Installation of electric weighing system. Amended 5/5/76.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
SA315B; T.C. H1IN	SH267NW	Installation of Simplex Model 3400 3400 spray system. Issued 6/16/76.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
SA315B; T.C. H1IN	SH268NW	Installation of automatic flagman Model #5. Issued 3/18/76.	NW	03500	Air Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
SA315B; T.C. H1IN	SA429NW	Installation of Simplex Model 4206 4206 aerial spray system. Issued 4/11/77.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA315B; T.C. H1IN	SH540NW	Install onboard weighing system. Issued 1/9/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA.315B; T.C. H1IN	SH695NW	Installation of Model 2512 weighing system. Issued 12/14/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA.315B; T.C. H1IN	SH1735SW	H-frame external cargo hook. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.315B Alouette III; T.C. H1IN	SH1909SW	Replacement of existing landing light and anti-collision light. Reissued 9/30/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.315B; T.C. H1IN	SH2425SW	Installation of low range airspeed indicator and pitot pressure surge chamber. Issued 3/4/77.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
SA.316B Alouette III: T.C. H1IN	SH168WE	Installation of Nightsun SC-16C searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
SA.316B Alouette III; T.C. H1IN	SH647NW	Installation of cargo baskets. Issued 8/3/78.	NW	44032	Inland Helicopters 2660 Vine Street Grants Pass, OR 97526
SA.316B, SA.316C, SA319B; T.C. H1IN	SH223WE	Installation of tail rotor floodlight. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA-360C; T.C. H8EU	SH2962SW	Blade bolt balance pin adapter. Issued 3/23/79.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
SA360C; T.C. H8EU	SH4051SW	Modification of lower cabin plexiglass panels. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C, SA-365C; T.C. H8EU, H10EU	SH1179EA	Installation of DeVore tail floodlight on upper surfaces of horizontal stabilizer. Reissued and amended 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
SA-365C; T.C. H10EU	SH2987SW	External markings. Issued 4/23/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA-365C; T.C. H10EU	SH4050SW	Twelve-place interior with forward facing seats. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-365C; T.C. H10EU	SH4052SW	Modification of lower cabin plexiglass panels. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-365C; T.C. H10EU	SH4072SW	Interior installation. Issued 1/11/80.	SW	41780	Heliflight Systems, Inc. P.O. Box 90879 Houston, TX 77090
SA-365C; T.C. H10EU	SH4073SW	Equipment shelf in upper baggage area. Issued 1/11/80.	SW	41780	Heliflight Systems, Inc. P.O. Box 90879 Houston, TX 77090
SA-365C1; T.C. H10EU	SH198RM	Installation of new auxiliary fuel tank and litter installation. Issued 4/7/80.	SW	41775	Helicopter Medical Evacuation, Inc. P.O. Box 1462 Fort Collins, CO 80522

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AVIONS MARCEL DASSAULT (A.M.D.)

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon; T.C. A7EU	SA16GL	Incorporating AMF (Leland) inverter MGE-23-400. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
Fan Jet Falcon all models; T.C. A7EU	SA45GL	Install AMF inverter MGH 549-1. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
Fan Jet Falcon; T.C. A7EU	SA176GL	Addition of interior/exterior emergency lighting, flight compartment door, and baggage compartment smoke detector system. Issued 5/18/77.	GL	47630	K-C Aviation, Inc. Outagamie Airport Appleton, WI 54911
Fan Jet Falcon; T.C. A7EU	SA414GL	Installation of a Litton LTN 211 Omega navigation system. Issued 6/10/80.	GL	47630	K-C Aviation, Inc. Outagamie Airport Appleton, WI 54911
Fan Jet Falcon; T.C. A7EU	SA472CE	Install Twi. MK III supplementary lighting system using Model A wing tip and Model L tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
Fan Jet Falcon; T.C. A7EU	SA590EA	Installation of interior. Amended 3/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
Fan Jet Falcon; T.C. A7EU	SA598CE	Install cargo bulkhead and baggage rack. Reissued 7/10/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
Fan Jet Falcon; T.C. A7EU	SA653EA	Installation of partition and door below cut provisions. Amended 11/6/70.	EA	07498	AiResearch Aviation Company L.I. MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779
Fan Jet Falcon; T.C. A7EU	SA649SW	Interior modification. Reissued April 1973.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon; T.C. A7EU	SA677SW	Interior. Reissued April 1973.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon; T.C. A7EU	SA688SW	Angle of attack system. Reissued March 1977.	NE	26010	Continental Development Corp. Box 511 Ridgefield, CT 06877
Fan Jet Falcon; T.C. A7EU	SA691SW	Interior modification. Reissued April 1973.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon; T.C. A7EU	SA698CE	Install Woodward electronic engine synchronizer system. Amended 1/20/72.	GL	87250	Woodward Governor Company 5001 NOrth Second Street Rockford, IL 61101
Fan Jet Falcon; T.C. A7EU	SA704SW	PB-60 autopilot dual axis.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
Fan Jet Falcon; T.C. A7EU	SA730SW	Relocation and install inverters.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
Fan Jet Falcon; T.C. A7EU	SA740SW	Collins AP103F/FD108 Flight Director Systems and Sensors, equipment for Category II. Reissued 1/30/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA753SW	Class D baggage compartment.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
Fan Jet Falcon; T.C. A7EU	SA758SW	Jump seat. Reissued April 1973.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon; T.C. A7EU	SA770SW	Bendix Eclipse Pioneer PB-60 Flight Control System for Category II.	EA	16010	The Bendix Corporation Navigation & Controls Division Teterboro, NJ 07608

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon; T.C. A7EU	SA785SW	Collins AL-101 radio altimeter system.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420
Fan Jet Falcon; T.C. A7EU	SA786SW	AP/ACN-153(V) Doppler System.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420
Fan Jet Falcon; T.C. A7EU	SA804SW	Collins AP-103F/FD-109G flight director system and associated sensors for 3-axis. Reissued 1/30/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA805SW	Collins AP-103F/FD-109G flight director system and associated sensors for 2-axis. Reissued 1/30/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA814EA	Installation of Fairchild Company voice recorder Model A100 and control unit A151 and Lockheed Corp. flight recorder Model 109C. Reissued 2/22/77.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 907 - Adams Field Little Rock, AR 72203
Fan Jet Falcon; T.C. A7EU	SA833SW	VOR antenna.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420
Fan Jet Falcon; T.C. A7EU	SA841SW	Dual FD-300 Flight Director Systems, AL-101 Radio Altimeter, G-1640 Cables Comparator.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
Fan Jet Falcon; T.C. A7EU	SA852SW	Rear mounted 2500VA inverter package. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA856SW	Bendix ALA-51A radio altimeter.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420
Fan Jet Falcon; T.C. A7EU	SA871SW	28 volt 4 amp hour nickle cadmium battery.	SW	12250	Associated Radio Service Company Box 20718, Walnut Hill Station Dallas, TX 78420
Fan Jet Falcon; T.C. A7EU	SA875SW	Jump seat. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA920SW	AP104/FD109H/FD109F Flight Director System.	SW	24252	Collins Radio Company Addison Airport Addison, TX 75001
Fan Jet Falcon; T.C. A7EU	SA927SW	Angle of attack system.	NE	26010	Continental Development Corp. P.O. Box 511 Ridgefield, CT 06877
Fan Jet Falcon; T.C. A7EU	ST933SO	Installation of Collins FPC-75 flight profile computer (ground proximity warning system). Issued 5/20/77.	SO	24262	Collins Radio Group Rockwell International 1591 Phoenix Boulevard, Suite 1 Atlanta, GA 30349
Fan Jet Falcon; T.C. A7EU	SA1016SW	Collins AL-101 Radio altimeter.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
Fan Jet Falcon; T.C. A7EU	SA1025WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1031WE	Executive interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1116WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1129WE	Executive interior, equipment and avionics.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1131WE	Collins AP-103E/AP-103F autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1136WE	GTCP 39-92, for ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon; T.C. A7EU	SA1139WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1155EA	Installation of Solar T-62T-39, in lieu of Solar T-62T-29, gas turbine auxiliary power unit and removal of Freon air conditioning systems. Amended 8/15/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon; T.C. A7EU	SA1204WE	Integrated auxiliary power unit and air conditioning system using Solar T-62T-29A gas turbine. Reissued 12/20/77.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon; T.C. A7EU	SA1230WE	Storage box in rear compartment.	WE	62080	Pacific Airmotive Corporation Aircraft & Eng. Center 3000 N. Clybourn Avenue Burbank, CA 91502
Fan Jet Falcon; T.C. A7EU	SA1298WE	Emergency flight instrument system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1336WE	Flight data recorder and cockpit voice recorder.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1337WE	Emergency cabin lighting.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1357SW	Installation of inverter rack. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon; T.C. A7EU	SA1342WE	Installation of accumulator pressure gauges.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1374WE	Installation of Bendix DRA-12 doppler radar system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1436WE	Installation of Shoulder Harness for Pilot Seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1508WE	Installation of an Automated Specialties, Inc. angle of attach system. Amended 9/4/68.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1515SW	Replace existing 13 x 5.0-4 wheel and tire w/14.5 x 5.5-6 wheel and tire. Reissued 4/6/77.	SO	34808	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 9 Memphis, TN 38118
Fan Jet Falcon; T.C. A7EU	SA1573WE	Installation of Lear Jet Type Air Conditioning System and Auxiliary Heater.	RM	37098	Gates Rubber Company 8601 Montview Boulevard Denver, CO 80220
Fan Jet Falcon; T.C. A7EU	SA1588SW	Foxtronics/TRAMM BT1 600 nickel cadmium battery temperature system. Issued 1/5/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
Fan Jet Falcon; T.C. A7EU	SA1595SW	Transequip cargo handling equipment. Issued 1/22/73.	SW	34810	Federal Express Corporation P.O. Box 493 - Adams Field Little Rock, AR 72203
Fan Jet Falcon; T.C. A7EU	SA1616WE	Installation of ladder and hand rail in aft compartment. Amended 5/23/68.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA-90405
Fan Jet Falcon; T.C. A7EU	SA1621WE	Installation of inverters.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
t+1 Fan Jet Falcon; T.C. A7EU	SA1666SW	Nose wheel steering modification. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA1707WE	Installation of inverters.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon; T.C. A7EU	SA1737SW	WA402001 galley. Issued 10/9/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon; T.C. A7EU	SA1778WE	Installation of electric floor heater blankets	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1818WE	Installation of Sperry SP-40 Automatic Flight Control System and SPI-73E Sperry Instrumentation System.	WE	74570	Sperry Flight System Division Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
Fan Jet Falcon; T.C. A7EU	SA2058WE	Installation of interior and equipment, including special remote sensing equipment (aerial prospecting). Amended 5/4/70.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA2159WE	Installation of General Precision Laboratories GPK-1000 doppler radar systems. Issued 5/22/70.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91503
Fan Jet Falcon; T.C. A7EU	SA2377SW	Install BH185R-289 EGT temperature indicator system. Issued 11/9/76.	SW	43075	Howell Instruments, Inc. 3479 West Vickery Boulevard Fort Worth, TX 76107
Fan Jet Falcon; T.C. A7EU	SA4067SW	Install Freon air conditioner compressor/condensor package in aft fuselage tail section. Issued 12/6/79.	SW	26230	Cooper Airmotive Aircraft Services P.O. Box 7409 Dallas, TX 75209
Fan Jet Falcon and Series C, D, E; T.C. A7EU	SA1398CE	Installation of Collins APS-80 2-axis automatic flight control system integrated with a (partial) ADS-80 air data system. Issued 2/11/78.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
Fan Jet Falcon and Series C, D, E; T.C. A7EU	SA1851WE	Installation of single point pressure fueling system. Amended 6/16/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
Fan Jet Falcon; Series C, D, E, F; T.C. A7EU	SA669SW	Revised autopilot static system for Collins AP103F autopilot. Reissued 1/30/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2568WE	Installation of engine thrust reversers. Amended 10/31/72.	GL	02400	Aeronca, Inc. 1712 Germantown Road Middletown, OH 45042
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2704WE	Installation of (1) engine pylon mounted vertical tail floodlights, (2) horizontal stabilizer mounted vertical tail floodlights or both systems. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2792WE	Installation of Dorne & Margolin antenna assembly (DMN 4-15) on the vertical tail cap. Reissued 12/20/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon and Series E, F; T.C. A7EU	SA2550WE	Installation of Flite-Tronics inverters Model PC-17A. Amended 2/20/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series C, D; T.C. A7EU	SA829EA	Installation of Teledyne Avionics auto throttle system. Reissued 1/7/72.	SW	78127	Teledyne Incorporated 3401 Shiloh Road Garland, TX 75040
Fan Jet Falcon, Fan Jet Falcon C, D, E; T.C. A7EU	SA1102EA	Installation of Teledyne Avionics angle of attack indicating system, P/N SL112B2300. Issued 5/31/78.	EA	78000	Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon Series C, D, E; T.C. A7EU	SA1137SW	Installation of Teledyne Avionics normalized angle of attack indicating system. Amended 11/9/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA28NE	Installation of Canadian Marconi CMA-734 omega navigation system. Amended 3/26/80.	NE	74935	Stead Aviation Corporation Manchester Municipal Airport Manchester, NH 03103
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; F; T.C. A7EU	SA30NE	Installation of Global Navigation, Inc. loop antenna, P/N 11455-2, on horizontal stabilizer. Amended 1/17/80.	NE	74935	Stead Aviation Corporation Manchester Municipal Airport Manchester, NH 03103
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA29GL	Installation of equipment rack at fuselage station 00. Issued 7/9/73.	GL	02400	Aeronca, Inc. 1712 Germantown Road Middletown, OH 45042

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series C, D, E, F: T.C. A7EU	SA35NE	Installation of Stead Aviation bracket, P/N SA AB1585. Issued 7/18/80.	NE	74935	Stead Aviation Corporation Manchester Airport Manchester, NH 03103
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA57GL	Installation of passenger couch. Reissued 7/10/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
Fan Jet Falcon Series C, D, E, F: T.C. A7EU	SA122GL	Installation of radome kit 4076X. Issued 8/16/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
Fan Jet Falcon Series C, D, E, F: T.C. A7EU	ST849SO	PPG Industries windshields, Federal Express P/N's 111-0071, (L/H), 111-0072 (R/H), 111-0073 (center). Issued 8/4/75.	SO	34808	Federal Express Corporation 2839 Sprankel Road P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST882SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA891SW	Dorne & Margolin DMN4-15-5 antenna. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA894EA	Installation of Grimes three light strobe kit P/N 34-0302-1 as supplemental lighting. Issued 12/20/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST925SO	Manufacture of main landing gear door arm for Fan Jet Falcon Series airplane. Issued 2/24/77.	SO	05090	Aircraft Equipment Cert. Corp. P.O. Box 18850 Memphis, TN 38118
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	ST948SO	Installation of Aircraft Equipment Certification Corp. pilot/copilot/center windshield panels. Amended 6/2/78.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C,D,E,F: T.C. A7EU	ST960SO	Manufacture and installation of Aircraft Equipment Certification Corp. (AECC) modular container and rack assembly. Issued 10/21/77.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	ST961SO	Replacement of the ball-bearing type right-hand engine throttle crossover cable with a reinforced wire type. Issued 11/10/77.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis International Airport Memphis, TN 38138
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST1001SO	Installation of Federal Express Corp. brake mount flange. Issued 6/6/78.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1163EA	Installation of Solar T-62T-40C APU. Amended 1/23/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1164EA	Installation of cabin air-conditioning flood duct. Amended 10/10/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1172EA	Installation of Hamilton Standard R72-3W air cycle machine, P/N 750660 Model 7/10 heat exchangers P/N 753355. Amended 3/20/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1213SW	Alteration for battery charging from ground power unit. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F: T.C. A7EU	SA1435CE	Addition of improved autopilot static port systems. Issued 9/28/78.	CE	59270	MidCoast Aviation Service, Inc. Lambert Field P.O. Box 10254 St. Louis, MO 63145
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1461SW	Three Flite-Tronics PC-17A inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1462SW	Collins AP-105/FD-108/FD-109 autopilot/flight director system. Amended 9/28/78.	CE	24250	Rockwell International Collins Radio Group Collins Road Cedar Rapids, IA 52406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1469SW	Fairchild stem system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1633SW	Three Avionics Instruments, Inc. 1A1000 inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1699SW	Solar T-62T-39 turbine APU. Issued 7/6/73.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1713SW	Couch installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1714SW	Galley installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1768SW	Gulton proximity switch system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1885SW	Solar T62T-39 turbine APU. Issued 6/14/74.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1893SW	Landing light installation, alternate position. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1988SW	Jump seat. Issued 5/20/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1996SW	Installation of auxiliary landing lights. Issued 11/6/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2204SW	Installation of electronics rack. Issued 9/14/76.	SW	34280	Fancon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2232SW	Install Collins dual RCS-31 RNAV system. Issued 8/15/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2474SW	Horn silence switch. Issued 6/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2485SW	Fabrication and installation of three-place couch. Issued 8/5/77.	SW	34280	Falcon Jet Corporation LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C,D, E, F; T.C. A7EU	SA4095SW	Radio master system. Issued 3/4/80	SW	34280	Falcon Jet Corporation P.O. Box 6156 Little Rock, AR 72216
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA907CE	Battery temperature indicating and over temperature warning system. Amended June 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 E. Lewis Street Wichita, KS 67202
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA1483SW	Avionics installation (VHF communi- cations, VHF navigation, ADF's DME's, transponders, weather radar radio altimeter, third attitude gyro). Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F, Falcon 10; T.C. A7EU, A10EU	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
Fan Jet Falcon Series C, D, E, F, Mystere 20; T.C. A7EU	SA119GL	Electrical cable harness assemblies for left and right engines; each consisting of starter-generator cables, starter-generator ground cable, master junction cable and fan tach sensor cable. Amended 2/6/78.	GL	37379	General Electric Company Aviation Service Operation/Cincinnati 260 West Mitchell Avenue Cincinnati, OH 44232
Fan Jet Falcon Series D; T.C. A7EU	SA918EA	Installation of Canadian Marconi CMA-712 doppler navigation system. Reissued 11/9/72.	EA	47665	Karr Electronics Corporation 232 Wescott Drive Rahway, NJ 07065

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series D; T.C. A7EU	SA993SW	Collins AP-104 Autopilot and FD-109H/FD-109F Flight Directors for Category I and II. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1327WE	Installation of dual inverters. Amended 3/18/69.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon Series D; T.C. A7EU	SA1467SW	Cargo interior. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1468SW	Openable window in co-pilot's side and qualifying existing pilot's and new co-pilot's windows as emergency exits. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1473SW	Replace passenger entrance door with wide cargo door. Amended 7/7/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA2640WE	Installation of a Garrett Model 75 area navigation system. Amended 9/18/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D; T.C. A7EU	SA3394WE	Replacement of cargo barrier net installed per STC SA1467SW with a rigid cargo barrier partition. Issued 7/11/77.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Blvd. Torrence, CA 92680
Fan Jet Falcon Series D, E; T.C. A7EU	SA1771SW	Installation of Sperry SPZ-200 autopilot/flight director control system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA1570SW	Collins AP105/FD108 autopilot/flight, flight director system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA1577WE	Installation of jump seat. Amended 10/19/70.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA2404SW	System to disable the take off out of trim warning system when high power is applied during operation of thrust reversers.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA2588AWE	Installation of a Hoskins Model Mk III (Twilighter) anticollision lighting system. Amended 12/21/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
Fan Jet Falcon Series D, F; T.C. A7EU	SA1495SW	Installation of Fairchild voice, recorder model A100 and Lockheed flight recorder model 109C. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series D, F; T.C. A7EU	SA1806SW	Co-pilot brake modification. Issued 2/6/74.	SW	34810	Federal Express Corporation P.O. Box 493 Little Rock, AR 72203
Fan Jet Falcon Series D, F; T.C. A7EU	SA2344SW	Hartman Systems Co. vertical scale engine instruments. Issued 8/11/76.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series E; T.C. A7EU	SA3714WE	Revise existing interior to include three place side facing divan, galley, storage cabinet, three folding tables, cockpit door, stereo/flitephone cabinet, T.V./recorder cabinet and shoulder harness restraint for divan. Amended 11/22/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 E. Spring Street Long Beach, CA 90806
Fan Jet Falcon Series F; T.C. A7EU	SA1381SW	Installation of Teledyne Avionics normalized angle of attach system, Model 112B500. Amended 2/8/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon Series F; T.C. A7EU	SA1499SW	Installation of inverter system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series F; T.C. A7EU	SA1692SW	Modification of control pedestal. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Fan Jet Falcon Series F; T.C. A7EU	SA1892SW	Collins ALT-50 radio altimeter. Issued 6/27/74.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series F; T.C. A7EU	SA2479SW	Wiring and antenna provisions, and radio rack for Litton LTN-201 omega system. Issued 7/15/77.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA142GL	Installation of radome kit 4128X. Issued 11/9/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
Falcon 10; T.C. A33EU	ST902SO	Installation of Collins ground proximity warning system. Issued 7/28/76.	SO	24262	Collins Radio Group Rockwell International 1591 Phoenix Boulevard, Suite 1 Atlanta, GA 30349
Falcon 10; T.C. A33EU	SA1002EA	Installation of Sperry SPZ-500/SPI-77D flight control instrument system. Reissued 1/7/80.	SW	07498	Falcon Jet Corporation P.O. Box 167 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA1012EA	Installation of Teledyne Avionics normalized angle of attack indicating system, P/N 112B1600. Issued 8/21/75.	EA	78000	Teledyne Avionics A Division of Teledyne, Inc. P.O. Box 6400 Charlottesville, VA 22906
Falcon 10; T.C. A33EU	SA1042EA	Installation of hydraulically actuated target type thrust reverser system. Amended 7/11/78.	EA	39540	Grumman Aerospace Corporation Bethpage, L.I., NY 11714
Falcon 10; T.C. A33EU	SA1201EA	Installation of cockpit pedestal extension or installation of cockpit pedestal extension and cockpit floor storage box. Issued 7/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
Falcon 10; T.C. A33EU	SA1223CE	Install King KFC-300 dual flight director flight control system (Category I configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1224CE	Install King KFC-300 dual flight director flight control system (Category II configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1294CE	Installation of Avcon Industries TSC-C39a stretcher, P/N 4001-105 or -106. Issued January 1977.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 North Wichita Station Wichita, KS 67204
Falcon 10; T.C. A33EU	SA1993SW	Install wing ice lights. Issued 6/9/75.	SW	26230	Cooper Airmotive, Inc. Executive Aircraft Division Redbird Airport Dallas, TX 75232
Falcon 10; T.C. A33EU	SA2225SW	Passenger compartment interior. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2226SW	Pressurization of nose cone to improve avionics reliability. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2846WE	Installation of Pulstar two-light supplemental lighting system. Issued 3/4/74.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92705
Falcon 10; T.C. A33EU	SA2857WE	Avionics modification and installations of an 8-passenger executive interior arrangement. Reissued 1/4/78.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2685SW	Install three place couch at Station 181.0 to 239.0 right side. Issued 12/11/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
Falcon 10; T.C. A33EU	SA2919WE	Installation of TFE731-2 engines S/N P73143 and S/N P79101, modified in accordance with STC SE66WE. Issued 8/21/74.	WE	07502	AiResearch Aviation Company 402 S. 36th Street Phoenix, AZ 85034
Falcon 10; T.C. A33EU	SA2983WE	Installation of a Garrett AirNAV 100 area navigation system. Issued 1/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Falcon 10; T.C. A33EU	SA3061WE	Installation of a Garrett AirNAV 100 or 200 navigation system. Amended 10/26/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3544WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 1/27/78	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3557WE	Installation of DeVore Aviation Corp. tail floodlights. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
Falcon 10; T.C. A33EU	SA3752WE	Installation of a communications components Ontrac III VLF/Omega navigation system. Issued 10/25/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA4015SW	Nose radio rack. Issued 7/12/79.	SW	34280	Falcon Jet Corporation P.O. Box 7001 Dallas, TX 75209
Falcon 10A; T.C. A33EU	ST153RM	Installation of Canadian Marconi CMA-734 Omega navigation system. Issued 9/11/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
Falcon 20; T.C. A7EU	ST823SO	Installation of SEMCA 14640-113 air conditioning valve. Reissued 7/23/75.	EA	42125	Hermetic Aircraft Instrument Corporation 200 Marine Street Farmingdale, L.I., NY 11735

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S-2R (Restricted Category): T.C. A4SW	SA3889WE	Installation of Goodyear brake assembly P/N 95-50377 or P/N 5308865, Goodyear wheel assembly P/N 50-00444 or P/N 530884, and 11.00-13, Type III, 8 P.R. tire. Amended 6/15/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90907
S-2R (Restricted Category); T.C. A4SW	SA3890WE	Installation of Wright R-1820-40, -60, -71, -87 engine and Hamilton Standard 33D50 or 43D50 constant speed propeller. Amended 5/18/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
S-2R (Restricted Category); T.C. A4SW	SA3897WE	Installation of Pezetel Model PZI-3S engine and Dowty Rotol model CR289/3-110-F/1 propeller. Issued 4/11/79.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93905
S-2R; T.C. A3SW	SA3927WE	Installation of an AiResearch TPE331-1-1012 turboprop engine. Issued 5/11/79.	WE	75210	Floyd D. Stilwell 5060 East Falcon Drive Mesa, AZ 85205
S-2R; T.C. A4SW	SA3961WE	Installation of extended engine mount, revised cowling and induction system, Hamilton Standard 22D40 or 12D40 constant speed propeller, and modified elevator trim tab system. Issued 5/23/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R; T.C. A4SW	SA4039SW	Lycoming LTP-101-600A1A turboprop. Issued 9/25/79.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
S-2R; T.C. A4SW	SA4109WE	Installation of cockpit canopy/ fuselage fairing. Issued 3/7/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R; T.C. A4SW	SA4110WE	Installation of spring-type tail wheel strut assembly. Issued 3/7/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R (Restricted Category): T.C. A4SW	SA4111WE	Installation of Wright R-1820-71, -60; GR1820G-202A; 702C9GC1, 2, 3, 4; 704C9G1, 2, 3, 4 engines and Hamilton Standard 43D50 constant speed propeller. Issued 3/7/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R, S/N 2526R and up modified by STC SA3961WE; T.C. A4SW	SA4112WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Issued 4/22/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R, S/N 2526R and up modified by STC SA3961WE, Normal Category; T.C. A3SW	SA4113WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Issued 4/22/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R (S/N 2526R and up modified by STC SA3897WE), S-2R-R3S (S/N R3S-001 and up): T.C. A4SW	SA4038WE	Installation of second pilot's seat and dual controls. Issued 10/29/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category): T.C. A3SW	SA4045WE	Installation of second pilot's seat and dual controls. Reissued 1/29/80.	SC	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up as modified by STC SA3897WE): T.C. A4SW	SA4046WE	Installation of passenger/cargo compartment. Reissued 1/29/80.	SC	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category): T.C. A3SW	SA4047WE	Installation of passenger/cargo compartment. Reissued 1/29/80.	SC	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R, S/N 2526R and up modified by STC SA3238WE, S-2R-T34 S/N 6009-6049, S/N T34-001 and up; T.C. A4SW	SA4107WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Issued 3/17/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S-2R S/N 2526R and up modified by STC SA3237WE, S-2R-T34 S/N 6009-6049, S/N T34-001 and up (normal category); T.C. A3SW	SA4108WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Issued 3/17/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
600 S2SR, 800 S-2R; T.C. A4SW	SA266NW	Installation of automatic flagman Model No. 6. Amended 5/12/77.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362
S2R-T34 (Normal Category), S2R-T15 (Restricted Category); T.C. A3SW, A4SW	SA1073SO	Installation of a 500 gallon hopper vent blister kit. Issued 5/29/79.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AT-11, 18, C45 Series; T.C. 2-582, 765	SA401WE	Wraparound windshield. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, C18S, D18S, D18C, E18S, G18S, H18, C45G, C-45H, TC-45G, TC-45H; T.C. 757, 765, 2-582	SA4-383	Metalized control surfaces replacing fabric covered surfaces. Amended 2/21/75.	EA	26833	Courtesy Air Service, Inc. Warren County Airport P.O. Box 561 Glens Falls, NY 12801
AT-11, C18S, D18S, E18S, C45G, C45H T.C. A2-582, A-757, A-765	SA4-1341	Installation of two-piece windshield. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
AT-11, C18S, C-45, -45A, -45G, 45H, D18C, D18S & 9700, G18S, AT-7, -7A, -7B, -7C, JRB-1, -2, -3, -4, -6, SNB-1, -2, -2C, -5, TC-45G, -45H, -45J, UC-45B, 45F; H18 Series BA680, -618 thru -710 & -712 thru -722; 2-582; T.C. 757, 765	SA643CE	Install center section spar reinforcement kit. Amended June 1973.	CE	47250	Ray M. Jourdan 11001 East 59th Street Raytown, MO 64133
AT-11, SNB-1; 18A, S18A; 18D, S18D, A18A, A18D, SA18A, SA18D; 18S, B18S; C18S, C-45, -45A, UC-45B, -45F, AT-7, -7A, -7B, -7C; JRB-1, -2, -3, -4, SNB-2, -2C; 3N, 3NM, JRB-6, D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), RC-45J (SNB-5P); D18C-T; T.C. A-2-52, 630, 684, 710, 757, 765, 770	SA962EA	Installation of Canadian Aerocon Limited fail-safe spar modification. Amended 6/26/74.	EA	19770	Canadian Aerocon Limited Suite 200, 280 Dorval Avenue Dorval 780, Quebec, Canada
AT-11, C18S, D18S, C-45G, H, SNB-5, 3N, 3NM, 3TM; T.C. 2-582, 757, 765	SA995WE	Cargo door installation. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91601
AT-11, AT-7, -7A, -7B, -7C, C18S, C-45, -45A, -C45G, 45H, D18C, D18S, E18S, E18S-9700, G18S, JRB-1, -2, -3, -4, -6, SNB-1, -2, -2C, -5, H18, TC-45G, -45H, -45J, UC-45B, -45F; T.C. 757, 765, 2-582	SA1206CE	Outer wing panel reinforcement. Issued April 1976.	CE	47250	Ray M. Jourdan 11001 East 59th Street Raytown, MO 64133
SNB-5; T.C. 765	SA22CE	Basic airworthiness certification kit. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aviation P.O. Box 11746 Tucson, AZ 85734
17 Series; T.C. 602	SA4-319	Eonite covering of complete airplane.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
17 Series; T.C. 602	SA4-449	Laminate 514 applied to elevator and horizontal stabilizer.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
17 Series: T.C. 713, 638, 649	SA4-673	Eonite covering on rudder, wings and ailerons.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
17 Series: T.C. 713, 638, 649, 641, 689	SA4-1252	Ceconite 101 covering of entire aircraft. Amended 9/21/66.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
17 Series; T.C. 649	SA4-827	Glass cloth applied over wings, fuselage, vertical and horizontal stabilizers.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
17 Series; T.C. 649	SA285EA	Fuselage wood formers and fabric covering replaced with metal.	NE	61535	New England Aero-Tech, Inc. and/or Edmund J. Catallozzi Bowles Airport Agawam, MA 01001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
17 Series; T.C. 649	SA603SO	Main entrance door located on left side of cabin removed.	SO	16300	Lloyd H. Berry 7917 Henry Avenue West Melbourne, FL 32904
17 Series; T.C. 649	SA1008WE	Poly-Fiber covering of fuselage and lower left-hand wing. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
17, 45 Series; T.C. 649, 765	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
17 Series; T.C. 689	SA4-83	Jacobs L4ME engine utilizing Cessna T-50 and locally fabricated components.	NW	52730	William G. McCelland 5502 N. 18th Tacoma, WA 98402
A17, B17B, B17L, B17R, C17B, C17L, C17R, D17A, D17R, D17S, E17B, E17L, F17D, G17S; ATC 560, 579, 602, 604 T.C. 713, 638, A-649, 641, 689, 779	SA555NW	Installation of landing truss assemblies. Issued 1/20/78.	NW	11337	Anything Antiques Route 1, Box 1567-C Yelm, WA 98597
B17L, SB17L, B17B, B17R, C17L, SC17L, C17B, C17R, SC17R, D17A, D17R, D17S, SD17S, E17B, E17L, SE17B, F17D, SF17D, G17S; T.C. 713, 638, 649, 641, 689, 779	SA131GL	Installation of Eastern Aircraft Corp. fuel quantity indicating system. Issued 8/4/76.	GL	31400	Eastern Aircraft Corp. Hangar #2 Grosse Isle Municipal Airport Grosse Isle, MI 48138
D17A; D17R; D17S, SD17S; E17B; F17D; AT-11, SNB-1, C18S; D18C, S, E18S, -9700, G18S, H18, C-45G, TC-45G, C45H, TC-, -45J, JRB-61; T.C. 713, 638, 649, 641, 689, 757, 765	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
17 Series; 18 Series; C-45A, B, S; 23, 33, 35, 36, 50, 55, 65 Series; T.C. A602, A604, A638, A673, A630, A684, A710, A765, A770, A757, A1CE, 3A15, 777, 5A4, 3A16, 3A20	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
D17A; T.C. 713	SA3541WE	Installation of Armour Plate Glass windshields. Reissued 3/20/79.	SC	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
D17R; T.C. 638	SA3545WE	Installation of Armour Plate Glass windshield. Reissued 3/20/79.	SC	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
D17S; T.C. 649	SA2378SW	Replace wheels, brake assembly and master cylinder. Issued 11/5/76.	SW	62520	Stephen H. Parker 414 East Hillmont Road Odessa, TX 79762
D17S, SD17S; T.C. 649	SA3546WE	Installation of Armour Plate Glass windshields. Reissued 3/20/79.	SC	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
D17S, SD17S; C45G; T.C. 649, 765	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
E17B, E17L, SE17B; T.C. 641	SA3542WE	Installation of Armour Plate Glass windshields. Reissued 3/20/79.	SC	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
F17D, SF17D; T.C. 689	SA3543WE	Installation of Armour Plate Glass windshields. Reissued 3/20/79.	SC	74915	Staggerwing Museum Foundation, Inc. P.O. Box 550 Tullahoma, TN 37388
18 Series; T.C. A684, A757, A765	SA814SO	Installation of wing spar strap. Issued December 1974.	SO	08190	Airline Training, Inc. P.O. Box 22833 Fort Lauderdale, FL 33315
18 Series; T.C. 757	SA1-158	New engine baffle system for Pratt & Whitney R-985 engine.	GL	90150	Zelair Corporation P.O. Box 262 Memorial Airport Defiance, OH 43512

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 757	SA1-202	Nacelle modification.	GL	90150	Zelair Corporation P.O. Box 262 Memorial Airport Defiance, OH 43512
18 Series; T.C. 757	SA3-20	Warren McArthur seats 297 and 297D (new designation 297-ST) modified.	GL	77060	Supreme Aircraft Service P.O. Box 82 Elmhurst, IL 60126
18 Series; T.C. 757	SA3-21	Hardman 1200N seats (new designation 1200N-ST1) modified.	GL	77060	Supreme Aircraft Service P.O. Box 82 Elmhurst, IL 60126
18 Series; T.C. 757	SA3-383	Beech D18S Goodyear wheels and brake assembly. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18 Series; T.C. 757	SA3-388	Beech D18S Goodyear wheels and brake assembly.	GL	52560	E.P. Lunken P.O. Box 360 Cincinnati, OH 45202
18 Series; T.C. 757	SA4-21	Fuel system modified to provide dual wobble pumps and suction crossfeed and attendant plumbing. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18 Series; T.C. 757	SA40SC	Main entrance door and cabin window relocated and fuselage station 9A bulkhead web removed.	SO	00086	A & H Aircraft Parts, Inc. P.O. Box 48-1312 Miami, FL 33101
18 Series; T.C. 757	SA69CE	Cabin entry door removed.	GL	22285	James R. Chunn 2222 Fuller Ann Arbor, MI 48106
18 Series; T.C. 757	SA78SC	Gross weight increased to 8,240 lbs. and extended wing tips installed.	SO	55600	Marrs Aircraft Avon Park, FL 33825
18 Series; T.C. 757	SA138SO	D18S landing gear 404-188400 on C18S. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18 Series; T.C. 757	SA302SO	Landing gear and spot brakes D18.	SO	48536	K. Knight & H. Sellers 1250 N.W. 57th Avenue Miami, FL 33101
18 Series; T.C. 757, 765	SA1-225	Enlargement of top pilot window.	GL	05970	Aircraft Service, Inc. Cleveland Hopkins Airport Cleveland, OH 44101
18 Series; T.C. 757, 765	SA3-257	Fiberglas baggage door.	GL	78365	Television Associates of Indiana, Inc. East Baker Avenue Michigan City, IN 46360
18 Series; T.C. 757, 765	SA3-387	Air stair door installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18 Series; T.C. 757, 765	SA3-503	Fuel boost pumps.	RM	11740	M. Lee Arnold 5203 State Street Murray, UT 84107
18 Series; T.C. 757, 765	SA4-32	Internal combustion heaters. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18 Series; T.C. 765	SA1-74	Air step door.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-134	RCA AVQ-50 weather avoidance radar.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18 Series; T.C. 765	SA1-136	Replacement fiberglass nose cap 237.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-154	Fischer and Porter flowmeter system addition to the propeller anti-icer system.	EA	62180	Page Airways, Inc. Rochester Airport Rochester, NY 14603
18 Series; T.C. 765	SA1-161	Enlarged window on each side of fuselage.	EA	71915	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 765	SA1-174	Hartzell HC-93Z30-2C/10152-5 1/2 propellers.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-191	Fuel flow meter system.	GL	05970	Aircraft Service, Inc. Cleveland Hopkins Airport Cleveland, OH 44101
18 Series; T.C. 765	SA1-200	Oxygen system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18 Series; T.C. 765	SA1-226	18" AVQ-50 antenna mount.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-234	12" AVQ-50 antenna mount.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-243	Combination of following STC's: SA1-60 fiberglass nose bowl; SA1-61 auxiliary wing tanks; SA1-62 E18S wing tips; SA1-76 fiberglass tail gear door; SA1-118 three-blade Hartzell propellers; SA1-236 air step door; SA2-383 stabilizer angle of incidence change; SA4-34 main landing gear doors.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-270	Fiberglass clamshell-like parts attached to rear of tail wheel well enclosure doors.	EA	48528	Robert S. Klein and E. Reed Zimmerman Tuckerton Road & Maple Lane Reading, PA 19603
18 Series; T.C. 765	SA1-338	Underseat radar scope mounts for: RCA 5" AVQ-50, Collins 4" WP-103, and RCA 5" AVQ-55/AVQ-20.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-568	Bendix 75-ampere 1273-1A generators and modification B100 to new Model 1273-3 with cooling and electrical changes.	EA	64825	Plymouth Aviation Corporation P.O. Box 247 Forest Hills, NY 11375
18 Series; T.C. 765	SA1-597	Collins WP-103 antenna mounts for 12" WP-103 antenna and 18" WP-103 antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA3-1	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
18 Series; T.C. 765	SA3-91	Grimes D-7080 rotating beacon on belly of aircraft.	GL	38325	Gopher Aviation, Inc. Rochester, MN 55901
18 Series; T.C. 765	SA3-93	Carburetor and windshield fluid deicing systems.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
18 Series; T.C. 765	SA3-134	Installation of electric fuel boost pumps - AN4100. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18 Series; T.C. 765	SA3-177	Electric emergency fuel pumps (Thompson TFD 600-3 pumps with Delco A4949 motors).	GL	38325	Gopher Aviation, Inc. Rochester, MN 55901
18 Series; T.C. 765	SA3-184	Mounting bracket to antenna 137X-1.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
18 Series; T.C. 765	SA3-252	Radome installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18 Series; T.C. 765	SA3-323	Radio DF antenna 137A-2 on bottom of fuselage.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
18 Series; T.C. 765	SA3-410	L-2C autopilot with approach coupler and altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
18 Series; T.C. 765	SA3-417	AP-102 automatic pilot including FD-105 integrated flight system instruments.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 765	SA3-677	Two Delco motors with two Pesco AN 4100, 200 g.p.h. fuel boost pumps.	GL	78610	Toman Aircraft Service 12801 S. 82nd Avenue Palos Park, IL 60464
18 Series; T.C. 765	SA4-992	Ceconite 101 covering of rudders, elevators, flaps and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
18 Series; T.C. 765	SA4-6	Two Janitrol heaters of 25,000 B.t.u. capacity each, Mot. B15C54 in right and left wheel well.	WE	80925	United States Steel Corporation 235 Montgomery Street San Francisco, CA 94010
18 Series; T.C. 765	SA4-125	E18S powerpack for 450 hp. (Maximum continuous and takeoff).	GL	39125	Goodyear Tire & Rubber Company Flight Operations Municipal Airport Akron, OH 44309
18 Series; T.C. 765	SA4-126	One Southwind 940-B 20,000 B.t.u. TSC-C20 heater in each nacelle.	GL	39125	Goodyear Tire & Rubber Company Flight Operations Municipal Airport Akron, OH 44309
18 Series; T.C. 765	SA4-509	Gross weight increased to 9,000 lbs. with powerpack STC SA4-125; Southwind heater STC SA4-126; and horizontal stabilizer STC SA2-120.	WE	67794	Richfield Oil Company 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA4-1076	Electrically-driven, mechanical, refrigerated air conditioner.	WE	08356	Airtransit, Inc. 3131 Monterosa Phoenix, AZ 85000
18 Series; T.C. 765	SA4-1102	Cabin window.	WE	67794	Richfield Oil Company 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA4-1110	Baggage compartment.	WE	67794	Richfield Oil Company 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA4-1378	R-985-APS Series engines. (Applies only to D18S aircraft modified per STC SA2-820.)	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91500
18 Series; T.C. 765	SA7EA	Koehler Air-Lav Model 45.	GL	90065	Youngstown Airways, Inc. Municipal Airport Youngstown, OH 44501
18 Series; T.C. 765	SA52EA	Underseat radar scope mount 299-05 for RCA 5" AVQ-55/AVQ-20 radar	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA111EA	One-piece window on left side of pilot's cockpit.	NE	71780	Simsbury Flying Service, Inc. 94 Walcot Road Simsbury, CT 06070
18 Series; T.C. 765	SA111SO	Installation of wing and empennage surface de-icing system.	EA	25635	Commuter A/C Manufacturing Corp. Box 904, Broome County Airport Binghampton, NY 13902
18 Series; T.C. 765	SA116SW	Combustion monitor.	EA	60100	Monitair Corporation Ramapo Valley Airport Spring Valley, NY 10977
18 Series; T.C. 765	SA186CE	Cowl flap modification kit TYL-6.	GL	14500	Barber-Colman Company Aircraft & Missile Products 1300 Rock Street Rockford, IL 61101
18 Series; T.C. 765	SA206SO	Heater fuse test switch and standby heater fuel system.	SO	75117	J.P. Stevens & Company, Inc. P.O. Drawer 5457, Station B Greenville, SC 29602
18 Series; T.C. 765	SA207CE	Pratt & Whitney R-985-APS engines per STC SE4-864 in aircraft with Beech 9,900 lbs. gross weight kit 766-1.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67202
18 Series; T.C. 765	SA222SO	RCA AVQ-55 radar system and a Narco UDI-2 DME system.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
18 Series; T.C. 765	SA240EA	Elevator trim tab servo as optional equipment with Sperry SP-3 automatic pilot system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18 Series; T.C. 765	SA276WE	Carburetor air filter and scoop.	WE	67794	Richfield Oil Corporation 555 S. Flower Street Los Angeles, CA 90052

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 765	SA297SO	Cabin picture window.	SO	43090	H.V. Howren P.O. Box 20711 Atlanta Airport Atlanta, GA 30304
18 Series; T.C. 765	SA303WE	Heater relocated.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18 Series; T.C. 765	SA335WE	107-gallon integral auxiliary fuel tank in each outer wing with or without fuel dumping provisions.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18 Series; T.C. 765	SA351CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
18 Series; T.C. 765	SA422CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation Marquette Division 1145 Galewood Drive Cleveland, OH 44110
18 Series; T.C. 765	SA473EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4855 Sawyer Road International Airport Columbus, OH 43219
18 Series; T.C. 765	SA468WE	Super 18 type window between bulkheads 9 and 10.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 94106
18 Series; T.C. 765	SA793SW	PT6A-20 (turbo-prop) engines, 2 Hartzell HC-B3TN-3X/T10173-5 props, power compensator and pitch stabilizer system, outer panel fuel tanks, modified wing tip, lengthened nose, increase in angle of incidence of horizontal stabilizer.	SW	29000	The Dee Howard Company 130 South Terminal Drive San Antonio, TX 78205
18 Series; T.C. 765	SA817SW	Modified wing tip.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
18 Series; T.C. 765	SA818SW	Outer wing panel.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
18 Series; T.C. 765	SA832SW	Main wing spar reinforcement.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
18 Series; T.C. 630, 684, 710, 757, 765	SA176SW	Aluminum sheet covering of elevator, rudders and ailerons.	SW	26600	Sherman V. Cornstubble 3707 N. Terry Street Fort Worth, TX 76101
18 Series; T.C. 630, 684, 710, 757, 765, 770	SA365SO	Remove fabric from ailerons, elevator, flap and rudder and replace with aluminum alclad. Amended 10/2/68.	SO	43300	Hudson Aircraft Service P.O. Box 2471 W.A.S. Tallahassee, FL 32300
18, C45; T.C. 757, 765	SA4-167	Aerofilter 1050-B-83 full flow filter with element 1A0094.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
18, C45; T.C. 757, 765	SA4-1387	Deluxe aircraft seat Model 18.	WE	84370	Vroom Aircraft Supply 3321 Burton Avenue Burbank, CA 91500
18, C45; T.C. 757, 765	SA4-1436	Chobert Model 202-406 rivets.	WE	53780	J.F. McRae's Aero-Crafts Building 708, Oakland Airport Oakland, CA 94615
18, C45; T.C. 757, 765	SA4-1510	Rectangular windows in cabin. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
18, C45; T.C. 757, 765	SA19SW	Aircraft seat frame.	SW	17600	Broadie's Aircraft and Engine Service Meacham Field Fort Worth, TX 76106
18, C45; T.C. 757, 765	SA53CE	Stewart-Warner heater 940B 24 in fuselage. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45; T.C. 757, 765	SA70WE	Automatic oil temperature regulator added to Beech oil coolers 94-189850 LH and 94-189840-1 RH. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45; T.C. 757, 765	SA145SO	Three additional windows.	SO	02470	Aero Products Engineering, Inc. P.O. Box 602 Miami, FL 33101
18, C45; T.C. 757, 765	SA192WE	Baggage compartment.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45; T.C. 757, 765	SA276SW	Folding door bulkhead 5.	SW	74125	Spartan Aircraft Company Aviation Service Division Municipal Airport Tulsa, OK 74115
18, C45; T.C. 757, 765	SA299SO	Aerial camera.	SO	43090	H.V. Howren Atlanta Airport Atlanta, GA 30304
18, C45; T.C. 757, 765	SA698WE	75-gallon outer wing fuel tanks.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 757, 765	SA813WE	Fiberglass wing tips 11048.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
18, C45 Series; T.C. 757, 765	SA1008WE	Poly-Fiber covering of elevator, rudders, ailerons and flaps. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
18, C45 Series; T.C. 757, 765, 770	SA3-732	Full-view passenger window. REissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 757, 765, 770	SA24CE	Oval passenger windows. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA1-45	Increase in window dimensions. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
18, C45 Series; T.C. 765	SA1-60	Fiberglass nose bowl assemblies 1005-C1-100 through -800.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA1-62	E18S wing tips Beech 414-18, 1500-610 right and -609 left.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA1-76	Full contour tail gear doors 215.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA1-242	Enlarged window on each side of fuselage.	EA	71915	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
18, C45 Series; T.C. 765	SA1-244	Enlarged windows in cabin.	EA	71915	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
18, C45 Series; T.C. 765	SA1-302	Upper nacelle modification.	GL	90150	Zelair Corporation P.O. Box 262 Defiance, OH 43512
18, C45 Series; T.C. 765	SA1-355	Increase to 9,000 lbs. gross weight and 450 hp.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA1-398	Pratt & Whitney R-985 engine installation with Simmonds Aerocessories 580047 fuel injector per STC SE1-391. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA1-427	Pratt & Whitney R-985 engine installation with Simmonds Aerocessories 580047 fuel injector per STC SE1-391, and takeoff weight increase to 9,800 lbs. and landing weight to 9,400 lbs. per STC SA2-820. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA1-502	Electrothermal propeller deicing system.	GL	38500	B. F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series; T.C. 765	SA3-81	Nose cap modification.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
18, C45 Series; T.C. 765	SA3-277	Rear cabin porthole window modification and two additional windows forward of bulkhead 11.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-278	Web removed from bulkheads 9 and 10 and baggage compartment installed between bulkheads 10 and 11 and 11 and 12.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-279	Nose section modification including E18S type nose cone and cover assembly installation of radar and radio racks.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-280	Type E18S tail wheel fork and truss assembly.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-313	New picture window between frames 5 and 7 on both sides of fuselage.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
18, C45 Series; T.C. 765	SA3-343	One standard cabin window between bulkheads 8 and 9 right side opposite cabin door.	GL	18752	Butler Aviation 4848 W. 63rd Street Chicago, IL 60607
18, C45 Series; T.C. 765	SA3-391	Cabin window and interior modification. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18, C45 Series; T.C. 765	SA3-409	Increase fuselage height, large windows, panorama windows, stair door, and emergency exit. Amended 1/1/67.	EA	05200	Aircraft Industries of Canada, Ltd. P.O. Box 100 St. Johns, Quebec, Canada
18, C45 Series; T.C. 765	SA3-476	L-2C autopilot with altitude control and approach coupler. (Eligible only on aircraft modified per STC SA2-820.)	GL	49860	Lear, Inc. 3714 Jefferson Avenue, S.E. Grand Rapids, MI 49501
18, C45 Series; T.C. 765	SA3-563	Cargo door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18, C45 Series; T.C. 765	SA3-629	Scott oxygen system.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
18, C45 Series; T.C. 765	SA3-630	Two each skylight windows enlarged in cockpit with Conrad one-piece windshield per STC SA2-204.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
18, C45 Series; T.C. 765	SA3-632	Beech Kit 581-1, except angle of incidence change (Item 602) and stall strips (Item 607c) of Spec. A-765; with STC SA2-383, with or without STC's SA2-204 and SA3-409; and wing spar modification. Maximum gross weight: takeoff 9,500 lbs., landing 9,400 lbs.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA3-697	Hydraulic unfeathering accumulator system in each nacelle on aircraft with Hartzell propellers.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
18, C45 Series; T.C. 765	SA3-738	M-4 flight control system. (Model may also be designated as Conrad 9800D, Conrad 10,200.)	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
18, C45 Series; T.C. 765	SA4-113	Safety performance kit, increase gross weight to 9,000 lbs. takeoff and landing when Pratt & Whitney R-985-AN4, -AN10, or -AN14B is modified using Hamilton Standard 22D30/6531-15 propellers or Hartzell HC-93Z30-2G10152-5 1/2 per STC SA1-118. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA4-119	Revised horizontal stabilizer angle of incidence from -2 degrees to -1/2 degrees. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series T.C. 765	SA4-152	One Model 940 Stewart-Warner heater in each wheel well. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA4-569	54-, 63-, or 107-gallon integral auxiliary fuel tank in each outer wing with or without fuel dump provisions and landing light installation.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA4-595	Fillet installation wing-fuselage and wing nacelle. (Eligible with STC's SA2-204 one-piece windshield and flush cockpit side windows; SA4-34 main landing gear door; SA4-113 Pratt & Whitney R-985-AN14B or -AN4 engines, wheel well door and elevator sealing strip; SA4-119 revised horizontal stabilizer angle of incidence; SA4-152 Stewart-Warner 940 heaters.)	WE	17108	Vance Breese 621 N. Arden Beverly Hills, CA 91203
18, C45 Series; T.C. 765	SA4-718	Auxiliary nose fuel tanks.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA4-769	Cambridge fuel air ratio analyzers.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA4-882	Large windows.	WE	17108	Vance Breese 621 N. Arden Beverly Hills, CA 91203
18, C45 Series; T.C. 765	SA4-910	New window.	WE	19900	Carma Aircraft Company P.O. Box 11312 Municipal Airport Tucson, AZ 85700
18, C45 Series; T.C. 765	SA4-922	Left-hand baggage door and baggage compartment.	WE	17108	Vance Breese 621 N. Arden Beverly Hills, CA 91203
18, C45 Series; T.C. 765	SA4-1035	Door frame between cabin and cockpit modified for folding door.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA4-1116	Three additional windows.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA4-1185	Stair door.	WE	17108	Vance Breese 621 N. Arden Beverly Hills, CA 91203
18, C45 Series; T.C. 765	SA4-1368	Wing tips.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA4-1397	Tricycle landing gear and nose assembly.	WE	84000	Volpar, Inc. 11035 Sutter Avenue Pacoima, CA 91331
18, C45 Series; T.C. 765	SA4-1486	Additional seats.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Sries; T.C. 765	SA4-1531	Tricycle landing gear and nose assembly with optional radome.	WE	84000	Volpar, Inc. 11035 Sutter Avenue Pacoima, CA 91331
18, C45 Series; T.C. 765	SA4-1536	Picture window G18 type.	WE	10360	American Turbine Eng. Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA4-1578	Main cabin entrance door replaced with stair door.	WE	83780	Volitan Aviation, Inc. 12820 Pierce Street Pacoima, CA 91331
18, C45 Series; T.C. 765	SA4-1595	Divan B-138.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA4-1596	Five TSO chairs.	WE	10360	American Turbine Engine Company 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA4-1624	Non-icing vent fairings.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series T.C. 765	SA4-1645	Stewart-Warner 8259A heater.	WE	83780	Volitan Aviation, Inc. 12820 Pierce Street Pacoima, CA 91331
18, C45 Series; T.C. 765	SA1EA	Full contour tail gear doors 312. (Eligible on Models D18S, C45C, C45H, TC45G and TC45H when tail wheel modified per item 608 of Aircraft Spec. A-765.)	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18, C45 Series; T.C. 765	SA27SC	Elevator door spring. (Model may also be designated as Conrad 9800D.) Reissued 8/15/68.	SC	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA31SC	Tricycle landing gear and revised nose assembly with optional radome. (Model may also be designated as Conrad 10,200.) Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
18, C45 Series; T.C. 765	SA46SC	Carburetor air scoop and air filter screen using carburetor and fiberglass air intake duct.	SC	73065	Gene E. Smith 4030 Matheson Avenue Miami, FL 33101
18, C45 Series; T.C. 765	SA55SW	Electrical pitch trim system.	SW	78430	Pat Thayer Aviation Electronics, Inc. P.O. Box 16037 International Airport San Antonio, TX 78205
18, C45 Series; T.C. 765	SA61CE	ALS-10A maximum safety light system. (Eligible only on aircraft having item 603, Aircraft Spec. A-765 installed.)	GL	12488	Atkins Light Corporation 7636 Lyndale Avenue, South Minneapolis, MN 55401
18, C45 Series; T.C. 765	SA76WE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
18, C45 Series; T.C. 765	SA80SC	Fiberglass nose cone.	SO	73065	Gene E. Smith 4040 Metneson Avenue Miami, FL 33101
18, C45 Series; T.C. 765	SA84SC	Seat track.	SO	02470	Aero Products Engineering, Inc. P.O. Box 48-602 Miami, FL 33101
18, C45 Series; T.C. 765	SA86SW	Enlarged cabin windows, left and right side, and emergency exit relocated.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
18, C45 Series; T.C. 765	SA111WE	Mark IV tricycle landing gear.	WE	84000	Volpar, Inc. 11035 Sutter Avenue Pacoima, CA 91331
18, C45 Series; T.C. 765	SA114SO	Substitute control wheel.	SO	37086	Garcia Aviation Company 15801 S.W. 120th Avenue Miami, FL 33101
18, C45 Series; T.C. 765	SA145SW	Cabin door (hinged at the bottom).	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
18, C45 Series; T.C. 765	SA148WE	RCA AVQ-55 weather mapping radar system.	WE	62080	Pacific Airmotive Corporation Aircraft & Eng. Center 3000 N. Clybourn Avenue Burbank, CA 91502
18, C45 Series; T.C. 765	SA149SO	Cabin picture windows.	SO	02470	Aero Products Engineering, Inc. P.O. Box 602 Miami, FL 33101
18, C45 Series; T.C. 765	SA150SW	Southwind heater 8259A (45,000 (B.t.u.), one in each side of the center wing section.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
18, C45 Series; T.C. 765	SA151SW	Windshield anti-icer system and three-gallon tank.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
18, C45 Series; T.C. 765	SA155SW	Metal covering of flaps.	SW	26600	Sherman V. Cornstubble 3507 N. Terry Fort Worth, TX 76101
18, C45 Series; T.C. 765	SA158SW	Pilot and copilot tracking seats.	GL	61234	National Flight Service, Inc. 105 E. Alexis Road Toledo, OH 43601

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series; T.C. 765	SA161SW	Cabin picture windows left and right sides.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
18, C45 Series; T.C. 765	SA174CE	Twin-engine electronic synchronizer for aircraft equipped with Hartzell propellers.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
18, C45 Series; T.C. 765	SA209SW	Nose heater. (Model may also be designated as Conrad 9800D, Conrad 9800E.)	SW	26780	Crest Conversions, Inc. Route 13, Box 490E San Antonio, TX 78205
18, C45 Series; T.C. 765	SA266EA	Installation of Chamberlain Engineering 2003K-B radome and antenna mount transmitter/receiver support bracket for use with 12 inch Bendix radar system No. RDR-100 or RDR-110. Amended 3/11/70.	GL	61750	Norton Company Plastics & Snythetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
18, C45 Series; T.C. 765	SA276CE	Picture window.	CE	65300	Product Development Group, Inc. P.O. Box 117 Rose Hill, KS 67133
18, C45 Series; T.C. 765	SA285WE	Nose strut snubber for aircraft with Volpar Trigear.	WE	84000	Volpar, Inc. 11035 Sutter Avenue Pacoima, CA 91331
18, C45 Series; T.C. 765	SA289WE	Carburetor air scoops.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA290WE	Main landing gear doors.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA305WE	Cabin modified to G18 configuration.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA321SW	Fuel system modified with STC SA459WE - 165-gallon wing fuel tanks.	SW	26780	Crest Conversions, Inc. Route 13, Box 490E San Antonio, TX 78205
18, C45 Series; T.C. 765	SA331WE	Baggage compartment. 107-gallon main fuel tank in each outboard wing panel required per STC SA333WE.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA332WE	Propeller spinners and increase in maximum continuous power to 450 hp.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA333WE	107-gallon main fuel tank in each outboard wing panel.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA356WE	A3A autopilot.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91203
18, C45 Series; T.C. 765	SA420WE	Stewart-Warner Series 940 combustion heaters in nacelle turtlebacks.	WE	39877	Hamilton Aircraft Company, Inc. 6501 S. Park Avenue Tucson, AZ 85706
18, C45 Series; T.C. 765	SA548WE	Air stair door.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
18, C45 Series; T.C. 765	SA554WE	Square topped stair cabin door.	WE	83780	Volitian Aviation, Inc. 12820 Pierce Street Pacoima, CA 91331
18, C45 Series; T.C. 765	SA564WE	Nine seats.	WE	09850	Al's Aircraft Interiors 2700 E. Wardlow Road Long Beach, CA 90806
18, C45 Series; T.C. 765	SA728WE	Extension of tail wheel. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma AVenue North Hollywood, CA 91406
18, C45 Series; T.C. 765	SA1011WE	100-gallon auxiliary outerwing fuel tanks.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA1135WE	Auxiliary 45-gallon wing leading edge fuel tank.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA1226WE	M-4 automatic flight control system.	EA	16030	The Bendix Corporation East Joppa Road Towson, MD 21204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18, C45 Series; T.C. 765	SA1258WE	Baggage compartment in forward and rear auxiliary fuel tank area and 100 gallon auxiliary fuel tank in outer wing.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 765	SA1277WE	Baggage compartment in forward and rear auxiliary fuel tank area, and 165 gallon auxiliary fuel tank in outer wing.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18, C45 Series; T.C. 684, 757, 765	SA1276WE	Replacement of carbon pile voltage regulator for 28-volt DC generator with Leland Airborne Products Type CSV-1105-2 solid state voltage regulator. Reissued 7/25/68.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91500
18 Series, C-45A, B, S, 50, 55 Series, 56TC, 65 Series; T.C. A630, A684, A710, A765, A770, A-757, 5A4, 3A16, 3A20	SA1675WE	Installation of exhaust gas temperature monitoring systems Model EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
18 Series, C-45, B, S, 23, 35, 50, 55 Series; T.C. A630, A684, A710, A765, A770, A757, A1CE, 777, 5A4, 3A16	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm).	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
18S, B18S, C-45C, F-2; T.C. 710	SA1152CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
C18, D18; T.C. A757, A765	SA389SO	Install cargo door; metalized ailerons, elevator, rudders, wing flaps. Reissued 4/12/73.	GL	05390	Aircraft Maintenance Specialists Janesville, WI 53545
C18S; T.C. 765	SA4-713	Installation of Stewart-Warner Model 940B heater in engine nacelles. REissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
C18S; T.C. 765	SA4-714	Installation of stabilizer angle of incidence change. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
C18S, AT-11, D18C, D18S, E18S, C45G, H, TC-45J (SNB-5), 3N, 3NM, 3TM, TC-45G, H, JRB-6, E18S-9700, G18S, H18; T.C. A-765, A-757,	SA2000WE	Installation of wing spar reinforcement. Reissued and amended 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aviation P.O. Box 11427 Tucson, AZ 85734
C18S, D18S, C-45G, H, TC45G, TC-45H; T.C. 757, A-765	SA4-875	Installation of Stewart-Warner Model 940B or 940F or 940C heater. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
C18S, D18S, C-45G, H, TC-45G, H, E18S, SNB-5, JRB-6, 3N, 3NM, 3TM; T.C. 757, 765	SA4-1584	Installation of two-piece plexiglass windshield. Amended 1/6/69.	WE	39877	Hamilton Aircraft Company, Inc. P.O. Box 11427 Tucson, AZ 85706
C18S, D18S, C-45G, C-45H, TC-45G, TC-45H; T.C. A757, A765	SA151SO	Installation of three additional windows. Reissued 9/11/79.	SO	08170	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
C18S, D18S, C-45G, -45H, TC-45G, -45H; SNB-5, JRB-6, 3N, 3NM, 3TM; T.C. A-757, A-765	SA419WE	Installation of modified tail wheel fork and truss assembly. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
C18S, D18S, C-45G, H, TC-45G, H, SNB-5, 3N, 3NM, 3TM; T.C. 757, 765	SA1448WE	Installation of cockpit entrance door. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
C18S, D18S, E18S, E18S-9700, C-45G, H, TC-45G, H, J, SNB-5, JRB-6; T.C. 765, 757 (for C18S)	SA459WE	Installation of 167-gallon main fuel tank in each outboard wing panel. Amended 8/2/68.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
C18S, E18S, E18S-9700, G18S, H18S, C45G, -H, TC45G, -H, -J (SNB-5), JRB-6; T.C. 765	SA895SW	Outer wing panel spar beef up.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78216

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
C18S, C-45, C-45A, B, C, F, UC-45B, F, AT-7, AT-7A, B, C, JRB-1, -2, -3, -4, SNB-2, -2C; T.C. 757	SA1153CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
C18S thru H18S, AT-7, -7A, -7B, -7C, C45, C45A, -45G & H, UC-45B & F, TC45G & H; T.C. A765	SA1744WE	Installation of various series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
C18S, D18S, C-45G, H, TC-45J; 3N, 3NM, 3TM, JRB-6; T.C. A-757, A-765	SA1905WE	Installation of cockpit exterior door on left side. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 International Airport Tucson, AZ 85706
C18S, C-45, -45A, UC-45B, -45F, AT-7, -7A, -7B, -7C, D18S, C45G, H, TC-45G, H, E18S, E18S-9700, G18S; T.C. 757, 765	SA1995O	Fabric attachment clips in place of rib lacing cord. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
C-18S, C-45, -45A, UC-45B, -45F, AT-7, -7A, -7B, -7C, JRB-1, -2, -3, -4, SNB-2, -2C; T.C. 757	SA3010WE	Installation of wing spar reinforcement. Reissued 4/24/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, JRB-6, SNB-5, C45G-H, TC45G, -H, 3N, 3NM, 3TM; T.C. A-765	SA4-1462	Gross weight modification. Amended 3/21/75	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, SNB-5, C45G, -H, TC45G, -H; T.C. A-765	SA4-1571	Gross weight increase modification; installation of tricycle landing gear, windshield, outer wing fuel tanks, picture window. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, SNB-5, C45G, -45H, TC-45G, -45H, JRB-6; T.C. A-765	SA360WE	"PAC Tradewind Modification" - (Gross weight modification, empennage modification, installation of tricycle gear, windshield, outer wing fuel tanks, M-4 autopilot, Bendix RS10B fuel injection system, and optional R-985 APS4 engines). Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, E18S, E18S-9700, C45-G, -H, TC45-G, -H, -J, SNB-5, JRB-6; T.C. 765	SA370WE	Installation of 167-gallon auxiliary outer wing fuel tanks. Amended 8/2/68.	WE	06750	Aircraft TAnk Service, Inc. 10201 Cohasset Street Burbank, CA 91504
D18C, D18S, SNB-5, C45G, -H, TC-45G, -H; T.C. A-765	SA398WE	Electrical wiring simplification and modernization to effect improvements in electrical load distribution and protection. Reissued 1/9/75.	WE	06750	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, JRB-6, SNB-5, C-45G, -45H, TC-45G, -H; T.C. A-765	SA543WE	Installation of L2-C autopilot. Reissued 1/9/75.	WE	06750	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, SNB-5, C45-G, -H, TC-45G, -H; T.C. A-765	SA547WE	Installation of cockpit lever control knobs. Reissued 1/9/75.	WE	06750	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, E18S, G18S, SNB-5, JRB-6, H18, C45G, C45H, TC45G, TC45H; T.C. A-765	SA567WE	Installation of South Wind Model 8259-A heater in nose assembly of aircraft modified for tricycle landing gear per STC SA4-1531 or SA111WE. Reissued 1/9/75.	WE	06750	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D18C, -S, E18S, -9700, G18S, H18, C45G, TC45G, C45H, TC45H-J, JRB-6, SNB-5 and STC-SA111WE; A-35, B- thru F, 35R; G-35, H-J-K-M-N-P, V35, 5A4 and STC SA76SW; 35-33, A33, B33, 50, 50A, B, C, D50A, D50B, C, D, E, F, G, H, J, F50, 56TC, 60, 65, A65, 65-80, -A80, B80, 70, 95, B95, B95A, D95, 95-55, -55A, D55; T.C. 765, A777, 3A20, 5A4, 3A15, A12CE, 3A20, 3A16	SA660WE	Installation of HRD-type fire extinguishing and detector system. Amended 7/11/77.	WE	43180	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
D18C, D18S, E18S, E18S-9700, G18S, H18, C45G, C45H, TC45G, TC-45H, TC-45J (SNB-5), JRB-6; T.C. 765	SA745SW	Mitchell automatic flight system AK235, Century III autopilot with opticnal pitch trim and/or radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6, 3N, 3NM, 3TM; T.C. 765	SA1016WE	Installation of United Aircraft of Canada Ltd. PT6 series engines. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, H, TC-45G, H, J, 3N, 3NM, 3TM, JRB-6, SNB-5, RC-45J, NSB-5P, UC-45J; T.C. 765	SA1154CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
D18C-5; T.C. 770	SA1155CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
D18C, D18S, E18S-9700, C45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6, G18S, H18, C-45J; T.C. A-765	SA1171WE	Installation of two AiResearch TPE 331 Series engines, tricycle landing gear, wing platform. Amended 1/22/69.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
D18C, D18S, C45G, C45H, E18S, TC-45G, -45H, JRB-6, SNB-5, 3N, 3NM, 3TM; T.C. A-765	SA1192WE	Modification of main spar. Reissued 1/9/75.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, D18S, E18S, E18S-9700, G18S, H18, C45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6; T.C. 765	SA1636WE	Installation of AiResearch TPE 331 series engine, tricycle landing gear and ventral fin, extension of fuselage and related changes. Amended 4/20/72.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
D18C, D18S, E18S-9700, E18S, C-45G, -45H, TC-45G, -45H, -45J (SNB-5), JRB-6, G-18S, H18; T.C. A-765	SA1832WE	Installation of Volpar Tricycle Landing Gear. Amended 10/26/73.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
D18C, D18S, E18S-9700, C45G, H, J, 3N, 3NM, 3TM, TC-45G, H, J, JRB-6; T.C. A-765	SA1961WE	Cabin floor installation. Amended 10/19/77.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue North Hollywood, CA 91406
D18C, -S, E18S-9700, C45G, -H, TC-45G, -H, -J, SNB-6, JRB-6; T.C. 765	SA2204WE	Installation of 2 AiResearch TPE 331-1 series turbo prop engines with Hartzell HCB3TN propellers: 8-1/2 inches extension of fuselage and ventral fin, tricycle landing gear installation and related modifications. Amended 8/27/71.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 91406
D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J (SNB-5), JRB-6, 3N, 3NM, 3TM; T.C. A-765	SA2353WE	Installation of cargo pod. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
23 (S/N M-555 and up), A23, A23A, A23-19, A23-24, B23, C23, 19A, B19, M19A, A24, A24R, B24R, C24R; T.C. A1CE	SA1147EA	Installation of DeVore vertical tail floodlights on upper surface of horizontal stabilator. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
23, A23, A23A, A23-19, -19A, -24, B23; 35, A35 thru G35; 35-33, -A33, -B33, -C33, -C33A, H35, J-, K-, M-, N-, P-, S-, V-; 95, B95, B95A, -55, -A55, B55, B55B, C-55; T.C. A1CE, A777, 3A15, 3A16	SA1262WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
23, A23, A23A, A23-19, A23-24; S35, V35, 35-33, 35-A33, B-33, -C33, 35-C33A; 50, B50, C, D, D50A, B, C, E, F50, F, G, H, J; 95, B95, -A, D95A, -55, -A55, -B55, C-55; T.C. A1CE, 3A15, 5A4, 3A16	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R; T.C. A1CE	SA1346SW	Mitchell automatic flight system AK341 cons. of Century I and opt. Omni Tracker. Issued 7/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R; T.C. A1CE	SA1348SW	Mitchell automatic flight system AK342 cons. of Century II autopilot with opt. radio coupler. Issued 7/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
23, A-23, A-23A, A23-19, A-23-24, 19A, B23; 35, A35, B35, C35, 35R, D35, E-, F-, G-; H35, J-K-M-, 35-33, N35, 35-A33-B33, P35, S35, 35-C33, E33, V35, V35A, 35-C33A, E33A; T.C. A1CE, 777, 3A15	SA1716WE	Installation of exhaust gas temperature system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R, B24R; T.C. A1CE	SA3214SW-D	Mitchell automatic flight system AK342 consisting of Century IIB autopilot with optional radio coupler. Issued 6/77/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
23, A23, A23A, A23-19, 19A, M19, M19A, A23-24 B23, C23, A24, A24R, B24R, C24R; T.C. A1CE	SA3223SW-D	Mitchell automatic flight system consisting of Century I autopilot and optional omni tracker. Issued 6/21/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A23-24; T.C. A1CE	SA3291WE	Installation of Pathfinder autopilot systems. Issued 11/9/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
B23; T.C. A1CE	SA664CE	Installation of Hoskins MK1B Light System. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
C23; T.C. A1CE	SA3331SW-D	Mitchell automatic flight system AK779, consisting of Century I autopilot with optional omni tracker. Issued 1/24/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C23; T.C. A1CE	SA3332SW-D	Mitchell automatic flight system AK780 consisting of Century IIB autopilot with optional radio couplers. Issued 1/24/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
Beech C23; T.C. A1CE	SA3799WE	Installation of flexible stainless steel oil cooler hoses. Issued 11/28/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
A24R, B24R, C24R; T.C. A1CE	SA4015WE	Installation of SDI model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 9/17/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B24R; T.C. A1CE	SA1701SW	Mitchell command electric trim system Model AK454. Issued 7/11/73.	SW	60000	Mitchell Industries, Inc. Box 610 Municipal Airport Mineral Wells, TX 76067
B24R; T.C. A1CE	SA3016SW-D	Mitchell AK544 cons. of Century III autopilot with opt. radio coupler and glide slope coupler. Issued 1/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
B24R; C24R; T.C. A1CE	SA3156WE	Installation of Pathfinder autopilot systems. Issued 3/16/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
B24R, C24R; T.C. A1CE	SA3160SW-D	Install Mitchell command electric trim system Model AK454. Issued 10/4/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C24R; T.C. A1CE	SA3313SW-D	Mitchell automatic flight system AK768, consisting of Century IIB autopilot with optional radio coupler. Issued 12/28/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C24R; T.C. A1CE	SA3314SW-D	Mitchell automatic flight system AK769 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 12/28/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C24R; T.C. A1CE	SA3315SW-D	Mitchell command electric trim, AK770. Issued 12/28/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral WElls, TX 76067
35 "Bonanza"; T.C. 777	SA1-460	Auxiliary wing tip fuel tanks. Reissued 2/14/75	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route #1, Box 172D Leesburg, FL 32738
35 Series; T.C. 777	SA222CE	Reinforce front lower carry-through section & wing attach fittings. Amended 6/2/80.	CE	47250	R.M. Jourdan & James Flanagan 11001 East 59th Street Raytown, MO 64133
35 Series; T.C. 777	SA387SO	Installation of Aviation Elec. Omni bearing tester Model OBT-X in accordance with AET Drawing Nos. 1001, 1002, 1003..	SO	13250	Aviation Electronics, Inc. DeKalb-Peachtree Airport Chamblee, GA 30005
35 Series; T.C. 777	SA599EA	Installation electronic voltage alarm, Drawing No. 80105.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
35 Series; T.C. 777	SA800SW	AK245 Century II Autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777	SA1493WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777	SA1902SW	Automatic flight system AK348 cons. of Century I autopilot with optional omni tracker. Issued 7/19/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
35 Series; T.C. 777	SA2144WE	Installation of Madras Air Service Part No. MAS 102 wing tips.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
35 Series; T.C. 777	SA2208WE	Installation of Red-Q-Mark Signet A-MK-100 or A-MK-110 marker assembly. Amended 8/7/70.	WE	67500	Res-Q-Mark International, Inc. 44 West Stetson Drive Scottsdale, AZ 85251
35 Series; T.C. 777, 3A15	SA1-55	Federal F-200 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
35 Series; T.C. 777, 3A15	SA1-341	Oil-free vacuum pump PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
35 Series; T.C. 777, 3A15	SA1-343	Oil-free vacuum pump.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A35, B, C, D, E, F, G; T.C. 777	SA3113SW-D	Automatic flight system AK415 cons. of Century IIB autopilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35, A36TC; T.C. 3A15	SA3339SW	Installation of Mitchell automatic flight system Model AK809 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C35; T.C. A-777	SA236GL	Installation of a Continental O-470-G engine and McCauley propeller #2A36C23-11-DE/S-84B-0. Issued 5/4/78.	GL	74970	Robert Steffey 37344 Woodland New Baltimore, MI 48047
C35 thru H35, J35, K35, M35, N35, 35-33, 35-A33; T.C. A-777, 3A15	SA361EA	A. Installation of monitair angle of attack and stall warning kit number 92-107, and B. Installation of Monitair angle of attack and stall warning kit number 92-105. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
C35, D35, E35, F35, G35; T.C. A-777	SA604NW	Install Lycoming IO-540-K engine and Hartzell HC-E2YR-1BF/F8476D-4 propeller. Issued 7/6/78.	NW	52625	Machen, Inc. S.3608 Davison Boulevard Spokane, WA 99204
C35, D35, E35, F35, G35; T.C. A-777	SA1584CE	Installation of elevator tail cone fairing. Issued 4/15/80.	CE	73220	Smith Speed Conversions, Inc. P.O. Box 430 Johnson, KS 67855
C35, D35, E35, F35, G35; T.C. 777	SA3267SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. 777	SA3268SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. A-777	SA4000WE	Installation of radome in wing leading edge. Issued 7/27/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
E-35; T.C. A-777	SA4043WE	Installation of Continental IO-520-BA engine and McCauley 3A32C propeller. Issued 10/26/79.	WE	06755	Aircraft Technical Service, Inc. 6701 Odessa Avenue Van Nuys, CA 91406
F35; T.C. 7777	SA173GL	Installation of Dukes fuel pump P/N 4140-00-39. Issued 5/27/77.	GL	01838	Aerodynamics, Inc. Oakland Pontiac Airport P.O. Box 508 Pontiac, MI 48056
H35, J35, K35, M35, N35, P35, S35, 35-33, -A33, -B33, -C33, -33A; T.C. 3A15	SA1-636	Install 300 Series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
H35 Series; T.C. 777	SA198NW	Installation of 3 bladed McCauley 3A34C76FM/S82NB-2 propeller with Woodward A210680 governor on Continental O-470-G engine. Issued 7/21/75.	NW	77570	Mel G. Taylor 20005 Northeast 13th Street Camas, WA 98607
H35 Series; T.C. 777	SA259NW	Installation of TCM continuous flow fuel injection system (EO No. 5701) replacing carbureation system. Issued 2/17/76.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road South Seattle, WA 98108
35 Series H thru P; T.C. 3A15	SA470NW	Installation of Cessna oil filter. Issued 7/14/77.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road Seattle, WA 98108
H35, J35, K35, M-35, N-35, P35, 35-33, 35-A33, 35-B33, 35-C33, E33, F33; T.C. 3A15	SA695CE	Install Frantz oil filter. Amended 5/27/71.	GL	70360	Schmidt Aero Service Municipal Airport Worthington, MN 56187
H35, J35, K35, M35, N35, P35, S35, V35, V35B, 35-C33A, E33A, E33C, F33A, F33C, G33, 36, A36; T.C. 3A15	SA884SO	Installation of exhaust silencers. Issued 2/11/76.	SO	16505	Beryl D'Sharron Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, 35-33, E33, -A33, -C33; T.C. 3A15	SA975SW	Installation of cabin air conditioner. Reissued 5/7/79.	RM	01950	Aero Engineering Corporation 8C Garden Center Broomfield, CO 80020

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H35, J35, K35, M35, N35, P35, 35-33, 35-A33, -B33, -C33, E33, F33; T.C. 3A15	SA1252WE	Installation of Rajay turbocharged Continental O-470-G-C1 and/or IO-470-C, -J, -K, -N engines. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90807
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA1585CE	Installation of elevator tail cone fairing. Issued 4/15/80.	CE	73220	Smith Speed Conversions, Inc. Box 430 Johnson, KS 67855
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-33, -A33, -B33, -C33, -C33A, G33, -E33A, F33A, 35, A35; T.C. 3A15	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, M35, N35, P35, S35, V35, V35A, F33A, 35-33, -A33, -B33, -C33, -C33A, E33A, G33, 36, A36; T.C. 3A15	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33; T.C. 3A15	SA2870WE	Installation of right and left hand cockpit side windows. Reissued 2/2/75.	SC	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA3117SW-D	Mitchell automatic flight system AK328 cons. of Century I autopilot with optional omni tracker. Issued 3/16/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35; T.C. 3A15	SA3127SW-D	Mitchell automatic flight system AK415 cons. of Century IIB auto- pilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33C, F33A, G33, 36, A36; T.C. 3A15	SA3184WE	Installation of ventral air skeg. Amended 4/12/79.	WE	84396	Walker Engineering 2240 Sawtelle Boulevard Los Angeles, CA 90064
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B (Utility Category); T.C. 3A15	SA3190WE	Installation of wing tip fences. Issued 5/11/76.	WE	64690	JOhn Pixton Enterprises P.O. Box 342 Santa Rosa, CA 95402
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3269SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3270SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35; T.C. 3A15	SA3310WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/6/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, 35-33, -A33, -B33, -C33; T.C. 3A15	SA3523WE	Installation of an airfoil separator in the engine breather system. Issued 11/25/77.	WE	84396	Walker Engineering Co. 2240 Sawtelle Los Angeles, CA 90025
H35, J35, K35, M35, N35, P35, S35, V35, F33, E33A, E33C, F33, F33A, F33C, G33, V35A, V35B, 36, A36, A36TC; T.C. 3A15	SA3999WE	Installation of radome in wing leading edge. Amended 8/14/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36, A36TC; T.C. 3A15	SA4100WE	Installation of DTL-1000, -1001 and/or -1002/3 cautopilot adapters for the Edo-Aire Mitchell Century III autopilot. Issued 2/12/80.	WE	47775	Douglas L. Fettler 1212 North Boradway, Apt. H Escondido, CA 92026

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36, A36TC; T.C. 3A15	SA4180WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
J35; T.C. 3A15	SA686CE	Install Continental IO-520-V engine derated to 250 H.P. and Hartzell HC-C3YF-1/8468A-8R propellers. Reissued March 1975.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
J35, K35, M35, 35-33; T.C. 3A15	SA1-354	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
J35, V35, A35, B35, C35, D35, E35, F35, G35; T.C. 3A15, 777	SA754SW	Mitchell automatic aileron stabilizer AK203.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
J35, K35, M35, N35, P35, S35, V35, V35B, E33, E33A, F33, F33A, 36, A36, 35-33, -A33, -B33, -C33, E33C, F33C, -C33A, V35A; T.C. 3A15	SA1474CE	Installation of redundant engine fuel flow transmitter and cockpit indicator. Reissued 4/24/79.	WE	71740	Silver Instruments, Inc. 2436 Stanwell Drive Concord, CA 94520
J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2978WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA1140CE	Installation of King model KFC-200 2-axis (3 optional) autopilot system with a King KCS-55 (or -55A) compass with a King KI-255 (or KI-256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 7/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M35; T.C. 3A15	SA958EA	Installation of Teledyne Continental IO-520-Ba Engine and associated components in place of Teledyne Continental IO-470-C engine and associated components. Issued 7/30/73.	EA	41760	Helicopter & Airplane Service Corp. Montgomery County Airpark Gaithersburg, MD 20760
N35; T.C. 3A15	SA4193WE	Replacing the control instrument panel. Issued 7/29/80.	WE	13300	Aviation Enterprises, Inc. 2870 East Wardlow Road Long Beach, CA 90807
N35, P35, S35; T.C. 3A15	SA134EA	15-gallon fiberglass wing tip fuel tanks. Reissued 2/6/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
P35, 35-B33; T.C. 3A15	SA178EA	Installation of Monitair angle of attach system, Model AA-2. REissued.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, 35-B33; T.C. 3A15	SA260EA	Installation of Monitair angle of attack and stall warning kit number 92-110. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, V35, V35A, V35B; T.C. 3A15	SA3203WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/24/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
S35, V35, V35A, V35B, 35-B33, 35-C33, 35-C33A, E33, E33A, F33, F33A, G33, 36, A36, A36TC; T.C. 3A15	SA180GL	Install Norton Company radar pod P/N 4133X. Amended 8/22/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
S35, V35, V35A, V35B, 35-B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36, A36TC; T.C. 3A15	SA328GL	Installation of Norton radome kit No. 4222X. Amended 6/3/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S35, V35; T.C. 3A15	SA352EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
S35, V35, V35A, V35B; T.C. 3A15	SA468SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and flight director indicator DH-841( ). Amended 11/14/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
S35, V35, V35B, 35-C33A, E33A, E33C, V35A, 36, A36, F33A, F33C; T.C. 3A15	SA785CE	Installation of Hartzell Propellers PHC-C3YF-1R/8468-6R, PHC-C3YF-1R/8468A-6R, PHC-C3YF-1RF/F8468A-6R and BHC-C2YF-1B/8468AR, BHC-C2YF-1BF/F8468AR. Amended 5/16/80.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
S35, V35, V35A, V35B; T.C. 3A15	SA1069SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director. Issued 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
S35, V35, V35A, V35B; T.C. 3A15	SA1417CE	Install elevator tail cone fairings. Issued 5/17/78.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
S35 S/N D7482 thru D796, V35, V35A, V35B; T.C. 3A15	SA1744SW	Mitchell automatic flight system AK409 cons. of Century I autopilot with optional omni tracker. Issued 10/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2556WE	Installation of Rajay turbosupercharged Continental TSIO-520-D engine. Amended 11/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
S35, V35, V35A, V35B, 35-C33A, E33C, F33A, F33C, 36, A36; T.C. 3A15	SA2935WE	Installation of Model DFP-5000 fuel monitor. Issued 10/25/74.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545
S35, V35, V35A, V35B; T.C. 3A15	SA3159SW-D	Automatic flight system AK409, consisting of Century I autopilot with optional omni tracker. Issued 10/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3172SW-D	Yaw damper Model YK631. Issued 12/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3272SW-D	Mitchell automatic flight system AK501 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/10/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3292SW-D	Mitchell command electric trim AK726. Issued 7/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, B; T.C. 3A15	SA3310SW-D	Installation of Mitchell automatic flight system AK804 consisting of Century 41 autopilot or AK804FD consisting of Century 41 autopilot flight director. Issued 11/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, B; T.C. 3A15	SA3324SW-D	Installation of Mitchell automatic flight system AK803 consisting of Century 21 autopilot. Issued 12/6/78.	SW	60000	Mitchell Industries,Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3327SW	Installation of Mitchell automatic flight system AK805 consisting of Century 21 autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3328SW	Installation of Mitchell automatic flight system AK806/FD consisting of Century 41/flight director autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S35, V35A, F33A, F33C, 36, A36; T.C. 3A15	SA3548WE	Installation of air/oil separator. Amended 4/28/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90025
S35, V35, V35A, V35B; T.C. 3A15	SA3668WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 7/13/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
V35; T.C. 3A15	SA503NW	Installation of Robertson STOL kit. Issued 9/7/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
V35; T.C. 3A15	SA707NW	Add RCA Primus weather radar. Issued 1/11/79.	NW	68500	Robertson Aircraft Corp. 839 West Perimeter Road Renton, WA 98055
V35, V35A; T.C. 3A15	SA925SW	Mitchell Automatic Flight System AK263 cons. of Century II autopilot with radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1185CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
V35, V35A, V35B; T.C. 3A15	SA1186CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
V35, V35A, V35B; T.C. 3A15	SA1500SW	Mitchell automatic flight system FD/AK282-382 cons. of flight director/autopilot with automatic command electric pitch trim. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1501SW	Mitchell automatic flight system AK383 cons. of Century III autopilot with optional automatic command electric trim, radio coupler, and glide slope coupler. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1722SW	Mitchell automatic flight system AK402, cons. of Century IIB autopilot with optional radio coupler. Issued 8/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3034SW-D	Mitchell automatic flight system AK503 or AK503FD cons. of Century IV autopilot or Century IV flight director autopilot with command/auto. electronic trim and annunciator panel. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3035SW-D	Mitchell automatic flight system AK501 cons. of Century III autopilot with optional command/auto. elec. pitch trim, radio, and glide slope coupler. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA4085SW	S-TEC System 60 (single axis) flight guidance system model ST-001. Issued 2/22/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Walters Industrial Complex Mineral Wells, TX 76067
V35A; T.C. 3A15	SA882SW	Mitchell automatic flight system AK260 consisting of Century III autopilot, optional radio coupler, automatic pitch trim, stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35A; T.C. 3A15	SA2030WE	Installation of Brittain B-VII, NAV-2B, B2C and BSA-4 Flight Control Systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, E33 and E33A; T.C. 3A15	SA1058WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, V35B, S35, F33A, A36; T.C. 3A15	SA3024WE	Installation of SDI Model CFS-1000-1001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
V35B (Utility Category); T.C. 3A15	SA2947WE	Installation of Collins AP-107 autopilot and FD-106 PV flight director. Reissued 4/22/75.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids Airport Cedar Rapis, IA 32406
V35B; T.C. 3A15	SA3215SW-D	Mitchell automatic flight system AK671 consisting of Century I autopilot with optional omni tracker. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3216SW-D	Mitchell automatic flight system AK672 consisting of Century IIB autopilot with optional radio coupler. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3217SW-D	Mitchell automatic flight system AK673 consisting of Century III autopilot with optional radio coupler and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3218SW-D	Mitchell automatic flight system AK674 consisting of Century IV autopilot or AK674FD consisting of Century IV flight director autopilot with remote annunciator. Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3219SW-D	Mitchell command electric trim system AK675. Issued 8/9/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3220SW-D	Mitchell yaw damper system YK676 Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
V35B; T.C. 3A15	SA4155SW	S-TEC system 60 (two axis) flight guidance system ST-017. Issued 7/18/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
V35B, A36, F33; T.C. 3A15	SA3683WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
35-33 Series; T.C. 3A15	SA1808WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33 Series; T.C. 3A15	SA1886WE	Installation of Brittain Industries NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3098SW-D	Mitchell automatic flight system AK306 cons. of Century I autopilot with optional omni tracker. Issued 1/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3107WE	Installation of exhaust silencer. Reissued 2/9/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA1036EA	Installation of vertical tail floodlights on upper surfaces of the horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
35-33, 35-A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A36TC; T.C. 3A15	SA1416CE	Install flap and aileron fairings and seals. Amended 3/24/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
35-A33; T.C. 3A15	SA270EA	Installation of a stability augmentation safety system (with or without camera system installed). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-A33; T.C. 3A15	SA1310CE	Chrome-plated brake disc installation. Issued 6/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35-B33, -C33A; T.C. 3A15	SA1289CE	Install King KFC-200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/21/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
35-C33, F33; T.C. 3A15	SA238GL	Installation of Continental IO-470-N engine and McCauley 2A36C23/84B-0 propeller. Amended 11/14/78.	GL	39517	Stewart Gross P.O. Box 634 Rochester, MN 55901
35-C33, 35-C33A; T.C. 3A15	SA394EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-C33; T.C. 3A15	SA896SW	Mitchell automatic flight system AK264 cons. of Century III autopilot with optional automatic aileron stabilizer, radio and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33, E33, F33; T.C. 3A15	SA1218SW	Automatic flight system AK306 cons. of Century I and optional tracking system. Issued 11/10/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33, E33, F33; T.C. 3A15	SA1365SW	Mitchell automatic flight system model AK347 cons. of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA1366SW	Mitchell automatic flight system model AK316, cons. of Century III autopilot with optional automatic pitch trim, radio coupler, glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3163SW-D	Install automatic flight system AK316 consisting of Century III autopilot with optional command automatic pitch trim system, radio coupler, and glide slope coupler. Issued 11/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3204WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 12/20/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3248SW-D	Mitchell automatic flight system AK716 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 10/3/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
E33, E33A, E33C, F33, F33A, F33C; T.C. 3A15	SA1550CE	Installation of elevator and rudder tail cone fairings. Issued 2/29/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 61 Johnson, KS 67855
E33, -A, -C; F33, -A, -C; T.C. 3A15	SA2057WE	Installation of Brittain Industries B-VII, NAV-2B, B2C and BSA4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
F33A; T.C. 3A15	SA1164CE	Installation of King KFC-200 two axis autopilot system with King KI-255 (or -256) flight command indicator or King KG-258 altitude horizon indicator with a KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
F33A; T.C. 3A15	SA3230SW-D	Mitchell automatic flight system AK660, consisting of Century IIB autopilot with optional radio coupler. Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F33A; T.C. 3A15	SA3232SW-D	Mitchell automatic flight system AK662, consisting of Century IV autopilot or AK662FD consisting of Century IV flight director with optional remote annunicator. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3229SW-D	Mitchell automatic flight system AK659 consisting of Century I autopilot with optional omni tracker. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, Tx 76067
F33A; T.C. 3A15	SA3231SW-D	Mitchell automatic flight system AK661, consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3233SW-D	Mitchell command electric trim AK663. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3234SW-D	Mitchell yaw damper system K664 Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3348SW	Installation of Mitchell automatic flight system AK821/FD consisting of Century 41/flight director autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3349SW	Installation of Mitchell automatic flight system AK820 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, G33, 36, A36; T.C. 3A15	SA480SO	Installation of Bendix FCS-810 automatic flight control system, including manual electrim trim and flight director indicator DH-841( ). Amended 10/4/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
F33A, S/N CE-316 & up; T.C. 3A15	SA1232SW	Mitchell automatic flight system AK315 cons. of Century III with optional automatic pitch trim, radio and glide slope coupler. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, E33A, 35-C33A, F33C; T.C. 3A15	SA1233SW	Mitchell automatic flight system AK317 cons. of Century I and optional tracking system. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1865SW	Mitchell automatic flight system AK448, Century IV autopilot and AK448FD, Century IV flight director with electronic command/automatic pitch trim. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1866SW	Mitchell automatic flight system AK452 cons. of Century III autopilot with optional electronic command/automatic pitch trim, radio coupler, and glide slope coupler. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA3087SW-D	Mitchell command electric trim AK563. Issued 12/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, 36A; T.C. 3A15	SA3193SW-D	Mitchell automatic flight system AK452 consisting of Century III autopilot with optional command automatic electronic pitch trim, radio, glide slope coupler. Issued 4/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G33; T.C. 3A15	SA571EA	Installation of Brittain Industries Models B7, NAV-2B, B2C and BSA4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
G33; T.C. 3A15	SA818CE	Install Hartzell propeller model BHC-I2YF-1BF/F8468AR with spinners A2295, or model PHC-L3YF-1RF/F8468A-6R with spinners A2295-1. Issued 1/14/72.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35/36 Series; T.C. 3A15	SA1711WE	Installation of Brittain Industries B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35/36 Series; T.C. 3A15	SA1712WE	Installation of Brittain Industries BSA-4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
35, 50 Series; T.C. 777, 3A15, 5A4	SA856WE	Glassfiber reinforced plastic wing tips.	WE	00450	ACKO P.O. Box 1431 Torrance, CA 90510
35, 50 Series; T.C. 777, 3A15, 5A4	SA998WE	Glass fiber reinforced plastic wing tips. Amended 6/13/69.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
35, 95 Series; T.C. 777, 3A15, 3A16	SA1-381	Installation of Fram Oil Filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
35, 95 Series; T.C. 777, 3A15, 3A16	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
36 Series; T.C. 3A15	SA961SW	Mitchell automatic flight system AK275 cons. of Century III autopilot with optional radio coupler, automatic pitch trim, aileron stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36 Series; T.C. 3A15	SA1916WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
36; T.C. 3A15	SA2068WE	Installation of Brittain Models B-VII, NAV-2B, B2C and BSA-4 flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
A36; T.C. 3A15	SA3206SW-D	Mitchell command electric trim model AK669. Issued 6/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1145CE	Installation of King Model KFC-200, 2 axis (3 optional) or stand alone yaw damper for Beech Model A36 S/N E572 and later autopilot system with a King KI-255 (KI-256 optional) flight command indicator with the KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
36, A36; T.C. 3A15	SA1231SW	Mitchell automatic flight system model AK311, cons. of Century II autopilot with optional radio coupler. Issued 12/8/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1360SW	Mitchell automatic flight system Model AK346 cons. of Century III autopilot with optional pitch trim, radio coupler, and glide slope coupler. Issued 8/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1634SW	Mitchell AK423 cons. of 1C707 omni/localizer converter. Issued 3/27/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1635SW	Mitchell AK417/FD cons. of flight director/autopilot with command electric trim. Issued 3/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3118SW-D	Automatic flight system AK448, Century IV autopilot or AK448FD, Century IV autopilot flight director with optional remote annuciator. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3119SW-D	Automatic flight system AK452 cons. of Century III autopilot with optional command/automatic electronic elevator pitch trim, radio and glide slope couplers. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
36, A36; T.C. 3A15	SA3244WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 8/11/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
36, A36, A36TC; T.C. 3A15	SA1448CE	Installation of elevator tail cone fairing. Amended 3/24/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
A36, Serial No. E185 and up; T.C. 3A15	SA84RM	Installation of freon type air conditioning system. Amended 3/21/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
A36; T.C. 3A15	SA283GL	Installation of a Continental IO-520-B, -BA engine modified in in accordance with STC SA282GL and a Symbolic Displays fuel flow indicating system, Model CFS-1000. Issued 11/14/78.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport Rockford, IL 61109
A36; T.C. 3A15	SA1093CE	Installation of AP-107 (2 axis) autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1095CE	Installation of AP-106 autopilot system and interface with Collins 329A-4V indicator. Amended July 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1096CE	Installation of yaw damper system. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1097CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1544CE	Installation of microwave landing system. Issued 1/22/80.	SW	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
A36; T.C. 3A15	SA3203SW-D	Mitchell yaw damper model YK670 Issued 5/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3204SW-D	Mitchell automatic flight system AK668 consisting of Century IV autopilot or AK668FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 5/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3205SW-D	Automatic flight system AK667 consisting of Century III autopilot with optional radio coupler and Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3207SW-D	Mitchell automatic flight system consisting of Century I autopilot with optional omni tracker. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3208SW-D	Mitchell automatic flight system AK666 consisting of Century IIB autopilot with optional radio coupler. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3340SC	Mitchell automatic flight system AK810 consisting of Century 41 flight director autopilot. Issued 7/25/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36; T.C. 3A15	SA4106WE	Modification of the rudder and brake systems to provide hand controls in addition to the conventional systems. Issued 3/25/80.	WE	05225	Aircraft Inspection & Maintenance, Inc. 2680 East Wardlaw Road Long Beach, CA 90807
A36, A36TC; T.C. 3A15	SA1106SC	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and option yaw damper and flight director. Issued 10/11/79.	SC	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A36, A36TC; T.C. 3A15	SA1496CE	Installation of King KFC 200 automatic flight control system. Amended 7/1/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
A36, A36TC; T.C. 3A15	SA1527CE-D	Installation of King KAS 297 altitude selector option. Issued 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
A36TC; T.C. 3A15	SA3329SW-D	Mitchell automatic flight system AK754 consisting of Century IV autopilot or Model AK754FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 1/2/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36TC; T.C. 3A15	SA3330SW-D	Mitchell automatic flight system AK753, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/2/79.	SW	60000	Mitchel Industries, Inc. P.O. Box 610 Mineral Wells, TX 75056
A36TC; T.C. 3A15	SA4114WE	Installation of Silver Instruments Fueltron IG or IP digital fuel flow and totalizer system. Issued 2/26/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
A36TC; T.C. 3A15	SA4140WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 4/10/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
45 Series; T.C. 5A3	SA366WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
45 Series; T.C. 5A3	SA425SW	Nose landing gear door removal.	SW	22700	Civil Air Patrol Corporation National Headquarters Ellington AFB, TX 77030
A-45 (T-34A, B-45); T.C. 5A3	SA876CE	Remove Continental O-470-13 or O-470-13A engine and propeller. Install Continental IO-470-N engine and Hartzell BHC-L2YF-FC846AR propeller. Issued December 1972.	CE	15250	Beech Aircraft Corporation 9709 East Central Wichita, KS 67206
A-45 (T-34A, B-45); T.C. 5A3	SA2211SW	Mitchell Century I Model AK409 autopilot with omni tracker. Issued 7/17/75.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA1864SW	Continental IC-520-B engine and McCauley 3A32C76/82NB-2 propeller. Issued 4/11/74.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA3191SW-D	Mitchell automatic flight system AK649 consisting of Century I autopilot with optional omni tracking system. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A45; T.C. 5A3	SA3192SW-D	Automatic flight system AK651 consisting of Century IIB autopilot with optional radio coupler. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D45; T.C. 5A3	SA183GL	Modification of basic aircraft for Restricted Category Airworthiness Certification by removing rudder-aileron bungee interconnect system, elevator down spring system and tail cone fairing. Issued 6/21/77.	GL	61302	Michigan Dept. of Natural Resource Stevens T. Mason Bldg. Lansing, MI 48926
50 Series; T.C. 5A4	SA1-262	Bendix Pioneer 9100-17-C1 fuel flow meter system.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series; T.C. 5A4	SA1-291	Radio shelves in nose baggage shelves.	EA	15210	Beckett Aviation Corporation Allegheny County Airport Dravosburg, PA 15034
50 Series; T.C. 5A4	SA1-357	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series; T.C. 5A4	SA1-443	2002X-R radome assembly.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50 Series; T.C. 5A4	SA1-503	Electrothermal propeller deicing system. (Applicable to aircraft with two 50-amp. generators or greater.)	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series; T.C. 5A4	SA3-208	Acron B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA3-703	Accumulator for unfeathering Hartzell HC-83XF, HC-93Z20 or HC-B3Z20 propellers.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA4-51	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-221	Autopilot I-2.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-382	Radio rack.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
50 Series; T.C. 5A4	SA4-439	Fiberglass reinforced plastic wing tips.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
50 SEries; T.C. 5A4	SA4-462	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-549	Federal F-400 autopilot.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
50 Series; T.C. 5A4	SA4-758	Aerofilter 30690B full flow lube oil filter with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
50 Series; T.C. 5A4	SA4-807	Automatic rudder control **Model B.**	GI	49858	Lear, Inc. 3714 Jefferson Avenue, S.E. Grand Rapids, MI 49501
50 Series; T.C. 5A4	SA4-808	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-1417	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA3CE	Governor 210385. (Not eligible with accumulator unfeathering system.)	GI	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA5CE	Propeller governors incorporating unfeathering accumulator shutoff valves. (Eligible only on aircraft equipped with Beech unfeathering system.)	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA24SW	Cabin seats. (Seat tracks installation per STC SA2-1068 required.)	SW	83650	Vicars Custom Aircraft Interiors 3709 N. Main Fort Worth, TX 76101
50 Series; T.C. 5A4	SA25CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA31SW	Automatic pilot AK104.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA41CE	Governor 210159.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA75SW	Landing gear doors. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50 Series; T.C. 5A4	SA76SW	Lycoming IGSO-540-B1A engines with associated powerplant changes, and landing gear doors; increase gross weight to 7,300 lbs. takeoff and 7,000 lbs. landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, Tx 78216
50 Series; T.C. 5A4	SA81SW	Automatic pilot AK119.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA158EA	Autopilot T-3 and altitude hold AH-1 as an accessory item.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series; T.C. 5A4	SA166CE	Twin-engine electronic synchronizer and unfeathering system.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA167CE	Electronic synchronizer kit.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA198SW	Three-place couch.	SW	85128	Westernair of Albuquerque, Inc. Route 6, Box 88 Albuquerque, NM 87101
50 Series; T.C. 5A4	SA207SW	Dual control. (Pilot's and copilot's seat installations per STC SA2-1068 required.) Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA213CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA242SW	Lycoming GC-480-G2D6 engines and increase in gross weight to 6,300 pounds. Reissued February 1973.	GL	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA323EA	7541K nose cap weather radome.	NE	53750	McMillan Radiation Labs, Inc. Brownville Avenue Ipswich, MA 01938
50 Series; T.C. 5A4	SA348SW	Radar nose. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA360SW	GO-480-G2D6 or -G2F6 engines and increase in weight to 6,000 pounds. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA370SW	Seven place seating capacity.	SW	80625	United Airmotive 1105 DeRidder Fort Worth, TX 76106
50 Series; T.C. 5A4	SA392WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA430SW	Pilot and copilot cockpit seats.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
50 Series; T.C. 5A4	SA405WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA433SW	Cabin door and stair.	SW	27242	Cross Roads Aviation, Inc. Addison Airport Addison, TX 75001
50 Series; T.C. 5A4	SA514SW	Six place seat and/or hat shelf.	SW	36125	Flying V Interiors Meacham Field Fort Worth, TX 76106
50 Series; T.C. 5A4	SA517SW	Goodrich wheel and brake. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA587SW	Lycoming IC-720-A1A engines, increase gross weight 7,600 pounds, 7,240 pounds landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
50 Series; T.C. 5A4	SA655SW	Lycoming IGSO-480-A1A6 engine; wing, vertical tail, landing gear modified, control system increased gross weight to 7,300 pounds takeoff, and 7,000 pounds landing.	SW	27242	Cross Roads Aviation, Inc. P.O. Box 60464 AMF Houston, TX 77060
50 Series; T.C. 5A4	SA1013WE	Advanced Army Aircraft Instrumentation System (AAAIS) and associated aircraft modifications.	WE	30400	Douglas Aircraft Company, Inc. 3855 Lakewood Boulevard Long Beach, CA 90801
50 Series; T.C. 5A4	SA1324WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA1385WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA1-565	Installation of radome kit No. 2002X. Amended 2/24/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA99CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights Model 1 or 2. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGAw Avenue Irvine, CA 92705
50, B50, C50, D50, D50A, D50B, D50C, D50E-5990, D50E, E50E, F50, G50, H50, J50; T.C. 5A4	SA276GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 1/17/79.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA383CE	Installation of Hoskins Twi. III supplementary high intensity lighting system. Reissued 5/4/70.	WE	77250*	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
50, B50, C50, D50, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA390GL	Install Cleveland conversion kit, P/K 199-88. Issued 6/18/80.	GL	62500	Parker Hannifin Corporation Aircraft Wheel & Brake Division 1160 Center Road Avon, OH 44011
50, B50 thru J50, D50A, B, C, D, E; 65, 65-80, 65-A8800, 65-B80 all; T.C. 5A4, 3A20	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 28C Stoughton, WI 53589
50, B50, C50, D50,D50A, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA1644WE	Installation of a Torginol Special Product Co. KarBar.	RM	25250	Combs Aircraft, Inc. Stapleton International Airport Denver, CO 80207
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA2631WE	Installation of Bellon Concrete, Inc. single piece windshield or alternate single piece sloped windshield. Amended 3/20/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4550 Jettridge Drive Atlanta, GA 30327
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA2872WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
B50, C50, D50; T.C. 5A4	SA2413WE	Modification of fuel vent outlet. Issued 9/3/71.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
C50; T.C. 5A4	SA3062SW-D	Mitchell AK370 cons. of Century III autopilot with command/automatic electronic pitch trim system, optional radio coupler, and glide slope coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C50; T.C. 5A4	SA3063SW-D	Mitchell automatic flight system AK542 cons. of Century IIB autopilot with optional radio coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, D50C, E50, F50, G50, H50; T.C. 5A4	SA1-453	Installation of Tactair T-3 automatic pilot and optional installation of Tactain AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
D50, D50A, B, C, E; T.C. 5A4	SA3138SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3139SW-D	Mitchell automatic flight system AK613, consisting of Century IIB autopilot with optional radio coupler. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3140SW-D	Mitchell automatic flight system AK606, consisting of Century I autopilot with optional omni tracker. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50 - modified - Excaliber STC SA587SW; 56TC, A56TC, 58, 58A, 58P, 58PA, 58TC, 58TCA, 60, A60, B60; 65, A65, 65-80, -A80, -A80-8800, -B80, -88, -70 modified - Excalibur STC SA444SW; 95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A (95-55, -A55, -B55 modified - Cclemill STC SA432SO; T.C. 5A4, 3A16, A12CE, A23CE, 3A20, 3A16	SA20GL	Installation of Woodward Type III electronic propeller synchronizer or synchrophaser system. Amended 9/25/78.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
D50C, E; T.C. 5A3	SA1334SW	Mitchell automatic flight system AK337, cons. of Century II autopilot with optional radio coupler. Issued 7/1/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA31WE	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
D50E; T.C. 5A4	SA33WE	Autopilot M-4.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
D50E; T.C. 5A4	SA391WE	Installation of Brittain Model B2D Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D50E; T.C. 5A4	SA837SW	Mitchell AK255 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA974CE	Installation of KNR 665 digital area navigation system. Amended May 1974.	CE	48250	King Radio Corporation Box 106 Olathe, KS 66061
E50, F50, G50, H50, J50; 80, A80, 65; T.C. 5A4, 3A20	SA1686WE	Installation of Vibration Isolation Products engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
50, 65 Series; T.C. 5A4, 3A20	SA15EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50, 65 Series; T.C. 5A4, 3A20	SA476EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
55, A55; B55, C55, D55, 56TC; 65-B80, A65-8200, 65-90, A90; 95, B95, B95A, D-95A, E95; T.C. 3A16, 3A20	SA1874WE	Installation of Brittain up-command signal adapter kit on certain airplanes equipped with Brittain models B-4A, B-4AF, B-5 and B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA681CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B55, C55; 95 Series; T.C. 3A16	SA1591WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1548WE	Installation of a Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1934WE	Installation of an approach speed control system. Reissued 12/4/69.	EA	69500	Safe Flight Instrument Corp. Box 550 White Plains, NY 10602
D55, E55, E55A, 56TC, A56TC, 58, 58A, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 58P, 58PA, 58TC; TC 3A16	SA453SO	Installation of Bendix Model FCS 810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 10/19/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
D-55, D55A, E55, E55A, 58, 58A, 56TC, A56TC, 95; T.C. 3A16	SA2048WE	Installation of Brittain Industries Model B-VII or NAV-2B or B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55, D55A, E55, E55A, 56TC, 58, 58A, 95, B95, B95A, D95A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A; T.C. 3A16	SA2871WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
E55; T.C. 3A16	SA126GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
E55; T.C. 3A16	SA896SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 4/22/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
E55; T.C. 3A16	SA3068WE	Installation of fuel flow instruments. Issued 8/8/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1126CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE982 and up); T.C. 3A16	SA1127CE	Installation of Collins AP-107 (2 axis) autopilot systems. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1128CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55, 58; T.C. 3A16	SA1008CE	Installation of an electric motor driven freon vapor cycle air conditioning system. Amended 10/9/74.	CE	02950	Aero Space Controls 1050 N. Mosley Wichita, KS 67214
56TC; T.C. 3A16	SA383SO	Installation of Bendix M-4C autopilot flight control system. Amended 7/14/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33309
56TC; T.C. 3A16	SA632CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114
56TC; T.C. 3A16	SA713CE	Conversion of wing tips to integral fuel tanks.	CE	16292	Frank R. Berry and William T. McKay Route 1, Box 204A Augusta, KS 67010
56TC; T.C. 3A16	SA1770WE	Installation of Brittain Industries Models B-5 or NAV-2B or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
56TC, A56TC; T.C. 3A16	SA1041CE	Replace existing nickel-cadmium battery with lead-acid battery. Issued January 1975.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
56 TC; 95 Series; T.C. 3A15, 3A16	SA1585WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
58 Series; T.C. 3A16	SA860EA	Installation of Aircraft Radio Corp. AF-530A automatic pilot system and electric operated elevator trim system. Amended 1/18/71.	EA	05950	Aircraft Radio Corporation Rockaway Valley Road Boonton, NJ 07005
58 Series; T.C. 3A16	SA1174SW	Mitchell automatic flight system FD/AF282-303 cons. of flight director/autopilot, automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1175SW	Auto flight system AK303 cons. of Century III, autopilot, with optional auto pitch trim, radio, and glide slope couplers. Issued 7/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1192SW	LN2 air conditioner system. Issued 9/22/70.	SW	83100	Ves-Kol Inc. 2805 National Drive Garland, TX 75040
58 Series; T.C. 3A16	SA1199SW	Mitchell automatic flight system 305 cons. of Century II autopilot with optional stabilizer and radio coupler. Issued 10/2/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA3119WE	Installation of Pathfinder autopilot systems. Issued 12/16/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
58, 58A; T.C. 3A16	SA94RM	Installation of freon type air conditioning system. Issued 3/24/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
58, 58A; T.C. 3A16	SA1045CE	Installation of Collins Radio Co. AP-107 autopilot system (2 axis). Amended February 1975.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1106CE-D	Installation of Collins Radio Group AP-106 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1107CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1108CE-D	Installation of Collins Radio Group AP-107 axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1687SW	Mitchell automatic flight system Model YK428 cons. of yaw damper. Issued 6/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1786SW	Mitchell Automatic Flight System AK451 cons. of Century III Autopilot with Electronic Pitch Trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1787SW	Mitchell Automatic Flight System AK447 cons. of Century IV Autopilot or AK447FD cons. of Century IV/Flight Director with Electronic Command/Automatic Pitch trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3131SW-D	Mitchell automatic flight system AK447, Century IV autopilot or AK447FD Century IV flight director autopilot with remote annuciator. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3132SW-D	Mitchell automatic flight system AK451, consisting of Century III autopilot with optional command automatic electric pitch trim, radio and glide slope couplers. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
58, 58A; T.C. 3A16	SA3341SW	Mitchell yaw damper systems, YK781. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3342SW	Mitchell automatic flight system AK816/FD consisting of Century 41/flight director autopilot. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3350SW	Installation of Mitchell automatic flight system AK815 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A, 58P, 58PA, 58TC, 58TCA, 65-80, -A80, -B80, -88, 95-C55, -C55A, D55, D55A, E55, E55A; T.C. A23, 3A20, 3A16	SA300CE	Installation of Woodward propeller governor on single and twin engine airplanes. Amended 9/18/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, II 61101
58, 58A, TH-1 and up; T.C. 3A16	SA863CE	Installation of Airborne/Goodyear pneumatic iceguard deicing system. Issued August 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
58, 58A, 95-B55, -B55A; T.C. 3A16	SA935SO	Installation of a Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Amended 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
58, 58A, 95-B55, -B55A; T.C. 3A16	SA936SO	Installation of Bendix NP-2041A area navigation computer programmer. Amended 4/10/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
58P; T.C. A23CE	SA113GL	Installation of radome kit 4109X. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA978SO	Installation of NP-2041A area navigation computer programmer. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA979SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
58P, 58PA, 58TC, 58 TCA; T.C. A23CE	SA1123CE	Install AP-106 autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1124CE	Install AP-107 (2 axis) autopilot and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1125CE	Install AP-107 (3 axis) autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1150CE	Installation of King Model KFC-200, 2-axis and KC-291 yaw damper FCS. Amended 6/2/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
58P, 58PA, 58TC, 58TCA: T.C. A23CE	SA1524CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3038SW-D	Mitchell automatic flight system AK449 or AK449FD cons. of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim and optional remote annuciator panel. Issued 1/17/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3039SW-D	Automatic flight system YK445 yaw damper system. Issued 1/17/75.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3040SW-D	Automatic flight system AK453 consisting of Century III autopilot optional command/automatic elecelectronic pitch trim system, radio and glide slope couplers. Issued 2/5/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3311SW-D	Mitchell automatic flight system AK453 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/22/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3338SW-D	Mitchell automatic flight system system AK813 consisting of Century 41 autopilot or AK813FD consisting 41 flight director autopilot with optional remote annunciator. Issued 4/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3344SW	Mitchell yaw damper system YK781. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3499WE	Installation of tail flood lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
58P, 58TC; T.C. A23CE	SA178GL	Install Cleveland conversion kit, P/N 199-73. Issued 5/23/77.	GL	23260	Cleveland Wheels and Brakes VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011
58P, 58TC; T.C. A23CE	SA3769WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
58P, 58TC, 58TCA; T.C. A23CE	SA4050WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Reissued 3/25/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
58TC; T.C. A23CE	SA124GL	Install Norton Company radome, P/N 4083X. Amended 2/21/79.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
60 Series; T.C. A12CE	SA1006SW	Mitchell Automatic Flight System AK291, cons. of Century III autopilot with optional pitch trim servo, radio and glide slope couplers.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60; T.C. A12CE	SA659SO	Installation of Bendix M-4C automatic flight control system, including manual electric trim, and/or installation of Bendix YD-4 yaw damper. Amended 11/10/72.	SO	15475	Bendix Avionics P.O. Box 9414 Ft. Lauderdale, FL 33310
60, A60; T.C. A12CE	SA945CE	Replacement of existing nickel-cadmium battery with lead-acid battery, Teledyne PS12-24. Amended October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133
60, A60; T.C. A12CE	SA1587SW	Mitchell automatic flight system YK380 consisting of yaw damper. Issued March 1973.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60; T.C. A12CE	SA1704SW	Mitchell automatic flight system AK429, cons. of Century IV autopilot with trim or AK429/FD cons. of Century IV autopilot/flight director with trim. Issued 7/20/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA154GL	Installation of Norton radome kit, No. 4132X. Issued 2/16/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
60, A60, B60; T.C. A12CE	SA179GL	Install Celveland conversion kit, P/N 199-73. Issued 5/23/77.	GL	23260	Cleveland Wheels and Brakes VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
60, A60, B60; T.C. A12CE	SA539SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator and/or YD-4 yaw damper. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
60, A60, B60; T.C. A12CE	SA1023CE	Installation of Collins Radio Co. AP-106 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1024CE	Installation of AP-107 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1025CE	Installation of yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A2CE	SA1741SW	Mitchell automatic flight system AK458 cons. of Century autopilot with optional radio coupler automatic/command pitch trim, glide slope coupler. Issued 10/12/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3151SW-D	Mitchell automatic flight system AK429 consisting of Century IV autopilot or AK429/FD consisting of Century IV flight director with optional remote annuciator. Issued 7/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A2CE	SA3162WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 3/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
60, A60, B60; T.C. A12CE	SA3293SW-D	Yaw damper system YK380. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3367SW-D	Mitchell automatic flight system AK870 consisting of Century 41 autopilot or AK870FD consisting of Century 41FD autopilot. Issued 5/6/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3368SW-D	Mitchell automatic flight system YK871 consisting of yaw damper system. Issued 5/6/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3605WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel indicating system. Amended 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
60, A60, B60; T.C. A12CE	SA3905WE	Installation of SDI Model CFS-200, -2001, or FT-200 fuel flow indicating system. Issued 4/13/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
60, 65-A80, B80, 65-88, 70; T.C. A12CE, 3A20	SA889EA	Installation of Grimes three light strobe kit P/N 34-0116-1 and -2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
60, A60, B90, C90, E90, 65-90, -A90, 100, A100; T.C. A12CE, 3A20, A14CE	SA2638WE	Installation of CCC BWS 50-08 Nicad battery overheat warning system. Amended 9/18/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
A60; T.C. A12CE	SA85RM	Installation of Teledyne Avionics angle of attack indicating system. Issued 11/2/76.	RM	14127	Avionics Engineering of Denver, Inc. 8895 Montview Boulevard, Hangar B Denver, CO 80220
A60; T.C. A12CE	SA1029CE	Installation of AP-106 and AP-107 automatic flight control systems and yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
B60; T.C. A12CE	SA570SO	Installation of Bendix M-4D automatic flight control system, including optional manual electric trim and optional flight director indicator. Issued 12/6/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B60; T.C. A12CE	SA1470CE	Installation of King KFC 250 flight control system (3 axis) using 3-inch or 4-inch indicators. Issued 2/5/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
65 Series; T.C. 3A20	SA1-643	Radar antenna mounts: 296-01 for 12" Collins WP-103 antenna; 296-03 12" RCA AVQ-55 antenna and 296-02 for 12" RCA AVQ-50 antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series; T.C. 3A20	SA3-516	Autopilot I-2C with or without 1350E approach coupler and 2203D2 altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA4CE	Propeller governors incorporating unfeathering accumulator shutoff valves.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
65 Series; T.C. 3A20	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
65 Series; T.C. 3A20	SA46WE	Full flow lube oil filter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
65 Series; T.C. 3A20	SA92CE	High intensity wing tip lights Model A, tail light Model C, with or without high intensity fuselage lights Model 1 or 2.	GL	42625	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
65 Series; T.C. 3A20	SA139SW	Buffet. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
65 Series; T.C. 3A20	SA161CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
65 Series; T.C. 3A20	SA186EA	Throttle stop device.	EA	87118	Stephen J. Wisey, Jr. 8 Steamboat Road Great Neck, NY 11022
65 Series; T.C. 3A20	SA188CE	Twin-engine synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
65 Series; T.C. 3A20	SA201EA	Sperry SP 3 elevator trim drive servo and trim tab bracket.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
65 Series; T.C. 3A20	SA210SO	Radar system AVQ55.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
65 Series; T.C. 3A20	SA218SW	Automatic pilot AK105.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA255CE	Oil tank heater blanket kit 65-42.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67206
65 Series; T.C. 3A20	SA269SW	Brushless generators, voltage regulators and control panels.	EA	37376	General Electric Company Specialty Controls Department Waynesboro, VA 22980
65 Series; T.C. 3A20	SA277EA	Installation of Chamberlain 2090K-B radome kit for Bendix 100 or RDR-110 radar systems with transmitter/ receiver unit and 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
65 Series; T.C. 3A20	SA280EA	2011K-B Series radome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series; T.C. 3A20	SA296CE	M4B or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA307CE	GUARD system (gear up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65 Series; T.C. 3A20	SA336EA	PB-60 autopilot.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
65 Series; T.C. 3A20	SA393EA	Electronic voltage alarm.	EA	53500	McKinley Engineering Company P.O. Box 275 Palisades Park, NJ 07650
65 Series; T.C. 3A20	SA411CE	M4E or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA444SW	Lycoming IO-720A1A engines and increase in takeoff and loading weight. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65 Series; T.C. 3A20	SA470SW	Automatic pilot AK122 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA471SW	Automatic trim system AK149.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA505CE	Install entrance door.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65 Series; T.C. 3A20	SA528SW	Lear 164 electro-mechanical rotary actuator.	SW	42131	H & H Enterprises P.O. Box 75135 Oklahoma Ctiy, OK 73125
65 Series; T.C. 3A20	SA651SW	AK206 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA695SW	Engine induction system air filter removed.	SW	71800	Sinclair Oil & Gas Company Aviation Department 3505 N. Sheridan Road Tulsa, OK 74101
65 Series; T.C. 3A20	SA704CE	Installation of BUTLER VAC and ADD navigation system. Amended April 1974.	CE	19000	Butler National Corporation 8246 Nieman Road Lenexa, KS 66214
65 Series; T.C. 3A20	SA722SW	AP-103F/FD-108 autopilot flight director system and related electronics.	SW	24252	Collins Radio Company P.O. Box 98 Addison Airport Addison, TX 75001
65 Series; T.C. 3A20	SA767SW	Mitchell Model AK 239 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA1004WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
65 Series; T.C. 3A20	SA1022WE	B-4 flight control system (PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1453WE	Installation of a Brittain Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1511WE	Pacific Airmotive Corp. rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
65 Series; T.C. 3A20	SA1528WE	Installation of Brittain B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1556WE	Installation of Brittain Industries B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65 Series; T.C. 3A20	SA1714WE	Removal of emergency exit to permit aircraft to engage in special purpose operations, as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
65 Series; T.C. 3A20	SA1794WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA2069WE	Installation of Brittain B-VII Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65, A65, A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 70; T.C. 3A20	SA22GL	Installation of Hartzell synchrophaser. Reissued 8/27/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
65, A65, 65-80, 65-A80, 65-B80; T.C. 3A20	SA43CE	Installation of Bendix M-4B and M-4C flight control system. Amended 3/8/67.	EA	15480	The Bendix Corporation Avionics Products Bendix Radio Division Baltimore, MD 21204
65, 65-80, 65-A80, 65-90; T.C. 3A20	SA318EA	Installation of Monitair angle of attach and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
65-L23F, 65-80, 65-A80, 65-B80, -90, -A90; T.C. 3A20	SA394CE	Install Hoskins Twi. Mk III supplemental high intensity lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
65, 65-80; T.C. 3A20	SA1-642	2011X Series radome. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
65, 65-80; T.C. 3A20	SA506WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTL Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
65, 65-80; T.C. 3A20	SA518SW	Goodrich wheel and brake. Reissued Feburary 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65, A65, 65-80, A65-8200, 65-A80, -A80-8800, -B80, -88, -70; T.C. 3A20	SA277GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 12/21/78.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
65, A65, -80, -A80, -A80-8800, A65-8200, -B80, 70; T.C. 3A20	SA1244SW	Mitchell automatic flight system FD/AP282-313 cons. of flight/director/autopilot and automatic pitch trim. Issued 1/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, A65, A65-8200, 65-80, -A80, -A80-8800, -B80, -88, -90, -A90, 70, B90, C90, E90; T.C. 3A20	SA1279CE	Installation of Avcon Ind. TSC-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
65, A65, 65-80; T.C. 3A20	SA1328SW	Replacement of existing alternators with 100 ampere Prestolite ALV-8042's. Reissued 10/20/72.	SW	61500	Nayak Aviation Corporation 206 E. Terminal Avenue San Antonio, TX 78216
65, A65, A65-8200, 65-80, -A80, -A80-880, -B80, -88, -90, -A90, -A90-1, -A90-2, -A90-3, -A90-4, 70, B90, C90, E90; T.C. 3A20	SA1583CE	Install wing front spar reinforcement kit. Issued 4/11/80.	WE	13177	Aviadesign, Inc. Suite 101, Bank of America, Levy Building 5808 E. Telephone Road Ventura, CA 93003
65, A65, 65-80, 65-A80; T.C. 3A20	SA2349SW	3-place divan. Issued 8/13/76.	SW	36550	Foster-Edwards Aircraft Co., Inc. Box 574 Addison, TX 75001
65, A65, A65-8200, 70; T.C. 3A20	SA2365WE	Installation of Hartzell HC-3X20-2/9333C or HC-A3X20-2/9333C propellers. Reissued 7/14/71.	SW	37080	Bernard A. Gallaher 1400 Southwest Tower Houston, TX 77002

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65, A65, A65-8200, 65-80, -A80, -A80-8800, -B80, -88, 70, 65-90, -A90, A90-1, -2, -3, -4, B90, C90 (S/N LJ502 thru 526); T.C. 3A20	SA3080WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
65, A65, 65-80, -A80, -B80, -A80-8800; T.C. 3A20	SA3114SW-D	Automatic flight system AK548, cons. of Century III autopilot with optional radio and glide slope couplers. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, 65-80, -A80, -B80, -A80-8800, A65-8200, 70; T.C. 3A20	SA3115SW-D	Mitchell AK585, cons. of Century IV autopilot or AK585FD Century IV flight director autopilot. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65-80; T.C. 3A20	SA185CE	Installation of AC Spark Plug Division oil filter assembly type OF-103-A, P/N 6435565; or type OF-105-A, P/N 25010400. Amended 6/5/80.	GL	00750	AC Spark Plug Division of General Motors Flint, MI 48556
65-80; T.C. 3A20	SA1009EA	Installation of Edo area navigation system Model TCE-71A. Reissued 12/19/78.	EA	32625	EDO-AIRE Div. of Edo Corporation 216 Passaic Avenue Fairfield, NJ 07006
65-80, -A80, -B80, -88, -90, -A90; T.C. 3A20	SA381EA	Installation of radome kit No. 2090X. Amended 12/15/76.	GI	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
65-80, -A80, -B80, -88, -90, -A90, B90, C90, E90, 100, A100, A100A, A100C, B100; T.C. 3A20, A14CE	SA37GI	Installation of Norton radome kit No. 2090XS. Amended 8/24/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
65-A80, -B80, -88, -90, -A90, -B90; T.C. 3A20	SA45GL	Install AMF inverter MGH 549-1. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
65-80, A-80, B-80; T.C. 3A20	SA2283WE	Installation of oil lever indicator system. Issued 11/30/70.	WE	25600	Communications Components Corp. 1524 West 15th Street Long Beach, CA 90813
65-B80 Queen Air; T.C. 3A20	SA940SO	Removal of existing fuel flowmeter and associated components and installation of fuel flowmeter. Issued 6/24/77.	SO	02850	Aerosonic Corporation P.O. Box 4627 Clearwater, FL 33518
A65, 65-B80 & 70; T.C. 3A20	SA660CE	Installation of Bendix M4-C Flight Control System.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33310
65-90; T.C. 3A20	SA133GL	Install B.F. Goodrich thermally efficient propeller de-icers. Amended 9/15/76.	GL	38500	B.F. Goodrich 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA826SW	Elevator electric trim system.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 - Adams Field Little Rock, AR 72203
65-90; T.C. 3A20	SA897EA	Installation of B.F. Goodrich electrothermal propeller deicing system. Issued 2/7/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Company 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA1108SO	Installation of Pratt & Whitney engine model PT6A-20 replacing model PT6A-6. Issued 10/15/79.	SO	14213	B. R. Power Division Aztec Leasing, Inc. 20 Piney Mountain Road Greenville, SC 29607
65-90; T.C. 3A20	SA2740SW	Installation of P&W PT6A-135 engines and bleed air conditioning and pressurization system. Issued 3/24/78.	SW	77111	E.J. Swearingen P.O. Box 4640 Waco, TX 76705
65-90, -A90; T.C. 3A20	SA761SW	Mitchell AK238 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65-90, -A90; T.C. 3A20	SA822SC	Installation of P & W PT6A-28 engines. Amended 3/27/78.	SO	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
65-90, 65-A90, 65-B90; T.C. 3A20	SA526SO	Installation of the Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-90, -A90, B90, C90, E90; T.C. 3A20	SA546SO	Instllation of Bendix M-4D automatic flight control system including optional manual electric trim system and optional flight director system. Issued April 1980.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Launderdale, FL 33310
65-90, -A90, -B90; T.C. 3A20	SA1177SW	Revised main landing gear doors.	SW	61500	Nayak Aviation Corporation 206 E. Terminal Drive San Antonio, TX 78216
65-90, -A90, B90, C90; T.C. 3A20	SA2693WE	Installation of inertial air separator scoops. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA810CE	Battery temperature sensing and over-temperature warning systems. Amended October 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA879SC	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA951CE	Installation of lead-acid battery. Issued October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, 99, A100; T.C. 3A20	SA1017SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA1194CE	Install Teledyne/Gill lead-acid battery, BB638/T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	78052	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, H90; T.C. 3A20	SA1451CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, 65-A90, B90 C90, E90, H90; T.C. 3A20	SA1452CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, A90, B90, C90, E90, 99, 99A, A99A, 100, A100; T.C. 3A20	SA2284SW	Ignition current monitor system. Issued 1/19/76.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
65-90, -90A, -A90-1, -2, -3, -4, B90, C90, E90, 99, 99A, A99, A99A, B99, 200, A200, 200T; T.C. 3A20, A14CE, A24CE	SA566NW	Installation of parachute deployment system. Issued 3/27/78.	NW	80915	U.S. Forest Service 3905 Vista Avenue Boise, ID 83705
65-90, -A90, -A90-1, -A90-2, -A90-3, B-90, C-90; 99, 99A; T.C. 3A20, A14CE	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457
65-90, -A90, -A90-1, -A90-2, -A90-3, -A90-4, B90, C90, E90; T.C. 3A20	SA2907WE	Installation of fuel tank boost pump. Amended 11/18/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
65-90, -A90, B90, C90; T.C. 3A20	SA3266SW-D	Mitchell automatic flight system AK725 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/24/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
65-A90; T.C. 3A20	SA691CE	Installation of fuel drain manifold tank.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
65-A90; T.C. 3A20	SA729SW	Installation of Collins AP-103F/FD-108 autopilot/flight director system and related electronics. Amended 2/14/68.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-A90; T.C. 3A20	SA845CE	Installation of wing flap override switch and duplicate flap down limit switch. Issued May 1972.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65-A90; T.C. 3A20	SA1813SW	Battery temperature sensing and indicating system. Issued 3/8/74.	SW	02300	Aero Instrument Supply, Inc. 7515 Lemon Avenue Box 7481 Dallas, TX 75209
65-A90, -A90-1, B90; T.C. 3A20	SA418SC	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-A90, B90; T.C. 3A20	SA16GL	Install AMF inverter MGE 23-400. Reissued 11/17/78.	GL	50360	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
65-A90, B90, C90; T.C. 3A20	SA377GL	Addition of fourth cabin window on right hand side of fuselage. Issued 11/28/79.	GL	18320	Burlington Northern Airmotive International Airport Minneapolis, MN 55450
65-A90, -B90, -C90, E90; T.C. 3A20	SA3971WE	Installation of SDI Model CFS-2002, fuel flow indicating system. Amended 10/19/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
65-B90, -A90 with 90-4031 kit; T.C. 3A30	SA537CE	Installation of Collins AP-103F/FD108 and AP-103F/FD109G Autopilot and flight director. Amended 9/13/68.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-B90, -A90 with 90-4031 kit; T.C. 3A20	SA567CE	Installation of Collins AP-103F/FD108 and AP-103F/FS108G, AP-103F/FD109G autopilot and flight director. Amended 5/4/70.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA569CE	Installation of Collins AP104/FD109H Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA60[illegible]E	Installation of Collins AP-104/FD-109F Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA969CE	Installation of fuel dump valve; G.W. increase to 10,000 pounds. Amended 3/9/70.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
B-90; T.C. 3A2	SA1665SW	Fabricate and install bar assembly. Issued 5/29/73.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
B-90, C-90; T.C. 3A20	SA1454SW	Mitchell automatic flight system model FD/AK282-318 cons. of flight director/autopilot with optional command trim. Issued 4/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B-90, C-90; T.C. 3A20	SA1458SW	Mitchell automatic flight system AK318 cons. of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 4/24/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90; T.C. 3A20	SA1517SW	Automatic flight system YK384 cons. of yaw damper. Issued 9/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90; T.C. 3A20	SA1583SW	Foxtronics/TRAMM BT1 600 nickel-cadmium battery temperature system. Issued 1/3/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
65-B90, C90, E90; T.C. 3A20	SA547CE	Installation of Bendix M4C autopilot. Amended 8/1/72.	SC	15475	The Bendix Corporation Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
65-B90, C90, E90; T.C. 3A20	SA1640SW	Mitchell automatic flight system AK422/FD cons. of Century IV autopilot/flight director with command electric trim. Issued 4/19/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B90, C90, E90; T.C. 3A20	SA3042SW-D	Mitchell automatic flight system AK456 or 456 FD cons. of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim system and optional remote annunciator panel. Issued 1/31/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90, E90; T.C. 3A20	SA3294SW-D	Yaw damper system YK384. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C90; T.C. 3A20	SA537SO	Installation of Bendix YD-4 yaw damper. Issued 5/15/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90; T.C. 3A20	SA541SO	Installation of Bendix FCS-810 automatic flight control system including optional flight director indicator DH-841. Amended 1/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90; T.C. 3A20	SA925EA	Installation of Collins AP-105 autopilot system. Issued 6/28/72.	NE	08160	AIRKAMAN, Inc. Bradley International Airport Windsor Locks, CT 06096
C90, E90; T.C. 3A20	SA546SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim system and optional flight director system. Amended 5/16/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90, E90; T.C. 3A20	SA3124WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
C90, E90, 99; T.C. 3A20, A14CE	SA1013SC	Replace existing nickel-cadmium battery with Gill BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road Suite 200 Atlanta, GA 30339
E90; T.C. 3A20	SA2667WE	Installation of Sperry SPZ-200 autopilot and Stars Instrument System or SPI-77C flight director system. Amended March 1974.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90; T.C. 3A20	SA2680WE	Category II approval of airborne instruments and equipment. Reissued 9/17/73.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90, 99, A100, 200; T.C. 3A20, A14CE, A24CE	SA920SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78052	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
76; T.C. A29CE	SA1153EA	Installation of DeVore "tel-tail" lights on lower surface of horizontal stabilizer. Reissued 7/24/79.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
76; T.C. A29CE	SA1455CE	Installation of DFC200 flight control system (2 axis). Issued 10/17/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
76; T.C. A29CE	SA3256SW-D	Mitchell automatic flight system AK694 consisting of Century IV autopilot or AK694FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3257SW-D	Mitchell automatic flight system AK693 consisting of Century III autopilot with optioanl radio and glide slope couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3258SW-D	Mitchell automatic flight system AK692 consisting of Century III autopilot with optional radio couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3259SW-D	Mitchell AK619 consisting of Century I autopilot with optional omni tracker. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
76; T.C. A29CE	SA3260SW-D	Mitchell command electric trim AK695. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
76; T.C. A29CE	SA3261SW-D	Yaw damper system AK696. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3317SW-D	Installation of Mitchell automatic flight system AK761 consisting of Century I autopilot with omni tracker. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3318SW-D	Installation of Mitchell automatic flight system AK762 consisting of Century IIB autopilot with optional radio couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3319SW-D	Installation of Mitchell automatic flight system AK763 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3320SW-D	Installation of Mitchell automatic flight system AK764 consisting of Century IV autopilot or AK764FD consisting of Century IV autopilot flight director with optional remote annunciator. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3321SW-D	Installation of Mitchell automatic flight system AK765 consisting of command electric trim system. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3322SW	Installation of Mitchell yaw damper YK766. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3345SW	Installation of Mitchell yaw damper YK838. Issued 1/28/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3346SW	Mitchell automatic flight system AK827/FD consisting of Century 41/FD flight director autopilot. Issued 12/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3356SW	Installation of Mitchell automatic flight system AK826 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Incc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA4005WE	Removal of main landing gear door. Issued 7/25/79.	WE	71630	Sierra Academy of Aeronautics Oakland International Airort Oakland, CA 94614
95 Series; T.C. 3A16	SA1-235	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
95 Series; T.C. 3A16	SA1-395	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-422	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-482	16" x 17" opening in lower surface of fuselage.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
95 Series; T.C. 3A16	SA1-588	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95 Series; T.C. 3A16	SA3-262	Automatic pilot L-2 with or without approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-470	L-2C autopilot with or without approach coupler and altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-624	Winslow oil filter 30409A.	CE	80670	United Airplane Sales, Inc. Municipal Airport Wichita, KS 67202
95 Series; T.C. 3A16	SA3-633	Autopilot I-2C with or without approach coupler and/or altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA4-574	Radio rack in nose compartment.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
95 Series; T.C. 3A16	SA4-691	Oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
95 Series; T.C. 3A16	SA4-1052	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A16	SA4-1612	Anticollision beacon Roto-Lite X6000, either 12 or 24 volt, on vertical fin	WE	49690	The Norman Larson Company Van Nuys Airport Van Nuys, CA 91408
95 Series; T.C. 3A16	SA9SW	Aileron trimmer ATC35-107.	SW	06000	Aircraftsmen, Inc. Hangar 2, Will Rogers Field Oklahoma City, OK 73125
95 Series; T.C. 3A16	SA44EA	Wet pump pneumatic deicing.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA70SW	Vapor automatic temperature control system.	CE	82540	Vapor Heating Company 2522 E. Douglas Wichita, KS 67202
95 Series; T.C. 3A16	SA74CE	Federal F-400 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
95 Series; T.C. 3A16	SA92SW	Automatic pilot AK103 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA171WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
95 Series; T.C. 3A16	SA173EA	Beech 5D1048 air reservoir assembly relocated for wing and tail boot deicer.	NE	08160	AirKaman, Inc. Bradley Field Windsor Locks, CT 06096
95 Series; T.C. 3A16	SA231EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA287CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA311WE	Beech pneumatic pitch assist PC-1 and optional installation altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA316EA	M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA360CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation Marquette Division 1145 Galewood Drive Cleveland, OH 44110

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95 Series; T.C. 3A16	SA474EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA474WE	B4 flight control system including basic autopilot, pitch assist PC-1, altitude hold AH-1, and navigational coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA516SW	Automatic trim AK160.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA617SW	III autopilot, automatic pitch trim, stabilizer and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA742SW	AK196 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA831WE	Single-place windshield.	WE	69590	SAFE-SITE, Inc. 3511 W. Sixth Street Los Angeles, CA 90005
95 Series; T.C. 3A16	SA844WE	One-piece windshield.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
95 Series; T.C. 3A16	SA1494WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1532WE	Installation of Brittain Model B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1542WE	Installation of Brittain Model B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1559WE	Installation of Brittain Industries Model B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1587WE	Installation of Brittain Model B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1677WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1833WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, B95A, D95A and E95; T.C. 3A16	SA153SC	Installation of turbosupercharged Lycoming O-360-A1A, IO-360-B1A or IO-360-B1B engines. Amended 2/28/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
95, B95, B95A, D95A, 95-55, 95-A55, 95-B55; T.C. 3A16	SA263CE	Supplemental Model A high intensity wing tip lights, Model C tail light, with or without Model 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
95, B95, B95A, D95A, 95-55, -A55, -B55, -C55, -D55, -56; T.C. 3A16	SA378CE	Installation of Hoskins Supp. Model A high intensity wing tip lights, Model D or K tail lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
95, B95, B95A, 95-A55, -55, D95A; T.C. 3A16	SA571WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTL Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
95, B95, B95A, 95-55, 95-A55, 95-B55, 95-B55B (T-42A), 95-C55; T.C. 3A16	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-3 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95, B95, 95-55, 95-A55, B95A, D95A, E95, 95-E55, -B55A, -B55B, -C55, D55, 95-C55A, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA901SC	Installation of single-piece sloped windshield. Amended 11/21/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. c/o F.K. Leddick & Associates, Inc. 175 W. Wieuca Rd., Suite 120 Atlanta, GA 30342
95, B95, B95A, D95A, E95; T.C. 3A16	SA1409SW	Mitchell automatic flight system AK366, cons. of Century I autopilot with optional omni tracker. Issued 12/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D95A; T.C. 3A16	SA1760WE	Installation of Brittain Industries Model B-5 or NAV-2 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, 95-55, -A55, B95A, D95A, E95, -B55, -B55A, -B55B, -C55, D55, -C55A, D55A, E55, E55A; T.C. 3A16	SA2977WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
95, B95, D95A, E95; T.C. 3A16	SA3090SW-D	Automatic flight system AK562, cons. of Century IIB autopilot. Issued 12/15/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95, B95, B95A, D95, E95; T.C. 5A3	SA3179SW-D	Automatic flight system AK650 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 1/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D95, E95; T.C. 5A3	SA3187SW-D	Mitchell automatic flight system AK366 consisting of Century I autopilot with optional omni tracking system. Issued 2/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D59A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA3680WE	Installation of centerline external air skeg. Amended 4/2/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90065
95, B95, B95A, E95, 95-55, -A55, -B55, -B55A, -B55B, -E55, 56TC, 58. 58A; T.C. 3A16	SA4184WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
95-55; T.C. 3A16	SA1820WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, -A55, -B55, -C55, -D55; T.C. 3A16	SA9CE	Installation of M4B or M4C flight control system. Amended 6/1/70.	SC	15475	Bendix Corporation Avionics Division 2100 N.W. 62nd Street P.O. Box 9414 Fort Lauderdale, FL 33310
95-55, -A55, -B55; T.C. A23CE	SA71GL	Install P/N BA7610 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities, Inc. 9600 West 52nd Street Kenosha, WI 53140
95-55, -A55, -B55; T.C. 3A16	SA126CE	Install Hartzell Model HC-A3XF-2B/7636D or HC-A3VF-2B/V7636D or HC-A3VF-2B/V7636N or PHC-A3XF-2B/7636D or PHC-A3VF-2B/V7636D or PHC-A3VF-2B/V7636K propellers with Woodward Model 210355 or 210438 governors. Reissued 2/26/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-55, 95-A55; T.C. 3A16	SA136RM	Removal of existing nose cone, Beech P/N 95-410011-3 and replacement with later model nose cone, Beech P/N 95-410021-605. Issued 3/28/78.	RM	73948	Spanish Fork Flying Service, Inc. Box 48 Spanish Fork, UT 84660
95-55, -A55; T.C. 3A16	SA387GL	Installation of Norton radome kit No. 415CX-100 and -200. Issued 2/8/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-55, A55; T.C. 3A16	SA447SW	Nose modification.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA448SW	Rear baggage compartment.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA540EA	Installation of radome kits No. 3063X-R-100 and -200. Reissued 3/12/76.	GI	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-55, 95-A55, -B55, -B55A, -B55B; T.C. 3A16	SA795CE	Install propeller Models BHC-C2YF-2CH/C8465-6 or BHC-2CHF/FC8465-6, DHC-C2YF-2CH/C8465-6 or DHC-C2YF-2CHF/FC8465-6 with spinner C-2285-1; or PHC-C3YF-2/FC7663-2R with spinner C-3567-1. Amended 8/30/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-55, -A55, -B55, -C55, D55; T.C. 3A16	SA886EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-011401. Issued 10/27/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
95-55, -A55, -B55, -B55A, B55B, C55, C55A, D55, D55A, E55, E55A, 58, 58A; 56TC, A56TC; T.C. 3A16	SA991EA	Installation of "Tel-Tail" logo lights. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA1014SO	Installation of Symbolic Displays Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/30/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
95-55, 95-A55, -B55, -C55, -D55, E55, E55A, 58; T.C. 3A16	SA1134CE	Installation of King Model KFC-200 2-axis (3 optional), flight control system. Amended 6/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-55, A55, B55, B55B, C55, D55, E55; T.C. 3A16	SA1173SW	Mitchell automatic flight system AK292 cons. of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers. Issued 7/14/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1299SW	Mitchell automatic flight system Model 282-292 cons. of flight director/autopilot with optional automatic pitch trim. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, -D55, -D55A, E55, E55A; T.C. 3A16	SA1300SW	Mitchell automatic flight system AK330, cons. of Century I autopilot with optional omni tracker. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA1472CE	Installation of elevator tail cone fairing. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-55, -A55, -B55, -C55, D55, D55A, E55, E55A, 56TC, A56TC; T.C. 3A16	SA1565SW	Mitchell automatic flight system AK408 cons. of Century II autopilot with optional radio coupler. Issued 12/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1743SW	Mitchell automatic flight system AK401 cons. of Century IIB autopilot with optional radio coupler. Issued 10/16/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA1777SW	Mitchell automatic flight system AK450 cons. of Century III autopilot with optional command/electric trim radio coupler, and glide slope coupler. Issued 12/26/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A; T.C. 3A16	SA1808SW	Installation of automatic flight system AK446 Century IV autopilot and AK446FD Century IV flight director autopilot with electronic/command, and pitch trim. Issued 2/15/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-55, E95, A-55, B55, C55, B95A, D95A; T.C. 3A16	SA1958WE	Installation of Brittain Industries NAV-2E flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, 95-A55, -B55, -C55, D55, E55, 58; T.C. 3A16	SA2543WE	Installation of SDI/Hoskins Model 700801 anticollision light. Amended 12/19/72.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
95-55, 95-B55A; T.C. 3A16	SA2882WE	Installation of McCAuley 3AF32C75/82NB-6 full-feathering constant speed propellers and D3499 or D3605 spinner assemblies. Issued 5/13/74.	WE	17154	Dennis A. Praegitzer Bridgeford Flying and Propeller Service P.O. Box 6277 Stockton, CA 95206
95-55, A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3108SW-D	Mitchell AK446 or AK446FD cons. of Century IV flight director autopilot with optional remote annuciator. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3109SW-D	Mitchell AK450 cons. of Century III autopilot with optional command automatic electronic pitch trim system, radio and glide slope coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3295SW-D	Yaw damper system YK428. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A13	SA3333SW-D	Mitchell automatic flight system AK401 consisting of Century IIB autopilot with optional radio couplers. Issued 2/20/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3918WE	Installation of Silver Instruments Fueltron III digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3919WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-A55; T.C. 3A16	SA2690WE	Installation of manual pitch trim system and Lear P/N 800880 autopilot. Issued 6/19/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510
95-A55, 95-B55, 95-C55; T.C. 3A16	SA1392WE	Modification of fuselage structure and control system to accommodate a camera installation between Stations 131 and 151.	WE	25971	Continental Airservice, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
95-A55, -B55, -C55, -D55, E55/E55A, 58; T.C. 3A16	SA1523CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-A55, -B55; T.C. 3A16	SA2964WE	Installation of Collins AP 107/FD 112C autopilot/flight director system. Reissued 1/14/75.	CE	24250	Collins Radio Group 5220 "C" Avenue, N.E. Station 120-120 Cedar Rapids, IA 52406
95-B55; T.C. 3A16	SA3179WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 7/27/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
95-B55; T.C. 3A16	SA3353SW	Installation of Mitchell automatic flight system AK841/FD consisting of Century 41/flight director autopilot. Issued 1/29/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-B55, -C55, D55, E55, 56TC, 58; T.C. 3A16	SA15GL	Installation of radome kit No. 3064X. Amended 9/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operation P.O. Box 350 Akron, OH 44309
95-B55, 95-C55, 56TC, D55, E55, 58; T.C. 3A16	SA40GL	Installation of Norton Company radome kit No. 3064X-R-500 for 10" RCA AVQ 45, 46, 47, and the 12" King KWX-40 radar antennas. Amended 4/11/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
95-B55, -B55A, E55, E55A, 58, 58A; T.C. 3A16	SA64GL	Installation of radome kit P/N 4083X. Amended 5/8/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-B55, -B55A, -C55, -C55A; T.C. 3A16	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
95-B55, -C55, 56TC, D55, E55, 58; T.C. 3A16	SA482EA	Installation of Radome Kit No. 3064X-R-500 for 10-inch RCA AVQ-45, AVQ-46, and AVQ-47 radar antenna. Amended 6/19/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
95-B55 & 95-B55A, T.C. 502 and up; 95-C55 & 95-C55A, TE-1 thru TE-451; 95-D55 & 95-D55A, TE-452 thru TE-767; 95-E55 & 95-E55A, TE768 and on; T.C. 3A16	SA799CE	Installation of Airborne/Goodyear iceguard. Issued April 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
95-B55, -B55A, E55, E55A, 58, 58A; T.C. 3A16	SA1471CE	Installation of flap and aileron seals. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-B55, 95-C55, 95-B55A, 95-C55A; T.C. 3A16	SA2031WE	Installation of Brittain Industries B-VII, NAV-2B, or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-B55, -B55A, E55, E55A; T.C. 3A16	SA3364SW	Mitchell automatic flight system AK842 consisting of Century 21 autopilot. Issued 6/6/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-B55, -B55A, -E55, -E55A; T.C. 3A16	SA3378SW-D	Mitchell automatic flight system AK841 consisting of Century 41 autopilot or AK841FD consisting of Century 41 flight director autopilot. Issued 5/15/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-B55, -B55A, -C55, -C55A, D55, D55A; T.C. 3A16	SA3657WE	Installation of a vapor cycle air conditioning system. Issued 6/28/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
95-C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA773CE	Installation of Hartzell BHC-C2Y, BHC-J2Y, PHC-C3Y or PHC-J3Y propellers in accordance with Hartzell Manual 115G. Amended 2/1/80.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1054CE	Installation of AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1055CE	Installation of AP-107 3-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1056CE	Installation of AP-107, 2-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, D55, E55, 56TC, A56TC, 58; T.C. 3A16	SA1345CE	Chrome plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
95-C55; T.C. 3A16	SA1713WE	Removal of emergency exit to permit aircraft to engage in special purpose operations such as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
95-C55, -C55A, D55, D55A, E55, E55A, 58 58A; T.C. 3A16	SA3840WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
B55; T.C. 3A16	SA1-463	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
B95; T.C. 3A16	SA3400WE	Installation of Pathfinder autopilot systems. Issued 7/5/77.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
B95A, D95A, E95; T.C. 3A16	SA1672SW	Mitchell automatic flight system AK425, cons. of Century III autopilot with optional command automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/7/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
99; T.C. A14CE	SA298GL	Reduce number of passenger seats from 15 to 9. Issued 3/22/79.	GL	27760	Custom Air Service Willow Run Airport Ypsilanti, MI 48197
99; T.C. A14CE	SA366GL	Installation of microwave landing system airborne equipment. Issued 10/12/79.	GL	58150	Mesaba Aviation 2002 Airport Road Grand Rapids, MN 55744
99; T.C. A14CE	SA4030SW	Pratt & Whitney PT6A-27/28 engines. Issued 8/30/79.	SW	69214	Royale Turbines, Inc. Shreveport Regional Airport Shreveport, LA 71109
99, 99A; T.C. A14CE	SA717CE	Installation of M4C autopilot.	CE	15477	Bendix Avionics 3303 East Harry Street Wichita, KS 67218
99, 99A, 99A (FACH), A99, A99A, B99; T.C. A14CE	SA114GL	Installation of Norton Radome Kit 3097X. Issued 5/20/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
99, 99A, A99, A99A, B99; T.C. A14CE	SA143GL	Modification of existing B.F. Goodrich propeller de-icing system. Issued 11/23/76.	GL	38500	B.F. Goodrich Engineered Systems Company Div. of B.F. Goodrich Company Akron, OH 44318
99, 99A, 100, A100; T.C. A14CE	SA811CE	Battery temperature sensing and over-temperature warning systems. Issued February 1972.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
99, A99, 99A, A99A, 100, A100, A100A T.C. A14CE	SA894SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	SO	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
99, 99A, 99A (FACH), A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1178CE	Install wing front spar reinforcement kit. Reissued 5/9/80.	WE	13177	Aviadesign, Inc. Suite 101, Bank of A., Levy Bldg. 5808 E. Telephone Road Ventura, CA 93003
99, 99A, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1280CE	Install Avcon Ind. TSO-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1453CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1454CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Reserach Corporation P.O. Box 222 Buffalo, NY 14225
99, 99A, A99, A99A, B99, 100, A100; T.C. A14CE	SA2908WE	Installation of fuel tank boost pump. Issued 7/23/74.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
99, 99A, 99A (FACH), A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA3106WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
99, 99A, A99, A99A, B99; T.C. A14CE	SA4013WE	Installation of a hydraulic landing gear retraction system. Issued 9/19/79.	WE	13177	Aviadesign, Inc. Suite 101, Bank of America Levy Building 5808 East Telephone Road Ventura, CA 93003
99A; T.C. A14CE	SA981EA	Installation of modified cargo door, airstair door, jump door in cargo door and external parachute's step. Amended 10/4/74.	EA	23450	C N C Industries, Inc. Hyde Field, Route 223 Clinton, MD 20735

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
100, A100; T.C. A14CE	SA1197CE	Install Teledyne/Gill lead-acid battery, BB638T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	65300	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133
100, A100; T.C. A14CE	SA1573SW	Foxtronics/TRAMM BT1 600 nickel cadmium battery temperature system. Issued 12/19/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
A100; T.C. A14CE	SA256GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
A100; T.C. A14CE	SA476SC	Installation of M4C autopilot in accordance with Bendix drawing list AE-163, Rev. A. Issued 10/14/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
A100; T.C. A14CE	SA1058SO	Replace existing nickel-cadmium batteries with Teledyne Gill B6381T batteries. Issued 3/29/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
B100; T.C. A14CE	SA1018SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
B100, S/N's BE-21 and up; T.C. A14CE	SA3981WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200; T.C. A24CE	SA381GL	Installation of a single Canadian Marconi CMA-734 Omega/VLF navigation system. Issued 1/4/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
200; T.C. A24CE	SA1016SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 POwers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
200; T.C. A24CE	SA1189CE	Installation of Safe Flight speed command or speed command and auto-throttle (SCAT) system. Amended 6/8/77	EA	69500	Safe Flight Instrument Corp. (SFIC) P.O. Box 550 White Plains, NY 10602
200; T.C. A24CE	SA3339WE	Installation of Hydro-Aire power brake/skid control system. Issued 5/17/77.	WE	26725	Hydro-Aire Division Crane Company, Inc. P.O. Box 7722 Burbank, CA 91510
200; T.C. A24CE	SA3982WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200, A200; T.C. A24CE	SA1278CE	Installation of Avcon Industries TSC-C39a stretchers. Issued February 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
200, A200, 200T; T.C. A24CE	SA192GL	Installation of Norton radome kit No. 2090XS Amended 8/24/78.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operation P.O. Box 350 Akron, OH 44309
200, A200, 200T; T.C. A24CE	SA1449CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
200, A200, 200T; T.C. A24CE	SA1450CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47B, B3, D, D1, E, G, G-2, H-1; 47G-2A, -2A-1, -3, -3B, -3B-1, -3B-27, -4, -4A, -5, -5A; 47J, K, J-2, J-2A; 206A, 206B; T.C. H-1, 2H3, 2H1, H2SW	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A450, A408W or A470W (white), A408R/W or A470 R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417
47B, B3, D, D1, E, G, G-2, H-1, G-2A, -2A-1, G3, -3B, -3B-1, -2, G-4, G-5, -5A, B-3B, -2A, G-4A-5; T.C. H-1, 2H3	SW2840SW	Chemical spray boom. Reissued 4/19/79.	SW	84614	Warnell Company Box 588 Atlanta, TX 75551
47D-1; T.C. H-1	SH13WE	Conversion of Bell Model 47D-1 to (1) Model 47G-2. Reissued 1/18/74.	SW	52800	Gifton McCreary 1921 W. 5th Street, Apt. #180 Irving, TX 75060
47D-1; T.C. H-1	SH283SW	Battery relocated and ballast installed. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D-1; T.C. H-1	SH397SW	Hydraulic boost kit. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D-1; T.C. H-1	SH529SW	Franklin 6V-350-A engine. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1; T.C. H1	SA2666WE	Ceconite 102 material covering of vertical fin. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
47D-1, 47G; T.C. H-1	SH213WE	Installation of exhaust muffler assembly. Issued 3/8/78.	WE	00100	A & H Welding Company 11230 Ilex Avenue Pacoima, CA 91331
47D1, 47G; T.C. H-1	SH752SW	Centerframe and Lycoming VO-435 engine.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G; T.C. H-1	SH888SW	Use of spacer in lieu of snap ring on tail rotor drive. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G-2; T.C. H-1	SH1007SW	Modify tail rotor pitch change mechanism to add duplex bearing. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G-2; T.C. H1	SH2772SW	Revise mast controls and remove stabilizer bar and install control system.	SW	78425	Texas Helicopter Corporation 1336 South Irving Heights Drive Irving, TX 75060
47D1, 47G-2; T.C. H-1	SH588SW	Conversion to single-place cabin without doors and revised controls. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G-2, 47G-3, 47G-4; T.C. H-1, 2H3	SH611SW	Left and right door with tinted sliding windows. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G2, G2A, G2A-1, G-3, -3B, -1, -4, -4A, -5, -3B-2; T.C. H-1, 2H3	SH972SW	Copilot's rudder pedals. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47E, 47G-2, -2A, -2A-1, 47G-3, -3B, -3B-1, -3B-2, 47G-4, -4A, 47G-5, 47J, 47J-2, -2A, 47K; T.C. H-1, 2H3, 2H1	SH102WE	Installation of automatic flagman model 5. Issued 2/17/71.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362
47G Series; T.C. H-1, 2H3, 2H1	SH5CE	Install 32 foot agricultural spray boom assembly. Issued 1/31/78.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G; T.C. 2H3	SH78WE	Installation of Calicopters Cabin Heater Kit CC 1000.	WE	19440	Calicopters, Inc. 1595 Lindbergh Street Stockton, CA 95206
47G; T.C. H-1	SH610EA	Following modifications are compatible with each other and may be incorporated simultaneously: STCs SA479SW, SH21EA, SH163EA.	EA	19950	Carson Helicopters, Inc. R.R. 1, Box 94 Perkasie, PA 18944

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 765	SA1-174	Hartzell HC-93Z30-2C/10152-5 1/2 propellers.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-191	Fuel flow meter system.	GL	05970	Aircraft Service, Inc. Cleveland Hopkins Airport Cleveland, OH 44101
18 Series; T.C. 765	SA1-200	Oxygen system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18 Series; T.C. 765	SA1-226	18" AVQ-50 antenna mount.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-234	12" AVQ-50 antenna mount.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-243	Combination of following STC's: SA1-60 fiberglass nose bowl; SA1-61 auxiliary wing tanks; SA1-62 E18S wing tips; SA1-76 fiberglass tail gear door; SA1-118 three-blade Hartzell propellers; SA1-236 air step door; SA2-383 stabilizer angle of incidence change; SA4-34 main landing gear doors.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-270	Fiberglass clamshell-like parts attached to rear of tail wheel well enclosure doors.	EA	48528	Robert S. Klein and E. Reed Zimmerman Tuckerton Road & Maple Lane Reading, PA 19603
18 Series; T.C. 765	SA1-338	Underseat radar scope mounts for: RCA 5" AVQ-50, Collins 4" WP-103, and RCA 5" AVQ-55/AVQ-20.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA1-568	Bendix 75-ampere 1273-1A generators and modification B100 to new Model 1273-3 with cooling and electrical changes.	EA	64825	Plymouth Aviation Corporation P.O. Box 247 Forest Hills, NY 11375
18 Series; T.C. 765	SA1-597	Collins WP-103 antenna mounts for 12" WP-103 antenna and 18" WP-103 antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA3-1	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
18 Series; T.C. 765	SA3-91	Grimes D-7080 rotating beacon on belly of aircraft.	GL	38325	Gopher Aviation, Inc. Rochester, MN 55901
18 Series; T.C. 765	SA3-93	Carburetor and windshield fluid deicing systems.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
18 Series; T.C. 765	SA3-134	Installation of electric fuel boost pumps - AN4100. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18 Series; T.C. 765	SA3-177	Electric emergency fuel pumps (Thompson TFD 600-3 pumps with Delco A4949 motors).	GL	38325	Gopher Aviation, Inc. Rochester, MN 55901
18 Series; T.C. 765	SA3-184	Mounting bracket to antenna 137X-1.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
18 Series; T.C. 765	SA3-252	Radome installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18 Series; T.C. 765	SA3-323	Radio DF antenna 137A-2 on bottom of fuselage.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
18 Series; T.C. 765	SA3-410	L-2C autopilot with approach coupler and altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
18 Series; T.C. 765	SA3-417	AP-102 automatic pilot including FD-105 integrated flight system instruments.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
18 Series; T.C. 765	SA3-677	Two Delco motors with two Pesco AN 4100, 200 g.p.h. fuel boost pumps.	GL	78610	Toman Aircraft Service 12801 S. 82nd Avenue Palos Park, IL 60464
18 Series; T.C. 765	SA4-992	Ceconite 101 covering of rudders, elevators, flaps and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
18 Series; T.C. 765	SA4-6	Two Janitrol heaters of 25,000 B.t.u. capacity each, Mot. B15C54 in right and left wheel well.	WE	80925	United States Steel Corporation 235 Montgomery Street San Francisco, CA 94010
18 Series; T.C. 765	SA4-125	E18S powerpack for 450 hp. (Maximum continuous and takeoff).	GL	39125	Goodyear Tire & Rubber Company Flight Operations Municipal Airport Akron, OH 44309
18 Series; T.C. 765	SA4-126	One Southwind 940-B 20,000 B.t.u. TSC-C20 heater in each nacelle.	GL	39125	Goodyear Tire & Rubber Company Flight Operations Municipal Airport Akron, OH 44309
18 Series; T.C. 765	SA4-509	Gross weight increased to 9,000 lbs. with powerpack STC SA4-125; Southwind heater STC SA4-126; and horizontal stabilizer STC SA2-120.	WE	67794	Richfield Oil Company 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA4-1076	Electrically-driven, mechanical, refrigerated air conditioner.	WE	08356	Airtransit, Inc. 3131 Monterosa Phoenix, AZ 85000
18 Series; T.C. 765	SA4-1102	Cabin window.	WE	67794	Richfield Oil Company 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA4-1110	Baggage compartment.	WE	67794	Richfield Oil Company 555 S. Flower Street Los Angeles, CA 90052
18 Series; T.C. 765	SA4-1378	R-985-APS Series engines. (Applies only to D18S aircraft modified per STC SA2-820.)	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91500
18 Series; T.C. 765	SA7EA	Koehler Air-Lav Model 45.	GL	90065	Youngstown Airways, Inc. Municipal Airport Youngstown, OH 44501
18 Series; T.C. 765	SA52EA	Underseat radar scope mount 299-05 for RCA 5" AVQ-55/AVQ-20 radar	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18 Series; T.C. 765	SA111EA	One-piece window on left side of pilot's cockpit.	NE	71780	Simsbury Flying Service, Inc. 94 Walcot Road Simsbury, CT 06070
18 Series; T.C. 765	SA111SO	Installation of wing and empennage surface de-icing system.	EA	25635	Commuter A/C Manufacturing Corp. Box 904, Broome County Airport Binghampton, NY 13902
18 Series; T.C. 765	SA116SW	Combustion monitor.	EA	60100	Monitair Corporation Ramapo Valley Airport Spring Valley, NY 10977
18 Series; T.C. 765	SA186CE	Cowl flap modification kit TYL-6.	GL	14500	Barber-Colman Company Aircraft & Missile Products 1300 Rock Street Rockford, IL 61101
18 Series; T.C. 765	SA206SO	Heater fuse test switch and standby heater fuel system.	SO	75117	J.P. Stevens & Company, Inc. P.O. Drawer 5457, Station B Greenville, SC 29602
18 Series; T.C. 765	SA207CE	Pratt & Whitney R-985-APS engines per STC SE4-864 in aircraft with Beech 9,900 lbs. gross weight kit 766-1.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67202
18 Series; T.C. 765	SA222SO	RCA AVQ-55 radar system and a Narco UDI-2 DME system.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
18 Series; T.C. 765	SA240EA	Elevator trim tab servo as optional equipment with Sperry SP-3 automatic pilot system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18 Series; T.C. 765	SA276WE	Carburetor air filter and scoop.	WE	67794	Richfield Oil Corporation 555 S. Flower Street Los Angeles, CA 90052

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
47H-1; T.C. TCH-1	SH909SW	Franklin 6V-350-A engine. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47J; T.C. 2H1	SH375AL	Installation of Airglas model L270C-47J skis. Issued 5/26/70.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
47J; T.C. 2H1	SH1422CE	Installation of engine exhaust muffler. Issued 6/12/78.	CE	36510	Fostaire Helicopters 400 North Wharf Street St. Louis, MO 63102
47J, 47J2, 47J2A, 47K; T.C. 2H1	SH194WE	Installation of Jasco alternator P/N 7555-1 24-volt system. Amended 7/3/79.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
47J, 47J2, 47J2A, 47K; T.C. 2H1	SH199WE	Installation of stirrup assemblies to directional control pedals for operation by handicapped pilot. Issued 4/14/77.	WE	28620	Barry C. Dallwig 113 East Elfin Green Port Hueneme, CA 93041
47J-2, -2A; 47G-3B, 3B-1, 3B-2; T.C. 2H1, 2H3	SH12CE	Replace existing engine induction air filter with AC Spark Plug Filter - Type AAF-103.	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
204, 205, 212; T.C. H1SW, H4SW	SH611NW	Installation of onboard weighing system. Issued 6/16/78.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
204B; T.C. H1SW	SH984SO	Installation of Lycoming T5313A or B engines, replacing Lycoming T5311A engines, including minor installation changes. Issued 5/10/78.	SO	86080	Wilco Aviation bBlackwell Airport P.O. Box 506 Ozark, AL 36360
204B, 205A, 205A-1; T.C. H1SW	SH149WE	Installation of Chadwick electronic weighing system C47. Issued 6/1/72.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
204B, 205A, 205A-1; T.C. H1SW	SH172WE	Installation of A500 battery temperature monitor systems. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
204B, 205A, 205A-1; 206A, 206B, 206B-1, 206L, 212; T.C. H1SW, H2SW, H4SW	SH155WE	Installation of battery temperature monitor system. Amended 6/22/78.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
204B, UH1-B; T.C. H1SW	SH183AL	Installation of Airglas L7000 or L8500B skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
204B, 205A, 205A-1, 212; T.C. H1SW, H4SW	SH733NW	Installation of onboard weighing system. Issued 3/21/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
205A, 205A-1; T.C. H1SW	SH198AL	Installation of Airglas L8500 or L8500A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
205A, 205A-1; T.C. H1SW	SH255WE	Installation of emergency exit window. Reissued 1/11/80.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
205A, 205A-1; T.C. H1SW	SH462NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
205A, 205A-1; T.C. H1SW	SH1022SW	Interior arrangement for 7 passenger seats and 1 jump seat. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
205A, 205A-1; T.C. H1SW	SH1789SW	Foxtronics/Tramm BTI 600 nickel cadmium battery temperature system. Issued 1/29/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
205A, -1, 212; T.C. H1SW, H4SW	SH1700SW	Hard surface skid shoes. Issued 6/6/73.	SW	61650	Northrop Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
205A-1; T.C. H1SW	SH140GL	Installation of dual band (K/X) type weather radome. Issued 10/27/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
206; T.C. H2SW	SH329NW	Installation of automatic flagman. Issued 10/28/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206 Series; T.C. H2SW	SH1091SC	Replace existing battery with an Eagle-Picher magnum 13 battery. Issued 8/22/79.	SW	18190	BSI Manufacturing, Inc. 101 Space Park South Drive Nashville, TN 37211
206; T.C. H2SW	SH1137SO	Install Utah Research and Development Co. model 124BC101 battery charging system. Issued 3/11/80.	SO	18190	BSI Manufacturing, Inc. 101A Space Park South Drive Nashville, TN 37211
206, 206A, 206B; T.C. H2SW	SH963EA	Installation of battery temperature alert system Model Bell B206-TA180 or B206D-TA180. Amended 6/28/74.	EA	25920	Consolidated Instrument Co., Inc. Teterboro Airport Teterboro, NJ 07608
206, 206A, 206A-1, 206B, 206B-1; T.C. H2SW	SH1018EA	Installation of Casey shroud type heater. Amended 11/14/79.	EA	20112	Casey Copter Accessories, Ltd. P.O. Box 121 Montreal International Airport Dorval, Quebec, Canada H4Y 1A5
206, A, A-1, B, B-1, L, L-1; T.C. H2SW	SH2828SW	Sloping pedestal and instrument. Issued 8/4/78.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
206, A, A-1, B, B-1, L; T.C. H2SW	SH4061SW	Install ruggedized attitude gyro and related vacuum system components. Issued 11/27/79.	SW	40000	Hamilton Instruments, Inc. 106 Neuhaus Street Houston, TX 77061
206A; T.C. H2SW	SH10CE	Install Hoskins Twilighter Mk III lighting system consisting of P/N 60-0032-31 power supply and two of Model 2 P/N 30-0021-11 lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
206A; T.C. H2SW	SH117WE	Installation of cargo rack on one side or on both sides of skid gear. Amended 10/20/70.	WE	03270	U.S. Department of Agriculture Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
206A, 206B, 206L, 206L-1, Normal Category; T.C. H2SW	SH240WE	Installation of baggage compartment extension. Issued 7/12/79.	WE	50275	Ronald A. Leibin and Stephen H. Crowe 2761 Hollywood Way Burbank, CA 91505
206A; T.C. H2SW	SH411AL	Installation of mirror kit assembly. Issued 12/15/70.	AL	10650	Anchorage Helicopter Service, Inc. 1812 East Fifth Avenue Anchorage, AK 99501
206A; T.C. H2SW	SH635EA	Operate with one or both rear doors removed and both front doors installed on helicopters equipped with or without emergency float gear.	EA	65008	The Port of New York Authority 111 8th Avenue, Room 1601 New Y
206A; T.C. H2SW	SH837EA	Installation of Airborne television and microwave transmission system. Amended 3/24/71.	EA	30992	Dynasciences Corporation Township Line Road Blue Bell, PA 19422
206A; T.C. H2SW	SH864EA	Installation of AACK-1R Optical Radiation Corporation Model B "Locator" search light plus relocation of landing lights. Installation of additional contact surfaces "bear paws" to standard skid gear. Issued 2/17/71.	EA	12495	Atlantic Aviation Corporation Bell Helicopter Service Center P.O. Box 2307 South Hackensack, NJ 07608
206A; T.C. H2SW	SH892EA	Installation of Grimes Manufacturing Company supplemental strobe lights. Issued 11/26/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
206A; T.C. H2SW	SH1164SW	Installation of dual battery system using the ship's original battery and one installed by Bell Service Instructions and Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
206A; T.C. H2SW	SH1675SW	Heater system for de-fog air. Issued 6/15/73.	SW	68768	Rockwell International Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
206A, A-1, 206B; T.C. H2SW	SH1534SW	Remove standard BHC short skid shoes and install full length hard surface skid shoes. Issued 11/8/72.	SW	61650	Northrop Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
206A, B; T.C. H2SW	SA116WE	Installation of Nightsun SX-16C Searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206A, B; T.C. H2SW	SH122WE	Installation of JB Systems, Inc. airconditioning system. Amended 12/10/73.	RM	45750	JB Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
206A, 206B; T.C. H2SW	SH124NW	Installation of Simplex 2700 and 2700A spray system tank assembly. Issued 9/9/74.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206A, 206B; T.C. H2SW	SH126WE	Installation of cartridge boost electrical starter system. Reissued 5/15/72.	WE	77492	Talley Industries, Inc. 4551 E. McKellips Road P.O. Box 849 Mesa, AZ 85201
206A, 206B; T.C. H2SW	SH138WE	Installation of Chadwick cargo rack C-72. Issued 1/6/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH139WE	Installation of Chadwick C-22 auxiliary fuel system and C-30 ferry kit. Issued 1/7/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH148WE	Installation of Chadwick electronic weighing system C-45. Issued 5/26/72.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH158WE	Installation of Silver Star I anticollision light. Issued 7/9/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
206A, 206B; T.C. H2SW	SH209WE	Installation of type design change covering the SFENA ministab flight control system in various model combinations. Reissued 9/7/79.	WE	71450	SFENA Corporation 385 Reed Street Santa Clara, CA 95050
206A, 206B; T.C. H2SW	SA244NW	Installation of HE-206-010 bleed air heater system. Issued 3/2/76.	EA	35777	J.E. Flippo Rural Route 1, Pritchard Lane Westbank, B.C., Canada VOH-2A9
206A, 206B normal category; T.C. H2SW	SH266WE	Installation of Carter Engineering Model CEL 450-206 searchlight. Issued 2/8/80.	WE	19986	Carter Engineering Company 232 South Glasgow Avenue Inglewood, CA 90301
206A, 206B; T.C. H2SW	SH278NW	Installation of an electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems Inter'l 619 Riverside Drive Seattle, WA 98108
206A, 206B; T.C. H2SW	SH309AL	Installation of cargo basket. Amended 7/26/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH332AL	Installation of Airglas model L2700-206A skis. Amended 3/3/73.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH380AL	Installation of cargo baskets. Amended 8/7/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH474AL	Installation of Alaskan Sky-Craft Company, Inc. cargo step. Amended 7/20/73.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH515AL	Installation of ASC transporter cargo step. Amended 4/4/75.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH543NW	Installation of Bell 205 series cyclic stick grip. Issued 12/9/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH544NW	Installation of 28 volt DC power outlet in cabin. Issued 11/10/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH625NW	Installation of collective torque tube actuated hour meter switch and an engine-out audible warning system. Issued 6/28/78.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH690NW	Installation of cyclic operated counter system. Issued 11/27/78.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH702NW	Installation of weighing system. Issued 1/23/79.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206A, 206B; T.C. H2SW	SH759NW	Installation of an onboard weighing system. Issued 5/3/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
206A, 206B; T.C. H2SW	SH791NW	Installation of a model 50 spray system. Issued 6/26/79.	NW	66340	Rambling Rotors, Inc. Route 2, Box 244 La Grande, OR 97850
206A, 206B; T.C. 42SW	SH848NW	Installation of a model 4900 spray system. Issued 10/22/79.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206A, 206B; T.C. H2SW	SH1062SO	Installation of fuel tank filler extension (increased fuel capacity).	SO	78475	Thoroughbred Helicopter Service, Inc. Route 3, Paris Pike Lexington, KY 40511
206A, 206B, 206L; T.C. H2SW	SH1125EA	Installation of Aircraft Parts Corp. starter-generator, P/N 150SG111Q. Amended 11/27/78.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
206A, 206B; T.C. H2SW	SH1134SC	Installation of one-piece entrance step. Issued 2/19/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri City Airport Blountville, TN 37617
206A, 206B; T.C. H2SW	SH1753SW	Collapsible table and bar in passenger compartment. Issued 10/25/73.	SW	36550	Foster-Edward Aircraft Company 304 Fair Oaks Boulevard Euless, TX 76039
206A, 206B; T.C. H2SW	SH1754SW	Foxtronics/Tramm BTI 600 nickel-cadmium battery temperature system (single battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1755SW	Foxtronics/Tramm BTI 600 nickel-cadmium battery temperature system (dual battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1759SW	Ni-Cad battery overtemperature warning system. Issued 11/6/73.	SW	22280	Chrysler Corporation Space Division P.O. Box 29200 New Orleans, LA 70189
206A, 206B; T.C. H2SW	SH2889SW	Fuel filler neck.	SW	32758	Edwards & Associates, Inc. 13611 Heartside Place Dallas, TX 75234
206A, 206B; T.C. H2SW	SH4083SW	Install wire strike protection system. Issued 2/16/80.	SW	75234	Bristol Aerospace, Limited P.O. Box 340283 Dallas, TX 75234
206A, 206B; T.C. H2SW	SH4134SW	Fuel extender. Issued 5/29/80.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
206A, 206B; T.C. H2SW	SH4135SW	Vertical sliding window, P/N 206-108. Issued 5/30/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206B-1; T.C. H2SW	SH164WE	Installation of A500 battery temperature monitor system. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
206A, B; 206L; T.C. H2SW	SA86GL	Installation of Marathon CA1700 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Co., Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48083
206A, 206B; 206L; T.C. H2SW	SH184WE	Installation of turbine over-temperature warning system. Amended 4/4/77.	WE	60425	MRSC Incorporated 10959 San Diego Mission Road San Diego, CA 92108
206A, 206B, 206L, 206L-1; T.C. H2SW	SH227WE	Installation of baggage compartment extension. Issued 11/3/78.	WE	50275	Ronald Leibin/Steve Crowe 2761 Hollywood Way Burbank, CA 91505
206A, 206B, 206L, 206L-1; T.C. H2SW	SH1147SC	Installation of baggage floor protector. Issued 5/29/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri City Airport Blountsville, TN 37617
206A, 206B, 206L, 206L-1; T.C. H2SW	SH1148SO	Installation of a rain-gutter. Issued 6/2/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri City Airport Blountsville, TN 37617

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206A, 206B; 206L; T.C. H2SW	SH736SO	Installation of SAFT type 1656 nickel-cadmium electrical storage battery. Amended 11/19/76.	SO	69800	SAFT America, Inc. P.O. Box 1886 711 Industrial Boulevard Valdosta, GA 31601
206A, 206B, 206L; T.C. H2SW	SH1148EA	Installation of a modified Lear-Siegler starter-generator, P/N 23032-010. Amended 6/1/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
206A, 206B, 206L; T.C. H2SW	SH4136SW	Replacement window, P/N 206-B-104-23, -24, 206-L-104-23, -24. Issued 5/30/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206L, 206L-1; T.C. H2SW	SH200GL	Installation of NI-CAD, Inc. Model No. 62239 engine lubrication system scavenge filter. Amended 6/22/79.	GL	61546	NI-CAD, Incorporated 24800 U.S. 20 South Bend, IN 46628
206A, 206B, 206L, 206L-1; T.C. H2SW Normal Category	SH244WE	Installation of cyclic support cover, P/N 2COS6C Issued 10/9/79.	WE	50275	Stephen H. Crowe and Ronald A. Leibin 2761 Hollywood Way Burbank, CA 91505
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH247WE	Installation of Silver Instruments fueltron IG or IP digital fuel flow and totalizer system. Issued 9/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH252WE	Installation of SDI model CFS-1002, fuel flow indicating system. Issued 9/14/79	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH253WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 9/17/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206A, 206B, 206L, 206L-1; T.C. H2SW	SH4146SW	Vertical slide window in crew door. Issued 6/25/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206L-1; T.C. H2SW	SH198WE	Installation of tail rotor flood lights on the upper surfaces of horizontal stabilizers. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
206B; T.C. H2SW	SH5NE	Installation of revised instrument panel and installation of pressure operated gyro instrument back-up system. Issued 12/14/73.	NE	26550	Copters Unlimited, Inc. T.F. Green State Airport Warwick, RI 02886
206B; T.C. H2SW	SH134GL	Install Allison 250-C20B engine. Issued 9/10/76.	GL	14212	Aztec Aviation, Inc. Grissom Airport Bedford, IN 47421
206B; T.C. H2SW	SH174WE	Installation of Nightsun SX-16C searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
206B; T.C. H2SW	SH237WE	Installation of a "HCS-206" helicopter computer system. Issued 5/23/79.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
206B; T.C. H2SW	SH384GL	Installation of Tayburn Electronics, Inc. airborne television and microwave transmission system (electronic news gathering). Issued 1/31/80.	GL	02392	Aeronautical Systems, Inc. Lane Air Terminal P.O. Box 19824 Port Columbus Int'l. Airport Columbus, OH 43219
206B; T.C. H2SW	SH446NW	Installation of Simplex 5000 spray kit. Amended 6/30/78.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206B; T.C. H2SW	SH515NW	Installation of Pacific Forest Research Center Mark II aerial ignition system. Issued 9/13/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig HArbor, WA 98335
206B; T.C. H2SW	SH830NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705
206B; T.C. H2SW	SH1030CE	Installation of battery temperature monitor and over temperature warning system. Issued May 1974.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Wichita, KS 67202

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206B Jet Ranger II and III; T.C. H2SW	SH1503CE	Installation of Collins APS-841H automatic flight control system. Amended 4/10/80.	CE	24250	Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
206B; T.C. H2SW	SH4076SW	Installation of public address system. Issued 1/18/80.	SW	11890	Associated Air Center 8201 Lemmon Avenue Dallas, TX 75220
206L; T.C. H2SW	SH586AL	Install Airglas Model L2700-206L skis. Issued 6/10/76.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
206L, 206L-1; T.C. H2SW	SH1541CE	Installation of Collins APS-841H helicopter automatic flight control system. Issued 4/21/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
206L, 206L-1; T.C. H2SW	SH4114SW	Installation of SFENA radio console 10713. Issued 4/28/80.	SW	11890	SFENA Corporation c/o Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220
206L, 206L-1; T.C. H2SW	SH4115SW	Installation of instrument panel kit, 10501. Issued 4/28/80.	SW	11890	SFENA Corporation c/o Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220
206L-1; T.C. H2SW	SH4099SW	SFENA 3-axis mini-stab system for single pilot IFR operation. Issued 5/9/80.	SW	11890	SFENA Corporation c/o Associated Air Center P.O. Box 20718 Dallas, TX 75220
212; T.C. H4SW	SH17NW	Installation of Chadwick Electronic weighing system C-47. Issued 2/16/73.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
212; T.C. H4SW	SH171WE	Installation of A500 battery temperature monitor systems. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
212; T.C. H4SW	SH205WE	Installation of tail/rotor flood lights on upper surface of the horizontal stabilizers. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
212; T.C. H4SW	SH256WE	Installation of emergency exit window. Reissued 1/11/80.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
212; T.C. H4SW	SH261WE	Installation of rappelling kit support structures. Issued 6/9/80.	WE	80912	U.S. Department of Agriculture Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
212; T.C. H4SW	SH400NW	Installation of modified left hand door. Issued 1/20/77.	NW	33900	Evergreen Helicopters P.O. Box 358 McMinnville, OR 97128
212; T.C. H4SW	SH449AL	Installation of Airglas model L8500A skis. Amended 6/10/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
212; T.C. H4SW	SH463NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
212; T.C. H4SW	SH467NW	Cargo release switch wired in series with spare switch on pilot's cyclic control grip. Issued 6/15/77.	NW	85330	Weyerhouser Company 28801 Airport Road Eugene, OR 97401
212; T.C. H4SW	SH942EA	Installation of Tramm BTI-600 battery temperature indicating system. Issued 12/26/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
212; T.C. H4SW	SH1281SW	Interior installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1284SW	Installation of Norton Company's radome and radar antenna brackets. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1286SW	Installation of Butler VAC/ADD area navigation system for VFR operation only. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
212; T.C. H4SW	SH1288SW	Installation of dual PC-17-400 Hertz static inverters. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn AVenue Burbank, CA 91505
212; T.C. H4SW	SH1289SW	Extension of power feeds to allow power distribution from the aft pedestal area. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1290SW	Installation of an extended instrument panel. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1333SW	Installation of weather radar equipment. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH2281SW	Environmental control unit. Issued 1/6/76.	SW	11890	Associated Air Center 7011 Lemmon Avenue Dallas, TX 75209
212; T.C. H4SW	SH2338SW	Modification for IFR type of operation. Issued 7/28/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220
212; T.C. H4SW	SH2466SW	AC inverter power system. Issued 5/24/77.	SW	11890	Associated Air Center, Inc. P.O. Box 20718 Love Field Dallas, TX 75220
212; T.C. H4SW	SH2746SW	Modification of four emergency exit panels. Issued 4/4/78.	SW	64300	Petroleum Helicopters, Inc. P.O. Box T Lafayette, LA 70502
212; T.C. H4SW	SH2892SW	Install 150 or 180 gallon auxiliary fuel tanks; standard utility seats modified; optional seats. Issued 12/21/78.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75222
214; T.C. H6SW	SH464NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems Inter'l. 619 Riverside Drive Seattle, WA 98108
214B, 214B-1; T.C. H6SW	SH2298SW	Interior arrangement and installation. Issued 3/2/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
7FC, 11AC; T.C. 759	SA1008WE	Installation of Poly-Fiber covering material (complete aircraft). Amended 8/21/79.	WE	75250	Stits Aircraft Coatings P.O. Box 3084 43rd South Fort Drive Riverside, CA 92519
7GC, 7GCB, 7GCBC, 7HC; T.C. 759	SA18CE	Installation of Pee-Kay Model 1800 or B1800 (TSO-C27-2) seaplane floats. Amended 8/17/73.	EA	29998	Pee-Kay Devore Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7GC, KC, GCB, GCA, GCAA, GCBC: T.C. 759	SA216AL	Install L-2500A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCA (landplane), 7GCB, 7GCBC (land and float plane); T.C. A-759	SA283AL	Installation of Hartzell HC 82XL-1, -2, or -6 propeller hub with 7636D-4 blades or HC-C2YL-1B hub with 7663-4 blades and appropriate Woodward governor. Amended 7/22/69.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
7GCA, 7GCB, 7KC, 7GCBA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
7GCAA, 7GCBC, 7KCAB; T.C. A-759	SA33GL	Installation of EDO Model 88A-1650 floats. Reissued 6/22/76.	GL	03480	Air-Ads-of-Dayton with Edo-Aire Seaplane Division 3800 Clearview Drive Dayton, OH 45439
7GCAA, 7GCBC, 7ECAB; T.C. A-759	SA1536WE	Installation of larger rudder. Reissued 6/5/69.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7GCAA, 7GCBC, 7KCAB, 14-19-3A, 17-30; T.C. 1A3, A-759	SA71GL	Install P/N BA8110 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities, Inc. 9600 West 52nd Street Kenosha, WI 53140
7GCB; T.C. 759	SA323AL	Installation of McCauley 1A175-GM8042 propeller.	AL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645
7GCBC; T.C. 759	SA266AL	Installation of L-2500 skis. Amended 6/21/68.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCBC; T.C. 759	SA520AL	Installation of leading edge cuff stall fences, tip fences. Amended 2/2/77.	AL	27250	Crosswinds, Inc. 2301-1/2 Merrill Field Drive Anchorage, AK 99507
7KCAB; T.C. A-759	SA25RM	Installation of Christen Model 801 Inverted Oil System. Issued 3/28/74.	RM	49369	Lloyd Land Star Route, Box 65A Hudson, CO 80642
8GCBC; T.C. A21CE	SA72GL	Installation of wheel replacement ski models M2000 and M3000. Issued 3/12/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
8GCBC; T.C. A21CE	SA530AL	Installation of Hartzell HC-C2YK-1BF/F7666A-0. Issued 10/21/74.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
8GCBC; T.C. A21CE	SA666AL	Installation of Fluidyne C3000A skis. Issued 7/17/79.	AL	35800	Flirite, Inc. P.O. Box 297 Kodiak, AK 99615
8GCBC; T.C. A21CE	SA741NW	Installation of EDO-AIRE Model 689-2130 seaplane floats. Amended 6/4/80.	EA	32625	EDO-AIRE Seaplane Division Republic Airport East Farmingdale, NY 11735
8GCBC; T.C. A21CE	SA742NW	Installation of Hartzell HC-C2YR-1BF/F7666A-O propeller on a Lycoming O-360-C1E engine. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA743NW	Installation of Bellanca 72 gallon fuel system. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA1001EA	Installation of Pee-Kay Model 2300 (TSO-C27-2) seaplane floats. Issued 4/11/75.	EA	29998	Pee-Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
11AC; T.C. 761	SA4-99	Fiberglass cloth with resin over muslin applied.	WE	46783	R.W. Johnson Route 2, Box 571-B Ojai, CA 93023

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
11AC; T.C. 761	SA4-789	McCauley 1B90-CM/7045 propeller on Continental A-65-8 engine.	NW	68536	Paul H. Robinson 604 S. 136 Street Seattle, WA 98101
11AC; T.C. 761	SA345CE	Remove right door.	CE	35650	Flanagan Aircraft 20224 R.D. Mize Road Independence, MO 64050
11AC, S11AC, 11BC; T.C. 761	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
11AC, S11AC, 11BC; T.C. 761	SA4-1276	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
11AC, S11AC, 11BC, S11BC, 11CC, S11CC; T.C. A-761, A-796	SA57RM	Installation of Lycoming O-235-C1 or C-235-C2C engine. Issued 6/19/75.	RM	84393	Colman I. Wagner 801 1st Street East Clark, SD 57225
11AC, 11BC; T.C. 761	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 8677 North Street Los Angeles, CA 90063
11AC, 11BC, 11CC; T.C. 761, 796	SA217AL	Install L-1650A or L-2000A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
11AC, 11BC, 11CC; T.C. 761, 796	SA535AL	Installation of wing auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
11BC; T.C. 761	SA3-7	Installation of Pee-Kay Model 1500 floats with Edo struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC; T.C. 796	SA3-115	Model 3000 main ski and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
11CC; T.C. 796	SA3-670	Install Pee-Kay Model 1500 floats with Edo struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC; T.C. 796	SA69SO	Continental C85-12F Series engine less starter and generator.	SO	09720	C.W. Lasner 14100 NW. 62 Court Miami, FL 33012
11CC; T.C. 796	SA262CE	Manufacture parts and install 12-30A electrical system. (Requires alteration of engine per STC SE3CE.)	GL	67160	Kenneth L. Pepke 7788 Auburn Detroit, MI 48233
11CC, S11CC; T.C. 796	SA4-1270	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13, 14-19, 14-19-2, -19-3, -19-3A, 17-30, -31, -31A, -31TC, -31ATC; T.C. 1A3, 773	SA846SW	Wing root fairings. Reissued 11/27/78.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
14-19 Series; T.C. 1A3	SA1-551	Fuselage and fin covered with metal skin.	EA	72100	Skycraft Design, Inc. Mercer County Airport West Trenton, NJ 08628
14-19 Series; T.C. 1A3	SA4-867	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series; T.C. 1A3	SA4-883	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series; T.C. 1A3	SA4-909	Autopilot. Reissued October 1973.	WE	17492	Brittain Industries, Inc. 12027 S. Prairie Avenue Hawthorne, CA 90250
14-19 Series; T.C. 1A3	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
14-19 Series; T.C. 1A3	SA4-1127	Ceconite 101 covering of entire aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-19 Series; T.C. 1A3	SA4-1269	Full flow oil filter 30409A with element 1AC235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
14-19 Series; T.C. 1A3	SA4-1283	Ceconite 103 covering of plywood portions of the aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3429 Van Nuys, CA 91408
14-19 Series; T.C. 1A3	SA486SW	Automatic pilot AK143, AK143E and AK143E-3.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
14-19 Series; T.C. 1A3	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court, P.O. Box 175B San Leandro, CA 94577
14-19 Series; T.C. 1A3	SA645SW	AK125 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19, 14-19-2; T.C. 1A3	SA294GL	Install Cleveland wheel 40-97A and brake 30-63A. Issued 3/22/79.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19, -A-2, -3, -3A, 17-30, -31, -31TC; T.C. 1A3	SA666NW	Installation of TEflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
14-19-2; T.C. 1A3	SA203GL	Installation of McCauley 2A34C66-N/S-90AT-12 propeller manufacturer's installation with instruction. Issued 12/8/77.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-2; T.C. 1A3	SA798WE	Installation of George W. Adams DGA-2000 or Bodell BMI-2000 Wheel Assemblies in lieu of Firestone DFA180 wheel assembly. Firestone CFA252 brakes or Bodell BMI252 brakes required with this installation. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
14-19-3, 14-19-3A; T.C. 1A3	SA292GL	Install Cleveland wheel 40-75E and brake 30-52M on main gear. Issued 1/31/79.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-3, 14-19-3A, 17-30, -30A, -31, -31A, -31TC, -31ATC; T.C. 1A3, A18CE	SA847SW	Main landing wheel doors. Reissued 11/27/78.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
14-19-3, 14-19-3A; T.C. 1A3	SA874SW	Hartzell/Wren Beta System reverse pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
14-19-3A; T.C. 1A3	SA108GL	Installation of Continental IO-520D engine and McCauley D2A34C58/90AT-10 propeller. Issued 2/11/76.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-3A; T.C. 1A3	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STC - SA645SW.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19-3A, 17-30; T.C. 1A3	SA981SW	Manual Electric Trim AK276.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19-3A, 17-30, -31, -31TC; T.C. 1A3	SA1196SW	Mitchell automatic flight system model AK309 consisting of Century I, automatic aileron stabilizer with omni tracker. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30; T.C. 1A3	SA845SW	Nose gear doors. Reissued 1/24/79.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
17-30; T.C. 1A3	SA693SW	Mitchell automatic flight system AK233 consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio coupler, glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30; T.C. 1A3	SA3780WE	Installation of Continental IO-520-K engine, Hartzell HC-C3YF-1B/8468A-8R propellers, and associated installation components. Issued 11/29/78.	WE	08347	Air Repair P.O. Box 813 Santa Paula, CA 93060

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
17-30, -30A, -31, -31A; -31ATC; T.C. A18CE	SA903SO	Reposition of fuel pump. Issued 7/30/76.	SO	86295	Keith Wilson Aircraft, Inc. 2787 North Second Street Memphis, TN 38127
17-30A; T.C. A18CE	SA1344CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 6103
17-30A; T.C. A18CE	SA3688WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
17-30A, -31A; T.C. A18CE	SA1118SW	Manual electric trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, -31, -31ATC; T.C. A18CE	SA1195SW	Mitchell automatic flight system AS309 consisting of Century I, automatic aileron stabilizer with omni tracker. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA574SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric pitch trim and optional flight director indicator DH-841. Issued 2/1/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1235SW	Automatic flight system AK215, consisting of Century II autopilot with optional automatic aileron stabilizer and radio coupler. Issued 12/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1236SW	Automatic flight system AK233, consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio, and glide couplers. Issued 12/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1257CE	Installation of the King KFC-200 2-axis, flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or stand alone electric trim. Amended 10/6/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1811SW	Mitchell automatic flight system AK466 and AK466FD consisting of Century IV autopilot and Century IV flight director with electronic command/automatic pitch trim. Issued 2/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1812SW	Mitchell automatic flight system AK465 consisting of Century III autopilot with optional electronic command/automatic pitch trim, radio coupler, and glide slope coupler. Issued 2/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3059SW-D	Mitchell AK466 and AK466FD consisting of Century IV autopilot and Century IV flight director with electronic command/automatic pitch trim. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3060SW-D	Mitchell AK465 consisting of Century III autopilot with optional electronic command/automatic pitch trim, optional radio coupler, and glide slope coupler. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3061SW-D	Mitchell AK495 consisting of Century I autopilot with optional omni tracker. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3071SW-D	Mitchell automatic flight system AK546 consisting of Century IIB autopilot with optional radio coupler. Issued 9/5/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-100, -200; 707-300; 720; 727, 727C, -200; 737; T.C. 4A21, 4A26, 4A28, A3WE, 4A27	SA2534SW-D	Replacement of Switch assembly International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707-100, -200; 707-300; 720; 727, 727C, 727-200; 737; T.C. 4A21, 4A26, 4A28, A3WE, A16WE	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, and EL-104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707-100, -100B, -200, -300, -400, 720, 720B; T.C. 4A21, 4A26, 4A28	SA2579WE	Modify airplanes by the installation of wing tip mounted emblem light. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, MN 87109
707-100/100B, -200, -300/300B/300C, 720/720B; T.C. 4A21, 4A26, 4A28	SA2605WE	Installation of turbine thrust reverser linkage. Amended 8/2/73.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
707-100B; T.C. 4A21	SA984CE-D	Increase maximum zero fuel weight. Issued 9/22/76.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-100B; T.C. 4A21	SA4140SW	Steward-Davis Model 81000 auxiliary power system. Issued 7/2/80.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
707-100B, -300B, 720; T.C. 4A21, 4A26, 4A28	SA2635WE	Installation of forward fan thrust reverser bearings. Issued 1/11/73.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85282
707-121, -139, -321, -321B, -331, -321C, 720-023B, -030B; T.C. 4A21, 4A28	SA311EA	Installation of Aerotherm Corp. Model 1003 stretcher. Reissued 12/5/72.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-121, -139, -321, -321B, -321C, -331, 720-023B, -030B, 737-100, -200; T.C. 4A21, 4A26, 4A28, A16WE	SA677CE	Installation of Crimsco cargo container, P/N 600301, in passenger compartment. Amended December 1974.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
707-121B Series; T.C. 4A21	SA531EA	Installation of EMCO autopilot monitoring system Model No. APMS-E. Amended 9/27/68.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707-121B, -123B, -139B, -227, -321, -321B, -321C, -323C, -327C, -331, -123, -155C, -295; 720-023B, -027, -030B, -048, -062, 727-21C, -21, -27, -27C, -81, -90C, -95; T.C. 4A28, 4A21, 4A26, A3WE, 4A25	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 12/10/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-121B, -139B; T.C. 4A21	ST655SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in forward passenger compartment.	SO	67030	Mace Unit of REF Dynamics, UOP 5846 Victor Street Jacksonville, FL 32207
707-121B, -139B; 707-321, -321B, -321C, -331; 720-023B, -030B; 727-21, -21C; 747-121; T.C. 4A21, 4A26, 4A28, A3WE, A20WE	ST706SO-D	Installation of Skydrol 500C hydraulic fluid. Reissued 9/7/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-121B, -139B; 707-321, -321B, -321C, -331; 720-023B, -030B; T.C. 4A21, 4A26, 4A28	ST708SO-D	Installation of an REF Dynamics carry-on baggage compartment. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-121B, -139B; 707-321, -321B, -321C; 707-331; 720-023B, -030B; T.C. 4A21, 4A26, 4A28	ST711SO-D	Installation of door mounted evacuation slide illumination lights. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-123B; T.C. 4A21	SA405EA-D	Convert all Boeing 707-123B aircraft to winter configuration. Amended 10/10/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-123B, 707-323B, 707-323C; T.C. 4A21, 4A26	SA401EA-D	Installation of door mounted evacuation slides on forward and aft entry doors and forward and aft galley service doors. Amended 9/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 707-323B and 707-323C; T.C. 4A21, 4A26	SA415EA-D	Installation of Bell & Howell projection system in 707-123B, install Bell & Howell projection system in 707-323C, install Bell & Howell projection system in 707-323B. Amended 4/21/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 720B-023; T.C. 4A21, 4A28	SA551EA-D	Installation of autopilot go-around unit. Amended 8/11/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, -323C, -323B, 720-023B, 727-23, -35, -95, -123, -223; T.C. A3WE, 4A28, 4A21	SA554EA-D	Install underseat luggage retention device.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, -138, -323CC, -023B; T.C. 4A21, 4A26, 4A28	SA555EA-D	To comply with FAR 25.812(e), a lever lock switch will be installed at a point accessible to the forward flight attendant seat. Amended 4/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B; T.C. 4A21	SA983CE-D	Cargo door and interior installation non-convertible air freighter. Issued 5/24/76.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-123B; T.C. 4A21	SA4053WE	Installation of an auxiliary fuel tank system consiting of two identical tank assemblies located in the forward cargo compartment and one located in the aft cargo compartment. Issued 10/30/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
707-123B, -138B; T.C. 4A21	SA3257WE	Installation of AiResearch GTCP 85-98CK auxiliary power unit in forward cargo compartment. Amended 8/18/78.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-123B, 707-138B; T.C. 4A21	SA3441WE	Installation of airstairs. Amended 3/15/79.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
707-124 Series; T.C. 4A21	SA582CE	Relocation of Lockheed Aircraft Service Model 109CR, flight recorder to aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA584CE	Autopilot modification to incorporate variable intercept feature.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA585CE	Installation of Fairchild Cockpit Voice Recorder System.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA586CE	Installation of Fenwall fuel vent surge tank protection system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA627CE	Installation of (1) dual radio altimeter provisions (2) single Bendix ALA-51 radio altimeter transmitter-receiver with dual indicators.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131; T.C. 4A21	SA439CE	Installation of logo lights on horizontal stabilizer. Amended 11/25/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131; T.C. 4A21	SA556CE	Installation of auto-thrust provisions. Amended 3/19/69.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-124/-131/-131B; 707-331/-331B/-331C/ -373; T.C. 4A21, 4A26	SA577CE	Replace Bendix type 15866, 15897 and 19903 vertical gyros with Bendix type 19911 or 19912 vertical gyros.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, 131, -131B- -331, -331B, -373C, -338C; T.C. 4A21, 4A26	SA680CE	Modify the A.C. essential bus power source circuitry to provide automatic transfer. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131, -131B, -331, -331B, -331C; T.C. 4A21, 4A26	SA682CE	Install Litton Model E-30 microwave oven.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-131; T.C. 4A21	SA555CE	Installation of a single SCAT system. Amended 3/19/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131; T.C. 4A21	SA862CE	Addition of large cargo door in left hand side of fuselage. Issued August 1972.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-131, -131B; T.C. 4A21	SA607CE	Installation of provisions for dual radio altimeters and single Bendix Model ALA-51A equipment. Amended 4/29/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131, -131B, 331, 331B, 331C; T.C. 4A21, 4A26	SA3-708	Install motion picture projector and screen. Amended 12/27/67.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131, -131B, 720B; T.C. 4A21, 4A28	SA432CE	Installation of Fenwall fuel vent surge tank protection system. Amended 8/22/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA197CE	Installation of a single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA298CE	Installation of a single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA488CE	Relocation of LAS Model 109CR flight recorder.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA1052CE	Replacement of existing fire detection system with a Kidde dual loop fire detection system. Issued September 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA1520CE	Installation of a Growth Industries dual cavity oven. Issued 10/31/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-131B, -331B, 331, 331C, 373, 338C; T.C. 4A21, 4A26	SA519CE	Installation of logo lights in horizontal stabilizer. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131/-131B/-331/ -331B/-331C/-373C, 338; T.C. 4A21, 4A27	SA827CE	Install Butler National Corp. flight recorder/communications interface unit. Amended April 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B, -331B, -331C; T.C. 4A26	SA1478CE	Installation of pitot heater failure indication system. Issued 3/22/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-138B; T.C. 4A21	SA797EA	Installation of inflight motion picture system. Reissued 2/26/73.	EA	44000	Inflight Motion Pictures, Inc. 175-20 148th Avenue Jamaica, NY 11434
707-138B; T.C. 4A21	SA1132EA	Installation of two Solar Model T-62T-40C2 APU's for ground use only. Amended 11/8/79.	EA	63275	PATS, Inc. 7190-8 Oakland MIlls Road Columbia, MD 21046
707-138B; T.C. 4A21	SA1136EA	Installation of an onboard passenger loading stairs. Amended 12/14/78.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
707-138B; T.C. 4A21	SA1403WE	Interior arrangements.	NW	74920	Standard Airways, Inc. Tower Building Seventh and Olive Streets Seattle, WA 98101
707-138B; T.C. 4A21	SA3320WE	Installation of radio altimeter system No. 1. Issued 1/17/77.	WE	13970	Aviation Service & Support Corp. 4150 Donald Douglas Drive Long Beach, CA 90801
707-139B Series; T.C. 4A21	SA687EA	Installation of Data Link System.	EA	62300	Pan American World Airways, Inc. JFK International Airport Hangar 17 - Room 2011 Jamaica, NY 11430
707-139B, -121B, 720-023B, -030B; T.C. 4A21, 4A28	SA1937WE	Installation of under-seat baggage restraint system. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-153B; T.C. 4A21	SA81NW	Minor modifications to pilot's instrument panel and relocation of autopilot accelerometer and rate gyros for improved performance. Amended 12/7/73.	SW	24252	Collins Radio Company Avionics Systems Center P.O. Box 98 Addison, TX 75001
707-153B; T.C. 4A21	SA856EA	Installation of a compartment bulkhead at fuselage station 978. Issued 12/22/70.	EA	80910	Department of the Air Force Hq. 89th Military Airlift Wing (SM) MAC Andrews Air Force Base Washington, D.C. 20331
707-153B; T.C. 4A21	SA1700WE	Installation of Dual Litton LTN-51 Inertial Navigation Systems. Amended 10/21/68.	WE	51500	Litton Systems, Inc. Guidance & Control Systems Div. 5500 Canoga Avenue Woodland Hills, CA 91364
707-153B, -353B; T.C. 4A21, 4A26	SA350EA	Passenger Berth Installations. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Company P.O. Box 33 Ontario, CA 91761
707-153B, -353B; T.C. 4A21, 4A26	SA648EA	Modification of Collins FD109G Flight Director.	EA	80910	Department of the Air Force Hq. 89th Military Wing (SM) MAC Andrews Air Force Base Washington, D.C. 20331
707-153B, -353B; T.C. 4A21, 4A26	SA858EA	Modification of rigid high pressure starter air lines on numbers 2 and 3 engines. Issued 12/29/70.	EA	80910	Department of the Air Force Hq. 89th Military Airlift Wing (SM) MAC Andrews Air Force Base Washington, D.C. 20331
707-200; T.C. 4A21	SA1155SO	Installation of cargo floor, cargo restraint bulkhead, landing gear position indicator, and smoke detection system (Class "E" cargo compartment). Issued 6/30/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
707-227, 720-027; T.C. 4A21, 4A28	SA1138WE	Installation of fire warning monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Canoga Park, CA 91304
707-300; T.C. 4A26	SA208NW	Installation of Fairchild Stan (R) weight and balance system. Issued 10/21/75.	NW	08350	Air Repair, Inc. 811 West Perimeter Road Renton, WA 98055
707-300 Series; T.C. 4A26	SA3599WE	Installation of single or dual Litton LTN-201 Omega navigation as a means to update INS or doppler in the NAT MNPS airspace. Amended 5/8/78.	WE	51500	Litton Aero Products Division 6700 Eaton Avenue Canoga Park, CA 91303
707-300, -300B, -300C, -400; T.C. 4A26	SA171GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	GL	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
707-300, -300B, -300C, -400 Series; T.C. 4A26	ST661SO	Installation of dual band "C/X" type weather radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Company P.O. Box 350 Akron, OH 44309
707-300, -300B, -300C, -400 Series; T.C. 4A26	SA3167WE	Installation of dual Litton LTN-51 inertial navigation systems. Issued 4/5/76.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
707-300, -300B, -300C, -400, 338C; T.C. 4A26	SA726CE	Installation of Kollsman altitude alerting system. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-300, -300B, -300C, 707-400 Series; T.C. 4A26	SA3486WE	Installation of dual Litton LTN-51, or dual Litton LTN-72, or one Litton LTN-72 inertial navigation systems. Issued 11/3/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91364
707-300, -300B, -300C, -400; T.C. 4A26	SA3830WE	Installation of dual Delco C-IVA inertial navigation system. Amended 10/17/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
707-300, -300B, -300C; T.C. 4A26	SA4097WE	Installation of forward entrance airstair. Issued 2/5/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanover Street Van Nuys, CA 91406
707-300, -400; T.C. 4A26	SA3331WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-300B, -300C; T.C. 4A26	SA817NW	Modification of cabin passenger interior, and forward storage units. Issued 8/8/79.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
707-300B, -300C; T.C. 4A26	SA2594WE	Modify 707-300B and -300C series airplanes by the installation of wing tip mounted emblem light. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
707-300B, -300C; T.C. 4A26	SA2610WE	Installation of Bell & Howell movie projection system Nos. 478441 and 478440. Issued 1/11/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
707-300C, 727C; T.C. 4A26, A3WE	SA647SO	Installation of AIF partition class divider P/Ns 402-1, 402-2, 402-3, 402-4, and header assembly P/Ns 403-1 and 404-1. Amended 7/16/68.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33142
707-300C Series; T.C. 4A26	ST939SO	Installation of livestock pen. Issued 6/10/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-300C Series; T.C. 4A26	SA1443WE	Installation of tray carrier.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-320; T.C. 4A26	SA2374WE	Installation of an air filter to the cabin pressure limit control outflow safety valve, P/N 103430-3. Issued 6/24/71.	WE	07505	AiResearch Manufacturing Company 2525 W. 190th Street Torrance, CA 90509
707-320C; T.C. 4A26	SA251NW	Installation of cargo system. Issued 1/16/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
707-320C Series; T.C. 4A26	SA3539WE	Installation of single, palletized Litton LTN-51 or LTN-72 inertial navigation system. Issued 12/20/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
707-321; T.C. 4A26	ST710SO-D	Relocation of "B" galley approximately 10" forward of present location. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321; T.C. 4A26	SA778CE	Addition of large cargo door in left hand side of fuselage. Issued June 1971.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA852CE-D	Reduction of empty weight by removal of all passenger interior equipment and installation of fire resistant lining. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA1555WE	Installation of fire warning electrical monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Canoga Park, CA 91304
707-321, -321B; T.C. 4A26	SA344EA	Install inertial navigation system. Amended 4/1/66.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321, -321B, -321C, -331, -386C; T.C. 4A26	ST652SO-D	Installation of P&W JT8D engine and associated structural and fairing pod under L.H. wing between No. 2 engine and fuselage. Reissued 9/7/78.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
707-321, -321B, -331; T.C. 4A26	ST656SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in the forward passenger compartment. Amended 11/6/68.	SO	67030	Mace Unit of REF Dynamics, UOP 4856 Victor Street Jacksonville, FL 32207
707-321, -321B, -321C, -331; T.C. 4A26	ST712SO-D	Modification and installation of a Hardman Model 6747 seat. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321, -324C; T.C. 4A26	SA2238WE	Installation of Brownline Cargo net assembly #41412 used in conjunction with Brownline pallet assemblies #40160 and 40144. Amended 5/16/75.	WE	17740	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-321, -331, 720-040B; T.C. 4A26, 4A28	SA1-593	See Document No. Report No. 3078, dated January 30, 1969, concerning pallet assembly IR-3000 Rev. B. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-321, -400; T.C. 4A26	ST914SO	Installation of cargo floor. Amended 1/19/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-321B; T.C. 4A26	SA611EA	Installation of dual A.C. electronics navigation systems on R/N N435PA, S/N 5034. Amended 5/21/68.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B; T.C. 4A26	ST702SO-D	Installation of Bendix FINDS. Limited to aircraft N421PA S/N 19266. Issued 11/15/68.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST707SO-D	Modified aircraft to incorporate Emerson engine performance monitoring system, aircraft S/N 19363, N428PA. Issued 10/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST713SO-D	Installation of a coat closet between fuselage stations 373 and 414 L.H. side. Reissued 9/12/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B; T.C. 4A26	SA1067EA	Installation of stowage cabinets Issued 12/16/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
707-321B; T.C. 4A26	SA3549WE	Installation of Garrett GTCP85-98CK auxiliary power unit in forward baggage compartment. Issued 1/27/78.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-321B, 321C T.C. 4A26	ST709SO-D	Installation of flight spares container in right hand main landing gear wheel well on fuselage station 960 bulkhead. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	SA700EA	Switches are installed on outboard thrust levers to disengage autothrottle system.	EA	62300	Pan American World Airways, Inc. Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	ST704SO-D	Installation of Bell & Howell forward projection movie system. Reissued 9/7/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321-B, -321C; T.C. 4A26	SA1076EA-D	Removal of Loran navigation system and installation of dual Omega navigation systems for updating doppler. Amended 8/13/79.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321C; T.C. 4A26	SA541NW	Installation of quick change interior. Issued 1/18/78.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98021
707-321C; T.C. 4A26	SA1134WE	Palletized cargo system installation 65-42629 or 65-43629 with Brownline pallet 22630-51, 26100-51 or -52 and Brownline net assy 23225-51, 23226-51, or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1143WE	Installation of Boeing palletized cargo system. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1293WE	Palletized cargo system installation 65-42629 with Brownline pallet 22630-51 and net assy 23225-51 or 23226-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1597WE	Installation of Heath Tecna Corporation pallet AC-10065 and Brownline Corporation Net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C; T.C. 4A26	SA2125WE	Installation of Ancra Cargo Net Assembly 40234-10 used in conjunction with either Brownline pallet assembly 22630-51 or Heath Tecna pallet assembly AC 10065-1.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 90245

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-321C; T.C. 4A26	SA2221WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp Net Assembly 40234-10 and net assemblies approved to NAS 3610-2A1N and NAS 3610-2A3N. Issued 8/19/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
707-321C; T.C. 4A26	SA3005WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-321C, 727-21C; T.C. 4A26, A3WE	SA736EA	Installation of L. Marino forward cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-321C, 727-21C; T.C. 4A26, A3WE	SA1859WE	Installation of net assembly AC-10292-1 used in conjunction with pallet assembly AC-10065-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C, 727-21C; T.C. 4A26, A3WE	SA2045WE	Modification by installation of pallet assembly 40160 used in conjunction with net assemblies 23225-51, 23226-51, 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; 727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA849EA	Goodyear Aerospace Corporation cargo pallet (1.5 Fwd.) P/N 634A303-001-101 is eligible to be used only in combination(s) as shown in the following tables:	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315

BOEING COMPANY			CARGO NET		
AIRPLANE MODEL	CARGO RESTRAINT SYSTEM	WEIGHT & BALANCE CONTROL MANUAL (b)	MANUFACTURER & PART NO.		TIE-DOWN CONFIGURATION
707-321C (a)	65-42629 65-43629	D6-14083.6	Brownline	40510-101 22758-51 23225-51	88" x 125"
			Marino	LM1500-100	88" x 125"
			Brownline (Chg. G)	21970-51	88" x 108"
727-21C (a)	65-49102	D6-21000.17C	Brownline	40510-101 22758-51 23225-51 23226-51	88" x 125"
			Marino	LM1500-100	88" x 125"
			Brownline (Chg. G)	21970-51	88" x 108"
747-121	65B-60060 Lower Lobe Compartment Aft Hold ONLY	D6-13700	Brownline	22758-51	88" x 125"

(a) Barrier Net Installation per Boeing Drawing 65-34700-1 required for these model aircraft with this installation.

(b) The applicable Boeing Weight and Balance Control Manual must be used to obtain permissible compartment load, under conditions described therein, not to exceed the pallet-net combination(s) capacity of 13,300 lb. for the 88" x 125" tie down configuration or 8000 lb. for the 88" x 108" tie down configuration.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-321C;727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA1902WE	Installation of Irvin cargo pallet assembly 125014 used in conjunction with net assembly 22758-51 (Brownline), net assembly 40234010 (ANCRA), and net assembly LMI-500-100 (Marino). Amended 8/25/70.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
707-321C, 727-21C; T.C. 4A26, A3WE	SA2103WE	Installation of Net Assembly 40510-101 used in conjunction with Brownline Pallet Assemblies 40160-101 thru -100, 22630-51 and Heath Pallet AC-10065-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-323, 707-385C; 707-323B; T.C. 4A26	SA517EA-D	Installation of dual Litton LTN-51 inertial navigation systems. Install No. 2 ship's battery (24 volts, 36 AH) to provide standby DC power for No. 2 inertial navigation system. Installation perforated filler panels fore and aft of both control/display units. Amended 1/22/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA556EA-D	Convert interior passenger arrangement to winter configuration of 4 first class lounge, 32 first class seats and 101 tourist class seats. Amended	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA561EA-D	Installation of automatic throttle/speed control system. Amended 3/2/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA562EA-D	Installation of dual aileron and elevator surface servos to operate in a single servo configuration with the PB20 autopilot system. Amended 3/31/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA564EA-D	Modify the interior arrangement of the 707-323B aircraft from its present configuration to 32 F/C plus 102 T/C passenger. Install additional meal stowage. Issued 5/18/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA508EA-D	Install a single inertial navigation system (LTN-51E). Amended 1/5/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74116
707-323C; T.C. 4A26	SA525EA-D	Convert interior passenger arrangement to the summer configuration of four first class lounge, 26 first class, and 113 tourist class seats. Amended 4/15/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA559EA-D	Interior arrangement and configuration.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA565EA-D	Install emergency evacuation slide lights for station 990. Issued 6/17/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA1560WE	Installation of Aeronca cargo containers on Boeing 707-323C.	WE	02398	Aeronca, Inc. Aerocal Division 24751 S. Crenshaw Boulevard Torrance, CA 90505
707-323C; T.C. 4A26	SA1720WE	Installation of Heath Tecna structural igloo assembly AC-0123. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2008WE	Installation of structural cargo container AC-10260-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2401WE	Installation of Transequip structural igloo assembly P/N 245084 in conjunction with loading systems 65-42625, 65-42630, and 64-34899. Issued 8/26/71.	WE	79000	Transequip, Inc. 5438 W. 104th Street Los Angeles, CA 90045
707-323C; T.C. 4A26	SA2453WE	Installation of Transequip structural containers in position I13 (container 235111) and position I14 (container 235112). Amended 10/30/79.	WE	79000	Transequip, Inc. 5438 West 104th Street Los Angeles, CA 90045
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2022WE	Installation of pallet assembly 40122-101, -102, -103, -104, and -105 used in conjunction with net assemblies 22178-51, 23652-51, 22361-51c, 22780-51, 22780-52, 22656-51, 22656-52, and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2174WE	Installation of pallet assembly 40550-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22362-51 or AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -331C, 373C, 385C; 727-31C, -180C; T.C. 4A26, A3WE	SA1924WE	Installation of Irvin cargo pallet assembly 125001-501, -503, -505, -507 used in conjunction with net assembly 10-60934-1 (Boeing).	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
707-323C, -331C, -373C, 727-1A7C, -31C, -180C; T.C. 4A26, A3WE	SA2098WE	Installation of structural cargo container 40619-101, -103. Amended 5/16/75.	WE	17740	Brooks & Perkins 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA945WE	Installation of autopilot go-around unit. Amended 8/1/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C and 707-385C; T.C. 4A26	SA1524WE	Brownline Structural Containers 23885-51 may be used as optional cargo equipment either in place of or with cargo net assemblies. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA1939WE	Modify by installation of structural cargo container 24385-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA2234WE	Installation of Brownline Division structural container No. 41342-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -385C; 727-22C; T.C. 4A26	SA2278WE	Installation of Brownline cargo container model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division Torrance, CA 90505
707-326C; T.C. 4A26	ST701SO-D	Installation of alternate inertial navigation system control display unit. Limited to aircraft N870PA, S/N 20016; N871PA, S/N 20017; N872PA, S/N 20018. Amended 6/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-327C; T.C. 4A26	SA739EA	Installation of Inflight Motion Picture System. Reissued 10/24/73.	EA	11434	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-327C, -330C, -338C, -351C, 727-25C, -27C, -30C, -51C, -62C; T.C. 4A26, A3WE	SA2026WE	Installation of pallet assembly 40134-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22364-51, 23215-51, 23618-51 or 23783-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-327C; T.C. 4A21	SA2748WE	Installation of weight and balance computer system. Issued 8/15/73.	WE	52010	Lockheed Aircraft Service Company Ontario International Airport P.O. Box 33 Ontario, CA 91764
707-330C, 727-30C; T.C. A3WE	SA1917WE	The type design change consists of installation of pallet assembly 24076-51 in conjunction with net assembly 22361-51, 22364-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-331; T.C. 4A26	SA428CE	Installation of single seat system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA489CE	Relocation of Lockheed Air Service Model 109CF flight recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA635CE	Installation of dual radio altimeter system provisions and single radio altimeter equipment. Amended 2/20/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA854CE-D	60,000 lbs. main deck allowable loading. Issued 12/7/73.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-331; T.C. 4A26	SA1551WE	Installation of fire warning monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Conoga Park, CA 91304
707-331, 707-331 (ADV); T.C. 4A26	SA291CE	Installation of single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331, -331B, -331C, -373C, -338C; T.C. 4A26	SA465CE	Installation of Fenwall fuel vent surge tank. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64108
707-331 (Advanced), -331C, -338C, -373C; T.C. 4A26	SA899CE	To permit autopilot coupled approaches at 40 degrees flp setting below 500 feet. Issued August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331, -331B, -331B(ADV), -331C, -373C; T.C. 4A26	SA1327CE	Installation of Bendix ONS-25-5 Omega navigation system for updating primary self-contained navigation system. Issued March 1977.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195
707-331, -373C, 727-31A, -180C; T.C. 4A26, A3WE	SA2290WE	Installation of Ancra pallet net assembly P/N 40452-10 used in conjunction with Boeing 9g pallet assemblies (88" x 125") numbers 10-60935-1, 10-60935-11, 10-60935-17, 10-60935-21, 10-60935-27 and 10-60935-37. Amended 2/22/71.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 990245
707-331B, -331C; T.C. 4A26	SA1518CE	Installation of a Growth Industries dual cavity oven. Issued 10/18/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-331B, -331C, -338C, -373; T.C. 4A26	SA1039CE	Replacement of existing fire detection system with a Kidde dual loop fire detection system. Issued September 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C; T.C. 4A26	SA523CE	Installation of single SCAT system. Amended 7/31/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C; T.C. 4A26	SA524CE	Installation of auto throttle system. Amended 7/1/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, Mo 64153
707-331C; T.C. 4A26	SA658CE	Installation of dual radio altimeter provisions single equipment.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331 (Convertible), 707-338C; T.C. 4A26	SA234CE	Autopilot variable angle intercept installation. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C, -338C; T.C. 4A26	SA385CE	Installation of single SCAT system. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C, -338C; T.C. 4A26	SA386CE	Installation of auto thrust system. Amended 8/7/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C, -373C, -338C; T.C. 4A26	SA783CE	Installation of revised life raft and courier seat provisions. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA757EA	Goodyear Aerospace Corporation Cargo pallet with barrier net installation. Amended 3/17/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massilon Road Akron, OH 44315
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1866WE	Installation of Heathair AC-10113-1 net assembly in conjunction with pallet assemblies AC-10070-1 and AC-10347-1. Reissued 1/6/71.	NW	41625	Heath Techna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1963WE	Installation of pallet assembly 23250-52 used in conjunction with net assemblies 22178-51, 22780-52, 22656-51, 22656-52 and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2930 Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2172WE	Installation of Irvin Industries Net Assembly 120012-501 used in conjunction with Cargo Pallet 125001-501, -503, -505, -507. Issued 8/19/70.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2412WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, 727-31C; T.C. 4A26, A3WE	SA2088WE	Installation of cargo pallet assemblies 1950-90-501 and 1950-90-1001 used in conjunction with net assembly 22758-51 (Brownline).	WE	19890	Cargo Systems, Inc. 1040 West Hoover Street Orange, CA 92667
707-338C; T.C. 4A26	SA730EA	9G 10,000 lb. maximum capacity Pallet Cargo Net P/N LM 1505-1 eligible as replacement for approved Brownline Net P/N 22361-51 or Boeing Net 10-60934-1 in combination with 125" x 88" pallets Brownline P/N 23223-51 or Phenrock P/N 22861-51 or Bruggermann & Brand P/N 2102. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-338C; T.C. 4A26	SA1230CE-D	Passenger cabin contemporary interior installation. Issued 2/1/77.	CE	16878	The Boeing Company 3802 South Oliver Wichita, KS 67210
707-338C; T.C. 4A26	SA2352WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargo pallet assembly P/N 24076-51. Issued 6/14/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-345C; T.C. 4A26	SA675EA	Installation of L. Marino cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-345C; T.C. 4A26	SA725EA	Pallet P/N LM1600 (1.5G Fwd). Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-347, 720-047B; T.C. 4A26, 4A28	SA2557WE	Replacement of existing girt on Air Cruiser evacuation slide P/Ns 15D22093-7, 15D22093-11, 15D22094-10 and 15D22454-2 with Sargent Industries/PICO Division girt P/N 6176105-103. Issued 6/30/72.	WE	70130	Sargent Industries Pico Division 2045 Evans Avenue San Francisco, CA 94124
707-347C; T.C. 4A26	SA979CE-D	Passenger interior arrangement modified to 5 pallet cargo/passenger configuration, per Boeing Dwg. 65-88752 & 65-88753, cargo conversion capability, Class "B" compartment with passengers, Class "E" compartment with no passengers. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-347C; T.C. 4A26	SA2975WE	Installation of shroud assembly, P/N 0350740068, in Universal Oil Products galley P/N 10870, to Weber Aircraft Company beverage cart, P/N 818620-411. Issued 1/6/75.	WE	48550	H. Koch & Sons 5410 E. LaPalma Anaheim, CA 92807
707-347C; T.C. 4A26	SA3601WE	Installation of a single Collins INS 61B inertial navigation system. Issued 3/10/78.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C; T.C. 4A26	SA3792WE	Installation of Litton LTN-211 omega navigation system. Amended 8/31/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C, -351C, 720-047B; T.C. 4A26, 4A28	SA808EA	Installation of inflight motion picture system. Amended 3/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-349C; T.C. 4A26	SA1596WE	Installation of Brownline Pallet 23997-51 and Net 22758-51 combination. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-349C; T.C. 4A26	SA1624WE	Installation of Decca Omni trac, Decca Doppler and Decca Loran. Amended 5/10/68.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-349C; T.C. 4A26	SA1650WE	Modification of co-pilot's C-11 compass system to a C-11B system by addition of remote compensator.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
707-351B/C; T.C. 4A26	SA87GL	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
707-351B; T.C. 4A26	SA1168EA	Installation of dual solar T-62T-40C2 gas turbine auxiliary power units, for ground use only. Amended 11/8/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
707-351C, 727-51C, -25C; T.C. 4A26, A3WE	SA1888WE	Installation of pallet assembly AC-10359-1 used in conjunction with net assembly AC-10373-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-351C; T.C. 4A26	SA2526WE	Installation of Satco Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with assemblies conforming to NAS 3610-1A2N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
707-351C; T.C. 4A26	SA2528WE	Installation of Satco, Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with net assemblies conforming to NAS 3610-1A3N, 2A1N, 2A2N, 2A3N, 2A5N, and 2A6N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
707-351C; T.C. 4A26	SA2773WE	Installation of Tridair Industries 3G net assembly. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
707-351C, -384C; T.C. 4A26	SA855CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-353B; T.C. 4A26	SA83NW	Relocation of autopilot accelerometer and rate gyros. Issued 1/16/74.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
707-353B; T.C. 4A26	SA1596SW	Steel duct installation for APU according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
707-353B; T.C. 4A26	SA1927WE	Installation of dual Litton inertial navigation systems.	WE	51500	Litton Systems, Inc. 5500 Canoga Park Woodland Hills, CA 91364
707-355C; T.C. 4A26	ST654SO	Installation of liquor service galley.	SO	05356	Aircraft Interior FAbricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
707-359B; T.C. 4A26	SA2863WE	Passenger audio entertainment system installation. Issued 3/29/74.	WE	33223	Electronic Engineering Company of California 1441 E. Chestnut Avenue Santa Ana, CA 92701
707-365C, -372C, 727-172C; T.C. 4A26, A3WE	SA1795WE	Installation of Heath Tecna AC-015201 structural container. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
707-369C; T.C. 4A26	SA1234CE-D	Passenger cabin contemporary interior installation. Issued 1/24/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-372C and 707-365C; T.C. 4A26	SA1674WE	Installation of Heath Tecna Corporation AC-10160 pallet with AC-10069 net. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastic Division 19819 - 84th Avenue South Kent, WA 98031
707-373C; T.C. 4A26	SA426CE	Modify SCAT system circuit. Amended 9/9/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-373C; T.C. 4A26	SA714CE	Installation of dual Bendix ALA-51 radio altimeter provisions and equipment.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-373C; T.C. 4A26	SA2843WE	Modification by installation of horse stalls P/N 690069 on NAS 3610-2A4P pallet. Issued 3/15/74.	WE	87900	W.W. Industries, Inc. 12450 Inglewood Avenue Hawthorne, CA 90250

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
707-384B; T.C. 4A26	SA853CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-384B, 707-384C; T.C. 4A26	SA576CE	Installation of multi-channel audio entertainment system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-384B, 707-384C; T.C. 4A26	SA546CE	Installation of doppler autopilot tie-in Bendix DRA-12 doppler radar with CPA-24 computer to Bendix PB-20 autopilot. Amended 12/27/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-386C; T.C. 4A26	SA2808WE	Installation of dual Litton LTN-72 inertial navigation system. Issued 2/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Road Woodland Hills, CA 91364
707-387B; T.C. 4A26	SA1232CE-D	Installation of large cargo door in left hand side of forward fuselage. Issued 6/10/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-387B; T.C. 4A26	SA1233CE-D	Increase maximum zero fuel weight to 96,162 KG Issued 8/31/77.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-387B; T.C. 4A26	SA1236CE-D	Installation of auxiliary power unit. Issued 9/26/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-399C; T.C. 4A26	SA850CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aereos Portugeses. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-400, 720 Series; T.C. 4A26, 4A28	ST912SO	Installation of cargo barrier net. Amended 9/13/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
720 Series; T.C. 4A28	SA88NW	Optional interior seating arrangement. Issued 1/14/74.	NW	10174	American Aviation Services 777 Perimeter Road Boeing Field Seattle, WA 98108
720 Series; T.C. 4A28	SA95CE	Crimsco 600301 jet cargo containers in forward cabin.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
720 Series; T.C. 4A28	SA148SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA180NW	Installation for 149 passenger configuration. Issued 5/7/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720 Series; T.C. 4A28	SA182SO	Interior modifications.	SO	31429	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA302EA	Inflight motion picture system. Amended 6/9/67.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA369EA	Litton low range altimeter system.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430
720 Series; T.C. 4A28	SA371CE	Wheel 152051-4 and brake assembly 260997-1.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46620
720 Series; T.C. 4A28	SA380EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430
720 Series; T.C. 4A28	SA458WE	Crimsco jet cargo container 04-005--01, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA460CE	Wheel assembly 152051-5 and brake assembly 2600997-3.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46600

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
720 Series; T.C. 4A28	SA468EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
720 Series; T.C. 4A28	SA773WE	Closed circuit television entertainment system.	WE	25970	Continental Air Lines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
720 Series; T.C. 4A28	ST806SO	Installation of a cargo floor, smoke detector system and cargo restraint bulkhead. Amended 12/12/78.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
720 Series; T.C. 4A28	SA8[illegible]8CE-D	Additional overwing escape hatch installation interior configuration 2nd additional overwing escape hatch installation. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
720 Series; T.C. 4A28	SA1222WE	Boeing improved type engine thrust reverser forward pressure seal.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128
720 Series; T.C. 4A28	SA1245WE	Either single or dual Collins AL-101 radio altimeter system.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128
720, 720B; T.C. 4A28	SA177NW	Installation of container rack and six accompanying containers on forward right-hand coat closet. Reissued 5/29/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720, 720B; T.C. 4A28	ST564SO	Installation of HF antenna and associated hardware and structural provisions for mounting HF tuning unit. Issued 11/19/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
720, 720B; T.C. 4A28	ST662SO	Installation of nose cap "C/X" band weather radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
720, 720B; T.C. 4A28	ST931SO	Addition of smoke detector system for conversion to cargo carrier. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	ST932SO	Mechanical landing gear position indicator. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	SA3332WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
720B; T.C. 4A28	SA328NW	Installation of Fairchild weight and balance system (STAN). Issued [illegible]/28/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
720B; T.C. 4A28	SA2806SW	Stewart-Davis, Inc. auxiliary power unit. Issued 6/30/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
720-22; T.C. 4A28	SA112NW	Installation of cabin interior arrangement. Issued 5/16/74.	NW	08480	Alaska Airlines, Inc. Seattle/Tacoma Int'l Airport Seattle, WA 98155
720-22; T.C. 4A28	SA278EA	See Document No. Report No. 3187, dated 4/18/67, Rev. 1/30/69, concerning Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
720-022; T.C. 4A28	SA1553WE	Installation of Fairchild P/N 13920-301 or 15630-601 Flight Data Recorder and Honeywell P/N 180 VI Central Data Computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2095WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2206WE	Installation of Bendix third attitude indicator. Issued 7/20/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720-022; T.C. 4A28	SA2744WE-D	Alternate 143 passenger seating configuration. Issued 3/28/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
720-022; T.C. 4A28	SA2746WE-D	Alternate 149 passenger seating configuration. Issued 5/3/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2834WE-D	Alternate 101 passenger seating configuration. Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2831WE-D	Couple EDO Loran system to ADF sense antenna instead of fin cap (nc fin cap on UAL B720). Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2833WE-D	Installation of two HF communications systems. Issued 3/27/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022, -023, -025, -027, -048, -062, 720B-023B, -024B, -030B, -040B, -047B, -051B, -058B, -059B, -060B, -068B; T.C. 4A28	SA460CE	Replace main wheel and brake assemblies with Bendix wheel assembly P/N 152051-5 or P/N 152051-4 and Bendix brake assembly P/N 2600997-3. Reissued 5/1/79.	GL	15500	The Bendix Corporation Aircraft Brake & Strut Division 3520 West Westmoor Street P.O. Box 10 South Bend, IN 46624
720-022 and 727-22; T.C. 4A28 and A3WE	SA1396WE	Installation of McMillan Radome P/N 2406 as a replacement for Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720B-023; T.C. 4A28	SA412EA-D	Relocate the L.A.S.I. flight data recorder to the aft fuselage area at Station 1452 utilizing remote vertical accelerometer in left wheel well. Install new auxiliary pitot tube and static ports for the flight recorder.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
720-023B; T.C. 4A28	SA985CE-D	Side cargo door and interior installation. Issued 3/17/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-023B, -030B; T.C. 4A28	ST657SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in forward passenger compartment.	SO	67030	Mace Unit of REF Dynamics, UOP 4856 Victor Street Jacksonville, FL 32207
720-023B, -030B, 720-047B; T.C. 4A28	SA651CE-D	Increase maximum ramp weight to 235,000 lbs. and zero fuel weight to 156,000 lbs. Amended 11/21/78.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-024B; T.C. 4A28	SA1617WE	Rewiring of galley electrical power supply.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA1767WE	Installation of Galley Models CAG-10, -20, 30 and -40 manufactured by Dale Engineering & Development, Inc. Amended 10/10/68.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA2599WE	Installation of Bell & Howell movie system. Issued 9/29/72.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-025; T.C. 4A28	SA251GL	Installation of Canadian Marconi Model CMA-740 Omega/VLF navigation system. Amended 12/29/78.	GL	10340	American Trans-Air 2600 South High School Road Indianapolis, IN 46241
720-025; T.C. 4A28	ST668SO	Installation of International Inflatables Co. door-mounted inflatable evacuation slide, P/N 68040, and International Inflatables Co. door-mounted slide container, P/N C0800.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
720-027; T.C. 4A28	SA82NW	Installation of navigator's station. Issued 12/11/73.	NW	10174	American Aviation Services, Inc. 7777 Perimeter Road Boeing Field Seattle, WA 98108
720-047B; T.C. 4A28	SA194NW	Installation of new look interior arrangement. Issued 6/30/75.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
720-051B; T.C. 4A28	SA801CE	Install Mark II (Hytrol) anti-skid system. Issued December 1971.	CE	16878	The Boeing Company Wichita Division 3801 S. Oliver Wichita, KS 67210
727 Series; T.C. A3WE	SA1033O	Collins 54W-1 comparator warning system. Amended 8/10/66.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA121GL	Installation of bleed-air valve actuator, P/N G66, to replace Boeing P/N 10-60817, in various locations in anti-ice system. Issued 11/3/76.	GL	60350	MPC Products Corporation 4200 West Victoria Avenue Chicago, IL 60646
727 Series; T.C. A3WE	SA140SO	Manufacture and install coatroom and magazine rack.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33148
727 Series; T.C. A3WE	SA159SO	Aircraft integrated data systems (AIDS).	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA161SO	Dual radio altimeter system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA183SO	Crimsco cargo containers 6003 in main cabin. Amended 12/15/66.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
727 Series; T.C. A3WE	SA339CE	Fairchild cockpit voice recorder system. Amended 3/15/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA354CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA372CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA425EA-D	Install standby horizon system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA427CE	Flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64108
727 Series; T.C. A3WE	SA438CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA447EA	Vector analog computer system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727 Series; T.C. A3WE	SA469EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA490NW	Installation of PRIMUS-90 weather radar with standard black and white and also with color display.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188
727 Series; T.C. A3WE	SA535EA	Fabrication and installation of Marinc Flex-Net P/N LM365. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA604SO	Dual Collins FD-109 integrated flight system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA625SO	Installation of main landing gear wheel assembly, P/N 3-1287 and brake assembly P/N 2-1147 or 2-1147-1, 2-1190.	GL	38504	B.F. Goodrich Engineered Systems Company Box 340 Troy, OH 45373
727 Series; T.C. A3WE	ST664SO	Modify door-mounted evacuation slide container, Boeing P/N 65-26998-1, from a two-point closure to a positive single-point closure. Amended 3/30/70.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
727 Series; T.C. A3WE	SA699WE	Crimsco jet cargo container 04-005-01-1, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60660

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727 Series; T.C. A3WE	SA1093WE	Power source for Captain's CDI select relay switch relocated.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1105WE	Dual Collins AL-101 radio altimeter systems.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727; T.C. A3WE	SA1128EA	Installation of coat closet. Amended 9/11/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
727 Series; T.C. A3WE	SA1154WE	Cockpit voice recorder.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1265WE	Brownline pallet 23118 or Douglas pallet 5776662-505 with Brownline net 23143.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727 Series; T.C. A3WE	SA1322WE	Engine mounted fire detector unit modified to provide continuous support. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety System Division 1440 Fourth Street Berkeley, CA 94710
727 Series; T.C. A3WE	SA1367WE	Use of Brownline Corp. Pallet Nos. 23640-51 and 23224-51 in place of Douglas Aircraft Co. Pallet No. 577662-505.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1451WE	Installation of constant speed drive, load controller, generator and voltage regulator.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1509WE	Revised interior arrangement.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727 Series; T.C. A3WE	SA1563WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1868SW	Portable solid oxygen system for first-aid use. Issued 4/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
727 Series; T.C. A3WE	SA2422WE	Installation of Valley Todeco bolt VAL 22016 to replace Boeing bolt BAC B30EK8-48 on 727 thrust reverser. Issued 9/23/71.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727, 727C; T.C. 2H3	SA800CE	Installation of three cell forward and three cell aft auxiliary fuel tanks in lower cargo compartment. Issued June 1972.	CE	16878	The Boeing Company 3801 South Oliver Street Wichita, KS 67210
727, 727-100, -22; T.C. A3WE	SA2563WE	Installation of garment bag module. Issued 8/23/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	SA169GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, F/N 298-1026-01 or -02. Reissued 12/21/78.	GL	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	ST650SO	Installation of dual band (C/X) type weather radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
727, 727C, 727-200 Series; T.C. A3WE	SA1239CE-D	Grimes coffee maker and warmer unit installation. Issued 11/20/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727, 727-100, 727C, 727-200; T.C. A3WE	SA2668WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-50 autopilot as replacement for Sperry or Smiths rate gyros. Amended 6/20/73.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3130WE	Installation of dual Litton LTN-72 or a single or dual LTN-72R INS/RNAV navigation system. Amended 5/18/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3145WE	Installation of Sperry Model Block V SP-50 autopilot and Honeywell Air Data computer. Issued 3/12/76.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3153WE	Installation of forward coat closet on left hand side just aft of forward entry door. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3154WE	Installation of interior configuration consisting of 10 first class and 98 coach seats. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3654WE	Installation of interior configuration with 10 first class and 95 coach seats. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series T.C. A3WE	SA3665WE	Installation of a dual Collins 61E inertial navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3679WE	Installation of a Global GNS-500A VLF/Omega navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, 727-100C, 727-200; T.C. A3WE	SA3717WE	Installation of a cabin divider. Issued 8/29/78.	WE	25970	Continental Air Lines International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3755WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-211 omega navigation system and a true airspeed system. Amended 3/23/79.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3964WE	Installation of dual Litton LTN-211 omega navigation systems. Issued 5/23/79.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, -200; T.C. A3WE	SA4161WE	Installation of Teledyne angle of attach system. Issued 7/7/80.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, -100C Series; 727-223, -225, -227, -228, -231, -235, -251, -264, -284, -295; T.C. A3WE	SA3220WE	Addition of filter to the cabin pressure limit control feature of P/N 103280 outflow valve. Issued 6/24/76.	WE	07505	AiResearch Manufacturing Company Garrett Corporation 2525 West 190th Street Torrance, CA 90509
727, 727C, 727-100, -100C, 727-200; T.C. A3WE	SA2348WE	Modify Boeing 727 Series airplanes by installation of emblem lights. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
727, 727C, 727-200, 737; T.C. A3WE	SA3292WE	Installation of thrust reverser short track. Issued 11/23/76.	WE	78475	Thrustair, Inc. 12990 Branford Avenue Arleta, CA 91331
727, 727C, 727-200, 737; T.C. A3WE	SA3306WE	Installation of thrust reverser cascades. Issued 12/3/76.	WE	41015	Hasko-Air, Inc. 9042 Owensmouth Avenue Canoga Park, CA 91304
727, 727-100, 727C, 727-100C, 727-200 Series; T.C. A3WE	SA3521WE	Installation of a cabin divider. Issued 11/8/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-200; T.C. A3WE	ST436SO	Installation of thrust reverser deflector door drive. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727, 727C, 727-200; T.C. A3WE	ST450SO	Modification of thrust reverser forward deflector door link. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727-1H2; T.C. A3WE	SA2480WE	Addition of INS attitude reference data to flight instruments. Issued 2/15/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-1H2; T.C. A3WE	SA2552WE	Install Litton P/N 451158 automatic data entry unit. Issued 8/17/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-2B7; T.C. A3WE	SA2168WE	Installation of Henry Engineering lounge tables No. 17701 and No. A17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727-2B7; T.C. A3WE	SA2170WE	Installation of class divider. Issued 5/27/70.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-2J0; T.C. A3WE	SA1235CE-D	Forward auxiliary fuel tank removal and reinstallation. Issued 10/9/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-2M7; T.C. A3WE	SA3505WE	Installation of ground proximity warning system. Issued 10/27/77.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3564WE	Installation of auxiliary fuel tanks in the forward and aft belly cargo/baggage compartments. Issued 1/20/78.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3380WE	Installation of dual LTN-51, or dual LTN-72, or dual LTN-72R, or one LTN-51 and either one LTN-72 or one LTN-72R inertial navigation system. Amended 4/29/80.	WE	43340	Hughes Airwest, Inc P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3967WE	Installation of coat room assembly No. RW2527036. Issued 5/29/79.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2L4; T.C. A3WE	SA3065WE	Installation of 3400 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 7/16/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-14; T.C. A3WE	SA1942WE	Revised interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14; T.C. A3WE	SA1986WE	Interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -35, -193, -214, -235; T.C. A3WE	SA1885WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727-14, -51; T.C. A3WE	SA1717WE	Revised interior arrangement. Amended 4/20/77.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
727-14, -51, -214, -254, -2J7, -2Q8; T.C. A3WE	SA3013WE	Installation of ground proximity warning system. Amended 12/19/78.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -51, -214, -254, -2Q8; T.C. A3WE	SA3939WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/11/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-17; T.C. A3WE	SA3674WE	Installation of 2700 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 6/30/78.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-17, -31, -31C, -180C, -231, -231A; T.C. A3WE	SA1488CE	Installation of a pitot heater failure indication system. Issued 5/4/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-21; T.C. A3WE	SA264NW	Interior arrangement. Issued 2/20/76.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188
727-21; T.C. A3WE	SA1078EA-D	Installation of two closets in rear of cabin to accommodate a bar or food cart and provisions for parking the carts in flight at two locations. Amended 11/8/79.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
727-21, 21C; T.C. A3WE	SA6125O-D	Installation of portable berth (aerctherm stretcher). Reissued 9/6/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727-21, -22, -81; T.C. A3WE	SA2660WE	Modification of cabin interior. Amended 12/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-21, -81; T.C. A3WE	SA3022WE-D	Installation of new seating arrangement. Amended 11/10/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-21C; T.C. A3WE	SA1292WE	Installation of Boeing palletized cargo system 65-49102 with Brownline pallet 22630-51 or 26100-52 Brownline net assembly 23225-51, 23226-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-21C; T.C. A3WE	SA1594WE	Installation of Heath Tecna Corp. pallet AC-10065 and Brownline Corp. net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-21C; T.C. A3WE	SA3006WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-21C; T.C. A3WE	SA3672WE	Installation of Brownline quick change pallets, P/N's 45881-101, 45882-101 and 46129-101. Issued 6/19/78.	WE	17740	Brooks & Perkins Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-21C, -22C, -25C, -27C, -30C, -31C; T.C. A3WE	SA696CE	Installation Aeroquip Corp. cargo tie-down net.	GL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203
727-22; T.C. A3WE	SA1788WE	Interior arrangement installation.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94125
727-22; T.C. A3WE	SA3323WE	Installation of forward facing flight attendant seat on forward galley. Issued 1/20/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-22; T.C. A3WE	SA3364WE-D	Revise cabin seating to accommodate 118 all-coach configuration. Issued 4/25/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C; T.C. A3WE	SA3023WE-D	Revise seating arrangement from 18 first class/78 coach to 12 first class/86 coach configuration and further revised to 10 first class/86 coach configuration. Amended 6/11/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-22, 727-22QC; T.C. A3WE	SA1687WE	Modify existing Collins Radio Company type FD-109 Flight Director installation to add "Steering", "Airspeed-Hold", and "Auto Approach" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3079WE	Installations of Collins FPC-75-P/N 622-2615-012 or P/N 622-2615-212, or P/N 622-2615-013, ground proximity warning system computer in airplanes. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3350WE-D	Air data system. Amended 7/20/79.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-22, -24C, -30, -76, -92C; T.C. A3WE	SA3655WE	Installation of Nordskog Company auxiliary galley Model 1-420. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727-22, -24C, -30, -76, -92C, -224; T.C. A3WE	SA4157WE	Installation of Fairchild beverage cart, Model 79067000. Issued 6/6/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-22, -30, -76, 92C; T.C. A3WE	SA981CE-D	Reconfiguration of flight crew instrument panels, avionics and passenger cabin. Amended 8/28/78.	CE	16877	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-22C; T.C. A3WE	SA645CE	Make and install pallets in accordance with Brooks & Perkins Drawing Index No. 16987DL-E and Installation Instructions No. BPS 149. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA814CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-22C; T.C. A3WE	SA842CE	Installation of cargo pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA1622WE	Modification of type design to permit installation of Heath Tecna Corp. AC-10061 pallet with AC-10069 net.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-22C; T.C. A3WE	SA1816WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-22C; T.C. A3WE	SA1962WE	Modify by installation of pallet assemblies 40160101 thru 40160108 used in conjunction with net assemblies 22672-51, -52; 23143-51, 22758-51, -52; 22273-51, 7776967-1 (Douglas) and 3950020 (Aeroquip). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1, or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
727-22C; T.C. A3WE	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517, with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks & Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2255WE	Installation of Satco, Inc., pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-22C; T.C. A3WE	SA2274WE	Installation of Irvin 88" x 125" cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
727-22C; T.C. A3WE	SA2844WE	Installation of coat and luggage stowage unit. Issued 2/25/74.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-22C; T.C. A3WE	SA3359WE-D	Retrofit of Kollsman P/N A41869-10-021 altimeters on the captain's and first officer's instrument panel. Issued 1/11/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3577WE-D	Installs overhead stowage bin kit. Issued 8/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3673WE	Installation of cargo restraint system which meets the requirements of a NAS 3610 class IIA restraint system. Issued 6/21/78.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
727-22C; T.C. A3WE	SA3775WE	Installation of the Brownline 46000-101 cargo system. Issued 10/31/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-22C, -24C, -25C, -116C; T.C. A3WE	SA4098WE	Installation of cargo system, P/N 4727C-101. Issued 3/10/80.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-022; T.C. A3WE	SA2838WE-D	Installs barrier and tie-down fitting for using preloaded liquor service cart on-board aircraft. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-022; T.C. A3WE	SA3575WE-D	Remove all first class seats, the class divider, the carry-on baggage and garment bag modules and replace with all coach seats to increase seating capacity to 112 passengers. Issued 4/24/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-022;	SA3363WE-D	Installation of dual Collins FD-109A flight director systems. Issued 4/24/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-022, -022C, -222; T.C. A3WE	SA2201WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727-22, -222, -22QC; T.C. A3WE	SA2096WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-23; T.C. A3WE	SA411EA-D	Relocate the flight data recorder Station 1120 on cabin floor, left hand side, aft of last row of seats to provide improved crash survivability. Amended 12/8/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23; T.C. A3WE	SA563EA	Installation of digital adaptive recording system (DARS) on one Boeing 727-23. Issued 4/7/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA501EA-D	Delete auxiliary vertical gyro on 727-23 and 727-123 and authorize use of either Sperry or Bendix gyros on 727-35 and 727-95. Amended 9/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA515EA-D	Install REF Dynamics beverage bar. Amended 2/16/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA523EA-D	Install overwing emergency lights. Amended 1/12/69.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA524EA-D	Change interior passenger seating arrangement.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA558EA-D	Modification of leading edge slat and flap position indication system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95 and 727-123; T.C. A3WE	SA866WE	Installation of ILS Back Course and Compass Switches. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA872WE	Installation of Collins P/N 54W-1 instrument comparator. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1195WE	Installation of dual Collins FS-108 flight director systems. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1575WE	Installation of dual Collins AL-101 radio altimeter system. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-95, 727-123; T.C. A3WE	SA804WE	Installation of Honeywell HG180 Modular Air Data Computer System. Amended 6/26/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -223; T.C. A3WE	SA552EA-D	Installation of autopilot go-around unit. Issued 4/24/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-24C, 727-116C; T.C. A3WE	SA1441CE-D	Change crew instrument panels and systems revisions. Reissued 9/19/79.	CE	16877	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-24C; T.C. A3WE	SA1661WE	Installation of Bendix Dual DRA 12 Doppler System.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2886WE	Interior arrangement. Issued 5/18/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-24C, 727-92C; T.C. A3WE	SA2899WE	Installation of courier seat. Issued 6/15/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2942WE	Installation of Nordskog Galleys 1-289A and 1-290A. Amended 11/14/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, -92C; T.C. A3WE	SA3855WE	Installation of Brownline cargo/seat pallet system 45980, configuration -101. Issued 2/12/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
727-25; T.C. A3WE	ST588SO	Installation of 119 passenger interior and installation of two EAL 52-RA-7 four man life rafts. Issued 4/30/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST663SO	Installation of LORAN A navigation system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST740SC	Cabin interior arrangement and furnishings changes. Issued 6/3/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST426SO	Installation of Honeywell HG180V3 air data computer with electronic altimeters, altitude reporting digitizer and altitude alerting system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST741SO	Cabin interior configuration changes. Amended 1/24/75.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST751SO	Modification of main cabin passenger interior configuration from 14 first class and 89 tourist class to 12 first class and 95 tourist class accommodations. Issued 5/28/76.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, -25C; T.C. A3WE	ST954SO	Installation of Mansfield Aircraft Products model 1470 galley/coatroom. Issued 8/29/77.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C, -225; T.C. A3WE	ST510SO	Installation of dual HF communications system using vertical fin leading edge slotted antenna. Amended 1/13/78.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	ST534SO	Interior - two pallet cargo/65 passenger MAC configuration installed. Issued 4/13/73.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	SA2364WE	Installation of Satco, Inc. cargo pallet assembly P/N 31095-501, -503, -505, -507 in conjunction with net assemblies NAS 3610-2A1N, -2A2N, -2A3K, -2A5N, and -2A6N. Amended 5/18/72.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-30; T.C. A3WE	SA982CE-D	Interior arrangement installation. Amended June 1976.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-30; T.C. A3WE	SA3157WE	Installation of 1200 gallon auxiliary fuel tank in forward cargo compartment. Issued 3/26/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-30 T.C. A3WE	SA3319WE	Installation of auxiliary fuselage fuel tanks (1600 gallons) in forward and aft cargo compartment. Issued 12/28/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91406
727-30, -81; T.C. A3WE	SA2734WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 2/13/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-030, -224; T.C. A3WE	SA3408WE	Installation of Lermer Apparatebau GMBH beverage cart No. L15701. Issued 5/26/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-31; T.C. A3WE	SA478CE	Modification to flap quadrant.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31; T.C. A3WE	SA570CE	Install Models 14801 or 14802 Henry Engineering Company bar unit. Amended 10/18/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C; T.C. A3WE	SA373CE	Installation of a single SCAT system. Amended 8/12/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C; T.C. A3WE	SA604CE	Installation of dual radio altimeter provision - single equipment driving dual indicators. Amended 2/3/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C, -180C; T.C. A3WE	SA235CE	Installation of Kollsman Integrated Flight Instrument System (KIFIS). Amended 5/8/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C, -180C; T.C. A3WE	SA734CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, -31C, -180C; T.C. A3WE	SA779CE	Installation of Bendix gyro horizon and inverter. Issued June 1971.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA553CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA828CE	Install Butler National Corp. flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA1137CE	Installation of hydraulic interconnect override system. Issued June 1975.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180C, 727-231; T.C. A3WE	SA1542CE	Installation of a Growth Industries dual cavity oven. Issued 12/12/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-31, -31C, -231; T.C. A3WE	SA490CE	Installation of Safe Flight Corp. auto power servo kits. Amended 10/9/74.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31C, -180C; T.C. A3WE	SA741CE	Install Henry Engineering auxiliary bar model 15501A and one additional triple passenger seat.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-35; T.C. A3WE	SA639SO	Installation of hatrack assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA640SO	Installation of liquor service galley assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA1566WE	Installation of Sperry SP-50 Mod Block IV Single Channel Autopilot. Amended 5/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-35, 727-95, 727-123; T.C. A3WE	SA1576WE	Replacement of Captain's altimeter and First Officer's altimeter and and installation of third altimeter. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-35, -235; T.C. A3WE	ST738SO	Installation of Gulton Model EMBS 144 nickel-cadmium electrical storage battery and integral automatic control system. Issued 1/23/74.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami International Airport Jamaica, NY 11430
727-46; T.C. A3WE	SA847CE-D	Structural and system modification for installation of service door and retractable step. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-46; T.C. A3WE	SA2970WE	Installation of 300 gallon auxiliary fuel tank in aft cargo compartment. Issued 12/20/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-51, -51C, -151C, -251; T.C. A3WE	SA89GI	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-75, -232, -295; T.C. A3WE	ST855SC	Installation of Bendix ground proximity warning system. Issued 10/16/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-76; T.C. A3WE	SA4164WE	Installation of dual Delco carousel IVA inertial navigation system. Issued 6/27/80.	WE	07500	AiResearch Aviation Company 6201 WEst Imperial Highway Los Angeles, CA 90045
727-77; T.C. A3WE	SA3559WE	Installation of a 1932-gallon auxiliary fuel tank system in forward and aft cargo compartments. Issued 2/6/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-81; T.C. A3WE	SA2724WE	Installation of executive cabin interior. Amended 9/20/74.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727-81, -100; T.C. A3WE	SA263NW	Garment bag module modification. Issued 2/25/76.	NW	47722	Kelley-Morrow Enterprises The Common Building 1200 - 112th N.E. Bellevue, WA 98004
727-81, -100; T.C. A3WE	SA2732WE	Installation of duel LTN-104 navigation systems. Amended 3/13/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-90, -90C; T.C. A3WE	SA2245WE	Interior arrangements. Issued 9/18/70.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98158
727-90C; T.C. A3WE	SA139NW	Installation of quick change interior arrangement. Amended 4/21/75.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98108
727-90C; T.C. A3WE	SA327NW	Interior arrangements 98 PAX and two cargo pallet/63. Issued 7/23/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA129NW	Installation of cabin interior arrangement. Issued 9/23/74.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA310NW	Interior arrangement. Issued 5/28/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, 737-202C, -210C; T.C. A3WE, A16WE	SA1823WE	Installation of "Heathair" AC-10360 cargo pallet assembly and AC-10374 cargo net assembly. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-92C; T.C. A3WE	SA1839WE	Stewardess seat installed on Nordskog 769 galley.	WE	61605	Nordskog Co., Inc. 16000 Strathern Street Van Nuys, CA 91406
727-95; T.C. A3WE	SA704EA	Installation of Henry Engineering Company Galleys Models Nos. 14001 and 14002. Reissued 12/8/72.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-100 Series Models type certificated as of 6/17/68; T.C. A3WE	SA587CE	Installation of Hoskins Twilighter Mark V high intensity light system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
727-100; T.C. A3WE	SA612NW	Installation of coat closet. Issued 5/26/78.	NW	48532	KME Manufacturing, Inc. The Commons Building 1200 112th Street, N.E. Renton, WA 98055
727-100; T.C. A3WE	SA643NW	Installation of six carry-on baggage modules. Issued 9/13/78.	NW	78672	Tramco, Inc. 1033 Thomas Avenue, S.W. Renton, WA 98055
727-100; T.C. A3WE	SA697NW	Install life raft stowage compartments. Issued 12/14/78.	NW	41625	Heath Tecna 19819 84th Avenue South Kent, WA 98031
727-100; T.C. A3WE	SA1130SC	Installation of an aft galley storage module. Issued 1/22/80.	SO	64500	Piedmont Airlines Smith-Reynolds Airport Winston-Salem, NC 27102
727-100; T.C. A3WE	SA2498SW	Collins FPC-75 ground proximity warning system. Issued 1/23/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
727-100 Series; T.C. A3WE	SA3501WE	Installation of Litton LTN-201 omega navigation system. Amended 12/29/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-100 Series; T.C. A3WE	SA3810WE	Installation of a maximum of eight auxiliary fuel tanks in forward and aft cargo compartments. Amended 1/4/80.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-100 Series; T.C. A3WE	SA3851WE	Installation of Litton LTN-211 Omega Navigation System. Amended 4/19/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100, -100B, -200; T.C. 4A21	ST660SO	Installation of "C/X" band nose radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
727-100, -100C Series; T.C. A3WE	SA3661WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-201 Omega navigation system and a true airspeed system. Issued 10/11/78.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
727-100, -200; T.C. A3WE	SA1050CE	Install Crimsco cargo container, P/N 600301. Issued November 1974.	CE	27000	Crimsco, Inc. 5001 E. 59th Street Kansas City, MO 64130
727-100, -200; T.C. A3WE	SA2240WE	Installation of door-mounted emergency light. Amended 9/23/70.	WE	44266	International Inflatables Company Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
727-100, -200; T.C. A3WE	SA3333WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
727-100, -200; T.C. A3WE	SA3374WE	Installation of bearing P/N VTB02220 as replacement for Boeing P/N 10-60545-113S in main landing gear lock system assembly. Issued 3/29/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200; T.C. A3WE	SA3379WE	Installation of bearing, P/N VTE02800 in lieu of Boeing bearing P/N 10-60545-143. Issued 4/20/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200 Series; T.C. A3WE	SA3508WE	Installation of Valley-Todeco bearings, P/Ns VTB-02900, VTB-02910, VTE-02920, VTB-02930. Issued 11/8/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, 727-200; T.C. A3WE	SA3716WE	Installation of a Dretloh Model 5002, P/N 121214-1 food carrier. Issued 8/25/78.	WE	30702	Dretloh Aircraft Supply, Inc. 980 North Lemon Orange, CA 92667
727-100, -200; T.C. A3WE	SA4133WE	Installation of an ARINC communications addressing and reporting system (ACARS). Issued 4/24/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100, 100QC; 737; T.C. A3WE, A16WE	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
727-171C, 727-173C; T.C. A3WE	SA1693WE	Revised interior arrangement with Nordskog hostess seat 6734 and door 61246 and associated modifications added to Mapco Galley Model 680T-1.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-172C; T.C. A3WE	SA671EA	Installation of pallet net for use with Boeing pallets.	SO	44750	Irvin Industries, Inc. 1315 Versailles Road Lexington, KY 40501
727-172C; T.C. A3WE	SA849CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aeros Portugeses requirements. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-172C; T.C. A3WE	SA1662WE	Installation of Heath Tecna Corp. AC-10160 pallet with AC-10069 net on Boeing 707-172C. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-173C; T.C. A3WE	SA1907WE	Interior arrangement reflecting 122 passenger quick change conversion configuration. Amended 6/3/69.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
727-173C; T.C. A3WE	SA2385WE	Installation of interior arrangement. Amended 9/14/71.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-180C; T.C. A3WE	SA558CE	Installation of Kollsman integrated flight instrument system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-180C; T.C. A3WE	SA559CE	Installation of a single SCAT system. Amended 8/11/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-180C; T.C. A3WE	SA560CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-200; T.C. A3WE	SA349NW	Installation of wind screen in forward cabin RH side. Issued 8/27/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 832 Issaquah, WA 98027
727-200; T.C. A3WE	SA359NW	Installation of carry-on baggage unit. Issued 9/28/76.	NW	48532	KME Manufacturing, Inc. 1200 - 112th N.E. Bellevue, WA 98004
727-200; T.C. A3WE	SA547NW	Installation of Mark I interior kit. Issued 11/22/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue S. Kent, WA 98031
727-200; T.C. A3WE	ST742SO	Modification and installation of seat model 914-1. Issued 6/26/74.	SO	21560	Charlotte Aircraft Corporation P.O. Box 1225 Miami, FL 33148
727-200; T.C. A3WE	SA774SO	Installation of the Litton LTN-211 Omega Navigation System. Issued 11/30/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airlines Miami, FL 33148
727-200; T.C. A3WE	SA816NW	An interior installation. Issued 8/8/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
727-200; T.C. A3WE	SA2335SW	Modification to increase depth of Weber 808737-618-M pilot seat and 808737-619-M copilot seat. Issued 7/23/76.	SW	14222	B & H Parts Company Meacham Field Fort Worth, TX 76106
727-200; T.C. A3WE	SA2672WE	Installation of coat and luggage stowage unit. Issued 3/23/73.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
727-200; T.C. A3WE	SA3054WE	Installation of dual Litton LTN-72 inertial navigation system. Amended 6/22/76.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-200; T.C. A3WE	SA3081WE	Replacement of evacuation slide container latches with latches of a new design. Reissued 6/2/76.	WE	70130	Sargent Industries PICO Division Kahr Bearing Division 2045 Evans Avenue San Francisco, CA 94124
727-200; T.C. A3WE	SA3594WE-D	Removal of all first class seating and class divider. Relocate cabin seating to provide 14 rows at 38-inch pitch. Installation of additional furnishings. Amended 1/7/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-200 Series; T.C. A3WE	SA3882WE	Installation of aft cargo hold trash chute container assembly, P/N E-25-0256. Amended 2/12/80.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-200, 737; T.C. A3WE, A16WE	SA764NW	Inner window pane replacement. Issued 5/3/79.	NW	79672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
727-214; T.C. A3WE	SA1922WE	Interior arrangement. Amended 6/6/69.	RM	37015	Frontier Airlines 5900 East 39th Avenue Denver, CO 80207
727-214, -254, -2Q8; T.C. A3WE	SA3069WE	Installation of galley in forward passenger compartment. Amended 2/12/80.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3560WE	Installation of PSA galley P/N C-25-0085. Issued 1/18/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3625WE	Installation of 168 passenger interior arrangement. Issued 4/3/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3820WE	Installation of 165 passenger interior arrangement, and aft stowage closet. Issued 1/8/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor San Diego, CA 92101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-222; T.C. A3WE	SA2448WE	Installation of McDonnell Douglas Eros II collision avoidance system. Issued 11/22/71.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2743WE-D	Installation "New Look" cabin interiors. Amended 6/10/77.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2826WE-D	Installations of provisions for ground proximity warning system. Issued 2/21/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2832WE-D	Installation of ground proximity warning system with cockpit annunciations deactivated and warning signals connected to digital recorder. Issued 3/13/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2841WE-D	Revise cabin seating configuration to accommodate 14 first class/112 coach configuration. Amended 8/20/76.	WE	80500	United Airlines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3037WE-D	Revise cabin seating configuration to accommodate 10 first class/118 coach configuration. Issued 2/24/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3353WE-D	This modification installs a retractable cart tie-down at the Sta. 350-50 and LBL 32.34. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3354WE-D	This modification installs modified seats in the first class compartment. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3355WE-D	Installation of carry-on baggage and garment bag modules just aft of forward entry door on left side of passenger cabin. Issued 10/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3362WE-D	Installation of a Safe Flight P/N 6500-2 windshear warning computer for in-service evaluation. Issued 3/15/78.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3578WE-D	Installation of arinc communications addressing reporting system (ACARS). Amended 2/9/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3589WE	Installation of passenger audio entertainment system. Issued 7/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3590WE-D	The cabin interior seating configuration will change from 10F/124Y to 14F/118Y. One row of coach seats will be removed and one row of first class seats added. The class divider will be moved accordingly. Issued 2/9/79.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3592WE-D	Replace the auxiliary galley/stowage compartment located in the RH aft passenger cabin between station 1101 and 1137 with a new stowage compartment. Amended 12/17/79.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA4063WE	Deletion of the pair of excess Type I emergency exits located at station 720 and 15. Issued 11/29/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-223; T.C. A3WE	SA521EA-D	Install single area navigation system. Amended 9/10/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74151
727-224; . C. A3WE	SA3325WE	Installation of auxiliary bar unit No. 1-368. Issued 1/13/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-225; T.C. A3WE	ST593SO	Installation of 18 first class/116 tourist class passenger interior with modified coatroom and windscreen. Issued May 1974.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225; T.C. A3WE	ST753SO	Installation of main cabin equipment to provide accommodations for 137 passengers (12 first class and 125 tourist class). Issued 8/4/76.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225A; T.C. A3WE	SA775SO	Installation of a coatroom and class divider partition in the main cabin at B.S. 544. Issued 12/3/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-225; T.C. A3WE	SA1238CE-D	Interior conversion to 177 tourist class passengers. Issued 11/7/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-231; T.C. A3WE	SA561CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA562CE	Installation of single seat system. Amended June 1974.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA639CE	Modification of SCAT/Auto Throttle to include auto-land throttle closure feature.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA721CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA1287CE	Revision of engine fire detection circuit. Issued December 1976.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA1475CE	Installation of Simmonds Precision performance advisory system (fuel management). Issued 3/6/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-237; T.C. A3WE	SA2729WE	Installation of interior arrangement. Issued 7/23/73.	WE	62160	Pacific Southwest Airlines 3220 N. Harbor Drive San Diego, CA 92101
727-247; T.C. A3WE	SA469NW	Installation of coat closet unit on Western Airlines aircraft. Issued 6/24/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
727-247; T.C. A3WE	ST549SO	Manufacture and installation of P/N 10826-1 cart stowage unit. Amended 11/18/77.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
727-247; T.C. A3WE	ST550SO	Manufacture and installation of P/N 10825 coat closet unit. This STC is limited to Boeing 727-247 aircraft with wide body interiors. Issued 9/21/73.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
727-247; T.C. A3WE	SA3495WE	Conversion of UOP galley by installation of UOP oven, Grimes coffeemaker and overboard drain system. Issued 9/30/77.	SC	8130	Aerospace Division Universal Oil Products 4856 Victor Street Jacksonville, FL 32207
727-247; T.C . A3WE	SA3644WE	Installation of IPECO pilot and co-pilot crew seats. Issued 5/16/78.	WE	54860	MARCON Associates, Inc. Agents for IPECO Europe Ltd. 18436 Hawthorne Boulevard Suite 212 Torrance, CA 90504
727-247, -2Q8; T.C. A3WE	SA29NE	Installation of Aerospace Division galleys, P/Ns 190E1000-103, 190E2000-105, -106, and -107 in Western Airlines Boeing 727-247 and -2Q8 aircraft. Amended 5/4/79.	NE	81120	Aerospace Division Universal Oil Products Route 202 Bantam, CT 06750
727-248, -2Q8; T.C. A3WE	SA3929WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/3/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
727-281;737-281; T.C. A3WE, A16WE	SA33NW	Installation of class divider in constant section at station 500 on Model 727-281 and station 525 on Model 737-281. Issued 3/14/73.	NW	83765	Vinnedge and Associates P.O. Box 374 North Bend, WA 98045
727-291 and 727-295; T.C. A3WE	SA1602WE	Revised interior arrangement with Frontier Galley Models 13301, 13302, 13303, and 13304 installed. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727, 727C, 727-200; T.C. A3WE	ST731SO	Installation of automatic in-flight lock for ventral stair-door. Amended 5/18/73.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727, 727C, 727-200; T.C. A3WE	SA2315WE	Installation of thrust reverser adjustable offset links on above aircraft equipped with Boeing Thrust Reversers, BAC P/N 65-27800-1, 65-27800-3 and 65-27800 only. Issued 2/22/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2337WE	Installation of Triumph Corporation solid offset thrust reverser links. Issued 4/9/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2391WE	Modification of nose gear steering cylinder. Issued 7/30/71.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727, 727C, 727-200; T.C. A3WE	SA2471WE	Installation of Triumph Corporation 5026 series bearings and rod ends on thrust reversers. Issued 2/1/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T.C. A3WE	SA2487WE	Installation of main landing gear lock actuator bearing assembly. Issued 3/3/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2518WE	Installation of thrust reverser forward deflector door link. Issued 5/1/72.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727, 727C, 727-200; T.C. A3WE	SA2627WE	Installation of fuel control rod end bearings. Issued 1/4/73.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T.C. A3WE	SA2779WE	Installation of auxiliary power fire detector unit. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 Fourth Street Berkeley, CA 94710
727 Series, 737 Series; T.C. A3WE, A16WE	SA1052SO	Installation of GE battery P/N 43B022RB36 in place of Marathon P/N CA-727-7, CA-727-20, or CA-27-20 batteries or SAFT P/N 23180 batteries; or installation of GE battery P/N 43B020RB10 replacing Marathon P/N CA-727-7, CA-727-20 or CA-27-20 or SAFT P/N 23186 or 23180 batteries. Amended 5/11/79.	SO	37380	General Electric Company P.O. Box 114 GAinesville, FL 32602
727 Series; 737 Series; T.C. A3WE, A16WE	SA2501WE	Installation of replacement cooling turbine nozzle assembly. Reissued 1/5/79.	WE	67145	Repair Tech International 13900 Saticoy Street Van Nuys, CA 91402
737 Series; T.C. A16WE	SA270NW	Interior arrangement. Issued 3/11/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA353NW	Installation interior components consisting of 2 wind screens and 3 decorative panels on existing galleys. Issued 9/7/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA370NW	Removal of passenger interior, installation of cargo compartment liners and cargo tie down equipment. Issued 11/8/76.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	ST854SO	Installation of Bendix GPW-83 ground ppoximity warning system. Amended 1/21/76.	SO	64500	Piedmont Aviation, Inc. P.O. Box 2720 Smith Reynolds Airport Winston-Salem, NC 27102
737; T.C. A16WE	SA751NW	Installation of a coat closet/ storage bin. Issued 4/12/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737; T.C. A16WE	SA781NW	Installation of a coat closet. Issued 6/7/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
737; T.C. A16WE	SA853NW	Installation of a coat closet. Issued 10/29/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA1401SW	Replace Marathon CA-737 battery with General Electric 43B022RB10 battery. Issued 12/9/71.	GL	37379	General Electric Company 206 W. Mitchell Avenue Cincinnati, OH 45232
737; T.C. A16WE	SA1519SW	Coat closet. Issued 10/14/72.	SW	16750	EIDCO, Inc. 2732 Ludelle Fort Worth, TX 76105
737; T.C. A16WE	SA3983WE	Installation of storage unit, P/N 10165. Issued 6/26/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
737-2A1; T.C. A16WE	ST136RM	Installation of interior arrangement. Issued 4/25/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2A6; T.C. A16WE	SA2153WE	Installation of fuselage fuel tanks in forward and aft cargo compartments.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA6RM	Interior arrangement modification. Amended 3/10/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA66RM	Revision of aft coat closet capacity from 100 lbs. to 250 lbs. Amended 8/6/80.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA67RM	Installation of trash module in aft coat closet. Issued 3/12/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -222, -247, -291; T.C. A16WE	SA75RM	Installation of Mapco closet module, P/N 1345, under forward left side hatrack. Issued 5/26/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0. -2H4, -212, -217, -291, -222; T.C. A16WE	SA101RM	Install dual SELCAL system. Amended 6/22/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-021; T.C. A16WE	SA523AL	Installation of ground proximity warning system. Reissued 6/19/75.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
737-T43A; T.C. A16WE	SA265GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500, and Harrowe barometric altitude rate computer P/N 4030-03-1. Issued 8/25/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
737-2S2C, -2Q8C; T.C. A16WE	SA4019WE	Installation of Brownline cargo pallet restraint system, P/N 46926-101, -102. Amended 11/21/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-100, -200, -200C Series; T.C. A16WE	SA2705WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-77 autopilot as a replacement for Sperry or Smiths rate gyros. Amended 7/15/74.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
737-100, 737-200; T.C. A16WE	SA2828WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-100, -200; T.C. A16WE	SA3334WE	Installation of stretcher carrier, AM 2003. Issued 2/6/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
737-100/200/200C; T.C. A16WE	SA2267WE	Installation of door mounted emergency light. Issued 10/30/70.	WE	44266	International Inflatables Co. Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
737-100/200/200C; T.C. A16WE	SA2564WE	Installation of garment bag module. Amended 9/20/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-100, -200, -200C; T.C. A16WE	SA170GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-6, with Courter flap asumetry detector kit, P/N 298-1026-02. Reissued 12/21/78.	GL	26675	Courter, Incorporated 375 North Lake Street Boyne City, MI 49712
737-100, -200, -200C; T.C. A16WE	ST686SO	Installation of nose cap "C/X" band weather radar radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
737-100, -200, -200 Series; T.C. A16WE	SA887EA	Installation of structural provisions for tail logo lights. Amended 4/19/72.	EA	18750	Butler Aviation - Friendship, Inc. Sub. of Butler Aviation Int'l Friendship Int'l Airport Baltimore, MD 21240
737-100/200/200C; T.C. A16WE	SA2542WE	Installation of wing-tip mounted logo lights. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
737-200; T.C. A16WE	SA53RM	Installation of Sundstrand Data Control ground proximity warning system and glide slope monitoring system. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA55RM	Installation of Universal Oil Products Co. galley tray cart. Amended 8/18/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA62RM	Installation of Universal Oil Products Co. beverage cart, P/N 11143-1. Issued 8/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA103NW	Installation of modified lower interior sidewall. Issued 4/12/74.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	SA178NW	Installation of perfume dispenser into three lavatories. Issued 5/12/75.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	ST201RM	Modification of Sundstrand data control ground proximity warning system and glide slope monitoring system installation. Issued 6/30/80.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	ST430SO	Installation of unusual events recording system.	GL	77600	Technology, Inc. 7400 Colonel Glenn Highway Dayton, OH 45431
737-200; T.C. A16WE	ST875SO	Replacement of Monogram P/N 3299-1 or Leach P/N TD1514-1002 timer assemblies with Piedmont P/N 737D-81017 solid state timer. Amended 7/13/76.	SO	64500	Piedmont Aviation, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200 Series; T.C. A16WE	ST1020SO	Installation of 112 passenger interior arrangement. Issued 8/31/78.	SO	64500	Piedmont Aviation Smith-Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	ST1034SO	Fabrication and installation of an aft right hand windscreen. Issued 11/15/78.	SO	64500	Piedmont Airlines Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1113SO	Fabrication and installation of an aft left-hand windscreen. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1114SO	Fabrication and installation of a forward coat closet. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA2747WE-D	This modification provides an all coach seating configuration for 113 passengers. Issued 5/24/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
737-200; T.C. A16WE	SA3134WE	Installation of Collins ground proximity warning system. Issued 1/7/76.	WE	04080	Air California P.O. Box 2678 Hangar #6, Oakland Int'l Airport Oakland, CA 94614

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-200; T.C. A16WE	SA4042WE	Installation of new overhead enclosed stowage compartments, new fluorescent wash lighting and modified passenger service units. Amended 3/20/80.	WE	42150	HITCO 1600 West 135th Street Gardena, CA 90249
727-200, -200C; T.C. A16WE	SA3464WE	Installation of alternate Systron Donner lower engine fire/overheat detector system, P/N 1705-1, in place of approved P/N 1705 lower engine fire/overheat detector system. Issued 9/2/77.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 4th Street Berkeley, CA 94710
737-200C; T.C. A16WE	SA28NW	Interior modification consisting of installation of cargo/passenger partition and coat closet/service tray stowage. Amended 6/29/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA79NW	Seat pallets for Alaska Airlines. Issued 11/9/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA101NW	Interior modification consisting of installation of windscreens and aft coat closet. Issued 4/22/74.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA276NW	Installation of forward LH/RH wind screen in existing approved interior arrangement. Issued 5/13/76.	NW	83765	Vinnedge & Associates P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA337AL	Installation of palletized seating system on high profile cargo roller system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405
737-200C; T.C. A16WE	SA452AL	Installation of palletized cargo/passenger system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405
737-200C; T.C. A16WE	SA492AL	Installation of BE-1006 landing aid system. Amended 12/11/73.	AL	85890	Wien Consolidated Airlines, Inc. 4100 Int'l Airport Road Anchorage, AK 99502
737-201, 737-214; T.C. A16WE	SA1899WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
737-210C; T.C. A16WE	SA3900WE	Installation of heavy duty cargo handling and quick change system, P/N 90045. Issued 4/10/79.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
737-214; T.C. A16WE	SA856CE-D	Installation of two Collins 618T-2 HF radio systems - installation of Bendix "X" band weather radar system - installation of Kollsman Air Data computer. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
737-214; T.C. A16WE	SA1825WE	Installation of Henry Engineering Co. Lounge Tables No. 17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90307
737-222; T.C. A16WE	SA1601WE	Modification of Collins FD109 flight director systems to add a "steering" and "airspeed-hold" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2097WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2182WE	Installation of Bendix Third Attitude Indicator (per requirements of FAR 121.305(j)). Issued 6/10/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2232WE	Replacement of nickel-cadmium battery with 2 lead-acid batteries. Amended 1/28/76.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2525WE	Installation of interior arrangement. Amended 12/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-222; T.C. A16WE	SA3034WE-D	Replace one first class seat assembly with carry-on baggage module, relocate existing garment bag module and remove LH and RH class divider allowing the two modules to serve as class dividers. Issued 1/26/77.	WE	80500	United Air Lines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3360WE-D	Conversion of passenger cabin from 8/85 dual class configuration to 103 seat all coach configuration. Issued 1/5/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3579WE-D	Installation of Arinc Communications Addressing and Reporting System (ACARS). Amended 8/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3946WE-D	Installation of 113-passenger, all-coach seating configuration. Issued 5/30/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3947WE-D	Remove existing galleys, coatrooms and windscreens. Install MAPCO galleys and stowage/service centers. Install a 125-passenger all-coach seating configuration. Issued 7/11/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3948WE-D	Installation of new overhead stowage compartments, ceiling and sidewall panels and lighting systems. Issued 7/11/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-242C; T.C. A16WE	SA2372WE	Installation of Satco, Inc. cargo pallet assembly P/N 31094-501 in conjunction with NAS 3610-2B2N, -2B5N, and 1B2N net assemblies. Issued 7/1/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
737-247; T.C. A16WE	SA191NW	Installation of modified two passenger seat and underseat baggage restraint. Issued 6/15/75.	NW	08350	Air Repair, Inc. 811 West Perimeter Road Renton, WA 98055
737-247; T.C. A16WE	ST551SO	Manufacture and installation of P/N 10816 coat closet unit. Issued May 1974.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST552SO	Manufacture and installation of P/N 10815 cart stowage unit. Issued May 1974.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST567SO	Manufacture and installation of P/N 10949-1 RH aft galley (FS 991.09-1023.25). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST568SO	Manufacture and installation of P/N 10948-1 RH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST569SO	Manufacture and installation of P/N 10950-1 LH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-248C; T.C. A16WE	SA2129WE	Installation of Brownline Division cargo pallet assembly 41121101 and cargo net assembly 41119101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-248C; T.C. A16WE	SA2130WE	Installation of Brownline Division cargo pallet assembly 41120101 and cargo net assemblies: Brownline 22361-51, 22178-51, 41122101, 41123101, AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-275C; T.C. A16WE	SA233NW	Installation of cargo handling equipment for three forward cargo pallet positions. Issued 10/24/75.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737-293; T.C. A16WE	SA2007WE	Installation of header and drape.	WE	62080	Pacific Airmotive Corporation, Inc. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91503

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
737-293; T.C. A16WE	SA2960WE	Installation of galley module in Nordskog galleys P/N's 897 and 898. Issued 12/31/74.	WE	61529	Neushul Corporation 1911 West 139th Street Gardena, CA 90249
737-293; T.C. A16WE	SA3197WE	Installation of auxiliary stowage compartment. Issued 8/17/76.	WE	04080	Air California P.O. Box 2678, Airport Station Oakland International Airport Oakland, CA 94614
747 Series; T.C. A20WE	SA41GL	Install Brooks & Perkins cargo container P/N 17609-E-100. Reissued 2/2/76.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA44NW	Installation of cargo containers. Amended 11/16/76.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747 Series; T.C. A20WE	SA47GL	Install cargo container P/N 17617-E-100. Amended 7/14/75.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA48GL	Install cargo container P/N 17630-E-100. Issued 4/19/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA108NW	Installation of Mark IV visual entertainment system. Issued 4/26/74.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
747 Series; T.C. A20WE	SA139GL	Install Brooks & Perkins cargo container, P/N 17701-E-100. Issued 10/21/76.	GL	17750	Brooks & Perkins 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA255NW	Installation of Xenon light modification in visual entertainment system. Issued 1/26/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
747; T.C. A20WE	SA508NW	Installation of class divider/coat closet assembly. Issued 8/29/77.	NW	48532	KME Manufacturing Company 849 Seneca, S.W. Renton, WA 98055
747 Series; T.C. A20WE	SA689CE	Installation of Brooks & Perkins cargo container, P/N's 17026-100, Type A; 17026-100-1, Type A; and 17083-100, Type A. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA692CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA694CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA702CE	Installation of Bendix standby horizon indicator and inverter.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
747 Series; T.C. A20WE	SA711CE	Installation Brooks & Perkins cargo container.	GL	17750	Brooks & Perkins, Inc. 1950 West Fort Street Detroit, MI 48216
747 Series; T.C. A20WE	SA792CE	Make and install P/N 17455-100 cargo container. Issued August 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747; T.C. A20WE	SA835NW	Installation of storage units at station 617. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA836NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA837NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747 Series; T.C. A20WE	ST867SO	Installation of Bendix ground proximity warning system. Issued 11/4/75.	SO	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
747 Series; T.C. A20WE	SA1435SW	Refrigerated air cargo container for lower lobe. Issued 2/24/72.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747 Series; T.C. A20WE	SA1780SW	Portable solid oxygen system. Issued 1/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
747 Series; T.C. A20WE	SA2334SW	LD-3 cargo container, P/N DCT 1250. Issued 7/20/76.	SW	04250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74115
747 Series; T.C. A20WE	SA2756WE	Modify aircraft by installation of Hermes refrigerated LD-3 cargo container, Koolflite P/N 1000. S/N 8-3-001 only. Issued 9/6/73.	WE	42120	Hermes Enterprises P.O. Box 5141 Sherman Oaks, CA 91413
747 Series; T.C. A20WE	SA2801SW	Install container baggage/freight LD-3 type. Issued 6/19/78.	SW	04250	Air Cargo Equipment Corp. P.O. Box 15630 Tulsa, OK 74112
747 Series; T.C. A20WE	SA3041WE-D	Replacement of NAS3610-2L1C cargo containers with L size pallets and nets. Issued 7/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747SP; T.C. A20WE	SA285GL	Install MAPCO Model 1550 low boy galley. Amended 1/10/79.	GL	54700	Mensfield Aircraft Products Co. Mansfield Lahm Airport Mansfield, OH 44901
747-21; T.C. A20WE	SA34NE	Installation of Aerospace Div. U.O.P. Inc., main deck closet assembly, P/N 402490-1. Issued 4/18/80.	NE	81120	U.O.P., Inc. Aerospace Division Route 202 Bantam, CT 06750
747SP-21; T.C. A20WE	SA1079EA-D	Installation of flight attendant crew berth compartment in the main cabin, zone "B" aft end. Amended 4/17/79.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
747SP-21; T.C. A20WE	SA1080EA-D	Installation of Delco F130A performance management system. Amended 6/30/80.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
747SP-27; T.C. A20WE	SA1174EA	Installation of 16mm movie system in zone B cabin. Issued 10/30/79.	EA	44000	Inflight Motion Pictures Division of Inflight Services, Inc. 175-28 148th Avenue Jamaica, NY 11434
747-2F6B; T.C. A20WE	SA4072WE	Installation of a video projection system. Issued 1/16/80.	WE	15375	Bell and Howell Company Avicom Division 360 Sierra Madre Villa Pasadena, CA 91109
747-E4A, -E4B; T.C. A20WE	SA307GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500. Issued 5/2/79.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
747-SP44, 747-244B; T.C. A20WE	SA3740WE	Installation of main dock cargo/baggage system. Issued 4/19/79.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-E4A, -E4B; T.C. A20WE	SA2951WE	Installation of Steward Davis Airstairs P/N 77004. Amended 3/23/78.	WE	33770	E - Systems, Inc. Greenville, Division P.O. Box 1056 Greenville, TX 75401
747-100; T.C. A20WE	SA817EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A300-001-101. Amended 3/9/71.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA824EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A400-001-101. Reissued 9/8/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA835EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A401-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA842EA	Installation of Goodyear Aerospace Corp. Universal lower deck baggage/cargo container P/N 625A402-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA2117WE	Installation of 747 lower deck modular and unitized baggage/cargo containers.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-100; T.C. A20WE	SA2222WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp. Net Assembly 40234-10, and net assemblies approved to NAS 3610-2AN and NAS 3610-2A3N. Issued 8/16/70.	WE	70250	Satco, Incorporated 1509 El Segundo Boulevard El Segundo, CA 90245
747-100; T.C. A20WE	SA2708WE	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-103. Issued 6/7/73.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747-100 Series; T.C. A20WE	SA3547WE	Installation of cargo container P/N 025-45571	WE	25970	Continental Airlines 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
747-100 Series; 747-200 Series; T.C. A20WE	SA976CE-D	Fuselage structure and related modification for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA977CE-D	Interior modifications for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA978CE-D	Cargo handling and power drive system. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA2646WE	Installation of lock assembly No. 41853-101, -102, -103, -201, -202, -203, -204, -301, -302, -303, -304. Amended 4/20/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200 Series; T.C. A20WE	SA3754WE	Installation of forward and aft lower cargo compartment door sill restraint fittings. Issued 10/9/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, 747-200 Series; T.C. A20WE	SA3813WE	Installation of Brownline side restraint, P/N 44981-101. Issued 12/20/78.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Boulevard Torrance, CA 90505
747-100, -200B; T.C. A20WE;	SA2446WE	Installation of Brownline single pallet lock assembly. Amended 1/3/75.	WE	79500	Tridair Industries Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200B; T.C. A20WE	SA2801WE	Installation of main deck cargo restraint system. Issued 1/16/74.	WE	79000	Transequip Inc. 180 N. Aviation Boulevard El Segundo, CA 90245
747-100, -200B; T.C. A20WE	SA3424WE	Installation of BMA main deck baggage container, P/N 302928. Issued 6/9/77.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-100, -200B, -200C, -200F; T.C. A20WE	SA2845WE	Installation of logo light assembly. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
747-100, -200B, -200C, -200F; T.C. A20WE	SA2895WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100, -200B, -200C, -200F; T.C. A20WE	SA2962WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 12/16/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100 Series, 747-200C, 200F Series; T.C. A20WE	SA3074WE	Installation of 96 x 125 inch animal containers. Amended 11/30/77.	EA	72778	J.D. Smith Air Export, Inc. One World Trade Center Suite 2161 New York, NY 10048
747-100, -200B, -200C, 747SR, 747SP; T.C. A20WE	SA3480WE	Installation of Hughes passenger entertainment/passenger service multiplex system. Issued 11/3/77.	WE	43330	Hughes Aircraft Company Microelectronics Products Div. 500 Superior Avenue Newport Beach, CA 92663
747-100, -200B, -200C, 747SR, 747SP Series; T.C. A20WE	SA3511WE	Installation of stretcher carrier P/N AM2003. Issued 3/21/78.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
747-100, -200B, -200C, -200F; T.C. A20WE	SA3604WE	Installation of Transequip, Inc. auto transponder assembly, P/N 303500. Issued 3/2/78.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-121; T.C. A20WE	SA503EA-D	1) Add additional first class passenger seats and class divider. 2) Add two additional coat closets in Zone C. Issued 5/11/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
747-121; T.C. A20WE	ST714SO-D	Installation of NASA aircraft-to-satellite data acquisition relay (ASDAR) system. Amended 12/14/77.	WE	62300	Pan American World Airways, Inc. J.F.K. International Airport Jamaica, NY 11430
747-121; T.C. A20WE	SA809EA	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-121; T.C. A20WE	SA869EA	Installation of carry-on luggage containers. Issued 4/2/71.	NE	81120	Aerospace Division Universal Oil Products Company Bantam, CT 06750
747-121; T.C. A20WE	SA936EA	Installation of expanded digital flight data recorder system. Amended 4/13/73.	EA	62300	Pan American World Airways Pan Am Building New York, NY 10017
747-121; T.C. A20WE	SA1077EA-D	Installations of Delco F130A flight management system. Amended 8/14/79.	EA	62300	Pan American World Airways, Inc. J.F.K. International Airport Jamaica, NY 11430
747-121; T.C. A20WE	SA2466WE	Installation of AiResearch P/N 216001-401 and -402 class divider - bulkhead assembly. Issued 1/13/72.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121; T.C. A20WE	SA2706WE	Modification by installation of AiResearch coat closed P/N 2130091. Issued 5/30/73.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121; T.C. A20WE	SA3494WE	Installation of Weber Aircraft auxiliary galley, P/N 822767. Issued 9/22/77.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-121, 747-123; T.C. A20WE	SA2444WE	Installation of tables without association with a seating arrangement. Amended 4/27/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
747-121, -122, -238B; T.C. A20WE	SA2823WE-D	Installation of equipment required to conduct NASA/UAL global air sampling program. Amended 11/25/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-121, -123, -273C; T.C. A20WE	SA3007WE	Installation of cargo pallet assembly, P/N 31250-521. Amended 11/19/75.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-121, -132; T.C. A20WE	SA2624WE	Interior arrangement modification. Amended 4/27/78.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121, 747-132; T.C. A20WE	SA3550WE	Installation of Weber auxiliary galley, P/N 822767 Amended 6/1/78.	WE	84900	Weber Aircraft Div. of Walter Kidde & Co., Inc. 2820 Ontario Street Burbank, CA 91510
747-122; T.C. A20WE	SA2193WE	Installation of entree cart 802000, tray cart 803000, liquor cart 804000, and waste cart 805000. Amended 9/2/71.	WE	34220	Fairchild Hiller Corporation Stratos-Western Division 1800 Rosecrans AVenue Manhattan Beach, CA 90266
747-122; T.C. A20WE	SA2658WE	Modification of lower deck cargo compartment restraint system. Issued 3/14/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2717WE	Installation of interior arrangement. Issued 6/26/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2750WE	Modification of aircraft for installation of spacer pallets. Issued 9/7/73.	WE	80500	United Air Lines, Inc. Maint. Base, Engineering Dept. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2821WE-D	Installation of additional service cart retractable tiedowns. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-122; T.C. A20WE	SA2822WE-D	Modified cabin interior configuration. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2829WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco, CA 94128
747-122; T.C. A20WE	SA3352WE-D	Reduced first class seating to 26 seat places, relocated class divider, installed 10-across coach seating - 348 coach seat places. Issued 11/14/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3581WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 11/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3942WE-D	Rework of high frequency communications system to install single-sideband capability. Issued 3/27/80.	WE	80500	United Airlines, Inc. San Francisco Int'l. Airport San Francisco, CA 94128
747-122, -123; T.C. A20WE	SA3066WE	Installation of lower lobe food service modules, P/Ns 810720 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-123; T.C. A20WE	SA2926WE	Modification to incorporate cargo restraint system P/N 43830, configuration -101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-123; T.C. A20WE	SA2928WE	Installation of carrier aircraft crew galley Model FTL 47-1 in the upper lounge. Issued 9/6/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
747-123; T.C. A20WE	SA3016WE	Installation of Brownline cargo systems 44297-101 and 44297-102. Issued 5/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-127; T.C. A20WE	SA2972WE	Modification of lower deck aft cargo compartment restraint system to accommodate NAS 3610 Size A aircraft unit load devices. Issued 12/27/74.	SW	17075	Braniff International Exchange Park Dallas, TX 75235
747-128; T.C. A20WE	SA3436WE	Installation of Brownline cargo system 45600-102. Issued 6/21/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-131; T.C. A20WE	SA715CE	Installation of aircraft integrated data system. Amended 12/12/77.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA728CE	Installation of Hamilton Standard TAT/EPRL System.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA877CE	Installation of expanded parameter flight recorder. Amended April 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA2411WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90248
747-131; T.C. A20WE	SA2755WE	Modification of aircraft for installation of 13-inch beverage carts. Issued 9/4/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-131; T.C. A20WE	SA3491WE	Installation of Brownline cargo system 45747-101. Issued 9/27/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-132; T.C. A20WE	SA3381WE	Installation of Brownline lower lobe cargo system, No. 45478-101. Issued 4/11/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-132; T.C. A20WE	SA3446WE	Installation of Browline cargo system 45600-101. Issued 7/5/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-133; T.C. A20WE	SA1443CE-D	Installation of Type I door, extension of upper deck and interior reconfiguration. Issued 5/20/80.	CE	16878	Boeing Military Airplane Company 3801 South Oliver Wichita, KS 67210
747-135; T.C. A20WE	ST505SO	Manufacture of Nordskog storage units in accordance with Nordskog drawings 1-209, Rev. B and 1-210, Rev. B and their installation in accordance with NAL E.O. P-2350-01 and P-2350-00-06, Rev. B respectively. Issued 5/23/72.	SO	61220	National Airlines, Inc. Box 2055, Airport Mail Facility Miami, FL 33159
747-135, -151, -251B, -251F; T.C. A20WE	SA90GL	Installation of Bendix GPW-83 ground proximity warning system. Amended 6/8/76.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
747-136; T.C. A20WE	SA1144EA	Installation of movie screens in upper deck and 'B' cabin. Issued 4/27/79.	EA	4400	Inflight Motion Pictures, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-136; T.C. A20WE	SA1145EA	Installation of 16 mm movie pallet in 'B' cabin. Amended 3/31/80.	EA	44000	Inflight Motion Picutres, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-136; T.C. A20WE	SA1430CE-D	Installation of a Type I door in the left-hand side of the upper deck fuselage. Amended 11/9/79.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-151, -251B; T.C. A20WE	SA2783WE	Installation of wheeled refrigerated module, P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-200 Series; T.C. A20WE	SA3659WE	Installation of Litton LTN-72R INS/RNAV and/or LTN-72 INS navigation systems in a triple configuration. Issued 6/21/78.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
747-200B, -200C; T.C. A20WE	SA983EA	Installation of Super 8mm IMPAK projector assemblies, P/N's 10304 ("A" Compartment) and 10306 ("C-D-E" Compartment). Issued 6/18/74.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
747-200F; T.C. A20WE	SA190NW	Installation of 29th position pallet/container kit. Issued 6/10/75.	NW	85142	Western Gear Corporation Flight Structures Division 2100 Norton Everett, WA 98201
747-206B; T.C. A20WE	SA1442CE-D	Installation of Type I door, left side, upper deck fuselage. Issued 10/25/79.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-212B; T.C. A20WE	SA4093WE	Installation of a 458, 490, and 514 passenger interior arrangements. Amended 3/28/80.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
747-221F, -246F, -249F; T.C. A20WE	SA3304WE	Installation of Brownline Cargo System No. 45102-101, -103 and -301. Amended 4/26/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-221F; T.C. A20WE	SA4001WE	Installation of Brownline pallet restraint system, P/N 46484-103 and -104. Issued 8/14/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-237B; T.C. A20WE	SA1444CE-D	Installation of type I door (left side, upper deck fuselage) extension of upper deck and interior reconfiguration. Issued 7/25/80.	CE	16878	Boeing Military Airplane Company 3801 South Oilver Wichita, KS 67210
747-238B; T.C. A20WE	ST565SO	Lower lobe right hand module unit, P/N 10892-1 left hand module unit P/N 10893-1 and -101, and lower lobe cupboards unit P/N 68878-1 and -101. Amended 7/1/76.	SO	81130	Aerospace Division of UOP 4856 Victor Street Jacksonville, FL 32207
747-238B; T.C. A20WE	SA570EA	Installation of Universal Oil Products tray cart modules P/Ns 68878, 68879, 68880 in Boeing Model 747-238B. Issued 8/31/71.	NE	81120	Aerospace Division Universal Oil Products Company Bantam, CT 06750

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
747-238B; T.C. A20WE	SA2393WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargc pallet assembly P/N 24076-51 and KAS 3610-2A4P pallet. Issued 8/10/71.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-238B; T.C. A20WE	SA3868WE	Installation of Brownline cargo system 44297 configuration - 104. Issued 1/25/80.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 Lomita Boulevard Torrance, CA 90505
747-245F; T.C. A20WE	SA1032EA	Installation of Collins FPC-75 ground proximity warning system. Amended 3/20/76.	EA	70600	Seaboard World Airlines Seaboard World Building JFK International Airport Jamaica, NY 11430
747-249F; T.C. A20WE	SA4040WE	Installation of Brownline lower compartment cargo pallet restraint system, P/K 45478-102. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-249F; T.C. A20WE	SA4052WE	Installation of Brownline cargo system, 45600-103. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-257B; T.C. A20WE	SA2307WE	Installation of drink trolly 744000. Reissued 8/3/71.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-258B; T.C. A20WE	SA891EA	Installation of inflight motion picture system. Amended 1/11/72.	EA	44000	Inflight Motion Pictures, Inc 175-28 148th Avenue Jamaica, NY 11424
747-284B; T.C. A20WE	SA2791WE	Modification of airplane lower deck aft cargo compartment restraint system. Issued 12/10/73.	EU	61797	Olympic Airways S.A. 96, Syngrov Avenue Athens, Greece
Miscellaneous	SA4-1210	Eonnex cover on aircraft surfaces	WE	33500	Eonair, Inc. Route 1, Box 632 Bakersfield, CA 93308

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BRITISH AEROSPACE, AIRCRAFT GROUP

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH-125; T.C. A3EU	SA350NW	Installation of nose taxi lights. Issued 9/3/76.	NW	60181	Morrison-Knudson Company P.O. Box 7808 Boise, ID 83729
DH-125; T.C. A3EU	SA386NW	Modify all navigation to accept Grimes light mounted in Lord tail light bracket. Issued 12/14/76.	NW	60181	Morrison-Knudson Company P.O. Box 7808 Boise, ID 83729
DH.125 Series; T.C. A3EU	SA4147SW	Install 1, 2, or 3 place side facing seat, frame only. Issued 6/30/80.	SW	28000	Custom Aircraft Conversions 234 West Turbo Drive San Antonio, TX 78216
DH.125, BH.125; T.C. A3EU	SA16GL	Incorporating AMF (Leland) inverters MGE 23-400 or MGE-23-413. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
DH.125, HS.125, BH.125; T.C. A3EU	ST1030SO	Replace existing lead-acid type battery with Teledyne Gill BB639/TE series lead-acid type batteries. Amended 1/18/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
DH.125-1A; T.C. A3EU	SA235EA	Interior bulkhead and door at fuselage station 260.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA236EA	Interior bulkhead and door at fuselage station 391.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA237EA	Two-place seat.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA238EA	Baggage compartment smoke detector system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA239EA	Automatic flight control system. Amended 6/27/67.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
DH.125-1A; T.C. A3EU	SA289EA	Bulkhead and door at fuselage station 391.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA341EA	Bulkheads and bulkhead door. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA342EA	Seat track extensions, inboard and outboard.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA354EA	Bulkheads and bulkhead door. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA366EA	Bulkhead and bulkhead door.	EA	12500	Atlantic Aviation Corporation P.O Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA399EA	Bulkhead and door at fuselage station 258-260. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA432EA	Hydra-electric fuel filter differential pressure switch.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA434EA	Performance of Category II equipment and systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA435EA	Combined ASI/machmeter.	EA	12500	Atlantic Aviation Corporation P.C. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA601EA	Installation of Astek BO 200-81123 combined ASI/machmeter.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH.125-1A; T.C. A3EU	SA858WE	Environmental control system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A; T.C. A3EU	SA859WE	Air conditioning primary feed duct.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A; T.C. A3EU	SA860WE	Pressurization control system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A; T.C. A3EU	SA956WE	SP-40B automatic flight control system.	WE	74570	Sperry Phoenix Company P.O. Box 2529 Phoenix, AZ 85000
DH.125-1A; T.C. A3EU	SA958WE	Supplemental exterior lighting.	GL	42626	Donald E. Hoskins, Inc. 4980 Marine Drive Chicago, IL 60607
DH.125/1A; T.C. A3EU	SA1142WE	Jump seat. Amended 4/9/69.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125/1A; T.C. A3EU	SA1147SW	Main landing gear doors. Issued 5/25/70.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78216
DH.125/1A; T.C. A3EU	SA1166WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DH.125/1A; T.C. A3EU	SA1167WE	System installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH. 125-1A, -3A; T.C. A3EU	SA1176EA	Installation of Solar T-62T-40C APU when Garrett AiResearch TFE-731-3-1H engines are installed in accordance with STC SA3925WE. Amended 6/27/80.	EA	73275	PATS, Incorporated 7190-B Oakland Mills Road Columbia, MD 21046
DH 125-1A/521, 522, DH 125-3A/522; T.C. A3EU	SA1358WE	Installation of combined airspeed and machmeter indicator. Amended 3/3/69.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH 125-1A/522; T.C. A3EU	SA487EA	Installation of bulkhead and door at fuselage station 263 13/16.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH 125-1A/522, -3A; T.C. A3EU	SA486EA	Installation of Bendix radio altimeter antennas.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA335EA	Installation of Collins Radio Altimeter Antennas P/N 437X-1. Amended 5/23/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA385EA	Installation of glide slope antenna at fuselage station 114. Amended 7/1/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA386EA	Installation of HF antenna. Amended 7/1/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA440EA	Installation of ADF sense antenna. Amended 4/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA442EA	Installation of bulkhead and bulkhead door at fuselage station 391.5. Amended 3/12/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA484EA	Installation of under seat deck avionics equipment shelf. Amended 5/25/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA536EA	Installation of Dorne & Margolin DMN 4-7 VOR/LOC antenna. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA543EA	Installation of Bendix PB-60 automatic flight control system. Amended 11/9/71.	EA	16010	The Bendix Corporation Navigation and Control Division Teterbora, NJ 07608
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA716EA	Installation of Sonotone CA9 Nickel Cadmium batteries. Amended 1/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH.125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -3A/RA, -1A/S-522, -400A, BH.125-400A, -600A; T.C. A3EU	SA717EA	Installation of Compudex, Inc. model automatic fuel range computer. Amended 10/3/75.	EA	25760	Compudex, Inc. P.O. Box 93 Norristown, PA 19404
DH.125-1A, -1A/522, -1/R-522, -3A, -3A/R, -1A/S-522, -400A; T.C. A3EU	SA826EA	Replacement of lead-acid batteries with sonotone nickel-cadmium batteries. Issued 6/3/70.	EA	13185	Aviation Aids and Technical Service Company P.O. Box 515 Montreal Int'l Airport Montreal 300, P.Q. Canada
DH.125-1A, -1A/522, -1A/R-522, -1A/S-522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, -600A; T.C. A3EU	SA866EA	Installation of Grimes three light strobe kit P/N 30-0301-1. Amended 5/24/74.	GI	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
DH.125-1A, -1A/522, DH.125-A/R-522, DH.125-3A, DH.125-1A/S-522, DH.125-3A/RA; T.C. A3EU	SA872EA	Replacement of existing Leland inverter type MGE-23-400. Issued 4/21/71.	EA	15800	The Bendix Corporation Electric Power Division Eatontown, NJ 07724
DH-125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -1A/S-522, -3A/RA, -400A; T.C. A3EU	SA740CE	Install three each single phase solid state inverters, a paralleling control, and a warning control unit. Reissued 1/9/78.	CE	24450	Colt Electronics Company 137 West 9th Avenue N. Kansas City, MO 64146
DH-125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -1A/S-522, -3A/RA, -400, HS-125-600A; T.C. A3EU	SA1466CE	Installation of Phoenix Aerospace VR-1010-24-2AD voltage regulators. Issued 12/22/78.	CE	24450	Colt Electronics Company 137 WEst 9th Avenue North Kansas City, MO 64116
DH 125-1A, 1A/522, -1A/R-522, 1A/R-522-3A, -3A/R, -1A/S-522, -3A/RA, -400A, BH 125-400A, -600A, HS 125-600A, -700A; T.C. A3EU	SA2927WE	Installation of logo light on lower surface of horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DH.125-1A, -1A/522, -1A/S-522, -3A, -400A; T.C. A3EU	SA3382WE	Installation of a single-point pressure refueling system. Amended 6/13/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
DH.125-1A, -1A/522, -1A/3-522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, HS.125-700; T.C. A3EU	SA3551WE	Installation of either a single or dual Global GNS-500A VLF/OMEGA navigation system. Amended 6/20/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, -600A, -700A; T.C. A3EU	SA327EA	Installation of retractable seat. Amended 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
DH.125-1A, 3A, 3A/R, 3A/RA, 400A, HS-125-700A; T.C. A3EU	SA857WE	Installation of GTCP30-92 or GTCP30-92C auxiliary power unit. Amended 1/11/78.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A/522, DH.125 Series 3A, 3A/RA, 400A; T.C. A3EU	SA929EA	Installation of No. 2 battery isolation circuit. Amended 1/31/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -3A, -3ARA, DH.125-400A, BH.125-400A; T.C. A3EU	SA1002CE	Relocation of warning cancel switch from instrument panel to #1 engine power lever. Issued March 1974.	CE	15250	Beech Aircraft Corporation P.O. Box 85 Wichita, KS 67201
DH.125-1A/S-522, Series 3A; T.C. A3EU	SA3925WE	Installation of Garrett AiResearch TFE-731-3-1H engines and related changes. Amended 11/21/79.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-1A/S-522-3A; T.C. A3EU	SA4030WE	Installation of Collins APS-80 autopilot. Amended 7/30/80.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
DH 125-1A, -3A, -400A, BH-125-400A; T.C. A3EU	SA4084SW	Pitot heat monitor system. Issued 2/20/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH.125-1A, -1A/522, -3A, -1A/R-522, -3A/R, -1A/S-522, -3A/RA, -400A, HS.125-600A, -700A, B.H.125-400A, -600A; T.C. A3EU	SA4188WE	Installation of IPECO pilot and co-pilot crew seats. Issued 7/16/80.	WE	54860	Marcon Associates, Inc. Suite 101 18436 Hawthorne Boulevard Torrance, CA 90504
DH.125-3A/RA; T.C. A3EU	SA602EA	Installation of bulkhead door and bulkhead at fuselage station 263 13/16.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA674EA	Installation of forward and aft bulkheads and doors.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779
DH.125-3A/RA; T.C. A3EU	SA679EA	Installation of bulkhead and bulkhead door at fuselage station 260.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA710EA	Installation of dual Bendix CB-60B compass system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA711EA	Installation of dual Bendix FD-60 flight director system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA712EA	Installation of Bendix 1903718-1 flight director monitor warning system. Amended 7/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA713EA	Installation of Bendix MKA-28C marker beacon receiver system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA714EA	Installation of dual Bendix RNA-26C VHF navigation system with 8RNX-26A glide slope receiver.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA719EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA788EA	Installation of Bendix ALA-51A radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A, -3A/R, -3A/RA; T.C. A3EU	SA457EA	Installation of combined ASI/Machmeter. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A, -3A/R, -3A/RA; T.C. A3EU	SA539EA	Installation of Collins 37P-5 glide slope antenna at fuselage station 114. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125, DH-125-400A; T.C. A3EU	SA355CE	Installation of Hoskins Twilighter Mk III/Mk IIIB high intensity lighting system. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
DH-125, DH-125-400A; T.C. A3EU	SA2404WE	Consolidation of STCs SA355CE and STC 362CE into one STC having MASTER ELIGIBILITY LIST - amended to include improved power supply assembly and subchassis timer assembly for Twilighter MK III high intensity supplementary lighting system. Issued 8/16/71.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
DH-125-400A; T.C. A3EU	SA764EA	Installation of interior furnishings and avionics systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA765EA	Installation of bulkhead and door between fuselage station 249.86 and fuselage station 281.79.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA766EA	Incorporation of entrance area installation.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA767EA	Installation of forward cabin lavatory.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DH-125-400A; T.C. A3EU	SA768EA	Installation of a two place, side facing divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA769EA	Installation of Kollsman combined ASI/Machmeter A39469-10036.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA770EA	Installation of United Controls angle of attach system. Reissued 12/18/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA793EA	Installation of Litton skyphone system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA831EA	Installation of three Flite-Tronics PC-17 static inverters and one Jet Electronics & Technology, Inc. emergency power supply, Model PS-800. Issued 6/24/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA833EA	Installation of electric elevator trim system. Amended 4/12/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA1981WE	Installation of Sperry Model SP-40C automatic flight control system (P/N 1782874-512). Amended 11/28/69.	WE	74570	Sperry Slight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 95027
DH-125-400A; T.C. A3EU	SA2066WE	Category II system and equipment approval of Sperry Models SP-40 automatic flight control system P/N 1782874-512, and SPI-60 integrated instrument system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 85027
DH. 125-400A, BH. 125-400A; T.C. A3EU	SA1173EA	Rework of Solar T-62T-39 APU installed by STC SA674CE when Garrett AiResearch TFE-731-3-1H engines are installed. Issued 10/25/79.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125-400A, BH.125-400A; T.C. A3EU	SA3870WE	Installation of Garrett AiResearch TFE-731-3-1H engines and related changes. Issued 2/28/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, BH.125-400A; T.C. A3EU	SA4009WE	Installation of Collins APS-80 autopilot. Issued 8/9/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH 125 Series 400A, BH 125 Series 400A; T.C. A3EU	SA4116WE	Modification of a previously approved Micrcturbo APU Model 024 type "Saphir4" installation. Issued 3/10/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH-125-400A, BH-125-400A, DH125-1A/S-522; T.C. A3EU	SA4115WE	Installation of light dump baulk system. Issued 3/11/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, DH.125-3A/RA; BH.125-400A; T.C. A3EU	SA844EA	Installation of Teledyne Avionics angle of attack system. Reissued 7/1/76.	EA	78000	Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906
DH.125-400A, DH-125-3A/RA; BH.125-400A; T.C. A3EU	SA857EA	Installation of Microturbo, Inc. auxiliary power unit Model 024, type "Saphir 4." Amended 4/2/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; BH.125-400A, -600A, HS.125-700A; T.C. A3EU	SA674CE	Installation of Solar Model T-62T-39Y or -39 or -40C auxiliary power unit modifications. Amended 5/23/80.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH. 125-1A, -3A, -400A, HS. 125-600A, -700A, BH. 125-400A, -600A; T.C. A3EU	SA1175EA	Installation of access doors. Issued 11/19/79.	EA	73275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125, HS.125 Beechcraft; T.S. A3EU	ST1003SO	Replace existing lead-acid batteries with Gill BB638/T1-E lead acid batteries, part numbers BSI 200 left and BSI 200 right Issued 6/23/78.	SO	15100	The Battery Shop, Inc. P.O. Box 17312 Nashville, TN 37127
DH-125-400A, HS 125-600A; T.C. A3EU	SA786EA	Installation of lavatory door and bulkhead at station 392. Amended 7/19/76.	EA	07498	AiResearch Aviation Company 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BH125-400A; T.C. A3EU	SA1413SW	Three Flite-Tronics static inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
BH125-600A; T.C. A3EU	SA1888SW	Collins flight control system FCS-105. Issued 6/21/74.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
BH125-600A; T.C. A3EU	SA1923SW	Solar T62T-39 turbine auxiliary power unit. Issued 1/17/75.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
BH125-600A; T.C. A3EU	SA1948SW	Teledyne Avionics normalized angle of attach indicating system P/N 112B900. Amended 9/14/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
BH125-600A; T.C. A3EU	SA2271SW	Interior. Issued 10/27/76.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203
HBH/HS.125-600A, HS.125-700A; T.C. A3EU	SA1101EA	Installation of GNS-500A VLF/Omega system. Amended 5/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS.125-600A, BH.125-600A, HS.125-700A; T.C. A3EU	SA3705WE	Installation of Garret AIRNAV 200 or an AirNav 300 area navigation system. Amended 3/5/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA1074EA	Installation of bulkhead and door at F.S. 391.5 Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. 3EU	SA1075EA	Installation of forward baggage and avionics compartment. Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1104EA	Installation of oxygen system. Issued 6/7/78.	EA	44035	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A3EU	SA1105EA	Installation of Collins VHF 251 standby communication. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A36EU	SA1106EA	Installation of baggage compartment structural entrance area for use with drawer jump seat. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1107EA	Installation of aft cabin bulkhead and door installation. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1108EA	Installation of avionic equipment rack - washroom. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1109EA	Installation of air distribution system. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1110EA	Installation of emergency lighting system to meet the retroactive requirements of FAR 25.2. Amended 10/25/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1111EA	Installation of Wulfsberg III B flitefone. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1112EA	Installation of nose gear taxi lights. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada

Aircraft Make, Mcdel & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
HS. 125-700A; T.C. A3EU	SA1113EA	Installation of general lighting. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1114EA	Installation of cabin lining. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1115EA	Installation of Jet AI-804 emeregency horizon. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1116EA	Installation of forward cabin bulkhead LHS and RHS. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A3EU	SA1117EA	Installation of dual Collins ADS-80F air data system. Reissued 7/26/78.	CE	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1118EA	Installation of Collins FGS-80 flight director system with FD 109 instruments. Amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1119EA	Installation of a single Collins ADS-80F air data system. Reissued 7/26/78.	CE	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1120EA	Installation of a side facing single seat. Issued 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS.125-700A; T.C. A3EU	SA1140EA	Installation of a three place side facing divan, aft cabin left hand side. Issued 1/19/79.	EA	44034	Innstech Aviation Limited Montreal International Airport Dorval, Quebec Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1183EA	Installation of bar galley unit. Issued 2/8/80.	EA	44034	Innotech Aviaiton Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1184EA	Installation of Collins WXR-300 color radar system and the Collins RNS-300 radar navigation system. Amended 4/25/80.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
HS 125-700A; T.C. A3EU	SA1196EA	Installation of solar T-62T-40C APU with 400 ampere starter-generator. Issued 5/29/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
HS-125-700A; T.C. A3EU	SA1538CE	Modification of aircraft to incorporate a fuel management computer. Issued 12/4/79.	CE	24540	Colt Electronics Company 131 West Ninth Avenue North Kansas City, MO 64116
HS.125-700A; T.C. A3EU	SA3552WE	Installation of Delco C-IVA inertial navigation system. Issued 1/13/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS. 125-700A; T.C. A3EU	SA3663WE	Installation of Foxboro engine fuel flow and totalizer system. Issued 6/19/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS. 125-700A; T.C. A3EU	SA3690WE	Installation of a Garrett/ AiResearch GTCP36-100 APU in the tail compartment. Issued 6/30/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3878WE	Installation of Eldec engine fuel flow and totalizer system. Issued 3/8/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3885WE	Installation of dual Global GNS-500A VLF/Omega navigation system. Issued 4/16/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
HS.125-700A; T.C. A3EU	SA3984WE	Installation of dual Litton LTN-211 ONS. Reissued 3/21/80.	WE	51500	Litton Aero Products, Inc. 6700 Eton Avenue Canoga Park, CA 91303

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
HS.125-700; T.C. A3EU	SA4021SW	BKM 100 PHM 700 pitot heat monitor system. Issued 7/24/79.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
HS. 125-700A; T.C. A3EU	SA4042SW	Relocation of center point pressure refueling system. Issued 9/26/79.	SW	11670	Arkansas Modification Center P.O. Box 3356 - Adams Field Little Rock, AR 72203
HS 125-700A; T.C. A3EU	SA4078SW	Install BKM specific range computer system (SRCS). Issued 1/25/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75234
HS.125-700A; T.C. A3EU	SA4152SW	Jump seat. Issued 7/9/80.	SW	11670	Arkansas Modification Center P.O. Box 3356 - Adams Field Little Rock, AR 72203
H.P. 137 Jetstream Mk1; T.C. A21EU	SA275GL	Modification of cabin and cockpit conditioned air and air distrubition system. Issued 11/6/78.	GL	08140	Air Illinois, Inc. Southern Illinois Airport P.O. Box 1224 Carbondale, IL 62901
H.P. 137 MK1 and H.P. 137 as modified STC SA3425WE; T.C. A21EU	SA440SO	Installation of Bendix Model M-4C automatic flight control system (AFCS) and installation of a Bendix M-4DAFCS. Amended 6/21/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
H.P. 137 MK1; T.C. A21EU	SA785EA	Installation of replacement radome P/N 3079KX. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
H.P. 137 MK1; T.C. A21EU	SA815EA	Installation of Compudex, Inc. Model TJ10-HP automatic fuel range computer.	EA	25760	Compudex, Inc. P.O. Box 93 Morristown, PA 19404
H.P. 137 MK1; T.C. A21EU	SA827EA	Relocation of fire-wall fuel and hydraulic system shut-off valves. Amended 6/25/70.	EA	18750	Butler Aviation-Friendship, Inc. Subsidiary of Butler Aviation International, Inc. Friendship Int'l Airport, MD 21240
H.P. 137 MK1; T.C. A21EU	SA1707SW	Three-place side facing couch. Issued 8/1/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA1769SW	Single seat. Issued 12/6/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA2043WE	Installation of instrument panel for day VFR operation.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2074WE	Installation of 18-passenger cabin interior, instruments, and avionics system.	WE	74270	Spartan - Van Nuys 7929 Hayvenhurst Avenue Van Nuys, CA 91406
H.P. 137 MK1; T.C. A21EU	SA2076WE	Installation of Collins AP-104/ FD-109 autopilot - flight director system. Reissued 4/21/70.	CE	24250	Collins Radio Company 5225 "C" Avenue, NE Cedar Rapids, IA 52406
H.P. 137 MK1; T.C. A21EU	SA2115WE	Intallation of observer jump seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2250WE	Relocation of fuel and hydraulic shut-off valves (modification found to comply with requirement of AD 70-15-04, Amendment 39-1031). Reissued 10/24/72.	WE	49850	Lear Avia Corporation P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
H.P. 137 MK1; T.C. A21EU	SA2293SW	P & W AGL PT6A-34 engines. Issued 7/9/76.	SW	46340	Jetstream, Inc. Box 1132 Waco, TX 76705
H.P. 137 MK1; T.C. A21EU	SA3064WE	The installation of an alternate method of complying with AD 72-23-01 by equivalency. Amended 9/23/75.	WE	11354	Apollo Airways 404 William Moffet Road Goleta, CA 93017
H.P. 137 MK1; T.C. A21EU	SA3136WE	Installation of ice shield on fuselage. Issued 1/19/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017
H.P. 137 MK1; T.C. A21EU	SA3281WE	Modification of cabin and cockpit air distribution system. Issued 10/12/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H.P. 137 Mk 1; T.C. A21EU	SA3425WE	Installation of two AiResearch TPE331-3U-303V engines and related changes. Amended 2/2/78.	SW	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101
H.P. 137, MK-1; T.C. A21EU	SA3534WE	Installation of cabin interior arrangement. Reissued 1/16/78.	SW	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101
HP.137 MK1; T.C. A21EU	SA3598WE	Installation of Abex P/N 40161 Model AP05V-060 hydraulic pump in lieu of original Vickers hydraulic pump. No installation data required. Issued 6/12/78.	WE	71655	Sierra Pacific Airlines 703 Airport Road Bishop, CA 93514
H.P. 137; T.C. A21EU	SA3932WE	Installation of underseat baggage restraint bars. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
B-121 Series 1, 2, 3; T.C. A22EU	SA308EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
B-121 Series 1, 2, 3; T.C. A22EU	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Beagle B.206 Series 2; A11EU	SA667SO	Installation of Bendix Model M-4C automatic flight control system.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
B206; T.C. A11EU	SA683SO	Installation of Goodrich wheels, brakes, and tires on main landing gears.	SO	58700	Miami Aviation Corporation Hangar 102, Opa Locka Airport Opa Locka, FL 33054

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BRITISH AIRCRAFT CORPORATION, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BAC 1-11; T.C. A5EU	SA514EA-D	Install Butler Vector Analog Computer System to provide area navigation capability. Amended 11/17/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11; T.C. A5EU	SA279NW	Interior arrangement. Issued 4/30/76.	NW	01700	AeroAmerica, Inc. 7777 Perimeter Road Seattle, WA 98108
BAC 1-11; T.C. A5EU	SA634SW	Litton low range radio altimeter.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA660SW	Cockpit voice recorder A-100 and control panel A-152.	SW	17075	Braniff International P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA792SW	Relocation of LAS 109C flight recorder.	SW	17075	Braniff Airways Love Field Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA973WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
BAC 1-11; T.C. A5EU	SA1213WE	Fairchild A113 cockpit voice recorder and A152A control panel.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11; T.C. A5EU	SA1350SW	Installation of center wing tank fuel system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1432SW	Installation of Collins INS-61B inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1740SW	Install dual Delco Carousel IV or IVA inertial navigation systems. Reissued 4/18/80.	WE	78490	Tiger Air, Inc. 1888 Century Park East Los Angeles, CA 90067
BAC 1-11; T.C. A5EU	SA1761SW	Dual Collins INS 61B inertial navigation systems. Reissued 3/20/74.	GL	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11; T.C. A5EU	SA2365SW	Modification of Marston heat exchanger. Issued 10/5/76.	SW	52068	LORI 501 South Lansing Tulsa, OK 74120
BAC 1-11; T.C. A5EU	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, and EL-104B in emergency slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
BAC 1-11; T.C. A5EU	SA2709SW	Installation of heat exchanger. Issued 1/23/78.	SW	52068	LORI 510 South Lansing Tulsa, OK 74120
BAC 1-11, 200 Series; T.C. A5EU	SA1200EA	Installation of cabinet assembly. Issued 7/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
BAC 1-11, 200 Series; T.C. A5EU	SA1947WE	Installation of underseat baggage restraint system. REissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
BAC 1-11, 200 Series; T.C. A5EU	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
BAC 1-11, 200 Series; T.C. A5EU	SA3616WE	Installation of single LTN-51 or LTN-72 inertial navigation system. Issued 3/27/78.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2261WE	Installation of inflatable emergency evacuation slides at forward passenger and service doors. Amended 7/14/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2306WE	Installation of emergency exit lights at forward passenger door, at forward service door, and at both overwing emergency doors. Issued 1/15/71.	WE	44266	International Inflatables Company Div. Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2722WE	Modify aircraft by installation of wing mounted emblem lights. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2813WE	Structural modifications. Amended 7/15/74.	GL	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11, 200, 400; T.C. A5EU	SA4143SW	Pitot heat monitor system.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
BAC 1-11 203/AE, 204/AF, 215/AU; T.C. A5EU	SA1021EA	Installation of Collins FPC-75 ground proximity warning system and Bendix ALA-51A radio altimeter system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
BAC 1-11 204/AF, 215/AU; T.C. A5EU	SA840EA	Installation of Technical Standard Order inflatable escape slides. Amended 2/17/71.	EA	07250	Air Cruisers Company Division of Garrett Corporation P.O. Box 180 Belmar, NJ 07719
BAC 1-11 400 Series equipped with Rolls Royce RB 163-25 Spey 511-14 engines; T.C. A5EU	ST846SO	Increase maximum ramp weight to 89,000 lbs., increase maximum takeoff weight to 88,500 lbs. and decrease maximum landing weight to 77,200 lbs. Issued 7/1/75.	SO	37885	Bruce Gilman P.O. Box 1372 Vickksburg, MS 39180
BAC 1-11 400; T.C. A5EU	SA3439WE	Installation of single or dual Litton LTN-51 inertial navigation systems. Issued 7/22/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91367
BAC 1-11, 401/AK; T.C. A5EU	SA403EA-D	Interior configuration - change from 69 passenger all coach to 16 first class and 49 tourist class with class divider and curtain installation between two sections.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA408EA-D	Installation of maintenance/flight data recording system. Amended 7/19/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA422EA-D	Installation of dual Collins AL-101 low range radio altimeter.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA449EA	Cockpit voice recorder.	EA	60092	Mohawk Airlines, Inc. Oneida County Airport Utica, NY 13503
BAC 1-11, 401/AK; T.C. A5EU	SA553EA-D	Installation of autopilot go-around unit on BAC 1-11. Amended 10/6/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 410AK; T.C. A5EU	SA554EA-D	Install underseat luggage retention device. Amended 12/4/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11 410AK; T.C. A5EU	SA555EA-D	To comply with FAR 25.812(e), a lever lock switch will be installed at a point accessible seat. Amended 4/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA2860WE	Installation of executive interior. Amended 7/15/74.	WE	07500	AiResearch Aviation Corporation 6201 W. Imperial Highway Los Angeles, CA 90045
BAC 1-11, 401/AK; T.C. A5EU	SA2971WE	Installation of maximum 1565 gallon auxiliary fuel tanks in forward and aft cargo compartment. Amended 2/12/80.	WE	06750	Aircraft Tank Service, Inc. 10201 Conasset Street Burbank, CA 91505
BAC 1-11 401/AK; T.C. A5EU	SA3431WE	Installation of two couches in aft of aircraft. Issued 6/15/77.	WE	62083	Pacific American Airlines 2800 Clybourn Avenue Burbank, CA 91510

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB, 422/EQ; T.C. A5EU	SA1995WE	Installation of auxiliary fuel tanks in forward and aft cargo compartments. Amended 12/6/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB; T.C. A5EU	SA2776WE	Installation of dual Litton, LTN-51 inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11, 401AK, 410AQ, 412A/EB, 414EG, 419EB, 422EQ; T.C. A5EU	SA2873WE	Installation of a single or dual Litton, LTN-104, area navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EP; T.C. A5EU	SA3567WE	Installation of single or dual Litton LTN-51 or LTN-72 INS. Issued 3/17/78.	WE	51500	Litton Aero Products Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
BAC 1-11, 412A/EB Series, 422EQ; T.C. A5EU	SA2911WE	Installation of relocated engine water injection storage tank. Amended 2/20/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
BAC 1-11, 414EG; T.C. A5EU	SA3819WE	Installation of 1478 gallon auxiliary fuel tank system in the forward and aft cargo compartments. Issued 1/25/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
140 Series; T.C. 768, 5A2	SA4-79	Recovering of wings with metal .020 aluminum 2024-T3 clad.	NW	61780	Francisco Ochoa 4836 E. Mercer Way Mercer Island, WA 98040
140 Series; T.C. 768, 5A2	SA4-376	Lycoming O-235-C1 engine.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
140 Series; T.C. 768, 5A2	SA105GL	Install a pitot-static tube. Issued 1/16/76.	RM	48529	Lowell Kleven P.O. Box 1279 Jackson, WY 83001
140 Series; T.C. 768, 5A2	SA175WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	70614	Seagull Aviation P.O. Box 104 Brigham City, UT 84302
140 Series; T.C. 768, 5A2	SA267SW	Continental O-200-A engine and a McCauley 1A100 MCM propeller.	SW	74850	S & S Pipeline Patrol P.O. Box 787 Dickinson, TX 77539
140, 140A; T.C. 5A2	SA547EA	Installation of Continental O-200-A engine and McCauley 1A100 MCM6952 or 1A101/DCM6952 propeller. Amended 7/2/80.	EA	52542	John T. Lucas & M. David Emmett RD #2 Emporium, PA 15834
140, 170, 172, 175, 180; T.C. 768, 5A2, 799, 3A12, 3A17, 5A6	SA1-252	Safety gear Model A.	EA	37140	Geiss Gears, Inc. 3350 Tennyson Street, NW Washington, D.C. 20015
140, 150, 170, 172, 175, 180, 182, 185, 210; T.C. 768, 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21	SA12WE	Fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
140, 150, 172 Series: T.C. 768, 5A2, 3A19, 3A12	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
140, 150, 170, 172, 175, 180, 182, 210 Series; T.C. A768, 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A21	SA596EA	Installation of electronic voltage alarm Drawing No. 80104.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
140A; T.C. 5A2	SA323GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
140A, 150, 170, 172, 175, 180, 182, 185, 206, 210, 207, 305; T.C. 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, A4CE, 3A21, A16CE, 5A5, 3A14	SA995SW	Increase wing leading edge radius wing tip fairings, and landing light lens. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
140A, 150, 170, 172, 175, 177, 180, 182, 185, 206, 210, 207, 305 Series; T.C. 3A17, 5A6, 3A13, 3A24, A4CE, 3A21, A16CE, 5A2, 799, 5A5, 3A19, 3A12, 3A14	SA1371SW	Wing leading cuff, wing tips and upper surface flow fences. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
140A, 150, 170, 172, 175, 180, 182, 185, 206, 207, 210, 305 Series; T.C. 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, A4CE, A16CE, 3A21, 5A5	SA1474SW	Installation of "NASA" 1223000-7 and -8 wing tip. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
150 Series; T.C. 3A19	SA1-479	Aero control AP and heading lock GD.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109
150 Series; T.C. 3A19	SA1-630	Dry vacuum pump and instrument vacuum system 113A5.	GL	03760	Airborne Mechanisms Division Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
150 Series; T.C. 3A19	SA4-965	Autopilot. Peissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150 Series; T.C. 3A19	SA4-1342	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
150 series; T.C. 3A19	SA4-1373	Brake blocks AB-6531 and AB-6532.	EA	46748	Johns-Manville Corporation 22 E. 40 Street New York, NY 10001
150 Series; T.C. 3A19	SA17WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	64275	Peterson Aviation 3100 Airport Avenue Santa Monica, CA 90406
150 Series; T.C. 3A19	SA164WE	Fuel filter PFF-100.	WE	64600	Pioneer Aero Service P.O. Box 227 Burbank, CA 91500
150 Series; T.C. 3A19	SA534CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
150 Series; T.C. 3A19	SA607SW	AK193 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
150 Series; T.C. 3A19	SA1433WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
150, 172, 175, 180, 182, 310; T.C. 3A19, 3A12, 3A17, 5A6, 3A13, 3A10	SA1-124	Lube oil filter BP55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
150, 170, 172, 175, 180, 182; T.C. 3A19, 799, 3A12, 3A17, 5A6, 3A13	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
150, 170, 172, 175, 180, 182, 185, 210; T.C. 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21	SA220SO	Tow bar, release mechanism, and safety tow link.	SO	37092	Gasser Banners, Inc. P.O. Box 3502 Metropolitan Airport Nashville, TN 37217
150, 180 Series; T.C. 3A19, 3A13	SA270SO	Water and ice detector in fuel gascolator and carburetor.	SO	71545	Charles B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
150, 170, 172, 177, 180, 182; T.C. 3A19, 3A12, 799, 5A6, 3A13, A13CE	SA316SO	Carburetor ice detector. Amended 8/31/66.	SO	71545	C.B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
150, 170, 172, 175; T.C. 3A19, 799, 3A12, 3A17	SA971WE	Installation of Jasco 76540 (35a.) alternator kit or Jasco #6555 (50a.) alternator kit. Amended 10/29/76.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M, 170B, 172, 172A, B, C, D, E, F, G, H, I, K, L, M, 175, 175A, B, C, P172D, 180, 180A, B, C, D, E, F, G, H, J, 182A thru P, 185, 185A, B, C, D, E, A185E, A185F, 210, 210A, B, C, D, 205, 205A; T.C. 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A24, 3A21	SA150NW	Installation of flap gap seals. Amended 9/16/75.	NW	16856	B & M Aviation P.O. Box 1563 Bellingham, WA 98225

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150 thru 150M, A150K, L, M; 170, 170A, 170B; 172 thru 172N; 177B; 177RG; 180 thru 180J, K; 182 thru 182Q; 185 thru 185E, A185E; A185F, R172K; 206, P206 thru P206E, TP206A thru TP206E, TU206A thru TU206E, U206 thru U206G; TU206A thru TU206G, TP206A thru TP206E, 207, 207A, T207A, T207; 210 thru 210F; 210K, L, M, T210K, L, M, 336; 337 thru 337F; T337B thru T337F; T.C. 3A19, A-799, 3A12, A13CE, 5A6, 3A13, 3A24, A4CE, A16CE, 3A21, A2CE, A6CE, A20CE, 3A17	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 11/30/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
150, A thru G; 172, A thru H; 175, A, B, C; 177; 180, A thru H; 182, A thru K; 185, A A thru E, A185E; 190; 195 A & B; 206, P206, U206, P206A, U206A, TP206A, TU206A, P206B, TP206B, TU206A; U206B, TU206B, P206C, U206C, TP206C,206C; 210, A thru G, T210-F, -G, 210-5(205)-5A(205A); 336; 337 A, B, C, T337C; T.C. 3A19, 3A12, 3A17, A13CE, 5A6, 3A13, 3A24, 790, A4CE, 3A21, A2CE, A6CE	SA1261WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Subsidiary Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
150, 150A, B, C, D, E, F, G. H, J, K, A150K; T.C. 3A19	SA1346CE	Chrome plate brake disc installation. Amended 9/6/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
150, 170, 172, 175, 180, 182, 185 Series; T.C. 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A24	SA1455WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reid 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
150, 170, 175, 180, 182, 185 Series; T.C. 3A19, A-799, 3A17, 5A6, 3A13, 3A24	SA1473WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
150; 170; 172; 175; 177; 180; 182; 185; 190; 206; 195 Series; 210 Series; 310 Series; 320; 336; 337; 401, 401A, 402, 411, 411A, 421; T.C. 3A19, 799, 3A12, 3A17, A13CE, 5A6, 3A13, A9CE, 790, A4CE, 3A21, 3A10, 3A25, A2CE, A6CE, A7CE	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 6/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
150, 150A thru 150H, J; T.C. 3A19	SA1944WE	Installation of Madras wing tips. Amended 4/23/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
150 thru 150L; T.C. 3A19	SA1977WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
150, 150A thru 150E; T.C. 3A19	SA2053WE	An adjustable lateral trim capability through spring bungee control of aileron per Strato Engineering Company. Reissued 5/23/73.	WE	25940	Consulting Aerospace Engineers 1845 Empire Burbank, CA 91504
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, A150L, A150M; T.C. 3A19	SA2850SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams c/b/a Bush Conversions P.O. Box 431 Udall, KS 67146

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150; 170; 172; 175; 177; 180; 182; 185; 190, 195; 206; 210; 310; 320; 336; 337; 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A19, 799, 3A12, 3A17, A13CE, 5A6, 3A13, A9CE, 790, A4CE, 3A21, 3A10, 3A25, A2CE, A6CE, A7CE	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm)	WE	48750	K S Avionics 18145 Judy Street Castro VAlley, CA 94546
150 thru 150K; T.C. 3A19	SA2119WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
150, 150A thru 150H; 150J, 150K, A150K, 150L, A150L; T.C. 3A19	SA2219WE	Installation of Filtrator Company engine crankcase breather and vacuum pump air-oil separator. Reissued 7/10/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route 1, Box 172D Leesburg, FL 32748
150, 150A thru 150H, 150J, K, L; T.C. 3A19	SA2790WE	Installation of angle of attack indicator. Issued 12/10/73.	WE	78470	Thompson Aircraft Company 8219 Billy Mitchell Drive Santee, CA 92071
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M, 152, L, M, 152, A152; T.C. 3A19	SA3112WE	Installation of flap slot closures. Amended 7/19/77.	WE	78450	Thermal Aircraft Company 56 – 850 Thermal Street Thermal, CA 92274
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M, 152, A152; T.C. 3A19	SA3345WE	Recognition light installation on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
150, 150A, B, C, D, E, F, G, H, J, K, A150L, A150M, 150M, 152, A152; T.C. 3A19	SA4065SW	Metal chip detector in engine oil. Issued 12/4/79.	SW	02323	Aero Logistics International P.O. Box 34395 Dallas, TX 75234
150C, 150D, 15, 150F, 150G, 150H, 150J, 150K, 150L; T.C. 3A19	SA2687WE	Installation of protective device on fuel tank vent line. Issued 5/17/73.	WE	68516	S. Harry Robertson Research Engineers 8002 E. Cypress Street Scottsdale, AZ 85257
150D thru G; 172D thru H; 182A thru L; 206, P206, -A, -B, U206, -A, -B, TU206A, -B, TO206A, -B; 210, D thru F, T210F; 310 D thru P; 320 D, E, F; 337A; 411; T.C. 3A19, 3A12, 3A13, A4CE, 3A21, 3A10, 3A25, A6CE, A7CE	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs SA603SW, SA606SW, SA607SW, SA621SW, SA624SW, SA637SW, SA667SW, SA669SW, SA675SW, SA681SW, SA709SW, SA727SW, SA737SW, SA789SW, SA795SW, SA658SW, SA668SW.	SW	60000	EDO-AIRE Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
150D thru H, J, K, L, M, A150K, A150L; M; T.C. 3A19	SA1809WE	Installation of one twelve-gallon auxiliary fuel tank in each outboard wide panel. Amended 4/20/77.	WE	37580	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
150D thru 150K; T.C. 3A19	SA2191WE	Installation of recontoured wing leading edge, stall fences, and drooped ailerons in flaps down mode. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98004
150D thru H, J, K, L, M, A150K, A150L; M; T.C. 3A19	SA2192WE	Installation of recontoured wing leading edge, stall fences, and drooped ailerons in flaps down mode. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
150, 150D thru H, 150J, K, L, M; T.C. 3A19	SA3037SW-D	Automatic flight system AK457 consisting of Century I autopilot with optional omni tracker. Issued 1/17/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
150D, E, F, G, H, J, K, L utility category; T.C. 3A19	SA3733WE	Installation of a special door (right hand side only) to facilitate aerial photography. Issued 9/6/78.	SW	26718	Robert M. Craig 131 Burwell Road Highland, TX 77562
150E, F, G; 172 thru 172D, F, G, H, M; 175A, B, C; 177; 180A thru H; T.C. 3A19, 3A12, 3A17, A13CE, 5A6	SA1431WE	Installation of rudder trim system. Amended 4/2/78. tive flight control sealed drawings. Amended 3/15/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
150F; T.C. 3A19	SA287GL	Installation of Lycoming O-320-D2B engine and McCauley Model 1C172/TM propeller using the existing installation hardward on an aircraft previously modified in accordance with STC SA572CE. Issued 12/15/78.	GL	71505	Max L. Shanklin 1769 Rooker Road Mooresville, IN 46158
150F, G, H, J; T.C. 3A19	SA221GL	Installation of wheel replacement type skis, FluiDyne all metal (TSO approved) Model A2000A main skis, FluiDyne Model AT2000A tail ski. Issued 2/14/78.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
150F thru K; T.C. 3A19	SA2035WE	Installation of Aerial photographic camera kit serial No. 101. Amended 7/17/70.	NW	34824	Federal Water Pollution Control Administration Pacific Northwest Water Laboratory 200 S.W. 35th Street Corvallis, OR 97330
150F, G, H, J, K; T.C. 3A19	SA2846SW	Conversion from trigear to conventional gear configuration and reconversion to trigear. Issued 9/8/78.	SW	28000	Custom Craft, Inc. 234 West Turbo Drive San Antonio, TX 78216
A150K, A150L; T.C. 3A19	SA1395SW	Revise fuel and oil system for inverted flight. Issued 11/24/71.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
152, 152A; T.C. 3A19	SA4057WE	Installation of a muffler and exhaust heat exchanger. Issued 4/16/80.	WE	35725	Flight Research, Inc. Hangar 61, Mojave Airport Mojave, CA 93501
A152; T.C. 3A19	SA1384CE	Install Lycoming O-320-E2D engine and McCauley 1C172TM7458 propeller. Issued 11/11/77.	CE	12777	Avcon Industries 1006 W. 53rd Street N. Wichita, KS 67204
170 Series; T.C. 799	SA1-13	Recovering of wings with metal except ailerons and flaps.	GL	37182	General Aviation, Inc. P.O. Box 232 Lost Nation Airport Willoughby, OH 44094
170 Series; T.C. 799	SA1-107	69A103 gyro stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
170 Series; T.C. 799	SA1-240	Lycoming O-435-C engine and Hartzell HC-12X20-8D/8433-6 or HC-12X20-5C/8433-6 propellers.	NE	37050	Fulton Conversion Company Southbury, CT 06488
170 Series; T.C. 799	SA1-245	Lycoming O-340-A1A engine and Hartzell HC-82XL-1D/8433-12 propeller on aircraft with Edo 89-2000 floats.	NE	79952	Turner Aviation Company, Inc. Turner, ME 04282
170 Series; T.C. 799	SA1-316	Dart I-M turn control unit.	EA	61400	Navigation Devices, Inc. P.O. Box 1107 Binghamton, NY 13902
170 Series; T.C. 799	SA1-416	Lube oil filter. Amended 9/11/67.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
170 Series; T.C. 799	SA1-647	Leading edge landing lights.	EA	72100	Skycraft Design, Inc. Mercer County Airport West Trenton, NJ 08628
170 Series; T.C. 799	SA3-53	Model 3000 main and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-159	C-3000 main and AWT 2500A or CT-3000 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-329	C-3000 main ski and AWT 2500A tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-339	C-3000 wheel ski on airplanes having a cross-wind wheel utilizing a 6.00-6 tire.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-451	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1504 Gretchen Wichita, KS 67202
170 Series; T.C. 799	SA3-695	Dacron fabric on wings.	GL	30518	Downer Aircraft Company Alexandria, MN 56308

Pages 12 and 13 missing.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170A, 170B (landplanes, normal category only); T.C. A-799	SA806CE	Installation of Lycoming engine model O-360-A1A and McCauley propeller model HC-C2YK-1B/7666A-2. Amended September 1976.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 Wichita, KS 67204
170A, 170B; T.C. 799	SA989CE	Installation of STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
170A, 170B; T.C. A-799	SA1073CE	Installation of wing leading edge cuffs, Cessna drooped wing tips, stall fences, and aileron gap seals. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
170A, 170B (Normal Category): T.C. A-799	SA2454WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
170A, 170B (landplane only normal category); T.C. A-799	SA3797WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision, muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29075	Del-Air P.O. Box 746 Strathmore, CA 93267
170A, B, 172A thru 172M, 175, 175A thru 175D; T.C. A-799, 3A12, 3A17	SA115NW	Modification of R.H. Door and the addition of a jump seat. Issued 5/24/74.	NW	18260	Charles P. Bunch 1211 Donovan Avenue Bellingham, WA 98225
170A, B, 172, 172A thru 172I, K, L, M, N, 175 thru 175C; R172K, 172RG; T.C. 799, 3A12, 3A17	SA1614WE	Installation of one 12-gallon auxiliary fuel tank in each outboard wing panel. Amended 6/27/80.	WE	35746	Flint Aero 336 Front Street El Cajon, CA 92020
170B; T.C. 799	SA111NW	Installation of McCauley 1A175-DM propeller with Cessna 0550162 spinner on Continental C-145 series and O-300 series engines. Reissued 6/28/74.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98026
170B; T.C. 799	SA602AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA602AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	AL	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA603AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA603AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	AK	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA604AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA604AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	·08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA1417SW	Mitchell automatic flight system AK358 consisting of Century I autopilot with optional omni tracker. Issued 1/10/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
170B; T.C. A-799	SA1490CE	Installation of flap and aileron gap seals.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
170B (Landplane only, Normal & Utility Category); T.C. A-799	SA2100WE	Installation of contoured wing leading edge and aileron gap cover. Reissued 1/18/77.	WE	65700	Marshall E. Quackenbush P.O. Box 235 Inyokern, CA 93527
170B; T.C. A-799	SA2851SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
170B (Landplane only, Normal & Utility Category); T.C. A-799	SA3318WE	Installation of flap gap closures. Issued 1/5/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170B, 172 A, B, C, 175, A, B, C, 180, A, B, C, D, F, 182, A, B, C, D: T.C. A-799, 3A12, 3A17, 5A6, 3A13	SA1-612	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
170B, 172, 172A, 172B, 172C, 172D; T.C. A-799, 3A12	SA93EA	Installation of Monitair angle of attack system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
170B; 172, 172A thru H, 175, 175A, B, C, 180, 180A thru H, 182, 182A thru D; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA175EA	Installation of wing struts modified to include Wings With Springs Model 200 hydraulic-pneumatic shock absorbers and associated airframe modifications. Amended 8/17/77.	EA	86500	Wings With Springs, Inc. Box 495, R.D. 3 Latrobe, PA 15650
170B, 172, 172A, B, C, D, E, F, G, H, I, K, L, M, 172M, 175, 175A, B, C; T.C. A-797, 3A12	SA293NW	Installation of Franklin 6A0350-Ce engine, McCauley 2A31C21/84S06 propeller using Kit No. 20690 as per STC SA360EA. In addition, installation of Hartzell HC-C2YF-1BF/F8459-4 to -8 conjunction with same engine. Issued 6/22/76.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98661
170B, 172, 172A; T.C. A-799, 3A12	SA360EA	Installation of Franklin Engine Co., Inc. Model 6A-335-B engine with McCauley 2A31C21/84S-8 propeller and new engine mount and associated components. Amended 6/19/70.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
170B, 172 thru 172L; T.C. A799, 3A12	SA499NW	Installation of Robertson Aircraft STOL kit with Robertson leading edge cuff, fence, Cessna wing flap filler panel. Issued 8/29/77.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98660
170B, 172B thru M, 175, 175A thru C; T.C. A797, 3A12, 3A17	SA637NW	Instllation of AC oil filter assembly OF-104A. Issued 7/13/78.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98661
170B; 180; 185; T.C. 799, 3A24, 5A16	SA1971WE	Installation of Model ARB-3 Automatic Downed Aircraft Marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue, Box 822 Fort Collins, CO 80521
170B, 172, 180, 182, 185, 210 Series; T.C. A-799, 3A12, 5A6, 3A13, 3A24, 3A21	SA4120SW	Add sheet metal flap seals and neoprene flexible aileron gap seals. Issued 5/5/80.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
170, 172 Series T.C. 799, 3A12	SA4-1404	Vacuum system 121 and 121A. (Eligible only on engines with dampened crankshafts).	WE	40685	Marlin and Myron Harms 10828 Burl Avenue
170, 172 Series; T.C. 799, 3A12	SA318WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
170, 172 Series; T.C. 799, 3A12	SA429WE	Exhaust pipe extensions LG-100.	WE	39463	Lloyd M. Green 619 W. Roses Road San Gabriel, CA 91776
170, 172 Series; T.C. 799, 3A12	SA672SW	Cessna 305(L-19) wings.	SW	76737	James A. Summersett, Jr. 418 Redcliff Drive San Antonio, TX 78216
170, 172 Series; T.C. 799, 3A12	SA733WE	12.7-gallon auxiliary fuel tank.	WE	05600	Aircraft Modification and Repair 20331 Hesperian Boulevard Hayward, CA 94541
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA1-426	Auxiliary seat in baggage compartment.	NE	84950	William A. Welch Boyce Road, RD-1 Danbury, CT 06810
170, 172, 175 Series; T.C. 799, 3A12, 3A17	SA1-516	Griswold lateralizer and heading lock.	NE	39800	Herbert Haer 80 Federal Street Boston, MA 02109
170, 172, 175 Series; T.C. 799, 3A12, 3A17	SA1-545	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
170, 172, 180, 182 Series; T.C. 799, 3A12, 5A6, 3A13	SA3-75	Grimes rotating anti-collision light D-7080-1-12.	GL	59360	Mid States Aviation Corporation Sky Harbor Airport Northbrook, IL 60062

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
170, 172, 175, 180 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA3-333	Installation of Doyn fiberglass wheel fairings. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170, 172, 175, 180 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA4-367	Super automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
170, 172, 175, 180 Series; T.C. 799, 3A12, 3A17, 5A6	SA4-620	Baggage door on left side of fuselage.	WE	08262	The Air Oasis 2601 E. Spring Street Long Beach, CA 90801
170, 172, 180, 182; T.C. 799, 3A12, 5A6, 3A13	SA4-662	Camera pod.	WE	52710	Clifton G. McBride 620 Rollingwood Drive Vallejo, CA 94590
170, 172, 175, 180, 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA4-676	RDF-2 radio direction finder.	WE	70275	Savage Industries, Inc. 3125 N. 29 Avenue Phoenix, AZ 85000
170, 172, 175, 180, 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA5-12	Rear canvas hammock seat.	AL	05958	Aircraft Rebuilders 1803 Lake Otis Road Anchorage, AK 99500
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA81WE	Aileron and rudder trim controls.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA158CE	Cessna wing tips and attached lights 1223000-1 left, 1223000-2 right tips, and 1423006-12 left, 0423006-13 right lights, or an equivalent.	GL	70385	Schott Aviation, Inc. Baldwin Field Quincy, IL 62301
170, 172, 175, 180, 182, 185 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13, 3A24	SA238SW	Cargo door. Reissued 4/6/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA765WE	SP51463-1A speedplates.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
170, 172, 180, 182, 185 Series; T.C. 799, 3A12, 5A6, 3A21, 3A24	SA981WE	Two detachable folding rear	WE	59730	Missionary Aviation Fellowship P.O. Box 32 Fullerton, CA 92632
170, 180 Series; T.C. 799, 5A6	SA1-188	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
170, 180 Series; T.C. 799, 5A6	SA3-468	CF-3000 main wheel skis and AWT 2500A or CT-3000 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170, 180 Series; T.C. 799, 5A6	SA463WE	Jump door 62-500.	NW	72250	Skymotive, Inc. Route 1, Box 32 Snohomish, WA 98290
172 Series; T.C. 3A12	SA1-9	69A115 gyro-stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
172 Series; T.C. 3A12	SA1-116	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
172 Series; T.C. 3A12	SA1-438	Lycoming O-360-A1A engine and McCauley 2D36C14/78 KM-4 propeller with Woodward 210105 AA governor.	NE	90160	Albert E. Zotack 295 First Avenue Stratford, CT 06497
172 Series; T.C. 3A12	SA3-11	Propeller installations - Two-position controllable, hub 2B-36C7, blades 78K-2 or 78K-4.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45401
172 Series; T.C. 3A12	SA3-82	Retractable lifting handles Model H, P/N 50-9.	GL	87750	Woychik Aircraft Equipment Middleton, WI 53562
172 Series; T.C. 3A12	SA3-89	Equipment shelves and Grimes D-7080 rotating beacon.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
172 Series; T.C. 3A12	SA3-90	Lear ADF loop and housing.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
172 Series; T.C. 3A12	SA3-107	Rudder trim system.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172 Series; T.C. 3A12	SA3-108	Single axis automatic pilot A-2 or A-3.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
172 Series; T.C. 3A12	A3-126	Lycoming O-340-A1A engine and Hartzell HC-82XG-1DB/8433-12 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172 Series; T.C. 3A12	SA3-179	A3500A or A2500A main skis and NA1200A nose skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-256	Main ski AWB2500A and nose wheel ski AWN1200.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-355	C3000 main ski and AWN1200 nose wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-614	Model 3000 main skis and Model 2000 nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-655	Wheel fairings.	RM	55700	Marsh Flying Club, Inc. 812 E. 34th Street Sioux Falls, SD 57101
172 Series; T.C. 3A12	SA3-690	Installation of Doyn swept-tail asembly kit 1400. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172 Series; T.C. 3A12	SA4-40	Automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
172 Series; T.C. 3A12	SA4-198	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
172 Series; T.C. 3A12	SA4-531	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
172 Series; T.C. 3A12	SA4-602	Autopilot. Reissued October 1973.	WE	17492	Brittain Industries, Inc. 12027 S. Prairie Avenue Hawthorne, CA 90250
172 Series; T.C. 3A12	SA4-686	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
172 Series; T.C. 3A12	SA44SO	Cessna L-19 wing conversion.	SO	55600	Marrs Aircraft Avon Park, FL 33825
172 Series; T.C. 3A12	SA64CE	Sky-lite B-100 beacon light.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
172 Series; T.C. 3A12	SA88CE	C-3000 main skis and AWN-1200A nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA94CE	Removal of right cabin door.	GL	72116	Skylane Flying Service, Inc. 2029 Allens Lane Evansville, IN 47708
172 Series; T.C. 3A12	SA117EA	Flow lube oil filter PB 55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
172 Series; T.C. 3A12	SA242EA	40-0040 and 40-0043 supplemental light system.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
172 Series; T.C. 3A12	SA313SO	Federal FS103 autopilot.	SO	00078	A & E Service McCollum Airport Marietta, GA 30060
172 Series; T.C. 3A12	SA414SW	Jump step or mud guard on right landing gear.	SW	73030	Curtis J. Smith, Jr. Route 2, Box 314 Breaux Bridge, LA 70517
172; T.C. 3A12	SA531NW	Installation of windshield. Issued 10/12/77.	NW	71506	Jack Shannon 215 Terminal Building Boeing Field Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172 Series; T.C. 3A12	SA533CE	Installation of Canairco 1214 WB supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
172 Series; T.C. 3A12	SA603SW	AK191 Century II autopilot and AK192 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172 Series; T.C. 3A12	SA792WE	Lycoming O-360 Series engines and Sensenich M67EMM propellers.	NW	53510	McKinzie Aircraft Repair, Inc. 1300 N. 26 Street Springfield, OR 97477
172 Series; T.C. 3A12	SA861WE	Pilot and passenger restraint harness.	WE	62125	Pacific Scientific Company 1346 S. State College Boulevard Anaheim, CA 92803
172 Series; T.C. 3A12	SA1078WE	Franklin 6A-335-B engine with McCAuley 2A31C/84S-6 propeller using EDO 89-2000 floats.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172 Series; T.C. 3A12	SA1308WE	Installation of Brittain Model CSA-1 stability Augmentation System.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
172 Series; T.C. 3A12	SA1468WE	Installation of Brittain Model B2C Autopilot System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172 Series; T.C. 3A12	SA1677SW	Wing leading edge cuff. Issued 6/20/73.	SW	73850	Southern Aircraft Corporation P.O. Box 78 Page, OK 74939
172 Series; T.C. 3A12	SA1806WE	Installation of Brittain Industries B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172 Series; T.C. 3A12	SA3072WE	Installation of emergency warning system. Issued 7/23/75.	WE	77274	Systems Management Associates, Inc. P.O. Box 957 Palo Alto, CA 94302
172, 172A, B, C, D, E, F, G, H; T.C. 3A12	SA3-571	Lycoming O-360-A1D engine, McCauley 2D36C14/78FM-4 or Hartzell HC-C2YK-1A/7666-2 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172, 172A, B, C, D, E, F; T.C. 3A12	SA3-664	Install Model 113A6, 200CW-6 or 212CW-6 dry vacuum pump and instrument vacuum system. Amended 7/31/79.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
172, 172A thru 172I, K, L, M, N, P; 182, 182A thru 182N, P; T.C. 3A12, 3A13	SA21GL	Installation of Grimes multi-plexed anti-collision light system. Issued 5/9/73.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
172, 172A, B, C, 175, 175A, B, C, 182, 182A thru E; T.C. 3A13, 3A12, 3A17	SA43EA	Installation of Re-Vue Agency "nite-lite" electronic aerial advertising sign. REissued 3/15/71.	RM	67300	Re-Vue Agency, Inc. 616 East 4th Street Pueblo, CO 80204
172, 172A, 172B, 172C, 172D; 180, 180A, 180B, 180C, 180D, 180E, 180F; 182, 182A, 182B, 182C, 182D, 182E; 185, 185A, 185B, 185C, 185D; 210, 210-5, 210A, 210B, 210C; 310C, 310D, 310E, 310F, 310G, 310H; T.C. 3A12, 5A6, 3A13, 3A24, 3A21, 3A10 (310 Series thru 310H Riley conversion per STC SA212SO.)	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
172, 172A, 172B, 172C; T.C. 3A12	SA211GL	Installation of windshield P/N W-2055, W/T-2055 or W/G-2055 on Cessna 172 and 172A, and P/N W-2056, W/T-2056 or W/G-2056 on Cessna 172B and 172C. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
172, 172A, B, C, D, E, F, G, H, I, K, L, M, N; T.C. 3A12	SA296GL	Convert to conventional landing gear. Amended 11/19/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172, 172A, B, C, D, E, F, G, H. I, K, L, M, N; T.C. 3A12	SA315GL	Installation of Fluidyne skis. Amended 2/7/80.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 172A, B, C, D, E, F, G, H, I, K, L, M; T.C. 3A12	SA326GL	installation of fuel tankcaps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
172, 172D, 172K; T.C. 3A12	SA340NW	Installation of Pee Kay Model 2300 floats. Issued 9/15/76.	NW	70620	Seaplane Flying, Inc. P.O. Box 2164 Vancouver, WA 98661
172, 172A, B, C, D, E, F, G, H Landplanes, 172D, E, F, G, H Floatplanes (EDO 89-2000 floats only.) T.C. 3A12	SA420CE	Lycoming O-360-A1A or A1D engine, McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1B/7666-2 propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172, A thru I; T.C. 3A12	SA729EA	Replacement of existing wheel/brake assemblies with Goodyear wheel/brake assemblies 9543679/95444295.	GL	39125	Aviation Products Division The Goodyear Tire & Rubber Company 1144 East Market Street Akron, OH 44315
172, 172A thru I, K, L, M, N (Landplanes, normal category only); T.C. 3A12	SA807CE	Install Lycoming 180 h.p. engine and constant speed propeller. Amended 1/31/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
172, S/N 17254893 and on; T.C. 3A12	SA864CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
172, 172A thru 172I, 172K, 172L, 172M (S/N 17260759 thru 17265684); T.C. 3A12	SA902CE	Install STOL kit. Amended 2/26/80.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
172 thru 172N; T.C. 3A12	SA910CE	Install STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Amended May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
172, 172A, B, C, D, E, F, G, H, I, K, M, N; T.C. 3A12	SA1484CE	Installation of flap and aileron seals. Issued 4/18/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
172, 172A thru 172G (landplanes and float-planes), 172, 172H thru 172L (landplanes only); T.C. 3A12	SA1689WE	Installation of drooped ailerons contoured wing leading edge and wing stall fences. Amended 2/26/71.	NW	68510	Charyl C. Robertson 15209 N.E. 16th Place, Apt. #17 Bellevue, WA 98004
172 thru 172L; T.C. 3A12	SA2002WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
172, 172A thru 172L (normal category); T.C. 3A12	SA2075WE	Installation of Madras Air Service Inc. "Super Tips." Amended 8/16/72.	NW	54000	Madras Air Service, Inc. Route 2, Box 1225 Madras, OR 97741
172, 172A thru 172L, 175, 175A, 180, 180A 180H, 205, 205A; T.C. 3A12, 3A17, 5A6, 3A21	SA2256WE	Installation of leading edge "cuff" on each wing. Amended 4/29/80.	WE	65700	Marshall E. Quackenbush P.O. Box 2421 California City, CA 93505
172, 172A thru 172G; 182A thru 182N, 206, U206, U206B thru U206E; 210 thru T210F; TU206C, D, E; T.C. 3A12, 3A13, 3A21, A4CE	SA2286WE	Installation of wing leading edge cuff. Amended 3/16/72.	RM	09750	Alpine Aircraft Corporation Route 4, Box 173A Greeley, CO 80631
172, 172A, B, C, D, E, F, G, H, I, K, L; T.C. 3A12	SA2852SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
172, 172A, B, C, D, E, F, G, H, I, K, L, M, N (normal and utility categories); T.C. 3A12	SA3105WE	Installation of flapgap fairing. Amended 8/22/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
172, 172A, B, C, D, E, F (T-41), G, H (T-41A), I, K, L, M, N; T.C. 3A12	SA3338WE	Recognition light installation on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172, 172A, B, C, D, E, F, G, H, I, K, L; T.C. 3A12	SA3788WE	Installation of the "liftrol" wing spoiler system. Reissued 6/6/80.	WE	23145	Esther E. Cleaves 4542 Norma Drive San Diego, CA 92115
172, 172A thru H (landplane only, normal category); T.C. 3A12	SA3796WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29075	Del-Air P.O. Box 746 Strathmore, CA 93267
172, F172; T.C. 3A12	SA3418WE	Installation of SDI Novastar II combined position/anticollision lighting system. Issued 6/22/77.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
172A Seaplane; T.C. 3A12	SA181GL	Installation of McCauley 1A200/DFA propeller. Issued 6/16/77.	GL	77569	Les G. Taylor 1115 - 19th Street South St. Cloud, MN 56301
172A, B, C, D, E, F, G, H; T.C. 3A12, 3A17	SA18EA	Wet-to-dry vacuum pump conversion kit 300-1. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
172A thru 172M; T.C. 3A12	SA358NW	Installation of Pee Kay Model 2300 seaplane floats. Issued 8/24/76.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
172A - 172K; T.C. 3A12	SA650CE	Installation of Fleet Model 2500 floats. Reissued 12/21/71.	EA	79550	Trifield Associates 560 Daytona Drive Fort Erie, Ontario, Canada
172B, 172C, 172D, 172E, 172F, 172G; T.C. 3A12	SA116SO	Installation of Franklin Model 6A-335-B engine with 2A31C21/84S-8 propeller and new engine mount and new engine mount and associated components only on landplane models. Amended 9/9/68.	EA	36750	Franklin Engine Company, Inc. Subsidiary of Allied Aero Industries, Inc. Old Liverpool Road Syracuse, NY 13208
172B, 172C; 175 thru 175C; 180 thru 180F; 182 thru 182E; 185, 185A, 185B; 210, 210A, 210B, 210C, 210D, 210E; P206; 310 thru 310E; T.C. 3A12, 3A17, 5A6, 3A13, 3A24, 3A21, A4CE, 3A10	SA232EA	Installation of Tactair omni lock model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair model omni lock model OH-4). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
172B, G, 175A, B, C; T.C. 3A12	SA751EA	Installation of winterization kit. Issued 4/21/69.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
172B thru G; T.C. 3A12	SA1334WE	Installation of Franklin 6A-350-C2 engine and McCauley 2A31C/84S-6 propeller. Amended 9/26/68.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172B thru H; T.C. 3A12	SA1774WE	Installation of Lycoming O-320-E2D engine and McCauley 1C172/MTM7653 propeller.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172D, P172D, 182E, F, 185, 185A, 185B, 210, 210A; 210B, 210C, 210-5; T.C. 3A12, 3A17, 3A24, 3A21, 3A13	SA17EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
172D, E, F, G, H, I, K; T.C. 3A12	SA319GL	Bolen wheel extenders on Cessna models modified per STC SA296GL. Issued 6/12/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172D thru 172K; T.C. 3A12	SA365NW	Installation of Pee Kay Model 2300 seaplane floats. Approval is intended for installation in listed models with Franklin 6A0360-C2 engine installation IAW Seaplane Flying, Inc., STC SA340NW. Issued 10/5/76.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
172D, 172E (seaplane); T.C. 3A12	SA596WE	Installation of Doyn Aircraft Company kit per STC SA3-571. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172, E thru L; T.C. 3A12	SA1221SW	Mitchell automatic flight system AK312 consisting of Century I with optional omni tracker. Issued 11/18/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172D thru 172I, K, L; T.C. 3A12	SA1645SW	Mitchell automatic flight system AK403, consisting of Century IIB autopilot with optional radio coupler. Issued 4/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172D thru 172K Seaplane Versions; T.C. 3A12	SA1694WE	Installation of Franklin 6A-350-C2 engine, McCauley 2A31C/84S-6 propeller, and Aqua Float Corp., Model 2400, or EDO Corp. Model 248B-2440 floats (Columbia Marine, Inc. Kit #106) for operation on wheels, floats or skis @ 2400 lbs. g.w. (Fluidyne Model 3000 main and 2000 nose skis required for ski operations. Amended and reissued 5/1/70.	EA	36750	Franklin Engine Company, Inc. Sub. Allied Aero Industries, Inc. Old Liverpool Road Syracuse, NY 13208
172D, 172E; T.C. 3A12	SA2268WE	Installation of Brittain Industries B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172D, E, F, G, H; T.C. 3A12	SA2375SW	Install Lycoming O-320-D2G engine rated for 160 h.p. take-off and 150 METO. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
172D thru M, 177, 177A, B, 177RG, 182L, M, N, 206, C, U206, U206B, D, E, F, TP206A, B, P206A, B, TU206A, B, C, D, E, F, P206E, TP206E, 210D, E, F, L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE, A20CE, 3A12	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot system. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
172D thru L, 177, A, B, 182L, M, N, 206, U206, B, C, D, E, TU206B, C, D, E, P206A, B, TP206A, B, P206E, TP206E, 210E, D, F, L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE, 3A21	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot system. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
172D, E, F, G, H, I, K, L, M, 177, A, B, 182E thru N, U206C, D, E, F, TU206C, D, E, F, P206E, TP206E, 210, 210D, E, F, L, 210L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE	SA2654WE	Installation of Pathfinder Model P2A( ) autopilot. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Road Torrance, CA 90505
172D, E, F, G, H, I, K, L; T.C. 3A12	SA3046SW-D	Automaticght system AK524 consisting of Century IIB autopilot with optional radio coupler. Issued 3/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172F, G, H, I, K, L; T.C. 3A12	SA1311CE	Chrome plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
172G; T.C. 3A12	SA299GL	Installation of Cessna Nav-O-Matic 200A autopilot. Issued 4/2/79.	GL	37077	Galesburg, AP & L R.R. 2, Airport Galesburg, IL 61401
172H; T.C. 3A12	SA204GL	Installation of Avco Lycoming O-320-E2D engine. Issued 12/16/77.	GL	65326	Professional Aviation, Inc. Porter County Airport 3801 Murvihill Road Valparaiso, IN 46383
172H; T.C. 3A12	SA414NW	Installation of Lycoming O-360-A1F6D engine and McCauley propeller. Issued 3/15/77.	NW	70040	Salem Aviation 2680 Aerial Way S.E. Salem, OR 97302
172I, 172K, 172L; T.C. 3A12	SA87NW	Installation of Lycoming O-360-A1A 180 h.p. engine and Hartzell HC-C2YK-1A/7666A-0 propeller. Amended 12/12/74.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
172I, 172K, 172L, 172M seaplane (normal category only); T.C. 3A12	SA332GL	Installation of Lycmoming O-360-A4A engine and McCauley 1A200/DFA propeller. Amended 5/19/80.	GL	77569	Les G. Taylor 1115 - 19th Street South St. Cloud, MN 56301

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172I and 172K landplanes and seaplanes EDO 89-2000 (floats only), 172L, 172M, 172N (landplanes) (12 volt only): T.C. 3A12	SA647CE	Install Lycoming O-360-A1A 180 h.p. engine and constant speed propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172I, K, M, R172K (floatplane configuration): T.C. 3A12, 3A17	SA665CE	Installation of Model 2400 Aqua floats. Amended 7/10/79.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
172I, 172K, 172L, 172M; T.C. 3A12	SA992CE	Installation of 10-inch diameter camera hole per Product Development Group, Inc. Issued February 1974.	CE	36000	Floair, Inc. Mid-Continent Airport Wichita, KS 67209
172I, 172K, 172L, 172M, 172N (Seaplane): T.C. 3A12	SA1000EA	Installation of Pee-Kay Model 2300 or B2300 (TSO-C27-2) seaplane floats. Amended 7/19/78.	EA	29998	Pee Kay Float Division Devore Aviation Corporation 206 Newton Road Plainview, NY 11803
172I, 172K, 172L, 172M (Landplane): T.C. 3A12	SA1225CE	Installation of Lycoming O-320-E2D/STC SE1226CE or O-320-D2G engine and McCauley 1C160/CTM 7557 or 1C160/DTM 7557 propeller. Amended March 1977.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
172I, 172K thru 172N; T.C. 3A12	SA3777WE	Installation of flexible stainless steel oil cooler hoses. Issued 10/31/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
172I, 172K, 172L, 172M, 172N; T.C. 3A12	SA3858WE	Installation of an air/oil separator. Issued 3/2/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036.
R172K; T.C. 3A17	SA1491CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
172K; T.C. 3A17	SA3824SW-D	Mitchell automatic flight system AK730 consisting of Century I autopilot with optional omni tracking system. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172K, 172M (normal category landplane only); T.C. 3A12	SA2575WE	Installation of observer station in rear seat-baggage compartment area, searchlight and dual speakers in bottom of aft fuselage, windows in baggage compartment area (baggage was removed), and a muffler. Amended 1/4/73.	WE	87465	World Associates, Inc. 430 Wilshire Boulevard Suite 204 Santa Monica, CA 90401
172L; T.C. 3A12	SA494SO	Installation of radio equipment rack in instrument panel. Issued 2/18/72.	SO	18400	Burnside-Ott Aviation Training Center 12800 S.W. 137 Avenue Miami, FL 33156
172L, S/N 17259224 thru 17260758; T.C. 3A12	SA965CE	Installation of Model IU328-001 vacuum pump and IU292-003 suction relief valve. Issued November 1973.	CE	43600	EDO-AIRE Wichita Division 1326 S. Walnut Wichita, KS 67213
172M; T.C. 3A12	SA6NE	Installation of Whelen anti-collision strobe light power supplies, Models HS-41 and HD-42 as direct replacements for Models HS and HD installed in accordance with STC SA615EA or STC SA800EA. Issued 3/21/74.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
172M; T.C. 3A12	SA1798SW	Mitchell Automatic Flight System AK467 consisting of Century IIV Autopilot with optional Radio Coupler. Issued 1/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M; T.C. 3A12	SA1799SW	Mitchell Automatic Flight System AK472 consisting of Century I Autopilot with optional omni tracker. Issued 1/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M; T.C. 3A12	SA2671WE	Installation of upper wing surface face stall fences and aileron gap sealing strips. Issued 3/19/73.	WE	39520	Group One 2915 Earhart Apron Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172M, 172N; T.C. 3A12	SA146GL	Installation of EPA portable enviro pod. Amended 12/10/79.	GL	07696	AFAL/RWF Wright-Patterson AFB, OH 45433
172M, 172N; T.C. 3A12	SA380GL	Installation of Tull microwave landing system airborne equipment. Amended 5/12/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
172M, 172N; T.C. 3A12	SA1402CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172M, 172N; T.C. 3A12	SA3200SW-D	Automaitc flight system AK467 consisting of Century II autopilot with optional radio coupler. Issued 4/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA3201SW-D	Automatic flight sytem AK472 consisting of Century I autopilot with optional omni tracker. Issued 4/7/77.	SW	6000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA4080SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
172M, 180J, 182P, A185F, A188B, 188B, U206F; T.C. 3A12, 3A13, 5A6, 3A24, A4CE, A9CE	SA974EA	Installation of L/R wing tip transparent fairing and sensor mounting bracket. Issued 2/26/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
172N; T.C. 3A12	SA168GL	Install Heath Kit Model 01-1154 aircraft digital clock/timer. Issued 4/28/77.	GL	41610	The Heath Company Hilltop Road Benton Harbor, MI 49022
172N; T.C. 3A12	SA584NW	Installation of Edo 689-2130 seaplane floats. Amended 1/8/80.	EA	32625	Edo-Aire, Seaplane Division 65 Marcus Drive Melville, NY 11746
172N; T.C. 3A12	SA1324CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/7666A-2 propeller. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 North Wichita Station Wichita, KS 67204
172N; T.C. 3A12	SA3301SW-D	Mitchell automatic flight system AK730, consisting of Century I autopilot with optional omni tracking system. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A12	SA3302SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A17	SA3303SW-D	Mitchell automatic flight system AK732 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172RG; T.C. 3A17	SA3363SW	Mitchell automatic flight system AK861 consisting of Century 21 autopilot. Issued 3/14/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P172D; 180D, 180F; 182A, 182A-F; 185, 185A, 185B; T.C. 3A12, 5A6, 3A13, 3A24	SA1696WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
P172D, R172E, R172F, R172G, R172H, R172J, R172K; T.C. 3A17	SA3487WE	Installation of tail flood light. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
R172K; T.C. 3A17	SA460NW	Installation of PeeKay model 2300 or B2300 seaplane floats. Amended 4/20/78.	EA	29998	PeeKay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
R172K Landplane only; T.C. 3A17	SA1437CE	Install rerated Continental IO-360-K engine. Issued 10/6/78.	CE	44802	Brad E. Isham 416 West Fourth Street Valley Center, KS 67147
R172K; T.C. 3A17	SA3227SW-D	Mitchell automatic flight system AK699 consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
R172K; T.C. 3A17	SA3228SW-D	Mitchell automatic flight system AK698 consisting of Century IIB autopilot with optional radio coupler. Issued 8/2/77.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3285SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3286SW-D	Mitchell automatic flight system AK732 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R172K; T.C. 3A17	SA4048WE	Installation of Silver Instruments fueltron IG or fueltron digital fuel flow and totalizer system. Issued 10/24/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
R172K, 175, 175A, 175B, 175C; T.C. 3A17	SA383GL	Convert to conventional landing gear. Issued 1/31/80.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 175 Series; T.C. 3A12, 3A17	SA1-219	Gyro-stabilizer 69A122.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
172, 175 Series; T.C. 3A12, 3A17	SA3-576	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
172, 175 Series; T.C. 3A12, 3A17	SA4-1601	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175 Series; T.C. 3A12, 3A17	SA109SW	Automatic pilot AK106.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA393WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
172, 175 Series; T.C. 3A 4A17	SA411SW	Automatic pitch trim AK 138.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA436EA	New engine, propeller and engine mount. Amended 9/21/67.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
172, 175 Series; T.C. 3A12, 3A17	SA610SW	Lycoming O-320 and O-360 Series engines with Hartzell HC-82XL-7636D-4; HC-C2YK-2R/7666 or HC-92Z-2B/8447-12A propeller.	SW	67650	R.F.B. Company Chandler Field Purcell, OK 73080
172, 175, 180, 182, 310 Series; T.C. 3A12, 3A17, 5A6, 3A13, 3A10	SA4-306	Roto-Nav bracket and Grimes D 7080 anti-collision light on vertical fin.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175, 182 Series; T.C. 3A12, 3A17, 3A13	SA4-893	Installation of wheel fenders on nose gear and main gear. Reissued 2/9/71.	NW	12565	Aurora Air Inc. d/b/a Madras Air Service Madras, OR 97741
172, 175, 180, 182 Series; T.C. 3A12 3A17, 5A6, 3A13	SA10WE	Arens Vernier type throttle control.	WE	82400	Van Nuys Skyways, Inc. 16700 Roscoe Boulevard Van Nuys, CA 91408
172, 175, 180 Series; T.C. 3A12, 3A17, 3A13	SA462WE	Jump door 62-500.	NW	72252	Skymotive, Inc. Route 1, Box 32 Snohomish, WA 98290
172, 175, 182 Series; T.C. 3A12, 3A13, 3A17	SA480CE	Nose and main gear wheel fairings. (Jetstreams) using standing unaltered Cessna landing gear and nose gear for model and year using 500 x 5 nose and 600 x 6 main gear tires.	GL	26750	Creative Designs 1338 Orkla Drive Minneapolis, MN 55427
172, 180; T.C. 3A12, 5A6, 3A13	SA2362WE	Installation of lure toxicant dispenser AEY 70, Model #1. Amended 9/27/73.	NW	03270	U S D A 3706 W. Nob Hill Boulevard Yakima, WA 98902

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
172, 180, 182 Series; T.C. 3A16, 5A6, 3A13	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Company airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
172, 180, 185; T.C. 3A17, 5A6, 3A24	SA271NW	Removal of paper air induction paper. Issued 3/16/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
172, 182 Series; T.C. 3A12, 3A13	SA1-193	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
172, 182 Series; T.C. 3A12, 3A13	SA116EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/63.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
172, 182, 206, 210 Series; T.C. 3A12, 3A13, A4CE, 3A21	SA895WE	Kienzle 65 flight time recorder.	WE	18460	Burrows and Sons 1829 Bridgeport Avenue Claremont, CA 91711
175 Series; T.C. 3A17	SA3-285	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 1405 S. Oliver Wichita, KS 67207
175 Series; T.C. 3A17	SA3-611	Model 3000 main ski and Model 2000 nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
175 Series; T.C. 3A17	SA3-691	Installation of Doyn swept-tail assembly kit 1400. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
175 Series; T.C. 3A17	SA4-547	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
175 Series; T.C. 3A17	SA4-1406	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
175 Series; T.C. 3A17	SA3EA	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
175 Series; T.C. 3A17	SA5WE	Cowl flap.	WE	87473	Thompson International Aviation P.O. Box 68 Hereford, AZ 85615
175 Series; T.C. 3A17	SA11SO	Tank type end plates.	SO	26580	Corben Development Corporation P.O. Box 1603 Venice, FL 33595
175 Series; T.C. 3A17	SA12CE	Removal of right cabin door.	PC	96754	W.E. Avery 116 Kuulei Road Kailua, HI 96754
175 Series; T.C. 3A17	SA28WE	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
175 Series; T.C. 3A17	SA49CE	Conversion of aircraft for parachute jumping operations.	GL	41190	Haven Aviation Memorial Airpark Grand Haven, MI 49417
175 Series; T.C. 3A17	SA72CE	Sky-Lite B-100 beacon light.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
175 Series; T.C. 3A17	SA179NW	Installation of flap gap seals. Issued 1/25/75.	NW	78477	Thunderbird Aero Enterprise Paine Field Everett, WA 98204
175 Series; T.C. 3A17	SA221SO	Conversion of aircraft for parachute jumping and aerial photography.	SO	62490	Edward Richard Parker P.O. Box 578 Andrews Murphy AirPark Andrews, NC 28901
175; T.C. 3A17	SA586NW	Installation of a Franklin 6AS-350-A1 engine. Issued 7/28/78.	NW	70620	Seaplane Flying, Inc. P.O. Box 1264 Vancouver, WA 98661
175, 175A, 175B Landplane; T.C. 3A17	SA424CE	Install Lycoming O-360-A1A or O-360-A1D engine and Hartzell HC-C2YK-1A/7666-2, HC-922K-8D/8447-12A or McCauley 2D36C14/78KM-4 propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
175, 175A, B; T.C. 3A17	SA3-674	Lycoming O-360-A1D engine and McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1A/7666-2 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
175, 175A, B, C, P172D; T.C. 3A17	SA1-610	Wet-to-dry vacuum pump conversion kit 300-2. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
175, 175A, B, C; P172D; T.C. 3A17	SA122NW	Installation of Continental O-470 engine, McCauley 2A34C66N/90A-8 propeller, engine mount, cowling, baffles and associated parts. Issued 7/25/74.	NW	47646	Leslie L. Kammeyer Route 2, Box 38 Enumclaw, WA 98022
175, 175A, B, C; T.C. 3A17	SA161EA	Install new engine, propeller and engine mount. Amended 3/17/67.	EA	36750	Franklin Engine Company, Inc. Liverpool Road Syracuse, NY 13208
175, 175A, 175B, 175C; T.C. 3A17	SA212GL	Installation of windshield P/Ns W-2056, W/T-2056 or W/G-2056. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
175, 175A, 175B, 175C; T.C. 3A17	SA1492CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
175, 175A, B, C, P172D, T210F, G, H, J, K, L, M, 310, 310A, B, C, F thru L, N, P, Q, 310J-1, 310R, E310H, E310J, T310P, Q, 320D, E, F, 337, 337A, B, C, D, E, G, M337B, T337B, C, D, E, F, G, 340, 340A, 401, 401A, B, 402, 402A, B, 414, 421, 421A, B; T.C. 3A17, 3A10, 32A25, A6CE, A7CE	SA660WE	Installation of HRD-type fire-extinguishing and detector system. Amended 7/11/77.	WE	43180	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
175, 175A, B, C, P172D; T.C. 3A17	SA327GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
175, 175A, 175B, 175C, P172D (Landplane), R172E (T-41B); T.C. 3A17	SA777CE	Install Lycoming O-360-A1A, 180 hp engine and Hartzell HC-C2YK-1A/766A-2 propeller. Amended 5/6/80.	CE	12775	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 Wichita, KS 67204
175, 175A, 175B, 175C, P172D, R172E, R172F, R172G, R172H, R172J; T.C. 3A17	SA948CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Amended 5/6/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
175A, B, C, P172D (normal category); T.C. 3A17	SA2229WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
175, 175A, B, C; T.C. 3A17	SA2853SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
175, 175A, 175B, 175C (landplane only, normal category); T.C. 3A17	SA3795WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision, muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29075	Del-Air P.O. Box 746 Strathmore, CA 93267
175, 175A, 175B, 175C; T.C. 3A17	SA4177WE	Installation of electric inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
175, 180, 182; T.C. 3A17, 5A6, 3A13	SA2710WE	Installation of carburetor heat box bearings. Issued 6/15/73.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
177; T.C. A13CE	SA466SO	Removal of right entrance door of cabin for aerial photography. Issued 5/20/71. Modified per STC SA545CE.	SO	25060	Columbus-Muscogee Aviation, Inc. P.O. Box 4608 Columbus, GA 31904
177; T.C. A13CE	SA545CE	Installation of Lycoming O-360-A1A (180 h.p.) engine and new Hartzell propellers. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
177; T.C. A13CE	SA602CE	Install shoulder harness.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67202
177; T.C. A13CE	SA906CE	Installation of Lycoming O-360-A1A 180 hp engine and Hartzell HC-C2YK-1B/766A-2 or 7666-2 constant speed propeller. Issued 5/9/73.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 1006 W. 53 North Wichita, KS 67204
177; T.C. A13CE	SA1608WE	Installation of Brittain B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
177; T.C. A13CE	SA3861WE	Installation of an air/oil separator. Issued 3/2/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
177, 177A; T.C. A13CE	SA956CE	Installation of STOL kit (wing leading edge cuffs, drooped tips and vortex generators). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177, 177A, 177B; T.C. A13CE	SA1347CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
177, 177A, B; T.C. A13CE	SA3180SW-D	Automatic flight system AK420 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3181SW-D	Automatic flight system AK421 consisting of Century IIB autopilot with optional radio coupler. Issued 2/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3402WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
152, A152, 177, 177A, B, 177RG, 180 landplane and seaplane, 180A, B, C, D, E, F, G, H, I, J, K seaplane versions, 182, 182A, 210A, B, C, D, E, 310F, G, H, I; T.C. A13CE, 3A19, A20CE, 5A6, 3A21, 3A10	SA71GL	Installation of: 152's P/N BA4106 filter assembly; 177's P/N BA5710 filter assembly; 180's & 182's P/N BA8110 filter assembly; 210's P/N BA2110 filter assembly; 310's P/N BA2310 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140
177, 180, 182, 185, A185, 188, A188, 210-5 (205), 206, U206, TU206, P206, TP206, 207, T207, 210, T210; T.C. A13CE, 5A6, 3A13, 3A24, A9CE, 3A21, A4CE, A16CE	SA728NW	Installation of vented fuel cap. Issued 3/9/79.	NW	82675	Venting Engineering 5420 "A" Street Tacoma, WA 98408
177A; T.C. A13CE	SA601CE	Install Hartzell Model HC-C2YK-1B/7666A-2 constant speed propeller. Amended 2/28/69.	CE	56868	Galen D. Means 1818 North Edgemoor Drive Wichita, KS 67201
177B; T.C. A13CE	SA1060CE	Installation of wing leading edge cuffs and vortex generators on vertical stabilizer. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177B; T.C. A13CE	SA1607SW	Mitchell command/electric trim AK419. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SW1608SW	Mitchell AFS system AK420 consisting of Century I autopilot with optional omni tracker. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SA1609SW	Mitchell AFS system AK421 consisting of Century I autopilot with optional radio coupler. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RB; T.C. A20CE	SA3297SW-D	Mitchell automatic flight system AK759, consisting of Century IIB autopilot with optional radio coupler. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
177RG; T.C. A20CE	SA1049CE	Installation of wing leading edge cuffs and vertical stabilizer vortex generators. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177RG; T.C. A20CE	SA1348CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
177RG; T.C. A20CE	SA1479SW	Mitchell automatic flight system AK378 consisting of Century I autopilot with optional omni tracker. Issued 8/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RG; T.C. A20CE	SA1510SW	Mitchell automatic flight system AK379 consisting of Century III autopilot with optional radio coupler. Issued 9/8/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3296SW-D	Mitchell automatic flight system AK758 consisting of Century I autopilot with optional omni tracking system. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3298SW-D	Mitchell automatic flight system AK760, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3387WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
177RG; T.C. A20CE	SA3860WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
177RG; T.C. A20CE	SA4024WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 9/10/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
180 Series; T.C. 5A6	SA1-7	Gyro-stabilizer 69A116 on aircraft with serial numbers 32151 and up.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-16	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA1-91	Modification to accommodate Robinson Aviation vertical mount NRIA.	EA	18756	Allen G. Butler 233 Front Street Phillipsburg, PA 16866
180 Series; T.C. 5A6	SA1-106	Gyro-stabilizer 69A107.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-212	Hole cut in lower skin and reinforced.	NE	44030	Inland Fisheries and Game Department Maine
180 Series; T.C. 5A6	SA1-221	Gyro-stabilizer 69A124.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA3-122	Model 3000 main ski and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-160	Conversion of electrical system, engine and aircraft to 24v and installation of additional battery box. (Aircraft with Continental O-470-J engine only).	GL	43342	Harvey M. Hughes Capital City Airport Lansing, MI 48924
180 Series; T.C. 5A6	SA3-161	C-3000 hydraulically-actuated main wheel skis with AWT-2500A or CT-3000 tail wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-292	Hydraulic landing gear actuating system with Edo 289-2700 amphibian gear.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180 Series; T.C. 5A6	SA3-330	C-3000 manually-actuated main skis and AWT-2500A or CT-3000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-340	C-3000 main wheel skis on aircraft with crosswind gear.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-381	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
180 Series; T.C. 5A6	SA3-480	Change in airspeed and center of gravity limits with Edo 249-2870 floats and 2850 maximum weight.	AL	08483	Alaska Coastal Airlines 2 Marine Way Juneau, AK 99801
180 Series; T.C. 5A6	SA3-578	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
180 Series; T.C. 5A6	SA3-592	Structural reinforcement wires from center sectional spars to upper engine mount bolts rear of fire wall in windshield.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA3-597	Engine driven hydraulic pump system for Federal C-3000 main ski.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA4-23	Conversion to tricycle gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-56	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-92	Folding type rear seat.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-117	Auxiliary fuel tank in baggage compartment.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-532	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA4-603	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA4-688	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
180 Series; T.C. 5A6	SA41WE	Two fabric rear seat assemblies supported by two steel tube beams.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA42EA	Floor viewing window.	EA	49730	Latrobe Aviation, Inc. P.O. Box 150 Latrobe, PA 15650
180 Series; T.C. 5A6	SA102AL	Shackle release at wing lift strut fittings right and left wings (seaplane only).	AL	03270	U.S. Department of Agriculture Forest Service P.O. Box 1631 Juneau, AK 99801
180 Series; T.C. 5A6	SA110SW	Removal of perforated cones from exhaust muffler.	SW	76850	Sun Oil Company P.O. Box 292 Patterson, LA 70392
180 Series; T.C. 5A6	SA168SW	Conversion of aircraft for parachute jumping operations.	SW	40684	John Hardy, Jr. 1105 St. John's Road El Paso, TX 79910
180 Series; T.C. 5A6	SA173WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401
180 Series; T.C. 5A6	SA200RM	Installation of flight strobe light, Model 4400. Issued 4/22/80.	RM	79760	Tri Star Corporation P.O. Box 1727 730 Independent Avenue Grand Junction, CO 81501
180 Series; T.C. 5A6	SA214SW	Removal of perforated cones on cabin and carburetor heat-sides of muffler assembly with Continental O-470-K engine.	SW	52870	J. Ray McDermott & Company, Inc. Aviation Division P.O. Box 38 Harvey, LA 70058

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180 Series; T.C. 5A6	SA221WE	Cleveland 30-21 wheel and brake assemblies 8:00 x 6 tires, Cessna heavy duty axles and 185 hose assemblies.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA289CE	Sky diving door.	GL	78474	Melvin J. Thompson 2408 Illinois Avenue New Holstein, WI 53061
180 Series; T.C. 5A6	SA312NW	Installation of Edo 628-2960 floats. Amended 6/6/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180 Series; T.C. 5A6	SA527WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
180 Series; T.C. 5A6	SA531AL	Installation of leading edge cuff stall fences, and flap and aileron gap seals. Issued 10/25/74.	AL	27250	Crosswinds, Inc. 8134 Lake Otis Parkway Anchorage, AK 99507
180 Series: T.C. 5A6	SA532CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
180 Series; T.C. 5A6	SA702WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304, and optional Hi-Lo sensitivity adaptor.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
180 Series: T.C. 5A6	SA703WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold and NAV-1 navigation coupler and optional Hi-Lo sensitivity adaptor. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA939WE	Insertion into exhaust collector or exhaust stack of thermocoupled cylinder, a probe to read relative exhaust temperature.	WE	47746	Richard W. Kennedy 3352 Via Bartolo Street San Diego, CA 92101
180 Series; T.C. 5A6	SA983WE	Removal of right-hand door to permit parachute jumping and aerial photography operation (seaplane).	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
180 Series; T.C. 5A6	SA1373WE	Model 3000 floats.	EA	19800	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond, British Columbia, Canada
180 Series; T.C. 5A6	SA2630WE	Installation of SKI Model 10-202186 (Pulstar TM) combined position - anti-collision lighting system. Amended 5/11/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180F, 182, 182A thru 182D; T.C. 5A6, 3A13	SA1-37	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 46226
180, 180A, 180B; T.C. 5A6	SA1-363	Installation of Edo Model 439-2705 amphibious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, (seaplanes); T.C. 5A6	SA1-464	Installation of Edo models 439-2705 amphibious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, E, F, G, H, J, 182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P; T.C. 5A6, 3A16	SA1-611	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
180, 180A, B, C, D, E, (seaplanes); T.C. 5A6	SA1-622	Installation of Edo Model 249A-2870 seaplane floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180 thru 180F; T.C. 5A6	SA24GL	Installation of Model M-3000 wheel replacement skis. Issued 6/4/73.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapid, MN 56470

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180, 180A thru 180F, H, J, 185, 185A, B, A185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA62GL	Install wheel and brake conversion kit P/N 199-60. Amended 10/25/74.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011
180, 180A thru 180F, H, J, 185, 185A, B, A185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA63GL	Install wheel and brake conversion kit P/N 199-62. Amended 10/25/74.	GL	23260	Cleveland Wheels & Brakes Div. of Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011
180, 180A thru 180J; T.C. 5A6	SA73GL	Installation of wheel replacement skis, Model M3000. Amended 7/16/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
180, 180A thru 180F, 182, 182A thru F; T.C. 5A6, 3A13	SA94EA	Installation of Monitair angle of attack system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
180, 180A thru 180F; T.C. 5A6	SA104CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180 thru 180H, J, 185 thru 185E, A185E, F; T.C. 3A24, 5A6	SA213AL	Installation of main tail gear skid, or main gear skis with two position wheel fittings. Amended 12/10/75.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180, 180A thru 180H, 185, 185E, A185E, 185F; T.C. 3A24	SA223AL	Installation of Model L3000 wheel replacement skis. Amended April 1974.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180 thru 180K; T.C. 5A6	SA286CE	Installation of Pee Kay Model 3500 or A3500 or B3500 floats, seaplane (TSO-C27-2) on Cessna Models 180 thru 180H airplanes. Amended and reissued 1/19/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
180, 180A thru 180H; T.C. 5A6	SA296AL	Installation of "quick-change" leading edge for horizontal stabilizer. Amended 12/15/71.	AL	05958	Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
180 Series 32015 and up, 180A thru 180K; T.C. 5A6	SA349CE	Installation of Aqua Model 180-85 floats. Amended and reissued 7/12/77.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
180 thru 180E; T.C. 5A6	SA367CE	Installation of floor level seat belt brackets to accommodate four occupants. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
180 thru 180H; 182 thru 182L; 185 thru 185E, A185E; 210 thru 210H, 210-5, -5A, T210F, G, H; 206, 206P, 206TP, 206TU, U206A, U206P, U206TP, U206TU, U206B, U206C; T.C. A4CE	SA453CE	Install Hoskins Twilighter Mk.III supplementary lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180H; T.C. 5A6	SA651AL	Fabricate canvas hammock rear seat and associated parts and install. Issued 8/23/78.	AL	61765	Nugget Aviation Route B, Box 188B Palmer, AK 99645
180, 180A thru 180H; T.C. 5A6	SA658AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180, 180A thru H; T.C. 5A6	SA745CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109
180A thru 180H; T.C. 5A6	SA787EA	Installation of Fleet-Line Floats 2900. Reissued 12/21/71.	EA	64630	Pioneer Airways P.O. Box 357 Atikokan, Ontario, Canada
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA816SW	Hartzell BHC-A2VF-3/V8833 reversible pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
180, S/N 18051824 and on; T.C. 5A6	SA865CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180, 180A, B, C, D, E, F, G, H, 182, 182A, B, C, D, E, F, G, H, J, K, L, 185, 185A, B, C, D, E, A185E, 210, 210A, B, C, D, E, F, T210F, 206, P206, P206A, B, C, D, U206, U206A, B, C, D, TP206A, B, C, D, TU206A, B, C, D; T.C. 5A6, 3A13, 3A24, 3A21, 4ACE	SA901SW	Increased wing leading edge radius. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 96133
180, 180A thru 180H, J, 180K, Landplanes, Seaplanes and Amphibians; T.C. 5A6	SA967CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Amended 5/8/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
180, 180A thru 180H; T.C. 5A6	SA1004CE	Install STOL kit. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
180, 180A thru 180H, 180J; T.C. 5A6	SA1157WE	Turbocharged Continental O-470-A, J, K, L, or R engine. Reissued 1/16/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
180 thru 180H, 180J Landplane, Floatplane and Amphibian; T.C. 5A6	SA1435WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, except 180J, a flap actuated elevator trip system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA1493CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
180, 180A thru 180H, J; 180H Landplane and Floatplane; T.C. 5A6	SA1705WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 4/20/77.	WE	35780	William E. Flint 8402 North Magnolia, Suite G La Mesa, CA 92041
180, 180A thru H, A185E; T.C. 5A6, 3A24	SA1749WE	Installation of Canadian Aircraft Products, Ltd. Model 3000D floats.	EA	19800	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond, British Columbia, Canada
180 thru 180H; T.C. 5A6	SA2003WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA2854SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
180, 180A, B, C, D, E, F, G, H, J Landplanes Normal Category; T.C. 5A6	SA3313WE	Installation of flap gap closures. Issued 1/5/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA3419WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
180A; T.C. 5A6	SA388NW	Installation of McCauley 2A34C201/90DA-2 or -8 or McCauley 2A34C203/90DCA-2 or -8. Issued 12/23/76.	NW	61660	North Sound Aviation 1340 Peterson Road Burlington, WA 98233
180A thru 180H; T.C. 5A6	SA1943WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
180B; T.C. 3A24	SA155NW	Installation of baggage hatch with cover on EDO 249-3870 and 628-2960 floats. Issued 7/15/75.	NW	11780	Arts Aircraft Parts & Repair 4647 110th N.E. Kirkland, WA 98033
180B, 182 Normal Category; T.C. 3A13	SA3862WE	Shorten vertical leg of the control column 1-1/4 inches to provide clearance for additional avionics equipment in the instrument panel. Issued 2/6/79.	WE	16752	Big Bear Avionics P.O. Box 768 500 Meadow Lane Big Bear City, CA 92314

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180F, G, H, J; T.C. 5A6	SA3146SW-D	Mitchell automatic flight system AK602 consisting of Century IIB autopilot with optional radio coupler. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180F, G, H, J; T.C. 5A6	SA3147SW-D	Mitchell automatic flight system AK603 consisting of Century I autopilot with optional omni tracker. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180G, 180H, 180J, 180K; T.C. 5A6	SA649NW	Installation of modification to increase gross weight of floatplane to 3190 lbs. when Edo 628-2960 floats are installed. Issued 8/8/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180G, 180H; T.C. 5A6	SA1349CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
180G, H, J (S/N 18051313 and Subs); T.C. 5A6	SA2979WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
180H; T.C. 5A6	SA569EA	Installation of Tactair T-3 automatic pilot with A-651 horizon gyro and B-650 directional gyro. Issued 7/29/71.	GL	75200	George B. Stillwagon 546 Hathaway Road Dayton, OH 45419
180H, 180J; T.C. 5A6	SA262NW	Installation of 3-bladed McCauley D3A32C90/82NC-2 propeller, Cessna 1250809 spinner. Issued 2/27/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180J; T.C. 5A6	SA556NW	Installation of Continental O-470-Rengine. Issued 1/12/79.	NW	41520	Jim Hayton 1712 A Lakeview Boulevard Mount Vernon, WA 98273
180J; T.C. 5A6	SA3183WE	Installation of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
180J, 180K; T.C. 5A6	SA659AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20511	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180K; T.C. 5A6	SA3282SW-D	Mitchell automatic flight system AK751 consisting of Century I autopilot with optional omni tracker. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K; T.C. 5A6	SA3283SW-D	Mitchell automatic flight system AK752 consisting of Century IIB autopilot with optional radio couplers. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K, T207A, 210N, P210N, 337H, P337H, T337H, 340A, 404, 421C; T.C. 5A6, A6CE, A16CE, 3A21, 3A25, A25CE, A7CE	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 8/7/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
180, 182 Series; T.C. 5A6, 3A13	SA3-123	Heater-muffler assembly 430-10P.	EA	40350	Hanlon & Wilson, Inc. 321-325 Penwood Avenue Pittsburg, PA 15644
180, 182 Series; T.C. 5A6, 3A13	SA4-868	Shackle release at wing lift strut fittings, right and left wings (restricted category only).	RM	03270	U.S. Department of Agriculture Forest Service Missoula, MT 59801
180, 182 Series; T.C. 5A6, 3A13	SA4-1092	Seat belt and seat back to accommodate additional passenger on the rear seat.	RM	39464	Green River Aviation Company P.O. Box 606 Green River, UT 84525
180, 182 Series; T.C. 5A6, 3A13	SA4-1588	Cessna 210 wing tip assemblies.	WE	42130	H & H Flying Service, Inc. P.O. Box 742 Redding, CA 96001
180, 182 Series; T.C. 5A6, 3A13	SA5-19	Hammock seat in place of upholstered rear seat.	AL	08460	Alaska Aeronautical Ind. P.O. Box 4591 Spenard, AK 99503

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
180, 182 Series; T.C. 5A6, 3A13	SA108CE	Continental O-470 Series engines modified for Bendix RSA5 fuel injection system.	GL	15500	The Bendix Corporation 717 Bendix Drive South Bend, IN 46600
180, 182 Series; T.C. 5A6, 3A13	SA264SO	Cessna 210 wing tips 1223000-1 and -2.	SO	61180	Nashville Flying Service, Inc. Berry Field Nashville, TN 37202
180, 182 Series; T.C. 5A6, 3A13	SA561WE	12.7-gallon auxiliary fuel tank.	WE	05600	Aircraft Modification and Repair 20331 Hesperian Boulevard Hayward, CA 94541
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA1-519	Griswold lateralizer and heading lock.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA102SW	Automatic pilot AK109 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA4121SW	Add wing strut fairings and contour wing struts. Issued 5/5/80.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA1-576	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA334SW	Alternator.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216
180, 182, 210 Series; T.C. 5A6, 3A13, 3A21	SA96SW	Mixture control indicator kits SE-1.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216
180, 185; T.C. 5A6, 3A24	SA361NW	Installation of 8/50 x 6 main wheels with Cleveland brakes and Cleveland wheel assembly. Issued 10/15/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA701WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180, 185 Series; T.C. 5A6, 3A24	SA2273WE	Installation of Cessna Model 206 rear seats. Amended 10/18/74.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA2767WE	Installation of anti-collision lighting system. Issued 9/28/73.	WE	70500	Scientifico Scientific Components Company 350 Vista Baya Newport Beach, CA 92660
180, 185, 206; T.C. 5A6, 3A24, A4CE	SA754NW	Installation of Fernandez model 8001 and 8001A skis. Issued 4/27/79.	NW	46400	Jobmaster, Inc. 608 West Perimter Road Renton, WA 98055
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA65CE	Tow hitch assembly.	EA	73550	Soaring Society of America, Inc. Elmira, NY 14902
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA271CE	Tow hitch assembly.	CE	67207	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA1-8	Gyro-stabilizer 69A107.	GL	38175	Globe Industries, Inc. 1784 Stanley Avenue Dayton, OH 45404
182 Series; T.C. 3A13	SA1-36	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA3-18	Yaw axis stabilizer 8000B.	GL	20335	Cedar Engineering, Inc. 5806 W. 36th Street Minneapolis, MN 55401
182 Series; T.C. 3A13	SA3-44	Main ski AWB-2500A and nose wheel ski AWN-1200.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-109	Rudder trim system.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA3-110	Single axis automatic pilot A-2 or A-3.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182 Series; T.C. 3A13	SA3-171	AWB2500A main and AWN1200 nose wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-286	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562
182 Series; T.C. 3A13	SA3-348	C-3000 main ski and AWN-1200 nose wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-452	Model 3000 main skis and Model 2000 nose skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-577	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
182 Series; T.C. 3A13	SA4-39	L-2B automatic pilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
182 Series; T.C. 3A13	SA4-132	Automatic rudder control B.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
182 Series; T.C. 3A13	SA4-199	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
182 Series; T.C. 3A13	SA4-533	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA4-548	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA4-668	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
182 Series; T.C. 3A13	SA4-1359	Landing gear modified.	WE	70560	Scott Aero Service, Inc. Municipal Airport Long Beach, CA 90801
182 Series; T.C. 3A13	SA1SO	Wing tips.	SO	75880	Dale Stoughton 6405 S.W. 12 Street Hollywood, FL 33022
182 Series; T.C. 3A13	SA4EA	Single axis autopilot 510A.	EA	05950	Aircraft Radio Corporation P.O. Box 150 Boonton, NJ 07005
182 Series; T.C. 3A13	SA27SW	Automatic pilot AK088, AK088R or AK088E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA40CE	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Montorey, CA 93940
182 Series; T.C. 3A13	SA97WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA101SW	Automatic pilot AK110 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA129EA	HC-A2XF-G/8433-2 or BHC-A2XF-G/8433-2 propeller.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
182 Series; T.C. 3A13	SA183WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	90155	ZIV United Artists, Inc. 7324 Santa Monica Boulevard Hollywood, CA 90028
182 Series; T.C. 3A13	SA361WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA363WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182 Series; T.C. 3A13	SA391CE	210 wing tips.	CE	42030	Carl H. Helms 701 Lou Holland Drive Kansas City, MO 64116
182 Series; T.C. 3A13	SA450SW	Automatic pitch trim system AK134.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA461NW	Installation of Continental IO-520-F engine and McCauley D2A34C58-LMN-90AT-8 propeller. Issued 6/13/77.	NW	85615	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
182 Series; T.C. 3A13	SA489SW	Automatic pilot AK154 and lateral quidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA502WE	Flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA516WE	Original Goodyear wheel and brake assembly replaced with Celveland wheel and brake assembly.	RM	39464	Green River Aviation Company, Inc. P.O. Box 606 Green River, UT 84525
182 Series; T.C. 3A13	SA525WE	B-4 flight control system, including pitch assist PC-1 altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA535CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
182 Series; T.C. 3A13	SA585SO	Fuselage cutout and rerouting of rudder, elevator and trim cables. Amended 1/6/75.	SO	22787	Mr. Joel Clark P.O. Box 317 Bay Minette, AL 36507
182 Series; T.C. 3A13	SA60-SW	AK180 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA617SO	Installation of A or B of Continental O-470-M engines (per STC SE616SO).	SO	61644	North Perry Aviation, Inc. 8000 W. Pembroke Road Hollywood, FL 33023
182 Series; T.C. 3A13	SA624SW	AK197 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA658SW	AK199 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA707SW	AK243 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA709SW	AK229 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA795SW	Mitchell Century II autopilot AK241 with optional automatic aileron stabilizer and radic coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA814WE	Modification to allow installation of camera through 15-inch diameter cutout in bottom of fuselage.	WE	08262	The Air Oasis Company 2361 Airlane San Diego, CA 92101
182; T.C. 3A13	SA1008SO	Installation of an adjustable trim tab on the left aileron. Issued 7/6/78.	SO	03110	Aero-Trim, Inc. 1150 100 Street Bay Harbor, FL 33154
182 Series; T.C. 3A13	SA1383WE	Installation of Brittain Pitch Assist Model PC-1 with Altitude Hold. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1384WE	Installation of Brittain Industries Model CSA-1 Stability Augmentation. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182 Series; T.C. 3A13	SA1474WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1671WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1673WE	Installation of Brittain Industries B-5 Flight Control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1706WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1871WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1872WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA2343WE	Installation of PHI controls Model 312 elapsed time indicator. Issued 4/27/71.	WE	64380	PHI Controls P.O. Box 6307 Torrance, CA 90504
182 Series; T.C. 3A13	SA2719WE	Installation of Symbolic Displays IFO-1A anti-collision lights. Amended 1/23/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
182, 182A thru 182F; T.C. 3A13	SA103CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
182, 182A, B, C, D, E, F, G; T.C. 3A13	SA301GL	Installation of windshield P/Ns W-2071, W/T-2071, W/G-2071, W-2072, W/T-2072, W/G-2072, W-2073, W/T-2073, W/G-2073. Reissued 5/17/79.	GL	39450	Great LAkes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
182, 182A, B; T.C. 3A13	SA355NW	Convert a Cessna 182 aircraft to tailwheel configuration. Amended 1/31/78.	NW	47708	Keefer Aircraft Engineering 11457 Glendale Way S. Seattle, WA 98168
182, 182A thru 182H, 182J thru N, P, Q; T.C. 3A13	SA950CE	STOL kit installation (wing leading leading edge cuffs, drooped tips stall fences and aileron gap seals. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
182, 210, 310, 320 Series; T.C. 3A13 3A21, 3A10, 3A25	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilct with NAV-1 navigation coupler and heading lock.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 thru 182D; T.C. 3A13	SA874CE	Removal of right front seat, rear seat, and baggage shelf (if installed); installation of floor level seat belt brackets to accommodate four occupants in addition to the pilot. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
182, 182A, 182B, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M; T.C. 3A13	SA935SW	Installation of cabin air conditioning system. Amended 5/7/79.	RM	01956	Aero Engineering 8C Garden Center Broomfield, CO 80020
182, 182A thru 182H, J, K, L, M, N, P, Q (Thru S/N 18266590); T.C. 3A13	SA949CE	STOL kit installation. Amended 2/4/80.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
182, 182A thru H, J thru N, P; T.C. 3A13	SA1032WE	Installation of Rajay turbosupercharged Continental O-470-L or -R engine. Amended 10/1/75.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
182 thru 182P; T.C. 3A13	SA1382WE	Installation of flap actuated aileron droop system for all models; except 182P, recontoured wing leading edge, flap actuated elevator system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
182, 182A thru 182H, 182J thru 182N, 182P, Q, R182, TR182; T.C. 3A13	SA1494CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182, A, B, C, D; T.C. 3A13	SA1579SW	Mitchell automatic flight system AK414, consisting of Century IIB autopilot with optional radio coupler. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. box 610 Municipal Airport Mineral Wells, TX 76067
182, A, B, C, D; T.C. 3A13	SA1580SW	Mitchell automatic flight system AK411, consisting of Century I autopilot with optional omni tracker. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182, 182A thru 182H, 182J thru 182Q; T.C. 3A13	SA1758WE	Installation of 12-gallon auxiliary fuel tank in each wing inboard of tip. Amended 3/15/79.	WE	35746	Flint Aero 8402-G Magnolia Avenue Gillespie Airport Plaza Santee, CA 92071
182, 182A thru 182H, 182J thru 182N; T.C. 3A13	SA1938WE	Installation of Madras Air Service "Super Tips." Amended 8/4/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
182 thru 182N; T.C. 3A13	SA2004WE	Installation of contoured wing leading edge and following options: stall fences, Robertson wing tips, positive aileron seals. Reissued 8/10/72.	NW	66175	Charyl C. Raisbeck 839 West Perimeter Road Renton Municipal Airport Renton, WA 98055
182, 182A thru 182H, 182J, 182K, 182L, 182M, 182N, 182P; T.C. 3A13	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
182, 182A, B, C, D; T.C. 3A13	SA2888SW	Replacement of control wheel. Issued 12/18/78.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
182, 182A, B, C; T.C. 3A13	SA2890SW	Installation of Continental O-470-R engine. Issued 12/20/78.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3113WE	Installation of flap gap fairing. Amended 8/22/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, 182Q, R182, TR182; T.C. 3A13	SA3349WE	Installation of vertical tail flood lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3652WE	Installation of an air/oil separator. Amended 3/13/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
182A; T.C. 3A13	SA239GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 5/1/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
182A thru 182H, 182J thru 182N; T.C. 3A13	SA1006CE	Install landing gear speedpants. Amended 10/9/74.	CE	15230	Bede Aircraft, Inc. Newton Municipal Airport P.O. Box 706 Newton, KS 67114
182A thru P; T.C. 3A13	SA25NW	Installation of insect refrigeration release equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA26NW	Installation of twine dispenser equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA67NW	Installation of twine dispenser equipment. Issued 9/10/73.	NW	80914	U.S. Department of Agriculture 3706 W. Nob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA2371WE	Installation of lure-toxicant distributor. Amended March 1974.	NW	80914	U.S. Department of Agriculture Agricultural Research Service 3706 W. Nob Hill Boulevard Yakima, WA 98902
182A, B, C, D, E, F, G, H, J, K, L, M, N, P; T.C. 3A13	SA2761SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Amended 7/15/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
182B; T.C. 3A13	SA198GL	Installation of Continental 0-470-R engine in lieu of Continental 0-470-L engine using original installation hardward & components. Issued 10/20/77.	GL	64285	Mark W. Peterson and Assoc. 2627 Springdale Road Duluth, MN 55811

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182D thru P; T.C. 3A13	SA27NW	Installation of auxiliary crew seat in rear seat area. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182D; T.C. 3A13	SA1338SW	Cessna NAV-O-MATIC 400 autopilot. Issued 7/9/71.	SW	12630	Autopilots Central, Inc. 3260 North Sheridan Road Tulsa, OK 74131
182E, 182F, 210B, 210C, 210-5; T.C. 3A13, 2A21	SA36EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
182E, F, G, H; T.C. 3A13	SA513SW	Heavy duty brake kits. (Also eligible on Wren 460 and 460H aircraft). Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H; T.C. 3A13	SA626SW	Nose gear wheel and tire. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K, L, M; T.C. 3A13	SA692SW	Reverse pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K; T.C. 3A13	SA789SW	Automatic aileron stabilizer AK204.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, F, G, H, J, K, L, M; T.C. 3A13	SA923SW	Droop ailerons. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, K, L, M, 206, P206, U206, 210C, D, E, F, G (205), 210-5 (205A), 210-5A, 337, 337A, B, C, D, T337B, C, D; T.C. 3A13, 3A21, A4CE, A6CE	SA1021SW	Flap on switch on control wheel. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E thru N; T.C. 3A13	SA1211SW	Automatic flight system AK310 consisting of Century I and optional tracking system. Issued 11/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, F, G, H, J, K, L, M, N; T.C. 3A13	SA1594SW	Mitchell automatic flight system AK399 consisting of Century IIB autopilot with optional radio. Issued 1/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, 182F, 182G, 182H, 182J, 182K; T.C. 3A13	SA2546WE	Installation of Pathfinder Engineering Corp. Model P1-( ) autopilot. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA2908SW	Exhaust extension. Issued 2/2/79.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182E, F, G, H, J, K, L, M, N, P (S/N 18253599 and Subs); T.C. 3A13	SA2980WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2502 E. Wardlow Road Long Beach, CA 90807
182E thru 182H, 182H thru 182Q, NOTE; T.C. 3A13	SA3608WE	Installation of replacement flexible fuel cell in wings. Issued 3/15/78. NOTE: 182E S/N 18253599 thru 182H18256143 except aircraft modified by Cessna Service Kit SK182-41; 182H S/N 18256144 and subsequent thru 182Q S/Ns. Also 182E thru 182H aircraft which have been modified by Cessna SK182-41.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
182F; T.C. 3A13	SA198EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182F; T.C. 3A13	SA933EA	Installation of wing struts modified to include Wings With Springs Model 300 hydraulic-pneumatic shock absorbers and associated airframe modifications. Amended 2/13/76.	EA	86500	Wings With Springs, Inc. Box 495, R.D. 3 Latrobe, PA 15650
182F, G; T.C. 3A13	SA403SW	Full span double slotted flaps, drooped wing leading edge, aileron actuated drag plates, Robertson U.I.S. nose control system, increased elevator aerodynamic balance, and relocated pilot head. Reissued 4/22/80.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182H, J, K, L, M; T.C. 3A13	SA485SW	STOL operations modification. (Also eligible on Wren 460H aircraft.) Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182H, J, K, L, M, N; T.C. 3A13	SA1350CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
182H, 182J, 182K, 182L, 182M (Landplane only, normal category); T.C. 3A13	SA2662WE	Removal of nose control surface (which was installed as part of Wren 460 modification in accordance with STC SA485SW). Issued 3/9/73.	WE	17125	Breuner STOL Company 50 Melody Lane Orinda, CA 94563
182H, J, K, L, M, N, P206A, P206B, P206C, P206D, P206E (landplane only); T.C. 3A13, A4CE	SA2799WE	Installation of camera pod attached to bottom of fuselage by straps. Issued 1/8/74.	WE	15190	Bechtel Corporation 50 Beale Street San Francisco, CA 94119
182K, L, M, N, P; 210G, H, J, K, L, T210G, H, J, K, L; T.C. 3A13, 3A21	SA6GL	Installation of Grimes strobe anti-collision lights. Issued 1/5/73.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
182K, L, M, N, P, Q; T.C. 3A13	SA2748SW	Streamlined nose gear kit. Issued 4/14/78.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182M Normal Category; T.C. 3A13	SA2723WE	Installation of external cargo pack (ski carrier). Issued 7/11/73.	WE	87114	Wirly Sales 7610 Owens Street Tujunga, CA 91042
182N, 182P; T.C. 3A13	SA2177WE	Installation of Brittain Ind. B-7, NAV-2B, B2C or BSS flight control system. Reissued 9/19/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182N (S/N 18260446 and up), 182P, 182Q; T.C. 3A13	SA1406CE	Install 25-gallon auxiliary fuel tank in fuselage baggage compartment. Amended 5/12/78.	CE	45250	Javelin Aircraft Company, Inc. 1978 Easy Street Wichita, KS 67230
182P; T.C. 3A13	SA1554SW	Mitchell automatic flight system AK396 consisting of Century I with optional omni tracker. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1555SW	Mitchell automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1556SW	Mitchell command/electric trim system. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA3063WE	Installation of Pathfinder autopilot system and/or electric pitch trim system. Amended 12/3/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182P; T.C. 3A13	SA3072SW-D	Mitchell automatic flight system AK540 consisting of Century III autopilot with optional radio and slope couplers. Issued 9/10/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA3190SW-D	Mitchell command electric trim AK410 Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
182P, 182Q; T.C. 3A13	SA1296CE	Installation of King KFC-200 2-axis, flight control system with KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KX-292 mode controller. Amended 9/22/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
182P, 182Q; T.C. 3A13	SA1403CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
182P, 182Q; T.C. 3A13	SA3188SW-D	Install automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, 182Q; T.C. 3A13	SA3189SW-D	Automatic flight system AK396 consisting of Century 1 autopilot with optional omni tracker system. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, Q; T.C. 3A13	SA4079SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
182Q; T.C. 3A13	SA255GL	Install a Pathfinder P2A autopilot. Issued 7/19/78.	GL	04543	Air Central Enterprises 44050 Russia Road Elyria, OH 44035
182Q; T.C. 3A13	SA3279SW-D	Mitchell automatic flight system AK744 consisting of Century I autopilot with optional omni tracker. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3280SW-D	Mitchell automatic flight system AK745 consisting of Century IIB autopilot with optional radio coupler. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3281SW-D	Mitchell automatic flight system AK 746 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3763WE	Installation of Pathfinder autopilot systems. Issued 10/27/78.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
R182; T.C. 3A13	SA144RM	Installation of Pathfinder P2A single-axis autopilot. Issued 6/29/78.	RM	02454	Aeronics Jefferson County Airport Hangar B4A Broomfield, CO 80020
R182; T.C. 3A13	SA1433CE	Installation of KFC 200 flight control system with or without flight director. Amended 10/27/79.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
R182; T.C. 3A13	SA3273SW-D	Mitchell automatic flight system AK741 consisting of Century IIB autopilot with optional radio coupler. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3274SW-D	Mitchell automatic flight system AK742 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3275SW-D	Mitchell automatic flight system AK743 consisting of Century IV autopilot with optional remote annunciator. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A12	SA3316SW-D	Installation of Mitchell command electric trim system AK778. Issued 11/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3834WE	Installation of Pathfinder autopilot systems. Issued 2/13/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
185 Series; T.C. 3A24	SA4-1617	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
185 Series; T.C. 3A24	SA33SO	Conversion of aircraft for parachute jumping operations.	SO	34288	Falling Angels, Inc. 339 E. New York Avenue De Land, FL 32720
185 Series; T.C. 3A24	SA84CE	25-gallon auxiliary fuel system in cargo pack. (Aircraft equipped with 62-gallon usable main fuel tanks only.)	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
185 Series; T.C. 3A24	SA108SW	Edo 289-2700 and 439-2705 amphibious floats.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
185 Series; T.C. 3A24	SA111CE	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562
185 Series; T.C. 3A24	SA147SW	Edo 429-2705 or 289-2700 amphibious floats.	SW	27270	Cruse Aviation, Inc. 8501 Telephone Road Houston, TX 77002
185 Series; T.C. 3A24	SA172WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401
185 Series; T.C. 3A24	SA202WE	Cessna 210 wing tip assemblies 1223000-1, -2, and wing tip mounted navigation lights.	NW	49270	Lake Aero Service 9306 Veterans Drive, SW Tacoma, WA 98402
185 Series; T.C. 3A24	SA215SW	L-2 autopilot.	SW	03120	Aerotron Radio Company P.O. Box 8396 Tulsa, OK 74101
185 Series; T.C. 3A24	SA213WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
185 Series; T.C. 3A24	SA261NW	Installation of automatic flagman. Issued 2/5/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362
185 Series; T.C. 3A24	SA343EA	Holes in floor of aircraft for use of viewfinder and camera.	NE	50780	Herbert P. Lindblad Mousam Road Springfield, ME 04487
185 Series; T.C. 3A24	SA417WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
185 Series; T.C. 3A24	SA1081WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
185 Series; T.C. 3A24	SA1568WE	Installation of emergency fuel system.	WE	59730	Missionary Aviation Fellowship P.O. Box 2828 Fullerton, CA 92632
185 Landplane; T.C. 3A24 —	SA943WE	Installation of Continental TSIO-470-B engine.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
185, 185A, B, C, D, 210, 210A, B, C, 210-5, 210-5A, 210E, F, G, H, J, K, L; T.C. 3A21, 3A24	SA1-629	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
185, A, B, C, D, E, A185E; T.C. 3A24	SA3-717	Ski installation: main gear Model 4000; tail gear Model 1500, CT-3600, CT-3200, CT-3400. Amended 2/19/76.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
185, 185A, 185B; T.C. 3A24	SA123CE	High intensity wing tip lights Model B and tail light Model C with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
185, 185A, B, C, D, E, A185E; T.C. 3A24 (Floatplane configuration)	SA169CE	Install Wipline Model 3700 or 3900 twin floats. Amended 7/22/76.	GL	86750	Wipline, Inc. South End Doane Train Inver Grove Heights, MN 55075
185 - 185D;	SA324AL	Installation of Continental IO-520-D engine. Revised 6/16/69.	AL	08472	Alaska Air Guides, Inc. P.O. Box 4165 Anchorage, AK 99503
185 thru 185E, A185E, A185F; T.C. 3A24	SA328CE	Install Model 180-85 aqua floats. Reissued 7/31/78.	SC	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA445CE	Installation of Pee Kay 3500, A3500, B3500, C3500, 2950 or 3000 seaplane floats (TSO-C27-2). Amended and reissued 1/19/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
185, 185A, 185B, 185C, 185D, 185E, A185E; T.C. 3A24	SA480AL	Installation of EDO-AIRE Mitchell Century I autopilot and omni tracker. Issued 5/25/72.	AL	03124	Aerotronics of Alaska, Inc. Box 4-1582 Anchorage, AK 99509
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA525NW	Installation of Continental IO-520-D engine and McCauley D2A34C58/90AT-4 propeller. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA526NW	Installation of Edo Model 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA587NW	Installation of Hartzell HC-C3YF-1RF/F9587C-15 propeller on Continental IO-520-D engine. Issued 5/5/78.	AL	08492	Alaska Propeller Specialists, Inc. 5251 Lakeshore Drive Anchorage, AK 99503
185, 185A, 185B, 185C, 185D, 185E; T.C. 3A24	SA631AL	Install leading edge cuff. Issued 4/28/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA746CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109
185, S/N 185-1201 and on; T.C. 3A24	SA866CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA954SW	Installation of droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
185, 185A thru 185E, A185E and F Landplanes, Seaplanes and Amphibians; T.C. 3A24	SA968CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
185, 185A, C, D, E, A185E; T.C. 3A24	SA1351CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
185, 185A thru 185E, A185E, A185F Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA1441WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge (except A185F) stall fence, flap actuated elevator trim system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA1495CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
185, 185A thru 185E; T.C. 3A24	SA2108WE	Installation of Madras Air Service wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
185, 185A thru 185E, A185E Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA2189WE	Installation of recontoured wing leading edge, stall fences, wing tips, and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, 185B, 185C, and 185D, 185E, A185E, A185F Landplane; T.C. 3A24	SA2529WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 9/20/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite G Santee, CA 92071
185, 185A, B, C, D, E; T.C. 3A24	SA2802SW	Install leading edge cuffs, stall fences, aileron seals, and wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
185, A, B, C, D, E, A185E; T.C. 3A24	SA3084SW-D	Automatic flight system AK554, consisting of Century I autopilot with optional omni tracker. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
185, A, B, C, D, E, A185E; T.C. 3A24	SA3085SW-D	Automatic flight system AK555, consisting of Century IIB autopilot with optional radio coupler. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
185, 185A, B, C, D, E, A185E, F; T.C. 3A24	SA3383WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87019
185A, A185F (Seaplane Configuration only); T.C. 3A24	SA7GL	Installation of Model 3730 amphibious floats, Model 3700, 3800 or 3900 seaplane floats. Amended 7/20/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
185A, 185E, A185E, A185F, 206, P206, P206A, U206A, TP206A, TU206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E, U206F, TU206F, U206G; T.C. 3A24, A4CE	SA522NW	Installation of float hatch kits on Edo 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA4139WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 4/10/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw AVenue Irvine, CA 92705
185B; T.C. 3A24	SA199EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
185E, A185, A185F; T.C. 3A24	SA240NW	Installation of McCauley D3A32C90/ propeller, Cessna spinner, governor, and associated systems on Continental IO-520-D engine. Amended 1/16/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
A185E; T.C. 3A24	SA507NW	Installation of Edo floats and Cessna cargo pack, Issued 8/31/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
A185E; T.C. 3A24	SA592AL	Install leading edge cuff, stall fences, and flap and aileron gap seals. Issued 7/19/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
A185E; T.C. 3A24	SA930SW	Droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
A185E; T.C. 3A24	SA1148SW	Aileron drooping device. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
A185E; T.C. 3A24	SA1990WE	Installation of Tritan Amphibious float model TA 3500. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
A185E (Floatplane Amphibian configuration only); T.C. 3A24	SA805CE	Installation of Wipline Model 3730 amphibious twin floats. Issued and amended 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
A185E, A185F; T.C. 3A24	SA501NW	Installation of McCauley D3A32C90/82NC-2 on Lycoming IO-520-D engine. Issued 8/29/77.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
A185E, A185F; T.C. 3A24	SA832EA	Installation of Edo Model 582-3430 seaplane floats. Amended 7/25/80.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185E, A185F; T.C. 3A24	SA877EA	Installation of Pee Kay Model 3500A (TSO C-27-2) amphibious floats. Amended 6/7/75.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
A185E, A185F (Floatplane and Amphibious Configurations; T.C. 3A24	SA985EA	Installation of McCauley Propeller Model D3A32C90/82NC-2. Amended 2/25/75.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
A185E, A185F; T.C. 3A24	SA2875WE	Installation of modified brake system. Issued 4/30/74.	WE	59730	Mission Aviation Fellowship P.O. Box 142 Ramona, CA 92065
A185F; T.C. 3A24	SA17NE	Installation of EDO Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Reissued and amended 9/5/79.	NE	32625	EDO-AIRE Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A185F; T.C. 3A24	SA51NW	Installation of Cessna cargo pack. Issued 7/31/73.	NW	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA164NW	Installation of EDO-628-2960 seaplane floats with Cessna cargo pack kit No. AK-185-23D, cargo pack fairing, rudder non-linear centering spring and ventral fin. Issued 2/28/75.	NW	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA420NW	Installation of cargo pac and McCauley 3-bladed propeller. Issued 3/17/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA558NW	Installation of Edo Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Amended 1/15/80.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185F; T.C. 3A24	SA596NW	Install Cessna A185E wing panels. Issued 4/27/78.	NW	03215	Airmetal Northwest, Inc. P.O. Box 387 Arlington, WA 98223
A185F; T.C. 3A24	SA634AL	Install leading edge cuff. Issued 5/31/78.	AK	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
A185F; T.C. 3A24	SA780NW	Installation of Edo 628-2960 floats on a A185F equipped with Cessna cargo pod (P/N 0700062-43) must include Cessna ventral fin (P/N 0712764-2) and linear rudder centering system. Issued 6/1/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
A185F; T.C. 3A24	SA3251SW-D	Mitchell automatic flight system AK703 consisting of Century IV autopilot or AK703FD consisting of Century IV flight director with optional remote annuciator. Issued 11/18/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
188, A188; T.C. A9CE	SA709CE	Install wing fence.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
188, A188; T.C. A9CE	SA1126SW	Alternate air filter.	SW	43500	Hutchinson Aircraft Box 1070 Borger, TX 79006
188, A188; T.C. A9CE	SA1352CE	Chrome-plated brake disc installation. Issued 3/2/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
188, A188; T.C. A9CE	SA1919WE	Installation of Madras Air Service wing tips. AMended 8/16/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
188, 188A, A188, A188A; T.C. A9CE	SA142NW	Normal and restricted category installation of recontoured wing leading edge and stall fences. Options: wing strut fillet or wing tips. Issued 12/11/74.	NW	68500	Robertson Aircraft Corporation 839 Perimeter Road Renton, WA 98055
188, 188A, A188, A188A, T.C. A9CE	SA1007CE	Installation of full spar leading edge cuffs and drooped wing tips. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
188, 188A, A188, A188A; T.C. A9CE	SA1355SW	Wing leading edge cuff to increase leading edge radius. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
188, 188A, A188, A188A; T.C. A9CE	SA1373SW	Fairing on wing strut intersection. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
188, 188A, A188, A188A; T.C. A9CE	SA1745WE	Installation of Automatic Flagman (Marker Dispensing Unit). Amended 8/10/73.	NW	03500	Air-Ag, Inc. Route 4, City County Airport Walla Walla, WA 99362
188, 188A, A188, A188A; T.C. A9CE	SA2340WE	Installation of recontoured wing leading edge, drooped ailerons, stall fences, new wing strut fillet; optional flap actuated elevator trim system, Robertson wing tips 10-105, Madras Air Services super tips. Issued 4/13/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
188, 188A, 188B, A188, A188A, A188B; T.C. A9CE	SA1179CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508, Renner Field Goodland, KS 67735
188, 188A, 188B, A188, A188A, A188B; T.C. A9CE	SA4099WE	Installation of two Conrel dispensing pads, drawing No. 21940. Reissued 5/8/80.	WE	08550	Albany International Controlled Release Division P.O. Box 537 Buckeye, AZ 85326
A188; T.C. A9CE	SA543SO	Extruded aluminum leading edge cuff. Issued 8/2/73.	SO	79820	Tunico P.O. Box 356 Tunica, MS 38676
A188, A188A, A188B; T.C. A9CE	SA99RM	Installation of freon type air conditioning system. Issued 7/12/77.	RM	32300	Dale Edlund Billings Aircraft, Logan Field Billings, MT 59102
A188, A188A, A188B; T.C. A9CE	SA900SO	Installation of cabin air conditioning. Issued 5/31/76.	SO	69228	Mr. Dwight Kerry Rudder Route 1, P.O. Box 11A Canton, MS 39046
A188B; T.C. A9CE	SA40RM	Installation of Freon air-conditioning system. Amended 3/22/76.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
A188B; T.C. A9CE	SA672NW	Installation of Hartzell HC-C3YF-1RF/F9587C-178 propeller on Continental IO-520-D engine. Issued 9/29/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
190 Series; T.C. 790	SA3-227	ARC I-11 loop and housing, ARC ADF receiver R-30A and power unit, and ARC control head.	CE	44380	Interstate Airmotive, Inc. Lambert Field St. Louis, MO 63155
190 Series; T.C. 790	SA4-1075	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	06625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
190 Series; T.C. 790	SA4-1275	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
190 Series; T.C. 790	SA42WE	Eclipse Aviation generator 790-1B.	WE	34292	Robert F. Fallon 1201 Deborah Drive Tustin, CA 92680
190 Series; T.C. 790	SA220WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	69245	Rusty's Flying Service 1041 W. Alondra Compton, CA 90220
190 Series; T.C. 790	SA354SW	Cargo conversion.	SW	33994	Executive Airlines, Inc. 206 E. Terminal Drive International Airport San Antonio, TX 78205
190, 195; T.C. 790	SA573CE	Installation of block swivel action of crosswing gear.	CE	47250	Ray M. Jourdan 11001 E. 59th Street Raytown, MO 64133
190, 195; T.C. 790	SA1492WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
190, 195, 195B; T.C. A-790	SA54GL	Install wheel and brake conversion kit P/N 199-61. Issued 6/10/74.	GL	23260	Cleveland Wheel and Brakes Div. of VanSickle Industries 1160 Avon Center Road Avon, OH 44011
190, 195, 195B; T.C. A-790	SA120NW	Installation of Hartzell HC-B3P20-4/P10160-12E propeller on Jacobs-Page R-755S engine. Amended 4/20/77.	NW	87008	William Wiprud 6443 Southwest Beaverton Hillsdale Airport Portland, OR 97221
190, 195, 195A, B; T.C. A-790	SA1284CE	Replacement axles. Issued 10/13/76.	CE	19020	Butterfly Aviation, Inc. P.O. Box 736 Renner Field Goodland, KS 67735
190, 195, 195A, B; T.C. A-790	SA2388WE	Removal of left-hand exit. Issued 7/26/71.	WE	67014	Everett A. Redding 18250 Grand Avenue Elsinore, CA 92330
195; T.C. A-790	SA199GL	Installation of oil filter between engine oil gallery and propeller governor/nose case tappet rocker arm supply. Issued 11/4/77.	GL	60093	Richard C. Moen 536 South 1st Street Dundee, IL 60118

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
195; T.C. 790	SA1268SW	Jacobs-Page R-755-S engine. Reissued 5/24/77.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
205, 205A; T.C. 3A21	SA3836WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Voulevard Los Angeles, CA 90064
205, 205A, 210, 210A, 210B, 210C, 210D, 210E, 210F, 210G, 210H, 210J, 210K, 210L, 210M; T.C. 3A21	SA2784SW	INstallation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions Box 431 Udall, KS 67146
206 Series; T.C. A4CE	SA65NW	Installation of fiberglass wing tips. Issued 9/20/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
206 Series; T.C. A4CE	SA635SW	McCauley DA3A32C90/82NC-2 propeller.	SW	84395	L.L. Walker Company P.O. Box 5158 Houston, TX 77012
206 Series; T.C. A4CE	SA669SW	AK218 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206; T.C. A4CE	SA685AL	Installation of Hartzell and blade propeller. Issued 5/16/80.	AL	08492	Alaska Propeller Specialists 5251 Lakeshore Drive Anchorage, AK 99503
206 Series; T.C. A4CE	SA727SW	AK231 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206 Series; T.C. A4CE	SA1255WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	73760	Sonora Aviation, Inc. P.O. Box 1027 Carson City, NV 89701
206 Series; T.C. A4CE	SA1893WE	Installation of Brittain Flight Control Systems Model B-5, NAV-2B or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
206 Series; T.C. A4CE	SA3837WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
206, P206, U206, P206A, U206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA332CE	Installation of Wipline Models 3700 and 3900 twin floats on Cessna Floatplane configuration. (Floatplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
206, P206, U206; T.C. A4CE	SA392GL	Installation of Great Lakes Aero Products windsheild P/Ns W-2065, W/T-2065 and W/G-2065. Issued 3/10/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
*206, *P206, *P206A, *U206, *U206A, U206B, C, D, E, F, G (S/N U20603522 thru U20604649, U20604659 and up) (1979 models), TP206A, TU206A, B, C, D, E, F (S/N U20601701 thru U20602199); T.C. A4CE *These models are approved with a gross weight of 3500 lbs., all others approved with 3600 lbs. gross weight.	SA439NW	Installation of Edo-696M-3500 and/or 696-3500 amphibious floats. Reissued and amended 10/22/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
206, P206, U206, U206F, Floatplane configuration; T.C. A4CE	SA474CE	Install Aqua Model 3526 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
206, P206, P206A, TP206A, U206, U206A, thru G, TU206A thru TU206G; T.C. A4CE	SA512CE	Installation of Pee Kay Model 3500 or A3500 or B3500 seaplane floats. Amended and reissued 1/29/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newton Road Plainview, NY 11803

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206, P206, U206, P206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206A, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA666CE	Install Wipline Model 3730 twin floats (amphibious). (Seaplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
206, P206, P206A, TP206A, U206, U206A thru G, TU206A thru G; T.C. A4CE	SA851EA	Installation of Pee Kay Model 3500A amphibious floats (TSO C-27). Amended and reissued 1/29/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newton Road Plainview, NY 11803
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA893CE	Camera hole cut-out in lower fuselage structure. Reissued 2/17/76.	GL	59452	Mr. Wayne B. Millard 4144 South Highway 101 Minneapolis, MN 55345
206, P206, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA908CE	Install STOL kit. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F landplanes only; T.C. A4CE	SA990CE	Install STOL kit (wing leading edge cuffs, drooped tips, and stall fences). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, TU206A, B, C, D, E, F; T.C. A4CE	SA1069CE	Enlargement of factory installed camera hole and installation of a view finder hole. Issued November 1974.	CE	36000	FloAir, Inc. Hangar #17 Mid-Continent Airport Wichita, KS 67209
206, U206A, B, D, E, TU206A, B, D, E, P206A, B, C, D, E; T.C. A4CE	SA1353CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F; T.C. A4CE	SA1513WE	Installation of flap actuated aileron droop system, recontoured wing leading edge (except TU206F and U206F), and flap actuated elevator trim system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, 210-5, 210-5A; T.C. A4CE, 3A21	SA1870WE	Installation of Brittain Model NAV-2B Flight Control. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
206, U206, P206 Landplane and Floatplane, P206B, TP206B, P206C, TP206C, P206D, TP206D, P206E, TP206E Landplane and Skiplane, P206A Landplane, U206A, U206B, U206C, U206D, TU206A, TU206B, TU206C, TU206D, TU206E Skiplane; T.C. A4CE	SA2326WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, P206A, B, C, D, E, F, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G; T.C. A4CE	SA2479WE	Installation of larger fuel containing wing tips. Amended 7/25/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite G Santee, CA 92071
206, P206, 206-A, -B, -C, -D, -E, TP206A, B, C, D, E, U206, A, B, C, D, E, F; T.C. A4CE	SA2855SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G; T.C. A4CE	SA3348WE	Recognition light installation on horizontal stabilizer. Issued 3/7/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F; T.C. A4CE	SA3462WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 8/19/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
206, P206, A, B, C, D, E, TP206, A, B, C, D, E, U206, A, B, C, D, E, F, G, TU206A, B, C, D, E, F, G; T.C. A4CE	SA3739WE	Installation of Silver Instruments' fueltron IG or fueltron IP digital fuel flow and totalizer system. Amended 4/2/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
206 (S/N 206-0001 thru 206-0137 except 206-0094, S/N 206-0094, 206-0138 thru 206-0275), U206 (S/N U206-04074), P206 (S/N P206-0001 thru P206-00647); T.C. A4CE	SA3825WE	Installation of replacement flexible fuel cell in wings. Issued 8/2/79.	WE	08357	Air-Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
P206A/B/C/D/E, U206A/B/C/D/E/F/G; T.C. A4CE	SA3686WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
P206C, P206D, U206C, U206D, U206E; T.C. A4CE	SA1431SW	Mitchell automatic flight system AK368 consisting of Century III autopilot with optional automatic electric pitch trim, radio, and glide slope couplers. Issued 2/25/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206; T.C. A4CE	SA652NW	Installation of McCauley D3A32C90/82NC-2 propeller on Continental IO-520-A engine. Issued 8/15/78.	NW	64790	Robert Plummer Bob's Aircraft Maintenance Challis, ID 83226
U206, TU206; T.C. A4CE	SA1037CE	Installation of 26 gallon auxiliary fuel tank in baggage compartment. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA2782SW	Installation of Continental TSIO-520-M. Issued 5/30/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F, TU206G; T.C. A4CE	SA3856WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1430SW	Mitchell automatic flight system AK350, consisting of Century I autopilot with omni tracker. Issued 2/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1449SW	Mitchell automatic flight system AK369, consisting of Century II autopilot with optional radio coupler. Issued 3/22/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Minerals Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1572SW	Mitchell automatic flight system AK405 consisting of Century IIB autopilot with optional radio coupler. Issued 12/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1846SW	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/electronic pitch trim, radio coupler, and glide slope coupler. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1887SW	Automatic flight system AK470, consisting of Century IIB autopilot with optional radio coupler. Issued 6/17/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA3097SW-D	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/electronic pitch trim, radio coupler and glide slope coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
U206C, -D, -E, -F, TU206C, -D, -E, -F, P206C, -D, -E, TP206C, -D, -E; T.C. A4CE	SA2164WE	Installation of Edo Model FD-3500A (TSO C-27-2) amphibious floats. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
U206F, TU206F, U206G, TU206G, T.C. A4CE	SA3GL	Installation of Bendix FCS-810 autopilot and flight director. Amended 2/13/78.	GL	66080	Russell Hammer Radio Ranch, Inc. Radio Ranch Airport Polo, IL 61064
U206F, G, TU206F, G (Seaplane configuration only); T.C. A4CE	SA18GL	Installation of Wipline Model 3730 floats. Amended 6/12/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
U206F, TU206F; T.C. A4CE	SA1845SW	Mitchell automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3177SW-D	Install Mitchell automatic flight system AK470 consisting of Century IIB with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3178SW-D	Install automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, U206G, TU206F, TU206G; T.C. A4CE	SA3262SW-D	Mitchell automatic flight system AK715 consisting of Century III autopilot with optional radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3263SW-D	Mitchell automatic flight system AK714 consisting of Century IIB autopilot with optional radio couplers. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3264SW-D	Mitchell automatic flight system AK713 consisting of Century I autopilot with optional omni tracker. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3265SW-D	Mitchell automatic flight system AK717/FD consisting of Century IV/ flight director autopilot with optional remote annunciator. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F (Seaplane configuration only); T.C. A4CE	SA3296WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/23/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
U206F, U206G, TU206F, TU206G;	SA3454WE	Installation of an emergency fuel system. Amended 2/7/78.	WE	59730	Mission Aviation Fellowship P.O. Box 2828 Fullerton, CA 92633
U206G, TU206G; T.C. A4CE	SA1480CE	Installation of King KFC200 automatic flight control system, two axis, with or without flight director. Issued 3/27/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
TU206C; T.C. A4CE	SA566CE	Install one or two blister windows.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
TU206C, TU206D; T.C. A4CE	SA935EA	Installation of window in bottom of fuselage at F. Station 35.5. Amended 4/18/73.	EA	52060	Long Island Airways Box 248 Ronkonkoma, NY 11779
TU206G; T.C. A4CE	SA831NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705
TU206G; T.C. A4CE	SA4004SW	Camera port. Issued 6/20/79.	SW	28490	Daily Tubbs Aero, Inc. 2115 Danbury Drive San Antonio, TX 78217
206, 207, 210 Series; T.C. A4CE, A16CE, 3A21	SA2809SW	Install Symbolic Displays CFS-1000 electronic fuel flow metering system. Issued 7/2/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
206, 210 Series; T.C. 3A21, A4CE	SA149SW	Automatic pilot AK120, AK120E, AK102E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206, 210 Series; T.C. 3A21, A4CE	SA245WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
206, 210 Series; T.C. 3A21, A4CE	SA526SW	Automatic trim AK171.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206, 210 Series; T.C. 3A21, A4CE	SA674WE	Flight control system B-4 including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
207; T.C. A16CE	SA1402SW	Mitchell automatic flight system AK357 consisting of Century II autopilot with optional radio coupler. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1403SW	Mitchell automatic flight model AK356 consisting of Century I autopilot with optional omni tracker. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1404SW	Mitchell automatic flight system Model AK361 consisting of command/electric trim system. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA2856SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
207, T207; T.C. A16CE	SA1354CE	Chrome-plated brake disc installation. Issued 8/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
207, T207; T.C. A16CE	SA2121WE	Installation of recontoured wing leading edge, drooped ailerons, in flaps down mode, stall fences, and elevator trim spring. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
207, T207; T.C. A16CE	SA2327WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
207, T207; T.C. A16CE	SA2676WE	Installation of larger fuel containing wing tips. Amended 5/23/77.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041
207, T207; T.C. A16CE	SA3427WE	Installation of tail flood light on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
210 Series; T.C. 3A21	SA1-625	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA3-503	L-2B autopilot with or without altitude controller and/or approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
210 Series; T.C. 3A21	SA4-1086	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
210 Series; T.C. 3A21	SA4-1372	Brake blocks AB-6526 and AB-6527.	EA	46748	Johns-Manville Corporation 22 E. 40 Street New York, NY 10001
210 Series; T.C. 3A21	SA4-1416	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA20SW	Automatic pilot AK086, AK086E or AK086R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210 Series; T.C. 3A21	SA89SW	Automatic pilot AK112.	SW	60000	Mitchell Industries, INc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA89NW	Installation of King VOR Model KX 170B or KX 175B, King DME Model KN65 and King Area Navigation computer Model KN74. Issued 2/11/74.	NW	70040	Salem Aviation 2680 Aerial Way, S.E. Salem, OR 97302
210 Series; T.C. 3A21	SA103SW	Automatic pilot AK111.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA110EA	Removal of right front door and other modifications.	EA	72108	Sky Diving, Inc. Cameron Airpark Medford, NJ 08055
210 Series; T.C. 3A21	SA118EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA199WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	82270	V. Vincent Vandever, Inc. 6447 W. Reade Avenue Glendale, AZ 85301
210 Series; T.C. 3A21	SA330SW	Automatic pilot AK126 and lateral guidance/radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA420SW	Automatic pitch trim AK133.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA464EA	Propeller, spinner, and governor.	GL	73830	Southeastern Ohio Air Service, Inc. P.O. Box 863 Municipal Airport Zanesville, OH 43701
210 Series; T.C. 3A21	SA469WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold (optional). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA531CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
210 Series; T.C. 3A21	SA618WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA627WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA637SW	AK209 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA675SW	AK212 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA1100SW	Increase wing leading edge radius. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
210 Series; T.C. 3A21	SA1305WE	PCA-1 pitch assist with altitude hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1343WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1471WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210 Series; T.C. 3A21	SA1478WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1606WE	Installation of Brittain Industries B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1609WE	Installation of Brittain Industries Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1618WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1631WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1672WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1684WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1882WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1887WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA2720WE	Installation of Symbolic Displays IFO-1A anti-collision lights. Amended 3/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
210, 210A; T.C. 3A21	SA1527WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 8/7/73.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041
210, 210A; T.C. 3A21	SA3377WE	Installation of flap gap fairing. Issued 3/24/77.	WE	78450	Thermal Aircraft Company [illegible]-850 Tyler Street Thermal, CA 92274
210, 210A; T.C. 3A21	SA3732WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 9/14/78.	WE	84542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
210, 210A, 210B, 210C, 210K, 210L, T210K, T210L; T.C. 3A21	SA52GL	Installation of wheel and brake conversion kit P/N 199-60. Issued 6/6/74.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Industries, Inc. 1660 Avon Center Road Avon, OH 44011
210, 210F, T210F (205), 210-5 (205A), 210-5A; T.C. 3A21	SA64NW	Installation of fiberglass wing tips. Issued 9/13/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
210, 210A, 210B, 210C, 210-5; T.C. 3A21	SA93CE	High intensity wing tip lights Model B, and tail light Model C, with or without fuselage lights. Reissued 10/17/74.	GL	42626	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
210, 210A, B, C, D, E, F, 210-5(205), 210-5A (205A), T-210F; T.C. 3A21	SA940CE	STOL Kit installation. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
210, 210A, 210B, 210C, 210D, 210E, 210F; T.C. 3A21	SA1048CE	Installation of STOL kit (wing leading edge cuffs, stall fences, aileron gap seals and droop wing tips). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
210, -A, -B, -C, 210-5 (205), 210-5A (205A); T.C. 3A21	SA1098WE	Installation of Rajay turbosupercharged Continental IO-470-E or IO-470-S engine. Amended 8/11/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
210, 210A thru 210H, 210J, K, L, T210F thru T210H, T210J, K, L; T.C. 3A21	SA1525WE	Installation of droop ailerons in flaps down mode, recontoured wing leading edge, and elevator trim spring (except on T210K, L, and 210K and L). Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210 thru 210K, T210F thru T210K, 210-5 (205), 210-5A (205A); T.C. 3A21	SA2242WE	Installation of recontoured wing leading edge stall fences, and for 206, 205A, 210A, 210B and 210C positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
210, 210A, B, C, D, E, F, G, H, J, K, L, M, T210F, G, H, J, K, L, M, (205) 210-5, (205A), 210-5A, P210N; T.C. 3A21	SA3312WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
210, 210A, B, C, D, E, F, G, H, J, K, L, M, N, P210; T.C. 3A21	SA3453WF	Installation of a cargo container. Amended 4/25/80.	WE	02465	Aero Pod, Inc. 17202 Sandra Lee Lyn Huntington Beach, CA 92649
210A, B, C, D, E, F; T.C. 3A21	SA3649WE	Installation of replacement flexible fuel cell in the wings of the 210 Cessna aircraft. Issued 5/16/78.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
210B, C; T.C. 3A21	SA3144SW-D	Mitchell automatic flight system AK604 consisting of Century I autopilot with optional omni tracker. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B, C; T.C. 3A21	SA3145SW-D	Mitchell automatic flight system AK605 consisting of Century IIB autopilot with optional radio coupler. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B; 210-5(205), 210-5A(205A); T.C. 3221	SA3522WE	Installation of Knisley muffler in lieu of original Cessna mufflers. Issued 11/11/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
210B, 210C, 210E, 210-5(205, 210-5A (205A); T.C. 3A21	SA393GL	Installation of Great Lakes Aero Products windwhield, P/N W-2065, W/T-2065, W/G-2065. Issued 3/10/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
210C; T.C. 3A21	SA197EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
210C, D, E, F, G, H, J, K, T210F, G, H, J, K, 210-5(205), 210-5A(205A); T.C. 3A21	SA1312CE	Chrome-plated brake disc installation. Amended 9/13/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
210D, E; T.C. 3A21	SA376NW	Installation of McCauley D3A32C88-XLM/S-82NC-2 propeller and Continental IO-520-A engine. Issued 11/15/76.	NW	34827	Felts Field Aviation 3100 North Division Spokane, WA 99207
210D, E, F, T210F; T.C. 3A21	SA906SW	Mitchell automatic aileron stabilizer AK211 and omni tracker AK246.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, E, F, T210F; T.C. 3A21	SA1376SW	Mitchell automatic flight system AK349 consisting of Century I with optional omni tracker. Issued 10/4/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, E, F, T210F; T.C. 3A21	SA3141SW-D	Mitchell automatic flight system AK620 consisting of Century IIB autopilot with optional radio coupler. Issued 6/3/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, 210E, 210F, T210F; T.C. 3A21	SA2677WE	Installation of larger fuel containing wing tips. Amended 4/6/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210D, E, F, G, H, J, K, L, M, T210F, G, H, J, L, M, K, P210N; T.C. 3A21	SA3751WE	Installation of Fueltron IG digital fuel flow and totalizer system. Amended 11/22/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
210D, 210E, P206; T.C. 3A21, A4CE	SA693WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210D, E, F, G, H, J, K; T.C. 3A21	SA790CE	Installation of engine condition monitor kit ECM-6. Issued August 1971.	GL	31750	ECM Corporation 412 North Weinbach Avenue Evansville, IN 47711
210G; T.C. 3A21	SA829SW	Automatic flight system AK254 Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G; T.C. 3A21	SA850SW	AK258 consisting of Century III autopilot with optional aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, T210G, 210H, T210H, 210J, T210J, 210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N; T.C. 3A21	SA966CE	Installation of leading edge cuffs, droop tips, aileron gap seals, and stall fences. Amended 4/25/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
210G, H, J, K, L, M, T210G, T210H, T210J, T210K, T210L, T210M, 210N, P210N, T210N; T.C. 3A21	SA2862WE	Installation of larger fuel containing wing tips. Amended 7/23/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210G, H, J, T210G, H, J; T.C. 3A21	SA3168SW-D	Automatic flight system AK641 consisting of Century IV autopilot or AK641-FD consisting of Century IV flight director with optional remote annuciator. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J; T.C. 3A21	SA3169SW-D	Automatic flight system AK642 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J, K; T.C. 3A21	SA3170SW-D	Automatic flight system AK643 consisting of Century IIB autopilot with optional radio coupler. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, K, T210G, H, J; T.C. 3A21	SA3171SW-D	Automatic flight system AK644 consisting of Century I autopilot with optional omni tracker. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
T210F; T.C. 3A21	SA1042SW	Hartzell-Wren beta control system. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
T210F; T.C. 3A21	SA2277WE	Installation of Brittain Industries B2C flight control systems. Amended 10/20/72.	[illegible]	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G; T.C. 3A21	SA1420WE	Installation of Brittain Industries B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G, H, J; T.C. 3A21	SA2689SW	Install TSIO-520-M engine. Issued 12/9/77.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
210H; T.C. 3A21	SA725CE	Installation of electric gyros and standby power source.	CE	43374	Humphrey, Incorporated 434 North Oliver Wichita, KS 67208
210J; T.C. 3A21	SA2249WE	Installation of Brittain Industries B-7, NAV-2B, B2C and BSS flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210J, T210J, 210K, T210K; T.C. 3A21	SA1326SW	Mitchell automatic flight system AK334, consisting of Century II autopilot with optional radio coupler, and automatic aileron stabilizer. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210J, T210J, 210K, T210K; T.C. 3A21	SA1327SW	Mitchell automatic flight system AK332, consisting of Century I autopilot with optional omni tracker. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA71RM	Installation of JB Systems air conditioning system. Amended 6/8/79.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA210NW	Collins AP-107 low profile 3 axis automatic flight control system. Amended 12/2/77.	NW	24250	Collins Radio Group 855 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210F, 210L, T210L, 210M, T210M; T.C. 3A21	SA211NW	Installation of Collins AP-107 low profile two axis automatic flight control system. Amended 12/2/77.	CE	24250	Collins Radio Group 855 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA212NW	Installation of AP-107 low profile yaw damper system. Amended 12/2/77.	CE	24250	Collins Radio Group 355 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K; T.C. 3A21	SA1325SW	Mitchell automatic flight system AK331, consisting of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K; T.C. 3A21	SA2199WF	Installation of Brittain Industries B-7, NAV-2B, B2C, and BSS flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210K, T210K, 210L, T210L; T.C. 3A21	SA509SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 3/3/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210K, T210K, 210L, T210L, 210M, T210M, T210N; T.C. 3A21	SA1202CE	Installation of King Model KFC-200 two axis flight control system with or without flight director. Amended 11/28/78.	CE	48250	King Radio Corporation 400 North Robers Road Olathe, KS 66061
210L, T210L; T.C. 3A21	SA1506SW	Mitchell aytomatic flight system AK388, consisting of Century III autopilot with optional automatic pitch trim, radio and glide slope coupler. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA1507SW	Mitchell automatic flight system AK386 consisting of Century I with optional omni tracker. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA1526SW	Mitchell automatic flight system AK387, consisting of Century IIB autopilot with optional radio coupler. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3001SW-D	Automatic flight system AK468, Century IV autopilot or AK468FD Century IV flight director with electronic command/automatic pitch trim and optional remote annuciator panel. Issued 4/26/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3112SW-D	Automatic flight system AK566 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/5/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3247WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder Autopilot Systems and/or Pitch Trim Systems. Issued 8/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
210L, T210L, 210M, T210M; T.C. 3A21	SA1006SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 6/30/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210L, 210M; T.C. 3A21	SA3685WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
210L, 210M, T210L, T210M; T.C. 3A21	SA3182SW-D	Mitchell automatic flight system AK387 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
210L, 210M, T210L, T210M; T.C. 3A21	SA3183SW-D	Mitchell automatic flight system AK386 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210 S/N 21061040 and up, P210N, 210M, T210M, T210N: T.C. 3A21	SA3835WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow Amended 6/12/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714
210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA1005SO	Installation of Bendix FCS-870 automatic flight control system, or installation of Bendix FCS-870 automatic flight control system with reduced flap motor speed. Amended 12/13/79.	SC	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210N, P210N, T210N; T.C. 3A21	SA756NW	Installation of leading edge stall strips, change aileron droop. Issued 4/20/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N; T.C. 3A21	SA760NW	Installation of RCA digital weather radar system. Issued 5/3/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N, P210N; T.C. 3A21	SA1420CE	Install wing leading edge cuffs (with or without de-icer boots) and wing stall fences. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
P210N; T.C. 3A21	SA1487CE	Installation of King KFC200 AFCS, two axis, with or without flight director. Issued 5/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
P210N; T.C. 3A21	SA1552CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
P210N; T.C. 3A21	SA3289SW-D	Mitchell automatic flight system AK737 consisting of Century IIB autopilot with optional radio and glide slope couplers. Issued 6/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P210N; T.C. 3A21	SA3290SW-D	Mitchell automatic flight system AK738 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P210N; T.C. 3A21	SA3291SW-D	Mitchell automatic flight system AK739 consisting of Century IV autopilot or AK739FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 210 Mineral Wells, TX 76067
210-5 (205), 210-5A (205A); T.C. 3A21	SA993CE	Install STOL kit (leading edge cuff, droop tips, stall fence and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
T210F, G, H, J, K, L, TU206A, B, C, D, E, F, TP206A, B, C, D, E; T.C. 3A21, A4CE	SA4111SW	Hartzell PHC-J3YF-IRF/F7663-2Q propeller. Issued 4/10/80	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
T210L, T210M; T.C. 3A21	SA3857WE	Installation of an air/oil separator. Issued 3/13/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nusy, CA 91409
305 Series; T.C. 5A5	SA504SW	Rerouting of oil to oil cooler and addition of extra cooler.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA295SW	Three-place configuration.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA353SW	Conversion of aircraft for parachute jumping operations.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA505SW	McCauley 1A200PM propeller.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA568SW	Gross weight increased to 2,300 2,300 pounds.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
305A; T.C. 5A5	SA1201SW	Lycoming O-540-A4B5 engine. Reissued 3/19/75.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
305A; T.C. 5A5	SA1620SW	Cessna 180 fuel cells. Issued 4/19/73.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA1702SW	20-gallon fuel cells. Issued 7/19/73.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A, 305B; T.C. 5A5, 3A14	SA3-370	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
305A, B, C, D, E, F; T.C. 5A5, 3A14	SA2857SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
310 Series: T.C. 3A10	SA1-21	Federal autopilot F-400.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
310 Series; T.C. 3A10	SA1-293	Lightweight reservoir pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-506	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-579	Taxi lamp in right outboard cowling.	GL	22400	Cincinnati Aircraft, Inc. Lunken Airport Cincinnati, OH 45202
310 Series; T.C. 3A10	SA3-55	Radio equipment.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
310 Series; T.C. 3A10	SA3-440	L-3 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA3-475	Full feathering, constant speed propellers, hubs 2AF36C26, blades 90MF-10.	GL	52720	McCauley Industrial Corporation 1807 Howell Avenue Dayton, OH 45401
310 Series; T.C. 3A10	SA3-636	M-4 flight control system with altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA3-643	Transa-Strobe beacon B-7228.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
310 Series; T.C. 3A10	SA3-662	Hydraulic accumulator in each engine nacelle and new propeller governor C210355 or A210438.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
310 Series; T.C. 3A10	SA3-665	Cabin air temperature control system on Southwind (Stewart-Warner) 8240-A heater.	GL	82500	Vap-Air Division Vapor Corporation 6444 W. Howard Street Chicago, IL 60607
310 Series: T.C. 3A10	SA4-3	32-gallon auxiliary fuel tank in baggage compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-127	56-gallon auxiliary fuel tank in hat rack compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-239	Thompson TF2800 engine-driven fuel pump.	WE	33460	Engineering Modification Company 6850 Vineland Avenue North Hollywood, CA 91603
310 Series; T.C. 3A10	SA4-702	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
310 Series; T.C. 3A10	SA4-1217	Extension of augmenter tubes to trailing edge of wing.	WE	10116	AMC Augmenters 2648 N. Campbell Tucson, AZ 85700

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310 Series; T.C. 3A10	SA4-1400	SP-3 autopilot.	WE	74570	Sperry Phoenix Company P.O. Box 2529 Phoenix, AZ 85000
310 Series; T.C. 3A10	SA4-1598	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA6SO	Window on each side of cabin between fuselage stations 69.25 and 109.375. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA37SO	Fuselage access holes in bottom skin of fuselage.	SO	76830	Sunny South Aircraft Service, Inc. 300 S.W. 41 Street County International Airport Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA44CE	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA58SO	Dual camera ports. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA59SO	One-piece windshield	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA60SO	Third window on each side of fuselage.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA61SO	Underwing exhaust system and nacelle fairings.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA77SO	Engines modified per STC SE738O.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Fort Lauderdale, FL 33300
310 Series; T.C. 3A10	SA97SO	A, B, or C of turbocharged Continental IO-470-D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA99SO	Auxiliary fuel tanks under nacelle fairing (4-tank and 6-tank systems).	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA109EA	Pump type pneumatic deicing system.	GL	38500	B.F Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA119CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA202SW	Cessna 0895000-8, -9 aft cowling doors.	SW	08168	Airline Aviation, Inc. P.O. Box 1024 Roswell, NM 88201
310 Series; T.C. 3A10	SA248SO	Increase takeoff gross weight to 4,830 pounds. Reissued 8/6/74.	SW	66150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA254SO	Swept vertical tail. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA303CE	Installation of Bendix Model M-4B/C autopilot flight control system. Amended 2/20/69.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA325CE	GUARD system (Gear Up Automatic Response Device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612
310 Series; T.C. 3A10	SA347SW	Cowling and exhaust system.	SW	60089	Modern Aero Sales, Inc. 4837 S. Hampton Road Dallas, TX 75221
310 Series; T.C. 3A10	SA348WE	Installation of air induction system. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2606 E. Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310 Series; T.C. 3A10	SA385WE	Turbocharged Lycoming IO-540-A1A5 engines. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA390WE	Pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA444NW	Replace original split flaps with Fowler flaps. Issued 5/12/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
310 Series; T.C. 3A10	SA448EA	Electrothermal propeller deicing system.	GL	38500	The B.F. Goodrich Company Municipal Airport Akron, OH 44318
310 Series; T.C. 3A10	SA457SW	AK145 automatic pitch trim.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA477SO	Modify control wheel. Issued 10/27/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602 IAB Miami, FL 33148
310 Series; T.C. 3A10	SA517WE	Flight control system B-4, including pitch assist PC-1, altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, INc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA621SW	AK198 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA678SW	Lear or Motorola L-2C autopilot.	SW	03120	Aerotron Radio Company International Airport Tulsa, OK 74101
310 Series; T.C. 3A10	SA737SW	AK201 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310; T.C. 3A10	SA1359CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
310 Series; T.C. 3A10	SA1490WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1799WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1896WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA2406SW	Addition of hydro seal fluid additive to nose and main gear shock strut. Issued 2/11/77.	SW	49722	Granville Lasseter 802 East Grant Street Morton, TX 79346
310, 310A thru 310J, 320, 320A, B, C, D; T.C. 3A10, 3A25	SA1-620	Kit No. 2014X for 12-inch RCA AVQ-45, AVQ-47, AVQ-50, AVQ-55 and 12-inch Collins WP-103 radar antenna. Amended 4/15/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310B, 310C; T.C. 3A10	SA1-185	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
310 thru 310Q, T310P, Q, E310H, J, T310R, 320 thru 320F, 340, 340A, 337G, 336, 337, 337B, C, D, E, F, G, T337B, C, D, E, F, G, 401, 401A, B, 402, 402A, B, 404, 411, 411A, 414, 414A, 421, 421A, B, C; T.C. 3A10, 3A25, A7CE, A6CE, A2CE	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 9/25/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310, 310A thru 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P., T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA111GL	Install Cleveland conversion kit P/N 199-64. Issued 6/30/76.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Industries, Inc. 1160 Center Road Avon, OH 44011
310-A thru 310-K, 320A thru 320-D, 320-1; T.C. 3A10, 3A25	SA302CE	Supplemental high intensity position light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
310, 310A thru H, E310H, 310J, J-1, E310J, 310K, L, N, 320, 320-1, 320-A, B, C, D, E, F, 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA362CE	Install Hoskins Twilighter Mk III and Mk IIIB light system. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
310, 310A thru J, 320, 320A thru D; T.C. 3A10	SA396EA	Installation of Radome Kit No. 2310X-R. Reissued 4/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310C; T.C. 3A10	SA814SW	Underwing exhaust.	SW	08168	Airlane Aviation, Inc. P.O. Box 1024 Roswell, NM 88204
310, 310A thru 310F; T.C. 3A10	SA574WE	Installation of leading gear position mirror on left wing tip tank. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
310, 310A, B, C, D, E, F, G, H, I, J, K, L, N, P, Q, E310H, 310J-1, E310J, T310P, T310Q; T.C. 3A10	SA3235WE	Installation of recognition light assembly on horizontal stabilizer. Issued 7/13/76.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
310, 310A, B, C, D, E, F, G, H, I, J, K, L, N, P, Q, R, T310P, T310Q, T310R; T.C. 3A10	SA4136WE	Installation of inflatable door seal. Issued 4/10/80.	WE	36320	Bob Fields Aerocessories 340 "E" East Santa Maria St. San Paula, CA 93060
310, 310B; T.C. 3A10	SA26SO	Aerodynamic clean-up, cabin soundproofing, new interior and cooling duct changes. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310F, 310Q; T.C. 3A10	SA74SO	Installation of seats and camera port. Reissued 9/10/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D; T.C.- 3A10	SA76SO	Installation of two (2) R.H. and two (2) L.H. single seats and enlarged emergency exit. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B thru 310G; T.C. 3A10	SA212SO	Installation of Lycoming IO-540-A1A5 engines and Hartzell HCA3XK-2B/7636D propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D, 310F; T.C. 3A10	SA455SO	Installation of extended window modification. Issued 3/18/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
310, 310F thru N; 320, 320-1, 320A thru F; 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA240WE	Consolidation of STCs SA355CE and SA362CE into one STC having MASTER ELIGIBILITY LIST - amended to include improved power supply assembly and subchassis timer assembly for Twilighter MK III high intensity supplementary lighting system. Issued 8/16/71.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
310B, C, D, E, F, G, H, I, J, K, L, N, P, Q, T210P, T210Q; T.C. 3A10	SA3243WE	Installation of pilot's and co-pilot's side vent windows. Issued 8/13/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
310C thru 310G; T.C. 3A10	SA2383WE	Installation of turbo-charged Continental IO-470-D engine. Issued 8/18/71.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310C, D, F, G, H, I, J, K, L, N, P, Q, T310P, T310Q, T310R; T.C. 3A10	SA3671WE	Installation of Fueltron IIIG or IIIP digital fuel flow indicating system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
310D; T.C. 3A10	SA391GL	Installation of Great Lakes Aero Products windshield P/Ns W-2070, W/T-2070 or W/G-2070. Issued 3/3/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
310D thru 310L, 310N, 310P, 320, 320A thru 320F; T.C. 3A10, 3A25	SA2534WE	Installation of Cessna 310P-type fiberglass tail stinger and yaw reduction adapter. Amended 5/30/73.	WE	01750	Aerocessories Company 1779 Fitzgerald Road Simi, CA 93065
310D, G, H, I, J, K, L; T.C. 3A10	SA3078SW-D	Auto flight system AK556, Century IV autopilot or AK556FD Century IV flight director. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J; T.C. 3A10	SA3079SW-D	Mitchell yaw damper system YK 558. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J; T.C. 3A10	SA3082SW-D	Automatic flight system AK557, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, E, F, G, H, I, J, K, L, N, P, Q, R, T310P, T310Q, T310R, 320-1, 320C, D, E, F; T.C. 3A10, 3A25	SA3105SW-D	Mitchell automatic flight system AK584 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310F, 310G; T.C. 3A10	SA752EA	Installation of ground to air recovery equipment. Restricted Category. Amended 8/6/69.	EA	09500	All American Eng. Company Box 1247 Lancaster Pike & Center Road Wilmington, DE 19899
310G, H, I, J, K, L, N, P; T.C. 3A10	SA412SO	Installation of Continental IO-520-E engines. The engines are limited to 260 hp. Amended 12/16/71.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
310G, H thru Q, J-1; E310H, J; T310P, Q; 320A, B thru F; 402, A, B, 401, A, B; 411, A; 414; 421, A, B; T.C. 3A10, 3A25, A7CE	SA568EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-0107-1. Amended 11/7/75.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
310G thru 310Q, 310R, 320A thru 320F, 340A, 401, 401A, B, 402, 402A, B, 411A, 414, 421, 421A, B; T.C. 3A10, 3A25, A7CE	SA574NW	Installation of forward facing recognition lights and clear plastic wing tip tank nose cone. Amended 4/13/78.	NW	28850	Robert M. DeBorde 20645 S.W. Clarion Aloha, OR 97005
310G, H, I, J, K, L, M, P, 310Q thru 310Q-0601; T.C. 3A10	SA3789WE	Installation of 36-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
310H; T.C. 3A10	SA294SO	Installation of turbocharged Continental IO-470-D engines. Reissued 12/5/74.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90801
310H thru 310L, 320 thru 320E, 401, 402; T.C. 3A10, 3A25, A7CE	SA1847WE	Installation of Brittain Up-Command Signal Adapter Kit. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310I, 310J; T.C. 3A10	SA181SO	Installation of turbosupercharged Continental IO-470-U engines. Amended 8/9/68.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
310I, J, K, L, M, P, Q, R, T310P, T310Q, T310R, 320A, B, C, D, E, F, 340, 401, 401A, B, 402, 402A, B, 414, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA107GL	Conversion of oil lubricated deice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
310I, J, K, L, N, P, R, Q, T310P, T310Q, T310R; T.C. 3A10	SA701CE	Install Airborne wing and tail pneumatic deice kit 703B. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310I, L, N, P, Q, T310P, 320C, 320E; T.C. 3A10, 3A25	SA1883SW	Install Hartzell synchrophase system. Issued 6/11/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708
310I, J, K, L, M, P, Q; 320B, C, D, E, F; T.C. 3A10, 3A25	SA1904SW	Additional auxiliary transfer tanks. Issued 8/13/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708
310J, E310J, T310P, T310Q, 310K, 310L, 310N; 320D, 320E, 320F, 340; 401, 401A, 401B, 402, 402A, 402B, 414, 411, 411A, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA14GL	Installation of detachable lead strap propeller deicers. Issued 3/20/73.	GL	44318	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310J, K, L, N, P, Q, R, T310P, T310Q, T310R; T.C. 3A10	SA471SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 6/3/76.	SC	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
310K, 310L, 310N, 310P, 310Q, 320E, 320F; T.C. 3A10, 3A25	SA42GL	Install Norton Company radome kit No. 3060X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310K, 310L, 310N, 320E, 320F, 310P, 310Q; T.C. 3A10, 3A25	SA490EA	Installation of Chamberlain Radome Kit No. 3060K-B for Bendix radar RDR-100 or RDR-110 systems. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310K, L, N, P, Q, 320E, 320F; T.C. 3A10, 3A25	SA150GL	Install Norton Company radome Kit No. 4131X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310K, L, N, P, Q, 320F; T.C. 3A10, 3A25	SA537EA	Installation of Radome Kit No. 3060X-R. Amended 8/25/72.	GL	61750	Norton Company Plastics & SYnthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310L, N, P, Q; T.C. 3A10	SA2082WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Bartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68145	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
310N; T.C. 3A10	SA2784WE	Installation of Ontrac II VLF 1000 very low frequency navigation system. Amended 12/3/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3266WE	Installation of ONTRAC III VLF/Omega navigation system. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway AVenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3287WE	Installation of Ontrac III VLF/Omega navigation system as a means of navigation (but not sole means) for EN ROUTE navigation. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3924WE	Installation of ONTRAC IIIA VLF/Omega navigation system. Issued 5/25/79.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N, P, Q, T310Q; T.C. 3A10	SA3018SW-D	Automatic flight system AK442 consisting of Century III autopilot with optional command and auto. elec. elevator pitch trim, radio, and glide slope coupler. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, Q, T310P, Q; T.C. 3A10	SA3019SW-D	Automatic flight system AK443 and AK443FD consisting of Century IV autopilot and Century IV flight director autopilot with trim system and annuciator panel. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, T310P, T310Q; T.C. 3A10	SA3020SW-D	Automatic flight system YK444 consisting of yaw damper. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310P, 310Q; T.C. 3A10	SA592NW	Installation of Fowler flaps. Issued 4/14/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
310P, 310Q, T310P, T310Q; T.C. 3A10	SA137NW	Installation of Collins AP-107 low profile automatic flight control system (FCS), including yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA138NW	Installation of Collins low profile yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA875EA	Installation of Brittain Industries, Inc. flight control system Model B-7 or NAV-2B or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310P, T310P, 310Q; T.C. 3A10	SA1142SW	Edo-Aire Mitchell automatic flight system, AK300 consisting of Century III with pitch trim, radio, and glide slope coupler. Issued 5/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P, Q, N, T310P, T310Q; T.C. 3A10	SA1190SW	Mitchell automatic flight FD/AP282-300 consisting of flight director/automatic pilot and automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P/T310P, 310Q/T310Q, 310R/T310R; T.C. 3A10	SA1273CE	Installation of King KFC 200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 4/14/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
310 P/T 310P, 310Q/ T310Q, 310R/T310R; T.C. 3A10	SA1555CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
310P, 310Q, 310R; T.C. 3A10	SA2203WE	Installation of air conditioning system. Amended 6/3/76.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
310P, T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA3602WE	Installation of vapor cycle airconditioning system. Issued 3/6/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
T-310; T.C. 3A10	SA192RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
T310, 320, 320A, B, C, D, E, F, 340, 401, A, 411, A, 414, 421, A, B; T.C. 3A10, 3A25	SA3RM	Modification of engine exhaust stacks by replacement of expansion joint with slip fit joint. Reissued.	RM	41750	Heliarc Welding Service, Inc. 3916 Niagara Street, Box 7301 Denver, CO 80207
T310 Series, 320A, B, C, D, E, F, 401, 401A, 402, 402A, B, 404, 414, 421C; T.C. 3A10, 3A25, A7CE	SA103RM	Installation of exhaust turbo connector, P/N 30477-3 Issued 8/17/77.	RM	41750	Heliare Welding Service, Inc. 3965 Newport Denver, CO 80207
T310 Series, 320, 320A, B, C, D, E, F, 340, 340A; T.C. 3A10, 3A25	SA110RM	Modify Cessna exhaust system by replacement of the inter-cylinder expansion joints with a slip fit joint.	RM	41750	Heliare Welding Service, Inc. 3965 Newport Denver, CO 80207
T310L;	SA530NW	Installation of McCauley D3A34C402/90DFA-10 propeller on Continental TSIO-520-H engine. Issued 10/4/77.	NW	67090	Keith L. Remington 253 S.W. 4th Avenue Ontario, OR 97914
T310P; T.C. 3A10	SA1018SW	Bendix M4-C autopilot.	SC	15475	Bendix Avionics P.O. Box 9414 Fort Lauderdale, FL 33310
T310P; T.C. 3A10	SA2292WE	Modification of waste gate controls. Issued 1/20/71.	WE	25400	Comp Air, Inc. 1285 Rollins Road Burlingame, CA 94010

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
T310P, T310Q, 320, 320-1, 320A thru 320F, 340, 411, 411A, 401, 401A, B, 402, 402A, B, 421, 421A, 414; T.C. 3A10, 3A25, A7CE	SA128GL	Replace existing asbestos or bellows exhaust seal with slip joint. Reissued 12/15/78.	GL	84915	Frank Webner 725 N. Hamilton Road Columbus, OH 43219
T310P, Q, 320D, E, F; T.C. 3A10, 3A25	SA2750SW	Install Continental TSIO-520-E engine. Issued 4/10/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
T310P, T310Q, T310R, 320D, 320F; T.C. 3A10, 3A25	SA2862SW	CFS-2000 electronic fuel flow metering system. Issued 10/18/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
T310P, T310Q, T310R, 320D, E, F; T.C. 3A25	SA4011SW	Installation of TSIO-520-N, or TSIO-520-NB engine. Issued 7/9/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
310Q; T.C. 3A10	SA723CE	Incorporate openable windows and drop hole.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
310Q, T310Q; 310R, T310R; T.C. 3A10	SA775CE	Installation of janitrol Aero Division vapor cycle air conditioning system. Amended 12/9/74.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
T310Q; T.C. 3A10	SA2242SW	Continental TSIO-520-J engines. Issued 9/15/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
310R; T.C. 3A10	SA103GL	Install Norton Company radome Part No. 4096X. Amended 6/22/76.	GL	61750	Norton Company P.O. Box 350 Akron, OH 44309
310R; T.C. 3A10	SA1081CE-D	Installation of Collins Radio Group AP-106, 3-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1082CE-D	Installation of Collins Radio Group AP-107, 3-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1083CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1084CE-D	Installation of Collins Radio yaw damper system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R/T310R; T.C. 3A10	SA1301CE	Installation of Enk Aviation fire suppression system. Amended 11/28/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
310, 320; T.C. 3A10, 3A25	SA99SW	Automatic pilot AK113 and lateral guidance radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320; T.C. 3A10, 3A25	SA234EA	Installation of Chamberlain 2310K-B series radome kit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309
310, 320; T.C. 3A10, 3A25	SA237SO	Control wheel modification. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 320 Series; T.C. 3A10, 3A25	SA272EA	Installation of Chamberlain 2014K-B radome kit as follows: Kit No. 2014K-B for Bendix RDR-100 or RDR-110 radar systems with 12" antenna and transmitter receiver unit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309
310, 320 Series; T.C. 3A10, 3A25	SA338SW	Automatic pilot AK125.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA409SW	Automatic pitch trim AK137.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA446CE	30-gallon auxiliary fuel tank in baggage compartment.	CE	36000	FloAir, Inc. Municipal Airport Newton, KS 67114

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
310, 320 Series; T.C. 3A10, 3A25	SA455WE	Single-piece windshield.	WE	20630	Cessna Components, Inc. P.O. Box 521 Long Beach, CA 90801
310, 320 Series; T.C. 3A10, 3A25	SA471EA	SAGA (Semi-automatic gear actuating) system.	GL	44010	In-Flight Services Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
310, 320 Series; T.C. 3A10, 3A25	SA521SW	Automatic pilot AK157 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA667SW	AK222 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA722WE	30-gallon wing leading edge fuel tanks. Amended 9/2/65.	WE	20630	Cessna Components, Inc. 3200 Airport Avenue Santa Monica, CA 90406
310, 320 Series; T.C. 3A10, 3A25	SA1175WE	One-piece windshield.	WE	14230	Cee Bailey's Aircraft Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
310, 320 Series; T.C. 3A10, 3A25	SA1452WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1604WE	Installation of Brittain B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1880WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; 320 Series; 336 Series; 337 Series; 401, 402, 411, 421 Series; T.C. 3A10, 3A25, A2CE, A6CE, A7CE	SA1675WE	Installation of exhaust gas temperature monitoring systems Model EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
320 Series; T.C. 3A25	SA3-737	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA101SO	One right-hand and two left-hand single seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320 Series; T.C. 3A25	SA104EA	L-2C autopilot slave cables around existing approved camera opening in lower surface of fuselage.	EA	20630	Aero Service Corporation North Philadelphia Airport Philadelphia, PA
320 Series; T.C. 3A25	SA117CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA119SO	Passenger seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320 Series; T.C. 3A25	SA127SW	Auxiliary baggage compartment and adjustable seat modification.	SW	37154	Gen-Aero, Inc. P.O. Box 6767 San Antonio, TX 78205
320 Series; T.C. 3A25	SA130CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA306CE	GUARD System (gear up automatic response device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
320 Series; T.C. 3A25	SA492SW	Emergency alternate air door actuation.	SW	33270	El Paso Natural Gas Company P.O. Box 1492 El Paso, TX 79910
320 Series; T.C. 3A25	SA632WE	B-4 flight control system including pitch assist PC-1, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
320 Series; T.C. 3A25	SA744SW	M4B/C autopilot.	SO	15475	The Bendix Corporation Avionics Group P.O. Box 9414 Fort Lauderdale, FL 33310
320, 320-1; T.C. 3A25	SA285SO	Installation of Lycoming IO-540-A1A5 powerplants and Hartzell HCA3XK-2B/7636D propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320, 320-1, 320A, 320B, 320C; T.C. 3A25	SA518SO	Installation of Continental IO-520-E derated engines and McCauley D3AF32C87/82NC-6 or -8 propellers. Issued 8/28/72.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F (320 series S/N's 0001-D9999; 320E0001-F9999); T.C. 3A25	SA110GL	Install Cleveland conversion kit P/N 199-64. Issued 6/30/76.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
320, 320A, 320B, 320C, 320D, 320E, 320F S/N's 0001 and on; T.C. 3A25	SA808CE	Install Airborne wing and tail pneumatic deice kit 703C. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
320, 320-1, 320A, B, C, D, E, F, 340; T.C. 3A25	SA3231WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
320, 320A; T.C. 3A25	SA3239WE	Installation of nacelle baggage lockers. Issued 7/27/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, B, C, D, E, F; T.C. 3A25	SA3242WE	Installation of pilot's and co-pilot's side vent windows. Issued 7/30/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, 320B, 320C, 320D, 320E, 320F; T.C. 3A25	SA3822WE	Installation of 34-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
320, 320A thru 320F, 320-1, 340; T310P, T310Q; 401, 401A, B, 402, 402A, B; 411, 411A, 414, 421, 421A; T.C. 3A25, 3A10, A7CE, A7CE	SA1642WE	Modification of exhaust system components. Amended 12/7/73.	SW	87348	Wooley Tool & Manufacturing Div. Chromalloy American Corporation P.O. Box 3508 Odessa, TX 79760
320A, B, C, D, E, F, 340, 340A; T.C. 3A25	SA193RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welidng Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
320A, B, C, D, E, F, 320-1; T.C. 3A25	SA3164SW-D	Install automatic flight system AK584 consisting of Century IIB automatic pilot with optional radio coupler. Issued 11/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
320A thru 320D; T.C. 3A25	SA2339WE	Installation of exhaust bellows. Issued 4/12/71.	WE	01735	Aero Bellows Manufacturing Company 3211B Winona Avenue Burbank, CA 91504
320E, 320F; T.C. 3A25	SA4GL	Installation of Bendix FCS-810 autopilot flight director system. Issued 10/18/72.	GL	47767	Ralph Kerns Kerns Aircraft Electronics, Inc. Weir Cook Municipal Airport Indianapolis, IN 46206
320E, 320V; T.C. 3A25	SA2122WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Hartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
320F; T.C. 3A25	SA4012SW	Dual camera port. Issued 7/6/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
335, 340, 340A; T.C. 3A25	SA914EA	Installation of Radome kit P/N 4057KX. Amended 7/10/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
335, 340A; T.C. 3A25	SA1302CE	Install Enk Aviation fire suppression system. Amended 10/9/79.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
336; T.C. A2CE	SA203SW	Right front seat replaced with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72003
336; T.C. A2CE	SA286NW	Request for multiple STC on Model 336. Issued 4/23/76.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
336; T.C. A2CE	SA445SW	Automatic pilot AK140, pitch trim system AK141, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
336; T.C. A2CE	SA936CE	STOL Kit installation. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
336; T.C. A2CE	SA1260CE	Install FiQuench extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
336; T.C. A2CE	SA1355CE	Chrome-plated brake disc installation. Issued 8/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
336; T.C. A2CE	SA1875SW	Wing edge leading cuffs, wing tips, vortex generators on fuselage and fairing on vertical tails. Reissued 9/15/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
336, 337; T.C. A6CE, A2CE	SA1056SW	Revise wing contours leading edge and redesign landing light deflector plates. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
336, 337, 337A thru C; T.C. A6CE, A2CE	SA406CE	Hoskins Supp. Position Light System includes Model A wing tip lights, Model 2 fuselage light used as tail light or Model L tail light. Reissued 10/17/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
337; T.C. A6CE	SA491SW	Automatic pilot AK135, automatic pitch trim AK156, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA668SW	AK210 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA1473CE	Installation of Tull microwave landing system with modified King KX175B and KN 73 receivers. Issued 2/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
337; T.C. A6CE	SA2200WE	Installation of Brittain Industries B2C and BSS flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
337, 337A, B, C, D, E, F, G, H, T337B, C, D, E, F, G, H, P337H; T.C. A6CE	SA385GL	Installation of Norton radome kit No. 4231X. Issued 2/1/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
337, 337A, B, C, D, E, F, G, M337B, T337B, C, D, E, F, G; T.C. A6CE	SA937CE	Installation of STOL kit (leading edge cuffs, stall fence, droop wing tips, and vortex generators on rear engine lower cowling). Amended 5/25/78.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
337, 337A, B, C, D, E, F, G, M337B, N337B, T337B, C, D, E, F, G; T.C. A6CE	SA1258CE	Installation of FIQUENCH fire extinguishing system in cabin and/or fire extinghishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
337, 337A, 337B, T337B, 337C, 337D, 337E, 337F, 337G; T.C. A6CE	SA1558SW	Vortex generators on fuselage, wing leading edge cuffs, wing tips, and fairings on vertical tail. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
337, 337A (USAF 02B), 337B, M337B (USAF 02A), 337C, T337B, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G; T.C. A6CE	SA1627WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, stall fences, aileron centering springs, conical cambered wing tips and flap actuated elevator trim spring. Also takeoff gross weight increase for all models except for T337G and 337G. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
337, 337A; T.C. A6CE	SA2335WE	Installation of one-piece windshield and relocation of compass. Reissued 5/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route 1, Box 127D Leesburg, FL 32748
337, 337A, B, C, D, E, F, G, M337B, T337B, T337C, T337D, T337E, T337F, T337G; T.C. A6CE	SA3056WE	Installation of fuel flow instruments. Issued 8/15/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
337, 337A, 337B, T377B, 337C, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G, T337P; T.C. A6CE	SA3818WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
337, T337, 337E, T337E; T.C. A6CE	SA1356CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
337A; T.C. A6CE	SA190SO	Cabin door removed and wind deflector installed.	SO	90106	Young, Isherwood & Marsh P.O. Box 982 Christiansted St. Croix, Virgin Islands
337A; T.C. A6CE	SA801SW	Mitchell AK244 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A thru 337H, T337B thru H, P337H; T.C. A6CE	SA32RM	Installation of electrically driven freon air-conditioning system. Amended 11/9/78.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA1922SW	Automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 10/11/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA3250SW-D	Mitchell automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 11/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337B; T.C. A6CE	SA842SW	AK252 consisting of Century III autopilot with optional pitch trim stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337D; T.C. A6CE	SA672CE	Install auxiliary fuel tank in baggage area.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
337D; T.C. A6CE	SA678CE	Install fuselage top emergency exit door.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
337D; T.C. A6CE	SA1038EA	Installation of recognition lights (LCGC) on trailing edge of Robertson wing tips. Issued 8/9/76.	EA	29990	DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
337D, T337D, 337G, T337G; T.C. A6CE	SA478NW	Installation of Bendix weather radar system. Amended 4/13/78.	NW	67135	Renton Aviation, Inc. 840 Perimeter Road Renton, WA 98055
337D, 337E, 337F, 337G, T337D, T337E, T337F; T337G; T.C. A6CE	SA482SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and flight direcotr indicator. Amended 7/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
337E, F; T.C. A6CE	SA1359SW	Mitchell automatic flight system FD/AP282-345 consisting of flight director/autopilot with optional pitch trim. Issued 5/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
337E, F; T.C. A6CE	SA1478SW	Mitchell automatic flight system AK345 consisting of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 6/9/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067
337E, F.; T.C. A6CE	SA1520SW	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 10/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3148SW-D	Mitchell automatic flight system AK537 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3149SW-D	Mitchell automatic flight system AK536 consisting of Century IV autopilot or Model AK536FD flight director autopilot with optional remote annuciator. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3252SW-D	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 11/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337G; T.C. A6CE	SA1205CE	Installation of King KFC-200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/6/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
F337E, FT337E, F337F, FT337F, F337G, FT337GP; T.C. A23EU	SA1259CE	Install FiQuench fire extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
340 Series; T.C. 3A25	SA186NW	Installation of Continental TSIO-520-J engine. Issued 5/30/75.	NW	85165	Western Skyways Portland/Trourdale Airport Troutdale, OR 97060
340 Series; T.C. 3A25	SA474NW	Replace original split flaps with Fowler flaps.	NW	68500	Robertston Aircraft Corporation 939 West Perimeter Road Renton, WA 98055
340; T.C. 3A25	SA1357CE	Chrome-plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
340 Series; T.C. 3A25	SA1441SW	Mitchell automatic flight system AK367 consisting of Century III autopilot with optional automatic pitch trim, radio, and glide slope couplers. Issued 3/15/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA1442SW	Mitchell automatic flight system FD/AP282-367 consisting of flight director/autopilot with automatic electric trim. Issued 3/3/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA1881SW	Continental TSIO-520-J engine. Issued 5/23/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
340 Series; T.C. 3A25	SA1979SW	In-Line fuel pumps for auxiliary tanks. Issued 5/8/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
340 Series; T.C. 3A25	SA2346SW	Teledyne Continental TSIO-520-N engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340; T.C. 3A25	SA2770SW	Cleveland heavy duty brakes. Issued 5/9/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340 Series; T.C. 3A25	SA3043SW-D	Mitchell automatic flight system AK525 or AK525 FD consisting of Century IV autopilot with command/ automatic electric pitch trim system and optional remote annuciator panel. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA3044SW-D	Mitchell automatic flight system YK525 consisting of yaw damper system. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340; T.C. 3A25	SA3485WE	Installation of Continental TSIO-520-N engines and increase takeoff power to 310 h.p. Amended 11/18/77.	WE	68120	Riley Aircraft Corporation 2303 Palomar Airport Road Carlsbad, CA 92008
340, 340A; T.C. 3A25	SA16RM	Installation of freon type air conditioning system. Amended 10/6/77.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
340, 340A; T.C. 3A25	SA281GL	Install Cleveland conversion kit P/N 199-72. Issued 11/8/78	GL	23260	Cleveland Wheels and Brakes Van Sickle Div. of Parker Hannifin 1160 Center Road Avon, OH 44011
340, 340A; T.C. 3A25	SA502SO	Installation of Bendix FCS-810 automatic flight control system including manual eletric trim and optional flight director indicator DH-841. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340, 340A; T.C. 3A25	SA1062CE	Installation of Collins AP-107 autopilot. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
340, 340A; T.C. 3A25	SA2483SW	Increase seating capacity on aft baggage shelf for a total of 7 occupants. Reissued 3/20/78.	SW	66300	RAM Aircraft Modification P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340, 340A; T.C. 3A25	SA2844SW	Installation of SDI Model CPS-2000, -2001, or FT-200 indicating fuel flow system. Amended 3/9/79.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
340, 340A; T.C. 3A25	SA3610WE	Installation of Silver Instruments Fueltron IIIG or IIIP fuel flow and totalizer system. Amended 4/24/80.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94515
340, 340A; T.C. 3A25	SA3871WE	Installation of vapor cycle air conditioning system. Issued 1/15/80.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
340, 340A (S/Ns 340A0001 thru 340A0600); T.C. 3A25	SA3923WE	Installation of Lycoming TIO-540-R2AD engines. Issued 6/1/79.	WE	68120	Riley Aircraft Corporation 2016 Palomar Airport Road Carlsbad, CA 92008
340-0001 and on; T.C. 3A25	SA55GL	Install Airborne wing and tail pneumatic deice kit 710. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
340A; T.C. 3A25	SA1015SO	Installation of Bendix FCS-870 automatic flight control system, including manual electric trim and optional flight director system. Issued 8/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
340A; T.C. 3A25	SA1025SO	Installation of a Bendix NP-2041A area navigation computer programmer. Issued 10/4/78.	SO	15475	Bendix AVionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340A; T.C. 3A25	SA1276CE	Install King KFC 200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or KG-258 attitude horizon gyro and a KC-292 mode controller. Amended 5/8/78	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
304A; T.C. 3A25	SA1551CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, 421B, 421C; T.C. A7CE	SA197GL	Install Cleveland conversion kit P/N 199-76. Amended 8/28/78.	GL	23260	Cleveland Wheels and Brakes Div. of VanSickle Ind., Inc. 1160 Center Road Avon, OH 44011
401, 401A, 401B, 402, 402A, 402B (normal category); T.C. A7CE	SA29NW	Installation of Fowler Flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 2/23/73.	NW	68500	Robertson Aircraft Corporation Renton Municipal Airport Renton, WA 98055
401, 401A, 402, 402A, 402B, 414; T.C. A7CE	SA109RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA117NW	Installation of Allison 250-B17 or 250-B17B engines and related changes. Reissued 1/6/77.	WE	25640	Commuter Investment and Development Corporation 2800 Clybourn Avenue Van Nuys, CA 91406
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA167GL	Install Cleveland conversion kit P/N 199-72. Issued 4/15/77.	GL	23260	Cleveland Wheels and Brakes Van Sickle Industries, Inc. 1160 Center Road Avon, OH 44011
401, 401A, 402, 402A, B, 414; T.C. A7CE	SA194RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
401, 402, 411, 411A, 401A, 401B; T.C. A7CE	SA346EA	Installation of Chamberlain radome kit No. 2022X-B for Bendix RDR-100 or RDR-110 series radar system. Amended 7/30/71.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A; T.C. A7CE	SA437EA	Installation of radome P/N 2022X. Amended 5/27/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A, 414, 421, 421A; T.C. A7CE	SA438EA	Installation of Norton radome kit No. 2022X-3. Amended 11/2/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
401A, 401B, 402A, B, 414, 421, 421A, 421B; T.C. A7CE	SA465SO	Installation of Bendix FCS-810 automatic flight control system including flight director indicator DH-841( ) and manual electric trim. Amended 6/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA618SO	Installation of M-4B or M-4C automatic flight control systems. Amended 4/27/73.	SO	15475	The Bendix Corporation Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA646CE	Install wing and tail pneumatic deice kit 702A on 401/402 aircraft (S/N 0135 and above), kit 702B on 414 aircraft and kit 702C on 401/402 aircraft (S/N 0001 through 0134 only). Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
401, 401A, 401B, 402, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C; T.C. A7CE	SA1146SO	Installation of nose cone erosion cap. Issued 5/29/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri-City Airport Blountsville, TN 37617
401, 401A, B; T.C. A6CE	SA1158SW	Mitchell automatic flight system FD/AP282-302 consisting of flight director/automatic pilot and automatic pitch trim. Issued 6/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, 401B, 402, 402A; T.C. A7CE	SA1206SW	Edo-Aire Mitchell automatic flight system AK302, consisting of Century III autopilot with optional pitch trim, radio, and glide slope couplers. Issued 10/23/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, B, C; T.C. A7CE	SA1326CE	Installation of Avcon Industries TSO C39a stretcher. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
401, 401A, 402, 402A, 411, 411A, 414; T.C. A7CE	SA1358CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 601 Southwest Boulevard Kansas City, KS 66103
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 414A, 421, 421A, 421B, 421C; T.C. A7CE	SA1393CE	Install forward baggage door warning system. Issued 1/3/78.	CE	84955	Wells Aircraft, Inc. Municipal Airport Hutchinson, KS 67501
401, 401A all S/N's, 402, 402A, 402B thru S/N 0300, 411, 411A all S/N's, 414 thru S/N 0350, 421, 421A, 421B thru 0300; T.C. A7CE	SA2091WE	Installation of air conditioning system. Amended 5/21/79.	RM	45758	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
401, 401A, B, 402, 402A, B; T.C. A7CE	SA2845SW	Symbolic Displays CPS-2000 electronic fuel flow metering system. Issued 9/8/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
401*, 401A*, 401B*, 402*, 402A*, 402B*, 402C, 411, 411A, 414*, 414A, 421, 421A, 421B, 421C; *Includes those models modified per STC SA117NW.	SA3003WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 421, 421A, 421B; T.C. A7CE	SA3017WE	Installation of fuel flow instruments.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
401, A, B, 402, 402A; T.C. A7CE	SA3057SW-D	Mitchell automatic flight system AK530 or AK435FD consisting of Century IV autopilot or Century IV flight director autopilot with command/autopilot electric pitch trim and annuciator. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, B, 402; T.C. A7CE	SA3058SW-D	Mitchell flight system YK535 consisting of yaw damper system. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA3838WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
401, 401A, 401B, 402, 402A, 402B, 414 thru S/N 414-0350;	SA3930WE	Installation of 37.5 gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 448, Seamans Airport Factoryville, PA 18419
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA4117WE	Installation of Silver Instruments fueltron 111G or fueltron 111P digital fuel flow and totalizer system. Issued 3/13/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
T.C. A7CE					
401, 402; T.C. A7CE	SA784SW	Mitchell Model AK240 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 402; T.C. A6CE	SA1472WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402; T.C. A6CE	SA1599WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402, 411; T.C. A7CE	SA472EA	SAGA (Semi-automatic gear actuating) system. Amended 5/23/67.	GL	43750	In-Flight Devices Corporation 4805 Sawyer Road International Airport Columbus, OH 43219
401A; T.C. A7CE	SA3192WE	Installation of single global and dual global GNS-500A navigation system. Amended 3/23/79.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
402; T.C. A7CE	SA634CE	Install tenth seat and attach FAA approved AFMS.	CE	36080	FloAir, Inc. Hangar #17, Municipal Airport Wichita, KS 67209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
402; T.C. A7CE	SA1742SW	Vapor cycle air conditioning system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
402; T.C. A7CE	SA1863SW	Two cameras and navigation sight. Issued 5/7/74.	SW	42825	A.D. Howard, Jr. 6817 N.W. 43rd Street Bethany, OK 73008
402; T.C. A7CE	SA2424WE	Installation of Allison 250-B17 engines and related changes. Amended 9/21/73.	WE	10208	American Jet Industries 3021 Airport Avenue Santa Monica, CA 90405
402, 402A; T.C. A7CE	SA2333SW	Fiberglass tailcone for magnetometer. Issued 7/23/76.	SW	42825	A.D. Howard, Jr. 1911 Moulton Court Oklahoma City, OK 73127
402A, B, C, 421B, C, 414A; T.C. A7CE	SA807EA	Installation of Norton Radome Kit No. 4009X. Reissued 5/6/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
402B; T.C. A7CE	SA700CE	Install right-hand side rear window.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
402B; T.C. A7CE	SA1061CE	Installation of Collins Company AP-107 (3 axis) autopilot system. Issued January 1975.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1110CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1111CE-D	Installation of AP-107 autopilot (2 axis). Amended June 1976.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1501CE	Sierra utility flight inspection equipment rack installed in left hand side forward location. Issued 7/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
402B, 402C; T.C. A7CE	SA1303CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
402B (S/Ns 402B0301 and up), 414 (S/Ns 414-0351 and up), 414A (S/Ns 414A0001 and up), 421B (S/Ns 421B0001 and up); 421C (S/Ns 421C001 and up) (6, 7, 8, 9 or 10 place); T.C. A7CE	SA8RM	Installation of Freon type air-conditioning system. Amended 1/12/78.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
402B, 414, 421B; T.C. A7CE	SA547SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim and optional flight director system in serial numbers 402B0301 and up, 4140351 and up, and 421B0301 and up. Issued 8/17/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
402B, 414, 421B; T.C. A7CE	SA584SO	Installation of Bendix YD-4 yaw damper system. Issued 4/5/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
402C; T.C. A7CE	SA300CE	Installation of Woodward Governor propellers on single and twin engine airplanes for P/N B210659. Issued 5/22/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
402C; T.C. A7CE	SA1502CE	Install King KFC200 automatic flight control system, with or without flight director. Amended 6/24/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
402C, 414A, 421C; T.C. A7CE	SA1526CE-D	Installation of King KAS 297 altitude selector option. Issued 2/6/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404, S/N 404-0001 and up; T.C. A25CE	SA143RM	Installation of air conditioner system. Issued 6/2/78.	RM	45750	J B Systems, Inc. P.O. Box 800 Longmont, CO 80501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
404; T.C. A25CE	SA195GL	Installation of Norton radome kit 4009X.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
404; T.C. A25CE	SA195RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
404; T.C. A25CE	SA721NW	Installation of camera bays. Issued 2/23/79.	NW	85165	Western Skyways Portland-Troutdale Airport Troutdale, OR 97060
404; T.C. A25CE	SA1297CE	Installation of King KFC 200 2-axis flight control system. Amended 5/27/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA1482CE	Installation of Tull microwave landing system. Issued 4/9/79.	CE	81650	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
404; T.C. A25CE	SA1304CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
404; T.C. A25CE	SA1600CE	Installation of TSO'd stretcher. Issued 7/17/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
404; T.C. A25CE	SA1528CE-D	Installation of King KAS 297 altitude selector option. Issued 2/18/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA3384WE	Removal of cargo doors and installation of P/N A770000 airstream deflector. Issued 6/8/77.	WE	07630	Airflite, Inc., South 2700 East Wardlow Road Long Beach, CA 90801
404; T.C. A25CE	SA3388WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
404; T.C. A25CE	SA4017WE	Installation of SDI model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 8/31/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
404; T.C. A25CE	SA4105WE	Installation of tail stinger and/or nose stinger. Issued 2/21/80.	WE	77500	Tallmantz Aviation, Inc. 19711 South Airport Way Santa Ana, CA 92707
404; T.C. A25CE	SA4163WE	Installation of doppler radar antenna. Issued 5/21/80.	WE	77500	Tallmantz Aviation, Inc. 19711 Airport Way South Santa Ana, CA 92707
411 Series; T.C. A7CE	SA402CE	50-gallon auxiliary fuel tank.	CE	36000	Floair, Inc. Municipal Airport Newton, KS 67114
411 Series; T.C. A7CE	SA515SW	Automatic pilot AK158, lateral guidance radio coupler AK123 and automatic trim system AK159.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA681SW	AK221 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA839EA	Installation of Radome Kit P/N 4009K-B for Bendix RDR-100 and RDR-110 systems - 12" antenna. Amended 11/29/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
411 Series; T.C. A7CE	SA1227WE	Installation of Brittain Model B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
411 Series; T.C. A7CE	SA1467WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
411 Series; T.C. A7CE	SA2378WE	Installation of Global Navigation Model GNS-200 VLF navigation system. Amended 2/26/74.	WE	38090	Global Navigation, Inc. 2733 Pacific Coast Highway Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
411 Series; T.C. A7CE	SA2913WE	Installation of GNS-500 VLF navigation system. Amended 2/28/75.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
411 Series; T.C. A7CE	SA3138WE	Installation of GNS-500A VLF/OMAGE navigation system. Amended 1/17/77.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
411, 411A Series; T.C. A7CE	SA1120WE	Bendix automatic flight control system type M4B and M4C.	SO	15475	The Bendix Corporation Avionics Products Fort Lauderdale, FL 33310
400, 411A, 421, 421A; T.C. A7CE	SA102RM	Installation of exhaust turbo connector, P/N 042177-5. Issued 5/19/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street Denver, CO 80207
411, 411A, 421, 421A, 421B; T.C. A7CE	SA108RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless, sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
411, 421; T.C. A7CE	SA487CE	Install windshield wipers.	GL	27500	Marquette Metal Products Company Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
411A; T.C. A7CE	SA4167WE	Removal of main cabin door. Issued 5/29/80.	WE	18264	Richard Bungay/Richard Fowler 1345-D Silica Avenue Sacramento, CA 95815
414; T.C. A7CE	SA48NW	Installation of fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servc rudder trim tab. Issued 6/29/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
414; T.C. A7CE	SA433SO	Installation of Bendix Model M4C flight control system. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
414; T.C. A7CE	SA1040CE	Installation of AP-107 autopilot. Amended 10/2/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
414; T.C. A7CE	SA1219SW	Mitchell automatic flight system AK308 consisting of Century III with automatic pitch trim, radio, and glide slope couplers. Issued 11/18/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA1899SW	Freon air conditioning system. Issued 9/9/74.	SW	37154	Gen-Aero, Inc. P.O. Box 16278 San Antonio, TX 78246
414; T.C. A7CE	SA1220SW	Mitchell automatic flight system Model FD/AP282-308 consisting of flight director/autopilot, auto-pilot pitch trim. Issued 11/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA2354SW	Teledyne Continental TSIO-520-N, -J, engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
414; T.C. A7CE	SA2P12SW	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
414; T.C. A7CE	SA3334SW-D	Mitchell automatic flight system AK624 consisting of Century IV autopilot or AK624FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3335SW-D	Mitchell yaw damper system, YK628. Issued 3/6/69.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3366SW-D	Mitchell yaw damper system YK867. Issued 5/28/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
414; T.C. A7CE	SA3666WE	Installation of Silver Instruments Fueltron IIIG digital fuel flow and totalizer system. Issued 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
414; T.C. A7CE	SA3682WE	Installation of Continental TSIO-520-N engine and associated installation components. Issued 7/12/78.	WE	68120	Riley Aircraft Corporation 2386 Palomar Airport Road Carlsbad, CA 92008
414A T.C. A7CE	SA985SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director and optional yaw damper. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
414A; T.C. A7CE	SA986SO	Installation of Bendix NP-2041A NP-2041A area navigation computer programmer. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
414A; T.C. A7CE	SA1400CE	Install Enk Aviation fire suppression system. Issued 2/9/78.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
414A; T.C. A7CE	SA1431CE	Install King KFC-200 flight control system with or without flight director. Amended 6/9/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
414A; T.C. A7CE	SA1521CE-D	Installation of King KFC 250 flight control system. Amended 7/25/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
414A; T.C. A7CE	SA3304SW-D	Mitchell automatic flight system AK774/FD consisting of Century IV/ flight director autopilot with optional remote annunciator.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414, 421; T.C. A7CE	SA536CE	Install electrical connectors in pressure bulkhead(s) at Station(s) 100 and/or 273.94. Amended 12/4/70.	RM	05940	Charles O. Peacock Aircraft Radio & Accessory Co., Inc. Hangar #4, Stapleton Field Denver, CO 80207
414, 421A; T.C. A7CE	SA732EA	Installation of radome Part No. 4004X. Amended 5/12/75.	GL	61750	Norton Company Plastics & Synethetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
414, 421A; T.C. A7CE	SA780EA	Installation of Radome Kit No. 4004K-B for Bendix RDR-100 or RDR-110 series radar systems - 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
414, 421, 421A, B, C; T.C. A7CE	SA2440SW	Airstair door saver. Issued 3/23/77.	SW	00060	AAR of Oklahoma, Inc. P.O. Box 19508 Oklahoma City, OK 73119
421 Series; T.C. A7CE	SA574CE	Installation of toilet seat belt.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
421 Series; T.C. A7CE	SA591EA	Installation of Radome Part Part No. 3084X. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
421 Series; T.C. A7CE	SA661EA	Installation of Radome Kit No. 3084K for Bendix RDR-100 or RDR-110 series radar systems 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
421 Series; T.C. A7CE	SA662CE	Installation of Jet Electronics & Technology, Inc. Model FC120A autopilot.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street Grand Rapids, MI 49508
421 Series; T.C. A7CE	SA673CE	Install Hartzell HC-B3WF-2/9349-3 propellers.	GL	41000	Hartzell Propellers, Inc. 350 Washington Avenue P.O. Box 909 Piqua, OH
421 Series; T.C. A7CE	SA968SW	Mitchell automatic flight system AK279 consisting of Century II autopilot with optional automatic pitch trim, radio, and glide slope couplers, automatic aileron stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
421 Series; T.C. A7CE	SA978SW	Collins FD108 flight director system.	SW	06000	Aircraftsmen, Inc. Box 82516 Oklahoma City, OK 73108
421 Series; T.C. A7CE	SA1776WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
421, 421A; T.C. A7CE	SA794CE	Install vapor cycle air conditioning system. Reissued 10/15/71.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
421, 421A; T.C. A7CE	SA1897WE	Installation of a seventh seat in aft baggage compartment.	RM	25250	Combs Aircraft, Inc. Stapleton International Airport Denver, CO 80207
421, 421A, 421B; T.C. A7CE	SA2RM	Installation of a seventh seat in aft baggage compartment. Reissued 4/6/73.	RM	25250	Combs - Gates Denver, Inc. Stapleton International Airport Denver, CO 80207
421, 421A, 421B; T.C. A7CE	SA18NW	Installation of Fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 4/13/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
421, 421A, 421B; T.C. A7CE	SA632SO	Installation of Bendix Model M-4C automatic flight control system, including manual electric trim. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33309
421, 421A, 421B; T.C. A7CE	SA1200CE	Installation of FiQuench cabin and/or engine fire extinguishant system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
421, 421A, 421B; T.C. A7CE	SA1210CE	Installation of Hanlon & Wilson exhaust systems, P/N 8108-59 and P/N 8109-59 or P/N 8108-159 and 8109-159. Amended 3/19/80.	EA	40350	Hanlon & Wilson Company P.O. Box 641 Jeanette, PA 15644
421, 421A, 421B, 421C; T.C. A7CE	SA1343CE	Install Sierra data console on left hand seat rails. Reissued 9/15/77.	EA	71660	Sierra-Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, 421B, 421C; T.C. A7CE	SA1375CE	Reduce height of existing survival seat. Reissued 10/3/77.	EA	71660	Sierra Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, B, C; T.C. A7CE	SA3228WE	Installation of Silver Instruments Fueltron IIIG or IIIP fuel indicating system. Amended 1/11/80.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545
421B; T.C. A7CE	SA135GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 10/26/76.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
421B; T.C. A7CE	SA952CE	Installation of King Radio Model KFC-300 automatic flight control system. Amended 12/19/75.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA986CE	Installation of Collins Radio Group AP-106 autopilot system. Amended January 1977.	CE	24250	Collins Radio Group Avionics Certification Center Cedar Rapids, IA 52406
421B; T.C. A7CE	SA987CE	Installation of Sperry SPZ-200/ STARS IVC automatic flight control system with optional Sperry AA-220/ RT-220 radar altimeter. Issued February 1974.	CE	90080	Yingling Aircraft, Inc. P.O. Box 1162 Wichita, KS 67201
421B; T.C. A7CE	SA1001CE	Installation of H-14 autopilot. Issued April 1974.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA1035CE	Installation of openable window aft of cabin door. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
421B; T.C. A7CE	SA1167CE	Installation of AP 107 autopilot (2 axis). Serials 301 and subsequent. Issued 3/29/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1667SW	Mitchell automatic flight system Model YK385 consisting of yaw damper. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
421B; T.C. A7CE	SA1168CE	Installation of Collins Radio Group AP-107, 3 axis, autopilot system and interface with Collins 329A-4V indicator. Serials 301 and subsequent. Issued 10/20/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1668SW	Mitchell automatic flight system AK407, consisting of Century IV autopilot with trim; or AK407/FD consisting of Century IV autopilot/ flight director with trim. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421B; T.C. A7CE	SA2749WE	Installation of Lear AFC-70 AP/FD steering computer system. Issued 8/23/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Reno, NV 89510
421B; T.C. A7CE	SA2810WE	Installation of Collins AP-105 autopilot and FD-108 flight director systems. Issued 1/30/74.	WE	78622	Tower Avionics Center Hangar 8, Oakland Int'l Airport Oakland, CA 94614
421B; T.C. A7CE	SA3881WE	Installation of dual elevator trim tab actuator. Issued 3/14/79.	WE	68120	Riley Aircraft Corporation 2386 Palomar Airport Road Carlsbad, CA 92008
421C; T.C. A7CE	SA196RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welidng Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
421C; T.C. A7CE	SA438NW	Replace original split flaps with Fowler flaps. Issued 4/22/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
421C; T.C. A7CE	SA886SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 2/26/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA890SO	Installation of Bendix FCS-810 automatic flight control system including manual electric pitch and optional flight director indicator. Amended 11/1/76.	SC	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA1120CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1121CE	Installation of Collins Radio Group AP-107 (2 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1122CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1191EA	Installation of Hanlon & Wilson exhaust system P/N 8294-1(L.H) and 8294-2(R.H.) Issued 4/2/80.	EA	40350	Hanlon & Wilson Company P.O. Box 641 Jeanette, PA 15644
421C; T.C. A7CE	SA1246CE	Install King KFC-200 2 axis (3 optional) flight control system with a KI-255 flight command indicator. Amended 6/2/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
421C; T.C. A7CE	SA1305CE	Installation of fire suppression system. Amended 6/24/80.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64105
421C; T.C. A7CE	SA3110SW-D	Mitchell automatic flight system AK579, consisting of Century IV autopilot or AK579FD, consisting of Century IV flight director autopilot with remote annuciator. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3111SW-D	Mitchell yaw damper YK580. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3458WE	Modification of fuselage to install camera window. Issued 7/14/77.	WE	84000	Volpar, Inc. 7929 Hayvenhurst Avenue Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
441; T.C. A28CE	SA400GL	Installation of Litton LTN-211 Omega/VLF navigation system. Issued 6/12/80.	GI	37182	General Aviation, Inc. Capital City Airport Lansing, MI 48906
441: T.C. A28CE	SA1424CE	Install Sierra Electronics consle. Reissued 7/3/78.	EA	71660	Sierra Research Corp. P.O. Box 222 Buffalo, NY 14225
441; T.C. A28CE	SA1599CE	Installation of TSO'd stretcher. Issued 7/17/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
441; T.C. A28CE	SA2818SW	Install three place side facing couch. Issued 7/19/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
441; T.C. A28CE	SA3498WE	Installation of tail flood light on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
500 Series; T.C. A22CE	SA8GL	Installation of engine synchronizer kit P/N 213522. Issued 4/18/73.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
500 Series; T.C. A22CE	SA13RM	Installation of Branson cargo liner and retention system. Issued 7/23/73.	RM	09752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207
500 Series; T.C. A22CE	SA15RM	Installation of three-place couch with or without quick change aft divider. Amended 4/2/76.	RM	09752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207
500 Series; T.C. A22CE	SA18RM	Install beverage service buffet in baggage compartment. Issued 11/21/73.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA19RM	Install two lounge seats in rear of baggage compartment. Amended 11/8/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA23RM	Installation of aft beverage cabinet, P/N 90241-1. Amended 5/20/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA47RM	Installation of single seat in the center of aft baggage compartment. Reissued 3/10/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
500 Series; T.C. A22CE	SA51RM	Installation of tail cone ski rack. Reissued 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series; T.C. A22CE	SA52RM	Installation of stretcher. Amended 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series; T.C. A22CE	SA54RM	Installation of tail cone storage box and engine cover storage box. Amended 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA58RM	Installation of deluxe three-place aft couch. Amended 10/7/77.	RM	17085	Branson Engineering Company, Inc. 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA79RM	Installation of side-looking camera hatch. Reissued 7/29/77.	CE	20625	Cessna Aircraft Company Wichita Municipal Airport P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA83RM	Increased ramp and takeoff weights for restricted category operation. Issued 10/22/76.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA97RM	Installation of dual aft lounge seats. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA100RM	Installation of lounge seat toilet. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	ST131RM	Installation of Global Navigation, Inc. GNS-500A VLF/Omega navigation system. Issued 2/7/78.	RM	14127	Avionics Engineering of Denver, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
500; T.C. A22CE	ST174RM	Installation of extended width cabin door. Issued 5/4/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500; T.C. A22CE	SA645NW	Increased fuel and performance modifications. Issued 8/4/78.	NW	12270	Astec Engineering, Inc. 830 N. Riverside Drive Renton, WA 98055
500; T.C. A22CE	SA802NW	Installation of transponder identification switch on left hand control wheel. Issued 7/13/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
500 Series; T.C. A22CE	SA897SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement battery. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
500 (S/N 500-001 thru -0213); T.C. A22CE	SA991CE	Installation of KFC-300 automatic flight control system. Amended 4/10/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
500 Series; T.C. A22CE	SA1013CE	Installation of retractable aircraft recognition lights. Amended 7/26/78.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 Series; T.C. A22CE	SA1059EA	Installation of an airways calibration system. Reissued 9/27/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 (S/N 350 and on); T.C. A22CE	SA1371CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 Series; T.C. A22CE	SA1574SW	Installation of hassock according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500; T.C. A22CE	SA1579CE	Installation of tail-cone baggage compartment. Issued 3/7/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
500 Series; T.C. A22CE	SA1589SW	Installation of Singer Kearfott SKK-1000A doppler system; Collins INS-61B inertial navigation system; JET PS 823B emergency power system. Reissued 11/20/73.	CE	20225	Cessna Aircraft Company P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA1597SW	Stretcher installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 N. Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1619SW	Installation of emergency power supply according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1727SW	Jump seat. Issued 9/13/73.	SW	12250	Associated Radio Service Company Box 20718 Dallas, TX 75220
500 Series; T.C. A22CE	SA1945SW	Aft equipment bay storage unit. Issued 1/7/75.	SW	38242	William L. Goin, Jr. 7930 Airport Boulevard Houston, TX 77017
500 Series; T.C. A22CE	SA2383SW	Install refreshment bar and galley bulkhead. Issued 11/19/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
500 Series; T.C. A22CE	SA2925WE	Installation of power brake and skid control system. Issued 9/24/74.	WE	13230	Aviation Brake Systems, Ltd. 3535 West 5th Street Oxnard, CA 93030
500, 501; T.C. A22CE	SA2698SW	Freon air conditioning system. Issued 12/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
500, 501; T.C. A22CE, A27CE	SA2883SW	Installation of Ray Electronics Model 7507A battery current monitoring system. Issued 12/7/78.	SW	66500	Ray Electronics Company 11933 Warfield Drive San Antonio, TX 78216
500, 501; T.C. A22CE, A27CE	SA4034SW	Zee systems air conditioner. Issued 8/30/79.	SW	28775	Darling Aviation, Inc. P.O. Box 79230 Fort Worth, TX 76179
500, 501, 550, 551; T.C. A22CE, A27CE	SA1051SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid battery. Issued 3/29/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500, 501, 550, 551; T.C. A27CE, A22CE	SA2916SW	Installation of alternate gear horn switch. Issued 2/26/79.	SW	47720	Keith Products, Inc. 625 Opar Richardson, TX 75080
500, 501, 550, 551; T.C. A27CE, A22CE	SA4054SW	Installation of one, two, or three-place side facing seat, frame only. Issued 10/23/79.	SW	28000	Custom Aircraft Conversions 234 West Turbo Drive San Antonio, TX 78216
500, 550; T.C. A22CE	SA80RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Amended 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST151RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST166RM	Installation of three-place or single-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST174RM	Installation of extended width cabin door. Amended 5/18/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	SA1457CE	Install microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
500, 550; T.C. A22CE	SA1513CE	Installation of Avcon 4001-213 and -214 stretcher. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
500, 550; T.C. A22CE	SA1534CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
500, 550; T.C. A22CE	SA2906WE	Installation of vertical tail floodlights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
500, 550; T.C. A22CE	SA3000SW	Fabrication and installation of 3-place side facing couch and shoulder harness. Issued 5/25/79.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
501; T.C. A27CE	ST117RM	Installation of deluxe three-place aft couch. Issued 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	ST118RM	Installation of tail cone storage box and engine cover storage box. Issued 10/22/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	SA125RM	Installation of tail cone ski rack. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA126RM	Installation of stretcher. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA152RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Issued 9/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA177RM	Installation of a single seat in the center of aft baggage compartment. Issued 6/25/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA732NW	Installation of "Eagle" performance kit. Issued 5/10/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
501; T.C. A27CE	SA1372CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
501; T.C. A27CE	SA1423CE	Insalll King KFC-300 AFCS with duel flight director and transferable autopilot. Issued 6/21/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
501; T.C. A27CE	SA1580CE	Installation of tail-cone baggage compartment. Issued 3/7/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
501, 551; T.C. A27CE	SA150RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA171RM	Installation of three-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA1514CE	Installation of Avcon 4001-213 and -214 stretchers. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA1535CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA3409WE	Installation of vertical tail floodlights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
550; T.C. A22CE	ST165RM	Installation of fiberglass tail cone in lieu of metal tail cone. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
550; T.C. A22CE	SA1499CE	Installation of Total Flood (TFC) Halon 1301 fuselage flood system. Issued 7/11/79.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
551; T.C. A27CE	SA1500CE	Installation of Total Flood (TFC) Halon 1301 fuselage flood system. Issued 7/11/79.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
CH-1C; T.C. 3H10	SH4WE	Fifth passenger seat and seat belt.	NW	84625	Washington Aircraft & Transport Co. Boeing Field Seattle, WA 98101
Miscellaneous	SA582NW	Replacement wire rope cable assemblies. Issued 5/12/78.	NW	81180	University Swedging 800 N.W. 46th Street Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DHC-2, MK1; T.C. A-806	SA456NW	Installation of auxiliary seaplane stabilizer fins. Issued 6/2/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK 1; T.C. A-806	SA527AL	Removal of left rear door for parachute jumping. Issued 8/9/74.	AL	19906	A. Dean Carrell 7100 Lake Otis Parkway Anchorage, AK 99507
Beaver DHC-2, MK 1; T.C. 806	SA1913WE	Installation of EDO Model 679-4930 floats. Amended and reissued 8/27/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
DHC-2, MK 1; T.C. A-806	SA2520WE	Hatch installation in Bristol amphibious floats. Issued 4/28/72.	NW	61626	North Country, Inc. 2525 14th Avenue South Seattle, WA 98168
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14(14V) or -28(28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA800EA	Installation of Aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W (red/white), or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
Otter DHC-3; T.C. 815	SA4-183	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
Otter DHC-3; T.C. 815	SA135NW	Installation of Sorm Industries bulk cargo tank. Issued 11/15/74.	NW	73820	Sorm Industries 7999 Perimeter Road Seattle, WA 98108
Otter DHC-3; T.C. 815	SA336NW	Installation of Hamilton Standard 23D40-311/6601A-7 propeller. Issued 8/18/76.	NW	40517	Harold J. Hansen 20602 - 135th Avenue South Seattle, WA 98148
DHC-3; T.C. A-815	SA678NW	Installation of Edo Model 56-7850A floats. Issued 10/17/78.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-6; T.C. A9EA	SA106NW	Installation of emergency exit on each side of fuselage. Amended 5/17/74.	EA	71910	S K Aircraft Company 16 Shotgun Lane Levittown, NY 11756
DHC-6; T.C. A9EA	SA235NW	Modification of cabin compartment airstair door. Issued 11/5/75.	NW	08360	Air Transport Industry Jet Air Hangar, Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA570NW	Installation of new interior interior panel. Issued 2/28/78.	NW	08360	Air Transport Industries Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA841EA	Installation of radome and support bracketry for RCA AVQ-45 antenna and radar units. Issued 9/10/70.	EA	35300	Field Aviation Company Limited Toronto International Airport Malton, Ontario, Canada
DHC-6 T.C. A9EA	SA1837WE	Installation of freon air conditioning system. Amended 8/25/77.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
DHC-6; T.C. A9EA	SA2366WE	Installation of emblem lights at mid span of horizontal stabilizer. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DHC-6; T.C. A9EA	SA3816WE	Installation of underseat baggage restraint bar. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DHC-6-100, -200, -300; T.C. A9EA	SA207GL	Install airborne fuel booster pump Model 1D2-14. Issued 1/10/78.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
DHC-6-100, -200, -300; T.C. A9EA	SA357AL	Installation of bulk fluid cargo tanks. Amended 5/15/72.	NW	78820	Sorm Industries 7999 Perimeter Road South Seattle, WA 98108
DHC-6-100, -200, -300; T.C. A9EA	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DHC-6 Series 100, 200; 300; T.C. A9EA	SA943EA	Replacement of deHavilland wing bleed air ducting with alternate ducting. Reissued 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
DHC-6-100, -200, -300; T.C. A9EA	SA998EA	Installation of engine fuel drain recirculation system. Reissued 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
DHC-6 Series 100, 200; 300; T.C. A9EA	SA2516WE	Installation of lightning arrestors on wing tips and vertical fin. Issued 9/19/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6-100, -200, -300; T.C. A9EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
DHC-6 Series 100, 200, 300; T.C. A9EA	SA2608WE	Installation of equivalent modifications to deHavilland modifications. Issued 11/3/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2553WE	Installation of Adel cannister fuel pumps. Reissued 8/24/72.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2898WE	Installation of a fuel tank boost pump. Issued 6/14/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, S/N 130, 210, 231 and subsequent; T.C. A9EA	SA1117CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
DHC-6-200; T.C. A9EA	SA771EA	Installation of Dual Mark 15 Decca Systems.	EA	61542	New York Airways, Inc. P.O. Box 426 LaGuardia Airport Station Flushing, NY 11371
DHC-6-200; T.C. A9EA	SA3103WE	Removal of left-hand cargo doors to permit aircraft to engage in special operations, i.e. parachute jumping, aerial photography, etc. Issued 10/24/75.	WE	38250	Golden West Airlines, Inc. 5801 W. Imperial Highway Los Angeles, CA 90045
DHC-6-300; T.C. A9EA	SA130RM	Installation of dual-SELCAL system. Issued 1/28/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA132RM	Change in Airplane Flight Manual operating limitations to permit landings with air-operable jump-door open. Issued 2/15/78.	RM	07701	Department of the Air Force Hq., Aerospace Defense Command Peterson AFB, CO 80914
DHC-6-300; T.C. A9EA	SA135RM	Installation of Leach P/N V110-C-032-AC overvoltage relays. Issued 3/3/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA170NW	Installation of bulk fluid cargo tank for carriage on non-flamable, non-corrosive, non-toxic liquids. Issued 4/3/75.	WE	73820	Sorm Industries 7999 Perimeter Road Seattle, WA 98108
DHC-6-300; T.C. A9EA	SA185RM	Installation of Bendix RDR-160 weather radar system. Issued 10/26/79.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-7-100; T.C. A20EA	ST127RM	Supplemental oxygen system installation. Issued 2/2/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
DHC-7-100; T.C. A20EA	ST128RM	Installation of ground proximity warning system, Collins FPC-75. Issued 1/23/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
D.H. 104 Dove Series; T.C. 807	SA1-72	Three-place seat.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
D.H. 104 Dove Series; T.C. 807	SA1-73	39-gallon auxiliary fuel tank in cabin with 3-place seat per STC SA1-72.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
D.H. 104 Dove Series; T.C. 807	SA1-321	Airstair door.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

EAGLE BALLOONS, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Challenger; T.C. A13SO	SI329GL	Installation of Rego quick acting spring loaded valve, P/N 7553S, in lieu of Rego valve, P/N 2553, using original installation hardware and components. Issued 7/18/79.	GL	35360	Finn-Bilt, Ltd. 11602 Brier Hill Road Huntley, IL 60142
Challenger; T.C. A13SO	SI410GL	Installation of Balloon Works burner model T3-017. Issued 5/23/80.	GL	48825	Robert A. Isles 3750 Collins Rochester, MI 48063

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F-27 Series; T.C. 7A1	SA3-685	Burns 2DH1EM-2 swivel chair track.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA3-687	SP-20 amplifier.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA4-947	Floor structure for installation of seats and divans.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA4-1027	Aircraft interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA4-1209	Cabin air-conditioning modification and addition of inflight cabin air recirculation.	NW	85122	West Coast Airlines, Inc. Georgetown Station Seattle, WA 98108
F-27 Series; T.C. 7A1	SA4-1453	Cabin air-conditioning system modification.	WE	16892	Bonanza Air Lines P.O. Box 391 Las Vegas, NV 89114
F-27 Series; T.C. 7A1	SA4-1543	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA435SW	Collins 137Y-1 doppler antenna and 621C-1 transmitter-receiver.	SW	12250	Associated Radio Service Company 7515 Lemmon Dallas, TX 75220
F-27 Series; T.C. 7A1	SA54SW	Interior installation. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA56SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA119SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA120SW	Autopilot AP-101E with flight director computer 562A-6 or 562A-4A.	CE	24250	Collins Radio Company 855 35 Street, NE Cedar Rapids, IA 52401
F-27 Series; T.C. 7A1	SA142EA	Rewire nose gear steering system.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27 Series; T.C. 7A1	SA153WE	Nacelle tail cone of 2024T3 material.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
F-27 Series; T.C. 7A1	SA190SW	Automatic pilot AP-103.	CE	24250	Collins Radio Company 855 35 Street, NE Cedar Rapids, IA 52401
F-27 Series; T.C. 7A1	SA225CE	Independent military pneumatic system and compressor.	CE	62030	Ozark Air Lines, Inc. Box 6007, Lambert Field St. Louis, MO 63145
F-27 Series; T.C. 7A1	SA245SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA282SO	Replacement parts manufactured for Fairchild P/Ns 27-727930-3 and -7.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27 Series; T.C. 7A1	SA288CE	Aural speed warning system.	CE	62030	Ozark Air Lines, Inc. Box 6007, Lambert Field St. Louis, MO 63145
F-27 Series; T.C. 7A1	SA306SW	Aft cabin window. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA323SO	Solid state voltage regulator.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F-27 Series; T.C. 7A1	SA330SO	New cockpit door with electric lock device.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27 Series; T.C. 7A1	SA342SC	Cockpit voice recorder.	SC	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27 Series; T.C. 7A1	SA441EA	Automatic flight control and flight director system.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
F-27 Series; T.C. 7A1	SA446WE	GPT30-54 turbine APU.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA468CE	United Data Control V-557 cockpit voice recorder.	CE	62030	Ozark Airlines, Inc. Box 6007, Lambert Field St. Louis, MO 63145
F-27 Series; T.C. 7A1	SA487SW	Rotating beacon. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA591SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA619WE	18-passenger interior and equipment, including an oxygen system, inverter, and antennas.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA631SW	Fairchild A-100 voice recorder system.	WE	62070	Pacific Air Lines San Francisco Int'l Airport San Francisco, CA 94119
F-27 Series; T.C. 7A1	SA632SW	United Data F-542 recorder.	SW	63750	Qualitron Aero, Inc. 4401 N. Main Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA729WE	High Density interior arrangement.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 391 McCarran Field Las Vegas, NV 89114
F-27 Series; T.C. 7A1	SA750WE	Overspeed warning system.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 391 McCarran Field Las Vegas, NV 89114
F-27 Series; T.C. 7A1	SA790WE	Replacement of carbon pile voltage regulator for 30-volt DC generator with Ieland Airborne Products Type CSV-1105-1 solid state voltage regulator.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
F-27 Series; T.C. 7A1	SA853WE	Bendix 4B39 solid state voltage and frequency control modification to Jack & Heintz F-35-5 rotary inverter.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
F-27 Series; T.C. 7A1	SA968WE	Two windows in aft fuselage.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA969WE	Two radar altimeter antennas. (This is a structural installation only and does not include the operational evaluation of the antennas or system.)	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA970WE	Doppler antenna. (This is a structural installation only and does not include the operational evaluation of the antenna or system.)	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
F-27 Series; T.C. 7A1	SA985WE	Wing flap actuated landing gear aural warning system.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 391 McCarren Field Las Vegas, NV 89114
F-27 Series; T.C. 7A1	SA1133WE	Flight data recorder 5424.	WE	34213	Fairchild Camera and Instrument Corporation 5921 E. Sheila Street Los Angeles, CA 90022

Aircraft Make, Model & T.C. No.	STC No.	Description	PG	STC Code	STC Holder
F-27 Series; T.C. 7A1	SA1188WE	Collins Radio Company cockpit voice recorder system.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 12405 Phoenix, AZ 85034
F-27 Series; T.C. 7A1	SA1225WE	Emergency lighting system.	WE	16892	Bonanza Air Lines, Inc. P.O. Box 12405 Phoenix, AZ 85034
F-27 Series; T.C. 7A1	SA1314WE	Installation of either United Control Data Division #V-557 or Fairchild #A-100 cockpit voice recorder system.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
F-27 Series; T.C. 7A1	SA1333WE	Northern Aero Industries, Ltd. cyclic deicing switch.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
F-27 Series; T.C. 7A1	SA1406WE	Relocation of Fairchild flight data recorder.	WE	16892	Bonanza Air Lines, Inc. 3737 E. Bonanza Way P.O. Box 12405 Phoenix, AZ 85034
F-27 Series; T.C. 7A1	SA1496WE	Installation of fire detection aural warning system.	WE	62070	Pacific Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94119
F-27 Series; T.C. 7A1	SA1537SW	Installation of a galley. Issued 11/10/72.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1538SW	Installation of a bar. Issued 11/10/72.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1539SW	Bulkhead and desk. Issued 11/10/72.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1540SW	Lavatory. Issued 11/10/72.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1571WE	Relocation of Fairchild Model F-542 flight data recorder.	NW	85122	West Coast Airlines, Inc. 1219 Westlake North Seattle, WA 98108
F-27 Series; T.C. 7A1	SA1629SW	Change seat to rigid back and relocate legs to accommodate installation with plush side panels for headrest for aft facing. Issued 3/20/73.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA1738SW	LEAR AVIA battery temperature sensor system. Issued 9/27/73.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
F-27 Series; T.C. 7A1	SA3096WE	Installation of Collins Radio Co. Model FPC-75 ground proximity warning system. Amended 4/6/76.	WE	83340	Hughes Air West P.O. Box 2966 Phoenix, AZ 85036
F-27, -27A, -27B, -27F, -27G; T.C. 7A1	SA253CE	Supplemental Model E high intensity wing tip lights, Model C tail light, with or without Model 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
F-27, -27A, -27B, -27F; T.C. 7A1	SA302WE	Incorporation of Napier Spraymat deicing (as manufactured by applicanat) externally on Rotol propeller spinner as alternate to Dowty Rotol internal elements. Reissued 10/22/70.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
F-27, -27A, -27B, -27F; T.C. 7A1	SA384SW	Installation of radio racks with associated changes. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
F-27, -27A, -27B, -27F; T.C. 7A1	SA386SW	To fabricate wiring harness and make complete radio installation. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
F-27, -27A, -27F, -27J; T.C. 7A1	SA578SW	Fabrication and installation of rack for radar in nose wheel area. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F27, F27A, -B, -F, -G, -J, FJ227; T.C. 7A1	SA392CE	Install Hoskins Twin Mk V supplementary lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
F-27, F-27A, F-27B, F-27F, F-27G, F-27J, F-27M; T.C. 7A1	SA1463CE	Installation of microwave landing system airborne equipment. Issued 12/12/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
F-27, -27A, -27B, -27F, -27G, -27J, -27M, FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2569WE	Installation of battery temperature monitor system. Amended 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
F-27, -27A, -27B, -27F, -27G, -27J, -27M, FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2916WE	Installation of emblem lights on tip of horizontal tail. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
F-27, F-27A, -27B, -27F, -27J; T.C. 7A1	SA364SW	Collins AP-103E autopilot on aircraft with gross weight up to and including 42,000 pounds. Reissued 1/18/78.	WE	78490	Tiger Air Service Center, Inc. 3000 N. Clybourn Avenue Burbank, CA 91505
F-27, FH-227; T.C. 7A1	SA2-889	McMillan radome 7141X. Amended 11/21/73.	SO	64500	Piedmont Aviation Smith-Reynolds Airport Winston-Salem, NC 27102
F-27, FH-227; T.C. 7A1	ST542SC	Installation of Tramm BTI 600 Nicad battery temperature indicating system. Amended 10/10/73.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
F-27, FH-227; T.C. 7A1	SA1131CE	Replacement of Walter Kidde chemical air drier housing with Overland housing. Issued April 1975.	CE	62026	Overland Aviation Service Co. 10271 Bach Boulevard Overland, MO 63132
F-27, FH-227; T.C. 7A1	SA1144CE	Replacement of Walter Kidde Chemical air drier refillable cartridge P/N 891643 with Overland housing. Issued July 1975.	CE	62026	Overland Aviation Service Co. 10271 Bach Boulevard Overland, MO 63132
F-27, FH-227; T.C. 7A1	SA1458WE	Installation of rain repellent system.	WE	90405	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27A; T.C. 7A1	SA219AL	Installation of cockpit voice recorder. Reissued 2/12/74.	AL	85890	Wien Air Alaska, Inc. 4100 Int'l Airport Road Anchorage, AK 99502
F-27A, F-27B; T.C. 7A1	SA350AL	Installation of baggage restraint. Reissued 2/4/74.	AL	85890	Wien Air Alaska, Inc. 4100 Int'l Airport Road Anchorage, AK 99502
F-27A, F-27F, F-27J; T.C. 7A1	SA622SW	Relocation of United Data recorder Model F-542 to aft cabin area. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourne Avenue Burbank, CA 91505
F27A, F, G, J, FH-227; T.C. 7A1	SA1610SW	Installation of Safeway deicer overshoe P/N 5651 and/or Semsa lead P/N S.2002 in lieu of Dowty Rotol overshoe and/or leads on Dowty Rotol propeller model R193/4-30-5/50 with blades P/N R.A. 25907. Amended 12/7/73.	EA	70830	SEMSA, Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779
F-27F; T.C. 7A1	SA4EU	Installation of lateral freight net at fuselage station 600.394 forward of rear luggage compartment.	EU	43720	Industriemaatschappij AVIO-DIEPEN N.V. Vliegveld Iepenburg RIJSWIJK (Z-HOLLAND) THE NETHERLANDS
F-27F; T.C. 7A1	SA5EU	Installation of metal freight floor in forward cabin.	EU	43720	Industriemaatschappij AVIO-DIEPEN N.V. Vliegveld Iepenburg RIJSWIJK (Z-HOLLAND) THE NETHERLANDS
F-27F; T.C. 7A1	SA6EU	Installation of General Logistics tie down rails along LH and RH walls and forward extension of LH seat rails.	EU	43720	Industriemaatschappij AVIO-DIEPEN N.V. Vliegveld Iepenburg RIJSWIJK (Z-HOLLAND) THE NETHERLANDS
F-27F; T.C. 7A1	SA2065WE	Installation of Bendix Model PB-60 flight control system.	EA	16010	The Bendix Corporation Teterboro, NJ 07608

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F-27F, F-27G; T.C. 7A1	SA1179SW	Installation of Hartman vertical scale engine instruments. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourne Avenue Burbank, CA 91505
F-27J, -27M; T.C. 7A1	SA1030SW	Interior installation. Reissued 8/12/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
F-27J, -27M; T.C. 7A1	SA1031SW	Electronics system. Reissued 8/12/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
FH-227; T.C. 7A1	SA456EA	Interior. Amended 5/31/67.	EA	18750	Butler Aviation Friendship, Inc. Friendship Int'l Airport Baltimore, MD 21240
FH-227; T.C. 7A1	SA479EA	Manufacture and installation of buffet units.	EA	18750	Butler Aviation Friendship, Inc. Friendship Int'l Airport Baltimore, MD 21240
FH-227; T.C. 7A1	SA638CE	Installation of engine starter voltage control unit in starter system.	CE	62030	Ozark Airlines, Inc. P.O. Box 10007 Lambert Field St. Louis, MO 63145
FH-227; T.C. 7A1	SA685SW	Installation of provisions for SP-50F autopilot, includes wiring, cabling, brackets and racks only. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
FH-227; T.C. 7A1	SA705EA	Installation of Leland CSV1186-2 regulator on Jack & Heintz F45-10C inverter.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, L.I., NY 11735
FH-227; T.C. 7A1	SA739SW	Interior modification.	SW	42550	Horton & Horton Custom Works, Inc. Meacham Field Fort Worth, TX 76106
FH-227; T.C. 7A1	SA799EA	Installation of overvoltage and overfrequency protection for Lear Siegler Inverters Model F45-10.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA670SW	Electronic system. Reissued 9/12/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
FH-227, -227B, -227C; T.C. 7A1	SA748SW	Sperry SP-50F autopilot. Reissued 9/12/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
FH-227, FH-227B; T.C. 7A1	SA854SW	Attitude & directional gyro displays HF, VHF Communication, ADF and VHF Navigation Receivers; Weather Radar installation, and Audio System for crew and passengers. Reissued 5/20/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA902EA	Installation of Brownline cargo system. Issued 2/24/72.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA931SW	Interior modification in accordance with Horton & Horton Works, Inc., DL 5918 dated 18 June 1968. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2246WE	Installation of large cargo door. Amended 9/20/71.	EA	34249	Fairchild Hiller Corporation Fairchild Drive Germantown, MD 20767
FH-227, -227B, -227C, -227D, -227E;	SA2251WE	Installation of Fairchild cockpit voice recorder system and Sundstrand United Data Control flight recorder system. Amended 1/7/71.	EA	34249	Fairchild Hiller Corporation Fairchild Drive Germantown, MD 20767
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2363WE	Installation of interior arrangement. Reissued 6/3/74.	EA	34249	Fairchild Industries, Inc. 20301 Century Boulevard Germantown, MD 20767
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA2954WE	Installation of convertible passenger-cargo cabin interior. Issued 10/21/74.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA735SW	Installation of Collins AP-103F automatic flight control system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
FH-227, -227B, -227C, -227D, -227E; T.C. 7A1	SA736SW	Electronics installation according to Collins DL 271-6224-000, or installation of United Data Control Model F-542 flight data recorder as an alternate for Fairchild 5424(502). Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
FH-227, -227B, -227D; T.C. 7A1	SA763SW	Complete electronics system including pilot's servo altimeter, antennas, flight data recorder, cockpit voice recorder. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
FH-227B; T.C. 7A1	SA971CE	Relocation and modification of existing hostess seat installation. Issued November 1973.	CE	62030	Ozark Airlines, Inc. Box 10007, Lambert Field St. Louis, MO 63145
FH-227B; T.C. 7A1	SA1059CE	New pilot and copilot seat belt - shoulder harness restraint system. Issued November 1974.	CE	62030	Ozark Airlines, Inc. Box 1007, Lambert Field St. Louis, MO 63145
FH-227B; T.C. 7A1	SA1946WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
FH-227B, -227C; T.C. 7A1	SA1176CE	Installation of Collins FPC-75 ground proximity warning system. Amended September 1976.	CE	62030	Ozark Air Lines, Inc. St. Louis International Airport Lambert Field St. Louis, MD 63145
FH-227B, -227C, -227D, -227E; T.C. 7A1	SA2945WE	Installation of convertible passenger-cargo cabin interior. Amended 10/29/74.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
FH-227C; T.C. 7A1	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 11/18/68.	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
FH-227C; T.C. 7A1	SA919EA	Installation of Collins AL 101 radio altimeter system. Reissued 12/23/75.	NE	08256	Air New England Logan International Airport East Boston, MA 02128
F-45; T.C. 603	SA306WE	Ceconite 101 covering of rudder, elevators and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
M-62 Series; T.C. 724	SA4-1082	Ceconite 101 covering of fuselage, ailerons, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
M-62 Series; T.C. 724	SA4-1362	Spraying and dusting modification.	WE	84834	Weatherly Aviation Company 2304 San Felipe Road Hollister, CA 95023
M-62 Series; T.C. 724	SH110WE	Installation of dual foldable/rigid internal litter on left side of passenger compartment. Reissued 10/8/74.	EA	34249	Fairchild Industries, Inc. Fairchild Drive Germantown, MD 20767
M-62 Series; T.C. 724	SH111WE	Installation of step on either side or both sides of aircraft, attached to skid and torsion bar between Stations 60 and 100.	WE	03270	U.S.D.A. Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
M-62 Series; T.C. 724	SA180SW	Modification of aircraft to 1 PCLM Part 8 agricultural aircraft. Reissued 4/17/74.	SO	61796	Ernest Olsen Route 1 Rebecca, GA 31788
M-62 Series; T.C. 724	SA333SW	Part 8 agricultural aircraft modification. Reissued 4/17/74.	SO	61796	Ernest Olsen Route 1 Rebecca, GA 31788
M-62 Series; T.C. 724	SA612WE	Pratt & Whitney R-985-AN1 engine.	WE	84834	Weatherly Aviation Co., Inc. 2304 San Felipe Road Hollister, CA 95023
M-62 Series; T.C. 724	SA648SW	Jacobs R755-9-B2M engine, propeller, revised aileron. Reissued 4/17/74.	SO	61796	Ernest Olsen Route 1 Rebecca, GA 31788
M-62 Series; T.C. 724	SA1008WE	Poly-Fiber covering of fuselage. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92519
FH-1100; T.C. H2WE	SH87WE	Installation of twin litters on left side of interior passenger compartment including supporting structure and movable center door post. Reissued 6/23/80.	WE	42139	Hiller Aviation 2075 North Scranton Avenue Porterville, CA 93257

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
FH-1100; T.C. H2WE	SH107WE	Installation of Nightsun SX-16C searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
FH-1100; T.C. H2WE	SH118WE	Installation of single, foldable emergency stretcher on left side of passenger compartment. Amended 10/7/70.	WE	65328	Progressive Aviation, Ltd. Reid - Hillview Airport San Jose, CA 95122
FH-1100; T.C. H2WE	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
FH-1100; T.C. H2WE	SH341AL	Installation of Airglas skis.	AI	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
FH-1100; T.C. H2WE	SH360AL	Installation of modified cargo racks.	AI	08486	Alaska Helicopters P.O. Box 6283, Airport Annex Anchorage, AK 99502
FH-1100; T.C. H2WE	SH367AL	Installation of Alaskan Sky-Craft Co. cargo baskets. Revised 5/20/70.	AL	08500	Alaskan Sky-Craft Company, 7007 Seward Highway Anchorage, AK 99502
FH-1100; T.C. H2WE	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/79.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
FH-1100; T.C. H2WE	SH646EA	Installation of provisions for radar antenna waveguide.	EA	34249	Fairchild Hiller Corporation Aircraft Division Hagerstown, MD 21740
FH-1100; T.C. H2WE	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
FH-1100; T.C. H2WE	SH975EA	Installation of Consolidated Instrument Co., Inc. B206-TA-180 and B206D-TA-180 temperature alert temperature monitoring. Issued 3/20/74.	EA	25920	Consolidated Instrument Co., Inc. Teterboro Airport Teterboro, NJ 07608
FH-1100; T.C. H2WE	SH1010SW	Sliding tinted glass window assembly for forward right and left cabin doors.	SW	54500	M & N Plastics, Inc. 300 S. Lake Street Fort Worth, TX 76104

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

FOKKER - VFW B.V.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F27; T.C. A-817	SA302WE	Incorporation of Napier Spraymat de-icing (as manufactured by applicant) externally on Rotol propeller spinner as an alternate to Dowty Rotol internal elements. Reissued 10/22/70.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
F27 Mark 200, 400, 500, 600; T.C. 817	SA1610SW	Installation of Safeway de-icer overshoe P/N 5651 and/or Semsa lead P/N S.2002 in lieu of Dowty Rotol overshoes and/or leads on Dowty Rotol propeller model R193/4-30-4/50 with blades P/N R.C. 25907. Amended 12/7/73.	EA	70830	Semsa, Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779
F-28 Mark 1000; T.C. A20EU	SA2999WE	Installation of emblem lights on flap track fairings. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GATES LEARJET CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
23 Series; T.C. A5CE	SA148GL	Installation of radome kit 4088X. Issued 1/31/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
23 Series; T.C. A5CE	SA377AL	Installation of nose wheel guard. Issued 6/19/70.	AL	05958	Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
23 Series; T.C. A5CE	SA1019CE	Install lower cabin door designed to accommodate flare racks. Issued May 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1020CE	Install lower cabin door to accommodate aerial photography equipment. Issued May 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1098CE	Installation of drift (navigation) sight to be used in conjunction with aerial photography equipment. Issued February 1975.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1169CE	Stretcher installation in cabin area. Issued 10/21/75.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1171CE	Stretcher installation in baggage area. Issued 10/21/75.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
23 Series; T.C. A5CE	SA1299CE	Installation of provisions for infra-red scanning equipment. Amended July 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23 Series; T.C. A5CE	SA1321CE	Installation of dry ice dispenser. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23 Series; T.C. A5CE	SA1335CE	Installation of datum console rack. Issued 6/27/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23 Series; T.C. A5CE	SA1378CE	Install structural provisions on right hand side of airplane for removable camera door. Issued 10/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23 Series; T.C. A5CE	SA1381CE	Structural provisions for infra-red scanning equipment. Issued 10/26/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23; T.C. A5CE	SA1395CE	Install structural provision for Jelco infra-red scanner. Issued 1/5/78	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1396CE	Install lower cabin door designed to accept a carousel flare dispensing unit capable of being reloaded in flight. Issued 2/8/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1411CE	Install structural provision for a particle measuring probe. Issued 4/18/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1412CE	Install dry ice dispenser. Issued 4/19/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1548CE	Structural provision for NASA - Daedalus IR scanner. Issued 2/22/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
23 Series; T.C. A5CE	SA2294WE	Modification of nose wheel steering system. Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
23 Series; T.C. A5CE	SA2992WE	Installation of logo lights on horizontal stabilizer lower surface. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
23, 24 Series; T.C. A5CE, A10CE	SA481CE	Modification of electrical system for compliance with AD 66-14-02.	GL	34020	Executive Jet Aviation, Inc. Port Columbus Int'l Airport Columbus, OH 43219
23, 24 Series; T.C. A5CE, A10CE	SA830SW	Heat static units.	SW	29232	Delta Aircraft P.O. Box 12182 San Antonio, TX 78205
23, 24, 24A, 24B, 24C, 24D, 25, 25B, 25C; T.C. A5CE, A10CE	SA21RM	Installation of cabin divider. Issued 12/5/73.	RM	25252	Combs Gates Denver, Inc. Hangar #7 Stapleton Int'l Airport Denver, CO 80207
23, 24, 24B, 24D, 25, 25B, 25C; T.C. A5CE, A10CE	SA412CE	Installation of Woodward Electronic Engine synchronizer system.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
23, 24, 24B, 24D, 25, 25B, 25C, 35, 36; T.C. A5CE, A10CE	SA871SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 25, 25A, 25B, 25C; 35, 36; T.C. A5CE, A10CE	SA996EA	Installation of Shaw Aero fuel filler cap P/N's 457-2, -266, 370, -431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A; T.C. A5CE, A10CE	SA2429WE	Installation of windshield rain repellent system. Issued 10/8/71.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
23, 24, 24A, 24B, 24C, 24B-A, 25, 25A; T.C. A5CE, A10CE	SA2447WE	Installation of Lear Ni-Cad safety unit. Reissued 10/24/72.	WE	49850	Lear Avia Corporation P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
23, 24, 25; T.C. A5CE, A10CE	SA175RM	Replacement of throttle knob, Model EP-004, for 20 series Learjet equipped with Dee Howard thrust reversers. Issued 6/18/79.	RM	45790	Jet Accessories, Inc. P.O. Box 38568 Stapleton Field Denver, CO 80238
23, 24, 25 Series; T.C. A5CE, A10CE	ST488SO	Installation of Butler National 6A VAC/10A ADD Area Navigation System with altitude alerting capabilities that meet requirements of FAR 91.51. Issued 1/28/72.	SC	73874	Southern Airways Company Hangar One Atlanta, GA 30320
23, 24, 25, 35, 36 Series; T.C. A5CE, A10CE	SA1033SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid batteries. Issued 11/21/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
24; T.C. A10CE	SA841NW	Performance improvement fairings to wing and nacelles. Issued 10/23/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road Seattle, WA 98108
24; A10CE	SA1065SO	Installation of support rack (incubator). Issued 4/18/79.	SC	64150	Personalized Interiors, Inc. 240 S.W. 34th Street Ft. Lauderdale, FL 33315
24 Series; T.C. A10CE	SA1874WE	Installation of Janco auxiliary cabin heater.	RM	37098	The Gates Rubber Company 8601 Montview Boulevard Denver, CO 80220
24 Series; T.C. A10CE	SA2329WE	Installation of Microcom, Inc. Lear AFC-70 autopilot (previous modification per STC SA2228WE - Microcom, Inc. nose wheel steering modification required). Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
24 Series; T.C. A10CE	SA2373WE	Installation of Microcom, Inc. Lear altitude alerter system, Microcom P/N 800074. Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
24, 24A, 24B; T.C. A10CE	SA1549CE	Installation of structural provisions for infra-red scanning equipment. Issued 2/26/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, B, BA, C, D, D-A, 25, 25A, B, C; T.C. A10CE	SA1RM	Installation of cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, D, E, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA14RM	Installation of Branson flight crew emergency exit. Amended 6/12/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, B, B-A, C, D, D-A, E, F, 25, 25A, B, BC, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA149GL	Installation of radome kit 4088X. Issued 1/31/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations Akron, OH 44309
24, 24A, 24B, 24C, 24D, 25, 25A, 25B, 25C; T.C. A10CE	SA960CE	Lower cabin door designed to accommodate four flare racks for cloud seeding. Issued February 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E, 24F, 25, 25A, 25D, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA961CE	Installation of lower cabin door designed to accommodate aerial photography equipment. Amended 6/7/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E., 25, 25A, 25B, 25C, 25D, 25F, 35, 36; T.C. A10CE	SA1091CE	Installation of drift (navigation) sight to be used in conjunction with aerial photography equipment. Amended 5/3/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A thru 24F, 25, 25A thru 25F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1170CE	Stretcher installation in cabin area. Amended 6/1/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A thru 24F, 25, 25A, B, D, F, 28, 35, 35A; T.C. A10CE	SA1172CE	Stretcher installation in baggage area. Amended 6/1/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E, 24F, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA1281CE	Lower cabin door designed to accommodate a flare rack capable of being reloaded in flight. Amended 6/22/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA1298CE	Installation of provisions for infra-red scanning equipment. Reissued July 1977.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
24, 24A thru 24D, 25, 25A thru 25F (S/N 25-229 or earlier), 35, 35A, 36, 36A; T.C. A10CE	SA1322CE	Installation of dry ice dispenser. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
24, 24A, B, C, D, 25, 25A, B,C, D, F; T.C. A10CE	SA1332CE	Install Litton digiprox ground proximity warning system (GPWS). Reissued 8/3/78.	WE	51500	Aero Products Division Litton Systems, Inc. 21050 Burbank Boulevard Woodland Hills, CA 91364
24, 24A, B, C, D, 25, 25A, B, C, D, 35, 35A, 36, 36A; T.C. A10CE	SA1336CE	Installation of datum console rack. Reissued 9/13/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1377CE	Install structural provisions on right hand side of airplane for removable camera door. Amended 6/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1382CE	Structural provisions for infra-red scanning equipment. Amended 6/4/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F; T.C. A10CE	SA1394CE	Install structural provision for Jelco infra-red scanner. Issued 1/5/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F; T.C. A10CE	SA1397CE	Install lower cabin door designed to accept a carousel flare dispensing unit capable of being reloaded in flight. Issued 2/8/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1410CE	Install structural provision for particle measuring probe. Amended 6/22/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1413CE	Installation of dry ice dispenser. Amended 6/4/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1477CE	Structural plug installation in right side of forward fuselage when camera door is removed. Issued 3/21/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA2876WE	Installation of vertical tail floodlights on the horizontal stabilizer. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3225WE	Installation of R.C.A. Primus 35 weather radar system. Issued 6/25/76.	WE	37095	Gates Learjet Modification & Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3226WF	Installation of Collins FD 112V flight director system. Issued 6/25/76.	WE	37095	Gates Learjet Modification & Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 24F; T.C. A10CE	SA3263WE	Installation of J.E.T. DAC 2000 RNAV system. Issued 11/29/76.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3264WE	Installation of Global GNS-500A VLF navigation system. Reissued 3/3/78.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3326WE	Installation of Collins ALT-55 radio altimeter. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3327WE	Installation of Motorola Model NA135 Selcal system. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E,F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3328WE	Installation of flight data recorder Sundstrand Model FA542. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3422WE	Installation of dual Collins MC-103 compass systems.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3426WE	Installation of R.C.A. Primus 400 weather radar system. Issued 6/29/77.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24C, 24D, 24D-1, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F; T.C. A10CE	SA3615WE	Installation of Collins NCS-31A area navigation system. Issued 4/7/78.	WE	37095	Gates Learjet-Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3647WE	Installation of dual Collins ALT-50 and ALT-55 radio altimeter system with comparator. Issued 6/5/78.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3677WE	Installation of Wulfsberg WT-200 communication transceiver system. Issued 8/31/78.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F; T.C. A10CE	SA3807WE	Installation of Jet Elec. & Tech. DAC-2000 R/NAV system with transfer switching for data from pilot to copilot panel. Issued 12/19/78.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA3735WE	Installation of optional single or dual H-field antenna (Global P/N 11455-1) for Global GNS-500A system. Amended 7/19/79.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3850WE	Installation of RCA Primus 300 color weather radar system. Issued 2/7/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3866WE	Installation of Wulfsberg Model AT-960 antenna. Issued 3/6/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29; T.C. A10CE	SA3899WE	Installation of Collins FIS-84 flight instrument system. Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3915WE	Installation of RCA Primus 400 check list (Data Nav I). Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA3975WE	Installation of Collins WXR-300 color radar. Issued 6/7/79.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4003WE	Installation of Bendix RDR-1200/RDR-1300 color radar check list. Issued 7/26/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29; T.C. A10CE	SA4028WE	Installation of Sundstrand Mark II ground proximity warning system. Issued 9/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25B, D; T.C. A10CE	SA4054WE	Installation of SUNAIR ASB-850 high frequency radio communications system. Issued 1/16/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F; T.C. A10CE	SA4073WE	Installation of Sunair ASB-850 high frequency radio communication system. Issued 1/23/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4194WE	Installation of dual Sperry C-14A compass systems. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24B; T.C. A10CE	ST485SO	Installation of Smiths Industries Type 3B series (WL/1101 AM/MS or 1103 AM/MS) servoed altimeter WL/504/CUF altitude alerting unit, and Smiths pressure error transducer (Type A108 for Model 24 and Type 104 for Model 24B). Issued 1/19/72.	SC	73075	Smiths Industries, Inc. St. Petersburg/Clearwater Airport St. Petersburg, FL 33732
24, 25; T.C. A10CE	SA117GL	Installation of cabin temperature control system. Issued 5/17/76.	GL	31640	Ned Wilkins Eaton Corp. Flight Operations Cuyahoga County Airport 355 Richmond Road Cleveland, OH 44143

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
24, 25; T.C. A10CE	SA891CE	Relocate optical window port. Amended May 1976.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 25; T.C. A10CE	SA1635WE	Modification of lower half of passenger entry door to accommodate camera installation. Amended 8/29/75.	WE	43450	Mark Hurd Aerial Surveys, Inc. Box 488 Goleta, CA 93017
24, 25; T.C. A10CE	SA1746SW	Model 7107 battery fault warning system. Issued 10/19/73.	SW	66500	Ray Electronics Company 107 Braniff Drive San Antonio, TX 78216
24, 25; T.C. A10CE	SA2228WE	Modification of nose wheel steering. Amended 5/12/75.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
24, 25, 35, 36 Series; T.C. A10CE	SA2788SW	Tail-stringer antenna housing. Issued 6/5/78.	SW	74965	Sted-Mac Co. Box 6123 A.T.S. Midland, TX 79701
24A as certified under STC SA7RM, 25, 25A, 25B modified per STC SA14RM; T.C. A10CE	SA9RM	Installation of cabin cargo retention nets. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24A as certified under STC SA7RM, 25, 25A, 25B modified per STC SA14RM; T.C. A10CE	SA10RM	Installation of cabin cargo liner. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24B, 24D; T.C. A10CE	SA136GL	Install Intercontinental Dynamics Corp.'s altimeter P/N 16007-703 or P/N 16007-803 in aircraft equipped with IDC altitude alerter. Issued 10/1/76.	GL	34020	Executive Jet Sales, Inc. Port Columbus Int'l Airport Columbus, OH 43219
24B, 24D, 25, 25B, 25C; T.C. A10CE	SA2675WE	Installation of sound suppressors. Reissued 11/12/75.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
24D; T.C. A10CE	SA31RM	Structural provisions for cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24D; T.C. A10CE	SA33RM	Quick change cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24D; T.C. A10CE	SA232NW	Installation of Mark II performance system. Issued 10/24/75.	NW	66175	The Raisbeck Group 2471 Perkins Lane West Seattle, WA 98199
24D; T.C. A10CE	SA639RM	Install EP-001 starter/generator decoupler system. Issued 6/28/78.	AL	45790	Jet Accessories, Inc. P.O. Box 38568 Stapleton Field Denver, CO 80238
24D; T.C. A10CE	SA1648SW	Stretcher installation according to Qualitron Aero. Reissued 5/20/59.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
24E, 24F, 25D, 25F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4146WE	Installation of Litton LTN-211 Omega/VLF navigation system. Issued 5/5/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
25 Series; T.C. A10CE	SA3280WE	Installation of fuel filler well for fuselage tanks. Issued 10/27/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
25, 25A, 25B, 25D, 28; T.C. A10CE	SA3891WE	Installation of Sunair Model ASE-130 high frequency radio communication system. Issued 3/27/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
25, 25A, 25B, 25C, 25D, 25F, 28, 29, 35, 36, 36A; T.C. A10CE	SA1489CE	Removal of 24-inch executive door and installation of 36-inch cargo door. Amended 7/3/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1376CE	Andrea Radio Corp. (A-81) five station interphone system. Reissued 12/30/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1497CE	Structural provision for NASA - Daedalus IR scanner. Amended 12/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3561WE	Installation of a fuel filter. Amended 5/20/80.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
25, 25B; T.C. A10CE	ST147RM	Installation of Communications Components Corp. Ontrac III VLF/Omega navigation system. Issued 8/7/78.	RM	05940	Aircraft Radio & Accessory, Inc. Hangar 1 Stapleton Internationl Airport Denver, CO 80207
25, 25B, 25C; T.C. A10CE	SA30GL	Installation of electronic engine synchronizer system. Issued 7/12/73.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
25, 25B, 25C; T.C. A10CE	SA953CE	Installation of dual camera/intervalometer. Issued October 1973.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North Wichita, KS 67204
25, 25B, 25C; T.C. A10CE	SA3622WE	Modifications to add installation provisions for twin aerial survey cameras in the belly of the airplane. Issued 4/10/78.	WE	43450	Mark Hurd Aerial Surveys, Inc. P.O. Box 489 Goleta, CA 93017
25B; T.C. A10CE	SA29RM	Install mid-fuselage cargo compartment (500 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA30RM	Install tail cone cargo compartment (300 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA92GI	Install a Foster Airdata System, Inc. AD611/D area navigation system. Reissued and amended 2/20/79.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
25D; T.C. A10CE	SA4034WE	Installation of Canadian Marconi CMA-771 Omega/VLF navigation system. Issued 12/26/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
28, 29; T.C. A10CE	SA3926WE	Installation of Garrett Rescu 99 locator transmitter. Issued 5/9/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
29; T.C. A10CE	SA3928WE	Installation of Collins 718-U5 high frequency radio communications system. Issued 5/2/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35; T.C. A10CE	SA1195CE	Installation of dual Sperry C-12 gyro-compass system for use as navigational air. Issued 1/23/76.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35; T.C. A10CE	SA2288SW	Litton LTN-104 inertial navigation system. Issued March 1976.	SW	12250	Associated Radio Service 6911 Lemmon Avenue Dallas, TX 75220
35, 35A; T.C. A10CE	SA3633WE	Installation of AiResearch AiRNAV-200 RNAV and Global GNS-500A VLF navigation systems. Issued 4/27/78.	WE	37095	Gates Learjet-Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA3931WE	Installation of Litton LTN-72R inertial navigation system with DME/DME update. Issued 5/11/79.	WE	37094	Gates Learjet Corproation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA4075WE	Installation of Collins 718U-5M high frequency radio communications system. Issued 1/11/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA4086WE	Installation of Sperry SPI-80 flight director system. Issued 2/26/80.	WE	37094	Gates Learjet Corporation P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA82RM	Installation of Sperry SP180/81 Flight Director System, interfaced with J.E.T. FC-200 Automatic Flight Control System. Issued 10/8/76.	RM	05940	Aircraft Radio and Accessory Company, Inc. Hangar #1 Stapleton Int'l Airport Denver, CO 80202
35, 35A, 36, 36A; T.C. A10CE	SA160GL	Install a J.E.T. DAC-2000 3-D RNAV system. Amended 4/15/77.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
35, 35A, 36, 36A; T.C. A10CE	SA405NW	Installation of an ONTRAC III VLF/Omega navigation system. Amended 9/27/77.	NW	16888	Boise Cascade Aviation 3565 South Owyhee Boise, ID 83705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, 35A, 36, 36A; T.C. A10CE	SA1507CE	Installation of electronic consoles on cabin seat rails. Reissued 8/20/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1508CE	Installation of mounting plates in the tail cone for mounting of electrical inverters. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1509CE	Installation of instrumentation rack and inverter rack in baggage compartment. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1531CE	Installation of a pod aerodynamic fairing capable of accepting target towing equipment. Issued 10/31/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
35, 35A, 36, 36A; T.C. A10CE	SA1533CE	Installation of a Maritime Patrol surveillance system. Reissued 11/16/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA3198WE	Installation of Garrett TFE 731 engine synchronizer/EMI filter - engine speed. Issued 5/20/76.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. A10CE	SA3340WE	Installation of Communications Components Corp. ONTRAC III VLF/ Omega navigation system. Issued 2/10/77.	WE	37094	Gates Learjet Modification and Service Center Tucson Int'l Airport Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3346WE	Installation of Collins Radio Co. flight profile comparator (ground proximity warning system - GPWS). Issued 2/18/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3375WE	Installation of Foster Airdata AD611D area navigation system. Amended 7/17/79.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3396WE	Installation of hydromechanical fuel controls, computers, and harnesses. Issued 5/5/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. aA10CE	SA3398WE	Installation of cold cathode cabin lighting system. Issued 5/6/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3411WE	Installation of AFCS heading select system. Issued 5/20/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3420WE	Installation of pitch trim tone system. Issued 6/29/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3421WE	Installation of modified control wheel and stick pusher cutout system. Issued 6/29/77	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3438WE	Installation of Garrett AirNav 100 or 200 navigation system. Amended 6/1/78.	WE	07500	AiResearch Manufacturing Company of California 2525 West 190th Street Torrance, CA 90509
35, 35A, 36, 36A; T.C. A10CE	SA3440WE	Installation of VOR/ILS compass and vertical gyro instrument switching system.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3442WE	Installation of AFCS heading and/or pitch maneuver transfer systems. Amended 1/27/78.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3509WE	Installation of Tracor 7640 omega navigation system. Issued 11/4/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
35, 35A, 36, 36A; T.C. A10CE	SA3530WE	Installation of dual Collins 718U-5 HF system. Amended 10/31/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3531WE	Installation of Sundstrand MKII ground proximity warning system. Issued 12/12/77.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3532WE	Installation of Collins ANS-31A area navigation system. Issued 1/12/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3568WE	Installation of Delco Carousel IV-A inertial navigation system. Issued 2/17/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3808WE	Installation of Jet Elect. & Tech. DAC-2000 3-D R/NAV system. Issued 12/20/78.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3865WE	Installation of Sperry C-11B compass system. Issued 3/5/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3896WE	Installation of Collins FIS-84 flight instrument system. Issued 4/10/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3916WE	Installation of directional gyro and vertical gyro transfer switching system. Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3994WE	Installation of ONTRAC III Mod 6, Omega/VLF navigation system. Issued 7/17/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA4192WE	Installation of Canadian Marconi CMA-771 Omega/VLF navigation system. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA4204WE	Installation of Collins FDS-85 flight director, pilots side. Issued 7/30/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 36; T.C. A10CE	SA766NW	Installation of stall fences and removal of vortex generators. Issued 5/4/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road South Seattle, WA 98108
35A; T.C. A10CE	SA4060WE	Installation of Sunair ASB-500 high frequency radio communication system. Issued 1/17/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35A, 36A; T.C. A10CE	SA1240CE	Installation of Intercontinental Dynamics Corp. RAD/BAR altimeter without voice terrain advisory. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1241CE	Installation of dual IDC maximum allowable mach/airspeed indicators type 575, P/N 25850. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1306CE	Install copilot's IDC maximum allowable airspeed/mach indicator type 575, P/N 26320. Issued 3/14/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1340CE	Dual camera installation. Issued 7/14/77.	CE	37094	Gates Learjet Corporation 8220 West Harry Wichita, KS 67209
35A, 36A; T.C. A10CE	SA1505CE	Wing pylon external stores installation. Issued 9/28/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
36, 36A; T.C. A10CE	SA3529WE	Installation of Litton LTN-72 inertial navigation system. Issued 1/13/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
36, 36A; T.C. A10CE	SA3864WE	Installation of Litton LTN-72R inertial navigation/area navigation system. Issued 3/6/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
36, 36A; T.C. A10CE	SA4033WE	Installation of Litton LTN-72 (INS)/Global GNS-500A (VLF/Omega) or Litton LTN-72R (INS)/Global GNS-500A (VLF/Omega) interface. Amended 5/25/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
240; T.C. 793	SA4-1222	Doppler antenna at fuselage station 667.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1224	Autopilot AP-103.	CE	24250	Collins Radio Company 855 35 Street, N.E. Cedar Rapids, IA 52401
240; T.C. 793	SA4-1226	Janitrol S-50 cockpit heater.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1228	Shrouding of flammable fluid system valve required by AD 59-02-01.	WE	54600	Don Maier & Associates 6214 W. Manchester Avenue Los Angeles, CA 90052
240; T.C. 793	SA4-1236	Pressure bulkhead and support provisions for McMillan radome.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1241	AVQ-50 radar and equipment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1526	100,000 B.T.U. heater for ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1528	18-passenger cabin arrangement, APU installation and an aft baggage compartment smoke detector.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA4-1558	CV-340 compressor.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA7CE	Cockpit auxiliary heater installation, Janco Model 8032. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA13SW	APU for ground operation only.	SW	34000	Executive Aircraft Service Redbird Airport Dallas, TX 75232
240; T.C. 793	SA16CE	Float type fuel gage installation - ground visual fuel. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA32CE	Interior general arrangement - floor plan #9. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA35CE	Installation of generator overheat indicator. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240; T.C. 793	SA63EA	General Dynamics rectangular exhaust exit mufflers on aircraft with Hamilton Standard 43E60/6895-12 propellers and Pratt & Whitney R-2800-CB-16/17 engines.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
240; T.C. 793	SA177WE	Distance measuring equipment and transponder, and relocation of inverter installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA252SO	Supporting structure for camera mount A-28.	SO	10160	American Airmotive Corp. P.O. Box 187 International Airport Miami, FL 33101
240; T.C. 793	SA274EA	Electromagnetometer transmitting coil, batteries, transmitter junction box, and receiving "Bird." Amended 8/15/66.	EA	35300	Field Aviation Company, Ltd. P.O. Box 1001 Toronto Int'l Airport Melton, Ontario, Canada
240; T.C. 793	SA275EA	Antenna, radome, gyro and compass.	EA	44179	U.S. Geological Survey Department of Interior 8300 Colesville Road Silver Springs, MD 20907
240; T.C. 793	SA320WE	Ground blower.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240; T.C. 793	SA442WE	Extendable boom, detection crystal support, antenna, inverters, converters, and window enlargement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
240; T.C. 793	SA696SW	Fairchild cockpit voice recorder and control unit A-152-2.	SW	20550	Central Airlines, Inc. P.O. Box 2554 Fort Worth, TX 76101
240; T.C. 793	SA1054WE	Rolls Royce RDa 10 542-4 engines and Dowty Rotol R.245/4-40-4.5/13 propellers, an AiResearch APU and two combustion heaters.	WE	37280	General Dynamics 3302 Pacific Highway San Diego, CA 92112
240; T.C. 793	SA1303WE	Two 15KS-1000A1 standby rocket engines in fuselage tail cone and an aft pressure bulkhead.	WE	02315	Aerojet-General Corporation P.O. Box 15847 Sacramento, CA 95813
240; T.C. 793	SA1316WE	Underwing pressure refueling system and Roylin "Magna Stick" fuel level indicator.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
240; T.C. 793	SA3099WE	Modification of cargo door and cargo floor and removal of cabin pressurization. Issued 11/26/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
240; T.C. A-793	SA3697WE	Installation of cargo door, cargo floor and entry door. Amended 9/26/78.	WE	39877	Hamilton Aviation Company P.O. Box 11427 Tucson, AZ 85734
240; T.C. A-793	SA3801WE	Instalaltion of cargo door and cargo floor. Issued 12/6/78.	WE	39877	Hamilton Aviation Company Tucson Aviation Center P.O. Box 11746 Tucson, AZ 85734
240-17; T.C. A-793	SA4077WE	Conversion of military model T-29A to model 240-17. Issued 3/28/80.	WE	10360	American Turbine Engine Company 1150 Busch Garden Court Pasadena, CA 91105
240-27; T.C. 793	SA149EA	Conversion of military model B29B to model 240-27. Reissued 6/27/77.	WE	39877	Gordon B. Hamilton The Hamilton Aviation Co. P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. 793	SA150EA	Installation of: 19 passenger executive interior Solar T-350M2 turbine APU comm and navigational systems. Reissued 6/27/77.	WE	39877	Gordon B. Hamilton The Hamilton Aviation Co. P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. 793	SA777SO	Installation of a cargo barrier bulkhead. Issued 10/4/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
240-27 (T-29B); T.C. 793	SA1048SO	Conversion of USAF Model T-29B into the civil Model 240-27 with deviations to TCDS A-793. Amended 8/16/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
240-27 (T-29B); T.C. A-793	SA1100SO	Conversion of the USAF T-29B into the civil model 240-27 with deviations to Aircraft Spec. A-793. Issued 9/10/79.	SO	44320	International Transportation P.O. Box 1183 Ormond Beach, FL 32074
240-27 (T-29B); T.C. 793	SA1135SO	Installation of a Class "E" cargo compartment, cargo floor modification, large aft cargo door, and removal of certain components of the previously deactivated pressurization system. Issued 2/22/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
240-27 (T-29C); T.C. A-793	SA1152SO	Conversion of USAF Model T-29C into Civil Model 240-27. Issued 6/27/80.	SO	44320	International Transportation P.O. Box 1183 Ormond Beach, FL 32074
240-27; T.C. A-793	SA3831WE	Installation of King weather radar. Amended 11/7/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. A-793	SA4025WE	Installation of cargo door, cargo floor, class "E" cargo compartment provisions for weather radar installation. Issued 9/28/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. A-793	SA4026WE	Conversion of military T-29B to civil model 240-27. Issued 9/28/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240-27; T.C. A-793	SA4027WE	Installation of a boarding ladder. Issued 9/28/79.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
T29B/240-27; T.C. A-793	SA4155WE	Installation of two Southwind combustion heaters, P/N 8472, with associated plumbing, ducting and fire protection. Issued 5/29/80.	WE	39877	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
240, 340; T.C. 793, 6A6	SA4-861	Stainless steel overlay nacelle area required by AD 59-02-01.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
240, 340; T.C. 6A6	SA426EA	Installation of Chamberlain replacement radome 3008 or 3008C. Amended 11/27/67.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company Aero Product Operations P.O. Box 1187 Akron, OH 44309
240, 340, 440; T.C. 793, 6A6	SA1-656	Radome assembly 3008.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
240, 340, 440; T.C. 793, 6A6	SA3-420	Main cabin seat installations (including divan and seat belts). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
240, 340, 440; T.C. 793, 6A6	SA4-500	Engine mount core assemblies. (Parts manufactured under license from United Aircraft Corporation.)	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
240, 340, 440; T.C. 793, 6A6	SA4-525	Engine mount core 106-1F and 106-1J.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
240, 340, 440; T.C. 793, 6A6	SA4-568	Engine mount core assemblies DE1468.	WE	83500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
240, 340, 440; T.C. 793, 6A6	SA41SO	B-300B engine oil separator.	SO	04400	Air Carrier Engine Service, Inc. International Airport Miami, FL 33101
240, 340, 440; T.C. 793, 6A6	SA118SO	BS-040-2 oil separator.	SO	04400	Air Carrier Engine Service, Inc. International Airport Miami, FL 33101
240, 340, 440; T.C. 793, 6A6	SA125CE	High intensity wing tip lights Model B or F, tail lights Model C, with or without Model 2 fuselage lights, STC SA4-1100 modified aircraft. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
240, 340, 440; T.C. 793, 6A6	SA775SW	Airstep.	SW	85128	Westernair of Albuquerque, Inc. 4736 Isleta Boulevard, SW Albuquerque, NM 87101
240D, 340D, 440D; T.C. 793, 6A6	SA1927SW	Installation of Safeway De-Icer boot P/N 5660 and/or Semsa Lead P/N S2001 in lieu of Dowty Rotol boots and/or leads on Dowty Rotol propeller models R245/4-40-4.5/13 with blades P/N 6.6000.2301 or Model R259/4-40-4.5/17 with blades P/N 6.6000.4300. Amended 2/27/75.	EA	70830	SEMSA, Inc. 2125 Smithtown Avenue Ronkonkoma, NY 11779
240D (600); T.C. 793	SA1992SW	Aft cargo door between F.S. 549 and 658 between floorline and stringer and associated structural modifications. Issued 6/6/75.	SW	07740	Air Freighters International P.O. Box 2 15808 Addison Road Addison, TX 75001
340; T.C. 6A6	SA1-488	Various radio and modifications plus rearrangement of control head on pedestal and revised radio electrical circuitry.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
340; T.C. 6A6	SA3-419	General interior floor plan arrangement. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340; T.C. 6A6	SA3-421	Installation of auxiliary power unit. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340; T.C. 6A6	SA4-38	Two additional passenger windows and three double passenger seats forward of fuselage station 243.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340; T.C. 6A6	SA4-219	Vibration suppressor plates.	WE	52010	Lockheed Aircraft Service, Inc. P.O. Box 33 Ontario, CA 91761

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340; T.C. 6A6	SA4-1164	Flammable fluid system valve shrouding required by AD 59-02-01.	WE	54600	Don Maier & Associates 6214 W. Manchester Avenue Los Angeles, CA 90052
340; T.C. 6A6	SA4-1211	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340; T.C. 6A6	SA4-1321	Interior modification including a 16-passenger executive type interior arrangement and baggage compartment smoke detector.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340; T.C. 6A6	SA4PC	Brownline cargo pallet and net assemblies.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA5PC	Conversion to an all cargo airplane.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA6PC	Cargo/passenger combination interior.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA7PC	Removable triple seat.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
340; T.C. 6A6	SA83WE	Interior arrangement for 58 occupants.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340 with STC SA4-110 incorporated; T.C. 6A6	SA406GL	Installation of a Canadian Marconi CMA734 omega navigation system. Issued 5/16/80.	GL	84642	The Way International Box 328 New Knoxville, OH 45871
340; T.C. 6A6	ST409SO	Rear service door hinge.	SO	29234	Delta Air LInes, INc. Atlanta Airport Atlanta, GA 30320
340; T.C. 6A6	SA506SW	Hydraulic system modification.	SW	34180	FAA Aeronautical Center Engineering Division Will Rogers Field Oklahoma City, OK 73101
340; T.C. 6A6	SA713WE	AiResearch GTP30-54 turbine APU.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
340; T.C. 6A6	SA952EA	Installation of Solar T-62T-39 gas turbine auxiliary power unit. Issued 4/11/73.	EA	18750	Butler Aviation Friendship, Inc. Sub. of Butler Aviation Int'l Friendship Int'l Airport Baltimore, MD 21240
340; T.C. 6A6	SA2702SW	Two Friedrich window air conditioners and three electrical heaters. Issued 12/22/77.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
340; T.C. 6A6	SA4187WE	Installation of provisions for side looking radar. Issued 7/15/80.	WE	06755	Aircraft Technical Service, Inc. 6701 Odessa Avenue Van Nuys, CA 91406
340, 440; T.C. 6A6	SA1-471	Weather mapping radar.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
340, 440; T.C. 6A6	SA1-474	Installation of Chamberlain Aviation 2008X Series radomes. Reissued 9/12/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
340, 440; T.C. 6A6	SA1-500	Waste King flight data recorder 5424.	EA	18751	Butler Aviation National Airport Washington, D.C. 20090
340, 440; T.C. 6A6	SA3-486	Interior cabin configuration - general floor plan (20 passenger configuration). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340, 440; T.C. 6A6	SA3-487	Janitrol heater installation (100,000 BTU). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA3-488	Installation of radar nose, Bendix ANT-1E antenna and pitot modification (including Radome fabrication). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
340, 440; T.C. 6A6	SA3-511	Radome and airspeed indicator system.	SW	17075	Braniff Airways, Inc. Love Field Dallas, TX 75235
340, 440; T.C. 6A6	SA3-649	Maximum safety light system YG-766A or ALS9A-CV.	GL	59650	Minneapolis-Honeywell Regulator Company 2747 Fourth Avenue, South Minneapolis, MN 55401
340, 440; T.C. 6A6	SA4-36	General Dynamics 340 outer wing integral fuel tanks.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 400; T.C. 6A6	SA4-135	Oil tank and supporting structure rework (relocation of oil tank installation plumbing, oil tanks support rework, engine oil tank modification).	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-160	Andover type D-2, Model V-32 APU and associated equipment for ground operation only.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-194	Ranger APU for ground operation only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-207	AiResearch C-7500-1 divan.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-248	Cabin tables.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-249	Hardman 3048 and 3041 chairs.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-250	Galley and buffet.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-390	Radio and cargo compartment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Anglees, CA 90045
340, 440; T.C. 6A6	SA4-409	Interior for 52 passengers.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-418	Auxiliary A.D.I. tank in aft baggage compartment.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
340, 440; T.C. 6A6	SA4-582	Napier Eland 504 turboprop engines with deHavilland PD216/466 propellers with XPR5662950SA-124 or PPR626950SA-124 blades.	EU	61150	D. Napier & Son, Ltd. Acton London, W. 3, England
340, 440; T.C. 6A6	SA4-689	Napier Eland 504 turboprop engines with deHavilland PD216/466 propellers with XPR5662950SA-124 or PPR626950SA-124 blades.	EU	61150	D. Napier & Son, Ltd. Acton London, W. 3, England
340, 440; T.C. 6A6	SA4-914	Goodrich multidisc brakes and Westinghouse "Decelostat" anti-skid controller type AP-3 on aircraft modified per STC SA4-582.	EU	61150	D. Napier & Son, Ltd. Acton London, W. 3, England
340, 440; T.C. 6A6	SA4-1008	Seat track mounting floor structure.	SW	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1041	Alternate fuel source in aircraft with Pratt & Whitney R-2800 Series "C" engines and fuel flowmeters.	SW	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1100	Installation of Allison model 501-D13D or 501-D13H turbo propeller engines with Aero Products A6441FN-606A propeller, with associated modifications to engine mounting, nacelle, empennage, accessories and system. Amended 5/10/71.	GL	29750	Detroit Diesel Allison Division General Motors Corporation Indianapolis, IN 46206

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA4-1114	Fuel tank extension for 2,080-gallon turbine engine fuel on aircraft modified per SA4-1100.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA4-1120	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1152	Interior and equipment.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1191	17-passenger interior arrangement and smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1242	Extension of wing tank and oil tank rework. Fuel tank revised for use JP-4 fuel and kerosene.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1243	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1249	Extension of fuel tank to station 29 (for JP-4 kerosene or gasoline) and provisions for a gravity flow fuel jettison system on aircraft modified per STC SA4-1100 only.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA4-1318	McMillan radome.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1343	Gas turbine in tail cone section.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1344	Modification to air-conditioning system and installation of an air start supply line.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA4-1513	Interior and equipment on aircraft modified per STC SA4-1100.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1519	Air-driven alternator and vertical stabilizer omni navigational antenna and electrical system deviations on aircraft modified per STC SA4-1100.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA4-1589	Interior modification including divans, swivel chairs and cabinets for a total of 13 passengers on aircraft modified per STC SA4-1100.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA2SW	Auxiliary power battery (emergency D.C. power and emergency feathering system).	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
340, 440; T.C. 6A6	SA23WE	United Data Control F-542 flight data recorder.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA24WE	RCA AVQ-50 weather avoidance radar system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA25WE	Seat track on aircraft modified per STC SA4-409.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA34RM	Installation of Sierra 7000 SANS-TACAN System. Amended 12/12/74.	RM	11870	Aspen Airways, Inc. Hangar 5 Stapleton Int'l Airport Denver, CO 80207
340, 440; T.C. 6A6	SA36WE	Modification of fuel source for Ranger APU and Janitrol ground heater approved under STC's SA4-194 and SA4-195.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA42RM	Installation of two Sperry GH-14 gyro-horizon instruments. Reissued 1/20/75.	RM	37015	Frontier Airlines 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA50RM	Installation of additional anti-collision light system (white strobe lights). Issued 2/10/75.	RM	37015	Frontier Airlines 8250 Smith Road Denver, CO 80207

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA59RM	Installation of Collins type 331A-6P/6A course indicator and relocation of altitude alert control. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA60RM	Installation of Sundstrand ground proximity warning system, glide slope monitoring system and Honeywell low range radio altimeter system. Issued 7/11/75. Supplemental T.C. SA4-1100.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA71WE	Fuel source modification for Ranger APU approved under STC SA2-962.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA83GL	Install Bendix GPW-83 ground proximity warning system. Issued 9/5/75.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450
340, 440; T.C. 6A6	SA96GL	Installation of Collins FPC-590A ground proximity warning system. Issued 11/7/75.	GL	90135	Zantop International Airlines, Inc. Detroit-Willow Run Airport Ypsilanti, MI 48197
340, 440; T.C. 6A6	SA104RM	Install dual SELCAL system. Issued 6/22/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100); T.C. 6A6	ST133RM	Modification of turbine inlet temperature indicator Model BH183M to install precision potentionmeter in place of original tapot. Issued 2/17/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100); T.C. 6A6	ST134RM	Installation of coat closet at body station 230. Issued 2/22/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA151EA	Bendix doppler radar DRA-12.	EA	08196	Airmar Radio Service, Inc. 2177 Smithtown Avenue Ronkonkoma, NY 11779
340, 440; T.C. 6A6	SA184WE	Two 15KS-1000-A1 or two 15KS-1000-A1(E) standby rocket engines in fuselage tail cone. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
340, 440; T.C. 6A6	SA227EA	Nose cap weather radome. Amended 3/29/66.	EA	16600	Bethlehem Steel Corporation Aviation Service Division Bethlehem, PA 18016
340, 440; T.C. 6A6	SA232CE	Install aural mach warning system. Amended 2/27/67.	GL	37808	General Motors Corporation 3044 W. Grand Boulevard Detroit, MI 48202
340, 440; T.C. 6A6	SA264EA	Janitrol S-200 heater for ground operation only.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
340, 440; T.C. 6A6	SA279WE	Window emergency exit on right side of aircraft at station 651.5.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA379CE	Installation of Hoskins twilighter Mk V intensity STC SA4-1100 modified aircraft. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
340, 400; T.C. 6A6	SA423WE	Cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA427EA	All cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA428EA	Installation of FM #1, 2, and 3 Radiophone. Amended 5/26/67.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA429EA	Cabinet.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA443WE	Installation of cargo door, a cargo floor and an emergency exit, plus removal of original cargo door and forward passenger entrance door. Reissued 2/6/70.	NW	49350	Robert T. Lamson 7840 Southeast 20th Mercer Island, WA 98040
340, 440; T.C. 6A6	SA451EA	Cockpit voice recorder.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA454CE	Model CH 3002-3181 Hoover Aircraft Products evacuation chute.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
340, 440; T.C. 6A6	SA483EA	Installation of cabin window at F.S. 730.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA494EA	ADF-PA Interconnection.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA495EA	Installation of Flight Interphone System.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	ST519SO	Installation of underseat baggage restraint bars. Issued 11/1/72.	SO	77070	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440; T.C. 6A6	SA542CE	Make and install horizontal stabilizer tips.	GL	12570	Auto-Craft Engineering 1904 N. Colorado Avenue Indianapolis, IN 46206
340, 440; T.C. 6A6	ST548SO	Installation of external induction ram air scoops. Issued 8/28/73.	SO	53788	Mackey International Airlines 500 S.W. 34 Street Fort Lauderdale, FL 33315
340, 440; T.C. 6A6	ST596SO	Installation of exhaust system bracket. Reissued 1/6/75.	SO	02394	Aeronautical Engineering, Inc. 342 N.E. 2nd Court Dania, FL 33004
340, 440; T.C. 6A6	SA604EA	Installation of United Control Model F542 Flight Data Recorder.	EA	09520	Allegheny Airlines Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA651EA	Installation of UHF/FM Secure System.	EA	52012	Lockheed Aircraft Service, Inc. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA695WE	Rain repellant system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA669WE	Smoke detector, flight data recorder, and oxygen breathing system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	ST700SO	Installation of exterior emergency lighting system. Amended 5/8/72.	SO	77070	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440; T.C. 6A6	SA775WE	Interior.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505
340, 440; T.C. 6A6	SA780WE	Yoke assembly, pilot and copilot control.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA874WE	Shoulder harness installation. Amended 6/9/76.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90404
340, 440; T.C. 6A6	SA884EA	Installation of tail logo lights. Amended 10/19/71.	EA	18750	Butler Aviation Friendship, Inc. Sub. Butler Aviation International Friendship Int'l Airport Baltimore, MD 21240
340, 440; T.C. 6A6	SA896EA	Installation of Marshell interior kit assembly No. 96123. Amended 7/13/73.	EA	54200	Magee Plastics Company 6000 Babcock Boulevard Pittsburgh, PA 15237
340, 440; T.C. 6A6	SA908WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
340, 440; T.C. 6A6	SA925WE	Pitch servo of Sperry SP-20 autopilot system.	EA	16600	Bethlehem Steel Company 701 E. Third Street Bethlehem, PA 18016
340, 440; T.C. 6A6	ST926SO	Installation of cargo door and interior. Amended 7/18/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440; T.C. 6A6	ST927SO	Installation of cargo floor. Amended 7/18/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440; T.C. 6A6	SA1015WE	Modified fiberglass vertical stabilizer tip, and Grimes 9950-1 rotating beacon.	RM	37015	Frontier Airlines, Inc. Stapleton Int'lernational Airport Denver, CO 80207
340, 440; T.C. 6A6	SA1015EA	Installation of Atlantic Aviation Corp. (TSO C-39) attendant seat P/N 21.737. Issued 9/22/75.	EA	12500	Atlantic Aviation Corporation Greater Wilmington Airport Box 1709 Wilmington, DE 19899
340, 440 (580); T.C. 6A6	SA1027EA	Installation of Collins FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Alleghery Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340/440 modified in accordance with STC SA4-1100; T.C. 6A6	ST1035SC	Installation of a combination passenger/cargo interior to include an all cargo, 44 passenger/cargo, 10 passenger/cargo, and 6 passenger/cargc configurations. Issued 12/4/78.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36302
340, 440; T.C. 6A6	SA1060WE	AP101E Collins autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA1096WE	Rolls Royce Dart 542-4 engines with Dowty Rotol (c) R245/4-40-4.5/13 or (c) R259/4-40-4.5/17 propellers and associated modifications. Amended 7/27/66.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1097SO	Installation of two (2) double seats to increase passenger configuration from 44 to 48. Issued 8/30/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
340, 440; T.C. 6A6	SA1119WE	Twc additional emergency exits, and interior arrangement.	WE	37280	General Dynamics Conviar Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1132WE	Parker Aircraft, Inc. under-wing pressure refueling valve and Roylin "Magna-Stick" fuel indicator.	WE	06750	Aircraft Tack Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA1146WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA1174WE	Fuel jettison system.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA1218WE	Cargc floor, cargo door and forward service door.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1268WE	Interior and equipment.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505
340, 440; T.C. 6A6	SA1331WE	Installation of United Data Control, Inc. Model V-557 cockpit voice recorder system. Amended 3/28/67.	RM	37015	Frontier Airlines 5900 East 39th Street Denver, CO 80207
340, 440; T.C. 6A6	SA1338WE	Seat track, additional emergency exit and interior arrangement.	WE	37280	General Dynamics Corp. P.O. Box 1950 San Diego, CA 92112
340, 440; T.C. 6A6	SA1366WE	Installation of Collins Radio Company FD105 flight director system.	WE	37280	General Dynamics Convair Division P.O. Box 1950 San Diego, CA 92112

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G44, G44A, Modified -- Colemill STC 2-13; T.C. A-734	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 1/19/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
G-44, G-44A, SCAN 30; T.C. 734	SA61SW	Horizontal stabilizer raised 5/8 inch per STC SA2-13.	SW	52870	J.R. McDermott & Company, Inc. Lakefront Airport New Orleans, LA 70113
G-44, G-44A, SCAN 30; T.C. 734	SA121EA	Wheel 40-46 and brake 30-31.	GL	23250	The Cleveland Aircraft Products Company P.O. Box 158 Avon, OH 44011
G-44, G-44A, SCAN 30; T.C. 734	SA380WE	Engine, propeller and associated modifications of nacelle, electrical oil, fuel and vacuum systems.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA603WE	Large aft door. Reissued 3/17/67.	SC	37084	Gander Aircraft 3923 N.W. 24th Street Miami, FL 33142
G-44, G-44A; T.C. 734	SA835SO	Installation of Lycoming GO-480-G2D6 engines with Hartzell HC-A3VF-5R/V9333CH-3 reversing propellers. Reissued 10/9/79.	SO	02330	AEROMAR, Inc. 317 North Coconut Lane Palm Island Miami, FL 33139
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3174SW-D	Automatic flight system AK645 consisting of Century I autopilot with optional omni tracker system. Issued 1/31/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3175SW-D	Mitchell automatic flight system AK646 consisting of Century IIB autopilot with optional radio coupler. Issued 1/31/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3176SW-D	Mitchell automatic flight system AK647 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/17/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3184SW-D	Automatic flight system AK656 consisting of Century I autopilot with optional omni tracker. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3185SW-D	Mitchell automatic flight system AK657 consisting of Century IIB with optional radio coupler. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3186SW-D	Automatic flight system AK658 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Scan Type 30; T.C. A734	SA3221SW-D	Mitchell automatic flight system AK706 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 6/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Scan Type 30; T.C. A734	SA3222SW-D	Mitchell automatic flight system AK705 consisting of Century IIB autopilot with optional radio couplers. Issued 7/8/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44, G-44A; T.C. A-734	SA3979WE	Installation of Silver Instruments fueltron 111G digital fuel flow and totalizer system. Issued 6/15/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
G-73; T.C. 783	SA1-490	Opening in leading edge of right-hand wing for passing light installation.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
G-73; T.C. 783	SA1-546	Type 21 pump type pneumatic deicer system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
G-73; T.C. 783	SA3-22	Hull step fairing.	GL	17190	Briggs Manufacturing Company 6600 East Outer Drive Warren, MI 48089

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-73; T.C. 783	SA3-165	Two 100-ampere Eclipse 30E16-1 generators.	GL	37808	General Motors Air Transport City Airport Detroit, MI 48202
G-73; T.C. 783	SA3-194	Sonotone sintered-plate Alkaline Nickel-Cadmium battery.	GL	71520	George W. Sherwood City Airport Detroit, MI 48233
G-73; T.C. 783	SA4-1554	Structure modification to improve access to fuel tanks for stripping and resealing.	WE	06750	Aircraft Tank Service, Inc. 10201 Conasset Street Burbank, CA 91504
G-73; T.C. 783	SA292EA	Pump type pneumatic deicer system.	GL	38500	B.F. Goodrich Airport Operations Municipal Airport Akron, OH 44318
G-73; T.C. 783	SA310EA	Fabrication of new passenger seats and necessary cabin interior modifications. Amended 4/5/68.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
G-73; T.C. 783	SA319SW	Structural installation of McMillan 7501XW radome and RCA AVQ-55 antenna mount.	SW	12250	Associated Radio Service Company 7515 Lemmon Avenue Dallas, TX 75220
G-73; T.C. A-783	SA412GL	Installation of Parker Hannifin conversion kit P/N 199-81. Issued 5/29/80.	GL	62500	Parker Hannifin Corporation Cleveland Wheels & Brakes Div. 1160 Center Road Avon, OH 44011
G-73; T.C. 783	SA614SO	Installation of nose wheel shimmy damper IAW Gander drawings GA-2055 Chg. A and GA-2056 Chg. A.	SO	37084	Gander Aircraft Corporation 3923 N.W. 24th Street Miami, FL 33142
G-73; T.C. 783	SA1008WE	POly-Fiber covering of rudder. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
G-73; T.C. 783	SA2323WE	Increase in gross weight and installation of United Aircraft of Canada, Ltd., PT6A-27 engines. Amended 12/18/73.	WE	36699	Frakes Aviation, Inc. P.O. Box 159 Angwin, CA 94508
G-164; T.C. 1A16	SA4-1017	Lycoming R680-13 engine and Hamilton Standard 2B20-329/6135A-9 propeller.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA4-1019	Pratt & Whitney R-985-AN1, -NAS, -AN-14BMI, -39 or -39A engines and Hamilton Standard 2D30-277/6101A-12 to -18 propellers. Amended 9/30/65.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA32NW	Installation of 15.5 gallon auxiliary fuel tank in each upper wing panel. Amended 6/30/77.	NW	52066	Russell Longnecker Box 77 Mt. Vernon, WA 98273
G-164; T.C. 1A16	SA39WE	Pratt & Whitney R985-AN-3 engine and Hamilton Stnadard 2D30-227/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164; T.C. 1A16	SA170SW	Sensenich 5404R/MA96K propeller.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA287SW	Jacobs R-755-L4MB or R-755-B2M engine.	SW	52610	Lyon Flying Service, Inc. P.O. Box 726 Welsh, LA 70591
G-164; T.C. 1A16	SA312SW	Jacobs R-755-B2MI, R-755-B2M, L4M Series, R-755-A2M, or R-755-A2MI engine with short mount A1681, carburetor air filter box, funnel A1667, and Sensenich J5404/MA96K propeller.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA326CE	25-gallon auxiliary fuel tank on wing.	CE	59315	Mid-Continent Aerial Sprayers, Inc. P.O. Box 307 Hayti, MO 63851
G-164; T.C. 1A16	SA507SW	Optional 46-gallon wing center section fuel tank and alternate right-hand or left-hand carburetor muffs equipped with Jacobs L4M and R-755 series engine.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA647WE	Modified landing gear.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-164; T.C. 1A16	SA648WE	Additional flying wire.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA651WE	Modified wheels and brakes.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA1278WE	Ceconite 101 covering of wings and ailerons.	WE	26240	Cooper Engineering Corporation P.O. Box 3428 Van Nuys, CA 91408
G-164; T.C. 1A16	SA1295WE	Automatic flagman marker dispensing unit.	NW	03500	Air-Ag, Inc. Route 4 Walla Walla, WA 99362
G-164; T.C. 1A16	SA1407WE	Installation of Pratt & Whitney R-985-AN-1 engine and Hamilton Standard 2D30/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164; T.C. 1A16	SA1586WE	Installation of Pratt & Whitney R-1340-AN-1 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164, G-164A; T.C. 1A16	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
G-164, G-164A; T.C. 1A16	SA270WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller. Amended 7/11/68.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164, G-164A; T.C. 1A16	SA406NW	Installation of wing span extension. Amended 5/23/77.	RM	02360	Aero Mod General, Inc. Box 68 Latah, UT
G-164, G-164A; T.C. 1A16	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
G-164, G-164A; T.C. 1A16	SA940SW	Installation of Micronair AU-3000 spray units. Reissued 10/2/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164, G-164A; T.C. 1A16	SA1282SW	Jacobs-Page R-755SM engine and Grumman 5404/M96K propeller. Reissued 5/24/77.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
G-164 (S/N 301-400), G164A (S/N 400 and up); T.C. 1A16	SA1312WE	Fabrication and installation of 285-gallon fiberglass hopper (replaces 245-gallon metal hopper). Reissued 6/12/75.	GL	39542	Grumman American Aviation 318 Bishop Road Cleveland, OH 44143
G-164, G-164A; T.C. 1A16	SA1319CE	Chrome plated brake disc installation. Issued 7/22/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
G-164, G-164A; T.C. 1A16	SA1777WE	Installation of Hamilton Standard 3D40/6101A-17 propeller.	WE	85125	Western Aircraft Sales P.O. Box 753 Long Beach, CA 90801
G-164, G-164A; T.C. 1A16	SA2012WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	17022	Bowles Flying Service Route 1, Box 124-B Live Oak, CA 95953
G-164, G-164A, G-164B; T.C. 1A16	SA832SO	Installation of Hamilton Standard Model 2D30/6101A-10S propeller. Amended 10/15/76.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164, G164A, G-164B; T.C. 1A16	SA1427CE	Install smoke generator for Part 137, agricultural aircraft operations, only. Issued 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508 Renner Field Goodland, KS 67735
G-164, G-164A, G164B; T.C. 1A16	SA3077WE	Installation of elevator servo-tab. Reissued 3/17/77.	WE	26540	Robert L. Copeland 171 West Shannon Chandler, AZ 85224
G-164, G-164A, G-164B; T.C. 1A16	SA4101WE	Installation of locking tail wheel. Issued 2/14/80.	WE	11470	APS Products, Inc. 6751 Airport Road Redding, CA 96001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-164, G-164A, G-164B, G-164C; T.C. 1A16	SA2747SW	Lockable full swivel tail wheel. Issued 4/6/78.	SW	36700	Frakes Aviation Cleburne Airport Rt. 3, Box 229-B Cleburne, TX 76031
G-164, G-164A, AA-1, AA-1A, AA-1B, AA-5; T.C. 1A16, A11EA, A16EA	SA713GL	G-164's install P/N BA8210 filter assembly; AA-1, AA-5 install P/N BA 4210 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140
G-164A; T.C. 1A16	SA99NW	Installation of HSP 3D40-401 hub with EAC-100-2 blades. Issued 3/29/74.	NW	33000	Efficiency Aircraft P.O. Box 37 Kent, WA 98031
G-164A; T.C. 1A16	SA445NW	Installation of EAC-22D30-AG-200-4S prop on P&W R-985-AN-1 engine. Issued 5/9/77.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A; T.C. 1A16	SA809SW	Installation of 5-inch longer engine mount in S/N 401 and up. Reissued 9/25/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164A; T.C. 1A16	SA833SO	Installation of Hamilton Standard Model 12D40/6101A-105 propeller approved under STC SP830SO on Pratt & Whitney R1340-AN-1, S1H1 or S3H1 engines listed in TDS 1A16. Issued 4/28/75.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164A; T.C. 1A16	SA994SW	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101-12 propeller. Reissued 4/19/73.	GL	39542	Grumman American Aviation Corp. 318 Bishop Road Cleveland, OH 44143
G-164A, S/N 526 and up with a P & W R-1340-AN-1 engine and Hamilton Standard 12D40 propeller; T.C. 1A16	SA1077CE	Installation of Edo-Aire propeller governor. Issued January 1975.	CE	32500	Edo-Aire, Inc. Wichita Division 1326 S. Walnut Street Wichita, KS 67213
G-164A; T.C. 1A16	SA1222SW	64-gallon or 80-gallon fuel tanks. Issued 11/17/70.	EA	39540	Grumman Aerospace Corporation P.O. Box 147 Elmira, NY 14902
G-164A; T.C. 1A16	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 7/24/73.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-164A; T.C. 1A16	SA1422SW	Paper filter for engine induction air. Issued 1/19/72.	SW	17260	Frank Brinster 2214 North Parkwood Harlingen, TX 78550
G-164A; T.C. 1A16	SA2015WE	The 12-volt or 24-volt D.C. electrical generating system is replaced by an alternator system. Amended 12/21/78.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
G-164A; T.C. 1A16	SA2356SW	Wing tip extension of 20 inches. Issued 9/14/76.	SW	34405	Fram & Ranch Aerial Service Wharton, TX 77055
G-164A; T.C. 1A16	SA2444SW	Install P&W ACL PT6A-34 engine. Issued 12/2/77.	SW	36700	Frakes Aviation, Inc. Route 2, Box 229-B Cleburne Airport Cleburne, TX 76031
G-164A; T.C. 1A16	SA2731SW	PZL-3S engine and Dowty-Rotol propeller CR 289/3-110-F/1. Issued 3/17/78.	SW	52610	Lyon Flying Service, Inc. P.O. Box 726 Welsh, LA 70591
G-164A, G-164B; T.C. 1A16	SA78RM	Installation of air conditioner system. Amended 6/21/77.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
G-164A, G-164B; T.C. 1A16	SA434NW	Installation of EAC-12D40-AG-100S-4S prop on Pratt & Whitney R-1340-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA436NW	Installation of WAC-2D30-425-AG-100-4A prop on Pratt & Whitney R-985-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA1102SO	Manufacture and installation of a 360 gallon agricultural spray dispensing hopper. Amended 3/6/80.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701
G-164A, G-164B; T.C. 1A16	SA1129SO	Installation of a 320 gallon agricultural spary dispensing hopper. Issued 1/24/80.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-164A, G-164B; T.C. 1A16	SA1131SC	Installation of replacement fiberglass fuselage skin panels. Issued 3/13/80.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701
G164A, G164B; T.C. 1A16	SA2666WE	Ceconite 102 material covering of: G-164A - vertical and horizontal tail and wings; G-164B - complete aircraft. Amended 4/19/78.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-164A, G-164B; T.C. 1A16	SA4185WE	Installation of two Conrel dispensing pods. Issued 7/15/80.	WE	08550	Albany International Controlled Release Division P.O. Box 537 Buckeye, AZ 85326
G-164B; T.C. 1A16	SA199RM	Oil temperature controlled system. Issued 4/17/80.	RM	18268	Vincent S. Buraas P.O. Box 176 Northwood, ND 58267
G-164B; T.C. 1A16	SA4116SW	Lycoming LTP-101-600-A1A engine. Issued 4/29/80.	SW	62196	Page Industries, Inc. P.O. Bxo 191 Yukon, OK 73099
G-164B (Restricted Category); T.C. 1A16	SA3876WE	Installation of Alvis Leonides engine and Dowty Rotol (c)R284/3-20-3/8 constant speed propeller. Issued 3/6/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Morteson Avenue Salinas, CA 93905
G-164C (Restricted Category); T.C. 1A16	SA3764WE	Installation of Wright R-1820-71, -60; GP1820G-202A, 702C9GC1, 2, 3, 4, 704C9GC1, 2, 3, 4 engine and Hamilton Standard 43D50 or 33D50 constant speed propeller. Reissued 4/11/80.	CE	59320	Mid-Continent Aircraft Corp. Drawer L Hayti, MO 63851
G-164C; T.C. 1A16	SA4127WE	Installation of an AiResearch TPE331-1-101Z turboprop engine. Issued 4/18/80.	WE	75210	Floyd D. Stilwell Marsh Aviation 5060 E. Falcon Drive Mesa, AZ 85205
AA-1 Series; T.C. A11EA	SA809NW	Installation of fixed (flush) cowl flap, nose gear strut fairing and retainer. Issued 7/20/79.	NW	27241	Maynord C. Corsby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1 Series; T.C. A11EA	SA810NW	Installation of main landing gear fairings from the AA-5 series aircraft incorporating sheet metal covers over rubber in place of stock rubber parts. Issued 7/20/79.	NW	27241	Maynord C. Crosby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1; T.C. A11EA	SA1410SW	Mitchell automatic flight system AK301, consisting of Century I autopilot with optional omni tracker. Issued 12/28/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-1; T.C. A11EA	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
AA-1; T.C. A11EA	SA2104WE	Installation of Brittain Models B2C and PSS flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
AA-1; T.C. A11EA	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1010CE	Installation of wing leading edge cuffs. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1313CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-1, AA-1A, AA-1B; T.C. A11EA	SA3234WE	Installation of Piper oil cooler and associated installation components. Issued 7/8/76.	WE	05390	Aircraft Maintenance Service 7950B Joe Crosson Drive Santee, CA 92071
AA-1, AA-1A, AA-1B; T.C. A11EA	SA4106SW	Increase gross weight to 1560 lbs. for AA-1, 1560 lbs. for AA-1A, and 1600 lbs. for AA-1B. Issued 3/26/80.	SW	24100	James E. Collier Route 4, Box 810 Jefferson, TX 75657

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AA-1 (1969 and on), AA-1A (1969 and on), AA-1B (1969 and on), AA-5 (1972, 1973 and 1974 only); T.C. A16EA	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
AA-1; AA-5; T.C. A11EA, A16EA	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1B; T.C. A11EA	SA10NW	Installation of VA-3 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-1B; T.C. A11EA	SA11NW	Installation of VA-2 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	VAn's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-1C Utility Category; T.C. A11EA	SA3695WE	Installation of Lycoming 0-235-C2C engine and McCauley 1A105/SCM7154 propeller. No installation data required. Placards required with this installation: At the fuel filler caps - "80/87 MIN OCTANE AVGAS" Issued 7/7/78	WE	03105	Aero-Training, Inc. 89 John Glenn Drive Concord, CA 94520
AA-5; T.C. A11EA	SA66NW	Installation of VA-4 fiberglass wheel fairings. Issued 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-5; T.C. A16EA	SA1472SW	Mitchell automatic flight system AK374 consisting of Century IIB autopilot with optional omni tracker. Issued 6/28/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5; T.C. A16EA	SA1486SW	Mitchell automatic flight system AK373 consisting of Century I autopilot with optional radio coupler. Issued 5/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5, -5A, -5B; T.C. A16EA	SA1314CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-5B; T.C. A16EA	SA3031SW-D	Mitchell automatic flight system AK514 consisting of Century I autopilot with omni tracking system. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5B; T.C. A16EA	SA3032SW-D	Mitchell automatic flight system AK515 consisting of Century IIB autopilot with optional radio coupler. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5B; T.C. A16EA	SA3301WE	Installation of Model EGT-1 exhaust gas temperature monitoring system. Issued 11/23/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
AA-5B; T.C. A16EA	SA3309WE	Modification of primary control system by addition of rudder-aileron interconnect and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/27/77.	WE	12250	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
G-159; T.C. 1A17	SA1-399	Forward and aft attachment for HF antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA1-400	Bendix radar scanner attaching brakcets and electrical cable firewall plugs.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-401	Glide slope antenna mounting bracket.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-402	Installation of 37K-2 Marker Beacon Antenna. Amended 7/24/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-403	Fabrication of mounting blocks and installations of Lear sense antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-404	Fabrication and installation of adaptor for mounting Chance Vought seat 22-93597-B-2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-405	DL-1 loop assembly.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-406	Collins 37P-2 antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-407	AC Spark Plug Division FM telephone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-408	Radio equipment shelves.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-412	Bulkhead at station 193.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-413	Double-hinged door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-414	Bulkhead and door at station 232.5.	EA	23600	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-415	Bulkhead and door at station 485.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-417	Baggage compartment smoke detector system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-420	AC Spark Plug Division FM telephone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-421	Bendix LPA-70C loop antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-432	High frequency antenna. Amended 7/25/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-447	Bulkhead and door at station 251.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-448	Bulkheads at stations 183 and 239 and baggage shelf.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-449	Bulkhead and door at station 493.	EA	12500	Atlantic Aviation Corporation P.O. Bos 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-450	Partial bulkhead at station 223.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-465	Bulkhead at station 232.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-466	Bulkhead at station 257.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA1-472	Installation of Atlantic Aviation Corporation's TSO-C39 seat model "Retractable Seat --G II." Amended 1/13/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-493	Telectro AT-134-A marker antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-494	Collins 013107800 transponder antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-495	Collins 537F-1 radar scanner.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-498	Automatic flight control systems.	CE	24250	Collins Radio Company 855 35 Street, N.E. Cedar Rapids, IA 52401
G-159; T.C. 1A17	SA1-505	Two internally-mounted Aerojet-General 15KS-1000 A1 aircraft rocket engines in rear wing fillet.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361
G-159; T.C. 1A17	SA4-931	Avionics racks	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-932	Jump seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-942	Cabin oxygen supply system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa MOnica, CA 90405
G-159; T.C. 1A17	SA4-968	Divan.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-969	Swivel seat, fuselage station 133.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-972	L-102B autopilot.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
G-159; T.C. 1A17	SA4-976	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-991	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1000	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1015	Interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1048	Avionics racks to fuselage station 193.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1049	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1051	Oxygen breathing system applicable to altitude up to 30,000 feet.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1057	Anti-collision light.	GL	12488	Atkins Light Corporation 7636 Lyndale Avenue, South Minneapolis, MN 55401
G-159; T.C. 1A17	SA4-1058	Interior and equipment.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1068	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA4-1087	Cabin interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1098	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1115	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1123	Interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1125	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1168	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1267	Cabin interior furnishings and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1293	General Electric 20M63C8 generator.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1320	Interior modification including passenger oxygen system and baggage compartment smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1379	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1381	Interior modification.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1445	Modification to Bendix DRA-12 doppler radar.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
G-159; T.C. 1A17	SA4-1481	Cabin interior furnishings and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1497	Ten-passenger interior arrangement, system, and aft baggage compartment smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1580	Auxiliary power unit modification (GTCP 85-91C and/or GTC 85-291C installation). Amended 6/2/66.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1581	Interior modification including three swivel seats for authorized crew members only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1582	Third crew member seat.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA11EA	Fabrication and installation of baggage compartment storage shelves.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA12EA	Bulkhead and door at station 251.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA16EA	Fabrication and installation of an Avionics bracket under the floor.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA16GL	Incorporating AMF (Leland) inverters MGE 23-3 or MGE 23-400. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
G-159; T.C. 1A17	SA56WE	Interior and distance measuring equipment system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA60EA	Collins 237Z-1 antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA66EA	Fabrication and installation of a two-place seat.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA72WE	Interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA81EA	Fabrication and installation of bracketry for mounting a Collins 537F-8 radar scanner.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA88EA	Installation of a bulkhead and door at station 392.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA96EA	Wilcox electric transponder antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA98EA	Antenna masts.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA101EA	Skyphone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA106EA	Bulkhead and door at station 244.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA110WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA122EA	Atkins anti-collision light system control wiring changes, per STC SA4-1057.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA122CE	Install Hoskins supplementary light system consisting of Model A wing tip lights, or Model C or 2 tail light optionally, two of Model fuselage lights with M-3 or M-5 power supply. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
G-159; T.C. 1A17	SA131EA	Modification of extraction section of Vickers-Armstrongs, Ltd. engine mount attachment pin, 60216.	EA	52064	Robert Long and Ray Williams 49 Champ Avenue Pearl River, NY 10965
G-159; T.C. 1A17	SA138EA	Collins 137A-4 ADF fixed loop antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA141WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA147EA	Bulkhead and door at Station 487 and fore and aft bulkhead at Station 525.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA148EA	Bulkhead and door at Station 232.5 to Station 242.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA150WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA156EA	Kollsman 1708-01 sextant mount in ditching hatch.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA168EA	Bulkhead and door at fuselage Station 192.375. Amended 3/17/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA174GL	Modification of floor support between stations 228.5 and 353 to eliminate decrease in allowable floor loading with increased zero fuel weight. Issued 5/12/77.	GL	90135	Zantop Airways, Inc. Detroit Metro Airport Detroit, MI 48242

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA187EA	Bulkhead and door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA203EA	Two place seating capacity in cabin.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA218EA	Bulkhead and door at Station 232.5 - 226.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA267EA	Bulkhead and door at Station 487. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA282EA	Under-the-floor rework between fuselage stations 416 and 525 for divan installation.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA288EA	Executive interior and communication/navigation equipment.	EA	78510	Timmins Aviation, Ltd. Montreal International Airport Dorval, P.Q., Canada
G-159; T.C. 1A17	SA296WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA297GL	Installation of single Canadian Marconi CMA-734 Omega/VLF navigation system. Amended 6/30/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
G-159; T.C. 1A17	SA302WE	Incorporation of Napier Spraymat de-icing (as manufactured by applicant) externally on Rotol propeller spinner as an alternate to Dowty Rotol internal elements. Reissued 10/22/70.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
G-159; T.C. 1A17	SA314EA	Door in bulkhead at Station 525.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA315EA	Bulkhead and door at Station 232.5 - 226.5. Amended 3/17/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA340EA	3051 replacement radome. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
G-159; T.C. 1A17	SA352WE	Interior.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA370EA	Main landing gear nutcracker microswitch assembly relocated.	EA	86200	George R. Williams 49 Champ Avenue Pearl River, NY 10965
G-159; T.C. 1A17	SA373EA	Two three-place couches and oxygen provisions.	EA	03100	Aero Trades, Inc. Long Island Airport Ronkonkoma, NY 11779
G-159; T.C. 1A17	SA376GL	Reduction of maximum zero fuel gross weight. Issued 11/26/79.	GL	91034	Zantop Airways, Inc. Detroit Metro Airport Detroit, MI 48242
G-159; T.C. 1A17	SA389WE	11-passenger interior and equipment installation including dual Collins DF-203 ADF receivers and dual Collins MC-102 gyrosyn compasses.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA394SW	HF-G overspeed warning system.	SW	40000	The Hamilton Company 106 Neuhaus Street Houston, TX 77002
G-159; T.C. 1A17	SA399WE	Maximum allowable airspeed indicator.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA406SW	Engine breather drain extension with fairing.	SW	11604	Arco Sheet Metal Company 8346 Lockheed Houston, TX 77002

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA427SW	To install brackets for the installation of 2 each ADF loops, 1 each marker antenna, 4 each cabin speakers, 2 each cockpit speakers, and to install 4 each ADF sense antenna mounting brackets. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91502
G-159; T.C. 1A17	SA435SW	To fabricate wiring harness and make complete radio, radar installation. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-159; T.C. 1A17	SA437SW	Fabrication and installation of radio rack. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-159; T.C. 1A17	SA448WE	Interior.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA486WE	11-passenger interior and equipment installation including Collins flight director system (dual), radio magnetic indicator switching, plus DME and ATC transponder systems.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	ST512SO	Installation of cargo door and nets. Reissued 9/20/74.	EA	18750	Butler Aviation Baltimore/Washington Int'l Airport Baltimore, MD 21240
G-159; T.C. 1A17	SA541EA	Installation of new nose section, new nose gear, cabin interior and AiResearch GTC Model No. 85-134.	EA	39540	Grumman Aircraft Engineering Corp. Bethpage, L.I., NY 11714
G-159; T.C. 1A17	SA571SW	Collins radio altimeter system.	SW	12250	Associated Radio Service P.O. Box 20718 Dallas, TX 75221
G-159; T.C. 1A17	SA577EA	Installation of a 3-position fuel filter heat valve and control system for each engine.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA623WE	Eighteen-occupant interior with Atlantic Aviation jump seat for an additional crew member.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA636EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA637EA	Installation of Collins 621A-3 transponder.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA638EA	Installation of Collins 860E-2 DME.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA664EA	Installation of Sperry G-11B Gyro Compass System.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA665EA	Installation of Bendix DMA-29A DME System.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA666EA	Installation of Bendix TRA-61A transponder system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA667EA	Installation of Bendix MKA-28C marker beacon receiver.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA668EA	Installation of Frieden Type B-5 Driftmeter.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA723WE	12-passenger interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA730WE	12-passenger interior arrangement.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA735WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA761WE	13-passenger interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	ST762SO	Installation of main cabin floor support structure. Issued 8/19/77.	GL	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST763SO	Installation of courier seat and cockpit/main cabin partition. Issued 8/19/77.	GL	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST764SO	Enlarged passageway in FS525 main cabin bulkhead. Issued 8/19/77.	GL	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
G-159; T.C. 1A17	SA807SW	FD108/AP103E/F Flight Director-Autopilot combination for Category II operation.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA838WE	Shelf and webbing in baggage compartment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA839WE	Lavatory external service pan.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA879WE	Two radar altimeter antennas.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA886WE	Honeywell aircraft recognition light system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA888EA	Installation of Grimes three light strobe kit 34-0303-1 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
G-159; T.C. 1A17	ST889SO	Installation of Collins ground proximity warning system. Issued 3/16/76.	SC	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-159; T.C. 1A17	SA893SW	Dual FD-109 Flight Director/AP-104 Autopilot, 54W-1C Comparator Warning, AL-101 Radio Altimeter, MC-102 Compass, 51RV-1, VOR/ILS, 51Z-4 Marker, 860E-2 DME and DF-203 ADF systems.	SW	24252	Collins Radio Company Avionics System Center P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA998CE	Installation of battery temperature monitor and over temperature warning system.	CE	05250	Aircraft Instrument and and Development, Inc. 317 E. Lewis Wichita, KS 67202
G-159; T.C. 1A17	ST999SO	Installation of Bendix ground proximity warning system. Issued 6/24/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-159; T.C. 1A17	SA1034EA	Installation of Safeway de-icer overshoes P/N 5651 and/or Semsa leads P/N S.2002 on Dowty Rotol propeller model R184/4-30-4/50 with blades P/N R.A25907. Issued 3/22/76.	EA	70830	Semsa, Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779
G-159; T.C. 1A17	SA1050SO	Replace existing nickel cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
G-159; T.C. 1A17	SA1098WE	EGT and r.p.m. indicator for APU, Model GTC 85-37.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1137EA	Installation of the Global GNS-500A Omega navigation system. Amended 6/13/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-159; T.C. 1A17	SA1284WE	Kollsman MS28011-2 sextant.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-159; T.C. 1A17	SA1318WE	Lear Siegler, Inc. 510K autopilot system.	WE	07500	AiReserach Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1341CE	Installation of Collins Radio Group FPS-80 flight control system including electric trim. Amended 5/16/80.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, NE Cedar Rapids, IA 52406
G-159; T.C. 1A17	SA1536SW	Foxtronics TRAMM BTI-600 nickel-cadmium battery temperature system. Issued 11/10/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
G-159; T.C. 1A17	SA1559SW	Semi-automatic fuel trim system. Issued 12/4/72.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159; T.C. 1A17	SA1678SW	Modification of Burns BH 1600 (P/N 908-2-1 and -2) double seats. Issued 6/20/73.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1709SW	Oxygen service installation. Issued 7/31/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-159; T.C. 1A17	SA1745SW	ANS-70A Area Navigation System. Issued 2/21/74.	SW	24252	Collins Radio Company 1200 N. Alma Road Richardson, TX 75207
G-159; T.C. 1A17	SA1763SW	Modification to Burns BH1600 double seats to aft facing. Issued 11/14/73.	SW	84600	Ward Int'l Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1964WE	Installation of jump seat.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1955SW	Installation of Collins AP-105 autopilot for Category I operation. Amended 5/5/80.	CE	24250	Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
G-159; T.C. 1A17	SA2629WE	Installation of single point refueling system. Issued 1/8/73.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-159; T.C. 1A17	SA3044WE	Installation of fuel tank inter-connect system. Issued 7/9/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-159; T.C. 1A17	SA3641WE	Installation of DeVore Aviation Corp. horizontal stabilizer mounted vertical tail flood lights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
G-159, G-1159; T.C. 1A17, A12EA	SA10NE	Installation of a "back-up" passenger seat restraing system. Amended 3/30/78.	NE	69850	S.A.G.E. Corporation Burlington Int'l Airport Burlington, VT 05401
G-159, G-1159; T.C. 1A17, A12EA	SA1082SW	Revise nose gear steering cockpit control by installing BKM Guide-master.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159, G-1159; T.C. 1A17, A12EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
G-1159; T.C. A12EA	SA23NE	Installation of aluminum grating on cargo door at fuselage station 539.75. Issued 3/27/78.	NE	69850	S.A.G.E. Corporation Burlington International Airport Burlington, VT 05401
G-1159; T.C. A12EA	ST222GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
G-1159; T.C. A12EA	SA272GL	Installation of Intercontinental Dynamics Corp. engine vertical scale instruments. Amended 12/5/78.	EA	44160	Intercontinental Dynamics Corp. 170 Coolidge Avenue Box 81 Englewood, NJ 07631
G-1159; T.C. A12EA	ST566SO	Installation of Bendix RNS-3400 area navigation system. Amended 5/23/74.	SC	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA579EA	Installation of a custom interior.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA606EA	Installation of shelf and bracketry at fuselage station 743.0 - 769.62, replace metal skins with fiberglass between fuselage station 813.31 and 855.00 and bracketry provisions between fuselage station 812.50 and 826.50.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA607EA	Manufacturing and installation of partition and door blow out provisions. Amended 12/29/69.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA608EA	Installation of dual Sperry SPI-73E flight director.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA618EA	Installation of Atlantic Aviation Corporation's TSO'd retractable seat, Type G11. Amended 6/17/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA623EA	Installation of bulkhead door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA624EA	Installation of bulkhead and bulkhead door at fuselage station 194.25.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA625EA	Installation of bulkhead and bulkhead door at fuselage station 503.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA626EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. Reissued 6/3/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA627EA	Installation of Collins 54W-1 comparator warning system. Amended 12/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA628EA	Installation of Collins AL-101 radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA629EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA630EA	Installation of Sperry C-11B gyro compass system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA631EA	Installation of dual Collins F.D. 109G flight director systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA632EA	Installation of Pyrotector smoke detector system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA633EA	Installation of constant flow passenger oxygen system. Amended 12/5/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA645EA	Installation of structural provisions for the Collins doppler DH-101.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA649EA	Installation of Litton LTN-51 inertial navigation system. Amended 12/11/68.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA654EA	Installation of Honeywell hi-intensity recognition lights. Reissued 11/12/68.	GL	42250	Honeywell, Inc. 2600 Ridgway Road Minneapolis, MN 55413
G-1159; T.C. A12EA	SA655EA	Installation of Collins flight directors.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA657EA	Installation of Sperry comparator warning unit.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA658EA	Installation of Sperry altitude preselect system. Amended 12/31/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA659EA	Installation of Bendix ALA-51A radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE19899
G-1159; T.C. A12EA	SA660EA	Installation of dual Sperry SPI-73E flight director system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA662EA	Installation of an Air-Lavatory Drain. Amended 12/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA663EA	Installation of EDO Loran System. Amended 1/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA669EA	Installation of bulkhead and bulkhead door at fuselage station 201.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA670EA	Installation of bulkheads at fuselage stations 467.5, 485.0 and 515.25; bulkhead doors at fuselage stations 485.0 and 515.25; and longitudinal bulkhead at buttline 4 between fuselage stations 467.5 and 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA680EA	Installation of conference table.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA681EA	Installation of bulkhead and bulkhead door at fuselage station 255.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA682EA	Installation of bulkhead and bulkhead door at fuselage station 495.0. Amended 9/10/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA683EA	Installation of sliding door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA684EA	Installation of intercostals between fuselage station 244-1/2 to fuselage station 257-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA685EA	Installation of intercostals between fuselage station 487 to fuselage station 498. Amended 10/22/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA688EA	Installation of Collins FD-109H and FD-109F flight director system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA689EA	Installation of IDC 17000-22 Air Data Computer. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA691EA	Installation of a dual Collins DF-203 ADF.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA692EA	Installation of intercostals between fuselage station 193 to fuselage station 206.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA693EA	Installation of bulkhead and bulkhead door at fuselage station 495 5/8.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA694EA	Installation of bulkhead and bulkhead door at fuselage station 200.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA699EA	Installation of intercostals between fuselage station 345 7/8 to fuselage station 355 1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA701EA	Installation of Hartman Systems Company vertical scale engine instruments. Reissued 11/29/68.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA702EA	Installation of intercostals between fuselage station 452 1/2 to fuselage station 466.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA706EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. This STC does not apply to S/Ns 6, 11, 12, 14. Amended 12/27/73.	SC	15475	Bendix Corporation Bendix Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33309
G-1159; T.C. A12EA	SA718EA	Installation of intercostals between fuselage station 498 to fuselage station 512.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA721EA	Installation of swivel seat installation, fuselage stations 287 1/2 to fuselage station 379.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA722EA	Installation of Safe Flight SCAT/ Autopower System. Amended 1/7/75.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
G-1159; T.C. A12EA	SA723EA	Installation of intercostals between fuselage station 43-1/2 and fuselage station 452-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA724EA	Installation of vertical scale full quantity indicators Model VS-2PE (639-) as replacement for original round dial indicators.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746
G-1159; T.C. A12EA	SA726EA	Installation of seat track reinforcement conference table grouping.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA733EA	installation of intercostals between fuselage station 297 to fuselage station 306-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA734EA	Long range under floor oxygen cylinder installation. Amended 7/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA735EA	Installation of divan base aft support/attachment at fuselage station 460-1/4.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA748EA	Installation of skyphone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA749EA	Installation of combined divan-bunk on right hand side of aircraft between fuselage station 183 and fuselage station 255. Issued 4/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA750EA	Installation of seat track extension. Issued 4/16/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA758EA	Installation of partial bulkhead and door at fuselage station 182. Amended 11/19/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA759EA	Installation of bulkhead attachment. Amended 8/22/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA760EA	Installation of bulkhead and bulkhead door at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA761EA	Installation of bulkhead at fuselage station 448. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA763EA	Installation of Litton LTN-51 inertial navigation system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA777EA	Installation of bulkhead at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA778EA	Installation of bulkhead at fuselage station 459.5. Amended 8/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA779EA	Installation of Custom Products Model 400-21 three place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA783EA	Installation of Electronic Resources Skyphone (UHF) antenna 10-222-04880.	EA	12500	Atlantic Aviation Corporation Wilmington, DE 19899
G-1159; T.C. A12EA	SA789EA	Installation of two-place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA790EA	Installation of bulkhead and door at fuselage station 507.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA806EA	Installation of Atlantic Aviation Corporation's retractable seat-GII and refreshment cabinet.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	ST674SO	Installation of Collins ground proximity warning system. Issued 12/15/75.	SO	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-1159; T.C. A12EA	ST888SO	Installation of Litton "Digiprox" ground proximity warning system. Issued 3/9/76.	SO	51502	Litton Systems, Inc. 6065 Roswell Road N.E. Suite 305B Atlanta, GA 30328
G-1159; T.C. A12EA	SA937SW	Crew jump seat.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA940SW	Microair AU-3000 spray units.	EA	39540	Grumman Aircraft Engineering P.O. Box 147 Elmira, NY 14901
G-1159; T.C. A12EA	SA941SW	Collins HF communication system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA942SW	Collins AL-101 radio altimeter.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA943SW	Dual Sperry SPI-73 integrated flight system, Sperry instrumentation, comparator monitor and dual Sperry C11B compass system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA945SW	Litton LTN51 inertial navigation system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA946SW	Update Sperry 2587400-274 air data computer.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA948SW	Increase of DC output capabilities for APU TR unit.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA951SW	Passenger oxygen system and supplemental (long range) oxygen supply.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA957EA	Installation of modular berthable 1 or 2 place side-facing seat. Issued 7/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA970EA	Installation of Fairchild cockpit voice recorder Model A100 and A151 control unit. Issued 11/26/73.	EA	07498	AiResearch Aviation Company Islip MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA996EA	Installation of Shaw Aero fuel filler cap P/Ns 457-2, -266, -370, 431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
G-1159; T.C. A12EA	ST998SO	Installation of Bendix ground proximity warning system. Amended 8/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA1036SW	Bendix ALA-51A radio altimeter.	SW	12259	Associated RAdio Service Company P.O. Box 20718 Dallas, TX 75220

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA1037SW	Emergency lights and battery.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1060EA	Installation of a single or dual Delco Electronics Carousel IV-A inertial navigation system with computer program, P/N 7881711-006. Reissued and amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1061EA	Installation of a dual Collins ALT-55B radio altimeter system. Amended 12/23/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA1062EA	Installation of a Sperry air data computer, Intercontinental Dynamics Co. (IDC) servo altimeters and mach. Amended 12/28/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA1063EA	Installation of a dual Collins flight director system, Model FD-109Y. Amended 1/23/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. 4/30/79	SA1068SO	Installation of Intercontinental Dynamics Corp. radio/barometric altimeter with voice terrain advisory and Sperry mini air data computer. Issued 4/30/79.	SO	39725	Gulfstream American Corporation P.O. Box 2206 Savannah, GA 31402
G-1159; T.C. A12EA	SA1070EA	Installation of dual Litton LTN-72R navigation system. Reissued and amended 4/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1093SW	Decca loran system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1139EA	Installation of a dual or single Global GNS-500A VLF/Omega navigation system. Amended 10/10/79.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1157EA	Replacement of Garrett AiResearch GTCP-36-6 APU with Solar T-62T-40C2 APU. Amended 10/5/79.	EA	73275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
G-1159; T.C. A12EA	SA1186EA	Installation of an Eldec Corp. digital fuel flowmeter and totalizer system. Issued 2/22/80.	EA	10135	Amerada Hess Corporation Mercer County Airport P.O. Box 7385 West Trenton, NJ 08628
G-1159; T.C. A12EA	SA1187EA	Installation of a single Litton LTN-211 Omega/VLF navigation system. Issued 3/17/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1197EA	Installation of a single Litton LTN-72 inertial navigation system. Issued 5/30/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1250SW	Decca type 72 doppler radar system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1251SW	Decca omni-trac system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1336SW	Installation of pressure refueling control system. Issued 7/8/71.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1423SW	Electrical wiring feed thru Station 580. Issued 1/24/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1447SW	Battery fault warning system. Issued 9/18/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1480SW	Installation of FD-109F flight director, INS-61B inertial navigation system, Bendix ALA-51 radio altimeter. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-1159; T.C. A12EA	SA1481SW	Installation of cockpit control for center point refueling system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourne Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA1496SW	Tramm BTI-600 battery temperature indicating system. Issued 7/31/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA1553SW	Dual Collins INS-61B inertial navigation units. Issued 11/15/72.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1613SW	BKM master warning interface device between master warning control panel and aircraft inputs. Issued 3/1/73.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA1697SW	Avionics cooling fan. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1698SW	Oxygen service installation. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1633WE	Installation of jump seat in cockpit.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1634WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1654WE	Installation of passenger oxygen continuous flow system.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1683WE	Installation of passenger oxygen system.	WE	07500	AiResearch Aviation Company 6021 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1756WE	Installation of an aircraft integrated weight and balance system (STAN).	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1757WE	Installation of United Control flight data recorder.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1769WE	Installation of Sonotone Battery Model No. 989074-1 and battery container.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1771WE	Installation of SD1 Hoskins anti-collision light system. Amended 11/28/73.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
G-1159; T.C. A12EA	SA1772WE	Installation of United Control speed command system. Amended 6/19/70.	NW	80685	United Control Corporation Overlake Industrial Park Redmond, WA 98052
G-1159; T.C. A12EA	SA1800WE	Installation of radio rack and placards only for avionic components between fuselage stations 181-193 RH.	WE	63750	Qualitron Aero, Inc. Lockheed Air Terminal 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1814WE	Rain repellent system installation. Amended 10/25/73.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-1159; T.C. A12EA	SA1817WE	Installation of Sperry ATS-500 autothrottle system.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1819WE	Installation of doppler antenna and mount for doppler receiver and transmitter.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1848WE	Installation of Custom Products Model 1875 jump seat on radio rack.	WE	62105	Pacific General Corporation 3210A Winona Burbank, CA 91502
G-1159; T.C. A12EA	SA1868WE	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system.	SC	15475	Bendix Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA1889WE	Installation of Sperry SP-50G automatic flight control system, Sperry SPI-73E integrated instrument system and Sperry ATS-500 automatic throttle system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation P.O. Box 2529 Phoenix, AZ 85027

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA1898WE	Installation of Litton Model LTN-51 inertial navigation system. Amended 7/9/69.	WE	51500	Litton Systems, Inc. Guidance & Control Systems Division 5500 Canoga Avenue Woodland HIlls, GA 91364
G-1159; T.C. A12EA	SA1983WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2016WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2165WE	Installation of altitude preselect and alerting system (SP-50G Altitude Preselect System). Issued 7/8/70.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
G-1159; T.C. A12EA	SA2184WE	Installation of dual AC Carousel IV inertial navigation system. Amended 10/23/79.	GL	37810	General Motors Corporation A.C. Electronics Division Milwaukee, WI 53201
G-1159; T.C. A12EA	SA2234SW	Passenger continuous flow oxygen system. Issued 8/15/75.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2235SW	Dual Collins 61B inertial systems. Issued 8/15/75.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2237SW	BKM specific range computer. Issued 8/26/75.	SW	16850	The BKM Company P.O. Box 7001 , Dallas, TX 75209
G-1159; T.C. A12EA	SA2270SW	Manufacture and install a divan. Issued 11/7/75.	SW	11890	Associated Air Center Box 20718 - Love Field Dallas, TX 75220
G-1159; T.C. A12EA	SA2277SW	Continuous flow, low pressure oxygen system. Issued 12/10/75.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2366SW	Lighted speed brake handle. Issued 10/6/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2387SW	Dual Litton LTN-72R area navigation system. Issued 11/27/76.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2407SW	Install HF antenna on tail cone. Issued 2/11/77.	SW	36600	Foxtronics, Inc. P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA2430WE	Installation of dual Collins INS-61B inertial navigation system. Reissued 11/29/71.	CE	24250	Collins Radio Company 855 35th Street Cedar Rapids, IA 52406
G-1159; T.C. A12EA	SA2512WE	Relocation of speed-logic control unit of GTCP36-6 turbine auxiliary power unit and mounting provisions for spare speed-logic unit. Issued 5/12/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2592WE	Installation of auxiliary taxi light system. Issued 9/1/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2593WE	Installation of Dorne and Margolin DMN 4-15 antenna (VOR/localizer) is installed in vertical stabilizer. Amended 11/9/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2757WE	Installation of crew oxygen regulator and mask assemblies. Issued 9/7/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2797WE	Installation of wing tip mounted emblem lights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
G-1159; T.C. A12EA	SA2807WE	Installation of dual GAMMA I (SFN-2610) inertial navigation systems. Amended 6/28/74.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2907SW	Pitot head indicating system. Issued 1/30/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
G-1159; T.C. A12EA	SA2965WE	Installation of dual GAMMA I inertial navigation systems. Issued 1/16/75.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2995SW	Global GNS-500A VLF Omega navigation system. Issued 5/10/79.	SW	11890	Associated Air Center P.O. Box 20719 Dallas, TX 75220
G-1159; T.C. A12EA	SA3089WE	Installation of 104006 computer program in LTN-104 ANS. Issued 10/1/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
G-1159; T.C. A12EA	SA3223WE	Installation of Garrett AirNAV 100 or 200 area navigation system. Amended 6/1/78.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3288WE	Installation of Canadian Marconi vertical scale engine instruments. Issued 10/22/76.	WE	30000	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3302WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 9/17/76.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3370WE	Installation of dual ONTRAC III VLF/OMEGA navigation system. Issued 12/1/77.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3399WE	Installation of a single or dual Litton LTN-72R INS/RNAV navigation system. Amended 7/11/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3600WE	Installation of a single or a dual Delco C-IVA inertial navigation systems. Amended 1/30/80.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3629WE	Installation of either single LTN-51 or LTN-72. Issued 4/14/78.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
G-1159; T.C. A12EA	SA3635WE	Installation of IPECO pilot and co-pilot crew seats. Amended 6/26/79.	WE	54860	Marcon Associates, Inc. 18436 Hawthorne Blvd. Suite 212 Torrance, CA 90504
G-1159; T.C. A12EA	SA3636WE	Installation of single Delco Carousel IVA inertial navigation system. Issued 6/22/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3691WE	Installation of Devore Aviation wing tip tank tail cone mounted vertical tail floodlights. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
G-1159; T.C. A12EA	SA3973WE	Installation of equipment racks for the mounting of a radar system. Issued 6/15/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
G-1159; T.C. A12EA	SA4142SW	Door seal pressure gage, P/N 791026-1. Issued 6/16/80.	SW	08225	AirModa, Inc. P.O. Box 29034 Dallas, TX 75229
G-1159; T.C. A12EA	SA4166WE	Installation of oxygen system for passengers and third crew member. Issued 6/12/80.	WE	78490	Tiger Air Service Center 3000 North Clybourn Avenue Burbank, CA 91505
GA-7; T.C. A17SO	SA1425CE	Install King KFC-200 automatic flight control system. Issued 7/14/78.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
GA-7; T.C. A17SO	SA3235SW-D	Mitchell automatic flight system AK634 consisting of Century IV autopilot or AK634FD consisting of Century IV flight director autopilot with remote annunciator. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3236SW-D	Mitchell automatic flight system AK634 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3238SW-D	Mitchell command electric trim AK637. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

HAWKER SIDDELEY AVIATION, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
748; T.C. A24EU	SA45GL	Install AMF inverter MGH 549-1. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
748 Series 2A; T.C. A24EU	SA125GL	Installation of Plessey Company P/N 612-1-39863 ground proximity warning system. Issued 7/12/76.	GL	08140	Air Illinois, Inc. Southern Illinois Airport Carbondale, IL 62901
748 Series 2A; T.C. A24EU	SA2944WE	Installation of DeVore emblem lights on horizontal stabilizer tips. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
HELIO AIRCRAFT, LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H-250; T.C. 1A8	SA846EA	Installation of PeeKay Model 3500A amphibious floats. Issued 10/12/70.	EA	63626	PeeKay Aircraft Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
H-250; T.C. 1A8	SA867EA	Installation of Aerofab TSO C27 PeeKay Model B3500. Issued 3/19/71.	EA	29998	PeeKay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
H-250, H-295; T.C. 1A8	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
H-250, H-295; T.C. 1A8	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
H-250, H-295, H-391, H-391B, H-395, H-395B; T.C. 1A8	SA547SW	AK177 automatic pilot, AK123 lateral guidance radio coupler, and AK178 automatic trim.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-391, H-395; T.C. 1A8	SA354SO	Aft cabin door removed.	SO	27245	Vernon L. Crouch 2564 Alandale Drive Macon, GA 31201
H-250, H-295, H-391, H-395; T.C. 1A8	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
H-250, H-295, H-391, H-395; T.C. 1A8	SA1087SC	Installation of Brownline seat. Issued 7/6/79.	SO	47390	Jungle Aviation and Radio Service, Inc. P.O. Box 248 Waxhaw, NC 28173
H-250, H-295, H-391, H-395, H-395A; T.C. 1A8	SA1112WE	Sling-type passenger seat.	NW	75600	Stolairco, Inc. 6660 Perimeter Road S. Boeing Field Seattle, WA 98108
H-250, H-295, H-391, H-395, H-395A; T.C. 1A8	SA1491WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA1590CE	Modification of main spar carry-thru assembly. Issued 5/30/80.	CE	17120	Clarence H. Brent Box 486 Pittsburg, KS 66762
H250, H295, H391B, H395; T.C. 1A8	SA916SO	Installation of Cessna seat rails and seats. Issued 1/13/77.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H250, H295, H391B, H395; T.C. 1A8	SA917SO	Installation of cargo door.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA179AL	Installation of Airglas wheel skis. Amended 4/28/67.	NW	75600	Stolairco, Inc. 6660 Perimeter Road S. Boeing Field Seattle, WA 98108
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA218AL	Main gear shock strut restrictor.	AL	08125	Airglas Engineering Co., Inc P.O. Box 6107 Anchorage, AK 99502
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA234AL	Installation of Goodyear 30 x 13 x 6 main gear tires. Revised 6/30/69.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H250, H295, H395; T.C. 1A8	SA2381SW	Modification of main landing gear assembly, P/N 250-040-451, by addition of gussets at intersection of drag brace and main leg. Issued 11/15/76.	SW	30230	Dodd Engineering & Welding 3302 North Lewis Tulsa, OK 74110
H-250, H-295, H-395; T.C. 1A8	SA3247SW-D	Mitchell automatic flight system AK618 consisting of Century IIB autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-395, H-395A; T.C. 1A8	SA3244SW-D	Mitchell automatic flight system AK614, consisting of Century III autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H250, H-295, H-395, H-395A; T.C. 1A8	SA3245SW-D	Mitchell automatic flight system AK615, consisting of Century IIB autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-395, H-395A; T.C. 1A8	SA3246SW-D	Mitchell automatic flight system AK617 consisting of Century III autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-391, H-395A, H-391B, 500; T.C. 1A8, A2EA	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AF in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
H-250, H-391, H-395A, H-391B, 500; T.C. 1A8, A2EA	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 10/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
H-250, H-395A, H-395B; T.C. 1A8	SA1389CE	Install tailwheel yoke assembly to accommodate a Cleveland 600 x 6 wheel and either 600 x 6, 700 x 6 or 800 x 6 tires. Issued 12/15/77.	AL	90130	William G. Zaegel P.O. Box 3464 Anchorage, AK 99501
H-295; T.C. 1A8	SA860SW	Mitchell automatic flight system AK256 consisting of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76106
H-295; T.C. 1A8	SA1399SW	Installation of tricycle landing gear. Amended 5/17/78.	CE	42000	Helio Aircraft Limited Box 604 Pittsburg, KS 66762
Helio H-295; T.C. 1A8	SA1589CE	Increase gross weight. Issued 5/30/80.	CE	17120	Clarence H. Brent Box 486 Pittsburg, KS 66762
H-295 (USAF U-10D); T.C. 1A8	SA2136WE	Installation of Tritan amphibious float Model TA 3500. Reissued 5/24/76	NE	23370	T.M. Close Corporation Box 464 Gardner Municipal Airport Gardner, MA 01440

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
H295, H-391, H395; T.C. 1A8	SA987SO	Removal of the Leece-Neville generator and voltage regulator and installation of a JASCO alternator kit 6565-1. Amended 11/8/79.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H-295, H-391, H-395; T.C. 1A8	SA1086SO	Installation of stowable co-pilot's rudder pedals. Amended 8/30/79.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H-295, -391B; T.C. 1A8	SA2666WE	Ceconite 102 material covering of ailerons. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
H-295, H-395; T.C. 1A8	SA900WE	Installation of turbosupercharged Lycoming GO-480-F2D6 engine. Amended 5/20/70.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
H-295, H-395; T.C. 1A8	SA1592WE	Installation of automatic fuel mixture control. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
HT-295; T.C. 1A8	SA35RM	Installation of Bendix FCS-810 autopilot, a trim adapter and Bendix HSD-830 compass. Amended 3/20/78.	RM	05940	Aircraft Radio & Accessory Company, Inc. Hangar No. 1 Stapleton Int'l Airport Denver, CO 80207
H-391, H-391B, H-395, H-395A; T.C. 1A8	SA284WE	B2D autopilot. Amended October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
H-391B; T.C. 1A8	SA709WE	Ceconite 101 covering of ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
H-391B; T.C. 1A8	SA731CE	Installation of Edo 582-3430 floats.	NE	47270	Frank Joy Cape Cod Aeromarine Box 398 Orleans, MA 02653
H-391B; T.C. 1A8	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
H-391B, H-395, H-395A; T.C. 1A8	SA235AL	Installation of modified oleo shock strut.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H-391B, H-395A; T.C. 1A8	SA152AL	L J 2800 floats.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 1254 Anchorage, AK 99502
H-395; T.C. 1A8	SA125SO	Turbocharger GO-480-G1D6 engine.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
H-395; T.C. 1A8	SA156SO	Turbocharged Lycoming GO-480-G1D6 engine.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
H-395; T.C. 1A8	SA393CE	Lycoming GO-480-G1D6 engine and Hartzell HC-B3Z-20-1/101510-5 propeller.	CE	42000	Helio Aircraft Limited P.O. Box 604 Pittsburg, KS 66762
H-395; T.C. 1A8	SA490SW	Turbocharger. Reissued 4/6/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
H-395; T.C. 1A8	SA1213CE	Installation of EDO 582-3430 floats. Issued May 1976.	AL	75095	Stephens Bros. Plumbing, Inc. 7339 Arctic Boulevard Anchorage, AK 99502
H-395; T.C. 1A8	SA1467CE	Increase in maximum gross weight from 3,000 lbs. to 3,300 lbs./ modification and kit installation instructions. Issued 12/28/78.	CE	17120	Clarence H. Brent P.O. Box 486 Pittsburg, KS 66762
H-395; T.C. 1A8	SA1696WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
500; T.C. A2EA	SA104SO	Swearingen combustion monitor. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500; T.C. A2EA	SA305SO	Lycoming IO-540-C2C engines, 315A10 Rajay turbochargers and modified fuel system. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
500; T.C. A2EA	SA459CE	Models C4200A and 1800 skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
500; T.C. A2EA	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
HST-550; T.C. A4EA	SA615SW	AK213 stabilizer and AK214 pitch trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
HST-550; T.C. A4EA	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by STC SA615SW.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
269A, B, C; T.C. 4H12	SH152AWE	Installation of SKI/Hoskins Model 700801 anti-collision light system. Issued 8/18/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
269A, 269B, 269C; T.C. 4H12	SH157WE	Installation of fiberglass/aluminum baggage compartment. Issued 7/6/73.	WE	39300	Gould Engineering, Inc. Falcon Field Airport 4600 E. McKellips Road Mesa, AZ 85205
269A, 269B, 269C; T.C. 4H12	SH249WE	Installation of a searchlight kit. Issued 9/5/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4H12	SH258WE	Installation of MCT-10 mounting rack. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4H12	SH259WE	Installation of utility compartment. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269B; T.C. 4H12	SA123WE	Installation of E.O.S. 1 KW searchlight and Technical Engineering & Manufacturing Co., Inc. Model TA-30 alternator.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH128WE	Installation of Nightsun SX-10 searchlight Kit No. 019600 when: A TA-30 dual voltage alternator is installed per STC SH131WE; the helicopter is equipped with a Dovsek Model 200C or 300B light mounts, the mount's indicator light conforms to Hughes Service Information Notice #N92. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
269B, 269C; T.C. 4H12	SH131WE	Installation of EMPAC (U.S. Energy Corporation) Model TA-30 dual voltage alternator system (12 volts/ 60 amperes and 28 volts/68 amperes) in lieu of 12-volt alternator. Issued 7/7/71.	WE	80890	United State Energy Corporation 2780 Temple Avenue Long Beach, CA 90806
269B, 269C; T.C. 4H12	SH145WE	Installation of modified oil filler tube and dipstick. Issued 5/31/72.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH146WE	Installation of utility window. Issued 6/2/72.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH202WE	Installation of controls for pilot-in-command on right side. Issued 4/28/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
269B, 269C, Normal Category; T.C. 4H12	SH245WE	Installation of searchlight. Issued 7/31/79.	WE	19986	Carter Engineering Company, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
269B, 269C; T.C. 4H12 Only those rotorcraft having Hughes P/N 269A4593 or 269A8241, or 269A4593 muffler installed.	SH1138CE	Installation of engine exhaust tail pipe extension. Issued May 1975.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052
269C; T.C. 4H12	SH134WE	Installation of Spectrolab Nightsun SX-16C searchlight. Amended 3/3/75.	WE	65328	Progressive Aviaiton Limited Reid-Hillview Airport San Jose, CA 95122
269C; T.C. 4H12	SH224WE	Installation of heated pitot. Issued 9/13/78.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
269C; T.C. 4H12	SH1099CE	Installation of cabin heater and engine exhaust tail pipe extension. Issued March 1975.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052
300 Series (269C); T.C. 4H12	SH333NW	Installation of automatic flagman. Issued 10/28/76.	NW	03500	Air Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
369; T.C. H3WE	SH390NW	Installation of electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
369 Series; T.C. H3WE	SH598NW	Installation of load readout device. Issued 5/18/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
369 Series; T.C. H3WE	SH667NW	Installation of fiberglass fuel tanks under rear seat. Issued 9/15/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369 Series; T.C. H3WE	SH829NW	Installation of a weighing system. Issued 9/6/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
369, 369A, 369H, 369HM, 369HS, 369HE, 369D; T.C. H3WE	SH207WE	Installation of range extension fuel tank in cargo area of Hughes 369 series helicopters. Issued 1/10/78.	WE	68501	Robertson Aircraft, Inc. P.O. Box 968 Tempe, AZ 85281
369A, 369D, 369H; 369HE, 369HM, 369HS; T.C. H3WE	SH215WE	Installation of floodlights on fuselage. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
369A, H, HM, HE, HS; T.C. H3WE	SH358AL	Installation of Airglas L2700-369 skis. Amended 6/26/74.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369A, H, HS, HE; T.C. H3WE	SH1657SW	Full length, hard surface, skid shoes on standard skid landing gear. Issued 6/18/73.	SW	61650	Northrup Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
369D; T.C. H3WE	SH220WE	Installation of a "HCS-500D" helicopter computer system. Issued 7/28/78.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
369D; T.C. H3WE	SH246WE	Installation of ATI Model 13-0044, 13-0045 and 13-0046 speaker kits. Issued 8/17/79.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
369D; T.C. H3WE	SH654AL	Install Airglas Model L2700-369HD skis. Issued 10/24/78.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D; T.C. H3WE	SH678AL	Installation of Airglas skis. Issued 12/28/79.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D (H500D); T.C. H3WE	SH1546CE	Installation of Collins APS-841HAFCS. Issued 7/7/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
369D, 369H Series; T.C. H3WE	SH567NW	Installation of engine driven pump, tank hoses and spray nozzles for fire fighting. Issued 2/24/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369D, 369HE, 369HM, 369HS; T.C. H3WE	SH112GL	Installation of Marathon CA1700-1 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213
369D, 369HE, 369HM, 369HS; T.C. H3WE	SA123GL	Installation of SAFT 1656-1 nickel cadmium electrical storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213
369D, 369HE, 369HS; T.C. H3WE	SH236WE	Installation of searchlight. Issued 4/26/79.	WE	19986	Carter Engineering, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
369D, HE, HM, HS; T.C. H3WE	SH552NW	Installation of cargo hook electronic scale system. Issued 1/4/78.	NW	73067	Marvin A. Smith 5503 West Flowing Lake Road Snohomish, WA 98290
369D, 369H, 369HE, 369HM, 369HS; T.C. H3WE	SH183WE	Installation of turbine overtemperature warning system. Amended 4/4/77.	WE	60425	MRSC Incorporated 10959 San Diego Mission Road San Diego, CA 92108
369D, 369HE, 369HM, 369HS; T.C. H3WE	SH401GL	Installation of Ni-Cad Model No. 72639 engine lubrication system scavenge filter. Issued 4/18/80.	GL	61546	Ni-Cad, Incorporated 24800 U.S. 20 West South Bend, IN 46628
369D, HE, HM, HS; T.C. H3WE	SH958SO	Installation of SAFT 16156 nickel cadmium battery. Amended 1/17/79.	SO	69800	SAFT America, Inc. P.O. Box 1886 Valdosta, GA 31601
369D, H, HM, HS, HE; T.C. H3WE	SH1142EA	Installation of APC starter-generator, P/N 150SG111Q. Issued 4/23/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
369D, 369HE, 369HS; T.C. H3WE	SH189WE	Installation of searchlight kit. Amended 3/16/79.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
369D, 369HE, 369HS; T.C. H3WE	SH190WE	Installation of P.A. speaker kit. Amended 4/14/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH250WE	Installation of a P.A. speaker kit. Issued 9/17/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH898EA	Installation of pod type cargo container kits. Amended 11/22/78.	EA	72263	Skypods Limited P.O. Box 221 Arnprior, Ontario, Canada
369D, 369HE, 369HS; T.C. H3WE	SH1134EA	Installation of external cargo container (POD) kit. Amended 4/11/80.	EA	83757	Viking Helicopters, Ltd. P.O. Box 5104 - Station "F" Ottawa, Ontario, K2C3H4 Canada
369H; T.C. H3WE	SH184NW	Installation of Chadwick C-500 aerial spray system. Issued 5/23/75.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369H; T.C. H3WE	SH431NW	Installation of Model 500 spray system. Amended 5/9/77.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH1054EA	Installation of Garrett AiResearch environmental control system. Amended 9/8/77.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
369HE, 369HM, 369HS; T.C. H3WE	SH129WE	Installation of Chadwick C-20 auxiliary fuel systems. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH132WE	Installation of two side cargo racks P/N DMC-023-200-1. Issued 8/25/71.	NW	61798	Olympic Helicopters, Inc. 8241 Perimeter Road South Boeing Field Seattle, WA 98108
369HE, 369HM, 369HS; T.C. H3WE	SA133WE	Installation of C-75 cargo rack set, P/N 75-0000-00. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH516AL	Installation of Model L2700-369HS skis. Issued 5/1/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
369HS; T.C. H3WE	SH214WE	Installation of external neutron detector moduel and associated cockpit displays. Issued 4/18/78.	WE	31225	EG & G, Incorporated P.O. Box 1912 Las Vegas, NV 89101
369HS; T.C. H3WE	SH242NW	Installation of battery in Hughes 369HS helicopter to replace original. Issued 12/11/75.	NW	47708	Keefer Aircraft Engineer 11457 Glendale Way South Seattle, WA 98168
369HS; T.C. H3WE	SH690SO	Installation of SunAir Electronics Model ASB-60 or ASB-125 HF radio transceiver and associated system. Reissued 6/20/73.	WE	43344	Hughes Helicopters Div. of Summa Corporation Centinela & Teale Streets Culver City, CA 90230

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1121, 1121A, 1121B; T.C. A2SW	SA1434SW	Increase maximum zero fuel weight from 12,000 lbs. to 12,340 lbs. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128
1121, 1121A, 1121B; T.C. A2SW	SA1513SW	Ground air conditioner. Reissued 2/28/73.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA1879SW	Engine thrust reversers. Issued 6/7/74.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
1121, 1121A, 1121B; T.C. A2SW	SA1947SW	Fuel drain collector. Issued 1/17/75.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2203SW	Install capacitance type fuel gaging system. Reissued 3/10/78.	SW	44860	Israel Aircraft International 2025 S. Nicklas Oklahoma City, OK 73128
1121, 1121A, 1121B; T.C. A2SW	SA2389SW	Install identification and recognition lights in wings. Issued 12/8/76.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2615WE	Installation of nose wheel steering control wheel unit. Reissued April 1973.	SW	04540	Air Center, Inc. Wiley Post Airport P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2695SW	Install aircraft taxi lights on main landing gears. Issued 12/15/77.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2712SW	Modify existing TSO three-place forward facing couch. Issued 1/24/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2713SW	Install two and three-place couches (TSO 39a) side facing at right side of cabin. Issued 1/26/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2716SW	Relocation of thrust reverser hydraulic accumulator pressure gage. Issued 2/1/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2745SW	Install aft baggage compartment. Issued 4/4/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2894SW	Installation of hydraulic accumulator. Issued 1/10/79.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B, 1122; T.C. A2SW	SA927EA	Installation of Grimes three light strobe kit P/N 34-0305-1 as supplemental lighting. Issued 7/7/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
1121, 1121A, 1121B, 1123; T.C. A2SW	SA2471SW	Fabrication and installation of aircraft cabin door retainer. Issued 6/9/77.	SW	04540	Air Center, Inc. P.O. Box 32168 Okahoma City, OK 73132
1121, 1121A, 1121B, 1123; T.C. A2SW	SA3000WE	Installation of logo light assembly. Amended 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA398EA	3065 replacement nose cap radome. Amended 7/16/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA791CE	Installation of either of the following electronic synchronizer kits P/N 213521 or P/N 213517. Amended 9/28/72.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA2396SW	Fabrication and installation of aircraft positive door latch. Issued 1/14/77.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121B; T.C. A2SW	SA1805WE	Installation of ground air conditioner. Amended 7/16/69.	WE	85135	Western Commander, Inc. 8029 Woodley Avenue Van Nuys, CA 91406
1121A, 1121B; T.C. A2SW	SA1820SW	Collins MC-103 dual compass system. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1121A, 1121B; T.C. A2SW	SA1821SW	Bendix RDR-1200 weather radar. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1822SW	ADF installation - Collins DF206. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1823SW	Bendix MKA-28 marker beacon. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1824SW	Bendix RTA42A VHF communications. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1825SW	Bendix ALA-51 radio altimeter. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1826SW	Collins 621A-6 ATC transponder. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1827SW	UHF communication/ADF - Collins ARC159/DF301E. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1828SW	Bendix RNA-26F VOR/ILS system. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1829SW	Sierra tacan system. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1831SW	Pointer II emergency locator transmitter beacon. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1832SW	J.E.T. SI-2500 inverters. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 63074 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1833SW	Collins 346B-3 audio/interphone system. Issued 7/3/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1834SW	Radio racks. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1835SW	Flight inspection console structure. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1836SW	Pedestal extension. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1837SW	Seat modification. Issued 10/3/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1838SW	Standby gyro system. Issued 3/22/74.	SW	63750	Qualitron System, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1840SW	Emergency lighting. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1841SW	Ramp air conditioning. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1843SW	Interior lighting. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1844SW	Emergency locator receiver. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1849WE	Installation of United Control Speed Command System.	WE	85135	Western Commander, Inc. 8029 Woodley Avenue Van Nuys, CA 91406
1121A, 1121B; T.C. A2SW	SA2644WE	Installation of single point refueling system. Issued 2/7/73.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1121B; T.C. A2SW	SA1819SW	FCS-105 consisting of dual FD109 flight directors and AP105 autopilot. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121B; T.C. A2SW	SA1830SW	IDC altitude alerter/vertical navigation system. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121B; T.C. A2SW	SA1842SW	Electrical power system. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121B; T.C. A2SW	SA1877SW	Area navigation system. Issued 4/30/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1123; T.C. A2SW	SA956EA	Installation of Tramm battery temperature indicating system Model BT1600 and battery isolation system. Amended 8/21/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1123; T.C. A2SW	SA1566SW	Teledyne Avionics normalized angle of attack system. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128
1123; T.C. A2SW	SA2897WE	Installation of single point refueling system. Issued 6/11/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1124; T.C. A2SW	ST231GL	Installation of two Canadian Marconi CMA-734 omega navigation systems. Issued 3/24/78.	GL	02392	Aeronautical Systems, Inc. 4393 E. 17th Avenue Columbus, OH 43219
1124; T.C. A2SW	SA2058SW	Installation of Lear Siegler 23065-018-1 starter generator. Issued 11/3/78.	SW	44860	Israel Aircraft Ind. Int'l, Inc. 2025 South Nicklas Oklahoma City, OK 73128
1124; T.C. A2SW	SA4129SW	Aft fuselage spare generator ballast. Issued 5/23/80.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73123

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
KWAD COMPANY

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Pine Air Super-V; T.C. 4A29	SA222CE	Reinforce front lower carry-through section and wing attach fittings. Amended 6/2/80.	CE	47250	R.M. Jourdan & James Flanagan 11001 East 59th Street Raytown, MO 64133
Super V; T.C. A-51N, 4A29	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AF in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Super V; T.C. A-51N, 4A29	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Bay Aviation Super V; T.C. 4A29	SA454WE	Pneumatic flight control. Reissued October 1973.	SW	17490	Brttain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RO	STC Code	STC Holder
188A, 188C; T.C. 4A22	SA670WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
188A, 188C; T.C. 4A22	SA685WE	Aural warning signal when Vmo/Mmo is exceeded.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
188A, 188C; T.C. 4A22	SA686WE	Aural warning signal when Vmo/Mmo is exceeded.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
188A, 188C; T.C. 4A22	ST733SO	Installation of exterior emergency lighting system. S/Ns 1001, 1002, 1004 thru 1148 and 2001 thru 2022 only. Issued 10/20/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
188A, 188C; T.C. 4A22	ST749SO	Installation of plug type metal panels to replace the original clear plastic main cabin windows. Issued 11/24/75.	SO	56838	MCA Leasing 7216 N.W. 25th Street Miami, FL 33122
188A, 188C; T.C. 4A22	ST754SO	Installation of remote control essential A-C bus normal and alternate electrical circuit breaker system. Amended 8/9/77	SO	56838	MCA Leasing Corporation 7216 Northwest 25th Street Miami, FL 33122
188A, 188C; T.C. 4A22	ST852SO	Installation of cargo door. Issued 9/25/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
188A, 188C; T.C. 4A22	ST853SO	Installation of Sundstrand ground proximity warning system. Issued 9/26/75.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	ST885SO	Modification to a cargo configuration. Amended 2/7/78.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661037 Miami, FL 33166
188A, 188C; T.C. 4A22	SA1170WE	Cockpit voice recorder.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
188A, 188C; T.C. 4A22	SA1206WE	Beta range override control switch.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
188A, 188C; T.C. 4A22	SA1754WE	Installation of cargo doors, cargo floor and other changes. Amended 1/22/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario Int'l Airport Ontario, CA 91761
188A, 188C; T.C. 4A22	SA1982WE	Installation of luggage barrier.	WE	52860	McCulloch Properties, Inc. 2733 East Spring Street Long Beach, CA 90807
188A, 188C; T.C. 4A22	SA1984WE	Installation of inflatable slide for right rear emergency exit and for left rear service door; also International Inflatables emergency light No. 60555. Amended 6/24/71.	WE	44266	International Inflatables Co. Div. of Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
188A, 188C; T.C. 4A22	SA2187WE	Modification of inflatable slide International Inflatables emergency escape chute kit #RP 684. Amended 7/7/70.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
188A, 188C; T.C. 4A22	SA2197WE	Installation of Brownline modified cargo restraint system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
188A, 188C; T.C. 4A22	SA2301WE	Installation of emblem light. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
188A, 188C; T.C. 4A22	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 10240. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
188A, 188C; T.C. 4A22	SA2456WE	Installation of Collins Model 860E-2 and dual DME system. Amended 1/5/72.	WE	30000	DeVore Aviation Service Corp. 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
188A, 188C; T.C. 4A22	SA2559WE	Installation of H. Koch & Sons beverage cart P/N 601-710315-1 on stowage mushroom plate assembly. Amended 11/9/72.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	SA2711WE	Modification of flight station temperature control. Reissued 10/2/73.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
188A (S/N 1035 and up), 188C; T.C. 4A22	SA2889WE	Conversion of Lockheed Model 188A and 188C into all cargo configuration by installation of cargo door, cargo floor and cargo lining. Amended 8/25/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA2963WE	Increase maximum zero fuel weight to 90,000 pounds by modifying aircraft. Issued 1/29/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A, 188C; T.C. 4A22 T.C. 4A22	SA2974WE	Modification for installation of aft galley and forward galley rework. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
188A (S/N 1035 and up), 188C; T.C. 4A22	SA3059WE	Maximum landing weight substantiated to 98,102 pounds (from 95,650 pounds). Issued 10/23/75.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA3098WE	Structural modifications. Issued 10/31/75.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA3120WE	Modification consisting of installation of cargo pallet restraint system. Amended 8/12/77.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
188, 188C; T.C. 4A22	SA3141WE	Installation of AiResearch GTCP85-98, -98C or -98CK auxiliary power unit to supply starting air and 400 HZ power. Issued 4/30/76.	AL	67017	Reeve Aleutian Airways, Inc. P.O. Box 6027 Anchorage, AK 99502
188A, 188C; T.C. 4A22	SA3152WE	Installation of cargo door only. Issued 4/29/76.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA3159WE	Installation of cargo floor and interior. Issued 4/29/76.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A, 188C; T.C. 4A22	SA3675WE	Installation of Brownline cargo system P/N 46234-101. Amended 4/30/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 Lomita Blvd. Torrance, CA 90505
188B, A188B; T.C. A9CE	SA3088WE	Installation of CEDAD fender assemblies. Issued 9/5/75.	WE	20325	CEDAD Company 4700 Brooks Street Montclair, CA 91763
188C; T.C. 4A22	SA91GL	Installation of radio altimeter antenna opening and radio rack. Issued 10/29/75.	GL	65760	Quality Controlled Electronics, Inc. Willow Run Airport Ypsilanti, MI 48197
188C; T.C. 4A22	SA132CE	Overspeed warning system.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
188C; T.C. 4A22	SA707EA	Relocation of cabin window right-side from fuselage station 217-236 to fuselage station 333-352. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761.
188C; T.C. 4A22	SA708EA	Installation of opening in fuselage right hand for emergency exit between fuselage station 226 and fuselage station 253.4. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
188C; T.C. 4A22	SA709EA	Installation of floor structure and miscellaneous modifications. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
188C; T.C. 4A22	ST750SC	Installation of main cabin cargo crash barrier bulkhead. Issued 11/24/75.	SO	56838	MCA Leasing 7216 N.W. 25th Street Miami, FL 33122
188C; T.C. 4A22	SA796EA	Installation of six-seat pallet. Reissued 12/11/78.	WE	33905	Evergreen Inter'l Airlines, Inc. Marana Air Park Marana, AZ 85238
188C; T.C. 4A22	SA1081SC	Increase in fuel weight from 86,000 pounds to 92,340 pounds. Issued 6/14/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661087 Miami, FL 33166
188C; T.C. 4A22	SA1637WE	Installation of cargo door approximately 80 inches high by 144 inches long in left side of fuselage forebody.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91764
188C; T.C. 4A22	SA1779WE	Installation of Heathair AC-10194, AC-10195 pallets and Heathair AC-10196, AC-10197 nets on Lockheed electra model 188C cargo freighter. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 93031
188C; T.C. 4A22	SA2092WE	Installation of Heath 54 x 88 inch cargo pallet AC-10528-1 and net AC-10657-101. As modified per STC SA1754WE. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
188C; T.C. 4A22	SA2152WE	Installation of Heath 88 x 108 inch cargo pallet AC-10527-1 and net AC-10196-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
188C; T.C. 4A22	SA2694WE	Modification for installation of: nose and wingtip instrumentation boom provisions; research apparatus mounting provisions; dropsonde dispenser; increased breathing oxygen provisions and research electrical system. Issued 5/30/73.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
188C; T.C. 4A22	SA2695WE	Modification for installation of: nose instrumentation boom and wingtip instrumentation boom. Modification per STC SA2694WE is required prior to this modification. Issued 5/30/73.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
188C; T.C. 4A22	SA2991WE	Installation of passenger compartment interior arrangement in aft fuselage. . Issued 2/21/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188C; T.C. 4A22	SA3084WE	Installation of Collins FPC-75 ground proximity warning system computer. Amended 7/21/76.	WE	04080	Air California P.O. Box 2678 Oakland, CA 94614
188C; T.C. 4A22	SA3299WE	Modification of passenger compartment interior arrangement in aft fuselage and relocation of forward airstair to rear left-hand Type 1 exit. Issued 11/23/76.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
L-188C; T.C. 4A22	SA3618WE	Relocation of forward airstair to rear left hand type 1 exit. Issued 3/27/78.	WE	10210	American Jet Industries, Inc. 7701 Woodley Van Nuys, CA 91406
L-1011; T.C. A23WE	ST858SO	Installation of Bendix ground proximity warning system. Issued 10/20/75.	SO	29234	Delta Air Lines Atlanta Airport Atlanta, GA 30320
L-1011; T.C. A23WE	SA994CE	Installation of Inflight Motion Picture, Inc. 16 mm motion picture projection system. Amended May 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
L-1011; T.C. A23WE	SA1047SO	Installation of the Litton LTN-211 omega navigation system. Issued 2/7/79.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011; A23WE	SA1456CE	Installation of nine-abreast seating. Issued 10/31/78.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
L-1011; T.C. A23WE	SA1540CE	Installation of a Growth Industries dual cavity oven. Issued 12/11/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
L-1011; T.C. A23WE	SA1664SW	First aid portable chemical oxygen system. Issued 6/25/73.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
L-1011; T.C. A23WE	SA1689SW	Cabin attendant portable chemical oxygen system. Issued 6/25/73.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
L-1011 (193E); T.C. A23WE	SA2647WE	Installation of cocktail table in first-class lounge. Issued	WE	18390	Burns Aero Seat Company 2820 N. Hollywood Way Burbank, CA 91502
L-1011-385 Series; T.C. A23WE	SA3527WE	Installation of single or dual Litton LTN-201 omega navigation systems. Amended 3/26/79.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
L-1011-385-1; T.C. A23WE	ST752SO	Modification of main cabin passenger seating arrangement. Amended 3/22/78.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	ST831SO	Installation of food and beverage cart stowage provisions. Issued 4/30/75.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	ST851SO	Installation of Sundstrand ground proximity warning system. Issued 8/7/75.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	SA857CE	Crimsco entree cart. Amended February 1975.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
L-1011-385-1; T.C. A23WE	SA1198CE	Deactivation of flap load relief system in accordance with TWA M.C. 98686. Issued 2/1/76.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
L-1011-385-1; T.C. A23WE	SA1286CE	Installation of additional aircraft integrated data system and digital flight data recorder parameters. Amended 11/22/77.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195
L-1011-385-1; T.C. A23WE	SA1325CE	Install food and beverage service center in aft passenger. Issued May 1977.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport P.O. Box 20126 Kansas City, MO 64195
L-1011-385-1; T.C. A23WE	SA2519WE	Installation of H. Koch & Sons, Inc., food, beverage and waste cart. Amended 9/14/72.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	SA2894WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
T.C. A23WE					
L-1011-385-1; T.C. A23WE	SA3087WE	Installations of ground proximity warning system. Amended 4/27/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
L-1011-385-1; T.C. A23WE	SA3474WE	Installation of aircraft video system. Issued 12/1/77.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
L-1011-385-1; T.C. A23WE	SA3512WE	Installation of stretcher carrier, P/N 2003. Issued 3/21/78.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
L-1011-385-1; T.C. A23WE	SA3809WE	Installation of a dual Delco C-1VA INS.	WE	29125	Delco Electronics Division General Motors Corporation 6767 Hollister Avenue Goleta, CA 93017
L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15; T.C. A23WE	SA3316WE	Installation of a 16-inch coach class serving cart Model 953000-249, and 7805000-201, -203, -205, -207 in the passenger main deck coach areas and/or lower galley service areas. Amended 2/26/80.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
L-1011-385-1, L-1011-385-1-14, -15; T.C. A23WE	SA3317WE	Installation of 13-inch waste cart Model 956000-231, -233, -235, -237, -239 in passenger main deck and/or lower galley service areas. Amended 11/2/79.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1, L-1011-385-1-14, -15; T.C. A23WE	SA3709WE	A bolt-on retract actuator fitting specified by FAA sealed Aviation Hydraulics (Stellar Canoga Ind.) installed on the main landing gear outer cylinder. Issued 1/22/79.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1, L-1011-385-15; T.C. A23WE	SA1593CE	Replaces magnetic wheel TAT-EPR indicator with a solid state indicator. Issued 6/3/80.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
L-1011-385-1-15; T.C. A23WE	SA1407CE	Install Fairchild auto-annunciator system. Issued 4/3/78.	CE	79400	Trans World Airlines, Inc. Room 1-422 Kansas City Int'l Airport Kansas City, MO 64153
L-1011-385-1-15; T.C. A23WE	SA1408CE	Install Delco electronics triple C-IV inertial navigation system. Issued 4/3/78.	CE	79400	Trans World Airlines, Inc. Room 1-422 Kansas City Int'l Airport Kansas City, MO 64153
L-1011-385-1-15 (193T-Cathay Pacific Ser.)	SA3076WE	Installation of a thirteen inch cool beverage cart. Amended 10/5/79.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1-15 (1935-Saudia Series); T.C. A23WE	SA3315WE	Installation of 16-inch beverage cart Model 954000-225 in passenger main deck and/or lower galley service area. Issued 12/15/76.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1 (193K); T.C. A23WE	SA2689WE	Installation of horizontal situation indicator. Issued 5/11/73.	EU	26700	Court Line Aviation Lutton Airport Lutton, England
L-1011-385-1-193A; T.C. A23WE	SA2793WE	Cart tiedown assembly. Issued 12/20/73.	WE	48550	H. Koch & Sons Koch Road Corte Madera, CA 94925
1049 Series; T.C. 6A5	SA1-312	Replacement of laminated Sierracin cabin windows with built-up sheet metal plug.	EA	70600	Seaboard & Western Airlines JFK International Airport Jamaica, NY 11430
1049 Series; T.C. 6A5	SA1-352	Aft facing, folding, stewardess seat TECO 527A-1 at fuselage station 338.	EA	70600	Seaboard & Western Airlines JFK International Airport Jamaica, NY 11430
1049 Series; T.C. 6A5	SA4-310	Emergency radio transmitter.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94616
1049 Series; T.C. 6A5	SA4-311	Interior seating change to provide 98 cabin places.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-312	Ten man life raft stowage provisions.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-316	Emergency equipment.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-351	Modification of airplane including removal of coat closet.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA4-352	101 cabin seats and four crewmember seats.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-377	112 and 116 cabin seats and four crewmember seats.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-514	Interior modification and installation of passenger interior.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-948	Overhead emergency exit hatch between fuselage station 278.4 and 296.8 in top centerline of aircraft.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1049 Series; T.C. 6A5	SA4-1074	Seat track and other modifications.	WE	79956	Twentieth Century Aircraft 10800 Sherman Way Sun Valley, CA 91352
1049 Series; T.C. 6A5	SA4-1167	Interior modification.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1181	Passenger interior configuration.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1322	Fire proofing of main landing gear doors to comply with Airworthiness Directive 60-05-02.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1371	Passenger interior for 105 occupants.	WE	30265	Dollar Lines, Ltd. 311 California Street San Francisco, CA 94101
1049 Series; T.C. 6A5	SA4-1396	Structural reinforcements.	WE	30265	Dollar Lines, Ltd. 311 California Street San Francisco, CA 94101
1049 Series; T.C. 6A5	SA4-1474	Weather radar.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series; T.C. 6A5	SA4-1498	Interior modification.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1565	Interior arrangement for 111 occupants.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series; T.C. 6A5	SA4-1649	Increase in zero fuel weight to 108,000 pounds.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA6EA	Pallets and rollers and guide rails.	EA	31500	Eastern Rotorcraft Corp. P.O. Box 110 Doylestown, PA 18901
1049 Series; T.C. 6A5	SA36SO	Cargo loading door, floor structure, fuselage reinforcements, cargo tie-down devices, etc.	SO	11326	Robert E. Anson and L.C. Callaway, Jr. 7211 SW 52 Court Miami, FL 33101
1049 Series; T.C. 6A5	SA186WE	Interior modification to 108 passenger configuration.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series; T.C. 6A5	SA188WE	Catenary cargo restraining net at fuselage station 710 on aircraft converted to cargo configurations.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA189WE	Modification of air conditioning system for Class E cargo compartment.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA200SO	Cockpit voice recording system.	SO	34120	Eastern Air Lines, Inc. International Airport Miami, FL 33148
1049 Series; T.C. 6A5	SA219WE	Modification of 1049 M.L.G. orifice plate.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA233WE	Structural reinforcement to wing to permit operation at higher weights.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA456WE	Modification to allow operation at the following weights: takeoff - 142,100 pounds; landing - 114,500 pounds; zero fuel - 109,500 pounds.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA635WE	Single Collins 860E-1 distance measuring equipment system.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA659WE	Wing skin change.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series; T.C. 6A5	SA717WE	Single Collins 860E-1 distance measuring equipment system.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1049 Series; T.C. 6A5	SA755WE	Three 1,800-gallon KC97 fuselage tanks for carriage of petroleum fuels as cargo.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA901WE	Emergency exit lighting modification deleting the impact switch.	WE	52010	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA1143WE	Four 1800-gallon tanks.	WE	52010	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA1289WE	United Control V-557 cockpit voice recorder system.	WE	36100	The Flying Tiger Lines, Inc. 7401 World Way West Los Angeles, CA 90009
1049 Series; T.C. 6A5	SA1362WE	Collins 642C-1 cockpit voice recorder system.	WE	08170	Airlift International, Inc. International Airport San Francisco, CA 94128
1049-G-82, 1049-H-82; T.C. 6A5	SA1843WE	Installation of RCA AVQ-50 weather radar with McMillan 7161X radome and Collins 37P-4 glide slope antenna.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
1049H; T.C. 6A5	ST489SO	Installation of cargo restraining bulkhead. Issued 2/1/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
1049, 1649 Series; T.C. 6A5, 4A17	SA4-608	Engine mount core assemblies DE-643-1 on Wright TC18 Series engines.	WE	30500	Dow-Elco 1313 W. Olympic Boulevard Montebello, CA 90640
1649A; T.C. 4A17	SA4-1402	Reinforcing structure.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1649A; T.C. 4A17	SA258WE	One Type III emergency exit.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1649A; T.C. 4A17	SA259WE	Interior installation.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1649A; T.C. 4A17	SA466CE	Fairchild A-100 cockpit voice recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
1649A; T.C. 4A17	SA836WE	Hydro-Aire Mark II anti-skid braking system to reduce required landing field length.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
1649A-98; T.C. 4A17	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
1649A-98; T.C. 4A17	SA2666WE	Ceconite 102 material covering rudders and trim tabs. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329; T.C. 2A15	SA1428SW	Collins INS-61B inertial navigation system. Reissued 11/72.	CE	24250	Collins Radio Company 325 10th Avenue, S.E. Cedar Rapids, IA 52406
1329; T.C. 2A15	SA1483WE	Installation of a modified control column component.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1512SW	Model 7107 battery fault warning system. Issued 11/14/72.	SW	66500	Ray Electronics 107 Braniff Drive San Antonio, TX 78216
1329; T.C. 2A15	SA1525SW	TRAMM BT1 600 nickel cadmium battery temperature indicator. Issued 10/18/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
1329; T.C. 2A15	SA1533SW	Lear-Siegler 51528-000 solid state voltage regulator. Issued 10/31/72.	SW	17116	Kenneth J. Brenner 1124 Parkhave Drive Richardson, TX 75080
1329; T.C. 2A15	SA1537WE	Installation of control column.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Hwy. Los Angeles, CA 90045
1329; T.C. 2A15	SA1869SW	Two Hamilton Standard air cycle refrigeration units. Issued 4/18/74.	SW	34000	Executive Aircraft Service, Inc. Div. of Cooper Airmotive, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA1997SW	Continuous ignition control system. Issued 6/18/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329; T.C. 2A15	SA2978SW	Oxygen system. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329; T.C. 2A15	SA2984SW	Low oil pressure sensor switch. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329; T.C. 2A15	SA2985SW	Inverter relocation. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329; T.C. 2A15	SA2998SW	Litton LTN-72R INS/RNAV system. Issued 5/23/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329; T.C. 2A15	SA4018WE	Installation of on-board air stairs. Issued 12/6/79.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
1329; T.C. 2A15	SA4082SW	Pitot heat monitoring system. Issued 2/12/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329-23 (Jetstar); T.C. 2A15	SA1126SO	Deletion of empennage de-icing provisions - removal of empennage de-icing boots. Issued 1/9/80.	SO	52020	Lockheed - Georgia Company 86 South Cobb Drive Marietta, GA 30063
1329-23, -23A, -23D, -23E; T.C. 2A15	SA1043WE	Installation of GTCP30-92 or GTCP30-92C auxiliary power units Amended 8/13/76.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Hwy. Los Angeles, CA 90045
1329-23A; T.C. 2A15	ST240GL	Installation of Litton LTN-211 omega navigation system. Issued 5/2/78.	GL	47630	K-C Aviation, Inc. Outagamie Airport Appleton, WI 54911
1329-23A; T.C. 2A15	SA868EA	Modification of Sperry SP40C auto-pilot, installed per STC SA1664WE. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329-23A; T.C. 2A15	SA883EA	Installation of AIMS equipment. Issued 9/10/71	SO	07700	Department of the Air Force Warner Robbins Air Material Area (MMC) Robins AFB, GA 31093
1329-23A; T.C. 2A15	SA950EA	Installation of air-conditioning flood duct. Reissued 10/13/77.	EA	63275	PATS, Incorporated 9033-C Red Branch Road Columbia, MD 21045
1329-23A; T.C. 2A15	SA1596CE	Installation of electrical power generation system modification system. Issued 6/6/80.	CE	24540	Colt Electronics Co., Inc. 15301 West 109th Lenexa, KS 66219
1329-23A, -23D, -23E; T.C. 2A15	SA374CE	Installation of Symbolic Displays Twilighter Mk. III supplemental lighting system. Amended 5/29/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329-23A, -23D, -23E; T.C. 2A15	SA880EA	Installation of Solar T-62T-39 gas turbine auxiliary power unit. Amended 12/21/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
1329-23A, -23D, -23E; T.C. 2A15	SA898CE	Installation of AID battery temperature monitor and over-temperature warning system. Amended June 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Wichita, KS 67202
1329-23A, -23D, -23E, -25; T.C. 2A15	ST911SO	Installation of Bendix GPW-83 ground proximity warning system. Amended 8/3/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
1329-23A, -23D, -23E; T.D. 2A15	SA918SW	Installation of Teledyne avionics normalized angle of attack indicating system. Reissued 1/7/72.	SW	78127	Teledyne Inc. 3401 Shiloh Road Garland, TX 75040
1329-23A, -23D, -23E; T.C. 2A15	SA954EA	Installation of battery isolation system. Issued 5/4/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329-23A, -23D, -23E; T.C. 2A15	SA996EA	Installation of Shaw Aero fuel filler cap P/Ns 457-2, -266, -370, 431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
1329-23A, -23D, -23E, -25; T.C. 2A15	SA1459CE	Installation of mocrowave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
1329-23A, -23D, -23E; T.C. 2A15	SA1664WE	Installation of Sperry SP-40C auto flight control system and SPI-73B Sperry instrumentation system.	WE	74570	Sperry Flight Systems Div. Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
1329-23A, -23D, -23E; T.C. 2A15	SA1930WE	Installation of Collins Model WP-130G weather radar system. Reissued 8/4/69.	WE	24253	Collins Radio Company 9841 Airport Boulevard Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
1329-23A, -23D, -23E; T.C. 2A15	SA2603WE	Installation of single point refueling system. Amended 8/20/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-23A, -23D, -23E; T.C. 2A15	SA3207WE	Installation of Rosemount pitot/static probes. Issued 7/23/76.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3208WE	Installation of Litton LTN-104 navigation system. Issued 7/23/76.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3209WE	Installation of Collins AP-105 autopilot and FD-109 flight director. Issued 7/16/76.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3210WE	Installation of a Teledyne angle of attack system. Issued 11/19/76.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3221WE	Installation of a single point refueling system for Lockheed Jetstar airplane with AiResearch TFE731-3 engines. Amended 8/18/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-23A, -23D, -23E; T.C. 2A15	SA3268WE	Installation of a single or dual Collins 61E inertial navigation system. Amended 12/8/77.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
t) (					
1329-23A, -23D, -23E; T.C. 2A15	SA3365WE	Installation of Delco Carousel IVA inertial navigation system. Issued 6/7/77.	WE	85135	Western Commander, Inc. 16300 Dailey Drive Van Nuys, CA 91406
1329-23A, -23D, -23E; T.C. 2A15	SA3389WE	Installation of Delco C-IVA inertial navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3536WE	Installation of nickel-cadmium batteries in aircraft nose compartment. Issued 12/9/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329-23A, -23D, -23E; T.C. 2A15	SA3563WE	Installation of Eldec engine fuel flow and totalizer system. Issued 2/22/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3704WE	Installation of Litton LTN-211 Omega Navigation System. Amended 1/30/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA2943WE	Installation of recognition lights on horizontal stabilizer upper surface. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3206WE	Installation of Garrett AirNav 100 area navigation system. Amended 6/1/78.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3372WE	Installation of single or dual ONTRAC III VLF/Omega navigation systems. Amended 5/13/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3390WE	Installation of Global Model GNS-500A VLF/Omega navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3391WE	Installation of Delco C-IVA inertial navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3572WE	Installation of Sperry TERN-100 area navigation system. Issued 2/14/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -25; T.C. 2A15	SA3520WE	Installation of Sperry SPZ-500 autopilot and Sperry SPI-80/81 flight directors. Issued 11/23/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23D; T.C. 2A15	SA928EA	Installation of battery isolation circuit. Issued 7/14/72.	EA	70580	Scott Paper Company Scott Plaza Philadelphia, PA 19113
1329-23D; T.C. 2A15	SA931EA	Installation of battery isolation system. Issued 8/24/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
L1329-23E; T.C. 2A15	SA116GL	Installation of Global GNS-500A VLF/OMEGA navigation system. Amended 3/2/78.	GL	61880	Onan Corporation 1400 - 73rd Avenue, Northeast Minneapolis, MN 55432
1329-23F; T.C. 2A15	SA1989WE	Installation of United Control approach speed system, computer P/N 965-0158-001. Reissued 8/26/70.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA1049EA	Installation of seat tracks and cabin decks. Issued 6/7/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329-25; T.C. 2A15	SA1052EA	Installation of Solar gas turbine auxiliary power unit T-62T-40C. Amended 3/12/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
1329-25; T.C. 2A15	SA1056EA	Installation of a speed command of attitude and thrust system (SCAT). Amended 7/19/79.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA1581CE	Modification of aircraft to incorporate a fuel management computer. Issued 4/1/80.	CE	24540	Colt Electronics Company 15301 West 109th Street Lenexa, KS 66219
1329-25; T.C. 2A15	SA2920SO	Installation of BKM pitot heat monitor system. Issued 2/28/79.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329-25;	SA2976SW	Floor plan arrangement, floorboards and seat track. Issued 4/13/79.	SW	47632	K-C Aviaiton, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2977SW	Pressurized water system lavatory, commissary, and bar. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2979SW	Flushing toilet with outside servicing capabilities. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
1329-25; T.C. 2A15	SA2980SW	Galley component assembly. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2981SW	Baggage compartment modification aft cabin, station 547.5 to 567.0. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2982SW	Baggage compartment modification, station 240.0 to 310.0, right side. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2983SW	Cabin entry ramp, center aisle, station 284.0 to 328.0.	SW	47632	K-C Aviation 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA3297WE	Installation of GTCP 30-92C auxiliary power unit. Issued 1/21/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-25; T.C. 2A15	SA3324WE	Installation of a single point refueling system for Lockheed Jetstar airplane. Issued 1/17/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-25; T.C. 2A15	SA3371WE	Installation of Teledyne angle of attack system. Issued 3/10/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
382; T.C. A1SO	SA3793WE	Installation of Tracor 7640A ONS. Issued 2/2/79.	WE	79200	Transinternational Airlines Engineering Department P.O. Box 2504 Oakland International Airport Oakland, CA 94164
382, 382B; T.C. A1SO	ST427SO	Installation of cargo rail system Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382, 382B, 382E; T.C. A1SO	SA733CE	Installation of cargo pallets.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382, 382B, 382E, 382F, 382G; T.C. A1SO	SA1625WE	Pallet assembly provisions per FAA Sealed L.A.S. Top Drawing 4035910 as modifying aircraft with four KC-97, 1800 gallon tanks installed in accordance with STC SA889WE. Amended 2/23/77.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
382, 382B, 382E, 382G; T.C. A1SO	ST400SO	Installation of palletized cargo loading and restraint system. Amended 11/25/74.	SC	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382, 382B, 382E, 382G; T.C. A1SO	ST407SO	Installation of palletized cargo loading and restraint system. Amended 4/7/72.	SO	52020	Lockheed-Georgie Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA303AL	Installation of 4000 gallon steel tank in the cargo compartment.	AL	44045	Interior Airways, Inc. P.O. Box 3029 Fairbanks, AK 99701
382B; T.C. A1SO	SA368SO	Palletized cargo loading system. Amended 7/10/67.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA374SO	Palletized cargo loading system per Lockheed Industrial Products top assy. dwg. 256-000. Amended 7/25/69.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA1274WE	Triple seat/bunk. Amended 7/10/67.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98109
382B, 382E, 382G; T.C. A1SO	ST401SO	Installation of palletized cargo loading and restraint Amended 11/25/74.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B, 382E, 382G; T.C. A1SO	ST527SO	Installation of inplane cargo system in accordance with Aeronautical Engineers, Inc. dwgs. AE2178 & AE2178, Change "C". Reissued 2/13/73.	SO	73870	Southern Air Transport, Inc. P.O. Box 1266 International Airport Miami, FL 33148
382B, 382E, 382G; T.C. A1SO	SA569AL	Installation Collins FPC-75 ground proximity warning system. Issued 11/25/75.	AL	08488	Alaska International Air, Inc. P.O. Box 60029 Fairbanks, AK 99701

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
382E; T.C. A1SO	SA2461WE	Installation of Sorm bulk liquid cargo tank assembly SI-3100. Issued 12/17/71.	NW	73820	Sorm Industries 7999 Perimeter Road, South Seattle, WA 98108
382E; T.C. A1SO	SA3171WE	The auxiliary power unit Model GTC 85-71 located in the forward end of the left hand main landing gear wheel well fairing has been replaced by an AiResearch Gas turbine compressor Model GTCP 85-98CK(A). Issued 4/9/76.	WE	87450	World Airways, Inc. Maintenance & Engrg. Center Oakland International Airport Oakland, CA 94614
382E, 382G; T.C. A1SO	SA1156SO	Installation of dual Litton, LTN-211, Omega navigation system (ONS). Issued 7/3/80.	SO	73870	Southern Air Transport, Inc. P.O. Box 52-4093 International Airport Miami, FL 33152
382E, 382G; T.C. A1SO	SA2418WE	Installation of cargo loading system. Issued 9/29/71.	WE	70258	Saturn Airways, Inc. P.O. Box 2426 Oakland International Airport Oakland, CA 94614
382E, 382G; T.C. A1SO	SA3144WE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/9/76.	WE	68770	Rockwell International Corp. Collins Radio Group 750 S. Douglas Street El Segundo, CA 90245
382G; T.C. A1SO	ST913SO	Installation of six 24" x 36" plug type doors in cargo compartment walls. Issued 12/1/76.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G; T.C. A1SO	SA1056SO	Increase in zero fuel weight from 126,790 lbs. to 128,790 lbs. with pylon tanks on and 125,000 lbs. to 127,000 lbs. without pylon tanks. Issued 3/23/79.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G; T.C. A1SO	SA2912WE	Installation of palletized dual LTK-51 INS or dual LTN-72 INS or combination of either. Amended 9/26/74.	WE	51500	Litton Systems, Inc. Aero Product Division 21050 Burbank Blvd. Woodland Hills, CA 91364
382G; T.C. A1SO	SA2929WE	Installation of palletized dual LTK-51 or dual LTN-72 INS or combination of either. Issued 10/2/74	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91364

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MAULE AIRCRAFT CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M-4; T.C. 3A23	SA316SO	Installation of carburetor ice detector.	SO	71545	Charles B. Shivers, Jr. 8929 Valleybrook Road Birmingham, AL 35206
M-4; T.C. 3A23	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 19145 Judy Street Castro Valley, CA 94546
M-4; T.C. 3A23	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Bee Dee M-4, M-4; T.C. 3A23	SA273WE	Vacuum system 121A.	WE	40689	Harms Industries P.O. Box 3246 Inglewood, CA 90306
M-4, 4C, 4S, 4T, M-4-210, 210C, 210S, 210T; T.C. 3A23	SA222AL	Installation of L-2500A skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
M-4, M-4C, M-4S, M-4T, M-4-210, M-4-210C, -210S, -210T, M-4-220, -220C, -220S, -220T, M-4-180C, M-4-180S, M-4-180T; T.C. 3A23	SA433AL	Installation of Wilbur's tire-cushioned model 2300 skis. Amended 12/16/71.	AL	86070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4, -4C, -4S, -4T, M-4-210, -210S, -210T; T.C. 3A23	SA693SW	AK223 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
M-4, M-4-210; T.C. 3A23	SA258CE	Remove right rear door.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4, M-4-210; T.C. 3A23	SA486CE	Installation of Canadian Aircraft Products, Ltd. Model 62-2000 floats. Amended 7/20/67.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M4, M-4-210, M-4-210C; T.C. 3A23	SA690SW	Wing tips modified.	SW	34900	Harvey J. Ferguson Upper Valley Aviation, Inc. McAllen, TX 78501
M4-4C, -4S, -4T, M-4-210, -210C, -210S, -210T; T.C. 3A23 Applicable only to aircraft modified by STC SA963SW.	SA808SW	Installation of Mitchell Model AK246 omni-tracker.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M-4-210, -5-210C; T.C. 3A23	SA164AL	Installation of auxiliary cabin heater and cowl flaps. Amended 2/10/76.	AL	86070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA589CE	Installation of Fleet Manufacturing, Ltd. Model 2500 floats.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA609CE	Installation of Edo Corp. Model 248A-2440 or Model 248B440 floats. Amended.	SO	56750	Maule Aircraft Corp. Spence Air Force Base Moultrie, GA 31768
M-4-210, M-4-220, M-4; T.C. 3A23	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M-4-210C, -220C, M-5-210, -220C; T.C. 3A23	SA2931WE	Installation of plexiglas covering for two main cabin doors, right passenger door, and baggage door. Issued 9/17/74.	WE	36190	Foothill Aircraft Sales and Service 13th and Benson Upland, CA 91786
M4-220; T.C. 3A23	SA415SO	Installation of Mitchell Century II autopilot. Amended 6/26/69.	SO	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M4-220; T.C. 3A23	SA417SO	Installation of aileron stabilizer and tracker.	SO	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768
M-4-220, M-4-220C, M-4-220S, M-4-220T;	SA610CE	Installation of Edo Corp. Model 248A-2440 or Model 248B-2440 floats. Amended 9/19/69.	SO	56750	Maule Aircraft Corporation Spence Air Force Base Moultrie, GA 31768
M-5-210C, M-5-220C, M-5-235C, M-5-210TC; T.C. 3A23	SA937SO	Installation of aqua Model 2400 floats. Amended 6/20/80.	SO	22776	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
M-5-210C, M-5-235; T.C. 3A23	SA1099SO	Installation of Fiberfloat model 2400 or 2400A floats and modified wing tips. Issued May 1980.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830
M-5-235C; T.C. 3A23	SA1008WE	Installation of poly-fiber covering material of fuselage and empennage. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
M-5-235C; T.C. 3A23	SA1099SO	Installation of Fiberfloat Model 2400 floats and modified wing tips. Issued 9/4/79.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3 Series; T.C. 669	SA323SO	Solid state voltage regulator.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
DC-3 Series; T.C. 669	SA324SO	Wing flap actuated switch.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
DC-3 Series; T.C. 669	SA334EA	Janitrol heater and APU.	NE	08160	AIRKAMAN, Inc. Bradley International Airport Windsor Locks, CT 06096
DC-3 Series; T.C. 669	SA358EA	Increased capacity of divans and seat.	GL	73884	Southern Ohio Aviation Company 10600 Springboro Pike Miamisburg, OH 45342
DC-3 Series; T.C. 669	SA431EA	Stewart-Warner southwind heater.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
DC-3 Series; T.C. 669	SA604SW	Fuel flow system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
DC-3 Series; T.C. 669	ST746SO	Installation of short engine stacks. Issued 1/8/75.	SO	69242	R.W.D., Inc. P.O. Box 165 Miami, FL 33148
DC-3 Series; T.C. 669	SA881WE	Two air mixing baffles in carburetor air scoop.	WE	70632	Sears Roebuck & Company 2650 East Olympic Boulevard Los Angeles, CA 90054
DC-3 Series; T.C. 669	SA961WE	Seats and bulkhead for interior arrangement of 33 occupants.	WE	44225	International Aviation Development Corporation 542 San Ramon Valley Boulevard Danville, CA 94526
DC-3 Series: T.C. 669	SA1158WE	AVQ-75 distance measuring equipment.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
DC-3 Series; T.C. A-669	SA1485CE	Installation of fire extinguisher system for engines and/or cabin heater and/or aft fuselage baggage compartment. Issued 5/10/79.	CE	78621	Total Flood Corporation P.O. Box 12183 Overland Park, KS 66212
DC-3 Series: T.C. 669	SA1593WE	Installation of cargo containers.	NE	18200	Buker Airways, Inc. Hartness Municipal Airport Springfield, VT 05150
DC3/C-47; T.C. A-669	ST140RM	Installation of internal spray tank and wing booms. Issued 5/3/78.	RM	22220	Christler Flying Service, Inc. P.O. Box 231 Thermopolis, WY 82443
DC-3, DC-4/47; T.C. A-618, A-669	SA70GL	Installation of Norton radome kit 4067X. Amended 5/21/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
DC-3, -3A; T.C. 618, 669	SA106CE	Hoskins Model F or B wing tip and Model C or K tail lights with or without two Model 1 or 2 fuselage lights. Amended 6/20/68.	GL	42625	Hoskins, Inc. 34 North Bennett Street GEneva, IL 60134
DC-3, -3A, -3C, -3D; T.C. A-618, A-669	SA4-220	Tail wheel cover and fairing. Reissued 9/12/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3, -3A, -3C, -3D; T.C. A-618, A-669	SA4-230	Aileron gap closures. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3A, -3C, -3D; T.C. A-669	SA4-138	Engine cowling, baffles, siamese type exhaust system and modification cowl flaps for aircraft with Pratt & Whitney R-1830-92 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-151	Siamese type exhaust system. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-3A, -3C, -3D; T.C. A-669	SA4-228	Main landing gear doors, actuating system, main landing gear assist bungee, oil cooler fairing and oil cooler fixed section for aircraft with Pratt & Whitney R-1830-75, -92 or -94 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-272	Engine cowling and baffles for aircraft with Pratt & Whitney R-1830-75 or -94 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-279	Engine cowling and baffles for aircraft with Pratt & Whitney R-1830-92 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-309	Engine cowling and baffles for aircraft with Pratt & Whitney R-1830-92 engines incorporating R-1830-75 or -94 cylinders. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-780	Engine baffles on aircraft with Pratt & Whitney R-1830-92 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -3C, -3D; T.C. A-669	SA4-816	Engine baffles on aircraft with Pratt & Whitney R-1830-75 or R-1830-94 engines. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, -C-S3C4G; T.C. A-669	SA133AL	Installation of flap actuated landing gear aural warning device.	AL	67017	Reeve Aleutian Airways, Inc. P.O. Box 6027 Anchorage, AK 99502
DC-3A, -3C, -3D; T.C. A-669	SA494WE	Exhaust heat exchanger for cabin heating system. Reissued 9/27/74.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 91503
DC-3A, DC-3C; T.C. A-669	ST540SO	Installation includes: four interior overhead emergency lights powered by power supply located in forward fuselage; exterior overwing emergency light in wing fillet, one on each side, powered by power supply in aft fuselage; emergency light control switches installed in both flight and passenger compartments. Issued 6/15/73.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
DC-3A, -3C, -3D; T.C. A-669	SA4148WE	Installation of flap and landing gear aural warning system. Issued 5/8/80.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-3A, -3C, -3D; DC-4, C54-DC, C54A, B, D, E, G; DC-6, -6A, -6B; DC-7B; T.C. 669, 762, 6A4, 4A10	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
DC-3A, -3C, -3D; DC-4; DC-6A; T.C. 669, A762, 6A3	SA1744WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
DC-3C; T.C. 669	SA1-324	Installation of autosyn fuel flowmeter transmitter (Eclipse Type 9054-5A). Reissued 11/14/77.	EA	59466	Dorothy M. Miller 22[illegible] Main Street Bethlehem, PA 18017
DC-3C; T.C. A-669	SA1158SO	Installation of Fueltron fuel flow system in accordance with JARS dwg. SK-800205 entitled fuel feed line and installation of transducer on DC-3 engine (R-1830-94/75); SK-800206 entitled Fueltron III PT (ig) wiring. Issued 7/7/80	SO	47390	Jungle Aviation & Radio Service, Inc. P.O. Box 248 Waxhaw, NC 28173
Super DC-3; T.C. 6A2	SA1-14	Relocation of airspeed pitot head.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
DC-3C; T.C. 669	SA1066EA	Modification of cabin to all cargo configuration. Amended 9/11/78.	EA	09735	Alpha Airlines, Inc. JFK International Airport Hangar 14 Jamaica, NY 11430

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Super DC-3; T.C. 6A2	SA3241WE	Installation of turbopropeller Rolls-Royce Dart 510 engines, Dowty Rotol (c)R-130/4-20-4/12E propellers, and associated system and equipment modifications. Issued 8/18/76.	NE	64580	Pilgrim Aviation & Airlines, Inc. Box 1743 New London, CT 06320
Super DC-3, R4D-8, -8Z; T.C. 6A2	SA4149WE	Installation of a flap and landing gear aural warning system. Issued 5/8/80.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-3-G102, -G102A, -G103A, -202A; T.C. A-618	SA4147WE	Installation of a flap and landing aural warning system. Issued 5/8/80	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-6; T.C. A-781	SA2761WE	Interior arrangement. Issued 9/24/73.	WE	57900	Mercer Airlines 2777 Hollywood Way Burbank, CA 91505
DC-6 Series; T.C. 781, 6A3, 6A4	SA1-580	Television broadcasting equipment. Amended 2/8/66.	GL	59380	Midwest Program on Airborne Television Instruction, Inc. Memorial Center Purdue University Lafayette, IN 47901
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-41	Structure, power plant, systems and equipment modification.	GL	61700	Northwest Airlines, Inc. 1885 University Avenue St. Paul, MN 55111
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-202	Oil filter 30816A with CP-1438-0 element.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-218	Windows in fuselage.	SC	62300	Pan American World Airways, Inc. P.O. Box 817 Miami, FL 33159
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-502	Engine mount core assemblies.	WE	30500	Dow-Elco, Inc. 1313 West Olympic Boulevard Montebello, CA 90640
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-508	Bulkhead and cabin attendant seat.	WE	35723	Flight-Line Engineering 500 Densmore Encino, CA 91316
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-523	Interior modification for 85 passengers (93 total occupants).	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los ANgeles, CA 90045
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-525	Engine mount core 106-1F and 106-1J.	WE	83500	Vibration Isolation Products, Inc. 212 West Magnolia Burbank, CA 91505
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-543	112-passenger seating arrangement.	WE	39460	Great Lakes Airlines, Inc. Lockheed Air Terminal Burbank, CA 91500
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-568	Engine mount core assemblies DE1468.	WE	30500	Dow-Elco, Inc. 1313 West Olympic Boulevard Montebello, CA 90640
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-577	Aileron trim control gearing modification.	GL	80500	United Air Lines, Inc. 5959 S. Cicero Avenue Chicago, IL 60650
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-1169	Interior modifications.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-6 Series; T.C. 781, 6A3, 6A4	SA4-1311	Ceconite 101 covering of rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC-6 Series; T.C. 781, 6A3, 6A4	SA1PC	DC-7 increased power cabin superchargers.	PC	41260	Hawaiian Airlines, Inc. P.O. Box 9008 Honolulu, HI 96820
DC-6 Series; T.C. 781, 6A3, 6A4	SA12SO	Altimeter vibrators.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-6 Series; T.C. 781, 6A3, 6A4	SA21SO	Modified zero reader system.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-6 Series; T.C. 781, 6A3, 6A4	SA100NW	Installation of cargo door, 6g barrier bulkhead, and a class E cargo compartment. Issued 4/5/74.	NW	69204	Rosembalm Aviation P.O. Box 1524 Medford, OR 97501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-6 Series; T.C. 781, 6A3, 6A4	SA140EA	AMF "Unifreight MARK VI" cargo handling system.	EA	10226	American Machine & Foundry Co. Whiteford & Eden Roads York, PA 17405
DC-6 Series; T.C. 781, 6A3, 6A4	SA197SO	Cockpit voice recorder.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-6 Series; T.C. 781, 6A3, 6A4	SA229SO	B-400 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
DC-6 Series; T.C. 781, 6A3, 6A4	SA363SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-6 Series; T.C. 781, 6A3, 6A4	SA424WE	Single Federal (ITT) Type AFN3544 distance measuring equipment system.	SW	10150	American Airlines, Inc. Service Engineering Division Tulsa, OK 74151
DC-6 Series; T.C. 781, 6A3, 6A4	SA426WE	Single Federal (ITT) Type AFN3544 distance measuring equipment.	SW	10150	American Airlines, Inc. Service Engineering Division Tulsa, OK 74151
DC-6 Series; T.C. 781, 6A3, 6A4	ST528SO	Installation of cargo restraining bulkhead. Issued 2/20/74.	SC	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6 Series; T.C. 781, 6A3, 6A4	SA815WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-6 Series; T.C. 781, 6A3, 6A4	SA911WE	Interior arrangement for 87 occupants and installation of seat tracks and bulkhead.	WE	61238	National Interests, Inc. Municipal Airport Reno, NV 89501
DC-6 Series; CT.C. 781, 6A3, 6A4	SA932WE	ADI system components on Pratt & Whitney AM 83-3 and -4 engines.	WE	61237	National Interest, Inc. of Carson City, Nevada c/o Lamm Associates, Inc. International Airport Oakland, CA 94614
DC-6 Series; T.C. 781, 6A3, 6A4	SA1045WE	Door-mounted inflatable evacuation slides.	GL	80500	United Air Lines, Inc. P.O. Box 8000 O'Hare International Airport Chicago, IL 60666
DC-6 SEries; T.C. 781, 6A3, 6A4	SA1082WE	Interior arrangements.	WE	07500	AiResearch Aviation Service 6201 West Imperial Highway Los Angeles, CA 90045
DC-6 Series; T.C. 781, 6A3, 6A4	SA1148WE	Interior modifications.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-6 Series; T.C. 781, 6A3, 6A4	SA1302WE	Fairchild A100 voice recorder.	WE	85126	Western Air Lines, Inc. 6060 Avion Drive Los Angeles, CA 90052
DC-6 Series; T.C. 781, 6A3, 6A4	SA1311WE	United Data Control V557 voice recorder.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-6 Series; T.C. 781, 6A3, 6A4	SA1517WE	Interior arrangement for 97 occupants, DME installation, interior emergency lighting installation.	WE	57918	Mercer Enterprises Hollywood-Burbank Airport 2777 Hollywood Way Burbank, CA 91505
DC-6; T.C. 781	ST807SO	Installation of cargo interior and extension of lower aft cargo compartment. Reissued 1/3/75.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 480756 Miami, FL 33148
DC-6; T.C. 781	SA2994WE	Deactivation of high blower on CB-16 engines. Issued 1/4/75.	WE	57918	Mercer Enterprises Hollywood-Burbank Airport 2777 Hollywood Way Burbank, CA 91505
DC-6; T.C. 6A3, 6A4	SA1313WE	Fairchild A100 voice recorder.	WE	87430	World Air Center Oakland International Airport Oakland, CA 94614
DC-6, DC-6A (USAF C-118A), DC-6B, DC-7, -7B, -7C; T.C. 6A4, 4A10, 6A3, 785	ST484SO	Installation of cargo restraining bulkhead. Amended 2/12/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-6, DC-6A (C-118A), DC-6B; T.C. A-781, 6A3, 6A4	SA1066SO	Alternate installation of hydraulic pump utilizing existing engine drive. Issued 4/23/79.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 Northwest 57th Avenue Miami, FL 33152
DC-6, -6A (C-118A), -6B; T.C. A-791, 6A3, 6A4	SA1083SO	Installation of four Pratt & Whitney R-2800-99W engines and Hamilton Standard propellers. Issued 7/3/79.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 28426 Atlanta, GA 30328
DC-6, -6B; T.C. 781, 6A4	ST456SO	Installation of cargo restraining bulkhead. A clean and unobstructed passageway between the crew compartment and cargo compartment on the side of the bulkhead is required. Issued 4/9/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST463SO	Installation of cargo door. Issued 5/4/71.	SO	58700	Miami Aviation Corporation Hangar 102, Opa Locka Airport Opa Locka, FL 33054
DC-6, -6B; T.C. 781, 6A4	ST470SO	Installation of aft cargo door. Issued 6/22/71.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST495SO	Installation of aft cargo door. Issued 2/28/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST535SO	Installation of cargo floor. Amended 6/4/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST536SO	Installation of aft cargo door. Amended 6/16/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST555SO	Installation of rear cargo door. Issued 9/28/73.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33152
DC-6, -6B; T.C. 781, 6A4	ST595SO	Installation of exhaust system bracket. Reissued 1/6/75.	SO	02394	Aeronautical Engineering, Inc. 342 N.W. 2nd Court Dania, FL 33004
DC-6, -6B; T.C. 781, 6A4	ST597SO	Installation of aft cargo door. Amended and reissued 6/16/75.	SO	02394	Aeronautique Engineering, Inc. 342 N.E. 2nd Court Dania, FL 33004
DC-6, -6B; T.C. 781, 6A4	ST843SO	Installation of aft cargo door. Amended 6/3/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6 Series, DC-7 Series; T.C. 781, 6A3, 6A4, 4A10	SA4-328	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-329	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-330	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA76EA	Radome assembly 3016.	GL	21220	Chamberlain Aviation, Inc. 2664 Cilchrist Road Akron, OH 44309
DC-6A, DC-7B, -7BF, -7C, -7CF; T.C. 6A3, 4A10	SA470CE	Installation of Fairchild cockpit voice recorder Model A-100. Amended 3/1/67.	GL	81064	Universal Airlines, Inc. Detroit-Metropolitan Airport Inkster, MI 48141
DC-6A; T.C. 6A3	ST671SO	Installation of cargo loading/restraint system for palletized cargo. Amended 6/24/69.	SO	46000	Jet Avion Corporation 950 S.E. 8th Street Hialeah, FL 33010
DC-6A, DC-6B; T.C. 6A3	ST34GL	Remove cabin pressurization system, modify cabin air heating and ventilating system. Issued 9/24/73.	GL	90135	Zantop International Airlines, Inc. Willow Run Airport Ypsilanti, MI 48197
DC-6A (C-118A), DC-6B; T.C. 6A3, 6A4	ST964SO	Installation of cargo interior, installation of cargo restraint and modification of pressurization system. Amended 10/17/78.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 480756 Miami, FL 33148

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-6A, DC-6B, USAF C-118A (DC-6A); T.C. 6A4, 6A3	ST974SO	Installation of extra crew seating and air distribution system. Issued 3/29/78.	SO	15410	Bellomy - Lawson Aviation, Inc. P.O. Box 522760 Miami, FI 33152
DC-6A, USAF C-118A, Navy R6D-1, DC-63, R6D-1Z; T.C. 6A3	ST981SO	Deactivation of the cabin pressurization system, conversion of the cargo compartment to a class "E" compartment, and modification of the ventilation. Amended 10/10/79.	SC	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
DC-6A/C-118A; T.C. 6A3	SA1506CE	Engine driven cabin air compressors and associated cabin pressurization controls removed. Amended 4/8/80.	CE	64292	Petroleum Air Transport, Inc. P.O. Box 187 Hazlewood, MO 63042
DC-6A, DC-6B; T.C. 6A3	SA1363WE	Installation of Fairchild Industrial Products Model A100 cockpit voice recorder system. Amended 4/30/68.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 2426 Oakland International Airport Oakland, CA 94614
C-118A; T.C. 6A3	SA770SO	Installation of cargo pallet and container loading and restraint system. Issued 4/12/79.	SO	02390	Aeronautica Engineers, Inc. P.O. Box 661027 Miami, FL 33166
R6D-1; T.C. 6A3	SA3406WE	Modification of oxygen system including addition of supply bottle, pressure relief valve, and microphone in smoke masks. Issued 5/19/77.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-6B; T.C. 6A4	ST454SO	Installation of aft cargo door. Issued 3/1/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST514SO	Installation of forward cargo door. Amended 2/12/75.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6B; T.C. 6A4	ST523SO	Installation of forward cargo door. Amended 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST529SO	Installation of cargo floor. Reissued 3/12/73.	SO	08368	Airtech Service, Inc. P.O. Box 516 Miami, FL 33148
DC-6B; T.C. 6A4	ST532SO	Installation of main cabin compartment. Issued 3/27/73.	SC	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST553SO	Installation of cargo floor. Issued 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST729SO	Removal of pressurization and cabin cooling systems. Issued 7/10/72.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6B; T.C. 6A4	SA1434WE	Installation of modified DC-7 type cargo loading system.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 426 Oakland International Airport Oakland, CA 94914
DC-6B; T.C. 6A4	SA1457WE	Installation on auxiliary power unit in fuselage.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport AVenue Santa Monica, CA 90405
DC-6B; T.C. 6A4	SA1510CE	Engine driven cabin air compressors and associated cabin pressurization controls removed. Amended 4/8/80.	CE	64292	Petroleum Air Transport, Inc. P.O. Box 187 Hazelwood, MO 63042
DC-6B; T.C. 6A4	SA1604SW	Aft cargo door between F.S. 661 and F.S. 801. Issued 2/13/73.	SW	08351	Air Services, Inc. P.O. Box 2 Addison, TX 75001
DC-6B Cargo; T.C. 6A4	SA1663WE	MOdification of DC-6B cargo aircraft to incorporate passenger or combination passenger/cargo arrangements.	WE	25970	Continental Airlines Los Angeles International Airport Los Angeles, CA 90009
DC-6B Cargo; T.C. 6A4	SA1765WE	Installation of cargo bulkhead, crew lavatory, vanity, galley and tunk.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-6B; T.C. 6A4	SA2721WE	Install external retardant tank. Amended 10/5/77.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-6B; T.C. 6A4	SA2861WE	Installation of rear cargo door system GA61104. Issued 4/4/74.	SW	37093	Gary Aircraft Corporation P.O. Box 3486 San Antonio, TX 78211
DC-7 Series; T.C. 4A10	SA1-25	Substitution of rotating discs 9531691 and 9531704 in 9560285 and 9560286 brake assemblies.	GL	39011	Goodyear Aircraft Corporation Akron, OH 44309
DC-7 Series; T.C. 4A10	SA3-311	Wheels 150741-1 and/or 150741-5 and brake assembly 150835-5.	GL	15500	Bendix Aviation Corporation 401 North Bendix Drive South Bend, IN 46600
DC-7 Series; T.C. 4A10	SA4-54	Passenger/cargo interior arrangement configurations.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-91	One 4-piece divan left-hand side inboard facing and one 2-place divan right-hand side aft facing from Station 891 aft to pressure dome.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-124	Station 122 bulkhead.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-255	Aft cabin lounge.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-355	Interior modification coach to mixed class.	WE	07500	AiResearch AVviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-405	Interior modification to mixed class.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-442	Modification of communication equipment to provide navigator station.	SW	10150	American Airlines, Inc. Municipal Airport Tulsa, OK 74101
DC-7 Series; T.C. 4A10	SA4-507	Deterjet DJ1025 valve in place of Wright torquemeter booster pump upper housing per STC SEW-10.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-608	Engine mount core assemblies DE-643-1 on Wright TC18 series engines.	WE	30500	Dow-Elco, Inc. 1313 West Olympic Boulevard Montebello, CA 90640
DC-7 Series; T.C. 4A10	SA10SO	Provisioned for installation of 10,000 pound military pallet.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-7 Series; T.C. 4A10	SA23SO	Observer's seat fuselage Station 55.	SC	68130	Riddle Airlines P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA30SO	Two emergency exits at stations 437.9 - 460.5 from Type IV to Type III modified.	SO	68130	Riddle Airlines, Inc. P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA35SC	Access hole in horizontal stabilizer.	SO	68130	Riddle Airlines, Inc. P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA89SC	Oil separator B-300-1.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
DC-7 Series; T.C. 4A10	SA103WE	Interior arrangement for 104 passengers.	EA	19640	Camaero, Inc. Room 2004 27 Wall Street New York, NY 10005
DC-7 Series; T.C. 4A10	SA176NW	Installation of Fairchild Andover Model 204 auxiliary power unit for ground use only.	NW	18700	Butler Aircraft Company P.O. Box 338 Redmond, OR 97756
DC-7 Series; T.C. 4A10	SA188EA	Cabin interior modifications.	EA	80923	United States Overseas Airlines P.O. Box 234 Wildwood, NJ 08260
DC-7 Series; T.C. 4A10	SA214WE	Passenger interior arrangements and cargo interior.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. California Avenue Burbank, CA 91505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-7 Series; T.C. 4A10	SA294WE	Door in floor for cabin access.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA314WE	Passenger interior arrangements and cargo interior for operation of aircraft at 106,400 pounds zero fuel weight.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 North Clybourn Avenue Burbank, CA 91505
DC-7 Series; T.C. 4A10	SA364SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l. Airport Atlanta, GA 30320
DC-7 Series; T.C. 4A10	SA365EA	All weather landing system.	EA	74574	Sperry Gyroscope Company 2221 Smithtown Avenue Ronkonkoma, NY 11779
DC-7 Series; T.C. 4A10	SA425WE	Single Federal (ITT) Type AFN3544 distance measuring equipment system.	SW	10150	American Airlines, Inc. Service Engineering Division Tulsa, OK 74151
DC-7 Series; T.C. 4A10	SA493SW	104-passenger interior arrangement.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
DC-7 Series; T.C. 4A10	SA500EA	Installation of microvision operational all-weather landing system.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
DC-7 Series; T.C. 4A10	SA588WE	Ceconite 101 covering of rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC-7 Series; T.C. 4A10	SA600SO	Cockpit voice recording system.	SO	08170	Airlift International, Inc. P.O. Box 335 Miami, FL 33148
DC-7 Series; T.C. 4A10	SA602WE	99-passenger interior arrangement modification including floor structure.	WE	05370	Aircraft Investors Hangar 28, Oakland Airport Oakland, CA 94614
DC-7 Series; T.C. 4A10	SA656WE	Interior modification for 98 occupants.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA724WE	Interior arrangement modification for 89 and 99 passengers and installation of modified navigator's seat.	WE	44188	International Aerodyne, Inc. 11319 Vanowen Street North Hollywood, CA 91603
DC-7 Series; T.C. 4A10	SA796WE	Wing flap attachments modification.	WE	30400	Douglas Aircraft Company, Inc. 3855 Lakewood Boulevard Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1068WE	Interior arrangement.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1075WE	AVQ9 radar altimeter, APN9 Loran receiver, AT144 HF transmitter and AR144 HF receiver.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1361WE	Fairchild Industrial Products Model A100, cockpit voice recorder system.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 2426 Oakland International Airport Oakland, CA 94614
DC-7, -7B, -7C; T.C. 4A10	SA2709WE	Installation of 3,000 gallon external retardant tanks under fuselage at wing center section. Amended 6/17/80.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-7, -7B, -7C; T.C. 4A10	SA3015WE	Installation of LH and RH upper viewing windows above side cockpit windows. Amended 6/17/75.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-7B; T.C. 4A10	ST631SO	Installation of loading and restraint system for palletized cargo. Amended 9/12/68.	SO	46000	Jet Avion Corporation 950 SE 8th Street Hialeah, FL 33010
DC-7B; T.C. 4A10	ST651SO	Installation of cargo transportation pallet and new assemblies (Heath Techna P/N AC-10195) pallet w/AC 10197 net, or AC-10194 pallet w/AC-10196 net.	NW	41625	Heath Techna Corporation 19819 84th Avenue Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-7CF: T.C. 4A10	SA469CE	Fairchild A-100 cockpit voice recorder.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul International Airport St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA1-599	Gables Engineering G-1010A instrument failure warning system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA1-601	Crimsco cargo container 6003 utilizing 6004 adapter in passenger compartment. Amended 5/3/67.	EA	62300	Pan American World Airways, Inc. 135 East 42nd Street New York, NY 10001
DC-8 Series; T.C. 4A25	SA3-603	Equipment furnishings, cargo provisions, forward cargo cabin DC-8.	GL	61700	Northwest Airlines, Inc. 1885 University Avenue St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA3-666	Aft cabin bin substituted for three 3-place left-hand tourist passenger seats between Stations 1253 to 1360.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul International Airport St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA4-918	Waste King flight data recorder 5424.	GL	80500	United Air Lines, Inc. 5959 South Cicero Avenue Chicago, IL 60650
DC-8 Series; T.C. 4A25	SA4-1026	Forward lounge.	WE	18390	Burns Aero Seat Company, Inc. 3900 Cohasset Street Burbank, CA 91502
DC-8 Series; T.C. 4A25	SA45SC	M6861-100 life rafts. Amended 5/8/67.	SC	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA52SO	6924-100 life rafts.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA55SO	B-500-2 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
DC-8 Series; T.C. 4A25	SA69EA	Brown line 21105-51 stretcher kit in passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 East 42nd Street New York, NY 10001
DC-8 Series; T.C. 4A25	SA70SC	Deactivation of center wing and forward auxiliary fuel tanks.	SO	61220	National Airlines, Inc. International Airport Miami, FL 33159
DC-8 Series; T.C. 4A25	SA77EA	SP-30 autopilot modification to allow manual pitch operation while maintaining automatic roll and yaw control.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA94SO	WN233-102 and WN333-101 passenger seats.	SO	02800	Aerosmith Products Corporation 6940 SW 12th Street Miami, FL 33144
DC-8 Series; T.C. 4A25	SA155SO	Cockpit voice recorder.	SC	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA176SO	Auxiliary galley.	SC	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA194SO	Passenger seating and cabin interior.	SO	61220	National Airlines P.O. Box 2055 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA222EA	Bendix DRA-12/CPA-24 doppler computer system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA286SO	Gables G-1340B instrument warning system.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA293EA	Tray carrier.	EA	62300	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA305EA	Inflight motion picture system provisions. Amended 10/5/67.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8 Series: T.C. 4A25	SA306SO	Forward lounge compartment configuration change.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series: T.C. 4A25	SA312EA	Aerotherm 1003 stretcher.	EA	62300	Pan American World Airways, Inc. Pan Am Building New York, NY 10017
DC-8 Series: T.C. 4A25	SA324EA	Litton LN-12 inertial navigation system and Bendix navigational computer.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, L.I., NY 11430
DC-8 Series: T.C. 4A25	SA333EA	Litton low range altimeter system and activation of altitude bar.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, L.I., NY 11430
DC-8 Series: T.C. 4A25	SA343SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l. Airport Atlanta, GA 30320
DC-8 Series: T.C. 4A25	SA350SO	Galleys 1 and 4.	SO	19846	Capitol Airways, Inc. Berry Field Nashville, TN 37202
DC-8 Series: T.C. 4A25	SA359SO	Seat belt attachment.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series: T.C. 4A25	SA370SO	Single radio altimeter.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series: T.C. 4A25	SA373SO	Installation of remote accelerometer and mount assy for DC-8 flight recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series: T.C. 4A25	SA377EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways, Inc. JFK International Airlines Jamaica, NY 11430
DC-8 Series: T.C. 4A25	SA380SO	Installation of stretcher assembly.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series: T.C. 4A25	SA445EA	Installation of cockpit voice recorder. Amended 2/27/67.	EA	62300	Seaboard World Airlines Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8 Series: T.C. 4A25	SA479WE	Cargo bins and adapters in passenger cabin.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series: T.C. 4A25	SA497EA	Installation of Inflight Motion Picture Provisions.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8 Series: T.C. 4A25	SA543EA	Cockpit voice recorder.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
DC-8 Series: T.C. 4A25	SA544WE	Interior arrangements.	WE	79200	Trans International Airlines Box 2306, Airport Station Oakland, CA 94614
DC-8 Series: T.C. 4A25	SA545WE	Interior arrangements.	WE	79200	Trans International Airlines Box 2306, Airport Station Oakland, CA 94614
DC-8 Series: T.C. 4A25	SA582WE	Aileron power system modification to incorporate a flexible hose.	SC	62300	Pan American World Airways, Inc. Pan Am Building Miami, FL 33159
DC-8 Series: T.C. 4A25	SA602SO	Dual Collins AL-101 radio altimeter system.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series: T.C. 4A25	SA613SO	Installation of Collins FD-109 FD-109 flight director system. Amended 12/28/67.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series: T.C. 4A25	SA833WE	Two triple seats in main cabin and associated changes.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series: T.C. 4A25	SA855WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8 Series; T.C. 4A25	SA994WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-8 Series; T.C. 4A25	SA1184WE	United Data Control cockpit voice recorder.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1220WE	Brownline pallet 23118-51 and Brownline pallet net 22672-51.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1347WE	GAlley 100 and 200 at fuselage stations 447.75 to 490, and 1385.5 to 1416.	WE	28560	Dale Engineering Company 12243 Branford Street Sun Valley, CA 91352
DC-8 Series; T.C. 4A25	SA1349WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1522WE	Substitution of Brownline cargo container assembly P/N 24026-51 for Douglas pallet assembly P/N 5776662-505 and net P/N 7778335.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airlines San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA1538WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder and Honeywell P/N 180 VI central air data computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA1796WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8 Series; T.C. 4A25	SA2318WE	Installation of emergency exit lights. Issued 3/2/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331
DC-8 and DC-8F Series; T.C. 4A25	SA1783WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8; DC-9; T.C. 4A25, A6WE	SA2538SW-D	Replacement of switch assembly, International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-8; DC-9; T.C. 4A25, A6WE	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, 104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-8, DC-9, DC-10; T.C. 4A25, A6WE, A22WE	SA2728WE	Incorporation of Holcombe Industries HI_LITE SYSTEM P/N 50-1001 for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -8F-54, -8F-55, -61, -61F, -62, -62F, -63, -63F; DC-9-11, -12, -13, -14, -15, -15F, -21, -31, -32, -32F, -41; DC-10-10; T.C. 4A25, A6WE, A22WE	SA10GL	Installation of Gayston Model 800LG and 800SC static dischargers on transport category airplanes. Issued 12/15/72.	GL	37125	Gayston Corporation 55 Janney Road Dayton, OH 45404
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, -61, -61F, -62, -62F, -63, -63F, DC-8F-54, -55; T.C. 4A25	SA928WE	Installation of replacement safety belt assemblies. Amended 10/9/74.	WE	68725	Rocket Jet/ARD Division American Safety Flight Systems, Inc. 1311 Grand Central Avenue Glendale, CA 91201
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, F-54, F-55; T.C. 4A25	SA1063SO	Installation of forward cargo door. Issued 4/6/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, -61, -61F, -62, -62F, -63, -63F, DC8F-54/55; T.C. 4A25	SA2539WE	Installation of emblem light. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-8-12, -21, -33, -51, -52; T.C. 4A25	SA228EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 - 148th Avenue Jamaica, NY 11434
DC-8, -12, -21, -31, -32, -33, -52; T.C. 4A25	SA676CE	Installation of Crimsco cargo container, P/N 600301, utilizing Model 6004 adapter in passenger compartment.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
DC-8-20, -30, -40, -50 Series; T.C. 4A25	SA266GL	Installation of Litton LTN-211 Omega navigation system. Amended 4/26/79.	GL	61788	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-20/50; T.C. 4A25	SA3030WE-D	Install a carry-on baggage module. Issued 9/7/76.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Airport San Francisco, CA 94128
DC-8-21; T.C. 4A25	SA3869WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 2/20/79.	WE	66405	G. S. Rasmussen P. O. Box 10519 Glendale, CA 91209
DC-8-21, DC-8-51; T.C. 4A25	ST449SO	Installation of air data computer with altitude display, altitude reporting, and altitude alerting capabilities. Issued 12/30/70.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, DC-8-51; T.C. 4A25	ST670SO	Installation of International Inflatables Co. P/N 68035 door-mounted emergency evacuation slide at forward entrance door and service door and International Inflatables Co. P/N 68085-3 door mounted emergency evacuation slide at aft entrance and service doors. Amended 10/6/69.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, -32, -51; T.C. 4A25	ST680SO	Installation of Pan Avion Model LSR-210 and LSR-273 emergency evacuation slides and Pan Avion slide pack containers P/N 017-33 and P/N 017-34 at forward and aft passenger entry and service doors.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -54, -55; T.C. 4A25	ST844SO	Installation of cargo interior. Amended 5/8/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, DC-8F-54, -55; T.C. 4A25	SA915SW	Installation of Bendix P/N 19E138-2A flexible drive shaft in lieu of Dana P/N 26567 universal joint shaft on Pratt & Whitney Model JT3D-1 engine gear box and C.S.D. Amended 10/1/71.	EA	16000	The Bendix Corporation Fluid Power Division 211 Seward Avenue Utica, NY 13503
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1033WE	Either single or dual Collins AL-101 radio altimeter systems. Amended 11/19/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airlines San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1034WE	Installation control and annuciation circuitry to implement Flight Director "Go-Around" command modes. Amended 4/1/68.	WE	80500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -54, -55; T.C. 4A25	SA1088SO	Installation of a cargo interior. Issued 7/11/79.	SW	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1405WE	Structural installation of Dorne and Margolin DMC 33-2 Satcom VHF radic antenna.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -32, -51, -61; T.C. 4A25	SA1980WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	FG	STC Code	STC Holder
DC-8, -8-21, -31, -33, -51, -52, -54F, -61, -62; T.C. 4A25	SA2211WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-21, -52; T.C. 4A25	SA2316WE	Revised interior arrangement to an all-tourist, 149-passenger configuration. Amended 5/23/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -51, DC-9 Series; T.C. 4A25, A6WE	SA2405WE	Installation of PICO Division pressure regulator P/N 3001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
DC-8-21, -31, -33, -51, -52; T.C. 4A25	SA2573WE	Installation of interior modifications. Amended 3/6/74.	WE	80500	United Air Lines, Inc. Maintenance Base Engineering Department San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -8F-54, -8-61, -61F, -62, -63, -63F; T.C. 4A25	SA2827WE-D	Installation of Collins FPC-75 P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -51, -52; T.C. 4A25	SA3033WE-D	Revise interior arrangement to increase coach seating. Amended 6/3/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -33, -51, -52, -61, -62, DC-8F-54; T.C. 4A25	SA3189WE	Installation of UAL MLG orifice support tube assembly, P/N 6F13540-501 and -502. Issued 10/4/77.	WE	80500	United Air Lines San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-33; T.C. 4A25	SA260NW	Modification of pax airplane configuration to cargo configuration (bulk). Issued 2/17/76.	NW	69204	Rosenbalm Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	ST266GL	Installation of a Litton LTN 211 Omega navigation system. Issued 8/25/78.	GL	61798	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA289GL	Load palletized livestock as bulk cargo. Issued 12/22/78.	GL	44036	InterContinental Airways, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA421NW	Cargo modification as done under STC's SA207NW and SA260NW and SA324NW. Issued 3/15/77.	NW	69204	Rosenbalm Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	SA2036WE	Installation of Henry Windscreen Model No. 48102. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8-33; T.C. 4A25	SA2825WE-D	Revise interior arrangement to accommodate all coach, 186 passenger overwater configuration. Amended 4/3/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-33; T.C. 4A25	SA3403WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo handling system, and increasing maximum landing and zero fuel weight. Amended 6/14/78.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846
DC-8-33; T.C. 4A25	SA3611WE	Modification to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2057 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3804WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/13/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3907WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-33; T.C. 4A25	SA3910WE	Modifications to permit an increase in maximum allowable zero fuel weight.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3612WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3749WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo floor, and increasing maximum landing and zero fuel weight. Issued 9/28/78.	WE	52995	McDonnell Douglas Corp. 3855 Lakewood Boulevard Long Beach, CA 90846
DC-8-43; T.C. 4A25	SA3805WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3880WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 3/28/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3911WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43, -53; T.C. 4A25	SA2681WE	Installation of enclosed overhead stowage bins, sculptured ceiling panels, with integral lighting, improved sidewall lighting, and revised passenger service units. Issued 4/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-50, -60; T.C. 4A25	SA3963WE	Installation of dual Global GNS-500A VLF/Omega navigation systems. Issued 5/23/79.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
DC-8-51; T.C. 4A25	SA1768WE	Installation of stewardess seat Model 6878 on Nordskog galley Model 305A.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-51; T.C. 4A25	SA4078WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 2/6/80.	WE	66405	G. S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-51, -52; T.C. 4A25	SA2835WE-D	Installation of enclosed overhead stowage compartments, improved ceiling and sidewall lighting, relocation of motion picture projector compartments and complete cabin refurbishment. Issued 4/30/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-51, -52, -8F-54, -8-61; T.C. 4A25	SA3357WE-D	Retrofit of fuel quantity indicators and totalizers, Gull Airborne Instruments, Inc. P/Ns 206-009 and 206-016 series. Issued 1/30/78.	WE	80500	United Air Lines San Francisco Int'l Airport San Francisco, CA 91406
DC-8-51, -61; T.C. 4A25	ST857SO	Installation of Bendix ground proximity warning system. Amended 11/14/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8-52; T.C. 4A25	SA448NW	Installation of new look interior conversion kit for Aviaco Air Lines.	NW	41625	Heath Tecna Corporation 19819 - 84th Avenue, South Kent, WA 98031
DC-8-52; T.C. 4A25	SA3945WE-D	Installation of a DC-8-51 landing gear on DC-8-52 airplane. Issued 6/9/80.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-53; T.C. 4A25	SA3613WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3806WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3908WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209

Aircraft Make, Model & T.C. No.	STC No.	Description	RC	STC Code	STC Holder
DC-8-53; T.C. 4A25	SA3909WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3912WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8F; T.C. 4A25	SA605EA	Installation of pallet P/N 6524 incorporating Douglas cargo loading system or pallet P/N 6524 must use nets and be loaded in accordance with Douglas pallet P/N 5776662-505 instructions.	EA	66470	Ray. Daisley Co., Inc. 585 West Hoffman Avenue Lindenhurst, NY 11757
DC-8F-54; T.C. 4A25	SA633CE	Make and install cargo pallets in accordance with Brooks & Perkins Drawing List No. 16987. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	ST677SO	Installation of Nordskog galley Models 376, 377, 378 and 379 at right hand galley positions 1, 2, 3, and 4.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST684SO	Interior conversion of passenger cabin to accommodate 24 first class and 105 tourist class passengers. Amended 1/8/70.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST747SO	Installation of livestock transportation pens. Issued 1/31/75.	SO	21560	Casco Division Charlotte Aircraft Corporation P.O. Box 481225 Miami, FL 33148
DC-8F-54; T.C. 4A25	SA804EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8F-54; T.C. 4A25	SA813CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA843CE	Installation of cargo-pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA1793WE	Installation of Heathair AC-0152-1 structural container in DC-8F-54 aircraft equipped with cargo loading system No. 7778202-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54; T.C. 4A25	SA1991WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, -52; 22672-51, -52; or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54; T.C. 4A25	SA1997WE	Installation of Brownline pallet assembly P/N 40309 and net assembly Brownline P/N 21350-51, 21710-51, -52, Douglas P/N 7776431-1 or 7776431-501. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54; T.C. 4A25	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1 or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
DC-8F-54; T.C. 4A25	SA2255WE	Installation of Satco, Inc. pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8F-54; T.C. 4A25	SA2274WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8F-54; T.C. 4A25	SA2745WE-D	This modification provides seats, oxygen, cockpit communications, emergency equipment and other items necessary to carry six couriers or other persons authorized aft of Station 1370. Issued 4/22/78.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54; T.C. 4A25	SA3586WE-D	Installation of a removable dual Delco C-IV inertial navigation system for navigation only. Issued 10/27/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54, -55; T.C. 4A25	SA697CE	Installation of Aeroquip Corp. cargo tie-down net.	CL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203
DC-8F-54, -55; T.C. 4A25	SA1623WE	Installation of Heath 88 x 125-inch cargo pallet P/N AC-10061-1 and cargo net P/N AC-10069-1 on subject models equipped with McDonnell Douglas cargo loading system No. 7776939. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1665WE	Installation of Heath Tecna 88 x 125-inch cargo pallet, P/N AC-10160 and net P/N AC-10069. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1875WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517 with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks and Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2234WE	Installation of Brownline Division Division structural container 41342-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2278WE	Installation of Brownline cargo container Model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-F54, -8-55 Series; T.C. 4A25	SA2137WE	Installation of Litton inertial navigation system(s) LTN51 (dual or single) or LTN72 (dual or single). Amended 12/14/78.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
DC-8F-54, -8-55; T.C. 4A25	SA4088WE	Installation of single or dual Litton LTN-72 INS. Issued 1/30/80.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
DC-8F-54, -8F-55, -8-61F, -62F, -63F; T.C. 4A25	SA1807WE	Installation of Brownline pallets and nets. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-61F, -8-63F; T.C. 4A25	SA2098WE	Modification by installation of structural cargo container 40619-101 and -102. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA1812WE	Installation of Heath Tecna 88 x 125-inch cargo pallets P/N AC-10355-1 and AC-10366-1 and net P/N AC-10357-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA2114WE	Installation of Brownline cargo container Model 40622. Amended 5/16/75.	WE	79500	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F, -9-32F, -33F; T.C. 4A25, A6WE	SA2152WE	Installation of Heath 88 x 108-inch cargo pallet AC-10527-1 and net AC-10196-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031

Aircraft Make, Model & T.C. No.	STC No.	Description	FG	STC Code	STC Holder
DC-8F-54, -8-62F; T.C. 4A25	SA1974WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and Brownline net assembly P/N 22672-51, 22672-52, 23143-51, 40657, 40850, 40517, 22273-51, 22758-51, 22758-52; Douglas net assembly P/N 7776967-1 or Aeroquip net assembly P/N 3950020. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55; T.C. 4A25	SA672EA	Installation of two place courier seat, lavatory compartment and smoke curtain.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8F-55; T.C. 4A25	SA1395WE	Substitution of Brownline pallet P/N 23640-51 and P/N 23224-51 for Douglas pallet P/N 5776662-505.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-55, -8-61F; T.C. 4A25	SA1764WE	Installation of Heathair pallet Model AC10194 and net Model AC-10196. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8F-55, -61F, -63F; T.C. 4A25	SA1028EA	Installation of Collins FPC-75 ground proximity warning system. Amended 6/22/76.	EA	70600	Seaboard World Airlines, Inc. Seaboard World Building JFK International Airport Jamaica, NY 11430
DC-8F-55, -8-62F; T.C. 4A25	SA2059WE	Installation of 88 x 125-inch cargo pallet P/N 24076-51, 88 x 108-inch pallets P/N 40309101 and 40309102, and 88 x 53-inch pallets P/N 40464101 and 40464102 with net assemblies 22361-51, 22364-51, 22758-51, 22273-51, 21530-51, 21710-51, -52, and 21869-51. Amended 10/12/70.	WE	17749	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55, -8-63F; T.C. 4A25	SA589EA	Installation of dual omnitrac navigation system. Amended 7/19/68.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8F-55, -8-63F; T.C. 4A25	SA675EA	Installation of L. Marino cargo net. Amended 3/31/70.	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
DC-8F-55, -8-63F; T.C. 4A25	SA725EA	DC-8F pallet P/N LM1600 (1.50 Fwd), DC-8-63F pallet P/N LM1600 (1.50 Fwd).	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
DC-8F-55, -8-63F; T.C. 4A25	SA2218WE	Installation of Satco cargo pallet P/N 31 80-501, NAS classification 3610-2A3P and P/N 31076-501, NAS classification 3610-2A1P with cargo nets Brownline P/N 22758-51, -52, -54, 22672-52, 22273-51, 23226-51, 40517-101; Heath Tecna P/N AC 10292-1; Marino P/N LM 1500-100; and ANCRA Corp. P/N 40178-10. Amended 10/12/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8-61; T.C. 4A25	SA467EA	Inflight Motion Picture provisions. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-61; T.C. 4A25	SA1400WE	Installation of 198-passenger interior arrangement. Amended 4/17/74.	GL	80500	United Air Lines, Inc. Executive Offices 1200 Algonquin Road Elk Grove Township, IL 60007
DC-8-61; T.C. 4A25	SA1926WE	Dual installation of A.C. Electronics Carousel IV INS units. Amended 1/16/70.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2128WE	Installation of RCA Model AVQ-30C weather radar system.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2558WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other interior changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2674WE	Revised interior arrangement. Issued 3/23/73.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94158

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-61; T.C. 4A25	SA2739WE-D	Revised seating configuration. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2741WE-D	Installation of equipment to provide guidance to flight director and SP-30AL autopilot to conduct two-segment approaches. Amended 4/7/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2804WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 3/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61; T.C. 4A25	SA2824WE-D	Installation of dual Delco C-IV inertial navigation systems. Issued 1/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3032WE-D	Install carry-on baggage module in place of one first class seat assembly. Amended 12/27/76.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3038WE-D	Installation of dual Collins FD-109 flight director system. Issued 5/24/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3039WE-D	Installs galley units and all supporting structure including plumbing and wiring at three locations. Amended 8/19/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3040WE-D	Installation of cabin new look, cabin refurbishment, inflight entertainment installation, passenger seat procurement and rework, and internal partitions and stowage cabinet. Issued 6/11/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61;	SA3356WE-D	Revise interior arrangement to accommodate dual class, 12 first class and 177 coach passenger configuration. Issued 11/4/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3582WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3587WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 12/14/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3588WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 1/5/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3593WE-D	Seat mix change from 26 F/C and 156 coach passenger configuration to 26 F/C and 164 coach passenger configuration. Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC8-61; T.C. 4A25	SA3943WE-D	Rework of high-frequency communications system to install single-sideband capability. Issued 5/16/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA4091WE	Deletion of a pair of excess Type 1 exits at station 1124. Issued 1/22/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61, -61F, DC-8-63, -63F; T.C. 4A25	SA1873WE	Installation of Litton Systems dual LTN-51 or ITN-52 inertial navigation systems. Amended 1/4/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61, -62, -62F; T.C. 4A25	SA1006EA	Installation of cabin interior furnishings. Amended 8/26/77.	EA	12500	Atlantic Aviation Corporation Greater Wilmington Airport P.O. Box 1709 Wilmington, DE 19899

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-61, -63; T.C. 4A25	SA1096SC	Installation of Tracor, Inc. omega navigation systems. Issued 8/23/79.	SO	19848	Capitol International Airways, Inc. P.O. Box 325 Smyrna, TN 37167
DC-8-61F; T.C. 4A25	ST687SO	Installation of AIF class divider partitions, left hand and right hand assembly, P/N 32012 with header assembly, P/N 32013.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-61F; T.C. 4A25	SA2157WE	Installation of 242 passenger seating arrangement. Issued 6/5/70.	WE	81064	Universal Airlines 401 McCormick Street San Leandro, CA 94577
DC-8-61F; T.C. 4A25	SA2481WE	Installation of Trans Com Model 1357 movie projector and screen assemblies. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
DC-8-61F; T.C. 4A25	SA3279WE	Installation of Litton ground proximity warning system computer P/N 456300-01, -202 in the provisions under STC SA1028EA. Issued 10/28/76.	WE	51500	Litton Systems, Inc. 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F; T.C. 4A25	SA2800WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Amended 3/12/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F, DC-8-63F; T.C. 4A25	SA630CE	Installation of cargo pallets. Amended 11/1/79.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8-61F, -8-63F; T.C. 4A25	SA1733WE	Installation of Nordskog seat assembly P/N 61247 with certain interior arrangements. Amended 4/12/71.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-62; T.C. 4A25	SA1959WE	Installation of movie projection system.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-8-62; T.C. 4A25	SA2299WE	Installation of third AC electronics carousel IV inertial navigation system. Issued 12/31/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2310SW	Install wheel and brake advisory system. Issued 5/17/76.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
DC-8-62; T.C. 4A25	SA2377WE	Installation of Collins Radio Company INS - 61B inertial navigation system. Amended 12/7/71.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2533WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other architectural changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2581WE	Installation of Collins Radio Company inertial navigation systems. Issued 8/23/72.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
DC-8-62; T.C. 4A25	SA2738WE-D	Revise seating arrangement to 154 passenger configuration; revise passenger service unit locations to comply with seating configuration; install class dividers and curtains. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2742WE-D	Install dual class seating arrangement (4 and 6 across). Amended 5/2/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2818WE-D	Installation of triple Delco Electronics carousel IV-A inertial navigation system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2819WE-D	Installation of Atlantic Aviation wide body kit. Issued 11/8/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-62; T.C. 4A25	SA2820WE-D	Installation of passenger entertainment and automatic announce system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2840WE-D	Install an alternate all tourist seating and galley configuration. Galley configuration was previously approved under STC SA2296WE. Amended 6/8/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2904WE	Installation of GAMMA inertial navigation system. Issued 7/2/74.	WE	71838	The Singer Company Kearfott Division 5730 West Manchester Avenue Los Angeles, CA 90045
DC-8-62; T.C. 4A25	SA3351WE-D	Installs a 181 passenger all coach cabin seating configuration.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3361WE-D	Installs a 16 first class/123 coach dual class seating configuration. Issued 1/16/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3576WE-D	Revise interior arrangement to accommodate 162 coach passenger configuration. Issued 6/2/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3584WE-D	Seat mix change from 162 passenger all coach configuration to 18F/129Y-147 passenger configuration. Amended 11/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62, -62F; T.C. 4A25	SA993EA	Installation of Inflight Motion Pictures, Inc. 16 mm. movie projection system IR4000 and screen assemblies. Amended 8/26/77.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-62F; T.C. 4A25	SA2308WE	Installation of cargo barrier net. Issued 1/27/71.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-8-62F; T.C. 4A25	SA2785WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 11/20/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-62F, DC-9-31; T.C. 4A25, A6WE	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 12/10/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
DC-8-63; T.C. 4A25	SA649SO	Installation of lounge table AIF P/N 31538-101.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-63; T.C. 4A25	ST681SO	Installation of class divider partition assembly P/N 31929-100 left hand and 31929-200 right hand at fuselage station 2900.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST682SO	Installation of lounge table assembly P/N 31928/100 right hand and P/N 31928-101 left hand at fuselage station 338.0.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST728SO	Interior modification and installation of 251 passenger service units and galley attachments to provide for 251 passenger arrangement (less seats and galleys). Issued 4/28/72.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-8-63; T.C. 4A25	ST737SO	Main cabin interior modifications. Issued 3/28/73.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-8-63; T.C. 4A25	SA750NW	Installation of Mark I interior kit. Issued 4/12/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
DC-8-63; T.C. 4A25	SA1730WE	Installation of cockpit voice recorder, seat lights, passenger service outlets, communication panel relocation, galley wiring changes, flight data recorder and vertical accelerometer, pitot tube with heater circuit, marker beacon.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-63; T.C. 4A25	SA1738WE	Modification of interior arrangement to 221 passenger Military Airlift Command configuration. Amended 11/7/68.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA1909WE	Modification of interior arrangement to provide automatic folding attendant seats at the four jet escape exits.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA2704WE-D	Installation of enclosed overhead stowage bins, sculptured ceiling panels with integral lighting, cabin refurbishment. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-63; T.C. 4A25	SA3854WE	Installation of Tracor 7640A ONS. Issued 3/21/79.	WE	79200	Transinternational Airlines P.O. Box 2504 Oakland International Airport Oakland, CA 94614
DC-8-63, -63F; T.C. 4A25	SA2154WE	Installation of triple Litton LTN-51 inertial navigation system. Amended 4/23/71.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
DC-8-63F; T.C. 4A25	SA652EA	Installation of dual Decca doppler systems, Type 72. Reissued 7/2/69.	EA	44900	I.T.T. Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
DC-8-63F; T.C. 4A25	ST766SO	Installation of double deck livestock transportation pens. Issued 11/1/77.	SO	11320	Animal Air Services, Inc. 14441 Northwest 13 Court Miami, FI 33162
DC-8-63F; T.C. 4A25	SA1039EA	Installation of animal restraint system for air shipment of livestock. Reissued 11/9/78.	EA	79304	Transmeridian Air Cargo Ltd. Stansted Airport Stansted, Essex, England
DC-8-63F; T.C. 4A25	SA1731WE	Install single Decca Model 72 doppler radar (ground speed and drift angle only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA1928WE	Installation of Heath Tecna 88 x 125-inch cargo pallet P/N AC-10065-1 with Heath Tecna net P/N AC-10292-1 or Brownline net P/N 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1950WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and net assembly P/N 22672-51, 22672-52, 22758-51, 22758-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1955WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, 22758-52, 22672-51, 22672-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1978WE	Installation of underseat baggage restraint system with certain specified seat models. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1987WE	Installation of Edo Model 144 ADF-Ioran antenna splitter.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2017WE	Installation of Decca Model 72 doppler radar (ground speed and drift meter only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2018WE	Installation of Decca Model ADL-21 Loran.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2087WE	Installation of Cargo Systems, Inc. 88 x 125-inch cargo pallet assembly 1950-90-1 with Brownline net P/N 22758-51.	WE	19890	Cargo Systems, Inc. 1040 West Hoover Orange, CA 92667

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-8-63F; T.C. 4A25	SA2113WE	Installation of two Decca Type 05 Omnitrac 2B Doppler/Loran navigation computer systems with pictorial displays.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2247WE	Installation of Lockheed Aircraft Services Company Model 250-A weight and balance computer system. Issued 10/9/70.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2259WE	Installation of Brownline pallet assembly P/N 41339 and Brownline net assembly P/N 41344. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA2287WE	Installation of Henry Engineering cargo container Model 52501. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8-63F; T.C. 4A25	SA2313WE	Installation of Kollsman "Slim Pac" altitude alerting system. 3/1/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8=63F; T.C. 4A25	SA2314WE	Revised seating arrangement to 244 passenger all tourist configuration. Issued 2/18/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2427WE	Installation of a third attitude indicator. Issued 10/15/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2465WE	Installation of dual Delco Carousel IV inertial navigation system. Issued 12/30/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2522WE	Installation of Nordskog tray carrier storage unit Model 798P. Issued 5/17/72.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-63F; T.C. 4A25	SA2604WE	Installation of Custom Products passenger type seat and flight crew glare protection curtain. Issued 10/24/72.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2616WE	Installation of Trans Com Model 1144 movie projector, screen assemblies and sound system. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
DC-8-63F; T.C. 4A25	SA2632WE	Modification of airplane to provide attitude information from INS in lieu of two vertical gyros (this modification pertains only to aircraft previously modified by STC SA2465WE). Issued 1/9/73.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2634WE	Installation of three Litton LTN-72 inertial navigation systems. Issued 1/9/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-63F; T.C. 4A25	SA2957WE	Installation of separate differential oil pressure system and associated warning light indication. Issued 12/23/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA3082WE	Installation of Satco, Inc. cargo pallet assembly, P/N 31250-521. Issued 9/3/75.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8-63F; T.C. 4A25	SA3123WE	Installation of cargo container P/N 10-1000. Amended 4/19/76.	WE	25955	Container Development 2636 North Ontario Burbank, CA 91504
DC-8-63F; T.C. 4A25	SA3176WE	Installation of Litton Aero Products digital ground proximity warning system. Issued 4/21/76.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-63F; T.C. 4A25	SA4118WE	Installation of a Winters air stair in the aft passenger entry door. Issued 6/4/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC8-63F; T.C. 4A25	SA4119WE	Installation of a Winters air stairs in the forward passenger entry door. Issued 5/29/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
DC-9 Series; T.C. A6WE	SA333SO	Beverage bar.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA335NW	Modified cabin interior kit. Issued 8/13/76.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
DC-9 Series; T.C. A6WE	ST399SO	Addition of underseat luggage restraint.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA457CE	Lockheed Aircraft service 109D flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA508CE	Installation of Safe Flight P/N 1300-33 SCAT computer in lieu of P/N 1300-32.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA520CE	Installation of airborne engine vibration monitoring system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA580EA	Installation of Collins Radio CLC Type 560F-3 area navigation system.	EA	31420	Eastern Airlines, Inc. 10 Rockefeller Plaza New York, NY 10020
DC-9 Series; T.C. A6WE	ST626SO	Removal of complete passenger accommodations; installation of cargo interior. Amended 5/13/69.	SO	34220	Fairchild Hiller Corporation Aircraft Service Division St. Augustine, FL 32084
DC-9 Series; T.C. A6WE	ST627SO	Installation of cargo accommodations. Amended 5/13/69.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
DC-9 Series; T.C. A6WE	SA640NW	Installation of deep interior rack kits. Issued 7/21/78.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
DC-9 Series; T.C. A6WE	SA727NW	Delete L.H. galley, add coatroom, add 2 auxiliary galley units at forward left and right side of cabin. Issued 2/27/79.	NW	78672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
DC-9 Series; T.C. A6WE	SA730CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA752CE	Install Bendix gyro horizon, P/N 1978130-2, and Bendix inverter, P/N 1964771-2.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA829CE	Install Butler National Corporation flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA1003SW	Modify 721B galley to 721B-1 and install.	SW	84250	Vought Aircraft Service Co. Div. of LTV Aerospace Corp. 4100 North Main Street Fort Worth, TX 76107
DC-9 Series; T.C. A6WE	SA1459WE	Interior configuration modification.	WE	16892	Bonanza Air Lines 3737 East Bonanza Way P.O. Box 12405 Phoenix, AZ 85034
DC-9 Series; T.C. A6WE	SA1784WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-9 Series; T.C. A6WE	SA1797WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-9 Series; T.C. A6WE	SA2330WE	Installation of battery-powered emergency exit lighting in tail-cone. Issued 3/29/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331
DC-9 Series; T.C. A6WE	SA2451SW	Marathon Battery Co. P/N 85-0050 six cell magnesium emergency light pack. Issued 4/20/77.	SW	54810	Marathon Battery Company 8301 Imperial Drive Waco, TX 76710

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9 Series; T.C. A6WE	SA2541WE	Installation of tail cone slide cover. Issued 6/2/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352
DC-9 Series; T.C. A6WE	SA3623WE	Installation of stretcher carrier P/N 2003. Issued 4/13/78.	WE	08205	Air Medic, Inc. 12517 Chandler Blvd. No. Hollywood, CA 91607
DC-9-10; T.C. A6WE	ST498SO	Modification of main landing gear brake stud. Issued 4/19/72.	SO	84470	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-8-10; T.C. A6WE	SA4200WE	Installation of a stall warning comparator system and AD 78-23-06 compliance for McDonnell Douglas DC-9-10 aircraft. Issued 7/25/80.	WE	78427	Texas International Airlines P.O. Box 12788 Houston, TX 77017
DC-9-10-20, -30, -40 Series; T.C. A6WE	ST699SO	Installation of International Inflatable Company Model 68 90 emergency evacuation slide modified with Pan Avion valve assembly P/N 526-43. Issued 11/9/71.	SO	62384	Pan Avion P.O. Box 213 Miami, FL 33101
DC-9-10, -20, -30, -40 Series; T.C. A6WE	SA2223WE	Installation of door mounted battery-powered emergency lights. Amended 5/6/71.	WE	44266	International Inflatables Company 9880 San Fernando Boulevard Pacoima, CA 91331
DC-9-10, -30; T.C. A6WE	ST870SO	Installation of Collins FPC 75 ground proximity warning system. Issued 11/25/75.	SO	73874	Southern Airways, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-10, -30; T.C. A6WE	SA1177CE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/11/79.	CE	62030	Ozark Air Lines, Inc. St. Louis International Airport Lambert Field St. Louis, MO 63145
DC-9-10, -30; T.C. A6WE	SA3097WE	Installation of Collins Radio Co. Model FPC-75 ground proximity warning system. Amended 4/6/76.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-11, -12, -13, -14, -15, -31, -32; T.C. A6WE	ST735SO	Installation of protective rigid cover over tail cone emergency evacuation slide (installation of International Inflatables Model 68090 slide per STC ST676SO or equivalent required with this STC). Issued 12/4/72.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
DC-9-11, -12, -13, -14, -15, -15F; T.C. A6WE	SA2233WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-9-11, -12, -13, -14, -15, -15F, -21; T.C. A6WE	SA2503WE	Installation of replacement cooling turbine nozzle assembly. Issued 4/20/72.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91503
DC-9-11, -12, -13, -14, -15, -15F: T.C. A6WE	SA2645WE	Installation of dual Litton LTN-51 inertial navigation system. Issued 2/2/73.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
DC-9-11, -14, -15F, -31; T.C. A6WE	SA1933WE	Installation of under seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-11, -31; T.C. A6WE	SA1195EA	Installation of Magee Plastics passenger service units (PSU's) in lieu of original manufacturer's PSU's. Issued 5/19/80.	EA	54200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15237
DC-9-14, -15; T.C. A6WE	SA527CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2981WE	Modification of No. 1 galley, Hughes Airwest P/N RW2530045 or Nordskog P/N 742A Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2982WE	MOdification of No. 2 galley, Hughes Airwest P/N RW2530051 or Nordskog P/N 645A. Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-14, -31; T.C. A6WE	ST676SO	Installation of International Inflatables Company emergency evacuation slide, Model 68090, at tail cone exit.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-9-14, -9-31, -9-32; T.C. A6WE	SA2765WE	Installation of altitude alerting and reporting capabilities. Issued 10/10/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15; T.C. A6WE	SA1511CE	Increase the passenger capacity from 83 to 90. Issued 9/6/79.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9-15; T.C. A6WE	SA1728WE	Installation of Bendix Model DRA 12 Doppler navigation system and relocation of ATC transponder antenna and marker beacon antenna. Amended 2/6/70.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-9-15; T.C. A6WE	SA2587WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 3/18/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
DC-9-15; T.C. A6WE	SA2764WE	Altitude alerting and reporting capabilities are provided by installation of Harowe P/N 2031-01-1 altitude alert system, replacement of captain's barometric altimeter with a Harowe P/N 2050-01-1 servo actuated altimeter and two existing air data computers are replaced by Sperry P/N 2587400-176 air data computer. Issued 9/28/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15; T.C. A6WE	SA3051WE	Change seating configuration to 80 economy class, and installation of two auxiliary galleys at fuselage stations 764.5 to 784. Issued 5/29/75.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846
DC-9-15F; T.C. A6WE	SA2028WE	Replacement of V.H.F. 7533483 SAU polyethylene dielectric coaxial cables with Type RG115 A/U PTFE dielectric coaxial cables and addition of head-shield between APU exhaust shroud and wiring conduits.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
DC-9-15F; T.C. A6WE	SA2763WE	The captain's altimeter is replaced by Harowe P/N 2050-01-1 servo actuated altimeter and existing altitude alert system is replaced by Harowe P/N 2031-01-1 altitude alert system. Issued 9/19/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15F; T.C. A6WE	SA2788WE	Installation of galley assembly, P/N RW2530045. Issued 12/6/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA2789WE	Installation of Hughes Airwest galley assembly, P/N RW2530051. Issued 12/10/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA3558WE	Installation of 535-gallon auxiliary fuel tank system in forward cargo compartment. Issued 3/8/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
DC-9-21, -31, -32F (USAF C-9A), -32, -33F, -41; T.C. A6WE	SA862EA	Addition of airspeed select function to speed command/autothrottle system. Amended 6/27/78.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
DC-9-21, -31, -32, -32F, -33F, -41, -51; T.C. A6WE	SA2212WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-9 Series 30; T.C. A6WE	SA130GL	Installation of Systron-Donner Model 8160-20-P10 angular rate sensor in lieu of presently installed rate gyros in pitch-axis computer, roll-axis computer, and stability augmentation computers. Issued 7/23/76.	GL	61625	North Central Airlines, Inc. 7500 Northliner Drive Minneapolis, MN 55450
DC-9-30; T.C. A6WE	SA3642WE	A speed comman system, safe flight P/N 1312-25B installed. Issued 5/16/78.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-30, -9-31; T.C. A6WE	SA294NW	Interior arrangement, coatroom installation. Issued 5/14/76.	NW	48532	KME Manufacturing 800 North 6th Street Renton, WA 98055
DC-9 Series 30; T.C. A6WE	ST499SO	Modification of main landing gear brake stud. Issued 4/19/72.	SC	84770	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-9 Series 30; T.C. A6WE	SA1658WE	Installation of Airborne vibration monitoring system equipment.	WE	25917	Consolidated Electrodynamics Corp. Transducer Products Division 1400 South Shamrock Avenue Morovia, CA 91016
DC-9 Series 30; T.C. A6WE	SA2473WE	Installation of AiResearch cooling turbine P/N 204950-5-3 in lieu of P/N 204950-5-2. Issued 2/18/72.	WE	07505	AiResearch Manufacturing Company Division of Garrett Corporation 9851 Sepulveda Boulevard Los Angeles, CA 90009
DC-9 Series 30; T.C. A6WE	SA2803WE	Replacement of splined end on DC-9 nose gear cylinder, Douglas P/N 5920602. Amended 2/1/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9 Series 30; T.C. A6WE	SA2805WE	Replacement of splined end of DC-9 nose gear cylinder. Issued 1/18/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9-30; T.C. A6WE	SA3887WE	Installation of two Howell Model H900 solid state exhaust gas temperature indicators. Issued 3/29/79.	WE	43340	Hughes Airwest 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-30; T.C. A6WE	SA4059WE	Installation of ground proximity warning system (GPWS) and altitude alert system. Issued 12/13/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
DC-9-30, -32F, -33F, -51; T.C. A6WE	SA3115WE	Installation of Collins ground proximity warning system. Amended 4/7/76.	PC	41260	Hawaiian Airlines Honolulu International Airport Honolulu, HI 96820
DC-9-30, -50; T.C. A6WE	SA84GL	Install Bendix GPW-83 ground proximity warning system. Amended 8/10/76.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450
DC-9-31; T.C. A6WE	ST464SO	Installation of Decca IIB 06 omnitrac area navigation system. Operations will not be predicated on use of vertical guidance information of area navigation system. Amended 6/29/71.	SC	31420	Eastern Airlines International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	ST557SO	Installation of 99 passenger interior arrangement. Issued 10/6/73.	SO	31420	Eastern Airlines International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	SA878EA	Installation of SFENA standby horizon indicating system. Reissued 12/22/75.	CE	62030	Ozark Air Lines Box 10007, Lambert Field St. Louis, MO 63145
DC-9-31, -32; T.C. A6WE	SA3888WE	Installation of an auxiliary fuel tank system in the forward baggage compartment. Amended 5/25/79.	WE	43340	Hughes Air West, Inc. 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-31, -32, -32F, -33F, -41; T.C. A6WE	SA2502WE	Installation of replacement cooling turbine nozzle assembly. Amended 11/13/73.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91504
DC-9-31, -9-51; T.C. A6WE	SA1019EA	Installation of Collins Model FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
DC-9-31/-51; T.C. A6WE	SA3455WE	Installation of tourist and first class interiors. Amended 10/12/79.	SC	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-9-32; T.C. A6WE	ST856SO	Installation of Bendix ground proximity warning system. Issued 10/21/75.	SC	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	ST921SO	Fabrication and installation of baggage stowage rack, P/N 325100. Issued 1/28/77.	SO	29234	Delta Airlines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	SA1895WE	Installation of a second observer seat in flight crew compartment.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-9-32; T.C. A6WE	SA2106WE	Modification consists of interior arrangement, various passenger entertainment systems and avionics equipment. Reissued 8/20/73.	GL	64730	Playboy Enterprises, Inc. 919 North Michigan Avenue Chicago, IL 60611
DC-9-32 (VC-9C), DC-9-32F(C-9A); T.C. A6WE	ST248GL	Installation of Collins Model FPC flight profile comparator, P/N 622-2615-500, and Harowe barometric altitude rate computer, P/N 4030-03-1. Amended 7/19/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
DC-9-32F; T.C. A6WE	SA1043EA	Installation of structural provisions for executive interior. Issued 11/24/76.	EA	12500	Atlantic Aviation Corporation Box 1709 Wilmington, DE 19899
DC-9-32F; T.C. A6WE	SA2598WE	Installation of passenger pallet system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA697EA	Installation of (4) Aerojet-General Corp. 15 KS-1000-A1 or Bristol Aerospace (1968) Ltd. 15 KS-1000-A1(B) rocket engines and fairings. Amended 2/29/72.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-9-32F, -9-33F; T.C. A6WE	SA1193EA	Installation of ceiling panel kits. Issued 4/16/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
DC-9-32F, -33F; T.C. A6WE	SA1970WE	Installation of 88 x 108-inch cargo pallet P/N 24545-51, -52, or -53 with net P/N 24550-51, -52, or -53 and 88 x 54-inch cargo pallet P/N 24546-51, -52, or -53 with net P/N 24551-51 or -52. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2021WE	Installation of various cargo pallets and nets (per Tridair "Loading Instructions Drawing No. 40414). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2092WE	Installation of Heath 54 x 88-inch cargo pallet AC-10528-1 and net AC-10657-101. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-9-41; T.C. A6WE	SA3366WE	Modification of cabin interior. Installation includes all or part of the following overhead storage compartments, sculptured ceiling and sidewall panels, flourescent cabin lighting, standby lighting, emergency lighting, and an overwing exit locator sign. Amended 3/31/78.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-9-51; T.C. A6WE	SA3660WE	Installation of Carrier Aircraft coat closet Model EAL951-1. Issued 6/6/78.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-51; T.C. A6WE	SA3800WE	Installation of a 130 passenger seating arrangement, two galleys, and associated water drain mast. Issued 12/6/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
DC-9-51; T.C. A6WE	SA4002SW	In-place cargo system. Issued 7/31/79.	SW	04250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74112
DC-9, DC-10-30; T.C. A6WE	SA1068EA	Replacement of Fairchild Burns seats by Magee Plastics Co. seat trim kit P/N 67203. Issued 2/14/78.	EA	53200	Magee Plastics Company 515 Rochester Road Pittsburgh, PA 15237
DC-10; T.C. A22WE	SA285NW	Installation of Trans Com System. Issued 4/15/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
DC-10; T.C. A22WE	SA419NW	Class divider installation. Issued 3/10/77.	NW	48532	KME Manufacturing 800 North 6th Street Renton, WA 98055
DC-10; T.C. A22WE	SA713NW	Installation of class divider. Issued 1/30/79.	NW	48532	KME Manufacturing Company The Commons Building 1200 112th N.E. Bellevue, WA 98004

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10; T.C. A22WE	SA3892WE	Installation of Stowe Corp. service carts. Issued 3/23/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-10; T.C. A22WE	SA2611WE	Installation of three Litton LTN-51 inertial navigation systems, an inertial navigation switching unit and two Sperry horizontal situation indicators. Amended 3/5/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10;	SA2816WE	Modification of DC-10-10 aircraft for the installation of spacer pallets. Issued 2/8/74.	WE	80500	United Air Lines, Inc. Engineering Department San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2836WE-D	Installation of Bell and Howell video entertainment system in A, B and C zones of passenger cabin. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2837WE-D	Install new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 12/9/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2888WE	Installation of three Litton LTN-51 or LTN-72 inertial navigation systems. Issued 2/28/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10; T.C. A22WE	SA3025WE-D	Installation of refrigeration cooling for DME interrogators. Amended 3/12/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3031WE-D	Installation of four additional serving cart tie downs on main deck. Amended 9/13/78.	WE	80500	United Airlines, Inc. Maint San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3035WE-D	Install slide-raft assembly at each LH and RH cabin door exit. Issued 2/17/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3036WE-D	Modifies aircraft to install dual Delco C-IV inertial navigation systems (INS) for attitude and direction reference, navigation, and autopilot steering. Issued 3/22/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3127WE	Installation of first class passenger seats incorporating unitized oxygen systems. Issued 12/11/75.	WE	85126	Western Airlines, Inc. 6060 AVion Drive Los Angeles, CA 90052
DC-10-10; T.C. A22WE	SA3358WE-D	Reduces first class seating to 16 seat places, installs 9-across coach seating - 243 seat places, installs class divider, lounge table, PSF, and closets in zone A, closet in zone C. Issued 11/15/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3510WE	Replace primary thrust reverser with conical nozzle and plug; modify pylon aft fairing; and remove upper and lower actuators and drive cables. Issued 10/31/77.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012
DC-10-10; T.C. A22WE	SA3580WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 4/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3591WE-D	Installs new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 9/11/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-10; T.C. A22WE	SA3696WE	Training requirements, special limitations, and installation of required provisions, including communications and equipment to permit occupancy of the lower galley during taxi. Issued 7/12/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3815WE	Installation of a video projection system. Amended 2/28/79.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10; T.C. A22WE	SA3941WE-D	Installation of a UHF radio telephone system. Issued 6/9/80.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA4041WE	Installation of Litton LTN-211 Omega navigation system. Issued 11/30/79.	WE	85126	Western Airlines, Inc. 6060 Avion Drive Los Angeles, CA 90052
DC-10-10; T.C. A22WE	SA4126WE	Installation of Stowe Corp. entree cart, P/N 10074. Issued 4/9/80.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-10, -10-10F; T.C. A22WE	SA2524WE	Installation of lounge seats, four-place divan, L-shaped bar, and cocktail tables. Amended 3/8/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2770WE	Installation of visual entertainment system. Issued 10/2/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10, -10-10F; T.C. A22WE	SA2924WE	Installation of wheeled refrigerated module, P/N 73011000. Issued 8/27/74.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-10F; T.C. A22WE	SA2948WE	Installation of buffet/bar and bustle assembly. Issued 1/22/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA2985WE	Modification of installed G1 and G1A galleys (Dale P/Ns CAG-11000, CF-10-1, CAG-10000, CF-7000). Issued 1/22/75.	WE	25970	Continental Airlines 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2987WE	Installation of cabin lounge swivel seats and adjustable table with removable top. Issued 1/23/75.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3014WE	Installation of floor game table assembly. Amended 1/20/76.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91100
DC-10-10, -10-10F; T.C. A22WE	SA3212WE	Installation of forward cargo compartment positive vent sump drain. Issued 6/15/76.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA1367WE	Installation of nine-abreast coach seating and associated oxygen and electrical system modification. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3368WE	Installation of eight-abreast coach seating in forward cabin behind the first class section, and associated oxygen and electrical system modifications. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3827WE	Installation of folding leaf table. Issued 1/31/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA3843WE	Installation of Nordskog Ind. galley 1-419. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3844WE	Installation of composites, unlimited coat closet, P/N 225-46103. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Aicport Los Angeles, CA 90009
DC10-10, -10-10F; T.C. A22WE	SA3845WE	Installation of buffet/bar unit, P/N 2142396. Amended 7/11/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-10, -10-10F; T.C. A22WE	SA3847WE	Installation of a new lounge and first class accommodations. Amended 7/12/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3848WE	Installation of HITCO refrigerated galley module. Amended 3/16/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-10-10, -10-10F; T.C. A22WE	SA3875WE	Installation of Continental Air Lines flight attendant seat, P/N 225-46317. Issued 3/16/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3937WE	Installation of HITCO storage galley module. Issued 5/18/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-10-10, -10-10F; T.C. A22WE	SA3996WE	Installation of Litton LTN-2110NS. Issued 7/18/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA4058WE	Installation of folding leaf table. Issued 11/8/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
DC-10-10, -10-10F; T.C. A22WE	SA4122WE	Installation of aluminum cabin window plug assembly to replace outer acrylic cabin window pane. Issued 3/24/80.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA4158WE	Installation of Fairchild beverage cart model 79067000. Issued 6/6/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3432WE	Installation of fire/overheat detection system. Amended 2/14/78.	WE	77300	Systron Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3626WE	Revision of DC-10 fire overheat detection system to allow intermixing of Systron-Donner fire detectors with Edison detectors in the fan, core, and pylon sections of the CF6 engines. Issued 4/11/78.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10F, -10-30, -10-30F, -10-40; T.C. A22WE	SA4138WE	Installation of cabin window plug assembly. Issued 4/21/80.	WE	32760	Edwards Enterprises 230 Constitution Drive Menlo Park, CA 94025
DC-10-10, -10-10CF; T.C. A22WE	SA3407WE	Installation of Lermer Apparatebau GMBH beverage cart No. L15701. Issued 5/20/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 91406
DC-10-10, -10-30; T.C. A22WE	SA776SO	Installation of SICMA food tray stowage carts. Amended 3/14/80.	SO	71600	SICMA Aero Seats, Inc. 6929 N.W. 46th Street Miami, FL 33166
DC-10-10, -10-30; T.C. A22WE	ST734SO	Installation of NAL Val-Pack coatroom, P/N 10621-1. Amended 3/30/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-10-10, -10-30; T.C. A22WE	SA2853WE	Retractable tiedown assemblies. Amended 3/23/78.	WE	48550	H. Koch & Sons Koch Road Corte Madera, CA 94925
DC-10-10, -10-30; T.C. A22WE	SA3067WE	Installation of lower lobe food service modules, P/Ns 818720, 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
DC-10-10, -10-30; T.C. A22WE	SA4134WE	Installation of an ARINC communication addressing and reporting system (ACARS). Issued 6/13/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-30; -10-30F; T.C. A22WE	SA2395WE	Installation of coffee bar cart, P/N 801000. Amended 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2774WE	Installation of wing tip mounted emblem lights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2893WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1704-C West 134th Street Gardena, CA 90249
DC-10-10, -10-30, -10-40; T.C. A22WE	SA930EA	Installation of Inflight Motion Pictures, Inc. projection unit assembly DC-10 16mm Tri-Jet system 10300 or light weight Tri-Jet projection system, DC-10 P/N 10307. Amended 9/14/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA947EA	Installation of Inflight Motion Pictures, Inc. screen assemblies. Amended 8/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, New York 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA969EA	Installation of Inflight movie projection assembly P/N 10270, Super 8mm IMPAK system. Issued 11/21/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA990EA	Installation of 16mm projection unit assembly and center stowage bins, P/N 10310. Issued 10/3/74.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA3335WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
DC-10-10, -10-30F; T.C. A22WE	SA2817WE-D	Installation of provisions for ground proximity warning system. Amended 6/26/75.	WE	80500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-10-10, -10-30F; T.C. A22WE	SA2830WE-D	Installation of Collins FPC-75 ground proximity warning system computer. Amended 3/30/76.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10F; T.C. A22WE	SA4006WE	Installation of a 3-place courier seat. Issued 7/31/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10F; T.C. A22WE	SA4156WE	Installation of a two-place courier seat. Issued 5/12/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-30; T.C. A22WE	SA2663WE	Installation of Trans Com movie and projector entertainment system, Model 2420. Issued 3/19/73.	WE	76800	Trans Com A Division of Sundstrand Data Control, Inc. 3100 Pullman Avenue Costa Mesa, CA 92626
DC-10-30; T.C. A22WE	SA2684WE	Installation of Tridair Industries main deck baggage container system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-10-30; T.C. A22WE	SA2707WE	Installation of cabin lounge seats, folding tables, cart stowage unit, and class divider partition. Issued 6/6/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Airport Mail Facility Miami, FL 33159
DC-10-30; T.C. A22WE	SA3194WE	Installation of Airborne video-cassette system. Issued 5/12/76.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA3344WE	Installation of dual Litton LTN-72R INS/RNAV navigation systems. Issued 2/23/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-30; T.C. A22WE	SA3393WE	Installation of Airborne Video-cassette system.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA3569WE	Installation of aircraft video system. Amended 6/5/79.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA4010WE	Installation of video projection system. Issued 10/5/79.	WE	15375	Bell and Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10; T.C. A22WE	SA4070WE	A video projection system is installed. Issued 6/25/80.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
DC-10-30; T.C. A22WE	SA4186WE	Installation of Stowe Corp. liquor cart, P/N 10051-3. Issued 7/22/80.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-30, -10-30F; T.C. A22WE	SA2775WE	Installation of Fairchild Stratos tray carrier rack assembly. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2777WE	Installation of service center (G 1) and coffee bar G-2 assemblies. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2780WE	Installation of serving cart pallets, P/N 989200 and 990100. Issued 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-30F; T.C. A22WE	SA2938WE	Carts and pallet assembly installation. Issued 10/9/74.	WE	28560	Dale Engineering & Development, Inc. 12243 Branford Street Sun Valley, CA 91352
DC-10-30F; T.C. A22WE	SA2949WE	Installation of passenger entertainment/service system. Amended 12/6/74.	WE	33223	Electronic Engineering Company of California 1441 East Chestnut Avenue Santa Ana, CA 92701
DC-10-30F; T.C. A22WE	SA2950WE	Installation of ballast assembly. Issued 11/18/74.	WE	79200	Trans International Airlines Oakland International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA3128WE	Installation of 376 passenger interior arrangement and associated oxygen system modifications. Issued 12/15/75.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA3117WE	Installation of courier seat module assembly. Issued 1/21/76.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA418[illegible]WE	Installation of DRIESSEN meal cart in lieu of Nordskag carts P/N's 50193 and 50194. Issued 7/2/80.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA4197WE	Installation of first class interior arrangement. Issued 7/25/80.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
DC-10-40; T.C. A22WE	SA88GL	Installation of Bendix GPW-83 ground proximity warning systems. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40; T.C. A22WE	SA372GL	Installation of Honeywell P/N HG280DD80 digital airdata computer in the number three position per NWA project 1-34-40300 in place of the Honeywell P/N HG280D5 presently used in this position for data collection purposes only. Issued 10/26/79.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40; T.C. A22WE	SA2782WE	Installation of wheeled refrigerated module P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-40, -10-40F; T.C. A22WE	SA3114WE	Installation of wing and tail engine pods. Amended 3/15/79.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MESSERSCHMITT - BOLKOW - BLOHM - GMBH

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BO-105A, BO-105C; T.C. H3EU	SA26RM	Installation of JB Systems air-conditioning system. Issued 6/14/74.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
BO-105A, BO-105C; T.C. H3EU	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
BO-105A, BO-105C; T.C. H3EU	SH978EA	Installation of Consolidated Instrument Co., Inc. battery temperature alert system, Models B206-TA180 or B206E-TA180. Issued 4/4/74.	EA	25920	Consolidated Instrument Company Teterboro Airport Teterboro, NJ 07608
BO-105A, BO-105C, BO-105S; T.C. H3EU	SH1065EA	Installation of Devore tail rotor floodlight on upper surfaces of horizontal stabilizer. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
BO-105C; T.C. H3EU	SH218NW	Installation and maintenance of Allison 250-C20 engine equipment with Bendix fuel control system. Issued 9/10/75.	NW	98124	The Boeing Company P.O. Box 3707 Seattle, WA 98124
BO-105C; T.C. H3EU	SH239WE	Installation of Chandler Evans (CECO) Model 104900-A3-A2 fuel controllers and Model 104500-A governors. Issued 6/11/79.	WE	08353	Air Services International 7300 East Evans Drive Scottsdale, AZ 85026
BO-105C; T.C. H3EU	SH971EA	Installation of cabin door post and door latching mechanism modification Kit No. SK212-10415 (Kit Nos. 101 and 102 or 201 and 202). Reissued 7/11/80.	EA	56832	MBB Helicopter Corporation Weston Way, P.O. Box 514 West Chester, PA 19380
BO-105C; T.C. H3EU	SH1025EA	Installation of ten inch cabin extension, modification of cabin doors, relocation of battery and structural modification of tailboom to fuselage splice. Amended 1/9/78.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1031EA	Installation of AiResearch Manufacturing Co. environmental control unit, P/N 2200850-1 (Carson P/N C-105-20-5000-29). Reissued 5/21/80.	EA	56833	MBB Helicopter Corporation Weston Way - P.O. Box 514 West Chester, PA 19380
BO-105C; T.C. H3EU	SH1041EA	Relocation of battery to a position just aft of No. 2 engine. Issued 10/12/76.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1069EA	Installation of cabin door post and door latch assembly in accordance with data. Issued 2/23/78.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1073EA	Installation of electric chip directors in main transmission and intermediate and tail rotor gear boxes. Amended 6/19/80.	EA	47790	Keystone Helicopter Corporation 1420 Phoenixville Pike West Chester, PA 19380
BO-105C, BO-105S; T.C. H3EU	SH1102EA	Installation of emergency float kit, F105-85189. Amended 5/6/80.	EA	56832	MBB Helicopter Corporation Weston Way - P.O. Box 514 West Chester, PA 19380
BO-209-150 FV and RV, BO-209-150FF; T.C. A27EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AF in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
BO-209-150 FV and RV, BO-209-150FF; T.C. A27EU	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MITSUBISHI AIRCRAFT INTERNATIONAL, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B, -2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, -40, -60; T.C. A10SW	SA1042SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638T series lead-acid type batteries. Issued 1/15/79.	SC	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Atlanta, GA 30339
MU-2B, MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A10SW	SA1460CE	Installation of microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
MU-2B, -2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, -40, -60; T.C. A10SW	SA3524WE	Installation of vertical tail flood lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
MU-2B-25, -2B-26, -2B-35, -2B-36; T.C. A10SW	SA304GL	Installation of Hartzell HC-B3TN-5C/T10178B-13Q propellers in lieu of HC-B3TN-5C/T10178B-11 or 11R propellers using original installation hardware and components. No installation data are required. Amended 12/29/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-36A, -2B-60; T.C. A10SW	SA215GL	Installation of two 25-gallon auxiliary fuel tanks in nose section of main landing gear wheel fairings. Amended 12/26/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62707
MU-2B-36A; T.C. A10SW	SA216GL	Installation of right side fuselage window at station 6335. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-36A; T.C. A10SW	SA217GL	Installation of right side fuselage window at station 6897. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-20, -25, -26; T.C. A2PC	SA561SO	Installation of Bendix M-4D automatic flight control system including optional yaw trim, optional manual electric pitch trim and optional flight director system. Amended 1/24/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-20, -25, -26, -30, -35, -36; T.C. A2PC	SA2238SW	Tip tanks lights. Issued 6/8/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35; T.C. A2PC	SA1489SW	Antennas. Issued 7/6/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35; T.C. A2PC	SA1805SW	Foxboro fuel flow signal conditioning unit PC-620. Issued 2/7/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35, -36; T.C. A2PC	SA1940SW	Goulton GB40 cell batteries. Issued 12/12/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -35; T.C. A2PC	SA1776SW	Lear Siegler starter generator, P/N 23046-007M. Issued 1/4/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San angelo, TX 76901
MU-2B-20, -25, -35; T.C. A2PC	SA1814SW	Dual baro scale altimeter. Issued March 1974.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -30; T.C. A2PC	SA161GL	Install Garrett AiResearch TPE331-6-252M engines. Amended 6/15/77.	GL	07503	AiResearch Capitol Aviation Co. Capital Airport Springfield, IL 62705
MU-2B-20, -30; T.C. A2PC	SA1316SW	Series/parallel selector switch for battery start selection. Issued 5/26/71.	SW	60073	Mitsubishi Aircraft Int'l, INc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -30; T.C. A2PC	SA1547SW	Dual FC-17 static inverters. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1465SW	Interior. Issued 8/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1541SW	King basic avionics package. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1546SW	Basic King avionics package. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1548SW	Area NAV KCN 610. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1549SW	AVQ-55 weather radar. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1564SW	Collins basic avionics package. Issued 12/15/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1628SW	RCA AVQ-21 weather radar. Issued 3/15/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1646SW	Sunair ASB-100 HF system. Issued 4/27/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1647SW	Sperry stars IVB flight director. Issued 4/27/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1710SW	Bendix RDR-1200 weathervision system. Issued 8/2/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1711SW	RCA AVQ-47 weather radar. Issued 8/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1733SW	Battery temperature warning system. Issued 9/21/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
MU-2B-25; T.C. A2PC	SA1752SW	Sperry AA-20 radio altimeter. Issued 10/29/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1817SW	Collins ALT-50 radar altimeter. Issued 3/6/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1859SW	RDR-100 weather radar. Issued 3/26/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1793SW	Install Collins FDS-112 C/V flight director. Issued 11/20/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1818SW	Aerosonics encoding altimeter and alerter. Issued 9/13/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1925SW	Basic King gold crown avionics. Issued 2/14/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA2268SW	Installation of #2 VHF comm antenna. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -2B-26, -2B-35, -2B-36; T.C. A10SW	SA304GL	Installation of Hartzell HC-B3TN-5C/T10178B-13Q propellers in lieu of HC-B3TN-5C/T10178B-11 or 11R propellers using original installation hardwarde and components. No installation data are required. Amended 12/12/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1882SW	Chart holder. Issued December 1974.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1912SW	Instrument panel modification. Issued 9/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1914SW	Cooling air inlet screen. Issued 10/15/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1928SW	Sperry GH-14 flight director. Issued 1/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1929SW	United Instruments encoding altimeter. Issued 1/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1964SW	Cooling air inlet modification. Issued 9/25/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1990SW	Pressure relief overboard vent line and restrictor fitting to EPA fuel purge system. Issued 5/21/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2233SW	Rewiring of auto-manual air conditioning switch. Issued 8/15/75.	SW	60073	Mitsubishi Aircraft International P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2263SW	Modification of ECS mixing chamber. Issued 10/9/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2487SW	Outside air temperature indicator. Issued 8/6/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A10SW	SA3489WE	Installation of fuel boost pump. Issued 9/23/77.	WE	26725	Hydro-Aire Division of the Crane Company 3000 Winona Avenue P.O. Box 7722 Burbank, CA 91510
MU-2B-25, -35; T.C. A2PC	SA1614SW	IDC 570-24929-002 encoding altimeter; or Smith's WL-1350 AM/MS-1(-2) encoding altimeter. Issued 6/6/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1615SW	Encoding altimeter/alerting system. Issued 3/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20 Series; T.C. 2A3	SA1786WE	Installation of Brittain Industries B-6 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1787WE	Installation of Brittain NAV-2B flight control. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20, M22 Series; T.C. 2A3, A6SW	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
Mark 20, 20A; T.C. 2A3	SA2666WE	Ceconite 102 material covering of rudder, elevators, ailerons and flaps. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M20, M20A; T.C. 2A3	SA2823SW	Reinforcement of vertical tail spar. Issued 7/31/78.	SW	64407	Harry L. Phillips Route 3, Box 420F Fort Worth, TX 76067
M20, M20A, M20B; T.C. 2A3	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amneded 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA4-1210	Installation of Zonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	ZONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
M20 thru M20F; T.C. 2A3	SA600EA	Installation of electronic voltage alarm.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
M20, M20A thru M20E; T.C. 2A3	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
M20, M20A thru M20E; T.C. 2A3	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs: SA705SW, SA732SW.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M20, -A, -B, -C, -D, -E, -F, -G; T.C. 2A3	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 South Curtice Street Littleton, CO 80120
M20, M20A, M20B, M20C, -D, -E, -F; T.C. 2A3	SA1462WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	80120	Hanna-Aero Corporation 5222 South HOlly Street Littleton, CO 80120
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1932SW	Chrome plated disc brakes. Issued 11/27/74.	SW	29580	W.A. DeMaine Route 3, Box 62 Pine Bluff, AR 71601

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA3275WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell Mfrg. BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
M20, M20A, C, D, E, F, G, J, K; T.C. 2A3	SA4178WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
M20A, M20B, M20C, M20D, M20G; T.C. 2A3	SA1156WE	Installation of Rajay turbosupercharged Lycoming O-360-A1A or -A1D engine. Amended 8/2/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA738EA	Installation of Whelen Engineering Co., Inc. Model HD-14 anti-collision strobe light system.	NE	85500	Whelen Engineering Co., Inc. 3 Winter Avenue Deep River, CT 06417
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light systems. Amended 10/4/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
M20B, C, D, E, F, G; T.C. 2A3	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
M20B, M20C, M20D, M20E, M20F, M20G, Normal Category; T.C. 2A3	SA3938WE	INstallation of flap gap seal. Issued 5/21/79.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA4023WE	Installation of flap gap fairings, flap hinge fairings, fuselage fairing at the tail cone, and a plexiglass landing light fairing. Amended 1/17/80.	WE	65015	John A. Porter 29 Walnut Via 501 E. Orangethorpe Avenue Anaheim, CA 92801
M20C, M20D; T.C. 2A3	SA77CE	Installation of McCauley 2D34C53/74E-0 or B2D34C53/74E-0 propeller with D-2809 spinner. Amended 5/24/68.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
M20C, M20D; T.C. 2A3	SA3859WE	Installation of an air/oil separator. Issued 3/12/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
Mooney M20C, M20D, M20E; T.C. 2A3	SA138WE	Installation of Grimes Model D-7080. Rotating beacon on vertical fin. Reissued 3/8/76.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
M20C, M20D, M20G; T.C. 2A3	SA375GL	Installation of Lycoming O-360-A1F6 or O-360-A1F6D in lieu of Lycoming O-360-A1D. Amended 4/18/80.	GL	90152	Louis M. Zeller, Jr. Route 1, Box 298-B Mount Vernon, IN 47620
M20C, M20D, M20G; T.C. 2A3	SA386GL	Installation of McCauley Propellers B2D34C212/78CDA-4, B2D34C212/78CDA-4E, B2D34C214/90DHB-16, B2D34C214/90DHB-16E, using original hardware and components. No installation data are required. Reissued 4/22/80.	GL	90152	Louis M. Zeller, Jr. Route 1, Box 298-B Mount Vernon, IN 47620
M20C (S/N 20-0011 and on - 1974), (S/N 20-1147 and on - 1975), M20E (S/N 21-0025 and on - 1974), (S/N 21-1161 and on - 1975); T.C. 2A3	SA2993WE	Installation of Pathfinder autopilot systems and/or electric pitch trim systems. Issued 2/21/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C (S/N 20-0011 and on), M20E (S/N 21-0025 and on); T.C. 2A3	SA3222WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 11/15/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, E, F; T.C. 2A3	SA1938SW	Brittain LSA-6 lateral stability augmentation system (positive control). Issued 1/7/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20C, E, F, G; T.C. 2A3	SA2207SW	NAV-FLITE II and B-5 flight control systems. Issued 7/23/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20C, E, F, G; T.C. 2A3	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, E, F, G; T.C. 2A3	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, M20E, M20F; T.C. 2A3	SA2654WE	Installation of Pathfinder P2A autopilot system. Amended 4/14/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20E/Super 21: T.C. 2A3	SA999CE	Installation of ERC battery monitor. Issued March 1974.	CE	33229	Electronic Research Company P.O. Box 913 Shawnee Mission, KS 66201
M20E, M20F; T.C. 2A3	SA250GL	Installation of Lycoming IO-360-A1B6 engine in lieu of Lycoming IO-360-A1A engine using original installation hardware and components. No installation data are required. Issued 6/30/78.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA320GL	Installation of Hartzell Model HC-C2YK-1( )F/F7666A-4Q propeller in lieu of Hartzell Model HC-C2YK-1/7666-2 propeller using original installation hardware and components on aircraft previously modified in accordance with STC No. SA250GL. No installation data are required. Issued 6/28/79.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA1411WE	Installation of Rajay turbocharged Lycoming IO-360-A1A engine. Amended 5/9/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20E, M20F, M20J; T.C. 2A3	SA2968WE	Installation of manifold pressure gage/fuel flow meter (fuel pressure gage) in lieu of original gage/meter. Amended 11/20/79.	WE	65015	John A. Porter 29 Walnut Via 501 East Orangethorpe Avenue Anaheim, CA 92801
M20E, M20F, M20J; T.C. 2A3	SA3728WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
M20E, M20F, M20J; T.C. 2A3	SA4065WE	Installation of Silver Instruments fueltron 1G or IP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20F, S/N 22-1179 and up; M20J, S/N 24-0001 and up; T.C. 2A3	SA1212CE	Installation of King KFC 200 2 axis (3 optional) flight control system with KCS 55/55A compass and King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or third axis (yaw damper) only, or manual electric trim only. Amended 9/8/77.	CE	48750	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20F, S/N 22-0013 and on (1974 models), S/N 22-1179 and on (1975 models); T.C. 2A3	SA2986WE	Installation of Pathfinder autopilot systems. Issued 2/19/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20F; T.C. 2A3	SA3047SW-D	Automatic flight system AK523 consisting of Century III autopilot with command automatic electronic pitch trim system and optional radio and glide slope couplers. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3048SW-D	Automatic flight system AK476 consisting of Century IIB autopilot with optional radio coupler. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3049SW-D	Automatic flight system AK475 consisting of Century I autopilot with optional omni tracker. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F: T.C. 2A3	SA3064SW-D	Mitchell command electric trim AK541. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
M20F; T.C. 2A3	SA3186WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20F; T.C. 2A3	SA4087WE	Installation of Hartzell HC-C2YK-1B/7666A-4Q constant speed propeller. No installation data required. Issued 1/9/80.	WE	52025	Paul E. Loewen P.O. Box 545 Lakeport, CA 95453
M20J; T.C. 2A3	SA1300CE	Installation of Edo-Aire propeller governor Model 34-826-014-11. Amended 1/9/78.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
M20J; T.C. 2A3	SA3307SW-D	Installation of Mitchell automatic flight system AK801 consisting of Century 41 autopilot or Model AK801FD consisting of Century 41 flight director autopilot. Issued 10/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3308SW-D	Installation of Mitchell automatic flight system AK802 consisting of Century 21 autopilot. Issued 10/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3555WE	Installation of Rajay turbocharged Lycoming IO-360-A3B6D and/or IO-360-A1B6D engines. Issued 12/30/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90801
M20J, M20K; T.C. 2A3	SA300CE	Installation of propeller governors on single and twin engine aircraft, P/N M20J E210490, M20K E210760. Issued 2/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
M20J (24-0939 and up), M20K; T.C. 2A3	SA1464CE	Installation of KFC 200 two axis (three optional) flight control system. Amended 3/3/80.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M20J, M20K; T.C. 2A3	SA1525CE-D	Installation of King KNS 81 digital area navigation system. Issued 1/23/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20K; T.C. 2A3	SA378GL	Installation of Silver Instruments fueltron IG digital fuel flow meter. Reissued 1/3/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20K; T.C. 2A3	SA3325SW-D	Mitchell automatic flight system AK807 consisting of Century 41 autopilot flight director autopilot. Issued 1/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NIHON AEROPLANE MANUFACTURING CO., LTD.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
YS-11, -11A: T.C. A1PC	ST424SO	Installation of replacement radome assembly.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11, -11A; T.C. A1PC	SA863EA	Incorporation of Chromalloy Electronics Division ESL-1 or ESL-6 emergency slide lighting system. Reissued 3/6/73.	SO	22225	Chromalloy Electronics Div. of Chromalloy American Corp. 3901 North 29th Avenue Hollywood, FL 33020
YS-11, -11A; T.C. A1PC	SA2728WE	Incorporation of Holcombe Industries Hi-Lite system (P/N 50-1001) for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
YS-11, -11A-200, -300, -500, -600; T.C. A1PC	SA1198EA	Installation of a Safeway deicer overshoe P/N 5939 on Dowty Rotol propeller, model R209/4-40-4.5/2. Issued 6/23/80.	EA	70830	Semsa, Inc. 2125 Smithtown Avenue Ronkonkoma, NY 11779
YS-11A Series; T.C. A1PC	SA393SO	Install Goodyear 9540512 wheels in place of Goodyear 9543138 wheels.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A; T.C. A1PC	SA4110SW	Installation of Dynamic Air Engineering air condition system. Issued 4/22/80.	SW	07740	Air Freight International, Inc. P.O. Box 2 Addison, TX 75001
YS-11-A200; T.C. A1PC	SA1949WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach,CA 90807
YS-11A-200, -300, -500, -600; T.C. A1PC	ST487SO	Installation of P.P.G. manufactured main windshields, P/Ns 5613-00001 (L/H) and 5613-00002 (R/H) and Barber Colman P/N HYLZ 8882 temperture controller. Amended 2/22/74.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500; T.C. A1PC	ST486SO	Installation of external APU control panel. Amended 2/16/72.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500; T.C. A1PC	ST866SO	Installation of Bendix ground proximity warning system. Amended 11/20/75.	SO	64500	Piedmont Aviaton, Inc. P.O. Box 2720 Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A, -500; T.C. A1PC	SA2910SW	Unpressurized cargo door in rear left hand portion of fuselage. Amended 5/9/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A Series 500; T.C. A1PC	SA3873WE	Installation of bleed air heating system. Amended 8/17/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A-500; T.C. A1PC	SA4094SW	Aft cargo door between F.S. 636.2 and 758.9 between floorline and stringer 27 and associated structural changes. Issued 3/3/80.	SW	07740	Air Freighters Int'l, Inc. P.O. Box 2 Addison, TX 75001
YS-11A-600; T.C. A1PC	SA3047WE	Installation of provisions only for ground proximity warning system. Issued 5/28/75.	WE	87450	World Airways, Inc. Maintenance & Engineering Center Oakland International Airport Oakland, CA 94614
YS-11A-626; T.C. A1PC	SA78NW	Cabin modiication. Issued October 1973.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-12; T.C. 780	SA660AL	Installation of extended flaps, flap control system and modified ailerons. Issued 1/9/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12; T.C. 780	SA660AL	Installation of extended flaps, flap control system and modified ailerons. Issued 1/9/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99501
PA-12; T.C. 780	SA687AL	Installation of left side cabin door. Issued 7/16/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12; T.C. 780	SA689AL	Increased gross weight to 1935 lbs. Issued 7/8/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12 Series; T.C. 780	SA815CE	Installation of skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
PA-12 Series; T.C. 780	SA2038WE	Installation of Lycoming O-320 engine, McCauley 1A170/1C172 and Sensenich M74DM propellers and associated alternator systems. Amended 3/7/74.	NW	61526	Harold G. Nelson 3005 Southwest Marshall Street Pendleton, OR 97801
PA-12 Series; T.C. 780	SA3283WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	76860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-12, PA-12S; T.C. 780	SA202EA	Installation of either a Lycoming engine O-290-D (125 HP) or O-290-D2 (135 HP) with Sensenich propeller M74RM. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181, 1216 North Road Lyons, WI 53148
PA-12, -12S; T.C. A-780	SA444AL	Installation of McCauley 1A175/GM propeller. Issued 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-12, -12S; T.C. A-780	SA476AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12, -12S; T.C. A-780	SA476AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA494AL	Installation of electric fuel gauges. Issued 5/1/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -12S; T.C. A-780	SA517AL	Installation of plexiglass skylight on top of cabin. Issued 5/17/74.	AL	27250	Crosswinds, Inc. 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, PA-12S; T.C. 780	SA537AL	Installation of Day & Night 4-1 fiberglass propeller spinner.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12, PA-12S; T.C. 780	SA537AL	Installation of Day & Night 4-1 fiberglass propeller spinner.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA566AL	Installation of Lycoming O-320 engine. Amended 11/25/75.	AL	26815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12, -12S; T.C. 780	SA629AL	Install fiberglass wing tip assembly.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA653AL	Install Avco Lycoming O-320-A2B or O-320-C2B engine and Sensenich 74M6-0-52 propeller. Issued 9/8/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12, -14 Series; T.C. 780, 797	SA5-48	Structure approval only of engine mount assembly on aircraft for use with engines of not more than 363 pounds total installed weight and 170 hp (4 cylinder).	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-12, -14 Series; T.C. 780, 797	SA5-66	Structural approval only of Fred A. Shaw engine mount and forward fuselage modification for installation of 150 hp engine. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12, -14 Series; T.C. 780, 797	SA5-66	Structural approval only of Fred A. Shaw engine mount and forward fuselage modification for installation of 150 hp engine. Reissued 5/7/79.	AL	42051	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -14 Series; T.C. 780, 797	SA83AL	Lycoming O-320 Series (150 hp models only) engines and Sensenich M74DM propeller, using Stoddard engine mount 501. Amended 6/12/69.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA148AL	PA-18 main landing gear and installation of EDO 2000 floats. Amended 3/3/69.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA148AL	PA-18 main landing gear and installation of EDO 2000 floats. Amended 3/3/69.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA149AL	Installation of auxiliary baggage compartment.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-12, -14 Series; T.C. 780, 797	SA189AL	Install left side cabin door.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA189AL	Install left side cabin door.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA190AL	Increased gross weight to 1935 pounds.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA190AL	Increased gross weight to 1935 pounds.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA213SO	Electric fuel quantity indicator. indicator.	SO	54615	Obed L. Malpass 1502 Morris Road Wilmington, NC 28401
PA-12, -14 Series; T.C. 780, 797	SA289AL	Install rudder centering device.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th PPlace Anchorage, AK 99503
PA-12, -14 Series; T.C. 780, 797	SA2313SW	Install 22-1/2 gallon fuel tank. Issued 5/20/77.	SW	75498	W.L. Stoddard Stoddard Aero Service c/o Plane Booster, Inc. Box 541 McAllen, TX 78501
PA-12, -14, -16, -18, -10; T.C. 780, 797, 1A1, 1A2, 1A4	SA147AL	Electric fuel quantity gauge system.	AL	42158	C.D. Hogan 1831 Lake Otis Parkway Anchorage, AK 99501
PA-12, PA-14, PA-16, PA-18, PA-20, PA-22; T.C. 780, 797, 1A1, 1A2, 1A4, 1A6, AR-7	SA22RM	Manufacture of exact replacement parts, front and rear lift strut assembly. Amended 3/13/79.	RM	50500	Light Plane Components, Inc. 509 Buckley Road Aurora, CO 80011
PA-12, -14, -18; T.C. 780, 797, 1A2	SA215AL	Install L-2500A wheel replacement skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99501
PA-12, PA-14, PA-20, PA-22 Series; T.C. 780, 797, 1A4, 1A6	SA5-60	Installation of Russ Simpson sea fins.	AL	71774	Simpson Airservice, Inc. P.O. Box 2226 Ketchikan, AK 99901
PA-12; PA-22; T.C. A780, 1A6	SA388SO	Metalize wings, wing landing/taxi light installation. Amended 7/2/70.	SO	68550	W.F. Robison Valley Air Service P.O. Box 241 Lanett, AL 36863
PA-12, PA-22, PA-23, PA-28; T.C. 780, 1A6 2A13, 1A10	SA316SO	Carburetor ice detector. Amended 10/5/66.	SO	71545	C.B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
PA-12S; T.C. 780	SA610AL	Install Avco Lycoming O-360-A2A engine. Amended 2/25/77.	AL	20514	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-14 Series; T.C. 797	SA1-51	Lycoming O-290-D2 engine with Edo 89-2000 floats, water rudder and seaplane fin.	EA	14775	Arthur E. Barr 387 Eldred Street Williamsport, PA 17701
PA-14 Series; T.C. 797	SA1-573	Lycoming O-320 engine with PA-18A-150 cylinder baffles, Sensenich M74DM propeller and Harrison AP13-SJ03-01 oil cooler.	EA	77082	Susquehanna Aero Marine 378 Eldred Street Williamsport, PA 17701
PA-14 Series; T.C. 797	SA3-106	Edo 89-2000 floats, water rudder and auxiliary tail fin.	GL	61515	Henry E. Neils 2637 27th Avenue South Minneapolis, MN 55401
PA-14 Series; T.C. 797	SA4-78	Lycoming O-320 engine, Sensenich M74DM59 propeller, Piper PA-18A-150 engine cooling baffles modified, Harrison AP13-SJ03-01 oil cooler.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-14 Series; T.C. 797	SA4-81	Lycoming O-290-D2 engine and Sensenich M76AM-2/74-52 propeller.	NW	50900	Marine Air, Inc. Friday Harbor, WA 98250
PA-14 Series; T.C. 797	SA4-410	Lycoming 150 hp engine O-320-A2A.	WE	14960	Bates Aviation, Inc. 940 East 120th Street Hawthorne, CA 90250
PA-14 Series; T.C. 797	SA4-411	Modification of fuel system to PA-18 to facilitate takeoff either tank.	WE	14960	Bates Aviation, Inc. 940 East 120th Street Hawthorne, CA 90250
PA-14 Series; T.C. 797	SA4-412	Large PA-18 tail surfaces.	WE	14960	Bates Aviation, Inc. 940 East 120th Street Hawthorne, CA 90250
PA-14 Series; T.C. 797	SA4-561	Application of glass cloth to fuselage and to horizontal and vertical stabilizer.	WE	38060	Glasco-Air Products, In County Airport Oxnard, CA 93030
PA-14 Series; T.C. 797	SA4-913	Ceconite 101 covering of wings, fuselage and vertical fin.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-14 Series; T.C. 797	SA57NW	Installation of Lycoming O-320-E2D engine, McCauley TM7653 propeller and Lycoming alternator. Issued 3/6/74.	NW	61526	Harold G. Nelson 3005 Southwest Marshall Street Pendleton, OR 97801
PA-14 Series; T.C. 797	SA192AL	Flap handle installation and adjustable fore and aft pilot and co-pilot's seat.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-14 Series; T.C. 797	SA196SW	Hartzell HC-82XL-6F/7636D-4 propeller, Woodward 210080P governor, and Piper 14-733-00 propeller control	SW	71776	J.B. Simpson P.O. Box 126 Gilliam, LA 71029
PA-14 Series; T.C. 797	SA253AL	Installation of McCauley 1A175/GM propeller. Amended 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-14 Series; T.C. 797	SA356AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-14 Series; T.C. 797	SA368AL	Installation of McCauley 1A175/GM8242, GM8244, or GM8246 propellers. Amended 8/18/72.	AL	28660	Daniels & Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-14 Series; T.C. 797	SA378SW	Lycoming O-320 engine, -6-inch wheels, and Piper PA-18 horizontal tail surfaces.	SW	01575	Aerial Repairing P.O. Box 909 Ponca City, OK 74601
PA-14 Series; T.C. 797	SA398AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-14 Series; T.C. 797	SA469AL	Installation of electric fuel gauges. Amended 5/1/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-14 Series; T.C. 797	SA477AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-14 Series; T.C. 797	SA477AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-14 and Seaplane Versions; T.C. 797	SA496AL	Installation of leading edge cuff. Amended 3/4/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA502AL	Installation of cargo door in right side of aircraft. Amended 10/31/73.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-14; T.C. 797	SA505AL	Installation of landing gear safety cables. Issued 10/1/73.	AL	30250	F. Atlee Dodge Aircraft Maintenance 2301-1/2 Merrill Field Drive Anchorage, AK 99502
PA-14; T.C. 797	SA528AL	Installation of welded steel rear float fittings. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA534AL	Installation of auxiliary fuel tank. Amended 2/7/75.	AL	75500	W.I. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99503
PA-14; T.C. 797	SA538AL	Installation of modified landing gear (PA-18 type) with main landing gear legs lengthened 6 inches. Issued 1/30/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
t+1 PA-14; T.C. 797	SA541AL	Installation of O-360-A2A Lycoming engine and McCauley 1A200 DFA 82-45 propeller. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA546AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-14; T.C. 797	SA546AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA548AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-14; T.C. 797	SA548AL	Installation of Piper PA-18 type landing gear. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA562AL	Installation of Day & Night 2-4 aluminum engine cowling. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-14; T.C. 797	SA562AL	Installation of Day & Night 2-4 aluminum engine cowling. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA567AL	Installation of O-320-A2B Lycoming engine. Issued 11/21/75.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-14; T.C. A-797	SA598AL	Installation of Day & Night modified flap control system.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-14; T.C. A-797	SA598AL	Installation of Day & Night modified flap control system.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-14; T.C. 797	SA630AL	Install fiberglass wing tip assembly. Issued 4/28/78.	AL	20512	Charles C. Center 8134 LAke Otis Parkway Anchorage, AK 99507
PA-14; T.C. A797	SA645AL	Install Avco Lycoming O-320-D2A or O-320-B2B engine and McCauley 1A175/GM8246 prop. Issued 7/31/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. A797	SA647AL	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA657AL	Install Avco Lycoming O-320-A2B or O-320-E2D engine and McCauley 1A175/GM 8246 propeller. Issued 11/27/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA686AL	Installation of PA-18 main landing gear. Issued 7/6/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-14; T.C. 797	SA688AL	Installation of left side cabin door. Issued 7/16/80.	AI	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA690AL	Increase gross weight to 1,935 lbs. Issued 7/8/80.	AI	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA3213WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avneue Torrance, CA 90501
PA-14, PA-18, PA-20; T.C. 797, 1A2, 1A4	SA41AL	Six inch wheels and brakes.	GL	56570	Wesley W. Mathias 154 North Broad Street Bremen, OH 43107
PA-15; T.C. 800	SA1-619	Continental A-65-8F engine and McCauley 1A90CF-7147 propeller.	NE	39514	Griswold Air Service Griswold Airport Madison, CT 06443
PA-15; T.C. 800	SA4-1225	Eonite covering on complete aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-15; T.C. 800	SA69AL	Installation of fuel tanks. Amended 2/7/75.	AI	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-15; T.C. 800	SA3214WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-15, PA-17; T.C. 800, 805	SA4-1025	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-16 Series; T.C. 1A1	SA1-577	Installation of Sensenich controllable pitch propeller Model CS3FM4/C374E. Amended 6/24/70.	EA	64268	Theodore J. Peters County Line Road, RD 3 Sommerville, NJ 08876
PA-16 Series; T.C. 1A1	SA4-900	Ceconite 101 covering of wings, fuselage, ailerons, elevator and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-16 Series; T.C. 1A1	SA399AL	Conversion of 4" wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-16 Series; T.C. 1A1	SA412NW	Replace original equipment expander-tube brakes with new Cleveland wheels and brakes. Issued 3/3/77.	NW	00300	Michael J. Abdo 9415 Lexington Avenue, S.W. Tacoma, WA 98498
PA-16 Series; T.C. 1A1	SA3215WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-16, -16S; T.C. 1A1	SA447AL	Installation of auxiliary fuel tanks in right wing. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-16, -16A; PA-18, PA-18S, "105", "125", "135", "150"; "PA-18A"135", "150:"; PA-18AS"125", "135", "150"; PA-19S; PA-23, -23-160, -235, -23-250; PA-24, -24-250, -260; PA-28-140, 150, 160, 180, -235, PA-28-S-160, -S-180; PA-30; T.C. 1A1, 1A2, 1A10, 1A15, A1EA. 2A13	SA630WE	Installation of Coast Winslow Filter Corporation 409 series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-282	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-327	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16S; T.C. 1A1	SA384AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/17/70.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-17 Series; T.C. 805	SA4-483	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-17 Series; T.C. 805	SA446AL	Installation of fuel tanks. Amended 2/7/75.	AL	17000	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-17 Series; T.C. 805	SA3216WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-18 Series; T.C. 1A2	SA388EA	Lycoming O-320 engine.	EA	61075	J. Arlington Myers 228 East Keller Street Castanea, PA 17726
PA-18 Series; T.C. 1A2	SA425AL	Installation of removable seat back support. Issued 4/23/71.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99503
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18 Series; T.C. 1A2	SA526AL	Build up 1-1/4" axle to 1-1/2" axle to install Celveland wheel and brake. Issued 8/7/74.	AL	68436	Bill Robek Box 10-214 Klatt Station ANchorage, AK 99502
PA-18 Series; T.C. 1A2	SA540AL	Installation of modified landing gear with main gear legs lengthened 6 inches. Issued 2/19/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18; T.C. 1A2	SA682AL	Installation of 160 hp Lycoming O-320. Issued 6/26/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18; T.C. 1A2	SA1586CE	Modified brake master cylinder. Issued 5/9/80.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-18 Series; T.C. 1A2, AR-7	SA1-32	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
t+1 PA-18 Series; T.C. 1A2, AR-7	SA1-41	McCauley fixed pitch MET-L-PROP 1A170/GM7450, 1A170/GM7452 and 1A170/GM7454 propellers with Lycoming O-320-A1A engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-59	McCauley fixed pitch MET-L-PROP 1A170/GM7448 and 1A170/GM7450 with Lycoming C-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-155	McCauley fixed pitch MET-L-PROP 1A170/GM7448 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell AVenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-156	McCauley fixed pitch MET-L-PROP 1A170/GM7446 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-349	Glider tow. Amended 5/12/67.	EA	70400	Schweizer Aircraft Corporation Box 147, County Airport Elmira, NY 14902
PA-18 Series; T.C. 1A2, AR-7	SA4-254	Hartzell HC82XG-6/7636D-4 propeller Lycoming 70385 dual drive assembly, Woodward 210115 single acting governor and J-6230-1 lord mount assembly.	WE	15415	Ellen Belotti 1208 East Charleston Road Las Vegas, NV 89114

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18 Series; T.C. 1A2, AR-7	SA4-364	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-18 Series; T.C. 1A2, AR-7	SA4-1644	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-18 Series; T.C. 1A2, AR-7	SA5-31	Auxiliary baggage tube.	AL	17000	M.R. Borer 1307 West 39th Place Spenard, AK
PA-18 Series; T.C. 1A2, AR-7	SA4AL	Installation of auxiliary wing fuel tanks. Amended 5/20/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
PA-18 Series; T.C. 1A2, AR-7	SA4RM	Installation of modified landing gear, Cleveland P/N 40-84 wheels and P/N 30-41 brakes. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-18 Series; T.C. 1A2, AR-7	SA17RM	Replace landing gear vee for PA-18 series P/N 10033. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-18 Series; T.C. 1A2, AR-7	SA24EA	Conversion of aircraft for parachute jumping and aerial photography operations.	EA	61075	J. Arlington Myers 331 North Water Street Mill Hall, PA 17751
PA-18 Series; T.C. 1A2, AR-7	SA44AL	Auxiliary wing fuel tanks.	AL	86070	Joseph Wilbur P.O. Box 931 Anchorage, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA50AL	Cowl flaps.	AL	05960	Aircraft Repair & Maintenance Co. P.O. Box 6207 Anchorage, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA70EA	Edo 339JHS amphibious floats.	EA	61622	North American Flying Service, Inc. Bergen Turnpike Little Ferry, NJ 07643
PA-18 Series; T.C. 1A2, AR-7	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Co. airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
PA-18 Series; T.C. 1A2, AR-7	SA141AL	Removal of agricultural hatch.	AL	45000	Jake's Aircraft Salvage 3906 Barbara Drive Spenard, AK 99503
PA-18 Series; T.C. 1A2, AR-7	SA143AL	Enlarged instrument panel.	AL	30250	F.A. Dodge P.O. Box 6409 Anchorage, AK 99506
PA-18 Series; T.C. 1A2, AR-7	SA150AL	Installation of cockpit operated cowl flap winterization kit. Reivsed 7/29/69.	AL	39400	Charles L. Gray 319 Slater Street Fairbanks, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA230EA	Flottorp controllable pitch propeller.	EA	11730	Arnold Air Service Dale & Mackey Road, RD 2 Gasport, NY 14067
PA-18 Series; T.C. 1A2, AR-7	SA234SW	Alteration of method of attaching spray plates and dust spreader to spray tank and alteration of emergency dump cable hookups.	SW	42480	John L. Horne, Jr. P.O. Box 218 Webbers Falls, OK 74470
PA-18 Series; T.C. 1A2, AR-7	SA284SW	Landplane lower cowl on aircraft with Edo 89-2000 floats.	SW	72752	Slidell Aviation Services Route 2, Box 99 Slidell, LA 70458
PA-18 Series; T.C. 1A2, AR-7	SA324CE	Manufacture hitch and bracket. Install tow hitch. Amended 5/6/71.	CE	76500	Stubben-McCandless South Omaha Airport Route 1 Papillion, NE 68046
PA-18 Series; T.C. 1A2, AR-7	SA569SW	Cessna 172 landing gear.	SW	61100	Myhand and Deam Aircraft Route 5, Box 505 Pine Bluff, AR 71601
PA-18 Series; T.C. 1A2	SA894WE	Lycoming O-320-A2B engine and Sensenich M74DM-56 propeller.	RM	35770	Sam B. Flint P.O. Box 332 Holly, CO 81047
PA-18 Series; T.C. 1A2	SA1588CE	Modified airplane, widening fuselage and increasing gross weight. Issued 5/21/80.	CE	14752	B.A.R.F. Inc. P.O. Box 447 Clarence, MO 63437

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18, PA-18A; T.C. 1A2, AR-7	SA4-1430	125-gallon hopper and small swathmaster. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-18, PA-18A; T.C. 1A2	SA1243CE	Install Cleveland wheels and brakes and optional wheel fenders. Amended 9/29/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, -18A; T.C. 1A2	SA1244CE	Replace landing gear components. Issued July 1976.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, PA-19; T.C. 1A2, AR-7	SA3-180	C2200 main (hydraulically actuated) and CTF2200 or CT3000 tail skis.	GL	36030	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; 8yC. 1A2, AR-7	SA3-328	C-2200 main (manually actuated) and AWT2500 or AWT2500A tail wheel-skis.	GL	36060	FluiDyne Engineering Corp. Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA3-352	Model 3000 main skis and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA4-823	Eonite covering on entire aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-18, PA-19; T.C. 1A2, AR-7	SA4-986	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-18, PA-19, PA-20; T.C. 1A2, 1A4	SA3-423	CT-3000 tail ski on airplanes with Scott 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-20, PA-22; T.C. 1A2, AR-7, 1A4, 1A6	SA3-654	Laminated plastic and fiberglass nose.	RM	28500	Dakota Aviation Company P.B. Box 18 Huron, SD 57350
PA-18, PA-22, PA-23, PA-24 Series; T.C. 1A2, 1A6, 1A10, 1A15	SA1-383	Lube oil filter PB 55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
PA-18, -22, -23, -24, -25, -28 Series; T.C. 1A6, 1A2, AR-7, 1A10, 1A15, 2A13	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace AVenue Torrance, CA 90510
PA-18, PA-25; T.C. 1A2, AR-7, 2A8	SA673SW	All metal covering of aileron.	SW	60168	Luther W. Moore 1110 West 29th Street Plainview, TX 79072
PA-18, 90 thru 150; T.C. 1A2	SA753CE	Installation of skis.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
PA-18, -18A, -105, -125, -135, -150, 18A-135, -150; T.C. 1A2	SA400AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	GL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-18, -18"105", -18A, -18"125", -18"135", -18A-"135", -18"150", -18A-150, -19 and seaplane versions; T.C. 1A2	SA427AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65662
PA-18, -18"105", -18A, -18"125", -18"135", -18A-"125", -18"150", -18A-150, -19 and seaplane versions; T.C. 1A2	SA427AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18, -18A, -18-105, -18-125, -18-135, -18A-135, -18-150, and seaplane versions; T.C. 1A2	SA489AL	Installation of modified dog leg brace baggage compartment. Issued 10/24/72.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501

5900

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18, -18-105, -125, -135, -150, PA-18S, -18S-105, -125, -135, -150, PA-18A, -18A-135, -150, PA-18AS-125, -135, -150, PA-19, PA-19S; T.C. 1A2	SA624AL	Install fiberglass wing tip assembly. Issued 3/21/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, PA-18-105, -125, -135, -150, PA-18S, PA-18S-105, -125, -135, -150, PA-18A, -18A-135, -150, PA-18AS-125, -135, PA-19, PA-19S; T.C. 1A2	SA638AL	Fabricate rudder mounted strobe light support bracket. Issued 6/14/78.	AL	30250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18, -18-105, -125, -135, -150, PA-18, -18-105, -125, -135, -150, PA-18A, -18A-125, -18A-135, -150, PA-18AS-125, -135, -150; T.C. 1A2	SA641AL	Fabricate front wing spar butt attachment repair fitting. Issued 7/10/78.	AL	20514	Clinton C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, -18"105" Special, -18A, -18"125", -18"135", -18A"135", -18"150", -18A"150", -19; T.C. 1A2	SA900CE	Replace round wing tips with constant-chord, square tips and wing splates. Amended February 1975.	CE	35650	James W. Flanagan and Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18, -18A, PA-19; T.C. 1A2	SA1245CE	Installation of Scott master cylinder having Flanagan Aircraft conversion. Amended 6/22/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, -18A, -18-105, -18-125, -18-135, -18-150, -18A-150, PA-19; T.C. 1A2	SA2478WE	Installation of automatic flagman Model 5. Issued 2/14/72.	NW	03500	Air-Ag, Inc. Route 4, City County Airport Walla Walla, WA 99362
PA-18, -105, -125, -135, -150; T.C. 1A2	SA5-7	Install framing and seat in baggage compartment. Amended 7/25/68.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99501
PA-18, -18-105, -125, -135, -150, PA-18A-125, -135, -150; PA-19; T.C. 1A2	SA301AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99501
PA-18, -18"105", -18A, -18"125", -18"135", -18A"135", -18"150", -18A"150", PA-19 (Army L-18C); T.C. 1A2	SA3282WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-18, -18S, -18-135, -18S-135, -18A-135, PA-18-105 (Special), PA-18S-105 (Special), PA-18-150, -18A-150, -18S-150; T.C. 1A2	SA490AL	Installation of leading edge cuff. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, -18S, -18"105", "125", "135", "150", -18A, "135", "150", -18S"105", "125", "135", "150", PA-19, -19S, PA-22, -22-108, -135, -150, -160, -22S-135, -150, PA-24, -24-250, -260; T.C. 1A2, 1A6, 1A15	SA1033EA	Replace steel oil cooler lines with Aeroquip type 303-8 hose using AN-823-8D elbows, AN-816-8D nipples and AN-321-8 hose fittings. Issued 1/29/76.	EA	78472	Walter Thompson, Sr. 32 High View Avenue Florida, NY 10921
PA-18, -18-125, -18-135, -18-150; PA-19; T.C. 1A2	SA2468WE	Use of GCA-600 axle adapter assembly for installation of Cleveland Model 40-84A wheels and Model 30-41 brakes. Issued 1/20/72.	WE	15435	Ken Bemis Brawley Municipal Airport P.O. Box 1293 Brawley, CA 92227
PA-18A; T.C. 1A2	SA681AL	Installation of removable crossbar. Issued 1/10/80.	AL	30250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18A; T.C. 1A2	SA886CE	Metalize bottom of fuselage per Flanagan Aircraft Drawing List No. 2. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18A; T.C. 1A2	SA887CE	Removal of hopper cover and installation of Iexan skylight and side windows. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A; T.C. 1A2	SA888CE	Relocation of battery box and/or installation of an external power receptacle. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A, -18A-135, -18A-150; T.C. 1A2	SA5-29	Install third seat in baggage compartment and relocate battery aft of baggage compartment. Amended 7/25/68.	AI	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99503
PA-18A, PA-18A"135"; -18A"150"; T.C. 1A2	SA1369CE	Electrical system and instrument panel modification. Issued 9/28/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18S, -19S, -18S"105" (Special), -18S"125" -18S"135"; T.C. 1A2	SA3-96	Install Pee-Kay MOdel 1500 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-105, 18S-105, -125, 18S-125, -18AS-125, 18-135, 18S-135, 18A-135, -18AS-135; T.C. 1A2	SA136AL	Installation of Lycoming O-320 engine. Amended 5/14/68.	AI	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-105, -18S-105, -18-125, -18A-125, -18AS-125, -18A-135, -18S-135, -18AS-135; T.C. 1A2	SA292AL	Increased gross weights to PA-18-150 weights and C.G. envelope. Note: Airplanes must have Lycoming O-320 engine installed, except the PA-18-135 or PA-18-135 for which the engine change is optional. Amended 5/5/72.	AI	17000	W.T. Ellis and M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-105, -125, -135, -150, -18S, -105, -125, -135, -150, -18A-135, -150, -18AS-125, -135, -150, PA-16, PA-16S, PA-19S, PA-22, -108, -125, -150, -160; PA-23, -160, -250; PA-24, -250; PA-24-400; PA-28-160, -235; PA-30; T.C. 1A6, 1A10, 1A15, 2A13, A1EA	SA589WE	Installation of full-flow lube oil filters on the aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court San Leandro, CA 94577
PA-18S, PA-18S"105", -18S"125", -18AS"125", -18S"135", -18AS"135", PA-19S; T.C. 1A2	SA159CE	Installation of Pee-Kay Model 1800 floats. Reissued 6/12/74.	EA	29998	Pee-Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-125; T.C. 1A2	SA669CE	Install Aqua Model 1900 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Reserach and Engineering, Inc. 805 Geiger Road Zephyrhills Hills, FL 33599
PA-18-125, -18A, -18-135, -18A-135, -18-150, -18A-150, 18S-125, -18AS, -18S-135, -18AS-135, -18S-150, -18AS-150, T.C. 1A2	SA98AL	Installation of two auxiliary fuel tanks. Amended 2/7/75.	AI	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-18-125, -135, -150, -18S-125, -135, -150, 18A-135, -150, 18AS-135, -150; T.C. 1A2	SA117AL	Installation of Cunningham auxiliary fuel belly tank. Amended 9/16/68.	AI	08472	Airglas Engineering Co., Inc. P.O. Box 4165 Anchorage, AK 99502
PA-18-125, PA-18-135, PA-18A-135; T.C. 1A2	SA388EA	Installation of Lycoming O-320, O-320-A2A or C-320-A2B engine (150 hp) and Sensenich propeller M74DM-56 configuration I. Increase in maximum allowable gross weight and C.G. limits as per Model PA-18-150 values - configuration II. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-18S-125; T.C. 1A2	SA2397WE	Installation of McCauley Model 1A175-GM/8240 propeller. Issued 10/27/71.	NW	09300	Kenneth R. Alexander 1732 Northwest 64th Seattle, WA 98107

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18S"125", PA-18S-135, 18S-150; T.C. 1A2	S[illegible]79EA	Installation of Edo Model 88A-1650 seaplane floats with Edo Model 088A21 attachment gear. Reissued 4/1/76.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
PA-18S-125, -150; T.C. 1A2	SA1099WE	Install fiberglass reinforced plastic floats. Reissued 9/20/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
PA-18-135; T.C. 1A2, AR-7	SA1-33	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine. Amended 9/5/75.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-18-135, -18A-135, -18S-135, -18AS-135, -18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA279AL	Installation of McCauley 1A175/GM propeller on -135 models listed and installation of McCauley 1A175/GM 8241 through GM 8244 on the -150 models listed. Amended 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-135, -18A-135, -18-150; T.C. 1A2	SA518CE	Install Aqua Model 1900 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research and Engineering, Inc. 805 Geiger Road Zephryhills, FL 33599
PA-18"135", -18A"135", -18S-"135", -18AS"125", -18"150", -18A-"150", -18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622
PA-18"135", -18A"135", -18S-"135", -18AS"135", -18"150", -18A-"150", '18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1333CE	Installation of replacement engine mount. Issued June 1977.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1366CE	Installation of a third seat, removable cross member, and reinforced baggage compartment floor. Issued 8/26/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18-135, -150, PA-20, PA-22, PA-23, PA-24 less 24-180, -24-280, -24-400, PA-25, PA-28 less -28-140, PA-28-180, -235, PA-30, PA-31, PA-32, PA-34, PA-39; T.C. 1A2, 1A4, 1A6, 1A10, 1A15, 2A8, 2A10, 2A13, A1EA, A8EA, A3SO, 1A10, A1EA	SA1512WE	Installation of exhaust gas temperature monitoring system Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18-135, -150, PA-22, PA-23, PA-24, -24-400, PA-28, -28-235, PA-30, PA-31, PA-32; T.C. 1A2, 1A6, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18A-135, PA-18A-150; T.C. 1A2	SA1368CE	Cabin metalization; installation of new boot cowl, firewall, swing up side windows, larger baggage door, and inspection access in aft fuselage. Issued 9/12/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18S-135; T.C. 1A2	SA288AL	Install McCauley 1A175-GM8040 or 1A175-GM8044 propeller. Amended 4/2/69.	AL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645
PA-18-150; T.C. 1A2	SA36RM	Installation of Lycoming O-360-C2A or O-360-A3A 180 hp engine. Issued 11/22/74.	RM	46780	David C. Johnson 10850 Thomas Road Colorado Springs, CO 80908
PA-18-150; T.C. 1A2	SA532AL	Installation of Lycoming O-360-A2A engine. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-18"150"; T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-18"150"; T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18-150; T.C. 1A2	SA590AL	Install extended baggage compartment. Issued 7/2/76.	AL	39250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18-150; T.C. 1A2	SA596AL	Install Hartzell propeller Model HC-C2YL-1BF/F8468-8R. Issued 3/4/77.	AL	30250	Atlee R. Dodge P.O. Box 6409 Anchorage, AK 99509
PA-18-150; T.C. 1A2	SA612AL	Extended ailerons. Issued 5/25/77.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18"150", -18A"150", -18S"150", -18AS"150"; T.C. 1A2	SA4-1143	Installation of Lycoming O-320-A3B engine and Hartzell HC-82XL-6B/7636D-2 propeller. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
PA-18"150", -18A"150"; T.C. 1A2	SA92NW	Installation of Lycoming O-360-A2D engine, McCauley 1A200-FA8241 propeller, and associated sub-systems. Issued 3/1/74.	NW	32756	Ed's Aviation Service P.O. Box 156 Arlington, WA 98223
PA-18"150", -18A"150"; T.C. 1A2	SA109CE	Installation of Pee-Kay Model 1800 floats. Reissued 6/12/74.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-150, -18A-150; T.C. 1A2	SA349AL	Installation of McCauley 1A175-GM 8242, GM8244, or GM8246 propeller. Amended 4/10/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-18-150, -18A-150; T.C. 1A2	SA353AL	Installation of Sorensen Aircraft Co. 60-gallon belly tank. Revised 2/12/71.	AL	76900	Superior Airmotive of Alaska, Inc. 2301 Merrill Field Drive Anchorage, AK 99501
PA"18"150", PA"18A"150"; T.C. 1A2, AR-7	SA575WE	Belly master spray system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-18-150, -18A-150; T.C. 1A2	SA589AL	Install square horizontal stabilizers, elevators, and rudder. Issued 6/28/76.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA284AL	Installation of Hartzell propeller with Woodward 2100-80-RS governor. Amended 10/30/75.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA510AL	Installation of "Summer-all defroster valve". Issued 1/10/74.	AL	76738	Sumrall & Tears 3001 Yale Drive Anchorage, AK 99504
PA-18"150", PA-18S"150"; T.C. 1A2	SA648AL	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150", PA-18A"150", PA-18S"150", PA-18AS"150"; T.C. 1A2	SA649AL	Fabricate 30.5 gallon wing fuel tanks. Issued 8/17/78.	AL	30250	F. Atlee Dodge Box 4609 Anchorage, AK 99502
PA-18A-150; T.C. 1A2	SA623AL	Install wing tip assembly.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18A"150"; T.C. 1A2	SA1370CE	Revised fuel gaging and dual fuel feed line installation from both tanks. Two wing fuel tanks standard. Issued 11/18/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18S-150, 18AS-150; T.C. 1A2	SA392AL	Installation of McCauley 1A175 GM8242, 8244, or 8246 propeller. Amended 9/24/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-20 Series; T.C. 1A4	SA1-89	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engines.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-20 Series; T.C. 1A4	SA1-157	McCauley fixed pitch MET-L-PROP 1A170/GM7450 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-20 Series; T.C. 1A4	SA1-167	Lycoming O-320 150 hp engine, Sensenich M-74DM propeller, Piper PA-22-150 engine baffles, and and Harrison AP13SJ03-01 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamsport, PA 17701
PA-20 Series; T.C. 1A4	SA4-564	Eonite covering on wings, fuselage and control surfaces.	WE	52090	William C. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
t+1 PA-20 Series; T.C. 1A4	SA4-778	Ceconite covering.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-20 Series; T.C. 1A4	SA12RM	Installation of Light Plane Components landing gear vee assembly, P/N LPC 1012. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-20 Series; T.C. 1A4	SA31CE	Removal of rear left door and installation of placard.	CE	50725	Lincoln Sport Parachute Club, Inc. 929 Furnas Avenue Lincoln, NE 68501
PA-20 Series; T.C. 1A4	SA73CE	Covering with dacron of wings, fuselage, tail group, flaps, all control surfaces, or any of these individually.	GL	30518	Downer Aircraft Company P.O. Box 46 Alexandria, MN 56308
PA-20 Series; T.C. 1A4	SA211WE	Removal of left-hand cabin door for parachute jumping and aerial photography operations.	RM	38040	Glacier View Skyways, Inc. P.O. Box 252 Kalispell, MT 59901
PA-20; T.C. 1A4	SA224GL	Install Gerdes control wheels, Model No. A-1561-C and A-1562-C utilizing AN3-12 bolts (2), AN3-65 self-locking nuts (2) and AC-940-316 washers (2). Issued 2/15/78.	GL	64950	Matthew C. Poleski 25 Immelman Lane Hampshire, IL 60140
PA-20 Series; T.C. 1A4	SA278WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-20 Series; T.C. 1A4	SA509AL	addition of crankcase relief valve. Issued 11/16/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-20 Series; T.C. 1A4	SA542AL	Installation of leading edge cuff. Amended 3/4/77.	AL	27250	Crosswinds, Inc. 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20 Series; T.C. 1A4	SA671WE	BN-1 propeller spinner.	WE	75250	Raymond M. Stits 3665 Rubidoux Boulevard Riverside, CA 92502
PA-20 Series; T.C. 1A4	SA3217WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-20, PA-20-115, -20-135; T.C. 1A4	SA12AL	Installation of auxiliary fuel tank(s). Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2350 East Fifth Avenue Anchorage, AK 99501
PA-20 Landplane, -20-115, -135; T.C. 1A4	SA25EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lycons, WI 53148
PA-20, -20S; T.C. 1A4	SA125AL	Installation of squared off wing tips and end plates. Amended 12/1/65.	AL	61640	Northland Aviation P.O. Box 3143 Fairbanks, AK 99702
PA-20-115, -135; T.C. 1A4	SA401AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-20, PA-20S, -20-115, -20S-115, -20-135, -20S-135, and these models modified by STC SA1-167 (150 HP Lycoming O-320 engine); T.C. 1A4	SA396GL	Installation of Aero Ski wheel replacement skis in accordance with the following: 1) Model M1800 and M2000 skis, 2) Model M3000H skis. Issued 4/18/80.	GL	02750	Aero Ski Manufacturing Co., Inc. Box 346 Park Rapids, MN 56470

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-20, -20S, -20"115", -20S-"115", -20-"135", -20S-"135"; T.C. 1A4	SA479AL	Installation of fiberglass wing tips. Issued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-20, -20S, -20"115", -20S-"115", -20-"135", -20S-"135"; T.C. 1A4	SA479AL	Installation of fiberglass wing tips. Issued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-20, -20-115, -135, PA-20S, -20S-115, -135; T.C. 1A4	SA626AL	Install fiberglass wing tip assembly. Issued 3/21/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20, -115, -20S, -20S-115, -135, -20S-135; PA-22, -135, 22S-135, -150, 22S-150, -160, 22S-160, -108; PA-24, -250, -400, -260; PA28-140, -150, -160, -180, -235, S-160, S-180, R-180; PA-30; PA-32-260, -300, 32S-300; T.C. 1A4, 1A6, 1A15, 2A13, A1EA, A3SO	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
PA-20, PA-20"115", -"135", PA-20S"115", -"135", PA-22, 22-108, -135, -150, -160, 22S-135, -150, -160; T.C. 1A6	SA2142WE	Installation of DASCO heated pitot tube kit No. 2022-12.	WE	30129	Diversified Aviation Service Co. 20499 Santa Maria Avenue Castro Valley, CA 94546
PA-20, PA-20-"135"; T.C. 1A4	SA635AL	Install Avco Lycoming O-320-A2B engine and Sensenich propeller. Issued 6/6/78.	EA	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20-115, -20-135, PA-22, -22-135, -150, -160, -108, PA-23, -23-160, PA-24 S/N 1 thru 1476, PA24-250 S/N 1 thru 1476; T.C. 1A4	SA71GL	PA-20's install BA4106 filter assembly, PA-22's install BA4016 filter assembly, PA-23's, -24 install BA-3110 filter assembly, PA-24-250 install BA-3210 Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities Co. 9600 West 52nd Street Kenoska, WI 53140
PA-20-135; T.C. 1A4	SA1-24	McCauley fixed pitch MET-L-PROP Models 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine. Reissued 8/5/77.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-20S, PA-20-115, -22-135; T.C. 1A4	SA118GL	Installation of Huron Aviation Products alternator, P/N 10346 and regulator, P/N 10316. Amended 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-20S, 20S-115, 20S-135, PA-20S*; T.C. 1A4	SA385AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/21/70. *This approval includes PA20S models with Lycoming O-320, 150 hp engine installed per an appropriate STC.	AL	17000	M.P. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20S, -20S*, -115*, -135*; T.C. 1A4	SA387AL	Installation of McCauley 1A175GM8241 propeller. Issued 7/23/70. *Aircraft must be equipped with Edo 88-1650 floats and modified in accordance with STC SA1-167.	AL	17000	M.P. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20S-115, -125; T.C. 1A4	SA388AL	Installation of Edo 88-1650 floats (Spec item 209(a)) when modified per STC SA1-167 and SA387AL. Issued 8/3/70.	AL	17000	M.P. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20, PA-22 Series; T.C. 1A6	SA1-132	24ST alclad on wings.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-20, PA-22 Series; T.C. 1A6	SA1-133	24ST alclad skin on flaps.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-20, PA-22 Series; T.C. 1A6	SA1-325	Replacement of fabric covering with metal skins, ailerons and flaps.	EA	72100	Skycraft Design, Inc. P.O. Box 67 West Trenton, NJ 08628
PA-20, PA-22 Series; T.C. 1A6	SA1-492	Metallizing of wing panel excluding aileron and flap.	NE	27770	Custom Aircraft Industries 30 Broad Street Pascoag, RI 02859

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-20, PA-22; T.C. 1A4, 1A6	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
PA-20, PA-22 Series; T.C. 1A6	SA1487WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA1-22	McCauley fixed pitch propellers 1A170/GM7459 and 1A170/GM7457 with Lycoming O-320 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-23	McCauley fixed pitch propellers 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-90	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-109	69A110 gyro stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
PA-22 Series; T.C. 1A6	SA1-128	Dry vacuum pump 113A1 for counter-clockwise engine accessory drive and 113A2 for clockwise drive, or 10-113-1 and 10-113-2.	GL	66380	Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
PA-22 Series; T.C. 1A6	SA1-131	Dural angles and 24ST alclad skin on fuselage.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-22 Series; T.C. 1A6	SA1-255	Dart I-M turn control unit.	EA	61400	Navigation Devices, Inc. P.O. Box 1107 Binghamton, NY 13902
PA-22 Series; T.C. 1A6	SA1-275	Lycoming O-320 150 hp engine and Sensenich M74DM propeller, Piper PA-22-150 engine baffles, Harrison AP13SJ03 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamport, PA 17701
PA-22 Series; T.C. 1A6	SA1-337	Oil-free vacuum pump PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-22 Series; T.C. 1A6	SA1-386	Installation of heated pitot tube.	EA	34180	Federal Aviation Administration Engineering & Manufacturing Branch Federal Building, EA-210 JFK International Airport Jamaica, NY 11430
PA-22 Series; T.C. 1A6	SA3-77	Vertical fin plates attached to tip ribs of horizontal stabilizer for seaplane operation only.	GL	60092	Modern Die & Tool Company 227 Iron Street Detroit, MI 48233
PA-22 Series; T.C. 1A6	SA3-143	Grimes D7080-12 rotating beacon on fuselage access panel.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
PA-22 Series; T.C. 1A6	SA3-363	Installation of Doyn fiberglass wheel fairings. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
PA-22 Series; T.C. 1A6	SA3-382	Manually operated oil cooler shutter assembly.	CE	65020	Ken L. Potter 13831 Botts Road Grandview, MO 64030
PA-22 Series; T.C. 1A6	SA3-477	C2200 (hydraulically actuated) main and AWN1200A nose wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-22 Series; T.C. 1A6	SA3-494	C2200 (manually actuated) main and AWN1200A nose wheel -skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-22 Series; T.C. 1A6	SA3-631	Dacron cover.	GL	30518	Downer Aircraft Industries, Inc. Municipal Airport Alexandria, MN 56308
PA-22 Series; T.C. 1A6	SA3-639	Removal of rear door, operation with door removed, and reinstallation of door.	CE	50715	Lincoln Aviation Inst., Inc. P.O. Box 4168, Havelock Station Lincoln, NE 68529
PA-22 Series; T.C. 1A6	SA4-114	Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22 Series; T.C. 1A6	SA4-222	Fiberglass covering.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
PA-22 Series; T.C. 1A6	SA4-298	Fuselage structural alterations and additions to provide for the installation of Fairchild Aviation aerial camera A5A or similar.	WE	62063	Pacific Aero Industries Municipal Airport San Jose, CA 95125
PA-22 Series; T.C. 1A6	SA4-343	"B" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-22 Series; T.C. 1A6	SA4-391	Fiberglass wheel fenders.	NW	85550	Art Whitaker Pearson Field Vancouver, WA 98660
PA-22 Series; T.C. 1A6	SA4-423	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA4-815	Lycoming O-320 engine and Sensenich M74DM propeller.	NW	53200	McKenzie Aircraft Repair 1300 North 27th Street Springfield, OR 97477
PA-22 Series; T.C. 1A6	SA4-871	Aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-22 Series; T.C. 1A6	SA4-903	Ceconite 101 covering of fuselage, wings, horizontal and vertical stabilizer, ailerons, flaps, rudder and elevator.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-22 Series; T.C. 1A6	SA4-938	Eonite covering on entire aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-22 Series; T.C. 1A6	SA4-998	Installation of wheel fairings. Reissued 2/9/71.	NW	12565	Aurora Air, Inc. d/b/a Madras Air Service Madras, OR 97741
PA-22 Series; T.C. 1A6	SA4-1346	Fiberglass cover on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
PA-22 Series; T.C. 1A6	SA4-1502	AB-6564 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-22 Series; T.C. 1A6	SA4-1587	Retractable wheel fairing on main landing gear.	WE	30708	Duce Aircraft Company R.R. 4, Box 711 Valley Center, CA 92082
PA-22 Series; T.C. 1A6	SA4-1621	Removal of left-hand door for parachute jumping and aerial photography.	WE	19856	Capitol Sky Park, Inc. Municipal Airport Sacramento, CA 95855
PA-22 Series; T.C. 1A6	SA5-30	Rear door removed.	AL	69740	Safeway Airways P.O. Box 1062, Merrill Field Anchorage, AK 99500
PA-22 Series; T.C. 1A6	SA48AL	L1650A or I2000A skis.	AL	08125	Airglas Engineering P.O. Box 1254 Anchorage, AK 99502
PA-22 Series; T.C. 1A6	SA60CE	Model 1800 floats installed, Pee-Kay. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-22 Series; T.C. 1A6	SA91AL	Change of brake system to disc type as used on PA-22-108 by changing brake parts.	AL	75500	Stoddard Aero SErvice 2550 East Fifth Avenue Anchorage, AK 99501
PA-22 Series; T.C. 1A6	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743
PA-22 Series; T.C. 1A6	SA143EA	Univair Aeromatic F-200H/0074E propeller on aircraft utilizing Lycoming O-320 or O-320-A1A engine.	EA	53160	George A. McIntosh 435 Van Cortlandt Park Avenue Yonkers, NY 10705
PA-22 Series; T.C. 1A6	SA145CE	APU receptacle under the right front seat to the right of battery box.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis, MO 63155

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22 Series; T.C. 1A6	SA157CE	Jump seat baggage compartments.	CE	14270	Baker's Flying Service, Inc. 1025 Lou Holland Drive Municipal Airport Kansas City, MO 64108
PA-22 Series; T.C. 1A6	SA247SO	Removal of door during operation of aircraft.	SO	43260	W.E. Huckabee, Jr. 424 South Green Street Thomaston, GA 30286
PA-22 Series; T.C. 1A6	SA314SO	Lycoming O-290-D engine.	SO	54450	M & M Flyers Bessemer, AL 35020
PA-22 Series; T.C. 1A6	SA447WE	Torsc tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
PA-22 Series; T.C. 1A6	SA448CE	Prestolite ALK-5000 alternator.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
PA-22 Series; T.C. 1A6	SA461WE	Removal of right-hand door for parachute jumping and aerial photography operations.	NW	42138	Hillsboro Aviation Hillsboro, OR 97123
PA-22 Series; T.C. 1A6	SA481WE	Lycoming O-320-A1A engine and Sensenich M74DM propeller.	RM	47758	Kensair Corporation P.O. Box 332 County Airport Broomfield, CO 80020
PA-22 series; T.C. 1A6	SA666WE	Edo 88-1650 floats with Harrison oil cooler AP13SJ03-01 or AP12CU03-01, bottom engine cowl assembly 13159-8, side engine cowl 14237, reinforced fuselage 12480 and Sensenich M74DM or M76AM-2 propellers.	NW	36002	Floathaven Seaplane Base 2095 South Lake Whatcom Boulevard Bellingham, WA 98225
PA-22 Series; T.C. 1A6	SA819SW	Extended wing and fuselage.	SW	71776	Simpson Aviation Company P.O. Box 126 Gilliam, LA 71029
PA-22 Series; T.C. 1A6	SA1360CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, MO 66103
PA-22, PA-22-108, -135, -150, -22S-150, -22-160, -22S-160; T.C. 1A6 t+1	SA1-604	Installation of Aerostat external power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-22, -22-108 (Normal Category Only - All Models), -22-135, -150, -160; T.C. 1A6	SA45RM	Conversion from tri-cycle landing gear (nose wheel) to conventional landing gear (tail wheel). Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-22, PA-22-108, -135, -150, -160; T.C. 1A6	SA232GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-22, -22-108, -22-135, -22S-135, -22-150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA395GL	Installation of Aero Ski wheel in accordance with the following: 1) Model M180 and M2000 skis 2) Model M3000H skis. Issued 4/18/80.	GL	32750	Aero Ski Manufacturing Co., Inc. Box 346 Park Rapids, MN 56470
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA625AL	Install fiberglass wing tip assembly. Issued 3/27/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-22, -22-108, -22-135, -22-150, -22-160, -22S-150, -22S-160; T.C. 2A6	SA536AL	Installation of auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-22, -22-135, -150, -160; T.C. 1A6	SA26EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-108, -135, -22S-135, -22-150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA40EA	Wet-to-dry vacuum pump conversion kit 300-1. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-22, -22-108 (Normal Category only - all models), -22-135, -22-150, -22-160; T.C. 1A6	SA181RM	Installation of Lycoming Model O-360-A4A engine and Sensenich Model 76EM8-60 propeller. Issued 8/2/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-108; T.C. 1A6	SA847EA	Installation of Lycoming O-320-A (150 hp) or O-320-B (160 hp) engine. Amended 4/7/78.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-108, -135, -150, PA-23, -23-250, PA-24, -24-250, -260, -400, PA-28-140, -150, -160, -180, -235, PA-30; T.C. 1A6, 1A10, 1A15, 2A13, A1EA	SA1202WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
PA-22, -22-135; T.C. 1A6	SA1-274	Installation of Lycoming O-320 (150 hp) series engine and Sensenich M74DM propeller. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-135; T.C. 1A6	SA3-709	Install Piper control modification kit, P/N 754-174.	GL	51770	Richard E. Lloyd Lloyd Flying Service Schaumburg Airport, Box 79B Roselle, IL 60172
PA-22-108, -135, -150, -160 (landplane only - normal category only); T.C. 1A6	SA4-1263	Installation of conventional landing gear. Reissued and amended 12/4/79.	WE	52543	Lucas Aircraft 1125 Terrace Drive Napa, CA 94558
PA-22-150; T.C. 1A6	SA545AL	Installation of leading edge cuff. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-150; T.C. 1A6	SA703CE	Install aileron and wing fences and booster tips per STC SA573SW. Issued 5/19/70.	GL	22210	Dr. Edward W. Chrencik 29 9th Avenue North Hopkins, MN 55343
PA-22S-150; T.C. 1A6	SA297AL	Installation of McCauley 1A175 GM8241 propeller.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-22-160; T.C. 1A6	SA95NW	Installation of Lycoming O-360-A1A engine, McCauley 1A200-FA8248 propeller, and associates sub-systems. Issued 3/11/74.	NW	61680	Northwest Aero Aircraft Services 2036 West Bakerview Road Bellingham, WA 98225
PA-22, PA-23, PA-24 Series; T.C. 1A6, 1A10, 1A15	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ 85642
PA-23 Series; T.C. 1A10	SA1-5	Unfeathering system change to HC-82XL-2/7636D-4 or HC-A2XL-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
PA-23 Series; T.C. 1A10	SA1-6	Unfeathering system change to HC-82XG-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
PA-23 Series; T.C. 1A10	SA1-28	Radio rack limited to 30 pounds of radio equipment.	GL	03600	Airborne Communications, Inc. Lunken Airport Cincinnati, OH 45275
PA-23 Series; T.C. 1A10	SA1-53	Conversion to Goodyear 6.50-8 wheels (9531319) and brakes (9531779).	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-103	Radio-shelf.	GL	72494	Skyways, Inc. P.O. Box 175 Vandalia, OH 45377
PA-23 Series; T.C. 1A10	SA1-117	Propeller anti-icing kit.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA1-120	F-300 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
PA-23 Series; T.C. 1A10	SA1-137	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA1-169	Reinforcement of floor structure between fuselage station 91-1/2 and 123-3/4 and provision for tie-down facilities.	GL	60485	A.E. Muhlhauser 1602 Emerson Avenue (N.C.H.) Cincinnati, OH 45275
PA-23 Series; T.C. 1A10	SA1-177	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-399	Oil-free vacuum PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-23 Series; T.C. 1A10	SA1-468	Six or 13 quart propeller anti-icing kit WAP-101A, revision 2.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA1-484	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-485	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-534	Lightweight reservoir type deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-548	SP-3 autopilot EB2597034.	EA	74590	Sperry Rand Corporation MacArthur Field Ronkonkoma, NY 11779
PA-23 Series; T.C. 1A10	SA1-586	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-23 Series; T.C. 1A10	SA3-94	Narco 1016 antenna and/or remote compass transmitter, equipment shelf, oxygen bottle mounting.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705
PA-23 Series; T.C. 1A10	SA3-158	Radio power pack on bulkhead forward of instrument panel.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705
PA-23 Series; T.C. 1A10	SA3-334	Installation of aerial camera provisions. Reissued 1/31/80.	SW	26230	Cooper Airmotive Aircraft Services 3300 Love Field Drive Dallas, TX 75235
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-handy hydrotrim aileron trim device.	GL	30465	Kingsley A. Doutt 115 West Maple Street Alpena, MI 49707 AND
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-hand hydrotrim aileron trim device.	GL	64262	Charles L. Petch Hubbard Lake, MI 49747
PA-23 Series; T.C. 1A10	SA3-509	L-2B autopilot with or without altitude control and approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-23 Series; T.C. 1A10	SA3-564	Propeller unfeathering accumulator.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA3-641	Cabin air temperature control system.	GL	82500	Vap-Air Division Vapor Corporation 6444 West Howard Street Chicago, IL 60607
PA-23 Series; T.C. 1A10	SA3-644	Adams Rite 2302 rev. C-2 handle on inside of cabin door.	CE	65301	Product Development Group 2522 East Douglas Wichita, KS 67202

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers and increase gross weight to 3,684 lbs.	CE	56868	Galen D. Means 847 Watson Lane Wichita, KS 67201
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers and increase gross weight to 3,684 lbs.	SW	67016	AND Jackson M. Reed 607 North Peters Norman, OK 73069
PA-23 Series; T.C. 1A10	SA4-299	Windows at station 144.	WE	79877	Hamilton Aircraft Company, Inc. 6501 South Park Avenue Tucson, AZ 85706
PA-23 Series; T.C. 1A10	SA4-345	"B" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-23 Series; T.C. 1A10	SA4-522	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA4-652	Full flow aerofilter kit 3-1A101.	WE	96625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-23 Series; T.C. 1A10	SA4-783	Lycoming 150 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-23 Series; T.C. 1A10	SA4-994	Installation of Firestone Model DFA-233 wheel assemblies, Model CFA-299 brake assemblies and 6.50x8 6-ply tires.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1016	Lycoming 160 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-23 Series; T.C. 1A10	SA4-1131	SP-3 autopilot, less altitude and navigation hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85000
PA-23 Series; T.C. 1A10	SA4-1166	Installation of Firestone Model DFA-188 wheel.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1602	Dorsal fin.	RM	60280	Mountain States Aviation, Inc. Stapleton Field Denver, CO 80202
PA-23 Series; T.C. 1A10	SA2WE	Fuel pressure warning lights.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
PA-23 Series; T.C. 1A10	SA47CE	Governor 210413.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA65EA	One Aerojet-General 15NS-250 aircraft rocket engine on underside of fuselage on airplane centerline aft of main spar wing and relocation of cabin air intake scoop assembly.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361
PA-23 Series; T.C. 1A10	SA69SW	Extended nose with baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA100SW	Automatic pilot AK114.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA114SW	Combustion monitor.	EA	60100	Monitair Corporation Ramapo Valley Airport Spring Valley, NY 10977
PA-23 Series; T.C. 1A10	SA140SW	Cabin window addition.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA172EA	Reinforcement of rearmost seat and installation of additional safety belt.	EA	16804	Walter E. Hoffman, Jr. Birchwood Lodges & Cottages East Stroudsburg, PA 18301
PA-23 Series; T.C. 1A10	SA202SO	Fyr-Fyter 23-4, 2 1/2 lb., dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA219EA	Installation of Katz integrated flight indicator Model KIFI-2 or KIFI-2A. Amended 5/21/69.	NE	36300	Forest City Aviation Services, Inc. 749 Congress Street Portland, ME 04102
PA-23 Series; T.C. 1A10	SA226EA	Added structure aft of cabin area.	EA	67000	Reding Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23 Series; T.C. 1A10	SA232EA	Installation of Tactair omni lock Model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair model omni lock Model OL-1). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA242SO	Two-place couch.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA243EA	13-quart propeller anti-icing kit WAP-102.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA244SO	PA-23-250 wing root and nacelle fairings.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA250WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA266SO	Modification of fuel cap 16097-00 by making a new cover and enlarging the lower vent hole. Rework fuel cell filler neck door 19049-06 by putting a spring loading vent in the door to be used as auxiliary vent during icing conditions.	SO	12700	Avco Corporation Aerospace Structures Division Nashville, TN 37202
PA-23 Series; T.C. 1A10	SA268WE	Sixth seat and emergency exit.	WE	60095	Monarch Aviation Associates P.O. Box 527 Monterey, CA 93940
PA-23 Series; T.C. 1A10	SA280SW	Forward fuselage section and long nose 30542-02.	SW	79794	Tulsa Airmotive, Inc. P.O. Box 176 Broken Arrow, OK 74012
PA-23 Series; T.C. 1A10	SA309WE	Non-icing fuel tank vents.	WE	08750	Aircraft Tank Service, Inc. 1201 Cohasset Street Burbank, CA 91504
PA-23 Series; T.C. 1A10	SA311SW	Alternate static source.	SW	71800	Sinclair Oil & Gas Company Aviation Department, Box 521 Tulsa, OK 74101
PA-23 Series; T.C. 1A10	SA319EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA337EA	Conversion of aircraft electrical system to 24 volt.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23 Series; T.C. 1A10	SA339SW	Electrical hydraulic pump. Reissued 9/20/77.	SW	90142	The Zee Company, Inc. 123 Braniff Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA363SW	Pitch trim system AK120.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA371SW	Fiberglass nose cone.	SW	70750	Sequin Aviation Route 1, Box 225A Sequin, TX 78155
PA-23 Series; T.C. 1A10	SA372EA	Automatic flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-23 Series; T.C. 1A10	SA376WE	Left and right third window.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA387WE	Sixth seat and escape hatch.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA394WE	Replacement engine nose cowls.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA395WE	Lycoming O-360-A1A engines and Hartzell HC-C2YK-2R/7666-2 propellers.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA412WE	One-piece windshield.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA417SW	Rear baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA423SW	Fiberglass landing gear doors.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA461SW	Ramshorn type control wheel.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA462SW	One-piece windshield.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA463SW	Landing gear wheel well doors.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA465SW	Pitch trim system AK148.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA471CE	Dorsal fin.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23 Series; T.C. 1A10	SA476SW	Pitch trim system AK151.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA484SW	Large baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA497SW	Fiberglass engine nose cowl.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA498SW	Dual brakes.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA499SW	Engine nacelle and fuselage wing root fairings.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA504WE	11016 fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA523SW	Automatic trim system AK165.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA539WE	Turbosupercharged Lycoming IO-540-C1B5 or -C1C5 engine. Amended 6/14/66.	WE	66250	Rajay Corporation 2062 East Wardlow Raod Long Beach, CA 90807
PA-23 Series; T.C. 1A10	SA540SW	Piper auto-control III Model AK162 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA551WE	Installation of Brittain Model B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA557SW	Fiberglass nose cone.	SW	44930	J & G Aero Company P.O. Box 3031 Tyler, TX 75701

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA566SW	AK184 automatic flight system, AK185 stabilizer, and AK188 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA574SW	Rear baggage door.	SW	61500	Mayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA580SW	Modified engine mounts.	SW	67650	RFB Company, Inc. Chandler Field Purcell, OK 73080
PA-23 Series; T.C. 1A10	SA590SW	Gross weight increased.	SW	61500	Mayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA597SW	Extended nose with baggage compartment. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA598SW	Wheel well doors. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA599SW	Fiberglass engine nose cowls.	SW	59500	James W. Miller 6517 Moss Oak San Antonio, TX 78229
PA-23 Series; T.C. 1A10	SA600SW	Nacelle and wing root fairings. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA605SW	Rear baggage door.	SW	61500	Mayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA612SW	Square wing tips. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA613SW	Dorsal fin and square tip fin and rudder. Amended 7/31/68.	SW	50500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA614WE	D-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA615WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A0	SA616WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA617WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA636SW	MOdified nose, gear doors, nacelle fairings, and wing tips.	SW	70750	Sequin Aviation Route 1, Box 225 Sequin, TX 78155
PA-23 Series; T.C. 1A10	SA671SW	Dorsal fin and square rudder.	SW	70750	Sequin Aviation Route 1, Box 225 Sequin, TX 78155
PA-23 Series; T.C. 1A10	SA697SW	One-piece windshield. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA698SW	Rear picture window.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78116
PA-23 Series; T.C. 1A10	SA747SW	Pitch trim AK228 (manual).	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA764WE	Aztec "B" nose section.	RM	08315	Airport Development Corp. 5120 West Rowland Avenue Littleton, CO 80120

Aircraft Make, Model & T.C. No.	STC No.	Description	PG	STC Code	STC Holder
PA-23 Series; T.C. 1A10	SA774SW	Franklin 6A-350-C1 engines, McCauley 2AF31C10/84SF-8 propeller increase gross weight 3675 lbs. takeoff, 3500 lbs. landing. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA803SW	Dual brakes. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA824WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA852WE	Turbosupercharged Lycoming O-540-A1B5, -A1D5, or -A3D5 engines (S/N's 27-1 thru 27-2504).	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA867SW	Lycoming O-540-A1D5 engines.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA882EA	Installation of supplemental strobe light Grimes P/N 30-0437-100. Amended 5/2/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23 Series; T.C. 1A10	SA909WE	Turbosupercharged Lycoming IO-540-J4A5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA953SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23 Series; T.C. 1A10	SA978WE	Turbosupercharged Lycoming IO-540-C4B5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA1076CE	Installation of Halon 1301 cabin fire extinguishing system and engine nacelle fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64105
PA-23 Series; T.C. 1A10	SA1348WE	B-4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA1480WE	Installation of an integral 24 gallon auxiliary fuel tank in each wing tip.	WE	58500	Met-Co-Aire 3848 Campus Drive Newport Beach, CA 92660
PA-23 Series; T.C. 1A10	SA1486WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA2914WE	Installation of improved rudder trim tab actuating rod. Issued 8/13/74.	WE	13800	Aviation Research Corporation P.O. Box 718 Santa Ynez, CA 93460
PA-23, -23-160; T.C. 1A10	SA4-1637	Installation of turbosupercharged Lycoming O-320-A or -B series engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23, -23-160; T.C. 1A10	SA2CE	Installation of Doyn Model 1600 dorsal fin. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23, PA-23-160; T.C. 1A10	SA265CE	Lycoming IO-360-B1B engines and Hartzell HC-C2YK-2RA/7666A-2 propellers. Gross weight increase to 3,684 lbs. on PA-23 and to 4,000 lbs. on PA-23-160. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23, -23-160; T.C. 1A10	SA802CE	Alter tip of vertical fin and rudder. Amended August 1976.	CE	60174	J.J. Morelli Route 1, Box 138 Platte City, MO 64079
PA-23, -23-160; T.C. 1A10	SA897SW	Fiberglass propeller spinners. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA898SW	Revised engine cowling. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA1260WE	Installation of turbosupercharged Lycoming O-360-A1A or A1D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RO	STC Code	STC Holder
PA-23, -23-160; T.C. 1A10	SA1306SW	Lycoming IO-360-C1C engines with Hartzell HC-C2YK-2/C7666A-4 propellers with gross weight increase. Issued 5/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23, -23-160; T.C. 1A10	SA2793SW	Rudder hinge reinforcing bracket. Issued 6/7/74.	SW	70750	Sequin Aviation, Inc. 2075 Highway 46 Sequin, TX 78155
PA-23, -23-160; T.C. 1A10	SA3099SW-D	Mitchell automatic flight system AK587 consisting of Century I autopilot with optional omni tracker. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3100SW-D	Mitchell automatic flight system AK588 consisting of Century III with optional radio coupler and glide slope coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3101SW-D	Mitchell automatic flight system AK586 consisting of Century IID autopilot with optional radio coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160, -23-235, -23-250, PA-24, -24-250, -24-400, PA-28-150, -28-160, -28-180, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, PA-23-235, PA-23-250; T.C. 1A10	SA136EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, -235, -250; T.C. 1A10	SA236CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-23, -23-160, -23-235; T.C. 1A10	SA317EA	Radome kit No. 2025R-B for Bendix RDR-100 or RDR-110 series radar systems with 12-inch antenna per Chamberlain installation. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23, -23-160, -235, PA-25; T.C. 1A10	SA362SW	Rear baggage compartment. Reissued 4/24/79.	SW	70750	Sequin Aviation 2075 Highway 46 Sequin, TX 78155
PA-23, -160, -235; T.C. 1A10	SA398CE	Install Hoskins twilighter Mk III supplemental lighting system consisting of Model F wing lights with Model P or R (dual) tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1180 North Batavia Orange, CA 92667
PA-23, 23-160, 23-235, 23-250; PA-24, -24-250, -260, -400; PA-31, -31P; T.C. A8EA, 1A10, 1A15	SA660WE	Installation of HRD-type fire extinguishing system. Amended 7/11/77.	WE	43190	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91015
PA-23, -160, -235; T.C. 1A10	SA694SW	Nacelle saddleback. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23-160, -235, -250; PA-30, PA-39; T.C. 1A10, A1EA	SA890EA	Installation of Grimes three light strobe kit P/N 30-0101-2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23, -23-160, -23-235, -23-250, -E23-250, PA-24, -24-250, -24-260, -24-400, PA-28-140, -28-150, -28-160, -28-180, -28-235, -28S-160, -28S-180, -28R-180, -28R-200, PA-30, PA-39, PA-32-260, -32-300, -32S-300, PA-30, PA-39; T.C. 1A10, 1A15, 2A13, A1EA, A3SO	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light system two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 11/30/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23, -160, -235, -250; PA-24-180, -250, -400; *PA-28-140, -150, -160, -180, -235; *PA-31; T.C. 1A10, 2A13, A8EA	SA1290WE	Installation of "Quazar" high intensity supplemental exterior flashing lights. Amended 11/25/69. *Approved anti-collision light system is required.	RM	66000	Radair, Inc. 5665 South Curtis Street Littleton, CO 80120
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SW	67016	AND Jackson M. Reel 607 North Peters Street Norman, OK 73069
PA-23-160; T.C. 1A10	SA47SO	Installation of one-piece instrument panel.	SW	68145	Riley International Corporation 6211 West Northwest Highway Dallas, TX 75225
PA-23-160; T.C. 1A10	SA68NW	Installation of cargo door on right side of fuselage. Issued 10/30/73.	SC	70280	Elbridge P. Sawyer P.O. Box 148 Dayton, OH 37321
PA-23-160, -235, -250; T.C. 1A10	SA162SW	Cabin emergency exit window and sixth seat. Reissued 10/3/78.	SW	70750	Seguin Aviation, Inc. 2075 Highway 46 Seguin, TX 78155
PA-23-160; T.C. 1A10	SA272CE	Installation of Lycoming IO-360-B1A engines and Hartzell HC-C2YK-2RA/7666A-2 propellers. Gross weight increase to 4000 lbs. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-235; T.C. 2A10	SA1136SW	Fiberglass fuselage shell.	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
PA-23-235; T.C. 2A10	SA1205SW	Manual electric trim AK268. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235; T.C. 2A10	SA1746WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23-235; T.C. 2A10	SA1847WE	Installation of Brittain up-command signal adapter kit. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23-235, -250; T.C. 1A10	SA495CE	Installation of Hartzell Model HC-A3XK-2B/7636D-4 three-bladed propellers.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23-235, PA-23-250; T.C. 1A10	SA530WE	Installation of Rajay turbosupercharged Lycoming IO-540-C1B5 or C1C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23-235, -23-250; T.C. 1A10	SA1315SW	Dorsal fin. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-235, -23-250; T.C. 1A10	SA1361CE	Chrome plated brake disc installation. Issued 3/6/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA155EA	Install B.F. Goodrich pneumatic de-icing system. Amended 8/10/79.	GI	38500	B.F. Goodrich Engineered Systems Company 500 South Main Street Akron, OH 44318
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA921SW	Mitchell automatic flight system AK242 consisting of Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1091SW	Mitchell automatic flight director system FD/AP 282-184 consisting of flight director, automatic pilot, auto-flite AK 185.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, -23-250, -E23-50, Serial Nos. 27-1 thru 27-4573; T.C. 1A10	SA1124EA	Installation of enlarged cargo door. Reissued 8/25/78.	EA	26683	Courtesy Air Service, Inc. P.O. Box 561 Warren County Airport Glen Falls, NY 12801

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-235, -23-250 (S/N 271 thru 27-7554172), PA-E23-250 (S/N 27-2505 thru 27-7554172), PA-23-250 (Model "F") (S/N 27-7654001 and up); T.C. 1A10	SA1126EA	Installation of DeVore tel-tail lights on upper surface of stabilator. Reissued 9/28/78.	EA	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1262SW	Mitchell automatic flight system FD282-242 consisting of flight director/autopilot, and automatic pitch trim. Issued 2/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1276SW	Mitchell automatic flight system AK332, consisting of Piper autoflite II and omni tracker system. Issued 3/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1377SW	Mitchell automatic flight system AK340, consisting of Century I and optional tracker. Issued 10/14/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA2442WE	Installation of dual hydraulic pump (New Eastern Industries hydraulic pump 1233-HnG Type 311 on right engine; pump 1233-HnG Type 311 in lieu of existing pump on left engine). Amended 3/29/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, 23-250, PA-E23-250;	SA2445WE	Installation of recontoured inboard wing leading edge, stall fences, drooped ailerons in flaps down mode, rudder anti-servo tab system, and optional raked wing tips. Issued 11/16/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA3133SW-D	Mitchell automatic flight system AK599, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/7/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA3137SW-D	Mitchell automatic flight system AK611 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, -250; PA-24, -24-250, -260; PA-25, -25-235, -25-260; PA-28-150, -28-160, -28-180, -28-235; T.C. 1A10, 1A15, 2A8, 2A13	SA693CE	Replace existing engine induction air filter with AC Spark Plug Division filter.	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
PA-23-250; T.C. 1A10	SA11NE	Installation of laser sensor system. Issued 10/31/75.	NE	33485	Environmental Research and Technology, Inc. 696 Virginia Road Concord, MA 01742
PA-23-250; T.C. 1A10	SA39RM	Installation of freon air-conditioning system. Issued 4/23/75.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-23-250; T.C. 1A10	SA164CE	Installation of Hartzell HC-A3XK-2B/7636D-4 propellers and C-2513-2P spinners. Reissued 3/9/78.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-250; T.C. 1A10	SA179CE	Installation of the following: Lycoming IO-540-A1A5 or IO-540-G1A5 engines, Hartzell HC-A3XK-2C/8433-10 or HC-A3XK-2B/7636D-4 propellers. Reissued 3/9/79.	SC	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-250; T.C. 1A10	SA205GL	Installation of Aerosonic totalize fuel flow indication system in lieu of fuel pressure gages. Issued 12/19/77.	GL	73190	Roger Smith Aircraft Sales, Inc. Aurora Municipal Airport Sugar Grove, IL 60554
PA-23-250; T.C. 1A10	SA335CE	Installation of Honeywell H-14 YG-391 autopilot. Amended 9/9/66.	GL	42250	Honeywell, Inc. East 70th & 34th Avenue South Wold-Chamberlain Field Minneapolis, MN 55450

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250, S/N 27-2000 and subsequent; T.C. 1A10	SA427GL	Installation of Tull microwave landing system airborne equipment. Issued 7/23/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
PA-23-250; T.C. 1A10	SA429SO	Installation of Bendix Model FCS-80 automatic flight control system with manual electric pitch trim and flight director indicator. Amended 6/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA441NW	Installation of 3-bladed propeller and Piper Navajo spinner. Amended 1/12/78.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
PA-23-250; T.C. 1A10	SA480EA	Installation of photographic equipment.	NE	71400	James W. Sewall Company 147 Center Street Old Town, ME 04468
PA-23-250; T.C. 1A10	SA497SO	Installation of Bendix WLS-880 wings leveler system with and without Bendix FCS-810 automatic flight control system. Issued 11/8/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA590SO	Installation of M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA591SO	Installation of Bendix RNS-3400 area navigation system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250 (S/N 27-2505 and up); T.C. 1A10	SA621EA	Installation of a U.S. mail cargo kit. Amended 4/15/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23-250 (Aztec C, I, E); T.C. 1A10	SA663CE	Installation of Goodyear ice-guard de-icing kit Nos. 320-642. Reissued 4/17/72.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA667CE	Installation of wing and empennage deicing boot. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA668CE	Installation of wing and empennage deicing all weather antenna. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA688CE	Installation of propeller unfeathering system. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capitol Airport Springfield, IL 62705
PA-23-250; T.C. 1A10	SA850EA	Installation of radome kit 4025KX. Amended 9/12/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250; T.C. 1A10	SA922SO	Installation of Piper PA-23-250 "E" model fuselage nose. Amended 6/30/77.	SC	41400	Hawthorne Aviation Municipal Airport P.O. Box 10005 Charleston, SC 29411
PA-23-250 (Aztec F) defined by item VI in TCDS 1A10; T.C. 1A10	SA952SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA1022CE	Installation of King Model KGS-55 pictorial navigation system (compass), with optional KA-52 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1027CE	Installation of KCS-55 pictorial navigation system (compass), with optional KA-57 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250 (Landplanes) (S/Ns 27-2505 thru 27-74-05471); T.C. 1A10	SA1063CE	installation of two Hartzell HC-E3YR-2AF/FC7663-2R propellers and C-3269A or 82D3273P spinners. Reissued August 1976.	SW	03034	AeroStol Company 5104 Rector Fort Worth, TX 76133

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250; T.C. 1A10	SA1102CE	Installation of AP-107, 2-axis autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250; T.C. 1A10	SA1103CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250; T.C. 1A10	SA1163CE	Installation of KFC-200 automatic flight control system. Amended 6/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1314SW	Fiberglass extended nose. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-250; T.C. 1A10	SA1390CE	Install 1/4-inch plywood flooring over existing floor, remove 4 passenger seats, install reinforcement tubing. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250; T.C. 1A10	SA1391CE	Cutting and reattaching the left and right lower engine cowling with AN 2700-4 cam locks. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250 (S/N 27-2505 and up); T.C. 1A10	SA1444WE	Installation of Edo Model 679-4930 floats and addition of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663
PA-23-250; T.C. 1A10	SA1554CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1810WE	Installation of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663
PA-23-250; T.C. 1A10	SA3209SW-D	Mitchell automatic flight system, Piper altimatic X autopilot, AK684 or AK684FD, Piper altimatic X flight director autopilot with remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, Serial Nos. 27-2000 and up; T.C. 1A10	SA3823WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 4/28/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-23-250 (carbureted engine only); T.C. 1A10	SA4151WE	Installation of Silver Instruments fueltron IIIG-C or IIIP-C digital fuel flow and totalizer system. Issued 5/6/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-23-250 (S/Ns 27-2000 and up), -E23-250; T.C. 1A10	SA619EA	Installation of radome kit 3061K for Bendix FDR-100 or RDR-110. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-23-250, -E23-250; T.C. 1A10	SA20GL	Installation of Woodward electronic propeller synchronizer system. Amended 11/6/75.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA25GL	Installation of propeller unfeathering accumulator system on light twin-engine airplanes. Issued 6/26/73.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA51GL	Install Foster Airdata Systems, Inc. AD611/D area navigation system per STC. Reissued and amended 2/20/79.	GI	36520	Foster Airdata, Inc. 7020 Huntley Road Columbus, OH 43229
PA-23-250, -E23-250; T.C. 1A10	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 40355
PA-23-250, -E23-250 with counterweighted props, PA-31, PA-32-260, -31-325, -31-350, T.C. 1A10, A20SO, A3SO	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 1/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250, -E23-250; T.C. 1A10	SA430EA	Installtion of radome kit No. 3061X. Amended 11/12/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250, S/N 27-2000 and up, -E23-250; T.C. 1A10	SA1162EA	Installation of Silver Instruments fueltron IIIG or IIID digital fuel flow and tctalizer system. Amended 5/27/80.	WE	71740	Silver Instruments 2346 Stanwell Drive Concord, CA 94520
PA-23-250, -E23-250; T.C. 1A10	SW1524SW	Mitchell automatic flight system AK371 consisting of altimatic IIIB-1 autopilot with optional command/electric trim system with radio and glide slope couplers. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1571SW	Mitchell automatic flight system AK382 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 12/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1653SW	Mitchell automatic flight system AK372 consisting of AutoFlite II with optional tracking system. Issued 5/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3002SW-D	Automatic flight system AK479 consisting of Piper altimatic IIIC autopilot with optional command/automatic electric elevator trim servc altimeter, radio coupler, and glide slope coupler. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3003SW-D	Automatic flight system AK477 and AK477FD consisting of Century IV autopilot and Century IV flight director autopilot with command/automatic electric trim, and optional annunciator panel and servoed altimeter. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3005SW-D	Automatic flight system AK508 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3006SW-D	Automatic flight system AK494 and AK494FD consisting of Century IV autopilot and Century IV director autopilot and command/automatic electric elevator trim and optional annuciator panel. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3007SW-D	Automatic flight system AK504 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim, radic coupler, glide slope coupler. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3027SW-D	Mitchell command/electric trim system AK562. Issued 10/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3104SW-D	Mitchell automatic flight system AK583, consisting of Century IIB autopilot with optional radio coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3290WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/8/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA.95EA	Installation of Goodrich Electrothermal propeller de-icing system kit 77-170. Amended 10/27/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Co. 500 South Main Street Akron, OH 44318

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA840WE	Installation of Rajay Turbosupercharged Lycoming IO-540-C4B5 or -C4C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23 Series, PA-24 Series; T.C. 1A10, 1A15	SA230CE	Airspeed indicator landing gear warning system.	CE	74923	Standard Precision, Inc. 4105 West Pawnee Wichita, KS 67202
PA-23, PA-24, PA-28 Series; T.C. 1A10, 1A15, 2A13	SA148SW	Replacement of right front seat with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72003
PA-23, PA-24, PA-28, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA662WE	Hi-Lo sensitivity adaptor BI-400, and autopilot with NAV-1 navigation coupler and heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23, PA-24, PA-30 Series; T.C. 1A10, 1A15, A1EA	SA188SO	Flight control wheel.	SO	37086	Garcia Aviation Company 13010 SW 82nd Avenue Road Miami, FL 33156
PA-23, PA-25, PA-26 Series; T.C. 1A10, 1A15, 2A8, 2A10	SA4-1501	AB-6562 and AB-6563 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-23, PA-30, PA-31, PA-34, PA-39 Series; T.C. 1A10, A1EA, A8EA, 1E10	SA1675WE	Installation of exhaust gas temperature monitoring systems EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-24 Series; T.C. 1A15	SA1-340	Oil-free vacuum pump PA-201.	GL	11880	Associated Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-24 Series; T.C. 1A15	SA1-544	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-24 Series; T.C. 1A15	SA3-309	L2-B autopilot with or without altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA3-315	Arcon B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA3-351	L-2B autopilot with optional altitude control and automatic approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA4-[illegible]2	Autopilot and optional navigation coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA4-666	Grimes D-7080-1-12 rotating beacon.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-24 Series; T.C. 1A15	SA4-852	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-24 Series; T.C. 1A15	SA4-955	Fiberglass vertical fin mount for either Grimes or Whelen WRM rotating beacons.	NW	85550	Art Whitaker Pearson Airpark Vancouver, WA 98660
PA-24 Series; T.C. 1A15	SA4-956	Three seat belts to accommodate three persons or rear seat.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-971	20-gallon auxiliary fuel tank in baggage compartment.	WE	77260	Symons Engineering P.O. Box 90002 Airport Station Los Angeles, CA 90009
PA-24 Series; T.C. 1A15	SA4-1032	Aerofilter 30409A full flow lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-24 Series; T.C. 1A15	SA4-1132	SP-3 autopilot, less altitude and navigation-hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85027

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24 Series; T.C. 1A15	SA4-1235	Installation of Brittain 15-gallon wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA4-1248	Fuel drain modified to incorporate a handle extending forward through front bulkhead.	WE	14960	Bates Aviation, Inc. 1026 East 120th Street Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-1351	Installation of wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA2SO	Fifth passenger seat.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA18SO	Cockpit operated fuel drain valve.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA48WE	Belly-mounted rotating anti-collision light to supplement top fuselage-mounted standard rotating light.	WE	75250	Stits Aircraft Company P.O. Box 3084 Riverside, CA 92502
PA-24 Series; T.C. 1A15	SA59SW	Piper altimatic pilot AK089 or AK089R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24 Series; T.C. 1A15	SA74SW	Quick door release mechanism.	SW	69207	Ross Aviation, Inc. R.F.D. 5, Riverside Airport Tulsa, OK 74101
PA-24 Series; T.C. 1A15	SA112CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155
PA-24 Series; T.C. 1A15	SA113CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155
PA-24 Series; T.C. 1A15	SA160SW	Automatic pilot AK115, AK115E or AK115E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24 Series; T.C. 1A15	SA203SO	Fyr-Fyter 23-4, 2-1/2 pound, dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-24 Series; T.C. 1A15	SA315SW	Fabrication and installation of split rear seat back.	SW	71365	Seven Bar Flying Service, Inc. 10001 Coors Road, NW Albuquerque, NM 87101
PA-24 Series; T.C. 1A15	SA341CE	SAGA (semi-automatic gear actuator) control system. Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
PA-24 Series; T.C. 1A15	SA362WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA478EA	SAGA (semi-automatic gear actuator) system.	GL	43750	In-Flight Devices Corporatin 4885 Sawyer Road International Airport Columbus, OH 43219
PA-24 Series; T.C. 1A15	SA482WE	Plastic wing tips replaced with "Speedplates".	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
PA-24 Series; T.C. 1A15	SA510CE	Modify electrical system to combination 12/24 volt system for starting engine.	EA	12700	Avco Lycoming Division Avco Corporation Williamsport, PA 17701
PA-24 Series; T.C. 1A15	SA511WE	Lycoming O-540-B1B5 engine, Hartzell HC-A2XK-1/8433-7 propeller required.	WE	46790	Johnston Aircraft Service P.O. Box 757 Tulare, CA 93274
PA-24 Series; T.C. 1A15	SA553WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA598EA	Installation electronic voltage alarm, Drawing No. 80107.	EA	53500	McKinley Engineering Corp. P.O. Box 275 Palisades Park, NJ 07650

Aircraft Make, Model & T.C. No.	STC No.	Description	RO	STC Code	STC Holder
PA-24 Series; T.C. 1A15	SA871WE	Fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-24 Series; T.C. 1A15	SA881EA	Installation of Grimes 30-0437-1 anti-collision strobe light kit, P/N 34-0200-1. Amended 5/2/72.	GI	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-24 Series; T.C. 1A15	SA891WE	Toe brakes.	RM	12540	Atlas AViation, Inc. 8505 Montview Boulevard Denver, CO 80202
PA-24 Series; T.C. 1A15	SA904WE	Hanlon and Wilson exhaust system, 637-129.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA1109WE	Hanlon and Wilson exhaust system.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA1605WE	Installation of Brittain B-4A flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24-180; T.C. 1A15	SA4-3151	Wing tip fuel tanks installed. Amended 1/10/69.	WE	17492	Brittain Industries, Inc. 2700 Skypark Drive Torrance, CA 90505
PA-24-180; T.C. 1A15	SA127EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-24(-180), -24-250, -24-260, -24-400; T.C. 1A15	SA208GL	Installation of one piece windshield. Issued 1/23/78.	GI	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-24, PA-24-250, -260, -400; T.C. 1A15	SA270GL	Installation of forward windows, P/N's W-, W/T-, WG-2058-187 or -250 and W-, W/T-, W/G-2059-187 or -250. Issued 10/2/78.	GI	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-24, -24-250; T.C. 1A15	SA3074SW-D	Mitchell automatic flight system AK547 consisting of Century I autopilot with optional omni tracker. Issued 10/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, 24-250, -260; PA-28, 28-140, -150, -160, -180, -235; PA-30; PA-32-260, -300; T.C. 1A15, 2A13, A1EA, A3SO	SA808SW	Installation of Mitchell Model AK246 omni tracker. Applicable only to aircraft modified by STCs SA511SW, SA532SW, SA581SW, SA662SW, SA707SW.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -260, -400; T.C. 1A15	SA891SO	Remove existing windshield and install single piece windshield. Amended 4/27/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260; T.C. 1A15	SA1315CE	Chrome-plated brake disc installations. Issued June 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA1706SW	Portable solid oxygen system. Issued 7/27/73.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3070WE	Installation of single piece windshield. Issued 7/23/75.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-24, -24-250, -24-400; T.C. 1A15	SA2495WE	Installation of recontoured wing leading edge, stall fences, drooped ailerons in flaps-down mode, flap-actuated stabilator trim system, optional new wing tips, optional SC-100 stall warning system. Issued 3/27/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24, -24-250; PA-28-180; T.C. 1A15, 2A13	SA2654WE	Installation of Pathfinder P2A autopilot system. Reissued 5/31/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; T.C. 1A15	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260, PA-30; T.C. 1A15, A1EA	SA3045SW-D	Automatic flight system AK519 consisting of Century IIB autopilot with optional radio coupler. Issued 3/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3565WE	Installation of single piece windshield. Issued 1/20/78.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-24, -24-250, -24-260; T.C. 1A15	SA3776WE	Installation of flexible stainless steel oil cooler hoses. Issued 11/1/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-24, -250, -260, -400; T.C. 1A15	SA4179WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
PA-24-250; T.C. 1A15	SA5-27	Remove Lycoming O-540-A1A5 (250 hp) engine and install Lycoming O-540-B1B5 (235 hp) engine. Revised 3/3/62.	AL	63845	Peninsula Airways, Inc. P.O. Box 110 Naknek, AK 99633
PA-24-250; T.C. 1A15	SA811WE	Installation of turbosupercharged Lycoming IO-540-C1B5 or C1C5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-250 (Normal Category); T.C. 1A15	SA3451WE	Installation of Hartzell HC-A3VK4/V7636D-0 or V7636N-0 constant speed propeller. Amended 5/27/80.	WE	06755	Aircraft Technical Service, Inc. 6701 Odessa Avenue Van Nuys, CA 91406
PA-24-250, -24-260; T.C. 1A15	SA3684WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
*PA-24-250, *-24-260; T.C. 1A15	SA3773WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79. *This installation limited to those aircraft with fuel injected engines.	WE	71740	Silver Instruments, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-24-250, 24-260, PA-30; T.C. 1A15, A1EA	SA1027SW	Manual electric pitch trim AK267.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA893SO	Installation of exhaust silencers. Issued 4/22/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24-260 (S/Ns 24-4783 and 24-4804 and up); T.C. 1A15	SA1026SW	Piper automatic flight system Model AK186 consisting of altimatic IIIB autopilot, auto-flite, electric pitch trim, radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260 (S/N 24-4783, 24-4804 and up with IO-540 series normally aspirated engines; T.C. 1A15	SA1178EA	Installation of Silver Instruments fueltron IG digital fuel flow and totalizer system. Reissued 2/26/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-24-260; T.C. 1A15	SA1331SW	Mitchell automatic flight system AK326 consisting of Piper autoflite II and optional tracking system. Issued 6/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA1521SW	Mitchell automatic flight system AK393, consisting of Century I autopilot with optional omni tracker. Issued 10/17/72.	SW	60000	Mitchell Industries, INc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA2052WE	Installation of Lycoming IO-540-R1A5 engine and Rajay turbosuperchargers.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-260, -24-400; T.C. 1A15	SA31NW	Installation of Madras wing tips. Issued 3/13/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-24-400; T.C. 1A15	SA2359WE	Installation of turbosupercharged Lycoming IC-720-A1A engine. Issued 6/1/71.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-400; T.C. 1A15	SA3134SW-D	Mitchell automatic flight system AK593 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-400; T.C. 1A15	SA3135SW-D	Mitchell automatic flight system AK597 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
PA-24-400; T.C. 1A15	SA3136SW-D	Mitchell automatic flight system AK609 consisting of Century I autopilot with optional omni tracker. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-28; T.C. 1A15, 2A13	SA1485WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24, PA-30; T.C. 1A15, A1EA	SA313SW	Pitch trim system AK124.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA331SO	External power supply plug.	SO	60120	Montgomery Aviation Corporation P.O. Box 92 Montgomery, AL 36100
PA-24, PA-30; T.C. 1A15, A1EA	SA466SW	Pitch trim system AK147.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA475SW	Pitch trim system AK152.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA524SW	Pitch trim system AK164.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA525SW	Piper autocontrol III, Mitchell AK161 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA581SW	Stabilizer AK179.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A15EA	SA662SW	Automatic flight system 220.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA756SW	AK236 automatic flight system with Century II autopilot, optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-25 Series; T.C. 2A8, 2A10	SA4-1592	Spray equipment.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA157SO	Air-oil type main landing gear shock absorber.	SO	64665	Piper Aircraft Corporation Vero Beach, FL 32960
PA-25 Series; T.C. 2A8, 2A10	SA168WE	Installation of Agavenco P/N 1826 15-gallon additional capacity cell to Piper fiberglass spray tank. Amended 3/18/68.	WE	03250	Agricultural Aviation Engineering Company McCarran Airport Las Vegas, NV 89109
PA-25 Series; T.C. 2A8, 2A10	SA185WE	Electrical spray control valve.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Crive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA292SO	FrigiKing JC-1 air conditioner.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-25 Series; T.C. 2A8, 2A10	SA300SO	Auxiliary oil radiator.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-25 Series; T.C. 2A8, 2A10	SA512SW	Metal ribs and metal covering of wings.	SW	60168	Luther W. Moore 1110 West 29th Street Plainview, TX 79072
PA-25 Series; T.C. 2A8, 2A10	SA829WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-25, -25-235, -260; T.C. 2A10	SA915SO	Lower forward longeron reinforcement by adding tubing in trangle shape outboard between fore and aft wing spar root attach fittings and modifying wing root rib to fit over modified longeron. Issued 1/6/77.	SO	05966	Aircraft Service Center, Inc. Route 2, Tifton Airport Tifton, GA 31794
PA-25, -25-235, -260; T.C. 2A10	SA1180CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Gox 508 Renner Field Goodland, KS 67735
PA-25, -25-235, -260; T.C. 2A10	SA1294WE	Installation of automatic flagman. Amended 4/17/72.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362
PA-25, -25-235, -260; T.C. 2A10	SA1417WE	Installation of fiberglass wing tips. Amended 3/26/69.	NW	74750	Sportsman Airpark, Inc. P.O. Box 248 Newberg, OR 97132
PA-25-235; T.C. 2A8	SA41RM	Installation of freon air-conditioning system. Issued 1/9/75.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-25-235; T.C. 2A8, 2A10	SA521WE	Swathmaster dust and spray attachment.	WE	79250	Transland Aircraft, Inc. 2923 190th Street Redondo Beach, CA 90277
PA-25-235; T.C. 2A8, 2A10	SA710CE	Install Compro Aviation rudder horn extension.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
PA-25-235; I.C. 2A8, 2A10	SA997WE	Installation of 180-gallon hopper tank. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-25-235; T.C. 2A10	SA1399WE	Installation of Shell B1-Flon spray system. amended 7/19/68.	NW	71770	Simplex Manufacturing Company 4224 Northeast 42nd Avenue Portland, OR 97218
PA-25-235; T.C. 2A10	SA1630SW	Revised exhaust system. Issued 5/5/73.	SW	53784	Karl D. McWilliams d/b/a K & C Aircraft Service Municipal Building Airport Frederick, OK 73542
PA-25-235, -25-260; T.C. 2A8	SA1316CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-25-235, -25-260; T.C. 2A8	SA1892WE	Installation of hydraulic system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton AVenue Harbor City, CA 90710
PA-25-235, -25-260; T.C. 2A8	SA368NW	Installation of outboard wing fuel tank with modified fuel pump system. Issued 10/19/76.	NW	03270	U.S.D.A. 3706 West Nob Hill Boulevard Yakima, WA 98902
PA-25, PA28-140, PA32-260; T.C. 2A8, 2A13, A3SO	SA693WE	Install AC induction air filter type AAF-104. Amended 4/26/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
PA-28 Series; T.C. 2A13	SA1-649	Lube oil filter PB55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
PA-28 Series; T.C. 2A13	SA8PC	Installation of baggage compartment kit IFC-BC-001 behind rear seats in the cabin.	PC	44810	Island Flight Center, Inc. 203 Lagoon Drive Honolulu, HI 96819
PA-28 Series; T.C. 2A13	SA100EA	AF-510, AF-512A or AF-512B autopilots.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005
PA-28 Series; T.C. 2A13	SA110SO	Electric pitch trim system.	SC	64665	Piper Aircraft Corporation Vero Beach, FL 32960

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28 Series; T.C. 2A13	SA180EA	Geared starter.	EA	79953	Turner Field, Inc. Prospectville, PA 19077
PA-28 Series; T.C. 2A13	SA164SW	Automatic pilot AK092E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA178WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-28 Series; T.C. 2A13	SA222SW	Hartzell HC-82XL-6N/7636D-4 propeller and cowl rework.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA224CE	A3000 main and NB1200 nose skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA236SW	Piper auto-control II automatic pilot AK085E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA246SW	Nose cowling modified.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA263EA	Modification of engine mount to permit use of Lord mounting kit J-10778-4.	EA	12700	Lycoming Division Avco Corporation Williamsport, PA 17701
PA-28 Series; T.C. 2A13	SA319CE	Model 2500 wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA369SW	Automatic pilot AK129, pitch trim system AK130, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA481SW	Removal of door for parachute jumping.	SW	37055	Ervin J. Fusilier 9617 Fulton Street Houston, TX 77002
PA-28 Series; T.C. 2A13	SA511SW	Stabilizer AK153.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA530SW	Automatic pitch trim system AK166.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA556SW	Constant speed propeller.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA601WE	Flight control system B-4 including pitch assist PC-1, altitude hold AH-1, and	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
PA-28 Series; T.C. 2A13	SA645WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA646WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA707SW	AD127 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA708SW	Plane booster safe flight wing tips 101-28.	SW	81250	Upper Valley Aviation, Inc. Harvey J. Ferguson McAllen, TX 78501
PA-28 Series; T.C. 2A13	SA880WE	New design fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-28 Series; T.C. 2A13	SA1191WE	Removal of baggage door for aerial photography operations.	RM	47725	Kelsey Ellis Air Service, Inc. Municipal Airport Salt Lake City, UT 84101

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28 Series; T.C. 2A13	SA1354WE	PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1469WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1470WE	Installation of Brittain Model PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28-140; T.C. 2A13	SA578EA	Installation of Monitair angle of attack/stall warning kit, P/N 9-92-1000. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140; T.C. 2A13	SA687SO	Installation of flight attitude alerting system. Amended 6/1/70.	SO	05350	Aircraft Instruments, Inc. 420 Lincoln Road, Suite 206 Miami Beach, FL 33139
PA-28-140; T.C. 2A13	SA913EA	Installation of Elano Corporation heater-muffler system. Issued 5/11/72.	GL	33200	Elano Corporation 2455 Dayton - Xenia Road Xenia, OH 45385
PA-28-140; T.C. 2A13	SA1189SW	Air circulator. Issued 9/15/70.	SW	83100	Ves-Kol 2805 National Drive Garland, TX 75040
PA-28-140; T.C. 2A13	SA1192EA	Instalation of Safe Flight (SFIC) SC-150 speed control system. Issued 4/15/80.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
PA-28-140; T.C. 2A13	SA2052WE	Installation of Hartzell HC82XL-6F/8433-12 propeller (after conversion of engine to Lycoming O-320-E1A model).	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-140; T.C. 2A13	SA2325WE	Replacement of Station 140.6 vinyl bulkhead panel with fiberglass baggage compartment. Issued 3/19/71.	WE	21000	Chaffee Aircraft Service Corp. 2105 Valley Boulevard Colton, CA 92324
PA-28-140; T.C. 2A13	SA2706SW	Lycoming O-320-D3G engine. Issued 1/20/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-140; T.C. 2A13	SA2842WE	Installation of Novastar anti-collision lighting system. Issued 2/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28-140; T.C. 2A13	SA3071WE	Installation of Bendix P/N 480543 electric auxiliary fuel pump. Issued 8/7/75.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
PA-28-140 (Normal and utility category); T.C. 2A13	SA3415WE	Installation of Lycoming O-320-D2A engine and Sensenich M74DM6-0-60 propeller. Reissued 5/1/79.	NE	30310	Arthur M. D'Onofrio, Jr. 206 Winthrop Boulevard Cromwell, CT 06416
PA-28-140, -28-150 and PA-28-151 landplanes; T.C. 2A13	SA1331CE	Installation of 160 hp Lycoming engine and repitched Sensenich Amended 10/27/77.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
PA-28-140, -150, -160, -180, -235; T.C. 2A13	SA2NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 7/31/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
PA-28-140, -28-150, -28-160, -28-180, -28S-180, -28-235; T.C. 2A13	SA363EA	Installation of Monitair angle of attack and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140, -150, -160, -180; T.C. 2A13	SA549NW	Installation of Deemers wing tips. Issued 12/5/77.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
PA-28-140, -140B, -140C, -140D, -140E, -150, -160, -160B, -160C, -160D, -160E, -160F, -180, -232, -235B thru F, PA-32-260, -300, -32R-300; T.C. 2A13, A3SO	SA600NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. NOTE: Installation does not apply to those models with tapered wings. Issued 10/25/78.	NW	19830	Robert C. Cansdale Bob's Aircraft Supply Thun Field Puyallup, WA 98371

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-140, -150, -151, -160; T.C. 2A13	SA793CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/7666A-2 propeller. Amended 6/29/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
PA-28-140, -150, -160, -180, -235, 28-S-160, S-180, 28R-180, -200; T.C. 2A13	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-1 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-28-140, -150, -160, -180, -235, -S-160, -S-180, -R-180; T.C. 2A13	SA822SW	Mitchell automatic flight system AK217 consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -200, PA-34-200; T.C. 2A13, A7SO	SA979EA	Installation of L/R wing tip transparent fairings and sensor mounting bracketry. Issued 4/5/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
PA-28-140, -28-150, -28-160, -28-180, -28R-200 (S/N 28R-35001 thru 28R-7135329; T.C. 2A13	SA1072CE	Installation of wing leading edge cuffs and droop tips, dorsal fin and vertical stabilizer vortex Amended 5/1/80.	CE	42560	Horton Stol-Craft, Inc. Wellington Municipal Airport Wellington, KS 67152
PA-28-140, -150, -160, -180, -235, -28S-160, -28S-180, -23R-180, -28R-200, -28-151, -28-161, -28-181, -28R-201, -28R-201T, PA-32-260, -300, -32S-300, -32R-300; T.C. 2A13, A3SO	SA1123EA	Installation of Devore vertical tail floodlights on upper surface of horizontal stabilator. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1227CE	Installation of dorsal fin. Amended December 1976.	CE	44800	Isham Aircraft P.O. Box 12172 Wichita, KS 67212
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1228CE	Installation of wing tip extension. Amended June 1976.	CE	44800	Isham Aircraft 416 West Fourth Street Valley Center, KS 67147
PA-28-140, -150, -160, -180, -235; PA-28R-180; T.C. 2A13	SA1157SW	Mitchell flight system AK295 consisting of Piper AutoFlite II, automatic aileron stabilizer and opticnal tracking system. Issued 6/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -235, -200; T.C. 2A13	SA1272SW	Automatic flight system AK307, consisting of Century I and omni tracker. Issued 3/9/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 3A12	SA1317CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Bouelvard Kansas City, KS 66103
PA-28-140, -150, -160, -180 (S/Ns 28-1 thru 28-4377), PA-28-235 (S/N 28-10003 thru 28-11039); T.C. 2A13	SA1373CE	Install third window. Amended 11/17/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1741WE	Installation of hand control for rudder system. Amended 6/13/73.	WE	16854	William Henry Blackwood Route 3, Box 744B3 Escondido, CA 92025
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1898SW	Installation of wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-28-140, -150, -160, -180; T.C. 2A13	SA2179WE	Installation of leading edge cuff, drooped ailerons, wing stall fences, raked wing tips, fuselage flaps, stabilator trim-spring and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98007
PA-28-140, -150, -160, -180, PA-28R-180, -200, -235, PA-32-260, -300; T.C. 2A13	SA3026SW-D	Mitchell auto flight system AK463 consisting of Century IIB autopilot with optional radio coupler. Issued 10/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-140, -150, -160, -180, -28R-200, -235; T.C. 2A13	SA3165SW-D	Automatic flight system AK174 consisting of auto-control IIB autopilot with optional radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -160, -180, -235, -28R-180, -200; T.C. 2A13	SA3166SW-D	Automatic flight system AK295 consisting of Piper autoflite II. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -151, -160, -180, -181, -28R-180, -28R-200, -28-235; T.C. 2A13	SA3435WE	Installation of flexible oil home assembly. Amended 1/11/79.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-28-140, -150, -160, -180, -151, -181, PA-28S-160, -180, PA-28R-180-200; T.C. 2A13	SA3687WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
PA-28-151; T.C. 2A13	SA228GL	Installation of Lycoming O-320-D3G engine in lieu of Lycoming O-320-E3D engine using original installation hardware and components. No installation data required. Issued 3/3/78.	EA	90108	W. Irvine Young 54 Atomic Avenue Toronto, Ontario M8Z-5L4 Canada
PA-28-151; T.C. 2A13	SA1716SW	Mitchell automatic flight system AK430 consisting of AutoFlite II with optional omni tracker. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA1717SW	Mitchell automatic flight system AK431 consisting of auto-control III with optional radio coupler. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA2969SW	Lycoming O-320-D3G engine. Issued 4/5/79.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-151; T.C. 2A13	SA3012WE	Installation of Pathfinder autopilot systems. Issued 4/24/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-151, -161, -181, PA-28R-200, -201, PA-28-235, -28R-201T; T.C. 2A13	SA1075SO	"Wing-Ding" door stop to be installed using existing screws (Piper P/N 415 309, MS27039-0809) on leading edge of right wing at inboard side of fuel cell (W.S. 57.00). Issued 5/18/79.	SO	65327	William J. Stephenson Pro-Flite of Vero, Inc. P.O. Box 998 Vero Beach, FL 32960
PA-28-151, -181; T.C. 2A13	SA3065SW-D	Mitchell automatic flight system AK431 consisting of autocontrol IIIB with optional radio coupler. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3066SW-D	Mitchell automatic flight system AK430 consisting of autoflite II with optional omni tracker. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3095SW-D	Mitchell automatic flight system AK575 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3096SW-D	Mitchell automatic flight system AK576 consisting of Century IIB autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067
PA28-160; T.C. 2A13	SA1971WE	Installation of Model ARB-3 automatic downed aircraft marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue Box 822 Fort Collins, CO 80521
PA-28-160, -28-180, -28-235; T.C. 2A13	SA1484WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28-161, -181; T.C. 2A13	SA419GL	Installation of Tull microwave landing system airborne equipment. Issued 6/18/80.	GL	18320	Burlington Northern Airmotive 3600 East 78th Street Minneapolis, MN 55450

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-161, -181, -201T, -236; T.C. 2A13	SA3352SW	Installation of Mitchell automatic flight system AK851 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TS 76067
PA-28-180; T.C. 2A13	SA1789WE	Installation of Brittain lateral stability augmentation system and super venturi. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-180; T.C. 2A13	SA1792WE	Installation of Morse protection system.	WE	60190	Morse Products Manufacturing 12960 Bradley Avenue Sylmar, CA 91342
PA-28-180; T.C. 2A13	SA2213WE	Conversion of Lycoming O-360-A3A engine to Model O-360-A1A engine and installation of Hartzell HC-C2YK1-B/7666A-0 propeller. Issued 9/8/70.	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-180; T.C. 2A13	SA3233WE	Installation of Symbolic Displays "Novastar" anti-collision light. Issued 7/22/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28R-180; T.C. 2A13	SA962SW	Piper automatic flight system AK271 consisting of altimatic with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180; T.C. 2A13	SA1237SW	Mitchell automatic flight system Model AK314 consisting of altimatic IIIB-1 with optional automatic pitch trim and radio coupler. Issued 12/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA1406SW	Mitchell flight system Model AK269 consisting of Piper autocontrol III autopilot with optional radio coupler. Issued 12/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180; -200; T.C. 2A13	SA2202WE	Installation of contoured leading edge, drooped ailerons, fuselage flap, stabilator trim spring, wing stall fences, raked wing tips, and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98004
PA-28R-180, -200; T.C. 2A13	SA2490SW	Wing tip extension and dorsal fin. Reissued 10/6/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28R-180, -200; T.C. 2A13	SA3004SW-D	Automatic flight system AK436 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA3093SW-D	Mitchell automatic flight system AK577 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA3094SW-D	Mitchell automatic flight system AK578 consisting of Century IIB autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200, -201; T.C. 2A13	SA3841WE	Installation of SDI Model CFS-1000, -1001, or F1-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 MCGaw Avenue Irvine, CA 92714
PA-28R-200; T.C. 2A13	SA194GL	Installation of Lycoming IO-360-C1C6 engine in lieu of Lycoming IO-360-C1C engine using original installation hardware and components. Issued 11/11/77.	GL	71517	Shelby Aircraft Engine Parts, Inc. P.O. Box 454 Shelbyville, IL 62565
PA-28R-200 (S/N 28R-7235001 and up), -28R-201T, -28R-201 (S/N 28R-7737002 and up); T.C. 2A13	SA1183CE	Installation of a two-axis King Model KFC200 flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 1/26/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28R-201: T.C. 2A13	SA420GL	Installation of Tull microwave landing system airborne equipment. Issued 6/18/80.	GL	18320	Burlington Northern Airsotive 3600 East 70th Street Minneapolis, MN 55450
PA-28R-201, -201T; T.C. 2A13	SA3161SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -201T; T.C. 2A13	SA3162SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3194SW-D	Automatic flight system AK638 consisting of Piper altimatic IIIC autopilot with optional radio coupler and glide slope coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3195SW-D	Install automatic flight system AK652 consisting of Century III autopilot with optional radio coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-200, -28R-201T; T.C. 2A13	SA3196SW-D	Install automatic flight system AK653 consisting of Century IIB autopilot with optional radio coupler. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-200, -28R-201T; T.C. 2A13	SA3197SW-D	Install automatic flight system AK654 consisting of Century I autopilot with optional omni tracker. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201T; T.C. 2A13	SA148RM	Install Model CFS-1000 fuel flow meter and related systems. Issued 8/15/78.	RM	77248	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-28R-201T; T.C. 2A13	SA1383CE	Installation of Edo-Aire propeller governor Model 34-828-014-12. Issued 10/28/77.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
PA-28R-201T; T.C. 2A13	SA3771WE	Installation of Fueltron IG digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-28RT-201, -28RT-201T; T.C. 2A13	SA1498CE	Installation of King KFC 200 automatic flight control system. Issued 6/18/79.	CE	48250	King Radio Corporation 400 NOrth Rogers Road Olathe, KS 66061
PA-28RT-201, -28RT-201T; T.C. 2A13	SA3323SW-D	Mitchell automatic flight system AK755 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 11/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3336SW-D	Mitchell automatic flight system AK777 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/21/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3359SW	Installation of Mitchell Century #1 autopilot/flight director AK863/FD. Issued 4/16/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3360SW-D	Installation of Mitchell automatic flight system AK862 consisting of Century 21 autopilot. Issued 5/16/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28-235; T.C. 2A13	SA1131EA	Installation of a radome pod SERP-1001 or -1002 on right wing. Amended 3/28/80.	EA	08332	David L. Stanislaw d/b/a Airquip Horsham Road Ambler, PA 19002
PA-28-235; T.C. 2A13	SA2143WE	Installation of drooped leading edge, drooped ailerons, wing stall fences, fuselage flap, drooped wing tips and elevator trim spring. Amended 12/30/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
PA-28-235; T.C. 2A13	SA2147WE	Installation of Brittain Industries B-7 flight control system. Reissued 11/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-28-235; T.C. 2A13	SA3187WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-235; T.C. 2A13	SA4103SW	Installation of Brittain B-5 flight control system. Issued 3/20/80.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-235, PA-32-260, -300; T.C. A3SO, 2A13	SA1156EA	Installation of radome pod SERP-1021 or -1022 on right wing. Issued 6/26/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002
PA-28, PA-32; T.C. 2A13, A3SO	SA281AL	Installation of large nose gear fork and 8.00-6 nose gear tire. Amended 6/20/68.	AL	78487	Tibbetts-Herre Airmotive P.O. Box 110 Naknek, AK 99633
PA-28, PA-32; T.C. 2A13, A3SO	SA472SO	Installation of hand control for rudder pedal operation. Amended 6/27/74.	SO	85450	The Wheelchair Pilots Association 4211 Fourth Avenue South St. Petersburg, FL 33711
PA-28, PA-32; T.C. 2A13 A3SO	SA757SW	AK234 automatic flight system with Century II autopilot optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; PA-32-260; T.C. 2A13, A3SO	SA788SW	Piper auto-control II automatic pilot AK172E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA72RM	Installation of camera wells. Amended 12/9/76.	RM	42420	Horizons, Inc. P.O. Box 3134 Rapid City, SD 57701
PA-30 Series; T.C. A1EA	SA184EA	Installation of 13-quart alcohol propeller anti-icing kit utilizing either a Weldon pump (P/N 100B-6) or a Bendix pump (P/N 478360). Amended 10/15/71.	NE	86000	Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA225EA	Installation of Monitair angle of attack and stall warning system. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-30 Series; T.C. A1EA	SA233EA	Reservoir-type pneumatic wing and tail deicing system. Amended 10/7/70.	NE	86000	R.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA282CE	GUART System (Gear-up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 West Walnut Street Chicago, IL 60612
PA-30 Series; T.C. A1EA	SA343SW	Automatic pilot AK127, AK127E or AK127E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA477EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
PA-30 Series; T.C. A1EA	SA520SO	Installation of Bendix FCS-810 (Piper Altimatic V/F/D) automatic flight control including manual electric trim and optional flight director indicator. Amended 8/13/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-30 Series; T.C. A1EA	SA531SW	Fifth seat.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-30; T.C. A1EA	SA533NW	Installation of aileron trim. Issued 10/19/77.	EA	73160	Robert Smith Box 43 Okanagan Mission Kelowna, B.C., Canada
PA-30 Series; T.C. A1EA	SA534EA	Replacement of existing stall warning detector Safe Flight P/N C-52207 with pre-stall warning and speed control transducer, Safe Flight P/N 792 and speed control indicator, P/N 571.	EA	69500	Safe Flight Instruments Corp. New King Street White Plains, NY 10601

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-30 Series; T.C. A1EA	SA559WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30 Series; T.C. A1EA	SA576SW	AK186 altimatic III autopilot, AK179 stabilizer, and AK189 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA591CE	Install Alco XW20101-PA-30-L windshield wiper system.	CE	08750	Alco Controls Corporation P.O. Box 12700 St. Louis, MO 63141
PA-30 Series; T.C. A1EA	SA727WE	Installation of Brittain Industries Model TT-5 wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-30 Series; T.C. A1EA	SA738CE	Install King Radio KNC 610 area navigation computer. Amended May 1974.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA766WE	Plastic wing tips replaced with "Speedplates" SP51463.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
PA-30 Series; T.C. A1EA	SA767WE	Modification to include three pair of seat belts on rear seat to accommodate three passengers.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-30 Series; T.C. A1EA	SA776CE	Installation of King Radio KN-74 area navigation computer. Issued June 1971.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA789CE	Install Woodward propeller unfeathering accumulator system. Issued July 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-30 Series; T.C. A1EA	SA1111SW	Outer wing integral auxiliary fuel tanks and increase gross weight of 180 pounds.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1112SW	Dorsal fin.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1113SW	Extended nose with baggage compartment.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1114SW	Nacelle baggage compartments.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1115SW	Dual brakes.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1151SW	Lycoming IC-360-C1C engines (200 hp) with Hartzell HC-C2YK-2/C7666A-4 propeller. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1152SW	One-piece windshield. Issued 6/8/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1153SW	Square wing tips with dual navigation lights. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1154SW	Rudder and aileron interconne system. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1337SW	Pneumatic de-icing system. Issued 7/8/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-30; T.C. A1EA	SA1401CE	Install King Model KNS 80 digital area navigation system. Issued 2/16/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olather, KS 66061
PA-30 Series; T.C. A1EA	SA1935WE	Installation of Brittain flight control system Model B-5, NAV-2B, or B2C. Reissued 10/20/72.	SW	17400	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30; T.C. A1EA	SA3707WE	Installation of single piece windshield. Issued 8/7/78.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-30; T.C. A1EA	SA3729WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-30; T.C. A1EA	SA4066WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-30, PA-39; T.C. A1EA	SA209GL	Installation of one piece windshield. Issued 1/23/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-30, PA-39; T.C. A1EA	SA673EA	Installation of radome kit 3058X. Amended 5/26/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-30, PA-39; T.C. A1EA	SA676EA	Installation of Norton Company radome kit 3058-B. Amended 3/24/71.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-30, PA-39; T.C. A1EA	SA787WE	Installation of turbosupercharged Lycoming IC-320-B1A, IO-320-C1A or LIC-320-C1A engines. Amended 3/10/70.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA848EA	Installation of pneumatic pump operated wing and tail de-icing boot system. Issued 10/22/70.	NE	86000	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-30, PA-39; T.C. A1EA	SA1239SW	Turbosupercharged Lycoming IO-360-C1C engines. Issued 1/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30, PA-39; T.C. A1EA	SA1254SW	Electrothermal propeller de-icing system. Issued 1/27/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30, PA-39; T.C. A1EA	SA1320CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-30, PA-39; T.C. A1EA	SA1341SW	Nose taxi light. Issued 7/20/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246
PA-30, PA-39; T.C. A1EA	SA2312WE	Installation of leading edge cuffs, stall fences, stall strips drooped ailerons, flap actuated stabilator trim system, raked wing tips (optional) and dorsal fin. Amended 4/2/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-30, PA-39; T.C. A1EA	SA2849WE	Installation of oxygen system. Amended 10/3/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA3128SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional command automatic trim, readio, and glide slope couplers. Issued 5/6/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA3336WE	Installation of single piece windshield. Issued 2/2/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-30, PA-39; T.C. A1EA	SA4189WE	Installation of DTL-1000, -1001 and/or -1002/3 autopilot adapters for the Edo-Aire Mitchell century III autopilot. Issued 7/29/80.	WE	47775	Douglas L. Kettler 1212 North Broadway, Apt. H Escondido, CA 92026
PA-31 (S/N 31-2 and up); T.C. A8EA	SA142RM	Install Model CFS-2000 fuel flow meter and related systems. Issued 5/12/78.	RM	77250	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-31; T.C. A8EA	SA191GL	Installation of microwave landing airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31 Series; T.C. A20SO	SA367GL	Installation of Norton radome kit No. 2032X Issued 10/9/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA529EA	Installation of kit for radar antenna.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company P.O. Box 1187 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA541CE	Installation of Hoskins Twilighter Mk III supplemental lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-31 Series; T.C. A8EA	SA546EA	Incorporation of opening in lower surface of fuselage aft of front spar.	NE	86000	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-31 Series; T.C. A8EA	SA613EA	Installation of nine seats. Amended 6/6/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31 Series; T.C. A8EA	SA622EA	Incorporation of camera hatch and mountings to accommodate Zeiss RMK A15/23 camera.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
PA-31 Series; T.C. A8EA	SA741EA	Installation of co-pilot door. Amended 11/3/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31 Series; T.C. A8EA	SA865EA	Installation of radome kit 2031KX. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA908SW	Air conditioner.	SW	64410	R.D. Philpot Industries, Inc. Box 47062 Dallas, TX 75247
PA-31 Series; T.C. A8EA	SA986SW	Baggage lockers in revised aft nacelle fairings.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1000SW	Nine place seating arrangement.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1054SW	Stretcher.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1055SW	Baggage retaining net.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1065SW	Mitchell flight director and autopilot Model 282-187 with slaved directional gyro. Issued 9/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA1120SO	Installation of single camera and camera aperature on starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31; T.C. A20SO	SA1121SO	Installation of supply dropping aperature and sliding shutter and antenna fairing. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31; T.C. A20SO	SA1123SO	Installation of navigation sight and transparent plastic dome on the lower fuselage station 128. Issued 1/8/80.	SC	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31 Series; T.C. A8EA	SA1155SW	Three-place couch. Reissued 6/20/78.	SO	28380	Cypress Aviation, Inc. 3840 Drone Field road Lakeland Airport Lakeland, FL 33803
PA-31 Series; T.C. A8EA	SA1204SW	Manual electric trim AK281. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31 Series; T.C. A8EA	SA1234SW	Mitchell automatic flight system FD/AK282-273, consisting of flight director /autopilot with optional automatic aileron stabilizer AK273. Issued 12/21/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31 Series; T.C. A8EA	SA1305SW	Auxiliary fuel tank. Issued 5/10/71.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1340SW	Four-place couch. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 WEst, Meacham Field Fort Worth, TX 76106
PA-31 Series; T.C. A8EA	SA1569WE	Installation of windshield wiper system.	CE	08750	Alco Controls Corporation Box 12700 St. Louis, MO 63141
PA-31 Series; T.C. A8EA	SA1651WE	Installation of ski carrying pod under fuselage at wing root.	NW	57700	Melridge Aviation Company 1901 East Fifth Street Vancouver, WA 98661
PA-31 Series; T.C. A8EA	SA2124WE	Installation of air conditioning system.	RM	45750	J.B. Systems 120 South Bowen Circle Longmont, CO 80501
PA-31 Series; T.C. A8EA	SA3130SW-D	Mitchell automatic flight system AK589 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA1164SO	Installation of a Bendix FCS-870 automatic flight control system. Issued 7/2/80.	SC	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
PA-31; T.C. A20SO	SA3355SW	Mitchell automatic flight system AK846/FD consisting of Century IV/flight director autopilot with optional remote annunciator. Issued 2/19/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA3768WE	Installation of Fueltron digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-31, PA-31-300; T.C. A8EA	SA603EA	Addition of a 32-inch high door on L.H. side of fuselage between fuselage stations 244-261. Reissued 6/21/78.	SO	28380	Cypress Aviation, Inc. 3480 Drone Field Road Lakeland Airport Lakeland, FL 33803
PA-31, -300; T.C. A8EA	SA744EA	Modification of toilet seat hassock and installation of safety belt. Issued 4/4/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31, -300; T.C. A8EA	SA1255SW	Mitchell automatic flight system Model AK324 consisting of Piper autoflite II and tracking system. Issued 1/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA1522SW	Mitchell automatic flight system AK394, consisting of Century I autopilot with optional omni tracker. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3008SW-D	Automatic flight system AK483 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim, radio, and glide slope couplers. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3009SW-D	Automatic flight system AK496 and AK496FD consisting of Century IV autopilot and Century IV flight director with command/automatic electric elevator pitch trim and opticnal annuciator panel. Issued 7/12/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31, -31-300; T.C. A8EA	SA3010SW-D	Automatic flight system YK491 consisting of yaw damper. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -31-300, -325, -350; T.C. A8EA	SA1318CE	Chrome-plated brake disc installation. Issued May 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-31 (S/N 31-712 and up), PA-31-325, -350; T.C. A8EA	SA1529CE-D	Installation of King KAS 297 altitude selector option. Issued 2/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, -31-300, -31-325, -350; T.C. A20SO	SA1595CE	Installation of TSO'd stretcher. Issued 6/5/80.	CE	12777	Avicon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
PA-31, -31-300, -325, -350; T.C. A8EA	SA3401WE	Installation of single piece windshield. Issued 5/10/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-31, 31-300, PA-31P; T.C. A8EA	SA852EA	Installation of Grimes 555 Series three light strobe kit P/N 34-0100-1. Amended 5/10/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-31, -31P, -31-325, -31-350; T.C. A8EA	SA437SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and optional flight director indicator. Amended 4/4/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31, -31P, -31T, -31-300, -325, -350, -31T1; T.C. A8EA	SA1008EA	Installation of single lamp logo light in horizontal tail. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
PA-31, -31P, -31-300, -325, -350; T.C. A8EA	SA1187CE	Installation of King Model KCS 55A pictorial navigation (compass) with optional KS 52 autopilot adapter. Issued 12/10/75.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31-350, -31-325; T.C. A8EA	SA1166CE	Installation of King KFC-200, 2 axis (3 optional) flight control system, autopilot only or autopilot with flight director. Amended 1/4/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31T; T.C. A8EA	SA578NW	Install redesigned 7th seat (toilet). Issued 5/12/78.	NW	70640	Seattle Flight Service, Inc. 7001 Perimeter Road Seattle, WA 98108
PA-31-300; T.C. A8EA	SA184GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31-300, -310, -325, -350; T.C. A8CE	SA1136CE	Installation of Fiquench cabin fire extinguisher and engine fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
PA-31-325; T.C. A8EA	SA1085CE-D	Installation of Collins Radio Group AP-106, 3-axis autopilot system. Amended 6/25/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1086CE-D	Installation of Collins Radio Group AP-107, 3-axis autopilot system. Amended 6/26/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1087CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system. Amended 6/26/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1088CE-D	Installation of Collins Radio Group yaw damper system. Amended 4/25/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA3017SW-D	Automatic flight system AK485 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim system, radio, and glide slope couplers. Issued 9/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31-325; T.C. A8EA	SA3021SW-D	Automatic flight system AK500 and AK500FD consisting of Century IV autopilot and Century IV flight director autopilot with electronic command/automatic pitch trim system and optional annuciator panel. Issued 10/4/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3129SW-D	Automatic flight system AK590 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3211SW-D	Mitchell automatic flight system AK686 or AK686FD, Piper altimatic X flight director autopilot with optional remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325, -31-350; T.C. A20SO	SA300CE	Installation of propeller governors on single and twin engine aircraft: P/N L210571 left engine, R210571 right engine. Issued 1/2/80. P/N L210721 left engine, R210721 right engine. Issued 2/2/80. P/N L210573 left engine, R210573 right engine. Issued 5/7/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-31-325, PA-31-350 S/N 31-7405479 and up (S/N 31-5001 thru 7405478 when modified per Piper SL722); T.C. A20SO	SA4037WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel and totalizer system. Amended 3/13/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-31-350; T.C. A8EA	SA8NE	Installation of Collins AP-107 2-axis or 3-axis autopilot including yaw damper system. Reissued 12/19/74.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, NE Cedar Rapids, IA 52406
PA-31-350; T.C. A20SO	SA295GL	Install Cleveland conversion kit, P/N 199-83. Issued 3/15/79.	GL	23260	Cleveland Wheels & Brakes Vansickle Division of Parker Hannifin 1160 Center Road Avon, OH 44011
PA-31-350; T.C. A8EA	SA923SO	Installation of Bendix FCS-870 automatic flight control system. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31-350; T.C. A8EA	SA924SO	Installation of Bendix NP-2041A area navigation computer. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31-350; T.C. A20SO	SA1119SO	Installation of twin cameras and two camera aperatures on starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, Fl 33803
PA-31-350; T.C. A20SO	SA1122SO	Installation of single camera and camera aperature on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1124SO	Installation of a single camera and camera aperature and antenna fairing on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1125SO	Installation of twin cameras and two camera aperatures plus camera sights on starboard side of lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A8EA	SA1611SW	Mitchell automatic flight system AK413 consisting of altimatic IIIB-1 with optional automatic pitch trim, radio coupler, and glide slope couplers. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA1612SW	Mitchell automatic flight system AK416 consisting of autoflite II with optional tracking system. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31-350; T.C. A8EA	SA1807SW	AP106 2-axis or 3-axis autopilot including yaw damper and FD-108 flight director. Issued 2/14/74.	SW	24252	Collins Radio Company Box 98 Addison, TX 75001
PA-31-350; T.C. A8EA	SA3015SW-D	Automatic flight system AK-498, cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio, and glide slope coupler. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3016SW-D	Automatic flight system AK499 and AK499FD cons. of Century IV flight director autopilot w/command automatic electric elevator pitch trim and opt. annunciator panel. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3086SW-D	Automatic flight system AK560 cons. of Century III autopilot w/ opt. radio & glide slope couplers. Issued 11/27/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3212SW-S	Mitchell automatic flight system Piper altimatic X autopilot, AK687 or AK687FD Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A20SO	SA4096WE	Installation of SDI model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 1/18/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-31P-425; T.C. A8EA	SA284GL	Install Cleveland conversion kit, P/N 199-83. Amended 2/28/79.	GL	23260	Cleveland Wheels & Brakes VanSickle Division of Parker Hannifin 1160 Center Road Avon, OH 44011
PA-31P; T.C. A8EA	SA483SO	Installation of Bendix YD4 yaw damper system. Issued 12/23/71.	SO	15475	Bendix Avionics Division P.O. Box 8414 Ft. Lauderdale, FL 33310
PA-31P; T.C. A8EA	SA782CE	Installation of King Radio H-14 autopilot. Issued 6/71.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
PA-31P; T.C. A8EA	SA1265SW	Mitchell automatic flight system model AK323 cons. of Piper Autoflite II and Omni tracking system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA1523SW	Mitchell automatic flight system AK395, cons. of Century autopilot w/opt. omni tracker. Issued 10/17/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3012SW-D	Automatic flight system AK484 cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 8/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3013SW-D	Automatic flight system AK492 & AK492FD cons. of Century IV autopilot and Century IV flight director w/command automatic electric pitch trim and opt. annunciator panel. Issued 8/9/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3014SW-D	Automatic flight system YK493 cons. of yaw damper. Issued 8/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3213SW-D	Mitchell automatic flight system Piper altimatic X autopilot, AK688 or AK688FD, Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P, -31T, -31T1; T.C. A8EA	SA1594CE	Installation of TSO'd stretcher. Issued 6/5/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
PA-31T; T.C. A8EA	SA415GL	Installation of a Collins LRN 70 Omega navigation system. Issued 6/20/80.	GL	60568	Muncie Aviation Company P.O. Box 1169 Munci, IN 47305

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-31T; T.C. A8EA	SA190GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 8/16/77.	GL	46250	Jet Electronics and Technology, Inc. 5353 52nd Street N.E. Grand Rapids, MI 49508
PA-31T; T.C. A1EA	SA213GL	Installation of storm window in right hand cockpit window duplicating storm window now installed in left hand cockpit window. Issued 2/2/78.	GL	61629	Northern Airmotive, Inc. 3600 East 70th Street Minneapolis, MN 55450
PA-31T; T.C. A8EA	SA578SO	Instl. of a Bendix M-4D automatic flight control system, including opticnal manual electric pitch trim and flight director system. Amended 10/1/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
PA-31T; T.C. A8EA	SA665NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. Issued 9/14/78.	NW	28850	Robert M. DeBorde 20645 S.W. Clarion Aloha, OR 97005
PA-31T; T.C. A8EA	SA1188CE	Intallation of King KFC 300 automatic flight control system. Amended 4/15/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31T; T.C. A8EA	SA4066SW	Auto-feather system 1. Issued 12/4/79.	EA	64665	Piper Aircraft Corporation 820 East Bald Eagle Drive Lockhaven, PA 17745
PA-31T, -31T1; T.C. A8EA	SA4016WE	Installation of SDI model CFS-2002, fuel flow indicating system. Amended 1/16/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-31T1; T.C. A8EA	SA1053SO	Installation of FCS-870 automatic flight control system, including manual electric trim, optional yaw damper system, and optional flight director. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, Fl 33310
PA-31T1; T.C. A8EA	SA1054SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, Fl 33310
PA-31T1; T.C. A8EA	SA1405CE	Install King KFC-250 autopilot/flight director. Amended 3/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32; T.C. A3SO	SA311NW	Installation of flap extension, spoiler L/E cuff and optional cambered wing tips. Issued 5/28/76.	NW	68500	Robertson Aircraft 839 W. Perimeter Road Renton, WA 98055
PA-32; T.C. A3SO	SA532SW	AK173 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32; T.C. A3SO	SA1523WE	Inst'l. of Brittain Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-32; T.C. A3SO	SA1607WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-32-260; T.C. A3SO	SA371EA	Zeiss aerial camera and intervalometer.	NE	71400	James W. Sewall Co. 147 Center Street Old Town, ME 00468
PA-32-260; T.C. A3SO	SA409GL	Installation of a Lycoming IO-540-K1A5 engine, Hartzell propeller and associated components. Issued 5/23/80.	GL	60179	Melvin C. Morkert 915 Montclair Drive Racine, WI 53402
PA-32-260; T.C. A3SO	SA533SW	Auto-Control III AK174.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA538SW	Piper Altimatic II autopilot and/or radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA1310SW	Stretcher in lieu of rear seats. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72203
PA-32-260; T.C. A3SO	SA1557WE	Installation of turbosupercharged Lycoming 0-540-E4B5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-32-260, -32-300; T.C. A3SO	SA3NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 8/1/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
PA-32-260, -32-300; T.C. A3SO	SA530CE	Install FluiDyne Model 4000 & 2500A skis.	GL	36060	FluiDyne Engr. Corp. 5900 Olson Memorial Hwy. Minneapolis, MN 55422
PA-32-260, -32-300; T.C. A3SO	SA939SW	Mitchell Manual Electric Pitch Trim System AK272.	SW	76067	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300; T.C. A3SO	SA1362CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-32-260, -32-300; T.C. A3SO	SA1568SW	Wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-32-260, -32-300; T.C. A3SO	SA2217WE	Installation of recontoured wing leading edge, raked wing tips, fuselage flap, stall fences, droop ailerons and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 1540 Sunset Highway Bellevue, WA 98007
PA-32-260, -32-300; T.C. A3SO	SA2933WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 Wardlow Road Long Beach, CA 90807
PA-32-260, -32-300; T.C. A3SO	SA3173SW-D	Automatic flight system AK174 cons. of Piper autocontrol IIIB autopilot w/opt radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32S-300; T.C. A3SO	SA1172SW	Mitchell flight system AK304 cons. of Piper autoflite II with optional auto aileron stabilizer and tracking system. Issued 7/17/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32S-300; T.C. A3SO	SA1378SW	Mitchell automatic flight system AK320, cons. of Century I and opt. tracker. Issued 10/26/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300 -32S-300; T.C. A3SO	SA3011SW-D	Automatic flight system AK488 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -300, -32R-300;	SA3736WE	Installation of an engine oil cooler hose. Issued 9/22/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-32-260, -300, -32S-300, -32R-300; T.C. A3SO	SA3839WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
PA-32-260, -300, -32R-300, -32RT-300, -32RT-300T; T.C. A3SO	SA364GL	For "T" tail configuration - installation of Norton radome kit No. 4229X. For conventional tail configuration - installation of Norton radome kit No. 4229XC. Amended 6/13/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Oeprations P.O. Box 350 Akron, OH 44309
PA-32-300; T.C. A3SO	SA893EA	Installation of 8-quart alcohol propeller anti-icing kit WAP-800A. Issued 12/15/71.	NE	86000	E. W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-32-300; T.C. A3SO	SA3305SW-D	Mitchell automatic flight system AK775 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 9/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300; T.C. A3SO	SA3306SW-D	Mitchell automatic flight system AK776, consisting of Century III autopilot with optional and glide slope couplers. Issued 9/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300, -32R-300; T.C. A3SO	SA1154EA	Installation of radome pod SERP-1011 or -1012 on right wing. Amended 12/6/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-32-300, -32R-300; T.C. A3SO	SA3670WE	Installation of Silver Instruments Fueltron IG digital fuel flow indicating system. Issued 6/23/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-32-300, -32R-300, -32S-300, -32RT-300; T.C. A3SO	SA3774WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-32-301, -301T, -32R-301, -301T; T.C. A3SO	SA3361SW	Mitchell automatic flight system AK865 consisting of Century 41 autopilot or AK865FD consisting of flight director autopilot. Issued 5/9/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-301, -301T, -32R-301, -301T; T.C. A3SO	SA3362SW-D	Mitchell automatic flight system AK864 consisting of Century 21 autopilot. Issued 5/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R; T.C. A3SO	SA21NE	Installation of Whelen A600-PR and A600-PG anti-collision strobe with forward and tail position light assemblies as replacements for wing tip lights. Issued 3/1/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
PA-32R-200; T.C. A3SO	SA3102SW-D	Mitchell AK591, consisting of Century IIB autopilot w/opt radio coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-200; T.C. A3SO	SA3103SW-D	Mitchell AK592 cons. of Century III autopilot w/opt. radio coupler and glide slope coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA260GL	Install a Foster Airdata RNAV 511 area navigation system with 51ASA (Alpha) or 51DSA (Delta) steering adapter, or without either adapter. Amended 6/29/79.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
PA-32R-300; T.C. A3SO	SA975SO	Installation of two 15-gallon auxiliary fuel tanks, one in each wing. Issued 4/5/78.	SO	28380	Cypress Aviation, Inc. 3400 Drane Field Road Lakeland Municipal Airport Lakeland, FL 33803
PA32R-300 S/N 32R-7680001 and u T.C. A3SO	SA1201CE	Installation of King KFC 200, 2 axis, flight control system with a King KCS-55 (or -55A) compass and a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 9/9/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32R-300; T.C. A3SO	SA3052SW-D	Mitchell automatic flight system AK529 cons. of Piper altimetric IIIC w/command/auto. elec. pitch trim, opt. radio coupler and glide slope coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3053SW-D	Installation of Mitchell automatic flight system AK530 cons. of Piper autocontrol IIIB autopilot with opt. radio coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3054SW-D	Mitchell automatic flight system AK531 cons. of Piper autoflite II w/opt. omni tracker. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3055SW-D	Mitchell command/electric trim system Model AK532. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3513WE	Installation of Rajay turbocharged Lycoming IO-540-K1G5D engine. Issued 11/8/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
PA-32RT-300, -32RT-300T;	SA1159EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
PA-32RT-300, PA-32RT-300T; T.C. A3SO	SA1430CE	Install King KFC-200 automatic flight control system. Issued 8/9/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-32RT-300; T.C. A3SO	SA3253SW-D	Mitchell automatic flight system AK677 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3254SW-D	Mitchell command electric trim system AK 678. Issued 2/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3255SW-D	Mitchell automatic flight system AK 679 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300T; T.C. A3SO	SA3309SW-D	Installation of Mitchell automatic flight system consisting of Century IV autopilot or AK771 consisting of flight director autopilot with optional remote annunciator. Issued 10/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32S-300; T.C. A3SO	SA932EA	Installation of Pee Kay Model B3500 seaplane floats and Pee Kay Model 3500A amphibious floats. Issued 9/22/72.	EA	29998	Pee Kay DeVore Inc. 125 Mineola Avenue Roselyn Heights, NY 11577
PA-32S-300; T.C. A3SO	SA2253WE	Installation of Edo Model FD-3500-21 amphibious floats. Reissued 5/24/76.	WE	23370	T. M. Close Corporation Gardner Municipal Arpt. Box 464 Gardner, MA 01440
PA-32R-301, -32R-301T; T.C. A3SO	SA1522CE-D	Installation of King KFC 200 flight control system. Issued 12/17/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-34; T.C. A7SO	SA1363CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-34; T.C. A7SO	SA2285SW	Camera and viewfinder installation. Issued 1/22/76.	SW	42825	A. D. Howard, Jr. 1911 Moulton Ct. Oklahoma City, OK 73127
PA-34-200; T.C. A7SO	SA154NW	Installation of full span flaps by removing aileron and changing deployment route of all flaps, spoilers mounted above flap, conical cambered wing tips, anti-balance rudder tab and optional dorsal fin. Issued 1/28/75.	NW	68500	Robertson Aircraft Corp. 839 W. Perimeter Road Renton, WA 98055
PA-34-200; T.C. A7SO	SA292NW	Installation of cooling louvers on top of both nacelle accessory sections. Issued 5/13/76.	NW	01530	Advanced Aviation 4911 S. 290th Place Auburn, WA 98002
PA-34-200; T.C. A7SO	SA493SO	Installation of Bendix FCS-810 (Piper altimatic V/FD) automatic flight control system including manual electric trim and optional flight director indicator. Issued 2/17/72.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
PA-34-200; T.C. A7SO	SA900EA	Installation of electrothermal propeller de-icer system. Amended 1/14/74.	GL	38500	B. F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200; T.C. A7SO	SA901EA	Installation of wing ice light kit. Amended 12/6/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200; T.C. A7SO	SA1321SW	Mitchell automatic flight system AK298 cons. of altimatic IIIB-1 autopilot w/opt automatic command electric pitch trim, radio coupler and glide slope coupler. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA1322SW	Mitchell automatic flight system Model AK335 cons. of Piper autocontrol III w/opt. radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA1323SW	Mitchell command electric pitch trim Model AK321. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-34-200; T.C. A7SO	SA2932WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA2937WE	Installation of turbosupercharged Lycoming IO/LIO-360-C1E6 engine. Amended 3/31/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA3002WE	Installation of wing tip fuel tanks of 17 gal capacity (each). Reissued 5/14/76.	WE	68501	Robertson Aircraft Corp. 2301 E. Utopia Rd. Phoenix, AZ 85024
PA-34-200, S/N 34-E4, S/N 34-7250001 and up; T.C. A7SO	SA903EA	Installation of B.F. Goodrich pneumatic de-icing system. Amended 11/1/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200, -34-200T; T.C. A7SO	SA50GL	Installation of Norton Radome Kit No. 4011KX Amended 3/15/79.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Product Division P.O. Box 350 Akron, OH 44309
PA-34-200, -34-200T; T.C. A7SO	SA510NW	Installation of Cessna fuel tank assembly. Issued 8/20/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
PA-34-200, -34-200T; T.C. A7SO	SA3554WE	Installation of vertical tail floodlights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
PA-34-200T; T.C. A7SO	SA106RM	Installation of freon type air conditioning system. Issued 8/3/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-34-200T; T.C. A7SO	SA154RM	Install Symbolic Displays TSO'd Model CFS-2000 fuel flow meter and related systems. Issued 9/22/78.	RM	77248	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-34-200T; T.C. A7SO	SA968SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 1/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7SO	SA969SO	Installation of NP-2041A area navigation computer programmer. Issued 1/9/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7DO	SA1118SO	Installation of Hartzell 3-bladed propellers, Models – PHC-C3YF-2( )UF/FC-7663-2R and PHC-C3YF-2L( )UF/FJC-7663-2R or PHC-C3YF--( )UF/FC-7663B-2R and PHC-C3YF-2L( )UF/FJC-7663B-2R. Issued 12/21/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
PA-34-200T; T.C. A7SO	SA1147CE	Installation of King Model KFC 200 flight control system, with King KCS 55 or 55A compass and a King KI-255 (or -256) flight command indicator on a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 9/13/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
PA-34-200T; T.C. A7SO	SA1553CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-34-200T; T.C. A7SO	SA3023SW-D	Automatic flight system AK487 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electronic elevator pitch trim, radio, and glide coupler. Issued 9/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3024SW-D	Automatic flight system AK505 cons. of Piper auto-control IIIB autopilot w/opt. radio coupler. Issued 10/24/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3089SW-D	Mitchell automatic flight system AK561 cons. of Century III Autopilot w/opt radio coupler and glide slope coupler. Issued 12/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA-34-200T; T.C. A7SO	SA3669WE	Installation of FUELTRON IIIG digital fuel flow indicating system. Issued 6/21/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-36; T.C. A9SO	SA277NW	Installation of automatic flagman. Issued 3/30/76.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362
PA-36; T.C. A9SO	SA1364CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas Citym KS 66103
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	SA1291CE	Installation of Lycoming IO-720-A1B engine. Amended 4/17/79.	CE	11003	Mr. Clinton Anderson Nehawka, NB 68413
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	SA3452WE	Installation of Lycoming IO-720-A1B engine and Hartzell HC-C3YR-1RF/F8475R constant speed propeller. Amended 2/5/79.	WE	46790	Johnston Aircraft Service, Inc. P.O. Box 1457 Tulare Municipal Airport Tulare, CA 93274
PA-36-375; T.C. A10SO	SA3535WE	Installation of hydraulic system to power spray dispersal system. Issued 12/21/77.	WE	03290	Agrinautics 1333 Patrick Lane Las Vegas, NV 89119
PA-36-375; T.C. A10SO	SA3703WE	Installation of hydraulic power spray pump. Issued 7/27/78.	WE	03290	Agrinautics 1333 Patrick Lane Las Vegas, NV 89119
PA-39 Series; T.C. A1EA	SA816EA	Installation of 13 quart alcohol propeller anti-icing kit WAP-500B. Amended 10/15/71.	NE	86000	Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-39 Series; T.C. A1EA	SA1342SW	Mitchell automatic flight system AK296 cons. of Piper altimatic IIIB-1 autopilot w/opt. automatic pitch trim, radio, and glide slope couplers. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1343SW	Mitchell automatic flight system AK325 cons. of Piper autoflite II w/opt. tracking system. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1344SW	Mitchell command electric trim AK267. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1386SW	Mitchell automatic flight system model AK339, cons. of Piper autocontrol III autopilot with optional radic coupler. Issued 11/16/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1638SW	Mithcell automatic flight system AK355, consisting of Century I with omni tracker. Issued 4/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-40; T.C. A1EA	SA3028SW-D	Mitchell auto. flight system AK481, consisting of Piper altimatic IIIC autopilot with command automatic electric pitch trim system, opticnal radio, and glide slope couplers. Issued 10/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-40; T.C. A1EA	SA3036SW-D	Automatic flight system AK506 consisting of Piper autocontrol IIIB autopilot with optional radio coupler. Issued 12/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA1158EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
PA-44-180; T.C. A19SO	SA1504CE	Installation of King KFC 200 FCS (2 axis) with or without flight director. Issued 8/2/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-44-180; T.C. A19SO	SA3276SW-D	Installation of Mitchell automatic flight system AK 723 consisting of Piper autocontrol IIIB with optional radic couplers. Issued 4/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
PA44-180; T.C. A1980	SA3277SW-D	Mitchell automatic flight system AK719 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 4/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3278SW-D	Mitchell command electric trim AK718.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3287SW-D	Mitchell,automatic flight system AK756 consisting of Century IIB autopilot with optional radio coupler. Issued 5/26/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A1980	SA3288SW-D	Mitchell automatic flight system AK757 consisting of Century III autopilot with optional radio and and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell INdustries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180, -44-180T; T.C. A19SO	SA3375SW-D	Mitchell automatic flight system AK873 consisting of Century 41 autopilot or AK873FD. Issued 6/4/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180, -44-180T; T.C. A19SO	SA3376SW-D	Mitchell automatic flight system AK874 consisting of Century 21 autopilot. Issued 6/4/80.	SW	6000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180, -44-180T; T.C. A19SO	SA3377SW-D	Yaw damper system YK875. Issued 6/4/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MISCELLANEOUS	SA788WE	Mixture monitor (exhaust gas temperature probe and gage). See FAA-approved eligibility list for models.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PIPER AIRCRAFT CORPORATION, CALIFORNIA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
600; T.C. A17WE	SA1347SW	Alternate vent for fuel pressure gages. Issued 7/22/71.	SW	84250	Vought Aircraft Service Company Meacham Field Fort Worth, TX 76106
600; T.C. A17WE	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
600; T.C. A17WE	SA1675WE	Installation of K S Avionics EGT-2 exhaust gas monitoring system. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
600 (S/N 60-0266-XX and up, and those aircraft with previously installed option #108); T.C. A17WE	SA3770WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 6/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
600, 601; T.C. A17WE	SA20GL	Installation of Woodward electronic propeller synchronizer system. Amended 11/6/75.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601; T.C. A17WE	SA35GL	Install wheel and brake conversion kit P/N 199-51. Reissued 7/23/74.	GL	23260	Cleveland Wheels & Brakes Div. Van Sickle Industries, Inc. 1160 Avon Center Road Avon, OH 44011
600, 601; T.C. A17WE	SA443SO	Instllation of Bendix RDR-110 weather radar system per Bendix drawing 4009700, Rev. B. Installation of Norton AD4059KX-5 radome approved per STC SA845EA. Issued 9/25/70.	SC	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601; T.C. A17WE	SA771CE	Installation of Woodward propeller unfeathering accumulator system. Issued June 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601; T.C. A17WE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
600, 601; T.C. A17WE	SA845EA	Installation of radome kit P/N 4059KX or 4059X. Reissued 9/29/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
600, 601; T.C. A17WE	SA1308SW	Addition of toilet provision. Issued 5/7/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1356SW	Fabricate and install rib-wing fairing-inboard (flap attachment bracket). Issued 8/13/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1362SW	Storage drawers under cabin seats. Issued 9/3/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76067
600, 601; T.C. A17WE	SA1363SW	Installation of pressure relief valves in fuel tanks. Issued 9/3/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1382SW	Modify two passenger seats to face aft. Issued 10/29/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1391SW	Dual hydrauic pump. Issued 11/12/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1452SW	Modfy Ted Smith control tube P/N A600128-3. Issued 3/30/72.	SW	84250	Vought Aircraft Services Compay Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1797SW	Mitchell automatic flight system AK459 consisting of Century autopilot with optional omni tracker. Issued 1/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
600, 601; T.C. A17WE	SA2357WE	Installation of auxiliary hydraulic pump. Issued 5/28/71.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
600, 601; T.C. A17WE	SA3884WE	Installation of cabin door pneumatic spring counter-balance. Issued 4/5/79.	WE	64423	Physical Systems, Inc. 7049 Vineland Avenue North Hollywood, CA 91605
600, 601, 601P; T.C. A17WE	SA444SO	Intallation of Bendix Model FCS 810 flight control system, including flight director indicator DH 841( ). Amended 6/3/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601, 601P; T.C. A17WE	SA1089CE-D	Installation of Collins Radio Group AP-106 autopilot system and interface with Collins FD-112 flight director. Amended 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1090CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1104CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1139SO	Installation of a Bendix FCS-870 automatic flight control system. The following options are included: preselect altitude, yaw damper and flight director system. Issued 3/13/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601, 601P; T.C. A17WE	SA1174CE	Installation of Aero Space Controls Corp. 100 AMP alternator. Issued 10/31/75.	CE	02950	Aero Space controls Corporation 1050 North Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1175CE	Installation of Aero Space Controls Corp. air conditioning system. Issued 10/31/75.	CE	02950	Aero Space Controls Corporation 1050 Nort Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1184CE	Install King Model KFC-200 2-axis (3 optional) flight control system with King KCS-55 (or -55A) compass and a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 9/1/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
600, 601, 601P; T.C. A17WE	SA1277CE	Installation of Avcon Industries TSC-C39a stretcher, P/N 4001-101 or 4001-102. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
600, 601, 601P; T.C. A17WE	SA1530CE-D	Installation of King KAS 297 altitude selector option. Issued 2/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
600, 601, 601P; T.C. A17WE	SA2207WE	Installation of JB Systems air conditioning system. Amended 5/21/76.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
600, 601, 601P; T.C. A17WE	SA2336WE	Installation of Prestolite 70 amp alternators (Avco Lycoming P/N 78314) in lieu of existing 50 amp alternators. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA2367WE	Installaton of Prestolite 70 amp alternators (Avco Lycoming P/N 78314). Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA2655WE	Installation of auxiliary hydraulic pump option. Reissued 4/11/78.	WE	64666	Piper Aircraft corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA3029SW-D	Mitchell automatic flight system AK521 consisting of Century III autopilot with command automatic electric pitch trim system, radio, and glide slope couplers. Issued 11/27/74.	SW	60000	Mitchell Indusries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
600, 601, 601P; T.C. A17WE	SA3030SW-D	Mitchell automatic flight system AK522 or AK522FD consisting of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim and optional annuciator panel. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3033SW-D	Automatic flight system AK455 consisting of Century I autopilot with optional omni tracker. Issued 1/9/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P (S/N 60-0266-XX and up and those aircraft with previously installed option #108); T.C. A17WE	SA3370WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 6/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
600, 601, 601P; T.C. A17WE	SA3643WE	Installation of vertical tail floodlight. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
600, 601, 601P S/N 266 and up and aircraft with option 108 previously installed; T.C. A17WE	SA4029WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 9/21/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
600, 601, 601P; T.C. A17WE	SA4144WE	Installation of 35 ampere-hour batteries. Issued 5/1/80	WE	74932	Starline Aircraft Company 3704 State Street, Suite 306 P.O. Box 6765 Santa Barbara, CA 93111
601; T.C. A17WE	SA2346WE	Installation of turbocharger overboost protection. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601; T.C. A17WE	SA2664WE	Modification of fuselage structure for pressurization to 3.20 psi operating pressure, and installation of pressurization system. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601P; T.C. A17WE	SA61GL	Installation of radome kit P/N 4079KX or 4079X. Reissued 8/29/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

RAVEN INDUSTRIES, INC.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
S-40A; T.C. A15CE	SB1WE	Replacement of Raven single burner system P/N 09645 with Raven two burner system P/N 10118 on Raven S-40 model balloon. Amended 10/2/75.	WE	70550	Scorpion Productions 246 Lomita Drive P.O. Box 1147 Perris, CA 92370
S-40A, S-50A, S-55A, RX-7; T.C. A15CE	SL163GL	Modification: Move the velcro 4 to 6 inches back away from the lip of the deflation port. Enlarge deflation panel. Issued 7/2/80.	GL	85870	Matt H. Wiederkehr 1604 Euclid Street St. Paul, MN 55106
S-40A, S-50A, S-60A; T.C. A15CE	SL575SO	Installation of ABP-181 automatic balloon pilot (automatic temperature control). Reissued 11/5/74.	SO	23345	J. Donald Cline 807 Larkwood Drive Greensboro, NC 27410
S-40A, -50A, -60A; T.C. A15CE	SL575SO	Installation of ABP-181 automatic balloon pilot (automatic temperature control). Reissued 11/5/74.	SO	23345	J. Donald Cline 807 Larkwood Drive Greensboro, NC 27410
S-40A, -50A, -60A; T.C. A15CE	SA1720SW	Install four burner can assembly. Issued 8/28/73.	SW	28308	Cutter Flying Service, Inc. P.O. Box 274 Albuquerque, NM 87108
S-40A, S-50A, S-55A, S-60A, RX-6; T.C. A15CE	SB4WE	Installation of digital readout balloon envelope temperature indicator. Issued 5/6/77.	WE	01450	Advanced Aircraft Components 1459 Irving Avenue Glendale, CA 91201
S-40A, -50A, -55A, -60A, RX-6, -7; T.C. A15CE	SB9WE	Installation of a digital readout balloon envelope temperature indicator. Issued 11/14/79.	WE	01450	Advanced Aircraft Components 1459 Irving Avenue Glendale, CA 91201
S-50A, S-55A, S-60A; T.C. A15CE	SL962SO	Installation of ball lock pins, MS 17985-545 or MS 17984-545. Amended 6/26/78.	SO	14285	Balloons, Inc. 1978 East Roxboro Road, N.E. Atlanta, GA 30324
S-60A; A15CE	SL164GL	Modification: Move the velcro 4 to 6 inches back away from the lip deflation panel. Issued 4/22/77.	GL	85870	Matt H. Wiederkehr 1604 Euclid Street St. Paul, MN 55106

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

REIMS AVIATION S.A.

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
F150G, H, J, K, FA150K, F150L, FA150L, FRA150L, F172F, G, H, K, L, M; T.C. A13EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
F150G, H, J, K, FA150K, F150L, FA150L, FRA150L, F172F, G, H, K, L, M; T.C. A13EU	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
F150G; F172; T.C. A13EU, A4EU	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
F150G, H, J, K, L, FA150K, FA150L, F150L; T.C. A13EU	SA1809WE	Installation of one 12-gallon auxiliary fuel tank in each outboard wing panel. Amended 2/22/74.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041
F172F, G, H, K, L, M, N, FR172E, F, G, H, J, K; T.C. A4EU	SA1614WE	Installation of one 12-gallon auxiliary fuel tank in each outboard wing panel. Amended 6/27/80.	WE	35746	Flint Aero 8402-G North Magnolia Gillespie Field Plaza Santee, CA 92071
F177RG; T.C. A26EU	SA71GL	Installation of P/N BA 5710 filter assembly. Issued 12/29/77.	WE	17062	Brackett Aircraft Specialties Co. 4910 East Falcon Drive Mesa, AZ 85205
F182P; T.C. A42EU	SA1758WE	Installation of 12-gallon auxiliary fuel tank in each wing inboard of tip. Amended 2/15/79.	WE	35780	Flint Aero 8402-G Magnolia Avenue Gillespie Airport Plaza Santee, CA 92071
F337E, F, G, FT337E, F, G; T.C. A23EU	SA20GL	Installation of Woodward electronic propeller synchronizer system. Amended 10/30/75.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT

ROCKWELL INTERNATIONAL CORP., CALIFCRNIA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265; T.C. A2WE	SA16GL	Incorporating AMF (Leland) inverters MGE 23-400. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
NA-265; T.C. A2WE	SA687NW	Installation of Mark II system, increased take-off weight, wing modifications, modified A-O-A system, landing gear beef-up. Issued 11/15/78.	NW	66175	The Raisbeck Group 7777 Perimeter Road, South Seattle, WA 98108
NA-265 Series; T.C. A2WE	ST1031SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 11/16/78.	SO	78053	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
NA-265; T.C. A2WE	SA1569SW	Battery temperature sensor warning system. Issued 12/14/72.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
NA-265; T.C. A2WE	SA1854WE	Installation of aft ballast, optional large capacity batteries, heavy duty landing gear assemblies, and extended center of gravity limits. Reissued 7/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Capham Street El Segundo, CA 90245
NA-265, NA-265-20, -30, -40, -60, -70, -80; T.C. A2WE	SA1290CE	Installation of Avcon Industries TSO-C39a stretcher P/N 4006-103 and/or 4006-104. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street Wichita, KS 67204
NA-265, NA-265-20, -30, -40, -60, -70, -80; T.C. A2WE	SA3052WE	Installation of recognition light on horizontal stabilizer upper surfaces. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
NA-265-40; T.C. A2WE	SA139CE	General interior configuration, 7 place. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA140CE	Reclining passenger seat installation (Tpy). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA141CE	Swivel reclining passenger seat installation (Typ). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA142CE	Two place passenger couch installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA143CE	Crew and passenger oxygen system installation. Amended 8/22/77.	CE	28765	Sabreliner Completion Center Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-40; T.C. A2WE	SA171CE	General interior configuration, 8 place - version #2. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA172CE	Two place passenger seat installation (typ). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA181CE	Two place passenger/baggage seat. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5501 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA204CE	General interior configuration, 9 place - version #4. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA205CE	Hand baggage rack installation, stations 147 - 206. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA206CE	Auxiliary passenger seat installation, station 194. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-40; T.C. A2WE	SA219CE	Electronics components package version E. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA220CE	Electronic components package version D. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA221CE	General interior configuration, 9 place version #5. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA243CE	Electronics components package version G. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA244CE	Electronics components package version F. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA245CE	Auxiliary hand baggage rack installation, station 186. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA246CE	General interior configuration, 8 place - version #6. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA267GL	Installation of dual Marconi CMA-734 Omega navigation system. Amended 6/30/80.	GL	18752	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
NA-265-40; T.C. A2WE	SA277CE	Electronic components package version H. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA314CE	Electronic components package version J. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA352CE	Engine vibration monitor installation, Airborne JT-12A6A engine. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA384CE	Electronic components package version K. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA401CE	Electronic components package version L. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA409CE	Electronics components package version M. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA431CE	Install Hoskins Twilighter Mk III supplemental lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1108 North Batavia Orange, CA 92667
NA-265-40; T.C. A2WE	SA449CE	Installation of H.F. transceiver, Sun Air Model T22-RA. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-40; T.C. A2WE	SA450CE	Installation of electronics components package version N, Option A. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA475CE	Install 11 place interior, version #7. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA476CE	Passenger seat. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA477CE	Three place passenger seat. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA509CE	Install ten-place interior, version #8. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-40, -60, -65, -70, -80; T.C. A2WE	SA1545CE	Installation of protective cover No. DIC-2. Amended 3/10/80.	CE	44933	J & H Manufacturing Co., Inc. 511 East locus Carter Lake, IA 68110
t+1 NA-265-40, -60, -70; T.C. A2WE	SA756CE	Install Woodward engine synchronizer system. Amended 4/10/74.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
NA-265-40, -60, -70; T.C. A2WE	SA1162CE	Installation of P & D valve fuel reservoir. Issued February 1976.	CE	68765	Rockwell International Corp. Sabreliner Division Missouri Completion Center Route 3 Perryville, MO 63775
NA-265-40, -60, -70; T.C. A2WE	SA1946SW	Engine fuel shut down system. Issued 1/17/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70; T.C. A2WE	SA1972SW	BKM 100-265 nose wheel steering control. Issued 4/9/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA265-40, -60, -70; T.C. A2WE	SA2789SW	Foxboro fuel management system. Issued 6/2/78.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70; T.C. A2WE	SA4096SW	Bleed air engine fuel manifold purge system. Issued 3/12/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70; T.C. A2WE	SA4137SW	Installation of engine starter inhibit circuit. Issued 6/10/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA746EA	Installation of Norton radome kit numbers, P/N 3090X-1, 3090X-10, 3090X-15, 3090X-20 or 3090X-30. Amended 5/18/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
NA265-40, -60, -70, -80; T.C. A2WE	SA1330CE	Installation of Global GNS-500A VLF/Omega navigation system. Amended 6/23/80.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60, -70, -80; T.C. A2WE	SA1450CE	Installation of microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
NA-265-40, -60, -70, -80; T.C. A2WE	SA1961SW	Entrance door counterbalance system. Issued 4/22/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2382SW	Change nose gear linkage and stop assembly to provide increased steering capability from 35 degrees to 45 degrees. Issued 11/16/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2388SW	Install diode across coil of hydraulic pump relay. Issued 11/24/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, 0-70, -80; T.C. A2WE	SA2701SW	Relocation of hydraulic pressure. Issued 12/22/77.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA265-40, -60, -70, -80; T.C. A2WE	SA2838SW	Installation of recognition lgihts. Issued 8/21/78.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2933SW	BKM pitot heat monitor system. Issued 3/16/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -80; T.C. A2WE	ST996SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
NA-265-40, -60, -80; T.C. A2WE	SA1957SW	Additional hydraulic pressure switch. Issued 3/3/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-60; T.C. A2WE	SA500CE	Installation of oxygen system. Amended 11/10/75.	CE	68765	Sabreliner Division Rockwell International St. Louis Int'l Airport 6161 Aviation Drive St. Louis, MO 63145

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-60; T.C. A2WE	SA501CE	Installation of portable SunAir H.F. transceiver Model SA-14DA. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA502CE	Install a nine-place version No. 1 version No. 1-3 interior. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA503CE	Installation of electronic components package version A. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA522CE	Install 12-place interior. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA540CE	Installation of electronics components package version B. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA549CE	Installation of electronics components package version D. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA565CE	Install 8-place version 3 interior. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA596CE	Installation of electronics components package, version E. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA597CE	Installation of dual RCA AVQ-75 DME with hold feature. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA654CE	Installation of electronics components package, version F. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA685CE	Install a ten-place interior, version No. 4. Reissued 10/1/70.	CE	68765	Aviation Services Division North American Rockwell 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA705CE	Installation of electronics components package, version G. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA804CE	Installation of electronic components package, version H. Issued May 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA817CE	Install aislewise divan.	CE	33580	EPM Corporation P.O. Box 5978 Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA818NW	Installation of Goodyear brake assembly, P/N 9550338-1. Issued 8/1/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road South Seattle, WA 98108
NA-265-60; T.C. A2WE	SA838CE	Installation of electronics components package, version J. Issued August 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA839CE	Installation of ten-place interior, version No. 5. Issued August 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA896CE	Installation of electronic components package, version K. Amended 12/1/75.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA265-60; T.C. A2WE	SA958CE	Installation of 12-place interior Version No. 7. Amended 11/20/78.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-60; T.C. A2WE	SA996CE	Installation of electronic components package, version L. Amended March 1974.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1012CE	Install interior, version No. 8. Issued April 1974.	CE	68765	Aviation Services Division Rockwell International Corp. Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1014CE	Cockpit voice and flight data recorder, altitude alerter system and encoding and weather radar. Amended November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1075CE	Aft lavatory auxiliary seat installation. Issued January 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1078CE	Aft lavatory and auxiliary L.H. installation. Issued February 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1092CE	Installation of electronic components package, version M. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1139CE	Install aft facing forward L.H. seat installation. Issued May 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1146CE	Interior installation, version No. 9. Issued July 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1148CE	Installation of electronic components package, version N. Issued 7/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1149CE	Installation of electronic components package, version P. Issued 7/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1182CE	Auxiliary seat and baggage area installation. Issued 11/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1191CE	Aisle facing seat and baggage area. Issued 1/6/76.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1221CE	Install interior, version No. 10. Issued May 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1242CE	Install Collins ADF-60A automatic direction finding and Intercontinental Dynamics Corp. RAD/BAR with voice terrain advisory system. Amended September 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1247CE	Forward lavatory L.H. installation. Issued July 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1339CE	Aft lavatory installation. Issued 7/6/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1367CE	Interior installation, Version No. 11. Issued 9/15/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1379CE	Install Collins FPC-75 GPWS, IDC SAT/TAS Collins ALT-55B radio altimeter and Wulfsberg Flitefone III provisions. Issued 10/18/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-60; T.C. A2WE	SA1385CE	Install electronic components package Version "R". Issued 11/15/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1386CE	Install electronics components package Version "Q". Issued 11/23/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1392CE	Install Global GNS-500A VLF/OMEGA navigation system. Issued 12/29/77.	CE	59270	Midcoast Aviation Services, Inc. Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1421CE	Install convertible baggage, aisle facing seat. Issued 6/12/78.	CE	59270	Midcoast Aviation Services Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1434CE	Interior installation Version No. 12. Issued 9/19/78.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63775
NA-265-60; T.C. A2WE	SA1476SW	Normalized angle of attack indicating system. Amended 8/27/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
NA-265-60; T.C. A2WE	SA1811WE	Installation of reinforced structure and certain components in partial provision for UCAR configuration. Reissued 7/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60; T.C. A2WE	SA1912WE	Installation of nose boom extension and/or doppler radome and fairing. Amended 5/8/69.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
NA-265-60; T.C. A2WE	SA2878SW	Install two two-place side facing couches. Issued 12/5/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
NA-265-60, Serial No. 306-23 and subsequent; T.C. A2WE	SA3042WE	Installation of engine fuel drain sump tank. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
NA-265-60, -70; T.C. A2WE	SA737CE	Installation of Solar APU Model T-62T-39 and T-62T-39Y. Reissued 6/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60, -80; T.C. A2WE	SA1129CE	Installation of IFR delivery package. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International Corp. 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60, -80; T.C. A2WE	SA1479CE	Installation of forward auxiliary fuel cell (56 gallons). Amended 4/30/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-65; T.C. A2WE	SA1537CE	Installation of Solar Model T-62T-40C auxiliary power unit (APU). Issued 12/29/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA816CE	H.F. antenna installation. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA824CE	Audible hydraulic pressure warning system. Issued February 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA868CE	Installation of Tramm BTI-600 battery temperature indicator system. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA869CE	Installation of RCA AVQ-21 weather radar. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA870CE	Installation of Collins ALT-50 radio altimeter. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-70; T.C. A2WE	SA969CE	Installation of 7-passenger interior. Issued November 1973.	CE	68765	North American Rockwell Aviation Services Division Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA1248CE	Installation of Collins AP104/FD109H automatic flight control system. Issued November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA2766WE	Replacement of existing engines with GE CF700-2D-2 fan jet engines. Issued 10/31/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-80; T.C. A2WE	SA995CE	Install electronic components package, version A. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA997CE	Install interior, version No. 2. Issued February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1015CE	Installation of electronic components package Version "C". Amended 12/22/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1026CE	Install interior, version No. 3. Issued May 1974.	CE	68765	Aviation Services Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1028CE	Installation of electronic components package, version B. Issued 1/20/75.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1043CE	Installation of electronic components package, version D. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1065CE	Installation of electronic components package, version E. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1066CE	Installation of Teledyne angle of attack indicating system SL112B1400. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1067CE	Auxiliary seat installation aft lavatory. Issued November 1974.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1074CE	Auxiliary seat installation. Issued January 1975.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1100CE	Interior installation No. 4. Issued March 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1101CE	Installation of cockpit voice recorder and flight data recorder. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1132CE	Install aft lavatory auxiliary seat. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1133CE	Interior installation, FAA Airways Checker. Issued July 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1142CE	Interior installation, version No. 5. Issued June 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
NA-265-80; T.C. A2WE	SA1249CE	Interior installation, version No. 6 (wide body). Issued August 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1272CE	Interior installation, version No. 7.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1274CE	Installation of electronic components package, Version "F". Amended 6/21/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1275CE	Interior installation, version No. 8.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1288CE	Interior installation, version No. 9. Issued November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1293CE	Commode installation - aft lavatory. Issued January 1977.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1323CE	Interior installation, No. 10. Issued May 1977.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1329CE	Installation of Collins NCS-31A navigation control system with dual control heads, HI-350 remote compass and Collins 728U-5 HF transceiver system. Issued 5/20/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1337CE	Installation of Intercontinental Dynamics cCorp. vertical navigation system. Issued 5/21/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1342CE	Install electronics components package, Version "G". Issued 8/9/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1374CE	Installation of 800 VA and 2500 VA static inverters. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA265-80; T.C. A2WE	SA1387CE	Passenger compartment wiring provisions installation. Issued 11/30/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA3974WE	Installation of Litton LTN-72R area navigation system. Issued 7/6/79.	WE	11620	Area Equipment Company, Inc. 7707-1/2 Woodley Avenue Building 901 Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ROCKWELL INTERNATIONAL CORP., OKLAHOMA

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500 Series; T.C. 6A1	SA1-541	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500 Series; T.C. 6A1	SA1-555	ANC-3A computer and ANC-C2 or ANC-D2 controller.	EA	31050	Dynavia Corporation 3021 West Clay Street Richmond, VA 23219
500 Series; T.C. 6A1	SA1-607	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500 Series; T.C. 6A1	SA3-525	37R-2 antenna.	CE	24250	Collins Radio Company 855 35th Street, NE Cedar Rapids, IA 52406
500 Series; T.C. 6A1	SA4-904	Installation of mufflers and modification of carburetor heat system. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500 Series; T.C. 6A1	SA4-1309	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
500 Series; T.C. 6A1	SA30CE	210405 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
500 Series; T.C. 6A1	SA70CE	Federal F-500 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
500 Series; T.C. 6A1	SA166WE	Removal of main cabin door and hinge pins.	WE	42129	Herpolsheimer Enterprises 12345 VEntura Boulevard Studio City, CA
500 Series; T.C. 6A1	SA168CE	Twin engine synchronizer.	GL	87250	Woodward Governor Company 5001 NOrth Second Street Rockford, IL 61101
500 Series; T.C. 6A1	SA257CE	Turbocharged Lycoming engines, IO-540-A1A5 with Hartzell HC-A3VK-2/V7636D propellers. Reissued 12/5/74.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90801
500 Series; T.C. 6A1	SA340SO	Continental IO-520E engines and Hartzell 3-bladed propellers.	SO	23700	Colemill Enterprises, Inc. P.O. Box 5221 Nashville, IN 37206
500 Series; T.C. 6A1	SA366SO	Gross weight increased to 6530 pounds.	SO	23700	Colemill Enterprises, Inc. Cornelia Fort Air Park Nashville, TN 37202
500 Series; T.C. 6A1	SA459EA	Conversion to Model 500B.	GL	73885	Southern Ohio Aviation Sales Co. Box 97 Montgomery County Airport West Carrollton, OH 44615
500 Series; T.C. 6A1	SA476WE	Nacelle mounted fuel booster pump. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500 Series; T.C. 6A1	SA680SW	AK221 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500 Series; T.C. 6A1	SA683WE	Turbosupercharged Continental IO-470-M engines. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
500 Series; T.C. 6A1	SA1106WE	Mounting provisions for Reconofax XI infrared scanner unit.	EA	03270	U.S. Forest Service Department of Agriculture 1210 Independence Avenue, SW Washington, D.C. 20250
500, 500A, B, 520, 560, 560A, B, E; T.C. 6A1, 2A4	SA90CE	High intensity wing tip lights, tail light and fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
500, 500A, B, 560A, E, 680, 680F, FL, F(P), T, 720; T.C. 6A1, 2A4	SA92EA	Install wheels P/N's 3-1112 and/or 311-58 and P/N's 2-878 and/or 2-971 and/or 2-1087. Reissued 9/4/74.	GL	38504	B.F. Goodrich Engineered Systems Company P.O. Box 340 Troy, OH 45373
500, 500-A, B, S, U, 560A, E; T.C. 6A1	SA303GL	Install Cleveland conversion kit No. 199-74 on models which use MII-H-5606 brake fluid (red oil) or install conversion kit No. 199-74A on models which use Skydrol brake fluid (nonpetroleum base). Issued 4/13/79.	GL	23260	Cleveland Wheels & Brakes VanSickle Division of Parker Hannifin 1160 Center Road Avon, OH 44011
500, 500A, B, 560A, E, F, 680, 680E, F, FL, F(P), FL(P), T, 720; T.C. 6A1, 2A4	SA321EA	Install wheels P/N 301174, P/N's 2-993 and/or 2-1107. Reissued 9/4/74.	GI	38504	B.F. Goodrich Engineered Systems Company P.O. Box 340 Troy, OH 45373
500, 500A, B, U, 560, 560A, E, F, 680, 680F, 680FL, 680FL(P), 680T, 680W, 720; T.C. 6A1, 2A4	SA404CE	Installation of Hoskins supplemental position light system which includes Model A wing tip lights and Model D or K (dual) tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
500, 500A, B, S, U, 560, 560A, E, F, 680, E, F, FL, FL(P), V, W, 720; T.C. 6A1, 2A4	SA527EA	Installation of Collier Model 1AC internally mounted ADF sense antenna. Amended 11/21/68.	GL	24000	Collier Aero Products Company Box 509 Municipal Airport Mansfield, OH 44901
500, 500A, 520, 560; T.C. 6A1	SA589WE	Installation of full-flow lube oil filters on the aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
500, 500-A, -B, -S, -U, 520, 560, 560-A, -E, F, 680, 680-E, -F, FL, FL(P), T, V, W, 681, 685, 690, 720, 111, 112; T.C. 6A1, 2A4, A11SO, A12SO	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14(14V) or -28(28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
500, 500-A, -B, 520, 560; T.C. 6A1	SA630WE	Installation of Coast Winslow Filter Corporation 409 series oil filter assemblies. Reissued 8/29/74.	GI	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
500, 500-A, -B, -S, -U, 520, 560, 560-A, -E, F, 680, 680-E, -F, FL, 680FL(P), T, V, W, 681, 685, 690, 720, 111, 112; T.C. 6A1, 2A4, A11SO, A12SO	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
500, 500-A, -B, -S, -U, 520, 560, 560-A, -E, -F, 680-E, -F, FL(P); T.C. 6A1, 2A4	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
500, 500A, -B, -S, -U, 520, 560, 560-A, -E, -F, 680, -E, -F*, FL, FL(P), T, V, W, 681, 685, 690, 690A, B, 720; T.C. 2A4, 6A1 Includes Pressurized Versions*	SA1017EA	Installation of vertical tail floodlights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
500, 500A, B, S, U, 560A, 680E, F; T.C. 6A1, 2A4	SA1135SW	Modification of fuselage for installation of Bendix ANA-12 doppler antenna. Issued 3/30/70.	SW	47770	Kerr Aviation Services, Inc. P.O. Box 399 Bethany, OK 73008
500, 500-A, B, U, 560, 560A, E, F, 680, E, F, FL; T.C. 6A1, 2A4	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 South Curtis Street Littleton, CO 80120
500, 500A, 500B, 500S, 500U, 520, 560, 560A, 560E; T.C. 6A1	SA3476WE	Replacement installation of tail cone assembly. Issued 9/7/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
680 Series; T.C. 2A4	SA662WE	Hi-Lo sensitivity adaptor SI-400 and autopilot with NAV-1 navigation coupler and heading lock.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
680 Series; T.C. 2A4	SA665SW	deHavilland airborne profile recorder in aft fuselage.	EA	04515	Air Carrier Service Corp. 2233 Wisconsin Avenue, NW Washington, D.C. 20007
680 Series; T.C. 2A4	SA684SW	AP103F/FD-108 automatic flight control system.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA710SW	PT6A-20 engine.	SW	77110	Swearingen Aircraft P.O. Box 6904 San Antonio, TX 78209
680 Series; T.C. 2A4	SA1155WE	Camera.	NW	05123	Western Aerial Contractors, Inc. Route 1, Box 740 Eugene, OR 97401
680, 680E, 720; T.C. 2A4	SA660WE	Installation of HRD type fire extinguishing system. Amended 7/11/77.	WE	43190	HTL Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
680, 680-E, -F, -FL, -FL(P), T, V, W, 681, 685, 690, 720; T.C. 2A4	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Ic. 18145 Judy Street Castro Valley, CA 94546
680E; T.C. 2A4	SA450EA	Modification to lower surface of fuselage to accommodate Wild Camera Model RC5 or RC8. Amended 2/9/68.	EA	52060	Long Island Airways P.O. Box 828 Ronkonkoma, NY 11779
680E; T.C. 2A4	SA1782WE	Installation of drooped ailerons drooped wing leading edge, stall fence and rudder seal. Reissued 1/5/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
680F; T.C. 2A4	SA2691WE	Installation ofLycoming IO-720-BIB turbocharged engine. Reissued 7/22/74.	WE	69220	Mr. R P M Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680F; T.C. 2A4	SA3299SW-D	Mitchell automatic flight system AK772, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/21/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F; T.C. 2A4	SA3300SW-D	Mitchell automatic flight system AK773, consisting of Century IV autopilot, consisting of Century IV flight director autopilot with optional remote annunciator. Issued 8/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F, 680FL; T.C. 2A4	SA155CE	Intallation of Honeywell H-14 adaptive autopilot.	CE	48250	King Radio Corpratin 400 North Rogers Road Olathe, KS 66061
680FL; T.C. 2A4	SA2EU	Cargc door modification	EU	08440	ALAR-Empresa Iberica de Material Aeronautico Ld Lisbon, Portugal
680FL; T.C. 2A4	SA102GL	Installation of baggage compartment. Issued 12/29/75.	GL	31362	Eagle Aviation, Inc. Bishop Airport Flint, MI 48507
680FL; T.C. 2A4	SA929SW	Automatic flight system AK270 consisting of Century III autopilot with optional automatic pitch trim. radic and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
680FL; T.C. 2A4	SA1089SW	59-gallon wing auxiliary fuel tank.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680FL; T.C. 2A4	SA1094SW	RD-8, RC-9, and RMK-A-15/23 camera.	SW	47770	Kerr Aviation Service, Inc. Box 399 Bethany, OK 73008
680FL; T.C. 2A4	SA1095SW	installation of Bendix AMA-12A.	SW	47770	Kerr Aviation Service,Inc. Box 399 Bethany, OK 73008
680FL; T.C. 2A4	SA1358SW	Dual or single camera installation and navigation sights. Issued 8/25/71.	SW	42825	A.D. Howard, Jr. 6817 Northwest 23rd Street Bethany, OK 73008

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
680FL; T.C. 2A4	SA2448SW	Extension of baggage area to F.S. 308, encompassing re-routing of powerplant and aileron control cables in baggage compartment area. Issued 4/7/77.	SW	25260	Harry B. Combs, Jr. P.O. Box 4580 Waco, TX 76101
680FL, FL(P): T.C. 2A4	SA806SW	Flap close-out strips.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
680FL, 680FL(P), 680(F); T.C. 2A4	SA2891WE	Installation of Lycoming IO-720-B1B turbocharged engine. Reissued 8/2/74.	WE	69220	Mr. RPM, Inc. Suite 321 7120 Hayvenhurst venue Van Nuys, CA 91406
680FL, 680FL(P): T.C. 2A4	SA2903SW	Installation of wing flap gap seals. Issued 1/25/79.	SW	69218	Mr. R.P.M., Inc. P.O. Box 40414 Everman Branch Fort Worth, TX 76140
680FL(P): T.C. 2A4	SA3322WE	Installation of cockpit overhead windows. Issued 1/18/77.	WE	69220	Mr. RPM, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680FL(P), T, V, W, 681; T.C. 2A4	SA1261SW	Camera installation. Issued 3/11/71.	SW	30530	Downtown Airpark, Inc. Box 94846 Bethany, OK 73109
680FL(P), 680T, V, W, 681, 690; T.C. 2A4	SA1584SW	Aerial survey camera. Issued 1/3/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 68))*
680FL, 685; T.C. 2A4	SA1649SW	Camera installation. Issued 5/1/73.	SW	42825	A.D. Howard, Jr. 817 Northwest 43rd Street Bethany, OK 73008
680FL, 680FL(P), 680T, V, W, 681, 685A, 690, 690A; T.C. 2A4	SA1977SW	Modification of fuselage for installation of doppler antenna. Issued 5/6/75.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Oklahoma City, OK 73008
680T, V, W; T.C. 2A4	SA887SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
680T, 680V, 680W, 681; T.C. 2A4	SA895EA	Installation of Grimes three light strobe kit. Issued 1/20/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
680T, V, W, 681; T.C. 2A4	SA1926SW	Fuel purge system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681; T.C. 2A4	SA1962SW	Generator over-voltage/over-current protection. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681, 690; T.C. 2A4	SA1705SW	Freon air conditioning system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680V, W; T.C. 2A4	SA1529SW	Modification of hydraulic system and air conditioning pressurization system. Issued 7/25/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680V, W; T.C. 2A4	SA1530SW	Modify existing 3000 psi hydraulic system to 1000 psi hydraulic system. Issued 12/23/72.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680W; T.C. 2A4	SA3469WE	Installation of AiResearch TPE 331-6-252M engines. Amended 2/27/78.	WE	07502	AiResearch Manufacturing Co. of Arizona 402 South 36th Street P.O. Box 5217 Phoenix, AZ 85010
680, 720 Series; T.C. 2A4	SA37CE	C210403 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
680, 720 Series; T.C. 2A4	SA39CE	C210310 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
681; T.C. 2A4	SA1005CE	Installation of IAD battery temperature monitor and over-temperature warning system. Issued March 1974.	CE	05250	Aircraft Instrument & Development, Inc. 317 East Lewis Wichita, KS 67202

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
685 Series; T.C. 2A4	SA17GL	Installation of Bendix FCS-810 autopilot. Issued 4/12/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
685 Series; T.C. 2A4	SA56GL	Install wheel assembly P/N 3-1174 and brake assembly P/N 2-993-1. Issued 7/23/74.	GL	38504	B.F. Goodrich Engineered Systems Company Division of B.F. Goodrich Co. P.O. Box 340 Troy, OH 45373
685; T.C. 2A4	SA155RM	Installation of Singer SKK-1000 doppler navigation system, SKQ-601 dead reckoning computer, and Sperry C-12 compass system. Issued 10/4/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
685 Series; T.C. 2A4	SA878SO	Installation of Silver Instruments Fueltron III, fuel flow gages. Issued 1/21/76.	SC	12493	Atlantic Aero, Inc. P.O. Box 8946 Grensboro, NC 27410
685; T.C. 2A4	SA3849WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 1/30/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
690 Series; T.C. 2A4	SA26GL	Installation of Bendix M-4C autopilot. Issued 7/2/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O.Box 1060 Rockford, IL 61109
690 Series; T.C. 2A4	SA530SO	Installaton of manual electric trim system. Issued 2/28/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
690 Series; T.C. 2A4	SA2606WE	Installation of Lear AFC-70 autopilot. Amended 7/20/73.	WE	49850	LearAvia Corporation Avioncs Division 14505 Mt. Anderson Avenue Reno, NV 89510
690 Series; T.C. 2A6	SA2727WE	Installation of LearAvia electric pitch trim system. Issued 7/20/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510
690, 690A; T.C. 2A4	SA74GL	Install wing tip recognition lights. Issued 3/21/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
690, 690A; T.C. 2A4	SA85SW	Installation of auxiliary bleed air shut-off and fuselage temperature monitoring system. Reissued 1/30/78.	SW	68768	Rockwell Aviation Service Division 3300 Love Field Drive Dallas, TX 75235
690, 690A; T.C. 2A4	SA1059SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid batteries. Issued 3/29/79.	SC	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
690, 690A, 690B; T.C. 2A4	SA2577WE	Installation of flight FCS-105 flight control system. Amended 8/14/78.	CE	24250	Collins Radio Group Rockwell International 400 Collins Raod, N.E. Cedar Rapids, IA 52406
690A; T.C. 2A4	SA79GL	Instal Bendix M4D autopilot system. Issued 4/18/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61101
690A; T.C. 2A4	SA1009CE	Install Model KFC-300 automatic flight control system (autopilot and flight director). Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
690A; T.C. 2A4	SA1011CE	Install Model KVN-395 vertical navigation computer for operation with Model KFC-300 automatic flight control system. Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
690A; T.C. 2A4	SA1873SW	Sperry SPZ-200/STARS IVC. Issued 5/1/74.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, OK 73109
690A; T.C. 2A4	SA1876SW	AP-106 autopilot and manual electric trim. Issued 4/29/74.	SW	24252	Collins Radio Company Addison Airport Addison, TX 75001

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
690A, 690B; T.C. 2A4	SA1024SO	Installation of AiResearch TPE331-5-252K engines in Model 690A replacing AiResearch TPE331-5-251K engines; installation of TPE331-5-252K engines in Model 690B. Amended 6/18/80.	SO	37087	The Garrett Corporation c/o AiResearch Aviation Company Bush Field Agusta, GA 30906
690C; T.C. 2A4	SA405GL	Installation of a Collins LRN 70 omega navigation system. Issued 5/13/80.	GL	33231	Electrosonics Division AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
695; T.C. 2A4	SA411GL	Installation of a Collins LRN 70 Omega navigation system. Issued 6/2/80.	GL	33231	Electrosonics Division AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
695; T.C. 2A4	SA418GL	Installation of a Collins LRN 70 Omega navigation system. Issued 6/20/80.	GL	33231	Electrosonics Division of AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
720; T.C. 2A4	SA1-553	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace ad Defense Products 500 South Main Street Akron, OH 45373
720; T.C. 2A4	SA395SW	Four-place seating capacity.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
111, 112; T.C. A11SO, A12SO	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
111, 112; T.C. A11SO, A12SO	SA1502SW	Mitchell automatic flight system AK364 consisting of Century I autopilot with optional omni tracker. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1503SW	Mitchell automatic flight system AK 363 consisting of Century IIB autopilot with optional radio coupler. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1504SW	Mitchell automatic flight system AK362 consisting of Century III with optional command/electric pitch trim, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1505SW	Mitchell command/electric pitch trim. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1728SW	Cabin air scoop. Issued 9/13/73.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
112; T.C. A12SO	SA243NW	Installation of Lycoming IO-540 engine with 3-bladed Hoffman, 3-bladed Hartzell, or 2-bladed Hartzell propeller. Amended 5/26/78.	NW	52625	Machen, Inc. S. 3408 Davison Boulevard Spokane, WA 99204
112; T.C. A11SO, A12SO	SA2900WE	Installation of Pathfinder autopilots. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Asler Street Torrance, CA 90505
112; T.C. A12SO	SA3155WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 4/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torranc, CA 90505
112, 112B, 112TC, 112TCA, 114, 114A; T.C. A12SO	SA237GL	Install leading edge landing lights. Amended 1/24/80.	GL	37182	General Aviation, Inc. Lost Nation Airport Willoughby, OH 44094
112, 112B, 112TC, 112TCA, 114; T.C. A12SO	SA1229CE	Install King Model KFC-200 2-axis (3 optional) flight control system with KCS 55/55A compass and a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller; or stand alone electric trim. Amended 1/18/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
112, 114; T.C. A12SO	SA3120SW-D	Automatic flight system AK572 consisting of Century I autopilot with optional omni tracker. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A12SO	SA3121SW-D	Automatic flight system AK573 consisting of Century IIB autopilot with optional radio coupler. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A12SO	SA3122SW-D	Automatic flight system AK574 consisting of Century III autopilot with optional radio and glide slope Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A1SO	SA3123SW-D	Mitchel command electric trim AK582. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112B, 112TC, 112TCA, 114; T.C. A12SO	SA3778WE	Installation of retractable landing lights. Issued 11/8/78.	WE	47070	Fred W. Jones 2901 East Spring Street Long Beach, CA 90806
112TC, 112TCA; T.C. A12SO	SA3787WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
112TC, 112TCA; T.C. A12SO	SA3920WE	Installation of fueltron IG or IP digital fuel flow and totalizer system. Amended 1/9/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
114; T.C. A12SO	SA300CE	Installation of propeller governors on single and twin engine aircraft P/N J210345. Issued 5/7/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
114; T.C. A12SO	SA3727WE	Installation of SDI Model CFS-1000, -1001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
114; T.C. A12SO	SA3308WE	Modification of aileron control system by addition of aileron centering spring and installation of Pathfinder autopilot system and/or pitch trim systems. Issued 1/7/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
114; T.C. A12SO	SA3727WE	Installation of SDI Model CFS-1000 fuel flow indicator. Issued 9/6/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SOCIETE NATIONALE INDUSTRIELLE AEROSPATIALE (S.N.I.A.S.)

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SE 3130 Alouette II; T.C. 7H1	SH1-175	American type rate of climb, altimeter, air speed and outside air temperature indicators.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-253	Goodyear floats and United States hardware.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-315	Modification of rotor swash plate.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-461	Engine air inlet duct screens.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-475	Purolator fuel filter element type EP-173 P/N 6656561 and gasket 6656574.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-504	Cabin heating system utilizing Stewart-Warner 940F24 heater.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-527	Transmission gears in transmission box assembly SE 3130 62-30-00; 81P740009 first stage sun gear, one; 81P740006 second stage sun gear, one; 81P740007 satellite gear, twelve.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-563	Tail light modification.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-592	American manufactured instrument panel and cabin dome lighting.	EA	67170	Republic Aviaiton Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-614	Anti-collision rotating beacon light.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-616	Marginal weather instrument group consisting of directional gyro, gyro horizon and turn-slip indicators.	EA	67170	Republic Aviation Corp. Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-617	Grimes eyebrow instrument lights.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-618	Shoulder harness for pilot and copilot.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-623	American type folding 3-man troop seat.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH159EA	Raybestos-Manhatten Ray-Bond (R) R8001 adhesive as an alternate bond for bonding of Alouette.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. 7H1	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. 7H1	SH1870SW	Install 315A-22-11-200 protection assembly for tail drive shaft. Issued 4/17/74.	SW	84300	Vought Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. 7H1	SH1913SW	External cargo carrier. Reissued 8/31/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Irving, TX 75050
SE.313 Series, SA318C; T.C. 7H1	SH437NW	Incorporation of a weighing system for external load operations. Amended 6/10/77.	NW	56890	Measurement Systems Inter'l 619 Riverside Drive Seattle, WA 98108
SA-318C; T.C. 7H1	SH130WE	Installation of Nightsun SX-16C searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA-318C; T.C. 7H1	SH406AL	Installation of L2700 SA 318 skis. Reivsed 2/2/71.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
SA318C; T.C. 7H1	SH440AL	Installation of cargo baskets. Issued 7/16/71.	AL	08500	Alaskan Sky-Craft Company P.O. Box 6206 Anchorage, AK 99502
SA-318C; T.C. 7H1	SH475AL	Installation of ASC-3 maintenance platform, -4 maintenance platform step, and -5 personnel step. Issued 4/3/72.	AL	08500	Alaskan Sky-Craft Company P.O. Box 6206 Anchorage, AK 99502
SA-318C; T.C. 7H1	SH540NW	Install onboard weighing system. Issued 1/9/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OF 97203
SA-318C; T.C. 7H1	SH694NW	Installation of Model 2512 weighing system. Issued 12/14/78.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SA-318C; T.C. 7H1	SA1249SW	Eastern rotorcraft cargo hook 2A15E. Reissued 10/7/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-318C; T.C. 7H1	SH1253SW	S.E.B. 505 starter-generator to replace Labinal starter-generator. Reissued 9/30/77.	SW	84300	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-318C; T.C. 7H1	SH1277SW	Eastern Rotorcraft cargo hook and "H" frame 17080-1. Issued 3/17/71.	SW	84300	Vought Helicopter, Inc. 1701 West Marshall Drive Grand Prairie, TX 75050
SA-318C; T.C. 7H1	SH1384SW	Replace existing landing light and anti-collision light. Reissued 9/30/77.	SW	84300	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-318C; T.C. 7H1	SH1792SW	Foxtronics/Tramm BTI 600 nickel cadmium battery temperature system. Issued 1/29/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
SA330F, G, J; T.C. H4EU	SH2963SW	Seat belt assembly. Issued 3/23/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA330G; T.C. H4EU	SH1983SW	Utility interior arrangement. Reissued 11/8/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA330G; T.C. H4EU	SH1985SW	Supplementary strobe lights and replacement of existing power position lights on sponson. Reissued 11/8/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA330G; T.C. H4EU	SA1986SW	Fixed position retractable landing lights. Reissued 11/8/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH529AL	Installation of L2700 SA341HS skis. Amended 11/26/74.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
SA. 341G; T.C. H6EU	SH734NW	Installation of an Onboard Weighing System. Issued 3/21/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SA.341G; T.C. H6EU	SH1621SW	Eastern Rotorcraft cargo hook. Reissued 6/30/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1654SW	Environmental control unit. Reissued 1/22/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1770SW	Modified cockpit instrument panel. Reissued 6/30/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1858SW	Tail rotor drive shaft cover. Issued 3/20/74.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA.341G; T.C. H6EU	SH1894SW	Grimes Manufacturing Co. landing light Model G-3600 A-3. Issued 7/22/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SA1903SW	Single/dual stowable litter kit. Reissued 6/7/77.	SW	03010	Aerospatiale Helicopter Corp. 1707 W. Marshall Drive Grand Prairie, TX 75050

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA.341G; T.C. H6EU	SH1956SW	Install 341-78-3D-036 hour meter kit. Reissued 3/5/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1991SW	Installation of instruments. Issued 5/26/75.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2264SW	Alternate main gear box shaft input seal. Issued 10/17/75.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2272SW	Strobe lights. Issued 11/18/75.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2278SW	Installation of coffee bar. Issued 12/11/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA.341G; T.C. H6EU	SH2291SW	Motorola stereo Model TD204S. Issued 2/12/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2292SW	Flitephone III system. Issued 2/12/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G;	SH2306SW	Relocation of emergency float inflation bottles and quick removal provisions for emergency floats. Issued 4/28/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2347SW	Install Nightsun searchlight. Issued 8/12/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2371SW	Installation of main rotor head. Issued 10/21/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2379SW	Extend cabin section 200mm just forward of rear bulkhead. Issued 11/9/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marsnall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2400SW	Installation of ATC SH1975 configurations -5, -6, IFR Category II certification. Issued 2/2/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2453SW	Installation of cabin floor extension. Issued 4/22/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA341G; T.C. H6EU	SH2472SW	Installation of exterior markings. Amended 4/24/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA341G; T.C. H6EU	SH2497SW	Structural provisions and installaticn of aft ballast. Issue 8/24/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA341G; T.C. H6EU	SH2664SW	Install right hand maintenance step. Issued 10/12/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-341G; T.C. H6EU	SH2931SW	Toe weights in skid gear. Issued 3/12/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
262A Series; T.C. A6EU	SA2367SW	Install complete interior including lavatory, galley and seating. Reissued 1/12/77.	SW	36700	Frakes AViation, Inc. Route 3, Box 229-B Cleburne, TX 76031
262A Series; T.C. A6EU	SA2369SW	Install P&W ACL PT6A-45A engine. Issued 10/19/76.	SW	36700	Frakes Aviation, Inc. Route 3, Box 229-B Cleburne, TX 76031
Nord 262A; T.C. A6EU	SA3596WE	Replace existing one-piece entry door with a two-piece door with integral steps in the lower half. Issued 3/15/78.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
262A-12; T.C. A6EU	SA370CE	MP-5 autostereo magnetic tape player unit.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
262A-12; T.C. A6EU	SA388CE	U.S. manufactured aircraft control cable substituted to AN standards.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241

SOCIETE NATIONALE INDUSTRIELLE AEROSPATIALE (S.N.I.A.S.) 4

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
262A-12; T.C. A6EU	SA482CE	Installation of cockpit voice recorder.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
262A-12; T.C. A6EU	SA987EA	Installation of forward facing modified double seat on right hand side of aircraft cabin at Station 503 including incorporation of associated seat supporting structure. Reissued 8/4/74.	EA	66390	Ransome Airlines North Philadelphia Airport Grant Avenue & Ashton Road Philadelphia, PA 19114
262A-12; T.C. A6EU	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 3/21/72.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Nord) 262 A-12; T.C. A6EU	SA2666WE	Ceconite 102 material covering of upper rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
"Corvette" SN601; T.C. A37EU	SA2230SW	Interior and associated modifications. Reissued 6/22/76.	EU	73645	Societe Nationale Indus. Aerospatiale 37 Blvd. de Montmorency Paris 16, France
SA-360C; T.C. H8EU	SH2319SW	Seat modification. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2320SW	Installation of bar. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2321SW	Install folding table. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2322SW	Installation of coat closet. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2323SW	Installation of trash container. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2324SW	Inner-window assembly. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. A8EU	SH2402SW	Emergency lighting system. Issued 2/3/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA360C; T.C. H8EU	SH2441SW	Soundproofing. Issued 3/29/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C; T.C. H8EU	SH2445SW	Installation of exterior markings. Amended 4/24/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C; T.C. H8EU	SH2708SW	Alternate anti-collision/strobe lights. Issued 1/23/78.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C; T.C. H8EU	SH4019SW	Installation of RCA Primus 50 radar. Issued 7/18/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350, D, D-1; T.C. H9EU	SH2825SW	Air Cruisers Model D24724 emergency flotation gear. Issued 8/25/78.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2934SW	Supplemental strobe lights. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2935SW	Standard interior. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2936SW	Reversible dual bunch seat. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2937SW	Dual non-stowable litter kit. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2938SW	Electric gyro instruments. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AS-350B; T.C. H9EU	SH2972SW	Net assemblies in side baggage compartment. Issued 4/11/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2973SW	Minimum required external markings. Issued 4/11/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4016SW	Installation of hourmeter. Issued 7/13/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 76067
AS-350B; T.C. H9EU	SH4032SW	Air Cruisers Model D24724 emergency flotation gear. Issued 8/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4044SW	Patient supplemental oxygen supply. Issued 1/18/80.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4048SW	Installation of a storage pouch. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B, AS-350C, AS-350D; T.C. H9EU	SH183RM	Installation of electric driven air-conditioner system. Issued 9/5/79.	RM	45750	J B Systems 120 Bowen Circle Longmont, CO 80501
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH189RM	Installation of belt driven air-conditioner system. Amended 1/10/80.	RM	01950	Aero Engineering Corporation 2678 Delta Drive Colorado Springs, CO 80910
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH2875SW	Electric turn and slip indicator. Issued 4/23/80.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH4086SW	Cabin ventilation system. Issued 2/27/80.	SW	03010	Aerospataile Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH4119SW	Installation of dual litters P/N 350A-82-1000-01. Issued 5/5/80.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH748NW	Installation of a weighing system. Issued 4/12/79.	NW	52685	McAllister Engineering Enterprises 9739 South 208th Street Kent, WA 98031
AS-350C; T.C. H9EU	SH2814SW	Chip detectors. Issued 7/14/78.	SW	03010	Aerospatiale Helicopters, Inc. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH2817SW	Install net assemblies in side baggage compartments. Issued 7/18/78.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH2819SW	Minimum required external markings. Issued 7/19/78.	SW	03010	Aerospatiale Helicopters, Inc. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-305C, D, D-1; T.C. H9EU	SH740NW	Installation of a weighing system. Issued 4/6/79.	NW	56890	Measurement Systems International 580 South Lucille Street Seattle, WA 98108
AS-350C, D, D-1; T.C. H9EU	SH771NW	Installation of a weighing system. Issued 5/15/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
AS-350C, D, D-1; T.C. H9EU	SH2866SW	Installation of hourmeter. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2886SW	Installation of supplemental strobe lights. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2895SW	Installation of standard interior. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2913SW	Installation of reversible dual bench seat. Issued 2/21/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9Eu	SH2914SW	Installation of dual non-stowable litter kit. Issued 2/21/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D1; T.C. H9EU	SH2915SW	Modify damping capacity accumulator, P/N 350A54.1006.00. Issued 2/22/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
AS-350C, D, D-1; T.C. H9EU	SH2917SW	Install electric gyro instruments. Issued 2/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2929SW	Install TEDECC fuel flow chip detector. Issued 3/9/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4043SW	Patient supplemental oxygen supply. Issued 1/18/80.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4049SW	Installation of a storage pouch. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350D; T.C. H9EU	SH1543CE	Installation of Collins APS-841H helicopter automatic flight control systems. Amended 4/22/80.	CE	24250	Collins Avionic Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
AS-350D, -350D1; T.C. H9EU	SH1189EA	Installation of Aircraft Parts (APC) starter-generator, P/N 150SG114Q. Issued 3/26/80.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
S.O.C.A.T.A. - GROUPE AEROSPATIALE

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
880, 885, 894; T.C. 7A14	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
MS880B, MS892A-150, MS892E-150, MS894A, MS894E, MS893A, MS893E, MS895; T.C. 7A14	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
MS880B, MS892A-150, MS892E-150, MS894A, MS894E, MS893A, MS893E, MS895; T.C. 7A14	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
MS880B, MS885, MS892A-150, MS892E-150 (Rallye 150GT), MS893A, MS893E (Rallye 180GT), MS894A, MS894E (Rallye 220 and 220GT), Rallye 100S, 150T, 150ST, 235E (235GT); T.C. 7A14	SA1130EA	Installation of Devore vertical tail floodlights on upper surface of horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite P 6104 Kircher Street, N.E. Albuquerque, NM 87109
MS892A-150, MS893A, MS894A; T.C. 7A14	SA3050SW-D	Automatic flight system AK527 consisting of Century I autopilot with optional omni tracker. Issued 3/20/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
MS892A-150, MS893A, MS894A; T.C. 7A14	SA3051SW-D	Automatic flight system AK528 consisting of Century IIB autopilot with optional radio coupler. Issued 3/20/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
(Rallye) 235E; T.C. 7A14	SA3249SW-D	Mitchell yaw damper YK724. Issued 10/14/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SWEARINGEN AVIATION CORPORATION

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA26T; T.C. A5SW	SA418SO	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C. A5SW	SA461SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C. A5SW	SA571SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation each engine is limited to a maximum of 550 SHP. Issued 12/14/73.	SC	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
SA26T; T.C. A5SW	SA600WE	Install Hoskins Twilighter Mk IIIq supplemental lighting system with Model P wing tip and Model K tail light.	GL	42625	Hoskins, Inc. 34 North Bennett Geneva, IL 60134
SA26T; T.C. A5SW	SA764SW	Bendix M4C autopilot flight control system.	SO	15475	The Bendix Corporation P.O. Box 23430 Fort Lauderdale, FL 33309
SA26T; T.C. A5SW	SA1464WE	Installation of supporting structure and placards only for avionic components in the aft compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26T; T.C. A5SW	SA1465WE	Installation of supporting structure and placards only for avionic components in forward compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26-T, SA26-AT, (Merlin II); T.C. A5SW	SA600CE	Install Hoskins Twilighter Mk III supplemental lighting system with Model P wing tip and Model K tail light. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
SA26-T, SA26-AT, (Merlin II); T.C. A5SW	SA3057WE	Installation of fuel tank boost pump. Issued 7/17/75.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA26-T, SA26-AT, Merlin II; T.C. A5SW	SA3465WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA26-T, 26-AT, 226-T, 226-AT; T.C. A5SW	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SA226T; T.C. A5SW	SA1078SO	Installation of Bendix FCS-8700 automatic flight control system. Issued 6/5/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-T, SA226-AT; T.C. A5SW	SA254GL	Installation of emergency/continuous water-alcohol injection system. Amended 10/3/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
SA226-T, SA226-AT; T.C. A5SW	SA273GL	Installation of a Scenic exhaust assembly, P/N YR-12013 in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-T, SA226-AT; T.C. A5SW	SA613AL	Install nose wheel steering lock system. Issued 6/3/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502
SA226-T, SA226-AT; T.C. A5SW	SA2909WE	Installation of fuel tank boost pump. Amended 8/12/75.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA226-T, SA226-AT: T.C. A5SW	SA3481WE	Installation of recognition light on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA226-TC; T.C. A8SW	SA279GL	Installation of emergency/continuous water-alcohol injection system. Issued 11/1/78.	GL	07503	AiReserach Aviation Company Capital Airport Springfield, IL 62705
SA226-TC; T.C. A8SW	SA189GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA615AL	Install nose wheel steering lock system. Issued 6/21/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502
SA226-TC; T.C. A8SW	SA1068CE	Installation of Collins Radio Co. AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-TC; T.C. A8SW	SA1582CE	Installation of Collins FCS-150 automatic flight control system. Issued 4/2/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
SA226-TC; T.C. A8SW	SA2910WE	Installation of fuel tank boost pump. Issued 7/23/74.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA226-TC; T.C. A8SW	SA3482WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA226T (S/N T-201 and up), SA226AT (S/N AT-001 and up): T.C. A5SW	SA972CE	Installation of AID battery temperature sensing and over temperature warning system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT: T.C. A5SW	SA188GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA274GL	Installation of a Scenic exhaust assembly, P/N YR-12013, in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-AT; T.C. A5SW	SA1051CE	Installation of Collins Radio Co. AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-AT; T.C. A5SW	SA1575SW	Battery isolation system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1576SW	Ray Electronics Model 7107 battery fault warning system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1577SW	Collins FCS-105 automatic/flight director system with Sperry dual flight director system. Issued 1/26/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1673SW	Battery isolation system. Issued 6/11/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA2344WE	Installation of Collins Radio Co. Model FCS-10583 autopilot flight flight director systems. Reissued 8/20/71.	CE	24250	Collins Radio Company 855 - 35th Street, N.E. Cedar Rapids, IA 52406
SA226-AT; T.C. A5SW	SA2860WE	Installation of AiResearch TPE 331-3U-307G engines and propeller synchrophasing. Issued 3/21/74.	WE	07502	AiResearch Manufacturing Company of Arizona 402 South 36th Street Phoenix, AZ 85034
SA226-AT; T.C. A5SW	SA3075WE	Installation of Garrett AirNav 100 area navigation system. Issued 10/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T(B): T.C. A5SW	SA1166EA	Installation of Litton LTN211 Omega navigation system. Amended 4/15/80.	EA	78412	Teterboro Aircraft Service, Inc. 401 Industrial Avenue Teterboro, NJ 07608

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
SA226-T(B): T.C. A5SW	SA1167EA	Installation of Collins ADS-80 air data system. Amended 4/15/80.	EA	78412	Teterboro Aircraft Service, Inc. 401 Industrial Avenue Teterboro, NJ 07608
SA226-T; T.C. A5SW	SA1238SW	Bendix M-4C automatic flight control system. Issued 12/22/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-T; T.C. A5SW	SA1241SW	Installation of supporting structure, avionics components and systems. Issued 1/6/71.	WE	07500	AiResearch Aviaiton Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1271SW	Collins AP105 automatic flight control system. Issued 3/16/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1600SW	Battery isolation system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1601SW	Ray Electronics Model 7107 battery fault warning system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1602SW	Collins AP105 automatic flight control system with dual Sperry Stars flight directors. Issued 2/6/73.	WE	07500	AiResearch Aviation Company 6201 WEst Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA2864WE	Modification to install electrical and structural provisions for Texas Instrument, Inc. infra-red scanner system. Issued 4/25/74.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T, SA226-T(B): T.C. A5SW	SA804SO	Installation of Bendix M-4D automatic flight control system, including integration into the existing Swearingen pitch trim and yaw damping systems. Amended 12/14/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226T, SA226AT; T.C. A5SW	SA2428WE	Installation of Hoskins/SDI Twilighter MK III supplemental lighting system. Issued 10/50/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226TC (S/N TC-201 and up); T.C. A8SW	SA973CE	Installation of AID battery temperature sensing and over-temperature sensing system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA821SO	Installation of Bendix M-4D automatic flight control system including optional flight director system and integration into existing Swearingen pitch trim system. Issued 1/29/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-AT, SA226-TC: T.C. A5SW, A8SW	SA1247SW	Bendix M-4C autopilot. Reissued 8/2/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
ENGINE
TELEDYNE CONTINENTAL MOTORS

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
A-40, -2, -3, -4; A-40-5; A-50; A-65; A-70, -2; A-75; A-80; A-100; C-75, C-85; C-90; C-115, -125; C-145; E-165, E-185; E-225, -2, -4, -8, -9; O-200-A; O-300; GO-300-A thru F; IO-346-A, -B; IO-360-A thru D; O-470-4, -11, -11-C1, -13-13A, -15; C-470-A, B, E, G, H, J, K, L, M, N, P, R; GIO-470-A; IO-470-A, -C; O-470-D thru U; FSO-470-A, -2; TSIO-470-B, -C, -D; IO-520-A, -B, -C; FSO-526-A, -C; GSO-526-A; GTSIO-520-C; TSIO-520; ATC 72, 174, T.C. 190, 205, ATC 32, T.C. 213, 217, 241, 233, 236, 246, 252, 253, 267, 298, E3CE, E1CE, 269, 273, E2CE, 3E1, 281, 3E3, E5CE, 292, 303, E7CE, E8CE-2	SE44WE	Use of Kling Aviation oil, specifications KL-100, KL-200, and KI-300 in Continental and Lycoming engines.	WE	48530	Kling Oil Company 1492 Oddstad Drive Redwood City, CA 94063
A-50, A-65, A-70, A-80, C-85, C-90, O-200, C-75, C-115, C-125, C-145, O-300, E-165-2, E-185-2, O-470, GO-300; T.C. 190, 205, 213, 217, 233, 252, 236, 253, 246, 273, 298	SE1-201	Installation of Richter B-4 or B-5 probes in Marvel-Schebler carburetors MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6, HA-6 series and Bendix NA-S3B and NA-S3A1. Amended 9/20/77.	EA	68000	Richter Aero Equipment Essex, NY 12936
A-50, A-65, A-70, A-80, C-85, C-90, O-200, C-115, C-125, C-145, C-300, E-165, E-185, O-470, GO-300; T.C. 190, 205, 213, 217, 233, 252, 236,	SE208SO	Installation of ice indicator in the carburetor.	SO	71545	Charles B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
A-65 Series; T.C. E-205	SE64WE	Installation of oil screen and oil cooler adapter. Issued 5/24/74.	WE	42137	Laurence E. Hill 336 South Parish Place Burbank, CA 91506
A65, A75, C75, C85 Suffix "F" Series; T.C. 205, 213, 233	SE4CE	Motorola alternator A12NK451. Amended 1/20/78.	CE	15404	Steven E./Robert F. Bell R.R. #1, Box 5 Lawrence, KS 66044
A65, A75, C75, C85 Suffix "F" Series; T.C. 205, 213, 233	SE984SW	Delcc 55A ampere alternator.	SW	84396	Lee A. Waldrop 7624 Palomar Fort Worth, TX 76118
C-85; T.C. 233	SE3CE	R-30-A alternator.	GL	67160	Kenneth J. Repke 7788 Auburn Detroit, MI 48233
C-145, O-300 Series; T.C. 253	SE3-663	Install dry vacuum pump drive. Reissued 7/15/69.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
E-165-2, E-185-1, -3, -8, -9, -11; T.C. E-246	SE416GL	Installation of a spin-on oil filter adapter and spin-on filter in lieu of original screen. Issued 6/23/80.	GL	71920	S & K Engineering 302 West Lafever Street Ossian, IN 46777
D-185, E-225 Series; T.C. 246, 267	SE419SW	Full flow oil filter. Amended 3/1/67.	GL	77017	The Superior Flow Company Div. of A & E Manufacturing, Inc. 11300 Schaefer Highway Detroit, MI 48233
E-185 Series; T.C. 246	SE248EA	MOdification of Hartzell C-192-2 "T-Drive" for use with Airborne Mechanisms dry vacuum pump.	EA	85600	Edward J. White 207 Stephen Drive Cinnaminson, NJ 08077

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
E-185, E-225, O-470 Series; T.C. 246, 267, 269	SE23SW	R5-5EC1 fuel injection system.	GI	15500	Bendix Products Aerospace Div. 717 Bendix Drive South Bend, IN 46600
O-200 Series; T.C. E-252	SE2791SW	Revised starter clutch. Issued 6/6/78	SW	14214	B C & J Enterprises P.O. Box 19676 Oklahoma City, OK 73144
O-200-A; T.C. 252	SE8WE	Alternate oil sump.	WE	78476	Thorp Aircraft Company 909 East Magnolia Boulevard Burbank, CA 91500
O-200-A; T.C. E-252	SE82WE	Closing off of the oil outlet port of the main thrust bearing; installation of an 0-200-B crankshaft; modifying the front oil seal slinger flange; machining an already existing molded pad on the crankshaft to receive a side mounted fuel pump. Issued 10/11/77.	WE	48527	Harvey J. Klein 1736 S. Bedford Street Los Angeles, CA 90035
O-200-A; T.C. 252	SE1396SW	Revise engine oil pick up system. Issued 11/24/71.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
E-225; T.C. 267	SE3WE	T-1106 turbocharger.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
E-225-4, -8; T.C. E-267	SE417GL	Installation of a spin-on oil filter adapter and spin-on filter in lieu of original screen. Issued 6/23/80.	GL	71920	S & K Engineering 302 West Lafever Street Ossian, IN 46777
O-300-A, -B, -C, -D, -E; IO-360-A, -B, -C, -D; IO-470-D thru -H, -J, -K, -L, -M, -R, -S, -U, -V; O-470-J, -R, IO-470-C; O-470-4, -11, -13, -15; IO-520-A, -D, -E, -F, -J, -K, -L; TSIO-520-C, -G, -H; GTSIO-520-C, -D, -F, -H; T.C. 253, E1CE, 3E1, 273, 269, E5CE, E8CE, E7CE	SE12GL	Installation of oil filler cap. Issued 7/11/73.	GL	85850	Ray Whyte Electric Products Co. 30201 Harper Avenue St. Clair Shores, MI 48083
IO-346 and IO-520; T.C. E3WE, E5CE	SE34WE	Installation of Electro-Coatings, Inc. piston rings P/N 252501 and 252509 on Continental piston 631475 for use in Channel-cromium plated Continental IC-346 and IO-520 engine cylinder.	WE	33219	Electro-Coatings, Inc. 1401 Park Avenue Emeryville, CA
IO-360-A, -B, -C, -D, -G, -H, -J, -K; T.C. E1CE	SE234GL	Installation of a steel pin in Continental fuel pump, P/N 638157. Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
IO-360-K; T.C. E1CE	SE1436CE	Modify engine to obtain 210 hp, 2800 rpm for 5 minutes at takeoff and 195 hp 2600 rpm continuous (new designation IO-360-KC/STC SE1436CE). Issued 10/6/78.	CE	44802	Brad E. Isham 416 West Fourth Street Valley Center, KS 67147
TSIO-360-A, -B, -C, -D, -E, -F, LTSIO-360-E; T.C. E9CE	SE235GL	Installation of a steel pin in Continental fuel pump P/N 634263 (TSIC-360-A, -B), 639508 (TSIO-360-C, -D, -E, -F), and 639508 (LTSIC-360-E). Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
O-470 Series; T.C. 269	SE264SW	Marvel-Schebler MA-4-5 carburetor.	SW	32000	Ector Aircraft Company 1703 West Crescent Drive Odessa, TX 79760
O-470 Series; T.C. 273	SE1CE	RSA-5 fuel injection system.	GL	15500	Bendix Products Aerospace Div. 717 Bendix Drive South Bend, IN 46600
O-470 Series; T.C. 273	SE141SW	Rework crankcase in area of starter drive needle bearing.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
O-470 Series; T.C. 273	SE616SO	Installation of O-470-R parts in lieu of normal O-470-M parts.	SO	61644	North Perry Aviation, Inc. 8000 West Pembroke Road Hollywood, FL 33023

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
O-470, IO-470 Series; T.C. 273	SE325SW	Full flow oil filter. Amended 3/1/67.	GL	77017	The Superior Flow Company Div. of A & E Manufacturing, Inc. 11300 Schaefer Highway Detroit, MI 48233
O-470, IO-470 Series; T.C. 273, 3E1	SE73SO	Continental GIO-470 engine oil sump assembly 628943 and oil pump suction tube assembly 628660.	SO	05580	Aircraft Modification Engineering Company P.O. Box 48-1314 Miami, FL 32960
O-470, IO-470, TSIO-470 Series; T.C. 269, 273, 3E1, 3E3	SE16WE	Bendix S-600 low tension ignition system.	WE	70055	Salinas Engine Works Municipal Airport Salinas, CA 93901
O-470, IO-470, TSIO-470 Series; T.C. 269, 273, 3E1, 3E3	SE26WE	Piston ring 250000, 250000+2W and 250000+10W on Continental E Series piston 534895, O-470 piston 534895, 626992 and 537883 and IO-470 piston 534895.	SW	21500	Electro-Coatings, Inc. Channelcromium Division P.O. Box 428 Grapevine, TX 76051
O-470-A, J, K, L, R, G-C1, IO-470-C, -J, -K; T.C. 273, 3E1	SE25WE	Installation of two Rajay turbochargers Model 315F10, P/N RJ0080-102. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
O-470-B, -G, -H, -K, -L, -M, -N, -S, -T, -U, O-470-B-C1, G-C1, K-C1, L-C1, M-C1, IO-470-A, -C; T.C. E-273	SE95WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-470 Series; T.C. 273, 3E1	SE82SO	Engine sump reworked to provide 15 1/8-quart total oil capacity.	SO	68140	Riley Aeronautics Corporation 2100 Northwest 50th Street Fort Lauderdale, FL 33300
IO-470 Series; T.C. 273, 3E1	SE387SW	Modification of ring grooves on Continental Motors pistons 539814 (3 ring) and 627738 (4 ring).	SW	82250	Van Der Horst Corporation of America P.O. Box 428 Terrell, TX 75160
IO-470 Series; T.C. 3E1	SE2-984	Modification of Continental IO-470 piston 6277338 for piston ring used in Continental O-470 piston 537883.	SW	21500	Pennington Channelcromium Company Division of Electro-Coatings, Inc. 319 Dakota Street San Antonio, TX 78205
IO-470 Series; T.C. 3E1	SE94SW	Modification of Continental IO-470 pistons 627738 and 539814 compression ring grooves.	SW	22250	Chrome Plate, Inc. 2805 South Flores Street San Antonio, TX 78205
IO-470 Series; T.C. 3E1	SE152SO	Modification of throttle body location.	SO	37084	Gander Aircraft Corporation 3923 Northwest 24th Street Miami, FL 33142
IO-470-C; T.C. E273	SE994SO	Installation of fuel line filters into individual fuel injector lines. Issued 5/25/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-470-D, -E, -F, -H, -L, -M, -N, -S, -U, -V, -VO; T.C. 3E1	SE69WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	SO	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-470-D, -E, -F, -G, -H, -L, -LO, -N, -P, -R, -S, -T, -U, -V, -VO, LIO-470-A; T.C. 3E1	SE92WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-470-D, E, M, N, S, U, V; T.C. 3E1	SE96SO	Installation of two (2) Rajay turbochargers Model 315F10, P/N RJ0080-102. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
IO-470-J, -K, -N, L; T.C. 3E1	SE992SO	Installation of fuel line filters into individual fuel injector lines. Amended 9/17/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-470, IO-520, TSIO-520 Series; T.C. E-273, 3E1, 3E3, E5CE, E8CE	SE55WE	Modification of fuel injection manifold valve P/N 626547 to the P/N 631427 or P/N 636326 configuration. Issued 2/10/72.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
GIO-470-A; T.C. E2CE	SE70WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
TSIO-470 Series; T.C. 3E3	SE166SW	Modification of Continental TSIO-470 Series piston 629185 for piston rings used in Continental O-470 Series piston 537883.	SW	21500	Pennington Channelcromium Co. Div. of Electro-Coatings, Inc. 319 Dakota Street San Antonio, TX 78205
TSIO-470 Series; T.C. 3E3	SE271SW	Modification of Continental TSIO-470 piston 629185 compression ring grooves.	SW	22250	Chrome Plate, Inc. 2805 South Flores Street San Antonio, TX 78205
TSIO-470-B, -C, -D; T.C. 3E3	SE71WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
TSIO-470B, C, D; T.C. 3E3	SE93WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-520, TSIO-520 Series; T.C. E5CE	SE70RM	Installation of JB Systems compressor brackets P/N 21-052-19. Amended 6/8/79.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
GTSIO-520-C, -D; T.C. E7CE	SE74WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-520-A, -B, -BA, -C, -D, -E, -F, -J, -K, -L, -M; T.C. E5CE	SE72WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-520-A, -B, -BA, -C, -D, -E, -F, -J, -K, -L, -M; T.C. E-273	SE94WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-520-B, -BA; T.C. E5CE	SE282GL	Installation of a fuel flow transducer, Symbolic Displays P/N 201B. Issued 11/14/78.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport Rockford, IL 61109
IO-520-B, -BA, C; T.C. E5CE	SE993SO	Installation of fuel line filters into the individual fuel injector lines. Amended 9/17/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-520-D; T.C. E5CE	SE75WE	Installation of emergency fuel system. Issued 9/9/75.	WE	59730	Mission Aviation Fellowship Box 2828 3519 West Commonwealth Fullerton, CA 92633
IO-520-E; T.C. E5CE	SE451SO	Installation of air compressor gear box drive. Amended 4/6/71.	SO	65333	Puerto Rico Int'l Airlines P.O. Box 1498 Bayamon, PR 00619
IO-520-F; T.C. E5CE	SE80WE	Installation of an emergency fuel system. Issued 9/13/77.	WE	59730	Mission Aviaiton Fellowship P.O. Box 2828 Fullerton, CA 92633
IO-520-G; T.C. E7CE	SE1004SW	Install alternator braces. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
TSIO-520-A, -B, -C, -D, -E, -G, -H, -J, -K, -L; T.C. E8CE	SE73WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
TSIO-520-A, -B, -C, -D, -E, -F, -G, -H, -J, -K, -L, -M, -N, -P, -R; T.C. E8CE	SE96WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
TSIO-520-C, M; T.C. E8CE	SE88WE	Installation of emergency fuel system. Issued 2/7/78.	WE	59730	Mission Aviation Fellowship Box 2828 Fullerton, CA 92633
TSIO-520-D; T.C. E8CE	SE57WE	Installation of two (2) Rajay P/N RJ0080-100, -101 or -102 turbo-superchargers on Continental Teledyne engine. Amended 11/17/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
TSIO-520-D; T.C. E8CE	SE233GL	Installation of a steel pin in Continental fuel pump P/N's 639508 and 632637. Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174

Engine Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
TSIO-520-K; T.C. E5CE	SE1908SW	Conversion of TSIO-520-K to TSIO-520-J. Issued 8/29/74.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
TSIO-520-N; T.C. E8CE	SE2831SW	Bendix S6RN-1251 and S6RN-1255 magnetos. Issued 8/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
TSIO-520-T; T.C. E8CE	SE1462CE	Installation of SSP Products heater core and shroud. Issued 12/4/78.	CE	20625	Cessna Aircraft Company Pawnee Division 5800 East Pawnee Wichita, KS 67201
W-670-6A; T.C. E-162	SE4127SW	Install modified W-670-23 piston, P/N 4180, to replace W-670-6A piston, P/N 4177. Issued 5/21/80.	SW	39710	Gulf Coast Dusting Company 5334 Allison Road Houston, TX 77048
Miscellaneous	SE34WE	Installation of Electro-Coatings, Inc., piston rings on Continental pistons. Amended 3/14/68.	SW	21500	Electro-Coatings, Inc. Channelcromium Division P.O. Box 428 Grapevine, TX 76051
Miscellaneous	SE41WE	Installation of emergency fuel system.	WE	59730	Missionary Aviation Fellowship P.O. Box 2828 Fullerton, CA 92633
Miscellaneous	SE43WE	Installation of an additional dowel in crankshaft accessory gear.	WE	16853	Willard S. Blackinton 9333 Edgewood Drive La Mesa, CA 92041

Miscellaneous Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Miscellaneous	SA899WE	Installation of Model 110 or 111 mixture indicator on single engine aircraft and Model 210 or 211 mixture indictor on twin engine aircraft.	WE	32050	Ectron Corporation 8070 Engineer Blvd. San Diego, CA 92111
Miscellaneous	SA1008WE	Application of Poly-Fiber cover on aircraft.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
Miscellaneous	SA1064WE	Ice detection probe in carburetors.	RM	66000	Radair, Inc. 3385 S. Bannock Street Englewood, CO 80110
Miscellaneous	SA1290WE	Installation of supplemental exterior flashing lights.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
Miscellaneous	SA1335WE	Supplemental exterior flashing lights.	WE	18250	Bullock Magnetics Corporation 2818A Metropolitan Place Pomona, CA 91767
Miscellaneous	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglas cloth. (See Aircraft & Model for individual listing). Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Miscellaneous	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. (See Aircraft & Model for individual listing). Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Miscellaneous	SA1427WE	Installation of A.I.R. Corp. Fuel-Water Detector.	WE	04550	A.I.R. Corporation P.O. Box 2421 Oakland Int'l. Airport Oakland, CA 94614
Miscellaneous	SA1446WE	Inst'l. of supplemental exterior flashing lights.	WE	86540	Ray Winn c/o Winn Avionics 4641 Corral Place Las Vegas, NV 89109
Miscellaneous	SA1462WE	Installation of Control Postion Indicator (CPI) System.	NW	65017	Positive Flight Control 14220 Sunset Highway Bellevue, WA 98004
Miscellaneous	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 6/26/68.	WE	48750	KS Avionics 18145 Judy Street Castro Valley, CA 94546
Miscellaneous	SA1582WE	Installation of Control Position Indicator (CPI) System.	NW	65017	Positive Flight Control 14220 Sunset Highway Bellevue, WA 98004
Miscellaneous	SA1588WE	Installation of supplemental exterior flashing lights.	RM	29250	Delta Products, Inc. P.O. Box 1147 Grand Junction, CO 81501
Miscellaneous	SA1632WE	Installation of supplemental exterior flashing lights.	WE	70500	Scientifico Scientific Components Company 350 Vista Baya Newport Beach, CA 92660
Miscellaneous	SA1686WE	Installation of Vibration Isolation Products engine mount P/N VIP 50545-1	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Blvd. Burbank, CA 91505
Miscellaneous	SA1716WE	Installation of exhaust gas temperature system.	RM	40500	Hanna-Aero Company 5222 S. Holly Street Littleton, CO 80120
Miscellaneous	SA2336SW	Brittain B-12 Accu-Flite System. Issued 7/23/76.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Miscellaneous	SA2386SW	S.A.F.E., EGT, CHT Systems. Issued 1/25/77.	SW	14040	Avicon Development Corporation 701 N. Central Expressway Richardson, TX 75080
Miscellaneous	SA2905SW	AVICON TS1 fuel flow totalizer. Issued 1/30/79.	SW	14040	Avicon Development Corporation 701 North Central Expressway Richardson, TX 75080

Miscellaneous Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
Miscellaneous	SA2906SW	AVICON AF1 fuel flow processor. Issued 1/30/79.	SW	14040	Avicon Development Corporation 701 North Central Expressway Richardson, TX 75080
Miscellaneous	SA4087SW	Installation of Brittain BI-817 directional gyro coupler. Issued 2/27/80.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Miscellaneous Engines	SE2932SW	Install carburetor air temperature indicator. Issued 3/14/79.	SW	09250	Alcor, Inc. P.O. Box 32516 San Antonio, TX 78284

*U.S. GOVERNMENT PRINTING OFFICE: 1980-0-721-634/233

725-617
Copies 160

431-A-5
ap

TD 4.36:980/supp.-3

APR 8 1981

U.S. DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

SUMMARY OF SUPPLEMENTAL TYPE CERTIFICATES

This contains revisions to Summary of Supplemental Type Certificates issued for October, November, December 1980

9336

PAGE CONTROL CHART

Remove Pages	Insert Pages
Aeronca 1-2	Aeronca 1-2
Aircraft Parts & Develop. 1-2	Aircraft Parts & Develop. 1-2
Arctic Aircraft 1	Arctic Aircraft 1
Avions Marcel Dassault 3 thru 9	Avions Marcel Dassault 3 thru 9
Ayres Corp. 1 thru 4	Ayres Corp. 1 thru 4
Beech 1-2, 27 thru 32, 35 thru 74	Beech 1-2, 27 thru 32, 35 thru 75
Bell 9 thru 14	Bell 9 thru 14
Bellanca DE 1-2	Bellanca DE 1-2
Bellanca MN 1 thru 9	Bellanca MN 1 thru 9
Boeing 1 thru 49	Boeing 1 thru 49
Boeing Wichita 1 thru 4	Boeing Wichita 1 thru 4
British Aerospace 1 thru 9	British Aerospace 1 thru 9
British Aircraft 1 thru 3	British Aircraft 1 thru 3
Cessna 1 thru 4, 23 thru 83	Cessna 1 thru 4, 23 thru 84
Commonwealth 1	Commonwealth 1
Costruzioni Aero. (Agusta) 1	Costruzioni Aero. (Agusta) 1
Curtiss Wright 1-2	Curtiss Wright 1-2
deHavilland 1 thru 8	deHavilland 1 thru 8
Empressa 1	Empressa 1
Fairchild 1-2	Fairchild 1-2

PAGE CONTROL CHART

Remove Pages	Insert Pages
Gates Learjet 1 thru 10	Gates Learjet 1 thru 10
General Dynamics 1-2, 15 thru 19	General Dynamics 1-2, 15 thru 19
Gov't Aircraft Factory 1	Goc't Aircraft Factory 1
Great Lakes OH 1	Great Lakes OH 1
Grumman Amer. Aviation 1 thru 3	Grumman Amer. Aviation 1 thru 3
Gulfstream American 3 thru 8, 15 thru 24	Gulfstream American 3 thru 8, 15 thru 24
Helio 1 thru 4	Helio 1 thru 4
Jobmaster 1	Jobmaster 1
Laister Kauffman 1	Laister Kauffman 1
Lockheed GA 9 thru 11	Lockheed GA 9 thru 11
Luscombe GA 1 thru 3	Luscombe GA 1 thru 3
Martin 1-2	Martin 1-2
Maule 1-2	Maule 1-2
McClish 1	McClish 1
McDonnell Douglas 7-8, 15 thru 42	McDonnell Douglas 7-8, 15 thru 42
Meyers 1	Meyers 1
Mooney 3 thru 6	Mooney 3 thru 6
Mooney Mite 1-2	Mooney Mite 1-2
Naval Aircraft Factory 1	Naval Aircraft Factory 1
Navion 1 thru 5	Navion 1 thru 5
Nelson 1	Nelson 1
Nihon 1	Nihon 1
No. American Avia. OH 1	No. American Avia. OH 1
Piper 1-2, 15-16, 21 thru 67	Piper 1-2, 15-16, 21 thru 68
Piper Aircraft CA 1 thru 3	Piper Aircraft CA 1 thru 3
Rockwell Inter'l CA 7 thru 10	Rockwell Inter'l CA 7 thru 10

PAGE CONTROL CHART

Remove Pages	Insert Pages
Rockwell Inter'l OK 1 thru 4, 11 thru 15	Rockwell Inter'l OK 1 thru 4, 11 thru 15
Ryan 1	Ryan 1
Schweizer 1	Schweizer 1
Sikorsky 3	Sikorsky 3
Spinks Ind. 1	Spinks Ind. 1
Stinson 1-2	Stinson 1-2
Swearingen 1 thru 3	Swearingen 1 thru 3
Taylorcraft Aviation 1-2	Taylorcraft Aviation 1-2
Taylorcraft Inc. 1-2	Taylorcraft Inc. 1-2
Univair 1 thru 6	Univair 1 thru 6
Universal 1-2	Universal 1-2
Waco 1	Waco 1
Wagner 1	Wagner 1
ENGINES	
Avco Lycoming 3	Avco Lycoming 3
Teledyne 1 thru 5	Teledyne 1 thru 5

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AERONCA, INC.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
C-2; T.C. 351	SA204EA	Continental A40-3 engine S/N 664.	EA	16755	Samuel P. Bigony 994 Vale Street Pottstown, PA 19464
C-2, C-3 Series: T.C. 351, 396	SA296WE	Ceconite 101 covering of complete airplane.	WE	26200	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
C-2 Standard, C-2 Scout, PC-2; C-3, PC-3; 60-TF; O-58B; 15AC, S15AC; ATC 351, 396, T.C. 728, 751, 802	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 North Street Los Angeles, CA 90063
C-2 Standard, C-2 Scout, PC-2, PC-3, C-3, 60-TF, O-58B, 15AC, S15AC; T.C. 351, 396, 728, 751, 802	SA2666WE	Ceconite 102 material covering of: C-2 series - wings, elevators, horizontal stabilizer and rudder; C-3, PC-3 - complete aircraft; 60-TF - wings; O-58B - wings, fuselage, ailerons, elevators and rudder; 15AC, S15AC - fuselage, vertical fin, horizontal stabilizer, elevator, rudder, ailerons, and landing gear vees. 8/19/78	WE	20250	Ceconite, Inc. 4677 North Street Los Angeles, CA 90063
C-3, PC-3; T.C. 396	SA4-1409	Eonite covering of wings and fuselage.	WE	52090	William J. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
C-3, PC-3, 15AC, S15AC, 50TC, 60TF, 65TC, 65TF, 50TL, 65TL, 65TAC, 65TAF, 65TAL, YO58; T.C. 396, 802, 728	SA4-1210	Installation of Fonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 North Street Los Angeles, CA 90063
C-3, LC; T.C. A-396, ATC 614	SA1008WE	Installation of Poly-Fiber covering material (complete aircraft). Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
50TC, 50TL, YO58, 60TF, 65TAC, 65TAF, 65TAL, 65TC, 65TF, 65TL; 15AC, S15AC; T.C. 728, 802	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92509
50-TC, 60-TF, 65-TC, 15AC; T.C. 728, 802	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
50TC, 65TC, 60TC, 65TF, 60TF, 50TL, 65TL, 65TAC, 65TAF, 65TAL; O58A, B, SO-58B; 15AC, S15AC; T.C. A-728, A-751, A-802	SA308EA	Installation of carburetor ice detection system Model 105AP manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and MA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
50TC, 60TC, 65TC, 65TF, 60TF, 50TL, 65TL, 65TAC, 65TAF, 65TAL; O58A, B, SO-58B; 15AC, S15AC; T.C. A-728, A-751, A-802	SA499EA	Installation of carburetor ice detection system 107AP-12 or 107AP-25 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and MA-6 series carburetor. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
[illegible] 50, 60, 65; 058; 15AC, S15AC; T.C. A-728, A-751, A-802	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
50, 60, 65T; 15AC; T.C. 728, 802	SA1350WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
60-TF; T.C. 728	SA4-1104	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
O-58B, S/N 05891012 and up; T.C. A-751	SA132GL	Install metal wing ribs. Issued 9/13/76.	GL	18060	Eric J. Brown 2008 East 121st Street (#320) Burnsville, MN 55337
O-58B; T.C. 751	SA176WE	Ceconite 101 covering of wings, fuselage, ailerons, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
O-58B; T.C. 751	SA220EA	Removal of door for parachute jumping.	EA	73942	Bart Spadaro Montauk Highway East Moriches, NY 11940
15AC; T.C. 802	SA4-567	Glass cloth over fuselage, vertical and horizontal stabilizers.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
15AC; T.C. 802	SA4-1593	Removal of door for parachute jumping and aerial photography operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
15AC; T.C. 802	SA302NW	Install Lycoming O-360 engine and Hartzell prop engine mount and fiberglass cowling. Reissued 4/27/78.	NW	60096	Monohan Aircraft, Inc. 2311 East Lake Sammamish Pl., S.E. Issaquah, WA 98027
15AC Landplane or Seaplane; T.C. A-802	SA306GL	Installation of Lycoming O-360-A1F6D and Hartzell Model HC-C2YK-1BF/F7666A-2 propeller on aircraft previously modified in accordance with STC SA302NW, using the existing installation hardware and components. Issued 5/7/79.	GL	94890	Weber's Aero Repair, Inc. Municipal Airport Alexandria, MN 56308
15AC; T.C. 802	SA424AL	Installation of seat belt attachments. Issued 4/19/71.	AL	60185	Robert J. Morrison P.O. Box 356 Chugiak, AK 99567
15AC; T.C. 802	SA552NW	Install cargo hook electronic scale. Issued 1/4/78.	NW	73067	Marvin Smith 5503 West Flowing Lake Road Snohomish, WA 98290
15AC, S15AC; T.C. 802	SA3-423	CT-3000 tail ski on airplanes equipped with Scott Model 3200 or or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
15AC, S15AC; T.C. 802	SA3-725	Prentics Aircraft lift strut fitting 61-16-1.	GL	33248	Ellington Aircraft Salvage East Broadway Walbridge, OH 43465
15AC, S15AC; T.C. 802	SA3-731	Replacement part upper and lower wing strut fittings.	GL	49330	Lake of the Woods Flying Service Baudette, MN 56623
15AC, S15AC; T.C. A-802	SA4-1290	Ceconite 101 covering of fuselage vertical fin, horizontal stabilizer, elevator, rudder, ailerons and landing gear Vees.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
15AC, S15AC; T.C. A-802	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
15AC, S15AC; T.C. 802	SA549CE	Installation of Continental IO-346-B engine with Hartzell HC-C2YF-1A/7663 constant speed. Amended 7/15/76.	GL	46784	W.L. Johnson, Jr. 7721 Driftwood, S.E. Grand Rapids, MI 49506

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT

AIRCRAFT PARTS & DEVELOPMENT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A Series; T.C. 758	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
A Series; T.C. 758	SA4-1422	Ceconite 101 covering of entire airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
A Series; T.C. 758	SA4-1193	Continental C-145-2 engine and Sensenich 76JC48 or McCauley 1A170 propeller.	RM	59780	Missoula Aerial Service P.O. Box 1158 Missoula, MT 59801
A Series; T.C. 758	SA4-1493	Aluminum hopper.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1498	Fuselage tube structure modification and installation of new overturn structure.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1503	Increase maximum gross weight to 1,835 pounds with Continental W670-6A engine, Sensenich 90LA78 propeller and associated modifications.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1594	Wing fuel tanks. (Restricted category only.)	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1632	Wheels, brakes, rudder pedals and brake cylinders modification.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A Series; T.C. 758	SA4-1633	Hopper.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
A, A2, 3, 4, 5, 5T, 6, 9; A-9A T.C. A-758, A4WE	SA309EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system Model 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SP, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
A, A2, 3, 4, 5, 5T, 6, 9; T.C. A-758	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine FAR 23/CAR 3 aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
A, -2, -3, -4, -5, -6; T.C. 758	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A, A-2, A-3, A-4, A-5, A-6; T.C. 758	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A; A-9A; T.C. A-758, A4WE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
A-3; T.C. 758	SA1008WE	Poly-Fiber covering of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Coatings 43rd South Fort Drive Box 3084 Riverside, CA 92519

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A-9; T.C. A4WE	SA765SW	Modified McCauley 2D34CT69/84HF-0 propeller and governor installed.	SW	85700	Whiteface Aviation Company Drawer 433 Hereford, TX 79045
A-9, A-9A, T.C. A4WE	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
A-9, -9A, -9B; T.C. A758, A4WE	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A-9, -9A, -9B; T.C. A-758, A4WE	SA693CE	Install AC induction air filter type AAF-104. Amended 5/4/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
A-9, A-9B Series; T.C. A-758	SA1743WE	Installation of Automatic Flagman (Marker Dispensing Unit).	NW	03500	Air-Ag, Inc. Route 4 Walla Walla, WA 99362
A-9, A-9B (Restricted Category Only); T.C. A-758	SA2334WE	Installation of Jacobs R755-A2M or R755-SM engine, JAS engine mount, Grumman SR-5404/MA96K-2 propeller and associated equipment. Amended 5/19/72.	WE	46790	Johnston Aircraft Service P.O. Box 757 Tulare Air Park Tulare, CA 93274
A9B; T.C. A-758	SA98RM	Install a Hartzell Model HC-C3YR-1RF/F8468A-6R propeller per Hi-Country Aviation installation instructions, approved 5/10/77. Reissued 4/12/79.	SW	05765	Aircraft Parts & Development Corp. P.O. Box 1849 Laredo, TX 78041

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ARCTIC AIRCRAFT COMPANY, INC.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA-1A Series; T.C. 737, 754	SA4-289	BW-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92509
SA-1A Series; T.C. 737, 754	SA4-1514	Ceconite 101 covering of entire airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SA-1A, A-1A-65F, -85F, -90F; T.C. 737	SA4-1210	Installation of Connex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S-1A, S1A-65F; S-1B1; T.C. A-737, A-754	SA308EA	Installation of A.R.P. Industries, carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 10/31/75.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
S-1A, S1A-65F; S-1B1; T.C. A-737, A-754	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
S-1A, -1A-65F, -85F, -90F; T.C. 737	SA573AL	Install Cleveland wheel assembly 40-28 and Cleveland brake assembly 30-18. Issued 3/31/76.	AL	11610	Arctic Aircraft Company P.O. Box 6141 Anchorage, AK 99502
S-1A, S-1B1, -65F, -85F, -90F; T.C. 737	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Callair, Interstate) S-1A, S-1A-65F, -85F, -90F, S-1B1 (Army L-6, XL-6); T.C. 737, 754	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S-1B1; T.C. A-754	SA415AL	Application of Dacron fabric as exterior covering material. Amended 6/4/71.	AL	11610	Arctic Aircraft Co., Inc. P.O. Box 6141 Anchorage, AK 99502
S-1B1; T.C. A-754	SA468AL	Installation of United Airmotive Inc. model 25-A skis. Issued 1/5/72.	AL	11610	Arctic Aircraft Co., Inc. P.O. Box 6141 Anchorage, AK 99502
S-1B1; T.C. A-754	SA574AL	Install Cleveland wheel assembly 40-28 and Cleveland brake assembly 30-18. Issued 3/31/76.	AL	11610	Arctic Aircraft Company P.O. Box 6141 Anchorage, AK 99502
S-1B1 (Army L-6); T.C. 754	SA1008WE	Installation of poly-fiber covering material of fuselage and empennage. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon; T.C. A7EU	SA1139WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1155EA	Installation of Solar T-62T-39, in lieu of Solar T-62T-29, gas turbine auxiliary power unit and removal of Freon air conditioning systems. Amended 8/15/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon; T.C. A7EU	SA1204WE	Integrated auxiliary power unit and air conditioning system using Solar T-62T-29A gas turbine. Reissued 12/20/77.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon; T.C. A7EU	SA1230WE	Storage box in rear compartment.	WE	62080	Pacific Airmotive Corporation Aircraft & Eng. Center 3000 N. Clybourn Avenue Burbank, CA 91502
Fan Jet Falcon; T.C. A7EU	SA1298WE	Emergency flight instrument system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1336WE	Flight data recorder and cockpit voice recorder.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1337WE	Emergency cabin lighting.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1357SW	Installation of inverter rack. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon; T.C. A7EU	SA1342WE	Installation of accumulator pressure gauges.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1374WE	Installation of Bendix DRA-12 doppler radar system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1436WE	Installation of Shoulder Harness for Pilot Seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1508WE	Installation of an Automated Specialties, Inc. angle of attach system. Amended 9/4/68.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1515SW	Replace existing 13 x 5.0-4 wheel and tire w/14.5 x 5.5-6 wheel and tire. Reissued 4/6/77.	SO	34808	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon; T.C. A7EU	SA1573WE	Installation of Lear Jet Type Air Conditioning System and Auxiliary Heater.	RM	37098	Gates Rubber Company 8601 Montview Boulevard Denver, CO 80220
Fan Jet Falcon; T.C. A7EU	SA1588SW	Foxtronics/IRAMM BT1 600 nickel cadmium battery temperature system. Issued 1/5/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
Fan Jet Falcon; T.C. A7EU	SA1595SW	Transequip cargo handling equipment. Issued 1/22/73.	SW	34810	Federal Express Corporation P.O. Box 493 - Adams Field Little Rock, AR 72203
Fan Jet Falcon; T.C. A7EU	SA1616WE	Installation of ladder and hand rail in aft compartment. Amended 5/23/68.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1621WE	Installation of inverters.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
t+1 Fan Jet Falcon; T.C. A7EU	SA1666SW	Nose wheel steering modification. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA1707WE	Installation of inverters.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon; T.C. A7EU	SA1737SW	WA402001 galley. Issued 10/9/7[illegible].	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon; T.C. A7EU	SA1778WE	Installation of electric floor heater blankets	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1818WE	Installation of Sperry SP-40 Automatic Flight Control System and SPI-73E Sperry Instrumentation System.	WE	74570	Sperry Flight System Division Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
Fan Jet Falcon; T.C. A7EU	SA2058WE	Installation of interior and equipment, including special remote sensing equipment (aerial prospecting). Amended 5/4/70.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA2159WE	Installation of General Precision Laboratories GPF-1000 doppler radar systems. Issued 5/22/70.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91503
Fan Jet Falcon; T.C. A7EU	SA2377SW	Install BH185R-289 EGT temperature indicator system. Issued 11/9/76.	SW	43075	Howell Instruments, Inc. 3479 West Vickery Boulevard Fort Worth, TX 76107
Fan Jet Falcon; T.C. A7EU	SA4067SW	Install Freon air conditioner compressor/condensor package in aft fuselage tail section. Issued 12/6/79.	SW	26230	Cooper Airmotive Aircraft Services P.O. Box 7409 Dallas, TX 75209
Fan Jet Falcon, Fan Jet Falcon C, D, E; T.C. A7EU	SA1102EA	Installation of Teledyne Avionics angle of attack indicating system, P/N SL112B2300. Issued 5/31/78.	EA	78000	Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon and Series C, D, E; T.C. A7EU	SA1398CE	Installation of Collins APS-80 2-axis automatic flight control system integrated with a (partial) ADS-80 air data system. Issued 2/11/78.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
Fan Jet Falcon and Series C, D, E; T.C. A7EU	SA1851WE	Installation of single point pressure fueling system. Amended 6/16/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA28NE	Installation of Canadian Marconi CMA-734 omega navigation system. Amended 3/26/80.	NE	74935	Stead Aviation Corporation Manchester Municipal Airport Manchester, NH 03103
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA30NE	Installation of Global Navigation, Inc. loop antenna, P/N 11455-2, on horizontal stabilizer. Amended 1/17/80.	NE	74935	Stead Aviation Corporation Manchester Municipal Airport Manchester, NH 03103
Fan Jet Falcon; Series C, D, E, F; T.C. A7EU	SA689SW	Revised autopilot static system for Collins AP103F autopilot. Reissued 1/30/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon, Fan JEt Falcon Series C, D, E, F; T.C. A7EU	SA1202EA	Installation of Hamilton Standard R70-3W refrigeration package, P/N 739443-21. Issued 8/4/80.	EA	63275	PAIS, Inc. 7190-B Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1435CE	Addition of improved autopilot static port systems. Issued 9/28/78.	CE	59270	MidCoast Aviation Service, Inc. Lambert Field P.O. Box 10254 St. Louis, MO 63145
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1996SW	Installation of auxliliary landing lights. Issued 11/6/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2568WE	Installation of engine thrust reversers. Amended 10/31/72.	GL	02400	Aeronca, Inc. 1712 Germantown Road Middletown, OH 45042
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2704WE	Installation of (1) engine pylon mounted vertical tail floodlights, (2) horizontal stabilizer mounted vertical tail floodlights or both systems. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2792WE	Installation of Dorne & Margolin antenna assembly (DMN 4-15) on the vertical tail cap. Reissued 12/20/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon and Series E, F; T.C. A7EU	SA2550WE	Installation of Flite-Tronics inverters Model PC-17A. Amended 2/20/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series C, D; T.C. A7EU	SA829EA	Installation of Teledyne Avionics auto throttle system. Reissued 1/7/72.	SW	78127	Teledyne Incorporated 3401 Shiloh Road Garland, TX 75040
Fan Jet Falcon Series C, D, E; T.C. A7EU	SA1137SW	Installation of Teledyne Avionics normalized angle of attack indicating system. Amended 11/9/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA29GL	Installation of equipment rack at fuselage station 00. Issued 7/9/73.	GL	02400	Aeronca, Inc. 1712 Germantown Road Middletown, OH 45042
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA35NE	Installation of Stead Aviation bracket, P/N SA AB1585. Issued 7/18/80.	NE	74935	Stead Aviation Corporation Manchester Airport Manchester, NH 03103
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA57GL	Installation of passenger couch. Reissued 7/10/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA122GL	Installation of radome kit 4076X. Issued 8/16/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST849SO	PPG Industries windshields, Federal Express P/N's 111-0071, (L/H), 111-0072 (R/H), 111-0073 (center). Issued 8/4/75.	SO	34808	Federal Express Corporation 2839 Sprankel Road P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST882SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA891SW	Dorne & Margolin DMN4-15-5 antenna. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA894EA	Installation of Grimes three light strobe kit P/N 34-0302-1 as supplemental lighting. Issued 12/20/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST925SO	Manufacture of main landing gear door arm for Fan Jet Falcon Series airplane. Issued 2/24/77.	SO	05090	Aircraft Equipment Cert. Corp. P.O. Box 18850 Memphis, TN 38118
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST948SO	Installation of Aircraft Equipment Certification Corp. pilot/copilot/ center windshield panels. Amended 6/2/78.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST960SO	Manufacture and installation of Aircraft Equipment Certification Corp. (AECC) modular container and rack assembly. Issued 10/21/77.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST961SO	Replacement of the ball-bearing type right-hand engine throttle crossover cable with a reinforced wire type. Issued 11/15/77.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis International Airport Memphis, TN 38138
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST1001SO	Installation of Federal Express Corp. brake mount flange. Issued 6/6/78.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1163EA	Installation of Solar T-62T-40C APU. Amended 1/23/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1164EA	Installation of cabin air-conditioning flood duct. Amended 10/10/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1172EA	Installation of Hamilton Standard 872-3W air cycle machine, P/N 750660 Model 7/10 heat exchangers P/N 753355. Amended 3/20/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1213SW	Alteration for battery charging from ground power unit. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1461SW	Three Flite-Tronics PC-17A inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1462SW	Collins AP-105/FD-108/FD-109 autopilot/flight director system. Amended 9/28/78.	CE	24250	Rockwell International Collins Radio Group Collins Road Cedar Rapids, IA 52406
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1469SW	Fairchild stem system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1633SW	Three Avionics Instruments, Inc. 1A1000 inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1699SW	Solar T-62T-39 turbine APU. Issued 7/6/73.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1713SW	Couch installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1714SW	Galley installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1768SW	Gulton proximity switch system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1885SW	Solar T62T-39 turbine APU. Issued 6/14/74.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1893SW	Landing light installation, alternate position. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1988SW	Jump seat. Issued 5/20/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2204SW	Installation of electronics rack. Issued 9/14/76.	SW	34280	Fancon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2232SW	Install Collins dual NCS-31 RNAV system. Issued 8/15/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2474SW	Horn silence switch. Issued 6/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2485SW	Fabrication and installation of three-place couch. Issued 8/5/77.	SW	34280	Falcon Jet Corporation LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA3437WE	Installation of Garrett AiRNAV 100 or 300 navigation system. Amended 8/29/80.	WE	07500	AiReserach Manufacturing Co. of California 2525 West 190th Street Torrance, CA 90509
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA4095SW	Radio master system. Issued 3/4/80	SW	34280	Falcon Jet Corporation P.O. Box 6156 Little Rock, AR 72216
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA907CE	Battery temperature indicating and over temperature warning system. Amended June 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 E. Lewis Street Wichita, KS 67202
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA1483SW	Avionics installation (VHF communications, VHF navigation, ADF's DME's, transponders, weather radar radio altimeter, third attitude gyro). Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon Series C, D, E, F, Falcon 10: T.C. A7EU, A10EU	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
Fan Jet Falcon Series C, D, E, F, Mystere 20; T.C. A7EU	SA1193[illegible]	Electrical cable harness assemblies for left and right engines; each consisting of starter-generator cables, starter-generator ground cable, master junction cable and fan tach sensor cable. Amended 2/6/78.	GL	37379	General Electric Company Aviation Service Operation/Cincinnati 260 West Mitchell Avenue Cincinnati, OH 44232
Fan Jet Falcon Series D; T.C. A7EU	SA918EA	Installation of Canadian Marconi CMA-712 doppler navigation system. Reissued 11/9/72.	EA	47665	Karr Electronics Corporation 232 Wescott Drive Rahway, NJ 07065
Fan Jet Falcon Series D; T.C. A7EU	SA993SW	Collins AP-104 Autopilot and FD-109H/FD-109F Flight Directors for Category I and II. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1327WE	Installation of dual inverters. Amended 3/18/69.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon Series D; T.C. A7EU	SA1467SW	Cargo interior. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1468SW	Openable window in co-pilot's side and qualifying existing pilot's and new co-pilot's windows as emergency exits. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1473SW	Replace passenger entrance door with wide cargo door. Amended 7/7/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA2640WE	Installation of a Garrett Model 75 area navigation system. Amended 9/18/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D; T.C. A7EU	SA3394WE	Replacement of cargo barrier net installed per STC SA1467SW with a rigid cargo barrier partition. Issued 7/11/77.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Blvd. Torrence, CA 92680
Fan Jet Falcon Series D, E; T.C. A7EU	SA1771SW	Installation of Sperry SPZ-200 autopilot/flight director control system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 – AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F: T.C. A7EU	SA1570SW	Collins AP105/FD108 autopilot/flight, flight director system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F: T.C. A7EU	SA1577WE	Installation of jump seat. Amended 10/19/70.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D, E, F: T.C. A7EU	SA2404SW	System to disable the take off out of trim warning system when high power is applied during operation of thrust reversers.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA2598AWE	Installation of a Hoskins Model Mk III (Twilighter) anticollision lighting system. Amended 12/21/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
Fan Jet Falcon Series D, F: T.C. A7EU	SA1495SW	Installation of Fairchild voice, recorder model A100 and Lockheed flight recorder model 109C. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series D, F: T.C. A7EU	SA1806SW	Co-pilot brake modification. Issued 2/6/74.	SW	34810	Federal Express Corporation P.O. Box 493 Little Rock, AR 72203
Fan Jet Falcon Series D, F; T.C. A7EU	SA2344SW	Hartman Systems Co. vertical scale engine instruments. Issued 8/11/76.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 – Adams Field Little Rock, AR 72203

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon Series F; T.C. A7EU	SA3714WE	Revise existing interior to include three place side facing divan, galley, storage cabinet, three folding tables, cockpit door, stereo/flitephone cabinet, T.V./recorder cabinet and shoulder harness restraint for divan. Amended 11/22/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 E. Spring Street Long Beach, CA 90806
Fan Jet Falcon Series F; T.C. A7EU	SA1381SW	Installation of Teledyne Avionics normalized angle of attach system, Model 112B500. Amended 2/8/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon Series F; T.C. A7EU	SA1499SW	Installation of inverter system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series F; T.C. A7EU	SA1692SW	Modification of control pedestal. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series F; T.C. A7EU	SA1892SW	Collins ALT-50 radio altimeter. Issued 6/27/74.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series F; T.C. A7EU	SA2479SW	Wiring and antenna provisions, and radio rack for Litton LTN-201 omega system. Issued 7/15/77.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA142GL	Installation of radome kit 4128X. Issued 11/9/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
Falcon 10; T.C. A33EU	ST902SO	Installation of Collins ground proximity warning system. Issued 7/28/76.	SO	24262	Collins Radio Group Rockwell International 1591 Phoenix Boulevard, Suite 1 Atlanta, GA 30349
Falcon 10; T.C. A33EU	SA1002EA	Installation of Sperry SPZ-500/SPI-77D flight control instrument system. Reissued 1/7/80.	SW	07498	Falcon Jet Corporation P.O. Box 167 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA1012EA	Installation of Teledyne Avionics normalized angle of attack indicating system, P/N 112B1600. Issued 8/21/75.	EA	78000	Teledyne Avionics A Division of Teledyne, Inc. P.O. Box 6400 Charlottesville, VA 22906
Falcon 10; T.C. A33EU	SA1042EA	Installation of hydraulically actuated target type thrust reverser system. Amended 7/11/78.	EA	39540	Grumman Aerospace Corporation Bethpage, L.I., NY 11714
Falcon 10; T.C. A33EU	SA1201EA	Installation of cockpit pedestal extension or installation of cockpit pedestal extension and cockpit floor storage box. Issued 7/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
Falcon 10; T.C. A33EU	SA1203EA	Installation of a dual Sperry SPI-501 flight director system. Issued 8/8/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
Falcon 10; T.C. A33EU	SA1223CE	Install King KFC-300 dual flight director flight control system (Category I configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1224CE	Install King KFC-300 dual flight director flight control system (Category II configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1294CE	Installation of Avcon Industries TSO-C39a stretcher, P/N 4001-105 or -106. Issued January 1977.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 North Wichita Station Wichita, KS 67204
Falcon 10; T.C. A33EU	SA1993SW	Install wing ice lights. Issued 6/9/75.	SW	26230	Cooper Airmotive, Inc. Executive Aircraft Division Redbird Airport Dallas, TX 75232
Falcon 10; T.C. A33EU	SA2225SW	Passenger compartment interior. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Falcon 10; T.C. A33EU	SA2226SW	Pressurization of nose cone to improve avionics reliability. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2846WE	Installation of Pulstar two-light supplemental lighting system. Issued 3/4/74.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92705
Falcon 10; T.C. A33EU	SA2957SW	Avionics modification and installations of an 8-passenger executive interior arrangement. Reissued 1/4/78.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2885SW	Install three place couch at Station 181.0 to 239.0 right side. Issued 12/11/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
Falcon 10; T.C. A33EU	SA2919WE	Installation of TFE731-2 engines S/N P73143 and S/N P79101, modified in accordance with STC SE66WE. Issued 8/21/74.	WE	07502	AiResearch Aviation Company 402 S. 36th Street Phoenix, AZ 85034
Falcon 10; T.C. A33EU	SA2983WE	Installation of a Garrett AirNAV 100 area navigation system. Issued 1/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3061WE	Installation of a Garrett AirNAV 100, 200 or 300 navigation system. Amended 8/29/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3544WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 1/27/78	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3557SW	Installation of DeVore Aviation Corp. tail floodlights. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite E 6104 Kircher Street, N.E. Albuquerque, NM 87109
Falcon 10; T.C. A33EU	SA3752WE	Installation of a communications components Ontrac III VLF/Omega navigation system. Issued 10/25/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA4015SW	Nose radio rack. Issued 7/12/79.	SW	34280	Falcon Jet Corporation P.O. Box 7001 Dallas, TX 75209
Falcon 10A; T.C. A33EU	ST153RM	Installation of Canadian Marconi CMA-734 Omega navigation system. Issued 9/11/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
Falcon 20; T.C. A7EU	ST823SO	Installation of SEMCA 14640-113 air conditioning valve. Reissued 7/23/75.	EA	42125	Hermetic Aircraft Instrument Corporation 200 Marine Street Farmingdale, L.I., NY 11735
Mystere-Falcon 50; T.C. A46EU	SA1208EA	Installation of Teledyne Avionics angle of attach system, SL112B4800. Issued 10/8/80.	EA	76000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
AYRES CORPORATION
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S2A; T.C. 2A9	SA653WE	Ceconite 101 covering of fuselage and tail group.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
S-2A, S-2B, S-2C, 600 S-2C, S-2R, 600 S-2D; T.C. 2A9, 2A7, A3SW, A4SW	SA4-1210	All fabric surfaces. Issued 3/21/77.	WE	52090	William G. Lott Box 635, Winter Village Bakersfield, CA 93307
S2A; S2B, S2C, 600-S2C; T.C. 2A9, 2A7	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Snow) S2A, S2B, S2C, 600-S2C, (Aero Commander) 600-S2D, S2R; T.C. 2A9, 2A7, A3SW, A4SW	SA2666WE	Ceconite 102 material covering of: S2A - fuselage and tail group; S2B, S2C, 600-S2C - empennage; 600-S2D - vertical fin, left and right elevators, rudder; S2R - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S2B, S2C, 600-S2C; T.C. 2A7	SA550WE	Wing auxiliary fuel tanks.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S2B; T.C. 2A7	SA609WE	Pratt & Whitney R-1340 AN-1 engine (restricted category only).	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S2B, S2C, 600-S2C; T.C. 2A7	SA1164WE	Ceconite 101 covering of empennage.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
S2C; T.C. 2A7	SA398SW	Electrical system.	SW	19670	C.G. Campbell P.O. Box 605 Archer City, TX 76351
S2C; T.C. 2A7	SA1630WE	Installation of Serv-Aero Engineering vibrodamp engine mount, mount, P/N 2059.	WE	71000	Serv-Aero Engineering, Inc. Salinas Municipal Airport Salinas, CA 93901
S-2C, 600-S2C; T.C. 2A7	SA1650SW	Replace military surplus AT-6 seat with Snow seat assembly 10136-1. Issued 5/7/73.	SW	73400	Snow Engineering Company 3708 Cedar Elm Wichita Falls, TX 76308
S2C, S2D, S2R; T.C. A3SW, 2A7	SA465NW	Installation of EAC-12D40-AG-100-4S propellers on Pratt & Whitney R-1340-AN-1-SH1H-1. Issued 6/13/77.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
600-S2C, -S2D, -S2R, T.C. 2A7, A3SW, A4SW	SA1834WE	Modification and installation of 70 ampere Motorola Model SA-70N-24 alternator (Vasquez P/N FMM-1002) system.	WE	82560	Frank C. Vasquez 5888 East Parkside Drive Fresno, CA 93702
600S-2D, S-2R; T.C. A3SW	SA1651SW	Replace military surplus AT-6 seat with Snow seat assembly 10136-1. Issued 5/7/73.	SW	73400	Snow Engineering Company 3708 Cedar Elm Wichita Falls, TX 76308
600S-2D, S-2R; T.C. A4SW	SA1652SW	Replace military surplus AT-6 seat with Snow seat assembly 10136-1. Issued 5/7/73.	SW	73400	Snow Engineering Company 3708 Cedar Elm Wichita Falls, TX 7630
600-S2C; T.C. 2A7	SA732WE	Replacement engine mount including vibration dampeners.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2C, 600-S2C, S2R, 600 S-2D; T.C. 2A7, A3SW	SA2440WE	Installation of automatic flagman Model No. 4. Issued 2/14/72.	NW	03500	Air-Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
S-2R Thrush; T.C. A4SW	SA24RM	Installation of electrically driven freon air-conditioning system. Amended 4/18/79.	RM	45750	J P Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
S-2R; T.C. A4SW	SA162GL	Install Cleveland Wheel and Brake conversion kit, P/N 199-68A. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S-2R; T.C. A4SW	SA834SO	Installation of Hamilton Standard Model 12D40/6101A-10S propeller approved under STC SP830SO on P&W R1340-AN-1, S1H1 or S3H1 engines listed in TDS A4SW. Issued 4/27/75.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
S-2R; T.C. A4SW	SA1008WE	Installation of poly-fiber covering material of horizontal and vertical stabilizer. Amended 8/21/79.	WE	75250	Stits Aircraft Coatings 43rd South Fort Drive P.O. Box 3084 Riverside, CA 92519
S2R; T.C. A3SW, A4SW	SA1103SO	Installation of a 400-gallon hopper window kit. Issued 9/21/79.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701
S-2R; T.C. A4SW	SA1165CE	Intallation of air conditioning system, restricted category. Issued 9/30/75.	CE	02950	Aero Space Controls Corp. 1050 North Mosley Wichita, KS 67214
S-2R; T.C. A4SW	SA1181CE	Installation of air conditioning system, normal category. Issued 11/21/75.	CE	02950	Aero Space Controls Corp. 1050 North Mosley Wichita, KS 67214
S-2R; T.C. A4SW	SA1638WE	Fabrication and installation of 400-gallon fiberglass hopper. Reissued 10/31/74.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
S-2R; T.C. A3SW	SA2807SW	P&W R1340-AN2 engine and Hamilton Standard 23D40/AG200-0S propeller. Issued 6/30/78.	SW	74986	STC Engineering Company 4410 Northwest 54th Street Oklahoma City, OK 73112
S-2R; T.C. A4SW	SA2901WE	Installation Serv-Aero vibrodamp engine mount in lieu of Aero Commander engine mount. Issued 6/18/74.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2 (R): T.C. A3SW	SA2969WE	Installation of Wright R-1300-1B engine and Hamilton Standard 3D40 or 23D40 constant speed propeller (normal or restricted category). Amended 2/27/75.	NW	47460	J & W Aircraft Company, Inc. P.O. Box 785 Warden, WA 98857
S-2R; T.C. A4SW	SA3227WE	Installation of an AiResearch TPE331-1-101Z, TPE331-25DA or TPE331-25FA turboprop engine. Amended 5/5/78.	WE	75210	Floyd D. Stilwell 5060 East Falcon Mesa, AZ 85205
S-2R; T.C. A4SW	SA3230WE	Installation of Hamilton Standard 3D40/6101A-18 constant speed propeler (restricted category). Issued 7/13/76.	WE	46770	Cliff Johnson 2000 South Union Avenue Bakersfield, CA 93307
S-2R; T.C. A3SW	SA3237WE	Installation of United Aircraft of Canada PT6A-27 or PT6A-34 engine. Amended 8/29/77.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2R; T.C. A3SW	SA3238WE	Installation of a United Aircraft of Canada PT6A-27 or PT6A-34 engine. Amended 8/29/77.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2R (Restricted Category): T.C. A4SW	SA3497WE	Installation of Wright R-1820-71, -60; SR1820G-202A; 702C9GC1, 2, 3, 4; 704C9GC1, 2, 3, 4 engines and Hamilton Standard 4D350 or 33D50 constant speed propeller. Amended 5/22/80.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93905
S-2R (Snow) (Restricted Category): T.C. A4SW	SA3595WE	Installation of dual controls and bench seat. Issued 2/16/78.	WE	55627	Marsh Aviation Company 5060 East Falcon Drive Mesa, AZ 85205
S-2R (Restricted Category): T.C. A4SW	SA3767WE	Installation of 500 gallon fiberglass hopper and relocated oil cooler. Issued 10/26/78.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (Normal Category): T.C. A3SW	SA3842WE	Installation of 500 gallon fiberglass hopper and relocated oil cooler and deletion of the alternate air inlet doors. Reissued 3/7/79.	SO	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R (as modified under STC SA3227WE): T.C. A4SW	SA3886WE	Installation of Aerospace Controls Corp. No. 1922 air conditioning air conditioning system. Issued 3/20/79.	WE	55627	Marsh Aviation Company 5060 East Falcon Drive Mesa, AZ 85205

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S-2R (Restricted Category); T.C. A4SW	SA3889WE	Installation of Goodyear brake assembly P/N 95-50377 or P/N 5308865, Goodyear wheel assembly P/N 50-00444 or P/N 530884, and 11.00-13, Type III, 8 P.R. tire. Amended 6/15/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90907
S-2R (Restricted Category); T.C. A4SW	SA3890WE	Installation of Wright R-1820-40, -60, -71, -87 engine and Hamilton Standard 33D50 or 43D50 constant speed propeller. Amended 5/18/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
S-2R (Restricted Category); T.C. A4SW	SA3897WE	Installation of Pezetel Model PZL-3S engine and Dowty Rotol model CR289/3-110-F/1 propeller. Issued 4/11/79.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93905
S-2R; T.C. A3SW	SA3927WE	Installation of an AiResearch TPE331-1-1012 turboprop engine. Issued 5/11/79.	WE	75210	Floyd D. Stilwell 5060 East Falcon Drive Mesa, AZ 85205
S-2R; T.C. A4SW	SA3961WE	Installation of extended engine mount, revised cowling and induction system, Hamilton Standard 22D40 or 12D40 constant speed propeller, and modified elevator trim tab system. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708
S-2R; T.C. A4SW	SA4039SW	Lycoming LTP-101-600A1A turboprop. Issued 9/25/79.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
S-2R; T.C. A4SW	SA4109WE	Installation of cockpit canopy/ fuselage fairing. Issued 3/7/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R, S-2D; T.C. A4SW	SA4110WE	Installation of spring-type tail wheel strut assembly. Amended 8/1/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R (Restricted Category); T.C. A4SW	SA4111WE	Installation of Wright R-1820-71, -60; SR1820G-202A; 702C9GC1, 2, 3, 4; 704C9G1, 2, 3, 4 engines and Hamilton Standard 43D50 or 33D50 constant speed propeller. Amended 5/22/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R, S/N 2526R and up modified by STC SA3961WE; T.C. A4SW	SA4112WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708
S-2R, S/N 2526R and up modified by STC SA3961WE, Normal Category: T.C. A3SW	SA4113WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708
S-2R (S/N 2526R and up modified by STC SA3897WE), S-2R-R3S (S/N R3S-001 and up); T.C. A4SW	SA4038WE	Installation of second pilot's seat and dual controls. Issued 10/29/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category); T.C. A3SW	SA4045WE	Installation of second pilot's seat and dual controls. Reissued 1/29/80.	SO	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up as modified by STC SA3897WE); T.C. A4SW	SA4046WE	Installation of passenger/cargo compartment. Reissued 1/29/80.	SO	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category); T.C. A3SW	SA4047WE	Installation of passenger/cargo compartment. Reissued 1/29/80.	SO	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R, S/N 2526R and up modified by STC SA3239WE, S-2R-T34 S/N 6009-6049, S/N T34-001 and up; T.C. A4SW	SA4107WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S-2R S/N 2526R and up modified by STC SA3237WE, S-2R-T34 S/N 6000-6049, S/N T34-001 and up (normal category); T.C. A3SW	SA4108SO	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708
600 S2D, 800 S-2R; T.C. A4SW	SA266NW	Installation of automatic flagman Model No. 6. Amended 5/12/77.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362
S2R-T34 (Normal Category), S2R-T15 (Restricted Category); T.C. A3SW, A4SW	SA1073WE	Installation of a 500 gallon hopper vent blister kit. Issued 5/29/79.	WE	79295	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
BEECH AIRCRAFT CORP.
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
AT-11; T.C. 2-582	SA1-50	Installation of Hartzell Propellers without and with unfeathering kit. amended 10/23/67.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
AT-11; T.C. 2-582	SA1-109	Floorboard.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
AT-11; T.C. 2-582	SA3-385	L-2C autopilot with or without automatic altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
AT-11; T.C. 2-582	SA3-441	Main landing gear.	GL	22790	John J. Clark 305 N. Owen Street Mt. Prospect, IL 60056
AT-11; T.C. 2-582	SA4-109	Seat track.	WE	82600	Vegas Airways, Inc. P.O. Box 347 Redondo Beach, CA 90277
AT-11; T.C. 2-582	SA4-833	Glass cloth on rudders, elevators, flaps and ailerons.	WE	38060	Glasco-Air Products 1125 First Street San Fernando, CA 91340
AT-11; T.C. 2-582	SA4-1238	Hamilton Standard full-feathering propellers, hubs 22D30-33 and blades 6531A-15; feathering pumps, Pesco 1F301 DE-3; Hamilton Standard 4B2-P6 governors.	RM	18380	Ken Burnham Aviation Service 1326 N. Prospect Street Colorado Springs, CO 80901
AT-11 (Army), SNB-1 (Navy), B17B, B17L, SB17L, B17R, C17B, C17L, SC17L, C17R, SC17R, D17A, D17R, D17S, SD17S, E17B, SE17B, E17L, F17D, SF17D, G17S, 18A, S18A, 18D, S18D, A18A, SA18A, A18D, SA18D, 18S, B18S, C18S, D18C, D18S, E18S, G18S, H18, C45G, TC45G, C45H, TC45H, TC45J, JRB6, SNB5; T.C. 2-582, 560, 579, 602, 604, 713, 638, 649, 641, 689, 779, 630, 684, 710, 737, 765	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Army) AT-11, (Navy) SNB-1, D17A, D17R, D17S, SD17S, E17B, F17D, C18S, D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45H, TC-45J, JRB-6; T.C. 2-582, 713, 638, 649, 641, 689, 757, 765	SA2666WE	Ceconite 102 material covering of: 2-582, C18S, D18C, D18S, E18S, E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J, JRB-6 - rudders, elevators, ailerons, and flaps; D17A, D17R, D17S, SD17S, E17B, F17D - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
AT-11; T.C. 2-582	SA4WE	Main cabin door and hinge pins removed.	WE	70310	Schaefer's Air Service 4627 Beverly Boulevard Los Angeles, CA 90052
AT-11, SNB-1; T.C. 2-582	SA1151CE	Install crack detection system. Issued 12/23/75.	WE	39877	Gordon B. Hamilton 4215 East Cooper Tucson, AZ 85711
AT-11, SNB-1; T.C. 2-582	SA3021WE	Installation of wing spar reinforcement. Reissued 5/20/77.	WE	03000	Aerospace Products, Inc. 5536 Satsuma Avenue Hollywood, CA 91406
AT-11, 18 Series; T.C. 2-582, 757	SA4-108	Cabin door width increased by 10 or 14 inches.	WE	82600	Vegas Airways, Inc. P.O. Box 347 Redondo Beach, CA 90277
AT-11, 18 Series; T.C. 2-582, 757	SA4-128	Engines, propellers, revised nacelles, wheel-well doors, airspeed system, fuel system and elevator seal strips. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
AT-11, 18 Series: T.C. 2-582, 757	SA4-819	Ceconite 101 covering of rudders, elevators, ailerons and flaps.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
AT-11, 18 Series: T.C. 2-582, 757	SA1125SO	Substitute control wheel.	SO	37086	Garcia Aviation Company 15801 S.W. 120th Avenue Miami, FL 33101
AT-11, 18 Series: T.C. 2-582, 757	SA2499SO	Increase in takeoff weight to 10,200 lbs. and landing weight to 9,800 lbs. and extension of aft C.G. limit to (+120.5) at 10,200 lbs. (Model may also be designated as Conrad 10,200.) Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
AT-11, 18 Series: T.C. 2-582, 757, 765	SA3-86	Installation of RCA AVQ-50 radar antenna mount. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
AT-11, 18 Series: T.C. 2-582, 757, 765	SA4-1069	Left and right cowl flaps with electronic actuators, control switches, and indicator.	WE	62442	Paragon Tool Die & Engineering 11035 Sutter Avenue Pacoima, CA 91331
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA1-61	Auxiliary outboard wing tanks. Amended 2/14/69.	WE	03000	Aerospace Products, INc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA1-236	Air stair door. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA4-34	Main landing gear door. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA4-120	Dual airspeed system. Reissued 8/15/68.	SO	08190	Airline Training, Inc. P.O. Box 22833 South Andrews Station Ft. Lauderdale, FL 33315
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA4-855	Windows in cabin.	WE	84000	Volpar, Inc. 16300 Stagg Street Van Nuys, CA 94106
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA4-1030	Fonite covering on all control surfaces including flaps.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA4-1047	Fiberglas nose cone. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA4-1122	Interior card table, accordian door and indirect lighting. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA4-1198	Aft bulkhead removal.	WE	10360	American Turbine Engineering Co. 1150 Busch Gardens Court Pasadena, CA 91105
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA4-1427	Pratt & Whitney R-985 Series engines modified for fuel injection.	GL	15500	The Bendix Corporation 401 Bendix Drive South Bend, IN 46600
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA125SW	Hand operated cowl flap.	SW	14060	Avio Engineering Company, Inc. 11140 Pinocchio Drive Dallas, TX 75235
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA485WE	Metal covering on elevator, aileron, rudder and flap. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series: T.C. 2-582, 757, 765	SA565WE	Wing tips. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45: T.C. 2-582, 757, 765, 770	SA4-711	Power air step (retractable entrance step). Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406
AT-11, 18, C45 Series: T.C. 2-582, 765	SA3-232	Sonotone CA6 (24 H320) or one Sonotone CA7 (19 cell 12H120) battery.	GL	71520	George W. Sherwood 11107 Nashville Detroit, MI 48233
AT-11, 18, C45 Series: T.C. 2-582, 765	SA18WE	Redesign bulkhead 5 to accommodate an accordian door. Amended 2/14/69.	WE	03000	Aerospace Products, Inc. 5523 Satsuma Avenue North Hollywood, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
23 (S/N M-555 and up), A23, A23A, A23-19, A23-24, B23, C23, 19A, B19, M19A, A24, A24R, B24R, C24R; T.C. A1CE	SA1147EA	Installation of DeVore vertical tail floodlights on upper surface of horizontal stabilator. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
23, A23, A23A, A23-19, -19A, -24, B23; 35, A35 thru G35; 35-33, -A33, -B33, -C33, -C33A, H35, J-, K-, M-, N-, P-, S-, V-; 95, B95, B95A, -55, -A55, B55, B55B, C-55; T.C. A1CE, A777, 3A15, 3A16	SA1262WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
23, A23, A23A, A23-19, A23-24; S35, V35, 35-33, 35-A33, B-33, -C33, 35-C33A; 50, B50, C, D, D50A, B, C, E, F50, F, G, H, J; 95, B95, -A, D95A, -55, -A55, -B55, C-55; T.C. A1CE, 3A15, 5A4, 3A16	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R; T.C. A1CE	SA1346SW	Mitchell automatic flight system AK341 cons. of Century I and opt. Omni Tracker. Issued 7/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R; T.C. A1CE	SA1348SW	Mitchell automatic flight system AK342 cons. of Century II autopilot with opt. radio coupler. Issued 7/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
23, A-23, A-23A, A23-19, A-23-24, 19A, B23; 35, A35, B35, C35, 35R, D35, E-, F-, G-; H35, J-K-M-, 35-33, N35, 35-A33-B33, P35, S35, 35-C33, E33, V35, V35A, 35-C33A, E33A; T.C. A1CE, 777, 3A15	SA1716WE	Installation of exhaust gas temperature system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
23, A23, A23A, A23-19, 19A, B19, M19A, A23-24, B23, C23, A24, A24R, B24R; T.C. A1CE	SA3214SW-D	Mitchell automatic flight system AK342 consisting of Century IIB autopilot with optional radio coupler. Issued 6/27/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
23, A23, A23A, A23-19, 19A, M19, M19A, A23-24 B23, C23, A24, A24R, B24R, C24R; T.C. A1CE	SA3223SW-D	Mitchell automatic flight system consisting of Century I autopilot and optional omni tracker. Issued 6/21/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A23-24; T.C. A1CE	SA3291WE	Installation of Pathfinder autopilot systems. Issued 11/9/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
B23; T.C. A1CE	SA664CE	Installation of Hoskins MK1B Light System. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
C23; T.C. A1CE	SA437GL	Installation of Tull microwave landing system airborne equipment. Issued 8/22/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
C23; T.C. A1CE	SA3331SW-D	Mitchell automatic flight system AK779, consisting of Century I autopilot with optional omni tracker. Issued 1/24/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Walls, TX 76067
C23; T.C. A1CE	SA3332SW-D	Mitchell automatic flight system AK780 consisting of Century IIB autopilot with optional radio couplers. Issued 1/24/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
Beech C23; T.C. A1CE	SA3799WE	Installation of flexible stainless steel oil cooler hoses. Issued 11/28/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A24R, B24R, C24R: T.C. A1CE	SA4015WE	Installation of SDI model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 9/17/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
B24R; T.C. A1CE	SA1701SW	Mitchell command electric trim system Model AK454. Issued 7/11/73.	SW	60000	Mitchell Industries, Inc. Box 610 Municipal Airport Mineral Wells, TX 76067
B24R; T.C. A1CE	SA3016SW-D	Mitchell AK544 cons. of Century III autopilot with opt. radio coupler and glide slope coupler. Issued 1/28/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
B24R; C24R; T.C. A1CE	SA3156WE	Installation of Pathfinder autopilot systems. Issued 3/16/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
B24R, C24R; T.C. A1CE	SA3160SW-D	Install Mitchell command electric trim system Model AK454. Issued 10/4/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C24R; T.C. A1CE	SA3313SW-D	Mitchell automatic flight system AK768, consisting of Century IIB autopilot with optional radio coupler. Issued 12/29/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C24R; T.C. A1CE	SA3314SW-D	Mitchell automatic flight system AK769 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 12/28/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C24R; T.C. A1CE	SA3315SW-D	Mitchell command electric trim, AK770. Issued 12/28/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral WElls, TX 76067
35 "Bonanza"; T.C. 777	SA1-460	Auxiliary wing tip fuel tanks. Reissued 2/14/75	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route #1, Box 172D Leesburg, FL 32738
35 Series; T.C. 777	SA222CE	Reinforce front lower carry-through section & wing attach fittings. Amended 6/2/80.	CE	47250	R.M. Jourdan & James Flanagan 11001 East 59th Street Raytown, MO 64133
35 Series; T.C. 777	SA3878SO	Installation of Aviation Elec. Omni bearing tester Model OBT-X in accordance with AET Drawing Nos. 1001, 1002, 1003.	SO	13250	Aviation Electronics, Inc. DeKalb-Peachtree Airport Chamblee, GA 30005
35 Series; T.C. 777	SA599EA	Installation electronic voltage alarm, Drawing No. 80105.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
35 Series; T.C. 777	SA800SW	AK245 Century II Autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777	SA1493WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777	SA1902SW	Automatic flight system AK348 cons. of Century I autopilot with optional omni tracker. Issued 7/19/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
35 Series; T.C. 777	SA2144WE	Installation of Madras Air Service Part No. MAS 102 wing tips.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
35 Series; T.C. 777	SA2208WE	Installation of Red-Q-Mark Signet A-MK-100 or A-MK-110 marker assembly. Amended 9/7/70.	WE	67500	Res-Q-Mark International, Inc. 44 West Stetson Drive Scottsdale, AZ 85251
35 Series; T.C. 777, 3A15	SA1-55	Federal F-200 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
35 Series; T.C. 777, 3A15	SA1-341	Oil-free vacuum pump PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35 Series: T.C. 777, 3A15	SA1-343	Oil-free vacuum pump.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
35 Series: T.C. 777, 3A15	SA1-377	Replacement of d.c. belt-driven generator and regulator with Leece-Neville belt-driven alternator with built-in silicon rectifier.	SO	33239	Ellingsworth Products Co., Inc. 1009 E. Broadway Louisville, KY 40201
35 Series: T.C. 777, 3A15	SA1-379	Lube oil filter PB55-1 on aircraft with Continental E-185-1 through -11 engines. Amended 9/11/67.	NE	36728	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
35 Series: T.C. 777, 3A15	SA1-478	Griswold lateralizer.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109
35 Series: T.C. 777, 3A15	SA1-491	Flare rack modification to include radio equipment mount.	NE	81400	Usher Aviation Radio Division Municipal Airport New Haven, CT 06510
35 Series: T.C. 777, 3A15	SA1-569	Continental IO-470-J engine (fuel injection) and Hartzell propeller BHC-92ZF-1D1/8447.	EA	74930	Glen Stauffer 1000 Susquehanna Avenue West Pittston, PA 18643
35 Series: T.C. 777, 3A15	SA1-584	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
35 Series: T.C. 777, 3A15	SA1-587	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
35 Series: T.C. 777, 3A15	SA1-628	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
35 Series: T.C. 777, 3A15	SA3-3	BC Chinook cabin heater.	RM	28500	Dakota Aviation Company P.O. Box 18 Huron, SD 57350
35 Series: T.C. 777, 3A15	SA3-8	L-2P automatic pilot including approach coupler and altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series: T.C. 777, 3A15	SA3-56	Oxygen equipment, Purtain Type E bottles and Scott #8800 console.	GL	15850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
35 Series: T.C. 777, 3A15	SA3-58	Grimes D-7080-2-12 rotating beacon.	GL	60135	Moody Bible Institute 820 N. LaSalle Street Chicago, IL 60607
35 Series: T.C. 777, 3A15	SA3-196	Lear ADF-12C kit complete and LTRA-5 with scope complete.	GL	17070	Louis J. Prandix, Sr. Southwest Airport Springfield, IL 62701
35 Series: T.C. 777, 3A15	SA3-241	Electric motor-driven AN4100 fuel pump.	GL	37076	C.W. Gaenzler Wayne Major Airport Inkster, MI 48141
35 Series: T.C. 777, 3A15	SA3-264	Radio rack aft of baggage compartment.	CE	44340	Interstate Airmotive, Inc. Lambert Field St. Louis, MO 63155
35 Seris: T.C. 777, 3A15	SA3-276	Scott 8800 oxygen console.	CE	78616	Topeka Aircraft Sales & Service Municipal Airport Topeka, KS 66603
35 Series: T.C. 777, 3A15	SA3-298	Electric motor-driven fuel booster pump.	GL	37076	Carl W. Gaenzler Wayne Major Airport Inkster, MI 48141
35 Series: T.C. 777, 3A15	SA3-317	Baggage compartment windows.	CE	40686	Gordon O. Harper 6070 Grant Street Omaha, NE 68108
35 Series: T.C. 777, 3A15	SA3-673	L-2B autopilot with or without altitude control and/or approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series: T.C. 777, 3A15	SA4-96	Manual-electric control for Beech 215-107/215-207-88 propeller.	WE	23426	C & M Plumbing & Heating 11667 Monte Vista Avenue Chino, CA 97170

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	SIC CODE	STC HOLDER
35 Series: T.C. 777, 3A15	SA4-133	Automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
35 Series: T.C. 777, 3A15	SA4-190	Automatic rudder control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series: T.C. 777, 3A15	SA4-191	F-2 automatic pilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series: T.C. 777, 3A15	SA4-239	Thompson TF 2800 engine-driven fuel pump installation on Continental O-470-3 engine.	WE	33460	Engineering Modification Company 6850 Vineland Avenue North Hollywood, CA 91603
35 Series: T.C. 777, 3A15	SA4-280	Ceco CE-9136, AN-4100 or AN-4101 electric fuel pump.	WE	38200	Peter Gluckmann 61 Lick Place San Francisco, CA 94101
35 Series: T.C. 777, 3A15	SA4-282	Tactair T-3 automatic pilot.	WE	64708	Planeservice, Inc. 7250 Hayvenhurst Avenue Van Nuys, CA 91408
35 Series: T.C. 777, 3A15	SA4-344	"RP" arcon system.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
35 Series: T.C. 777, 3A15	SA4-393	Fiberglas reinforced plastic wing tips incorporating positions.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
35 Series: T.C. 777, 3A15	SA4-435	Automatic rudder control Model B.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series: T.C. 777, 3A15	SA4-436	F-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series: T.C. 777, 3A15	SA4-489	Automatic rudder control.	NW	35690	Flightcraft, Inc. 6200 N.E. Marine Drive Portland, OR 97208
35 Series: T.C. 777, 3A15	SA4-550	Continental E-225-8 engine with Hartzell HC-12X20-7C/8433 propeller and modification of fuel system.	WE	60178	D.H. Moreton 560 Marquette Street Pacific Palisades, CA 90272
35 Series: T.C. 777, 3A15	SA4-559	20-gallon auxiliary fuel tank.	WE	77260	Symons Engineering P.O. Box 45002 Airport Station Los Angeles, CA 90009
35 Series: T.C. 777, 3A15	SA4-562	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
35 Series: T.C. 777, 3A15	SA4-618	Right and left rear windows.	NW	61710	Northwest Air Service P.O. Box 20 Boeing Field Seattle, WA 98101
35 Series: T.C. 777, 3A15	SA4-651	Continental E-225-8 engine and Hartzell propeller.	WE	19945	Carson Airplane SErvice Gillespie Field Santee, CA 92071
35 Series: T.C. 777, 3A15	SA4-703	30409A lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corportation 4069 Hollis Street Oakland, CA 94608
35 Series: T.C. 777, 3A15	SA4-707	Aerofilter 30409A lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
35 Series: T.C. 777, 3A15	SA4-709	Aerofilter 30409A lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
35 Series: T.C. 777, 3A15	SA4-716	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series: T.C. 777, 3A15	SA4-785	Hartzell HC-12X20-7D/8433-0 propeller.	WE	86300	R.K. Wilson 3808 Via La Selva Palos Verdes Estates, CA 90274

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35 Series; T.C. 777, 3A15	SA4-819	Hartzell HC-12X20-7D/8433-0 propeller.	WE	78618	Torpet Aircraft, Inc. Orange County Airport Santa Ana, CA 92702
35 Series; T.C. 777, 3A15	SA4-862	Wing tip modification to fiberglass construction.	WE	38235	C.E. Goetz 11665 Monte Vista Avenue Chino, CA 91710
35 Series; T.C. 777, 3A15	SA4-1146	Hartzell HC-12X20-7C/8433-0 propeller.	WE	09730	Alpha Aircraft P.O. Box 63 Bakersfield, CA 93300
35 Series; T.C. 777, 3A15	SA4-1239	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA4-1245	Ski bag compartment.	NW	35690	Flightcraft, Inc. 6200 N.E. Marine Drive Portland, OR 97208
35 Series; T.C. 777, 3A15	SA4-1260	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series; T.C. 777, 3A15	SA4-1305	Hartzell HC-12X20-7E/8433-0 propeller.	WE	21400	Chandler Aircraft Service 151 W. Lambert Avenue El Monte, CA 91731
35 Series; T.C. 777, 3A15	SA4-1437	Leece-Neville alternator A001-2002AA and regulator A001-3533RA.	WE	82600	Vegas Airways, Inc. P.O. Box 347 Redondo Beech, CA 90277
35 Series; T.C. 777, 3A15	SA4-1538	Oil-air separator.	WE	81790	Vaeth Aircraft Repair 13 and Benson Streets Upland, CA 91786
35 Series; T.C. 777, 3A15	SA4-1611	Anticollision beacon Roto-Lite X5000, either 12 or 24-volt, on the top or bottom of fuselage.	WE	49690	The Norman Larson Company Van Nuys Airport Van Nuys, CA 91408
35 Series; T.C. 777, 3A15	SA4-1620	Installation of Brittain Industries Model M668 wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d.b.a. Osborne Tank & Supply Star Route, Box 12 Oro Grande, CA 92368
35 Series; T.C. 777, 3A15	SA13EA	Single-axis autopilot AF-510A, AF-512A or AF-512B.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005
35 Series; T.C. 777, 3A15	SA22SW	AK087, AK087E or AK087P automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA23CE	210419 governor.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
35 Series; T.C. 777, 3A15	SA33SW	Beech T-24 ailerons 45-135050-3 with servo attach fittings 45-115090.	SW	05070	Aircraft & Engine Enterprises P.O. Box 68 Moore, OK 73060
35 Series; T.C. 777, 3A15	SA81SW	Continental engine modified for fuel injection per STC SE23SW.	GL	15500	The Bendix Corporation 717 N. Bendix Drive South Bend, IN 46600
35 Series; T.C. 777, 3A15	SA57CE	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
35 Series; T.C. 777, 3A15	SA64SW	AK100 automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA90SW	AK101 automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA91SW	AK102 automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series; T.C. 777, 3A15	SA109WE	M-4 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
35 Series; T.C. 777, 3A15	SA112EA	AF-510A, AF-512A or AF-512B autopilots.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35 Series: T.C. 777, 3A15	SA115CE	Turbo volt Model "Three-Five" emergency electrical and vacuum system.	GL	84500	Ward Aero, Inc. P.O. Box 219 Haines Airport Three Rivers, MI 49093
35 Series: T.C. 777, 3A15	SA115SW	Combustion monitor.	SW	77110	The Swearingen Company P.O. Box 6904 San Antonio, TX 78209
35 Series: T.C. 777, 3A15	SA130EA	AF-510A, AF-512A, or AF-512B autopilots.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005
35 Series: T.C. 777, 3A15	SA136WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series: T.C. 777, 3A15	SA137WE	Beech wing tip kit 35-660.	WE	21400	Chandler Aircraft Service 151 W. Lambert Avenue El Monte, CA 91731
35 Series: T.C. 777, 3A15	SA147CE	Moni-Meters on aircraft equipped with King KY-90, KY-95, Narco Mark 4 or 12 transceivers.	GL	60086	Mobile Engineering 220 Southdale Center Minneapolis, MN 55435
35 Series: T.C. 777, 3A15	SA152CE	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
35 Series: T.C. 777, 3A15	SA165SW	Automatic pilot AK121.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 Series: T.C. 777, 3A15	SA219EA	Installation of Katz Integrated Flight Indicator. Amended 5/21/69.	NE	36300	Forest City Aviation Service 749 Congress Street Portland, ME 04102
35 Series: T.C. 777, 3A15	SA265SO	Extension addition to nose landing gear doors.	SO	43504	Thomas E. Hutchinson P.O. Box 128 Morrisville, NC 27560
35 Series: T.C. 777, 3A15	SA269WE	Pneumatic pitch assist PC-1 and optional installation altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series: T.C. 777, 3A15	SA292WE	Alternator A-14-0 or A-14-5 and voltage regulator A-20.	WE	14000	Aviation Specialities Company, Inc. 2410 E. Airline Way Phoenix, AZ 85000
35 Series: T.C. 777, 3A15	SA293CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Place Port Columbus Int'l Airport Columbus, OH 43219
35 Series: T.C. 777, 3A15	SA294CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Place Port Columbus Int'l Airport Columbus, OH 43219
35 Series: T.C. 777, 3A15	SA312WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series: T.C. 777, 3A15	SA321SO	Tank type wing tip plates.	SO	26580	Corben Development Corporation P.O. Box 1603 Venice, FL 33595
35 Series: T.C. 777, 3A15	SA321WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series: T.C. 777, 3A15	SA322WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series: T.C. 777, 3A15	SA323WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35 Series: T.C. 777, 3A15	SA332EA	Electronic voltage alarm.	EA	53500	McKinley Engineering Company P.O. Box 275 Palisades Park, NJ 07650
35 Series: T.C. 777, 3A15	SA334SW	Alternator.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78205
35 Series: T.C. 777, 3A15	SA359SW	Carburetor air filter (dry type).	SW	77016	The Superior Flow Company P.O. Box 12504 Oklahoma City, OK 73112

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA1-570	Installation of Hartzell Model HC-A2X20-4 or HC-A2V20-4 propeller equipped with 8433 or 8833-4 or V8433, V8833-4 blades respectively. Amended 6/29/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
35, A35 thru G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36; T.C. A-777, 3A15	SA11GL	Installation of Cleveland 6.00-6 wheels and brakes. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
35, A35 thru G35, H35, 35R, J35, K35, M35, N35, P35, S35, 45, A45, D45, 95, B95, B95A, D95A, E95, 95-55, -A55, -B55A, -B55B, -B55, -C55, -C55A, E55, D55, D55A, E55, F55A; T.C. A-777, 3A15, 3A16	SA19GL	Install Cleveland 7.00-8 wheels and brakes. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
35, A35 thru H35, J35, K35, 35R, 95; T.C. A-777, 3A15	SA23EA	Installation of third cabin window on both sides of fuselage. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, J35, K35, M35, 35-33; T.C. A777, 3A15	SA28EA	Installation of 12-gallon fiberglass wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, J35, K35, M35, 35-33; T.C. A777, 3A15	SA30EA	Installation of 13.5 gallon fiberglass wing tip tank assembly. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, 35R, D35, E35, F35, G35: T.C. 777	SA41EA	Wet-to-dry vacuum pump conversion kit 300-2. Reissued and Amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
35, A35 thru P35, 35-33, -A33, -B33; T.C. A777, 3A15	SA80EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35, A35 thru H35, J35, K35, M35, N35, P35, S35, V35, 33, A33, B33, C33, C33A, E33, E33A, 55, A55, B55, B55A, B55B, C55, C55A, D55, D55A, 95, B95, B95A, D95A, E95; T.C. A-777, 3A15, 3A16	SA93GL	Install left hand side window, P/N W-2048 or W/T-2048. Amended 6/19/79.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
35, A35 thru H35, J35, K35, M35, N35, P35, S35, V35, 33, A33, B33, C33, C33A, E33, E33A, 55, A55, B55, B55A, B55B, C55, C55A, D55, D55A: T.C. A-777, 3A15, 3A16	SA94GL	Install right side door window, P/N W-2049 or W/T-2049. Amended 6/19/79.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
35, A35 thru H35, J35, K35, M35, N35, P35, S35, 33, A33, B33, 55, A55, B55, B55A, B55B, 95, B95, B95A, D95A, E95; T.C. A-777, 3A15, 3A16	SA95GL	Install one piece windshield (P/N W2050 or WT2050). Amended 6/19/79.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
35, A35, B35, C35, D35, E35, F35, G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. A-777, 3A15	SA152NW	Installation of deck and glare shield (with or without instrument lights). Issued 1/13/75.	NW	70384	R.J. Schroers 4479 139th Avenue, S.E. Bellview, WA 98006

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, A35 thru H35, J35, K35, M35, N35, 35R, 35-33, 35-A33; T.C. A-777, 3A15	SA177EA	Installation of Monitair angle of attach system, Model AA-2. Reissued 2/14/72.	GI	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
35, A35, B35, C35, D35, E35, F35, G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33A, F33, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A; T.C. A-777, 3A15	SA197NW	Installation of Clark three-light gear position indicator system. Issued 7/17/75.	NW	22786	Harold M. Clark, Jr. 7703 Husky Loop S.E. Olympia, WA 98503
35, A35 thru H35, J35, K35, M35, 35-33, N35, P35; T.C. A777, 3A15	SA283EA	Alternate fiberglass fuel tip tanks. Reissued 2/6/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, 35R, J35, K35, M35, N35, P35, 35-33, S-35, 35B-33, V35, V35TC, 35-A33, -C33, -C33A, 95-55, -A55, -B55, -C55, 95, B95, B95A, D95: T.C. A777, 3A15	SA593WE	Installation of single-piece windshield. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B- thru H-, J-, K-, M-, N-, P-, S-, V-; 65-88; 95-55, -A55, -B55, B55B, -C55; T.C. 3A15/A-777, 3A20, 3A16	SA808SW	Installation of Mitchell Model AK206 omni-tracker. Applicable only to aircraft modified by the following STCs SA617SW, SA638SW, SA651SW, SA701SW, SA742SW, SA754SW, SA755SW.	SW	60000	EDO-AIRE Mitchell P.O. Box 610 Mineral Wells, TX 76067
35, A35 thru G35, 35R, H35 thru S35, 35-33, -C33, E33, F33, F33A, E33C, G33, V35, V35A, B, 36, A36, A36TC; T.C. 3A15, A-777	SA809SO	Installation of Beryl D'Shannon fiberglass tip tanks (15 gallons each), and fuel transfer system. Amended 2/8/80.	SO	16505	Beryl D'Shannon Specialties, Inc. Suite 120 175 West Wieuca Road Atlanta, GA 30342
35, A35 thru G35, 35R, H35, J35, K35, M35, N35, P35, S35, V35; T.C. A-777, 3A15	SA838SO	Installation of Beryl D'Shannon fiberglass air scoops (inlet and exit). Amended 12/16/76.	SO	16505	Beryl D'Shannon Aviation P.O. Box 76155 Atlanta, GA 30328
35, A35 thru G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35 thru S35, V35, V35A, V35B, 36, 36A; T.C. A-777, 3A15	SA942SO	Installation of adjustable directional trim device on lower aft fuselage (ventral location) Issued 7/1/77.	SO	16505	Beryl D'Shannon Aviation Specialities, Inc. P.O. Box 76155 Atlanta, GA 30328
35 thru 35R, 35-33 thru A36; T.C. 3A15, A-777	SA995SO	Installation of a single-piece sloped windshield. Amended 5/7/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4530 Jettridge Drive, N.W. Atlanta, GA 30327
35 thru 35R, 35-33 thru A-36; T.C. 3A15, A-777	SA997SO	Installation of a single-piece sloped windshield. Amended 11/21/79.	SO	16505	Beryl D' Shannon Aviation Specialties, Inc. c/o F.K. Leddick & Associates, Inc. 175 W. Wieuca Rd., Suite 120 Atlanta, GA 30342
35, A35, B35, C35, D35, E35, F35, G35, 35R (S/N D-1 thru D-4865): T.C. 777	SA999WE	Installation of either Tasco #6340-1 (35A) alternator kit or Tasco #6555-1 (50A) alternator kit. Amended 10/28/76.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
35, 33, 36, 45 Series; T.C. A777, 3A15, 5A3	SA1000CE	Install cabin and engine compart-fire suppression system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
35, A35, B35, C35 (up to and including S.N. 2901): T.C. A-777	SA1375WE	Installation of Dukes Astronautics Model 4140-00-39 Auxiliary Fuel Pump into fuel system.	NW	24200	Collins Aviation Service 6660 Perimeter Road Boeing Field Seattle, WA 98108
35, 33, 95, 56 Series; T.C. 3A15, 3A16	SA1497SW	Sombra screen kit No. BE-6L, BE-6S, BE-4. Issued 8/11/72.	SW	73750	Sombra Corporation 1122 LaVista Drive McAllen, TX 78501
35, A35 thru G35, 35R, H35, J35, K35, M35, N35, P35; T.C. 777, 3A15	SA1722WE	Installation of Fiberglass tail fairing. Reissued 1/12/76.	WE	13300	Aviation Enterprises, Inc. 3900 E. Spring Street Long Beach, CA 90806

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, A35, B35, C35, D35, E35, G35, F35, 35R; T.C. 777	SA2000SW	Dual control wheel. Issued 8/15/75.	SW	42185	Ray Hollander Box 600 El Paso, TX 79944
35, A35, B35, C35, Serial D1 through D2900; T.C. A-777	SA2029WE	Installation of Delta Sigmatronix Emergency Electric Fuel Pump Kit, PK-2, in lieu of Beech hand pump P/N 35-924230 (on aircraft equipped with Beech P/N 35-921171 or P/N 35-924065 fuel unit).	WE	29500	Delta Sigmatronix, Inc. P.O. Box 6183 San Jose, CA 95150
35, A35 thru F35, 35R, 35-33, 35-A33, -B & C33, H35, J35, K35, M35, N35, P35; T.C. 3A15	SA2219WE	Installation of Filtrator Company engine crankcase breather and vacuum pump air-oil separator. Reissued 7/10/75.	SO	16505	Beryl D'Shannon Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru G35, R35, H35, J35, K35, M35, N35, P35; T.C. A-777, 3A15	SA2271WE	Installation of long fiberglass tailcone to replace the short factory installed tailcone. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, 35R; J35, K35, M35, N35, P35, S35, V35, V35A, V35 (turbo), 35-33, -A33, -B33, -C33, -C33A, E33, E33A; T.C. 777, 3A15	SA2470WE	Installation of anticollision lighting system. Issued 2/8/72.	WE	70500	Scientifico Scientific Components Company 350 Vista Bays Newport Beach, CA 92660
35, A35 thru H35, J35, K35, M35, N35, P35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, F33, F33A, F33C, G33; T.C. A-777, 3A15	SA2633WE	Installation of enlarged window and baggage compartment. Amended 8/16/78.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, D35, E35, G35, 35R, F35; H35, J35, K35, M35, N35, P35, 35-33, 35-A33, -B33, -C33, E33, F33, G33, V35, V35A, V35B, S35, 35-C33A, E33A, E33C, F33A, F33C, 36, A36; T.C. A-777, 3A15	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA2858WE	Installation of right and left hand cockpit side windows. Reissued 1/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA3020WE	Installation of exhaust silencer. Reissued 2/9/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, A35B, D, E, F, G, 35R; T.C. 777	SA3271SW-D	Mitchell yaw damper system YK631. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A777	SA3337WE	Installation of ventral air skeg. Amended 4/2/79.	WE	84396	Walker Engineering, Inc. 2240 Sawtelle Boulevard Los Angeles, CA 90064
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA3678WE	Installation of air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
35-33, -A33, -B33, -C33, -E33C, -C33A, E33, F33A, F33, F33A, F33C, G33, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; 36, A36; T.C. 3A15	SA1874CE	Installation of redundant engine fuel flow transmitter and cockpit indicator. Reissued 4/24/79.	WE	71740	Silver Instruments, Inc. 2436 Stanwell Drive Concord, CA 94520
35-A33, -B33, -C33, C33A, E33, E33A, F33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA3025SW-D	Automatic flight system AK497, cons. of Century IIB autopilot with optional radio coupler. Issued 9/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 (Normal or Utility Category), A35, B35, C35, D35, E35, F35, G35 (Utility Category); T.C. A-777	SA3191WE	Installation of wing tip fences. Issued 5/11/76.	WE	64690	John Pixton Enterprises P.O. Box 342 Santa Rosa, CA 95402

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35-C33, -C33A, E33, F33C, G33, F33A; T.C. 3A15	SA4158SW	S-TEC system 60 (two axis) flight guidance system, Model ST-009 (14 volt system). Issued 7/29/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
35, 35R; T.C. A-777	SA1423WE	Wing truss reinforcement, front spar, and change of hinge points for landing gear idler arm. Amended 6/14/76.	WE	59870	Fred J. Miller 355 Vista Baya Newport Beach, CA 92660
A35 thru F35, G35 and 35R, H35, J35, K35, M35; T.C. A-777, 3A15	SA1-27	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
A35 thru G35, H35; T.C. A77, 3A15	SA1-303	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35 thru G35, H35; T.C. A777, 3A15	SA1-368	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35, B35, C35, D35, E35, F35, G35, H35; T.C. A-777, 3A15	SA144EA	Increase to 200 pounds in maximum gross weight for takeoff and landing. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35 thru H35, J35, K35, M35, N35, P35; 35-33, -A33, -B33, C33A, E33A, E33C, F33A, F33C, S35, V35, V35A, V35B; T.C. A-777, 3A15	SA153EA	Installation of Beryl D'Shannon fiberglass tip tanks (15 gal. FP4-100, ref. STC's SA283EA and SA134EA) and fuel transfer system. Amended 9/28/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4530 Jettridge Drive, S.W. Atlanta, GA 30227
A35 thru H35, J35, K35, M35; T.C. A-777, 3A15	SA181EA	Increase of 200 pounds in maximum gross weight for takeoff and landing. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35, B35, C35, D35, E35, F35, G35, T.C. A-777	SA384WE	Adjustable pilot and copilot seat. Reissued 1/12/76.	WE	13300	Aviation Enterprises, Inc. 3900 E. Spring Street Long Beach, CA 90806
A35 thru G35, 35R, H35, J35; T.C. A-777, 3A15	SA507WE	Adjustable back rest. Reissued 1/12/76.	WE	13300	Aviation Enterprises, Inc. 3900 E. Spring Street Long Beach, CA 90806
A35, B thru F; T.C. 777	SA1270SW	Mitchell automatic flight system model AK328 cons. of Century I autopilot with omni tracking system. Issued 3/1/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35 thru H35, J35, K35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, F33, F33A, G33; T.C. A-777, 3A15	SA2091WE	Installation of Madras Air Service P/N MAS 102 wing tips. Amended 4/5/74.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
A35 thru H35; T.C. A-777, 3A15	SA2131WE	Installation of Delta Sigmatronix emergency electric fuel pump P/N 29000 in above models equipped with Beech P/N 35-924230 fuel unit.	WE	29500	Delta Sigmatronix, Inc. P.O. Box 6183 San Jose, CA 95150
A35 thru H35, J35, K35: T.C. 777, 3A15	SA2200SW	Continental IO-520-B or -BA engines. Issued 9/5/75.	SW	78420	Texas Aviation Engineering Company Meacham Field Fort Worth, TX 76106
A35, B35, C35, D35, E35, F35, G35; T.C. A-777	SA2546WE	Installation of Pathfinder Engineering Corp. Model P1-( ) autopilot system. Amended 11/13/74.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
A35, B35, C35, D35, E35, F35, G35; T.C. A-777	SA2547WE	Installation of Pathfinder Engineering Corporation Model P2-( ) autopilot system. Reissued 2/20/74.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
A35 thru H35, J35, K35, N35, M35, P35, S35, 35-33, -A33, -B33, -C33, G-33, V35, V35B, E33, F33A, V35A, 36, A36; T.C. A777, 3A15	SA2654WE	Installation of Pathfinder Model P2A autopilot system. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A35, B35, C35, D35, E35, F35, G35; T.C. A777	SA3116SW-D	Mitchell automatic flight system AK328 cons. of Century I autopilot with optional omni tracker. Issued 3/16/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35, B, C, D, E, F, G; T.C. 777	SA3113SW-D	Automatic flight system AK415 cons. of Century IIB autopilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35, A36TC; T.C. 3A15	SA3339SW	Installation of Mitchell automatic flight system Model AK809 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C35; T.C. A-777	SA236GL	Installation of a Continental O-470-G engine and McCauley propeller #2A36C23-11-DE/S-84B-0. Issued 5/4/78.	GL	74970	Robert Steffey 37344 Woodland New Baltimore, MI 48047
C35 thru F35, J35, K35, M35, N35, 35-33, 35-A33; T.C. A-777, 3A15	SA361EA	A. Installation of monitair angle of attack and stall warning kit number 92-107, and B. Installation of Monitair angle of attack and stall warning kit number 92-105. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
C35, D35, E35, F35, G35; T.C. A-777	SA604NW	Install Lycoming IO-540-K engine and Hartzell HC-F2YR-1BF/F8476D-4 propeller. Issued 7/6/78.	NW	52625	Macken, Inc. S.3608 Davison Boulevard Spokane, WA 99204
C35, D35, E35, F35, G35; T.C. A-777	SA1584CE	Installation of elevator tail cone fairing. Issued 4/15/80.	CE	73220	Smith Speed Conversions, Inc. P.O. Box 430 Johnson, KS 67855
C35, D35, E35, F35, G35; T.C. 777	SA3267SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. 777	SA3268SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. A-777	SA4000WE	Installation of radome in wing leading edge. Issued 7/27/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
E-35; T.C. A-777	SA4043WE	Installation of Continental IO-520-BA engine and McCauley 3A32C propeller. Issued 10/26/79.	WE	06755	Aircraft Technical Service, Inc. 6701 Odessa Avenue Van Nuys, CA 91406
F35; T.C. 7777	SA173GL	Installation of Dukes fuel pump P/N 4140-00-39. Issued 5/27/77.	GL	01838	Aerodynamics, Inc. Oakland Pontiac Airport P.O. Box 506 Pontiac, MI 48056
H35, J35, K35, M35, N35, P35, S35, 35-33, -A33, -B33, -C33, -33A; T.C. 3A15	SA1-636	Install 300 Series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
H35 Series; T.C. 777	SA198NW	Installation of 3 bladed McCauley 3A34C76FM/S82NB-2 propeller with Woodward A210680 governor on Continental O-470-G engine. Issued 7/21/75.	NW	77570	Mel G. Taylor 20005 Northeast 13th Street Camas, WA 98607
H35 Series; T.C. 777	SA259NW	Installation of TCM continuous flow fuel injection system (EO No. 5701) replacing carbureation system. Issued 2/17/76.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road South Seattle, WA 98108
35 Series H thru P; T.C. 3A15	SA470NW	Installation of Cessna oil filter. Issued 7/14/77.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road Seattle, WA 98108
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA421GL	Installation of aileron and flap gap seals. Amended 10/17/80.	GL	33997	Executive Aircraft Maintenance Corp. Crystal Lake Airport Crystal Lake, IL 60014

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H35, J35, K35, M-35, N-35, P35, 35-33, 35-A33, 35-B33, 35-C33, E33, F33; T.C. 3A15	SA695CE	Install Frantz oil filter. Amended 5/27/71.	GL	70360	Schmidt Aero Service Municipal Airport Worthington, MN 56187
H35, J35, K35, M35, N35, P35, S35, V35, V35B, 35-C33A, E33A, E33C, F33A, F33C, G33, 36, A36; T.C. 3A15	SA884SO	Installation of exhaust silencers. Issued 2/11/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, 35-33, E33, -A33, -C33; T.C. 3A15	SA975SW	Installation of cabin air conditioner. Reissued 5/7/79.	RM	01950	Aero Engineering Corporation 8C Garden Center Broomfield, CO 80020
H35, J35, K35, M35, N35, P35, 35-33, 35-A33, -B33, -C33, E33, F33; T.C. 3A15	SA1252WE	Installation of Rajay turbocharged Continental O-470-G-C1 and/or TO-470-C, -J, -K, -N engines. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90807
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA1595CE	Installation of elevator tail cone fairing. Issued 4/15/80.	CE	73220	Smith Speed Conversions, Inc. Box 430 Johnson, KS 67855
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-33, -A33, -B33, -C33, -C33A, E33, -E33A, F33A, 35, A35; T.C. 3A15	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, N35, P35, S35, V35, V35A, F33A, 35-33, -A33, -B33, -C33, -C33A, E33A, G33, 36, A36; T.C. 3A15	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33; T.C. 3A15	SA2870WE	Installation of right and left hand cockpit side windows. Reissued 2/2/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA3117SW-D	Mitchell automatic flight system AK328 cons. of Century I autopilot with optional omni tracker. Issued 3/16/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35; T.C. 3A15	SA3127SW-D	Mitchell automatic flight system AK415 cons. of Century IIB autopilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33C, F33A, G33, 36, A36; T.C. 3A15	SA3184WE	Installation of ventral air skeg. Amended 4/12/79.	WE	84396	Walker Engineering 2240 Sawtelle Boulevard Los Angeles, CA 90064
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B (Utility Category); T.C. 3A15	SA3190WE	Installation of wing tip fences. Issued 5/11/76.	WE	64690	JOhn Pixton Enterprises P.O. Box 342 Santa Rosa, CA 95402
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3269SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3270SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35; T.C. 3A15	SA3310WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/6/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, 35-33, -A33, -B33, -C33; T.C. 3A15	SA3523WE	Installation of an airfoil separator in the engine breather system. Issued 11/25/77.	WE	84396	Walker Engineering Co. 2240 Sawtelle Los Angeles, CA 90025

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H35, J35, K35, M35, N35, P35, S35, V35, F33, E33A, E33C, F33, F33A, F33C, G33, V35A, V35B, 36, A36, A36TC; T.C. 3A15	SA3999WE	Installation of radome in wing leading edge. Amended 8/14/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA4100WE	Installation of DTT-1000, -1001 and/or -1002/3 cautopilot adapters for the Edo-Aire Mitchell Century III autopilot. Issued 2/12/80.	WE	47775	Douglas L. Kettler 1212 North Boradway, Apt. H Escondido, CA 92026
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36, A36TC; T.C. 3A15	SA4180WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
J35; T.C. 3A15	SA686CE	Install Continental IO-520-V engine derated to 250 H.P. and Hartzell HC-C3YF-1/8468A-8R propellers. Reissued March 1975.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
J35, K35, M35, 35-33; T.C. 3A15	SA1-354	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
J35, V35, A35, B35, C35, D35, E35, F35, G35; T.C. 3A15, 777	SA754SW	Mitchell automatic aileron stabilizer AK203.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
J35, K35, M35, N35, P35, S35, V35, V35B, E33, E33A, F33, F33A, 36, A36, 35-33, -A33, -B33, -C33, E33C, F33C, -C33A, V35A; T.C. 3A15	SA1474CE	Installation of redundant engine fuel flow transmitter and cockpit indicator. Reissued 4/24/79.	WE	71740	Silver Instruments, Inc. 2436 Stanwell Drive Concord, CA 94520
J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2978WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA1140CE	Installation of King model KFC-200 2-axis (3 optional) autopilot system with a King KCS-55 (or -55A) compass with a King KI-255 (or KI-256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 7/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M35; T.C. 3A15	SA958EA	Installation of Teledyne Continental IO-520-Ba Engine and associated components in place of Teledyne Continental IO-470-C engine and associated components. Issued 7/30/73.	EA	41760	Helicopter & Airplane Service Corp. Montgomery County Airpark Gaithersburg, MD 20760
'35; .C. 3A15	SA4193WE	Replacing the control instrument panel. Issued 7/29/80.	WE	13300	Aviation Enterprises, Inc. 2870 East Wardlow Road Long Beach, CA 90807
35, P35, S35; .C. 3A15	SA134EA	15-gallon fiberglass wing tip fuel tanks. Reissued 2/6/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
P35, 35-B33; T.C. 3A15	SA178EA	Installation of Monitair angle of attach system, Model AA-2. REissued.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, 35-B33; T.C. 3A15	SA260EA	Installation of Monitair angle of attack and stall warning kit number 92-110. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, V35, V35A, V35B; T.C. 3A15	SA3203WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/24/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S35, V35, V35A, V35B, 35-B33, 35-C33, 35-C33A, E33, E33A, F33, F33A, G33, 36, A36, A36TC; T.C. 3A15	SA180GL	Install Norton Company radar pod P/N 4133X. Amended 8/22/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
S35, V35, V35A, V35B, 35-B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36, A36TC; T.C. 3A15	SA328GL	Installation of Norton radome kit No. 4222X. Amended 6/3/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
S35, V35; T.C. 3A15	SA352EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
S35, V35, V35A, V35B, 35-C33A, E33A, E33C, F33A, F33C, 36, A36; T.C. 3A15	SA449GL	Installation of Shadin Co. 910501 fuel or 910503 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Suite 206 Minneapolis, MN 55426
S35, V35, V35A, V35B; T.C. 3A15	SA468SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and flight director indicator DH-841( ). Amended 11/14/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
S35, V35, V35B, 35-C33A, E33A, F33C, V35A, 36, A36, F33A, F33C; T.C. 3A15	SA785CE	Installation of Hartzell Propellers PHC-C3YF-1R/8468-6R, PHC-C3YF-1R/8468A-6R, PHC-C3YF-1RF/F8468A-6R and BHC-C2YF-1B/8468AR, BHC-C2YF-1BF/F8468AR. Amended 5/16/80.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
S35, V35, V35A, V35B; T.C. 3A15	SA1069SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director. Issued 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
S35, V35, V35A, V35B; T.C. 3A15	SA1417CE	Install elevator tail cone fairings. Issued 5/17/78.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
S35 S/N D7482 thru D796, V35, V35A, V35B; T.C. 3A15	SA1744SW	Mitchell automatic flight system AK409 cons. of Century I autopilot with optional omni tracker. Issued 10/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2556WE	Installation of Rajay turbosupercharged Continental TSIO-520-D engine. Amended 11/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
S35, V35, V35A, V35B, 35-C33A, F33C, F33A, F33C, 36, A36; T.C. 3A15	SA2935WE	Installation of Model DFF-5000 fuel monitor. Issued 10/25/74.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545
S35, V35, V35A, V35B; T.C. 3A15	SA3159SW-D	Automatic flight system AK409, consisting of Century I autopilot with optional omni tracker. Issued 10/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WEils, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3172SW-D	Yaw damper Model YK631. Issued 12/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3272SW-D	Mitchell automatic flight system AK501 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/10/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3292SW-D	Mitchell command electric trim AK726. Issued 7/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, B; T.C. 3A15	SA3310SW-D	Installation of Mitchell automatic flight system AK804 consisting of Century 41 autopilot or AK804FD consisting of Century 41 autopilot flight director. Issued 11/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S35, V35, V35A, B; T.C. 3A15	SA3324SW-D	Installation of Mitchell automatic flight system AK803 consisting of Century 21 autopilot. Issued 12/6/78.	SW	60000	Mitchell Industries,Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3327SW	Installation of Mitchell automatic flight system AK805 consisting of Century 21 autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3328SW	Installation of Mitchell automatic flight system AK806/FD consisting of Century 41/flight director autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35A, F33A, F33C, 36, A36; T.C. 3A15	SA3548WE	Installation of air/oil separator. Amended 4/28/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90025
S35, V35, V35A, V35B; T.C. 3A15	SA3668WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 7/13/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
S35, V35, V35A, V35B; T.C. 3A15	SA4139SW	S-TEC system 60 (two axis) flight guidance system Model ST-007 with optional flight director/steering horizon and vertical speed. Issued 6/16/80.	SW	79463	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
V35; T.C. 3A15	SA503NW	Installation of Robertson STOL kit. Issued 9/7/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
V35; T.C. 3A15	SA707NW	Add RCA Primus weather radar. Issued 1/11/79.	NW	68500	Robertson Aircraft Corp. 839 West Perimeter Road Renton, WA 98055
V35, V35A; T.C. 3A15	SA925SW	Mitchell Automatic Flight System AK263 cons. of Century II autopilot with radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1185CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
V35, V35A, V35B; T.C. 3A15	SA1186CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
V35, V35A, V35B; T.C. 3A15	SA1500SW	Mitchell automatic flight system FD/AP282-382 cons. of flight director/autopilot with automatic command electric pitch trim. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1501SW	Mitchell automatic flight system AK383 cons. of Century III autopilot with optional automatic command electric trim, radio coupler, and glide slope coupler. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1722SW	Mitchell automatic flight system AK402, cons. of Century IIB autopilot with optional radio coupler. Issued 8/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3034SW-D	Mitchell automatic flight system AK503 or AK503FD cons. of Century IV autopilot or Century IV flight director autopilot with command/auto. electronic trim and annuciator panel. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3035SW-D	Mitchell automatic flight system AK501 cons. of Century III autopilot with optional command/auto. elec. pitch trim, radio, and glide slope coupler. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
V35, V35A, V35B; T.C. 3A15	SA4085SW	S-TEC System 60 (single axis) flight guidance system model ST-001. Issued 2/22/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Walters Industrial Complex Mineral Wells, TX 76067
V35, F33A, C, A36; T.C. 3A15	SA4133SW	S-TEC system 60-1 (single axis) flight guidance system, ST-002 Issued 5/29/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
V35A; T.C. 3A15	SA882SW	Mitchell automatic flight system AK260 consisting of Century III autopilot, optional radio coupler, automatic pitch trim, stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35A; T.C. 3A15	SA2030WE	Installation of Brittain B-VII, NAV-2B, B2C and BSA-4 Flight Control Systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, E33 and E33A; T.C. 3A15	SA1858WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, V35B, S35, F33A, A36; T.C. 3A15	SA3824WE	Installation of SDI Model CFS-1000-1001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714
V35B (Utility Category); T.C. 3A15	SA2947WE	Installation of Collins AP-107 autopilot and FD-106 PV flight director. Reissued 4/22/75.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids Airport Cedar Rapis, IA 32406
V35B; T.C. 3A15	SA3215SW-D	Mitchell automatic flight system AK671 consisting of Century I autopilot with optional omni tracker. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3216SW-D	Mitchell automatic flight system AK672 consisting of Century IIB autopilot with optional radio coupler. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3217SW-D	Mitchell automatic flight system AK673 consisting of Century III autopilot with optional radio coupler and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3218SW-D	Mitchell automatic flight system AK674 consisting of Century IV autopilot or AK674FD consisting of Century IV flight director autopilot with remote annunciator. Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3219SW-D	Mitchell command electric trim system AK675. Issued 8/9/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3220SW-D	Mitchell yaw damper system YK676 Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
V35B; T.C. 3A15	SA4155SW	S-TEC system 60 (two axis) flight guidance system ST-017. Issued 7/18/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
V35B, A36, F33; T.C. 3A15	SA3683WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
35-33 Series; T.C. 3A15	SA1808WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33 Series; T.C. 3A15	SA1886WE	Installation of Brittain Industries NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3098SW-D	Mitchell automatic flight system AK306 cons. of Century I autopilot with optional omni tracker. Issued 1/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3107WE	Installation of exhaust silencer. Reissued 2/9/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA1036EA	Installation of vertical tail floodlights on upper surfaces of the horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
35-33, 35-A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A36TC; T.C. 3A15	SA1416CE	Install flap and aileron fairings and seals. Amended 3/24/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
35-A33; T.C. 3A15	SA270EA	Installation of a stability augmentation safety system (with or without camera system installed). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-A33; T.C. 3A15	SA1310CE	Chrome-plated brake disc installation. Issued 6/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
35-B33, -C33A; T.C. 3A15	SA1289CE	Install King KFC-200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/21/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
35-C33, F33; T.C. 3A15	SA238GL	Installation of Continental IO-470-N engine and McCauley 2A36C23/84B-0 propeller. Amended 11/14/78.	GL	39517	Stewart Gross P.O. Box 634 Rochester, MN 55901
35-C33, 35-C33A; T.C. 3A15	SA394EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-C33; T.C. 3A15	SA896SW	Mitchell automatic flight system AK264 cons. of Century III autopilot with optional automatic aileron stabilizer, radio and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33, E33, F33; T.C. 3A15	SA1218SW	Automatic flight system AK306 cons. of Century I and optional tracking system. Issued 11/10/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33, E33, F33; T.C. 3A15	SA1365SW	Mitchell automatic flight system model AK347 cons. of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA1366SW	Mitchell automatic flight system model AK316, cons. of Century III autopilot with optional automatic pitch trim, radio coupler, glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3163SW-D	Install automatic flight system AK316 consisting of Century III autopilot with optional command automatic pitch trim system, radio coupler, and glide slope coupler. Issued 11/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3204WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 12/20/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3248SW-D	Mitchell automatic flight system AK716 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 10/3/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
E33, E33A, E33C, F33, F33A, F33C; T.C. 3A15	SA1550CE	Installation of elevator and rudder tail cone fairings. Issued 2/29/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 61 Johnson, KS 67855
E33, -A, -C; F33, -A, -C; T.C. 3A15	SA2057WE	Installation of Brittain Industries B-VII, NAV-2B, B2C and BSA4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
F33A; T.C. 3A15	SA1164CE	Installation of King KFC-200 two axis autopilot system with King KI-255 (or -256) flight command indicator or King KG-258 altitude horizon indicator with a KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
F33A; T.C. 3A15	SA3230SW-D	Mitchell automatic flight system AK660, consisting of Century IIB autopilot with optional radio coupler. Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3232SW-D	Mitchell automatic flight system AK662, consisting of Century IV autopilot or AK662FD consisting of Century IV flight director with optional remote annunicator. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3229SW-D	Mitchell automatic flight system AK659 consisting of Century I autopilot with optional omni tracker. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, Tx 76067
F33A; T.C. 3A15	SA3231SW-D	Mitchell automatic flight system AK661, consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3233SW-D	Mitchell command electric trim AK663. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3234SW-D	Mitchell yaw damper system K664 Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3348SW	Installation of Mitchell automatic flight system AK821/FD consisting of Century 41/flight director autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3349SW	Installation of Mitchell automatic flight system AK820 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, G33, 36, A36; T.C. 3A15	SA480SO	Installation of Bendix FCS-810 automatic flight control system, including manual electrim trim and flight director indicator DH-841( ). Amended 10/4/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
F33A, S/N CE-316 & up; T.C. 3A15	SA1232SW	Mitchell automatic flight system AK315 cons. of Century III with optional automatic pitch trim, radio and glide slope coupler. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, E33A, 35-C33A, F33C; T.C. 3A15	SA1233SW	Mitchell automatic flight system AK317 cons. of Century I and optional tracking system. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1865SW	Mitchell automatic flight system AK448, Century IV autopilot and AK448FD, Century IV flight director with electronic command/automatic pitch trim. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1866SW	Mitchell automatic flight system AK452 cons. of Century III autopilot with optional electronic command/automatic pitch trim, radio coupler, and glide slope coupler. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
F33A, 36, A36; T.C. 3A15	SA3087SW-D	Mitchell command electric trim AK563. Issued 12/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, 36A; T.C. 3A15	SA3193SW-D	Mitchell automatic flight system AK452 consisting of Century III autopilot with optional command automatic electronic pitch trim, radio, glide slope coupler. Issued 4/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G33; T.C. 3A15	SA571EA	Installation of Brittain Industries Models B7, NAV-2B, B2C and BSA4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
G33; T.C. 3A15	SA818CE	Install Hartzell propeller model BHC-L2YF-1BF/F8468AR with spinners A2295, or model PHC-L3YF-1RF/F8468A-6R with spinners A2295-1. Issued 1/14/72.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
35/36 Series; T.C. 3A15	SA1711WE	Installation of Brittain Industries B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35/36 Series; T.C. 3A15	SA1712WE	Installation of Brittain Industries BSA-4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
35, 50 Series; T.C. 777, 3A15, 5A4	SA856WE	Glassfiber reinforced plastic wing tips.	WE	00450	ACKO P.O. Box 1431 Torrance, CA 90510
35, 50 Series; T.C. 777, 3A15, 5A4	SA998WE	Glass fiber reinforced plastic wing tips. Amended 6/13/69.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
35, 95 Series; T.C. 777, 3A15, 3A16	SA1-381	Installation of Fram Oil Filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
35, 95 Series; T.C. 777, 3A15, 3A16	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
36 Series; T.C. 3A15	SA961SW	Mitchell automatic flight system AK275 cons. of Century III autopilot with optional radio coupler, automatic pitch trim, aileron stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36 Series; T.C. 3A15	SA1916WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
36; T.C. 3A15	SA2068WE	Installation of Brittain Models B-VII, NAV-2B, B2C and BSA-4 flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
A36; T.C. 3A15	SA3206SW-D	Mitchell command electric trim model AK669. Issued 6/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1145CE	Installation of King Model KFC-200, 2 axis (3 optional) or stand alone yaw damper for Beech Model A36 S/N E572 and later autopilot system with a King KI-255 (KI-256 optional) flight command indicator with the KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
36, A36; T.C. 3A15	SA1231SW	Mitchell automatic flight system model AK311, cons. of Century II autopilot with optional radio coupler. Issued 12/8/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1360SW	Mitchell automatic flight system Model AK346 cons. of Century III autopilot with optional pitch trim, radio coupler, and glide slope coupler. Issued 8/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
36, A36: T.C. 3A15	SA1634SW	Mitchell AK423 cons. of 1C707 omni/localizer converter. Issued 3/27/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1635SW	Mitchell AK417/FD cons. of flight director/autopilot with command electric trim. Issued 3/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36: T.C. 3A15	SA3118SW-D	Automatic flight system AK448, Century IV autopilot or AK448FD, Century IV autopilot flight director with optional remote annuciator. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36: T.C. 3A15	SA3119SW-D	Automatic flight system AK452 cons. of Century III autopilot with optional command/automatic electronic elevator pitch trim, radio and glide slope couplers. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36: T.C. 3A15	SA3244WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 8/11/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
36, A36; T.C. 3A15	SA4132SW	S-TEC system 60-1 (single axis) flight guidance system, SF006. Issued 5/29/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
36, A36, A36TC; T.C. 3A15	SA1448CE	Installation of elevator tail cone fairing. Amended 3/24/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
A36, Serial No. E185 and up; T.C. 3A15	SA84RM	Installation of freon type air conditioning system. Amended 3/21/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
A36: T.C. 3A15	SA283GL	Installation of a Continental IO-520-B, -BA engine modified in in accordance with STC SA282GL and a Symbolic Displays fuel flow indicating system, Model CFS-1000. Issued 11/14/78.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport Rockford, IL 61109
A36; T.C. 3A15	SA1093CE	Installation of AP-107 (2 axis) autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1095CE	Installation of AP-106 autopilot system and interface with Collins 329A-4V indicator. Amended July 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1096CE	Installation of yaw damper system. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1097CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1544CE	Installation of microwave landing system. Issued 1/22/80.	SW	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
A36: T.C. 3A15	SA3203SW-D	Mitchell yaw damper model YK670 Issued 5/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36: T.C. 3A15	SA3204SW-D	Mitchell automatic flight system AK668 consisting of Century IV autopilot or AK668FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 5/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3205SW-D	Automatic flight system AK667 consisting of Century III autopilot with optional radio coupler and Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A36; T.C. 3A15	SA3207SW-D	Mitchell automatic flight system consisting of Century I autopilot with optional omni tracker. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3208SW-D	Mitchell automatic flight system AK666 consisting of Century IIB autopilot with optional radio coupler. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3340SO	Mitchell automatic flight system AK810 consisting of Century 41 flight director autopilot. Issued 7/25/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36; T.C. 3A15	SA4106WE	Modification of the rudder and brake systems to provide hand controls in addition to the conventional systems. Issued 3/25/80.	WE	05225	Aircraft Inspection & Maintenance, Inc. 2680 East Wardlaw Road Long Beach, CA 90807
A36, A36TC; T.C. 3A15	SA1106SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and option yaw damper and flight director. Issued 10/11/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
A36, A36TC; T.C. 3A15	SA1496CE	Installation of King KFC 200 automatic flight control system. Amended 7/1/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
A36, A36TC; T.C. 3A15	SA1527CE-D	Installation of King KAS 297 altitude selector option. Issued 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
A36TC; T.C. 3A15	SA3329SW-D	Mitchell automatic flight system AK754 consisting of Century IV autopilot or Model AK754FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 1/2/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36TC; T.C. 3A15	SA3330SW-D	Mitchell automatic flight system AK753, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/2/79.	SW	60000	Mitchel Industries, Inc. P.O. Box 610 Mineral Wells, TX 75056
A36TC; T.C. 3A15	SA4114WE	Installation of Silver Instruments Fueltron IG or IP digital fuel flow and totalizer system. Issued 2/26/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
A36TC; T.C. 3A15	SA4140WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 4/10/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
45 Series; T.C. 5A3	SA366WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
45 Series; T.C. 5A3	SA425SW	Nose landing gear door removal.	SW	22700	Civil Air Patrol Corporation National Headquarters Ellington AFB, TX 77030
A-45 (T-34A, B-45); T.C. 5A3	SA876CE	Remove Continental O-470-13 or O-470-13A engine and propeller. Install Continental IO-470-N engine and Hartzell BHC-L2YF-FC846AR propeller. Issued December 1972.	CE	15250	Beech Aircraft Corporation 9709 East Central Wichita, KS 67206
A-45 (T-34A, B-45); T.C. 5A3	SA2211SW	Mitchell Century I Model AK409 autopilot with omni tracker. Issued 7/17/75.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA1864SW	Continental IO-520-B engine and McCauley 3A32C76/82NB-2 propeller. Issued 4/11/74.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA3191SW-D	Mitchell automatic flight system AK649 consisting of Century I autopilot with optional omni tracking system. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A45: T.C. 5A3	SA3192SW-D	Automatic flight system AK651 consisting of Century IIB autopilot with optional radio coupler. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D45: T.C. 5A3	SA183GL	Modification of basic aircraft for Restricted Category Airworthiness Certification by removing rudder-aileron bungee interconnect system, elevator down spring system and tail cone fairing. Issued 6/21/77.	GL	61302	Michigan Dept. of Natural Resource Stevens T. Mason Bldg. Lansing, MI 48926
50 Series: T.C. 5A4	SA1-262	Bendix Pioneer 9100-17-C1 fuel flow meter system.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series: T.C. 5A4	SA1-291	Radio shelves in nose baggage shelves.	EA	15210	Beckett Aviation Corporation Allegheny County Airport Dravosburg, PA 15034
50 Series: T.C. 5A4	SA1-357	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series: T.C. 5A4	SA1-443	2002X-R radome assembly.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
50 Series: T.C. 5A4	SA1-503	Electrothermal propeller deicing system. (Applicable to aircraft with two 50-amp. generators or greater.)	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series: T.C. 5A4	SA3-209	Acron B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series: T.C. 5A4	SA3-703	Accumulator for unfeathering Hartzell HC-83XF, HC-93Z20 or HC-B3Z20 propellers.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series: T.C. 5A4	SA4-51	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series: T.C. 5A4	SA4-221	Autopilot L-2.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series: T.C. 5A4	SA4-382	Radio rack.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
50 Series: T.C. 5A4	SA4-439	Fiberglass reinforced plastic wing tips.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
50 Series: T.C. 5A4	SA4-462	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series: T.C. 5A4	SA4-549	Federal F-400 autopilot.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
50 Series: T.C. 5A4	SA4-759	Aerofilter 30690B full flow lube oil filter with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
50 Series: T.C. 5A4	SA4-807	Automatic rudder control Model B.	GL	49858	Lear, Inc. 3714 Jefferson Avenue, S.E. Grand Rapids, MI 49501
50 Series: T.C. 5A4	SA4-909	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series: T.C. 5A4	SA4-1417	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series: T.C. 5A4	SA3CE	Governor 210385. (Not eligible with accumulator unfeathering system.)	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	SIC CODE	STC HOLDER
50 Series; T.C. 5A4	SA5CE	Propeller governors incorporating unfeathering accumulator shutoff valves. (Eligible only on aircraft equipped with Beech unfeathering system.)	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA24SW	Cabin seats. (Seat tracks installation per STC SA2-1068 required.)	SW	83650	Vicars Custom Aircraft Interiors 3709 N. Main Fort Worth, TX 76101
50 Series; T.C. 5A4	SA25CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA31SW	Automatic pilot AK104.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA41CE	Governor 210159.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA75SW	Landing gear doors. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA76SW	Lycoming IGSO-540-B1A engines with associated powerplant changes, and landing gear doors; increase gross weight to 7,300 lbs. takeoff and 7,000 lbs. landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA81SW	Automatic pilot AK119.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA158EA	Autopilot T-3 and altitude hold AH-1 as an accessory item.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series; T.C. 5A4	SA166CE	Twin-engine electronic synchronizer and unfeathering system.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA167CE	Electronic synchronizer kit.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA198SW	Three-place couch.	SW	85128	Westernair of Albuquerque, Inc. Route 6, Box 88 Albuquerque, NM 87101
50 Series; T.C. 5A4	SA207SW	Dual control. (Pilot's and co-copilot's seat installations per STC SA2-1068 required.) Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA213CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA242SW	Lycoming GO-480-G2D6 engines and increase in gross weight to 6,300 pounds. Reissued February 1973.	GL	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA323EA	7541F nose cap weather radome.	NE	53750	McMillan Radiation Labs, Inc. Brownville Avenue Ipswich, MA 01938
50 Series; T.C. 5A4	SA348SW	Radar nose. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA360SW	GO-480-G2D6 or -G2F6 engines and increase in weight to 6,000 pounds. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA370SW	Seven place seating capacity.	SW	80625	United Airmotive 1105 DeRidder Fort Worth, TX 76106
50 Series; T.C. 5A4	SA392WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
50 Series: T.C. 5A4	SA430SW	Pilot and copilot cockpit seats.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
50 Series: T.C. 5A4	SA405WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series: T.C. 5A4	SA433SW	Cabin door and stair.	SW	27242	Cross Roads Aviation, Inc. Addison Airport Addison, TX 75001
50 Series: T.C. 5A4	SA514SW	Six place seat and/or hat shelf.	SW	36125	Flying V Interiors Meacham Field Fort Worth, TX 76106
50 Series: T.C. 5A4	SA517SW	Goodrich wheel and brake. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series: T.C. 5A4	SA587SW	Lycoming IO-720-A1A engines, increase gross weight 7,600 pounds, 7,240 pounds landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series: T.C. 5A4	SA655SW	Lycoming IGSO-480-A1A6 engine; wing, vertical tail, landing gear modified, control system increased gross weight to 7,300 pounds takeoff, and 7,000 pounds landing.	SW	27242	Cross Roads Aviation, Inc. P.O. Box 60464 AMF Houston, TX 77060
50 Series: T.C. 5A4	SA1013WE	Advanced Army Aircraft Instrumentation System (AAAIS) and associated aircraft modifications.	WE	30400	Douglas Aircraft Company, Inc. 3855 Lakewood Boulevard Long Beach, CA 90801
50 Series: T.C. 5A4	SA1324WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series: T.C. 5A4	SA1395WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50: T.C. 5A4	SA1-565	Installation of radome kit No. 2002X. Amended 2/24/77.	GL	61750	Morton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50: T.C. 5A4	SA40CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights Model 1 or 2. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGAw Avenue Irvine, CA 92705
50, B50, C50, D50, D50A, D50B, D50C, D50E-5990, D50E, E50, F50, G50, H50, J50: T.C. 5A4	SA2763GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 1/17/79.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50: T.C. 5A4	SA383CE	Installation of Hoskins Twi. III supplementary high intensity lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1108 N. Batavia Orange, CA 92667
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50: T.C. 5A4	SA390GL	Install Cleveland conversion kit, P/N 199-83. Issued 6/18/90.	GL	62500	Parker Hannifin Corporation Aircraft Wheel & Brake Division 1160 Center Road Avon, OH 44011
50, B50 thru J50, D50A, B, C, D, E; 65, 65-80, 65-A8800, 65-B80 all; T.C. 5A4, 3A20	SA594WE	Installation of oil filter assemblies. Reissued 9/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50: T.C. 5A4	SA1644WE	Installation of a Torginol Special Product Co. VarBar.	RM	25250	Combs Aircraft, Inc. Stapleton International Airport Denver, CO 80207
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50: T.C. 5A4	SA2631NE	Installation of Bellon Concrete, Inc. single piece windshield or alternate single piece sloped windshield. Amended 3/20/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4550 Jettridge Drive Atlanta, GA 30327

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA2872WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
B50; T.C. 5A4	SA452GL	Installation of a Shadin Co. 910502 or 910504 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Suite 206 Minneapolis, MN 55426
B50, C50, D50; T.C. 5A4	SA2413WE	Modification of fuel vent outlet. Issued 9/3/71.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
C50; T.C. 5A4	SA3062SW-D	Mitchell AK370 cons. of Century III autopilot with command/automatic electronic pitch trim system, optional radio coupler, and glide slope coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C50; T.C. 5A4	SA3063SW-D	Mitchell automatic flight system AK542 cons. of Century IIB autopilot with optional radio coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, D50C, E50, F50, G50, H50; T.C. 5A4	SA1-453	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
D50, D50A, B, C, E; T.C. 5A4	SA3138SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3139SW-D	Mitchell automatic flight system AK613, consisting of Century IIB autopilot with optional radio coupler. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3140SW-D	Mitchell automatic flight system AK606, consisting of Century I autopilot with optional omni tracker. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50 – modified – Excaliber STC SA587SW; 56TC, A56TC, 58, 58A, 58P, 58PA, 58TC, 58TCA, 60, A60, B60; 65, A65, 65-80, -A80, -A80-8800, -B80, -88, -70 modified – Excalibur STC SA444SW; 95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A (95-55, -A55, -B55 modified – Colemill STC SA432SO; T.C. 5A4, 3A16, A12CE, A23CE, 3A20, 3A16	SA20GL	Installation of Woodward Type III electronic propeller synchronizer or synchrophaser system. Amended 9/25/78.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
D50C, E; T.C. 5A3	SA1334SW	Mitchell automatic flight system AK337, cons. of Century II autopilot with optional radio coupler. Issued 7/1/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA31WE	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
D50E; T.C. 5A4	SA33WE	Autopilot M-4.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
D50E; T.C. 5A4	SA391WE	Installation of Brittain Model B2D Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
D50E; T.C. 5A4	SA837SW	Mitchell AK255 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA974CE	Installation of KNR 665 digital area navigation system. Amended May 1974.	CE	48250	King Radio Corporation Box 106 Olathe, KS 66061
E50, F50, G50, H50, J50; 80, A80, 65; T.C. 5A4, 3A20	SA1686WE	Installation of Vibration Isolation Products engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
50, 65 Series; T.C. 5A4, 3A20	SA15EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50, 65 Series; T.C. 5A4, 3A20	SA476EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
55, A55; B55, C55, D55, 56TC; 65-B80, A65-8200, 65-90, A90; 95, B95, B95A, D-95A, E95; T.C. 3A16, 3A20	SA1874WE	Installation of certain up-command signal adapter kit on certain airplanes equipped with Brittain models B-4A, B-4AP, B-5 and B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA681CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114
B55, C55; 95 Series; T.C. 3A16	SA1591WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1548WE	Installation of a Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1934WE	Installation of an approach speed control system. Reissued 12/4/69.	EA	69500	Safe Flight Instrument Corp. Box 550 White Plains, NY 10602
D55, E55, E55A, 56TC, A56TC, 58, 58A, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 58P, 58PA, 58TC; TC 3A16	SA453SO	Installation of Bendix Model FCS 810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 10/19/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
D-55, D55A, E55, E55A, 58, 58A, 56TC, A56TC, 95; T.C. 3A16	SA2048WE	Installation of Brittain Industries Model B-VII or NAV-2B or B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55, D55A, E55, E55A, 56TC, 58, 58A, 95, B95, B95A, D95A, E95, 95-55, -A55, -B55, -B55A, -C55, -C55A; T.C. 3A16	SA2871WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
E55; T.C. 3A16	SA126GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
E55; T.C. 3A16	SA896SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 4/22/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
E55; T.C. 3A16	SA3068WE	Installation of fuel flow instruments. Issued 9/8/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1126CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE982 and up): T.C. 3A16	SA1127CE	Installation of Collins AP-107 (2 axis) autopilot systems. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1128CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
E55, 58; T.C. 3A16	SA1008CE	Installation of an electric motor driven freon vapor cycle air conditioning system. Amended 10/9/74.	CE	02950	Aero Space Controls 1050 N. Mosley Wichita, KS 67214
56TC; T.C. 3A16	SA383SO	Installation of Bendix M-4C autopilot flight control system. Amended 7/14/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33309
56TC; T.C. 3A16	SA632CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114
56TC; T.C. 3A16	SA713CE	Conversion of wing tips to integral fuel tanks.	CE	16292	Frank R. Berry and William T. McKay Route 1, Box 204A Augusta, KS 67010
56TC; T.C. 3A16	SA1770WE	Installation of Brittain Industries Models B-5 or NAV-2B or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
56TC, A56TC; T.C. 3A16	SA1041CE	Replace existing nickel-cadmium battery with lead-acid battery. Issued January 1975.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
56TC, A56TC, 58, 58A, 58TC, 58TCA: T.C. 3A16	SA4194SW	Installation of camera port. Issued 9/2/80.	SW	42800	A.D. Howard Route 2, Box 4 Culdesac, ID 83524
56 TC; 95 Series; T.C. 3A15, 3A16	SA1585WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	[illegible]90	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
58 Series; T.C. 3A16	SA960EA	Installation of Aircraft Radio Corp. AF-530A automatic pilot system and electric operated elevator trim system. Amended 1/18/71.	EA	05950	Aircraft Radio Corporation Rockaway Valley Road Boonton, NJ 07005
58 Series; T.C. 3A16	SA1174SW	Mitchell automatic flight system FD/AP202-303 cons. of flight director/autopilot, automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1175SW	Auto flight system AF303 cons. of Century III, autopilot, with optional auto pitch trim, radio, and glide slope couplers. Issued 7/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1192SW	LM2 air conditioner system. Issued 9/22/70.	SW	83100	Wes-Kol Inc. 2805 National Drive Garland, TX 75040
58 Series; T.C. 3A16	SA1199SW	Mitchell automatic flight system 305 cons. of Century II autopilot with optional stabilizer and radio coupler. Issued 10/2/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA3119WE	Installation of Pathfinder autopilot systems. Issued 12/16/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
58, 58A; T.C. 3A16	SA96RM	Installation of freon type air conditioning system. Issued 3/24/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 90501
58, 58A; T.C. 3A16	SA1045CE	Installation of Collins Radio Co. AP-107 autopilot system (2 axis). Amended February 1975.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1106CE-D	Installation of Collins Radio Group AP-106 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1107CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
58, 58A; T.C. 3A16	SA1108CE-D	Installation of Collins Radio Group AP-107 axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1687SW	Mitchell automatic flight system Model YF428 cons. of yaw damper. Issued 6/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1786SW	Mitchell Automatic Flight System AK451 cons. of Century III Autopilot with Electronic Pitch Trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1787SW	Mitchell Automatic Flight System AK447 cons. of Century IV Autopilot or AK447FD cons. of Century IV/Flight Director with Electronic Command/Automatic Pitch trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3131SW-D	Mitchell automatic flight system AK447, Century IV autopilot or AK447FD Century IV flight director autopilot with remote annuciator. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3132SW-D	Mitchell automatic flight system AK451, consisting of Century III autopilot with optional command automatic electric pitch trim, radio and glide slope couplers. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3341SW	Mitchell yaw damper systems, YF781. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3342SW	Mitchell automatic flight system AK816/FD consisting of Century 41/flight director autopilot. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3350SW	Installation of Mitchell automatic flight system AK815 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A, 58P, 58PA, 58TC, 58TCA, 65-80, -A80, -B80, -88, 95-C55, -C55A, D55, D55A, E55, E55A; T.C. A23, 3A20, 3A16	SA300CE	Installation of Woodward propeller governor on single and twin engine airplanes. Amended 9/18/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
58, 58A, TH-1 and up; T.C. 3A16	SA963CE	Installation of Airborne/Goodyear pneumatic iceguard deicing system. Issued August 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
58, 58A, 95-B55, -B55A; T.C. 3A16	SA935SO	Installation of a Bendix FCS-970 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Amended 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
58, 58A, 95-B55, -B55A; T.C. 3A16	SA936SO	Installation of Bendix NP-2041A area navigation computer programmer. Amended 4/10/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
58P; T.C. A23CE	SA113GL	Installation of radome kit #109X. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA978SO	Installation of NP-2041A area navigation computer programmer. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA979SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
58P, 58PA, 58TC, 58 TCA; T.C. A23CE	SA1123CE	Install AP-106 autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1124CE	Install AP-107 (2 axis) autopilot and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1125CE	Install AP-107 (3 axis) autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1150CE	Installation of King Model KFC-200, 2-axis and KC-291 yaw damper FCS. Amended 6/2/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1524CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3038SW-D	Mitchell automatic flight system AK449 or AK449FD cons. of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim and optional remote annuciator panel. Issued 1/17/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3039SW-D	Automatic flight system YK445 yaw damper system. Issued 1/17/75.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3040SW-D	Automatic flight system AK453 consisting of Century III autopilot optional command/automatic elec-electronic pitch trim system, radio and glide slope couplers. Issued 2/5/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3311SW-D	Mitchell automatic flight system AK453 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/22/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3338SW-D	Mitchell automatic flight system system AK813 consisting of Century 41 autopilot or AK813FD consisting 41 flight director autopilot with optional remote annunciator. Issued 4/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3344SW	Mitchell yaw damper system YK781. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3499SW	Installation of tail flood lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
58P, 58TC; T.C. A23CE	SA178GL	Install Cleveland conversion kit, P/N 199-73. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
58P, 58TC; T.C. A23CE	SA3769WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
58P, 58TC, 58TCA; T.C. A23CE	SA4050WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Reissued 3/25/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
58TC; T.C. A23CE	SA124GL	Install Norton Company radome, P/N 4083X. Amended 2/21/79.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
60 Series; T.C. A12CE	SA1006SW	Mitchell Automatic Flight System AK291, cons. of Century III autopilot with optional pitch trim servo, radio and glide slope couplers.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60; T.C. A12CE	SA659SO	Installation of Bendix M-4C automatic flight control system, including manual electric trim, and/or installation of Bendix YD-4 yaw damper. Amended 11/10/72.	SO	15475	Bendix Avionics P.O. Box 9414 Ft. Lauderdale, FL 33310
60, A60; T.C. A12CE	SA945CE	Replacement of existing nickel-cadmium battery with lead-acid battery, Teledyne PS12-24. Amended October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133
60, A60; T.C. A12CE	SA1547SW	Mitchell automatic flight system YK380 consisting of yaw damper. Issued March 1973.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60; T.C. A12CE	SA1704SW	Mitchell automatic flight system AK429, cons. of Century IV autopilot with trim or AK429/FD cons. of Century IV autopilot/flight director with trim. Issued 7/20/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA154GL	Installation of Norton radome kit, No. 4132X. Issued 2/16/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
60, A60, B60; T.C. A12CE	SA179GL	Install Celveland conversion kit, P/N 199-73. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
60, A60, B60; T.C. A12CE	SA539SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator and/or YD-4 yaw damper. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
60, A60, B60; T.C. A12CE	SA1023CE	Installation of Collins Radio Co. AP-106 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1024CE	Installation of AP-107 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1025CE	Installation of yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A2CE	SA1741SW	Mitchell automatic flight system AK458 cons. of Century autopilot with optional radio coupler automatic/command pitch trim, glide slope coupler. Issued 10/12/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3151SW-D	Mitchell automatic flight system AK429 consisting of Century IV autopilot or AK429/FD consisting of Century IV flight director with optional remote annuciator. Issued 7/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A2CE	SA3162SW	Installation of recognition light assembly on the horizontal stabilizer. Reissued 3/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
60, A60, B60; T.C. A12CE	SA3293SW-D	Yaw damper system YK380. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3367SW-D	Mitchell automatic flight system AK870 consisting of Century 41 autopilot or AK870FD consisting of Century 41FD autopilot. Issued 5/6/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
60, A60, B60; T.C. A12CE	SA3368SW-D	Mitchell automatic flight system YK871 consisting of yaw damper system. Issued 5/6/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3605WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel indicating system. Amended 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
60, A60, B60; T.C. A12CE	SA3905WE	Installation of SDI Model CFS-200, -2001, or FT-200 fuel flow indicating system. Issued 4/13/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
60, 65-A80, B80, 65-88, 70; T.C. A12CE, 3A20	SA899EA	Installation of Grimes three light strobe Kit P/N 34-0116-1 and -2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
60, A60, B90, C90, E90, 65-90, -A90, 100, A100; T.C. A12CE, 3A20, A14CE	SA2638WE	Installation of CCC BWS 50-08 Nicad battery overheat warning system. Amended 9/18/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
A60; T.C. A12CE	SA85RM	Installation of Teledyne Avionics angle of attack indicating system. Issued 11/2/76.	RM	14127	Avionics Engineering of Denver, Inc. 8895 Montview Boulevard, Hangar 8 Denver, CO 80220
A60; T.C. A12CE	SA1029CE	Installation of AP-106 and AP-107 automatic flight control systems and yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
B60; T.C. A12CE	SA570SO	Installation of Bendix M-4D automatic flight control system, including optional manual electric trim and optional flight director indicator. Issued 12/6/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
B60; T.C. A12CE	SA1470CE	Installation of King KFC 250 flight control system (3 axis) using 3-inch or 4-inch indicators. Issued 2/5/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
65 Series; T.C. 3A20	SA1-643	Radar antenna mounts: 296-01 for 12" Collins WP-103 antenna; 296-03 12" RCA AVQ-55 antenna and 296-02 for 12" RCA AVQ-50 antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series; T.C. 3A20	SA3-516	Autopilot L-2C with or without 1350B approach coupler and 220302 altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA4CE	Propeller governors incorporating unfeathering accumulator shutoff valves.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
65 Series; T.C. 3A20	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
65 Series; T.C. 3A20	SA46WE	Full flow lube oil filter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
65 Series; T.C. 3A20	SA92CE	High intensity wing tip lights Model A, tail light Model C, with or without high intensity fuselage lights Model 1 or 2.	GL	42625	Donald F. Hoskins 4980 Marine Drive Chicago, IL 60607
65 Series; T.C. 3A20	SA139SW	Buffet. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
65 Series; T.C. 3A20	SA161CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation 1185 Galewood Drive Cleveland, OH 44110
65 Series; T.C. 3A20	SA186EA	Throttle stop device.	EA	87118	Stephen T. Wissey, Jr. 8 Steamboat Road Great Neck, NY 11022
65 Series; T.C. 3A20	SA189CE	Twin-engine synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65 Series: T.C. 3A20	SA201GL	Sperry SP 3 elevator trim drive servo and trim tab bracket.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
65 Series: T.C. 3A20	SA210SO	Radar system AVQ55.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
65 Series: T.C. 3A20	SA219SW	Automatic pilot AK105.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series: T.C. 3A20	SA255CE	Oil tank heater blanket kit 65-42.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67206
65 Series: T.C. 3A20	SA269SW	Brushless generators, voltage regulators and control panels.	EA	37376	General Electric Company Specialty Controls Department Waynesboro, VA 22980
65 Series: T.C. 3A20	SA277EA	Installation of Chamberlain 2090K-B radome kit for Bendix 100 or RDR-110 radar systems with transmitter/ receiver unit and 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
65 Series: T.C. 3A20	SA280GL	2011K-B Series radome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series: T.C. 3A20	SA296CE	M4P or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series: T.C. 3A20	SA307CE	GUARD system (gear up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612
65 Series: T.C. 3A20	SA336EA	PB-60 autopilot.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
65 Series: T.C. 3A20	SA393EA	Electronic voltage alarm.	EA	53500	McKinley Engineering Company P.O. Box 275 Palisades Park, NJ 07650
65 Series: T.C. 3A20	SA411CE	M4P or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series: T.C. 3A20	SA444SW	Lycoming IO-720A1A engines and increase in takeoff and loading weight. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65 Series: T.C. 3A20	SA470SW	Automatic pilot AK122 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series: T.C. 3A20	SA471SW	Automatic trim system AK149.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series: T.C. 3A20	SA505CE	Install entrance door.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65 Series: T.C. 3A20	SA529SW	Gear 168 electro-mechanical rotary actuator.	SW	42131	H & H Enterprises P.O. Box 75135 Oklahoma Ctiy, OK 73125
65 Series: T.C. 3A20	SA651SW	AK206 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series: T.C. 3A20	SA695SW	Engine induction system air filter removal.	SW	71800	Sinclair Oil & Gas Company Aviation Department 3505 N. Sheridan Road Tulsa, OK 74101
65 Series: T.C. 3A20	SA704CE	Installation of BUTLER VAC and ADF navigation system. Amended April 1974.	CE	19000	Butler National Corporation 8246 Nieman Road Lenexa, KS 66214

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65 Series; T.C. 3A20	SA722SW	AP-103F/FD-108 autopilot flight director system and related electronics.	SW	24252	Collins Radio Company P.O. Box 98 Addison Airport Addison, TX 75001
65 Series; T.C. 3A20	SA767SW	Mitchell Model AK 239 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA1004WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
65 Series; T.C. 3A20	SA1022WE	B-4 flight control system (PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1453WE	Installation of a Brittain Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1511WE	Pacific Airmotive Corp. rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
65 Series; T.C. 3A20	SA1528WE	Installation of Brittain B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1556WE	Installation of Brittain Industries B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1714WE	Removal of emergency exit to permit aircraft to engage in special purpose operations, as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
65 Series; T.C. 3A20	SA1794WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA2069WE	Installation of Brittain B-VII Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65, A65, A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 70; T.C. 3A20	SA22GL	Installation of Hartzell synchrophaser. Reissued 8/27/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
65, A65, 65-80, 65-A80, 65-B80; T.C. 3A20	SA43CE	Installation of Bendix M-4B and M-4C flight control system. Amended 3/8/67.	EA	15480	The Bendix Corporation Avionics Products Bendix Radio Division Baltimore, MD 21204
65, 65-80, 65-A80, 65-90; T.C. 3A20	SA318EA	Installation of Monitair angle of attach and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
65-L23F, 65-80, 65-A80, 65-B80, -90, -A90; T.C. 3A20	SA394CE	Install Hoskins Twi. Mk III supplemental high intensity lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
65, 65-80; T.C. 3A20	SA1-642	2011X Series radome. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
65, 65-80; T.C. 3A20	SA506WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTI Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
65, 65-80; T.C. 3A20	SA518SW	Goodrich wheel and brake. Reissued Feburary 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65, A65, 65-80, A65-8200, 65-A80, -A80-8800, -B80, -88, -70; T.C. 3A20	SA277GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 12/21/78.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65, A65, -80, -A80, -A80-8800, A65-8200, -B80, 70: T.C. 3A20	SA1244SW	Mitchell automatic flight system FD/AP282-313 cons. of flight/director/autopilot and automatic pitch trim. Issued 1/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, A65, A65-8200, 65-80, -A80, -A80-8800, -B80, -88, -90, -A90, 70, B90, C90, E90: T.C. 3A20	SA1279CE	Installation of Avcon Ind. I30-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
65, A65, 65-80: T.C. 3A20	SA1328SW	Replacement of existing alternators with 100 ampere Prestolite ALV-8042's. Reissued 10/20/72.	SW	61500	Nayak Aviation Corporation 206 E. Terminal Avenue San Antonio, TX 78216
65, A65, A65-8200, 65-80, -A80, -A80-880, -B80, -88, -90, -A90, -A90-1, -A90-2, -A90-3, -A90-4, 70, B90, C90, E90; T.C. 3A20	SA1583CE	Install wing front spar reinforcement kit. Issued 4/11/80.	WE	13177	Aviadesign, Inc. Suite 101, Bank of America, Levy Building 5808 E. Telephone Road Ventura, CA 93003
65, A65, 65-80, 65-A80; T.C. 3A20	SA2349SW	3-place divan. Issued 8/13/76.	SW	36550	Foster-Edwards Aircraft Co., Inc. Box 574 Addison, TX 75001
65, A65, A65-8200, 70: T.C. 3A20	SA2365WE	Installation of Hartzell HC-3X20-2/9333C or HC-A3X20-2/9333C propellers. Reissued 7/14/71.	SW	37080	Bernard A. Gallaher 1400 Southwest Tower Houston, TX 77002
65, A65, A65-8200, 65-90, -A80, -A80-8800, -B80, -88, 70, 65-90, -A90, A90-1, -2, -3, -4, B90, C90 (S/N LJ502 thru 526): T.C. 3A20	SA3080WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
65, A65, 65-80, -A80, -B80, -A80-8800: T.C. 3A20	SA3114SW-D	Automatic flight system AK549, cons. of Century III autopilot with optional radio and glide slope couplers. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, 65-80, -A80, -B80, -A80-8800, A65-8200, 70: T.C. 3A20	SA3115SW-D	Mitchell AK585, cons. of Century IV autopilot or AK585FD Century IV flight director autopilot. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, A65, -80, -A80, -B80, -88, -90, C90, E90, 65-A90, A99, 99, B99, 100, A100, B100, 200, A200; T.C. 3A20, A14CE, A24CE	SA4157SW	Install one, two, or three place side facing seat (frame only). Issued 7/25/80.	WE	28000	Custom Aircraft Conversions 234 West Turbo Drive San Antonio, TX 78216
65-90: T.C. 3A20	SA185CE	Installation of AC Spark Plug Division oil filter assembly type OF-103-A, P/N 6435565; or type OF-105-A, P/N 25010400. Amended 6/5/80.	GL	00750	AC Spark Plug Division of General Motors Flint, MI 48556
65-80: T.C. 3A20	SA1009EA	Installation of Edo area navigation system Model TCP-71A. Reissued 12/19/78.	EA	32625	EDO-AIRE Div. of Edo Corporation 216 Passaic Avenue Fairfield, NJ 07006
65-80, -A80, -B80, -88, -90, -A90: T.C. 3A20	SA381EA	Installation of radome kit No. 2090K. Amended 12/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
65-80, -A80, -B80, -88, -90, -A90, B90, C90, E90, 100, A100, A100A, A100C, B100; T.C. 3A20, A14CE	SA37GL	Installation of Norton radome kit No. 2090KS. Amended 8/24/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
65-90, -A90, -A80-8800, -B80, -88: T.C. 3A20	SA453GL	Installation of a Shadin Co. 910502 or 910504 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Suite 206 Minneapolis, MN 55426
65-A80, -B80, -88, -90, -A90, -B90: T.C. 3A20	SA45GL	Install AMF inverter MGH 549-1. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65-90, A-90, B-80; T.C. 3A20	SA2283WE	Installation of oil lever indicator system. Issued 11/30/70.	WE	25600	Communications Components Corp. 1524 West 15th Street Long Beach, CA 90813
65-B80 Queen Air; T.C. 3A20	SA940SO	Removal of existing fuel flowmeter and associated components and installation of fuel flowmeter. Issued 6/24/77.	SO	02850	Aerosonic Corporation P.O. Box 4627 Clearwater, FL 33518
65-B80; T.C. 3A20	SA1607CE	Installation of microwave landing system airborne equipment. Issued 9/26/80.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
A65, 65-B80 & 70; T.C. 3A20	SA660CE	Installation of Bendix M4-C Flight Control System.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33310
65-90; T.C. 3A20	SA133GL	Install B.F. Goodrich thermally efficient propeller de-icers. Amended 9/15/76.	GL	38500	B.F. Goodrich 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA826SW	Elevator electric trim system.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 - Adams Field Little Rock, AR 72203
65-90; T.C. 3A20	SA997EA	Installation of B.F. Goodrich electrothermal propeller deicing system. Issued 2/7/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Company 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA1108SO	Installation of Pratt & Whitney engine model PT6A-20 replacing model PT6A-6. Issued 10/15/79.	SO	14213	B. R. Power Division Aztec Leasing, Inc. 20 Piney Mountain Road Greenville, SC 29607
65-90; T.C. 3A20	SA2740SW	Installation of P&W PT6A-135 engines and bleed air conditioning and pressurization system. Issued 3/24/78.	SW	77111	E.J. Swearingen P.O. Box 4640 Waco, TX 76705
65-90, -A90; T.C. 3A20	SA761SW	Mitchell AP238 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65-90, -A90; T.C. 3A20	SA822SO	Installation of P & W PT6A-28 engines. Amended 3/27/78.	SO	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
65-90, 65-A90, 65-B90; T.C. 3A20	SA526SO	Installation of the Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-90, -A90, B90, C90, E90; T.C. 3A20	SA546SO	Instllation of Bendix M-4D automatic flight control system including optional manual electric trim system and optional flight director system. Issued April 1980.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Launderdale, FL 33310
65-90, -A90, -B90; T.C. 3A20	SA1177SW	Revised main landing gear doors.	SW	61500	Mayak Aviation Corporation 206 E. Terminal Drive San Antonio, TX 78216
65-90, -A90, B90, C90; T.C. 3A20	SA2693WE	Installation of inertial air separator scoops. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA810CE	Battery temperature sensing and over-temperature warning systems. Amended October 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA879SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA951CE	Installation of lead-acid battery. Issued October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, 99, A100; T.C. 3A20	SA1017SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78050	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA1194CE	Install Teledyne/Gill lead-acid battery, BB639/T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	78052	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, H90; T.C. 3A20	SA1451CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, 65-A90, B90 C90, E90, H90; T.C. 3A20	SA1452CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, A90, B90, C90, E90, 99, 99A, A99A, 100, A100; T.C. 3A20	SA2284SW	Ignition current monitor system. Issued 1/19/76.	SW	16850	The BY4 Company Box 7001 Dallas, TX 75209
65-90, -90A, -A90-1, -2, -3, -4, B90, C90, E90, 99, 99A, A99, A99A, B99, 200, A200, 200T; T.C. 3A20, A14CE, A24CE	SA566NW	Installation of parachute deployment system. Issued 3/27/78.	NW	80915	U.S. Forest Service 3905 Vista Avenue Boise, ID 83705
65-90, -A90, -A90-1, -A90-2, -A90-3, B-90, C-90; 99, 99A; T.C. 3A20, A14CE	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457
65-90, -A90, -A90-1, -A90-2, -A90-3, -A90-4, B90, C90, E90; T.C. 3A20	SA2907WE	Installation of fuel tank boost pump. Amended 11/18/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
65-90, -A90, B90, C90; T.C. 3A20	SA3266SW-D	Mitchell automatic flight system AK725 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/24/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
65-90, -A90, B90, C90, E90; T.C. 3A20	SA3369SW-D	Automatic flight system YK835 consisting of yaw damper system. Issued 7/21/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
65-A90; T.C. 3A20	SA691CE	Installation of fuel drain manifold tank.	GL	37809	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65-A90; T.C. 3A20	SA729SW	Installation of Collins AP-103F/FD-108 autopilot/flight director system and related electronics. Amended 2/14/68.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-A90; T.C. 3A20	SA845CE	Installation of wing flap override switch and duplicate flap down limit switch. Issued May 1972.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65-A90; T.C. 3A20	SA1813SW	Battery temperature sensing and indicating system. Issued 3/8/74.	SW	02300	Aero Instrument Supply, Inc. 7515 Lemon Avenue Box 7481 Dallas, TX 75209
65-A90, -A90-1, B90; T.C. 3A20	SA418SO	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-A90, B90; T.C. 3A20	SA16GL	Install AMF inverter MSE 23-400. Reissued 11/17/78.	GL	50360	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
65-A90, B90, C90; T.C. 3A20	SA377GL	Addition of fourth cabin window on right hand side of fuselage. Issued 11/29/79.	GL	18320	Burlington Northern Airmotive International Airport Minneapolis, MN 55450
65-A90, -B90, -C90, E90; T.C. 3A20	SA3971WE	Installation of SDI Model CFS-2002, fuel flow indicating system. Amended 10/19/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
65-B90, -A90 with 90-4031 kit; T.C. 3A30	SA537CE	Installation of Collins AP-103F/FD108 and AP-103F/FD109G Autopilot and flight director. Amended 9/13/69.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-B90, -A90 with 90-4031 kit; T.C. 3A20	SA567CE	Installation of Collins AP-103F/FD108 and AP-103F/FS108G, AP-103F/FD109G autopilot and flight director. Amended 5/4/70.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
B90: T.C. 3A20	SA569CE	Installation of Collins AP104/ FD109H Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90: T.C. 3A20	SA603CE	Installation of Collins AP-104/ FD-109F Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90: T.C. 3A20	SA989CE	Installation of fuel dump valve: G.W. increase to 10,000 pounds. Amended 3/5/70.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
B-90: T.C. 3A2	SA1665SW	Fabricate and install bar assembly. Issued 5/29/73.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
B-90, C-90: T.C. 3A20	SA1454SW	Mitchell automatic flight system model FD/AP282-318 cons. of flight director/autopilot with optional command trim. Issued 4/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B-90, C-90: T.C. 3A20	SA1458SW	Mitchell automatic flight system AK318 cons. of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 4/24/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90: T.C. 3A20	SA1517SW	Automatic flight system YK384 cons. of yaw damper. Issued 9/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90: T.C. 3A20	SA1593SW	Foxtronics/TRAM BT1 600 nickel-cadmium battery temperature system. Issued 1/3/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
65-B90, C90, E90: T.C. 3A20	SA547CE	Installation of Bendix M4C autopilot. Amended 8/1/72.	SO	15475	The Bendix Corporation Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
65-B90, C90, E90: T.C. 3A20	SA1640SW	Mitchell automatic flight system AK422/FD cons. of Century IV autopilot/flight director with command electric trim. Issued 4/19/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90, E90: T.C. 3A20	SA3042SW-D	Mitchell automatic flight system AK456 or 456 FD cons. of Century IV autopilot or Century IV flight director autopilot with command/ automatic electronic pitch trim system and optional remote annuciator panel. Issued 1/31/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90, E90: T.C. 3A20	SA3294SW-D	Yaw damper system YK384. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
B90, C90, E90: T.C. 3A20	SA3379SW-D	Mitchell automatic flight system AK878 consisting of Century 41 autopilot or AK878 FD consisting of Century 41 flight director autopilot. Issued 6/30/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C90: T.C. 3A20	SA537SO	Installation of Bendix YD-4 yaw damper. Issued 5/15/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90: T.C. 3A20	SA541SO	Installation of Bendix FCS-910 automatic flight control system including optional flight director indicator DH-841. Amended 1/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90: T.C. 3A20	SA925EA	Installation of Collins AP-105 autopilot system. Issued 6/28/72.	NE	08160	AIRKAMAN, Inc. Bradley International Airport Windsor Locks, CT 06096
C90, E90: T.C. 3A20	SA546SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim system and optional flight director system. Amended 5/16/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
C90, E90: T.C. 3A20	SA3124WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
C90, E90, 99: T.C. 3A20, A14CE	SA1011SO	Replace existing nickel-cadmium battery with Gill RB638/T series lead-acid battery. Issued 9/3/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road Suite 200 Atlanta, GA 30339
E90: T.C. 3A20	SA2667WE	Installation of Sperry SPZ-200 autopilot and Stars Instrument System or SPI-77C flight director system. Amended March 1974.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90: T.C. 3A20	SA2680WE	Category II approval of airborne instruments and equipment. Reissued 9/17/73.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90, 99, A100, 200: T.C. 3A20, A14CE, A24CE	SA920SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78052	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
76: T.C. A29CE	SA1153EA	Installation of DeVore "tel-tail" lights on lower surface of horizontal stabilizer. Reissued 7/24/79.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
76: T.C. A29CE	SA1455CE	Installation of KFC200 flight control system (2 axis). Issued 10/17/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
76: T.C. A29CE	SA3256SW-D	Mitchell automatic flight system AK694 consisting of Century IV autopilot or AK694FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76: T.C. A29CE	SA3257SW-D	Mitchell automatic flight system AK693 consisting of Century III autopilot with optioanl radio and glide slope couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76: T.C. A29CE	SA3258SW-D	Mitchell automatic flight system AK692 consisting of Century III autopilot with optional radio couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76: T.C. A29CE	SA3259SW-D	Mitchell AK619 consisting of Century I autopilot with optional omni tracker. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral wells, TX 76067
76: T.C. A29CE	SA3260SW-D	Mitchell command electric trim AK695. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
76: T.C. A29CE	SA3261SW-D	Yaw damper system AK696. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral wells, TX 76067
76: T.C. A29CE	SA3317SW-D	Installation of Mitchell automatic flight system AK761 consisting of Century I autopilot with omni tracker. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76: T.C. A29CE	SA3318SW-D	Installation of Mitchell automatic flight system AK762 consisting of Century IIB autopilot with optional radio couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76: T.C. A29CE	SA3319SW-D	Installation of Mitchell automatic flight system AK763 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral wells, TX 76067
76: T.C. A29CE	SA3320SW-D	Installation of Mitchell automatic flight system AK764 consisting of Century IV autopilot or AK764FD consisting of Century IV autopilot flight director with optional remote annunciator. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
76; T.C. A29CE	SA3321SW-D	Installation of Mitchell automatic flight system AK765 consisting of command electric trim system. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3322SW	Installation of Mitchell yaw damper YD766. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3345SW	Installation of Mitchell yaw damper YD838. Issued 1/28/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3346SW	Mitchell automatic flight system AK827/FD consisting of Century 41/FD flight director autopilot. Issued 12/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3356SW	Installation of Mitchell automatic flight system AK826 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Incc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA4005WE	Removal of main landing gear door. Issued 7/25/79.	WE	71630	Sierra Academy of Aeronautics Oakland International Airort Oakland, CA 94614
95 Series; T.C. 3A16	SA1-235	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
95 Series; T.C. 3A16	SA1-395	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-422	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-482	16" x 17" opening in lower surface of fuselage.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
95 Series; T.C. 3A16	SA1-588	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
95 Series; T.C. 3A16	SA3-262	Automatic pilot L-2 with or without approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-470	L-2C autopilot with or without approach coupler and altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-624	Winslow oil filter 30409A.	CE	80670	United Airplane Sales, Inc. Municipal Airport Wichita, KS 67202
95 Series; T.C. 3A16	SA3-633	Autopilot I-2C with or without approach coupler and/or altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA4-570	Radio rack in nose compartment.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
95 Series; T.C. 3A16	SA4-691	Oil filter 30409A with element 130235.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
95 Series; T.C. 3A16	SA4-1052	Autopilot and optional nav-coupler "add-on" BT-300, BT-301 or BT-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA4-1612	Anticollision beacon Roto-lite X6000, either 12 or 24 volt, on vertical fin	WE	49690	The Norman Larson Company Van Nuys Airport Van Nuys, CA 91408

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95 Series; T.C. 3A16	SA9SW	Aileron trimmer ATC35-107.	SW	06000	Aircraftsmen, Inc. Hangar 2, Will Rogers Field Oklahoma City, OK 73125
95 Series; T.C. 3A16	SA44EA	Wet pump pneumatic deicing.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA70SW	Vapor automatic temperature control system.	CE	82540	Vapor Heating Company 2522 E. Douglas Wichita, KS 67202
95 Series; T.C. 3A16	SA74CE	Federal F-400 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
95 Series; T.C. 3A16	SA92SW	Automatic pilot AK103 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA171WE	Full flow lube oil filter 304093 with element 140235.	WE	96625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
95 Series; T.C. 3A16	SA173EA	Beech 5D1048 air reservoir assembly relocated for wing and tail boot deicer.	NE	08160	AirKaman, Inc. Bradley Field Windsor Locks, CT 06096
95 Series; T.C. 3A16	SA231EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA287CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA311WE	Beech pneumatic pitch assist PC-1 and optional installation altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA316EA	M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA360CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation Marquette Division 1145 Galewood Drive Cleveland, OH 44110
95 Series; T.C. 3A16	SA474EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4895 Sawyer Road International Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA474WE	B4 flight control system including basic autopilot, pitch assist PC-1, altitude hold AH-1, and navigational coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA516SW	Automatic trim AK160.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA617SW	III autopilot, automatic pitch trim, stabilizer and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA742SW	AK196 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA821WE	Single-place windshield.	WE	69590	SAFE-SITE, Inc. 3511 W. Sixth Street Los Angeles, CA 90005
95 Series; T.C. 3A16	SA844WE	One-piece windshield.	WE	14238	Dee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
95 Series; T.C. 3A16	SA1494WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95 Series: T.C. 3A16	SA1532WE	Installation of Brittain Model B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series: T.C. 3A16	SA1542WE	Installation of Brittain Model B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series: T.C. 3A16	SA1559WE	Installation of Brittain Industries Model B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series: T.C. 3A16	SA1597WE	Installation of Brittain Model B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series: T.C. 3A16	SA1677WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series: T.C. 3A16	SA1933WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, B95A, D95A and E95; T.C. 3A16	SA153SO	Installation of turbosupercharged Lycoming O-360-A1A, IO-360-B1A or IO-360-B1B engines. Amended 2/28/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
95, B95, B95A, D95A, 95-55, 95-A55, 95-B55: T.C. 3A16	SA263CE	Supplemental Model A high intensity wing tip lights, Model C tail light, with or without Model 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
95, B95, B95A, D95A, 95-55, -A55, -B55, -C55, -D55, -56: T.C. 3A16	SA378CE	Installation of Hoskins Supp. Model A high intensity wing tip lights, Model D or E tail lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
95, B95, B95A, 95-A55, -55, D95A: T.C. 3A16	SA571WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTI Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
95, B95, B95A, 95-55, 95-A55, 95-B55, 95-B55B (T-42A), 95-C55: T.C. 3A16	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-3 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
95, B95, 95-55, 95-A55, B95A, D95A, E95, 95-B55, -B55A, -B55B, -C55, D55, 95-C55A, D55A, E55, E55A, 56TC, A56TC, 58, 58A: T.C. 3A16	SA901SO	Installation of single-piece sloped windshield. Amended 11/21/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. c/o F.K. Leddick & Associates, Inc. 175 W. Wieuca Rd., Suite 120 Atlanta, GA 30342
95, B95, B95A, D95A, E95: T.C. 3A16	SA1409SW	Mitchell automatic flight system AK366, cons. of Century I autopilot with optional omni tracker. Issued 12/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D95A: T.C. 3A16	SA1760WE	Installation of Brittain Industries Model B-5 or NAV-2 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, 95-55, -A55, B95A, D95A, E95, -B55, -B55A, -B55B, -C55, D55, -C55A, D55A, E55, E55A: T.C. 3A16	SA2977WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
95, B95, D95A, E95: T.C. 3A16	SA3090SW-D	Automatic flight system AK562, cons. of Century IIB autopilot. Issued 12/15/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95, B95, B95A, D95, E95: T.C. 5A3	SA3179SW-D	Automatic flight system AK650 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 1/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95, B95, B95A, D95, E95; T.C. 5A3	SA3187SW-D	Mitchell automatic flight system AK366 consisting of Century I autopilot with optional omni tracking system. Issued 2/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D59A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA3680WE	Installation of centerline external air skeg. Amended 4/2/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90065
95, B95, B95A, E95, 95-55, -A55, -B55, -B55A, -B55B, -E55, 56TC, 58, 58A; T.C. 3A16	SA4184WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
95-55; T.C. 3A16	SA1820WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, -A55, -B55, -C55, -D55; T.C. 3A16	SA9CE	Installation of M4D or M4C flight control system. Amended 6/1/70.	SO	15475	Bendix Corporation Avionics Division 2100 N.W. 62nd Street P.O. Box 9414 Fort Lauderdale, FL 33310
95-55, -A55, -B55; T.C. A23CE	SA71GL	Install P/N BA7610 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities, Inc. 9600 West 52nd Street Kenosha, WI 53140
95-55, -A55, -B55; T.C. 3A16	SA126CE	Install Hartzell Model HC-A3XF-2B/7636D or HC-A3VF-2B/V7636D or HC-A3VF-2B/V7636M or PHC-A3XF-2B/7636D or PHC-A3VF-2B/V7636D or PHC-A3VF-2B/V7636M propellers with Woodward Model 210355 or 210438 governors. Reissued 2/26/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-55, 95-A55; T.C. 3A16	SA136RM	Removal of existing nose cone, Beech P/N 95-410011-3 and replacement with later model nose cone, Beech P/N 95-410021-605. Issued 3/28/78.	RM	73948	Spanish Fork Flying Service, Inc. Box 48 Spanish Fork, UT 84660
95-55, -A55; T.C. 3A16	SA387GL	Installation of Norton radome kit No. 4150X-100 and -200. Issued 2/8/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-55, A55; T.C. 3A16	SA447SW	Nose modification.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA448SW	Rear baggage compartment.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA540EA	Installation of radome kits No. 3063X-B-100 and -200. Reissued 3/12/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-55, 95-A55, -B55, -B55A, -B55B; T.C. 3A16	SA795CE	Install propeller Models BHC-C2YF-2CH/C8465-6 or BHC-2CHF/FC8465-6, PHC-C2YF-2CH/C8465-6 or PHC-C2YF-2CHF/FC8465-6 with spinner C-2285-1; or PHC-C3YF-2/FC7663-2R with spinner C-3567-1. Amended 8/30/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-55, -A55, -B55, -C55, D55; T.C. 3A16	SA886EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-011401. Issued 10/27/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
95-55, -A55, -B55, -B55A, B55B, C55, C55A, D55, D55A, E55, E55A, 58, 58A; 56TC, A56TC; T.C. 3A16	SA991EA	Installation of "Tel-Tail" logo lights. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite 6 6104 Kircher Street, N.E. Albuquerque, NM 87109

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA1014WE	Installation of Symbolic Displays Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/30/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
95-55, 95-A55, -B55, -C55, -D55, E55, E55A, 58; T.C. 3A16	SA1130CE	Installation of King Model KFC-200 2-axis (3 optional), flight control system. Amended 6/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-55, A55, B55, B55A, C55, D55, E55; T.C. 3A16	SA1173SW	Mitchell automatic flight system AK292 cons. of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers. Issued 7/10/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1299SW	Mitchell automatic flight system Model 282-292 cons. of flight director/autopilot with optional automatic pitch trim. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -D55, -D55A, E55, E55A; T.C. 3A16	SA1300SW	Mitchell automatic flight system AK330, cons. of Century I autopilot with optional omni tracker. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA1872CE	Installation of elevator tail cone fairing. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-55, -A55, -B55, -C55, D55, D55A, E55, E55A, 56TC, A56TC; T.C. 3A16	SA1565SW	Mitchell automatic flight system AK408 cons. of Century II autopilot with optional radio coupler. Issued 12/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1743SW	Mitchell automatic flight system AK401 cons. of Century IIB autopilot with optional radio coupler. Issued 10/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA1777SW	Mitchell automatic flight system AK450 cons. of Century III autopilot with optional command/electric trim radio coupler, and glide slope coupler. Issued 12/26/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A; T.C. 3A16	SA1808SW	Installation of automatic flight system AK446 Century IV autopilot and AK446FD Century IV flight director autopilot with electronic/command, and pitch trim. Issued 2/15/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, B95, A-55, B55, C55, B95A, D95A; T.C. 3A16	SA1958WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, 95-A55, -B55, -C55, D55, E55, 58; T.C. 3A16	SA2543WE	Installation of SDI/Hoskins Model 700801 anticollision light. Amended 12/19/72.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
95-55, 95-B55A; T.C. 3A16	SA2882WE	Installation of McCAuley 3AF32C75/82NS-6 full-feathering constant speed propellers and D3499 or D3605 spinner assemblies. Issued 5/13/74.	WE	17154	Dennis A. Praegitzer Bridgeford Flying and Propeller Service P.O. Box 6277 Stockton, CA 95206
95-55, A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3108SW-D	Mitchell AK446 or AK446FD cons. of Century IV flight director autopilot with optional remote annuciator. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3109SW-D	Mitchell AK450 cons. of Century III autopilot with optional command automatic electronic pitch trim system, radio and glide slope coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3295SW-D	Yaw damper system YK428. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	SIC CODE	STC HOLDER
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A13	SA3333SW-D	Mitchell automatic flight system AK401 consisting of Century IIB autopilot with optional radio couplers. Issued 2/20/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3918WE	Installation of Silver Instruments Fueltron III digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3919WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-55, -A55, -B55, -B55A, -B55B, -C55, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA4208WE	Installation of DTI-1000, -1001, and/or -1002/3 autopilot adapters for the Edo-Aire Mitchell Century III autopilot. Issued 8/13/80.	WE	47775	Douglas L. Fettler 1212 North Broadway, Apt. H Escondido, CA 92026
95-A55; T.C. 3A16	SA2690WE	Installation of manual pitch trim system and Lear P/N 800890 autopilot. Issued 6/19/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510
95-A55, 95-B55, 95-C55; T.C. 3A16	SA1392WE	Modification of fuselage structure and control system to accommodate a camera installation between Stations 131 and 151.	WE	25971	Continental Airservice, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
95-A55, -B55, -C55, -D55, E55/E55A, 58; T.C. 3A16	SA1523CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-A55, -B55; T.C. 3A16	SA2964WE	Installation of Collins AP 107/FD 112C autopilot/flight director system. Reissued 1/14/75.	CE	24250	Collins Radio Group 5220 "C" Avenue, N.E. Station 120-120 Cedar Rapids, IA 52406
95-B55; T.C. 3A16	SA3179WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 7/27/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
95-B55; T.C. 3A16	SA3353SW	Installation of Mitchell automatic flight system AK841/FD consisting of Century 41/flight director autopilot. Issued 1/29/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-B55, -C55, D55, E55, 56TC, 58; T.C. 3A16	SA15GL	Installation of radome kit No. 3064X. Amended 9/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operation P.O. Box 350 Akron, OH 44309
95-B55, 95-C55, 56TC, D55, E55, 58; T.C. 3A16	SA40GL	Installation of Norton Company radome kit No. 3064X-R-500 for 10" RCA AVQ 45, 46, 47, and the 12" King KWX-40 radar antennas. Amended 4/11/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-B55, -B55A, E55, E55A, 58, 58A; T.C. 3A16	SA64GL	Installation of radome kit P/N 4083X. Amended 5/8/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-B55, -B55A, -C55, -C55A; T.C. 3A16	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
95-B55, -C55, 56TC, D55, E55, 58; T.C. 3A16	SA492EA	Installation of Radome Kit No. 3064X-R-500 for 10-inch RCA AVQ-45, AVQ-46, and AVQ-47 radar antenna. Amended 6/19/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
95-B55 & 95-B55A, T.C. 502 and up; 95-C55 & 95-C55A, TE-1 thru TE-451; 95-D55 & 95-D55A, TE-452 thru TE-767; 95-E55 & 95-E55A, TE768 and on; T.C. 3A16	SA799CE	Installation of Airborne/Goodyear iceguard. Issued April 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95-D55, -D55A, E55, E55A, 58, 58A; T.C. 3A16	SA1471CE	Installation of flap and aileron seals. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-B55, 95-C55, 95-B55A, 95-C55A; T.C. 3A16	SA2031WE	Installation of Brittain Industries B-VII, MAV-2B, or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-B55, -B55A, E55, E55A; T.C. 3A16	SA3364SW	Mitchell automatic flight system AK842 consisting of Century 21 autopilot. Issued 6/6/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-B55, -B55A, -E55, -E55A; T.C. 3A16	SA3378SW-D	Mitchell automatic flight system AK841 consisting of Century 41 autopilot or AK841FD consisting of Century 41 flight director autopilot. Issued 5/15/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-B55, -B55A, -C55, -C55A, D55, D55A; T.C. 3A16	SA3657WE	Installation of a vapor cycle air conditioning system. Issued 6/28/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
95-C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA773CE	Installation of Hartzell BHC-C2Y, BHC-J2Y, PHC-C3Y or PHC-J3Y propellers in accordance with Hartzell Manual 115G. Amended 2/1/80.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1054CE	Installation of AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1055CE	Installation of AP-107 3-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1056CE	Installation of AP-107, 2-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, D55, E55, 56TC, A56TC, 58; T.C. 3A16	SA1345CE	Chrome plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
95-C55; T.C. 3A16	SA1713WE	Removal of emergency exit to permit aircraft to engage in special purpose operations such as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
95-C55, -C55A, D55, D55A, E55, E55A, 58 58A; T.C. 3A16	SA3840WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
B95; T.C. 3A16	SA1-463	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
B95; T.C. 3A16	SA3400WE	Installation of Pathfinder autopilot systems. Issued 7/5/77.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
B95A, D95A, E95; T.C. 3A16	SA1672SW	Mitchell automatic flight system AK425, cons. of Century III autopilot with optional command automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/7/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
99; T.C. A14CE	SA299GL	Reduce number of passenger seats from 15 to 9. Issued 3/22/79.	GL	27760	Custom Air Service Willow Run Airport Ypsilanti, MI 48197
99; T.C. A14CE	SA366GL	Installation of microwave landing system airborne equipment. Issued 10/12/79.	GL	58150	Mesaba Aviation 2002 Airport Road Grand Rapids, MN 55744
99; T.C. A14CE	SA4030SW	Pratt & Whitney PT6A-27/28 engines. Issued 8/30/79.	SW	69214	Royale Turbines, Inc. Shreveport Regional Airport Shreveport, LA 71109
99, 99A; T.C. A14CE	SA717CE	Installation of M4C autopilot.	CE	15477	Bendix Avionics 3303 East Harry Street Wichita, KS 67218

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
99, 99A, 99A (FACH), A99, A99A, B99: T.C. A14CE	SA114GL	Installation of Norton Radome Kit 3097X. Issued 5/20/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
99, 99A, A99, A99A, B99; T.C. A14CE	SA143GL	Modification of existing B.F. Goodrich propeller de-icing system. Issued 11/23/76.	GL	38500	B.F. Goodrich Engineered Systems Company Div. of B.F. Goodrich Company Akron, OH 44318
99, 99A, 100, A100: T.C. A14CE	SA811CE	Battery temperature sensing and over-temperature warning systems. Issued February 1972.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
99, A99, 99A, A99A, 100, A100, A100A T.C. A14CE	SA894SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	SO	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
99, 99A, 99A (FACH), A99, A99A, B99, 100, A100, A100A, A100C, B100: T.C. A14CE	SA1178CE	Install wing front spar reinforcement kit. Reissued 5/9/80.	WE	13177	Aviadesign, Inc. Suite 101, Bank of A., Levy Bldg. 5808 E. Telephone Road Ventura, CA 93003
99, 99A, A99A, B99, 100, A100, A100A, A100C, B100: T.C. A14CE	SA1290CE	Install Avcon Ind. TSO-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100: T.C. A14CE	SA1453CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100: T.C. A14CE	SA1454CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Reserach Corporation P.O. Box 222 Buffalo, NY 14225
99, 99A, A99, A99A, B99, 100, A100: T.C. A14CE	SA2908WE	Installation of fuel tank boost pump. Issued 7/23/78.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
99, 99A, 99A (FACH), A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA3106WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/90.	SW	30002	DeVore Aviation Corporation Suite P 6104 Kircher Street, N.E. Albuquerque, NM 87109
99, 99A, A99, A99A, B99; T.C. A14CE	SA4013WE	Installation of a hydraulic landing gear retraction system. Issued 9/19/79.	WE	13177	Aviadesign, Inc. Suite 101, Bank of America Levy Building 5808 East Telephone Road Ventura, CA 93003
99A: T.C. A14CE	SA981EA	Installation of modified cargo door, airstair door, jump door in cargo door and external parachute's step. Amended 10/4/74.	EA	23450	C M C Industries, Inc. Hyde Field, Route 223 Clinton, MD 20735
100, A100: T.C. A14CE	SA1197CE	Install Teledyne/Gill lead-acid battery, BB638T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	65300	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133
100, A100: T.C. A14CE	SA1573SW	Foxtronics/TRAM BT1 600 nickel cadmium battery temperature system. Issued 12/19/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
A100: T.C. A14CE	SA256GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
A100: T.C. A14CE	SA476SO	Installation of M4C autopilot in accordance with Bendix drawing list AF-163, Rev. A. Issued 10/14/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
A100; T.C. A14CE	SA1058SO	Replace existing nickel-cadmium batteries with Teledyne Gill B6381T batteries. Issued 3/29/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
B100; T.C. A14CE	SA1018SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
B100, S/N's BE-21 and up; T.C. A14CE	SA3981WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200; T.C. A24CE	SA381GL	Installation of a single Canadian Marconi CMA-734 Omega/VLF navigation system. Issued 1/4/80.	GL	18753	Butler Aviation – O'Hare, Inc. P.O. Box 66139 Chicago, II 60666
200; T.C. A24CE	SA1016SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 POwers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
200; T.C. A24CE	SA1178SO	Installation of J.E.T. DAC 2000 3-D area navigation system. Issued 9/30/80.	SO	75114	Stevens Beechcraft, Inc. P.O. Box 589 Greer, SC 29651
200; T.C. A24CE	SA1189CE	Installation of Safe Flight speed command or speed command and auto- throttle (SCAT) system. Amended 6/8/77	EA	69500	Safe Flight Instrument Corp. (SFIC) P.O. Box 550 White Plains, NY 10602
200; T.C. A24CE	SA3339WE	Installation of Hydro-Aire power brake/skid control system. Issued 5/17/77.	WE	26725	Hydro-Aire Division Crane Company, Inc. P.O. Box 7722 Burbank, CA 91510
200; T.C. A24CE	SA3982WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200, A200; T.C. A24CE	SA1278CE	Installation of Avcon Industries TSO-C39a stretchers. Issued February 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
200, A200, 200T; T.C. A24CE	SA192GL	Installation of Norton radome kit No. 2090KS Amended 8/24/78.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operation P.O. Box 350 Akron, OH 44309
200, A200, 200T; T.C. A24CE	SA1449CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
200, A200, 200T; T.C. A24CE	SA1450CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
200, A200, 200T; T.C. A24CE	SA1591CE	Installation of utility flight inspection equipment mounting rack. Issued 5/30/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
200, 200C, 200CT, 200T, A200, A200C, A200CT; T.C. A24CE	SA1602CE	Installation of wing front spar reinforcement kit. Issued 10/1/80.	CE	13177	Aviadesign, Inc. Suite 311 5755 Valentine Road Ventura, CA 93003

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	FG	STC CODE	STC HOLDER
206 Series; T.C. H2SW	SH1091SO	Replace existing battery with an Eagle-Picher magnum 13 battery. Issued 8/22/79.	SW	18190	BSI Manufacturing, Inc. 101 Space Park South Drive Nashville, TN 37211
206; T.C. H2SW	SH1137SO	Install Utah Research and Development Co. model 124BC101 battery charging system. Issued 3/11/80.	SO	18190	BSI Manufacturing, Inc. 101A Space Park South Drive Nashville, TN 37211
206, 206A, 206B; T.C. H2SW	SH963EA	Installation of battery temperature alert system Model Bell B206-TA180 or B206D-TA180. Amended 6/28/74.	EA	25920	Consolidated Instrument Co., Inc. Teterboro Airport Teterboro, NJ 07608
206 Series; T.C. H2SW	SA4206WE	Installation of Ametek TOT indicator, P/N SEL-019AU. Issued 8/14/80.	WE	16751	A. Biederman, Inc. 1045 Air Way Glendale, CA 91201
206, 206A, 206A-1, 206B, 206B-1; T.C. H2SW	SH1018EA	Installation of Casey shroud type heater. Amended 11/14/79.	EA	20112	Casey Copter Accessories, Ltd. P.O. Box 121 Montreal International Airport Dorval, Quebec, Canada H4Y 1A5
206, A, A-1, B, B-1, L, L-1; T.C. H2SW	SH2828SW	Sloping pedestal and instrument. Issued 8/4/78.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
206, A, A-1, B, B-1, L; T.C. H2SW	SH4061SW	Install ruggedized attitude gyro and related vacuum system components. Issued 11/27/79.	SW	40000	Hamilton Instruments, Inc. 106 Neuhaus Street Houston, TX 77061
206A; T.C. H2SW	SH10CE	Install Hoskins Twilighter Mk III lighting system consisting of P/N 60-0032-31 power supply and two of Model 2 P/N 30-0021-11 lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
206A; T.C. H2SW	SH117WE	Installation of cargo rack on one side or on both sides of skid gear. Amended 10/20/70.	WE	03270	U.S. Department of Agriculture Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
206A, 206B, 206L, 206L-1, Normal Category; T.C. H2SW	SH240WE	Installation of baggage compartment extension. Issued 7/12/79.	WE	50275	Ronald A. Leibin and Stephen H. Crowe 2761 Hollywood Way Burbank, CA 91505
206A; T.C. H2SW	SH411AL	Installation of mirror kit assembly. Issued 12/15/70.	AL	10650	Anchorage Helicopter Service, Inc. 1812 East Fifth Avenue Anchorage, AK 99501
206A; T.C. H2SW	SH635EA	Operate with one or both rear doors removed and both front doors installed on helicopters equipped with or without emergency float gear.	EA	65008	The Port of New York Authority 111 8th Avenue, Room 1601 New York, NY 10011
206A; T.C. H2SW	SH837EA	Installation of Airborne television and microwave transmission system. Amended 3/24/71.	EA	30992	Dynasciences Corporation Township Line Road Blue Bell, PA 19422
206A; T.C. H2SW	SH864EA	Installation of AACK-1P Optical Radiation Corporation Model B "Locator" search light plus relocation of landing lights. Installation of additional contact surfaces "bear paws" to standard skid gear. Issued 2/17/71.	EA	12495	Atlantic Aviation Corporation Bell Helicopter Service Center P.O. Box 2307 South Hackensack, NJ 07608
206A; T.C. H2SW	SH892EA	Installation of Grimes Manufacturing Company supplemental strobe lights. Issued 11/26/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
206A; T.C. H2SW	SH1164SW	Installation of dual battery system using the ship's original battery and one installed by Bell Service Instructions and Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
206A; T.C. H2SW	SH1675SW	Heater system for de-fog air. Issued 6/15/73.	SW	68768	Rockwell International Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
206A, A-1, 206B; T.C. H2SW	SH1534SW	Remove standard BHC short skid shoes and install full length hard surface skid shoes. Issued 11/8/72.	SW	61650	Northrop Worldwide Aircraft P.O. Box 108 Lawton, OK 73501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206A, B: T.C. H2SW	SA116WE	Installation of Nightsun SX-16C Searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
206A, B: T.C. H2SW	SH122WE	Installation of JB Systems, Inc. airconditioning system. Amended 12/10/73.	RM	45750	JB Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
206A, 206B: T.C. H2SW	SH124NW	Installation of Simplex 2700 and 2700A spray system tank assembly. Issued 9/9/74.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206A, 206B: T.C. H2SW	SH126WE	Installation of cartridge boost electrical starter system. Reissued 5/15/72.	WE	77492	Talley Industries, Inc. 4551 E. McKellips Road P.O. Box 849 Mesa, AZ 85201
206A, 206B: T.C. H2SW	SH138WE	Installation of Chadwick cargo rack C-72. Issued 1/6/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B: T.C. H2SW	SH139WE	Installation of Chadwick C-22 auxiliary fuel system and C-30 ferry kit. Issued 1/7/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B: T.C. H2SW	SH148WE	Installation of Chadwick electronic weighing system C-45. Issued 5/26/72.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B: T.C. H2SW	SH158WE	Installation of Silver Star I anticollision light. Issued 7/9/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
206A, 206B: T.C. H2SW	SH209WE	Installation of type design change covering the SFENA ministab flight control system in various model combinations. Reissued 9/7/79.	WE	71450	SFENA Corporation 385 Reed Street Santa Clara, CA 95050
206A, 206B: T.C. H2SW	SA244NW	Installation of HE-206-010 bleed air heater system. Issued 3/2/76.	EA	35777	J.E. Flippo Rural Route 1, Pritchard Lane Westbank, B.C., Canada VOH-2A9
206A, 206B normal category: T.C. H2SW	SH266WE	Installation of Carter Engineering Model CEI 450-206 searchlight. Issued 2/8/80.	WE	19986	Carter Engineering Company 232 South Glasgow Avenue Inglewood, CA 90301
206A, 206B: T.C. H2SW	SH278NW	Installation of an electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems Inter'l 619 Riverside Drive Seattle, WA 98108
206A, 206B: T.C. H2SW	SH309AL	Installation of cargo basket. Amended 7/26/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B: T.C. H2SW	SH332AL	Installation of Airglas model L2700-206A skis. Amended 3/3/73.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
206A, 206B: T.C. H2SW	SH380AL	Installation of cargo baskets. Amended 8/7/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B: T.C. H2SW	SH474AL	Installation of Alaskan Sky-Craft Company, Inc. cargo step. Amended 7/20/73.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH515AL	Installation of ASC transporter cargo step. Amended 4/4/75.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH543NW	Installation of Bell 205 series cyclic stick grip. Issued 12/9/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B: T.C. H2SW	SH544NW	Installation of 28 volt DC power outlet in cabin. Issued 11/10/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B: T.C. H2SW	SH625NW	Installation of collective torque tube actuated hour meter switch and an engine-out audible warning system. Issued 6/28/78.	NW	85330	Weyerhaueser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH690NW	Installation of cyclic operated counter system. Issued 11/27/78.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206A, 206B; T.C. H2SW	SH702NW	Installation of weighing system. Issued 1/23/79.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
206A, 206B; T.C. H2SW	SH759NW	Installation of an onboard weighing system. Issued 5/3/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
206A, 206B; T.C. H2SW	SH791NW	Installation of a model 50 spray system. Issued 6/26/79.	NW	66340	Rambling Rotors, Inc. Route 2, Box 244 La Grande, OR 97850
206A, 206B; T.C. H2SW	SH848NW	Installation of a model 4900 spray system. Issued 10/22/79.	NW	71770	Simplex Manufacturing Compa 5224 N.E. 42nd Avenue Portland, OR 97218
206A, 206B; T.C. H2SW	SH1062SO	Installation of fuel tank filler extension (increased fuel capacity).	SO	78475	Thoroughbred Helicopter Service, Inc. Route 3, Paris Pike Lexington, KY 40511
206A, 206B, 206L; T.C. H2SW	SH1125EA	Installation of Aircraft Parts Corp. starter-generator, P/N 150SG111Q. Amended 11/27/78.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
206A, 206B; T.C. H2SW	SH1134SO	Installation of one-piece entrance step. Issued 2/19/80.	SO	02390	Aeronautical Accessories, P.O. Box 1177 Tri City Airport Blountville, TN 37617
206A, 206B; T.C. H2SW	SH1163SO	Installation of an entrance step on high skid gear with emergency flotation system (pop-outs). Issued 7/31/80.	SO	02380	Aeronautical Accessories, P.O. Box 1177 Tri-City Airport Blountville, TN 37617
206A, 206B; T.C. H2SW	SH1753SW	Collapsible table and bar in passenger compartment. Issued 10/25/73.	SW	36550	Foster-Edward Aircraft Co 304 Fair Oaks Boulevard Euless, TX 76039
206A, 206B; T.C. H2SW	SH1754SW	Foxtronics/Iramm BTI 600 nickel-cadmium battery temperature system (single battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1755SW	Foxtronics/Iramm BTI 600 nickel-cadmium battery temperature system (dual battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1759SW	Ni-Cad battery overtemperature warning system. Issued 11/6/73.	SW	22280	Chrysler Corporation Space Division P.O. Box 29200 New Orleans, LA 70189
206A, 206B; T.C. H2SW	SH2889SW	Fuel filler neck.	SW	32758	Edwards & Associates, In 13611 Heartside Place Dallas, TX 75234
206A, 206B; T.C. H2SW	SH4083SW	Install wire strike protection system. Issued 2/16/80.	SW	75234	Bristol Aerospace, Limit P.O. Box 340283 Dallas, TX 75234
206A, 206B; T.C. H2SW	SH4134SW	Fuel extender. Issued 5/29/80.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
206A, 206B; T.C. H2SW	SH4135SW	Vertical sliding window, P/N 206-108. Issued 5/30/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206B-1; T.C. H2SW	SH164WE	Installation of A500 battery temperature monitor system. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
206A, B; 206L; T.C. H2SW	SA86GL	Installation of Marathon CA1700 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Co., 19717 East Nine Mile Ro St. Clair Shores, MI 4
206A, 206B; 206L; T.C. H2SW	SH184WE	Installation of turbine over-temperature warning system. Amended 4/4/77.	WE	60425	MFSC Incorporated 10959 San Diego Mission San Diego, CA 92108
206A, 206B, 206L, 206L-1; T.C. H2SW	SH227WE	Installation of baggage compartment extension. Issued 11/3/78.	WE	50275	Ronald Teitin/Steve Cr 2761 Hollywood Way Burbank, CA 91505
206A, 206B, 206L, 206L-1; T.C. H2SW	SH1147SO	Installation of baggage floor protector. Issued 5/29/80.	SO	02390	Aeronautical Accessori P.O. Box 1177 Tri City Airport Blountsville, TN 3761

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206A, 206B, 206L, 206L-1: T.C. H2SW	SH1148SO	Installation of a rain-gutter. Issued 6/2/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri City Airport Blountsville, TN 37617
206A, 206B; 206L: T.C. H2SW	SH736SO	Installation of SAFT type 1656 nickel-cadmium electrical storage battery. Amended 11/19/76.	SO	69800	SAFT America, Inc. P.O. Box 1886 711 Industrial Boulevard Valdosta, GA 31601
206A, 206B, 206L: T.C. H2SW	SH1148EA	Installation of a modified Lear-Siegler starter-generator, P/N 23032-010. Amended 6/1/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
206A, 206B, 206L: T.C. H2SW	SH4136SW	Replacement window, P/N 206-B-104-23, -24, 206-L-104-23, -24. Issued 5/30/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206L, 206L-1: T.C. H2SW	SH200GL	Installation of NI-CAD, Inc. Model No. 62239 engine lubrication system scavenge filter. Amended 6/22/79.	GL	61546	NI-CAD, Incorporated 24800 U.S. 20 South Bend, IN 46628
206A, 206B, 206L, 206L-1: T.C. H2SW Normal Category	SH244WE	Installation of cyclic support cover, P/N 20096C Issued 10/9/79.	WE	50275	Stephen H. Crowe and Ronald A. Leibin 2761 Hollywood Way Burbank, CA 91505
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1: T.C. H2SW	SH247WE	Installation of Silver Instruments fueltron IG or IP digital fuel flow and totalizer system. Issued 9/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1: T.C. H2SW	SH252WE	Installation of SDI model CFS-1002, fuel flow indicating system. Issued 9/14/79	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1: T.C. H2SW	SH253WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 9/17/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206A, 206B, 206L, 206L-1: T.C. H2SW	SH4146SW	Vertical slide window in crew door. Issued 6/25/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206L-1: T.C. H2SW	SH199SW	Installation of tail rotor flood lights on the upper surfaces of horizontal stabilizers. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
206B: T.C. H2SW	SH5NE	Installation of revised instrument panel and installation of pressure operated gyro instrument back-up system. Issued 12/14/73.	NE	26550	Copters Unlimited, Inc. T.F. Green State Airport Warwick, RI 02886
206B: T.C. H2SW	SH134GL	Install Allison 250-C20B engine. Issued 9/10/76.	GL	14212	Aztec Aviation, Inc. Grissom Airport Bedford, IN 47421
206B: T.C. H2SW	SH174WE	Installation of Nightsun SX-16C searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
206B: T.C. H2SW	SH237WE	Installation of a "HCS-206" helicopter computer system. Issued 5/23/79.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
206B: T.C. H2SW	SH384GL	Installation of Tayburn Electronics, Inc. airborne television and microwave transmission system (electronic news gathering). Issued 1/31/80.	GL	02392	Aeronautical Systems, Inc. Lane Air Terminal P.O. Box 19824 Port Columbus Int'l. Airport Columbus, OH 43219
206B: T.C. H2SW	SH446NW	Installation of Simplex 5000 spray kit. Amended 6/30/78.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206B: T.C. H2SW	SH515NW	Installation of Pacific Forest Research Center Mark II aerial ignition system. Issued 9/13/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig HArbor, WA 98335
206B: T.C. H2SW	SH830NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206B; T.C. H2SW	SH1030CE	Installation of battery temperature monitor and over temperature warning system. Issued May 1974.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Wichita, KS 67202
206B Jet Ranger II and III; T.C. H2SW	SH1503CE	Installation of Collins APS-841H automatic flight control system. Amended 4/10/80.	CE	24250	Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
206B; T.C. H2SW	SH4076SW	Installation of public address system. Issued 1/18/80.	SW	11890	Associated Air Center 8201 Lemmon Avenue Dallas, TX 75220
206L; T.C. H2SW	SH586AL	Install Airglas Model L2700-206L skis. Issued 6/10/76.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
206L, 206L-1; T.C. H2SW	SH1173SO	Installation of a wire strike protection system. Issued 10/8/80.	SO	17299	Bristol Aerospace, Ltd. P.O. Box 1177 Tri-City Airport Blountville, TN 37617
206L, 206L-1; T.C. H2SW	SH1541CE	Installation of Collins APS-841H helicopter automatic flight control system. Issued 4/21/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
206L, 206L-1; T.C. H2SW	SH4114SW	Installation of SFENA radio console 10713. Issued 4/28/80.	SW	71451	SFENA Corporation Aerospace Controls 2617 Aviation Parkway Grand Prairie, TX 75051
206L, 206L-1; T.C. H2SW	SH4115SW	Installation of instrument panel kit, 10501. Issued 4/28/80.	SW	71451	SFENA Corporation Aerospace Controls 2617 Aviation Parkway Grand Prairie, TX 75051
206L-1; T.C. H2SW	SH4099SW	SFENA 3-axis mini-stab system for single pilot IFR operation. Issued 5/9/80.	SW	71451	SFENA Corporation Aerospace Controls 2617 Aviation Parkway Grand Prairie, TX 75051
212; T.C. H4SW	SH17NW	Installation of Chadwick Electronic weighing system C-47. Issued 2/16/73.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
212; T.C. H4SW	SH171WE	Installation of A500 battery temperature monitor systems. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
212; T.C. H4SW	SH205WE	Installation of tail/rotor flood lights on upper surface of the horizontal stabilizers. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
212; T.C. H4SW	SH256WE	Installation of emergency exit window. Reissued 1/11/80.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
212; T.C. H4SW	SH261WE	Installation of rappelling kit support structures. Issued 6/9/80.	WE	80912	U.S. Department of Agriculture Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
212; T.C. H4SW	SH400NW	Installation of modified left hand door. Issued 1/20/77.	NW	33900	Evergreen Helicopters P.O. Box 358 McMinnville, OR 97128
212; T.C. H4SW	SH449AL	Installation of Airglas model L8500A skis. Amended 6/10/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
212; T.C. H4SW	SH463NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
212; T.C. H4SW	SH467NW	Cargo release switch wired in series with spare switch on pilot's cyclic control grip. Issued 6/15/77.	NW	85330	Weyerhouser Company 28801 Airport Road Eugene, OR 97401
212; T.C. H4SW	SH942EA	Installation of Tramm BTI-600 battery temperature indicating system. Issued 12/26/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
212; T.C. H4SW	SH1281SW	Interior installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
212: T.C. H4SW	SH1284SW	Installation of Norton Company's radome and radar antenna brackets. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1286SW	Installation of Butler VAC/ADD area navigation system for VFR operation only. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212: T.C. H4SW	SH1298SW	Installation of dual PC-17-400 Hertz static inverters. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn AVenue Burbank, CA 91505
212: T.C. H4SW	SH1289SW	Extension of power feeds to allow power distribution from the aft pedestal area. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1290SW	Installation of an extended instrument panel. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1333SW	Installation of weather radar equipment. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH2281SW	Environmental control unit. Issued 1/6/76.	SW	11890	Associated Air Center 7011 Lemmon Avenue Dallas, TX 75209
212: T.C. H4SW	SH2338SW	Modification for IFF type of operation. Issued 7/28/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220
212: T.C. H4SW	SH2466SW	AC inverter power system. Issued 5/24/77.	SW	11890	Associated Air Center, Inc. P.O. Box 20718 Love Field Dallas, TX 75220
212; T.C. H4SW	SH2746SW	Modification of four emergency exit panels. Issued 4/4/78.	SW	64300	Petroleum Helicopters, Inc. P.O. Box T Lafayette, LA 70502
212; T.C. H4SW	SH2892SW	Install 150 or 180 gallon auxiliary fuel tanks; standard utility seats modified; optional seats. Issued 12/21/78.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75222
214: T.C. H6SW	SH464NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems Inter'l. 619 Riverside Drive Seattle, WA 98108
214B, 214B-1: T.C. H6SW	SH2298SW	Interior arrangement and installation. Issued 3/2/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BELLANCA AIRCRAFT CORP., DELAWARE

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	SIC CODE	STC HOLDER
14-9, 14-12, 14-13 Series; T.C. 716, 745, 773	SA1177WE	NFCO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
14-12, 14-13 Series; T.C. 773, 745	SA4-527	Ceconite 101 covering of airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13 Series; T.C. 773	SA1-104	McCauley 1A170 propeller.	EA	73728	Thomas L.P. Solt, Jr. 410 Woodlawn Avenue Bethlehem, PA 18016
14-13 Series; T.C. 773	SA1-431	Rerouting of fuel lines and substitution of Bendix 476087 fuel pump for original hand-operated emergency pump.	EA	22785	H.L. Clark Ashdown Road Ballston Lake, NY 12019
14-13 Series; T.C. 773	SA1-551	Fuselage and fin covered with metal skin.	EA	72100	Skycraft Design, Inc. P.O. Box 67 Mercer County Airport West Trenton, NJ 08628
14-13 Series; T.C. 773	SA3-48	Koppers F-200 hub with 00-74R blade.	CE	33242	Elliott Flying Service, Inc. P.O. Box 418 Davenport, IA 52802
14-13 Series; T.C. 773	SA4-169	Fiberglas cloth with resin over original fabric.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
14-13 Series; T.C. 773	SA4-302	RM-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
14-13 Series; T.C. 773	SA4-468	Flaps recovered.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13 Series; T.C. 773	SA4-604	Hydraulic landing gear retracting system.	WE	48230	Kidwell Aviation Company Municipal Airport Torrance, CA 90510
14-13 Series; T.C. 773	SA4-840	Fabric replaced with glass cloth on wings, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
14-13 Series; T.C. 773	SA4-1283	Ceconite 103 covering of plywood portions of the aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13 Series; T.C. 773	SA4-1421	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-13 Series; T.C. 773	SA29EA	Sensenich M74DR fixed pitch metal propeller (Pitch 60) on aircraft equipped with Franklin 6A4-165-B3 engine.	EA	73728	Thomas L.P. Solt, Jr. 410 Woodlawn Avenue Bethlehem, PA 18016
14-13 Series; T.C. 773	SA599WE	Franklin engine 6A-335-B, McCauley propeller 2A31C21/84S-8 with Woodward governor 201453, and Firestone DFA-190 wheel assembly and CFA-252 brake assembly or equivalent.	WE	28854	Debs Aircraft and Engine Company 1065 Arroyo Street San Fernando, CA 91340
14-13 Series; T.C. 773	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
14-13 Series; T.C. 773	SA846SW	Wing root fairings.	SW	02460	Aero Plastic Enterprises, Inc. 1315 Keller Lane Seguin, TX 78155
14-13 Series; T.C. 773	SA995SO	Installation of external reservoir brake system. Issued 5/27/76.	SO	63335	R.W. Patterson, Jr. 2153 Nancy Circle Smyrna, GA 30080
14-13 Series; T.C. 773	SA1008WE	Poly-Fiber covering of elevators, rudder and horizontal stabilizers. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
14-13 Series; T.C. 773	SA1029WE	McCauley 1A170/DM7654 propeller.	NW	56550	Kenneth Eddy Mathews Route 3, Box 500 Poulsbo, WA 98370
14-13 Series; T.C. 773	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
14-13 Series; T.C. 773	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm).	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
14-13, -13-2, -3, -3W; T.C. A-773	SA4-1210	Installation of Fonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
14-13, -13-2, -3, -3W; T.C. A-773	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
14-13, -13-2, -3, -3W; T.C. A-773	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, or Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetor. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
14-13, -13-2, -13-3, -13-3W; T.C. A-773	SA797WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 Wheel Assemblies in lieu of Firestone wheel assy No. DFA180. Firestone CFA252 brakes or Bodell BMI252 brakes are required with this installation. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
14-13, -13-2, -3, -3W; T.C. A-773	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
14-13, -13-2, -3, -3W; T.C. A-773	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
14-13, -2, -3, -3W; 14-12F-3; T.C. 773, 745	SA1351WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
14-13, 14-13-2, 14-13-3, 14-13-3W, 14-12F-3; T.C. 773, 745	SA2666WE	Ceconite 102 material covering complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BELLANCA AIRCRAFT CORP., MINNESOTA

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
7 Series; T.C. 759	SA1-319	Continental C85-12 engine.	SO	17068	Columbus D. Bradley 325 Pasadena Drive Lexington, KY 40507
7 Series; T.C. 759	SA3-6	Installation of Pee-Kay Model 1500 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-214	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-303	Reinforced plastic instrument panel (exact duplicate of 5-150).	RM	28500	Dakota Aviation Company P.O. Box 18 Huron, SD 57350
7 Series; T.C. 759	SA3-322	Door modified to seaplane door.	GL	48900	E.O. Kunde Personal Air Service Mahtomedi, MN 55115
7 Series; T.C. 759	SA3-361	C-2200 main ski and CTF-2200 tail wheel ski or AWT 2500 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-362	C-2200 main ski and CTF-2200 tail wheel ski or AWT tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-368	A2000A main wheel-replacement ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-432	Install two auxiliary fins, one ventral fin and Pee-Kay Model 1800 floats. (Reissued 11/13/70.)	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-496	Install two auxiliary fins, one ventral fin and Pee-Kay Model 1800 floats. (Reissued 11/13/70.)	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-515	Skis L-1500A on main gear and L-1200A on nose gear.	AL	08125	Airglas Engineering Company P.O. Box 1254 Anchorage, AK 99502
7 Series; T.C. 759	SA3-523	Install four auxiliary and one ventral fin and Pee-Kay Model 1800 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-628	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA4-97	Auxiliary five-gallon fuel tank in wing.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
7 Series; T.C. 759	SA4-276	BM-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
7 Series; T.C. 759	SA4-339	Addition of exhaust stacks with venturi, pump, control valve, and tank for insect control work.	WE	71910	Vern Skaggs 2301 Pacific Coast Highway Lomita, CA 90717
7 Series; T.C. 759	SA4-359	Glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
7 Series; T.C. 759	SA4-699	9003-232-72T propeller with Continental C-90-12 engine.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7 Series; T.C. 759	SA4-836	Ceconite 101 covering of entire airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
7 Series: T.C. 759	SA4-1009	Eonite covering on complete airplane.	WE	52090	William G. Iott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
7 Series: T.C. 759	SA4-1636	Tri-cycle landing gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
7 Series: T.C. 759	SA5-49	Tires and tubes 25x11x4.	AL	21540	Chapman Air Taxi P.O. Box 829 Palmer, AK 99645
7 Series: T.C. 759	SA5-68	Airglass Engineering L1500A main and L1200A nose skis.	AL	11386	Louis M. Applegate P.O. Box 1047 Fairbanks, AK 99701
7 Series: T.C. 759	SA6AL	L-1500A, L1650A, or L-2000A main skis and L-1200A nose ski.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 1254 Anchorage, AK 99502
7 Series: T.C. 759	SA33CE	Removal of door.	GL	46778	Darryl F. Johnson Route 5 Mount Pleasant, MI 48858
7 Series: T.C. 759	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred P. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743
7 Series: T.C. 759	SA216SW	Conversion of aircraft to tri-cycle gear configuration.	SW	47610	K.C. Aircraft, Inc. P.O. Box 4248 Lucian Field Shreveport, LA 71102
7 Series: T.C. 759	SA217AL	Install L-1650A or L-2000A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7 Series: T.C. 759	SA220SO	Tow bar, releast mechanism, and safety tow link.	SO	37092	Gasser Banners, Inc. P.O. Box 3502 Metropolitan Airport Nashville, TN 37217
7 Series: T.C. 759	SA222SO	Change Model 7AC powerplant from Continental C65-8 to C85-12.	SO	74928	Star Aircraft P.O. Box 411 Hialeah, FL 33010
7 Series: T.C. 759	SA274WE	Fuel system modification.	WE	55100	Marks Aviation Torrance Airport Torrance, CA 90510
7 Series: T.C. 759	SA286EA	Edo 60-1320 floats.	EA	61622	North American Flying Service, Inc. Little Ferry, NJ 07643
7 Series: T.C. 759	SA513AL	Installation of Hartzell model HC-C2YL-1BF/F8468A-8R constant speed propeller. Issued 2/11/74.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
7 Series: T.C. 759	SA1177WE	WSCO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
7AC: T.C. 759	SA2-227	Windshield manufactured in accordance with Luminous Plastics, Inc. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
7AC & 7AC CONV: T.C. A-759	SA3-372	Installation of Lycoming C-235-C or Lycoming O-235-C1 engine and appropriate propeller. Reissued and amended 11/27/70.	RM	84393	C.I. Wagner Wagner Aerial Service Clark, SD 57225
7 Series; 11AC: T.C. 759, 761	SA3-435	Continental A-75-8 or A-75-9F carburetor type engine.	GL	62029	John T. Ownes 2707 East Towers Drive, Apt. 203 Cincinnati, OH 45238
7 Series; 11AC: T.C. 759, 761	SA4-369	Lift strut assemblies.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7 Series, 11AC, 11BC, S11AC: T.C. 759, 761	SA3-215	Laminated plastic and fiberglass nose cowl D-576P.	RM	28500	Dakota Aviation Company P.O. Box 18 Huron, SD 57350
7 Series, 11CC, S11CC; T.C. 759, 796	SA3-424	CTP-2200 tail ski on airplanes equipped with Scott 3000 tail wheel.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	PG	STC CODE	STC HOLDER
7 Series, 11AC, S11AC, 11BC; T.C. 759, 761	SA4-444	Carburetor and cabin hot air muff with replaceable air inlet and outlet.	WE	66600	Peter H. Raymen 5829 Deborah Street Long Beach, CA 90801
7 Series, 11AC, S11AC, 11BC; T.C. 759, 761	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
7 Series, 11 Series; T.C. A-759, A-761, A-796	SA2710WE	Installation of carburetor heat box bearings. Issued 6/15/73.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
(Aeronca Champion) 7AC, S7AC, 7BCM (Army L-16A), 7CCM (Army L-16B), S7CCM, 7DC, S7DC, 7EC, S7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCB, 7GCBA, 7HC, 7JC, 7KC, 7GCAA, 7GCBC, (Aeronca Trvtek) 11AC, S11AC, 11BC, S11BC, 11CC, S11CC, 14-19 Series; T.C. 759, 761, 796, 1A3	SA2666WE	Ceconite 102 material covering: Models listed - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
7AC, S7AC, 7BCM, 7CCM, S7CCM, 7DC, S7DC, 7EC, S7EC, 7FC, 7GC, 7ACA, 7ECA, 7GCA, 7GCAA, 7KC, 7KCAB, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 11AC, S11AC, 11BC, S11BC; T.C. 759, 761	SA4-1210	Installation of Fonnex cover on aircraft surfaces. Amended 6/30/76.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
7AC, S7AC, 7BCM, 7CCM, S7CCM, 7EC, S7EC, 11AC, S11AC, 11BC, S11BC; T.C. A759, A761	SA19SO	Installation of left and/or right auxiliary fuel tank(s). Reissued 11/8/77.	GL	02250	Aero Fabricators, Inc. P.O. Box 181 1216 North Road Lyons, WI 53148
7AC, S7AC, 7EC, 7FC, 7BCM, 7CCM, S7CCM, 7DC, 7GCBA, S7DC, 7JC, 11AC, S11AC, 11BC, S11BC, 11CC, S11CC; T.C. 759, 761, 796	SA150SO	Surface fabric attachment clip. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
7; 11, S11; 11CC, S11CC; 14-19, 17-30, -31; T.C. A-759, A-761, A-796, 1A3	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
7 Series; 14-19; T.C. A-759, 1A3	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
7 Series; 14-19, 14-19-2, 14-19-3; T.C. 759, 1A3	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
7 Series; 14-19, 14-19-2, 14-19-3; T.C. 759, 1A3	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
7AC, 7BCM, 7CCM, 7DC; T.C. A-759	SA2309WE	Installation of Madras Air Service Part No. 104 wing tips. Amended 10/26/71.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
7AC, 7BCM, 7CCM, 7DC, S7AC, S7BC, S7CC, S7DC, 11AC, S11AC, 11BC; T.C. 759, 761	SA89AL	Installation of auxiliary fuel tanks. Amended 2/7/75	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
7AC, 7BCM, 7CCM, 7DC, 7EC, 7ECA, 7GC, 7GCA, 7GCB, 7GCBC, 7KCAB, 77GAA w/ oleo; T.C. A-759	SA754CE	Install Aero Model M1500, M1800 or M2000 main skis. Amended 1/13/72.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
7AC, BC, BCM, DC, EC, ECA, FC, GC, GCA, GCB, GCBA, HC, JC, KC, S7AC, S7EC, S7CCM, S7DC, 7GCAA, 7GCBC, 7CCM; 11AC, S11AC, 11BC, S11BC, 11CC, S11CC; 14-19, -2; 8GCBC; T.C. A-759, A-761, A-796, 1A3, A21CE	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and MA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
7AC, BC, BCM, DC, EC, ECA, FC, GC, GCA, GCB, GCBA, HC, JC, KC, S7AC, S7EC, S7CCM, S7DC, 7GCAA, 7GCBC, 7CCM; 11AC, S11AC, 11BC, S11BC, 11CC, S11CC; 14-19, -2; T.C. A-759, A-761, A-796, 1A3	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and MA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
7AC, S7AC, 7BCM, 7CCM, S7CCM, 7DC, S7DC, 7EC, S7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCB, 7GCBA, 7HC, 7JC, 7KC, 7GCAA, 7GCBC; 11AC, S11AC, 11BC, S11BC; 11CC, S11CC; 14-19 Series; T.C. 759, 761, 796, 1A3	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCAA, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 7KCAB; 14-19-3A, 17-30, -30A, -31A, -31ATC; T.C. A-759, 1A3	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417
7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCAA, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 7KCAB: 14-19-3A, 17-30, 17-30A, 17-31A; 17-31ATC; T.C. A-759, 1A3	SA900EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A450, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417
7ECA; T.C. 759	SA334CE	Installation of Pee-Kay Model 1800 or B1800 (TSO-C27-2) seaplane floats and two auxiliary fins. Amended 8/17/73.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7ECA (Seaplane); T.C. 759	SA483AL	Installation of McCauley 1B90-LCM-7534 propeller. Issued 7/17/72.	AL	42132	Martin (NMI) Hettinga 1138 I Street Anchorage, AK 99501
7ECA; T.C. A-759	SA745EA	Installation of Edo Model 88-1650A floats. Amended 1/13/78.	GL	32625	Edo-Aire Seaplane Div. (Edo Corp.) c/o Air Aids of Dayton 3800 Clearview Drive Dayton, OH 45439
7ECA, 7KCA, 8KCAB; T.C. A759, A21CE	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Company airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
7ECA, 7KCAB land only; T.C. 759	SA608AL	Install leading edge cuff. Amended 8/31/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
7ECA, 7GCBC; T.C. A-759	SA261AL	Installation of Airglas Model L2000 and L-1650 wheel replacement skis. Amended 11/22/68.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7ECA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA442AL	Installation of 8.50x6 4- or 6-ply rated Goodyear or UniRoyal tires. Amended 11/7/73.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
7ECA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA3019WE	Installation of 8.50 x 6.00 4-ply rated, Type III aircraft tires. Issued 9/30/75.	WE	39580	Guardian Flying Service, Inc. 500 E. Highway 41 Las Vegas, NV 89119
7ECA, 7GCAA, 7GCBC, 7KCAB, 8KCAB; T.C. 759, A21CE	SA693CE	Install AC induction air filter type AAF-106. Amended 3/1/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
7ECA, 7GCAA, 7KCAB, 7GCBC w/ landing gear; T.C. A-759	SA755CE	Install Model M1500, M1800, or M2000 main skis. Amended 12/9/71.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
7FC; T.C. A-759	SA374GL	Remove tri-cycle landing gear and install main landing gear and tail wheel. Issued 12/16/79.	GL	48244	King Aero Services, Inc. 7170 East Main Street Reynoldsburg, OH 43068
7FC, 11AC; T.C. 759	SA1008WE	Installation of Poly-Fiber covering material (complete aircraft). Amended 8/21/79.	WE	75250	Stits Aircraft Coatings P.O. Box 3084 43rd South Fort Drive Riverside, CA 92519
7GC, 7GCB, 7GCBC, 7HC; T.C. 759	SA19CE	Installation of Pee-Kay Model 1800 or P1800 (TSO-C27-2) seaplane floats. Amended 8/17/73.	EA	29998	Pee-Kay Devore Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7GC, 7EC, GCB, GCA, GCAA, GCBC: T.C. 759	SA216AL	Install L-2500A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCA (landplane), 7GCB, 7GCBC (land and float plane); T.C. A-759	SA283AL	Installation of Hartzell HC 92ZF-1, -2, or -6 propeller hub with 7636D-4 blades or HC-C2YL-1B hub with 7663-4 blades and appropriate Woodward governor. Amended 7/22/69.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
7GCA, 7GCB, 7EC, 7GCBA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
7GCAA, 7GCBC, 7KCAB; T.C. A-759	SA33GL	Installation of EDO Model 88A-1650 floats. Reissued 6/22/76.	GL	03480	Air-Ads-of-Dayton with Edo-Aire Seaplane Division 3800 Clearview Drive Dayton, OH 45439
7GCAA, 7GCBC, 7KCAB; T.C. A-759	SA1536WE	Installation of larger rudder. Reissued 6/5/69.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7GCAA, 7GCBC, 7KCAB, 14-19-3A, 17-30; T.C. 1A3, A-759	SA71GL	Install P/N BA8110 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities, Inc. 9600 West 52nd Street Kenosha, WI 53140
7GCB; T.C. 759	SA323AL	Installation of McCauley 1A175-GM8042 propeller.	AL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645
7GCBC; T.C. 759	SA266AL	Installation of L-2500 skis. Amended 6/21/68.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCBC; T.C. 759	SA520AL	Installation of leading edge cuff stall fences, tip fences. Amended 2/2/77.	AL	27250	Crosswinds, Inc. 2301-1/2 Merrill Field Drive Anchorage, AK 99507
7KCAB; T.C. A-759	SA25RM	Installation of Christen Model 801 Inverted Oil System. Issued 3/28/74.	RM	49369	Lloyd Land Star Route, Box 65A Hudson, CO 80642
8GCBC; T.C. A21CE	SA72GL	Installation of wheel replacement ski models M2000 and M3000. Issued 3/12/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
8GCBC; T.C. A21CE	SA530AL	Installation of Hartzell HC-C2YK-1BF/F7666A-0. Issued 10/21/74.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
8GCBC; T.C. A21CE	SA666AL	Installation of Fluidyne C3000A skis. Issued 7/17/79.	AL	35800	Flirite, Inc. P.O. Box 297 Kodiak, AK 99615
8GCBC; T.C. A21CE	SA741NW	Installation of EDO-AIRE Model 689-2130 seaplane floats. Amended 6/4/80.	EA	32625	EDO-AIRE Seaplane Division Republic Airport East Farmingdale, NY 11735
8GCBC; T.C. A21CE	SA742NW	Installation of Hartzell HC-C2YK-1BF/F7666A-0 propeller on a Lycoming O-360-C1E engine. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA743NW	Installation of Bellanca 72 gallon fuel system. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
8GCBC: T.C. A21CE	SA1001EA	Installation of Pee-Kay Model 2300 (TSO-C27-2) seaplane floats. Issued 4/11/75.	EA	29998	Pee-Kay Flo... Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
11AC: T.C. 761	SA4-99	Fiberglass cloth with resin over muslin applied.	WE	46783	R.W. Johnson Route 2, Box 571-B Ojai, CA 93023
11AC: T.C. 761	SA4-789	McCauley 1A90-CM/7045 propeller on Continental A-65-8 engine.	NW	68536	Paul H. Robinson 604 S. 136 Street Seattle, WA 98101
11AC: T.C. 761	SA345CE	Remove right door.	CE	35650	Flanagan Aircraft 20224 R.D. Mize Road Independence, MO 64050
11AC, S11AC, 11BC: T.C. 761	SA4-302	RS-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
11AC, S11AC, 11BC: T.C. 761	SA4-1274	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
11AC, S11AC, 11BC, S11BC, 11CC, S11CC: T.C. A-761, A-796	SA572RM	Installation of Lycoming O-235-C1 or O-235-C2C engine. Issued 6/19/75.	RM	84393	Colman L. Wagner 401 1st Street East Clark, SD 57225
11AC, 11BC: T.C. 761	SA1250WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
11AC, 11BC, 11CC: T.C. 761, 796	SA217AL	Install L-1650A or L-2000A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
11AC, 11BC, 11CC: T.C. 761, 796	SA515AL	Installation of wing auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
11BC: T.C. 761	SA3-7	Installation of Pee-Kay Model 1500 floats with EDO struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC: T.C. 796	SA3-115	Model 3000 main ski and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
11CC: T.C. 796	SA3-670	Install Pee-Kay Model 1500 floats with EDO struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC: T.C. 796	SA699SO	Continental C85-12F Series engine less starter and generator.	SO	49720	C.W. Lasher 14100 NW. 62 Court Miami, FL 33012
11CC: T.C. 796	SA262GL	Manufacture parts and install 12-30A electrical system. (Requires alteration of engine per STC SE3CE.)	GL	67160	Kenneth L. Repke 7788 Auburn Detroit, MI 48233
11CC, S11CC: T.C. 796	SA4-1270	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13, 14-19, 14-19-2, -19-3, -19-3A, 17-30, -31, -31A, -31TC, -31ATC; T.C. 1A3, 773	SA845SW	Wing root fairings. Reissued 11/27/78.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
14-19 Series: T.C. 1A3	SA1-551	Fuselage and fin covered with metal skin.	EA	72100	Skycraft Design, Inc. Mercer County Airport West Trenton, NJ 08628
14-19 Series: T.C. 1A3	SA4-867	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series: T.C. 1A3	SA4-893	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series: T.C. 1A3	SA4-909	Autopilot. Reissued October 1973.	WE	17492	Brittain Industries, Inc. 12027 S. Prairie Avenue Hawthorne, CA 90250
14-19 Series: T.C. 1A3	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
14-19 Series; T.C. 1A3	SA4-1127	Ceconite 101 covering of entire aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91409
14-19 Series; T.C. 1A3	SA4-1269	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
14-19 Series; T.C. 1A3	SA4-1283	Ceconite 103 covering of plywood portions of the aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-19 Series; T.C. 1A3	SA486SW	Automatic pilot AK143, AK143E and AK143B-3.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
14-19 Series; T.C. 1A3	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court, P.O. Box 175B San Leandro, CA 94577
14-19 Series; T.C. 1A3	SA645SW	AK125 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19, 14-19-2; T.C. 1A3	SA294GL	Install Cleveland wheel 40-97A and brake 30-63A. Issued 3/22/79.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19, -A-2, -3, -3A, 17-30, -31, -31TC; T.C. 1A3	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George C. Johnson 10015 South Meridian Puyallup, WA 98371
14-19-2; T.C. 1A3	SA203GL	Installation of McCauley 2A34C66-N/S-90AT-12 propeller manufacturer's installation with instruction. Issued 12/8/77.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-2; T.C. 1A3	SA799WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 Wheel Assemblies in lieu of Firestone DFA180 wheel assembly. Firestone CFA252 brakes or Bodell BMI252 brakes required with this installation. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
14-19-3, 14-19-3A; T.C. 1A3	SA292GL	Install Cleveland wheel 40-75E and brake 30-52M on main gear. Issued 1/31/79.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-3, 14-19-3A, 17-30, -30A, -31, -31A, -31TC, -31ATC; T.C. 1A3, A18CE	SA847SW	Main landing wheel doors. Reissued 11/27/78.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
14-19-3, 14-19-3A; T.C. 1A3	SA874SW	Hartzell/Wren Beta System reverse pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
14-19-3A; T.C. 1A3	SA108GL	Installation of Continental IO-520D engine and McCauley D2A34C58/90AT-10 propeller. Issued 2/11/76.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-3A; T.C. 1A3	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STC - SA645SW.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19-3A, 17-30; T.C. 1A3	SA981SW	Manual Electric Trim AK276.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19-3A, 17-30, -31, -31TC; T.C. 1A3	SA1196SW	Mitchell automatic flight system model AK309 consisting of Century I, automatic aileron stabilizer with omni tracker. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30; T.C. 1A3	SA845SW	Nose gear doors. Reissued 1/24/79.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
17-30; T.C. 1A3	SA869SW	Mitchell automatic flight system AK233 consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio coupler, glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30; T.C. 1A3	SA3780WE	Installation of Continental IO-502-K engine, Hartzell HC-C3YF-1P/8468A-6R propellers, and associated installation components. Issued 11/29/78.	WE	08347	Air Repair P.O. Box 813 Santa Paula, CA 93060
17-30, -30A, -31, -31A; -31ATC; T.C. A18CE	SA903SO	Reposition of fuel pump. Issued 7/30/76.	SO	86295	Keith Wilson Aircraft, Inc. 2787 North Second Street Memphis, TN 38127
17-30A; T.C. A18CE	SA1348CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 6103
17-30A; T.C. A18CE	SA3688WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
17-30A, -31A; T.C. A18CE	SA1118SW	Manual electric trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, -31, -31ATC; T.C. A18CE	SA1195SW	Mitchell automatic flight system AS309 consisting of Century I, automatic aileron stabilizer with omni tracker. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA574SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric pitch trim and optional flight director indicator DH-841. Issued 2/1/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1235SW	Automatic flight system AK215, consisting of Century II autopilot with optional automatic aileron stabilizer and radio coupler. Issued 12/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1236SW	Automatic flight system AK233, consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio, and glide couplers. Issued 12/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1257CE	Installation of the King KFC-200 2-axis, flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or stand alone electric trim. Amended 10/6/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1811SW	Mitchell automatic flight system AK466 and AK466FD consisting of Century IV autopilot and Century IV flight director with electronic command/automatic pitch trim. Issued 2/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1812SW	Mitchell automatic flight system AK465 consisting of Century III autopilot with optional electronic command/automatic pitch trim, radio coupler, and glide slope coupler. Issued 2/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3059SW-D	Mitchell AK466 and AK466FD consisting of Century IV autopilot and Century IV flight director with electronic command/automatic pitch trim. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3060SW-D	Mitchell AK465 consisting of Century III autopilot with optional electronic command/automatic pitch trim, optional radio coupler, and glide slope coupler. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3061SW-D	Mitchell AK495 consisting of Century I autopilot with optional omni tracker. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3071SW-D	Mitchell automatic flight system AK586 consisting of Century IIB autopilot with optional radio coupler. Issued 9/5/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3083SW-D	Mitchell command electric trim AK585. Issued 12/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, -31A, -31ATC; T.C. A18CE	SA3267WE	Modification of aileron control system by addition of aileron centering spring and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 10/1/76.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BOEING COMPANY

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
B-17F, B-17G; L.T.C. 1	SA4-1088	Cargo door.	WE	34204	Fairchild Aerial Survey 2945 N. Hollywood Way Burbank, CA 91500
B-17F, B-17G; L.T.C. 1	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
B-17F, B-17G; L.T.C. 1	SA4-1520	Ceconite 101 covering of all fabric covered surfaces.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
B-17F, B-17G; L.T.C. -1	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Army) B-17F, B-17G, 377; LTC 1, T.C. 812	SA2666WE	Ceconite 102 material covering of: B-17F, B-17G – all fabric covered surfaces; 377 - ailerons, elevators and rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
377; T.C. 812	SA1-248	Radio equipment.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
377; T.C. 812	SA1-250	Incorporation of STC SA4-175 without weight increase.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
377; T.C. 812	SA1-323	Galley service door to emergency exit door.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
377; T.C. 812	SA3-34	Propeller reverse control circuit revision.	GL	61700	Northwest Airlines Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
377; T.C. 812	SA3-73	Revise Minneapolis-Honeywell turbo-supercharger control system.	GL	61700	Northwest Airlines Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
377; T.C. 812	SA4-175	Hamilton Standard 34E60/7015-2 propellers and increase in take-off and landing weights.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-384	Deterjet DJ-1015E valve between governor and nose cap mounting pad.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-416	Deterjet DJ-1015F valve between governor and nose case mounting pad.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-429	Full flow oil filter 31024A with element 1A0099.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
377; T.C. 812	SA4-709	Passenger cabin interior and weight reduction modification.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-717	Removal of No. 3 generator system and one refrigeration system.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
377; T.C. 812	SA4-842	Conversion of British Overseas Airways Corp. Boeing 377, and communications and navigation equipment changes.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
377; T.C. 812	SA29SO	Cargo loading door in upper forward section of main cabin and relocation of lower forward cargo door.	SO	47100	Opal E. Jones 274 Palm Avenue Miami, FL 33101

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
377; T.C. 812	SA473WE	Front upper spar cap and rear upper and lower spar caps reinforcement.	SO	47100	Opal E. Jones 274 Palm Avenue Miami, FL 33101
377; T.C. 812	SA501WE	Ceconite 101 covering of ailerons, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
377; 0t.c. 812	SA875WE	Cargo door added between fuselage stations 678 and 822 (left side aft of wing).	SO	47100	Opal E. Jones Box 48-625, Int'l Airport Miami, FL 33159
377; T.C. 812	SA916WE	Removal of galley door on right-hand side of fuselage between stations 1090 and 1120. Stringers extended across existing opening with additional "skin" to cover opening.	SO	47100	Opal E. Jones Box 48-625, Int'l Airport Miami, FL 33159
707 Series; T.C. 4A21	SA400EA	Installation and activation of Litton Model 502 Low Range Altimeter System. Activation of H76B Altitude Bars. Installed individually or concurrently.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21	SA420EA-D	Relocate the L.A.S.I. Flight Data Recorder to the aft fuselage area at Station 1462. Install new auxiliary pitot tube and static ports for the flight recorder.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21	SA494CE	Installation of dual doppler navigation systems with autopilot tie-in.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21	SA507CE	Installation of LAS 109C flight recorder - aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21	SA507EA-D	Install lounge and beverage bar. Install electrical wiring. Install bar and galley structural tiedowns. Install buffets.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21	SA1867SW	Portable solid oxygen system for flight attendant/passenger first-aid use. Issued 4/15/74.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
707 Series; T.C. 4A21, 4A26	SA1-345	Canadian Marconi CMA-621 doppler system.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA1-473	ADF system modification. Reissued 3/20/74.	WE	52070	Lockheed Aircraft Service Company P.O. Box 33 Ontario, CA 91761
707 Series; T.C. 4A21, 4A26	SA1-529	Crimsco cargo container 600301.	EA	62300	Pan American World Airways, Inc. 135 E. 42 Street New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA1-530	Instrument failure and warning system.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA1-651	Instrument warning system - Gables Engineering amplifier G-1010A, annuciator panels G-1080, G-1081 and G1052 warning sounder.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA3-478	Pilot's and copilot's KIFIS computers modified to make them interchangeable with each other and with the computers used on 707-331 aircraft.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA3-572	Dual Bendix DRA-12 doppler radars and dual Bendix CPA-24 computers.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA4-690	Removable flight cradle assemblies on aft side of bulkheads.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
707 Series; T.C. 4A21, 4A26	SA4-1284	Wheel 150741-5, brake assemblies 151924-2, -3, -4, -5, or -6, and hydraulic adjuster 151826 or -2.	GL	15500	Bendix Aviation Corporation Bendix Products Division 401 N. Bendix Drive South Bend, IN 46600

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707 Series; T.C. 4A21, 4A26	SA4-1418	Forward lounge.	WE	07500	AiResearch Aviation Service 6201 W. Imperial HIghway Los Angeles, CA 90045
707 Series; T.C. 4A21, 4A26	SA35EA	Brown-Line 21105-52 stretcher kit in the passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 E. 42 Street New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA45SO	Life rafts 46861-100. Amended 5/8/67.	SO	62300	Pan American World Airways, Inc. Pan American Building Miami, FL 33159
707 Series; T.C. 4A21, 4A26	SA48EA	Triple tray carrier stowage unit (auxiliary galley) in passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 E. 42 Street New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA52SO	Life rafts 6924-100.	SO	62300	Pan American World Airways, Inc. Pan American Building Miami, FL 33159
707 Series; T.C. 4A21, 4A26	SA76CE	Automatic engine power control system integrated with Safe Flight Corp. speed control approach/take-off system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA90EA	PB-20 autopilot modification.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA91EA	PB-20 autopilot modification.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA101CE	Doppler radar navigation system modification and installation of compass test receptacles.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA102CE	Coupler, Bendix DRA-12 doppler radar with CPA-24 computer to Bendix PB-20D automatic pilot.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA126EA	Unifreight Mark V Model A cargo handling system.	NE	10225	American Machine & Foundry Co. 737 Canal Street Stamford, CT 06904
707 Series; T.C. 4A21, 4A26	SA137EA	Unifreight Mark V Model B cargo handling system. (Original approval issued to American Machine & Foundry Co.)	NW	16876	The Boeing Company Renton, WA 98055
707 Series; T.C. 4A21, 4A26	SA138CE	Inflight maintenance and performance recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA146SO	Modified structure of aircraft to provide for inertial navigation system. Amended 6/19/67.	SO	62300	Pan American World Airways, Inc. Pan American Building Miami, FL 33159
707 Series; T.C. 4A21, 4A26	SA166EA	Unifreight Mark V Model C cargo handling system. (Original approval issued to American Machine & Foundry Co.)	NW	16876	The Boeing Company Renton, WA 98055
707 Series; T.C. 4A21, 4A26	SA195SO	Structural provisions to accommodate Litton navigation system.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707 Series; T.C. 4A21, 4A26	SA195CE	Autothrust system.	CE	79100	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA196CE	Autopilot modified for variable angle intercept and control panel for variable angle capture.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA198CE	Dual low range radio altimeter system provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA202CE	Modification of autopilot amplifiers and control panel to provide a variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA233CE	Coupler on Bendix DRA-12 doppler radar to Bendix PB-20D autopilot.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707 Series: T.C. 4A21, 4A26	SA237CE	Autopilot variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA242CE	Coupler on Bendix DRA-12 doppler radar with CPA-24 computer to Bendix PB-20E automatic pilot.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA247CE	Autopilot variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA248CE	Autopilot variable angle intercept. Amended 5/24/67.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA264CE	Second flight director system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA273CE	Second flight director system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA274CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA290CE	Installation of a single auto throttle system. Amended 2/20/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA290EA	Television-audio passenger entertainment system.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series: T.C. 4A21, 4A26	SA297CE	Fairchild cockpit voice recorder recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA299CE	1-70071 auto thrust servo assembly provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA304CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA305CE	Ten channel audio system provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA309EA	50-ampere transformer-rectifier.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series: T.C. 4A21, 4A26	SA313CE	Ten channel audio system provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA317SW	Magnetic shaft seal on input and output shafts of Sundstrand constant-speed-drives 40-AD-14, 40-AD-04, 40-AD-12 and 49-AD-06.	NE	54250	Magnetic Seal Corporation 166 Bay Spring Avenue West Barrington, RI 02890
707 Series: T.C. 4A21, 4A26	SA342CE	Autopilot variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA343CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA349EA	Oxygen system. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
707 Series: T.C. 4A21, 4A26	SA364EA	Pallet ID-650-4.	SO	44598	Irving Air Chute Company, Inc. 1315 Versailles Road Lexington, KY 40507
707 Series: T.C. 4A21, 4A26	SA365CE	Ten channel audio system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series: T.C. 4A21, 4A26	SA366CE	Fairchild cockpit voice recorder system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707 Series; T.C. 4A21, 4A26	SA375CE	Autopilot amplifiers modified to incorporate variable angle intercept feature. Amended 5/24/67.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA376EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA376CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA378EA	Dual Sperry SGN-10-2 inertial navigation systems.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA379EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways, Inc. Hangar #14 JFK International Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA381CE	Fairchild cockpit voice recorder equipment. Amended 4/27/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA389CE	Eclipse-Pioneer 15470, 15492 and 18729 autopilot amplifier.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA390CE	Eclipse-Pioneer 18729 autopilot amplifier.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA402EA	Single pressure operated check valve in hydraulic lines.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA404EA	Extended over water operation.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA406EA	19-man configuration.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA425CE	Installation of an auto thrust system. Amended 1/31/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA428CE	Installation of a single SCAT system. Amended 4/21/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA429CE	Installation of an auto thrust system. Amended 4/21/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA430CE	Passenger motion picture and tape player equipment.	EA	44000	InFlight Motion Pictures, Inc. 10 Rockefeller Plaza New York, NY 10001
707 Series; T.C. 4A21, 4A26	SA435CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA436CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA437CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA439EA	Inertial navigation system.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA443EA	Litton 502 low range altimeter system.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A21, 4A26	SA454EA	Crew galley. Amended 5/2/67.	EA	67030	REF Dynamics Corporation 393 Jericho Turnpike Mineola, NY 11501
707 Series; T.C. 4A21, 4A26	SA467CE	Safe Flight Corp. auto power servo kit K-102.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707 Series; T.C. 4A21, 4A26	SA726WE	Revise interior configurations.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707 Series; T.C. 4A21, 4A26	SA757WE	Three-class passenger interior.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA784CE	Installation of Bendix standby horizon indicator. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A21, 4A26	SA847WE	Replace two rows of economy class seats with two rows of coach seats.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA972WE	Install one additional row of tourist triple class seats and remove one row of first class seats (without lounge).	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1057WE	Interior modification.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1110WE	Seating arrangement revised.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1151WE	Dual Collins AL-101 or dual Litton 502 low range radio altimeter. Amended 7/22/66.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1152WE	Stowage compartment in main deck cargo compartment.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
707 Series; T.C. 4A21, 4A26	SA1176WE	Interior arrangements.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
707 Series; T.C. 4A21, 4A26	SA1217WE	Cockpit voice recorder system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 Series; T.C. 4A21, 4A26	SA1224WE	Dual FD-109 flight director systems, dual low range radio altimeters, wiring provision, DME and navigation switching.	SW	24252	Collins Radio Company Avionics Systems Center P.O. Box 98 Addison, TX 75001
707 Series; T.C. 4A21, 4A26	SA1229WE	United Data Control V557 cockpit voice recorder.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
707 Series; T.C. 4A21, 4A26	SA1279WE	In-flight entertainment system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
707 Series; T.C. 4A21, 4A26	SA419EA-D	Install vertical remote accelerometer and adapter harness to permit interchangeable use with a modified or unmodified flight recorder in the existing location. Amended 9/8/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA200EA	Installation of SCAT and Auto Thrust Systems.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A26	SA423EA-D	Installation of Dorne and Margolin VHF antenna, DMA 33-2.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA492EA	Installation of Autonetics Air Turbulence Detection System.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A26	SA497CE	Installation of LAS 109CR flight recorder - aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A26	SA498CE	Installation of LAS 109CR flight recorder - aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A26	SA499CE	Installation of LAS 109CR flight recorder - aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707 Series; T.C. 4A26	SA510EA-D	Installation of passenger seats and interior arrangement.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA511CE	Autopilot variable angle intercept installation. Amended 7/1/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707 Series; T.C. 4A26	SA511EA-D	Modification of life raft overhead stovage compartment.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA513EA-D	Install water tank assembly in forward baggage compartment.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
707 Series; T.C. 4A26	SA533EA	Installation of Dual Bendix DRA-12 Doppler and CPA-24 Computer Systems. Relocation of existing EDO Loran System to Cockpit Pedestal Area. Amended 11/27/67.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707 Series; T.C. 4A26	SA1424WE	Installation of REA Express 7 Arts Transvision Inflight Motion Picture System.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
707 Series; T.C. 4A26	SA1442WE	Installation of inflight motion picture projection system.	WE	25917	Consolidated Electrodynamics Corp. 360 Sierra Madre Villa Pasadena, CA 91100
707 Series; T.C. 4A26	SA1499WE	Installation of Class Partition Assembly System.	EA	62300	Pan American World Airways, Inc. 200 Park Avenue New York, NY 10017
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA4-1559	Preloaded aluminum baggage container and base fabricated.	WE	36180	John Bean Division of Food Machinery & Chemical Corp. 1115 Coleman Avenue San Jose, CA 95125
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA166SO	Low range radar altimeter system.	SO	62300	Pan American World Airways, Inc. Pan American Building Miami, FL 33159
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA183EA	Mansfield aft and forward bar units in passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 E. 42 Street New York, NY 10001
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA240SW	Seat loaded cargo containers.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA402SW	Dual Collins FD-108 flight director system.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA509EA	Install a standby horizon system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720 Series; T.C. 4A21, 4A26, 4A28	SA516EA-D	Install 30 cps chokes in Bendix Course Indicator P/N 7236.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA734WE	Closed-circuit television and stereo system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA1128WE	Cockpit voice recorder.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA1221WE	Dual Collins AL-101 low range radio altimeter. Amended 12/29/66.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707, 720; T.C. 4A21, 4A26, 4A28	SA1281WE	Fire detector system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707 and 720 airplanes equipped with Boeing P/N 65-11685 and 65-68862 forward thrust reverser doors; T.C. 4A21, 4A26, 4A28	SA1388CE	Replace magnesium or aluminum forward thrust reverser blocker doors with nylon doors. Issued 12/8/77.	CE	65330	Progressive Manufacturing Co. 1101 S. Ninth Street Kansas City, KS 66105
707, 720 Series; T.C. 4A21, 4A28	SA502EA-D	Install a triple class cabin divider to partition the area between the economy and coach passengers. Amended 11/17/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707/720; T.C. 4A26, 4A28	SA2163WE	Installation of door mounted emergency light. Amended 9/28/70.	WE	44266	International Inflatables Company Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
707/720; T.C. 4A26, 4A28	SA2281WE	Installation of pneumatic butterfly-shutoff valve, P/N 397794-1-1. Issued 12/7/70.	WE	07502	AiResearch Manufacturing Company 402 South 36th Street Phoenix, AZ 85034
707/720; T.C. 4A26, 4A28	SA2282WE	Installation of fluid pressure regulating valve, P/N 898304-1-1. Issued 12/7/71.	WE	07502	AiResearch Manufacturing Company 402 South 36th Street Phoenix, AZ 85034
707/720; T.C. 4A26, 4A28	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans AVenue San Francisco, CA 94124
707, 720 Series; T.C. 4A21, 4A28	SA2637WE	Installation of aft thrust reverser lower latch hook bearings. Issued 1/3/73.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85281
707, 720, 727, 737; T.C. 4A21, 4A26, A3WE, A16WE, 4A28	SA2728WE	Incorporation of HI-LITE SYSTEM P/N 50-1001 for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation 857 Thornton Street San Leandro, CA 94577
707, 727; T.C. 4A26, A3WE	SA2451SW	Marathon Battery Co. part 85-0050 six cell magnesium emergency light pack. Issued 4/20/77.	SW	54810	Marathon Battery Company 8301 Imperial Drive Waco, TX 76710
707, 727; T.C. 4A26, A3WE	SA481EA	Installation of pallet nets. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707; 727; 737; T.C. 4A21, 4A26, 4A28, A3WE, A16WE	SA863EA	Incorporation of DME Corporation emergency evacuation slide lighting system, Model ESL-1, -6, -6-1. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707, 727, 747, 747SP; T.C. 4A26, A3WE, A2WE	SA1967SW	Model ID-8 liquor dispenser. Issued 4/4/75.	SW	16896	Booth, Inc. 1725 Bandy Lake Road Carrollton, TX 75006
707-100, -100B, -200; T.C. 4A21	SA172GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	GL	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
707-100, -100B, -200; T.C. 4A21	SA719CE	Installation of Kollsman altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City International Airport Kansas City, MO 64153
707-100 long body, -100B long body, -100B short body, -200; T.C. 4A21	SA3712WE	Installation of a 40" x 56" adjustable height, folding leaf table. Issued 8/17/78.	WE	28125	Custom Products Company 11626 Tuxford Street Sun Valley, CA 91352
707-100 long body, -100B long body, -100B short body, -200; T.C. 4A21	SA3713WE	Installation of a 40" x 67.25" adjustable height, folding leaf table. Issued 8/17/78.	WE	28125	Custom Products Company 11626 Tuxford Street Sun Valley, CA 91352
707-100, -100B, -200; T.C. 4A21	SA3756WE	Installation of stretcher carrier, P/N AM2003. Issued 10/11/78.	WE	08205	Air Medica, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
707-100, -100B (short-body); T.C. 4A21	SA4025SW	Structural provisions of mid-lavatory service pan. Issued 7/27/79.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
707-100, -200, -300, 720; T.C. 4A21, 4A26, 4A28	SA2EA	Replacement of universal type drive shaft P/N 204679 with Bendix flexible drive shaft model 19E40-1B between the P&W J3C or JT4A series engine mounted gearbox and Sundstrand constant speed drive. Amended 7/23/75.	EA	16000	Bendix Fluid Power Division The Bendix Corporation 211 Seward Avenue Utica, NY 13503

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-100, -100B Long Body, -100B Short Body, -200; 707-300, -400, -300B, -300C; 720, 720B; 727, 727C, 727-200; 737-100, -200, -200C; 747-100, -200B, -200F; T.C. 4A21, 4A26, 4A28, A3WE, A16WE, A20WE	SA10GL	Installation of Gayston Model 800'G and 800SG static dischargers on transport category airplanes. Issued 12/15/72.	GL	37125	Gayston Corporation 55 Janney Road Dayton, OH 45404
707-100, -200; 707-300; 720; 727, 727C, -200; 737; T.C. 4A21, 4A26, 4A28, A3WE, 4A27	SA2534SW-D	Replacement of Switch assembly International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707-100, -200; 707-300; 720; 727, 727C, 727-200; 737; T.C. 4A21, 4A26, 4A28, A3WE, A16WE	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with D4F Corp. EL-104, EL-104A, and EL-104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
707-100, -100B, -200, -300, -400, 720, 720B; T.C. 4A21, 4A26, 4A28	SA2579WE	Modify airplanes by the installation of wing tip mounted emblem light. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
707-100/100B, -200, -300/300B/300C, 720/720B; T.C. 4A21, 4A26, 4A28	SA2605WE	Installation of turbine thrust reverser linkage. Amended 9/2/73.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
707-100B; T.C. 4A21	SA984CE-D	Increase maximum zero fuel weight. Issued 9/22/76.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-100B; T.C. 4A21	SA4140SW	Steward-Davis Model 81000 auxiliary power system. Issued 7/2/80.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
707-100B, -300B, 720; T.C. 4A21, 4A26, 4A28	SA2635WE	Installation of forward fan thrust reverser bearings. Issued 1/11/73.	WE	79750	Triumph Corporation 2130 South Industrial Park Avenue Tempe, AZ 85282
707-121, -139, -321, -321B, -331, -321C, 720-023B, -030B; T.C. 4A21, 4A28	SA311EA	Installation of Aerotherm Corp. Model 1003 stretcher. Reissued 12/5/72.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-121, -139, -321, -321B, -321C, -331, 720-023B, -030B, 737-100, -200; T.C. 4A21, 4A26, 4A28, A16WE	SA677CE	Installation of Crimsco cargo container, P/N 600301, in passenger compartment. Amended December 1974.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
707-121B Series; T.C. 4A21	SA531EA	Installation of EMCO autopilot monitoring system Model No. APMS-S. Amended 9/27/68.	EA	62300	Pan American World Airways, Inc. Hangar #14, JFK Int'l Airport Jamaica, NY 11430
707-121B, -123B, -139B, -227, -321, -321B, -321C, -323C, -327C, -331, -123, -155C, -295; 720-023B, -027, -030B, -048, -062, 727-21C, -21, -27, -27C, -81, -90C, -95; T.C. 4A28, 4A21, 4A26, A3WE, 4A25	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 12/10/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-121B, -139B; T.C. 4A21	ST655SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in forward passenger compartment.	SO	67030	Mace Unit of REF Dynamics, UOP 5846 Victor Street Jacksonville, FL 32207
707-121B, -139B; 707-321, -321B, -321C, -331; 720-023B, -030B; 727-21, -21C; 747-121; T.C. 4A21, 4A26, 4A28, A3WE, A20WE	ST706SO-D	Installation of Skydrol 500C hydraulic fluid. Reissued 9/7/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-121B, -139B; 707-321, -321B, -321C, -331; 720-023B, -030B; T.C. 4A21, 4A26, 4A28	ST708SO-D	Installation of an REF Dynamics carry-on baggage compartment. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-121B, -139B; 707-321, -321B, -321C; 707-331; 720-023B, -030B; T.C. 4A21, 4A26, 4A28	ST711SO-D	Installation of door mounted evacuation slide illumination lights. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-123B; T.C. 4A21	SA405EA-D	Convert all Boeing 707-123B aircraft to winter configuration. Amended 10/10/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 707-323B, 707-323C; T.C. 4A21, 4A26	SA401EA-D	Installation of door mounted evacuation slides on forward and aft entry doors and forward and aft galley service doors. Amended 9/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 707-323B and 707-323C: T.C. 4A21, 4A26	SA415EA-D	Installation of Bell & Howell projection system in 707-123B, install Bell & Howell projection system in 707-323C, install Bell & Howell projection system in 707-323B. Amended 4/21/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, 720B-023; T.C. 4A21, 4A28	SA551EA-D	Installation of autopilot go-around unit. Amended 8/11/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, -323C, -323B, 720-023B, 727-23, -35, -95, -123, -223; T.C. A3WE, 4A28, 4A21	SA554EA-D	Install underseat luggage retention device.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B, -138, -323CC, -023B; T.C. 4A21, 4A26, 4A28	SA555EA-D	To comply with FAR 25.812(e), a lever lock switch will be installed at a point accessible to the forward flight attendant seat. Amended 4/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-123B; T.C. 4A21	SA983CE-D	Cargo door and interior installation non-convertible air freighter. Issued 5/24/76.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-123B; T.C. 4A21	SA4053WE	Installation of an auxiliary fuel tank system consiting of two identical tank assemblies located in the forward cargo compartment and one located in the aft cargo compartment. Issued 10/30/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
707-123B, -138B; T.C. 4A21	SA3257WE	Installation of AiResearch GTCP 85-98CK auxiliary power unit in forward cargo compartment. Amended 8/18/78.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-123B, 707-138B; T.C. 4A21	SA3441WE	Installation of airstairs. Amended 3/15/79.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
707-124 Series; T.C. 4A21	SA582CE	Relocation of Lockheed Aircraft Service Model 109CP, flight recorder to aft location.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA584CE	Autopilot modification to incorporate variable intercept feature.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA585CE	Installation of Fairchild Cockpit Voice Recorder System.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA586CE	Installation of Fenwall fuel vent surge tank protection system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124 Series; T.C. 4A21	SA627CE	Installation of (1) dual radio altimeter provisions (2) single Bendix ALA-51 radio altimeter transmitter-receiver with dual indicators.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131; T.C. 4A21	SA439CE	Installation of logo lights on horizontal stabilizer. Amended 11/25/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131; T.C. 4A21	SA556CE	Installation of auto-thrust provisions. Amended 3/19/69.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-124/-131/-131B; 707-331/-331B/-331C/ -373; T.C. 4A21, 4A26	SA577CE	Replace Bendix type 15866, 15897 and 19903 vertical gyros with Bendix type 19911 or 19912 vertical gyros.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, 131, -131B- -331, -331B, -373C, -338C; T.C. 4A21, 4A26	SA680CE	Modify the A.C. essential bus power source circuitry to provide automatic transfer. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-124, -131, -131B, -331, -331B, -331C; T.C. 4A21, 4A26	SA682CE	Install Litton Model F-30 microwave oven.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131; T.C. 4A21	SA555CE	Installation of a single SCAT system. Amended 3/19/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131; T.C. 4A21	SA862CE	Addition of large cargo door in left hand side of fuselage. Issued August 1972.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-131, -131B; T.C. 4A21	SA607CE	Installation of provisions for dual radio altimeters and single Bendix Model ALA-51A equipment. Amended 4/29/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131, -131B, 331, 331B, 331C; T.C. 4A21, 4A26	SA3-708	Install motion picture projector and screen. Amended 12/27/67.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
707-131, -131B, 720B; T.C. 4A21, 4A28	SA432CE	Installation of Fenwall fuel vent surge tank protection system. Amended 8/22/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA197CE	Installation of a single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
707-131B; T.C. 4A21	SA298CE	Installation of a single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA488CE	Relocation of LAS Model 109CR flight recorder.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA1052CE	Replacement of existing fire detection system with a Kidde dual loop fire detection system. Issued September 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B; T.C. 4A21	SA1520CE	Installation of a Growth Industries dual cavity oven. Issued 10/31/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-131B, -331B, 331, 331C, 373, 338C; T.C. 4A21, 4A26	SA519CE	Installation of logo lights in horizontal stabilizer. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-131/-131B/-331/ -331B/-331C/-373C, 338; T.C. 4A21, 4A27	SA827CE	Install Butler National Corp. flight recorder/communications interface unit. Amended April 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-131B, -331B, -331C; T.C. 4A26	SA1478CE	Installation of pitot heater failure indication system. Issued 3/22/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-138B; T.C. 4A21	SA797EA	Installation of inflight motion picture system. Reissued 2/26/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-138B; T.C. 4A21	SA1132EA	Installation of two Solar Model T-62T-40C2 APU's for ground use only. Amended 11/8/79.	EA	63275	PATS, Inc. 7190-8 Oakland MIlls Road Columbia, MD 21046
707-138B; T.C. 4A21	SA1136EA	Installation of an onboard passenger loading stairs. Amended 12/14/78.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
707-138B; T.C. 4A21	SA1403WE	Interior arrangements.	NW	74920	Standard Airways, Inc. Tower Building Seventh and Olive Streets Seattle, WA 98101
707-138B; T.C. 4A21	SA3320WE	Installation of radio altimeter system No. 1. Issued 1/17/77.	WE	13970	Aviation Service & Support Corp. 4150 Donald Douglas Drive Long Beach, CA 90801

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-139B Series; T.C. 4A21	SA687EA	Installation of Data Link System.	EA	62300	Pan American World Airways, Inc. JFK International Airport Hangar 17 - Room 2011 Jamaica, NY 11430
707-139B, -121B, 720-023B, -030B; T.C. 4A21, 4A28	SA1937WE	Installation of under-seat baggage restraint system. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-153B; T.C. 4A21	SA91SW	Minor modifications to pilot's instrument panel and relocation of autopilot accelerometer and rate gyros for improved performance. Amended 12/7/73.	SW	24252	Collins Radio Company Avionics Systems Center P.O. Box 98 Addison, TX 75001
707-153B; T.C. 4A21	SA856EA	Installation of a compartment bulkhead at fuselage station 978. Issued 12/22/70.	EA	80910	Department of the Air Force Hq. 89th Military Airlift Wing (SM) MAC Andrews Air Force Base Washington, D.C. 20331
707-153B; T.C. 4A21	SA1700WE	Installation of Dual Litton LTN-51 Inertial Navigation Systems. Amended 10/21/68.	WE	51500	Litton Systems, Inc. Guidance & Control Systems Div. 5500 Canoga Avenue Woodland Hills, CA 91364
707-153B, -353B; T.C. 4A21, 4A26	SA350EA	Passenger Berth Installations. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Company P.O. Box 33 Ontario, CA 91761
707-153B, -353B; T.C. 4A21, 4A26	SA648EA	Modification of Collins FD109G Flight Director.	EA	80910	Department of the Air Force Hq. 89th Military Wing (SM) MAC Andrews Air Force Base Washington, D.C. 20331
707-153B, -353B; T.C. 4A21, 4A26	SA858EA	Modification of rigid high pressure starter air lines on numbers 2 and 3 engines. Issued 12/29/70.	EA	80910	Department of the Air Force Hq. 89th Military Airlift Wing (SM) MAC Andrews Air Force Base Washington, D.C. 20331
707-200, -300, -400; T.C. 4A21	SA1155SO	Installation of cargo floor, cargo restraint bulkhead, landing gear position indicator, and smoke detection system (Class "E" cargo compartment). Amended 7/24/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
707-227, 720-027; T.C. 4A21, 4A28	SA1138WE	Installation of fire warning monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Deering Canoga Park, CA 91304
707-300; T.C. 4A26	SA208NW	Installation of Fairchild Stan (P) weight and balance system. Issued 10/21/75.	NW	08350	Air Repair, Inc. 811 West Perimeter Road Renton, WA 98055
707-300 Series; T.C. 4A26	SA3599WE	Installation of single or dual Litton LTN-201 Omega navigation as a means to update INS or doppler in the NAT MNPS airspace. Amended 5/8/78.	WE	51500	Litton Aero Products Division 6700 Eaton Avenue Canoga Park, CA 91303
707-300, -300B, -300C, -400; T.C. 4A26	SA171GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	GL	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
707-300, -300B, -300C, -400 Series; T.C. 4A26	ST661SO	Installation of dual band "C/X" type weather radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Company P.O. Box 350 Akron, OH 44309
707-300, -300B, -300C, -400 Series; T.C. 4A26	SA3167WE	Installation of dual Litton LTN-51 inertial navigation systems. Issued 4/5/76.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
707-300, -300B, -300C, -400, 338C; T.C. 4A26	SA726CE	Installation of Kollsman altitude alerting system. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-300, -300B, -300C, 707-400 Series; T.C. 4A26	SA3486WE	Installation of dual Litton LTN-51, or dual Litton LTN-72, or one Litton LTN-72 inertial navigation systems. Issued 11/3/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91364
707-300, -300B, -300C, -400; T.C. 4A26	SA3830WE	Installation of dual Delco C-IVA inertial navigation system. Amended 10/17/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-300, -300B, -300C; T.C. 4A26	SA4097WE	Installation of forward entrance airstair. Issued 2/5/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanover Street Van Nuys, CA 91406
707-300, -400; T.C. 4A26	SA3331WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
707-300, -400; T.C. 4A26	SA4156SW	Aft airstair. Issued 7/25/80.	SW	43005	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
707-300B, -300C; T.C. 4A26	SA817NW	Modification of cabin passenger interior, and forward storage units. Issued 8/8/79.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
707-300B, -300C; T.C. 4A26	SA2594WE	Modify 707-300B and -300C series airplanes by the installation of wing tip mounted emblem light. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
707-300B, -300C; T.C. 4A26	SA2610WE	Installation of Bell & Howell movie projection system Nos. 478441 and 478440. Issued 1/11/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
707-300C, 727C; T.C. 4A26, A3WE	SA647SO	Installation of AIF partition class divider P/Ns 402-1, 402-2, 402-3, 402-4, and header assembly P/Ns 403-1 and 404-1. Amended 7/16/68.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33142
707-300C Series; T.C. 4A26	ST939SO	Installation of livestock pen. Issued 6/10/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-300C Series; T.C. 4A26	SA1443WE	Installation of tray carrier.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-320; T.C. 4A26	SA2374WE	Installation of an air filter to the cabin pressure limit control outflow safety valve, P/N 103430-3. Issued 6/24/71.	WE	07505	AiResearch Manufacturing Company 2525 W. 190th Street Torrance, CA 90509
707-320C; T.C. 4A26	SA251NW	Installation of cargo system. Issued 1/16/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
707-320C Series; T.C. 4A26	SA3539WE	Installation of single, palletized Litton LTN-51 or LTN-72 inertial navigation system. Issued 12/20/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
707-321; T.C. 4A26	ST710SO-D	Relocation of "B" galley approximately 10" forward of present location. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321; T.C. 4A26	SA778CE	Addition of large cargo door in left hand side of fuselage. Issued June 1971.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA852CE-D	Reduction of empty weight by removal of all passenger interior equipment and installation of fire resistant lining. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA1555WE	Installation of fire warning electrical monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Canoga Park, CA 91304
707-321, -321B; T.C. 4A26	SA344EA	Install inertial navigation system. Amended 4/1/66.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321, -321B, -321C, -331, -386C; T.C. 4A26	ST652SO-D	Installation of P&W JT8D engine and associated structural and fairing pod under L.H. wing between No. 2 engine and fuselage. Reissued 9/7/78.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
707-321, -321B, -331; T.C. 4A26	ST656SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in the forward passenger compartment. Amended 11/6/68.	SO	67030	Mace Unit of R&F Dynamics, UOP 4856 Victor Street Jacksonville, FL 32207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-321, -321B, -321C, -331; T.C. 4A26	ST712SO-D	Modification and installation of a Hardman Model 6747 seat. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321, -324C; T.C. 4A26	SA2238WE	Installation of Brownline Cargo net assembly #41412 used in conjunction with Brownline pallet assemblies #40160 and 40144. Amended 5/16/75.	WE	17740	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321, -331, 720-040B; T.C. 4A26, 4A28	SA1-593	See Document No. Report No. 3078, dated January 30, 1969, concerning pallet assembly IR-3000 Rev. B. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-321, -400; T.C. 4A26	ST914SO	Installation of cargo floor. Amended 1/19/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-321B; T.C. 4A26	SA611EA	Installation of dual A.C. electronics navigation systems on P/N N435PA, S/N 5034. Amended 5/21/68.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B; T.C. 4A26	ST702SO-D	Installation of Bendix FINDS. Limited to aircraft N421PA S/N 19266. Issued 11/15/68.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST707SO-D	Modified aircraft to incorporate Emerson engine performance monitoring system, aircraft S/N 19363, N428PA. Issued 10/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST713SO-D	Installation of a coat closet between fuselage stations 373 and 414 L.H. side. Reissued 9/12/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B; T.C. 4A26	SA1067EA	Installation of stowage cabinets Issued 12/16/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
707-321B; T.C. 4A26	SA3549WE	Installation of Garrett GTCP85-98CK auxiliary power unit in forward baggage compartment. Issued 1/27/78.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-321B, 321C; T.C. 4A26	ST709SO-D	Installation of flight spares container in right hand main landing gear wheel well on fuselage station 960 bulkhead. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	SA700EA	Switches are installed on outboard thrust levers to disengage autothrottle system.	EA	62300	Pan American World Airways, Inc. Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	ST704SO-D	Installation of Bell & Howell forward projection movie system. Reissued 9/7/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321-B, -321C; T.C. 4A26	SA1076EA-D	Removal of Loran navigation system and installation of dual Omega navigation systems for updating doppler. Amended 8/13/79,	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321C; T.C. 4A26	SA581NW	Installation of quick change interior. Issued 1/18/78.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98021
707-321C; T.C. 4A26	SA1134WE	Palletized cargo system installation 65-42629 or 65-43629 with Brownline pallet 22630-51, 26100-51 or -52 and Brownline net assy 23225-51, 23226-51, or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1143WE	Installation of Boeing palletized cargo system. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1293WE	Palletized cargo system installation 65-42629 with Brownline pallet 22630-51 and net assy 23225-51 or 23226-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-321C; T.C. 4A26	SA1597WE	Installation of Heath Tecna Corporation pallet AC-10065 and Brownline Corporation Net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C; T.C. 4A26	SA2125WE	Installation of Ancra Cargo Net Assembly 40234-10 used in conjunction with either Brownline pallet assembly 22630-51 or Heath Tecna pallet assembly AC 10065-1.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 90245
707-321C; T.C. 4A26	SA2221WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp Net Assembly 40234-10 and net assemblies approved to NAS 3610-2A1N and NAS 3610-2A3N. Issued 8/19/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
707-321C; T.C. 4A26	SA3005WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-321C, 727-21C; T.C. 4A26, A3WE	SA736EA	Installation of I. Marino forward cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-321C, 727-21C; T.C. 4A26, A3WE	SA1859WE	Installation of net assembly AC-10292-1 used in conjunction with pallet assembly AC-10065-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C, 727-21C; T.C. 4A26, A3WE	SA2045WE	Modification by installation of pallet assembly 40160 used in conjunction with net assemblies 23225-51, 23226-51, 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; 727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA849EA	Goodyear Aerospace Corporation cargo pallet (1.5 Fwd.) P/N 634A303-001-101 is eligible to be used only in combination(s) as shown in the following tables:	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315

BOEING COMPANY			CARGO NET	
AIRPLANE MODEL	CARGO RESTRAINT SYSTEM	WEIGHT & BALANCE CONTROL MANUAL (b)	MANUFACTURER & PART NO.	TIE-DOWN CONFIGURATION
707-321C (a)	65-42629 65-43629	D6-14083.6	Brownline 40510-101 22758-51 23225-51	88" x 125"
			Marino LM1500-100	88" x 125"
			Brownline 21970-51 (Chg. G)	88" x 108"
727-21C (a)	65-49102	D6-21000.17C	Brownline 40510-101 22758-51 23225-51 23226-51	88" x 125"
			Marino LM1500-100	88" x 125"
			Brownline 21970-51 (Chg. G)	88" x 108"
747-121	65B-60060 Lower Lobe Compartment Aft Hold ONLY	D6-13700	Brownline 22758-51	88" x 125"

(a) Barrier Net Installation per Boeing Drawing 65-34700-1 required for these model aircraft with this installation.

(b) The applicable Boeing Weight and Balance Control Manual must be used to obtain permissible compartment load, under conditions described therein, not to exceed the pallet-net combination(s) capacity of 13,300 lb. for the 88" x 125" tie down configuration or 8000 lb. for the 88" x 108" tie down configuration.

707-321C;727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA1902WE	Installation of Irvin cargo pallet assembly 125014 used in conjunction with net assembly 22758-51 (Brownline), net assembly 40234010 (ANCRA), and net assembly LMI-500-100 (Marino). Amended 8/25/70.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-321C, 727-21C; T.C. 4A26, A3WE	SA2103WE	Installation of Net Assembly 40510-101 used in conjunction with Brownline Pallet Assemblies 40160-101 thru -100, 22630-51 and Heath Pallet AC-10065-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323, 707-385C; 707-323B; T.C. 4A26	SA517EA-D	Installation of dual Litton LTN-51 inertial navigation systems. Install No. 2 ship's battery (24 volts, 36 AH) to provide standby DC power for No. 2 inertial navigation system. Installation perforated filler panels fore and aft of both control/display units. Amended 1/22/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA556EA-D	Convert interior passenger arrangement to winter configuration of 4 first class lounge, 32 first class seats and 101 tourist class seats. Amended	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA561EA-D	Installation of automatic throttle/speed control system. Amended 3/2/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA562EA-D	Installation of dual aileron and elevator surface servos to operate in a single servo configuration with the PB20 autopilot system. Amended 3/31/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA564EA-D	Modify the interior arrangement of the 707-323B aircraft from its present configuration to 32 F/C plus 102 T/C passenger. Install additional meal stowage. Issued 5/18/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA508EA-D	Install a single inertial navigation system (LTN-51E). Amended 1/5/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74116
707-323C; T.C. 4A26	SA525EA-D	Convert interior passenger arrangement to the summer configuration of four first class lounge, 26 first class, and 113 tourist class seats. Amended 4/15/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA559EA-D	Interior arrangement and configuration.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA565EA-D	Install emergency evacuation slide lights for station 930. Issued 6/17/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA1560WE	Installation of Aeronca cargo containers on Boeing 707-323C.	WE	02398	Aeronca, Inc. Aerocal Division 24751 S. Crenshaw Boulevard Torrance, CA 90505
707-323C; T.C. 4A26	SA1720WE	Installation of Heath Tecna structural igloo assembly AC-0123. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2008WE	Installation of structural cargo container AC-10260-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2401WE	Installation of Transequip structural igloo assembly P/N 245084 in conjunction with loading systems 65-42625, 65-42630, and 64-34899. Issued 8/26/71.	WE	79000	Transequip, Inc. 5438 W. 104th Street Los Angeles, CA 90045
707-323C; T.C. 4A26	SA2453WE	Installation of Transequip structural containers in position I13 (container 235111) and position I14 (container 235112). Amended 10/30/79.	WE	79000	Transequip, Inc. 5438 West 104th Street Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2022WE	Installation of pallet assembly 40122-101, -102, -103, -104, and -105 used in conjunction with net assemblies 22178-51, 23652-51, 22361-51c, 22780-51, 22780-52, 22656-51, 22656-52, and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2174WE	Installation of pallet assembly 40550-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22362-51 or AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -331C, 373C, 385C; 727-31C, -180C; T.C. 4A26, A3WE	SA1924WE	Installation of Irvin cargo pallet assembly 125001-501, -503, -505, -507 used in conjunction with net assembly 10-60934-1 (Boeing).	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
707-323C, -331C, -373C, 727-1A7C, -31C, -180C; T.C. 4A26, A3WE	SA2098WE	Installation of structural cargo container 40619-101, -103. Amended 5/16/75.	WE	17740	Brooks & Perkins 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA945WE	Installation of autopilot go-around unit. Amended 8/1/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C and 707-385C; T.C. 4A26	SA1524WE	Brownline Structural Containers 23885-51 may be used as optional cargo equipment either in place of or with cargo net assemblies. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA1939WE	Modify by installation of structural cargo container 24385-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA2234WE	Installation of Brownline Division structural container No. 41342-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -385C; 727-22C; T.C. 4A26	SA2278WE	Installation of Brownline cargo container model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division Torrance, CA 90505
707-326C; T.C. 4A26	ST701SO-D	Installation of alternate inertial navigation system control display unit. Limited to aircraft N870PA, S/N 20016; N871PA, S/N 20017; N872PA, S/N 20018. Amended 6/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-327C; T.C. 4A26	SA739EA	Installation of Inflight Motion Picture System. Reissued 10/24/73.	EA	11434	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-327C, -330C, -338C, -351C, 727-25C, -27C, -30C, -51C, -62C; T.C. 4A26, A3WE	SA2026WE	Installation of pallet assembly 40134-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22364-51, 23215-51, 23618-51 or 23783-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-327C; T.C. 4A21	SA2748WE	Installation of weight and balance computer system. Issued 8/15/73.	WE	52010	Lockheed Aircraft Service Company Ontario International Airport P.O. Box 33 Ontario, CA 91764
707-330C, 727-30C; T.C. A3WE	SA1917WE	The type design change consists of installation of pallet assembly 24076-51 in conjunction with net assembly 22361-51, 22364-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-331; T.C. 4A26	SA428CE	Installation of single seat system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA489CE	Relocation of Lockheed Air Service Model 109CP flight recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-331; T.C. 4A26	SA635CE	Installation of dual radio altimeter system provisions and single radio altimeter equipment. Amended 2/20/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA854CE-D	60,000 lbs. main deck allowable loading. Issued 12/7/73.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-331; T.C. 4A26	SA1551WE	Installation of fire warning monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Conoga Park, CA 91304
707-331, 707-331 (ADV); T.C. 4A26	SA291CE	Installation of single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331, -331B, -331C, -373C, -338C; T.C. 4A26	SA465CE	Installation of Fenwall fuel vent surge tank. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64108
707-331 (Advanced), -331C, -338C, -373C; T.C. 4A26	SA899CE	To permit autopilot coupled approaches at 40 degrees flo setting below 500 feet. Issued August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331, -331B, -331B(ADV), -331C, -373C; T.C. 4A26	SA1327CE	Installation of Bendix ONS-25-5 Omega navigation system for updating primary self-contained navigation system. Issued March 1977.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195
707-331, -373C, 727-31A, -180C; T.C. 4A26, A3WE	SA2290WE	Installation of Ancra pallet net assembly P/N 40452-10 used in conjunction with Boeing 9g pallet assemblies (88" x 125") numbers 10-60935-1, 10-60935-11, 10-60935-17, 10-60935-21, 10-60935-27 and 10-60935-37. Amended 2/22/71.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 990245
707-331B, -331C; T.C. 4A26	SA1518CE	Installation of a Growth Industries dual cavity oven. Issued 10/18/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-331B, -331C, -338C, -373; T.C. 4A26	SA1039CE	Replacement of existing fire detection system with a Kidde dual loop fire detection system. Issued September 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C; T.C. 4A26	SA523CE	Installation of single SCAT system. Amended 7/31/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C; T.C. 4A26	SA524CE	Installation of auto throttle system. Amended 7/1/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, Mo 64153
707-331C; T.C. 4A26	SA658CE	Installation of dual radio altimeter provisions single equipment.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331 (Convertible), 707-338C; T.C. 4A26	SA234CE	Autopilot variable angle intercept installation. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C, -338C; T.C. 4A26	SA385CE	Installation of single SCAT system. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C, -338C; T.C. 4A26	SA386CE	Installation of auto thrust system. Amended 8/7/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C, -373C, -338C; T.C. 4A26	SA783CE	Installation of revised life raft and courier seat provisions. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA757GL	Goodyear Aerospace Corporation Cargo pallet with barrier net installation. Amended 3/17/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massilon Road Akron, OH 44315
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1866NW	Installation of Heathair AC-10113-1 net assembly in conjunction with pallet assemblies AC-10070-1 and AC-10347-1. Reissued 1/6/71.	NW	41625	Heath Techna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1963WE	Installation of pallet assembly 23250-52 used in conjunction with net assemblies 22178-51, 22780-52, 22656-51, 22656-52 and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2172WE	Installation of Irvin Industries Net Assembly 120012-501 used in conjunction with Cargo Pallet 125001-501, -503, -505, -507. Issued 8/19/70.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2412WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, 727-31C; T.C. 4A26, A3WE	SA2088WE	Installation of cargo pallet assemblies 1950-90-501 and 1950-90-1001 used in conjunction with net assembly 22758-51 (Brownline).	WE	19890	Cargo Systems, Inc. 1040 West Hoover Street Orange, CA 92667
707-338C; T.C. 4A26	SA730EA	9G 10,000 lb. maximum capacity Pallet Cargo Net P/N LM 1505-1 eligible as replacement for approved Brownline Net P/N 22361-51 or Boeing Net 10-60934-1 in combination with 125" x 88" pallets Brownline P/N 23223-51 or Phenrock P/N 22861-51 or Bruggermann & Brand P/N 2102. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-338C; T.C. 4A26	SA1230CE-D	Passenger cabin contemporary interior installation. Issued 2/1/77.	CE	16878	The Boeing Company 3802 South Oliver Wichita, KS 67210
707-338C; T.C. 4A26	SA2352WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargo pallet assembly P/N 24076-51. Issued 6/14/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-345C; T.C. 4A26	SA675EA	Installation of L. Marino cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-345C; T.C. 4A26	SA725EA	Pallet P/N LM1600 (1.53 Fwd). Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-347, 720-047B; T.C. 4A26, 4A28	SA2557WE	Replacement of existing girt on Air Cruiser evacuation slide P/Ns 15D22093-7, 15D22093-11, 15D22094-10 and 15D22454-2 with Sargent Industries/PICO Division girt P/N 6176105-103. Issued 6/30/72.	WE	70130	Sargent Industries Pico Division 2045 Evans Avenue San Francisco, CA 94124
707-347C; T.C. 4A26	SA979CE-D	Passenger interior arrangement modified to 5 pallet cargo/passenger configuration, per Boeing Dwg. 65-88752 & 65-88753, cargo conversion capability, Class "B" compartment with passengers, Class "E" compartment with no passengers. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-347C; T.C. 4A26	SA2975WE	Installation of shroud assembly, P/N 0350740068, in Universal Oil Products galley P/N 10870, to Weber Aircraft Company beverage cart, P/N 818620-411. Issued 1/6/75.	WE	48550	H. Koch & Sons 5410 E. LaPalma Anaheim, CA 92807
707-347C; T.C. 4A26	SA3601WE	Installation of a single Collins INS 61B inertial navigation system. Issued 3/10/78.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C; T.C. 4A26	SA3792WE	Installation of Litton LTN-211 omega navigation system. Amended 8/31/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C, -351C, 720-047B; T.C. 4A26, 4A28	SA808EA	Installation of inflight motion picture system. Amended 3/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-349C; T.C. 4A26	SA1596WE	Installation of Brownline Pallet 23997-51 and Net 22758-51 combination. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-349C; T.C. 4A26	SA1624WE	Installation of Decca Omni trac, Decca Doppler and Decca Loran. Amended 5/10/69.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
707-349C; T.C. 4A26	SA1650WE	Modification of co-pilot's C-11 compass system to a C-11B system by addition of remote compensator.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
707-351B/C; T.C. 4A26	SA87GL	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
707-351B; T.C. 4A26	SA1168EA	Installation of dual solar T-62T-40C2 gas turbine auxiliary power units, for ground use only. Amended 11/8/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
707-351C, 727-51C, -25C; T.C. 4A26, A3WE	SA1888WE	Installation of pallet assembly AC-10359-1 used in conjunction with net assembly AC-10373-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-351C; T.C. 4A26	SA2526WE	Installation of Satco Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with assemblies conforming to NAS 3610-1A2N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
707-351C; T.C. 4A26	SA2528WE	Installation of Satco, Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with net assemblies conforming to NAS 3610-1A3N, 2A1N, 2A2N, 2A3N, 2A5N, and 2A6N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
707-351C; T.C. 4A26	SA2773WE	Installation of Tridair Industries 3G net assembly. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
707-351C, -384C; T.C. 4A26	SA355CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-353B; T.C. 4A26	SA83NW	Relocation of autopilot accelerometer and rate gyros. Issued 1/16/74.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
707-353B; T.C. 4A26	SA1596WE	Steel duct installation for APU according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
707-353B; T.C. 4A26	SA1927WE	Installation of dual Litton inertial navigation systems.	WE	51500	Litton Systems, Inc. 5500 Canoga Park Woodland Hills, CA 91364
707-355C; T.C. 4A26	ST654SO	Installation of liquor service galley.	SO	05356	Aircraft Interior FAbricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
707-359B; T.C. 4A26	SA2863WE	Passenger audio entertainment system installation. Issued 3/29/74.	WE	33223	Electronic Engineering Company of California 1441 E. Chestnut Avenue Santa Ana, CA 92701
707-365C, -372C, 727-172C; T.C. 4A26, A3WE	SA1795WE	Installation of Heath Tecna AC-015201 structural container. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
707-369C; T.C. 4A26	SA1234CE-D	Passenger cabin contemporary interior installation. Issued 1/24/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-372C and 707-365C; T.C. 4A26	SA1674WE	Installation of Heath Tecna Corporation AC-10160 pallet with AC-10069 net. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastic Division 19819 - 84th Avenue South Kent, WA 98031
707-373C; T.C. 4A26	SA426CE	Modify SCAT system circuit. Amended 9/9/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-373C; T.C. 4A26	SA714CE	Installation of dual Bendix ALA-51 radio altimeter provisions and equipment.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-373C; T.C. 4A26	SA2843WE	Modification by installation of horse stalls P/N 690069 on NAS 3610-2A4P pallet. Issued 3/15/74.	WE	87900	W.W. Industries, Inc. 12450 Inglewood Avenue Hawthorne, CA 90250
707-384B; T.C. 4A26	SA853CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-384B, 707-384C; T.C. 4A26	SA576CE	Installation of multi-channel audio entertainment system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-384B, 707-384C; T.C. 4A26	SA546CE	Installation of doppler autopilot tie-in Bendix DRA-12 doppler radar with CPA-24 computer to Bendix PB-20 autopilot. Amended 12/27/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-386C; T.C. 4A26	SA2808WE	Installation of dual Litton LTN-72 inertial navigation system. Issued 2/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Road Woodland Hills, CA 91364
707-387B; T.C. 4A26	SA1232CE-D	Installation of large cargo door in left hand side of forward fuselage. Issued 6/10/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-387B; T.C. 4A26	SA1233CE-D	Increase maximum zero fuel weight to 96,162 KG Issued 8/31/77.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-387B; T.C. 4A26	SA1236CE-D	Installation of auxiliary power unit. Issued 9/26/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-399C; T.C. 4A26	SA850CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aereos Portugeses. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-400, 720 Series; T.C. 4A26, 4A28	ST912SO	Installation of cargo barrier net. Amended 9/13/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
720 Series; T.C. 4A28	SA88NW	Optional interior seating arrangement. Issued 1/14/74.	NW	10174	American Aviation Services 777 Perimeter Road Boeing Field Seattle, WA 98108
720 Series; T.C. 4A28	SA95CE	Crimsco 600301 jet cargo containers in forward cabin.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
720 Series; T.C. 4A28	SA148SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA180NW	Installation for 149 passenger configuration. Issued 5/7/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720 Series; T.C. 4A28	SA182SO	Interior modifications.	SO	31429	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA302EA	Inflight motion picture system. Amended 6/9/67.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA369EA	Litton low range altimeter system.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430
720 Series; T.C. 4A28	SA371CE	Wheel 152051-4 and brake assembly 260997-1.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46620
720 Series; T.C. 4A28	SA380EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
720 Series; T.C. 4A28	SA458WE	Crimsco jet cargo container 04-005--01, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA460CE	Wheel assembly 152051-5 and brake assembly 2600997-3.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46600
720 Series; T.C. 4A28	SA468EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
720 Series; T.C. 4A28	SA773WE	Closed circuit television entertainment system.	WE	25970	Continental Air Lines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
720 Series; T.C. 4A28	ST806SO	Installation of a cargo floor, smoke detector system and cargo restraint bulkhead. Amended 12/12/78.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
720 Series; T.C. 4A28	SA848CE-D	Additional overwing escape hatch installation interior configuration 2nd additional overwing escape hatch installation. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
720 Series; T.C. 4A28	SA1222WE	Boeing improved type engine thrust reverser forward pressure seal.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128
720 Series; T.C. 4A28	SA1245WE	Either single or dual Collins AL-101 radio altimeter system.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128
720, 720B; T.C. 4A28	SA177NW	Installation of container rack and six accompanying containers on forward right-hand coat closet. Reissued 5/29/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720, 720B; T.C. 4A28	ST564SO	Installation of HF antenna and associated hardware and structural provisions for mounting HF tuning unit. Issued 11/19/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
720, 720B; T.C. 4A28	ST662SO	Installation of nose cap "C/X" band weather radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
720, 720B; T.C. 4A28	ST931SO	Addition of smoke detector system for conversion to cargo carrier. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	ST932SO	Mechanical landing gear position indicator. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	SA3332WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
720B; T.C. 4A28	SA328NW	Installation of Fairchild weight and balance system (STAN). Issued 7/28/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
720B; T.C. 4A28	SA2806SW	Stewart-Davis, Inc. auxiliary power unit. Issued 6/30/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
720-22; T.C. 4A28	SA112NW	Installation of cabin interior arrangement. Issued 5/16/74.	NW	08480	Alaska Airlines, Inc. Seattle/Tacoma Int'l Airport Seattle, WA 98155
720-22; T.C. 4A28	SA278EA	See Document No. Report No. 1187, dated 4/18/67, Rev. 1/30/69, concerning Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
720-022; T.C. 4A28	SA1553WE	Installation of Fairchild P/N 13920-301 or 15630-601 Flight Data Recorder and Honeywell P/N 180 VI Central Data Computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
720-022; T.C. 4A28	SA2095WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2206WE	Installation of Bendix third attitude indicator. Issued 7/20/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720-022; T.C. 4A28	SA2744WE-D	Alternate 143 passenger seating configuration. Issued 3/28/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2746WE-D	Alternate 149 passenger seating configuration. Issued 5/3/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2834WE-D	Alternate 101 passenger seating configuration. Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2831WE-D	Couple EDO Loran system to ADF sense antenna instead of fin cap (no fin cap on UAL B720). Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2833WE-D	Installation of two HF communications systems. Issued 3/27/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022, -023, -025, -027, -048, -062, 720B-023B, -024B, -030B, -040B, -047B, -051B, -058B, -059B, -060B, -068B; T.C. 4A28	SA460CE	Replace main wheel and brake assemblies with Bendix wheel assembly P/N 152051-5 or P/N 152051-4 and Bendix brake assembly P/N 2600997-3. Reissued 5/1/79.	GL	15500	The Bendix Corporation Aircraft Brake & Strut Division 3520 West Westmoor Street P.O. Box 10 South Bend, IN 46624
720-022 and 727-22; T.C. 4A28 and A3WE	SA1396WE	Installation of McMillan Radome P/N 2406 as a replacement for Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720B-023; T.C. 4A28	SA412EA-D	Relocate the L.A.S.I. flight data recorder to the aft fuselage area at Station 1452 utilizing remote vertical accelerometer in left wheel well. Install new auxiliary pitot tube and static ports for the flight recorder.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
720-023B; T.C. 4A28	SA985CE-D	Side cargo door and interior installation. Issued 3/17/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-023B, -030B; T.C. 4A28	ST657SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in forward passenger compartment.	SO	67030	Mace Unit of PEF Dynamics, UOP 4856 Victor Street Jacksonville, FL 32207
720-023B, -030B, 720-047B; T.C. 4A28	SA851CE-D	Increase maximum ramp weight to 235,000 lbs. and zero fuel weight to 156,000 lbs. Amended 11/21/78.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-024B; T.C. 4A28	SA1617WE	Rewiring of galley electrical power supply.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA1767WE	Installation of Galley Models CAG-10, -20, 30 and -40 manufactured by Dale Engineering & Development, Inc. Amended 10/10/68.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA2599WE	Installation of Bell & Howell movie system. Issued 9/29/72.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-025; T.C. 4A28	SA251GL	Installation of Canadian Marconi Model CMA-740 Omega/VLF navigation system. Amended 12/29/78.	GL	10340	American Trans-Air 2600 South High School Road Indianapolis, IN 46241
720-025; T.C. 4A28	ST668SO	Installation of International Inflatables Co. door-mounted inflatable evacuation slide, P/N 68040, and International Inflatables Co. door-mounted slide container, P/N 00800.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
720-027; T.C. 4A28	SA82NW	Installation of navigator's station. Issued 12/11/73.	NW	10174	American Aviation Services, Inc. 7777 Perimeter Road Boeing Field Seattle, WA 98108
720-047B; T.C. 4A28	SA194NW	Installation of new look interior arrangement. Issued 6/30/75.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
720-051B; T.C. 4A28	SA801CE	Install Mark II (Hytrol) anti-skid system. Issued December 1971.	CE	16878	The Boeing Company Wichita Division 3801 S. Oliver Wichita, KS 67210
727 Series; T.C. A3WE	SA103SO	Collins 54W-1 comparator warning system. Amended 8/10/66.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA121GL	Installation of bleed-air valve actuator, P/N 366, to replace Boeing P/N 10-60817, in various locations in anti-ice system. Issued 11/3/76.	GL	60350	MPC Products Corporation 4200 West Victoria Avenue Chicago, IL 60646
727 Series; T.C. A3WE	SA140SO	Manufacture and install coatroom and magazine rack.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33148
727 Series; T.C. A3WE	SA159SO	Aircraft integrated data systems (AIDS).	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA161SO	Dual radio altimeter system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA183SO	Crimsco cargo containers 6003 in main cabin. Amended 12/15/66.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
727 Series; T.C. A3WE	SA339CE	Fairchild cockpit voice recorder system. Amended 3/15/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA354CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA372CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA425EA-D	Install standby horizon system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA427CE	Flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64108
727 Series; T.C. A3WE	SA438CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727 Series; T.C. A3WE	SA447EA	Vector analog computer system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727 Series; T.C. A3WE	SA469EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA490NW	Installation of PRIMUS-90 weather radar with standard black and white and also with color display.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188
727 Series; T.C. A3WE	SA535EA	Fabrication and installation of Marino Flex-Net P/N LM365. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA604SO	Dual Collins FD-109 integrated flight system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA625SO	Installation of main landing gear wheel assembly, P/N 3-1287 and brake assembly P/N 2-1147 or 2-1147-1, 2-1190.	GL	38504	B.F. Goodrich Engineered Systems Company Box 340 Troy, OH 45373

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727 Series; T.C. A3WE	ST664SO	Modify door-mounted evacuation slide container, Boeing P/N 65-26998-1, from a two-point closure to a positive single-point closure. Amended 3/30/70.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
727 Series; T.C. A3WE	SA699WE	Crimsco jet cargo container 04-005-01-1, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727 Series; T.C. A3WE	SA1093WE	Power source for Captain's CDI select relay switch relocated.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1105WE	Dual Collins AL-101 radio altimeter systems.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727; T.C. A3WE	SA1128EA	Installation of coat closet. Amended 9/11/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
727 Series; T.C. A3WE	SA1154WE	Cockpit voice recorder.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1265WE	Brownline pallet 23118 or Douglas pallet 5776662-505 with Brownline net 23143.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727 Series; T.C. A3WE	SA1322WE	Engine mounted fire detector unit modified to provide continuous support. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety System Division 1440 Fourth Street Berkeley, CA 94710
727 Series; T.C. A3WE	SA1367WE	Use of Brownline Corp. Pallet Nos. 23640-51 and 23224-51 in place of Douglas Aircraft Co. Pallet No. 577662-505.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1451WE	Installation of constant speed drive, load controller, generator and voltage regulator.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1509WE	Revised interior arrangement.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727 Series; T.C. A3WE	SA1563WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1868SW	Portable solid oxygen system for first-aid use. Issued 4/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
727 Series; T.C. A3WE	SA2422WE	Installation of Valley Todeco bolt VAL 22016 to replace Boeing bolt BAC B30EY8-48 on 727 thrust reverser. Issued 9/23/71.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727, 727C; T.C. 2H3	SA800CE	Installation of three cell forward and three cell aft auxiliary fuel tanks in lower cargo compartment. Issued June 1972.	CE	16878	The Boeing Company 3801 South Oliver Street Wichita, KS 67210
727, 727-100, -22; T.C. A3WE	SA2563WE	Installation of garment bag module. Issued 8/23/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	SA169GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	GL	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	ST650SO	Installation of dual band (C/X) type weather radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
727, 727C, 727-200 Series; T.C. A3WE	SA1239CE-D	Grimes coffee maker and warmer unit installation. Issued 11/20/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727, 727-100, 727C, 727-200; T.C. A3WE	SA2668WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-50 autopilot as replacement for Sperry or Smiths rate gyros. Amended 6/20/73.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3130WE	Installation of dual Litton LTN-72 or a single or dual LTN-72R INS/RNAV navigation system. Amended 5/18/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3145WE	Installation of Sperry Model Block V SP-50 autopilot and Honeywell Air Data computer. Issued 3/12/76.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3153WE	Installation of forward coat closet on left hand side just aft of forward entry door. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3154WE	Installation of interior configuration consisting of 10 first class and 98 coach seats. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3654WE	Installation of interior configuration with 10 first class and 95 coach seats. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series T.C. A3WE	SA3665WE	Installation of a dual Collins 61B inertial navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3679WE	Installation of a Global GNS-500A VLF/Omega navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, 727-100C, 727-200; T.C. A3WE	SA3717WE	Installation of a cabin divider. Issued 9/29/78.	WE	25970	Continental Air Lines International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3755WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-211 omega navigation system and a true airspeed system. Amended 3/23/79.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3964WE	Installation of dual Litton LTN-211 omega navigation systems. Issued 5/23/79.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, -200; T.C. A3WE	SA4161WE	Installation of Teledyne angle of attach system. Issued 7/7/80.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, -100C Series; 727-223, -225, -227, -228, -231, -235, -251, -260, -284, -295; T.C. A3WE	SA3220WE	Addition of filter to the cabin pressure limit control feature of P/N 103280 outflow valve. Issued 6/24/76.	WE	07505	AiResearch Manufacturing Company Garrett Corporation 2525 West 190th Street Torrance, CA 90509
727, 727C, 727-100, -100C, 727-200; T.C. A3WE	SA2348WE	Modify Boeing 727 Series airplanes by installation of emblem lights. Reissued 2/29/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
727, 727C, 727-200, 737; T.C. A3WE	SA3292WE	Installation of thrust reverser short track. Issued 11/23/76.	WE	78475	Thrustair, Inc. 12990 Branford Avenue Arleta, CA 91331
727, 727C, 727-200, 737; T.C. A3WE	SA3306WE	Installation of thrust reverser cascades. Issued 12/3/76.	WE	41015	Hasko-Air, Inc. 9042 Owensmouth Avenue Canoga Park, CA 91304
727, 727-100, 727C, 727-100C, 727-200 Series; T.C. A3WE	SA3521WE	Installation of a cabin divider. Issued 11/8/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-200; T.C. A3WE	ST436SO	Installation of thrust reverser deflector door drive. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727, 727C, 727-200; T.C. A3WE	ST450SO	Modification of thrust reverser forward deflector door link. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-182; T.C. A3WE	SA2480WE	Addition of INS attitude reference data to flight instruments. Issued 2/15/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-182; T.C. A3WE	SA2552WE	Install Litton P/N 451158 automatic data entry unit. Issued 8/17/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-287; T.C. A3WE	SA2168WE	Installation of Henry Engineering lounge tables No. 17701 and No. A17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727-287; T.C. A3WE	SA2170WE	Installation of class divider. Issued 5/27/70.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-230; T.C. A3WE	SA1235CE-D	Forward auxiliary fuel tank removal and reinstallation. Issued 10/9/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-247; T.C. A3WE	SA3505WE	Installation of ground proximity warning system. Issued 10/27/77.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
727-247; T.C. A3WE	SA3564WE	Installation of auxiliary fuel tanks in the forward and aft belly cargo/baggage compartments. Issued 1/20/78.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-247; T.C. A3WE	SA3390WE	Installation of dual LTN-51, or dual LTN-72, or dual LTN-72R, or one LTN-51 and either one LTN-72 or one LTN-72R inertial navigation system. Amended 4/29/80.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-247; T.C. A3WE	SA3967WE	Installation of coat room assembly No. RW2527036. Issued 5/29/79.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-214; T.C. A3WE	SA3065WE	Installation of 3400 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 7/16/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-14; T.C. A3WE	SA1942WE	Revised interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14; T.C. A3WE	SA1986WE	Interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -35, -193, -214, -235; T.C. A3WE	SA1885WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727-14, -51; T.C. A3WE	SA1717WE	Revised interior arrangement. Amended 4/20/77.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
727-14, -51, -214, -254, -2J7, -208; T.C. A3WE	SA3013WE	Installation of ground proximity warning system. Amended 12/19/78.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -51, -214, -254, -208; T.C. A3WE	SA3939WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/11/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-17; T.C. A3WE	SA3674WE	Installation of 2700 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 6/30/78.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-17, -31, -31C, -180C, -231, -231A; T.C. A3WE	SA1488CE	Installation of a pitot heater failure indication system. Issued 5/4/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-21; T.C. A3WE	SA264NW	Interior arrangement. Issued 2/20/76.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-21; T.C. A3WE	SA1078EA-D	Installation of two closets in rear of cabin to accommodate a bar or food cart and provisions for parking the carts in flight at two locations. Amended 11/8/79.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
727-21, 21C; T.C. A3WE	SA6129D-D	Installation of portable berth (aerotherm stretcher). Reissued 9/6/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727-21, -22, -81; T.C. A3WE	SA2660WE	Modification of cabin interior. Amended 12/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-21, -81; T.C. A3WE	SA3022WE-D	Installation of new seating arrangement. Amended 11/10/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-21C; T.C. A3WE	SA1292WE	Installation of Boeing palletized cargo system 65-49102 with Brownline pallet 22630-51 or 26100-52 Brownline net assembly 23225-51, 23226-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-21C; T.C. A3WE	SA1594WE	Installation of Heath Tecna Corp. pallet AC-10065 and Brownline Corp. net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-21C; T.C. A3WE	SA3006WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-21C; T.C. A3WE	SA3672WE	Installation of Brownline quick change pallets, P/N's 45881-101, 45882-101 and 46129-101. Issued 6/19/78.	WE	17740	Brooks & Perkins Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-21C, -22C, -25C, -27C, -30C, -31C; T.C. A3WE	SA696CE	Installation Aeroquip Corp. cargo tie-down net.	GL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203
727-22; T.C. A3WE	SA1788WE	Interior arrangement installation.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94125
727-22; T.C. A3WE	SA3323WE	Installation of forward facing flight attendant seat on forward galley. Issued 1/20/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-22; T.C. A3WE	SA3364WE-D	Revise cabin seating to accommodate 118 all-coach configuration. Issued 4/25/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C; T.C. A3WE	SA3023WE-D	Revise seating arrangement from 18 first class/78 coach to 12 first class/86 coach configuration and further revised to 10 first class/86 coach configuration. Amended 6/11/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-22, 727-22QC; T.C. A3WE	SA1687WE	Modify existing Collins Radio Company type FD-109 Flight Director installation to add "Steering", "Airspeed-Hold", and "Auto Approach" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3079WE	Installations of Collins FPC-75-P/N 622-2615-012 or P/N 622-2615-212, or P/N 622-2615-013, ground proximity warning system computer in airplanes. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3350WE-D	Air data system. Amended 7/20/79.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-22, -24C, -30, -76, -92C; T.C. A3WE	SA3655WE	Installation of Nordskog Company auxiliary galley Model 1-420. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727-22, -24C, -30, -76, -92C, -224; T.C. A3WE	SA4157WE	Installation of Fairchild beverage cart, Model 79067000. Issued 6/6/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-22, -30, -76, 92C; T.C. A3WE	SA981CE-D	Reconfiguration of flight crew instrument panels, avionics and passenger cabin. Amended 8/28/78.	CE	16877	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-22C; T.C. A3WE	SA645CE	Make and install pallets in accordance with Brooks & Perkins Drawing Index No. 16987DL-E and Installation Instructions No. BPS 149. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA814CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA842CE	Installation of cargo pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA1622WE	Modification of type design to permit installation of Heath Tecna Corp. AC-10061 pallet with AC-10069 net.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-22C; T.C. A3WE	SA1816WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-22C; T.C. A3WE	SA1962WE	Modify by installation of pallet assemblies 40160101 thru 40160108 used in conjunction with net assemblies 22672-51, -52; 23143-51, 22759-51, -52; 22273-51, 7776967-1 (Douglas) and 3950020 (Aeroquip). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1, or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
727-22C; T.C. A3WE	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517, with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks & Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2255WE	Installation of Satco, Inc., pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-22C; T.C. A3WE	SA2274WE	Installation of Irvin 88" x 125" cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
727-22C; T.C. A3WE	SA2844WE	Installation of coat and luggage stowage unit. Issued 2/25/74.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-22C; T.C. A3WE	SA3359WE-D	Retrofit of Kollsman P/N A41869-10-021 altimeters on the captain's and first officer's instrument panel. Issued 1/11/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3577WE-D	Installs overhead stowage bin kit. Issued 8/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3673WE	Installation of cargo restraint system which meets the requirements of a NAS 3610 class IIA restraint system. Issued 6/21/78.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-22C; T.C. A3WE	SA3775WE	Installation of the Brownline 46000-101 cargo system. Issued 10/31/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-22C, -24C, -25C, -116C; T.C. A3WE	SA4098WE	Installation of cargo system, P/N 47270-101. Issued 3/10/80.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-022; T.C. A3WE	SA2838WE-D	Installs barrier and tie-down fitting for using preloaded liquor service cart on-board aircraft. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-022: T.C. A3WE	SA3575WE-D	Remove all first class seats, the class divider, the carry-on baggage and garment bag modules and replace with all coach seats to increase seating capacity to 112 passengers. Issued 4/24/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-022;	SA3363WE-D	Installation of dual Collins FD-109A flight director systems. Issued 4/24/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-022, -022C, -222; T.C. A3WE	SA2201WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727-22, -222, -222C: T.C. A3WE	SA2096WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-23; T.C. A3WE	SA411EA-D	Relocate the flight data recorder Station 1120 on cabin floor, left hand side, aft of last row of seats to provide improved crash survivability. Amended 12/8/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23: T.C. A3WE	SA563EA	Installation of digital adaptive recording system (DAPS) on one Boeing 727-23. Issued 4/7/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA501EA-D	Delete auxiliary vertical gyro on 727-23 and 727-123 and authorize use of either Sperry or Bendix gyros on 727-35 and 727-95. Amended 9/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA515EA-D	Install REF Dynamics beverage bar. Amended 2/16/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA523EA-D	Install overwing emergency lights. Amended 1/12/69.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA524EA-D	Change interior passenger seating arrangement.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA558EA-D	Modification of leading edge slat and flap position indication system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95 and 727-123: T.C. A3WE	SA866WE	Installation of ILS Back Course and Compass Switches. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA872WE	Installation of Collins P/N 54W-1 instrument comparator. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1195WE	Installation of dual Collins FS-108 flight director systems. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1575WE	Installation of dual Collins AL-101 radio altimeter system. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-95, 727-123; T.C. A3WE	SA804WE	Installation of Honeywell HG180 Modular Air Data Computer System. Amended 6/26/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-23, -223; T.C. A3WE	SA552EA-D	Installation of autopilot go-around unit. Issued 4/24/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-24C, 727-116C; T.C. A3WE	SA1441CE-D	Change crew instrument panels and systems revisions. Reissued 9/19/79.	CE	16877	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-24C; T.C. A3WE	SA1661WE	Installation of Bendix Dual DRA 12 Doppler System.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2886WE	Interior arrangement. Issued 5/18/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2899WE	Installation of courier seat. Issued 6/15/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2942WE	Installation of Nordskog Galleys 1-289A and 1-290A. Amended 11/14/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, -92C; T.C. A3WE	SA3855WE	Installation of Brownline cargo/seat pallet system 45980, configuration -101. Issued 2/12/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
727-25; T.C. A3WE	ST588SO	Installation of 119 passenger interior and installation of two EAI 52-RA-7 four man life rafts. Issued 4/30/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST663SO	Installation of LORAN A navigation system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST740SO	Cabin interior arrangement and furnishings changes. Issued 6/3/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST426SO	Installation of Honeywell HG180V3 air data computer with electronic altimeters, altitude reporting digitizer and altitude alerting system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST741SO	Cabin interior configuration changes. Amended 1/24/75.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST751SO	Modification of main cabin passenger interior configuration from 14 first class and 89 tourist class to 12 first class and 95 tourist class accommodations. Issued 5/28/76.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, -25C; T.C. A3WE	ST954SO	Installation of Mansfield Aircraft Products model 1470 galley/coatroom. Issued 8/29/77.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C, -225; T.C. A3WE	ST510SO	Installation of dual HF communications system using vertical fin leading edge slotted antenna. Amended 1/13/78.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	ST534SO	Interior - two pallet cargo/65 passenger MAC configuration installed. Issued 4/13/73.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	SA2364WE	Installation of Satco, Inc. cargo pallet assembly P/N 31095-501, -503, -505, -507 in conjunction with net assemblies NAS 3610-2A1N, -2A2N, -2A3N, -2A5N, and -2A6N. Amended 5/18/72.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-30; T.C. A3WE	SA982CE-D	Interior arrangement installation. Amended June 1976.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-30; T.C. A3WE	SA3157WE	Installation of 1200 gallon auxiliary fuel tank in forward cargo compartment. Issued 3/26/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-30 T.C. A3WE	SA3319WE	Installation of auxiliary fuselage fuel tanks (1600 gallons) in forward and aft cargo compartment. Issued 12/28/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91406
727-30, -81; T.C. A3WE	SA2734WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 2/13/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-030, -224; T.C. A3WE	SA3408WE	Installation of Lermer Apparatebau GMBH beverage cart No. L15701. Issued 5/26/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 91406
727-31; T.C. A3WE	SA478CE	Modification to flap quadrant.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31; T.C. A3WE	SA570CE	Install Models 14801 or 14802 Henry Engineering Company bar unit. Amended 10/18/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C; T.C. A3WE	SA373CE	Installation of a single SCAT system. Amended 8/12/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C; T.C. A3WE	SA604CE	Installation of dual radio altimeter provision - single equipment driving dual indicators. Amended 2/3/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C, -180C; T.C. A3WE	SA235CE	Installation of Kollsman Integrated Flight Instrument System (KIFIS). Amended 5/8/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C, -180C; T.C. A3WE	SA734CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, -31C, -180C; T.C. A3WE	SA779CE	Installation of Bendix gyro horizon and inverter. Issued June 1971.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA553CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA828CE	Install Butler National Corp. flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA1137CE	Installation of hydraulic interconnect override system. Issued June 1975.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180C, 727-231; T.C. A3WE	SA1542CE	Installation of a Growth Industries dual cavity oven. Issued 12/12/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-31, -31C, -231; T.C. A3WE	SA490CE	Installation of Safe Flight Corp. auto power servo kits. Amended 10/9/74.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31C, -180C; T.C. A3WE	SA741CE	Install Henry Engineering auxiliary bar model 15501A and one additional triple passenger seat.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-35; T.C. A3WE	SA639SO	Installation of hatrack assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA640SO	Installation of liquor service galley assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA1566WE	Installation of Sperry SP-50 Mod Block IV Single Channel Autopilot. Amended 5/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-35, 727-95, 727-123; T.C. A3WE	SA1576WE	Replacement of Captain's altimeter and First Officer's altimeter and and installation of third altimeter. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-35, -235; T.C. A3WE	ST738SO	Installation of Gulton Model EMBS 144 nickel-cadmium electrical storage battery and integral automatic control system. Issued 1/23/74.	EA	61220	National Airlines, Inc. P.O. Box 2055 Miami International Airport Jamaica, NY 11430
727-46; T.C. A3WE	SA847CE-D	Structural and system modification for installation of service door and retractable step. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-46; T.C. A3WE	SA2970WE	Installation of 300 gallon auxiliary fuel tank in aft cargo compartment. Issued 12/20/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-51, -51C, -151C, -251; T.C. A3WE	SA99GL	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
727-75, -232, -295; T.C. A3WE	ST855SO	Installation of Bendix ground proximity warning system. Issued 10/16/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-76; T.C. A3WE	SA4164WE	Installation of dual Delco carousel IVA inertial navigation system. Issued 6/27/80.	WE	07500	AiResearch Aviation Company 6201 WEst Imperial Highway Los Angeles, CA 90045
727-77; T.C. A3WE	SA3559WE	Installation of a 1932-gallon auxiliary fuel tank system in forward and aft cargo compartments. Issued 2/6/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-81; T.C. A3WE	SA2724WE	Installation of executive cabin interior. Amended 9/20/74.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727-81, -100; T.C. A3WE	SA263NW	Garment bag module modification. Issued 2/25/76.	NW	47722	Kelley-Morrow Enterprises The Common Building 1200 - 112th N.E. Bellevue, WA 98004
727-81, -100; T.C. A3WE	SA2732WE	Installation of duel LTN-104 navigation systems. Amended 3/13/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-90, -90C; T.C. A3WE	SA2245WE	Interior arrangements. Issued 9/18/70.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98158
727-90C; T.C. A3WE	SA139NW	Installation of quick change interior arrangement. Amended 4/21/75.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98108
727-90C; T.C. A3WE	SA327NW	Interior arrangements 98 PAX and two cargo pallet/63. Issued 7/23/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA129NW	Installation of cabin interior arrangement. Issued 9/23/74.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA310NW	Interior arrangement. Issued 5/28/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, 737-202C, -210C; T.C. A3WE, A16WE	SA1823WE	Installation of "Heathair" AC-10360 cargo pallet assembly and AC-10374 cargo net assembly. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-92C; T.C. A3WE	SA1839WE	Stewardess seat installed on Nordskog 769 galley.	WE	61605	Nordskog Co., Inc. 16000 Strathern Street Van Nuys, CA 91406
727-95; T.C. A3WE	SA704EA	Installation of Henry Engineering Company Galleys Models Nos. 14001 and 14002. Reissued 12/8/72.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-100 Series Models type certificated as of 6/17/68; T.C. A3WE	SA587CE	Installation of Hoskins Twilighter Mark V high intensity light system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
727-100; T.C. A3WE	SA612NW	Installation of coat closet. Issued 5/26/78.	NW	48532	KME Manufacturing, Inc. The Commons Building 1200 112th Street, N.E. Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-100; T.C. A3WE	SA643NW	Installation of six carry-on baggage modules. Issued 9/13/78.	NW	78672	Tramco, Inc. 1033 Thomas Avenue, S.W. Renton, WA 98055
727-100; T.C. A3WE	SA697NW	Install life raft stowage compartments. Issued 12/14/78.	NW	41625	Heath Tecna 19819 84th Avenue South Kent, WA 98031
727-100; T.C. A3WE	SA1130SO	Installation of an aft galley storage module. Issued 1/22/80.	SO	64500	Piedmont Airlines Smith-Reynolds Airport Winston-Salem, NC 27102
727-100; T.C. A3WE	SA1205EA	Installation of on board folding stairs. Issued 9/10/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
727-100; T.C. A3WE	SA1206EA	Installation of humidifier system. Issued 9/10/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
727-100; T.C. A3WE	SA2498SW	Collins FPC-75 ground proximity warning system. Issued 1/23/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
727-100 Series; T.C. A3WE	SA3501WE	Installation of Litton LTN-201 omega navigation system. Amended 12/29/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100 Series; T.C. A3WE	SA3810WE	Installation of a maximum of eight auxiliary fuel tanks in forward and aft cargo compartments. Amended 1/4/80.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-100 Series; T.C. A3WE	SA3851WE	Installation of Litton LTN-211 Omega Navigation System. Amended 4/19/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100, -100B, -200; T.C. 4A21	ST660SO	Installation of "C/X" band nose radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
727-100, -100C Series; T.C. A3WE	SA3661WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-201 Omega navigation system and a true airspeed system. Issued 10/11/78.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
727-100, -200; T.C. A3WE	SA1050CE	Install Crimsco cargo container, P/N 600301. Issued November 1974.	CE	27000	Crimsco, Inc. 5001 E. 59th Street Kansas City, MO 64130
727-100, -200; T.C. A3WE	SA2240WE	Installation of door-mounted emergency light. Amended 9/23/70.	WE	44266	International Inflatables Company Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
727-100, -200; T.C. A3WE	SA3333WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
727-100, -200; T.C. A3WE	SA3374WE	Installation of bearing P/N VTB02220 as replacement for Boeing P/N 10-60545-113S in main landing gear lock system assembly. Issued 3/29/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200; T.C. A3WE	SA3379WE	Installation of bearing, P/N VTB02800 in lieu of Boeing bearing P/N 10-60545-143. Issued 4/20/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200 Series; T.C. A3WE	SA3508WE	Installation of Valley-Todeco bearings, P/Ns VTB-02900, VTB-02910, VTB-02920, VTB-02930. Issued 11/8/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, 727-200; T.C. A3WE	SA3716WE	Installation of a Dretloh Model 5002, P/N 121214-1 food carrier. Issued 8/25/78.	WE	30702	Dretloh Aircraft Supply, Inc. 980 North Lemon Orange, CA 92667
727-100, -200; T.C. A3WE	SA4133WE	Installation of an ARINC communications addressing and reporting system (ACARS). Issued 4/24/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100, 100C; 737; T.C. A3WE, A16WE	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-171C, 727-173C; T.C. A3WE	SA1693WE	Revised interior arrangement with Nordskog hostess seat 6734 and door 61246 and associated modifications added to Mapco Galley Model 680T-1.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-172C; T.C. A3WE	SA671EA	Installation of pallet net for use with Boeing pallets.	SO	44750	Irvin Industries, Inc. 1315 Versailles Road Lexington, KY 40501
727-172C; T.C. A3WE	SA849CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aeros Portugeses requirements. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-172C; T.C. A3WE	SA1662WE	Installation of Heath Tecna Corp. AC-10160 pallet with AC-10069 net on Boeing 707-172C. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-173C; T.C. A3WE	SA1907WE	Interior arrangement reflecting 122 passenger quick change conversion configuration. Amended 6/3/69.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
727-173C; T.C. A3WE	SA2385WE	Installation of interior arrangement. Amended 9/14/71.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
727-180C; T.C. A3WE	SA558CE	Installation of Kollsman integrated flight instrument system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-180C; T.C. A3WE	SA559CE	Installation of a single SCAT system. Amended 8/11/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-180C; T.C. A3WE	SA560CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-200; T.C. A3WE	SA349NW	Installation of wind screen in forward cabin RH side. Issued 8/27/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 832 Issaquah, WA 98027
727-200; T.C. A3WE	SA359NW	Installation of carry-on baggage unit. Issued 9/28/76.	NW	48532	KMF Manufacturing, Inc. 1200 - 112th N.E. Bellevue, WA 98004
727-200; T.C. A3WE	SA547NW	Installation of Mark I interior kit. Issued 11/22/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue S. Kent, WA 98031
727-200; T.C. A3WE	ST742SO	Modification and installation of seat model 914-1. Issued 6/26/74.	SO	21560	Charlotte Aircraft Corporation P.O. Box 1225 Miami, FL 33148
727-200; T.C. A3WE	SA774SO	Installation of the Litton LTN-211 Omega Navigation System. Issued 11/30/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airlines Miami, FL 33148
727-200; T.C. A3WE	SA816NW	An interior installation. Issued 8/8/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
727-200; T.C. A3WE	SA2335SW	Modification to increase depth of Weber 808737-618-M pilot seat and 808737-619-M copilot seat. Issued 7/23/76.	SW	14222	B & H Parts Company Meacham Field Fort Worth, TX 76106
727-200; T.C. A3WE	SA2672WE	Installation of coat and luggage stowage unit. Issued 3/23/73.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
727-200; T.C. A3WE	SA3054WE	Installation of dual Litton LTN-72 inertial navigation system. Amended 6/22/76.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-200; T.C. A3WE	SA3081WE	Replacement of evacuation slide container latches with latches of a new design. Reissued 6/2/76.	WE	70130	Sargent Industries PICO Division Kahr Bearing Division 2045 Evans Avenue San Francisco, CA 94124
727-200; T.C. A3WE	SA3594WE-D	Removal of all first class seating and class divider. Relocate cabin seating to provide 14 rows at 38-inch pitch. Installation of additional furnishings. Amended 1/7/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-200 Series; T.C. A3WE	SA3882WE	Installation of aft cargo hold trash chute container assembly, P/N B-25-0256. Amended 2/12/80.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-200, 737; T.C. A3WE, A16WE	SA764NW	Inner window pane replacement. Issued 5/3/79.	NW	79672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
727-214; T.C. A3WE	SA1922WE	Interior arrangement. Amended 6/6/69.	RM	37015	Frontier Airlines 5900 East 39th Avenue Denver, CO 80207
727-214, -254, -208; T.C. A3WE	SA3069WE	Installation of galley in forward passenger compartment. Amended 2/12/80.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3560WE	Installation of PSA galley P/N C-25-0085. Issued 1/18/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3625WE	Installation of 168 passenger interior arrangement. Issued 4/3/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3820WE	Installation of 165 passenger interior arrangement, and aft stowage closet. Issued 1/8/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor San Diego, CA 92101
727-222; T.C. A3WE	SA2448WE	Installation of McDonnell Douglas Eros II collision avoidance system. Issued 11/22/71.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2743WE-D	Installation "New Look" cabin interiors. Amended 6/10/77.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2826WE-D	Installations of provisions for ground proximity warning system. Issued 2/21/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2832WE-D	Installation of ground proximity warning system with cockpit annunciations deactivated and warning signals connected to digital recorder. Issued 3/13/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2841WE-D	Revise cabin seating configuration to accommodate 14 first class/112 coach configuration. Amended 8/20/76.	WE	80500	United Airlines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3037WE-D	Revise cabin seating configuration to accommodate 10 first class/118 coach configuration. Issued 2/24/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3353WE-D	This modification installs a retractable cart tie-down at the Sta. 350-50 and LBL 32.34. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3354WE-D	This modification installs modified seats in the first class compartment. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3355WE-D	Installation of carry-on baggage and garment bag modules just aft of forward entry door on left side of passenger cabin. Issued 10/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3362WE-D	Installation of a Safe Flight P/N 6500-2 windshear warning computer for in-service evaluation. Issued 3/15/78.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3578WE-D	Installation of arinc communications addressing reporting system (ACARS). Amended 2/9/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3589WE	Installation of passenger audio entertainment system. Issued 7/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-222; T.C. A3WE	SA3590WE-D	The cabin interior seating configuration will change from 10F/124Y to 14F/118Y. One row of coach seats will be removed and one row of first class seats added. The class divider will be moved accordingly. Issued 2/9/79.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3592WE-D	Replace the auxiliary galley/stowage compartment located in the RH aft passenger cabin between station 1101 and 1137 with a new stowage compartment. Amended 12/17/79.	WE	90500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA4063WE	Deletion of the pair of excess Type I emergency exits located at station 720 and 15. Issued 11/29/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-223; T.C. A3WE	SA521EA-D	Install single area navigation system. Amended 9/10/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74151
727-224; T.C. A3WE	SA3325WE	Installation of auxiliary bar unit No. 1-368. Issued 1/13/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-225; T.C. A3WE	ST593SO	Installation of 18 first class/116 tourist class passenger interior with modified coatroom and windscreen. Issued May 1974.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225; T.C. A3WE	ST753SO	Installation of main cabin equipment to provide accommodations for 137 passengers (12 first class and 125 tourist class). Issued 8/4/76.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225A; T.C. A3WE	SA775SO	Installation of a coatroom and class divider partition in the main cabin at B.S. 544. Issued 12/3/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-225; T.C. A3WE	SA1238CE-D	Interior conversion to 177 tourist class passengers. Issued 11/7/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-231; T.C. A3WE	SA561CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA562CE	Installation of single seat system. Amended June 1974.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA639CE	Modification of SCAT/Auto Throttle to include auto-land throttle closure feature.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA721CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA1287CE	Revision of engine fire detection circuit. Issued December 1976.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA1475CE	Installation of Simmonds Precision performance advisory system (fuel management). Issued 3/6/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-237; T.C. A3WE	SA2729WE	Installation of interior arrangement. Issued 7/23/73.	WE	62160	Pacific Southwest Airlines 3220 N. Harbor Drive San Diego, CA 92101
727-247; T.C. A3WE	SA469NW	Installation of coat closet unit on Western Airlines aircraft. Issued 6/24/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
727-247; T.C. A3WE	ST549SO	Manufacture and installation of P/N 10826-1 cart stowage unit. Amended 11/18/77.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-247; T.C. A3WE	ST550SO	Manufacture and installation of P/N 10825 coat closet unit. This STC is limited to Boeing 727-247 aircraft with wide body interiors. Issued 9/21/73.	SO	91130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
727-247; T.C. A3WE	SA3495WE	Conversion of UOP galley by installation of UOP oven, Grimes coffeemaker and overboard drain system. Issued 9/30/77.	SO	8130	Aerospace Division Universal Oil Products 4856 Victor Street Jacksonville, FL 32207
727-247; T.C . A3WE	SA3644WE	Installation of IPECO pilot and co-pilot crew seats. Issued 5/16/78.	WE	54860	MAPCON Associates, Inc. Agents for IPECO Europe Ltd. 18436 Hawthorne Boulevard Suite 212 Torrance, CA 90504
727-247, -208; T.C. A3WE	SA29NE	Installation of Aerospace Division galleys, P/Ns 190F1000-103, 190F2000-105, -106, and -107 in Western Airlines Boeing 727-247 and -208 aircraft. Amended 5/4/79.	NE	81120	Aerospace Division Universal Oil Products Route 202 Bantam, CT 06750
727-248, -208; T.C. A3WE	SA3929WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/3/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
727-281;737-281; T.C. A3WE, A16WE	SA33NW	Installation of class divider in constant section at station 500 on Model 727-281 and station 525 on Model 737-281. Issued 3/14/73.	NW	83765	Vinnedge and Associates P.O. Box 374 North Bend, WA 98045
727-291 and 727-295; T.C. A3WE	SA1602WE	Revised interior arrangement with Frontier Galley Models 13301, 13302, 13303, and 13304 installed. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727, 727C, 727-200; T.C. A3WE	ST731SO	Installation of automatic in-flight lock for ventral stair-door. Amended 5/18/73.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727, 727C, 727-200; T.C. A3WE	SA2315WE	Installation of thrust reverser adjustable offset links on above aircraft equipped with Boeing Thrust Reversers, BAC P/N 65-27800-1, 65-27800-3 and 65-27800 only. Issued 2/22/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2337WE	Installation of Triumph Corporation solid offset thrust reverser links. Issued 4/9/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2391WE	Modification of nose gear steering cylinder. Issued 7/30/71.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727, 727C, 727-200; T.C. A3WE	SA2471WE	Installation of Triumph Corporation 5026 series bearings and rod ends on thrust reversers. Issued 2/1/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T.C. A3WE	SA2487WE	Installation of main landing gear lock actuator bearing assembly. Issued 3/3/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2518WE	Installation of thrust reverser forward deflector door link. Issued 5/1/72.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727, 727C, 727-200; T.C. A3WE	SA2627WE	Installation of fuel control rod end bearings. Issued 1/4/73.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T.C. A3WE	SA2779WE	Installation of auxiliary power fire detector unit. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 Fourth Street Berkeley, CA 94710
727 Series, 737 Series; T.C. A3WE, A16WE	SA1052SO	Installation of GE battery P/N 43B022RB36 in place of Marathon P/N CA-727-7, CA-727-20, or CA-27-20 batteries or SAFT P/N 23180 batteries; or installation of GE battery P/N 43B020RB10 replacing Marathon P/N CA-727-7, CA-727-20 or CA-27-20 or SAFT P/N 23186 or 23180 batteries. Amended 5/11/79.	SO	37380	General Electric Company P.O. Box 114 GAinesville, FL 32602

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727 Series; 737 Series; T.C. A3WE, A16WE	SA2501WE	Installation of replacement cooling turbine nozzle assembly. Reissued 1/5/79.	WE	67145	Repair Tech International 13900 Saticoy Street Van Nuys, CA 91402
737 Series; T.C. A16WE	SA270NW	Interior arrangement. Issued 3/11/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA353NW	Installation interior components consisting of 2 wind screens and 3 decorative panels on existing galleys. Issued 9/7/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA370NW	Removal of passenger interior, installation of cargo compartment liners and cargo tie down equipment. Issued 11/8/76.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	ST854SO	Installation of Bendix GPW-93 ground proximity warning system. Amended 1/21/76.	SO	64500	Piedmont Aviation, Inc. P.O. Box 2720 Smith Reynolds Airport Winston-Salem, NC 27102
737; T.C. A16WE	SA751NW	Installation of a coat closet/ storage bin. Issued 4/12/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA781NW	Installation of a coat closet. Issued 6/7/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
737; T.C. A16WE	SA853NW	Installation of a coat closet. Issued 10/29/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA1401SW	Replace Marathon CA-737 battery with General Electric 43B022FB10 battery. Issued 12/9/71.	GL	37379	General Electric Company 206 W. Mitchell Avenue Cincinnati, OH 45232
737; T.C. A16WE	SA1519SW	Coat closet. Issued 10/14/72.	SW	16750	BIDCO, Inc. 2732 Ludelle Fort Worth, TX 76105
737; T.C. A16WE	SA3983WE	Installation of storage unit, P/N 10165. Issued 6/26/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
737-2A1; T.C. A16WE	ST136RM	Installation of interior arrangement. Issued 4/25/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2A6; T.C. A16WE	SA2153WE	Installation of fuselage fuel tanks in forward and aft cargo compartments.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA6RM	Interior arrangement modification. Amended 3/10/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA66RM	Revision of aft coat closet capacity from 100 lbs. to 250 lbs. Amended 8/6/80.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA67RM	Installation of trash module in aft coat closet. Issued 3/12/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -222, -247, -291; T.C. A16WE	SA75RM	Installation of Mapco closet module, P/N 1345, under forward left side hatrack. Issued 5/26/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -217, -291, -222; T.C. A16WE	SA101RM	Install dual SELCAL system. Amended 6/22/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-021; T.C. A16WE	SA523AL	Installation of ground proximity warning system. Reissued 6/19/75.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
737-T43A; T.C. A16WE	SA265GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500, and Harrowe barometric altitude rate computer P/N 4030-03-1. Issued 8/25/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
737-282C, -2Q8C; T.C. A16WE	SA4019WE	Installation of Brownline cargo pallet restraint system, P/N 46926-101, -102. Amended 11/21/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-100, -200, -200C Series; T.C. A16WE	SA2705WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-77 autopilot as a replacement for Sperry or Smiths rate gyros. Amended 7/15/74.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
737-100, 737-200; T.C. A16WE	SA2828WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-100, -200; T.C. A16WE	SA3334WE	Installation of stretcher carrier, AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
737-100/200/200C; T.C. A16WE	SA2267WE	Installation of door mounted emergency light. Issued 10/30/70.	WE	44266	International Inflatables Co. Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
737-100/200/200C; T.C. A16WE	SA2564WE	Installation of garment bag module. Amended 9/20/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
737-100, -200, -200C; T.C. A16WE	SA170GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-6, with Courter flap asumetry detector kit, P/N 298-1026-02. Reissued 12/21/78.	GL	26675	Courter, Incorporated 375 North Lake Street Boyne City, MI 49712
737-100, -200, -200C; T.C. A16WE	ST686SO	Installation of nose cap "C/X" band weather radar radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
737-100, -200, -200 Series; T.C. A16WE	SA887EA	Installation of structural provisions for tail logo lights. Amended 4/19/72.	EA	18750	Butler Aviation - Friendship, Inc. Sub. of Butler Aviation Int'l Friendship Int'l Airport Baltimore, MD 21240
737-100/200/200C; T.C. A16WE	SA2542WE	Installation of wing-tip mounted logo lights. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
737-200; T.C. A16WE	SA53RM	Installation of Sundstrand Data Control ground proximity warning system and glide slope monitoring system. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA55RM	Installation of Universal Oil Products Co. galley tray cart. Amended 8/18/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA62RM	Installation of Universal Oil Products Co. beverage cart, P/N 11143-1. Issued 8/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA103NW	Installation of modified lower interior sidewall. Issued 4/12/74.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	SA178NW	Installation of perfume dispenser into three lavatories. Issued 5/12/75.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	ST201RM	Modification of Sundstrand data control ground proximity warning system and glide slope monitoring system installation. Issued 6/30/80.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	ST430SO	Installation of unusual events recording system.	GL	77600	Technology, Inc. 7400 Colonel Glenn Highway Dayton, OH 45431

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
737-200; T.C. A16WE	ST875SO	Replacement of Monogram P/N 3299-1 or Leach P/N TD1514-1002 timer assemblies with Piedmont P/N 737D-81017 solid state timer. Amended 7/13/76.	SO	64500	Piedmont Aviation, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200 Series; T.C. A16WE	ST1020SO	Installation of 112 passenger interior arrangement. Issued 8/31/78.	SO	64500	Piedmont Aviation Smith-Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	ST1034SO	Fabrication and installation of an aft right hand windscreen. Issued 11/15/78.	SO	64500	Piedmont Airlines Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1113SO	Fabrication and installation of an aft left-hand windscreen. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1114SO	Fabrication and installation of a forward coat closet. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA2747WE-D	This modification provides an all coach seating configuration for 113 passengers. Issued 5/24/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
737-200; T.C. A16WE	SA3134WE	Installation of Collins ground proximity warning system. Issued 1/7/76.	WE	04080	Air California P.O. Box 2678 Hangar #6, Oakland Int'l Airport Oakland, CA 94614
737-200; T.C. A16WE	SA4042WE	Installation of new overhead enclosed stowage compartments, new fluorescent wash lighting and modified passenger service units. Amended 3/20/80.	WE	42150	HITCO 1600 West 135th Street Gardena, CA 90249
727-200, -200C; T.C. A16WE	SA3464WE	Installation of alternate Systron Donner lower engine fire/overheat detector system, P/N 1705-1, in place of approved P/N 1705 lower engine fire/overheat detector system. Issued 9/2/77.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 4th Street Berkeley, CA 94710
737-200C; T.C. A16WE	SA28NW	Interior modification consisting of installation of cargo/passenger partition and coat closet/service tray stowage. Amended 6/29/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA79NW	Seat pallets for Alaska Airlines. Issued 11/9/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA101NW	Interior modification consisting of installation of windscreens and aft coat closet. Issued 4/22/74.	NW	93765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA276NW	Installation of forward LH/RH wind screen in existing approved interior arrangement. Issued 5/13/76.	NW	83765	Vinnedge & Associates P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA337AL	Installation of palletized seating system on high profile cargo roller system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405
737-200C; T.C. A16WE	SA452AL	Installation of palletized cargo/ passenger system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405
737-200C; T.C. A16WE	SA492AL	Installation of RE-1006 landing aid system. Amended 12/11/73.	AL	85890	Wien Consolidated Airlines, Inc. 4100 Int'l Airport Road Anchorage, AK 99502
737-201, 737-214; T.C. A16WE	SA1899WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
737-210C; T.C. A16WE	SA3900WE	Installation of heavy duty cargo handling and quick change system, P/N 90045. Issued 4/10/79.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
737-214; T.C. A16WE	SA856CE-D	Installation of two Collins 618T-2 HF radio systems - installation of Bendix "X" band weather radar system - installation of Kollsman Air Data computer. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
737-214; T.C. A16WE	SA1825WE	Installation of Henry Engineering Co. Lounge Tables No. 17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90307
737-222; T.C. A16WE	SA1601WE	Modification of Collins FD109 flight director systems to add a "steering" and "airspeed-hold" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2097WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2182WE	Installation of Bendix Third Attitude Indicator (per requirements of FAR 121.305(j)). Issued 6/10/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2232WE	Replacement of nickel-cadmium battery with 2 lead-acid batteries. Amended 1/29/76.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2529WE	Installation of interior arrangement. Amended 12/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3038WE-D	Replace one first class seat assembly with carry-on baggage module, relocate existing garment bag module and remove LH and RH class divider allowing the two modules to serve as class dividers. Issued 1/26/77.	WE	80500	United Air Lines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3360WE-D	Conversion of passenger cabin from 8/85 dual class configuration to 103 seat all coach configuration. Issued 1/5/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3579WE-D	Installation of Arinc Communications Addressing and Reporting System (ACARS). Amended 8/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3986WE-D	Installation of 113-passenger, all-coach seating configuration. Issued 5/30/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3987WE-D	Remove existing galleys, coatrooms and windscreens. Install WAPCO galleys and stowage/service centers. Install a 125-passenger all-coach seating configuration. Issued 7/11/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3988WE-D	Installation of new overhead stowage compartments, ceiling and sidewall panels and lighting systems. Issued 7/11/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222C; T.C. A16WE	SA2372WE	Installation of Satco, Inc. cargo pallet assembly P/N 31098-501 in conjunction with NAS 3610-2920, -2B5M, and 1P2N net assemblies. Issued 7/1/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
737-247; T.C. A16WE	SA191NW	Installation of modified two passenger seat and underseat baggage restraint. Issued 6/15/75.	NW	08350	Air Repair, Inc. 811 West Perimeter Road Renton, WA 98055
737-247; T.C. A16WE	ST55180	Manufacture and installation of P/N 10816 coat closet unit. Issued May 1978.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST55280	Manufacture and installation of P/N 10815 cart stowage unit. Issued May 1978.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
737-247; T.C. A16WE	ST567SO	Manufacture and installation of P/N 10949-1 RH aft galley (FS 991.09-1023.25). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST568SO	Manufacture and installation of P/N 10948-1 RH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST569SO	Manufacture and installation of P/N 10950-1 LH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-248C; T.C. A16WE	SA2129WE	Installation of Brownline Division cargo pallet assembly 41121101 and cargo net assembly 41119101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-248C; T.C. A16WE	SA2130WE	Installation of Brownline Division cargo pallet assembly 41120101 and cargo net assemblies: Brownline 22361-51, 22178-51, 41122101, 41123101, AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-275C; T.C. A16WE	SA233NW	Installation of cargo handling equipment for three forward cargo pallet positions. Issued 10/24/75.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737-293; T.C. A16WE	SA2007WE	Installation of header and drape.	WE	62080	Pacific Airmotive Corporation, Inc Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91503
737-293; T.C. A16WE	SA2960WE	Installation of galley module in Nordskog galleys P/N's 897 and 898. Issued 12/31/74.	WE	61529	Neushul Corporation 1911 West 139th Street Gardena, CA 90249
737-293; T.C. A16WE	SA3197WE	Installation of auxiliary stowage compartment. Issued 8/17/76.	WE	04080	Air California P.O. Box 2678, Airport Station Oakland International Airport Oakland, CA 94614
747 Series; T.C. A20WE	SA41GL	Install Brooks & Perkins cargo container P/N 17609-E-100. Reissued 2/2/76.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA44NW	Installation of cargo containers. Amended 11/16/76.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747 Series; T.C. A20WE	SA47GL	Install cargo container P/N 17617-E-100. Amended 7/14/75.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA48GL	Install cargo container P/N 17630-E-100. Issued 4/19/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA108NW	Installation of Mark IV visual entertainment system. Issued 4/26/74.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
747 Series; T.C. A20WE	SA139GL	Install Brooks & Perkins cargo container, P/N 17701-E-100. Issued 10/21/76.	GL	17750	Brooks & Perkins 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA255NW	Installation of Xenon light modification in visual entertainment system. Issued 1/26/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
747; T.C. A20WE	SA508NW	Installation of class divider/coat closet assembly. Issued 8/29/77.	NW	48532	KME Manufacturing Company 849 Seneca, S.W. Renton, WA 98055
747 Series; T.C. A20WE	SA689CE	Installation of Brooks & Perkins cargo container, P/N's 17026-100, Type A; 17026-100-1, Type A; and 17083-100, Type A. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA692CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747 Series; T.C. A20WE	SA694CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA702CE	Installation of Bendix standby horizon indicator and inverter.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
747 Series; T.C. A20WE	SA711CE	Installation Brooks & Perkins cargo container.	GL	17750	Brooks & Perkins, Inc. 1950 West Fort Street Detroit, MI 48216
747 Series; T.C. A20WE	SA792CE	Make and install P/N 17455-100 cargo container. Issued August 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747; T.C. A20WE	SA835NW	Installation of storage units at station 617. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA836NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA837NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747 Series; T.C. A20WE	ST867SO	Installation of Bendix ground proximity warning system. Issued 11/4/75.	SO	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
747 Series; T.C. A20WE	SA1435SW	Refrigerated air cargo container for lower lobe. Issued 2/24/72.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA1780SW	Portable solid oxygen system. Issued 1/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
747 Series; T.C. A20WE	SA2334SW	LD-3 cargo container, P/N DCT 1250. Issued 7/20/76.	SW	04250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74115
747 Series; T.C. A20WE	SA2756WE	Modify aircraft by installation of Hermes refrigerated LD-3 cargo container, Koolflite P/N 1000. S/N 8-3-001 only. Issued 9/6/73.	WE	42120	Hermes Enterprises P.O. Box 5141 Sherman Oaks, CA 91413
747 Series; T.C. A20WE	SA2801SW	Install container baggage/freight LD-3 type. Issued 6/19/78.	SW	04250	Air Cargo Equipment Corp. P.O. Box 15630 Tulsa, OK 74112
747 Series; T.C. A20WE	SA3041WE-D	Replacement of NAS3610-2L1C cargo containers with L size pallets and nets. Issued 7/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747SP; T.C. A20WE	SA285GL	Install MAPCO Model 1550 low boy galley. Amended 1/10/79.	GL	54700	Mansfield Aircraft Products Co. Mansfield Lahm Airport Mansfield, OH 44901
747-21; T.C. A20WE	SA34NE	Installation of Aerospace Div. U.O.P. Inc., main deck closet assembly, P/N 402490-1. Issued 4/18/80.	NE	81120	U.O.P., Inc. Aerospace Division Route 202 Bantam, CT 06750
747SP-21; T.C. A20WE	SA1079EA-D	Installation of flight attendant crew berth compartment in the main cabin, zone "B" aft end. Amended 4/17/79.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
747SP-21, -121 (all except N659PA); T.C. A20WE	SA1080EA-D	Installation of Delco F130A performance management system. Amended 8/30/80.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
747SP-27; T.C. A20WE	SA1174EA	Installation of 16mm movie system in zone B cabin. Issued 10/30/79.	EA	44000	Inflight Motion Pictures Division of Inflight Services, Inc. 175-28 148th Avenue Jamaica, NY 11434
747-2F6B; T.C. A20WE	SA4072WE	Installation of a video projection system. Issued 1/16/80.	WE	15375	Bell and Howell Company Avicom Division 360 Sierra Madre Villa Pasadena, CA 91109

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-E4A, -E4B; T.C. A20WE	SA307GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500. Issued 5/2/79.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
747-SP44, 747-244B; T.C. A20WE	SA3740WE	Installation of main dock cargo/baggage system. Issued 4/19/79.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-E4A, -E4B; T.C. A20WE	SA2951WE	Installation of Steward Davis Airstairs P/N 77004. Amended 3/23/78.	WE	33770	E - Systems, Inc. Greenville, Division P.O. Box 1056 Greenville, TX 75401
747-100; T.C. A20WE	SA817EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A300-001-101. Amended 3/9/71.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA824EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A400-001-101. Reissued 9/8/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA835EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A401-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA842EA	Installation of Goodyear Aerospace Corp. Universal lower deck baggage/cargo container P/N 625A402-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA2117WE	Installation of 747 lower deck modular and unitized baggage/cargo containers.	WE	84750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
747-100; T.C. A20WE	SA2222WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp. Net Assembly 40234-10, and net assemblies approved to NAS 3610-2AM and NAS 3610-2A3M. Issued 8/16/70.	WE	70250	Satco, Incorporated 1509 El Segundo Boulevard El Segundo, CA 90245
747-100; T.C. A20WE	SA2708WE	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-103. Issued 6/7/73.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747-100 Series; T.C. A20WE	SA3547WE	Installation of cargo container P/N 025-45571	WE	25970	Continential Airlines 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
747-100 Series; 747-200 Series; T.C. A20WE	SA976CE-D	Fuselage structure and related modification for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA977CE-D	Interior modifications for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA978CE-D	Cargo handling and power drive system. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series; 747-200 Series; T.C. A20WE	SA2646WE	Installation of lock assembly No. 41853-101, -102, -103, -201, -202, -203, -204, -301, -302, -303, -304. Amended 4/20/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200 Series; T.C. A20WE	SA3758WE	Installation of forward and aft lower cargo compartment door sill restraint fittings. Issued 10/9/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, 747-200 Series; T.C. A20WE	SA3813WE	Installation of Brownline side restraint, P/N 44981-101. Issued 12/20/78.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Boulevard Torrance, CA 90505
747-100, -200B; T.C. A20WE;	SA2446WE	Installation of Brownline single pallet lock assembly. Amended 1/3/75.	WE	79500	Tridair Industries Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200B; T.C. A20WE	SA2801WE	Installation of main deck cargo restraint system. Issued 1/16/74.	WE	79000	Transequip Inc. 180 N. Aviation Boulevard El Segundo, CA 90245

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-100, -200B; T.C. A20WE	SA3424WE	Installation of BMA main deck baggage container, P/N 302928. Issued 6/9/77.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-100, -200B, -200C, -200F; T.C. A20WE	SA2845WE	Installation of logo light assembly. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
747-100, -200B, -200C, -200F; T.C. A20WE	SA2895WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100, -200B, -200C, -200F; T.C. A20WE	SA2962WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 12/16/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100 Series, 747-200C, 200F Series; T.C. A20WE	SA3074WE	Installation of 96 x 125 inch animal containers. Amended 11/30/77.	EA	72770	J.D. Smith Air Export, Inc. One World Trade Center Suite 2161 New York, NY 10048
747-100, -200B, -200C, 747SP, 747SP; T.C. A20WE	SA3480WE	Installation of Hughes passenger entertainment/passenger service multiplex system. Issued 11/3/77.	WE	43330	Hughes Aircraft Company Microelectronics Products Div. 500 Superior Avenue Newport Beach, CA 92663
747-100, -200B, -200C, 747SP, 747SP Series; T.C. A20WE	SA3511WE	Installation of stretcher carrier P/N AM2003. Issued 3/21/78.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
747-100, -200B, -200C, -200F; T.C. A20WE	SA3630WE	Installation of Transequip, Inc. auto transponder assembly, P/N 303500. Issued 3/2/78.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-121; T.C. A20WE	SA503EA-D	1) Add additional first class passenger seats and class divider. 2) Add two additional coat closets in Zone C. Issued 5/11/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
747-121; T.C. A20WE	ST714SO-D	Installation of NASA aircraft-to-satellite data acquisition relay (ASDAR) system. Amended 12/14/77.	WE	62300	Pan American World Airways, Inc. J.F.K. International Airport Jamaica, NY 11430
747-121; T.C. A20WE	SA809EA	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-121; T.C. A20WE	SA869EA	Installation of carry-on luggage containers. Issued 4/2/71.	NE	81120	Aerospace Division Universal Oil Products Company Bantam, CT 06750
747-121; T.C. A20WE	SA936EA	Installation of expanded digital flight data recorder system. Amended 4/13/73.	EA	62300	Pan American World Airways Pan Am Building New York, NY 10017
747-121; T.C. A20WE	SA1077EA-D	Installations of Delco F130A flight management system. Amended 8/14/79.	EA	62300	Pan American World Airways, Inc. J.F.K. International Airport Jamaica, NY 11430
747-121; T.C. A20WE	SA2466WE	Installation of AiResearch P/N 216001-401 and -402 class divider - bulkhead assembly. Issued 1/13/72.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121; T.C. A20WE	SA2706WE	Modification by installation of AiResearch coat closed P/N 2130091. Issued 5/30/73.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121; T.C. A20WE	SA3494WE	Installation of Weber Aircraft auxiliary galley, P/N 822767. Issued 9/22/77.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-121, 747-123; T.C. A20WE	SA2444WE	Installation of tables without association with a seating arrangement. Amended 4/27/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
747-121, -122, -238B; T.C. A20WE	SA2823WE-D	Installation of equipment required to conduct NASA/UAL global air sampling program. Amended 11/25/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-121, -123, -273C; T.C. A20WE	SA3007WE	Installation of cargo pallet assembly, P/N 31250-521. Amended 11/19/75.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-121, -132; T.C. A20WE	SA2624WE	Interior arrangement modification. Amended 4/27/78.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121, 747-132; T.C. A20WE	SA3550WE	Installation of Weber auxiliary galley, P/N 822767 Amended 6/1/78.	WE	84900	Weber Aircraft Div. of Walter Kidde & Co., Inc. 2820 Ontario Street Burbank, CA 91510
747-122; T.C. A20WE	SA2193WE	Installation of entree cart 802000, tray cart 803000, liquor cart 804000, and waste cart 805000. Amended 9/2/71.	WE	34220	Fairchild Hiller Corporation Stratos-Western Division 1800 Rosecrans AVenue Manhattan Beach, CA 90266
747-122; T.C. A20WE	SA2658WE	Modification of lower deck cargo compartment restraint system. Issued 3/14/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2717WE	Installation of interior arrangement. Issued 6/26/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2750WE	Modification of aircraft for installation of spacer pallets. Issued 9/7/73.	WE	80500	United Air Lines, Inc. Maint. Base, Engineering Dept. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2821WE-D	Installation of additional service cart retractable tiedowns. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2822WE-D	Modified cabin interior configuration. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2829WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3352WE-D	Reduced first class seating to 26 seat places, relocated class divider, installed 10-across coach seating - 348 coach seat places. Issued 11/14/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3581WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 11/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3942WE-D	Rework of high frequency communications system to install single-sideband capability. Issued 3/27/80.	WE	80500	United Airlines, Inc. San Francisco Int'l. Airport San Francisco, CA 94128
747-122, -123; T.C. A20WE	SA3066WE	Installation of lower lobe food service modules, P/Ns 819720 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-123; T.C. A20WE	SA2926WE	Modification to incorporate cargo restraint system P/N 43830, configuration -101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-123; T.C. A20WE	SA2928WE	Installation of carrier aircraft crew galley Model FTL 47-1 in the upper lounge. Issued 9/6/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
747-123; T.C. A20WE	SA3016WE	Installation of Brownline cargo systems 44297-101 and 44297-102. Issued 5/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-127; T.C. A20WE	SA2972WE	Modification of lower deck aft cargo compartment restraint system to accommodate NAS 3610 Size A aircraft unit load devices. Issued 12/27/74.	SW	17075	Braniff International Exchange Park Dallas, TX 75235

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-128; T.C. A20WE	SA3436WE	Installation of Brownline cargo system 45600-102. Issued 6/21/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-131; T.C. A20WE	SA715CE	Installation of aircraft integrated data system. Amended 12/12/77.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA728CE	Installation of Hamilton Standard TAT/EPRL System.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA877CE	Installation of expanded parameter flight recorder. Amended April 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA2411WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90248
747-131; T.C. A20WE	SA2755WE	Modification of aircraft for installation of 13-inch beverage carts. Issued 9/4/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-131; T.C. A20WE	SA3091WE	Installation of Brownline cargo system 45747-101. Issued 9/27/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-132; T.C. A20WE	SA3381WE	Installation of Brownline lower lobe cargo system, No. 45478-101. Issued 4/11/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-132; T.C. A20WE	SA3446WE	Installation of Browline cargo system 45600-101. Issued 7/5/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-133; T.C. A20WE	SA1443CE-D	Installation of Type I door, extension of upper deck and interior reconfiguration. Issued 5/20/80.	CE	16878	Boeing Military Airplane Company 3801 South Oliver Wichita, KS 67210
747-135; T.C. A20WE	ST505SO	Manufacture of Nordskog storage units in accordance with Nordskog drawings 1-209, Rev. B and 1-210, Rev. B and their installation in accordance with NAL E.O. P-2350-01 and P-2350-00-06, Rev. B respectively. Issued 5/23/72.	SO	61220	National Airlines, Inc. Box 2055, Airport Mail Facility Miami, FL 33159
747-135, -151, -251B, -251F; T.C. A20WE	SA903GL	Installation of Bendix GPW-83 ground proximity warning system. Amended 6/8/76.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
747-136; T.C. A20WE	SA1144EA	Installation of movie screens in upper deck and 'B' cabin. Issued 4/27/79.	EA	4400	Inflight Motion Pictures, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-136; T.C. A20WE	SA1145EA	Installation of 16 mm movie pallet in 'B' cabin. Amended 3/31/80.	EA	44000	Inflight Motion Picutres, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-136; T.C. A20WE	SA1438CE-D	Installation of a Type I door in the left-hand side of the upper deck fuselage. Amended 11/9/79.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-151, -251B; T.C. A20WE	SA2783WE	Installation of wheeled refrigerated module, P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-200 Series; T.C. A20WE	SA3659WE	Installation of Litton LTN-72R INS/RNAV and/or LTN-72 INS navigation systems in a triple configuration. Issued 6/21/78.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
747-200B, -200C; T.C. A20WE	SA983EA	Installation of Super 8mm IMPAK projector assemblies, P/N's 10304 ("A" Compartment) and 10306 ("C-D-E" Compartment). Issued 6/18/74.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-200F; T.C. A20WE	SA190NW	Installation of 29th position pallet/container kit. Issued 6/10/75.	NW	95142	Western Gear Corporation Flight Structures Division 2100 Norton Everett, WA 98201
747-206B; T.C. A20WE	SA1442CE-D	Installation of Type I door, left side, upper deck fuselage. Issued 10/25/79.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-212B; T.C. A20WE	SA4093WE	Installation of passenger interior arrangements. Amended 8/22/80.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
747-221F, -246F, -249F; T.C. A20WE	SA3304WE	Installation of Brownline Cargo System No. 45102-101, -103 and -301. Amended 4/26/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Iomita Boulevard Torrance, CA 90505
747-221F; T.C. A20WE	SA4001WE	Installation of Brownline pallet restraint system, P/N 46484-103 and -104. Issued 8/14/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Iomita Boulevard Torrance, CA 90505
747-237B; T.C. A20WE	SA1444CE-D	Installation of type I door (left side, upper deck fuselage) extension of upper deck and interior reconfiguration. Issued 7/25/80.	CE	16878	Boeing Military Airplane Company 3801 South Oilver Wichita, KS 67210
747-238B; T.C. A20WE	ST565SO	Lower lobe right hand module unit, P/N 10892-1 left hand module unit P/N 10893-1 and -101, and lower lobe cupboards unit P/N 68878-1 and -101. Amended 7/1/76.	SO	81130	Aerospace Division of UOP 4956 Victor Street Jacksonville, FL 32207
747-238B; T.C. A20WE	SA570EA	Installation of Universal Oil Products tray cart modules P/Ns 68878, 68879, 68880 in Boeing Model 747-238B. Issued 8/31/71.	NE	81120	Aerospace Division Universal Oil Products Company Bartam, CT 06750
747-238B; T.C. A20WE	SA2393WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargo pallet assembly P/N 24076-51 and NAS 3610-2A4P pallet. Issued 8/10/71.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-238B; T.C. A20WE	SA3868WE	Installation of Brownline cargo system 44297 configuration - 104. Issued 1/25/80.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 Lomita Boulevard Torrance, CA 90505
747-245F; T.C. A20WE	SA1032EA	Installation of Collins FPC-75 ground proximity warning system. Amended 3/20/76.	EA	70600	Seaboard World Airlines Seaboard World Building JFK International Airport Jamaica, NY 11430
747-249F; T.C. A20WE	SA4040WE	Installation of Brownline lower compartment cargo pallet restraint system, P/N 45478-102. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-249F; T.C. A20WE	SA4052WE	Installation of Brownline cargo system, 45600-103. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-257B; T.C. A20WE	SA2307WE	Installation of drink trolly 744000. Reissued 8/3/71.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-258B; T.C. A20WE	SA891EA	Installation of inflight motion picture system. Amended 1/11/72.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11424
747-284B; T.C. A20WE	SA2791WE	Modification of airplane lower deck aft cargo compartment restraint system. Issued 12/10/73.	EU	61797	Olympic Airways S.A. 96, Syngrov Avenue Athens, Greece
Miscellaneous	SA4-1210	Bonnex cover on aircraft surfaces.	WE	33500	Bonair, Inc. Route 1, Box 632 Bakersfield, CA 93308

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BOEING AIRPLANE CO., WICHITA DIVISION

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
75 Series; T.C. 743	SA3-600	Fuselage alteration. (Restricted category only.)	CE	17030	Boyde Aircraft Company P.O. Box 321 Caruthersville, MO 63830
75 Series; T.C. 743	SA4-225	Removable metal fuselage panels.	WE	61194	National Aircraft Corporation 15001 Oxnard Street Van Nuys, CA 91408
75 Series; T.C. 743	SA4-227	Eonite covering on wings and ailerons.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
75 Series; T.C. 743	SA4-326	Aerial dust and spray equipment.	WE	79250	Transland Aircraft, Inc. 2823 190 Street Redondo Beach, CA 90277
75 Series; T.C. 743	SA4-347	Installation of modified BT-13 engine mount.	RM	15300	Ed Beegles Aircraft Service Co. 921-22nd Street Greeley, CO 80631
75 Series; T.C. 743	SA4-401	Tail wheel trunnion. (Restricted category only.)	WE	37078	Gail Aircraft Engineering Company Municipal Airport Sacramento, CA 95814
75 Series; T.C. 743	SA4-541	Eonite covering on elevators, rudder, and horizontal and vertical stabilizers.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
75 Series; T.C. 743	SA4-589	Installation of Swathmaster dispensing unit. Reissued 10/31/74.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
75 Series; T.C. 743	SA4-632	Tail wheel trunnion.	WE	30288	Don's Shop 3074 S. Elm Avenue Fresno, CA 93721
75 Series; T.C. 743	SA4-658	Replacement of wing compression members, Boeing 75-1134 and 75-1234.	WE	83000	Vern's Wing Shop Minter Field, Box 629 Bakersfield, CA 93308
75 Series; T.C. 743	SA4-667	Transland 3001 F.G. aerial dust and spray hopper installed. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
75 Series; T.C. 743	SA4-730	Impregnated glass cloth hopper-tank type PBC-F1, PBC-R1 or PBS-2.	WE	64430	Pickell & Bemis P.O. Box 1298 Brawley, CA 92227
75 Series; T.C. 743	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
75 Series; T.C. 743	SA4-889	Hydraulic spray rig retractable system. (Restricted category only.)	WE	03230	Agair, Inc. P.O. Box 335 Dos Palos, CA 93620
75 Series; T.C. 743	SA4-908	Pratt & Whitney R1340-AN1 engine and Hamilton Standard propeller 12D40-305/6101A-12 propeller. Amended 4/29/74.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA4-982	Quick-change clamping unit.	RM	22200	George Chisholm 317 13 Street Greeley, CO 80631
75 Series; T.C. 743	SA4-1089	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
75 Series; T.C. 743	SA4-1197	Control lock, locking rudder, elevator, and ailerons.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA4-1312	Hartzell HA-B3Z30-1/10160-6 ground adjustable propeller (on aircraft with Pratt & Whitney R-985 Series engines only).	WE	85124	West Coast Propeller Company 1101 Chestnut Street Burbank, CA 91500

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
75 Series; T.C. 743	SA4-1314	Combination hopper-tank.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA4-1326	Rudder modified.	WE	48534	Simon Kniff P.O. Box 907 Dos Palos, CA 93620
75 Series; T.C. 743	SA4-1391	Wings metal or fiberglas tip. (Restricted category only.)	WE	12550	Atwood Aviation, Inc. 236 Gail Street Salinas, CA 93901
75 Series; T.C. 743	SA4-1568	Carburetor air intake cleaner. (Eligible on aircraft equipped with Pratt & Whitney R-985 Series engines.)	WE	73946	Spain-Air, Inc. P.O. Box 236 Dos Palos, CA 93620
75 Series; T.C. 743	SA8SW	Fabrication and installation of engine mount for Pratt & Whitney R-985 and R-1340 engines. (Restricted category only.)	SW	37089	Gardner Flyers, Inc. P.O. Box 836 Crystal City, TX 78839
75 Series; T.C. 743	SA26WE	Removable aluminum fuselage panels. (Restricted category only.)	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA34SW	Metal wing ribs and new wood spar (same as original spar). Reissued 10/3/77.	SW	83760	Vincent Aeronautical Covington-Vincent Airport Route 1, Box 677-A Covington, LA 70433
75 Series; T.C. 743	SA35SW	Engine mount assembly, shroud and cowling, oil tank, heat valve to carburetor air intake, and air filter for Pratt & Whitney R-985 engine. (Restricted category only.)	SW	46460	Johnny's Repair Service 709 Indiana Weslaco, TX 78596
75 Series; T.C. 743	SA36SW	Engine mount assembly.	SW	46460	Johnny's Repair Service 709 Indiana Weslaco, TX 78596
75 Series; T.C. 743	SA38SW	Pratt & Whitney R-1340 engine mount.	SW	72595	Skyways, Inc. Kaplan, LA 70548
75 Series; T.C. 743	SA98WE	Modified wing panels. Amended 11/11/74.	WE	83000	Vern's Wing Shop 5032 Airport Drive Bakersfield, CA 93308
75 Series; T.C. 743	SA104SW	101 engine mount for installation of Pratt & Whitney R-985 or R-1340 engine.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
75 Series; T.C. 743	SA191SW	Upper and lower wing spans increased by 15-inch extension on each side. Reissued 10/3/77.	SW	83760	Vincent Aeronautical Covington-Vincent Airport Route 1, Box 677-A Covington, LA 70433
75 Series; T.C. 743	SA206SW	Molded fiberglas fuselage covering. (Restricted category only.)	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
75 Series; T.C. 743	SA210SW	Consolidated-Vultee BT-13 engine mount assembly modification by welding finger plates and gussets.	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
75 Series; T.C. 743	SA220SO	Tow bar, release mechanism, and safety tow link.	SO	37092	Gasser Banners, Inc. P.O. Box 3502 Metropolitan Airport Nashville, TN 37217
75 Series; T.C. 743	SA266SW	Engine mount M1 for Pratt & Whitney R-985 or R-1340 engine installation. Reissued.	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
75 Series; T.C. 743	SA275SO	Automotive type master cylinders.	SO	30360	Dothan Aviation Corporation Municipal Airport Dothan, AL 36301
75 Series; T.C. 743	SA284CE	Wheel fairings.	CE	59315	Mid-Continent Aerial Sprayers P.O. Box 307 Hayti, MO 63851
75 Series; T.C. 743	SA293SO	Wing modifications.	SO	59740	Mississippi State University Aerophysics Department State College, MS 39762
75 Series; T.C. 743	SA331NW	Installation of automatic flagman. Issued 10/6/76.	NW	03500	Air Ag, Inc. City-County Airport Walla Walla, WA 99362

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
75 Series; T.C. 743	SA353CE	DD985 engine mount for use with Pratt & Whitney R-985 engine or DD 1340 engine mount for use with Pratt & Whitney R-1340 engine.	CE	28400	D & D Aero Spraying, Inc. R.F.D. 1 Rantoul, KS 66079
75 Series; T.C. 743	SA365WE	Trim tab elevator cables and pulleys relocated.	WE	60162	Moore Aviation, Inc. P.O. Box 868 Tulare, CA 93274
75 Series; T.C. 743	SA409WE	Clean air filter assembly. (Restricted category only.)	WE	37091	Garriott Crop Dusting, Inc. 909 Mt. Lassen Lane Bakersfield, CA 93300
75 Series; T.C. 743	SA491CE	Install two Wagner FC-6086 brake system master cylinders.	CE	59315	Mid-Continent Aircraft Corp. Mid-Continent Maintenance Div. Drawer "L" Hayti, MO 63851
75 Series; T.C. 743	SA493CE	Install starter system for use with auxiliary power supply.	CE	59315	Mid-Continent Aircraft Corp. Mid-Continent Maintenance Div. Drawer "L" Hayti, MO 63851
75 Series; T.C. 743	SA575SW	Tail surface modified.	SW	34400	Farm Air Service P.O. Box 68 Nome, TX 77629
75 Series; T.C. 743	SA607WE	75-000 wings.	WE	08354	Airspray Manufacturing Corp. 11841 S. Henderson Caruthers, CA 93609
75 Series; T.C. 743	SA643SW	Engine mount assembly for Jacobs R-755 engines.	SW	77760	Tedder Aviation Corporation P.O. Box 5 Texarkana, TX 75501
75 Series; T.C. 743	SA720WE	Wings. Reissued 8/13/75.	NW	19620	J.W. Calley P.O. Box 156 Nezperce, ID 83543
75 Series; T.C. 743	SA733SW	Engine and oil cooler mounts.	SW	68380	Roane Flying Service P.O. Box 2397 West Helena, AR 72390
75 Series; T.C. 743	SA734SW	Center section mounted instrument panel.	SW	68380	Roane Flying Service P.O. Box 2397 West Helena, AR 72390
75 Series; T.C. 743	SA746SW	Fiberglas fuselage and fairings.	SW	68380	Roane Flying Service, Inc. P.O. Box 2397 West Helena, AR 72390
75 Series; T.C. 743	SA1073SW	Fiberglass fuselage skin. Issued 5/18/70.	SW	35200	Fiberglsss Specialties 5845 Clementshire Houston, TX 77017
75 Series; T.C. 743	SA1208WE	Steel aileron actuating fitting replacement for Boeing P/N 75-1417.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
75 Series; T.C. 743	SA1269WE	Modified rudder.	WE	30288	Don's Shop 3074 S. Elm Avenue Fresno, CA 93706
75 Series; T.C. 743	SA1270WE	AGAR squared wings. Reissued 8/13/75.	NW	19620	J.W. Calley P.O. Box 156 Nezperce, ID 83543
75 Series; T.C. 743	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
75 Series (All 75 Series Models on T.C. A-743); A75N1; T.C. A-743, 743	SA2269WE	Installation of modified wheels and brakes. Issued 10/23/70.	WE	41640	Milton Heemstra P.O. Box 1061 Dos Palos, CA 93620
75 Series (All 75 Series Models on T.C. A-743); A75N1; T.C. A-743, 743	SA1008WE	Installation of Poly-Fiber covering material (wings). Amended 8/7/69.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92502
A75N1; T.C. A-743	SA4-144	Installation of Pratt & Whitney R-985 engine and conversion of airplane to duster. Reissued 3/11/70.	EA	25780	Conair Aviation, Ltd. P.O. Box 220 Abbotsford, British Columbia Canada

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A75N1; T.C. A-743	SA15NE	Installation of Curtiss-Reed Model 55501-5 propeller in accordance with Curtiss installation and maintenance instructions, Pub. S-120-647, on aircraft equipped with Continental W-670-6N engine. Issued 4/14/77.	EA	58635	Robert B. Meyersburg 6321 Tone Court Bethesda, MD 20034
75, A75, B75, A75N1, B75N1; T.C. 743	SA4-919	Modified wing. Amended 9/25/73.	WE	73000	Leo F. Smith & Company, Inc. 225 South Bent San Marcos, CA 92069
75, A75, B75, E75, A75J1, A75N1, B75N1, D75N1; T.C. 743	SA1053CE	Install spring steel landing gear. Issued November 1974.	CE	03160	Aero Wide Tract 1250 North Lakeview Derby, KS 67037
75, A75, B, E, A75J1, A75N1, B-, D-, 1B75A, E75N1; 377; T.C. 743, 812	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A75L3, 75, A75, B75, E75, A75J1, B75N1, D75N1, IB75A, E75N1; T.C. 743	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
A75L3, 75, A75, B75, E75, A75J1, A75N1, B75N1; T.C. 743	SA4-1357	Sellers small Swathmaster dust and spray dispensing equipment. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
75, A75, B75, A75N1, B75N1; T.C. 743	SA4-1456	Installation of Transland 230-gallon hopper. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
A75L3, 75, A75, B75, E75, A75J1, A75N1, B75N1, D75N1; T.C. A-743	SA1703WE	Installation of Serv-Aero four aileron system. Issued 3/24/70.	WE	71080	Serv-Aero Engineering, Inc. Salinas Municipal Airport Salinas, CA 93901
A75L3, 75, A75, B75, E75, A75J1, A75N1, B75N1, D75N1; T.C. A-743	SA1540WE	Installation of Pratt & Whitney R-985-AN-1 engine, Hamilton Standard 2D30/6101A-12 propeller, modified fuel and oil systems.	WE	71000	Serv-Aero Engineering, Inc. Salinas Municipal Airport Salinas, CA 93901
A75L3, 75, A75, B75, E75, A75J1, A75N1, B75N1, D75N1; T.C. A-743	SA2188WE	Installation of JAS No. 1 moveable canopy on 75 series aircraft modified by FAA approved hopper installation in lieu of front seat and with Pratt & Whitney R-985 engine installed. Issued 7/9/70.	WE	46790	Johnston Aircraft Service P.O. Box 757 Tulare Airpark Tulare, CA 93274
A75L3, 75, A75, B75, E75, A75J1, A75L300, A75N1, B75N1, D75N1, IB75A, E75N1; T.C. 743	SA2666WE	Complete aircraft covering of Ceconite 102 material. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
E75 (Navy N2S-5); T.C. A-743	SA361GL	Installation of sheet metal skin on fuselage, BT-13 wheels and brakes, fiberglass wheel fairings, D-18/C45 engine cowling and prop spinner, and electrical system. Issued 12/10/79.	GL	67018	Reed's Aircraft Restoration Peter B. Reed Box 38 West Chester, OH 45069
875; T.C. 743	SA575CE	Install Lycoming R-680-E3B engine and Hamilton Standard propeller 2B20/6135A-9.	GL	79590	Trim-A-Plane Service Detroit City Airport Detroit, MI 48213

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BRITISH AEROSPACE, AIRCRAFT GROUP

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH-125; T.C. A3EU	SA350NW	Installation of nose taxi lights. Issued 9/3/76.	NW	60181	Morrison-Knudson Company P.O. Box 7808 Boise, ID 83729
DH-125; T.C. A3EU	SA386NW	Modify all navigation to accept Grimes light mounted in Lord tail light bracket. Issued 12/14/76.	NW	60181	Morrison-Knudson Company P.O. Box 7808 Boise, ID 83729
DH.125 Series; T.C. A3EU	SA4147SW	Install 1, 2, or 3 place side facing seat, frame only. Issued 6/30/80.	SW	28000	Custom Aircraft Conversions 234 West Turbo Drive San Antonio, TX 78216
DH.125, BH.125; T.C. A3EU	SA16GL	Incorporating AMF (Leland) inverters MGE 23-400 or MGE-23-413. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
DH.125, HS.125, BH.125; T.C. A3EU	ST1030SC	Replace existing lead-acid type battery with Teledyne Gill BB639/TE series lead-acid type batteries. Amended 1/18/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
DH.125-1A; T.C. A3EU	SA235EA	Interior bulkhead and door at fuselage station 260.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA236EA	Interior bulkhead and door at fuselage station 391.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA237EA	Two-place seat.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA238EA	Baggage compartment smoke detector system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA239EA	Automatic flight control system. Amended 6/27/67.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
DH.125-1A; T.C. A3EU	SA289EA	Bulkhead and door at fuselage station 391.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA341EA	Bulkheads and bulkhead door. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA342EA	Seat track extensions, inboard and outboard.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA354EA	Bulkheads and bulkhead door. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA366EA	Bulkhead and bulkhead door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA399EA	Bulkhead and door at fuselage station 258-260. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA432EA	Hydra-electric fuel filter differential pressure switch.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA434EA	Performance of Category II equipment and systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA435EA	Combined ASI/machmeter.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH.125-1A; T.C. A3EU	SA601EA	Installation of Astek BO 200-81123 combined ASI/machmeter.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A; T.C. A3EU	SA858WE	Environmental control system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A; T.C. A3EU	SA859WE	Air conditioning primary feed duct.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A; T.C. A3EU	SA860WE	Pressurization control system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A; T.C. A3EU	SA956WE	SP-40B automatic flight control system.	WE	74570	Sperry Phoenix Company P.O. Box 2529 Phoenix, AZ 85000
DH.125-1A; T.C. A3EU	SA958WE	Supplemental exterior lighting.	GL	42626	Donald E. Hoskins, Inc. 4980 Marine Drive Chicago, IL 60607
DH.125/1A; T.C. A3EU	SA1142WE	Jump seat. Amended 4/9/69.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125/1A; T.C. A3EU	SA1147SW	Main landing gear doors. Issued 5/25/70.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78216
DH.125/1A; T.C. A3EU	SA1166WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DH.125/1A; T.C. A3EU	SA1167WE	System installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH. 125-1A, -3A; T.C. A3EU	SA1176EA	Installation of Solar T-62T-40C APU when Garrett AiResearch TFE-731-3-1H engines are installed in accordance with STC SA3925WE. Amended 6/27/80.	EA	73275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH 125-1A/521, 522, DH 125-3A/522; T.C. A3EU	SA1358WE	Installation of combined air-speed and machmeter indicator. Amended 3/3/69.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH 125-1A/522; T.C. A3EU	SA487EA	Installation of bulkhead and door at fuselage station 263 13/16.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH 125-1A/522, -3A; T.C. A3EU	SA486EA	Installation of Bendix radio altimeter antennas.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA335EA	Installation of Collins Radio Altimeter Antennas P/N 437X-1. Amended 5/23/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA385EA	Installation of glide slope antenna at fuselage station 114. Amended 7/1/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA386EA	Installation of HF antenna. Amended 7/1/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA440EA	Installation of ADF sense antenna. Amended 4/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA442EA	Installation of bulkhead and bulkhead door at fuselage station 391.5. Amended 3/12/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA484EA	Installation of under seat deck avionics equipment shelf. Amended 5/25/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA536EA	Installation of Dorne & Margolin DMN 4-7 VOR/LOC antenna. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA543EA	Installation of Bendix PB-60 automatic flight control system. Amended 11/9/71.	EA	16010	The Bendix Corporation Navigation and Control Division Teterbora, NJ 07608

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA; T.C. A3EU	SA716EA	Installation of Sonotone CA9 Nickel Cadmium batteries. Amended 1/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -3A/RA, -1A/S-522, -400A, BH.125-400A, -600A; T.C. A3EU	SA717EA	Installation of Compudex, Inc. model automatic fuel range computer. Amended 10/3/75.	EA	25760	Compudex, Inc. P.O. Box 93 Norristown, PA 19404
DH.125-1A, -1A/522, -1/R-522, -3A, -3A/R, -1A/S-522, -400A; T.C. A3EU	SA826EA	Replacement of lead-acid batteries with sonotone nickel-cadmium batteries. Issued 6/3/70.	EA	13185	Aviation Aids and Technical Service Company P.O. Box 515 Montreal Int'l Airport Montreal 300, P.Q. Canada
DH.125-1A, -1A/522, -1A/R-522, -1A/S-522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, -600A; T.C. A3EU	SA866EA	Installation of Grimes three light strobe kit P/N 34-0301-1. Amended 5/24/74.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
DH.125-1A, -1A/522, DH.125-A/R-522, DH.125-3A, DH.125-1A/S-522, DH.125-3A/RA; T.C. A3EU	SA872EA	Replacement of existing Leland inverter type MGE-23-400. Issued 4/21/71.	EA	15800	The Bendix Corporation Electric Power Division Eatontown, NJ 07724
DH-125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -1A/S-522, -3A/RA, -400A; T.C. A3EU	SA740CE	Install three each single phase solid state inverters, a paralleling control, and a warning control unit. Reissued 1/9/78.	CE	24450	Colt Electronics Company 137 West 9th Avenue N. Kansas City, MO 64146
DH-125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -1A/S-522, -3A/RA, -400, HS-125-600A; T.C. A3EU	SA1466CE	Installation of Phoenix Aerospace VR-1010-24-2AD voltage regulators. Issued 12/22/78.	CE	24450	Colt Electronics Company 137 WEst 9th Avenue North Kansas City, MO 64116
DH 125-1A, 1A/522, -1A/R-522, 1A/R-522-3A, -3A/R, -1A/S-522, -3A/RA, -400A, BH 125-400A, -600A, HS 125-600A, -700A; T.C. A3EU	SA2927WE	Installation of logo light on lower surface of horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DH.125-1A, -1A/522, -1A/S-522, -3A, -400A; T.C. A3EU	SA3382WE	Installation of a single-point pressure refueling system. Amended 6/13/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
DH.125-1A, -1A/522, -1A/3-522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, HS.125-700; T.C. A3EU	SA3551WL	Installation of either a single or dual Global GNS-500A VLF/OMEGA navigation system. Amended 6/20/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-1A, -1A/522, -3A, -3A/R, -3A/RA, -400A, BH.125-400A, -600A, -700A; T.C. A3EU	SA327EA	Installation of retractable seat. Amended 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
DH.125-1A, -1A/522, -1A/R-522, -3A, -3A/R, -1A/S-522, -3A/RA, -400A, -600A, -700A, BH.125-400A, -600A; T.C. A3EU	SA422GL	Installation of hydraulic system hoses. Issued 7/11/80.	GL	47630	K-C Aviation, Inc. Outagamie Airport Appleton, WI 54911
DH.125-1A, 3A, 3A/R, 3A/RA, 400A, HS-125-700A; T.C. A3EU	SA857WE	Installation of GTCP30-92 or GTCP30-92C auxiliary power unit. Amended 1/11/78.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DH.125-1A/522, DH.125 Series 3A, 3A/RA, 400A; T.C. A3EU	SA929EA	Installation of No. 2 battery isolation circuit. Amended 1/31/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-1A, -3A, -3ARA, DH.125-400A, BH.125-400A; T.C. A3EU	SA1002CE	Relocation of warning cancel switch from instrument panel to #1 engine power lever. Issued March 1974.	CE	15250	Beech Aircraft Corporation P.O. Box 85 Wichita, KS 67201
DH.125-1A/S-522, Series 3A; T.C. A3EU	SA3925WL	Installation of Garrett AiResearch TFE-731-3-1H engines and related changes. Amended 11/21/79.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH.125-1A/S-522-3A; T.C. A3EU	SA4030WE	Installation of Collins APS-80 autopilot. Amended 7/30/80.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
DH 125-1A, -3A, -400A, BH-125-400A; T.C. A3EU	SA4084SW	Pitot heat monitor system. Issued 2/20/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
DH.125-1A, -1A/522, -3A, -1A/R-522, -3A/R, -1A/S-522, -3A/RA, -400A, HS.125-600A, -700A, B.H.125-400A, -600A; T.C. A3EU	SA4188WE	Installation of IPECO pilot and co-pilot crew seats. Issued 7/16/80.	WE	54860	Marcon Associates, Inc. Suite 101 18436 Hawthorne Boulevard Torrance, CA 90504
DH.125-3A/RA; T.C. A3EU	SA602EA	Installation of bulkhead door and bulkhead at fuselage station 263 13/16.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA674EA	Installation of forward and aft bulkheads and doors.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779
DH.125-3A/RA; T.C. A3EU	SA679EA	Installation of bulkhead and bulkhead door at fuselage station 260.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA710EA	Installation of dual Bendix CB-60B compass system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA711EA	Installation of dual Bendix FD-60 flight director system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA712EA	Installation of Bendix 1903718-1 flight director monitor warning system. Amended 7/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA713EA	Installation of Bendix MKA-28C marker beacon receiver system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA714EA	Installation of dual Bendix RNA-26C VHF navigation system with 8RNX-26A glide slope receiver.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA719EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A/RA; T.C. A3EU	SA788EA	Installation of Bendix ALA-51A radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A, -3A/R, -3A/RA; T.C. A3EU	SA457EA	Installation of combined ASI/Machmeter. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH.125-3A, -3A/R, -3A/RA; T.C. A3EU	SA539EA	Installation of Collins 37P-5 glide slope antenna at fuselage station 114. Amended 4/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125, DH-125-400A; T.C. A3EU	SA355CE	Installation of Hoskins Twilighter Mk III/Mk IIIB high intensity lighting system. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
DH-125, DH-125-400A; T.C. A3EU	SA2404WE	Consolidation of STCs SA355CE and STC 362CE into one STC having MASTER ELIGIBILITY LIST - amended to include improved power supply assembly and subchassis timer assembly for Twilighter MK III high intensity supplementary lighting system. Issued 8/16/71.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
DH-125-400A; T.C. A3EU	SA764EA	Installation of interior furnishings and avionics systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA765EA	Installation of bulkhead and door between fuselage station 249.86 and fuselage station 281.79.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA766EA	Incorporation of entrance area installation.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH-125-400A; T.C. A3EU	SA767EA	Installation of forward cabin lavatory.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA768EA	Installation of a two place, side facing divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA769EA	Installation of Kollsman combined ASI/Machmeter A39469-10036.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA770EA	Installation of United Controls angle of attach system. Reissued 12/18/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA793EA	Installation of Litton skyphone system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA831EA	Installation of three Flite-Tronics PC-17 static inverters and one Jet Electronics & Technology, Inc. emergency power supply, Model PS-800. Issued 6/24/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA833EA	Installation of electric elevator trim system. Amended 4/12/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA1981WE	Installation of Sperry Model SP-40C automatic flight control system (P/N 1782874-512). Amended 11/28/69.	WE	74570	Sperry Slight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 95027
DH-125-400A; T.C. A3EU	SA2066WE	Category II system and equipment approval of Sperry Models SP-40 automatic flight control system P/N 1782874-512, and SPI-60 integrated instrument system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 85027
DH. 125-400A, BH. 125-400A; T.C. A3EU	SA1173EA	Rework of Solar T-62T-39 APU installed by STC SA674CE when Garrett AiResearch TFE-731-3-1H engines are installed. Issued 10/25/79.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125-400A, BH.125-400A; T.C. A3EU	SA3870WE	Installation of Garrett AiResearch TFE-731-3-1H engines and related changes. Issued 2/28/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, BH.125-400A; T.C. A3EU	SA4009WE	Installation of Collins APS-80 autopilot. Issued 8/9/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH 125 Series 400A, BH 125 Series 400A; T.C. A3EU	SA4116WE	Modification of a previously approved Microturbo APU Model 024 type "Saphir4" installation. Issued 3/10/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH-125-400A, BH-125-400A, DH125-1A/S-522; T.C. A3EU	SA4115WE	Installation of light dump baulk system. Issued 3/11/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, DH.125-3A/RA; BH.125-400A; T.C. A3EU	SA844EA	Installation of Teledyne Avionics angle of attack system. Reissued 7/1/76.	EA	78000	Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906
DH.125-400A, DH-125-3A/RA; BH.125-400A; T.C. A3EU	SA857EA	Installation of Microturbo, Inc. auxiliary power unit Model 024, type "Saphir 4." Amended 4/2/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; BH.125-400A, -600A, HS.125-700A; T.C. A3EU	SA674CE	Installation of Solar Model T-62T-39Y or -39 or -40C auxiliary power unit modifications. Amended 5/23/80.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH. 125-1A, -3A, -400A, HS. 125-600A, -700A, BH. 125-400A, -600A; T.C. A3EU	SA1175EA	Installation of access doors. Issued 11/19/79.	EA	73275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125, HS.125 Beechcraft; T.S. A3EU	ST1003SO	Replace existing lead-acid batteries with Gill BB638/T1-E lead acid batteries, part numbers BSI 200 left and BSI 200 right Issued 6/23/78.	SO	15100	The Battery Shop, Inc. P.O. Box 17312 Nashville, TN 37127

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH-125-400A, HS 125-600A; T.C. A3EU	SA786EA	Installation of lavatory door and bulkhead at station 392. Amended 7/19/76.	EA	07498	AiResearch Aviation Company 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779
BH125-400A; T.C. A3EU	SA1413SW	Three Flite-Tronics static inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
BH125-600A; T.C. A3EU	SA1888SW	Collins flight control system FCS-105. Issued 6/21/74.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
BH125-600A; T.C. A3EU	SA1923SW	Solar T62T-39 turbine auxiliary power unit. Issued 1/17/75.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
BH125-600A; T.C. A3EU	SA1948SW	Teledyne Avionics normalized angle of attack indicating system P/N 112B900. Amended 9/14/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
BH125-600A; T.C. A3EU	SA2271SW	Interior. Issued 10/27/76.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203
HBH/HS.125-600A, HS.125-700A; T.C. A3EU	SA1101EA	Installation of GNS-500A VLF/Omega system. Amended 5/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS.125-600A, BH.125-600A, HS.125-700A; T.C. A3EU	SA3705WE	Installation of Garret AIRNAV 200 or an AirNav 300 area navigation system. Amended 3/5/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA1074EA	Installation of bulkhead and door at F.S. 391.5 Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. 3EU	SA1075EA	Installation of forward baggage and avionics compartment. Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1104EA	Installation of oxygen system. Issued 6/7/78.	EA	44035	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A3EU	SA1105EA	Installation of Collins VHF 251 standby communication. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A36EU	SA1106EA	Installation of baggage compartment structural entrance area for use with drawer jump seat. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1107EA	Installation of aft cabin bulkhead and door installation. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1108EA	Installation of avionic equipment rack - washroom. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1109EA	Installation of air distribution system. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1110EA	Installation of emergency lighting system to meet the retroactive requirements of FAR 25.2. Amended 10/25/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1111EA	Installation of Wulfsberg III B flitefone. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
HS. 125-700A; T.C. A3EU	SA1112EA	Installation of nose gear taxi lights. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1113EA	Installation of general lighting. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1114EA	Installation of cabin lining. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1115EA	Installation of Jet AI-804 emeregency horizon. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1116EA	Installation of forward cabin bulkhead LHS and RHS. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A3EU	SA1117EA	Installation of dual Collins ADS-80F air data system. Reissued 7/26/78.	CE	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1118EA	Installation of Collins FGS-80 flight director system with FD 109 instruments. Amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1119EA	Installation of a single Collins ADS-80F air data system. Reissued 7/26/78.	CE	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1120EA	Installation of a side facing single seat. Issued 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS.125-700A; T.C. A3EU	SA1140EA	Installation of a three place side facing divan, aft cabin left hand side. Issued 1/19/79.	EA	44034	Innstech Aviation Limited Montreal International Airport Dorval, Quebec Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1183EA	Installation of bar galley unit. Issued 2/8/80.	EA	44034	Innotech Aviaiton Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1184EA	Installation of Collins WXR-300 color radar system and the Collins RNS-300 radar navigation system. Amended 4/25/80.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
HS 125-700A; T.C. A3EU	SA1196EA	Installation of solar T-62T-40C APU with 400 ampere starter-generator. Issued 5/29/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
HS-125-700A; T.C. A3EU	SA1538CE	Modification of aircraft to incorporate a fuel management computer. Issued 12/4/79.	CE	24540	Colt Electronics Company 131 West Ninth Avenue North Kansas City, MO 64116
HS.125-700A; T.C. A3EU	SA3552WE	Installation of Delco C-IVA inertial navigation system. Issued 1/13/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS. 125-700A; T.C. A3EU	SA3663WE	Installation of Foxboro engine fuel flow and totalizer system. Issued 6/19/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS. 125-700A; T.C. A3EU	SA3690WE	Installation of a Garrett/ AiResearch GTCP36-100 APU in the tail compartment. Issued 6/30/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3878WE	Installation of Eldec engine fuel flow and totalizer system. Issued 3/8/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3885WE	Installation of dual Global GNS-500A VLF/Omega navigation system. Issued 4/16/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
HS.125-700A; T.C. A3EU	SA3984WE	Installation of dual Litton LTN-211 ONS. Reissued 3/21/80.	WE	51500	Litton Aero Products, Inc. 6700 Eton Avenue Canoga Park, CA 91303
HS.125-700; T.C. A3EU	SA4021SW	BKM 100 PHM 700 pitot heat monitor system. Issued 7/24/79.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
HS. 125-700A; T.C. A3EU	SA4042SW	Relocation of center point pressure refueling system. Issued 9/26/79.	SW	11670	Arkansas Modification Center P.O. Box 3356 - Adams Field Little Rock, AR 72203
HS 125-700A; T.C. A3EU	SA4078SW	Install BKM specific range computer system (SRCS). Issued 1/25/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75234
HS.125-700A; T.C. A3EU	SA4152SW	Jump seat. Issued 7/9/80.	SW	11670	Arkansas Modification Center P.O. Box 3356 - Adams Field Little Rock, AR 72203
H.P. 137 Jetstream Mk1; T.C. A21EU	SA275GL	Modification of cabin and cockpit conditioned air and air distrubition system. Issued 11/6/78.	GL	08140	Air Illinois, Inc. Southern Illinois Airport P.O. Box 1224 Carbondale, IL 62901
H.P. 137 MK1 and H.P. 137 as modified STC SA3425WE; T.C. A21EU	SA440SO	Installation of Bendix Model M-4C automatic flight control system (AFCS) and installation of a Bendix M-4DAFCS. Amended 6/21/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
H.P. 137 MK1; T.C. A21EU	SA785EA	Installation of replacement radome P/N 3079KX. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
H.P. 137 MK1; T.C. A21EU	SA815EA	Installation of Compudex, Inc. Model TJ10-HP automatic fuel range computer.	EA	25760	Compudex, Inc. P.O. Box 93 Morristown, PA 19404
H.P. 137 MK1; T.C. A21EU	SA827EA	Relocation of fire-wall fuel and hydraulic system shut-off valves. Amended 6/25/70.	EA	18750	Butler Aviation-Friendship, Inc. Subsidiary of Butler Aviation International, Inc. Friendship Int'l Airport, MD 21240
H.P. 137 MK1; T.C. A21EU	SA1707SW	Three-place side facing couch. Issued 8/1/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA1769SW	Single seat. Issued 12/6/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA2043WE	Installation of instrument panel for day VFR operation.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2074WE	Installation of 18-passenger cabin interior, instruments, and avionics system.	WE	74270	Spartan - Van Nuys 7929 Hayvenhurst Avenue Van Nuys, CA 91406
H.P. 137 MK1; T.C. A21EU	SA2076WE	Installation of Collins AP-104/ FD-109 autopilot - flight director system. Reissued 4/21/70.	CE	24250	Collins Radio Company 5225 "C" Avenue, NE Cedar Rapids, IA 52406
H.P. 137 MK1; T.C. A21EU	SA2115WE	Intallation of observer jump seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2250WE	Relocation of fuel and hydraulic shut-off valves (modification found to comply with requirement of AD 70-15-04, Amendment 39-1031). Reissued 10/24/72.	WE	49850	Lear Avia Corporation P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
H.P. 137 MK1; T.C. A21EU	SA2293SW	P & W AGL PT6A-34 engines. Issued 7/9/76.	SW	46340	Jetstream, Inc. Box 1132 Waco, TX 76705
H.P. 137 MK1; T.C. A21EU	SA3064WE	The installation of an alternate method of complying with AD 72-23-01 by equivalency. Amended 9/23/75.	WE	11354	Apollo Airways 404 William Moffet Road Goleta, CA 93017
H.P. 137 MK1; T.C. A21EU	SA3136WE	Installation of ice shield on fuselage. Issued 1/19/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H.P. 137 MK1; T.C. A21EU	SA3281WE	Modification of cabin and cockpit air distribution system. Issued 10/12/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017
H.P. 137 Mk 1; T.C. A21EU	SA3425WE	Installation of two AiResearch TPE331-3U-303V engines and related changes. Amended 2/2/78.	SW	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101
H.P. 137, MK-1; T.C. A21EU	SA3534WE	Installation of cabin interior arrangement. Reissued 1/16/78.	SW	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101
HP.137 MK1; T.C. A21EU	SA3598WE	Installation of Abex P/N 40161 Model AP05V-060 hydraulic pump in lieu of original Vickers hydraulic pump. No installation data required. Issued 6/12/78.	WE	71655	Sierra Pacific Airlines 703 Airport Road Bishop, CA 93514
H.P. 137; T.C. A21EU	SA3932WE	Installation of underseat baggage restraint bars. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
B-121 Series 1, 2, 3; T.C. A22EU	SA308EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
B-121 Series 1, 2, 3; T.C. A22EU	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Beagle B.206 Series 2; A11EU	SA667SO	Installation of Bendix Model M-4C automatic flight control system.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
B206; T.C. A11EU	SA683SO	Installation of Goodrich wheels, brakes, and tires on main landing gears.	SO	58700	Miami Aviation Corporation Hangar 102, Opa Locka Airport Opa Locka, FL 33054

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
BRITISH AIRCRAFT CORP., LTD.
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BAC 1-11; T.C. A5EU	SA514EA-D	Install Butler Vector Analog Computer System to provide area navigation capability. Amended 11/17/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11; T.C. A5EU	SA279NW	Interior arrangement. Issued 4/30/76.	NW	01700	AeroAmerica, Inc. 7777 Perimeter Road Seattle, WA 98108
BAC 1-11; T.C. A5EU	SA634SW	Litton low range radio altimeter.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA660SW	Cockpit voice recorder A-100 and control panel A-152.	SW	17075	Braniff International P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA792SW	Relocation of LAS 109C flight recorder.	SW	17075	Braniff Airways Love Field Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA973WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
BAC 1-11; T.C. A5EU	SA1213WE	Fairchild A113 cockpit voice recorder and A152A control panel.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11; T.C. A5EU	SA1350SW	Installation of center wing tank fuel system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1432SW	Installation of Collins INS-61B inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1740SW	Install dual Delco Carousel IV or IVA inertial navigation systems. Reissued 4/18/80.	WE	78490	Tiger Air, Inc. 1888 Century Park East Los Angeles, CA 90067
BAC 1-11; T.C. A5EU	SA1761SW	Dual Collins INS 61B inertial navigation systems. Reissued 3/20/74.	GL	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11; T.C. A5EU	SA2365SW	Modification of Marston heat exchanger. Issued 10/5/76.	SW	52068	LORI 501 South Lansing Tulsa, OK 74120
BAC 1-11; T.C. A5EU	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, and EL-104B in emergency slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
BAC 1-11; T.C. A5EU	SA2709SW	Installation of heat exchanger. Issued 1/23/78.	SW	52068	LORI 510 South Lansing Tulsa, OK 74120
BAC 1-11, 200 Series; T.C. A5EU	SA1200EA	Installation of cabinet assembly. Issued 7/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
BAC 1-11, 200 Series; T.C. A5EU	SA1947WE	Installation of underseat baggage restraint system. REissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
BAC 1-11, 200 Series; T.C. A5EU	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
BAC 1-11, 200 Series; T.C. A5EU	SA3616WE	Installation of single LTN-51 or LTN-72 inertial navigation system. Issued 3/27/78.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2261WE	Installation of inflatable emergency evacuation slides at forward passenger and service doors. Amended 7/14/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2306WE	Installation of emergency exit lights at forward passenger door, at forward service door, and at both overwing emergency doors. Issued 1/15/71.	WE	44266	International Inflatables Company Div. Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2722WE	Modify aircraft by installation of wing mounted emblem lights. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2813WE	Structural modifications. Amended 7/15/74.	GL	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11, 200, 400; T.C. A5EU	SA4143SW	Pitot heat monitor system. Issued 6/16/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
BAC 1-11 203/AE, 204/AF, 215/AU; T.C. A5EU	SA1021EA	Installation of Collins FPC-75 ground proximity warning system and Bendix ALA-51A radio altimeter system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
BAC 1-11 203/AE, 204/AF, 215/AU T.C. A5EU	SA1207EA	Installation of new shoulder harness to forward flight attendant's seat, wind screen/bulkhead on right side front of passenger compartment. Issued 9/26/80.	EA	80870	USAir Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
BAC 1-11 204/AF, 215/AU; T.C. A5EU	SA840EA	Installation of Technical Standard Order inflatable escape slides. Amended 2/17/71.	EA	07250	Air Cruisers Company Division of Garrett Corporation P.O. Box 180 Belmar, NJ 07719
BAC 1-11 400 Series equipped with Rolls Royce RB 163-25 Spey 511-14 engines; T.C. A5EU	ST846SO	Increase maximum ramp weight to 89,000 lbs., increase maximum take-off weight to 88,500 lbs. and decrease maximum landing weight to 77,200 lbs. Issued 7/1/75.	SO	37885	Bruce Gilman P.O. Box 1372 Vickksburg, MS 39180
BAC 1-11 400; T.C. A5EU	SA3439WE	Installation of single or dual Litton LTN-51 inertial navigation systems. Issued 7/22/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91367
BAC 1-11, 401/AK; T.C. A5EU	SA403EA-D	Interior configuration - change from 69 passenger all coach to 16 first class and 49 tourist class with class divider and curtain installation between two sections.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA408EA-D	Installation of maintenance/flight data recording system. Amended 7/19/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA422EA-D	Installation of dual Collins AL-101 low range radio altimeter.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA449EA	Cockpit voice recorder.	EA	60092	Mohawk Airlines, Inc. Oneida County Airport Utica, NY 13503
BAC 1-11, 401/AK; T.C. A5EU	SA553EA-D	Installation of autopilot go-around unit on BAC 1-11. Amended 10/6/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 410AK; T.C. A5EU	SA554EA-D	Install underseat luggage retention device. Amended 12/4/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11 410AK; T.C. A5EU	SA555EA-D	To comply with FAR 25.812(e), a lever lock switch will be installed at a point accessible seat. Amended 4/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA2868WE	Installation of executive interior. Amended 7/15/74.	WE	07500	AiResearch Aviation Corporation 6201 W. Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BAC 1-11, 401/AK; T.C. A5EU	SA2971WE	Installation of maximum 1565 gallon auxiliary fuel tanks in forward and aft cargo compartment. Amended 2/12/80.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91505
BAC 1-11 401/AK; T.C. A5EU	SA3431WE	Installation of two couches in aft of aircraft. Issued 6/15/77.	WE	62083	Pacific American Airlines 2800 Clybourn Avenue Burbank, CA 91510
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB, 422/EQ; T.C. A5EU	SA1995WE	Installation of auxiliary fuel tanks in forward and aft cargo compartments. Amended 12/6/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB; T.C. A5EU	SA2776WE	Installation of dual Litton, LTN-51 inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11, 401AK, 410AQ, 412A/EB, 414EG, 419EB, 422EQ; T.C. A5EU	SA2873WE	Installation of a single or dual Litton, LTN-104, area navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EP; T.C. A5EU	SA3567WE	Installation of single or dual Litton LTN-51 or LTN-72 INS. Issued 3/17/78.	WE	51500	Litton Aero Products Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
BAC 1-11, 412A/EB Series, 422EQ; T.C. A5EU	SA2911WE	Installation of relocated engine water injection storage tank. Amended 2/20/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
BAC 1-11, 414EG; T.C. A5EU	SA3819WE	Installation of 1478 gallon auxiliary fuel tank system in the forward and aft cargo compartments. Issued 1/25/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

CESSNA AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
C-145, C-146; T.C. 701	SA4-1516	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
T-50; T.C. 722	SA1-196	Fiberglass application over fabric.	GI	62390	Anita H. Paner 7811 Hamilton Avenue Cincinnati, OH 45231
T-50; T.C. 722	SA4-161	Fiberglass fabric on fuselage, ailerons, flaps, empennage and wings.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
T-50; T.C. 722	SA4-1347	Ceconite 101 covering of entire airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
T50, 120, 140, 170, 170A, 170B; T.C. 722, 768, 799	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
T-50; 120, 140; C-145, -165; 170; T.C. 722, 768, 701, 799	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C-145, C-165, T-50, 120, 140, 170; T.C. 701, 722, 768, 799	SA2666WE	Ceconite 102 material covering of: C-145, C-165 - wings; T-50 - complete aircraft; 120, 140, 170 - wings. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
120; T.C. 768	SA1-39	Recovering of wings with metal skin, .020" 24ST alclad, except ailerons.	SO	16894	Boone County Aviation, Inc. P.O. Box 6 Erlanger, KY 41018
120, 140 Series; T.C. 768, 5A2	SA1-259	Wing covering of alclad panels.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047
120, 140 Series; T.C. 768, 5A2	SA1-436	Leading edge landing lights in left-hand wing.	EA	72100	Skycraft Design P.O. Box 67 West Trenton, NJ 08628
120, 140 Series; T.C. 768, 5A2	SA3-114	Instrument panel modification.	RM	84912	Weber Aviation Municipal Airport Rapid City, SD 57701
120, 140 Series; T.C. 768, 5A2	SA4-89	Recovering of wings with metal .020 alclad 2024T3 aluminum alloy.	WE	49380	J.E. Lane, Jr. 3504 Niblick Drive La Mesa, CA 92041
120, 140 Series; T.C. 768,5A2	SA4-95	Lycoming 0.235C-1 engine.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
120, 140 Series; T.C. 768, 5A2	SA4-174	Glass cloth application over muslin to wings only.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
120, 140 Series; T.C. 768, 5A2	SA4-341	Recovering of wings with .020 24ST alclad sheet.	WE	18275	Frank A. Burdick 43316 N. 20 Street West Lancaster, CA 93534
120, 140 Series; T.C. 768, 5A2	SA4-360	Recovering of wings with aluminum alloy sheet.	WE	19900	Carma Manufacturing Company P.O. Box 11312 Municipal Airport Tuscon, AZ 85700
120, 140 Series; T.C. 768, 5A2	SA4-581	Lycoming O-290-D engine and Sensenich M76AM-2 or CS3FM4 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
120, 140 Series; T.C. 768, 5A2	SA4-640	Lycoming O-290-D2 engine and Sensenich M76AM-2 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
120, 140 Series; T.C. 768, 5A2	SA4-674	Eonite covering on wings.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
120, 140 Series; T.C. 768, 5A2	SA4-803	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 94108
120, 140 Series; T.C. 768, 5A2	SA4-916	Tricycle gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
120, 140 Series; T.C. 768, 5A2	SA4-1200	Delco-Remy generator 1101879 and and regulator 1118384.	RM	91060	Universal Aircraft Industries P.O. Box 5306 Denver, CO 80217
120, 140 Series; T.C. 768, 5A2	SA4-1346	Fiberglas covering of airplane surfaces.	WE	49790	Quentin Laywell 5627 Laurette Street San Diego, CA 92100
120, 140 Series; T.C. 768, 5A2	SA54CE	Covering of wings with .020" 24ST aluminum.	CE	14223	B & W Aircraft Repair, Inc. St. Peters, MO 63376
120, 140 Series; T.C. 768, 5A2	SA99EA	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
120, 140 Series; T.C. 768, 5A2	SA295WE	Mounting bracket fabrication.	NW	43380	Glen Humphreys 2325 S.W. 116 Seattle, WA 98146
120, 140 Series; T.C. 768, 5A2	SA1008WE	Poly-Fiber covering of right and left wing. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
120/140; T.C. A768	SA388SO	Metalize wings, wing landing/taxi light installation. Amended 7/2/70.	SO	68550	W.F. Polison Valley Air Service P.O. Box 241 Lanett, AL 36863
120, 140 Series; T.C. A-768	SA1209WE	Replacement of wing drag wires in two outboard wing bays with 3/16 inch Stratton Aero Enterprises drag wires. Reissued 8/11/78.	WE	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
120, 140, 150; T.C. 768, 3A19	SA1143SW	Redesigned muffler assemblies. Issued 5/15/70.	SW	25350	Comisky Engineering Company, Inc. P.O. Box 268 Mena, AR 71953
120, 140, 170 Series; T.C. 768, 5A2, 799 t) (	SA331CE	New base instrument panel incorporating artificial horizon.	GL	74000	Spartacus Industries P.O. Box 634 Muskegon, MI 49443
120, 140, 170; T.C. 768, 3A12	SA4-207	Spar reworked to facilitate rigging of metalized wings.	RM	84394	Wagner Aircraft Service P.O. Box 267 Grand Junction, CO 81501
120, 140, 170; T.C. 768, 3A12	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
120, 140, 170; T.C. 768, 3A12	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
120, 140; 170, 170A, -B; T.C. 768, 799	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
120, 140, 170, 180; T.C. 768, 5A2, 799, 5A6	SA3-423	CT-300 tail ski on airplanes equipped with Scott 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
120, 140, A, 170, 170A, B, 172, 172A, B, C, D, E, 180, 180A, B, C, D, E, F, G, 182, 182A, B, C, D, E, F, G, 210, 210A, B, C, D, 210-5, -5A, 150, 150A, B, C, D, 305A, B; T.C. 768, 5A2, 799, 3A12, 5A6, 3A13, 3A21, 3A19, 3A14	SA4-394	Installation of George M. Adams DGA-2000 wheels and Bodell Manufacturing Model BMI-252 brakes. Amended 1/15/76.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torranca, CA 90501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
120, 140, 140 (S/N 8004 thru 13399), 140A (S/N 13400 and up), 170, 170A, 170B, 172, 172A thru 172E, 175, 175A, 175B, 175C, P172D, 180, 180A thru 180F, 182, 182A thru 182G; T.C. A-768, A-799, 3A12, 3A13, 3A17, 5A2, 5A6	SA13GL	Installation of Cleveland wheel No. 40-97A and brake No. 30-63A. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
120, 140, 170, 305A, 305C, 305B; T.C. 768, 5A2, 799, 5A5, 3A14	SA34CE	Tow hitch assembly.	EA	73550	Soaring Society of American, Inc. Elmira, NY 14902
120, 140, 140A, 150, 150A, B, D, E, F, G, H, J, K, L, A150K, 170, 170A, B, 172, 172A, B, C, D, E, F, G, H, I, K, L, M; T.C. 768, 5A2, 3A19, 799, 3A12	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24115 116th S.E. Kent, WA 98031
120, 140; 140A, 150 to 150-L; 170, 170A, B; 172 to 172M; 175 to 175C; 177 to 177B; 180 to 180J; 182 to 182Q; T.C. 768, 5A2, 3A19, A799, 3A12, 3A17, A13CE, 5A6, 3A13	SA86NW	Installation of automatic carburetor alternate air control unit. Issued 12/28/73.	NW	01775	Aero-Deicers, Inc. 5407 S.E. 62nd Avenue Portland, OR 97206
120, 140, 170, 172, 175, 180, 182; T.C. 768, 5A2, 799, 3A12, 3A17, 5A6, 3A13	SA121CE	Nose and main gear wheel fairing (Jetstreams) using standard unaltered Cessna landing gear and nose gear fork for model and year using 500 x 5 nose and 600 x 6 main gear tires. Amended 3/1/77.		26750	Creative Designs 1338 Orkla Drive Minneapolis, MN 55427
120, 140, 150, 170, 172, 175, 180, 182, 185, 190, 195, 210, 310, 320; T.C. 768, 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 3A24, 790, 3A21, 3A10, 3A25	SA147CE	Moni-Meters on aircraft equipped with King KY-90, KY-95, Narco Mark 4 or Mark 12 transceivers.	GL	60086	Mobile Engineering 220 Southdale Center Minneapolis, MN 55435
120, 140, 170, 305A, 305C, 305D; T.C. 768, 5A2, 799, 5A5, 3A14	SA268CE	Tow hitch assembly.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
120, 140; 140A; 150, A thru L; 170, 170A, -B; A150K, A150L; 172, 172A thru L; 175, A, B, C, P172D; 180, A thru H; 182; 177, 177A, B; 182A thru H, J thru N, P, 188, 188A; 185, 190, 321; T.C. A-768, 5A2, 3A13, A-799, A-758, 3A17, 5A6, A-729, A13CE, A9CE, 3A11	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
120, 140; 140A; 150, A, B, C, D, E, L; 170, A, B; A150K, A150L; 172, 172A, B, C, D, E, F, G, H, J; 175, A, B, C, P172D; 180, A thru H; 177 177A, B; 188, 188A; 182, 182A thru P; 182; 321; T.C. A-768, 5A2, 3A19, A-799, A-758, 3A13, 3A17, 5A6, A13CE, A9CE, 3A11	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred F. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
120, 140, 150, 170, 172, 175, 177, 177RG, 180, 182; T.C. A-768, 3A19, A799, 3A12, 3A17, A13CE, A20CE, 5A6, 3A13	SA582NW	Fabrication of wire ropes. Issued 5/12/78.	NW	81180	University Swazing 7001 Perimeter Road Seattle, WA 98108

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
120, 140, 140A, 150, 170, 175, 180, 182, 310; T.C. A768, 5A2, 3A19, 3A17, 5A6, 3A13, 3A10	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
120, 140; 140; 150; 170; 172; 172, 175; 177; 180; 182; 185; 188, A188; 206; 207, T207; 210; 305; 310; 320; 321; 336; 337; 401, 401A, 402, 402A; 411, 411A, 421, 421A; T.C. A-768, 5A2, 3A19, A-799, 3A12, 3A17, A13CE, 5A6, 3A13, 3A24, A9CE, A4CE, A16CE, 3A21, 5A5, 3A14, 3A10, 3A25, 3A11, A2CE, A6CE, A7CE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
120, 140; 140A; 150, 150A thru H, J, K, L, M, A150K, L, M, 170, 170A, B; 172, 172A thru 172M; 175, 175A, B, D, P172D; 177RG; 177, 177A, 177B; 180, 180A thru J; 182, 182A thru 182P; 185, 185A thru 185E, -A185E, A185F; 188, A188,, 188A, 188B, A188A, A188B; 190, 195, 195A, B; 206, P206, P206A, B, C, D, E, TU206A thru TU206F, TP206A thru TP206E, U206, U206A, B, C, D, E, F; 207, T207, 207A, T207A; 210, 210A thru 210H, J, K, L, T210F, G, H, J, (205) 210-5, (205A), K, L, 210-5A; 310, 310A thru 310Q, E310H, -J-1, E310-J, -K, -L, -N, -P, T310P, T310Q; 320, A, B, C, D, E, 320F, 320-1; 337, -A thru -G, T337D, -E, -F, -G; 336; 340; 401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 421, 421A, B; T.C. A-768, 5A2, 3A19, A-799, 3A12, 3A17, A20CE, A13CE, 5A6, 3A13, 3A24, A9CE, A-790, A4CE, A16CE, 3A21, 3A10, 3A25, A6CE, A2CE, 3A25, A7CE	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W A408R/W or A470R/W (red/white) (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
120, 140, 150, 170, 180, 190, 195; T.C. 768, 5A2, 3A19, 799, 3A12, 3A17, 5A6, 3A13, 790	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
120, 140; 150, A thru H; 170, -A, -B; 172, A thru I; 177; 180, A thru H; 182, A thru L; P206D, U206D, TP206D, TU206C; 207, T207; M337B; 310, A thru N, E310H, -J, 310J-1; 320, -1, A thru F; 401, 402, 411, 411A, 421; T.C. 768, 3A19, 799, 3A12, A13CE, 5A6, 3A13, A4CE, A16CE, A6CE, 3A10, 3A25, A7CE	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
140 Series; T.C. 768, 5A2	SA1-1	Recovering of wings with 24ST alclad skin.	EA	05972	Aircraftsmen, Inc. Zahn Airport Lindenhurst, L.I., NY 11757

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172M, 172N; T.C. 3A12	SA146GL	Installation of EPA portable enviro pod. Amended 12/10/79.	GL	07696	AFAL/RWF Wright-Patterson AFB, OH 45433
172M, 172N; T.C. 3A12	SA380GL	Installation of Tull microwave landing system airborne equipment. Amended 5/12/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
172M, 172N; T.C. 3A12	SA1402CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172M, 172N; T.C. 3A12	SA3200SW-D	Automaitc flight system AK467 consisting of Century II autopilot with optional radio coupler. Issued 4/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA3201SW-D	Automatic flight sytem AK472 consisting of Century I autopilot with optional omni tracker. Issued 4/7/77.	SW	6000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA4080SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
172M, 180J, 182P, A185F, A188B, 188B, U206F; T.C. 3A12, 3A13, 5A6, 3A24, A4CE, A9CE	SA974EA	Installation of L/R wing tip transparent fairing and sensor mounting bracket. Issued 2/26/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
172N; T.C. 3A12	SA168GL	Install Heath Kit Model 01-1154 aircraft digital clock/timer. Issued 4/28/77.	GL	41610	The Heath Company Hilltop Road Benton Harbor, MI 49022
172N; T.C. 3A12	SA584NW	Installation of Edo 689-2130 seaplane floats. Amended 1/8/80.	EA	32625	Edo-Aire, Seaplane Division 65 Marcus Drive Melville, NY 11746
172N; T.C. 3A12	SA1168SO	Instalaltion of Aqua Model 2200 floats. Issued 8/8/80.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FI 33599
172N; T.C. 3A12	SA1324CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/7666A-2 propeller. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 North Wichita Station Wichita, KS 67204
172N; T.C. 3A12	SA3301SW-D	Mitchell automatic flight system AK730, consisting of Century I autopilot with optional omni tracking system. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A12	SA3302SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A17	SA3303SW-D	Mitchell automatic flight system AK732 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172RG; T.C. 3A17	SA3363SW	Mitchell automatic flight system AK861 consisting of Century 21 autopilot. Issued 3/14/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P172D; 180D, 180F; 182A, 182A-F; 185, 185A, 185B; T.C. 3A12, 5A6, 3A13, 3A24	SA1686WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
P172D, R172E, R172F, R172G, R172H, R172J, R172K; T.C. 3A17	SA3487WE	Installation of tail flood light. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
R172K; T.C. 3A17	SA460NW	Installation of PeeKay model 2300 or E2300 seaplane floats. Amended 4/20/78.	EA	29998	PeeKay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
R172K Landplane only; T.C. 3A17	SA1437CE	Install rerated Continental IO-360-K engine. Issued 10/6/78.	CE	44802	Brad E. Isham 416 west Fourth Street Valley Center, KS 67147

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
R172K; T.C. 3A17	SA3227SW-D	Mitchell automatic flight system AK699 consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3228SW-D	Mitchell automatic flight system AK698 consisting of Century IIB autopilot with optional radio coupler. Issued 8/2/77.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3285SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3286SW-D	Mitchell automatic flight system AK732 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R172K; T.C. 3A17	SA4048WE	Installation of Silver Instruments fueltron IG or fueltron digital fuel flow and totalizer system. Issued 10/24/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
R172K, 175, 175A, 175B, 175C; T.C. 3A17	SA383GL	Convert to conventional landing gear. Issued 1/31/80.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 175 Series; T.C. 3A12, 3A17	SA1-219	Gyro-stabilizer 69A122.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
172, 175 Series; T.C. 3A12, 3A17	SA3-576	Speed kit.	CE	65900	P & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
172, 175 Series; T.C. 3A12, 3A17	SA4-1601	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175 Series; T.C. 3A12, 3A17	SA109SW	Automatic pilot AK106.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA393WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
172, 175 Series; T.C. 3A #A17	SA411SW	Automatic pitch trim AK 138.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA436EA	New engine, propeller and engine mount. Amended 9/21/67.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
172, 175 Series; T.C. 3A12, 3A17	SA610SW	Lycoming O-320 and O-360 Series engines with Hartzell HC-82XL-7636D-4; HC-C2YK-2R/7666 or HC-92Z-2B/8447-12A propeller.	SW	67650	R.F.B. Company Chandler Field Purcell, OK 73080
172, 175, 180, 182, 310 Series; T.C. 3A12, 3A17, 5A6, 3A13, 3A10	SA4-306	Roto-Nav bracket and Grimes D 7080 anti-collision light on vertical fin.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175, 182 Series; T.C. 3A12, 3A17, 3A13	SA4-893	Installation of wheel fenders on nose gear and main gear. Reissued 2/9/71.	NW	12565	Aurora Air Inc. d/b/a Madras Air Service Madras, OR 97741
172, 175, 180, 182 Series; T.C. 3A12 3A17, 5A6, 3A13	SA10WE	Arens Vernier type throttle control.	WE	82400	Van Nuys Skyways, Inc. 16700 Roscoe Boulevard Van Nuys, CA 91408
172, 175, 180 Series; T.C. 3A12, 3A17, 3A13	SA462WE	Jump door 62-500.	NW	72252	Skymotive, Inc. Route 1, Box 32 Snohomish, WA 98290
172, 175, 182 Series; T.C. 3A12, 3A13, 3A17	SA480CE	Nose and main gear wheel fairings. (Jetstreams) using standing unaltered Cessna landing gear and nose gear for model and year using 500 x 5 nose and 600 x 6 main gear tires.	GL	26750	Creative Designs 1338 Orkla Drive Minneapolis, MN 55427

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172, 180; T.C. 3A12, 5A6, 3A13	SA2362WE	Installation of lure toxicant dispenser AEY 70, Model #1. Amended 9/27/73.	NW	03270	U S D A 3706 W. Nob Hill Boulevard Yakima, WA 98902
172, 180, 182 Series; T.C. 3A16, 5A6, 3A13	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Company airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
172, 180, 185; T.C. 3A17, 5A6, 3A24	SA271NW	Removal of paper air induction paper. Issued 3/16/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
172, 182 Series; T.C. 3A12, 3A13	SA1-193	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
172, 182 Series; T.C. 3A12, 3A13	SA116EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/63.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
172, 182, 206, 210 Series; T.C. 3A12, 3A13, A4CE, 3A21	SA895WE	Kienzle 65 flight time recorder.	WE	18460	Burrows and Sons 1829 Bridgeport Avenue Claremont, CA 91711
175 Series; T.C. 3A17	SA3-285	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 1405 S. Oliver Wichita, KS 67207
175 Series; T.C. 3A17	SA3-611	Model 3000 main ski and Model 2000 nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
175 Series; T.C. 3A17	SA3-691	Installation of Doyn swept-tail assembly kit 1400. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
175 Series; T.C. 3A17	SA4-547	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
175 Series; T.C. 3A17	SA4-1406	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
175 Series; T.C. 3A17	SA3EA	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
175 Series; T.C. 3A17	SA5WE	Cowl flap.	WE	87473	Thompson International Aviation P.O. Box 68 Hereford, AZ 85615
175 Series; T.C. 3A17	SA11SO	Tank type end plates.	SO	26580	Corben Development Corporation P.O. Box 1603 Venice, FL 33595
175 Series; T.C. 3A17	SA12CE	Removal of right cabin door.	PC	96754	W.E. Avery 116 Kuulei Road Kailua, HI 96754
175 Series; T.C. 3A17	SA28WE	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
175 Series; T.C. 3A17	SA49CE	Conversion of aircraft for parachute jumping operations.	GL	41190	Haven Aviation Memorial Airpark Grand Haven, MI 49417
175 Series; T.C. 3A17	SA72CE	Sky-Lite B-100 beacon light.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
175 Series; T.C. 3A17	SA179NW	Installation of flap gap seals. Issued 1/25/75.	NW	78477	Thunderbird Aero Enterprise Paine Field Everett, WA 98204
175 Series; T.C. 3A17	SA221SO	Conversion of aircraft for parachute jumping and aerial photography.	SO	62490	Edward Richard Parker P.O. Box 578 Andrews Murphy AirPark Andrews, NC 28901
175; T.C. 3A17	SA586NW	Installation of a Franklin 6AS-350-A1 engine. Issued 7/28/78.	NW	70620	Seaplane Flying, Inc. P.O. Box 1264 Vancouver, WA 98661

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
175, 175A, 175B Landplane; T.C. 3A17	SA424CE	Install Lycoming O-360-A1A or O-360-A1D engine and Hartzell HC-C2YK-1A/7666-2, HC-922K-8D/8447-12A or McCauley 2D36C14/78KM-4 propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
175, 175A, B; T.C. 3A17	SA3-674	Lycoming O-360-A1D engine and McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1A/7666-2 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
175, 175A, B, C, P172D; T.C. 3A17	SA1-610	Wet-to-dry vacuum pump conversion kit 300-2. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
175, 175A, B, C; P172D; T.C. 3A17	SA122NW	Installation of Continental O-470 engine, McCauley 2A34C66N/90A-8 propeller, engine mount, cowling, baffles and associated parts. Issued 7/25/74.	NW	47646	Leslie L. Kammeyer Route 2, Box 38 Enumclaw, WA 98022
175, 175A, B, C; T.C. 3A17	SA161EA	Install new engine, propeller and engine mount. Amended 3/17/67.	EA	36750	Franklin Engine Company, Inc. Liverpool Road Syracuse, NY 13208
175, 175A, 175B, 175C; T.C. 3A17	SA212GL	Installation of windshield P/Ns W-2056, W/T-2056 or W/G-2056. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
175, 175A, 175B, 175C; T.C. 3A17	SA1492CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
175, 175A, B, C, P172D, T210F, G, H, J, K, L, M, 310, 310A, B, C, F thru L, N, P, Q, 310J-1, 310R, E310H, E310J, T310P, Q, 320D, E, F, 337, 337A, B, C, D, E, G, M337B, T337B, C, D, E, F, G, 340, 340A, 401, 401A, B, 402, 402A, B, 414, 421, 421A, B; T.C. 3A17, 3A10, 32A25, A6CE, A7CE	SA660WE	Installation of HRD-type fire-extinguishing and detector system. Amended 7/11/77.	WE	43180	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
175, 175A, B, C, P172D; T.C. 3A17	SA327GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
175, 175A, 175B, 175C, P172D (Landplane), R172E (T-41B); T.C. 3A17	SA777CE	Install Lycoming O-360-A1A, 180 hp engine and Hartzell HC-C2YK-1A/766A-2 propeller. Amended 5/6/80.	CE	12775	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 Wichita, KS 67204
175, 175A, 175B, 175C, P172D, R172E, R172F, R172G, R172H, R172J; T.C. 3A17	SA948CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Amended 5/6/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
175A, B, C, P172D (normal category): T.C. 3A17	SA2229WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
175, 175A, B, C; T.C. 3A17	SA2853SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
175, 175A, 175B, 175C (landplane only, normal category): T.C. 3A17	SA3795WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision, muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29075	Del-Air P.O. Box 746 Strathmore, CA 93267
175, 175A, 175B, 175C; T.C. 3A17	SA4177WE	Installation of electric inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
175, 180, 182; T.C. 3A17, 5A6, 3A13	SA2710WE	Installation of carburetor heat box bearings. Issued 6/15/73.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
177; T.C. A13CE	SA466SO	Removal of right entrance door of cabin for aerial photography. Issued 5/20/71. Modified per STC SA545CE.	SO	25060	Columbus-Muscogee Aviation, Inc. P.O. Box 4608 Columbus, GA 31904

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
177; T.C. A13CE	SA545CE	Installation of Lycoming O-360-A1A (180 h.p.) engine and new Hartzell propellers. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
177; T.C. A13CE	SA602CE	Install shoulder harness.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67202
177; T.C. A13CE	SA906CE	Installation of Lycoming O-360-A1A 180 hp engine and Hartzell HC-C2YK-1B/766A-2 or 7666-2 constant speed propeller. Issued 5/9/73.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 1006 W. 53 North Wichita, KS 67204
177; T.C. A13CE	SA1608WE	Installation of Brittain B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
177; T.C. A13CE	SA3861WE	Installation of an air/oil separator. Issued 3/2/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
177, 177A; T.C. A13CE	SA956CE	Installation of STOL kit (wing leading edge cuffs, drooped tips and vortex generators). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177, 177A, 177B; T.C. A13CE	SA1347CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
177, 177A, B; T.C. A13CE	SA3180SW-D	Automatic flight system AK420 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3181SW-D	Automatic flight system AK421 consisting of Century IIB autopilot with optional radio coupler. Issued 2/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3402WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
152, A152, 177, 177A, B, 177RG, 180 landplane and seaplane, 180A, B, C, D, E, F, G, H, I, J, K seaplane versions, 182, 182A, 210A, B, C, D, E, 310F, G, H, I; T.C. A13CE, 3A19, A20CE, 5A6, 3A21, 3A10	SA71GL	Installation of: 152's P/N BA4106 filter assembly; 177's P/N BA5710 filter assembly; 180's & 182's P/N BA8110 filter assembly; 210's P/N BA2110 filter assembly; 310's P/N BA2310 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140
177, 180, 182, 185, A185, 188, A188, 210-5 (205), 206, U206, TU206, P206, TP206, 207, T207, 210, T210; T.C. A13CE, 5A6, 3A13, 3A24, A9CE, 3A21, A4CE, A16CE	SA728NW	Installation of vented fuel cap. Issued 3/9/79.	NW	82675	Venting Engineering 5420 "A" Street Tacoma, WA 98408
177A; T.C. A13CE	SA601CE	Install Hartzell Model HC-C2YK-1B/7666A-2 constant speed propeller. Amended 2/28/69.	CE	56868	Galen D. Means 1818 North Edgemoor Drive Wichita, KS 67201
177B; T.C. A13CE	SA1060CE	Installation of wing leading edge cuffs and vortex generators on vertical stabilizer. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177B; T.C. A13CE	SA1607SW	Mitchell command/electric trim AK419. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SW1608SW	Mitchell AFS system AK420 consisting of Century I autopilot with optional omni tracker. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SA1609SW	Mitchell AFS system AK421 consisting of Century I autopilot with optional radio coupler. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
177RG; T.C. A20CE	SA3297SW-D	Mitchell automatic flight system AK759, consisting of Century IIB autopilot with optional radio coupler. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG, S/N 177RG1267 and subsequent; T.C. A20CE	SA446GL	Installation of Tull microwave landing system airborne equipment. Issued 9/17/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
177RG; T.C. A20CE	SA1049CE	Installation of wing leading edge cuffs and vertical stabilizer vortex generators. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177RG; T.C. A20CE	SA1348CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
177RG; T.C. A20CE	SA1479SW	Mitchell automatic flight system AK378 consisting of Century I autopilot with optional omni tracker. Issued 8/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RG; T.C. A20CE	SA1510SW	Mitchell automatic flight system AK379 consisting of Century IIB autopilot with optional radio coupler. Issued 9/8/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3296SW-D	Mitchell automatic flight system AK758 consisting of Century I autopilot with optional omni tracking system. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3298SW-D	Mitchell automatic flight system AK760, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3387WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	36002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
177RG; T.C. A20CE	SA3860WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
177RG; T.C. A20CE	SA4024WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 9/10/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
180 Series; T.C. 5A6	SA1-7	Gyro-stabilizer 69A116 on aircraft with serial numbers 32151 and up.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-16	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA1-91	Modification to accommodate Robinson Aviation vertical mount RRIA.	EA	18756	Allen G. Butler 233 Front Street Phillipsburg, PA 18866
180 Series; T.C. 5A6	SA1-106	Gyro-stabilizer 69A107.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-212	Hole cut in lower skin and reinforced.	NE	44030	Inland Fisheries and Game Department Maine
180 Series; T.C. 5A6	SA1-221	Gyro-stabilizer 69A124.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA3-122	Model 3000 main ski and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-160	Conversion of electrical system, engine and aircraft to 24v and installation of additional battery box. (Aircraft with Continental O-470-J engine only).	GL	43342	Harvey M. Hughes Capital City Airport Lansing, MI 48924

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180 Series; T.C. 5A6	SA3-161	C-3000 hydraulically-actuated main wheel skis with AWT-2500A or CT-3000 tail wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-292	Hydraulic landing gear actuating system with Edo 289-2700 amphibian gear.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA3-330	C-3000 manually-actuated main skis and AWT-2500A or CT-3000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-340	C-3000 main wheel skis on aircraft with crosswind gear.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-381	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
180 Series; T.C. 5A6	SA3-480	Change in airspeed and center of gravity limits with Edo 249-2870 floats and 2850 maximum weight.	AL	08483	Alaska Coastal Airlines 2 Marine Way Juneau, AK 99801
180 Series; T.C. 5A6	SA3-578	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
180 Series; T.C. 5A6	SA3-592	Structural reinforcement wires from center sectional spars to upper engine mount bolts rear of fire wall in windshield.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA3-597	Engine driven hydraulic pump system for Federal C-3000 main ski.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA4-23	Conversion to tricycle gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-56	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-92	Folding type rear seat.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-117	Auxiliary fuel tank in baggage compartment.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-532	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA4-603	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA4-688	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
180 Series; T.C. 5A6	SA41WE	Two fabric rear seat assemblies supported by two steel tube beams.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA42EA	Floor viewing window.	EA	49730	Latrobe Aviation, Inc. P.O. Box 150 Latrobe, PA 15650
180 Series; T.C. 5A6	SA102AL	Shackle release at wing lift strut fittings right and left wings (seaplane only).	AL	03270	U.S. Department of Agriculture Forest Service P.O. Box 1631 Juneau, AK 99801
180 Series; T.C. 5A6	SA110SW	Removal of perforated cones from exhaust muffler.	SW	76850	Sun Oil Company P.O. Box 292 Patterson, LA 70392
180 Series; T.C. 5A6	SA168SW	Conversion of aircraft for parachute jumping operations.	SW	40684	John Hardy, Jr. 1105 St. John's Road El Paso, TX 79910
180 Series; T.C. 5A6	SA173RM	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180 Series; T.C. 5A6	SA200RM	Installation of flight strobe light, Model 4400. Issued 4/22/80.	RM	79760	Tri Star Corporation P.O. Box 1727 730 Independent Avenue Grand Junction, CO 81501
180 Series; T.C. 5A6	SA214SW	Removal of perforated cones on cabin and carburetor heat-sides of muffler assembly with Continental O-470-K engine.	SW	52870	J. Ray McDermott & Company, Inc. Aviation Division P.O. Box 38 Harvey, LA 70058
180 Series; T.C. 5A6	SA221WE	Cleveland 30-21 wheel and brake assemblies 8:00 x 6 tires, Cessna heavy duty axles and 185 hose assemblies.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA289CE	Sky diving door.	GL	78474	Melvin J. Thompson 2408 Illinois Avenue New Holstein, WI 53061
180 Series; T.C. 5A6	SA312NW	Installation of Edo 628-2960 floats. Amended 6/6/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180 Series; T.C. 5A6	SA527WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
180 Series; T.C. 5A6	SA531AL	Installation of leading edge cuff stall fences, and flap and aileron gap seals. Issued 10/25/74.	AL	27250	Crosswinds, Inc. 8134 Lake Otis Parkway Anchorage, AK 99507
180 Series; T.C. 5A6	SA532CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
180 Series; T.C. 5A6	SA702WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304, and optional Hi-Lo sensitivity adaptor.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
180 Series; T.C. 5A6	SA703WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold and NAV-1 navigation coupler and optional Hi-Lo sensitivity adaptor. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA939WE	Insertion into exhaust collector or exhaust stack of thermocoupled cylinder, a probe to read relative exhaust temperature.	WE	47746	Richard W. Kennedy 3352 Via Bartolo Street San Diego, CA 92101
180 Series; T.C. 5A6	SA983WE	Removal of right-hand door to permit parachute jumping and aerial photography operation (seaplane).	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
180 Series; T.C. 5A6	SA1373WE	Model 3000 floats.	EA	19800	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond, British Columbia, Canada
180 Series; T.C. 5A6	SA2630WE	Installation of SKI Model 10-202186 (Pulstar TM) combined position - anti-collision lighting system. Amended 5/11/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180F, 182, 182A thru 182D; T.C. 5A6, 3A13	SA1-37	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 46226
180, 180A, 180B; T.C. 5A6	SA1-363	Installation of Edo Model 439-2705 amphibious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, (seaplanes); T.C. 5A6	SA1-464	Installation of Edo models 439-2705 amphibious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, E, F, G, H, J, 182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P; T.C. 5A6, 3A16	SA1-611	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180, 180A, B, C, D, E, (seaplanes); T.C. 5A6	SA1-622	Installation of Edo Model 249A-2870 seaplane floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180 thru 180F; T.C. 5A6	SA24GL	Installation of Model M-3000 wheel replacement skis. Issued 6/4/73.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapid, MN 56470
180, 180A thru 180F, H, J, 185, 185A, B, A185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA62GL	Install Cleveland wheel and brake conversion kit, P/N 199-60. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
180, 180A thru 180F, H, J, 185, 185A, B, 185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA63GL	Install Cleveland wheel and brake conversion kit, P/N 199-62. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
180, 180A thru 180J; T.C. 5A6	SA73GL	Installation of wheel replacement skis, Model M3000. Amended 7/16/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
180, 180A thru 180F, 182, 182A thru F; T.C. 5A6, 3A13	SA94EA	Installation of Monitair angle of attack system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
180, 180A thru 180F; T.C. 5A6	SA104CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180 thru 180H, J, 185 thru 185E, A185E, F; T.C. 3A24, 5A6	SA213AL	Installation of main tail gear skid, or main gear skis with two position wheel fittings. Amended 12/10/75.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180, 180A thru 180H, 185, 185E, A185E, 185F; T.C. 3A24	SA223AL	Installation of Model L3000 wheel replacement skis. Amended April 1974.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180 thru 180K; T.C. 5A6	SA286CE	Installation of Pee Kay Model 3500 or A3500 or B3500 floats, seaplane (TSC-C27-2) on Cessna Models 180 thru 180H airplanes. Amended and reissued 1/19/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
180, 180A thru 180H; T.C. 5A6	SA296AL	Installation of "quick-change" leading edge for horizontal stabilizer. Amended 12/15/71.	AL	05958	Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
180 Series 32015 and up, 180A thru 180K; T.C. 5A6	SA349CE	Installation of Aqua Model 180-85 floats. Amended and reissued 7/12/77.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, Fl 33599
180 thru 180E; T.C. 5A6	SA367CE	Installation of floor level seat belt brackets to accommodate four occupants. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
180 thru 180H; 182 thru 182L; 185 thru 185E, A185E; 210 thru 210H, 210-5, -5A, T210F, G, H; 206, 206P, 206TP, 206TU, U206A, U206P, U206TP, U206TU, U206B, U206C; T.C. A4CE	SA453CE	Install Hoskins Twilighter Mk.III supplementary lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180H; T.C. 5A6	SA651AL	Fabricate canvas hammock rear seat and associated parts and install. Issued 8/23/78.	AL	61765	Nugget Aviation Route B, Box 188B Palmer, AK 99645
180, 180A thru 180H; T.C. 5A6	SA658AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180, 180A thru H; T.C. 5A6	SA745CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109
180A thru 180H; T.C. 5A6	SA787EA	Installation of Fleet-Line Floats 2900. Reissued 12/21/71.	EA	64630	Pioneer Airways P.O. Box 357 Atikokan, Ontario, Canada

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA816SW	Hartzell BHC-A2VF-3/V8833 reversible pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
180, S/N 18051824 and on; T.C. 5A6	SA865CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
180, 180A, B, C, D, E, F, G, H, 182, 182A, B, C, D, E, F, G, H, J, K, L, 185, 185A, B, C, D, E, A185E, 210, 210A, B, C, D, E, F, T210F, 206, P206, P206A, B, C, D, U206, U206A, B, C, D, TP206A, B, C, D, TU206A, B, C, D; T.C. 5A6, 3A13, 3A24, 3A21, A4CE	SA901SW	Increased wing leading edge radius. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 96133
180, 180A thru 180H, J, 180K, Landplanes, Seaplanes and Amphibians; T.C. 5A6	SA967CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Amended 5/8/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
180, 180A thru 180H; T.C. 5A6	SA1004CE	Install STOL kit. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
180, 180A thru 180H, 180J; T.C. 5A6	SA1157WE	Turbocharged Continental O-470-A, J, K, L, or R engine. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
180 thru 180H, 180J Landplane, Floatplane and Amphibian; T.C. 5A6	SA1435WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, except 180J, a flap actuated elevator trip system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA1493CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
180, 180A thru 180H, J; 180H Landplane and Floatplane; T.C. 5A6	SA1705WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 4/20/77.	WE	35780	William E. Flint 8402 North Magnolia, Suite G La Mesa, CA 92041
180, 180A thru H, A185E; T.C. 5A6, 3A24	SA1749WE	Installation of Canadian Aircraft Products, Ltd. Model 3000D floats.	EA	19800	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond. British Columbia. Canada
180 thru 180H; T.C. 5A6	SA2003WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA2654SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
180, 180A, B, C, D, E, F, G, H, J Landplanes Normal Category; T.C. 5A6	SA3313WE	Installation of flap gap closures. Issued 1/5/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA3419WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
180A; T.C. 5A6	SA388NW	Installation of McCauley 2A34C201/90DA-2 or -8 or McCauley 2A34C203/90DCA-2 or -8. Issued 12/23/76.	NW	61660	North Sound Aviation 1340 Peterson Road Burlington, WA 98233
180A thru 180H; T.C. 5A6	SA1943WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
180B; T.C. 3A24	SA155NW	Installation of baggage hatch with cover on EDO 249-3870 and 628-2960 floats. Issued 7/15/75.	NW	11780	Arts Aircraft Parts & Repair 4647 110th N.E. Kirkland, WA 98033

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180D, 182 Normal Category; T.C. 3A13	SA3862WE	Shorten vertical leg of the control column 1-1/4 inches to provide clearance for additional avionics equipment in the instrument panel. Issued 2/6/79.	WE	16752	Big Bear Avionics P.O. Box 768 500 Meadow Lane Big Bear City, CA 92314
180F, G, H, J; T.C. 5A6	SA3146SW-D	Mitchell automatic flight system AK602 consisting of Century IIB autopilot with optional radio coupler. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180F, G, H, J; T.C. 5A6	SA3147SW-D	Mitchell automatic flight system AK603 consisting of Century I autopilot with optional omni tracker. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180G, 180H, 180J, 180K; T.C. 5A6	SA649NW	Installation of modification to increase gross weight of floatplane to 3190 lbs. when Edo 628-2960 floats are installed. Issued 8/8/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180G, 180H; T.C. 5A6	SA1349CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
180G, H, J (S/N 18051313 and Subs); T.C. 5A6	SA2979WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
180H; T.C. 5A6	SA569EA	Installation of Tactair T-3 automatic pilot with A-651 horizon gyro and B-650 directional gyro. Issued 7/29/71.	GL	75200	George B. Stillwagon 546 Hathaway Road Dayton, OH 45419
180H, 180J; T.C. 5A6	SA2621NW	Installation of 3-bladed McCauley D3A32C90/82NC-2 propeller, Cessna 1250809 spinner. Issued 2/27/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180J; T.C. 5A6	SA556NW	Installation of Continental O-470-Rengine. Issued 1/12/79.	NW	41520	Jim Hayton 1712 A Lakeview Boulevard Mount Vernon, WA 98273
180J; T.C. 5A6	SA3183WE	Installation of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
180J, 180K; T.C. 5A6	SA659AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20511	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180K; T.C. 5A6	SA3202SW-D	Mitchell automatic flight system AK751 consisting of Century I autopilot with optional omni tracker. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K; T.C. 5A6	SA3203SW-D	Mitchell automatic flight system AK752 consisting of Century IIB autopilot with optional radio couplers. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K, T207A, 210N, P210N, 337H, P337H, T337H, 340A, 402C, 404, 421C; T.C. 5A6, A6CE, A16CE, 3A21, 3A25, A25CE, A7CE	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 5/22/80.	GL	97250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
180, 182 Series; T.C. 5A6, 3A13	SA3-123	Heater-muffler assembly 430-10P.	EA	40350	Hanlon & Wilson, Inc. 321-325 Penwood Avenue Pittsburg, PA 15644
180, 182 Series; T.C. 5A6, 3A13	SA4-868	Shackle release at wing lift strut fittings, right and left wings (restricted category only).	RM	03270	U.S. Department of Agriculture Forest Service Missoula, MT 59801
180, 182 Series; T.C. 5A6, 3A13	SA4-1092	Seat belt and seat back to accommodate additional passenger on the rear seat.	RM	39464	Green River Aviation Company P.O. Box 606 Green River, UT 84525
180, 182 Series; T.C. 5A6, 3A13	SA4-1508	Cessna 210 wing tip assemblies.	WE	42130	H & H Flying Service, Inc. P.O. Box 742 Redding, CA 96001

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180, 182 Series; T.C. 5A6, 3A13	SA5-19	Hammock seat in place of upholstered rear seat.	AL	08460	Alaska Aeronautical Ind. P.O. Box 4591 Spenard, AK 99503
180, 182 Series; T.C. 5A6, 3A13	SA108CE	Continental O-470 Series engines modified for Bendix RSA5 fuel injection system.	GL	15500	The Bendix Corporation 717 Bendix Drive South Bend, IN 46600
180, 182 Series; T.C. 5A6, 3A13	SA264SO	Cessna 210 wing tips 1223000-1 and -2.	SO	61180	Nashville Flying Service, Inc. Berry Field Nashville, TN 37202
180, 182 Series; T.C. 5A6, 3A13	SA561WE	12.7-gallon auxiliary fuel tank.	WE	05600	Aircraft Modification and Repair 20331 Hesperian Boulevard Hayward, CA 94541
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA1-519	Griswold lateralizer and heading lock.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA102SW	Automatic pilot AK109 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA4121SW	Add wing strut fairings and contour wing struts. Issued 5/5/80.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA1-576	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA334SW	Alternator.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216
180, 182, 210 Series; T.C. 5A6, 3A13, 3A21	SA96SW	Mixture control indicator kits SE-1.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216
180, 185; T.C. 5A6, 3A24	SA361NW	Installation of 8/50 x 6 main wheels with Cleveland brakes and Cleveland wheel assembly. Issued 10/15/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA701WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180, 185 Series; T.C. 5A6, 3A24	SA2273WE	Installation of Cessna Model 206 rear seats. Amended 10/18/74.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA2767WE	Installation of anti-collision lighting system. Issued 9/28/73.	WE	70500	Scientifico Scientific Components Company 350 Vista Baya Newport Beach, CA 92660
180, 185, 206; T.C. 5A6, 3A24, A4CE	SA754NW	Installation of Fernandez model 8001 and 8001A skis. Issued 4/27/79.	NW	46400	Jobmaster, Inc. 608 West Perimter Road Renton, WA 98055
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA65CE	Tow hitch assembly.	EA	73550	Soaring Society of America, Inc. Elmira, NY 14902
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA271CE	Tow hitch assembly.	CE	67207	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA1-8	Gyro-stabilizer 69A107.	GL	38175	Globe Industries, Inc. 1784 Stanley Avenue Dayton, OH 45404
182 Series; T.C. 3A13	SA1-36	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA3-18	Yaw axis stabilizer 8000B.	GL	20335	Cedar Engineering, Inc. 5806 W. 36th Street Minneapolis, MN 55401
182 Series; T.C. 3A13	SA3-44	Main ski AWB-2500A and nose wheel ski AWN-1200.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-109	Rudder trim system.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182 Series; T.C. 3A13	SA3-110	Single axis automatic pilot A-2 or A-3.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA3-171	AWB2500A main and AWN1200 nose wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-286	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562
182 Series; T.C. 3A13	SA3-348	C-3000 main ski and AWN-1200 nose wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-452	Model 3000 main skis and Model 2000 nose skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-577	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
182 Series; T.C. 3A13	SA4-39	L-2B automatic pilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
182 Series; T.C. 3A13	SA4-132	Automatic rudder control B.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
182 Series; T.C. 3A13	SA4-199	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
182 Series; T.C. 3A13	SA4-533	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA4-548	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA4-668	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
182 Series; T.C. 3A13	SA4-1359	Landing gear modified.	WE	70560	Scott Aero Service, Inc. Municipal Airport Long Beach, CA 90801
182 Series; T.C. 3A13	SA1SO	Wing tips.	SO	75880	Dale Stoughton 6408 S.W. 12 Street Hollywood, FI 33022
182 Series; T.C. 3A13	SA4EA	Single axis autopilot 510A.	EA	05950	Aircraft Radio Corporation P.O. Box 150 Boonton, NJ 07005
182 Series; T.C. 3A13	SA27SW	Automatic pilot AK088, AK088R or AK088E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA40CE	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Montorey, CA 93940
182 Series; T.C. 3A13	SA97WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA101SW	Automatic pilot AK110 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA129EA	HC-A2XF-G/8433-2 or BHC-A2XF-G/8433-2 propeller.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
182 Series; T.C. 3A13	SA183WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	90155	ZIV United Artists, Inc. 7324 Santa Monica Boulevard Hollywood, CA 90028
182 Series; T.C. 3A13	SA361WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182 Series; T.C. 3A13	SA363WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA391CE	210 wing tips.	CE	42030	Carl H. Helms 701 Lou Holland Drive Kansas City, MO 64116
182 Series; T.C. 3A13	SA450SW	Automatic pitch trim system AK134.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA461NW	Installation of Continental IO-520-F engine and McCauley D2A34C58-LMN-90AT-8 propeller. Issued 6/13/77.	NW	85615	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
182 Series; T.C. 3A13	SA489SW	Automatic pilot AK154 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA502WE	Flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA516WE	Original Goodyear wheel and brake assembly replaced with Celveland wheel and brake assembly.	RM	39464	Green River Aviation Company, Inc. P.O. Box 606 Green River, UT 84525
182 Series; T.C. 3A13	SA525WE	B-4 flight control system, including pitch assist PC-1 altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA535CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
182 Series; T.C. 3A13	SA585SO	Fuselage cutout and rerouting of rudder, elevator and trim cables. Amended 1/6/75.	SO	22787	Mr. Joel Clark P.O. Box 317 Bay Minette, AL 36507
182 Series; T.C. 3A13	SA60-SW	AK180 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA617SO	Installation of A or B of Continental O-470-M engines (per STC SE616SO).	SO	61644	North Perry Aviation, Inc. 8000 W. Pembroke Road Hollywood, FL 33023
182 Series; T.C. 3A13	SA624SW	AK197 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA659SW	AK199 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA707SW	AK243 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA709SW	AK229 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA795SW	Mitchell Century II autopilot AK241 with optional automatic aileron stabilizer and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA814WE	Modification to allow installation of camera through 15-inch diameter cutout in bottom of fuselage.	WE	08262	The Air Oasis Company 2361 Airlane San Diego, CA 92101
182; T.C. 3A13	SA1008SO	Installation of an adjustable trim tab on the left aileron. Issued 7/6/78.	SO	03110	Aero-Trim, Inc. 1150 100 Street Bay Harbor, FL 33154
182 Series; T.C. 3A13	SA1383WE	Installation of Brittain Pitch Assist Model PC-1 with Altitude Hold. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182 Series; T.C. 3A13	SA1384WE	Installation of Brittain Industries Model CSA-1 Stability Augmentation. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1474WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1671WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1673WE	Installation of Brittain Industries B-5 Flight Control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1706WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1871WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1872WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA2343WE	Installation of PHI controls Model 312 elapsed time indicator. Issued 4/27/71.	WE	64380	PHI Controls P.O. Box 6307 Torrance, CA 90504
182 Series; T.C. 3A13	SA2719WE	Installation of Symbolic Displays IFC-1A anti-collision lights. Amended 1/23/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
182, 182A thru 182F; T.C. 3A13	SA103CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
182, 182A, B, C, D, E, F, G; T.C. 3A13	SA301GL	Installation of windshield P/Ns W-2071, W/T-2071, W/G-2071, W-2072, W/T-2072, W/G-2072, W-2073, W/T-2073, W/G-2073. Reissued 5/17/79.	GL	39450	Great LAkes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
182, 182A, B; T.C. 3A13	SA355NW	Convert a Cessna 182 aircraft to tailwheel configuration. Amended 1/31/78.	NW	47708	Keefer Aircraft Engineering 11457 Glendale Way S. Seattle, WA 98168
182, 182A thru 182H, 182J thru N, P, Q; T.C. 3A13	SA950CE	STOL kit installation (wing leading leading edge cuffs, drooped tips stall fences and aileron gap seals. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
182, 210, 310, 320 Series; T.C. 3A13 3A21, 3A10, 3A25	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 thru 182D; T.C. 3A13	SA874CE	Removal of right front seat, rear seat, and baggage shelf (if installed); installation of floor level seat belt brackets to accommodate four occupants in addition to the pilot. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
182, 182A, 182B, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M; T.C. 3A13	SA935SW	Installation of cabin air conditioning system. Amended 5/7/79.	RM	01950	Aero Engineering 8C Garden Center Broomfield, CO 80020
182, 182A thru 182H, J, K, L, M, N, P, Q (Thru S/N 18266590); T.C. 3A13	SA949CE	STOL kit installation. Amended 2/4/80.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
182, 182A thru H, J thru N, P; T.C. 3A13	SA1032WE	Installation of Rajay turbosupercharged Continental O-470-L or -P engine. Amended 10/1/75.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
182 thru 182P; T.C. 3A13	SA1382WE	Installation of flap actuated aileron droop system for all models; except 182P, recontoured wing leading edge, flap actuated elevator system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182, 182A thru 182H, 182J thru 182N, 182P, Q, R182, TR182; T.C. 3A13	SA1494CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
182, A, B, C, D; T.C. 3A13	SA1579SW	Mitchell automatic flight system AK414, consisting of Century IIB autopilot with optional radio coupler. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. box 610 Municipal Airport Mineral Wells, TX 76067
182, A, B, C, D; T.C. 3A13	SA1580SW	Mitchell automatic flight system AK411, consisting of Century I autopilot with optional omni tracker. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182, 182A thru 182H, 182J thru 182Q; T.C. 3A13	SA1758WE	Installation of 12-gallon auxiliary fuel tank in each wing inboard of tip. Amended 3/15/79.	WE	35746	Flint Aero 8402-G Magnolia Avenue Gillespie Airport Plaza Santee, CA 92071
182, 182A thru 182H, 182J thru 182N; T.C. 3A13	SA1938WE	Installation of Madras Air Service "Super Tips." Amended 8/4/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
182 thru 182N; T.C. 3A13	SA2004WE	Installation of contoured wing leading edge and following options: stall fences, Robertson wing tips, positive aileron seals. Reissued 8/10/72.	NW	66175	Charyl C. Raisbeck 839 West Perimeter Road Renton Municipal Airport Renton, WA 98055
182, 182A thru 182H, 182J, 182K, 182L, 182M, 182N, 182P; T.C. 3A13	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
182, 182A, B, C, D; T.C. 3A13	SA2888SW	Replacement of control wheel. Issued 12/18/78.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
182, 182A, B, C; T.C. 3A13	SA2890SW	Installation of Continental O-470-R engine. Issued 12/20/78.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3113WE	Installation of flap gap fairing. Amended 8/22/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, 182Q, R182, TR182; T.C. 3A13	SA3349WE	Installation of vertical tail flood lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3652WE	Installation of an air/oil separator. Amended 3/13/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
182A; T.C. 3A13	SA239GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 5/1/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
182A thru 182H, 182J thru 182N; T.C. 3A13	SA1006CE	Install landing gear speedpants. Amended 10/9/74.	CE	15230	Bede Aircraft, Inc. Newton Municipal Airport P.O. Box 706 Newton, KS 67114
182A thru P; T.C. 3A13	SA25NW	Installation of insect refrigeration release equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA26NW	Installation of twine dispenser equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA67NW	Installation of twine dispenser equipment. Issued 9/10/73.	NW	80914	U.S. Department of Agriculture 3706 W. Nob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA2371WE	Installation of lure-toxicant distributor. Amended March 1974.	NW	80914	U.S. Department of Agriculture Agricultural Research Service 3706 W. Nob Hill Boulevard Yakima, WA 98902
182A, B, C, D, E, F, G, H, J, K, L, M, N, P; T.C. 3A13	SA2761SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Amended 7/15/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182B; T.C. 3A13	SA198GL	Installation of Continental 0-470-R engine in lieu of Continental 0-470-L engine using original installation hardware & components. Issued 10/20/77.	GL	64285	Mark W. Peterson and Assoc. 2627 Springdale Road Duluth, MN 55811
182D thru P; T.C. 3A13	SA27NW	Installation of auxiliary crew seat in rear seat area. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182D; T.C. 3A13	SA1338SW	Cessna NAV-O-MATIC 400 autopilot. Issued 7/9/71.	SW	12630	Autopilots Central, Inc. 3260 North Sheridan Road Tulsa, OK 74131
182E, 182F, 210B, 210C, 210-5; T.C. 3A13, 2A21	SA36EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
182E, F, G, H; T.C. 3A13	SA513SW	Heavy duty brake kits. (Also eligible on Wren 460 and 460H aircraft). Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H; T.C. 3A13	SA626SW	Nose gear wheel and tire. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K, L, M; T.C. 3A13	SA692SW	Reverse pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K; T.C. 3A13	SA789SW	Automatic aileron stabilizer AK204.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, F, G, H, J, K, L, M; T.C. 3A13	SA923SW	Droop ailerons. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, K, L, M, 206, P206, U206, 210C, D, E, F, G (205), 210-5 (205A), 210-5A, 337, 337A, B, C, D, T337B, C, D; T.C. 3A13, 3A21, A4CE, A6CE	SA1021SW	Flap on switch on control wheel. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E thru N; T.C. 3A13	SA1211SW	Automatic flight system AK310 consisting of Century I and optional tracking system. Issued 11/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, F, G, H, J, K, L, M, N; T.C. 3A13	SA1594SW	Mitchell automatic flight system AK399 consisting of Century IIB autopilot with optional radio. Issued 1/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, 182F, 182G, 182H, 182J, 182K; T.C. 3A13	SA2546WE	Installation of Pathfinder Engineering Corp. Model P1-( ) autopilot. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA2908SW	Exhaust extension. Issued 2/2/79.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182E, F, G, H, J, K, L, M, N, P (S/N 18253599 and Subs); T.C. 3A13	SA2980WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2502 E. Wardlow Road Long Beach, CA 90807
182E thru 182H, 182H thru 182Q, NOTE; T.C. 3A13	SA3608WE	Installation of replacement flexible fuel cell in wings. Issued 3/15/78. NOTE: 182E S/N 18253599 thru 182H18256143 except aircraft modified by Cessna Service Kit SK182-41; 182H S/N 18256144 and subsequent thru 182Q S/Ns. Also 182E thru 182H aircraft which have been modified by Cessna SK182-41.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
182F; T.C. 3A13	SA198EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182F; T.C. 3A13	SA933EA	Installation of wing struts modified to include Wings With Springs Model 300 hydraulic-pneumatic shock absorbers and associated airframe modifications. Amended 2/13/76.	EA	86500	Wings With Springs, Inc. Box 495, R.D. 3 Latrobe, PA 15650
182F, G; T.C. 3A13	SA403SW	Full span double slotted flaps, drooped wing leading edge, aileron actuated drag plates, Robertson U.I.S. nose control system, increased elevator aerodynamic balance, and relocated pilot head. Reissued 4/22/80.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182H, J, K, L, M; T.C. 3A13	SA485SW	STOL operations modification. (Also eligible on Wren 460H aircraft.) Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182H, J, K, L, M, N; T.C. 3A13	SA1350CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
182H, 182J, 182K, 182L, 182M (Landplane only, normal category); T.C. 3A13	SA2662WE	Removal of nose control surface (which was installed as part of Wren 460 modification in accordance with STC SA485SW). Issued 3/9/73.	WE	17125	Breuner STOL Company 50 Melody Lane Orinda, CA 94563
182H, J, K, L, M, N, P206A, P206B, P206C, P206D, P206E (landplane only); T.C. 3A13, A4CE	SA2799WE	Installation of camera pod attached to bottom of fuselage by straps. Issued 1/8/74.	WE	15190	Bechtel Corporation 50 Beale Street San Francisco, CA 94119
182K, L, M, N, P; 210G, H, J, K, L, T210G, H, J, K, L; T.C. 3A13, 3A21	SA6GL	Installation of Grimes strobe anti-collision lights. Issued 1/5/73.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
182K, L, M, N, P, Q; T.C. 3A13	SA2748SW	Streamlined nose gear kit. Issued 4/14/78.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182M Normal Category; T.C. 3A13	SA2723WE	Installation of external cargo pack (ski carrier). Issued 7/11/73.	WE	87114	Wirly Sales 7610 Owens Street Tujunga, CA 91042
182N, 182P; T.C. 3A13	SA2177WE	Installation of Brittain Ind. B-7, NAV-2B, B2C or BSS flight control system. Reissued 9/19/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182N (S/N 18260446 and up), 182P, 182Q; T.C. 3A13	SA1406CE	Install 25-gallon auxiliary fuel tank in fuselage baggage compartment. Amended 5/12/78.	CE	45250	Javelin Aircraft Company, Inc. 1978 Easy Street Wichita, KS 67230
182P; T.C. 3A13	SA1554SW	Mitchell automatic flight system AK396 consisting of Century I with optional omni tracker. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1555SW	Mitchell automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1556SW	Mitchell command/electric trim system. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA3063WE	Installation of Pathfinder autopilot system and/or electric pitch trim system. Amended 12/3/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182P; T.C. 3A13	SA3072SW-D	Mitchell automatic flight system AK540 consisting of Century III autopilot with optional radio and slope couplers. Issued 9/10/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA3190SW-D	Mitchell command electric trim AK410 Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182P, 182Q; T.C. 3A13	SA1296CE	Installation of King KFC-200 2-axis, flight control system with KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KX-292 mode controller. Amended 9/22/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
182P, 182Q; T.C. 3A13	SA1403CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
182P, 182Q; T.C. 3A13	SA3188SW-D	Install automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, 182Q; T.C. 3A13	SA3189SW-D	Automatic flight system AK396 consisting of Century 1 autopilot with optional omni tracker system. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, Q; T.C. 3A13	SA4079SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
182P, 182Q; T.C. 3A13	SA4112SW	S-TEC system 60-1 (single axis) flight guidance system, Model ST-003. Issued 4/21/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
182Q; T.C. 3A13	SA255GL	Install a Pathfinder P2A autopilot. Issued 7/19/78.	GL	04543	Air Central Enterprises 44050 Russia Road Elyria, OH 44035
182Q; T.C. 3A13	SA3279SW-D	Mitchell automatic flight system AK744 consisting of Century I autopilot with optional omni tracker. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3280SW-D	Mitchell automatic flight system AK745 consisting of Century IIB autopilot with optional radio coupler. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3281SW-D	Mitchell automatic flight system AK 746 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3763WE	Installation of Pathfinder autopilot systems. Issued 10/27/78.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
R182; T.C. 3A13	SA144RM	Installation of Pathfinder P2A single-axis autopilot. Issued 6/29/78.	RM	02454	Aeronics Jefferson County Airport Hangar B4A Broomfield, CO 80020
R182; T.C. 3A13	SA1433CE	Installation of KFC 200 flight control system with or without flight director. Amended 10/27/79.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
R182; T.C. 3A13	SA3273SW-D	Mitchell automatic flight system AK741 consisting of Century IIB autopilot with optional radio coupler. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3274SW-D	Mitchell automatic flight system AK742 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3275SW-D	Mitchell automatic flight system AK743 consisting of Century IV autopilot with optional remote annunciator. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A12	SA3316SW-D	Installation of Mitchell command electric trim system AK778. Issued 11/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
R182; T.C. 3A13	SA3834WE	Installation of Pathfinder autopilot systems. Issued 2/13/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
185 Series; T.C. 3A24	SA4-1617	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
185 Series; T.C. 3A24	SA33SO	Conversion of aircraft for parachute jumping operations.	SO	34288	Falling Angels, Inc. 339 E. New York Avenue De Land, FL 32720
185 Series; T.C. 3A24	SA84CE	25-gallon auxiliary fuel system in cargo pack. (Aircraft equipped with 62-gallon usable main fuel tanks only.)	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
185 Series; T.C. 3A24	SA108SW	Edo 289-2700 and 439-2705 amphibious floats.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
185 Series; T.C. 3A24	SA111CE	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562
185 Series; T.C. 3A24	SA147SW	Edo 429-2705 or 289-2700 amphibious floats.	SW	27270	Cruse Aviation, Inc. 8501 Telephone Road Houston, TX 77002
185 Series; T.C. 3A24	SA172WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401
185 Series; T.C. 3A24	SA202WE	Cessna 210 wing tip assemblies 1223000-1, -2, and wing tip mounted navigation lights.	NW	49270	Lake Aero Service 9306 Veterans Drive, SW Tacoma, WA 98402
185 Series; T.C. 3A24	SA215SW	L-2 autopilot.	SW	03120	Aerotron Radio Company P.O. Box 8396 Tulsa, OK 74101
185 Series; T.C. 3A24	SA213WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
185 Series; T.C. 3A24	SA261NW	Installation of automatic flagman. Issued 2/5/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362
185 Series; T.C. 3A24	SA343EA	Holes in floor of aircraft for use of viewfinder and camera.	NE	50780	Herbert P. Lindblad Mousam Road Springfield, ME 04487
185 Series; T.C. 3A24	SA417WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
185 Series; T.C. 3A24	SA1081WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
185 Series; T.C. 3A24	SA1568WE	Installation of emergency fuel system.	WE	59730	Missionary Aviation Fellowship P.O. Box 2828 Fullerton, CA 92632
185 Landplane; T.C. 3A24	SA943WE	Installation of Continental TSIO-470-B engine.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
185, 185A, B, C, D, 210, 210A, B, C, 210-5, 210-5A, 210E, F, G, H, J, K, L; T.C. 3A21, 3A24	SA1-629	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
185, A, B, C, D, E, A185E; T.C. 3A24	SA3-717	Ski installation: main gear Model 4000; tail gear Model 1500, CT-3600, CT-3200, CT-3400. Amended 2/19/76.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
185, 185A, 185B; T.C. 3A24	SA123CE	High intensity wing tip lights Model B and tail light Model C with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
185, 185A, B, C, D, E, A185E; T.C. 3A24 (Floatplane configuration)	SA169CE	Install Wipline Model 3700 or 3900 twin floats. Amended 7/22/76.	GL	86750	Wipline, Inc. South End Doane Train Inver Grove Heights, MN 55075

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
185 - 185D;	SA324AL	Installation of Continental IO-520-D engine. Revised 6/16/69.	AL	08472	Alaska Air Guides, Inc. P.O. Box 4165 Anchorage, AK 99503
185 thru 185E, A185E, A185F; T.C. 3A24	SA328CE	Install Model 180-85 aqua floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FI 33599
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA445CE	Installation of Pee Kay 3500, A3500, B3500, C3500, 2950 or 3000 seaplane floats (TSO-C27-2). Amended and reissued 1/19/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
185, 185A, 185B, 185C, 185D, 185E, A185E; T.C. 3A24	SA480AL	Installation of EDO-AIRE Mitchell Century I autopilot and omni tracker. Issued 5/25/72.	AL	03124	Aerotronics of Alaska, Inc. Box 4-1582 Anchorage, AK 99509
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA525NW	Installation of Continental IO-520-D engine and McCauley D2A34C58/90AT-4 propeller. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA526NW	Installation of Edo Model 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA587NW	Installation of Hartzell HC-C3YF-1RF/F9587C-15 propeller on Continental IO-520-D engine. Issued 5/5/78.	AL	08492	Alaska Propeller Specialists, Inc. 5251 Lakeshore Drive Anchorage, AK 99503
185, 185A, 185B, 185C, 185D, 185E; T.C. 3A24	SA631AL	Install leading edge cuff. Issued 4/28/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA746CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109
185, S/N 185-1201 and on; T.C. 3A24	SA866CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA954SW	Installation of droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
185, 185A thru 185E, A185E and F Landplanes, Seaplanes and Amphibians; T.C. 3A24	SA968CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
185, 185A, C, D, E, A185E; T.C. 3A24	SA1351CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
185, 185A thru 185E, A185E, A185F Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA1441WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge (except A185F) stall fence, flap actuated elevator trim system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA1495CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
185, 185A thru 185E; T.C. 3A24	SA2108WE	Installation of Madras Air Service wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
185, 185A thru 185E, A185E Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA2189WE	Installation of recontoured wing leading edge, stall fences, wing tips, and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, 185B, 185C, and 185D, 185E, A185E, A185F Landplane; T.C. 3A24	SA2529WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 9/20/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite G Santee, CA 92071
185, 185A, B, C, D, E; T.C. 3A24	SA2802SW	Install leading edge cuffs, stall fences, aileron seals, and wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
185, A, B, C, D, E, A185E; T.C. 3A24	SA3084SW-D	Automatic flight system AK554, consisting of Century I autopilot with optional omni tracker. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
185, A, B, C, D, E, A185E; T.C. 3A24	SA3085SW-D	Automatic flight system AK555, consisting of Century IIB autopilot with optional radio coupler. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
185, 185A, B, C, D, E, A185E, F; T.C. 3A24	SA3383WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87019
185A, A185F (Seaplane Configuration only); T.C. 3A24	SA7GL	Installation of Model 3730 amphibious floats, Model 3700, 3800 or 3900 seaplane floats. Amended 7/20/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
185A, 185E, A185E, A185F, 206, P206, P206A, U206A, TP206A, TU206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E, U206F, TU206F, U206G; T.C. 3A24, A4CE	SA522NW	Installation of float hatch kits on Edo 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA4139WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 4/10/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw AVenue Irvine, CA 92705
185B; T.C. 3A24	SA199EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
185E, A185, A185F; T.C. 3A24	SA240NW	Installation of McCauley D3A32C90/ propeller, Cessna spinner, governor, and associated systems on Continental IO-520-D engine. Amended 1/16/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
A185E; T.C. 3A24	SA507NW	Installation of Edo floats and Cessna cargo pack, Issued 8/31/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
A185E; T.C. 3A24	SA592AL	Install leading edge cuff, stall fences, and flap and aileron gap seals. Issued 7/19/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
A185E; T.C. 3A24	SA930SW	Droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
A185E; T.C. 3A24	SA1148SW	Aileron drooping device. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
A185E; T.C. 3A24	SA1990WE	Installation of Tritan Amphibious float model TA 3500. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
A185E (Floatplane Amphibian configuration only); T.C. 3A24	SA805CE	Installation of Wipline Model 3730 amphibious twin floats. Issued and amended 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
A185E, A185F; T.C. 3A24	SA501NW	Installation of McCauley D3A32C90/82NC-2 on Lycoming IO-520-D engine. Issued 8/29/77.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
A185E, A185F; T.C. 3A24	SA832EA	Installation of Edo Model 582-3430 seaplane floats. Amended 7/25/80.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185E, A185F; T.C. 3A24	SA877EA	Installation of Pee Kay Model 3500A (TSO C-27-2) amphibious floats. Amended and reissued 7/24/80.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 1 Barstow Road Great Neck, NY 11021

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A185E, A185F (Float-plane and Amphibious Configurations; T.C. 3A24	SA985EA	Installation of McCauley Propeller Model D3A32C90/82NC-2. Amended 2/25/75.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
A185E, A185F; T.C. 3A24	SA2875WE	Installation of modified brake system. Issued 4/30/74.	WE	59730	Mission Aviation Fellowship P.O. Box 142 Ramona, CA 92065
A185F; T.C. 3A24	SA17NE	Installation of EDO Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Reissued and amended 9/5/79.	NE	32625	EDO-AIRE Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185F; T.C. 3A24	SA51NW	Installation of Cessna cargo pack. Issued 7/31/73.	NW	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA164NW	Installation of EDO-628-2960 seaplane floats with Cessna cargo pack kit No. AK-185-23D, cargo pack fairing, rudder non-linear centering spring and ventral fin. Issued 2/28/75.	NW	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA420NW	Installation of cargo pac and McCauley 3-bladed propeller. Issued 3/17/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA558NW	Installation of Edo Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Amended 1/15/80.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185F; T.C. 3A24	SA596NW	Install Cessna A185E wing panels. Issued 4/27/78.	NW	08215	Airmetal Northwest, Inc. P.O. Box 387 Arlington, WA 98223
A185F; T.C. 3A24	SA634AL	Install leading edge cuff. Issued 5/31/78.	AK	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
A185F; T.C. 3A24	SA780NW	Installation of Edo 628-2960 floats on a A185F equipped with Cessna cargo pod (P/N 0700062-43) must include Cessna ventral fin (P/N 0712764-2) and linear rudder centering system. Issued 6/1/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
A185F; T.C. 3A24	SA3251SW-D	Mitchell automatic flight system AK703 consisting of Century IV autopilot or AK703FD consisting of Century IV flight director with optional remote annuciator. Issued 11/18/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
188, A188; T.C. A9CE	SA709CE	Install wing fence.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
188, A188; T.C. A9CE	SA1126SW	Alternate air filter.	SW	43500	Hutchinson Aircraft Box 1070 Borger, TX 79006
188, A188; T.C. A9CE	SA1352CE	Chrome-plated brake disc installation. Issued 3/2/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
188, A188; T.C. A9CE	SA1919WE	Installation of Madras Air Service wing tips. AMended 8/16/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
188, 188A, A188, A188A; T.C. A9CE	SA142NW	Normal and restricted category installation of recontoured wing leading edge and stall fences. Options: wing strut fillet or wing tips. Issued 12/11/74.	NW	68500	Robertson Aircraft Corporation 839 Perimeter Road Renton, WA 98055
188, 188A, A188, A188A, T.C. A9CE	SA1007CE	Installation of full spar leading edge cuffs and drooped wing tips. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
188, 188A, A188, A188A; T.C. A9CE	SA1355SW	Wing leading edge cuff to increase leading edge radius. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
188, 188A, A188, A188A; T.C. A9CE	SA1373SW	Fairing on wing strut intersection. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
188, 188A, A188, A188A; T.C. A9CE	SA1745WE	Installation of Automatic Flagman (Marker Dispensing Unit). Amended 8/10/73.	NW	03500	Air-Ag, Inc. Route 4, City County Airport Walla Walla, WA 99362
188, 188A, A188, A188A; T.C. A9CE	SA2340WE	Installation of recontoured wing leading edge, drooped ailerons, stall fences, new wing strut fillet; optional flap actuated elevator trim system, Robertson wing tips 10-105, Madras Air Services super tips. Issued 4/13/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
188, 188A, 188B, A188, A188A, A188B; T.C. A9CE	SA1179CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508, Renner Field Goodland, KS 67735
188, 188A, 188B, A188, A188A, A188B; T.C. A9CE	SA4099WE	Installation of two Conrel dispensing pads, drawing No. 21940. Reissued 5/8/80.	WE	08550	Albany International Controlled Release Division P.O. Box 537 Buckeye, AZ 85326
A188; T.C. A9CE	SA543SO	Extruded aluminum leading edge cuff. Issued 8/2/73.	SO	79820	Tunico P.O. Box 356 Tunica, MS 38676
A188, A188A, A188B; T.C. A9CE	SA99RM	Installation of freon type air conditioning system. Issued 7/12/77.	RM	32300	Dale Edlund Billings Aircraft, Logan Field Billings, MT 59102
A188, A188A, A188B; T.C. A9CE	SA900SO	Installation of cabin air conditioning. Issued 5/31/76.	SO	69228	Mr. Dwight Kerry Rudder Route 1, P.O. Box 11A Canton, MS 39046
A188B; T.C. A9CE	SA40RM	Installation of Freon air-conditioning system. Amended 3/22/76.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
A188B; T.C. A9CE	SA672NW	Installation of Hartzell HC-C3YF-1RF/F9587C-17S propeller on Continental IO-520-D engine. Issued 9/29/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
A188B, T188C; T.C. A9CE	SA461GL	Installation of hopper gate with positive metering device. Issued 10/22/80.	GL	50640	Eli Lilly and Company 740 South Alabama Street Indianapolis, IN 46285
190 Series; T.C. 790	SA3-227	APC I-11 loop and housing, ARC ADF receiver R-30A and power unit, and ARC control head.	CE	44340	Interstate Airmotive, Inc. Lambert Field St. Louis, MO 63155
190 Series; T.C. 790	SA4-1075	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
190 Series; T.C. 790	SA4-1275	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
190 Series; T.C. 790	SA42WE	Eclipse Aviation generator 790-1B.	WE	34292	Robert F. Fallon 1201 Deborah Drive Tustin, CA 92680
190 Series; T.C. 790	SA220WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	69245	Rusty's Flying Service 1041 W. Alondra Compton, CA 90220
190 Series; T.C. 790	SA354SW	Cargo conversion.	SW	33994	Executive Airlines, Inc. 206 E. Terminal Drive International Airport San Antonio, TX 78205
190, 195; T.C. 790	SA573CE	Installation of block swivel action of crosswing gear.	CE	47250	Ray M. Jourdan 11001 E. 59th Street Raytown, MO 64133
190, 195; T.C. 790	SA1492WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
190, 195, 195A, 195B; T.C. A-790	SA54GL	Install Cleveland wheel and brake conversion kit, P/N 199-61. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
190, 195, 195B; T.C. A-790	SA120NW	Installation of Hartzell HC-B3P20-4/P10160-12E propeller on Jacobs-Page R-755S engine. Amended 4/20/77.	NW	87008	William Wiprud 6443 Southwest Beaverton Hillsdale Airport Portland, OR 97221
190, 195, 195A, B; T.C. A-790	SA1284CE	Replacement axles. Issued 10/13/76.	CE	19020	Butterfly Aviation, Inc. P.O. Box 736 Renner Field Goodland, KS 67735
190, 195, 195A, B; T.C. A-790	SA2388WE	Removal of left-hand exit. Issued 7/26/71.	WE	67014	Everett A. Redding 18250 Grand Avenue Elsinore, CA 92330
195; T.C. A-790	SA199GL	Installation of oil filter between engine oil gallery and propeller governor/nose case tappet rocker arm supply. Issued 11/4/77.	GL	60093	Richard C. Moen 536 South 1st Street Dundee, IL 60118
195; T.C. 790	SA1268SW	Jacobs-Page R-755-S engine. Reissued 5/24/77.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
205, 205A; T.C. 3A21	SA3836WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Voulevard Los Angeles, CA 90064
205, 205A, 210, 210A, 210B, 210C, 210D, 210E, 210F, 210G, 210H, 210J, 210K, 210L, 210M; T.C. 3A21	SA2784SW	INstallation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions Box 431 Udall, KS 67146
206 Series; T.C. A4CE	SA65NW	Installation of fiberglass wing tips. Issued 9/20/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
206 Series; T.C. A4CE	SA635SW	McCauley DA3A32C90/82NC-2 propeller.	SW	84395	L.L. Walker Company P.O. Box 5158 Houston, TX 77012
206 Series; T.C. A4CE	SA669SW	AK218 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206; T.C. A4CE	SA685AL	Installation of Hartzell and blade propeller. Issued 5/16/80.	AL	08492	Alaska Propeller Specialists 5251 Lakeshore Drive Anchorage, AK 99503
206 Series; T.C. A4CE	SA727SW	AK231 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206 Series; T.C. A4CE	SA1255WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	73760	Sonora Aviation, Inc. P.O. Box 1027 Carson City, NV 89701
206 Series; T.C. A4CE	SA1893WE	Installation of Brittain Flight Control Systems Model B-5, NAV-2B or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
206 Series; T.C. A4CE	SA3837WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
206, P206, U206, P206A, U206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA332CE	Installation of Wipline Models 3700 and 3900 twin floats on Cessna Floatplane configuration. (Floatplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
206, P206, U206; T.C. A4CE	SA392GL	Installation of Great Lakes Aero Products windsheild P/Ns W-2065, W/T-2065 and W/G-2065. Issued 3/10/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
*206, *P206, *P206A, *U206, *U206A, U206B, C, D, E, F, G (S/N U20603522 thru U20604649, U20604659 and up) (1979 models), TP206A, TU206A, B, C, D, E, F (S/N U20601701 thru U20602199); T.C. A4CE *These models are approved with a gross weight of 3500 lbs., all others approved with 3600 lbs. gross weight.	SA439NW	Installation of Edo-696M-3500 and/or 696-3500 amphibious floats. Reissued and amended 10/22/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
206, P206, U206, U206F, Floatplane configuration; T.C. A4CE	SA474CE	Install Aqua Model 3526 floats. Reissued 7/31/78.	SC	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
206, P206, P206A, TP206A, U206, U206A, thru G, TU206A thru TU206G; T.C. A4CE	SA512CE	Installation of Pee Kay Model 3500 or A3500 or B3500 seaplane floats. Amended and reissued 7/29/80.	EA	29998	P K Floats DeVore Aviation Corporation 1 Barstow Road Great Neck, NY 11021
206, P206, U206, P206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206A, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA666CE	Install Wipline Model 3730 twin floats (amphibious). (Seaplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
206, P206, P206A, TP206A, U206, U206A thru G, TU206A thru G; T.C. A4CE	SA851EA	Installation of Pee Kay Model 3500A, C3500A and/or D3500A amphibious floats (TSO C-27). Amended and reissued 7/29/80.	EA	29998	P K Floats DeVore Aviation Corporation 1 Barstow Road Great Neck, NY 11021
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA893CE	Camera hole cut-out in lower fuselage structure. Reissued 2/17/76.	GL	59452	Mr. Wayne B. Millard 4144 South Highway 101 Minneapolis, MN 55345
206, P206, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA909CE	Install STOL kit. Reissued 4/24/79.	CE	96195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F landplanes only; T.C. A4CE	SA990CE	Install STOL kit (wing leading edge cuffs, drooped tips, and stall fences). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, TU206A, B, C, D, E, F; T.C. A4CE	SA1069CE	Enlargement of factory installed camera hole and installation of a view finder hole. Issued November 1974.	CE	36000	FloAir, Inc. Hangar #17 Mid-Continent Airport Wichita, KS 67209
206, U206A, B, D, E, TU206A, B, D, E, P206A, B, C, D, E; T.C. A4CE	SA1353CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F; T.C. A4CE	SA1513WE	Installation of flap actuated aileron droop system, recontoured wing leading edge (except TU206F and U206F), and flap actuated elevator trim system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, 210-5, 210-5A; T.C. A4CE, 3A21	SA1870WE	Installation of Brittain Model NAV-2B Flight Control. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206, U206, P206 Landplane and Floatplane, P206B, TP206B, P206C, TP206C, P206D, TP206D, P206E, TP206E Landplane and Skiplane, P206A Landplane, U206A, U206B, U206C, U206D, TU206A, TU206B, TU206C, TU206D, TU206E Skiplane; T.C. A4CE	SA2326WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, P206A, B, C, D, E, F, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G; T.C. A4CE	SA2479WE	Installation of larger fuel containing wing tips. Amended 7/25/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite G Santee, CA 92071
206, P206, 206-A, -B, -C, -D, -E, TP206A, B, C, D, E, U206, A, B, C, D, E, F; T.C. A4CE	SA2855SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G; T.C. A4CE	SA3348WE	Recognition light installation on horizontal stabilizer. Issued 3/7/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F; T.C. A4CE	SA3462WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 8/19/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
206, P206, A, B, C, D, E, TP206, A, B, C, D, E, U206, A, B, C, D, E, F, G, TU206A, B, C, D, E, F, G; T.C. A4CE	SA3739WE	Installation of Silver Instruments' fueltron IG or fueltron IP digital fuel flow and totalizer system. Amended 4/2/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
206 (S/N 206-0001 thru 206-0137 except 206-0094, S/N 206-0094, 206-0138 thru 206-0275), U206 (S/N U206-04074), P206 (S/N P206-0001 thru P206-00647); T.C. A4CE	SA3825WE	Installation of replacement flexible fuel cell in wings. Issued 8/2/79.	WE	08357	Air-Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
P206A/B/C/D/E, U206A/B/C/D/E/F/G; T.C. A4CE	SA3686WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
P206C, P206D, U206C, U206D, U206E; T.C. A4CE	SA1431SW	Mitchell automatic flight system AF368 consisting of Century III autopilot with optional automatic electric pitch trim, radio, and glide slope couplers. Issued 2/25/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206; T.C. A4CE	SA652NW	Installation of McCauley D3A32C90/82NC-2 propeller on Continental IO-520-A engine. Issued 8/15/78.	NW	64790	Robert Plummer Bob's Aircraft Maintenance Challis, ID 83226
U206, TU206; T.C. A4CE	SA1037CE	Installation of 26 gallon auxiliary fuel tank in baggage compartment. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA2782SW	Installation of Continental TSIO-520-M. Issued 5/30/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F, TU206G; T.C. A4CE	SA3856WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1430SW	Mitchell automatic flight system AF350, consisting of Century I autopilot with omni tracker. Issued 2/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1449SW	Mitchell automatic flight system AK369, consisting of Century II autopilot with optional radio coupler. Issued 3/22/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Minerals Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1572SW	Mitchell automatic flight system AK405 consisting of Century IIB autopilot with optional radio coupler. Issued 12/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1846SW	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/electronic pitch trim, radio coupler, and glide slope coupler. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1887SW	Automatic flight system AK470, consisting of Century IIB autopilot with optional radio coupler. Issued 6/17/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA3097SW-D	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/electronic pitch trim, radio coupler and glide slope coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, -D, -E, -F, TU206C, -D, -E, -F, P206C, -D, -E, TP206C, -D, -E; T.C. A4CE	SA2164WE	Installation of Edo Model FD-3500A (TSO C-27-2) amphibious floats. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
U206F, TU206F, U206G, TU206G, T.C. A4CE	SA3GL	Installation of Bendix FCS-810 autopilot and flight director. Amended 2/13/78.	GL	66080	Russell Hammer Radio Ranch, Inc. Radio Ranch Airport Polo, IL 61064
U206F, G, TU206F, G (Seaplane configuration only); T.C. A4CE	SA18GL	Installation of Wipline Model 3730 floats. Amended 6/12/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
U206F, TU206F; T.C. A4CE	SA1845SW	Mitchell automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3177SW-D	Install Mitchell automatic flight system AK470 consisting of Century IIB with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3178SW-D	Install automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, U206G, TU206F, TU206G; T.C. A4CE	SA3262SW-D	Mitchell automatic flight system AK715 consisting of Century III autopilot with optional radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3263SW-D	Mitchell automatic flight system AK714 consisting of Century IIB autopilot with optional radio couplers. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3264SW-D	Mitchell automatic flight system AK713 consisting of Century I autopilot with optional omni tracker. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3265SW-D	Mitchell automatic flight system AK717/FD consisting of Century IV/flight director autopilot with optional remote annunciator. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F (Seaplane configuration only); T.C. A4CE	SA3296WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/23/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
U206F, U206G, TU206F, TU206G;	SA3454WE	Installation of an emergency fuel system. Amended 2/7/78.	WE	59730	Mission Aviation Fellowship P.O. Box 2828 Fullerton, CA 92633
U206G, TU206G; T.C. A4CE	SA1480CE	Installation of King KFC200 automatic flight control system, two axis, with or without flight director. Issued 3/27/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
TU206C; T.C. A4CE	SA566CE	Install one or two blister windows.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
TU206C, TU206D; T.C. A4CE	SA935EA	Installation of window in bottom of fuselage at F. Station 35.5. Amended 4/18/73.	EA	52060	Long Island Airways Box 248 Ronkonkoma, NY 11779
TU206G; T.C. A4CE	SA831NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705
TU206G; T.C. A4CE	SA4004SW	Camera port. Issued 6/20/79.	SW	28490	Daily Tubbs Aero, Inc. 2115 Danbury Drive San Antonio, TX 78217
206, 207, 210 Series; T.C. A4CE, A16CE, 3A21	SA2809SW	Install Symbolic Displays CFS-1000 electronic fuel flow metering system. Issued 7/2/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206, 210 Series; T.C. 3A21, A4CE	SA149SW	Automatic pilot AK120, AK120E, AK102E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206, 210 Series; T.C. 3A21, A4CE	SA245WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
206, 210 Series; T.C. 3A21, A4CE	SA526SW	Automatic trim AK171.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206, 210 Series; T.C. 3A21, A4CE	SA674WE	Flight control system B-4 including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
207; T.C. A16CE	SA1402SW	Mitchell automatic flight system AK357 consisting of Century II autopilot with optional radio coupler. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1403SW	Mitchell automatic flight model AK356 consisting of Century I autopilot with optional omni tracker. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1404SW	Mitchell automatic flight system Model AK361 consisting of command/electric trim system. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA2856SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
207, 207A; T.C. A16CE	SA696AL	Installation of Hartzell three-blade constant speed propeller. Issued 10/10/80.	AL	08492	Alaska Propeller Specialists 5251 Lakeshore Drive Anchorage, AK 99503
207, T207; T.C. A16CE	SA1354CE	Chrome-plated brake disc installation. Issued 8/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
207, T207; T.C. A16CE	SA2121WE	Installation of recontoured wing leading edge, drooped ailerons, in flaps down mode, stall fences, and elevator trim spring. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
207, T207; T.C. A16CE	SA2327WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
207, T207; T.C. A16CE	SA2676WE	Installation of larger fuel containing wing tips. Amended 5/23/77.	WE	35780	William E. Flint 7745 Foralt Street La Mesa, CA 92041
207, T207; T.C. A16CE	SA3427WE	Installation of tail flood light on horizontal stabilizer. Reissued 2/28/90.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
210 Series; T.C. 3A21	SA1-625	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA3-503	L-2B autopilot with or without altitude controller and/or approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
210 Series; T.C. 3A21	SA4-1086	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
210 Series; T.C. 3A21	SA4-1372	Brake blocks AB-6526 and AB-6527.	EA	46748	Johns-Manville Corporation 22 E. 40 Street New York, NY 10001
210 Series; T.C. 3A21	SA4-1416	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA20SW	Automatic pilot AK086, AK086E or AK086R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA89SW	Automatic pilot AK112.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA89NW	Installation of King VOR Model KX 170B or KX 175B, King DME Model KN65 and King Area Navigation computer Model KN74. Issued 2/11/74.	NW	70040	Salem Aviation 2680 Aerial Way, S.E. Salem, OR 97302
210 Series; T.C. 3A21	SA103SW	Automatic pilot AK111.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA110EA	Removal of right front door and other modifications.	EA	72108	Sky Diving, Inc. Cameron Airpark Medford, NJ 08055
210 Series; T.C. 3A21	SA118EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA199WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	82270	V. Vincent Vandever, Inc. 6447 W. Reade Avenue Glendale, AZ 85301
210 Series; T.C. 3A21	SA330SW	Automatic pilot AK126 and lateral guidance/radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA420SW	Automatic pitch trim AK133.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA464EA	Propeller, spinner, and governor.	GL	73830	Southeastern Ohio Air Service, Inc. P.O. Box 863 Municipal Airport Zanesville, OH 43701
210 Series; T.C. 3A21	SA469WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold (optional). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA531CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210 Series; T.C. 3A21	SA618WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA627WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA637SW	AK209 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA675SW	AK212 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA1100SW	Increase wing leading edge radius. Reissued 4/22/80.	CE	85735	E.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
210 Series; T.C. 3A21	SA1305WE	PCA-1 pitch assist with altitude hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1343WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1471WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1478WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1606WE	Installation of Brittain Industries B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1609WE	Installation of Brittain Industries Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1618WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1631WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1672WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1684WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1882WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1887WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA2720WE	Installation of Symbolic Displays IFC-1A anti-collision lights. Amended 3/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
210, 210A; T.C. 3A21	SA1527WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 8/7/73.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041
210, 210A; T.C. 3A21	SA3377WE	Installation of flap gap fairing. Issued 3/24/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
210, 210A; T.C. 3A21	SA3732WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 9/14/78.	WE	84542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210, 210A, 210B, 210C, 210K, 210L, T210K, T210L, 210M, T210M, P210N; T.C. 3A21	SA52GL	Installation of Parker Hannifin wheel and brake conversion kit, P/N 199-60, on Model P210 install kit No. 199-60A. Reissued 9/11/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Avon Center Road Avon, OH 44011
210, 210F, T210F (205), 210-5 (205A), 210-5A; T.C. 3A21	SA64NW	Installation of fiberglass wing tips. Issued 9/13/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
210, 210A, 210B, 210C, 210-5; T.C. 3A21	SA93CE	High intensity wing tip lights Model B, and tail light Model C, with or without fuselage lights. Reissued 10/17/74.	GL	42626	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
210, 210A, B, C, D, E, F, 210-5(205), 210-5A (205A), T-210F; T.C. 3A21	SA940CE	STCI Kit installation. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.C. Box 608 Udall, KS 67146
210, 210A, 210B, 210C, 210D, 210E, 210F; T.C. 3A21	SA1048CE	Installation of STOL kit (wing leading edge cuffs, stall fences, aileron gap seals and droop wing tips). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
210, -A, -B, -C, 210-5 (205), 210-5A (205A); T.C. 3A21	SA1098WE	Installation of Rajay turbosupercharged Continental IO-470-E or IO-470-S engine. Amended 8/11/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
210, 210A thru 210H, 210J, K, L, T210F thru T210H, T210J, K, L; T.C. 3A21	SA1525WE	Installation of droop ailerons in flaps down mode, recontoured wing leading edge, and elevator trim spring (except on T210K, L, and 210K and L). Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
210 thru 210K, T210F thru T210K, 210-5 (205), 210-5A (205A); T.C. 3A21	SA2242WE	Installation of recontoured wing leading edge stall fences, and for 206, 205A, 210A, 210B and 210C positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
210, 210A, B, C, D, E, F, G, H, J, K, L, M, T210F, G, H, J, K, L, M, (205) 210-5, (205A), 210-5A, P210N; T.C. 3A21	SA3312WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
210, 210A, B, C, D, E, F, G, H, J, K, L, M, N, P210; T.C. 3A21	SA3453WE	Installation of a cargo container. Amended 4/25/80.	WE	02465	Aero Pod, Inc. 17202 Sandra Lee Lyn Huntington Beach, CA 92649
210A, B, C, D, E, F; T.C. 3A21	SA3649WE	Installation of replacement flexible fuel cell in the wings of the 210 Cessna aircraft. Issued 5/16/78.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
210B, C; T.C. 3A21	SA3144SW-D	Mitchell automatic flight system AK604 consisting of Century I autopilot with optional omni tracker. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B, C; T.C. 3A21	SA3145SW-D	Mitchell automatic flight system AK605 consisting of Century IIB autopilot with optional radio coupler. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B; 210-5(205), 210-5A(205A); T.C. 3221	SA3522WE	Installation of Knisley muffler in lieu of original Cessna mufflers. Issued 11/11/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
210B, 210C, 210E, 210-5(205, 210-5A (205A); T.C. 3A21	SA393GL	Installation of Great Lakes Aero Products windwhield, P/N W-2065, W/T-2065, W/G-2065. Issued 3/10/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
210C; T.C. 3A21	SA197EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
210C, D, E, F, G, H, J, K, T210F, G, H, J, K, 210-5(205), 210-5A(205A); T.C. 3A21	SA1312CE	Chrome-plated brake disc installation. Amended 9/13/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210D, E; T.C. 3A21	SA376NW	Installation of McCauley D3A32C88-XLM/S-82NC-2 propeller and Continental IO-520-A engine. Issued 11/15/76.	NW	34827	Felts Field Aviation 3100 North Division Spokane, WA 99207
210D, E, F, T210F; T.C. 3A21	SA906SW	Mitchell automatic aileron stabilizer AK211 and omni tracker AK246.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, E, F, T210F; T.C. 3A21	SA1376SW	Mitchell automatic flight system AK349 consisting of Century I with optional omni tracker. Issued 10/4/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, E, F, T210F; T.C. 3A21	SA3141SW-D	Mitchell automatic flight system AK620 consisting of Century IIB autopilot with optional radio coupler. Issued 6/3/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, 210E, 210F, T210F; T.C. 3A21	SA2677WE	Installation of larger fuel containing wing tips. Amended 4/6/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210D, E, F, G, H, J, K, L, M, T210F, G, H, J, L, M, K, P210N; T.C. 3A21	SA3751WE	Installation of Fueltron IG digital fuel flow and totalizer system. Amended 11/22/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
210D, 210E, P206; T.C. 3A21, A4CE	SA693WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
210D, E, F, G, H, J, K; T.C. 3A21	SA790CE	Installation of engine condition monitor kit ECM-6. Issued August 1971.	GL	31750	ECM Corporation 412 North Weinbach Avenue Evansville, IN 47711
210G; T.C. 3A21	SA829SW	Automatic flight system AK254 Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G; T.C. 3A21	SA850SW	AK258 consisting of Century III autopilot with optional aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, T210G, 210H, T210H, 210J, T210J, 210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N; T.C. 3A21	SA966CE	Installation of leading edge cuffs, droop tips, aileron gap seals, and stall fences. Amended 4/25/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
210G, H, J, K, L, M, T210G, T210H, T210J, T210K, T210L, T210M, 210N, P210N, T210N; T.C. 3A21	SA2862WE	Installation of larger fuel containing wing tips. Amended 7/23/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210G, H, J, T210G, H, J; T.C. 3A21	SA3168SW-D	Automatic flight system AK641 consisting of Century IV autopilot or AK641-FD consisting of Century IV flight director with optional remote annuciator. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J; T.C. 3A21	SA3169SW-D	Automatic flight system AK642 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J, K; T.C. 3A21	SA3170SW-D	Automatic flight system AK643 consisting of Century IIB autopilot with optional radio coupler. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, K, T210G, H, J; T.C. 3A21	SA3171SW-D	Automatic flight system AK644 consisting of Century I autopilot with optional omni tracker. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
T210F; T.C. 3A21	SA1042SW	Hartzell-Wren beta control system. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
T210F; T.C. 3A21	SA2277WE	Installation of Brittain Industries B2C flight control systems. Amended 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G; T.C. 3A21	SA1420WE	Installation of Brittain Industries B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G, H, J; T.C. 3A21	SA2689SW	Install TSIO-520-M engine. Issued 12/9/77.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
210H; T.C. 3A21	SA725CE	Installation of electric gyros and standby power source.	CE	43374	Humphrey, Incorporated 434 North Oliver Wichita, KS 67208
210J; T.C. 3A21	SA2249WE	Installation of Brittain Industries B-7, NAV-2B, B2C and BSS flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210J, T210J, 210K, T210K; T.C. 3A21	SA1326SW	Mitchell automatic flight system AK334, consisting of Century II autopilot with optional radio coupler, and automatic aileron stabilizer. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210J, T210J, 210K, T210K; T.C. 3A21	SA1327SW	Mitchell automatic flight system AK332, consisting of Century I autopilot with optional omni tracker. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA71RM	Installation of JB Systems air conditioning system. Amended 6/8/79.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA210NW	Collins AP-107 low profile 3 axis automatic flight control system. Amended 12/2/77.	NW	24250	Collins Radio Group 855 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA211NW	Installation of Collins AP-107 low profile two axis automatic flight control system. Amended 12/2/77.	CE	24250	Collins Radio Group 855 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA212NW	Installation of AP-107 low profile yaw damper system. Amended 12/2/77.	CE	24250	Collins Radio Group 355 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K; T.C. 3A21	SA1325SW	Mitchell automatic flight system AK331, consisting of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K; T.C. 3A21	SA2199WE	Installation of Brittain Industries B-7, NAV-2B, B2C, and BSS flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210K, T210K, 210L, T210L; T.C. 3A21	SA509SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 3/3/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210K, T210K, 210L, T210L, 210M, T210M, T210N; T.C. 3A21	SA1202CE	Installation of King Model KFC-200 two axis flight control system with or without flight director. Amended 11/28/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
210L, T210L; T.C. 3A21	SA1506SW	Mitchell aytomatic flight system AK388, consisting of Century III autopilot with optional automatic pitch trim, radio and glide slope coupler. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA1507SW	Mitchell automatic flight system AK386 consisting of Century I with optional omni tracker. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210L, T210L; T.C. 3A21	SA1526SW	Mitchell automatic flight system AK387, consisting of Century IIB autopilot with optional radio coupler. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3001SW-D	Automatic flight system AK468, Century IV autopilot or AK468FD Century IV flight director with electronic command/automatic pitch trim and optional remote annuciator panel. Issued 4/26/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3112SW-D	Automatic flight system AK566 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/5/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3247WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder Autopilot Systems and/or Pitch Trim Systems. Issued 8/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
210L, T210L, 210M, T210M; T.C. 3A21	SA1006SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 6/30/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210L, 210M; T.C. 3A21	SA3685WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
210L, 210M, T210L, T210M; T.C. 3A21	SA3192SW-D	Mitchell automatic flight system AK387 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, 210M, T210L, T210M; T.C. 3A21	SA3183SW-D	Mitchell automatic flight system AK386 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210 S/N 21061040 and up, P210N, 210M, T210M, T210N; T.C. 3A21	SA3835WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow Amended 6/12/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714
210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA1005SO	Installation of Bendix FCS-870 automatic flight control system, or installation of Bendix FCS-870 automatic flight control system with reduced flap motor speed. Amended 12/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210N, P210N, T210N; T.C. 3A21	SA756NW	Installation of leading edge stall strips, change aileron droop. Issued 4/20/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N; T.C. 3A21	SA760NW	Installation of RCA digital weather radar system. Issued 5/3/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N, P210N; T.C. 3A21	SA1420CE	Install wing leading edge cuffs (with or without de-icer boots) and wing stall fences. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
P210N; T.C. 3A21	SA180RM	Installation of Aero Engineering air-conditioning system. Reissued 10/24/80.	RM	01806	Aero Engineering Corporation 2678 Delta Drive Colorado Springs, CO 80910
P210N; T.C. 3A21	SA1487CE	Installation of King KFC200 AFCS, two axis, with or without flight director. Issued 5/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
P210N; T.C. 3A21	SA1552CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
P210N; T.C. 3A21	SA3289SW-D	Mitchell automatic flight system AK737 consisting of Century IIB autopilot with optional radio and glide slope couplers. Issued 6/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
P210N; T.C. 3A21	SA3290SW-D	Mitchell automatic flight system AK738 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P210N; T.C. 3A21	SA3291SW-D	Mitchell automatic flight system AK739 consisting of Century IV autopilot or AK739FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 210 Mineral Wells, TX 76067
210-5 (205), 210-5A (205A); T.C. 3A21	SA993CE	Install STOL kit (leading edge cuff, droop tips, stall fence and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
T210F, G, H, J, K, L, TU206A, B, C, D, E, F, TP206A, B, C, D, E; T.C. 3A21, A4CE	SA4111SW	Hartzell PHC-J3YF-IRF/F7663-2Q propeller. Issued 4/10/80.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
T210L, T210M; T.C. 3A21	SA3857WE	Installation of an air/oil separator. Issued 3/13/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nusy, CA 91409
305 Series; T.C. 5A5	SA504SW	Rerouting of oil to oil cooler and addition of extra cooler.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA295SW	Three-place configuration.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA353SW	Conversion of aircraft for parachute jumping operations.	SW	32000	Ector Aircraft Company 1703 W. Crescent Drive Odessa, TX 79760
305A; T.C. 5A5	SA505SW	McCauley 1A200PM propeller.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA568SW	Gross weight increased to 2,300 2,300 pounds.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA1201SW	Lycoming O-540-A4B5 engine. Reissued 3/19/75.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
305A; T.C. 5A5	SA1620SW	Cessna 180 fuel cells. Issued 4/19/73.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A; T.C. 5A5	SA1702SW	20-gallon fuel cells. Issued 7/19/73.	SW	32000	Ector Aircraft Company 414 East Hillmont Road Odessa, TX 79760
305A, 305B; T.C. 5A5, 3A14	SA3-370	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
305A, B, C, D, E, F; T.C. 5A5, 3A14	SA2857SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
310 Series; T.C. 3A10	SA1-21	Federal autopilot F-400.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
310 Series; T.C. 3A10	SA1-293	Lightweight reservoir pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-506	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-579	Taxi lamp in right outboard cowling.	GL	22400	Cincinnati Aircraft, Inc. Lunken Airport Cincinnati, OH 45202
310 Series; T.C. 3A10	SA3-55	Radio equipment.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310 Series; T.C. 3A10	SA3-440	L-3 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA3-475	Full feathering, constant speed propellers, hubs 2AF36C26, blades 90MF-10.	GL	52720	McCauley Industrial Corporation 1807 Howell Avenue Dayton, OH 45401
310 Series; T.C. 3A10	SA3-636	M-4 flight control system with altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA3-643	Transa-Strobe beacon B-7228.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
310 Series; T.C. 3A10	SA3-662	Hydraulic accumulator in each engine nacelle and new propeller governor C210355 or A210438.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
310 Series; T.C. 3A10	SA3-665	Cabin air temperature control system on Southwind (Stewart-Warner) 8240-A heater.	GL	82500	Vap-Air Division Vapor Corporation 6444 W. Howard Street Chicago, IL 60607
310 Series; T.C. 3A10	SA4-3	32-gallon auxiliary fuel tank in baggage compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-127	56-gallon auxiliary fuel tank in hat rack compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-239	Thompson TF2800 engine-driven fuel pump.	WE	33460	Engineering Modification Company 6850 Vineland Avenue North Hollywood, CA 91603
310 Series; T.C. 3A10	SA4-702	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
310 Series; T.C. 3A10	SA4-1217	Extension of augmenter tubes to trailing edge of wing.	WE	10116	AMC Augmenters 2648 N. Campbell Tucson, AZ 85700
310 Series; T.C. 3A10	SA4-1400	SP-3 autopilot.	WE	74570	Sperry Phoenix Company P.O. Box 2529 Phoenix, AZ 85000
310 Series; T.C. 3A10	SA4-1598	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA6SO	Window on each side of cabin between fuselage stations 89.25 and 109.375. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA37SO	Fuselage access holes in bottom skin of fuselage.	SO	76830	Sunny South Aircraft Service, Inc. 300 S.W. 41 Street County International Airport Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA44CE	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA58SC	Dual camera ports. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA59SO	One-piece windshield	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA60SO	Third window on each side of fuselage.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA61SO	Underwing exhaust system and nacelle fairings.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA77SO	Engines modified per STC SE73SO.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Fort Lauderdale, FL 33300

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310 Series; T.C. 3A10	SA97SO	A, B, or C of turbocharged Continental IO-470-D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA99SO	Auxiliary fuel tanks under nacelle fairing (4-tank and 6-tank systems).	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA109EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA119CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA202SW	Cessna 0895000-8, -9 aft cowling doors.	SW	08168	Airline Aviation, Inc. P.O. Box 1024 Roswell, NM 88201
310 Series; T.C. 3A10	SA248SO	Increase takeoff gross weight to 4,830 pounds. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA254SO	Swept vertical tail. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA303CE	Installation of Bendix Model M-4E/C autopilot flight control system. Amended 2/20/69.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA325CE	GUARD system (Gear Up Automatic Response Device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612
310 Series; T.C. 3A10	SA347SW	Cowling and exhaust system.	SW	60089	Modern Aero Sales, Inc. 4637 S. Hampton Road Dallas, TX 75221
310 Series; T.C. 3A10	SA348WE	Installation of air induction system. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2606 E. Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA385WE	Turbocharged Lycoming IO-540-A1A5 engines. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA390WE	Pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA444NW	Replace original split flaps with Fowler flaps. Issued 5/12/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
310 Series; T.C. 3A10	SA448EA	Electrothermal propeller deicing system.	GL	38500	The B.F. Goodrich Company Municipal Airport Akron, OH 44318
310 Series; T.C. 3A10	SA457SW	AK145 automatic pitch trim.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA477SO	Modify control wheel. Issued 10/27/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602 IAB Miami, FL 33148
310 Series; T.C. 3A10	SA517WE	Flight control system B-4, including pitch assist PC-1, altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA621SW	AK198 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA678SW	Lear or Motorola L-2C autopilot.	SW	03120	Aerotron Radio Company International Airport Tulsa, OK 74101
310 Series; T.C. 3A10	SA737SW	AK201 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310; T.C. 3A10	SA1359CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
310 Series; T.C. 3A10	SA1490WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1799WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1896WE	Installation of Brittain Industries NAV-2E flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA2406SW	Addition of hydro seal fluid additive to nose and main gear shock strut. Issued 2/11/77.	SW	49722	Granville Lasseter 802 East Grant Street Morton, TX 79346
310, 310A thru 310J, 320, 320A, B, C, D; T.C. 3A10, 3A25	SA1-620	Kit No. 2014X for 12-inch RCA AVQ-45, AVQ-47, AVQ-50, AVQ-55 and 12-inch Collins WP-103 radar antenna. Amended 4/15/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310B, 310C; T.C. 3A10	SA1-185	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
310 thru 310Q, T310P, Q, E310H, J, T310R, 320 thru 320E, 340, 340A, 336, 337, 337B, C, D, E, F, G, H, T337B, C, D, E, F, G, P337H, T337H, 401, 401A, B, 402, 402A, B, C, 404, 411, 411A, 414, 414A, 421, 421A, B, C; T.C. 3A10, 3A25, A7CE, A6CE, A2CE	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 4/30/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
310, 310A thru 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P,, T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA111GL	Install Cleveland conversion kit P/N 199-64. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
310-A thru 310-F, 320A thru 320-D, 320-1; T.C. 3A10, 3A25	SA302CE	Supplemental high intensity position light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
310, 310A thru H, E310H, 310J, J-1, E310J, 310K, L, N, 320, 320-1, 320-A, B, C, D, E, F, 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA362CE	Install Hoskins Twilighter Mk III and Mk IIIB light system. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
310, 310A thru J, 320, 320A thru D; T.C. 3A10	SA396EA	Installation of Radome Kit No. 2310X-P. Reissued 4/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310C; T.C. 3A10	SA814SW	Underwing exhaust.	SW	08168	Airlane Aviation, Inc. P.O. Box 1024 Roswell, NM 88204
310, 310A thru 310F; T.C. 3A10	SA574WE	Installation of leading gear position mirror on left wing tip tank. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
310, 310A, B, C, D, E, F, G, H, I, J, K, L, N, P, Q, E310H, 310J-1, E310J, T310P, T310Q; T.C. 3A10	SA3235WE	Installation of recognition light assembly on horizontal stabilizer. Issued 7/13/76.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310, 310A, B, C, D, E, F, G, H, I, J, K, L, N, P, Q, R, T310P, T310Q, T310R; T.C. 3A10	SA4136WE	Installation of inflatable door seal. Issued 4/10/80.	WE	36320	Bob Fields Aerocessories 340 "E" East Santa Maria St. San Paula, CA 93060
310, 310B; T.C. 3A10	SA26SO	Aerodynamic clean-up, cabin soundproofing, new interior and cooling duct changes. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310P, 310Q; T.C. 3A10	SA74SO	Installation of seats and camera port. Reissued 9/10/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D; T.C. 3A10	SA76SO	Installation of two (2) R.H. and two (2) L.H. single seats and enlarged emergency exit. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B thru 310G; T.C. 3A10	SA212SO	Installation of Lycoming IO-540-A1A5 engines and Hartzell HCA3XR-2B/7636D propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D, 310F; T.C. 3A10	SA455SO	Installation of extended window modification. Issued 3/18/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
310, 310F thru N; 320, 320-1, 320A thru F; 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA240WE	Consolidation of STCs SA355CE and SA362CE into one STC having MASTER ELIGIBILITY LIST - amended to include improved power supply assembly and subchassis timer assembly for Twilighter MK III hign intensity supplementary lighting system. Issued 8/16/71.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
310B, C, D, E, F, G, H, I, J, K, L, N, P, Q, T210P, T210Q; T.C. 3A10	SA3243WE	Installation of pilot's and co-pilot's side vent windows. Issued 8/13/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
310B, C, D, E, F, G, H, I, J, K; T.C. 3A10	SA391GL	Installation of Great Lakes Aero Products windshield P/Ns W-2070, W/T-2070 or W/G-2070. Amended 9/15/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
310C thru 310G; T.C. 3A10	SA2383WE	Installation of turbo-charged Continental IO-470-D engine. Issued 8/18/71.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
310C, D, F, G, H, I, J, K, L, N, P, Q, T310P, T310Q, T310R; T.C. 3A10	SA3671WE	Installation of Fueltron IIIG or IIIP digital fuel flow indicating system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
310D thru 310L, 310N, 310P, 320, 320A thru 320F; T.C. 3A10, 3A25	SA2534WE	Installation of Cessna 310P-type fiberglass tail stinger and yaw reduction adapter. Amended 5/30/73.	WE	01750	Aerocessories Company 1779 Fitzgerald Road Simi, CA 93065
310D, G, H, I, J, K, L; T.C. 3A10	SA3078SW-D	Auto flight system AK556, Century IV autopilot or AK556FD Century IV flight director. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J; T.C. 3A10	SA3079SW-D	Mitchell yaw damper system YK 558. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J; T.C. 3A10	SA3082SW-D	Automatic flight system AK557, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, E, F, G, H, I, J, K, L, N, P, Q, R, T310P, T310Q, T310R, 320-1, 320C, D, E, F; T.C. 3A10, 3A25	SA3105SW-D	Mitchell automatic flight system AK584 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310F, 310G; T.C. 3A10	SA752EA	Installation of ground to air recovery equipment. Restricted Category. Amended 8/6/69.	EA	09500	All American Eng. Company Box 1247 Lancaster Pike & Center Road Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310G, H, I, J, K, L, N, P; T.C. 3A10	SA412SO	Installation of Continental IO-520-E engines. The engines are limited to 260 hp. Amended 12/16/71.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
310G, H thru Q, J-1; E310H, J; T310P, Q; 320A, B thru F; 402, A, B, 401, A, B; 411, A; 414; 421, A, B; T.C. 3A10, 3A25, A7CE	SA568EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-0107-1. Amended 11/7/75.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
310G thru 310Q, 310R, 320A thru 320F, 340A, 401, 401A, B, 402, 402A, B, 411A, 414, 421, 421A, B; T.C. 3A10, 3A25, A7CE	SA574NW	Installation of forward facing recognition lights and clear plastic wing tip tank nose cone. Amended 4/13/78.	NW	28850	Robert M. DeBorde 20645 S.W. Clarion Aloha, OR 97005
310G, H, I, J, K, L, N, P, 310Q thru 310Q-0601; T.C. 3A10	SA3789WE	Installation of 36-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
310H; T.C. 3A10	SA294SO	Installation of turbocharged Continental IO-470-D engines. Reissued 12/5/74.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90801
310H thru 310L, 320 thru 320E, 401, 402; T.C. 3A10, 3A25, A7CE	SA1847WE	Installation of Brittain Up-Command Signal Adapter Kit. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310I, 310J; T.C. 3A10	SA181SO	Installation of turbosupercharged Continental IO-470-U engines. Amended 8/9/68.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
310I, J, K, L, N, P, Q, R, T310P, T310Q, T310R, 320A, B, C, D, E, F, 340, 401, 401A, B, 402, 402A, B, 414, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA107GL	Conversion of oil lubricated deice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
310I, J, K, L, N, P, R, Q, T310P, T310Q, T310R; T.C. 3A10	SA701CE	Install Airborne wing and tail pneumatic deice kit 703B. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
310I, L, N, P, Q, T310P, 320C, 320E; T.C. 3A10, 3A25	SA1883SW	Install Hartzell synchrophase system. Issued 6/11/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708
310I, J, K, L, N, P, Q; 320B, C, D, E, F; T.C. 3A10, 3A25	SA1904SW	Additional auxiliary transfer tanks. Issued 8/13/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708
310J, E310J, T310P, T310Q, 310K, 310L, 310N; 320D, 320E, 320F, 340; 401, 401A, 401B, 402, 402A, 402B, 414, 411, 411A, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA14GL	Installation of detachable lead strap propeller deicers. Issued 3/20/73.	GL	44318	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310J, K, L, N, P, Q, R, T310P, T310Q, T310R; T.C. 3A10	SA4718SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 6/3/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
310K, 310L, 310N, 310P, 310Q, 320E, 320F; T.C. 3A10, 3A25	SA42GL	Install Norton Company radome kit No. 3060X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310K, 310L, 310N, 320E, 320F, 310P, 310Q; T.C. 3A10, 3A25	SA490EA	Installation of Chamberlain Radome Kit No. 3060K-B for Bendix radar RDR-100 or RDR-110 systems. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310K, L, N, P, Q, 320E, 320F; T.C. 3A10, 3A25	SA150GL	Install Norton Company radome Kit No. 4131X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310K, L, N, P, Q, 320F; T.C. 3A10, 3A25	SA537EA	Installation of Radome Kit No. 3060X-R. Amended 8/25/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310L, N, P, Q: T.C. 3A10	SA2082WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Hartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68145	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
310N; T.C. 3A10	SA2784WE	Installation of Ontrac II VLF 1000 very low frequency navigation system. Amended 12/3/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3266WE	Installation of ONTRAC III VLF/Omega navigation system. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway AVenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3287WE	Installation of Ontrac III VLF/Omega navigation system as a means of navigation (but not sole means) for EN ROUTE navigation. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3924WE	Installation of ONTRAC IIIA VLF/Omega navigation system. Issued 5/25/79.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N, P, Q, T310Q; T.C. 3A10	SA3018SW-D	Automatic flight system AK442 consisting of Century III autopilot with optional command and auto. elec. elevator pitch trim, radio, and glide slope coupler. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, Q, T310P, Q; T.C. 3A10	SA3019SW-D	Automatic flight system AK443 and AK443FD consisting of Century IV autopilot and Century IV flight director autopilot with trim system and annuciator panel. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, T310P, T310Q; T.C. 3A10	SA3020SW-D	Automatic flight system YK444 consisting of yaw damper. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P, 310Q; T.C. 3A10	SA592NW	Installation of Fowler flaps. Issued 4/14/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
310P, 310Q, T310P, T310Q; T.C. 3A10	SA137NW	Installation of Collins AP-107 low profile automatic flight control system (FCS), including yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA138NW	Installation of Collins low profile yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA875EA	Installation of Brittain Industries, Inc. flight control system Model B-7 or NAV-2E or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310P, T310P, 310Q; T.C. 3A10	SA1142SW	Edo-Aire Mitchell automatic flight system, AK300 consisting of Century III with pitch trim, radio, and glide slope coupler. Issued 5/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P, Q, R, T310P, T310Q; T.C. 3A10	SA1190SW	Mitchell automatic flight FD/AP282-300 consisting of flight director/automatic pilot and automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P/T310P, 310Q/T310Q, 310R/T310R; T.C. 3A10	SA1273CE	Installation of King KFC 200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 4/14/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310 P/T 310P, 310Q/ T310Q, 310R/T310R; T.C. 3A10	SA1555CE-D	Installation of King FAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
310P, 310Q, 310R; T.C. 3A10	SA2203WE	Installation of air conditioning system. Amended 6/3/76.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
310P, T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA3602WE	Installation of vapor cycle airconditioning system. Issued 3/6/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
T-310; T.C. 3A10	SA192RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
T310, 320, 320A, B, C, D, E, F, 340, 401, A, 411, A, 414, 421, A, B; T.C. 3A10, 3A25	SA3RM	Modification of engine exhaust stacks by replacement of expansion joint with slip fit joint. Reissued.	RM	41750	Heliarc Welding Service, Inc. 3916 Niagara Street, Box 7301 Denver, CO 80207
T310 Series, 320A, B, C, D, E, F, 401, 401A, 402, 402A, B, 404, 414, 421C; T.C. 3A10, 3A25, A7CE	SA103RM	Installation of exhaust turbo connector, P/N 30477-3 Issued 8/17/77.	RM	41750	Heliare Welding Service, Inc. 3965 Newport Denver, CO 80207
T310 Series, 320, 320A, B, C, D, E, F, 340, 340A; T.C. 3A10, 3A25	SA110RM	Modify Cessna exhaust system by replacement of the inter-cylinder expansion joints with a slip fit joint.	RM	41750	Heliare Welding Service, Inc. 3965 Newport Denver, CO 80207
T310I;	SA530NW	Installation of McCauley D3A34C402/ 90DFA-10 propeller on Continental TSIO-520-H engine. Issued 10/4/77.	NW	67090	Keith L. Remington 253 S.W. 4th Avenue Ontario, OR 97914
T310P; T.C. 3A10	SA1018SW	Bendix M4-C autopilot.	SO	15475	Bendix Avionics P.O. Box 9414 Fort Lauderdale, FL 33310
T310P; T.C. 3A10	SA2292WE	Modification of waste gate controls. Issued 1/20/71.	WE	25400	Comp Air, Inc. 1285 Rollins Road Burlingame, CA 94010
T310P, T310Q, 320, 320-1, 320A thru 320F, 340, 411, 411A, 401, 401A, B, 402, 402A, B, 421, 421A, 414; T.C. 3A10, 3A25, A7CE	SA128GL	Replace existing asbestos or bellows exhaust seal with slip joint. Reissued 12/15/78.	GL	84915	Frank Webner 725 N. Hamilton Road Columbus, OH 43219
T310P, Q, 320D, E, F; T.C. 3A10, 3A25	SA2750SW	Install Continental TSIO-520-E engine. Issued 4/10/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
T310P, T310Q, T310R, 320D, 320F; T.C. 3A10, 3A25	SA2862SW	CFS-2000 electronic fuel flow metering system. Issued 10/18/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
T310P, T310Q, T310R, 320D, E, F; T.C. 3A25	SA4011SW	Installation of TSIO-520-N, or TSIO-520-NB engine. Issued 7/9/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
310Q; T.C. 3A10	SA723CE	Incorporate openable windows and drop hole.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
310Q, T310Q; 310R, T310R; T.C. 3A10	SA775CE	Installation of Janitrol Aero Division vapor cycle air conditioning system. Amended 12/9/74.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
T310Q; T.C. 3A10	SA2242SW	Continental TSIO-520-J engines. Issued 9/15/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
310R; T.C. 3A10	SA103GL	Install Norton Company radome Part No. 4096X. Amended 6/22/76.	GL	61750	Norton Company P.O. Box 350 Akron, OH 44309
310R; T.C. 3A10	SA1081CE-D	Installation of Collins Radio Group AP-106, 3-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1082CE-D	Installation of Collins Radio Group AP-107, 3-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310R; T.C. 3A10	SA1083CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1084CE-D	Installation of Collins Radio yaw damper system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R/T310R; T.C. 3A10	SA1301CE	Installation of Enk Aviation fire suppression system. Amended 11/28/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MC 64015
310, 320; T.C. 3A10, 3A25	SA99SW	Automatic pilot AK113 and lateral guidance radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320; T.C. 3A10, 3A25	SA234EA	Installation of Chamberlain 2310K-B series radome kit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309
310, 320; T.C. 3A10, 3A25	SA237SO	Control wheel modification. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 320 Series; T.C. 3A10, 3A25	SA272EA	Installation of Chamberlain 2014K-B radome kit as follows: Kit No. 2014K-B for Bendix RDP-100 or RDR-110 radar systems with 12" antenna and transmitter receiver unit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309
310, 320 Series; T.C. 3A10, 3A25	SA338SW	Automatic pilot AK125.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA409SW	Automatic pitch trim AK137.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA446CE	30-gallon auxiliary fuel tank in baggage compartment.	CE	36000	FloAir, Inc. Municipal Airport Newton, KS 67114
310, 320 Series; T.C. 3A10, 3A25	SA455WE	Single-piece windshield.	WE	20630	Cessna Components, Inc. P.O. Box 521 Long Beach, CA 90801
310, 320 Series; T.C. 3A10, 3A25	SA471EA	SAGA (Semi-automatic gear actuating) system.	GL	44010	In-Flight Services Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
310, 320 Series; T.C. 3A10, 3A25	SA521SW	Automatic pilot AK157 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA667SW	AK222 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA722WE	30-gallon wing leading edge fuel tanks. Amended 9/2/65.	WE	20630	Cessna Components, Inc. 3200 Airport Avenue Santa Monica, CA 90406
310, 320 Series; T.C. 3A10, 3A25	SA1175WE	One-piece windshield.	WE	14238	Cee Bailey's Aircraft Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
310, 320 Series; T.C. 3A10, 3A25	SA1452WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1604WE	Installation of Brittain B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1880WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310 Series; 320 Series; 336 Series; 337 Series; 401, 402, 411, 421 Series; T.C. 3A10, 3A25, A2CE, A6CE, A7CE	SA1675WE	Installation of exhaust gas temperature monitoring systems Model EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
320 Series; T.C. 3A25	SA3-737	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA101SO	One right-hand and two left-hand single seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320 Series; T.C. 3A25	SA104EA	L-2C autopilot slave cables around existing approved camera opening in lower surface of fuselage.	EA	20630	Aero Service Corporation North Philadelphia Airport Philadelphia, PA
320 Series; T.C. 3A25	SA117CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA119SO	Passenger seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320 Series; T.C. 3A25	SA127SW	Auxiliary baggage compartment and adjustable seat modification.	SW	37154	Gen-Aero, Inc. P.O. Box 6767 San Antonio, TX 78205
320 Series; T.C. 3A25	SA130CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA306CE	GUARD System (gear up automatic response device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
320 Series; T.C. 3A25	SA492SW	Emergency alternate air door actuation.	SW	33270	El Paso Natural Gas Company P.O. Box 1492 El Paso, TX 79910
320 Series; T.C. 3A25	SA632WE	B-4 flight control system including pitch assist PC-1, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
320 Series; T.C. 3A25	SA744SW	M4B/C autopilot.	SO	15475	The Bendix Corporation Avionics Group P.O. Box 9414 Fort Lauderdale, FL 33310
320, 320-1; T.C. 3A25	SA285SO	Installation of Lycoming IO-540-A1A5 powerplants and Hartzell HCA3XK-2B/7636D propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320, 320-1, 320A, 320B, 320C; T.C. 3A25	SA518SO	Installation of Continental IO-520-E derated engines and McCauley D3AF32C87/82NC-6 or -8 propellers. Issued 8/28/72.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F (320 series S/N's 0001-D9999; 320E0001-F9999); T.C. 3A25	SA110GL	Install Cleveland conversion kit P/N 199-64. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
320, 320A, 320B, 320C, 320D, 320E, 320F S/N's 0001 and on; T.C. 3A25	SA808CE	Install Airborne wing and tail pneumatic deice kit 703C. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
320, 320-1, 320A, B, C, D, E, F, 340; T.C. 3A25	SA3231WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
320, 320A; T.C. 3A25	SA3239WE	Installation of nacelle baggage lockers. Issued 7/27/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, B, C, D, E, F; T.C. 3A25	SA3242WE	Installation of pilot's and co-pilot's side vent windows. Issued 7/30/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, 320B, 320C, 320D, 320E, 320F; T.C. 3A25	SA3822WE	Installation of 34-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
320, 320A thru 320F, 320-1, 340; T310P, T310Q; 401, 401A, B, 402, 402A, B; 411, 411A, 414, 421, 421A; T.C. 3A25, 3A10, A7CE, A7CE	SA1642WE	Modification of exhaust system components. Amended 12/7/73.	SW	87348	Wooley Tool & Manufacturing Div. Chromalloy American Corporation P.O. Box 3508 Odessa, TX 79760
320A, B, C, D, E, F, 340, 340A; T.C. 3A25	SA193RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welidng Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
320A, B, C, D, E, F, 320-1; T.C. 3A25	SA3164SW-D	Install automatic flight system AK584 consisting of Century IIB automatic pilot with optional radio coupler. Issued 11/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
320A thru 320D; T.C. 3A25	SA2339WE	Installation of exhaust bellows. Issued 4/12/71.	WE	01735	Aero Bellows Manufacturing Company 3211B Winona Avenue Burbank, CA 91504
320E, 320F; T.C. 3A25	SA4GL	Installation of Bendix FCS-810 autopilot flight director system. Issued 10/18/72.	GL	47767	Ralph Kerns Kerns Aircraft Electronics, Inc. Weir Cook Municipal Airport Indianapolis, IN 46206
320E, 320V; T.C. 3A25	SA2122WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Hartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
320F; T.C. 3A25	SA4012SW	Dual camera port. Issued 7/6/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
335, 340, 340A; T.C. 3A25	SA914EA	Installation of Radome kit P/N 4057KX. Amended 7/10/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
335, 340A; T.C. 3A25	SA1302CE	Install Enk Aviation fire suppression system. Amended 10/9/79.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MC 64015
336; T.C. A2CE	SA203SW	Right front seat replaced with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72003
336; T.C. A2CE	SA286NW	Request for multiple STC on Model 336. Issued 4/23/76.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
336; T.C. A2CE	SA445SW	Automatic pilot AK140, pitch trim system AK141, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
336; T.C. A2CE	SA936CE	STOL Kit installation. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
336; T.C. A2CE	SA1260CE	Install FiQuench extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
336; T.C. A2CE	SA1355CE	Chrome-plated brake disc installation. Issued 8/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
336; T.C. A2CE	SA1875SW	Wing edge leading cuffs, wing tips, vortex generators on fuselage and fairing on vertical tails. Reissued 9/15/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
336, 337; T.C. A6CE, A2CE	SA1056SW	Revise wing contours leading edge and redesign landing light deflector plates. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
336, 337, 337A thru C; T.C. A6CE, A2CE	SA406CE	Hoskins Supp. Position Light System includes Model A wing tip lights, Model 2 fuselage light used as tail light or Model L tail light. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
337; T.C. A6CE	SA4918W	Automatic pilot AF135, automatic pitch trim AK156, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA668SW	AK210 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA1473CE	Installation of Tull microwave landing system with modified King KX175B and KN 73 receivers. Issued 2/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
337; T.C. A6CE	SA2200WE	Installation of Brittain Industries B2C and BSS flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
337, 337A, B, C, D, E, F, G, H, T337B, C, D, E, F, G, H, P337H; T.C. A6CE	SA385GL	Installation of Norton radome kit No. 4231X. Issued 2/1/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
337, 337A, B, C, D, E, F, G, M337B, T337B, C, D, E, F, G; T.C. A6CE	SA937CE	Installation of STOL kit (leading edge cuffs, stall fence, droop wing tips, and vortex generators on rear engine lower cowling). Amended 5/25/78.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
337, 337A, B, C, D, E, F, G, M337B, N337B, T337B, C, D, E, F, G; T.C. A6CE	SA1258CE	Installation of FIQUENCH fire extinguishing system in cabin and/or fire extinghishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MC 64015
337, 337A, 337B, T337B, 337C, 337D, 337E, 337F, 337G; T.C. A6CE	SA1558SW	Vortex generators on fuselage, wing leading edge cuffs, wing tips, and fairings on vertical tail. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
337, 337A (USAF 02B), 337B, M337B (USAF 02A), 337C, T337B, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G; T.C. A6CE	SA1627WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, stall fences, aileron centering springs, conical cambered wing tips and flap actuated elevator trim spring. Also takeoff gross weight increase for all models except for T337G and 337G. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
337, 337A; T.C. A6CE	SA2335WE	Installation of one-piece windshield and relocation of compass. Reissued 5/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route 1, Box 127D Leesburg, FL 32748
337, 337A, B, C, D, E, F, G, M337B, T337B, T337C, T337D, T337E, T337F, T337G; T.C. A6CE	SA3056WE	Installation of fuel flow instruments. Issued 8/15/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
337, 337A, 337B, T377B, 337C, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G, T337P; T.C. A6CE	SA3818WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
337, T337, 337E, T337E; T.C. A6CE	SA1356CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
337A; T.C. A6CE	SA190SO	Cabin door removed and wind deflector installed.	SO	90106	Young, Isherwood & Marsh P.O. Box 982 Christiansted St. Croix, Virgin Islands
337A; T.C. A6CE	SA801SW	Mitchell AF244 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A thru 337H, T337B thru H, P337H; T.C. A6CE	SA32RM	Installation of electrically driven freon air-conditioning system. Amended 11/9/78.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA1922SW	Automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 10/11/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA3250SW-D	Mitchell automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 11/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337B; T.C. A6CE	SA842SW	AK252 consisting of Century III autopilot with optional pitch trim stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337D; T.C. A6CE	SA672CE	Install auxiliary fuel tank in baggage area.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
337D; T.C. A6CE	SA678CE	Install fuselage top emergency exit door.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
337D; T.C. A6CE	SA1038EA	Installation of recognition lights (LOGO) on trailing edge of Robertson wing tips. Issued 8/9/76.	EA	29998	DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
337D, T337D, 337G, T337G; T.C. A6CE	SA478NW	Installation of Bendix weather radar system. Amended 4/13/78.	NW	67135	Renton Aviation, Inc. 840 Perimeter Road Renton, WA 98055
337D, 337E, 337F, 337G, T337D, T337E, T337F; T337G; T.C. A6CE	SA482SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and flight direcotr indicator. Amended 7/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
337E, F; T.C. A6CE	SA1359SW	Mitchell automatic flight system FD/AP282-345 consisting of flight director/autopilot with optional pitch trim. Issued 5/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F; T.C. A6CE	SA1478SW	Mitchell automatic flight system AK345 consisting of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 6/9/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067
337E, F,; T.C. A6CE	SA1520SW	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 10/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3148SW-D	Mitchell automatic flight system AK537 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3149SW-D	Mitchell automatic flight system AK536 consisting of Century IV autopilot or Model AK536FD flight director autopilot with optional remote annuciator. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3252SW-D	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 11/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337G; T.C. A6CE	SA1205CE	Installation of King KFC-200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/6/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
F337E, FT337E, F337F, FT337F, F337G, FT337GP; T.C. A23EU	SA1259CE	Install FiQuench fire extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340 Series; T.C. 3A25	SA186NW	Installation of Continental TSIO-520-J engine. Issued 5/30/75.	NW	85165	Western Skyways Portland/Trourdale Airport Troutdale, OR 97060
340 Series; T.C. 3A25	SA474NW	Replace original split flaps with Fowler flaps.	NW	68500	Robertston Aircraft Corporation 939 West Perimeter Road Renton, WA 98055
340; T.C. 3A25	SA1357CE	Chrome-plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
340 Series; T.C. 3A25	SA1441SW	Mitchell automatic flight system AK367 consisting of Century III autopilot with optional automatic pitch trim, radio, and glide slope couplers. Issued 3/15/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA1442SW	Mitchell automatic flight system FD/AP282-367 consisting of flight director/autopilot with automatic electric trim. Issued 3/3/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA1881SW	Continental TSIO-520-J engine. Issued 5/23/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
340 Series; T.C. 3A25	SA1979SW	In-line fuel pumps for auxiliary tanks. Issued 5/8/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
340 Series; T.C. 3A25	SA2346SW	Teledyne Continental TSIO-520-N engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340; T.C. 3A25	SA2770SW	Cleveland heavy duty brakes. Issued 5/9/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
340 Series; T.C. 3A25	SA3043SW-D	Mitchell automatic flight system AF525 or AF525 FD consisting of Century IV autopilot with command/automatic electric pitch trim system and optional remote annuciator panel. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA3044SW-D	Mitchell automatic flight system YF525 consisting of yaw damper system. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340; T.C. 3A25	SA3485WE	Installation of Continental TSIO-520-N engines and increase takeoff power to 310 h.p. Amended 11/18/77.	WE	68120	Riley Aircraft Corporation 2383 Palomar Airport Road Carlsbad, CA 92008
340, 340A; T.C. 3A25	SA16RM	Installation of freon type air conditioning system. Amended 10/6/77.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
340, 340A; T.C. 3A25	SA281GL	Install Cleveland conversion kit P/N 199-72. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
340, 340A; T.C. 3A25	SA502SO	Installation of Bendix FCS-810 automatic flight control system including manual eletric trim and optional flight director indicator DH-841. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340, 340A; T.C. 3A25	SA1062CE	Installation of Collins AP-107 autopilot. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
340, 340A; T.C. 3A25	SA2483SW	Increase seating capacity on aft baggage shelf for a total of 7 occupants. Reissued 3/20/78.	SW	66300	RAM Aircraft Modification P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340, 340A; T.C. 3A25	SA2844SW	Installation of SDI Model CFS-2000, -2001, or FT-200 indicating fuel flow system. Amended 3/9/79.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340, 340A; T.C. 3A25	SA3610WE	Installation of Silver Instruments Fueltron IIIG or IIIP fuel flow and totalizer system. Amended 4/24/80.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94515
340, 340A; T.C. 3A25	SA3871WE	Installation of vapor cycle air conditioning system. Issued 1/15/80.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
340, 340A (S/Ns 340A0001 thru 340A0600); T.C. 3A25	SA3923WE	Installation of Lycoming TIO-540-R2AD engines. Issued 6/1/79.	WE	68120	Riley Aircraft Corporation 2016 Palomar Airport Road Carlsbad, CA 92008
340-0001 and on; T.C. 3A25	SA55GL	Install Airborne wing and tail pneumatic deice kit 710. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
340A; T.C. 3A25	SA1015SO	Installation of Bendix FCS-870 automatic flight control system, including manual electric trim and optional flight director system. Issued 8/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
340A; T.C. 3A25	SA1025SO	Installation of a Bendix NP-2041A area navigation computer programmer. Issued 10/4/78.	SO	15475	Bendix AVionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340A; T.C. 3A25	SA1276CE	Install King KFC 200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or KG-258 attitude horizon gyro and a KC-292 mode controller. Amended 5/8/78	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
304A; T.C. 3A25	SA1551CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, 421B, 421C; T.C. A7CE	SA197GL	Install Cleveland conversion kit P/N 199-76. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
401, 401A, 401B, 402, 402A, 402B (normal category); T.C. A7CE	SA29NW	Installation of Fowler Flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 2/23/73.	NW	68500	Robertson Aircraft Corporation Renton Municipal Airport Renton, WA 98055
401, 401A, 402, 402A, 402B, 414; T.C. A7CE	SA109RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA117NW	Installation of Allison 250-B17 or 250-E17B engines and related changes. Reissued 1/6/77.	WE	25640	Commuter Investment and Development Corporation 2800 Clybourn Avenue Van Nuys, CA 91406
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414; T.C. A7CE	SA167GL	Install Cleveland conversion kit P/N 199-72. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
401, 401A, 402, 402A, B, 414; T.C. A7CE	SA194RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
401, 402, 411, 411A, 401A, 401B; T.C. A7CE	SA346EA	Installation of Chamberlain radome kit No. 2022K-B for Bendix RDR-100 or RDR-110 series radar system. Amended 7/30/71.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A; T.C. A7CE	SA437EA	Installation of radome P/N 2022X. Amended 5/27/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A, 414, 421, 421A; T.C. A7CE	SA438EA	Installation of Norton radome kit No. 2022X-3. Amended 11/2/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
401, 401A, B, 402, 402A, B, C, 411, 411A; T.C. A7CE	SA448GL	Installation of a Shadin Co. 910502 or 910504 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
401A, 401B, 402A, B, 414, 421, 421A, 421B; T.C. A7CE	SA465SO	Installation of Bendix FCS-810 automatic flight control system including flight director indicator DH-841( ) and manual electric trim. Amended 6/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA618SO	Installation of M-4B or M-4C automatic flight control systems. Amended 4/27/73.	SO	15475	The Bendix Corporation Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA646CE	Install wing and tail pneumatic deice kit 702A on 401/402 aircraft (S/N 0135 and above), kit 702B on 414 aircraft and kit 702C on 401/402 aircraft (S/N 0001 through 0134 only). Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
401, 401A, 401B, 402, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C; T.C. A7CE	SA1146SO	Installation of nose cone erosion cap. Issued 5/29/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri-City Airport Blountsville, TN 37617
401, 401A, B; T.C. A6CE	SA1158SW	Mitchell automatic flight system FD/AP282-302 consisting of flight director/automatic pilot and automatic pitch trim. Issued 6/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, 401B, 402, 402A; T.C. A7CE	SA1206SW	Edo-Aire Mitchell automatic flight system AK302, consisting of Century III autopilot with optional pitch trim, radio, and glide slope couplers. Issued 10/23/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, B, C; T.C. A7CE	SA1326CE	Installation of Avcon Industries TSC C39a stretcher. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
401, 401A, 402, 402A, 411, 411A, 414; T.C. A7CE	SA1358CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 414A, 421, 421A, 421B, 421C; T.C. A7CE	SA1393CE	Install forward baggage door warning system. Issued 1/3/78.	CE	84955	Wells Aircraft, Inc. Municipal Airport Hutchinson, KS 67501
401, 401A all S/N's, 402, 402A, 402B thru S/N 0300, 411, 411A all S/N's, 414 thru S/N 0350, 421, 421A, 421B thru 0300; T.C. A7CE	SA2091WE	Installation of air conditioning system. Amended 5/21/79.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
401, 401A, B, 402, 402A, B; T.C. A7CE	SA2845SW	Symbolic Displays CFS-2000 electronic fuel flow metering system. Issued 9/8/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
401*, 401A*, 401B*, 402*, 402A*, 402B*, 402C, 411, 411A, 414*, 414A, 421, 421A, 421B, 421C; *Includes those models modified per STC SA117NW.	SA3003WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 421, 421A, 421B; T.C. A7CE	SA3017WE	Installation of fuel flow instruments.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
401, A, B, 402, 402A; T.C. A7CE	SA3057SW-D	Mitchell automatic flight system AK538 or AK435FD consisting of Century IV autopilot or Century IV flight director autopilot with command/autopilot electric pitch trim and annunciator. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
401, 401A, B, 402; T.C. A7CE	SA3058SW-D	Mitchell flight system YK535 consisting of yaw damper system. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA3838WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
401, 401A, 401B, 402, 402A, 402B, 414 thru S/N 414-0350;	SA3930WE	Installation of 37.5 gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE T.C. A7CE	SA4117WE	Installation of Silver Instruments fueltron 111G or fueltron 111P digital fuel flow and totalizer system. Issued 3/13/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
401, 402; T.C. A7CE	SA784SW	Mitchell Model AK240 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 402; T.C. A6CE	SA1472WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402; T.C. A6CE	SA1599WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402, 411; T.C. A7CE	SA472EA	SAGA (Semi-automatic gear actuating) system. Amended 5/23/67.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
401A; T.C. A7CE	SA3192WE	Installation of single global and dual global GNS-500A navigation system. Amended 3/23/79.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
402; T.C. A7CE	SA634CE	Install tenth seat and attach FAA approved AFMS.	CE	36000	FloAir, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
402; T.C. A7CE	SA1742SW	Vapor cycle air conditioning system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
402; T.C. A7CE	SA1863SW	Two cameras and navigation sight. Issued 5/7/74.	SW	42825	A.D. Howard, Jr. 6817 N.W. 43rd Street Bethany, OK 73008
402; T.C. A7CE	SA2424WE	Installation of Allison 250-B17 engines and related changes. Amended 9/21/73.	WE	10208	American Jet Industries 3021 Airport Avenue Santa Monica, CA 90405
402, 402A; T.C. A7CE	SA2333SW	Fiberglass tailcone for magnetometer. Issued 7/23/76.	SW	42825	A.D. Howard, Jr. 1911 Moulton Court Oklahoma City, OK 73127
402A, B, C, 421B, C, 414A; T.C. A7CE	SA807EA	Installation of Norton Radome Kit No. 4009X. Reissued 5/6/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
402B; T.C. A7CE	SA700CE	Install right-hand side rear window.	CE	36000	FloAir, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
402B; T.C. A7CE	SA1061CE	Installation of Collins Company AP-107 (3 axis) autopilot system. Issued January 1975.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1110CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1111CE-D	Installation of AP-107 autopilot (2 axis). Amended June 1976.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1501CE	Sierra utility flight inspection equipment rack installed in left hand side forward location. Issued 7/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
402B, 402C; T.C. A7CE	SA1303CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
402B (S/Ns 402B0301 and up), 414 (S/Ns 414-0351 and up), 414A (S/Ns 414A0001 and up), 421B (S/Ns 421B0001 and up); 421C (S/Ns 421C001 and up) (6, 7, 8, 9 or 10 place); T.C. A7CE	SA8RM	Installation of Freon type air-conditioning system. Amended 1/12/78.	RM	45750	J.B. Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
402B, 414, 421B; T.C. A7CE	SA547SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim and optional flight director system in serial numbers 402B0301 and up, 4140351 and up, and 421B0301 and up. Issued 8/17/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
402B, 414, 421B; T.C. A7CE	SA584SO	Installation of Bendix YD-4 yaw damper system. Issued 4/5/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
402C; T.C. A7CE	SA300CE	Installation of Woodward Governor propellers on single and twin engine airplanes for P/N B210659. Issued 5/22/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
402C; T.C. A7CE	SA1502CE	Install King KFC200 automatic flight control system, with or without flight director. Amended 6/24/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
402C, 414A, 421C; T.C. A7CE	SA1526CE-D	Installation of King KAS 297 altitude selector option. Issued 2/6/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404, S/N 404-0001 and up; T.C. A25CE	SA143RM	Installation of air conditioner system. Issued 6/2/78.	RM	45750	J B Systems, Inc. P.O. Box 800 Longmont, CO 80501
404; T.C. A25CE	SA195GL	Installation of Norton radome kit 4009X.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
404; T.C. A25CE	SA195RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
404; T.C. A25CE	SA430GL	Installation of Collins LRN-70 Omega/VLF navigation system with computer program 11113322334.1. Issued 8/14/80.	GL	03465	Electrosonics Division of AiRadio Corporation 4885 Sawyer Road Columbus Int'l Airport Columbus, OH 43219
404; T.C. A25CE	SA721NW	Installation of camera bays. Issued 2/23/79.	NW	85165	Western Skyways Portland-Troutdale Airport Troutdale, OR 97060
404; T.C. A25CE	SA1297CE	Installation of King KFC 200 2-axis flight control system. Amended 5/27/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA1482CE	Installation of Tull microwave landing system. Issued 4/9/79.	CE	81650	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
404; T.C. A25CE	SA1304CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
404; T.C. A25CE	SA1600CE	Installation of TSO'd stretcher. Issued 7/17/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
404; T.C. A25CE	SA1528CE-D	Installation of King KAS 297 altitude selector option. Issued 2/18/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA3384WE	Removal of cargo doors and installation of P/N A770000 airstream deflector. Issued 6/8/77.	WE	07630	Airflite, Inc., South 2700 East Wardlow Road Long Beach, CA 90801

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
404; T.C. A25CE	SA3388WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
404; T.C. A25CE	SA4017WE	Installation of SDI model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 8/31/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
404; T.C. A25CE	SA4105WE	Installation of tail stinger and/or nose stinger. Issued 2/21/80.	WE	77500	Tallmantz Aviation, Inc. 19711 South Airport Way Santa Ana, CA 92707
404; T.C. A25CE	SA4163WE	Installation of doppler radar antenna. Issued 5/21/80.	WE	77500	Tallmantz Aviation, Inc. 19711 Airport Way South Santa Ana, CA 92707
411 Series; T.C. A7CE	SA402CE	50-gallon auxiliary fuel tank.	CE	36000	Floair, Inc. Municipal Airport Newton, KS 67114
411 Series; T.C. A7CE	SA515SW	Automatic pilot AK150, lateral guidance radio coupler AK123 and automatic trim system AK159.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA681SW	AK221 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA839EA	Installation of Radome Kit P/N 4009R-B for Bendix RDR-100 and RDR-110 systems - 12" antenna. Amended 11/29/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
411 Series; T.C. A7CE	SA1227WE	Installation of Brittain Model B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler.	EA	17500	Brittain Industries Div. Marco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
411 Series; T.C. A7CE	SA1467WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
411 Series; T.C. A7CE	SA2378WE	Installation of Global Navigation Model GNS-200 VLF navigation system. Amended 2/26/74.	WE	38090	Global Navigation, Inc. 2733 Pacific Coast Highway Torrance, CA 90505
411 Series; T.C. A7CE	SA2913WE	Installation of GNS-500 VLF navigation system. Amended 2/28/75.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
411 Series; T.C. A7CE	SA3138WE	Installation of GNS-500A VLF/OMAGE navigation system. Amended 1/17/77.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
411, 411A Series; T.C. A7CE	SA1120WE	Bendix automatic flight control system type M4B and M4C.	SO	15475	The Bendix Corporation Avionics Products Fort Lauderdale, FL 33310
400, 411A, 421, 421A; T.C. A7CE	SA102RM	Installation of exhaust turbo connector, P/N 082177-5. Issued 5/19/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street Denver, CO 80207
411, 411A, 421, 421A, 421B; T.C. A7CE	SA108RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless, sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
411, 421; T.C. A7CE	SA487CE	Install windshield wipers.	GL	27500	Marquette Metal Products Company Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
411A; T.C. A7CE	SA4167WE	Removal of main cabin door. Issued 5/29/80.	WE	18264	Richard Bungay/Richard Fowler 1345-D Silica Avenue Sacramento, CA 95815
414; T.C. A7CE	SA48NW	Installation of fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 6/29/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
414; T.C. A7CE	SA433SO	Installation of Bendix Model M4C flight control system. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
414; T.C. A7CE	SA1040CE	Installation of AP-107 autopilot. Amended 10/2/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
414; T.C. A7CE	SA1219SW	Mitchell automatic flight system AK308 consisting of Century III with automatic pitch trim, radio, and glide slope couplers. Issued 11/18/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA1899SW	Freon air conditioning system. Issued 9/9/74.	SW	37154	Gen-Aero, Inc. P.O. Box 16278 San Antonio, TX 78246
414; T.C. A7CE	SA1220SW	Mitchell automatic flight system Model FD/AP282-308 consisting of flight director/autopilot, autopilot pitch trim. Issued 11/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA2354SW	Teledyne Continental TSIO-520-N, -J, engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
414; T.C. A7CE	SA2812SW	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
414; T.C. A7CE	SA3334SW-D	Mitchell automatic flight system AK624 consisting of Century IV autopilot or AK624FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3335SW-D	Mitchell yaw damper system, YK628. Issued 3/6/69.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3366SW-D	Mitchell yaw damper system YK867. Issued 5/28/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3666WE	Installation of Silver Instruments Fueltron IIIG digital fuel flow and totalizer system. Issued 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
414; T.C. A7CE	SA3682WE	Installation of Continental TSIO-520-N engine and associated installation components. Issued 7/12/78.	WE	68120	Riley Aircraft Corporation 2386 Palomar Airport Road Carlsbad, CA 92008
414A T.C. A7CE	SA985SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director and optional yaw damper. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
414A; T.C. A7CE	SA986SO	Installation of Bendix NP-2041A NP-2041A area navigation computer programmer. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
414A; T.C. A7CE	SA1400CE	Install Enk Aviation fire suppression system. Issued 2/9/78.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
414A; T.C. A7CE	SA1431CE	Install King KFC-200 flight control system with or without flight director. Amended 6/9/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
414A; T.C. A7CE	SA1521CE-D	Installation of King KFC 250 flight control system. Amended 7/25/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
414A; T.C. A7CE	SA3304SW-D	Mitchell automatic flight system AK774/FD consisting of Century IV/ flight director autopilot with optional remote annunciator.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
414, 421; T.C. A7CE	SA536CE	Install electrical connectors in pressure bulkhead(s) at Station(s) 100 and/or 273.94. Amended 12/4/70.	RM	05940	Charles O. Peacock Aircraft Radio & Accessory Co., Inc. Hangar #4, Stapleton Field Denver, CO 80207
414, 421A; T.C. A7CE	SA732EA	Installation of radome Part No. 4004X. Amended 5/12/75.	GL	61750	Norton Company Plastics & Synethetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
414, 421A; T.C. A7CE	SA780EA	Installation of Radome Kit No. 4004K-B for Bendix RDR-100 or RDR-110 series radar systems - 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
414, 421, 421A, B, C; T.C. A7CE	SA2440SW	Airstair door saver. Issued 3/23/77.	SW	00060	AAR of Oklahoma, Inc. P.O. Box 19508 Oklahoma City, OK 73119
421 Series; T.C. A7CE	SA574CE	Installation of toilet seat belt.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
421 Series; T.C. A7CE	SA591EA	Installation of Radome Part Part No. 3084X. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
421 Series; T.C. A7CE	SA661EA	Installation of Radome Kit No. 3084K for Bendix RDR-100 or RDR-110 series radar systems 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
421 Series; T.C. A7CE	SA662CE	Installation of Jet Electronics & Technology, Inc. Model FC120A autopilot.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street Grand Rapids, MI 49508
421 Series; T.C. A7CE	SA673CE	Install Hartzell HC-B3WF-2/9349-3 propellers.	GL	41000	Hartzell Propellers, Inc. 350 Washington Avenue P.O. Box 909 Piqua, OH
421 Series; T.C. A7CE	SA968SW	Mitchell automatic flight system AK279 consisting of Century II autopilot with optional automatic pitch trim, radio, and glide slope couplers, automatic aileron stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421 Series; T.C. A7CE	SA978SW	Collins FD108 flight director system.	SW	06000	Aircraftsmen, Inc. Box 82516 Oklahoma City, OK 73108
421 Series; T.C. A7CE	SA1776WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
421, 421A; T.C. A7CE	SA794CE	Install vapor cycle air conditioning system. Reissued 10/15/71.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
421, 421A; T.C. A7CE	SA1897WE	Installation of a seventh seat in aft baggage compartment.	RM	25250	Combs Aircraft, Inc. Stapleton International Airport Denver, CO 80207
421, 421A, 421B; T.C. A7CE	SA2RM	Installation of a seventh seat in aft baggage compartment. Reissued 4/6/73.	RM	25250	Combs - Gates Denver, Inc. Stapleton International Airport Denver, CO 80207
421, 421A, 421B; T.C. A7CE	SA18NW	Installation of Fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 4/13/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
421, 421A, 421B; T.C. A7CE	SA632SO	Installation of Bendix Model M-4C automatic flight control system, including manual electric trim. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33309
421, 421A, 421B; T.C. A7CE	SA1200CE	Installation of FiQuench cabin and/or engine fire extinguishant system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
421, 421A, 421B; T.C. A7CE	SA1210CE	Installation of Hanlon & Wilson exhaust systems, P/N 8108-59 and P/N 8109-59 or P/N 8108-159 and 8109-159. Amended 3/19/80.	EA	40350	Hanlon & Wilson Company P.O. Box 641 Jeanette, PA 15644
421, 421A, 421B, 421C; T.C. A7CE	SA1343CE	Install Sierra data console on left hand seat rails. Reissued 9/15/77.	EA	71660	Sierra Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, 421B, 421C; T.C. A7CE	SA1375CE	Reduce height of existing survival seat. Reissued 10/3/77.	EA	71660	Sierra Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, B, C; T.C. A7CE	SA3228WE	Installation of Silver Instruments Fueltron IIIG or IIIP fuel indicating system. Amended 1/11/80.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545
421B; T.C. A7CE	SA135GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 10/26/76.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
421B; T.C. A7CE	SA952CE	Installation of King Radio Model KFC-300 automatic flight control system. Amended 12/19/75.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA986CE	Installation of Collins Radio Group AP-106 autopilot system. Amended January 1977.	CE	24250	Collins Radio Group Avionics Certification Center Cedar Rapids, IA 52406
421B; T.C. A7CE	SA987CE	Installation of Sperry SPZ-200/STARS IVC automatic flight control system with optional Sperry AA-220/RT-220 radar altimeter. Issued February 1974.	CE	90080	Yingling Aircraft, Inc. P.O. Box 1162 Wichita, KS 67201
421B; T.C. A7CE	SA1001CE	Installation of H-14 autopilot. Issued April 1974.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA1035CE	Installation of openable window aft of cabin door. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
421B; T.C. A7CE	SA1167CE	Installation of AP 107 autopilot (2 axis). Serials 301 and subsequent. Issued 3/29/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1667SW	Mitchell automatic flight system Model YK385 consisting of yaw damper. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421B; T.C. A7CE	SA1168CE	Installation of Collins Radio Group AP-107, 3 axis, autopilot system and interface with Collins 329A-4V indicator. Serials 301 and subsequent. Issued 10/20/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1668SW	Mitchell automatic flight system AK407, consisting of Century IV autopilot with trim; or AK407/FD consisting of Century IV autopilot/flight director with trim. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421B; T.C. A7CE	SA2749WE	Installation of Lear AFC-70 AP/FD steering computer system. Issued 8/23/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Reno, NV 89510
421B; T.C. A7CE	SA2810WE	Installation of Collins AP-105 autopilot and FD-108 flight director systems. Issued 1/30/74.	WE	78622	Tower Avionics Center Hangar 8, Oakland Int'l Airport Oakland, CA 94614
421B; T.C. A7CE	SA3881WE	Installation of dual elevator trim tab actuator. Issued 3/14/79.	WE	68120	Riley Aircraft Corporation 2386 Palomar Airport Road Carlsbad, CA 92008
421C; T.C. A7CE	SA196RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welidng Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
421C; T.C. A7CE	SA438NW	Replace original split flaps with Fowler flaps. Issued 4/22/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
421C; T.C. A7CE	SA886SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 2/26/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA890SO	Installation of Bendix FCS-810 automatic flight control system including manual electric pitch and optional flight director indicator. Amended 11/1/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA1120CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1121CE	Installation of Collins Radio Group AP-107 (2 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1122CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1191EA	Installation of Hanlon & Wilson exhaust system P/N 8294-1(L.H) and 8294-2(R.H.) Issued 4/2/80.	EA	40350	Hanlon & Wilson Company P.O. Box 641 Jeanette, PA 15644
421C; T.C. A7CE	SA1246CE	Install King KFC-200 2 axis (3 optional) flight control system with a KI-255 flight command indicator. Amended 6/2/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
421C; T.C. A7CE	SA1305CE	Installation of fire suppression system. Amended 6/24/80.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64105
421C; T.C. A7CE	SA3110SW-D	Mitchell automatic flight system AK579, consisting of Century IV autopilot or AK579FD, consisting of Century IV flight director autopilot with remote annuciator. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3111SW-D	Mitchell yaw damper YK580. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3458WE	Modification of fuselage to install camera window. Issued 7/14/77.	WE	84000	Volpar, Inc. 7929 Hayvenhurst Avenue Van Nuys, CA 91406
425; T.C. A7CE	SA1605CE	Installation of fire extinguisher system with only TFB12-0019-2 control panel assembly.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
441; T.C. A28CE	SA400GL	Installation of Litton LTN-211 Omega/VLF navigation system. Issued 6/12/80.	GL	37182	General Aviation, Inc. Capital City Airport Lansing, MI 48906
441; T.C. A28CE	SA1424CE	Install Sierra Electronics consle. Reissued 7/3/78.	EA	71660	Sierra Research Corp. P.O. Box 222 Buffalo, NY 14225
441; T.C. A28CE	SA1599CE	Installation of TSO'd stretcher. Issued 7/17/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
441; T.C. A28CE	SA2818SW	Install three place side facing couch. Issued 7/19/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
441; T.C. A28CE	SA3498WE	Installation of tail flood light on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
500 Series; T.C. A22CE	SA8GL	Installation of engine synchronizer kit P/N 213522. Issued 4/18/73.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
500 Series; T.C. A22CE	SA13RM	Installation of Branson cargo liner and retention system. Issued 7/23/73.	RM	09752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207
500 Series; T.C. A22CE	SA15RM	Installation of three-place couch with or without quick change aft divider. Amended 4/2/76.	RM	09752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500 Series; T.C. A22CE	SA18RM	Install beverage service buffet in baggage compartment. Issued 11/21/73.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA19RM	Install two lounge seats in rear of baggage compartment. Amended 11/8/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA23RM	Installation of aft beverage cabinet, P/N 90241-1. Amended 5/20/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA47RM	Installation of single seat in the center of aft baggage compartment. Reissued 3/10/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
500 Series; T.C. A22CE	SA51RM	Installation of tail cone ski rack. Reissued 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series; T.C. A22CE	SA52RM	Installation of stretcher. Amended 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series; T.C. A22CE	SA54RM	Installation of tail cone storage box and engine cover storage box. Amended 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CC 80033
500 Series; T.C. A22CE	SA58RM	Installation of deluxe three-place aft couch. Amended 10/7/77.	RM	17085	Branson Engineering Company, Inc. 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA79RM	Installation of side-looking camera hatch. Reissued 7/29/77.	CE	20625	Cessna Aircraft Company Wichita Municipal Airport P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA83RM	Increased ramp and takeoff weights for restricted category operation. Issued 10/22/76.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CC 80033
500 Series; T.C. A22CE	SA97RM	Installation of dual aft lounge seats. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CC 80033
500 Series; T.C. A22CE	SA100RM	Installation of lounge seat toilet. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	ST131RM	Installation of Global Navigation, Inc. GNS-500A VLF/Omega navigation system. Issued 2/7/78.	RM	14127	Avionics Engineering of Denver, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
500; T.C. A22CE	ST174RM	Installation of extended width cabin door. Issued 5/4/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500; T.C. A22CE	SA402GL	Installation of a Sperry SPZ500 flight/director/autopilot system. Issued 4/18/80.	GL	47636	Kal-Aero, Inc. Kalamazoo Municipal Airport 5605 Partage Road Kalamazoo, MI 49002
500; T.C. A22CE	SA645NW	Increased fuel and performance modifications. Issued 8/4/78.	NW	12270	Astec Engineering, Inc. 830 N. Riverside Drive Renton, WA 98055
500; T.C. A22CE	SA802NW	Installation of transponder identification switch on left hand control wheel. Issued 7/13/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
500 Series; T.C. A22CE	SA897SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement battery. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
500 (S/N 500-001 thru -0213); T.C. A22CE	SA991CE	Installation of KFC-300 automatic flight control system. Amended 4/10/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
500 Series; T.C. A22CE	SA1013CE	Installation of retractable aircraft recognition lights. Amended 7/26/78.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 Series; T.C. A22CE	SA1059EA	Installation of an airways calibration system. Reissued 9/27/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500 (S/N 350 and on); T.C. A22CE	SA1371CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 Series; T.C. A22CE	SA1574SW	Installation of hassock according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500; T.C. A22CE	SA1579CE	Installation of tail-cone baggage compartment. Issued 3/7/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
500 Series; T.C. A22CE	SA1589SW	Installation of Singer Kearfott SKF-1000A doppler system; Collins INS-61B inertial navigation system; JET PS 823E emergency power system. Reissued 11/20/73.	CE	20225	Cessna Aircraft Company P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA1597SW	Stretcher installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 N. Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1619SW	Installation of emergency power supply according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1727SW	Jump seat. Issued 9/13/73.	SW	12250	Associated Radio Service Company Box 20718 Dallas, TX 75220
500 Series; T.C. A22CE	SA1945SW	Aft equipment bay storage unit. Issued 1/7/75.	SW	38242	William L. Goin, Jr. 7930 Airport Boulevard Houston, TX 77617
500 Series; T.C. A22CE	SA2383SW	Install refreshment bar and galley bulkhead. Issued 11/19/76.	SW	94600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
500 Series; T.C. A22CE	SA2925WE	Installation of power brake and skid control system. Issued 9/24/74.	WE	13230	Aviation Brake Systems, Ltd. 3535 West 5th Street Oxnard, CA 93030
500, 501; T.C. A22CE	SA2698SW	Freon air conditioning system. Issued 12/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
500, 501; T.C. A22CE, A27CE	SA2883SW	Installation of Ray Electronics Model 7507A battery current monitoring system. Issued 12/7/78.	SW	66500	Ray Electronics Company 11933 Warfield Drive San Antonio, TX 78216
500, 501; T.C. A22CE, A27CE	SA4034SW	Zee systems air conditioner. Issued 8/30/79.	SW	28775	Darling Aviation, Inc. P.O. Box 79230 Fort Worth, TX 76179
500, 501, 550, 551; T.C. A22CE, A27CE	SA1051SO	Replace existing nickel-cadmium batteries with Teledyne Gill BE638/T series lead-acid battery. Issued 3/29/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
500, 501, 550, 551; T.C. A27CE, A22CE	SA2916SW	Installation of alternate gear horn switch. Issued 2/26/79.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75060
500, 501, 550, 551; T.C. A27CE, A22CE	SA4054SW	Installation of one, two, or three-place side facing seat, frame only. Issued 10/23/79.	SW	28000	Custom Aircraft Conversions 234 West Turbo Drive San Antonio, TX 78216
500, 550; T.C. A22CE	SA80RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Amended 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST151RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST166RM	Installation of three-place or single-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST174RM	Installation of extended width cabin door. Amended 5/18/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	SA1457CE	Install microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500, 550; T.C. A22CE	SA1513CE	Installation of Avcon 4001-213 and -214 stretcher. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
500, 550; T.C. A22CE	SA1534CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
500, 550; T.C. A22CE	SA2906WE	Installation of vertical tail floodlights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E.
500, 550; T.C. A22CE	SA3000SW	Fabrication and installation of 3-place side facing couch and shoulder harness. Issued 5/25/79.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
501; T.C. A27CE	ST117RM	Installation of deluxe three-place aft couch. Issued 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	ST118RM	Installation of tail cone storage box and engine cover storage box. Issued 10/22/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	SA125RM	Installation of tail cone ski rack. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA126RM	Installation of stretcher. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA152RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Issued 9/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA177RM	Installation of a single seat in the center of aft baggage compartment. Issued 6/25/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA732NW	Installation of "Eagle" performance kit. Issued 5/10/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
501; T.C. A27CE	SA1372CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
501; T.C. A27CE	SA1423CE	Insalll King KFC-300 AFCS with duel flight director and transfer-able autopilot. Issued 6/21/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
501; T.C. A27CE	SA1580CE	Installation of tail-cone baggage compartment. Issued 3/7/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
501, 551; T.C. A27CE	SA150RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA171RM	Installation of three-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA1514CE	Installation of Avcon 4001-213 and -214 stretchers. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA1535CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA3409WE	Installation of vertical tail floodlights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
550; T.C. A22CE	ST165RM	Installation of fiberglass tail cone in lieu of metal tail cone. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
550; T.C. A22CE	SA458GL	Installation of a Collins LRN-70 VLF/Omega navigation system. Issued 10/2/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
550; T.C. A22CE	SA1499CE	Installation of Total Flood (TFC) Halon 1301 fuselage flood system. Issued 7/11/79.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
551; T.C. A27CE	SA1500CE	Installation of Total Flood (TFC) Halon 1301 fuselage flood system. Issued 7/11/79.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
CH-1C; T.C. 3H10	SH4WE	Fifth passenger seat and seat belt.	NW	84625	Washington Aircraft & Transport Co. Boeing Field Seattle, WA 98101
Miscellaneous	SA582NW	Replacement wire rope cable assemblies. Issued 5/12/78.	NW	81180	University Swedging 800 N.W. 46th Street Seattle, WA 98108

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

COMMONWEALTH AIRCRAFT, INC.
DECEMBER 31, 1980

Aircraft Make, Model & T.C. No.	STC No.	Description	RG	STC Code	STC Holder
175; T.C. A-729	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
175, 180, 180F, 185, 190F; T.C. 729	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92505
175, 180, 180F, 185, 190F; T.C. 729	SA4-1208	Ceconite covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
175, 180, 180F, 185, 190F; T.C. 729	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
175, 180, F, 185, 190F; T.C. A-729	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
175, 180, F, 185, 190F; T.C. A-729	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
175, 180, -F, 185, 190F; 6000M; 9000; T.C. 729, 661, 624	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
175, 180, 180F, 185, 190F, 6000M, 9000, 9000 Deluxe; T.C. 729, 661, 624	SA2666WE	Ceconite 102 material covering of: 175, 180, 180F, 185, 190F - 4677 complete aircraft; 6000M - fuselage; 9000, 9000 Deluxe - wings, ailerons, horizontal stabilizer, elevators, vertical fins, rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
180; T.C. A-729	SA3976WE	Installation of McCauley 1B90CM7038 propeller on aircraft equipped with Continental A-80-9 engine. Issued 6/20/79.	WE	28798	John E. Daugherty 3066 East St. Louis Avenue Las Vegas, NV 89104
185; T.C. 729	SA4-901	Fiberglas covering on wings.	WE	38060	Glasco-Air Products Oxnard-Ventura County Airport Oxnard, CA 93030
185; T.C. 729	SA81GL	Installation of Continental C90-12F engine, McCauley 1B90CM7146 propeller, Maule tail wheel P/N SFS-1-4-P8. Issued 5/29/75.	GL	16890	Harvey Bolin Brandon, MN 56315
185; T.C. 729	SA1008WE	Installation of Poly-Fiber covering material. Amended 8/7/69.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92502
6000M; T.C. 661	SA441WE	Ceconite 101 covering of fuselage.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
7000, 9000L; T.C. 574, 591	SA519WE	Wheel adapters on Goodyear wheels 3LMBM.	WE	49345	Robert P. Lamb 2998 Daisy Avenue Long Beach, CA 90801
9000, 9000 Deluxe; T.C. 624	SA229WE	Ceconite 101 covering of wings, ailerons, horizontal stabilizer, elevators, vertical fin and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

COSTRUZIONI AERONAUTICHE GIOVANNI AGUSTA

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A109, A109A; T.C. H7EU	SH1190EA	Installation of Aircraft Parts Corp. (APC) starter-generator, P/N 150SG1110. Issued 4/1/80.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
A109A; T.C. H7EU	SH1135EA	Installation of a Collins ANS-31A area navigation system. Collins DME-40 system and miscellaneous avionic modifications. Reissued 10/27/80.	EA	12500	Costruzioni Aeronautiche Giovanni Agusta S.P.A. Cantieri-Campo Aviazione Cascina Costa (Gallarate) Italia
A109A; T.C. H7EU	SH2699SW	Stability augmentation/avionics equipment and cockpit modification for certification of single and pilot day-night (IMC) operations. Issued 5/18/78.	SW	12496	Atlantic Aviation Wm. P. Hobby Airport P.O. Drawer 12782 Houston, TX 77017

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
C-46, C-46/CW-20F, Super C-46; T.C. A772	SA1340WE	Cabin interior arrangement.	WE	44186	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238
C-46, C-46/CW-20F, Super C-46; T.C. A772	SA1341WE	Oxygen system.	WE	44186	Intermountain Aviation, Inc. Marana Air Park Marana, AZ 85238
C-46, C-46/CW-20F, Super C-46; T.C. A772	SA1744WE	Installation of various series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
C-46, C-46/CW20-T, Super C-46/CW20-T; T.C. 2A5, 3A2, 772, 786, 789, 808	SA117SO	Bergstrom BS-040-2 oil separator DL-040.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
C-46, C-46/CW20-T; T.C. 2A5, 3A2, 772, 786, 789, 808	SA129AL	Flap actuated landing gear aural warning device.	AL	67017	Reeve Aleutian Airways, Inc. P.O. Box 6027 Anchorage, AK 99500
C46A, C46D, C46F, C46R, C46E, CW-1; T.C. 3A2, 772, 789, 786, 808, 397	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C-46A, C46D, C46E, C-46F, C-46R; T.C. 3A2, 772, 786, 789, 808	SA249CE	Install supplementary lighting system using Model B or F wing tip lights and Model C tail light. Optionally, two Model 2 fuselage lights may be used with Model B wing tip lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
C46A, D, E, F: T.C. A-772	SA1620WE	Modification of floor deck.	NW	73820	Sorm Industries 7999 Perimeter Road South Seattle, WA 98109
C-46A, -46F; T.C. A-772	SA1380WE	Installation of four 500-gallon fuel oil tanks in fuselage. Reissued 5/31/77.	AL	08488	Alaska International Air, Inc. P.O. Box 60029 Fairbanks, AK 99701
C-46/CW20-T; T.C. 2A5, 3A2, 772, 786, 789, 808	SA4-115	Aerofilter 30816A.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
C-46/CW20-T; T.C. 2A5	SA4-568	Engine mount core assemblies DE1468.	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
C-46/CW20-T, Super C-46/CW20-T; T.C. 2A5	SA88SO	B-400 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
Robin J-1, J-1 De Luxe; T.C. 220	SA4-1561	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
J-1; 12-W; C-46A, -D, -E, -P, 4000; B-4000; B9-, C-; D-, E-, K-, L-, W-; ATC 220, 407, 32, 146, 149, 188, 205, 112	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C-46A, -46D, -46E, -46R (Robin) J-1, J-1 Deluxe, (Travel Air) 12-W, 4000, B-4000, B9-4000, C-4000, D4000, E4000, K-4000, L-4000 (Parks), W-4000; T.C. 3A2, 220, 407, 32, 146, 2-381, 149, 2-84, 188, 205, 2-560, 112	SA2666WE	Ceconite 102 material covering of: C-46A, -46D, -46F, -46R - ailerons; 4677 J-1, J-1 Deluxe - wings; 12-W - entire airframe; 4000, B-4000, B9-4000, C-4000, D-4000, E-4000, K-4000, L-4000, W-4000 - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. Worth Street Los Angeles, CA 90063
Travel Air 4000; T.C. 32	SA4-557	Wing center-section fittings (front and rear).	WE	27310	Dudley H. Cunningham 539 B Street Yuba City, CA 95991
Travel Air 4000; A.T.C. 32	SA1008WE	Installation of poly fiber covering material of fuselage, rudder and elevators. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
Travel Air 4000 Series; T.C. 2-381, 2-84, 2-560, 32, 146, 149, 188, 205, 112	SA700WE	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
DEHAVILLAND AIRCRAFT
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH82A; T.C. A8EU	SA1008WE	Installation of poly-fiber covering material of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
DH82A; T.C. A8EU	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 6/6/74.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Tiger Moth N-82DS; T.C. A8EU	SA2666WE	Covering of Ceconite 102 material on wings, fuselage and empennage. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Beaver DHC-2; T.C. 806	SA3-105	L2C automatic pilot with altitude control and approach coupler. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
Beaver DHC-2; T.C. 806	SA3-591	C5500 main ski and AWB4820 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
Beaver DHC-2; T.C. 806	SA4-182	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
Beaver DHC-2; T.C. 806	SA4-322	Full-flow oil filter 1050-B-83 with element 1A0094.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
Beaver DHC-2; T.C. 806	SA37EA	Removal of left rear cabin door for parachute jumping operations.	NE	85240	Westover SAC Aero Club Westover AFB, MA 01022
Beaver DHC-2; T.C. 806	SA115WE	Pratt & Whitney R-985-APS4 installation converted under STC SE4-864.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
Beaver DHC-2; T.C. 806	SA245AL	Relocation of wing tip fuel control valve.	AL	44050	U.S. Department of Interior Bureau of Commerical Fisheries P.O. Box 6088 Anchorage, AK 99500
Beaver DHC-2; T.C. 806	SA263SO	Removal of power plant extinguisher system and installation of firewall patches.	SO	74928	State Airlines, Inc. Municipal Airport Charlotte, NC 28208
Beaver DHC-2; T.C. 806	SA284NW	Installation of 3 place center seat in aircraft using original civilian or UgA military floor fittings. Amended 6/17/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA305NW	Installation of EDO 5250 floats and stabilizer fins. Issued 6/15/76.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA306NW	Installation of EDO 4665 floats. Issued 6/15/76.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA309NW	Installation of auxiliary vertical stabilizer fins. Issued 6/15/76.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA356NW	Installation of EAC-2D30-425/AG-100-4S propeller on Pratt & Whitney R-985 series engines. Issued 9/13/76.	NW	62120	Pacific Propeller P.O. Box 946 Kent, WA 98031
Beaver DHC-2; T.C. 806	SA397NW	Remove transport battery and battery box and install Gill 12-GCAB-9 or equal battery and battery box relocated to firewall per II K-8784. Issued 1/21/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA398NW	Install Hartzell HC-B3R30-4 propeller with R10152-5 1/2 blades, Hartzell C-4 propeller governor and Hartzell 836-32SR propeller spinner per II K-8785. Issued 1/24/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Beaver DHC-2; T.C. 806	SA415NW	Installation of EDO Model Wb-5030 floats. Issued 3/10/77.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA416NW	Installation of EDO Model 61-5870 floats. Issued 3/10/77.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-2; T.C. A-806	SA417NW	Installation of EDO Model Ya-6235 floats. Issued 3/10/77.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-2; T.C. A-806	SA523NW	Installation of float hatch covers on Edo 58-4580, 348-4580 or 679-4930 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2; T.C. A-806	SA524NW	Remove left or right rear cabin entrance door. Issued 10/12/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2; T.C. A-806	SA547AL	Modification of elevator and horizontal stabilizer tips. Issued 4/7/75.	AL	44050	U.S. Department of Interior Office of the Secretary Office of Aircraft Services 1936 Merrill Field Drive Anchorage, AK 99501
DHC-2; T.C. A-806	SA590NW	Installation of Hartzell HC-B3R30-1/R10152-5-1/2 propeller on P & W R-985 series engine. Amended 6/9/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA622WE	Fuel injected Pratt & Whitney R-985-AN-1, -2, -3, -4, -6, -6B, -8, -10, -12B, -14B, -14B1 or Wasp Jr. SB-3 engine.	WE	13750	Aviation Power Supply, Inc. 3011 Kenwood Street Burbank, CA 91503
DHC-2; T.C. A-806	SA646NW	Modification of main landing gear axles. Issued 11/1/78.	NW	37175	General Aircraft Supply 7149 Perimeter Road, S. Seattle, WA 98108
DHC-2; T.C. A-806	SA660WE	Installation of HRD-type fire extinguishing system. Amended 7/11/77.	WE	43180	HTL Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
DHC-2; T.C. A-806	SA703NW	Installation of enlarged side windows for aft cabin. Issued 1/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2; T.C. A-806	SA736NW	Installation of Cleveland 40-46 wheels and 30-31 brakes. Issued 4/6/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Beaver DHC-2; T.C. 806	SA1744WE	Installation of various series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
Beaver DHC-2; T.C. 806	SA1829WE	Installation of EDO Model 679-4930 floats.	NW	46400	Jobmaster Company, Inc. 1005 W. Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
DHC-2, MK 1; T.C. A-806	SA107NW	Installation of EDO Model Yd-6470 floats. Reissued 10/22/74.	GL	71516	Shawano Flying Service 248 Airport Road Shawano, WI 54166
DHC-2, MK1; T.C. A-806	SA425NW	Installation of 75 lb. capacity baggage compartment below the existing baggage compartment. Issued 3/28/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK1; T.C. A-806	SA426NW	Enlarged baggage compartment. Issued 3/23/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DH-2, MK1; T.C. A-806	SA427NW	Cabin access steps attached to float struts. Issued 3/28/77.	NW	47740	Kenmore Air Harbor P.C. Box 64 Kenmore, WA 98028

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DHC-2, MK1; T.C. A-806	SA428NW	Water rudder steering system. Issued 3/28/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK1; T.C. A-806	SA456NW	Installation of auxiliary seaplane stabilizer fins. Issued 6/2/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK 1; T.C. A-806	SA527AL	Removal of left rear door for parachute jumping. Issued 8/9/74.	AL	19906	A. Dean Carrell 7100 Lake Otis Parkway Anchorage, AK 99507
Beaver DHC-2, MK 1; T.C. 806	SA1913WE	Installation of EDO Model 679-4930 floats. Amended and reissued 8/27/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
DHC-2, MK 1; T.C. A-806	SA2520WE	Hatch installation in Bristol amphibious floats. Issued 4/28/72.	NW	61626	North Country, Inc. 2525 14th Avenue South Seattle, WA 98168
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14(14V) or -28(28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA800EA	Installation of Aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W (red/white), or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
Otter DHC-3; T.C. 815	SA4-183	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
Otter DHC-3; T.C. 815	SA135NW	Installation of Sorm Industries bulk cargo tank. Issued 11/15/74.	NW	73820	Sorm Industries 7999 Perimeter Road Seattle, WA 98108
Otter DHC-3; T.C. 815	SA336NW	Installation of Hamilton Standard 23D40-311/6601A-7 propeller. Issued 8/18/76.	NW	40517	Harold J. Hansen 20602 - 135th Avenue South Seattle, WA 98148
DHC-3; T.C. A-815	SA678NW	Installation of Edo Model 56-7850A floats. Issued 10/17/78.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-6; T.C. A9EA	SA106NW	Installation of emergency exit on each side of fuselage. Amended 5/17/74.	EA	71910	S K Aircraft Company 16 Shotgun Lane Levittown, NY 11756
DHC-6; T.C. A9EA	SA235NW	Modification of cabin compartment airstair door. Issued 11/5/75.	NW	08360	Air Transport Industry Jet Air Hangar, Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA570NW	Installation of new interior interior panel. Issued 2/28/78.	NW	08360	Air Transport Industries Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA841EA	Installation of radome and support bracketry for RCA AVQ-45 antenna and radar units. Issued 9/10/70.	EA	35300	Field Aviation Company Limited Toronto International Airport Malton, Ontario, Canada
DHC-6 T.C. A9EA	SA1837WE	Installation of freon air conditioning system. Amended 8/25/77.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
DHC-6; T.C. A9EA	SA2366WE	Installation of emblem lights at mid span of horizontal stabilizer. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DHC-6; T.C. A9EA	SA3816WE	Installation of underseat baggage restraint bar. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DHC-6-100, -200, -300; T.C. A9EA	SA207GL	Install airborne fuel booster pump Model 1D2-14, or 1D2-17. Amended 7/30/80.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
DHC-6-100, -200, -300; T.C. A9EA	SA357AL	Installation of bulk fluid cargo tanks. Amended 5/15/72.	NW	78820	Sorm Industries 7999 Perimeter Road South Seattle, WA 98108

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DHC-6-100, -200, -300; T.C. A9EA	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457
DHC-6 Series 100, 200; 300; T.C. A9EA	SA943EA	Replacement of deHavilland wing bleed air ducting with alternate ducting. Reissued 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
DHC-6-100, -200, -300; T.C. A9EA	SA998EA	Installation of engine fuel drain recirculation system. Reissued 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
DHC-6 Series 100, 200; 300; T.C. A9EA	SA2516WE	Installation of lightning arrestors on wing tips and vertical fin. Issued 9/19/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6-100, -200, -300; T.C. A9EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
DHC-6 Series 100, 200, 300; T.C. A9EA	SA2608WE	Installation of equivalent modifications to deHavilland modifications. Issued 11/3/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2553WE	Installation of Adel cannister fuel pumps. Reissued 8/24/72.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2898WE	Installation of a fuel tank boost pump. Issued 6/14/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, S/N 130, 210, 231 and subsequent; T.C. A9EA	SA1117CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
DHC-6-200; T.C. A9EA	SA771EA	Installation of Dual Mark 15 Decca Systems.	EA	61542	New York Airways, Inc. P.O. Box 426 LaGuardia Airport Station Flushing, NY 11371
DHC-6-200; T.C. A9EA	SA3103WE	Removal of left-hand cargo doors to permit aircraft to engage in special operations, i.e. parachute jumping, aerial photography, etc. Issued 10/24/75.	WE	38250	Golden West Airlines, Inc. 5801 W. Imperial Highway Los Angeles, CA 90045
DHC-6-300; T.C. A9EA	SA130RM	Installation of dual-SELCAL system. Issued 1/28/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA132RM	Change in Airplane Flight Manual operating limitations to permit landings with air-operable jump-door open. Issued 2/15/78.	RM	07701	Department of the Air Force Hq., Aerospace Defense Command Peterson AFB, CC 80914
DHC-6-300; T.C. A9EA	SA135RM	Installation of Leach P/N V110-D-032-AC overvoltage relays. Issued 3/3/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA170NW	Installation of bulk fluid cargo tank for carriage on non-flamable, non-corrosive, non-toxic liquids. Issued 4/3/75.	WE	73820	Sorm Industries 7999 Perimeter Road Seattle, WA 98108
DHC-6-300; T.C. A9EA	SA185RM	Installation of Bendix RDR-160 weather radar system. Issued 10/26/79.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-7-100; T.C. A20EA	ST127RM	Supplemental oxygen system installation. Issued 2/2/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
DHC-7-100; T.C. A20EA	ST128RM	Installation of ground proximity warning system, Collins FPC-75. Issued 1/23/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
D.H. 104 Dove Series; T.C. 807	SA1-72	Three-place seat.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
D.H. 104 Dove Series; T.C. 807	SA1-73	39-gallon auxiliary fuel tank in cabin with 3-place seat per STC SA1-72.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
D.H. 104 Dove Series; T.C. 807	SA1-321	Airstair door.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
D.H. 104 Dove Series; T.C. 807	SA3-61	Sonotone battery (nickle cadmium) 19-24M320.	GL	18450	Burroughs Corporation 6071 Second Avenue Detroit, MI 48233
D.H. 104 Dove Series; T.C. 807	SA3-321	L-5B autopilot and integrated flight equipment CIS-100. Amended 5/4/67.	EA	52535	LSI Service Corporation Harrisburg Division 6700 Allentown Boulevard Harrisburg, PA 17112
D.H. 104 Dove Series; T.C. 807	SA3-472	Stewart Warner 940B combustion heater in forward lower baggage compartment.	GL	77430	Tag Airlines Div. of Miller Oil Company City Airport Detroit, MI 48233
D.H. 104 Dove Series; T.C. 807	SA4-496	Radio panel overhead installation including engine starting switches and instrument lighting switches.	WE	73883	Southern California Aircraft Corp. International Airport Ontario, CA 91761
D.H. 104 Dove Series; T.C. 807	SA4-1361	Ceconite 101 covering of fabric-covered surfaces.	WE	26240	Cooper Engineering Corporation P.O. Box 3428 Van Nuys, CA 91408
D.H. 104 Dove Series; T.C. 807	SA120SO	Instrument panel. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA121SO	Electrical circuit breaker panel and related electrical bus bars. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA122SO	Seats to accommodate 11 passengers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA165SO	Six single-place seats and one two-place couch. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA167SO	Electrically heated windshield left-hand side. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA168SO	Hartzell HC-A3VK-2/V8433-4R propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA170SO	Auxiliary fuel system and bladder type tanks in leading edges of the wings. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA171SO	B.F. Goodrich deicers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA303SO	Wing leading edge clean-up. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA319SO	A or B of turbocharged Lycoming IO-720-A1A engines and Hartzell propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
104 Series; T.C. A-807	SA399CE	Hoskins Supp. position light system, includes Model B (dual) wing tip light Model C, D, or K tail light with or without Model 2 fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
104 Series; T.C. A-807	SA620SO	Installation of Airstair door. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
104 Series; T.C. A-807	SA676SW	AK219 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
104 Series; T.C. A-807	SA1554WE	Installation of two AiResearch TPE331 series engines and increase in fuselage length.	WE	19150	C-Air, Inc. 3521 E. Spring Street Long Beach, CA 90806

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH-104 Series 1A, 2A, 5A, 6A; T.C. 807	SA164SO	Installation of swept vertical tail, wing tips and elevator (STC SA303SO is prerequisite to this STC); installation of Lycoming IO-720-A1A engines (STC SE163SO) and Hartzell HC-A3VK-2/V8433-4R propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
DH-104 Series 1A, 2A, 5A, 6A; T.C. 807	SA135SW	Fuselage nose-mounted radome and structure.	SW	81300	C.R. Ursell 109 Briarcliff Drive San Antonio, TX 78205
DH-104-1A thru 8AXC; T.C. 807	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
D.H. 104, 1A, 2A, 5A, 5BA, 6A, 6BA, 7A, 8A; T.C. 807	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C.H. 104 Dove Series 1A, 2A, 5A, 5BA, 6A, 6BA, 7A, 8A; T.C. 807	SA2666WE	Ceconite 102 material covering of control surfaces. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA1747WE	Installation of two AiResearch TPE 331 series engines, increase in fuselage length and related changes. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA1815WE	Installation of cabin interior. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA1924SW	Structural modification of horizontal tail. Issued 10/23/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. Box 575 Addison, TX 75001
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA2438WE	Installation of spar reinforcing steel straps, on aircraft previously modified per STC SA1747WE. Reissued 5/23/73.	WE	25940	Consulting Aerospace Engineers 1845 Empire Burbank, CA 91504
D.H. 104 Dove Series 7AXC, 8AXC; T.C. A-807	SA2005WE	Installation of cabin air conditioning. This installation approved only on aircraft modified per STC SA1747WE. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 ADdison, TX 75001
D.H. 104 Dove Series 7AXC, 8AXC; T.C. A-807	SA2019WE	Installation of cabin heating system. This installation approved only on aircraft modified per STC SA1747WE. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. 104 Dove Series; D.H. 114 Heron Series; T.C. 807, 816	SA249SW	Airstair door.	SW	68768	North American Rockwell Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
114 Heron Series; T.C. 816	SA629SO	Installation of Hartzell propellers HC-A3VK-2/V8433-7 equipped with Goodyear deicing equipment. Reissued 7/29/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
114 Heron Series; T.C. 816	SA633SO	Installation of electrically heated windshield.	SW	69150	Riley International Corporation 6211 W. Northwest Highway Dallas, TX 75225
D.H. 114 Heron; T.C. 816	SA816WE	Hartzell HC-A3X21-2L/I 7636D propellers.	WE	70298	Charles Schachle 3901 E. Spring Street Long Beach, CA 90801
D.H. 114 Heron; T.C. 816	SA1228WE	Ceconite 101 covering of flaps and control surfaces.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
D.H. 114 Heron; T.C. 816	SA1323WE	Fabric on ailerons, elevators, flaps and rudder with "pop" rivets.	WE	06755	Aircraft Technical Service, Inc. 16300 Stagg Street Van Nuys, CA 91406
D.H. 114 Heron; T.C. 816	SA1535WE	Installation of combustion cabin heater.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
D.H. 114 Heron; T.C. 816	SA2805WE	Nickel Cadmium battery installation. Issued 1/25/74.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst AVenue Van Nuys, CA 91406
D.H. 114 Heron; T.C. 816	SA2806WE	Installation of additional emergency exits. Issued 1/25/74.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
D.H. 114 Heron Series 2A; T.C. A-816	SA740EA	Installation substitution of Lycoming engine IO-540-K1C5 in place of Lycoming Model IO-540-G1A4.	GL	87800	Wright Airlines, Inc. 2649 Broadway Cleveland, OH 44115
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST7448SO	Installation of smoke detection system for forward and aft holds. Issued 12/13/74.	SC	65333	Puerto Rican Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST745SO	Installation of windshield wiper for co-pilot's (R.H.) position. Issued 12/13/74.	SC	65333	Puerto Rico Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA757SO	Installation of emergency exit RH fuselage at F.S. 49-76, and permanent closure of three existing overhead exits. Issued 3/4/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST758SO	Metal covering of wing flaps. Issued 5/3/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA919SO	Airplane life extension. Amended 6/20/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Heron Series 2A, 2DA, 2X; T.C. A-816	ST957SO	Installation of Teledyne battery Model BB638/T-C replacing two Rebat R-35 batteries. Issued 9/22/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST965SO	Modification of cockpit direct vision window. Issued 12/7/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, -2DA, -2X; T.C. A-816	SA1089SC	Installation of shoulder harness for crew seats. Issued 7/19/75.	SO	65333	Puerto Rico Int'l Airlines, Inc. c/o Caribbean Aircraft Develop., Inc. Building 408-Opa Locka Airport Opa Locka, FL 33054
DH-114-2A, -2DA, -2X; T.C. A-816	SA1138SC	Installation of Bendix RDR 160B weather radar system. Issued 3/4/80.	SO	65333	Puerto Rico Int'l Airlines, Inc. c/o Caribbean Aircraft Develop., Inc. Building 408-Opa Locka Airport Opa Locka, FL 33054
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1368WE	Installation of Lycoming IO-540 series engines. Amended 10/31/72.	SW	68150	Riley International Corporation P.O. Box 5247 Waco, TX 76708
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1545WE	Installation of cabin interior arrangement, air conditioning equipment, electrically operated air compressors. Amended 6/25/68.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1685WE	Installation of four Continental IO-520-E engines. Amended 8/22/68.	SO	65333	Puerto Rico Int'l Airlines, Inc. P.O. Box 1498 Bayamon, PR 00619
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1710WE	Installation of stair door.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1729WE	Installation of over wing emergency exits and rear windows. Amended 12/4/69.	SO	65333	Puerto Rico Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1826WE	Installation of 22 occupant interior.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA2067WE	Installation of Janitrol 8-200 cabin heater. Reissued 7/29/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA3125WE	Installation of lower wing skin straps, lower spar doubler straps and engine mount pickup strap doublers. Amended 4/1/76.	WE	86680	Winters Aircraft Engineering Co. 17100 Ventura Boulevard Encino, CA 91316

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH-114, 2X; T.C. 816	SA1371WE	Interior installation.	WE	06755	Aircraft Technical Service, Inc. 16300 Stagg Street Van Nuys, CA 91406
DH-114, 2X; T.C. 816	SA1534WE	Installation of engine fire detection and extinguishment systems.	WE	06755	Aircraft Technical Service, Inc. 7150 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114, 2X; T.C. 816	SA1544WE	Cockpit modification and generator control.	WE	06755	Aircraft Technical Service, Inc. 7150 Hayvenhurst Avenue Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

EMPRESA BRASILEIRA DE AERONAUTICA S/A

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Embraer EMB-110P1; T.C. A21SO	SA1576CE	Installation of Collins ANS-351 area navigation system. Issued 3/6/80.	CE	24250	Collins Avionics Division 400 Collins Road, NE Cedar Rapids, IA 52406
Embraer EMB-110P1; T.C. A21SO	SA1577CE	Installation of Collins AP-106/FD-112 automatic flight control system. Issued 3/6/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
Embraer EMB-110P1; T.C. A21SO	SA1578CE	Installation of Collins electrical elevator trim system. Issued 3/6/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
Embraer EMB-110P1, -110P2; T.C. A21SO	SA1162SO	Installation of a Bendix FCS-8700 automatic flight control system including optional flight director. Issued 7/31/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
Embraer EMB-110P1, -110P2; T.C. A21SO	SA1167SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid battery. Issued 7/31/80.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, N.W. Atlanta, GA 30338

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

FAIRCHILD INDUSTRIES, INC.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
22C7D, 24C8, 24C8A, 24C8B, 24C8C, 24C8CS, 24C8D, 24C8DS, 24C8E, 24C8ES, 24C8F, 24C8FS, 24G, 24GS, 24H, 24HS, 24J, 24JS, 24K, 24KS, 24R-9, 24R-9S, 24R-40, 24R-40S, 24R-46, 24R-46S, 24W-9, 24W-9S, 24W-40, 24W-40S, 24W-41, 24W-41S, 24W-41A, 24W-41AS, 24W-46S, 24W-16; T.C. 503, 475, 497, 498, 535, 576, 600, 610, 633, 632, 663, 667, 706, 707, 503	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
22C7G, 24J, 24JS, 24R-9, 24R-40, -40S, 24R-46, -46A, -46S, M62A, M-62A-3, -4, M-62B, -62C, KR-21, F-45, C-82, KR-31; ATC 564, T.C. 663, 706, 724, 215, 603, AR-15, ATC-19	SA2666WE	Ceconite 102 material covering of: 22C7G - fuselage; 24J, 24JS, 24R-9, -40, -40S, -46, -46A, -46S - wings; M-62A, -62B, -62C - fuselage, ailerons, elevators and rudder; KR-21, KR-31 - complete aircraft; F-45 - rudder, elevators and ailerons; C-82 - control surfaces. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angel
C-119C; T.C. A21WE	SA2915WE	Installation of a 2400 gallon fire retardant tank assembly. Issued 7/19/74.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
C-119C; T.C. A21WE	SA2996WE	Installation of a 2400 gallon fire retardant tank assembly. Issued 1/14/75.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
C-119C; T.C. A21WE	SA2997WE	Installation of a 2400 gallon fire retardant tank assembly. Issued 1/14/75.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
C-119C, C-119G; T.C. A21WE	SA20RM	Install Westinghouse J-34-WE36 jet engines on top of center line of fuselage. Issued 11/23/73.	RM	41360	Hawkins & Powers Aviation, Inc. P.C. Box 391 Greybull, WY 82426
C-119C, C-119G; T.C. A21WE	SA74RM	Modification of floor and bottom fuselage for water and chemical tank installation. Issued 5/21/76.	RM	41360	Hawkins & Powers Aviation, Inc. P.O. Box 391 Greybull, WY 82426
C-119G; T.C. A21WE	SA46RM	Operation with cargo door removed. Issued 2/26/75.	RM	41360	Hawkins & Powers Aviation, Inc. Box 391 Greybull, WY 82426
C-119G; T.C. A21WE	SA49RM	Operation with cargo door removed. Issued 2/28/75.	RM	41360	Hawkins & Powers Aviation, Inc. Box 391 Greybull, WI 82426
C-119G-3E; T.C. A24WE	SA48RM	Operation with cargo door removed. Issued 2/27/75.	RM	41360	Hawkins & Powers Aviation, Inc. Box 391 Greybull, WY 82426
C-82A; T.C. AR-15	SA20SO	Cargo compartment floor modification for special cargo.	SO	58690	Miami Aircraft Maintenance, Inc. P.O. Box 48-1273 Miami, FL 33101
C-82A; T.C. AR-15	SA22SO	Four Aerojet General rocket engines 15FS100A1 and static pressure source.	SO	58690	Miami Aircraft Maintenance, Inc. P.C. Box 48-1273 Miami, FL 33101
KR-21; A.T.C. 215	SA946WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.C. Box 3428 Van Nuys, CA 91408
22, C7G; T.C. 564	SA783WE	Ceconite 101 covering of fuselage.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
22 C7G; 24J, 24JS; 24R-9, -40, -40S, -46, -46A; M-62A, -3, -4, M-62B, -C, 23-AE, -HO, -SL, -23A, -SL; KR-21; C-82 Jet Packet; KR-31; A.T.C. 564, T.C. 663, 706, 724, 603, AR-15, A.T.C. 19	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
24C8E, 24C83S; 24R Series; T.C. 600, 706	SA1008WE	Poly-Fiber covering of left and right elevators and top of horizontal stabilizer. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92519
24G, 24GS, 24W-46, M-62 Series; T.C. 633, 707, 724	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
24G, -GS; PT-19, -23, -26, M-62; 24W-46; A.T.C. 633, T.C. 724, 707	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
24J, 24JS, 24R Series; T.C. 663, 706	SA4-860	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
24R Series, 24W Series; T.C. 706, 707	SA4-863	Eonite covering of complete airplane.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
24R Series, 24W Series; T.C. 706, 707	SA4-985	Fiberglass covering on wings, ailerons, and fuselage.	WE	38060	Glasco-Air Products 1125 First Street San Fernando, CA 91340
24R46A; M62A-3, -4 (Army PT-26); T.C. A-706, A-724	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-7 and HA-6 series carburetors. Amended 11/20/75.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
24R46A; M62A-3, -4; T.C. A-706, A-724	SA489EA	Installation of A.R.P. Industries, 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 10/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
24W; T.C. 707	SA4-42	Engine mount for Jacobs R-755 engine.	WE	71000	Serv-Aero Engineering, Inc. P.O. Box 96 Dos Palos, CA 93620
24W; T.C. 707	SA4-45	Engine mount for Continental W670 engine.	WE	71000	Serv-Aero Engineering, Inc. P.O. Box 96 Dos Palos, CA 93620
F-27 Series; T.C. 7A1	SA1-429	Outer wing structure modification to provide additional fuel.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
F-27 Series; T.C. 7A1	SA1-574	Nose wheel steering actuator assembly. Amended 8/16/66.	EA	48000	Walter Kidde & Company, Inc. 675 Main Street Belleville, NJ 07109
F-27 Series; T.C. 7A1	SA3-610	F-542-L flight recorder.	WE	80700	United Data Control, Inc. 380 N. Halstead Street Pasadena, CA 91101
F-27 Series; T.C. 7A1	SA3-682	Three-place divan.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA3-683	Hardman 3045 swivel chair.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
F-27 Series; T.C. 7A1	SA3-684	Double stationary chair.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GATES LEARJET CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
23 Series; T.C. A5CE	SA148GL	Installation of radome kit 4088X. Issued 1/31/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
23 Series; T.C. A5CE	SA377AL	Installation of nose wheel guard. Issued 6/19/70.	AL	05958	Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
23 Series; T.C. A5CE	SA1019CE	Install lower cabin door designed to accommodate flare racks. Issued May 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1020CE	Install lower cabin door to accommodate aerial photography equipment. Issued May 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1098CE	Installation of drift (navigation) sight to be used in conjunction with aerial photography equipment. Issued February 1975.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1169CE	Stretcher installation in cabin area. Issued 10/21/75.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1171CE	Stretcher installation in baggage area. Issued 10/21/75.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
23 Series; T.C. A5CE	SA1299CE	Installation of provisions for infra-red scanning equipment. Amended July 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23 Series; T.C. A5CE	SA1321CE	Installation of dry ice dispenser. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23 Series; T.C. A5CE	SA1335CE	Installation of datum console rack. Issued 6/27/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23 Series; T.C. A5CE	SA1378CE	Install structural provisions on right hand side of airplane for removable camera door. Issued 10/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23 Series; T.C. A5CE	SA1381CE	Structural provisions for infra-red scanning equipment. Issued 10/26/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23; T.C. A5CE	SA1395CE	Install structural provision for Jelco infra-red scanner. Issued 1/5/78	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1396CE	Install lower cabin door designed to accept a carousel flare dispensing unit capable of being reloaded in flight. Issued 2/8/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1411CE	Install structural provision for a particle measuring probe. Issued 4/18/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1412CE	Install dry ice dispenser. Issued 4/19/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
23; T.C. A5CE	SA1548CE	Structural provision for NASA - Daedalus IR scanner. Issued 2/22/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
23 Series; T.C. A5CE	SA2294WE	Modification of nose wheel steering system. Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
23 Series; T.C. A5CE	SA2992WE	Installation of logo lights on horizontal stabilizer lower surface. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
23, 24 Series; T.C. A5CE, A10CE	SA481CE	Modification of electrical system for compliance with AD 66-14-02.	GL	34020	Executive Jet Aviation, Inc. Port Columbus Int'l Airport Columbus, OH 43219
23, 24 Series; T.C. A5CE, A10CE	SA830SW	Heat static units.	SW	29232	Delta Aircraft P.O. Box 12182 San Antonio, TX 78205
23, 24, 24A, 24B, 24C, 24D, 25, 25B, 25C; T.C. A5CE, A10CE	SA21RM	Installation of cabin divider. Issued 12/5/73.	RM	25252	Combs Gates Denver, Inc. Hangar #7 Stapleton Int'l Airport Denver, CO 80207
23, 24, 24B, 24D, 25, 25B, 25C; T.C. A5CE, A10CE	SA412CE	Installation of Woodward Electronic Engine synchronizer system.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
23, 24, 24B, 24D, 25, 25B, 25C, 35, 36; T.C. A5CE, A10CE	SA871SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 25, 25A, 25B, 25C; 35, 36; T.C. A5CE, A10CE	SA996EA	Installation of Shaw Aero fuel filler cap P/N's 457-2, -266, 370, -431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A; T.C. A5CE, A10CE	SA2429WE	Installation of windshield rain repellent system. Issued 10/8/71.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
23, 24, 24A, 24B, 24C, 24B-A, 25, 25A; T.C. A5CE, A10CE	SA2447WE	Installation of Lear Ni-Cad safety unit. Reissued 10/24/72.	WE	49850	Lear Avia Corporation P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
23, 24, 25; T.C. A5CE, A10CE	SA175RM	Replacement of throttle knob, Model EP-004, for 20 series Learjet equipped with Dee Howard thrust reversers. Issued 6/18/79.	RM	45790	Jet Accessories, Inc. P.O. Box 38568 Stapleton Field Denver, CO 80238
23, 24, 25 Series; T.C. A5CE, A10CE	ST488SO	Installation of Butler National 6A VAC/10A ADD Area Navigation System with altitude alerting capabilities that meet requirements of FAR 91.51. Issued 1/28/72.	SO	73874	Southern Airways Company Hangar One Atlanta, GA 30320
23, 24, 25, 35, 36 Series; T.C. A5CE, A10CE	SA1033SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid batteries. Issued 11/21/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
24; T.C. A10CE	SA841NW	Performance improvement fairings to wing and nacelles. Issued 10/23/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road Seattle, WA 98108
24; A10CE	SA1065SO	Installation of support rack (incubator). Issued 4/18/79.	SO	64150	Personalized Interiors, Inc. 240 S.W. 34th Street Ft. Lauderdale, FL 33315
24 Series; T.C. A10CE	SA1874WE	Installation of Janco auxiliary cabin heater.	RM	37098	The Gates Rubber Company 8601 Montview Boulevard Denver, CO 80220
24 Series; T.C. A10CE	SA2329WE	Installation of Microcom, Inc. Lear AFC-70 autopilot (previous modification per STC SA2228WE - Microcom, Inc. nose wheel steering modification required). Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
24 Series; T.C. A10CE	SA2373WE	Installation of Microcom, Inc. Lear altitude alerter system, Microcom P/N 800074. Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
24, 24A, 24B; T.C. A10CE	SA1549CE	Installation of structural provisions for infra-red scanning equipment. Issued 2/26/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, B, BA, C, D, D-A, 25, 25A, B, C; T.C. A10CE	SA1RM	Installation of cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, D, E, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1[illegible]	Installation of Branson flight crew emergency exit. Amended 6/12/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, B, B-A, C, D, D-A, E, F, 25, 25A, B, BC, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA149GL	Installation of radome kit 4088X. Issued 1/31/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations Akron, OH 44309
24, 24A, 24B, 24C, 24D, 25, 25A, 25B, 25C; T.C. A10CE	SA960CE	Lower cabin door designed to accommodate four flare racks for cloud seeding. Issued February 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E, 24F, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA961CE	Installation of lower cabin door designed to accommodate aerial photography equipment. Amended 6/7/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E,, 25, 25A, 25B, 25C, 25D, 25F, 35, 36; T.C. A10CE	SA1091CE	Installation of drift (navigation) sight to be used in conjunction with aerial photography equipment. Amended 5/3/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A thru 24F, 25, 25A thru 25F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1170CE	Stretcher installation in cabin area. Amended 6/1/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A thru 24F, 25, 25A, B, D, F, 28, 35, 35A; T.C. A10CE	SA1172CE	Stretcher installation in baggage area. Amended 6/1/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E, 24F, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA1281CE	Lower cabin door designed to accommodate a flare rack capable of being reloaded in flight. Amended 6/22/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA1298CE	Installation of provisions for infra-red scanning equipment. Reissued July 1977.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
24, 24A thru 24D, 25, 25A thru 25F (S/N 25-229 or earlier), 35, 35A, 36, 36A; T.C. A10CE	SA1322CE	Installation of dry ice dispenser. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
24, 24A, B, C, D, 25, 25A, B,C, D, F; T.C. A10CE	SA1332CE	Install Litton digiprox ground proximity warning system (GPWS). Reissued 8/3/78.	WE	51500	Aero Products Division Litton Systems, Inc. 21050 Burbank Boulevard Woodland Hills, CA 91364
24, 24A, B, C, D, 25, 25A, B, C, D, 35, 35A, 36, 36A; T.C. A10CE	SA1336CE	Installation of datum console rack. Reissued 9/13/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1377CE	Install structural provisions on right hand side of airplane for removable camera door. Amended 6/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1382CE	Structural provisions for infra-red scanning equipment. Amended 6/4/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F; T.C. A10CE	SA1394CE	Install structural provision for Jelco infra-red scanner. Issued 1/5/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F; T.C. A10CE	SA1397CE	Install lower cabin door designed to accept a carousel flare dispensing unit capable of being reloaded in flight. Issued 2/8/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1410CE	Install structural provision for particle measuring probe. Amended 6/22/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1413CE	Installation of dry ice dispenser. Amended 6/4/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1477CE	Structural plug installation in right side of forward fuselage when camera door is removed. Issued 3/21/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA2876WE	Installation of vertical tail floodlights on the horizontal stabilizer. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3225WE	Installation of R.C.A. Primus 35 weather radar system. Issued 6/25/76.	WE	37095	Gates Learjet Modification & Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3226WE	Installation of Collins FD 112V flight director system. Issued 6/25/76.	WE	37095	Gates Learjet Modification & Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 24F; T.C. A10CE	SA3263WE	Installation of J.E.T. DAC 2000 RNAV system. Issued 11/29/76.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3264WE	Installation of Global GNS-500A VLF navigation system. Reissued 3/3/78.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3326WE	Installation of Collins ALT-55 radio altimeter. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3327WE	Installation of Motorola Model NA135 Selcal system. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E,F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3328WE	Installation of flight data recorder Sundstrand Model FA542. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3422WE	Installation of dual Collins MC-103 compass systems.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3426WE	Installation of R.C.A. Primus 400 weather radar system. Issued 6/29/77.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24C, 24D, 24D-1, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F; T.C. A10CE	SA3615WE	Installation of Collins NCS-31A area navigation system. Issued 4/7/78.	WE	37095	Gates Learjet-Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
24, 24A, 24B, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3647WE	Installation of dual Collins ALT-50 and ALT-55 radio altimeter system with comparator. Issued 6/5/78.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3677WE	Installation of Wulfsberg WT-200 communication transceiver system. Issued 8/31/78.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F; T.C. A10CE	SA3807WE	Installation of Jet Elec. & Tech. DAC-2000 R/NAV system with transfer switching for data from pilot to copilot panel. Issued 12/19/78.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA3735WE	Installation of optional single or dual H-field antenna (Global P/N 11455-1) for Global GNS-500A system. Amended 7/19/79.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3850WE	Installation of RCA Primus 300 color weather radar system. Issued 2/7/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3866WE	Installation of Wulfsberg Model AT-960 antenna. Issued 3/6/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29; T.C. A10CE	SA3899WE	Installation of Collins F1S-84 flight instrument system. Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3915WE	Installation of RCA Primus 400 check list (Data Nav I). Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA3975WE	Installation of Collins WXR-300 color radar. Issued 6/7/79.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4003WE	Installation of Bendix RDR-1200/ RDR-1300 color radar check list. Issued 7/26/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29; T.C. A10CE	SA4028WE	Installation of Sundstrand Mark II ground proximity warning system. Issued 9/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25B, D; T.C. A10CE	SA4054WE	Installation of SUNAIR ASB-850 high frequency radio communications system. Issued 1/16/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F; T.C. A10CE	SA4073WE	Installation of Sunair ASB-850 high frequency radio communication system. Issued 1/23/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A; 25, 25A, B, C, D, F, 28, 29, 35, 36, 35A, 36A; T.C. A10CE	SA4131WE	Installation of Collins RNS-300 radar navigation system. Issued 7/18/80.	WE	37095	Gates Learjet Corporation P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4194WE	Installation of dual Sperry C-14A compass systems. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4195WE	Instalaltion of Collins FPA-80 flight profile advisory system. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
24, 24B; T.C. A10CE	ST485SO	Installation of Smiths Industries Type 3B series (WL/1101 AM/MS or 1103 AM/MS) servoed altimeter WL/504/CUF altitude alerting unit, and Smiths pressure error transducer (Type A108 for Model 24 and Type 104 for Model 24B). Issued 1/19/72.	SO	73075	Smiths Industries, Inc. St. Petersburg/Clearwater Airport St. Petersburg, FL 33732
24, 25; T.C. A10CE	SA117GL	Installation of cabin temperature control system. Issued 5/17/76.	GL	31640	Ned Wilkins Eaton Corp. Flight Operations Cuyahoga County Airport 355 Richmond Road Cleveland, OH 44143
24, 25; T.C. A10CE	SA891CE	Relocate optical window port. Amended May 1976.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 25; T.C. A10CE	SA1635WE	Modification of lower half of passenger entry door to accommodate camera installation. Amended 8/29/75.	WE	43450	Mark Hurd Aerial Surveys, Inc. Box 488 Goleta, CA 93017
24, 25; T.C. A10CE	SA1746SW	Model 7107 battery fault warning system. Issued 10/19/73.	SW	66500	Ray Electronics Company 107 Braniff Drive San Antonio, TX 78216
24, 25; T.C. A10CE	SA2228WE	Modification of nose wheel steering. Amended 5/12/75.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
24, 25, 35, 36 Series: T.C. A10CE	SA2788SW	Tail-stringer antenna housing. Issued 6/5/78.	SW	74965	Sted-Mac Co. Box 6123 A.T.S. Midland, TX 79701
24A as certified under STC SA7RM, 25, 25A, 25B modified per STC SA14RM; T.C. A10CE	SA9RM	Installation of cabin cargo retention nets. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24A as certified under STC SA7RM, 25, 25A, 25B modified per STC SA14RM; T.C. A10CE	SA10RM	Installation of cabin cargo liner. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24B, 24D; T.C. A10CE	SA136GL	Install Intercontinental Dynamics Corp.'s altimeter P/N 16007-703 or P/N 16007-803 in aircraft equipped with IDC altitude alerter. Issued 10/1/76.	GL	34020	Executive Jet Sales, Inc. Port Columbus Int'l Airport Columbus, OH 43219
24B, 24D, 25, 25B, 25C; T.C. A10CE	SA2675WE	Installation of sound suppressors. Reissued 11/12/75.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
24D; T.C. A10CE	SA31RM	Structural provisions for cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24D; T.C. A10CE	SA33RM	Quick change cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24D; T.C. A10CE	SA232NW	Installation of Mark II performance system. Issued 10/24/75.	NW	66175	The Raisbeck Group 2471 Perkins Lane West Seattle, WA 98199
24D; T.C. A10CE	SA639RM	Install EP-001 starter/generator decoupler system. Issued 6/28/78.	AL	45790	Jet Accessories, Inc. P.O. Box 38568 Stapleton Field Denver, CO 80238
24D; T.C. A10CE	SA1648SW	Stretcher installation according to Qualitron Aero. Reissued 5/20/59.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
24E, 24F, 25D, 25F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4146WE	Installation of Litton LTN-211 Omega/VLF navigation system. Issued 5/5/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
25 Series; T.C. A10CE	SA3280WE	Installation of fuel filler well for fuselage tanks. Issued 10/27/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
25, 25A, 25B, 25D, 28; T.C. A10CE	SA3891WE	Installation of Sunair Model ASB-130 high frequency radio communication system. Issued 3/27/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
25, 25A, 25B, 25C, 25D, 25F, 28, 29, 35, 36, 36A; T.C. A10CE	SA1489CE	Removal of 24-inch executive door and installation of 36-inch cargo door. Amended 7/3/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1376CE	Andrea Radio Corp. (A-81) five station interphone system. Reissued 12/30/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1497CE	Structural provision for NASA - Daedalus IR scanner. Amended 12/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3561WE	Installation of a fuel filter. Amended 5/20/80.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
25, 25B; T.C. A10CE	ST147RM	Installation of Communications Components Corp. Ontrac III VLF/Omega navigation system. Issued 8/7/78.	RM	05940	Aircraft Radio & Accessory, Inc. Hangar 1 Stapleton Internationl Airport Denver, CO 80207
25, 25B, 25C; T.C. A10CE	SA30GL	Installation of electronic engine synchronizer system. Issued 7/12/73.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
25, 25B, 25C; T.C. A10CE	SA953CE	Installation of dual camera/intervalometer. Issued October 1973.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North Wichita, KS 67204
25, 25B, 25C; T.C. A10CE	SA3622WE	Modifications to add installation provisions for twin aerial survey cameras in the belly of the airplane. Issued 4/10/78.	WE	43450	Mark Hurd Aerial Surveys, Inc. P.O. Box 489 Goleta, CA 93017
25B; T.C. A10CE	SA29RM	Install mid-fuselage cargo compartment (500 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA30RM	Install tail cone cargo compartment (300 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA92GL	Install a Foster Airdata System, Inc. AD611/D area navigation system. Reissued and amended 2/20/79.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
25D; T.C. A10CE	SA4034WE	Installation of Canadian Marconi CMA-771 Omega/VLF navigation system. Issued 12/26/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
28, 29; T.C. A10CE	SA3926WE	Installation of Garrett Rescu 99 locator transmitter. Issued 5/9/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
29; T.C. A10CE	SA3928WE	Installation of Collins 718-U5 high frequency radio communications system. Issued 5/2/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35; T.C. A10CE	SA1195CE	Installation of dual Sperry C-12 gyro-compass system for use as navigational air. Issued 1/23/76.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35; T.C. A10CE	SA2288SW	Litton LTN-104 inertial navigation system. Issued March 1976.	SW	12250	Associated Radio Service 6911 Lemmon Avenue Dallas, TX 75220
35, 35A; T.C. A10CE	SA3633WE	Installation of AiResearch AiRNAV-200 RNAV and Global GNS-500A VLF navigation systems. Issued 4/27/78.	WE	37095	Gates Learjet-Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA3931WE	Installation of Litton LTN-72R inertial navigation system with DME/DME update. Issued 5/11/79.	WE	37094	Gates Learjet Corproation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA4075WE	Installation of Collins 718U-5M high frequency radio communications system. Issued 1/11/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, 35A; T.C. A10CE	SA4086WE	Installation of Sperry SPI-80 flight director system. Issued 2/26/80.	WE	37094	Gates Learjet Corporation P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA82RM	Installation of Sperry SP180/81 Flight Director System, interfaced with J.E.T. FC-200 Automatic Flight Control System. Issued 10/8/76.	RM	05940	Aircraft Radio and Accessory Company, Inc. Hangar #1 Stapleton Int'l Airport Denver, CO 80202
35, 35A, 36, 36A; T.C. A10CE	SA160GL	Install a J.E.T. DAC-2000 3-D RNAV system. Amended 4/15/77.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
35, 35A, 36, 36A; T.C. A10CE	SA405NW	Installation of an ONTRAC III VLF/Omega navigation system. Amended 9/27/77.	NW	16888	Boise Cascade Aviation 3565 South Owyhee Boise, ID 83705
35, 35A, 36, 36A; T.C. A10CE	SA1507CE	Installation of electronic consoles on cabin seat rails. Reissued 8/20/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1508CE	Installation of mounting plates in the tail cone for mounting of electrical inverters. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1509CE	Installation of instrumentation rack and inverter rack in baggage compartment. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1531CE	Installation of a pod aerodynamic fairing capable of accepting target towing equipment. Issued 10/31/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
35, 35A, 36, 36A; T.C. A10CE	SA1533CE	Installation of a Maritime Patrol surveillance system. Reissued 11/16/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA3198WE	Installation of Garrett TFE 731 engine synchronizer/EMI filter - engine speed. Issued 5/20/76.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. A10CE	SA3340WE	Installation of Communications Components Corp. ONTRAC III VLF/Omega navigation system. Issued 2/10/77.	WE	37094	Gates Learjet Modification and Service Center Tucson Int'l Airport Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3346WE	Installation of Collins Radio Co. flight profile comparator (ground proximity warning system - GPWS). Issued 2/18/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3375WE	Installation of Foster Airdata AD611D area navigation system. Amended 7/17/79.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3396WE	Installation of hydromechanical fuel controls, computers, and harnesses. Issued 5/5/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. aA10CE	SA3398WE	Installation of cold cathode cabin lighting system. Issued 5/6/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3411WE	Installation of AFCS heading select system. Issued 5/20/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3420WE	Installation of pitch trim tone system. Issued 6/29/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3421WE	Installation of modified control wheel and stick pusher cutout system. Issued 6/29/77	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3438WE	Installation of Garrett AirNav 100 or 200 or 300 navigation system. Amended 8/29/80.	WE	07500	AiResearch Manufacturing Company of California 2525 West 190th Street Torrance, CA 90509

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, 35A, 36, 36A; T.C. A10CE	SA3440WE	Installation of VOR/ILS compass and vertical gyro instrument switching system.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3442WE	Installation of AFCS heading and/or pitch maneuver transfer systems. Amended 1/27/78.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3509WE	Installation of Tracor 7640 omega navigation system. Issued 11/4/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3530WE	Installation of dual Collins 718U-5 HF system. Amended 10/31/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3531WE	Installation of Sundstrand MKII ground proximity warning system. Issued 12/12/77.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3532WE	Installation of Collins ANS-31A area navigation system. Issued 1/12/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3568WE	Installation of Delco Carousel IV-A inertial navigation system. Issued 2/17/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3808WE	Installation of Jet Elect. & Tech. DAC-2000 3-D R/NAV system. Issued 12/20/78.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3865WE	Installation of Sperry C-11B compass system. Issued 3/5/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3896WE	Installation of Collins FIS-84 flight instrument system. Issued 4/10/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3916WE	Installation of directional gyro and vertical gyro transfer switching system. Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3994WE	Installation of ONTRAC III Mod 6, Omega/VLF navigation system. Issued 7/17/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA4192WE	Installation of Canadian Marconi CMA-771 Omega/VLF navigation system. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA4196WE	Installation of dual Sperry SPI-502 flight director's system. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA4204WE	Installation of Collins FDS-85 flight director, pilots side. Issued 7/30/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 36; T.C. A10CE	SA766NW	Installation of stall fences and removal of vortex generators. Issued 5/4/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road South Seattle, WA 98108
35A; T.C. A10CE	SA450GL	Installation of a dual Canadian Marconi CMA-734 Omega navigation system. Issued 9/19/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
35A; T.C. A10CE	SA4060WE	Installation of Sunair ASB-500 high frequency radio communication system. Issued 1/17/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35A, 36A; T.C. A10CE	SA1240CE	Installation of Intercontinental Dynamics Corp. RAD/BAR altimeter without voice terrain advisory. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1241CE	Installation of dual IDC maximum allowable mach/airspeed indicators type 575, P/N 25850. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1306CE	Install copilot's IDC maximum allowable airspeed/mach indicator type 575, P/N 26320. Issued 3/14/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1340CE	Dual camera installation. Issued 7/14/77.	CE	37094	Gates Learjet Corporation 8220 West Harry Wichita, KS 67209
35A, 36A; T.C. A10CE	SA1505CE	Wing pylon external stores installation. Issued 9/28/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35A, 36A; T.C. A10CE	SA1609CE	Installation of dual camera provisions. Issued 10/6/80.	CE	37094	Gates Learjet Corporation 8220 West Harry Wichita, KS 67209
36, 36A; T.C. A10CE	SA3529WE	Installation of Litton LTN-72 inertial navigation system. Issued 1/13/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
36, 36A; T.C. A10CE	SA3864WE	Installation of Litton LTN-72R inertial navigation/area navigation system. Issued 3/6/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
36, 36A; T.C. A10CE	SA4033WE	Installation of Litton LTN-72 (INS)/Global GNS-500A (VLF/Omega) or Litton LTN-72R (INS)/Global GNS-500A (VLF/Omega) interface. Amended 5/25/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
GENERAL DYNAMICS CORP.
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BT-13 Series; T.C. 2-571	SA4-404	Glass cloth application on control surfaces.	WE	38060	Glasco-Air Products, Inc. Oxnard-Ventura County Airport Oxnard, CA 93030
BT-13 Series; T.C. 2-571	SA4-625	Flap lids.	WE	54660	E.H. Mann & E. Snow 13226 Hubbard Street Sylmar, CA 91332
BT-13 Series; BT-15; T.C. 2-571	SA4-592	Eonite covering on ailerons and rudder.	WE	52090	William G. Iott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
BT-13 Series; BT-15; T.C. 2-571	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
BT-13, -13A, -13B, BT-31-15, PBY-6A; T.C. 2-571, AR-22, 785, 2-548	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BT-13, -13A (Navy SNV-1), -13B, (Navy SNV-2), -15; T.C. 2-571	SA1008WE	Installation of Poly-Fiber covering material. Amended 8/7/69.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92502
BT-13 Series, BT-15, Navy SNV Series; T.C. 2-571	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BT-13, -13A, -13B, BT-15, L-13A, PBY-5, PBY-5A, PBY-6A, 28-5ACF, P4Y-2; T.C. 2-571, AR-10, AR-22, 785, aAR-29	SA2666WE	Ceconite 102 material covering of: BT-13, -13A, -13B, BT-15 - rudder, elevators, flaps, and ailerons; L-13A - ailerons, elevators and rudder; PBY-5, -5A, -6A, 28-5ACF - ailerons, wing trailing edges, rudder and elevators; P4Y-2 - ailerons, rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
L-13 Series; T.C. AR-10	SA4-510	Landing gear modification.	WE	62442	Paragon Tool Die & Engineering 11035 Sutter Avenue Pacoima, CA 91331
L-13 Series; T.C. AR-10	SA4-521	Glass cloth application on control surfaces.	WE	38060	Glasco-Air Products, Inc. Oxnard-Ventura County Airport Oxnard, CA 93030
L-13 Series; T.C. AR-10	SA4-1020	Dust-spray tank and stabilizer braces.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
L-13 Series; T.C. AR-10	SA201WE	Hamilton Standard propeller, hub 2820, and blades 6135A-9.	WE	40520	Archie Hanson, Jr. 24733 Long Valley Road Calabasas, CA 91302
L-13 Series; T.C. AR-10	SA640WE	Ceconite 101 covering of ailerons, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
L-13A; P4Y-2; BT-13, -13A, -13B, -15; PBY-5, -5A, -6A, 28-5ACF; T.C. AR-10, AR-29, 2-571, 785	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
P4Y-2; T.C. AR-29	SA4-1144	Ceconite 101 covering of ailerons and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
P4Y-2; T.C. AR-29	SA1900WE	Installation of Wright R2600-35 engines and Hamilton Standard 23E50-505/6359A-13 propellers. Amended 1/15/74.	RM	41360	Hawkins & Powers Aviation, Inc. P.O. Box 391 Greybull, WY 82426
PB4Y-2, P4Y-2; T.C. AR-29	SA27RM	Integral fuel tank installation. Issued 5/14/74.	RM	41360	Hawkins & Powers Aviation, Inc. P.O. Box 391 Greybull, WY 82426

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PBY-5, PBY-5A; T.C. 2-548	SA14SO	Metal wing skin on trailing edge portion of wing.	SO	00082	A & G Aircraft Broward Co. Int'l Airport Fort Lauderdale, FL 33000
PBY-5, PBY-5A, PBY-6A, 28-5ACF; T.C. 2-548, AR22, 785	SA4-1066	Ceconite 101 covering of ailerons, wing trailing edges, rudder and elevators.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PBY-5A Series; T.C. 2-548	SA926SW	PBY-6A tail and retain blisters.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
PBY-5A, PBY-6A, 28-5ACF; T.C. 2-548, AR-22, 785	SA4-1056	Fabric covering attachment with screws instead of stitching. Reissued 2/19/71.	WE	42040	Hemet Valley Flying Service Co. P.O. Box 1678 Hemet, CA 92343
PBY-5A, 28-5ACF; T.C. 2-548, 785	SA4-493	104-1-B and 104-1-C engine mount cores on aircraft with Pratt & Whitney R-1830-92 or S1C3-G engine.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
PBY-5A, 28-5ACF; T.C. 2-548, 785	SA4-1470	Alclad sheet .020 2024-T3.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
PBY-6A; T.C. AR-22	SA2354WE	Installation of two (2) Wright R2600-35 engines and Hamilton Standard 23E50/6359A-18 propellers. Reissued 1/20/72.	CE	60180	Joseph E. Morris Box 10365, Lambert Field St. Louis, MO 63145
22; T.C. 4A27	SA1-562	CJ805-3B modified as an alternate to CJ805-3 engine.	NE	61628	Northeast Airlines, Inc. Logan International Airport East Boston, MA 02128
22; T.C. 4A27	SA91SO	Modification of rotating field element G.E. 291C777G1 of G.E. 400 cycle alternator 2CM211A1.	SO	63855	Peninsular Armature Works, Inc. 3525 N.W. 51 Street Miami, FL 33101
22; T.C. 4A27	SA214CE	Autothrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22; T.C. 4A27	SA215CE	Single SCAT system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
22; T.C. 4A27	SA216CE	Autopilot variable angle intercept.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
22; T.C. 4A27	SA217CE	Second flight director system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22; T.C. 4A27	SA223CE	Dual low range radio altimeter system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22; T.C. 4A27	SA241EA	Nose cap weather radome shell.	NE	53750	McMillan Radiation Labs, Inc. Brownville Avenue Ipswich, MA 01938
22; T.C. 4A27	SA279CE	Fairchild cockpit voice recorder system. Amended 3/18/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA280CE	Autothrust system equipment.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA281CE	Single SCAT system provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
22 Series; T.C. 4A27	SA281WE	Engine-mounted fire detector system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
22 Series; T.C. 4A27	SA308WE	Voice interruption priority system.	WE	61648	Northrop Corporation 222 N. Prairie Avenue Hawthorne, CA 90250
22 Series; T.C. 4A27	SA336SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Atlanta Airport Atlanta, GA 30320
22 Series; T.C. 4A27	SA376SO	Relocation of LAS 109C flight recorder and installation of a remote accelerometer.	SO	29234	Delta Air Lines, Inc. Atlanta Airport Atlanta, GA 30320

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340, 440; T.C. 6A6	SA59RM	Installation of Collins type 331A-6P/6A course indicator and relocation of altitude alert control. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA60RM	Installation of Sundstrand ground proximity warning system, glide slope monitoring system and Honeywell low range radio altimeter system. Issued 7/11/75. Supplemental T.C. SA4-1100.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA71WE	Fuel source modification for Ranger APU approved under STC SA2-962.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA83GL	Install Bendix GPW-83 ground proximity warning system. Issued 9/5/75.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450
340, 440; T.C. 6A6	SA96GL	Installation of Collins FPC-590A ground proximity warning system. Issued 11/7/75.	GL	90135	Zantop International Airlines, Inc. Detroit-Willow Run Airport Ypsilanti, MI 48197
340, 440; T.C. 6A6	SA104RM	Install dual SELCAL system. Issued 6/22/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100); T.C. 6A6	ST133RM	Modification of turbine inlet temperature indicator Model BH183M to install precision potentionmeter in place of original tapot. Issued 2/17/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100); T.C. 6A6	ST134RM	Installation of coat closet at body station 230. Issued 2/22/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440; T.C. 6A6	SA151EA	Bendix doppler radar DRA-12.	EA	08196	Airmar Radio Service, Inc. 2177 Smithtown Avenue Ronkonkoma, NY 11779
340, 440; T.C. 6A6	SA184WE	Two 15KS-1000-A1 or two 15KS-1000-A1(E) standby rocket engines in fuselage tail cone. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
340, 440; T.C. 6A6	SA227EA	Nose cap weather radome. Amended 3/29/66.	EA	16600	Bethlehem Steel Corporation Aviation Service Division Bethlehem, PA 18016
340, 440; T.C. 6A6	SA232CE	Install aural mach warning system. Amended 2/27/67.	GL	37808	General Motors Corporation 3044 W. Grand Boulevard Detroit, MI 48202
340, 440; T.C. 6A6	SA264EA	Janitrol S-200 heater for ground operation only.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
340, 440; T.C. 6A6	SA279WE	Window emergency exit on right side of aircraft at station 651.5.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440; T.C. 6A6	SA379CE	Installation of Hoskins twilighter MK V intensity STC SA4-1100 modified aircraft. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
340, 400; T.C. 6A6	SA423WE	Cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA427EA	All cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA428EA	Installation of FM #1, 2, and 3 Radiophone. Amended 5/26/67.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA429EA	Cabinet.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340, 440; T.C. 6A6	SA443WE	Installation of cargo door, a cargo floor and an emergency exit, plus removal of original cargo door and forward passenger entrance door. Reissued 2/6/70.	NW	49350	Robert T. Lamson 7840 Southeast 20th Mercer Island, WA 98040
340, 440; T.C. 6A6	SA451EA	Cockpit voice recorder.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA454CE	Model CH 3002-3181 Hoover Aircraft Products evacuation chute.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
340, 440; T.C. 6A6	SA483EA	Installation of cabin window at F.S. 730.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA494EA	ADF-PA Interconnection.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA495EA	Installation of Flight Interphone System.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	ST519SO	Installation of underseat baggage restraint bars. Issued 11/1/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440; T.C. 6A6	SA542CE	Make and install horizontal stabilizer tips.	GL	12578	Auto-Craft Engineering 1904 N. Colorado Avenue Indianapolis, IN 46206
340, 440; T.C. 6A6	ST548SO	Installation of external induction ram air scoops. Issued 8/28/73.	SO	53788	Mackey International Airlines 500 S.W. 34 Street Fort Lauderdale, FL 33315
340, 440; T.C. 6A6	ST596SO	Installation of exhaust system bracket. Reissued 1/6/75.	SO	02394	Aeronautical Engineering, Inc. 342 N.E. 2nd Court Dania, FL 33004
340, 440; T.C. 6A6	SA604EA	Installation of United Control Model F542 Flight Data Recorder.	EA	09520	Allegheny Airlines Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA651EA	Installation of UHF/FM Secure System.	EA	52012	Lockheed Aircraft Service, Inc. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA695WE	Rain repellant system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA669WE	Smoke detector, flight data recorder, and oxygen breathing system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	ST700SO	Installation of exterior emergency lighting system. Amended 5/8/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440; T.C. 6A6	SA775WE	Interior.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505
340, 440; T.C. 6A6	SA780WE	Yoke assembly, pilot and copilot control.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA788SO	Installation of main cabin floor panels, seat tracks, and seats to accommodate 50 passengers. Issued 8/15/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440; T.C. 6A6	SA874WE	Shoulder harness installation. Amended 6/9/76.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90404
340, 440; T.C. 6A6	SA884EA	Installation of tail logo lights. Amended 10/19/71.	EA	18750	Butler Aviation Friendship, Inc. Sub. Butler Aviation International Friendship Int'l Airport Baltimore, MD 21240

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340, 440; T.C. 6A6	SA896EA	Installation of Marshell interior kit assembly No. 96123. Amended 7/13/73.	EA	54200	Magee Plastics Company 6000 Babcock Boulevard Pittsburgh, PA 15237
340, 440; T.C. 6A6	SA908WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA925WE	Pitch servo of Sperry SP-20 autopilot system.	EA	16600	Bethlehem Steel Company 701 E. Third Street Bethlehem, PA 18016
340, 440; T.C. 6A6	ST926SO	Installation of cargo door and interior. Amended 7/18/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440; T.C. 6A6	ST927SO	Installation of cargo floor. Amended 8/27/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440; T.C. 6A6	SA1015WE	Modified fiberglass vertical stabilizer tip, and Grimes 9950-1 rotating beacon.	RM	37015	Frontier Airlines, Inc. Stapleton Int'lernational Airport Denver, CO 80207
340, 440; T.C. 6A6	SA1015EA	Installation of Atlantic Aviation Corp. (TSO C-39) attendant seat P/N 21.737-1. Reissued 10/24/80.	EA	12500	Atlantic Aviation Corporation Box 15000 Wilmington, DE 19850
340, 400 (580); T.C. 6A6	SA1027EA	Installation of Collins FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340/440 modified in accordance with STC SA4-1100; T.C. 6A6	ST1035SC	Installation of a combination passenger/cargo interior to include an all cargo, 44 passenger/cargo, 10 passenger/cargo, and 6 passenger/cargo configurations. Issued 12/4/78.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36302
340, 440; T.C. 6A6	SA1060WE	AP101E Collins autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA1096WE	Rolls Royce Dart 542-4 engines with Dowty Rotol (c) R245/4-40-4.5/13 or (c) R259/4-40-4.5/17 propellers and associated modifications. Amended 7/27/66.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1097SO	Installation of two (2) double seats to increase passenger configuration from 44 to 48. Issued 8/30/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
340, 440; T.C. 6A6	SA1119WE	Two additional emergency exits, and interior arrangement.	WE	37280	General Dynamics Conviar Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1132WE	Parker Aircraft, Inc. under-wing pressure refueling valve and Roylin "Magna-Stick" fuel indicator.	WE	06750	Aircraft Tack Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA1146WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA1174WE	Fuel jettison system.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440; T.C. 6A6	SA1210WE	Cargo floor, cargo door and forward service door.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1268WE	Interior and equipment.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505
340, 440; T.C. 6A6	SA1331WE	Installation of United Data Control, Inc. Model V-557 cockpit voice recorder system. Amended 3/28/67.	RM	37015	Frontier Airlines 5900 East 39th Street Denver, CO 80207
340, 440; T.C. 6A6	SA1338WE	Seat track, additional emergency exit and interior arrangement.	WE	37280	General Dynamics Corp. P.O. Box 1950 San Diego, CA 92112

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340, 440; T.C. 6A6	SA1366WE	Installation of Collins Radio Company FD105 flight director system.	WE	37280	General Dynamics Convair Division P.O. Box 1950 San Diego, CA 92112
340, 440; T.C. 6A6	SA1407SW	Provide 52-passenger seat aircraft with cargo carrying capability by installing an aft cargo door and reinforcing the floor and fuselage shell. Amended 6/1/72.	WE	37280	General Dynamics Corporation Convair Aerospace Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1438WE	Installation of an Avionics System.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA1482WE	Installation of interior arrangement.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA1505WE	Installation of radio transformer rectifier for standby D.C. power.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA2302WE	Modification of pedestal flight idle stop and lift to reverse system. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
340, 440; T.C. 6A6	SA2697WE	Modification including those airplanes further modified per STC SA1096WE for turbo propeller power for installation of cargo door, cargo floor and cargo lining. Issued 5/25/73.	WE	10208	American Jet Industries, Inc. 2800 Clybourn Avenue Burbank, CA 90405
340, 440; T.C. 6A6	SA2733WE	Modification of Model 340/440 previously modified per STC SA4-1100 for turbo propeller power for installation of cargo door, cargo floor and cargo lining. Issued 9/5/73.	WE	10208	American Jet Industries, Inc. 2800 Clybourn Avenue Burbank, CA 91505
340,440; T.C. 6A6	SA2896SW	Conversion to an all-cargo configuration. Issued 1/15/79.	SW	08128	Airgo, Inc. LB-31 Love Field Terminal Bldg. Dallas, TX 75235
340,440; T.C. 6A6	SA2897SW	Composite flooring, one double seat, nonstructural bulkhead.	SW	08128	Airgo, Inc. LB-31 Love Field Terminal Bldg. Dallas, TX 75235
CV340/440; T.C. 6A6	SA3132WE	Installation of an alternate (printed circuits) ice protection system on the engine air intake. Amended 11/17/77. This installation is approved for use on airplanes modified in accordance with STC SA4-1100 only.	WE	71680	Sierracin/Thermal Systems 13920 South Broadway Los Angeles, CA 90061
340, 440; T.C. 6A6	SA3294WE	Modification by installation of dual mach/airspeed warning system. Reissued 1/20/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA3479WE	Modification by installation of an alternate pallet restraint system.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
340/440; T.C. 6A6	SA3574WE	Modification of Convair 340 or 440 which have been modified per STC SA4-1100. Issued 3/24/78.	WE	45500	Jay Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90904
340/440; T.C. 6A6	SA3758WE	Enlarge cargo door on aircraft modified per STC No. SA2733WE. Issued 10/17/78.	WE	10218	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
340,440; T.C. 6A6	SA3772WE	Installation of cargo tie downs in aircraft modified per STC No. SA2733WE. Issued 11/1/78.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA
340, 440; T.C. 6A6	SA4075SW	BKM 100PHM-2 pitot head monitor system. Issued 1/17/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
340, 440; T.C. 6A6	SA4162WE	Installation of nose radome and relocation of airspeed pitot system. Amended 7/9/80.	WE	39876	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	DS	STC CODE	STC HOLDER
440; T.C. 6A6	SA4-49	Two 250-gallon auxiliary fuel tanks in wing center section.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-195	Janitrol S-50 ground heater.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-196	Extended wing tank installation and oil tank rework.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-245	GTP-70-17 auxiliary gas turbine power plant.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-314	Cabin interior.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
440; T.C. 6A6	SA4-407	Andover Type D-2, Model V-32 APU for ground operation only.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-408	Interior arrangement installation (right hand forward cargo door made permanently inoperative as an exit by seating arrangement).	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-675	Oscillograph rack.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-692	Interior equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-857	APS-14 antenna.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-897	Window station 730 L.H.	WE	07500	AiResearch Aviation Service Co. 6021 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-930	Aircraft interior.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440; T.C. 6A6	SA4-1319	Bendix RDR-1D radar and equipment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA4-1420	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA1950SW	Structural installation of Bendix ANA-12A-1 doppler antenna.	SW	12250	Associated Radio Service Co. 7515 Lemmon Avenue Dallas, TX 75220
440; T.C. 6A6	SA203WE	Interior and equipment installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440; T.C. 6A6	SA384EA	Two three-place couches.	EA	03100	Aero Trades, Inc. Long Island Airport Ronkonkoma, NY 11779
440; T.C. 6A6	ST929SO	Installation of a cargo door. Issued 5/10/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
440; T.C. 6A6	SA4181WE	Installation of side mounts and seats. Issued 7/17/80.	WE	39876	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
440; T.C. 6A6	SA4183WE	Installation of underseat baggage restraint. Issued 7/10/80.	WE	39876	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
GOVERNMENT AIRCRAFT FACTORIES

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
N22B; T.C. A7PC	SA363GL	Convert the landplane to a seaplane by installing Wipline Model 9812 twin seaplane floats. Issued 9/12/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
N22B; T.C. A7PC	SA428GL	Installation of Wipline Model 9500 amphibious twin seaplane floats per Wipaire, Inc. Issued 8/1/80.	GL	86745	Wipaire, Inc. South End Doane Trail Inver Grove Heights, MN 55075
N24A; T.C. A7PC	SA1210EA	Installation of APC's starter-generator, P/N 150SG111Q. Issued 11/4/80.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GREAT LAKES AIRCRAFT CO., OHIC

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
2T1 Series; T.C. A-167	SA1115WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
2T-1; 2T-1A; 2T-1E; ATC 167, 228, 354	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
2T-1, 2T-1A, 2T-1E; ATC 167, 228, 354	SA2666WE	Ceconite 102 material covering complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
2T-1A; T.C. 228	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GRUMMAN AMERICAN AVIATION CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
J2F Series; L.T.C. 17	SA1028WE	Ceconite 101 covering of wings, ailerons, rudder and elevators.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
J2F-3, -4, -5, -6, TBF-1-1C, -3, -3E, FM-2, G-21, -21A, G-44, -44A Scan Type 30; LTC-17, -8, -25, T.C. 654, 734	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Issued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J2F-3, -4, -5, -6, FM-2, G-21, -21A, G-44, -44A, SCAN Type 30, TBF-1, -1C, TBM-3, -3E; LTC 17, 25, T.C. 654, 734, LTC 8	SA2666WE	Ceconite 102 material covering of: J2F-3, -4, -5, -6 - wings, ailerons, rudder and elevators; FM-2 - all fabric-covered control surfaces; G-21, -21A - elevators, rudder, ailerons and wing trailing edge; G-44, -44A - rudder, elevators and ailerons; TBF-1, -1C, TBM-3, -3E - ailerons, rudder and elevators. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
TBF, TBM Series; LTC 8	SA4-911	Eonite covering on ailerons, rudder, elevators.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
TBF, TBM Series; LTC 8	SA4-1187	Ceconite 101 covering of ailerons, rudder and elevators.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
TBF, TBM Series; LTC 8	SA4-1504	Neoprene expander tube to replace piston brake seal.	WE	71640	Sierra Aviation Airport P.O. Box 21 Porterville, CA 93257
TBF, TBM, FM-2, G-21, G-21A; T.C. 654, LTC 8, LTC 25	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
FM-2; LTC 25	SA4-1613	Ceconite 101 covering of all fabric covered control surfaces.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
F8F-1; LTC 23	SA49GL	Installation of reinforcement of wing center section lower spar cap. Issued 5/31/74.	GL	14300	G.W. Balz 4171 Lake Terrace Kalamazoo, MI 49008
F8F-1; LTC 23	SA1008WE	Poly-Fiber covering of elevator and aileron. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
G-21 Series; T.C. 654	SA2317WE	Installation of dual brakes. Issued 2/24/71.	NW	53520	McKinnon Enterprises, Inc. Route 3, Box 690 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA1-3	Replacement of wing panel fabric by 025 aluminum, 24ST ALCLAD.	EA	56645	Mattituck Airbase Corporation Linden Airport Linden, NJ 07036
G-21, G-21A; T.C. 654	SA1-52	Installation of new propellers. Installation of emergency governor crossfeed system for unfeathering. Amended 10/23/67.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
G-21, G-21A; T.C. 654	SA4-591	Increased maximum weight capacity of bow compartment.	AL	08483	Alaska Coastal Airlines 2 Marine Way Juneau, AK 99801
G-21, G-21A; T.C. 654	SA4-677	Picture window.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-678	New nose.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-21, G-21A; T.C. 654	SA4-680	Windshield.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-681	Dorsal fin.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-682	Retractable float.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-683	Installation of auxiliary fuel tanks in outboard wing sections. Amended 6/25/68.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1055	Rotary beacon.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1109	Metqlizing of wings aft of spar.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1137	Ceconite 101 covering of elevators, rudder, ailerons and wing trailing edge.	WE	20250	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 90063
G-21, G-21A; T.C. 654	SA4-1467	Modification of increase maximum maximum weight to 9,200 lbs.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1550	Wing leading edge landing lights.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA4-1551	Electric gear retract motor.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA99GL	Install Cleveland Wheel and Brake conversion kit P/N 199-65. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
G-21, G-21A; T.C. 654	SA101WE	Picture window.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA108WE	Bulkhead station 26 flotation compartment.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA113SO	Replacement brake linings on Grumman G-29 main landing gear brake shoes. Amended 1/16/67.	SO	58708	Miami Brake & Clutch Service 3634 N.W. 36th Street Miami, FL 33101
G-21, G-21A; T.C. 654	SA138SW	Modifications to increase maximum weight to 9,000 pounds.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
G-21, G-21A; T.C. 654	SA355WE	Hull vents.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21A; T.C. 654	SA551SW	Modification of Beech C18 cowl to fit Grumman G-21A.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
G-21, G-21A; T.C. 654	SA696WE	Aluminum skin on elevator control surface.	WE	49365	Lancer Engineering 26927 Fond Du Lac Road Palos Verdes Peninsula, CA 90274
G-21, G-21A; T.C. 654	SA1589WE	Installation of two United Aircraft of Canada, Ltd. Model PT6-20 engines.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-21, G-21B; T.C. 654	SA96NW	Installation of Sorm Industries horizontal stabilizer forward support fitting. Issued 3/18/74.	NW	73820	Sorm Industries, Inc. 7999 West Perimeter Road Seattle, WA 98018
G-21A; T.C. 654	SA294AL	Installation of UACL model PT6A-20 engines.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
G-21A; T.C. 654	SA295AL	Installation of passenger seats. Amended 4/17/70.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-21A; T.C. 654	SA2298WE	Modification of Bendix master brake cylinder by installation of Griffco Aviation piston and O-rings in lieu of Bendix piston assembly P/N 52152. Issued 1/7/71.	NW	39492	Griffco Aviation 7580 Perimeter Road Boeing Field International Seattle, WA 98108
G-21A; T.C. 654	SA3630WE	Increase maximum weight to 8750 lbs. on aircraft equipped with Hartzell three bladed full feathering propellers (per STC SA1-52). Issued 4/5/78.	WE	20160	Catalina Airlines, Inc. Berth 95-95 P.O. Box 207 San Pedro, CA 90733

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G44, G44A, Modified -- Colemill STC 2-13; T.C. A-734	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 1/19/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
G-44, G-44A, SCAN 30; T.C. 734	SA61SW	Horizontal stabilizer raised 5/8 inch per STC SA2-13.	SW	52870	J.R. McDermott & Company, Inc. Lakefront Airport New Orleans, LA 70113
G-44, G-44A, SCAN 30; T.C. 734	SA121EA	Wheel 40-46 and brake 30-31. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
G-44, G-44A, SCAN 30; T.C. 734	SA380WE	Engine, propeller and associated modifications of nacelle, electrical oil, fuel and vacuum systems.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA603WE	Large aft door. Reissued 3/17/67.	SO	37084	Gander Aircraft 3923 N.W. 24th Street Miami, FL 33142
G-44, G-44A; T.C. 734	SA835SO	Installation of Lycoming GO-480-G2D6 engines with Hartzell HC-A3VP-5R/V9333CH-3 reversing propellers. Reissued 10/9/79.	SO	02330	AEROMAR, Inc. 317 North Coconut Lane Palm Island Miami, FL 33139
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3174SW-D	Automatic flight system AK645 consisting of Century I autopilot with optional omni tracker system. Issued 1/31/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3175SW-D	Mitchell automatic flight system AK646 consisting of Century IIB autopilot with optional radio coupler. Issued 1/31/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3176SW-D	Mitchell automatic flight system AK647 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/17/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3184SW-D	Automatic flight system AK656 consisting of Century I autopilot with optional omni tracker. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3185SW-D	Mitchell automatic flight system AK657 consisting of Century IIB with optional radio coupler. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3186SW-D	Automatic flight system AK658 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Scan Type 30; T.C. A734	SA3221SW-D	Mitchell automatic flight system AK706 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 6/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Scan Type 30; T.C. A734	SA3222SW-D	Mitchell automatic flight system AK705 consisting of Century IIB autopilot with optional radio couplers. Issued 7/8/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44, G-44A; T.C. A-734	SA3979WE	Installation of Silver Instruments fueltron 111G digital fuel flow and totalizer system. Issued 6/15/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
G-73; T.C. 783	SA1-490	Opening in leading edge of right-hand wing for passing light installation.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
G-73; T.C. 783	SA1-546	Type 21 pump type pneumatic deicer system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
G-73; T.C. 783	SA3-22	Hull step fairing.	GL	17190	Briggs Manufacturing Company 6600 East Outer Drive Warren, MI 48089

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-73; T.C. 783	SA3-165	Two 100-ampere Eclipse 30E16-1 generators.	GL	37808	General Motors Air Transport City Airport Detroit, MI 48202
G-73; T.C. 783	SA3-194	Sonotone sintered-plate Alkaline Nickel-Cadmium battery.	GL	71520	George W. Sherwood City Airport Detroit, MI 48233
G-73; T.C. 783	SA4-1554	Structure modification to improve access to fuel tanks for stripping and resealing.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-73; T.C. 783	SA292EA	Pump type pneumatic deicer system.	GL	38500	B.F. Goodrich Airport Operations Municipal Airport Akron, OH 44318
G-73; T.C. 783	SA310EA	Fabrication of new passenger seats and necessary cabin interior modifications. Amended 4/5/68.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
G-73; T.C. 783	SA319SW	Structural installation of McMillan 7501XM radome and RCA AVQ-55 antenna mount.	SW	12250	Associated Radio Service Company 7515 Lemmon Avenue Dallas, TX 75220
G-73; T.C. A-783	SA412GL	Installation of Parker Hannifin conversion kit P/N 199-81. Issued 5/29/80.	GL	62500	Parker Hannifin Corporation Cleveland Wheels & Brakes Div. 1160 Center Road Avon, OH 44011
G-73; T.C. 783	SA614SO	Installation of nose wheel shimmy damper IAW Gander drawings GA-2055 Chg. A and GA-2056 Chg. A.	SO	37084	Gander Aircraft Corporation 3923 N.W. 24th Street Miami, FL 33142
G-73; T.C. 783	SA1008WE	POly-Fiber covering of rudder. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
G-73; T.C. 783	SA2323WE	Increase in gross weight and installation of United Aircraft of Canada, Ltd., PT6A-27 engines. Amended 12/18/73.	WE	36699	Frakes Aviation, Inc. P.O. Box 159 Angwin, CA 94508
G-164; T.C. 1A16	SA4-1017	Lycoming R680-13 engine and Hamilton Standard 2B20-329/6135A-9 propeller.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA4-1019	Pratt & Whitney R-985-ANI, -NAS, -AN-14BMI, -39 or -39A engines and Hamilton Standard 2D30-277/6101A-12 to -18 propellers. Amended 9/30/65.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA32NW	Installation of 15.5 gallon auxiliary fuel tank in each upper wing panel. Amended 6/30/77.	NW	52066	Russell Longnecker Box 77 Mt. Vernon, WA 98273
G-164; T.C. 1A16	SA39WE	Pratt & Whitney R985-AN-3 engine and Hamilton Stnadard 2D30-227/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164; T.C. 1A16	SA170SW	Sensenich 5404R/MA96K propeller.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA287SW	Jacobs R-755-L4MB or R-755-B2M engine.	SW	52610	Lyon Flying Service, Inc. P.O. Box 726 Welsh, LA 70591
G-164; T.C. 1A16	SA312SW	Jacobs R-755-B2MI, R-755-B2M, L4M Series, R-755-A2M, or R-755-A2MI engine with short mount A1681, carburetor air filter box, funnel A1667, and Sensenich J5404/MA96K propeller.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA326CE	25-gallon auxiliary fuel tank on wing.	CE	59315	Mid-Continent Aerial Sprayers, Inc. P.O. Box 307 Hayti, MO 63851
G-164; T.C. 1A16	SA507SW	Optional 46-gallon wing center section fuel tank and alternate right-hand or left-hand carburetor muffs equipped with Jacobs L4M and R-755 series engine.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA647WE	Modified landing gear.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-164; T.C. 1A16	SA648WE	Additional flying wire.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA651WE	Modified wheels and brakes.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA1278WE	Ceconite 101 covering of wings and ailerons.	WE	26240	Cooper Engineering Corporation P.O. Box 3428 Van Nuys, CA 91408
G-164; T.C. 1A16	SA1295WE	Automatic flagman marker dispensing unit.	NW	03500	Air-Ag, Inc. Route 4 Walla Walla, WA 99362
G-164; T.C. 1A16	SA1407WE	Installation of Pratt & Whitney R-985-AN-1 engine and Hamilton Standard 2D30/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164; T.C. 1A16	SA1586WE	Installation of Pratt & Whitney R-1340-AN-1 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164, G-164A; T.C. 1A16	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	ECNAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
G-164, G-164A; T.C. 1A16	SA270WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller. Amended 7/11/68.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164, G-164A; T.C. 1A16	SA406NW	Installation of wing span extension. Amended 5/23/77.	RM	02360	Aero Mod General, Inc. Box 68 Latah, UT
G-164, G-164A; T.C. 1A16	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
G-164, G-164A; T.C. 1A16	SA940SW	Installation of Micronair AU-3000 spray units. Reissued 10/2/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164, G-164A; T.C. 1A16	SA1282SW	Jacobs-Page R-755SM engine and Grumman 5404/M96F propeller. Reissued 5/24/77.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
G-164 (S/N 301-400), G164A (S/N 400 and up); T.C. 1A16	SA1312WE	Fabrication and installation of 285-gallon fiberglass hopper (replaces 245-gallon metal hopper). Reissued 6/12/75.	GL	39542	Grumman American Aviation 318 Bishop Road Cleveland, OH 44143
G-164, G-164A; T.C. 1A16	SA1319CE	Chrome plated brake disc installation. Issued 7/22/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
G-164, G-164A; T.C. 1A16	SA1777WE	Installation of Hamilton Standard 3D40/6101A-17 propeller.	WE	85125	Western Aircraft Sales P.O. Box 753 Long Beach, CA 90801
G-164, G-164A; T.C. 1A16	SA2012WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	17022	Bowles Flying Service Route 1, Box 124-B Live Oak, CA 95953
G-164, G-164A, G-164B; T.C. 1A16	SA832SO	Installation of Hamilton Standard Model 2D30/6101A-10S propeller. Amended 10/15/76.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164, G164A, G-164B; T.C. 1A16	SA1427CE	Install smoke generator for Part 137, agricultural aircraft operations, only. Issued 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508 Renner Field Goodland, KS 67735
G-164, G-164A, G164B; T.C. 1A16	SA3077WE	Installation of elevator servo-tab. Reissued 3/17/77.	WE	26540	Robert I. Copeland 171 West Shannon Chandler, AZ 85224
G-164, G-164A, G-164B; T.C. 1A16	SA4101WE	Installation of locking tail wheel. Issued 2/14/80.	WE	11470	AFS Products, Inc. 6751 Airport Road Redding, CA 96001

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-164, G-164A, G-164B, G-164C; T.C. 1A16	SA2747SW	Lockable full swivel tail wheel. Issued 4/6/78.	SW	36700	Frakes Aviation Cleburne Airport Rt. 3, Box 229-B Cleburne, TX 76031
G-164, G-164A, AA-1, AA-1A, AA-1B, AA-5; T.C. 1A16, A11EA, A16EA	SA71GL	G-164's install P/N BA8210 filter assembly; AA-1, AA-5 install P/N BA 4210 filter assembly. Reissued 9/22/79.	WE	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140
G-164A; T.C. 1A16	SA99NW	Installation of HSP 3D40-401 hub with EAC-100-2 blades. Issued 3/29/74.	NW	33000	Efficiency Aircraft P.O. Box 37 Kent, WA 98031
G-164A; T.C. 1A16	SA445NW	Installation of EAC-22D30-AG-200-4S prop or P&W R-985-AN-1 engine. Issued 5/9/77.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A; T.C. 1A16	SA809SW	Installation of 5-inch longer engine mount in S/N 401 and up. Reissued 9/25/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164A; T.C. 1A16	SA833SO	Installation of Hamilton Standard Model 12D40/6101A-10S propeller approved under STC SP830SO on Pratt & Whitney R1340-AN-1, S1H1 or S3H1 engines listed in TDS 1A16. Issued 4/28/75.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164A; T.C. 1A16	SA994SW	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101-12 propeller. Reissued 4/19/73.	GL	39542	Grumman American Aviation Corp. 318 Bishop Road Cleveland, OH 44143
G-164A, S/N 526 and up with a P & W R-1340-AN-1 engine and Hamilton Standard 12D40 propeller; T.C. 1A16	SA1077CE	Installation of Edo-Aire propeller governor. Issued January 1975.	CE	32500	Edo-Aire, Inc. Wichita Division 1326 S. Walnut Street Wichita, KS 67213
G-164A; T.C. 1A16	SA1222SW	64-gallon or 80-gallon fuel tanks. Issued 11/17/70.	EA	39540	Grumman Aerospace Corporation P.O. Box 147 Elmira, NY 14902
G-164A; T.C. 1A16	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 7/24/73.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-164A; T.C. 1A16	SA1422SW	Paper filter for engine induction air. Issued 1/19/72.	SW	17260	Frank Brinster 2214 North Parkwood Harlingen, TX 78550
G-164A; T.C. 1A16	SA2015WE	The 12-volt or 24-volt D.C. electrical generating system is replaced by an alternator system. Amended 12/21/78.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
G-164A; T.C. 1A16	SA2356SW	Wing tip extension of 20 inches. Issued 9/14/76.	SW	34405	Fram & Ranch Aerial Service Wharton, TX 77055
G-164A; T.C. 1A16	SA2444SW	Install P&W ACL PT6A-34 engine. Issued 12/2/77.	SW	36700	Frakes Aviation, Inc. Route 2, Box 229-B Cleburne Airport Cleburne, TX 76031
G-164A; T.C. 1A16	SA2731SW	PZL-3S engine and Dowty-Rotol propeller CR 289/3-110-F/1. Issued 3/17/78.	SW	52610	Lyon Flying Service, Inc. P.O. Box 726 Welsh, LA 70591
G-164A, G-164B; T.C. 1A16	SA78RM	Installation of air conditioner system. Amended 6/21/77.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
G-164A, G-164B; T.C. 1A16	SA434NW	Installation of EAC-12D40-AG-100S-4S prop on Pratt & Whitney R-1340-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA436NW	Installation of WAC-2D30-425-AG-100-4A prop on Pratt & Whitney R-985-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA1102SO	Installation of a 360-gallon agricultural spray dispensing hopper. Reissued 8/25/80.	WE	79295	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
G-164A, G-164B; T.C. 1A16	SA1129SO	Installation of a 320 gallon agricultural spray dispensing hopper. Issued 1/24/80.	WE	79295	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTIO'	RG	STC CODE	STC HOLDER
G-164A, G-164B; T.C. 1A16	SA1131SO	Installation of replacement fiberglass fuselage skin panels. Reissued 8/25/80.	WE	79295	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
G164A, G164B; T.C. 1A16	SA2666WE	Ceconite 102 material covering of: G-164A - vertical and horizontal tail and wings; G-164B - complete aircraft. Amended 4/19/78.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-164A, G-164B; T.C. 1A16	SA4185WE	Installation of two Conrel dispensing pods. Issued 7/15/80.	WE	08550	Albany International Controlled Release Division P.O. Box 537 Buckeye, AZ 85326
G-164B; T.C. 1A16	SA199RM	Oil temperature controlled system. Issued 4/17/80.	RM	18268	Vincent S. Buraas P.O. Box 176 Northwood, ND 58267
G-164B; T.C. 1A16	SA4116SW	Lycoming LTP-101-600-A1A engine. Issued 4/29/80.	SW	62196	Page Industries, Inc. P.O. Exo 191 Yukon, OK 73099
G-164B (Restricted Category); T.C. 1A16	SA3876WE	Installation of Alvis Leonides engine and Dowty Rotol (c)R284/3-20-3/8 constant speed propeller. Issued 3/6/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Morteson Avenue Salinas, CA 93905
G-164C (Restricted Category); T.C. 1A16	SA3764WE	Installation of Wright R-1820-71, -60; GR1820G-202A, 702C9GC1, 2, 3, 4, 704C9GC1, 2, 3, 4 engine and Hamilton Standard 43D50 or 33D50 constant speed propeller. Reissued 4/11/80.	CE	59320	Mid-Continent Aircraft Corp. Drawer L Hayti, MO 63851
G-164C; T.C. 1A16	SA4127WE	Installation of an AiResearch TPE331-1-101Z turboprop engine. Issued 4/18/80.	WE	75210	Floyd D. Stilwell Marsh Aviation 5060 E. Falcon Drive Mesa, AZ 85205
AA-1 Series; T.C. A11EA	SA809NW	Installation of fixed (flush) cowl flap, nose gear strut fairing and retainer. Issued 7/20/79.	NW	27241	Maynord C. Corsby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1 Series; T.C. A11EA	SA810NW	Installation of main landing gear fairings from the AA-5 series aircraft incorporating sheet metal covers over rubber in place of stock rubber parts. Issued 7/20/79.	NW	27241	Maynord C. Crosby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1; T.C. A11EA	SA1410SW	Mitchell automatic flight system AK301, consisting of Century I autopilot with optional omni tracker. Issued 12/28/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-1; T.C. A11EA	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
AA-1; T.C. A11EA	SA2104WE	Installation of Brittain Models B2C and BSS flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
AA-1; T.C. A11EA	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1010CE	Installation of wing leading edge cuffs. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1313CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-1, AA-1A, AA-1B; T.C. A11EA	SA3234WE	Installation of Piper oil cooler and associated installation components. Issued 7/8/76.	WE	05390	Aircraft Maintenance Service 7950B Joe Crosson Drive Santee, CA 92071
AA-1, AA-1A, AA-1B; T.C. A11EA	SA4106SW	Increase gross weight to 1560 lbs. for AA-1, 1560 lbs. for AA-1A, and 1600 lbs. for AA-1B. Issued 3/26/80.	SW	24100	James E. Collier Route 4, Box 810 Jefferson, TX 75657

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
AA-1 (1969 and on), AA-1A (1969 and on), AA-1B (1969 and on), AA-5 (1972, 1973 and 1974 only); T.C. A16EA	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
AA-1; AA-5; T.C. A11EA, A16EA	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1B; T.C. A11EA	SA10NW	Installation of VA-3 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-1B; T.C. A11EA	SA11NW	Installation of VA-2 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	VAn's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-1C Utility Category; T.C. A11EA	SA3695WE	Installation of Lycoming O-235-C2C engine and McCauley 1A105/SCM7154 propeller. No installation data required. Placards required with this installation: At the fuel filler caps - "80/87 MIN OCTANE AVGAS" Issued 7/7/78	WE	03105	Aero-Training, Inc. 89 John Glenn Drive Concord, CA 94520
AA-5; T.C. A11EA	SA66NW	Installation of VA-4 fiberglass wheel fairings. Issued 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-5; T.C. A16EA	SA1472SW	Mitchell automatic flight system. AK374 consisting of Century IIB autopilot with optional omni tracker. Issued 6/28/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5; T.C. A16EA	SA1486SW	Mitchell automatic flight system AK373 consisting of Century I autopilot with optional radio coupler. Issued 5/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5, -5A, -5B; T.C. A16EA	SA1314CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33460	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-5B; T.C. A16EA	SA3031SW-D	Mitchell automatic flight system AK514 consisting of Century I autopilot with omni tracking system. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5B; T.C. A16EA	SA3032SW-D	Mitchell automatic flight system AK515 consisting of Century IIB autopilot with optional radio coupler. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5B; T.C. A16EA	SA3301WE	Installation of Model EGT-1 exhaust gas temperature monitoring system. Issued 11/23/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
AA-5B; T.C. A16EA	SA3309WE	Modification of primary control system by addition of rudder-aileron interconnect and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/27/77.	WE	12250	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
G-159; T.C. 1A17	SA1-399	Forward and aft attachment for HF antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-159; T.C. 1A17	SA761WE	13-passenger interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	ST762SO	Installation of main cabin floor support structure. Issued 8/19/77.	GL	90[illegible]5	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST763SO	Installation of courier seat and cockpit/main cabin partition. Issued 8/19/77.	GL	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST764SO	Enlarged passageway in F8525 main cabin bulkhead. Issued 8/19/77.	GL	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
G-159; T.C. 1A17	SA807SW	FD108/AP103E/F Flight Director-Autopilot combination for Category II operation.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA838WE	Shelf and webbing in baggage compartment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA839WE	Lavatory external service pen.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA879WE	Two radar altimeter antennas.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA886WE	Honeywell aircraft recognition light system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA888EA	Installation of Grimes three light strobe kit 34-0303-1 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
G-159; T.C. 1A17	ST889SO	Installation of Collins ground proximity warning system. Issued 3/16/76.	SO	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-159; T.C. 1A17	SA893SW	Dual FD-109 Flight Director/AP-104 Autopilot, 54W-1C Comparator Warning, AL-101 Radio Altimeter, MC-102 Compass, 51RV-1, VOR/ILS, 51Z-4 Marker, 860E-2 DME and DF-203 ADF systems.	SW	24252	Collins Radio Company Avionics System Center P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA999CE	Installation of battery temperature monitor and over temperature warning system.	CE	05250	Aircraft Instrument and and Development, Inc. 317 E. Lewis Wichita, KS 67202
G-159; T.C. 1A17	ST999SO	Installation of Bendix ground proximity warning system. Issued 6/24/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-159; T.C. 1A17	SA1034EA	Installation of Safeway de-icer overshoes P/N 5651 and/or Semsa leads P/N S.2002 on Dowty Rotol propeller model R184/4-30-4/50 with blades P/N R.A25907. Issued 3/22/76.	EA	70830	Semsa, Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779
G-159; T.C. 1A17	SA1050SO	Replace existing nickel cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
G-159; T.C. 1A17	SA1098WE	EGT and r.p.m. indicator for APU, Model GTC 85-37.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1137EA	Installation of the Global GNS-500A Omega navigation system. Amended 6/13/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-159; T.C. 1A17	SA1204EA	Installation of Solar T-62T-40C2 APU. Issued 8/8/80.	EA	73275	PATS, Inc. 7190-B Oakland Mills Road Columbia, MD 21046

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-159; T.C. 1A17	SA1284WE	Kollsman MS28011-2 sextant.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1318WE	Lear Siegler, Inc. 510K autopilot system.	WE	07500	AiReserach Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1341CE	Installation of Collins Radio Group FPS-80 flight control system including electric trim. Amended 5/16/80.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, NE Cedar Rapids, IA 52406
G-159; T.C. 1A17	SA1536SW	Foxtronics TRAMM BTI-600 nickel-cadmium battery temperature system. Issued 11/10/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
G-159; T.C. 1A17	SA1559SW	Semi-automatic fuel trim system. Issued 12/4/72.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159; T.C. 1A17	SA1678SW	Modification of Burns BH 1600 (P/N 908-2-1 and -2) double seats. Issued 6/20/73.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1709SW	Oxygen service installation. Issued 7/31/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-159; T.C. 1A17	SA1745SW	ANS-70A Area Navigation System. Issued 2/21/74.	SW	24252	Collins Radio Company 1200 N. Alma Road Richardson, TX 75207
G-159; T.C. 1A17	SA1763SW	Modification to Burns BH1600 double seats to aft facing. Issued 11/14/73.	SW	84600	Ward Int'l Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1964WE	Installation of jump seat.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1955SW	Installation of Collins AP-105 autopilot for Category I operation. Amended 5/5/80.	CE	24250	Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
G-159; T.C. 1A17	SA2629WE	Installation of single point refueling system. Issued 1/8/73.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-159; T.C. 1A17	SA3044WE	Installation of fuel tank inter-connect system. Issued 7/9/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-159; T.C. 1A17	SA3641WE	Installation of DeVore Aviation Corp. horizontal stabilizer mounted vertical tail flood lights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
G-159, G-1159; T.C. 1A17, A12EA	SA10NE	Installation of a "back-up" passenger seat restraing system. Amended 3/30/78.	NE	69850	S.A.G.E. Corporation Burlington Int'l Airport Burlington, VT 05401
G-159, G-1159; T.C. 1A17, A12EA	SA1082SW	Revise nose gear steering cockpit control by installing BKM Guide-master.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159, G-1159; T.C. 1A17, A12EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
G-1159; T.C. A12EA	SA23NE	Installation of aluminum grating on cargo door at fuselage station 539.75. Issued 3/27/78.	NE	69850	S.A.G.E. Corporation Burlington International Airport Burlington, VT 05401
G-1159; T.C. A12EA	ST222GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
G-1159; T.C. A12EA	SA272GL	Installation of Intercontinental Dynamics Corp. engine vertical scale instruments. Amended 12/5/78.	EA	44160	Intercontinental Dynamics Corp. 170 Coolidge Avenue Box 81 Englewood, NJ 07631
G-1159; T.C. A12EA	ST566SO	Installation of Bendix RNS-3400 area navigation system. Amended 5/23/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA579EA	Installation of a custom interior.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA606EA	Installation of shelf and bracketry at fuselage station 743.0 - 769.62, replace metal skins with fiberglass between fuselage station 813.31 and 855.00 and bracketry provisions between fuselage station 812.50 and 826.50.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA607EA	Manufacturing and installation of partition and door blow out provisions. Amended 12/29/69.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA608EA	Installation of dual Sperry SPI-73E flight director.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA618EA	Installation of Atlantic Aviation Corporation's TSO'd retractable seat, Type G11. Amended 6/17/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA623EA	Installation of bulkhead door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA624EA	Installation of bulkhead and bulkhead door at fuselage station 194.25.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA625EA	Installation of bulkhead and bulkhead door at fuselage station 503.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA626EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. Reissued 6/3/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA627EA	Installation of Collins 54W-1 comparator warning system. Amended 12/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA628EA	Installation of Collins AL-101 radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA629EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA630EA	Installation of Sperry C-11B gyro compass system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA631EA	Installation of dual Collins F.D. 109G flight director systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA632EA	Installation of Pyrotector smoke detector system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA633EA	Installation of constant flow passenger oxygen system. Amended 12/5/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA645EA	Installation of structural provisions for the Collins doppler DH-101.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA649EA	Installation of Litton LTN-51 inertial navigation system. Amended 12/11/68.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA654EA	Installation of Honeywell hi-intensity recognition lights. Reissued 11/12/68.	GL	42250	Honeywell, Inc. 2600 Ridgway Road Minneapolis, MN 55413
G-1159; T.C. A12EA	SA655EA	Installation of Collins flight directors.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA657EA	Installation of Sperry comparator warning unit.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA658EA	Installation of Sperry altitude preselect system. Amended 12/31/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA659EA	Installation of Bendix ALA-51A radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE19899
G-1159; T.C. A12EA	SA660EA	Installation of dual Sperry SPI-73E flight director system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA662EA	Installation of an Air-Lavatory Drain. Amended 12/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA663EA	Installation of EDO Loran System. Amended 1/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA669EA	Installation of bulkhead and bulkhead door at fuselage station 201.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA670EA	Installation of bulkheads at fuselage stations 467.5, 485.0 and 515.25; bulkhead doors at fuselage stations 485.0 and 515.25; and longitudinal bulkhead at buttline 4 between fuselage stations 467.5 and 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA680EA	Installation of conference table.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA681EA	Installation of bulkhead and bulkhead door at fuselage station 255.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA682EA	Installation of bulkhead and bulkhead door at fuselage station 495.0. Amended 9/10/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA683EA	Installation of sliding door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA684EA	Installation of intercostals between fuselage station 244-1/2 to fuselage station 257-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA685EA	Installation of intercostals between fuselage station 487 to fuselage station 498. Amended 10/22/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA688EA	Installation of Collins FD-109H and FD-109F flight director system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA689EA	Installation of IDC 17000-22 Air Data Computer. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA691EA	Installation of a dual Collins DF-203 ADF.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA692EA	Installation of intercostals between fuselage station 193 to fuselage station 206.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA693EA	Installation of bulkhead and bulkhead door at fuselage station 495 5/8.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA694EA	Installation of bulkhead and bulkhead door at fuselage station 200.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA699EA	Installation of intercostals between fuselage station 345 7/8 to fuselage station 355 1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA701EA	Installation of Hartman Systems Company vertical scale engine instruments. Reissued 11/29/68.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746
G-1159; T.C. A12EA	SA702EA	Installation of intercostals between fuselage station 452 1/2 to fuselage station 466.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA706EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. Amended 9/3/80.	SC	15475	Bendix Corporation Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA718EA	Installation of intercostals between fuselage station 498 to fuselage station 512.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA721EA	Installation of swivel seat installation, fuselage stations 287 1/2 to fuselage station 379.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA722EA	Installation of Safe Flight SCAT/Autopower System. Amended 1/7/75.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
G-1159; T.C. A12EA	SA723EA	Installation of intercostals between fuselage station 43-1/2 and fuselage station 452-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA724EA	Installation of vertical scale full quantity indicators Model VS-2PE (639-) as replacement for original round dial indicators.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746
G-1159; T.C. A12EA	SA726EA	Installation of seat track reinforcement conference table grouping.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA733EA	installation of intercostals between fuselage station 297 to fuselage station 306-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA734EA	Long range under floor oxygen cylinder installation. Amended 7/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA735EA	Installation of divan base aft support/attachment at fuselage station 460-1/4.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA748EA	Installation of skyphone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA749EA	Installation of combined divan-bunk on right hand side of aircraft between fuselage station 183 and fuselage station 255. Issued 4/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA750EA	Installation of seat track extension. Issued 4/16/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA758EA	Installation of partial bulkhead and door at fuselage station 182. Amended 11/19/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA759EA	Installation of bulkhead attachment. Amended 8/22/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA760EA	Installation of bulkhead and bulkhead door at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA761EA	Installation of bulkhead at fuselage station 448. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA763EA	Installation of Litton LTN-51 inertial navigation system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA777EA	Installation of bulkhead at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA778EA	Installation of bulkhead at fuselage station 459.5. Amended 8/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA779EA	Installation of Custom Products Model 400-21 three place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA783EA	Installation of Electronic Resources Skyphone (UHF) antenna 10-222-04880.	EA	12500	Atlantic Aviation Corporation Wilmington, DE 19899 P.O.
G-1159; T.C. A12EA	SA789EA	Installation of two-place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA790EA	Installation of bulkhead and door at fuselage station 507.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA806EA	Installation of Atlantic Aviation Corporation's retractable seat-GII and refreshment cabinet.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	ST874SO	Installation of Collins ground proximity warning system. Issued 12/15/75.	SO	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-1159; T.C. A12EA	ST888SO	Installation of Litton "Digiprox" ground proximity warning system. Issued 3/9/76.	SO	51502	Litton Systems, Inc. 6065 Roswell Road N.E. Suite 305B Atlanta, GA 30328
G-1159; T.C. A12EA	SA937SW	Crew jump seat.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA940SW	Micronair AU-3000 spray units.	EA	39540	Grumman Aircraft Engineering P.O. Box 147 Elmira, NY 14901
G-1159; T.C. A12EA	SA941SW	Collins HF communication system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA942SW	Collins AL-101 radio altimeter.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA943SW	Dual Sperry SPI-73 integrated flight system, Sperry instrumentation, comparator monitor and dual Sperry C11E compass system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA945SW	Litton LTN51 inertial navigation system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA946SW	Update Sperry 2587400-274 air data computer.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA948SW	Increase of DC output capabilities for APU TR unit.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA951SW	Passenger oxygen system and supplemental (long range) oxygen supply.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA957EA	Installation of modular berthable 1 or 2 place side-facing seat. Issued 7/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA970EA	Installation of Fairchild cockpit voice recorder Model A100 and A151 control unit. Issued 11/26/73.	EA	07498	AiResearch Aviation Company Islip MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA996EA	Installation of Shaw Aero fuel filler cap P/Ns 457-2, -266, -370, 431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
G-1159; T.C. A12EA	ST998SO	Installation of Bendix ground proximity warning system. Amended 8/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA1036SW	Bendix ALA-51A radio altimeter.	SW	12259	Associated PAdio Service Company P.O. Box 20716 Dallas, TX 75220
G-1159; T.C. A12EA	SA1037SW	Emergency lights and battery.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1060EA	Installation of a single or dual Delco Electronics Carousel IV-A inertial navigation system with computer program, P/N 7881711-006. Reissued and amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1061EA	Installation of a dual Collins ALT-55B radio altimeter system. Amended 12/23/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA1062EA	Installation of a Sperry air data computer, Intercontinental Dynamics Co. (IDC) servo altimeters and mach. Amended 12/28/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA1063EA	Installation of a dual Collins flight director system, Model FD-109Y. Amended 1/23/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. 4/30/79	SA1068SO	Installation of Intercontinental Dynamics Corp. radio/barometric altimeter with voice terrain advisory and Sperry mini air data computer. Issued 4/30/79.	SO	39725	Gulfstream American Corporation P.O. Box 2206 Savannah, GA 31402
G-1159; T.C. A12EA	SA1070EA	Installation of dual Litton LTN-72R navigation system. Reissued and amended 4/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1093SW	Decca loran system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1139EA	Installation of a dual or single Global GNS-500A VLF/Omega navigation system. Amended 10/10/79.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1157EA	Replacement of Garrett AiResearch GTCP-36-6 APU with Solar T-62T-40C2 APU. Amended 10/5/79.	EA	73275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
G-1159; T.C. A12EA	SA1186EA	Installation of an Eldec Corp. digital fuel flowmeter and totalizer system. Issued 2/22/80.	EA	10135	Amerada Hess Corporation Mercer County Airport P.O. Box 7385 West Trenton, NJ 08628
G-1159; T.C. A12EA	SA1187EA	Installation of a single Litton LTN-211 Omega/VLF navigation system. Issued 3/17/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1197EA	Installation of a single Litton LTN-72 inertial navigation system. Issued 5/30/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1250SW	Decca type 72 doppler radar system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1251SW	Decca omni-trac system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1336SW	Installation of pressure refueling control system. Issued 7/8/71.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1423SW	Electrical wiring feed thru Station 580. Issued 1/24/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1447SW	Battery fault warning system. Issued 9/18/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1480SW	Installation of FD-109F flight director, INS-61B inertial navigation system, Bendix ALA-51 radio altimeter. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA1481SW	Installation of cockpit control for center point refueling system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourne Avenue Burbank, CA 91505
G-1159; T.C. A12EA	SA1496SW	Tramm BTI-600 battery temperature indicating system. Issued 7/31/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA1553SW	Dual Collins INS-61B inertial navigation units. Issued 11/15/72.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1613SW	BKM master warning interface device between master warning control panel and aircraft inputs. Issued 3/1/73.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA1697SW	Avionics cooling fan. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1698SW	Oxygen service installation. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1633WE	Installation of jump seat in cockpit.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1634WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1654WE	Installation of passenger oxygen continuous flow system.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1683WE	Installation of passenger oxygen system.	WE	07500	AiResearch Aviation Company 6021 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1756WE	Installation of an aircraft integrated weight and balance system (STAN).	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1757WE	Installation of United Control flight data recorder.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1769WE	Installation of Sonotone Battery Model No. 989074-1 and battery container.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1771WE	Installation of SD1 Hoskins anti-collision light system. Amended 11/28/73.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
G-1159; T.C. A12EA	SA1772WE	Installation of United Control speed command system. Amended 6/19/70.	NW	80685	United Control Corporation Overlake Industrial Park Redmond, WA 98052
G-1159; T.C. A12EA	SA1800WE	Installation of radio rack and placards only for avionic components between fuselage stations 181-193 RH.	WE	63750	Qualitron Aero, Inc. Lockheed Air Terminal 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1814WE	Rain repellent system installation. Amended 10/25/73.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-1159; T.C. A12EA	SA1817WE	Installation of Sperry ATS-500 autothrottle system.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1819WE	Installation of doppler antenna and mount for doppler receiver and transmitter.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1848WE	Installation of Custom Products Model 1875 jump seat on radio rack.	WE	62105	Pacific General Corporation 3210A Winona Burbank, CA 91502
G-1159; T.C. A12EA	SA1868WE	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system.	SO	15475	Bendix Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA1889WE	Installation of Sperry SP-50G automatic flight control system, Sperry SPI-73E integrated instrument system and Sperry ATS-500 automatic throttle system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation P.O. Box 2529 Phoenix, AZ 85027

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA1898WE	Installation of Litton Model LTN-51 inertial navigation system. Amended 7/9/69.	WE	51500	Litton Systems, Inc. Guidance & Control Systems Division 5500 Canoga Avenue Woodland Hills, CA 91364
G-1159; T.C. A12EA	SA1983WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2016WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2165WE	Installation of altitude preselect and alerting system (SP-50G Altitude Preselect System). Issued 7/8/70.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
G-1159; T.C. A12EA	SA2184WE	Installation of dual AC Carousel IV inertial navigation system. Amended 10/23/79.	GL	37810	General Motors Corporation A.C. Electronics Division Milwaukee, WI 53201
G-1159; T.C. A12EA	SA2234SW	Passenger continuous flow oxygen system. Issued 8/15/75.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2235SW	Dual Collins 61B inertial systems. Issued 8/15/75.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2237SW	BKM specific range computer. Issued 8/26/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2270SW	Manufacture and install a divan. Issued 11/7/75.	SW	11890	Associated Air Center Box 20718 - Love Field Dallas, TX 75220
G-1159; T.C. A12EA	SA2277SW	Continuous flow, low pressure oxygen system. Issued 12/10/75.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2366SW	Lighted speed brake handle. Issued 10/6/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2387SW	Dual Litton LTN-72R area navigation system. Issued 11/27/76.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2407SW	Install HF antenna on tail cone. Issued 2/11/77.	SW	36600	Foxtronics, Inc. P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA2430WE	Installation of dual Collins INS-61B inertial navigation system. Reissued 11/29/71.	CE	24250	Collins Radio Company 855 35th Street Cedar Rapids, IA 52406
G-1159; T.C. A12EA	SA2512WE	Relocation of speed-logic control unit of GTCP36-6 turbine auxiliary power unit and mounting provisions for spare speed-logic unit. Issued 5/12/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2592WE	Installation of auxiliary taxi light system. Issued 9/1/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2593WE	Installation of Dorne and Margolin DMN 4-15 antenna (VOR/localizer) is installed in vertical stabilizer. Amended 11/9/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2757WE	Installation of crew oxygen regulator and mask assemblies. Issued 9/7/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2797WE	Installation of wing tip mounted emblem lights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
G-1159; T.C. A12EA	SA2807WE	Installation of dual GAMMA I (SFN-2610) inertial navigation systems. Amended 6/28/74.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2907SW	Pitot head indicating system. Issued 1/30/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA2965WE	Installation of dual GAMMA I inertial navigation systems. Issued 1/16/75.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2995SW	Global GNS-500A VLF Omega navigation system. Issued 5/10/79.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA3089WE	Installation of 104006 computer program in LTN-104 ANS. Issued 10/1/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
G-1159; T.C. A12EA	SA3223WE	Installation of Garrett AirNAV 100 or 200 or 300 area navigation system. Amended 8/29/80.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3288WE	Installation of Canadian Marconi vertical scale engine instruments. Issued 10/22/76.	WE	30000	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3302WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 9/17/76.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3370WE	Installation of dual ONTRAC III VLF/OMEGA navigation system. Issued 12/1/77.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3399WE	Installation of a single or dual Litton LTN-72R INS/RNAV navigation system. Amended 7/11/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3600WE	Installation of a single or a dual Delco C-IVA inertial navigation systems. Amended 1/30/80.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3629WE	Installation of either single LTN-51 or LTN-72. Issued 4/14/78.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
G-1159; T.C. A12EA	SA3635WE	Installation of IPECO pilot and co-pilot crew seats. Amended 6/26/79.	WE	54860	Marcon Associates, Inc. 18436 Hawthorne Blvd. Suite 212 Torrance, CA 90504
G-1159; T.C. A12EA	SA3636WE	Installation of single Delco Carousel IVA inertial navigation system. Issued 6/22/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3691WE	Installation of Devore Aviation wing tip tank tail cone mounted vertical tail floodlights. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
G-1159; T.C. A12EA	SA3973WE	Installation of equipment racks for the mounting of a radar system. Issued 6/15/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
G-1159; T.C. A12EA	SA4142SW	Door seal pressure gage, P/N 791026-1. Issued 6/16/80.	SW	08225	AirModa, Inc. P.O. Box 29034 Dallas, TX 75229
G-1159; T.C. A12EA	SA4166WE	Installation of oxygen system for passengers and third crew member. Issued 6/12/80.	WE	78490	Tiger Air Service Center 3000 North Clybourn Avenue Burbank, CA 91505
GA-7; T.C. A17SO	SA1425CE	Install King KFC-200 automatic flight control system. Issued 7/14/78.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
GA-7; T.C. A17SO	SA3235SW-D	Mitchell automatic flight system AK634 consisting of Century IV autopilot or AK634FD consisting of Century IV flight director autopilot with remote annunciator. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3236SW-D	Mitchell automatic flight system AK634 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3238SW-D	Mitchell command electric trim AK637. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

HELIO AIRCRAFT, LTD.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H-250; T.C. 1A8	SA846EA	Installation of PeeKay Model 3500A amphibious floats. Issued 10/12/70.	EA	63626	PeeKay Aircraft Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
H-250; T.C. 1A8	SA867EA	Installation of Aerofab TSO C27 PeeKay Model B3500. Issued 3/19/71.	EA	29998	PeeKay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
H-250, H-295; T.C. 1A8	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
H-250, H-295; T.C. 1A8	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
H-250, H-295, H-391, H-391B, H-395, H-395B; T.C. 1A8	SA547SW	AK177 automatic pilot, AK123 lateral guidance radio coupler, and AK178 automatic trim.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-391, H-395; T.C. 1A8	SA354SO	Aft cabin door removed.	SO	27245	Vernon L. Crouch 2564 Alandale Drive Macon, GA 31201
H-250, H-295, H-391, H-395; T.C. 1A8	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
H-250, H-295, H-391, H-395; T.C. 1A8	SA1087SO	Installation of Brownline seat. Issued 7/6/79.	SO	47390	Jungle Aviation and Radio Service, Inc. P.O. Box 248 Waxhaw, NC 28173
H-250, H-295, H-391, H-395, H-395A; T.C. 1A8	SA1112WE	Sling-type passenger seat.	NW	75600	Stolairco, Inc. 6660 Perimeter Road S. Boeing Field Seattle, WA 98108
H-250, H-295, H-391, H-395, H-395A; T.C. 1A8	SA1491WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA1590CE	Modification of main spar carry-thru assembly. Issued 5/30/80.	CE	17120	Clarence H. Brent Box 486 Pittsburg, KS 66762
H250, H295, H391B, H395; T.C. 1A8	SA916SO	Installation of Cessna seat rails and seats. Issued 1/13/77.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H250, H295, H391B, H395; T.C. 1A8	SA917SO	Installation of cargo door.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA179AL	Installation of Airglas wheel skis. Amended 4/28/67.	NW	75600	Stolairco, Inc. 6660 Perimeter Road S. Boeing Field Seattle, WA 98108
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA218AL	Main gear shock strut restrictor.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA234AL	Installation of Goodyear 30 x 13 x 6 main gear tires. Revised 6/30/69.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H250, H295, H395; T.C. 1A8	SA2381SW	Modification of main landing gear assembly, P/N 250-040-451, by addition of gussets at intersection of drag brace and main leg. Issued 11/15/76.	SW	30230	Dodd Engineering & Welding 3302 North Lewis Tulsa, OK 74110
H-250, H-295, H-395; T.C. 1A8	SA3247SW-D	Mitchell automatic flight system AK618 consisting of Century IIB autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-395, H-395A; T.C. 1A8	SA3244SW-D	Mitchell automatic flight system AK614, consisting of Century III autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H250, H-295, H-395, H-395A; T.C. 1A8	SA3245SW-D	Mitchell automatic flight system AK615, consisting of Century IIB autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-395, H-395A; T.C. 1A8	SA3246SW-D	Mitchell automatic flight system AK617 consisting of Century III autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-391, H-395A, H-391B, 500; T.C. 1A8, A2EA	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
H-250, H-391, H-395A, H-391B, 500; T.C. 1A8, A2EA	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 10/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
H-250, H-395A, H-395B; T.C. 1A8	SA1389CE	Install tailwheel yoke assembly to accommodate a Cleveland 600 x 6 wheel and either 600 x 6, 700 x 6 or 800 x 6 tires. Issued 12/15/77.	AL	90130	William G. Zaegel P.O. Box 3464 Anchorage, AK 99501
H-295; T.C. 1A8	SA860SW	Mitchell automatic flight system AK256 consisting of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76106
H-295; T.C. 1A8	SA1399SW	Installation of tricycle landing gear. Amended 5/17/78.	CE	42000	Helio Aircraft Limited Box 604 Pittsburg, KS 66762
Helio H-295; T.C. 1A8	SA1589CE	Increase gross weight. Issued 5/30/80.	CE	17120	Clarence H. Brent Box 486 Pittsburg, KS 66762

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H-295; T.C. 1A8	SA1601CE	Installation of TFC engine and cabin fire extinguisher system. Issued 10/23/80.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
H-295 (USAF U-10D); T.C. 1A8	SA2136WE	Installation of Tritan amphibious float Model TA 3500. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Box 464 Gardner Municipal Airport Gardner, MA 01440
H295, H-391, H395; T.C. 1A8	SA987SO	Removal of the Leece-Neville generator and voltage regulator and installation of a JASCO alternator kit 6565-1. Amended 11/8/79.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H-295, H-391, H-395; T.C. 1A8	SA1086SO	Installation of stowable co-pilot's rudder pedals. Amended 8/30/79.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H-295, -391B; T.C. 1A8	SA2666WE	Ceconite 102 material covering of ailerons. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
H-295, H-395; T.C. 1A8	SA900WE	Installation of turbosupercharged Lycoming GO-480-F2D6 engine. Amended 5/20/70.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
H-295, H-395; T.C. 1A8	SA1592WE	Installation of automatic fuel mixture control. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
HT-295; T.C. 1A8	SA35RM	Installation of Bendix FCS-810 autopilot, a trim adapter and Bendix HSD-830 compass. Amended 3/20/78.	RM	05940	Aircraft Radio & Accessory Company, Inc. Hangar No. 1 Stapleton Int'l Airport Denver, CO 80207
H-391, H-391B, H-395, H-395A; T.C. 1A8	SA204WE	B2D autopilot. Amended October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
H-391B; T.C. 1A8	SA709WE	Ceconite 101 covering of ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
H-391B; T.C. 1A8	SA731CE	Installation of Edo 582-3430 floats.	NE	47270	Frank Joy Cape Cod Aeromarine Box 398 Orleans, MA 02653
H-391B; T.C. 1A8	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
H-391B, H-395, H-395A; T.C. 1A8	SA235AL	Installation of modified oleo shock strut.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H-391B, H-395A; T.C. 1A8	SA152AL	L J 2800 floats.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 1254 Anchorage, AK 99502
H-395; T.C. 1A8	SA125SO	Turbocharger GO-480-G1D6 engine.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
H-395; T.C. 1A8	SA156SO	Turbocharged Lycoming GO-480-G1D6 engine.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
H-395; T.C. 1A8	SA393CE	Lycoming GO-480-G1D6 engine and Hartzell HC-B3Z-20-1/101510-5 propeller.	CE	42000	Helio Aircraft Limited P.O. Box 604 Pittsburg, KS 66762
H-395; T.C. 1A8	SA490SW	Turbocharger. Reissued 4/6/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
H-395; T.C. 1A8	SA1213CE	Installation of EDO 582-3430 floats. Issued May 1976.	AL	75095	Stephens Bros. Plumbing, Inc. 7339 Arctic Boulevard Anchorage, AK 99502
H-395; T.C. 1A8	SA1467CE	Increase in maximum gross weight from 3,000 lbs. to 3,300 lbs./ modification and kit installation instructions. Issued 12/28/78.	CE	17120	Clarence H. Brent P.O. Box 486 Pittsburg, KS 66762

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H-395; T.C. 1A8	SA1696WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
500; T.C. A2EA	SA104SO	Swearingen combustion monitor. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
500; T.C. A2EA	SA305SO	Lycoming IO-540-C2C engines, 315A10 Rajay turbochargers and modified fuel system. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
500; T.C. A2EA	SA459CE	Models C4200A and 1800 skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
500; T.C. A2EA	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
HST-550; T.C. A4EA	SA615SW	AK213 stabilizer and AK214 pitch trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
HST-550; T.C. A4EA	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by STC SA615SW.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

JOBMASTER COMPANY

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Howard DGA-11, Howard DGA-15P, DGA-15J, DGA-15W; T.C. 672, 717	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
DGA-15J, -15P; T.C. 717	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
DGA-15J, DGA-15P, DGA-15W; T.C. 717	SA4-876	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DGA-15J, -15P, -15W; T.C. 717	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
DGA-15P; T.C. 717	SA3-715	Remove cabin door.	CE	34625	Corbett H. Fasching 214 E. Colorado St. Joseph, MO 64501
DGA-15P; T.C. 717	SA3-716	Hartzell 3-bladed propeller HC-B3Z30-2E/10152-5-1/2 or HC-093Z30-2E/10152-5-1/2 with 836-16R spinner on aircraft with Pratt & Whitney R-985-AN-6 engine.	GL	56826	Maxwell Aircraft Service, Inc. Crystal Airport Minneapolis, MN 55428
DGA-15P; T.C. 717	SA4-20	BT-13 cowling and mounting brackets.	WE	84397	Jay Waldren 716 Arvin Street Bakersfield, CA 93300
DGA-15P; T.C. 717	SA4-887	Tricycle landing gear with either fixed or retractable nose gear and/or modified vertical stabilizer.	CE	77140	Elro M. Swindle 132 Denver Street Salina, KS 67401
DGA-15P; T.C. 717	SA4-1283	Ceconite 103 covering of plywood components.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DGA-15P; T.C. 717	SA1NW	Installation of EDO Xa5400 floats. Issued 7/18/72.	NW	46400	Jobmaster Company, Inc. 1005 West Perimeter Road Renton, WA 98055
DGA-15P; T.C. 717	SA27CE	Removal of door.	CE	77140	Elro M. Swindle 132 Denver Street Salina, KS 67401
DGA-15P; T.C. 717	SA170WE	Removal of cabin door for parachute jumping and aerial photography operations.	WE	14804	Homer J. Barry 826 Linda Vista Drive Banning, CA 92220
DGCA-15P; T.C. 717	SA1008WE	Poly-fiber covering of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Coatings 43rd South Fort Drive P.O. Box 3084 Riverside, CA 92519

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

LAISTER-KAUFFMAN AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
LK-10A Series; G.T.C. 15	SG4-741	Bubble canopies over each cockpit and change in configuration of vertical and horizontal tail.	WE	86204	John W. Williams 1986 Galveston San Diego, CA 92101
LK-10A Series; G.T.C. 15	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
LK-10A Series; G.T.C. 15	SG4-1230	Ceconite 101 covering of complete glider.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
LK-10A Series; G.T.C. 15	SG4-1411	Ceconite 103 covering of glider.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
LK-10A Series; G.T.C. 15	SG10WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 103 material. Amended 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
LK-10A Series; G.T.C. 15	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
LK-10A; G.T.C. 15	SA2666WE	Ceconite 102 material covering complete glider. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
LK-10A, -10B; G.T.C. 15	SG4-1240	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
LK-10A, -10B; G.T.C. 15	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329-23A, -23D, -23E; T.C. 2A15	SA3563WE	Installation of Eldec engine fuel flow and totalizer system. Issued 2/22/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3704WE	Installation of single or dual Litton LTN-211 Omega Navigation System. Amended 8/27/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA2943WE	Installation of recognition lights on horizontal stabilizer upper surface. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3206WE	Installation of Garrett AirNav 100 or 200 or 300 area navigation system. Amended 8/29/80.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3372WE	Installation of single or dual ONTRAC III VLF/Omega navigation systems. Amended 5/13/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3390WE	Installation of Global Model GNS-500A VLF/Omega navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3391WE	Installation of Delco C-IVA inertial navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3572WE	Installation of Sperry TERN-100 area navigation system. Issued 2/14/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -25; T.C. 2A15	SA3520WE	Installation of Sperry SPZ-500 autopilot and Sperry SPI-80/81 flight directors. Issued 11/23/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23D; T.C. 2A15	SA928EA	Installation of battery isolation circuit. Issued 7/14/72.	EA	70580	Scott Paper Company Scott Plaza Philadelphia, PA 19113
1329-23D; T.C. 2A15	SA931EA	Installation of battery isolation system. Issued 8/24/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
L1329-23E; T.C. 2A15	SA116GL	Installation of Global GNS-500A VLF/OMEGA navigation system. Amended 3/2/78.	GL	61880	Onan Corporation 1400 - 73rd Avenue, Northeast Minneapolis, MN 55432
1329-23F; T.C. 2A15	SA1989WE	Installation of United Control approach speed system, computer P/N 965-0158-001. Reissued 8/26/70.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA455GL	Installation of a Collins LRN-80 Omega navigation system. Issued 10/28/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Indianapolis, MN 55450
1329-25; T.C. 2A15	SA1049EA	Installation of seat tracks and cabin decks. Issued 6/7/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329-25; T.C. 2A15	SA1052EA	Installation of Solar gas turbine auxiliary power unit T-62T-40C. Amended 3/12/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
1329-25; T.C. 2A15	SA1056EA	Installation of a speed command of attitude and thrust system (SCAT). Amended 7/19/79.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA1581CE	Modification of aircraft to incorporate a fuel management computer. Issued 4/1/80.	CE	24540	Colt Electronics Company 15301 West 109th Street Lenexa, KS 66219
1329-25; T.C. 2A15	SA2920SC	Installation of BKM pitot heat monitor system. Issued 2/28/79.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329-25;	SA2976SW	Floor plan arrangement, floorboards and seat track. Issued 4/13/79.	SW	47632	K-C Aviaiton, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2977SW	Pressurized water system lavatory, commissary, and bar. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329-25; T.C. 2A15	SA2979SW	Flushing toilet with outside servicing capabilities. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2980SW	Galley component assembly. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2981SW	Baggage compartment modification aft cabin, station 547.5 to 567.0. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2982SW	Baggage compartment modification, station 240.0 to 310.0, right side. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2983SW	Cabin entry ramp, center aisle, station 284.0 to 328.0.	SW	47632	K-C Aviation 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA3297WE	Installation of GTCP 30-92C auxiliary power unit. Issued 1/21/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-25; T.C. 2A15	SA3324WE	Installation of a single point refueling system for Lockheed Jetstar airplane. Issued 1/17/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-25; T.C. 2A15	SA3371WE	Installation of Teledyne angle of attack system. Issued 3/10/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
382; T.C. A1SO	SA3793WE	Installation of Tracor 7640A ONS. Issued 2/2/79.	WE	79200	Transinternational Airlines Engineering Department P.O. Box 2504 Oakland International Airport Oakland, CA 94164
382, 382B; T.C. A1SO	ST427SO	Installation of cargo rail system Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382, 382B, 382E; T.C. A1SC	SA733CE	Installation of cargo pallets.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382, 382B, 382E, 382F, 382G; T.C. A1SO	SA1625WE	Pallet assembly provisions per FAA Sealed L.A.S. Top Drawing 4035910 as modifying aircraft with four KC-97, 1800 gallon tanks installed in accordance with STC SA889WE. Amended 2/23/77.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
382, 382B, 382E, 382G; T.C. A1SO	ST400SO	Installation of palletized cargo loading and restraint system. Amended 11/25/74.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382, 382B, 382E, 382G; T.C. A1SO	ST407SO	Installation of palletized cargo loading and restraint system. Amended 4/7/72.	SO	52020	Lockheed-Georgie Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA303AL	Installation of 4000 gallon steel tank in the cargo compartment.	AL	44045	Interior Airways, Inc. P.O. Box 3029 Fairbanks, AK 99701
382B; T.C. A1SO	SA368SO	Palletized cargo loading system. Amended 7/10/67.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA374SO	Palletized cargo loading system per Lockheed Industrial Products top assy. dwg. 256-000. Amended 7/25/69.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA1274WE	Triple seat/bunk. Amended 7/10/67.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98109
382B, 382E, 382G; T.C. A1SO	ST401SO	Installation of palletized cargo loading and restraint Amended 11/25/74.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B, 382E, 382G; T.C. A1SO	ST527SO	Installation of inplane cargo system in accordance with Aeronautical Engineers, Inc. dwgs. AE2178 & AE2178, Change "C". Reissued 2/13/73.	SO	73870	Southern Air Transport, Inc. P.O. Box 1266 International Airport Miami, FL 33148

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
382B, 382E, 382G; T.C. A1SO	SA569AL	Installation Collins FPC-75 ground proximity warning system. Issued 11/25/75.	AL	08488	Alaska International Air, Inc. P.O. Box 60029 Fairbanks, AK 99701
382E; T.C. A1SO	SA2461WE	Installation of Sorm bulk liquid cargo tank assembly SI-3100. Issued 12/17/71.	NW	73820	Sorm Industries 7999 Perimeter Road, South Seattle, WA 98108
382E; T.C. A1SO	SA3171WE	The auxiliary power unit Model GTC 85-71 located in the forward end of the left hand main landing gear wheel well fairing has been replaced by an AiResearch Gas turbine compressor Model GTCP 85-98CK(A). Issued 4/9/76.	WE	87450	World Airways, Inc. Maintenance & Engrg. Center Oakland International Airport Oakland, CA 94614
382E, 382G; T.C. A1SO	SA1156SO	Installation of dual Litton, LTN-211, Omega navigation system (ONS). Issued 7/3/80.	SO	73870	Southern Air Transport, Inc. P.O. Box 52-4093 International Airport Miami, FL 33152
382E, 382G; T.C. A1SO	SA2418WE	Installation of cargo loading system. Issued 9/29/71.	WE	70258	Saturn Airways, Inc. P.O. Box 2426 Oakland International Airport Oakland, CA 94614
382E, 382G; T.C. A1SO	SA3144WE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/9/76.	WE	68770	Rockwell International Corp. Collins Radio Group 750 S. Douglas Street El Segundo, CA 90245
382G; T.C. A1SO	ST913SO	Installation of six 24" x 36" plug type doors in cargo compartment walls. Issued 12/1/76.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G; T.C. A1SO	SA1056SO	Increase in zero fuel weight from 126,790 lbs. to 128,790 lbs. with pylon tanks on and 125,000 lbs. to 127,000 lbs. without pylon tanks. Issued 3/23/79.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G; T.C. A1SO	SA2912WE	Installation of palletized dual LTN-51 INS or dual LTN-72 INS or combination of either. Amended 9/26/74.	WE	51500	Litton Systems, Inc. Aero Product Division 21050 Burbank Blvd. Woodland Hills, CA 91364
382G; T.C. A1SO	SA2929WE	Installation of palletized dual LTN-51 or dual LTN-72 INS or combination of either. Issued 10/2/74	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91364

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

LUSCOMBE AIRCRAFT CORP., GEORGIA

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
8 Series; T.C. 694	SA1-271	Metal skin on wings.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047
8 Series; T.C. 694	SA4-173	Lycoming O-235-C1 or O-290-D engine in Model 8E or T8F landplane and Lycoming O-320 engine in Model 8E or 8F landplane.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
8 Series; T.C. 694	SA4-290	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
8 Series; T.C. 694	SA4-430	Metal wing covering.	WE	05600	Aircraft Modification and Repair Municipal Airport Hayward, CA 94541
8 Series; T.C. 694	SA4-463	New exhaust stack crossover tube with standard bend radius of 5.0 inches.	RM	81060	Universal Aircraft Ind. P.O. Box 5306 Terminal Annex Denver, CO 80217
8 Series; T.C. 694	SA4-503	New exhaust stacks.	RM	81060	Universal Aircraft Ind. P.O. Box 5306 Terminal Annex Denver, CO 80217
8 Series; T.C. 694	SA4-560	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. Oxnard-Ventura Airport Oxnard, CA 93030
8 Series; T.C. 694	SA4-642	Lycoming O-290-D2 engine and Sensenich M76AM-2 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
8 Series; T.C. 694	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
8 Series; T.C. 694	SA4-874	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Co. P.O. Box 3428 Van Nuys, CA 91408
8 Series; T.C. 694	SA4-1346	Fiberglass covering of aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
8 Series; T.C. 694	SA4-1443	Eonite covering of wings.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
8 Series; T.C. 694	SA4-1515	Retractable wheel fairings.	WE	30708	Duce Aircraft Co. Route 1, Box 711 Valley Center, CA 92082
8 Series; T.C. 694	SA87CE	Dorsal fin. Issued 6/24/70.	XX	67540	Kenneth Reuterskiold (Address Unknown)
8 Series; T.C. 694	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
8 Series; T.C. 694	SA150CE	Removal of right door, right control stick, and right door catch.	GL	84846	Carl C. Webb P.O. Box 217 Flora, IL 62839
8 Series; T.C. 694	SA317WE	Full flow filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
8 Series; T.C. 694	SA337SW	Door removed.	SW	26710	James E. Cox 2113 Bingle Road Houston, TX 77055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
8 Series; T.C. 694	SA344CE	Lycoming O-320 or O-320-A1A engine, McCauley 1C172/MGM 7462 propeller and Prestolite ALK 5001 S4UO alternator. Reissued 8/13/69.	SC	52580	Luscombe Aircraft Corporation 3201 Cains Hill Place, N.W. Atlanta, GA 30305
8 Series; T.C. 694	SA509WE	Removal of door for parachute jumping and aerial photography operations.	WE	48512	Geza Kiss 9017 Birchleaf Avenue Downey, CA 90240
8 Series; T.C. 694	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
8 Series; T.C. 694	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
8 Series; T.C. 694	SA1008WE	Poly-Fiber covering of both wings. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92402
8 Series; T.C. 694	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
8 Series; T.C. 694	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
8, 8A, 8B, 8C, 8D, 8E, 8F; T.C. A-694	SA2715WE	Installation of carry-through spar beams. Amended 8/28/73	WE	39355	William J. Gratrix P.O. Box 8217 Airport Station San Francisco, CA 94128
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA69NW	Installation of Matney's engine charge air - air filter assembly. Amended 10/8/74.	NW	56600	D. H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA489EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred P. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
8, 8A, B, C, D, E, F, T8F; T.C. 694	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
8, 8A, 8B, 8C, 8D, 8E, 8F, T-8F; T.C. 684	SA2666WE	Ceconite 102 material covering of wings. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
8, 8A, 8C, 8E, 8F, T8F; T.C. 694	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/30/70.	RM	40500	Hanna-Aero Corporation 5222 Holly Street Littleton, CO 80120
8B; T.C. 694	SA201GL	Installation of Sensenich 74CK propeller in lieu of original fixed pitch wood propeller using special bolts supplied by the propeller manufacturer. Issued 11/10/77.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
8E Landplane; T.C. A694	SA379GL	Installation of a Lycoming O-235-C2C engine, fiberglass cowling and miscellaneous modifications. Issued 1/4/80.	GL	61752	Dewey G. Norton 1351 Manton Boulevard Canton, MI 48187
8E or 8F Landplane; T.C. 694	SA229GL	Installation of Lycoming O-235-C1, O-235-C1C, O-235-C2A, O-235-C2B or O-235-C2C. Issued 3/16/78.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
8E or 8F; T.C. 694	SA230GL	Installation of single piece front and lower cowl. Amended 4/10/78.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MARTIN-MARIETTA CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
202, 202A; T.C. 795	SA1-560	2010X Series readome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
202, 202A; T.C. 795	SA5SO	B-300 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
202, 202A; T.C. 795	SA174EA	Cabin interior modification for cargo configuration.	EA	09520	Allegheny Airlines Greater Pittsburgh Airport Pittsburgh, PA 15231
202, 202A, 404; T.C. A-795, 1A7	SA107CE	High intensity wing tip lights, tail light, with or without high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
202, 202A, 404; T.C. A-795, 1A7	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
202, 202A, 404; T.C. A-795, 1A7	SA1744WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
202, 202A, 404; T.C. 795, 1A7	SA2666WE	Ceconite 102 material covering on rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
202, 404; T.C. 795, 1A7	SA4-153	Oil filter 30816A with CP-1438-0 element.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
202, 404; T.C. 795, 1A7	SA4-501	Engine mount core assemblies.	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
202, 404; T.C. 795, 1A7	SA4-525	Engine mount core 106-1F and 106-1J.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
202, 404; T.C. 795, 1A7	SA4-568	Engine mount core assemblies DE1468.	WE	30500	Dow-Elco, Inc. 1313 W. Olympic Boulevard Montebello, CA 90640
202, 404; T.C. 795, 1A7	SA375WE	Ceconite 101 covering of rudder.	WE	26240	Cooper Engineering Co. P.O. Box 3428 Van Nuys, CA 91408
404; T.C. 1A7	SA1-524	2010X Series radomes.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
404; T.C. 1A7	SA1-528	1010 Series radomes.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
404; T.C. 1A7	SA3-402	Floor modification, swivel seat installation, and divan seat belt installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
404; T.C. 1A7	SA3-403	Installation of Bendix RDR-1 weather radar system, radome and relocation of airspeed pitot. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
404; T.C. 1A7	SA3-404	Installation of Sperry SP20 autopilot. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
404; T.C. 1A7	SA3-405	Installation of APU - Lawrence Model 30D. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
404; T.C. 1A7	SA3-418	Installation of cockpit and general cabin arrangement and furnishings. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
404; T.C. 1A7	SA4-949	Auxiliary power plant.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
404; T.C. 1A7	SA4-950	Sperry A-12 autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
404; T.C. 1A7	SA4-951	Furniture.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
404; T.C. 1A7	SA4-952	Radome and structure.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
404; T.C. 1A7	SA4-953	Outer wings modified for integral type fuel tanks.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
404; T.C. 1A7	SA4-1042	Passenger seating capacity increased to 44.	WE	62070	Pacific Air Lines, Inc. San Francisco Inter'l. Airport San Francisco, CA 94119
404; T.C. 1A7	SA4-1124	Taran II demonstration weather radar system.	WE	43330	Hughes Aircraft Company Culver City, CA 90230
404; T.C. 1A7	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
404; T.C. 1A7	SA4-1220	Sperry A-12 autopilot system.	SO	78390	Tempo Design Corporation P.O. Box 456 Miami, FL 33148
404; T.C. 1A7	SA4-1221	Radome and radar antenna.	SO	78390	Tempo Design Corporation P.O. Box 456 Miami, FL 33148
404; T.C. 1A7	SA4-1229	Two 15KS-1000-A1 aircraft rocket engines.	WE	02315	Aerojet-General Corporation 6352 N. Irwindale Avenue Azusa, CA 91702
404; T.C. 1A7	SA4-1615	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
404; T.C. 1A7	SA64SO	D-300 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
404; T.C. 1A7	SA84WE	Sperry A-12 autopilot.	EA	61242	National Supply Company Allegheny County Airport Dravosburg, PA 15034
404; T.C. 1A7	SA97EA	Conversion to executive interior.	SO	31370	East Coast Flying Service, Inc. P.O. Box 18007 Imerson Airport Jacksonville, FL 32201
404; T.C. 1A7	SA258SO	Immersion heaters in oil tanks 404-2055010 for ground operation only.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA259SO	BMEP bleed system for R-2800CB-3 engines.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA260SO	Swivel seat intercostals at Station 616.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA261SO	Direct pressure actuated manifold pressure gage system.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA268SO	Manufacture replacement parts for Adel AD224278.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA276SO	J & H G-29-7BT generators.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
404; T.C. 1A7	SA322SO	(1) Installation of 44-seat interior, (2) rearrange 44-seat interior. Aircraft may be modified under either option. Approval of option 2 requires implementation of option 1. Amended 5/10/68.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MAULE AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M-4; T.C. 3A23	SA316SO	Installation of carburetor ice detector.	SO	71545	Charles B. Shivers, Jr. 8929 Valleybrook Road Birmingham, AL 35206
M-4; T.C. 3A23	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
M-4; T.C. 3A23	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Bee Dee M-4, M-4; T.C. 3A23	SA273WE	Vacuum system 121A.	WE	40689	Harms Industries P.O. Box 3246 Inglewood, CA 90306
M-4, 4C, 4S, 4T, M-4-210, 210C, 210S, 210T; T.C. 3A23	SA222AL	Installation of L-2500A skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
M-4, M-4C, M-4S, M-4T, M-4-210, M-4-210C, -210S, -210T, M-4-220, -220C, -220S, -220T, M-4-180C, M-4-180S, M-4-180T; T.C. 3A23	SA433AL	Installation of Wilbur's tire-cushioned model 2300 skis. Amended 12/16/71.	AL	86070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4, -4C, -4S, -4T, M-4-210, -210S, -210T; T.C. 3A23	SA693SW	AF223 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
M-4, M-4-210; T.C. 3A23	SA258CE	Remove right rear door.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4, M-4-210; T.C. 3A23	SA486CE	Installation of Canadian Aircraft Products, Ltd. Model 62-2000 floats. Amended 7/20/67.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M4, M-4-210, M-4-210C; T.C. 3A23	SA690SW	Wing tips modified.	SW	34900	Harvey J. Ferguson Upper Valley Aviation, Inc. McAllen, TX 79501
M4-4C, -4S, -4T, M-4-210, -210C, -210S, -210T; T.C. 3A23 Applicable only to aircraft modified by STC SA963SW.	SA808SW	Installation of Mitchell Model AF246 omni-tracker.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M-4-210, -5-210C; T.C. 3A23	SA164AL	Installation of auxiliary cabin heater and cowl flaps. Amended 2/10/76.	AL	96070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA589CE	Installation of Fleet Manufacturing, Ltd. Model 2500 floats.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA609CE	Installation of Edo Corp. Model 248A-2440 or Model 248B440 floats. Amended.	SO	56750	Maule Aircraft Corp. Spence Air Force Base Moultrie, GA 31768
M-4-210, M-4-220, M-4; T.C. 3A23	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M-4-210C, -220C, M-5-210, -220C; T.C. 3A23	SA2931WE	Installation of plexiglas covering for two main cabin doors, right passenger door, and baggage door. Issued 9/17/74.	WE	36190	Foothill Aircraft Sales and Service 13th and Benson Upland, CA 91786
M4-220; T.C. 3A23	SA415SO	Installation of Mitchell Century II autopilot. Amended 6/26/69.	SO	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M4-220; T.C. 3A23	SA417SO	Installation of aileron stabilizer and tracker.	SO	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768
M-4-220, M-4-220C, M-4-220S, M-4-220T;	SA610CE	Installation of Edo Corp. Model 248A-2440 or Model 248B-2440 floats. Amended 9/19/69.	SO	56750	Maule Aircraft Corporation Spence Air Force Base Moultrie, GA 31768
M-4, M-5; T.C. 3A23	SA697AL	Installation of main landing gear and tail landing gear wheel skis. Issued 10/14/80.	AL	70365	Richard J. Schneider 20 Malaspina Drive Eagle River, AK 99577
M-4-220C, -5-220C; T.C. 3A23	SA1160SO	Installation of Weldon, P/N 6005-2A, aircraft engine driven fuel pump in lieu of diaphram type pump. Issued 10/3/80.	SO	75840	Stones River Air Service, Inc. Hangar 621, Smyrna Airport Smyrna, TN 37167
M-5-210C, M-5-220C, M-5-235C, M-5-210TC; T.C. 3A23	SA937SO	Installation of aqua Model 2400 floats. Amended 6/20/80.	SO	22776	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
M-5-210C, M-5-235; T.C. 3A23	SA1099SO	Installation of Fiberfloat model 2400 or 2400A floats and modified wing tips. Issued May 1980.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830
M-5-235C; T.C. 3A23	SA1008WE	Installation of poly-fiber covering material of fuselage and empennage. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
M-5-235C; T.C. 3A23	SA1099SO	Installation of Fiberfloat Model 2400 floats and modified wing tips. Issued 9/4/79.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

McCLISH, THOMAS H.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HCLDER
B, B75L, B85C; T.C. 715	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
B, B75L, B85C; T.C. 715	SA4-1231	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Co. P.O. Box 3428 Van Nuys, CA 91408
B, B75L, B85C; T.C. 715	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
B75L, B85C; T.C. 715	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
B75L, B85C; T.C. 715	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carturetors. Amended 10/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
B75L, B85C; T.C. 715	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
B85C; T.C. 715	SA4-302	BH-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-3; T.C. 618, 669	SA4-798	Eonite covering on elevators, rudder and ailerons.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
DC-3; T.C. 618, 669	SA4-1091	Panorama windows.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3; T.C. 618, 669	SA4-1093	Interior furnishings for 12 passengers.	WE	02308	Aero Interiors Company 2940 N. Hollywood Way Burbank, CA 91502
DC-3; T.C. 618, 669	SA4-1099	Panorama picture window.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3; T.C. 618, 669	SA4-1452	Installation of two Aerojet-General 15KS-1000-A1 aircraft rocket engines and certification per SR-426. Reissued 3/10/71.	WE	30000	DeVore Aviation Service Corp. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DC-3; T.C. 618, 669	SA4-1566	Electrically-heated replacement windshield. Reissued 3/22/74.	SO	65025	PPG Industries, Inc. P.O. Box 2200 Huntsville, AL 35804
DC-3; T.C. 618, 669	SAIR-1	Fiberglass landing gear doors.	EU	78705	Transair Limited Croydon Airport Croydon, Surrey, England
DC-3; T.C. 618, 669	SA1CE	Weather radar installation, Collins Model WP-103. Reissued 10/1/71.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA18SW	Carburetor adapter. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
DC-3; T.C. 618, 669	SA68SW	Positive stop in rudder system and geared rudder tab installation.	SW	34000	Executive Aircraft Service P.O. Box 7307 Redbird Airport Dallas, TX 75232
DC-3; T.C. 618, 669	SA111SW	200,000 B.T.U. Janitrol S-200 heater in tail section. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
DC-3; T.C. 618, 669	SA121SW	Jump seat. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
DC-3; T.C. 618, 669	SA127SO	Brownline 20276 seat track.	SO	11900	Associated Aircraft Equipment Company, Inc. P.O. Box 542 Miami, FL 33101
DC-3; T.C. 618, 669	SA130SO	Extension on heater exchanger.	SO	08146	Air International P.O. Box 603 Miami, FL 33159
DC-3; T.C. 618, 669	SA177SO	Fabric attachment clips. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
DC-3; T.C. 618, 669	SA211CE	A.P.U. installation (Ranger Andover Model V-32D-2-1). Reissued 10/1/71.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3; T.C. 618, 669	SA231SW	Two Aerojet-General rocket engines (JATO) (15KS-1000-A1).	SW	44038	Inter-Continental Engine Service P.O. Box 1243 Brownsville, TX 78520
DC-3; T.C. 618, 669	SA340SW	Removal of main cabin passenger door.	SW	28600	Dallas Skydrivers, Inc. 3928 Bryn Mawr Dallas, TX 75225
DC-3; T.C. 618, 669	SA347WE	Aircraft modified for 41 occupants.	WE	57918	Mercer Enterprises Lockheed Air Terminal Burbank, CA 91505
DC-3; T.C. 618, 669	SA474SW	Chairs and floor structure. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aviation Service 7515 Lemmon Avenue Dallas, TX 75209
DC-3; T.C. 618, 669	SA794WE	Substitution of Chobert rivets for rib lacing on elevator.	WE	53780	J.F. McRae's Aero Crafts Building 708, Oakland Airport Oakland, CA 94615

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-3; T.C. 618, 669	SA929WE	Wing flap landing gear aural warning installation.	NW	85122	West Coast Airlines, Inc. Boeing Field Seattle, WA 98108
DC-3; T.C. 618, 669	SA933WE	Flap actuated gear warning system.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l. Airport Los Angeles, CA 90009
DC-3; T.C. 618, 669	SA1274WE	28-volt DC generator with Leland Airborne Products CVS-1105-2 solid state voltage regulator.	WE	69241	R&S Electrical Accessory Service, Inc. 3210 N. San Fernando Boulevard Burbank, CA 91504
DC-3; T.C. 618, 669	SA1275WE	Replacement of carbon pile voltage regulator for a 28-volt DC generator with Leland Airborne Products Type CSV-1105-2 solid state voltage regulator.	WE	13750	Aviation Power Supply, Inc. 3111 Fenwood Street Burbank, CA 91503
DC-3 Series; T.C. 618, 669, 6A2	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
DC-3, Super DC-3; T.C. 618, 6A2	SA4-1002	Alternate fuel source installation in aircraft with approved fuel flowmeter and Wright R-1820 or C9 Series engines.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-3; T.C. 669	SA1-265	JOhns-Manville brake lining Part AB-6512 in Goodrich 14 x 2-3/4 expander tube brake.	EA	46748	Johns-Mansville Sales Corp. 22 East 40 Street New York, NY 10001
DC-3; T.C. 669	SA1-281	12-volt electrical system revised to accept P1 200-ampere generators.	EA	80500	United Air Lines, Inc. National Airport Washington, D.C. 20090
DC-3; T.C. 669	SA1-346	Sierrocote windshield 220-1 and 220-2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DC-3; T.C. 669	SA1-375	Windows.	EA	71905	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
DC-3 Series; T.C. 669	SA1-513	Enrichment of auto lean mixture setting by installing auto lean jet P/N 22244-3000cc in PD-12F13 injection carburetor on Pratt & Whitney R-1830-75 engines.	EA	08375	Airwork Corporation Municipal Airport Millville, NJ 08332
DC-3 Series; T.C. 669	SA3-12	Reclassify aft cargo compartment from Class B to Class A.	GL	61700	Northwest Airlines, Inc. International Airport St. Paul, MN 55111
DC-3 Series; T.C. 669	SA3-23	Hydraulic system fluid reservoir modification.	CE	62030	Ozark Airlines, Inc. P.O. Box 6007 Lambert Field St. Louis, MO 63145
DC-3 Series; T.C. 669	SA3-26	Buffet modification.	GL	49300	Lake Central Airlines Weir Cook Airport Indianapolis, IN 46241
DC-3 SEries; T.C. 669	SA3-45	Two Eclipse 30E-07-11 200-ampere generators and 1589-1D regulators.	GL	37808	General Motors Air Transport Section City Airport, Bay #1 Detroit, MI 48202
DC-3 Series; T.C. 669	SA3-50	Modification of Stewart-Warner Model 940-B24 heater installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-65	Bendix RDR-1 radar antenna ANT-1C installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-68	Alternate landing light installation (Westinghouse 600W seal beam). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
DC-3 Series; T.C. 669	SA3-79	Cowl flap auxiliary actuator and cable assembly.	GL	61732	Northwestern Aeronautical Co. 6801-34th Avenue, South Wold Chamberlain Field Minneapolis, MN 55401
DC-3 Series; T.C. 669	SA3-84	Two Micro Switch 51SA1 lights.	GL	49300	Lake Central Airlines, Inc. Weir Cook Municipal Airport Indianapolis, IN 46241

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-6, DC-6A (C-118A), DC-6B; T.C. A-781, 6A3, 6A4	SA1066SC	Alternate installation of hydraulic pump utilizing existing engine drive. Issued 4/23/79.	SC	15410	Bellomy-Lawson Aviation, Inc. 3100 Northwest 57th Avenue Miami, FL 33152
DC-6, -6A (C-118A), -6B; T.C. A-791, 6A3, 6A4	SA1083SC	Installation of four Pratt & Whitney R-2800-99W engines and Hamilton Standard propellers. Issued 7/3/79.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 28426 Atlanta, GA 30328
DC-6, -6B; T.C. 781, 6A4	ST456SO	Installation of cargo restraining bulkhead. A clean and unobstructed passageway between the crew compartment and cargo compartment on the side of the bulkhead is required. Issued 4/9/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST463SO	Installation of cargo door. Issued 5/4/71.	SO	58700	Miami Aviation Corporation Hangar 102, Opa Locka Airport Opa Locka, FL 33054
DC-6, -6B; T.C. 781, 6A4	ST470SO	Installation of aft cargo door. Issued 6/22/71.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST495SO	Installation of aft cargo door. Issued 2/28/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST535SO	Installation of cargo floor. Amended 6/4/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST536SO	Installation of aft cargo door. Amended 6/16/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST555SO	Installation of rear cargo door. Issued 9/28/73.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33152
DC-6, -6B; T.C. 781, 6A4	ST595SO	Installation of exhaust system bracket. Reissued 1/6/75.	SO	02394	Aeronautical Engineering, Inc. 342 N.W. 2nd Court Dania, FL 33004
DC-6, -6B; T.C. 781, 6A4	ST597SO	Installation of aft cargo door. Amended and reissued 6/16/75.	SO	02394	Aeronautique Engineering, Inc. 342 N.E. 2nd Court Dania, FL 33004
DC-6, -6B; T.C. 781, 6A4	ST843SO	Installation of aft cargo door. Amended 6/3/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6 Series, DC-7 Series; T.C. 781, 6A3, 6A4, 4A10	SA4-328	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-329	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-330	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA76EA	Radome assembly 3016.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
DC-6A, DC-7B, -7BF, -7C, -7CF; T.C. 6A3, 4A10	SA470CE	Installation of Fairchild cockpit voice recorder Model A-100. Amended 3/1/67.	GL	81064	Universal Airlines, Inc. Detroit-Metropolitan Airport Inkster, MI 48141
DC-6A; T.C. 6A3	ST671SO	Installation of cargo loading/restraint system for palletized cargo. Amended 6/24/69.	SO	46000	Jet Avion Corporation 950 S.E. 8th Street Hialeah, FL 33010
DC-6A, DC-6B; T.C. 6A3	ST34GL	Remove cabin pressurization system, modify cabin air heating and ventilating system. Issued 9/24/73.	GL	90135	Zantop International Airlines, Inc. Willow Run Airport Ypsilanti, MI 48197
DC-6A (C-118A), DC-6B; T.C. 6A3, 6A4	ST964SO	Installation of cargo interior, installation of cargo restraint and modification of pressurization system. Amended 10/17/78.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 480756 Miami, FL 33148

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-6A, DC-6B, USAF C-118A (DC-6A); T.C. 6A4, 6A3	ST974SO	Installation of extra crew seating and air distribution system. Issued 3/29/78.	SO	15410	Bellomy - Lawson Aviation, Inc. P.O. Box 522760 Miami, FL 33152
DC-6A, USAF C-118A, Navy R6D-1, DC-63, R6D-1Z; T.C. 6A3	ST981SO	Deactivation of the cabin pressurization system, conversion of the cargo compartment to a class "E" compartment, and modification of the ventilation. Amended 10/10/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
DC-6A/C-118A; T.C. 6A3	SA1506CE	Engine driven cabin air compressors and associated cabin pressurization controls removed. Amended 4/8/80.	CE	64292	Petroleum Air Transport, Inc. P.O. Box 187 Hazlewood, MO 63042
DC-6A, R6D-1, C-118A; T.C. 6A3	SA4198WE	Forward and rear cargo door latch assembly, P/N TAS-3361150, and fitting installation, P/N TAS-5359955-8002. Issued 8/5/80.	WE	78500	Time Aviation Services, Inc. 9237 - 9253 San Fernando Road Sun Valley, CA 91352
DC-6A, DC-6B; T.C. 6A3	SA1363WE	Installation of Fairchild Industrial Products Model A100 cockpit voice recorder system. Amended 4/30/68.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 2426 Oakland International Airport Oakland, CA 94614
C-118A; T.C. 6A3	SA770SO	Installation of cargo pallet and container loading and restraint system. Issued 4/12/79.	SO	02390	Aeronautica Engineers, Inc. P.O. Box 661027 Miami, FL 33166
R6D-1; T.C. 6A3	SA3406WE	Modification of oxygen system including addition of supply bottle, pressure relief valve, and microphone in smoke masks. Issued 5/19/77.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-6B; T.C. 6A4	ST454SO	Installation of aft cargo door. Issued 3/1/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST514SO	Installation of forward cargo door. Amended 2/12/75.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6B; T.C. 6A4	ST523SO	Installation of forward cargo door. Amended 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST529SO	Installation of cargo floor. Reissued 3/12/73.	SO	08368	Airtech Service, Inc. P.O. Box 516 Miami, FL 33148
DC-6B; T.C. 6A4	ST532SO	Installation of main cabin compartment. Issued 3/27/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST553SO	Installation of cargo floor. Issued 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST729SO	Removal of pressurization and cabin cooling systems. Issued 7/10/72.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6B; T.C. 6A4	SA1434WE	Installation of modified DC-7 type cargo loading system.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 426 Oakland International Airport Oakland, CA 94914
DC-6B; T.C. 6A4	SA1457WE	Installation on auxiliary power unit in fuselage.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport AVenue Santa Monica, CA 90405
DC-6B; T.C. 6A4	SA1510CE	Engine driven cabin air compressors and associated cabin pressurization controls removed. Amended 4/8/80.	CE	64292	Petroleum Air Transport, Inc. P.O. Box 187 Hazelwood, MO 63042
DC-6B; T.C. 6A4	SA1604SW	Aft cargo door between F.S. 661 and F.S. 801. Issued 2/13/73.	SW	08351	Air Services, Inc. P.O. Box 2 Addison, TX 75001
DC-6B Cargo; T.C. 6A4	SA1663WE	MOdification of DC-6B cargo aircraft to incorporate passenger or combination passenger/cargo arrangements.	WE	25970	Continental Airlines Los Angeles International Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-6B Cargo; T.C. 6A4	SA1765WE	Installation of cargo bulkhead, crew lavatory, vanity, galley and tank.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-6B; T.C. 6A4	SA2721WE	Install external retardant tank. Amended 10/5/77.	WE	03150	Aero Union Corporation Municipal Airport Chico, CA 95926
DC-6B; T.C. 6A4	SA2861WE	Installation of rear cargo door system GA61104. Issued 4/4/74.	SW	37093	Gary Aircraft Corporation P.O. Box 3486 San Antonio, TX 78211
DC-7 Series; T.C. 4A10	SA1-25	Substitution of rotating discs 9531691 and 9531704 in 9560285 and 9560286 brake assemblies.	GL	39011	Goodyear Aircraft Corporation Akron, OH 44309
DC-7 Series; T.C. 4A10	SA3-311	Wheels 150741-1 and/or 150741-5 and brake assembly 150835-5.	GL	15500	Bendix Aviation Corporation 401 North Bendix Drive South Bend, IN 46600
DC-7 Series; T.C. 4A10	SA4-54	Passenger/cargo interior arrangement configurations.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-91	One 4-piece divan left-hand side inboard facing and one 2-place divan right-hand side aft facing from Station 891 aft to pressure dome.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-124	Station 122 bulkhead.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-255	Aft cabin lounge.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-355	Interior modification coach to mixed class.	WE	07500	AiResearch AVviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-405	Interior modification to mixed class.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA4-442	Modification of communication equipment to provide navigator station.	SW	10150	American Airlines, Inc. Municipal Airport Tulsa, OK 74101
DC-7 Series; T.C. 4A10	SA4-507	Deterjet DJ1025 valve in place of Wright torquemeter booster pump upper housing per STC SEW-10.	WE	62300	Pan American World Airways, Inc. International Airport San Francisco, CA 94119
DC-7 Series; T.C. 4A10	SA4-608	Engine mount core assemblies DE-643-1 on Wright TC18 series engines.	WE	30500	Dow-Elco, Inc. 1313 West Olympic Boulevard Montebello, CA 90640
DC-7 Series; T.C. 4A10	SA10SO	Provisioned for installation of 10,000 pound military pallet.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-7 Series; T.C. 4A10	SA23SO	Observer's seat fuselage Station 55.	SO	68130	Riddle Airlines P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA30SO	Two emergency exits at stations 437.9 - 460.5 from Type IV to Type III modified.	SO	68130	Riddle Airlines, Inc. P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA35SO	Access hole in horizontal stabilizer.	SO	68130	Riddle Airlines, Inc. P.O. Box 48-535 International Airport Miami, FL 33159
DC-7 Series; T.C. 4A10	SA89SO	Oil separator B-300-1.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
DC-7 Series; T.C. 4A10	SA103WE	Interior arrangement for 104 passengers.	EA	19640	Camaero, Inc. Room 2004 27 Wall Street New York, NY 10005
DC-7 Series; T.C. 4A10	SA176NW	Installation of Fairchild Andover Model 204 auxiliary power unit for ground use only.	NW	18700	Butler Aircraft Company P.O. Box 338 Redmond, OR 97756

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-7 Series; T.C. 4A10	SA188EA	Cabin interior modifications.	EA	80923	United States Overseas Airlines P.O. Box 234 Wildwood, NJ 08260
DC-7 Series; T.C. 4A10	SA214WE	Passenger interior arrangements and cargo interior.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. California Avenue Burbank, CA 91505
DC-7 Series; T.C. 4A10	SA294WE	Door in floor for cabin access.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
DC-7 Series; T.C. 4A10	SA314WE	Passenger interior arrangements and cargo interior for operation of aircraft at 106,400 pounds zero fuel weight.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 North Clybourn Avenue Burbank, CA 91505
DC-7 Series; T.C. 4A10	SA364SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l. Airport Atlanta, GA 30320
DC-7 Series; T.C. 4A10	SA365EA	All weather landing system.	EA	74574	Sperry Gyroscope Company 2221 Smithtown Avenue Ronkonkoma, NY 11779
DC-7 Series; T.C. 4A10	SA425WE	Single Federal (ITT) Type AFN3544 distance measuring equipment system.	SW	10150	American Airlines, Inc. Service Engineering Division Tulsa, OK 74151
DC-7 Series; T.C. 4A10	SA493SW	104-passenger interior arrangement.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
DC-7 Series; T.C. 4A10	SA500EA	Installation of microvision operational all-weather landing system.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
DC-7 Series; T.C. 4A10	SA588WE	Ceconite 101 covering of rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC-7 Series; T.C. 4A10	SA600SO	Cockpit voice recording system.	SO	08170	Airlift International, Inc. P.O. Box 335 Miami, FL 33148
DC-7 Series; T.C. 4A10	SA602WE	99-passenger interior arrangement modification including floor structure.	WE	05370	Aircraft Investors Hangar 28, Oakland Airport Oakland, CA 94614
DC-7 Series; T.C. 4A10	SA656WE	Interior modification for 98 occupants.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA724WE	Interior arrangement modification for 89 and 99 passengers and installation of modified navigator's seat.	WE	44188	International Aerodyne, Inc. 11319 Vanowen Street North Hollywood, CA 91603
DC-7 Series; T.C. 4A10	SA796WE	Wing flap attachments modification.	WE	30400	Douglas Aircraft Company, Inc. 3855 Lakewood Boulevard Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1068WE	Interior arrangement.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1075WE	AVQ9 radar altimeter, APN9 Loran receiver, AT144 HF transmitter and AR144 HF receiver.	WE	19550	California Airmotive Corporation 2680 East Wardlow Road Long Beach, CA 90801
DC-7 Series; T.C. 4A10	SA1361WE	Fairchild Industrial Products Model A100, cockpit voice recorder system.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 2426 Oakland International Airport Oakland, CA 94614
DC-7, -7B, -7C; T.C. 4A10	SA2709WE	Installation of 3,000 gallon external retardant tanks under fuselage at wing center section. Amended 6/17/80.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-7, -7B, -7C; T.C. 4A10	SA3015WE	Installation of LH and RH upper viewing windows above side cockpit windows. Amended 6/17/75.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-7B; T.C. 4A10	ST631SO	Installation of loading and restraint system for palletized cargo. Amended 9/12/68.	SO	46000	Jet Avion Corporation 950 SE 8th Street Hialeah, FL 33010

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-7B; T.C. 4A10	ST651SO	Installation of cargo transportation pallet and new assemblies (Heath Techna P/N AC-10195) pallet w/AC 10197 net, or AC-10194 pallet w/AC-10196 net.	NW	41625	Heath Techna Corporation 19819 84th Avenue Kent, WA 98031
DC-7CF; T.C. 4A10	SA469CE	Fairchild A-100 cockpit voice recorder.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul International Airport St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA1-599	Gables Engineering G-1010A instrument failure warning system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA1-601	Crimsco cargo container 6003 utilizing 6004 adapter in passenger compartment. Amended 5/3/67.	EA	62300	Pan American World Airways, Inc. 135 East 42nd Street New York, NY 10001
DC-8 Series; T.C. 4A25	SA3-603	Equipment furnishings, cargo provisions, forward cargo cabin DC-8.	GL	61700	Northwest Airlines, Inc. 1885 University Avenue St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA3-666	Aft cabin bin substituted for three 3-place left-hand tourist passenger seats between Stations 1253 to 1360.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul International Airport St. Paul, MN 55111
DC-8 Series; T.C. 4A25	SA4-918	Waste King flight data recorder 5424.	GL	80500	United Air Lines, Inc. 5959 South Cicero Avenue Chicago, IL 60650
DC-8 Series; T.C. 4A25	SA4-1026	Forward lounge.	WE	18390	Burns Aero Seat Company, Inc. 3900 Cohasset Street Burbank, CA 91502
DC-8 Series; T.C. 4A25	SA45SO	M6861-100 life rafts. Amended 5/8/67.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA52SO	6924-100 life rafts.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA55SO	B-500-2 oil separator.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 236 Miami, FL 33101
DC-8 Series; T.C. 4A25	SA69EA	Brown line 21105-51 stretcher kit in passenger compartment.	EA	62300	Pan American World Airways, Inc. 135 East 42nd Street New York, NY 10001
DC-8 Series; T.C. 4A25	SA70SO	Deactivation of center wing and forward auxiliary fuel tanks.	SO	61220	National Airlines, Inc. International Airport Miami, FL 33159
DC-8 Series; T.C. 4A25	SA77EA	SP-30 autopilot modification to allow manual pitch operation while maintaining automatic roll and yaw control.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA94SO	WN233-102 and WN333-101 passenger seats.	SO	02800	Aerosmith Products Corporation 6940 SW 12th Street Miami, FL 33144
DC-8 Series; T.C. 4A25	SA155SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA176SO	Auxiliary galley.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA194SO	Passenger seating and cabin interior.	SO	61220	National Airlines P.O. Box 2055 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA222EA	Bendix DRA-12/CPA-24 doppler computer system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA286SO	Gables G-1340B instrument warning system.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8 Series; T.C. 4A25	SA293EA	Tray carrier.	EA	62300	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8 Series; T.C. 4A25	SA305EA	Inflight motion picture system provisions. Amended 10/5/67.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA306SO	Forward lounge compartment configuration change.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA312EA	Aerotherm 1003 stretcher.	EA	62300	Pan American World Airways, Inc. Pan Am Building New York, NY 10017
DC-8 Series; T.C. 4A25	SA324EA	Litton LN-12 inertial navigation system and Bendix navigational computer.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, L.I., NY 11430
DC-8 Series; T.C. 4A25	SA333EA	Litton low range altimeter system and activation of altitude bar.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, L.I., NY 11430
DC-8 Series; T.C. 4A25	SA343SO	Cockpit voice recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l. Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA350SO	Galleys 1 and 4.	SO	19846	Capitol Airways, Inc. Berry Field Nashville, TN 37202
DC-8 Series; T.C. 4A25	SA359SO	Seat belt attachment.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA370SO	Single radio altimeter.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA373SO	Installation of remote accelerometer and mount assy for DC-8 flight recorder.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA377EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways, Inc. JFK International Airlines Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA380SO	Installation of stretcher assembly.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8 Series; T.C. 4A25	SA445EA	Installation of cockpit voice recorder. Amended 2/27/67.	EA	62300	Seaboard World Airlines Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA479WE	Cargo bins and adapters in passenger cabin.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA497EA	Installation of Inflight Motion Picture Provisions.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA543EA	Cockpit voice recorder.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
DC-8 Series; T.C. 4A25	SA544WE	Interior arrangements.	WE	79200	Trans International Airlines Box 2306, Airport Station Oakland, CA 94614
DC-8 Series; T.C. 4A25	SA545WE	Interior arrangements.	WE	79200	Trans International Airlines Box 2306, Airport Station Oakland, CA 94614
DC-8 Series; T.C. 4A25	SA582WE	Aileron power system modification to incorporate a flexible hose.	SO	62300	Pan American World Airways, Inc. Pan Am Building Miami, FL 33159
DC-8 Series; T.C. 4A25	SA602SO	Dual Collins AL-101 radio altimeter system.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA613SO	Installation of Collins FD-109 FD-109 flight director system. Amended 12/28/67.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-8 Series; T.C. 4A25	SA833WE	Two triple seats in main cabin and associated changes.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8 Series; T.C. 4A25	SA855WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA994WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-6 Series; T.C. 4A25	SA1184WE	United Data Control cockpit voice recorder.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1220WE	Brownline pallet 23118-51 and Brownline pallet net 22672-51.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1347WE	GAlley 100 and 200 at fuselage stations 447.75 to 490, and 1385.5 to 1416.	WE	28560	Dale Engineering Company 12243 Branford Street Sun Valley, CA 91352
DC-8 Series; T.C. 4A25	SA1349WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1522WE	Substitution of Brownline cargo container assembly P/N 24026-51 for Douglas pallet assembly P/N 5776662-505 and net P/N 7778335.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airlines San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA1538WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder and Honeywell P/N 180 VI central air data computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA1796WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8 Series; T.C. 4A25	SA2318WE	Installation of emergency exit lights. Issued 3/2/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331
DC-8 and DC-8F Series; T.C. 4A25	SA1783WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8; DC-9; T.C. 4A25, A6WE	SA2534SW-D	Replacement of switch assembly, International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-8; DC-9; T.C. 4A25, A6WE	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, 104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-8, DC-9, DC-10; T.C. 4A25, A6WE, A22WE	SA2728WE	Incorporation of Holcombe Industries HI_LITE SYSTEM P/N 50-1001 for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -8F-54, -8F-55, -61, -61F, -62, -62F, -63, -63F; DC-9-11, -12, -13, -14, -15, -15F, -21, -31, -32, -32F, -41; DC-10-10; T.C. 4A25, A6WE, A22WE	SA10GL	Installation of Gayston Model 800LG and 800SC static dischargers on transport category airplanes. Issued 12/15/72.	GL	37125	Gayston Corporation 55 Janney Road Dayton, OH 45404
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, -61, -61F, -62, -62F, -63, -63F, DC-8F-54, -55; T.C. 4A25	SA928WE	Installation of replacement safety belt assemblies. Amended 10/9/74.	WE	68725	Rocket Jet/ARD Division American Safety Flight Systems, Inc. 1311 Grand Central Avenue Glendale, CA 91201

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, F-54, F-55; T.C. 4A25	SA1063SO	Installation of forward cargo door. Issued 4/6/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, -61, -61F, -62, -62F, -63, -63F, DC8F-54/55; T.C. 4A25	SA2539WE	Installation of emblem light. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-8-12, -21, -33, -51, -52; T.C. 4A25	SA228EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 - 148th Avenue Jamaica, NY 11434
DC-8, -12, -21, -31, -32, -33, -52; T.C. 4A25	SA676CE	Installation of Crimsco cargo container, P/N 600301, utilizing Model 6004 adapter in passenger compartment.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
DC-8-20, -30, -40, -50 Series; T.C. 4A25	SA266GL	Installation of Litton LTN-211 Omega navigation system. Amended 4/26/79.	GL	61788	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-20/50; T.C. 4A25	SA3030WE-D	Install a carry-on baggage module. Issued 9/7/76.	WE	90500	United Airlines, Inc. Maintenance Operations Center San Francisco Airport San Francisco, CA 94128
DC-8-21; T.C. 4A25	SA3869WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 2/20/79.	WE	66405	G. S. Rasmussen P. O. Box 10519 Glendale, CA 91209
DC-8-21, DC-8-51; T.C. 4A25	ST449SO	Installation of air data computer with altitude display, altitude reporting, and altitude alerting capabilities. Issued 12/30/70.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, DC-8-51; T.C. 4A25	ST670SO	Installation of International Inflatables Co. P/N 68035 door-mounted emergency evacuation slide at forward entrance door and service door and International Inflatables Co. P/N 68085-3 door mounted emergency evacuation slide at aft entrance and service doors. Amended 10/6/69.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, -32, -51; T.C. 4A25	ST680SO	Installation of Pan Avion Model LSR-210 and LSR-273 emergency evacuation slides and Pan Avion slide pack containers P/N 017-33 and P/N 017-34 at forward and aft passenger entry and service doors.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -54, -55; T.C. 4A25	ST844SO	Installation of cargo interior. Amended 5/8/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, DC-8F-54, -55; T.C. 4A25	SA915SW	Installation of Bendix P/N 19E138-2A flexible drive shaft in lieu of Dana P/N 26567 universal joint shaft on Pratt & Whitney Model JT3D-1 engine gear box and C.S.D. Amended 10/1/71.	EA	16000	The Bendix Corporation Fluid Power Division 211 Seward Avenue Utica, NY 13503
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1033WE	Either single or dual Collins AL-101 radio altimeter systems. Amended 11/19/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airlines San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1034WE	Installation control and annuciation circuitry to implement Flight Director "Go-Around" command modes. Amended 4/1/68.	WE	90500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -54, -55; T.C. 4A25	SA1088SO	Installation of a cargo interior. Issued 7/11/79.	SW	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1405WE	Structural installation of Dorne and Margolin DMC 33-2 Satcom VHF radio antenna.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-21, -32, -51, -61; T.C. 4A25	SA1980WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8, -8-21, -31, -33, -51, -52, -54F, -61, -62; T.C. 4A25	SA2211WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-21, -52; T.C. 4A25	SA2316WE	Revised interior arrangement to an all-tourist, 149-passenger configuration. Amended 5/23/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -51, DC-9 Series; T.C. 4A25, A6WE	SA2405WE	Installation of PICC Division pressure regulator P/N 3001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
DC-8-21, -31, -33, -51, -52; T.C. 4A25	SA2573WE	Installation of interior modifications. Amended 3/6/74.	WE	80500	United Air Lines, Inc. Maintenance Base Engineering Department San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -8F-54, -8-61, -61F, -62, -63, -63F; T.C. 4A25	SA2827WE-D	Installation of Collins FPC-75 P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -51, -52; T.C. 4A25	SA3033WE-D	Revise interior arrangement to increase coach seating. Amended 6/3/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -33, -51, -52, -61, -62, DC-8F-54; T.C. 4A25	SA3189WE	Installation of UAL NLG orifice support tube assembly, P/N 6F13548-501 and -502. Issued 10/4/77.	WE	80500	United Air Lines San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-33; T.C. 4A25	SA260NW	Modification of pax airplane configuration to cargo configuration (bulk). Issued 2/17/76.	NW	69204	Rosenbalm Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	ST266GL	Installation of a Litton LTN 211 Omega navigation system. Issued 8/25/78.	GL	61788	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA289GL	Load palletized livestock as bulk cargo. Issued 12/22/78.	GL	44036	InterContinental Airways, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA421NW	Cargo modification as done under STC's SA207NW and SA260NW and SA324NW. Issued 3/15/77.	NW	69204	Rosenbalm Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	SA2036WE	Installation of Henry Windscreen Model No. 48102. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8-33; T.C. 4A25	SA2825WE-D	Revise interior arrangement to accommodate all coach, 186 passenger overwater configuration. Amended 4/3/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-33; T.C. 4A25	SA3403WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo handling system, and increasing maximum landing and zero fuel weight. Amended 6/14/78.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846
DC-8-33; T.C. 4A25	SA3611WE	Modification to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3804WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/13/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-33; T.C. 4A25	SA3907WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3910WE	Modifications to permit an increase in maximum allowable zero fuel weight.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3612WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3749WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo floor, and increasing maximum landing and zero fuel weight. Issued 9/28/78.	WE	52995	McDonnell Douglas Corp. 3855 Lakewood Boulevard Long Beach, CA 90846
DC-8-43; T.C. 4A25	SA3805WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3880WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 3/28/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3911WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43, -53; T.C. 4A25	SA2681WE	Installation of enclosed overhead stowage bins, sculptured ceiling panels, with integral lighting, improved sidewall lighting, and revised passenger service units. Issued 4/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-50, -60; T.C. 4A25	SA3963WE	Installation of dual Global GNS-500A VLF/Omega navigation systems. Issued 5/23/79.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
DC-8-51; T.C. 4A25	SA1768WE	Installation of stewardess seat Model 6878 on Nordskog galley Model 305A.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-51; T.C. 4A25	SA4078WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 2/6/80.	WE	66405	G. S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-51; T.C. 4A25	SA4080WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 8/21/80.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-51, -52; T.C. 4A25	SA2835WE-D	Installation of enclosed overhead stowage compartments, improved ceiling and sidewall lighting, relocation of motion picture projector compartments and complete cabin refurbishment. Issued 4/30/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-51, -52, -8F-54, -8-61; T.C. 4A25	SA3357WE-D	Retrofit of fuel quantity indicators and totalizers, Gull Airborne Instruments, Inc. P/Ns 206-009 and 206-016 series. Issued 1/30/78.	WE	80500	United Air Lines San Francisco Int'l Airport San Francisco, CA 91406
DC-8-51, -61; T.C. 4A25	ST857SO	Installation of Bendix ground proximity warning system. Amended 11/14/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8-52; T.C. 4A25	SA448NW	Installation of new look interior conversion kit for Aviaco Air Lines.	NW	41625	Heath Tecna Corporation 19819 - 84th Avenue, South Kent, WA 98031
DC-8-52; T.C. 4A25	SA3945WE-D	Installation of a DC-8-51 landing gear on DC-8-52 airplane. Issued 6/9/80.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-53; T.C. 4A25	SA3613WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-53; T.C. 4A25	SA3806WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3908WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3909WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3912WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8F; T.C. 4A25	SA605EA	Installation of pallet P/N 6524 incorporating Douglas cargo loading system or pallet P/N 6524 must use nets and be loaded in accordance with Douglas pallet P/N 5776662-505 instructions.	EA	66470	Ray, Daisley Co., Inc. 585 West Hoffman Avenue Lindenhurst, NY 11757
DC-8F-54; T.C. 4A25	SA633CE	Make and install cargo pallets in accordance with Brooks & Perkins Drawing List No. 16987. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	ST677SO	Installation of Nordskog galley Models 376, 377, 378 and 379 at right hand galley positions 1, 2, 3, and 4.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST684SO	Interior conversion of passenger cabin to accommodate 24 first class and 105 tourist class passengers. Amended 1/8/70.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST747SO	Installation of livestock transportation pens. Issued 1/31/75.	SO	21560	Casco Division Charlotte Aircraft Corporation P.O. Box 481225 Miami, FL 33148
DC-8F-54; T.C. 4A25	SA804EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8F-54; T.C. 4A25	SA813CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA843CE	Installation of cargo-pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA1793WE	Installation of Heathair AC-0152-1 structural container in DC-8F-54 aircraft equipped with cargo loading system No. 7778202-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54; T.C. 4A25	SA1991WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, -52; 22672-51, -52; or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54; T.C. 4A25	SA1997WE	Installation of Brownline pallet assembly P/N 40309 and net assembly Brownline P/N 21350-51, 21710-51, -52, Douglas P/N 7776431-1 or 7776431-501. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54; T.C. 4A25	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1 or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
DC-8F-54; T.C. 4A25	SA2255WE	Installation of Satco, Inc. pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8F-54; T.C. 4A25	SA2274WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
DC-8F-54; T.C. 4A25	SA2745WE-D	This modification provides seats, oxygen, cockpit communications, emergency equipment and other items necessary to carry six couriers or other persons authorized aft of Station 1370. Issued 4/22/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54; T.C. 4A25	SA3586WE-D	Installation of a removable dual Delco C-IV inertial navigation system for navigation only. Issued 10/27/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54, -55; T.C. 4A25	SA697CE	Installation of Aeroquip Corp. cargo tie-down net.	GL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203
DC-8F-54, -55; T.C. 4A25	SA1623WE	Installation of Heath 88 x 125-inch cargo pallet P/N AC-10061-1 and cargo net P/N AC-10069-1 on subject models equipped with McDonnell Douglas cargo loading system No. 7776939. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1665WE	Installation of Heath Tecna 88 x 125-inch cargo pallet, P/N AC-10160 and net P/N AC-10069. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1875WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517 with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks and Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2234WE	Installation of Brownline Division Division structural container 41342-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2278WE	Installation of Brownline cargo container Model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-F54, -8-55 Series; T.C. 4A25	SA2137WE	Installation of Litton inertial navigation system(s) LTN51 (dual or single) or LTN72 (dual or single). Amended 12/14/78.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
DC-8F-54, -8-55; T.C. 4A25	SA4088WE	Installation of single or dual Litton LTN-72 INS. Issued 1/30/80.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
DC-8F-54, -8F-55, -8-61F, -62F, -63F; T.C. 4A25	SA1807WE	Installation of Brownline pallets and nets. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-61F, -8-63F; T.C. 4A25	SA2098WE	Modification by installation of structural cargo container 40619-101 and -102. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA1812WE	Installation of Heath Tecna 88 x 125-inch cargo pallets P/N AC-10355-1 and AC-10366-1 and net P/N AC-10357-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA2114WE	Installation of Brownline cargo container Model 40622. Amended 5/16/75.	WE	79500	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F, -9-32F, -33F; T.C. 4A25, A6WE	SA2152WE	Installation of Heath 88 x 108-inch cargo pallet AC-10527-1 and net AC-10196-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
DC-8F-54, -8-62F; T.C. 4A25	SA1974WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and Brownline net assembly P/N 22672-51, 22672-52, 23143-51, 40657, 40850, 40517, 22273-51, 22758-51, 22758-52; Douglas net assembly P/N 7776967-1 or Aeroquip net assembly P/N 3950020. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55; T.C. 4A25	SA672EA	Installation of two place courier seat, lavatory compartment and smoke curtain.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8F-55; T.C. 4A25	SA1395WE	Substitution of Brownline pallet P/N 23640-51 and P/N 23224-51 for Douglas pallet P/N 5776662-505.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-55, -8-61F; T.C. 4A25	SA1764WE	Installation of Heathair pallet Model AC10194 and net Model AC-10196. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8F-55, -61F, -63F; T.C. 4A25	SA1028EA	Installation of Collins FPC-75 ground proximity warning system. Amended 6/22/76.	EA	70600	Seaboard World Airlines, Inc. Seaboard World Building JFK International Airport Jamaica, NY 11430
DC-8F-55, -8-62F; T.C. 4A25	SA2059WE	Installation of 88 x 125-inch cargo pallet P/N 24076-51, 88 x 108-inch pallets P/N 40309101 and 40309102, and 88 x 53-inch pallets P/N 40464101 and 40464102 with net assemblies 22361-51, 22364-51, 22758-51, 22273-51, 21530-51, 21710-51, -52, and 21869-51. Amended 10/12/70.	WE	17749	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55, -8-63F; T.C. 4A25	SA589EA	Installation of dual omnitrac navigation system. Amended 7/19/68.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8F-55, -8-63F; T.C. 4A25	SA675EA	Installation of L. Marino cargo net. Amended 3/31/70.	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
DC-8F-55, -8-63F; T.C. 4A25	SA725EA	DC-8F pallet P/N LM1600 (1.50 Fwd), DC-8-63F pallet P/N LM1600 (1.50 Fwd).	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
DC-8F-55, -8-63F; T.C. 4A25	SA2218WE	Installation of Satco cargo pallet P/N 31 80-501, NAS classification 3610-2A3P and P/N 31076-501, NAS classification 3610-2A1P with cargo nets Brownline P/N 22758-51, -52, -54, 22672-52, 22273-51, 23226-51, 40517-101; Heath Tecna P/N AC 10292-1; Marino P/N LM 1500-100; and ANCRA Corp. P/N 40178-10. Amended 10/12/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8-61; T.C. 4A25	SA467EA	Inflight Motion Picture provisions. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-61; T.C. 4A25	SA1400WE	Installation of 198-passenger interior arrangement. Amended 4/17/74.	GL	80500	United Air Lines, Inc. Executive Offices 1200 Algonquin Road Elk Grove Township, IL 60007
DC-8-61; T.C. 4A25	SA1926WE	Dual installation of A.C. Electronics Carousel IV INS units. Amended 1/16/70.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2128WE	Installation of RCA Model AVQ-30C weather radar system.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-61; T.C. 4A25	SA2558WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other interior changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2674WE	Revised interior arrangement. Issued 3/23/73.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94158
DC-8-61; T.C. 4A25	SA2739WE-D	Revised seating configuration. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2741WE-D	Installation of equipment to provide guidance to flight director and SP-30AL autopilot to conduct two-segment approaches. Amended 4/7/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2804WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 3/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61; T.C. 4A25	SA2824WE-D	Installation of dual Delco C-IV inertial navigation systems. Issued 1/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3032WE-D	Install carry-on baggage module in place of one first class seat assembly. Amended 12/27/76.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3038WE-D	Installation of dual Collins FD-109 flight director system. Issued 5/24/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3039WE-D	Installs galley units and all supporting structure including plumbing and wiring at three locations. Amended 8/19/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3040WE-D	Installation of cabin new look, cabin refurbishment, inflight entertainment installation, passenger seat procurement and rework, and internal partitions and stowage cabinet. Issued 6/11/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61;	SA3356WE-D	Revise interior arrangement to accommodate dual class, 12 first class and 177 coach passenger configuration. Issued 11/4/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3582WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3587WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 12/14/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3588WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 1/5/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3593WE-D	Seat mix change from 26 F/C and 156 coach passenger configuration to 26 F/C and 164 coach passenger configuration. Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC8-61; T.C. 4A25	SA3943WE-D	Rework of high-frequency communications system to install single-sideband capability. Issued 5/16/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA4091WE	Deletion of a pair of excess Type 1 exits at station 1124. Issued 1/22/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-61, -61F, DC-8-63, -63F; T.C. 4A25	SA1873WE	Installation of Litton Systems dual LTN-51 or LTN-52 inertial navigation systems. Amended 1/4/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61, -62, -62F; T.C. 4A25	SA1006EA	Installation of cabin interior furnishings. Amended 8/26/77.	EA	12500	Atlantic Aviation Corporation Greater Wilmington Airport P.O. Box 1709 Wilmington, DE 19899
DC-8-61, -63; T.C. 4A25	SA1096SO	Installation of Tracor, Inc. omega navigation systems. Issued 8/23/79.	SO	19848	Capitol International Airways, Inc. P.O. Box 325 Smyrna, TN 37167
DC-8-61F; T.C. 4A25	ST687SO	Installation of AIF class divider partitions, left hand and right hand assembly, P/N 32012 with header assembly, P/N 32013.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-61F; T.C. 4A25	SA2157WE	Installation of 242 passenger seating arrangement. Issued 6/5/70.	WE	81064	Universal Airlines 401 McCormick Street San Leandro, CA 94577
DC-8-61F; T.C. 4A25	SA2481WE	Installation of Trans Com Model 1357 movie projector and screen assemblies. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
DC-8-61F; T.C. 4A25	SA3279WE	Installation of Litton ground proximity warning system computer P/N 456300-01, -202 in the provisions under STC SA1028EA. Issued 10/28/76.	WE	51500	Litton Systems, Inc. 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F; T.C. 4A25	SA2800WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Amended 3/12/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F, DC-8-63F; T.C. 4A25	SA630CE	Installation of cargo pallets. Amended 11/1/79.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8-61F, -8-63F; T.C. 4A25	SA1733WE	Installation of Nordskog seat assembly P/N 61247 with certain interior arrangements. Amended 4/12/71.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-62; T.C. 4A25	SA1959WE	Installation of movie projection system.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-8-62; T.C. 4A25	SA2299WE	Installation of third AC electronics carousel IV inertial navigation system. Issued 12/31/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2310SW	Install wheel and brake advisory system. Issued 5/17/76.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
DC-8-62; T.C. 4A25	SA2377WE	Installation of Collins Radio Company INS - 61B inertial navigation system. Amended 12/7/71.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2533WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other architectural changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2581WE	Installation of Collins Radio Company inertial navigation systems. Issued 8/23/72.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
DC-8-62; T.C. 4A25	SA2738WE-D	Revise seating arrangement to 154 passenger configuration; revise passenger service unit locations to comply with seating configuration; install class dividers and curtains. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-62; T.C. 4A25	SA2742WE-D	Install dual class seating arrangement (4 and 6 across). Amended 5/2/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2818WE-D	Installation of triple Delco Electronics carousel IV-A inertial navigation system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2819WE-D	Installation of Atlantic Aviation wide body kit. Issued 11/8/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2820WE-D	Installation of passenger entertainment and automatic announce system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2840WE-D	Install an alternate all tourist seating and galley configuration. Galley configuration was previously approved under STC SA2296WE. Amended 6/8/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2904WE	Installation of GAMMA inertial navigation system. Issued 7/2/74.	WE	71838	The Singer Company Kearfott Division 5730 West Manchester Avenue Los Angeles, CA 90045
DC-8-62; T.C. 4A25	SA3351WE-D	Installs a 181 passenger all coach cabin seating configuration.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3361WE-D	Installs a 16 first class/123 coach dual class seating configuration. Issued 1/16/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3576WE-D	Revise interior arrangement to accommodate 162 coach passenger configuration. Issued 6/2/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3584WE-D	Seat mix change from 162 passenger all coach configuration to 18F/129Y-147 passenger configuration. Amended 11/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62, -62F; T.C. 4A25	SA993EA	Installation of Inflight Motion Pictures, Inc. 16 mm. movie projection system IR4000 and screen assemblies. Amended 8/26/77.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-62F; T.C. 4A25	SA2308WE	Installation of cargo barrier net. Issued 1/27/71.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-8-62F; T.C. 4A25	SA2785WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 11/20/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-62F, DC-9-31; T.C. 4A25, A6WE	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 12/10/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
DC-8-63; T.C. 4A25	SA649SO	Installation of lounge table AIF P/N 31538-101.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-63; T.C. 4A25	ST681SO	Installation of class divider partition assembly P/N 31929-100 left hand and 31929-200 right hand at fuselage station 2900.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST682SO	Installation of lounge table assembly P/N 31928/100 right hand and P/N 31928-101 left hand at fuselage station 338.0.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST728SO	Interior modification and installation of 251 passenger service units and galley attachments to provide for 251 passenger arrangement (less seats and galleys). Issued 4/28/72.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33149

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-63; T.C. 4A25	ST737SO	Main cabin interior modifications. Issued 3/28/73.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-8-63; T.C. 4A25	SA750NW	Installation of Mark I interior kit. Issued 4/12/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
DC-8-63; T.C. 4A25	SA1730WE	Installation of cockpit voice recorder, seat lights, passenger service outlets, communication panel relocation, galley wiring changes, flight data recorder and vertical accelerometer, pitot tube with heater circuit, marker beacon.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA1738WE	Modification of interior arrangement to 221 passenger Military Airlift Command configuration. Amended 11/7/68.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA1909WE	Modification of interior arrangement to provide automatic folding attendant seats at the four jet escape exits.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA2704WE-D	Installation of enclosed overhead stowage bins, sculptured ceiling panels with integral lighting, cabin refurbishment. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-63; T.C. 4A25	SA3854WE	Installation of Tracor 7640A ONS. Issued 3/21/79.	WE	79200	Transinternational Airlines P.O. Box 2504 Oakland International Airport Oakland, CA 94614
DC-8-63, -63F; T.C. 4A25	SA2154WE	Installation of triple Litton LTN-51 inertial navigation system. Amended 4/23/71.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
DC-8-63F; T.C. 4A25	SA652EA	Installation of dual Decca doppler systems, Type 72. Reissued 7/2/69.	EA	44900	I.T.T. Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
DC-8-63F; T.C. 4A25	ST766SO	Installation of double deck livestock transportation pens. Issued 11/1/77.	SO	11320	Animal Air Services, Inc. 14441 Northwest 13 Court Miami, FL 33162
DC-8-63F; T.C. 4A25	SA1039EA	Installation of animal restraint system for air shipment of livestock. Reissued 11/9/78.	EA	79304	Transmeridian Air Cargo Ltd. Stansted Airport Stansted, Essex, England
DC-8-63F; T.C. 4A25	SA1731WE	Install single Decca Model 72 doppler radar (ground speed and drift angle only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA1928WE	Installation of Heath Tecna 88 x 125-inch cargo pallet P/N AC-10065-1 with Heath Tecna net P/N AC-10292-1 or Brownline net P/N 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1950WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and net assembly P/N 22672-51, 22672-52, 22758-51, 22758-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1955WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, 22758-52, 22672-51, 22672-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1978WE	Installation of underseat baggage restraint system with certain specified seat models. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1987WE	Installation of Edo Model 144 ADF-Loran antenna splitter.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-63F; T.C. 4A25	SA2017WE	Installation of Decca Model 72 doppler radar (ground speed and drift meter only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2018WE	Installation of Decca Model ADL-21 Loran.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2087WE	Installation of Cargo Systems, Inc. 88 x 125-inch cargo pallet assembly 1950-90-1 with Brownline net P/N 22758-51.	WE	19890	Cargo Systems, Inc. 1040 West Hoover Orange, CA 92667
DC-8-63F; T.C. 4A25	SA2113WE	Installation of two Decca Type 05 Omnitrac 2B Doppler/Loran navigation computer systems with pictorial displays.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2247WE	Installation of Lockheed Aircraft Services Company Model 250-A weight and balance computer system. Issued 10/9/70.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2259WE	Installation of Brownline pallet assembly P/N 41339 and Brownline net assembly P/N 41344. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA2287WE	Installation of Henry Engineering cargo container Model 52501. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8-63F; T.C. 4A25	SA2313WE	Installation of Kollsman "Slim Pac" altitude alerting system. 3/1/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8=63F; T.C. 4A25	SA2314WE	Revised seating arrangement to 244 passenger all tourist configuration. Issued 2/18/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2427WE	Installation of a third attitude indicator. Issued 10/15/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2465WE	Installation of dual Delco Carousel IV inertial navigation system. Issued 12/30/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2522WE	Installation of Nordskog tray carrier storage unit Model 798P. Issued 5/17/72.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-63F; T.C. 4A25	SA2604WE	Installation of Custom Products passenger type seat and flight crew glare protection curtain. Issued 10/24/72.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2616WE	Installation of Trans Com Model 1144 movie projector, screen assemblies and sound system. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
DC-8-63F; T.C. 4A25	SA2632WE	Modification of airplane to provide attitude information from INS in lieu of two vertical gyros (this modification pertains only to aircraft previously modified by STC SA2465WE). Issued 1/9/73.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2634WE	Installation of three Litton LTN-72 inertial navigation systems. Issued 1/9/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-63F; T.C. 4A25	SA2957WE	Installation of separate differential oil pressure system and associated warning light indication. Issued 12/23/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA3082WE	Installation of Satco, Inc. cargo pallet assembly, P/N 31250-521. Issued 9/3/75.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-63F; T.C. 4A25	SA3123WE	Installation of cargo container P/N 10-1000. Amended 4/19/76.	WE	25955	Container Development 2636 North Ontario Burbank, CA 91504
DC-8-63F; T.C. 4A25	SA3176WE	Installation of Litton Aero Products digital ground proximity warning system. Issued 4/21/76.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-63F; T.C. 4A25	SA4118WE	Installation of a Winters air stair in the aft passenger entry door. Issued 6/4/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
DC8-63F; T.C. 4A25	SA4119WE	Installation of a Winters air stairs in the forward passenger entry door. Issued 5/29/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
DC-9 Series; T.C. A6WE	SA333SO	Beverage bar.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA335NW	Modified cabin interior kit. Issued 8/13/76.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
DC-9 Series; T.C. A6WE	ST399SO	Addition of underseat luggage restraint.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA457CE	Lockheed Aircraft service 109D flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA508CE	Installation of Safe Flight P/N 1300-33 SCAT computer in lieu of P/N 1300-32.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA520CE	Installation of airborne engine vibration monitoring system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA580EA	Installation of Collins Radio CLC Type 560F-3 area navigation system.	EA	31420	Eastern Airlines, Inc. 10 Rockefeller Plaza New York, NY 10020
DC-9 Series; T.C. A6WE	ST626SO	Removal of complete passenger accommodations; installation of cargo interior. Amended 5/13/69.	SO	34220	Fairchild Hiller Corporation Aircraft Service Division St. Augustine, FI 32084
DC-9 Series; T.C. A6WE	ST627SO	Installation of cargo accommodations. Amended 5/13/69.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
DC-9 Series; T.C. A6WE	SA640NW	Installation of deep interior rack kits. Issued 7/21/78.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
DC-9 Series; T.C. A6WE	SA727NW	Delete L.H. galley, add coatroom, add 2 auxiliary galley units at forward left and right side of cabin. Issued 2/27/79.	NW	78672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
DC-9 Series; T.C. A6WE	SA730CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA752CE	Install Bendix gyro horizon, P/N 1978130-2, and Bendix inverter, P/N 1964771-2.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA829CE	Install Butler National Corporation flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA1003SW	Modify 721B galley to 721B-1 and install.	SW	84250	Vought Aircraft Service Co. Div. of LTV Aerospace Corp. 4100 North Main Street Fort Worth, TX 76107
DC-9 Series; T.C. A6WE	SA1459WE	Interior configuration modification.	WE	16892	Bonanza Air Lines 3737 East Bonanza Way P.O. Box 12405 Phoenix, AZ 85034
DC-9 Series; T.C. A6WE	SA1784WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9 Series; T.C. A6WE	SA1797WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-9 Series; T.C. A6WE	SA2330WE	Installation of battery-powered emergency exit lighting in tail-cone. Issued 3/29/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331
DC-9 Series; T.C. A6WE	SA2451SW	Marathon Battery Co. P/N 85-0050 six cell magnesium emergency light pack. Issued 4/20/77.	SW	54810	Marathon Battery Company 8301 Imperial Drive Waco, TX 76710
DC-9 Series; T.C. A6WE	SA2541WE	Installation of tail cone slide cover. Issued 6/2/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352
DC-9 Series; T.C. A6WE	SA3623WE	Installation of stretcher carrier P/N 2003. Issued 4/13/78.	WE	08205	Air Medic, Inc. 12517 Chandler Blvd. No. Hollywood, CA 91607
DC-9-10; T.C. A6WE	ST498SO	Modification of main landing gear brake stud. Issued 4/19/72.	SO	84470	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-8-10; T.C. A6WE	SA4200WE	Installation of a stall warning comparator system and AD 78-23-06 compliance for McDonnell Douglas DC-9-10 aircraft. Issued 7/25/80.	WE	78427	Texas International Airlines P.O. Box 12788 Houston, TX 77017
DC-9-10-20, -30, -40 Series; T.C. A6WE	ST699SO	Installation of International Inflatable Company Model 68090 emergency evacuation slide modified with Pan Avion valve assembly P/N 526-43. Issued 11/9/71.	SO	62384	Pan Avion P.O. Box 213 Miami, FL 33101
DC-9-10, -20, -30, -40 Series; T.C. A6WE	SA2223WE	Installation of door mounted battery-powered emergency lights. Amended 5/6/71.	WE	44266	International Inflatables Company 9880 San Fernando Boulevard Pacoima, CA 91331
DC-9-10, -30; T.C. A6WE	ST870SO	Installation of Collins FPC 75 ground proximity warning system. Issued 11/25/75.	SO	73874	Southern Airways, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-10, -30; T.C. A6WE	SA1177CE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/11/79.	CE	62030	Ozark Air Lines, Inc. St. Louis International Airport Lambert Field St. Louis, MO 63145
DC-9-10, -30; T.C. A6WE	SA3097WE	Installation of Collins Radio Co. Model FPC-75 ground proximity warning system. Amended 4/6/76.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-11, -12, -13, -14, -15, -31, -32; T.C. A6WE	ST735SO	Installation of protective rigid cover over tail cone emergency evacuation slide (installation of International Inflatables Model 68090 slide per STC ST676SO or equivalent required with this STC). Issued 12/4/72.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
DC-9-11, -12, -13, -14, -15, -15F; T.C. A6WE	SA2233WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-9-11, -12, -13, -14, -15, -15F, -21; T.C. A6WE	SA2503WE	Installation of replacement cooling turbine nozzle assembly. Issued 4/20/72.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91503
DC-9-11, -12, -13, -14, -15, -15F; T.C. A6WE	SA2645WE	Installation of dual Litton LTN-51 inertial navigation system. Issued 2/2/73.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
DC-9-11, -14, -15F, -31; T.C. A6WE	SA1933WE	Installation of under seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-11, -31; T.C. A6WE	SA1195EA	Installation of Magee Plastics passenger service units (PSU's) in lieu of original manufacturer's PSU's. Issued 5/19/80.	EA	54200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15237
DC-9-14, -15; T.C. A6WE	SA527CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2981WE	Modification of No. 1 galley, Hughes Airwest P/N RW2530045 or Nordskog P/N 742A Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2982WE	Modification of No. 2 galley, Hughes Airwest P/N RW2530051 or Nordskog P/N 645A. Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-14, -31; T.C. A6WE	ST676SO	Installation of International Inflatables Company emergency evacuation slide, Model 68090, at tail cone exit.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-9-14, -9-31, -9-32; T.C. A6WE	SA2765WE	Installation of altitude alerting and reporting capabilities. Issued 10/10/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15; T.C. A6WE	SA1511CE	Increase the passenger capacity from 83 to 90. Issued 9/6/79.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9-15; T.C. A6WE	SA1728WE	Installation of Bendix Model DRA 12 Doppler navigation system and relocation of ATC transponder antenna and marker beacon antenna. Amended 2/6/70.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-9-15; T.C. A6WE	SA2587WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 3/18/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
DC-9-15; T.C. A6WE	SA2764WE	Altitude alerting and reporting capabilities are provided by installation of Harowe P/N 2031-01-1 altitude alert system, replacement of captain's barometric altimeter with a Harowe P/N 2050-01-1 servo actuated altimeter and two existing air data computers are replaced by Sperry P/N 2587400-176 air data computer. Issued 9/26/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15; T.C. A6WE	SA3051WE	Change seating configuration to 80 economy class, and installation of two auxiliary galleys at fuselage stations 764.5 to 784. Issued 5/29/75.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846
DC-9-15F; T.C. A6WE	SA2028WE	Replacement of V.H.F. 7533483 SAU polyethylene dielectric coaxial cables with Type RG115 A/U PTFE dielectric coaxial cables and addition of head-shield between APU exhaust shroud and wiring conduits.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
DC-9-15F; T.C. A6WE	SA2763WE	The captain's altimeter is replaced by Harowe P/N 2050-01-1 servo actuated altimeter and existing altitude alert system is replaced by Harowe P/N 2031-01-1 altitude alert system. Issued 9/19/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15F; T.C. A6WE	SA2788WE	Installation of galley assembly, P/N RW2530045. Issued 12/6/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA2789WE	Installation of Hughes Airwest galley assembly, P/N RW2530051. Issued 12/10/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA3558WE	Installation of 535-gallon auxiliary fuel tank system in forward cargo compartment. Issued 3/8/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
DC-9-21, -31, -32F (USAF C-9A), -32, -33F, -41; T.C. A6WE	SA862EA	Addition of airspeed select function to speed command/autothrottle system. Amended 6/6/80.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
DC-9-21, -31, -32, -32F, -33F, -41, -51; T.C. A6WE	SA2212WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9 Series 30; T.C. A6WE	SA130GL	Installation of Systron-Donner Model 8160-20-P10 angular rate sensor in lieu of presently installed rate gyros in pitch-axis computer, roll-axis computer, and stability augmentation computers. Issued 7/23/76.	GL	61625	North Central Airlines, Inc. 7500 Northliner Drive Minneapolis, MN 55450
DC-9-30; T.C. A6WE	SA3642WE	A speed comman system, safe flight P/N 1312-25B installed. Issued 5/16/78.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-30, -9-31; T.C. A6WE	SA294NW	Interior arrangement, coatroom installation. Issued 5/14/76.	NW	48532	KME Manufacturing 800 North 6th Street Renton, WA 98055
DC-9 Series 30; T.C. A6WE	ST499SO	Modification of main landing gear brake stud. Issued 4/19/72.	SO	84770	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-9 Series 30; T.C. A6WE	SA1658WE	Installation of Airborne vibration monitoring system equipment.	WE	25917	Consolidated Electrodynamics Corp. Transducer Products Division 1400 South Shamrock Avenue Morovia, CA 91016
DC-9 Series 30; T.C. A6WE	SA2473WE	Installation of AiResearch cooling turbine P/N 204950-5-3 in lieu of P/N 204950-5-2. Issued 2/18/72.	WE	07505	AiResearch Manufacturing Company Division of Garrett Corporation 9851 Sepulveda Boulevard Los Angeles, CA 90009
DC-9 Series 30; T.C. A6WE	SA2803WE	Replacement of splined end on DC-9 nose gear cylinder, Douglas P/N 5920602. Amended 2/1/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9 Series 30; T.C. A6WE	SA2805WE	Replacement of splined end of DC-9 nose gear cylinder. Issued 1/18/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9-30; T.C. A6WE	SA3887WE	Installation of two Howell Model H900 solid state exhaust gas temperature indicators. Issued 3/29/79.	WE	43340	Hughes Airwest 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-30; T.C. A6WE	SA4059WE	Installation of ground proximity warning system (GPWS) and altitude alert system. Issued 12/13/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
DC-9-30, -32F, -33F, -51; T.C. A6WE	SA3115WE	Installation of Collins ground proximity warning system. Amended 4/7/76.	PC	41260	Hawaiian Airlines Honolulu International Airport Honolulu, HI 96820
DC-9-30, -50; T.C. A6WE	SA84GL	Install Bendix GPW-83 ground proximity warning system. Amended 8/10/76.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450
DC-9-31; T.C. A6WE	ST464SO	Installation of Decca IIB 06 omnitrac area navigation system. Operations will not be predicated on use of vertical guidance information of area navigation system. Amended 6/29/71.	SO	31420	Eastern Airlines International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	ST557SO	Installation of 99 passenger interior arrangement. Issued 10/6/73.	SO	31420	Eastern Airlines International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	SA878EA	Installation of SFENA standby horizon indicating system. Reissued 12/22/75.	CE	62030	Ozark Air Lines Box 10007, Lambert Field St. Louis, MO 63145
DC-9-31; T.C. A6WE	SA1188EA	Installation of replacement window panels. Amended 8/8/80.	EA	54200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15231
DC-9-31, -32; T.C. A6WE	SA3888WE	Installation of an auxiliary fuel tank system in the forward baggage compartment. Amended 5/25/79.	WE	43340	Hughes Air West, Inc. 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-31, -32, -32F, -33F, -41; T.C. A6WE	SA2502WE	Installation of replacement cooling turbine nozzle assembly. Amended 11/13/73.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91504
DC-9-31, -9-51; T.C. A6WE	SA1019EA	Installation of Collins Model FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9-31/-51; T.C. A6WE	SA3455WE	Installation of tourist and first class interiors. Amended 10/12/79.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-9-32; T.C. A6WE	ST8568SO	Installation of Bendix ground proximity warning system. Issued 10/21/75.	SO	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	ST9218SO	Fatrication and installation of baggage stowage rack, P/N 325100. Issued 1/28/77.	SO	29234	Delta Airlines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	SA1895WE	Installation of a second observer seat in flight crew compartment.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-9-32; T.C. A6WE	SA2106WE	Modification consists of interior arrangement, various passenger entertainment systems and avionics equipment. Reissued 8/20/73.	GL	64730	Playboy Enterprises, Inc. 919 North Michigan Avenue Chicago, IL 60611
DC-9-32 (VC-9C), DC-9-32F (C-9A); T.C. A6WE	ST248GL	Installation of Collins Model FPC flight profile comparator, P/N 622-2615-500, and Barowe barometric altitude rate computer, P/N 4030-03-1. Amended 7/19/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
DC-9-32F; T.C. A6WE	SA1043EA	Installation of structural provisions for executive interior. Issued 11/24/76.	EA	12500	Atlantic Aviation Corporation Box 1709 Wilmington, DE 19899
DC-9-32F; T.C. A6WE	SA2598WE	Installation of passenger pallet system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA697EA	Installation of (4) Aerojet-General Corp. 15 KS-1000-A1 or Bristol Aerospace (1968) Ltd. 15 KS-1000-A1(B) rocket engines and fairings. Amended 2/29/72.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-9-32F, -9-33F; T.C. A6WE	SA1193EA	Installation of ceiling panel kits. Issued 4/16/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
DC-9-32F, -33F; T.C. A6WE	SA1970WE	Installation of 88 x 108-inch cargo pallet P/N 24545-51, -52, or -53 with net P/N 24550-51, -52, or -53 and 88 x 54-inch cargo pallet P/N 24546-51, -52, or -53 with net P/N 24551-51 or -52. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2021WE	Installation of various cargo pallets and nets (per Tridair "Loading Instructions Drawing No. 40414). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2092WE	Installation of Heath 54 x 88-inch cargo pallet AC-10528-1 and net AC-10657-101. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-9-41; T.C. A6WE	SA3366WE	Modification of cabin interior. Installation includes all or part of the following overhead storage compartments, sculptured ceiling and sidewall panels, flourescent cabin lighting, standby lighting, emergency lighting, and an overwing exit locator sign. Amended 3/31/78.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-9-51; T.C. A6WE	SA3660WE	Installation of Carrier Aircraft coat closet Model EAL951-1. Issued 6/6/78.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-51; T.C. A6WE	SA3800WE	Installation of a 130 passenger seating arrangement, two galleys, and associated water drain mast. Issued 12/6/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
DC-9-51; T.C. A6WE	SA4002SW	In-place cargo system. Issued 7/31/79.	SW	04250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74112

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9, DC-10-30; T.C. A6WE	SA1068EA	Replacement of Fairchild Burns seats by Magee Plastics Co. seat trim kit P/N 67203. Issued 2/14/78.	EA	53200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15237
DC-10; T.C. A22WE	SA285NW	Installation of Trans Com System. Issued 4/15/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
DC-10; T.C. A22WE	SA419NW	Class divider installation. Issued 3/10/77.	NW	48532	KME Manufacturing 800 North 6th Street Renton, WA 98055
DC-10; T.C. A22WE	SA713NW	Installation of class divider. Issued 1/30/79.	NW	48532	KME Manufacturing Company The Commons Building 1200 112th N.E. Bellevue, WA 98004
DC-10; T.C. A22WE	SA3892WE	Installation of Stowe Corp. service carts. Issued 3/23/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-10; T.C. A22WE	SA2611WE	Installation of three Litton LTN-51 inertial navigation systems, an inertial navigation switching unit and two Sperry horizontal situation indicators. Amended 3/5/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10;	SA2816WE	Modification of DC-10-10 aircraft for the installation of spacer pallets. Issued 2/8/74.	WE	80500	United Air Lines, Inc. Engineering Department San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2836WE-D	Installation of Bell and Howell video entertainment system in A, B and C zones of passenger cabin. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2837WE-D	Install new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 12/9/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2888WE	Installation of three Litton LTN-51 or LTN-72 inertial navigation systems. Issued 2/28/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10; T.C. A22WE	SA3025WE-D	Installation of refrigeration cooling for DME interrogators. Amended 3/12/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3031WE-D	Installation of four additional serving cart tie downs on main deck. Amended 9/13/78.	WE	80500	United Airlines, Inc. Maint San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3035WE-D	Install slide-raft assembly at each LH and RH cabin door exit. Issued 2/17/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3036WE-D	Modifies aircraft to install dual Delco C-IV inertial navigation systems (INS) for attitude and direction reference, navigation, and autopilot steering. Issued 3/22/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3127WE	Installation of first class passenger seats incorporating unitized oxygen systems. Issued 12/11/75.	WE	85126	Western Airlines, Inc. 6060 AVion Drive Los Angeles, CA 90052
DC-10-10; T.C. A22WE	SA3358WE-D	Reduces first class seating to 16 seat places, installs 9-across coach seating - 243 seat places, installs class divider, lounge table, PSF, and closets in zone A, closet in zone C. Issued 11/15/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-10-10; T.C. A22WE	SA3510WE	Replace primary thrust reverser with conical nozzle and plug; modify pylon aft fairing; and remove upper and lower actuators and drive cables. Issued 10/31/77.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012
DC-10-10; T.C. A22WE	SA3580WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 4/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3591WE-D	Installs new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 9/11/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3696WE	Training requirements, special limitations, and installation of required provisions, including communications and equipment to permit occupancy of the lower galley during taxi. Issued 7/12/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA3815WE	Installation of a video projection system. Amended 2/28/79.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10; T.C. A22WE	SA3941WE-D	Installation of a UHF radio telephone system. Issued 6/9/80.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA4041WE	Installation of Litton LTN-211 Omega navigation system. Issued 11/30/79.	WE	85126	Western Airlines, Inc. 6060 Avion Drive Los Angeles, CA 90052
DC-10-10; T.C. A22WE	SA4126WE	Installation of Stowe Corp. entree cart, P/N 10074. Issued 4/9/80.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-10, -10-10F; T.C. A22WE	SA2524WE	Installation of lounge seats, four-place divan, L-shaped bar, and cocktail tables. Amended 3/8/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2770WE	Installation of visual entertainment system. Issued 10/2/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10, -10-10F; T.C. A22WE	SA2924WE	Installation of wheeled refrigerated module, P/N 73011000. Issued 8/27/74.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-10F; T.C. A22WE	SA2948WE	Installation of buffet/bar and bustle assembly. Issued 1/22/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA2985WE	Modification of installed G1 and G1A galleys (Dale P/Ns CAG-11000, CF-10-1, CAG-10000, CF-7000). Issued 1/22/75.	WE	25970	Continental Airlines 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2967WE	Installation of cabin lounge swivel seats and adjustable table with removable top. Issued 1/23/75.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3014WE	Installation of floor game table assembly. Amended 1/20/76.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91100
DC-10-10, -10-10F; T.C. A22WE	SA3212WE	Installation of forward cargo compartment positive vent sump drain. Issued 6/15/76.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3367WE	Installation of nine-abreast coach seating and associated oxygen and electrical system modification. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3368WE	Installation of eight-abreast coach seating in forward cabin behind the first class section, and associated oxygen and electrical system modifications. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-10-10, -10-10F; T.C. A22WE	SA3827WE	Installation of folding leaf table. Issued 1/31/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA3843WE	Installation of Nordskog Ind. galley 1-419. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3844WE	Installation of composites, unlimited coat closet, P/N 225-46103. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Aicport Los Angeles, CA 90009
DC10-10, -10-10F; T.C. A22WE	SA3845WE	Installation of buffet/bar unit, P/N 2142396. Amended 7/11/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
DC-10-10, -10-10F; T.C. A22WE	SA3847WE	Installation of a new lounge and first class accommodations. Amended 7/12/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3848WE	Installation of HITCO refrigerated galley module. Amended 3/16/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-10-10, -10-10F; T.C. A22WE	SA3875WE	Installation of Continental Air Lines flight attendant seat, P/N 225-46317. Issued 3/16/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3937WE	Installation of HITCO storage galley module. Issued 5/18/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-10-10, -10-10F; T.C. A22WE	SA3996WE	Installation of Litton LTN-2110NS. Issued 7/18/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA4058WE	Installation of folding leaf table. Issued 11/8/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
DC-10-10, -10-10F; T.C. A22WE	SA4122WE	Installation of aluminum cabin window plug assembly to replace outer acrylic cabin window pane. Issued 3/24/80.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA4158WE	Installation of Fairchild beverage cart model 79067000. Issued 6/6/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3432WE	Installation of fire/overheat detection system. Amended 2/14/78.	WE	77300	Systron Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3626WE	Revision of DC-10 fire overheat detection system to allow intermixing of Systron-Donner fire detectors with Edison detectors in the fan, core, and pylon sections of the CF6 engines. Issued 4/11/78.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10F, -10-30, -10-30F, -10-40; T.C. A22WE	SA4138WE	Installation of cabin window plug assembly. Issued 4/21/80.	WE	32760	Edwards Enterprises 230 Constitution Drive Menlo Park, CA 94025
DC-10-10, -10-10CF; T.C. A22WE	SA3407WE	Installation of Lermer Apparatebau GMBH beverage cart No. L15701. Issued 5/20/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 91406
DC-10-10, -10-30; T.C. A22WE	SA776SO	Installation of SICMA food tray stowage carts. Amended 3/14/80.	SO	71600	SICMA Aero Seats, Inc. 6929 N.W. 46th Street Miami, FL 33166
DC-10-10, -10-30; T.C. A22WE	ST734SO	Installation of NAL Val-Pack coatroom, P/N 10621-1. Amended 3/30/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-10-10, -10-30; T.C. A22WE	SA2853WE	Retractable tiedown assemblies. Amended 3/23/78.	WE	48550	H. Koch & Sons Koch Road Corte Madera, CA 94925
DC-10-10, -10-30; T.C. A22WE	SA3067WE	Installation of lower lobe food service modules, P/Ns 818720, 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-10-10, -10-30; T.C. A22WE	SA4134WE	Installation of an ARINC communication addressing and reporting system (ACARS). Issued 6/13/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-30; -10-30F; T.C. A22WE	SA2395WE	Installation of coffee bar cart, P/N 801000. Amended 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2774WE	Installation of wing tip mounted emblem lights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2893WE	Installation of Hermes LD-3 Kool-flite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1704-C West 134th Street Gardena, CA 90249
DC-10-10, -10-30, -10-40; T.C. A22WE	SA930EA	Installation of Inflight Motion Pictures, Inc. projection unit assembly DC-10 16mm Tri-Jet system 10300 or light weight Tri-Jet projection system, DC-10 P/N 10307. Amended 9/14/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA947EA	Installation of Inflight Motion Pictures, Inc. screen assemblies. Amended 8/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, New York 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA969EA	Installation of Inflight movie projection assembly P/N 10270, Super 8mm IMPAK system. Issued 11/21/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA990EA	Installation of 16mm projection unit assembly and center stowage bins, P/N 10310. Issued 10/3/74.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA3335WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
DC-10-10, -10-30F; T.C. A22WE	SA2817WE-D	Installation of provisions for ground proximity warning system. Amended 6/26/75.	WE	80500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-10-10, -10-30F; T.C. A22WE	SA2830WE-D	Installation of Collins FPC-75 ground proximity warning system computer. Amended 3/30/76.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10F; T.C. A22WE	SA4006WE	Installation of a 3-place courier seat. Issued 7/31/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10F; T.C. A22WE	SA4156WE	Installation of a two-place courier seat. Issued 5/12/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-30; T.C. A22WE	SA2663WE	Installation of Trans Com movie and projector entertainment system, Model 2420. Issued 3/19/73.	WE	76800	Trans Com A Division of Sundstrand Data Control, Inc. 3100 Pullman Avenue Costa Mesa, CA 92626
DC-10-30; T.C. A22WE	SA2684WE	Installation of Tridair Industries main deck baggage container system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-10-30; T.C. A22WE	SA2707WE	Installation of cabin lounge seats, folding tables, cart stowage unit, and class divider partition. Issued 6/6/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Airport Mail Facility Miami, FL 33159
DC-10-30; T.C. A22WE	SA3194WE	Installation of Airborne video-cassette system. Issued 5/12/76.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA3344WE	Installation of dual Litton LTN-72R INS/RNAV navigation systems. Issued 2/23/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-30; T.C. A22WE	SA3393WE	Installation of Airborne Video-cassette system.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-10-30; T.C. A22WE	SA3569WE	Installation of aircraft video system. Amended 6/5/79.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA4010WE	Installation of video projection system. Issued 10/5/79.	WE	15375	Bell and Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10; T.C. A22WE	SA4070WE	A video projection system is installed. Issued 6/25/80.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA4186WE	Installation of Stowe Corp. liquor cart, P/N 10051-3. Issued 7/22/80.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-30, -10-30F; T.C. A22WE	SA2775WE	Installation of Fairchild Stratos tray carrier rack assembly. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2777WE	Installation of service center (G 1) and coffee bar G-2 assemblies. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2780WE	Installation of serving cart pallets, P/N 989200 and 990100. Issued 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-30F; T.C. A22WE	SA2938WE	Carts and pallet assembly installation. Issued 10/9/74.	WE	28560	Dale Engineering & Development, Inc. 12243 Branford Street Sun Valley, CA 91352
DC-10-30F; T.C. A22WE	SA2949WE	Installation of passenger entertainment/service system. Amended 12/6/74.	WE	33223	Electronic Engineering Company of California 1441 East Chestnut Avenue Santa Ana, CA 92701
DC-10-30F; T.C. A22WE	SA2950WE	Installation of ballast assembly. Issued 11/18/74.	WE	79200	Trans International Airlines Oakland International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA3128WE	Installation of 376 passenger interior arrangement and associated oxygen system modifications. Issued 12/15/75.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA3137WE	Installation of courier seat module assembly. Issued 1/21/76.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA4182WE	Installation of DRIESSEN meal cart in lieu of Nordskag carts P/N's 50193 and 50194. Issued 7/2/80.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
DC-10-30F; T.C. A22WE	SA4197WE	Installation of first class interior arrangement. Issued 7/25/80.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
DC-10-40; T.C. A22WE	SA80GL	Installation of Bendix GPW-83 ground proximity warning systems. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40; T.C. A22WE	SA372GL	Installation of Honeywell P/N HG280BD80 digital airdata computer in the number three position per NWA project 1-34-40300 in place of the Honeywell P/N HG280D5 presently used in this position for data collection purposes only. Issued 10/26/79.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40; T.C. A22WE	SA2782WE	Installation of wheeled refrigerated module P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-40; T.C. A22WE	SA4186WE	Installation of Stowe Corp. liquor cart, P/N 10051-3. Amended 8/18/80.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-40, -10-40F; T.C. A22WE	SA3139WE	Installation of wing and tail engine pods. Amended 3/15/79.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MEYERS INDUSTRIES, INC.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
OTW, OTW145, OTW-KR, OTW160; T.C. A736	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
OTW-145; T.C. A736	SA742CE	Install Warner Super Scarab 165 hp engine and increase gross weight to 1910 pounds.	GL	77750	Tecumseh Aviation Tecumseh, MI 49286
MAC-125C, MAC-145; T.C. 3A1	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 Huntington, L.I., NY 11743
MAC-125C, MAC-145; T.C. 3A1	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
MAC-125C, MAC-145; T.C. 3A1	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69280	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
MAC-145; T.C. 3A1	SA269GL	Installation of Continental O-300-A engine in lieu of Continental C145-2 using original installation hardware and components. No installation data are required. Issued 9/21/78.	GL	41190	Ralph E. Haven Route No. 1 Sherwood, OH 43556

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M20 Series; T.C. 2A3	SA1786WE	Installation of Brittain Industries B-6 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20 Series; T.C. 2A3	SA1787WE	Installation of Brittain NAV-2B flight control. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20, M22 Series; T.C. 2A3, A6SW	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
Mark 20, 20A; T.C. 2A3	SA2666WE	Ceconite 102 material covering of rudder, elevators, ailerons and flaps. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M20, M20A; T.C. 2A3	SA2823SW	Reinforcement of vertical tail spar. Issued 7/31/78.	SW	64407	Harry L. Phillips Route 3, Box 420F Fort Worth, TX 76067
M20, M20A, M20B; T.C. 2A3	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 1758 San Leandro, CA 94577
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D; T.C. 2A3	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amneded 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA4-1210	Installation of Ronnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M20 thru M20F; T.C. 2A3	SA600EA	Installation of electronic voltage alarm.	EA	53500	McKinley Engineering Corporation P.O. Box 275 Palisades Park, NJ 07650
M20, M20A thru M20E; T.C. 2A3	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
M20, M20A thru M20E; T.C. 2A3	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs: SA705SW, SA732SW.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M20, -A, -B, -C, -D, -E, -F, -G; T.C. 2A3	SA1290WE	Installation of "Quasar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 South Curtice Street Littleton, CO 80120
M20, M20A, M20B, M20C, -D, -E, -F; T.C. 2A3	SA1462WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	80120	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
M20, M20A, B, C, D, E, F, G; T.C. 2A3	SA1932SW	Chrome plated disc brakes. Issued 11/27/74.	SW	29580	W.A. DeMaine Route 3, Box 62 Pine Bluff, AR 71601

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M20, M20A, M20B, M20C, M20D, M20E; T.C. 2A3	SA3275WE	Installation of George M. Adams DJA-2000 or Bodell BMI-2000 wheels and Bodell Mfrg. BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
M20, M20A, C, D, E, F, G, J, K; T.C. 2A3	SA4178WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
M20A, M20B, M20C, M20D, M20G; T.C. 2A3	SA1156WE	Installation of Rajay turbosupercharged Lycoming O-360-A1A or -A1D engine. Amended 8/2/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA738EA	Installation of Whelen Engineering Co., Inc. Model HD-14 anti-collision strobe light system.	NE	85500	Whelen Engineering Co., Inc. 3 Winter Avenue Deep River, CT 06417
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light systems. Amended 10/4/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
M20B, C, D, E, F, G; T.C. 2A3	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
M20B, M20C, M20D, M20E, M20F, M20G, Normal Category; T.C. 2A3	SA3938WE	INstallation of flap gap seal. Issued 5/21/79.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
M20B, M20C, M20D, M20E, M20F, M20G; T.C. 2A3	SA4023WE	Installation of flap gap fairings, flap hinge fairings, fuselage fairing at the tail cone, and a plexiglass landing light fairing. Amended 1/17/80.	WE	65015	John A. Porter 29 Walnut Via 501 E. Orangethorpe Avenue Anaheim, CA 92801
M20C, M20D; T.C. 2A3	SA77CE	Installation of McCauley 2D34C53/74E-0 or B2D34C53/74E-0 propeller with D-2809 spinner. Amended 5/24/68.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
M20C, M20D; T.C. 2A3	SA3859WE	Installation of an air/oil separator. Issued 3/12/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
Mooney M20C, M20D, M20E; T.C. 2A3	SA138WE	Installation of Grimes Model D-7080. Rotating beacon on vertical fin. Reissued 3/8/76.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
M20C, M20D, M20G; T.C. 2A3	SA375GL	Installation of Lycoming O-360-A1F6 or O-360-A1F6D in lieu of Lycoming O-360-A1D. Amended 4/18/80.	GL	90152	Louis M. Zeller, Jr. Route 1, Box 298-B Mount Vernon, IN 47620
M20C, M20D, M20G; T.C. 2A3	SA386GL	Installation of McCauley Propellers B2D34C212/78CDA-4, B2D34C212/78CDA-4E, B2D34C214/90DHB-16, B2D34C214/90DHB-16E, using original hardware and components. No installation data are required. Reissued 4/22/80.	GL	90152	Louis M. Zeller, Jr. Route 1, Box 298-B Mount Vernon, IN 47520
M20C (S/N 20-0011 and on - 1974), (S/N 20-1147 and on - 1975), M20E (S/N 21-0025 and on - 1974), (S/N 21-1161 and on - 1975); T.C. 2A3	SA2993WA	Installation of Pathfinder autopilot systems and/or electric pitch trim systems. Issued 2/21/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C (S/N 20-0011 and on), M20E (S/N 21-0025 and on); T.C. 2A3	SA3222WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 11/15/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, M20E; T.C. 2A3	SA4131SW	S-TEC system 60-1 (single axis) flight guidance control system, Model ST-004. Issued 5/27/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
M20C, E, F; T.C. 2A3	SA1938SW	Brittain LSA-6 lateral stability augmentation system (positive control). Issued 1/7/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M20C, E, F, G; T.C. 2A3	SA2207SW	NAV-FLITE II and B-5 flight control systems. Issued 7/23/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20C, E, F, G; T.C. 2A3	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, E, F, G; T.C. 2A3	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, M20E, M20F; T.C. 2A3	SA2654WE	Installation of Pathfinder P2A autopilot system. Amended 4/14/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20E/Super 21; T.C. 2A3	SA999CE	Installation of ERC battery monitor. Issued March 1974.	CE	33229	Electronic Research Company P.O. Box 913 Shawnee Mission, KS 66201
M20E, M20F; T.C. 2A3	SA250GL	Installation of Lycoming IO-360-A1B6 engine in lieu of Lycoming IO-360-A1A engine using original installation hardware and components. No installation data are required. Issued 6/30/78.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA320GL	Installation of Hartzell Model HC-C2YK-1( )F/F7666A-4Q propeller in lieu of Hartzell Model HC-C2YK-1/7666-2 propeller using original installation hardware and components on aircraft previously modified in accordance with STC No. SA250GL. No installation data are required. Issued 6/28/79.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F; T.C. 2A3	SA1411WE	Installation of Rajay turbocharged Lycoming IO-360-A1A engine. Amended 5/9/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20E, M20F, M20J; T.C. 2A3	SA2968WE	Installation of manifold pressure gage/fuel flow meter (fuel pressure gage) in lieu of original gage/meter. Amended 11/20/79.	WE	65015	John A. Porter 29 Walnut Via 501 East Orangethorpe Avenue Anaheim, CA 92801
M20E, M20F, M20J; T.C. 2A3	SA3728WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
M20E, M20F, M20J; T.C. 2A3	SA4065WE	Installation of Silver Instruments fueltron 1G or IP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20F, S/N 22-1179 and up; M20J, S/N 24-0001 and up; T.C. 2A3	SA1212CE	Installation of King KFC 200 2 axis (3 optional) flight control system with KCS 55/55A compass and King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or third axis (yaw damper) only, or manual electric trim only. Amended 9/8/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20F, S/N 22-0013 and on (1974 models), S/N 22-1179 and on (1975 models); T.C. 2A3	SA2986WE	Installation of Pathfinder autopilot systems. Issued 2/19/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20F; T.C. 2A3	SA3047SW-D	Automatic flight system AK523 consisting of Century III autopilot with command automatic electronic pitch trim system and optional radio and glide slope couplers. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3048SW-D	Automatic flight system AK476 consisting of Century IIB autopilot with optional radio coupler. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3049SW-D	Automatic flight system AK475 consisting of Century I autopilot with optional omni tracker. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M20F; T.C. 2A3	SA3064SW-D	Mitchell command electric trim AK541. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3186WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20F; T.C. 2A3	SA4087WE	Installation of Hartzell HC-C2YR-1D/7666A-4Q constant speed propeller. No installation data required. Issued 1/9/80.	WE	52035	Paul E. Loewen P.O. Box 545 Lakeport, CA 95453
M20J; T.C. 2A3	SA1300CE	Installation of Edo-Aire propeller governor Model 34-826-014-11. Amended 1/9/78.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
M20J; T.C. 2A3	SA3307SW-D	Installation of Mitchell automatic flight system AK801 consisting of Century 41 autopilot or Model AK801FD consisting of Century 41 flight director autopilot. Issued 10/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3308SW-D	Installation of Mitchell automatic flight system AK802 consisting of Century 21 autopilot. Issued 10/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J; T.C. 2A3	SA3555WE	Installation of Rajay turbocharged Lycoming IO-360-A3B6D and/or IO-360-A1D6D engines. Issued 12/30/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90801
M20J, M20K; T.C. 2A3	SA300CE	Installation of propeller governors on single and twin engine aircraft, P/N M20J E210490, M20K E210760. Issued 2/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
M20J (24-0939 and up), M20K; T.C. 2A3	SA1464CE	Installation of KFC 200 two axis (three optional) flight control system. Amended 3/3/80.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M20J, M20K; T.C. 2A3	SA1525CE-D	Installation of King KNS 81 digital area navigation system. Issued 1/23/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20K; T.C. 2A3	SA378GL	Installation of Silver Instruments fueltron IG digital fuel flow meter. Reissued 1/3/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20K; T.C. 2A3	SA3325SW-D	Mitchell automatic flight system AK807 consisting of Century 41 autopilot flight director autopilot. Issued 1/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 10145 Judy Street Castro Valley, CA 94546
MK20 Series; MK22 Series; T.C. 2A3, A6SW	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 10145 Judy Street Castro Valley, CA 94546

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MOONEY MITE AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
18 Series; T.C. 803	SA1-353	Delco Remy generator 1101899 and associated plastic cowling.	EA	76100	George W. Strattner 6217 Hedgerow Drive Norfolk, VA 23501
18 Series; T.C. 803	SA3-483	Continental C85-12 engine. Revised April 1973.	CE	16786	W.P. Bilquist Rural Route #2, Box 113 Blue Springs, MO 64015
18 Series; T.C. 803	SA4-1106	Ceconite 101 covering of wings, ailerons, rudder, elevators, horizontal and vertical stabilizers.	WE	26240	Cooper Engineering Company P.O. Box 3820 Van Nuys, CA 91409
18 Series; T.C. 803	SA1044WE	Continental A75-8 65 hp engine and McCauley 1B90-CM/6753 propeller.	WE	03016	Aero-Spec. 240 North Dale Fullerton, CA 92631
18 Series; T.C. 803	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
18 Series; T.C. 803	SA1177WE	WECO carburetor temperature monitor.	WE	88550	Richard P. Winson 21310 Grace Avenue Torrance, CA 90510
18 Series; T.C. 803	SA1-615	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
18 Series; T.C. 803	SA4-302	SR-1 propeller spinner.	WE	75252	Raymond W. Stits 3663 Bloomington Boulevard Riverside, CA 92502
18 Series; T.C. 803	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 344 Altadena, CA 91001
18 Series; T.C. 803	SA1000WE	Poly-fiber covering of wings, fuselage, elevators, ailerons, stabilizers, and rudder. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
M-18C; T.C. A-803	SA71GL	Installation of P/N BA5110 filter assembly. Issued 12/29/77.	CE	17060	Brackett Aircraft Specialties Co. 3600 West 52nd Street Kenosha, WI 53140
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA4-1210	Installation of [illegible] cover on aircraft surfaces. Reissued 8/19/62.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA304EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Porcinelli DBB 1-165 36 Bay Drive East Huntington, L.I., NY 11743
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA409EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Porcinelli DBB 1-165 36 Bay Drive East Huntington, L.I., NY 11743
M-18C, -18C-55, -18L, -18LA;	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M-18C, -18C-55, -18L, -18LA; T.C. A-803	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
M-18C, M-18C55, M-18L, M-18LA; T.C. 803	SA2666WE	Ceconite 102 material covering of wings, ailerons, rudder, elevators, horizontal and vertical stabilizers. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NAVAL AIRCRAFT FACTORY

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Navy N3N-1, N3N-3; T.C. AR-2, 2-569	SA4-1568	Carburetor air intake cleaner on aircraft equipped with Pratt & Whitney R-985 series engines.	WE	73946	Spain-Air, Inc. P.O. Box 263 Dos Palos, CA 93620
Navy N3N-1, N3N-3; T.C. AR-2, 2-569	SA2477WE	Installation of automatic flagman model number 4. Issued 2/14/72.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362
Navy N3N-3; T.C. 2-569	SA4-346	Installation of modified B-13 engine mount.	RM	15300	Ed Beegles Aircraft Service Co. 921 - 22nd Street Greeley, CO 80631
Navy N3N-3; T.C. 2-569	SA4-779	Eonite covering on rudder.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
Navy N3N-3; T.C. 2-569	SA4-983	Quick-change clamping unit.	RM	22200	George Chisholm 317 - 13th Street Greeley, CO 80631
Navy N3N-3; T.C. 2-569	SA4-1210	Installation on Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Navy N3N-3; T.C. 2-569	SA4-1232	Ceconite 101 covering of wings, ailerons, rudder, elevators and horizontal and vertical stabilizers.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
Navy N3N-3; T.C. 2-569	SA4-1313	Hartzell HA-B3Z30-1/10160-6 ground adjustable propeller on aircraft with Pratt & Whitney R985 series engines.	WE	85124	West Coast Propeller Company 1101 Chestnut Street Burbank, CA 91500
Navy N3N-3; T.C. 2-569	SA1008WE	Installation of poly-fiber covering material of lower wings, ailerons, horizontal stabilizer, elevator, rudder. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
Navy N3N-3; T.C. 2-569	SA1135CE	Installation of center float and two outrigger floats. Issued May 1975.	CE	61554	Fred Niedner and Thomas Ahlers No. 1 Westbury Drive St. Charles, MO 63301
Navy N3N-3; T.C. 2-569	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Navy N3N-3; T.C. 2-569	SA1515WE	Installation of Hamilton Standard 3D40/6101A-20 propeller.	WE	85125	Western Aircraft Sales P.O. Box 753 Long Beach, CA 90801
Navy N3N-3; T.C. 2-569	SA2666WE	Ceconite 102 material covering of wings, ailerons, rudder, elevators, horizontal and vertical stabilizers. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
NAVION RANGEMASTER AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Navion Series; T.C. 782	SA1-88	Elimination of carburetor heater muff on aircraft with downdraft cooling systm and Bendix PS5BD carburetor.	EA	21100	Rudolph Chalow RD #1 Newfield, NJ 08344
Navion Series; T.C. 782	SA1-396	Navion retract links 143-33165 and 143-33165-10 modified.	EA	21100	Pudolph Chalow RD #1 Newfield, NJ 08344
Navion Series; I.C. 782	SA1-575	External electrical power receptacle.	EA	41500	Haynes Equipment Co., Inc. 62 Voorhis Lane Hackensack, NJ 07601
Navion Series; T.C. 782	SA1-635	HC-A2x20-4/8433 propeller.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
Navion Series; T.C. 782	SA3-31	Alternate repair parts for bulkhead.	GL	42860	Howard Aviation, Inc. P.O. Box 1287 Peoria, IL 61601
Navion Series; T.C. 782	SA3-60	Bushin in attachment plate hole of Palo Alto it alteration of angle of incidence of horizontal stabilizer.	GL	53580	F.C. McLaughlin P.O. Box 1287 Peoria, IL 61601
Navion Series; T.C. 782	SA3-176	Electric remote compass.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
Navion Series; T.C. 782	SA3-191	Arcon B automatic rudder control. Amended 4/26/66	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
Navion Series; T.C. 782	SA3-492	Window and windshield.	GL	60250	Mt. Hawley Aviation, Inc. Municipal Airport Peoria, IL 61601
Navion Series; T.C. 782	SA3-532	Fabriction and installation of rotating beacon brackets on aircraft with Grimes D-7080-1 light.	GL	60250	Mt. Hawley Aviation, INC. Municipal airport Peoria, IL 61601
Navion Series; T.C. 782	SA4-35	Wing root-fuselage fiberglass contoured fairings at leading edge of wing, and aluminum fairings contoured to existing fillet at inboard end of wing flaps extending aft to station 226.	WE	10235	American Navion Society P.O. Box 2503 Airport STATION Oakland, CA 94614
Navion Series; T.C. 782	SA4-118	Hartzell HC-12X20-7C/8433-0 propeller including governor kit.	WE	30450	Pobert Douthit P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA4-146	Globe gyro-stabilizer.	RM	50258	G.J. Lee, Jr. c/o Boulder Aircraft Boulder, CO 80302
Navion Series; T.C. 782	SA4-229	Retractable step and handle.	WE	30450	Robert Douthit P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA4-241	Change in incidence angle of horizontal stabilizer for Symons Engineering kit.	WE	77262	M.W. Symons Engineering Company 490 Nort Prairie Avenue Hawthorne, CA 90250
Navion Series; T.C. 782	SA4-313	Toe brake kit and parking brake.	WE	30450	Robert Douthit P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA4-363	Autopilot and optional "add-on" coupler BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA4-685	Aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Crporation 4069 Hollis Street Oakland, CA 94608

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Navion Series; T.C. 782	SA4-915	Installation of Brittain Mark II 20-gallon wing tip tanks (P/N 2009). Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank & Supply Star Route, Box 12 Oro Grande, CA 92368
Navion Series; T.C. 782	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
Navion Series; T.C. 782	SA4-1007	Installation of balance weights (Brittain Aircraft P/N 3010) on leading edge of Navion ailerons. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank & Supply Star Route, Box 12 Oro Grande, CA 92368
Navion Series; T.C. 782	SA4-1432	Fiberglass vertical stabilizer tip assembly ANS 0001 and Grimes rotating beacon G-8400A-8-12 or D-7080-1-12.	WE	10235	American Navion Society P.O. Box 2503 Airport Station Oakland, CA 94614
Navion Series; T.C. 782	SA4-1483	Fiberglass vertical fin tip and Grimes rotating beacon F-7080-1-12 or G-8400A-8-12.	WE	30450	Robert Douthit P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA4-1626	Fiberglass nose wheel streamlined fairing.	WE	30450	Robert Douthit & J.H. Ellis P.O. Box 795 El Centro, CA 92243
Navion Series; T.C. 782	SA36CE	Zip tip wing tips.	GL	79954	Tuscola Flying Service Route 2 Tuscola, IL 61953
Navion Series; T.C. 782	SA143SO	Control wheel.	SO	37086	Garcia Aviation Company 15801 Southwest 120th Avenue Miami, FL 33101
Navion Series; T.C. 782	SA162EA	Navion retract link assembly 145-34106.	EA	21100	Rudolph Chalow RD #1 Newfield, NJ 08344
Navion Series; T.C. 782	SA179WE	Main landing gear retract link assembly ANS 0003.	WE	10235	American Navion Society P.O. Box 2503 Airport Station Oakland, CA 94614
Navion Series; T.C. 782	SA200CE	Nose and main gear retracting link replacement.	GL	85147	Western Michigan Repair Service 3315 East Milham Avenue Kalamazoo, MI 49001
Navion Series; T.C. 782	SA249EA	Airborne mechanisms dry vacuum pump and regulator.	EA	85600	Edward J. White 207 Stephen Drive Cinnaminson, NJ 08077
Navion Series; T.C. 782	SA252WE	Nose landing gear retract link assembly ANS 0004.	WE	10235	American Navion Society P.O. Box 2503 Airport Station Oakland, CA 94614
Navion Series; T.C. 762	SA268SW	Automatic pilot AK116.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion Series; T.C. 782	SA278SO	Main and nose landing gear retract links.	SO	36765	William E. Freeman 570 Milligan Drive Stone Mountain, GA 30083
Navion Series; T.C. 782	SA292CE	Nose gear shimy damper.	GL	50370	Libersky Aero Service Municipal Airport Worthington, MN 56187
Navion Series; T.C. 782	SA298SW	Autopilot AF-512A or AF-512B.	EA	05950	Aircraft Radio Corporation Rockaway Valley Road P.O. Box 150 Boonton, NJ 07005
Navion Series; T.C. 782	SA299SW	Autopilot AF-510A.	EA	05950	Aircraft Radio Corporation Rockaway Valley Road P.O. Box 150 Boonton, NJ 07005
Navion Series; T.C. 782	SA334SW	Alternator.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216
Navion Series; T.C. 782	SA374WE	Modified carburetor air intake system.	WE	37875	Donald G. Gifford P.O. Box 474 Lodi, CA 95240
Navion Series; T.C. 782	SA543SW	Turbosupercharger.	SW	09250	Alcor Aviation, Inc. 2905 Bandera Road San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Navion Series; T.C. 782	SA570WE	Exhaust system.	WE	79427	Ted Stanke Municipal Airport Banning, CA 92220
Navion Series; T.C. 782	SA604WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold and NAV-1 navigation. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA644WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA750SW	Tip tank fairings and drain cover.	SW	70000	Sagefield Aircraft Service 1433 Northwest 7th Street Grand Prairie, TX 75050
Navion Series; T.C. 782	SA751SW	Nose gear doors and fixed main gear wheel fairings.	SW	70000	Sagefield Aircraft Service 1433 Northwest 7th Street Grand Prairie, TX 75050
Navion Series; T.C. 782	SA752WE	Lycoming GO-480-BID engine and Hartzell HC-82X20/9333C-3 propeller.	WE	51800	Bart N. Locanthi 2180 Pinecrest Drive Altadena, CA 91001
Navion Series; T.C. 782	SA758WE	Navion main landing gear wheel and axle modification.	WE	61990	H. Sanford Osborne Star Route, Box 12 Oro Grande, CA 92368
Navion Series; T.C. 782	SA769WE	Lear Romec fuel pump R6-15980 on Continental E-185-3 engine.	WE	87805	Wright Brothers, Inc. 401 Newhall Street San Jose, CA 95110
Navion Series; T.C. 782	SA878WE	N-2 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
Navion Series; T.C. 782	SA1488WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA1512WE	Installation of exhaust gas temperature monitoring system, Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Navion Series; T.C. 782	SA1579WE	Installation of Brittain Industries B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion Series; T.C. 782	SA1678WE	Installation of Brittain B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tuls, OK 74151
Navion Series; T.C. 782	SA2120WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Navion, Navion A, B, D; T.C. 782	SA4-1165	Installation of Firestone Model DFA-180 or Bodell BMI-2000 wheel in lieu of Firestone 6C5 or Goodrich 613MD wheel on nose gear. Amended 8/8/79.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
Navion (L-17A), Navion A, B, D, E, F, G, H; T.C. A-782	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
Navion (L-17A), Navion A (L-17B), (L-17C); T.C. A-782	SA3935WE	Installation of an air/oil separator. Issued 5/15/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
Navion, Navion A, B; T.C. 782	SA4022WE	Installation of toe brakes and revised rudder pedals at pilot station. Issued 8/30/79.	WE	50259	Eugene Leedy P.O. Box 816 Benning, CA 92220

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Navion A; T.C. A-782	SA253GL	Installation of a Continental E-225-4 engine modified in accordance with STC SE23SW, in lieu of a Continental E-225-4 which was installed. Issued 7/21/78.	GL	37079	Montie Gainey 1407 South Kitley Avenue Indianapolis, IN 46203
Navion A; T.C. A782	SA695CE	Install Frantz oil filter.	GL	70360	Donald R. Schmidt Schmidt Aero Service Worthington, MN 56187
Navion A; T.C. A782	SA1246WE	Alternator kit 6555-2 and 6555-2-2, "Jasco". Amended 10/28/76.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
Navion A; T.C. A782	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
Navion A; T.C. A782	SA2946WE	Istallation of new design cabin air valve. Issued 10/25/74.	WE	50250	Eugene Leedy 1011 DeGarmo Street San Fernando, CA 91340
Navion A; T.C. A782	SA3077SW-D	Mitchell auto flight system AK553 consisting of Century I autopilot with omni tracker. Issued 10/20/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion A, B; T.C. 782	SA1124SW	Modified wing tips.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
Navion A, B, C, D, E, F, G, H; T.C. A-782	SA54WE	Installation of single-piece windshield and side windows. Reissued 8/1/73.	WE	19200	Cal Aero Industries, Inc. 3521 East Spring Street Long Beach, CA 90806
Navion A, B, D, E, F, G (A & B with optional engine); T.C. A-782	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
Navion A, B, D, E, F, G; T.C. A-782	SA1582WE	Installation of control position indicator (CPI) system. Reissued 3/12/70.	NW	80685	United Control Corporation Overlake Industrial Park Redmond, WA 98052
Navion A, B, D, E, F, G, H; T.C. A-782	SA36GL	Install Cleveland Aircraft Products wheel and brake conversion kit, P/N 199-52. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
Navion A, B, D, E, F, G, H; T.C. A-782	SA46GL	Install Cleveland Aircraft Products wheel and brake conversion kit, P/N 199-52A. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
Navion A, B, D, E, F, G, H; T.C. A-782	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
Navion A, D, E, F, G; T.C. A-782	SA589WE	Installation of full flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
Navion A, D, E, F, G, H; T.C. A-782	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly treet Littleton, CO 80120
Navion A, B, D, E, F, G, H; T.C. A-782	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot. Amended 5/9/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Road Torrance, CA 90505
Navion A, B, D, E, F, G, H; T.C. A-782	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot. Amended 5/9/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Road Torrance, CA 90505
Navion A,B, D, E, F, G. H normal and utility category; T.C. A-782	SA3638WE	Installation of new air induction system with a filter on the alternate air source. Issued 5/3/78.	WE	30450	Robert Douthitt P.O. Box 795 El Centro, CA 92243

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Navion A, B, D, E, F, G, H; T.C. A-782	SA3639WE	Installation of warning light intended to prevent inadvertent operation of the aircraft on the aircraft on the tip tank fuel system while in the landing or take-off configuration, i.e., gear down. Issued 5/3/78.	WE	30450	Robert Douthitt P.O. Box 795 El Centro, CA 92243
Navion A, B, D, E, G, H; T.C. A-782	SA3640WE	Installation of flap lower close out strip. Issued 5/3/78.	WE	30450	Robert Douthitt P.O. Box 795 El Centro, CA 92243
Navion A, B, D, E, F, G, H; T.C. A-782	SA3786WE	Installation of tubular engine mount, cowling cooling baffles, air induction system and cowl flap mechanism. Issued 12/4/78.	WE	37081	GAMA Enterprises P.O. Box 55 Fawnskin, CA 92333
Navion, Navion A thru F; T.C. A-782	SA3821WE	Installation of single piece windshield, canopy side and rear windows. Issued 2/29/80.	WE	50259	Leedy Aviation P.O. Box 816 Banning, CA 92228
Navion A, B, C, D, E, F, G, H; T.C. A-782	SA3936WE	Installation of an air/oil separator. Issued 6/1/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
Navion A, B, E, F, G; T.C. A-782	SA4154WE	Installation of tubular engine mount, cowling, cooling baffles, air induction system and cowl flap mechanism. Issued 4/10/80.	WE	37081	Gama Enterprises P.O. Box 55 Fawnskin, CA 92333
Navion B; T.C. A-782	SA4-1121	Increase in allowable gross weight from 2850 to 3100 pounds per STC SA4-915 when equipped with 20 gallon wing-tip tanks (Brittain Aircraft P/N 1000). Reissued 2/2/71.	WE	62000	H. S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
Navion B; T.C. A-782	SA308EA	Istallation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Navion B; T.C. A-782	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Navion B; T.C. A-782	SA3447WE	Installation of steel engine mounting brackets. Issued 7/1/77.	WE	50250	Eugene Leedy P.O. Box 816 Banning, CA 92220
Navion G, H; T.C. A-782	SA2654WE	Installation of Pathfinder Model P2A autopilot. Amended 5/31/74.	WE	12380	Astronautics Crp. of America 2416 Amsler Road Torrance, CA 90505
Navion G, H; T.C. A-782	SA2961WE	Installation of Pathfinder autopilot systems and/or electric pitch trim systems. Issued 2/24/75.	WE	12380	Astronautics Corp. of America 2416 Asler Road Torrance, CA 90505
Navion G, H; T.C. A782	SA3224SW-D	Mitchell automatic flight system AK701 consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion G, H; T.C. A782	SA3225SW-D	Mitchell automatic flight system AK704 consisting of Century IIB autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Navion H; T.C. A-782	SA1190CE	Installation of King KFC 200 flight control system (2 axis). Issued April 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NELSON AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BB-1; GTC 19	SG4-1240	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NIHON AEROPLANE MANUFACTURING CO., INC.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
YS-11, -11A: T.C. A1PC	ST424SO	Installation of replacement radome assembly.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11, -11A; T.C. A1PC	SA863EA	Incorporation of Chromalloy Electronics Division ESL-1 or ESL-6 emergency slide lighting system. Reissued 3/6/73.	SO	22225	Chromalloy Electronics Div. of Chromalloy American Corp. 3901 North 29th Avenue Hollywood, FL 33020
YS-11, -11A; T.C. A1PC	SA2728WE	Incorporation of Holcombe Industries Hi-Lite system (P/N 50-1001) for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
YS-11, -11A-200, -11A-300, -11A-500, -11A-600; T.C. A1PC	SA460GL	Installation of pneumatic de-icers, P/Ns 21S-2056-10-1, -10-2, -11-1, -11-2. Issued 10/20/80.	GL	38500	B.F. Goodrich Engineered Products Group 500 South Main Street Akron, OH 44318
YS-11, -11A-200, -300, -500, -600; T.C. A1PC	SA1198EA	Installation of a Safeway deicer overshoe P/N 5939 on Dowty Rotol propeller, model R209/4-40-4.5/2. Issued 6/23/80.	EA	70830	Semsa, Inc. 2125 Smithtown Avenue Ronkonkoma, NY 11779
YS-11A Series; T.C. A1PC	SA393SO	Install Goodyear 9540512 wheels in place of Goodyear 9543138 wheels.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series; T.C. A1PC	SA1175SO	Installation of pitot heat indication system. Issued 10/10/80.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A; T.C. A1PC	SA4110SW	Installation of Dynamic Air Engineering air condition system. Issued 4/22/80.	SW	07740	Air Freight International, Inc. P.O. Box 2 Addison, TX 75001
YS-11-A200; T.C. A1PC	SA1949WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach,CA 90807
YS-11A-200, -300, -500, -600; T.C. A1PC	ST487SO	Installation of P.P.G. manufactured main windshields, P/Ns 5613-00001 (L/H) and 5613-00002 (R/H) and Barber Colman P/N HYLZ 8882 temperture controller. Amended 2/22/74.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500; T.C. A1PC	ST486SO	Installation of external APU control panel. Amended 2/16/72.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500; T.C. A1PC	ST866SO	Installation of Bendix ground proximity warning system. Amended 11/20/75.	SO	64500	Piedmont Aviaton, Inc. P.O. Box 2720 Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A, -500; T.C. A1PC	SA2910SW	Unpressurized cargo door in rear left hand portion of fuselage. Amended 5/9/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A Series 500; T.C. A1PC	SA3873WE	Installation of bleed air heating system. Amended 8/17/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A-500; T.C. A1PC	SA4094SW	Aft cargo door between F.S. 636.2 and 758.9 between floorline and stringer 27 and associated structural changes. Issued 3/3/80.	SW	07740	Air Freighters Int'l, Inc. P.O. Box 2 Addison, TX 75001
YS-11A-600; T.C. A1PC	SA3047WE	Installation of provisions only for ground proximity warning system. Issued 5/28/75.	WE	87450	World Airways, Inc. Maintenance & Engineering Center Oakland International Airport Oakland, CA 94614
YS-11A-626; T.C. A1PC	SA78NW	Cabin modiication. Issued October 1973.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NORTH AMERICAN AVIATION, INC., OHIO

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BC-1A, AT-6 Series; TT-6G; T.C. 2-575	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennge and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 288 Altadena,CA 91001
BC-1A, AT-6 Series; T-6G; T.C. 2-575	SA1008WE	Poly-Fiber covering of left elevator and right aileron. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
BC-1A, AT-6, -6A, -6B, -6D, -6F, SNJ-7, -6G; T.C. 2-575	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC-1A, AT-6, SNJ Series, T-6G; T.C. 2-575	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC-1A, AT-6, -6A, -6B, -6C, -6D, -6F, T-6G; T.C. 2-575	SA1351WE	Replace existing fabric on wings, fuelage, empennage, and/or control surface with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC-1A, AT-6, -6A, -6B, -6C, -6D, -6F, T-6G; T.C. 2-575	SA2666WE	Ceconite 102 material covering of rudder, elevators and ailerons. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
AT-6 Series; T.C. 2-575	SA4-764	Application of glass cloth to ailerons and elevators.	WE	38060	Slasco-Air Products Oxnard-Ventura Airport Oxnard, CA 93030
AT-6 Series; T.C. 2-575	SA4-859	Ceconite 101 covering of rudder, elevators and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3420 Van Nuys, CA 91406
AT-6 Series; T.C. 2-575	SA283SO	Glass-cloth wing tip caps.	SO	26580	Corben Development Corp. P.O. Box 1603 Venice, FL 33595
AT-6, -6A, -6B, -6C, -6D, -6F, T-6G; T.C. A-2-575	SA1521WE	Installation of metal covering on ailerons, elevators and rudder. Reissued 6/8/79.	WE	47732	Ken Aero 6960 Curran Street Brownfield Int'l Airport San Diego, CA 92173
AT-6, -6A, -6B, -6C, -6D, -6F, SNJ-7, T-6G; T.C. A-2-575	SA2814WE	Installation of Hamilton Standard 3D40 225/6101A-10 propeller. Issued 2/5/74.	WE	70100	Santa Monica Propeler Service 3025 Airport Boulevard Santa Monica, CA 90405
AT-6D (SNJ-5); AT-6F (SNJ-6), T-6G, SNJ-7, AT-6C (SNJ-4); T.C. A-2-575	SA3091SW-D	Mitchell automatic flight system AK520 consisting of Century III autopilot with optional radio coupler. Issued 12/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral wells, TX 76067
AT-6D (SNJ-5), AT-F (SNJ-5), AT-6F (SNJ-6), T-6G, SNJ-7, AT-6C (SNJ-4); T.C. A-2-575	SA3092SW-D	Mitchell automatic flight system, AK464, consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral wells, TX 76067

SUMMARY OF FEDERAL AVIATION ADMINISTRATION SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PIPER AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
J-2, J3, J4, PA-16, -18, -19, -22 Series; T.C. 595, 692, 703, 1A1, 1A2, 1A6	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
J2, J3, J4, J5A, PA-12; ATC 595, 660, T.C. A-703, A-725, A-780	SA582NW	Fabrication of wire ropes. Issued 5/12/78.	NW	81180	Unitersity Swedging 7001 Perimeter Road Seatlle, WA 98108
J2, J3C-40, -50, -50S, -65, -65S, PA-11, -11S, J3F-50, -50S, -60, -60S, -65, -65S, J3L, -S, -65, -65S, J4, J4A, J4A-S, J4B, J4E, J4F, J5A, J5A-80, J5B, J5C, AE-1, HE-1, PA-12, -12S, PA-14, PA-15, PA-17, PA-16, -16S, PA-18, -18A, -18S, -18-105, -18S-105, -18-125, -18AS-125, -18S-125, -18-135, -18A-135, -18AS-135, -18S-135, -18-150, -18AS-150, -18S-150, PA-19, -19S, Restricted Category PA-18A, -18A-135, -150, PA-20, -20S, -20-115, -20S-115, -20-135, -20S-135, PA-22, -22-103, -22-135, -22S-135, -22-150, -22S-150, -22-160, -22S-160, PA-25, -25-235; AIC 595, T.C. 691, 692, 698, 703, 708, 740, 724, 725, 780, 797, 800, 805, 1A1, 1A2, AR-7, 1A4, 1A6, 2A8, 2A10	SA2666WE	Ceconite 102 material covering of: J3C, J3F, PA-11, J3L Series - wings, fuselage, ailerons, elevator, rudder, horizontal and vertical stabilizer; PA-12, -12S, -15, -17, PA-18 Series, PA-19, -19S, PA-20 Series, PA-25 Series, J4 Series, J5 Series, J2 - complete aircraft; PA-14 - wings, fuselage and vertical fin; PA-16, -16S - wings, fuselage, ailerons, elevator and rudder; PA-22 Series - fuselage, wings, horizontal and vertical stabilizer, ailerons, flaps, rudder and elevator. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J3 Series; T.C. 691	SA1-423	Sensenich M74CK-2 fixed pitch metal propeller.	EA	39486	Robert A. Greimel 2571 Iverson Street, SE Washington, D.C. 20003
J3 Series; T.C. 691	SA1-497	Franklin 4AC-176-F3 engine.	GL	73330	Jimmie Snodgrass and William S. Cross P.O. Box 158 Racine, OH 45771
J3 Series; T.C. 691	SA3-111	Wing modification.	CE	36754	Roy M. Frazier Route 1 Chillicothe, MO 64601
J3 Series; T.C. 691	SA3-514	Modification to exhaust and carburetor air preheater muff systems and installation of exhaust stack shields on cowling.	GL	41170	George F. Haveman Home Acres Sky Ranch Lake City, MI 49651
J3 Series; T.C. 691	SA187AL	Install Continental C-90 and PA-18-95 cowl and baffles.	AL	08325	Air Power Overhaul P.O. Box 6025 Airport Annex Anchorage, AK 99502
J3 Series; T.C. 691	SA254CE	Model A fiberglass floats.	GL	39480	Greenwood Fiberglass Company Manitou Beach, MI 49253
J3 Series; T.C. 691	SA322CE	Manufacture hitch and bracket. Install tow hitch. Amended 5/6/71.	CE	76500	Stubben-McCandless South Omaha Airport Route 1 Papillion, NE 68046
J-3 Series; A.T.C. 660	SA309GL	Installation of Continental A65-8 engine and Sensenich module 72CK propeller (wood). Issued 5/18/79.	GL	14870	Bartlet Avaition, Inc. 5600 Portage Road Kalamazoo, MI 49002

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
J3 Series; T.C. 691	SA357CE	Model B fiberglass floats.	GL	39480	Greenwood Fiberglass Company 2690 Geneva Highway Manitou Beach, MI 49253
J3 Series; T.C. 691	SA8118W	Clip wings and install Continental A-75-8 engine.	SW	66450	Keith P. Rawe 418 Willow Lane Baytown, TX 77520
J3 Series; T.C. 691	SA1251WE	Belt-driven 35A or 55A alternator on Continental A-65-8 engines.	WE	37877	Gifford-Sherman Company 2000 Hawkins Way Spring Valley, CA 92077
J-3, J3 Series; T.C. 660, 691, 692, 698, 695	SA4-469	Application of glass cloth with resin.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
J-3, J3C-40, 50, 50S, 65, 65S, PA-11, -11S, J3F-50, 50S, 60, 60S, 65, 65S, J3L, -S, -65, -65S, J3P, J4, J4A, J4AS, J4B, E, F, J5A, -80, J5B, J5C, AE-1, HE-1, PA-12, -12S, PA-14, PA-15, PA-16, -16S, PA-18, -18A, -18S, -18"105", -"105S", -"125", PA-18AS"125", -18S"125", -18A"135", -18AS"135", -18S"135", -18"150", -18AS"150", -18S"150", PA-19, -19S, PA-20, -20S, -20"115", -20S"115", -20-"135", -20S"135", PA-22, -22-108, -22-135, -22S"135", -22"150", -22S"150", -22"160", -22S"160", PA-25, -25-235, -260; T.C. 660, 691, 692, 698, 695, 703, 708, 740, 721, 725, 780, 800, A797, 1A1, 1A2, AR-7, 1A4, 1A6, 2A8, 2A10	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J-3, J3, J4, J5, PA-11, -12, -14, -15, -17, -18, -19 Series; T.C. 660, 691, 692, 698, 695, 703, 708, 740, 721, 725, 780, 797, 800, 805, 1A2	SA5-9	25x11x4 tires and tubes with Airglass Engineering Company adapters LWA 950.	AL	69740	Safeway Airways P.O. Box 1062 Anchorage, AK 99500
J-3, PA-11, -12, -14, -16, -18, -20, -22 Series; T.C. 660, 691, 692, 698, 780, 797, 1A1, 1A2, 1A4, 1A6	SA5-13	Installation of 8.50x6 tires and tubes with Hayes 6-inch wheels. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622
J-3, PA-11, PA-12, -14, -16, -18, -20, -22 Series; T.C. 660, 691, 692, 698, 780, 797, 1A1, 1A2, 1A4, 1A6	SA5-13	Installation of 8.50x6 tires and tubes with Hayes 6-inch wheels. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
J3, J3C-65, -65S, PA-11, -11S, J4A, J4AS, J5A, J5A-80, PA-17, PA-18, PA-19; T.C. 703, 725, 805, 1A2	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
J-3, J3, J4, J5A, PA-11, -12, -14, -15, -16, -17, -18, -20 Series; T.C. 660, 691, 703, 725, 780, 797, 800, 1A1, 805, 1A2, 1A4	SA95AL	Maule SFS-1-4-P8 tail wheel; Hayes D-15-26 brake assembly using Kennedy Air Service adapter 64-1; Hayes wheel assembly D3-105MD; and 800x6, 850x6 or 900x6 4-ply tires and tubes.	AL	47744	Kennedy Air Service P.O. Box 94 Valdez, AK 99686
J3, J4, J5, PA-11, -12, -14, -15, -16, -17, -18, -19, -20 Series; T.C. 691, 692, 698, 703, 740, 725, 780, 797, 800, 1A1, 805, 1A2, 1A4	SA99AL	Six-inch wheels and brakes.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-14; T.C. 797	SA688AL	Installation of left side cabin door. Issued 7/16/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA690AL	Increase gross weight to 1,935 lbs. Issued 7/8/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA3213WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avneue Torrance, CA 90501
PA-14, PA-18, PA-20; T.C. 797, 1A2, 1A4	SA41AL	Six inch wheels and brakes.	GL	56570	Wesley W. Mathias 154 North Broad Street Bremen, OH 43107
PA-15; T.C. 800	SA1-619	Continental A-65-8F engine and McCauley 1A90CF-7147 propeller.	NE	39514	Griswold Air Service Griswold Airport Madison, CT 06443
PA-15; T.C. 800	SA4-1225	Eonite covering on complete aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-15; T.C. 800	SA69AL	Installation of fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-15; T.C. 800	SA3214WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-15, PA-17; T.C. 800, 805	SA4-1025	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-16 Series; T.C. 1A1	SA1-577	Installation of Sensenich controllable pitch propeller Model CS3FM4/C374E. Amended 6/24/70.	EA	64268	Theodore J. Peters County Line Road, RD 3 Sommerville, NJ 08876
PA-16 Series; T.C. 1A1	SA4-900	Ceconite 101 covering of wings, fuselage, ailerons, elevator and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-16 Series; T.C. 1A1	SA399AL	Conversion of 4" wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-16 Series; T.C. 1A1	SA412NW	Replace original equipment expander-tube brakes with new Cleveland wheels and brakes. Issued 3/3/77.	NW	00300	Michael J. Abdo 9415 Lexington Avenue, S.W. Tacoma, WA 98498
PA-16 Series; T.C. 1A1	SA3215WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-16, -16S; T.C. 1A1	SA447AL	Installation of auxiliary fuel tanks in right wing. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-16, -16A; PA-18, PA-18S, "105", "125", "135", "150"; "PA-18A"135", "150:"; PA-18AS"125", "135", "150"; PA-19S; PA-23, -23-160, -235, -23-250; PA-24, -24-250, -260; PA-28-140, 150, 160, 180, -235, PA-28-S-160, -S-180; PA-30; T.C. 1A1, 1A2, 1A10, 1A15, A1EA, 2A13	SA630WE	Installation of Coast Winslow Filter Corporation 409 series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-282	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-327	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16S; T.C. 1A1	SA384AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/17/70.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-17 Series; T.C. 805	SA4-483	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-17 Series; T.C. 805	SA446AL	Installation of fuel tanks. Amended 2/7/75.	AL	17000	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-17 Series; T.C. 805	SA3216WE	Installation of George M. Adams OGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-18 Series; T.C. 1A2	SA425AL	Installation of removable seat back support. Issued 4/23/71.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99503
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18 Series; T.C. 1A2	SA526AL	Build up 1-1/4" axle to 1-1/2" axle to install Celveland wheel and brake. Issued 8/7/74.	AL	68436	Bill Robek Box 10-214 Klatt Station ANchorage, AK 99502
PA-18 Series; T.C. 1A2	SA540AL	Installation of modified landing gear with main gear legs lengthened 6 inches. Issued 2/19/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18; T.C. 1A2	SA682AL	Installation of 160 hp Lycoming O-320. Issued 6/26/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18; T.C. 1A2	SA1586CE	Modified brake master cylinder. Issued 5/9/80.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-18 Series; T.C. 1A2, AR-7	SA1-32	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
t+1 PA-18 Series; T.C. 1A2, AR-7	SA1-41	McCauley fixed pitch MET-L-PROP 1A170/GM7450, 1A170/GM7452 and 1A170/GM7454 propellers with Lycoming O-320-A1A engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-59	McCauley fixed pitch MET-L-PROP 1A170/GM7448 and 1A170/GM7450 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-155	McCauley fixed pitch MET-L-PROP 1A170/GM7448 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell AVenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	'SA1-156	McCauley fixed pitch MET-L-PROP 1A170/GM7446 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-349	Glider tow. Amended 5/12/67.	EA	70400	Schweizer Aircraft Corporation Box 147, County Airport Elmira, NY 14902
PA-18 Series; T.C. 1A2, AR-7	SA4-254	Hartzell HC82XG-6/7636D-4 propeller Lycoming 70385 dual drive assembly, Woodward 210115 single acting governor and J-6230-1 lord mount assembly.	WE	15415	Ellen Belotti 1208 East Charleston Road Las Vegas, NV 89114

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18S"125", PA-18S-135, 18S-150; T.C. 1A2	SA879EA	Installation of Edo Model 88A-1650 seaplane floats with Edo Model 088A21 attachment gear. Reissued 4/1/76.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
PA-18S-125, -150; T.C. 1A2	SA1099WE	Install fiberglass reinforced plastic floats. Reissued 9/20/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
PA-18-135; T.C. 1A2, AR-7	SA1-33	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine. Amended 9/5/75.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-18-135, -18A-135, -18S-135, -18AS-135, -18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA279AL	Installation of McCauley 1A175/GM propeller on -135 models listed and installation of McCauley 1A175/GM 8241 through GM 8244 on the -150 models listed. Amended 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-135, -18A-135, -18-150; T.C. 1A2	SA518CE	Install Aqua Model 1900 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research and Engineering, Inc. 805 Geiger Road Zephryhills, FL 33599
PA-18"135", -18A"135", -18S-"135", -18AS"125", -18"150", -18A-"150", -18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622
PA-18"135", -18A"135", -18S-"135", -18AS"135", -18"150", -18A-"150", '18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1333CE	Installation of replacement engine mount. Issued June 1977.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1366CE	Installation of a third seat, removable cross member, and reinforced baggage compartment floor. Issued 8/26/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18-135, -150, PA-20, PA-22, PA-23, PA-24 less 24-180, -24-280, -24-400, PA-25, PA-28 less -28-140, PA-28-180, -235, PA-30, PA-31, PA-32, PA-34, PA-39; T.C. 1A2, 1A4, 1A6, 1A10, 1A15, 2A8, 2A10, 2A13, A1EA, A8EA, A3SO, 1A10, A1EA	SA1512WE	Installation of exhaust gas temperature monitoring system Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18-135, -150, PA-22, PA-23, PA-24, -24-400, PA-28, -28-235, PA-30, PA-31, PA-32; T.C. 1A2, 1A6, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18A-135, PA-18A-150; T.C. 1A2	SA1368CE	Cabin metalization; installation of new boot cowl, firewall, swing up side windows, larger baggage door, and inspection access in aft fuselage. Issued 9/12/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18S-135; T.C. 1A2	SA288AL	Install McCauley 1A175-GM8040 or 1A175-GM8044 propeller. Amended 4/2/69.	GL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645
PA-18-150; T.C. 1A2	SA36RM	Installation of Lycoming O-360-C2A or O-360-A3A 180 hp engine. Issued 11/22/74.	RM	46780	David C. Johnson 10850 Thomas Road Colorado Springs, CO 80908
PA-18-150; T.C. 1A2	SA532AL	Installation of Lycoming O-360-A2A engine. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18"150"; T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-18"150"; T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18-150; T.C. 1A2	SA590AL	Install extended baggage compartment. Issued 7/2/76.	AL	39250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18-150; T.C. 1A2	SA596AL	Install Hartzell propeller Model HC-C2YL-1BF/F8468-8R. Issued 3/4/77.	AL	30250	Atlee R. Dodge P.O. Box 6409 Anchorage, AK 99509
PA-18-150; T.C. 1A2	SA612AL	Extended ailerons. Issued 5/25/77.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18"150", -18A"150", -18S"150", -18AS"150"; T.C. 1A2	SA4-1143	Installation of Lycoming O-320-A3B engine and Hartzell HC-82XL-6B/7636D-2 propeller. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
PA-18"150", -18A"150"; T.C. 1A2	SA92NW	Installation of Lycoming O-360-A2D engine, McCauley 1A200-FA8241 propeller, and associated sub-systems. Issued 3/1/74.	NW	32756	Ed's Aviation Service P.O. Box 156 Arlington, WA 98223
PA-18"150", -18A"150"; T.C. 1A2	SA109CE	Installation of Pee-Kay Model 1800 floats. Reissued 6/12/74.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-150, -18A-150; T.C. 1A2	SA349AL	Installation of McCauley 1A175-GM 8242, GM8244, or GM8246 propeller. Amended 4/10/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-18-150, -18A-150; T.C. 1A2	SA353AL	Installation of Sorensen Aircraft Co. 60-gallon belly tank. Revised 2/12/71.	AL	76900	Superior Airmotive of Alaska, Inc. 2301 Merrill Field Drive Anchorage, AK 99501
PA-18"150", -18A"150"; T.C. 1A2	SA693AL	Installation of McCauley 1A175/GM8244 propeller. Issued 8/19/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150", -18A"150"; T.C. 1A2	SA694AL	Oil radiator installation. Issued 8/26/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA"18"150", PA"18A"150"; T.C. 1A2, AR-7	SA575WE	Belly master spray system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-18-150, -18A-150; T.C. 1A2	SA589AL	Install square horizontal stabilizers, elevators, and rudder. Issued 6/28/76.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA284AL	Installation of Hartzell propeller with Woodward 2100-80-RS governor. Amended 10/30/75.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA510AL	Installation of "Summer-all defroster valve". Issued 1/10/74.	AL	76738	Sumrall & Tears 3001 Yale Drive Anchorage, AK 99504
PA-18"150", PA-18S"150"; T.C. 1A2	SA648AL	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150", PA-18A"150", PA-18S"150", PA-18AS"150"; T.C. 1A2	SA649AL	Fabricate 30.5 gallon wing fuel tanks. Issued 8/17/78.	AL	30250	F. Atlee Dodge Box 4609 Anchorage, AK 99502
PA-18A-150; T.C. 1A2	SA623AL	Install wing tip assembly.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18A"150"; T.C. 1A2	SA1370CE	Revised fuel gaging and dual fuel feed line installation from both tanks. Two wing fuel tanks standard. Issued 11/18/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18S-150, 18AS-150; T.C. 1A2	SA392AL	Installation of McCauley 1A175 GM8242, 8244, or 8246 propeller. Amended 9/24/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-20 Series; T.C. 1A4	SA1-89	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engines.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-20 Series; T.C. 1A4	SA1-157	McCauley fixed pitch MET-L-PROP 1A170/GM7450 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-20 Series; T.C. 1A4	SA1-167	Lycoming O-320 150 hp engine, Sensenich M-74DM propeller, Piper PA-22-150 engine baffles, and and Harrison AP13SJ03-01 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamsport, PA 17701
PA-20 Series; T.C. 1A4	SA4-564	Eonite covering on wings, fuselage and control surfaces.	WE	52090	William C. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
t+1 PA-20 Series; T.C. 1A4	SA4-778	Ceconite covering.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-20 Series; T.C. 1A4	SA12RM	Installation of Light Plane Components landing gear vee assembly, P/N LPC 1012. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-20 Series; T.C. 1A4	SA31CE	Removal of rear left door and installation of placard.	CE	50725	Lincoln Sport Parachute Club, Inc. 929 Furnas Avenue Lincoln, NE 68501
PA-20 Series; T.C. 1A4	SA73CE	Covering with dacron of wings, fuselage, tail group, flaps, all control surfaces, or any of these individually.	GL	30518	Downer Aircraft Company P.O. Box 46 Alexandria, MN 56308
PA-20 Series; T.C. 1A4	SA211WE	Removal of left-hand cabin door for parachute jumping and aerial photography operations.	RM	38040	Glacier View Skyways, Inc. P.O. Box 252 Kalispell, MT 59901
PA-20; T.C. 1A4	SA224GL	Install Gerdes control wheels, Model No. A-1561-C and A-1562-C utilizing AN3-12 bolts (2), AN3-65 self-locking nuts (2) and AC-940-316 washers(2). Issued 2/15/78.	GL	64950	Matthew C. Poleski 25 Immelnan Lane Hampshire, IL 60140
PA-20 Series; T.C. 1A4	SA278WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-20 Series; T.C. 1A4	SA509AL	addition of crankcase relief valve. Issued 11/16/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-20 Series; T.C. 1A4	SA542AL	Installation of leading edge cuff. Amended 3/4/77.	AL	27250	Crosswinds, Inc. 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20 Series; T.C. 1A4	SA671WE	BN-1 propeller spinner.	WE	75250	Raymond M. Stits 3665 Rubidoux Boulevard Riverside, CA 92502
PA-20 Series; T.C. 1A4	SA3217WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-20, PA-20-115, -20-135; T.C. 1A4	SA12AL	Installation of auxiliary fuel tank(s). Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2350 East Fifth Avenue Anchorage, AK 99501
PA-20 Landplane, -20-115, -135; T.C. 1A4	SA25EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lycons, WI 53148
PA-20, -20S; T.C. 1A4	SA125AL	Installation of squared off wing tips and end plates. Amended 12/1/65.	AL	61640	Northland Aviation P.O. Box 3143 Fairbanks, AK 99702

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-20-115, -135; T.C. 1A4	SA401AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-20, PA-20S, -20-115, -20S-115, -20-135, -20S-135, and these models modified by STC SA1-167 (150 HP Lycoming O-320 engine); T.C. 1A4	SA396GL	Installation of Aero Ski wheel replacement skis in accordance with the following: 1) Model M1800 and M2000 skis, 2) Model M3000H skis. Issued 4/18/80.	GL	02750	Aero Ski Manufacturing Co., Inc. Box 346 Park Rapids, MN 56470
PA-20, -20S, -20"115", -20S-"115", -20-"135", -20S-"135"; T.C. 1A4	SA479AL	Installation of fiberglass wing tips. Issued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-20, -20S, -20"115", -20S-"115", -20-"135", -20S-"135"; T.C. 1A4	SA479AL	Installation of fiberglass wing tips. Issued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-20, -20-115, -135, PA-20S, -20S-115, -135; T.C. 1A4	SA626AL	Install fiberglass wing tip assembly. Issued 3/21/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20, -115, -20S, -20S-115, -135, -20S-135; PA-22, -135, 22S-135, -150, 22S-150, -160, 22S-160, -108; PA-24, -250, -400, -260; PA28-140, -150, -160, -180, -235, S-160, S-180, R-180; PA-30; PA-32-260, -300, 32S-300; T.C. 1A4, 1A6, 1A15, 2A13, A1EA, A3SO	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
PA-20, PA-20"115", -"135", PA-20S"115", -"135", PA-22, 22-108, -135, -150, -160, 22S-135, -150, -160; T.C. 1A6	SA2142WE	Installation of DASCO heated pitot tube kit No. 2022-12.	WE	30129	Diversified Aviation Service Co. 20499 Santa Maria Avenue Castro Valley, CA 94546
PA-20, PA-20-"135"; T.C. 1A4	SA635AL	Install Avco Lycoming O-320-A2B engine and Sensenich propeller. Issued 6/6/78.	EA	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20-115, -20-135, PA-22, -22-135, -150, -160, -180, PA-23, -23-160, PA-24 S/N 1 thru 1476, PA24-250 S/N 1 thru 1476; T.C. 1A4	SA71GL	PA-20's install BA4106 filter assembly, PA-22's install BA4016 filter assembly, PA-23's, -24 install BA-3110 filter assembly, PA-24-250 install BA-3210 Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities Co. 9600 West 52nd Street Kenoska, WI 53140
PA-20-135; T.C. 1A4	SA1-24	McCauley fixed pitch MET-L-PROP Models 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine. Reissued 8/5/77.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-20S, PA-20-115, -22-135; T.C. 1A4	SA118GL	Installation of Huron Aviation Products alternator, P/N 10346 and regulator, P/N 10316. Amended 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-20S, 20S-115, 20S-135, PA-20S*; T.C. 1A4	SA385AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/21/70. *This approval includes PA20S models with Lycoming O-320, 150 hp engine installed per an appropriate STC.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20S, -20S*, -115*, -135*; T.C. 1A4	SA387AL	Installation of McCauley 1A175GM8241 propeller. Issued 7/23/70. *Aircraft must be equipped with Edo 88-1650 floats and modified in accordance with STC SA1-167.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20S-115, -125; T.C. 1A4	SA388AL	Installation of Edo 88-1650 floats (Spec item 209(a)) when modified per STC SA1-167 and SA387AL. Issued 8/3/70.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20, PA-22 Series; T.C. 1A6	SA1-132	24ST alclad on wings.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-20, PA-22 Series; T.C. 1A6	SA1-133	24ST alclad skin on flaps.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-20, PA-22 Series; T.C. 1A6	SA1-325	Replacement of fabric covering with metal skins, ailerons and flaps.	EA	72100	Skycraft Design, Inc. P.O. Box 67 West Trenton, NJ 08628
PA-20, PA-22 Series; T.C. 1A6	SA1-492	Metallizing of wing panel excluding aileron and flap.	NE	27770	Custom Aircraft Industries 30 Broad Street Pascoag, RI 02859
PA-20, PA-22; T.C. 1A4, 1A6	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
PA-20, PA-22 Series; T.C. 1A6	SA1487WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA1-22	McCauley fixed pitch propellers 1A170/GM7459 and 1A170/GM7457 with Lycoming O-320 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-23	McCauley fixed pitch propellers 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-90	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-108	69A110 gyro stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
PA-22 Series; T.C. 1A6	SA1-128	Dry vacuum pump 113A1 for counter-clockwise engine accessory drive and 113A2 for clockwise drive, or 10-113-1 and 10-113-2.	GL	66380	Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
PA-22 Series; T.C. 1A6	SA1-131	Dural angles and 24ST alclad skin on fuselage.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-22 Series; T.C. 1A6	SA1-255	Dart I-M turn control unit.	EA	61400	Navigation Devices, Inc. P.O. Box 1107 Binghamton, NY 13902
PA-22 Series; T.C. 1A6	SA1-275	Lycoming O-320 150 hp engine and Sensenich M74DM propeller, Piper PA-22-150 engine baffles, Harrison AP13SJ03 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamport, PA 17701
PA-22 Series; T.C. 1A6	SA1-337	Oil-free vacuum pump PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-22 Series; T.C. 1A6	SA1-386	Installation of heated pitot tube.	EA	34180	Federal Aviation Administration Engineering & Manufacturing Branch Federal Building, EA-210 JFK International Airport Jamaica, NY 11430
PA-22 Series; T.C. 1A6	SA3-77	Vertical fin plates attached to tip ribs of horizontal stabilizer for seaplane operation only.	GL	60092	Modern Die & Tool Company 227 Iron Street Detroit, MI 48233
PA-22 Series; T.C. 1A6	SA3-143	Grimes D7080-12 rotating beacon on fuselage access panel.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
PA-22 Series; T.C. 1A6	SA3-363	Installation of Doyn fiberglass wheel fairings. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
PA-22 Series; T.C. 1A6	SA3-382	Manually operated oil cooler shutter assembly.	CE	65020	Ken L. Potter 13831 Botts Road Grandview, MO 64030
PA-22 Series; T.C. 1A6	SA3-477	C2200 (hydraulically actuated) main and AWN1200A nose wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-22 Series; T.C. 1A6	SA3-494	C2200 (manually actuated) main and AWN1200A nose wheel -skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-22 Series; T.C. 1A6	SA3-631	Dacron cover.	GL	30518	Downer Aircraft Industries, Inc. Municipal Airport Alexandria, MN 56308
PA-22 Series; T.C. 1A6	SA3-639	Removal of rear door, operation with door removed, and reinstallation of door.	CE	50715	Lincoln Aviation Inst., Inc. P.O. Box 4168, Havelock Station Lincoln, NE 68529
PA-22 Series; T.C. 1A6	SA4-114	Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-22 Series; T.C. 1A6	SA4-222	Fiberglass covering.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
PA-22 Series; T.C. 1A6	SA4-298	Fuselage structural alterations and additions to provide for the installation of Fairchild Aviation aerial camera A5A or similar.	WE	62063	Pacific Aero Industries Municipal Airport San Jose, CA 95125
PA-22 Series; T.C. 1A6	SA4-343	"B" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-22 Series; T.C. 1A6	SA4-391	Fiberglass wheel fenders.	NW	85550	Art Whitaker Pearson Field Vancouver, WA 98660
PA-22 Series; T.C. 1A6	SA4-423	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA4-815	Lycoming O-320 engine and Sensenich M74DM propeller.	NW	53200	McKenzie Aircraft Repair 1300 North 27th Street Springfield, OR 97477
PA-22 Series; T.C. 1A6	SA4-871	Aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-22 Series; T.C. 1A6	SA4-903	Ceconite 101 covering of fuselage, wings, horizontal and vertical stabilizer, ailerons, flaps, rudder and elevator.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-22 Series; T.C. 1A6	SA4-938	Eonite covering on entire aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-22 Series; T.C. 1A6	SA4-998	Installation of wheel fairings. Reissued 2/9/71.	NW	12565	Aurora Air, Inc. d/b/a Madras Air Service Madras, OR 97741
PA-22 Series; T.C. 1A6	SA4-1346	Fiberglass cover on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
PA-22 Series; T.C. 1A6	SA4-1502	AB-6564 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-22 Series; T.C. 1A6	SA4-1587	Retractable wheel fairing on main landing gear.	WE	30708	Duce Aircraft Company R.R. 4, Box 711 Valley Center, CA 92082
PA-22 Series; T.C. 1A6	SA4-1621	Removal of left-hand door for parachute jumping and aerial photography.	WE	19856	Capitol Sky Park, Inc. Municipal Airport Sacramento, CA 95855
PA-22 Series; T.C. 1A6	SA5-30	Rear door removed.	AL	69740	Safeway Airways P.O. Box 1062, Merrill Field Anchorage, AK 99500
PA-22 Series; T.C. 1A6	SA48AL	L1650A or L2000A skis.	AL	08125	Airglas Engineering P.O. Box 1254 Anchorage, AK 99502
PA-22 Series; T.C. 1A6	SA60CE	Model 1800 floats installed, Pee-Kay. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-22 Series; T.C. 1A6	SA91AL	Change of brake system to disc type as used on PA-22-108 by changing brake parts.	AL	75500	Stoddard Aero SErvice 2550 East Fifth Avenue Anchorage, AK 99501
PA-22 Series; T.C. 1A6	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-22 Series; T.C. 1A6	SA143EA	Univair Aeromatic F-200H/0074E propeller on aircraft utilizing Lycoming O-320 or O-320-A1A engine.	EA	53160	George A. McIntosh 435 Van Cortlandt Park Avenue Yonkers, NY 10705
PA-22 Series; T.C. 1A6	SA145CE	APU receptacle under the right front seat to the right of battery box.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis, MO 63155
PA-22 Series; T.C. 1A6	SA157CE	Jump seat baggage compartments.	CE	14270	Baker's Flying Service, Inc. 1025 Lou Holland Drive Municipal Airport Kansas City, MO 64108
PA-22 Series; T.C. 1A6	SA247SO	Removal of door during operation of aircraft.	SO	43260	W.E. Huckabee, Jr. 424 South Green Street Thomaston, GA 30286
PA-22 Series; T.C. 1A6	SA314SO	Lycoming O-290-D engine.	SO	54450	M & M Flyers Bessemer, AL 35020
PA-22 Series; T.C. 1A6	SA447WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
PA-22 Series; T.C. 1A6	SA448CE	Prestolite ALK-5000 alternator.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
PA-22 Series; T.C. 1A6	SA461WE	Removal of right-hand door for parachute jumping and aerial photography operations.	NW	42138	Hillsboro Aviation Hillsboro, OR 97123
PA-22 Series; T.C. 1A6	SA481WE	Lycoming O-320-A1A engine and Sensenich M74DM propeller.	RM	47758	Kensair Corporation P.O. Box 332 County Airport Broomfield, CO 80020
PA-22 series; T.C. 1A6	SA666WE	Edo 88-1650 floats with Harrison oil cooler AP13SJ03-01 or AP12CU03-01, bottom engine cowl assembly 13159-8, side engine cowl 14237, reinforced fuselage 12480 and Sensenich M74DM or M76AM-2 propellers.	NW	36002	Floathaven Seaplane Base 2095 South Lake Whatcom Boulevard Bellingham, WA 98225
PA-22 Series; T.C. 1A6	SA819SW	Extended wing and fuselage.	SW	71776	Simpson Aviation Company P.O. Box 126 Gilliam, LA 71029
PA-22 Series; T.C. 1A6	SA1360CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, MO 66103
PA-22, PA-22-108, -135, -150, -22S-150, -22-160, -22S-160; T.C. 1A6 t+1	SA1-604	Installation of Aerostat external power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-22, -22-108 (Normal Category Only - All Models), -22-135, -150, -160; T.C. 1A6	SA45RM	Conversion from tri-cycle landing gear (nose wheel) to conventional landing gear (tail wheel). Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-22, PA-22-108, -135, -150, -160; T.C. 1A6	SA232GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-22, -22-108, -22-135, -22S-135, -22-150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA395GL	Installation of Aero Ski wheel in accordance with the following: 1) Model M180 and M2000 skis 2) Model M3000H skis. Issued 4/18/80.	GL	02750	Aero Ski Manufacturing Co., Inc. Box 346 Park Rapids, MN 56470
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA625AL	Install fiberglass wing tip assembly. Issued 3/27/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-22, -22-108, -22-135, -22-150, -22-160, -22S-150, -22S-160; T.C. 2A6	SA536AL	Installation of auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-22, -22-135, -150, -160; T.C. 1A6	SA26EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-22-108, -135, -22S-135, -22-150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA40EA	Wet-to-dry vacuum pump conversion kit 300-1. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-22, -22-108 (Normal Category only - all models), -22-135, -22-150, -22-160; T.C. 1A6	SA181RM	Installation of Lycoming Model O-360-A4A engine and Sensenich Model 76EM8-60 propeller. Issued 8/2/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-108; T.C. 1A6	SA847EA	Installation of Lycoming O-320-A (150 hp) or O-320-B (160 hp) engine. Amended 4/7/78.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-108, -135, -150, PA-23, -23-250, PA-24, -24-250, -260, -400, PA-28-140, -150, -160, -180, -235, PA-30; T.C. 1A6, 1A10, 1A15, 2A13, A1EA	SA1202WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
PA-22, -22-135; T.C. 1A6	SA1-274	Installation of Lycoming O-320 (150 hp) series engine and Sensenich M74DM propeller. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-135; T.C. 1A6	SA3-709	Install Piper control modification kit, P/N 754-174.	GL	51770	Richard E. Lloyd Lloyd Flying Service Schaumburg Airport, Box 79B Roselle, IL 60172
PA-22-108, -135, -150, -160 (landplane only - normal category only); T.C. 1A6	SA4-1263	Installation of conventional landing gear. Reissued and amended 12/4/79.	WE	52543	Lucas Aircraft 1125 Terrace Drive Napa, CA 94558
PA-22-150; T.C. 1A6	SA545AL	Installation of leading edge cuff. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-150; T.C. 1A6	SA703CE	Install aileron and wing fences and booster tips per STC SA573SW. Issued 5/19/70.	GL	22210	Dr. Edward W. Chrencik 29 9th Avenue North Hopkins, MN 55343
PA-22S-150; T.C. 1A6	SA297AL	Installation of McCauley 1A175 GM8241 propeller.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-22-160; T.C. 1A6	SA95NW	Installation of Lycoming O-360-A1A engine, McCauley 1A200-FA8248 propeller, and associates sub-systems. Issued 3/11/74.	NW	61680	Northwest Aero Aircraft Services 2036 West Bakerview Road Bellingham, WA 98225
PA-22, PA-23, PA-24 Series; T.C. 1A6, 1A10, 1A15	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ 85642
PA-23 Series; T.C. 1A10	SA1-5	Unfeathering system change to HC-82XL-2/7636D-4 or HC-A2XL-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
PA-23 Series; T.C. 1A10	SA1-6	Unfeathering system change to HC-82XG-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
PA-23 Series; T.C. 1A10	SA1-28	Radio rack limited to 30 pounds of radio equipment.	GL	03600	Airborne Communications, Inc. Lunken Airport Cincinnati, OH 45275

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA1-53	Conversion to Goodyear 6.50-8 wheels (9531319) and brakes (9531779).	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-103	Radio-shelf.	GL	72494	Skyways, Inc. P.O. Box 175 Vandalia, OH 45377
PA-23 Series; T.C. 1A10	SA1-117	Propeller anti-icing kit.	NE	96000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA1-120	F-300 automatic pilot.	GL	04750	Aircraft Components, Inc. 715 Woodward Avenue Benton Harbor, MI 49022
PA-23 Series; T.C. 1A10	SA1-137	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 6/7/72.	GL	14124	Aeronics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA1-169	Reinforcement of floor structure between fuselage station 91-1/2 and 123-3/4 and provision for tie-down facilities.	GL	60485	A.R. Mehlhauser 1602 Emerson Avenue (N.C.B.) Cincinnati, OH 45239
PA-23 Series; T.C. 1A10	SA1-177	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-299	Oil-free vacuum PA-201.	GL	11000	[illegible] Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45015
PA-23 Series; T.C. 1A10	SA1-468	Six or 13 quart propeller anti-icing kit WAP-101A, revision 3.	NE	96000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA1-484	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-485	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-534	Lightweight reservoir type deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-548	SP-3 autopilot EB2597034.	EA	74590	Sperry Rand Corporation MacArthur Field Ronkonkoma, NY 11779
PA-23 Series; T.C. 1A10	SA1-586	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-23 Series; T.C. 1A10	SA3-94	Narco 1016 antenna and/or remote compass transmitter, equipment shelf, oxygen bottle mounting.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705
PA-23 Series; T.C. 1A10	SA3-158	Radio power pack on bulkhead forward of instrument panel.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705
PA-23 Series; T.C. 1A10	SA3-334	Installation of aerial camera provisions. Reissued 1/31/80.	SW	26230	Cooper Airmotive Aircraft Services 3300 Love Field Drive Dallas, TX 75235
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-handy hydrotrim aileron trim device.	GL	30465	Kingsley A. Doutt 115 West Maple Street Alpena, MI 49707 AND
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-hand hydrotrim aileron trim device.	GL	64262	Charles L. Petch Hubbard Lake, MI 49747
PA-23 Series; T.C. 1A10	SA3-509	L-2B autopilot with or without altitude control and approach coupler.	EA	16038	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204

AIRCRAFT MAKE, MODEL 6 T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA3-564	Propeller unfeathering accumulator.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA3-641	Cabin air temperature control system.	GL	82500	Vap-Air Division Vapor Corporation 6444 West Howard Street Chicago, IL 60607
PA-23 Series; T.C. 1A10	SA3-644	Adams Rite 2302 rev. C-2 handle on inside of cabin door.	CE	65301	Product Development Group 2522 East Douglas Wichita, KS 67202
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers and increase gross weight to 3,684 lbs.	CE	56868	Galen D. Means 847 Watson Lane Wichita, KS 67201
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers and increase gross weight to 3,684 lbs.	SW	67016	AND Jackson M. Reed 607 North Peters Norman, OK 73069
PA-23 Series; T.C. 1A10	SA4-299	Windows at station 144.	WE	39877	Hamilton Aircraft Company, Inc. 6501 South Park Avenue Tucson, AZ 85706
PA-23 Series; T.C. 1A10	SA4-345	"B" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-23 Series; T.C. 1A10	SA4-522	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA4-652	Full flow aerofilter kit 3-1A101.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-23 Series; T.C. 1A10	SA4-783	Lycoming 150 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-23 Series; T.C. 1A10	SA4-994	Installation of Firestone Model DFA-233 wheel assemblies, Model CFA-299 brake assemblies and 6.50x8 6-ply tires.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1016	Lycoming 160 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-23 Series; T.C. 1A10	SA4-1131	SP-3 autopilot, less altitude and navigation hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85000
PA-23 Series; T.C. 1A10	SA4-1166	Installation of Firestone Model DFA-180 wheel.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1602	Dorsal fin.	RM	60280	Mountain States Aviation, Inc. Stapleton Field Denver, CO 80202
PA-23 Series; T.C. 1A10	SA2WE	Fuel pressure warning lights.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
PA-23 Series; T.C. 1A10	SA47CE	Governor 210413.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA65EA	One Aerojet-General 15NS-250 aircraft rocket engine on underside of fuselage on airplane centerline aft of main spar wing and relocation of cabin air intake scoop assembly.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361
PA-23 Series; T.C. 1A10	SA69SW	Extended nose with baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA100SW	Automatic pilot AK114.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA114SW	Combustion monitor.	EA	60100	Monitair Corporation Ramapo Valley Airport Spring Valley, NY 10977

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA140SW	Cabin window addition.	SW	61500	Hayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA172EA	Reinforcement of rearmost seat and installation of additional safety belt.	EA	16804	Walter E. Hoffman, Jr. Birchwood Lodges & Cottages East Stroudsburg, PA 18301
PA-23 Series; T.C. 1A10	SA202SO	Fyr-Fyter 23-4, 2 1/2 lb., dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA219EA	Installation of Katz integrated flight indicator Model KIFI-2 or KIFI-2A. Amended 5/21/69.	NE	36300	Forest City Aviation Services, Inc. 749 Congress Street Portland, ME 04102
PA-23 Series; T.C. 1A10	SA226EA	Added structure aft of cabin area.	EA	67000	Reding Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23 Series; T.C. 1A10	SA232EA	Installation of Tactair omni lock Model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair model omni lock Model OL-1). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA242SO	Two-place couch.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA243EA	13-quart propeller anti-icing kit WAP-102.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA244SO	PA-23-250 wing root and nacelle fairings.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA250WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA266SO	Modification of fuel cap 16097-00 by making a new cover and enlarging the lower vent hole. Rework fuel cell filler neck door 19049-06 by putting a spring loading vent in the door to be used as auxiliary vent during icing conditions.	SO	12700	Avco Corporation Aerospace Structures Division Nashville, TN 37202
PA-23 Series; T.C. 1A10	SA268WE	Sixth seat and emergency exit.	WE	60095	Monarch Aviation Associates P.O. Box 527 Monterey, CA 93940
PA-23 Series; T.C. 1A10	SA280SW	Forward fuselage section and long nose 30542-02.	SW	79794	Tulsa Airmotive, Inc. P.O. Box 176 Broken Arrow, OK 74012
PA-23 Series; T.C. 1A10	SA309WE	Non-icing fuel tank vents.	WE	06750	Aircraft Tank Service, Inc. 1201 Cohasset Street Burbank, CA 91504
PA-23 Series; T.C. 1A10	SA311SW	Alternate static source.	SW	71800	Sinclair Oil & Gas Company Aviation Department, Box 521 Tulsa, OK 74101
PA-23 Series; T.C. 1A10	SA319EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA337EA	Conversion of aircraft electrical system to 24 volt.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23 Series; T.C. 1A10	SA339SW	Electrical hydraulic pump. Reissued 9/20/77.	SW	90142	The Zee Company, Inc. 123 Braniff Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA363SW	Pitch trim system AK128.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA371SW	Fiberglass nose cone.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA372EA	Automatic flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-23 Series; T.C. 1A10	SA376WE	Left and right third window.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA387WE	Sixth seat and escape hatch.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA394WE	Replacement engine nose cowls.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA395WE	Lycoming O-360-A1A engines and Hartzell HC-C2YK-2R/7666-2 propellers.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA412WE	One-piece windshield.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA417SW	Rear baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA423SW	Fiberglass landing gear doors.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA461SW	Ramshorn type control wheel.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA462SW	One-piece windshield.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA463SW	Landing gear wheel well doors.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA465SW	Pitch trim system AK148.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA471CE	Dorsal fin.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23 Series; T.C. 1A10	SA476SW	Pitch trim system AK151.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA484SW	Large baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA497SW	Fiberglass engine nose cowl.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA498SW	Dual brakes.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA499SW	Engine nacelle and fuselage wing root fairings.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA504WE	11016 fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA523SW	Automatic trim system AK165.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA539WE	Turbosupercharged Lycoming IO-540-C1B5 or -C1C5 engine. Amended 6/14/66.	WE	66250	Rajay Corporation 2062 East Wardlow Road Long Beach, CA 90807

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA540SW	Piper auto-control III Model AK162 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA551WE	Installation of Brittain Model B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA557SW	Fiberglass nose cone.	SW	44930	J & G Aero Company P.O. Box 3031 Tyler, TX 75701
PA-23 Series; T.C. 1A10	SA566SW	AK184 automatic flight system, AK185 stabilizer, and AK188 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA574SW	Rear baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA580SW	Modified engine mounts.	SW	67650	RFB Company, Inc. Chandler Field Purcell, OK 73080
PA-23 Series; T.C. 1A10	SA590SW	Gross weight increased.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA597SW	Extended nose with baggage compartment. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA598SW	Wheel well doors. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA599SW	Fiberglass engine nose cowls.	SW	59500	James W. Miller 6517 Moss Oak San Antonio, TX 78229
PA-23 Series; T.C. 1A10	SA600SW	Nacelle and wing root fairings. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA605SW	Rear baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA612SW	Square wing tips. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA613SW	Dorsal fin and square tip fin and rudder. Amended 7/31/68.	SW	50500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA614WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA615WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A0	SA616WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA617WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA636SW	MOdified nose, gear doors, nacelle fairings, and wing tips.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA671SW	Dorsal fin and square rudder.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA697SW	One-piece windshield. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA698SW	Rear picture window.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78114
PA-23 Series; T.C. 1A10	SA747SW	Pitch trim AK228 (manual).	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA764WE	Aztec "B" nose section.	RM	08315	Airport Development Corp. 5120 West Rowland Avenue Littleton, CO 80120
PA-23 Series; T.C. 1A10	SA774SW	Franklin 6A-350-C1 engines, McCauley 2AF31C10/84SF-8 propeller increase gross weight 3675 lbs. takeoff, 3500 lbs. landing. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA803SW	Dual brakes. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA824WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA852WE	Turbosupercharged Lycoming O-540-A1B5, -A1D5, or -A3D5 engines (S/N's 27-1 thru 27-2504).	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA867SW	Lycoming O-540-A1D5 engines.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA882EA	Installation of supplemental strobe light Grimes P/N 30-0437-100. Amended 5/2/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23 Series; T.C. 1A10	SA909WE	Turbosupercharged Lycoming IO-540-J4A5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA953SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23 Series; T.C. 1A10	SA978WE	Turbosupercharged Lycoming IO-540-C4B5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA1076CE	Installation of Halon 1301 cabin fire extinguishing system and engine nacelle fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64105
PA-23 Series; T.C. 1A10	SA1348WE	B-4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA1480WE	Installation of an integral 24 gallon auxiliary fuel tank in each wing tip.	WE	58500	Met-Co-Aire 3848 Campus Drive Newport Beach, CA 92660
PA-23 Series; T.C. 1A10	SA1486WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA2914WE	Installation of improved rudder trim tab actuating rod. Issued 8/13/74.	WE	13800	Aviation Research Corporation P.O. Box 718 Santa Ynez, CA 93460
PA-23, -23-160; T.C. 1A10	SA4-1637	Installation of turbosupercharged Lycoming O-320-A or -B series engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23, -23-160; T.C. 1A10	SA2CE	Installation of Doyn Model 1600 dorsal fin. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23, PA-23-160; T.C. 1A10	SA285CE	Lycoming IO-360-B1B engines and Hartzell HC-C2YK-2PA/7666A-2 propellers. Gross weight increase to 3,684 lbs. on PA-23 and to 4,000 lbs. on PA-23-160. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23, -23-160; T.C. 1A10	SA802CE	Alter tip of vertical fin and rudder. Amended August 1976.	CE	60174	J.J. Morelli Route 1, Box 138 Platte City, MO 64079
PA-23, -23-160; T.C. 1A10	SA897SW	Fiberglass propeller spinners. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA898SW	Revised engine cowling. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA1260WE	Installation of turbosupercharged Lycoming O-360-A1A or A1D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23, -23-160; T.C. 1A10	SA1306SW	Lycoming IO-360-C1C engines with Hartzell HC-C2YK-2/C7666A-4 propellers with gross weight increase. Issued 5/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23, -23-160; T.C. 1A10	SA2793SW	Rudder hinge reinforcing bracket. Issued 6/7/78.	SW	70750	Seguin Aviation, Inc. 2075 Highway 46 Seguin, TX 78155
PA-23, -23-160; T.C. 1A10	SA3099SW-D	Mitchell automatic flight system AK587 consisting of Century I autopilot with optional omni tracker. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3100SW-D	Mitchell automatic flight system AK588 consisting of Century III with optional radio coupler and glide slope coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3101SW-D	Mitchell automatic flight system AK586 consisting of Century IIB autopilot with optional radio coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160, -23-235, -23-250, PA-24, -24-250, -24-400, PA-28-150, -28-160, -28-180, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, PA-23-235, PA-23-250; T.C. 1A10	SA136EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, -235, -250; T.C. 1A10	SA236CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-23, -23-160, -23-235; T.C. 1A10	SA317EA	Radome kit No. 2025K-B for Bendix RDR-100 or RDR-110 series radar systems with 12-inch antenna per Chamberlain installation. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23, -23-160, -235, PA-25; T.C. 1A10	SA362SW	Rear baggage compartment. Reissued 4/24/79.	SW	70750	Seguin Aviation 2075 Highway 46 Seguin, TX 78155
PA-23, -160, -235; T.C. 1A10	SA398CE	Install Hoskins twilighter Mk III supplemental lighting system consisting of Model F wing lights with Model P or K (dual) tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
PA-23, 23-160, 23-235, 23-250; PA-24, -24-250, -260, -400; PA-31, -31P; T.C. A8EA, 1A10, 1A15	SA660WE	Installation of HRD-type fire extinguishing system. Amended 7/11/77.	WE	43190	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91015
PA-23, -160, -235; T.C. 1A10	SA894SW	Nacelle saddleback. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23-160, -235, -250; PA-30, PA-39; T.C. 1A10, A1EA	SA890EA	Installation of Grimes three light strobe kit P/N 34-0101-2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23, -23-160, -23-235, -23-250, -E23-250, PA-24, -24-250, -24-260, -24-400, PA-28-140, -28-150, -28-160, -28-180, -28-235, -28S-160, -28S-180, -28R-180, -28R-200, PA-30, PA-39, PA-32-260, -32-300, -32S-300, PA-30, PA-39; T.C. 1A10, 1A15, 2A13, A1EA, A3SO	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light system two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 11/30/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23, -160, -235, -250; PA-24-180, -250, -400; *PA-28-140, -150, -160, -180, -235; *PA-31; T.C. 1A10, 2A13, A8EA	SA1290WE	Installation of "Quazar" high intensity supplemental exterior flashing lights. Amended 11/25/69. *Approved anti-collision light system is required.	RM	66000	Radair, Inc. 5665 South Curtis Street Littleton, CO 80120
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SW	67016	AND Jackson M. Reed 607 North Peters Street Norman, OK 73069
PA-23-160; T.C. 1A10	SA47SO	Installation of one-piece instrument panel.	SW	68145	Riley International Corporation 6211 West Northwest Highway Dallas, TX 75225
PA-23-160; T.C. 1A10	SA68NW	Installation of cargo door on right side of fuselage. Issued 10/30/73.	SO	70280	Elbridge P. Sawyer P.O. Box 148 Dayton, OH 37321
PA-23-160, -235, -250; T.C. 1A10	SA162SW	Cabin emergency exit window and sixth seat. Reissued 10/3/78.	SW	70750	Seguin Aviation, Inc. 2075 Highway 46 Seguin, TX 78155
PA-23-160; T.C. 1A10	SA272CE	Installation of Lycoming IO-360-B1A engines and Hartzell HC-C2YK-2RA/7666A-2 propellers. Gross weight increase to 4000 lbs. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-235; T.C. 2A10	SA1136SW	Fiberglass fuselage shell.	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
PA-23-235; T.C. 2A10	SA1205SW	Manual electric trim AK268. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235; T.C. 2A10	SA1746WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23-235; T.C. 2A10	SA1847WE	Installation of Brittain up-command signal adapter kit. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23-235, -250; T.C. 1A10	SA495CE	Installation of Hartzell Model HC-A3XK-2B/7636D-4 three-bladed propellers.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23-235, PA-23-250; T.C. 1A10	SA530WE	Installation of Rajay turbosupercharged Lycoming IO-540-C1B5 or C1C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23-235, -23-250; T.C. 1A10	SA1315SW	Dorsal fin. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-235, -23-250; T.C. 1A10	SA1361CE	Chrome plated brake disc installation. Issued 3/6/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA155EA	Install B.F. Goodrich pneumatic de-icing system. Amended 8/10/79.	GL	38500	B.F. Goodrich Engineered Systems Company 500 South Main Street Akron, OH 44318

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA921SW	Mitchell automatic flight system AK242 consisting of Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1091SW	Mitchell automatic flight director system FD/AP 282-184 consisting of flight director, automatic pilot, auto-flite AK 185.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, -23-250, -E23-50, Serial Nos. 27-1 thru 27-4573; T.C. 1A10	SA1124EA	Installation of enlarged cargo door. Reissued 8/25/78.	EA	26683	Courtesy Air Service, Inc. P.O. Box 561 Warren County Airport Glen Falls, NY 12801
PA-23-235, -23-250 (S/N 271 thru 27-7554172), PA-E23-250 (S/N 27-2505 thru 27-7554172), PA-23-250 (Model "F") (S/N 27-7654001 and up); T.C. 1A10	SA1126EA	Installation of DeVore vertical tail floodlights on upper surface of stabilator. Reissued 9/28/78.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street Albuquerque, NM 87109
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1262SW	Mitchell automatic flight system FD282-242 consisting of flight director/autopilot, and automatic pitch trim. Issued 2/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1276SW	Mitchell automatic flight system AK332, consisting of Piper autoflite II and omni tracker system. Issued 3/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1377SW	Mitchell automatic flight system AK340, consisting of Century I and optional tracker. Issued 10/14/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA2442WE	Installation of dual hydraulic pump (New Eastern Industries hydraulic pump 1233-HnG Type 311 on right engine; pump 1233-HnG Type 311 in lieu of existing pump on left engine). Amended 3/29/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, 23-250, PA-E23-250;	SA2445WE	Installation of recontoured inboard wing leading edge, stall fences, drooped ailerons in flaps down mode, rudder anti-servo tab system, and optional raked wing tips. Issued 11/16/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA3133SW-D	Mitchell automatic flight system AK599, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/7/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA3137SW-D	Mitchell automatic flight system AK611 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, -250; PA-24, -24-250, -260; PA-25, -25-235, -25-260; PA-28-150, -28-160, -28-180, -28-235; T.C. 1A10, 1A15, 2A8, 2A13	SA693CE	Replace existing engine induction air filter with AC Spark Plug Division filter.	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
PA-23-250; T.C. 1A10	SA11NE	Installation of laser sensor system. Issued 10/31/75.	NE	33485	Environmental Research and Technology, Inc. 696 Virginia Road Concord, MA 01742
PA-23-250; T.C. 1A10	SA39RM	Installation of freon air-conditioning system. Issued 4/23/75.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-23-250; T.C. 1A10	SA164CE	Installation of Hartzell HC-A3XK-2B/7636D-4 propellers and C-2513-2P spinners. Reissued 3/9/78.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-250; T.C. 1A10	SA179CE	Installation of the following: Lycoming IO-540-A1A5 or IO-540-G1A5 engines, Hartzell HC-A3XK-2C/8433-10 or HC-A3XK-2B/7636D-4 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-250; T.C. 1A10	SA205GL	Installation of Aerosonic totalize fuel flow indication system in lieu of fuel pressure gages. Issued 12/19/77.	GL	73190	Roger Smith Aircraft Sales, Inc. Aurora Municipal Airport Sugar Grove, IL 60554
PA-23-250; T.C. 1A10	SA335CE	Installation of Honeywell H-14 YG-391 autopilot. Amended 9/9/66.	GL	42250	Honeywell, Inc. East 70th & 34th Avenue South Wold-Chamberlain Field Minneapolis, MN 55450
PA-23-250, S/N 27-2000 and subsequent; T.C. 1A10	SA427GL	Installation of Tull microwave landing system airborne equipment. Issued 7/23/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
PA-23-250; T.C. 1A10	SA429SO	Installation of Bendix Model FCS-80 automatic flight control system with manual electric pitch trim and flight director indicator. Amended 6/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA441NW	Installation of 3-bladed propeller and Piper Navajo spinner. Amended 1/12/78.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
PA-23-250; T.C. 1A10	SA480EA	Installation of photographic equipment.	NE	71400	James W. Sewall Company 147 Center Street Old Town, ME 04468
PA-23-250; T.C. 1A10	SA497SO	Installation of Bendix WLS-880 wings leveler system with and without Bendix FCS-810 automatic flight control system. Issued 11/8/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA590SO	Installation of M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA591SO	Installation of Bendix RNS-3400 area navigation system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250 (S/N 27-2505 and up); T.C. 1A10	SA621EA	Installation of a U.S. mail cargo kit. Amended 4/15/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23-250 (Aztec C, I, E); T.C. 1A10	SA663CE	Installation of Goodyear ice-guard de-icing kit Nos. 320-642. Reissued 4/17/72.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA667CE	Installation of wing and empennage deicing boot. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA668CE	Installation of wing and empennage deicing all weather antenna. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA688CE	Installation of propeller unfeathering system. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capitol Airport Springfield, IL 62705
PA-23-250; T.C. 1A10	SA850EA	Installation of radome kit 4025KX. Amended 9/12/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250; T.C. 1A10	SA922SO	Installation of Piper PA-23-250 "E" model fuselage nose. Amended 6/30/77.	SO	41400	Hawthorne Aviation Municipal Airport P.O. Box 10005 Charleston, SC 29411
PA-23-250 (Aztec F) defined by item VI in TCDS 1A10; T.C. 1A10	SA952SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-250; T.C. 1A10	SA1022CE	Installation of King Model KGS-55 pictorial navigation system (compass), with optional KA-52 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1027CE	Installation of KCS-55 pictorial navigation system (compass), with optional KA-57 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250 (Landplanes) (S/Ns 27-2505 thru 27-74-05471); T.C. 1A10	SA1063CE	installation of two Hartzell HC-E3YR-2AF/FC7663-2R propellers and C-3269A or 82D3273P spinners. Reissued August 1976.	SW	03034	AeroStol Company 5104 Rector Fort Worth, TX 76133
PA-23-250; T.C. 1A10	SA1102CE	Installation of AP-107, 2-axis autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250; T.C. 1A10	SA1103CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250; T.C. 1A10	SA1163CE	Installation of KFC-200 automatic flight control system. Amended 6/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1314SW	Fiberglass extended nose. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-250; T.C. 1A10	SA1390CE	Install 1/4-inch plywood flooring over existing floor, remove 4 passenger seats, install reinforcement tubing. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250; T.C. 1A10	SA1391CE	Cutting and reattaching the left and right lower engine cowling with AN 2700-4 cam locks. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250 (S/N 27-2505 and up); T.C. 1A10	SA1444WE	Installation of Edo Model 679-4930 floats and addition of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663
PA-23-250; T.C. 1A10	SA1554CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1810WE	Installation of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663
PA-23-250; T.C. 1A10	SA3209SW-D	Mitchell automatic flight system, Piper altimatic X autopilot, AK684 or AK684FD, Piper altimatic X flight director autopilot with remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, Serial Nos. 27-2000 and up; T.C. 1A10	SA3823WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 4/28/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-23-250 (carbureted engine only); T.C. 1A10	SA4151WE	Installation of Silver Instruments fueltron IIIG-C or IIIP-C digital fuel flow and totalizer system. Issued 5/6/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-23-250 (S/Ns 27-2000 and up), -E23-250; T.C. 1A10	SA619EA	Installation of radome kit 3061K for Bendix RDR-100 or RDR-110. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-23-250, -E23-250, PA-31, -31-325, -31-350; T.C. 1A10	SA20GL	Installation of Woodward Type II electronic propeller synchronizer system. Amended 1/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA25GL	Installation of propeller unfeathering accumulator system on light twin-engine airplanes. Issued 6/26/73.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-250, -E23-250; T.C. 1A10	SA51GL	Install Foster Airdata Systems, Inc. AD611/D area navigation system per STC. Reissued and amended 2/20/79.	GL	36520	Foster Airdata, Inc. 7020 Huntley Road Columbus, OH 43229
PA-23-250, -E23-250; T.C. 1A10	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 40355
PA-23-250, -E23-250 with counterweighted props, PA-31, PA-32-260, -31-325, -31-350, T.C. 1A10, A20SO, A3SO	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 1/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA430EA	Installtion of radome kit No. 3061X. Amended 11/12/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250, S/N 27-2000 and up, -E23-250; T.C. 1A10	SA1162EA	Installation of Silver Instruments fueltron IIIG or IIID digital fuel flow and totalizer system. Amended 5/27/80.	WE	71740	Silver Instruments 2346 Stanwell Drive Concord, CA 94520
PA-23-250, -E23-250; T.C. 1A10	SW1524SW	Mitchell automatic flight system AK371 consisting of altimatic IIIB-1 autopilot with optional command/electric trim system with radio and glide slope couplers. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1571SW	Mitchell automatic flight system AK382 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 12/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1653SW	Mitchell automatic flight system AK372 consisting of AutoFlite II with optional tracking system. Issued 5/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3002SW-D	Automatic flight system AK479 consisting of Piper altimatic IIIC autopilot with optional command/automatic electric elevator trim servo altimeter, radio coupler, and glide slope coupler. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3003SW-D	Automatic flight system AK477 and AK477FD consisting of Century IV autopilot and Century IV flight director autopilot with command/automatic electric trim, and optional annunciator panel and servoed altimeter. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3005SW-D	Automatic flight system AK508 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3006SW-D	Automatic flight system AK494 and AK494FD consisting of Century IV autopilot and Century IV director autopilot and command/automatic electric elevator trim and optional annuciator panel. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3007SW-D	Automatic flight system AK504 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim, radio coupler, glide slope coupler. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3027SW-D	Mitchell command/electric trim system AK562. Issued 10/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-250, -E23-250; T.C. 1A10	SA3104SW-D	Mitchell automatic flight system AK583, consisting of Century IIB autopilot with optional radio coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3290WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/8/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA195EA	Installation of Goodrich Electrothermal propeller de-icing system kit 77-170. Amended 10/27/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Co. 500 South Main Street Akron, OH 44318
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA840WE	Installation of Rajay Turbosupercharged Lycoming IO-540-C4B5 or -C4C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23 Series, PA-24 Series; T.C. 1A10, 1A15	SA230CE	Airspeed indicator landing gear warning system.	CE	74923	Standard Precision, Inc. 4105 West Pawnee Wichita, KS 67202
PA-23, PA-24, PA-28 Series; T.C. 1A10, 1A15, 2A13	SA148SW	Replacement of right front seat with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72003
PA-23, PA-24, PA-28, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA662WE	Hi-Lo sensitivity adaptor BI-400, and autopilot with NAV-1 navigation coupler and heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23, PA-24, PA-30 Series; T.C. 1A10, 1A15, A1EA	SA188SO	Flight control wheel.	SO	37086	Garcia Aviation Company 13010 SW 82nd Avenue Road Miami, FL 33156
PA-23, PA-25, PA-26 Series; T.C. 1A10, 1A15, 2A8, 2A10	SA4-1501	AB-6562 and AB-6563 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-23, PA-30, PA-31, PA-34, PA-39 Series; T.C. 1A10, A1EA, A8EA, 1E10	SA1675WE	Installation of exhaust gas temperature monitoring systems EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-24 Series; T.C. 1A15	SA1-340	Oil-free vacuum pump PA-201.	GL	11880	Associated Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-24 Series; T.C. 1A15	SA1-544	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-24 Series; T.C. 1A15	SA3-309	L2-B autopilot with or without altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA3-315	Arcon B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA3-351	L-2B autopilot with optional altitude control and automatic approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA4-572	Autopilot and optional navigation coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA4-666	Grimes D-7080-1-12 rotating beacon.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-24 Series; T.C. 1A15	SA4-852	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-24 Series; T.C. 1A15	SA4-955	Fiberglass vertical fin mount for either Grimes or Whelen WRM rotating beacons.	NW	85550	Art Whitaker Pearson Airpark Vancouver, WA 98660

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-24 Series; T.C. 1A15	SA4-956	Three seat belts to accommodate three persons or rear seat.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-971	20-gallon auxiliary fuel tank in baggage compartment.	WE	77260	Symons Engineering P.O. Box 90002 Airport Station Los Angeles, CA 90009
PA-24 Series; T.C. 1A15	SA4-1032	Aerofilter 30409A full flow lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-24 Series; T.C. 1A15	SA4-1132	SP-3 autopilot, less altitude and navigation-hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85027
PA-24 Series; T.C. 1A15	SA4-1235	Installation of Brittain 15-gallon wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA4-1248	Fuel drain modified to incorporate a handle extending forward through front bulkhead.	WE	14960	Bates Aviation, Inc. 1026 East 120th Street Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-1351	Installation of wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA2SO	Fifth passenger seat.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA18SO	Cockpit operated fuel drain valve.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA48WE	Belly-mounted rotating anti-collision light to supplement top fuselage-mounted standard rotating light.	WE	75250	Stits Aircraft Company P.O. Box 3084 Riverside, CA 92502
PA-24 Series; T.C. 1A15	SA59SW	Piper altimatic pilot AK089 or AK089R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24 Series; T.C. 1A15	SA74SW	Quick door release mechanism.	SW	69207	Ross Aviation, Inc. R.F.D. 5, Riverside Airport Tulsa, OK 74101
PA-24 Series; T.C. 1A15	SA112CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155
PA-24 Series; T.C. 1A15	SA113CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155
PA-24 Series; T.C. 1A15	SA160SW	Automatic pilot AK115, AK115E or AK115E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24 Series; T.C. 1A15	SA203SO	Fyr-Fyter 23-4, 2-1/2 pound, dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-24 Series; T.C. 1A15	SA315SW	Fabrication and installation of split rear seat back.	SW	71365	Seven Bar Flying Service, Inc. 10001 Coors Road, NW Albuquerque, NM 87101
PA-24 Series; T.C. 1A15	SA341CE	SAGA (semi-automatic gear actuator) control system. Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
PA-24 Series; T.C. 1A15	SA362WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA478EA	SAGA (semi-automatic gear actuator) system.	GL	43750	In-Flight Devices Corporatin 4885 Sawyer Road International Airport Columbus, OH 43219
PA-24 Series; T.C. 1A15	SA482WE	Plastic wing tips replaced with "Speedplates".	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-24 Series; T.C. 1A15	SA510CE	Modify electrical system to combination 12/24 volt system for starting engine.	EA	12700	Avco Lycoming Division Avco Corporation Williamsport, PA 17701
PA-24 Series; T.C. 1A15	SA511WE	Lycoming O-540-D1B5 engine, Hartzell HC-A2XK-1/8433-7 propeller required.	WE	46790	Johnston Aircraft Service P.O. Box 757 Tulare, CA 93274
PA-24 Series; T.C. 1A15	SA553WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA598EA	Installation electronic voltage alarm, Drawing No. 80107.	EA	53500	McKinley Engineering Corp. P.O. Box 275 Palisades Park, NJ 07650
PA-24 Series; T.C. 1A15	SA871WE	Fiberglass wing tips.	WE	58580	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-24 Series; T.C. 1A15	SA881EA	Installation of Grimes 30-0437-1 anti-collision strobe light kit, P/N 34-0200-1. Amended 5/2/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-24 Series; T.C. 1A15	SA891WE	Toe brakes.	RM	12540	Atlas Aviation, Inc. 8505 Montview Boulevard Denver, CO 80202
PA-24 Series; T.C. 1A15	SA904WE	Hanlon and Wilson exhaust system, 637-129.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA1109WE	Hanlon and Wilson exhaust system.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA1605WE	Installation of Brittain B-4A flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24-180; T.C. 1A15	SA4-3151	Wing tip fuel tanks installed. Amended 1/10/69.	WE	17492	Brittain Industries, Inc. 2700 Skypark Drive Torrance, CA 90505
PA-24-180; T.C. 1A15	SA127EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-24(-180), -24-250, -24-260, -24-400; T.C. 1A15	SA208GL	Installation of one piece windshield. Issued 1/23/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-24, PA-24-250, -260, -400; T.C. 1A15	SA270GL	Installation of forward windows, P/N's W-, W/T-, WG-2058-187 or -250 and W-, W/T-, WG-2059-187 or -250. Issued 10/2/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-24, -24-250, S/N 24-2299 and above, PA-24-260, S/N 24-3642, 24-4000 thru 24-4802, PA-24-400, S/N 26-2 and above; T.C. 1A15	SA463GL	Install instrument panel and instruments. Issued 10/24/80.	GL	50470	Jerome G. Liebler 3182 Briar Hill Milford, MI 48042
PA-24, -24-250; T.C. 1A15	SA3074SW-D	Mitchell automatic flight system AK547 consisting of Century I autopilot with optional omni tracker. Issued 10/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, 24-250, -260; PA-28, 28-140, -150, -160, -180, -235; PA-30; PA-32-260, -300; T.C. 1A15, 2A13, A1EA, A3SO	SA808SW	Installation of Mitchell Model AK246 omni tracker. Applicable only to aircraft modified by STCs SA511SW, SA532SW, SA581SW, SA662SW, SA707SW.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -260, -400; T.C. 1A15	SA891SO	Remove existing windshield and install single piece windshield. Amended 4/27/76.	SO	30784	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260; T.C. 1A15	SA1315CE	Chrome-plated brake disc installations. Issued June 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RS	STC CODE	STC HOLDER
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA1706SW	Portable solid oxygen system. Issued 7/27/73.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3070WE	Installation of single piece windshield. Issued 7/23/75.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-24, -24-250, -24-400; T.C. 1A15	SA2495WE	Installation of recontoured wing leading edge, stall fences, drooped ailerons in flaps-down mode, flap-actuated stabilator trim system, optional new wing tips, optional SC-100 stall warning system. Issued 3/27/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250; PA-28-180; T.C. 1A15, 2A13	SA2654WE	Installation of Pathfinder P2A autopilot system. Reissued 5/31/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; T.C. 1A15	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260, PA-30; T.C. 1A15, A1EA	SA3045SW-D	Automatic flight system AK519 consisting of Century IIB autopilot with optional radio coupler. Issued 3/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3565WE	Installation of single piece windshield. Issued 1/20/78.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-24, -24-250, -24-260; T.C. 1A15	SA3776WE	Installation of flexible stainless steel oil cooler hoses. Issued 11/1/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-24, -250, -260, -400; T.C. 1A15	SA4179WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
PA-24-250; T.C. 1A15	SA5-27	Remove Lycoming O-540-A1A5 (250 hp) engine and install Lycoming O-540-B1B5 (235 hp) engine. Revised 3/3/62.	AL	63845	Peninsula Airways, Inc. P.O. Box 110 Naknek, AK 99633
PA-24-250; T.C. 1A15	SA811WE	Installation of turbosupercharged Lycoming IO-540-C1B5 or C1C5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-250 (Normal Category); T.C. 1A15	SA3451WE	Installation of Hartzell HC-A3VK4/V7636D-0 or V7636N-0 constant speed propeller. Amended 5/27/80.	WE	06755	Aircraft Technical Service, Inc. 6701 Odessa Avenue Van Nuys, CA 91406
PA-24-250, -24-260; T.C. 1A15	SA3684WE	Installation of an air/oil seperator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
*PA-24-250, *-24-260; T.C. 1A15	SA3773WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79. *This installation limited to those aircraft with fuel injected engines.	WE	71740	Silver Instruments, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-24-250, 24-260, PA-30; T.C. 1A15, A1EA	SA1027SW	Manual electric pitch trim AK267.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA893SO	Installation of exhaust silencers. Issued 4/22/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24-260 (S/Ns 24-4783 and 24-4804 and up); T.C. 1A15	SA1026SW	Piper automatic flight system Model AK186 consisting of altimatic IIIB autopilot, auto-flite, electric pitch trim, radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-24-260 (S/N 24-4783, 24-4804 and up with IO-540 series normally aspirated engines; T.C. 1A15	SA1178EA	Installation of Silver Instruments fueltron IG digital fuel flow and totalizer system. Reissued 2/26/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-24-260; T.C. 1A15	SA1331SW	Mitchell automatic flight system AK326 consisting of Piper autoflite II and optional tracking system. Issued 6/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA1521SW	Mitchell automatic flight system AK393, consisting of Century I autopilot with optional omni tracker. Issued 10/17/72.	SW	60000	Mitchell Industries, INc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA2062WE	Installation of Lycoming IO-540-R1A5 engine and Rajay turbosuperchargers.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-260, -24-400; T.C. 1A15	SA31NW	Installation of Madras wing tips. Issued 3/13/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
PA-24-400; T.C. 1A15	SA2359WE	Installation of turbosupercharged Lycoming IO-720-A1A engine. Issued 6/1/71.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-400; T.C. 1A15	SA3134SW-D	Mitchell automatic flight system AK593 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-400; T.C. 1A15	SA3135SW-D	Mitchell automatic flight system AK597 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
PA-24-400; T.C. 1A15	SA3136SW-D	Mitchell automatic flight system AK609 consisting of Century I autopilot with optional omni tracker. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-20; T.C. 1A15, 2A13	SA1405WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24, PA-30; T.C. 1A15, A1EA	SA313SW	Pitch trim system AK124.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA331SO	External power supply plug.	SO	60120	Montgomery Aviation Corporation P.O. Box 92 Montgomery, AL 36100
PA-24, PA-30; T.C. 1A15, A1EA	SA466SW	Pitch trim system AK147.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA475SW	Pitch trim system AK152.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA524SW	Pitch trim system AK164.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA525SW	Piper autocontrol III, Mitchell AK161 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA581SW	Stabilizer AK179.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-24, PA-30; T.C. 1A15, A15EA	SA662SW	Automatic flight system 220.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA756SW	AK236 automatic flight system with Century II autopilot, optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-25 Series; T.C. 2A8, 2A10	SA4-1592	Spray equipment.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA157SO	Air-oil type main landing gear shock absorber.	SO	64665	Piper Aircraft Corporation Vero Beach, FL 32960
PA-25 Series; T.C. 2A8, 2A10	SA168WE	Installation of Agavenco P/N 1826 15-gallon additional capacity cell to Piper fiberglass spray tank. Amended 3/18/68.	WE	03250	Agricultural Aviation Engineering Company McCarran Airport Las Vegas, NV 89109
PA-25 Series; T.C. 2A8, 2A10	SA185WE	Electrical spray control valve.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Crive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA292SO	FrigiKing JC-1 air conditioner.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-25 Series; T.C. 2A8, 2A10	SA300SO	Auxiliary oil radiator.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-25 Series; T.C. 2A8, 2A10	SA512SW	Metal ribs and metal covering of wings.	SW	60168	Luther W. Moore 1110 West 29th Street Plainview, TX 79072
PA-25 Series; T.C. 2A8, 2A10	SA829WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-25, -25-235, -260; T.C. 2A10	SA915SO	Lower forward longeron reinforcement by adding tubing in trangle shape outboard between fore and aft wing spar root attach fittings and modifying wing root rib to fit over modified longeron. Issued 1/6/77.	SO	05966	Aircraft Service Center, Inc. Route 2, Tifton Airport Tifton, GA 31794
PA-25, -25-235, -260; T.C. 2A10	SA1180CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Gox 508 Renner Field Goodland, KS 67735
PA-25, -25-235, -260; T.C. 2A10	SA1294WE	Installation of automatic flagman. Amended 4/17/72.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362
PA-25, -25-235, -260; T.C. 2A10	SA1417WE	Installation of fiberglass wing tips. Amended 3/26/69.	NW	74750	Sportsman Airpark, Inc. P.O. Box 248 Newberg, OR 97132
PA-25-235; T.C. 2A8	SA41RM	Installation of freon air-conditioning system. Issued 1/9/75.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-25-235; T.C. 2A8, 2A10	SA521WE	Swathmaster dust and spray attachment.	WE	79250	Transland Aircraft, Inc. 2923 190th Street Redondo Beach, CA 90277
PA-25-235; T.C. 2A8, 2A10	SA710CE	Install Compro Aviation rudder horn extension.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
PA-25-235; T.C. 2A8, 2A10	SA997WE	Installation of 180-gallon hopper tank. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-25-235; T.C. 2A10	SA1399WE	Installation of Shell B1-Flon spray system. amended 7/19/68.	NW	71770	Simplex Manufacturing Company 4224 Northeast 42nd Avenue Portland, OR 97218
PA-25-235; T.C. 2A10	SA1630SW	Revised exhaust system. Issued 5/5/73.	SW	53784	Karl D. McWilliams d/b/a K & C Aircraft Service Municipal Building Airport Frederick, OK 73542

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-25-235, -25-260; T.C. 2A8	SA1316CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-25-235, -25-260; T.C. 2A8	SA1892WE	Installation of hydraulic system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton AVenue Harbor City, CA 90710
PA-25-235, -25-260; T.C. 2A8	SA368NW	Installation of outboard wing fuel tank with modified fuel pump system. Issued 10/19/76.	NW	03270	U.S.D.A. 3706 West Nob Hill Boulevard Yakima, WA 98902
PA-25, PA28-140, PA32-260; T.C. 2A8, 2A13, A3SO	SA693WE	Install AC induction air filter type AAF-104. Amended 4/26/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
PA-28 Series; T.C. 2A13	SA1-649	Lube oil filter PB55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
PA-28 Series; T.C. 2A13	SA8PC	Installation of baggage compartment kit IFC-BC-001 behind rear seats in the cabin.	PC	44810	Island Flight Center, Inc. 203 Lagoon Drive Honolulu, HI 96819
PA-28 Series; T.C. 2A13	SA100EA	AF-510, AF-512A or AF-512B autopilots.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005
PA-28 Series; T.C. 2A13	SA110SO	Electric pitch trim system.	SO	64665	Piper Aircraft Corporation Vero Beach, FL 32960
PA-28 Series; T.C. 2A13	SA180EA	Geared starter.	EA	79953	Turner Field, Inc. Prospectville, PA 19077
PA-28 Series; T.C. 2A13	SA164SW	Automatic pilot AK092E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA178WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-28 Series; T.C. 2A13	SA222SW	Hartzell HC-82XL-6H/7636D-4 propeller and cowl rework.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA224CE	A3000 main and NB1200 nose skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA236SW	Piper auto-control II automatic pilot AK085E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA246SW	Nose cowling modified.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA263EA	Modification of engine mount to permit use of Lord mounting kit J-10778-4.	EA	12700	Lycoming Division Avco Corporation Williamsport, PA 17701
PA-28 Series; T.C. 2A13	SA319CE	Model 2500 wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA369SW	Automatic pilot AK129, pitch trim system AK130, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA481SW	Removal of door for parachute jumping.	SW	37055	Ervin J. Fusilier 9617 Fulton Street Houston, TX 77002
PA-28 Series; T.C. 2A13	SA511SW	Stabilizer AK153.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA530SW	Automatic pitch trim systen AK166.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28 Series; T.C. 2A13	SA556SW	Constant speed propeller.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA601WE	Flight control system B-4 including pitch assist PC-1, altitude hold AH-1, and	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
PA-28 Series; T.C. 2A13	SA645WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA646WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA787SW	AD127 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA700SW	Plane booster safe flight wing tips 101-28.	SW	81250	Upper Valley Aviation, Inc. Harvey J. Ferguson McAllen, TX 78501
PA-28 Series; T.C. 2A13	SA880WE	New design fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-28 Series; T.C. 2A13	SA1191WE	Removal of baggage door for aerial photography operations.	RM	47725	Kelsey Ellis Air Service, Inc. Municipal Airport Salt Lake City, UT 84101
PA-28 Series; T.C. 2A13	SA1354WE	PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1469WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1470WE	Installation of Brittain Model PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28-140; T.C. 2A13	SA578EA	Installation of Monitair angle of attack/stall warning kit, P/N 9-92-1000. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140; T.C. 2A13	SA687SO	Installation of flight attitude alerting system. Amended 6/1/70.	SO	05350	Aircraft Instruments, Inc. 420 Lincoln Road, Suite 206 Miami Beach, FL 33139
PA-28-140; T.C. 2A13	SA913EA	Installation of Elano Corporation heater-muffler system. Issued 5/11/72.	GL	33200	Elano Corporation 2455 Dayton - Xenia Road Xenia, OH 45385
PA-28-140; T.C. 2A13	SA1189SW	Air circulator. Issued 9/15/70.	SW	83100	Ves-Kol 2805 National Drive Garland, TX 75040
PA-28-140; T.C. 2A13	SA1192EA	Instalation of Safe Flight (SFIC) SC-150 speed control system. Issued 4/15/80.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
PA-28-140; T.C. 2A13	SA2052WE	Installation of Hartzell HC82XL-6F/8433-12 propeller (after conversion of engine to Lycoming O-320-E1A model).	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-140; T.C. 2A13	SA2325WE	Replacement of Station 140.6 vinyl bulkhead panel with fiberglass baggage compartment. Issued 3/19/71.	WE	21000	Chaffee Aircraft Service Corp. 2105 Valley Boulevard Colton, CA 92324
PA-28-140; T.C. 2A13	SA2706SW	Lycoming O-320-D3G engine. Issued 1/20/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-140; T.C. 2A13	SA2842WE	Installation of Novastar anti-collision lighting system. Issued 2/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28-140; T.C. 2A13	SA3071WE	Installation of Bendix P/N 480543 electric auxiliary fuel pump. Issued 8/7/75.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28-140 (Normal and utility category); T.C. 2A13	SA3415WE	Installation of Lycoming O-320-D2A engine and Sensenich M74DM6-0-60 propeller. Reissued 5/1/79.	NE	30310	Arthur M. D'Onofrio, Jr. 206 Winthrop Boulevard Cromwell, CT 06416
PA-28-140, -28-150 and PA-28-151 landplanes; T.C. 2A13	SA1331CE	Installation of 160 hp Lycoming engine and repitched Sensenich Amended 10/27/77.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
PA-28-140, -150, -160, -180, -235; T.C. 2A13	SA2NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 7/31/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
PA-28-140, -28-150, -28-160, -28-180, -28S-180, -28-235; T.C. 2A13	SA363EA	Installation of Monitair angle of attack and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140, -150, -160, -180; T.C. 2A13	SA549NW	Installation of Deemers wing tips. Issued 12/5/77.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
PA-28-140, -140B, -140C, -140D, -140E, -150, -160, -160B, -160C, -160D, -160E, -160F, -180, -232, -235B thru F, PA-32-260, -300, -32R-300; T.C. 2A13, A3SO	SA600NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. NOTE: Installation does not apply to those models with tapered wings. Issued 10/25/78.	NW	19830	Robert C. Cansdale Bob's Aircraft Supply Thun Field Puyallup, WA 98371
PA-28-140, -150, -151, -160; T.C. 2A13	SA793CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/7666A-2 propeller. Amended 6/29/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
PA-28-140, -150, -160, -180, -235, 28-S-160, S-180, 28R-180, -200; T.C. 2A13	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-1 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-28-140, -150, -160, -180, -235, -S-160, -S-180, -R-180; T.C. 2A13	SA822SW	Mitchell automatic flight system AK217 consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -200, PA-34-200; T.C. 2A13, A7SO	SA979EA	Installation of L/R wing tip transparent fairings and sensor mounting bracketry. Issued 4/5/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
PA-28-140, -28-150, -28-160, -28-180, -28R-200 (S/N 28R-35001 thru 28R-7135329; T.C. 2A13	SA1072CE	Installation of wing leading edge cuffs and droop tips, dorsal fin and vertical stabilizer vortex Amended 5/1/80.	CE	42560	Horton Stol-Craft, Inc. Wellington Municipal Airport Wellington, KS 67152
PA-28-140, -150, -160, -180, -235, -28S-160, -28S-180, -23R-180, -28R-200, -28-151, -28-161, -28-181, -28R-201, -28R-201T, PA-32-260, -300, -32S-300, -32R-300; T.C. 2A13, A3SO	SA1123EA	Installation of Devore vertical tail floodlights on upper surface of horizontal stabilator. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1227CE	Installation of dorsal fin. Amended December 1976.	CE	44800	Isham Aircraft P.O. Box 12172 Wichita, KS 67212
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1228CE	Installation of wing tip extension. Amended June 1976.	CE	44800	Isham Aircraft 416 West Fourth Street Valley Center, KS 67147
PA-28-140, -150, -160, -180, -235; PA-28R-180; T.C. 2A13	SA1157SW	Mitchell flight system AK295 consisting of Piper AutoFlite II, automatic aileron stabilizer and optional tracking system. Issued 6/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -235, -200; T.C. 2A13	SA1272SW	Automatic flight system AK307, consisting of Century I and omni tracker. Issued 3/9/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 3A12	SA1317CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Bouelvard Kansas City, KS 66103
PA-28-140, -150, -160, -180 (S/Ns 28-1 thru 28-4377), PA-28-235 (S/N 28-10003 thru 28-11039); T.C. 2A13	SA1373CE	Install third window. Amended 11/17/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1741WE	Installation of hand control for rudder system. Amended 6/13/73.	WE	16854	William Henry Blackwood Route 3, Box 744B3 Escondido, CA 92025
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1898SW	Installation of wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-28-140, -150, -160, -180; T.C. 2A13	SA2179WE	Installation of leading edge cuff, drooped ailerons, wing stall fences, raked wing tips, fuselage flaps, stabilator trim-spring and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98007
PA-28-140, -150, -160, -180, PA-28R-180, -200, -235, PA-32-260, -300; T.C. 2A13	SA3026SW-D	Mitchell auto flight systen AK463 consisting of Century IIB autopilot with optional radio coupler. Issued 10/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, -28R-200, -235; T.C. 2A13	SA3165SW-D	Automatic flight system AK174 consisting of auto-control IIB autopilot with optional radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -160, -180, -235, -28R-180, -200; T.C. 2A13	SA3166SW-D	Automatic flight system AK295 consisting of Piper autoflite II. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -151, -160, -180, -181, -28R-180, -28R-200, -28-235; T.C. 2A13	SA3435WE	Installation of flexible oil hose assembly. Amended 1/11/79.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-28-140, -150, -160, -180, -151, -181, PA-28S-160, -180, PA-28R-180-200; T.C. 2A13	SA3687WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
PA-28-151; T.C. 2A13	SA228GL	Installation of Lycoming O-320-D3G engine in lieu of Lycoming O-320-E3D engine using original installation hardware and components. No installation data required. Issued 3/3/78.	EA	90108	W. Irvine Young 54 Atomic Avenue Toronto, Ontario M8Z-5L4 Canada
PA-28-151; T.C. 2A13	SA1716SW	Mitchell automatic flight system AK430 consisting of AutoFlite II with optional omni tracker. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA1717SW	Mitchell automatic flight system AK431 consisting of auto-control III with optional radio coupler. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA2969SW	Lycoming O-320-D3G engine. Issued 4/5/79.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-151; T.C. 2A13	SA3012WE	Installation of Pathfinder autopilot systems. Issued 4/24/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-151, -161, -181, PA-28R-200, -201, PA-28-235, -28R-201T; T.C. 2A13	SA1075SO	"Wing-Ding" door stop to be installed using existing screws (Piper P/N 415 309, MS27039-0809) on leading edge of right wing at inboard side of fuel cell (W.S. 57.00). Issued 5/18/79.	SO	65327	William J. Stephenson Pro-Flite of Vero, Inc. P.O. Box 998 Vero Beach, FL 32960
PA-28-151, -181; T.C. 2A13	SA3065SW-D	Mitchell automatic flight system AK431 consisting of autocontrol IIIB with optional radio coupler. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28-151, -181; T.C. 2A13	SA3066SW-D	Mitchell automatic flight system AK430 consisting of autoflite II with optional omni tracker. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3095SW-D	Mitchell automatic flight system AK575 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3096SW-D	Mitchell automatic flight system AK576 consisting of Century IIB autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067
PA28-160; T.C. 2A13	SA1971WE	Installation of Model ARB-3 automatic downed aircraft marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue Box 822 Fort Collins, CO 80521
PA-28-160, -28-180, -28-235; T.C. 2A13	SA1484WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28-161, -181; T.C. 2A13	SA419GL	Installation of full microwave landing system airborne equipment. Issued 6/18/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
PA-28-161, -181, -201T, -236; T.C. 2A13	SA3352SW	Installation of Mitchell automatic flight system AK851 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TS 76067
PA-28-180; T.C. 2A13	SA1789WE	Installation of Brittain lateral stability augmentation system and super venturi. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-180; T.C. 2A13	SA1792WE	Installation of Morse protection system.	WE	60190	Morse Products Manufacturing 12960 Bradley Avenue Sylmar, CA 91342
PA-28-180; T.C. 2A13	SA2213WE	Conversion of Lycoming O-360-A3A engine to Model O-360-A1A engine and installation of Hartzell HC-C2YK1-B/7666A-0 propeller. Issued 9/8/70.	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-180; T.C. 2A13	SA3233WE	Installation of Symbolic Displays "Novastar" anti-collision light. Issued 7/22/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28R-180; T.C. 2A13	SA962SW	Piper automatic flight system AK271 consisting of altimatic with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180; T.C. 2A13	SA1237SW	Mitchell automatic flight system Model AK314 consisting of altimatic IIIB-1 with optional automatic pitch trim and radio coupler. Issued 12/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA1406SW	Mitchell flight system Model AK269 consisting of Piper autocontrol III autopilot with optional radio coupler. Issued 12/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180; -200; T.C. 2A13	SA2202WE	Installation of contoured leading edge, drooped ailerons, fuselage flap, stabilator trim spring, wing stall fences, raked wing tips, and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98004
PA-28R-180, -200; T.C. 2A13	SA2490SW	Wing tip extension and dorsal fin. Reissued 10/6/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28R-180, -200; T.C. 2A13	SA3004SW-D	Automatic flight system AK436 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28R-180, -200; T.C. 2A13	SA3093SW-D	Mitchell automatic flight system AK577 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA3094SW-D	Mitchell automatic flight system AK578 consisting of Century IIB autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200, -201; T.C. 2A13	SA3841WE	Installation of SDI Model CFS-1000, -1001, or F1-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 MCGaw Avenue Irvine, CA 92714
PA-28R-200; T.C. 2A13	SA194GL	Installation of Lycoming IO-360-C1C6 engine in lieu of Lycoming IO-360-C1C engine using original installation hardware and components. Issued 11/11/77.	GL	71517	Shelby Aircraft Engine Parts, Inc. P.O. Box 454 Shelbyville, IL 62565
PA-28R-200 (S/N 28R-7235001 and up), -28R-201T, -28R-201 (S/N 28R-7737002 and up); T.C. 2A13	SA1183CE	Installation of a two-axis King Model KFC200 flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 1/26/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-28R-201; T.C. 2A13	SA420GL	Installation of full microwave landing system airborne equipment. Issued 6/18/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
PA-28R-201, -201T; T.C. 2A13	SA3161SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -201T; T.C. 2A13	SA3162SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3194SW-D	Automatic flight system AK638 consisting of Piper altimatic IIIC autopilot with optional radio coupler and glide slope coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3195SW-D	Install automatic flight system AK652 consisting of Century III autopilot with optional radio coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-200, -28R-201T; T.C. 2A13	SA3196SW-D	Install automatic flight system AK653 consisting of Century IIB autopilot with optional radio coupler. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-200, -28R-201T; T.C. 2A13	SA3197SW-D	Install automatic flight system AK654 consisting of Century I autopilot with optional omni tracker. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201T; T.C. 2A13	SA148RM	Install Model CFS-1000 fuel flow meter and related systems. Issued 8/15/78.	RM	77248	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-28R-201T; T.C. 2A13	SA1383CE	Installation of Edo-Aire propeller governor Model 34-828-014-12. Issued 10/28/77.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
PA-28R-201T; T.C. 2A13	SA3771WE	Installation of Fueltron IG digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-28RT-201, -28RT-201T; T.C. 2A13	SA1498CE	Installation of King KFC 200 automatic flight control system. Issued 6/18/79.	CE	48250	King Radio Corporation 400 NOrth Rogers Road Olathe, KS 66061
PA-28RT-201, -28RT-201T; T.C. 2A13	SA3323SW-D	Mitchell automatic flight system AK755 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 11/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28RT-201, -201T; T.C. 2A13	SA3336SW-D	Mitchell automatic flight system AK777 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/21/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3359SW	Installation of Mitchell Century 41 autopilot/flight director AK863/FD. Issued 4/16/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3360SW-D	Installation of Mitchell automatic flight system AK862 consisting of Century 21 autopilot. Issued 5/16/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28-235; T.C. 2A13	SA1131EA	Installation of a radome pod SERP-1001 or -1002 on right wing. Amended 3/28/80.	EA	08332	David L. Stanislaw d/b/a Airquip Horsham Road Ambler, PA 19002
PA-28-235; T.C. 2A13	SA2143WE	Installation of drooped leading edge, drooped ailerons, wing stall fences, fuselage flap, drooped wing tips and elevator trim spring. Amended 12/30/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
PA-28-235; T.C. 2A13	SA2147WE	Installation of Brittain Industries B-7 flight control system. Reissued 11/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-235; T.C. 2A13	SA3187WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-235; T.C. 2A13	SA4103SW	Installation of Brittain B-5 flight control system. Issued 3/20/80.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-235, PA-32-260, -300; T.C. A3SO, 2A13	SA1156EA	Installation of radome pod SERP-1021 or -1022 on right wing. Issued 6/26/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002
PA-28, PA-32; T.C. 2A13, A3SO	SA281AL	Installation of large nose gear fork and 8.00-6 nose gear tire. Amended 6/20/68.	AL	78487	Tibbetts-Herre Airmotive P.O. Box 110 Naknek, AK 99633
PA-28, PA-32; T.C. 2A13, A3SO	SA4728SO	Installation of hand control for rudder pedal operation. Amended 6/27/74.	SO	85450	The Wheelchair Pilots Association 4211 Fourth Avenue South St. Petersburg, FL 33711
PA-28, PA-32; T.C. 2A13, A3SO	SA757SW	AK234 automatic flight system with Century II autopilot optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; PA-32-260; T.C. 2A13, A3SO	SA788SW	Piper auto-control II automatic pilot AK172E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA72RM	Installation of camera wells. Amended 12/9/76.	RM	42420	Horizons, Inc. P.O. Box 3134 Rapid City, SD 57701
PA-30 Series; T.C. A1EA	SA184EA	Installation of 13-quart alcohol propeller anti-icing kit utilizing either a Weldon pump (P/N 100B-6) or a Bendix pump (P/N 478360). Amended 10/15/71.	NE	86000	Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA225EA	Installation of Monitair angle of attack and stall warning system. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-30 Series; T.C. A1EA	SA233EA	Reservoir-type pneumatic wing and tail deicing system. Amended 10/7/70.	NE	86000	R.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA282CE	GUART System (Gear-up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 West Walnut Street Chicago, IL 60612
PA-30 Series; T.C. A1EA	SA343SW	Automatic pilot AK127, AK127E or AK127E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-30 Series; T.C. A1EA	SA477EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
PA-30 Series; T.C. A1EA	SA520SO	Installation of Bendix FCS-810 (Piper Altimatic V/F/D) automatic flight control including manual electric trim and optional flight director indicator. Amended 8/13/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-30 Series; T.C. A1EA	SA531SW	Fifth seat.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-30; T.C. A1EA	SA533NW	Installation of aileron trim. Issued 10/19/77.	NW	73160	Robert Smith Box 43 Okanagan Mission Kelowna, B.C., Canada
PA-30 Series; T.C. A1EA	SA534EA	Replacement of existing stall warning detector Safe Flight P/N C-52207 with pre-stall warning and speed control transducer, Safe Flight P/N 792 and speed control indicator, P/N 571.	EA	69500	Safe Flight Instruments Corp. New King Street White Plains, NY 10601
PA-30 Series; T.C. A1EA	SA559WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30 Series; T.C. A1EA	SA576SW	AK186 altimatic III autopilot, AK179 stabilizer, and AK189 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA591CE	Install Alco XW20101-PA-30-L windshield wiper system.	CE	08750	Alco Controls Corporation P.O. Box 12700 St. Louis, MO 63141
PA-30 Series; T.C. A1EA	SA727WE	Installation of Brittain Industries Model TT-5 wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-30 Series; T.C. A1EA	SA738CE	Install King Radio KNC 610 area navigation computer. Amended May 1974.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA766WE	Plastic wing tips replaced with "Speedplates" SP51463.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
PA-30 Series; T.C. A1EA	SA767WE	Modification to include three pair of seat belts on rear seat to accommodate three passengers.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-30 Series; T.C. A1EA	SA776CE	Installation of King Radio KN-74 area navigation computer. Issued June 1971.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA789CE	Install Woodward propeller unfeathering accumulator system. Issued July 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-30 Series; T.C. A1EA	SA1111SW	Outer wing integral auxiliary fuel tanks and increase gross weight of 180 pounds.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1112SW	Dorsal fin.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1113SW	Extended nose with baggage compartment.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1114SW	Nacelle baggage compartments.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-30 Series; T.C. A1EA	SA1115SW	Dual brakes.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1151SW	Lycoming IO-360-C1C engines (200 hp) with Hartzell HC-C2YK-2/C7666A-4 propeller. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1152SW	One-piece windshield. Issued 6/8/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1153SW	Square wing tips with dual navigation lights. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1154SW	Rudder and aileron interconnect system. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1337SW	Pneumatic de-icing system. Issued 7/8/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246
PA-30; T.C. A1EA	SA1401CE	Install King Model KNS 80 digital area navigation system. Issued 2/16/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olather, KS 66061
PA-30 Series; T.C. A1EA	SA1935WE	Installation of Brittain flight control system Model B-5, NAV-2B, or B2C. Reissued 10/20/72.	SW	17400	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30; T.C. A1EA	SA3707WE	Installation of single piece windshield. Issued 8/7/78.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-30; T.C. A1EA	SA3729WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-30; T.C. A1EA	SA4066WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-30, PA-39; T.C. A1EA	SA209GL	Installation of one piece windshield. Issued 1/23/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-30, PA-39; T.C. A1EA	SA673EA	Installation of radome kit 3058X. Amended 5/26/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-30, PA-39; T.C. A1EA	SA676EA	Installation of Norton Company radome kit 3058-B. Amended 3/24/71.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-30, PA-39; T.C. A1EA	SA787WE	Installation of turbosupercharged Lycoming IO-320-B1A, IO-320-C1A or LIO-320-C1A engines. Amended 3/10/70.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA848EA	Installation of pneumatic pump operated wing and tail de-icing boot system. Issued 10/22/70.	NE	86000	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-30, PA-39; T.C. A1EA	SA1239SW	Turbosupercharged Lycoming IO-360-C1C engines. Issued 1/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30, PA-39; T.C. A1EA	SA1254SW	Electrothermal propeller de-icing system. Issued 1/27/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-30, PA-39; T.C. A1EA	SA1320CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33460	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-30, PA-39; T.C. A1EA	SA1341SW	Nose taxi light. Issued 7/20/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246
PA-30, PA-39; T.C. A1EA	SA2312WE	Installation of leading edge cuffs, stall fences, stall strips drooped ailerons, flap actuated stabilator trim system, raked wing tips (optional) and dorsal fin. Amended 4/2/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-30, PA-39; T.C. A1EA	SA2849WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA3128SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional command automatic trim, readio, and glide slope couplers. Issued 5/6/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA3336WE	Installation of single piece windshield. Issued 2/2/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-30, PA-39; T.C. A1EA	SA4189WE	Installation of DTL-1000, -1001 and/or -1002/3 autopilot adapters for the Edo-Aire Mitchell century III autopilot. Issued 7/29/80.	WE	47775	Douglas L. Kettler 1212 North Broadway, Apt. H Escondido, CA 92026
PA-31 (S/N 31-2 and up); T.C. A8EA	SA142RM	Install Model CFS-2000 fuel flow meter and related systems. Issued 5/12/78.	RM	77250	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-31; T.C. A8EA	SA191GL	Installation of microwave landing airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31 Series; T.C. A20SO	SA367GL	Installation of Norton radome kit No. 2032X Amended 10/24/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA529EA	Installation of kit for radar antenna.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company P.O. Box 1187 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA541CE	Installation of Hoskins Twilighter Mk III supplemental lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-31 Series; T.C. A8EA	SA546EA	Incorporation of opening in lower surface of fuselage aft of front spar.	NE	86000	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-31 Series; T.C. A8EA	SA613EA	Installation of nine seats. Amended 6/6/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31 Series; T.C. A8EA	SA622EA	Incorporation of camera hatch and mountings to accommodate Zeiss RMK A15/23 camera.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
PA-31 Series; T.C. A8EA	SA741EA	Installation of co-pilot door. Amended 11/3/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31 Series; T.C. A8EA	SA865EA	Installation of radome kit 2031KX. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA908SW	Air conditioner.	SW	64410	R.D. Philpot Industries, Inc. Box 47062 Dallas, TX 75247
PA-31 Series; T.C. A8EA	SA986SW	Baggage lockers in revised aft nacelle fairings.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31 Series; T.C. A8EA	SA1000SW	Nine place seating arrangement.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1054SW	Stretcher.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1055SW	Baggage retaining net.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1065SW	Mitchell flight director and autopilot Model 282-187 with slaved directional gyro. Issued 9/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA1120SO	Installation of single camera and camera aperature on starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31; T.C. A20SO	SA1121SO	Installation of supply dropping aperature and sliding shutter and antenna fairing. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31; T.C. A20SO	SA1123SO	Installation of navigation sight and transparent plastic dome on the lower fuselage station 128. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31 Series; T.C. A8EA	SA1155SW	Three-place couch. Reissued 6/20/78.	SO	28380	Cypress Aviation, Inc. 3840 Drone Field road Lakeland Airport Lakeland, FL 33803
PA-31 Series; T.C. A8EA	SA1204SW	Manual electric trim AK281. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31 Series; T.C. A8EA	SA1234SW	Mitchell automatic flight system FD/AP282-273, consisting of flight director /autopilot with optional automatic aileron stabilizer AK273. Issued 12/21/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31 Series; T.C. A8EA	SA1305SW	Auxiliary fuel tank. Issued 5/10/71.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1340SW	Four-place couch. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
PA-31 Series; T.C. A8EA	SA1569WE	Installation of windshield wiper system.	CE	88750	Alco Controls Corporation Box 12700 St. Louis, MO 63141
PA-31 Series; T.C. A8EA	SA1651WE	Installation of ski carrying pod under fuselage at wing root.	NW	57700	Melridge Aviation Company 1901 East Fifth Street Vancouver, WA 98661
PA-31 Series; T.C. A8EA	SA2124WE	Installation of air conditioning system.	RM	45750	J.B. Systems 120 South Bowen Circle Longmont, CO 80501
PA-31 Series; T.C. A8EA	SA3130SW-D	Mitchell automatic flight system AK589 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA1164SO	Installation of a Bendix FCS-870 automatic flight control system. Issued 7/2/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
PA-31; T.C. A20SO	SA3355SW	Mitchell automatic flight system AK846/FD consisting of Century IV/flight director autopilot with optional remote annunciator. Issued 2/19/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA3768WE	Installation of Fueltron digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31, PA-31-300; T.C. A8EA	SA603EA	Addition of a 32-inch high door on L.H. side of fuselage between fuselage stations 244-261. Reissued 6/21/78.	SO	28380	Cypress Aviation, Inc. 3480 Drone Field Road Lakeland Airport Lakeland, FL 33803
PA-31, -300; T.C. A8EA	SA744EA	Modification of toilet seat hassock and installation of safety belt. Issued 4/4/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31, -300; T.C. A8EA	SA1255SW	Mitchell automatic flight system Model AK324 consisting of Piper autoflite II and tracking system. Issued 1/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA1522SW	Mitchell automatic flight system AK394, consisting of Century I autopilot with optional omni tracker. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3008SW-D	Automatic flight system AK483 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim, radio, and glide slope couplers. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3009SW-D	Automatic flight system AK496 and AK496FD consisting of Century IV autopilot and Century IV flight director with command/automatic electric elevator pitch trim and optional annuciator panel. Issued 7/12/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -31-300; T.C. A8EA	SA3010SW-D	Automatic flight system YK491 consisting of yaw damper. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -31-300, -325, -350; T.C. A8EA	SA1318CE	Chrome-plated brake disc installation. Issued May 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-31, -31-325, -31-350; T.C. A20SO	SA454GL	Installation of Shadin Co. 910502 or 910504 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
PA-31 (S/N 31-712 and up), PA-31-325, -350; T.C. A8EA	SA1529CE-D	Installation of King KAS 297 altitude selector option. Issued 2/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, -31-300, -31-325, -350; T.C. A20SO	SA1595CE	Installation of TSO'd stretcher. Issued 6/5/80.	CE	12777	Avicon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
PA-31, -31-300, -325, -350; T.C. A8EA	SA3401WE	Installation of single piece windshield. Issued 5/10/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-31, 31-300, PA-31P; T.C. A8EA	SA852EA	Installation of Grimes 555 Series three light strobe kit P/N 34-0100-1. Amended 5/10/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-31, -31P, -31-325, -31-350; T.C. A8EA	SA437SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and optional flight director indicator. Amended 4/4/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31, -31P, -31T, -31-300, -325, -350, -31T1; T.C. A8EA	SA1000EA	Installation of single lamp logo light in horizontal tail. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
PA-31, -31P, -31-300, -325, -350; T.C. A8EA	SA1107CE	Installation of King Model PCS 55A pictorial navigation (compass) with optional KS 52 autopilot adapter. Issued 12/10/75.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31-350, -31-325; T.C. A8EA	SA1166CE	Installation of King KFC-200, 2 axis (3 optional) flight control system, autopilot only or autopilot with flight director. Amended 1/8/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31T; T.C. A8EA	SA178NW	Install redesigned [illegible] seat (toilet). Issued 5/12/70.	NW	70040	Seattle Flight Service, Inc. 7001 Perimeter Road Seattle, WA 98108

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31-300; T.C. A8EA	SA184GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31-300, -310, -325, -350; T.C. A8CE	SA1136CE	Installation of Fiquench cabin fire extinguisher and engine fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
PA-31-325; T.C. A8EA	SA1085CE-D	Installation of Collins Radio Group AP-106, 3-axis autopilot system. Amended 6/25/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1086CE-D	Installation of Collins Radio Group AP-107, 3-axis autopilot system. Amended 6/26/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1087CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system. Amended 6/26/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1088CE-D	Installation of Collins Radio Group yaw damper system. Amended 4/25/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA3017SW-D	Automatic flight system AK485 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim system, radio, and glide slope couplers. Issued 9/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3021SW-D	Automatic flight system AK500 and AK500FD consisting of Century IV autopilot and Century IV flight director autopilot with electronic command/automatic pitch trim system and optional annuciator panel. Issued 10/4/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3129SW-D	Automatic flight system AK590 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3211SW-D	Mitchell automatic flight system AK686 or AK686FD, Piper altimatic X flight director autopilot with optional remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325, -31-350; T.C. A20SO	SA300CE	Installation of propeller governors on single and twin engine aircraft: P/N L210571 left engine, R210571 right engine. Issued 1/2/80. P/N L210721 left engine, R210721 right engine. Issued 2/2/80. P/N L210573 left engine, R210573 right engine. Issued 5/7/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-31-325, PA-31-350 S/N 31-7405479 and up (S/N 31-5001 thru 7405478 when modified per Piper SL722); T.C. A20SO	SA4037WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel and totalizer system. Amended 3/13/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-31-350; T.C. A8EA	SA8NE	Installation of Collins AP-107 2-axis or 3-axis autopilot including yaw damper system. Reissued 12/19/74.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, NE Cedar Rapids, IA 52406
PA-31-350; T.C. A20SO	SA295GL	Install Cleveland conversion kit, P/N 199-63. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
PA-31-350; T.C. A8EA	SA932SO	Installation of Bendix FCS-870 automatic flight control system. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31-350; T.C. A8EA	SA934SO	Installation of Bendix NP-2041A area navigation computer. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31-350; T.C. A20SO	SA1119SO	Installation of twin cameras and two camera apertures on starboard side of the lower fuselage. Issued 5/8/80.	SO	64065	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31-350; T.C. A20SO	SA1122SO	Installation of single camera and camera aperature on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1124SO	Installation of a single camera and camera aperature and antenna fairing on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1125SO	Installation of twin cameras and two camera aperatures plus camera sights on starboard side of lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A8EA	SA1611SW	Mitchell automatic flight system AK413 consisting of altimatic IIIB-1 with optional automatic pitch trim, radio coupler, and glide slope couplers. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA1612SW	Mitchell automatic flight system AK416 consisting of autoflite II with optional tracking system. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA1807SW	AP106 2-axis or 3-axis autopilot including yaw damper and FD-108 flight director. Issued 2/14/74.	SW	24252	Collins Radio Company Box 98 Addison, TX 75001
PA-31-350; T.C. A8EA	SA3015SW-D	Automatic flight system AK-498, cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio, and glide slope coupler. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3016SW-D	Automatic flight system AK499 and AK499FD cons. of Century IV flight director autopilot w/command automatic electric elevator pitch trim and opt. annunciator panel. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3086SW-D	Automatic flight system AK560 cons. of Century III autopilot w/ opt. radio & glide slope couplers. Issued 11/27/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3212SW-S	Mitchell automatic flight system Piper altimatic X autopilot, AK687 or AK687FD Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A20SO	SA4096WE	Installation of SDI model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 1/10/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-31P-425;	SA204GL	Install Cleveland conversion kit.	GL	62500	Aircraft Wheel & Brake Division
PA-31T; T.C. A8EA	SA1178SO	Installation of a Bendix FCS-870 automatic flight control system including optional flight director. Issued 10/20/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
T.C. A8EA		P/N 199-03. Reissued 10/20/80.			Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
PA-31P; T.C. A8EA	SA493SO	Installation of Bendix Y34 yaw damper system. Issued 12/23/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
PA-31P; T.C. A8EA	SA702CE	Installation of King Radio [illegible] autopilot. Issued 6/71.	CE	48210	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
PA-31P; T.C. A8EA	SA1265SW	Mitchell automatic flight system model AK313 cons. of Piper Auto-flite II and Omni tracking system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	[illegible]	Mitchell automatic flight system AK195, cons. of Century autopilot w/opt. omni tracker. Issued [illegible].	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31P; T.C. A8EA	SA3012SW-D	Automatic flight system AK484 cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 8/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3013SW-D	Automatic flight system AK492 & AK492FD cons. of Century IV autopilot and Century IV flight director w/command automatic electric pitch trim and opt. annunciator panel. Issued 8/9/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3014SW-D	Automatic flight system YK493 cons. of yaw damper. Issued 8/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3213SW-D	Mitchell automatic flight system Piper altimatic X autopilot, AK688 or AK688FD, Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P, -31T, -31T1; T.C. A8EA	SA1594CE	Installation of TSO'd stretcher. Issued 6/5/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
PA-31T; T.C. A8EA	SA415GL	Installation of a Collins LRN 70 Omega navigation system. Issued 6/20/80.	GL	60568	Muncie Aviation Company P.O. Box 1169 Munci, IN 47305
PA-31T; T.C. A8EA	SA190GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 8/16/77.	GL	46250	Jet Electronics and Technology, Inc. 5353 52nd Street N.E. Grand Rapids, MI 49508
PA-31T; T.C. A1EA	SA213GL	Installation of storm window in right hand cockpit window duplicating storm window now installed in left hand cockpit window. Issued 2/2/78.	GL	61629	Northern Airmotive, Inc. 3600 East 70th Street Minneapolis, MN 55450
PA-31T; T.C. A8EA	SA578SO	Instl. of a Bendix M-4D automatic flight control system, including optional manual electric pitch trim and flight director system. Amended 10/1/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
PA-31T; T.C. A8EA	SA665NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. Issued 9/14/78.	NW	28850	Robert M. DeBorde 20645 S.W. Clarion Aloha, OR 97005
PA-31T; T.C. A8EA	SA1188CE	Intallation of King KFC 300 automatic flight control system. Amended 4/15/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31T; T.C. A8EA	SA4066SW	Auto-feather system 1. Issued 12/4/79.	EA	64665	Piper Aircraft Corporation 820 East Bald Eagle Drive Lockhaven, PA 17745
PA-31T, -31T1; T.C. A8EA	SA4016WE	Installation of SDI model CFS-2002, fuel flow indicating system. Amended 1/16/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-31T1; T.C. A8EA	SA1053SO	Installation of FCS-870 automatic flight control system, including manual electric trim, optional yaw damper system, and optional flight director. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31T1; T.C. A8EA	SA1054SO	Installation of Bendix RP-2041A area navigation computer programmer. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31T1; T.C. A8EA	SA1405CE	Install King KFC-250 autopilot/flight director. Amended 3/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32; T.C. A3SO	SA311NW	Installation of flap extension, spoiler L/E cuff and optional cambered wing tips. Issued 5/28/76.	NW	69500	Robertson Aircraft 839 W. Perimeter Road Renton, WA 98055
PA-32; T.C. A3SO	[illegible]	AK173 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-32; T.C. A3SO	SA1523WE	Inst'l. of Brittain Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-32; T.C. A3SO	SA1607WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-32-260; T.C. A3SO	SA371EA	Zeiss aerial camera and intervalometer.	NE	71400	James W. Sewall Co. 147 Center Street Old Town, ME 00468
PA-32-260; T.C. A3SO	SA409GL	Installation of a Lycoming IO-540-K1A5 engine, Hartzell propeller and associated components. Issued 5/23/80.	GL	60179	Melvin C. Morkert 915 Montclair Drive Racine, WI 53402
PA-32-260; T.C. A3SO	SA533SW	Auto-Control III AK174.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA538SW	Piper Altimatic II autopilot and/or radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA1310SW	Stretcher in lieu of rear seats. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, AR 72203
PA-32-260; T.C. A3SO	SA1557WE	Installation of turbosupercharged Lycoming O-540-E4B5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
PA-32-260, -32-300; T.C. A3SO	SA3NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 8/1/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
PA-32-260, -32-300; T.C. A3SO	SA530CE	Install FluiDyne Model 4000 & 2500A skis.	GL	36060	FluiDyne Engr. Corp. 5900 Olson Memorial Hwy. Minneapolis, MN 55422
PA-32-260, -32-300; T.C. A3SO	SA939SW	Mitchell Manual Electric Pitch Trim System AK272.	SW	76067	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300; T.C. A3SO	SA1362CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-32-260, -32-300; T.C. A3SO	SA1568SW	Wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-32-260, -32-300; T.C. A3SO	SA2217WE	Installation of recontoured wing leading edge, raked wing tips, fuselage flap, stall fences, droop ailerons and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 1540 Sunset Highway Bellevue, WA 98007
PA-32-260, -32-300; T.C. A3SO	SA2933WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 Wardlow Road Long Beach, CA 90807
PA-32-260, -32-300; T.C. A3SO	SA3173SW-D	Automatic flight system AK174 cons. of Piper autocontrol IIIB autopilot w/opt radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32R-300; T.C. A3SO	SA1172SW	Mitchell flight system AK306 cons. of Piper autoflite II with optional auto aileron stabilizer and tracking system. Issued 7/17/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32R-300; T.C. A3SO	SA1370SW	Mitchell automatic flight system AK320, cons. of Century I and opt. tracker. Issued 10/26/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300 -32R-300; T.C. A3SO	SA3011SW-D	Automatic flight system AK468 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 7/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-32-260, -300, -32R-300;	SA3736WE	Installation of an engine oil cooler hose. Issued 9/22/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-32-260, -300, -32S-300, -32R-300; T.C. A3SO	SA3839WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
PA-32-260, -300, -32R-300, -32RT-300, -32RT-300T; T.C. A3SO	SA364GL	For "T" tail configuration - installation of Norton radome kit No. 4229X. For conventional tail configuration - installation of Norton radome kit No. 4229XC. Amended 6/13/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Oeprations P.O. Box 350 Akron, OH 44309
PA-32-300; T.C. A3SO	SA893EA	Installation of 8-quart alcohol propeller anti-icing kit WAP-800A. Issued 12/15/71.	NE	86000	E. W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-32-300; T.C. A3SO	SA3305SW-D	Mitchell automatic flight system AK775 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 9/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300; T.C. A3SO	SA3306SW-D	Mitchell automatic flight system AK776, consisting of Century III autopilot with optional and glide slope couplers. Issued 9/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300, -32R-300; T.C. A3SO	SA1154EA	Installation of radome pod SERP-1011 or -1012 on right wing. Amended 12/6/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002
PA-32-300, -32R-300; T.C. A3SO	SA3570WE	Installation of Silver Instruments Fueltron IG digital fuel flow indicating system. Issued 6/23/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-32-300, -32R-300, -32S-300, -32RT-300; T.C. A3SO	SA3774WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-32-301, -301T; T.C. A3SO	SA3374SW-D	Mitchell automatic flight system AK872 consisting of command electric trim. Issued 6/16/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-301, -301T, -32R-301, -301T; T.C. A3SO	SA3361SW	Mitchell automatic flight system AK865 consisting of Century 41 autopilot or AK865FD consisting of flight director autopilot. Issued 5/9/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-301, -301T, -32R-301, -301T; T.C. A3SO	SA3362SW-D	Mitchell automatic flight system AK864 consisting of Century 21 autopilot. Issued 5/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R; T.C. A3SO	SA21NE	Installation of Whelen A600-PR and A600-PG anti-collision strobe with forward and tail position light assemblies as replacements for wing tip lights. Issued 3/1/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
PA-32R-200; T.C. A3SO	SA1102SW-D	Mitchell AK591, consisting of Century IIB autopilot w/opt radio coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-200; T.C. A3SO	SA1103SW-D	Mitchell AK592 cons. of Century III autopilot w/opt. radio coupler and glide slope coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA360GL	Install a Foster AirData RNAV 511 area navigation system with [illegible] (Alpha) or [illegible] (Delta) steering adapter, or without either adapter. Amended 6/29/79.	GL	[illegible]	Foster AirData Systems, Inc. 7020 Huntley Road Columbus, OH 43229
PA-32R-300; T.C. A3SO	[illegible]	Installation of two 15-gallon auxiliary fuel tanks, one in each wing. Issued 6/1/78.	SO	[illegible]	Cypress Aviation, Inc. [illegible] Drane Field Road Lakeland Municipal Airport Lakeland, FL 33803

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA32R-300 S/N 32R-7680001 and up; T.C. A3SO	SA1201CE	Installation of King KFC 200, 2 axis, flight control system with a King KCS-55 (or -55A) compass and a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 9/9/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32R-300; T.C. A3SO	SA3052SW-D	Mitchell automatic flight system AK529 cons. of Piper altimetric IIIC w/command/auto. elec. pitch trim, opt. radio coupler and glide slope coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3053SW-D	Installation of Mitchell automatic flight system AK530 cons. of Piper autocontrol IIIB autopilot with opt. radio coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3054SW-D	Mitchell automatic flight system AK531 cons. of Piper autoflite II w/opt. omni tracker. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3055SW-D	Mitchell command/electric trim system Model AK532. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3513WE	Installation of Rajay turbocharged Lycoming IO-540-K1G5D engine. Issued 11/8/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
PA-32RT-300; T.C. A3SO	SA429GL	Installation of Edo-Aire Mitchell automatic flight system Model AK771 consisting of a Century IV autopilot. Issued 8/4/80.	GL	08364	Airtronics, Inc. P.O. Box 297 Clintonville, WI 54929
PA-32RT-300, -32RT-300T;	SA1159EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
PA-32RT-300, PA-32RT-300T; T.C. A3SO	SA1430CE	Install King KFC-200 automatic flight control system. Issued 8/9/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32RT-300; T.C. A3SO	SA3253SW-D	Mitchell automatic flight system AK677 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3254SW-D	Mitchell command electric trim system AK 678. Issued 2/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3255SW-D	Mitchell automatic flight system AK 679 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300T; T.C. A3SO	SA3309SW-D	Installation of Mitchell automatic flight system consisting of Century IV autopilot or AK771 consisting of flight director autopilot with optional remote annunciator. Issued 10/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32S-300; T.C. A3SO	[illegible]	Installation of Pee Kay Model B3500 seaplane floats and Pee Kay Model 3500A amphibious floats. Issued 9/22/72.	EA	29998	Pee Kay Devcor Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-32R-300; T.C. A3SO	[illegible]	Installation of Edo Model PD-3500-29 amphibious floats. Reissued 1/26/78.	NE	[illegible]	[illegible] Corporation Gardner Municipal Arpt. Box [illegible] Gardner, MA [illegible]
PA-32R-300, -32R-300T; T.C. A3SO	[illegible]	Installation of King KFC 200 flight control system. Issued 12/13/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-28; T.C. [illegible]	[illegible]	Chrome-plated brake disc installation. Issued 6/16/75.	CE	[illegible]	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, K 66103

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-34; T.C. A7SO	SA2285SW	Camera and viewfinder installation. Issued 1/22/76.	SW	42825	A. D. Howard, Jr. 1911 Moulton Ct. Oklahoma City, OK 73127
PA-34-200; T.C. A7SO	SA154NW	Installation of full span flaps by removing aileron and changing deployment route of all flaps, spoilers mounted above flap, conical cambered wing tips, anti-balance rudder tab and optional dorsal fin. Issued 1/28/75.	NW	68500	Robertson Aircraft Corp. 839 W. Perimeter Road Renton, WA 98055
PA-34-200; T.C. A7SO	SA292NW	Installation of cooling louvers on top of both nacelle accessory sections. Issued 5/13/76.	NW	01530	Advanced Aviation 4911 S. 290th Place Auburn, WA 98002
PA-34-200; T.C. A7SO	SA493SO	Installation of Bendix FCS-810 (Piper altimatic V/FD) automatic flight control system including manual electric trim and optional flight director indicator. Issued 2/17/72.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
PA-34-200; T.C. A7SO	SA900EA	Installation of electrothermal propeller de-icer system. Amended 1/14/74.	GL	38500	B. F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200; T.C. A7SO	SA901EA	Installation of wing ice light kit. Amended 12/6/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200; T.C. A7SO	SA1321SW	Mitchell automatic flight system AK298 cons. of altimatic IIIB-1 autopilot w/opt automatic command electric pitch trim, radio coupler and glide slope coupler. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA1322SW	Mitchell automatic flight system Model AK335 cons. of Piper auto-control III w/opt. radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA1323SW	Mitchell command electric pitch trim Model AK321. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA2932WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA2937WE	Installation of turbosupercharged Lycoming IO/LIO-360-C1E6 engine. Amended 3/31/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA3002WE	Installation of wing tip fuel tanks of 17 gal capacity (each). Reissued 5/14/76.	WE	68501	Robertson Aircraft Corp. 2301 E. Utopia Rd. Phoenix, AZ 85024
PA-34-200, S/N 34-E4, S/N 34-7250001 and up; T.C. A7SO	SA903EA	Installation of B.F. Goodrich pneumatic de-icing system. Amended 11/1/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200, -34-200T; T.C. A7SO	SA50GL	Installation of Morton Radome Kit No. 4011KE Amended 3/15/79.	GL	61750	Morton Company Plastics & Synthetics Div. Aero Product Division P.O. Box 350 Akron, OH 44309
PA-34-200, -34-200T; T.C. A7SO	SA510NW	Installation of Cessna fuel tank assembly. Issued 6/20/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
PA-34-200, -34-200T; T.C. A7SO	[illegible]	Installation of vertical tail floodlights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
PA-34-200T; T.C. A7SO	[illegible]	Installation of freon type air conditioning system. Issued 6/3/77.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-34-200T; T.C. A7SO	[illegible]	Install Symbolic Displays [illegible] Model CFS-2000 fuel flow meter and related systems. Issued 5/22/78.	RM	77200	Symbolic Displays, Inc. 8885 Montview Boulevard Hangar 8 Denver, CO 80220

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-34-200T; T.C. A7SO	SA968SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 1/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7SO	SA969SO	Installation of NP-2041A area navigation computer programmer. Issued 1/9/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7DO	SA1118SO	Installation of Hartzell 3-bladed propellers, Models – PHC-C3YF-2( )UF/FC-7663-2R and PHC-C3YF-2L( )UF/FJC-7663-2R or PHC-C3YF—( )UF/FC-7663B-2R and PHC-C3YF-2L( )UF/FJC-7663B-2R. Issued 12/21/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
PA-34-200T; T.C. A7SO	SA1147CE	Installation of King Model KFC 200 flight control system, with King KCS 55 or 55A compass and a King KI-255 (or -256) flight command indicator on a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 9/13/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
PA-34-200T; T.C. A7SO	SA1553CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-34-200T; T.C. A7SO	SA3023SW-D	Automatic flight system AK487 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electronic elevator pitch trim, radio, and glide coupler. Issued 9/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3024SW-D	Automatic flight system AK505 cons. of Piper auto-control IIIB autopilot w/opt. radio coupler. Issued 10/24/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3089SW-D	Mitchell automatic flight system AK561 cons. of Century III Autopilot w/opt radio coupler and glide slope coupler. Issued 12/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3669WE	Installation of FUELTRON III3 digital fuel flow indicating system. Issued 6/21/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-34-200T; T.C. A7SO	SA4207WE	Installation of DTL-1000, -1001 and/or autopilot adapters for the Edo-Aire Mitchell Century III autopilot. Issued 8/8/8[illegible].	WE	[illegible]7775	Douglas L. Kettler Apt. H 1212 North Broadway Escondido, CA 92026
PA-36; T.C. A9SO	SA277NW	Installation of automatic flagman. Issued 3/30/76.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362
PA-36; T.C. A9SO	SA1364CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33460	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	SA1291CE	Installation of Lycoming IO-720-A1B engine. Amended 4/17/79.	CE	19003	Mr. Clinton Anderson [illegible]
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	[illegible]	Installation of Lycoming IO-720-A1B engine and Hartzell [illegible] constant speed propeller. Amended [illegible]	WE	[illegible]	Johnston Aircraft Service, Inc. P.O. Box [illegible] Tulare Municipal Airport Tulare, CA [illegible]
PA-36-375; T.C. A10SO	[illegible]	Installation of hydraulic system to power spray dispersal system. Issued 12/21/77.	WE	[illegible]	Agrinautics [illegible] Lane Las Vegas, NV [illegible]
PA-36-375; T.C. A10SO	[illegible]	Installation of hydraulic power spray pump. Issued [illegible]	WE	[illegible]	Agrinautics [illegible] Lane Las Vegas, NV [illegible]
PA-39 series; T.C. A1EA	[illegible]	Installation of [illegible] propeller [illegible] Amended [illegible]	[illegible]	[illegible]	[illegible] [illegible] Municipal Airport [illegible]

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-39 Series; T.C. A1EA	SA1342SW	Mitchell automatic flight system AK296 cons. of Piper altimatic IIIB-1 autopilot w/opt. automatic pitch trim, radio, and glide slope couplers. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1343SW	Mitchell automatic flight system AK325 cons. of Piper autoflite II w/opt. tracking system. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1344SW	Mitchell command electric trim AK267. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1386SW	Mitchell automatic flight system model AK339, cons. of Piper autocontrol III autopilot with optional radio coupler. Issued 11/16/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1638SW	Mithcell automatic flight system AK355, consisting of Century I with omni tracker. Issued 4/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-40; T.C. A1EA	SA3028SW-D	Mitchell auto. flight system AK481, consisting of Piper altimatic IIIC autopilot with command automatic electric pitch trim system, optional radio, and glide slope couplers. Issued 10/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-40; T.C. A1EA	SA3036SW-D	Automatic flight system AK506 consisting of Piper autocontrol IIIB autopilot with optional radio coupler. Issued 12/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA436GL	Installation of full microwave landing system airborne equipment. Issued 8/22/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
PA-44-180; T.C. A19SO	SA1158EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
PA-44-180; T.C. A19SO	SA1504CE	Installation of King KFC 200 FCS (2 axis) with or without flight director. Issued 8/2/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-44-180; T.C. A19SO	SA3276SW-D	Installation of Mitchell automatic flight system AK 723 consisting of Piper autocontrol IIID with optional radio couplers. Issued 6/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA44-180; T.C. A19SO	SA3277SW-D	Mitchell automatic flight system AK719 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 6/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3278SW-D	Mitchell command electric trim AK719.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3267SW-D	Mitchell automatic flight system AK716 consisting of Century IIB autopilot with optional radio coupler. Issued 5/26/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180; T.C. A19SO	SA3268SW-D	Mitchell automatic flight system AK717 consisting of Century III autopilot with optional radio and and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180, -44-180T; T.C. A19SO	[illegible]	Mitchell automatic flight system [illegible] consisting of Century 41 autopilot or [illegible]. Issued [illegible].	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180, -44-180T; T.C. A19SO	[illegible]	Mitchell automatic flight system [illegible] consisting of Century 21 autopilot. Issued [illegible].	SW	6000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-44-180, -44-180T; T.C. A19SO	SA3377SW-D	Yaw damper system YK875. Issued 6/4/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MISCELLANEOUS	SA788WE	Mixture monitor (exhaust gas temperature probe and gage). See FAA-approved eligibility list for models.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PIPER AIRCRAFT CORP., CALIFORNIA

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
600; T.C. A17WE	SA1347SW	Alternate vent for fuel pressure gages. Issued 7/22/71.	SW	84250	Vought Aircraft Service Company Meacham Field Fort Worth, TX 76106
600; T.C. A17WE	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
600; T.C. A17WE	SA1675WE	Installation of K S Avionics EGT-2 exhaust gas monitoring system. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
600 (S/N 60-0266-XX and up, and those aircraft with previously installed option #108); T.C. A17WE	SA3770WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 6/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
600, 601; T.C. A17WE	SA35GL	Install Cleveland Aircraft Products wheel and brake conversion kit, P/N 199-51. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
600, 601; T.C. A17WE	SA443SO	Instllation of Bendix RDR-110 weather radar system per Bendix drawing 4009700, Rev. B. Installation of Norton AD4059RX-5 radome approved per STC SA845EA. Issued 9/25/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601; T.C. A17WE	SA771CE	Installation of Woodward propeller unfeathering accumulator system. Issued June 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601; T.C. A17WE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
600, 601; T.C. A17WE	SA845EA	Installation of radome kit P/N 4059RX or 4059X. Reissued 9/29/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
600, 601; T.C. A17WE	SA1305SW	Addition of toilet provision. Issued 5/7/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1350SW	Fabricate and install rib-wing fairing-inboard (flap attachment bracket). Issued 6/11/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1362SW	Storage drawers under cabin seats. Issued 6/3/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1363SW	Installation of pressure relief valves in fuel tanks. Issued 6/3/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1382SW	Modify two passenger seats to face aft. Issued 10/26/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	[illegible]	Dual hydraulic pump. Issued 11/12/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	[illegible]	[illegible] control tube [illegible] Issued [illegible]	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	[illegible]	[illegible] automatic flight system [illegible] Issued [illegible]	SW	[illegible]	[illegible] Industries, Inc. P.O. Box [illegible] Municipal Airport Mineral Wells, TX [illegible]

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
600, 601; T.C. A17WE	SA2357WE	Installation of auxiliary hydraulic pump. Issued 5/28/71.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
600, 601; T.C. A17WE	SA3884WE	Installation of cabin door pneumatic spring counter-balance. Issued 4/5/79.	WE	64423	Physical Systems, Inc. 7049 Vineland Avenue North Hollywood, CA 91605
600, 601, 601P; T.C. A17WE	SA20GL	Installation of Woodward Type II electronic propeller synchronizer system. Amended 7/30/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601, 601P; T.C. A17WE	SA300CE	Installation of Woodward propeller governors on single and twin engine aircraft. Amended 7/30/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601, 601P; T.C. A17WE	SA444SO	Intallation of Bendix Model FCS 810 flight control system, including flight director indicator DH 841( ). Amended 6/3/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601, 601P; T.C. A17WE	SA1009CE-D	Installation of Collins Radio Group AP-106 autopilot system and interface with Collins FD-112 flight director. Amended 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1090CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1104CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1139SO	Installation of a Bendix FCS-870 automatic flight control system. The following options are included: preselect altitude, yaw damper and flight director system. Issued 3/13/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601, 601P; T.C. A17WE	SA1174CE	Installation of Aero Space Controls Corp. 100 AMP alternator. Issued 10/31/75.	CE	82950	Aero Space Controls Corporation 1050 North Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1175CE	Installation of Aero Space Controls Corp. air conditioning system. Issued 10/31/75.	CE	82950	Aero Space Controls Corporation 1050 West Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1184CE	Install King Model KFC-200 2-axis (3 optional) flight control system with King KCS-55 (or -55A) compass and a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a MC-202 mode controller. Amended 9/5/75.	CE	46250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
600, 601, 601P; T.C. A17WE	SA1277CE	Installation of [illegible] Industries [illegible], P/N [illegible] or [illegible]. Amended [illegible]	CE	[illegible]	[illegible] Industries, Inc. [illegible] Wichita, KS [illegible]
600, 601, 601P; T.C. A17WE	[illegible]	Installation of King KAS 297 altitude selector system. Issued [illegible]	CE	46250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
600, 601, 601P; T.C. A17WE	[illegible]	Installation of [illegible] air conditioning system. Amended [illegible]	[illegible]	[illegible]	[illegible] Systems, Inc. [illegible] [illegible]
600, 601, 601P; T.C. A17WE	[illegible]	Installation of [illegible] (Avco Lycoming [illegible]) [illegible] [illegible]	WE	[illegible]	Piper Aircraft Corporation Santa Maria Division [illegible] Santa Maria, CA [illegible]
600, 601, 601P; T.C. A17WE	[illegible]	Installation of [illegible] (Avco Lycoming [illegible]) [illegible] [illegible]	[illegible]	[illegible]	Piper Aircraft Corporation Santa Maria Division [illegible] Santa Maria, CA [illegible]

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
600, 601, 601P; T.C. A17WE	SA2655WE	Installation of auxiliary hydraulic pump option. Reissued 4/11/78.	WE	64846	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA3029SW-D	Mitchell automatic flight system AK521 consisting of Century III autopilot with command automatic electric pitch trim system, radio, and glide slope couplers. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3030SW-D	Mitchell automatic flight system AK522 or AK522FD consisting of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim and optional annunciator panel. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3033SW-D	Automatic flight system AK455 consisting of Century I autopilot with optional omni tracker. Issued 1/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P (S/N 60-0266-[illegible] and up and those aircraft with previously installed option 6108); T.C. A17WE	SA3370WE	Installation of Silver Instruments Fueltron 3333 or 333P digital fuel flow and totalizer system. Issued 6/20/79.	WE	71760	Silver Instruments, Inc. 2360 Stanwell Drive Concord, CA 94520
600, 601, 601P; T.C. A17WE	SA3372SW-D	Automatic flight system [illegible] consisting of yaw damper system. Issued 6/27/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3643WE	Installation of vertical tail floodlight. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite D 6104 Kircher Street, N.E. Albuquerque, NM 87109
600, 601, 601P S/N 266 and up and aircraft with option 908 previously installed; T.C. A17WE	SA4012WE	Installation of SDI Model CFS-2000, -2001, or FT-280 fuel flow indicating system. Issued 5/21/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
600, 601, 601P; T.C. A17WE	SA4016WE	Installation of 30 ampere-hour batteries. Issued 5/1/80	WE	[illegible]	[illegible] Aircraft Company 3700 State Street, Suite 208 P.O. Box [illegible] Santa Barbara, CA 93111
601; T.C. A17WE	SA2566WE	Installation of turbocharger overboost protection. Reissued 4/11/78.	WE	64846	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601; T.C. A17WE	SA2654WE	Modification of fuselage structure for pressurization to [illegible] psi operating pressure, and installation of pressurization system. Reissued 4/11/78.	WE	64846	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601P; T.C. A17WE	[illegible]	Installation of oxygen kit [illegible] Reissued [illegible]	GL	[illegible]	[illegible] Company [illegible] Division [illegible] Products Operations P.O. Box [illegible] [illegible], OH [illegible]

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35-C33, E33, F33; T.C. 3A15	SA1365SW	Mitchell automatic flight system model AK347 cons. of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA1366SW	Mitchell automatic flight system model AK316, cons. of Century III autopilot with optional automatic pitch trim, radio coupler, glide slope coupler. Issued 9/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3163SW-D	Install automatic flight system AK316 consisting of Century III autopilot with optional command automatic pitch trim system, radio coupler, and glide slope coupler. Issued 11/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3204WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Amended 12/20/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
35-C33A, E33A, E33C, F33A, F33C, G33; T.C. 3A15	SA3248SW-D	Mitchell automatic flight system AK716 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 10/3/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
E33, E33A, E33C, F33, F33A, F33C; T.C. 3A15	SA1550CE	Installation of elevator and rudder tail cone fairings. Issued 2/29/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 61 Johnson, KS 67855
E33, -A, -C; F33, -A, -C; T.C. 3A15	SA2057WE	Installation of Brittain Industries B-VII, NAV-2B, B2C and BSA4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
F33A; T.C. 3A15	SA1164CE	Installation of King KFC-200 two axis autopilot system with King KI-255 (or -256) flight command indicator or King KG-258 altitude horizon indicator with a KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
F33A; T.C. 3A15	SA3230SW-D	Mitchell automatic flight system AK660, consisting of Century IIB autopilot with optional radio coupler. Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3232SW-D	Mitchell automatic flight system AK662, consisting of Century IV autopilot or AK662FD consisting of Century IV flight director with optional remote annunicator. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3229SW-D	Mitchell automatic flight system AK659 consisting of Century I autopilot with optional omni tracker. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, Tx 76067
F33A; T.C. 3A15	SA3231SW-D	Mitchell automatic flight system AK661, consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3233SW-D	Mitchell command electric trim AK663. Issued 9/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3234SW-D	Mitchell yaw damper system K664 Issued 9/22/77	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3348SW	Installation of Mitchell automatic flight system AK821/FD consisting of Century 41/flight director autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A; T.C. 3A15	SA3349SW	Installation of Mitchell automatic flight system AK820 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
F33A; T.C. 3A15	SA3357SW-D	Mitchell yaw damper system YK837. Issued 3/17/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
F33A, G33, 36, A36; T.C. 3A15	SA480SO	Installation of Bendix FCS-810 automatic flight control system, including manual electrim trim and flight director indicator DH-841( ). Amended 10/4/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FI 33310
F33A, S/N CE-316 & up; T.C. 3A15	SA1232SW	Mitchell automatic flight system AK315 cons. of Century III with optional automatic pitch trim, radio and glide slope coupler. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, E33A, 35-C33A, F33C; T.C. 3A15	SA1233SW	Mitchell automatic flight system AK317 cons. of Century I and optional tracking system. Issued 12/9/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1865SW	Mitchell automatic flight system AK448, Century IV autopilot and AK448FD, Century IV flight director with electronic command/automatic pitch trim. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA1866SW	Mitchell automatic flight system AK452 cons. of Century III autopilot with optional electronic command/automatic pitch trim, radio coupler, and glide slope coupler. Issued 4/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA3087SW-D	Mitchell command electric trim AK563. Issued 12/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, 36A; T.C. 3A15	SA3193SW-D	Mitchell automatic flight system AK452 consisting of Century III autopilot with optional command automatic electronic pitch trim, radio, glide slope coupler. Issued 4/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
F33A, 36, A36; T.C. 3A15	SA4211SW	S-TEC system 60 (two axis) flight guidance system, ST-014, with optional flight director/steering horizon and optional vertical speed indicator/selector (14 volt system). Issued 10/2/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
F33A, A36; T.C. 3A15	SA4240SW	S-TEC system 60 (two axis) roll/pitch flight guidance system, ST-018, with optional flight director/steering horizon and optional vertical speed indicator/selector (28 volt system). Issued 12/5/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
G33; T.C. 3A15	SA571EA	Installation of Brittain Industries Models B7, NAV-2B, B2C and BSA4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
G33; T.C. 3A15	SA818CE	Install Hartzell propeller model BHC-I2YF-1BF/F8468AR with spinners A2295, or model PHC-L3YF-1RF/F8468A-6R with spinners A2295-1. Issued 1/14/72.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
35/36 Series; T.C. 3A15	SA1711WE	Installation of Brittain Industries B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35/36 Series; T.C. 3A15	SA1712WE	Installation of Brittain Industries BSA-4 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
35, 50 Series; T.C. 777, 3A15, 5A4	SA856WE	Glassfiber reinforced plastic wing tips.	WE	00450	ACKO P.O. Box 1431 Torrance, CA 90510
35, 50 Series; T.C. 777, 3A15, 5A4	SA998WE	Glass fiber reinforced plastic wing tips. Amended 6/13/69.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, 95 Series; T.C. 777, 3A15, 3A16	SA1-381	Installation of Fram Oil Filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
35, 95 Series; T.C. 777, 3A15, 3A16	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
36 Series; T.C. 3A15	SA961SW	Mitchell automatic flight system AK275 cons. of Century III autopilot with optional radio coupler, automatic pitch trim, aileron stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36 Series; T.C. 3A15	SA1916WE	Installation of Brittain Model NAV-2E Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
36; T.C. 3A15	SA2068WE	Installation of Brittain Models B-VII, NAV-2B, B2C and BSA-4 flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
36, A36; T.C. 3A15	SA994NW	Installation of a Continental TSIO-520-D engine, McCauley 2A36C82-T/S-84B-2 or 2A32C76-T/82NB-2 propeller and Rajay turbocharger system. Issued 7/23/80.	NW	35690	Flightcraft, Inc. 7505 N.E. Airport Way Portland, OR 97218
36, A36; T.C. 3A15	SA1145CE	Installation of King Model KFC-200, 2 axis (3 optional) or stand alone yaw damper for Beech Model A36 S/N E572 and later autopilot system with a King KI-255 (KI-256 optional) flight command indicator with the KC-292 mode controller. Amended July 1977.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
36, A36; T.C. 3A15	SA1231SW	Mitchell automatic flight system model AK311, cons. of Century II autopilot with optional radio coupler. Issued 12/8/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1360SW	Mitchell automatic flight system Model AK346 cons. of Century III autopilot with optional pitch trim, radio coupler, and glide slope coupler. Issued 8/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1634SW	Mitchell AK423 cons. of 1C707 omni/localizer converter. Issued 3/27/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA1635SW	Mitchell AK417/FD cons. of flight director/autopilot with command electric trim. Issued 3/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3118SW-D	Automatic flight system AK448, Century IV autopilot or AK448FD, Century IV autopilot flight director with optional remote annuciator. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3119SW-D	Automatic flight system AK452 cons. of Century III autopilot with optional command/automatic electronic elevator pitch trim, radio and glide slope couplers. Issued 3/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
36, A36; T.C. 3A15	SA3244WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 8/11/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
36, A36; T.C. 3A15	SA4132SW	S-TEC system 60-1 (single axis) flight guidance system, SF006. Issued 5/29/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
36, A36, A36TC; T.C. 3A15	SA1448CE	Installation of elevator tail cone fairing. Amended 3/24/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A36, Serial No. E185 and up; T.C. 3A15	SA84RM	Installation of freon type air conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
A36; T.C. 3A15	SA283GL	Installation of a Continental IO-520-B, -BA engine modified in in accordance with STC SA282GL and a Symbolic Displays fuel flow indicating system, Model CFS-1000. Issued 11/14/78.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport Rockford, IL 61109
A36; T.C. 3A15	SA1093CE	Installation of AP-107 (2 axis) autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1095CE	Installation of AP-106 autopilot system and interface with Collins 329A-4V indicator. Amended July 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1096CE	Installation of yaw damper system. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1097CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
A36; T.C. 3A15	SA1544CE	Installation of microwave landing system. Issued 1/22/80.	SW	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MC 64127
A36; T.C. 3A15	SA3203SW-D	Mitchell yaw damper model YK670 Issued 5/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3204SW-D	Mitchell automatic flight system AK668 consisting of Century IV autopilot or AK668FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 5/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3205SW-D	Automatic flight system AK667 consisting of Century III autopilot with optional radio coupler and Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3206SW-D	Mitchell command electric trim model AK669. Issued 6/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3207SW-D	Mitchell automatic flight system consisting of Century I autopilot with optional omni tracker. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA3208SW-D	Mitchell automatic flight system AK666 consisting of Century IIB autopilot with optional radio coupler. Issued 5/19/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A36; T.C. 3A15	SA334USC	Mitchell automatic flight system AK810 consisting of Century 41 flight director autopilot. Issued 7/25/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36; T.C. 3A15	SA4106WE	Modification of the rudder and brake systems to provide hand controls in addition to the conventional systems. Issued 3/25/80.	WE	05225	Aircraft Inspection & Maintenance, Inc. 2680 East Wardlaw Road Long Beach, CA 90807
A36, A36TC; T.C. 3A15	SA1106SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and option yaw damper and flight director. Issued 10/11/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
A36, A36TC; T.C. 3A15	SA1496CE	Installation of King KFC 200 automatic flight control system. Amended 7/1/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A36, A36TC; T.C. 3A15	SA1527CE-D	Installation of King KAS 297 altitude selector option. Issued 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
A36, A36TC; T.C. 3A15	SA3351SW-D	Mitchell yaw damper system YK832. Issued 3/11/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36TC; T.C. 3A15	SA3329SW-D	Mitchell automatic flight system AK754 consisting of Century IV autopilot or Model AK754FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 1/2/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
A36TC; T.C. 3A15	SA3330SW-D	Mitchell automatic flight system AK753, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/2/79.	SW	60000	Mitchel Industries, Inc. P.O. Box 610 Mineral Wells, TX 75056
A36TC; T.C. 3A15	SA4114WE	Installation of Silver Instruments Fueltron IG or IP digital fuel flow and totalizer system. Issued 2/26/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
A36TC; T.C. 3A15	SA4140WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 4/10/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
45 Series; T.C. 5A3	SA366WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
45 Series; T.C. 5A3	SA425SW	Nose landing gear door removal.	SW	22700	Civil Air Patrol Corporation National Headquarters Ellington AFB, TX 77030
A-45 (T-34A, B-45); T.C. 5A3	SA876CE	Remove Continental O-470-13 or O-470-13A engine and propeller. Install Continental IO-470-N engine and Hartzell BHC-L2YF-FC846AR propeller. Issued December 1972.	CE	15250	Beech Aircraft Corporation 9709 East Central Wichita, KS 67206
A-45 (T-34A, B-45); T.C. 5A3	SA2211SW	Mitchell Century I Model AK409 autopilot with omni tracker. Issued 7/17/75.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA1864SW	Continental IO-520-B engine and McCauley 3A32C76/82NB-2 propeller. Issued 4/11/74.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
A45; T.C. 5A3	SA3191SW-D	Mitchell automatic flight system AK649 consisting of Century I autopilot with optional omni tracking system. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A45; T.C. 5A3	SA3192SW-D	Automatic flight system AK651 conosisting of Century IIB autopilot with optional radio coupler. Issued 2/25/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D45; T.C. 5A3	SA183GL	Modification of basic aircraft for Restricted Category Airworthiness Certification by removing rudder-aileron bungee interconnect system, elevator down spring system and tail cone fairing. Issued 6/21/77.	GL	61302	Michigan Dept. of Natural Resource Stevens T. Mason Bldg. Lansing, MI 48926
50 Series; T.C. 5A4	SA1-262	Bendix Pioneer 9100-17-C1 fuel flow meter system.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series; T.C. 5A4	SA1-291	Radio shelves in nose baggage shelves.	EA	15210	Beckett Aviation Corporation Allegheny County Airport Dravosburg, PA 15034
50 Series; T.C. 5A4	SA1-357	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series; T.C. 5A4	SA1-443	2002X-R radome assembly.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
50 Series; T.C. 5A4	SA1-503	Electrothermal propeller deicing system. (Applicable to aircraft with two 50-amp. generators or greater.)	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50 Series; T.C. 5A4	SA3-208	Acron B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA3-703	Accumulator for unfeathering Hartzell HC-83XF, HC-93Z20 or HC-B3Z20 propellers.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA4-51	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-221	Autopilot L-2.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-382	Radio rack.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
50 Series; T.C. 5A4	SA4-439	Fiberglass reinforced plastic wing tips.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
50 SEries; T.C. 5A4	SA4-462	L-2 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-549	Federal F-400 autopilot.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
50 Series; T.C. 5A4	SA4-758	Aerofilter 30690B full flow lube oil filter with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
50 Series; T.C. 5A4	SA4-807	Automatic rudder control Model B.	GL	49858	Lear, Inc. 3714 Jefferson Avenue, S.E. Grand Rapids, MI 49501
50 Series; T.C. 5A4	SA4-808	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
50 Series; T.C. 5A4	SA4-1417	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA3CE	Governor 210385. (Not eligible with accumulator unfeathering system.)	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA5CE	Propeller governors incorporating unfeathering accumulator shutoff valves. (Eligible only on aircraft equipped with Beech unfeathering system.)	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA24SW	Cabin seats. (Seat tracks installation per STC SA2-1068 required.)	SW	83650	Vicars Custom Aircraft Interiors 3709 N. Main Fort Worth, TX 76101
50 Series; T.C. 5A4	SA25CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA31SW	Automatic pilot AK104.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA41CE	Governor 210159.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA75SW	Landing gear doors. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
50 Series; T.C. 5A4	SA76SW	Lycoming IGSO-540-B1A engines with associated powerplant changes, and landing gear doors; increase gross weight to 7,300 lbs. takeoff and 7,000 lbs. landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, Tx 78216
50 Series; T.C. 5A4	SA81SW	Automatic pilot AK119.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
50 Series; T.C. 5A4	SA158EA	Autopilot T-3 and altitude hold AH-1 as an accessory item.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
50 Series; T.C. 5A4	SA166CE	Twin-engine electronic synchronizer and unfeathering system.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA167CE	Electronic synchronizer kit.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA198SW	Three-place couch.	SW	85128	Westernair of Albuquerque, Inc. Route 6, Box 88 Albuquerque, NM 87101
50 Series; T.C. 5A4	SA207SW	Dual control. (Pilot's and copilot's seat installations per STC SA2-1068 required.) Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA213CE	Twin-engine electronic synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
50 Series; T.C. 5A4	SA242SW	Lycoming GO-480-G2D6 engines and increase in gross weight to 6,300 pounds. Reissued February 1973.	GL	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA323EA	7541K nose cap weather radome.	NE	53750	McMillan Radiation Labs, Inc. Brownville Avenue Ipswich, MA 01938
50 Series; T.C. 5A4	SA348SW	Radar nose. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA360SW	GO-480-G2D6 or -G2F6 engines and increase in weight to 6,000 pounds. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA370SW	Seven place seating capacity.	SW	80625	United Airmotive 1105 DeRidder Fort Worth, TX 76106
50 Series; T.C. 5A4	SA392WE	Beech pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA430SW	Pilot and copilot cockpit seats.	SW	34080	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
50 Series; T.C. 5A4	SA405WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA433SW	Cabin door and stair.	SW	27242	Cross Roads Aviation, Inc. Addison Airport Addison, TX 75001
50 Series; T.C. 5A4	SA514SW	Six place seat and/or hat shelf.	SW	36125	Flying V Interiors Meacham Field Fort Worth, TX 76106
50 Series; T.C. 5A4	SA517SW	Goodrich wheel and brake. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
50 Series; T.C. 5A4	SA587SW	Lycoming IO-720-A1A engines, increase gross weight 7,600 pounds, 7,240 pounds landing. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
50 Series; T.C. 5A4	SA655SW	Lycoming IGSO-480-A1A6 engine; wing, vertical tail, landing gear modified, control system increased gross weight to 7,300 pounds takeoff, and 7,000 pounds landing.	SW	27242	Cross Roads Aviation, Inc. P.O. Box 60464 AMF Houston, TX 77060
50 Series; T.C. 5A4	SA1013WE	Advanced Army Aircraft Instrumentation System (AAAIS) and associated aircraft modifications.	WE	30400	Douglas Aircraft Company, Inc. 3855 Lakewood Boulevard Long Beach, CA 90801
50 Series; T.C. 5A4	SA1324WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50 Series; T.C. 5A4	SA1385WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA1-565	Installation of radome kit No. 2002X. Amended 2/24/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA99CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights Model 1 or 2. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGAw Avenue Irvine, CA 92705
50, B50, C50, D50, D50A, D50B, D50C, D50E-5990, D50E, E50E, F50, G50, H50, J50; T.C. 5A4	SA276GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 1/17/79.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA383CE	Installation of Hoskins Twi. III supplementary high intensity lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA390GL	Install Cleveland conversion kit, P/N 199-88. Issued 6/18/80.	GL	62500	Parker Hannifin Corporation Aircraft Wheel & Brake Division 1160 Center Road Avon, OH 44011
50, B50 thru J50, D50A, B, C, D, E; 65, 65-80, 65-A8800, 65-B80 all; T.C. 5A4, 3A20	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA1644WE	Installation of a Torginol Special Product Co. KarBar.	RM	25250	Combs Aircraft, Inc. Stapleton International Airport Denver, CO 80207
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA2631WE	Installation of Bellon Concrete, Inc. single piece windshield or alternate single piece sloped windshield. Amended 3/20/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4550 Jettridge Drive Atlanta, GA 30327
50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50; T.C. 5A4	SA2872WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
B50; T.C. 5A4	SA452GL	Installation of a Shadin Co. 910502 or 910504 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Suite 206 Minneapolis, MN 55426
B50, C50, D50; T.C. 5A4	SA2413WE	Modification of fuel vent outlet. Issued 9/3/71.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
C50; T.C. 5A4	SA3062SW-D	Mitchell AK370 cons. of Century III autopilot with command/automatic electronic pitch trim system, optional radio coupler, and glide slope coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C50; T.C. 5A4	SA3063SW-D	Mitchell automatic flight system AK542 cons. of Century IIB autopilot with optional radio coupler. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
D50, D50A, D50C, E50, F50, G50, H50; T.C. 5A4	SA1-453	Installation of Tactair T-3 automatic pilot and optional installation of Tactain AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
D50, D50A, B, C, E; T.C. 5A4	SA3138SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3139SW-D	Mitchell automatic flight system AK613, consisting of Century IIB autopilot with optional radio coupler. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, B, C, E; T.C. 5A4	SA3140SW-D	Mitchell automatic flight system AK606, consisting of Century I autopilot with optional omni tracker. Issued 5/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50 - modified - Excaliber STC SA587SW; 56TC, A56TC, 58, 58A, 58P, 58PA, 58TC, 58TCA, 60, A60, B60; 65, A65, 65-80, -A80, -A80-8800, -B80, -88, -70 modified - Excalibur STC SA444SW; 95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A (95-55, -A55, -B55 modified - Colemill STC SA432SO; T.C. 5A4, 3A16, A12CE, A23CE, 3A20, 3A16	SA20GL	Installation of Woodward Type III electronic propeller synchronizer or synchrophaser system. Amended 9/25/78.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
D50C, E; T.C. 5A3	SA1334SW	Mitchell automatic flight system AK337, cons. of Century II autopilot with optional radio coupler. Issued 7/1/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA31WE	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
D50E; T.C. 5A4	SA33WE	Autopilot M-4.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
D50E; T.C. 5A4	SA391WE	Installation of Brittain Model B2D Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D50E; T.C. 5A4	SA837SW	Mitchell AK255 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
D50E; T.C. 5A4	SA974CE	Installation of KNR 665 digital area navigation system. Amended May 1974.	CE	48250	King Radio Corporation Box 106 Olathe, KS 66061
E50, F50, G50, H50, J50; 80, A80, 65; T.C. 5A4, 3A20	SA1686WE	Installation of Vibration Isolation Products engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
50, 65 Series; T.C. 5A4, 3A20	SA15EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44309
50, 65 Series; T.C. 5A4, 3A20	SA476EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
55, A55; B55, C55, D55, 56TC; 65-B80, A65-8200, 65-90, A90; 95, B95, B95A, D-95A, E95; T.C. 3A16, 3A20	SA1874WE	Installation of Brittain up-command signal adapter kit on certain airplanes equipped with Brittain models B-4A, B-4AP, B-5 and B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA681CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114
B55, C55; 95 Series; T.C. 3A16	SA1591WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1548WE	Installation of a Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55; T.C. 3A16	SA1934WE	Installation of an approach speed control system. Reissued 12/4/69.	EA	69500	Safe Flight Instrument Corp. Box 550 White Plains, NY 10602
D55, E55, E55A, 56TC, A56TC, 58, 58A, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 58P, 58PA, 58TC; TC 3A16	SA453SO	Installation of Bendix Model FCS 810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 10/19/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FI 33310
D-55, D55A, E55, E55A, 58, 58A, 56TC, A56TC, 95; T.C. 3A16	SA2048WE	Installation of Brittain Industries Model B-VII or NAV-2B or B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
D55, D55A, E55, E55A, 56TC, 58, 58A, 95, B95, B95A, D95A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A; T.C. 3A16	SA2871WE	Installation of right and left hand cockpit side windows. Reissued 2/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
E55; T.C. 3A16	SA126GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MC 64127
E55; T.C. 3A16	SA896SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 4/22/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
E55; T.C. 3A16	SA3068WE	Installation of fuel flow instruments. Issued 8/8/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1126CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE982 and up); T.C. 3A16	SA1127CE	Installation of Collins AP-107 (2 axis) autopilot systems. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55/E55A (S/N TE-982 and up); T.C. 3A16	SA1128CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
E55, 58; T.C. 3A16	SA1008CE	Installation of an electric motor driven freon vapor cycle air conditioning system. Amended 10/9/74.	CE	02950	Aero Space Controls 1050 N. Mosley Wichita, KS 67214
56TC; T.C. 3A16	SA383SO	Installation of Bendix M-4C autopilot flight control system. Amended 7/14/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33309
56TC; T.C. 3A16	SA632CE	Install wing leading edge fuel tanks. Reissued 4/4/78.	CE	48800	KWAD II Company RFD #4, Box 14 Newton, KS 67114
56TC; T.C. 3A16	SA713CE	Conversion of wing tips to integral fuel tanks.	CE	16292	Frank R. Berry and William T. McKay Route 1, Box 204A Augusta, KS 67010
56TC; T.C. 3A16	SA1770WE	Installation of Brittain Industries Models B-5 or NAV-2B or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
56TC, A56TC; T.C. 3A16	SA1041CE	Replace existing nickel-cadmium battery with lead-acid battery. Issued January 1975.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
56TC, A56TC, 58, 58A, 58TC, 58TCA; T.C. 3A16	SA4194SW	Installation of camera port. Issued 9/2/80.	SW	42800	A.D. Howard Route 2, Box 4 Culdesac, ID 83524
56 TC; 95 Series; T.C. 3A15, 3A16	SA1505WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
58 Series; T.C. 3A16	SA860EA	Installation of Aircraft Radio Corp. AF-530A automatic pilot system and electric operated elevator trim system. Amended 1/18/71.	EA	05950	Aircraft Radio Corporation Rockaway Valley Road Boonton, NJ 07005
58 Series; T.C. 3A16	SA1174SW	Mitchell automatic flight system FD/AP282-303 cons. of flight director/autopilot, automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1175SW	Auto flight system AK303 cons. of Century III, autopilot, with optional auto pitch trim, radio, and glide slope couplers. Issued 7/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA1192SW	LN2 air conditioner system. Issued 9/22/70.	SW	83100	Ves-Kol Inc. 2805 National Drive Garland, TX 75040
58 Series; T.C. 3A16	SA1199SW	Mitchell automatic flight system 305 cons. of Century II autopilot with optional stabilizer and radio coupler. Issued 10/2/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58 Series; T.C. 3A16	SA3119WE	Installation of Pathfinder autopilot systems. Issued 12/16/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
58, 58A; T.C. 3A16	SA94RM	Installation of freon type air conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
58, 58A; T.C. 3A16	SA1045CE	Installation of Collins Radio Co. AP-107 autopilot system (2 axis). Amended February 1975.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1106CE-D	Installation of Collins Radio Group AP-106 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1107CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1108CE-D	Installation of Collins Radio Group AP-107 axis autopilot system and interface with Collins FD-112V flight director. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
58, 58A; T.C. 3A16	SA1687SW	Mitchell automatic flight system Model YK428 cons. of yaw damper. Issued 6/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1786SW	Mitchell Automatic Flight System AK451 cons. of Century III Autopilot with Electronic Pitch Trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA1787SW	Mitchell Automatic Flight System AK447 cons. of Century IV Autopilot or AK447FD cons. of Century IV/Flight Director with Electronic Command/Automatic Pitch trim. Issued 1/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
58, 58A; T.C. 3A16	SA3131SW-D	Mitchell automatic flight system AK447, Century IV autopilot or AK447FD Century IV flight director autopilot with remote annuciator. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3132SW-D	Mitchell automatic flight system AK451, consisting of Century III autopilot with optional command automatic electric pitch trim, radio and glide slope couplers. Issued 4/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3341SW	Mitchell yaw damper systems, YK781. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3342SW	Mitchell automatic flight system AK816/FD consisting of Century 41/flight director autopilot. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A; T.C. 3A16	SA3350SW	Installation of Mitchell automatic flight system AK815 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58, 58A, 58P, 58PA, 58TC, 58TCA, 65-80, -A80, -B80, -88, 95-C55, -C55A, D55, D55A, E55, E55A; T.C. A23, 3A20, 3A16	SA300CE	Installation of Woodward propeller governor on single and twin engine airplanes. Amended 9/18/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
58, 58A, 95-C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA486GL	Installation of a Shadin Co. 910502 or 910504 fuel flow indicating system. Issued 1/13/81.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Minneapolis, MN 55426
58, 58A, TH-1 and up; T.C. 3A16	SA863CE	Installation of Airborne/Goodyear pneumatic iceguard deicing system. Issued August 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
58, 58A, 95-B55, -B55A; T.C. 3A16	SA935SO	Installation of a Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Amended 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
58, 58A, 95-B55, -B55A; T.C. 3A16	SA936SO	Installation of Bendix NP-2041A area navigation computer programmer. Amended 4/10/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
58P; T.C. A23CE	SA113GL	Installation of Norton radome kit 4109X. Amended 2/3/81.	GL	61758	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
58P, 58PA, 58TC, 58TCA (S/Ns TJ115 thru TJ118, TJ126 and up, TK51 thru TK55, TK59 and up); T.C. A23CE	SA501GL	Installation of Shadin Company 910502 or 910504 fuel flow indicating system. Issued 2/12/81.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Minneapolis, MN 55426
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA978SO	Installation of NP-2041A area navigation computer programmer. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA979SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional yaw damper and optional flight director. Issued 4/12/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
58P, 58PA, 58TC, 58 TCA; T.C. A23CE	SA1123CE	Install AP-106 autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1124CE	Install AP-107 (2 axis) autopilot and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1125CE	Install AP-107 (3 axis) autopilot system and interface with either Collins FD-106 or FD-112 flight director. Amended May 1977.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1150CE	Installation of King Model KFC-200, 2-axis and KC-291 yaw damper FCS. Amended 6/2/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA1524CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3038SW-D	Mitchell automatic flight system AK449 or AK449FD cons. of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim and optional remote annuciator panel. Issued 1/17/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3039SW-D	Automatic flight system YK445 yaw damper system. Issued 1/17/75.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3040SW-D	Automatic flight system AK453 consisting of Century III autopilot optional command/automatic elec-electronic pitch trim system, radio and glide slope couplers. Issued 2/5/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3311SW-D	Mitchell automatic flight system AK453 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/22/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3338SW-D	Mitchell automatic flight system system AK813 consisting of Century 41 autopilot or AK813FD consisting 41 flight director autopilot with optional remote annunciator. Issued 4/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3344SW	Mitchell yaw damper system YK781. Issued 10/26/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
58P, 58PA, 58TC, 58TCA; T.C. A23CE	SA3499WE	Installation of tail flood lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
58P, 58TC; T.C. A23CE	SA178GL	Install Cleveland conversion kit, P/N 199-73. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
58P, 58TC; T.C. A23CE	SA3769WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
58P, 58TC, 58TCA; T.C. A23CE	SA4050WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Reissued 3/25/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
58TC; T.C. A23CE	SA124GL	Install Norton Company radome, P/N 4083X. Amended 2/3/81.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
60 Series; T.C. A12CE	SA1006SW	Mitchell Automatic Flight System AK291, cons. of Century III autopilot with optional pitch trim servo, radio and glide slope couplers.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60; T.C. A12CE	SA659SO	Installation of Bendix M-4C automatic flight control system, including manual electric trim, and/or installation of Bendix YD-4 yaw damper. Amended 11/10/72.	SO	15475	Bendix Avionics P.O. Box 9414 Ft. Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
60, A60; T.C. A12CE	SA945CE	Replacement of existing nickel-cadmium battery with lead-acid battery, Teledyne PS12-24. Amended October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133
60, A60; T.C. A12CE	SA1587SW	Mitchell automatic flight system YK380 consisting of yaw damper. Issued March 1973.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60; T.C. A12CE	SA1704SW	Mitchell automatic flight system AK429, cons. of Century IV autopilot with trim or AK429/FD cons. of Century IV autopilot/flight director with trim. Issued 7/20/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA154GL	Installation of Norton radome kit, No. 4132X. Issued 2/16/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
60, A60, B60; T.C. A12CE	SA179GL	Install Celveland conversion kit, P/N 199-73. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
60, A60, B60; T.C. A12CE	SA539SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator and/or YD-4 yaw damper. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
60, A60, B60; T.C. A12CE	SA1023CE	Installation of Collins Radio Co. AP-106 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1024CE	Installation of AP-107 autopilot and associated flight director. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A12CE	SA1025CE	Installation of yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
60, A60, B60; T.C. A2CE	SA1741SW	Mitchell automatic flight system AK450 cons. of Century autopilot with optional radio coupler automatic/command pitch trim, glide slope coupler. Issued 10/12/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3151SW-D	Mitchell automatic flight system AK429 consisting of Century IV autopilot or AK429/FD consisting of Century IV flight director with optional remote annuciator. Issued 7/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
60, A60, B60; T.C. A2CE	SA3162WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 3/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
60, A60, B60; T.C. A12CE	SA3293SW-D	Yaw damper system YK380. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3367SW-D	Mitchell automatic flight system AK870 consisting of Century 41 autopilot or AK870FD consisting of Century 41FD autopilot. Issued 5/6/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3368SW-D	Mitchell automatic flight system YK871 consisting of yaw damper system. Issued 5/6/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
60, A60, B60; T.C. A12CE	SA3605WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel indicating system. Amended 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
60, A60, B60; T.C. A12CE	SA3905WE	Installation of SDI Model CFS-200, -2001, or FT-200 fuel flow indicating system. Issued 4/13/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
60, 65-A80, B80, 65-88, 70; T.C. A12CE, 3A20	SA889EA	Installation of Grimes three light strobe Kit P/N 34-0116-1 and -2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
60, A60, B90, C90, E90, 65-90, -A90, 100, A100; T.C. A12CE, 3A20, A14CE	SA2638WE	Installation of CCC BWS 50-08 Nicad battery overheat warning system. Amended 9/18/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
A60; T.C. A12CE	SA85RM	Installation of Teledyne Avionics angle of attack indicating system. Issued 11/2/76.	RM	14127	Avionics Engineering of Denver, Inc. 8895 Montview Boulevard, Hangar B Denver, CO 80220
A60; T.C. A12CE	SA1029CE	Installation of AP-106 and AP-107 automatic flight control systems and yaw damper system. Issued June 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
B60; T.C. A12CE	SA570SO	Installation of Bendix M-4D automatic flight control system, including optional manual electric trim and optional flight director indicator. Issued 12/6/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
B60; T.C. A12CE	SA1470CE	Installation of King KFC 250 flight control system (3 axis) using 3-inch or 4-inch indicators. Issued 2/5/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
65 Series; T.C. 3A20	SA1-643	Radar antenna mounts: 296-01 for 12" Collins WP-103 antenna; 296-03 12" RCA AVQ-55 antenna and 296-02 for 12" RCA AVQ-50 antenna.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series; T.C. 3A20	SA3-516	Autopilot E-2C with or without 1350B approach coupler and 2203D2 altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA4CE	Propeller governors incorporating unfeathering accumulator shutoff valves.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
65 Series; T.C. 3A20	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
65 Series; T.C. 3A20	SA46WE	Full flow lube oil filter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
65 Series; T.C. 3A20	SA92CE	High intensity wing tip lights Model A, tail light Model C, with or without high intensity fuselage lights Model 1 or 2.	GL	42625	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
65 Series; T.C. 3A20	SA139SW	Buffet. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
65 Series; T.C. 3A20	SA161CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
65 Series; T.C. 3A20	SA186EA	Throttle stop device.	EA	87118	Stephen J. Wisey, Jr. 8 Steamboat Road Great Neck, NY 11022
65 Series; T.C. 3A20	SA188CE	Twin-engine synchronizer.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
65 Series; T.C. 3A20	SA201EA	Sperry SP 3 elevator trim drive servo and trim tab bracket.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
65 Series; T.C. 3A20	SA210SO	Radar system AVQ55.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
65 Series; T.C. 3A20	SA218SW	Automatic pilot AK105.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA255CE	Oil tank heater blanket kit 65-42.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67206

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65 Series; T.C. 3A20	SA269SW	Brushless generators, voltage regulators and control panels.	EA	37376	General Electric Company Specialty Controls Department Waynesboro, VA 22980
65 Series; T.C. 3A20	SA277EA	Installation of Chamberlain 2090K-B radome kit for Bendix 100 or RDR-110 radar systems with transmitter/ receiver unit and 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
65 Series; T.C. 3A20	SA280EA	2011K-B Series radome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
65 Series; T.C. 3A20	SA296CE	M4B or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA307CE	GUARD system (gear up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612
65 Series; T.C. 3A20	SA336EA	PB-60 autopilot.	EA	15600	The Bendix Corporation Eclipse-Pioneer Division Teterboro, NJ 07608
65 Series; T.C. 3A20	SA393EA	Electronic voltage alarm.	EA	53500	McKinley Engineering Company P.O. Box 275 Palisades Park, NJ 07650
65 Series; T.C. 3A20	SA411CE	M4B or M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
65 Series; T.C. 3A20	SA444SW	Lycoming IO-720A1A engines and increase in takeoff and loading weight. Reissued February 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65 Series; T.C. 3A20	SA470SW	Automatic pilot AK122 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA471SW	Automatic trim system AK149.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA505CE	Install entrance door.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65 Series; T.C. 3A20	SA528SW	Lear 164 electro-mechanical rotary actuator.	SW	42131	H & H Enterprises P.O. Box 75135 Oklahoma Ctiy, OK 73125
65 Series; T.C. 3A20	SA651SW	AK206 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA695SW	Engine induction system air filter removed.	SW	71800	Sinclair Oil & Gas Company Aviation Department 3505 N. Sheridan Road Tulsa, OK 74101
65 Series; T.C. 3A20	SA704CE	Installation of BUTLER VAC and ADD navigation system. Amended April 1974.	CE	19000	Butler National Corporation 8246 Nieman Road Lenexa, KS 66214
65 Series; T.C. 3A20	SA722SW	AP-103F/FD-108 autopilot flight director system and related electronics.	SW	24252	Collins Radio Company P.O. Box 98 Addison Airport Addison, TX 75001
65 Series; T.C. 3A20	SA767SW	Mitchell Model AK 239 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65 Series; T.C. 3A20	SA1004WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65 Series; T.C. 3A20	SA1022WE	B-4 flight control system (PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1453WE	Installation of a Brittain Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1511WE	Pacific Airmotive Corp. rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
65 Series; T.C. 3A20	SA1528WE	Installation of Brittain B-4AP Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1556WE	Installation of Brittain Industries B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA1714WE	Removal of emergency exit to permit aircraft to engage in special purpose operations, as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
65 Series; T.C. 3A20	SA1794WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A20	SA2069WE	Installation of Brittain B-VII Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65, A65, A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 70; T.C. 3A20	SA22GL	Installation of Hartzell synchrophaser. Reissued 8/27/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
65, A65, 65-80, 65-A80, 65-B80; T.C. 3A20	SA43CE	Installation of Bendix M-4B and M-4C flight control system. Amended 3/8/67.	EA	15480	The Bendix Corporation Avionics Products Bendix Radio Division Baltimore, MD 21204
65, 65-80, 65-A80, 65-90; T.C. 3A20	SA318EA	Installation of Monitair angle of attach and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
65-L23F, 65-80, 65-A80, 65-B80, -90, -A90; T.C. 3A20	SA394CE	Install Hoskins Twi. Mk III supplemental high intensity lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
65, 65-80; T.C. 3A20	SA1-642	2011X Series radome. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
65, 65-80; T.C. 3A20	SA506WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTL Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
65, 65-80; T.C. 3A20	SA518SW	Goodrich wheel and brake. Reissued Feburary 1973.	SW	33950	Excalibur Aviation Company P.O. Box 32007 San Antonio, TX 78216
65, A65, 65-80, A65-8200, 65-A80, -A80-8800, -B80, -88, -70; T.C. 3A20	SA277GL	Installation of a fire detection sensor, Systron-Donner P/N 3001-79-700/300-26 and associated hardware. Amended 12/21/78.	GL	55426	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
65, A65, 65-80, 65-A80, -B80, 65-88, 70; T.C. 3A20	SA1183SO	Replace existing nickel-cadmium battery with Teledyne Gill BB 640/T series lead-acid battery. Issued 11/12/80.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road Atlanta, GA 50339
65, A65, -80, -A80, -A80-8800, A65-8200, -B8Q, 70; T.C. 3A20	SA1244SW	Mitchell automatic flight system FD/AP282-313 cons. of flight/director/autopilot and automatic pitch trim. Issued 1/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65, A65, A65-8200, 65-80, -A80, -A80-8800, -B80, -88, -90, -A90, 70, B90, C90, E90; T.C. 3A20	SA1279CE	Installation of Avcon Ind. TSO-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
65, A65, 65-80; T.C. 3A20	SA1328SW	Replacement of existing alternators with 100 ampere Prestolite ALV-8042's. Reissued 10/20/72.	SW	61500	Nayak Aviation Corporation 206 E. Terminal Avenue San Antonio, TX 78216
65, A65, A65-8200, 65-80, -A80, -A80-880, -B80, -88, -90, -A90, -A90-1, -A90-2, -A90-3, -A90-4, 70, B90, C90, E90; T.C. 3A20	SA1583CE	Install wing front spar reinforcement kit. Issued 4/11/80.	WE	13177	Aviadesign, Inc. Suite 101, Bank of America, Levy Building 5808 E. Telephone Road Ventura, CA 93003
65, A65, 65-80, 65-A80; T.C. 3A20	SA2349SW	3-place divan. Issued 8/13/76.	SW	36550	Foster-Edwards Aircraft Co., Inc. Box 574 Addison, TX 75001
65, A65, A65-8200, 70; T.C. 3A20	SA2365WE	Installation of Hartzell HC-3X20-2/9333C or HC-A3X20-2/9333C propellers. Reissued 7/14/71.	SW	37080	Bernard A. Gallaher 1400 Southwest Tower Houston, TX 77002
65, A65, A65-8200, 65-80, -A80, -A80-8800, -B80, -88, 70, 65-90, -A90, A90-1, -2, -3, -4, B90, C90 (S/N LJ502 thru 526); T.C. 3A20	SA3080WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
65, A65, 65-80, -A80, -B80, -A80-8800; T.C. 3A20	SA3114SW-D	Automatic flight system AK548, cons. of Century III autopilot with optional radio and glide slope couplers. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, 65-80, -A80, -B80, -A80-8800, A65-8200, 70; T.C. 3A20	SA3115SW-D	Mitchell AK585, cons. of Century IV autopilot or AK585FD Century IV flight director autopilot. Issued 3/18/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65, A65, -80, -A80, -B80, -88, -90, C90, E90, 65-A90, A99, 99, B99, 100, A100, B100, 200, A200; T.C. 3A20, A14CE, A24CE	SA4157SW	Install one, two, or three place side facing seat (frame only). Issued 7/25/80.	WE	28000	Custom Aircraft Conversions 234 West Turbo Drive San Antonio, TX 78216
65-80; T.C. 3A20	SA185CE	Installation of AC Spark Plug Division oil filter assembly type OF-103-A, P/N 6435565; or type OF-105-A, P/N 25010400. Amended 6/5/80.	GL	00750	AC Spark Plug Division of General Motors Flint, MI 48556
65-80; T.C. 3A20	SA1009EA	Installation of Edo area navigation system Model TCE-71A. Reissued 12/19/78.	EA	32625	EDO-AIRE Div. of Edo Corporation 216 Passaic Avenue Fairfield, NJ 07006
65-80, -A80, -B80, -88, -90, -A90; T.C. 3A20	SA381EA	Installation of radome kit No. 2090X. Amended 12/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
65-80, -A80, -B80, -88, -90, -A90, B90, C90, E90, 100, A100, A100A, A100C, B100; T.C. 3A20, A14CE	SA37GL	Installation of Norton radome kit No. 2090XS. Amended 8/24/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
65-80, -A80, -A80-8800, -B80, -88; T.C. 3A20	SA453GL	Installation of a Shadin Co. 910502 or 910504 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Suite 206 Minneapolis, MN 55426
65-A80, -B80, -88, -90, -A90, -B90; T.C. 3A20	SA45GL	Install AMF inverter MGH 549-1. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
65-80, A-80, B-80; T.C. 3A20	SA2283WE	Installation of oil lever indicator system. Issued 11/30/70.	WE	25600	Communications Components Corp. 1524 West 15th Street Long Beach, CA 90813

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65-B80 Queen Air; T.C. 3A20	SA940SO	Removal of existing fuel flowmeter and associated components and installation of fuel flowmeter. Issued 6/24/77.	SO	02850	Aerosonic Corporation P.O. Box 4627 Clearwater, FL 33518
65-B80; T.C. 3A20	SA1607CE	Installation of microwave landing system airborne equipment. Issued 9/26/80.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MC 64127
A65, 65-B80 & 70; T.C. 3A20	SA660CE	Installation of Bendix M4-C Flight Control System.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33310
65-90; T.C. 3A20	SA133GL	Install B.F. Goodrich thermally efficient propeller de-icers. Amended 9/15/76.	GL	38500	B.F. Goodrich 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA826SW	Elevator electric trim system.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 - Adams Field Little Rock, AR 72203
65-90; T.C. 3A20	SA897EA	Installation of B.F. Goodrich electrothermal propeller deicing system. Issued 2/7/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Company 500 South Main Street Akron, OH 44318
65-90; T.C. 3A20	SA1108SO	Installation of Pratt & Whitney engine model PT6A-20 replacing model PT6A-6. Issued 10/15/79.	SO	14213	B. R. Power Division Aztec Leasing, Inc. 20 Piney Mountain Road Greenville, SC 29607
65-90; T.C. 3A20	SA2740SW	Installation of P&W PT6A-135 engines and bleed air conditioning and pressurization system. Issued 3/24/78.	SW	77111	E.J. Swearingen P.O. Box 4640 Waco, TX 76705
65-90, -A90; T.C. 3A20	SA761SW	Mitchell AK238 consisting of Century III autopilot with optional pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
65-90, -A90; T.C. 3A20	SA822SO	Installation of P & W PT6A-28 engines. Amended 3/27/78.	SO	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
65-90, 65-A90, 65-B90; T.C. 3A20	SA526SO	Installation of the Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-90, -A90, B90, C90, E90; T.C. 3A20	SA546SO	Instllation of Bendix M-4D automatic flight control system including optional manual electric trim system and optional flight director system. Issued April 1980.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Launderdale, FL 33310
65-90, -A90, -B90; T.C. 3A20	SA1177SW	Revised main landing gear doors.	SW	61500	Nayak Aviation Corporation 206 E. Terminal Drive San Antonio, TX 78216
65-90, -A90, B90, C90; T.C. 3A20	SA2693WE	Installation of inertial air separator scoops. Reissued 4/28/77.	WE	39877	Gordon B. Hamilton d/b/a Hamilton Aircraft Company P.O. Box 11427 Tucson, AZ 85706
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA810CE	Battery temperature sensing and over-temperature warning systems. Amended October 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA879SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA951CE	Installation of lead-acid battery. Issued October 1973.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, 99, A100; T.C. 3A20	SA1017SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65-90, 65-A90, B90, C90, E90; T.C. 3A20	SA1194CE	Install Teledyne/Gill lead-acid battery, BB638/T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	78052	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hill, KS 67133
65-90, 65-A90, B90, C90, E90, H90; T.C. 3A20	SA1451CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, 65-A90, B90 C90, E90, H90; T.C. 3A20	SA1452CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
65-90, A90, B90, C90, E90, 99, 99A, A99A, 100, A100; T.C. 3A20	SA2284SW	Ignition current monitor system. Issued 1/19/76.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
65-90, -90A, -A90-1, -2, -3, -4, B90, C90, E90, 99, 99A, A99, A99A, B99, 200, A200, 200T; T.C. 3A20, A14CE, A24CE	SA566NW	Installation of parachute deployment system. Issued 3/27/78.	NW	80915	U.S. Forest Service 3905 Vista Avenue Boise, ID 83705
65-90, -A90, -A90-1, -A90-2, -A90-3, B-90, C-90; 99, 99A; T.C. 3A20, A14CE	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457
65-90, -A90, -A90-1, -A90-2, -A90-3, -A90-4, B90, C90, E90; T.C. 3A20	SA2907WE	Installation of fuel tank boost pump. Amended 11/18/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
65-90, -A90, B90, C90; T.C. 3A20	SA3266SW-D	Mitchell automatic flight system AK725 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 2/24/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
65-90, -A90, B90, C90, E90; T.C. 3A20	SA3369SW-D	Automatic flight system YK835 consisting of yaw damper system. Issued 7/21/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
65-A90; T.C. 3A20	SA691CE	Installation of fuel drain manifold tank.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65-A90; T.C. 3A20	SA729SW	Installation of Collins AP-103F/FD-108 autopilot/flight director system and related electronics. Amended 2/14/68.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-A90; T.C. 3A20	SA845CE	Installation of wing flap override switch and duplicate flap down limit switch. Issued May 1972.	GL	37808	General Motors Corporation Air Transport Section Willow Run Airport Ypsilanti, MI 48197
65-A90; T.C. 3A20	SA1813SW	Battery temperature sensing and indicating system. Issued 3/8/74.	SW	02300	Aero Instrument Supply, Inc. 7515 Lemon Avenue Box 7481 Dallas, TX 75209
65-A90, -A90-1, B90; T.C. 3A20	SA418SO	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
65-A90, B90; T.C. 3A20	SA16GL	Install AMF inverter MGE 23-400. Reissued 11/17/78.	GL	50360	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
65-A90, B90, C90; T.C. 3A20	SA377GL	Addition of fourth cabin window on right hand side of fuselage. Issued 11/28/79.	GL	18320	Burlington Northern Airmotive International Airport Minneapolis, MN 55450
65-A90, B90, C90, E90; T.C. 3A20	SA1630CE	Installation of portable airway checking equipment rack on existing seat rails. Issued 1/21/81.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
65-A90, -B90, -C90, E90; T.C. 3A20	SA3971WE	Installation of SDI Model CFS-2002, fuel flow indicating system. Amended 10/19/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
65-A90-1, 65-A90-4; T.C. 3A20	SA1556CE-D	Installation of KFC 250 flight control system (3 axis). Amended 1/9/81.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
65-B90, -A90 with 90-4031 kit; T.C. 3A30	SA537CE	Installation of Collins AP-103F/FD108 and AP-103F/FD109G Autopilot and flight director. Amended 9/13/68.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
65-B90, -A90 with 90-4031 kit; T.C. 3A20	SA567CE	Installation of Collins AP-103F/FD108 and AP-103F/FS108G, AP-103F/FD109G autopilot and flight director. Amended 5/4/70.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA569CE	Installation of Collins AP104/FD109H Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA603CE	Installation of Collins AP-104/FD-109F Flight Control System.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
B90; T.C. 3A20	SA988CE	Installation of fuel dump valve; G.W. increase to 10,000 pounds. Amended 3/9/70.	CE	65300	Product Development Group, Inc. P.O. Box 177 Rose Bill, KS 67133
B-90; T.C. 3A2	SA1665SW	Fabricate and install bar assembly. Issued 5/29/73.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
B-90, C-90; T.C. 3A20	SA1454SW	Mitchell automatic flight system model FD/AP282-318 cons. of flight director/autopilot with optional command trim. Issued 4/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B-90, C-90; T.C. 3A20	SA1458SW	Mitchell automatic flight system AK318 cons. of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 4/24/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90; T.C. 3A20	SA1517SW	Automatic flight system YK384 cons. of yaw damper. Issued 9/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90; T.C. 3A20	SA1583SW	Foxtronics/TRAMM BT1 600 nickel-cadmium battery temperature system. Issued 1/3/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
65-B90, C90, E90; T.C. 3A20	SA547CE	Installation of Bendix M4C autopilot. Amended 8/1/72.	SO	15475	The Bendix Corporation Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
65-B90, C90, E90; T.C. 3A20	SA1640SW	Mitchell automatic flight system AK422/FD cons. of Century IV autopilot/flight director with command electric trim. Issued 4/19/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90, E90; T.C. 3A20	SA3042SW-D	Mitchell automatic flight system AK456 or 456 FD cons. of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim system and optional remote annuciator panel. Issued 1/31/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
B90, C90, E90; T.C. 3A20	SA3294SW-D	Yaw damper system YK384. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
B90, C90, E90; T.C. 3A20	SA3379SW-D	Mitchell automatic flight system AK878 consisting of Century 41 autopilot or AK878 FD consisting of Century 41 flight director autopilot. Issued 6/30/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C90; T.C. 3A20	SA537SO	Installation of Bendix YD-4 yaw damper. Issued 5/15/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90; T.C. 3A20	SA541SO	Installation of Bendix FCS-810 automatic flight control system including optional flight director indicator DH-841. Amended 1/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
C90; T.C. 3A20	SA925EA	Installation of Collins AP-105 autopilot system. Issued 6/28/72.	NE	08160	AIRKAMAN, Inc. Bradley International Airport Windsor Locks, CT 06096
C90, E90; T.C. 3A20	SA546SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim system and optional flight director system. Amended 5/16/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
C90, E90; T.C. 3A20	SA3124WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
C90, E90, F90, 99; T.C. 3A20, A14CE, A31CE	SA1013SO	Replace existing nickel-cadmium battery with Gill BE638/T series lead-acid battery. Amended 1/21/81.	SO	78054	Teledyne Battery Products 7520 Powers Ferry Road Suite 200 Atlanta, GA 30339
E90; T.C. 3A20	SA2667WE	Installation of Sperry SPZ-200 autopilot and Stars Instrument System or SPI-77C flight director system. Amended March 1974.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90; T.C. 3A20	SA2680WE	Category II approval of airborne instruments and equipment. Reissued 9/17/73.	CE	15250	Beech Aircraft Corporation 9709 E. Central Wichita, KS 67201
E90, F90, B100; T.C. 3A20, A31CE, A14CE	SA250CE	Installation of Woodward electronic propeller synchrophaser system. Amended 12/10/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
E90, 99, A100, 200; T.C. 3A20, A14CE, A24CE	SA920SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78052	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
76; T.C. A29CE	SA1153EA	Installation of DeVore "tel-tail" lights on lower surface of horizontal stabilizer. Reissued 7/24/79.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
76; T.C. A29CF	SA1455CE	Installation of DFC200 flight control system (2 axis). Issued 10/17/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
76; T.C. A29CE	SA3256SW-D	Mitchell automatic flight system AK694 consisting of Century IV autopilot or AK694FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3257SW-D	Mitchell automatic flight system AK693 consisting of Century III autopilot with opticanl radio and glide slope couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3258SW-D	Mitchell automatic flight system AK692 consisting of Century III autopilot with optional radio couplers. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3259SW-D	Mitchell AK619 consisting of Century I autopilot with optional omni tracker. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3260SW-D	Mitchell command electric trim AK695. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
76; T.C. A29CE	SA3261SW-D	Yaw damper system AK696. Issued 1/25/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3317SW-D	Installation of Mitchell automatic flight system AK761 consisting of Century I autopilot with omni tracker. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
76; T.C. A29CE	SA3318SW-D	Installation of Mitchell automatic flight system AK762 consisting of Century IIB autopilot with optional radio couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3319SW-D	Installation of Mitchell automatic flight system AK763 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3320SW-D	Installation of Mitchell automatic flight system AK764 consisting of Century IV autopilot or AK764FD consisting of Century IV autopilot flight director with optional remote annunciator. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3321SW-D	Installation of Mitchell automatic flight system AK765 consisting of command electric trim system. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3322SW	Installation of Mitchell yaw damper YK766. Issued 11/20/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
76; T.C. A29CE	SA3345SW	Installation of Mitchell yaw damper YK838. Issued 1/28/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3346SW	Mitchell automatic flight system AK827/FD consisting of Century 41/FD flight director autopilot. Issued 12/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA3356SW	Installation of Mitchell automatic flight system AK826 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Incc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
76; T.C. A29CE	SA4005WE	Removal of main landing gear door. Issued 7/25/79.	WE	71630	Sierra Academy of Aeronautics Oakland International Airort Oakland, CA 94614
95 Series; T.C. 3A16	SA1-235	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
95 Series; T.C. 3A16	SA1-395	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-422	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA1-482	16" x 17" opening in lower surface of fuselage.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
95 Series; T.C. 3A16	SA1-588	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
95 Series; T.C. 3A16	SA3-262	Automatic pilot L-2 with or without approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-470	L-2C autopilot with or without approach coupler and altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA3-624	Winslow oil filter 30409A.	CE	80670	United Airplane Sales, Inc. Municipal Airport Wichita, KS 67202

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95 Series; T.C. 3A16	SA3-633	Autopilot I-2C with or without approach coupler and/or altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA4-574	Radio rack in nose compartment.	RM	05940	Aircraft Radio & Accessory Co. Stapleton Air Field Denver, CO 80202
95 Series; T.C. 3A16	SA4-691	Oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
95 Series; T.C. 3A16	SA4-1052	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
65 Series; T.C. 3A16	SA4-1612	Anticollision beacon Roto-Lite X6000, either 12 or 24 volt, on vertical fin	WE	49690	The Norman Larson Company Van Nuys Airport Van Nuys, CA 91408
95 Series; T.C. 3A16	SA9SW	Aileron trimmer ATC35-107.	SW	06000	Aircraftsmen, Inc. Hangar 2, Will Rogers Field Oklahoma City, OK 73125
95 Series; T.C. 3A16	SA44EA	Wet pump pneumatic deicing.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA70SW	Vapor automatic temperature control system.	CE	82540	Vapor Heating Company 2522 E. Douglas Wichita, KS 67202
95 Series; T.C. 3A16	SA74CE	Federal F-400 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
95 Series; T.C. 3A16	SA92SW	Automatic pilot AK103 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA171WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oaklana, CA 94608
95 Series; T.C. 3A16	SA173EA	Beech 5D1048 air reservoir assembly relocated for wing and tail boot deicer.	NE	08160	AirKaman, Inc. Bradley Field Windsor Locks, CT 06096
95 Series; T.C. 3A16	SA231EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
95 Series; T.C. 3A16	SA287CE	GUARD System (Gear Up Automatic Response Device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA311WE	Beech pneumatic pitch assist PC-1 and optional installation altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA316EA	M4C flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
95 Series; T.C. 3A16	SA360CE	Windshield wiper.	GL	27500	Curtiss-Wright Corporation Marquette Division 1145 Galewood Drive Cleveland, OH 44110
95 Series; T.C. 3A16	SA474EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
95 Series; T.C. 3A16	SA474WE	B4 flight control system including basic autopilot, pitch assist PC-1, altitude hold AH-1, and navigational coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA516SW	Automatic trim AK160.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95 Series; T.C. 3A16	SA617SW	III autopilot, automatic pitch trim, stabilizer and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA742SW	AF196 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95 Series; T.C. 3A16	SA831WE	Single-place windshield.	WE	69590	SAFE-SITE, Inc. 3511 W. Sixth Street Los Angeles, CA 90005
95 Series; T.C. 3A16	SA844WE	One-piece windshield.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
95 Series; T.C. 3A16	SA1494WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1532WE	Installation of Brittain Model B-4AF Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1542WE	Installation of Brittain Model B-4AF Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1559WE	Installation of Brittain Industries Model B-5P flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1587WE	Installation of Brittain Model B-5P Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1677WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95 Series; T.C. 3A16	SA1833WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, B95A, D95A and E95; T.C. 3A16	SA153SO	Installation of turbosupercharged Lycoming O-360-A1A, IO-360-B1A or IO-360-B1B engines. Amended 2/28/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
95, B95, B95A, D95A, 95-55, 95-A55, 95-B55; T.C. 3A16	SA263CE	Supplemental Model A high intensity wing tip lights, Model C tail light, with or without Model 2 high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
95, B95, B95A, D95A, 95-55, -A55, -B55, -C55, -D55, -56; T.C. 3A16	SA378CE	Installation of Hoskins Supp. Model A high intensity wing tip lights, Model D or K tail lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
95, B95, B95A, 95-A55, -55, D95A; T.C. 3A16	SA571WE	Installation of HRD-type engine fire extinguishing system. Reissued 10/18/72.	WE	43190	HTL Industries, Inc. Advanced Technology Division Monrovia Instrument Department 1900 Walker Avenue Monrovia, CA 91016
95, B95, B95A, 95-55, 95-A55, 95-B55, 95-B55B (T-42A), 95-C55; T.C. 3A16	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-3 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
95, B95, 95-55, 95-A55, B95A, D95A, E95, 95-B55, -B55A, -B55B, -C55, D55, 95-C55A, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA901SO	Installation of single-piece sloped windshield. Amended 11/21/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. c/o F.K. Leddick & Associates, Inc. 175 W. Wieuca Rd., Suite 120 Atlanta, GA 30342
95, B95, B95A, D95A, E95; T.C. 3A16	SA1409SW	Mitchell automatic flight system AF366, cons. of Century I autopilot with optional omni tracker. Issued 12/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NC.	DESCRIPTION	RG	STC CODE	STC HOLDER
95, B95, B95A, D95A; T.C. 3A16	SA1760WE	Installation of Brittain Industries Model B-5 or NAV-2 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95, B95, 95-55, -A55, B95A, D95A, E95, -B55, -B55A, -B55B, -C55, D55, -C55A, D55A, E55, E55A; T.C. 3A16	SA2977WE	Installation of oxygen system. Amended 10/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
95, B95, D95A, E95; T.C. 3A16	SA3090SW-D	Automatic flight system AK562, cons. of Century IIB autopilot. Issued 12/15/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95, B95, B95A, D95, E95; T.C. 5A3	SA3179SW-D	Automatic flight system AK650 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 1/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D95, E95; T.C. 5A3	SA3187SW-D	Mitchell automatic flight system AK366 consisting of Century I autopilot with optional omni tracking system. Issued 2/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95, B95, B95A, D59A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA3680WE	Installation of centerline external air skeg. Amended 4/2/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90065
95, B95, B95A, E95, 95-55, -A55, -B55, -B55A, -B55B, -E55, 56TC, 58. 58A; T.C. 3A16	SA4184WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
95-55; T.C. 3A16	SA1820WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, -A55, -B55, -C55, -D55; T.C. 3A16	SA9CE	Installation of M4B or M4C flight control system. Amended 6/1/70.	SO	15475	Bendix Corporation Avionics Division 2100 N.W. 62nd Street P.O. Box 9414 Fort Lauderdale, FL 33310
95-55, -A55, -B55; T.C. A23CE	SA71GL	Install P/N BA7610 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities, Inc. 9600 West 52nd Street Kenosha, WI 53140
95-55, -A55, -B55; T.C. 3A16	SA126CE	Install Hartzell Model HC-A3XF-2B/7636D or HC-A3VF-2B/V7636D or HC-A3VF-2B/V7636N or PHC-A3XF-2B/7636D or PHC-A3VF-2B/V7636D or PHC-A3VF-2B/ V7636N propellers with Woodward Model 210355 or 210438 governors. Reissued 2/26/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-55, 95-A55; T.C. 3A16	SA136RM	Removal of existing nose cone, Beech P/N 95-410011-3 and replacement with later model nose cone, Beech P/N 95-410021-605. Issued 3/28/78.	RM	73948	Spanish Fork Flying Service, Inc. Box 48 Spanish Fork, UT 84660
95-55, -A55; T.C. 3A16	SA387GL	Installation of Norton radome kit No. 4150X-100 and -200. Issued 2/8/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-55, A55; T.C. 3A16	SA447SW	Nose modification.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA448SW	Rear baggage compartment.	SW	77110	Swearingen Aviation Corporation Box 32486 San Antonio, TX 78216
95-55, A55; T.C. 3A16	SA540EA	Installation of radome kits No. 3063X-R-100 and -200. Reissued 3/12/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95-55, 95-A55, -B55, -B55A, -B55B; T.C. 3A16	SA795CE	Install propeller Models BHC-C2YF-2CH/C8465-6 or BHC-2CHF/FC8465-6, DHC-C2YF-2CH/C8465-6 or DHC-C2YF-2CHF/FC8465-6 with spinner C-2285-1; or PHC-C3YF-2/FC7663-2R with spinner C-3567-1. Amended 8/30/73.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-55, -A55, -B55, -C55, D55; T.C. 3A16	SA886EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-011401. Issued 10/27/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
95-55, -A55, -B55, -B55A, B55B, C55, C55A, D55, D55A, E55, E55A, 58, 58A; 56TC, A56TC; T.C. 3A16	SA991EA	Installation of "Tel-Tail" logo lights. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA1014SO	Installation of Symbolic Displays Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/30/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
95-55, 95-A55, -B55, -C55, -D55, E55, E55A, 58; T.C. 3A16	SA1134CE	Installation of King Model KFC-200 2-axis (3 optional), flight control system. Amended 6/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-55, A55, B55, B55B, C55, D55, E55; T.C. 3A16	SA1173SW	Mitchell automatic flight system AK292 cons. of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers. Issued 7/14/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1299SW	Mitchell automatic flight system Model 282-292 cons. of flight director/autopilot with optional automatic pitch trim. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, -D55, -D55A, E55, E55A; T.C. 3A16	SA1300SW	Mitchell automatic flight system AK330, cons. of Century I autopilot with optional omni tracker. Issued 4/23/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA1472CE	Installation of elevator tail cone fairing. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-55, -A55, -B55, -C55, D55, D55A, E55, E55A, 56TC, A56TC; T.C. 3A16	SA1565SW	Mitchell automatic flight system AK408 cons. of Century II autopilot with optional radio coupler. Issued 12/12/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A16	SA1743SW	Mitchell automatic flight system AK401 cons. of Century IIB autopilot with optional radio coupler. Issued 10/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA1777SW	Mitchell automatic flight system AK450 cons. of Century III autopilot with optional command/electric trim radio coupler, and glide slope coupler. Issued 12/26/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A; T.C. 3A16	SA1808SW	Installation of automatic flight system AK446 Century IV autopilot and AK446FD Century IV flight director autopilot with electronic/command, and pitch trim. Issued 2/15/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, E95, A-55, B55, C55, B95A, D95A; T.C. 3A16	SA1958WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-55, 95-A55, -B55, -C55, D55, E55, 58; T.C. 3A16	SA2543WE	Installation of SDI/Hoskins Model 700801 anticollision light. Amended 12/19/72.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
95-55, 95-B55A; T.C. 3A16	SA2882WE	Installation of McCAuley 3AF32C75/82NB-6 full-feathering constant speed propellers and D3499 or D3605 spinner assemblies. Issued 5/13/74.	WE	17154	Dennis A. Praegitzer Bridgeford Flying and Propeller Service P.O. Box 6277 Stockton, CA 95206

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95-55, A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3108SW-D	Mitchell AK446 or AK446FD cons. of Century IV flight director autopilot with optional remote annuciator. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, B55, -B55A, -C55, -C55A, D55, D55A, E55, E55A; T.C. 3A16	SA3109SW-D	Mitchell AK450 cons. of Century III autopilot with optional command automatic electronic pitch trim system, radio and glide slope coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3295SW-D	Yaw damper system YK428. Issued 6/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-55, -A55, -B55, -B55B, -C55, D55, D55A, E55, E55A; T.C. 3A13	SA3333SW-D	Mitchell automatic flight system AK401 consisting of Century IIB autopilot with optional radio couplers. Issued 2/20/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-55, -A55, B55, B55A, D55A, E55, E55A; T.C. 3A16	SA3354SW-D	Mitchell yaw damper system YK843. Issued 3/17/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 66067
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3918WE	Installation of Silver Instruments Fueltron III digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-55, -A55, -B55, -C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA3919WE	Installation of Silver Instruments Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 4/27/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
95-55, -A55, -B55, -B55A, -B55B, -C55, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A; T.C. 3A16	SA4208WE	Installation of DTL-1000, -1001, and/or -1002/3 autopilot adapters for the Edo-Aire Mitchell Century III autopilot. Issued 8/13/80.	WE	47775	Douglas L. Kettler 1212 North Broadway, Apt. H Escondido, CA 92026
95-A55; T.C. 3A16	SA2690WE	Installation of manual pitch trim system and Lean P/N 800880 autopilot. Issued 6/19/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510
95-A55, 95-B55, 95-C55; T.C. 3A16	SA1392WE	Modification of fuselage structure and control system to accommodate a camera installation between Stations 131 and 151.	WE	25971	Continental Airservice, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
95-A55, -B55, -C55, -D55, E55/E55A, 58; T.C. 3A16	SA1523CE-D	Installation of King KAS 297 altitude selector option. Amended 2/13/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
95-A55, -B55; T.C. 3A16	SA2964WE	Installation of Collins AP 107/ FD 112C autopilot/flight director system. Reissued 1/14/75.	CE	24250	Collins Radio Group 5220 "C" Avenue, N.E. Station 120-120 Cedar Rapids, IA 52406
95-B55; T.C. 3A16	SA3179WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 7/27/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
95-B55; T.C. 3A16	SA3353SW	Installation of Mitchell automatic flight system AK841/FD consisting of Century 41/flight director autopilot. Issued 1/29/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
95-B55, -C55, D55, E55, 56TC, 58; T.C. 3A16	SA15GL	Installation of radome kit No. 3064X. Amended 9/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operation P.O. Box 350 Akron, OH 44309
95-B55, 95-C55, 56TC, D55, E55, 58; T.C. 3A16	SA40GL	Installation of Norton Company radome kit No. 3064X-R-500 for 10" RCA AVQ 45, 46, 47, and the 12" King KWX-40 radar antennas. Amended 4/11/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
95-B55, -B55A, E55, E55A, 58, 58A; T.C. 3A16	SA64GL	Installation of Norton radome kit P/N 4083X. Amended 2/3/81.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
95-B55, -B55A, -C55, -C55A; T.C. 3A16	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
95-B55, -C55, 56TC, D55, E55, 58; T.C. 3A16	SA482EA	Installation of Radome Kit No. 3064X-R-500 for 10-inch RCA AVQ-45, AVQ-46, and AVQ-47 radar antenna. Amended 6/19/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Cperations P.O. Box 1187 Akron, OH 44309
95-B55 & 95-B55A, T.C. 502 and up; 95-C55 & 95-C55A, TE-1 thru TE-451; 95-D55 & 95-D55A, TE-452 thru TE-767; 95-E55 & 95-E55A, TE768 and on; T.C. 3A16	SA799CE	Installation of Airborne/Goodyear iceguard. Issued April 1972.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
95-B55, -B55A, E55, E55A, 58, 58A; T.C. 3A16	SA1471CE	Installation of flap and aileron seals. Issued 2/5/79.	CE	73220	Smith Speed Conversions, Inc. Stanton County Airport P.O. Box 601 Johnson, KS 67855
95-B55, 95-C55, 95-B55A, 95-C55A; T.C. 3A16	SA2031WE	Installation of Brittain Industries B-VII, NAV-2B, or B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
95-B55, -B55A, E55, E55A; T.C. 3A16	SA3364SW	Mitchell automatic flight system AK842 consisting of Century 21 autopilot. Issued 6/6/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-B55, -B55A, -E55, -E55A; T.C. 3A16	SA3378SW-D	Mitchell automatic flight system AK841 consisting of Century 41 autopilot or AK841FD consisting of Century 41 flight director autopilot. Issued 5/15/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
95-B55, -B55A, -C55, -C55A, D55, D55A; T.C. 3A16	SA3657WE	Installation of a vapor cycle air conditioning system. Issued 6/28/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
95-C55, -C55A, D55, D55A, E55, E55A, 58, 58A; T.C. 3A16	SA773CE	Installation of Hartzell BHC-C2Y, BHC-J2Y, PHC-C3Y or PHC-J3Y propellers in accordance with Hartzell Manual 115G. Amended 2/1/80.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1054CE	Installation of AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1055CE	Installation of AP-107 3-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, C55A, D55, E55, E55A; T.C. 3A16	SA1056CE	Installation of AP-107, 2-axis autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
95-C55, D55, E55, 56TC, A56TC, 58; T.C. 3A16	SA1345CE	Chrome plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
95-C55; T.C. 3A16	SA1713WE	Removal of emergency exit to permit aircraft to engage in special purpose operations such as aerial photography, etc.	WE	69243	Ryan Aeronautical Company 2701 Harbor Drive San Diego, CA 92112
95-C55, -C55A, D55, D55A, E55, E55A, 58 58A; T.C. 3A16	SA3840WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
B95; T.C. 3A16	SA1-463	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
B95; T.C. 3A16	SA3400WE	Installation of Pathfinder autopilot systems. Issued 7/5/77.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
B95A, D95A, E95; T.C. 3A16	SA1672SW	Mitchell automatic flight system AK425, cons. of Century III autopilot with optional command automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/7/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
99; T.C. A14CE	SA298GL	Reduce number of passenger seats from 15 to 9. Issued 3/22/79.	GL	27760	Custom Air Service Willow Run Airport Ypsilanti, MI 48197
99; T.C. A14CE	SA366GL	Installation of microwave landing system airborne equipment. Issued 10/12/79.	GL	58150	Mesaba Aviation 2002 Airport Road Grand Rapids, MN 55744
99; T.C. A14CE	SA4030SW	Pratt & Whitney PT6A-27/28 engines. Issued 8/30/79.	SW	69214	Royale Turbines, Inc. Shreveport Regional Airport Shreveport, LA 71109
99, 99A; T.C. A14CE	SA717CE	Installation of M4C autopilot.	CE	15477	Bendix Avionics 3303 East Harry Street Wichita, KS 67218
99, 99A, 99A (FACH), A99, A99A, B99; T.C. A14CE	SA114GL	Installation of Norton Radome Kit 3097X. Issued 5/20/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
99, 99A, A99, A99A, B99; T.C. A14CE	SA143GL	Modification of existing B.F. Goodrich propeller de-icing system. Issued 11/23/76.	GL	38500	B.F. Goodrich Engineered Systems Company Div. of B.F. Goodrich Company Akron, OH 44318
99, 99A, 100, A100; T.C. A14CE	SA811CE	Battery temperature sensing and over-temperature warning systems. Issued February 1972.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
99, A99, 99A, A99A, 100, A100, A100A T.C. A14CE	SA894SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	SO	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
99, 99A, 99A (FACH), A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1178CE	Install wing front spar reinforcement kit. Reissued 5/9/80.	WE	13177	Aviadesign, Inc. Suite 101, Bank of A., Levy Bldg. 5808 E. Telephone Road Ventura, CA 93003
99, 99A, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1280CE	Install Avcon Ind. TSO-C39a stretcher with a P/N 4001-103 or 4001-104 installed. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N Wichita, KS 67204
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1453CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
99, 99A, A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA1454CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Reserach Corporation P.O. Box 222 Buffalo, NY 14225
99, A99, 100, A100, B100; T.C. A14CE	SA1631CE	Installation of portable airway checking equipment rack on existing seat rails. Issued 1/21/81.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
99, 99A, A99, A99A, B99, 100, A100; T.C. A14CE	SA2908WE	Installation of fuel tank boost pump. Issued 7/23/74.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
99, 99A, 99A (FACH), A99, A99A, B99, 100, A100, A100A, A100C, B100; T.C. A14CE	SA3106WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
99, 99A, A99, A99A, B99; T.C. A14CE	SA4013WE	Installation of a hydraulic landing gear retraction system. Issued 9/19/79.	WE	13177	Aviadesign, Inc. Suite 101, Bank of America Levy Building 5808 East Telephone Road Ventura, CA 93003
99A; T.C. A14CE	SA981EA	Installation of modified cargo door, airstair door, jump door in cargo door and external parachute's step. Amended 10/4/74.	EA	23450	C N C Industries, Inc. Hyde Field, Route 223 Clinton, MD 20735

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
100, A100; T.C. A14CE	SA1197CE	Install Teledyne/Gill lead-acid battery, BB638T with venting and neutralizer, in lieu of nickel-cadmium. Issued February 1976.	CE	65300	Teledyne Battery Products c/o Product Development Group, Inc. P.O. Box 177 Rose Hills, KS 67133
100, A100; T.C. A14CE	SA1573SW	Foxtronics/TRAMM BT1 600 nickel cadmium battery temperature system. Issued 12/19/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
A100; T.C. A14CE	SA256GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
A100; T.C. A14CE	SA476SO	Installation of M4C autopilot in accordance with Bendix drawing list AE-163, Rev. A. Issued 10/14/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
A100; T.C. A14CE	SA1058SO	Replace existing nickel-cadmium batteries with Teledyne Gill B6381T batteries. Issued 3/29/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
B100; T.C. A14CE	SA1018SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
B100, S/N's BE-21 and up; T.C. A14CE	SA3981WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200; T.C. A24CE	SA381GL	Installation of a single Canadian Marconi CMA-734 Omega/VLF navigation system. Issued 1/4/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
200; T.C. A24CE	SA1016SO	Replace existing nickel-cadmium battery with Gill Teledyne BB638/T series lead-acid battery. Issued 8/3/78.	SO	78054	Teledyne Battery Products 6520 POwers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
200; T.C. A24CE	SA1174SO	Installation of J.E.T. DAC 2000 3-D area navigation system. Issued 9/30/80.	SO	75114	Stevens Beechcraft, Inc. P.O. Box 589 Greer, SC 29651
200; T.C. A24CE	SA1189CE	Installation of Safe Flight speed command or speed command and auto-throttle (SCAT) system. Amended 6/8/77	EA	69500	Safe Flight Instrument Corp. (SFIC) P.O. Box 550 White Plains, NY 10602
200; T.C. A24CE	SA3339WE	Installation of Hydro-Aire power brake/skid control system. Issued 5/17/77.	WE	26725	Hydro-Aire Division Crane Company, Inc. P.O. Box 7722 Burbank, CA 91510
200; T.C. A24CE	SA3982WE	Installation of SDI Model CFS-2002 fuel flow indicating system. Issued 6/20/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
200, A200; T.C. A24CE	SA1278CE	Installation of Avcon Industries TSC-C39a stretchers. Issued February 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
200, A200, 200T; T.C. A24CE	SA192GL	Installation of Norton radome kit No. 2090XS Amended 8/24/78.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operation P.O. Box 350 Akron, OH 44309
200, A200, 200T; T.C. A24CE	SA1449CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
200, A200, 200T; T.C. A24CE	SA1450CE	Installation of Sierra electronic console. Reissued 10/16/78.	EA	71660	Sierra Research Corporation P.O. Box 222 Buffalo, NY 14225
200, A200, 200T; T.C. A24CE	SA1591CE	Installation of utility flight inspection equipment mounting rack. Issued 5/30/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
200, A200, 200T; T.C. A24CE	SA1632CE	Installation of portable airway checking equipment rack on existing seat rails. Issued 1/21/81.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
200, 200C, 200CT, 200T, A200, A200C, A200CT; T.C. A24CE	SA1602CE	Installation of wing front spar reinforcement kit. Issued 10/1/80.	CE	13177	Aviadesign, Inc. Suite 311 5755 Valentine Road Ventura, CA 93003

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
47B, B3, D, D1, E, G, G-2, H-1; 47G-2A, -2A-1, -3, -3B, -3B-1, -3B-27, -4, -4A, -5, -5A; 47J, K, J-2, J-2A; 206A, 206B; T.C. H-1, 2H3, 2H1, H2SW	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A450, A408W or A470W (white), A408R/W or A470 R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417
47B, B3, D, D1, E, G, G-2, H-1, G-2A, -2A-1, G3, -3B, -3B-1, -2, G-4, G-5, -5A, B-3B, -2A, G-4A-5; T.C. H-1, 2H3	SW2840SW	Chemical spray boom. Reissued 4/19/79.	SW	84614	Warnell Company Box 588 Atlanta, TX 75551
47D-1; T.C. H-1	SH13WE	Conversion of Bell Model 47D-1 to (1) Model 47G-2. Reissued 1/18/74.	SW	52800	Gifton McCreary 1921 W. 5th Street, Apt. #180 Irving, TX 75060
47D-1; T.C. H-1	SH283SW	Battery relocated and ballast installed. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D-1; T.C. H-1	SH397SW	Hydraulic boost kit. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D-1; T.C. H-1	SH529SW	Franklin 6V-350-A engine. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1; T.C. H1	SA2666WE	Ceconite 102 material covering of vertical fin. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
47D-1, 47G; T.C. H-1	SH213WE	Installation of exhaust muffler assembly. Issued 3/8/78.	WE	00100	A & H Welding Company 11230 Ilex Avenue Pacoima, CA 91331
47D1, 47G; T.C. H-1	SH752SW	Centerframe and Lycoming VO-435 engine.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G; T.C. H-1	SH888SW	Use of spacer in lieu of snap ring on tail rotor drive. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G-2; T.C. H-1	SH1007SW	Modify tail rotor pitch change mechanism to add duplex bearing. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G-2, G-2A, G-2A-1, G-3, OH-13H, 47G-3B, G-3B-1, G-3B-2, G-3B-2A, G-4, G-4A, G-5, G-5A; T.C. H1, H5SW, 2H3	SH2772SW	Revise mast controls and remove stabilizer bar and install control system. Reissued 10/27/80.	SW	52800	Gifton McCreary 1336 South Irving Heights Drive Irving, TX 75060
47D1, 47G-2; T.C. H-1	SH588SW	Conversion to single-place cabin without doors and revised controls. Reissued 11/27/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G-2, 47G-3, 47G-4; T.C. H-1, 2H3	SH611SW	Left and right door with tinted sliding windows. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47G, 47G2, G2A, G2A-1, G-3, -3B, -1, -4, -4A, -5, -3B-2; T.C. H-1, 2H3	SH972SW	Copilot's rudder pedals. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47D1, 47E, 47G-2, -2A, -2A-1, 47G-3, -3B, -3B-1, -3B-2, 47G-4, -4A, 47G-5, 47J, 47J-2, -2A, 47K; T.C. H-1, 2H3, 2H1	SH102WE	Installation of automatic flagman model 5. Issued 2/17/71.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362
47G Series; T.C. H-1, 2H3, 2H1	SH5CE	Install 32 foot agricultural spray boom assembly. Issued 1/31/78.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G; T.C. 2H3	SH78WE	Installation of Calicopters Cabin Heater Kit CC 1000.	WE	19440	Calicopters, Inc. 1595 Lindbergh Street Stockton, CA 95206
47G; T.C. H-1	SH610EA	Following modifications are compatible with each other and may be incorporated simultaneously: STCs SA479SW, SH21EA, SH163EA.	EA	19950	Carson Helicopters, Inc. R.R. 1, Box 94 Perkasie, PA 18944

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
47G Series; T.C. 2H3	SH657NW	Installation of Allison 250 series engines. Issued 9/7/78.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
47G Series; T.C. 2H3	SH787NW	Installation of model 5700 spray system. Issued 7/9/79.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G Series; T.C 2H3	SH856NW	Installation of Simplex Model 4800 spray system. Amended 11/28/80.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G Series; T.C 2H3	SH888NW	Installation of a Simplex Model 5750 spray system. Issued 2/21/80.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G Seires; T.C. 2H3	SH889NW	Installation of a Simplex Model 4850 spray system. Issued 2/21/80.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G Series; T.C. 2H3	SH890NW	Installation of a Simplex Model 4700 spray system. Issued 2/21/80.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G Series; T.C. 2H3	SH891NW	Installation of a Simplex Model 5600 spray system. Issued 2/21/80.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47 Series (as modified by STC SH657NW); T.C. H-1, 2H3	SH828NW	Installation of weighing system. Issued 9/6/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
47G, 47G-2; T.C. H-1	SH165GL	Installation of low fuel warning system. Issued 4/27/77.	GL	49320	Lake Line Helicopters, Inc. 13601 Pioneer Trail Eden Prairie, MN 55343
47G, 47G2; T.C. H-1	SH191WE	Installation of Jasco alternator, P/N 7555-1, 24 volt system. Amended 4/19/79.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
47G-2; T.C. H-1	SA151GL	Installation of Lycoming VO-435-A1F engine modified in accordance with STC SE144GL. Amended 7/5/77.	GL	49320	Lake Line Helicopters, Inc. 13601 Pioneer Trail Eden Prairie, MN 55343
47G-2; T.C. H-1	SH159WE	Installation of a muffler. Amended 11/8/73.	WE	49850	LearAvia Corporation Avionics Division P.O. Box 10600 14505 Mt. Anderson Avenue Reno, NV 89510
47G-2; T.C. H-1	SA266CE	Installation of crane bar. Reissued 1/29/75.	EA	69232	G. Loren Ruhl 724 Thirteenth Avenue, Apt. #3 Huntington, WV 25701
47G-2, 47G-2A, -2A-1, 47G-3B, -3B-1, -3B-2, 47G-4, -4A, 47G-5; T.C. 2H3	SH141WE	Installation of aerial seeder. Amended 5/2/72.	NW	71770	Simplex Manufacturing Company 5224 NE. 42 Avenue Portland, OR 97218
47G-2, 47G-2A, 47G-2A-1, 47G-3B, 47G-1, 47G-3B-2, 47G-4, 47G-4A, 47G-5; T.C. 2H3	SH143WE	Installation of a 12 volt, 40 ampere alternator on auxiliary power take-off pad. Issued 5/9/72.	WE	03270	U.S. Department of Agriculture Forest Service 444 East Bonita Avenue San Dimas, CA 91773
47G-2, -2A, -2A1, -3, -3B, -3B1, -2, -4, -4A; T.C. H-1, 2H3	SH381AL	Installation of cargo baskets. Issued 8/18/70.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
47G-2, G-2A, G-2A-1, G-5; 47G-3, G-3B, G-3B-1, G-4, G-4A; 47J, J-2, J-2A, X; T.C. H-1, 2H3, 2H1	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Division of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
47G-2, 47G-2A-1; T.C. 2H3	SH960EA	Incorporation of AVCO Lycoming Model VO-435-A1F or VO-435-A1F engine modified in accordance with STC SE959EA. Amended and reissued 3/11/76.	EA	03300	AGROTORS, Inc. Box 578 Gettysburg, PA 17325
47G-2, -2A, -2A-1, 47G-3B, -3B-1, -3B-2, 47G-4, -4A, OH-13H/Mark 5A, 6C; T.C. H-1, 2H3, H5SW	SE2348SW	Redesigned spray system. Reissued 10/27/80.	SW	52800	Gifton McCreary 1336 S. Irving Heights Drive Irving, TX 75060
47G-2, -2A, -2A1, 2H3, Texas Helicopter M74/OH, 13E; T.C. H-1, 2H3, H7SW	SH2397SW	Install Ag-King 500B spray system with two tanks (800 lbs. total allowable) 32 feet boom on end of skid tubes and engine driven pump. Issued 1/27/77.	SW	03240	Ag-King Manufacturing P.O. Box 815 Paragould, AR 72450

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
47G-2, 47G-5, 47G-5A,, -2A, -2A1; T.C. 2H3	SH161WE	Installation of exhaust muffler assembly. Amended 10/16/75.	WE	00100	A & H Welding Company 9317 Borden Avenue Sun Valley, CA 91352
47G-2A, -2A-1, 47G-3, -3B, -3B-1, 47G-4; T.C. 2H3	SH54WE	Installation of modified hydraulic boost cylinder. Reissued 7/31/80.	WE	62465	Parker Bertea Services Helicopter Division 1320 Flower Street Glendale, CA 91201
47G-2A, -2A-1, 47G-3, -3B-1, 47G-4; T.C. 2H3	SH68WE	Installation of modified hydraulic boost cylinder. Reissued 7/31/80.	WE	62465	Parker Bertea Services Helicopter Division 1320 Flower Street Glendale, CA 91201
47G-2A, -2A-1, G-3, G-3B, G-3B-1, G-3B-2, G-3B-2A, G-4, G-4A, G-5, G-5A; T.C. 2H3	SH166GL	Installation of low fuel warning system. Issued 4/27/77.	GL	49320	Lake Line Helicopters, Inc. 13601 Pioneer Trail Eden Prairie, MN 55343
47G-2A, 47G-2A1, 47G-5, 47G-5A; T.C. 2H3	SH170WE	Installation of exhaust muffler assembly. Issued 9/13/74.	WE	49850	LearAvia Corporation P.O. Box 10825 Reno, NV 89510
47G-2A, -2A-1, -3B, -3B-1, -3B-2, -3B-2A, -5, -5A, -4, -4A; T.C. 2H3	SH175WE	Removal of generator and installation of Ford-GPD alternator. Issued 1/8/75.	WE	78620	TORQAID 3190 Cherry Avenue Long Beach, CA 90807
47G-2A, -2A-1, 47G-3, -3B, -3B-1, -3B-2, -3B-2A, 47G-4, -4A, 47G-5, -5A; T.C. 2H3	SH193WE	Installation of Jasco alternator P/N 7555-1 volt system. Amended 7/3/79.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
47G-2A, -2A-1, -3-B, -3-B-1, -3-B-2, G-4; T.C. 2H3	SA357SW	Installation of Simplex spray kit. Amended 5/18/77.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
47G-2A, -2A-1, 47G-3, -3B, -3B-1, -3B-2, 47G-4, -4A, 47G-5; T.C. 2H3	SH370GL	Installation of Ni-Cad model No. 82164 engine lubrication system scavenge filter. Issued 11/2/79.	GL	61546	Ni-Cad, Inc. 24800 U.S. 20 South Bend, IN 46628
47G3, 47G-3B, 47G-3B-1, 47G-2A, 47G-4A, 47G-5; T.C. 2H3	SH88WE	Installation of cargo hook. Amended 5/10/71.	WE	63350	Thomas A. Patterson Helicopter Mechanics Service 7621 Tobias Avenue Van Nuys, CA 91405
47G-3B; T.C. 2H3	SH157GL	Installation of Lycoming VO-435-A1F engine. Issued 4/22/77.	GL	03280	Agri Helicopter, Inc. 840 Havana Road Owatonna, MN 55060
47G-3B; T.C. 2H3	SH173WE	Installation of derated Lycoming TVO-435-B1A or TVO-435-B1B engine in lieu of TVC-435-A1A engine using existing TVO-435-A1A installation components. Issued 11/11/74.	WE	85144	Western Helicopters, Inc. P.O. Box 579 1670 Airport Way Rialto, CA 92376
47G-3B; T.C. 2H3	SH404GL	Installation of Lycoming VO-435-A1 engine. Issued 5/9/80.	GL	03280	Agri Helicopter, Inc. Route #1, Box 7G Ouatonna, MN 55060
47G-3B; T.C. 2H3	SH986EA	Installation of Avco Lycoming engine Model TVC-435-B1A (O-435-25A) in lieu of model TVO-4350A1A. Issued 8/16/74.	EA	61188	Nassau County Police Department Air Bureau 1490 Franklin Avenue Mineola, NY 11501
47G-3B; T.C. 2H3	SH227GL	Installation of Lycoming VO-435-A1F engine. Issued 3/6/78.	GL	03280	Agri Helicopter, Inc. 840 Havana Road Owatonna, MN 55060
47G-3B, 47G-3B-1; T.C. 2H3	SH504GL	Installation of Lycoming VO-435-A1F engine modified in accordance with STC SE144GL and associated changes. Issued 2/18/81.	GL	78613	Tom-Cat Helicopters, Inc. Route 1, Box 7G Owatonna, MN 55060
47G-3B-1; T.C. 2H3	SH86WE	Installation of cargo racks.	RM	65331	Provo Flying Service, Inc. P.O. Box 691 Provo, UT 84601
47G-3B-1; T.C. 2H3	SH93WE	Installation of supplemental exterior flashing lights.	RM	29250	Delta Products, Inc. P.O. Box 1147 Grand Junction, CC 81501
47G-3B-1; T.C. 2H3	SH226GL	Installation of Lycoming VO-435-A1F engine. Issued 3/6/78.	GL	03280	Agri Helicopter, Inc. 840 Havana Road Owatonna, MN 55060

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
47G-3B-1, 47G-3B-2, 47G-4, 47G-4A, 47G-5; T.C. 2H3	SH100WE	Installation of fiberglass baggage carriers.	WE	79300	Transland Aircraft, Inc. 24511 Frampton Avenue Harbor City, CA 90710
47G-3B-2A, 47G-5A; T.C. 2H3	SH153WE	Installation of Transland Model 54170 agricultural spray system. Reissued 10/31/74.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
47G-4, 47G-4A; T.C. 2H3	SH162WE	Installation of exhaust muffler assembly. Issued 3/8/74.	WE	00100	A & H Welding Company 9317 Borden Avenue Sun Valley, CA 91352
47G-5; T.C. 2H3	SH15CE	Install Stewart Warner Model 940F combustion heater. Issued June 1972.	CE	33580	EPM Corporation P.O. Box 5978, Lambert Field St. Louis, MO 63134
47G-5; T.C. 2H3	SH204WE	Installation of AC-OF-104A oil filter at longtudinal station (-14.0). Amended 10/3/79.	WE	90115	Yuma Helicopters, Inc. P.O. Box 4935 Yuma, AZ 85364
47G-5 (Normal Category); T.C. 2H3	SH254WE	Installation of Gill Model PS-6-11 battery, together with an external power source. Issued 9/28/79.	WE	90115	Yuma Heliocpters, Inc. P.O. Box 4935 Yuma, AZ 85364
47H-1; T.C. TCH-1	SH909SW	Franklin 6V-350-A engine. Reissued 11/22/74.	SW	52800	Gifton McCreary Route 1, Box 59A Roanoke, TX 76262
47J; T.C. 2H1	SH375AL	Installation of Airglas model L2700-47J skis. Issued 5/26/70.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
47J; T.C. 2H1	SH1422CE	Installation of engine exhaust muffler. Issued 6/12/78.	CE	36510	Fostaire Helicopters 400 North Wharf Street St. Louis, MO 63102
47J, 47J2, 47J2A, 47K; T.C. 2H1	SH194WE	Installation of Jasco alternator P/N 7555-1 24-volt system. Amended 7/3/79.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
47J, 47J2, 47J2A, 47K; T.C. 2H1	SH199WE	Installation of stirrup assemblies to directional control pedals for operation by handicapped pilot. Issued 4/14/77.	WE	28620	Barry C. Dallwig 113 East Elfin Green Port Hueneme, CA 93041
47J-2, -2A; 47G-3B, 3B-1, 3B-2; T.C. 2H1, 2H3	SH12CE	Replace existing engine induction air filter with AC Spark Plug Filter - Type AAF-103.	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
204, 205, 212; T.C. H1SW, H4SW	SH611NW	Installation of onboard weighing system. Issued 6/16/78.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
204B; T.C. H1SW	SH984SO	Installation of Lycoming T5313A or B engines, replacing Lycoming T5311A engines, including minor installation changes. Issued 5/10/78.	SO	86080	Wilco Aviation bBlackwell Airport P.O. Box 506 Ozark, AL 36360
204B, 205A, 205A-1; T.C. H1SW	SH149WE	Installation of Chadwick electronic weighing system C47. Issued 6/1/72.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
204B, 205A, 205A-1; T.C. H1SW	SH172WE	Installation of A500 battery temperature monitor systems. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
204B, 205A, 205A-1; 206A, 206B, 206B-1, 206L, 212; T.C. H1SW, H2SW, H4SW	SH155WE	Installation of battery temperature monitor system. Amended 6/22/78.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
204B, UH1-B; T.C. H1SW	SH183AL	Installation of Airglas L7000 or L8500B skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
204B, 205A, 205A-1, 212; T.C. H1SW, H4SW	SH733NW	Installation of onboard weighing system. Issued 3/21/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
204B, 205A-1; T.C. H1SW	SH1201SO	Installation of a wire strike protection system. Issued 2/2/81.	SO	17300	Bristol Aerospace, Ltd. P.O. Box 1177, Tri-City Airport Blountville, TN 37617
205A, 205A-1; T.C. H1SW	SH198AL	Installation of Airglas L8500 or L8500A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
205A, 205A-1; T.C. H1SW	SH255WE	Installation of emergency exit window. Reissued 1/11/80.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
205A, 205A-1; T.C. H1SW	SH462NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
205A, 205A-1; T.C. H1SW	SH1022SW	Interior arrangement for 7 passenger seats and 1 jump seat. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
205A, 205A-1; T.C. H1SW	SH1789SW	Foxtronics/Tramm BTI 600 nickel cadmium battery temperature system. Issued 1/29/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
205A, -1, 212; T.C. H1SW, H4SW	SH1700SW	Hard surface skid shoes. Issued 6/6/73.	SW	61650	Northrop Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
205A-1; T.C. H1SW	SH140GL	Installation of dual band (K/X) type weather radome. Issued 10/27/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
206; T.C. H2SW	SH329NW	Installation of automatic flagman. Issued 10/28/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362
206 Series; T.C. H2SW	SH1091SO	Replace existing battery with an Eagle-Picher magnum 13 battery. Issued 8/22/79.	SW	18190	BSI Manufacturing, Inc. 101 Space Park South Drive Nashville, TN 37211
206; T.C. H2SW	SH1137SO	Install Utah Research and Development Co. model 124BC101 battery charging system. Issued 3/11/80.	SO	18190	BSI Manufacturing, Inc. 101A Space Park South Drive Nashville, TN 37211
206, 206A, 206B; T.C. H2SW	SH963EA	Installation of battery temperature alert system Model Bell B206-TA180 or B206D-TA180. Amended 6/28/74.	EA	25920	Consolidated Instrument Co., Inc. Teterboro Airport Teterboro, NJ 07608
206 Series; T.C. H2SW	SA4206WE	Installation of Ametek TOT indicator, P/N SEL-019AU. Issued 8/14/80.	WE	16751	A. Biederman, Inc. 1045 Air Way Glendale, CA 91201
206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1; T.C. H2SW	SH1018EA	Installation of Casey shroud type heater. Amended 12/8/80.	EA	20112	Casey Copter Accessories, Ltd. P.O. Box 121 Montreal International Airport Dorval, Quebec, Canada H4Y 1A5
206, A, A-1, B, B-1, L, L-1; T.C. H2SW	SH2828SW	Sloping pedestal and instrument. Issued 8/4/78.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
206, A, A-1, B, B-1, L; T.C. H2SW	SH4061SW	Install ruggedized attitude gyro and related vacuum system components. Issued 11/27/79.	SW	40000	Hamilton Instruments, Inc. 106 Neuhaus Street Houston, TX 77061
206A; T.C. H2SW	SH10CE	Install Hoskins Twilighter Mk III lighting system consisting of P/N 60-0032-31 power supply and two of Model 2 P/N 30-0021-11 lights. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
206A; T.C. H2SW	SH117WE	Installation of cargo rack on one side or on both sides of skid gear. Amended 10/20/70.	WE	03270	U.S. Department of Agriculture Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
206A, 206B, 206L, 206L-1, Normal Category; T.C. H2SW	SH240WE	Installation of baggage compartment extension. Issued 7/12/79.	WE	50275	Ronald A. Leibin and Stephen H. Crowe 2761 Hollywood Way Burbank, CA 91505
206A; T.C. H2SW	SH411AL	Installation of mirror kit assembly. Issued 12/15/70.	AL	10650	Anchorage Helicopter Service, Inc. 1812 East Fifth Avenue Anchorage, AK 99501
206A; T.C. H2SW	SH635EA	Operate with one or both rear doors removed and both front doors installed on helicopters equipped with or without emergency float gear.	EA	65008	The Port of New York Authority 111 8th Avenue, Room 1601
206A; T.C. H2SW	SH837EA	Installation of Airborne television and microwave transmission system. Amended 3/24/71.	EA	30992	Dynasciences Corporation Township Line Road Blue Bell, PA 19422

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206A; T.C. H2SW	SH864EA	Installation of AACK-1R Optical Radiation Corporation Model B "Locator" search light plus relocation of landing lights. Installation of additional contact surfaces "bear paws" to standard skid gear. Issued 2/17/71.	EA	12495	Atlantic Aviation Corporation Bell Helicopter Service Center P.O. Box 2307 South Hackensack, NJ 07608
206A; T.C. H2SW	SH892EA	Installation of Grimes Manufacturing Company supplemental strobe lights. Issued 11/26/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
206A; T.C. H2SW	SH1164SW	Installation of dual battery system using the ship's original battery and one installed by Bell Service Instructions and Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
206A; T.C. H2SW	SH1675SW	Heater system for de-fog air. Issued 6/15/73.	SW	68768	Rockwell International Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
206A, A-1, 206B; T.C. H2SW	SH1534SW	Remove standard BHC short skid shoes and install full length hard surface skid shoes. Issued 11/8/72.	SW	61650	Northrop Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
206A, B; T.C. H2SW	SA116WE	Installation of Nightsun SX-16C Searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
206A, B; T.C. H2SW	SH122WE	Installation of JB Systems, Inc. airconditioning system. Amended 12/10/73.	RM	45750	JB Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501
206A, 206B; T.C. H2SW	SH124NW	Installation of Simplex 2700 and 2700A spray system tank assembly. Issued 9/9/74.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206A, 206B; T.C. H2SW	SH126WE	Installation of cartridge boost electrical starter system. Reissued 5/15/72.	WE	77492	Talley Industries, Inc. 4551 E. McKellips Road P.O. Box 849 Mesa, AZ 85201
206A, 206B; T.C. H2SW	SH138WE	Installation of Chadwick cargo rack C-72. Issued 1/6/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH139WE	Installation of Chadwick C-22 auxiliary fuel system and C-30 ferry kit. Issued 1/7/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH148WE	Installation of Chadwick electronic weighing system C-45. Issued 5/26/72.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
206A, 206B; T.C. H2SW	SH158WE	Installation of Silver Star I anticollision light. Issued 7/9/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
206A, 206B; T.C. H2SW	SH209WE	Installation of type design change covering the SFENA ministab flight control system in various model combinations. Reissued 9/7/79.	WE	71450	SFENA Corporation 385 Reed Street Santa Clara, CA 95050
206A, 206B; T.C. H2SW	SA244NW	Installation of HE-206-010 bleed air heater system. Issued 3/2/76.	EA	35777	J.E. Flippo Rural Route 1, Pritchard Lane Westbank, B.C., Canada VOH-2A9
206A, 206B normal category; T.C. H2SW	SH266WE	Installation of Carter Engineering Model CEL 450-206 searchlight. Issued 2/8/80.	WE	19986	Carter Engineering Company 232 South Glasgow Avenue Inglewood, CA 90301
206A, 206B; T.C. H2SW	SH278NW	Installation of an electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems Inter'l 619 Riverside Drive Seattle, WA 98108
206A, 206B; T.C. H2SW	SH309AL	Installation of cargo basket. Amended 7/26/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH332AL	Installation of Airglas model L2700-206A skis. Amended 3/3/73.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206A, 206B; T.C. H2SW	SH380AL	Installation of cargo baskets. Amended 8/7/73.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH474AL	Installation of Alaskan Sky-Craft Company, Inc. cargo step. Amended 7/20/73.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH515AL	Installation of ASC transporter cargo step. Amended 4/4/75.	AL	08500	Alaskan Sky-Craft Company, Inc. P.O. Box 6206 Anchorage, AK 99502
206A, 206B; T.C. H2SW	SH543NW	Installation of Bell 205 series cyclic stick grip. Issued 12/9/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH544NW	Installation of 28 volt DC power outlet in cabin. Issued 11/10/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH625NW	Installation of collective torque tube actuated hour meter switch and an engine-out audible warning system. Issued 6/28/78.	NW	85330	Weyerhaueser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH690NW	Installation of cyclic operated counter system. Issued 11/27/78.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH702NW	Installation of weighing system. Issued 1/23/79.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
206A, 206B; T.C. H2SW	SH759NW	Installation of an onboard weighing system. Issued 5/3/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
206A, 206B; T.C. H2SW	SH791NW	Installation of a model 50 spray system. Issued 6/26/79.	NW	66340	Rambling Rotors, Inc. Route 2, Box 244 La Grande, OR 97850
206A, 206B; T.C. H2SW	SH848NW	Installation of a model 4900 spray system. Issued 10/22/79.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206A, 206B; T.C. H2SW	SH879NW	Installation of a 1/8" thick clear plexiglass door-length window on the right hand from cabin door. Issued 1/17/80.	NW	85330	Weyerhauser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH960NW	Installation of a D.C. "generator out" warning light. Issued 6/23/80.	NW	85330	Weyerhauser Company 1020 26th Avenue, N.W. Gig Harbor, WA 98335
206A, 206B; T.C. H2SW	SH1062SO	Installation of fuel tank filler extension (increased fuel capacity).	SO	78475	Thoroughbred Helicopter Service, Inc. Route 3, Paris Pike Lexington, KY 40511
206A, 206B, 206L; T.C. H2SW	SH1125EA	Installation of Aircraft Parts Corp. starter-generator, P/N 150SG111Q. Amended 11/27/78.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
206A, 206B; T.C. H2SW	SH1134SO	Installation of one-piece entrance step. Issued 2/19/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri City Airport Blountville, TN 37617
206A, 206B; T.C. H2SW	SH1163SO	Installation of an entrance step on high skid gear with emergency flotation system (pop-outs). Issued 7/31/80.	SO	02380	Aeronautical Accessories, Inc. P.O. Box 1177 Tri-City Airport Blountville, TN 37617
206A, 206B; T.C. H2SW	SH1214EA	Installation of Field Aviation moveable window panel(s) in aft door(s) only. Issued 12/10/80.	NW	35300	Field Aviation Company, Ltd. Toronto Inter'l Airport P.O. Box 6023 Toronto A.M.F. Ontario Canada, L5P 1B9
206A, 206B; T.C. H2SW	SH1216EA	Installation of Wesscam camera pod and associated components. Issued 12/24/80.	EA	44868	ISTEC, Ltd. 1810 Highway 6 North Hamilton, Ontario Canada, L9J 1B2
206A, 206B; T.C. H2SW	SH1753SW	Collapsible table and bar in passenger compartment. Issued 10/25/73.	SW	36550	Foster-Edward Aircraft Company 304 Fair Oaks Boulevard Euless, TX 76039

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206A, 206B; T.C. H2SW	SH1754SW	Foxtronics/Tramm BTI 600 nickel-cadmium battery temperature system (single battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1755SW	Foxtronics/Tramm BTI 600 nickel-cadmium battery temperature system (dual battery version). Issued 10/26/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
206A, 206B; T.C. H2SW	SH1759SW	Ni-Cad battery overtemperature warning system. Issued 11/6/73.	SW	22280	Chrysler Corporation Space Division P.O. Box 29200 New Orleans, LA 70189
206A, 206B; T.C. H2SW	SH2889SW	Fuel filler neck.	SW	32758	Edwards & Associates, Inc. 13611 Heartside Place Dallas, TX 75234
206A, 206B; T.C. H2SW	SH4083SW	Install wire strike protection system. Issued 2/16/80.	SW	75234	Bristol Aerospace, Limited P.O. Box 340283 Dallas, TX 75234
206A, 206B; T.C. H2SW	SH4134SW	Fuel extender. Issued 5/29/80.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
206A, 206B; T.C. H2SW	SH4135SW	Vertical sliding window, P/N 206-108. Issued 5/30/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206B-1; T.C. H2SW	SH164WE	Installation of A500 battery temperature monitor system. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
206A, B; 206L; T.C. H2SW	SA86GL	Installation of Marathon CA1700 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Co., Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48083
206A, 206B; 206L; T.C. H2SW	SH184WE	Installation of turbine over-temperature warning system. Amended 4/4/77.	WE	60425	MRSC Incorporated 10959 San Diego Mission Road San Diego, CA 92108
206A, 206B, 206L, 206L-1; T.C. H2SW	SH227WE	Installation of baggage compartment extension. Issued 11/3/78.	WE	50275	Ronald Leibin/Steve Crowe 2761 Hollywood Way Burbank, CA 91505
206A, 206B, 206L, 206L-1; T.C. H2SW	SH1147SO	Installation of baggage floor protector. Issued 5/29/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri City Airport Blountsville, TN 37617
206A, 206B, 206L, 206L-1; T.C. H2SW	SH1148SO	Installation of a rain-gutter. Issued 6/2/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri City Airport Blountsville, TN 37617
206A, 206B; 206L; T.C. H2SW	SH736SO	Installation of SAFT type 1656 nickel-cadmium electrical storage battery. Amended 11/19/76.	SO	69800	SAFT America, Inc. P.O. Box 1886 711 Industrial Boulevard Valdosta, GA 31601
206A, 206B, 206L; T.C. H2SW	SH1148EA	Installation of a modified Lear-Siegler starter-generator, P/N 23032-010. Amended 6/1/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
206A, 206B, 206L; T.C. H2SW	SH4136SW	Replacement window, P/N 206-B-104-23, -24, 206-L-104-23, -24. Issued 5/30/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206L, 206L-1; T.C. H2SW	SH200GL	Installation of NI-CAD, Inc. Model No. 62239 engine lubrication system scavenge filter. Amended 6/22/79.	GL	61546	NI-CAD, Incorporated 24800 U.S. 20 South Bend, IN 46628
206A, 206B, 206L, 206L-1; T.C. H2SW Normal Category	SH244WE	Installation of cyclic support cover, P/N 2COS6C Issued 10/9/79.	WE	50275	Stephen H. Crowe and Ronald A. Leibin 2761 Hollywood Way Burbank, CA 91505
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH247WE	Installation of Silver Instruments fueltron IG or IP digital fuel flow and totalizer system. Issued 9/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH252WE	Installation of SDI model CFS-1002, fuel flow indicating system. Issued 9/14/79	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206A thru S/N 253, 206B S/N 2059 and up, 206L, 206L-1; T.C. H2SW	SH253WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 9/17/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206A, 206B, 206L, 206L-1; T.C. H2SW	SH4146SW	Vertical slide window in crew door. Issued 6/25/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206L, 206L-1;	SH4224SW	Passenger door bubble window, P/N 206B/L106.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246
206A, 206B, 206L, 206L-1; T.C. H2SW	SH4225SW	Installation of 206-110 wedge window assembly. Issued 10/31/80.	SW	64000	Perkins Plastics, Inc. P.O. Box 4246 Fort Worth, TX 76106
206A, 206B, 206L-1; T.C. H2SW	SH198WE	Installation of tail rotor flood lights on the upper surfaces of horizontal stabilizers. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
206B; T.C. H2SW	SH5NE	Installation of revised instrument panel and installation of pressure operated gyro instrument back-up system. Issued 12/14/73.	NE	26550	Copters Unlimited, Inc. T.F. Green State Airport Warwick, RI 02886
206B (S/N 1 thru 2211); T.C. H2SW	SH134GL	Install Allison 250-C20B engine. Amended 1/12/81.	GL	14212	Aztec Aviation, Inc. Grissom Airport Bedford, IN 47421
206B; T.C. H2SW	SH174WE	Installation of Nightsun SX-16C searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
206B; T.C. H2SW	SH237WE	Installation of a "HCS-206" helicopter computer system. Issued 5/23/79.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
206B; T.C. H2SW	SH384GL	Installation of Tayburn Electronics, Inc. airborne television and microwave transmission system (electronic news gathering). Issued 1/31/80.	GL	02392	Aeronautical Systems, Inc. Lane Air Terminal P.O. Box 19824 Port Columbus Int'l. Airport Columbus, OH 43219
206B; T.C. H2SW	SH446NW	Installation of Simplex 5000 spray kit. Amended 6/30/78.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
206B; T.C. H2SW	SH515NW	Installation of Pacific Forest Research Center Mark II aerial ignition system. Issued 9/13/77.	NW	85330	Weyerhaeuser Company 1020 26th Avenue, N.W. Gig HArbor, WA 98335
206B; T.C. H2SW	SH830NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705
206B; T.C. H2SW	SH971NW	Installation of FLIR Systems infrared camera and accessories in Spectrolab search light gimbal. Issued 7/1/80.	NW	35840	FLIR Systems, Inc. 11830 S.W. Kerr Parkway Suite 350 Lake Oswego, OR 97035
206B; T.C. H2SW	SH996NW	Remote sensing unit and supporting structure on exterior left side. Issued 7/28/80.	NW	35008	F.H. Structures P.O. Box 1711 Bellevue, WA 98009
206B; T.C. H2SW	SH1030CE	Installation of battery temperature monitor and over temperature warning system. Issued May 1974.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Wichita, KS 67202
206B Jet Ranger II and III; T.C. H2SW	SH1503CE	Installation of Collins APS-841H automatic flight control system. Amended 4/10/80.	CE	24250	Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
206B; T.C. H2SW	SH4076SW	Installation of public address system. Issued 1/18/80.	SW	11890	Associated Air Center 8201 Lemmon Avenue Dallas, TX 75220
206B, 206L, 206L-1; T.C. H2SW	SH4233SW	Extended instrument panel and shroud. Issued 11/17/80.	SW	26065	Continental Radio Company 8701 Travelair Houston, TX 77061
206B, 206L, 206L-1; T.C. H2SW	SH4234SW	Inclined pedestal panel. Issued 11/17/80.	SW	26065	Continental Radio Company 8701 Travelair Houston, TX 77061

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206B, 206L, 206L-1; T.C. H2SW	SH4235SW	Dorne & Margolin DM N48-1 VOR antenna. Issued 11/17/80.	SW	26065	Continental Radio Company 8701 Travelair Houston, TX 77061
206L; T.C. H2SW	SH586AL	Install Airglas Model L2700-206L skis. Issued 6/10/76.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
206L, 206L-1; T.C. H2SW	SH1173SO	Installation of a wire strike protection system. Issued 10/8/80.	SO	17299	Bristol Aerospace, Ltd. P.O. Box 1177 Tri-City Airport Blountville, TN 37617
206L, 206L-1; T.C. H2SW	SH1541CE	Installation of Collins APS-841H helicopter automatic flight control system. Issued 4/21/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
206L, 206L-1; T.C. H2SW	SH4114SW	Installation of SFENA radio console 10713. Issued 4/28/80.	SW	71451	SFENA Corporation Aerospace Controls 2617 Aviation Parkway Grand Prairie, TX 75051
206L, 206L-1; T.C. H2SW	SH4115SW	Installation of instrument panel kit, 10501. Issued 4/28/80.	SW	71451	SFENA Corporation Aerospace Controls 2617 Aviation Parkway Grand Prairie, TX 75051
206L-1; T.C. H2SW	SH4099SW	SFENA 3-axis mini-stab system for single pilot IFR operation. Issued 5/9/80.	SW	71451	SFENA Corporation Aerospace Controls 2617 Aviation Parkway Grand Prairie, TX 75051
212; T.C. H4SW	SH17NW	Installation of Chadwick Electronic weighing system C-47. Issued 2/16/73.	NW	20750	Chadwick Incorporated 4375 S.W. 142nd Avenue Beaverton, OR 97005
212; T.C. H4SW	SH171WE	Installation of A500 battery temperature monitor systems. Issued 10/16/74.	WE	27300	C.S. Engineering 19097 Center Street Castro Valley, CA 94546
212; T.C. H4SW	H205WE	Installation of tail/rotor flood lights on upper surface of the horizontal stabilizers. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
212; T.C. H4SW	SH256WE	Installation of emergency exit window. Reissued 1/11/80.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
212; T.C. H4SW	SH261WE	Installation of rappelling kit support structures. Issued 6/9/80.	WE	80912	U.S. Department of Agriculture Forest Service Equipment Development Center 444 East Bonita Avenue San Dimas, CA 91773
212; T.C. H4SW	SH400NW	Installation of modified left hand door. Issued 1/20/77.	NW	33900	Evergreen Helicopters P.O. Box 358 McMinnville, OR 97128
212; T.C. H4SW	SH449AL	Installation of Airglas model L8500A skis. Amended 6/10/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
212; T.C. H4SW	SH463NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
212; T.C. H4SW	SH467NW	Cargo release switch wired in series with spare switch on pilot's cyclic control grip. Issued 6/15/77.	NW	85330	Weyerhouser Company 28801 Airport Road Eugene, OR 97401
212; T.C. H4SW	SH942EA	Installation of Tramm BTI-600 battery temperature indicating system. Issued 12/26/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
212; T.C. H4SW	SH1186SO	Replace existing nickel-cadmium battery with Teledyne Gill BB638T series lead-acid battery. Issued 11/17/80.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, N.W. Atlanta, GA 30339
212; T.C. H4SW	SH1281SW	Interior installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1284SW	Installation of Norton Company's radome and radar antenna brackets. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
212; T.C. H4SW	SH1286SW	Installation of Butler VAC/ADD area navigation system for VFR operation only. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1288SW	Installation of dual PC-17-400 Hertz static inverters. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn AVenue Burbank, CA 91505
212; T.C. H4SW	SH1289SW	Extension of power feeds to allow power distribution from the aft pedestal area. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1290SW	Installation of an extended instrument panel. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH1333SW	Installation of weather radar equipment. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
212; T.C. H4SW	SH2281SW	Environmental control unit. Issued 1/6/76.	SW	11890	Associated Air Center 7011 Lemmon Avenue Dallas, TX 75209
212; T.C. H4SW	SH2338SW	Modification for IFR type of operation. Issued 7/28/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220
212; T.C. H4SW	SH2466SW	AC inverter power system. Issued 5/24/77.	SW	11890	Associated Air Center, Inc. P.O. Box 20718 Love Field Dallas, TX 75220
212; T.C. H4SW	SH2746SW	Modification of four emergency exit panels. Issued 4/4/78.	SW	64300	Petroleum Helicopters, Inc. P.O. Box T Lafayette, LA 70502
212; T.C. H4SW	SH2892SW	Install 150 or 180 gallon auxiliary fuel tanks; standard utility seats modified; optional seats. Issued 12/21/78.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75222
214; T.C. H6SW	SH464NW	Incorporation of a weighing system for external load operations. Issued 6/10/77.	NW	56890	Measurement Systems Inter'l. 619 Riverside Drive Seattle, WA 98108
214B, 214B-1; T.C. H6SW	SH2298SW	Interior arrangement and installation. Issued 3/2/76.	SW	11890	Associated Air Center P.O. Box 20718, Love Field Dallas, TX 75220

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BELLANCA AIRCRAFT CORP., MINNESOTA

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
7 Series; T.C. 759	SA1-319	Continental C85-12 engine.	SO	17068	Columbus D. Bradley 325 Pasadena Drive Lexington, KY 40507
7 Series; T.C. 759	SA3-6	Installation of Pee-Kay Model 1500 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-214	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-303	Reinforced plastic instrument panel (exact duplicate of 5-150).	RM	28500	Dakota Aviation Company P.O. Box 18 Huron, SD 57350
7 Series; T.C. 759	SA3-322	Door modified to seaplane door.	GL	48900	E.O. Kunde Personal Air Service Mahtomedi, MN 55115
7 Series; T.C. 759	SA3-361	C-2200 main ski and CTF-2200 tail wheel ski or AWT 2500 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-362	C-2200 main ski and CTF-2200 tail wheel ski or AWT tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-368	A2000A main wheel-replacement ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA3-432	Install two auxiliary fins, one ventral fin and Pee-Kay Model 1800 floats. (Reissued 11/13/70.)	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-496	Install two auxiliary fins, one ventral fin and Pee-Kay Model 1800 floats. (Reissued 11/13/70.)	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-515	Skis L-1500A on main gear and L-1200A on nose gear.	AL	08125	Airglas Engineering Company P.O. Box 1254 Anchorage, AK 99502
7 Series; T.C. 759	SA3-523	Install four auxiliary and one ventral fin and Pee-Kay Model 1800 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7 Series; T.C. 759	SA3-628	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series; T.C. 759	SA4-97	Auxiliary five-gallon fuel tank in wing.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
7 Series; T.C. 759	SA4-276	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
7 Series; T.C. 759	SA4-338	Addition of exhaust stacks with venturi, pump, control valve, and tank for insect control work.	WE	71910	Vern Skaggs 2301 Pacific Coast Highway Lomita, CA 90717
7 Series; T.C. 759	SA4-359	Glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
7 Series; T.C. 759	SA4-699	R003-232-72T propeller with Continental C-90-12 engine.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7 Series; T.C. 759	SA4-836	Ceconite 101 covering of entire airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
7 Series; T.C. 759	SA4-1009	Eonite covering on complete airplane.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
7 Series; T.C. 759	SA4-1636	Tri-cycle landing gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
7 Series; T.C. 759	SA5-49	Tires and tubes 25x11x4.	AL	21540	Chapman Air Taxi P.O. Box 829 Palmer, AK 99645
7 Series; T.C. 759	SA5-68	Airglass Engineering L1500A main and L1200A nose skis.	AL	11386	Louis M. Applegate P.O. Box 1047 Fairbanks, AK 99701
7 Series; T.C. 759	SA6AL	L-1500A, A1650A, or L-2000A main skis and L-1200A nose ski.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 1254 Anchorage, AK 99502
7 Series; T.C. 759	SA33CE	Removal of door.	GL	46778	Darryl F. Johnson Route 5 Mount Pleasant, MI 48858
7 Series; T.C. 759	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743
7 Series; T.C. 759	SA216SW	Conversion of aircraft to tri-cycle gear configuration.	SW	47610	K.C. Aircraft, Inc. P.O. Box 4248 Lucian Field Shreveport, LA 71102
7 Series; T.C. 759	SA217AL	Install L-1650A or I-2000A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7 Series; T.C. 759	SA220SO	Tow bar, releast mechanism, and safety tow link.	SO	37092	Gasser Banners, Inc. P.O. Box 3502 Metropolitan Airport Nashville, TN 37217
7 Series; T.C. 759	SA232SO	Change Model 7AC powerplant from Continental C65-8 to C85-12.	SO	74928	Star Aircraft P.O. Box 411 Hialeah, FL 33010
7 Series; T.C. 759	SA274WE	Fuel system modification.	WE	55100	Marks Aviation Torrance Airport Torrance, CA 90510
7 Series; T.C. 759	SA286EA	Edo 60-1320 floats.	EA	61622	North American Flying Service, Inc. LIttle Ferry, NJ 07643
7 Series; T.C. 759	SA513AL	Installation of Hartzell model HC-C2YL-1BF/F8468A-8R constant speed propeller. Issued 2/11/74.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
7 Series; T.C. 759	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
7AC; T.C. 759	SA2-227	Windshield manufactured in accordance with Luminous Plastics, Inc. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
7AC & 7AC CONV; T.C. A-759	SA3-372	Installation of Lycoming O-235-C or Lycoming O-235-C1 engine and appropriate propeller. Reissued and amended 11/27/70.	RM	84393	C.L. Wagner Wagner Aerial Service Clark, SD 57225
7 Series; 11AC; T.C. 759, 761	SA3-435	Continental A-75-8 or A-75-8F carburetor type engine.	GL	62029	John T. Ownes 2707 East Towers Drive, Apt. 203 Cincinnati, OH 45238
7 Series; 11AC; T.C. 759, 761	SA4-369	Lift strut assemblies.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7 Series, 11AC, 11BC, S11AC; T.C. 759, 761	SA3-215	Laminated plastic and fiberglass nose cowl D-576P.	RM	28500	Dakota Aviation Company P.O. Box 18 Huron, SD 57350
7 Series, 11CC, S11CC; T.C. 759, 796	SA3-424	CTF-2200 tail ski on airplanes equipped with Scott 3000 tail wheel.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
7 Series, 11AC, S11AC, 11BC; T.C. 759, 761	SA4-444	Carburetor and cabin hot air muff with replaceable air inlet and outlet.	WE	66600	Peter H. Raymen 5829 Deborah Street Long Beach, CA 90801
7 Series, 11AC, S11AC, 11BC; T.C. 759, 761	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
7 Series, 11 Series; T.C. A-759, A-761, A-796	SA2710WE	Installation of carburetor heat box bearings. Issued 6/15/73.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
(Aeronca Champion) 7AC, S7AC, 7BCM (Army L-16A), 7CCM (Army L-16B), S7CCM, 7DC, S7DC, 7EC, S7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCB, 7GCBA, 7HC, 7JC, 7KC, 7GCAA, 7GCBC, (Aeronca Trytek) 11AC, S11AC, 11BC, S11BC, 11CC, S11CC, 14-19 Series; T.C. 759, 761, 796, 1A3	SA2666WE	Ceconite 102 material covering: Models listed - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
7AC, S7AC, 7BCM, 7CCM, S7CCM, 7DC, S7DC, 7EC, S7EC, 7FC, 7GC, 7ACA, 7ECA, 7GCA, 7GCAA, 7KC, 7KCAB, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 11AC, S11AC, 11BC, S11BC; T.C. 759, 761	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
7AC, S7AC, 7BCM, 7CCM, S7CCM, 7EC, S7EC, 11AC, S11AC, 11BC, S11BC; T.C. A759, A761	SA19SO	Installation of left and/or right auxiliary fuel tank(s). Reissued 11/8/77.	GL	02250	Aero Fabricators, Inc. P.O. Box 181 1216 North Road Lyons, WI 53148
7AC, S7AC, 7EC, 7FC, 7BCM, 7CCM, S7CCM, 7DC, 7GCBA, S7DC, 7JC, 11AC, S11AC, 11BC, S11BC, 11CC, S11CC; T.C. 759, 761, 796	SA150SO	Surface fabric attachment clip. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
7; 11, S11; 11CC, S11CC; 14-19, 17-30, -31; T.C. A-759, A-761, A-796, 1A3	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
7 Series; 14-19; T.C. A-759, 1A3	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
7 Series; 14-19, 14-19-2, 14-19-3; T.C. 759, 1A3	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
7 Series; 14-19, 14-19-2, 14-19-3; T.C. 759, 1A3	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
7AC, 7BCM, 7CCM, 7DC; T.C. A-759	SA2309WE	Installation of Madras Air Service Part No. 104 wing tips. Amended 10/26/71.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
7AC, 7BCM, 7CCM, 7DC, S7AC, S7BC, S7CC, S7DC, 11AC, S11AC, 11BC; T.C. 759, 761	SA89AL	Installation of auxiliary fuel tanks. Amended 2/7/75	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
7AC, 7BCM, 7CCM, 7DC, 7EC, 7ECA, 7GC, 7GCA, 7GCB, 7GCBC, 7KCAB, 77GAA w/ oleo; T.C. A-759	SA754CE	Install Aero Model M1500, M1800 or M2000 main skis. Amended 1/13/72.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
7AC, BC, BCM, DC, EC, ECA, FC, GC, GCA, GCB, GCBA, HC, JC, KC, S7AC, S7EC, S7CCM, S7DC, 7GCAA, 7GCBC, 7CCM; 11AC, S11AC, 11BC, S11BC, 11CC, S11CC; 14-19, -2; 8GCBC; T.C. A-759, A-761, A-796, 1A3, A21CE	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
7AC, BC, BCM, DC, EC, ECA, FC, GC, GCA, GCB, GCBA, HC, JC, KC, S7AC, S7EC, S7CCM, S7DC, 7GCAA, 7GCBC, 7CCM; 11AC, S11AC, 11BC, S11BC, 11CC, S11CC; 14-19, -2; T.C. A-759, A-761, A-796, 1A3	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
7AC, S7AC, 7BCM, 7CCM, S7CCM, 7DC, S7DC, 7EC, S7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCB, 7GCBA, 7HC, 7JC, 7KC, 7GCAA, 7GGBC; 11AC, S11AC, 11BC, S11BC; 11CC, S11CC; 14-19 Series; T.C. 759, 761, 796, 1A3	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCAA, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 7KCAB; 14-19-3A, 17-30, -30A, -31A, -31ATC; T.C. A-759, 1A3	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417
7EC, 7ECA, 7FC, 7GC, 7GCA, 7GCAA, 7GCB, 7GCBA, 7GCBC, 7HC, 7JC, 7KCAB; 14-19-3A, 17-30, 17-30A, 17-31A; 17-31ATC; T.C. A-759, 1A3	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A450, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. 3 Winter Avenue Deep River, CT 06417
7ECA; T.C. 759	SA334CE	Installation of Pee-Kay Model 1800 or B1800 (TSO-C27-2) seaplane floats and two auxiliary fins. Amended 8/17/73.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7ECA (Seaplane); T.C. 759	SA483AL	Installation of McCauley 1B90-LCM-7534 propeller. Issued 7/17/72.	AL	42132	Martin (NMI) Hettinga 1138 I Street Anchorage, AK 99501
7 ECA; T.C. A-759	SA745EA	Installation of Edo Model 88-1650A floats. Amended 1/13/78.	GL	32625	Edo-Aire Seaplane Div. (Edo Corp.) c/o Air Aids of Dayton 3800 Clearview Drive Dayton, OH 45439
7ECA, 7KCA, 8KCAB; T.C. A759, A21CE	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Company airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
7ECA, 7KCAB land only; T.C. 759	SA606AL	Install leading edge cuff. Amended 8/31/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
7ECA, 7GCBC; T.C. A-759	SA261AL	Installation of Airglas Model L2000 and L-1650 wheel replacement skis. Amended 11/22/68.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7ECA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA442AL	Installation of 8.50x6 4- or 6-ply rated Goodyear or UniRoyal tires. Amended 11/7/73.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
7ECA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA3019WE	Installation of 8.50 x 6.00 4-ply rated, Type III aircraft tires. Issued 4/30/75.	WE	39580	Guardian Flying Service, Inc. 500 E. Highway 41 Las Vegas, NV 89119
7ECA, 7GCAA, 7GCBC, 7KCAB, 8KCAB; T.C. 759, A21CE	SA693CE	Install AC induction air filter type AAF-106. Amended 3/1/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
7ECA, 7GCAA, 7KCAB, 7GCBC w/ landing gear; T.C. A-759	SA755CE	Install Model M1500, M1800, or M2000 main skis. Amended 12/9/71.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
7FC; T.C. A-759	SA374GL	Remove tri-cycle landing gear and install main landing gear and tail wheel. Issued 12/16/79.	GL	48244	King Aero Services, Inc. 7170 East Main Street Reynoldsburg, OH 43068

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
7FC, 11AC; T.C. 759	SA1008WE	Installation of Poly-Fiber covering material (complete aircraft). Amended 8/21/79.	WE	75250	Stits Aircraft Coatings P.O. Box 3084 43rd South Fort Drive Riverside, CA 92519
7GC, 7GCB, 7GCBC, 7HC; T.C. 759	SA18CE	Installation of Pee-Kay Model 1800 or B1800 (TSO-C27-2) seaplane floats. Amended 8/17/73.	EA	29998	Pee-Kay Devore Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
7GC, KC, GCB, GCA, GCAA, GCBC: T.C. 759	SA216AL	Install L-2500A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCA (landplane), 7GCB, 7GCBC (land and float plane); T.C. A-759	SA283AL	Installation of Hartzell HC 82XL-1, -2, cr -6 propeller hub with 7636D-4 blades or HC-C2YL-1B hub with 7663-4 blades and appropriate Woodward governor. Amended 7/22/69.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
7GCA, 7GCB, 7KC, 7GCBA, 7GCAA, 7GCBC, 7KCAB; T.C. 759	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
7GCAA, 7GCBC, 7KCAB; T.C. A-759	SA33GL	Installation of EDO Model 88A-1650 floats. Reissued 6/22/76.	GL	03480	Air-Ads-of-Dayton with Edo-Aire Seaplane Division 3800 Clearview Drive Dayton, OH 45439
7GCAA, 7GCBC, 7ECAB; T.C. A-759	SA1536WE	Installation of larger rudder. Reissued 6/5/69.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
7GCAA, 7GCBC, 7KCAB, 14-19-3A, 17-30; T.C. 1A3, A-759	SA71GL	Install P/N BA8110 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities, Inc. 9600 West 52nd Street Kenosha, WI 53140
7GCB; T.C. 759	SA323AL	Installation of McCauley 1A175-GM8042 propeller.	AL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645
7GCBC; T.C. 759	SA266AL	Installation of L-2500 skis. Amended 6/21/68.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
7GCBC; T.C. 759	SA520AL	Installation of leading edge cuff stall fences, tip fences. Amended 2/2/77.	AL	27250	Crosswinds, Inc. 2301-1/2 Merrill Field Drive Anchorage, AK 99507
7GCBC, 8GCBC; T.C. A-759, A21CE	SA977NW	Installation of automatic flagmen, Model No. 5A. Issued 7/22/80.	NW	61619	North American Industries, Inc. Route 4, City County Airport Walla Walla, WA 99362
7KCAB; T.C. A-759	SA25RM	Installation of Christen Model 801 Inverted Oil System. Issued 3/28/74.	RM	49369	Lloyd Land Star Route, Box 65A Hudson, CO 80642
8GCBC; T.C. A21CE	SA72GL	Installation of wheel replacement ski models M2000 and M3000. Issued 3/12/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
8GCBC; T.C. A21CE	SA530AL	Installation of Hartzell HC-C2YK-1BF/F7666A-0. Issued 10/21/74.	AL	61640	Northland Aviation, Inc. P.O. Box 3143 Fairbanks, AK 99701
8GCBC; T.C. A21CE	SA656NW	Installation of Pee-Kay Model 2300 or B2300 seaplane floats (on an aircraft with constant speed propellers and long range fuel tanks. Reissued 9/19/80.	SW	30000	PeeKay Float Division DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
8GCBC; T.C. A21CE	SA666AL	Installation of Fluidyne C3000A skis. Issued 7/17/79.	AL	35800	Flirite, Inc. P.O. Box 297 Kodiak, AK 99615
8GCBC; T.C. A21CE	SA741NW	Installation of EDO-AIRE Model 689-2130 seaplane floats. Amended 6/4/80.	EA	32625	EDO-AIRE Seaplane Division Republic Airport East Farmingdale, NY 11735
8GCBC; T.C. A21CE	SA742NW	Installation of Hartzell HC-C2YR-1BF/F7666A-0 propeller on a Lycoming O-360-C1E engine. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
8GCBC; T.C. A21CE	SA743NW	Installation of Bellanca 72 gallon fuel system. Issued 4/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
8GCBC; T.C. A21CE	SA1001EA	Installation of Pee-Kay Model 2300 (TSO-C27-2) seaplane floats. Issued 4/11/75.	EA	29998	Pee-Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
8KCAB; T.C. A21CE	SA874NW	Installation of a smoke generating system. Issued 1/15/80.	NW	65930	R & K Aeromotive, Inc. 10011 173rd Avenue, S.W. Rochester, WA 98579
11AC; T.C. 761	SA4-99	Fiberglass cloth with resin over muslin applied.	WE	46783	R.W. Johnson Route 2, Box 571-B Ojai, CA 93023
11AC; T.C. 761	SA4-789	McCauley 1B90-CM/7045 propeller on Continental A-65-8 engine.	NW	68536	Paul H. Robinson 604 S. 136 Street Seattle, WA 98101
11AC; T.C. 761	SA345CE	Remove right door.	CE	35650	Flanagan Aircraft 20224 R.D. Mize Road Independence, MC 64050
11AC, S11AC, 11BC; T.C. 761	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
11AC, S11AC, 11BC; T.C. 761	SA4-1276	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
11AC, S11AC, 11BC, S11BC, 11CC, S11CC; T.C. A-761, A-796	SA57RM	Installation of Lycoming O-235-C1 or O-235-C2C engine. Issued 6/19/75.	RM	84393	Colman L. Wagner 401 1st Street East Clark, SD 57225
11AC, 11BC; T.C. 761	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
11AC, 11BC, 11CC; T.C. 761, 796	SA217AL	Install I-1650A or I-2000A skis.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
11AC, 11BC, 11CC; T.C. 761, 796	SA535AL	Installation of wing auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
11BC; T.C. 761	SA3-7	Installation of Pee-Kay Model 1500 floats with Edo struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC; T.C. 796	SA3-115	Model 3000 main ski and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
11CC; T.C. 796	SA3-670	Install Pee-Kay Model 1500 floats with Edo struts and fittings. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
11CC; T.C. 796	SA69SO	Continental C85-12F Series engine less starter and generator.	SO	49720	C.W. Lasher 14100 NW. 62 Court Miami, FL 33012
11CC; T.C. 796	SA262CE	Manufacture parts and install 12-30A electrical system. (Requires alteration of engine per STC SE3CE.)	GL	67160	Kenneth L. Repke 7788 Auburn Detroit, MI 48233
11CC, S11CC; T.C. 796	SA4-1270	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-13, 14-19, 14-19-2, -19-3, -19-3A, 17-30, -31, -31A, -31TC, -31ATC; T.C. 1A3, 773	SA846SW	Wing root fairings. Reissued 11/27/78.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
14-19 Series; T.C. 1A3	SA1-551	Fuselage and fin covered with metal skin.	EA	72100	Skycraft Design, Inc. Mercer County Airport West Trenton, NJ 08628
14-19 Series; T.C. 1A3	SA4-867	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series; T.C. 1A3	SA4-883	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
14-19 Series; T.C. 1A3	SA4-909	Autopilot. Reissued October 1973.	WE	17492	Brittain Industries, Inc. 12027 S. Prairie Avenue Hawthorne, CA 90250

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
14-19 Series; T.C. 1A3	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ
14-19 Series; T.C. 1A3	SA4-1127	Ceconite 101 covering of entire aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-19 Series; T.C. 1A3	SA4-1269	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
14-19 Series; T.C. 1A3	SA4-1283	Ceconite 103 covering of plywood portions of the aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
14-19 Series; T.C. 1A3	SA486SW	Automatic pilot AK143, AK143E and AK143E-3.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
14-19 Series; T.C. 1A3	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court, P.O. Box 175E San Leandro, CA 94577
14-19 Series; T.C. 1A3	SA645SW	AK125 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19, 14-19-2; T.C. 1A3	SA294GL	Install Cleveland wheel 40-97A and brake 30-63A. Issued 3/22/79.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19, -A-2, -3, -3A, 17-30, -31, -31TC; T.C. 1A3	SA666NW	Installation of TEflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
14-19-2; T.C. 1A3	SA203GL	Installation of McCauley 2A34C66-N/S-90AT-12 propeller manufacturer's installation with instruction. Issued 12/8/77.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-2; T.C. 1A3	SA798WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 Wheel Assemblies in lieu of Firestone DFA180 wheel assembly. Firestone CFA252 brakes or Bodell BMI252 brakes required with this installation. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
14-19-3, 14-19-3A; T.C. 1A3	SA292GL	Install Cleveland wheel 40-75E and brake 30-52M on main gear. Issued 1/31/79.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-3, 14-19-3A, 17-30, -30A, -31, -31A, -31TC, -31ATC; T.C. 1A3, A18CE	SA847SW	Main landing wheel doors. Reissued 11/27/78.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130
14-19-3, 14-19-3A; T.C. 1A3	SA874SW	Hartzell/Wren Beta System reverse pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
14-19-3A; T.C. 1A3	SA108GL	Installation of Continental IO-520D engine and McCauley D2A34C58/90AT-10 propeller. Issued 2/11/76.	GL	84890	Weber's Aero Repair, Inc. P.O. Box 264 Alexandria, MN 56308
14-19-3A; T.C. 1A3	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STC - SA645SW.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19-3A, 17-30; T.C. 1A3	SA981SW	Manual Electric Trim AK276.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
14-19-3A, 17-30, -31, -31TC; T.C. 1A3	SA1196SW	Mitchell automatic flight system model AK309 consisting of Century I, automatic aileron stabilizer with omni tracker. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30; T.C. 1A3	SA845SW	Nose gear doors. Reissued 1/24/79.	SW	42750	Houde Fiberglass Products 1321 Hillcrest New Braunfels, TX 78130

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
17-30; T.C. 1A3	SA869SW	Mitchell automatic flight system AK233 consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio coupler, glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30; T.C. 1A3	SA3780WE	Installation of Continental IO-502-K engine, Hartzell HC-C3YF-1B/8468A-8R propellers, and associated installation components. Issued 11/29/78.	WE	08347	Air Repair P.O. Box 813 Santa Paula, CA 93060
17-30, -30A, -31, -31A; -31ATC; T.C. A18CE	SA903SO	Reposition of fuel pump. Issued 7/30/76.	SO	86295	Keith Wilson Aircraft, Inc. 2787 North Second Street Memphis, TN 38127
17-30A; T.C. A18CE	SA1344CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 6103
17-30A; T.C. A18CE	SA3688WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
17-30A, -31A; T.C. A18CE	SA1118SW	Manual electric trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, -31, -31ATC; T.C. A18CE	SA1195SW	Mitchell automatic flight system AS309 consisting of Century I, automatic aileron stabilizer with omni tracker. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA574SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric pitch trim and optional flight director indicator DH-841. Issued 2/1/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FI 33310
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1235SW	Automatic flight system AK215, consisting of Century II autopilot with optional automatic aileron stabilizer and radio coupler. Issued 12/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1236SW	Automatic flight system AK233, consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, radio, and glide couplers. Issued 12/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1257CE	Installation of the King KFC-200 2-axis, flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or stand alone electric trim. Amended 10/6/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1811SW	Mitchell automatic flight system AK466 and AK466FD consisting of Century IV autopilot and Century IV flight director with electronic command/automatic pitch trim. Issued 2/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA1812SW	Mitchell automatic flight system AK465 consisting of Century III autopilot with optional electronic command/automatic pitch trim, radio coupler, and glide slope coupler. Issued 2/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3059SW-D	Mitchell AK466 and AK466FD consisting of Century IV autopilot and Century IV flight director with electronic command/automatic pitch trim. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3060SW-D	Mitchell AK465 consisting of Century III autopilot with optional electronic command/automatic pitch trim, optional radio coupler, and glide slope coupler. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3061SW-D	Mitchell AK495 consisting of Century I autopilot with optional omni tracker. Issued 7/2/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3071SW-D	Mitchell automatic flight system AK546 consisting of Century IIB autopilot with optional radio coupler. Issued 9/5/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, 17-31A, 17-31ATC; T.C. A18CE	SA3083SW-D	Mitchell command electric trim AK545. Issued 12/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
17-30A, -31A, -31ATC; T.C. A18CE	SA3267WE	Modification of aileron control system by addition of aileron centering spring and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 10/1/76.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-300, -300B, -300C; T.C. 4A26	SA4097WE	Installation of forward entrance airstair. Issued 2/5/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanover Street Van Nuys, CA 91406
707-300, -400; T.C. 4A26	SA3331WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
707-300, -400; T.C. 4A26	SA4156SW	Aft airstair. Issued 7/25/80.	SW	43005	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
707-300B, -300C; T.C. 4A26	SA817NW	Modification of cabin passenger interior, and forward storage units. Issued 8/8/79.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
707-300B, -300C; T.C. 4A26	SA1620CE	Replace Pratt & Whitney JT3D-3B engines with JT3D-3C engines. Issued 12/29/80.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Inter'l Airport Kansas City, MO 64195
707-300B, -300C; T.C. 4A26	SA2594WE	Modify 707-300B and -300C series airplanes by the installation of wing tip mounted emblem light. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
707-300B, -300C; T.C. 4A26	SA2610WE	Installation of Bell & Howell movie projection system Nos. 478441 and 478440. Issued 1/11/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
707-300C, 727C; T.C. 4A26, A3WE	SA647SO	Installation of AIF partition class divider P/Ns 402-1, 402-2, 402-3, 402-4, and header assembly P/Ns 403-1 and 404-1. Amended 7/16/68.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33142
707-300C Series; T.C. 4A26	SA793SO	Installation of provisions for transportation of livestock. Issued 10/22/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
707-300C Series; T.C. 4A26	ST939SO	Installation of livestock pen. Issued 6/10/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-300C Series; T.C. 4A26	SA1443WE	Installation of tray carrier.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-320; T.C. 4A26	SA2374WE	Installation of an air filter to the cabin pressure limit control outflow safety valve, P/N 103430-3. Issued 6/24/71.	WE	07505	AiResearch Manufacturing Company 2525 W. 190th Street Torrance, CA 90509
707-320C; T.C. 4A26	SA251NW	Installation of cargo system. Issued 1/16/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
707-320C Series; T.C. 4A26	SA3539WE	Installation of single, palletized Litton LTN-51 or LTN-72 inertial navigation system. Issued 12/20/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
707-321; T.C. 4A26	ST710SO-D	Relocation of "B" galley approximately 10" forward of present location. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321; T.C. 4A26	SA778CE	Addition of large cargo door in left hand side of fuselage. Issued June 1971.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA852CE-D	Reduction of empty weight by removal of all passenger interior equipment and installation of fire resistant lining. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-321; T.C. 4A26	SA1555WE	Installation of fire warning electrical monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Canoga Park, CA 91304
707-321, -321B; T.C. 4A26	SA344EA	Install inertial navigation system. Amended 4/1/66.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321, -321B, -321C, -331, -386C; T.C. 4A26	ST652SO-D	Installation of P&W JT8D engine and associated structural and fairing pod under L.H. wing between No. 2 engine and fuselage. Reissued 9/7/78.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
707-321, -321B, -331; T.C. 4A26	ST656SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in the forward passenger compartment. Amended 11/6/68.	SO	67030	Mace Unit of REF Dynamics, UOP 4856 Victor Street Jacksonville, FL 32207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-321, -321B, -321C, -331; T.C. 4A26	ST712SO-D	Modification and installation of a Hardman Model 6747 seat. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321, -324C; T.C. 4A26	SA2238WE	Installation of Brownline Cargo net assembly #41412 used in conjunction with Brownline pallet assemblies #40160 and 40144. Amended 5/16/75.	WE	17740	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321, -331, 720-040B; T.C. 4A26, 4A28	SA1-593	See Document No. Report No. 3078, dated January 30, 1969, concerning pallet assembly IR-3000 Rev. B. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
707-321, -400; T.C. 4A26	ST914SO	Installation of cargo floor. Amended 1/19/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
707-321B; T.C. 4A26	SA611EA	Installation of dual A.C. electronics navigation systems on P/N N435PA, S/N 5034. Amended 5/21/68.	EA	62300	Pan American World Airways Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B; T.C. 4A26	ST702SO-D	Installation of Bendix FINDS. Limited to aircraft N421PA S/N 19266. Issued 11/15/68.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST707SO-D	Modified aircraft to incorporate Emerson engine performance monitoring system, aircraft S/N 19363, N428PA. Issued 10/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-321B; T.C. 4A26	ST713SO-D	Installation of a coat closet between fuselage stations 373 and 416 L.H. side. Reissued 9/12/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B; T.C. 4A26	SA1067EA	Installation of stowage cabinets Issued 12/16/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
707-321B; T.C. 4A26	SA3549WE	Installation of Garrett GTCP85-98CK auxiliary power unit in forward baggage compartment. Issued 1/27/78.	WE	07450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
707-321B, 321C; T.C. 4A26	ST709SO-D	Installation of flight spares container in right hand main landing gear wheel well on fuselage station 960 bulkhead. Reissued 9/11/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	SA700EA	Switches are installed on outboard thrust levers to disengage autothrottle system.	EA	62300	Pan American World Airways, Inc. Hangar #14 - JFK Int'l Airport Jamaica, NY 11430
707-321B, -321C; T.C. 4A26	ST704SO-D	Installation of Bell & Howell forward projection movie system. Reissued 9/7/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321-B, -321C; T.C. 4A26	SA1076EA-D	Removal of Loran navigation system and installation of dual Omega navigation systems for updating doppler. Amended 8/13/79.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
707-321C; T.C. 4A26	SA541NW	Installation of quick change interior. Issued 1/18/78.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98021
707-321C; T.C. 4A26	SA1134WE	Palletized cargo system installation 65-42629 or 65-43629 with Brownline pallet 22630-51, 26100-51 or -52 and Brownline net assy 23225-51, 23226-51, or 22750-51. Amended 5/16/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1143WE	Installation of Boeing palletized cargo system. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; T.C. 4A26	SA1293WE	Palletized cargo system installation 65-42629 with Brownline pallet 22630-51 and net assy 23225-51 or 23226-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-321C; T.C. 4A26	SA1597WE	Installation of Heath Tecna Corporation pallet AC-10065 and Brownline Corporation Net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C; T.C. 4A26	SA2125WE	Installation of Ancra Cargo Net Assembly 40234-10 used in conjunction with either Brownline pallet assembly 22630-51 or Heath Tecna pallet assembly AC 10065-1.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 90245
707-321C; T.C. 4A26	SA2221WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp Net Assembly 40234-10 and net assemblies approved to NAS 3610-2A1N and NAS 3610-2A3N. Issued 8/19/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
707-321C; T.C. 4A26	SA3005WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-321C, 727-21C; T.C. 4A26, A3WE	SA736EA	Installation of L. Marino forward cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-321C, 727-21C; T.C. 4A26, A3WE	SA1859WE	Installation of net assembly AC-10292-1 used in conjunction with pallet assembly AC-10065-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-321C, 727-21C; T.C. 4A26, A3WE	SA2045WE	Modification by installation of pallet assembly 40160 used in conjunction with net assemblies 23225-51, 23226-51, 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-321C; 727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA849EA	Goodyear Aerospace Corporation cargo pallet (1.5 Fwd.) P/N 634A303-001-101 is eligible to be used only in combination(s) as shown in the following tables:	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315

BOEING COMPANY			CARGO NET	
AIRPLANE MODEL	CARGO RESTRAINT SYSTEM	WEIGHT & BALANCE CONTROL MANUAL (b)	MANUFACTURER & PART NO.	TIE-DOWN CONFIGURATION
707-321C (a)	65-42629 65-43629	D6-14083.6	Brownline 40510-101 22758-51 23225-51	88" x 125"
			Marino LM1500-100	88" x 125"
			Brownline 21970-51 (Chg. G)	88" x 108"
727-21C (a)	65-49102	D6-21000.17C	Brownline 40510-101 22758-51 23225-51 23226-51	88" x 125"
			Marino LM1500-100	88" x 125"
			Brownline 21970-51 (Chg. G)	88" x 108"
747-121	65B-60060 Lower Lobe Compartment Aft Hold ONLY	D6-13700	Brownline 22758-51	88" x 125"

(a) Barrier Net Installation per Boeing Drawing 65-34700-1 required for these model aircraft with this installation.

(b) The applicable Boeing Weight and Balance Control Manual must be used to obtain permissible compartment load, under conditions described therein, not to exceed the pallet-net combination(s) capacity of 13,300 lb. for the 88" x 125" tie down configuration or 8000 lb. for the 88" x 108" tie down configuration.

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-321C;727-21C; 747-121; T.C. 4A26, A3WE, A20WE	SA1902WE	Installation of Irvin cargo pallet assembly 125014 used in conjunction with net assembly 22758-51 (Brownline), net assembly 40234010 (ANCRA), and net assembly LMI-500-100 (Marino). Amended 8/25/70.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-321C, 727-21C: T.C. 4A26, A3WE	SA2103WE	Installation of Net Assembly 40510-101 used in conjunction with Brownline Pallet Assemblies 40160-101 thru -100, 22630-51 and Heath Pallet AC-10065-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323, 707-385C; 707-323B; T.C. 4A26	SA517EA-D	Installation of dual Litton LTN-51 inertial navigation systems. Install No. 2 ship's battery (24 volts, 36 AH) to provide standby DC power for No. 2 inertial navigation system. Installation perforated filler panels fore and aft of both control/display units. Amended 1/22/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA556EA-D	Convert interior passenger arrangement to winter configuration of 4 first class lounge, 32 first class seats and 101 tourist class seats. Amended	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA561EA-D	Installation of automatic throttle/speed control system. Amended 3/2/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA562EA-D	Installation of dual aileron and elevator surface servos to operate in a single servo configuration with the PB20 autopilot system. Amended 3/31/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323B; T.C. 4A26	SA564EA-D	Modify the interior arrangement of the 707-323B aircraft from its present configuration to 32 F/C plus 102 T/C passencer. Install additional meal stowage. Issued 5/18/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA508EA-D	Install a single inertial navigation system (LTN-51E). Amended 1/5/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74116
707-323C; T.C. 4A26	SA525EA-D	Convert interior passenger arrangement to the summer configuration of four first class lounge, 26 first class, and 113 tourist class seats. Amended 4/15/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA559EA-D	Interior arrangement and configuration.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA565EA-D	Install emergency evacuation slide lights for station 990. Issued 6/17/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C; T.C. 4A26	SA1560WE	Installation of Aeronca cargo containers on Boeing 707-323C.	WE	02398	Aeronca, Inc. Aerocal Division 24751 S. Crenshaw Boulevard Torrance, CA 90505
707-323C; T.C. 4A26	SA1720WE	Installation of Heath Tecna structural igloo assembly AC-0123. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2008WE	Installation of structural cargo container AC-10260-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-323C; T.C. 4A26	SA2401WE	Installation of Transequip structural igloo assembly P/N 245084 in conjunction with loading systems 65-42625, 65-42630, and 64-34899. Issued 8/26/71.	WE	79000	Transequip, Inc. 5438 W. 104th Street Los Angeles, CA 90045
707-323C; T.C. 4A26	SA2453WE	Installation of Transequip structural containers in position I13 (container 235111) and position I14 (container 235112). Amended 10/30/79.	WE	79000	Transequip, Inc. 5438 West 104th Street Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2022WE	Installation of pallet assembly 40122-101, -102, -103, -104, and -105 used in conjunction with net assemblies 22178-51, 23652-51, 22361-51c, 22780-51, 22780-52, 22656-51, 22656-52, and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -327C, -329C, -330C, -331C, -336C, -337C, -338C, -351C, -373C, -385C; 727-25C, -27C, -29C, -30C, -31C, -51C, -62C, -180C; T.C. 4A26, A3WE	SA2174WE	Installation of pallet assembly 40550-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22362-51 or AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -331C, 373C, 385C; 727-31C, -180C; T.C. 4A26, A3WE	SA1924WE	Installation of Irvin cargo pallet assembly 125001-501, -503, -505, -507 used in conjunction with net assembly 10-60934-1 (Boeing).	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
707-323C, -331C, -373C, 727-1A7C, -31C, -180C; T.C. 4A26, A3WE	SA2098WE	Installation of structural cargo container 40619-101, -103. Amended 5/16/75.	WE	17740	Brooks & Perkins 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA945WE	Installation of autopilot go-around unit. Amended 8/1/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
707-323C and 707-385C; T.C. 4A26	SA1524WE	Brownline Structural Containers 23885-51 may be used as optional cargo equipment either in place of or with cargo net assemblies. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA1939WE	Modify by installation of structural cargo container 24385-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C and 707-385C; T.C. 4A26	SA2234WE	Installation of Brownline Division structural container No. 41302-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-323C, -385C; 727-22C; T.C. 4A26	SA2278WE	Installation of Brownline cargo container model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division Torrance, CA 90505
707-326C; T.C. 4A26	ST701SO-D	Installation of alternate inertial navigation system control display unit. Limited to aircraft N870PA, S/N 20016; N871PA, S/N 20017; N872PA, S/N 20018. Amended 6/10/69.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
707-327C; T.C. 4A26	SA739EA	Installation of Inflight Motion Picture System. Reissued 10/24/73.	EA	11434	Inflight Motion Pictures, Inc. 175-2[illegible] 148th Avenue Jamaica, NY 11434
707-327C, -330C, -338C, -351C, 727-25C, -27C, -30C, -51C, -62C; T.C. 4A26, A3WE	SA2026WE	Installation of pallet assembly 40134-101, -102, -103, -104 and -105 used in conjunction with net assemblies 22364-51, 23215-51, 23618-51 or 23783-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-327C; T.C. 4A21	SA2748WE	Installation of weight and balance computer system. Issued 8/15/73.	WE	52010	Lockheed Aircraft Service Company Ontario International Airport P.O. Box 33 Ontario, CA 91764
707-330C, 727-30C; T.C. A3WE	SA1917WE	The type design change consists of installation of pallet assembly 24076-51 in conjunction with net assembly 22361-51, 22364-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-331; T.C. 4A26	SA428CE	Installation of single seat system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-331; T.C. 4A26	SA489CE	Relocation of Lockheed Air Service Model 109CR flight recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-331; T.C. 4A26	SA635CE	Installation of dual radio altimeter system provisions and single radio altimeter equipment. Amended 2/20/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
707-331; T.C. 4A26	SA854CE-D	60,000 lbs. main deck allowable loading. Issued 12/7/73.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-331; T.C. 4A26	SA1551WE	Installation of fire warning monitoring circuit in engine fire detection system. Reissued 6/8/73.	WE	20511	Celesco Industries 7800 Dearing Conoga Park, CA 91304
707-331, 707-331 (ADV); T.C. 4A26	SA291CE	Installation of single SCAT system. Amended 7/23/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
707-331, -331B, -331C, -373C, -338C; T.C. 4A26	SA465CE	Installation of Fenwall fuel vent surge tank. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64108
707-331 (Advanced), -331C, -338C, -373C; T.C. 4A26	SA899CE	To permit autopilot coupled approaches at 40 degrees flp setting below 500 feet. Issued August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
707-331, -331B, -331B(ADV), -331C, -373C; T.C. 4A26	SA1327CE	Installation of Bendix ONS-25-5 Omega navigation system for updating primary self-contained navigation system. Issued March 1977.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64195
707-331, -373C, 727-31A, -180C; T.C. 4A26, A3WE	SA2290WE	Installation of Ancra pallet net assembly P/N 40452-10 used in conjunction with Boeing 9g pallet assemblies (88" x 125") numbers 10-60935-1, 10-60935-11, 10-60935-17, 10-60935-21, 10-60935-27 and 10-60935-37. Amended 2/22/71.	WE	10750	Ancra Corporation 616 East Franklin Avenue El Segundo, CA 990245
707-331B, -331C; T.C. 4A26	SA1518CE	Installation of a Growth Industries dual cavity oven. Issued 10/18/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
707-331B, -331C, -338C, -373; T.C. 4A26	SA1039CE	Replacement of existing fire detection system with a Kidde dual loop fire detection system. Issued September 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
707-331C; T.C. 4A26	SA523CE	Installation of single SCAT system. Amended 7/31/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
707-331C; T.C. 4A26	SA524CE	Installation of auto throttle system. Amended 7/1/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, Mo 64153
707-331C; T.C. 4A26	SA658CE	Installation of dual radio altimeter provisions single equipment.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
707-331 (Convertible), 707-338C; T.C. 4A26	SA234CE	Autopilot variable angle intercept installation. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-331C, -338C; T.C. 4A26	SA385CE	Installation of single SCAT system. Amended July 1973.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
707-331C, -338C; T.C. 4A26	SA386CE	Installation of auto thrust system. Amended 8/7/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
707-331C, -373C, -338C; T.C. 4A26	SA783CE	Installation of revised life raft and courier seat provisions. Amended August 1973.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA757EA	Goodyear Aerospace Corporation Cargo pallet with barrier net installation. Amended 3/17/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massilon Road Akron, OH 44315
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1866WE	Installation of Heathair AC-10113-1 net assembly in conjunction with pallet assemblies AC-10070-1 and AC-10347-1. Reissued 1/6/71.	NW	41625	Heath Techna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA1963WE	Installation of pallet assembly 23250-52 used in conjunction with net assemblies 22178-51, 22780-52, 22656-51, 22656-52 and AMF 306-60078-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2172WE	Installation of Irvin Industries Net Assembly 120012-501 used in conjunction with Cargo Pallet 125001-501, -503, -505, -507. Issued 8/19/70.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, -373C, 727-31C, -180C; T.C. 4A26, A3WE	SA2412WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 South Figueroa Street Gardena, CA 90247
707-331C, 727-31C; T.C. 4A26, A3WE	SA2088WE	Installation of cargo pallet assemblies 1950-90-501 and 1950-90-1001 used in conjunction with net assembly 22758-51 (Brownline).	WE	19890	Cargo Systems, Inc. 1040 West Hoover Street Orange, CA 92667
707-338C; T.C. 4A26	SA730EA	9G 10,000 lb. maximum capacity Pallet Cargo Net P/N LM 1505-1 eligible as replacement for approved Brownline Net P/N 22361-51 or Boeing Net 10-60934-1 in combination with 125" x 88" pallets Brownline P/N 23223-51 or Phenrock P/N 22861-51 or Bruggermann & Brand P/N 2102. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-338C; T.C. 4A26	SA1230CE-D	Passenger cabin contemporary interior installation. Issued 2/1/77.	CE	16878	The Boeing Company 3802 South Oliver Wichita, KS 67210
707-338C; T.C. 4A26	SA2352WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargo pallet assembly P/N 24076-51. Issued 6/14/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
707-345C; T.C. 4A26	SA675EA	Installation of L. Marino cargo net. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-345C; T.C. 4A26	SA725EA	Pallet P/N LM1600 (1.5G Fwd). Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
707-347, 720-047B; T.C. 4A26, 4A28	SA2557WE	Replacement of existing girt on Air Cruiser evacuation slide P/Ns 15D22093-7, 15D22093-11, 15D22094-10 and 15D22454-2 with Sargent Industries/PICO Division girt P/N 6176105-103. Issued 6/30/72.	WE	70130	Sargent Industries Pico Division 2045 Evans Avenue San Francisco, CA 94124
707-347C; T.C. 4A26	SA979CE-D	Passenger interior arrangement modified to 5 pallet cargo/passenger configuration, per Boeing Dwg. 65-88752 & 65-88753, cargo conversion capability, Class "B" compartment with passengers, Class "E" compartment with no passengers. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-347C; T.C. 4A26	SA2975WE	Installation of shroud assembly, P/N 0350740068, in Universal Oil Products galley P/N 10870, to Weber Aircraft Company beverage cart, P/N 818620-411. Issued 1/6/75.	WE	48550	H. Koch & Sons 5410 E. LaPalma Anaheim, CA 92807
707-347C; T.C. 4A26	SA3601WE	Installation of a single Collins INS 61B inertial navigation system. Issued 3/10/78.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C; T.C. 4A26	SA3792WE	Installation of Litton LTN-211 omega navigation system. Amended 8/31/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
707-347C, -351C, 720-047B; T.C. 4A26, 4A28	SA808EA	Installation of inflight motion picture system. Amended 3/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-349C; T.C. 4A26	SA1596WE	Installation of Brownline Pallet 23997-51 and Net 22758-51 combination. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
707-349C; T.C. 4A26	SA1624WE	Installation of Decca Omni trac, Decca Doppler and Decca Loran. Amended 5/10/68.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
707-349C; T.C. 4A26	SA1650WE	Modification of co-pilot's C-11 compass system to a C-11B system by addition of remote compensator.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
707-351B/C; T.C. 4A26	SA87GL	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
707-351B; T.C. 4A26	SA1168EA	Installation of dual solar T-62T-40C2 gas turbine auxiliary power units, for ground use only. Amended 11/8/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
707-351C, 727-51C, -25C; T.C. 4A26, A3WE	SA1888WE	Installation of pallet assembly AC-10359-1 used in conjunction with net assembly AC-10373-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
707-351C; T.C. 4A26	SA2526WE	Installation of Satco Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with assemblies conforming to NAS 3610-1A2N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
707-351C; T.C. 4A26	SA2528WE	Installation of Satco, Inc. cargo pallet assemblies P/N 31095-501, -503, -505, -507 when used in conjunction with net assemblies conforming to NAS 3610-1A3N, 2A1N, 2A2N, 2A3N, 2A5N, and 2A6N. Issued 5/18/72.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
707-351C; T.C. 4A26	SA2773WE	Installation of Tridair Industries 3G net assembly. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
707-351C, -384C; T.C. 4A26	SA855CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-353B; T.C. 4A26	SA83NW	Relocation of autopilot accelerometer and rate gyros. Issued 1/16/74.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
707-353B; T.C. 4A26	SA1596SW	Steel duct installation for APU according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
707-353B; T.C. 4A26	SA1927WE	Installation of dual Litton inertial navigation systems.	WE	51500	Litton Systems, Inc. 5500 Canoga Park Woodland Hills, CA 91364
707-355C; T.C. 4A26	ST6548O	Installation of liquor service galley.	SO	05356	Aircraft Interior FAbricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
707-359B; T.C. 4A26	SA2863WE	Passenger audio entertainment system installation. Issued 3/29/74.	WE	33223	Electronic Engineering Company of California 1441 E. Chestnut Avenue Santa Ana, CA 92701
707-365C, -372C, 727-172C; T.C. 4A26, A3WE	SA1795WE	Installation of Heath Tecna AC-015201 structural container. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
707-369C; T.C. 4A26	SA1234CE-D	Passenger cabin contemporary interior installation. Issued 1/24/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-372C and 707-365C; T.C. 4A26	SA1674WE	Installation of Heath Tecna Corporation AC-10160 pallet with AC-10069 net. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastic Division 19819 - 84th Avenue South Kent, WA 98031
707-373C; T.C. 4A26	SA426CE	Modify SCAT system circuit. Amended 9/9/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
707-373C; T.C. 4A26	SA714CE	Installation of dual Bendix ALA-51 radio altimeter provisions and equipment.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
707-373C; T.C. 4A26	SA2843WE	Modification by installation of horse stalls P/N 690069 on NAS 3610-2A4P pallet. Issued 3/15/74.	WE	87900	W.W. Industries, Inc. 12450 Inglewood Avenue Hawthorne, CA 90250
707-384B; T.C. 4A26	SA853CE-D	Passenger cabin interior seating arrangement. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-384B, 707-384C; T.C. 4A26	SA576CE	Installation of multi-channel audio entertainment system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-384B, 707-384C; T.C. 4A26	SA546CE	Installation of doppler autopilot tie-in Bendix DRA-12 doppler radar with CPA-24 computer to Bendix PB-20 autopilot. Amended 12/27/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
707-386C; T.C. 4A26	SA2808WE	Installation of dual Litton LTN-72 inertial navigation system. Issued 2/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Road Woodland Hills, CA 91364
707-387B; T.C. 4A26	SA1232CE-D	Installation of large cargo door in left hand side of forward fuselage. Issued 6/10/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-387B; T.C. 4A26	SA1233CE-D	Increase maximum zero fuel weight to 96,162 KG Issued 8/31/77.	CE	16878	The Boeing Company 3801 S. Oliver Wichita, KS 67210
707-387B; T.C. 4A26	SA1236CE-D	Installation of auxiliary power unit. Issued 9/26/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
707-399C; T.C. 4A26	SA850CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aereos Portugeses. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
707-400, 720 Series; T.C. 4A26, 4A28	ST912SO	Installation of cargo barrier net. Amended 9/13/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
720 Series; T.C. 4A28	SA88NW	Optional interior seating arrangement. Issued 1/14/74.	NW	10174	American Aviation Services 777 Perimeter Road Boeing Field Seattle, WA 98108
720 Series; T.C. 4A28	SA95CE	Crimsco 600301 jet cargo containers in forward cabin.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
720 Series; T.C. 4A28	SA148SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA180NW	Installation for 149 passenger configuration. Issued 5/7/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720 Series; T.C. 4A28	SA182SO	Interior modifications.	SO	31429	Eastern Air Lines, Inc. International Airport Miami, FL 33148
720 Series; T.C. 4A28	SA302EA	Inflight motion picture system. Amended 6/9/67.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA369EA	Litton low range altimeter system.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430
720 Series; T.C. 4A28	SA371CE	Wheel 152051-4 and brake assembly 260997-1.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46620
720 Series; T.C. 4A28	SA380EA	ARINC 557 Fairchild A100 cockpit voice recorder.	EA	62300	Pan American World Airways JFK Int'l Airport Jamaica, NY 11430

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
720 Series; T.C. 4A28	SA458WE	Crimsco jet cargo container 04-005--01, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720 Series; T.C. 4A28	SA460CE	Wheel assembly 152051-5 and brake assembly 2600997-3.	GL	15500	The Bendix Corporation Aerospace Division 401 N. Bendix Drive South Bend, IN 46600
720 Series; T.C. 4A28	SA468EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
720 Series; T.C. 4A28	SA773WE	Closed circuit television entertainment system.	WE	25970	Continental Air Lines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
720 Series; T.C. 4A28	ST806SO	Installation of a cargo floor, smoke detector system and cargo restraint bulkhead. Amended 12/12/78.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
720 Series; T.C. 4A28	SA848CE-D	Additional overwing escape hatch installation interior configuration 2nd additional overwing escape hatch installation. Issued July 1975.	CE	16876	The Boeing Company 3801 South Oliver Wichita, KS 67210
720 Series; T.C. 4A28	SA1222WE	Boeing improved type engine thrust reverser forward pressure seal.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128
720 Series; T.C. 4A28	SA1245WE	Either single or dual Collins AL-101 radio altimeter system.	WE	80500	United Air Lines, Inc. Maintenance Base - Int'l Airport San Francisco, CA 94128
720, 720B; T.C. 4A28	SA177NW	Installation of container rack and six accompanying containers on forward right-hand coat closet. Reissued 5/29/75.	NW	01700	AeroAmerica, Inc. 7227 Perimeter Road Seattle, WA 98108
720, 720B; T.C. 4A28	ST564SO	Installation of HF antenna and associated hardware and structural provisions for mounting HF tuning unit. Issued 11/19/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
720, 720B; T.C. 4A28	ST662SO	Installation of nose cap "C/X" band weather radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
720, 720B; T.C. 4A28	ST931SO	Addition of smoke detector system for conversion to cargo carrier. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	ST932SO	Mechanical landing gear position indicator. Issued 5/20/77.	SO	56838	MCA Leasing Corporation P.O. Box 480531, MIAD Miami, FL 33148
720, 720B; T.C. 4A28	SA3332WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
720B; T.C. 4A28	SA328NW	Installation of Fairchild weight and balance system (STAN). Issued 7/28/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
720B; T.C. 4A28	SA2806SW	Stewart-Davis, Inc. auxiliary power unit. Issued 6/30/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
720-22; T.C. 4A28	SA112NW	Installation of cabin interior arrangement. Issued 5/16/74.	NW	08480	Alaska Airlines, Inc. Seattle/Tacoma Int'l Airport Seattle, WA 98155
720-22; T.C. 4A28	SA278EA	See Document No. Report No. 3187, dated 4/18/67, Rev. 1/30/69, concerning Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
720-022; T.C. 4A28	SA1553WE	Installation of Fairchild P/N 13920-301 or 15630-601 Flight Data Recorder and Honeywell P/N 180 VI Central Data Computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
720-022; T.C. 4A28	SA2095WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2206WE	Installation of Bendix third attitude indicator. Issued 7/20/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
720-022; T.C. 4A28	SA2744WE-D	Alternate 143 passenger seating configuration. Issued 3/28/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2746WE-D	Alternate 149 passenger seating configuration. Issued 5/3/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2834WE-D	Alternate 101 passenger seating configuration. Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2831WE-D	Couple EDO Loran system to ADF sense antenna instead of fin cap (no fin cap on UAL B720). Issued 3/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022; T.C. 4A28	SA2833WE-D	Installation of two HF communications systems. Issued 3/27/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
720-022, -023, -025, -027, -048, -062, 720B-023B, -024B, -030B, -040B, -047B, -051B, -058B, -059B, -060B, -068B; T.C. 4A28	SA460CE	Replace main wheel and brake assemblies with Bendix wheel assembly P/N 152051-5 or P/N 152051-4 and Bendix brake assembly P/N 2600997-3. Reissued 5/1/79.	GL	15500	The Bendix Corporation Aircraft Brake & Strut Division 3520 West Westmoor Street P.O. Box 10 South Bend, IN 46624
720-022 and 727-22; T.C. 4A28 and A3WE	SA1396WE	Installation of McMillan Radome P/N 2406 as a replacement for Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
720B-023; T.C. 4A28	SA412EA-D	Relocate the L.A.S.I. flight data recorder to the aft fuselage area at Station 1452 utilizing remote vertical accelerometer in left wheel well. Install new auxiliary pitot tube and static ports for the flight recorder.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
720-023B; T.C. 4A28	SA985CE-D	Side cargo door and interior installation. Issued 3/17/77.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-023B, -030B; T.C. 4A28	ST657SO	Installation of Mace Galley Model No. 101 in aft passenger compartment and Mace Galley Model No. 102 in forward passenger compartment.	SO	67030	Mace Unit of REF Dynamics, UOP 4856 Victor Street Jacksonville, FL 32207
720-023B, -030B, 720-047B; T.C. 4A28	SA851CE-D	Increase maximum ramp weight to 235,000 lbs. and zero fuel weight to 156,000 lbs. Amended 11/21/78.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
720-024B; T.C. 4A28	SA1617WE	Rewiring of galley electrical power supply.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA1767WE	Installation of Galley Models CAG-10, -20, 30 and -40 manufactured by Dale Engineering & Development, Inc. Amended 10/10/68.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-024B; T.C. 4A28	SA2599WE	Installation of Bell & Howell movie system. Issued 9/29/72.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
720-025; T.C. 4A28	SA251GL	Installation of Canadian Marconi Model CMA-740 Omega/VLF navigation system. Amended 12/29/78.	GL	10340	American Trans-Air 2600 South High School Road Indianapolis, IN 46241
720-025; T.C. 4A28	ST668SO	Installation of International Inflatables Co. door-mounted inflatable evacuation slide, P/N 68040, and International Inflatables Co. door-mounted slide container, P/N 00800.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
720-027; T.C. 4A28	SA82NW	Installation of navigator's station. Issued 12/11/73.	NW	10174	American Aviation Services, Inc. 7777 Perimeter Road Boeing Field Seattle, WA 98108
720-047B; T.C. 4A28	SA194NW	Installation of new look interior arrangement. Issued 6/30/75.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
720-051B; T.C. 4A28	SA801CE	Install Mark II (Hytrol) anti-skid system. Issued December 1971.	CE	16878	The Boeing Company Wichita Division 3801 S. Oliver Wichita, KS 67210
727 Series; T.C. A3WE	SA103SO	Collins 54W-1 comparator warning system. Amended 8/10/66.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA121GL	Installation of bleed-air valve actuator, P/N G66, to replace Boeing P/N 10-60817, in various locations in anti-ice system. Issued 11/3/76.	GL	60350	MPC Products Corporation 4200 West Victoria Avenue Chicago, IL 60646
727 Series; T.C. A3WE	SA140SO	Manufacture and install coatroom and magazine rack.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24 Avenue Miami, FL 33148
727 Series; T.C. A3WE	SA159SO	Aircraft integrated data systems (AIDS).	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA161SO	Dual radio altimeter system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA183SO	Crimsco cargo containers 6003 in main cabin. Amended 12/15/66.	SO	62300	Pan American World Airways, Inc. P.O. Box 2096 Miami, FL 33159
727 Series; T.C. A3WE	SA339CE	Fairchild cockpit voice recorder system. Amended 3/15/66.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727 Series; T.C. A3WE	SA354CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727 Series; T.C. A3WE	SA372CE	Auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727 Series; T.C. A3WE	SA425EA-D	Install standby horizon system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA427CE	Flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64108
727 Series; T.C. A3WE	SA438CE	United Data Control 557 cockpit voice recorder provisions.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727 Series; T.C. A3WE	SA447EA	Vector analog computer system.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727 Series; T.C. A3WE	SA469EA	Fabric cargo bins in passenger compartments. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA490NW	Installation of PRIMUS-90 weather radar with standard black and white and also with color display.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188
727 Series; T.C. A3WE	SA535EA	Fabrication and installation of Marino Flex-Net P/N LM365. Reissued 6/7/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
727 Series; T.C. A3WE	SA604SO	Dual Collins FD-109 integrated flight system.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727 Series; T.C. A3WE	SA625SO	Installation of main landing gear wheel assembly, P/N 3-1287 and brake assembly P/N 2-1147 or 2-1147-1, 2-1190.	GL	38504	B.F. Goodrich Engineered Systems Company Box 340 Troy, OH 45373

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727 Series; T.C. A3WE	ST664SO	Modify door-mounted evacuation slide container, Boeing P/N 65-26998-1, from a two-point closure to a positive single-point closure. Amended 3/30/70.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
727 Series; T.C. A3WE	SA699WE	Crimsco jet cargo container 04-005-01-1, including jet cargo container seat track latch assembly 04-005-03 in main passenger compartment.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60660
727 Series; T.C. A3WE	SA1093WE	Power source for Captain's CDI select relay switch relocated.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1105WE	Dual Collins AL-101 radio altimeter systems.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727; T.C. A3WE	SA1128EA	Installation of coat closet. Amended 9/11/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
727 Series; T.C. A3WE	SA1154WE	Cockpit voice recorder.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1265WE	Brownline pallet 23118 or Douglas pallet 5776662-505 with Brownline net 23143.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727 Series; T.C. A3WE	SA1322WE	Engine mounted fire detector unit modified to provide continuous support. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety System Division 1440 Fourth Street Berkeley, CA 94710
727 Series; T.C. A3WE	SA1367WE	Use of Brownline Corp. Pallet Nos. 23640-51 and 23224-51 in place of Douglas Aircraft Co. Pallet No. 577662-505.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1451WE	Installation of constant speed drive, load controller, generator and voltage regulator.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727 Series; T.C. A3WE	SA1509WE	Revised interior arrangement.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727 Series; T.C. A3WE	SA1563WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727 Series; T.C. A3WE	SA1868SW	Portable solid oxygen system for first-aid use. Issued 4/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
727 Series; T.C. A3WE	SA2422WE	Installation of Valley Todeco bolt VAL 22016 to replace Boeing bolt BAC B30EK8-48 on 727 thrust reverser. Issued 9/23/71.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727, 727C; T.C. 2H3	SA800CE	Installation of three cell forward and three cell aft auxiliary fuel tanks in lower cargo compartment. Issued June 1972.	CE	16878	The Boeing Company 3801 South Oliver Street Wichita, KS 67210
727, 727-100, -22; T.C. A3WE	SA2563WE	Installation of garment bag module. Issued 8/23/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	SA169GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-3, with Courter flap asymetry detector kit, P/N 298-1026-01 or -02. Reissued 12/21/78.	GL	26675	Courter, Inc. 375 North Lake Street Boyne City, MI 49712
727, 727-100, 727C, 727-100C, -200; T.C. A3WE	ST6508SO	Installation of dual band (C/X) type weather radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
727, 727C, 727-200 Series; T.C. A3WE	SA1239CE-D	Grimes coffee maker and warmer unit installation. Issued 11/20/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727, 727-100, 727C, 727-200; T.C. A3WE	SA2668WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-50 autopilot as replacement for Sperry or Smiths rate gyros. Amended 6/20/73.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3130WE	Installation of dual Litton LTN-72 or a single or dual LTN-72R INS/RNAV navigation system. Amended 5/18/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3145WE	Installation of Sperry Model Block V SP-50 autopilot and Honeywell Air Data computer. Issued 3/12/76.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3153WE	Installation of forward coat closet on left hand side just aft of forward entry door. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727 Series, 727C, 727-100, 727-100C; T.C. A3WE	SA3154WE	Installation of interior configuration consisting of 10 first class and 98 coach seats. Amended 9/16/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3654WE	Installation of interior configuration with 10 first class and 95 coach seats. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C Series T.C. A3WE	SA3665WE	Installation of a dual Collins 61B inertial navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, 727-100C Series; T.C. A3WE	SA3679WE	Installation of a Global GNS-500A VLF/Omega navigation system. Issued 7/11/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, 727-100C, 727-200; T.C. A3WE	SA3717WE	Installation of a cabin divider. Issued 8/29/78.	WE	25970	Continental Air Lines International Airport Los Angeles, CA 90009
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3755WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-211 omega navigation system and a true airspeed system. Amended 3/23/79.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, 727-100C; T.C. A3WE	SA3964WE	Installation of dual Litton LTN-211 omega navigation systems. Issued 5/23/79.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
727, 727C, 727-100, -200; T.C. A3WE	SA4161WE	Installation of Teledyne angle of attach system. Issued 7/7/80.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727, 727C, 727-100, -100C Series; 727-223, -225, -227, -228, -231, -235, -251, -264, -284, -295; T.C. A3WE	SA3220WE	Addition of filter to the cabin pressure limit control feature of P/N 103280 outflow valve. Issued 6/24/76.	WE	07505	AiResearch Manufacturing Company Garrett Corporation 2525 West 190th Street Torrance, CA 90509
727, 727C, 727-100, -100C, 727-200; T.C. A3WE	SA2348WE	Modify Boeing 727 Series airplanes by installation of emblem lights. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
727, 727C, 727-200, 737; T.C. A3WE	SA3292WE	Installation of thrust reverser short track. Issued 11/23/76.	WE	78475	Thrustair, Inc. 12990 Branford Avenue Arleta, CA 91331
727, 727C, 727-200, 737; T.C. A3WE	SA3306WE	Installation of thrust reverser cascades. Issued 12/3/76.	WE	41015	Hasko-Air, Inc. 9042 Owensmouth Avenue Canoga Park, CA 91304
727, 727-100, 727C, 727-100C, 727-200 Series; T.C. A3WE	SA3521WE	Installation of a cabin divider. Issued 11/8/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727, 727C, 727-200; T.C. A3WE	ST436SO	Installation of thrust reverser deflector door drive. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727, 727C, 727-200; T.C. A3WE	ST450SO	Modification of thrust reverser forward deflector door link. Amended 1/9/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-1H2; T.C. A3WE	SA2480WE	Addition of INS attitude reference data to flight instruments. Issued 2/15/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-1H2; T.C. A3WE	SA2552WE	Install Litton P/N 451150 automatic data entry unit. Issued 8/17/72.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-2B7; T.C. A3WE	SA2168WE	Installation of Henry Engineering lounge tables No. 17701 and No. A17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727-2B7; T.C. A3WE	SA2170WE	Installation of class divider. Issued 5/27/70.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-2J0; T.C. A3WE	SA1235CE-D	Forward auxiliary fuel tank removal and reinstallation. Issued 10/9/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-2M7; T.C. A3WE	SA3505WE	Installation of ground proximity warning system. Issued 10/27/77.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3564WE	Installation of auxiliary fuel tanks in the forward and aft belly cargo/baggage compartments. Issued 1/20/78.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3380WE	Installation of dual LTN-51, or dual LTN-72, or dual LTN-72R, or one LTN-51 and either one LTN-72 or one LTN-72R inertial navigation system. Amended 4/29/80.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2M7; T.C. A3WE	SA3967WE	Installation of coat room assembly No. RW2527036. Issued 5/29/79.	WE	43340	Hughes Airwest, Inc. P.O. Box 2966 Phoenix, AZ 85036
727-2L4; T.C. A3WE	SA3065WE	Installation of 3400 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 7/16/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-14; T.C. A3WE	SA1942WE	Revised interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14; T.C. A3WE	SA1986WE	Interior arrangement.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -35, -193, -214, -235; T.C. A3WE	SA1885WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727-14, -51; T.C. A3WE	SA1717WE	Revised interior arrangement. Amended 4/20/77.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
727-14, -51, -214, -254, -2J7, -2Q8; T.C. A3WE	SA3013WE	Installation of ground proximity warning system. Amended 12/19/78.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-14, -51, -214, -254, -2Q8; T.C. A3WE	SA3939WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/11/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-17; T.C. A3WE	SA3674WE	Installation of 2700 gallon auxiliary fuel tanks in forward and aft cargo compartments. Issued 6/30/78.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-17, -31, -31C, -180C, -231, -231A; T.C. A3WE	SA1488CE	Installation of a pitot heater failure indication system. Issued 5/4/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-21; T.C. A3WE	SA264NW	Interior arrangement. Issued 2/20/76.	NW	08480	Alaska Airlines Seattle-Tacoma Int'l Airport Seattle, WA 98188

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-21; T.C. A3WE	SA1078EA-D	Installation of two closets in rear of cabin to accommodate a bar or food cart and provisions for parking the carts in flight at two locations. Amended 11/8/79.	EA	62300	Pan American World Airways JFK International Airport Jamaica, NY 11430
727-21, 21C; T.C. A3WE	SA6128O-D	Installation of portable berth (aerotherm stretcher). Reissued 9/6/78.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
727-21, -22, -81; T.C. A3WE	SA2660WE	Modification of cabin interior. Amended 12/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-21, -81; T.C. A3WE	SA3022WE-D	Installation of new seating arrangement. Amended 11/10/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-21C; T.C. A3WE	SA1292WE	Installation of Boeing palletized cargo system 65-49102 with Brownline pallet 22630-51 or 26100-52 Brownline net assembly 23225-51, 23226-51 or 22758-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-21C; T.C. A3WE	SA1594WE	Installation of Heath Tecna Corp. pallet AC-10065 and Brownline Corp. net 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-21C; T.C. A3WE	SA3006WE	Installation of cargo pallet assembly, P/N 31250-521. Issued 4/9/75.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-21C; T.C. A3WE	SA3672WE	Installation of Brownline quick change pallets, P/N's 45881-101, 45882-101 and 46129-101. Issued 6/19/78.	WE	17740	Brooks & Perkins Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-21C, -22C, -25C, -27C, -30C, -31C; T.C. A3WE	SA696CE	Installation Aeroquip Corp. cargo tie-down net.	GL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203
727-22; T.C. A3WE	SA1788WE	Interior arrangement installation.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94125
727-22; T.C. A3WE	SA3323WE	Installation of forward facing flight attendant seat on forward galley. Issued 1/20/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-22; T.C. A3WE	SA3364WE-D	Revise cabin seating to accommodate 118 all-coach configuration. Issued 4/25/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C; T.C. A3WE	SA3023WE-D	Revise seating arrangement from 18 first class/78 coach to 12 first class/86 coach configuration and further revised to 10 first class/86 coach configuration. Amended 6/11/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-22, 727-22QC; T.C. A3WE	SA1687WE	Modify existing Collins Radio Company type FD-109 Flight Director installation to add "Steering", "Airspeed-Hold", and "Auto Approach" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3079WE	Installations of Collins FPC-75- P/N 622-2615-012 or P/N 622-2615-212, or P/N 622-2615-013, ground proximity warning system computer in airplanes. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22, -22C, -222; T.C. A3WE	SA3350WE-D	Air data system. Amended 7/20/79.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-22, -24C, -30, -76, -92C; T.C. A3WE	SA3655WE	Installation of Nordskog Company auxiliary galley Model 1-420. Issued 5/26/78.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
727-22, -24C, -30, -76, -92C, -224; T.C. A3WE	SA4157WE	Installation of Fairchild beverage cart, Model 79067000. Issued 6/6/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-22, -30, -76, 92C; T.C. A3WE	SA981CE-D	Reconfiguration of flight crew instrument panels, avionics and passenger cabin. Amended 8/28/78.	CE	16877	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-22C; T.C. A3WE	SA645CE	Make and install pallets in accordance with Brooks & Perkins Drawing Index No. 16987DL-E and Installation Instructions No. BPS 149. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA814CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA842CE	Installation of cargo pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
727-22C; T.C. A3WE	SA1622WE	Modification of type design to permit installation of Heath Tecna Corp. AC-10061 pallet with AC-10069 net.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-22C; T.C. A3WE	SA1816WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-22C; T.C. A3WE	SA1962WE	Modify by installation of pallet assemblies 40160101 thru 40160108 used in conjunction with net assemblies 22672-51, -52; 23143-51, 22758-51, -52; 22273-51, 7776967-1 (Douglas) and 3950020 (Aeroquip). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1, or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
727-22C; T.C. A3WE	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517, with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks & Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-22C; T.C. A3WE	SA2255WE	Installation of Satco, Inc., pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-22C; T.C. A3WE	SA2274WE	Installation of Irvin 88" x 125" cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
727-22C; T.C. A3WE	SA2844WE	Installation of coat and luggage stowage unit. Issued 2/25/74.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
727-22C; T.C. A3WE	SA3359WE-D	Retrofit of Kollsman P/N A41869-10-021 altimeters on the captain's and first officer's instrument panel. Issued 1/11/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3577WE-D	Installs overhead stowage bin kit. Issued 8/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-22C; T.C. A3WE	SA3673WE	Installation of cargo restraint system which meets the requirements of a NAS 3610 class IIA restraint system. Issued 6/21/78.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-22C; T.C. A3WE	SA3775WE	Installation of the Brownline 46000-101 cargo system. Issued 10/31/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
727-22C, -24C, -25C, -116C; T.C. A3WE	SA4098WE	Installation of cargo system, P/N 47270-101. Issued 3/10/80.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
727-022; T.C. A3WE	SA2838WE-D	Installs barrier and tie-down fitting for using preloaded liquor service cart on-board aircraft. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-022; T.C. A3WE	SA3575WE-D	Remove all first class seats, the class divider, the carry-on baggage and garment bag modules and replace with all coach seats to increase seating capacity to 112 passengers. Issued 4/24/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-022;	SA3363WE-D	Installation of dual Collins FD-109A flight director systems. Issued 4/24/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-022, -022C, -222; T.C. A3WE	SA2201WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
727-22, -222, -22QC; T.C. A3WE	SA2096WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-23; T.C. A3WE	SA411EA-D	Relocate the flight data recorder Station 1120 on cabin floor, left hand side, aft of last row of seats to provide improved crash survivability. Amended 12/8/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23; T.C. A3WE	SA563EA	Installation of digital adaptive recording system (DARS) on one Boeing 727-23. Issued 4/7/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA501EA-D	Delete auxiliary vertical gyro on 727-23 and 727-123 and authorize use of either Sperry or Bendix gyros on 727-35 and 727-95. Amended 9/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95, 727-123; T.C. A3WE	SA515EA-D	Install REF Dynamics beverage bar. Amended 2/16/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA523EA-D	Install overwing emergency lights. Amended 1/12/69.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA524EA-D	Change interior passenger seating arrangement.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
727-23, -35, -95, -123; T.C. A3WE	SA558EA-D	Modification of leading edge slat and flap position indication system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-35, 727-95 and 727-123; T.C. A3WE	SA866WE	Installation of ILS Back Course and Compass Switches. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA872WE	Installation of Collins P/N 54W-1 instrument comparator. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1195WE	Installation of dual Collins FS-108 flight director systems. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, -35, -95, -123; T.C. A3WE	SA1575WE	Installation of dual Collins AL-101 radio altimeter system. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-23, 727-95, 727-123; T.C. A3WE	SA804WE	Installation of Honeywell HG180 Modular Air Data Computer System. Amended 6/26/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-23, -223; T.C. A3WE	SA552EA-D	Installation of autopilot go-around unit. Issued 4/24/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-24C, 727-116C; T.C. A3WE	SA1441CE-D	Change crew instrument panels and systems revisions. Reissued 9/19/79.	CE	16877	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-24C; T.C. A3WE	SA1661WE	Installation of Bendix Dual DRA 12 Doppler System.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2886WE	Interior arrangement. Issued 5/18/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2899WE	Installation of courier seat. Issued 6/15/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, 727-92C; T.C. A3WE	SA2942WE	Installation of Nordskog Galleys 1-289A and 1-290A. Amended 11/14/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
727-24C, -92C; T.C. A3WE	SA3855WE	Installation of Brownline cargo/seat pallet system 45980, configuration -101. Issued 2/12/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
727-25; T.C. A3WE	ST588SO	Installation of 119 passenger interior and installation of two EAL 52-RA-7 four man life rafts. Issued 4/30/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST663SO	Installation of LORAN A navigation system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25; T.C. A3WE	ST740SO	Cabin interior arrangement and furnishings changes. Issued 6/3/74.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST426SO	Installation of Honeywell HG180V3 air data computer with electronic altimeters, altitude reporting digitizer and altitude alerting system.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST741SO	Cabin interior configuration changes. Amended 1/24/75.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C; T.C. A3WE	ST751SO	Modification of main cabin passenger interior configuration from 14 first class and 89 tourist class to 12 first class and 95 tourist class accommodations. Issued 5/28/76.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, -25C; T.C. A3WE	ST954SO	Installation of Mansfield Aircraft Products model 1470 galley/coatroom. Issued 8/29/77.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25, 25C, -225; T.C. A3WE	ST510SO	Installation of dual HF communications system using vertical fin leading edge slotted antenna. Amended 1/13/78.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	ST534SO	Interior - two pallet cargo/65 passenger MAC configuration installed. Issued 4/13/73.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-25C; T.C. A3WE	SA2364WE	Installation of Satco, Inc. cargo pallet assembly P/N 31095-501, -503, -505, -507 in conjunction with net assemblies NAS 3610-2A1N, -2A2N, -2A3N, -2A5N, and -2A6N. Amended 5/18/72.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
727-30; T.C. A3WE	SA982CE-D	Interior arrangement installation. Amended June 1976.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-30; T.C. A3WE	SA3157WE	Installation of 1200 gallon auxiliary fuel tank in forward cargo compartment. Issued 3/26/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-30 T.C. A3WE	SA3319WE	Installation of auxiliary fuselage fuel tanks (1600 gallons) in forward and aft cargo compartment. Issued 12/28/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91406
727-30, -81; T.C. A3WE	SA2734WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 2/13/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-030, -224; T.C. A3WE	SA3408WE	Installation of Lermer Apparatebau GMBH beverage cart No. L15701. Issued 5/26/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 91406
727-31; T.C. A3WE	SA478CE	Modification to flap quadrant.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727-31; T.C. A3WE	SA570CE	Install Models 14801 or 14802 Henry Engineering Company bar unit. Amended 10/18/68.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727-31, -31C; T.C. A3WE	SA373CE	Installation of a single SCAT system. Amended 8/12/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
727-31, 727-31C; T.C. A3WE	SA604CE	Installation of dual radio altimeter provision - single equipment driving dual indicators. Amended 2/3/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-31, -31C, -180C; T.C. A3WE	SA235CE	Installation of Kollsman Integrated Flight Instrument System (KIFIS). Amended 5/8/69.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727-31, -31C, -180C; T.C. A3WE	SA734CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
727-31, -31C, -180C; T.C. A3WE	SA779CE	Installation of Bendix gyro horizon and inverter. Issued June 1971.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA553CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA828CE	Install Butler National Corp. flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
727-31, 727-31C, 727-180, 727-231; T.C. A3WE	SA1137CE	Installation of hydraulic interconnect override system. Issued June 1975.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-31, 727-31C, 727-180C, 727-231; T.C. A3WE	SA1542CE	Installation of a Growth Industries dual cavity oven. Issued 12/12/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MC 64195
727-31, -31C, -231; T.C. A3WE	SA490CE	Installation of Safe Flight Corp. auto power servo kits. Amended 10/9/74.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
727-31C, -180C; T.C. A3WE	SA741CE	Install Henry Engineering auxiliary bar model 15501A and one additional triple passenger seat.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
727-35; T.C. A3WE	SA639SO	Installation of hatrack assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA640SO	Installation of liquor service galley assembly.	SO	05356	Aircraft Interior Fabricators 2180 N.W. 24 Avenue Miami, FL 33142
727-35; T.C. A3WE	SA1566WE	Installation of Sperry SP-50 Mod Block IV Single Channel Autopilot. Amended 5/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
727-35, 727-95, 727-123; T.C. A3WE	SA1576WE	Replacement of Captain's altimeter and First Officer's altimeter and and installation of third altimeter. Amended 4/8/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-35, -235; T.C. A3WE	ST738SO	Installation of Gulton Model EMBS 144 nickel-cadmium electrical storage battery and integral automatic control system. Issued 1/23/74.	EA	61220	National Airlines, Inc. P.O. Box 2055 Miami International Airport Jamaica, NY 11430
727-46; T.C. A3WE	SA847CE-D	Structural and system modification for installation of service door and retractable step. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-46; T.C. A3WE	SA2970WE	Installation of 300 gallon auxiliary fuel tank in aft cargo compartment. Issued 12/20/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
727-51, -51C, -151C, -251; T.C. A3WE	SA89GL	Installation of Bendix GPW-83 ground proximity warning system. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
727-75, -232, -295; T.C. A3WE	ST855SO	Installation of Bendix ground proximity warning system. Issued 10/16/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-76; T.C. A3WE	SA4164WE	Installation of dual Delco carousel IVA inertial navigation system. Issued 6/27/80.	WE	07500	AiResearch Aviation Company 6201 WEst Imperial Highway Los Angeles, CA 90045
727-77; T.C. A3WE	SA3559WE	Installation of a 1932-gallon auxiliary fuel tank system in forward and aft cargo compartments. Issued 2/6/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-81; T.C. A3WE	SA2724WE	Installation of executive cabin interior. Amended 9/20/74.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
727-81, -100; T.C. A3WE	SA263NW	Garment bag module modification. Issued 2/25/76.	NW	47722	Kelley-Morrow Enterprises The Common Building 1200 - 112th N.E. Bellevue, WA 98004
727-81, -100; T.C. A3WE	SA2732WE	Installation of duel LTN-104 navigation systems. Amended 3/13/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-90, -90C; T.C. A3WE	SA2245WE	Interior arrangements. Issued 9/18/70.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98158
727-90C; T.C. A3WE	SA139NW	Installation of quick change interior arrangement. Amended 4/21/75.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98108
727-90C; T.C. A3WE	SA327NW	Interior arrangements 98 PAX and two cargo pallet/63. Issued 7/23/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA129NW	Installation of cabin interior arrangement. Issued 9/23/74.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, -155C; T.C. A3WE	SA310NW	Interior arrangement. Issued 5/28/76.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
727-90C, 737-202C, -210C; T.C. A3WE, A16WE	SA1823WE	Installation of "Heathair" AC-10360 cargo pallet assembly and AC-10374 cargo net assembly. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-92C; T.C. A3WE	SA1839WE	Stewardess seat installed on Nordskog 769 galley.	WE	61605	Nordskog Co., Inc. 16000 Strathern Street Van Nuys, CA 91406
727-95; T.C. A3WE	SA704EA	Installation of Henry Engineering Company Galleys Models Nos. 14001 and 14002. Reissued 12/8/72.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
727-100 Series Models type certificated as of 6/17/68; T.C. A3WE	SA587CE	Installation of Hoskins Twilighter Mark V high intensity light system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
727-100; T.C. A3WE	SA612NW	Installation of coat closet. Issued 5/26/78.	NW	48532	KME Manufacturing, Inc. The Commons Building 1200 112th Street, N.E. Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-100; T.C. A3WE	SA643NW	Installation of six carry-on baggage modules. Issued 9/13/78.	NW	78672	Tramco, Inc. 1033 Thomas Avenue, S.W. Renton, WA 98055
727-100; T.C. A3WE	SA697NW	Install life raft stowage compartments. Issued 12/14/78.	NW	41625	Heath Tecna 19819 84th Avenue South Kent, WA 98031
727-100; T.C. A3WE	SA1130SO	Installation of an aft galley storage module. Issued 1/22/80.	SO	64500	Piedmont Airlines Smith-Reynolds Airport Winston-Salem, NC 27102
727-100; T.C. A3WE	SA1205EA	Installation of on board folding stairs. Issued 9/10/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
727-100; T.C. A3WE	SA1206EA	Installation of humidifier system. Issued 9/10/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
727-100; T.C. A3WE	SA2498SW	Collins FPC-75 ground proximity warning system. Issued 1/23/78.	SW	29000	The Dee Howard Company P.O. Box 17300 San Antonio, TX 78217
727-100 Series; T.C. A3WE	SA3501WE	Installation of Litton LTN-201 omega navigation system. Amended 12/29/77.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100 Series; T.C. A3WE	SA3810WE	Installation of a maximum of eight auxiliary fuel tanks in forward and aft cargo compartments. Amended 1/4/80.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
727-100 Series; T.C. A3WE	SA3851WE	Installation of Litton LTN-211 Omega Navigation System. Amended 4/19/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100, -100B, -200; T.C. 4A21	ST660SO	Installation of "C/X" band nose radome AD4100CX-2-1. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
727-100, -100C Series; T.C. A3WE	SA3661WE	Installation of a single Litton LTN-51 inertial navigation system, a single Litton LTN-201 Omega navigation system and a true airspeed system. Issued 10/11/78.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
727-100, -200; T.C. A3WE	SA1050CE	Install Crimsco cargo container, P/N 600301. Issued November 1974.	CE	27000	Crimsco, Inc. 5001 E. 59th Street Kansas City, MC 64130
727-100, -200; T.C. A3WE	SA2240WE	Installation of door-mounted emergency light. Amended 9/23/70.	WE	44266	International Inflatables Company Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
727-100, -200; T.C. A3WE	SA3333WE	Installation of stretcher carrier AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
727-100, -200; T.C. A3WE	SA3374WE	Installation of bearing P/N VTB02220 as replacement for Boeing P/N 10-60545-113S in main landing gear lock system assembly. Issued 3/29/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200; T.C. A3WE	SA3379WE	Installation of bearing, P/N VTB02800 in lieu of Boeing bearing P/N 10-60545-143. Issued 4/20/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, -200 Series; T.C. A3WE	SA3508WE	Installation of Valley-Todeco bearings, P/Ns VTB-02900, VTB-02910, VTB-02920, VTB-02930. Issued 11/8/77.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342
727-100, 727-200; T.C. A3WE	SA3716WE	Installation of a Dretloh Model 5002, P/N 121214-1 food carrier. Issued 8/25/78.	WE	30702	Dretloh Aircraft Supply, Inc. 980 North Lemon Orange, CA 92667
727-100, -200; T.C. A3WE	SA4133WE	Installation of an ARINC communications addressing and reporting system (ACARS). Issued 4/24/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
727-100, 100QC; 737; T.C. A3WE, A16WE	SA6NW	Installation of visual approach monitor. Issued 3/12/73.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-171C, 727-173C; T.C. A3WE	SA1693WE	Revised interior arrangement with Nordskog hostess seat 6734 and door 61246 and associated modifications added to Mapco Galley Model 680T-1.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-172C; T.C. A3WE	SA671EA	Installation of pallet net for use with Boeing pallets.	SO	44750	Irvin Industries, Inc. 1315 Versailles Road Lexington, KY 40501
727-172C; T.C. A3WE	SA849CE-D	Reconfiguration of crew compartment panels and avionics system to Transportes Aeros Portugeses requirements. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
727-172C; T.C. A3WE	SA1662WE	Installation of Heath Tecna Corp. AC-10160 pallet with AC-10069 net on Boeing 707-172C. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
727-173C; T.C. A3WE	SA1907WE	Interior arrangement reflecting 122 passenger quick change conversion configuration. Amended 6/3/69.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
727-173C; T.C. A3WE	SA2385WE	Installation of interior arrangement. Amended 9/14/71.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
727-180C; T.C. A3WE	SA558CE	Installation of Kollsman integrated flight instrument system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727-180C; T.C. A3WE	SA559CE	Installation of a single SCAT system. Amended 8/11/75.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-180C; T.C. A3WE	SA560CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
727-200; T.C. A3WE	SA349NW	Installation of wind screen in forward cabin RH side. Issued 8/27/76.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 832 Issaquah, WA 98027
727-200; T.C. A3WE	SA359NW	Installation of carry-on baggage unit. Issued 9/28/76.	NW	48532	KME Manufacturing, Inc. 1200 - 112th N.E. Bellevue, WA 98004
727-200; T.C. A3WE	SA547NW	Installation of Mark I interior kit. Issued 11/22/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue S. Kent, WA 98031
727-200; T.C. A3WE	ST742SO	Modification and installation of seat model 914-1. Issued 6/26/74.	SO	21560	Charlotte Aircraft Corporation P.O. Box 1225 Miami, FL 33148
727-200; T.C. A3WE	SA774SO	Installation of the Litton LTN-211 Omega Navigation System. Issued 11/30/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airlines Miami, FL 33148
727-200; T.C. A3WE	SA816NW	An interior installation. Issued 8/8/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
727-200; T.C. A3WE	SA857NW	Installation of Sundstrand performance advisory display (SPAD) system. Issued 11/14/79.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
727-200; T.C. A3WE	SA969NW	Installation of a left hand coat closet. Issued 7/1/80.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 832 Issaquah, WA 98027
727-200; T.C. A3WE	SA984NW	Installation of a telescoping baggage handling system in the forward cargo compartment. Issued 7/22/80.	NW	04250	Air Cargo Equipment Corp. 1550 North 105th East Avenue Tulsa, OK 74112
727-200; T.C. A3WE	SA1026NW	Installation of ceiling liferaft compartments. Issued 9/22/80.	NW	41625	Heath Tecna 19819 84th Avenue South Kent, WA 98031
727-200; T.C. A3WE	SA2335SW	Modification to increase depth of Weber 808737-618-M pilot seat and 808737-619-M copilot seat. Issued 7/23/76.	SW	14222	B & H Parts Company Meacham Field Fort Worth, TX 76106
727-200; T.C. A3WE	SA2672WE	Installation of coat and luggage stowage unit. Issued 3/23/73.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-200; T.C. A3WE	SA3054WE	Installation of dual Litton LTN-72 inertial navigation system. Amended 6/22/76.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
727-200; T.C. A3WE	SA3081WE	Replacement of evacuation slide container latches with latches of a new design. Reissued 6/2/76.	WE	70130	Sargent Industries PICO Division Kahr Bearing Division 2045 Evans Avenue San Francisco, CA 94124
727-200; T.C. A3WE	SA3594WE-D	Removal of all first class seating and class divider. Relocate cabin seating to provide 14 rows at 38-inch pitch. Installation of additional furnishings. Amended 1/7/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-200 Series; T.C. A3WE	SA3882WE	Installation of aft cargo hold trash chute container assembly, P/N B-25-0256. Amended 2/12/80.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-200, -225; T.C. A3WE	SA1190SO	Installation of passenger interior. Amended 12/18/80.	SO	31420	Eastern Air Lines, Inc. Miami International Airlines Miami, FL 33148
727-200, 737; T.C. A3WE, A16WE	SA764NW	Inner window pane replacement. Issued 5/3/79.	NW	79672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
727-214; T.C. A3WE	SA1922WE	Interior arrangement. Amended 6/6/69.	RM	37015	Frontier Airlines 5900 East 39th Avenue Denver, CO 80207
727-214, -254, -2Q8; T.C. A3WE	SA3069WE	Installation of galley in forward passenger compartment. Amended 2/12/80.	WE	62160	Pacific Southwest Airlines 3225 N. Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3560WE	Installation of PSA galley P/N C-25-0085. Issued 1/18/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3625WE	Installation of 168 passenger interior arrangement. Issued 4/3/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
727-214, -254; T.C. A3WE	SA3820WE	Installation of 165 passenger interior arrangement, and aft stowage closet. Issued 1/8/79.	WE	62160	Pacific Southwest Airlines 3225 North Harbor San Diego, CA 92101
727-222; T.C. A3WE	SA2448WE	Installation of McDonnell Douglas Eros II collision avoidance system. Issued 11/22/71.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2743WE-D	Installation "New Look" cabin interiors. Amended 6/10/77.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2826WE-D	Installations of provisions for ground proximity warning system. Issued 2/21/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2832WE-D	Installation of ground proximity warning system with cockpit annunciations deactivated and warning signals connected to digital recorder. Issued 3/13/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA2841WE-D	Revise cabin seating configuration to accommodate 14 first class/112 coach configuration. Amended 8/20/76.	WE	80500	United Airlines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3037WE-D	Revise cabin seating configuration to accommodate 10 first class/118 coach configuration. Issued 2/24/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3353WE-D	This modification installs a retractable cart tie-down at the Sta. 350-50 and LBL 32.34. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3354WE-D	This modification installs modified seats in the first class compartment. Issued 10/28/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-222; T.C. A3WE	SA3355WE-D	Installation of carry-on baggage and garment bag modules just aft of forward entry door on left side of passenger cabin. Issued 10/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3362WE-D	Installation of a Safe Flight P/N 6500-2 windshear warning computer for in-service evaluation. Issued 3/15/78.	WE	80500	United Airlines San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3578WE-D	Installation of arinc communications addressing reporting system (ACARS). Amended 2/9/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3589WE	Installation of passenger audio entertainment system. Issued 7/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3590WE-D	The cabin interior seating configuration will change from 10F/124Y to 14F/118Y. One row of coach seats will be removed and one row of first class seats added. The class divider will be moved accordingly. Issued 2/9/79.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA3592WE-D	Replace the auxiliary galley/stowage compartment located in the RH aft passenger cabin between station 1101 and 1137 with a new stowage compartment. Amended 12/17/79.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
727-222; T.C. A3WE	SA4063WE	Deletion of the pair of excess Type I emergency exits located at station 720 and 15. Issued 11/29/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
727-223; T.C. A3WE	SA521EA-D	Install single area navigation system. Amended 9/10/68.	SW	10150	American Airlines, Inc. 3800 North Mingo Road Tulsa, OK 74151
727-224; T.C. A3WE	SA3325WE	Installation of auxiliary bar unit No. 1-368. Issued 1/13/77.	WE	61605	Nordskog Industries, Inc. 16000 Strathern Street Van Nuys, CA 91406
727-225; T.C. A3WE	ST593SO	Installation of 18 first class/116 tourist class passenger interior with modified coatroom and windscreen. Issued May 1974.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225; T.C. A3WE	ST753SO	Installation of main cabin equipment to provide accommodations for 137 passengers (12 first class and 125 tourist class). Issued 8/4/76.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727-225A; T.C. A3WE	SA775SO	Installation of a coatroom and class divider partition in the main cabin at B.S. 544. Issued 12/3/79.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
727-225; T.C. A3WE	SA1238CE-D	Interior conversion to 177 tourist class passengers. Issued 11/7/78.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
727-231; T.C. A3WE	SA561CE	Installation of auto thrust system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA562CE	Installation of single seat system. Amended June 1974.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA639CE	Modification of SCAT/Auto Throttle to include auto-land throttle closure feature.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA721CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
727-231; T.C. A3WE	SA1287CE	Revision of engine fire detection circuit. Issued December 1976.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727-231; T.C. A3WE	SA1475CE	Installation of Simmonds Precision performance advisory system (fuel management). Issued 3/6/79.	CE	79400	Trans World Airlines P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
727-237; T.C. A3WE	SA2729WE	Installation of interior arrangement. Issued 7/23/73.	WE	62160	Pacific Southwest Airlines 3220 N. Harbor Drive San Diego, CA 92101
727-247; T.C. A3WE	SA469NW	Installation of coat closet unit on Western Airlines aircraft. Issued 6/24/77.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
727-247; T.C. A3WE	ST549SO	Manufacture and installation of P/N 10826-1 cart stowage unit. Amended 11/18/77.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
727-247; T.C. A3WE	ST550SO	Manufacture and installation of P/N 10825 coat closet unit. This STC is limited to Boeing 727-247 aircraft with wide body interiors. Issued 9/21/73.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FI 32207
727-247; T.C. A3WE	SA3495WE	Conversion of UOP galley by installation of UOP oven, Grimes coffeemaker and overboard drain system. Issued 9/30/77.	SO	8130	Aerospace Division Universal Oil Products 4856 Victor Street Jacksonville, FI 32207
727-247; T.C . A3WE	SA3644WE	Installation of IPECO pilot and co-pilot crew seats. Issued 5/16/78.	WE	54860	MAPCON Associates, Inc. Agents for IPECC Europe Ltd. 18436 Hawthorne Boulevard Suite 212 Torrance, CA 90504
727-247, -2Q8; T.C. A3WE	SA29NE	Installation of Aerospace Division galleys, P/Ns 190E1000-103, 190E2000-105, -106, and -107 in Western Airlines Boeing 727-247 and -2Q8 aircraft. Amended 5/4/79.	NE	81120	Aerospace Division Universal Oil Products Route 202 Bantam, CT 06750
727-248, -2Q8; T.C. A3WE	SA3929WE	Installation of automatic communications addressing and reporting system (ACARS). Issued 5/3/79.	WE	85126	Western Airlines 6060 Avion Drive Los Angeles, CA 90045
727-281;737-281; T.C. A3WE, A16WE	SA33NW	Installation of class divider in constant section at station 500 on Model 727-281 and station 525 on Model 737-281. Issued 3/14/73.	NW	83765	Vinnedge and Associates P.O. Box 374 North Bend, WA 98045
727-291 and 727-295; T.C. A3WE	SA1602WE	Revised interior arrangement with Frontier Galley Models 13301, 13302, 13303, and 13304 installed. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
727, 727C, 727-200; T.C. A3WE	ST7319SO	Installation of automatic in-flight lock for ventral stair-door. Amended 5/18/73.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
727, 727C, 727-200; T.C. A3WE	SA2315WE	Installation of thrust reverser adjustable offset links on above aircraft equipped with Boeing Thrust Reversers, BAC P/N 65-27800-1, 65-27800-3 and 65-27800 only. Issued 2/22/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2337WE	Installation of Triumph Corporation solid offset thrust reverser links. Issued 4/9/71.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727, 727C, 727-200; T.C. A3WE	SA2391WE	Modification of nose gear steering cylinder. Issued 7/30/71.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
727, 727C, 727-200; T.C. A3WE	SA2471WE	Installation of Triumph Corporation 5026 series bearings and rod ends on thrust reversers. Issued 2/1/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T. A3WE	SA2487WE	Installation of main landing gear lock actuator bearing assembly. Issued 3/3/72.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85281
727 727C, 727-200; T.C A3WE	SA2518WE	Installation of thrust reverser forward deflector door link. Issued 5/1/72.	WE	82000	Valley-Todeco, Inc. 12975 Bradley Avenue Sylmar, CA 91342

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
727, 727C, 727-200; T.C. A3WE	SA2627WE	Installation of fuel control rod end bearings. Issued 1/4/73.	WE	79750	Triumph Corporation 2130 S. Industrial Park Avenue Tempe, AZ 85282
727, 727C, 727-200; T.C. A3WE	SA2779WE	Installation of auxiliary power fire detector unit. Reissued 2/11/74.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 Fourth Street Berkeley, CA 94710
727 Series, 737 Series; T.C. A3WE, A16WE	SA1052SO	Installation of GE battery P/N 43B022RB36 in place of Marathon P/N CA-727-7, CA-727-20, or CA-27-20 batteries or SAFT P/N 23180 batteries; or installation of GE battery P/N 43B020RB10 replacing Marathon P/N CA-727-7, CA-727-20 or CA-27-20 or SAFT P/N 23186 or 23180 batteries. Amended 5/11/79.	SO	37380	General Electric Company P.O. Box 114 GAinesville, FI 32602
727 Series; 737 Series; T.C. A3WE, A16WE	SA2501WE	Installation of replacement cooling turbine nozzle assembly. Reissued 1/5/79.	WE	67145	Repair Tech International 13900 Saticoy Street Van Nuys, CA 91402
737 Series; T.C. A16WE	SA270NW	Interior arrangement. Issued 3/11/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA353NW	Installation interior components consisting of 2 wind screens and 3 decorative panels on existing galleys. Issued 9/7/76.	NW	08350	Air Repair 811 West Perimeter Road Renton, WA 98055
737 Series; T.C. A16WE	SA370NW	Removal of passenger interior, installation of cargo compartment liners and cargo tie down equipment. Issued 11/8/76.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA751NW	Installation of a coat closet/ storage bin. Issued 4/12/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA781NW	Installation of a coat closet. Issued 6/7/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
737: T.C. A16WE	SA853NW	Installation of a coat closet. Issued 10/29/79.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	ST854SO	Installation of Bendix GPW-83 ground proximity warning system. Amended 1/21/76.	SO	64500	Piedmont Aviation, Inc. P.O. Box 2720 Smith Reynolds Airport Winston-Salem, NC 27102
737; T.C. A16WE	SA877NW	Installation of coat closet/dry gallery unit. Issued 1/7/80.	NW	78672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055
737; T.C. A16WE	SA884NW	Installation of windscreens. Issued 1/30/80.	NW	48532	KME, Inc. 1260 112th Northeast Bellevue, WA 98004
737; T.C. A16WE	SA1029NW	Installation of a cargo system. Issued 9/27/80.	NW	87365	Vinnedge & Asscciates, Inc. P.O. Box 832 Issaquah, WA 98027
737; T.C. A16WE	SA1401SW	Replace Marathon CA-737 battery with General Electric 43B022RB10 battery. Issued 12/9/71.	GL	37379	General Electric Company 206 W. Mitchell Avenue Cincinnati, OH 45232
737; T.C. A16WE	SA1519SW	Coat closet. Issued 10/14/72.	SW	16750	BIDCO, Inc. 2732 Ludelle Fort Worth, TX 76105
737; T.C. A16WE	SA3983WE	Installation of storage unit, P/N 10165. Issued 6/26/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
737-2A1; T.C. A16WE	ST136RM	Installation of interior arrangement. Issued 4/25/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2A6; T.C. A16WE	SA2153WE	Installation of fuselage fuel tanks in forward and aft cargo compartments.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA6RM	Interior arrangement modification. Amended 3/10/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA66RM	Revision of aft coat closet capacity from 100 lbs. to 250 lbs. Amended 8/6/80.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CC 80207
737-2C0, -2H4, -212, -214, -291, -222, -247; T.C. A16WE	SA67RM	Installation of trash module in aft coat closet. Issued 3/12/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CC 80207
737-2C0, -2H4, -212, -214, -222, -247, -291; T.C. A16WE	SA75RM	Installation of Mapco closet module, P/N 1345, under forward left side hatrack. Issued 5/26/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-2CO, -2H4, -212, -217, -291, -222; T.C. A16WE	SA101RM	Install dual SELCAL system. Amended 6/22/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-021; T.C. A16WE	SA523AL	Installation of ground proximity warning system. Reissued 6/19/75.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
737-T43A; T.C. A16WE	SA265GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500, and Harrowe barometric altitude rate computer P/N 4030-03-1. Issued 8/25/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
737-2S2C, -2Q8C; T.C. A16WE	SA4019WE	Installation of Brownline cargo pallet restraint system, P/N 46926-101, -102. Amended 11/21/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-100, -200, -200C Series; T.C. A16WE	SA2705WE	Installation of Systron-Donner Model 8160-20-P1 rate sensors in Sperry SP-77 autopilot as a replacement for Sperry or Smiths rate gyros. Amended 7/15/74.	WE	77300	Systron-Donner Corporation 200 San Miguel Road Concord, CA 94518
737-100, 737-200; T.C. A16WE	SA2828WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-100, -200; T.C. A16WE	SA3334WE	Installation of stretcher carrier, AM 2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
737-100/200/200C; T.C. A16WE	SA2267WE	Installation of door mounted emergency light. Issued 10/30/70.	WE	44266	International Inflatables Co. Division Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
737-100/200/200C; T.C. A16WE	SA2564WE	Installation of garment bag module. Amended 9/20/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
737-100, -200, -200C; T.C. A16WE	SA170GL	Replace differential synchro and switch in Courter flap position indicator, P/N 18-1299-6, with Courter flap asumetry detector kit, P/N 298-1026-02. Reissued 12/21/78.	GL	26675	Courter, Incorporated 375 North Lake Street Boyne City, MI 49712
737-100, -200, -200C; T.C. A16WE	ST686SO	Installation of nose cap "C/X" band weather radar radome. Amended 10/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
737-100, -200, -200 Series; T.C. A16WE	SA887EA	Installation of structural provisions for tail logo lights. Amended 4/19/72.	EA	18750	Butler Aviation - Friendship, Inc. Sub. of Butler Aviation Int'l Friendship Int'l Airport Baltimore, MD 21240
737-100/200/200C; T.C. A16WE	SA2542WE	Installation of wing-tip mounted logo lights. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
737-200; T.C. A16WE	SA53RM	Installation of Sundstrand Data Control ground proximity warning system and glide slope monitoring system. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
737-200; T.C. A16WE	SA55RM	Installation of Universal Oil Products Co. galley tray cart. Amended 8/18/76.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA62RM	Installation of Universal Oil Products Co. beverage cart, P/N 11143-1. Issued 8/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	SA103NW	Installation of modified lower interior sidewall. Issued 4/12/74.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	SA178NW	Installation of perfume dispenser into three lavatories. Issued 5/12/75.	NW	08350	Air Repair, Inc. 811 W. Perimeter Road Renton, WA 98155
737-200; T.C. A16WE	ST201RM	Modification of Sundstrand data control ground proximity warning system and glide slope monitoring system installation. Issued 6/30/80.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
737-200; T.C. A16WE	ST430SO	Installation of unusual events recording system.	GL	77600	Technology, Inc. 7400 Colonel Glenn Highway Dayton, OH 45431
737-200; T.C. A16WE	ST875SO	Replacement of Monogram P/N 3299-1 or Leach P/N TD1514-1002 timer assemblies with Piedmont P/N 737D-81017 solid state timer. Amended 7/13/76.	SO	64500	Piedmont Aviation, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA883NW	Installation of the Mark I interior conversion kit. Issued 1/30/80.	NW	41625	Heath Tecna 19819 84th Avenue South Kent, WA 98031
737-200 Series; T.C. A16WE	ST1020SO	Installation of 112 passenger interior arrangement. Issued 8/31/78.	SO	64500	Piedmont Aviation Smith-Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	ST1034SO	Fabrication and installation of an aft right hand windscreen. Issued 11/15/78.	SO	64500	Piedmont Airlines Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1113SO	Fabrication and installation of an aft left-hand windscreen. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA1114SO	Fabrication and installation of a forward coat closet. Issued 12/7/79.	SO	64500	Piedmont Airlines, Inc. Smith Reynolds Airport Winston-Salem, NC 27102
737-200; T.C. A16WE	SA2747WE-D	This modification provides an all coach seating configuration for 113 passengers. Issued 5/24/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
737-200; T.C. A16WE	SA3134WE	Installation of Collins ground proximity warning system. Issued 1/7/76.	WE	04080	Air California P.O. Box 2678 Hangar #6, Oakland Int'l Airport Oakland, CA 94614
737-200; T.C. A16WE	SA4042WE	Installation of new overhead enclosed stowage compartments, new fluorescent wash lighting and modified passenger service units. Amended 3/20/80.	WE	42150	HITCO 1600 West 135th Street Gardena, CA 90249
727-200, -200C; T.C. A16WE	SA3464WE	Installation of alternate Systron Donner lower engine fire/overheat detector system, P/N 1705-1, in place of approved P/N 1705 lower engine fire/overheat detector system. Issued 9/2/77.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 4th Street Berkeley, CA 94710
737-200C; T.C. A16WE	SA28NW	Interior modification consisting of installation of cargo/passenger partition and coat closet/service tray stowage. Amended 6/29/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA79NW	Seat pallets for Alaska Airlines. Issued 11/9/73.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA101NW	Interior modification consisting of installation of windscreens and aft coat closet. Issued 4/22/74.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
737-200C; T.C. A16WE	SA276NW	Installation of forward LH/RH wind screen in existing approved interior arrangement. Issued 5/13/76.	NW	83765	Vinnedge & Associates P.O. Box 374 North Bend, WA 98045
737-200C; T.C. A16WE	SA337AL	Installation of palletized seating system on high profile cargo roller system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405
737-200C; T.C. A16WE	SA452AL	Installation of palletized cargo/ passenger system. Reissued 12/5/72.	NW	83765	Vinnedge & Associates, Inc. R.W. Vinnedge P.O. Box 374 North Bend, WA 98405
737-200C; T.C. A16WE	SA492AL	Installation of BE-1006 landing aid system. Amended 12/11/73.	AL	85890	Wien Consolidated Airlines, Inc. 4100 Int'l Airport Road Anchorage, AK 99502
737-201, 737-214; T.C. A16WE	SA1899WE	Installation of under-seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
737-210C; T.C. A16WE	SA3900WE	Installation of heavy duty cargo handling and quick change system, P/N 90045. Issued 4/10/79.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
737-214; T.C. A16WE	SA856CE-D	Installation of two Collins 618T-2 HF radio systems - installation of Bendix "X" band weather radar system - installation of Kollsman Air Data computer. Issued July 1975.	CE	16878	The Boeing Company 3801 South Oliver Wichita, KS 67210
737-214; T.C. A16WE	SA1825WE	Installation of Henry Engineering Co. Lounge Tables No. 17701. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90307
737-222; T.C. A16WE	SA1601WE	Modification of Collins FD109 flight director systems to add a "steering" and "airspeed-hold" modes.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2097WE	Installation of McMillan Radome P/N 2593 in lieu of Boeing Radome P/N 65-2040.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA2182WE	Installation of Bendix Third Attitude Indicator (per requirements of FAR 121.305(j)). Issued 6/10/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2232WE	Replacement of nickel-cadmium battery with 2 lead-acid batteries. Amended 1/28/76.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare Int'l Airport Chicago, IL 60666
737-222; T.C. A16WE	SA2525WE	Installation of interior arrangement. Amended 12/16/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3034WE-D	Replace one first class seat assembly with carry-on baggage module, relocate existing garment bag module and remove LH and RH class divider allowing the two modules to serve as class dividers. Issued 1/26/77.	WE	80500	United Air Lines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3360WE-D	Conversion of passenger cabin from 8/85 dual class configuration to 103 seat all coach configuration. Issued 1/5/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3579WE-D	Installation of Arinc Communications Addressing and Reporting System (ACARS). Amended 8/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3946WE-D	Installation of 113-passenger, all-coach seating configuration. Issued 5/30/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-222; T.C. A16WE	SA3947WE-D	Remove existing galleys, coatrooms and windscreens. Install MAPCO galleys and stowage/service centers. Install a 125-passenger all-coach seating configuration. Issued 7/11/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
737-222; T.C. A16WE	SA3948WE-D	Installation of new overhead stowage compartments, ceiling and sidewall panels and lighting systems. Issued 7/11/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
737-242C; T.C. A16WE	SA2372WE	Installation of Satco, Inc. cargo pallet assembly P/N 31094-501 in conjunction with NAS 3610-2B2N, -2B5N, and 1B2N net assemblies. Issued 7/1/71.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
737-247; T.C. A16WE	SA191NW	Installation of modified two passenger seat and underseat baggage restraint. Issued 6/15/75.	NW	08350	Air Repair, Inc. 811 West Perimeter Road Renton, WA 98055
737-247; T.C. A16WE	ST551SO	Manufacture and installation of P/N 10816 coat closet unit. Issued May 1974.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FI 32207
737-247; T.C. A16WE	ST552SO	Manufacture and installation of P/N 10815 cart stowage unit. Issued May 1974.	SO	81130	Universal Oil Products Company Aerospace Division 4856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST567SO	Manufacture and installation of P/N 10949-1 RH aft galley (FS 991.09-1023.25). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FL 32207
737-247; T.C. A16WE	ST568SO	Manufacture and installation of P/N 10948-1 RH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FI 32207
737-247; T.C. A16WE	ST569SO	Manufacture and installation of P/N 10950-1 LH forward galley (FS 914.87-947.00). Issued 12/7/73.	SO	81130	Aerospace Division of UOP 3856 Victor Street Jacksonville, FI 32207
737-248C; T.C. A16WE	SA2129WE	Installation of Brownline Division cargo pallet assembly 41121101 and cargo net assembly 41119101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-248C; T.C. A16WE	SA2130WE	Installation of Brownline Division cargo pallet assembly 41120101 and cargo net assemblies: Brownline 22361-51, 22178-51, 41122101, 41123101, AMF 306-60120-1. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
737-275C; T.C. A16WE	SA233NW	Installation of cargo handling equipment for three forward cargo pallet positions. Issued 10/24/75.	NW	83765	Vinnedge & Associates P.O. Box 832 Issaquah, WA 98027
737-293; T.C. A16WE	SA2007WE	Installation of header and drape.	WE	62080	Pacific Airmotive Corporation, Inc. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91503
737-293; T.C. A16WE	SA2960WE	Installation of galley module in Nordskog galleys P/N's 897 and 898. Issued 12/31/74.	WE	61529	Neushul Corporation 1911 West 139th Street Gardena, CA 90249
737-293; T.C. A16WE	SA3197WE	Installation of auxiliary stowage compartment. Issued 8/17/76.	WE	04080	Air California P.O. Box 2678, Airport Station Oakland International Airport Oakland, CA 94614
747 Series; T.C. A20WE	SA41GL	Install Brooks & Perkins cargo container P/N 17609-E-100. Reissued 2/2/76.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA44NW	Installation of cargo containers. Amended 11/16/76.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747 Series; T.C. A20WE	SA47GL	Install cargo container P/N 17617-E-100. Amended 7/14/75.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA48GL	Install cargo container P/N 17630-E-100. Issued 4/19/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA108NW	Installation of Mark IV visual entertainment system. Issued 4/26/74.	NW	76800	Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747 Series; T.C. A20WE	SA139GL	Install Brooks & Perkins cargo container, P/N 17701-E-100. Issued 10/21/76.	GL	17750	Brooks & Perkins 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA255NW	Installation of Xenon light modification in visual entertainment system. Issued 1/26/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
747; T.C. A20WE	SA508NW	Installation of class divider/coat closet assembly. Issued 8/29/77.	NW	48532	KME Manufacturing Company 849 Seneca, S.W. Renton, WA 98055
747 Series; T.C. A20WE	SA689CE	Installation of Brooks & Perkins cargo container, P/N's 17026-100, Type A; 17026-100-1, Type A; and 17083-100, Type A. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747 Series; T.C. A20WE	SA692CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA694CE	Install GATX LD3 cargo containers. Reissued 1/15/71.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA702CE	Installation of Bendix standby horizon indicator and inverter.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MC 64153
747 Series; T.C. A20WE	SA711CE	Installation Brooks & Perkins cargo container.	GL	17750	Brooks & Perkins, Inc. 1950 West Fort Street Detroit, MI 48216
747 Series; T.C. A20WE	SA792CE	Make and install P/N 17455-100 cargo container. Issued August 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
747; T.C. A20WE	SA835NW	Installation of storage units at station 617. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA836NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747; T.C. A20WE	SA837NW	Installation of storage unit, upper deck. Issued 9/27/79.	NW	48532	KME The Commons Building 1200 112th N.E. Bellevue, WA 98055
747 Series; T.C. A20WE	ST867SO	Installation of Bendix ground proximity warning system. Issued 11/4/75.	SO	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
747 Series; T.C. A20WE	SA1435SW	Refrigerated air cargo container for lower lobe. Issued 2/24/72.	SW	04250	Air Cargo Equipment Corporation 5555 South Garnett Road Tulsa, OK 74115
747 Series; T.C. A20WE	SA1780SW	Portable solid oxygen system. Issued 1/15/74.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
747 Series; T.C. A20WE	SA2334SW	LD-3 cargo container, P/N DCT 1250. Issued 7/20/76.	SW	04250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74115
747 Series; T.C. A20WE	SA2756WE	Modify aircraft by installation of Hermes refrigerated LD-3 cargo container, Koolflite P/N 1000. S/N 8-3-001 only. Issued 9/6/73.	WE	42120	Hermes Enterprises P.O. Box 5141 Sherman Oaks, CA 91413
747 Series; T.C. A20WE	SA2801SW	Install container baggage/freight LD-3 type. Issued 6/19/78.	SW	04250	Air Cargo Equipment Corp. P.O. Box 15630 Tulsa, OK 74112
747 Series; T.C. A20WE	SA3041WE-D	Replacement of NAS3610-2L1C cargo containers with L size pallets and nets. Issued 7/27/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747SP; T.C. A20WE	SA285GL	Install MAPCO Model 1550 low boy galley. Amended 1/10/79.	GL	54700	Mansfield Aircraft Products Co. Mansfield Lahm Airport Mansfield, OH 44901

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747SP; T.C. A20WE	SA929NW	Installation of sidewall stowage units. Issued 4/18/80.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
747SP; T.C. A20WE	SA930NW	Installtion of an upper deck closet. Issued 4/18/80.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
747-21; T.C. A20WE	SA34NE	Installation of Aerospace Div. U.O.P. Inc., main deck closet assembly, P/N 402490-1. Issued 4/18/80.	NE	81120	U.O.P., Inc. Aerospace Division Route 202 Bantam, CT 06750
747SP-21; T.C. A20WE	SA1079EA-D	Installation of flight attendant crew berth compartment in the main cabin, zone "B" aft end. Amended 4/17/79.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
747SP-21, -121, -132; T.C. A20WE	SA1080EA-D	Installation of Delco F130A performance management system. Amended 9/25/80.	EA	62300	Pan American World Airways, Inc. JFK International Airport Jamaica, NY 11430
747SP-27; T.C. A20WE	SA1174EA	Installation of 16mm movie system in zone B cabin. Issued 10/30/79.	EA	44000	Inflight Motion Pictures Division of Inflight Services, Inc. 175-28 148th Avenue Jamaica, NY 11434
747-2F6B; T.C. A20WE	SA4072WE	Installation of a video projection system. Issued 1/16/80.	WE	15375	Bell and Howell Company Avicom Division 360 Sierra Madre Villa Pasadena, CA 91109
747-E4A, -E4B; T.C. A20WE	SA307GL	Installation of Collins FPC-75 flight profile comparator, P/N 622-2615-500. Issued 5/2/79.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
747-SP44, 747-244B; T.C. A20WE	SA3740WE	Installation of main dock cargo/baggage system. Issued 4/19/79.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-E4A, -E4B; T.C. A20WE	SA2951WE	Installation of Steward Davis Airstairs P/N 77004. Amended 3/23/78.	WE	33770	E - Systems, Inc. Greenville, Division P.O. Box 1056 Greenville, TX 75401
747-100; T.C. A20WE	SA817EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A300-001-101. Amended 3/9/71.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA824EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A400-001-101. Reissued 9/8/70.	GL	39000	Goodyear Aerospace Corporation 1210 Massillon Road Akron, OH 44315
747-100; T.C. A20WE	SA835EA	Installation of Goodyear Aerospace Corp. lower deck baggage/cargo container P/N 625A401-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA842EA	Installation of Goodyear Aerospace Corp. Universal lower deck baggage/ cargo container P/N 625A402-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-100; T.C. A20WE	SA2117WE	Installation of 747 lower deck modular and unitized baggage/cargo containers.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90247
747-100; T.C. A20WE	SA2222WE	Installation of SATCO Pallet No. 31080-501 with Marino Net Assembly LM1500-100, Ancra Corp. Net Assembly 40234-10, and net assemblies approved to NAS 3610-2AN and NAS 3610-2A3N. Issued 8/16/70.	WE	70250	Satco, Incorporated 1509 El Segundo Boulevard El Segundo, CA 90245
747-100; T.C. A20WE	SA2708WE	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-103. Issued 6/7/73.	WE	39010	Goodyear Aerospace Corporation Arizona Division Litchfield Park, AZ 85340
747-100 Series; T.C. A20WE	SA3547WE	Installation of cargo container P/N 025-45571	WE	25970	Continential Airlines 7300 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
747-100 Series, 747-200 Series; T.C. A20WE	SA976CE-D	Fuselage structure and related modification for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-100 Series, 747-200 Series; T.C. A20WE	SA977CE-D	Interior modifications for cargo. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series, 747-200 Series; T.C. A20WE	SA978CE-D	Cargo handling and power drive system. Amended 10/28/77.	CE	16878	The Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-100 Series, 747-200 Series; T.C. A20WE	SA2646WE	Installation of lock assembly No. 41853-101, -102, -103, -201, -202, -203, -204, -301, -302, -303, -304. Amended 4/20/79.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200 Series; T.C. A20WE	SA3754WE	Installation of forward and aft lower cargo compartment door sill restraint fittings. Issued 10/9/78.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, 747-200 Series; T.C. A20WE	SA3813WE	Installation of Brownline side restraint, P/N 44981-101. Issued 12/20/78.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Boulevard Torrance, CA 90505
747-100 Series, 747-200B Series; T.C. A20WE	SA490GL	Installation of a Telephonics P/N 547-000-1 central switching unit. Issued 1/14/81.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul International Airport St. Paul, MN 55111
747-100, -200B; T.C. A20WE;	SA2446WE	Installation of Brownline single pallet lock assembly. Amended 1/3/75.	WE	79500	Tridair Industries Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505
747-100, -200B; T.C. A20WE	SA2801WE	Installation of main deck cargo restraint system. Issued 1/16/74.	WE	79000	Transequip Inc. 180 N. Aviation Boulevard El Segundo, CA 90245
747-100, -200B; T.C. A20WE	SA3424WE	Installation of BMA main deck baggage container, P/N 302928. Issued 6/9/77.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747, 747-100, -200B, -200C, -200F, 747SR; T.C. A20WE	SA488GL	Modification of B.F. Goodrich slide/raft assembly 7A1238. Issued 1/8/81.	GL	83500	B.F. Goodrich Engineered Products Group 500 South Main Street Akron, OH 44318
747-100, -200B, -200C, -200F; T.C. A20WE	SA2845WE	Installation of logo light assembly. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
747-100, -200B, -200C, -200F; T.C. A20WE	SA2895WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100, -200B, -200C, -200F; T.C. A20WE	SA2962WE	Installation of Hermes LD-3 Koolflite refrigerated cargo container. Issued 12/16/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
747-100 Series, 747-200C, 200F Series; T.C. A20WE	SA3074WE	Installation of 96 x 125 inch animal containers. Amended 11/30/77.	EA	72770	J.D. Smith Air Export, Inc. One World Trade Center Suite 2161 New York, NY 10048
747-100, -200B, -200C, 747SR, 747SP; T.C. A20WE	SA3480WE	Installation of Hughes passenger entertainment/passenger service multiplex system. Issued 11/3/77.	WE	43330	Hughes Aircraft Company Microelectronics Products Div. 500 Superior Avenue Newport Beach, CA 92663
747-100, -200B, -200C, 747SR, 747SP Series; T.C. A20WE	SA3511WE	Installation of stretcher carrier P/N AM2003. Issued 3/21/78.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
747-100, -200B, -200C, -200F; T.C. A20WE	SA3604WE	Installation of Transequip, Inc. auto transponder assembly, P/N 303500. Issued 3/2/78.	WE	79000	Transequip, Inc. 180 North Aviation Boulevard El Segundo, CA 90245
747-121; T.C. A20WE	SA503EA-D	1) Add additional first class passenger seats and class divider. 2) Add two additional coat closets in Zone C. Issued 5/11/70.	SW	10150	American Airlines, Inc. Maintenance & Engineering Tulsa, OK 74151
747-121; T.C. A20WE	ST714SO-D	Installation of NASA aircraft-to-satellite data acquisition relay (ASDAR) system. Amended 12/14/77.	WE	62300	Pan American World Airways, J.F.K. International Airport Jamaica, NY 11430

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-121; T.C. A20WE	SA809EA	Installation of Goodyear Aerospace Corp. lower baggage container P/N 625A100-001-101. Reissued 12/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-121; T.C. A20WE	SA869EA	Installation of carry-on luggage containers. Issued 4/2/71.	NE	81120	Aerospace Division Universal Oil Products Company Bantam, CT 06750
747-121; T.C. A20WE	SA936EA	Installation of expanded digital flight data recorder system. Amended 4/13/73.	EA	62300	Pan American World Airways Pan Am Building New York, NY 10017
747-121; T.C. A20WE	SA1077EA-D	Installations of Delco F130A flight management system. Amended 8/14/79.	EA	62300	Pan American World Airways, Inc. J.F.K. International Airport Jamaica, NY 11430
747-121; T.C. A20WE	SA2466WE	Installation of AiResearch P/N 216001-401 and -402 class divider - bulkhead assembly. Issued 1/13/72.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121; T.C. A20WE	SA2706WE	Modification by installation of AiResearch coat closed P/N 2130091. Issued 5/30/73.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121; T.C. A20WE	SA3494WE	Installation of Weber Aircraft auxiliary galley, P/N 822767. Issued 9/22/77.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-121, -123, -131, -132, -156; T.C. A20WE	SA1215EA	Installation of Air Cruisers slide/raft evacuation systems. Amended 12/22/80.	EA	07250	Air Cruisers Company Div. of Garrett Corporation P.O. Box 180 Belmar, NJ 07719
747-121, 747-123; T.C. A20WE	SA2444WE	Installation of tables without association with a seating arrangement. Amended 4/27/72.	WE	07500	AiResearch Aviation Company Airline Products Facility 19201 Susana Road Compton, CA 90221
747-121, -122, -238B; T.C. A20WE	SA2823WE-D	Installation of equipment required to conduct NASA/UAL global air sampling program. Amended 11/25/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-121, -123, -273C; T.C. A20WE	SA3007WE	Installation of cargo pallet assembly, P/N 31250-521. Amended 11/19/75.	WE	70250	Satco, Incorporated 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-121, -132; T.C. A20WE	SA2624WE	Interior arrangement modification. Amended 4/27/78.	WE	07500	AiResearch Aviation Company Airline Products FAcility 19201 Susana Road Compton, CA 90221
747-121, 747-132; T.C. A20WE	SA3550WE	Installation of Weber auxiliary galley, P/N 822767 Amended 6/1/78.	WE	84900	Weber Aircraft Div. of Walter Kidde & Co., Inc. 2820 Ontario Street Burbank, CA 91510
747-122; T.C. A20WE	SA2193WE	Installation of entree cart 802000, tray cart 803000, liquor cart 804000, and waste cart 805000. Amended 9/2/71.	WE	34220	Fairchild Hiller Corporation Stratos-Western Division 1800 Rosecrans AVenue Manhattan Beach, CA 90266
747-122; T.C. A20WE	SA2658WE	Modification of lower deck cargo compartment restraint system. Issued 3/14/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2717WE	Installation of interior arrangement. Issued 6/26/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2750WE	Modification of aircraft for installation of spacer pallets. Issued 9/7/73.	WE	80500	United Air Lines, Inc. Maint. Base, Engineering Dept. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2821WE-D	Installation of additional service cart retractable tiedowns. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA2822WE-D	Modified cabin interior configuration. Issued 11/26/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-122; T.C. A20WE	SA2829WE-D	Installation of Collins FPC-75, P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco, CA 94128
747-122; T.C. A20WE	SA3352WE-D	Reduced first class seating to 26 seat places, relocated class divider, installed 10-across coach seating - 348 coach seat places. Issued 11/14/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3581WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 11/2/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
747-122; T.C. A20WE	SA3942WE-D	Rework of high frequency communications system to install single-sideband capability. Issued 3/27/80.	WE	80500	United Airlines, Inc. San Francisco Int'l. Airport San Francisco, CA 94128
747-122, -123; T.C. A20WE	SA3066WE	Installation of lower lobe food service modules, P/Ns 818720 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
747-123; T.C. A20WE	SA2926WE	Modification to incorporate cargo restraint system P/N 43830, configuration -101. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-123; T.C. A20WE	SA2928WE	Installation of carrier aircraft crew galley Model FTL 47-1 in the upper lounge. Issued 9/6/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
747-123; T.C. A20WE	SA3016WE	Installation of Brownline cargo systems 44297-101 and 44297-102. Issued 5/10/75.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Boulevard Torrance, CA 90505
747-127; T.C. A20WE	SA2972WE	Modification of lower deck aft cargo compartment restraint system to accommodate NAS 3610 Size A aircraft unit load devices. Issued 12/27/74.	SW	17075	Braniff International Exchange Park Dallas, TX 75235
747-128; T.C. A20WE	SA3436WE	Installation of Brownline cargo system 45600-102. Issued 6/21/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-131; T.C. A20WE	SA715CE	Installation of aircraft integrated data system. Amended 12/12/77.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA728CE	Installation of Hamilton Standard TAT/EPRL System.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
747-131; T.C. A20WE	SA877CE	Installation of expanded parameter flight recorder. Amended April 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
747-131; T.C. A20WE	SA2411WE	Installation of Irvin net assembly 409054-501 for use in conjunction with pallet assemblies Brownline P/N 23250-51 or 23250-52. Issued 12/6/71.	WE	44750	Irvin Industries, Inc. 15001 S. Figueroa Street Gardena, CA 90248
747-131; T.C. A20WE	SA2755WE	Modification of aircraft for installation of 13-inch beverage carts. Issued 9/4/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-131; T.C. A20WE	SA3491WE	Installation of Brownline cargo system 45747-101. Issued 9/27/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-131/156; T.C. A20WE	SA1614CE	Modification of upper deck to 16 passenger configuration. Issued 11/17/80.	CE	79400	Trans World Airlines, Inc. Kansas City Inter'l Airport P.O. Box 20126 Kansas City, MC 64195
747-132; T.C. A20WE	SA3381WE	Installation of Brownline lower lobe cargo system, No. 45478-101. Issued 4/11/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 West Lomita Boulevard Torrance, CA 90505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-132; T.C. A20WE	SA3446WE	Installation of Browline cargo system 45600-101. Issued 7/5/77.	WE	17740	Brooks & Perkins, Inc. Brownline Division 2950 W. Lomita Blvd. Torrance, CA 90505
747-133; T.C. A20WE	SA1443CE-D	Installation of Type I door, extension of upper deck and interior reconfiguration. Issued 5/20/80.	CE	16878	Boeing Military Airplane Company 3801 South Oliver Wichita, KS 67210
747-135; T.C. A20WE	ST505SO	Manufacture of Nordskog storage units in accordance with Nordskog drawings 1-209, Rev. B and 1-210, Rev. B and their installation in accordance with NAL E.O. P-2350-01 and P-2350-00-06, Rev. B respectively. Issued 5/23/72.	SO	61220	National Airlines, Inc. Box 2055, Airport Mail Facility Miami, FL 33159
747-135, -151, -251B, -251F; T.C. A20WE	SA90GL	Installation of Bendix GPW-83 ground proximity warning system. Amended 6/8/76.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
747-136; T.C. A20WE	SA1144EA	Installation of movie screens in upper deck and 'B' cabin. Issued 4/27/79.	EA	4400	Inflight Motion Pictures, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-136; T.C. A20WE	SA1145EA	Installation of 16 mm movie pallet in 'B' cabin. Amended 3/31/80.	EA	44000	Inflight Motion Picutres, Inc. 178-25 148th Avenue Jamaica, NY 11434
747-136; T.C. A20WE	SA1438CE-D	Installation of a Type I door in the left-hand side of the upper deck fuselage. Amended 11/9/79.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-151, -251B; T.C. A20WE	SA2783WE	Installation of wheeled refrigerated module, P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild-Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-200; T.C. A20WE	SA871NW	Installation of a sidewall stowage unit. Issued 12/10/79.	NW	25550	The Commons Building 1200 112th N.E. Bellevue, WA 98004
747-200; T.C. A20WE	SA872NW	Installation of a trolley stowage unit. Issued 12/12/79.	NW	25550	The Commons Building 1200 112th N.E. Bellevue, WA 98004
747-200; T.C. A20WE	SA873NW	Installation of an attendant's console. Issued 12/12/79.	NW	25550	The Commons Building 1200 112th N.E. Bellevue, WA 98004
747-200 Series: T.C. A20WE	SA3659WE	Installation of Litton LTN-72R INS/RNAV and/or LTN-72 INS navigation systems in a triple configuration. Issued 6/21/78.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
747-200B, -200C; T.C. A20WE	SA983EA	Installation of Super 8mm IMPAK projector assemblies, P/N's 10304 ("A" Compartment) and 10306 ("C-D-E" Compartment). Issued 6/18/74.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
747-200F; T.C. A20WE	SA190NW	Installation of 29th position pallet/container kit. Issued 6/10/75.	NW	85142	Western Gear Corporation Flight Structures Division 2100 Norton Everett, WA 98201
747-206B; T.C. A20WE	SA1442CE-D	Installation of Type I door, left side, upper deck fuselage. Issued 10/25/79.	CE	16878	Boeing Wichita Company 3801 South Oliver Wichita, KS 67210
747-212B; T.C. A20WE	SA4093WE	Installation of passenger interior arrangements. Amended 8/22/80.	WE	36100	Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009
747-221F, -246F, -249F; T.C. A20WE	SA3304WE	Installation of Brownline Cargo System No. 45102-101, -103 and -301. Amended 4/26/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-221F; T.C. A20WE	SA4001WE	Installation of Brownline pallet restraint system, P/N 46484-103 and -104. Issued 8/14/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-237B; T.C. A20WE	SA1444CE-D	Installation of type I door (left side, upper deck fuselage) extension of upper deck and interior reconfiguration. Issued 7/25/80.	CE	16878	Boeing Military Airplane Company 3801 South Oilver Wichita, KS 67210

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
747-238B; T.C. A20WE	ST565SO	Lower lobe right hand module unit, P/N 10892-1 left hand module unit P/N 10893-1 and -101, and lower lobe cupboards unit P/N 68878-1 and -101. Amended 7/1/76.	SO	81130	Aerospace Division of UOP 4856 Victor Street Jacksonville, FL 32207
747-238B; T.C. A20WE	SA570EA	Installation of Universal Oil Products tray cart modules P/Ns 68878, 68879, 68880 in Boeing Model 747-238B. Issued 8/31/71.	NE	81120	Aerospace Division Universal Oil Products Company Bantam, CT 06750
747-238B; T.C. A20WE	SA2393WE	Installation of Satco, Inc. cargo net assembly P/N 31128-501 in conjunction with Tridair-Brownline cargo pallet assembly P/N 24076-51 and NAS 3610-2A4P pallet. Issued 8/10/71.	WE	70250	Satco, Inc. 1509 E. El Segundo Boulevard El Segundo, CA 90245
747-238B; T.C. A20WE	SA3868WE	Installation of Brownline cargo system 44297 configuration – 104. Issued 1/25/80.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 Lomita Boulevard Torrance, CA 90505
747-245F; T.C. A20WE	SA1032EA	Installation of Collins FPC-75 ground proximity warning system. Amended 3/20/76.	EA	70600	Seaboard World Airlines Seaboard World Building JFK International Airport Jamaica, NY 11430
747-249F; T.C. A20WE	SA4040WE	Installation of Brownline lower compartment cargo pallet restraint system, P/N 45478-102. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-249F; T.C. A20WE	SA4052WE	Installation of Brownline cargo system, 45600-103. Issued 11/2/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 West Lomita Boulevard Torrance, CA 90505
747-257B; T.C. A20WE	SA2307WE	Installation of drink trolly 744000. Reissued 8/3/71.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
747-258B; T.C. A20WE	SA891EA	Installation of inflight motion picture system. Amended 1/11/72.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11424
747-284B; T.C. A20WE	SA2791WE	Modification of airplane lower deck aft cargo compartment restraint system. Issued 12/10/73.	EU	61797	Olympic Airways S.A. 96, Syngrov Avenue Athens, Greece
Miscellaneous	SA4-1210	Eonnex cover on aircraft surfaces.	WE	33500	Eonair, Inc. Route 1, Box 632 Bakersfield, CA 93309

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BOEING COMPANY, VERTOL DIVISION

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
107-II; T.C. 1H16	SH205NW	Installation improved aft transmission lower case, modification of aft transmission upper case. Issued 8/15/75.	NW	25000	Columbia Helicopters 5407 North Lagoon Avenue Portland, OR 97217
107-II; T.C. 1H16	SH269EA	Instruments for instrument flight (HIR). Amended 3/22/67.	EA	61542	New York Airways, Inc. P.O. Box 426 LaGuardia Airport Station Flushing, NY 11371
107-II; T.C. 1H16	SH422NW	Installation of electrical sensors on each main rotor blade to monitor blade integrity in flight. Issued 3/14/77.	NW	25000	Columbia Helicopters 5407 North Lagoon Avenue Portland, OR 97217
107-II; T.C. 1H16	SH897NW	Replacement of the differential collective pitch trim actuator (DCPT) in the longitudinal control system by a rigid link. Issued 3/4/80.	NW	25000	Columbia Helicopters P.O. Box 3500 Portland, OR 97208
Vertol II; T.C. H8WE	SH593NW	Installation of in-flight blade monitoring system. Issued 4/27/78.	NW	25000	Columbia Helicopters P.O. Box 3500 Portland, OR 97208

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH-125-400A; T.C. A3EU	SA767EA	Installation of forward cabin lavatory.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA768EA	Installation of a two place, side facing divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA769EA	Installation of Kollsman combined ASI/Machmeter A39469-10036.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA770EA	Installation of United Controls angle of attach system. Reissued 12/18/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA793EA	Installation of Litton skyphone system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA831EA	Installation of three Flite-Tronics PC-17 static inverters and one Jet Electronics & Technology, Inc. emergency power supply, Model PS-800. Issued 6/24/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA833EA	Installation of electric elevator trim system. Amended 4/12/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; T.C. A3EU	SA1981WE	Installation of Sperry Model SP-40C automatic flight control system (P/N 1782874-512). Amended 11/28/69.	WE	74570	Sperry Slight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 95027
DH-125-400A; T.C. A3EU	SA2066WE	Category II system and equipment approval of Sperry Models SP-40 automatic flight control system P/N 1782874-512, and SPI-60 integrated instrument system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19 Avenue Phoenix, AZ 85027
DH.125, HS.125, BH.125; T.C. A3EU	SA1184SO	Replace existing batteries with the SAFT 2371-5 series nickel-cadmium batteries. Issued 11/12/80.	SO	69800	SAFT America, Inc. 711 Industrial Valdosta, GA 31601
DH.125, HS.125, BH.125; T.C. A3EU	SA1185SO	Replace existing batteries with the SAFT 2376-5 series nickel-cadmium batteries. Issued 11/12/80.	SO	15000	Battery Shop, Inc. 101A Space Nashville, TN 37217
DH. 125-400A, BH. 125-400A; T.C. A3EU	SA1173EA	Rework of Solar T-62T-39 APU installed by STC SA674CE when Garrett AiResearch TFE-731-3-1H engines are installed. Issued 10/25/79.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125-400A, BH.125-400A; T.C. A3EU	SA3870WE	Installation of Garrett AiResearch TFE-731-3-1H engines and related changes. Issued 2/28/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, BH.125-400A; T.C. A3EU	SA4009WE	Installation of Collins APS-80 autopilot. Issued 8/9/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH 125 Series 400A, BH 125 Series 400A; T.C. A3EU	SA4116WE	Modification of a previously approved Microturbo APU Model 024 type "Saphir4" installation. Issued 3/10/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH-125-400A, BH-125-400A, DH125-1A/S-522; T.C. A3EU	SA4115WE	Installation of light dump baulk system. Issued 3/11/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DH.125-400A, DH.125-3A/RA; BH.125-400A; T.C. A3EU	SA844EA	Installation of Teledyne Avionics angle of attack system. Reissued 7/1/76.	EA	78000	Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906
DH.125-400A, DH-125-3A/RA; BH.125-400A; T.C. A3EU	SA857EA	Installation of Microturbo, Inc. auxiliary power unit Model 024, type "Saphir 4." Amended 4/2/71.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
DH-125-400A; BH.125-400A, -600A, HS.125-700A; T.C. A3EU	SA674CE	Installation of Solar Model T-62T-39Y or -39 or -40C auxiliary power unit modifications. Amended 5/23/80.	EA	63275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH. 125-1A, -3A, -400A, HS. 125-600A, -700A, BH. 125-400A, -600A; T.C. A3EU	SA1175EA	Installation of access doors. Issued 11/19/79.	EA	73275	PATS, Incorporated 7190-8 Oakland Mills Road Columbia, MD 21046
DH.125, HS.125 Beechcraft; T.S. A3EU	ST1003SO	Replace existing lead-acid batteries with Gill BB638/T1-E lead acid batteries, part numbers BSI 200 left and BSI 200 right Issued 6/23/78.	SO	15100	The Battery Shop, Inc. P.O. Box 17312 Nashville, TN 37127
DH-125-400A, HS 125-600A; T.C. A3EU	SA786EA	Installation of lavatory door and bulkhead at station 392. Amended 7/19/76.	EA	07498	AiResearch Aviation Company 2221 Smithtown Avenue Ronkonkoma, L.I., NY 11779
BH125-400A; T.C. A3EU	SA1413SW	Three Flite-Tronics static inverters. Reissued 2/14/75.	SO	34809	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
BH125-600A; T.C. A3EU	SA1888SW	Collins flight control system FCS-105. Issued 6/21/74.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
BH125-600A; T.C. A3EU	SA1923SW	Solar T62T-39 turbine auxiliary power unit. Issued 1/17/75.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
BH125-600A; T.C. A3EU	SA1948SW	Teledyne Avionics normalized angle of attach indicating system P/N 112P900. Amended 9/14/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
BH125-600A; T.C. A3EU	SA2271SW	Interior. Issued 10/27/76.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203
HBH/HS.125-600A, HS.125-700A; T.C. A3EU	SA1101EA	Installation of GNS-500A VLF/Omega system. Amended 5/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS.125-600A, BH.125-600A, HS.125-700A; T.C. A3EU	SA3705WE	Installation of Garret AIRNAV 200 or an AirNav 300 area navigation system. Amended 3/5/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA1074EA	Installation of bulkhead and door at F.S. 391.5 Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. 3EU	SA1075EA	Installation of forward baggage and avionics compartment. Issued 5/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1104EA	Installation of oxygen system. Issued 6/7/78.	EA	44035	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A3EU	SA1105EA	Installation of Collins VHF 251 standby communication. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A36EU	SA1106EA	Installation of baggage compartment structural entrance area for use with drawer jump seat. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1107EA	Installation of aft cabin bulkhead and door installation. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1108EA	Installation of avionic equipment rack - washroom. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1109EA	Installation of air distribution system. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
HS. 125-700A; T.C. A3EU	SA1110EA	Installation of emergency lighting system to meet the retroactive requirements of FAR 25.2. Amended 10/25/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1111EA	Installation of Wulfsberg III B flitefone. Amended 1/24/79.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1112EA	Installation of nose gear taxi lights. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1113EA	Installation of general lighting. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1114EA	Installation of cabin lining. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1115EA	Installation of Jet AI-804 emeregency horizon. Issued 6/8/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS. 125-700A; T.C. A3EU	SA1116EA	Installation of forward cabin bulkhead LHS and RHS. Amended 10/24/78.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec H4Y1A6 Canada
HS.125-700A; T.C. A3EU	SA1117EA	Installation of dual Collins ADS-80F air data system. Reissued 7/26/78.	CE	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1118EA	Installation of Collins FGS-80 flight director system with FD 109 instruments. Amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS. 125-700A; T.C. A3EU	SA1119EA	Installation of a single Collins ADS-80F air data system. Reissued 7/26/78.	CE	24250	Collins General Aviation Division 400 Collins Road, N.E. Cedar Rapids, IA 52402
HS. 125-700A; T.C. A3EU	SA1120EA	Installation of a side facing single seat. Issued 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
HS.125-700A; T.C. A3EU	SA1140EA	Installation of a three place side facing divan, aft cabin left hand side. Issued 1/19/79.	EA	44034	Innatech Aviation Limited Montreal International Airport Dorval, Quebec Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1183EA	Installation of bar galley unit. Issued 2/8/80.	EA	44034	Innotech Aviaiton Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
H.S. 125-700A; T.C. A3EU	SA1184EA	Installation of Collins WXR-300 color radar system and the Collins RNS-300 radar navigation system. Amended 4/25/80.	EA	44034	Innotech Aviation Limited P.O. Box 130 Montreal International Airport Dorval, Quebec, Canada H4Y1A6
HS 125-700A; T.C. A3EU	SA1196EA	Installation of solar T-62T-40C APU with 400 ampere starter-generator. Issued 5/29/80.	EA	63275	PATS, Inc. 7190-B Oakland Mills Road Columbia, MD 21046
HS-125-700A; T.C. A3EU	SA1538CE	Modification of aircraft to incorporate a fuel management computer. Issued 12/4/79.	CE	24540	Colt Electronics Company 131 West Ninth Avenue North Kansas City, MO 64116
HS.125-700A; T.C. A3EU	SA3552WE	Installation of Delco C-IVA inertial navigation system. Issued 1/13/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS. 125-700A; T.C. A3EU	SA3663WE	Installation of Foxboro engine fuel flow and totalizer system. Issued 6/19/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
HS. 125-700A; T.C. A3EU	SA3690WE	Installation of a Garrett/ AiResearch GTCP36-100 APU in the tail compartment. Issued 6/30/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3878WE	Installation of Eldec engine fuel flow and totalizer system. Issued 3/8/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
HS.125-700A; T.C. A3EU	SA3885WE	Installation of dual Global GNS-500A VLF/Omega navigation system. Issued 4/16/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
HS.125-700A; T.C. A3EU	SA3984WE	Installation of dual Litton LTN-211 ONS. Reissued 3/21/80.	WE	51500	Litton Aero Products, Inc. 6700 Eton Avenue Canoga Park, CA 91303
HS.125-700; T.C. A3EU	SA4021SW	BKM 100 PHM 700 pitot heat monitor system. Issued 7/24/79.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
HS. 125-700A; T.C. A3EU	SA4042SW	Relocation of center point pressure refueling system. Issued 9/26/79.	SW	11670	Arkansas Modification Center P.O. Box 3356 - Adams Field Little Rock, AR 72203
HS 125-700A; T.C. A3EU	SA4078SW	Install BKM specific range computer system (SRCS). Issued 1/25/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75234
HS.125-700A; T.C. A3EU	SA4152SW	Jump seat. Issued 7/9/80.	SW	11670	Arkansas Modification Center P.O. Box 3356 - Adams Field Little Rock, AR 72203
H.P. 137 Jetstream Mk1; T.C. A21EU	SA275GL	Modification of cabin and cockpit conditioned air and air distrubition system. Issued 11/6/78.	GL	08140	Air Illinois, Inc. Southern Illinois Airport P.O. Box 1224 Carbondale, IL 62901
H.P. 137 MK1 and H.P. 137 as modified STC SA3425WE; T.C. A21EU	SA440SO	Installation of Bendix Model M-4C automatic flight control system (AFCS) and installation of a Bendix M-4DAFCS. Amended 6/21/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
H.P. 137 MK1; T.C. A21EU	SA785EA	Installation of replacement radome P/N 3079KX. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
H.P. 137 MK1; T.C. A21EU	SA815EA	Installation of Compudex, Inc. Model TJ10-HP automatic fuel range computer.	EA	25760	Compudex, Inc. P.O. Box 93 Morristown, PA 19404
H.P. 137 MK1; T.C. A21EU	SA827EA	Relocation of fire-wall fuel and hydraulic system shut-off valves. Amended 6/25/70.	EA	18750	Butler Aviation-Friendship, Inc. Subsidiary of Butler Aviation International, Inc. Friendship Int'l Airport, MD 21240
H.P. 137 MK1; T.C. A21EU	SA1707SW	Three-place side facing couch. Issued 8/1/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA1769SW	Single seat. Issued 12/6/73.	SW	68146	Jack M. Riley, Jr. P.O. Box 5247 Waco, TX 76708
H.P. 137 MK1; T.C. A21EU	SA2043WE	Installation of instrument panel for day VFR operation.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2074WE	Installation of 18-passenger cabin interior, instruments, and avionics system.	WE	74270	Spartan - Van Nuys 7929 Hayvenhurst Avenue Van Nuys, CA 91406
H.P. 137 MK1; T.C. A21EU	SA2076WE	Installation of Collins AP-104/ FD-109 autopilot - flight director system. Reissued 4/21/70.	CE	24250	Collins Radio Company 5225 "C" Avenue, NE Cedar Rapids, IA 52406
H.P. 137 MK1; T.C. A21EU	SA2115WE	Intallation of observer jump seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
H.P. 137 MK1; T.C. A21EU	SA2250WE	Relocation of fuel and hydraulic shut-off valves (modification found to comply with requirement of AD 70-15-04, Amendment 39-1031). Reissued 10/24/72.	WE	49850	Lear Avia Corporation P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H.P. 137 MK1; T.C. A21EU	SA2293SW	P & W AGL PT6A-34 engines. Issued 7/9/76.	SW	46340	Jetstream, Inc. Box 1132 Waco, TX 76705
H.P. 137 MK1; T.C. A21EU	SA3064WE	The installation of an alternate method of complying with AD 72-23-01 by equivalency. Amended 9/23/75.	WE	11354	Apollo Airways 404 William Moffet Road Goleta, CA 93017
H.P. 137 MK1; T.C. A21EU	SA3136WE	Installation of ice shield on fuselage. Issued 1/19/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017
H.P. 137 MK1; T.C. A21EU	SA3281WE	Modification of cabin and cockpit air distribution system. Issued 10/12/76.	WE	11354	Apollo Airways, Inc. 404 William Moffet Road Goleta, CA 93017
H.P. 137 Mk 1; T.C. A21EU	SA3425WE	Installation of two AiResearch TPE331-3U-303V engines and related changes. Amended 2/2/78.	SW	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101
H.P. 137, MK-1; T.C. A21EU	SA3534WE	Installation of cabin interior arrangement. Reissued 1/16/78.	SW	20580	Century Aircraft Corporation 501 Plaza One Amarillo, TX 79101
HP.137 MK1; T.C. A21EU	SA3598WE	Installation of Abex P/N 40161 Model AP05V-060 hydraulic pump in lieu of original Vickers hydraulic pump. No installation data required. Issued 6/12/78.	WE	71655	Sierra Pacific Airlines 703 Airport Road Bishop, CA 93514
H.P. 137; T.C. A21EU	SA3932WE	Installation of underseat baggage restraint bars. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
B-121 Series 1, 2, 3; T.C. A22EU	SA308EA	Installation of A.R.P. Industries Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
B-121 Series 1, 2, 3; T.C. A22EU	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Beagle B.206 Series 2; A11EU	SA667SO	Installation of Bendix Model M-4C automatic flight control system.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
B206; T.C. A11EU	SA683SO	Installation of Goodrich wheels, brakes, and tires on main landing gears.	SO	58700	Miami Aviation Corporation Hangar 102, Opa Locka Airport Opa Locka, FL 33054

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BRITISH AIRCRAFT CORP., LTD.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BAC 1-11; T.C. A5EU	SA514EA-D	Install Butler Vector Analog Computer System to provide area navigation capability. Amended 11/17/67.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11; T.C. A5EU	SA279NW	Interior arrangement. Issued 4/30/76.	NW	01700	AeroAmerica, Inc. 7777 Perimeter Road Seattle, WA 98108
BAC 1-11; T.C. A5EU	SA634SW	Litton low range radio altimeter.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA660SW	Cockpit voice recorder A-100 and control panel A-152.	SW	17075	Braniff International P.O. Box 35001 Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA792SW	Relocation of LAS 109C flight recorder.	SW	17075	Braniff Airways Love Field Dallas, TX 75235
BAC 1-11; T.C. A5EU	SA973WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
BAC 1-11; T.C. A5EU	SA1213WE	Fairchild A113 cockpit voice recorder and A152A control panel.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11; T.C. A5EU	SA1350SW	Installation of center wing tank fuel system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1432SW	Installation of Collins INS-61B inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11; T.C. A5EU	SA1740SW	Install dual Delco Carousel IV or IVA inertial navigation systems. Reissued 4/18/80.	WE	78490	Tiger Air, Inc. 1888 Century Park East Los Angeles, CA 90067
BAC 1-11; T.C. A5EU	SA1761SW	Dual Collins INS 61B inertial navigation systems. Reissued 3/20/74.	GL	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11; T.C. A5EU	SA2365SW	Modification of Marston heat exchanger. Issued 10/5/76.	SW	52068	LORI 501 South Lansing Tulsa, OK 74120
BAC 1-11; T.C. A5EU	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, and EL-104B in emergency slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
BAC 1-11; T.C. A5EU	SA2709SW	Installation of heat exchanger. Issued 1/23/78.	SW	52068	LORI 510 South Lansing Tulsa, OK 74120
BAC 1-11, 200 Series; T.C. A5EU	SA1200EA	Installation of cabinet assembly. Issued 7/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
BAC 1-11, 200 Series; T.C. A5EU	SA1947WE	Installation of underseat baggage restraint system. REissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 E. Wardlow Road Long Beach, CA 90807
BAC 1-11, 200 Series; T.C. A5EU	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
BAC 1-11, 200 Series; T.C. A5EU	SA3616WE	Installation of single LTN-51 or LTN-72 inertial navigation system. Issued 3/27/78.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2261WE	Installation of inflatable emergency evacuation slides at forward passenger and service doors. Amended 7/14/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352
BAC 1-11, 200 Series, 400 Series; T.C. A5EU	SA2306WE	Installation of emergency exit lights at forward passenger door, at forward service door, and at both overwing emergency doors. Issued 1/15/71.	WE	44266	International Inflatables Company Div. Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2722WE	Modify aircraft by installation of wing mounted emblem lights. Reissued 2/20/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
BAC 1-11, 200, 400 Series; T.C. A5EU	SA2813WE	Structural modifications. Amended 7/15/74.	GL	61200	National Aircraft Leasing, Ltd. 222 S. Riverside Plaza Chicago, IL 60606
BAC 1-11, 200, 400; T.C. A5EU	SA4143SW	Pitot heat monitor system. Issued 6/16/80.	SW	16850	The BFM Company P.O. Box 7001 Dallas, TX 75209
BAC 1-11 203/AE, 204/AF, 215/AU; T.C. A5EU	SA1021EA	Installation of Collins FPC-75 ground proximity warning system and Bendix ALA-51A radio altimeter system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
BAC 1-11 203/AE, 204/AF, 215/AU T.C. A5EU	SA1207EA	Installation of new shoulder harness to forward flight attendant's seat, wind screen/bulkhead on right side front of passenger compartment. Amended 12/23/80.	EA	80870	USAir, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
BAC 1-11 204/AF, 215/AU; T.C. A5EU	SA840EA	Installation of Technical Standard Order inflatable escape slides. Amended 2/17/71.	EA	07250	Air Cruisers Company Division of Garrett Corporation P.O. Box 180 Belmar, NJ 07719
BAC 1-11 400 Series equipped with Rolls Royce RB 163-25 Spey 511-14 engines; T.C. A5EU	ST846SO	Increase maximum ramp weight to 89,000 lbs., increase maximum take-off weight to 88,500 lbs. and decrease maximum landing weight to 77,200 lbs. Issued 7/1/75.	SO	37885	Bruce Gilman P.O. Box 1372 Vickksburg, MS 39180
BAC 1-11 400; T.C. A5EU	SA3439WE	Installation of single or dual Litton LTN-51 inertial navigation systems. Issued 7/22/77.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91367
BAC 1-11, 401/AK; T.C. A5EU	SA403EA-D	Interior configuration - change from 69 passenger all coach to 16 first class and 49 tourist class with class divider and curtain installation between two sections.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA408EA-D	Installation of maintenance/flight data recording system. Amended 7/19/68.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA422EA-D	Installation of dual Collins AL-101 low range radio altimeter.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
BAC 1-11, 401/AK; T.C. A5EU	SA449EA	Cockpit voice recorder.	EA	60092	Mohawk Airlines, Inc. Oneida County Airport Utica, NY 13503
BAC 1-11, 401/AK; T.C. A5EU	SA553EA-D	Installation of autopilot go-around unit on BAC 1-11. Amended 10/6/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 410AK; T.C. A5EU	SA554EA-D	Install underseat luggage retention device. Amended 12/4/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11 410AK; T.C. A5EU	SA555EA-D	To comply with FAR 25.812(e), a lever lock switch will be installed at a point accessible seat. Amended 4/30/69.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
BAC 1-11, 401/AK; T.C. A5EU	SA2868WE	Installation of executive interior. Amended 7/15/74.	WE	07500	AiResearch Aviation Corporation 6201 W. Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BAC 1-11, 401/AK; T.C. A5EU	SA2971WE	Installation of maximum 1565 gallon auxiliary fuel tanks in forward and aft cargo compartment. Amended 2/12/80.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91505
BAC 1-11 401/AK; T.C. A5EU	SA3431WE	Installation of two couches in aft of aircraft. Issued 6/15/77.	WE	62083	Pacific American Airlines 2800 Clybourn Avenue Burbank, CA 91510
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB, 422/EQ; T.C. A5EU	SA1995WE	Installation of auxiliary fuel tanks in forward and aft cargo compartments. Amended 12/6/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EB; T.C. A5EU	SA2776WE	Installation of dual Litton, LTN-51 inertial navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clytourn Avenue Burbank, CA 91505
BAC 1-11, 401AK, 410AQ, 412A/EB, 414EG, 419EB, 422EQ; T.C. A5EU	SA2873WE	Installation of a single or dual Litton, LTN-104, area navigation system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
BAC 1-11, 401AK, 410/AQ, 419/EP, 412A/EP; T.C. A5EU	SA3567WE	Installation of single or dual Litton LTN-51 or LTN-72 INS. Issued 3/17/78.	WE	51500	Litton Aero Products Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
BAC 1-11, 412A/EB Series, 422EQ; T.C. A5EU	SA2911WE	Installation of relocated engine water injection storage tank. Amended 2/20/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
BAC 1-11, 414EG; T.C. A5EU	SA3819WE	Installation of 1478 gallon auxiliary fuel tank system in the forward and aft cargo compartments. Issued 1/25/79.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

BRITTEN NORMAN, LTD.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BN Series; T.C. A17EU	SA1842WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
BN-2 Series; T.C. A17EU	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
BN-2 Series; T.C. A17EU	SA1675WE	Installation of K S Avionics EGT-2 exhaust gas monitoring system. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
BN-2, BN-2A; T.C. A17EU	SA843EA	Replace existing wheel/brake assemblies. Issued 9/23/70.	GL	39125	Product Support Department Aviation Products Division The Goodyear Tire & Rubber Co. 1144 East Market Street Akron, OH 44315
BN-2, BN-2A, BN-2A6; T.C. A17EU	SA474SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and flight director indicator DH-841( ). Issued 9/2/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
BN-2, BN-2A, BN-2A6; T.C. A17EU	SA1312SW	Automatic flight system AK336 consisting of Century III autopilot and command/automatic electric trim with optional radio and glide slope couplers. Issued 5/13/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2, BN-2A, BN-2A6; T.C. A17EU	SA1351SW	Mitchell automatic flight system AK 338, consisting of Century I with optional tracker. Issued 7/26/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2, BN-2A, BN-2A6; T.C. A17EU	SA2455WE	Installation of air conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
BN-2, BN-2A, BN-2A-6, -2A-8, -2A-9; T.C. A17EU	SA2243WE	Installation of Rajay turbocharged Lycoming O-540-E4C5 engines. Amended 3/16/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
BN-2, -2A, -2A-6, -2A-8, -2A-9, -2AMKIII; T.C. A17EU. A29EU	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BN-2, -2A, -2A-6, -2A-8, -2A-9, -2AMKIII; T.C. A17EU. A29EU	SA489EA	Installation of carburetor ice detection system 107AP-12 or 107AP-24 manufactured by A.R.P. Industries, Inc. in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BN-2, -2A, -2A-2, -2A-6, -2A-8; BN-2A, MK.III; T.C. A17EU, A29EU	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BN-2, -2A, -2A-2, -2A-6, -2A-8; BN-2A, MK.III: T.C. A17EU, A29EU	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
BN-2, -2A, -2A-2, -2A-3, -2A-6, -2A-8, -2A-9, -2A-20, -2A-21, -2A-26, -2A-27; T.C. A17EU	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 10/15/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
BN-2, -2A, -2A-2, -2A-3, -2A-6, -2A-8, -2A-9, -2A-20, -2A-21, -2A-26, -2A-27; T.C. A17EU	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 10/15/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
BN-2, BN-2A, -2A-2, -3, -6, -8, -9, -20, -21, -26, -27, BN-2B-20, -21, -26, -27; T.C. A17EU	SA874EA	Installation of Radome Kit No. 3082KX. Amended 1/21/81.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
BN-2A-3, -9, -21; T.C. A17EU	SA3041SW-D	Mitchell automatic flight system AK518 consisting of Century III autopilot with optional command/automatic electronic pitch trim, radio, and glide slope couplers. Issued 1/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2A Mk III; T.C. A29EU	SA3056SW-D	Mitchell automatic flight system AK533 consisting of Century III autopilot with command/automatic electronic pitch trim system and optional radio coupler and glide slope coupler. Issued 5/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2A Mk III; T.C. A29EU	SA3073SW-D	Mitchell command electric trim system. Issued 9/15/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
BN-2A-6; T.C. A17EU	SA73NW	Remove left rear cabin entrance door. Issued 3/27/74.	NW	49240	La Grande Air Service Route 2, Box 2546 La Grande, OR 97850
BN-2A-6; T.C. A17EU	SA693CE	Install AC induction air filter AAF-104. Amended 11/3/73.	GL	00750	A C Spark Plug Division General Motors Corporation Flint, MI 48556
BN-2A-21; T.C. A17EU	SA1053EA	Installation of air polution sampling and analysis equipment and doppler navigation system. Amended 12/20/78.	EA	29998	DeVore Aviation Corporation 206 Newton Road Plainview, NY 11803

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
150 thru 150M, A150K, L, M; 170, 170A, 170B; 172 thru 172N; 177B; 177RG; 180 thru 180J, K; 182 thru 182Q; 185 thru 185E, A185E; A185F, R172K; 206, P206 thru P206E, TP206A thru TP206E, TU206A thru TU206E, U206 thru U206G; TU206A thru TU206G, TP206A thru TP206E, 207, 207A, T207A, T207; 210 thru 210F; 210K, L, M, T210K, L, M, 336; 337 thru 337F; T337B thru T337F; T.C. 3A19, A-799, 3A12, A13CE, 5A6, 3A13, 3A24, A4CE, A16CE, 3A21, A2CE, A6CE, A20CE, 3A17	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 11/30/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
150, A thru G; 172, A thru H; 175, A, B, C; 177; 180, A thru H; 182, A thru K; 185, A A thru E, A185E; 190; 195 A & B; 206, P206, U206, P206A, U206A, TP206A, TU206A, P206B, TP206B, TU206A; U206B, TU206B, P206C, U206C, TP206C,206C; 210, A thru G, T210-F, -G, 210-5(205)-5A(205A); 336; 337 A, B, C, T337C; T.C. 3A19, 3A12, 3A17, A13CE, 5A6, 3A13, 3A24, 790, A4CE, 3A21, A2CE, A6CE	SA1261WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Subsidiary Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
150, 150A, B, C, D, E, F, G. H, J, K, A150K; T.C. 3A19	SA1346CE	Chrome plate brake disc installation. Amended 9/6/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
150, 170, 172, 175, 180, 182, 185 Series; T.C. 3A19, A-799, 3A12, 3A17, 5A6, 3A13, 3A24	SA1455WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reid 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
150, 170, 175, 180, 182, 185 Series; T.C. 3A19, A-799, 3A17, 5A6, 3A13, 3A24	SA1473WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
150; 170; 172; 175; 177; 180; 182; 185; 190; 206; 195 Series; 210 Series; 310 Series; 320; 336; 337; 401, 401A, 402, 411, 411A, 421; T.C. 3A19, 799, 3A12, 3A17, A13CE, 5A6, 3A13, A9CE, 790, A4CE, 3A21, 3A10, 3A25, A2CE, A6CE, A7CE	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 6/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
150, 150A thru 150H, J; T.C. 3A19	SA1944WE	Installation of Madras wing tips. Amended 4/23/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
150 thru 150L; T.C. 3A19	SA1977WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
150, 150A thru 150E; T.C. 3A19	SA2053WE	An adjustable lateral trim capability through spring bungee control of aileron per Strato Engineering Company. Reissued 5/23/73.	WE	25940	Consulting Aerospace Engineers 1845 Empire Burbank, CA 91504
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, A150L, A150M; T.C. 3A19	SA2850SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams c/b/a Bush Conversions P.O. Box 431 Udall, KS 67146

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
150; 170; 172; 175; 177; 180; 182; 185; 190, 195; 206; 210; 310; 320; 336; 337; 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A19, 799, 3A12, 3A17, A13CE, 5A6, 3A13, A9CE, 790, A4CE, 3A21, 3A10, 3A25, A2CE, A6CE, A7CE	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm).	WE	48750	K S Avionics 18145 Judy Street Castro VAlley, CA 94546
150 thru 150K; T.C. 3A19	SA2119WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
150, 150A thru 150H; 150J, 150K, A150K, 150L, A150L; T.C. 3A19	SA2219WE	Installation of Filtrator Company engine crankcase breather and vacuum pump air-oil separator. Reissued 7/10/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route 1, Box 172D Leesburg, FL 32748
150, 150A thru 150H, 150J, K, L; T.C. 3A19	SA2790WE	Installation of angle of attack indicator. Issued 12/10/73.	WE	78470	Thompson Aircraft Company 8219 Billy Mitchell Drive Santee, CA 92071
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M, 152, L, M, 152, A152; T.C. 3A19	SA3112WE	Installation of flap slot closures. Amended 7/19/77.	WE	78450	Thermal Aircraft Company 56 - 850 Thermal Street Thermal, CA 92274
150, 150A, B, C, D, E, F, G, H, J, K, L, M, A150K, L, M, 152, A152; T.C. 3A19	SA3345WE	Recognition light installation on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
150, 150A, B, C, D, E, F, G, H, J, K, A150L, A150M, 150M, 152, A152; T.C. 3A19	SA4065SW	Metal chip detector in engine oil. Issued 12/4/79.	SW	02323	Aero Logistics International P.O. Box 34395 Dallas, TX 75234
150, 150D thru H, 150J, K, L, M; T.C. 3A19	SA3037SW-D	Automatic flight system AK457 consisting of Century I autopilot with optional omni tracker. Issued 1/17/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
150C, 150D, 15, 150F, 150G, 150H, 150J, 150K, 150L; T.C. 3A19	SA2687WE	Installation of protective device on fuel tank vent line. Issued 5/17/73.	WE	68516	S. Harry Robertson Research Engineers 8002 E. Cypress Street Scottsdale, AZ 85257
150D thru G; 172D thru H; 182A thru L; 206, P206, -A, -B, U206, -A, -B, TU206A, -B, TO206A, -B; 210, D thru F, T210F; 310 D thru P; 320 D, E, F; 337A; 411; T.C. 3A19, 3A12, 3A13, A4CE, 3A21, 3A10, 3A25, A6CE, A7CE	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs SA603SW, SA606SW, SA607SW, SA621SW, SA624SW, SA637SW, SA667SW, SA669SW, SA675SW, SA681SW, SA709SW, SA727SW, SA737SW, SA789SW, SA795SW, SA658SW, SA668SW.	SW	60000	EDO-AIRE Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
150D thru H, J, K, L, M, A150K, A150L; M; T.C. 3A19	SA1809WE	Installation of one twelve-gallon auxiliary fuel tank in each outboard wide panel. Amended 4/20/77.	WE	37580	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
150D thru 150K; T.C. 3A19	SA2191WE	Installation of recontoured wing leading edge, stall fences, and drooped ailerons in flaps down mode. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98004
150D thru H, J, K, L, M, A150K, A150L; M; T.C. 3A19	SA2192WE	Installation of recontoured wing leading edge, stall fences, and drooped ailerons in flaps down mode. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
150D, E, F, G, H, J, K, L utility category; T.C. 3A19	SA3733WE	Installation of a special door (right hand side only) to facilitate aerial photography. Issued 9/6/78.	SW	26718	Robert M. Craig 131 Burwell Road Highland, TX 77562
150E, F, G; 172 thru 172D, F, G, H, M; 175A, B, C; 177; 180A thru H; T.C. 3A19, 3A12, 3A17, A13CE, 5A6	SA1431WE	Installation of rudder trim system. Amended 4/2/78. tive flight control sealed drawings. Amended 3/15/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
150F; T.C. 3A19	SA287GL	Installation of Lycoming O-320-D2B engine and McCauley Model 1C172/TM propeller using the existing installation hardward on an aircraft previously modified in accordance with STC SA572CE. Issued 12/15/78.	GL	71505	Max L. Shanklin 1769 Rooker Road Mooresville, IN 46158
150F, G, H, J; T.C. 3A19	SA221GL	Installation of wheel replacement type skis, FluiDyne all metal (TSO approved) Model A2000A main skis, FluiDyne Model AT2000A tail ski. Issued 2/14/78.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
150F thru K; T.C. 3A19	SA2035WE	Installation of Aerial photographic camera kit serial No. 101. Amended 7/17/70.	NW	34824	Federal Water Pollution Control Administration Pacific Northwest Water Laboratory 200 S.W. 35th Street Corvallis, OR 97330
150F, G, H, J, K; T.C. 3A19	SA2846SW	Conversion from trigear to conventional gear configuration and reconversion to trigear. Issued 9/8/78.	SW	28000	Custom Craft, Inc. 234 West Turbo Drive San Antonio, TX 78216
150F and subsequent, A150 and subsequent, 152, A152; T.C. 3A19	SA1615CE	Quick drain in fuel line at tee fitting forward of fuel selector valve. Issued 11/19/80.	CE	84955	Wells Aircraft, Inc. Municipal Airport P.O. Box 858 Hutchinson, KS 67501
A150K, A150L; T.C. 3A19	SA1395SW	Revise fuel and oil system for inverted flight. Issued 11/24/71.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
152; T.C. 3A19	SA1000NW	Installation of Lycoming O-235-L2C (modified) (SE792NW) engine, McCauley 1A103/TCM 6958 propeller. Issued 8/18/80.	NW	16859	Kennis G. Blackman Building C-52-1 Paine Field, WA 98204
152; T.C. 3A19	SA1219EA	Installation of a Sensenich Model 72CKS6-0-56 or -54 metal propeller and a S72CK spinner assembly. Issued 1/20/81.	EA	70850	Sensenich Corporation P.O. Box 1168 Lancaster, PA 17600
152, 152A; T.C. 3A19	SA4057WE	Installation of a muffler and exhaust heat exchanger. Issued 4/16/80.	WE	35725	Flight Research, Inc. Hangar 61, Mojave Airport Mojave, CA 93501
A152; T.C. 3A19	SA1384CE	Install Lycoming 0-320-E2D engine and McCauley 1C172TM7458 propeller. Issued 11/11/77.	CE	12777	Avcon Industries 1006 W. 53rd Street N. Wichita, KS 67204
170 Series; T.C. 799	SA1-13	Recovering of wings with metal except ailerons and flaps.	GL	37182	General Aviation, Inc. P.O. Box 232 Lost Nation Airport Willoughby, OH 44094
170 Series; T.C. 799	SA1-107	69A103 gyro stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
170 Series; T.C. 799	SA1-240	Lycoming O-435-C engine and Hartzell HC-12X20-8D/8433-6 or HC-12X20-5C/8433-6 propellers.	NE	37050	Fulton Conversion Company Southbury, CT 06488
170 Series; T.C. 799	SA1-245	Lycoming O-340-A1A engine and Hartzell HC-82XL-1D/8433-12 propeller on aircraft with Edo 89-2000 floats.	NE	79952	Turner Aviation Company, Inc. Turner, ME 04282
170 Series; T.C. 799	SA1-316	Dart I-M turn control unit.	EA	61400	Navigation Devices, Inc. P.O. Box 1107 Binghamton, NY 13902
170 Series; T.C. 799	SA1-416	Lube oil filter. Amended 9/11/67.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
170 Series; T.C. 799	SA1-647	Leading edge landing lights.	EA	72100	Skycraft Design, Inc. Mercer County Airport West Trenton, NJ 08628
170 Series; T.C. 799	SA3-53	Model 3000 main and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-159	C-3000 main and AWT 2500A or CT-3000 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
170 Series; T.C. 799	SA3-329	C-3000 main ski and AWT 2500A tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-339	C-3000 wheel ski on airplanes having a cross-wind wheel utilizing a 6.00-6 tire.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170 Series; T.C. 799	SA3-451	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1504 Gretchen Wichita, KS 67202
170 Series; T.C. 799	SA3-695	Dacron fabric on wings.	GL	30518	Downer Aircraft Company Alexandria, MN 56308
170 Series; T.C. 799	SA4-7	Recovering of wings with metal skin. Amended July 1973.	WE	73000	Leo F. Smith & Company, Inc. 225 South Bent San Marcos, CA 92069
T170 Series; T.C. 799	SA4-11	Recovering of wings with metal except flaps and ailerons.	WE	02620	Aero Sales & Service, Inc. Chandler Field Fresno, CA 93721
170 Series; T.C. 799	SA4-28	Conversion to tricycle gear type.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170 Series; T.C. 799	SA4-55	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170 Series; T.C. 799	SA4-226	Metal skin on wings.	WE	18275	Frank A. Burdick 43316 N. 20th Street, W. Lancaster, CA 93534
170 Series; T.C. 799	SA4-486	Glass cloth with resin applied.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
170 Series; T.C. 799	SA4-802	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
170 Series; T.C. 799	SA4-993	Full flow filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
170 Series; T.C. 799	SA4-1062	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
170 Series; T.C. 799	SA4-1096	Eonite covering on wings.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
170 Series; T.C. 799	SA5-44	Conversion of aircraft for parachute jumping operations.	AL	14900	Barton Air Service 1700 E. Fifth Avenue Anchorage, AK 99500
170 Series; T.C. 799	SA15CE	Dry vacuum pump and vacuum system 113A6.	GL	03760	Airborne Mechanisms Division Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
170 Series; T.C. 799	SA235SO	Recovering of wings with .020 alclad 2024-T3 aluminum.	SO	43300	Hudson Aircraft Service P.O. Box 2471 W A S Tallahassee, FL 32302
170 Series; T.C. 799	SA236WE	Cessna 210 wing tips 12230000-1 and -2.	RM	84394	Donald H. Wagner P.O. Box 267 Grand Junction, CO 81501
170 Series; T.C. 799	SA351WE	Pneumatic pitch assist PC-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
170 Series; T.C. 799	SA544CE	Installation of Flight Systems Model 500B white strobe beacon.	GL	35727	Flight Systems P.O. Box 62 Wheeling, IL 60090
170 Series; T.C. 799	SA1008WE	Poly-Fiber covering of both wings. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
170, 170A, 170B; T.C. 799	SA2-224	Windshield manufactured in accordance with Luminous Plastics, Inc. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
170, 170A, 170B; T.C. 799	SA23GL	Installation of wheel replacement skis Model M2000, M3000. Reissued 1/13/76.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapid, MN 56470
170, 170A, 170B; T.C. 799	SA135CE	Lycoming O-320-A1A, -A1B, -A3A, -A3B, or O-320-B1A, -B1B, -B3A, or B3B engine, Hartzell HC-82X or -A2X Series propellers with 7636D-4 blades and Woodward 210080 governor. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170, 170A, 170B; T.C. 799	SA196NW	Installation of blown bubble, one-piece, clear plexiglass windshield. Issued 7/10/75.	NW	71506	Jack Shannon 8451 S.E. 39th Mercer Island, WA 98040
170, 170A, 170B; T.C. 799	SA210GL	Installation of Great Lakes Aero Products windshield P/Ns W-2055, W/T-2055 or W/G-2055. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
170, 170A, 170B; T.C. 799	SA224AL	Installation of L-2500A or L-3000 skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
Cessna 170, 170A, 170B; T.C. 799	SA632AL	Install McCauley 1A175 7DM80 propeller.	AL	08492	Alaska Propeller Specialists, Inc. 5251 Lakeshore Drive Anchorage, AK 99503
170, 170A, 170B, 172, 172A; T.C. A-799, 3A12	SA152NW	Installation of deck and glare shield (with and without instrument lights). Issued 1/13/75.	NW	70384	R.J. Schroers 4479 139th Avenue, S.E. Bellview, WA 98006
170 thru 170B, 172 thru 172K, P172D, R172E, R172F, 175 thru 175C, 180 thru 180H, 182 thru 182M, 185 thru 185E, A185E; T.C. 799, 3A12, 3A17, 5A6, 3A13, 3A24	SA605CE	Install O'Neill Model "Ultralite" 7G aircraft.	GL	61850	O'Neill Airplane Company 791 Livingston Carlyle, IL 62231
170, 170A, B, 172, 712A thru 172N, 180, 180A thru 180K, 182, 182A thru 182Q, 185, 185A thru 185E; T.C. A-799, 3A12	SA933NW	Installation of Blancher Model 101 stowable seats in place of second row seats. Issued 5/16/80.	NW	18195	Bud's Aero Specialties, Inc. P.O. Box 190 Eatonville, WA 98328
170, -A, -B; 172, -A thru -H; 175, -A, -B, -C, P172D, R172E (T41B); *177; 180, -A, -B, -C, -D, -E, -F, -G, -H; 182, -A, -B, -C, -D, -E, -F, -G, -H, -J, -K; 185, -A, -B, -C, -D, -E, A185E; 210, -A, -B, -C, -D, -E, -F, T-210F, 210G, T-210G, 210-5(205), 210-5A(205A); 401, 402, 411, 411A; T.C. A-799, 3A12, 3A17, A13CE, 3A13, 3A24, 3A21, A7CE *Approved anti-collision light system is required.	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
170, 170A, 170B; T.C. A-799	SA2472WE	Installation of strobe light systemNW with flashtube or rudder tip and power supply in fuselage. Issued 2/9/72.		70384	R.J. Schroers 4479 139th Avenue S.E. Bellevue, WA 98006
170, 170A, 170B; T.C. A-799	SA3715WE	Installation of vertical tail floodlight. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
170A; T.C. 799	SA1973WE	Installation of Hanna-Aero Corp. voltmeter P/N 1305.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
170A, 170B; T.C. 799	SA3-13	Install 170 hp Lycoming O-340-A1A engine and Hartzell HC-82XL-1DB/8433-12 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
170A, 170B; T.C. 799	SA3-672	Lycoming O-360-A1A, A1D or B1B engine and McCauley 2D36C14-X/78KM-4 propeller or Lycoming O-360-A1A and A1D engines with Hartzell HC-C2YK-1A/7666A-2 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170A, 170B; T.C. A-799	SA325GL	Installation of fuel tank caps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
170A, 170B (Landplane only); T.C. 799	SA421CE	Lycoming O-360-A1A or O-360-A1D 180 hp engine, O-360-B1B 168 hp engine and constant speed propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
170A, 170B; T.C. 799	SA749CE	Install Hartzell propeller model HC-C2YK-1A/7666A.	CE	12775	Avcon Industries, Inc. Route 1, Box 204A Augusta Municipal Airport Augusta, KS 67010
170A, 170B (landplanes, normal category only); T.C. A-799	SA806CE	Installation of Lycoming engine model O-360-A1A and McCauley propeller model HC-C2YK-1B/7666A-2. Amended September 1976.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 Wichita, KS 67204
170A, 170B; T.C. 799	SA989CE	Installation of STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
170A, 170B; T.C. A-799	SA1073CE	Installation of wing leading edge cuffs, Cessna drooped wing tips, stall fences, and aileron gap seals. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
170A, 170B (Normal Category); T.C. A-799	SA2454WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
170A, 170B (landplane only normal category); T.C. A-799	SA3797WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision, muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29075	Del-Air P.O. Box 746 Strathmore, CA 93267
170A, B, 172A thru 172M, 175, 175A thru 175D; T.C. A-799, 3A12, 3A17	SA115NW	Modification of R.H. Door and the addition of a jump seat. Issued 5/24/74.	NW	18260	Charles P. Bunch 1211 Donovan Avenue Bellingham, WA 98225
170A, B, 172, 172A thru 172I, K, I, M, N, 175 thru 175C; R172K, 172RG; T.C. 799, 3A12, 3A17	SA1614WE	Installation of one 12-gallon auxiliary fuel tank in each outboard wing panel. Amended 6/27/80.	WE	35746	Flint Aero 336 Front Street El Cajon, CA 92020
170B; T.C. 799	SA111NW	Installation of McCauley 1A175-DM propeller with Cessna 0550162 spinner on Continental C-145 series and O-300 series engines. Reissued 6/28/74.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
170B; T.C. 799	SA602AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA602AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	AL	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA603AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA603AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	AK	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502
170B; T.C. 799	SA604AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577 AND
170B; T.C. 799	SA604AL	Addition of Pee Kay Model 2300 floats. Amended 4/1/77.	EA	08500	AK Sky-Craft Company, Inc. Box 6206 Anchorage, AK 99502

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
170B; T.C. 799	SA1417SW	Mitchell automatic flight system AK358 consisting of Century I autopilot with optional omni tracker. Issued 1/10/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
170B; T.C. A-799	SA1490CE	Installation of flap and aileron gap seals.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
170B (Landplane only, Normal & Utility Category); T.C. A-799	SA2100WE	Installation of contoured wing leading edge and aileron gap cover. Reissued 1/18/77.	WE	65700	Marshall E. Quackenbush P.O. Box 235 Inyokern, CA 93527
170B; T.C. A-799	SA2851SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
170B (Landplane only, Normal & Utility Category); T.C. A-799	SA3318WE	Installation of flap gap closures. Issued 1/5/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
170B, 172 A, B, C, 175, A, B, C, 180, A, B, C, D, F, 182, A, B, C, D; T.C. A-799, 3A12, 3A17, 5A6, 3A13	SA1-612	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
170B, 172, 172A, 172B, 172C, 172D; T.C. A-799, 3A12	SA93EA	Installation of Monitair angle of attack system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
170B; 172, 172A thru H, 175, 175A, B, C, 180, 180A thru H, 182, 182A thru D; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA175EA	Installation of wing struts modified to include Wings With Springs Model 200 hydraulic-pneumatic shock absorbers and associated airframe modifications. Amended 8/17/77.	EA	86500	Wings With Springs, Inc. Box 495, R.D. 3 Latrobe, PA 15650
170B, 172, 172A, B, C, D, E, F, G, H, I, K, L, M, 172M, 175, 175A, B, C; T.C. A-797, 3A12	SA293NW	Installation of Franklin 6A0350-Ce engine, McCauley 2A31C21/84S06 propeller using Kit No. 20690 as per STC SA360EA. In addition, installation of Hartzell HC-C2YF-1BF/F8459-4 to -8 conjunction with same engine. Issued 6/22/76.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98661
170B, 172, 172A; T.C. A-799, 3A12	SA360EA	Installation of Franklin Engine Co., Inc. Model 6A-335-B engine with McCauley 2A31C21/84S-8 propeller and new engine mount and associated components. Amended 6/19/70.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
170B, 172 thru 172L; T.C. A799, 3A12	SA499NW	Installation of Robertson Aircraft STOL kit with Robertson leading edge cuff, fence, Cessna wing flap filler panel. Issued 8/29/77.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98660
170B, 172B thru M, 175, 175A thru C; T.C. A797, 3A12, 3A17	SA637NW	Instllation of AC oil filter assembly OF-104A. Issued 7/13/78.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98661
170B; 180; 185; T.C. 799, 3A24, 5A16	SA1971WE	Installation of Model ARB-3 Automatic Downed Aircraft Marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue, Box 822 Fort Collins, CO 80521
170B, 172, 180, 182, 185, 210 Series; T.C. A-799, 3A12, 5A6, 3A13, 3A24, 3A21	SA4120SW	Add sheet metal flap seals and neoprene flexible aileron gap seals. Issued 5/5/80.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
170, 172 Series T.C. 799, 3A12	SA4-1404	Vacuum system 121 and 121A. (Eligible only on engines with dampened crankshafts).	WE	40685	Marlin and Myron Harms 10828 Burl Avenue
170, 172 Series; T.C. 799, 3A12	SA318WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
170, 172 Series; T.C. 799, 3A12	SA429WE	Exhaust pipe extensions LG-100.	WE	39463	Lloyd M. Green 619 W. Roses Road San Gabriel, CA 91776
170, 172 Series; T.C. 799, 3A12	SA672SW	Cessna 305(L-19) wings.	SW	76737	James A. Summersett, Jr. 418 Redcliff Drive San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
170, 172 Series; T.C. 799, 3A12	SA733WE	12.7-gallon auxiliary fuel tank.	WE	05600	Aircraft Modification and Repair 20331 Hesperian Boulevard Hayward, CA 94541
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA1-426	Auxiliary seat in baggage compartment.	NE	84950	William A. Welch Boyce Road, RD-1 Danbury, CT 06810
170, 172, 175 Series; T.C. 799, 3A12, 3A17	SA1-516	Griswold lateralizer and heading lock.	NE	39800	Herbert Haer 80 Federal Street Boston, MA 02109
170, 172, 175 Series; T.C. 799, 3A12, 3A17	SA1-545	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
170, 172, 180, 182 Series; T.C. 799, 3A12, 5A6, 3A13	SA3-75	Grimes rotating anti-collision light D-7080-1-12.	GL	59360	Mid States Aviation Corporation Sky Harbor Airport Northbrook, IL 60062
170, 172, 175, 180 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA3-333	Installation of Doyn fiberglass wheel fairings. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
170, 172, 175, 180 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA4-367	Super automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
170, 172, 175, 180 Series; T.C. 799, 3A12, 3A17, 5A6	SA4-620	Baggage door on left side of fuselage.	WE	08262	The Air Oasis 2601 E. Spring Street Long Beach, CA 90801
170, 172, 180, 182; T.C. 799, 3A12, 5A6, 3A13	SA4-662	Camera pod.	WE	52710	Clifton G. McBride 620 Rollingwood Drive Vallejo, CA 94590
170, 172, 175, 180, 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA4-676	RDF-2 radio direction finder.	WE	70275	Savage Industries, Inc. 3125 N. 29 Avenue Phoenix, AZ 85000
170, 172, 175, 180, 182; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA5-12	Rear canvas hammock seat.	AL	05958	Aircraft Rebuilders 1803 Lake Otis Road Anchorage, AK 99500
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA81WE	Aileron and rudder trim controls.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA158CE	Cessna wing tips and attached lights 1223000-1 left, 1223000-2 right tips, and 1423006-12 left, 0423006-13 right lights, or an equivalent.	GL	70385	Schott Aviation, Inc. Baldwin Field Quincy, IL 62301
170, 172, 175, 180, 182, 185 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13, 3A24	SA238SW	Cargo door. Reissued 4/6/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
170, 172, 175, 180, 182 Series; T.C. 799, 3A12, 3A17, 5A6, 3A13	SA765WE	SP51463-1A speedplates.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
170, 172, 180, 182, 185 Series; T.C. 799, 3A12, 5A6, 3A21, 3A24	SA981WE	Two detachable folding rear	WE	59730	Missionary Aviation Fellowship P.O. Box 32 Fullerton, CA 92632
170, 180 Series; T.C. 799, 5A6	SA1-188	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
170, 180 Series; T.C. 799, 5A6	SA3-468	CF-3000 main wheel skis and AWT 2500A or CT-3000 tail wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
170, 180 Series; T.C. 799, 5A6	SA463WE	Jump door 62-500.	NW	72250	Skymotive, Inc. Route 1, Box 32 Snohomish, WA 98290
172 Series; T.C. 3A12	SA1-9	69A115 gyro-stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
172 Series; T.C. 3A12	SA1-116	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
172 Series; T.C. 3A12	SA1-438	Lycoming O-360-A1A engine and McCauley 2D36C14/78 KM-4 propeller with Woodward 210105 AA governor.	NE	90160	Albert E. Zotack 295 First Avenue Stratford, CT 06497

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172 Series; T.C. 3A12	SA3-11	Propeller installations - Two-position controllable, hub 2B-36C7, blades 78K-2 or 78K-4.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45401
172 Series; T.C. 3A12	SA3-82	Retractable lifting handles Model H, P/N 50-9.	GL	87750	Woychik Aircraft Equipment Middleton, WI 53562
172 Series; T.C. 3A12	SA3-89	Equipment shelves and Grimes D-7080 rotating beacon.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, Il 62705
172 Series; T.C. 3A12	SA3-90	Lear ADF loop and housing.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
172 Series; T.C. 3A12	SA3-107	Rudder trim system.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
172 Series; T.C. 3A12	SA3-108	Single axis automatic pilot A-2 or A-3.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
172 Series; T.C. 3A12	SA3-126	Lycoming O-340-A1A engine and Hartzell HC-82XG-1DB/8433-12 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172 Series; T.C. 3A12	SA3-179	A3500A or A2500A main skis and NA1200A nose skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-256	Main ski AWB2500A and nose wheel ski AWN1200.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-355	C3000 main ski and AWN1200 nose wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-614	Model 3000 main skis and Model 2000 nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA3-655	Wheel fairings.	RM	55700	Marsh Flying Club, Inc. 812 E. 34th Street Sioux Falls, SD 57101
172 Series; T.C. 3A12	SA3-690	Installation of Doyn swept-tail asembly kit 1400. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172 Series; T.C. 3A12	SA4-40	Automatic rudder control.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
172 Series; T.C. 3A12	SA4-198	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
172 Series; T.C. 3A12	SA4-531	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
172 Series; T.C. 3A12	SA4-602	Autopilot. Reissued October 1973.	WE	17492	Brittain Industries, Inc. 12027 S. Prairie Avenue Hawthorne, CA 90250
172 Series; T.C. 3A12	SA4-686	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
172 Series; T.C. 3A12	SA44SO	Cessna L-19 wing conversion.	SO	55600	Marrs Aircraft Avon Park, FL 33825
172 Series; T.C. 3A12	SA64CE	Sky-lite B-100 beacon light.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
172 Series; T.C. 3A12	SA88CE	C-3000 main skis and AWN-1200A nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
172 Series; T.C. 3A12	SA94CE	Removal of right cabin door.	GL	72116	Skylane Flying Service, Inc. 2029 Allens Lane Evansville, IN 47708
172 Series; T.C. 3A12	SA117EA	Flow lube oil filter PB 55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172 Series; T.C. 3A12	SA242EA	40-0040 and 40-0043 supplemental light system.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
172 Series; T.C. 3A12	SA313SO	Federal FS103 autopilot.	SO	00078	A & E Service McCollum Airport Marietta, GA 30060
172 Series; T.C. 3A12	SA414SW	Jump step or mud guard on right landing gear.	SW	73030	Curtis J. Smith, Jr. Route 2, Box 314 Breaux Bridge, LA 70517
172; T.C. 3A12	SA531NW	Installation of windshield. Issued 10/12/77.	NW	71506	Jack Shannon 215 Terminal Building Boeing Field Seattle, WA 98108
172 Series; T.C. 3A12	SA533CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
172 Series; T.C. 3A12	SA603SW	AK191 Century II autopilot and AK192 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172 Series; T.C. 3A12	SA792WE	Lycoming O-360 Series engines and Sensenich M67EMM propellers.	NW	53510	McKinzie Aircraft Repair, Inc. 1300 N. 26 Street Springfield, OR 97477
172 Series; T.C. 3A12	SA861WE	Pilot and passenger restraint harness.	WE	62125	Pacific Scientific Company 1346 S. State College Boulevard Anaheim, CA 92803
172 Series; T.C. 3A12	SA1078WE	Franklin 6A-335-B engine with McCAuley 2A31C/84S-6 propeller using EDO 89-2000 floats.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172 Series; T.C. 3A12	SA1308WE	Installation of Brittain Model CSA-1 stability Augmentation System.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
172 Series; T.C. 3A12	SA1468WE	Installation of Brittain Model B2C Autopilot System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172 Series; T.C. 3A12	SA1677SW	Wing leading edge cuff. Issued 6/20/73.	SW	73850	Southern Aircraft Corporation P.O. Box 78 Page, OK 74939
172 Series; T.C. 3A12	SA1806WE	Installation of Brittain Industries B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172 Series; T.C. 3A12	SA3072WE	Installation of emergency warning system. Issued 7/23/75.	WE	77274	Systems Management Associates, Inc. P.O. Box 957 Palo Alto, CA 94302
172, 172A, B, C, D, E, F, G, H; T.C. 3A12	SA3-571	Lycoming O-360-A1D engine, McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1A/7666-2 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
172, 172A, B, C, D, E, F; T.C. 3A12	SA3-664	Install Model 113A6, 200CW-6 or 212CW-6 dry vacuum pump and instrument vacuum system. Amended 7/31/79.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
172, 172A thru 172I, K, L, M, N, P; 182, 182A thru 182N, P; T.C. 3A12, 3A13	SA21GL	Installation of Grimes multi-plexed anti-collision light system. Issued 5/9/73.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
172, 172A, B, C, 175, 175A, B, C, 182, 182A thru E; T.C. 3A13, 3A12, 3A17	SA43EA	Installation of Re-Vue Agency "nite-lite" electronic aerial advertising sign. REissued 3/15/71.	RM	67300	Re-Vue Agency, Inc. 616 East 4th Street Pueblo, CO 80204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172, 172A, 172B, 172C, 172D; 180, 180A, 180B, 180C, 180D, 180E, 180F; 182, 182A, 182B, 182C, 182D, 182E; 185, 185A, 185B, 185C, 185D; 210, 210-5, 210A, 210B, 210C; 310C, 310D, 310E, 310F, 310G, 310H; T.C. 3A12, 5A6, 3A13, 3A24, 3A21, 3A10 (310 Series thru 310H Riley conversion per STC SA212SO.)	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
172, 172A, 172B, 172C; T.C. 3A12	SA211GL	Installation of windshield P/N W-2055, W/T-2055 or W/G-2055 on Cessna 172 and 172A, and P/N W-2056, W/T-2056 or W/G-2056 on Cessna 172B and 172C. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
172, 172A, B, C, D, E, F, G, H, I, K, L, M, N; T.C. 3A12	SA296GL	Convert to conventional landing gear. Amended 11/19/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 172A, B, C, D, E, F, G, H. I, K, L, M, N; T.C. 3A12	SA315GL	Installation of Fluidyne skis. Amended 2/7/80.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 172A, B, C, D, E, F, G, H, I, K, L, M; T.C. 3A12	SA326GL	installation of fuel tankcaps. Issued 7/16/79.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
172, 172D, 172F; T.C. 3A12	SA340NW	Installation of Pee Kay Model 2300 floats. Issued 9/15/76.	NW	70620	Seaplane Flying, Inc. P.O. Box 2164 Vancouver, WA 98661
172, 172A, B, C, D, E, F, G, H Landplanes, 172D, E, F, G, H Floatplanes (EDO 89-2000 floats only.) T.C. 3A12	SA420CE	Lycoming O-360-A1A or A1D engine, McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1B/7666-2 propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172, A thru I; T.C. 3A12	SA729EA	Replacement of existing wheel/brake assemblies with Goodyear wheel/brake assemblies 9543679/95444295.	GL	39125	Aviation Products Division The Goodyear Tire & Rubber Company 1144 East Market Street Akron, OH 44315
172, 172A thru I, K, L, M, N (Landplanes, normal category only); T.C. 3A12	SA807CE	Install Lycoming 180 h.p. engine and constant speed propeller. Amended 1/31/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
172, S/N 17254893 and on; T.C. 3A12	SA864CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
172, 172A thru 172I, 172K, 172L, 172M (S/N 17260759 thru 17265684); T.C. 3A12	SA902CE	Install STOL kit. Amended 2/26/80.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
172 thru 172M; T.C. 3A12	SA910CE	Install STOL kit (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Amended May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
172, 172A, B, C, D, E, F, G, H, I, K, M, N; T.C. 3A12	SA1484CE	Installation of flap and aileron seals. Issued 4/18/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
172, 172A thru 172G (landplanes and float-planes), 172, 172H thru 172L (landplanes only); T.C. 3A12	SA1689WE	Installation of drooped ailerons contoured wing leading edge and wing stall fences. Amended 2/26/71.	NW	68510	Charyl C. Robertson 15209 N.E. 16th Place, Apt. #17 Bellevue, WA 98004
172 thru 172L; T.C. 3A12	SA2002WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
172, 172A thru 172L (normal category); T.C. 3A12	SA2075WE	Installation of Madras Air Service Inc. "Super Tips." Amended 8/16/72.	NW	54000	Madras Air Service, Inc. Route 2, Box 1225 Madras, OR 97741

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172, 172A thru 172L, 175, 175A, 180, 180A 180H, 205, 205A; T.C. 3A12, 3A17, 5A6, 3A21	SA2256WE	Installation of leading edge "cuff" on each wing. Amended 4/29/80.	WE	65700	Marshall E. Quackenbush P.O. Box 2421 California City, CA 93505
172, 172A thru 172G; 182A thru 182N, 206, U206, U206B thru U206E; 210 thru T210F; TU206C, D, E; T.C. 3A12, 3A13, 3A21, A4CE	SA2286WE	Installation of wing leading edge cuff. Amended 3/16/72.	RM	09750	Alpine Aircraft Corporation Route 4, Box 173A Greeley, CO 80631
172, 172A, B, C, D, E, F, G, H, I, K, L; T.C. 3A12	SA2852SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
172, 172A, B, C, D, E, F, G, H, I, K, L, M, N (normal and utility categories); T.C. 3A12	SA3105WE	Installation of flapgap fairing. Amended 8/22/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
172, 172A, B, C, D, E, F (T-41), G, H (T-41A), I, K, L, M, N; T.C. 3A12	SA3338WE	Recognition light installation on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
172, 172A, B, C, D, E, F, G, H, I, K, L; T.C. 3A12	SA3788WE	Installation of the "liftrol" wing spoiler system. Reissued 6/6/80.	WE	23145	Esther E. Cleaves 4542 Norma Drive San Diego, CA 92115
172, 172A thru H (landplane only, normal category); T.C. 3A12	SA3796WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29075	Del-Air P.O. Box 746 Strathmore, CA 93267
172, F172; T.C. 3A12	SA3418WE	Installation of SDI Novastar II combined position/anticollision lighting system. Issued 6/22/77.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
172A Seaplane; T.C. 3A12	SA181GL	Installation of McCauley 1A200/DFA propeller. Issued 6/16/77.	GL	77569	Les G. Taylor 1115 - 19th Street South St. Cloud, MN 56301
172A, B, C, D, E, F, G, H; T.C. 3A12, 3A17	SA18EA	Wet-to-dry vacuum pump conversion kit 300-1. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
172A thru 172M; T.C. 3A12	SA358NW	Installation of Pee Kay Model 2300 seaplane floats. Issued 8/24/76.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
172A - 172F; T.C. 3A12	SA650CE	Installation of Fleet Model 2500 floats. Reissued 12/21/71.	EA	79550	Trifield Associates 560 Daytona Drive Fort Erie, Ontario, Canada
172B, 172C, 172D, 172E, 172F, 172G; T.C. 3A12	SA116SO	Installation of Franklin Model 6A-335-B engine with 2A31C21/84S-8 propeller and new engine mount and new engine mount and associated components only on landplane models. Amended 9/9/68.	EA	36750	Franklin Engine Company, Inc. Subsidiary of Allied Aero Industries, Inc. Old Liverpool Road Syracuse, NY 13208
172B, 172C; 175 thru 175C; 180 thru 180F; 182 thru 182E; 185, 185A, 185B; 210, 210A, 210B, 210C, 210D, 210E; P206; 310 thru 310E; T.C. 3A12, 3A17, 5A6, 3A13, 3A24, 3A21, A4CE, 3A10	SA232EA	Installation of Tactair omni lock model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair model omni lock model OH-4). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
172B, G, 175A, B, C; T.C. 3A12	SA751EA	Installation of winterization kit. Issued 4/21/69.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
172B thru G; T.C. 3A12	SA1334WE	Installation of Franklin 6A-350-C2 engine and McCauley 2A31C/84S-6 propeller. Amended 9/26/68.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
172B thru H; T.C. 3A12	SA1774WE	Installation of Lycoming O-320-E2D engine and McCauley 1C172/MTM7653 propeller.	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172D, P172D, 182E, F, 185, 185A, 185B, 210, 210A; 210B, 210C, 210-5; T.C. 3A12, 3A17, 3A24, 3A21, 3A13	SA17EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
172D, E, F, G, H, I, K; T.C. 3A12	SA319GL	Bolen wheel extenders on Cessna models modified per STC SA296GL. Issued 6/12/79.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172D thru 172K; T.C. 3A12	SA365NW	Installation of Pee Kay Model 2300 seaplane floats. Approval is intended for installation in listed models with Franklin 6A0360-C2 engine installation IAW Seaplane Flying, Inc., STC SA340NW. Reissued 9/19/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
172D, 172E (seaplane); T.C. 3A12	SA596WE	Installation of Doyn Aircraft Company kit per STC SA3-571. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172, E thru L; T.C. 3A12	SA1221SW	Mitchell automatic flight system AK312 consisting of Century I with optional omni tracker. Issued 11/18/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172D thru 172I, K, L; T.C. 3A12	SA1645SW	Mitchell automatic flight system AK403, consisting of Century IIB autopilot with optional radio coupler. Issued 4/25/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172D thru 172K Seaplane Versions; T.C. 3A12	SA1694WE	Installation of Franklin 6A-350-C2 engine, McCauley 2A31C/84S-6 propeller, and Aqua Float Corp., Model 2400, or EDO Corp. Model 248B-2440 floats (Columbia Marine, Inc. Kit #106) for operation on wheels, floats or skis @ 2400 lbs. g.w. (Fluidyne Model 3000 main and 2000 nose skis required for ski operations. Amended and reissued 5/1/70.	EA	36750	Franklin Engine Company, Inc. Sub. Allied Aero Industries, Inc. Old Liverpool Road Syracuse, NY 13208
172D, 172E; T.C. 3A12	SA2268WE	Installation of Brittain Industries B2C flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
172D, E, F, G, H; T.C. 3A12	SA2375SW	Install Lycoming O-320-D2G engine rated for 160 h.p. take-off and 150 METO. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
172D thru M, 177, 177A, B, 177RG, 182L, M, N, 206, C, U206, U206B, D, E, F, TP206A, B, P206A, B, TU206A, B, C, D, E, F, P206E, TP206E, 210D, E, F, I, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE, A20CE, 3A12	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot system. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
172D thru L, 177, A, B, 182L, M, N, 206, U206, B, C, D, E, TU206B, C, D, E, P206A, B, TP206A, B, P206E, TP206E, 210E, D, F, L, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE, 3A21	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot system. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
172D, E, F, G, H, I, K, L, M, 177, A, B, 182E thru N, U206C, D, E, F, TU206C, D, E, F, P206E, TP206E, 210, 210D, E, F, L, 210I, T210L, 337; T.C. 3A12, 3A13, A4CE, A6CE	SA2654WF	Installation of Pathfinder Model P2A( ) autopilot. Amended 7/3/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Road Torrance, CA 90505
172D, E, F, G, H, I, K, L; T.C. 3A12	SA3046SW-D	Automaticght system AK524 consisting of Century IIB autopilot with optional radio coupler. Issued 3/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172F, G, H, I, K, L; T.C. 3A12	SA1311CE	Chrome plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
172G; T.C. 3A12	SA299GL	Installation of Cessna Nav-O-Matic 200A autopilot. Issued 4/2/79.	GL	37077	Galesburg, AP & I R.R. 2, Airport Galesburg, IL 61401
172H; T.C. 3A12	SA204GL	Installation of Avco Lycoming O-320-E2D engine. Issued 12/16/77.	GL	65326	Professional Aviation, Inc. Porter County Airport 3801 Murvihill Road Valparaiso, IN 46383
172H; T.C. 3A12	SA414NW	Installation of Lycoming O-360-A1F6D engine and McCauley propeller. Issued 3/15/77.	NW	70040	Salem Aviation 2680 Aerial Way S.E. Salem, OR 97302
172I, 172K, 172L; T.C. 3A12	SA87NW	Installation of Lycoming O-360-A1A 180 h.p. engine and Hartzell HC-C2YK-1A/7666A-0 propeller. Amended 12/12/74.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
172I, 172K, 172L, 172M seaplane (normal category only); T.C. 3A12	SA332GL	Installation of Lycmoming O-360-A4A engine and McCauley 1A200/DFA propeller. Amended 5/19/80.	GL	77569	Les G. Taylor 1115 - 19th Street South St. Cloud, MN 56301
172I and 172K landplanes and seaplanes EDO 89-2000 (floats only), 172L, 172M, 172N (landplanes) (12 volt only); T.C. 3A12	SA647CE	Install Lycoming O-360-A1A 180 h.p. engine and constant speed propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172I, K, M, R172K (floatplane configuration); T.C. 3A12, 3A17	SA665CE	Installation of Model 2400 Aqua floats. Amended 7/10/79.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
172I, 172K, 172L, 172M; T.C. 3A12	SA992CE	Installation of 10-inch diameter camera hole per Product Development Group, Inc. Issued February 1974.	CE	36000	Floair, Inc. Mid-Continent Airport Wichita, KS 67209
172I, 172K, 172L, 172M, 172N (Seaplane); T.C. 3A12	SA1000EA	Installation of Pee-Kay Model 2300 or B2300 (TSO-C27-2) seaplane floats. Amended 7/19/78.	EA	29998	Pee Kay Float Division Devore Aviation Corporation 206 Newton Road Plainview, NY 11803
172I, 172K, 172L, 172M (Landplane); T.C. 3A12	SA1225CE	Installation of Lycoming O-320-E2D/ STC SE1226CE or O-320-D2G engine and McCauley 1C160/CTM 7557 or 1C160/DTM 7557 propeller. Amended March 1977.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
172I, 172K thru 172N; T.C. 3A12	SA3777WE	Installation of flexible stainless steel oil cooler hoses. Issued 10/31/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
172I, 172K, 172L, 172M, 172N; T.C. 3A12	SA3858WE	Installation of an air/oil separator. Issued 3/2/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036.
R172K; T.C. 3A17	SA1491CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
172K; T.C. 3A17	SA3824SW-D	Mitchell automatic flight system AK730 consisting of Century I autopilot with optional omni tracking system. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172K, 172M (normal category landplane only); T.C. 3A12	SA2575WE	Installation of observer station in rear seat-baggage compartment area, searchlight and dual speakers in bottom of aft fuselage, windows in baggage compartment area (baggage was removed), and a muffler. Amended 1/4/73.	WE	87465	World Associates, Inc. 430 Wilshire Boulevard Suite 204 Santa Monica, CA 90401
172L; T.C. 3A12	SA494SO	Installation of radio equipment rack in instrument panel. Issued 2/18/72.	SO	18400	Burnside-Ott Aviation Training Center 12800 S.W. 137 Avenue Miami, FL 33156

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172L, S/N 17259224 thru 17260758; T.C. 3A12	SA965CE	Installation of Model IU328-001 vacuum pump and IU292-003 suction relief valve. Issued November 1973.	CE	43600	EDO-AIRE Wichita Division 1326 S. Walnut Wichita, KS 67213
172M; T.C. 3A12	SA6NE	Installation of Whelen anti-collision strobe light power supplies, Models HS-41 and HD-42 as direct replacements for Models HS and HD installed in accordance with STC SA615EA or STC SA800EA. Issued 3/21/74.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
172M; T.C. 3A12	SA1798SW	Mitchell Automatic Flight System AK467 consisting of Century IIV Autopilot with optional Radio Coupler. Issued 1/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M; T.C. 3A12	SA1799SW	Mitchell Automatic Flight System AK472 consisting of Century I Autopilot with optional omni tracker. Issued 1/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M; T.C. 3A12	SA2671WE	Installation of upper wing surface face stall fences and aileron gap sealing strips. Issued 3/19/73.	WE	39520	Group One 2915 Earhart Apron Torrance, CA 90505
172M, 172N; T.C. 3A12	SA146GL	Installation of EPA portable enviro pod. Amended 12/10/79.	GL	07696	AFAL/RWF Wright-Patterson AFB, OH 45433
172M, 172N; T.C. 3A12	SA380GL	Installation of Tull microwave landing system airborne equipment. Amended 5/12/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
172M, 172N; T.C. 3A12	SA1211EA	Installation of EPA portable enviro-pod with Tensor-Hasselblad camera configuration. Issued 11/12/80.	EA	78403	Tensor Industries, Inc. 2878 Hartland Road Falls Church, VA 22043
172M, 172N; T.C. 3A12	SA1402CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
172M, 172N; T.C. 3A12	SA3200SW-D	Automaitc flight system AK467 consisting of Century II autopilot with optional radio coupler. Issued 4/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA3201SW-D	Automatic flight sytem AK472 consisting of Century I autopilot with optional omni tracker. Issued 4/7/77.	SW	6000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172M, 172N; T.C. 3A12	SA4080SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
172M, 172N (S/N 17269309 and below); T.C. 3A12	SA4221SW	S-TEC system 60 (two axis) flight guidance system, Model ST-019, with optional flight director steering horizon and vertical speed selector (14 volt system). Issued 10/27/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
172M, 172N (S/N 17269309); T.C. 3A12	SA4230SW	S-TEC system 60 roll flight guidance kit, Model ST-008. Issued 11/12/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
172M, 180J, 182P, A185F, A188B, 188B, U206F; T.C. 3A12, 3A13, 5A6, 3A24, A4CE, A9CE	SA974EA	Installation of L/R wing tip transparent fairing and sensor mounting bracket. Issued 2/26/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
172N; T.C. 3A12	SA168GL	Install Heath Kit Model 01-1154 aircraft digital clock/timer. Issued 4/28/77.	GL	41610	The Heath Company Hilltop Road Benton Harbor, MI 49022
172N; T.C. 3A12	SA584NW	Installation of Edo 689-2130 seaplane floats. Amended 1/8/80.	EA	32625	Edo-Aire, Seaplane Division 65 Marcus Drive Melville, NY 11746
172N; T.C. 3A12	SA1168SC	Instalaltion of Aqua Model 2200 floats. Issued 8/8/80.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172N; T.C. 3A12	SA1324CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/ 7666A-2 propeller. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 North Wichita Station Wichita, KS 67204
172N; T.C. 3A12	SA3301SW-D	Mitchell automatic flight system AK730, consisting of Century I autopilot with optional omni tracking system. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A12	SA3302SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 7/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172N; T.C. 3A17	SA3303SW-D	Mitchell automatic flight system AK732 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
172P, 172Q; T.C. 3A13	SA4197SW	S-TEC system 60 (two axis) flight guidance system, Model ST-011, with optional flight director/steering horizon and vertical speed indicator/selector (14 volt system). Issued 9/9/80.	SW	79463	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
172N; T.C. 3A12	SA4243SW	S-TEC system 60 (two axis) flight guidance system Model ST-025 with optional flight director/steering horizon and optional vertical speed/indicator selector (28 volt system). Issued 12/11/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
172N; T.C. 3A12	SA4244SW	S-TEC system 60 single axis flight guidance system, Model ST-012 (28 volt system). Issued 12/11/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
172RG; T.C. 3A17	SA3363SW	Mitchell automatic flight system AK861 consisting of Century 21 autopilot. Issued 3/14/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P172D; 180D, 180F; 182A, 182A-F; 185, 185A, 185B; T.C. 3A12, 5A6, 3A13, 3A24	SA1686WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
P172D, R172E, R172F, R172G, R172H, R172J, R172K; T.C. 3A17	SA3487WE	Installation of tail flood light. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
R172K; T.C. 3A17	SA460NW	Installation of PeeKay model 2300 or B2300 seaplane floats. Reissued 9/19/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
R172K Landplane only; T.C. 3A17	SA1437CE	Install rerated Continental IO-360-K engine. Issued 10/6/78.	CE	44802	Brad E. Isham 416 west Fourth Street Valley Center, KS 67147
R172K; T.C. 3A17	SA3227SW-D	Mitchell automatic flight system AK699 consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3228SW-D	Mitchell automatic flight system AK698 consisting of Century IIB autopilot with optional radio coupler. Issued 8/2/77.	SW	60000	Mitchell Industries P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3285SW-D	Mitchell automatic flight system AK731 consisting of Century IIB autopilot with optional radio coupler. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R172K; T.C. 3A17	SA3286SW-D	Mitchell automatic flight system AK732 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
R172K; T.C. 3A17	SA4048WE	Installation of Silver Instruments fueltron IG or fueltron digital fuel flow and totalizer system. Issued 10/24/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
R172K, 175, 175A, 175B, 175C; T.C. 3A17	SA383GL	Convert to conventional landing gear. Issued 1/31/80.	GL	16889	Ralph Bolen, Inc. 1311 U.S. 40 S.W. London, OH 43140
172, 175 Series; T.C. 3A12, 3A17	SA1-219	Gyro-stabilizer 69A122.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
172, 175 Series; T.C. 3A12, 3A17	SA3-576	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
172, 175 Series; T.C. 3A12, 3A17	SA4-1601	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175 Series; T.C. 3A12, 3A17	SA109SW	Automatic pilot AK106.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA393WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
172, 175 Series; T.C. 3A #A17	SA411SW	Automatic pitch trim AK 138.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
172, 175 Series; T.C. 3A12, 3A17	SA436EA	New engine, propeller and engine mount. Amended 9/21/67.	EA	36750	Franklin Engine Company, Inc. Old Liverpool Road Syracuse, NY 13208
172, 175 Series; T.C. 3A12, 3A17	SA610SW	Lycoming O-320 and O-360 Series engines with Hartzell HC-82XL-7636D-4; HC-C2YK-2R/7666 or HC-92Z-2B/8447-12A propeller.	SW	67650	R.F.B. Company Chandler Field Purcell, OK 73080
172, 175, 180, 182, 310 Series; T.C. 3A12, 3A17, 5A6, 3A13, 3A10	SA4-306	Roto-Nav bracket and Grimes D 7080 anti-collision light on vertical fin.	WE	08262	Air Oasis Company Municipal Airport Long Beach, CA 90801
172, 175, 182 Series; T.C. 3A12, 3A17, 3A13	SA4-893	Installation of wheel fenders on nose gear and main gear. Reissued 2/9/71.	NW	12565	Aurora Air Inc. d/b/a Madras Air Service Madras, OR 97741
172, 175, 180, 182 Series; T.C. 3A12 3A17, 5A6, 3A13	SA10WE	Arens Vernier type throttle control.	WE	82400	Van Nuys Skyways, Inc. 16700 Roscoe Boulevard Van Nuys, CA 91408
172, 175, 180 Series; T.C. 3A12, 3A17, 3A13	SA462WE	Jump door 62-500.	NW	72252	Skymotive, Inc. Route 1, Box 32 Snohomish, WA 98290
172, 175, 182 Series; T.C. 3A12, 3A13, 3A17	SA480CE	Nose and main gear wheel fairings. (Jetstreams) using standing unaltered Cessna landing gear and nose gear for model and year using 500 x 5 nose and 600 x 6 main gear tires.	GL	26750	Creative Designs 1338 Orkla Drive Minneapolis, MN 55427
172, 180; T.C. 3A12, 5A6, 3A13	SA2362WE	Installation of lure toxicant dispenser AEY 70, Model #1. Amended 9/27/73.	NW	03270	U S D A 3706 W. Nob Hill Boulevard Yakima, WA 98902
172, 180, 182 Series; T.C. 3A16, 5A6, 3A13	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Company airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
172, 180, 185; T.C. 3A17, 5A6, 3A24	SA271NW	Removal of paper air induction paper. Issued 3/16/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
172, 182 Series; T.C. 3A12, 3A13	SA1-193	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Monterey, CA 93940
172, 182 Series; T.C. 3A12, 3A13	SA116EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/63.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
172, 182, 206, 210 Series; T.C. 3A12, 3A13, A4CE, 3A21	SA895WE	Kienzle 65 flight time recorder.	WE	18460	Burrows and Sons 1829 Bridgeport Avenue Claremont, CA 91711
175 Series; T.C. 3A17	SA3-285	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 1405 S. Oliver Wichita, KS 67207
175 Series; T.C. 3A17	SA3-611	Model 3000 main ski and Model 2000 nose ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
175 Series; T.C. 3A17	SA3-691	Installation of Doyn swept-tail assembly kit 1400. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
175 Series; T.C. 3A17	SA4-547	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
175 Series; T.C. 3A17	SA4-1406	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
175 Series; T.C. 3A17	SA3EA	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
175 Series; T.C. 3A17	SA5WE	Cowl flap.	WE	87473	Thompson International Aviation P.O. Box 68 Hereford, AZ 85615
175 Series; T.C. 3A17	SA11SO	Tank type end plates.	SO	26580	Corben Development Corporation P.O. Box 1603 Venice, FL 33595
175 Series; T.C. 3A17	SA12CE	Removal of right cabin door.	PC	96754	W.E. Avery 116 Kuulei Road Kailua, HI 96754
175 Series; T.C. 3A17	SA28WE	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
175 Series; T.C. 3A17	SA49CE	Conversion of aircraft for parachute jumping operations.	GL	41190	Haven Aviation Memorial Airpark Grand Haven, MI 49417
175 Series; T.C. 3A17	SA72CE	Sky-Lite B-100 beacon light.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
175 Series; T.C. 3A17	SA179NW	Installation of flap gap seals. Issued 1/25/75.	NW	78477	Thunderbird Aero Enterprise Paine Field Everett, WA 98204
175 Series; T.C. 3A17	SA221SO	Conversion of aircraft for parachute jumping and aerial photography.	SO	62490	Edward Richard Parker P.O. Box 578 Andrews Murphy AirPark Andrews, NC 28901
175; T.C. 3A17	SA586NW	Installation of a Franklin 6AS-350-A1 engine. Issued 7/28/78.	NW	70620	Seaplane Flying, Inc. P.O. Box 1264 Vancouver, WA 98661
175, 175A, 175B Landplane; T.C. 3A17	SA424CE	Install Lycoming O-360-A1A or O-360-A1D engine and Hartzell HC-C2YK-1A/7666-2, HC-922K-8D/8447-12A or McCauley 2D36C14/78KM-4 propeller. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
175, 175A, B; T.C. 3A17	SA3-674	Lycoming O-360-A1D engine and McCauley 2D36C14/78KM-4 or Hartzell HC-C2YK-1A/7666-2 propeller. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
175, 175A, B, C, P172D; T.C. 3A17	SA1-610	Wet-to-dry vacuum pump conversion kit 300-2. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
175, 175A, B, C; P172D; T.C. 3A17	SA122NW	Installation of Continental O-470 engine, McCauley 2A34C66N/90A-8 propeller, engine mount, cowling, baffles and associated parts. Issued 7/25/74.	NW	47646	Leslie L. Kammeyer Route 2, Box 38 Enumclaw, WA 98022
175, 175A, B, C; T.C. 3A17	SA161EA	Install new engine, propeller and engine mount. Amended 3/17/67.	EA	36750	Franklin Engine Company, Inc. Liverpool Road Syracuse, NY 13208

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
175, 175A, 175B, 175C; T.C. 3A17	SA212GL	Installation of windshield P/Ns W-2056, W/T-2056 or W/G-2056. Issued 1/24/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
175, 175A, 175B, 175C; T.C. 3A17	SA1492CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
175, 175A, B, C, P172D, T210F, G, H, J, K, L, M, 310, 310A, B, C, F thru L, N, P, Q, 310J-1, 310R, E310H, E310J, T310P, Q, 320D, E, F, 337, 337A, B, C, D, E, G, M337B, T337B, C, D, E, F, G, 340, 340A, 401, 401A, B, 402, 402A, B, 414, 421, 421A, B; T.C. 3A17, 3A10, 32A25, A6CE, A7CE	SA660WE	Installation of HRD-type fire-extinguishing and detector system. Amended 7/11/77.	WE	43180	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
175, 175A, B, C, P172D; T.C. 3A17	SA327GL	Installation of fuel tank caps. Issued 7/16/79.	GI	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
175, 175A, 175B, 175C, P172D (Landplane), R172E (T-41B); T.C. 3A17	SA777CE	Install Lycoming O-360-A1A, 180 hp engine and Hartzell HC-C2YK-1A/766A-2 propeller. Amended 5/6/80.	CE	12775	Avcon Industries, Inc. 1006 West 53rd Street, North P.O. Box 4248 Wichita, KS 67204
175, 175A, 175B, 175C, P172D, R172E, R172F, R172G, R172H, R172J; T.C. 3A17	SA948CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Amended 5/6/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
175A, B, C, P172D (normal category); T.C. 3A17	SA2229WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
175, 175A, B, C; T.C. 3A17	SA2853SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
175, 175A, 175B, 175C (landplane only, normal category); T.C. 3A17	SA3795WE	Installation of Elano P/N 099001-063"F", or later FAA approved revision, muffler in lieu of original Avcon muffler. Reissued 2/25/80.	WE	29075	Del-Air P.O. Box 746 Strathmore, CA 93267
175, 175A, 175B, 175C; T.C. 3A17	SA4177WE	Installation of electric inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
175, 180, 182; T.C. 3A17, 5A6, 3A13	SA2710WE	Installation of carburetor heat box bearings. Issued 6/15/73.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
177; T.C. A13CE	SA466SO	Removal of right entrance door of cabin for aerial photography. Issued 5/20/71. Modified per STC SA545CE.	SO	25060	Columbus-Muscogee Aviation, Inc. P.O. Box 4608 Columbus, GA 31904
177; T.C. A13CE	SA545CE	Installation of Lycoming O-360-A1A (180 h.p.) engine and new Hartzell propellers. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
177; T.C. A13CE	SA602CE	Install shoulder harness.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67202
177; T.C. A13CE	SA906CE	Installation of Lycoming O-360-A1A 180 hp engine and Hartzell HC-C2YK-1B/766A-2 or 7666-2 constant speed propeller. Issued 5/9/73.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 1006 W. 53 North Wichita, KS 67204
177; T.C. A13CE	SA1608WE	Installation of Brittain B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
177; T.C. A13CE	SA3861WE	Installation of an air/oil separator. Issued 3/2/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
177, 177A; T.C. A13CE	SA956CE	Installation of STOL kit (wing leading edge cuffs, drooped tips and vortex generators). Reissued May 1977.	CE	42560	Horton STCL-Craft Wellington Municipal Airport Wellington, KS 67152
177, 177A, 177B; T.C. A13CE	SA1347CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
177, 177A, B; T.C. A13CE	SA3180SW-D	Automatic flight system AK420 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3181SW-D	Automatic flight system AK421 consisting of Century IIB autopilot with optional radio coupler. Issued 2/22/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177, 177A, B; T.C. A13CE	SA3402WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
152, A152, 177, 177A, B, 177RG, 180 landplane and seaplane, 180A, B, C, D, E, F, G, H, I, J, K seaplane versions, 182, 182A, 210A, B, C, D, E, 310F, G, H, I; T.C. A13CE, 3A19, A20CE, 5A6, 3A21, 3A10	SA71GL	Installation of: 152's P/N BA4106 filter assembly; 177's P/N BA5710 filter assembly; 180's & 182's P/N BA8110 filter assembly; 210's P/N BA2110 filter assembly; 310's P/N BA2310 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140
177, 180, 182, 185, A185, 188, A188, 210-5 (205), 206, U206, TU206, P206, TP206, 207, T207, 210, T210; T.C. A13CE, 5A6, 3A13, 3A24, A9CE, 3A21, A4CE, A16CE	SA728NW	Installation of vented fuel cap. Issued 3/9/79.	NW	82675	Venting Engineering 5420 "A" Street Tacoma, WA 98408
177A; T.C. A13CE	SA601CE	Install Hartzell Model HC-C2YK-1B/7666A-2 constant speed propeller. Amended 2/28/69.	CE	56868	Galen D. Means 1818 North Edgemoor Drive Wichita, KS 67201
177B; T.C. A13CE	SA1060CE	Installation of wing leading edge cuffs and vortex generators on vertical stabilizer. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177B; T.C. A13CE	SA1607SW	Mitchell command/electric trim AK419. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SW1608SW	Mitchell AFS system AK420 consisting of Century I autopilot with optional omni tracker. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177B; T.C. A13CE	SA1609SW	Mitchell AFS system AK421 consisting of Century I autopilot with optional radio coupler. Issued 2/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RB; T.C. A20CE	SA3297SW-D	Mitchell automatic flight system AK759, consisting of Century IIB autopilot with optional radio coupler. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG, S/N 177RG1267 and subsequent; T.C. A20CE	SA446GL	Installation of Tull microwave landing system airborne equipment. Issued 9/17/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
177RG; T.C. A20CE	SA1049CE	Installation of wing leading edge cuffs and vertical stabilizer vortex generators. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
177RG: T.C. A20CE	SA1348CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
177RG; T.C. A20CE	SA1479SW	Mitchell automatic flight system AK378 consisting of Century I autopilot with optional omni tracker. Issued 8/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RG; T.C. A20CE	SA1510SW	Mitchell automatic flight system AK379 consisting of Century IIB autopilot with optional radio coupler. Issued 9/8/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3296SW-D	Mitchell automatic flight system AK758 consisting of Century I autopilot with optional omni tracking system. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3298SW-D	Mitchell automatic flight system AK760, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 6/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
177RG; T.C. A20CE	SA3387WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
177RG; T.C. A20CE	SA3860WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
177RG; T.C. A20CE	SA4024WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 9/10/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
180 Series; T.C. 5A6	SA1-7	Gyro-stabilizer 69A116 on aircraft with serial numbers 32151 and up.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-16	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA1-91	Modification to accommodate Robinson Aviation vertical mount NRIA.	EA	18756	Allen G. Butler 233 Front Street Phillipsburg, PA 16866
180 Series; T.C. 5A6	SA1-106	Gyro-stabilizer 69A107.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA1-212	Hole cut in lower skin and reinforced.	NE	44030	Inland Fisheries and Game Department Maine
180 Series; T.C. 5A6	SA1-221	Gyro-stabilizer 69A124.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
180 Series; T.C. 5A6	SA3-122	Model 3000 main ski and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-160	Conversion of electrical system, engine and aircraft to 24v and installation of additional battery box. (Aircraft with Continental O-470-J engine only).	GL	43342	Harvey M. Hughes Capital City Airport Lansing, MI 48924
180 Series; T.C. 5A6	SA3-161	C-3000 hydraulically-actuated main wheel skis with AWT-2500A or CT-3000 tail wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-292	Hydraulic landing gear actuating system with Edo 289-2700 amphibian gear.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA3-330	C-3000 manually-actuated main skis and AWT-2500A or CT-3000 tail skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-340	C-3000 main wheel skis on aircraft with crosswind gear.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
180 Series; T.C. 5A6	SA3-381	18-gallon auxiliary fuel system.	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180 Series; T.C. 5A6	SA3-480	Change in airspeed and center of gravity limits with Edo 249-2870 floats and 2850 maximum weight.	AL	08483	Alaska Coastal Airlines 2 Marine Way Juneau, AK 99801
180 Series; T.C. 5A6	SA3-578	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
180 Series; T.C. 5A6	SA3-592	Structural reinforcement wires from center sectional spars to upper engine mount bolts rear of fire wall in windshield.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA3-597	Engine driven hydraulic pump system for Federal C-3000 main ski.	GL	87000	Wiplinger Aircraft Service Fleming Field South St. Paul, MN 55075
180 Series; T.C. 5A6	SA4-23	Conversion to tricycle gear.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-56	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
180 Series; T.C. 5A6	SA4-92	Folding type rear seat.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-117	Auxiliary fuel tank in baggage compartment.	WE	59730	Missionary Aviation Fellowship Municipal Airport Fullerton, CA 92632
180 Series; T.C. 5A6	SA4-532	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
180 Series; T.C. 5A6	SA4-603	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA4-688	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
180 Series; T.C. 5A6	SA41WE	Two fabric rear seat assemblies supported by two steel tube beams.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA42EA	Floor viewing window.	EA	49730	Latrobe Aviation, Inc. P.O. Box 150 Latrobe, PA 15650
180 Series; T.C. 5A6	SA102AL	Shackle release at wing lift strut fittings right and left wings (seaplane only).	AL	03270	U.S. Department of Agriculture Forest Service P.O. Box 1631 Juneau, AK 99801
180 Series; T.C. 5A6	SA110SW	Removal of perforated cones from exhaust muffler.	SW	76850	Sun Oil Company P.O. Box 292 Patterson, LA 70392
180 Series; T.C. 5A6	SA168SW	Conversion of aircraft for parachute jumping operations.	SW	40684	John Hardy, Jr. 1105 St. John's Road El Paso, TX 79910
180 Series; T.C. 5A6	SA173WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401
180 Series; T.C. 5A6	SA200RM	Installation of flight strobe light, Model 4400. Issued 4/22/80.	RM	79760	Tri Star Corporation P.O. Box 1727 730 Independent Avenue Grand Junction, CO 81501
180 Series; T.C. 5A6	SA214SW	Removal of perforated cones on cabin and carburetor heat-sides of muffler assembly with Continental O-470-K engine.	SW	52870	J. Ray McDermott & Company, Inc. Aviation Division P.O. Box 38 Harvey, LA 70058
180 Series; T.C. 5A6	SA221WE	Cleveland 30-21 wheel and brake assemblies 8:00 x 6 tires, Cessna heavy duty axles and 185 hose assemblies.	WE	59730	Missionary Aviation Fellowship 3519 W. Commonwealth Avenue Fullerton, CA 92632
180 Series; T.C. 5A6	SA289CE	Sky diving door.	GL	78474	Melvin J. Thompson 2408 Illinois Avenue New Holstein, WI 53061

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180 Series; T.C. 5A6	SA312NW	Installation of Edo 628-2960 floats. Amended 6/6/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180 Series; T.C. 5A6	SA527WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
180 Series; T.C. 5A6	SA531AL	Installation of leading edge cuff stall fences, and flap and aileron gap seals. Issued 10/25/74.	AL	27250	Crosswinds, Inc. 8134 Lake Otis Parkway Anchorage, AK 99507
180 Series; T.C. 5A6	SA532CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
180 Series; T.C. 5A6	SA702WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304, and optional Hi-Lo sensitivity adaptor.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
180 Series; T.C. 5A6	SA703WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold and NAV-1 navigation coupler and optional Hi-Lo sensitivity adaptor. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180 Series; T.C. 5A6	SA939WE	Insertion into exhaust collector or exhaust stack of thermocoupled cylinder, a probe to read relative exhaust temperature.	WE	47746	Richard W. Kennedy 3352 Via Bartolo Street San Diego, CA 92101
180 Series; T.C. 5A6	SA983WE	Removal of right-hand door to permit parachute jumping and aerial photography operation (seaplane).	NW	25050	Columbia Marine, Inc. P.O. Box 179 Vancouver, WA 98663
180 Series; T.C. 5A6	SA1373WE	Model 3000 floats.	EA	19800	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond, British Columbia, Canada
180 Series; T.C. 5A6	SA2630WE	Installation of SKI Model 10-202186 (Pulstar TM) combined position - anti-collision lighting system. Amended 5/11/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180F, 182, 182A thru 182D; T.C. 5A6, 3A13	SA1-37	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 46226
180, 180A, 180B; T.C. 5A6	SA1-363	Installation of Edo Model 439-2705 amphitious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, (seaplanes); T.C. 5A6	SA1-464	Installation of Edo models 439-2705 amphibious floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180, 180A, B, C, D, E, F, G, H, J, 182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P; T.C. 5A6, 3A16	SA1-611	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
180, 180A, B, C, D, E, (seaplanes); T.C. 5A6	SA1-622	Installation of Edo Model 249A-2870 seaplane floats. Amended 1/13/78.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
180 thru 180F; T.C. 5A6	SA24GL	Installation of Model M-3000 wheel replacement skis. Issued 6/4/73.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapid, MN 56470
180, 180A thru 180F, H, J, 185, 185A, B, A185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA62GL	Install Cleveland wheel and brake conversion kit, P/N 199-60. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
180, 180A thru 180F, H, J, 185, 185A, B, 185E, A185F, 206E, 206F, TU206E, TU206F; T.C. A4CE, 5A6, 3A24	SA63GL	Install Cleveland wheel and brake conversion kit, P/N 199-62. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180, 180A thru 180J; T.C. 5A6	SA73GL	Installation of wheel replacement skis, Model M3000. Amended 7/16/75.	GL	02750	Aero Ski Manufacturing Co., Inc. Park Rapids, MN 56470
180, 180A thru 180F, 182, 182A thru F; T.C. 5A6, 3A13	SA94EA	Installation of Monitair angle of attack system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
180, 180A thru 180F; T.C. 5A6	SA104CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180 thru 180H, J, 185 thru 185E, A185E, F; T.C. 3A24, 5A6	SA213AL	Installation of main tail gear skid, or main gear skis with two position wheel fittings. Amended 12/10/75.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180, 180A thru 180H, 185, 185E, A185E, 185F; T.C. 3A24	SA223AL	Installation of Model L3000 wheel replacement skis. Amended April 1974.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
180 thru 180K; T.C. 5A6	SA286CE	Installation of Pee Kay Model 3500 or A3500 or B3500 floats, seaplane (TSO-C27-2) on Cessna Models 180 thru 180H airplanes. Amended and reissued 1/19/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
180, 180A thru 180H; T.C. 5A6	SA296AL	Installation of "quick-change" leading edge for horizontal stabilizer. Amended 12/15/71.	AL	05958	Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
180 Series 32015 and up, 180A thru 180K; T.C. 5A6	SA349CE	Installation of Aqua Model 180-85 floats. Amended and reissued 7/12/77.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
180 thru 180E; T.C. 5A6	SA367CE	Installation of floor level seat belt brackets to accommodate four occupants. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
180 thru 180H; 182 thru 182L; 185 thru 185E, A185E; 210 thru 210H, 210-5, -5A, T210F, G, H; 206, 206P, 206TP, 206TU, U206A, U206P, U206TP, U206TU, U206B, U206C; T.C. A4CE	SA453CE	Install Hoskins Twilighter Mk.III supplementary lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
180, 180A thru 180K; T.C. 5A6	SA471GL	Installation of Great Lakes Aero Products windshield P/Ns W-2072, W/T-2072 and W/G-2072 (for aircraft S/N 30000 thru 50355) and P/Ns W-2073, W/T-2073 and W/G-2073 (for aircraft S/Ns 50356 and up). Issued 11/17/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
180, 180A thru 180H; T.C. 5A6	SA651AL	Fabricate canvas hammock rear seat and associated parts and install. Issued 8/23/78.	AL	61765	Nugget Aviation Route B, Box 188B Palmer, AK 99645
180, 180A thru 180H; T.C. 5A6	SA658AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180, 180A thru H; T.C. 5A6	SA745CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109
180A thru 180H; T.C. 5A6	SA787EA	Installation of Fleet-Line Floats 2900. Reissued 12/21/71.	EA	64630	Pioneer Airways P.O. Box 357 Atikokan, Ontario, Canada
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA816SW	Hartzell BHC-A2VF-3/V8833 reversible pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
180, S/N 18051824 and on; T.C. 5A6	SA865CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180, 180A, B, C, D, E, F, G, H, 182, 182A, B, C, D, E, F, G, H, J, K, L, 185, 185A, B, C, D, E, A185E, 210, 210A, B, C, D, E, F, T210F, 206, P206, P206A, B, C, D, U206, U206A, B, C, D, TP206A, B, C, D, TU206A, B, C, D; T.C. 5A6, 3A13, 3A24, 3A21, A4CE	SA901SW	Increased wing leading edge radius. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 96133
180, 180A thru 180H, J, 180K, Landplanes, Seaplanes and Amphibians; T.C. 5A6	SA967CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals). Amended 5/8/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
180, 180A thru 180H; T.C. 5A6	SA1004CE	Install STOL kit. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
180, 180A thru 180H, 180J; T.C. 5A6	SA1157WE	Turbocharged Continental O-470-A, J, K, L, or R engine. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
180 thru 180H, 180J Landplane, Floatplane and Amphibian; T.C. 5A6	SA1435WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, except 180J, a flap actuated elevator trip system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA1493CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
180, 180A thru 180H, J; 180H Landplane and Floatplane; T.C. 5A6	SA1705WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 4/20/77.	WE	35780	William E. Flint 8402 North Magnolia, Suite G La Mesa, CA 92041
180, 180A thru H, A185E; T.C. 5A6, 3A24	SA1749WE	Installation of Canadian Aircraft Products, Ltd. Model 3000D floats.	EA	19800	Canadian Aircraft Products, Ltd. 261 Viscount Way Richmond, British Columbia, Canada
180 thru 180H; T.C. 5A6	SA2003WE	Installation of recontoured wing leading edge, stall fences, wing tips and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
180, 180A, B, C, D, E, F, G, H; T.C. 5A6	SA2854SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
180, 180A, B, C, D, E, F, G, H, J Landplanes Normal Category; T.C. 5A6	SA3313WE	Installation of flap gap closures. Issued 1/5/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
180, 180A thru 180H, 180J, 180K; T.C. 5A6	SA3419WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
180A; T.C. 5A6	SA388NW	Installation of McCauley 2A34C201/90DA-2 or -8 or McCauley 2A34C203/90DCA-2 or -8. Issued 12/23/76.	NW	61660	North Sound Aviation 1340 Peterson Road Burlington, WA 98233
180A thru 180H; T.C. 5A6	SA1943WE	Installation of Madras wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
180B; T.C. 3A24	SA155NW	Installation of baggage hatch with cover on EDO 249-3870 and 628-2960 floats. Issued 7/15/75.	NW	11780	Arts Aircraft Parts & Repair 4647 110th N.E. Kirkland, WA 98033
180B, 182 Normal Category; T.C. 3A13	SA3862WE	Shorten vertical leg of the control column 1-1/4 inches to provide clearance for additional avionics equipment in the instrument panel. Issued 2/6/79.	WE	16752	Big Bear Avionics P.O. Box 768 500 Meadow Lane Big Bear City, CA 92314
180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K; T.C. 5A6	SA470GL	Modification of fuel tank caps by the incorporation of an alternate vent. Issued 11/17/80.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180F, G, H, J; T.C. 5A6	SA3146SW-D	Mitchell automatic flight system AK602 consisting of Century IIB autopilot with optional radio coupler. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180F, G, H, J; T.C. 5A6	SA3147SW-D	Mitchell automatic flight system AK603 consisting of Century I autopilot with optional omni tracker. Issued 6/24/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180G, 180H, 180J, 180K; T.C. 5A6	SA649NW	Installation of modification to increase gross weight of floatplane to 3190 lbs. when Edo 628-2960 floats are installed. Issued 8/8/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180G, 180H; T.C. 5A6	SA1349CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
180G, H, J (S/N 18051313 and Subs); T.C. 5A6	SA2979WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
180H; T.C. 5A6	SA569EA	Installation of Tactair T-3 automatic pilot with A-651 horizon gyro and B-650 directional gyro. Issued 7/29/71.	GL	75200	George B. Stillwagon 546 Hathaway Road Dayton, OH 45419
180H, 180J; T.C. 5A6	SA262NW	Installation of 3-bladed McCauley D3A32C90/82NC-2 propeller, Cessna 1250809 spinner. Issued 2/27/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180J; T.C. 5A6	SA556NW	Installation of Continental O-470-Rengine. Issued 1/12/79.	NW	41520	Jim Hayton 1712 A Lakeview Boulevard Mount Vernon, WA 98273
180J; T.C. 5A6	SA3183WE	Installation of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
180J, 180K; T.C. 5A6	SA659AL	Installation of leading edge cuff, stall fences, and flap and aileron gap seals. Issued 12/19/78.	AL	20511	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
180J, 180K; T.C. 5A6	SA4246SW	S-TEC system 60 (two axis) flight guidance system, Model ST-024 with optional flight drector/steering horizon and optional vertical speed indicator/selector (14 volt system). Issued 12/11/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
180K; T.C. 5A6	SA3282SW-D	Mitchell automatic flight system AK751 consisting of Century I autopilot with optional omni tracker. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K; T.C. 5A6	SA3283SW-D	Mitchell automatic flight system AK752 consisting of Century IIB autopilot with optional radio couplers. Issued 4/27/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
180K, T207A, 210N, P210N, 337H, P337H, T337H, 340A, 402C, 404, 421C; T.C. 5A6, A6CE, A16CE, 3A21, 3A25, A25CE, A7CE	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 5/22/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
180, 182 Series; T.C. 5A6, 3A13	SA3-123	Heater-muffler assembly 430-10P.	EA	40350	Hanlon & Wilson, Inc. 321-325 Penwood Avenue Pittsburg, PA 15644
180, 182 Series; T.C. 5A6, 3A13	SA4-868	Shackle release at wing lift strut fittings, right and left wings (restricted category only).	RM	03270	U.S. Department of Agriculture Forest Service Missoula, MT 59801
180, 182 Series; T.C. 5A6, 3A13	SA4-1092	Seat belt and seat back to accommodate additional passenger on the rear seat.	RM	39464	Green River Aviation Company P.O. Box 606 Green River, UT 84525

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
180, 182 Series; T.C. 5A6, 3A13	SA4-1588	Cessna 210 wing tip assemblies.	WE	42130	H & H Flying Service, Inc. P.O. Box 742 Redding, CA 96001
180, 182 Series; T.C. 5A6, 3A13	SA5-19	Hammock seat in place of upholstered rear seat.	AL	08460	Alaska Aeronautical Ind. P.O. Box 4591 Spenard, AK 99503
180, 182 Series; T.C. 5A6, 3A13	SA108CE	Continental O-470 Series engines modified for Bendix RSA5 fuel injection system.	GL	15500	The Bendix Corporation 717 Bendix Drive South Bend, IN 46600
180, 182 Series; T.C. 5A6, 3A13	SA264SO	Cessna 210 wing tips 1223000-1 and -2.	SO	61180	Nashville Flying Service, Inc. Berry Field Nashville, TN 37202
180, 182 Series; T.C. 5A6, 3A13	SA561WE	12.7-gallon auxiliary fuel tank.	WE	05600	Aircraft Modification and Repair 20331 Hesperian Boulevard Hayward, CA 94541
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA1-519	Griswold lateralizer and heading lock.	NE	14230	Herbert Baer 80 Federal Street Boston, MA 02109
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA102SW	Automatic pilot AK109 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
180, 182, 185 Series; T.C. 5A6, 3A13, 3A24	SA4121SW	Add wing strut fairings and contour wing struts. Issued 5/5/80.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA1-576	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
180, 182, 185, 210 Series; T.C. 5A6, 3A13, 3A24, 3A21	SA334SW	Alternator.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216
180, 182, 210 Series; T.C. 5A6, 3A13, 3A21	SA96SW	Mixture control indicator kits SE-1.	SW	09250	Alcor, Inc. 2905 Bandera Road San Antonio, TX 78216
180, 185; T.C. 5A6, 3A24	SA361NW	Installation of 8/50 x 6 main wheels with Cleveland brakes and Cleveland wheel assembly. Issued 10/15/76.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA701WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
180, 185 Series; T.C. 5A6, 3A24	SA2273WE	Installation of Cessna Model 206 rear seats. Amended 10/18/74.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
180, 185 Series; T.C. 5A6, 3A24	SA2767WE	Installation of anti-collision lighting system. Issued 9/28/73.	WE	70500	Scientifico Scientific Components Company 350 Vista Baya Newport Beach, CA 92660
180, 185, 206; T.C. 5A6, 3A24, A4CE	SA754NW	Installation of Fernandez model 8001 and 8001A skis. Issued 4/27/79.	NW	46400	Jobmaster, Inc. 608 West Perimter Road Renton, WA 98055
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA65CE	Tow hitch assembly.	EA	73550	Soaring Society of America, Inc. Elmira, NY 14902
180, 185, 321 Series; T.C. 5A6, 3A24, 3A11	SA271CE	Tow hitch assembly.	CE	67207	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA1-8	Gyro-stabilizer 69A107.	GL	38175	Globe Industries, Inc. 1784 Stanley Avenue Dayton, OH 45404
182 Series; T.C. 3A13	SA1-36	Federal F-300 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA3-18	Yaw axis stabilizer 8000B.	GL	20335	Cedar Engineering, Inc. 5806 W. 36th Street Minneapolis, MN 55401
182 Series; T.C. 3A13	SA3-44	Main ski AWB-2500A and nose wheel ski AWN-1200.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182 Series; T.C. 3A13	SA3-109	Rudder trim system.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA3-110	Single axis automatic pilot A-2 or A-3.	CE	45250	Javelin Aircraft Company, Inc. 9135 E. Douglas Wichita, KS 67207
182 Series; T.C. 3A13	SA3-171	AWB2500A main and AWN1200 nose wheel skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-286	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562
182 Series; T.C. 3A13	SA3-348	C-3000 main ski and AWN-1200 nose wheel ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-452	Model 3000 main skis and Model 2000 nose skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
182 Series; T.C. 3A13	SA3-577	Speed kit.	CE	65900	R & E Aircraft Accessories, Inc. 1054 Gretchen Wichita, KS 67202
182 Series; T.C. 3A13	SA4-39	L-2B automatic pilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
182 Series; T.C. 3A13	SA4-132	Automatic rudder control B.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
182 Series; T.C. 3A13	SA4-199	13-gallon auxiliary fuel system.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
182 Series; T.C. 3A13	SA4-533	Federal F-200 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
182 Series; T.C. 3A13	SA4-548	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA4-668	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
182 Series; T.C. 3A13	SA4-1359	Landing gear modified.	WE	70560	Scott Aero Service, Inc. Municipal Airport Long Beach, CA 90801
182 Series; T.C. 3A13	SA1SO	Wing tips.	SO	75880	Dale Stoughton 6408 S.W. 12 Street Hollywood, FL 33022
182 Series; T.C. 3A13	SA4FA	Single axis autopilot 510A.	EA	05950	Aircraft Radio Corporation P.O. Box 150 Boonton, NJ 07005
182 Series; T.C. 3A13	SA27SW	Automatic pilot AK088, AK088R or AK088E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA40CE	Conversion of aircraft for parachute jumping operations.	WE	62425	Parachute Club of America P.O. Box 409 Montorey, CA 93940
182 Series; T.C. 3A13	SA97WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA101SW	Automatic pilot AK110 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA129EA	HC-A2XF-G/8433-2 or BHC-A2XF-G/8433-2 propeller.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
182 Series; T.C. 3A13	SA183WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	90155	ZIV United Artists, Inc. 7324 Santa Monica Boulevard Hollywood, CA 90028

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182 Series; T.C. 3A13	SA361WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA363WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA391CE	210 wing tips.	CE	42030	Carl H. Helms 701 Lou Holland Drive Kansas City, MO 64116
182 Series; T.C. 3A13	SA450SW	Automatic pitch trim system AK134.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA461NW	Installation of Continental IO-520-F engine and McCauley D2A34C58-LMN-90AT-8 propeller. Issued 6/13/77.	NW	85615	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
182 Series; T.C. 3A13	SA489SW	Automatic pilot AK154 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA502WE	Flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA516WE	Original Goodyear wheel and brake assembly replaced with Celveland wheel and brake assembly.	RM	39464	Green River Aviation Company, Inc. P.O. Box 606 Green River, UT 84525
182 Series; T.C. 3A13	SA525WE	B-4 flight control system, including pitch assist PC-1 altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA535CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
182 Series; T.C. 3A13	SA585SO	Fuselage cutout and rerouting of rudder, elevator and trim cables. Amended 1/6/75.	SO	22787	Mr. Joel Clark P.O. Box 317 Bay Minette, AL 36507
182 Series; T.C. 3A13	SA60-SW	AK180 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA617SO	Installation of A or B of Continental O-470-M engines (per STC SE616SO).	SO	61644	North Perry Aviation, Inc. 8000 W. Pembroke Road Hollywood, FL 33023
182 Series; T.C. 3A13	SA624SW	AK197 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA658SW	AK199 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA707SW	AK243 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA709SW	AK229 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA795SW	Mitchell Century II autopilot AK241 with optional automatic aileron stabilizer and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182 Series; T.C. 3A13	SA814WE	Modification to allow installation of camera through 15-inch diameter cutout in bottom of fuselage.	WE	08262	The Air Oasis Company 2361 Airlane San Diego, CA 92101
182; T.C. 3A13	SA957NW	Installation of weather radar unit. Issued 6/16/80.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182; T.C. 3A13	SA1008SO	Installation of an adjustable trim tab on the left aileron. Issued 7/6/78.	SO	03110	Aero-Trim, Inc. 1150 100 Street Bay Harbor, FL 33154
182 Series; T.C. 3A13	SA1383WE	Installation of Brittain Pitch Assist Model PC-1 with Altitude Hold. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1384WE	Installation of Brittain Industries Model CSA-1 Stability Augmentation. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1474WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1671WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1673WE	Installation of Brittain Industries B-5 Flight Control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1706WF	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1871WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA1872WE	Installation of Brittain Model NAV-2B Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 Series; T.C. 3A13	SA2343WE	Installation of PHI controls Model 312 elapsed time indicator. Issued 4/27/71.	WE	64380	PHI Controls P.O. Box 6307 Torrance, CA 90504
182 Series; T.C. 3A13	SA2719WE	Installation of Symbolic Displays IFO-1A anti-collision lights. Amended 1/23/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
182, 182A thru 182F; T.C. 3A13	SA103CE	High intensity wing tip lights Model B, tail light Model C, with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
182, 182A, B, C, D, E, F, G; T.C. 3A13	SA301GL	Installation of windshield P/Ns W-2071, W/T-2071, W/G-2071, W-2072, W/T-2072, W/G-2072, W-2073, W/T-2073, W/G-2073. Reissued 5/17/79.	GL	39450	Great LAkes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
182, 182A, B; T.C. 3A13	SA355NW	Convert a Cessna 182 aircraft to tailwheel configuration. Reissued 9/25/78.	NW	14233	Baer's Flying Service and Satra Aircraft Route 1, Box 93E Ronan, MT 59864
182, 182A thru 182H, 182J thru N, P, Q: T.C. 3A13	SA950CE	STOL kit installation (wing leading leading edge cuffs, drooped tips stall fences and aileron gap seals. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
182, 210, 310, 320 Series; T.C. 3A13 3A21, 3A10, 3A25	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
182 thru 182D; T.C. 3A13	SA874CE	Removal of right front seat, rear seat, and baggage shelf (if installed); installation of floor level seat belt brackets to accommodate four occupants in addition to the pilot. Reissued 10/24/72.	WE	80918	United States Parachute Association P.O. Box 409 Monterey, CA 93940
182, 182A, 182B, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M; T.C. 3A13	SA935SW	Installation of cabin air conditioning system. Amended 5/7/79.	RM	01950	Aero Engineering 8C Garden Center Broomfield, CO 80020
182, 182A thru 182H, J, K, L, M, N, P, Q (Thru S/N 18266590); T.C. 3A13	SA949CE	STOL kit installation. Amended 2/4/80.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182, 182A thru H, J thru N, P; T.C. 3A13	SA1032WE	Installation of Rajay turbosupercharged Continental O-470-L or -R engine. Amended 10/1/75.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
182 thru 182P; T.C. 3A13	SA1382WE	Installation of flap actuated aileron droop system for all models; except 182P, recontoured wing leading edge, flap actuated elevator system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
182, 182A thru 182H, 182J thru 182N, 182P, Q, R182, TR182; T.C. 3A13	SA1494CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
182, A, B, C, D; T.C. 3A13	SA1579SW	Mitchell automatic flight system AF414, consisting of Century IIB autopilot with optional radio coupler. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. box 610 Municipal Airport Mineral Wells, TX 76067
182, A, B, C, D; T.C. 3A13	SA1580SW	Mitchell automatic flight system AF411, consisting of Century I autopilot with optional omni tracker. Issued 12/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182, 182A thru 182H, 182J thru 182Q; T.C. 3A13	SA1758WE	Installation of 12-gallon auxiliary fuel tank in each wing inboard of tip. Amended 3/15/79.	WE	35746	Flint Aero 8402-G Magnolia Avenue Gillespie Airport Plaza Santee, CA 92071
182, 182A thru 182H, 182J thru 182N; T.C. 3A13	SA1938WE	Installation of Madras Air Service "Super Tips." Amended 8/4/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
182 thru 182N; T.C. 3A13	SA2004WE	Installation of contoured wing leading edge and following options: stall fences, Robertson wing tips, positive aileron seals. Reissued 8/10/72.	NW	66175	Charyl C. Raisbeck 839 West Perimeter Road Renton Municipal Airport Renton, WA 98055
182, 182A thru 182H, 182J, 182K, 182L, 182M, 182N, 182P; T.C. 3A13	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
182, 182A, B, C, D; T.C. 3A13	SA2888SW	Replacement of control wheel. Issued 12/18/78.	SW	78420	Texas Aviation Engineering Meacham Field Fort Worth, TX 76106
182, 182A, B, C; T.C. 3A13	SA2890SW	Installation of Continental O-470-R engine. Issued 12/20/78.	SW	78420	Texas Aviation Engineering Co. Meacham Field Fort Worth, TX 76106
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3113WE	Installation of flap gap fairing. Amended 8/22/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, 182Q, R182, TR182; T.C. 3A13	SA3349WE	Installation of vertical tail flood lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
182, 182A, B, C, D, E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA3652WE	Installation of an air/oil separator. Amended 3/13/79.	WE	84396	Walker Engineering Company 5760 West 3rd Street Los Angeles, CA 90036
182A; T.C. 3A13	SA239GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 5/1/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
182A thru 182H, 182J thru 182N; T.C. 3A13	SA1006CE	Install landing gear speedpants. Amended 10/9/74.	CE	15230	Bede Aircraft, Inc. Newton Municipal Airport P.O. Box 706 Newton, KS 67114
182A thru P; T.C. 3A13	SA25NW	Installation of insect refrigeration release equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA26NW	Installation of twine dispenser equipment. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182A thru P; T.C. 3A13	SA67NW	Installation of twine dispenser equipment. Issued 9/10/73.	NW	80914	U.S. Department of Agriculture 3706 W. Nob Hill Boulevard Yakima, WA 98902

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182A thru P; T.C. 3A13	SA2371WE	Installation of lure-toxicant distributor. Amended March 1974.	NW	80914	U.S. Department of Agriculture Agricultural Research Service 3706 W. Nob Hill Boulevard Yakima, WA 98902
182A, B, C, D, E, F, G, H, J, K, L, M, N, P; T.C. 3A13	SA2761SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Amended 7/15/80.	CE	86195	Rob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
182B; T.C. 3A13	SA198GL	Installation of Continental 0-470-R engine in lieu of Continental 0-470-L engine using original installation hardward & components. Issued 10/20/77.	GL	64285	Mark W. Peterson and Assoc. 2627 Springdale Road Duluth, MN 55811
182B, C, D, E, F, G, H, J, K, L, M, N, P, Q, R182, TR182; T.C. 3A13	SA469GL	Modification of fuel tank caps by the incorporation of an alternate vent. Issued 11/17/80.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
182D thru P; T.C. 3A13	SA27NW	Installation of auxiliary crew seat in rear seat area. Issued 2/6/73.	NW	80914	U.S. Department of Agriculture 3706 W. Knob Hill Boulevard Yakima, WA 98902
182D; T.C. 3A13	SA1338SW	Cessna NAV-O-MATIC 400 autopilot. Issued 7/9/71.	SW	12630	Autopilots Central, Inc. 3260 North Sheridan Road Tulsa, OK 74131
182E, 182F, 210B, 210C, 210-5; T.C. 3A13, 2A21	SA36EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
182E, F, G, H; T.C. 3A13	SA513SW	Heavy duty brake kits. (Also eligible on Wren 460 and 460H aircraft). Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H; T.C. 3A13	SA626SW	Nose gear wheel and tire. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K, L, M; T.C. 3A13	SA692SW	Reverse pitch propeller. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, J, K; T.C. 3A13	SA789SW	Automatic aileron stabilizer AK204.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, F, G, H, J, K, L, M; T.C. 3A13	SA923SW	Droop ailerons. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E, F, G, H, K, L, M, 206, P206, U206, 210C, D, E, F, G (205), 210-5 (205A), 210-5A, 337, 337A, B, C, D, T337B, C, D; T.C. 3A13, 3A21, A4CE, A6CE	SA1021SW	Flap on switch on control wheel. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182E thru N; T.C. 3A13	SA1211SW	Automatic flight system AK310 consisting of Century I and optional tracking system. Issued 11/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, F, G, H, J, K, L, M, N; T.C. 3A13	SA1594SW	Mitchell automatic flight system AK399 consisting of Century IIB autopilot with optional radio. Issued 1/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182E, 182F, 182G, 182H, 182J, 182K; T.C. 3A13	SA2546WE	Installation of Pathfinder Engineering Corp. Model P1-( ) autopilot. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182E, F, G, H, J, K, L, M, N, P, Q; T.C. 3A13	SA2908SW	Exhaust extension. Issued 2/2/79.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182E, F, G, H, J, K, L, M, N, P (S/N 18253599 and Subs); T.C. 3A13	SA2980WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2502 E. Wardlow Road Long Beach, CA 90807

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182E thru 182H, 182H thru 182Q, NOTE; T.C. 3A13	SA3608WE	Installation of replacement flexible fuel cell in wings. Issued 3/15/78. NOTE: 182E S/N 18253599 thru 182H18256143 except aircraft modified by Cessna Service Kit SK182-41; 182H S/N 18256144 and subsequent thru 182Q S/Ns. Also 182E thru 182H aircraft which have been modified by Cessna SK182-41.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
182F; T.C. 3A13	SA198EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
182F; T.C. 3A13	SA933EA	Installation of wing struts modified to include Wings With Springs Model 300 hydraulic-pneumatic shock absorbers and associated airframe modifications. Amended 2/13/76.	EA	86500	Wings With Springs, Inc. Box 495, R.D. 3 Latrobe, PA 15650
182F, G; T.C. 3A13	SA403SW	Full span double slotted flaps, drooped wing leading edge, aileron actuated drag plates, Robertson U.L.S. nose control system, increased elevator aerodynamic balance, and relocated pilot head. Reissued 4/22/80.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182H, J, K, L, M; T.C. 3A13	SA485SW	STOL operations modification. (Also eligible on Wren 460H aircraft.) Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
182H, J, K, L, M, N; T.C. 3A13	SA1350CE	Chrome-plate brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
182H, 182J, 182K, 182L, 182M (Landplane only, normal category); T.C. 3A13	SA2662WE	Removal of nose control surface (which was installed as part of Wren 460 modification in accordance with STC SA485SW). Issued 3/9/73.	WE	17125	Breuner STOL Company 50 Melody Lane Orinda, CA 94563
182H, J, K, L, M, N, P206A, P206B, P206C, P206D, P206E (landplane only); T.C. 3A13, A4CE	SA2799WE	Installation of camera pod attached to bottom of fuselage by straps. Issued 1/8/74.	WE	15190	Bechtel Corporation 50 Beale Street San Francisco, CA 94119
182K, L, M, N, P; 210G, H, J, K, L, T210G, H, J, K, L; T.C. 3A13, 3A21	SA6GL	Installation of Grimes strobe anti-collision lights. Issued 1/5/73.	GL	39500	Grimes Manufacturing Company 515 N. Russell Street Urbana, OH 43078
182K, L, M, N, P, Q; T.C. 3A13	SA2748SW	Streamlined nose gear kit. Issued 4/14/78.	SW	35688	Flight Bonus, Inc. P.O. Box 665 Hurst, TX 76053
182M Normal Category; T.C. 3A13	SA2723WE	Installation of external cargo pack (ski carrier). Issued 7/11/73.	WE	87114	Wirly Sales 7610 Owens Street Tujunga, CA 91042
182N, 182P; T.C. 3A13	SA2177WE	Installation of Brittain Ind. B-7, NAV-2B, B2C or BSS flight control system. Reissued 9/19/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
182N (S/N 18260446 and up), 182P, 182Q; T.C. 3A13	SA1406CE	Install 25-gallon auxiliary fuel tank in fuselage baggage compartment. Amended 5/12/78.	CE	45250	Javelin Aircraft Company, Inc. 1978 Easy Street Wichita, KS 67230
182P; T.C. 3A13	SA1554SW	Mitchell automatic flight system AK396 consisting of Century I with optional omni tracker. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1555SW	Mitchell automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA1556SW	Mitchell command/electric trim system. Issued 11/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
182P; T.C. 3A13	SA3063WE	Installation of Pathfinder autopilot system and/or electric pitch trim system. Amended 12/3/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182P; T.C. 3A13	SA3072SW-D	Mitchell automatic flight system AK540 consisting of Century III autopilot with optional radio and slope couplers. Issued 9/10/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P; T.C. 3A13	SA3190SW-D	Mitchell command electric trim AK410 Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, 182Q; T.C. 3A13	SA1296CE	Installation of *King KFC-200 2-axis*, flight control system with KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 9/22/77.	CE	48250	*King Radio Corporation* 400 North Rogers Road Olathe, KS 66061
182P, 182Q; T.C. 3A13	SA1403CE	Install wing stall fences and aileron gap seals. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
182P, 182Q; T.C. 3A13	SA3188SW-D	Install automatic flight system AK397 consisting of Century IIB autopilot with optional radio coupler. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, 182Q; T.C. 3A13	SA3189SW-D	Automatic flight system AK396 consisting of Century I autopilot with optional omni tracker system. Issued 3/1/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
182P, Q; T.C. 3A13	SA4079SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
182P, 182Q; T.C. 3A13	SA4112SW	S-TEC system 60-1 (single axis) flight guidance system, Model ST-003. Issued 4/21/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
182Q; T.C. 3A13	SA255GL	Install a Pathfinder P2A autopilot. Issued 7/19/78.	GL	04543	Air Central Enterprises 44050 Russia Road Elyria, OH 44035
182Q; T.C. 3A13	SA3279SW-D	Mitchell automatic flight system AK744 consisting of Century I autopilot with optional omni tracker. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3280SW-D	Mitchell automatic flight system AK745 consisting of Century IIB autopilot with optional radio coupler. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3281SW-D	Mitchell automatic flight system AK 746 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
182Q; T.C. 3A13	SA3763WE	Installation of Pathfinder autopilot systems. Issued 10/27/78.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
182Q; T.C. 3A13	SA4238SW	S-TEC system (two axis) flight guidance system, ST-016, with optional flight director steering horizon and optional vertical speed/indicator selector (28 volt system). Issued 11/19/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
R182; T.C. 3A13	SA144RM	Installation of Pathfinder P2A single-axis autopilot. Issued 6/29/78.	RM	02454	Aeronics Jefferson County Airport Hangar B4A Broomfield, CO 80020
R182, TR182; T.C. 3A13	SA1205SO	Installation of Bendix FCS-870 flight control system. Issued 2/25/81.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
R182; T.C. 3A13	SA1433CE	Installation of KFC 200 flight control system with or without flight director. Amended 10/27/79.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
R182; T.C. 3A13	SA3273SW-D	Mitchell automatic flight system AK741 consisting of Century IIB autopilot with optional radio coupler. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3274SW-D	Mitchell automatic flight system AK742 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3275SW-D	Mitchell automatic flight system AK743 consisting of Century IV autopilot with optional remote annunciator. Issued 3/16/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A12	SA3316SW-D	Installation of Mitchell command electric trim system AK778. Issued 11/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
R182; T.C. 3A13	SA3434WE	Installation of Pathfinder autopilot systems. Issued 2/13/79.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
185 Series; T.C. 3A24	SA4-1617	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
185 Series; T.C. 3A24	SA339SO	Conversion of aircraft for parachute jumping operations.	SO	34288	Falling Angels, Inc. 339 E. New York Avenue De Land, FL 32720
185 Series; T.C. 3A24	SA84CE	25-gallon auxiliary fuel system in cargo pack. (Aircraft equipped with 62-gallon usable main fuel tanks only.)	CE	45250	Javelin Aircraft Company, Inc. 9175 E. Douglas Wichita, KS 67207
185 Series; T.C. 3A24	SA108SW	Edo 289-2700 and 439-2705 amphibious floats.	SW	62280	Pan Air Corporation P.O. Box 26425 New Orleans, LA 70113
185 Series; T.C. 3A24	SA111CE	Retractable lifting handles Model H, P/N 50-10.	GL	87750	Woychik Aircraft Equipment 2112 Clark Street Middleton, WI 53562
185 Series; T.C. 3A24	SA147SW	Edo 429-2705 or 289-2700 amphibious floats.	SW	27270	Cruse Aviation, Inc. 8501 Telephone Road Houston, TX 77002
185 Series; T.C. 3A24	SA172WE	Conversion of aircraft for parachute jumping and aerial photography operations.	RM	73896	Southwestern Skyways, Inc. P.O. Box 1639 Ogden, UT 84401
185 Series; T.C. 3A24	SA202WE	Cessna 210 wing tip assemblies 1223000-1, -2, and wing tip mounted navigation lights.	NW	49270	Lake Aero Service 9306 Veterans Drive, SW Tacoma, WA 98402
185 Series; T.C. 3A24	SA215SW	L-2 autopilot.	SW	03120	Aerotron Radio Company P.O. Box 8396 Tulsa, OK 74101
185 Series; T.C. 3A24	SA213WE	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
185 Series; T.C. 3A24	SA261NW	Installation of automatic flagman. Issued 2/5/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362
185 Series; T.C. 3A24	SA343EA	Holes in floor of aircraft for use of viewfinder and camera.	NE	50780	Herbert P. Lindblad Mousam Road Springfield, ME 04487
185 Series; T.C. 3A24	SA417WE	Tormo tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
185 Series; T.C. 3A24	SA1081WE	B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
185 Series; T.C. 3A24	SA1568WE	Installation of emergency fuel system.	WE	59730	Missionary Aviation Fellowship P.O. Box 2828 Fullerton, CA 92632

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
185 Landplane; T.C. 3A24	SA943WE	Installation of Continental TSIO-470-B engine.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA 91105
185, 185A, B, C, D, 210, 210A, B, C, 210-5, 210-5A, 210E, F, G, H, J, K, L; T.C. 3A21, 3A24	SA1-629	Install 300 series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
185, A, B, C, D, E, A185E; T.C. 3A24	SA3-717	Ski installation: main gear Model 4000; tail gear Model 1500, CT-3600, CT-3200, CT-3400. Amended 2/19/76.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
185, 185A, 185B; T.C. 3A24	SA123CE	High intensity wing tip lights Model B and tail light Model C with or without fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
185, 185A, B, C, D, E, A185E; T.C. 3A24 (Floatplane configuration)	SA169CE	Install Wipline Model 3700 or 3900 twin floats. Amended 7/22/76.	GL	06750	Wipline, Inc. South End Doane Train Inver Grove Heights, MN 55075
185 - 185D;	SA324AL	Installation of Continental IO-520-D engine. Revised 6/16/69.	AL	08472	Alaska Air Guides, Inc. P.O. Box 4165 Anchorage, AK 99503
185 thru 185E, A185E, A185F; T.C. 3A24	SA328CE	Install Model 180-85 aqua floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA445CE	Installation of Pee Kay 3500, A3500, B3500, C3500, 2950 or 3000 seaplane floats (TSO-C27-2). Amended and reissued 1/19/79.	EA	29998	P K Floats DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
185, 185A, 185B, 185C, 185D, 185E, A185E, A185F; T.C. 3A24	SA468GL	Modification of fuel tank caps by the incorporation of an alternate vent. Issued 11/17/80.	GL	36742	John J. Francissen 426 Pleasant Drive Roselle, IL 60172
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA472GL	Installation of Great Lakes Aero Products windshield P/Ns W-2073, W/T-2073 and W/G-2073. Issued 11/17/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
185, 185A, 185B, 185C, 185D, 185E, A185E; T.C. 3A24	SA480AL	Installation of EDO-AIRE Mitchell Century I autopilot and omni tracker. Issued 5/25/72.	AL	03124	Aerotronics of Alaska, Inc. Box 4-1582 Anchorage, AK 99509
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA525NW	Installation of Continental IO-520-D engine and McCauley D2A34C58/90AT-4 propeller. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185, 185A, 185B, 185C, 185D, 185E, 185F; T.C. 3A24	SA526NW	Installation of Edo Model 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA587NW	Installation of Hartzell HC-C3YF-1RF/F9587C-15 propeller on Continental IO-520-D engine. Issued 5/5/78.	AL	08492	Alaska Propeller Specialists, Inc. 5251 Lakeshore Drive Anchorage, AK 99503
185, 185A, 185B, 185C, 185D, 185E; T.C. 3A24	SA631AL	Install leading edge cuff. Issued 4/28/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA746CE	Install Altair Model 3630 floats.	GL	10000	Altair Enterprises, Inc. 2589 Seppala Boulevard North St. Paul, MN 55109
185, S/N 185-1201 and on; T.C. 3A24	SA866CE	Installation of electro pneumatic stall warning system. Issued October 1972.	CE	47500	Kaeton Engineering Company 1000 West 55th Street South Wichita, KS 67217
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA954SW	Installation of droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
185, 185A thru 185E, A185E and F Landplanes, Seaplanes and Amphibians; T.C. 3A24	SA968CE	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences, and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
185, 185A, C, D, E, A185E; T.C. 3A24	SA1351CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
185, 185A thru 185E, A185E, A185F Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA1441WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge (except A185F) stall fence, flap actuated elevator trim system and installation of SC-100 stall warning system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA1495CE	Installation of flap and aileron gap seals. Issued 5/21/79.	CE	05060	Aircraft Development Company 1326 North Westlink Boulevard Wichita, KS 67212
185, 185A thru 185E; T.C. 3A24	SA2108WE	Installation of Madras Air Service wing tips. Amended 2/21/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
185, 185A thru 185E, A185E Landplane, Floatplane and Amphibian, 185, 185A thru 185E Skiplane; T.C. 3A24	SA2189WE	Installation of recontoured wing leading edge, stall fences, wing tips, and positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
185, 185A, 185B, 185C, and 185D, 185E, A185E, A185F Landplane; T.C. 3A24	SA2529WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 9/20/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite G Santee, CA 92071
185, 185A, B, C, D, E, A185E; T.C. 3A24	SA2802SW	Install leading edge cuffs, stall fences, aileron seals, and wing tips. Amended 11/17/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
185, A, B, C, D, E, A185E; T.C. 3A24	SA3084SW-D	Automatic flight system AK554, consisting of Century I autopilot with optional omni tracker. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
185, A, B, C, D, E, A185E; T.C. 3A24	SA3085SW-D	Automatic flight system AK555, consisting of Century IIB autopilot with optional radio coupler. Issued 11/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
185, 185A, B, C, D, E, A185E, F; T.C. 3A24	SA3383WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87019
185A, A185F (Seaplane Configuration only); T.C. 3A24	SA7GL	Installation of Model 3730 amphibious floats, Model 3700, 3800 or 3900 seaplane floats. Amended 7/20/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
185A, 185E, A185E, A185F, 206, P206, P206A, U206A, TP206A, TU206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E, U206F, TU206F, U206G; T.C. 3A24, A4CE	SA522NW	Installation of float hatch kits on Edo 582-3430 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
185A, B, C, D, E, A185E, A185F; T.C. 3A24	SA4139WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Issued 4/10/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw AVenue Irvine, CA 92705
185B; T.C. 3A24	SA199EA	Installation of Tactair T-3 autopilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
185E, A185, A185F; T.C. 3A24	SA240NW	Installation of McCauley D3A32C90/ propeller, Cessna spinner, governor, and associated systems on Continental IO-520-D engine. Amended 1/16/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
A185E; T.C. 3A24	SA507NW	Installation of Edo floats and Cessna cargo pack, Issued 8/31/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A185E; T.C. 3A24	SA592AL	Install leading edge cuff, stall fences, and flap and aileron gap seals. Issued 7/19/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
A185E; T.C. 3A24	SA930SW	Droop ailerons with flaps. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
A185E; T.C. 3A24	SA1148SW	Aileron drooping device. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
A185E; T.C. 3A24	SA1990WE	Installation of Tritan Amphibious float model TA 3500. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
A185E (Floatplane Amphibian configuration only); T.C. 3A24	SA805CE	Installation of Wipline Model 3730 amphibious twin floats. Issued and amended 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
A185E, A185F; T.C. 3A24	SA501NW	Installation of McCauley D3A32C90/82NC-2 on Lycoming IO-520-D engine. Issued 8/29/77.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
A185E, A185F; T.C. 3A24	SA832EA	Installation of Edo Model 582-3430 seaplane floats. Amended 7/25/80.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185E, A185F; T.C. 3A24	SA877EA	Installation of Pee Kay Model 3500A (TSO C-27-2) amphibious floats. Amended and reissued 7/24/80.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 1 Barstow Road Great Neck, NY 11021
A185E, A185F (Floatplane and Amphibious Configurations; T.C. 3A24	SA985EA	Installation of McCauley Propeller Model D3A32C90/82NC-2. Amended 2/25/75.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
A185E, A185F; T.C. 3A24	SA2875WE	Installation of modified brake system. Issued 4/30/74.	WE	59730	Mission Aviation Fellowship P.O. Box 142 Ramona, CA 92065
A185F; T.C. 3A24	SA17NE	Installation of EDO Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Reissued and amended 9/5/79.	NE	32625	EDO-AIRE Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185F; T.C. 3A24	SA51NW	Installation of Cessna cargo pack. Issued 7/31/73.	NW	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA164NW	Installation of EDO-628-2960 seaplane floats with Cessna cargo pack kit No. AK-185-23D, cargo pack fairing, rudder non-linear centering spring and ventral fin. Issued 2/28/75.	NW	46400	Jobmaster Company, Inc. 608 W. Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA420NW	Installation of cargo pac and McCauley 3-bladed propeller. Issued 3/17/77.	NW	67135	Renton Aviation, Inc. 840 West Perimeter Road Renton, WA 98055
A185F; T.C. 3A24	SA558NW	Installation of Edo Model 696-3500 amphibious seaplane floats with Model 696-1200 attachment gear. Amended 1/8/81.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
A185F; T.C. 3A24	SA596NW	Install Cessna A185E wing panels. Issued 4/27/78.	NW	08215	Airmetal Northwest, Inc. P.O. Box 387 Arlington, WA 98223
A185F; T.C. 3A24	SA634AL	Install leading edge cuff. Issued 5/31/78.	AK	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
A185F; T.C. 3A24	SA780NW	Installation of Edo 628-2960 floats on a A185F equipped with Cessna cargo pod (P/N 0700062-43) must include Cessna ventral fin (P/N 0712764-2) and linear rudder centering system. Issued 6/1/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A185F; T.C. 3A24	SA3251SW-D	Mitchell automatic flight system AK703 consisting of Century IV autopilot or AK703FD consisting of Century IV flight director with optional remote annuciator. Issued 11/18/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A185F; T.C. 3A24	SA4245SW	S-TEC system 60 (two axis) flight guidance system, Model ST-024 with optional flight director/steering horizon and optional vertical speed indicator/selector (14 volt system). Issued 12/11/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
188, A188; T.C. A9CE	SA709CE	Install wing fence.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
188, A188; T.C. A9CE	SA1126SW	Alternate air filter.	SW	43500	Hutchinson Aircraft Box 1070 Borger, TX 79006
188, A188; T.C. A9CE	SA1352CE	Chrome-plated brake disc installation. Issued 3/2/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
188, A188; T.C. A9CE	SA1919WE	Installation of Madras Air Service wing tips. AMended 8/16/72.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
188, 188A, A188, A188A; T.C. A9CE	SA142NW	Normal and restricted category installation of recontoured wing leading edge and stall fences. Options: wing strut fillet or wing tips. Issued 12/11/74.	NW	68500	Robertson Aircraft Corporation 839 Perimeter Road Renton, WA 98055
188, 188A, A188, A188A, T.C. A9CE	SA1007CE	Installation of full spar leading edge cuffs and drooped wing tips. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
188, 188A, A188, A188A; T.C. A9CE	SA1355SW	Wing leading edge cuff to increase leading edge radius. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
188, 188A, A188, A188A; T.C. A9CE	SA1373SW	Fairing on wing strut intersection. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
188, 188A, A188, A188A; T.C. A9CE	SA1745WE	Installation of Automatic Flagman (Marker Dispensing Unit). Amended 8/10/73.	NW	03500	Air-Ag, Inc. Route 4, City County Airport Walla Walla, WA 99362
188, 188A, A188, A188A; T.C. A9CE	SA2340WE	Installation of recontoured wing leading edge, drooped ailerons, stall fences, new wing strut fillet; optional flap actuated elevator trim system, Robertson wing tips 10-105, Madras Air Services super tips. Issued 4/13/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
188, 188A, 188B, A188, A188A, A188B; T.C. A9CE	SA1179CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508, Renner Field Goodland, KS 67735
188, 188A, 188B, A188, A188A, A188B; T.C. A9CE	SA4099WE	Installation of two Conrel dispensing pads, drawing No. 21940. Reissued 5/8/80.	WE	08550	Albany International Controlled Release Division P.O. Box 537 Buckeye, AZ 85326
A188; T.C. A9CE	SA543SO	Extruded aluminum leading edge cuff. Issued 8/2/73.	SO	79820	Tunico P.O. Box 356 Tunica, MS 38676
A188, A188A, A188B; T.C. A9CE	SA99RM	Installation of freon type air conditioning system. Issued 7/12/77.	RM	32300	Dale Edlund Billings Aircraft, Logan Field Billings, MT 59102
A188, A188A, A188B; T.C. A9CE	SA900SO	Installation of cabin air conditioning. Issued 5/31/76.	SO	69228	Mr. Dwight Kerry Rudder Route 1, P.O. Box 11A Canton, MS 39046
A188B; T.C. A9CE	SA40RM	Installation of Freon air-conditioning system. Amended 3/22/76.	RM	45750	J B Systems, Inc. 120 S. Bowen Circle Longmont, CO 80501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A188B; T.C. A9CE	SA672NW	Installation of Hartzell HC-C3YF-1RF/F9587C-178 propeller on Continental IO-520-D engine. Issued 9/29/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
A188B, T188C; T.C. A9CE	SA461GL	Installation of hopper gate with positive metering device. Issued 10/22/80.	GL	50640	Eli Lilly and Company 740 South Alabama Street Indianapolis, IN 46285
190 Series; T.C. 790	SA3-227	ARC L-11 loop and housing, ARC ADF receiver R-30A and power unit, and ARC control head.	CE	44340	Interstate Airmotive, Inc. Lambert Field St. Louis, MO 63155
190 Series; T.C. 790	SA4-1075	Full flow lube oil filter 30409A-12 with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
190 Series; T.C. 790	SA4-1275	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
190 Series; T.C. 790	SA42WE	Eclipse Aviation generator 790-1B.	WE	34292	Robert F. Fallon 1201 Deborah Drive Tustin, CA 92680
190 Series; T.C. 790	SA220WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	69245	Rusty's Flying Service 1041 W. Alondra Compton, CA 90220
190 Series; T.C. 790	SA354SW	Cargo conversion.	SW	33994	Executive Airlines, Inc. 206 E. Terminal Drive International Airport San Antonio, TX 78205
190, 195; T.C. 790	SA573CE	Installation of block swivel action of crosswing gear.	CE	47250	Ray M. Jourdan 11001 E. 59th Street Raytown, MO 64133
190, 195; T.C. 790	SA1492WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
190, 195, 195A, 195B; T.C. A-790	SA54GL	Install Cleveland wheel and brake conversion kit, P/N 199-61. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
190, 195, 195B; T.C. A-790	SA120NW	Installation of Hartzell HC-B3P20-4/P10160-12E propeller on Jacobs-Page R-755S engine. Amended 4/20/77.	NW	87008	William Wiprud 6443 Southwest Beaverton Hillsdale Airport Portland, OR 97221
190, 195, 195A, B; T.C. A-790	SA1284CE	Replacement axles. Issued 10/13/76.	CE	19020	Butterfly Aviation, Inc. P.O. Box 736 Renner Field Goodland, KS 67735
190, 195, 195A, B; T.C. A-790	SA2388WE	Removal of left-hand exit. Issued 7/26/71.	WE	67014	Everett A. Redding 18250 Grand Avenue Elsinore, CA 92330
195; T.C. A-790	SA199GL	Installation of oil filter between engine oil gallery and propeller governor/nose case tappet rocker arm supply. Issued 11/4/77.	GL	60093	Richard C. Moen 536 South 1st Street Dundee, IL 60118
195; T.C. 790	SA1268SW	Jacobs-Page R-755-S engine. Reissued 10/27/80.	SW	44943	Jacobs Service Company 4305 Saturn Way Chandler, AZ 85224
205, 205A; T.C. 3A21	SA3836WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company 2240 Sawtelle Vouleward Los Angeles, CA 90064
205, 205A, 210, 210A, 210B, 210C, 210D, 210E, 210F, 210G, 210H, 210J, 210K, 210L, 210M; T.C. 3A21	SA2784SW	Installation of leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions Box 431 Udall, KS 67146
206 Series; T.C. A4CE	SA65NW	Installation of fiberglass wing tips. Issued 9/20/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
206 Series; T.C. A4CE	SA635SW	McCauley DA3A32C90/82NC-2 propeller.	SW	84395	L.L. Walker Company P.O. Box 5158 Houston, TX 77012

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206 Series; T.C. A4CE	SA669SW	AK218 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206; T.C. A4CE	SA685AL	Installation of Hartzell and blade propeller. Issued 5/16/80.	AL	08492	Alaska Propeller Specialists 5251 Lakeshore Drive Anchorage, AK 99503
206 Series; T.C. A4CE	SA727SW	AK231 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206; T.C. A4CE	SA864NW	Installation of RCA weather scout radar. Issued 11/21/79.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
206 Series; T.C. A4CE	SA1255WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	73760	Sonora Aviation, Inc. P.O. Box 1027 Carson City, NV 89701
206 Series; T.C. A4CE	SA1893WE	Installation of Brittain Flight Control Systems Model B-5, NAV-2B or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
206 Series; T.C. A4CE	SA3837WE	Installation of an air/oil separator. Issued 2/7/79.	WE	94396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
206, P206, U206, P206A, U206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA332CE	Installation of Wipline Models 3700 and 3900 twin floats on Cessna Floatplane configuration. (Floatplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
206, P206, U206; T.C. A4CE	SA392GL	Installation of Great Lakes Aero Products windsheild P/Ns W-2065, W/T-2065 and W/G-2065. Issued 3/10/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
*206, *P206, *P206A, *U206, *U206A, U206B, C, D, E, F, G (S/N U20603522 thru U20604649, U20604659 and up) (1979 models), TP206A, TU206A, B, C, D, E, F (S/N U20601701 thru U20602199); T.C. A4CE *These models are approved with a gross weight of 3500 lbs., all others approved with 3600 lbs. gross weight.	SA439NW	Installation of Edo-696M-3500 and/or 696-3500 amphibious floats. Reissued and amended 10/22/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
206, P206, U206, U206F, Floatplane configuration; T.C. A4CE	SA474CE	Install Aqua Model 3526 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
206, P206, P206A, TP206A, U206, U206A, thru G, TU206A thru TU206G; T.C. A4CE	SA512CE	Installation of Pee Kay Model 3500 or A3500 or B3500 seaplane floats. Amended and reissued 7/29/80.	EA	29998	P K Floats DeVore Aviation Corporation 1 Barstow Road Great Neck, NY 11021
206, P206, U206, P206A, TU206A, TP206A, U206B, TU206B, U206C, TU206C, U206A, U206D, TU206D, U206E, TU206E; T.C. A4CE	SA666CE	Install Wipline Model 3730 twin floats (amphibious). (Seaplane configuration only.) Amended and reissued 7/22/76.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075
206, P206, P206A, TP206A, U206, U206A thru G, TU206A thru G; T.C. A4CE	SA851EA	Installation of Pee Kay Model 3500A, C3500A and/or D3500A amphibious floats (TSO C-27). Amended and reissued 7/29/80.	EA	29998	P K Floats DeVore Aviation Corporation 1 Barstow Road Great Neck, NY 11021
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA893CE	Camera hole cut-out in lower fuselage structure. Reissued 2/17/76.	GL	59452	Mr. Wayne B. Millard 4144 South Highway 101 Minneapolis, MN 55345

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206, P206, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA908CE	Install STOL kit. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F landplanes only; T.C. A4CE	SA990CE	Install STOL kit (wing leading edge cuffs, drooped tips, and stall fences). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, TP206A, B, C, D, TU206A, B, C, D, E, F; T.C. A4CE	SA1069CE	Enlargement of factory installed camera hole and installation of a view finder hole. Issued November 1974.	CE	36000	FloAir, Inc. Hangar #17 Mid-Continent Airport Wichita, KS 67209
206, U206A, B, D, E, TU206A, B, D, E, P206A, B, C, D, E; T.C. A4CE	SA1353CE	Chrome-plated brake disc installation. Issued 8/22/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
206, P206, P206A, P206B, P206C, P206D, P206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F; T.C. A4CE	SA1513WE	Installation of flap actuated aileron droop system, recontoured wing leading edge (except TU206F and U206F), and flap actuated elevator trim system. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, 210-5, 210-5A; T.C. A4CE, 3A21	SA1870WE	Installation of Brittain Model NAV-2B Flight Control. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
206, U206, P206 Landplane and Floatplane, P206B, TP206B, P206C, TP206C, P206D, TP206D, P206E, TP206E Landplane and Skiplane, P206A Landplane, U206A, U206B, U206C, U206D, TU206A, TU206B, TU206C, TU206D, TU206E Skiplane; T.C. A4CE	SA2326WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
206, P206, P206A, B, C, D, E, F, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G; T.C. A4CE	SA2479WE	Installation of larger fuel containing wing tips. Amended 7/25/77.	WE	35746	Flint Aero 8402 N. Magnolia, Suite G Santee, CA 92071
206, P206, 206-A, -B, -C, -D, -E, TP206A, B, C, D, E, U206, A, B, C, D, E, F; T.C. A4CE	SA2855SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F, G, TP206A, B, C, D, E, TU206A, B, C, D, E, F, G; T.C. A4CE	SA3348WE	Recognition light installation on horizontal stabilizer. Issued 3/7/77.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
206, P206, P206A, B, C, D, E, U206, U206A, B, C, D, E, F; T.C. A4CE	SA3462WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 8/19/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
206, P206, A, B, C, D, E, TP206, A, B, C, D, E, U206, A, B, C, D, E, F, G, TU206A, B, C, D, E, F, G; T.C. A4CE	SA3739WE	Installation of Silver Instruments' fueltron IG or fueltron IP digital fuel flow and totalizer system. Amended 4/2/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206 (S/N 206-0001 thru 206-0137 except 206-0094, S/N 206-0094, 206-0138 thru 206-0275), U206 (S/N U206-04074), P206 (S/N P206-0001 thru P206-00647); T.C. A4CE	SA3825WE	Installation of replacement flexible fuel cell in wings. Issued 8/2/79.	WE	08357	Air-Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
P206A/B/C/D/E, U206A/B/C/D/E/F/G; T.C. A4CE	SA3686WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
P206C, P206D, U206C, U206D, U206E; T.C. A4CE	SA1431SW	Mitchell automatic flight system AK368 consisting of Century III autopilot with optional automatic electric pitch trim, radio, and glide slope couplers. Issued 2/25/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206; T.C. A4CE	SA652NW	Installation of McCauley D3A32C90/82NC-2 propeller on Continental IO-520-A engine. Issued 8/15/78.	NW	64790	Robert Plummer Bob's Aircraft Maintenance Challis, ID 83226
U206, TU206; T.C. A4CE	SA1037CE	Installation of 26 gallon auxiliary fuel tank in baggage compartment. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
TP206A, B, C, D, E, TU206A, B, C, D, E, F; T.C. A4CE	SA2782SW	Installation of Continental TSIO-520-M. Issued 5/30/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
TP206A, TP206B, TP206C, TP206D, TP206E, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F, TU206G; T.C. A4CE	SA3856WE	Installation of an air/oil separator. Issued 3/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1430SW	Mitchell automatic flight system AK350, consisting of Century I autopilot with omni tracker. Issued 2/7/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, U206E, P206C, P206D, P206E; T.C. A4CE	SA1449SW	Mitchell automatic flight system AK369, consisting of Century II autopilot with optional radio coupler. Issued 3/22/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Minerals Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1572SW	Mitchell automatic flight system AK405 consisting of Century IIB autopilot with optional radio coupler. Issued 12/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1846SW	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/electronic pitch trim, radio coupler, and glide slope coupler. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA1887SW	Automatic flight system AK470, consisting of Century IIB autopilot with optional radio coupler. Issued 6/17/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, U206D, P206C, P206D, P206E; T.C. A4CE	SA3097SW-D	Mitchell automatic flight system AK471 consisting of Century III autopilot with optional command/electronic pitch trim, radio coupler and glide slope coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206C, -D, -E, -F, TU206C, -D, -E, -F, P206C, -D, -E, TP206C, -D, -E; T.C. A4CE	SA2164WE	Installation of Edo Model FD-3500A (TSO C-27-2) amphibious floats. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Gardner Municipal Airport Box 464 Gardner, MA 01440
U206F, TU206F, U206G, TU206G, T.C. A4CE	SA3GL	Installation of Bendix FCS-810 autopilot and flight director. Amended 2/13/78.	GL	66080	Russell Hammer Radio Ranch, Inc. Radio Ranch Airport Polo, IL 61064
U206F, G, TU206F, G (Seaplane configuration only); T.C. A4CE	SA18GL	Installation of Wipline Model 3730 floats. Amended 6/12/79.	GL	86750	Wipline, Inc. South End Doane Trail Inver Grove Heights, MN 55075

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
U206F, TU206F; T.C. A4CE	SA1845SW	Mitchell automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 3/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3177SW-D	Install Mitchell automatic flight system AK470 consisting of Century IIB with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, G, TU206F, G; T.C. A4CE	SA3178SW-D	Install automatic flight system AK469 consisting of Century I autopilot with optional omni tracker. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
U206F, U206G, TU206F, TU206G; T.C. A4CE	SA3262SW-D	Mitchell automatic flight system AK715 consisting of Century III autopilot with optional radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3263SW-D	Mitchell automatic flight system AK714 consisting of Century IIB autopilot with optional radio couplers. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3264SW-D	Mitchell automatic flight system AK713 consisting of Century I autopilot with optional omni tracker. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F, U206G, TU206G; T.C. A4CE	SA3265SW-D	Mitchell automatic flight system AK717/FD consisting of Century IV/flight director autopilot with optional remote annunciator. Issued 2/17/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
U206F, TU206F (Seaplane configuration only); T.C. A4CE	SA3296WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/23/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
U206F, U206G, TU206F, TU206G;	SA3454WE	Installation of an emergency fuel system. Amended 2/7/78.	WE	59730	Mission Aviation Fellowship P.O. Box 2828 Fullerton, CA 92633
U206G, TU206G; T.C. A4CE	SA1480CE	Installation of King KFC200 automatic flight control system, two axis, with or without flight director. Issued 3/27/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
TU206C; T.C. A4CE	SA566CE	Install one or two blister windows.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
TU206C, TU206D; T.C. A4CE	SA935EA	Installation of window in bottom of fuselage at F. Station 35.5. Amended 4/18/73.	EA	52060	Long Island Airways Box 248 Ronkonkoma, NY 11779
TU206G; T.C. A4CE	SA831NW	Installation of an aerial flare dispenser system. Issued 9/11/79.	NW	16887	Boise Inter-Agency Fire Center 3905 Vista Avenue Boise, ID 83705
TU206G; T.C. A4CE	SA852NW	Installation of PeeKay Model 2300 seaplane floats. Reissued 9/19/80.	NW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
TU206G; T.C. A4CE	SA4004SW	Camera port. Issued 6/20/79.	SW	28490	Daily Tubbs Aero, Inc. 2115 Danbury Drive San Antonio, TX 78217
206, 207, 210 Series; T.C. A4CE, A16CE, 3A21	SA2809SW	Install Symbolic Displays CFS-1000 electronic fuel flow metering system. Issued 7/2/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
206, 210 Series; T.C. 3A21, A4CE	SA149SW	Automatic pilot AK120, AK120E, AK102E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206, 210 Series; T.C. 3A21, A4CE	SA245WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
206, 210 Series; T.C. 3A21, A4CE	SA526SW	Automatic trim AK171.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
206, 210 Series; T.C. 3A21, A4CE	SA674WE	Flight control system B-4 including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
207; T.C. A16CE	SA1402SW	Mitchell automatic flight system AK357 consisting of Century II autopilot with optional radio coupler. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1403SW	Mitchell automatic flight model AK356 consisting of Century I autopilot with optional omni tracker. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA1404SW	Mitchell automatic flight system Model AK361 consisting of command/electric trim system. Issued 12/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
207; T.C. A16CE	SA2856SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
207, 207A; T.C. A16CE	SA696AL	Installation of Hartzell three-blade constant speed propeller. Issued 10/10/80.	AL	08492	Alaska Propeller Specialists 5251 Lakeshore Drive Anchorage, AK 99503
207, T207; T.C. A16CE	SA1354CE	Chrome-plated brake disc installation. Issued 8/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
207, T207; T.C. A16CE	SA2121WE	Installation of recontoured wing leading edge, drooped ailerons, in flaps down mode, stall fences, and elevator trim spring. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
207, T207; T.C. A16CE	SA2327WE	Installation of recontoured wing leading edge, stall fences, and wing tips. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
207, T207; T.C. A16CE	SA2676WE	Installation of larger fuel containing wing tips. Amended 5/23/77.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041
207, T207; T.C. A16CE	SA3427WE	Installation of tail flood light on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
210 Series; T.C. 3A21	SA1-625	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA3-503	L-2B autopilot with or without altitude controller and/or approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
210 Series; T.C. 3A21	SA4-1086	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
210 Series; T.C. 3A21	SA4-1372	Brake blocks AB-6526 and AB-6527.	EA	46748	Johns-Manville Corporation 22 E. 40 Street New York, NY 10001
210 Series; T.C. 3A21	SA4-1416	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA20SW	Automatic pilot AK086, AK086E or AK086R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA89SW	Automatic pilot AK112.	SW	60000	Mitchell Industries, INc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210 Series; T.C. 3A21	SA89NW	Installation of King VOR Model KX 170B or KX 175B, King DME Model KN65 and King Area Navigation computer Model KN74. Issued 2/11/74.	NW	70040	Salem Aviation 2680 Aerial Way, S.E. Salem, OR 97302
210 Series; T.C. 3A21	SA103SW	Automatic pilot AK111.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA110EA	Removal of right front door and other modifications.	EA	72108	Sky Diving, Inc. Cameron Airpark Medford, NJ 08055
210 Series; T.C. 3A21	SA118EA	Installation of Fram Part Flow Lube Oil Filter Model PB 55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
210 Series; T.C. 3A21	SA199WE	Conversion of aircraft for parachute jumping and aerial photography operations.	WE	82270	V. Vincent Vandever, Inc. 6447 W. Reade Avenue Glendale, AZ 85301
210 Series; T.C. 3A21	SA330SW	Automatic pilot AK126 and lateral guidance/radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA420SW	Automatic pitch trim AK133.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA464EA	Propeller, spinner, and governor.	GL	73830	Southeastern Ohio Air Service, Inc. P.O. Box 863 Municipal Airport Zanesville, OH 43701
210 Series; T.C. 3A21	SA469WE	Installation of Brittain Model PC-1 Pitch Assist and Model AH-1 Altitude Hold (optional). Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA531CE	Installation of Canairco 1214 WS supplementary light.	GL	19824	Canairco Limited 400 1st Avenue North Minneapolis, MN 55401
210 Series; T.C. 3A21	SA618WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA627WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA637SW	AK209 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA675SW	AK212 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210 Series; T.C. 3A21	SA1100SW	Increase wing leading edge radius. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
210 Series; T.C. 3A21	SA1305WE	PCA-1 pitch assist with altitude hold. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1343WE	Installation of Brittain Industries Model B-4 Flight Control System. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1471WE	Installation of Brittain Model CSA-1 Stability Augmentation System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1478WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1606WE	Installation of Brittain Industries B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210 Series; T.C. 3A21	SA1609WE	Installation of Brittain Industries Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1618WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1631WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1672WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1684WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1882WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA1887WE	Installation of Brittain Model NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210 Series; T.C. 3A21	SA2720WE	Installation of Symbolic Displays IFC-1A anti-collision lights. Amended 3/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
210, 210A; T.C. 3A21	SA1527WE	Installation of twelve gallon auxiliary fuel tank in each wing inboard of tip. Amended 8/7/73.	WE	35780	William E. Flint 7745 Ropalt Street La Mesa, CA 92041
210, 210A; T.C. 3A21	SA3377WE	Installation of flap gap fairing. Issued 3/24/77.	WE	78450	Thermal Aircraft Company 56-850 Tyler Street Thermal, CA 92274
210, 210A; T.C. 3A21	SA3732WE	Installation of Knisley mufflers in lieu of original Cessna mufflers. Issued 9/14/78.	WE	84542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
210, 210A, 210B, 210C, 210K, 210L, T210K, T210L, 210M, T210M, P210N; T.C. 3A21	SA52GL	Installation of Parker Hannifin wheel and brake conversion kit, P/N 199-60, on Model P210 install kit No. 199-60A. Reissued 9/11/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Avon Center Road Avon, OH 44011
210, 210F, T210F (205), 210-5 (205A), 210-5A; T.C. 3A21	SA64NW	Installation of fiberglass wing tips. Issued 9/13/73.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
210, 210A, 210B, 210C, 210-5; T.C. 3A21	SA93CE	High intensity wing tip lights Model B, and tail light Model C, with or without fuselage lights. Reissued 10/17/74.	GL	42626	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
210, 210A, B, C, D, E, F, 210-5(205), 210-5A (205A), T-210F; T.C. 3A21	SA940CE	STOL Kit installation. Reissued 4/24/79.	CE	86195	Bob or Barbara Williams P.O. Box 608 Udall, KS 67146
210, 210A, 210B, 210C, 210D, 210E, 210F; T.C. 3A21	SA1048CE	Installation of STOL kit (wing leading edge cuffs, stall fences, aileron gap seals and droop wing tips). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
210, -A, -B, -C, 210-5 (205), 210-5A (205A); T.C. 3A21	SA1098WE	Installation of Rajay turbosupercharged Continental IO-470-E or IO-470-S engine. Amended 8/11/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
210, 210A thru 210H, 210J, K, L, T210F thru T210H, T210J, K, L; T.C. 3A21	SA1525WE	Installation of droop ailerons in flaps down mode, recontoured wing leading edge, and elevator trim spring (except on T210K, L, and 210K and L). Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
210 thru 210K, T210F thru T210K, 210-5 (205), 210-5A (205A); T.C. 3A21	SA2242WE	Installation of recontoured wing leading edge stall fences, and for 206, 205A, 210A, 210B and 210C positive aileron seals. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210, 210A, B, C, D, E, F, G, H, J, K, L, M, T210F, G, H, J, K, L, M, (205) 210-5, (205A), 210-5A, P210N; T.C. 3A21	SA3312WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
210, 210A, B, C, D, E, F, G, H, J, K, L, M, N, P210; T.C. 3A21	SA3053WE	Installation of a cargo container. Amended 4/25/80.	WE	02465	Aero Pod, Inc. 17202 Sandra Lee Lyn Huntington Beach, CA 92649
210A, B, C, D, E, F; T.C. 3A21	SA3649WE	Installation of replacement flexible fuel cell in the wings of the 210 Cessna aircraft. Issued 5/16/78.	WE	08357	Air Tech Services 8147 Secura Way Santa Fe Springs, CA 90670
210B, C; T.C. 3A21	SA3144SW-D	Mitchell automatic flight system AK604 consisting of Century I autopilot with optional omni tracker. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B, C; T.C. 3A21	SA3145SW-D	Mitchell automatic flight system AK605 consisting of Century IIB autopilot with optional radio coupler. Issued 6/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210B; 210-5(205), 210-5A(205A); T.C. 3221	SA3522WE	Installation of Knisley muffler in lieu of original Cessna mufflers. Issued 11/11/77.	WE	48542	Knisley Welding, Inc. 11267-G Coloma Road Rancho Cordova, CA 95670
210B, 210C, 210E, 210-5(205, 210-5A (205A); T.C. 3A21	SA393GL	Installation of Great Lakes Aero Products windwhield, P/N W-2065, W/T-2065, W/G-2065. Issued 3/10/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
210C; T.C. 3A21	SA197EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
210C, D, E, F, G, H, J, K, T210F, G, H, J, K, 210-5(205), 210-5A(205A); T.C. 3A21	SA1312CE	Chrome-plated brake disc installation. Amended 9/13/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
210D, E; T.C. 3A21	SA376NW	Installation of McCauley D3A32C88-XLM/S-82NC-2 propeller and Continental IO-520-A engine. Issued 11/15/76.	NW	34827	Felts Field Aviation 3100 North Division Spokane, WA 99207
210D, E, F, T210F; T.C. 3A21	SA906SW	Mitchell automatic aileron stabilizer AK211 and omni tracker AK246.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, E, F, T210F; T.C. 3A21	SA1376SW	Mitchell automatic flight system AK349 consisting of Century I with optional omni tracker. Issued 10/4/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, E, F, T210F; T.C. 3A21	SA3141SW-D	Mitchell automatic flight system AK620 consisting of Century IIB autopilot with optional radio coupler. Issued 6/3/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210D, 210E, 210F, T210F; T.C. 3A21	SA2677WE	Installation of larger fuel containing wing tips. Amended 4/6/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210D, E, F, G, H, J, K, L, M, T210F, G, H, J, L, M, K, P210N; T.C. 3A21	SA3751WE	Installation of Fueltron IG digital fuel flow and totalizer system. Amended 11/22/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
210D, 210E, P206; T.C. 3A21, A4CE	SA693WE	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
210D, E, F, G, H, J, K; T.C. 3A21	SA790CE	Installation of engine condition monitor kit ECM-6. Issued August 1971.	GL	31750	ECM Corporation 412 North Weinbach Avenue Evansville, IN 47711

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210G; T.C. 3A21	SA829SW	Automatic flight system AK254 Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G; T.C. 3A21	SA850SW	AK254 consisting of Century III autopilot with optional aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, T210G, 210H, T210H, 210J, T210J, 210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N; T.C. 3A21	SA966CE	Installation of leading edge cuffs, droop tips, aileron gap seals, and stall fences. Amended 4/25/80.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
210G, H, J, K, L, M, N, T210G, H, J, K, L, M, N; T.C. 3A21	SA1618CE	Installation redundant NASA type fuel vent system and modification of fuel vapor return system. Amended 1/27/81.	CE	84955	Wells Aircraft, Inc. P.O. Box 858 Hutchinson, KS 67501
210G, H, J, K, L, M, T210G, T210H, T210J, T210K, T210L, T210M, 210N, P210N, T210N; T.C. 3A21	SA2862WE	Installation of larger fuel containing wing tips. Amended 7/23/79.	WE	35746	Flint Aero 8402 North Magnolia, Suite G Santee, CA 92071
210G, H, J, T210G, H, J; T.C. 3A21	SA3168SW-D	Automatic flight system AK641 consisting of Century IV autopilot or AF641-FD consisting of Century IV flight director with optional remote annuciator. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J; T.C. 3A21	SA3169SW-D	Automatic flight system AK642 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, T210G, H, J, K; T.C. 3A21	SA3170SW-D	Automatic flight system AK643 consisting of Century IIB autopilot with optional radio coupler. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210G, H, J, K, T210G, H, J; T.C. 3A21	SA3171SW-D	Automatic flight system AK644 consisting of Century I autopilot with optional omni tracker. Issued 12/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
T210F; T.C. 3A21	SA1042SW	Hartzell-Wren beta control system. Reissued 9/20/77.	SW	64271	Peterson Aircraft Repair 5104 Rector Fort Worth, TX 76133
T210F; T.C. 3A21	SA2277WE	Installation of Brittain Industries B2C flight control systems. Amended 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G; T.C. 3A21	SA1420WE	Installation of Brittain Industries B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
T210G, H, J; T.C. 3A21	SA2689SW	Install TSIO-520-M engine. Issued 12/9/77.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
210H; T.C. 3A21	SA725CE	Installation of electric gyros and standby power source.	CE	43374	Humphrey, Incorporated 434 North Oliver Wichita, KS 67208
210J; T.C. 3A21	SA2249WE	Installation of Brittain Industries B-7, NAV-2B, B2C and BSS flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210J, T210J, 210K, T210K; T.C. 3A21	SA1326SW	Mitchell automatic flight system AK334, consisting of Century II autopilot with optional radio coupler, and automatic aileron stabilizer. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210J, T210J, 210K, T210K; T.C. 3A21	SA1327SW	Mitchell automatic flight system AK332, consisting of Century I autopilot with optional omni tracker. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA71RM	Installation of air conditioning system. Reissued 9/17/80.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA210NW	Collins AP-107 low profile 3 axis automatic flight control system. Amended 12/2/77.	NW	24250	Collins Radio Group 855 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA211NW	Installation of Collins AP-107 low profile two axis automatic flight control system. Amended 12/2/77.	CE	24250	Collins Radio Group 855 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K, 210L, T210L, 210M, T210M; T.C. 3A21	SA212NW	Installation of AP-107 low profile yaw damper system. Amended 12/2/77.	CE	24250	Collins Radio Group 355 - 35th Street, N.E. Cedar Rapids, IA 52406
210K, T210K; T.C. 3A21	SA1325SW	Mitchell automatic flight system AK331, consisting of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler. Issued 6/10/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210K, T210K; T.C. 3A21	SA2199WE	Installation of Brittain Industries B-7, NAV-2B, B2C, and BSS flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
210K, T210K, 210L, T210L; T.C. 3A21	SA509SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 3/3/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210K, T210K, 210L, T210L, 210M, T210M, T210N; T.C. 3A21	SA1202CE	Installation of King Model KFC-200 two axis flight control system with or without flight director. Amended 11/28/78.	CE	48250	King Radio Corporation 400 North Robers Road Olathe, KS 66061
210L, T210L; T.C. 3A21	SA1506SW	Mitchell aytomatic flight system AK388, consisting of Century III autopilot with optional automatic pitch trim, radio and glide slope coupler. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA1507SW	Mitchell automatic flight system AK386 consisting of Century I with optional omni tracker. Issued 8/31/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA1526SW	Mitchell automatic flight system AK387, consisting of Century IIB autopilot with optional radio coupler. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3001SW-D	Automatic flight system AK468, Century IV autopilot or AK468FD Century IV flight director with electronic command/automatic pitch trim and optional remote annuciator panel. Issued 4/26/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3112SW-D	Automatic flight system AK566 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/5/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210L; T.C. 3A21	SA3247WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder Autopilot Systems and/or Pitch Trim Systems. Issued 8/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
210L, T210L, 210M, T210M; T.C. 3A21	SA1006SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 6/30/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210L, 210M, 210N, P210N, T210L, T210M, T210N; T.C. 3A21	SA1552CE-D	Installation of King KAS 297 altitude selector option. Amended 9/12/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
210L, 210M; T.C. 3A21	SA3685WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
210L, 210M, T210L, T210M; T.C. 3A21	SA3182SW-D	Mitchell automatic flight system AK387 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, 210M, T210L, T210M; T.C. 3A21	SA3183SW-D	Mitchell automatic flight system AK386 consisting of Century I autopilot with optional omni tracker system. Issued 2/4/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
210L, T210 S/N 21061040 and up, P210N, 210M, T210M, T210N; T.C. 3A21	SA3835WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow Amended 6/12/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714
210M, T210M, 210N, T210N, P210N; T.C. 3A21	SA1005SO	Installation of Bendix FCS-870 automatic flight control system, or installation of Bendix FCS-870 automatic flight control system with reduced flap motor speed. Amended 12/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
210N, P210N, T210N; T.C. 3A21	SA756NW	Installation of leading edge stall strips, change aileron droop. Issued 4/20/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N; T.C. 3A21	SA760NW	Installation of RCA digital weather radar system. Issued 5/3/79.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
210N, T210N, P210N; T.C. 3A21	SA1420CE	Install wing leading edge cuffs (with or without de-icer boots) and wing stall fences. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
P210N; T.C. 3A21	SA180RM	Installation of Aero Engineering air-conditioning system. Reissued 10/24/80.	RM	01806	Aero Engineering Corporation 2678 Delta Drive Colorado Springs, CO 80910
P210N; T.C. 3A21	SA1487CE	Installation of King KFC200 AFCS, two axis, with or without flight director. Issued 5/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
P210N; T.C. 3A21	SA3289SW-D	Mitchell automatic flight system AK737 consisting of Century IIB autopilot with optional radio and glide slope couplers. Issued 6/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P210N; T.C. 3A21	SA3290SW-D	Mitchell automatic flight system AK738 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
P210N; T.C. 3A21	SA3291SW-D	Mitchell automatic flight system AK739 consisting of Century IV autopilot or AK739FD consisting of Century IV FD autopilot with optional remote annunciator. Issued 5/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 210 Mineral Wells, TX 76067
210-5 (205), 210-5A (205A); T.C. 3A21	SA993CE	Install STOL kit (leading edge cuff, droop tips, stall fence and aileron gap seals). Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
T210F, G, H, J, K, L, TU206A, B, C, D, E, F, TP206A, B, C, D, E; T.C. 3A21, A4CE	SA4111SW	Hartzell PHC-J3YF-IRF/F7663-2Q propeller. Issued 4/10/80.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
T210L, T210M; T.C. 3A21	SA3857WE	Installation of an air/oil separator. Issued 3/13/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nusy, CA 91409
305A; T.C. 5A5	SA295SW	Three-place configuration. Reissued 11/18/80.	SW	32000	Ector Aircraft Company, Inc. 414 East Hillmont Road Odessa, TX 79762
305A; T.C. 5A5	SA353SW	Conversion of aircraft for parachute jumping operations. Reissued 11/18/80.	SW	32000	Ector Aircraft Company, Inc. 414 East Hillmont Road Odessa, TX 79762
305A Series; T.C. 5A5	SA504SW	Rerouting of oil to oil cooler and addition of extra cooler. Reissued 11/18/80.	SW	32000	Ector Aircraft Company, Inc. 414 East Hillmont Road Odessa, TX 79762

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
305A; T.C. 5A5	SA505SW	McCauley 1A200PM propeller.	SW	32000	Ector Aircraft Company, Inc. 414 East Hillmont Road Odessa, TX 79762
305A; T.C. 5A5	SA568SW	Gross weight increased to 2,300 2,300 pounds.	SW	32000	Ector Aircraft Company, Inc. 414 East Hillmont Road Odessa, TX 79762
305A; T.C. 5A5	SA1201SW	Lycoming O-540-A4B5 engine. Reissued 3/19/75.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
305A; T.C. 5A5	SA1620SW	Cessna 180 fuel cells. Issued 4/19/73.	SW	32000	Ector Aircraft Company, Inc. 414 East Hillmont Road Odessa, TX 79762
305A; T.C. 5A5	SA1702SW	20-gallon fuel cells. Issued 7/19/73. Reissued 11/18/80.	SW	32000	Ector Aircraft Company, Inc. 414 East Hillmont Road Odessa, TX 79762
305A, 305B; T.C. 5A5, 3A14	SA3-370	Model 3000 main skis and Model 1000 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
305A, B, C, D, E, F; T.C. 5A5, 3A14	SA2857SW	Leading edge cuffs, stall fences, aileron seals, wing tips. Reissued 6/6/80.	CE	86195	Bob Williams d/b/a Bush Conversions P.O. Box 431 Udall, KS 67146
310 Series; T.C. 3A10	SA1-21	Federal autopilot F-400.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
310 Series; T.C. 3A10	SA1-293	Lightweight reservoir pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-506	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA1-579	Taxi lamp in right outboard cowling.	GL	22400	Cincinnati Aircraft, Inc. Lunken Airport Cincinnati, OH 45202
310 Series; T.C. 3A10	SA3-55	Radio equipment.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705
310 Series; T.C. 3A10	SA3-440	L-3 autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA3-475	Full feathering, constant speed propellers, hubs 2AF36C26, blades 90MF-10.	GL	52720	McCauley Industrial Corporation 1807 Howell Avenue Dayton, OH 45401
310 Series; T.C. 3A10	SA3-636	M-4 flight control system with altitude controller.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA3-643	Transa-Strobe beacon B-7228.	GL	37096	Gas Equipment & Eng. Company 1015 Diamond Avenue Evansville, IN 47708
310 Series; T.C. 3A10	SA3-662	Hydraulic accumulator in each engine nacelle and new propeller governor C210355 or A210438.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
310 Series; T.C. 3A10	SA3-665	Cabin air temperature control system on Southwind (Stewart-Warner) 8240-A heater.	GL	82500	Vap-Air Division Vapor Corporation 6444 W. Howard Street Chicago, IL 60607
310 Series; T.C. 3A10	SA4-3	32-gallon auxiliary fuel tank in baggage compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-127	56-gallon auxiliary fuel tank in hat rack compartment.	WE	00430	Alden E. Acker 3330 Vosberg Street Pasadena, CA 91109
310 Series; T.C. 3A10	SA4-239	Thompson TF2800 engine-driven fuel pump.	WE	33460	Engineering Modification Company 6850 Vineland Avenue North Hollywood, CA 91603

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310 Series; T.C. 3A10	SA4-702	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
310 Series; T.C. 3A10	SA4-1217	Extension of augmenter tubes to trailing edge of wing.	WE	10116	AMC Augmenters 2648 N. Campbell Tucson, AZ 85700
310 Series; T.C. 3A10	SA4-1400	SP-3 autopilot.	WE	74570	Sperry Phoenix Company P.O. Box 2529 Phoenix, AZ 85000
310 Series; T.C. 3A10	SA4-1598	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA6SO	Window on each side of cabin between fuselage stations 89.25 and 109.375. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA37SO	Fuselage access holes in bottom skin of fuselage.	SO	76830	Sunny South Aircraft Service, Inc. 300 S.W. 41 Street County International Airport Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA44CE	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA58SO	Dual camera ports. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA59SO	One-piece windshield	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA60SO	Third window on each side of fuselage.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA61SO	Underwing exhaust system and nacelle fairings.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FI 33300
310 Series; T.C. 3A10	SA77SO	Engines modified per STC SE73SO.	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Fort Lauderdale, FL 33300
310 Series; T.C. 3A10	SA97SO	A, B, or C of turbocharged Continental IO-470-D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA99SO	Auxiliary fuel tanks under nacelle fairing (4-tank and 6-tank systems).	SO	79906	Turbo-Mod, Inc. P.O. Box 5003 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA109EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310 Series; T.C. 3A10	SA119CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
310 Series; T.C. 3A10	SA202SW	Cessna 0895000-8, -9 aft cowling doors.	SW	08168	Airline Aviation, Inc. P.O. Box 1024 Roswell, NM 88201
310 Series; T.C. 3A10	SA248SO	Increase takeoff gross weight to 4,830 pounds. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA254SO	Swept vertical tail. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310 Series; T.C. 3A10	SA303CE	Installation of Bendix Model M-4B/C autopilot flight control system. Amended 2/20/69.	SO	15475	The Bendix Corporation Bendix Avionics Products P.O. Box 9414 Ft. Lauderdale, FL 33300
310 Series; T.C. 3A10	SA325CE	GUARD system (Gear Up Automatic Response Device).	GL	43750	In-Flight Devices, Inc. 1621 W. Walnut Street Chicago, IL 60612

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310 Series; T.C. 3A10	SA347SW	Cowling and exhaust system.	SW	60089	Modern Aero Sales, Inc. 4837 S. Hampton Road Dallas, TX 75221
310 Series; T.C. 3A10	SA348WE	Installation of air induction system. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2606 E. Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA385WE	Turbocharged Lycoming IO-540-A1A5 engines. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
310 Series; T.C. 3A10	SA390WE	Pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA444NW	Replace original split flaps with Fowler flaps. Issued 5/12/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
310 Series; T.C. 3A10	SA448EA	Electrothermal propeller deicing system.	GL	38500	The B.F. Goodrich Company Municipal Airport Akron, OH 44318
310 Series; T.C. 3A10	SA457SW	AK145 automatic pitch trim.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA477SO	Modify control wheel. Issued 10/27/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602 IAB Miami, FL 33148
310 Series; T.C. 3A10	SA517WE	Flight control system B-4, including pitch assist PC-1, altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, INc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA621SW	AK198 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310 Series; T.C. 3A10	SA678SW	Lear or Motorola L-2C autopilot.	SW	03120	Aerotron Radio Company International Airport Tulsa, OK 74101
310 Series; T.C. 3A10	SA737SW	AK201 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310; T.C. 3A10	SA1359CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
310 Series; T.C. 3A10	SA1490WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1799WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA1896WE	Installation of Brittain Industries NAV-2B flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; T.C. 3A10	SA2406SW	Addition of hydro seal fluid additive to nose and main gear shock strut. Issued 2/11/77.	SW	49722	Granville Lasseter 802 East Grant Street Morton, TX 79346
310, 310A thru 310J, 320, 320A, B, C, D; T.C. 3A10, 3A25	SA1-620	Kit No. 2014X for 12-inch RCA AVQ-45, AVQ-47, AVQ-50, AVQ-55 and 12-inch Collins WP-103 radar antenna. Amended 4/15/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310B, 310C; T.C. 3A10	SA1-185	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310 thru 310Q, T310P, Q, E310H, J, T310R, 320 thru 320F, 340, 340A, 336, 337, 337B, C, D, E, F, G, H, T337B, C, D, E, F, G, P337H, T337H, 401, 401A, B, 402, 402A, B, C, 404, 411, 411A, 414, 414A, 421, 421A, B, C; T.C. 3A10, 3A25, A7CE, A6CE, A2CE	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 4/30/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
310, 310A thru 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P,, T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA111GL	Install Cleveland conversion kit P/N 199-64. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
310-A thru 310-K, 320A thru 320-D, 320-1; T.C. 3A10, 3A25	SA302CE	Supplemental high intensity position light system. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
310, 310A thru H, E310H, 310J, J-1, E310J, 310K, L, N, 320, 320-1, 320-A, B, C, D, E, F, 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA362CE	Install Hoskins Twilighter Mk III and Mk IIIB light system. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
310, 310A thru J, 320, 320A thru D; T.C. 3A10	SA396EA	Installation of Radome Kit No. 2310X-R. Reissued 4/15/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
310, 310A, 310C; T.C. 3A10	SA814SW	Underwing exhaust.	SW	08168	Airlane Aviation, Inc. P.O. Box 1024 Roswell, NM 88204
310, 310A thru 310F; T.C. 3A10	SA574WE	Installation of leading gear position mirror on left wing tip tank. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
310, 310A thru 310R, T310P, Q, R, 320, 320A thru F, 335, 340, A, 401, 401A, B, 402, 402A, B, C, 414, 414A; T.C. 3A10, 3A25, A7CE	SA1007NW	Installation of a low thrust detector system. Issued 8/19/80.	NW	01425	Advanced Aero Safety P.O. Box 2683 Renton, WA 98055
310, 310A, B, C, D, E, F, G, H, I, J, K, L, N, P, Q, E310H, 310J-1, E310J, T310P, T310Q; T.C. 3A10	SA3235WE	Installation of recognition light assemtly on horizontal stabilizer. Issued 7/13/76.	WE	30000	DeVore Aviation Corporation 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
310, 310A, B, C, D, E, F, G, H, I, J, K, L, N, P, Q, R, T310P, T310Q, T310R; T.C. 3A10	SA4136WE	Installation of inflatable door seal. Issued 4/10/80.	WE	36320	Bob Fields Aerocessories 340 "E" East Santa Maria St. San Paula, CA 93060
310, 310B; T.C. 3A10	SA26SO	Aerodynamic clean-up, cabin soundproofing, new interior and cooling duct changes. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310P, 310Q; T.C. 3A10	SA74SO	Installation of seats and camera port. Reissued 9/10/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D; T.C. 3A10	SA76SO	Installation of two (2) R.H. and two (2) L.H. single seats and enlarged emergency exit. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B thru 310G; T.C. 3A10	SA2128O	Installation of Lycoming IO-540-A1A5 engines and Hartzell HCA3XK-2B/7636D propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 310B, 310C, 310D, 310F; T.C. 3A10	SA455SO	Installation of extended window modification. Issued 3/18/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310, 310F thru N; 320, 320-1, 320A thru F; 401, 401A, 402, 411, 411A, 421, 421A; T.C. 3A10, 3A25, A7CE	SA240WE	Consolidation of STCs SA355CE and SA362CE into one STC having MASTER ELIGIBILITY LIST - amended to include improved power supply assembly and subchassis timer assembly for Twilighter MK III high intensity supplementary lighting system. Issued 8/16/71.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
310B, C, D, E, F, G, H, I, J, K, L, N, P, Q, T210P, T210Q; T.C. 3A10	SA3243WE	Installation of pilot's and co-pilot's side vent windows. Issued 8/13/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
310B, C, D, E, F, G, H, I, J, K; T.C. 3A10	SA391GL	Installation of Great Lakes Aero Products windshield P/Ns W-2070, W/T-2070 or W/G-2070. Amended 9/15/80.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
310C thru 310G; T.C. 3A10	SA2383WE	Installation of turbo-charged Continental IO-470-D engine. Issued 8/18/71.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
310C, D, F, G, H, I, J, K, L, N, P, Q, T310P, T310Q, T310R; T.C. 3A10	SA3671WE	Installation of Fueltron IIIG or IIIP digital fuel flow indicating system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
310D thru 310L, 310N, 310P, 320, 320A thru 320F; T.C. 3A10, 3A25	SA2534WE	Installation of Cessna 310P-type fiberglass tail stinger and yaw reduction adapter. Amended 5/30/73.	WE	01750	Aerocessories Company 1779 Fitzgerald Road Simi, CA 93065
310D, G, H, I, J, K, L; T.C. 3A10	SA3078SW-D	Auto flight system AK556, Century IV autopilot or AK556FD Century IV flight director. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J; T.C. 3A10	SA3079SW-D	Mitchell yaw damper system YK 558. Issued 10/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, G, H, I, J; T.C. 3A10	SA3082SW-D	Automatic flight system AK557, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 11/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310D, E, F, G, H, I, J, K, L, N, P, Q, R, T310P, T310Q, T310R, 320-1, 320C, D, E, F; T.C. 3A10, 3A25	SA3105SW-D	Mitchell automatic flight system AF584 consisting of Century IIB autopilot with optional radio coupler. Issued 2/4/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310F, 310G; T.C. 3A10	SA752EA	Installation of ground to air recovery equipment. Restricted Category. Amended 8/6/69.	EA	09500	All American Eng. Company Box 1247 Lancaster Pike & Center Road Wilmington, DE 19899
310G, H, I, J, K, L, N, P; T.C. 3A10	SA412SO	Installation of Continental IO-520-E engines. The engines are limited to 260 hp. Amended 12/16/71.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
310G, H thru Q, J-1; E310H, J; T310P, Q; 320A, B thru F; 402, A, B, 401, A, B; 411, A; 414; 421, A, B; T.C. 3A10, 3A25, A7CE	SA568EA	Installation of Grimes Manufacturing Company three light strobe kit P/N 34-0107-1. Amended 11/7/75.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
310G thru 310Q, 310R, 320A thru 320F, 340A, 401, 401A, B, 402, 402A, B, 411A, 414, 421, 421A, B; T.C. 3A10, 3A25, A7CE	SA574NW	Installation of forward facing recognition lights and clear plastic wing tip tank nose cone. Amended 4/13/78.	NW	28850	Robert M. DeBorde 20645 S.W. Clarion Aloha, OR 97005
310G, H, I, J, K, L, N, P, 310Q thru 310Q-0601; T.C. 3A10	SA3789WE	Installation of 36-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
310H; T.C. 3A10	SA294SO	Installation of turbocharged Continental IO-470-D engines. Reissued 12/5/74.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90801

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310H thru 310L, 320 thru 320E, 401, 402; T.C. 3A10, 3A25, A7CE	SA1847WE	Installation of Brittain Up-Command Signal Adapter Kit. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310I, 310J; T.C. 3A10	SA181SO	Installation of turbosupercharged Continental IO-470-U engines. Amended 8/9/68.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
310I, J, K, L, N, P, Q, R, T310P, T310Q, T310R, 320A, B, C, D, E, F, 340, 401, 401A, B, 402, 402A, B, 414, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA107GL	Conversion of oil lubricated deice pumps and related hardware to Airborne dry air pump 400 series conversion kits. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
310I, J, K, L, N, P, R, Q, T310P, T310Q, T310R; T.C. 3A10	SA701CE	Install Airborne wing and tail pneumatic deice kit 703B. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
310I, L, N, P, Q, T310P, 320C, 320E; T.C. 3A10, 3A25	SA1883SW	Install Hartzell synchrophase system. Issued 6/11/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708
310I, J, K, L, M, P, Q; 320B, C, D, E, F; T.C. 3A10, 3A25	SA1904SW	Additional auxiliary transfer tanks. Issued 8/13/74.	SW	68150	Riley Jetstream Corporation P.O. Box 5247 Waco, TX 76708
310J, E310J, T310P, T310Q, 310K, 310L, 310N; 320D, 320E, 320F, 340; 401, 401A, 401B, 402, 402A, 402B, 414, 411, 411A, 421, 421A, 421B; T.C. 3A10, 3A25, A7CE	SA14GL	Installation of detachable lead strap propeller deicers. Issued 3/20/73.	GL	44318	B.F. Goodrich Aerospace and Defense Products 500 S. Main Street Akron, OH 44318
310J, K, L, N, P, Q, R, T310P, T310Q, T310R; T.C. 3A10	SA471SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and optional flight director indicator. Amended 6/3/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
310K, 310L, 310N, 310P, 310Q, 320E, 320F; T.C. 3A10, 3A25	SA42GL	Install Norton Company radome kit No. 3060X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310K, 310L, 310N, 320E, 320F, 310P, 310Q; T.C. 3A10, 3A25	SA490EA	Installation of Chamberlain Radome Kit No. 3060K-B for Bendix radar RDR-100 or RDR-110 systems. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310K, L, N, P, Q, 320E, 320F; T.C. 3A10, 3A25	SA150GL	Install Norton Company radome Kit No. 4131X. Amended 3/28/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
310K, L, N, P, Q, 320F; T.C. 3A10, 3A25	SA537EA	Installation of Radome Kit No. 3060X-R. Amended 8/25/72.	GL	61750	Norton Company Plastics & SYnthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
310L, N, P, Q: T.C. 3A10	SA2082WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Hartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68145	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
310N; T.C. 3A10	SA2784WE	Installation of Ontrac II VLF 1000 very low frequency navigation system. Amended 12/3/73.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3266WE	Installation of ONTRAC III VLF/Omega navigation system. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway AVenue Costa Mesa, CA 92626
310N; T.C. 3A10	SA3287WE	Installation of Ontrac III VLF/Omega navigation system as a means of navigation (but not sole means) for EN ROUTE navigation. Amended 3/3/77.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310N; T.C. 3A10	SA3924WE	Installation of ONTRAC IIIA VLF/Omega navigation system. Issued 5/25/79.	WE	25600	Communications Components Corp. 3000 Airway Avenue Costa Mesa, CA 92626
310N, P, Q, T310Q; T.C. 3A10	SA3018SW-D	Automatic flight system AK442 consisting of Century III autopilot with optional command and auto. elec. elevator pitch trim, radio, and glide slope coupler. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, Q, T310P, Q; T.C. 3A10	SA3019SW-D	Automatic flight system AK443 and AK443FD consisting of Century IV autopilot and Century IV flight director autopilot with trim system and annuciator panel. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310N, P, T310P, T310Q; T.C. 3A10	SA3020SW-D	Automatic flight system YK444 consisting of yaw damper. Issued 8/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P, 310Q; T.C. 3A10	SA592NW	Installation of Fowler flaps. Issued 4/14/78.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
310P, 310Q, T310P, T310Q; T.C. 3A10	SA137NW	Installation of Collins AP-107 low profile automatic flight control system (FCS), including yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA138NW	Installation of Collins low profile yaw damper system. Amended 12/12/74.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
310P, 310Q, T310P, T310Q; T.C. 3A10	SA875EA	Installation of Brittain Industries, Inc. flight control system Model B-7 or NAV-2B or B2C. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310P, T310P, 310Q; T.C. 3A10	SA1142SW	Edo-Aire Mitchell automatic flight system, AK300 consisting of Century III with pitch trim, radio, and glide slope coupler. Issued 5/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P, Q, N, T310P, T310Q; T.C. 3A10	SA1190SW	Mitchell automatic flight FD/AP282-300 consisting of flight director/automatic pilot and automatic pitch trim. Issued 9/24/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310P/T310P, 310Q/T310Q, 310R/T310R; T.C. 3A10	SA1273CE	Installation of King KFC 200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 4/14/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
310 P/T 310P, 310Q/ T310Q, 310R/T310R; T.C. 3A10	SA1555CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
310P, 310Q, 310R; T.C. 3A10	SA2203WE	Installation of air conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
310P, T310P, 310Q, T310Q, 310R, T310R; T.C. 3A10	SA3602WE	Installation of vapor cycle airconditioning system. Issued 3/6/78.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
T-310; T.C. 3A10	SA192RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
T310, 320, 320A, B, C, D, E, F, 340, 401, A, 411, A, 414, 421, A, B; T.C. 3A10, 3A25	SA3RM	Modification of engine exhaust stacks by replacement of expansion joint with slip fit joint. Reissued.	RM	41750	Heliarc Welding Service, Inc. 3916 Niagara Street, Box 7301 Denver, CO 80207
T310 Series, 320A, B, C, D, E, F, 401, 401A, 402, 402A, B, 404, 414, 421C; T.C. 3A10, 3A25, A7CE	SA103RM	Installation of exhaust turbo connector, P/N 30477-3 Issued 8/17/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
T310 Series, 320, 320A, B, C, D, E, F, 340, 340A; T.C. 3A10, 3A25	SA110RM	Modify Cessna exhaust system by replacement of the inter-cylinder expansion joints with a slip fit joint.	RM	41750	Heliare Welding Service, Inc. 3965 Newport Denver, CO 80207
T310L;	SA530NW	Installation of McCauley D3A34C402/90DFA-10 propeller on Continental TSIO-520-H engine. Issued 10/4/77.	NW	67090	Keith L. Remington 253 S.W. 4th Avenue Ontario, OR 97914
T310P; T.C. 3A10	SA1018SW	Bendix M4-C autopilot.	SO	15475	Bendix Avionics P.O. Box 9414 Fort Lauderdale, FL 33310
T310P; T.C. 3A10	SA2292WE	Modification of waste gate controls. Issued 1/20/71.	WE	25400	Comp Air, Inc. 1285 Rollins Road Burlingame, CA 94010
T310P, T310Q, 320, 320-1, 320A thru 320F, 340, 411, 411A, 401, 401A, B, 402, 402A, B, 421, 421A, 414; T.C. 3A10, 3A25, A7CE	SA128GL	Replace existing asbestos or bellows exhaust seal with slip joint. Reissued 12/15/78.	GL	84915	Frank Webner 725 N. Hamilton Road Columbus, OH 43219
T310P, Q, 320D, E, F; T.C. 3A10, 3A25	SA2750SW	Install Continental TSIO-520-E engine. Issued 4/10/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
T310P, T310Q, T310R, 320D, 320F; T.C. 3A10, 3A25	SA2862SW	CFS-2000 electronic fuel flow metering system. Issued 10/18/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
T310P, T310Q, T310R, 320D, E, F; T.C. 3A25	SA4011SW	Installation of TSIO-520-N, or TSIO-520-NB engine. Issued 7/9/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
310Q; T.C. 3A10	SA723CE	Incorporate openable windows and drop hole.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
310Q, T310Q; 310R, T310R; T.C. 3A10	SA775CE	Installation of janitrol Aero Division vapor cycle air conditioning system. Amended 12/9/74.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
T310Q; T.C. 3A10	SA2242SW	Continental TSIO-520-J engines. Issued 9/15/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
310R; T.C. 3A10	SA103GL	Install Norton Company radome Part No. 4096X. Amended 6/22/76.	GL	61750	Norton Company P.O. Box 350 Akron, OH 44309
310R; T.C. 3A10	SA1081CE-D	Installation of Collins Radio Group AP-106, 3-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1082CE-D	Installation of Collins Radio Group AP-107, 3-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1083CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R; T.C. 3A10	SA1084CE-D	Installation of Collins Radio yaw damper system. Amended 6/27/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
310R/T310R; T.C. 3A10	SA1301CE	Installation of Enk Aviation fire suppression system. Amended 11/28/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
310R, T310R, 335, 340, 340A; T.C. 3A10, 3A25	SA4222SW	Mount collision avoidance lights in engine nacelle. Issued 10/29/80.	SW	46760	Johnson Aviation Products P.O. Box 6031 Tyler, TX 75711
310, 320; T.C. 3A10, 3A25	SA99SW	Automatic pilot AK113 and lateral guidance radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320; T.C. 3A10, 3A25	SA234EA	Installation of Chamberlain 2310K-B series radome kit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
310, 320; T.C. 3A10, 3A25	SA237SO	Control wheel modification. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
310, 320 Series; T.C. 3A10, 3A25	SA272EA	Installation of Chamberlain 2014K-B radome kit as follows: Kit No. 2014K-B for Bendix RDR-100 or RDR-110 radar systems with 12" antenna and transmitter receiver unit. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Company P.O. Box 1187 Akron, OH 44309
310, 320 Series; T.C. 3A10, 3A25	SA338SW	Automatic pilot AK125.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA409SW	Automatic pitch trim AK137.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA446CE	30-gallon auxiliary fuel tank in baggage compartment.	CE	36000	FloAir, Inc. Municipal Airport Newton, KS 67114
310, 320 Series; T.C. 3A10, 3A25	SA455WE	Single-piece windshield.	WE	20630	Cessna Components, Inc. P.O. Box 521 Long Beach, CA 90801
310, 320 Series; T.C. 3A10, 3A25	SA471EA	SAGA (Semi-automatic gear actuating) system.	GL	44010	In-Flight Services Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
310, 320 Series; T.C. 3A10, 3A25	SA521SW	Automatic pilot AK157 and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA667SW	AK222 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
310, 320 Series; T.C. 3A10, 3A25	SA722WE	30-gallon wing leading edge fuel tanks. Amended 9/2/65.	WE	20630	Cessna Components, Inc. 3200 Airport Avenue Santa Monica, CA 90406
310, 320 Series; T.C. 3A10, 3A25	SA1175WE	One-piece windshield.	WE	14238	Cee Bailey's Aircraft Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90801
310, 320 Series; T.C. 3A10, 3A25	SA1452WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1604WE	Installation of Brittain B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310, 320 Series; T.C. 3A10, 3A25	SA1880WE	Installation of Brittain Industries B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
310 Series; 320 Series; 336 Series; 337 Series; 401, 402, 411, 421 Series; T.C. 3A10, 3A25, A2CE, A6CE, A7CE	SA1675WE	Installation of exhaust gas temperature monitoring systems Model EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
320 Series; T.C. 3A25	SA3-737	M-4 flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA101SO	One right-hand and two left-hand single seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320 Series; T.C. 3A25	SA104EA	L-2C autopilot slave cables around existing approved camera opening in lower surface of fuselage.	EA	20630	Aero Service Corporation North Philadelphia Airport Philadelphia, PA
320 Series; T.C. 3A25	SA117CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
320 Series; T.C. 3A25	SA119SO	Passenger seats. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320 Series; T.C. 3A25	SA127SW	Auxiliary baggage compartment and adjustable seat modification.	SW	37154	Gen-Aero, Inc. P.O. Box 6767 San Antonio, TX 78205
320 Series; T.C. 3A25	SA130CE	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
320 Series; T.C. 3A25	SA306CE	GUARD System (gear up automatic response device). Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
320 Series; T.C. 3A25	SA492SW	Emergency alternate air door actuation.	SW	33270	El Paso Natural Gas Company P.O. Box 1492 El Paso, TX 79910
320 Series; T.C. 3A25	SA632WE	B-4 flight control system including pitch assist PC-1, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
320 Series; T.C. 3A25	SA744SW	M4B/C autopilot.	SO	15475	The Bendix Corporation Avionics Group P.O. Box 9414 Fort Lauderdale, FL 33310
320, 320-1; T.C. 3A25	SA285SO	Installation of Lycoming IO-540-A1A5 powerplants and Hartzell HCA3XR-2B/7636D propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
320, 320-1, 320A, 320B, 320C; T.C. 3A25	SA518SO	Installation of Continental IO-520-E derated engines and McCauley D3AF32C87/82NC-6 or -8 propellers. Issued 8/28/72.	SO	23700	Colemill Enterprises, Inc. P.O. Box 60627 Nashville, TN 37206
320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F (320 series S/N's 0001-D9999; 320E0001-F9999); T.C. 3A25	SA110GL	Install Cleveland conversion kit P/N 199-64. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
320, 320A, 320B, 320C, 320D, 320E, 320F S/N's 0001 and on; T.C. 3A25	SA808CE	Install Airborne wing and tail pneumatic deice kit 703C. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
320, 320-1, 320A, B, C, D, E, F, 340; T.C. 3A25	SA3231WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
320, 320A; T.C. 3A25	SA3239WE	Installation of nacelle baggage lockers. Issued 7/27/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, B, C, D, E, F; T.C. 3A25	SA3242WE	Installation of pilot's and co-pilot's side vent windows. Issued 7/30/76.	WE	01750	Aerocessories Company 1905 West 5th Street Oxnard, CA 93030
320, 320A, 320B, 320C, 320D, 320E, 320F; T.C. 3A25	SA3822WE	Installation of 34-gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419
320, 320A thru 320F, 320-1, 340; T310P, T310Q; 401, 401A, B, 402, 402A, B; 411, 411A, 414, 421, 421A; T.C. 3A25, 3A10, A7CE, A7CE	SA1642WE	Modification of exhaust system components. Amended 12/7/73.	SW	87348	Wooley Tool & Manufacturing Div. Chromalloy American Corporation P.O. Box 3508 Odessa, TX 79760
320A, B, C, D, E, F, 340, 340A; T.C. 3A25	SA193RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welidng Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
320A, B, C, D, E, F, 320-1; T.C. 3A25	SA3164SW-D	Install automatic flight system AF584 consisting of Century IIB automatic pilot with optional radio coupler. Issued 11/11/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport , Mineral Wells, TX 76067
320A thru 320D; T.C. 3A25	SA2339WE	Installation of exhaust bellows. Issued 4/12/71.	WE	01735	Aero Bellows Manufacturing Company 3211B Winona Avenue Burbank, CA 91504

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
320E, 320F; T.C. 3A25	SA4GL	Installation of Bendix FCS-810 autopilot flight director system. Issued 10/18/72.	GL	47767	Ralph Kerns Kerns Aircraft Electronics, Inc. Weir Cook Municipal Airport Indianapolis, IN 46206
320E, 320V; T.C. 3A25	SA2122WE	Installation of two Lycoming TIO-540-A2B turbocharged engines and two Hartzell HC-E3YR-2/C8468-6R propellers. Reissued 3/28/74.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
320F; T.C. 3A25	SA4012SW	Dual camera port. Issued 7/6/79.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
335, 340, 340A; T.C. 3A25	SA914EA	Installation of Radome kit P/N 4057KX. Amended 7/10/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
335, 340A; T.C. 3A25	SA1302CE	Install Enk Aviation fire suppression system. Amended 10/9/79.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
336; T.C. A2CE	SA203SW	Right front seat replaced with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72003
336; T.C. A2CE	SA286NW	Request for multiple STC on Model 336. Issued 4/23/76.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
336; T.C. A2CE	SA445SW	Automatic pilot AK140, pitch trim system AK141, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
336; T.C. A2CE	SA936CE	STOI Kit installation. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
336; T.C. A2CE	SA1260CE	Install FiQuench extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
336; T.C. A2CE	SA1355CE	Chrome-plated brake disc installation. Issued 8/19/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
336; T.C. A2CE	SA1875SW	Wing edge leading cuffs, wing tips, vortex generators on fuselage and fairing on vertical tails. Reissued 9/15/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
336, 337; T.C. A6CE, A2CE	SA1056SW	Revise wing contours leading edge and redesign landing light deflector plates. Reissued 4/22/80.	CE	85735	B.A. Whitsitt 1707 North Mount Carmel Wichita, KS 67203
336, 337, 337A thru C; T.C. A6CE, A2CE	SA406CE	Hoskins Supp. Position Light System includes Model A wing tip lights, Model 2 fuselage light used as tail light or Model L tail light. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
337; T.C. A6CE	SA491SW	Automatic pilot AK135, automatic pitch trim AK156, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA668SW	AK210 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337; T.C. A6CE	SA1473CE	Installation of Tull microwave landing system with modified King KX175B and KN 73 receivers. Issued 2/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MC 64127
337; T.C. A6CE	SA2200WE	Installation of Brittain Industries B2C and BSS flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
337, 337A, B, C, D, E, F, G, H, T337B, C, D, E, F, G, H, P337H; T.C. A6CE	SA385GL	Installation of Norton radome kit No. 4231X. Issued 2/1/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
337, 337A, B, C, D, E, F, G, M337B, T337B, C, D, E, F, G; T.C. A6CE	SA937CE	Installation of STOL kit (leading edge cuffs, stall fence, droop wing tips, and vortex generators on rear engine lower cowling). Amended 5/25/78.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
337, 337A, B, C, D, E, F, G, M337B, N337B, T337B, C, D, E, F, G; T.C. A6CE	SA1258CE	Installation of FIQUENCH fire extinguishing system in cabin and/or fire extinghishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
337, 337A, 337B, T337B, 337C, 337D, 337E, 337F, 337G; T.C. A6CE	SA1558SW	Vortex generators on fuselage, wing leading edge cuffs, wing tips, and fairings on vertical tail. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
337, 337A (USAF 02B), 337B, M337B (USAF 02A), 337C, T337B, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G; T.C. A6CE	SA1627WE	Installation of drooped ailerons in flaps down mode, recontoured wing leading edge, stall fences, aileron centering springs, conical cambered wing tips and flap actuated elevator trim spring. Also takeoff gross weight increase for all models except for T337G and 337G. Reissued 11/5/73.	NW	68500	Robertson Aircraft Corporation 839 W. Perimeter Road Renton, WA 98055
337, 337A; T.C. A6CE	SA2335WE	Installation of one-piece windshield and relocation of compass. Reissued 5/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. Route 1, Box 127D Leesburg, FL 32748
337, 337A, B, C, D, E, F, G, M337B, T337B, T337C, T337D, T337E, T337F, T337G; T.C. A6CE	SA3056WE	Installation of fuel flow instruments. Issued 8/15/75.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
337, 337A, 337B, T377B, 337C, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G, T337P; T.C. A6CE	SA3818WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Amended 1/31/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
337, T337, 337E, T337E; T.C. A6CE	SA1356CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
337A; T.C. A6CE	SA190SO	Cabin door removed and wind deflector installed.	SO	90106	Young, Isherwood & Marsh P.O. Box 982 Christiansted St. Croix, Virgin Islands
337A; T.C. A6CE	SA801SW	Mitchell AK244 Century II autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A thru 337H, T337B thru H, P337; T.C. A6CE	SA32RM	Installation of electrically driven freon air-conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA1922SW	Automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 10/11/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337A, B, T337B, 337C, T337C, 337D; T.C. A6CE	SA3250SW-D	Mitchell automatic flight system AK404 consisting of Century IIB autopilot with optional radio coupler. Issued 11/2/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337B; T.C. A6CE	SA842SW	AK252 consisting of Century III autopilot with optional pitch trim stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337D; T.C. A6CE	SA672CE	Install auxiliary fuel tank in baggage area.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
337D; T.C. A6CE	SA678CE	Install fuselage top emergency exit door.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
337D; T.C. A6CE	SA1038EA	Installation of recognition lights (LOGO) on trailing edge of Robertson wing tips. Issued 8/9/76.	EA	29998	DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
337D, T337D, 337G, T337G; T.C. A6CE	SA478NW	Installation of Bendix weather radar system. Amended 4/13/78.	NW	67135	Renton Aviation, Inc. 840 Perimeter Road Renton, WA 98055
337D, 337E, 337F, 337G, T337D, T337E, T337F; T337G; T.C. A6CE	SA482SO	Installation of Bendix FCS-810 automatic flight control system including manual electric trim and flight direcotr indicator. Amended 7/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
337E, F; T.C. A6CE	SA1359SW	Mitchell automatic flight system FD/AP282-345 consisting of flight director/autopilot with optional pitch trim. Issued 5/19/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F; T.C. A6CE	SA1478SW	Mitchell automatic flight system AK345 consisting of Century III autopilot with optional automatic pitch trim radio coupler, and glide slope coupler. Issued 6/9/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067
337E, F,; T.C. A6CE	SA1520SW	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 10/27/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3148SW-D	Mitchell automatic flight system AK537 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3149SW-D	Mitchell automatic flight system AK536 consisting of Century IV autopilot or Model AK536FD flight director autopilot with optional remote annuciator. Issued 7/2/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337E, F, G; T.C. A6CE	SA3252SW-D	Mitchell automatic flight system AK400 consisting of Century IIB autopilot with optional radio coupler. Issued 11/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
337G; T.C. A6CE	SA1205CF	Installation of King KFC-200 2-axis (3 optional) flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/6/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
F337E, FT337E, F337F, FT337F, F337G, FT337GP; T.C. A23EU	SA1259CE	Install FiQuench fire extinguishing system in cabin and/or fire extinguishant system in engine compartments. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
340 Series; T.C. 3A25	SA186NW	Installation of Continental TSIO-520-J engine. Issued 5/30/75.	NW	85165	Western Skyways Portland/Troutdale Airport Troutdale, OR 97060
340 Series; T.C. 3A25	SA474NW	Replace original split flaps with Fowler flaps.	NW	68500	Robertston Aircraft Corporation 939 West Perimeter Road Renton, WA 98055
340; T.C. 3A25	SA1357CE	Chrome-plated brake disc installation. Issued 1/13/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
340 Series; T.C. 3A25	SA1441SW	Mitchell automatic flight system AK367 consisting of Century III autopilot with optional automatic pitch trim, radio, and glide slope couplers. Issued 3/15/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340 Series; T.C. 3A25	SA1442SW	Mitchell automatic flight system FD/AP282-367 consisting of flight director/autopilot with automatic electric trim. Issued 3/3/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA1881SW	Continental TSIO-520-J engine. Issued 5/23/75.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
340 Series; T.C. 3A25	SA1979SW	In-Line fuel pumps for auxiliary tanks. Issued 5/8/75.	SW	68146	Jack N. Riley, Jr. 4307 Shady Glen Waco, TX 76708
340 Series; T.C. 3A25	SA2346SW	Teledyne Continental TSIO-520-N engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340; T.C. 3A25	SA2770SW	Cleveland heavy duty brakes. Issued 5/9/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
340 Series; T.C. 3A25	SA3043SW-D	Mitchell automatic flight system AK525 or AK525 FD consisting of Century IV autopilot with command/ automatic electric pitch trim system and optional remote annuciator panel. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340 Series; T.C. 3A25	SA3044SW-D	Mitchell automatic flight system YK525 consisting of yaw damper system. Issued 2/8/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
340; T.C. 3A25	SA3485WE	Installation of Continental TSIO-520-N engines and increase takeoff power to 310 h.p. Amended 11/18/77.	WE	68120	Riley Aircraft Corporation 2383 Palomar Airport Road Carlsbad, CA 92008
340, 340A; T.C. 3A25	SA16RM	Installation of freon type air conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
340, 340A; T.C. 3A25	SA281GL	Install Cleveland conversion kit P/N 199-72. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
340, 340A; T.C. 3A25	SA502SO	Installation of Bendix FCS-810 automatic flight control system including manual eletric trim and optional flight director indicator DH-841. Amended 6/15/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340, 340A; T.C. 3A25	SA1062CE	Installation of Collins AP-107 autopilot. Amended 3/15/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
340, 340A; T.C. 3A25	SA2483SW	Increase seating capacity on aft baggage shelf for a total of 7 occupants. Reissued 3/20/78.	SW	66300	RAM Aircraft Modification P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
340, 340A; T.C. 3A25	SA2844SW	Installation of SDI Model CFS-2000, -2001, or FT-200 indicating fuel flow system. Amended 3/9/79.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
340, 340A; T.C. 3A25	SA3610WE	Installation of Silver Instruments Fueltron IIIG or IIIP fuel flow and totalizer system. Amended 4/24/80.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94515
340, 340A; T.C. 3A25	SA3871WE	Installation of vapor cycle air conditioning system. Issued 1/15/80.	WE	30860	Dynamic Air Engineering, Inc. 620 East Dyer Road Santa Ana, CA 92705
340, 340A (S/Ns 340A0001 thru 340A0600): T.C. 3A25	SA3923WE	Installation of Lycoming TIO-540-R2AD engines. Issued 6/1/79.	WE	68120	Riley Aircraft Corporation 2016 Palomar Airport Road Carlsbad, CA 92008
340-0001 and on: T.C. 3A25	SA55GL	Install Airborne wing and tail pneumatic deice kit 710. Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340A: T.C. 3A25	SA1015SO	Installation of Bendix FCS-870 automatic flight control system, including manual electric trim and optional flight director system. Issued 8/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
340A: T.C. 3A25	SA1025SO	Installation of a Bendix NP-2041A area navigation computer programmer. Issued 10/4/78.	SO	15475	Bendix AVionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
340A: T.C. 3A25	SA1276CE	Install King KFC 200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or KG-258 attitude horizon gyro and a KC-292 mode controller. Amended 5/8/78	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
304A: T.C. 3A25	SA1551CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Boulevard Olathe, KS 66061
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, 421B, 421C: T.C. A7CE	SA197GL	Install Cleveland conversion kit P/N 199-76. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
401, 401A, 401B, 402, 402A, 402B (normal category): T.C. A7CE	SA29NW	Installation of Fowler Flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 2/23/73.	NW	68500	Robertson Aircraft Corporation Renton Municipal Airport Renton, WA 98055
401, 401A, 402, 402A, 402B, 414: T.C. A7CE	SA109RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA117NW	Installation of Allison 250-B17 or 250-B17B engines and related changes. Reissued 1/6/77.	WE	25640	Commuter Investment and Development Corporation 2800 Clybourn Avenue Van Nuys, CA 91406
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414; T.C. A7CE	SA167GL	Install Cleveland conversion kit P/N 199-72. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
401, 401A, 402, 402A, B, 414; T.C. A7CE	SA194RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
401, 402, 411, 411A, 401A, 401B; T.C. A7CE	SA346EA	Installation of Chamberlain radome kit No. 2022K-B for Bendix RDR-100 or RDR-110 series radar system. Amended 7/30/71.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A; T.C. A7CE	SA437EA	Installation of radome P/N 2022X. Amended 5/27/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
401, 401A, 401B, 402, 411, 411A, 414, 421, 421A; T.C. A7CE	SA438EA	Installation of Norton radome kit No. 2022X-3. Amended 11/2/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
401, 401A, B, 402, 402A, B, C, 411, 411A; T.C. A7CE	SA448GL	Installation of a Shadin Co. 910502 or 910504 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
401A, 401B, 402A, B, 414, 421, 421A, 421B; T.C. A7CE	SA465SO	Installation of Bendix FCS-810 automatic flight control system including flight director indicator DH-841( ) and manual electric trim. Amended 6/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA618SO	Installation of M-4B or M-4C automatic flight control systems. Amended 4/27/73.	SO	15475	The Bendix Corporation Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
401, 401A, 401B, 402, 402A, 402B, 414; T.C. A7CE	SA646CE	Install wing and tail pneumatic deice kit 702A on 401/402 aircraft (S/N 0135 and above), kit 702B on 414 aircraft and kit 702C on 401/402 aircraft (S/N 0001 through 0134 only). Amended 8/26/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
401, 401A, 401B, 402, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C; T.C. A7CE	SA1146SO	Installation of nose cone erosion cap. Issued 5/29/80.	SO	02390	Aeronautical Accessories, Inc. P.O. Box 1177 Tri-City Airport Blountsville, TN 37617
401, 401A, B; T.C. A6CE	SA1158SW	Mitchell automatic flight system FD/AP282-302 consisting of flight director/automatic pilot and automatic pitch trim. Issued 6/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, 401B, 402, 402A; T.C. A7CE	SA1206SW	Edo-Aire Mitchell automatic flight system AK302, consisting of Century III autopilot with optional pitch trim, radio, and glide slope couplers. Issued 10/23/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, B, 402, 402A, B, 411, 411A, 414, 421, 421A, B, C; T.C. A7CE	SA1326CE	Installation of Avcon Industries TSO C39a stretcher. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
401, 401A, 402, 402A, 411, 411A, 414; T.C. A7CE	SA1358CE	Chrome-plated brake disc installation. Issued 1/16/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 414A, 421, 421A, 421B, 421C; T.C. A7CE	SA1393CE	Install forward baggage door warning system. Issued 1/3/78.	CE	84955	Wells Aircraft, Inc. Municipal Airport Hutchinson, KS 67501
401, 401A all S/N's, 402, 402A, 402B thru S/N 0300, 411, 411A all S/N's, 414 thru S/N 0350, 421, 421A, 421B thru 0300; T.C. A7CE	SA2091WE	Installation of air conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
401, 401A, B, 402, 402A, B; T.C. A7CE	SA2845SW	Symbolic Displays CFS-2000 electronic fuel flow metering system. Issued 9/8/78.	SW	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
401*, 401A*, 401B*, 402*, 402A*, 402B*, 402C, 411, 411A, 414*, 414A, 421, 421A, 421B, 421C; *Includes those models modified per STC SA117NW.	SA3003WE	Installation of recognition light assembly on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
401, 401A, 401B, 402, 402A, 402B, 411, 411A, 414, 421, 421A, 421B; T.C. A7CE	SA3017WE	Installation of fuel flow instruments.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
401, A, B, 402, 402A; T.C. A7CE	SA3057SW-D	Mitchell automatic flight system AK538 or AK435FD consisting of Century IV autopilot or Century IV flight director autopilot with command/autopilot electric pitch trim and annuciator. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, B, 402; T.C. A7CE	SA3058SW-D	Mitchell flight system YK535 consisting of yaw damper system. Issued 6/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE	SA3838WE	Installation of an air/oil separator. Issued 2/5/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
401, 401A, 401B, 402, 402A, 402B, 414 thru S/N 414-0350;	SA3930WE	Installation of 37.5 gallon auxiliary fuel tanks in each wing. Reissued 9/20/79.	EA	03550	Air America, Inc. Box 444, Seamans Airport Factoryville, PA 18419

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
401, 401A, 401B, 402, 402A, 402B; T.C. A7CE T.C. A7CE	SA4117WE	Installation of Silver Instruments fueltron 111G or fueltron 111P digital fuel flow and totalizer system. Issued 3/13/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
401, 402; T.C. A7CE	SA784SW	Mitchell Model AK240 Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
401, 402; T.C. A6CE	SA1472WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402; T.C. A6CE	SA1599WE	Installation of Brittain Model B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
401, 402, 411; T.C. A7CE	SA472EA	SAGA (Semi-automatic gear actuating) system. Amended 5/23/67.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
401A; T.C. A7CE	SA3192WE	Installation of single global and dual global GNS-500A navigation system. Amended 3/23/79.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
402; T.C. A7CE	SA634CE	Install tenth seat and attach FAA approved AFMS.	CE	36000	FloAir, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
402; T.C. A7CE	SA1742SW	Vapor cycle air conditioning system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
402; T.C. A7CE	SA1863SW	Two cameras and navigation sight. Issued 5/7/74.	SW	42825	A.D. Howard, Jr. 6817 N.W. 43rd Street Bethany, OK 73008
402; T.C. A7CE	SA2424WE	Installation of Allison 250-B17 engines and related changes. Amended 9/21/73.	WE	10208	American Jet Industries 3021 Airport Avenue Santa Monica, CA 90405
402, 402A; T.C. A7CE	SA2333SW	Fiberglass tailcone for magnetometer. Issued 7/23/76.	SW	42825	A.D. Howard, Jr. 1911 Moulton Court Oklahoma City, OK 73127
402A, B, C, 421B, C, 414A; T.C. A7CE	SA807EA	Installation of Norton Radome Kit No. 4009X. Reissued 5/6/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
402B; T.C. A7CE	SA700CE	Install right-hand side rear window.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
402B; T.C. A7CE	SA1061CE	Installation of Collins Company AP-107 (3 axis) autopilot system. Issued January 1975.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1110CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1111CE-D	Installation of AP-107 autopilot (2 axis). Amended June 1976.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
402B; T.C. A7CE	SA1501CE	Sierra utility flight inspection equipment rack installed in left hand side forward location. Issued 7/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
402B, 402C; T.C. A7CE	SA1303CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
402B (S/Ns 402B0301 and up), 414 (S/Ns 414-0351 and up), 414A, 421B, 402C, 421C (all S/Ns 6, 7, 8, 9 or 10 seat); T.C. A7CE	SA8RM	Installation of Freon type air-conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
402B, 414, 421B; T.C. A7CE	SA547SO	Installation of Bendix M-4D automatic flight control system including optional manual electric trim and optional flight director system in serial numbers 402B0301 and up, 4140351 and up, and 421B0301 and up. Issued 8/17/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
402B, 414, 421B; T.C. A7CE	SA58[illegible]	[illegible]ion of Bendix YD-4 yaw [illegible]stem. [illegible]sued 4/5/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
402C; T.C. A7CE	SA300CE	Installation of Woodward Governor propellers on single and twin engine airplanes for P/N B210659. Issued 5/22/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
402C; T.C. A7CE	SA927NW	Installation of a fowler flap system. Issued 4/21/80.	NW	68500	Robertson Aircraft Corp. 839 West Perimeter Road Renton, WA 98055
402C; T.C. A7CE	SA1502CE	Install King KFC200 automatic flight control system, with or without flight director. Amended 6/24/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
402C, 414A, 421C; T.C. A7CE	SA1526CE-D	Installation of King KAS 297 altitude selector option. Issued 2/6/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404, S/N 404-0001 and up; T.C. A25CE	SA143RM	Installation of air conditioner system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
404; T.C. A25CE	SA195GL	Installation of Norton radome kit 4009X.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
404; T.C. A25CE	SA195RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
404; T.C. A25CE	SA430GL	Installation of Collins LRN-70 Omega/VLF navigation system with computer program 11113322334.1. Issued 8/14/80.	GL	03465	Electrosonics Division of AiRadio Corporation 4885 Sawyer Road Columbus Int'l Airport Columbus, OH 43219
404; T.C. A25CE	SA721NW	Installation of camera bays. Reissued 7/15/80.	NW	00070	AAR Western Skyways Portland-Troutdale Airport Troutdale, OR 97060
404; T.C. A25CE	SA1297CE	Installation of King KFC 200 2-axis flight control system. Amended 5/27/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA1482CE	Installation of Tull microwave landing system. Issued 4/9/79.	CE	81650	Wilcox Electric, Inc. 1400 Chestnut Street Kansas City, MO 64127
404; T.C. A25CE	SA1304CE	Installation of Enk Aviation fire protection system. Amended 12/5/79.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64015
404; T.C. A25CE	SA1600CE	Installation of TSO'd stretcher. Issued 7/17/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
404; T.C. A25CE	SA1528CE-D	Installation of King KAS 297 altitude selector option. Issued 2/18/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
404; T.C. A25CE	SA3384WE	Removal of cargo doors and installation of P/N A770000 airstream deflector. Issued 6/8/77.	WE	07630	Airflite, Inc., South 2700 East Wardlow Road Long Beach, CA 90801
404; T.C. A25CE	SA3388WE	Installation of recognition lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
404; T.C. A25CE	SA4017WE	Installation of SDI model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 8/31/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
404; T.C. A25CE	SA4105WE	Installation of tail stinger and/or nose stinger. Issued 2/21/80.	WE	77500	Tallmantz Aviation, Inc. 19711 South Airport Way Santa Ana, CA 92707
404; T.C. A25CE	SA4163WE	Installation of doppler radar antenna. Issued 5/21/80.	WE	77500	Tallmantz Aviation, Inc. 19711 Airport Way South Santa Ana, CA 92707
411 Series; T.C. A7CE	SA402CE	50-gallon auxiliary fuel tank.	CE	36000	Floair, Inc. Municipal Airport Newton, KS 67114
411 Series; T.C. A7CE	SA515SW	Automatic pilot AK158, lateral guidance radio coupler AK123 and automatic trim system AK159.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA681SW	AK221 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
411 Series; T.C. A7CE	SA839EA	Installation of Radome Kit P/N 4009K-B for Bendix RDP-100 and RDR-110 systems - 12" antenna. Amended 11/29/72.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
411 Series; T.C. A7CE	SA1227WE	Installation of Brittain Model B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, NAV-1 navigation coupler.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
411 Series; T.C. A7CE	SA1467WE	Installation of Brittain Model B-4A flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
411 Series; T.C. A7CE	SA2378WE	Installation of Global Navigation Model GNS-200 VLF navigation system. Amended 2/26/74.	WE	38090	Global Navigation, Inc. 2733 Pacific Coast Highway Torrance, CA 90505
411 Series; T.C. A7CE	SA2913WE	Installation of GNS-500 VLF navigation system. Amended 2/28/75.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
411 Series; T.C. A7CE	SA3138WE	Installation of GNS-500A VLF/OMAGE navigation system. Amended 1/17/77.	WE	38090	Global Navigation, Inc. 24701 Crenshaw Boulevard Torrance, CA 90505
411, 411A Series; T.C. A7CE	SA1120WE	Bendix automatic flight control system type M4B and M4C.	SO	15475	The Bendix Corporation Avionics Products Fort Lauderdale, FL 33310
400, 411A, 421, 421A; T.C. A7CE	SA102RM	Installation of exhaust turbo connector, P/N 042177-5. Issued 5/19/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Street Denver, CO 80207
411, 411A, 421, 421A, 421B; T.C. A7CE	SA108RM	Modify exhaust stacks by replacing existing bellows or seal type joints with a clampless, sealess type slip joint. Issued 12/14/77.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
411, 421; T.C. A7CE	SA487CE	Install windshield wipers.	GL	27500	Marquette Metal Products Company Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
411A; T.C. A7CE	SA4167WE	Removal of main cabin door. Issued 5/29/80.	WE	18264	Richard Bungay/Richard Fowler 1345-D Silica Avenue Sacramento, CA 95815
414; T.C. A7CE	SA48NW	Installation of fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 6/29/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
414; T.C. A7CE	SA433SO	Installation of Bendix Model M4C flight control system. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
414; T.C. A7CE	SA1040CE	Installation of AP-107 autopilot. Amended 10/2/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
414; T.C. A7CE	SA1219SW	Mitchell automatic flight system AK308 consisting of Century III with automatic pitch trim, radio, and glide slope couplers. Issued 11/18/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA1899SW	Freon air conditioning system. Issued 9/9/74.	SW	37154	Gen-Aero, Inc. P.O. Box 16278 San Antonio, TX 78286
414; T.C. A7CE	SA1220SW	Mitchell automatic flight system Model FD/AP282-308 consisting of flight director/autopilot, autopilot pitch trim. Issued 11/20/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
414; T.C. A7CE	SA2354SW	Teledyne Continental TSIO-520-N, -J, engines. Reissued 3/20/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Madison Cooper Airport Waco, TX 76708
414; T.C. A7CE	SA2812SW	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
414; T.C. A7CE	SA3334SW-D	Mitchell automatic flight system AK624 consisting of Century IV autopilot or AK624FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/6/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3335SW-D	Mitchell yaw damper system, YK628. Issued 3/6/69.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3366SW-D	Mitchell yaw damper system YK867. Issued 5/28/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414; T.C. A7CE	SA3666WE	Installation of Silver Instruments Fueltron IIIG digital fuel flow and totalizer system. Issued 6/22/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
414; T.C. A7CE	SA3682WE	Installation of Continental TSIO-520-N engine and associated installation components. Issued 7/12/78.	WE	68120	Riley Aircraft Corporation 2306 Palomar Airport Road Carlsbad, CA 92008
414A; T.C. A7CE	SA892NW	Installation of a fowler flap system. Issued 2/12/80.	NW	68500	Robertson Aircraft Corp. 839 West Perimeter Road Renton, WA 98055
414A T.C. A7CE	SA985SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director and optional yaw damper. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
414A; T.C. A7CE	SA986SO	Installation of Bendix NP-2041A NP-2041A area navigation computer programmer. Issued 5/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
414A; T.C. A7CE	SA1400CE	Install Enk Aviation fire suppression system. Issued 2/9/78.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
414A; T.C. A7CE	SA1431CE	Install King KFC-200 flight control system with or without flight director. Amended 6/9/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
414A; T.C. A7CE	SA1521CE-D	Installation of King KFC 250 flight control system. Amended 7/25/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
414A; T.C. A7CE	SA3304SW-D	Mitchell automatic flight system AK774/FD consisting of Century IV/ flight director autopilot with optional remote annunciator.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
414, 421; T.C. A7CE	SA536CE	Install electrical connectors in pressure bulkhead(s) at Station(s) 100 and/or 273.94. Amended 12/4/70.	RM	05940	Charles O. Peacock Aircraft Radio & Accessory Co., Inc. Hangar #4, Stapleton Field Denver, CO 80207

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
414, 421A; T.C. A7CE	SA732EA	Installation of radome Part No. 4004X. Amended 5/12/75.	GL	61750	Norton Company Plastics & Synethetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
414, 421A; T.C. A7CE	SA780EA	Installation of Radome Kit No. 4004K-B for Bendix RDR-100 or RDR-110 series radar systems - 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
414, 421, 421A, B, C; T.C. A7CE	SA2440SW	Airstair door saver. Issued 3/23/77.	SW	00060	AAR of Oklahoma, Inc. P.O. Box 19508 Oklahoma City, OK 73119
421 Series; T.C. A7CE	SA574CE	Installation of toilet seat belt.	CE	36000	Floair, Inc. Hangar #17, Municipal Airport Wichita, KS 67209
421 Series; T.C. A7CE	SA591EA	Installation of Radome Part Part No. 3084X. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
421 Series; T.C. A7CE	SA661EA	Installation of Radome Kit No. 3084K for Bendix RDR-100 or RDR-110 series radar systems 12" antenna. Amended 3/11/70.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
421 Series; T.C. A7CE	SA662CE	Installation of Jet Electronics & Technology, Inc. Model FC120A autopilot.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street Grand Rapids, MI 49508
421 Series; T.C. A7CE	SA673CE	Install Hartzell HC-B3WF-2/9349-3 propellers.	GL	41000	Hartzell Propellers, Inc. 350 Washington Avenue P.O. Box 909 Piqua, OH
421 Series; T.C. A7CE	SA968SW	Mitchell automatic flight system AK279 consisting of Century II autopilot with optional automatic pitch trim, radio, and glide slope couplers, automatic aileron stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421 Series; T.C. A7CE	SA978SW	Collins FD108 flight director system.	SW	06000	Aircraftsmen, Inc. Box 82516 Oklahoma City, OK 73108
421 Series; T.C. A7CE	SA1776WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
421, 421A; T.C. A7CE	SA794CE	Install vapor cycle air conditioning system. Reissued 10/15/71.	GL	45175	Janitrol Aero Division Midland-Ross Corporation 4200 Surface Road Columbus, OH 43228
421, 421A; T.C. A7CE	SA1897WE	Installation of a seventh seat in aft baggage compartment.	RM	25250	Combs Aircraft, Inc. Stapleton International Airport Denver, CO 80207
421, 421A, 421B; T.C. A7CE	SA2RM	Installation of a seventh seat in aft baggage compartment. Reissued 4/6/73.	RM	25250	Combs - Gates Denver, Inc. Stapleton International Airport Denver, CO 80207
421, 421A, 421B; T.C. A7CE	SA18NW	Installation of Fowler flaps, flap actuated drooped ailerons, flap actuated elevator trim and anti-servo rudder trim tab. Issued 4/13/73.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055
421, 421A, 421B; T.C. A7CE	SA632SO	Installation of Bendix Model M-4C automatic flight control system, including manual electric trim. Amended 4/27/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33309
421, 421A, 421B; T.C. A7CE	SA1200CE	Installation of FiQuench cabin and/or engine fire extinguishant system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
421, 421A, 421B; T.C. A7CE	SA1210CE	Installation of Hanlon & Wilson exhaust systems, P/N 8108-59 and P/N 8109-59 or P/N 8108-159 and 8109-159. Amended 3/19/80.	EA	40350	Hanlon & Wilson Company P.O. Box 641 Jeanette, PA 15644

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
421, 421A, 421B, 421C; T.C. A7CE	SA1343CE	Install Sierra data console on left hand seat rails. Reissued 9/15/77.	EA	71660	Sierra Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, 421B, 421C; T.C. A7CE	SA1375CE	Reduce height of existing survival seat. Reissued 10/3/77.	EA	71660	Sierra Research Corporation 247 Cayuga Road Buffalo, NY 14225
421, 421A, B, C; T.C. A7CE	SA3228WE	Installation of Silver Instruments Fueltron IIIG or IIIP fuel indicating system. Amended 1/11/80.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545
421B; T.C. A7CE	SA135GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 10/26/76.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
421B; T.C. A7CE	SA952CE	Installation of King Radio Model KFC-300 automatic flight control system. Amended 12/19/75.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA986CE	Installation of Collins Radio Group AP-106 autopilot system. Amended January 1977.	CE	24250	Collins Radio Group Avionics Certification Center Cedar Rapids, IA 52406
421B; T.C. A7CE	SA987CE	Installation of Sperry SPZ-200/ STARS IVC automatic flight control system with optional Sperry AA-220/ RT-220 radar altimeter. Issued February 1974.	CE	90080	Yingling Aircraft, Inc. P.O. Box 1162 Wichita, KS 67201
421B; T.C. A7CE	SA1001CE	Installation of H-14 autopilot. Issued April 1974.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
421B; T.C. A7CE	SA1035CE	Installation of openable window aft of cabin door. Issued July 1974.	CE	36000	FloAir, Inc. Mid-Continent Airport Wichita, KS 67209
421B; T.C. A7CE	SA1167CE	Installation of AP 107 autopilot (2 axis). Serials 301 and subsequent. Issued 3/29/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1667SW	Mitchell automatic flight system Model YK385 consisting of yaw damper. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421B; T.C. A7CE	SA1168CE	Installation of Collins Radio Group AP-107, 3 axis, autopilot system and interface with Collins 329A-4V indicator. Serials 301 and subsequent. Issued 10/20/75.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
421B; T.C. A7CE	SA1668SW	Mitchell automatic flight system AK407, consisting of Century IV autopilot with trim; or AK407/FD consisting of Century IV autopilot/ flight director with trim. Issued 5/30/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421B; T.C. A7CE	SA2749WE	Installation of Lear AFC-70 AP/FD steering computer system. Issued 8/23/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Reno, NV 89510
421B; T.C. A7CE	SA2810WE	Installation of Collins AP-105 autopilot and FD-108 flight director systems. Issued 1/30/74.	WE	78622	Tower Avionics Center Hangar 8, Oakland Int'l Airport Oakland, CA 94614
421B; T.C. A7CE	SA3881WE	Installation of dual elevator trim tab actuator. Issued 3/14/79.	WE	68120	Riley Aircraft Corporation 2386 Palomar Airport Road Carlsbad, CA 92008
421C; T.C. A7CE	SA196RM	New slip joint exhaust manifold. Issued 12/20/79.	RM	41750	Heliarc Welidng Service, Inc. 3965 Newport Street P.O. Box 38509 AMF Denver, CO 80238
421C; T.C. A7CE	SA438NW	Replace original split flaps with Fowler flaps. Issued 4/22/77.	NW	68500	Robertson Aircraft Corporation 839 West Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
421C; T.C. A7CE	SA481GL	Installation of a Collins LRN-70 Omega Navigation System. Issued 12/16/80.	GL	03465	Electronics Division AiRadio Corporation 4885 Sawyer Road Columbus Inter'l Airport Columbus, OH 43219
421C; T.C. A7CE	SA886SO	Installation of Bendix M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued 2/26/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA890SO	Installation of Bendix FCS-810 automatic flight control system including manual electric pitch and optional flight director indicator. Amended 11/1/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
421C; T.C. A7CE	SA1120CE	Installation of Collins Radio Group AP-106 autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1121CE	Installation of Collins Radio Group AP-107 (2 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1122CE	Installation of Collins AP-107 (3 axis) autopilot system. Issued July 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
421C; T.C. A7CE	SA1191EA	Installation of Hanlon & Wilson exhaust system P/N 8294-1(L.H) and 8294-2(R.H.) Issued 4/2/80.	EA	40350	Hanlon & Wilson Company P.O. Box 641 Jeanette, PA 15644
421C; T.C. A7CE	SA1246CE	Install King KFC-200 2 axis (3 optional) flight control system with a KI-255 flight command indicator. Amended 6/2/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
421C; T.C. A7CE	SA1305CE	Installation of fire suppression system. Amended 6/24/80.	CE	33471	Enk Aviation Corporation 1409 Plaza Center Blue Springs, MO 64105
421C; T.C. A7CE	SA3110SW-D	Mitchell automatic flight system AK579, consisting of Century IV autopilot or AK579FD, consisting of Century IV flight director autopilot with remote annuciator. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3111SW-D	Mitchell yaw damper YK580. Issued 2/17/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
421C; T.C. A7CE	SA3458WE	Modification of fuselage to install camera window. Issued 7/14/77.	WE	84000	Volpar, Inc. 7929 Hayvenhurst Avenue Van Nuys, CA 91406
425; T.C. A7CE	SA1605CE	Installation of fire extinguisher system with only TFB12-0019-2 control panel assembly.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
441; T.C. A28CE	SA400GL	Installation of Litton LTN-211 Omega/VLF navigation system. Issued 6/12/80.	GL	37182	General Aviation, Inc. Capital City Airport Lansing, MI 48906
441; T.C. A28CE	SA868NW	Installation of two camera ports for aerial photography. Issued 11/28/79.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
441; T.C. A28CE	SA1424CE	Install Sierra Electronics consle. Reissued 7/3/78.	EA	71660	Sierra Research Corp. P.O. Box 222 Buffalo, NY 14225
441; T.C. A28CE	SA1599CE	Installation of TSO'd stretcher. Issued 7/17/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
441; T.C. A28CE	SA2018SW	Install three place side facing couch. Issued 7/19/78.	SW	04540	Air Center, Inc. P.O. Box 32160 Oklahoma City, OK 73132
441; T.C. A28CE	SA3498WE	Installation of tail flood light on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500 Series; T.C. A22CE	SA8GL	Installation of engine synchronizer kit P/N 213522. Issued 4/18/73.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
500 Series; T.C. A22CE	SA13RM	Installation of Branson cargo liner and retention system. Issued 7/23/73.	RM	09752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207
500 Series; T.C. A22CE	SA15RM	Installation of three-place couch with or without quick change aft divider. Amended 4/2/76.	RM	09752	Alpine Aircraft Charter, Inc. Stapleton International Airport Denver, CO 80207
500 Series; T.C. A22CE	SA18RM	Install beverage service buffet in baggage compartment. Issued 11/21/73.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA19RM	Install two lounge seats in rear of baggage compartment. Amended 11/8/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA23RM	Installation of aft beverage cabinet, P/N 90241-1. Amended 5/20/74.	CE	20625	Cessna Aircraft Company P.O. Box 1107 Wichita, KS 67201
500 Series; T.C. A22CE	SA47RM	Installation of single seat in the center of aft baggage compartment. Reissued 3/10/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
500 Series; T.C. A22CE	SA51RM	Installation of tail cone ski rack. Reissued 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series; T.C. A22CE	SA52RM	Installation of stretcher. Amended 2/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500 Series; T.C. A22CE	SA54RM	Installation of tail cone storage box and engine cover storage box. Amended 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CC 80033
500 Series; T.C. A22CE	SA58RM	Installation of deluxe three-place aft couch. Amended 10/7/77.	RM	17085	Branson Engineering Company, Inc. 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA79RM	Installation of side-looking camera hatch. Reissued 7/29/77.	CE	20625	Cessna Aircraft Company Wichita Municipal Airport P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA83RM	Increased ramp and takeoff weights for restricted category operation. Issued 10/22/76.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CC 80033
500 Series; T.C. A22CE	SA97RM	Installation of dual aft lounge seats. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	SA100RM	Installation of lounge seat toilet. Issued 3/21/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Avenue Wheat Ridge, CO 80033
500 Series; T.C. A22CE	ST131RM	Installation of Global Navigation, Inc. GNS-500A VLF/Omega navigation system. Issued 2/7/78.	RM	14127	Avionics Engineering of Denver, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
500; T.C. A22CE	ST174RM	Installation of extended width cabin door. Issued 5/4/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500; T.C. A22CE	SA402GL	Installation of a Sperry SPZ500 flight/director/autopilot system. Issued 4/18/80.	GL	47636	Kal-Aero, Inc. Kalamazoo Municipal Airport 5605 Portage Road Kalamazoo, MI 49002
500; T.C. A22CE	SA645NW	Increased fuel and performance modifications. Issued 8/4/78.	NW	12270	Astec Engineering, Inc. 830 N. Riverside Drive Renton, WA 98055
500; T.C. A22CE	SA802NW	Installation of transponder identification switch on left hand control wheel. Issued 7/13/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
500 Series; T.C. A22CE	SA897WE	Installation of Teledyne P/N BB638/T- Series lead-acid replacement battery. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500; T.C. A22CE	SA903NW	Installation of wing tip recognition lights on ASTEC "Eagle" modified Cessna 500. Issued 3/14/80.	NW	01535	Advanced Systems Technology, Inc. Snohomish County Airport Everett, WA 98204
500 (S/N 500-001 thru -0213); T.C. A22CE	SA991CE	Installation of KFC-300 automatic flight control system. Amended 4/10/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
500 Series; T.C. A22CE	SA1013CE	Installation of retractable aircraft recognition lights. Amended 7/26/78.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 Series; T.C. A22CE	SA1059EA	Installation of an airways calibration system. Reissued 9/27/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 (S/N 350 and on); T.C. A22CE	SA1371CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277
500 Series; T.C. A22CE	SA1574SW	Installation of hassock according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500; T.C. A22CE	SA1579CE	Installation of tail-cone baggage compartment. Issued 3/7/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
500 Series; T.C. A22CE	SA1589SW	Installation of Singer Kearfott SKY-1000A doppler system; Collins INS-61B inertial navigation system; JET PS 823B emergency power system. Reissued 11/20/73.	CE	20225	Cessna Aircraft Company P.O. Box 1977 Wichita, KS 67201
500 Series; T.C. A22CE	SA1597SW	Stretcher installation according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 N. Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1619SW	Installation of emergency power supply according to Qualitron Aero. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
500 Series; T.C. A22CE	SA1727SW	Jump seat. Issued 9/13/73.	SW	12250	Associated Radio Service Company Box 20718 Dallas, TX 75220
500 Series; T.C. A22CE	SA1945SW	Aft equipment bay storage unit. Issued 1/7/75.	SW	38242	William L. Goin, Jr. 7930 Airport Boulevard Houston, TX 77017
500 Series; T.C. A22CE	SA2383SW	Install refreshment bar and galley bulkhead. Issued 11/19/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
500 Series; T.C. A22CE	SA2925WE	Installation of power brake and skid control system. Issued 9/24/74.	WE	13230	Aviation Brake Systems, Ltd. 3535 West 5th Street Oxnard, CA 93030
500, 501; T.C. A22CE	SA2698SW	Freon air conditioning system. Issued 12/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
500, 501; T.C. A22CE, A27CE	SA2883SW	Installation of Ray Electronics Model 7507A battery current monitoring system. Issued 12/7/78.	SW	66500	Ray Electronics Company 11933 Warfield Drive San Antonio, TX 78216
500, 501; T.C. A22CE, A27CE	SA4034SW	Zee systems air conditioner. Issued 8/30/79.	SW	28775	Darling Aviation, Inc. P.O. Box 79230 Fort Worth, TX 76179
500, 501, 550, 551; T.C. A22CE, A27CE	SA1051SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid battery. Issued 3/29/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
500, 501, 550, 551; T.C. A27CE, A22CE	SA2916SW	Installation of alternate gear horn switch. Issued 2/26/79.	SW	47720	Keith Products, Inc. 625 Opar Richardson, TX 75080
500, 501, 550, 551; T.C. A27CE, A22CE	SA4054SW	Installation of one, two, or three-place side facing seat, frame only. Issued 10/23/79.	SW	28000	Custom Aircraft Conversions 234 West Turbo Drive San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500, 550; T.C. A22CE	SA80RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Amended 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST151RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST166RM	Installation of three-place or single-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	ST174RM	Installation of extended width cabin door. Amended 5/18/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
500, 550; T.C. A22CE	SA483GL	Installation of a center console extension to house a long range navigation control display unit. Issued 12/22/80.	GL	47636	Kal-Aero, Inc. 5605 Portage Road Kalamazoo, MI 49002
500, 550; T.C. A22CE	SA503GL	Installation of wiring changes to aircraft equipped with dual flight directors to prevent the uncoupled flight director system trim control switch (TCS) from disrupting the coupled flight director/autopilot operation. Issued 2/6/81.	GL	47630	K-C Aviation, Inc. Outagamie Airport Appleton, WI 54911
500, 550; T.C. A22CE	SA1457CE	Install microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
500, 550; T.C. A22CE	SA1513CE	Installation of Avcon 4001-213 and -214 stretcher. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
500, 550; T.C. A22CE	SA1534CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
500, 550; T.C. A22CE	SA2906WE	Installation of vertical tail floodlights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
500, 550; T.C. A22CE	SA3000SW	Fabrication and installation of 3-place side facing couch and shoulder harness. Issued 5/25/79.	SW	04546	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
501; T.C. A27CE	ST117RM	Installation of deluxe three-place aft couch. Issued 10/11/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	ST118RM	Installation of tail cone storage box and engine cover storage box. Issued 10/22/77.	RM	17085	Branson Aircraft Corporation 7993 West 48th Ave. Wheat Ridge, CO 80033
501; T.C. A27CE	SA125RM	Installation of tail cone ski rack. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA126RM	Installation of stretcher. Issued 12/22/77.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA152RM	Installation of extended range fuel tank and relocation of aft pressure bulkhead. Issued 9/15/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA177RM	Installation of a single seat in the center of aft baggage compartment. Issued 6/25/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway, Unit B Denver, CO 80216
501; T.C. A27CE	SA732NW	Installation of "Eagle" performance kit. Issued 5/10/79.	NW	12270	ASTEC Snohomish County Airport Everett, WA 98204
501; T.C. A27CE	SA926NW	Installation of wing tip recognition lights on ASTEC "Eagle" modified Cessna 501. Issued 5/5/80.	NW	01535	Advanced Systems Technology, Inc. Snohomish County Airport Everett, WA 98204
501; T.C. A27CE	SA1372CE	Dual camera installation. Reissued/amended 10/14/77.	CE	20625	Cessna Aircraft Company Wallace Division P.O. Box 7704 Wichita, KS 67277

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
501; T.C. A27CE	SA1423CE	Insalll King KFC-300 AFCS with duel flight director and transferable autopilot. Issued 6/21/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
501; T.C. A27CE	SA1580CE	Installation of tail-cone baggage compartment. Issued 3/7/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
501, 551; T.C. A27CE	SA150RM	Installation of fully reclining seat backs. Amended 10/20/78.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA171RM	Installation of three-place side facing couch. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
501, 551; T.C. A27CE	SA1514CE	Installation of Avcon 4001-213 and -214 stretchers. Issued 11/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA1535CE	Installation of side facing jump seat. Issued 11/5/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd St. North Wichita, KS 67204
501, 551; T.C. A27CE	SA3409WE	Installation of vertical tail floodlights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
550; T.C. A22CE	ST165RM	Installation of fiberglass tail cone in lieu of metal tail cone. Issued 1/22/79.	RM	17085	Branson Aircraft Corporation 4275 Broadway Denver, CO 80216
550; T.C. A22CE	ST207RM	Installation of tail cone assembly with H-field antenna for VLF/Omega installations. Issued 11/26/80.	RM	25252	Combs Gates Denver, Inc. Avionics Division Hangar #1 Stapleton Inter'l Airport Denver, CO 80207
550; T.C. A22CE	SA458GL	Installation of a Collins LRN-70 VLF/Omega navigation system. Issued 10/2/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
550; T.C. A22CE	SA482GL	Installation of a Collins LRN-85 Omega Navigation System. Issued 12/18/80.	GL	19833	Capital Aircraft Electronics, Inc. P.O. Box 19741 AMF 4808 East Fifth Avenue Columbus, OH 43219
550; T.C. A22CE	SA1499CE	Installation of Total Flood (TFC) Halon 1301 fuselage flood system. Issued 7/11/79.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
551; T.C. A27CE	SA208RM	Installation of tail cone assembly with H-field antenna for VLF/Omega installations. Issued 11/26/80.	RM	25252	Combs Gates Denver, Inc. Avionics Division Hangar #1 Stapleton Inter'l Airport Denver, CO 80207
551; T.C. A27CE	SA1500CE	Installation of Total Flood (TFC) Halon 1301 fuselage flood system. Issued 7/11/79.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015
CH-1C; T.C. 3H10	SH4WE	Fifth passenger seat and seat belt.	NW	84625	Washington Aircraft & Transport Co. Boeing Field Seattle, WA 98101
Miscellaneous	SA582NW	Replacement wire rope cable assemblies. Issued 5/12/78.	NW	81180	University Swedging 800 N.W. 46th Street Seattle, WA 98108

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

COMPOSITE AIRCRAFT CORP.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Windecker AC-7; T.C. A7SW	SA4088SW	Brittain Model B-5 flight control system. Issued 2/27/80.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Windecker AC-7; T.C. A7SW	SA4089SW	Brittain BI-822 horizontal situation indicator adapter. Issued 2/27/80.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

DEHAVILLAND AIRCRAFT

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH82A; T.C. A8EU	SA1008WE	Installation of poly-fiber covering material of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
DH82A; T.C. A8EU	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 6/6/74.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Tiger Moth N-82DS; T.C. A8EU	SA2666WE	Covering of Ceconite 102 material on wings, fuselage and empennage. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Beaver DHC-2; T.C. 806	SA3-105	L2C automatic pilot with altitude control and approach coupler. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
Beaver DHC-2; T.C. 806	SA3-591	C5500 main ski and AWB4820 tail ski.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
Beaver DHC-2; T.C. 806	SA4-182	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
Beaver DHC-2; T.C. 806	SA4-322	Full-flow oil filter 1050-B-83 with element 1A0094.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
Beaver DHC-2; T.C. 806	SA37EA	Removal of left rear cabin door for parachute jumping operations.	NE	85240	Westover SAC Aero Club Westover AFB, MA 01022
Beaver DHC-2; T.C. 806	SA115WE	Pratt & Whitney R-985-APS4 installation converted under STC SE4-864.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
Beaver DHC-2; T.C. 806	SA245AL	Relocation of wing tip fuel control valve.	AL	44050	U.S. Department of Interior Bureau of Commerical Fisheries P.O. Box 6088 Anchorage, AK 99500
Beaver DHC-2; T.C. 806	SA263SO	Removal of power plant extinguisher system and installation of firewall patches.	SO	74928	State Airlines, Inc. Municipal Airport Charlotte, NC 28208
Beaver DHC-2; T.C. 806	SA284NW	Installation of 3 place center seat in aircraft using original civilian or UgA military floor fittings. Amended 6/17/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA305NW	Installation of EDO 5250 floats and stabilizer fins. Issued 6/15/76.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA306NW	Installation of EDO 4665 floats. Issued 6/15/76.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA309NW	Installation of auxiliary vertical stabilizer fins. Issued 6/15/76.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA356NW	Installation of EAC-2D30-425/AG-100-4S propeller on Pratt & Whitney R-985 series engines. Issued 9/13/76.	NW	62120	Pacific Propeller P.O. Box 946 Kent, WA 98031
Beaver DHC-2; T.C. 806	SA397NW	Remove transport battery and battery box and install Gill 12-GCAB-9 or equal battery and battery box relocated to firewall per II K-8784. Issued 1/21/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA398NW	Install Hartzell HC-B3R30-4 propeller with R10152-5 1/2 blades, Hartzell C-4 propeller governor and Hartzell 836-32SR propeller spinner per II K-8785. Issued 1/24/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028,
Beaver DHC-2; T.C. 806	SA415NW	Installation of EDO Model Wb-5030 floats. Issued 3/10/77.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Beaver DHC-2; T.C. 806	SA416NW	Installation of EDO Model 61-5870 floats. Issued 3/10/77.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-2; T.C. A-806	SA417NW	Installation of EDO Model Ya-6235 floats. Issued 3/10/77.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-2; T.C. A-806	SA523NW	Installation of float hatch covers on Edo 58-4580, 348-4580 or 679-4930 floats. Issued 10/11/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2; T.C. A-806	SA524NW	Remove left or right rear cabin entrance door. Issued 10/12/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2; T.C. A-806	SA547AL	Modification of elevator and horizontal stabilizer tips. Issued 4/7/75.	AL	44050	U.S. Department of Interior Office of the Secretary Office of Aircraft Services 1936 Merrill Field Drive Anchorage, AK 99501
DHC-2; T.C. A-806	SA590NW	Installation of Hartzell HC-B3R30-1/R10152-5-1/2 propeller on P & W R-985 series engine. Amended 6/9/78.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA622WE	Fuel injected Pratt & Whitney R-985-AN-1, -2, -3, -4, -6, -6B, -8, -10, -12B, -14B, -14B1 or Wasp Jr. SB-3 engine.	WE	13750	Aviation Power Supply, Inc. 3011 Kenwood Street Burbank, CA 91503
DHC-2; T.C. A-806	SA646NW	Modification of mail landing gear axles. Issued 11/1/78.	NW	37175	General Aircraft Supply 7149 Perimeter Road, S. Seattle, WA 98108
DHC-2: T.C. A-806	SA660WE	Installation of HRD-type fire extinguishing system. Amended 7/11/77.	WE	43180	HTL Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
DHC-2; T.C. A-806	SA703NW	Installation of enlarged side windows for aft cabin. Issued 1/10/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2; T.C. A-806	SA736NW	Installation of Cleveland 40-46 wheels and 30-31 brakes. Issued 4/6/79.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
Beaver DHC-2; T.C. 806	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Beaver DHC-2; T.C. 806	SA1744WE	Installation of various series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
Beaver DHC-2; T.C. 806	SA1829WE	Installation of EDO Model 679-4930 floats.	NW	46400	Jobmaster Company, Inc. 1005 W. Perimeter Road Renton, WA 98055
Beaver DHC-2; T.C. 806	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
DHC-2, MK 1; T.C. A-806	SA107NW	Installation of EDO Model Yd-6470 floats. Reissued 10/22/74.	GL	71516	Shawano Flying Service 248 Airport Road Shawano, WI 54166
DHC-2, MK1; T.C. A-806	SA425NW	Installation of 75 lb. capacity baggage compartment below the existing baggage compartment. Issued 3/28/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK1; T.C. A-806	SA426NW	Enlarged baggage compartment. Issued 3/23/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DH-2, MK1; T.C. A-806	SA427NW	Cabin access steps attached to float struts. Issued 3/28/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK1; T.C. A-806	SA428NW	Water rudder steering system. Issued 3/28/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DHC-2, MK1; T.C. A-806	SA456NW	Installation of auxiliary seaplane stabilizer fins. Issued 6/2/77.	NW	47740	Kenmore Air Harbor P.O. Box 64 Kenmore, WA 98028
DHC-2, MK 1; T.C. A-806	SA527AL	Removal of left rear door for parachute jumping. Issued 8/9/74.	AL	19906	A. Dean Carrell 7100 Lake Otis Parkway Anchorage, AK 99507
Beaver DHC-2, MK 1; T.C. 806	SA1913WE	Installation of EDO Model 679-4930 floats. Amended and reissued 8/27/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
DHC-2, MK 1; T.C. A-806	SA2520WE	Hatch installation in Bristol amphibious floats. Issued 4/28/72.	NW	61626	North Country, Inc. 2525 14th Avenue South Seattle, WA 98168
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14(14V) or -28(28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
DHC-2, MK.I, MK.II, MK.III; DHC-3; DHC-6, Models 1, 100, 110, 200, 210, 300; T.C. A-806, A-815, A9EA	SA800EA	Installation of Aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W (red/white), or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
Otter DHC-3; T.C. 815	SA4-183	101-78 engine mount.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
Otter DHC-3; T.C. 815	SA135NW	Installation of Sorm Industries bulk cargo tank. Issued 11/15/74.	NW	73820	S[illegible]m Industries [illegible]99 Perimeter Road Seattle, WA 98108
Otter DHC-3; T.C. 815	SA336NW	Installation of Hamilton Standard 23D40-311/6601A-7 propeller. Issued 8/18/76.	NW	40517	Harold J. Hansen 20602 - 135th Avenue South Seattle, WA 98148
DHC-3; T.C. A-815	SA678NW	Installation of Edo Model 56-7850A floats. Issued 10/17/78.	NW	46400	Jobmaster, Inc. 608 West Perimeter Road Renton, WA 98055
DHC-6; T.C. A9EA	SA106NW	Installation of emergency exit on each side of fuselage. Amended 5/17/74.	EA	71910	S K Aircraft Company 16 Shotgun Lane Levittown, NY 11756
DHC-6; T.C. A9EA	SA235NW	Modification of cabin compartment airstair door. Issued 11/5/75.	NW	08360	Air Transport Industry Jet Air Hangar, Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA570NW	Installation of new interior interior panel. Issued 2/28/78.	NW	08360	Air Transport Industries Paine Field Everett, WA 98204
DHC-6; T.C. A9EA	SA841EA	Installation of radome and support bracketry for RCA AVQ-45 antenna and radar units. Issued 9/10/70.	EA	35300	Field Aviation Company Limited Toronto International Airport Malton, Ontario, Canada
DHC-6; T.C. A9EA	SA2366WE	Installation of emblem lights at mid span of horizontal stabilizer. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DHC-6; T.C. A9EA	SA3816WE	Installation of underseat baggage restraint bar. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DHC-6-100, -200, -300; T.C. A9EA	SA207GL	Install airborne fuel booster pump Model 1D2-14, or 1D2-17. Amended 7/30/80.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
DHC-6-100, -200, -300; T.C. A9EA	SA210RM	Fabrication and installation of a static line anchor cable. Issued 1/8/81.	RM	80915	United States Forest Service MEDC Building #1 Fort Missoula Missoula, MT 59801
DHC-6-100, -200, -300; T.C. A9EA	SA357AL	Installation of bulk fluid cargo tanks. Amended 5/15/72.	NW	78820	Sorm Industries 7999 Perimeter Road South Seattle, WA 98108

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DHC-6-100, -200, -300; T.C. A9EA	SA572EA	Installation of Safeway Model 5735 deicer boot and cable assembly. Amended 6/2/72.	NE	69750	Safeway Products, Inc. 440 Middlefield Street Middletown, CT 06457
DHC-6 Series 100, 200; 300; T.C. A9EA	SA943EA	Replacement of deHavilland wing bleed air ducting with alternate ducting. Reissued 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
DHC-6-100, -200, -300; T.C. A9EA	SA998EA	Installation of engine fuel drain recirculation system. Reissued 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
DHC-6 Series 100, 200; 300; T.C. A9EA	SA2516WE	Installation of lightning arrestors on wing tips and vertical fin. Issued 9/19/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6-100, -200, -300; T.C. A9EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
DHC-6 Series 100, 200, 300; T.C. A9EA	SA2608WE	Installation of equivalent modifications to deHavilland modifications. Issued 11/3/72.	WE	38250	Golden West Airlines, Inc. 5801 West Imperial Highway Los Angeles, CA 90045
DHC-6-1, -100, -200, -300; T.C. A9EA	SA1837WE	Installation of freon air conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2553WE	Installation of Adel cannister fuel pumps. Reissued 8/24/72.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, Model 1, 100, 200, 300; T.C. A9EA	SA2898WE	Installation of a fuel tank boost pump. Issued 6/14/74.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
DHC-6, S/N 130, 210, 231 and subsequent; T.C. A9EA	SA1117CE-D	Installation of Collins AP-106 autopilot. Amended June 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
DHC-6-200; T.C. A9EA	SA771EA	Installation of Dual Mark 15 Decca Systems.	EA	61542	New York Airways, Inc. P.O. Box 426 LaGuardia Airport Station Flushing, NY 11371
DHC-6-200; T.C. A9EA	SA3103WE	Removal of left-hand cargo doors to permit aircraft to engage in special operations, i.e. parachute jumping, aerial photography, etc. Issued 10/24/75.	WE	38250	Golden West Airlines, Inc. 5801 W. Imperial Highway Los Angeles, CA 90045
DHC-6-300; T.C. A9EA	SA130RM	Installation of dual-SELCAL system. Issued 1/28/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA132RM	Change in Airplane Flight Manual operating limitations to permit landings with air-operable jump-door open. Issued 2/15/78.	RM	07701	Department of the Air Force Hq., Aerospace Defense Command Peterson AFB, CO 80914
DHC-6-300; T.C. A9EA	SA135RM	Installation of Leach P/N V110-D-032-AC overvoltage relays. Issued 3/3/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-6-300; T.C. A9EA	SA170NW	Installation of bulk fluid cargo tank for carriage on non-flamable, non-corrosive, non-toxic liquids. Issued 4/3/75.	WE	73820	Sorm Industries 7999 Perimeter Road Seattle, WA 98108
DHC-6-300; T.C. A9EA	SA185RM	Installation of Bendix RDR-160 weather radar system. Issued 10/26/79.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
DHC-7-100; T.C. A20EA	ST127RM	Supplemental oxygen system installation. Issued 2/2/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
DHC-7-100; T.C. A20EA	ST128RM	Installation of ground proximity warning system, Collins FPC-75. Issued 1/23/78.	RM	68780	Rocky Mountain Airways Stapleton Int'l Airport Hangar No. 6 Denver, CO 80207
D.H. 104 Dove Series; T.C. 807	SA1-72	Three-place seat.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
D.H. 104 Dove Series; T.C. 807	SA1-73	39-gallon auxiliary fuel tank in cabin with 3-place seat per STC SA1-72.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
D.H. 104 Dove Series; T.C. 807	SA1-321	Airstair door.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
D.H. 104 Dove Series; T.C. 807	SA3-61	Sonotone battery (nickle cadmium) 19-24M320.	GL	18450	Burroughs Corporation 6071 Second Avenue Detroit, MI 48233
D.H. 104 Dove Series; T.C. 807	SA3-321	L-5B autopilot and integrated flight equipment CIS-100. Amended 5/4/67.	EA	52535	LSI Service Corporation Harrisburg Division 6700 Allentown Boulevard Harrisburg, PA 17112
D.H. 104 Dove Series; T.C. 807	SA3-472	Stewart Warner 940B combustion heater in forward lower baggage compartment.	GL	77430	Tag Airlines Div. of Miller Oil Company City Airport Detroit, MI 48233
D.H. 104 Dove Series; T.C. 807	SA4-496	Radio panel overhead installation including engine starting switches and instrument lighting switches.	WE	73883	Southern California Aircraft Corp. International Airport Ontario, CA 91761
D.H. 104 Dove Series; T.C. 807	SA4-1361	Ceconite 101 covering of fabric-covered surfaces.	WE	26240	Cooper Engineering Corporation P.O. Box 3428 Van Nuys, CA 91408
D.H. 104 Dove Series; T.C. 807	SA120SO	Instrument panel. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA121SO	Electrical circuit breaker panel and related electrical bus bars. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA122SO	Seats to accommodate 11 passengers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA165SO	Six single-place seats and one two-place couch. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA167SO	Electrically heated windshield left-hand side. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA168SO	Hartzell HC-A3VK-2/V8433-4R propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA170SO	Auxiliary fuel system and bladder type tanks in leading edges of the wings. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA171SO	B.F. Goodrich deicers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA303SO	Wing leading edge clean-up. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
D.H. 104 Dove Series; T.C. 807	SA319SO	A or B of turbocharged Lycoming IO-720-A1A engines and Hartzell propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
104 Series; T.C. A-807	SA399CE	Hoskins Supp. position light system, includes Model B (dual) wing tip light Model C, D, or K tail light with or without Model 2 fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
104 Series; T.C. A-807	SA620SO	Installation of Airstair door. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
104 Series; T.C. A-807	SA676SW	AK219 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
104 Series; T.C. A-807	SA1554WE	Installation of two AiResearch TPE331 series engines and increase in fuselage length.	WE	19150	C-Air, Inc. 3521 E. Spring Street Long Beach, CA 90806
DH-104 Series 1A, 2A, 5A, 6A; T.C. 807	SA164SO	Installation of swept vertical tail, wing tips and elevator (STC SA303SO is prerequisite to this STC); installation of Lycoming IO-720-A1A engines (STC SE163SO) and Hartzell HC-A3VK-2/V8433-4R propellers. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
DH-104 Series 1A, 2A, 5A, 6A; T.C. 807	SA135SW	Fuselage nose-mounted radome and structure.	SW	81300	C.R. Ursell 109 Briarcliff Drive San Antonio, TX 78205
DH-104-1A thru 8AXC; T.C. 807	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
D.H. 104, 1A, 2A, 5A, 5BA, 6A, 6BA, 7A, 8A; T.C. 807	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
C.H. 104 Dove Series 1A, 2A, 5A, 5BA, 6A, 6BA, 7A, 8A; T.C. 807	SA2666WE	Ceconite 102 material covering of control surfaces. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA1747WE	Installation of two AiResearch TPE 331 series engines, increase in fuselage length and related changes. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA1815WE	Installation of cabin interior. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA1924SW	Structural modification of horizontal tail. Issued 10/23/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. Box 575 Addison, TX 75001
D.H. Dove 104, Series 7A, 8A, 7AXC, 8AXC; T.C. 807	SA2438WE	Installation of spar reinforcing steel straps, on aircraft previously modified per STC SA1747WE. Reissued 5/23/73.	WE	25940	Consulting Aerospace Engineers 1845 Empire Burbank, CA 91504
D.H. 104 Dove Series 7AXC, 8AXC; T.C. A-807	SA2005WE	Installation of cabin air conditioning. This installation approved only on aircraft modified per STC SA1747WE. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 ADdison, TX 75001
D.H. 104 Dove Series 7AXC, 8AXC; T.C. A-807	SA2019WE	Installation of cabin heating system. This installation approved only on aircraft modified per STC SA1747WE. Reissued 9/5/74.	SW	78416	Texas Airplane Manufacturing Co., Inc. P.O. Box 575 Addison, TX 75001
D.H. 104 Dove Series; D.H. 114 Heron Series; T.C. 807, 816	SA249SW	Airstair door.	SW	68768	North American Rockwell Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
114 Heron Series; T.C. 816	SA629SO	Installation of Hartzell propellers HC-A3VF-2/V8433-7 equipped with Goodyear deicing equipment. Reissued 7/29/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
114 Heron Series; T.C. 816	SA633SO	Installation of electrically heated windshield.	SW	68150	Riley International Corporation 6211 W. Northwest Highway Dallas, TX 75225
D.H. 114 Heron; T.C. 816	SA816WE	Hartzell HC-A3X21-2L/L7636D propellers.	WE	70298	Charles Schachle 3901 E. Spring Street Long Beach, CA 90801
D.H. 114 Heron; T.C. 816	SA1228WE	Ceconite 101 covering of flaps and control surfaces.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
D.H. 114 Heron; T.C. 816	SA1323WE	Fabric on ailerons, elevators, flaps and rudder with "pop" rivets.	WE	06755	Aircraft Technical Service, Inc. 16300 Stagg Street Van Nuys, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
D.H. 114 Heron; T.C. 816	SA1535WE	Installation of combustion cabin heater.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
D.H. 114 Heron; T.C. 816	SA2805WE	Nickel Cadmium battery installation. Issued 1/25/74.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst AVenue Van Nuys, CA 91406
D.H. 114 Heron; T.C. 816	SA2806WE	Installation of additional emergency exits. Issued 1/25/74.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
D.H. 114 Heron Series 2A; T.C. A-816	SA740EA	Installation substitution of Lycoming engine IO-540-K1C5 in place of Lycoming Model IO-540-G1A4.	GL	87800	Wright Airlines, Inc. 2649 Broadway Cleveland, OH 44115
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST744SO	Installation of smoke detection system for forward and aft holds. Issued 12/13/74.	SO	65333	Puerto Rican Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST745SO	Installation of windshield wiper for co-pilot's (R.H.) position. Issued 12/13/74.	SO	65333	Puerto Rico Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA757SO	Installation of emergency exit RH fuselage at F.S. 49-76, and permanent closure of three existing overhead exits. Issued 3/4/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST758SO	Metal covering of wing flaps. Issued 5/3/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA919SO	Airplane life extension. Amended 6/20/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Heron Series 2A, 2DA, 2X; T.C. A-816	ST957SO	Installation of Teledyne battery Model BB638/T-C replacing two Rebat R-35 batteries. Issued 9/22/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	ST965SO	Modification of cockpit direct vision window. Issued 12/7/77.	SO	65333	Puerto Rico Int'l Airlines, Inc. Isla Verde, PR 00913
DH-114 Series 2A, -2DA, -2X; T.C. A-816	SA1089SO	Installation of shoulder harness for crew seats. Issued 7/19/75.	SO	65333	Puerto Rico Int'l Airlines, Inc. c/o Caribbean Aircraft Develop., Inc. Building 408-Opa Locka Airport Opa Locka, FL 33054
DH-114-2A, -2DA, -2X; T.C. A-816	SA1138SO	Installation of Bendix RDR 160B weather radar system. Issued 3/4/80.	SO	65333	Puerto Rico Int'l Airlines, Inc. c/o Caribbean Aircraft Develop., Inc. Building 408-Opa Locka Airport Opa Locka, FL 33054
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1368WE	Installation of Lycoming IO-540 series engines. Amended 10/31/72.	SW	68150	Riley International Corporation P.O. Box 5247 Waco, TX 76708
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1545WE	Installation of cabin interior arrangement, air conditioning equipment, electrically operated air compressors. Amended 6/25/68.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1685WE	Installation of four Continental IO-520-E engines. Amended 8/22/68.	SO	65333	Puerto Rico Int'l Airlines, Inc. P.O. Box 1498 Bayamon, PR 00619
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1710WE	Installation of stair door.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1729WE	Installation of over wing emergency exits and rear windows. Amended 12/4/69.	SO	65333	Puerto Rico Int'l Airlines, Inc. International Airport Isla Verde, PR 00913
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA1826WE	Installation of 22 occupant interior.	WE	06755	Aircraft Technical Service, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA2067WE	Installation of Janitrol 8-200 cabin heater. Reissued 7/29/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DH-114 Series 2A, 2DA, 2X; T.C. 816	SA3125WE	Installation of lower wing skin straps, lower spar doubler straps and engine mount pickup strap doublers. Amended 4/1/76.	WE	86680	Winters Aircraft Engineering Co. 17100 Ventura Boulevard Encino, CA 91316
DH-114, 2X; T.C. 816	SA1371WE	Interior installation.	WE	06755	Aircraft Technical Service, Inc. 16300 Stagg Street Van Nuys, CA 91406
DH-114, 2X; T.C. 816	SA1534WE	Installation of engine fire detection and extinguishment systems.	WE	06755	Aircraft Technical Service, Inc. 7150 Hayvenhurst Avenue Van Nuys, CA 91406
DH-114, 2X; T.C. 816	SA1544WE	Cockpit modification and generator control.	WE	06755	Aircraft Technical Service, Inc. 7150 Hayvenhurst Avenue Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

EMPRESA BRASILEIRA DE AERONAUTICA S/A

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Embraer EMB-110P1; T.C. A21SO	SA1576CE	Installation of Collins ANS-351 area navigation system. Issued 3/6/80.	CE	24250	Collins Avionics Division 400 Collins Road, NE Cedar Rapids, IA 52406
Embraer EMB-110P1; T.C. A21SO	SA1577CE	Installation of Collins AP-106/FD-112 automatic flight control system. Issued 3/6/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
Embraer EMB-110P1; T.C. A21SO	SA1578CE	Installation of Collins electrical elevator trim system. Issued 3/6/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
Embraer EMB-110P1, -110P2; T.C. A21SO	SA1162SO	Installation of a Bendix FCS-8700 automatic flight control system including optional flight director. Issued 7/31/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
Embraer EMB-110P1, -110P2; T.C. A21SO	SA1167SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid battery. Issued 7/31/80.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, N.W. Atlanta, GA 30338
EMB-110P1, -110P2; T.C. A21SO	SA4257SW	Coat closet in passenger compartment. Issued 1/7/81.	SW	69214	Royale Turbines, Inc. Shreveport Regional Airport Shreveport, LA 71109

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

GATES LEARJET CORP.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
23 Series; T.C. A5CE	SA148GL	Installation of radome kit #088X. Issued 1/31/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
23 Series; T.C. A5CE	SA377AL	Installation of nose wheel guard. Issued 6/19/70.	AL	05958	Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501
23 Series; T.C. A5CE	SA1019CE	Install lower cabin door designed to accommodate flare racks. Issued May 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1020CE	Install lower cabin door to accommodate aerial photography equipment. Issued May 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1098CE	Installation of drift (navigation) sight to be used in conjunction with aerial photography equipment. Issued February 1975.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1169CE	Stretcher installation in cabin area. Issued 10/21/75.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1171CE	Stretcher installation in baggage area. Issued 10/21/75.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
23 Series; T.C. A5CE	SA1290WE	Installation of "Quasar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
23 Series; T.C. A5CE	SA1299CE	Installation of provisions for infra-red scanning equipment. Amended July 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23 Series; T.C. A5CE	SA1321CE	Installation of dry ice dispenser. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23 Series; T.C. A5CE	SA1335CE	Installation of datum console rack. Issued 6/27/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23 Series; T.C. A5CE	SA1378CE	Install structural provisions on right hand side of airplane for removable camera door. Issued 10/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23 Series; T.C. A5CE	SA1381CE	Structural provisions for infra-red scanning equipment. Issued 10/26/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
23; T.C. A5CE	SA1395CE	Install structural provision for Jelco infra-red scanner. Issued 1/5/78	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1396CE	Install lower cabin door designed to accept a carousel flare dispensing unit capable of being reloaded in flight. Issued 2/8/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1411CE	Install structural provision for a particle measuring probe. Issued 4/18/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1412CE	Install dry ice dispenser. Issued 4/19/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
23; T.C. A5CE	SA1548CE	Structural provision for NASA - Daedalus IR scanner. Issued 2/22/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
23 Series; T.C. A5CE	SA2294WE	Modification of nose wheel steering system. Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
23 Series; T.C. A5CE	SA2992WE	Installation of logo lights on horizontal stabilizer lower surface. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
23, 24 Series; T.C. A5CE, A10CE	SA481CE	Modification of electrical system for compliance with AD 66-14-02.	GL	34020	Executive Jet Aviation, Inc. Port Columbus Int'l Airport Columbus, OH 43219
23, 24 Series; T.C. A5CE, A10CE	SA830SW	Heat static units.	SW	29232	Delta Aircraft P.O. Box 12182 San Antonio, TX 78205
23, 24, 24A, 24B, 24C, 24D, 25, 25B, 25C; T.C. A5CE, A10CE	SA21RM	Installation of cabin divider. Issued 12/5/73.	RM	25252	Combs Gates Denver, Inc. Hangar #7 Stapleton Int'l Airport Denver, CO 80207
23, 24, 24B, 24D, 25, 25B, 25C; T.C. A5CE, A10CE	SA412CE	Installation of Woodward Electronic Engine synchronizer system.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
23, 24, 24B, 24D, 25, 25B, 25C, 35, 36; T.C. A5CE, A10CE	SA871SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 25, 25A, 25B, 25C; 35, 36; T.C. A5CE, A10CE	SA996EA	Installation of Shaw Aero fuel filler cap P/N's 457-2, -266, 370, -431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A; T.C. A5CE, A10CE	SA2429WE	Installation of windshield rain repellent system. Issued 10/8/71.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
23, 24, 24A, 24B, 24C, 24B-A, 25, 25A; T.C. A5CE, A10CE	SA2447WE	Installation of Lear Ni-Cad safety unit. Reissued 10/24/72.	WE	49850	Lear Avia Corporation P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
23, 24, 25; T.C. A5CE, A10CE	SA175RM	Replacement of throttle knob, Model EP-004, for 20 series Learjet equipped with Dee Howard thrust reversers. Issued 6/18/79.	RM	45790	Jet Accessories, Inc. P.O. Box 38568 Stapleton Field Denver, CO 80238
23, 24, 25 Series; T.C. A5CE, A10CE	ST488SO	Installation of Butler National 6A VAC/10A ADD Area Navigation System with altitude alerting capabilities that meet requirements of FAR 91.51. Issued 1/28/72.	SO	73874	Southern Airways Company Hangar One Atlanta, GA 30320
23, 24, 25, 35, 36 Series; T.C. A5CE, A10CE	SA1033SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid batteries. Amended 11/26/80.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
24; T.C. A10CE	SA841NW	Performance improvement fairings to wing and nacelles. Issued 10/23/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road Seattle, WA 98108
24; A10CE	SA1065SO	Installation of support rack (incubator). Issued 4/18/79.	SO	64150	Personalized Interiors, Inc. 240 S.W. 34th Street Ft. Lauderdale, FL 33315
24 Series; T.C. A10CE	SA1874WE	Installation of Janco auxiliary cabin heater.	RM	37098	The Gates Rubber Company 8601 Montview Boulevard Denver, CO 80220
24 Series; T.C. A10CE	SA2329WE	Installation of Microcom, Inc. Lear AFC-70 autopilot (previous modification per STC SA2228WE - Microcom, Inc. nose wheel steering modification required). Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
24 Series; T.C. A10CE	SA2373WE	Installation of Microcom, Inc. Lear altitude alerter system, Microcom P/N 800074. Reissued 1/8/73.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
24, 24A, 24B; T.C. A10CE	SA1549CE	Installation of structural provisions for infra-red scanning equipment. Issued 2/26/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, B, BA, C, D, D-A, 25, 25A, B, C; T.C. A10CE	SA1RM	Installation of cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, D, E, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA14RM	Installation of Branson flight crew emergency exit. Amended 6/12/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A, B, B-A, C, D, D-A, E, F, 25, 25A, B, BC, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA149GL	Installation of radome kit 4088X. Issued 1/31/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations Akron, OH 44309
24, 24A, 24B, 24C, 24D, 25, 25A, 25B, 25C; T.C. A10CE	SA960CE	Lower cabin door designed to accommodate four flare racks for cloud seeding. Issued February 1974.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E, 24F, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA961CE	Installation of lower cabin door designed to accommodate aerial photography equipment. Amended 6/7/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E,, 25, 25A, 25B, 25C, 25D, 25F, 35, 36; T.C. A10CE	SA1091CE	Installation of drift (navigation) sight to be used in conjunction with aerial photography equipment. Amended 5/3/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A thru 24F, 25, 25A thru 25F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1170CE	Stretcher installation in cabin area. Amended 6/1/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A thru 24F, 25, 25A, B, D, F, 28, 35, 35A; T.C. A10CE	SA1172CE	Stretcher installation in baggage area. Amended 6/1/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 24A, 24B, 24C, 24D, 24E, 24F, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA1281CE	Lower cabin door designed to accommodate a flare rack capable of being reloaded in flight. Amended 6/22/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA1298CE	Installation of provisions for infra-red scanning equipment. Reissued July 1977.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
24, 24A thru 24D, 25, 25A thru 25F (S/N 25-229 or earlier), 35, 35A, 36, 36A; T.C. A10CE	SA1322CE	Installation of dry ice dispenser. Issued May 1977.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
24, 24A, B, C, D, 25, 25A, B,C, D, F; T.C. A10CE	SA1332CE	Install Litton digiprox ground proximity warning system (GPWS). Reissued 8/3/78.	WE	51500	Aero Products Division Litton Systems, Inc. 21050 Burbank Boulevard Woodland Hills, CA 91364
24, 24A, B, C, D, 25, 25A, B, C, D, 35, 35A, 36, 36A; T.C. A10CE	SA1336CE	Installation of datum console rack. Reissued 9/13/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1377CE	Install structural provisions on right hand side of airplane for removable camera door. Amended 6/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1382CE	Structural provisions for infra-red scanning equipment. Amended 6/4/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F; T.C. A10CE	SA1394CE	Install structural provision for Jelco infra-red scanner. Issued 1/5/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F; T.C. A10CE	SA1397CE	Install lower cabin door designed to accept a carousel flare dispensing unit capable of being reloaded in flight. Issued 2/8/78.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1410CE	Install structural provision for particle measuring probe. Amended 6/22/79.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA1413CE	Installation of dry ice dispenser. Amended 6/4/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street N. Wichita, KS 67204
24, 24A, B, C, D, E, F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1477CE	Structural plug installation in right side of forward fuselage when camera door is removed. Issued 3/21/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA2876WE	Installation of vertical tail floodlights on the horizontal stabilizer. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3225WE	Installation of R.C.A. Primus 35 weather radar system. Issued 6/25/76.	WE	37095	Gates Learjet Modification & Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3226WF	Installation of Collins FD 112V flight director system. Issued 6/25/76.	WE	37095	Gates Learjet Modification & Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 24F; T.C. A10CE	SA3263WE	Installation of J.E.T. DAC 2000 RNAV system. Issued 11/29/76.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, 25, 25A, b, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3264WE	Installation of Global GNS-500A VLF navigation system. Reissued 3/3/78.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3326WE	Installation of Collins ALT-55 radio altimeter. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A thru 24F, 25, 25A thru 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3327WE	Installation of Motorola Model NA135 Selcal system. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E,F, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3328WE	Installation of flight data recorder Sundstrand Model FA542. Issued 1/21/77.	WE	37095	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3422WE	Installation of dual Collins MC-103 compass systems.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3426WE	Installation of R.C.A. Primus 400 weather radar system. Issued 6/29/77.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24C, 24D, 24D-1, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F; T.C. A10CE	SA3615WE	Installation of Collins NCS-31A area navigation system. Issued 4/7/78.	WE	37095	Gates Learjet-Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3647WE	Installation of dual Collins ALT-50 and ALT-55 radio altimeter system with comparator. Issued 6/5/78.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734 .

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
24,. 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3677WE	Installation of Wulfsberg WT-200 communication transceiver system. Issued 8/31/78.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F; T.C. A10CE	SA3807WE	Installation of Jet Elec. & Tech. DAC-2000 R/NAV system with transfer switching for data from pilot to copilot panel. Issued 12/19/78.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA3735WE	Installation of optional single or dual H-field antenna (Global P/N 11455-1) for Global GNS-500A system. Amended 7/19/79.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3850WE	Installation of RCA Primus 300 color weather radar system. Issued 2/7/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3866WE	Installation of Wulfsberg Model AT-960 antenna. Issued 3/6/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29; T.C. A10CE	SA3899WE	Installation of Collins F18-84 flight instrument system. Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA3915WF	Installation of RCA Primus 400 check list (Data Nav I). Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA3975WE	Installation of Collins WXR-300 color radar. Issued 6/7/79.	WE	37095	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4003WE	Installation of Bendix RDR-1200/ RDR-1300 color radar check list. Issued 7/26/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29; T.C. A10CE	SA4028WE	Installation of Sundstrand Mark II ground proximity warning system. Issued 9/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25B, D; T.C. A10CE	SA4054WE	Installation of SUNAIR ASB-850 high frequency radio communications system. Issued 1/16/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F; T.C. A10CE	SA4073WE	Installation of Sunair ASB-850 high frequency radio communication system. Issued 1/23/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A; 25, 25A, B, C, D, F, 28, 29, 35, 36, 35A, 36A; T.C. A10CE	SA4131WE	Installation of Collins RNS-300 radar navigation system. Issued 7/18/80.	WE	37095	Gates Learjet Corporation P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4194WE	Installation of dual Sperry C-14A compass systems. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
24, 24A, B, B-A, C, D, D-A, E, F, F-A, 25, 25A, B, C, D, F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4195WE	Instalaltion of Collins FPA-80 flight profile advisory system. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
24, 24B; T.C. A10CE	ST485SO	Installation of Smiths Industries Type 3B series (WL/1101 AM/MS or 1103 AM/MS) servoed altimeter WL/504/CUF altitude alerting unit, and Smiths pressure error transducer (Type A108 for Model 24 and Type 104 for Model 24B). Issued 1/19/72.	SO	73075	Smiths Industries, Inc. St. Petersburg/Clearwater Airport St. Petersburg, FL 33732
24, 24D; T.C. A10CE	SA944NW	XR drag reduction system, including recontoured wing leading edge, ailerons, flaps, outboard wing, tip fin cuff, inboard wing, engine pylon, engine nacelle and convergent - divergent nozzles. Issued 6/16/80.	NW	43005	The Dee Howard Company P.O. Box 17300 San Antonio Inter'l Airport San Antonio, TX 78217
24, 25; T.C. A10CE	SA117GL	Installation of cabin temperature control system. Issued 5/17/76.	GL	31640	Ned Wilkins Eaton Corp. Flight Operations Cuyahoga County Airport 355 Richmond Road Cleveland, OH 44143
24, 25; T.C. A10CE	SA891CE	Relocate optical window port. Amended May 1976.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North P.O. Box 4248 Wichita, KS 67204
24, 25; T.C. A10CE	SA1635WE	Modification of lower half of passenger entry door to accommodate camera installation. Amended 8/29/75.	WE	43450	Mark Hurd Aerial Surveys, Inc. Box 488 Goleta, CA 93017
24, 25; T.C. A10CE	SA1746SW	Model 7107 battery fault warning system. Issued 10/19/73.	SW	66500	Ray Electronics Company 107 Braniff Drive San Antonio, TX 78216
24, 25; T.C. A10CE	SA2228WE	Modification of nose wheel steering. Amended 5/12/75.	WE	49850	Lear Avia Corporation Avionics Division P.O. Box 10825 14505 Mt. Anderson Reno, NV 89506
24, 25, 35, 36 Series; T.C. A10CE	SA2788SW	Tail-stringer antenna housing. Issued 6/5/78.	SW	74965	Sted-Mac Co. Box 6123 A.T.S. Midland, TX 79701
24A as certified under STC SA7RM, 25, 25A, 25B modified per STC SA14RM; T.C. A10CE	SA9RM	Installation of cabin cargo retention nets. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24A as certified under STC SA7RM, 25, 25A, 25B modified per STC SA14RM; T.C. A10CE	SA10RM	Installation of cabin cargo liner. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24B, 24D; T.C. A10CE	SA136GL	Install Intercontinental Dynamics Corp.'s altimeter P/N 16007-703 or P/N 16007-803 in aircraft equipped with IDC altitude alerter. Issued 10/1/76.	GL	34020	Executive Jet Sales, Inc. Port Columbus Int'l Airport Columbus, OH 43219
24B, 24D, 25, 25B, 25C; T.C. A10CE	SA2675WE	Installation of sound suppressors. Reissued 11/12/75.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
24D; T.C. A10CE	SA31RM	Structural provisions for cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24D; T.C. A10CE	SA33RM	Quick change cargo restraint system. Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
24D; T.C. A10CE	SA232NW	Installation of Mark II performance system. Issued 10/24/75.	NW	66175	The Raisbeck Group 2471 Perkins Lane West Seattle, WA 98199
24D; T.C. A10CE	SA639RM	Install EP-001 starter/generator decoupler system. Issued 6/28/78.	RM	45790	Jet Accessories, Inc. P.O. Box 38568 Stapleton Field Denver, CO 80238
24D; T.C. A10CE	SA1648SW	Stretcher installation according to Qualitron Aero. Reissued 5/20/59.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
24E, 24F, 25D, 25F, 28, 29, 35, 35A, 36, 36A; T.C. A10CE	SA4146WE	Installation of Litton LTN-211 Omega/VLF navigation system. Issued 5/5/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
25 Series; T.C. A10CE	SA3280WE	Installation of fuel filler well for fuselage tanks. Issued 10/27/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
25, 25A, 25B, 25D, 28; T.C. A10CE	SA3891WE	Installation of Sunair Model ASB-130 high frequency radio communication system. Issued 3/27/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
25, 25A, 25B, 25C, 25D, 25F, 28, 29, 35, 36, 36A; T.C. A10CE	SA1489CE	Removal of 24-inch executive door and installation of 36-inch cargo door. Amended 7/3/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CF	SA1376CE	Andrea Radio Corp. (A-81) five station interphone system. Reissued 12/30/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
25, 25A, B, C, D, F, 35, 35A, 36, 36A; T.C. A10CE	SA1497CE	Structural provision for NASA - Daedalus IR scanner. Amended 12/19/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25, 25A, 25B, 25C, 25D, 25F, 35, 35A, 36, 36A; T.C. A10CE	SA3561WE	Installation of a fuel filter. Amended 5/20/80.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
25, 25B; T.C. A10CE	ST147RM	Installation of Communications Components Corp. Ontrac III VLF/Omega navigation system. Issued 8/7/78.	RM	05940	Aircraft Radio & Accessory, Inc. Hangar 1 Stapleton Internationl Airport Denver, CO 80207
25, 25B, 25C; T.C. A10CE	SA30GL	Installation of electronic engine synchronizer system. Issued 7/12/73.	GL	87250	Woodward Governor Company 5001 N. Second Street Rockford, IL 61101
25, 25B, 25C; T.C. A10CE	SA953CE	Installation of dual camera/intervalometer. Issued October 1973.	CE	12777	Avcon Industries, Inc. 1006 W. 53rd Street, North Wichita, KS 67204
25, 25B, 25C; T.C. A10CE	SA3622WE	Modifications to add installation provisions for twin aerial survey cameras in the belly of the airplane. Issued 4/10/78.	WE	43450	Mark Hurd Aerial Surveys, Inc. P.O. Box 489 Goleta, CA 93017
25 (equipped with ECR 1513), 25, 25C (equipped with ECR 1511), 25D, 25F; T.C. A10CE	SA900NW	Mark II performance system, including recontoured flap leading edge, wing vortex generator removal, installation of wing stall strips, etc. Issued 3/3/80.	NW	43005	Howard/Raisbeck P.O. Box 17300 San Antonio Inter'l Airport San Antonio, TX 78217
25B; T.C. A10CE	SA29RM	Install mid-fuselage cargo compartment (500 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA30RM	Install tail cone cargo compartment (300 pounds capacity). Reissued 5/11/79.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
25B; T.C. A10CE	SA92GL	Install a Foster Airdata System, Inc. AD611/D area navigation system. Reissued and amended 2/20/79.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
25D; T.C. A10CE	SA4034WE	Installation of Canadian Marconi CMA-771 Omega/VLF navigation system. Issued 12/26/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
28; T.C. A10CE	SA480GL	Installation of full microwave landing system airborne equipment. Issued 12/10/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
28, 29; T.C. A10CE	SA3926WE	Installation of Garrett Rescu 99 locator transmitter. Issued 5/9/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
29; T.C. A10CE	SA3928WE	Installation of Collins 718-U5 high frequency radio communications system. Issued 5/2/79.	WE	37094	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35; T.C. A10CE	SA1195CE	Installation of dual Sperry C-12 gyro-compass system for use as navigational air. Issued 1/23/76.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35; T.C. A10CE	SA2288SW	Litton LTN-104 inertial navigation system. Issued March 1976.	SW	12250	Associated Radio Service 6911 Lemmon Avenue Dallas, TX 75220
35, 35A; T.C. A10CE	SA3633WE	Installation of AiResearch AiRNAV-200 RNAV and Global GNS-500A VLF navigation systems. Issued 4/27/78.	WE	37095	Gates Learjet-Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA3931WE	Installation of Litton LTN-72R inertial navigation system with DME/DME update. Issued 5/11/79.	WE	37094	Gates Learjet Corproation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA4075WE	Installation of Collins 718U-5M high frequency radio communications system. Issued 1/11/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A; T.C. A10CE	SA4086WE	Installation of Sperry SPI-80 flight director system. Issued 2/26/80.	WE	37094	Gates Learjet Corporation P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA82RM	Installation of Sperry SP180/81 Flight Director System, interfaced with J.E.T. FC-200 Automatic Flight Control System. Issued 10/8/76.	RM	05940	Aircraft Radio and Accessory Company, Inc. Hangar #1 Stapleton Int'l Airport Denver, CO 80202
35, 35A, 36, 36A; T.C. A10CE	SA160GL	Install a J.E.T. DAC-2000 3-D RNAV system. Amended 4/15/77.	GL	46250	Jet Electronics & Technology, Inc. 5353 52nd Street, S.E. Grand Rapids, MI 49508
35, 35A, 36, 36A; T.C. A10CE	SA405NW	Installation of an ONTRAC III VLF/Omega navigation system. Amended 9/27/77.	NW	16888	Boise Cascade Aviation 3565 South Owyhee Boise, ID 83705
35, 35A, 36, 36A; T.C. A10CE	SA1507CE	Installation of electronic consoles on cabin seat rails. Reissued 8/20/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1508CE	Installation of mounting plates in the tail cone for mounting of electrical inverters. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1509CE	Installation of instrumentation rack and inverter rack in baggage compartment. Reissued 8/17/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA1531CE	Installation of a pod and aerodynamic fairing for target towing equipment. Amended 12/2/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
35, 35A, 36, 36A; T.C. A10CE	SA1533CE	Installation of a Maritime Patrol surveillance system. Reissued 11/16/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35, 35A, 36, 36A; T.C. A10CE	SA3198WE	Installation of Garrett TFE 731 engine synchronizer/EMI filter - engine speed. Issued 5/20/76.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. A10CE	SA3340WE	Installation of Communications Components Corp. ONTRAC III VLF/Omega navigation system. Issued 2/10/77.	WE	37094	Gates Learjet Modification and Service Center Tucson Int'l Airport Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3346WE	Installation of Collins Radio Co. flight profile comparator (ground proximity warning system - GPWS). Issued 2/18/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3375WE	Installation of Foster Airdata AD611D area navigation system. Amended 7/17/79.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3396WE	Installation of hydromechanical fuel controls, computers, and harnesses. Issued 5/5/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
35, 35A, 36, 36A; T.C. aA10CE	SA3398WE	Installation of cold cathode cabin lighting system. Issued 5/6/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, 35A, 36, 36A; T.C. A10CE	SA3411WE	Installation of AFCS heading select system. Issued 5/20/77.	WE	37094	Gates Learjet Modification and Service Center P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3420WE	Installation of pitch trim tone system. Issued 6/29/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3421WE	Installation of modified control wheel and stick pusher cutout system. Issued 6/29/77	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3438WE	Installation of Garrett AirNav 100 or 200 or 300 navigation system. Amended 8/29/80.	WE	07500	AiResearch Manufacturing Company of California 2525 West 190th Street Torrance, CA 90509
35, 35A, 36, 36A; T.C. A10CE	SA3440WE	Installation of VOR/ILS compass and vertical gyro instrument switching system.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3442WE	Installation of AFCS heading and/or pitch maneuver transfer systems. Amended 1/27/78.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3509WE	Installation of Tracor 7640 omega navigation system. Issued 11/4/77.	WE	37094	Gates Learjet - Tucson Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3530WE	Installation of dual Collins 718U-5 HF system. Amended 10/31/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3531WE	Installation of Sundstrand MKII ground proximity warning system. Issued 12/12/77.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3532WE	Installation of Collins ANS-31A area navigation system. Issued 1/12/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3568WE	Installation of Delco Carousel IV-A inertial navigation system. Issued 2/17/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3808WE	Installation of Jet Elect. & Tech. DAC-2000 3-D R/NAV system. Issued 12/20/78.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3865WE	Installation of Sperry C-11B compass system. Issued 3/5/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3896WE	Installation of Collins FIS-84 flight instrument system. Issued 4/10/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3916WE	Installation of directional gyro and vertical gyro transfer switching system. Issued 4/20/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA3994WE	Installation of ONTRAC III Mod 6, Omega/VLF navigation system. Issued 7/17/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA4192WE	Installation of Canadian Marconi CMA-771 Omega/VLF navigation system. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 35A, 36, 36A; T.C. A10CE	SA4196WE	Installation of dual Sperry SPI-502 flight director's system. Issued 7/18/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, 35A, 36, 36A; T.C. A10CE	SA4204WE	Installation of Collins FDS-85 flight director, pilots side. Issued 7/30/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35, 36; T.C. A10CE	SA766NW	Installation of stall fences and removal of vortex generators. Issued 5/4/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road South Seattle, WA 98108
35A; T.C. A10CE	SA450GL	Installation of a dual Canadian Marconi CMA-734 Omega navigation system. Issued 9/19/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
35A; T.C. A10CE	SA4060WE	Installation of Sunair ASB-500 high frequency radio communication system. Issued 1/17/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
35A, 36A; T.C. A10CE	SA1240CE	Installation of Intercontinental Dynamics Corp. RAD/BAR altimeter without voice terrain advisory. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1241CE	Installation of dual IDC maximum allowable mach/airspeed indicators type 575, P/N 25850. Issued July 1976.	CE	37094	Gates Learjet Corporation Wichita Mid-Continent Airport P.O. Box 1280 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1306CE	Install copilot's IDC maximum allowable airspeed/mach indicator type 575, P/N 26320. Issued 3/14/77.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67201
35A, 36A; T.C. A10CE	SA1340CE	Dual camera installation. Issued 7/14/77.	CE	37094	Gates Learjet Corporation 8220 West Harry Wichita, KS 67209
35A, 36A; T.C. A10CE	SA1505CE	Wing pylon external stores installation. Issued 9/28/79.	CE	37094	Gates Learjet Corporation P.O. Box 7707 Wichita, KS 67277
35A, 36A; T.C. A10CE	SA1609CE	Installation of dual camera provisions. Issued 10/6/80.	CE	37094	Gates Learjet Corporation 8220 West Harry Wichita, KS 67209
36, 36A; T.C. A10CE	SA3529WE	Installation of Litton LTN-72 inertial navigation system. Issued 1/13/78.	WE	37095	Gates Learjet - Tucson Tucson Int'l Airport P.O. Box 11186 Tucson, AZ 85734
36, 36A; T.C. A10CE	SA3864WF	Installation of Litton LTN-72R inertial navigation/area navigation system. Issued 3/6/79.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734
36, 36A; T.C. A10CE	SA4033WE	Installation of Litton LTN-72 (INS)/Global GNS-500A (VLF/Omega) or Litton LTN-72R (INS)/Global GNS-500A (VLF/Omega) interface. Amended 5/25/80.	WE	37095	Gates Learjet Corporation Tucson International Airport P.O. Box 11186 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340, 440: T.C. 6A6	SA59RM	Installation of Collins type 331A-6P/6A course indicator and relocation of altitude alert control. Issued 7/11/75.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440: T.C. 6A6	SA60RM	Installation of Sundstrand ground proximity warning system, glide slope monitoring system and Honeywell low range radio altimeter system. Issued 7/11/75. Supplemental T.C. SA4-1100.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440: T.C. 6A6	SA71WE	Fuel source modification for Ranger APU approved under STC SA2-962.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440: T.C. 6A6	SA83GL	Install Bendix GPW-83 ground proximity warning system. Issued 9/5/75.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450
340, 440: T.C. 6A6	SA96GL	Installation of Collins FPC-590A ground proximity warning system. Issued 11/7/75.	GL	90135	Zantop International Airlines, Inc. Detroit-Willow Run Airport Ypsilanti, MI 48197
340, 440: T.C. 6A6	SA104RM	Install dual SELCAL system. Issued 6/22/77.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100): T.C. 6A6	ST133RM	Modification of turbine inlet temperature indicator Model BH183M to install precision potentionmeter in place of original tapot. Issued 2/17/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340/440 (modified by STC SA4-1100): T.C. 6A6	ST134RM	Installation of coat closet at body station 230. Issued 2/22/78.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440: T.C. 6A6	SA151EA	Bendix doppler radar DRA-12.	EA	08196	Airmar Radio Service, Inc. 2177 Smithtown Avenue Ronkonkoma, NY 11779
340, 440: T.C. 6A6	SA184WE	Two 15KS-1000-A1 or two 15KS-1000-A1(P) standby rocket engines in fuselage tail cone. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
340, 440: T.C. 6A6	SA227EA	Nose cap weather radome. Amended 3/29/66.	EA	16600	Bethlehem Steel Corporation Aviation Service Division Bethlehem, PA 18016
340, 440 modified by STC SA4-1000: T.C. 6A6	ST209RM	Installation of flight attendant shoulder harness. Issued 12/1/80.	RM	37015	Frontier Airlines, Inc. 8250 Smith Road Denver, CO 80207
340, 440: T.C. 6A6	SA232CE	Install aural mach warning system. Amended 2/27/67.	GL	37808	General Motors Corporation 3044 W. Grand Boulevard Detroit, MI 48202
340, 440: T.C. 6A6	SA264EA	Janitrol S-200 heater for ground operation only.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
340, 440: T.C. 6A6	SA279WE	Window emergency exit on right side of aircraft at station 651.5.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
340, 440: T.C. 6A6	SA379CE	Installation of Hoskins twilighter Mk V intensity STC SA4-1100 modified aircraft. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
340, 400: T.C. 6A6	SA423WE	Cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440: T.C. 6A6	SA427EA	All cargo interior.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440: T.C. 6A6	SA428EA	Installation of FM #1, 2, and 3 Radiophone. Amended 5/26/67.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440: T.C. 6A6	SA429EA	Cabinet.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340, 440; T.C. 6A6	SA443WE	Installation of cargo door, a cargo floor and an emergency exit, plus removal of original cargo door and forward passenger entrance door. Reissued 2/6/70.	NW	49350	Robert T. Lamson 7840 Southeast 20th Mercer Island, WA 98040
340, 440; T.C. 6A6	SA451EA	Cockpit voice recorder.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA454CE	Model CH 3002-3181 Hoover Aircraft Products evacuation chute.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
340, 440; T.C. 6A6	SA483EA	Installation of cabin window at F.S. 730.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA494EA	ADF-PA Interconnection.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440; T.C. 6A6	SA495EA	Installation of Flight Interphone System.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440: T.C. 6A6	ST519SO	Installation of underseat baggage restraint bars. Issued 11/1/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440: T.C. 6A6	SA542CE	Make and install horizontal stabilizer tips.	GL	12578	Auto-Craft Engineering 1904 N. Colorado Avenue Indianapolis, IN 46206
340, 440: T.C. 6A6	ST548SO	Installation of external induction ram air scoops. Issued 8/28/73.	SO	53788	Mackey International Airlines 500 S.W. 34 Street Fort Lauderdale, FL 33315
340, 440: T.C. 6A6	ST596SO	Installation of exhaust system bracket. Reissued 11/18/80.	SO	12535	Atlas Aircraft Corporation 7400 Northwest 41st Street Miami, FL 33166
340, 440: T.C. 6A6	SA604EA	Installation of United Control Model F542 Flight Data Recorder.	EA	09520	Allegheny Airlines Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA651EA	Installation of UHF/FM Secure System.	EA	52012	Lockheed Aircraft Service, Inc. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
340, 440: T.C. 6A6	SA695WE	Rain repellant system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440: T.C. 6A6	SA669WE	Smoke detector, flight data recorder, and oxygen breathing system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440: T.C. 6A6	ST700SO	Installation of exterior emergency lighting system. Amended 5/8/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
340, 440: T.C. 6A6	SA775WE	Interior.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505
340, 440: T.C. 6A6	SA780WE	Yoke assembly, pilot and copilot control.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440: T.C. 6A6	SA788SO	Installation of main cabin floor panels, seat tracks, and seats to accommodate 50 passengers. Issued 8/15/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440; T.C. 6A5	SA791SO	Installation of a cabin attendant seat, stowage cabinet, and partition modification. Issued 9/19/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440; T.C. 6A6	SA874WE	Shoulder harness installation. Amended 6/9/76.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90404

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340, 440: T.C. 6A6	SA884EA	Installation of tail logo lights. Amended 10/19/71.	EA	18750	Butler Aviation Friendship, Inc. Sub. Butler Aviation International Friendship Int'l Airport Baltimore, MD 21240
340, 440; T.C. 6A6	SA896EA	Installation of Marshell interior kit assembly No. 96123. Amended 7/13/73.	EA	54200	Magee Plastics Company 6000 Babcock Boulevard Pittsburgh, PA 15237
340, 440; T.C. 6A6	SA908WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA925WE	Pitch servo of Sperry SP-20 autopilot system.	EA	16600	Bethlehem Steel Company 701 E. Third Street Bethlehem, PA 18016
340, 440; T.C. 6A6	ST926SO	Installation of cargo door and interior. Amended 7/18/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440: T.C. 6A6	ST927SO	Installation of cargo floor. Amended 8/27/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
340, 440: T.C. 6A6	SA1015WE	Modified fiberglass vertical stabilizer tip, and Grimes 9950-1 rotating beacon.	RM	37015	Frontier Airlines, Inc. Stapleton Int'lernational Airport Denver, CO 80207
340, 440: T.C. 6A6	SA1015EA	Installation of Atlantic Aviation Corp. (TSO C-39) attendant seat P/N 21,737-1. Reissued 10/24/80.	EA	12500	Atlantic Aviation Corporation Box 15000 Wilmington, DE 19850
340, 400 (580); T.C. 6A6	SA1027EA	Installation of Collins FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340/440 modified in accordance with STC SA4-1100; T.C. 6A6	ST1035SO	Installation of a combination passenger/cargo interior to include an all cargo, 44 passenger/cargo, 10 passenger/cargo, and 6 passenger/cargo configurations. Issued 12/4/78.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36302
340, 440; T.C. 6A6	SA1060WE	AP101E Collins autopilot.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
340, 440; T.C. 6A6	SA1096WE	Rolls Royce Dart 542-4 engines with Dowty Rotol (c) R245/4-40-4.5/13 or (c) R259/4-40-4.5/17 propellers and associated modifications. Amended 7/27/66.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440: T.C. 6A6	SA1097SO	Installation of two (2) double seats to increase passenger configuration from 44 to 48. Issued 8/30/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AI 36301
340, 440; T.C. 6A6	SA1119WE	Two additional emergency exits, and interior arrangement.	WE	37280	General Dynamics Conviar Division 3302 Pacific Highway San Diego, CA 92112
340, 440: T.C. 6A6	SA1132WE	Parker Aircraft, Inc. under-wing pressure refueling valve and Roylin "Magna-Stick" fuel indicator.	WE	06750	Aircraft Tack Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440: T.C. 6A6	SA1146WE	Collins autopilot and flight director systems.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA1174WE	Fuel jettison system.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
340, 440: T.C. 6A6	SA1218WE	Cargo floor, cargo door and forward service door.	WE	37280	General Dynamics Convair Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1268WE	Interior and equipment.	WE	62080	Pacific Airmotive Corp. Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340, 440; T.C. 6A6	SA1331WE	Installation of United Data Control, Inc. Model V-557 cockpit voice recorder system. Amended 3/28/67.	RM	37015	Frontier Airlines 5900 East 39th Street Denver, CO 80207
340, 440; T.C. 6A6	SA1338WE	Seat track, additional emergency exit and interior arrangement.	WE	37280	General Dynamics Corp. P.O. Box 1950 San Diego, CA 92112
340, 440; T.C. 6A6	SA1366WE	Installation of Collins Radio Company FD105 flight director system.	WE	37280	General Dynamics Convair Division P.O. Box 1950 San Diego, CA 92112
340, 440; T.C. 6A6	SA1407WE	Provide 52-passenger seat aircraft with cargo carrying capability by installing an aft cargo door and reinforcing the floor and fuselage shell. Amended 6/1/72.	WE	37280	General Dynamics Corporation Convair Aerospace Division 3302 Pacific Highway San Diego, CA 92112
340, 440; T.C. 6A6	SA1438WE	Installation of an Avionics System.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA1482WE	Installation of interior arrangement.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA1505WE	Installation of radio transformer rectifier for standby D.C. power.	WE	62080	Pacific Airmotive Corporation Aircraft & Engineering Center 3000 N. Clybourn Avenue Burbank, CA 91502
340, 440; T.C. 6A6	SA2302WE	Modification of pedestal flight idle stop and lift to reverse system. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
340, 440; T.C. 6A6	SA2697WE	Modification including those airplanes further modified per STC SA1096WE for turbo propeller power for installation of cargo door, cargo floor and cargo lining. Issued 5/25/73.	WE	10208	American Jet Industries, Inc. 2800 Clybourn Avenue Burbank, CA 90405
340, 440; T.C. 6A6	SA2733WE	Modification of Model 340/440 previously modified per STC SA4-1100 for turbo propeller power for installation of cargo door, cargo floor and cargo lining. Issued 9/5/73.	WE	10208	American Jet Industries, Inc. 2800 Clybourn Avenue Burbank, CA 91505
340,440; T.C. 6A6	SA2896SW	Conversion to an all-cargo configuration. Issued 1/15/79.	SW	08128	Airgo, Inc. LB-31 Love Field Terminal Bldg. Dallas, TX 75235
340,440; T.C. 6A6	SA2897SW	Composite flooring, one double seat, nonstructural bulkhead.	SW	08128	Airgo, Inc. LB-31 Love Field Terminal Bldg. Dallas, TX 75235
CV340/440; T.C. 6A6	SA3132WE	Installation of an alternate (printed circuits) ice protection system on the engine air intake. Amended 11/17/77. This installation is approved for use on airplanes modified in accordance with STC SA4-1100 only.	WE	71680	Sierracin/Thermal Systems 13920 South Broadway Los Angeles, CA 90061
340, 440; T.C. 6A6	SA3294WE	Modification by installation of dual mach/airspeed warning system. Reissued 1/20/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
340, 440; T.C. 6A6	SA3479WE	Modification by installation of an alternate pallet restraint system.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
340/440; T.C. 6A6	SA3574WE	Modification of Convair 340 or 440 which have been modified per STC SA4-1100. Issued 3/24/78.	WE	45500	Jay Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90904
340/440; T.C. 6A6	SA3758WE	Enlarge cargo door on aircraft modified per STC No. SA2733WE. Issued 10/17/78.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
340,440: T.C. 6A6	SA3772WE	Installation of cargo tie downs in aircraft modified per STC No. SA2733WE. Issued 11/1/78.	WE	10360	American Turbine Engine Company 1150 Busch Gardens Court Pasadena, CA
340, 440: T.C. 6A6	SA4075SW	BEM 100PHM-2 pitot head monitor system. Issued 1/17/80.	SW	16852	The BEM Company P.O. Box 7001 Dallas, TX 75209
340, 440: T.C. 6A6	SA4162WE	Installation of nose radome and relocation of airspeed pitot system. Amended 7/9/80.	WE	39876	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734
440: T.C. 6A6	SA4-49	Two 250-gallon auxiliary fuel tanks in wing center section.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA4-195	Janitrol S-50 ground heater.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA4-196	Extended wing tank installation and oil tank rework.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA4-245	GTP-70-17 auxiliary gas turbine power plant.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA4-314	Cabin interior.	WE	79995	Union Oil Company of California 617 W. Seventh Street Los Angeles, CA 90052
440: T.C. 6A6	SA4-407	Andover Type D-2, Model V-32 APU for ground operation only.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440: T.C. 6A6	SA4-408	Interior arrangement installation (right hand forward cargo door made permanently inoperative as an exit by seating arrangement).	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440: T.C. 6A6	SA4-675	Oscillograph rack.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA4-692	Interior equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440: T.C. 6A6	SA4-857	APN-14 antenna.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA4-897	Window station 730 L.H.	WE	07500	AiResearch Aviation Service Co. 6021 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA4-930	Aircraft interior.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
440: T.C. 6A6	SA4-1319	Bendix RDR-1D radar and equipment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA4-1428	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA195SW	Structural installation of Bendix AMA-12A-1 doppler antenna.	SW	12250	Associated Radio Service Co. 7515 Lemmon Avenue Dallas, TX 75220
440: T.C. 6A6	SA283WE	Interior and equipment installation.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
440: T.C. 6A6	SA384EA	Two three-place couches.	EA	03100	Aero Trades, Inc. Long Island Airport Ronkonkoma, NY 11779
440: T.C. 6A6	ST929SO	Installation of a cargo door. Issued 5/10/77.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
440: T.C. 6A6	SA4181WE	Installation of side mounts and seats. Issued 7/17/80.	WE	39876	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
440; T.C. 6A6	SA4183WE	Installation of underseat baggage restraint. Issued 7/10/80.	WE	39876	Hamilton Aviation Company P.O. Box 11746 Tucson, AZ 85734

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G44, G44A, Modified -- Colemill STC 2-13; T.C. A-734	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 1/19/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
G-44, G-44A, SCAN 30; T.C. 734	SA61SW	Horizontal stabilizer raised 5/8 inch per STC SA2-13.	SW	52870	J.R. McDermott & Company, Inc. Lakefront Airport New Orleans, LA 70113
G-44, G-44A, SCAN 30; T.C. 734	SA121EA	Wheel 40-46 and brake 30-31. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
G-44, G-44A, SCAN 30; T.C. 734	SA380WE	Engine, propeller and associated modifications of nacelle, electrical oil, fuel and vacuum systems.	NW	53520	McKinnon Enterprises, Inc. Route 1, Box 520 Sandy, OR 97055
G-44, G-44A, SCAN 30; T.C. 734	SA603WE	Large aft door. Reissued 3/17/67.	SO	37084	Gander Aircraft 3923 N.W. 24th Street Miami, FL 33142
G-44, G-44A; T.C. 734	SA835SO	Installation of Lycoming GO-480-G2D6 engines with Hartzell HC-A3VP-5R/V9333CH-3 reversing propellers. Reissued 10/9/79.	SO	02330	AEROMAR, Inc. 317 North Coconut Lane Palm Island Miami, FL 33139
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3174SW-D	Automatic flight system AK645 consisting of Century I autopilot with optional omni tracker system. Issued 1/31/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3175SW-D	Mitchell automatic flight system AK646 consisting of Century IIB autopilot with optional radio coupler. Issued 1/31/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44 (OA-14, F4F-2), G-44A and Scan Type; T.C. A-734	SA3176SW-D	Mitchell automatic flight system AK647 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/17/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3184SW-D	Automatic flight system AK656 consisting of Century I autopilot with optional omni tracker. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3185SW-D	Mitchell automatic flight system AK657 consisting of Century IIB with optional radio coupler. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G44, G44A Scan Type 30; T.C. 734	SA3186SW-D	Automatic flight system AK658 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 2/23/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Scan Type 30; T.C. A734	SA3221SW-D	Mitchell automatic flight system AK706 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 6/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
Scan Type 30; T.C. A734	SA3222SW-D	Mitchell automatic flight system AK705 consisting of Century IIB autopilot with optional radio couplers. Issued 7/8/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
G-44, G-44A; T.C. A-734	SA3979WE	Installation of Silver Instruments fueltron 111G digital fuel flow and totalizer system. Issued 6/15/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
G-73; T.C. 783	SA1-490	Opening in leading edge of right-hand wing for passing light installation.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
G-73; T.C. 783	SA1-546	Type 21 pump type pneumatic deicer system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
G-73; T.C. 783	SA3-22	Hull step fairing.	GL	17190	Briggs Manufacturing Company 6600 East Outer Drive Warren, MI 48089

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-73; T.C. 783	SA3-165	Two 100-ampere Eclipse 30E16-1 generators.	GL	37808	General Motors Air Transport City Airport Detroit, MI 48202
G-73; T.C. 783	SA3-194	Sonotone sintered-plate Alkaline Nickel-Cadmium battery.	GL	71520	George W. Sherwood City Airport Detroit, MI 48233
G-73; T.C. 783	SA4-1554	Structure modification to improve access to fuel tanks for stripping and resealing.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-73; T.C. A-783	SA36NE	Install Edison continuous loop fire detection system. Issued 11/6/80.	NE	11720	Armtec Industries Manchester Municipal Airport Manchester, NH 03103
G-73; T.C. 783	SA292EA	Pump type pneumatic deicer system.	GL	38500	B.F. Goodrich Airport Operations Municipal Airport Akron, OH 44318
G-73; T.C. 783	SA310EA	Fabrication of new passenger seats and necessary cabin interior modifications. Amended 4/5/68.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
G-73; T.C. 783	SA319SW	Structural installation of McMillan 7501XM radome and RCA AVQ-55 antenna mount.	SW	12250	Associated Radio Service Company 7515 Lemmon Avenue Dallas, TX 75220
G-73; T.C. A-783	SA412GL	Installation of Parker Hannifin conversion kit P/N 199-81. Issued 5/29/80.	GL	62500	Parker Hannifin Corporation Cleveland Wheels & Brakes Div. 1160 Center Road Avon, OH 44011
G-73; T.C. 783	SA614SO	Installation of nose wheel shimmy damper IAW Gander drawings GA-2055 Chg. A and GA-2056 Chg. A.	SO	37084	Gander Aircraft Corporation 3923 N.W. 24th Street Miami, FL 33142
G-73; T.C. 783	SA1008WE	Poly-Fiber covering of rudder. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
G-73; T.C. 783	SA2323WE	Increase in gross weight and installation of United Aircraft of Canada, Ltd., PT6A-27 engines. Amended 12/18/73.	WE	36699	Frakes Aviation, Inc. P.O. Box 159 Angwin, CA 94508
G-164; T.C. 1A16	SA4-1017	Lycoming R680-13 engine and Hamilton Standard 2B20-329/6135A-9 propeller.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA4-1019	Pratt & Whitney R-985-ANI, -NAS, -AN-14BMI, -39 or -39A engines and Hamilton Standard 2D30-277/6101A-12 to -18 propellers. Amended 9/30/65.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA32NW	Installation of 15.5 gallon auxiliary fuel tank in each upper wing panel. Amended 6/30/77.	NW	52066	Russell Longnecker Box 77 Mt. Vernon, WA 98273
G-164; T.C. 1A16	SA39WE	Pratt & Whitney R985-AN-3 engine and Hamilton Stnadard 2D30-227/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164; T.C. 1A16	SA170SW	Sensenich 5404R/MA96K propeller.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA287SW	Jacobs R-755-L4MB or R-755-B2M engine.	SW	52610	Lyon Flying Service, Inc. P.O. Box 726 Welsh, LA 70591
G-164; T.C. 1A16	SA312SW	Jacobs R-755-B2MI, R-755-B2M, L4M Series, R-755-A2M, or R-755-A2MI engine with short mount A1681, carburetor air filter box, funnel A1667, and Sensenich J5404/MA96K propeller.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901
G-164; T.C. 1A16	SA326CE	25-gallon auxiliary fuel tank on wing.	CE	59315	Mid-Continent Aerial Sprayers, Inc. P.O. Box 307 Hayti, MO 63851
G-164; T.C. 1A16	SA507SW	Optional 46-gallon wing center section fuel tank and alternate right-hand or left-hand carburetor muffs equipped with Jacobs L4M and R-755 series engine.	EA	39540	Grumman Aircraft Engineering Corp. P.O. Box 147 Elmira, NY 14901

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-164; T.C. 1A16	SA647WE	Modified landing gear.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA648WE	Additional flying wire.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA651WE	Modified wheels and brakes.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164; T.C. 1A16	SA1278WE	Ceconite 101 covering of wings and ailerons.	WE	26240	Cooper Engineering Corporation P.O. Box 3428 Van Nuys, CA 91408
G-164; T.C. 1A16	SA1295WE	Automatic flagman marker dispensing unit.	NW	03500	Air-Ag, Inc. Route 4 Walla Walla, WA 99362
G-164; T.C. 1A16	SA1407WE	Installation of Pratt & Whitney R-985-AN-1 engine and Hamilton Standard 2D30/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164; T.C. 1A16	SA1586WE	Installation of Pratt & Whitney R-1340-AN-1 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
G-164, G-164A; T.C. 1A16	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Amended 6/30/76.	WE	33500	EONAIR, Inc. 417 Watts Drive Bakersfield, CA 93307
G-164, G-164A; T.C. 1A16	SA270WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller. Amended 7/11/68.	WE	37000	Frenco Company 1849 Airport Drive Bakersfield, CA 93308
G-164, G-164A; T.C. 1A16	SA406NW	Installation of wing span extension. Amended 5/23/77.	RM	02360	Aero Mod General, Inc. Box 68 Latah, UT
G-164, G-164A; T.C. 1A16	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
G-164, G-164A; T.C. 1A16	SA940SW	Installation of Micronair AU-3000 spray units. Reissued 10/2/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164, G-164A; T.C. 1A16	SA1282SW	Jacobs-Page R-755SM engine and Grumman 5404/M96K propeller. Reissued 10/27/80.	SW	44943	Jacobs Service Company 4305 Saturn Way Chandler, AZ 85224
G-164 (S/N 301-400), G164A (S/N 400 and up); T.C. 1A16	SA1312WE	Fabrication and installation of 285-gallon fiberglass hopper (replaces 245-gallon metal hopper). Reissued 6/12/75.	GL	39542	Grumman American Aviation 318 Bishop Road Cleveland, OH 44143
G-164, G-164A; T.C. 1A16	SA1319CE	Chrome plated brake disc installation. Issued 7/22/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
G-164, G-164A; T.C. 1A16	SA1777WE	Installation of Hamilton Standard 3D40/6101A-17 propeller.	WE	85125	Western Aircraft Sales P.O. Box 753 Long Beach, CA 90801
G-164, G-164A; T.C. 1A16	SA2012WE	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101A-12 propeller.	WE	17022	Bowles Flying Service Route 1, Box 124-B Live Oak, CA 95953
G-164, G-164A, G-164B; T.C. 1A16	SA832SO	Installation of Hamilton Standard Model 2D30/6101A-10S propeller. Amended 10/15/76.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164, G164A, G-164B; T.C. 1A16	SA1427CE	Install smoke generator for Part 137, agricultural aircraft operations, only. Issued 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Box 508 Renner Field Goodland, KS 67735
G-164, G-164A, G164B; T.C. 1A16	SA3077WE	Installation of elevator servo-tab. Reissued 3/17/77.	WE	26540	Robert L. Copeland 171 West Shannon Chandler, AZ 85224

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-164, G-164A, G-164B; T.C. 1A16	SA4101WE	Installation of locking tail wheel. Issued 2/14/80.	WE	11470	APS Products, Inc. 6751 Airport Road Redding, CA 96001
G-164, G-164A, G-164B, G-164C; T.C. 1A16	SA2747SW	Lockable full swivel tail wheel. Issued 4/6/78.	SW	36700	Frakes Aviation Cleburne Airport Rt. 3, Box 229-B Cleburne, TX 76031
G-164, G-164A, AA-1, AA-1A, AA-1B, AA-5; T.C. 1A16, A11EA, A16EA	SA71GL	G-164's install P/N BA8210 filter assembly; AA-1, AA-5 install P/N BA 4210 filter assembly. Reissued 9/22/79.	WE	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140
G-164A; T.C. 1A16	SA99NW	Installation of HSP 3D40-401 hub with EAC-100-2 blades. Issued 3/29/74.	NW	33000	Efficiency Aircraft P.O. Box 37 Kent, WA 98031
G-164A; T.C. 1A16	SA445NW	Installation of EAC-22D30-AG-200-4S prop or P&W R-985-AN-1 engine. Issued 5/9/77.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A; T.C. 1A16	SA809SW	Installation of 5-inch longer engine mount in S/N 401 and up. Reissued 9/25/69.	EA	39540	Grumman Aerospace Corporation South Oyster Bay Road Bethpage, L.I., NY 11714
G-164A; T.C. 1A16	SA833SO	Installation of Hamilton Standard Model 12D40/6101A-10S propeller approved under STC SP830SO on Pratt & Whitney R1340-AN-1, S1H1 or S3H1 engines listed in TDS 1A16. Issued 4/28/75.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
G-164A; T.C. 1A16	SA994SW	Installation of Pratt & Whitney R-1340 engine and Hamilton Standard 12D40/6101-12 propeller. Reissued 4/19/73.	GL	39542	Grumman American Aviation Corp. 318 Bishop Road Cleveland, OH 44143
G-164A, S/N 526 and up with a P & W R-1340-AN-1 engine and Hamilton Standard 12D40 propeller; T.C. 1A16	SA1077CE	Installation of Edo-Aire propeller governor. Issued January 1975.	CE	32500	Edo-Aire, Inc. Wichita Division 1326 S. Walnut Street Wichita, KS 67213
G-164A; T.C. 1A16	SA1222SW	64-gallon or 80-gallon fuel tanks. Issued 11/17/70.	EA	39540	Grumman Aerospace Corporation P.O. Box 147 Elmira, NY 14902
G-164A; T.C. 1A16	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 7/24/73.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-164A; T.C. 1A16	SA1422SW	Paper filter for engine induction air. Issued 1/19/72.	SW	17260	Frank Brinster 2214 North Parkwood Harlingen, TX 78550
G-164A; T.C. 1A16	SA2015WE	The 12-volt or 24-volt D.C. electrical generating system is replaced by an alternator system. Amended 12/21/78.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
G-164A; T.C. 1A16	SA2356SW	Wing tip extension of 20 inches. Issued 9/14/76.	SW	34405	Fram & Ranch Aerial Service Wharton, TX 77055
G-164A; T.C. 1A16	SA2444SW	Install P&W ACL PT6A-34 engine. Issued 12/2/77.	SW	36700	Frakes Aviation, Inc. Route 2, Box 229-B Cleburne Airport Cleburne, TX 76031
G-164A; T.C. 1A16	SA2731SW	PZL-3S engine and Dowty-Rotol propeller CR 289/3-110-F/1. Issued 3/17/78.	SW	52610	Lyon Flying Service, Inc. P.O. Box 726 Welsh, LA 70591
G-164A, G-164B; T.C. 1A16	SA78RM	Installation of air conditioner system. Amended 6/21/77.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
G-164A, G-164B; T.C. 1A16	SA434NW	Installation of EAC-12D40-AG-100S-4S prop on Pratt & Whitney R-1340-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA436NW	Installation of WAC-2D30-425-AG-100-4A prop on Pratt & Whitney R-985-AN-1 engine.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
G-164A, G-164B; T.C. 1A16	SA1102SO	Installation of a 360-gallon agricultural spray dispensing hopper. Reissued 8/25/80.	WE	79295	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-164A, G-164B; T.C. 1A16	SA1129SO	Installation of a 320 gallon agricultural spray dispensing hopper. Issued 1/24/80.	WE	79295	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
G-164A, G-164B; T.C. 1A16	SA1131SO	Installation of replacement fiberglass fuselage skin panels. Reissued 8/25/80.	WE	79295	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
G164A, G164B; T.C. 1A16	SA2666WE	Ceconite 102 material covering of: G-164A - vertical and horizontal tail and wings; G-164B - complete aircraft. Amended 4/19/78.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
G-164A, G-164B; T.C. 1A16	SA4185WE	Installation of two Conrel dispensing pods. Issued 7/15/80.	WE	08550	Albany International Controlled Release Division P.O. Box 537 Buckeye, AZ 85326
G-164B; T.C. 1A16	SA199RM	Oil temperature controlled system. Issued 4/17/80.	RM	18268	Vincent S. Buraas P.O. Box 176 Northwood, ND 58267
G-164B; T.C. 1A16	SA474GL	Installation of a "Townend" engine ring cowling assembly. Issued 11/26/80.	GL	39306	Steven Govus Route 1, Box 461 Monon, IN 47959
G-164B; T.C. 1A16	SA4116SW	Lycoming LTP-101-600-A1A engine. Issued 4/29/80.	SW	62196	Page Industries, Inc. P.O. Bxo 191 Yukon, OK 73099
G-164B (Restricted Category); T.C. 1A16	SA3876WE	Installation of Alvis Leonides engine and Dowty Rotol (c)R284/3-20-3/8 constant speed propeller. Issued 3/6/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Morteson Avenue Salinas, CA 93905
G-164C (Restricted Category); T.C. 1A16	SA3764WE	Installation of Wright R-1820-71, -60; GR1820G-202A, 702C9GC1, 2, 3, 4, 704C9GC1, 2, 3, 4 engine and Hamilton Standard 43D50 or 33D50 constant speed propeller. Reissued 4/11/80.	CE	59320	Mid-Continent Aircraft Corp. Drawer L Hayti, MO 63851
G-164C; T.C. 1A16	SA4127WE	Installation of an AiResearch TPE331-1-101Z turboprop engine. Issued 4/18/80.	WE	75210	Floyd D. Stilwell Marsh Aviation 5060 E. Falcon Drive Mesa, AZ 85205
AA-1 Series; T.C. A11EA	SA809NW	Installation of fixed (flush) cowl flap, nose gear strut fairing and retainer. Issued 7/20/79.	NW	27241	Maynord C. Corsby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1 Series; T.C. A11EA	SA810NW	Installation of main landing gear fairings from the AA-5 series aircraft incorporating sheet metal covers over rubber in place of stock rubber parts. Issued 7/20/79.	NW	27241	Maynord C. Crosby c/o Ken Blackman Bldg. C-52-1, Paine Field Everett, WA 98204
AA-1; T.C. A11EA	SA1410SW	Mitchell automatic flight system AK301, consisting of Century I autopilot with optional omni tracker. Issued 12/28/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-1; T.C. A11EA	SA1716WE	Installation of exhaust gas temperature gauge (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
AA-1; T.C. A11EA	SA2104WE	Installation of Brittain Models B2C and BSS flight control systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
AA-1; T.C. A11EA	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1010CE	Installation of wing leading edge cuffs. Reissued May 1977.	CE	42560	Horton STOL-Craft Wellington Municipal Airport Wellington, KS 67152
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1313CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-1, AA-1A, AA-1B; T.C. A11EA	SA3234WE	Installation of Piper oil cooler and associated installation components. Issued 7/8/76.	WE	05390	Aircraft Maintenance Service 7950B Joe Crosson Drive Santee, CA 92071

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
AA-1, AA-1A, AA-1B; T.C. A11EA	SA4106SW	Increase gross weight to 1560 lbs. for AA-1, 1560 lbs. for AA-1A, and 1600 lbs. for AA-1B. Issued 3/26/80.	SW	24100	James E. Collier Route 4, Box 810 Jefferson, TX 75657
AA-1, AA-1A, AA-1B, AA-1C; T.C. A11EA	SA991NW	Engine mount, cowling, carburetor air on Lycoming O-235-L2C (modified by STC SE792NW) and Sensenich 72CK-S12-0-57 propeller. Issued 7/17/80.	NW	16851	Kennis G. Blackman 7305 97th Avenue, S.E. Snohomish, WA 98290
AA-1, AA-1A, AA-1B, AA-1C; T.C. A11EA	SA1009NW	Grumman American AA-5A dorsal fin. Issued 8/21/80.	NW	16851	Kennis G. Blackman 7305 97th Avenue, S.E. Snohomish, WA 98210
AA-1 (1969 and on), AA-1A (1969 and on), AA-1B (1969 and on), AA-5 (1972, 1973 and 1974 only); T.C. A16EA	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
AA-1, AA-1A; AA-5; T.C. A11EA, A16EA	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408 (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
AA-1; AA-5; T.C. A11EA, A16EA	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
AA-1B; T.C. A11EA	SA10NW	Installation of VA-3 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-1B; T.C. A11EA	SA11NW	Installation of VA-2 fiberglass wheel fairings. Amended 9/4/73.	NW	82350	VAn's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-1C Utility Category; T.C. A11EA	SA3695WE	Installation of Lycoming 0-235-C2C engine and McCauley 1A105/SCM7154 propeller. No installation data required. Placards required with this installation: At the fuel filler caps - "80/87 MIN OCTANE AVGAS" Issued 7/7/78	WE	03105	Aero-Training, Inc. 89 John Glenn Drive Concord, CA 94520
AA-5; T.C. A11EA	SA66NW	Installation of VA-4 fiberglass wheel fairings. Issued 9/4/73.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
AA-5; T.C. A16EA	SA1472SW	Mitchell automatic flight system AK374 consisting of Century IIB autopilot with optional omni tracker. Issued 6/28/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5; T.C. A16EA	SA1486SW	Mitchell automatic flight system AK373 consisting of Century I autopilot with optional radio coupler. Issued 5/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5, -5A, -5B; T.C. A16EA	SA1314CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
AA-5B; T.C. A16EA	SA3031SW-D	Mitchell automatic flight system AK514 consisting of Century I autopilot with omni tracking system. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AA-5B; T.C. A16EA	SA3032SW-D	Mitchell automatic flight system AK515 consisting of Century IIB autopilot with optional radio coupler. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
AA-5B; T.C. A16EA	SA3301WE	Installation of Model EGT-1 exhaust gas temperature monitoring system. Issued 11/23/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
AA-5B; T.C. A16EA	SA3309WE	Modification of primary control system by addition of rudder-aileron interconnect and installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/27/77.	WE	12250	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
G-159; T.C. 1A17	SA1-399	Forward and aft attachment for HF antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-400	Bendix radar scanner attaching brakcets and electrical cable firewall plugs.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-401	Glide slope antenna mounting bracket.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-402	Installation of 37K-2 Marker Beacon Antenna. Amended 7/24/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-403	Fabrication of mounting blocks and installations of Lear sense antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-404	Fabrication and installation of adaptor for mounting Chance Vought seat 22-93597-B-2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-405	DL-1 loop assembly.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-406	Collins 37R-2 antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-407	AC Spark Plug Division FM telephone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-408	Radio equipment shelves.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-412	Bulkhead at station 193.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-413	Double-hinged door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-414	Bulkhead and door at station 232.5.	EA	23600	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-415	Bulkhead and door at station 485.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-417	Baggage compartment smoke detector system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-420	AC Spark Plug Division FM telephone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-421	Bendix LPA-70C loop antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-432	High frequency antenna. Amended 7/25/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-447	Bulkhead and door at station 251.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-448	Bulkheads at stations 183 and 239 and baggage shelf.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-159; T.C. 1A17	SA1-449	Bulkhead and door at station 493.	EA	12500	Atlantic Aviation Corporation P.O. Bos 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-450	Partial bulkhead at station 223.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-465	Bulkhead at station 232.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-466	Bulkhead at station 257.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-472	Installation of Atlantic Aviation Corporation's TSO-C39 seat model "Retractable Seat --G II." Amended 1/13/70.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-493	Telectro AT-134-A marker antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-494	Collins 013107800 transponder antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-495	Collins 537F-1 radar scanner.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA1-498	Automatic flight control systems.	CE	24250	Collins Radio Company 855 35 Street, N.E. Cedar Rapids, IA 52401
G-159; T.C. 1A17	SA1-505	Two internally-mounted Aerojet-General 15KS-1000 A1 aircraft rocket engines in rear wing fillet.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361
G-159; T.C. 1A17	SA4-931	Avionics racks.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-932	Jump seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-942	Cabin oxygen supply system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa MOnica, CA 90405
G-159; T.C. 1A17	SA4-968	Divan.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-969	Swivel seat, fuselage station 133.	WE	45500	Jay-Dee Aircraft Supply Co., Inc 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-972	L-102B autopilot.	WE	49858	Lear, Inc. 3171 S. Bundy Drive Santa Monica, CA 90406
G-159; T.C. 1A17	SA4-976	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-991	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service C 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1000	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service C 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1015	Interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1048	Avionics racks to fuselage station 193.	WE	45500	Jay-Dee Aircraft Supply Co., 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1049	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-159; T.C. 1A17	SA4-1051	Oxygen breathing system applicable to altitude up to 30,000 feet.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1057	Anti-collision light.	GL	12488	Atkins Light Corporation 7636 Lyndale Avenue, South Minneapolis, MN 55401
G-159; T.C. 1A17	SA4-1058	Interior and equipment.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1068	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1087	Cabin interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1098	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1115	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1123	Interior furnishings.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1125	Interior modification including radio, instruments, and electronics.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1168	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1267	Cabin interior furnishings and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1293	General Electric 20M63C8 generator.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1320	Interior modification including passenger oxygen system and baggage compartment smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1379	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1381	Interior modification.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1445	Modification to Bendix DRA-12 doppler radar.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
G-159; T.C. 1A17	SA4-1481	Cabin interior furnishings and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1497	Ten-passenger interior arrangement, system, and aft baggage compartment smoke detector.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA4-1580	Auxiliary power unit modification (GTCP 85-91C and/or GTC 85-291C installation). Amended 6/2/66.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1581	Interior modification including three swivel seats for authorized crew members only.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA4-1582	Third crew member seat.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA11EA	Fabrication and installation of baggage compartment storage shelves.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-159; T.C. 1A17	SA12EA	Bulkhead and door at station 251.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA16EA	Fabrication and installation of an Avionics bracket under the floor.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA16GL	Incorporating AMF (Leland) inverters MGE 23-3 or MGE 23-400. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
G-159; T.C. 1A17	SA56WE	Interior and distance measuring equipment system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA60EA	Collins 237Z-1 antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA66EA	Fabrication and installation of a two-place seat.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA72WE	Interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA81EA	Fabrication and installation of bracketry for mounting a Collins 537F-8 radar scanner.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA88EA	Installation of a bulkhead and door at station 392.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA96EA	Wilcox electric transponder antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA98EA	Antenna masts.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA101EA	Skyphone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA106EA	Bulkhead and door at station 244.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA110WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA122EA	Atkins anti-collision light system control wiring changes, per STC SA4-1057.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA122CE	Install Hoskins supplementary light system consisting of Model A wing tip lights, or Model C or 2 tail light optionally, two of Model fuselage lights with M-3 or M-5 power supply. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
G-159; T.C. 1A17	SA131EA	Modification of extraction section of Vickers-Armstrongs, Ltd. engine mount attachment pin, 60216.	EA	52064	Robert Long and Ray Williams 49 Champ Avenue Pearl River, NY 10965
G-159; T.C. 1A17	SA138EA	Collins 137A-4 ADF fixed loop antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA141WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA147EA	Bulkhead and door at Station 487 and fore and aft bulkhead at Station 525.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA148EA	Bulkhead and door at Station 232.5 to Station 242.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA150WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-159; T.C. 1A17	SA156EA	Kollsman 1708-01 sextant mount in ditching hatch.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA168EA	Bulkhead and door at fuselage Station 192.375. Amended 3/17/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA174GL	Modification of floor support between stations 228.5 and 353 to eliminate decrease in allowable floor loading with increased zero fuel weight. Issued 5/12/77.	GL	90135	Zantop Airways, Inc. Detroit Metro Airport Detroit, MI 48242
G-159; T.C. 1A17	SA187EA	Bulkhead and door.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA203EA	Two place seating capacity in cabin.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA218EA	Bulkhead and door at Station 232.5 - 226.5.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA267EA	Bulkhead and door at Station 487. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA282EA	Under-the-floor rework between fuselage stations 416 and 525 for divan installation.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA288EA	Executive interior and communication/navigation equipment.	EA	78510	Timmins Aviation, Ltd. Montreal International Airport Dorval, P.Q., Canada
G-159; T.C. 1A17	SA296WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA297GL	Installation of single Canadian Marconi CMA-734 Omega/VLF navigation system. Amended 6/30/80.	GL	18753	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
G-159; T.C. 1A17	SA302WE	Incorporation of Napier Spraymat de-icing (as manufactured by applicant) externally on Rotol propeller spinner as an alternate to Dowty Rotol internal elements. Reissued 10/22/70.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
G-159; T.C. 1A17	SA314EA	Door in bulkhead at Station 525.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA315EA	Bulkhead and door at Station 232.5 - 226.5. Amended 3/17/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA340EA	3051 replacement radome. Reissued 4/12/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
G-159; T.C. 1A17	SA352WE	Interior.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA370EA	Main landing gear nutcracker microswitch assembly relocated.	EA	86200	George R. Williams 49 Champ Avenue Pearl River, NY 10965
G-159; T.C. 1A17	SA373EA	Two three-place couches and oxygen provisions.	EA	03100	Aero Trades, Inc. Long Island Airport Ronkonkoma, NY 11779
G-159; T.C. 1A17	SA376GL	Reduction of maximum zero fuel gross weight. Issued 11/26/79.	GL	91034	Zantop Airways, Inc. Detroit Metro Airport Detroit, MI 48242
G-159; T.C. 1A17	SA389WE	11-passenger interior and equipment installation including dual Collins DF-203 ADF receivers and dual Collins MC-102 gyrosyn compasses.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-159; T.C. 1A17	SA394SW	HF-G overspeed warning system.	SW	40000	The Hamilton Company 106 Neuhaus Street Houston, TX 77002
G-159; T.C. 1A17	SA399WE	Maximum allowable airspeed indicator.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA406SW	Engine breather drain extension with fairing.	SW	11604	Arco Sheet Metal Company 8346 Lockheed Houston, TX 77002
G-159; T.C. 1A17	SA427SW	To install brackets for the installation of 2 each ADF loops, 1 each marker antenna, 4 each cabin speakers, 2 each cockpit speakers, and to install 4 each ADF sense antenna mounting brackets. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91502
G-159; T.C. 1A17	SA435SW	To fabricate wiring harness and make complete radio, radar installation. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-159; T.C. 1A17	SA437SW	Fabrication and installation of radio rack. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-159; T.C. 1A17	SA448WE	Interior.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA486WE	11-passenger interior and equipment installation including Collins flight director system (dual), radio magnetic indicator switching, plus DME and ATC transponder systems.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	ST512SO	Installation of cargo door and nets. Reissued 9/20/74.	EA	18750	Butler Aviation Baltimore/Washington Int'l Airport Baltimore, MD 21240
G-159; T.C. 1A17	SA541EA	Installation of new nose section, new nose gear, cabin interior and AiResearch GTC Model No. 85-134.	EA	39540	Grumman Aircraft Engineering Corp. Bethpage, L.I., NY 11714
G-159; T.C. 1A17	SA571SW	Collins radio altimeter system.	SW	12250	Associated Radio Service P.O. Box 20718 Dallas, TX 75221
G-159; T.C. 1A17	SA577EA	Installation of a 3-position fuel filter heat valve and control system for each engine.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA623WE	Eighteen-occupant interior with Atlantic Aviation jump seat for an additional crew member.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA636EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA637EA	Installation of Collins 621A-3 transponder.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA638EA	Installation of Collins 860E-2 DME.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA664EA	Installation of Sperry C-11B Gyro Compass System.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA665EA	Installation of Bendix DMA-29A DME System.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA666EA	Installation of Bendix TRA-61A transponder system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA667EA	Installation of Bendix MKA-28C marker beacon receiver.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-159; T.C. 1A17	SA668EA	Installation of Frieden Type B-5 Driftmeter.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-159; T.C. 1A17	SA723WE	12-passenger interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA730WE	12-passenger interior arrangement.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA735WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-159; T.C. 1A17	SA761WE	13-passenger interior arrangement.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	ST762SO	Installation of main cabin floor support structure. Issued 8/19/77.	GL	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST763SO	Installation of courier seat and cockpit/main cabin partition. Issued 8/19/77.	GL	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	ST764SO	Enlarged passageway in FS525 main cabin bulkhead. Issued 8/19/77.	GL	90135	Zantop Airways, Inc. Detroit Willow Run Airport Detroit, MI 48242
G-159; T.C. 1A17	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
G-159; T.C. 1A17	SA807SW	FD108/AP103E/F Flight Director-Autopilot combination for Category II operation.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA838WE	Shelf and webbing in baggage compartment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA839WE	Lavatory external service pen.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA879WE	Two radar altimeter antennas.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA886WE	Honeywell aircraft recognition light system.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA888EA	Installation of Grimes three light strobe kit 34-0303-1 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
G-159; T.C. 1A17	ST889SO	Installation of Collins ground proximity warning system. Issued 3/16/76.	SO	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-159; T.C. 1A17	SA893SW	Dual FD-109 Flight Director/AP-104 Autopilot, 58W-1C Comparator Warning, AL-101 Radio Altimeter, MC-102 Compass, 51RV-1, VOR/ILS, 51Z-4 Marker, 860E-2 DME and DF-203 ADF systems.	SW	24252	Collins Radio Company Avionics System Center P.O. Box 98 Addison, TX 75001
G-159; T.C. 1A17	SA998CE	Installation of battery temperature monitor and over temperature warning system.	CE	05250	Aircraft Instrument and and Development, Inc. 317 E. Lewis Wichita, KS 67202
G-159; T.C. 1A17	ST999SO	Installation of Bendix ground proximity warning system. Issued 6/24/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-159; T.C. 1A17	SA1034EA	Installation of Safeway de-icer overshoes P/N 5651 and/or Semsa leads P/N S.2002 on Dowty Rotol propeller model R184/4-30-4/50 with Blades P/N R.A25907. Issued 3/22/76.	EA	70830	Semsa, Incorporated 2125 Smithtown Avenue Ronkonkoma, NY 11779
G-159; T.C. 1A17	SA1050SO	Replace existing nickel cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 3/6/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-159; T.C. 1A17	SA1098WE	EGT and r.p.m. indicator for APU, Model GTC 85-37.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1137EA	Installation of the Global GNS-500A Omega navigation system. Amended 6/13/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-159; T.C. 1A17	SA1204EA	Installation of Solar T-62T-40C2 APU. Issued 8/8/80.	EA	73275	PATS, Inc. 7190-8 Oakland Mills Road Colubmia, MD 21046
G-159; T.C. 1A17	SA1284WE	Kollsman MS28011-2 sextant.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1318WE	Lear Siegler, Inc. 510K autopilot system.	WE	07500	AiReserach Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1341CE	Installation of Collins Radio Group FPS-80 flight control system including electric trim. Amended 5/16/80.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, NE Cedar Rapids, IA 52406
G-159; T.C. 1A17	SA1536SW	Foxtronics TRAMM BTI-600 nickel-cadmium battery temperature system. Issued 11/10/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
G-159; T.C. 1A17	SA1559SW	Semi-automatic fuel trim system. Issued 12/4/72.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159; T.C. 1A17	SA1678SW	Modification of Burns BH 1600 (P/N 908-2-1 and -2) double seats. Issued 6/20/73.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1709SW	Oxygen service installation. Issued 7/31/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-159; T.C. 1A17	SA1745SW	AMS-70A Area Navigation System. Issued 2/21/74.	SW	24252	Collins Radio Company 1200 N. Alma Road Richardson, TX 75207
G-159; T.C. 1A17	SA1763SW	Modification to Burns BH1600 double seats to aft facing. Issued 11/14/73.	SW	84600	Ward Int'l Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
G-159; T.C. 1A17	SA1964WE	Installation of jump seat.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-159; T.C. 1A17	SA1955SW	Installation of Collins AP-105 autopilot for Category I operation. Amended 5/5/80.	CE	24250	Collins Avionics Division Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
G-159; T.C. 1A17	SA2629WE	Installation of single point refueling system. Issued 1/8/73.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-159; T.C. 1A17	SA3044WE	Installation of fuel tank inter-connect system. Issued 7/9/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
G-159; T.C. 1A17	SA3641WE	Installation of DeVore Aviation Corp. horizontal stabilizer mounted vertical tail flood lights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
G-159, G-1159; T.C. 1A17, A12EA	SA10NE	Installation of a "back-up" passenger seat restraing system. Amended 3/30/78.	NE	69850	S.A.G.E. Corporation Burlington Int'l Airport Burlington, VT 05401
G-159, G-1159; T.C. 1A17, A12EA	SA1082SW	Revise nose gear steering cockpit control by installing BKM Guide-master.	SW	16850	The BKM Company P.O. Box 7703 Dallas, TX 75209
G-159, G-1159; T.C. 1A17, A12EA	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	F S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
G-1159; T.C. A12EA	SA23NE	Installation of aluminum grating on cargo door at fuselage station 539.75. Issued 3/27/78.	NE	69850	S.A.G.E. Corporation Burlington International Airport Burlington, VT 05401
G-1159; T.C. A12EA	ST222GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA272GL	Installation of Intercontinental Dynamics Corp. engine vertical scale instruments. Amended 12/5/78.	EA	44160	Intercontinental Dynamics Corp. 170 Coolidge Avenue Box 81 Englewood, NJ 07631
G-1159; T.C. A12EA	ST566SO	Installation of Bendix RNS-3400 area navigation system. Amended 5/23/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA579EA	Installation of a custom interior.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA606EA	Installation of shelf and bracketry at fuselage station 743.0 - 769.62, replace metal skins with fiberglass between fuselage station 813.31 and 855.00 and bracketry provisions between fuselage station 812.50 and 826.50.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA607EA	Manufacturing and installation of partition and door blow out provisions. Amended 12/29/69.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA608EA	Installation of dual Sperry SPI-73E flight director.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA618EA	Installation of Atlantic Aviation Corporation's TSO'd retractable seat, Type G11. Amended 6/17/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA623EA	Installation of bulkhead door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA624EA	Installation of bulkhead and bulkhead door at fuselage station 194.25.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA625EA	Installation of bulkhead and bulkhead door at fuselage station 503.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA626EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. Reissued 6/3/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA627EA	Installation of Collins 54W-1 comparator warning system. Amended 12/19/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA628EA	Installation of Collins AL-101 radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA629EA	Installation of Bendix RDR-1E weather radar system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA630EA	Installation of Sperry C-11B gyro compass system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA631EA	Installation of dual Collins F.D. 109G flight director systems.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA632EA	Installation of Pyrotector smoke detector system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA633EA	Installation of constant flow passenger oxygen system. Amended 12/5/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA645EA	Installation of structural provisions for the Collins doppler DH-101.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA649EA	Installation of Litton LTN-51 inertial navigation system. Amended 12/11/68.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA654EA	Installation of Honeywell hi-intensity recognition lights. Reissued 11/12/68.	GL	42250	Honeywell, Inc. 2600 Ridgway Road Minneapolis, MN 55413
G-1159; T.C. A12EA	SA655EA	Installation of Collins flight directors.	EA	07498	AiResearch Aviation Company Long Island MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779
G-1159; T.C. A12EA	SA657EA	Installation of Sperry comparator warning unit.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA658EA	Installation of Sperry altitude preselect system. Amended 12/31/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA659EA	Installation of Bendix ALA-51A radio altimeter system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE19899
G-1159; T.C. A12EA	SA660EA	Installation of dual Sperry SPI-73E flight director system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA662EA	Installation of an Air-Lavatory Drain. Amended 12/11/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA663EA	Installation of EDO Loran System. Amended 1/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA669EA	Installation of bulkhead and bulkhead door at fuselage station 201.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA670EA	Installation of bulkheads at fuselage stations 467.5, 485.0 and 515.25; bulkhead doors at fuselage stations 485.0 and 515.25; and longitudinal bulkhead at buttline 4 between fuselage stations 467.5 and 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA680EA	Installation of conference table.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA681EA	Installation of bulkhead and bulkhead door at fuselage station 255.0.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA682EA	Installation of bulkhead and bulkhead door at fuselage station 495.0. Amended 9/10/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA683EA	Installation of sliding door at fuselage station 539.75.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA684EA	Installation of intercostals between fuselage station 244-1/2 to fuselage station 257-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA685EA	Installation of intercostals between fuselage station 487 to fuselage station 498. Amended 10/22/68.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA688EA	Installation of Collins FD-109H and FD-109F flight director system. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA689EA	Installation of IDC 17000-22 Air Data Computer. Amended 1/28/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA691EA	Installation of a dual Collins DF-203 ADF.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA692EA	Installation of intercostals between fuselage station 193 to fuselage station 206.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA693EA	Installation of bulkhead and bulkhead door at fuselage station 495 5/8.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA694EA	Installation of bulkhead and bulkhead door at fuselage station 200.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA699EA	Installation of intercostals between fuselage station 345 7/8 to fuselage station 355 1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA701EA	Installation of Hartman Systems Company vertical scale engine instruments. Reissued 11/29/68.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746
G-1159; T.C. A12EA	SA702EA	Installation of intercostals between fuselage station 452 1/2 to fuselage station 466.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA706EA	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system. Amended 9/3/80.	SO	15475	Bendix Corporation Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA718EA	Installation of intercostals between fuselage station 498 to fuselage station 512.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA721EA	Installation of swivel seat installation, fuselage stations 287 1/2 to fuselage station 379.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA722EA	Installation of Safe Flight SCAT/ Autopower System. Amended 1/7/75.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
G-1159; T.C. A12EA	SA723EA	Installation of intercostals between fuselage station 43-1/2 and fuselage station 452-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA724EA	Installation of vertical scale full quantity indicators Model VS-2PE (639-) as replacement for original round dial indicators.	EA	40750	Hartman Systems Company 360 Wolf Hill Road Huntington Station, NY 11746
G-1159; T.C. A12EA	SA726EA	Installation of seat track reinforcement conference table grouping.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA733EA	installation of intercostals between fuselage station 297 to fuselage station 306-1/2.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA734EA	Long range under floor oxygen cylinder installation. Amended 7/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA735EA	Installation of divan base aft support/attachment at fuselage station 460-1/4.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA748EA	Installation of skyphone antenna.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA749EA	Installation of combined divan-bunk on right hand side of aircraft between fuselage station 183 and fuselage station 255. Issued 4/15/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA750EA	Installation of seat track extension. Issued 4/16/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA758EA	Installation of partial bulkhead and door at fuselage station 182. Amended 11/19/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA759EA	Installation of bulkhead attachment. Amended 8/22/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA760EA	Installation of bulkhead and bulkhead door at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA761EA	Installation of bulkhead at fuselage station 448. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA763EA	Installation of Litton LTN-51 inertial navigation system.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA777EA	Installation of bulkhead at fuselage station 499. Amended 9/4/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA778EA	Installation of bulkhead at fuselage station 459.5. Amended 8/25/69.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA779EA	Installation of Custom Products Model 400-21 three place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA783EA	Installation of Electronic Resources Skyphone (UHF) antenna 10-222-04880.	EA	12500	Atlantic Aviation Corporation Wilmington, DE 19899
G-1159; T.C. A12EA	SA789EA	Installation of two-place divan.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA790EA	Installation of bulkhead and door at fuselage station 507.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA806EA	Installation of Atlantic Aviation Corporation's retractable seat-GII and refreshment cabinet.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	ST874SO	Installation of Collins ground proximity warning system. Issued 12/15/75.	SO	24262	Collins Radio Group Rockwell International Suite 1 1591 Phoenix Boulevard Atlanta, GA 30349
G-1159; T.C. A12EA	ST888SO	Installation of Litton "Digiprox" ground proximity warning system. Issued 3/9/76.	SO	51502	Litton Systems, Inc. 6065 Roswell Road N.E. Suite 305B Atlanta, GA 30328
G-1159; T.C. A12EA	SA937SW	Crew jump seat.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA940SW	Micronair AU-3000 spray units.	EA	39540	Grumman Aircraft Engineering P.O. Box 147 Elmira, NY 14901
G-1159; T.C. A12EA	SA941SW	Collins HF communication system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA942SW	Collins AL-101 radio altimeter.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA943SW	Dual Sperry SPI-73 integrated flight system, Sperry instrumentation, comparator monitor and dual Sperry C11B compass system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA945SW	Litton LTN51 inertial navigation system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA946SW	Update Sperry 2587400-274 air data computer.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA948SW	Increase of DC output capabilities for APU TR unit.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA951SW	Passenger oxygen system and supplemental (long range) oxygen supply.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA957EA	Installation of modular berthable 1 or 2 place side-facing seat. Issued 7/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA970EA	Installation of Fairchild cockpit voice recorder Model A100 and A151 control unit. Issued 11/26/73.	EA	07498	AiResearch Aviation Company Islip MacArthur Airport 2221 Smithtown Avenue Ronkonkoma, NY 11779

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA996EA	Installation of Shaw Aero fuel filler cap P/Ns 457-2, -266, -370, 431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
G-1159; T.C. A12EA	ST998SO	Installation of Bendix ground proximity warning system. Amended 8/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA1036SW	Bendix ALA-51A radio altimeter.	SW	12259	Associated RAdio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA1037SW	Emergency lights and battery.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1060EA	Installation of a single or dual Delco Electronics Carousel IV-A inertial navigation system with computer program, P/N 7881711-006. Reissued and amended 6/16/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1061EA	Installation of a dual Collins ALT-55B radio altimeter system. Amended 12/23/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA1062EA	Installation of a Sperry air data computer, Intercontinental Dynamics Co. (IDC) servo altimeters and mach. Amended 12/28/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. A12EA	SA1063EA	Installation of a dual Collins flight director system, Model FD-109Y. Amended 1/23/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
G-1159; T.C. 4/30/79	SA1068SC	Installation of Intercontinental Dynamics Corp. radio/barometric altimeter with voice terrain advisory and Sperry mini air data computer. Issued 4/30/79.	SO	39725	Gulfstream American Corporation P.O. Box 2206 Savannah, GA 31402
G-1159; T.C. A12EA	SA1070EA	Installation of dual Litton LTN-72R navigation system. Reissued and amended 4/24/78.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1093SW	Decca loran system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1139EA	Installation of a dual or single Global GNS-500A VLF/Omega navigation system. Amended 10/10/79.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1157EA	Replacement of Garrett AiResearch GTCP-36-6 APU with Solar T-62T-40C2 APU. Amended 10/5/79.	EA	73275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
G-1159; T.C. A12EA	SA1186EA	Installation of an Eldec Corp. digital fuel flowmeter and totalizer system. Issued 2/22/80.	EA	10135	Amerada Hess Corporation Mercer County Airport P.O. Box 7385 West Trenton, NJ 08628
G-1159; T.C. A12EA	SA1187EA	Installation of a single Litton LTN-211 Omega/VLF navigation system. Issued 3/17/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1193SC	Installation of Global GNS-500A Omega navigation system. Issued 12/16/80.	SO	39725	Gulfstream American Corp. P.O. Box 2206 Savannah, GA 31402
G-1159; T.C. A12EA	SA1197EA	Installation of a single Litton LTN-72 inertial navigation system. Issued 5/30/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
G-1159; T.C. A12EA	SA1250SW	Decca type 72 doppler radar system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1251SW	Decca omni-trac system. Issued 11/10/69.	EA	44900	ITT Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
G-1159; T.C. A12EA	SA1336SW	Installation of pressure refueling control system. Issued 7/8/71.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA1423SW	Electrical wiring feed thru Station 580. Issued 1/24/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1447SW	Battery fault warning system. Issued 9/18/72.	SW	12240	Associated Radio of San Antonio P.O. Box 16218 San Antonio, TX 78246
G-1159; T.C. A12EA	SA1480SW	Installation of FD-109F flight director, INS-61B inertial navigation system, Bendix ALA-51 radio altimeter. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
G-1159; T.C. A12EA	SA1481SW	Installation of cockpit control for center point refueling system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourne Avenue Burbank, CA 91505
G-1159; T.C. A12EA	SA1496SW	Tramm BTI-600 battery temperature indicating system. Issued 7/31/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA1553SW	Dual Collins INS-61B inertial navigation units. Issued 11/15/72.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
G-1159; T.C. A12EA	SA1613SW	BKM master warning interface device between master warning control panel and aircraft inputs. Issued 3/1/73.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA1697SW	Avionics cooling fan. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1698SW	Oxygen service installation. Issued 6/29/73.	SW	08225	AIRMODA, Inc. P.O. Box 35033 Dallas, TX 75235
G-1159; T.C. A12EA	SA1633WE	Installation of jump seat in cockpit.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1634WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1654WE	Installation of passenger oxygen continuous flow system.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1683WE	Installation of passenger oxygen system.	WE	07500	AiResearch Aviation Company 6021 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1756WE	Installation of an aircraft integrated weight and balance system (STAN).	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1757WE	Installation of United Control flight data recorder.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1769WE	Installation of Sonotone Battery Model No. 989074-1 and battery container.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA1771WE	Installation of SDI Hoskins anti-collision light system. Amended 11/28/73.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Street Orange, CA 92667
G-1159; T.C. A12EA	SA1772WE	Installation of United Control speed command system. Amended 6/19/70.	NW	80685	United Control Corporation Overlake Industrial Park Redmond, WA 98052
G-1159; T.C. A12EA	SA1800WE	Installation of radio rack and placards only for avionic components between fuselage stations 181-193 RH.	WE	63750	Qualitron Aero, Inc. Lockheed Air Terminal 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1814WE	Rain repellent system installation. Amended 10/25/73.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
G-1159; T.C. A12EA	SA1817WE	Installation of Sperry ATS-500 autothrottle system.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502
G-1159; T.C. A12EA	SA1819WE	Installation of doppler antenna and mount for doppler receiver and transmitter.	WE	63750	Qualitron Aero, Inc. 2777 Hollywood Way Burbank, CA 91502

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA1848WE	Installation of Custom Products Model 1875 jump seat on radio rack.	WE	62105	Pacific General Corporation 3210A Winona Burbank, CA 91502
G-1159; T.C. A12EA	SA1868WE	Installation of Bendix DRA-12 and CPA-24 doppler radar and navigation system.	SO	15475	Bendix Avionics Division 2100 N.W. 62nd Street Fort Lauderdale, FL 33310
G-1159; T.C. A12EA	SA1889WE	Installation of Sperry SP-50G automatic flight control system, Sperry SPI-73E integrated instrument system and Sperry ATS-500 automatic throttle system.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation P.O. Box 2529 Phoenix, AZ 85027
G-1159; T.C. A12EA	SA1898WE	Installation of Litton Model LTN-51 inertial navigation system. Amended 7/9/69.	WE	51500	Litton Systems, Inc. Guidance & Control Systems Division 5500 Canoga Avenue Woodland Hills, CA 91364
G-1159; T.C. A12EA	SA1983WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2016WE	Installation of external lavatory service.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2165WE	Installation of altitude preselect and alerting system (SP-50G Altitude Preselect System). Issued 7/8/70.	WE	74570	Sperry Flight Systems Division Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
G-1159; T.C. A12EA	SA2184WE	Installation of dual AC Carousel IV inertial navigation system. Amended 10/23/79.	GL	37810	General Motors Corporation A.C. Electronics Division Milwaukee, WI 53201
G-1159; T.C. A12EA	SA2234SW	Passenger continuous flow oxygen system. Issued 8/15/75.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2235SW	Dual Collins 61B inertial systems. Issued 8/15/75.	SW	12250	Associated Radio Service Company P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2237SW	BKM specific range computer. Issued 8/26/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2270SW	Manufacture and install a divan. Issued 11/7/75.	SW	11890	Associated Air Center Box 20718 - Love Field Dallas, TX 75220
G-1159; T.C. A12EA	SA2277SW	Continuous flow, low pressure oxygen system. Issued 12/10/75.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2366SW	Lighted speed brake handle. Issued 10/6/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2387SW	Dual Litton LTN-72R area navigation system. Issued 11/27/76.	SW	11890	Associated Air Center Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA2407SW	Install HF antenna on tail cone. Issued 2/11/77.	SW	36600	Foxtronics, Inc. P.O. Box 7031 Dallas, TX 75209
G-1159; T.C. A12EA	SA2430WE	Installation of dual Collins INS-61B inertial navigation system. Reissued 11/29/71.	CE	24250	Collins Radio Company 855 35th Street Cedar Rapids, IA 52406
G-1159; T.C. A12EA	SA2512WE	Relocation of speed-logic control unit of GTCP36-6 turbine auxiliary power unit and mounting provisions for spare speed-logic unit. Issued 5/12/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2592WE	Installation of auxiliary taxi light system. Issued 9/1/72.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2593WE	Installation of Dorne and Margolin DMN 4-15 antenna (VOR/localizer) is installed in vertical stabilizer. Amended 11/9/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2757WE	Installation of crew oxygen regulator and mask assemblies. Issued 9/7/73.	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
G-1159; T.C. A12EA	SA2797WE	Installation of wing tip mounted emblem lights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
G-1159; T.C. A12EA	SA2807WE	Installation of dual GAMMA I (SKN-2610) inertial navigation systems. Amended 6/28/74.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2907SW	Pitot head indicating system. Issued 1/30/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
G-1159; T.C. A12EA	SA2965WE	Installation of dual GAMMA I inertial navigation systems. Issued 1/16/75.	WE	71838	The Singer Company Kearfott Division 5730 W. Manchester Avenue Los Angeles, CA 90045
G-1159; T.C. A12EA	SA2995SW	Global GNS-500A VLF Omega navigation system. Issued 5/10/79.	SW	11890	Associated Air Center P.O. Box 20718 Dallas, TX 75220
G-1159; T.C. A12EA	SA3089WE	Installation of 104006 computer program in LTN-104 ANS. Issued 10/1/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
G-1159; T.C. A12EA	SA3223WE	Installation of Garrett AirNAV 100 or 200 or 300 area navigation system. Amended 8/29/80.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3288WE	Installation of Canadian Marconi vertical scale engine instruments. Issued 10/22/76.	WE	30000	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3302WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 9/17/76.	WE	51500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3370WE	Installation of dual ONTRAC III VLF/OMEGA navigation system. Issued 12/1/77.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3399WE	Installation of a single or dual Litton LTN-72R INS/RNAV navigation system. Amended 7/11/79.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3600WE	Installation of a single or a dual Delco C-IVA inertial navigation systems. Amended 1/30/80.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
G-1159; T.C. A12EA	SA3629WE	Installation of either single LTN-51 or LTN-72. Issued 4/14/78.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
G-1159; T.C. A12EA	SA3635WE	Installation of IPECO pilot and co-pilot crew seats. Amended 6/26/79.	WE	54860	Marcon Associates, Inc. 18436 Hawthorne Blvd. Suite 212 Torrance, CA 90504
G-1159; T.C. A12EA	SA3636WE	Installation of single Delco Carousel IVA inertial navigation system. Issued 6/22/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
G-1159; T.C. A12EA	SA3691WE	Installation of Devore Aviation wing tip tank tail cone mounted vertical tail floodlights. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
G-1159; T.C. A12EA	SA3973WE	Installation of equipment racks for the mounting of a radar system. Issued 6/15/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
G-1159; T.C. A12EA	SA4142SW	Door seal pressure gage, P/N 791026-1. Issued 6/16/80.	SW	08225	AirModa, Inc. P.O. Box 29034 Dallas, TX 75229
G-1159; T.C. A12EA	SA4166WE	Installation of oxygen system for passengers and third crew member. Issued 6/12/80.	WE	78490	Tiger Air Service Center 3000 North Clybourn Avenue Burbank, CA 91505
GA-7; T.C. A17SO	SA1425CE	Install King KFC-200 automatic flight control system. Issued 7/14/78.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
GA-7; T.C. A17SO	SA3235SW-D	Mitchell automatic flight system AK634 consisting of Century IV autopilot or AK634FD consisting of Century IV flight director autopilot with remote annunciator. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3236SW-D	Mitchell automatic flight system AK634 consisting of Century III autopilot with optional radio coupler and glide slope coupler. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
GA-7; T.C. A17SO	SA3238SW-D	Mitchell command electric trim AK637. Issued 10/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
HELIO AIRCRAFT, LTD.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H-250; T.C. 1A8	SA846EA	Installation of PeeKay Model 3500A amphibious floats. Issued 10/12/70.	EA	63626	PeeKay Aircraft Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
H-250; T.C. 1A8	SA867EA	Installation of Aerofab TSO C27 PeeKay Model B3500. Issued 3/19/71.	EA	29998	PeeKay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
H-250, H-295; T.C. 1A8	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
H-250, H-295; T.C. 1A8	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
H-250, H-295, H-391, H-391B, H-395, H-395B; T.C. 1A8	SA547SW	AK177 automatic pilot, AK123 lateral guidance radio coupler, and AK178 automatic trim.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-391, H-395; T.C. 1A8	SA354SO	Aft cabin door removed.	SO	27245	Vernon L. Crouch 2564 Alandale Drive Macon, GA 31201
H-250, H-295, H-391, H-395; T.C. 1A8	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
H-250, H-295, H-391, H-395; T.C. 1A8	SA1087SO	Installation of Brownline seat. Issued 7/6/79.	SO	47390	Jungle Aviation and Radio Service, Inc. P.O. Box 248 Waxhaw, NC 28173
H-250, H-295, H-391, H-395, H-395A; T.C. 1A8	SA1112WE	Sling-type passenger seat.	NW	75600	Stolairco, Inc. 6660 Perimeter Road S. Boeing Field Seattle, WA 98108
H-250, H-295, H-391, H-395, H-395A; T.C. 1A8	SA1491WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
H-250, H-295, H-391, H-391B, H-395, H-395A; T.C. 1A8	SA1590CE	Modification of main spar carry-thru assembly. Issued 5/30/80.	CE	17120	Clarence H. Brent Box 486 Pittsburg, KS 66762
H250, H295, H391B, H395; T.C. 1A8	SA916SO	Installation of Cessna seat rails and seats. Issued 1/13/77.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H250, H295, H391B, H395; T.C. 1A8	SA917SO	Installation of cargo door.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA179AL	Installation of Airglas wheel skis. Amended 4/28/67.	NW	75600	Stolairco, Inc. 6660 Perimeter Road S. Boeing Field Seattle, WA 98108
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA218AL	Main gear shock strut restrictor.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H-250, H-295, H-391B, H-395, H-395A; T.C. 1A8	SA234AL	Installation of Goodyear 30 x 13 x 6 main gear tires. Revised 6/30/69.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H250, H295, H395; T.C. 1A8	SA2381SW	Modification of main landing gear assembly, P/N 250-040-451, by addition of gussets at intersection of drag brace and main leg. Issued 11/15/76.	SW	30230	Dodd Engineering & Welding 3302 North Lewis Tulsa, OK 74110
H-250, H-295, H-395; T.C. 1A8	SA3247SW-D	Mitchell automatic flight system AK618 consisting of Century IIB autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-395, H-395A; T.C. 1A8	SA3244SW-D	Mitchell automatic flight system AK614, consisting of Century III autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H250, H-295, H-395, H-395A; T.C. 1A8	SA3245SW-D	Mitchell automatic flight system AK615, consisting of Century IIB autopilot with optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-295, H-395, H-395A; T.C. 1A8	SA3246SW-D	Mitchell automatic flight system AK617 consisting of Century III autopilot with optional radio coupler. Issued 9/29/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H-250, H-391, H-395A, H-391B, 500; T.C. 1A8, A2EA	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
H-250, H-391, H-395A, H-391B, 500; T.C. 1A8, A2EA	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 10/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
H-250, H-395A, H-395B; T.C. 1A8	SA1389CE	Install tailwheel yoke assembly to accommodate a Cleveland 600 x 6 wheel and either 600 x 6, 700 x 6 or 800 x 6 tires. Issued 12/15/77.	AL	90130	William G. Zaegel P.O. Box 3464 Anchorage, AK 99501
H-295; T.C. 1A8	SA860SW	Mitchell automatic flight system AK256 consisting of Century III autopilot with optional automatic pitch trim, radio coupler, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76106
H-295; T.C. 1A8	SA1399SW	Installation of tricycle landing gear. Amended 5/17/78.	CE	42000	Helio Aircraft Limited Box 604 Pittsburg, KS 66762
Helio H-295; T.C. 1A8	SA1589CE	Modification to increase gross weight to 3800 lbs. Amended 2/5/81.	CE	17120	Clarence H. Brent Box 486 Pittsburg, KS 66762
H-295; T.C. 1A8	SA1601CE	Installation of TFC engine and cabin fire extinguisher system. Issued 10/23/80.	CE	78621	Total Flood Corporation 1409 Plaza Center Blue Springs, MO 64015

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H-295 (USAF U-10D); T.C. 1A8	SA2136WE	Installation of Tritan amphibious float Model TA 3500. Reissued 5/24/76.	NE	23370	T.M. Close Corporation Box 464 Gardner Municipal Airport Gardner, MA 01440
H295, H-391, H395; T.C. 1A8	SA987SO	Removal of the Leece-Neville generator and voltage regulator and installation of a JASCO alternator kit 6565-1. Amended 11/8/79.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H-295, H-391, H-395; T.C. 1A8	SA1086SO	Installation of stowable co-pilot's rudder pedals. Amended 8/30/79.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
H-295, -391B; T.C. 1A8	SA2666WE	Ceconite 102 material covering of ailerons. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
H-295, H-395; T.C. 1A8	SA900WE	Installation of turbosupercharged Lycoming GO-480-F2D6 engine. Amended 5/20/70.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
H-295, H-395; T.C. 1A8	SA1592WE	Installation of automatic fuel mixture control. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
HT-295; T.C. 1A8	SA35RM	Installation of Bendix FCS-810 autopilot, a trim adapter and Bendix HSD-830 compass. Amended 3/20/78.	RM	05940	Aircraft Radio & Accessory Company, Inc. Hangar No. 1 Stapleton Int'l Airport Denver, CO 80207
H-391, H-391B, H-395, H-395A; T.C. 1A8	SA284WE	B2D autopilot. Amended October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
H-391B; T.C. 1A8	SA709WE	Ceconite 101 covering of ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
H-391B; T.C. 1A8	SA731CE	Installation of Edo 582-3430 floats.	NE	47270	Frank Joy Cape Cod Aeromarine Box 398 Orleans, MA 02653
H-391B; T.C. 1A8	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
H-391B, H-395, H-395A; T.C. 1A8	SA235AL	Installation of modified oleo shock strut.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
H-391B, H-395A; T.C. 1A8	SA152AL	L J 2800 floats.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 1254 Anchorage, AK 99502
H-395; T.C. 1A8	SA125SO	Turbocharger GO-480-G1D6 engine.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
H-395; T.C. 1A8	SA156SO	Turbocharged Lycoming GO-480-G1D6 engine.	WE	66250	Rajay Corporation 2602 E. Wardlow Road Long Beach, CA 90807
H-395; T.C. 1A8	SA393CE	Lycoming GO-480-G1D6 engine and Hartzell HC-B3Z-20-1/101510-5 propeller.	CE	42000	Helio Aircraft Limited P.O. Box 604 Pittsburg, KS 66762
H-395; T.C. 1A8	SA490SW	Turbocharger. Reissued 4/6/76.	SW	09250	Alcor, Inc. 10130 Jones Maltsberger Road San Antonio, TX 78216
H-395; T.C. 1A8	SA1213CE	Installation of EDO 582-3430 floats. Issued May 1976.	AL	75095	Stephens Bros. Plumbing, Inc. 7339 Arctic Boulevard Anchorage, AK 99502
H-395; T.C. 1A8	SA1467CE	Increase in maximum gross weight from 3,000 lbs. to 3,300 lbs./ modification and kit installation instructions. Issued 12/28/78.	CE	17120	Clarence H. Brent P.O. Box 486 Pittsburg, KS 66762
H-395; T.C. 1A8	SA1696WE	Installation of engine mounts P/N VIP 50525-1 and VIP 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500; T.C. A2EA	SA104SO	Swearingen combustion monitor. Reissued 8/6/74.	SW	68150	Riley Turbostream Corporation P.O. Box 5247 Waco, TX 76708
500; T.C. A2EA	SA305SO	Lycoming IO-540-C2C engines, 315A10 Rajay turbochargers and modified fuel system. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
500; T.C. A2EA	SA459CE	Models C4200A and 1800 skis.	GL	36060	FluiDyne Engineering Corporation 5900 Olson Memorial Highway Minneapolis, MN 55422
500; T.C. A2EA	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
HST-550; T.C. A4EA	SA615SW	AK213 stabilizer and AK214 pitch trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
HST-550; T.C. A4EA	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by STC SA615SW.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
HILLER AVIATION

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH1-457	Aircooler Motors 6VS-335B turbo-supercharged engine (derated).	EA	19950	Carson Helicopters, Inc. RR-1, Box 94 Perkasie, PA 18944
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH4-178	Curved control stick.	WE	61772	Nystrom Aviation, Inc. 1901 Embarcadero Road Palo Alto, CA 94302
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH4-1071	Spray equipment kit.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH4-1101	Aerofilter 30690B with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH9AL	Airglas tundra pads L-100.	AL	44260	International Helicopters P.O. Box 6227, Annex Anchorage, AK 99500
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH32WE	Fabricate and install jump-step.	WE	80912	USDA, Forest Service Arcadia Equipment Development and Test Center 701 N. Santa Anita Avenue Arcadia, CA 91006
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH83WE	Installation of modified air induction system.	WE	23170	Wayne Clevenger 785 Monterey Road Salinas, CA 93901
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH52WE	High volume fifty foot spray boom kit.	NW	71770	Simplex Manufacturing Company 5224 NE 42nd Avenue Portland, OR 97218
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH77AL	Tundra snow shoes.	AL	33650	ERA Helicopters, Inc. P.O. Box 762 Anchorage, AK 99501
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH80WE	INstallation of Simplex thirty-two foot spray boom.	NW	71770	Simplex Manufacturing Company 5224 NE 42nd Avenue Portland, OR 97218
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH82WE	Installation of spray system and extended landing gear.	WE	23170	Wayne Clevenger 785 Monterey Road Salinas, CA 93901
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH160AL	Airborne control survey system.	EA	44049	U.S. Department of Interior Geological Survey Topographic Division Washington, D.C. 20000
UH-12 Series; T.C. 6H1, 6H2, 4H11, H1WE	SH446EA	Installation of Franklin engine Model 6V-350B in Fairchild Hiller UH-12A helicopter. Amended 6/30/70.	EA	36750	Franklin Engine Company, Inc. Liverpool Road Syracuse, NY 13208
UH-12, UH-12A, UH-12B, UH-12C, UH-12D, UH-12E; T.C. 6H1, 6H2, 4H10, 4H11	SH12CE	Installation of type AAF-102 AC filter. Amended 5/27/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
UH-12C; T.C. 6H2	SH141GL	Installation of Bell 47 canopy and one piece doors. Issued 11/8/76.	GL	74926	Stanley Tool & Die Company Route #1 Rock Falls, IL 61071
UH-12D; T.C. 4H10	SH177WE	Installation of Allison 250-C20 engine and related changes. Issued 4/10/75.	NW	73720	Soloy Conversions Limited 2209 E. 13th Street The Dalles, OR 97058
UH-12D; T.C. 4H10	SH247NW	Installation of ejector pump engine oil cooler system on turbine powered UH-12D. Issued 1/20/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SA287NW	Installation of landing gear float kit. Issued 4/23/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH295NW	Installation of two 20-gallon auxiliary fuel tanks. Issued 5/18/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
UH-12D; T.C. 4H10	SH297NW	Installation of cabin heater kit for turbine powered helicopters. Issued 5/19/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH299NW	Installation of Soloy cargo racks. Issued 5/18/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH321NW	Installation of Bendix fuel control and power governor system. Issued 7/9/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH338NW	Installation of Harrison transmission oil cooler. Issued 8/12/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH359GL	Installation of NI-CAD Model No. 12367 engine lubrication system scavenge filter. Issued 8/13/79.	GL	61546	NI-CAD, Inc. 24800 U.S. 20 South Bend, IN 46628
UH-12D; T.C. 4H10	SH380NW	Installation of automatic reignition kit on Allison 250-C20. Issued 1/11/77.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H10	SH475NW	Agricultural spray pump system utilizing Simplex STCs. Installation will be made on turbine modified helicopters. Issued 7/13/77.	NW	73721	Soloy Conversions P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H11	SH505NW	Installation of cargo hook release pedal. Issued 8/23/77.	NW	73721	Soloy Conversions Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D; T.C. 4H11	SH559NW	Installation of inlet particle separator system on Allison 250-C20 powered helicopter. Issued 1/18/78.	NW	73721	Soloy Conversions Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12D, UH-12E; T.C. 4H11	SH634NW	Installation of tundra pads. Issued 7/12/78.	NW	73721	Soloy Conversions P.O. Box 60 Chehalis, WA 98532
UH-12D, UH-12E; T.C. 4H10, 4H11	SH877SO	Installation of tail rotor guard assembly. Issued 2/2/76.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28677
UH-12D, UH-12E; T.C. 4H10, 4H11	SH1014NW	Simplex Model 4600 spray system - agricultural. Issued 8/25/80.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
UH-12E; T.C. 4H11	SH242GL	Installation of a General Electric 100 amp generator, P/N 2CM299H1,, and a distribution box. Issued 5/23/78.	GL	31570	East West Helicopter, Inc. 9005 Killey Road Harrison, OH 45030
UH-12E; T.C. 4H11	SH248NW	Installation of ejector pump engine oil cooler system on turbine powered UH-12E. Issued 1/20/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH288NW	Installation of landing gear float kit. Issued 4/23/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH296NW	Installation of auxiliary fuel tanks. Issued 5/18/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH298NW	Installation of cabin heater kit for turbine powered helicopters. Issued 5/19/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH300GL	Installation of NI-CAD, Inc. Model No. 12367 engine lubrication system scavenge filter. Amended 8/13/79.	GL	61546	NI-CAD, Inc. 24800 U.S. 20 South Bend, IN 46628
UH-12E; T.C. 4H11	SH300NW	Installation of Soloy cargo racks. Issued 5/18/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH322NW	Installation of Bendix fuel control and power governor system. Issued 7/9/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH339NW	Installation of Harrison transmission oil cooler. Issued 8/12/76.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
UH-12E; T.C. 4H11	SH381NW	Installation of automatic reignition kit on Allison 250-C20. Issued 1/11/77.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH476NW	Agricultural spray pump system utilizing Simplex STCs; installation will be made on turbine modified helicopters. Issued 7/13/77.	NW	73721	Soloy Conversions P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH506NW	Installation of cargo hook release pedal. Issued 8/23/77.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E; T.C. 4H11	SH560NW	Installation of inlet particle separator system on Allison 250-C20 powered helicopter. Issued 1/18/78.	NW	73721	Soloy Conversions, Ltd. P.O. Box 60 Chehalis, WA 98532
UH-12E Series; T.C. 4H11	SH717NW	Installation of Simplex Model 4500 spray system. Issued 2/20/79.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
UH-12E, UH-12E (4 place); T.C. 4H11	SH887NW	Simplex Model 4650 spray system - agricultural. Issued 2/21/80.	NW	71770	Simplex Manufacturing Company 5224 N.E. 42nd Avenue Portland, OR 97218
UH-12E (Restricted); T.C. 4H11	SH948NW	Installation of Model No. 5 automatic flagman. Issued 10/24/79.	NW	61619	North American Industries Route 4, City-County Airport Walla Walla, WA 99362
UH-12E; T.C. 4H11	SH951SO	Installation of removable center collective stick. Issued 8/17/77.	SO	47390	Jungle Aviation and Radio Service, Inc. Box 248 Waxhaw, NC 28173
UH-12E, -12E-1; T.C. 4H11	SH201WE	Installation of stirrup assemblies to directional control pedals for operation by handicapped pilot. Issued 4/14/77.	WE	28620	Barry C. Dallwig 113 East Elfin Green Port Hueneme, CA 93041
UH-12E, UH-12E-L, UH-12L, UH-12L4; T.C. 4H11, H1WE	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
UH-12E, -12E (4 place); T.C. 4H11	SH178WE	Installation of Allison 250-C20 engine and related changes. Amended 11/14/75.	NW	73720	Soloy Conversions Limited 2209 E. 13th Street The Dalles, OR 97058
UH-12E, -12E (4 place); T.C. 4H11	SH273NW	Installation of Simplex Model 3300 serial spray system. Issued 3/16/76.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
UH-12E, UH-12E-4; T.C. 4H11	SH539NW	Installation of weighing system. Issued 10/31/77.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
UH-12E, UH-12E-L; T.C. 4H11	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
UH-12E, -12E-4, -12SL3, -12SL4; T.C. 4H11	SH165NW	Installation of Model 1620 and 1621 aerial seeders systems. Issued 3/17/75.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
UH-12E, -12E-4, -12SL3, -12SL4; T.C. 4H11	SH215NW	Installation of Model 4400 aerial dust system. Issued 9/9/75.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
UH-12E, -12E-4, UH-12L, UH-12L4; UH-12E and -12E4 as modified by STC SH178NW; T.C. 4H11, H1WE	SA618NW	Installation of onboard weighing system adapter for use with Eastern Rotorcraft cargo hook No. 2A15E. Issued 6/15/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
269A, B, C; T.C. 4H12	SH152AWE	Installation of SKI/Hoskins Model 700801 anti-collision light system. Issued 8/18/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
269A, 269B, 269C; T.C. 4H12	SH157WE	Installation of fiberglass/aluminum baggage compartment. Issued 7/6/73.	WE	39300	Gould Engineering, Inc. Falcon Field Airport 4600 E. McKellips Road Mesa, AZ 85205
269A, 269B, 269C; T.C. 4H12	SH249WE	Installation of a searchlight kit. Issued 9/5/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4H12	SH258WE	Installation of MCT-10 mounting rack. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4H12	SH259WE	Installation of utility compartment. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269B; T.C. 4H12	SA123WE	Installation of E.O.S. 1 KW searchlight and Technical Engineering & Manufacturing Co., Inc. Model TA-30 alternator.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH128WE	Installation of Nightsun SX-10 searchlight Kit No. 019600 when: A TA-30 dual voltage alternator is installed per STC SH131WE; the helicopter is equipped with a Dovsek Model 200C or 300B light mounts, the mount's indicator light conforms to Hughes Service Information Notice #N92. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
269B, 269C; T.C. 4H12	SH131WE	Installation of EMPAC (U.S. Energy Corporation) Model TA-30 dual voltage alternator system (12 volts/60 amperes and 28 volts/68 amperes) in lieu of 12-volt alternator. Issued 7/7/71.	WE	80890	United State Energy Corporation 2780 Temple Avenue Long Beach, CA 90806
269B, 269C; T.C. 4H12	SH145WE	Installation of modified oil filler tube and dipstick. Issued 5/31/72.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH146WE	Installation of utility window. Issued 6/2/72.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4H12	SH202WE	Installation of controls for pilot-in-command on right side. Issued 4/28/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
269B, 269C, Normal Category; T.C. 4H12	SH245WE	Installation of searchlight. Issued 7/31/79.	WE	19986	Carter Engineering Company, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
269B, 269C; T.C. 4H12 Only those rotorcraft having Hughes P/N 269A4593 or 269A8241, or 269A4593 muffler installed.	SH1138CE	Installation of engine exhaust tail pipe extension. Issued May 1975.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052
269C; T.C. 4H12	SH134WE	Installation of Spectrolab Nightsun SX-16C searchlight. Amended 3/3/75.	WE	65328	Progressive Aviaiton Limited Reid-Hillview Airport San Jose, CA 95122
269C; T.C. 4H12	SH224WE	Installation of heated pitot. Issued 9/13/78.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
269C; T.C. 4H12	SH1099CE	Installation of cabin heater and engine exhaust tail pipe extension. Issued March 1975.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052
300 Series (269C); T.C. 4H12	SH333NW	Installation of automatic flagman. Issued 10/28/76.	NW	03500	Air Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
369; T.C. H3WE	SH390NW	Installation of electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
369 Series; T.C. H3WE	SH598NW	Installation of load readout device. Issued 5/18/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
369 Series; T.C. H3WE	SH667NW	Installation of fiberglass fuel tanks under rear seat. Issued 9/15/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369 Series; T.C. H3WE	SH829NW	Installation of a weighing system. Issued 9/6/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
369, 369A, 369H, 369HM, 369HS, 369HE, 369D; T.C. H3WE	SH207WE	Installation of range extension fuel tank in cargo area of Hughes 369 series helicopters. Issued 1/10/78.	WE	68501	Robertson Aircraft, Inc. P.O. Box 968 Tempe, AZ 85281
369A, 369D, 369H; 369HE, 369HM, 369HS; T.C. H3WE	SH215WE	Installation of floodlights on fuselage. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
369A, H, HM, HE, HS; T.C. H3WE	SH358AL	Installation of Airglas L2700-369 skis. Amended 6/26/74.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369A, H, HS, HE; T.C. H3WE	SH1657SW	Full length, hard surface, skid shoes on standard skid landing gear. Issued 6/18/73.	SW	61650	Northrup Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
369D; T.C. H3WE	SH220WE	Installation of a "HCS-500D" helicopter computer system. Issued 7/28/78.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
369D; T.C. H3WE	SH246WE	Installation of ATI Model 13-0044, 13-0045 and 13-0046 speaker kits. Issued 8/17/79.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
369D; T.C. H3WE	SH493GL	Installation of a Shadin Co. 910510 fuel flow indicating system. Issued 1/13/81.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Minneapolis, MN 55426
369D; T.C. H3WE	SH654AL	Install Airglas Model L2700-369HD skis. Issued 10/24/78.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D; T.C. H3WE	SH678AL	Installation of Airglas skis. Issued 12/28/79.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D; T.C. H3WE	SH1172SO	Installation of an AFE Model 3000 canopy defogger system. Issued 1/14/81.	SO	01480	Advanced Flight Engineering, Inc. Interior Building St. Petersburg - Clearwater Inter'l Airport Clearwater, FL 33515
369D (H500D); T.C. H3WE	SH1546CE	Installation of Collins APS-841HAFCS. Issued 7/7/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
369D, 369H Series; T.C. H3WE	SH567NW	Installation of engine driven pump, tank hoses and spray nozzles for fire fighting. Issued 2/24/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369D, 369HE, 369HM, 369HS; T.C. H3WE	SH112GL	Installation of Marathon CA1700-1 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213
369D, 369HE, 369HM, 369HS; T.C. H3WE	SA123GL	Installation of SAFT 1656-1 nickel cadmium electrical storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213
369D, 369HE, 369HS; T.C. H3WE	SH236WE	Installation of searchlight. Issued 4/26/79.	WE	19986	Carter Engineering, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
369D, HE, HM, HS; T.C. H3WE	SH552NW	Installation of cargo hook electronic scale system. Issued 1/4/78.	NW	73067	Marvin A. Smith 5503 West Flowing Lake Road Snohomish, WA 98290
369D, 369H, 369HE, 369HM, 369HS; T.C. H3WE	SH183WE	Installation of turbine overtemperature warning system. Amended 4/4/77.	WE	60425	MRSC Incorporated 10959 San Diego Mission Road San Diego, CA 92108
369D, 369HE, 369HM, 369HS; T.C. H3WE	SH401GL	Installation of Ni-Cad Model No. 72639 engine lubrication system scavenge filter. Issued 4/18/80.	GL	61546	Ni-Cad, Incorporated 24800 U.S. 20 West South Bend, IN 46628

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
369D, HE, HM, HS; T.C. H3WE	SH958SO	Installation of SAFT 16156 nickel cadmium battery. Amended 1/17/79.	SO	69800	SAFT America, Inc. P.O. Box 1886 Valdosta, GA 31601
369D, H, HM, HS, HE; T.C. H3WE	SH1142EA	Installation of APC starter-generator, P/N 150SG111Q. Issued 4/23/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
369D, 369HE, 369HS; T.C. H3WE	SH189WE	Installation of searchlight kit. Amended 3/16/79.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH190WE	Installation of P.A. speaker kit. Amended 4/14/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH250WE	Installation of a P.A. speaker kit. Issued 9/17/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH898EA	Installation of pod type cargo container kits. Amended 11/22/78.	EA	72263	Skypods Limited P.O. Box 221 Arnprior, Ontario, Canada
369D, 369HE, 369HS; T.C. H3WE	SH1134EA	Installation of external cargo container (POD) kit. Amended 4/11/80.	EA	83757	Viking Helicopters, Ltd. P.O. Box 5104 - Station "F" Ottawa, Ontario, K2C3H4 Canada
369H; T.C. H3WE	SH184NW	Installation of Chadwick C-500 aerial spray system. Issued 5/23/75.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369H; T.C. H3WE	SH431NW	Installation of Model 500 spray system. Amended 5/9/77.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH1054EA	Installation of Garrett AiResearch environmental control system. Amended 9/8/77.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
369HE, 369HM, 369HS; T.C. H3WE	SH129WE	Installation of Chadwick C-20 auxiliary fuel systems. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH132WE	Installation of two side cargo racks P/N DMC-023-200-1. Issued 8/25/71.	NW	61798	Olympic Helicopters, Inc. 8241 Perimeter Road South Boeing Field Seattle, WA 98108
369HE, 369HM, 369HS; T.C. H3WE	SA133WE	Installation of C-75 cargo rack set, P/N 75-0000-00. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH516AL	Installation of Model L2700-369HS skis. Issued 5/1/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
369HS; T.C. H3WE	SH214WE	Installation of external neutron detector moduel and associated cockpit displays. Issued 4/18/78.	WE	31225	EG & G, Incorporated P.O. Box 1912 Las Vegas, NV 89101
369HS; T.C. H3WE	SH242NW	Installation of battery in Hughes 369HS helicopter to replace original. Issued 12/11/75.	NW	47708	Keefer Aircraft Engineer 11457 Glendale Way South Seattle, WA 98168
369HS; T.C. H3WE	SH690SO	Installation of SunAir Electronics Model ASB-60 or ASB-125 HF radio transceiver and associated system. Reissued 6/20/73.	WE	43344	Hughes Helicopters Div. of Summa Corporation Centinela & Teale Streets Culver City, CA 90230

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ISRAEL AIRCRAFT INDUSTRIES, LTD.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1100 Series; T.C. A2SW	SA1192SO	Install Utah Research & Development Co. Model 126BC-101 battery charging system. Issued 12/16/80.	SO	18190	BSI Manufacturing, Inc. 101A Space Park South Drive Nashville, TN 37211
1121; T.C. A2SW	SA187SO	Bar cabinet and 2-place couch.	SO	18749	Butler Aviation Palm Beach, Inc. International Airport West Palm Beach, FL 33401
1121; T.C. A2SW	SA353SO	Two forward seats in cabin between Stations 115.78 and 134.78.	SO	68430	Robbins Airborne 2456 Winchester Memphis, TN 38101
1121; T.C. A2SW	SA387EA	Automatic flight control system.	GL	15210	Beckett Aviation Corporation Municipal Airport Youngstown, OH 44501
1121; T.C. A2SW	SA555SW	Seat tracks.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001 AND
1121; T.C. A2SW	SA555SW	Seat tracks.	SW	22792	Clark Engineering Service 6441 Happy Lane Dallas, TX 75221
1121; T.C. A2SW	SA620SW	Instrument standby 400 CPS static inverter and ground blower system.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA629SW	Angle of attack system.	NE	26010	Continental Development Corp. P.O. Box 511 Ridgefield, CT 06877
1121; T.C. A2SW	SA630SW	Installation of antenna for electronics system, and electronic equipment shelves. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
1121; T.C. A2SW	SA640SW	Antenna system.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA664SW	Interior. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1121; T.C. A2SW	SA679SW	ADF sense antenna.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA702SW	Installation of electronic equipment for Category II operation. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
1121; T.C. A2SW	SA724SW	Radome plastic nose cap.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA865SW	Antenna system.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA866SW	Standby AC power system.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
1121; T.C. A2SW	SA959SW	DA2001 quick release pin for nose gear torque train.	SW	29232	Delta Aircraft P.O. Box 12182 San Antonio, TX 78205
1121; T.C. A2SW	SA967EA	Installation of Tramm BTI-6000 dual battery temperature indicating system. Issued 11/13/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1121; T.C. A2SW	SA1246SW	Install equipment necessary to certify aircraft to 45,000 feet (crew only) and 41,000 feet (passenger). Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. Suite 115 2025 S. Nicklas Oklahoma City, OK 73128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1121; T.C. A2SW	SA1290WE*	Installation of "Quazar" high-intensity supplemental exterior flashing lights. *Approved anti-collision light system is required. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 S. Curtice Street Littleton, CO 80120
1121; T.C. A2SW	SA1356WE	Gas turbine 3TCP30-92 auxiliary power unit.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
1121; T.C. A2SW	SA1487SW	Replacement of existing cockpit light dimmers. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas , Suite 115 Oklahoma City, OK 73128
1121; T.C. A2SW	SA1775WE	Installation of nose wheel steering quick disconnect pin.	WE	71746	SIMCO 1660 - 18th Street Santa Monica, CA 90404
1121; T.C. A2SW	SA2013WE	Installation of single point pressure refueling system.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1121; T.C. A2SW	SA2408SW	Three-place couch side facing with toilet. Issued 2/14/77.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
1121; T.C. A2SW	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
1121; T.C. A2SW	SA2847SW	Forward cabin window, left and right side at fuselage station 115.78 to 134.78 and right side window at fuselage station 150.15. Issued 5/31/79.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A; T.C. A2SW	SA964CE	Installation of IAD battery temperature indicating and over temperature warning system. Issued October 1973.	CE	05250	Aircraft Instrument & Development, Inc. 317 E. Lewis Street Wichita, KS 67202
1121, 1121A; T.C. A2SW	SA1165SW	Installation of bleed air heated engine inlet ducts. Reissued 2/5/80.	SW	44860	Israel Aircraft Ind. Int'l, Inc. 2025 South Nicklas Oklahoma City, OK 73125
1121, 1121A, 1121B; T.C. A2SW	SA416CE	Install Hoskins supplementary Twilighter Mk III lighting system with Model A single wing tip lights and Model D (dual) tail light or tail light assembly. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 N. Batavia Orange, CA 92667
1121, 1121A, 1121B; T.C. A2SW	ST881SO	Installation of Teledyne P/N BP638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
1121, 1121A, 1121B; T.C. A2SW	SA922SW	Drag chute as safety item. Reissued 2/14/75.	SO	34808	Federal Express Corporation AMF P.O. Box 30167 Memphis, TN 38130
1121, 1121A, 1121B; T.C. A2SW	SA934SW	Aft baggage compartment. Amended 8/12/75.	SO	34808	Federal Express Corporation AMF P.O. Box 30167 Memphis, TN 38130
1121, 1121A, 1121B; T.C. A2SW	SA948EA	Installation of battery isolation system. Issued 3/23/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1121, 1121A, 1121B; T.C. A2SW	SA1274SW	CA5 batteries. Reissued 2/28/73.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA1298SW	Teledyne Avionics normalized angle of attack indicating system 112B400 with optional input to slow/fast indicator of Collins 329B-8G flight director instrument. Issued 6/16/71.	SW	78127	Teledyne, Inc. 3401 Shiloh Road Garland, TX 75040
1121, 1121A, 1121B; T.C. A2SW	SA1311SW	Redesigned nose wheel corotating drive shaft. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128
1121, 1121A, 1121B; T.C. A2SW	SA1345SW	Gross weight increase to 18,500 lbs. takeoff with B.F. Goodrich wheels, brakes and anti-skid system. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1121, 1121A, 1121B; T.C. A2SW	SA1434SW	Increase maximum zero fuel weight from 12,000 lbs. to 12,340 lbs. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128
1121, 1121A, 1121B; T.C. A2SW	SA1513SW	Ground air conditioner. Reissued 2/28/73.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA1879SW	Engine thrust reversers. Issued 6/7/74.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
1121, 1121A, 1121B; T.C. A2SW	SA1947SW	Fuel drain collector. Issued 1/17/75.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2203SW	Install capacitance type fuel gaging system. Reissued 3/10/78.	SW	44860	Israel Aircraft International 2025 S. Nicklas Oklahoma City, OK 73128
1121, 1121A, 1121B; T.C. A2SW	SA2389SW	Install identification and recognition lights in wings. Issued 12/8/76.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2615WE	Installation of nose wheel steering control wheel unit. Reissued April 1973.	SW	04540	Air Center, Inc. Wiley Post Airport P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2695SW	Install aircraft taxi lights on main landing gears. Issued 12/15/77.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2712SW	Modify existing TSO three-place forward facing couch. Issued 1/24/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2713SW	Install two and three-place couches (TSO 39a) side facing at right side of cabin. Issued 1/26/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2716SW	Relocation of thrust reverser hydraulic accumulator pressure gage. Issued 2/1/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2745SW	Install aft baggage compartment. Issued 4/4/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B; T.C. A2SW	SA2894SW	Installation of hydraulic accumulator. Issued 1/10/79.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121A, 1121B, 1122; T.C. A2SW	SA927EA	Installation of Grimes three light strobe kit P/N 34-0305-1 as supplemental lighting. Issued 7/7/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
1121, 1121A, 1121B, 1123; T.C. A2SW	SA2471SW	Fabrication and installation of aircraft cabin door retainer. Issued 6/9/77.	SW	04540	Air Center, Inc. P.O. Box 32168 Okahoma City, OK 73132
1121, 1121A, 1121B, 1123; T.C. A2SW	SA3000WE	Installation of logo light assembly. Amended 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA398EA	3065 replacement nose cap radome. Amended 7/16/76.	GL	61750	Norton Company Plastucs & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA791CE	Installation of either of the following electronic synchronizer kits P/N 213521 or P/N 213517. Amended 9/28/72.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
1121, 1121A, 1121B, 1123, 1124; T.C. A2SW	SA2396SW	Fabrication and installation of aircraft positive door latch. Issued 1/14/77.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
1121, 1121B; T.C. A2SW	SA1805WE	Installation of ground air conditioner. Amended 7/16/69.	WE	85135	Western Commander, Inc. 8029 Woodley Avenue Van Nuys, CA 91406
1121A, 1121B; T.C. A2SW	SA1820SW	Collins MC-103 dual compass system. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-60; T.C. A2WE	SA996CE	Installation of electronic components package, version L. Amended March 1974.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1012CE	Install interior, version No. 8. Issued April 1974.	CE	68765	Aviation Services Division Rockwell International Corp. Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1014CE	Cockpit voice and flight data recorder, altitude alerter system and encoding and weather radar. Amended November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1075CE	Aft lavatory auxiliary seat installation. Issued January 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1078CE	Aft lavatory and auxiliary L.H. installation. Issued February 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1092CE	Installation of electronic components package, version M. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1139CE	Install aft facing forward L.H. seat installation. Issued May 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1146CE	Interior installation, version No. 9. Issued July 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1148CE	Installation of electronic components package, version N. Issued 7/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1149CE	Installation of electronic components package, version P. Issued 7/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1182CE	Auxiliary seat and baggage area installation. Issued 11/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1191CE	Aisle facing seat and baggage area. Issued 1/6/76.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1221CE	Install interior, version No. 10. Issued May 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1242CE	Install Collins ADF-60A automatic direction finding and Intercontinental Dynamics Corp. RAD/BAR with voice terrain advisory system. Amended September 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1247CE	Forward lavatory L.H. installation. Issued July 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1339CE	Aft lavatory installation. Issued 7/6/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1367CE	Interior installation, Version No. 11. Issued 9/15/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1379CE	Install Collins FPC-75 GPWS, IDC SAT/TAS Collins ALT-55B radio altimeter and Wulfsberg Flitefone III provisions. Issued 10/18/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-60; T.C. A2WE	SA1385CE	Install electronic components package Version "R". Issued 11/15/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1386CE	Install electronics components package Version "Q". Issued 11/23/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-60; T.C. A2WE	SA1392CE	Install Global GNS-500A VLF/OMEGA navigation system. Issued 12/29/77.	CE	59270	Midcoast Aviation Services, Inc. Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1421CE	Install convertible baggage, aisle facing seat. Issued 6/12/78.	CE	59270	Midcoast Aviation Services Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1434CE	Interior installation Version No. 12. Issued 9/19/78.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63775
NA-265-60; T.C. A2WE	SA1476SW	Normalized angle of attack indicating system. Amended 8/27/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
NA-265-60; T.C. A2WE	SA1811WE	Installation of reinforced structure and certain components in partial provision for UCAR configuration. Reissued 7/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60; T.C. A2WE	SA1912WE	Installation of nose boom extension and/or doppler radome and fairing. Amended 5/8/69.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
NA-265-60; T.C. A2WE	SA2878SW	Install two two-place side facing couches. Issued 12/5/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
NA-265-60, Serial No. 306-23 and subsequent; T.C. A2WE	SA3042WE	Installation of engine fuel drain sump tank. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
NA-265-60, -70; T.C. A2WE	SA737CE	Installation of Solar APU Model T-62T-39 and T-62T-39Y. Reissued 6/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60, -80; T.C. A2WE	SA1129CE	Installation of IFR delivery package. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International Corp. 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60, -80; T.C. A2WE	SA1479CE	Installation of forward auxiliary fuel cell (56 gallons). Amended 4/30/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-65; T.C. A2WE	SA1537CE	Installation of Solar Model T-62T-40C auxiliary power unit (APU). Issued 12/29/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-65; T.C. A2WE	SA1603CE	Installation of Collins FPC-75 ground proximity warning system. Issued 10/1/80.	CE	68765	Sabreliner Division Rockwell International Route 3 Perryville, MO 64105
NA-265-65; T.C. A2WE	SA1611CE	Modification to incorporate fuel management computer. Issued 10/6/80.	CE	24540	Colt Electronics Company 15301 West 109th Street Lenexa, KS 66219
NA-265-70; T.C. A2WE	SA816CE	H.F. antenna installation. Amended February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA824CE	Audible hydraulic pressure warning system. Issued February 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA868CE	Installation of Tramm BTI-600 battery temperature indicator system. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-70; T.C. A2WE	SA869CE	Installation of RCA AVQ-21 weather radar. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA870CE	Installation of Collins ALT-50 radio altimeter. Issued October 1972.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA969CE	Installation of 7-passenger interior. Issued November 1973.	CE	68765	North American Rockwell Aviation Services Division Lambert Field St. Louis, MO 63145
NA-265-70; T.C. A2WE	SA1248CE	Installation of Collins AP104/FD109H automatic flight control system. Issued November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA2766WE	Replacement of existing engines with GE CF700-2D-2 fan jet engines. Issued 10/31/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-80; T.C. A2WE	SA995CE	Install electronic components package, version A. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA997CE	Install interior, version No. 2. Issued February 1974.	CE	68765	Aviation Services Division North American Rockwell Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1015CE	Installation of electronic components package Version "C". Amended 12/22/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1026CE	Install interior, version No. 3. Issued May 1974.	CE	68765	Aviation Services Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1028CE	Installation of electronic components package, version B. Issued 1/20/75.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1043CE	Installation of electronic components package, version D. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Corp. Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1065CE	Installation of electronic components package, version E. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1066CE	Installation of Teledyne angle of attack indicating system SL112B1400. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1067CE	Auxiliary seat installation aft lavatory. Issued November 1974.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1074CE	Auxiliary seat installation. Issued January 1975.	CE	68765	Aviation Services Division Rockwell International Lambert Field St. Louis, MO 63145
NA-265-80; T.C. A2WE	SA1100CE	Interior installation No. 4. Issued March 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1101CE	Installation of cockpit voice recorder and flight data recorder. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1132CE	Install aft lavatory auxiliary seat. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-80; T.C. A2WE	SA1133CE	Interior installation, FAA Airways Checker. Issued July 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1142CE	Interior installation, version No. 5. Issued June 1975.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-80; T.C. A2WE	SA1249CE	Interior installation, version No. 6 (wide body). Issued August 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1272CE	Interior installation, version No. 7.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1274CE	Installation of electronic components package, Version "F". Amended 6/21/77.	CE	68765	Sabreliner Completion Center Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1275CE	Interior installation, version No. 8.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1288CE	Interior installation, version No. 9. Issued November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1293CE	Commode installation - aft lavatory. Issued January 1977.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1323CE	Interior installation, No. 10. Issued May 1977.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1329CE	Installation of Collins NCS-31A navigation control system with dual control heads, HI-350 remote compass and Collins 728U-5 HF transceiver system. Issued 5/20/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1337CE	Installation of Intercontinental Dynamics cCorp. vertical navigation system. Issued 5/21/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1342CE	Install electronics components package, Version "G". Issued 8/9/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA1374CE	Installation of 800 VA and 2500 VA static inverters. Amended 12/21/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA265-80; T.C. A2WE	SA1387CE	Passenger compartment wiring provisions installation. Issued 11/30/77.	CE	68765	Sabreliner Division Rockwell International Municipal Airport Perryville, MO 63775
NA-265-80; T.C. A2WE	SA3974WE	Installation of Litton LTN-72R area navigation system. Issued 7/6/79.	WE	11620	Area Equipment Company, Inc. 7707-1/2 Woodley Avenue Building 901 Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

ROCKWELL INTERNATIONAL CORP., OKLAHOMA

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500 Series; T.C. 6A1	SA1-541	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500 Series; T.C. 6A1	SA1-555	ANC-3A computer and ANC-C2 or ANC-D2 controller.	EA	31050	Dynavia Corporation 3021 West Clay Street Richmond, VA 23219
.500 Series; T.C. 6A1	SA1-607	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500 Series; T.C. 6A1	SA3-525	37R-2 antenna.	CE	24250	Collins Radio Company 855 35th Street, NE Cedar Rapids, IA 52406
500 Series; T.C. 6A1	SA4-904	Installation of mufflers and modification of carburetor heat system. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500 Series; T.C. 6A1	SA4-1309	L-2C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
500 Series; T.C. 6A1	SA30CE	210405 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
500 Series; T.C. 6A1	SA70CE	Federal F-500 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
500 Series; T.C. 6A1	SA166WE	Removal of main cabin door and hinge pins.	WE	42129	Herpolsheimer Enterprises 12345 VEntura Boulevard Studio City, CA
500 Series; T.C. 6A1	SA168CE	Twin engine synchronizer.	GL	87250	Woodward Governor Company 5001 NOrth Second Street Rockford, IL 61101
500 Series; T.C. 6A1	SA257CE	Turbocharged Lycoming engines, IO-540-A1A5 with Hartzell HC-A3VK-2/V7636D propellers. Reissued 12/5/74.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90801
500 Series; T.C. 6A1	SA340SO	Continental IO-520E engines and Hartzell 3-bladed propellers.	SO	23700	Colemill Enterprises, Inc. P.O. Box 5221 Nashville, IN 37206
500 Series; T.C. 6A1	SA366SO	Gross weight increased to 6530 pounds.	SO	23700	Colemill Enterprises, Inc. Cornelia Fort Air Park Nashville, TN 37202
500 Series; T.C. 6A1	SA459EA	Conversion to Model 500B.	GL	73885	Southern Ohio Aviation Sales Co. Box 97 Montgomery County Airport West Carrollton, OH 44615
500 Series; T.C. 6A1	SA476WE	Nacelle mounted fuel booster pump. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500 Series; T.C. 6A1	SA680SW	AK221 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500 Series; T.C. 6A1	SA683WE	Turbosupercharged Continental IO-470-M engines. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
500 Series; T.C. 6A1	SA1106WE	Mounting provisions for Reconofax XI infrared scanner unit.	EA	03270	U.S. Forest Service Department of Agriculture 1210 Independence Avenue, SW Washington, D.C. 20250

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500, 500A, B, 520, 560, 560A, B, E; T.C. 6A1, 2A4	SA90CE	High intensity wing tip lights, tail light and fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
500, 500A, B, 560A, E, 680, 680F, FL, F(P), T, 720; T.C. 6A1, 2A4	SA92EA	Install wheels P/N's 3-1112 and/or 311-58 and P/N's 2-878 and/or 2-971 and/or 2-1087. Reissued 9/4/74.	GL	38504	B.F. Goodrich Engineered Systems Company P.O. Box 340 Troy, OH 45373
500, 500-A, B, S, U, 560A, E; T.C. 6A1	SA303GL	Install Cleveland conversion kit No. 199-74 on models which use MIL-H-5606 brake fluid (red oil) or install conversion kit No. 199-74A on models which use Skydrol brake fluid (nonpetroleum base). Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
500, 500A, B, 560A, E, F, 680, 680E, F, FL, F(P), FL(P), T, 720; T.C. 6A1, 2A4	SA321EA	Install wheels P/N 301174, P/N's 2-993 and/or 2-1107. Reissued 9/4/74.	GL	38504	B.F. Goodrich Engineered Systems Company P.O. Box 340 Troy, OH 45373
500, 500A, B, U, 560, 560A, E, F, 680, 680F, 680FL, 680FL(P), 680T, 680W, 720; T.C. 6A1, 2A4	SA404CE	Installation of Hoskins supplemental position light system which includes Model A wing tip lights and Model D or K (dual) tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
500, 500A, B, S, U, 560, 560A, E, F, 680, E, F, FL, FL(P), V, W, 720; T.C. 6A1, 2A4	SA527EA	Installation of Collier Model 1AC internally mounted ADF sense antenna. Amended 11/21/68.	GL	24000	Collier Aero Products Company Box 509 Municipal Airport Mansfield, OH 44901
500, 500A, 520, 560; T.C. 6A1	SA589WE	Installation of full-flow lube oil filters on the aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court P.O. Box 175B San Leandro, CA 94577
500, 500-A, -B, -S, -U, 520, 560, 560-A, -E, F, 680, 680-E, -F, FL, FL(P), T, V, W, 681, 685, 690, 720, 111, 112; T.C. 6A1, 2A4, A11SO, A12SO	SA615EA	Installation of Whelen anti-collision strobe light system Models HD, HR or HS (-14(14V) or -28(28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
500, 500-A, -B, 520, 560; T.C. 6A1	SA630WE	Installation of Coast Winslow Filter Corporation 409 series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
500, 500-A, -B, -S, -U, 520, 560, 560-A, -E, F, 680, 680-E, -F, FL, 680FL(P), T, V, W, 681, 685, 690, 720, 111, 112; T.C. 6A1, 2A4, A11SO, A12SO	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
500, 500-A, -B, -S, -U, 520, 560, 560-A, -E, -F, 680-E, -F, FL(P); T.C. 6A1, 2A4	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light systems two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 4/27/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
500, 500A, -B, -S, -U, 520, 560, 560-A, -E, -F, 680, -E, -F*, FL, FL(P), T, V, W, 681, 685, 690, 690A, B, 720; T.C. 2A4, 6A1 Includes Pressurized Versions*	SA1017EA	Installation of vertical tail floodlights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
500, 500A, B, S, U, 560A, 680E, F; T.C. 6A1, 2A4	SA1135SW	Modification of fuselage for installation of Bendix ANA-12 doppler antenna. Issued 3/30/70.	SW	47770	Kerr Aviation Services, Inc. P.O. Box 399 Bethany, OK 73008
500, 500-A, B, U, 560, 560A, E, F, 680, E, F, FL; T.C. 6A1, 2A4	SA1290WE	Installation of "Quazar" high-intensity supplemental exterior flashing lights. Amended 11/25/69.	RM	66000	Radair, Inc. 5665 South Curtis Street Littleton, CO 80120

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500, 500A, 500B, 500S, 500U, 520, 560, 560A, 560E; T.C. 6A1	SA3476WE	Replacement installation of tail cone assembly. Issued 9/7/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
500, 500A, 500B, 500U, 500S, 520, 560, 560A, 560E; T.C. 6A1	SA3492WE	Replacement installation of vertical tip assembly. Issued 10/26/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
500A, B, U, 560A, E, 680, E, F, F(P), FL, FL(P), T, 720; T.C. 6A1, 2A4	SA1-143	Installation of Chamberlain 2001X series radome kits. Amended 8/17/78.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
500A - modified -- Colemill STC SA340SO; 500B, 500S, 500U, 700; 500S, 500U - modified — Mr. RPM STC SA2478SW; 685; T.C. 6A1, 2A4, A12SW	SA20GL	Installation of Woodward Type II electronic propeller synchronizer or synchrophaser system. Amended 11/30/78.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
500A, B, 560B, 680FL; T.C. 6A1, 2A4	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
500-A, -B, -S, -U; T.C. 6A1	SA447SO	Installation of Bendix Model FCS810 flight control system, including manual electric trim and flight director indicator DH 841( ). Amended 6/17/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
500A, B, U, 560A, F, 680, 680E, F, FL, FL(P), T, 720; T.C. 6A1, 2A4	SA458EA	Installation of nose cap radome kit No. 3066X-R. Amended 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
500A, B, U; T.C. 6A1	SA802SW	Bendix M4-B/C autopilot flight control system.	SO	15475	Bendix Avionics P.O. Box 9414 Fort Lauderdale, FL 33310
500A, B, U; T.C. 6A1	SA1662SW	Outboard fuel system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
500-A, -B, -S, -U, 560A, 560E; T.C. 6A1	SA1072SW	Universal camera.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
500A, B, S, U, 560A, E, F, 680, E, F; T.C. 6A1, 2A4	SA1122SW	Dual cameras and navigation sights.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
500A, B, S, U, 560A, E, F, 680, E, F; T.C. 6A1, 2A4	SA1332SW	Modify fuselage for camera and navigation sight. Issued 6/24/71.	SW	42825	A.D. Howard, Jr. 6817 NOrthwest 43rd Street Bethany, OK 73008
500A, B, S, U, 560A, E, F, 680, E, F; T.C. 6A1, 2A4	SA1393SW	Mitchell automatic flight system FD/AP282-353 consisting of flight director/autopilot with automatic command trim system. Issued 11/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500A, B, S, U; T.C. 6A1	SA1394SW	Mitchell automatic flight system Model AK353 consisting of Century III autopilot with optional automatic/command trim, radio coupler, glide slope coupler. Issued 11/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500A, B, S, U; T.C. 6A1	SA1445SW	Modification of MItchell automatic flight system AK221 installed per STC SA680SW. Issued 3/13/72.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
500A, B, S, U; T.C. 6A1	SA3142SW-D	Mitchell automatic flight system AK600 consisting of Century IV autopilot or Model AK600FD consisting of Century IV flight director autopilot with remote annunciator. Issued 6/1/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500A, B, S, U; T.C. 6A1	SA3143SW-D	Mitchell automatic flight system AK601 consisting of Century III autopilot with optional radio and glide slope coupler. Issued 6/1/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500A, B, S, U, 520, 560A; T.C. 6A1	SA3516WE	Installation of cockpit overhead windows. Issued 12/1/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
500A, 560, 560A, 560E; T.C. 6A1	SA1686WE	Installation of engine mounts P/N VIP 50525-1 and 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
500A, B, S, U, 560A, E, 680, E, F; T.C. 6A1, 2A4	SA1847WE	Installation of Brittain up-command signal adapter kit on certain airplanes equipped with Brittain Models B-4A, B-4AP, B-5 and B-5P flight control system. Amended 12/4/70.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
500B; T.C. 6A1	SA1138SW	Fiberglass tail cone. Issued 4/8/70.	SW	47770	Kerr Aviation Services, Inc. P.O. Box 399 Bethany, OK 73008
500B; T.C. 6A1	SA1971WE	Installation of Model ARB-3 automatic downed aircraft marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue Box 822 Fort Collins, CO 80521
500B; T.C. 6A1	SA3867WE	Installation of SDI model CFS-1000, -2001 or FT-200 fuel indicating system. Issued 2/16/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
500B, 500B (with STC SA529WE); T.C. 6A1	SA111RM	Modify exhaust stacks by installing straight slip joint. Issued 3/27/78.	RM	41750	Heliarc Welding Service, Inc. 3965 Newport Denver, CO 80207
500-B, -S, -U; T.C. 6A1	SA529WE	Installation of turbosupercharged Lycoming IO-540 Series engine. Reissued 1/14/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
500-B, -S, -U; T.C. 6A1	SA973SW	Auxiliary outboard wing tanks.	SW	66250	A.D. Howard, Jr. 6817 NOrthwest 43rd Street Bethany, OK 73008
500B, U, S; T.C. 6A1	SA2826SW	Auxiliary fuel tank. Issued 8/2/78.	SW	66250	A.D. Howard, Jr. 1911 Moulton Court Oklahoma City, OK 73127
500B, 500U; T.C. 6A1	SA1-606	Installation of electrothermal propeller deicing system. Amended 3/24/67.	GL	38500	The B.F. Goodrich Company 500 South Main Street Akron, OH 44318
500S; T.C. 6A1	SA66GL	Install Collins AP-106 autopilot consisting of Collins 913K-1 two each 334C-9 (662-0964-001, -002), 334C-6 (622-0965-002), 590A-6, 614E-1, 339T-1, 161H-1, 590B-3, and 390B-18 units. Reissued 2/11/76.	CE	24250	Collins Radio Group 5225 "C" Avenue, NE Cedar Rapids, IA 52406
500S; T.C. 6A1	SA101GL	Installation of Collins AP-107 autopilot. Reissued 2/11/76.	CE	24250	Collins Radio Group 5225 "C" Avenue, NE Cedar Rapids, IA 52406
500S modified - Mr. RPM per STC SA2478SW, 112TC, 112TCA, 114; T.C. 6A1, A12SO	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 3/1/79.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
500S; T.C. 6A1	SA854EA	Installation of Radome Kit No. 4022KX. Amended 12/16/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
500S; T.C. 6A1	SA2478SW	Installation of Lycoming IO-720-B1B engine and increase take-off and landing weight to 7800 lbs. Issued 7/15/77.	SW	69218	Mr. R.P.M., Inc. P.O. Box 4580 Waco, TX 76705
500, 111 Series; T.C. 6A1, A11SO	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
680 Series; T.C. 2A4	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock. Reissued.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
680 Series; T.C. 2A4	SA665SW	deHavilland airborne profile recorder in aft fuselage.	EA	04515	Air Carrier Service Corp. 2233 Wisconsin Avenue, NW Washington, D.C. 20007
680 Series; T.C. 2A4	SA684SW	AP103F/FD-108 automatic flight control system.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA710SW	PT6A-20 engine.	SW	77110	Swearingen Aircraft P.O. Box 6904 San Antonio, TX 78209
680 Series; T.C. 2A4	SA1155WE	Camera.	NW	85123	Western Aerial Contractors, Inc. Route 1, Box 740 Eugene, OR 97401
680, 680E, 720; T.C. 2A4	SA660WE	Installation of HRD type fire extinguishing system. Amended 7/11/77.	WE	43190	HTL Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
680, 680-E, -F, -FL, -FL(P), T, V, W, 681, 685, 690, 720; T.C. 2A4	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Ic. 18145 Judy Street Castro Valley, CA 94546
680E; T.C. 2A4	SA450EA	Modification to lower surface of fuselage to accommodate Wild Camera Model RC5 or RC8. Amended 2/9/68.	EA	52060	Long Island Airways P.O. Box 828 Ronkonkoma, NY 11779
680E; T.C. 2A4	SA1782WE	Installation of drooped ailerons drooped wing leading edge, stall fence and rudder seal. Reissued 1/5/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
680F; T.C. 2A4	SA278GL	Installation of Cleveland kit, No. 199-74. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
680F; T.C. 2A4	SA2691WE	Installation ofLycoming IO-720-AIB turbocharged engine. Reissued 7/22/74.	WE	69220	Mr. R P M Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680F; T.C. 2A4	SA3299SW-D	Mitchell automatic flight system AK772, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/21/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F; T.C. 2A4	SA3300SW-D	Mitchell automatic flight system AK773, consisting of Century IV autopilot, consisting of Century IV flight director autopilot with optional remote annunciator. Issued 8/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F, 680FL; T.C. 2A4	SA155CE	Intallation of Honeywell H-14 adaptive autopilot.	CE	48250	King Radio Corpratin 400 North Rogers Road Olathe, KS 66061
680FL; T.C. 2A4	SA2EU	Cargo door modification	EU	08440	ALAR-Empresa Iberica de Material Aeronautico Ld Lisbon, Portugal
680FL; T.C. 2A4	SA102GL	Installation of baggage compartment. Issued 12/29/75.	GL	31362	Eagle Aviation, Inc. Bishop Airport Flint, MI 48507
680FL; T.C. 2A4	SA929SW	Automatic flight system AK270 consisting of Century III autopilot with optional automatic pitch trim. radio and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
680FL; T.C. 2A4	SA1089SW	59-gallon wing auxiliary fuel tank.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680FL; T.C. 2A4	SA1094SW	RD-8, RC-9, and RMK-A-15/23 cameras.	SW	47770	Kerr Aviation Service, Inc. Box 399 Bethany, OK 73008
680FL; T.C. 2A4	SA1095SW	installation of Bendix ANA-12A.	SW	47770	Kerr Aviation Service,Inc. Box 399 Bethany, OK 73008

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
680FL; T.C. 2A4	SA1358SW	Dual or single camera installation and navigation sights. Issued 8/25/71.	SW	42825	A.D. Howard, Jr. 6817 Northwest 23rd Street Bethany, OK 73008
680FL; T.C. 2A4	SA2448SW	Extension of baggage area to F.S. 308, encompassing re-routing of powerplant and aileron control cables in baggage compartment area. Issued 4/7/77.	SW	25260	Harry B. Combs, Jr. P.O. Box 4580 Waco, TX 76101
680FL, FL(P); T.C. 2A4	SA806SW	Flap close-out strips.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
680FL, 680FL(P), 680(P); T.C. 2A4	SA2891WE	Installation of Lycoming IO-720-B1B turbocharged engine. Reissued 8/2/74.	WE	69220	Mr. RPM, Inc. Suite 321 7120 Hayvenhurst venue Van Nuys, CA 91406
680FL, 680FL(P); T.C. 2A4	SA2903SW	Installation of wing flap gap seals. Issued 1/25/79.	SW	69218	Mr. R.P.M., Inc. P.O. Box 40414 Everman Branch Fort Worth, TX 76140
680FL(P); T.C. 2A4	SA3322WE	Installation of cockpit overhead windows. Issued 1/18/77.	WE	69220	Mr. RPM, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680FL(P), T, V, W, 681; T.C. 2A4	SA1261SW	Camera installation. Issued 3/11/71.	SW	30530	Downtown Airpark, Inc. Box 94846 Bethany, OK 73109
680FL(P), 680T, V, W, 681, 690; T.C. 2A4	SA1584SW	Aerial survey camera. Issued 1/3/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 68))*
680FL, 685; T.C. 2A4	SA1649SW	Camera installation. Issued 5/1/73.	SW	42825	A.D. Howard, Jr. 817 Northwest 43rd Street Bethany, OK 73008
680FL, 680FL(P), 680T, V, W, 681, 685A, 690, 690A; T.C. 2A4	SA1977SW	Modification of fuselage for installation of doppler antenna. Issued 5/6/75.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Oklahoma City, OK 73008
680T, V, W; T.C. 2A4	SA887SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
680T, 680V, 680W, 681; T.C. 2A4	SA895EA	Installation of Grimes three light strobe kit. Issued 1/20/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
680T, V, W, 681; T.C. 2A4	SA1926SW	Fuel purge system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681; T.C. 2A4	SA1962SW	Generator over-voltage/over-current protection. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681, 690; T.C. 2A4	SA1705SW	Freon air conditioning system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680V, W; T.C. 2A4	SA1529SW	Modification of hydraulic system and air conditioning pressurization system. Issued 7/25/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680V, W; T.C. 2A4	SA1530SW	Modify existing 3000 psi hydraulic system to 1000 psi hydraulic system. Issued 12/23/72.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
690W; T.C. 2A4	SA3469WE	Installation of AiResearch TPE 331-6-252M engines. Amended 2/27/78.	WE	07502	AiResearch Manufacturing Co. of Arizona 402 South 36th Street P.O. Box 5217 Phoenix, AZ 85010
680, 720 Series; T.C. 2A4	SA37CE	C210403 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
680, 720 Series; T.C. 2A4	SA39CE	C210310 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
681; T.C. 2A4	SA337GL-D	Installation of AiResearch TPE331-1-151-K engines. Amended 8/27/80.	GL	07499	AiResearch Aviation Company Capital Airport Springfield, IL 62705
681; T.C. 2A4	SA1005CE	Installation of IAD battery temperature monitor and over-temperature warning system. Issued March 1974.	CE	05250	Aircraft Instrument & Development, Inc. 317 East Lewis Wichita, KS 67202
685 Series; T.C. 2A4	SA17GL	Installation of Bendix FCS-810 autopilot. Issued 4/12/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
685 Series; T.C. 2A4	SA56GL	Install wheel assembly P/N 3-1174 and brake assembly P/N 2-993-1. Issued 7/23/74.	GL	38504	B.F. Goodrich Engineered Systems Company Division of B.F. Goodrich Co. P.O. Box 340 Troy, OH 45373
685; T.C. 2A4	SA155RM	Installation of Singer SKK-1000 doppler navigation system, SKQ-601 dead reckoning computer, and Sperry C-12 compass system. Issued 10/4/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
685 Series; T.C. 2A4	SA878SO	Installation of Silver Instruments Fueltron III, fuel flow gages. Issued 1/21/76.	SO	12493	Atlantic Aero, Inc. P.O. Box 8946 Grensboro, NC 27410
685; T.C. 2A4	SA3849WE	Installation of Fueltron IIIS or IIIP digital fuel flow and totalizer system. Issued 1/30/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
690 Series; T.C. 2A4	SA26GL	Installation of Bendix M-4C autopilot. Issued 7/2/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O.Box 1060 Rockford, IL 61109
690 Series; T.C. 2A4	SA530SO	Installaton of manual electric trim system. Issued 2/28/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
690 Series; T.C. 2A4	SA2606WE	Installation of Lear AFC-70 autopilot. Amended 7/20/73.	WE	49850	LearAvia Corporation Avioncs Division 14505 Mt. Anderson Avenue Reno, NV 89510
690 Series; T.C. 2A6	SA2727WE	Installation of LearAvia electric pitch trim system. Issued 7/20/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510
690, 690A; T.C. 2A4	SA74GL	Install wing tip recognition lights. Issued 3/21/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
690, 690A; T.C. 2A4	SA85SW	Installation of auxiliary bleed air shut-off and fuselage temperature monitoring system. Reissued 1/30/78.	SW	68768	Rockwell Aviation Service Division 3300 Love Field Drive Dallas, TX 75235
690, 690A; T.C. 2A4	SA1059SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid batteries. Issued 3/29/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339
690, 690A, 690B; T.C. 2A4	SA2577WE	Installation of flight FCS-105 flight control system. Amended 8/14/78.	CE	24250	Collins Radio Group Rockwell International 400 Collins Raod, N.E. Cedar Rapids, IA 52406
690A; T.C. 2A4	SA79GL	Instal Bendix M4D autopilot system. Issued 4/18/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61101
690A; T.C. 2A4	SA1009CE	Install Model KFC-300 automatic flight control system (autopilot and flight director). Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
690A; T.C. 2A4	SA1011CE	Install Model KVN-395 vertical navigation computer for operation with Model KFC-300 automatic flight control system. Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
690A; T.C. 2A4	SA1873SW	Sperry SPZ-200/STARS IVC. Issued 5/1/74.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, OK 73109
690A; T.C. 2A4	SA1876SW	AP-106 autopilot and manual electric trim. Issued 4/29/74.	SW	24252	Collins Radio Company Addison Airport Addison, TX 75001
690A, 690B; T.C. 2A4	SA1024SO	Installation of AiResearch TPE331-5-252K engines in Model 690A replacing AiResearch TPE331-5-251K engines; installation of TPE331-5-252K engines in Model 690B. Amended 6/18/80.	SO	37087	The Garrett Corporation c/o AiResearch Aviation Company Bush Field Agusta, GA 30906
690C; T.C. 2A4	SA405GL	Installation of a Collins LRN 70 Omega navigation system. Issued 5/13/80.	GL	33231	Electrosonics Division AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
695; T.C. 2A4	SA411GL	Installation of a Collins LRN 70 Omega navigation system. Issued 6/2/80.	GL	33231	Electrosonics Division AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
695; T.C. 2A4	SA418GL	Installation of a Collins LRN 70 Omega navigation system. Issued 6/20/80.	GL	33231	Electrosonics Division of AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
720; T.C. 2A4	SA1-553	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace ad Defense Products 500 South Main Street Akron, OH 45373
720; T.C. 2A4	SA395SW	Four-place seating capacity.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
111, 112; T.C. A11SO, A12SO	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10815 South Meridian Puyallup, WA 98371
111, 112; T.C. A11SO, A12SO	SA1502SW	Mitchell automatic flight system AK364 consisting of Century I autopilot with optional omni tracker. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1503SW	Mitchell automatic flight system AK 363 consisting of Century IIB autopilot with optional radio coupler. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1504SW	Mitchell automatic flight system AK362 consisting of Century III with optional command/electric pitch trim, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1505SW	Mitchell command/electric pitch trim. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1728SW	Cabin air scoop. Issued 9/13/73.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
112; T.C. A12SO	SA243NW	Installation of Lycoming IO-540 engine with 3-bladed Hoffman, 3-bladed Hartzell, or 2-bladed Hartzell propeller. Amended 5/26/78.	NW	52625	Machen, Inc. S. 3408 Davison Boulevard Spokane, WA 99204
112; T.C. A11SO, A12SO	SA2900WE	Installation of Pathfinder autopilots. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Amler Street Torrance, CA 90505
112; T.C. A12SO	SA3155WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 4/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torranc, CA 90505
112, 112B, 112TC, 112TCA, 114, 114A; T.C. A12SO	SA2370GL	Install leading edge landing lights. Amended 1/24/80.	GL	37182	General Aviation, Inc. Lost Nation Airport Willoughby, OH 44094

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
112, 112B, 112TC, 112TCA, 114; T.C. A12SO	SA1229CE	Install King Model KFC-200 2-axis (3 optional) flight control system with KCS 55/55A compass and a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller; or stand alone electric trim. Amended 1/18/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
112, 114; T.C. A12SO	SA3120SW-D	Automatic flight system AK572 consisting of Century I autopilot with optional omni tracker. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A12SO	SA3121SW-D	Automatic flight system AK573 consisting of Century IIB autopilot with optional radio coupler. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A12SO	SA3122SW-D	Automatic flight system AK574 consisting of Century III autopilot with optional radio and glide slope Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A18O	SA3123SW-D	Mitchel command electric trim AK582. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112B, 112TC, 112TCA, 114; T.C. A12SO	SA3778WE	Installation of retractable landing lights. Issued 11/8/78.	WE	47070	Fred W. Jones 2901 East Spring Street Long Beach, CA 90806
112TC, 112TCA; T.C. A12SO	SA3787WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
112TC, 112TCA; T.C. A12SO	SA3920WE	Installation of fueltron IG or IP digital fuel flow and totalizer system. Amended 1/9/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
114; T.C. A12SO	SA300CE	Installation of propeller governors on single and twin engine aircraft P/N J210345. Issued 5/7/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
114; T.C. A12SO	SA3727WE	Installation of SDI Model CFS-1000, -1001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
114; T.C. A12SO	SA3308WE	Modification of aileron control system by addition of aileron centering spring and installation of Pathfinder autopilot system and/or pitch trim systems. Issued 1/7/77.	WE	12380	Astronautics Corp. of America 2416 Ameler Street Torrance, CA 90505
114; T.C. A12SO	SA3727WE	Installation of SDI Model CFS-1000 fuel flow indicator. Issued 9/6/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
RYAN AERONAUTICAL COMPANY
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SCW-145; T.C. 658	SA4-339	Curtiss metal propeller 55518 and replacement of .080 windshield with bubble .125 (grade I) plexiglass.	WE	70262	Walter B. Saunders Gillespie Field Santee,CA 92071
SCW-145; T.C. 658	SA988WE	Ceconite 101 covering of ailerons, fin rudder, stabilizer and elevators.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SCW-145; ST-3KR; T.C. 658, 749	SA1351WE	Replace existing fabric on wings, fuselage, empennage,and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
SCW-145, ST-3KR; T.C. 658, 749	SA2666WE	Ceconite 102 material covering of: SCW-145 - complete aircraft; SCW-145 - ailerons, fin, rudder, stabilizer and elevators; ST-3KR - wings, flaps, horizontal stabilizer, elevator. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
ST-3KR; T.C. 749	SA4-822	Ceconite 101 covering of wings, flaps, ailerons, horizontal stabilizer and elevators.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
ST-3KR; T.C. 749	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
ST-3KR; T.C. 749	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
ST-3KR; T.C. 749	SA1008WE	Installatin of Poly-Fiber covering material (complete aircraft). Amended 8/7/69.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
ST-3KR (Army PT-22, -22A); T.C. 749	SA1350WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
ST-3KR; T.C. A-749	SA2921WE	Reduce size of cockpit openings, install rounded windshields, flush rivet and increase fuselage skin gages, install internal top longerons, remove external top longerons and install internal aileron balance weight. Issued 8/14/74.	WE	25700	Component Air, Inc. P.O. Bx 946 Santa Paula, CA 93060

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SCHWEIZER AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SGS 1-26 Series; T.C. 1G10	SG4WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SGS-1-26C; SGU-2-22E, SGU-1-19, -19A; T.C. 1G10, GTC G-18, G-17	SA1008WE	Installation of Poly-Fiber covering material (fuselage and control surfaces SGS-1-26C, SGU-2-22E) (complete aircraft SGU-1-19, -19A). Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
SGS 2-8A; T.C. 5	SG4-1156	Ceconite 101 covering of complete glider.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SGS 2-8A, SGU 2-22CK; T.C. 5, 18	SG4-1411	Ceconite 103 covering of glider.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SGS 2-8A; SGS-126, -A, -C; SGU 2-22CK, 22E; SGU 1-19; GTC 5, 18, 17, 1G10	SG10WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 103 material. Amended 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
SGS 2-8A; TG-3A, SGU-1-19; SGS-126, -26A, -26B, -26C; SGU 2-22, -22A, -22B, -22C, -22CK, -22E, -22EK; GTC 5, 17, T.C. 1G10, GTC 18	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or ontrol surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
SGS 2-8A, TG-3A, SGU-1-19, SGS 1-26, -26A, -26B, -26C, SGU 2-22, -22A, -22B, -22C, -22CK, -22E, -22EK; GTC 5, 17, 18, T.C. 1G10, 2-11	SA2666WE	Ceconite 102 material covering of: SGU-1-19, 1-26, -26A, -26B SGU 2-22 series - complete glider; SGS 2-8A, TG-3A complete glider; SGS 1-26C - control surfaces. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
SGU 1-19; T.C. G-17	SG7WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SGS1-26, -26A, B, C, SGS2-8, -8A, SGU-1-19, -1-19A, SGU-2-22, -22A, -22B, -22C, -22CK, -22E, -22KK; T.C. GTC 1G10, GTC 5, GTC G-17, GTC G-18	SG4-1240	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
2-33, 2-33A, 2-33AK; T.C. G2EA	SG305GL	Install full swivel tail wheel, Cronig P/N SK-1, utilizing existing mounting points, bolts and hardware. Issued 6/5/79.	GL	27237	Alvin Cronig 18708 Lomond Boulevard Shaker Heights, IL 44122

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S-64E; T.C. H6EA	SA3894WE	Installation of hoist pump (yoke type), P/N ACH60552L6. Issued 4/2/79.	WE	01770	Aero-Craft Hydraulics, Inc. 2428 West Carson Street Torrance, CA 90501
S-64E; T.C. H6EA	SA3895WE	Installation of auxiliary power unit (APU) starter motor, P/N ACH-3911-205SPCL. Issued 4/2/79.	WE	01770	Aero-Craft Hydraulics, Inc. 2428 West Carson Street Torrance, CA 90501
S-76A; T.C. H1NE	SH270WE	Installation of a Collins LRN-80 VLF/Omega navigation system as a means of navigation for enroute navigation within the 48 contiguous U.S. and D.C. Issued 4/4/80.	WE	24205	Collins General Aviation Division 3000 Airway Avenue Costa Mesa, AZ 92626
S-76A; T.C. H1NE	SH286GL	Install Norton Co. radome P/N AD-4082X-2 (Sikorsky P/N 76600-02110-101) or Norton radome P/N AD-4082X-10 (Sikorsky P/N 76600-02110-102). Amended 12/20/79.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
S-76A; T.C. H1NE	SH399GL	Installation of Astronautics helicopter 3Q flight director system. Issued 3/20/80.	GL	12375	Astronautics Corp. of America P.O. Box 523 Milwaukee, WI 53201
S-76A; T.C. H1NE	SH435GL	Installation of Astronautics helicopter 2Q flight director system. Issued 8/23/80.	GL	12375	Astronautics Corp. of America 907 South First Street Milwaukee, WI 53201

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
SPINKS INDUSTRIES, M.H. SPINKS, SR.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Rawdon T-1; T.C. 794	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Rissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
Rawdon T-1; T.C. 794	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
Rawdon T-1; T.C. 794	SA444CE	Conversion of Goodyear L6H/MBD wheel to Rawdon Brothers T2A-2650 wheel. Reissued 4/7/78.	SW	74600	Spinks Industries P.O. Box 11099 Ft. Worth, TX 76110
Rawdon T-1; T.C. 794	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

STINSON DIVISION, CONSOLIDATED VULTEE AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
L-1, L-5, -5B, -5C, -5D, -5E, -5E-1, -5G, SM-8-8A, SR-7A, -7B, -7C, SR-8A, -8B, -8C, -8D, -8E, SR-9A, -9B, -9C, -9D, -9DM, -9E, -9E(M), -9F, HW-75, 10, 10A, 10B, V-77; LTC-26, T.C. 764, 295, ATC 594, 608, 609, 621, 625, 640, T.C. 709, 738, 774	SA2666WE	Ceconite 102 material covering of: L-1, L-5 Series, SM-8-8A, SR-8A Series, SR-9A Series, HW-75, 10, 10A, B - complete aircraft; SR-7A Series - horizontal stabilizer, elevators and rudder; V-77 - fuselage and vertical stabilizer. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Los Angeles, CA 9006
L-5 Series; T.C. 764	SA4-763	Glass cloth applies to wings, fuselage, and ailerons.	WE	30860	Glasco-Air Products County Airport Oxnard, CA 93030
L-5 Series; T.C. 764	SA4-1036	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
L-5 Series; T.C. 764	SA2PC	Air to ground public address system.	PC	41274	Hawaii Wing, Civil Air Patrol P.O. Box 2722 Honolulu, HI 96820
L-5 Series; T.C. 764	SA340WE	Engine mount 2028 (restricted category only).	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
L-5, -5B, -5C, -5D, -5E-1, -5G, SM-8A, IR-S, V77, HW75, 10A, 10B; T.C. 764, 295, 423, 774, A709, 738	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
L-5; HW-75; 10A, 10B; T.C. A-764, A-709, A-738	SA798EA	Installation of MOnitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
L-5, -5B, -5C, -5D, -5E, -5E-1, -5C; SR-7A, -7B, -7C; SR-8A, -8B, -8C; SR-8D, -8E; SR9A, -9B, -9C; SR-9D, -9DM, -9E, -9E(M), SR-9F; HW-75, 10; 10A, 10B; V-77; L-1; T.C. 764, ATC 594, 608, 609, 621, 640, T.C. 709, 738, 774, LTC 26	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
JR. S; T.C. 423	SA4-890	Glass cloth applied on fuselage.	WE	30860	Glasco-Air Products 1125 First Street San Fernando, CA 93030
Jr. SR-4; T.C. 519	SA207WE	Removal of cabin doors for parachute jumping and aerial photography operations.	NW	16400	Marvin L. Bertram 1034 West Oregon Street Moses Lake, WA 98837
SR-6; T.C. 580	SA4-374	Glass cloth applied to wings, fuselage, flaps, and tail surfaces.	WE	30860	Glasco-Air Products County Airport Oxnard, CA 93030
SR-7 Series; T.C. 594	SA499WE	Ceconite 101 covering of horizontal stabilizer, elevators and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SR-8 Series; T.C. 608	SA4-665	Glass cloth applied over fuselage, wings, and horizontal and vertical stabilizers.	WE	30860	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
SR-8 Series; T.C. 608	SA320SO	Conversion of airplane for parachute jumping.	SO	52547	Luke's Flying Service Moncks Corner, SC 29461
SR-8 Series; T.C. 608, 609	SA707WE	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
SR-9 Series; T.C. 621, 625, 640	SA4-1388	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SR-9F; T.C. 640	SA4-1202	Glass cloth applied over fuselage, wings, empennage and control surfaces.	WE	30860	Glasco-Air Products 1125 First Street San Fernando, CA 93030
SR-10D, SR-10E; T.C. 679	SA4-50	Increased gross weight to 4,650 pounds, modified fuselage, and replacement of horizontal surfaces from SR-10F.	WE	84610	Wardlow Aircraft Company 611 14th Street Huntington Beach, CA 92646
SR-10F; T.C. 685	SA4-504	Swing-out type engine mount, carburetor air heat, engine cowl, oil cooler, carburetor air scoop, and fabrication and installation of oil tank.	WE	84611	Floyd M. Wardlow 1717 Park Street Huntington Beach, CA 92646
SR-10F; T.C. 685	SA4-505	Metalizing of wigngs, fuselage, horizontal and vertical stabilizers; installation of cargo door and fuselage truss, cockpit door, engine firewall, Stewart Warner 940-B heater, and Wilgit seat fastener.	WE	84611	Floyd M. Wardlow 1717 Park Street Huntington Beach, CA 92646
SR-10F; T.C. 685	SA4-506	Cessna T-50 tail wheel assembly.	WE	84611	Floyd M. Wardlow 1717 Park Street Huntington Beach, CA 92646
V-77; T.C. 774	SA1-34	Modification for camera installation.	EA	77568	L.S. Taylor Engineering Clarion, PA 16214
V-77; T.C. 774	SA4-428	Glass cloth with resin applied to all fabric surfaces except movable controls.	WE	30860	Glasco-Air Products County Airport Oxnard, CA 93030
V-77; T.C. 774	SA4-478	Ceconite 101 covering of fuselage and vertical stabilizer.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
t•1 V-77; T.C. 774	SA4-1620	Removal of cabin door for parachute jumping and aerial photography operations.	WE	62550	Lawrence Parks 2880 Kistake Lane Reno, NV 89501
V-77; T.C. 774	SA368CE	Replace wing rib stitches with P-K screws. Reissued 8/30/72.	SW	68440	William Roberts 326 Hawthorne Lane Grand Prairie, TX 75050
V-77 (Landplane only, normal category); T.C. A-774	SA2622WE	Installation of Pratt & Whitney R-985-39, -39A, -AN-1, -AN-3, or -AN14BM1 engine and Hamilton Standard 2D30/6101A-15 or -21 propeller. Issued 12/13/72.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
HW-75; T.C. 709	SA1008WE	Poly-fiber covering of airplane. Amended 2/1/67.	WE	75250	Stits Aviation Corporation Box 3084 Riverside, CA 92502
HW-75, 10; T.C. 709	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
HW-75, 10; T.C. 709	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
HW-75, 10; T.C. 709	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
HW-75, 10, 10A, 10B; T.C. 709, 738	SA4-1575	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
10; T.C. 709	SA4-184	Continental C-85-12F engine.	WE	21402	W.H. Chandler 1005 East Mariposa Street Altadena, CA 91001
10; T.C. 709	SA342SW	Lycoming O-235-C1 engine with Sensenich M76AM-2 propeller, associated powerplant changes and electrical changes.	SW	70386	James A. Schultze 1009 Edinburgh Lane Denton, TX 76201
10A; T.C. 738	SA3-63	Replacement of original center elevator hinge and bearing assembly by split bearing and split housing hinge assembly.	GL	35660	Vern E. Flanders 1018 East Olive Street Bloomington, IL 61701
10A; T.C. 738	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
SWEARINGEN AVIATION CORP.
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA26T; T.C. A5SW	SA418SO	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C. A5SW	SA461SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C. A5SW	SA571SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation each engine is limited to a maximum of 550 SHP. Issued 12/14/73.	SO	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
SA26T; T.C. A5SW	SA600WE	Install Hoskins Twilighter Mk IIIq supplemental lighting system with Model P wing tip and Model K tail light.	GL	42625	Hoskins, Inc. 34 North Bennett Geneva, IL 60134
SA26T; T.C. A5SW	SA764SW	Bendix M4C autopilot flight control system.	SO	15475	The Bendix Corporation P.O. Box 23430 Fort Lauderdale, FL 33309
SA26T; T.C. A5SW	SA1464WE	Installation of supporting structure and placards only for avionic components in the aft compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26T; T.C. A5SW	SA1465WE	Installation of supporting structure and placards only for avionic components in forward compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26-T, SA26-AT, (Merlin II); T.C. A5SW	SA600CE	Install Hoskins Twilighter Mk III supplemental lighting system with Model P wing tip and Model K tail light. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
SA26-T, SA26-AT, (Merlin II): T.C. A5SW	SA3057WE	Installation of fuel tank boost pump. Issued 7/17/75.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA26-T, SA26-AT, Merlin II; T.C. A5SW	SA3465WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA26-T, 26-AT, 226-T, 226-AT; T.C. A5SW	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SA226T; T.C. A5SW	SA1078SO	Installation of Bendix FCS-8700 automatic flight control system. Issued 6/5/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-T, SA226-AT; T.C. A5SW	SA254GL	Installation of emergency/continuous water-alcohol injection system. Amended 10/3/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
SA226-T, SA226-AT; T.C. A5SW	SA273GL	Installation of a Scenic exhaust assembly, P/N YR-12013 in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-T, SA226-AT; T.C. A5SW	SA613AL	Install nose wheel steering lock system. Issued 6/3/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502
SA226-T, SA226-AT; T.C. A5SW	SA2909WE	Installation of fuel tank boost pump. Amended 8/12/75.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA226-T, SA226-AT; T.C. A5SW	SA3481WE	Installation of recognition light on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA226-TC; T.C. A8SW	SA279GL	Installation of emergency/continuous water-alcohol injection system. Issued 11/1/78.	GL	07503	AiReserach Aviation Company Capital Airport Springfield, IL 62705
SA226-TC; T.C. A8SW	SA189GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA615AL	Install nose wheel steering lock system. Issued 6/21/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502
SA226-TC; T.C. A8SW	SA1068CE	Installation of Collins Radio Co. AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-TC; T.C. A8SW	SA1582CE	Installation of Collins FCS-150 automatic flight control system. Issued 4/2/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
SA226-TC; T.C. A8SW	SA2910WE	Installation of fuel tank boost pump. Issued 7/23/74.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA226-TC; T.C. A8SW	SA3482WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA226T (S/N T-201 and up), SA226AT (S/N AT-001 and up); T.C. A5SW	SA972CE	Installation of AID battery temperature sensing and over temperature warning system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT; T.C. A5SW	SA188GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA274GL	Installation of a Scenic exhaust assembly, P/N YR-12013, in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-AT; T.C. A5SW	SA1051CE	Installation of Collins Radio Co. AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-AT; T.C. A5SW	SA1575SW	Battery isolation system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1576SW	Ray Electronics Model 7107 battery fault warning system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1577SW	Collins FCS-105 automatic/flight director system with Sperry dual flight director system. Issued 1/26/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1673SW	Battery isolation system. Issued 6/11/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA2344WE	Installation of Collins Radio Co. Model FCS-10583 autopilot flight flight director systems. Reissued 8/20/71.	CE	24250	Collins Radio Company 855 - 35th Street, N.E. Cedar Rapids, IA 52406
SA226-AT; T.C. A5SW	SA2860WE	Installation of AiResearch TPE 331-3U-307G engines and propeller synchrophasing. Issued 3/21/74.	WE	07502	AiResearch Manufacturing Company of Arizona 402 South 36th Street Phoenix, AZ 85034
SA226-AT; T.C. A5SW	SA3075WE	Installation of Garrett AirNav 100 area navigation system. Issued 10/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T(B); T.C. A5SW	SA338GL-D	Installation of continuous water alcohol injection system. Amended 8/4/80.	GL	07499	AiResearch Aviation Company Capital Airport Springfield, IL 62705

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA226-T(B); T.C. A5SW	SA1166EA	Installation of Litton LTN211 Omega navigation system. Amended 4/15/80.	EA	78412	Teterboro Aircraft Service, Inc. 401 Industrial Avenue Teterboro, NJ 07608
SA226-T(B); T.C. A5SW	SA1167EA	Installation of Collins ADS-80 air data system. Amended 4/15/80.	EA	78412	Teterboro Aircraft Service, Inc. 401 Industrial Avenue Teterboro, NJ 07608
SA226-T; T.C. A5SW	SA1238SW	Bendix M-4C automatic flight control system. Issued 12/22/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-T; T.C. A5SW	SA1241SW	Installation of supporting structure, avionics components and systems. Issued 1/6/71.	WE	07500	AiResearch Aviaiton Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1271SW	Collins AP105 automatic flight control system. Issued 3/16/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1600SW	Battery isolation system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1601SW	Ray Electronics Model 7107 battery fault warning system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1602SW	Collins AP105 automatic flight control system with dual Sperry Stars flight directors. Issued 2/6/73.	WE	07500	AiResearch Aviation Company 6201 WEst Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA2864WE	Modification to install electrical and structural provisions for Texas Instrument, Inc. infra-red scanner system. Issued 4/25/74.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T, SA226-T(B); T.C. A5SW	SA804SO	Installation of Bendix M-4D automatic flight control system, including integration into the existing Swearingen pitch trim and yaw damping systems. Amended 12/14/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226T, SA226AT; T.C. A5SW	SA2428WE	Installation of Hoskins/SDI Twilighter MK III supplemental lighting system. Issued 10/50/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226TC (S/N TC-201 and up); T.C. A8SW	SA973CE	Installation of AID battery temperature sensing and over-temperature sensing system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA821SO	Installation of Bendix M-4D automatic flight control system including optional flight director system and integration into existing Swearingen pitch trim system. Issued 1/29/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA1247SW	Bendix M-4C autopilot. Reissued 8/2/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

TAYLORCRAFT AVIATION CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BC Series; T.C. 696	SA1-217	Replacing original lacing for securing fabric to wings with screws and washers.	EA	19836	Capital Air Service, Inc. P.O. Box 467 Dover, DE 19901
BC Series; T.C. 696	SA4-294	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
BC Series; T.C. 696	SA4-613	Fiberglass wheel pants and mounting brackets of metal.	NW	82390	Richard Van Grunsven Route 2, Box 187 Forest Grove, OR 97116
BC Series; T.C. 696	SA4-830	Fiberglass covering on wings.	WE	38060	Glasco-Air Products County Airport Oxnard, CA 93030
BC Series; T.C. 696	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
BC Series; T.C. 696	SA4-906	Ceconite 101 covering of complete airframe. Amended 12/15/66.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
BC Series; T.C. 696	SA4-1346	Fiberglass covering on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
BC Series; T.C. 696	SA4-1438	Eronite covering of fuselage.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
BC Series; T.C. 696	SA208WE	Removal of right cabin door for parachute jumping and aerial photography operations.	RM	38040	Glacier View Skyways, Inc. P.O. Box 252 Kalispell, MT 59901
BC Series; T.C. 696	SA1008WE	Poly-Fiber covering of wings and ailerons. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
BC, BC12D; T.C. A-696	SA1-210	Conversion of Taylorcraft Model BC or Model BC12D to the equivalent of the following aircraft models: Model BC12D85 and Model BC12D-4-85 or Model 19. Amended 6/14/71.	EA	37882	Gilberti Aviation P.O. Box 246 Aliquippa, PA 15001
BC, BC-65, -12-65, -12D, -12D1, -12D-85, BCS, BCS-65, -12-65, -12D, -12D1, -12D-85, -12D-4, 85; T.C. 696	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC, -65, 12-65, -D, -D1, 12D-84, -4-85; BCS, -65, -12-65-D, -D1, -4-85; BC Series (Army L-2H); T.C. 696	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC, BCS, BC-65, S-65, 12-65, S12-65, 12D, S12-D, 12-D1, S12-D1, 12D-85, 12D-4-85; T.C. 696	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC, BCS, BC-65, BCS-65, BC12-65, BCS12-65, BC12D, BCS12-D, BC12-D1, BC12D-85, BC12D-4-85, BC12DS-4-85; T.C. 696	SA2666WE	Ceconite 102 material covering on complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC Series, 19; T.C. 696, 1A9	SA1-95	Wing lift struts to include a hydraulic-pneumatic shock absorber.	EA	86500	Wings With Springs, Inc. R.D. 3, Box 495 Latrobe, PA 15650

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BC Series, 19; T.C. 696, 1A9	SA4-1200	Delco-Remy generator 1101879 and regulator 1118384.	RM	81060	Universal Aircraft Industries P.O. Box 5306 Denver, CO 80217
BC Series, 19; T.C. 696, 1A9	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
BC-65, BCS-65, BC12-65, BCS12-65, BC12-D, BC12-D1, BC12D-85, BCS12D-85, BC12D-4-85, BCS12D-4-85, DC-65, DCO-65; T.C. A696	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	56600	D.H. Matney d/b/a Matney's Aircraft Service 24415 116th S.E. Kent, WA 98031
BC, BC-65, -12D, -12D1, BC12D-85, BCS12D-85, BC12D-4-85, 19; T.C. A-696, 1A9	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BC, BC-65, -12D, -12D1, BC12D-85, BCS12D-85, BC12D-4-85, 19; T.C. A-696, 1A9	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
BC-12D; T.C. 696	SA2-225	Windshield manufactured in accordance with Luminous Plastics, Drawing No. LP-650. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
BC12D; T.C. 696	SA661AL	Installation of plexiglass skylight in fuselage cabin. Issued 1/10/79.	AL	23130	Gregory H. Clayton Box 73204 Fairbanks, AK 99707
BC12D; T.C. 696	SA1901SW	Clipped wings, revised control system, added aileron, and elevator servo tabs. Issued 8/20/74.	SW	77125	Michael Swick Route 1, Box 163 Plano, TX 75074
BC12D; T.C. A696	SA2891SW	Installation of stick type control system. Issued 12/20/78.	SW	77124	Swick Aircraft Route 3, Box 163B Lewisville, TX 75067
BC12D; T.C. A-696	SA4108SW	Use of Piper metal spars to replace original wood spars. Issued 3/13/80.	SW	77125	Swick Aircraft Route 1, Box 128B McKinney, TX 75069
19; T.C. 1A9	SA90NW	Installation of Continental O-200-A engine, McCauley propeller IA100MCM/6950, and sub-systems. Issued 2/26/74.	NW	35740	Ronald W. Flinchbaugh 8265 Custer Road Tacoma, WA 98499
F19; T.C. 1A9	SA1070SO	Installation of Aqua Model 1500 floats. Issued 5/3/79.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
F19; T.C. 1A9	SA1129EA	Installation of PK Model 1800 or B1800 (TSO-C27) seaplane floats. Issued 9/7/78.	EA	29998	DeVore Aviation Corporation PK Floats 206 Newton Road Plainview, NY 11803

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
TAYLORCRAFT, INC.
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC Series; T.C. 746	SA1-86	McCauley metal fixed-pitch propeller 1B90-CM on aircraft powered by Continental A-65 engine.	EA	16575	Beth-Air Consulting 8618 Garfield Street Bethesda, MD 20014
DC Series; T.C. 746	SA3-43	Fiberglass fabric application to fuselage, wings and fixed tail surfaces.	CE	42330	Elmer Hopson 2451 Chelsea Kansas City, MO 64108
DC Series; T.C. 746	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
DC Series; T.C. 746	SA4-856	Glass cloth applied over wings and horizontal stabilizer.	WE	38060	Glasco-Air Products 1125 First Street San Fernando, CA 93030
DC Series; T.C. 746	SA4-1527	Ceconite 101 covering of wings and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC Series; T.C. 746	SA391SO	Installation of glass fabric covering on entire aircraft.	SO	55775	K.R. Martin Route 2 Ellenwood, GA 30049
DC, DCO, DF, DL (Army L-2); T.C. 746	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BF Series; T.C. A-699	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
Model A; T.C. 643	SA1008WE	Installation of poly-fiber covering material of complete aircraft. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
A, BF, BL Series; T.C. 643, 699, 700	SA4-906	Ceconite 101 covering of complete airframe. Amended 12/15/66.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
DC-65, DCO-65, DF-65, DL-65, A, BL, BLS, BL-65, BLS-65, BL-12-65, BLS-12-65; T.C. 746, 643, 700	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
DCO-65, 15A, 20, BF, BFS, BF-60, -65, BFS-60, -65, BF12-65, BFS12-65, BL, BLS, BL-65, BLS-65, BL12-65, BLS12-65; T.C. 746, 3A3, 699, 700	SA2666WE	Ceconite 102 material covering of: DCO-65 - wings and ailerons; 20 - wings; 15A, BF Series, BL Series - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
15A, 20; T.C. 3A3	SA3-423	CT-3000 tail ski on airplanes equipped with Scott Model 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
15A, 20; BF, BF-60, -65, BFS, BFS60, BF-12; BL, BL-65, BS12-65, BLS-65, BLS12-65; DC-65, DF-65, DCO-65; T.C. A-699, A-700, A-746	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
15A, 20; BF, BF-60, -65, BFS, BFS60, BF-12; BL, BL-65 BL12-65, BLS-65, BLS12-65; DC-65, DF-65, DCO-65; T.C. A-699, A-700, A-746	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
15A, 20; A; BF; BL; DC-65, DCO-65; FA-111; T.C. 3A3, A-699, A-700, A-746, 1A11	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
15A, 20, BL12-65, S12-65, BL, BLS, B1-65, BLS-65, BF, BFS, -60, -65, BFS-60, -65, 12-65, S12-65; DCO-65; T.C. 3A3, 700, 699, 746	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
20; T.C. 3A3	SA257WE	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
BF, BL Series; T.C. 699, 700	SA4-1346	Fiberglass covering on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
BF, BL Series; T.C. 699, 700	SA4-1438	Econite covering of fuselage.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
BL Series; T.C. 700	SA4-162	Glass cloth applied over old fabric with the exception of all flight control surfaces.	WE	85720	Whitehall Pacific Aviation, Inc. P.O. Box 3174 Ventura, CA 93001
BL, DC Series; T.C. 700, 746	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATIO

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

UNIVAIR AIRCRAFT CORP.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
108 Series; T.C. 767	SA1-10	Replacement of wing fabric with 24 ST. alclad skin.	EA	05972	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
108 Series; T.C. 767	SA1-48	Edo 249-2870 floats.	EA	16857	James R. Blakely P.O. Box 53 Westchester Station Bronx, NY 10461
108 Series; T.C. 767	SA1-374	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
108 Series; T.C. 767	SA1-258	Conversion of aileron covering from fabric to alclad panels.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047
108 Series; T.C. 767	SA3-27	Covering of wings .020-inch 24 ST. alclad.	GL	42860	Howard Aviation, Inc. P.O. Box 1287 Peoria, IL 61601
108 Series; T.C. 767	SA3-398	Fiberglass plastic covering of all fabric surfaces.	GL	34291	John H. Fallon 601 Woodward Heights Boulevard Ferndale, MI 48220
108 Series; T.C. 767	SA3-423	Model CT-3000 tail ski on airplanes equipped with Scott Model 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
108 Series; T.C. 767	SA3-606	Complete recover of all fabric surfaces with dacron fabric.	GL	30518	Downer Aircraft Industries, Inc. Alexandria, MN 56308
108 Series; T.C. 767	SA4-46	Lycoming O-435-1 engine, accessories, and Hartzell HC-12X20-8D propeller.	WE	71000	Serv-Aero Engineering, Inc. P.O. Box 96 Dos Palos, CA 93620
108 Series; T.C. 767	SA4-148	Conversion of aircraft electrical system to 24 volts and/or installation of Franklin 6A4-165-B3 engine. Reissued 10/5/79.	WE	18125	Dean D. Brubaker P.O. Box 84409 861 South Bringham Avenue Los Angeles, CA 90073
108 Series; T.C. 767	SA4-224	Application of fiberglass covering.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
108 Series; T.C. 767	SA4-284	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
108 Series; T.C. 767	SA4-630	Eonite covering of wings, fuselage and ailerons.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
108 Series; T.C. 767	SA4-760	Ceconite 101 covering of wings, fuselage and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
108 Series; T.C. 767	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage, and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
108 Series; T.C. 767	SA4-1195	Metalized wings.	WE	08223	Air-Mod 11379 Playa Street Culver City, CA 90230
108 Series; T.C. 767	SA4-1415	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
108 Series; T.C. 767	SA4-1484	Sheet metal on wings.	WE	33910	Robert B. Everitt 2134 Xavier Santa Clara, CA 95050
108 Series; T.C. 767	SA58EA	Conversion of airplane for parachute jumping and aerial photography operations.	NE	31368	East Coast Aviation Corp. Hanscom Field Lexington, MA 02173

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
108 Series; T.C. 767	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743
108 Series; T.C. 767	SA224SO	Removal of right door for parachute jumping and aerial photography operations.	SO	14760	Robert V. Barham 1984 Capri Drive Decatur, GA 30030
108 Series; T.C. 767	SA228WE	Removal of right cabin door for parachute jumping and aerial photography operations.	WE	40690	John C. Harrison 2535 Garfield Avenue Carmichael, CA 95608
108 Series; T.C. 767	SA327SO	Tricycle landing gear and Lycoming O-435 engine.	SO	68550	W.F. Robinson P.O. Box 241 Lanett, AL 36863
108 Series; T.C. 767	SA343WE	8:50X6 4-ply aircraft tires and 8:50X6 tubes.	NW	60172	Rex H. Morehouse 4922 Summers Lane Klamath Falls, OR 97601
108 Series; T.C. 767	SA463CE	Metal fuselage covering.	CE	84399	David E. Waldemer Flying W Ranch Fairdealing, MO 63939
108 Series; T.C. 767	SA515CE	Install metal wing covering.	CE	84399	David E. Waldemer Flying W Ranch Fairdealing, MO 63936
108 Series; T.C. A-767	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
108 Series; T.C. 767	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
108 Series; T.C. 767	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
108, 108-1, -2, -3; T.C. 767	SA3-366	Installation of FluiDyne (Fli-lite) Model 3000 main skis and Model 1000 tail skis. Reissued 7/22/79.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
t+1 108, 108-1, -2, -3; T.C. 767	SA615SO	Surface fabric attachment clips. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
108, 108-1, -2, -3; T.C. 767	SA859SO	Replacement of generator P/N 1101877 installed in Franklin 6A-150 and -165 engines with a modified Motorola RA12N550 alternator. Issued 10/20/75.	SO	15240	Stanley C. Bedford 2396 Santa Cruz Drive Clearwater, FL 33516
108, 108-1, -2, -3, -4, -5; T.C. A-767	SA800EA	Installation of aviation white anti-collision strobe lights, Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
108 Series, 415C, 415CD, 415D, E, G; T.C. 767, 718, 787	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Stinson) 108-1, -2, -3, -4, -5, (Erco, Alon) 415-C, -CD, 415-D, -E, -G; T.C. 767, 718, 787	SA2666WE	Ceconite 102 material covering of: 108 Series - wings, fuselage and ailerons; 415 Series - wings. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
108, 108-1, -2, -3, -4, -5, 415C, -CD, 415-D, E, G; T.C. A-767, 718, 787	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
108, 108-1, -2, -3, -5; T.C. 767	SA799WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheel assemblies in lieu of Firestone wheel assembly No. DFA 180. (DGA-2000 wheel approved under TSO-C26a.) Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
108 Series, A-2, A-2A, 415D, E, G, F-1, F-1A, M-10; T.C. 767, A-787	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
108 Series, 415; T.C. 767, 718, 787	SA1008WE	Poly-Fiber covering of left and right-hand aileron. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
108 Series, F-1, F-1A; T.C. 767, 787	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Av Torrance, CA 90510
108 Series, 415C; T.C. 767, 718	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
108-1, -2, -3, 415C, -CD, F-1, F-1A, 415D, E, G, A-2, A-2A; T.C. 767, 718, 787	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South HOlly Street Littleton, CO 80120
108, -1, -2, -3, -5, 415-C, -CD, A-2, A-2A, 415D, E, G, F-1, -1A, M10; T.C. 767, 718, 787	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
108, -1, -2, -3, -5, 415-C, -CD, A-2, A-2A, 415D, E, G, F-1, -1A, M10; T.C. 767, 718, 787	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
108-2, 108-3 (Landplane); T.C. 767	SA4-398	Installation of Lycoming O-435-C engine. Amended 7/10/75.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
108-2, 108-3; Land and Seaplanes; T.C. A-767	SA1199WE	Installation of Continental O-470-A, -J, -K, -L or -R engine and McCauley 2A34C/90A or 2A36C/90M propellers; or O-470A, -J, -K, or -L engine and Hartzell HC-A2XF-1/8433 or BHC-A2XF-1/8433 propellers, or O-470-R engine and Hartzell BHC-C2Y/8468 propeller. Amended 1/12/73.	NW	63500	PDX Aircraft Corporation 1906 Northeast Liberty Street Portland, OR 97211
108-3; T.C. A767	SA74NW	Install floats Edo. Issued October 1973.	NW	63500	PDX Aircraft Corporation 1906 Northeast Liberty Street Portland, OR 97211
108-3; T.C. A767	SA91NW	Installation of strobe light system with flashtube on rudder tip and power supply in fuselage. Amended 3/11/74.	NW	70384	R.J. Schroers 4479 139th Avenue SE Bellevue, WA 98006
108-3; T.C. A-767	SA238NW	Installation of Madras Air Service super tips. Issued 11/25/75.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
108-3; T.C. A-767	SA313NW	Installation of Franklin 6A-350-C1 engine and Hartzell HC-C2YF-1BF/F8459-4 to -8 propeller; also, McCauley 2A31C21/8456.	NW	70620	Seaplane Flying, Inc. 1111 S. E. Fifth Street Vancouver, WA 98661
108-3; T.C. A-767	SA637NW	Installation of oil filter assembly OF-104A. Issued 7/13/78.	NW	70620	Seaplane Flying, Inc. P.O. Box 2164 Vancouver, WA 98661
415 Series; T.C. 718, 787	SA1-4	Metal covering of outer wing panels.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047
415 Series; T.C. 718, 787	SA1-78	Metal skin replacement on wing surfaces.	EA	78623	George Townson P.O. Box 541 Meadowbrook, PA 19046

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
415 Series; T.C. 718, 787	SA1-208	Two 4595 100-watt General Electric sealed beam landing lights in nose cowling.	EA	08340	Air Service, Inc. P.O. Box 189 New Castle, DE 19720
415 Series; T.C. 718, 787	SA1-336	Continental C-90-14F engine and McCauley 1B90-CM7152 propeller.	EA	84925	Richard W. Weibley Skyport, P.O. Box 1229 Harrisburg, PA 17105
415 Series; T.C. 718, 787	SA1-440	Continental C90-12F engine.	EA	84925	Richard W. Weibley Skyport, P.O. Box 1229 Harrisburg, PA 17105
415 Series; T.C. 718, 787	SA3-19	Steel tube and aluminum covered hatch doors fabricated with plexiglass windows.	GL	01865	Aerodyne Products 2004 South 29th Street Milwaukee, WI 53202
415 Series; T.C. 718, 787	SA3-342	Metal 0.020-inch 20 24 ST 3 or 20 24 ST 4 alclad aluminum.	CE	60174	John J. Morelli Route 6, Box 428 Parkville, MO
415 Series; T.C. 718, 787	SA3-512	Aluminum alloy skin.	GL	28565	Robert B. Dale 30030 Minglewood Lane Farmington, MI 48024
415 Series; T.C. 718, 787	SA3-598	Metal 0.020 24ST aluminum on wings.	GL	86202	Harvey A. Williams 1446 North Lockwood Avenue Chicago, IL 60607
415 Series; T.C. 787	SA4-73	Metal skins 0.020 24ST and/or 75ST aluminum alloy.	WE	29160	Vern Dell Aircraft Metal Work Co. P.O. Box 42 Chula Vista, CA 92010
415 Series; T.C. 718, 787	SA4-139	Glass cloth over old fabric.	WE	85720	Whitehall Pacific Aviation, Inc. P.O. Box 31174 Ventura, CA 93001
415 Series; T.C. 718, 787	SA4-179	Fabric covering replaced with metal 0.020 24ST and/or 75ST aluminum alloy covering.	WE	29160	Vern Dell Aircraft Metal Work Co. P.O. Box 42 Chula Vista, CA 92010
415 Series; T.C. 718, 787	SA4-285	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
415 Series; T.C. 718, 787	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
415 Series; T.C. 718, 787	SA4-361	Aluminum alloy sheet on wings.	WE	19900	Carma Manufacturing Company P.O. Box 11312 Tucson, AZ 85700
415 Series; T.C. 718, 787	SA4-399	Metallizing of wings.	WE	77520	L.J. Tarnay 9314 Glasgow Place Los Angele, CA 90052
415 Series; T.C. 718, 787	SA4-441	New lower engine cowl made of fiberglass with Hetron #92 resin.	WE	78471	Wilbur Thompson 10617 South Prairie Avenue Inglewood, CA 90306
415 Series; T.C. 718, 787	SA4-448	New nose cowl made of fiberglass reinforced with Hetron #92 resin.	WE	78471	Wilbur Thompson 10617 South Prairie Avenue Inglewood, CA 90306
415 Series; T.C. 718, 787	SA4-729	Mounting brackets, flush window, and wiring to operate automotive type sealed-beam headlamp as a dual purpose landing and taxi light.	WE	01804	Aero Development Corporation P.O. Box 11201 Tucson, AZ 85706
415 Series; T.C. 718, 787	SA4-801	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
415 Series; T.C. 718, 787	SA4-839	Metal covering of wings.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series; T.C. 718, 787	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
415 Series; T.C. 718, 787	SA4-1652	Tapered roller bearing and plate on right-hand wheel half.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series; T.C. 718, 787	SA117WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
415 Series; T.C. 718, 787	SA162SO	Aileron trim system.	SO	03122	Aerotronics, Inc. Miami Beach, FL 33139

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
415 Series; T.C. 718, 787	SA341WE	Engine mount to remove down thrust and change horizontal tail incident.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series; T.C. 718, 787	SA465WE	Continental C-90-12F engine and McCauley 1B90-CM propeller.	WE	22218	R.B. Christianson 10510-1/2 Mather Avenue Sunland, CA 91040
415 Series, F-1; T.C. 718, 787	SA4-638	Single arm nose wheel fork with conventional double arm fabricated fork U415-34090-1-A and B.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
415 Series, F-1, F-1A; T.C. 718, 787	SA4-1254	Main gear wheel fairings, nose gear wheel fairing.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90275
415 Series, F-1, -1A; T.C. 718, 787	SA4-1606	Wing root fillets change from aluminum 3S and 24ST3 to fiberglass.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series, F-1, -1A; T.C. 718, 787	SA1WE	Fiberglass tail cone.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series, F-1, -1A; T.C. 718, 787	SA3WE	Fiberglass reinforced plastic engine cowl.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415-C, 415-CD, S/N 813 and up; T.C. A-718	SA120GL	Install Cleveland Wheel and Brakes conversion kit, P/N 199-69. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
415-C, 415-CD; T.C. A-718	SA330GL	Installation of Skyport Model SMK-15, 9-cu.ft. baggage compartment. Issued 7/18/79.	GL	36566	Skyport Aircoupe Services Division Fox Engineering Company 1340 Francis Street Jackson, MI 49203
415C, S/N 113 thru 812; T.C. A-718	SA2185WE	Installation of main gear wheel fairings and/or nose gear wheel fairing (nose gear fork P/N 415-34096 required for latter installation). (These fairings eligible for installation separately or in conjunction.) Issued 6/9/70.	WE	47750	Kenney Engineering 4120 Via Solano Pales Verdes Estates, CA 90274
415C, S/N 113 thru 812; T.C. A-718	SA3293WE	Installation of McCauley 1B90CM7351 propeller on aircraft equipped with Continental C-75-12 engine. Issued 11/15/76.	WE	39820	Ronald T. Hagerman
(Erco) 415-C, 415-CD; T.C. A-718	SA3502WE	Installation of fiberglass nose bowl. Issued 10/7/77.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
415C, -CD, -D, -E, -G, F-1, F-1A; T.C. A-718, A-787	SA319WE	Metal cover of wings in accordance with Air Fab Drawing No. 104, Rev. No. 1. Reissued 7/29/71.	RM	81000	Univair Aircraft Corporation Route 3, box 59 Aurora, CO 80010
415C, -CD, -D, -E, -G, F-1, F-1A; T.C. A-718, A-787	SA437WE	Installation of leading edge landing light in accordance with Air Fab Drawing No. 1011. Reissued 7/29/71.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80010
415C, 415CD, 415D, E, G; F-1, F-1A; A-2, A2-A, M10; T.C. A-718, A-787	SA2462WE	(1) Installation of main gear wheel fairings; (2) installation of nose gear wheel fairings. (These items eligible for installation separately or in conjunction with each other.) Issued 3/3/72.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
415D; T.C. A-787	SA5GL	Removal of fuselage fuel tank. Issued 10/3/72.	GL	28790	Norvel O. Dasher Route 1, Box 61 Elgin, IL 60120
415D; T.C. A787	SA381SO	Revised (1) brake handle per Drawing 9R, (2) seat belt anchor straps to seat per Drawing 10R, (3) rudder control system springs per Drawing 11R. Amended 3/14/68.	SO	68550	W.F. Robinson P.O. Box 241 Lanett, AL 36863
415D; T.C. A787	SA2628WE	Installation of Continental O-200-A engine, McCauley 1A101/DCM 6948 propeller, electric fuel transfer pump and associated changes. Amended 2/25/74.	WE	78624	Towns Aviation Service, Inc. 1800 West Deer Valley Road Phoenix, AZ 85027

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
415-D, E, G, (Erco) (Forney) F-1, F-1A; T.C. A-787	SA127GL	Install Cleveland Wheel and Brakes conversion kit, P/N 199-69. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
415-D, E, G, F-1, F-1A; T.C. A-787	SA331GL	Install Skyport Model SMK-15, 9-cu.ft. baggage compartment. Issued 7/18/79.	GL	36566	Skyport Aircoupe Services Division Fox Engineering Company 1340 Francis Street Jackson, MI 49203
(Erco) 415-D, E, G, F-1, F-1A, A-2, A2-A, M10; T.C. A-787 t•1	SA3503WE	Installation of fiberglass nose bowl.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
A-2; T.C. 787	SA1126WE	B2S autopilot.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
A-2; T.C. 787	SA1495WE	Installation of Brittain Model B2C flight control system.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
A-2, A2-A, M-10; T.C. A-787	SA2230WE	Installation of main gear wheel fairings on models equipped with "spring gear" main landing gear assemblies; also installation of nose gear wheel fairings. (These items eligible for installation separately or in conjunction with each other.) Amended 3/17/72.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
F-1, F-1A; T.C. 787	SA4-1590	Riveted fuel tanks changed to welded wing and nose tank assemblies and gauge from mechanical to electric float type.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
(Alon) A-2, A-2A, (Forney) F1, F-1A, (Mooney) M10; T.C. A-787	SA71GL	Install BA-4106 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
UNIVERSAL AIRCRAFT INDUSTRIES
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
GC-1 Series; T.C. 766	SA1512WE	Installation of gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
GC-1 Series; T.C. 766	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
GC-1A, GC-1B; T.C. 766	SA2-226	Windshield manufactured in accordance with Luminous Plastics. Reissued 4/9/79.	EA	52500	LP Aero Plastics, Inc. RD #1, Box 201B Jeanette, PA 15644
GC-1A, GC-1B; T.C. 766	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Blvd. Riverside, CA 92502
GC-1A, GC-1B; T.C. 766	SA4-403	GC 1-1 heavy duty "bubble" windshield. Reissued 6/4/73.	WE	07000	Aircraft Windshield Company 3842 Catalina Street Los Alamitos, CA 90720
GC-1A, GC-1B; T.C. 766	SA4-761	GC-1-3 heavy duty "bubble" windshield. REissued 6/4/73.	WE	0700	Aircraft Windshield Company 3842 Catalina Street Los Alamitos, CA 90720
GC-1A, GC-1B; T.C. 766	SA4-1200	Delco-Remy generator 1101879 and regulator 1118384.	RM	81060	Universal Aircraft Ind. P.O. Box 5306 Denver, CO 80217
GC-1A, GC-1B; T.C. A-766	SA23L	Installation of wheel and brake assemblies and axle spacer. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
GC-1A, GC-1B T.C. 766	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	5660	D. H. Matney d/b/a Matney's Acft. Ser. 24415 116th S. E. Kent, WA 98031
GC-1A, GC-1B; T.C. 766	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
GC-1A, GC-1B; T.C. 766	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
GC-1A, GC-1B: T.C. 766	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21328 Grace Ave. Torrance, CA 90510
GC-1A, -1B; T.C. A-766	SA2321WE	Installation of smooth skins with internal chordwise stringers for outboard wing panel in lieu of beaded skins. Issued 3/15/71.	WE	58630	Jess H. Meyers 8427 Lilienthal Ave. Los Angeles, CA 90045
GC-1A, -1B; T.C. A-766	SA2996SW	Brittain Model BSS stability augmentation system. Issued 5/16/79.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
GC-1A, -1B; T.C. A-766	SA3088SW-D	Mitchell automatic flight system AK564 cons. of Century I autopilot w/opt. omni tracker. Issued 12/3/75.	SW	6000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
GC-1A, GC-1B; T.C. A-766	SA4011WE	Installation of extended length gear door fairings. Issued 8/24/79.	WE	51096	Charles F. Lischer, Jr. 1732 Ano Nuevo Diamond Bar, CA 91765
GC-1B; T.C. 766	SA1-326	Continential 0-300-A engine with McCauley 1A170-DM7359 propeller and Cessna AK7053-3 spinner.	EA	64500	Piedmont Aviation, Inc. Route 2, Woodrun Field Roanoke, VA 24001
GC-1B;	SA1-335	Sensenich 62-inch pitch propeller M74DR-1 on aircraft equipped with Continental C-145-2 engine.	EA	21100	Rudolph Chalow R.D. 1 Newfield, N.J. 08344
GC-1B; T.C. 766	SA3-267	Narco Omnigator with (VIR-1) transmitter-receiver unit and (V12 MP-2) power unit.	CE	16858	Delmar G. Blodgett 3 Pan Drive St. Charles, MO. 63301
GC-1B; T.C. 766	SA4-145	Continental C-145-2, 0-300-A, or -B engine & Universal F200/0073-E, F200-H/0073-E, or McCauley 1A170DM/7361 propeller. Amended 9/24/75.	WE	16860	M. E. Bodell 23804 Pennsylvania Ave. Torrance, CA 90501
GC-1B; T.C. 766	SA4-156	Slightly modified Bonanza wing tips.	WE	16860	M. E. Bodell 23804 Pennsylvania Ave. Torrance, CA 90501
GC-1B; T.C. 766	SA4-157	Relocation of trim control handle to left side of fuselage about 9 inches below window & about 9 inches to rear of instrument panel.	WE	16860	M. E. Bodell 23804 Pennsylvania Ave. Torrance, CA 90501
GC-1B; T.C. 766	SA4-395	Fiberglas wing tips.	WE	79955	Wendell Willard Tweed 5726 Buffalo Ave. Van Nuys, CA 91408
GC-1B; T.C. 766	SA53NW	Installation of Continental IO-360-C engine with McCauley propeller. Issued 6/20/73.	NW	52625	MACHen, Inc. Box 412 Spokane, WA 99211
GC-1B; T.C. 766	SA60WE	Continental 0-300-A engine.	WE	81790	Vaeth Aircraft Repair 13th and Benson Streets Upland, CA 91786
GC-1B; T.C. 766	SA68SO	Down-draft cowling and baffles. Amended 11/22/78.	WE	77127	Swift Alturair 1780 Joe Crosson Drive El Cajon, CA 92026
GC-1B; T.C. 766	SA124CE	Rear seat and/or instrument panel.	CE	76615	Charles L. Stuteaman Wheeler Rd., Route 31 Kansas City, MO 64108
GC-1B; T.C. 766	SA149CE	Relocation of battery and removal of tail ballast.	GL	16857	Ernest R. Blatchley 132 Seminole Dr. West Lafayette, IN 47906
GC-1B; T.C. 766	SA167NW	Installation of access door aft of luggage compartment. Issued 3/25/75.	NW	52625	MACHen, Inc. South 3410 Davidson Blvd. Spokane, WA 99204
GC-1B; T.C. 766	SA169NW	Installation of modifield Bosch 4 pole electric motor & adapter plate as a replacement drive motor to the hydraulic system. Issued 3/28/75.	NW	52625	MACHen, Inc. South 3410 Davidson Blvd. Spokane, WA 99204
GC-1B; T.C. 766	SA203NW	Installation of Franklin 6A-350-C1 engine and McCauley 2A34C22/SF84-10 propeller. Issued 9/16/75.	NW	52625	MACHen, Inc. South 3410 Davidson Boulevard Spokane, WA 99204
GC-1B; T.C. 766	SA255SO	Auxiliary fuel tanks. Reissued 6/73.	WE	77130	Swift Tech Co. P.O. Box "p" Santee, CA 92071
GC-1B; T.C. A-766	SA275NW	Installation of Continental IO-360-D engine and McCauley D2A34C67/76C-2 propeller.	NW	52625	MACHen, Inc. South 3410 Davidson Boulevard Spokane, WA 99204
GC-1B; T.C. 766	SA313WE	Dowty Equpment Co. hand pump.	WE	67115	Rendco 1021 W. Holguin Lancaster, CA 93534
GC-1B; T.C. 766	SA345SO	Electric fuel pump Piper P/N 48-666; cockpit hatch & side glasses with fiberglas canopy. Reissued 3/1/73.	EA	49220	Paul B. Lacy III Route 1 Covington, VA 24426

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
WACO AIRCRAFT COMPANY
DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
UPF-7, VPF-7, ARE, HRE, SRE; T.C. 642, 714	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
ARE, HRE, SRE; T.C. 714	SA4-1212	Eonite covering on elevators, rudder and vertical stabilizer.	WE	52090	William C. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
EGC-8; T.C. 665	SA317CE	Remove left or right or both cabin doors.	CE	75116	Joseph B. Stevinson 5905 Locust St. Kansas City, MO 64110
RNF; T.C. 311	SA4-1289	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
RNF; UBF; UPF-7, VPF-7; UEC, UIC, YKS-7, ZKS-7; ATC 311, 473, T.C. 642, 626	SA1352WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
RNF, UBF, UEC, UIC, VPF-7, ZKS-7; ATC 311, 473, 467, 499, T.C. 642, 626	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
UBF; T.C. 473	SA628WE	Ceconite 101 covering of entire airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
UEC, UIC, YKS-7, ZKS-7; T.C. 467, 499, 626	SA4-1053	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
UPF-7, VPF-7; T.C. 642	SA4-1567	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
UPF-7, VPF-7, ASO; T.C. 642, ATC 41	SA1008WE	Installation of Poly-Fiber covering material (complete aircraft). Amended 8/21/79.	WE	75250	Stits Aircraft Corp. P.O. Box 3084 Riverside, CA 92509
YKS-7; T.C. 626	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglas cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

WAGNER, R.H.

DECEMBER 31, 1980

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
50-C, 65-C, 65-CA, S-50-C, S-65-C, S-65-CA, KCA; T.C. 675	SA4-288	BN-1 propeller spinner.	WE	75250	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
50L; T.C. 702	SA4-1572	Application of glass cloth to fuselage, wings, horizontal and vertical stabilizer.	WE	38060	Glasco-Air Products 13703 Woodcock Avenue San Fernando, CA 91340
50, 65; T.C. A-702	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
50-L, -LA, 65-LA, -LB; T.C. 702	SA1301WE	Ceconite 101 covering of entire airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
(Aeronca, Trytek) 50-L, -LA, 65-LA, -LB, 65-C, -CA, KCA, S-65-C, S-65-CA; T.C. 702, 675	SA2666WE	Ceconite 102 material covering of complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
65-C-CA, S-65-C, KCA, S-65-CA; T.C. 675	SA1351WE	Replace existing fabric on wings fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S-65-CA; T.C. 675	SA1-150	Continental C-85-8 engine, Sensenich 75GK-50 propeller, and Harrison HE431-9 engine oil cooler.	EA	61622	North American Flying Service Ludwig Haslbeck Little Ferry, NJ 07643
65-CA; T.C. 675	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
65-C; T.C. 675	SA1-583	Continental A-65-8 engine and Sensenich 72GK42 propeller.	EA	61795	A.H. Oldfield 308 West Main Street Waterloo, NY 13165
65-C, 65-CA, S-65-C, S-65-CA, KCA; T.C. 675	SA4-1298	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
IO-540-A1A5; T.C. 1E4	SE201SO	Modification of engine oil dip stick to provide 10.5 quart useable oil capacity in lieu of 9.25 quart capacity.	SW	68145	Riley International Corporation 6211 W. Northwest Highway Dallas, TX 75225
IO-540-A1A5, B1A5, B1B5, B1C5, C1B5, C1C5, C2C, C4B5, C4C5, C2C, C4B5, C4C5, E1A5, E1B5, G1A5, G1B5, G1C5, G1D5, G1E5, J4A5, K1A5, K1B5, L1A5, M1A5, P1A5, K1C5; K1F5, S1A5, K1E5; T.C. 1E4	SE6WE	Installation of two Rajay turbochargers P/N 0080-100, or -102. Amended 10/7/74.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
IO-540-A1A5, B1A5, B1B5, B1C5, E1A5, E1B5, E1C5, G1A5, G1B5, G1C5, G1D5, G1E5, P1A5, G1F5, S1A5; T.C. 1E4	SE60WE	Installation of two Rajay turbochargers P/N RJ 0327-1 or -2 and and 9 lb. ± 1 sonic nozzle. Amended 9/19/73.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
IO-540-K1G5D; T.C. 1E4	SE85WE	Installation of two Rajay turbochargers Model 315F10-2, P/N RJ 0080-102, on Lycoming engine. Issued 11/8/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
IO-540-S1A5 T.C. 1E4	SE81WE	Installation of two Rajay turbochargers, Model 325EF80, P/N 0330-1 and -2, and 9 lb. ± 1 lb. sonic nozzle on Lycoming engine Model IO-540-S1A5. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
IGSO-540-A1A, -A1D; T.C. 1E7	SE442GL	Incorporation of a fuel flow transducer. Issued 9/15/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
TIO-540-A1A, -A2A, -A1B, -A2B, -A1C, -A2C, -F2BD, -J2BD, LTIO-540-F2BD, -J2BD; T.C. E14EA	SE445GL	Incorporation of a fuel flow transducer. Issued 9/15/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
R-680-D6 (89-2000); T.C. 173	SA291SW	Revised cover plates.	SW	05752	Aircraft Parts 6037 Cameron Boulevard New Orleans, LA 64822
IO-720-A1A; T.C. 1E15	SE163SO	Two Rajay turbochargers 325E10.	SW	68145	Riley International Corporation 6211 W. Northwest Highway Dallas, TX 75225
IO-720-A1A; T.C. 1E15	SE205SO	Two Rajay turbochargers 325H10.	SW	68145	Riley International Corporation 6211 W. Northwest Highway Dallas, Texas 75225
t+1 IO-720-A1A, -A1B; T.C. 1E15	SE51WE	Installation of two (2) Rajay P/N RJ0326, RJ0326-1 or RJ0326-2 (or any combination thereof) turbochargers on Avco Lycoming Model IO-720-A1A and IO-720-A1B engines. Amended 1/18/74.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90801
IO-720-A1A, -A1B; T.C. 1E15	SE63WE	Installation of starter ring gear support assembly. Issued 12/12/73.	WE	01390	Neil J. Adler 2870 Sugarman Court La Jolla, CA 92037
IO-720-B1B; T.C. 1E15	SE62WE	Installation of two Rajay turbochargers, P/N RJ 0326 or -1 or -2. Amended 8/19/75.	WE	69220	Mr. RPM Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
ENGINE
TELEDYNE CONTINENTAL MOTORS

DECEMBER 31, 1980

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A-40, -2, -3, -4; A-40-5; A-50; A-65; A-70, -2; A-75; A-80; A-100; C-75, C-85; C-90; C-115, -125; C-145; E-165, E-185; E-225, -2, -4, -8, -9; O-200-A; O-300; GO-300-A thru F; IO-346-A, -B; IO-360-A thru D; O-470-4, -11, -11-C1, -13-13A, -15; O-470-A, B, E, G, H, J, K, L, M, N, P, R; GIO-470-A; IO-470-A, -C; O-470-D thru U; FSO-470-A, -2; TSIO-470-B, -C, -D; IO-520-A, -B, -C; FSO-526-A, -C; GSO-526-A; GTSIO-520-C; TSIO-520; ATC 72, 174, T.C. 190, 205, ATC 32, T.C. 213, 217, 241, 233, 236, 246, 252, 253, 267, 298, E3CE, E1CE, 269, 273, E2CE, 3E1, 281, 3E3, E5CE, 292, 303, E7CE, E8CE-2	SE44WE	Use of Kling Aviation oil, specifications KL-100, KL-200, and KL-300 in Continental and Lycoming engines.	WE	48530	Kling Oil Company 1492 Oddstad Drive Redwood City, CA 94063
A-50, A-65, A-70, A-80, C-85, C-90, O-200, C-75, C-115, C-125, C-145, O-300, E-165-2, E-185-2, O-470, GO-300; T.C. 190, 205, 213, 217, 233, 252, 236, 253, 246, 273, 298	SE1-201	Installation of Richter B-4 or B-5 probes in Marvel-Schebler carburetors MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6, HA-6 series and Bendix NA-S3B and NA-S3A1. Amended 9/20/77.	EA	68000	Richter Aero Equipment Essex, NY 12936
A-50, A-65, A-70, A-80, C-85, C-90, O-200, C-115, C-125, C-145, O-300, E-165, E-185, O-470, GO-300; T.C. 190, 205, 213, 217, 233, 252, 236,	SE208SO	Installation of ice indicator in the carburetor.	SO	71545	Charles B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
A-65 Series; T.C. E-205	SE64WE	Installation of oil screen and oil cooler adapter. Issued 5/24/74.	WE	42137	Laurence E. Hill 336 South Parish Place Burbank, CA 91506
A65, A75, C75, C85 Suffix "F" Series; T.C. 205, 213, 233	SE4CE	Motorola alternator A12NK451. Amended 1/20/78.	CE	15404	Steven E./Robert F. Bell R.R. #1, Box 5 Lawrence, KS 66044
A65, A75, C75, C85 Suffix "F" Series; T.C. 205, 213, 233	SE984SW	Delco 55A ampere alternator.	SW	84396	Lee A. Waldrop 7624 Palomar Fort Worth, TX 76118
C-85; T.C. 233	SE3CE	R-30-A alternator.	GL	67160	Kenneth J. Repke 7788 Auburn Detroit, MI 48233
C-145, O-300 Series; T.C. 253	SE3-663	Install dry vacuum pump drive. Reissued 7/15/69.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
E-165-2, E-185-1, -3, -8, -9, -11; T.C. E-246	SE416GL	Installation of a spin-on oil filter adapter and spin-on filter in lieu of original screen. Reissued 9/8/80.	GL	71920	S & K Engineering Rt #1, Box 417B Greeneville Municipal Airport Greeneville, TN 37743
D-185, E-225 Series; T.C. 246, 267	SE419SW	Full flow oil filter. Amended 3/1/67.	GL	77017	The Superior Flow Company Div. of A & E Manufacturing, Inc. 11300 Schaefer Highway Detroit, MI 48233
E-185 Series; T.C. 246	SE248EA	MOdification of Hartzell C-192-2 "T-Drive" for use with Airborne Mechanisms dry vacuum pump.	EA	85600	Edward J. White 207 Stephen Drive Cinnaminson, NJ 08077

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
E-185, E-225, O-470 Series; T.C. 246, 267, 269	SE23SW	R5-5BD1 fuel injection system.	GL	15500	Bendix Products Aerospace Div. 717 Bendix Drive South Bend, IN 46600
O-200 Series; T.C. E-252	SE2791SW	Revised starter clutch. Issued 6/6/78	SW	14214	B C & J Enterprises P.O. Box 19676 Oklahoma City, OK 73144
O-200-A; T.C. 252	SE8WE	Alternate oil sump.	WE	78476	Thorp Aircraft Company 909 East Magnolia Boulevard Burbank, CA 91500
0-200-A; T.C. E-252	SE82WE	Closing off of the oil outlet port of the main thrust bearing; installation of an 0-200-B crankshaft; modifying the front oil seal slinger flange; machining an already existing molded pad on the crankshaft to receive a side mounted fuel pump. Issued 10/11/77.	WE	48527	Harvey J. Klein 1736 S. Bedford Street Los Angeles, CA 90035
O-200-A; T.C. 252	SE1396SW	Revise engine oil pick up system. Issued 11/24/71.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
E-225; T.C. 267	SE3WE	T-1106 turbocharger.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
E-225-4, -8; T.C. E-267	SE417GL	Installation of a spin-on oil filter adapter and spin-on filter in lieu of original screen. Reissued 9/8/80.	GL	71920	S & K Engineering Rt #1, Box 417B Greeneville Municipal Airport Greeneville, TN 37743
O-300-A, -B, -C, -D, -E; IO-360-A, -B, -C, -D; IO-470-D thru -H, -J, -K, -L, -M, -R, -S, -U, -V; O-470-J, -R, IO-470-C; O-470-4, -11, -13, -15; IO-520-A, -D, -E, -F, -J, -K, -L; TSIO-520-C, -G, -H; GTSIO-520-C, -D, -F, -H; T.C. 253, E1CE, 3E1, 273, 269, E5CE, E8CE, E7CE	SE12GL	Installation of oil filler cap. Issued 7/11/73.	GL	85850	Ray Whyte Electric Products Co. 30201 Harper Avenue St. Clair Shores, MI 48083
IO-346 and IO-520; T.C. E3WE, E5CE	SE34WE	Installation of Electro-Coatings, Inc. piston rings P/N 252501 and 252509 on Continental piston 631475 for use in Channel-cromium plated Continental IO-346 and IO-520 engine cylinder.	WE	33219	Electro-Coatings, Inc. 1401 Park Avenue Emeryville, CA
IO-360-A, -B, -C, -D, -G, -H, -J, -K; T.C. E1CE	SE234GL	Installation of a steel pin in Continental fuel pump, P/N 638157. Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
IO-360-K; T.C. E1CE	SE1436CE	Modify engine to obtain 210 hp, 2800 rpm for 5 minutes at takeoff and 195 hp 2600 rpm continuous (new designation IO-360-KC/STC SE1436CE). Issued 10/6/78.	CE	44802	Brad E. Isham 416 West Fourth Street Valley Center, KS 67147
TSIO-360-A, -B, -C, -D, -E, -F, LTSIO-360-E; T.C. E9CE	SE235GL	Installation of a steel pin in Continental fuel pump P/N 634263 (TSIO-360-A, -B), 639508 (TSIO-360-C, -D, -E, -F), and 639508 (LTSIO-360-E). Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
O-470 Series; T.C. 269	SE264SW	Marvel-Schebler MA-4-5 carburetor.	SW	32000	Ector Aircraft Company 1703 West Crescent Drive Odessa, TX 79760
O-470 Series; T.C. 273	SE1CE	RSA-5 fuel injection system.	GL	15500	Bendix Products Aerospace Div. 717 Bendix Drive South Bend, IN 46600
O-470 Series; T.C. 273	SE141SW	Rework crankcase in area of starter drive needle bearing.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
O-470 Series; T.C. 273	SE616SO	Installation of O-470-R parts in lieu of normal O-470-4 parts.	SO	61644	North Perry Aviation, Inc. 8000 West Pembroke Road Hollywood, FL 33023

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
O-470, IO-470 Series; T.C. 273	SE325SW	Full flow oil filter. Amended 3/1/67.	GL	77017	The Superior Flow Company Div. of A & E Manufacturing, Inc. 11300 Schaefer Highway Detroit, MI 48233
O-470, IO-470 Series; T.C. 273, 3E1	SE73SO	Continental GIO-470 engine oil sump assembly 628943 and oil pump suction tube assembly 628660.	SO	05580	Aircraft Modification Engineering Company P.O. Box 48-1314 Miami, FL 32960
O-470, IO-470, TSIO-470 Series; T.C. 269, 273, 3E1, 3E3	SE16WE	Bendix S-600 low tension ignition system.	WE	70055	Salinas Engine Works Municipal Airport Salinas, CA 93901
O-470, IO-470, TSIO-470 Series; T.C. 269, 273, 3E1, 3E3	SE26WE	Piston ring 250000, 250000+2W and 250000+10W on Continental E Series piston 534895, O-470 piston 534895, 626992 and 537883 and IO-470 piston 534895.	SW	21500	Electro-Coatings, Inc. Channelcromium Division P.O. Box 428 Grapevine, TX 76051
O-470-A, J, K, L, R, G-C1, IO-470-C, -J, -K; T.C. 273, 3E1	SE25WE	Installation of two Rajay turbochargers Model 315F10, P/N RJ0080-102. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
O-470-B, -G, -H, -K, -L, -M, -N, -S, -T, -U, O-470-B-C1, G-C1, K-C1, L-C1, M-C1, IO-470-A, -C; T.C. E-273	SE95WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-470 Series; T.C. 273, 3E1	SE82SO	Engine sump reworked to provide 15 1/8-quart total oil capacity.	SO	68140	Riley Aeronautics Corporation 2100 Northwest 50th Street Fort Lauderdale, FL 33300
IO-470 Series; T.C. 273, 3E1	SE387SW	Modification of ring grooves on Continental Motors pistons 539814 (3 ring) and 627738 (4 ring).	SW	82250	Van Der Horst Corporation of America P.O. Box 428 Terrell, TX 75160
IO-470 Series; T.C. 3E1	SE2-984	Modification of Continental IO-470 piston 6277338 for piston ring used in Continental O-470 piston 537883.	SW	21500	Pennington Channelcromium Company Division of Electro-Coatings, Inc. 319 Dakota Street San Antonio, TX 78205
IO-470 Series; T.C. 3E1	SE94SW	Modification of Continental IO-470 pistons 627738 and 539814 compression ring grooves.	SW	22250	Chrome Plate, Inc. 2805 South Flores Street San Antonio, TX 78205
IO-470 Series; T.C. 3E1	SE152SO	Modification of throttle body location.	SO	37084	Gander Aircraft Corporation 3923 Northwest 24th Street Miami, FL 33142
IO-470-C; T.C. E273	SE994SO	Installation of fuel line filters into individual fuel injector lines. Issued 5/25/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-470-D, -E, -F, -H, -L, -M, -N, -S, -U, -V, -VO; T.C. 3E1	SE69WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	SO	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-470-D, -E, -F, -G, -H, -L, -LO, -N, -P, -R, -S, -T, -U, -V, -VO, LIO-470-A; T.C. 3E1	SE92WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-470-D, E, M, N, S, U, V; T.C. 3E1	SE96SO	Installation of two (2) Rajay turbochargers Model 315F10, P/N RJ0080-102. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
IO-470-J, -K, -N, L; T.C. 3E1	SE992SO	Installation of fuel line filters into individual fuel injector lines. Amended 9/17/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-470, IO-520, TSIO-520 Series; T.C. E-273, 3E1, 3E3, E5CE, E8CE	SE55WE	Modification of fuel injection manifold valve P/N 626547 to the P/N 631427 or P/N 636326 configuration. Issued 2/10/72.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
GIO-470-A; T.C. E2CE	SE70WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
TSIO-470 Series; T.C. 3E3	SE166SW	Modification of Continental TSIO-470 Series piston 629185 for piston rings used in Continental O-470 Series piston 537883.	SW	21500	Pennington Channelcromium Co. Div. of Electro-Coatings, Inc. 319 Dakota Street San Antonio, TX 78205
TSIO-470 Series; T.C. 3E3	SE271SW	Modification of Continental TSIO-470 piston 629185 compression ring grooves.	SW	22250	Chrome Plate, Inc. 2805 South Flores Street San Antonio, TX 78205
TSIO-470-B, -C, -D; T.C. 3E3	SE71WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
TSIO-470B, C, D; T.C. 3E3	SE93WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-520, TSIO-520 Series; T.C. E5CE	SE70RM	Installation of JB Systems compressor brackets P/N 21-052-19. Amended 6/8/79.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
GTSIO-520-C, -D; T.C. E7CE	SE74WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-520-A, -B, -BA, -C, -D, -E, -F, -J, -K, -L, -M; T.C. E5CE	SE72WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-520-A, -B, -BA, -C, -D, -E, -F, -J, -K, -L, -M; T.C. E-273	SE94WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-520-B, -BA; T.C. E5CE	SE282GL	Installation of a fuel flow transducer, Symbolic Displays P/N 201B. Issued 11/14/78.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport Rockford, IL 61109
IO-520-B, -BA, -BB; T.C. E5CE	SE443GL	Incorporation of a fuel flow transducer. Issued 9/15/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
IO-520-B, -BA, C; T.C. E5CE	SE993SO	Installation of fuel line filters into the individual fuel injector lines. Amended 9/17/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-520-D; T.C. E5CE	SE75WE	Installation of emergency fuel system. Issued 9/9/75.	WE	59730	Mission Aviation Fellowship Box 2828 3519 West Commonwealth Fullerton, CA 92633
IO-520-E; T.C. E5CE	SE451SO	Installation of air compressor gear box drive. Amended 4/6/71.	SO	65333	Puerto Rico Int'l Airlines P.O. Box 1498 Bayamon, PR 00619
IO-520-F; T.C. E5CE	SE80WE	Installation of an emergency fuel system. Issued 9/13/77.	WE	59730	Mission Aviaiton Fellowship P.O. Box 2828 Fullerton, CA 92633
IO-520-G; T.C. E7CE	SE1004SW	Install alternator braces. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
TSIO-520-A, -B, -C, -D, -E, -G, -H, -J, -K, -L; T.C. E8CE	SE73WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
TSIO-520-A, -B, -C, -D, -E, -F, -G, -H, -J, -K, -L, -M, -N, -P, -R; T.C. E8CE	SE96WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
TSIO-520-E, -EB; T.C. E8CE	SE444GL	Incorporation of a fuel flow transducer. Issued 9/15/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
TSIO-520-C, M; T.C. E8CE	SE88WE	Installation of emergency fuel system. Issued 2/7/78.	WE	59730	Mission Aviation Fellowship Box 2828 Fullerton, CA 92633

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
TSIO-520-D; T.C. E8CE	SE57WE	Installation of two (2) Rajay P/N RJ0080-100, -101 or -102 turbo-superchargers on Continental Teledyne engine. Amended 11/17/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
TSIO-520-D; T.C. E8CE	SE233GL	Installation of a steel pin in Continental fuel pump P/N's 639508 and 632637. Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
TSIO-520-K; T.C. E5CE	SE1908SW	Conversion of TSIO-520-K to TSIO-520-J. Issued 8/29/74.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
TSIO-520-N; T.C. E8CE	SE2831SW	Bendix S6RN-1251 and S6RN-1255 magnetos. Issued 8/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
TSIO-520-T; T.C. E8CE	SE1462CE	Installation of SSP Products heater core and shroud. Issued 12/4/78.	CE	20625	Cessna Aircraft Company Pawnee Division 5800 East Pawnee Wichita, KS 67201
W-670-6A; T.C. E-162	SE4127SW	Install modified W-670-23 piston, P/N 4180, to replace W-670-6A piston, P/N 4177. Issued 5/21/80.	SW	39710	Gulf Coast Dusting Company 5334 Allison Road Houston, TX 77048
Miscellaneous	SE34WE	Installation of Electro-Coatings, Inc., piston rings on Continental pistons. Amended 3/14/68.	SW	21500	Electro-Coatings, Inc. Channelcromium Division P.O. Box 428 Grapevine, TX 76051
Miscellaneous	SE41WE	Installation of emergency fuel system.	WE	59730	Missionary Aviation Fellowship P.O. Box 2828 Fullerton, CA 92633
Miscellaneous	SE43WE	Installation of an additional dowel in crankshaft accessory gear.	WE	16853	Willard S. Blackinton 9333 Edgewood Drive La Mesa, CA 92041

*U. S. GOVERNMENT PRINTING OFFICE : 1981 0-725-617/1160

728-119
copies 153
19 1981
431-A-5
TD 4.36: 980/supp.-4
contin
9336

U.S. DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

SUMMARY OF SUPPLEMENTAL TYPE CERTIFICATES

This contains revisions to Summary of Supplemental Type Certificates issued for January, February, March 1981

PAGE CONTROL CHART

Remove Pages	Insert Pages
Aerospatiale 1-2	Aerospatiale 1-2
Air Tractor 1	Air Tractor 1
Avions Marcel Dassault 3 thru 9	Avions Marcel Dassault 3 thru 9
Ayres Corporation 1 thru 4	Ayres Corporation 1 thru 4
Beech 35 thru 75	Beech 35 thru 77
Bell 5 thru 14	Bell 5 thru 15
Bellanca MN 1 thru 9	Bellanca MN 1 thru 9
Boeing 13 thru 49	Boeing 13 thru 50
Beoing Vertol 1	Boeing Vertol 1
British Aeropsace 5 thru 9	British Aerospace 5 thru 9
British Aircraft 1 thru 3	British Aircraft 1 thru 3
Britten-Norman 1-2	Britten-Norman 1 -2
Cessna 9 thru 84	Cessna 9 thru 86
- -	Composite Aircraft 1
DeHavilland 1 thru 8	DeHavilland 1 thru 8
Empressa 1	Empressa 1
Gates Learjet 1 thru 10	Gates Learjet 1 thru 10
General Dynamics 15 thru 19	General Dynamics 15 thru 20
Gulfstream American 3 thru 24	Gulfstream American 3 thru 25
Helio 1 thru 4	Helio 1 thru 4

PAGE CONTROL CHART

Remove Pages	Insert Pages
Hiller 1 thru 3	Hiller 1 thru 3
Hughes 3 thru 5	Hughes 3 thru 5
Israel Aircraft 1 thru 5	Israel Aircraft 1 thru 5
Kawasaki 1	Kawasaki 1
Lockheed 1 thru 19	Lockheed 1 thru 19
Lockheed GA 3 thru 11	Lockheed GA 3 thru 11
Maule 1-2	Maule 1-2
McDonnell Douglas 15-16, 21 thru 42	McDonnell Douglas 15-16, 21 thru 43
Messerschmitt 1-2	Messerschmitt 1-2
Mitsubishi Aircraft 1	Mitsubishi Aircraft 1
Mitsubishi Heavy Ind. 1 thru 8	Mitsubishi Heavy Ind. 1 thru 8
Mooney 5-6	Mooney 5-6
- -	New Zealand 1
Nihon 1	Nihon 1-2
No. American Aviation OH 1	No. American Aviation OH 1
Piper 5 thru 8, 11-12, 15 thru 68	Piper 5 thru 8, 11-12, 15 thru 68
Piper Aircraft CA 1 thru 3	Piper Aircraft CA 1 thru 3
Raven 1	Raven 1
Rockwell Int. CA 1 thru 10	Rockwell Int. CA 1 thru 11
Rockwell Int. OK 5 thru 15	Rockwell Int. OK 5 thru 15
Sikorsky 1	Sikorsky 1
S.N.I.A.S. 1 thru 6	S.N.I.A.S. 1 thru 6
STOL Aircraft 1-2	STOL Aircraft 1-2
Swearingen 1 thru 3	Swearingen 1 thru 3
Univair 1 thru 6	Univair 1 thru 6

PAGE CONTROL CHART

Remove Pages	Insert Pages
ENGINES	
Avco Lycoming 1 thru 3	Avco Lycoming 1 thru 3
Detroit Diesel 1	Detroit Diesel 1
Teledyne Continental 1 thru 5	Teledyne Continental 1 thru 5
PROPELLERS	
Hamilton Standard 1	Hamilton Standard 1

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
AEROSPATIALE

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Alouette III Series; T.C. H1IN	SH752NW	Installation of a weighing system. Issued 4/12/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SE.3160 Alouette III; T.C. H1IN	SH434AL	Installation of Alaskan Sky-Craft cargo baskets. Issued 6/10/71.	AL	08500	Alaskan Sky-Craft Company 7007 Seward Highway Anchorage, AK 99502
SE.3160, SA.316B, SA.316C, SA319B; T.C. H1IN	SA1243SW	Eastern rotorcraft cargo hook AK25LT. Reissued 1/4/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SE.3160 Alouette III; T.C. H1IN	SH1791SW	Foxtronics/Tramm BTI-600 nickel cadmium battery temperature. Issued 1/30/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
SE 3160 Alouette III, SA 316B Alouette III; T.C. H1IN	SA1320SW	External cargo baskets. Issued 6/1/71.	SW	84300	Vought Helicopter, Inc. 1507 Pacific Avenue Dallas, TX 75201
SE.3160 Alouette III, SA.316B Alouette III; T.C. H1IN	SH1490SW	AiResearch 92757 environmental control system. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160 Alouette III, SA.316B Alouette III; T.C. H1IN	SH1800SW	Install reclining passenger seat in forward left hand position. Issued 2/1/74.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SE.3160, SA.315B, SA.316B; T.C. H1IN	SH1471SW	Engine inlet sound suppresors. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.315B, SE316 Series; T.C. H1IN	SH437NW	Incorporation of weighing system for external load operations. Amended 6/10/77.	NW	56890	Measurement Systems International 619 Riverside Drive Seattle, WA 98108
SE3160, SA316B, SA319B; T.C. H1IN	SH71NW	Installation of electric weighing system. Amended 11/7/75.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
SE.3160, SA.315B, SA.316B, SA.319B, SA316C; T.C. H1IN	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SE.3160, SA.316B, SA.316C; Alouette III; T.C. H1IN	SH1900SW	Non-stowable litter kit. Issued 7/24/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1307SW	Eastern Rotorcraft cargo hook and H-frame. Reissued 1/4/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1318SW	Removable cabin step. Issued 10/2/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319B; T.C. H1IN	SH1320SW	External cargo baskets. Reissued 7/1/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SE.3160, SA.316B, SA.316C, SA.319C; T.C. H1IN	SH1385SW	Replace existing landing light and anti-collision light. Reissued 9/30/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA315B; T.C. H1IN	SH61NW	Installation of electric weighing system. Amended 5/5/76.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
SA315B; T.C. H1IN	SH267NW	Installation of Simplex Model 3400 3400 spray system. Issued 6/16/76.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
SA315B; T.C. H1IN	SH268NW	Installation of automatic flagman Model #5. Issued 3/18/76.	NW	03500	Air Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
SA315B; T.C. H1IN	SA429NW	Installation of Simplex Model 4206 4206 aerial spray system. Issued 4/11/77.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA315B; T.C. H1IN	SH540NW	Install onboard weighing system. Issued 1/9/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA.315B; T.C. H1IN	SH695NW	Installation of Model 2512 weighing system. Issued 12/14/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA.315B; T.C. H1IN	SH1735SW	H-frame external cargo hook. Issued 2/6/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.315B Alouette III; T.C. H1IN	SH1909SW	Replacement of existing landing light and anti-collision light. Reissued 9/30/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.315B; T.C. H1IN	SH2425SW	Installation of low range airspeed indicator and pitot pressure surge chamber. Issued 3/4/77.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
SA.315B, SA.316C, SA.319B; T.C. H1IN	SH4266SW	Alternate parts for installation of modification AM2195. Issued 2/13/81.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
SA.316B Alouette III; T.C. H1IN	SH168WE	Installation of Nightsun SC-16C searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
SA.316B Alouette III; T.C. H1IN	SH647NW	Installation of cargo baskets. Issued 8/3/78.	NW	44032	Inland Helicopters 2660 Vine Street Grants Pass, OR 97526
SA.316B, SA.316C, SA319B; T.C. H1IN	SH223WE	Installation of tail rotor floodlight. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerqve, NM 87109
SA-360C; T.C. H8EU	SH2962SW	Blade bolt balance pin adapter. Issued 3/23/79.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
SA360C; T.C. H8EU	SH4051SW	Modification of lower cabin plexiglass panels. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C, SA-365C; T.C. H8EU, H10EU	SH1179EA	Installation of DeVore tail floodlight on upper surfaces of horizontal stabilizer. Reissued and amended 2/29/80.	SW	30002	DeVore Aviation Corporation 6104-B Kircher Boulevard, N.E. Albuquerque, NM 87109
SA-365C; T.C. H10EU	SH2987SW	External markings. Issued 4/23/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA-365C; T.C. H10EU	SH4050SW	Twelve-place interior with forward facing seats. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-365C; T.C. H10EU	SH4052SW	Modification of lower cabin plexiglass panels. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-365C; T.C. H10EU	SH4072SW	Interior installation. Issued 1/11/80.	SW	41780	Heliflight Systems, Inc. P.O. Box 90879 Houston, TX 77090
SA-365C; T.C. H10EU	SH4073SW	Equipment shelf in upper baggage area. Issued 1/11/80.	SW	41780	Heliflight Systems, Inc. P.O. Box 90879 Houston, TX 77090
SA-365C, C1; T.C. H10EU	SH4252SW	Blade bolt balance pin adapter. Issued 12/18/80.	SW	03010	Aerospatiale Helicopter 2701 Forum Drive Grand Prairie, TX 75051
SA-365C, C1; T.C. H10EU	SH4253SW	Soundproofing. Issued 12/18/80.	SW	03010	Aerospatiale Helicopter 2701 Forum Drive Grand Prairie, TX 75051
SA-365C1; T.C. H10EU	SH198RM	Installation of new auxiliary fuel tank and litter installation. Issued 4/7/80.	SW	41775	Helicopter Medical Evacuation, Inc. P.O. Box 1462 Fort Collins, CO 80522

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

AIR TRACTOR, INC.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
AT-300; T.C. A9SW	SA265NW	Installation of automatic flagman Model #4. Issued 3/2/76.	NW	03500	Air Ag, Inc. Route 4, City-County Airport Walla Walla, WA 99362
AT-301; T.C. A9SW	SA943NW	Installation of Pacific Propellers EAC-12D40-425/AG-100-4S or EAC-22D40/AG-200-4S propeller assemblies using P&W 600 hp R-1340-S1H series engines. Issued 5/29/80.	NW	6212C	Pacific Propellers, Inc. P.O. Box 946 Kent, WA 98031

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon; T.C. A7EU	SA1139WE	Interior and equipment.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1155EA	Installation of Solar T-62T-39, in lieu of Solar T-62T-29, gas turbine auxiliary power unit and removal of Freon air conditioning systems. Amended 8/15/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon; T.C. A7EU	SA1204WE	Integrated auxiliary power unit and air conditioning system using Solar T-62T-29A gas turbine. Reissued 12/20/77.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon; T.C. A7EU	SA1230WE	Storage box in rear compartment.	WE	62080	Pacific Airmotive Corporation Aircraft & Eng. Center 3000 N. Clybourn Avenue Burbank, CA 91502
Fan Jet Falcon; T.C. A7EU	SA1298WE	Emergency flight instrument system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1336WE	Flight data recorder and cockpit voice recorder.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1337WE	Emergency cabin lighting.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1357SW	Installation of inverter rack. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon; T.C. A7EU	SA1342WE	Installation of accumulator pressure gauges.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1374WE	Installation of Bendix DRA-12 doppler radar system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1436WE	Installation of Shoulder Harness for Pilot Seat.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1508WE	Installation of an Automated Specialties, Inc. angle of attach system. Amended 9/4/68.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1515SW	Replace existing 13 x 5.0-4 wheel and tire w/14.5 x 5.5-6 wheel and tire. Reissued 4/6/77.	SO	34808	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon; T.C. A7EU	SA1573WE	Installation of Lear Jet Type Air Conditioning System and Auxiliary Heater.	RM	37098	Gates Rubber Company 8601 Montview Boulevard Denver, CO 80220
Fan Jet Falcon; T.C. A7EU	SA1588SW	Foxtronics/TRAMM BT1 600 nickel cadmium battery temperature system. Issued 1/5/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
Fan Jet Falcon; T.C. A7EU	SA1595SW	Transequip cargo handling equipment. Issued 1/22/73.	SW	34810	Federal Express Corporation P.O. Box 493 - Adams Field Little Rock, AR 72203
Fan Jet Falcon; T.C. A7EU	SA1616WE	Installation of ladder and hand rail in aft compartment. Amended 5/23/68.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1621WE	Installation of inverters.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
t+1 Fan Jet Falcon; T.C. A7EU	SA1666SW	Nose wheel steering modification. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon; T.C. A7EU	SA1707WE	Installation of inverters.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon; T.C. A7EU	SA1737SW	WA402001 galley. Issued 10/9/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon; T.C. A7EU	SA1778WE	Installation of electric floor heater blankets	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA1818WE	Installation of Sperry SP-40 Automatic Flight Control System and SPI-73E Sperry Instrumentation System.	WE	74570	Sperry Flight System Division Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
Fan Jet Falcon; T.C. A7EU	SA2058WE	Installation of interior and equipment, including special remote sensing equipment (aerial prospecting). Amended 5/4/70.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon; T.C. A7EU	SA2159WE	Installation of General Precision Laboratories GPK-1000 doppler radar systems. Issued 5/22/70.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91503
Fan Jet Falcon; T.C. A7EU	SA2377SW	Install BH185R-289 EGT temperature indicator system. Issued 11/9/76.	SW	43075	Howell Instruments, Inc. 3479 West Vickery Boulevard Fort Worth, TX 76107
Fan Jet Falcon; T.C. A7EU	SA4067SW	Install Freon air conditioner compressor/condensor package in aft fuselage tail section. Issued 12/6/79.	SW	26230	Cooper Airmotive Aircraft Services P.O. Box 7409 Dallas, TX 75209
Fan Jet Falcon, Fan Jet Falcon C, D, E; T.C. A7EU	SA1102EA	Installation of Teledyne Avionics angle of attack indicating system, P/N SL112B2300. Issued 5/31/78.	EA	78000	Teledyne Avionics P.O. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon and Series C, D, E; T.C. A7EU	SA1398CE	Installation of Collins APS-80 2-axis automatic flight control system integrated with a (partial) ADS-80 air data system. Issued 2/11/78.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
Fan Jet Falcon and Series C, D, E; T.C. A7EU	SA1851WE	Installation of single point pressure fueling system. Amended 6/16/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA28NE	Installation of Canadian Marconi CMA-734 omega navigation system. Amended 3/26/80.	NE	74935	Stead Aviation Corporation Manchester Municipal Airport Manchester, NH 03103
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA30NE	Installation of Global Navigation, Inc. loop antenna, P/N 11455-2, on horizontal stabilizer. Amended 1/17/80.	NE	74935	Stead Aviation Corporation Manchester Municipal Airport Manchester, NH 03103
Fan Jet Falcon; Series C, D, E, F; T.C. A7EU	SA689SW	Revised autopilot static system for Collins AP103F autopilot. Reissued 1/30/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon, Fan JEt Falcon Series C, D, E, F; T.C. A7EU	SA1202EA	Installation of Hamilton Standard R70-3W refrigeration package, P/N 738443-21. Issued 8/4/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1435CE	Addition of improved autopilot static port systems. Issued 9/28/78.	CE	59270	MidCoast Aviation Service, Inc. Lambert Field P.O. Box 10254 St. Louis, MO 63145
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1616CE	Installation of Global GNS-500A VLF omega navigation system. Issued 11/25/80.	CE	59270	Midcoast Aviation Services, Inc. Lambert Field St. Louis Inter'l Airport St. Louis, MC 63145
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1996SW	Installation of auxliliary landing lights. Issued 11/6/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2568WE	Installation of engine thrust reversers. Amended 10/31/72.	GL	02400	Aeronca, Inc. 1712 Germantown Road Middletown, OH 45042
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2704WE	Installation of (1) engine pylon mounted vertical tail floodlights, (2) horizontal stabilizer mounted vertical tail floodlights or both systems. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2792WE	Installation of Dorne & Margolin antenna assembly (DMN 4-15) on the vertical tail cap. Reissued 12/20/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon and Series E, F; T.C. A7EU	SA2550WE	Installation of Flite-Tronics inverters Model PC-17A. Amended 2/20/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series C, D; T.C. A7EU	SA829EA	Installation of Teledyne Avionics auto throttle system. Reissued 1/7/72.	SW	78127	Teledyne Incorporated 3401 Shiloh Road Garland, TX 75040
Fan Jet Falcon Series C, D, E; T.C. A7EU	SA1137SW	Installation of Teledyne Avionics normalized angle of attack indicating system. Amended 11/9/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA29GL	Installation of equipment rack at fuselage station 00. Issued 7/9/73.	GL	02400	Aeronca, Inc. 1712 Germantown Road Middletown, OH 45042
Fan Jet Falcon Series C, D, E, F: T.C. A7EU	SA35NE	Installation of Stead Aviation bracket, P/N SA AB1585. Issued 7/18/80.	NE	74935	Stead Aviation Corporation Manchester Airport Manchester, NH 03103
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA57GL	Installation of passenger couch. Reissued 7/10/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, II 62705
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA122GL	Installation of radome kit 4076X. Issued 8/16/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST849SO	PPG Industries windshields, Federal Express P/N's 111-0071, (L/H), 111-0072 (R/H), 111-0073 (center). Issued 8/4/75.	SO	34808	Federal Express Corporation 2839 Sprankel Road P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST882SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA891SW	Dorne & Margolin DMN4-15-5 antenna. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA894EA	Installation of Grimes three light strobe kit P/N 34-0302-1 as supplemental lighting. Issued 12/20/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST925SO	Manufacture of main landing gear door arm for Fan Jet Falcon Series airplane. Issued 2/24/77.	SO	05090	Aircraft Equipment Cert. Corp. P.O. Box 18850 Memphis, TN 38118
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST948SO	Installation of Aircraft Equipment Certification Corp. pilot/copilot/ center windshield panels. Amended 6/2/78.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C, D, E, F: T.C. A7EU	ST960SO	Manufacture and installation of Aircraft Equipment Certification Corp. (AECC) modular container and rack assembly. Issued 10/21/77.	SO	05090	Aircraft Equipment Certification Corporation 2856 Lambs Place, Suite 8 Memphis, TN 38118
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST961SO	Replacement of the ball-bearing type right-hand engine throttle crossover cable with a reinforced wire type. Issued 11/15/77.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis International Airport Memphis, TN 38138
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	ST1001SO	Installation of Federal Express Corp. brake mount flange. Issued 6/6/78.	SO	34808	Federal Express Corporation AMF Box 30167 Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1163EA	Installation of Solar T-62T-40C APU. Amended 1/23/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; .C. A7EU	SA1164EA	Installation of cabin air-conditioning flood duct. Amended 10/10/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1172EA	Installation of Hamilton Standard R72-3W air cycle machine, P/N 750660 Model 7/10 heat exchangers P/N 753355. Amended 3/20/80.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1213SW	Alteration for battery charging from ground power unit. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1461SW	Three Flite-Tronics PC-17A inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1462SW	Collins AP-105/FD-108/FD-109 autopilot/flight director system. Amended 9/28/78.	CE	24250	Rockwell International Collins Radio Group Collins Road Cedar Rapids, IA 52406
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1469SW	Fairchild stem system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1633SW	Three Avionics Instruments, Inc. 1A1000 inverters. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1699SW	Solar T-62T-39 turbine APU. Issued 7/6/73.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1713SW	Couch installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1714SW	Galley installation. Issued 8/13/73.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1768SW	Gulton proximity switch system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1885SW	Solar T62T-39 turbine APU. Issued 6/14/74.	SW	51250	Little Rock Airmotive, Inc. P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1893SW	Landing light installation, alternate position. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA1988SW	Jump seat. Issued 5/20/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2204SW	Installation of electronics rack. Issued 9/14/76.	SW	34280	Fancon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA2232SW	Install Collins dual NCS-31 RNAV system. Issued 8/15/75.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2474SW	Horn silence switch. Issued 6/21/77.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series C,D,E,F; T.C. A7EU	SA2485SW	Fabrication and installation of three-place couch. Issued 8/5/77.	SW	34280	Falcon Jet Corporation LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SA3437WE	Installation of Garrett AiRNAV 100 or 300 navigation system. Amended 8/29/80.	WE	07500	AiReserach Manufacturing Co. of California 2525 West 190th Street Torrance, CA 90509
Fan Jet Falcon Series C, D, E, F; T.C. A7EU	SH4095SW	Radio master system. Issued 3/4/80	SW	34280	Falcon Jet Corporation P.O. Box 6156 Little Rock, AR 72216
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA907CE	Battery temperature indicating and over temperature warning system. Amended June 1973.	CE	05250	Aircraft Instrument and Development, Inc., 317 E. Lewis Street Wichita, KS 67202

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon Series C, D, F; T.C. A7EU	SA1483SW	Avionics installation (VHF communications, VHF navigation, ADF's DME's, transponders, weather radar radio altimeter, third attitude gyro). Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series C, D, E, F, Falcon 10; T.C. A7EU, A10EU	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
Fan Jet Falcon Series C, D, E, F, Mystere 20; T.C. A7EU	SA119GL	Electrical cable harness assemblies for left and right engines; each consisting of starter-generator cables, starter-generator ground cable, master junction cable and fan tach sensor cable. Amended 2/6/78.	GL	37379	General Electric Company Aviation Service Operation/Cincinnati 260 West Mitchell Avenue Cincinnati, OH 44232
Fan Jet Falcon Series D; T.C. A7EU	SA918EA	Installation of Canadian Marconi CMA-712 doppler navigation system. Reissued 11/9/72.	EA	47665	Karr Electronics Corporation 232 Wescott Drive Rahway, NJ 07065
Fan Jet Falcon Series D; T.C. A7EU	SA993SW	Collins AP-104 Autopilot and FD-109H/FD-109F Flight Directors for Category I and II. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1327WE	Installation of dual inverters. Amended 3/18/69.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
Fan Jet Falcon Series D; T.C. A7EU	SW1467SW	Cargo interior. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1468SW	Openable window in co-pilot's side and qualifying existing pilot's and new co-pilot's windows as emergency exits. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA1473SW	Replace passenger entrance door with wide cargo door. Amended 7/7/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D; T.C. A7EU	SA2640WE	Installation of a Garrett Model 75 area navigation system. Amended 9/18/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D; T.C. A7EU	SA3394WE	Replacement of cargo barrier net installed per STC SA1467SW with a rigid cargo barrier partition. Issued 7/11/77.	WE	17740	Brownline Division of Brooks & Perkins, Inc. 2950 W. Lomita Blvd. Torrence, CA 92680
Fan Jet Falcon Series D, E; T.C. A7EU	SA1771SW	Installation of Sperry SPZ-200 autopilot/flight director control system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA1570SW	Collins AP105/FD108 autopilot/flight, flight director system. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA1577WE	Installation of jump seat. Amended 10/19/70.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA2404SW	System to disable the take off out of trim warning system when high power is applied during operation of thrust reversers.	SW	47720	Keith Products, Inc. 625 Opal Richardson, TX 75080
Fan Jet Falcon Series D, E, F; T.C. A7EU	SA2588AWE	Installation of a Hoskins Model Mk III (Twilighter) anticollision lighting system. Amended 12/21/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
Fan Jet Falcon Series D, F; T.C. A7EU	SA1495SW	Installation of Fairchild voice, recorder model A100 and Lockheed flight recorder model 109C. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series D, F; T.C. A7EU	SA1806SW	Co-pilot brake modification. Issued 2/6/74.	SW	34810	Federal Express Corporation P.O. Box 493 Little Rock, AR 72203
Fan Jet Falcon Series D, F; T.C. A7EU	SA2344SW	Hartman Systems Co. vertical scale engine instruments. Issued 8/11/76.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Fan Jet Falcon Series E; T.C. A7EU	SA3714WE	Revise existing interior to include three place side facing divan, galley, storage cabinet, three folding tables, cockpit door, stereo/flitephone cabinet, T.V./recorder cabinet and shoulder harness restraint for divan. Amended 11/22/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 E. Spring Street Long Beach, CA 90806
Fan Jet Falcon Series F; T.C. A7EU	SA1381SW	Installation of Teledyne Avionics normalized angle of attach system, Model 112B500. Amended 2/8/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
Fan Jet Falcon Series F; T.C. A7EU	SA1499SW	Installation of inverter system. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series F; T.C. A7EU	SA1692SW	Modification of control pedestal. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
Fan Jet Falcon Series F; T.C. A7EU	SA1892SW	Collins ALT-50 radio altimeter. Issued 6/27/74.	SW	34280	Falcon Jet Corporation, LRD P.O. Box 967 - Adams Field Little Rock, AR 72203
Fan Jet Falcon Series F; T.C. A7EU	SA2479SW	Wiring and antenna provisions, and radio rack for Litton LTN-201 omega system. Issued 7/15/77.	SW	11670	Arkansas Modification Center, Inc. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA142GL	Installation of radome kit 4128X. Issued 11/9/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
Falcon 10; T.C. A33EU	ST902SO	Installation of Collins ground proximity warning system. Issued 7/28/76.	SO	24262	Collins Radio Group Rockwell International 1591 Phoenix Boulevard, Suite 1 Atlanta, GA 30349
Falcon 10; T.C. A33EU	SA1002EA	Installation of Sperry SPZ-500/SPI-77D flight control instrument system. Reissued 1/7/80.	SW	07498	Falcon Jet Corporation P.O. Box 167 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA1012EA	Installation of Teledyne Avionics normalized angle of attack indicating system, P/N 112B1600. Issued 8/21/75.	EA	78000	Teledyne Avionics A Division of Teledyne, Inc. P.O. Box 6400 Charlottesville, VA 22906
Falcon 10; T.C. A33EU	SA1042EA	Installation of hydraulically actuated target type thrust reverser system. Amended 7/11/78.	EA	39540	Grumman Aerospace Corporation Bethpage, L.I., NY 11714
Falcon 10; T.C. A33EU	SA1201EA	Installation of cockpit pedestal extension or installation of cockpit pedestal extension and cockpit floor storage box. Issued 7/9/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
Falcon 10; T.C. A33EU	SA1203EA	Installation of a dual Sperry SPI-501 flight director system. Issued 8/8/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
Falcon 10; T.C. A33EU	SA1213EA	Installation of Collins FIS-85 flight instrument system and optional installation of Intercontinental Dynamics Corp. mach/airspeed indicators and barometric altimeter. Issued 12/4/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
Falcon 10; T.C. A33EU	SA1218EA	Instalaltion of Collins RNS-300 radar navigation system. Issued 1/12/81.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850
Falcon 10; T.C. A33EU	SA1223CE	Install King KFC-300 dual flight director flight control system (Category I configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1224CE	Install King KFC-300 dual flight director flight control system (Category II configuration). Issued August 1976.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
Falcon 10; T.C. A33EU	SA1294CE	Installation of Avcon Industries TSC-C39a stretcher, P/N 4001-105 or -106. Issued January 1977.	CE	12777	Avcon Industries, Inc. P.O. Box 4248 North Wichita Station Wichita, KS 67204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
Falcon 10; T.C. A33EU	SA1993SW	Install wing ice lights. Issued 6/9/75.	SW	26230	Cooper Airmotive, Inc. Executive Aircraft Division Redbird Airport Dallas, TX 75232
Falcon 10; T.C. A33EU	SA2225SW	Passenger compartment interior. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2226SW	Pressurization of nose cone to improve avionics reliability. Issued 3/19/76.	SW	11670	Arkansas Modification Center, Inc. P.O. Box 3356 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2846WE	Installation of Pulstar two-light supplemental lighting system. Issued 3/4/74.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92705
Falcon 10; T.C. A33EU	SA2857WE	Avionics modification and installations of an 8-passenger executive interior arrangement. Reissued 1/4/78.	SW	34280	Falcon Jet Corporation Little Rock Division P.O. Box 967 Little Rock, AR 72203
Falcon 10; T.C. A33EU	SA2885SW	Install three place couch at Station 181.0 to 239.0 right side. Issued 12/11/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, CK 73132
Falcon 10; T.C. A33EU	SA2919WE	Installation of TFE731-2 engines S/N P73143 and S/N P79101, modified in accordance with STC SE66WE. Issued 8/21/74.	WE	07502	AiResearch Aviation Company 402 S. 36th Street Phoeniz, AZ 85034
Falcon 10; T.C. A33EU	SA2983WE	Installation of a Garrett AirNAV 100 area navigation system. Issued 1/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3061WE	Installation of a Garrett AirNAV 100, 200 or 300 navigation system. Amended 8/29/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3544WE	Installation of GNS-500A VLF/OMEGA navigation system. Issued 1/27/78	WE	07500	AiResearch Aviation Company 6201 W. Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA3557WE	Installation of DeVore Aviation Corp. tail floodlights. Reissued 2/28/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
Falcon 10; T.C. A33EU	SA3752WE	Installation of a communications components Ontrac III VLF/Omega navigation system. Issued 10/25/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
Falcon 10; T.C. A33EU	SA4015SW	Nose radio rack. Issued 7/12/79.	SW	34280	Falcon Jet Corporation P.O. Box 7001 Dallas, TX 75209
Falcon 10A; T.C. A33EU	ST153RM	Installation of Canadian Marconi CMA-734 Omega navigation system. Issued 9/11/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
Falcon 20; T.C. A7EU	ST823SO	Installation of SEMCA 14640-113 air conditioning valve. Reissued 7/23/75.	EA	42125	Hermetic Aircraft Instrument Corporation 200 Marine Street Farmingdale, L.I., NY 11735
Mystere-Falcon 50; T.C. A46EU	SA1208EA	Installation of Teledyne Avionics angle of attach system, SL112B4800. Issued 10/8/80.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
Falcon 50; T.C. A46EU	SA4231SW	Vertical tail floodlight on upper and lower surfaces on horizontal stabilizer. Issued 11/13/80.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Blvd., N.E. Albuquerque, NM 87109

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
AYRES CORPORATION

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S2A; T.C. 2A9	SA653WE	Ceconite 101 covering of fuselage and tail group.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
S-2A, S-2B, S-2C, 600 S-2C, S-2R, 600 S-2D; T.C. 2A9, 2A7, A3SW, A4SW	SA4-1210	All fabric surfaces. Issued 3/21/77.	WE	52090	William G. Lott Box 635, Minter Village Bakersfield, CA 93307
S2A; S2B, S2C, 600-S2C; T.C. 2A9, 2A7	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Snow) S2A, S2B, S2C, 600-S2C, (Aero Commander) 600-S2D, S2R; T.C. 2A9, 2A7, A3SW, A4SW	SA2666WE	Ceconite 102 material covering of: S2A - fuselage and tail group; S2B, S2C, 600-S2C - empennage; 600-S2D - vertical fin, left and right elevators, rudder; S2R - complete aircraft. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
S2B, S2C, 600-S2C; T.C. 2A7	SA550WE	Wing auxiliary fuel tanks.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S2B; T.C. 2A7	SA609WE	Pratt & Whitney R-1340 AN-1 engine (restricted category only).	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S2B, S2C, 600-S2C; T.C. 2A7	SA1164WE	Ceconite 101 covering of empennage.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
S2C; T.C. 2A7	SA398SW	Electrical system.	SW	19670	C.G. Campbell P.O. Box 605 Archer City, TX 76351
S2C; T.C. 2A7	SA1630WE	Installation of Serv-Aero Engineering vibrodamp engine mount, mount, P/N 2059.	WE	71000	Serv-Aero Engineering, Inc. Salinas Municipal Airport Salinas, CA 93901
S-2C, 600-S2C; T.C. 2A7	SA1650SW	Replace military surplus AT-6 seat with Snow seat assembly 10136-1. Issued 5/7/73.	SW	73400	Snow Engineering Company 3708 Cedar Elm Wichita Falls, TX 76308
S2C, S2D, S2R; T.C. A3SW, 2A7	SA465NW	Installation of EAC-12D40-AG-100-4S propellers on Pratt & Whitney R-1340-AN-1-SH1H-1. Issued 6/13/77.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
600-S2C, -S2D, -S2R, T.C. 2A7, A3SW, A4SW	SA1834WE	Modification and installation of 70 ampere Motorola Model SA-70N-24 alternator (Vasquez P/N FMM-1002) system.	WE	82560	Frank C. Vasquez 5888 East Parkside Drive Fresno, CA 93702
600S-2D, S-2R; T.C. A3SW	SA1651SW	Replace military surplus AT-6 seat with Snow seat assembly 10136-1. Issued 5/7/73.	SW	73400	Snow Engineering Company 3708 Cedar Elm Wichita Falls, TX 76308
600S-2D, S-24; T.C. A4SW	SA1652SW	Replace military surplus AT-6 seat with Snow seat assembly 10136-1. Issued 5/7/73.	SW	73400	Snow Engineering Company 3708 Cedar Elm Wichita Falls, TX 7638
600-S2C; T.C. 2A7	SA732WE	Replacement engine mount including vibration dampeners.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2C, 600-S2C, S2R, 600 S-2D; T.C. 2A7, A3SW	SA2440WE	Installation of automatic flagman Model No. 4. Issued 2/14/72.	NW	03500	Air-Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
S-2R; T.C. A4SW	SA162GL	Install Cleveland Wheel and Brake conversion kit, P/N 199-68A. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S-2R; T.C. A4SW	SA834SO	Installation of Hamilton Standard Model 12D40/6101A-10S propeller approved under STC SP830SO on P&W R1340-AN-1, S1H1 or S3H1 engines listed in TDS A4SW. Issued 4/27/75.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
S-2R; T.C. A4SW	SA1008WE	Installation of poly-fiber covering material of horizontal and vertical stabilizer. Amended 8/21/79.	WE	75250	Stits Aircraft Coatings 43rd South Fort Drive P.O. Box 3084 Riverside, CA 92519
S2R; T.C. A3SW, A4SW	SA1103SO	Installation of a 400-gallon hopper window kit. Issued 9/21/79.	SO	79295	Transland, Inc. P.O. Box 4613 Crossroads Station Greenville, MS 38701
S-2R; T.C. A4SW	SA1165CE	Intallation of air conditioning system, restricted category. Issued 9/30/75.	CE	02950	Aero Space Controls Corp. 1050 North Mosley Wichita, KS 67214
S-2R; T.C. A4SW	SA1181CE	Installation of air conditioning system, normal category. Issued 11/21/75.	CE	02950	Aero Space Controls Corp. 1050 North Mosley Wichita, KS 67214
S-2R; T.C. A4SW	SA1638WE	Fabrication and installation of 400-gallon fiberglass hopper. Reissued 10/31/74.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
S-2R; T.C. A3SW	SA2807SW	P&W R1340-AN2 engine and Hamilton Standard 23D40/AG200-OS propeller. Issued 6/30/78.	SW	74946	STC Engineering Company 4410 Northwest 54th Street Oklahoma City, OK 73112
S-2R; T.C. A4SW	SA2901WE	Installation Serv-Aero vibrodamp engine mount in lieu of Aero Commander engine mount. Issued 6/18/74.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2 (R); T.C. A3SW	SA2969WE	Installation of Wright R-1300-1B engine and Hamilton Standard 3D40 or 23D40 constant speed propeller (normal or restricted category). Amended 2/27/75.	NW	47460	J & W Aircraft Company, Inc. P.O. Box 785 Warden, WA 98857
S-2R; T.C. A4SW	SA3227WE	Installation of an AiResearch TPE331-1-101Z, TPE331-25DA or TPE331-25FA turboprop engine. Amended 5/5/78.	WE	75210	Floyd D. Stilwell 5060 East Falcon Mesa, AZ 85205
S-2R; T.C. A4SW	SA3230WE	Installation of Hamilton Standard 3D40/6101A-18 constant speed propeler (restricted category). Issued 7/13/76.	WE	46770	Cliff Johnson 2000 South Union Avenue Bakersfield, CA 93307
S-2R; T.C. A3SW	SA3237WE	Installation of United Aircraft of Canada PT6A-27 or PT6A-34 engine. Amended 8/29/77.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2R; T.C. A3SW	SA3238WE	Installation of a United Aircraft of Canada PT6A-27 or PT6A-34 engine. Amended 3/29/77.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
S-2R (Restricted Category); T.C. A4SW	SA3497WE	Installation of Wright R-1820-71, -60; GR1820G-202A; 702C9GC1, 2, 3, 4; 704C9GC1, 2, 3, 4 engines and Hamilton Standard 4D350 or 33D50 constant speed propeller. Amended 5/22/80.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93905
S-2R (Snow) (Restricted Category); T.C. A4SW	SA3595WE	Installation of dual controls and bench seat. Issued 2/16/78.	WE	55627	Marsh Aviation Company 5060 East Falcon Drive Mesa, AZ 85205
S-2R (Restricted Category); T.C. A4SW	SA3767WE	Installation of 500 gallon fiberglass hopper and relocated oil cooler. Issued 10/26/78.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (Normal Category); T.C. A3SW	SA3842WE	Installation of 500 gallon fiberglass hopper and relocated oil cooler and deletion of the alternate air inlet doors. Reissued 3/7/79.	SO	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R (as modified under STC SA3227WE); T.C. A4SW	SA3886WE	Installation of Aerospace Controls Corp. No. 1922 air conditioning air conditioning system. Issued 3/20/79.	WE	55627	Marsh Aviation Company 5060 East Falcon Drive Mesa, AZ 85205

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S-2R (Restricted Category); T.C. A4SW	SA3889WE	Installation of Goodyear brake assembly P/N 95-50377 or P/N 5308865, Goodyear wheel assembly P/N 50-00444 or P/N 530884, and 11.00-13, Type III, 8 P.R. tire. Amended 6/15/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90907
S-2R (Restricted Category); T.C. A4SW	SA3890WE	Installation of Wright R-1820-40, -60, -71, -87 engine and Hamilton Standard 33D50 or 43D50 constant speed propeller. Amended 5/18/79.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
S-2R (Restricted Category); T.C. A4SW	SA3897WE	Installation of Pezetel Model PZL-3S engine and Dowty Rotol model CR289/3-110-F/1 propeller. Issued 4/11/79.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93905
S-2R; T.C. A3SW	SA3927WE	Installation of an AiResearch TPE331-1-1012 turboprop engine. Issued 5/11/79.	WE	75210	Floyd D. Stilwell 5060 East Falcon Drive Mexa, AZ 85205
S-2R; T.C. A4SW	SA3961WE	Installation of extended engine mount, revised cowling and induction system, Hamilton Standard 22D40 or 12D40 constant speed propeller, and modified elevator trim tab system. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708
S-2R; T.C. A4SW	SA4039SW	Lycoming LTP-101-600A1A turboprop. Issued 9/25/79.	SW	62196	Page Industries, Inc. P.O. Box 191 Yukon, OK 73099
S-2R; T.C. A4SW	SA4109WE	Installation of cockpit canopy/ fuselage fairing. Issued 3/7/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R, S-2D; T.C. A4SW	SA4110WE	Installation of spring-type tail wheel strut assembly. Amended 8/1/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R (Restricted Category); T.C. A4SW	SA4111WE	Installation of Wright R-1820-71, -60; GR1820G-202A; 702C9GC1, 2, 3, 4; 704C9G1, 2, 3, 4 engines and Hamilton Standard 43D50 or 33D50 constant speed propeller. Amended 5/22/80.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Salinas, CA 93905
S-2R, S/N 2526R and up modified by STC SA3961WE; T.C. A4SW	SA4112WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708
S-2R, S/N 2526R and up modified by STC SA3961WE, Normal Category; T.C. A3SW	SA4113WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708
S-2R (S/N 2526R and up modified by STC SA3897WE), S-2R-R3S (S/N R3S-001 and up); T.C. A4SW	SA4038WE	Installation of second pilot's seat and dual controls. Issued 10/29/79.	WE	71000	Serv-Aero Engineering, Inc. 37 Mortenson Avenue Municipal Airport Salinas, CA 93905
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category); T.C. A3SW	SA4045WE	Installation of second pilot's seat and dual controls. Reissued 1/29/80.	SO	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up as modified by STC SA3897WE); T.C. A4SW	SA4046WE	Installation of passenger/cargo compartment. Reissued 1/29/80.	SO	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R (S/N 2526R and up), S-2R-R3S (S/N R3S-001 and up modified by STC SA3897WE, normal category); T.C. A3SW	SA4047WE	Installation of passenger/cargo compartment. Reissued 1/29/80.	SO	14208	Ayres Corporation P.O. Box 3090 Albany, GA 31706
S-2R, S/N 2526R and up modified by STC SA3238WE, S-2R-T34 S/N 6009-6049, S/N T34-001 and up; T.C. A4SW	SA4107WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S-2R S/N 2526R and up modified by STC SA3237WE, S-2R-T34 S/N 6009-6049, S/N T34-001 and up (normal category); T.C. A3SW	SA4108WE	Installation of second pilot's seat and dual controls or passenger/cargo compartment. Reissued 8/12/80.	SO	14208	Ayres Corporation 1 Rockwell Avenue Albany, GA 31708
S-2R Thrush, S2-R-T34, -T15; T.C. A4SW	SA24RM	Installation of electrically driven freon air-conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
600 S2SR, 800 S-2R; T.C. A4SW	SA266NW	Installation of automatic flagman Model No. 6. Amended 5/12/77.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362
S2R-T34 (Normal Category), S2R-T15 (Restricted Category); T.C. A3SW, A4SW	SA1073SO	Installation of a 500 gallon hopper vent blister kit. Issued 5/29/79.	WE	79295	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA1-570	Installation of Hartzell Model HC-A2X20-4 or HC-A2V20-4 propeller equipped with 8433 or 8833-4 or V8433, V8833-4 blades respectively. Amended 6/29/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
35, A35 thru G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36; T.C. A-777, 3A15	SA11GL	Installation of Cleveland 6.00-6 wheels and brakes. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
35, A35 thru G35, H35, 35R, J35, K35, M35, N35, P35, S35, 45, A45, D45, 95, B95, B95A, D95A, E95, 95-55, -A55, -B55A, -B55B, -B55, -C55, -C55A, E55, D55, D55A, E55, E55A; T.C. A-777, 3A15, 3A16	SA19GL	Install Cleveland 7.00-8 wheels and brakes. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
35, A35 thru H35, J35, M35, 35R, 95; T.C. A-777, 3A15	SA23EA	Installation of third cabin window on both sides of fuselage. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, J35, K35, M35, 35-33; T.C. A777, 3A15	SA28EA	Installation of 12-gallon fiberglass wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, J35, K35, M35, 35-33; T.C. A777, 3A15	SA30EA	Installation of 13.5 gallon fiberglass wing tip tank assembly. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, 35R, D35, E35, F35, G35; T.C. 777	SA41EA	Wet-to-dry vacuum pump conversion kit 300-2. Reissued and Amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
35, A35 thru P35, 35-33, -A33, -B33; T.C. A777, 3A15	SA80EA	Installation of Tactair T-101 autopilot and optional installation of Tactair T-201 autopilot accessory kit (for use with Tactair T-101 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35, A35 thru H35, J35, K35, M35, N35, P35, S35, V35, 33, A33, B33, C33, C33A, E33, E33A, 55, A55, B55, B55A, B55B, C55, C55A, D55, D55A, 95, B95, B95A, D95A, E95; T.C. A-777, 3A15, 3A16	SA93GL	Install left hand side window, P/N W-2048 or W/T-2048. Amended 6/19/79.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
35, A35 thru H35, J35, K35, M35, N35, P35, S35, V35, 33, A33, B33, C33, C33A, E33, E33A, 55, A55, B55, B55A, B55B, C55, C55A, D55, D55A; T.C. A-777, 3A15, 3A16	SA94GL	Install right side door window, P/N W-2049 or W/T-2049. Amended 6/19/79.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
35, A35 thru H35, J35, K35, M35, N35, P35, S35, 33, A33, B33, 55, A55, B55, B55A, B55B, 95, B95, B95A, D95A, E95; T.C. A-777, 3A15, 3A16	SA95GL	Install one piece windshield (P/N W2050 or WT2050). Amended 6/19/79.	GL	39450	Great Lakes Aero Products 915 Kearsley Park Boulevard Flint, MI 48503
35, A35, B35, C35, D35, E35, F35, G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. A-777, 3A15	SA152NW	Installation of deck and glare shield (with or without instrument lights). Issued 1/13/75.	NW	70384	R.J. Schroers 4479 139th Avenue, S.E. Bellview, WA 98006

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, A35 thru H35, J35, K35, M35, N35, 35R, 35-33, 35-A33; T.C. A-777, 3A15	SA177EA	Installation of Monitair angle of attach system, Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
35, A35, B35, C35, D35, E35, F35, G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33D, F33A, F33, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A; T.C. A-777, 3A15	SA197NW	Installation of Clark three-light gear position indicator system. Issued 7/17/75.	NW	22786	Harold M. Clark, Jr. 7703 Husky Loop S.E. Olympia, WA 98503
35, A35 thru H35, J35, K35, M35, 35-33, N35, P35; T.C. A777, 3A15	SA283EA	Alternate fiberglass fuel tip tanks. Reissued 2/6/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, 35R, J35, K35, M35, N35, P35, 35-33, S-35, 35B-33, V35, V35TC, 35-A33, -C33, -C33A, 95-55, -A55, -B55, -C55, 95, B95, B95A, D95; T.C. A777, 3A15	SA593WE	Installation of single-piece windshield. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B- thru H-, J-, K-, M-, N-, P-, S-, V-; 65-88; 95-55, -A55, -B55, B55B, -C55; T.C. 3A15/A-777, 3A20, 3A16	SA808SW	Installation of Mitchell Model AK246 omni-tracker. Applicable only to aircraft modified by the following STCs SA617SW, SA638SW, SA651SW, SA701SW, SA742SW, SA754SW, SA755SW.	SW	60000	EDO-AIRE Mitchell P.O. Box 610 Mineral Wells, TX 76067
35, A35 thru G35, R35, H35 thru S35, 35-33, -C33, E33, F33, F33A, F33C, G33, V35, V35A, B, 36, A36, A36TC; T.C. 3A15, A-777	SA808SO	Installation of Beryl D'Shannon fiberglass tip tanks (15 gallons each), and fuel transfer system. Amended 2/8/80.	SO	16505	Beryl D'Shannon Specialties, Inc. Suite 120 175 West Wieuca Road Atlanta, GA 30342
35, A35 thru G35, 35R, H35, J35, K35, M35, N35, P35, S35, V35, 35-33, -A33, -B33, -C33, E33, F33, 35-C33A, E33A, E33C, F33A, F33C, G33, 36, A36, 95, B95, B95A, D95A, E95, 95-55, -A55, -B55, -B55A, -B55B, -C55, -C55A, D55, D55A, E55, E55A, 56TC, A56TC; T.C. A-777, 3A15, 3A16	SA838SO	Installation of Beryl D'Shannon fiberglass air scoops (inlet and exit). Amended 12/3/80.	SO	16505	Beryl D'Shannon Aviation P.O. Box 76155 Atlanta, GA 30328
35, A35 thru G35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35 thru S35, V35, V35A, V35B, 36, 36A; T.C. A-777, 3A15	SA942SO	Installation of adjustable directional trim device on lower aft fuselage (ventral location) Issued 7/1/77.	SO	16505	Beryl D'Shannon Aviation Specialities, Inc. P.O. Box 76155 Atlanta, GA 30328
35 thru 35R, 35-33 thru A36; T.C. 3A15, A-777	SA995SO	Installation of a single-piece sloped windshield. Amended 5/7/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4530 Jettridge Drive, N.W. Atlanta, GA 30327
35 thru 35R, 35-33 thru A-36; T.C. 3A15, A-777	SA997SO	Installation of a single-piece sloped windshield. Amended 11/21/79.	SO	16505	Beryl D' Shannon Aviation Specialties, Inc. c/o F.K. Leddick & Associates, Inc. 175 W. Wieuca Rd., Suite 120 Atlanta, GA 30342
35, A35, B35, C35, D35, E35, F35, G35, 35R (S/N D-1 thru D-4865); T.C. 777	SA999WE	Installation of either Jasco #6340-1 (35A) alternator kit or Jasco #6555-1 (50A) alternator kit. Amended 10/28/76.	WE	72500	Skytronics, Inc. 227 Oregon Street El Segundo, CA 90245
35, 33, 36, 45 Series; T.C. A777, 3A15, 5A3	SA1000CE	Install cabin and engine compart-fire suppression system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, A35, B35, C35, 35R, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, 35-33, -A33, -B33, -C33, -C33A, E33, F33, V35, V35A, B, E33A, 36, A36, F33A, G33; T.C. A36TC	SA1776SO	Installation of aileron and wing flap gap seals. Issued 10/10/80.	SO	30705	D'Shannon Products Company 4530 Jettring Drive Atlanta, GA 30327
35, A35, B35, C35 (up to and including S.N. 2901); T.C. A-777	SA1375WE	Installation of Dukes Astronautics Model 4140-00-39 Auxiliary Fuel Pump into fuel system.	NW	24200	Collins Aviation Service 6660 Perimeter Road Boeing Field Seattle, WA 98108
35, 33, 95, 56 Series; T.C. 3A15, 3A16	SA1497SW	Sombra screen kit No. BE-6L, BE-6S, BE-4. Issued 8/11/72.	SW	73750	Sombra Corporation 1122 LaVista Drive McAllen, TX 78501
35, A35 thru G35, 35R, H35, J35, K35, M35, N35, P35; T.C. 777, 3A15	SA1722WE	Installation of Fiberglass tail fairing. Reissued 1/12/76.	WE	13300	Aviation Enterprises, Inc. 3900 E. Spring Street Long Beach, CA 90806
35, A35, B35, C35, D35, E35, G35, F35, 35R; T.C. 777	SA2000SW	Dual control wheel. Issued 8/15/75.	SW	42185	Ray Hollander Box 600 El Paso, TX 79944
35, A35, B35, C35, Serial D1 through D2900; T.C. A-777	SA2029WE	Installation of Delta Sigmatronix Emergency Electric Fuel Pump Kit, PK-2, in lieu of Beech hand pump P/N 35-924230 (on aircraft equipped with Beech P/N 35-921171 or P/N 35-924065 fuel unit).	WE	29500	Delta Sigmatronix, Inc. P.O. Box 6183 San Jose, CA 95150
35, A35 thru F35, 35R, 35-33, 35-A33, -B & C33, H35, J35, K35, M35, N35, P35; T.C. 3A15	SA2219WE	Installation of Filtrator Company engine crankcase breather and vacuum pump air-oil separator. Reissued 7/10/75.	SO	16505	Beryl D'Shannon Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru G35, R35, H35, J35, K35, M35, N35, P35; T.C. A-777, 3A15	SA2271WE	Installation of long fiberglass tailcone to replace the short factory installed tailcone. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35 thru H35, 35R; J35, K35, M35, N35, P35, S35, V35, V35A, V35 (turbo), 35-33, -A33, -B33, -C33, -C33A, E33, E33A; T.C. 777, 3A15	SA2470WE	Installation of anticollision lighting system. Issued 2/8/72.	WE	70500	Scientifico Scientific Components Company 350 Vista Bays Newport Beach, CA 92660
35, A35 thru H35, J35, K35, M35, N35, P35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, F33, F33A, F33C, G33; T.C. A-777, 3A15	SA2633WE	Installation of enlarged window and baggage compartment. Amended 8/16/78.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, D35, F35, G35, 35R, E35; H35, J35, K35, M35, N35, P35, 35-33, 35-A33, -B33, -C33, E33, F33, G33, V35, V35A, V35B, S35, 35-C33A, E33A, E33C, F33A, F33C, 36, A36; T.C. A-777, 3A15	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA2858WE	Installation of right and left hand cockpit side windows. Reissued 1/7/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA3020WE	Installation of exhaust silencer. Reissued 2/9/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35, A35, A35B, D, E, F, G, 35R; T.C. 777	SA3271SW-D	Mitchell yaw damper system YK631. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A777	SA3337WE	Installation of ventral air skeg. Amended 4/2/79.	WE	84396	Walker Engineering, Inc. 2240 Sawtelle Boulevard Los Angeles, CA 90064

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
35, A35, B35, C35, D35, E35, F35, G35, 35R; T.C. A-777	SA3678WE	Installation of air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
35-33, -A33, -B33, -C33, -E33C, -C33A, E33, E33A, F33, F33A, F33C, G33, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; 36, A36; T.C. 3A15	SA1474CE	Installation of redundant engine fuel flow transmitter and cockpit indicator. Reissued 4/24/79.	WE	71740	Silver Instruments, Inc. 2436 Stanwell Drive Concord, CA 94520
35-A33, -B33, -C33, C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA3025SW-D	Automatic flight system AK497, cons. of Century IIB autopilot with optional radio coupler. Issued 9/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35 (Normal or Utility Category), A35, B35, C35, D35, E35, F35, G35 (Utility Category); T.C. A-777	SA3191WE	Installation of wing tip fences. Issued 5/11/76.	WE	64690	John Pixton Enterprises P.O. Box 342 Santa Rosa, CA 95402
35-C33, -C33A, E33, F33C, G33, F33A; T.C. 3A15	SA4158SW	S-TEC system 60 (two axis) flight guidance system, Model ST-009 (14 volt system). Issued 7/29/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
35, 35R; T.C. A-777	SA1423WE	Wing truss reinforcement, front spar, and change of hinge points for landing gear idler arm. Amended 6/14/76.	WE	59470	Fred J. Miller 355 Vista Bays Newport Beach, CA 92660
A35 thru F35, G35 and 35R, H35, J35, K35, M35; T.C. A-777, 3A15	SA1-27	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, CH 45226
A35 thru G35, H35; T.C. A77, 3A15	SA1-303	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35 thru G35, H35; T.C. A777, 3A15	SA1-368	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35, B35, C35, D35, E35, F35, G35, H35; T.C. A-777, 3A15	SA144EA	Increase to 200 pounds in maximum gross weight for takeoff and landing. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35 thru H35, J35, K35, M35, N35, P35; 35-33, -A33, -B33, C33A, E33A, E33C, F33A, F33C, S35, V35, V35A, V35B; T.C. A-777, 3A15	SA153EA	Installation of Beryl D'Shannon fiberglass tip tanks (15 gal. RB4-100, ref. STC's SA283EA and SA134EA) and fuel transfer system. Amended 9/28/79.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. 4530 Jettridge Drive, S.W. Atlanta, GA 30227
A35 thru H35, J35, K35, M35; T.C. A-777, 3A15	SA181EA	Increase of 200 pounds in maximum gross weight for takeoff and landing. Reissued 4/3/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
A35, B35, C35, D35, E35, F35, G35, T.C. A-777	SA384WE	Adjustable pilot and copilot seat. Reissued 1/12/76.	WE	13300	Aviation Enterprises, Inc. 3900 E. Spring Street Long Beach, CA 90806
A35 thru G35, 35R, H35, J35; T.C. A-777, 3A15	SA507WE	Adjustable back rest. Reissued 1/12/76.	WE	13300	Aviation Enterprises, Inc. 3900 E. Spring Street Long Beach, CA 90806
A35, B thru E; T.C. 777	SA1270SW	Mitchell automatic flight system model AK328 cons. of Century I autopilot with omni tracking system. Issued 3/1/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35 thru H35, J35, K35, 35R, 35-33, -A33, -B33, -C33, -C33A, E33, F33, F33A, G33; T.C. A-777, 3A15	SA2081WE	Installation of Madras Air Service P/N MAS 102 wing tips. Amended 4/5/74.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
A35 thru H35; T.C. A-777, 3A15	SA2131WE	Installation of Delta Sigmatronix emergency electric fuel pump P/N 29000 in above models equipped with Beech P/N 35-924230 fuel unit.	WE	29500	Delta Sigmatronix, Inc. P.O. Box 6183 San Jose, CA 95150

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A35 thru H35, J35, K35; T.C. 777, 3A15	SA2200SW	Continental IO-520-B or -BA engines. Issued 9/5/75.	SW	78420	Texas Aviation Engineering Company Meacham Field Fort Worth, TX 76106
A35, B35, C35, D35, E35, F35, G35; T.C. A-777	SA2546WE	Installation of Pathfinder Engineering Corp. Model P1-( ) autopilot system. Amended 11/13/74.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
A35, B35, C35, D35, E35, F35, G35; T.C. A-777	SA2547WE	Installation of Pathfinder Engineering Corporation Model P2-( ) autopilot system. Reissued 2/20/74.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
A35 thru H35, J35, K35, N35, M35, P35, S35, 35-33, -A33, -B33, -C33, G-33, V35, V35B, E33, E33A, V35A, 36, A36; T.C. A777, 3A15	SA2654WE	Installation of Pathfinder Model P2A autopilot system. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
A35, B35, C35, D35, E35, F35, G35; T.C. A777	SA3116SW-D	Mitchell automatic flight system AK328 cons. of Century I autopilot with optional omni tracker. Issued 3/16/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35, B, C, D, E, F, G; T.C. 777	SA3113SW-D	Automatic flight system AK415 cons. of Century IIB autopilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
A35, A36TC; T.C. 3A15	SA3339SW	Installation of Mitchell automatic flight system Model AK809 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
C35; T.C. A-777	SA236GL	Installation of a Continental O-470-G engine and McCauley propeller #2A36C23-11-DE/S-84B-0. Issued 5/4/78.	GL	74970	Robert Steffey 37344 Woodland New Baltimore, MI 48047
C35 thru H35, J35, K35, M35, N35, 35-33, 35-A33; T.C. A-777, 3A15	SA361EA	A. Installation of monitair angle of attack and stall warning kit number 92-107, and B. Installation of Monitair angle of attack and stall warning kit number 92-105. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
C35, D35, E35, F35, G35; T.C. A-777	SA604NW	Install Lycoming IO-540-K engine and Hartzell HC-E2YR-1BF/F8476D-4 propeller. Issued 7/6/78.	NW	52625	Machen, Inc. S.3608 Davison Boulevard Spokane, WA 99204
C35, D35, E35, F35, G35; T.C. A-777	SA1584CE	Installation of elevator tail cone fairing. Issued 4/15/80.	CE	73220	Smith Speed Conversions, Inc. P.O. Box 430 Johnson, KS 67855
C35, D35, E35, F35, G35; T.C. 777	SA3267SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. 777	SA3268SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
C35, D35, E35, F35, G35; T.C. A-777	SA4000WE	Installation of radome in wing leading edge. Issued 7/27/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
E-35; T.C. A-777	SA4043WE	Installation of Continental IO-520-BA engine and McCauley 3A32C propeller. Issued 10/26/79.	WE	06755	Aircraft Technical Service, Inc. 6701 Odessa Avenue Van Nuys, CA 91406
F35; T.C. 7777	SA173GL	Installation of Dukes fuel pump P/N 4140-00-39. Issued 5/27/77.	GL	01838	Aerodynamics, Inc. Oakland Pontiac Airport P.O. Box 508 Pontiac, MI 48056
H35, J35, K35, M35, N35, P35, S35, 35-33, -A33, -B33, -C33, -33A; T.C. 3A15	SA1-636	Install 300 Series dry vacuum pump conversion kits. Amended 12/8/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H35 Series; T.C. 777	SA198NW	Installation of 3 bladed McCauley 3A34C76FM/S82NB-2 propeller with Woodward A210680 governor on Continental O-470-G engine. Issued 7/21/75.	NW	77570	Mel G. Taylor 20005 Northeast 13th Street Camas, WA 98607
H35 Series; T.C. 777	SA259NW	Installation of TCM continuous flow fuel injection system (EQ No. 5701) replacing carbureation system. Issued 2/17/76.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road South Seattle, WA 98108
35 Series H thru P; T.C. 3A15	SA470NW	Installation of Cessna oil filter. Issued 7/14/77.	NW	24200	Collins Aviation, Inc. 6660 Perimeter Road Seattle, WA 98108
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA421GL	Installation of aileron and flap gap seals. Amended 10/17/80.	GL	33997	Executive Aircraft Maintenance Corp. Crystal Lake Airport Crystal Lake, IL 60014
H35, J35, K35, M-35, N-35, P35, 35-33, 35-A33, 35-B33, 35-C33, E33, F33; T.C. 3A15	SA695CE	Install Frantz oil filter. Amended 5/27/71.	GL	70360	Schmidt Aero Service Municipal Airport Worthington, MN 56187
H35, J35, K35, M35, N35, P35, S35, V35, V35B, 35-C33A, E33A, E33C, F33A, F33C, G33, 36, A36; T.C. 3A15	SA884SO	Installation of exhaust silencers. Issued 2/11/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, 35-33, E33, -A33, -C33; T.C. 3A15	SA975SW	Installation of cabin air conditioner. Reissued 5/7/79.	RM	01950	Aero Engineering Corporation 8C Garden Center Broomfield, CO 80020
H35, J35, K35, M35, N35, P35, 35-33, 35-A33, -B33, -C33, E33, F33; T.C. 3A15	SA1252WE	Installation of Rajay turbocharged Continental O-470-G-C1 and/or IO-470-C, -J, -K, -N engines. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90807
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA1585CE	Installation of elevator tail cone fairing. Issued 4/15/80.	CE	73220	Smith Speed Conversions, Inc. Box 430 Johnson, KS 67855
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-33, -A33, -B33, -C33, -C33A, G33, -E33A, F33A, 35, A35; T.C. 3A15	SA2619WE	Installation of Pathfinder Model P1-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, M35, N35, P35, S35, V35, V35A, F33A, 35-33, -A33, -B33, -C33, -C33A, E33A, G33, 36, A36; T.C. 3A15	SA2620WE	Installation of Pathfinder Model P2-( ) autopilot. Amended 11/25/75.	WE	12380	Astronautics Corporation of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33; T.C. 3A15	SA2870WE	Installation of right and left hand cockpit side windows. Reissued 2/2/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA3117SW-D	Mitchell automatic flight system AK328 cons. of Century I autopilot with optional omni tracker. Issued 3/16/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35; T.C. 3A15	SA3127SW-D	Mitchell automatic flight system AK415 cons. of Century IIB autopilot with optional radio coupler. Issued 3/26/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33C, F33A, G33, 36, A36; T.C. 3A15	SA3184WE	Installation of ventral air skeg. Amended 4/12/79.	WE	84396	Walker Engineering 2240 Sawtelle Boulevard Los Angeles, CA 90064
H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B (Utility Category); T.C. 3A15	SA3190WE	Installation of wing tip fences. Issued 5/11/76.	WE	64690	John Pixton Enterprises P.O. Box 342 Santa Rosa, CA 95402

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3269SW-D	Mitchell automatic flight system AK727 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA3270SW-D	Mitchell automatic flight system AK728 consisting of Century IV autopilot or AK728FD consisting of Century IV flight director autopilot with optional remote annunciator. Issued 3/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
H35, J35, K35, M35, N35; T.C. 3A15	SA3310WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 1/6/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
H35, J35, K35, M35, N35, P35, 35-33, -A33, -B33, -C33; T.C. 3A15	SA3523WE	Installation of an airfoil separator in the engine breather system. Issued 11/25/77.	WE	84396	Walker Engineering Co. 2240 Sawtelle Los Angeles, CA 90025
H35, J35, K35, M35, N35, P35, S35, V35, F33, E33A, E33C, F33, F33A, F33C, G33, V35A, V35B, 36, A36, A36TC; T.C. 3A15	SA3999WE	Installation of radome in wing leading edge. Amended 8/14/79.	WE	43566	I.F.R. Avionics, Inc. 16425 Hart Street Van Nuys, CA 91406
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA4100WE	Installation of DTL-1000, -1001 and/or -1002/3 cautopilot adapters for the Edo-Aire Mitchell Century III autopilot. Issued 2/12/80.	WE	47775	Douglas L. Kettler 1212 North Boradway, Apt. H Escondido, CA 92026
H35, J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36, A36TC; T.C. 3A15	SA4180WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerccessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
H35, J35, K35, M35, N35, P35; T.C. 3A15	SA4198SW	S-TEC system 60 (two axis) flight guidance system Model ST-010 with optional flight director/steering horizon and vertical speed indicator/selector (14 volt system). Issued 9/12/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
J35; T.C. 3A15	SA686CE	Install Continental IO-520-V engine derated to 250 H.P. and Hartzell HC-C3YF-1/8468A-8R propellers. Reissued March 1975.	SW	03034	AeroSTOL Company P.O. Box 4574 Fort Worth, TX 76106
J35, K35, M35, 35-33; T.C. 3A15	SA1-354	Auxiliary wing tip fuel tanks. Reissued 2/14/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
J35, V35, A35, B35, C35, D35, E35, F35, G35; T.C. 3A15, 777	SA754SW	Mitchell automatic aileron stabilizer AK203.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
J35, K35, M35, N35, P35, S35, V35, V35B, E33, E33A, F33, F33A, 36, A36, 35-33, -A33, -B33, -C33, E33C, F33C, -C33A, V35A; T.C. 3A15	SA1474CE	Installation of redundant engine fuel flow transmitter and cockpit indicator. Reissued 4/24/79.	WE	71740	Silver Instruments, Inc. 2436 Stanwell Drive Concord, CA 94520
J35, K35, M35, N35, P35, S35, V35, V35A, B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2978WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
K35, M35, N35, P35, S35, V35, V35A, V35B; T.C. 3A15	SA1140CE	Installation of King model KFC-200 2-axis (3 optional) autopilot system with a King KCS-55 (or -55A) compass with a King KI-255 (or KI-256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 7/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M35; T.C. 3A15	SA958EA	Installation of Teledyne Continental IO-520-Ba Engine and associated components in place of Teledyne Continental IO-470-C engine and associated components. Issued 7/30/73.	EA	41760	Helicopter & Airplane Service Corp. Montgomery County Airpark Gaithersburg, MD 20760
N35; T.C. 3A15	SA4193WE	Replacing the control instrument panel. Issued 7/29/80.	WE	13300	Aviation Enterprises, Inc. 2870 East Wardlow Road Long Beach, CA 90807
N35, P35, S35; T.C. 3A15	SA134EA	15-gallon fiberglass wing tip fuel tanks. Reissued 2/6/75.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
P35, 35-B33; T.C. 3A15	SA178EA	Installation of Monitair angle of attach system, Model AA-2. REissued.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, 35-B33; T.C. 3A15	SA260EA	Installation of Monitair angle of attack and stall warning kit number 92-110. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
P35, S35, V35, V35A, V35B; T.C. 3A15	SA3203WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/24/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
S35, V35, V35A, V35B, 35-B33, 35-C33, 35-C33A, E33, E33A, F33, F33A, G33, 36, A36, A36TC; T.C. 3A15	SA180GL	Install Norton Company radar pod P/N 4133X. Amended 8/22/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
S35, V35, V35A, V35B, 35-B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36, A36TC; T.C. 3A15	SA328GL	Installation of Norton radome kit No. 4222X. Amended 6/3/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
S35, V35; T.C. 3A15	SA352EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
S35, V35, V35A, V35B, 35-C33A, E33A, E33C, F33A, F33C, 36, A36; T.C. 3A15	SA449GL	Installation of Shadin Co. 910501 fuel or 910503 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Suite 206 Minneapolis, MN 55426
S35, V35, V35A, V35B; T.C. 3A15	SA468SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and flight director indicator DH-841( ). Amended 11/14/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FI 33310
S35, V35, V35B, 35-C33A, E33A, E33C, V35A, 36, A36, F33A, F33C; T.C. 3A15	SA785CE	Installation of Hartzell Propellers PHC-C3YF-1R/8468-6R, PHC-C3YF-1R/8468A-6R, PHC-C3YF-1RF/F8468A-6R and BHC-C2YF-1B/8468AR, BHC-C2YF-1BF/F8468AR. Amended 5/16/80.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
S35, V35, V35A, V35B; T.C. 3A15	SA1069SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director. Issued 5/3/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FI 33310
S35, V35, V35A, V35B; T.C. 3A15	SA1417CE	Install elevator tail cone fairings. Issued 5/17/78.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
S35 S/N D7482 thru D796, V35, V35A, V35B; T.C. 3A15	SA1744SW	Mitchell automatic flight system AK409 cons. of Century I autopilot with optional omni tracker. Issued 10/18/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B, 35-C33A, E33A, E33C, F33A, F33C; T.C. 3A15	SA2556WE	Installation of Rajay turbosupercharged Continental TSIO-520-D engine. Amended 11/17/78.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
S35, V35, V35A, V35B, 35-C33A, E33C, F33A, F33C, 36, A36; T.C. 3A15	SA2935WE	Installation of Model DFF-5000 fuel monitor. Issued 10/25/74.	WE	71740	Silver Instruments 1896 National Avenue Hayward, CA 94545

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S35, V35, V35A, V35B; T.C. 3A15	SA3159SW-D	Automatic flight system AK409, consisting of Century I autopilot with optional omni tracker. Issued 10/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3172SW-D	Yaw damper Model YK631. Issued 12/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3272SW-D	Mitchell automatic flight system AK501 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/10/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 601 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3292SW-D	Mitchell command electric trim AK726. Issued 7/11/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, B; T.C. 3A15	SA3310SW-D	Installation of Mitchell automatic flight system AK804 consisting of Century 41 autopilot or AK804FD consisting of Century 41 autopilot flight director. Issued 11/3/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, B; T.C. 3A15	SA3324SW-D	Installation of Mitchell automatic flight system AK803 consisting of Century 21 autopilot. Issued 12/6/78.	SW	60000	Mitchell Industries,Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3327SW	Installation of Mitchell automatic flight system AK805 consisting of Century 21 autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35, V35A, V35B; T.C. 3A15	SA3328SW	Installation of Mitchell automatic flight system AK806/FD consisting of Century 41/flight director autopilot. Issued 8/29/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
S35, V35A, F33A, F33C, 36, A36; T.C. 3A15	SA3548WE	Installation of air/oil separator. Amended 4/28/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90025
S35, V35, V35A, V35B; T.C. 3A15	SA3668WE	Installation of Silver Instruments Fueltron IG digital fuel flow and totalizer system. Issued 7/13/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
S35, V35, V35A, V35B; T.C. 3A15	SA4139SW	S-TEC system 60 (two axis) flight guidance system Model ST-007 with optional flight director/steering horizon and vertical speed. Issued 6/16/80.	SW	79463	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
V35; T.C. 3A15	SA503NW	Installation of Robertson STOL kit. Issued 9/7/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
V35; T.C. 3A15	SA707NW	Add RCA Primus weather radar. Issued 1/11/79.	NW	68500	Robertson Aircraft Corp. 839 West Perimeter Road Renton, WA 98055
V35, V35A; T.C. 3A15	SA925SW	Mitchell Automatic Flight System AK263 cons. of Century II autopilot with radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1185CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
V35, V35A, V35B; T.C. 3A15	SA1186CE	Installation of Collins AP-107 (2 axis) autopilot system and interface with Collins FD-112V flight director. Issued April 1976.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
V35, V35A, V35B; T.C. 3A15	SA1500SW	Mitchell automatic flight system FD/AP282-382 cons. of flight director/autopilot with automatic command electric pitch trim. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
V35, V35A, V35B; T.C. 3A15	SA1501SW	Mitchell automatic flight system AK383 cons. of Century III autopilot with optional automatic command electric trim, radio coupler, and glide slope coupler. Issued 8/21/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA1722SW	Mitchell automatic flight system AK402, cons. of Century IIB autopilot with optional radio coupler. Issued 8/29/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3034SW-D	Mitchell automatic flight system AK503 or AK503FD cons. of Century IV autopilot or Century IV flight director autopilot with command/ auto. electronic trim and annuciator panel. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA3035SW-D	Mitchell automatic flight system AK501 cons. of Century III autopilot with optional command/auto. elec. pitch trim, radio, and glide slope coupler. Issued 12/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35, V35A, V35B; T.C. 3A15	SA4085SW	S-TEC System 60 (single axis) flight guidance system model ST-001. Issued 2/22/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Walters Industrial Complex Mineral Wells, TX 76067
V35, F33A, C, A36; T.C. 3A15	SA4133SW	S-TEC system 60-1 (single axis) flight guidance system, ST-002. Issued 5/29/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
V35A; T.C. 3A15	SA882SW	Mitchell automatic flight system AK260 consisting of Century III autopilot, optional radio coupler, automatic pitch trim, stabilizer, and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35A; T.C. 3A15	SA2030WE	Installation of Brittain B-VII, NAV-2B, B2C and BSA-4 Flight Control Systems. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, E33 and E33A; T.C. 3A15	SA1858WE	Installation of Brittain Model B2C Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
V35A, V35B, S35, F33A, A36; T.C. 3A15	SA3824WE	Installation of SDI Model CFS-1000-T001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Irvine, CA 92714
V35B (Utility Category); T.C. 3A15	SA2947WE	Installation of Collins AP-107 autopilot and FD-106 PV flight director. Reissued 4/22/75.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids Airport Cedar Rapis, IA 32406
V35B; T.C. 3A15	SA3215SW-D	Mitchell automatic flight system AK671 consisting of Century I autopilot with optional omni tracker. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3216SW-D	Mitchell automatic flight system AK672 consisting of Century IIB autopilot with optional radio coupler. Issued 7/7/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3217SW-D	Mitchell automatic flight system AK673 consisting of Century III autopilot with optional radio coupler and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3218SW-D	Mitchell automatic flight system AK674 consisting of Century IV autopilot or AK674FD consisting of Century IV flight director autopilot with remote annunciator. Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3219SW-D	Mitchell command electric trim system AK675. Issued 8/9/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
V35B; T.C. 3A15	SA3220SW-D	Mitchell yaw damper system YK676 Issued 6/20/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
V35B; T.C. 3A15	SA3358SW-D	Mitchell automatic flight system YK833 consisting of yaw damper system. Issued 3/21/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
V35B; T.C. 3A15	SA4155SW	S-TEC system 60 (two axis) flight guidance system ST-017. Issued 7/18/80.	SW	74963	S-TEC Corporation Route 2, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
V35B, A36, F33; T.C. 3A15	SA3683WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
35-33 Series; T.C. 3A15	SA1808WE	Installation of Brittain Industries B-5 Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33 Series; T.C. 3A15	SA1886WE	Installation of Brittain Industries NAV-2B Flight Control System. Reissued 10/20/72.	SW	17496	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3098SW-D	Mitchell automatic flight system AK306 cons. of Century I autopilot with optional omni tracker. Issued 1/12/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-33, -A33, -B33, -C33, E33, F33; T.C. 3A15	SA3107WE	Installation of exhaust silencer. Reissued 2/9/76.	SO	15505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
35-33, -A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36; T.C. 3A15	SA1036EA	Installation of vertical tail floodlights on upper surfaces of the horizontal stabilizer. Reissued 2/28/80.	SW	31302	DeVore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
35-33, 35-A33, -B33, -C33, -C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A36TC; T.C. 3A15	SA1416CE	Install flap and aileron fairings and seals. Amended 3/24/80.	CE	73220	Smith Speed Conversions Stanton County Airport P.O. Box 601 Johnson, KS 67855
35-A33; T.C. 3A15	SA270EA	Installation of a stability augmentation safety system (with or without camera system installed). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-A33; T.C. 3A15	SA1310CE	Chrome-plated brake disc installation. Issued 6/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
35-B33, -C33A; T.C. 3A15	SA1289CE	Install King KFC-200, 2-axis (3 optional) flight control system with a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 10/21/77.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
35-C33, F33; T.C. 3A15	SA238GL	Installation of Continental IO-470-N engine and McCauley 2A36C23/84B-0 propeller. Amended 11/14/78.	GL	39517	Stewart Gross P.O. Box 634 Rochester, MN 55901
35-C33, 35-C33A; T.C. 3A15	SA394EA	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
35-C33; T.C. 3A15	SA896SW	Mitchell automatic flight system AK264 cons. of Century III autopilot with optional automatic aileron stabilizer, radio and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
35-C33, E33, F33; T.C. 3A15	SA1218SW	Automatic flight system AK306 cons. of Century I and optional tracking system. Issued 11/10/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1121A, 1121B; T.C. A2SW	SA1821SW	Bendix RDR-1200 weather radar. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1822SW	ADF installation - Collins DF206. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1823SW	Bendix MKA-28 marker beacon. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1824SW	Bendix RTA42A VHF communications. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1825SW	Bendix ALA-51 radio altimeter. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1826SW	Collins 621A-6 ATC transponder. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1827SW	UHF communication/ADF - Collins ARC159/DF301E. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1828SW	Bendix RNA-26F VOR/ILS system. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1829SW	Sierra tacan system. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1831SW	Pointer II emergency locator transmitter beacon. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1832SW	J.E.T. SI-2500 inverters. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 63074 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1833SW	Collins 346B-3 audio/interphone system. Issued 7/3/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1834SW	Radio racks. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1835SW	Flight inspection console structure. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1836SW	Pedestal extension. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1837SW	Seat modification. Issued 10/3/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1838SW	Standby gyro system. Issued 3/22/74.	SW	63750	Qualitron System, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1840SW	Emergency lighting. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1841SW	Ramp air conditioning. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1843SW	Interior lighting. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1844SW	Emergency locator receiver. Issued 3/22/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121A, 1121B; T.C. A2SW	SA1849WE	Installation of United Control Speed Command System.	WE	85135	Western Commander, Inc. 8029 Woodley Avenue Van Nuys, CA 91406
1121A, 1121B; T.C. A2SW	SA2644WE	Installation of single point refueling system. Issued 2/7/73.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1121B; T.C. A2SW	SA1819SW	FCS-105 consisting of dual FD109 flight directors and AP105 autopilot. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121B; T.C. A2SW	SA1830SW	IDC altitude alerter/vertical navigation system. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121B; T.C. A2SW	SA1842SW	Electrical power system. Issued 5/2/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1121B; T.C. A2SW	SA1877SW	Area navigation system. Issued 4/30/74.	SW	63750	Qualitron Aero, Inc. P.O. Box 60374 Houston, TX 77060
1123; T.C. A2SW	SA956EA	Installation of Tramm battery temperature indicating system Model BT1600 and battery isolation system. Amended 8/21/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1123; T.C. A2SW	SA1566SW	Teledyne Avionics normalized angle of attack system. Reissued 10/30/78.	SW	44860	Israel Aircraft Ind. Int'l., Inc. 2025 S. Nicklas, Suite 115 Oklahoma City, OK 73128
1123; T.C. A2SW	SA2897WE	Installation of single point refueling system. Issued 6/11/74.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1124; T.C. A2SW	ST231GL	Installation of two Canadian Marconi CMA-734 omega navigation systems. Issued 3/24/78.	GL	02392	Aeronautical Systems, Inc. 4393 E. 17th Avenue Columbus, OH 43219
1124; T.C. A2SW	SA2858SW	Installation of Lear Siegler 23065-018-1 starter generator. Issued 11/3/78.	SW	44860	Israel Aircraft Ind. Int'l, Inc. 2025 South Nicklas Oklahoma City, OK 73128
1124; T.C. A2SW	SA4129SW	Aft fuselage spare generator ballast. Issued 5/23/80.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73123

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

KAWASAKI HEAVY INDUSTRIES, LTD.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
KV107-II; T.C. H1PC	SH435NW	Install Boeing kit to increase the rotorcraft external load carrying capability from 19,000 to 22,000 pounds. Issued 4/12/77.	NW	25000	Columbia Helicopters P.O. Box 3500 Portland, OR 97218
KV-107-11; T.C. H1PC	SH897NW	Replacement of the differential collective pitch trim actuator (DCPT) in the longitudinal control system by a rigid link. Issued 3/4/80.	NW	25000	Columbia Helicopters P.O. Box 3500 Portland, OR 97218

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

LOCKHEED AIRCRAFT CORP.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
(SP-2E) P2V-5F; T.C. A17EA	ST163RM	Installation of 3100 gallon tank for fire retardant material delivery.	RM	33899	Evergreen Air of Montana P.O. Box 8345 Missoula, MT 59801
Vega D-2; T.C. 2-377	SA4-1283	Ceconite 101 covering of plywood components.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
B-34, PV-1; L.T.C. 13	SA3-360	Oil separator assembly on Pratt & Whitney R2800-CB16 Series engines.	GL	02500	Aeroquip Corporation 300 S. East Avenue Jackson, MI 49203
B-34, PV-1; L.T.C. 13	SA4-323	Full Flow oil filter 30816A with element 1A0097.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
B-34, PV-1, 18; L.T.C. 13, T.C. 723	SA1744WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
PV-1; L.T.C. 13	SA4-465	Rudder spring tab assembly.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
PV-1; L.T.C. 13	SA4-497	Increase in flaps extended speed varying from an increase to 243 mph at 12.5° flaps to 145 mph at 100° flaps.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA4-528	106-1 engine mount core.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505
PV-1; L.T.C. 13	SA4-1329	Alternate fuel source equipped with Pratt & Whitney R-2800 Series "C" engines and fuel flow meters.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
PV-1; L.T.C. 13	SA40SW	PV-1 oil tank modification to 24 U.S. gallons.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA46SW	Cockpit windows and windshield.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA47SW	Elevator and rudder control systems modification.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA48SW	Modification of aft fuselage to lower tail gear 9 inches.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA49SW	Vista Vision cabin windows and cabin emergency exit.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA52SW	Elevator nose down spring with electric actuator relief system.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA63SW	Pitot and static on wing tip boom.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA79SW	Goodyear six spot brake system on aircraft previously equipped with three spot brakes.	SW	81300	C.R. Ursell 109 Briarcliff Drive San Antonio, TX 78205
PV-1; L.T.C. 13	SA85SW	Elevator boost system.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1; L.T.C. 13	SA98CE	High intensity wing tip lights Model A, B, or E, tail light Model C, with or without Model 1 or 2 high-intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
PV-1; L.T.C. 13	SA123SW	Fiberglass horizontal stabilizer short tips.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PV-1: I.T.C. 13	SA126SW	Dual actuator rod modification on elevator trim control tab.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1: I.T.C. 13	SA205SW	Electric trim fail safe feature. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
PV-1: I.T.C. 13	SA212SW	Ground air conditioner unit.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1: I.T.C. 13	SA228SW	Underwing exhaust system.	SW	29000	The Dee Howard Company P.O. Box 16216 SAn Antonio, TX 78205
PV-1: I.T.C. 13	SA232SW	Outer wing panel extension.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1: I.T.C. 13	SA286SW	Modification of aircraft.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1: I.T.C. 13	SA309SW	Elevator nose down spring and relief system.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1: I.T.C. 13	SA449SW	Pressurized fuselage and other modifications.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1: I.T.C. 13	SA545SW	Tail cone.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1: I.T.C. 13	SA714SW	Main cabin windows enlarged.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1: I.T.C. 13	SA715SW	Cockpit side windows.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1: I.T.C. 13	SA718SW	Lowering of tail gear trunnion.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1: I.T.C. 13	SA719SW	Wing tip extended.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1: I.T.C. 13	SA720SW	Aerodynamic smoothing of outer wing.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1: I.T.C. 13	SA717SW	Elevator torque tube flange.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1: I.T.C. 13	SA783SW	Clamp, flap actuating cylinder #500 P/N 5-104268-1.	SW	29000	The Dee Howard Company 130 S. Terminal Drive San Antonio, TX 78205
PV-1: I.T.C. 13	SA760SW	Flap actuating cylinder attach bracket.	SW	29000	The Dee Howard Company P.O. Box 16216 San Antonio, TX 78205
PV-1, PV-2: LTC-13	SA4-487	Radar nose for Bendix C-Band, Bendix X-Band, or RCA C-Band.	WE	62060	PacAero Engineering Corporation 3021 Airport Avenue Santa Monica, CA 90405
PV-1, 18: I.T.C. 13, T.C. 723	SA220SW	Omni antenna. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
PV-1, 18 (Howard 250): I.T.C. 13, T.C. 723	SA285SW	Hydraulic windshield wipers. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
PV-1, 18 (Learstar): I.T.C. 13, T.C. 723	SA451CE	Supplemental high intensity position light system. Reissued 10/17/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92668
PV-2: I.T.C. 13	SA4-381	Deletion of bat wings, new radar nose, and other modifications.	WE	61778	Oakland Airmotive Company International Airport Oakland, CA 94614
PV-2: I.T.C. 13	SA4-529	Engine mount core 106-1F and 106-1J.	WE	83500	Vibration Isolation Products, Inc. 212 W. Magnolia Burbank, CA 91505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PV-2; L.T.C. 13	SA1002WE	Removal of cabin door.	RM	72596	Skyways, Inc. P.O. Box 587 Cody, WY 82414
10-A; T.C. 551	SA78EA	Installation of modified Beech D18S engine cowl. Reissued 6/2/72.	GL	20108	Casement Aviation P.O. Box 231 Painesville, OH 44077
10-A; T.C. 551	SA171EA	Installation of Goodyear Model L12-WRM, Type III, 11.00-12 Wheel-Brake Assemblies with 11.00-128 Ply Tires. Reissued 6/7/72.	GL	20108	Casement Aviation P.O. Box 231 Painesville, OH 44077
10-A; T.C. 551	SA271SO	Installation of wheel well fairings. Reissued 6/2/72.	GL	20108	Casement Aviation P.O. Box 231 Painesville, OH 44077
12A; T.C. 616	SA1-139	Windshield from a four-place to a two-piece glass.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
12A; T.C. 616	SA4-33	Installation of Hartzell propellers and Hartzell C-3 governors. Amended 10/23/67.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
18 (Learstar); T.C. 723	SA1-17	Main landing gear upper cylinder assembly.	GL	01824	Aerodraulics Company 16134 Brookpart Road Cleveland, OH 44135
18; T.C. 723	SA1-58	Picture windows.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-66	1003-X radome.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-87	South Wind cabin heater 940.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-99	Modification of three-place divan to four-place divan.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-121	Airspeed pitots on each wing tip and flush button static system located in nose of fuselage.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-138	Airspeed pitots and flush button static system.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-162	Westinghouse AH-4 and AH-5 decelostat anti-skid devices.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
18; T.C. 723	SA1-166	Two-piece windshield.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-168	Stabilizer tips 147 and bullet fairings 210.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-172	General Electric 2CM80B5 200-amper generators on aircraft with Wright 704C9GC1 engines.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
18; T.C. 723	SA1-194	Picture windows on left and right sides of fuselage.	EA	03100	Aero Trades, Inc. MacArthur Airport Ronkonkoma, NY 11779
18; T.C. 723	SA1-223	Radome assembly 2007X-R.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-264	Radome assembly 2006X-R for RCA AVQ-50 weather antenna system.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-334	Large window installation.	EA	71915	The S K Engineering Company 16 Shotgun Lane Levittown, NY 11756
18; T.C. 723	SA1-409	Sperry A-12 gyropilot.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
18; T.C. 723	SA1-419	RCA 5" AVQ-50 indicator and underseat mount.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
18; T.C. 723	SA1-514	Enrichment of auto lean mixture setting by installing auto lean jet 22244-3300cc injection.	EA	08375	Airwork Corporation Municipal Airport Millville, NJ 08332
18; T.C. 723	SA3-4	Seat in forward compartment stations 147 to 188.	CE	44054	Interstate Aircraft Company 3251 FAirfax Road Kansas City, KS 66115
18; T.C. 723	SA3-41	Short stack installation - Pratt & Whitney R-1830 or Wright R-1820 engines. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18; T.C. 723	SA3-42	Modification to Janitrol heater air inlet scoop. Installation of Janitrol heater overheat warning system. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18; T.C. 723	SA3-46	Nose heater installation - Stewart-Warner Model 940-B24. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18; T.C. 723	SA3-49	Two Eclipse 200-ampere generators (P-1), P/N 30E07-11.	GL	37808	General Motors Air Transport Section Bay 1, City Airport Detroit, MI 48202
18; T.C. 723	SA3-316	South Wind 8240 heater.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, IL 60068
18; T.C. 723	SA3-443	Curved glass, bird resistant windshield, and heating and ventilating system. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA3-444	Two ARDL-7A-115-29 relative danger lights under each wing tip.	GL	12448	Atkins Light Corporation 7636 Lyndale Avenue, South Minneapolis, MN 55401
18; T.C. 723	SA3-466	DC-3 exhaust collector ring and short stack installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
18; T.C. 723	SA4-14	Windshield modification.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18; T.C. 723	SA4-15	Nose pitot tube.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91505
18; T.C. 723	SA4-16	Door modification.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91505
18; T.C. 723	SA4-17	Lodestar retractable fuel dump chute.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91505
18; T.C. 723	SA4-18	Seat supports.	WE	02308	Aero Interiors, Inc. 2945 N. Hollywood Way Burbank, CA 91502
18; T.C. 723	SA4-19	ADF antenna.	WE	63750	Qualitron, Inc. 2945 Hollywood Way Burbank, CA 91502
18 (Learstar); T.C. 723	SA4-29	Radar nose for Bendix C-Band, Bendix X-Band or RCA C-Band. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-37	Picture window.	WE	39877	Gordon R. Hamilton 1002 E. Valencia Tucson, AZ 85711
18; T.C. 723	SA4-52	Oil filters 1258-B86-A and element 1258-OC.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
18; T.C. 723	SA4-57	Rework of outer wing panel for 348 gallon integral fuel tank. Reissued 11/11/74.	SW	30300	D.W. Donahue 1016 W. Houghton Street Santa Fe, NM 87501
18; T.C. 723	SA4-58	Oil tank assembly for increased oil supply. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
18; T.C. 723	SA4-59	Cockpit seats. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar): T.C. 723	SA4-69	Lockheed Model 18 modified to Learstar Mark II configuration. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-71	Rudder spring tab assembly. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-72	Radar nose for Bendix C-Band, Bendix X-Band, or RCA C-Band. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001
18 (Learstar): T.C. 723	SA4-130	Horizontal stabilizer incidence angle change to one degree. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar): T.C. 723	SA4-131	Drag reduction fairing addition. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-136	Wright R-1820-56A, -66, -72A engines, modified rudder spring mechanism and tab, elevator spring tab, retractable tail wheel assembly, stabilizer and tail-wheel, fairing-fuselage horizontal stabilizer tip, fairing installation - stabilizer intersection, modification Lodestar bat wing and flap seal. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-137	Installation of exhaust collector assembly including carburetor heater muff on Wright R1820-56A. Reissued 11/11/74.	SW	30300	D.H. Donahue 1016 W. Houghton Street Santa Fe, NM 87501
18 (Learstar): T.C. 723	SA4-155	Sperry Model A-12 automatic pilot installation modification. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-171	Approval to use 1,350 hp for takeoff with Wright R1820-56A, -66 and -72A engines and 1,300 hp, with Wright R-1820-56 and -72 engines with Hamilton Standard 33D50/6511-12 and -12S propellers.	SW	78465	Web Thomas aircraft Sales P.O. Box 575 Addison, TX 75001
18; T.C. 723	SA4-185	DC3 exhaust collector ring with modified short stack and new carburetor heat muff assembly on Wright R-1820-56 engine.	WE	65018	Potter Aircraft Service, Inc. Lockheed Air Terminal Burbank, CA 91500
18; T.C. 723	SA4-201	150-gallon outer wing tank and new fuel system.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18 (Learstar): T.C. 723	SA4-216	Picture window. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar): T.C. 723	SA4-217	Main cabin floor structure. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Lear jet); T.C. 723	SA4-223	Installation of exhaust collector assembly including carburetor heat muff. Reissued 11/11/74.	SW	30300	D.H. Donahue 1016 W. Houghton Street Santa Fe, NM 87501
18; T.C. 723	SA4-251	Fiberglass stabilizer fairing.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
18; T.C. 723	SA4-256	Horizontal stabilizer angle of incidence change and modified stabilizer tips, wing and flap trailing edge. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-257	Picture window. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar): T.C. 723	SA4-264	Two Jato motors 15KS-1000A1 in fuselage. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
18; T.C. 723	SA4-273	Installation of heat-shroud, propeller anti-icing alcohol tank, and modified DC-3 exhaust system. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-274	Outer wing fuel tanks, revised fuel system, change in angle of incidence of horizontal stabilizer one degree and installation of fuselage horizontal stabilizer fairing. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-275	Installation of PacAero wing tip. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-281	Horizontal stabilizer angle of incidence change. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-283	60158 stabilizer tip. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-307	Lear L-102A automatic pilot. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001
18; T.C. 723	SA4-366	Horizontal stabilizer tip, rudder spring tab, Learstar tail cone, elevator spring tab, Goodyear wheels and brakes, modification of wing trailing edge and reducing flap travel, change of stabilizer incidence. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-368	Picture window. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001
18; T.C. 723	SA4-371	Repair for wrinkles at wing station 120.	WE	39877	Hamilton Aircraft Company 6501 S. Park Avenue Tucson, AZ 85706
18; T.C. 723	SA4-397	Structural installation of flight line 28 P-001 seat. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-425	Modification per STC SA4-69 except gross weight modification per Dwg. 600030B, engine per Dwg. 606399 and DCN-1, picture window per STC SA-368 and pilot seat per STC SA4-397. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-438	100,000 BTU (S-100) Janitrol heater in No. 1 baggage compartment.	WE	62080	Pacific Airmotive Corporation 3000 N. Clybourn Avenue Burbank, CA 91505
18; T.C. 723	SA4-538	Propeller spinners.	NW	59600	Miner's Aircraft and Engine Service, Inc. 8165 First Avenue, South Seattle, WA 98101
18 (Learstar); T.C. 723	SA4-644	Lear L-5B autopilot. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales P.O. Box 575 Addison, TX 75001
18; T.C. 723	SA4-653	Exhaust system and exhaust trough on aircraft equipped with Pratt & Whitney R-1830-94 engines.	WE	43000	Ben Howard & Associates, Inc. 4200 Lincoln Boulevard Venice, CA 90291
18; T.C. 723	SA4-654	Modification of nacelle aft of firewall to fair-in structure in exhaust trough area on aircraft with Pratt & Whitney R-1830-94 engines.	WE	65018	Potter Aircraft Service, Inc. Lockheed Air Terminal Burbank, CA 91500
18 (Learstar); T.C. 723	SA4-715	Westinghouse air brake AH-5 decelostat anti-skid unit. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-732	Alternate fuel source on aircraft with Wright Cyclone engines with flow meter installation. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
18 (Learstar); T.C. 723	SA4-738	Modification to "Learstar" (NOTE 12 of Aircraft Spec A-723) except installation of Wright R1820-56A, -66, or -72A engines as per Dwg. 606327 DCN B-15. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-838	Sperry A-12 autopilot. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-973	Pitot - static system. Reissued 11/11/74.	SW	30300	D.H. Donahue 1016 W. Houghton Street Santa Fe, NM 87501
18; T.C. 723	SA4-1010	Autolite generator 2CM70R9 on Wright engines R1820-56A, -66, and -72A. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-1014	Radio shelf structure No. 1 baggage. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-1138	Gross weight modification including: increase power, installation of Goodyear wheels and brakes, two JATO motors, removal of bat wing and other changes. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA4-1310	20C63-S100 Janitrol heater.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
18; T.C. 723	SA4-1317	Gross weight modification including: increase power, installation of two JATO motors, outer wing tank, and Goodyear wheels and brakes, removal of bat wing and other changes. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18 (Learstar); T.C. 723	SA4-1552	Pittsburgh Plate Glass Company electrically-heated windshield. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA16SW	Electric trim tab servo. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18; T.C. 723	SA17SW	Electric trim tab servo. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18 (Learstar); T.C. 723	SA47WE	Interior and equipment installation. Reissued November 1975.	SW	78465	Web Thomas Aircraft Sales Box 575 Addison, TX 75001
18; T.C. 723	SA50SW	Extended wing tip. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18 (Howard 250); T.C. 723	SA51SW	Increase in gross weight to 22,500 pounds takeoff and 20,500 pounds landing. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18 (Howard 250); T.C. 723	SA69GL	Install emergency lighting system. Issued January 1975.	GL	65274	George J. Priester Aviation Service Pal-Waukee Airport Wheeling, IL 60090
18; T.C. 723	SA78SW	Enlarged lavatory window on right side of aft fuselage station 484. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA78GL	Install second static pressure system. Issued 4/18/75.	GL	65274	George J. Priester Aviation Service Pal-Waukee Airport Wheeling, IL 60090
18 Loadstar, Learstar Conversion; T.C. 723	SA100CE	High intensity wing tip lights Model A or B, tail light Model C, with or without Model 1 or 2 high intensity fuselage lights. Reissued 10/17/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92668
18; T.C. 723	SA105SW	Landing gear doors. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
18: T.C. 723	SA106SW	M-8 autopilot. Reissued 6/28/78.	SW	34000	Executive Aircraft Service Div. of Cooper Airmotive 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA107SW	Alcohol deicing system. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA129SW	Empennage saddle-back fairing. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18: T.C. 723	SA177SW	Tail cone. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18: T.C. 723	SA181SW	Oxygen system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18: T.C. 723	SA187SW	Firewall fluid shutoff valve. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18: T.C. 723	SA188SW	Scene-A-Ramic cabin windows. Reissued 1/27/81.	SW	26230	Cooper Airmotive 3300 Love Field Drive Dallas, TX 75235
18 (Howard 250): T.C. 723	SA192SW	Mighty Midget flap and gear hydraulic selector. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18: T.C. 723	SA194SW	Cockpit side windows. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA200SW	Electric trim system. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA201SW	Tail cone. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA211SW	Higher strength main landing gear drag strut anchor fitting. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18: T.C. 723	SA215WE	Pilot's seat and seat tracks.	WE	02315	Aerojet-General Corporation International Airport Ontario, CA 91761
18: T.C. 723	SA224EA	Electrically heated windshield.	EA	64686	Pittsburgh Plate Glass Company #1 Gateway Center Pittsburgh, PA 15222
18: T.C. 723	SA225SW	Centilevered pressure cowling on aircraft with Wright R-1820 engines. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA249SW	Fiberglass propeller spinner on aircraft with Hamilton Standard 33D50 or 23E50 propeller hub. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA273SW	Cockpit seats. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA278SW	Exhaust stack. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA301SW	Lower nacelle. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18: T.C. 723	SA306EA	Stewart-Warner south wind heater.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
18: T.C. 723	SA308SW	Geneerco cabin floor. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18 (Learstar): T.C. 723	SA325EA	Southwind heater in No. 2 baggage compartment.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
18; T.C. 723	SA327SW	Janitrol S-200 combustion heater below nose baggage bin floor. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
18 (Howard 250); T.C. 723	SA352SW	Dual selector valves and boost pumps. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aviation Service 7515 Lemmon Avenue Dallas, TX 75209
18 (Howard 250); T.C. 723	SA361SW	Jet stack exhaust system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA389SW	Windshield with modified Learstar sliding side cockpit windows. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18 (Howard 250); T.C. 723	SA554SW	Single disc brakes.	SW	68768	North American Rockwell Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
18 (Howard 250); T.C. 723	SA567SW	Airspeed system. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
Lockheed 18 (Learstar only); T.C. A-723	ST594SO	Installation of 19 passenger interior and Type III emergency. Issued May 1974.	SO	36012	Florida Airways International P.O. Box 22003 Fort Lauderdale, FL 33315
Lockheed 18 (Learstar only); T.C. A-723	SA614SW	Janitrol S-100 heater. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18; T.C. 723	SA1696WE	Installation of engine mounts P/N VIP 50525-1 and P/N 50545-1. Amended 6/7/73.	WE	83500	Vibration Isolation Products, Inc. P.O. Box 7029 Burbank, CA 91505
18 "Learstar"; T.C. 723	SA2718WE	Installation of intermixed engines, Wright R1820-76A and Wright 987C9HD1 engines. Issued 6/29/73.	WE	15130	Bay Aviation Services, Inc. P.O. Box 2545, Airport Station Int'l Airport, Hangar 6 Oakland, CA 94614
18, 18 (Howard); T.C. 723	SA146SW	Lear L-5 autopilot. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA183SW	Air conditioner. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA293SW	Two shot CO2 fire extinguisher. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA296SW	High pressure deicer boots. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA508SW	180-gallon outer panel fuel tank. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA509SW	Executette side mounted lavatory. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18, 18 (Howard); T.C. 723	SA510SW	Panoramic window. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
18-56; T.C. A-723	ST068SO	Removal of main cabin door. Issued 11/6/75.	SO	31363	Eagle Aviation Corporation P.O. Box 1082 Zephyrhills, FL 33599
18-56; T.C. A-723	ST892SO	Removal of main cabin door. Issued 4/13/76.	SO	75118	Harold D. Stewart 13123 N.W. 39th Avenue Gainesville, FL 32601
49; T.C. 763	SA4-27	Stratus supercharger and air cycler.	SW	17075	Braniff Airways, Inc. Love Field Dallas, TX 75235
49; T.C. 763	SA4-1616	Nose radome.	WE	49724	Las Vegas Hacienda, Inc. 2680 E. Wardlow Road Long Beach, CA 90801
49; T.C. 763	SA380	Radome and radar provisions for up to 22-inch diameter antenna RCA AVQ-10 or Bendix RDR-1 (X/C Band).	SO	78390	Tempo Design Corporation P.O. Box 456 Miami, FL 33148

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
49: T.C. 763	SA112WE	Structural mounts in McMillan radome and in cockpit for WP-103 Collins all weather radar.	WE	19550	California Airmotive Corporation 7139 Vineland Avenue North Hollywood, CA 91603
49: T.C. 763	SA776WE	Collins DME in aircraft.	WE	32100	Edde Airlines, Inc. 2850 E. Wardlow Road Long Beach, CA 90801
49: T.C. 763	SA845WE	Military D-2 auxiliary power unit in Zone 3 of No. 1 nacelle.	WE	49724	Las Vegas Hacienda, Inc. 2680 E. Wardlow Road Long Beach, CA 90801
49: T.C. 763	SA1296WE	Seats at emergency exit incorporating a free folding back.	WE	52860	McCulloch Properties, Inc. 2733 E. Spring Street Long Beach, CA 90807
49-46: T.C. A-763	SA1319WE	Installation of Collins ATC transponder Model 621A-2 with antenna type 237Z-1.	WE	52860	McCulloch Properties, Inc. 2733 E. Spring Street Long Beach, CA 90807
49-46: T.C. A-763	SA1360WE	Installation of Collins Model 642C-1 cockpit voice recorder system. Amended 3/10/67.	WE	52860	McCulloch Properties, Inc. 2733 E. Spring Street Long Beach, CA 90807
49, 149, 649, 749, 1049, 1649: T.C. 763, 6A5, 4A17	SA839SO	Oil separator H-300-1.	SO	04400	Air Carrier Engine Service, Inc. P.O. Box 48-236 Miami, FL 33101
49, 149, 649, 649A, 749, 749A, 1049 Series, 1649; T.C. 763, 6A5, 4A17	SA546WE	Modification of crew entrance door window mechanism.	WE	37082	Gamco Precision 10021 La Tuna Canyon Sun Valley, CA 91352
649, 649A, 749, 749A; T.C. 763	SA1-605	2015 Series radomes.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
49, 649, 649A, 749, 749A: T.C. 763	SA4-1500	Interior modification for 98 passengers, maximum occupants including crew.	WE	39460	Great Lakes Airlines, Inc. Lockheed Air Terminal Burbank, CA 91500
49, 749: T.C. 763	SA3-203	Smoke detection for cargo compartment.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Parkville, MO 64152
649, 749: T.C. 763	SA642WE	Operation with mixed Hamilton Standard 43E60/6901 and 43E60/6903 propellers.	WE	19550	California Airmotive Corporation 7139 Vineland Avenue North Hollywood, CA 91603
749: T.C. 763	SA1-480	Smoke detector system in cargo compartments Class B.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749, 749A: T.C. 763	SA354WE	Observer's jump seat.	WE	19550	California Airmotive Corp. 7139 Vineland Avenue North Hollywood, CA 91603
749A: T.C. 763	SA1-145	Cabin interior modification for 74 to 80 seats, inclusive of galley and crew bunk area.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749A: T.C. 763	SA1-146	Radio equipment.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749A: T.C. 763	SA1-147	Goodyear brake assembly 9540534 wheel assembly 9540753, and modification of brake control valve.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749A: T.C. 763	SA1-547	Modification of floor and support structure for cargo loading.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749A: T.C. 763	SA1-578	Cabin smoke detector system for cargo operation.	NE	35694	Flight Enterprises Int'l Aircraft Services, Inc. Bradley Field Division Windsor Locks, CT 06096
749A: T.C. 763	SA4-1634	Modification of interior to 81 through 85 and 90 passenger configurations.	WE	19550	California Airmotive Corp. 7139 Vineland Avenue North Hollywood, CA 91603
749A: T.C. 763	SA4-1657	Structural mounts in McMillan radome and in cockpit for WP-103 Collins all weather radar.	WE	19550	California Airmotive Corp. 7139 Vineland Avenue North Hollywood, CA 91603

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
749A; T.C. 763	SA464CE	Fairchild Model A-100 cockpit voice recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
749A; T.C. 763	SA24SO	Cargo loading door in forward section of main cabin and rework of main cabin floor structure.	SO	11326	Robert E. Anson and L.C. Callaway, Jr. 7211 S.W. 52nd Street Miami, FL 33101
749A; T.C. 763	SA66WE	Oversize cargo door on left side of fuselage aft of wing.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
749A; T.C. 763	SA326WE	Emergency safety equipment.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
749A; T.C. 763	SA327WE	Cargo tie-down rings for retaining a 4,700 pound R 3350 QEC package.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
188; T.C. 4A22	SA562NW	Installation of liquid cargo tanks. Issued 1/20/78.	NW	73820	Sorm, Inc. 7999 Perimeter Road, S. Seattle, WA 98108
188; T.C. 4A22	ST508SO	Installation of lap/shoulder belts. Issued 6/8/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
188; T.C. 4A22	SA2324WE	Installation of spraymat ice protection system on L-188 propeller spinner, Hamilton Standard P/N 553546, replacing Hamilton Standard heater blanket. Issued 3/10/71.	WE	32250	Edler Industries, Inc. 2101 Dove Street Newport Beach, CA 92660
188A-08; T.C. 4A22	SA410EA-D	Relocate flight data recorder installation to aft fuselage area. Amended 1/26/68.	EA	10150	American Airlines, Inc. 633 Third Avenue New York, NY 10001
188A-08; T.C. 4A22	SA418EA-D	Change interior arrangement of passenger compartment from existing configuration of tourist and first class to eighty passenger six lounge configuration.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
188A; T.C. 4A22	SA178SO	Cockpit voice recording system.	SO	61220	National Airlines, Inc. P.O. Box 2055 Airport Mail Facility Miami, FL 33159
188A; T.C. 4A22	SA228SO	Rewinding of rotating field element 291C671G1 for General Electric 400 cycle alternator Model 2CM 210 using a magnet wire insulated with Polythermaleze coating.	SO	63855	Peninsular Armature Works, Inc. 3525 NW 51 Street Miami, FL 33101
188A; T.C. 4A22	SA267SO	Aural Mach overspeed warning system to comply with Special Regulation SR450A.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A; T.C. 4A22	SA272SO	Overspeed warning system.	SO	61220	National Airlines, Inc. P.O. Box NAI Miami, FL 33159
188A; T.C. 4A22	SA335SW	Overspeed warning system.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235
188A; T.C. 4A22	SA594WE	Audible mach airspeed warning system.	WE	85126	Western Air Lines, Inc. 6060 Avion Drive Los Angeles, CA 90052
188A; T.C. 4A22	ST672SO	Installation of encoding altimeter, ATC transponder, and associated system.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A; T.C. 4A22	SA1055WE	Cockpit voice recorder system.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
188A; T.C. 4A22	SA1064SO	Increase in zero fuel weight from 82,500 lbs. to 90,800 lbs. Issued 4/13/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661087 Miami, FL 33166
188A; T.C. 4A22	SA1071SO	Increase in zero fuel weight from 86,000 pounds to 92,340 pounds. Issued 6/14/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661087 Miami, FL 33166

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
188A: T.C. 4A22	SA1090WE	Mach airspeed warning system.	SW	10150	American Airlines, Inc. Maintenance & Overhaul Center Tulsa, OK 74151
188A: T.C. 4A22	SA1104WE	Fairchild cockpit voice recorder system.	WE	85126	Western Air Lines, Inc. 6060 Avion Drive Los Angeles, CA 90052
188A; T.C. 4A22	SA1234WE	Essential power failure warning circuit modified.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
188A; T.C. 4A22	SA2162WE	Fabrication and installation of blanks in lieu of passenger compartment windows (glass fiber epoxy laminate reinforced with 0.080 x 7075T6 aluminum edge). Issued 5/27/70.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
188A; T.C. 4A22	SA2536WE	Modification and installation of: aft cargo door; cargo loading and retention system; strengthened floor support structure; increased zero fuel weight to 90,000 pounds; improved avionics and instrumentation. Amended 7/24/75.	WE	52010	Lockheed Aircraft Service Company Burbank, CA 91500
188A; T.C. 4A22	SA3700WE	The deletion of fueling valve indicator lights and test switch. Issued 7/25/78.	WE	33905	Evergreen Inter'l Airlines Marana Air Park Marana, AZ 85238
188A, 188C; T.C. 4A22	SA3-596	Waste-King 5424-200 flight recorder system. Amended 5/24/67.	GL	61700	Northwest Airlines, Inc. 1885 University Avenue, South St. Paul, MN 55111
188A, 188C; T.C. 4A22	SA1-403	Model 109C flight data recorder. Amended 10/13/66.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
188A, 188C; T.C. 4A22	SA97GL	Installation of Collins FPC-75/590A ground proximity warning system. Issued 11/7/75.	GL	90135	Zantop Int'l Airlines, Inc. Detroit-Willow Run Airport Ypsilanti, MI 48197
188A, 188C; T.C. 4A22	SA133SO	Cockpit voice recorder.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	SA158SO	Overwing emergency excape ropes.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	SA218WE	GTC 85-90E or GTCP 85-291E turbine.	WE	07500	AiResearch Aviation Service 6201 W. Imperial Highway Los Angeles, CA 90045
188A, 188C; T.C. 4A22	SA240SO	Oil separator #500-2.	SO	04400	Air Carrier Engine Service P.O. Box 48-236 Miami, FL 33148
188A, 188C; T.C. 4A22	SA638WE	Liquor bar.	WE	85126	Western Air Lines, Inc. 6060 Avion Drive Los Angeles, CA 90052
188A, 188C; T.C. 4A22	SA678WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
188A, 188C; T.C. 4A22	SA685WE	Aural warning signal when Vmo/Mmo is exceeded.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
188A, 188C; T.C. 4A22	SA686WE	Aural warning signal when Vmo/Mmo is exceeded.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
188A, 188C; T.C. 4A22	ST733SO	Installation of exterior emergency lighting system. S/Ns 1001, 1002, 1004 thru 1149 and 2001 thru 2022 only. Issued 10/20/72.	SO	77078	Survival Products, Inc. 5201 Roosevelt Street Hollywood, FL 33021
188A, 188C; T.C. 4A22	ST749SO	Installation of plug type metal panels to replace the original clear plastic main cabin windows. Issued 11/24/75.	SO	56838	MCA Leasing 7216 N.W. 25th Street Miami, FL 33122

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
188A, 188C; T.C. 4A22	ST754SO	Installation of remote control essential A-C bus normal and alternate electrical circuit breaker system. Amended 8/9/77	SO	56838	MCA Leasing Corporation 7216 Northwest 25th Street Miami, FL 33122
188A, 188C; T.C. 4A22	ST852SO	Installation of cargo door. Issued 9/25/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
188A, 188C; T.C. 4A22	ST853SO	Installation of Sundstrand ground proximity warning system. Issued 9/26/75.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	ST885SO	Modification to a cargo configuration. Amended 2/7/78.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661037 Miami, FL 33166
188A, 188C; T.C. 4A22	SA1178WE	Cockpit voice recorder.	WE	62160	Pacific Southwest Airlines 3100 Goddard Way San Diego, CA 92101
188A, 188C; T.C. 4A22	SA1206WE	Beta range override control switch.	SW	10150	American Airlines, Inc. Maintenance & Engineering Center Tulsa, OK 74151
188A, 188C; T.C. 4A22	SA1754WE	Installation of cargo doors, cargo floor and other changes. Amended 1/22/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario Int'l Airport Ontario, CA 91761
188A, 188C; T.C. 4A22	SA1982WE	Installation of luggage barrier.	WE	52860	McCullogh Properties, Inc. 2733 East Spring Street Long Beach, CA 90807
188A, 188C; T.C. 4A22	SA1984WE	Installation of inflatable slide for right rear emergency exit and for left rear service door; also International Inflatables emergency light No. 68555. Amended 6/24/71.	WE	44266	International Inflatables Co. Div. of Dynatron Systems Corp. 9880 San Fernando Road Pacoima, CA 91331
188A, 188C; T.C. 4A22	SA2187WE	Modification of inflatable slide International Inflatables emergency escape chute kit #KP 684. Amended 7/7/70.	WE	75119	Steward-Davis, Inc. 3200 Cherry Avenue Long Beach, CA 90807
188A, 188C; T.C. 4A22	SA2197WE	Installation of Brownline modified cargo restraint system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
188A, 188C; T.C. 4A22	SA2301WE	Installation of emblem light. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
188A, 188C; T.C. 4A22	SA2405WE	Installation of PICO Division pressure regulator P/N 30001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
188A, 188C; T.C. 4A22	SA2456WE	Installation of Collins Model 860E-2 and dual DME system. Amended 1/5/72.	WE	30000	DeVore Aviation Service Corp. 7120 Hayvenhurst Avenue Suite 108 Van Nuys, CA 91406
188A, 188C; T.C. 4A22	SA2559WE	Installation of H. Koch & Sons beverage cart P/N 601-710315-1 on stowage mushroom plate assembly. Amended 11/9/72.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
188A, 188C; T.C. 4A22	SA2711WE	Modification of flight station temperature control. Reissued 10/2/73.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
188A (S/N 1035 and up), 188C; T.C. 4A22	SA2889WE	Conversion of Lockheed Model 188A and 188C into all cargo configuration by installation of cargo door, cargo floor and cargo lining. Amended 8/25/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C; T.C. 4A22	SA2963WE	Increase maximum zero fuel weight to 90,000 pounds by modifying aircraft. Issued 1/29/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
188A, 188C: T.C. 4A22 T.C. 4A22	SA2974WE	Modification for installation of aft galley and forward galley rework. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
188A (S/N 1035 and up), 188C: T.C. 4A22	SA3059WE	Maximum landing weight substantiated to 98,102 pounds (from 95,650 pounds). Issued 10/23/75.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C: T.C. 4A22	SA3098WE	Structural modifications. Issued 10/31/75.	WE	10210	American Jet Industries 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C: T.C. 4A22	SA3120WE	Modification consisting of installation of cargo pallet restraint system. Amended 8/12/77.	WE	63700	Pemco Engineers, Inc. 10762 Chestnut Street Stanton, CA 90680
188, 188C: T.C. 4A22	SA3141WE	Installation of AiResearch GTCP85-98, -98C or -98CK auxiliary power unit to supply starting air and 400 HZ power. Issued 4/30/76.	AL	67017	Reeve Aleutian Airways, Inc. P.O. Box 6027 Anchorage, AK 99502
188A, 188C: T.C. 4A22	SA3152WE	Installation of cargo door only. Issued 4/29/76.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A (S/N 1035 and up), 188C: T.C. 4A22	SA3159WE	Installation of cargo floor and interior. Issued 4/29/76.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188A, 188C: T.C. 4A22	SA3675WE	Installation of Brownline cargo system P/N 46234-101. Amended 4/30/79.	WE	17740	Brownline Division Brooks & Perkins, Inc. 2950 Lomita Blvd. Torrance, CA 90505
188B, A188B: T.C. A9CE	SA3088WE	Installation of CEDAD fender assemblies. Issued 9/5/75.	WE	20325	CEDAD Company 4700 Brooks Street Montclair, CA 91763
188C: T.C. 4A22	SA91GL	Installation of radio altimeter antenna opening and radio rack. Issued 10/29/75.	GL	65760	Quality Controlled Electronics, Inc. Willow Run Airport Ypsilanti, MI 48197
188C: T.C. 4A22	SA132CE	Overspeed warning system.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
188C: T.C. 4A22	SA707EA	Relocation of cabin window right-side from fuselage station 217-236 to fuselage station 333-352. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761.
188C: T.C. 4A22	SA708EA	Installation of opening in fuselage right hand for emergency exit between fuselage station 226 and fuselage station 253.4. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
188C: T.C. 4A22	SA709EA	Installation of floor structure and miscellaneous modifications. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
188C: T.C. 4A22	ST750SO	Installation of main cabin cargo crash barrier bulkhead. Issued 11/24/75.	SO	56838	MCA Leasing 7216 N.W. 25th Street Miami, FL 33122
188C: T.C. 4A22	SA796EA	Installation of six-seat pallet. Reissued 12/11/78.	WE	33905	Evergreen Inter'l Airlines, Inc. Marana Air Park Marana, AZ 85238
188C: T.C. 4A22	SA1081SO	Increase in fuel weight from 86,000 pounds to 92,340 pounds. Issued 6/14/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661087 Miami, FL 33166
188C: T.C. 4A22	SA1637WE	Installation of cargo door approximately 80 inches high by 144 inches long in left side of fuselage forebody.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91764
188C: T.C. 4A22	SA1779WE	Installation of Heathair AC-10194, AC-10195 pallets and Heathair AC-10196, AC-10197 nets on Lockheed electra model 188C cargo freighter. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
188C: T.C. 4A22	SA2092WE	Installation of Heath 54 x 88 inch cargo pallet AC-10528-1 and net AC-10657-101. As modified per STC SA1754WE. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
188C: T.C. 4A22	SA2152WE	Installation of Heath 88 x 108 inch cargo pallet AC-10527-1 and net AC-10196-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
188C; T.C. 4A22	SA2694WE	Modification for installation of: nose and wingtip instrumentation boom provisions; research apparatus mounting provisions; dropsonde dispenser; increased breathing oxygen provisions and research electrical system. Issued 5/30/73.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
188C; T.C. 4A22	SA2695WE	Modification for installation of: nose instrumentation boom and wingtip instrumentation boom. Modification per STC SA2694WE is required prior to this modification. Issued 5/30/73.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
188C; T.C. 4A22	SA2991WE	Installation of passenger compartment interior arrangement in aft fuselage. Issued 2/21/75.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
188C; T.C. 4A22	SA3084WE	Installation of Collins FPC-75 ground proximity warning system computer. Amended 7/21/76.	WE	04080	Air California P.O. Box 2678 Oakland, CA 94614
188C; T.C. 4A22	SA3299WE	Modification of passenger compartment interior arrangement in aft fuselage and relocation of forward airstair to rear left-hand Type 1 exit. Issued 11/23/76.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
L-188C; T.C. 4A22	SA3618WE	Relocation of forward airstair to rear left hand type 1 exit. Issued 3/27/78.	WE	10210	American Jet Industries, Inc. 7701 Woodley Van Nuys, CA 91406
L-1011; T.C. A23WE	ST858SO	Installation of Bendix ground proximity warning system. Issued 10/20/75.	SO	29234	Delta Air Lines Atlanta Airport Atlanta, GA 30320
L-1011: T.C. A23WE	SA994CE	Installation of Inflight Motion Picture, Inc. 16 mm motion picture projection system. Amended May 1974.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MC 64153
L-1011; T.C. A23WE	SA1047SO	Installation of the Litton LTN-211 omega navigation system. Issued 2/7/79.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011; A23WE	SA1456CE	Installation of nine-abreast seating. Issued 10/31/78.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195
L-1011; T.C. A23WE	SA1540CE	Installation of a Growth Industries dual cavity oven. Issued 12/11/79.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MC 64195
L-1011; T.C. A23WE	SA1664SW	First aid portable chemical oxygen system. Issued 6/25/73.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
L-1011; T.C. A23WE	SA1689SW	Cabin attendant portable chemical oxygen system. Issued 6/25/73.	SW	79425	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
L-1011 (193E): T.C. A23WE	SA2647WE	Installation of cocktail table in first-class lounge. Issued	WE	18390	Burns Aero Seat Company 2820 N. Hollywood Way Burbank, CA 91502
L-1011-385 Series: T.C. A23WE	SA3527WE	Installation of single or dual Litton LTN-201 omega navigation systems. Amended 3/26/79.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91367
L-1011-385-1; T.C. A23WE	ST752SO	Modification of main cabin passenger seating arrangement. Amended 3/22/78.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
L-1011-385-1; T.C. A23WE	ST831SO	Installation of food and beverage cart stowage provisions. Issued 4/30/75.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	ST851SO	Installation of Sundstrand ground proximity warning system. Issued 8/7/75.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1; T.C. A23WE	SA857CE	Crimsco entree cart. Amended February 1975.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MC 64130
L-1011-385-1; T.C. A23WE	SA1198CE	Deactivation of flap load relief system in accordance with TWA M.O. 98686. Issued 2/1/76.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
L-1011-385-1; T.C. A23WE	SA1286CE	Installation of additional aircraft integrated data system and digital flight data recorder parameters. Amended 11/22/77.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64195
L-1011-385-1; T.C. A23WE	SA1325CE	Install food and beverage service center in aft passenger. Issued May 1977.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport P.O. Box 20126 Kansas City, MO 64195
L-1011-385-1; T.C. A23WE	SA2519WE	Installation of H. Koch & Sons, Inc., food, beverage and waste cart. Amended 9/14/72.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33149
L-1011-385-1; T.C. A23WE	SA2894WE	Installation of Hermes LD-3 Kool-flite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1705-C West 134th Street Gardena, CA 90249
T.C. A23WE					
L-1011-385-1; T.C. A23WE	SA3087WE	Installations of ground proximity warning system. Amended 4/27/78.	WE	62160	Pacific Southwest Airlines 3225 North Harbor Drive San Diego, CA 92101
L-1011-385-1; T.C. A23WE	SA3474WE	Installation of aircraft video system. Issued 12/1/77.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
L-1011-385-1; T.C. A23WE	SA3512WE	Installation of stretcher carrier. P/N 2003. Issued 3/21/78.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
L-1011-385-1; T.C. A23WE	SA3809WE	Installation of a dual Delco C-1VA INS.	WE	29125	Delco Electronics Division General Motors Corporation 6767 Hollister Avenue Goleta, CA 93017
L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15; T.C. A23WE	SA1619CE	Installation of two additional flight attendant seats. Issued 12/15/80.	CE	70260	Saudia Airlines P.O. Box 167 Jeddah, Saudi Arabia
L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15; T.C. A23WE	SA3316WE	Installation of a 16-inch coach class serving cart Model 953000-249, and 7805000-201, -203, -205, -207 in the passenger main deck coach areas and/or lower galley service areas. Amended 2/26/80.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1, L-1011-385-1-14, -15; T.C. A23WE	SA3317WE	Installation of 13-inch waste cart Model 956000-231, -233, -235, -237, -239 in passenger main deck and/or lower galley service areas. Amended 11/2/79.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1, L-1011-385-1-14, -15; T.C. A23WE	SA3709WE	A bolt-on retract actuator fitting specified by FAA sealed Aviation Hydraulics (Stellar Canoga Ind.) installed on the main landing gear outer cylinder. Issued 1/22/79.	SO	34120	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
L-1011-385-1, L-1011-385-15; T.C. A23WE	SA1593CE	Replaces magnetic wheel TAT-EPR indicator with a solid state indicator. Issued 6/3/80.	CE	79400	Trans World Airlines, Inc. P.O. Box 20126 Kansas City Int'l Airport Kansas City, MO 64195
L-1011-385-1-15; T.C. A23WE	SA1407CE	Install Fairchild auto-annunciator system. Issued 4/3/78.	CE	79400	Trans World Airlines, Inc. Room 1-422 Kansas City Int'l Airport Kansas City, MO 64153

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
L-1011-385-1-15; T.C. A23WE	SA1408CE	Install Delco electronics triple C-IV inertial navigation system. Issued 4/3/78.	CE	79400	Trans World Airlines, Inc. Room 1-422 Kansas City Int'l Airport Kansas City, MO 64153
L-1011-385-1-15 (193T-Cathay Pacific Ser.)	SA3076WE	Installation of a thirteen inch cool beverage cart. Amended 10/5/79.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1-15 (1935-Saudia Series): T.C. A23WE	SA3315WE	Installation of 16-inch beverage cart Model 954000-225 in passenger main deck and/or lower galley service area. Issued 12/15/76.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
L-1011-385-1 (193K); T.C. A23WE	SA2689WE	Installation of horizontal situation indicator. Issued 5/11/73.	EU	26700	Court Line Aviation Lutton Airport Lutton, England
L-1011-385-1-193A; T.C. A23WE	SA2793WE	Cart tiedown assembly. Issued 12/20/73.	WE	48550	H. Koch & Sons Koch Road Corte Madera, CA 94925
1049 Series; T.C. 6A5	SA1-312	Replacement of laminated Sierracin cabin windows with built-up sheet metal plug.	EA	70600	Seaboard & Western Airlines JFK International Airport Jamaica, NY 11430
1049 Series; T.C. 6A5	SA1-352	Aft facing, folding, stewardess seat TECO 527A-1 at fuselage station 338.	EA	70600	Seaboard & Western Airlines JFK International Airport Jamaica, NY 11430
1049 Series; T.C. 6A5	SA4-310	Emergency radio transmitter.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94616
1049 Series; T.C. 6A5	SA4-311	Interior seating change to provide 99 cabin places.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-312	Ten man life raft stowage provisions.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-316	Emergency equipment.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-351	Modification of airplane including removal of coat closet.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series; T.C. 6A5	SA4-352	101 cabin seats and four crewmember seats.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-377	112 and 116 cabin seats and four crewmember seats.	WE	79310	Transocean Air Lines Municipal Airport Oakland, CA 94614
1049 Series; T.C. 6A5	SA4-514	Interior modification and installation of passenger interior.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-948	Overhead emergency exit hatch between fuselage station 278.4 and 296.8 in top centerline of aircraft.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1074	Seat track and other modifications.	WE	79956	Twentieth Century Aircraft 10800 Sherman Way Sun Valley, CA 91352
1049 Series; T.C. 6A5	SA4-1167	Interior modification.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1181	Passenger interior configuration.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1322	Fire proofing of main landing gear doors to comply with Airworthiness Directive 60-05-02.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series; T.C. 6A5	SA4-1371	Passenger interior for 105 occupants.	WE	30265	Dollar Lines, Ltd. 311 California Street San Francisco, CA 94101
1049 Series; T.C. 6A5	SA4-1396	Structural reinforcements.	WE	30265	Dollar Lines, Ltd. 311 California Street San Francisco, CA 94101

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1049 Series: T.C. 6A5	SA4-1474	Weather radar.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series: T.C. 6A5	SA4-1498	Interior modification.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series: T.C. 6A5	SA4-1565	Interior arrangement for 111 occupants.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series: T.C. 6A5	SA4-1649	Increase in zero fuel weight to 108,000 pounds.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series: T.C. 6A5	SA6EA	Pallets and rollers and guide rails.	EA	31500	Eastern Rotorcraft Corp. P.O. Box 110 Doylestown, PA 18901
1049 Series: T.C. 6A5	SA36SO	Cargo loading door, floor structure, fuselage reinforcements, cargo tie-down devices, etc.	SO	11326	Robert F. Anson and L.C. Callaway, Jr. 7211 SW 52 Court Miami, FL 33101
1049 Series: T.C. 6A5	SA186WE	Interior modification to 108 passenger configuration.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series: T.C. 6A5	SA188WE	Catenary cargo restraining net at fuselage station 710 on aircraft converted to cargo configurations.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series: T.C. 6A5	SA189WE	Modification of air conditioning system for Class E cargo compartment.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series: T.C. 6A5	SA200SO	Cockpit voice recording system.	SO	34120	Eastern Air Lines, Inc. International Airport Miami, FL 33148
1049 Series: T.C. 6A5	SA219WE	Modification of 1049 M.L.G. orifice plate.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series: T.C. 6A5	SA233WE	Structural reinforcement to wing to permit operation at higher weights.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series: T.C. 6A5	SA456WE	Modification to allow operation at the following weights: takeoff - 142,100 pounds; landing - 114,500 pounds; zero fuel - 109,500 pounds.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series: T.C. 6A5	SA635WE	Single Collins 860E-1 distance measuring equipment system.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series: T.C. 6A5	SA659WE	Wing skin change.	WE	19550	California Airmotive Sales Corp. 7139 Vineland Avenue North Hollywood, CA 91603
1049 Series: T.C. 6A5	SA717WE	Single Collins 860E-1 distance measuring equipment system.	WE	36100	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series: T.C. 6A5	SA755WE	Three 1,800-gallon KC97 fuselage tanks for carriage of petroleum fuels as cargo.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1049 Series: T.C. 6A5	SA901WE	Emergency exit lighting modification deleting the impact switch.	WE	52010	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series: T.C. 6A5	SA1143WE	Four 1800-gallon tanks.	WE	52010	The Flying Tiger Line, Inc. Lockheed Air Terminal Burbank, CA 91500
1049 Series: T.C. 6A5	SA1289WE	United Control V-557 cockpit voice recorder system.	WE	36100	The Flying Tiger Lines, Inc. 7401 World Way West Los Angeles, CA 90009
1049 Series: T.C. 6A5	SA1362WE	Collins 642C-1 cockpit voice recorder system.	WE	08170	Airlift International, Inc. International Airport San Francisco, CA 94128
1049-G-82, 1049-H-82: T.C. 6A5	SA1843WE	Installation of RCA AVQ-50 weather radar with McMillan 7161X radome and Collins 37P-4 glide slope antenna.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1049H: T.C. 6A5	ST489SO	Installation of cargo restraining bulkhead. Issued 2/1/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
1049, 1649 Series: T.C. 6A5, 4A17	SA4-608	Engine mount core assemblies DE-643-1 on Wright TC18 Series engines.	WE	30500	Dow-Elco 1313 W. Olympic Boulevard Montebello, CA 90640
1649A: T.C. 4A17	SA4-1402	Reinforcing structure.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1649A: T.C. 4A17	SA258WE	One Type III emergency exit.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1649A: T.C. 4A17	SA259WE	Interior installation.	WE	52010	Lockheed Aircraft Service Co. International Airport Ontario, CA 91761
1649A: T.C. 4A17	SA466CE	Fairchild A-100 cockpit voice recorder.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
1649A: T.C. 4A17	SA836WE	Hydro-Aire Mark II anti-skid braking system to reduce required landing field length.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98155
1649A-98: T.C. 4A17	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
1649A-98: T.C. 4A17	SA2666WE	Ceconite 102 material covering rudders and trim tabs. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329; T.C. 2A15	SA297EA	DMET system.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA298EA	FM radiophone and R/O communications.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA299EA	Stowage box assembly.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA299WE	Interior modification and zero fuel weight increase to 23,700 pounds.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA302SW	HF-1 and HF-LM overspeed warning system.	SW	40000	The Hamilton Company 106 Neuhaus St. Houston, TX 77002
1329; T.C. 2A15	SA307WE	Custom interior.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA310SW	Jump seat.	SW	34000	Executive Aircraft Serv., Inc. Redbird Airport Dallas, TX 75232 AND
1329; T.C. 2A15	SA310SW	Jump seat.	SW	22792	Clark Engineering Service 6441 Happy Lane Dallas, TX 75221
1329; T.C. 2A15	SA322SW	Crew baggage rack and fire proof stainless steel box between stations 619.0 and 655.25.	SW	77010	Superior Oil Company Houston, TX 77002
1329; T.C. 2A15	SA331EA	Electronic equipment.	EA	52012	Lockheed Aircraft Service Co. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA334WE	Interior modification and zero fuel weight increase to 23,700 pounds. Amended 11/10/65.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA336SW	Couch. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA345SW	Bendix Doppler radar navigation system.	SW	12250	Associated Radio Service Co. 7515 Lemmon Ave. Dallas, TX 75220
1329; T.C. 2A15	SA346SW	Koehler Air-Lav 45 with outside servicing.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232 AND
1329; T.C. 2A15	SA346SW	Koehler Air-Lav 45 with outside servicing.	SW	27792	Clark Engineering Service 6441 Happy Lane Dallas, TX 75221
1329; T.C. 2A15	SA357EA	Bulkhead and door at fuselage station 527.5. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA359EA	Bulkhead at fuselage station 310.2. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	ST416SO	Installation of a Collins AP-104, S/N 5136 and up.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
1329; T.C. 2A15	SA424SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA452EA	Bulkhead and door at fuselage station 329 13/32. Amended 3/3/67.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA496EA	Installation of Vis-Audio engine low RPM warning system Model 600J. Amended 5/13/69.	EA	51095	Martin Lipstein 97 Stoneybrook Drive Metuchin, NJ 08840
1329; T.C. 2A15	SA496SW	Cockpit jump seat.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329; T.C. 2A15	SA499EA	Installation of bulkhead and door at F.S. 523.	EA	12500	Atlantic Aviation Service Co. P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA530EA	Electronics installation per Lockheed Report 3163. Interior installation per Lockheed Report 3164 and AFM Supplement No. 2.	EA	52012	Lockheed Aircraft Serv. Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA535SW	Relocation and use of miniature switches in fuel flow system.	SW	12250	Associated Radio Service Co. 7515 Lemmon Ave. Dallas, TX 75220
1329; T.C. 2A15	SA536SW	Litton low range radio altimeter system.	SW	12250	Associated Radio Service Co. 7515 Lemmon Ave. Dallas, TX 75220
1329; T.C. 2A15	SA549EA	Installation of spare tire storage provisions. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329; T.C. 2A15	SA549EA	Installation of stowage provisions for 4 metal containers and tools. Reissued 3/20/74.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329; T.C. 2A15	SA549SW	Spare tire mount. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329; T.C. 2A15	SA576EA	Alteration of AC system control panel.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329; T.C. 2A15	SA592EA	Incorporation of systems and equipment complying with Category II performance standards.	EA	80910	United States Air Force Hq. 89th Military Airlift Wing (SM) MAC Andrews AFB Washington, D.C. 20331
1329; T.C. 2A15	SA602SW	Hinged instrument panel.	SW	12250	Associated Radio Service Co. 7515 Lemmon Ave. Dallas, TX 75220
1329; T.C. 2A15	SA616EA	Installation of UHF/FM secure system.	EA	52012	Lockheed Aircraft Service Co. Div. of Lockheed Aircraft Corp. JFK International Airport Jamaica, NY 11430
1329; T.C. 2A15	SA616SW	Spare tire rack. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA618SW	Interior modifications. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, Tx 76106
1329; T.C. 2A15	SA623SW	Low oil pressure warning switch. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329; T.C. 2A15	SA687EA	Modification of Collins FD109G flight director.	EA	80910	Dept. of the Air Force Hq. 89th Military Wing (SM) MAC Andrews AFB Washington D.C. 20331
1329; T.C. 2A15	SA652SW	Auxiliary power unit.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA700SW	Audible fire warning system. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329; T.C. 2A15	SA703SW	Interior modification. Reissued April 1973.	SW	84600	Ward International Aircraft Service, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
1329; T.C. 2A15	SA762SW	Smith servo altimeter system.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA769SW	Collins 329P-1D peripheral commander.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329; T.C. 2A15	SA780SW	Bendix PB-60 automatic flight control system.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
1329; T.C. 2A15	SA781SW	Bendix FD-300 flight director system.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
1329; T.C. 2A15	SA782SW	Bendix polar path compass system.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
1329; T.C. 2A15	SA782EA	Installation of Lamar, Inc. Model ISM-1 engine speed monitor. Amended 6/26/70.	EA	49339	Lamar, Incorporated Burlington Country Airport Medford, NJ 08055
1329; T.C. 2A15	SA783SW	Bar extension equipment shelf.	SW	12250	Associated Radio Service Co. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA789WE	Interior modification.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA797CE	Install Kollsman altimeter P/N B39049-10-226 and altitude alerting unit P/N B55471-41-180.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l. Airport Kansas City, MC 64153
1329; T.C. 2A15	SA798CE	Install Bendix standby horizon P/N 19787991-1 & inverter type BS-823A, P/N 501-1075-1.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l. Airport Kansas City, MC 64153
1329; T.C. 2A15	SA803WE	Battery relocation.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA827SW	Fairchild 5424-502 flight data recorder.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA828SW	Fairchild A100 cockpit voice recorder.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA837WE	Interior installation.	WE	52010	Lockheed Aircraft Service, Inc. International Airport Ontario, CA 91761
1329; T.C. 2A15	SA851SW	Dual Bendix FD-60 flight director system.	EA	16010	The Bendix Corporation Navigation & Control Division Teterboro, NJ 07608
1329; T.C. 2A15	SA872SW	AP-104 autopilot, FD-109H/FD-109F flight director, comparator, AL-101 radio altimeter gyros, compass, and VHF/NAV interconnect for Category II operation.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
1329; T.C. 2A15	SA879SW	Hinged instrument panel and modification to control column.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA883SW	Mounting bracket antenna tuner.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Dallas, TX 78420
1329; T.C. 2A15	SA884SW	Hoskins power supply support.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA885SW	Bulkhead coax fitting and VHF or FM antenna.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA887SW	L Band Antenna.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station, Dallas, TX 78420
1329; T.C. 2A15	SA900SW	Skyphone antenna	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329; T.C. 2A15	SA902SW	Howell autotemp indicators.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA904SW	Relocation of mach airspeed warning switch.	SW	12250	Associated Radio Service Co. P.O. Box 20718 Walnut Hill Station Dallas, TX 78420
1329; T.C. 2A15	SA917SW	Master fire warning system, TVI system glare shield, instrument panel, and fuel management panel modification. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329; T.C. 2A15	SA919SW	Collins AL-101 radio altimeter system. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329; T.C. 2A15	SA928SW	Relocation of batteries and addition of third battery, AC inverters. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329; T.C. 2A15	SA952SW	Bendix doppler radar system. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329; T.C. 2A15	SA953SW	Bendix radio altimeter. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329; T.C. 2A15	SA955WE	Rain repellent system.	WE	45500	Jay-Dee Acft. Supply Co. Inc. 3021 Airport Avenue Santa Monica, CA 90405
1329; T.C. 2A15	SA990SW	Collins AP104 autopilot and FD109H/FD109F flight directors and IDC air data computer. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329; T.C. 2A15	SA1005SW	General Precision GPF-1000/GPQ-601 doppler radar navigation system.	EA	38518	General Precision Systems, Inc. 63 Bedford Road Pleasantville, NY 10570
1329; T.C. 2A15	SA1011SW	Relocation of inverters and batteries. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
1329 Series; T.C. 2A15	ST1032SO	Replacing existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 11/16/78.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
1329; T.C. 2A15	SA1104SW	Hartman vertical scale engine instruments and OAT instrument. Issued 12/4/69.	EA	40150	Hartman System Company, Inc. 360 Wolf Hill Road Huntington, NY 11746
1329; T.C. 2A15	SA1123WE	Froehler Air-Lav Models 45 and 25.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1124WE	Assembly and installation of jump seat in cockpit doorway. Amended 3/19/68.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1125WE	Bendix doppler antenna.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1185SW	Litton LTN-51 inertial navigation system. Issued 8/24/70.	SW	34000	Executive Aircraft Service, Inc. Redbird Airport Dallas, TX 75232
1329; T.C. 2A15	SA1283WE	Interior furnishing and avionics equipment.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329; T.C. 2A15	SA1325WE	Two of three inverters relocated forward of the nose wheel well.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1326WE	Two batteries relocated to under the floor at front of cabin.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329; T.C. 2A15	SA1359WE	United Control F-542 flight data recorder system.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329: T.C. 2A15	SA1428SW	Collins INS-61B inertial navigation system. Reissued 11/72.	CE	24250	Collins Radio Company 325 10th Avenue, S.E. Cedar Rapids, IA 52406
1329: T.C. 2A15	SA1483WE	Installation of a modified control column component.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329: T.C. 2A15	SA1512SW	Model 7107 battery fault warning system. Issued 11/14/72.	SW	66500	Ray Electronics 107 Braniff Drive San Antonio, TX 78216
1329: T.C. 2A15	SA1525SW	TRAMM BT1 600 nickel cadmium battery temperature indicator. Issued 10/18/72.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
1329: T.C. 2A15	SA1533SW	Lear-Siegler 51528-000 solid state voltage regulator. Issued 10/31/72.	SW	17116	Kenneth J. Brenner 1124 Parkhave Drive Richardson, TX 75080
1329: T.C. 2A15	SA1537WE	Installation of control column.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Hwy. Los Angeles, CA 90045
1329: T.C. 2A15	SA1869SW	Two Hamilton Standard air cycle refrigeration units. Reissued 1/27/81.	SW	26230	Cooper Airmotive Aircraft Service 3300 Love Field Drive Dallas, TX 75235
1329: T.C. 2A15	SA1997SW	Continuous ignition control system. Issued 6/18/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329: T.C. 2A15	SA2978SW	Oxygen system. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329: T.C. 2A15	SA2984SW	Low oil pressure sensor switch. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329: T.C. 2A15	SA2985SW	Inverter relocation. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329: T.C. 2A15	SA2998SW	Litton LTN-72R INS/RNAV system. Issued 5/23/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329: T.C. 2A15	SA4018WE	Installation of on-board air stairs. Issued 12/6/79.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
1329: T.C. 2A15	SA4082SW	Pitot heat monitoring system. Issued 2/12/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329: T.C. 2A15	SA4195SW	Landing flap/gear up warning system. Issued 10/30/80.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329-23 (Jetstar); T.C. 2A15	SA1126SO	Deletion of empennage de-icing provisions - removal of empennage de-icing boots. Issued 1/9/80.	SO	52020	Lockheed - Georgia Company 86 South Cobb Drive Marietta, GA 30063
1329-23, -23A, -23D, -23E; T.C. 2A15	SA1043WE	Installation of GTCP30-92 or GTCP30-92C auxiliary power units Amended 8/13/76.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Hwy. Los Angeles, CA 90045
1329-23A; T.C. 2A15	ST240GL	Installation of Litton LTN-211 omega navigation system. Issued 5/2/78.	GL	47630	K-C Aviation, Inc. Outagamie Airport Appleton, WI 54911
1329-23A; T.C. 2A15	SA868EA	Modification of Sperry SP40C autopilot, installed per STC SA1664WE. Reissued 3/20/78.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
1329-23B; T.C. 2A15	SA883EA	Installation of AIMS equipment. Issued 9/10/71	SO	07700	Department of the Air Force Warner Robbins Air Material Area (MMC) Robins AFB, GA 31093
1329-23A; T.C. 2A15	SA950EA	Installation of air-conditioning flood duct. Reissued 10/13/77.	EA	63275	RATS, Incorporated 9033-C Red Branch Road Columbia, MD 21045
1329-23A; T.C. 2A15	SA1596CE	Installation of electrical power generation system modification system. Issued 6/6/80.	CE	24540	Colt Electronics Co., Inc. 15301 West 109th Lenexa, KS 66219

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329-23A, -23D, -23E; T.C. 2A15	SA374CE	Installation of Symbolic Displays Twilighter Mk. III supplemental lighting system. Amended 5/29/73.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92664
1329-23A, -23D, -23E; T.C. 2A15	SA880EA	Installation of Solar T-62T-39 gas turbine auxiliary power unit. Amended 12/21/79.	EA	63275	PATS, Inc. 7190-B Oakland Mills Road Columbia, MD 21046
1329-23A, -23D, -23E; T.C. 2A15	SA898CE	Installation of AID battery temperature monitor and over-temperature warning system. Amended June 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Wichita, KS 67202
1329-23A, -23D, -23E, -25; T.C. 2A15	ST911SO	Installation of Bendix GPW-83 ground proximity warning system. Amended 8/3/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
1329-23A, -23D, -23E; T.D. 2A15	SA918SW	Installation of Teledyne avionics normalized angle of attack indicating system. Reissued 1/7/72.	SW	78127	Teledyne Inc. 3401 Shiloh Road Garland, TX 75040
1329-23A, -23D, -23E; T.C. 2A15	SA954EA	Installation of battery isolation system. Issued 5/4/73.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329-23A, -23D, -23E; T.C. 2A15	SA996EA	Installation of Shaw Aero fuel filler cap P/Ns 457-2, -266, -370, 431, -9R, -125, -1251. Amended 4/26/78.	EA	71512	Shaw Aero Devices, Inc. Industrial Road East Hampton, NY 11937
1329-23A, -23D, -23E, -25; T.C. 2A15	SA1459CE	Installation of mocrowave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
1329-23A, -23D, -23E; T.C. 2A15	SA1664WE	Installation of Sperry SP-40C auto flight control system and SPI-73B Sperry instrumentation system.	WE	74570	Sperry Flight Systems Div. Sperry Rand Corporation 21111 North 19th Avenue Phoenix, AZ 85027
1329-23A, -23D, -23E; T.C. 2A15	SA1930WE	Installation of Collins Model WP-130G weather radar system. Reissued 9/4/69.	WE	24253	Collins Radio Company 9841 Airport Boulevard Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
1329-23A, -23D, -23E; T.C. 2A15	SA2603WE	Installation of single point refueling system. Amended 8/20/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-23A, -23D, -23E; T.C. 2A15	SA3207WE	Installation of Rosemount pitot/static probes. Issued 7/23/76.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3208WE	Installation of Litton LTN-104 navigation system. Issued 7/23/76.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3209WE	Installation of Collins AP-105 autopilot and FD-109 flight director. Issued 7/16/76.	WE	07500	AiResearch Aviation Corporation 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3210WE	Installation of a Teledyne angle of attack system. Issued 11/19/76.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3221WE	Installation of a single point refueling system for Lockheed Jetstar airplane with AiResearch TFE731-3 engines. Amended 8/18/76.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-23A, -23D, -23E; T.C. 2A15	SA3268WE	Installation of a single or dual Collins 61B inertial navigation system. Amended 12/8/77.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3365WE	Installation of Delco Carousel IVA inertial navigation system. Issued 6/7/77.	WE	85135	Western Commander, Inc. 16300 Dailey Drive Van Nuys, CA 91406
1329-23A, -23D, -23E; T.C. 2A15	SA3389WE	Installation of Delco C-IVA inertial navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329-23A, -23D, -23E; T.C. 2A15	SA3536WE	Installation of nickel-cadmium batteries in aircraft nose compartment. Issued 12/9/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3563WE	Installation of Eldec engine fuel flow and totalizer system. Issued 2/22/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E; T.C. 2A15	SA3704WE	Installation of single or dual Litton LTN-211 Omega Navigation System. Amended 8/27/80.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA2943WE	Installation of recognition lights on horizontal stabilizer upper surface. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
1329-23A, -23D, -23E, -25: T.C. 2A15	SA3206WE	Installation of Garrett AirNav 100 or 200 or 300 area navigation system. Amended 8/29/80.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25: T.C. 2A15	SA3372WE	Installation of single or dual ONTRAC III VLF/Omega navigation systems. Amended 5/13/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3390WE	Installation of Global Model GNS-500A VLF/Omega navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25: T.C. 2A15	SA3391WE	Installation of Delco C-IVA inertial navigation system. Issued 5/6/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -23E, -25; T.C. 2A15	SA3572WE	Installation of Sperry TERN-100 area navigation system. Issued 2/14/78.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23A, -23D, -25; T.C. 2A15	SA3520WE	Installation of Sperry SPZ-500 autopilot and Sperry SPI-80/81 flight directors. Issued 11/23/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-23D; T.C. 2A15	SA928EA	Installation of battery isolation circuit. Issued 7/14/72.	EA	70580	Scott Paper Company Scott Plaza Philadelphia, PA 19113
1329-23D; T.C. 2A15	SA931EA	Installation of battery isolation system. Issued 8/24/72.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
L1329-23E; T.C. 2A15	SA116GL	Installation of Global GNS-500A VLF/OMEGA navigation system. Amended 3/2/78.	GL	61880	Onan Corporation 1400 - 73rd Avenue, Northeast Minneapolis, MN 55432
1329-23E; T.C. 2A15	SA1989WE	Installation of United Control approach speed system, computer P/N 965-0158-001. Reissued 8/26/70.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA455GL	Installation of a Collins LRN-80 Omega navigation system. Issued 10/28/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Indianapolis, MN 55450
1329-25; T.C. 2A15	SA1049EA	Installation of seat tracks and cabin decks. Issued 6/7/77.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
1329-25; T.C. 2A15	SA1052EA	Installation of Solar gas turbine auxiliary power unit T-62T-40C. Amended 3/12/79.	EA	63275	PATS, Inc. 7190-8 Oakland Mills Road Columbia, MD 21046
1329-25; T.C. 2A15	SA1056EA	Installation of a speed command of attitude and thrust system (SCAT). Amended 7/19/79.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
1329-25; T.C. 2A15	SA1581CE	Modification of aircraft to incorporate a fuel management computer. Issued 4/1/80.	CE	24540	Colt Electronics Company 15301 West 109th Street Lenexa, KS 66219
1329-25; T.C. 2A15	SA2920SO	Installation of BKM pitot heat monitor system. Issued 2/28/79.	SW	16852	The BKM Company P.O. Box 7001 Dallas, TX 75209
1329-25;	SA2976SW	Floor plan arrangement, floorboards and seat track. Issued 4/13/79.	SW	47632	K-C Aviaiton, Inc. 7440 Aviation Place Dallas, TX 75235

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
1329-25: T.C. 2A15	SA2977SW	Pressurized water system lavatory, commissary, and bar. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2979SW	Flushing toilet with outside servicing capabilities. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2980SW	Galley component assembly. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2981SW	Baggage compartment modification aft cabin, station 547.5 to 567.0. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2982SW	Baggage compartment modification, station 240.0 to 310.0, right side. Issued 4/13/79.	SW	47632	K-C Aviation, Inc. 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA2983SW	Cabin entry ramp, center aisle, station 284.0 to 328.0.	SW	47632	K-C Aviation 7440 Aviation Place Dallas, TX 75235
1329-25; T.C. 2A15	SA3297WE	Installation of GTCP 30-92C auxiliary power unit. Issued 1/21/77.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
1329-25; T.C. 2A15	SA3324WE	Installation of a single point refueling system for Lockheed Jetstar airplane. Issued 1/17/77.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
1329-25: T.C. 2A15	SA3371WE	Installation of Teledyne angle of attack system. Issued 3/10/77.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
382; T.C. A1SO	SA3793WE	Installation of Tracor 7640A ONS. Issued 2/2/79.	WE	79200	Transinternational Airlines Engineering Department P.O. Box 2504 Oakland International Airport Oakland, CA 94164
382, 382B; T.C. A1SO	ST427SO	Installation of cargo rail system Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382, 382B, 382E; T.C. A1SO	SA733CE	Installation of cargo pallets.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
382. 382B, 382E, 382F, 382G: T.C. A1SO	SA1625WE	Pallet assembly provisions per FAA Sealed L.A.S. Top Drawing 4035910 as modifying aircraft with four FC-97, 1800 gallon tanks installed in accordance with STC SA889WE. Amended 2/23/77.	WE	52010	Lockheed Aircraft Service Co. P.O. Box 33 Ontario, CA 91761
382, 382B, 382E, 382G: T.C. A1SO	ST400SO	Installation of palletized cargo loading and restraint system. Amended 11/25/74.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382, 382B, 382E, 382G: T.C. A1SO	ST407SO	Installation of palletized cargo loading and restraint system. Amended 4/7/72.	SO	52020	Lockheed-Georgie Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA303AL	Installation of 4000 gallon steel tank in the cargo compartment.	AL	44045	Interior Airways, Inc. P.O. Box 3029 Fairbanks, AK 99701
382B; T.C. A1SO	SA368SO	Palletized cargo loading system. Amended 7/10/67.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B; T.C. A1SO	SA374SO	Palletized cargo loading system per Lockheed Industrial Products top assy. dwg. 256-000. Amended 7/25/69.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060
382B: T.C. A1SO	SA1274WE	Triple seat/bunk. Amended 7/10/67.	NW	08480	Alaska Airlines, Inc. Seattle-Tacoma Int'l Airport Seattle, WA 98109
382B, 382F, 382G: T.C. A1SO	ST401SO	Installation of palletized cargo loading and restraint Amended 11/25/74.	SO	52020	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30060

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
382B, 382E, 382G: T.C. A1SO	ST527SO	Installation of inplane cargo system in accordance with Aeronautical Engineers, Inc. dwgs. AE2178 & AE2178, Change "C". Reissued 2/13/73.	SO	73870	Southern Air Transport, Inc. P.O. Box 1266 International Airport Miami, FL 33148
382B, 382E, 382G: T.C. A1SO	SA569AL	Installation Collins FPC-75 ground proximity warning system. Issued 11/25/75.	AL	08488	Alaska International Air, Inc. P.O. Box 60029 Fairbanks, AK 99701
382E: T.C. A1SO	SA2461WE	Installation of Sorm bulk liquid cargo tank assembly SI-3100. Issued 12/17/71.	NW	73820	Sorm Industries 7999 Perimeter Road, South Seattle, WA 98108
382E: T.C. A1SO	SA3171WE	The auxiliary power unit Model GTC 85-71 located in the forward end of the left hand main landing gear wheel well fairing has been replaced by an AiResearch Gas turbine compressor Model GTCP 85-98CK(A). Issued 4/9/76.	WE	87450	World Airways, Inc. Maintenance & Engrg. Center Oakland International Airport Oakland, CA 94614
382E, 382G: T.C. A1SO	SA1156SO	Installation of dual Litton, LTN-211, Omega navigation system (ONS). Issued 7/3/80.	SO	73870	Southern Air Transport, Inc. P.O. Box 52-4093 International Airport Miami, FL 33152
382E, 382G: T.C. A1SO	SA2418WE	Installation of cargo loading system. Issued 9/29/71.	WE	70258	Saturn Airways, Inc. P.O. Box 2426 Oakland International Airport Oakland, CA 94614
382E, 382G: T.C. A1SO	SA3144WE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/9/76.	WE	68770	Rockwell International Corp. Collins Radio Group 750 S. Douglas Street El Segundo, CA 90245
382G: T.C. A1SO	ST913SO	Installation of six 24" x 36" plug type doors in cargo compartment walls. Issued 12/1/76.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G: T.C. A1SO	SA1056SO	Increase in zero fuel weight from 126,790 lbs. to 128,790 lbs. with pylon tanks on and 125,000 lbs. to 127,000 lbs. without pylon tanks. Issued 3/23/79.	SO	52002	Lockheed-Georgia Company 86 South Cobb Drive Marietta, GA 30063
382G: T.C. A1SO	SA2912WE	Installation of palletized dual LTN-51 INS or dual LTN-72 INS or combination of either. Amended 9/26/74.	WE	51500	Litton Systems, Inc. Aero Product Division 21050 Burbank Blvd. Woodland Hills, CA 91364
382G: T.C. A1SO	SA2929WE	Installation of palletized dual LTN-51 or dual LTN-72 INS or combination of either. Issued 10/2/74	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Blvd. Woodland Hills, CA 91364

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MAULE AIRCRAFT CORP.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M-4; T.C. 3A23	SA316SO	Installation of carburetor ice detector.	SO	71545	Charles B. Shivers, Jr. 8929 Valleybrook Road Birmingham, AL 35206
M-4; T.C. 3A23	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
M-4; T.C. 3A23	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
Bee Dee M-4, M-4; T.C. 3A23	SA273WE	Vacuum system 121A.	WE	40689	Harms Industries P.O. Box 3246 Inglewood, CA 90306
M-4, 4C, 4S, 4T, M-4-210, 210C, 210S, 210T; T.C. 3A23	SA222AL	Installation of L-2500A skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
M-4, M-4C, M-4S, M-4T, M-4-210, M-4-210C, -210S, -210T, M-4-220, -220C, -220S, -220T, M-4-180C, M-4-180S, M-4-180T; T.C. 3A23	SA433AL	Installation of Wilbur's tire-cushioned model 2300 skis. Amended 12/16/71.	AL	86070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4, -4C, -4S, -4T, M-4-210, -210S, -210T; T.C. 3A23	SA693SW	AK223 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municiapl Airport Mineral Wells, TX 76067
M-4, M-4-210; T.C. 3A23	SA258CE	Remove right rear door.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4, M-4-210; T.C. 3A23	SA486CE	Installation of Canadian Aircraft Products, Ltd. Model 62-2000 floats. Amended 7/20/67.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M4, M-4-210, M-4-210C; T.C. 3A23	SA690SW	Wing tips modified.	SW	34900	Harvey J. Ferguson Upper Valley Aviation, Inc. McAllen, TX 78501
M4-4C, -4S, -4T, M-4-210, -210C, -210S, -210T; T.C. 3A23 Applicable only to aircraft modified by STC SA963SW.	SA808SW	Installation of Mitchell Model AK246 omni-tracker.	SW	60000	Edo-Aire Mitchell P.O. Box 610 Mineral Wells, TX 76067
M-4-210, -5-210C; T.C. 3A23	SA164AL	Installation of auxiliary cabin heater and cowl flaps. Amended 2/10/76.	AL	86070	Wilbur's Flight Operations 1740 East Fifth Avenue Anchorage, AK 99501
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA589CE	Installation of Fleet Manufacturing, Ltd. Model 2500 floats.	GL	56750	Maule Aircraft Corp. 6780 Brooklyn Road Rural Route 6 Jackson, MI 49201
M-4-210, M-4-210C, M-4-210S, M-4-210T; T.C. 3A23	SA609CE	Installation of Edo Corp. Model 248A-2440 or Model 248B440 floats. Amended.	SO	56750	Maule Aircraft Corp. Spence Air Force Base Moultrie, GA 31768
M-4-210, M-4-220, M-4; T.C. 3A23	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
M-4-210C, -220C, M-5-210, -220C; T.C. 3A23	SA2931WE	Installation of plexiglas covering for two main cabin doors, right passenger door, and baggage door. Issued 9/17/74.	WE	36190	Foothill Aircraft Sales and Service 13th and Benson Upland, CA 91786
M4-220; T.C. 3A23	SA415SO	Installation of Mitchell Century II autopilot. Amended 6/26/69.	SO	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M4-220; T.C. 3A23	SA417SO	Installation of aileron stabilizer and tracker.	SO	56750	Maule Aircraft Corporation Spence Air Base Moultrie, GA 31768
M-4-220, M-4-220C, M-4-220S, M-4-220T;	SA610CE	Installation of Edo Corp. Model 248A-2440 or Model 248B-2440 floats. Amended 9/19/69.	SO	56750	Maule Aircraft Corporation Spence Air Force Base Moultrie, GA 31768
M-4-220C; T.C. 3A23	SA906NW	Additional Harrison oil cooler. Issued 3/21/80.	NW	70620	Seaplane Flying, Inc. P.O. Box 61586 Vancouver, WA 98666
M-4, M-5; T.C. 3A23	SA697AL	Installation of main landing gear and tail landing gear wheel skis. Issued 10/14/80.	AL	70365	Richard J. Schneider 20 Malaspina Drive Eagle River, AK 99577
M-4-220C, -5-220C; T.C. 3A23	SA1160SO	Installation of Weldon, P/N 6005-2A, aircraft engine driven fuel pump in lieu of diaphram type pump. Issued 10/3/80.	SO	75840	Stones River Air Service, Inc. Hangar 621, Smyrna Airport Smyrna, TN 37167
M-5-180C, -210C, -220C, -235C; T.C. 3A23	SA500GL	Install fiberfloat wing tips, P/N 280-2 and 280-3. Issued 1/26/81.	GL	82450	Brian Van Wagnen Aircraft Specialists 6780 Brooklyn Road Jackson, MI 49201
M-5-210C, M-5-220C, M-5-235C, M-5-210TC; T.C. 3A23	SA937SO	Installation of aqua Model 2400 floats. Amended 6/20/80.	SO	22776	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
M-5-210C, M-5-235; T.C. 3A23	SA1099SO	Installation of Fiberfloat model 2400 or 2400A floats and modified wing tips. Issued May 1980.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830
M-5-235C; T.C. 3A23	SA1008WE	Installation of poly-fiber covering material of fuselage and empennage. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
M-5-235C; T.C. 3A23	SA1099SO	Installation of Fiberfloat Model 2400 floats and modified wing tips. Issued 9/4/79.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-6, DC-6A (C-118A), DC-6B; T.C. A-781, 6A3, 6A4	SA1066SO	Alternate installation of hydraulic pump utilizing existing engine drive. Issued 4/23/79.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 Northwest 57th Avenue Miami, FL 33152
DC-6, -6A (C-118A), -6B; T.C. A-781, 6A3, 6A4	SA1083SO	Installation of four Pratt & Whitney R-2800-99W engines and Hamilton Standard propellers. Issued 7/3/79.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 28426 Atlanta, GA 30328
DC-6, -6B; T.C. 781, 6A4	ST456SO	Installation of cargo restraining bulkhead. A clean and unobstructed passageway between the crew compartment and cargo compartment on the side of the bulkhead is required. Issued 4/9/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST463SO	Installation of cargo door. Issued 5/4/71.	SO	58700	Miami Aviation Corporation Hangar 102, Opa Locka Airport Opa Locka, FL 33054
DC-6, -6B; T.C. 781, 6A4	ST470SO	Installation of aft cargo door. Issued 6/22/71.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST495SO	Installation of aft cargo door. Issued 2/28/72.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST535SO	Installation of cargo floor. Amended 6/4/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST536SO	Installation of aft cargo door. Amended 6/16/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6, -6B; T.C. 781, 6A4	ST555SO	Installation of rear cargo door. Issued 9/28/73.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33152
DC-6, -6B; T.C. 781, 6A4	ST595SO	Installation of exhaust system bracket. Reissued 11/14/80.	SO	12535	Atlas Aircraft Corporation 7800 Northwest 41st Street Miami, FL 33166
DC-6, -6B; T.C. 781, 6A4	ST597SO	Installation of aft cargo door. Amended and reissued 6/16/75.	SO	02394	Aeronautique Engineering, Inc. 342 N.E. 2nd Court Dania, FL 33004
DC-6, -6B; T.C. 781, 6A4	ST943SO	Installation of aft cargo door. Amended 6/3/75.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 480602 Miami, FL 33148
DC-6 Series, DC-7 Series; T.C. 781, 6A3, 6A4, 4A10	SA4-328	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-329	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA4-330	Step kit added to fore and aft cargo door.	WE	61194	National Aircraft Corporation 3411 Tulare Avenue Burbank, CA 91500
DC-6, DC-7; T.C. 6A3, 6A4, 4A10	SA76RA	Radome assembly 3016.	GL	21220	Chamberlain Aviation, Inc. 2664 Gilchrist Road Akron, OH 44309
DC-6A, DC-7B, -7BF, -7C, -7CF; T.C. 6A3, 4A10	SA470CE	Installation of Fairchild cockpit voice recorder Model A-100. Amended 3/1/67.	GL	81064	Universal Airlines, Inc. Detroit-Metropolitan Airport Inkster, MI 48141
DC-6A; T.C. 6A3	ST671SO	Installation of cargo loading/restraint system for palletized cargo. Amended 6/24/69.	SO	46000	Jet Avion Corporation 950 S.E. 8th Street Hialeah, FL 33010
DC-6A, DC-6B; T.C. 6A3	ST34GL	Remove cabin pressurization system, modify cabin air heating and ventilating system. Issued 9/24/73.	GL	90135	Zantop International Airlines, Inc. Willow Run Airport Ypsilanti, MI 48197
DC-6A (C-118A), DC-6B; T.C. 6A3, 6A4	ST964SO	Installation of cargo interior, installation of cargo restraint and modification of pressurization system. Amended 10/17/78.	SO	15410	Bellomy-Lawson Aviation, Inc. P.O. Box 480756 Miami, FL 33148

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-6A, DC-6B, USAF C-118A (DC-6A): T.C. 6A4, 6A3	ST974SO	Installation of extra crew seating and air distribution system. Issued 3/29/78.	SO	15410	Bellomy - Lawson Aviation, Inc. P.O. Box 522760 Miami, FL 33152
DC-6A, USAF C-118A, Navy R6D-1, DC-6B, R6D-1Z: T.C. 6A3	ST981SO	Deactivation of the cabin pressurization system, conversion of the cargo compartment to a class "E" compartment, and modification of the ventilation. Amended 10/10/79.	SO	41464	Hayes International Corporation P.O. Box 929 Dothan, AL 36301
DC-6A/C-118A; T.C. 6A3	SA1506CE	Engine driven cabin air compressors and associated cabin pressurization controls removed. Amended 4/8/80.	CE	64292	Petroleum Air Transport, Inc. P.O. Box 187 Hazlewood, MO 63042
DC-6A, R6D-1, C-118A; T.C. 6A3	SA4198WE	Forward and rear cargo door latch assembly, P/N TAS-3361150, and fitting installation, P/N TAS-5359955-8002. Issued 9/5/80.	WE	78500	Time Aviation Services, Inc. 9237 - 9253 San Fernando Road Sun Valley, CA 91352
DC-6A, DC-6B; T.C. 6A3	SA1363WE	Installation of Fairchild Industrial Products Model A100 cockpit voice recorder system. Amended 4/30/69.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 2426 Oakland International Airport Oakland, CA 94614
C-118A; T.C. 6A3	SA770SO	Installation of cargo pallet and container loading and restraint system. Issued 4/12/79.	SO	02390	Aeronautica Engineers, Inc. P.O. Box 661027 Miami, FL 33166
R6D-1; T.C. 6A3	SA3406WE	Modification of oxygen system including addition of supply bottle, pressure relief valve, and microphone in smoke masks. Issued 5/19/77.	WE	03150	Aero Union Corporation Chico Municipal Airport Chico, CA 95926
DC-6B; T.C. 6A4	ST454SO	Installation of aft cargo door. Issued 3/1/71.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST514SO	Installation of forward cargo door. Amended 2/12/75.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6B; T.C. 6A4	ST523SO	Installation of forward cargo door. Amended 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST529SO	Installation of cargo floor. Reissued 3/12/73.	SO	08368	Airtech Service, Inc. P.O. Box 516 Miami, FL 33148
DC-6B; T.C. 6A4	ST532SO	Installation of main cabin compartment. Issued 3/27/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST553SO	Installation of cargo floor. Issued 9/24/73.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 602, I.A.B. Miami, FL 33148
DC-6B; T.C. 6A4	ST729SO	Removal of pressurization and cabin cooling systems. Issued 7/10/72.	SO	15410	Bellomy-Lawson Aviation, Inc. 3100 N.W. 57th Avenue P.O. Box 480756 Miami, FL 33148
DC-6B; T.C. 6A4	SA1434WE	Installation of modified DC-7 type cargo loading system.	WE	70258	Saturn Airways, Inc. Hangar 8, P.O. Box 426 Oakland International Airport Oakland, CA 94914
DC-6B; T.C. 6A4	SA1457WE	Installation on auxiliary power unit in fuselage.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport AVenue Santa Monica, CA 90405
DC-6B; T.C. 6A4	SA1510CE	Engine driven cabin air compressors and associated cabin pressurization controls removed. Amended 4/8/80.	CE	64292	Petroleum Air Transport, Inc. P.O. Box 187 Hazelwood, MO 63042
DC-6B; T.C. 6A4	SA1604SW	Aft cargo door between F.S. 661 and F.S. 801. Issued 2/13/73.	SW	08351	Air Services, Inc. P.O. Box 2 Addison, TX 75001,
DC-6B Cargo; T.C. 6A4	SA1663WE	Modification of DC-6B cargo aircraft to incorporate passenger or combination passenger/cargo arrangements.	WE	25970	Continental Airlines Los Angeles International Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8 Series; T.C. 4A25	SA855WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA994WE	Rain repellent system.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-8 Series; T.C. 4A25	SA1184WE	United Data Control cockpit voice recorder.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1220WE	Brownline pallet 23118-51 and Brownline pallet net 22672-51.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1347WE	GAlley 100 and 200 at fuselage stations 447.75 to 490, and 1385.5 to 1416.	WE	28560	Dale Engineering Company 12243 Branford Street Sun Valley, CA 91352
DC-8 Series; T.C. 4A25	SA1349WE	Passenger entertainment system, stereo and monaural tape deck audio.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8 Series; T.C. 4A25	SA1522WE	Substitution of Brownline cargo container assembly P/N 24026-51 for Douglas pallet assembly P/N 5776662-505 and net P/N 7778335.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airlines San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA1538WE	Installation of Fairchild Model 13920-301 or 15630-601 flight data recorder and Honeywell P/N 180 VT central air data computer.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8 Series; T.C. 4A25	SA1796WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8 Series; T.C. 4A25	SA2318WE	Installation of emergency exit lights. Issued 3/2/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331
DC-8 and DC-8F Series; T.C. 4A25	SA1783WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-8; DC-9; T.C. 4A25, A6WE	SA2534SW-D	Replacement of switch assembly, International Inflatables Co. P/N 68748, with DME Corp. P/N L-140 in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building E Pompano Beach, FL 33060
DC-8; DC-9; T.C. 4A25, A6WE	SA2539SW-D	Replacement of light assembly, International Inflatables Co. P/N 68555-1 with DME Corp. EL-104, EL-104A, 104B in emergency evacuation slide lighting system. Reissued 10/20/76.	SO	30200	DME Corporation 1631 South Old Dixie Highway Building F Pompano Beach, FL 33060
DC-8, DC-9, DC-10; T.C. 4A25, A6WE, A22WE	SA2728WE	Incorporation of Holcombe Industries HI_LITE SYSTEM P/N 50-1001 for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -8F-54, -8F-55, -61, -61F, -62, -62F, -63, -63F: DC-9-11, -12, -13, -14, -15, -15F, -21, -31, -32, -32F, -41: DC-10-10: T.C. 4A25, A6WE, A22WE	SA10GL	Installation of Gayston Model 800LG and 800SC static dischargers on transport category airplanes. Issued 12/15/72.	GL	37125	Gayston Corporation 55 Janney Road Dayton, OH 45404
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, -61, -61F, -62, -62F, -63, -63F, DC-8F-54, -55: T.C. 4A25	SA928WE	Installation of replacement safety belt assemblies. Amended 10/9/74.	WE	68725	Pocket Jet/ARD Division American Safety Flight Systems, Inc. 1311 Grand Central Avenue Glendale, CA 91201

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, F-54, F-55; T.C. 4A25	SA1063SO	Installation of forward cargo door. Issued 4/6/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-11, -12, -21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, -61, -61F, -62, -62F, -63, -63F, DC8F-54/55; T.C. 4A25	SA2539WE	Installation of emblem light. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-8-12, -21, -33, -51, -52; T.C. 4A25	SA228EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 - 148th Avenue Jamaica, NY 11434
DC-8, -12, -21, -31, -32, -33, -52; T.C. 4A25	SA676CE	Installation of Crimsco cargo container, P/N 600301, utilizing Model 6004 adapter in passenger compartment.	CE	27000	Crimsco, Inc. 5001 East 59th Street Kansas City, MO 64130
DC-8-20, -30, -40, -50 Series; T.C. 4A25	SA266GL	Installation of Litton LTN-211 Omega navigation system. Amended 4/26/79.	GL	61788	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-20/50; T.C. 4A25	SA3030WE-D	Install a carry-on baggage module. Issued 9/7/76.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Airport San Francisco, CA 94128
DC-8-21; T.C. 4A25	SA3869WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 2/20/79.	WE	66405	G. S. Rasmussen P. O. Box 10519 Glendale, CA 91209
DC-8-21, DC-8-51; T.C. 4A25	ST449SO	Installation of air data computer with altitude display, altitude reporting, and altitude alerting capabilities. Issued 12/30/70.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, DC-8-51; T.C. 4A25	ST670SO	Installation of International Inflatables Co. P/N 68035 door-mounted emergency evacuation slide at forward entrance door and service door and International Inflatables Co. P/N 68085-3 door mounted emergency evacuation slide at aft entrance and service doors. Amended 10/6/69.	SO	31420	Eastern Airlines, Inc. Miami International Airport Miami, FL 33148
DC-8-21, -51; T.C. 4A25	SA794SO	Installation of a cargo pallet loading and restraint system. Issued 12/16/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -32, -51; T.C. 4A25	ST680SO	Installation of Pan Avion Model LSP-210 and LSP-273 emergency evacuation slides and Pan Avion slide pack containers P/N 017-33 and P/N 017-34 at forward and aft passenger entry and service doors.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -54, -55; T.C. 4A25	ST844SO	Installation of cargo interior. Amended 5/8/79.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -55, DC-8F-54, -55; T.C. 4A25	SA915SW	Installation of Bendix P/N 19F138-2A flexible drive shaft in lieu of Dana P/N 26567 universal joint shaft on Pratt & Whitney Model JT3D-1 engine gear box and C.S.D. Amended 10/1/71.	EA	16000	The Bendix Corporation Fluid Power Division 211 Seward Avenue Utica, NY 13503
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1033WE	Either single or dual Collins AL-101 radio altimeter systems. Amended 11/19/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airlines San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1034WE	Installation control and annuciation circuitry to implement Flight Director "Go-Around" command modes. Amended 4/1/68.	WE	80500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -41, -42, -43, -51, -52, -53, -54, -55; T.C. 4A25	SA1098SO	Installation of a cargo interior. Issued 7/11/79.	SW	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-21, -31, -32, -33, -51, -52, -53, DC-8F-54, -55; T.C. 4A25	SA1405WE	Structural installation of Dorne and Margolin DMC 33-2 Satcom VHF radio antenna.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -32, -51, -61; T.C. 4A25	SA1980WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8, -8-21, -31, -33, -51, -52, -54F, -61, -62; T.C. 4A25	SA2211WE	Installation of Bendix third attitude indicator. Amended 11/25/75.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-21, -52; T.C. 4A25	SA2316WE	Revised interior arrangement to an all-tourist, 149-passenger configuration. Amended 5/23/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -51, DC-9 Series; T.C. 4A25, A6WE	SA2405WE	Installation of PICO Division pressure regulator P/N 3001 on automatically inflatable emergency evacuation slides in lieu of International Inflatables pressure regulator P/N 68240 and 70003. Amended 9/23/71.	WE	70130	Sargent Industries PICO Division 2045 Evans Avenue San Francisco, CA 94124
DC-8-21, -31, -33, -51, -52; T.C. 4A25	SA2573WE	Installation of interior modifications. Amended 3/6/74.	WE	80500	United Air Lines, Inc. Maintenance Base Engineering Department San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -32, -33, -51, -52, -8F-54, -8-61, -61F, -62, -63, -63F; T.C. 4A25	SA2827WE-D	Installation of Collins GPC-75 P/N 622-2615-012 or P/N 622-2615-212 ground proximity warning system computer. Amended 5/12/78.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -51, -52; T.C. 4A25	SA3033WE-D	Revise interior arrangement to increase coach seating. Amended 6/3/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-21, -31, -33, -51, -52, -61, -62, DC-8F-54; T.C. 4A25	SA3189WE	Installation of UAL MEG orifice support tube assembly, P/N 6F13548-501 and -502. Issued 10/4/77.	WE	80500	United Air Lines San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-32, -33; T.C. 4A25	SA792SO	Installation of equipment for transportation of livestock. Issued 10/9/80.	SO	02390	Aeronautical Engineers, Inc. P.O. Box 661027 Miami, FL 33166
DC-8-33; T.C. 4A25	SA260NW	Modification of pax airplane configuration to cargo configuration (bulk). Issued 2/17/76.	NW	69204	Rosenbalm Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	ST266GL	Installation of a Litton LTN 211 Omega navigation system. Issued 8/25/78.	GL	61788	Ohio Air Center, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA289GL	Load palletized livestock as bulk cargo. Issued 12/22/78.	GL	44036	InterContinental Airways, Inc. P.O. Box 765 Wilmington, OH 45177
DC-8-33; T.C. 4A25	SA421NW	Cargo modification as done under STC's SA207NW and SA260NW and SA324NW. Issued 3/15/77.	NW	69204	Rosenbalm Aviation P.O. Box 1524 Medford, OR 97501
DC-8-33; T.C. 4A25	SA2036WE	Installation of Henry Windscreen Model No. 48102. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-8-33; T.C. 4A25	SA2825WE-D	Revise interior arrangement to accommodate all coach, 186 passenger overwater configuration. Amended 4/3/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-33; T.C. 4A25	SA3403WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo handling system, and increasing maximum landing and zero fuel weight. Amended 6/14/78.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-33; T.C. 4A25	SA3611WE	Modification to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3804WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/13/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3907WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 8/20/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-33; T.C. 4A25	SA3910WE	Modifications to permit an increase in maximum allowable zero fuel weight.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3612WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3749WE	Conversion of passenger airplane to cargo only configuration by installation of cargo door, cargo floor, and increasing maximum landing and zero fuel weight. Issued 9/28/78.	WE	52995	McDonnell Douglas Corp. 3855 Lakewood Boulevard Long Beach, CA 90846
DC-8-43; T.C. 4A25	SA3805WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3880WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 3/28/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43; T.C. 4A25	SA3911WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-43, -53; T.C. 4A25	SA2681WE	Installation of enclosed overhead stowage bins, sculptured ceiling panels, with integral lighting, improved sidewall lighting, and revised passenger service units. Issued 4/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-50, -60; T.C. 4A25	SA3963WE	Installation of dual Global GNS-500A VLF/Omega navigation systems. Issued 5/23/79.	WE	33897	Evergreen Air Center Marana Air Park Marana, AZ 85238
DC-8-51; T.C. 4A25	SA1768WE	Installation of stewardess seat Model 6878 on Nordskog galley Model 305A.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-51; T.C. 4A25	SA4078WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 2/6/80.	WE	66405	G. S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-51; T.C. 4A25	SA4080WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 8/21/80.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-51, -52; T.C. 4A25	SA2835WE-D	Installation of enclosed overhead stowage compartments, improved ceiling and sidewall lighting, relocation of motion picture projector compartments and complete cabin refurbishment. Issued 4/30/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-51, -52, -8F-54, -8-61; T.C. 4A25	SA3357WE-D	Retrofit of fuel quantity indicators and totalizers, Gull Airborne Instruments, Inc. P/Ns 206-009 and 206-016 series. Issued 1/30/78.	WE	80500	United Air Lines San Francisco Int'l Airport San Francisco, CA 91406
DC-8-51, -61; T.C. 4A25	ST857SO	Installation of Bendix ground proximity warning system. Amended 11/14/75.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-8-52; T.C. 4A25	SA448NW	Installation of new look interior conversion kit for Aviaco Air Lines.	NW	41625	Heath Tecna Corporation 19819 - 84th Avenue, South Kent, WA 98031

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-52; T.C. 4A25	SA3945WE-D	Installation of a DC-8-51 landing gear on DC-8-52 airplane. Issued 6/9/80.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-53; T.C. 4A25	SA3613WE	Modifications to permit increase in maximum allowable zero fuel weight. Issued 3/27/78.	WE	66405	G.S. Rasmussen P.O. Box 2052 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3806WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 12/26/78.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3908WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3909WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/20/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-53; T.C. 4A25	SA3912WE	Modifications to permit an increase in maximum allowable zero fuel weight. Issued 4/23/79.	WE	66405	G.S. Rasmussen P.O. Box 10519 Glendale, CA 91209
DC-8-55, -61, -63; T.C. 4A25	SA1096SO	Installation of Tracor, Inc. OMEGA navigation systems, dual Models 7640A and 7800. Amended 11/18/80.	SO	19848	Capitol International Airways, Inc. P.O. Box 325 Smyrna, TN 37167
DC-8F; T.C. 4A25	SA605EA	Installation of pallet P/N 6524 incorporating Douglas cargo loading system or pallet P/N 6524 must use nets and be loaded in accordance with Douglas pallet P/N 5776662-505 instructions.	EA	66470	Ray, Daisley Co., Inc. 585 West Hoffman Avenue Lindenhurst, NY 11757
DC-8F-54; T.C. 4A25	SA633CE	Make and install cargo pallets in accordance with Brooks & Perkins Drawing List No. 16987. Reissued 6/3/74.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	ST677SO	Installation of Nordskog galley Models 376, 377, 378 and 379 at right hand galley positions 1, 2, 3, and 4.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST684SO	Interior conversion of passenger cabin to accommodate 24 first class and 105 tourist class passengers. Amended 1/8/70.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-8F-54; T.C. 4A25	ST747SO	Installation of livestock transportation pens. Issued 1/31/75.	SO	21560	Casco Division Charlotte Aircraft Corporation P.O. Box 481225 Miami, FL 33148
DC-8F-54; T.C. 4A25	SA804EA	Installation of Inflight Motion Picture system. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-20 148th Avenue Jamaica, NY 11434
DC-8F-54; T.C. 4A25	SA813CE	Install Brooks & Perkins cargo pallet P/N 17430-100-2. Issued December 1971.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA843CE	Installation of cargo-pallet 17469-500-1. Issued April 1972.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8F-54; T.C. 4A25	SA1793WE	Installation of Heathair AC-0152-1 structural container in DC-8F-54 aircraft equipped with cargo loading system No. 7778202-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54; T.C. 4A25	SA1991WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, -52; 22672-51, -52; or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8F-54; T.C. 4A25	SA1997WE	Installation of Brownline pallet assembly P/N 40309 and net assembly Brownline P/N 21350-51, 21710-51, -52, Douglas P/N 7776431-1 or 7776431-501. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54; T.C. 4A25	SA2025WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125010 with Aeroquip net P/N 3950020, Brownline net P/N 22672-51 or 23143-51, Heath net P/N AC-10069-1 or AC-10357-1 or McDonnell Douglas net P/N 7776967-1.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
DC-8F-54; T.C. 4A25	SA2255WE	Installation of Satco, Inc. pallets P/N 31080-501 and 31076-501. Issued 10/14/70.	WE	70250	Satco, Incorporated 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8F-54; T.C. 4A25	SA2274WE	Installation of Irvin 88 x 125-inch cargo pallet P/N 125109 with Aeroquip net P/N 3950020 or AC600607, McDonnell Douglas net P/N 7776967-1, Heathair net P/N AC-10069-1 or AC-10357-1, or Brownline net P/N 22672-51. Issued 11/12/70.	WE	44750	Irvin Industries, Inc. P.O. Box 300 Gardena, CA 90247
DC-8F-54; T.C. 4A25	SA2745WE-D	This modification provides seats, oxygen, cockpit communications, emergency equipment and other items necessary to carry six couriers or other persons authorized aft of Station 1370. Issued 4/22/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54; T.C. 4A25	SA3586WE-D	Installation of a removable dual Delco C-IV inertial navigation system for navigation only. Issued 10/27/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-54, -55; T.C. 4A25	SA697CE	Installation of Aeroquip Corp. cargo tie-down net.	GL	02500	Aeroquip Corporation Aircraft Division Jackson, MI 49203
DC-8F-54, -55; T.C. 4A25	SA1623WE	Installation of Heath 88 x 125-inch cargo pallet P/N AC-10061-1 and cargo net P/N AC-10069-1 on subject models equipped with McDonnell Douglas cargo loading system No. 7776939. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1665WE	Installation of Heath Tecna 88 x 125-inch cargo pallet, P/N AC-10160 and net P/N AC-10069. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA1875WE	Installation and intermixing of certain pallet/net combinations. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8F-54, -55; T.C. 4A25	SA2064WE	Installation of Tridair 88 x 125 inch cargo net P/N 40657, P/N 40850 or P/N 40517 with pallet assembly Tridair P/N 40160 configuration 101 thru 110, 23224-51; Brooks and Perkins P/N 16987 DL; Irwin Industries P/N 125010; Heathair P/N AC-10366-1; or Douglas P/N 5776662-505. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2234WE	Installation of Brownline Division Division structural container 41342-101B. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -55; T.C. 4A25	SA2278WE	Installation of Brownline cargo container Model 41013. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-F54, -8-55 Series; T.C. 4A25	SA2137WE	Installation of Litton inertial navigation system(s) LTN51 (dual or single) or LTN72 (dual or single).. Amended 12/14/78.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8F-54, -8-55; T.C. 4A25	SA4088WE	Installation of single or dual Litton LTN-72 INS. Issued 1/30/80.	WE	51500	Litton Aero Products 6700 Eton Avenue Canoga Park, CA 91303
DC-8F-54, -8F-55, -8-61F, -62F, -63F; T.C. 4A25	SA1807WE	Installation of Brownline pallets and nets. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-61F, -8-63F; T.C. 4A25	SA2098WE	Modification by installation of structural cargo container 40619-101 and -102. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA1812WE	Installation of Heath Tecna 88 x 125-inch cargo pallets P/N AC-10355-1 and AC-10366-1 and net P/N AC-10357-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
DC-8F-54, -8F-55, -8-63F; T.C. 4A25	SA2118WE	Installation of Brownline cargo container Model 40622. Amended 5/16/75.	WE	79500	Tridair Industries Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-54, -8F-55, -8-63F, -9-32F, -33F; T.C. 4A25, A6WE	SA2152WE	Installation of Heath 88 x 108-inch cargo pallet AC-10527-1 and net AC-10196-1. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 84th Avenue South Kent, WA 98031
DC-8F-54, -8-62F; T.C. 4A25	SA1978WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and Brownline net assembly P/N 22672-51, 22672-52, 23143-51, 40657, 40850, 40517, 22273-51, 22758-51, 22758-52; Douglas net assembly P/N 7776967-1 or Aeroquip net assembly P/N 3950020. Reissued 2/10/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55; T.C. 4A25	SA672EA	Installation of two place courier seat, lavatory compartment and smoke curtain.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8F-55; T.C. 4A25	SA1395WE	Substitution of Brownline pallet P/N 23640-51 and P/N 23224-51 for Douglas pallet P/N 5776662-505.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8F-55, -8-61F; T.C. 4A25	SA1764WE	Installation of Heathair pallet Model AC10194 and net Model AC-10196. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8F-55, -61F, -63F; T.C. 4A25	SA1028EA	Installation of Collins FPC-75 ground proximity warning system. Amended 6/22/76.	EA	70600	Seaboard World Airlines, Inc. Seaboard World Building JFK International Airport Jamaica, NY 11430
DC-8F-55, -8-62F; T.C. 4A25	SA2059WE	Installation of 88 x 125-inch cargo pallet P/N 24076-51, 88 x 108-inch pallets P/N 40309101 and 40309102, and 88 x 53-inch pallets P/N 40464101 and 40464102 with net assemblies 22361-51, 22364-51, 22758-51, 22273-51, 21530-51, 21710-51, -52, and 21869-51. Amended 10/12/70.	WE	17749	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8F-55, -8-63F; T.C. 4A25	SA589EA	Installation of dual omnitrac navigation system. Amended 7/19/68.	EA	70600	Seaboard World Airlines, Inc. Hangar #3 JFK International Airport Jamaica, NY 11430
DC-8F-55, -8-63F; T.C. 4A25	SA675EA	Installation of L. Marino cargo net. Amended 3/31/70.	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236
DC-8F-55, -8-63F; T.C. 4A25	SA725EA	DC-8F pallet P/N LM1600 (1.50 Fwd), DC-8-63F pallet P/N LM1600 (1.50 Fwd).	EA	54999	L. Marino, Inc. 8802 Foster Avenue Brooklyn, NY 11236

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8F-55, -8-63F; T.C. 4A25	SA2218WE	Installation of Satco cargo pallet P/N 3180-501, NAS classification 3610-2A3P and P/N 31076-501, NAS classification 3610-2A1P with cargo nets Brownline P/N 22758-51, -52, -54, 22672-52, 22273-51, 23226-51, 40517-101; Heath Tecna P/N AC 10292-1; Marino P/N LM 1500-100; and ANCRA Corp. P/N 40178-10. Amended 10/12/70.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8-61; T.C. 4A25	SA467EA	Inflight Motion Picture provisions. Reissued 10/24/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-61; T.C. 4A25	SA1400WE	Installation of 198-passenger interior arrangement. Amended 4/17/74.	GL	80500	United Air Lines, Inc. Executive Offices 1200 Algonquin Road Elk Grove Township, IL 60007
DC-8-61; T.C. 4A25	SA1926WE	Dual installation of A.C. Electronics Carousel IV INS units. Amended 1/16/70.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2128WE	Installation of RCA Model AVQ-30C weather radar system.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2558WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other interior changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2674WE	Revised interior arrangement. Issued 3/23/73.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94158
DC-8-61; T.C. 4A25	SA2739WE-D	Revised seating configuration. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2741WE-D	Installation of equipment to provide guidance to flight director and SP-30AL autopilot to conduct two-segment approaches. Amended 4/7/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA2804WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 3/7/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61; T.C. 4A25	SA2824WE-D	Installation of dual Delco C-IV inertial navigation systems. Issued 1/22/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3032WE-D	Install carry-on baggage module in place of one first class seat assembly. Amended 12/27/76.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3038WE-D	Installation of dual Collins FD-109 flight director system. Issued 5/24/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3039WE-D	Installs galley units and all supporting structure including plumbing and wiring at three locations. Amended 8/19/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3040WE-D	Installation of cabin new look, cabin refurbishment, inflight entertainment installation, passenger seat procurement and rework, and internal partitions and stowage cabinet. Issued 6/11/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61;	SA3356WE-D	Revise interior arrangement to accommodate dual class, 12 first class and 177 coach passenger configuration. Issued 11/4/77.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-61; T.C. 4A25	SA3582WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3587WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 12/14/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3588WE-D	Seat mix change from 223 passenger all coach charter configuration to 238 passenger all coach charter configuration. Issued 1/5/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA3593WE-D	Seat mix change from 26 F/C and 156 coach passenger configuration to 26 F/C and 164 coach passenger configuration. Issued 1/21/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC8-61; T.C. 4A25	SA3943WE-D	Rework of high-frequency communications system to install single-sideband capability. Issued 5/16/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61; T.C. 4A25	SA4091WE	Deletion of a pair of excess Type 1 exits at station 1124. Issued 1/22/80.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-61, -61F, DC-8-63, -63F; T.C. 4A25	SA1873WE	Installation of Litton Systems dual LTN-51 or LTN-52 inertial navigation systems. Amended 1/4/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61, -62, -62F; T.C. 4A25	SA1006EA	Installation of cabin interior furnishings. Amended 8/26/77.	EA	12500	Atlantic Aviation Corporation Greater Wilmington Airport P.O. Box 1709 Wilmington, DE 19899
DC-8-61F; T.C. 4A25	ST687SO	Installation of AIF class divider partitions, left hand and right hand assembly, P/N 32012 with header assembly, P/N 32013.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-61F; T.C. 4A25	SA2157WE	Installation of 242 passenger seating arrangement. Issued 6/5/70.	WE	81064	Universal Airlines 401 McCormick Street San Leandro, CA 94577
DC-8-61F; T.C. 4A25	SA2481WE	Installation of Trans Com Model 1357 movie projector and screen assemblies. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
DC-8-61F; T.C. 4A25	SA3279WE	Installation of Litton ground proximity warning system computer P/N 456300-01, -202 in the provisions under STC SA1028EA. Issued 10/28/76.	WE	51500	Litton Systems, Inc. 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F; T.C. 4A25	SA2800WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Amended 3/12/74.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-61F, DC-8-63F; T.C. 4A25	SA630CE	Installation of cargo pallets. Amended 11/1/79.	GL	17750	Brooks & Perkins, Inc. 12633 Inkster Road Livonia, MI 48150
DC-8-61F, -8-63F; T.C. 4A25	SA1733WE	Installation of Nordskog seat assembly P/N 61247 with certain interior arrangements. Amended 4/12/71.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-62; T.C. 4A25	SA1959WE	Installation of movie projection system.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-8-62; T.C. 4A25	SA2299WE	Installation of third AC electronics carousel IV inertial navigation system. Issued 12/31/70.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2310SW	Install wheel and brake advisory system. Issued 5/17/76.	SW	17075	Braniff Airways, Inc. P.O. Box 35001 Dallas, TX 75235

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-62; T.C. 4A25	SA2377WE	Installation of Collins Radio Company INS - 61B inertial navigation system. Amended 12/7/71.	GL	80500	United Air Lines, Inc. P.O. Box 8800 O'Hare International Airport Chicago, IL 60666
DC-8-62; T.C. 4A25	SA2533WE	Modification of interior installation to incorporate enclosed hatrack stowage compartments, improved cabin lighting, and various other architectural changes. Amended 2/5/75.	WE	80500	United Air Lines, Inc. Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2581WE	Installation of Collins Radio Company inertial navigation systems. Issued 8/23/72.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
DC-8-62; T.C. 4A25	SA2738WE-D	Revise seating arrangement to 154 passenger configuration; revise passenger service unit locations to comply with seating configuration; install class dividers and curtains. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2742WE-D	Install dual class seating arrangement (4 and 6 across). Amended 5/2/75.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2818WE-D	Installation of triple Delco Electronics carousel IV-A inertial navigation system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2819WE-D	Installation of Atlantic Aviation wide body kit. Issued 11/8/74.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2820WE-D	Installation of passenger entertainment and automatic announce system. Issued 11/9/74.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2840WE-D	Install an alternate all tourist seating and galley configuration. Galley configuration was previously approved under STC SA2296WE. Amended 6/8/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA2904WE	Installation of GAMMA inertial navigation system. Issued 7/2/74.	WE	71838	The Singer Company Kearfott Division 5730 West Manchester Avenue Los Angeles, CA 90045
DC-8-62; T.C. 4A25	SA3351WE-D	Installs a 181 passenger all coach cabin seating configuration.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3361WE-D	Installs a 16 first class/123 coach dual class seating configuration. Issued 1/16/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3576WE-D	Revise interior arrangement to accommodate 162 coach passenger configuration. Issued 6/2/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62; T.C. 4A25	SA3584WE-D	Seat mix change from 162 passenger all coach configuration to 18F/129Y-147 passenger configuration. Amended 11/1/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-8-62, -62F; T.C. 4A25	SA993EA	Installation of Inflight Motion Pictures, Inc. 16 mm. movie projection system IP4000 and screen assemblies. Amended 8/26/77.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-8-62F; T.C. 4A25	SA2308WE	Installation of cargo barrier net. Issued 1/27/71.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-8-62F; T.C. 4A25	SA2785WE	Installation of dual Litton LTN-51 or LTN-72 inertial navigation system. Issued 11/20/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-62F, DC-9-31; T.C. 4A25, A6WE	SA532EA	Installation of fabric cargo bins in passenger compartment. Amended 12/10/74.	EA	55000	Marino Systems, Inc. 17 Battery Place New York, NY 10004
DC-8-63; T.C. 4A25	SA649SO	Installation of lounge table AIF P/N 31538-101.	SO	05356	Aircraft Interior Fabricators, Inc. 2180 N.W. 24th Avenue Miami, FL 33142
DC-8-63; T.C. 4A25	ST681SO	Installation of class divider partition assembly P/N 31929-100 left hand and 31929-200 right hand at fuselage station 2900.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST682SO	Installation of lounge table assembly P/N 31928/100 right hand and P/N 31928-101 left hand at fuselage station 338.0.	SO	52544	Ludlum Associates Company P.O. Box 1337 Miami, FL 33148
DC-8-63; T.C. 4A25	ST728SO	Interior modification and installation of 251 passenger service units and galley attachments to provide for 251 passenger arrangement (less seats and galleys). Issued 4/28/72.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-8-63; T.C. 4A25	ST737SO	Main cabin interior modifications. Issued 3/28/73.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-8-63; T.C. 4A25	SA750NW	Installation of Mark I interior kit. Issued 4/12/79.	NW	41625	Heath Techna Corporation 19819 84th Avenue South Kent, WA 98031
DC-8-63; T.C. 4A25	SA913NW	Stowage unit. Issued 3/31/80.	NW	48532	KME, Inc. 1200 112th Avenue, N.E. Bellevue, WA 98004
DC-8-63; T.C. 4A25	SA1730WE	Installation of cockpit voice recorder, seat lights, passenger service outlets, communication panel relocation, galley wiring changes, flight data recorder and vertical accelerometer, pitot tube with heater circuit, marker beacon.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA1738WE	Modification of interior arrangement to 221 passenger Military Airlift Command configuration. Amended 11/7/68.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA1909WE	Modification of interior arrangement to provide automatic folding attendant seats at the four jet escape exits.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63; T.C. 4A25	SA2704WE-D	Installation of enclosed overhead stowage bins, sculptured ceiling panels with integral lighting, cabin refurbishment. Issued 10/19/73.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-9-63; T.C. 4A25	SA3854WE	Installation of Tracor 7640A ONS. Issued 3/21/79.	WE	79200	Transinternational Airlines P.O. Box 2504 Oakland International Airport Oakland, CA 94614
DC-8-63, -63F; T.C. 4A25	SA2154WE	Installation of triple Litton LTN-51 inertial navigation system. Amended 4/23/71.	WE	51500	Litton Systems, Inc. Aero Products Division 6700 Eton Avenue Canoga Park, CA 91303
DC-8-63F; T.C. 4A25	SA652EA	Installation of dual Decca doppler systems, Type 72. Reissued 7/2/69.	EA	44900	I.T.T. Navigator Systems, Inc. 12224 Parklawn Drive Rockville, MD 20852
DC-8-63F; T.C. 4A25	ST766SO	Installation of double deck livestock transportation pens. Issued 11/1/77.	SO	11320	Animal Air Services, Inc. 14441 Northwest 13 Court Miami, FL 33162
DC-8-63F; T.C. 4A25	SA1039EA	Installation of animal restraint system for air shipment of livestock. Reissued 11/9/78.	EA	79304	Transmeridian Air Cargo Ltd. Stansted Airport Stansted, Essex, England
DC-8-63F; T.C. 4A25	SA1731WE	Install single Decca Model 72 doppler radar (ground speed and drift angle only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-63F; T.C. 4A25	SA1928WE	Installation of Heath Tecna 88 x 125-inch cargo pallet P/N AC-10065-1 with Heath Tecna net P/N AC-10292-1 or Brownline net P/N 22758-51. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue, South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1950WE	Installation of 88 x 125-inch cargo pallet P/N 40160 and net assembly P/N 22672-51, 22672-52, 22758-51, 22758-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1955WE	Installation of 88 x 125-inch cargo pallet P/N 40144 and net assembly 22758-51, 22758-52, 22672-51, 22672-52, 40517 or 22273-51. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA1978WE	Installation of underseat baggage restraint system with certain specified seat models. Reissued 1/6/71.	NW	41625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-8-63F; T.C. 4A25	SA1987WE	Installation of Edo Model 144 ADF-Loran antenna splitter.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2017WE	Installation of Decca Model 72 doppler radar (ground speed and drift meter only).	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2018WE	Installation of Decca Model ADL-21 Loran.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2087WE	Installation of Cargo Systems, Inc. 88 x 125-inch cargo pallet assembly 1950-90-1 with Brownline net P/N 22758-51.	WE	19890	Cargo Systems, Inc. 1040 West Hoover Orange, CA 92667
DC-8-63F; T.C. 4A25	SA2113WE	Installation of two Decca Type 05 Omnitrac 2P Doppler/Loran navigation computer systems with pictorial displays.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2247WE	Installation of Lockheed Aircraft Services Company Model 250-A weight and balance computer system. Issued 10/9/70.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2259WE	Installation of Brownline pallet assembly P/N 41339 and Brownline net assembly P/N 41344. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-8-63F; T.C. 4A25	SA2287WE	Installation of Henry Engineering cargo container Model 52501. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-63F; T.C. 4A25	SA2313WE	Installation of Follsman "Slim Pac" altitude alerting system. 3/1/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8=63F; T.C. 4A25	SA2314WE	Revised seating arrangement to 244 passenger all tourist configuration. Issued 2/18/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2427WE	Installation of a third attitude indicator. Issued 10/15/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2465WE	Installation of dual Delco Carousel IV inertial navigation system. Issued 12/30/71.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2522WE	Installation of Nordskog tray carrier storage unit Model 798P. Issued 5/17/72.	WE	61605	Nordskog Company, Inc. 16000 Strathern Street Van Nuys, CA 91406
DC-8-63F; T.C. 4A25	SA2604WE	Installation of Custom Products passenger type seat and flight crew glare protection curtain. Issued 10/24/72.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-8-63F; T.C. 4A25	SA2616WE	Installation of Trans Com Model 1144 movie projector, screen assemblies and sound system. Reissued 4/23/73.	NW	76800	Trans Com A Division of Sundstrand Data Control, Inc. Overlake Industrial Park Redmond, WA 98052
DC-8-63F; T.C. 4A25	SA2632WE	Modification of airplane to provide attitude information from INS in lieu of two vertical gyros (this modification pertains only to aircraft previously modified by STC SA2465WE). Issued 1/9/73.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA2634WE	Installation of three Litton LTN-72 inertial navigation systems. Issued 1/9/73.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-63F; T.C. 4A25	SA2957WE	Installation of separate differential oil pressure system and associated warning light indication. Issued 12/23/74.	WE	36100	The Flying Tiger Line, Inc. 7401 World Way West Los Angeles Int'l Airport Los Angeles, CA 90009
DC-8-63F; T.C. 4A25	SA3092WE	Installation of Satco, Inc. cargo pallet assembly, P/N 31250-521. Issued 9/3/75.	WE	70250	Satco, Inc. 1509 East El Segundo Boulevard El Segundo, CA 90245
DC-8-63F; T.C. 4A25	SA3123WE	Installation of cargo container P/N 10-1000. Amended 4/19/76.	WE	25955	Container Development 2636 North Ontario Burbank, CA 91504
DC-8-63F; T.C. 4A25	SA3176WE	Installation of Litton Aero Products digital ground proximity warning system. Issued 4/21/76.	WE	51500	Litton Aero Products Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-8-63F; T.C. 4A25	SA4118WE	Installation of a Winters air stair in the aft passenger entry door. Issued 6/4/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
DC8-63F; T.C. 4A25	SA4119WE	Installation of a Winters air stairs in the forward passenger entry door. Issued 5/29/80.	WE	86680	Winters Aircraft Engineering Co. 16117 Vanowen Street Van Nuys, CA 91406
DC-9 Series; T.C. A6WE	SA333SO	Beverage bar.	SO	29234	Delta Air Lines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA335NW	Modified cabin interior kit. Issued 8/13/76.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
DC-9 Series; T.C. A6WE	ST399SO	Addition of underseat luggage restraint.	SO	73874	Southern Airways, Inc. Atlanta Airport Atlanta, GA 30320
DC-9 Series; T.C. A6WE	SA457CE	Lockheed Aircraft service 109D flight recorder relocated.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA508CE	Installation of Safe Flight P/N 1300-33 SCAT computer in lieu of P/N 1300-32.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA520CE	Installation of airborne engine vibration monitoring system.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA580EA	Installation of Collins Radio CIC Type 560F-3 area navigation system.	EA	31420	Eastern Airlines, Inc. 10 Rockefeller Plaza New York, NY 10020
DC-9 Series; T.C. A6WE	ST626SO	Removal of complete passenger accommodations; installation of cargo interior. Amended 5/13/69.	SO	34220	Fairchild Hiller Corporation Aircraft Service Division St. Augustine, FL 32084
DC-9 Series; T.C. A6WE	ST627SO	Installation of cargo accommodations. Amended 5/13/69.	EA	62028	Overseas National Airways JFK International Airport Jamaica, NY 11430
DC-9 Series; T.C. A6WE	SA640NW	Installation of deep interior rack kits. Issued 7/21/78.	NW	41625	Heath Tecna Corporation 19819 84th Avenue South Kent, WA 98031
DC-9 Series; T.C. A6WE	SA727NW	Delete L.H. galley, add coatroom, add 2 auxiliary galley units at forward left and right side of cabin. Issued 2/27/79.	NW	78672	TRAMCO, Inc. P.O. Box 1053 Renton, WA 98055

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9 Series; T.C. A6WE	SA730CE	Install altitude alerting system.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA752CE	Install Bendix gyro horizon, P/N 1978130-2, and Bendix inverter, P/N 1964771-2.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA829CE	Install Butler National Corporation flight recorder/communications interface unit. Issued May 1972.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9 Series; T.C. A6WE	SA1003SW	Modify 721B galley to 721B-1 and install.	SW	84250	Vought Aircraft Service Co. Div. of LTV Aerospace Corp. 4100 North Main Street Fort Worth, TX 76107
DC-9 Series; T.C. A6WE	SA1459WE	Interior configuration modification.	WE	16892	Bonanza Air Lines 3737 East Bonanza Way P.O. Box 12405 Phoenix, AZ 85034
DC-9 Series; T.C. A6WE	SA1784WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-9 Series; T.C. A6WE	SA1797WE	Installation of underseat baggage restraint system.	WE	08193	Air Logistics Corporation 3600 East Foothill Boulevard Pasadena, CA 91109
DC-9 Series; T.C. A6WE	SA2330WE	Installation of battery-powered emergency exit lighting in tail-cone. Issued 3/29/71.	WE	44266	International Inflatables Company 9880 San Fernando Road Pacoima, CA 91331
DC-9 Series; T.C. A6WE	SA2451SW	Marathon Battery Co. P/N 85-0050 six cell magnesium emergency light pack. Issued 4/20/77.	SW	54810	Marathon Battery Company 8301 Imperial Drive Waco, TX 76710
DC-9 Series; T.C. A6WE	SA2541WE	Installation of tail cone slide cover. Issued 6/2/72.	WE	44266	International Inflatables Company 7848 San Fernando Road Sun Valley, CA 91352
DC-9 Series; T.C. A6WE	SA3623WE	Installation of stretcher carrier P/N 2003. Issued 4/13/78.	WE	08205	Air Medic, Inc. 12517 Chandler Blvd. No. Hollywood, CA 91607
DC-9-10; T.C. A6WE	ST498SO	Modification of main landing gear brake stud. Issued 4/19/72.	SO	84470	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-8-10; T.C. A6WE	SA4200WE	Installation of a stall warning comparator system and AD 78-23-06 compliance for McDonnell Douglas DC-9-10 aircraft. Issued 7/25/80.	WE	78427	Texas International Airlines P.O. Box 12788 Houston, TX 77017
DC-9-10-20, -30, -40 Series; T.C. A6WE	ST699SO	Installation of International Inflatable Company Model 68090 emergency evacuation slide modified with Pan Avion valve assembly P/N 526-43. Issued 11/9/71.	SO	62384	Pan Avion P.O. Box 213 Miami, FL 33101
DC-9-10, -20, -30, -40 Series; T.C. A6WE	SA2223WE	Installation of door mounted battery-powered emergency lights. Amended 5/6/71.	WE	44266	International Inflatables Company 9880 San Fernando Boulevard Pacoima, CA 91331
DC-9-10, -30; T.C. A6WE	ST870SO	Installation of Collins FPC 75 ground proximity warning system. Issued 11/25/75.	SO	73874	Southern Airways, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-10, -30; T.C. A6WE	SA1177CE	Installation of Collins FPC-75 ground proximity warning system. Amended 7/11/79.	CE	62030	Ozark Air Lines, Inc. St. Louis International Airport Lambert Field St. Louis, MO 63145
DC-9-10, -30; T.C. A6WE	SA3097WE	Installation of Collins Radio Co. Model FPC-75 ground proximity warning system. Amended 4/6/76.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-11, -12, -13, -14, -15, -31, -32; T.C. A6WE	ST735SO	Installation of protective rigid cover over tail cone emergency evacuation slide (installation of International Inflatables Model 68090 slide per STC ST676SO or equivalent required with this STC). Issued 12/4/72.	SO	62384	Pan Avion 7291 N.W. 43rd Street Miami, FL 33166

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9-11, -12, -13, -14, -15, -15F; T.C. A6WE	SA2233WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-9-11, -12, -13, -14, -15, -15F, -21; T.C. A6WE	SA2503WE	Installation of replacement cooling turbine nozzle assembly. Issued 4/20/72.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91503
DC-9-11, -12, -13, -14, -15, -15F; T.C. A6WE	SA2645WE	Installation of dual Litton LTN-51 inertial navigation system. Issued 2/2/73.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
DC-9-11, -14, -15F, -31; T.C. A6WE	SA1933WE	Installation of under seat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-11, -31; T.C. A6WE	SA1195EA	Installation of Magee Plastics passenger service units (PSU's) in lieu of original manufacturer's PSU's. Issued 5/19/80.	EA	54200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15237
DC-9-14, -15; T.C. A6WE	SA527CE	Replace Bendix navigation and control type 17248 directional gyros with Bendix type 17265.	CE	79400	Trans World Airlines, Inc. Mid-Continent Int'l Airport Kansas City, MO 64153
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2981WE	Modification of No. 1 galley, Hughes Airwest P/N RW2530045 or Nordskog P/N 742A Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-14, -15, -15F, -31, -32; T.C. A6WE	SA2982WE	Modification of No. 2 galley, Hughes Airwest P/N RW2530051 or Nordskog P/N 645A. Issued 1/27/75.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-14, -31; T.C. A6WE	ST676SO	Installation of International Inflatables Company emergency evacuation slide, Model 68090, at tail cone exit.	SO	31420	Eastern Airlines, Inc. International Airport Miami, FL 33148
DC-9-14, -9-31, -9-32; T.C. A6WE	SA2765WE	Installation of altitude alerting and reporting capabilities. Issued 10/10/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15; T.C. A6WE	SA1511CE	Increase the passenger capacity from 83 to 90. Issued 9/6/79.	CE	79400	Trans World Airlines, Inc. Kansas City Int'l Airport Kansas City, MO 64153
DC-9-15; T.C. A6WE	SA1728WE	Installation of Bendix Model DRA 12 Doppler navigation system and relocation of ATC transponder antenna and marker beacon antenna. Amended 2/6/70.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
DC-9-15; T.C. A6WE	SA2587WE	Installation of auxiliary fuselage fuel tanks in forward and aft cargo compartments. Amended 3/18/75.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Burbank, CA 91504
DC-9-15; T.C. A6WE	SA2764WE	Altitude alerting and reporting capabilities are provided by installation of Harowe P/N 2031-01-1 altitude alert system, replacement of captain's barometric altimeter with a Harowe P/N 2050-01-1 servo actuated altimeter and two existing air data computers are replaced by Sperry P/N 2587400-176 air data computer. Issued 9/28/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15; T.C. A6WE	SA3051WE	Change seating configuration to 80 economy class, and installation of two auxiliary galleys at fuselage stations 764.5 to 784. Issued 5/29/75.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90846
DC-9-15F; T.C. A6WE	SA2028WE	Replacement of V.H.F. 7533483 SAU polyethylene dielectric coaxial cables with Type RG115 A/U PTFE dielectric coaxial cables and addition of head-shield between APU exhaust shroud and wiring conduits.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9-15F; T.C. A6WE	SA2763WE	The captain's altimeter is replaced by Harowe P/N 2050-01-1 servo actuated altimeter and existing altitude alert system is replaced by Harowe P/N 2031-01-1 altitude alert system. Issued 9/19/73.	WE	43340	Hughes Airwest San Francisco Int'l Airport San Francisco, CA 94119
DC-9-15F; T.C. A6WE	SA2788WE	Installation of galley assembly, P/N PW2530045. Issued 12/6/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA2789WE	Installation of Hughes Airwest galley assembly, P/N PW2530051. Issued 12/10/73.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-15F; T.C. A6WE	SA3558WE	Installation of 535-gallon auxiliary fuel tank system in forward cargo compartment. Issued 3/8/78.	WE	06750	Aircraft Tank Service 10201 Cohasset Street Burbank, CA 91504
DC-9-21, -31, -32F (USAF C-9A), -32, -33F, -41; T.C. A6WE	SA962EA	Addition of airspeed select function to speed command/autothrottle system. Amended 8/6/80.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
DC-9-21, -31, -32, -32F, -33F, -41, -51; T.C. A6WE	SA2212WE	Installation of emblem lights mounted on trailing edge of wing tips. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-9 Series 30; T.C. A6WE	SA130GL	Installation of Systron-Donner Model 8160-20-P10 angular rate sensor in lieu of presently installed rate gyros in pitch-axis computer, roll-axis computer, and stability augmentation computers. Issued 7/23/76.	GL	61625	North Central Airlines, Inc. 7500 Northliner Drive Minneapolis, MN 55450
DC-9-30; T.C. A6WE	SA3642WE	A speed comman system, safe flight P/N 1312-25B installed. Issued 5/16/78.	WE	43340	Hughes Airwest P.O. Box 2966 Phoenix, AZ 85036
DC-9-30, -9-31; T.C. A6WE	SA294NW	Interior arrangement, coatroom installation. Issued 5/14/76.	NW	48532	KME Manufacturing 800 North 6th Street Renton, WA 98055
DC-9 Series 30; T.C. A6WE	ST499SO	Modification of main landing gear brake stud. Issued 4/19/72.	SO	84770	W.C. Corporation 420 Armour Circle, N.E. Atlanta, GA 30324
DC-9 Series 30; T.C. A6WE	SA1658WE	Installation of Airborne vibration monitoring system equipment.	WE	25917	Consolidated Electrodynamics Corp. Transducer Products Division 1400 South Shamrock Avenue Morovia, CA 91016
DC-9 Series 30; T.C. A6WE	SA2473WE	Installation of AiResearch cooling turbine P/N 204950-5-3 in lieu of P/N 204950-5-2. Issued 2/18/72.	WE	07505	AiResearch Manufacturing Company Division of Garrett Corporation 9851 Sepulveda Boulevard Los Angeles, CA 90009
DC-9 Series 30; T.C. A6WE	SA2803WE	Replacement of splined end on DC-9 nose gear cylinder, Douglas P/N 5920602. Amended 2/1/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9 Series 30; T.C. A6WE	SA2805WE	Replacement of splined end of DC-9 nose gear cylinder. Issued 1/18/74.	WE	75000	Stellar Hydraulics Company 11310 Sherman Way Sun Valley, CA 91352
DC-9-30; T.C. A6WE	SA3887WE	Installation of two Howell Model H900 solid state exhaust gas temperature indicators. Issued 3/29/79.	WE	43340	Hughes Airwest 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-30; T.C. A6WE	SA4059WE	Installation of ground proximity warning system (GPWS) and altitude alert system. Issued 12/13/79.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
DC-9-30, -32F, -33F, -51; T.C. A6WE	SA3115WE	Installation of Collins ground proximity warning system. Amended 4/7/76.	PC	41260	Hawaiian Airlines Honolulu International Airport Honolulu, HI 96820
DC-9-30, -50; T.C. A6WE	SA84GL	Install Bendix GPW-83 ground proximity warning system. Amended 8/10/76.	GL	61625	North Central Airlines 7500 Northliner Drive Minneapolis, MN 55450

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9-31; T.C. A6WE	ST464SO	Installation of Decca IIB 06 omnitrac area navigation system. Operations will not be predicated on use of vertical guidance information of area navigation system. Amended 6/29/71.	SO	31420	Eastern Airlines International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	ST557SO	Installation of 99 passenger interior arrangement. Issued 10/6/73.	SO	31420	Eastern Airlines International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	SA785SO	Installation of interior configuration to accommodate 12 first class and 95 tourist class passengers. Amended 1/16/81.	SO	31420	Eastern Airlines Miami International Airport Miami, FL 33148
DC-9-31; T.C. A6WE	SA878EA	Installation of SFENA standby horizon indicating system. Reissued 12/22/75.	CE	62030	Ozark Air Lines Box 10007, Lambert Field St. Louis, MO 63145
DC-9-31; T.C. A6WE	SA1188EA	Installation of replacement window panels. Amended 8/8/80.	EA	54200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15231
DC-9-31, -32; T.C. A6WE	SA1003NW	CDP 1-11 interior retrofit kit. Issued 8/6/80.	NW	41625	Heath Tecna Corporation 19819 84th Avenue, S. Kent, WA 98031
DC-9-31, -32; T.C. A6WE	SA3888WE	Installation of an auxiliary fuel tank system in the forward baggage compartment. Amended 5/25/79.	WE	43340	Hughes Air West, Inc. 3737 East Bonanza Way P.O. Box 2966 Phoenix, AZ 85036
DC-9-31, -32, -32F, -33F, -41; T.C. A6WE	SA2502WE	Installation of replacement cooling turbine nozzle assembly. Amended 11/13/73.	WE	13750	Aviation Power Supply, Inc. Toro Division 3111 Kenwood Street Burbank, CA 91504
DC-9-31, -9-51; T.C. A6WE	SA1019EA	Installation of Collins Model FPC-75 ground proximity warning system. Amended 8/5/77.	EA	09520	Allegheny Airlines, Inc. Greater Pittsburgh Int'l Airport Pittsburgh, PA 15231
DC-9-31/-51; T.C. A6WE	SA3455WE	Installation of tourist and first class interiors. Amended 10/12/79.	SO	31420	Eastern Air Lines, Inc. International Airport Miami, FL 33148
DC-9-32; T.C. A6WE	ST956SO	Installation of Bendix ground proximity warning system. Issued 10/21/75.	SO	29234	Delta Air Lines Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	ST921SO	Fabrication and installation of baggage stowage rack, P/N 325100. Issued 1/28/77.	SO	29234	Delta Airlines, Inc. Hartsfield Atlanta Int'l Airport Atlanta, GA 30320
DC-9-32; T.C. A6WE	SA1895WE	Installation of a second observer seat in flight crew compartment.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-9-32; T.C. A6WE	SA2106WE	Modification consists of interior arrangement, various passenger entertainment systems and avionics equipment. Reissued 8/20/73.	GL	64730	Playboy Enterprises, Inc. 919 North Michigan Avenue Chicago, IL 60611
DC-9-32 (VC-9C), DC-9-32F (C-9A); T.C. A6WE	ST248GL	Installation of Collins Model FPC flight profile comparator, P/N 622-2615-500, and Harowe barometric altitude rate computer, P/N 4030-03-1. Amended 7/19/78.	GL	77280	Systems Research Laboratories, Inc. 2800 Indian Ripple Road Dayton, OH 45440
DC-9-32F; T.C. A6WE	SA1043EA	Installation of structural provisions for executive interior. Issued 11/24/76.	EA	12500	Atlantic Aviation Corporation Box 1709 Wilmington, DE 19899
DC-9-32F; T.C. A6WE	SA2598WE	Installation of passenger pallet system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA697EA	Installation of (4) Aerojet-General Corp. 15 KS-1000-A1 or Bristol Aerospace (1969) Ltd. 15 KS-1000-A1(B) rocket engines and fairings. Amended 2/29/72.	WE	52995	McDonnell Douglas Corporation 3855 Lakewood Boulevard Long Beach, CA 90801
DC-9-32F, -9-33F; T.C. A6WE	SA1193EA	Installation of ceiling panel kits. Issued 4/16/80.	EA	12500	Atlantic Aviation Corporation P.O. Box 15000 Wilmington, DE 19850

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-9-32F, -33F; T.C. A6WE	SA1970WE	Installation of 88 x 108-inch cargo pallet P/N 24545-51, -52, or -53 with net P/N 24550-51, -52, or -53 and 88 x 54-inch cargo pallet P/N 24546-51, -52, or -53 with net P/N 24551-51 or -52. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2021WE	Installation of various cargo pallets and nets (per Tridair "Loading Instructions Drawing No. 40814). Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-9-32F, -33F; T.C. A6WE	SA2092WE	Installation of Heath 54 x 88-inch cargo pallet AC-10528-1 and net AC-10657-101. Reissued 1/6/71.	NW	81625	Heath Tecna Corporation Plastics Division 19819 - 84th Avenue South Kent, WA 98031
DC-9-81; T.C. A6WE	SA3366WE	Modification of cabin interior. Installation includes all or part of the following overhead storage compartments, sculptured ceiling and sidewall panels, flourescent cabin lighting, standby lighting, emergency lighting, and an overwing exit locator sign. Amended 3/31/78.	WE	82150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-9-51; T.C. A6WE	SA779SO	Installation of accommodations for 12 first class and 108 tourist class passengers. Issued 2/1/80.	SO	31420	Eastern Air Lines, Inc. Miami International Airport Miami, FL 33148
DC-9-51; T.C. A6WE	SA3660WE	Installation of Carrier Aircraft coat closet Model EAL951-1. Issued 6/6/78.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-9-51; T.C. A6WE	SA3800WE	Installation of a 130 passenger seating arrangement, two galleys, and associated water drain mast. Issued 12/6/78.	WE	03116	Aerotron Aircraft Radio, Inc. 3521 East Spring Street Long Beach, CA 90806
DC-9-51; T.C. A6WE	SA4002SW	In-place cargo system. Issued 7/31/79.	SW	08250	Air Cargo Equipment Corporation P.O. Box 15630 Tulsa, OK 74112
DC-9, DC-10-30; T.C. A6WE	SA1068EA	Replacement of Fairchild Burns seats by Magee Plastics Co. seat trim kit P/N 67203. Issued 2/14/78.	EA	53200	Magee Plastics Company 535 Rochester Road Pittsburgh, PA 15237
DC-10; T.C. A22WE	SA285NW	Installation of Trans Com System. Issued 4/15/76.	NW	76800	Sundstrand Data Control Overlake Industrial Park Redmond, WA 98052
DC-10; T.C. A22WE	SA419NW	Class divider installation. Issued 3/10/77.	NW	48532	KME Manufacturing 800 North 6th Street Renton, WA 98055
DC-10; T.C. A22WE	SA713NW	Installation of class divider. Issued 1/30/79.	NW	48532	KME Manufacturing Company The Commons Building 1200 112th N.E. Bellevue, WA 98004
DC-10; T.C. A22WE	SA3892WE	Installation of Stowe Corp. service carts. Issued 3/23/79.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-10; T.C. A22WE	SA2611WE	Installation of three Litton LTN-51 inertial navigation systems, an inertial navigation switching unit and two Sperry horizontal situation indicators. Amended 3/5/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10;	SA2816WE	Modification of DC-10-10 aircraft for the installation of spacer pallets. Issued 2/8/74.	WE	80500	United Air Lines, Inc. Engineering Department San Francisco, CA 94128
DC-10-10; T.C. A22WE	SA2836WE-D	Installation of Bell and Howell video entertainment system in A, B and C zones of passenger cabin. Issued 5/1/75.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-10-10: T.C. A22WE	SA2837WE-D	Install new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 12/9/77.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA2888WE	Installation of three Litton LTN-51 or LTN-72 inertial navigation systems. Issued 2/28/75.	WE	51500	Litton Systems, Inc. Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-10: T.C. A22WE	SA3025WE-D	Installation of refrigeration cooling for DME interrogators. Amended 3/12/76.	WE	80500	United Air Lines, Inc. San Francisco Maintenance Base San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA3031WE-D	Installation of four additional serving cart tie downs on main deck. Amended 9/13/78.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA3035WE-D	Install slide-raft assembly at each LH and RH cabin door exit. Issued 2/17/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA3036WE-D	Modifies aircraft to install dual Delco C-IV inertial navigation systems (INS) for attitude and direction reference, navigation, and autopilot steering. Issued 3/22/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA3127WE	Installation of first class passenger seats incorporating unitized oxygen systems. Issued 12/11/75.	WE	85126	Western Airlines, Inc. 6060 AVion Drive Los Angeles, CA 90052
DC-10-10: T.C. A22WE	SA3358WE-D	Reduces first class seating to 16 seat places, installs 9-across coach seating - 243 seat places, installs class divider, lounge table, PSF, and closets in zone A, closet in zone C. Issued 11/15/77.	WE	80500	United Airlines, Inc. Maintenance Operations Center San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA3510WE	Replace primary thrust reverser with conical nozzle and plug; modify pylon aft fairing; and remove upper and lower actuators and drive cables. Issued 10/31/77.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012
DC-10-10: T.C. A22WE	SA3580WE-D	Installation of ARINC communications addressing and reporting system (ACARS). Issued 8/6/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA3591WE-D	Installs new lavatory module/bustle assembly at door 2 RH/LH, underfloor plumbing and related systems, modified main deck floor support structure, external service panel. Amended 9/11/79.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA3696WE	Training requirements, special limitations, and installation of required provisions, including communications and equipment to permit occupancy of the lower galley during taxi. Issued 7/12/78.	WE	80500	United Airlines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA3815WE	Installation of a video projection system. Amended 2/28/79.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10: T.C. A22WE	SA3841WE-D	Installation of a UHF radio telephone system. Issued 6/9/80.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10: T.C. A22WE	SA4041WE	Installation of Litton LTN-211 Omega navigation system. Issued 11/30/79.	WE	85126	Western Airlines, Inc. 6060 Avion Drive Los Angeles, CA 90052
DC-10-10: T.C. A22WE	SA4126WE	Installation of Stowe Corp. entree cart, P/N 10078. Issued 8/9/80.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-10-10, -10-10F; T.C. A22WE	SA2524WE	Installation of lounge seats, four-place divan, I-shaped bar, and cocktail tables. Amended 3/8/74.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2770WE	Installation of visual entertainment system. Issued 10/2/73.	WE	15375	Bell & Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10, -10-10F; T.C. A22WE	SA2924WE	Installation of wheeled refrigerated module, P/N 73011000. Issued 8/27/74.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-10F; T.C. A22WE	SA2948WE	Installation of buffet/bar and bustle assembly. Issued 1/22/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA2985WE	Modification of installed G1 and G1A galleys (Dale P/Ns CAG-11000, CF-10-1, CAG-10000, CF-7000). Issued 1/22/75.	WE	25970	Continental Airlines 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA2987WE	Installation of cabin lounge swivel seats and adjustable table with removable top. Issued 1/23/75.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3014WE	Installation of floor game table assembly. Amended 1/20/76.	WE	15375	Bell & Howell Company 360 Sierra Madre Villa Pasadena, CA 91100
DC-10-10, -10-10F; T.C. A22WE	SA3212WE	Installation of forward cargo compartment positive vent sump drain. Issued 6/15/76.	WE	25970	Continental Airlines, Inc. Los Angeles Int'l Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3367WE	Installation of nine-abreast coach seating and associated oxygen and electrical system modification. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3368WE	Installation of eight-abreast coach seating in forward cabin behind the first class section, and associated oxygen and electrical system modifications. Issued 3/10/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3827WE	Installation of folding leaf table. Issued 1/31/79.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
DC-10-10, -10-10F; T.C. A22WE	SA3843WE	Installation of Nordskog Ind. galley 1-419. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3844WE	Installation of composites, unlimited coat closet, P/N 225-46103. Amended 7/11/79.	WE	25970	Continental Airlines, Inc. International Aicport Los Angeles, CA 90009
DC10-10, -10-10F; T.C. A22WE	SA3845WE	Installation of buffet/bar unit, P/N 2142396. Amended 7/11/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
DC-10-10, -10-10F; T.C. A22WE	SA3847WE	Installation of a new lounge and first class accommodations. Amended 7/12/79.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3848WE	Installation of HITCO refrigerated galley module. Amended 3/16/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249
DC-10-10, -10-10F; T.C. A22WE	SA3875WE	Installation of Continental Air Lines flight attendant seat, P/N 225-46317. Issued 3/16/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA3937WE	Installation of HITCO storage galley module. Issued 5/18/79.	WE	42150	HITCO Defense Products Division 1600 West 135th Street Gardena, CA 90249.
DC-10-10, -10-10F; T.C. A22WE	SA3996WE	Installation of Litton LTN-2110NS. Issued 7/18/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-10-10, -10-10F: T.C. A22WE	SA4058WE	Installation of folding leaf table. Issued 11/8/79.	WE	07500	AiResearch Aviation Company 19201 Susana Road Compton, CA 90221
DC-10-10, -10-10F: T.C. A22WE	SA4122WE	Installation of aluminum cabin window plug assembly to replace outer acrylic cabin window pane. Issued 3/24/80.	WE	25970	Continental Airlines, Inc. 7300 World Way West Los Angeles, CA 90009
DC-10-10, -10-10F; T.C. A22WE	SA4158WE	Installation of Fairchild beverage cart model 79067000. Issued 6/6/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3432WE	Installation of fire/overheat detection system. Amended 2/14/78.	WE	77300	Systron Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10F, -10-30, -10-30F; T.C. A22WE	SA3626WE	Revision of DC-10 fire overheat detection system to allow intermixing of Systron-Donner fire detectors with Edison detectors in the fan, core, and pylon sections of the CF6 engines. Issued 4/11/78.	WE	77300	Systron-Donner Corporation Safety Systems Division 1440 - 4th Street Berkeley, CA 94710
DC-10-10, -10-10F, -10-30, -10-30F, -10-40; T.C. A22WE	SA4130WE	Installation of cabin window plug assembly. Issued 4/21/80.	WE	32760	Edwards Enterprises 230 Constitution Drive Menlo Park, CA 94025
DC-10-10, -10-10CF; T.C. A22WE	SA3407WE	Installation of Termer Apparatebau GMPP beverage cart No. L15701. Issued 5/20/77.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 91406
DC-10-10, -10-30; T.C. A22WE	SA776SO	Installation of SICMA food tray stowage carts. Amended 3/14/80.	SO	71600	SICMA Aero Seats, Inc. 6929 N.W. 46th Street Miami, FL 33166
DC-10-10, -10-30; T.C. A22WE	ST734SO	Installation of NAL Val-Pack coat-room, P/N 10621-1. Amended 3/30/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Miami, FL 33159
DC-10-10, -10-30; T.C. A22WE	SA2853WE	Retractable tiedown assemblies. Amended 3/23/78.	WE	48550	H. Koch & Sons Koch Road Corte Madera, CA 94925
DC-10-10, -10-30; T.C. A22WE	SA3067WE	Installation of lower lobe food service modules, P/Ns 818720, 820130, 820140, 820150. Issued 7/24/75.	WE	84900	Weber Aircraft 2820 Ontario Street Burbank, CA 91510
DC-10-10, -10-30; T.C. A22WE	SA4134WE	Installation of an ARINC communication addressing and reporting system (ACARS) Issued 6/13/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-10, -10-30; -10-30F: T.C. A22WE	SA2395WE	Installation of coffee bar cart, P/N 801000. Amended 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2774WE	Installation of wing tip mounted emblem lights. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
DC-10-10, -10-30, -10-30F, -10-40; T.C. A22WE	SA2893WE	Installation of Hermes LD-3 Kool-flite refrigerated cargo container. Issued 6/12/74.	WE	42120	Hermes Enterprises Koolflite Service 1704-C West 134th Street Gardena, CA 90249
DC-10-10, -10-30, -10-40; T.C. A22WE	SA930EA	Installation of Inflight Motion Pictures, Inc. projection unit assembly DC-10 16mm Tri-Jet system 10300 or light weight Tri-Jet projection system, DC-10 P/N 10307. Amended 9/14/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA947EA	Installation of Inflight Motion Pictures, Inc. screen assemblies. Amended 8/11/76.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, New York 11434
DC-10-10, -10-30, -10-40; T.C. A22WE	SA969EA	Installation of Inflight movie projection assembly P/N 10270, Super 8mm IMPAK system. Issued 11/21/73.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434.
DC-10-10, -10-30, -10-40; T.C. A22WE	SA990EA	Installation of 16mm projection unit assembly and center stowage bins, P/N 10310. Issued 10/3/74.	EA	44000	Inflight Motion Pictures, Inc. 175-28 148th Avenue Jamaica, NY 11434

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-10-10, -10-30, -10-40; T.C. A22WE	SA3335WE	Installation of stretcher carrier AM2003. Issued 2/8/77.	WE	08205	Air Medic, Inc. 12517 Chandler Boulevard North Hollywood, CA 91607
DC-10-10, -10-30F; T.C. A22WE	SA2817WE-D	Installation of provisions for ground proximity warning system. Amended 6/26/75.	WE	80500	United Air Lines, Inc. International Airport San Francisco, CA 94128
DC-10-10, -10-30F; T.C. A22WE	SA2830WE-D	Installation of Collins FPC-75 ground proximity warning system computer. Amended 3/30/76.	WE	80500	United Air Lines, Inc. San Francisco Int'l Airport San Francisco, CA 94128
DC-10-10F; T.C. A22WE	SA4006WE	Installation of a 3-place courier seat. Issued 7/31/79.	WE	25970	Continental Air Lines, Inc. International Airport Los Angeles, CA 90009
DC-10-10F; T.C. A22WE	SA4156WE	Installation of a two-place courier seat. Issued 5/12/80.	WE	25970	Continental Airlines, Inc. International Airport Los Angeles, CA 90009
DC-10-30; T.C. A22WE	SA2663WE	Installation of Trans Com movie and projector entertainment system, Model 2420. Issued 3/19/73.	WE	76800	Trans Com A Division of Sundstrand Data Control, Inc. 3100 Pullman Avenue Costa Mesa, CA 92626
DC-10-30; T.C. A22WE	SA2684WE	Installation of Tridair Industries main deck baggage container system. Amended 5/16/75.	WE	17740	Brooks & Perkins Brownline Division 2950 Lomita Boulevard Torrance, CA 90505
DC-10-30; T.C. A22WE	SA2707WE	Installation of cabin lounge seats, folding tables, cart stowage unit, and class divider partition. Issued 6/6/73.	SO	61220	National Airlines, Inc. P.O. Box 2055 Airport Mail Facility Miami, FL 33159
DC-10-30; T.C. A22WE	SA3194WE	Installation of Airborne video-cassette system. Issued 5/12/76.	WE	15375	Bell & Howell Company Airline Products Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA3384WE	Installation of dual Litton LTN-72R INS/RNAV navigation systems. Issued 2/23/77.	WE	51500	Litton Aero Products Division 21050 Burbank Boulevard Woodland Hills, CA 91364
DC-10-30; T.C. A22WE	SA3393WE	Installation of Airborne Video-cassette system.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA3569WE	Installation of aircraft video system. Amended 6/5/79.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA4010WE	Installation of video projection system. Issued 10/5/79.	WE	15375	Bell and Howell Company 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-10; T.C. A22WE	SA4070WE	A video projection system is installed. Issued 6/25/80.	WE	15375	Bell and Howell Company AVICOM Division 360 Sierra Madre Villa Pasadena, CA 91109
DC-10-30; T.C. A22WE	SA4186WE	Installation of Stowe Corp. liquor cart, P/N 10051-3. Issued 7/22/80.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-30, -10-30F; T.C. A22WE	SA2775WE	Installation of Fairchild Stratos tray carrier rack assembly. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2777WE	Installation of service center (G 1) and coffee bar G-2 assemblies. Reissued 3/10/75.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach, CA 90807
DC-10-30, -10-30F; T.C. A22WE	SA2780WE	Installation of serving cart pallets, P/N 989200 and 990100. Issued 11/1/73.	WE	34220	Fairchild Industries, Inc. Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-30F; T.C. A22WE	SA2938WE	Carts and pallet assembly installation. Issued 10/9/74.	WE	28560	Dale Engineering & Development, Inc. 12243 Branford Street Sun Valley, CA 91352
DC-10-30F; T.C. A22WE	SA2949WE	Installation of passenger entertainment/service system. Amended 12/6/74.	WE	33223	Electronic Engineering Company of California 1441 East Chestnut Avenue Santa Ana, CA 92701

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
DC-10-30F: T.C. A22WE	SA2950WE	Installation of ballast assembly. Issued 11/18/74.	WE	79200	Trans International Airlines Oakland International Airport Oakland, CA 94614
DC-10-30F: T.C. A22WE	SA3128WE	Installation of 376 passenger interior arrangement and associated oxygen system modifications. Issued 12/15/75.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-30F: T.C. A22WE	SA3137WE	Installation of courier seat module assembly. Issued 1/21/76.	WE	79200	Trans International Airlines International Airport Oakland, CA 94614
DC-10-30F: T.C. A22WE	SA4192WE	Installation of DRIESSEN meal cart in lieu of Nordskag carts P/N's 50193 and 50194. Issued 7/2/80.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
DC-10-30F: T.C. A22WE	SA4197WE	Installation of first class interior arrangement. Issued 7/25/80.	WE	87450	World Airways, Inc. Oakland International Airport Oakland, CA 94614
DC-10-40: T.C. A22WE	SA88GL	Installation of Bendix GPW-83 ground proximity warning systems. Issued 9/29/75.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40: T.C. A22WE	SA372GL	Installation of Honeywell P/N HG280BD80 digital airdata computer in the number three position per NWA project 1-34-40300 in place of the Honeywell P/N HG280D5 presently used in this position for data collection purposes only. Issued 10/26/79.	GL	61700	Northwest Airlines, Inc. Minneapolis/St. Paul Int'l Airport St. Paul, MN 55111
DC-10-40: T.C. A22WE	SA2782WE	Installation of wheeled refrigerated module P/N 73014000-101. Issued 11/1/73.	WE	34220	Fairchild Stratos Division 1800 Rosecrans Avenue Manhattan Beach, CA 90266
DC-10-40: T.C. A22WE	SA4186WE	Installation of Stowe Corp. liquor cart, P/N 10051-3. Amended 8/18/80.	WE	75900	Stowe Corporation 602 North Cypress Street Orange, CA 92667
DC-10-40, -10-40F: T.C. A22WE	SA3139WE	Installation of wing and tail engine pods. Amended 3/15/79.	WE	69000	Rohr Industries, Inc. P.O. Box 878 Chula Vista, CA 92012

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MESSERSCHMITT - BOLKOW - BLOHM - GMBH

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BO-105A, BO-105C; T.C. H3EU	SA26RM	Installation of JB Systems air-conditioning system. Issued 6/14/74.	RM	45750	JB Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
BO-105A, BO-105C; T.C. H3EU	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
BO-105A, BO-105C; T.C. H3EU	SH978EA	Installation of Consolidated Instrument Co., Inc. battery temperature alert system, Models B206-TA180 or B206D-TA180. Issued 4/8/74.	EA	25920	Consolidated Instrument Company Teterboro Airport Teterboro, NJ 07608
BO-105A, BO-105C, BO-105S; T.C. H3EU	SH479GL	Installation of Ni-Cad kit No. 101661 engine lubrication system scavenge filter. Issued 12/16/80.	GL	61546	Ni-Cad, Inc. 24800 U.S. 20 South Bend, IN 46628
BO-105A, BO-105C, BO-105S; T.C. H3EU	SH1065EA	Installation of Devore tail rotor floodlight on upper surfaces of horizontal stabilizer. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
BO-105C; T.C. H3EU	SH218NW	Installation and maintenance of Allison 250-C20 engine equipment with Bendix fuel control system. Issued 9/10/75.	NW	98124	The Boeing Company P.O. Box 3707 Seattle, WA 98124
BO-105C; T.C. H3EU	SH239WE	Installation of Chandler Evans (CECO) Model 104900-A3-A2 fuel controllers and Model 104500-A governors. Issued 6/11/79.	WE	08353	Air Services International 7300 East Evans Drive Scottsdale, AZ 85026
BO-105C; T.C. H3EU	SH971EA	Installation of cabin door post and door latching mechanism modification Kit No. SK212-10415 (Kit Nos. 101 and 102 or 201 and 202). Reissued 7/11/80.	EA	56832	MBB Helicopter Corporation Weston Way, P.O. Box 514 West Chester, PA 19380
BO-105C; T.C. H3EU	SH1025EA	Installation of ten inch cabin extension, modification of cabin doors, relocation of battery and structural modification of tail-boom to fuselage splice. Amended 1/9/78.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1031EA	Installation of AiResearch Manufacturing Co. environmental control unit, P/N 2200850-1 (Carson P/N C-105-20-5000-29). Reissued 5/21/80.	EA	56833	MBB Helicopter Corporation Weston Way - P.O. Box 514 West Chester, PA 19380
BO-105C; T.C. H3EU	SH1081EA	Relocation of battery to a position just aft of No. 2 engine. Issued 10/12/76.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1069EA	Installation of cabin door post and door latch assembly in accordance with data. Issued 2/23/78.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
BO-105C, BO-105S; T.C. H3EU	SH1073EA	Installation of electric chip directors in main transmission and intermediate and tail rotor gear boxes. Amended 6/19/80.	EA	47790	Keystone Helicopter Corporation 1420 Phoenixville Pike West Chester, PA 19380
BO-105C, BO-105S; T.C. H3EU	SH1182EA	Installation of emergency float kit, F105-85189. Amended 12/19/80.	EA	56832	MBB Helicopter Corporation Weston Way - P.O. Box 1507 West Chester, PA 19380
BO-209-150 FV and RV, BO-209-150FF; T.C. A27EU	SA309EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred P. Puccinelli DEP 1-145 36 Bay Drive East Huntington, L.I., NY 11743

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BO-209-150 FV and RV, BO-209-150FF; T.C. A27EU	SA489EA	Installation of A.P.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MITSUBISHI AIRCRAFT INTERNATIONAL, INC.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
MU-2B, -2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, -40, -60; T.C. A10SW	SA1042SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638T series lead-acid type batteries. Issued 1/15/79.	SO	78054	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Atlanta, GA 30339
MU-2B, MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A10SW	SA1460CE	Installation of microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
MU-2B, -2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, -40, -60; T.C. A10SW	SA3524WE	Installation of vertical tail flood lights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
MU-2B-25, -2B-26, -2B-35, -2B-36; T.C. A10SW	SA304GL	Installation of Hartzell HC-B3TN-5C/T10178B-13Q propellers in lieu of HC-B3TN-5C/T10178B-11 or 11R propellers using original installation hardware and components. No installation data are required. Amended 12/29/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-25, -26, -26A, -35, -36, -36A, -40, -60; T.C. A10SW	SA478GL	Installation of Norton radome No. 3077X, configuration A; No. 3077X-2 or 3077X-10, configuration B. Issued 12/5/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309
MU-2B-26A, -36A; T.C. A10SW	SA218GL	Installation of oil filter access door. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-26A, -36A; T.C. A10SW	SA219GL	Installation of tip tank lights. Issued 2/1/78.	GL	07503	AiREsearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-26A, -36A; T.C. A10SW	SA220GL	Modification of forward windshield center divider. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-26A, -36A, -40, -60; T.C. A10SW	SA214GL	Installation of wing tip tank fuel dumping system. Amended 5/29/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-36A, -2B-60; T.C. A10SW	SA215GL	Installation of two 25-gallon auxiliary fuel tanks in nose section of main landing gear wheel fairings. Amended 12/26/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62707
MU-2B-36A; T.C. A10SW	SA216GL	Installation of right side fuselage window at station 6335. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-36A; T.C. A10SW	SA217GL	Installation of right side fuselage window at station 6897. Issued 2/1/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

MITSUBISHI HEAVY INDUSTRIES, LTD.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
MU-2B: T.C. A2PC	SA595EA	Installation of replacement radome, P/N 3077F.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company Aero Products Operations P.O. Box 1187 Akron, OH 44309
MU-2B: T.C. A2PC	SA633SW	Heading selector and Omni/ILS coupler for Minneapolis-Honeywell H-14 automatic pilot.	SW	60152	Mooney Southwest, Inc. P.O. Box 6127 Midland, TX 79701
MU-2B: T.C. A2PC	SA726SW	Heading select, pitch trim and VOR/ILS coupling modes to Honeywell H-14 autopilot.	SW	60152	Mooney Southwest, Inc. P.O. Box 6127 Midland, TX 79701
MU-2B: T.C. A2PC	SA747CE	Installation of AiResearch TPE331-1-151A engines. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B: T.C. A2PC	SA907SW	AiResearch TPE331-25AA engines.	SW	60150	Mooney Aircraft, Inc. Route 1, Box 544 San Angelo, TX 76901
MU-2B: T.C. A2PC	SA1310WE	M-4C automatic flight control system.	SO	15475	The Bendix Corporation P.O. Box 23430 Fort Lauderdale, FL 33309
MU-2B, MU-2B-10, MU-2B-15, MU-2B-20: T.C. A2PC	SA996SW	Move air conditioning unit 20-inches aft and enlarge luggage compartment.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, MU-2B-10, MU-2B-15, MU-2B-20: T.C. A2PC	SA1029SW	Additional pitot system.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, MU-2B-10, MU-1B-15, MU-2B-20: T.C. A2PC t+1	SA1045SW	Two-place side facing seat.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, MU-2B-10, MU-2B-15, MU-2B-20: T.C. A2PC	SA1048SW	Replacement of Mitsubishi seats.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35; T.C. A2PC	SA582SO	Installation of Bendix RNS-3400 area navigation system. Amended 2/12/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B, MU-2B-10, -15, -20, -30: T.C. A2PC	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
MU-2B, -10, -15, -20, -25, -30, -35; T.C. A2PC	SA1411SW	Emergency locator transmitter. Issued 12/30/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA39GL	Installation of tip tank lights. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA98GL	Installation of engine ignition cut-out override system. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA588EA	Installation of Norton radome, P/N 3077X, configuration A; 3077X-2 or 3077X-10 configuration B. Amended 12/5/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Division P.O. Box 350 Akron, OH 44309
MU-2B, 2B-10, -15, -20, -25, -26, -30, -35, -36: T.C. A2PC	SA880SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1587SW	Aerosonic altimeter P/N A35-MA-10L1 to replace McCleod altimeter. Issued 1/5/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
MU-2B, -2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA3490WE	Installation of fuel boost pump. Issued 9/23/77.	WE	26725	Hydro-Aire Division of the Crane Company 3000 Winona Avenue P.O. Box 7722 Burbank, CA 91510
MU-2B, MU-2B-10, -15, -20, -25, -26, -26A, -30, -35, -36, -36A, 40, 60; T.C. A2PC	SA3524WE	Installation of vertical tail flood lights on horizontal stabilizer. Amended 4/13/79.	WE	30000	DeVore Aviation Corporation 16160 Stagg Street Van Nuys, CA 91406
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA32GL	Installation of oil filler access door. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA38GL	Installation of electrically heated glass windshield on pilot's side of aircraft. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA43GL	Installation of wing tip tank fuel dumping system (93 gallon tip tanks only). Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25,, -26, -30, -35, -36; T.C. A2PC	SA58GL	Modification of forward windshield center divider. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -20, -25, -30, -35; T.C. A2PC	SA68GL	Installation of engine fuel drain return line. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-10, -15, -25, -26, -36; T.C. A2PC	SA250CE	Installation of Woodward electronic propeller synchrophaser system. Amended 8/26/74.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1596SW	Alternate oil pressure transmitter. Issued 1/5/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1729SW	Adding weight of 60 pounds for ramp operation. Issued 9/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901
MU-2B-10, -15, -20, -25, -26, -30, -35, -36; T.C. A2PC	SA1857SW	B.F. Goodrich type 25S de-ice boots. Issued 3/19/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-10,-20, -25, -26, -30, -35, -36; T.C. A2PC	SA2266SW	Fabrication and installation of wing panel flap actuator access. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-15, -20; T.C. A2PC	SA955SW	M4C automatic flight control.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-15, -20; T.C. A2PC	SA1354SW	Bendix manual electric trim system. Issued 7/27/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-15, -20; T.C. A2PC	SA1874SW	Battery temperature warning system. Issued 4/24/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20; T.C. A2PC	SA291GL	Installation of auxiliary fuel tank in aft baggage compartment. Issued 1/12/79.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62707
MU-2B-20; T.C. A2PC	SA1313SW	Interior installation. Issued 5/21/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20; T.C. A2PC	SA1492SW	Hartman series parallel battery relay. Issued 6/14/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25; T.C. A2PC	SA1488SW	Avionics support shelving. Issued 7/6/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25; T.C. A2PC	SA1762SW	Single PC-17 inverter. Issued 11/9/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
MU-2B-20, -25; T.C. A2PC	SA1775SW	Flight system AK391 and AK391FD consisting of Century IV autopilot and Century IV autopilot flight director with command electric trim and yaw damper with rudder trim. Issued 12/21/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
MU-2B-20, -25, -26; T.C. A2PC	SA561SO	Installation of Bendix M-4D automatic flight control system including optional yaw trim, optional manual electric pitch trim and optional flight director system. Amended 1/24/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-20, -25, -26, -30, -35, -36; T.C. A2PC	SA2238SW	Tip tanks lights. Issued 6/8/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35; T.C. A2PC	SA1489SW	Antennas. Issued 7/6/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35; T.C. A2PC	SA1805SW	Foxboro fuel flow signal conditioning unit PC-620. Issued 2/7/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -30, -35, -36; T.C. A2PC	SA1940SW	Goulton GB40 cell batteries. Issued 12/12/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -25, -35; T.C. A2PC	SA1776SW	Lear Siegler starter generator, P/N 23046-007M. Issued 1/4/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San angelo, TX 76901
MU-2B-20, -25, -35; T.C. A2PC	SA1814SW	Dual baro scale altimeter. Issued March 1974.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -30; T.C. A2PC	SA161GL	Install Garrett AiResearch TPE331-6-252M engines. Amended 6/15/77.	GL	07503	AiResearch Capitol Aviation Co. Capital Airport Springfield, IL 62705
MU-2B-20, -30; T.C. A2PC	SA1316SW	Series/parallel selector switch for battery start selection. Issued 5/26/71.	SW	60073	Mitsubishi Aircraft Int'l, INc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-20, -30; T.C. A2PC	SA1547SW	Dual PC-17 static inverters. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1465SW	Interior. Issued 8/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1541SW	King basic avionics package. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1546SW	Basic King avionics package. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1548SW	Area NAV KCN 610. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1549SW	AVQ-55 weather radar. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1564SW	Collins basic avionics package. Issued 12/15/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1628SW	RCA AVQ-21 weather radar. Issued 3/15/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1646SW	Sunair ASB-100 HF system. Issued 4/27/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1647SW	Sperry stars IVB flight director. Issued 4/27/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1710SW	Bendix RDR-1200 weathervision system. Issued 8/2/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
MU-2B-25; T.C. A2PC	SA1711SW	RCA AVQ-47 weather radar. Issued 8/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1733SW	Battery temperature warning system. Issued 9/21/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1752SW	Sperry AA-20 radio altimeter. Issued 10/29/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1817SW	Collins ALT-50 radar altimeter. Issued 3/6/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25; T.C. A2PC	SA1859SW	RDR-100 weather radar. Issued 3/26/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1793SW	Install Collins FDS-112 C/V flight director. Issued 11/20/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1818SW	Aerosonics encoding altimeter and alerter. Issued 9/13/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA1925SW	Basic King gold crown avionics. Issued 2/14/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26; T.C. A2PC	SA2268SW	Installation of #2 VHF comm antenna. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1892SW	Chart holder. Issued December 1974.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1912SW	Instrument panel modification. Issued 9/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1918SW	Cooling air inlet screen. Issued 10/15/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1928SW	Sperry GH-14 flight director. Issued 1/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1929SW	United Instruments encoding altimeter. Issued 1/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3808 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1964SW	Cooling air inlet modification. Issued 9/25/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA1990SW	Pressure relief overboard vent line and restrictor fitting to EPA fuel purge system. Issued 5/21/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2233SW	Rewiring of auto-manual air conditioning switch. Issued 8/15/75.	SW	60073	Mitsubishi Aircraft International P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2263SW	Modification of ECS mixing chamber. Issued 10/9/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A2PC	SA2487SW	Outside air temperature indicator. Issued 9/6/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -26, -35, -36; T.C. A10SW	SA3489WE	Installation of fuel boost pump. Issued 9/23/77.	WE	26725	Hydro-Aire Division of the Crane Company 3000 Winona Avenue P.O. Box 7722 Burbank, CA 91510
MU-2B-25, -35; T.C. A2PC	SA1614SW	IDC 570-24929-002 encoding altimeter; or Smith's WL-1350 AM/MS-1(-2) encoding altimeter. Issued 6/6/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1615SW	Encoding altimeter/alerting system. Issued 3/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. Box 3848 San Angelo, TX 76901

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
MU-2B-25, -35; T.C. A2PC	SA1627SW	Collins FDS-112B flight director system. Issued 5/25/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1703SW	5V light source. Issued 7/18/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1712SW	Oil pressure indicator. Issued 8/10/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1732SW	Kratos 124.102 torque indicator. Issued 9/19/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1736SW	Ametek oil pressure transmitter, P/N 935A-5002. Issued 10/3/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1751SW	Shoulder harness. Issued 10/30/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1764SW	Smith's 1400 encoding altimeter-alerter. Issued 11/16/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1778SW	R.C. Allen gyro. Issued 1/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1779SW	Kollsman dual Baro scale altimeter. Issued 1/10/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1781SW	Revised ground and air starting procedures with bleed air heat to orifice in fuel control. Issued 1/17/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1816SW	King flight phone. Issued 3/26/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-25, -35; T.C. A2PC	SA1872SW	Hamilton Standard temperature control system. Issued 4/22/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2315SW	Dual FDS-112B flight director system. Issued 5/21/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2316SW	ONTRAC II VLF system. Issued 5/14/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2317SW	Install IDC RAD/BAR encoding altimeter with altitude alerting. Issued 5/21/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26; T.C. A2PC	SA2342WE	Installation of Sperry AA-100 radar altimeter. Issued 9/2/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2208SW	Continuous ignition system. Issued 7/10/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2247SW	Oxygen cylinder, P/N 6350 420 00R. Issued 10/1/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2274SW	Heated windshield. Issued 3/18/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2295SW	Install alternate interstage turbine temperature indicator, P/N 935A-6012.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2314SW	Digital clock. Issued 5/20/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-26, -36; T.C. A2PC	SA2343SW	Alternate aileron trim actuator. Issued 8/5/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
MU-2B-30; T.C. A2PC	SA115GL	Install Garrett AiResearch TPE 331-6-251M (P/N 896160-1) engines. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30; T.C. A2PC	SA1069SW	Mooney AB1001, TSO C-39 seats.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1085SW	Air conditioning system.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1146SW	Interior installation. Issued 5/15/70.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1198SW	11-place interior. Issued 9/30/70.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1218SW	Radio racks. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1215SW	Modify instrument panel. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1216SW	Battery relocation. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1257SW	Seat arrangement and interior. Issued 2/17/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
t+1 MU-2B-30; T.C. A2PC	SA1266SW	Drawer type toilet and across the back baggage shelf. Issued 2/19/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1275SW	Modify air-conditioning system. Issued 3/12/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1295SW	Installation of stretch headliner. Issued 4/30/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1304SW	Portable two-place jump seat. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
MU-2B-30; T.C. A2PC	SA1309SW	Portable one-place jump seat. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 West, Meacham Field Fort Worth, TX 76106
MU-2B-30; T.C. A2PC	SA1317SW	Revised battery installation. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
MU-2B-30; T.C. A2PC	SA1324SW	Bendix manual electric trim system. Issued 6/10/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
MU-2B-30; T.C. A2PC	SA1448SW	Divan and one-place jump seat. Issued 3/21/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30; T.C. A2PC	SA1484SW	Hartman series-parallel battery relay. Issued 6/22/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA27GL	Installation of right side fuselage window at station 6335. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30, -35; T.C. A2PC	SA28GL	Installation of right side fuselage window at station 6897. Reissued 7/18/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-30, -35; T.C. A2PC	SA1180SW	Chair installation. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
MU-2B-30, -35; T.C. A2PC	SA1419SW	Replace Gulton GE40A or CA5 Sonotone batteries with type 4076 saft batteries. Issued 1/12/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA1443SW	Modify pilot and copilot seats. Issued 3/9/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA1456SW	Installation of antennas. Issued 5/12/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35; T.C. A2PC	SA1470SW	Avionics support shelving. Issued 5/16/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-30, -35, -36; T.C. A2PC	SA60GL	Installation of two 25-gallon auxiliary fuel tanks in nose section of main landing gear wheel fairings. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, IL 62705
MU-2B-35; T.C. A2PC	SA947CE	Installation of KFC-300 automatic flight control system (integrated flight director and autopilot). Amended 1/14/76.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
MU-2B-35; T.C. A2PC	SA1352SW	Interior installation. Issued 8/20/71.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1511SW	PC-17 600 VA main inverter and PC-17 standby inverter. Issued 11/2/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1542SW	King KNC 610 area navigation computer. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1543SW	Sperry RA-220 radar altimeter. Issued 11/10/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1544SW	AVO-55 weather radar. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1545SW	Sperry Stars IVB flight director. Issued 11/10/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1563SW	Bonzer radar altimeter TRN-71. Issued 12/21/72.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1616SW	Sperry AA-210 radar altimeter system. Issued 3/7/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1636SW	Collins ALT-50 radar altimeter system. Issued 3/6/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1641SW	Sperrry SPZ-200 autopilot and Stars IVC flight director system. Reissued 4/18/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1678SW	Smith's encoding altimeter and alerting system. Issued 6/14/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San ANgelo, TX 76901
MU-2B-35; T.C. A2PC	SA1693SW	Bendix M-4D autopilot system. Issued 6/28/73.	SW	60073	Mitsubishi Aircraft, Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1708SW	ASP 125P/SAC-69 HF Comm. Issued 7/31/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1750SW	Battery temperature warning system. Issued 10/30/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1765SW	RDR-1200 weather radar. Issued 11/16/73.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 SAn Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1784SW	Flite phone III. Issued 1/24/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
MU-2B-35; T.C. A2PC	SA1785SW	Collins FDS-112 C/V flight director. Issued 1/28/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1804SW	Installation of 110 V outlet and wiring. Issued 2/7/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1849SW	Dual ASB 100A high frequency radios. Issued 3/14/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35; T.C. A2PC	SA1851SW	Install -501 single encoding altimeter and alerter system. Issued 3/14/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1560SW	Avionics basic Collins package. Issued 3/21/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1561SW	AVQ-21 weather radar. Issued 12/20/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1941SW	Basic King gold crown avionics. Issued 12/13/74.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1944SW	Bendix RDR-140 weather radar. Issued 1/8/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA1954SW	Jump seat. Issued 5/8/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA2246SW	Inverter relocation in forward equipment shelves and windshield anti-icing system panel changes. Issued 10/1/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA2269SW	King KRA 405 radar altimeter. Issued 10/31/75.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36; T.C. A2PC	SA2427SW	Optional VHF #2 Comm antenna. Issued 3/11/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-35, -36, -36A; T.C. A2PC	SA2489SW	Addition of baggage compartment in main landing gear wheel pods. Issued 8/17/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2309SW	Install Sperry TR114B transponder. Issued 6/17/76.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2399SW	Installation of Primus-40 weather radar. Issued 2/2/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2413SW	Install AiResearch TPE331-5-252M engines and Hartzell Propeller HC-B4TN-5DL/LT10282B-5.3R. Issued 2/18/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901
MU-2B-36; T.C. A2PC	SA2414SW	Install Bendix RNS-3500 area NAV system. Issued 2/24/77.	SW	60073	Mitsubishi Aircraft Int'l, Inc. P.O. Box 3848 San Angelo, TX 76901

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M20C, E, F, G: T.C. 2A3	SA2207SW	NAV-FLITE II and B-5 flight control systems. Issued 7/23/75.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
M20C, E, F, G: T.C. 2A3	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, E, F, G: T.C. 2A3	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 5/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20C, M20E, M20F; T.C. 2A3	SA2654WE	Installation of Pathfinder P2A autopilot system. Amended 4/14/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20E/Super 21; T.C. 2A3	SA999CE	Installation of ERC battery monitor. Issued March 1974.	CE	33229	Electronic Research Company P.O. Box 913 Shawnee Mission, KS 66201
M20E, M20F; T.C. 2A3	SA250GL	Installation of Lycoming IO-360-A1B6 engine in lieu of Lycoming IO-360-A1A engine using original installation hardware and components. No installation data are required. Issued 6/30/78.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F: T.C. 2A3	SA320GL	Installation of Hartzell Model HC-C2YK-1( )F/F7666A-40 propeller in lieu of Hartzell Model HC-C2YK-1/7666-2 propeller using original installation hardware and components on aircraft previously modified in accordance with STC No. SA250GL. No installation data are required. Issued 6/28/79.	GL	46260	Jet Enterprises, Inc. 4212 Airport Road Cincinnati, OH 45226
M20E, M20F: T.C. 2A3	SA1411WE	Installation of Rajay turbocharged Lycoming IO-360-A1A engine. Amended 5/9/77.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
M20E, M20F, M20J: T.C. 2A3	SA2968WE	Installation of manifold pressure gage/fuel flow meter (fuel pressure gage) in lieu of original gage/meter. Amended 11/20/79.	WE	65015	John A. Porter 29 Walnut Via 501 East Orangethorpe Avenue Anaheim, CA 92801
M20E, M20F, M20J; T.C. 2A3	SA3728WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
M20E, M20F, M20J; T.C. 2A3	SA4065WE	Installation of Silver Instruments fueltron 1G or IP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20F, S/N 22-1179 and up; M20J, S/N 24-0001 and up; T.C. 2A3	SA1212CE	Installation of King KFC 200 2 axis (3 optional) flight control system with KCS 55/55A compass and King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller or third axis (yaw damper) only, or manual electric trim only. Amended 9/8/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20F, S/N 22-0013 and on (1974 models), S/N 22-1179 and on (1975 models): T.C. 2A3	SA2986WE	Installation of Pathfinder autopilot systems. Issued 2/19/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20F; T.C. 2A3	SA3047SW-D	Automatic flight system AK523 consisting of Century III autopilot with command automatic electronic pitch trim system and optional radio and glide slope couplers. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3048SW-D	Automatic flight system AK876 consisting of Century IIB autopilot with optional radio coupler. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F; T.C. 2A3	SA3049SW-D	Automatic flight system AK475 consisting of Century I autopilot with optional omni tracker. Issued 3/26/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
M20F: T.C. 2A3	SA3064SW-D	Mitchell command electric trim AK541. Issued 7/3/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
M20F: T.C. 2A3	SA3186WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 6/17/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
M20F: T.C. 2A3	SA4087WE	Installation of Hartzell HC-C2YK-1B/7666A-40 constant speed propeller. No installation data required. Issued 1/9/80.	WE	52025	Paul E. Loewen P.O. Box 545 Lakeport, CA 95453
M20F, M20J: T.C. 2A3	SA4176SW	S-TEC system 60 (two axis) flight guidance system, Model ST-015, with optional flight director steering horizon and vertical speed indicator/selector (14 volt system). Issued 8/11/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrail Complex Mineral Wells, TX 76067
M20F, M20J: T.C. 2A3	SA4177SW	S-TEC manual electric trim system, Model ST-022. Issued 8/14/80.	SW	74963	S-TEC Corporation Route 3, Building 946 Wolters Industrial Complex Mineral Wells, TX 76067
M20J: T.C. 2A3	SA1300CE	Installation of Edo-Aire propeller governor Model 34-826-014-11. Amended 1/9/78.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
M20J: T.C. 2A3	SA3307SW-D	Installation of Mitchell automatic flight system AK801 consisting of Century 41 autopilot or Model AK801FD consisting of Century 41 flight director autopilot. Issued 10/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J: T.C. 2A3	SA3308SW-D	Installation of Mitchell automatic flight system AK802 consisting of Century 21 autopilot. Issued 10/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
M20J: T.C. 2A3	SA3555WE	Installation of Rajay turbocharged Lycoming IO-360-A3B6D and/or IO-360-A1D6D engines. Issued 12/30/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road Long Beach, CA 90801
M20J, M20K: T.C. 2A3	SA300CE	Installation of propeller governors on single and twin engine aircraft, P/N M20J F210490, M20K F210760. Issued 2/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
M20J (240773, 270939, 24-1094 and on), M20K: T.C. 2A3	SA1464CE	Installation of KFC 200 two axis (three optional) flight control system. Amended 12/3/80.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
M20J, M20K: T.C. 2A3	SA1525CE-D	Installation of King KNS 81 digital area navigation system. Issued 1/23/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
M20J, M20K: T.C. 2A3	SA1557CE-D	Installation of KAS 297 altitude select option. Issued 10/24/80.	CE	48250	King Radio Corporation 400 North Robers Road Olathe, KS 66061
M20K: T.C. 2A3	SA378GL	Installation of Silver Instruments fueltron IG digital fuel flow meter. Reissued 1/3/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
M20K: T.C. 2A3	SA3325SW-D	Mitchell automatic flight system AK807 consisting of Century 41 autopilot flight director autopilot. Issued 1/30/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MK20 Series: MK22 Series: T.C. 2A3, A6SW	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
MK20 Series: MK22 Series: T.C. 2A3, A6SW	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
NEW ZEALAND AEROSPACE IND., LTD.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
FU24A-954; T.C. A9PC	SA949NW	North American Industries automatic flagman Model #4. Issued 6/3/80.	NW	61619	North American Industries, Inc. Route 4, City County Airport Walla Walla, WA 99362

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NIHON AEROPLANE MANUFACTURING CO., LTD.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
YS-11, -11A: T.C. A1PC	ST424SO	Installation of replacement radome assembly.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11, -11A; T.C. A1PC	SA863EA	Incorporation of Chromalloy Electronics Division ESL-1 or ESL-6 emergency slide lighting system. Reissued 3/6/73.	SO	22225	Chromalloy Electronics Div. of Chromalloy American Corp. 3901 North 29th Avenue Hollywood, FL 33020
YS-11, -11A: T.C. A1PC	SA2728WE	Incorporation of Holcombe Industries Hi-Lite system (P/N 50-1001) for emergency evacuation slide lighting. Reissued 7/21/76.	WE	54825	Maravia Corporation P.O. Box 395 857 Thornton Street San Leandro, CA 94577
YS-11, -11A-200, -11A-300, -11A-500, -11A-600; T.C. A1PC	SA460GL	Installation of pneumatic de-icers, P/Ns 21S-2056-10-1, -10-2, -11-1, -11-2. Issued 10/20/80.	GL	38500	B.F. Goodrich Engineered Products Group 500 South Main Street Akron, OH 44318
YS-11, -11A-200, -300, -500, -600: T.C. A1PC	SA1198EA	Installation of a Safeway deicer overshoe P/N 5939 on Dowty Rotol propeller, model R209/4-40-4.5/2. Issued 6/23/80.	EA	70830	Semsa, Inc. 2125 Smithtown Avenue Ronkonkoma, NY 11779
YS-11A Series; T.C. A1PC	SA393SO	Install Goodyear 9540512 wheels in place of Goodyear 9543138 wheels.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series; T.C. A1PC	SA1175SO	Installation of pitot heat indication system. Issued 10/10/80.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A; T.C. A1PC	SA4110SW	Installation of Dynamic Air Engineering air condition system. Issued 4/22/80.	SW	07740	Air Freight International, Inc. P.O. Box 2 Addison, TX 75001
YS-11A; T.C. A1PC	SA4239SW	Foot warmers for cockpit and crew compartment heat. Issued 11/26/80.	SW	07740	Air Freighters Inter'l, Inc. P.O. Box 2 Addison, TX 75001
YS-11-A200; T.C. A1PC	SA1949WE	Installation of underseat baggage restraint system. Reissued 10/12/73.	WE	19910	Carrier Aircraft, Inc. 2750 East Wardlow Road Long Beach,CA 90807
YS-11A-200, -300, -500, -600: T.C. A1PC	ST487SO	Installation of P.P.G. manufactured main windshields, P/Ns 5613-00001 (L/H) and 5613-00002 (R/H) and Barber Colman P/N HYLZ 8882 temperture controller. Amended 2/22/74.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500: T.C. A1PC	ST486SO	Installation of external APU control panel. Amended 2/16/72.	SO	64500	Piedmont Aviation, Inc. Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A Series 500: T.C. A1PC	ST966SO	Installation of Bendix ground proximity warning system. Amended 11/20/75.	SO	64500	Piedmont Aviaton, Inc. P.O. Box 2720 Smith-Reynolds Airport Winston-Salem, NC 27102
YS-11A, -500: T.C. A1PC	SA2910SW	Unpressurized cargo door in rear left hand portion of fuselage. Amended 5/9/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A Series 500; T.C. A1PC	SA3873WE	Installation of bleed air heating system. Amended 8/17/79.	WE	10360	American Turbine Engine Company 2680 East Wardlow Road Long Beach, CA 90807
YS-11A-500: T.C. A1PC	SA4094SW	Aft cargo door between F.S. 636.2 and 758.9 between floorline and stringer 27 and associated structural changes. Issued 3/3/80.	SW	07740	Air Freighters Int'l, Inc. P.O. Box 2 Addison, TX 75001
YS-11A-500; T.C. A1PC	SA4261SW	Install bleed air heat system. Issued 1/13/81.	SW	07740	Air Freighters Inter'l, Inc. P.O. Box 2 Addison, TX 75001
YS-11A-600; T.C. A1PC	SA3047WE	Installation of provisions only for ground proximity warning system. Issued 5/28/75.	WE	87450	World Airways, Inc. Maintenance & Engineering Center Oakland International Airport Oakland, CA 94614

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
YS-11A-626: T.C. A1PC	SA78NW	Cabin modiication. Issued October 1973.	NW	83765	Vinnedge & Associates, Inc. P.O. Box 374 North Bend, WA 98045

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

NORTH AMERICAN AVIATION, INC., OHIO

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
BC-1A, AT-6 Series: TT-6G; T.C. 2-575	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennge and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
BC-1A, AT-6 Series: T-6G; T.C. 2-575	SA1008WE	Poly-Fiber covering of left elevator and right aileron. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
BC-1A, AT-6, -6A, -6B, -6D, -6F, SNJ-7, -6G; T.C. 2-575	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC-1A, AT-6, SNJ Series, T-66: T.C. 2-575	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC-1A, AT-6, -6A, -6B, -6C, -6D, -6F, T-6G; T.C. 2-575	SA1351WE	Replace existing fabric on wings, fuelage, empennage, and/or control surface with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
BC-1A, AT-6, -6A, -6B, -6C, -6D, -6F, T-6G; T.C. 2-575	SA2666WE	Ceconite 102 material covering of rudder, elevators and ailerons. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
AT-6 Series: T.C. 2-575	SA4-768	Application of glass cloth to ailerons and elevators.	WE	38060	Glasco-Air Products Oxnard-Ventura Airport Oxnard, CA 93030
AT-6 Series: T.C. 2-575	SA4-859	Ceconite 101 covering of rudder, elevators and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
AT-6 Series; T.C. 2-575	SA283SO	Glass-cloth wing tip caps.	SO	26580	Corben Development Corp. P.O. Box 1603 Venice, FI 33595
AT-6, -6A, -6B, -6C, -6D, -6F: T.C. A-2-575	SA1001NW	12-volt and 24-volt alternator systems. Issued 9/15/80.	NW	78590	William W. Todd 2958 S.W. 21st Court Gresham, OR 97030
AT-6, -6A, -6B, -6C, -6D, -6F, T-6G; T.C. A-2-575	SA1521WE	Installation of metal covering on ailerons, elevators and rudder. Reissued 6/8/79.	WE	47732	Ken Aero 6960 Curran Street Brownfield Int'l Airport San Diego, CA 92173
AT-6, -6A, -6B, -6C, -6D, -6F, SNJ-7, T-6G; T.C. A-2-575	SA2814WE	Installation of Hamilton Standard 3D40 225/6101A-18 propeller. Issued 2/5/74.	WE	70100	Santa Monica Propeler Service 3025 Airport Boulevard Santa Monica, CA 90405
AT-6D (SNJ-5): AT-6F (SNJ-6), T-6G, SNJ-7, AT-6C (SNJ-4): T.C. A-2-575	SA3091SW-D	Mitchell automatic flight system AK520 consisting of Century III autopilot with optional radio coupler. Issued 12/24/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
AT-6D (SNJ-5), AT-F (SNJ-5), AT-6F (SNJ-6), T-6G, SNJ-7, AT-6C (SNJ-4); T.C. A-2-575	SA3092SW-D	Mitchell automatic flight system, AK464, consisting of Century I autopilot with optional omni tracker.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
J3C-65, J3C-65S; T.C. A-691	SA465AL	Installation of PA-18 boot cowl and windshield. Issued 12/15/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA68AL	Installation of wing tank. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA456AL	Installation of PA-18 wing lift struts. Issued 11/22/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA458AL	Installation of PA-18 horizontal stabilizer trim system. Issued 11/23/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA460AL	Installation of PA-18 pitot-static system. Issued 11/24/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, 65S, PA-11, PA-11S;	SA462AL	Installation of PA-18 front seat. Issued 11/24/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3C-65, 65S, PA-11, PA-11S; T.C. A-691	SA463AL	Installation of PA-18 elevator control system. Issued 11/24/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J-3C; J-3F; J-3L; J-4, -4A; J-4E; J-5A, -5B, -5C; PA-11; PA-12; PA-14; PA-15; PA-16; PA-17; PA-18, -18A; PA-20; T.C. A-691, A-692, A-698, A-753, A-740, A-725, A-780, A-797, A-800, 1A1, A-805, 1A2, A9-7, 1A4	SA2NE	Installation of Cleveland wheels and brakes on several models of Piper aircraft. Issued 4/5/73.	NE	70320	Mr. William V. Scherbon Hadley Road Merrimac, MA 01860
J-3C, -3F, -3L; PA-11; T.C. A-691, A-692, A-698	SA302AL	Installation of AD 2500x10.5 wheel replacement skis and rigging. Amended 1/30/70.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99501
J3C, J3C-65, -65S, J3F, J3F-50, -50S, -60, -60S, -65, -65S, J3L, J31-S, J3L-65, -65S, J4, J4A, J4A-2, J4E, PA-12, PA-14, PA-15, PA-16, PA-17, PA-18, PA-18A, -18S, -125, -135, -150, PA-19, PA-19S, PA-20, PA-20S, -115, -135, PA-22, -108, -135, -150, -160, -22S, -135, -160, -150, PA-23-160, -235, -250, PA-24, -250, -260, PA-25, -235, PA-28, -140, -150, -160, -180, -235, PA-28S, -160, -180, PA-32-260; T.C. 691, A-692, A-698, A-703, A-740, A-780, A797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 1A10, 1A15, 2A8, 2A13, A3SO	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred P. Puccinelli DEP 1-145 36 Bay Drive East Huntington, L.I., NY 11743

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
J3C, J3C-65, -65S, PA-11, J3F, J3F-50, -50S, -60, -60S, -65, -65S, J3L, J3L-S, -65, -65S, J4, J4A, J4A-3, J4E, PA-12, PA-14, PA-15, PA-16, PA-17, PA-18, -18A, -18S, -125, -135, -150, PA-20, -20S, -115, -135, PA-19, -19S, PA-22, -22-108, -135, -150, -160, PA-22S, -135, -150, -160, PA-23, PA-23-160, -235, -250, PA-24, PA-24-250, -260, PA-25, -25-235, PA-28, -28-140, -150, -160, -180, -235, PA-28S, -28S-160, -180, PA-32, -32-260; T.C. A-691, A-692, A-698, A-703, A-740, A-780, A-797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 1A10, 1A15, 2A10, 2A13, A3SO	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
J3C, PA-11; J3F; J3L; J4; J4E; J5; PA-12, -12S; PA-14; PA-15; PA-17, PA-30, PA-31, -31-300; PA-32; PA-16; PA-18; PA-20; PA-22; PA-23; PA-24; PA-25; T.C. A-691, A-692, A-698, A-703, A-725, A-740, A-780, A-797, A-800, A-805, A1EA, A8EA, A3SO, 1A1, 1A2, 1A4, 1A6, 1A10, 1A15, 2A8, 2A10	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
J3C-40, -50, -65 (Army L-4A, -4B, -4J; Navy NE-1, -2), PA-11; T.C. A-691	SA3284WE	Installation of Geroge M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
Piper J3C-65; T.C. 691	SA158GL	Installation of engine fiberglass cowling. Issued 3/10/77.	GL	02250	Aero Fabricators, Inc. P.O. Box 181 Lyons, WI 53148
Piper J3C-65; T.C. A-691	SA196GL	Replacement of main wheels and brakes with Gerdes Products wheel A-1780 and A-1870-4 brake. Issued 10/27/77.	GL	43080	Robert I. Howell Rural Route #2 Lewisburg, OH 45338
J3C-65; PA-11; T.C. A-691	SA461AL	Installation of PA-18 landing gear cabane. Issued 11/24/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
J3-C, PA-11; PA-12; PA-14, PA-18, -19; T.C. 691, 780, 797, 1A2	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J3C-65, J3C-65S, J3F-65, -65S, PA-11, -11S; T.C. A-691, A-692	SA1038SO	Installation of Aqua Model 1500 floats. Amended 12/17/80.	SO	22775	Claggett Aircraft Products Research & Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
J3F; T.C. 692	SA394AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
J3F-50, -60, -65; T.C. A-692	SA821CE	Install Aero Model M1500, M1800, or M2000 main skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
J3F-60; T.C. 692	SA1008WE	Installation of poly-fiber covering material of fuselage and wing. Amended 8/21/79.	WE	75250	Stits Aircraft Corporation P.O. Box 3084 Riverside, CA 92509
J3L; T.C. 698	SA395AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
J3L, -65; T.C. A-698	SA822CE	Install Aero Model M1500, M1800 or M2000 main skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
J3L, -S, -65, -65S; PA-12, -12S; PA-14; PA-15; PA-17; J4, J4A, -S; J4B; J5A, -80, J5B, J5C, AE-1, HE-1; PA-11, -11S, J3C-40, -50, -50S, -65, -65S; J3F-50, -50S, -60, -60S, -65, -65S; PA-16, -16S; PA-18, -18A, -18S, -18-105 and -18S-105 (Special), -18-125, 18AS-125, -18S-125, -18-135, -18A-135, 18AS-135, -18-150, -18AS-150, -18S-150, PA-19, -19S; Restricted Category: PA-18A, -18A-135, -18A-150; AP-7, PA-20, -20S, -20-115, -20S-115, -20-135, -20S-135; PA-22, -22-108-135, -150, -160, -22S-135, 22S-150, 22S-160; PA-25, -25-235; T.C. 698, 780, 797, 800, 805, 703, 721, 725, 691, 692, 1A1, 1A2, AP-7, 1A4, 1A6, 2A8, 2A10	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
J4, J5, AE-1, HE-1, PA-11, -12, -14, -16, -18, -20, -22 Series; T.C. 691, 740, 725, 780, 797, 1A1, 1A2, 1A4, 1A6	SA1-510	Sur-Vent fuel tank filler cap.	EA	65332	Alfred P. Puccinelli DEP 1-145 36 Bay Drive East Huntington, L.I., NY 11743
J4 Series; T.C. 703	SA4-1130	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
J4 Series; T.C. 703	SA4-1401	McCauley 1A90-CF propeller.	WE	78492	Arthur P. Tillesen 8101 Larsen Street Garden Grove, CA 92600
J4 Series; T.C. 703	SA297WE	McCauley 1A90-CF propeller on Continental C-85-12 engine.	WE	01350	Dwight P. Addigton 409 Serenade Way San Jose, CA 95125
J5 Series; T.C. 725	SA11SW	Removal of outer wing tip bow.	SW	42127	Herring Aircraft Service P.O. Box 1082 Cedar Hill, TX 75104
J5 Series; T.C. 725	SA176CE	Removal of door and installation of placard.	CE	82380	Russell Van Dyke Marceline, MO 64658
J5 Series; T.C. 725	SA320CE	Lycoming O-290-D2 engine and Sensenich M76A-M2/7452 propeller.	CE	05967	Aircraft Service Company 7134 Booth Drive Prairie Village, KS
J5, AE-1, HE-1 Series; T.C. 725	SA4-1080	Ceconite 101 covering of complete airframe.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
J5A; T.C. A-725	SA305AL	Installation of 13-gallon auxiliary fuel tank. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J5A; T.C. A-725	SA495AL	Installation of Lycoming O-290-D and -D2 engine using Stoddard Model 501 engine mount. Amended 6/27/75.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
J5A; T.C. A-725	SA819CE	Install Aero Model M1500, M1800 or M2000 main skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
J5A, J5C; T.C. 725	SA396AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
J5A, J5A-80, J5B, J5C; T.C. A-725	SA1144SO	Removal of cabin entrance door and installation of placards. Issued 5/80.	SO	17012	Thomas A. Boswell P.O. Box 176 Elmore, AL 36025
J5A (Army L-4F), J5A-80, J5B (Army L-4G), J5C, AE-1, HE-1; T.C. A-725	SA3285WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
J-5C; T.C. A-725	SA354AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-11; T.C. 691	SA3-47	Extra 17-gallon right wing fuel tank.	CE	17305	Bristow Aircraft Company Bristow, IA 50611
PA-11; T.C. 691	SA4-479	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-11; T.C. 691	SA35AL	Installation of PA-18 flaps. Amended 3/7/67.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-11; T.C. 691	SA323CE	Manufacture hitch and bracket. Install tow hitch. Amneded 5/6/71.	CE	76500	Stubben-McCandless South Omaha Airport, Route 1 Pipillion, NE 68046
PA-11, -11S; T.C. 691	SA501AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-11, -11S; T.C. 691	SA501AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-11, -12, -14, -15, -16, -17, -18, -19, -20, -22, -25; T.C. 691, 780, 797, 800, 1A6, 1A1, 805, 1A2, 1A4, 2A8	SA4-977	Fiberglass rudder post mount for either Grimes or Whelen WRM rotating beacons.	NW	85751	Art Whitaker Pearson Airpark Vancouver, WA 98660
PA-11, -12, -14, -16, -20, -22; T.C. 691, 780, 797, 1A1, 1A4, 1A6	SA573SW	Booster wing tip kit 101-101-250.	SW	81250	Upper Valley Aviation, Inc. P.O. Box 541 McAllen, TX 78501
PA-11; PA-12; PA-14; PA-15; PA-16; PA-17; PA-18, PA-19; PA-20; PA-22, PA-25; PA-23, 23-160, 23-235, 23-250, E23-250; PA-24, -24-250, -24-260, -24-400; PA-28-140, 28-150, -28-160, -28-S-180, -28R-180, -28-180, -28-235, -28-S-160, -28R-200; PA-30, PA-39; PA-31, -31-300, -30P; PA-32-260, -300, -32S-300; T.C. A-691, A-780, A-797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 2A8, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA615EA	Installation of Whelen anti-collision strobe light system. Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
PA-11; PA-12; PA-14; PA-15; PA-16; PA-17; PA-18, PA-19; PA-20; PA-22; PA-25; PA-23, -23-160, -23-235, -23-250, -E23-250; PA-24, -24-250, -24-260, -24-400; PA-28-140, -28-150, -28-160, -28-S-180, -28R-180, -28-180, -28-235, -28-S-160, -28R-200; PA-30, PA-39; PA-31, -31-300, -31P; PA-32-260, -32-300, -32S-300; T.C. A-691, A-780, A-797, A-800, 1A1, A-805, 1A2, 1A4, 1A6, 2A8, 1A10, 1A15, 2A13, A1EA, A8EA, A3SO	SA800EA	Installation of aviation white anti-collision strobe lights. Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-12: T.C. 780	SA660AL	Installation of extended flaps, flap control system and modified ailerons. Issued 1/9/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12: T.C. 780	SA660AL	Installation of extended flaps, flap control system and modified ailerons. Issued 1/9/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99501
PA-12: T.C. 780	SA687AL	Installation of left side cabin door. Issued 7/16/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12; T.C. 780	SA689AL	Increased gross weight to 1935 lbs. Issued 7/8/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12 Series; T.C. 780	SA701AL	Installation of skis.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-12 Series; T.C. 780	SA815CE	Installation of skis. Issued February 1972.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
PA-12 Series; T.C. 780	SA2038WE	Installation of Lycoming O-320 engine, McCauley 1A170/1C172 and Sensenich M74DM propellers and associated alternator systems. Amended 3/7/74.	NW	61526	Harold G. Nelson 3005 Southwest Marshall Street Pendleton, OR 97801
PA-12 Series; T.C. 780	SA3283WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-12, PA-12S; T.C. 780	SA202EA	Installation of either a Lycoming engine O-290-D (125 HP) or O-290-D2 (135 HP) with Sensenich propeller M74PM. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181, 1216 North Road Lyons, WI 53148
PA-12, -12S; T.C. A-780	SA444AL	Installation of McCauley 1A175/GM propeller. Issued 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-12, -12S; T.C. A-780	SA476AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12, -12S; T.C. A-780	SA476AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA494AL	Installation of electric fuel gauges. Issued 5/1/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -12S; T.C. A-780	SA517AL	Installation of plexiglass skylight on top of cabin. Issued 5/17/74.	AL	27250	Crosswinds, Inc. 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, PA-12S; T.C. 780	SA537AL	Installation of Day & Night 4-1 fiberglass propeller spinner.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-12, PA-12S; T.C. 780	SA537AL	Installation of Day & Night 4-1 fiberglass propeller spinner.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA566AL	Installation of Lycoming O-320 engine. Amended 11/25/75.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-12, -12S; T.C. 780	SA629AL	Install fiberglass wing tip assembly.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12, -12S; T.C. A-780	SA653AL	Install Avco Lycoming O-320-A2B or O-320-C2B engine and Sensenich 74M6-0-52 propeller. Issued 9/8/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-12, -14 Series; T.C. 780, 797	SA5-48	Structure approval only of engine mount assembly on aircraft for use with engines of not more than 363 pounds total installed weight and 170 hp (4 cylinder).	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-12, -14 Series; T.C. 780, 797	SA5-66	Structural approval only of Fred A. Shaw engine mount and forward fuselage modification for installation of 150 hp engine. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622
PA-12, -14 Series; T.C. 780, 797	SA5-66	Structural approval only of Fred A. Shaw engine mount and forward fuselage modification for installation of 150 hp engine. Reissued 5/7/79.	AL	42051	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-12, -14 Series; T.C. 780, 797	SA83AL	Lycoming O-320 Series (150 hp models only) engines and Sensenich M74DM propeller, using Stoddard engine mount 501. Amended 6/12/69.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA148AL	PA-18 main landing gear and installation of EDO 2000 floats. Amended 3/3/69.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA148AL	PA-18 main landing gear and installation of EDO 2000 floats. Amended 3/3/69.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA149AL	Installation of auxiliary baggage compartment.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-12, -14 Series; T.C. 780, 797	SA189AL	Install left side cabin door.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA189AL	Install left side cabin door.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA190AL	Increased gross weight to 1935 pounds.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503 AND
PA-12, -14 Series; T.C. 780, 797	SA190AL	Increased gross weight to 1935 pounds.	AL	20514	Clinton C. Center 2301-1/2 Merrill Field Drive Anchorage, AK 99501
PA-12, -14 Series; T.C. 780, 797	SA213SO	Electric fuel quantity indicator. indicator.	SO	54615	Obed L. Malpass 1502 Morris Road Wilmington, NC 28401
PA-12, -14 Series; T.C. 780, 797	SA289AL	Install rudder centering device.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th PPlace Anchorage, AK 99503
PA-12, -14 Series; T.C. 780, 797	SA2313SW	Install 22-1/2 gallon fuel tank. Issued 5/20/77.	SW	75498	W.L. Stoddard Stoddard Aero Service c/o Plane Booster, Inc. Box 541 McAllen, TX 78501
PA-12, -14, -16, -18, -10; T.C. 780, 797, 1A1, 1A2, 1A4	SA147AL	Electric fuel quantity gauge system.	AL	42158	C.D. Hogan 1831 Lake Otis Parkway Anchorage, AK 99501
PA-12, PA-14, PA-16, PA-18, PA-20, PA-22; T.C. 780, 797, 1A1, 1A2, 1A4, 1A6, AR-7	SA22RM	Manufacture of exact replacement parts, front and rear lift strut assembly. Amended 3/13/79.	RM	50500	Light Plane Components, Inc. 509 Buckley Road Aurora, CO 80011
PA-12, -14, -18; T.C. 780, 797, 1A2	SA215AL	Install T-2500A wheel replacement skis.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99501
PA-12, PA-14, PA-20, PA-22 Series; T.C. 780, 797, 1A4, 1A6	SA5-60	Installation of Russ Simpson sea fins.	AL	71774	Simpson Airservice, Inc. P.O. Box 2226 Ketchikan, AK 99901
PA-12; PA-22; T.C. A780, 1A6	SA388SO	Metalize wings, wing landing/taxi light installation. Amended 7/2/70.	SO	68550	W.F. Robison Valley Air Service P.O. Box 241 Lanett, AL 36863
PA-12, PA-22, PA-23, PA-28; T.C. 780, 1A6 2A13, 1A10	SA316SO	Carburetor ice detector. Amended 10/5/66.	SO	71545	C.B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
PA-12S; T.C. 780	SA610AL	Install Avco Lycoming O-360-A2A engine. Amended 2/25/77.	AL	20514	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-14; T.C. 797	SA688AL	Installation of left side cabin door. Issued 7/16/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA690AL	Increase gross weight to 1,935 lbs. Issued 7/8/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-14; T.C. 797	SA702AL	Installation of skis. Issued 11/24/80.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-14; T.C. 797	SA3213WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avneue Torrance, CA 90501
PA-14, PA-18, PA-20: T.C. 797, 1A2, 1A4	SA41AL	Six inch wheels and brakes.	GL	56570	Wesley W. Mathias 154 North Broad Street Bremen, OH 43107
PA-15; T.C. 800	SA1-619	Continental A-65-8F engine and McCauley 1A90CF-7147 propeller.	NE	39514	Griswold Air Service Griswold Airport Madison, CT 06443
PA-15; T.C. 800	SA4-1225	Ronite covering on complete aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-15; T.C. 800	SA69AL	Installation of fuel tanks. Amended 2/7/75.	AL	75500	W.I. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-15; T.C. 800	SA3214WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-15, PA-17; T.C. 800, 805	SA4-1025	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-16 Series; T.C. 1A1	SA1-577	Installation of Sensenich controllable pitch propeller Model CS3F44/C374E. Amended 6/24/70.	EA	64268	Theodore J. Peters County Line Road, RD 3 Sommerville, NJ 08876
PA-16 Series; T.C. 1A1	SA4-900	Ceconite 101 covering of wings, fuselage, ailerons, elevator and rudder.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-16 (Landplane); T.C. 1A1	SA24EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-16 Series; T.C. 1A1	SA399AL	Conversion of 4" wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-16 Series; T.C. 1A1	SA412NW	Replace original equipment expander-tube brakes with new Cleveland wheels and brakes. Issued 3/3/77.	NW	00300	Michael J. Abdo 9415 Lexington Avenue, S.W. Tacoma, WA 98498
PA-16 Series; T.C. 1A1	SA3215WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-16, -16S; T.C. 1A1	SA447AL	Installation of auxiliary fuel tanks in right wing. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-16, -16S; T.C. 1A1	SA478AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-16, -16A; PA-18, PA-18S, "105", "125", "135", "150": "PA-18A"135", "150:"; PA-18AS"125", "135", "150"; PA-19S; PA-23, -23-160, -235, -23-250; PA-24, -24-250, -260; PA-28-140, 150, 160, 180, -235, PA-28-S-160, -S-180; PA-30; T.C. 1A1, 1A2, 1A10, 1A15, A1EA, 2A13	SA630WE	Installation of Coast Winslow Filter Corporation #09 series oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-282	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16, PA-20, PA-22; T.C. 1A1, 1A4, 1A6	SA1-327	Replacement of fabric covering with metal skins.	EA	72100	Skycraft Design, Inc. West Trenton, NJ 08628
PA-16S; T.C. 1A1	SA384AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/17/70.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-17 Series; T.C. 805	SA4-483	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-17 Series; T.C. 805	SA446AL	Installation of fuel tanks. Amended 2/7/75.	AL	17000	W.I. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-17 Series; T.C. 805	SA3216WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-18 Series; T.C. 1A2	SA425AL	Installation of removable seat back support. Issued 4/23/71.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99503
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-18 Series; T.C. 1A2	SA431AL	Replace original nose cowl with fiberglass. Reissued 5/7/79.	AL	76732	Ronald R. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18 Series; T.C. 1A2	SA526AL	Build up 1-1/4" axle to 1-1/2" axle to install Celveland wheel and brake. Issued 8/7/74.	AL	68436	Bill Pobek Box 10-214 Flatt Station ANchorage, AK 99502
PA-18 Series; T.C. 1A2	SA540AL	Installation of modified landing gear with main gear legs lengthened 6 inches. Issued 2/19/75.	AL	28815	Terry Allen Cartee and Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18; T.C. 1A2	SA682AL	Installation of 160 hp Lycoming O-320. Issued 6/26/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18; T.C. 1A2	SA1586CE	Modified brake master cylinder. Issued 5/9/80.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-18 Series; T.C. 1A2, AR-7	SA1-32	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
t+1 PA-18 Series; T.C. 1A2, AR-7	SA1-41	McCauley fixed pitch MET-L-PROP 1A170/GM7450, 1A170/GM7452 and 1A170/GM7454 propellers with Lycoming O-320-A1A engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-59	McCauley fixed pitch MET-L-PROP 1A170/GM7448 and 1A170/GM7450 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-155	McCauley fixed pitch MET-L-PROP 1A170/GM7448 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corporation 1840 Howell AVenue Dayton, OH 45417
PA-18 Series; T.C. 1A2, AR-7	SA1-156	McCauley fixed pitch MET-L-PROP 1A170/GM7446 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18 Series; T.C. 1A2, AR-7	SA1-349	Glider tow. Amended 5/12/67.	EA	70400	Schweizer Aircraft Corporation Box 147, County Airport Elmira, NY 14902
PA-18 Series; T.C. 1A2, AR-7	SA4-254	Hartzell HC82XG-6/7636D-4 propeller Lycoming 70385 dual drive assembly, Woodward 210115 single acting governor and J-6230-1 lord mount assembly.	WE	15415	Ellen Belotti 1208 East Charleston Road Las Vegas, NV 89114
PA-18 Series; T.C. 1A2, AR-7	SA4-364	Application of glass cloth with resin.	WE	38060	Glasco-Air Products, Inc. County Airport Oxnard, CA 93030
PA-18 Series; T.C. 1A2, AR-7	SA4-1644	Full flow lube oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-18 Series; T.C. 1A2, AR-7	SA5-31	Auxiliary baggage tube.	AL	17000	M.R. Borer 1307 West 39th Place Spenard, AK
PA-18 Series; T.C. 1A2, AR-7	SA4AL	Installation of auxiliary wing fuel tanks. Amended 5/20/71.	AL	30250	F. Atlee Dodge Aircraft Maintenance P.O. Box 6409 Anchorage, AK 99502
PA-18 Series; T.C. 1A2, AR-7	SA4RM	Installation of modified landing gear, Cleveland P/N 40-84 wheels and P/N 30-41 brakes. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-18 Series; T.C. 1A2, AR-7	SA17RM	Replace landing gear vee for PA-18 series P/N 10033. Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-18 Series; T.C. 1A2, AR-7	SA44AL	Auxiliary wing fuel tanks.	AL	86070	Joseph Wilbur P.O. Box 931 Anchorage, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA50AL	Cowl flaps.	AL	05960	Aircraft Repair & Maintenance Co. P.O. Box 6207 Anchorage, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA70EA	Edo 339JHS amphibious floats.	EA	61622	North American Flying Service, Inc. Bergen Turnpike Little Ferry, NJ 07643
PA-18 Series; T.C. 1A2, AR-7	SA105NW	Mounting and wiring for occasional installation and use of Barnes Engineering Co. airborne fire spotter system. Issued 4/30/74.	NW	61300	State of Washington Department of Natural Resources Route 13, Box 62 Olympia, WA 98501
PA-18 Series; T.C. 1A2, AR-7	SA141AL	Removal of agricultural hatch.	AL	45000	Jake's Aircraft Salvage 3906 Barbara Drive Spenard, AK 99503
PA-18 Series; T.C. 1A2, AR-7	SA143AL	Enlarged instrument panel.	AL	30250	F.A. Dodge P.O. Box 6409 Anchorage, AK 99506
PA-18 Series; T.C. 1A2, AR-7	SA150AL	Installation of cockpit operated cowl flap winterization kit. Reivsed 7/29/69.	AL	39400	Charles L. Gray 319 Slater Street Fairbanks, AK 99501
PA-18 Series; T.C. 1A2, AR-7	SA230EA	Flottorp controllable pitch propeller.	EA	11730	Arnold Air Service Dale & Mackey Road, RD 2 Gasport, NY 14067
PA-18 Series; T.C. 1A2, AR-7	SA234SW	Alteration of method of attaching spray plates and dust spreader to spray tank and alteration of emergency dump cable hookups.	SW	42480	John L. Horne, Jr. P.O. Box 218 Webbers Falls, OK 74470
PA-18 Series; T.C. 1A2, AR-7	SA284SW	Landplane lower cowl on aircraft with Edo 89-2000 floats.	SW	72752	Slidell Aviation Services Route 2, Box 99 Slidell, LA 70458
PA-18 Series; T.C. 1A2, AR-7	SA324CE	Manufacture hitch and bracket. Install tow hitch. Amended 5/6/71.	CE	76500	Stubben-McCandless South Omaha Airport Route 1 Papillion, NE 68046
PA-18 Series; T.C. 1A2, AR-7	SA569SW	Cessna 172 landing gear.	SW	61100	Myhand and Deam Aircraft Route 5, Box 505 Pine Bluff, AR 71601

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18 Series; T.C. 1A2	SA894WE	Lycoming O-320-A2B engine and Sensenich M74DM-56 propeller.	RM	35770	Sam B. Flint P.O. Box 332 Holly, CO 81047
PA-18 Series; T.C. 1A2	SA1588CE	Modified airplane, widening fuselage and increasing gross weight. Issued 5/21/80.	CE	14752	B.A.R.F. Inc. P.O. Box 447 Clarence, MO 63437
PA-18, PA-18A; T.C. 1A2, AR-7	SA4-1430	125-gallon hopper and small swathmaster. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-18, PA-18A; T.C. 1A2	SA1243CE	Install Cleveland wheels and brakes and optional wheel fenders. Amended 9/29/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, -18A; T.C. 1A2	SA1244CE	Replace landing gear components. Issued July 1976.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, PA-19; T.C. 1A2, AR-7	SA3-180	C2200 main (hydraulically actuated) and CTF2200 or CT3000 tail skis.	GL	36030	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA3-328	C-2200 main (manually actuated) and AWT2500 or AWT2500A tail wheel-skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA3-352	Model 3000 main skis and Model 1000 tail skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-19; T.C. 1A2, AR-7	SA4-923	Eonite covering on entire aircraft.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-18, PA-19; T.C. 1A2, AR-7	SA4-986	Ceconite 101 covering of complete airplane.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-18, PA-19; T.C. 1A2	SA703AL	Installation of skis. Issued 11/24/80.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99502
PA-18, PA-19, PA-20; T.C. 1A2, 1A4	SA3-423	CT-3000 tail ski on airplanes with Scott 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-18, PA-20, PA-22; T.C. 1A2, AR-7, 1A4, 1A6	SA3-654	Laminated plastic and fiberglass nose.	RM	28500	Dakota Aviation Company P.O. Box 18 Huron, SD 57350
PA-18, PA-22, PA-23, PA-24 Series; T.C. 1A2, 1A6, 1A10, 1A15	SA1-383	Lube oil filter PB 55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
PA-18, -22, -23, -24, -25, -28 Series; T.C. 1A6, 1A2, AR-7, 1A10, 1A15, 2A13	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace AVenue Torrance, CA 90510
PA-18, PA-25; T.C. 1A2, AR-7, 2A8	SA673SW	All metal covering of aileron.	SW	60168	Luther V. Moore 1110 West 29th Street Plainview, TX 79072
PA-18, 90 thru 150; T.C. 1A2	SA753CE	Installation of skis.	GL	02750	Aero Ski Manufacturing Company Park Rapids, MN 56470
PA-18, -18A, -105, -125, -135, -150, 18A-135, -150; T.C. 1A2	SA800AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	GL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-18, -18"105", -18A, -18"125", -18"135", -18A-"135", -18"150", -18A-150, -19 and seaplane versions; T.C. 1A2	SA427AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65662
PA-18, -18"105", -18A, -18"125", -18"135", -18A-"125", -18"150", -18A-150, -19 and seaplane versions; T.C. 1A2	SA427AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	AND Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18, -18A, -18-105, -18-125, -18-135, -18A-135, -18-150, and seaplane versions; T.C. 1A2	SA489AL	Installation of modified dog leg brace baggage compartment. Issued 10/24/72.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-18, -18-105, -125, -135, -150, PA-18S, -18S-105, -125, -135, -150, PA-18A, -18A-135, -150, PA-18AS-125, -135, -150, PA-19, PA-19S; T.C. 1A2	SA624AL	Install fiberglass wing tip assembly. Issued 3/21/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, PA-18-105, -125, -135, -150, PA-18S, PA-18S-105, -125, -135, -150, PA-18A, -18A-135, -150, PA-18AS-125, -135, PA-19, PA-19S; T.C. 1A2	SA638AL	Fabricate rudder mounted strobe light support bracket. Issued 6/14/78.	AL	30250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18, -18-105, -125, -135, -150, PA-18, -18-105, -125, -135, -150, PA-18A, -18A-125, -18A-135, -150, PA-18AS-125, -135, -150; T.C. 1A2	SA641AL	Fabricate front wing spar butt attachment repair fitting. Issued 7/10/78.	AL	20514	Clinton C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, -18"105" Special, -18A, -18"125", -18"135", -18A"135", -18"150", -18A"150", -19; T.C. 1A2	SA900CE	Replace round wing tips with constant-chord, square tips and wing splates. Amended February 1975.	CE	35650	James W. Flanagan and Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18, -18A, PA-19; T.C. 1A2	SA1245CE	Installation of Scott master cylinder having Flanagan Aircraft conversion. Amended 6/22/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18, -18A, -18-105, -18-125, -18-135, -18-150, -18A-150, PA-19; T.C. 1A2	SA2478WE	Installation of automatic flagman Model 5. Issued 2/14/72.	NW	03500	Air-Ag, Inc. Route 4, City County Airport Walla Walla, WA 99362
PA-18, -105, -125, -135, -150; T.C. 1A2	SA5-7	Install framing and seat in baggage compartment. Amended 7/25/68.	AL	17000	M.P. Borer 1307 West 39th Place Anchorage, AK 99501
PA-18, -18-105, -125, -135, -150, PA-18A-125, -135, -150; PA-19; T.C. 1A2	SA301AL	Installation of AD 2500x10.5 wheel replacement skis and rigging.	AL	30250	F. Atlee Dodge P.O. Box 6409 Anchorage, AK 99501
PA-18, -18"105", -18A, -18"125", -18"135", -18A"135", -18"150", -18A"150", PA-19 (Army L-18C); T.C. 1A2	SA3282WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheels and Bodell BMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-18, -18S, -18-135, -18S-135, -18A-135, PA-18-105 (Special), PA-18S-105 (Special), PA-18-150, -18A-150, -18S-150; T.C. 1A2	SA490AL	Installation of leading edge cuff. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18, -18S, -18"105", "125", "135", "150", -18A, "135", "150", -18S"105", "125", "135", "150", PA-19, -19S, PA-22, -22-108, -135, -150, -160, -22S-135, -150, PA-24, -24-250, -260; T.C. 1A2, 1A6, 1A15	SA1033EA	Replace steel oil cooler lines with Aeroquip type 303-8 hose using AN-823-8D elbows, AN-816-8D nipples and AN-321-8 hose fittings. Issued 1/29/76.	EA	78872	Walter Thompson, Sr. 32 High View Avenue Florida, NY 10921
PA-18, -18S, -18-"105" Special, -18S-"105" Special, -18-"135", -18S-135; T.C. 1A2	SA1191SO	Installation of Aqua Model 1500 floats. Issued 12/8/80.	SO	22775*	Claggett Aircraft Products Research and Engineering, Inc. 805 Geiger Road Zephyrhills, FL 33599
PA-18, -18-125, -18-135, -18-150; PA-19; T.C. 1A2	SA2468WE	Use of GCA-600 axle adapter assembly for installation of Cleveland Model 40-88A wheels and Model 30-41 brakes. Issued 1/20/72.	WE	15835	Ken Bemis Brawley Municipal Airport P.O. Box 1293 Brawley, CA 92227

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18A; T.C. 1A2	SA681AL	Installation of removable crossbar. Issued 1/10/80.	AL	30250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18A; T.C. 1A2	SA886CE	Metalize bottom of fuselage per Flanagan Aircraft Drawing List No. 2. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A; T.C. 1A2	SA887CE	Removal of hopper cover and installation of Lexan skylight and side windows. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A; T.C. 1A2	SA888CE	Relocation of battery box and/or installation of an external power receptacle. Amended July 1975.	CE	35650	James W. Flanagan & Elmer Olson 20224 R.D. Mize Road Independence, MO 64057
PA-18A, -18A-135, -18A-150; T.C. 1A2	SA5-29	Install third seat in baggage compartment and relocate battery aft of baggage compartment. Amended 7/25/69.	AL	17000	M.R. Borer 1307 West 39th Place Anchorage, AK 99503
PA-18A, PA-18A"135"; -18A"150"; T.C. 1A2	SA1369CE	Electrical system and instrument panel modification. Issued 9/28/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18S, -19S, -18S"105" (Special), -18S"125" -18S"135"; T.C. 1A2	SA3-96	Install Pee-Kay Model 1500 floats. Reissued 11/13/70.	EA	29998	Pee-Kay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-105, 18S-105, -125, 18S-125, -18AS-125, 18-135, 18S-135, 18A-135, -18AS-135; T.C. 1A2	SA136AL	Installation of Lycoming O-320 engine. Amended 5/14/69.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-105, -18S-105, -18-125, -18A-125, -18AS-125, -18A-135, -18S-135, -18AS-135; T.C. 1A2	SA292AL	Increased gross weights to PA-18-150 weights and C.G. envelope. Note: Airplanes must have Lycoming O-320 engine installed, except the PA-18-135 or PA-18-135 for which the engine change is optional. Amended 5/5/72.	AL	17000	W.T. Ellis and M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-105, -125, -135, -150, -18S, -105, -125, -135, -150, -18A-135, -150, -18AS-125, -135, -150, PA-16, PA-16S, PA-19S, PA-22, -108, -125, -150, -160; PA-23, -160, -250; PA-24, -250; PA-24-400; PA-28-160, -235; PA-30; T.C. 1A6, 1A10, 1A15, 2A13, A1EA	SA589WE	Installation of full-flow lube oil filters on the aircraft for the benefit of the engine. Amended 3/7/74.	WE	87500	Worldwide Aircraft Filter Corp. 1685 Abram Court San Leandro, CA 94577
PA-18S, PA-18S"105", -18S"125", -18AS"125", -18S"135", -18AS"135", PA-19S; T.C. 1A2	SA159CE	Installation of Pee-Kay Model 1800 floats. Reissued 6/12/74.	EA	29998	Pee-Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-125; T.C. 1A2	SA669CE	Install Aqua Model 1900 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Reserach and Engineering, Inc. 805 Geiger Road Zephyrhills Hills, FL 33599
PA-18-125, -18A, -18-135, -18A-135, -18-150, -18A-150, 18S-125, -18AS, -18S-135, -18AS-135, -18S-150, -18AS-150, T.C. 1A2	SA98AL	Installation of two auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.I. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-18-125, -135, -150, -18S-125, -135, -150, 18A-135, -150, 18AS-135, -150; T.C. 1A2	SA117AL	Installation of Cunningham auxiliary fuel belly tank. Amended 9/16/69.	AL	08472	Airglas Engineering Co., Inc. P.O. Box 4165 Anchorage, AK 99502

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18-125, PA-18-135, PA-18A-135; T.C. 1A2	SA388EA	Installation of Lycoming O-320, O-320-A2A or O-320-A2B engine (150 hp) and Sensenich propeller M74DM-56 configuration I. Increase in maximum allowable gross weight and C.G. limits as per Model PA-18-150 values – configuration II. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-18S-125; T.C. 1A2	SA2397WE	Installation of McCauley Model 1A175-GM/8240 propeller. Issued 10/27/71.	NM	09300	Kenneth R. Alexander 1732 Northwest 64th Seattle, WA 98107
PA-18S"125", PA-18S-135, 18S-150; T.C. 1A2	SA879EA	Installation of Edo Model 88A-1650 seaplane floats with Edo Model 088A21 attachment gear. Reissued 4/1/76.	EA	32625	Edo-Aire Seaplane Division Edo Corporation 65 Marcus Drive Melville, NY 11746
PA-18S-125, -150; T.C. 1A2	SA1099WE	Install fiberglass reinforced plastic floats. Reissued 9/20/79.	EA	32625	Edo-Aire Seaplane Division Division of Edo Corporation Republic Airport East Farmingdale, NY 11735
PA-18-135; T.C. 1A2, AR-7	SA1-33	McCauley fixed pitch MET-L-PROP 1A170/GM7450 and 1A170/GM7452 with Lycoming O-290-D2 engine. Amended 9/5/75.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-18-135, -18A-135, -18S-135, -18AS-135, -18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA279AL	Installation of McCauley 1A175/GM propeller on -135 models listed and installation of McCauley 1A175/GM 8241 through GM 8244 on the -150 models listed. Amended 8/4/71.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-18-135, -18A-135, -18-150; T.C. 1A2	SA518CE	Install Aqua Model 1900 floats. Reissued 7/31/78.	SO	22775	Claggett Aircraft Products Research and Engineering, Inc. 805 Geiger Road Zephryhills, FL 33599
PA-18"135", -18A"135", -18S-"135", -18AS"125", -18"150", -18A-"150", -18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-18"135", -18A"135", -18S-"135", -18AS"135", -18"150", -18A-"150", '18S"150", -18AS"150"; T.C. 1A2	SA551AL	Installation of Day & Night 4-1 fiberglass propeller spinner. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1333CE	Installation of replacement engine mount. Issued June 1977.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18-135, -18-150, -18A-135, -18A-150; T.C. 1A2	SA1366CE	Installation of a third seat, removable cross member, and reinforced baggage compartment floor. Issued 8/26/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18-135, -150, PA-20, PA-22, PA-23, PA-24 less 24-180, -24-280, -24-400, PA-25, PA-28 less -28-180, PA-28-180, -235, PA-30, PA-31, PA-32, PA-34, PA-39; T.C. 1A2, 1A4, 1A6, 1A10, 1A15, 2A8, 2A10, 2A13, A1EA, A8EA, A390, 1A10, A1EA	SA1512WE	Installation of exhaust gas temperature monitoring system Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18-135, -150, PA-22, PA-23, PA-24, -24-400, PA-28, -28-235, PA-30, PA-31, PA-32; T.C. 1A2, 1A6, 1A10, 1A15, 2A13, A1EA, A8EA, A390	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-18A-135, PA-18A-150; T.C. 1A2	SA1368CE	Cabin metalization; installation of new boot cowl, firewall, swing up side windows, larger baggage door, and inspection access in aft fuselage. Issued 9/12/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence, MO 64057
PA-18S-135; T.C. 1A2	SA288AL	Install McCauley 1A175-GM8040 or 1A175-GM8044 propeller. Amended 4/2/69.	GL	56512	Matanuska Air Services, Inc. P.O. Box 786 Palmer, AK 99645

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18-150: T.C. 1A2	SA36RM	Installation of Lycoming O-360-C2A or O-360-A3A 180 hp engine. Issued 11/22/78.	RM	46780	David C. Johnson 10850 Thomas Road Colorado Springs, CO 80908
PA-18-150: T.C. 1A2	SA532AL	Installation of Lycoming O-360-A2A engine. Amended 2/25/77.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150": T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 64622 AND
PA-18"150": T.C. 1A2	SA554AL	Installation of third seat in baggage compartment. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-18-150: T.C. 1A2	SA590AL	Install extended baggage compartment. Issued 7/2/76.	AL	39250	F. Atlee Dodge Box 6409 Anchorage, AK 99502
PA-18-150: T.C. 1A2	SA596AL	Install Hartzell propeller Model HC-C2YL-1BF/F8468-8R. Issued 3/4/77.	AL	30250	Atlee R. Dodge P.O. Box 6409 Anchorage, AK 99509
PA-18-150: T.C. 1A2	SA612AL	Extended ailerons. Issued 5/25/77.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18-"150": T.C. 1A2	SA1203SO	Installation of Fiberfloat Model 2400( ) floats. Issued 2/12/81.	SO	35100	Fiberfloat Corporation 895 East Gay Street Bartow, FL 33830
PA-18"150", -18A"150", -18S"150", -18AS"150"; T.C. 1A2	SA4-1143	Installation of Lycoming O-320-A3B engine and Hartzell HC-82XL-6B/7636D-2 propeller. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
PA-18"150", -18A"150"; T.C. 1A2	SA92NW	Installation of Lycoming O-360-A2D engine, McCauley 1A200-FA8241 propeller, and associated sub-systems. Issued 3/1/78.	NW	32756	Ed's Aviation Service P.O. Box 156 Arlington, WA 98223
PA-18"150", -18A"150"; T.C. 1A2	SA109CE	Installation of Pee-Kay Model 1800 floats. Reissued 6/12/78.	EA	29998	Pee Kay Float Division DeVore Aviation Corporation 125 Mineola Avenue Roslyn Heights, NY 11577
PA-18-150, -18A-150: T.C. 1A2	SA349AL	Installation of McCauley 1A175-GM 8242, GM8244, or GM8246 propeller. Amended 4/10/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-18-150, -18A-150: T.C. 1A2	SA353AL	Installation of Sorensen Aircraft Co. 60-gallon belly tank. Revised 2/12/71.	AL	76900	Superior Airmotive of Alaska, Inc. 2301 Merrill Field Drive Anchorage, AK 99501
PA-18"150", -18A"150"; T.C. 1A2	SA693AL	Installation of McCauley 1A175/GM8244 propeller. Issued 8/19/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150", -18A"150"; T.C. 1A2	SA694AL	Oil radiator installation. Issued 8/26/80.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150", PA-18A"150"; T.C. 1A2, AR-7	SA575WE	Belly master spray system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-18-150, -18A-150; T.C. 1A2	SA589AL	Install square horizontal stabilizers, elevators, and rudder. Issued 6/28/76.	AL	28815	Day & Night, Inc. 1729C, SRA Anchorage, AK 99507
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA284AL	Installation of Hartzell propeller with Woodward 2100-80-PS governor. Amended 10/30/75.	AL	14224	Bachner's Aircraft Service P.O. Box 2191 Phillips Field Fairbanks, AK 99701
PA-18-150, -18A-150, -18S-150, -18AS-150; T.C. 1A2	SA510AL	Installation of "Summer-all defroster valve". Issued 1/10/78.	AL	76738	Sumrall & Tears 3001 Yale Drive Anchorage, AK 99504
PA-18"150", PA-18S"150"; T.C. 1A2	SA648AL	Install Motorola 32.5 amp alternator. Issued 8/4/78.	AL	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18"150", PA-18A"150", PA-18S"150", PA-18AS"150"; T.C. 1A2	SA649AL	Fabricate 30.5 gallon wing fuel tanks. Issued 8/17/78.	AL	30250	F. Atlee Dodge Box 4609 Anchorage, AK 99502

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-18A-150; T.C. 1A2	SA623AL	Install wing tip assembly.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-18A"150"; T.C. 1A2	SA1370CE	Revised fuel gaging and dual fuel feed line installation from both tanks. Two wing fuel tanks standard. Issued 11/18/77.	CE	35650	Flanagan Aircraft Company 20224 R.D. Mize Road Independence Memorial Airport Independence, MO 64057
PA-18S-150, 18AS-150; T.C. 1A2	SA392AL	Installation of McCauley 1A175 GM8242, 8244, or 8246 propeller. Amended 9/24/70.	AL	28660	Daniels and Dick Star Route A, Box 1506B Anchorage, AK 99502
PA-18S-"150", -18AS-"150"; T.C. 1A2	SA912NW	Making the Fram CA-122 PL induction air filter eligible on the PA-18 models equipped with EDO 89-2000 floats installed. Issued 4/3/80.	NW	47740	Kenmore Air HArbor P.O. Box 64 Kenmore, WA 98028
PA-20 Series; T.C. 1A4	SA1-89	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engines.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-20 Series; T.C. 1A4	SA1-157	McCauley fixed pitch MET-L-PROP 1A170/GM7450 with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corporation 1840 Howell Avenue Dayton, OH 45417
PA-20 Series; T.C. 1A4	SA1-167	Lycoming O-320 150 hp engine, Sensenich M-74DM propeller, Piper PA-22-150 engine baffles, and and Harrison AP13SJ03-01 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamsport, PA 17701
PA-20 Series; T.C. 1A4	SA4-564	Eonite covering on wings, fuselage and control surfaces.	WE	52090	William C. Iott P.O. Box 632 Shafter Airport Bakersfield, CA 93308
t+1 PA-20 Series; T.C. 1A4	SA4-778	Ceconite covering.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-20 Series; T.C. 1A4	SA12RM	Installation of Light Plane Components landing gear vee assembly, P/N LPC 1012. Amended 3/13/79.	RM	50580	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-20 Series; T.C. 1A4	SA31CE	Removal of rear left door and installation of placard.	CE	50725	Lincoln Sport Parachute Club, Inc. 929 Furnas Avenue Lincoln, NE 68501
PA-20 Series; T.C. 1A4	SA73CE	Covering with dacron of wings, fuselage, tail group, flaps, all control surfaces, or any of these individually.	GL	30518	Downer Aircraft Company P.O. Box 46 Alexandria, MN 56308
PA-20 Series; T.C. 1A4	SA211WE	Removal of left-hand cabin door for parachute jumping and aerial photography operations.	RM	38040	Glacier View Skyways, Inc. P.O. Box 252 Kalispell, MT 59901
PA-20; T.C. 1A4	SA224GL	Install Gerdes control wheels, Model No. A-1561-C and A-1562-C utilizing AN3-12 bolts (2), AN3-65 self-locking nuts (2) and AC-980-316 washers(2). Issued 2/15/78.	GL	64950	Matthew C. Polaski 25 Immelman Lane Hampshire, IL 60140
PA-20 Series; T.C. 1A4	SA278WE	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-20 Series; T.C. 1A4	SA509AL	addition of crankcase relief valve. Issued 11/16/73.	AL	75500	Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-20 Series; T.C. 1A4	SA542AL	Installation of leading edge cuff. Amended 3/4/77.	AL	27250	Crosswinds, Inc. 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20 Series; T.C. 1A4	SA671WE	BN-1 propeller spinner.	WE	75250	Raymond M. Stits 3665 Rubidoux Boulevard Riverside, CA 92502
PA-20 Series; T.C. 1A4	SA3217WE	Installation of George M. Adams DGA-2000 or Rodell RMI-2000 wheels and Rodell RMI-252 brakes. Amended 12/27/78.	WE	16860	Malcolm E. Rodell 23804 Pennsylvania Avenue Torrance, CA 90501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-20, PA-20-115, -20-135; T.C. 1A4	SA12AL	Installation of auxiliary fuel tank(s). Amended 2/7/75.	AL	75500	W.I. Stoddard Stoddard Aero Service 2350 East Fifth Avenue Anchorage, AK 99501
PA-20 Landplane, -20-115, -135; T.C. 1A4	SA25EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lycons, WI 53148
PA-20, -20S; T.C. 1A4	SA125AL	Installation of squared off wing tips and end plates. Amended 12/1/65.	AL	61640	Northland Aviation P.O. Box 3143 Fairbanks, AK 99702
PA-20-115, -135; T.C. 1A4	SA401AL	Conversion of 4-inch wheels and brakes to 6-inch wheels and brakes. Issued 8/19/70.	AL	45000	Jake Bryant Jake's Aircraft Salvage 3906 Barbara Drive Anchorage, AK 99503
PA-20, PA-20S, -20-115, -20S-115, -20-135, -20S-135, and these models modified by STC SA1-167 (150 HP Lycoming O-320 engine): T.C. 1A4	SA396GL	Installation of Aero Ski wheel replacement skis in accordance with the following: 1) Model M1800 and M2000 skis. 2) Model M3000H skis. Issued 4/18/80.	GL	02750	Aero Ski Manufacturing Co., Inc. Box 346 Park Rapids, MN 56470
PA-20, -20S, -20"115", -20S-"115", -20-"135", -20S-"135"; T.C. 1A4	SA879AL	Installation of fiberglass wing tips. Issued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-20, -20S, -20"115", -20S-"115", -20-"135", -20S-"115"; T.C. 1A4	SA479AL	Installation of fiberglass wing tips. Issued 5/7/79.	AL	76732	Ronald F. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-20, -20-115, -135, PA-20S, -20S-115, -135; T.C. 1A4	SA626AL	Install fiberglass wing tip assembly. Issued 3/21/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20, -115, -20S, -20S-115, -135, -20S-135; PA-22, -135, 22S-135, -150, 22S-150, -160, 22S-160, -108; PA-24, -250, -400, -260; PA28-140, -150, -160, -180, -235, S-160, S-180, R-180; PA-30; PA-32-260, -300, 32S-300; T.C. 1A4, 1A6, 1A15, 2A13, A1EA, A3SO	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South Holly Street Littleton, CO 80120
PA-20, PA-20"115", -"135", PA-20S"115", -"135", PA-22, 22-108, -135, -150, -160, 22S-135, -150, -160; T.C. 1A6	SA2142WE	Installation of DASCO heated pitot tube kit No. 2022-12.	WE	30129	Diversified Aviation Service Co. 20499 Santa Maria Avenue Castro Valley, CA 94546
PA-20, PA-20-"135": T.C. 1A4	SA635AL	Install Avco Lycoming O-320-A2B engine and Sensenich propeller. Issued 6/6/78.	EA	27250	Crosswinds STOL 8134 Lake Otis Parkway Anchorage, AK 99507
PA-20-115, -20-135, PA-22, -22-135, -150, -160, -180, PA-23, -23-160, PA-24 S/N 1 thru 1476, PA24-250 S/N 1 thru 1476: T.C. 1A4	SA71GL	PA-20's install BA4106 filter assembly, PA-22's install BA4016 filter assembly, PA-23's, -24 install BA-3110 filter assembly, PA-24-250 install BA-3210 Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialities Co. 9600 West 52nd Street Kenosha, WI 53140
PA-20-135: T.C. 1A4	SA1-28	McCauley fixed pitch MET-L-PROP Models 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine. Reissued 8/5/77.	GL	52720	McCauley Accessory Division Cessna Aircraft Company 1840 Howell Avenue Dayton, OH 45417
PA-20S, PA-20-115, -22-135; T.C. 1A4	SA118GL	Installation of Huron Aviation Products alternator, P/N 10346 and regulator, P/N 10316. Amended 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-20S, 20S-115, 20S-135, PA-20S*; T.C. 1A4	SA385AL	Installation of rudder centering device in lieu of ventral fin. Issued 7/21/70. *This approval includes PA20S models with Lycoming O-320, 150 hp engine installed per an appropriate STC.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-20S, -20S*, -115*, -135*; T.C. 1A4	SA387AL	Installation of McCauley 1A175GM8241 propeller. Issued 7/23/70. *Aircraft must be equipped with Edo 88-1650 floats and modified in accordance with STC SA1-167.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20S-115, -125; T.C. 1A4	SA388AL	Installation of Edo 88-1650 floats (Spec item 209(a)) when modified per STC SA1-167 and SA387AL. Issued 8/3/70.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503
PA-20, PA-22 Series; T.C. 1A6	SA1-132	24ST alclad on wings.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-20, PA-22 Series; T.C. 1A6	SA1-133	24ST alclad skin on flaps.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-20, PA-22 Series; T.C. 1A6	SA1-325	Replacement of fabric covering with metal skins, ailerons and flaps.	EA	72100	Skycraft Design, Inc. P.O. Box 67 West Trenton, NJ 08628
PA-20, PA-22 Series; T.C. 1A6	SA1-492	Metallizing of wing panel excluding aileron and flap.	NE	27770	Custom Aircraft Industries 30 Broad Street Pascoag, RI 02859
PA-20, PA-22; T.C. 1A4, 1A6	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
PA-20, PA-22 Series; T.C. 1A6	SA1487WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA1-22	McCauley fixed pitch propellers 1A170/GM7459 and 1A170/GM7457 with Lycoming O-320 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-23	McCauley fixed pitch propellers 1A170/GM7455 and 1A170/GM7453 with Lycoming O-290-D2 engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-90	McCauley fixed pitch MET-L-PROP 1A170/GM7452 and 1A170/GM7454 in aircraft with Lycoming O-290-D engine.	GL	52720	McCauley Industrial Corp. 1840 Howell Avenue Dayton, OH 45417
PA-22 Series; T.C. 1A6	SA1-108	69A110 gyro stabilizer.	GL	38175	Globe Industries, Inc. 125 Sunrise Place Dayton, OH 45401
PA-22 Series; T.C. 1A6	SA1-128	Dry vacuum pump 113A1 for counter-clockwise engine accessory drive and 113A2 for clockwise drive, or 10-113-1 and 10-113-2.	GL	66380	Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
PA-22 Series; T.C. 1A6	SA1-131	Dural angles and 24ST alclad skin on fuselage.	EA	06002	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
PA-22 Series; T.C. 1A6	SA1-255	Dart I-M turn control unit.	EA	61400	Navigation Devices, Inc. P.O. Box 1107 Binghamton, NY 13902
PA-22 Series; T.C. 1A6	SA1-275	Lycoming O-320 150 hp engine and Sensenich M74DM propeller, Piper PA-22-150 engine baffles, Harrison AP13SJ03 oil cooler.	EA	77082	Susquehanna Aero-Marine 513 Washington Boulevard Williamport, PA 17701
PA-22 Series; T.C. 1A6	SA1-337	Oil-free vacuum pump PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-22 Series; T.C. 1A6	SA1-386	Installation of heated pitot tube.	EA	34180	Federal Aviation Administration Engineering & Manufacturing Branch Federal Building, EA-210 JFK International Airport Jamaica, NY 11430
PA-22 Series; T.C. 1A6	SA3-77	Vertical fin plates attached to tip ribs of horizontal stabilizer for seaplane operation only.	GL	60092	Modern Die & Tool Company 227 Iron Street , Detroit, MI 48233
PA-22 Series; T.C. 1A6	SA3-143	Grimes D7080-12 rotating beacon on fuselage access panel.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, IL 62705

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-22 Series; T.C. 1A6	SA3-363	Installation of Doyn fiberglass wheel fairings. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, N.W. Atlanta, GA 30327
PA-22 Series; T.C. 1A6	SA3-382	Manually operated oil cooler shutter assembly.	CE	65020	Ken L. Potter 13831 Botts Road Grandview, MO 64030
PA-22 Series; T.C. 1A6	SA3-477	C2200 (hydraulically actuated) main and AWN1200A nose wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-22 Series; T.C. 1A6	SA3-494	C2200 (manually actuated) main and AWN1200A nose wheel -skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-22 Series; T.C. 1A6	SA3-631	Dacron cover.	GL	30518	Downer Aircraft Industries, Inc. Municipal Airport Alexandria, MN 56308
PA-22 Series; T.C. 1A6	SA3-639	Removal of rear door, operation with door removed, and reinstallation of door.	CE	50715	Lincoln Aviation Inst., Inc. P.O. Box 4168, Havelock Station Lincoln, NE 68529
PA-22 Series; T.C. 1A6	SA4-118	Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-22 Series; T.C. 1A6	SA4-222	Fiberglass covering.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
PA-22 Series; T.C. 1A6	SA4-298	Fuselage structural alterations and additions to provide for the installation of Fairchild Aviation aerial camera A5A or similar.	WE	62063	Pacific Aero Industries Municipal Airport San Jose, CA 95125
PA-22 Series; T.C. 1A6	SA4-303	"B" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-22 Series; T.C. 1A6	SA4-391	Fiberglass wheel fenders.	NW	85550	Art Whitaker Pearson Field Vancouver, WA 98660
PA-22 Series; T.C. 1A6	SA4-423	Autopilot. Reissued October 1973.	SW	17890	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-22 Series; T.C. 1A6	SA4-815	Lycoming O-320 engine and Sensenich M74DM propeller.	NW	53200	McKenzie Aircraft Repair 1300 North 27th Street Springfield, OR 97477
PA-22 Series; T.C. 1A6	SA4-871	Aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-22 Series; T.C. 1A6	SA4-903	Ceconite 101 covering of fuselage, wings, horizontal and vertical stabilizer, ailerons, flaps, rudder and elevator.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-22 Series; T.C. 1A6	SA4-938	Eonite covering on entire aircraft.	WE	52090	William G. Iott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
PA-22 Series; T.C. 1A6	SA4-998	Installation of wheel fairings. Reissued 2/9/71.	NW	12565	Aurora Air, Inc. d/b/a Madras Air Service Madras, OR 97741
PA-22 Series; T.C. 1A6	SA4-1346	Fiberglass cover on aircraft surfaces.	WE	49790	Quentin Laywell 5627 Lauretta Street San Diego, CA 92110
PA-22 Series; T.C. 1A6	SA4-1502	AB-6564 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-22 Series; T.C. 1A6	SA4-1587	Retractable wheel fairing on main landing gear.	WE	30708	Duce Aircraft Company R.R. 4, Box 711 Valley Center, CA 92082
PA-22 Series; T.C. 1A6	SA4-1621	Removal of left-hand door for parachute jumping and aerial photography.	WE	19856	Capitol Sky Park, Inc. Municipal Airport Sacramento, CA 95855
PA-22 Series; T.C. 1A6	SA5-30	Rear door removed.	AL	69740	Safeway Airways P.O. Box 1062, Merrill Field Anchorage, AK 99500

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-22 Series; T.C. 1A6	SA48AL	L1650A or L2000A skis.	AL	08125	Airglas Engineering P.O. Box 1254 Anchorage, AK 99502
PA-22 Series; T.C. 1A6	SA60CE	Model 1800 floats installed, Pee-Fay. Reissued 11/13/70.	EA	29998	Pee-Fay DeVore, Inc. 125 Mineola Avenue Roslyn Heights, NY 11577
PA-22 Series; T.C. 1A6	SA91AL	Change of brake system to disc type as used on PA-22-108 by changing brake parts.	AL	75500	Stoddard Aero SErvice 2550 East Fifth Avenue Anchorage, AK 99501
PA-22 Series; T.C. 1A6	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred P. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743
PA-22 Series; T.C. 1A6	SA143EA	Univair Aeromatic F-200H/0074E propeller on aircraft utilizing Lycoming O-320 or O-320-A1A engine.	EA	53160	George A. McIntosh 435 Van Cortlandt Park Avenue Yonkers, NY 10705
PA-22 Series; T.C. 1A6	SA145CE	APU receptacle under the right front seat to the right of battery box.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis, MO 63155
PA-22 Series; T.C. 1A6	SA157CE	Jump seat baggage compartments.	CE	14270	Baker's Flying Service, Inc. 1025 Lou Holland Drive Municipal Airport Kansas City, MO 64108
PA-22 Series; T.C. 1A6	SA247SO	Removal of door during operation of aircraft.	SO	43260	W.E. Huckabee, Jr. 424 South Green Street Thomaston, GA 30286
PA-22 Series; T.C. 1A6	SA314SO	Lycoming O-290-D engine.	SO	54450	M & M Flyers Bessemer, AL 35020
PA-22 Series; T.C. 1A6	SA447WE	Torso tank 61900 or 64200. Amended 10/18/65.	WE	55060	Mark XII, Inc. 1115 Border Avenue Torrance, CA 90510
PA-22 Series; T.C. 1A6	SA448CE	Prestolite ALK-5000 alternator.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
PA-22 Series; T.C. 1A6	SA461WE	Removal of right-hand door for parachute jumping and aerial photography operations.	NW	42138	Hillsboro Aviation Hillsboro, OR 97123
PA-22 Series; T.C. 1A6	SA481WE	Lycoming O-320-A1A engine and Sensenich M74DM propeller.	RM	47758	Kensair Corporation P.O. Box 332 County Airport Broomfield, CO 80020
PA-22 series; T.C. 1A6	SA666WE	Edo 88-1650 floats with Harrison oil cooler AP13SJ03-01 or AP12CU03-01, bottom engine cowl assembly 13159-8, side engine cowl 14237, reinforced fuselage 12480 and Sensenich M74DM or M76AM-2 propellers.	NW	36002	Floathaven Seaplane Base 2095 South Lake Whatcom Boulevard Bellingham, WA 98225
PA-22 Series; T.C. 1A6	SA819SW	Extended wing and fuselage.	SW	71776	Simpson Aviation Company P.O. Box 126 Gilliam, IA 71029
PA-22 Series; T.C. 1A6	SA1360CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, MO 66103
PA-22, PA-22-108, -135, -150, -22S-150, -22-160, -22S-160; T.C. 1A6 t+1	SA1-604	Installation of Aerostat external power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-22, -22-108 (Normal Category Only - All Models), -22-135, -150, -160; T.C. 1A6	SA45RM	Conversion from tri-cycle landing gear (nose wheel) to conventional landing gear (tail wheel). Amended 3/13/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-22, PA-22-108, -135, -150, -160; T.C. 1A6	SA232GL	Installation of Huron Aviation Products alternator, P/N 10346, and regulator, P/N 10316. Issued 3/23/78.	GL	62270	Robert E. Pampe 301 Forest Hills Drive Huron, OH 44839
PA-22, -22-108, -22-135, -22S-135, -22-150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA395GL	Installation of Aero Ski wheel in accordance with the following: 1) Model M180 and M2000 skis 2) Model M3000H skis. Issued 4/18/80.	GL	02750	Aero Ski Manufacturing Co., Inc. Box 346 Park Rapids, MN 56470

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA625AL	Install fiberglass wing tip assembly. Issued 3/27/78.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-22, -22-108, -22-135, -22-150, -22-160, -22S-150, -22S-160; T.C. 2A6	SA536AL	Installation of auxiliary fuel tanks. Amended 2/7/75.	AL	75500	W.L. Stoddard Stoddard Aero Service 2550 East Fifth Avenue Anchorage, AK 99501
PA-22, -22-135, -150, -160; T.C. 1A6	SA26EA	Conversion of aircraft for parachute jumping and aerial photography. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-108, -135, -22S-135, -22-150, -22S-150, -22-160, -22S-160; T.C. 1A6	SA40EA	Wet-to-dry vacuum pump conversion kit 300-1. Reissued and amended 8/6/75.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-22, -22-108 (Normal Category only - all models), -22-135, -22-150, -22-160; T.C. 1A6	SA181RM	Installation of Lycoming Model O-360-A4A engine and Sensenich Model 76EM8-60 propeller. Issued 8/2/79.	RM	50500	Light Plane Components 509 Buckley Road Aurora, CO 80011
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22, -22-108, -135, -150, -160, PA-22S-135, -150, -160; T.C. 1A6	SA453AL	Installation of fiberglass wing tips. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-108; T.C. 1A6	SA847EA	Installation of Lycoming O-320-A (150 hp) or O-320-B (160 hp) engine. Amended 4/7/78.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-108, -135, -150, PA-23, -23-250, PA-24, -24-250, -260, -400, PA-28-140, -150, -160, -180, -235, PA-30; T.C. 1A6, 1A10, 1A15, 2A13, A1EA	SA1202WE	Installation of control position indicator (CPI) system. Reissued 2/18/72.	NW	76800	Sundstrand Data Control, Inc. Sub. Sundstrand Corporation Overlake Industrial Park Redmond, WA 98052
PA-22, -22-135; T.C. 1A6	SA1-274	Installation of Lycoming O-320 (150 hp) series engine and Sensenich M74DM propeller. Reissued 9/7/76.	GL	84390	Wag-Aero, Inc. Box 181 1216 North Road Lyons, WI 53148
PA-22-135; T.C. 1A6	SA3-709	Install Piper control modification kit, P/N 754-174.	GL	51770	Richard E. Lloyd Lloyd Flying Service Schaumburg Airport, Box 79B Roselle, IL 60172
PA-22-108, -135, -150, -160 (landplane only - normal category only): T.C. 1A6	SA4-1263	Installation of conventional landing gear. Reissued and amended 12/4/79.	WE	52543	Lucas Aircraft 1125 Terrace Drive Napa, CA 94558
PA-22-150; T.C. 1A6	SA545AL	Installation of leading edge cuff. Reissued 2/20/76.	AL	20512	Charles C. Center 8134 Lake Otis Parkway Anchorage, AK 99507
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	CE	42051	David M. Hendrick Star Route, Box 207B Buffalo, MO 65622 AND
PA-22-150; T.C. 1A6	SA557AL	Installation of left hand front door. Reissued 5/7/79.	AL	76732	Ronald E. Sullivan Star Route A, Box 1549 Anchorage, AK 99507
PA-22-150; T.C. 1A6	SA703CE	Install aileron and wing fences and booster tips per STC SA573SW. Issued 5/19/70.	GL	22210	Dr. Edward W. Chrencik 29 9th Avenue North Hopkins, MN 55343
PA-22-150, -160, -22S-160; T.C. 1A6	SA936NW	Lycoming O-360-A1A, McCauley 1A200-FA8248 propeller spinner, engine mount, exhaust system, modified landing gear or Edo 248-2440 floats, modified cowl. Issued 5/16/80.	NW	28847	Milo DeAngeles 5080 Glen Carin Drive N. Burnaby, B.C. Canada
PA-22-150, -160, -22S-160; T.C. 1A6	SA1027NW	Auxiliary fuel tanks. Reissued 11/10/80.	NW	28847	Milo DeAngeles 5080 Glen Carin Drive N. Burnaby, B.C. Canada
PA-22S-150; T.C. 1A6	SA297AL	Installation of McCauley 1A175 GM8241 propeller.	AL	17000	M.R. Borer Aircraft Services 1307 West 39th Place Anchorage, AK 99503

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-22-160; T.C. 1A6	SA95NW	Installation of Lycoming O-360-A1A engine, McCauley 1A200-FA8248 propeller, and associates sub-systems. Issued 3/11/74.	NW	61680	Northwest Aero Aircraft Services 2036 West Bakerview Road Bellingham, WA 98225
PA-22, PA-23, PA-24 Series; T.C. 1A6, 1A10, 1A15	SA4-925	Magnetic flight director 2000.	WE	23030	Clarkson Company Paul Spur, AZ 85642
PA-23 Series; T.C. 1A10	SA1-5	Unfeathering system change to HC-82XL-2/7636D-4 or HC-A2XL-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
PA-23 Series; T.C. 1A10	SA1-6	Unfeathering system change to HC-82XG-2/7636D-4 propellers.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 Piqua, OH 45356
PA-23 Series; T.C. 1A10	SA1-28	Radio rack limited to 30 pounds of radio equipment.	GL	03600	Airborne Communications, Inc. Lunken Airport Cincinnati, OH 45275
PA-23 Series; T.C. 1A10	SA1-53	Conversion to Goodyear 6.50-8 wheels (9531319) and brakes (9531779).	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-103	Radio-shelf.	GL	72498	Skyways, Inc. P.O. Box 175 Vandalia, OH 45377
PA-23 Series; T.C. 1A10	SA1-117	Propeller anti-icing kit.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA1-120	F-300 automatic pilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
PA-23 Series; T.C. 1A10	SA1-137	Installation of Tactair T-3 automatic pilot and optional installation of Tactair AH-1 altitude hold device (for use with Tactair T-3 autopilot). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA1-169	Reinforcement of floor structure between fuselage station 91-1/2 and 123-3/4 and provision for tie-down facilities.	GL	60485	A.E. Muhlhauser 1602 Emerson Avenue (N.C.H.) Cincinnati, OH 45275
PA-23 Series; T.C. 1A10	SA1-177	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-399	Oil-free vacuum PA-201.	GL	11880	Associate Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-23 Series; T.C. 1A10	SA1-468	Six or 13 quart propeller anti-icing kit WAP-101A, revision 2.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA1-484	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-485	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-534	Lightweight reservoir type deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA1-548	SP-3 autopilot EB2597034.	EA	74590	Sperry Rand Corporation MacArthur Field Ronkonkoma, NY 11779
PA-23 Series; T.C. 1A10	SA1-586	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-23 Series; T.C. 1A10	SA3-94	Narco 1016 antenna and/or remote compass transmitter, equipment shelf, oxygen bottle mounting.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA3-158	Radio power pack on bulkhead forward of instrument panel.	GL	19850	Capitol Aviation, Inc. Capitol Airport Springfield, IL 62705
PA-23 Series; T.C. 1A10	SA3-334	Installation of aerial camera provisions. Reissued 1/31/80.	SW	26230	Cooper Airmotive Aircraft Services 3300 Love Field Drive Dallas, TX 75235
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-handy hydrotrim aileron trim device.	GL	30465	Kingsley A. Doutt 115 West Maple Street Alpena, MI 49707 AND
PA-23 Series; T.C. 1A10	SA3-397	Petch Manufacturing Company right or left-hand hydrotrim aileron trim device.	GL	64262	Charles L. Petch Hubbard Lake, MI 49747
PA-23 Series; T.C. 1A10	SA3-509	T-2B autopilot with or without altitude control and approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-23 Series; T.C. 1A10	SA3-564	Propeller unfeathering accumulator.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA3-641	Cabin air temperature control system.	GL	82500	Vap-Air Division Vapor Corporation 6444 West Howard Street Chicago, IL 60607
PA-23 Series; T.C. 1A10	SA3-644	Adams Rite 2302 rev. C-2 handle on inside of cabin door.	CE	65301	Product Development Group 2522 East Douglas Wichita, KS 67202
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2B/7666-4 propellers and increase gross weight to 3,684 lbs.	CE	56868	Galen D. Means 847 Watson Lane Wichita, KS 67201 AND
PA-23 Series; T.C. 1A10	SA3-728	Lycoming O-360-AID engines with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2B/7666-4 propellers and increase gross weight to 3,684 lbs.	SW	67016	Jackson M. Reed 607 North Peters Norman, OK 73069
PA-23 Series; T.C. 1A10	SA4-299	Windows at station 144.	WE	39877	Hamilton Aircraft Company, Inc. 6501 South Park Avenue Tucson, AZ 85706
PA-23 Series; T.C. 1A10	SA4-345	"R" Arcon.	WE	60200	Motorola Aviation Electronics, Inc. 3302 Airport Avenue Santa Monica, CA 90406
PA-23 Series; T.C. 1A10	SA4-522	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA4-652	Full flow aerofilter kit 3-1A101.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-23 Series; T.C. 1A10	SA4-783	Lycoming 150 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-23 Series; T.C. 1A10	SA4-994	Installation of Firestone Model DFA-233 wheel assemblies, Model CFA-299 brake assemblies and 6.50x8 6-ply tires.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1016	Lycoming 160 hp O-340-A1A engine and Hartzell HC82XG-2B/8433-12 propeller.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-23 Series; T.C. 1A10	SA4-1131	SP-3 autopilot, less altitude and navigation hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85000
PA-23 Series; T.C. 1A10	SA4-1166	Installation of Firestone Model DFA-180 wheel.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501
PA-23 Series; T.C. 1A10	SA4-1602	Dorsal fin.	RM	60280	Mountain States Aviation, Inc. Stapleton Field Denver, CO 80202
PA-23 Series; T.C. 1A10	SA2WE	Fuel pressure warning lights.	WE	66250	Pajay Corporation 2602 East Wardlow Road Long Beach, CA 90807

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA47CE	Governor 210413.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23 Series; T.C. 1A10	SA65EA	One Aerojet-General 15NS-250 aircraft rocket engine on underside of fuselage on airplane centerline aft of main spar wing and relocation of cabin air intake scoop assembly.	EA	30004	DeVore Engineering Service 41-27 Bell Boulevard Bayside, NY 11361
PA-23 Series; T.C. 1A10	SA69SW	Extended nose with baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA100SW	Automatic pilot AK114.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA114SW	Combustion monitor.	EA	60100	Monitair Corporation Ramapo Valley Airport Spring Valley, NY 10977
PA-23 Series; T.C. 1A10	SA140SW	Cabin window addition.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA172EA	Reinforcement of rearmost seat and installation of additional safety belt.	EA	16804	Walter F. Hoffman, Jr. Birchwood Lodges & Cottages East Stroudsburg, PA 18301
PA-23 Series; T.C. 1A10	SA202SO	Fyr-Fyter 23-4, 2 1/2 lb., dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA219EA	Installation of Katz integrated flight indicator Model KIFI-2 or KIFI-2A. Amended 5/21/69.	NE	36300	Forest City Aviation Services, Inc. 749 Congress Street Portland, ME 04102
PA-23 Series; T.C. 1A10	SA226EA	Added structure aft of cabin area.	EA	67000	Reding Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23 Series; T.C. 1A10	SA232EA	Installation of Tactair omni lock Model OL-1 and optional installation of Tactair localizer adapter Model LA-1 (for use with Tactair model omni lock Model OL-1). Reissued 8/7/72.	GL	14124	Avionics, Inc. Terminal Building Lunken Airport Cincinnati, OH 45226
PA-23 Series; T.C. 1A10	SA242SO	Two-place couch.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA243EA	13-quart propeller anti-icing kit WAP-102.	NE	86000	E.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-23 Series; T.C. 1A10	SA244SO	PA-23-250 wing root and nacelle fairings.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-23 Series; T.C. 1A10	SA250WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA266SO	Modification of fuel cap 16097-00 by making a new cover and enlarging the lower vent hole. Rework fuel cell filler neck door 19049-06 by putting a spring loading vent in the door to be used as auxiliary vent during icing conditions.	SO	12700	Avco Corporation Aerospace Structures Division Nashville, TN 37202
PA-23 Series; T.C. 1A10	SA268WE	Sixth seat and emergency exit.	WE	60095	Monarch Aviation Associates P.O. Box 527 Monterey, CA 93940
PA-23 Series; T.C. 1A10	SA280SW	Forward fuselage section and long nose 30542-02.	SW	79794	Tulsa Airmotive, Inc. P.O. Box 176 Broken Arrow, OK 74012
PA-23 Series; T.C. 1A10	SA309WE	Non-icing fuel tank vents.	WE	06750	Aircraft Tank Service, Inc. 1201 Cohasset Street Burbank, CA 91504

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA311SW	Alternate static source.	SW	71800	Sinclair Oil & Gas Company Aviation Department, Box 521 Tulsa, OK 74101
PA-23 Series; T.C. 1A10	SA319EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
PA-23 Series; T.C. 1A10	SA337EA	Conversion of aircraft electrical system to 24 volt.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23 Series; T.C. 1A10	SA339SW	Electrical hydraulic pump. Reissued 9/20/77.	SW	90142	The Zee Company, Inc. 123 Braniff Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA363SW	Pitch trim system AK128.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA371SW	Fiberglass nose cone.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA372EA	Automatic flight control system.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-23 Series; T.C. 1A10	SA376WE	Left and right third window.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA387WE	Sixth seat and escape hatch.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA394WE	Replacement engine nose cowls.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA395WE	Lycoming O-360-A1A engines and Hartzell HC-C2YK-2R/7666-2 propellers.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA412WE	One-piece windshield.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA417SW	Rear baggage compartment.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA423SW	Fiberglass landing gear doors.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA461SW	Ramshorn type control wheel.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA462SW	One-piece windshield.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA463SW	Landing gear wheel well doors.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA465SW	Pitch trim system AK148.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA471CE	Dorsal fin.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23 Series; T.C. 1A10	SA476SW	Pitch trim system AK151.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA484SW	Large baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA497SW	Fiberglass engine nose cowl.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA498SW	Dual brakes.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA499SW	Engine nacelle and fuselage wing root fairings.	SW	70750	Seguin Aviation Route 1, Box 225A Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA504WE	11016 fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA523SW	Automatic trim system AK165.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA539WE	Turbosupercharged Lycoming IO-540-C1B5 or -C1C5 engine. Amended 6/14/66.	WE	66250	Rajay Corporation 2062 East Wardlow Raod Long Beach, CA 90807
PA-23 Series; T.C. 1A10	SA540SW	Piper auto-control III Model AK162 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA551WE	Installation of Brittain Model B-4 flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA557SW	Fiberglass nose cone.	SW	44930	J & G Aero Company P.O. Box 3031 Tyler, TX 75701
PA-23 Series; T.C. 1A10	SA566SW	AK184 automatic flight system, AK185 stabilizer, and AK188 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA574SW	Rear baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA580SW	Modified engine mounts.	SW	67650	RFB Company, Inc. Chandler Field Purcell, OK 73080
PA-23 Series; T.C. 1A10	SA590SW	Gross weight increased.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA597SW	Extended nose with baggage compartment. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA598SW	Wheel well doors. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA599SW	Fiberglass engine nose cowls.	SW	59500	James W. Miller 6517 Moss Oak San Antonio, TX 78229
PA-23 Series; T.C. 1A10	SA600SW	Nacelle and wing root fairings. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA605SW	Rear baggage door.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA612SW	Square wing tips. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA613SW	Dorsal fin and square tip fin and rudder. Amended 7/31/68.	SW	50500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA614WE	B-4 flight control system including PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA615WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301, or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A0	SA616WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA617WE	Pneumatic pitch assist PC-1 and altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA636SW	Modified nose, gear doors, nacelle fairings, and wing tips.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA671SW	Dorsal fin and square rudder.	SW	70750	Seguin Aviation Route 1, Box 225 Seguin, TX 78155
PA-23 Series; T.C. 1A10	SA697SW	One-piece windshield. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA698SW	Rear picture window.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78114
PA-23 Series; T.C. 1A10	SA747SW	Pitch trim AK228 (manual).	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23 Series; T.C. 1A10	SA764WE	Aztec "B" nose section.	RM	08315	Airport Development Corp. 5120 West Rowland Avenue Littleton, CO 80120
PA-23 Series; T.C. 1A10	SA774SW	Franklin 6A-350-C1 engines, McCauley 2AF31C10/84SF-8 propeller increase gross weight 3675 lbs. takeoff, 3500 lbs. landing. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA803SW	Dual brakes. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA824WE	Dorsal fin.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-23 Series; T.C. 1A10	SA852WE	Turbosupercharged Lycoming O-540-A1B5, -A1D5, or -A3D5 engines (S/N's 27-1 thru 27-2504).	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA867SW	Lycoming O-540-A1D5 engines.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-23 Series; T.C. 1A10	SA882EA	Installation of supplemental strobe light Grimes P/N 30-0437-100. Amended 5/2/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23 Series; T.C. 1A10	SA909WE	Turbosupercharged Lycoming IO-540-J4A5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA953SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23 Series; T.C. 1A10	SA978WE	Turbosupercharged Lycoming IO-540-C4B5 engines.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
PA-23 Series; T.C. 1A10	SA1076CE	Installation of Halon 1301 cabin fire extinguishing system and engine nacelle fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64105
PA-23 Series; T.C. 1A10	SA1348WE	B-4 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA1480WE	Installation of an integral 24 gallon auxiliary fuel tank in each wing tip.	WE	58500	Met-Co-Aire 3848 Campus Drive Newport Beach, CA 92660

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23 Series; T.C. 1A10	SA1486WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23 Series; T.C. 1A10	SA2914WE	Installation of improved rudder trim tab actuating rod. Issued 8/13/74.	WE	13800	Aviation Research Corporation P.O. Box 718 Santa Ynez, CA 93460
PA-23, -23-160; T.C. 1A10	SA4-1637	Installation of turbosupercharged Lycoming O-320-A or -B series engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23, -23-160; T.C. 1A10	SA2CE	Installation of Doyn Model 1600 dorsal fin. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23, PA-23-160; T.C. 1A10	SA285CE	Lycoming IO-360-B1B engines and Hartzell HC-C2YK-2RA/7666A-2 propellers. Gross weight increase to 3,684 lbs. on PA-23 and to 4,000 lbs. on PA-23-160. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23, -23-160; T.C. 1A10	SA802CE	Alter tip of vertical fin and rudder. Amended August 1976.	CE	60174	J.J. Morelli Route 1, Box 138 Platte City, MO 64079
PA-23, -23-160; T.C. 1A10	SA897SW	Fiberglass propeller spinners. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA898SW	Revised engine cowling. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23, -23-160; T.C. 1A10	SA1260WE	Installation of turbosupercharged Lycoming O-360-A1A or A1D engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23, -23-160; T.C. 1A10	SA1306SW	Lycoming IO-360-C1C engines with Hartzell HC-C2YK-2/C7666A-4 propellers with gross weight increase. Issued 5/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23, -23-160; T.C. 1A10	SA2793SW	Rudder hinge reinforcing bracket. Issued 6/7/78.	SW	70750	Seguin Aviation, Inc. 2075 Highway 46 Seguin, TX 78155
PA-23, -23-160; T.C. 1A10	SA3099SW-D	Mitchell automatic flight system AK587 consisting of Century I autopilot with optional omni tracker. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3100SW-D	Mitchell automatic flight system AK588 consisting of Century III with optional radio coupler and glide slope coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160; T.C. 1A10	SA3101SW-D	Mitchell automatic flight system AK586 consisting of Century IIB autopilot with optional radio coupler. Issued 1/14/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23, -23-160, -23-235, -23-250, PA-24, -24-250, -24-400, PA-28-150, -28-160, -28-180, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA135EA	Installation of engine exhaust combustion monitor. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, PA-23-235, PA-23-250; T.C. 1A10	SA136EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-23, PA-23-160, -235, -250; T.C. 1A10	SA236CE	High intensity wing tip lights Model B, tail light Model C, with or without high intensity fuselage lights. Reissued 10/17/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-23, -23-160, -23-235; T.C. 1A10	SA317EA	Radome kit No. 2025R-B for Bendix RDR-100 or RDR-110 series radar systems with 12-inch antenna per Chamberlain installation. Reissued 3/21/74.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23, -23-160, -235, PA-25; T.C. 1A10	SA362SW	Rear baggage compartment. Reissued 4/24/79.	SW	70750	Seguin Aviation 2075 Highway 46 Seguin, TX 78155
PA-23, -160, -235; T.C. 1A10	SA398CE	Install Hoskins twilighter Mk III supplemental lighting system consisting of Model F wing lights with Model P or K (dual) tail light. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
PA-23, 23-160, 23-235, 23-250; PA-24, -24-250, -260, -400; PA-31, -31P; T.C. A8EA, 1A10, 1A15	SA660WE	Installation of HRD-type fire extinguishing system. Amended 7/11/77.	WE	43190	H T L Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91015
PA-23, -160, -235; T.C. 1A10	SA894SW	Nacelle saddleback. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
PA-23-160, -235, -250; PA-30, PA-39; T.C. 1A10, A1EA	SA890EA	Installation of Grimes three light strobe kit P/N 34-0101-2 as supplemental lighting. Issued 11/4/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23, -23-160, -23-235, -23-250, -E23-250, PA-24, -24-250, -24-260, -24-400, PA-28-140, -28-150, -28-160, -28-180, -28-235, -28S-160, -28S-180, -28R-180, -28R-200, PA-30, PA-39, PA-32-260, -32-300, -32S-300, PA-30, PA-39; T.C. 1A10, 1A15, 2A13, A1EA, A3SO	SA917EA	Installation of Grimes Manufacturing Co. aviation white anti-collision strobe light system two light or three light series 555 for wing tips and tail, P/N 30-0555-( ). Amended 11/30/77.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-23, -160, -235, -250; PA-24-180, -250, -400; *PA-28-180, -150, -160, -180, -235; *PA-31; T.C. 1A10, 2A13, A8EA	SA1290WE	Installation of "Quazar" high intensity supplemental exterior flashing lights. Amended 11/25/69. *Approved anti-collision light system is required.	RM	66000	Radair, Inc. 5665 South Curtis Street Littleton, CO 80120
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327 AND
PA-23-160; T.C. 1A10	SA29CE	Lycoming O-360-A1D engine with Hartzell HC-92ZK-2B/8447-12A or HC-C2YK-2R/7666-4 propellers. Reissued 3/9/79.	SW	67016	Jackson M. Reed 607 North Peters Street Norman, OK 73069
PA-23-160; T.C. 1A10	SA47SO	Installation of one-piece instrument panel.	SW	68145	Riley International Corporation 6211 West Northwest Highway Dallas, TX 75225
PA-23-160; T.C. 1A10	SA68NW	Installation of cargo door on right side of fuselage. Issued 10/30/73.	SO	70280	Elbridge P. Sawyer P.O. Box 148 Dayton, OH 37321
PA-23-160, -235, -250; T.C. 1A10	SA162SW	Cabin emergency exit window and sixth seat. Reissued 10/3/78.	SW	70750	Seguin Aviation, Inc. 2075 Highway 46 Seguin, TX 78155
PA-23-160; T.C. 1A10	SA272CE	Installation of Lycoming IO-360-B1A engines and Hartzell HC-C2YK-2RA/7666A-2 propellers. Gross weight increase to 4000 lbs. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-235; T.C. 2A10	SA1136SW	Fiberglass fuselage shell.	SW	30750	Dusters & Sprayers Supply, Inc. P.O. Box 766 Chickasha, OK 73018
PA-23-235; T.C. 2A10	SA1205SW	Manual electric trim AK268. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235; T.C. 2A10	SA1746WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-23-235; T.C. 2A10	SA1847WE	Installation of Brittain up-command signal adapter kit. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-235, -250; T.C. 1A10	SA495CE	Installation of Hartzell Model HC-A3XF-2B/7636D-4 three-bladed propellers.	CE	30600	Doyn Aircraft, Inc. P.O. Box 18130 Wichita, KS 67218
PA-23-235, PA-23-250; T.C. 1A10	SA530WE	Installation of Rajay turbosupercharged Lycoming IO-540-C1B5 or C1C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23-235, -23-250; T.C. 1A10	SA1315SW	Dorsal fin. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-235, -23-250; T.C. 1A10	SA1361CE	Chrome plated brake disc installation. Issued 3/6/78.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA155EA	Install B.F. Goodrich pneumatic de-icing system. Amended 8/10/79.	GL	38500	B.F. Goodrich Engineered Systems Company 500 South Main Street Akron, OH 44318
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA921SW	Mitchell automatic flight system AK242 consisting of Century III autopilot with optional automatic pitch trim and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1091SW	Mitchell automatic flight director system FD/AP 282-184 consisting of flight director, automatic pilot, auto-flite AK 185.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, -23-250, -E23-50, Serial Nos. 27-1 thru 27-4573; T.C. 1A10	SA1124EA	Installation of enlarged cargo door. Reissued 8/25/78.	EA	26683	Courtesy Air Service, Inc. P.O. Box 561 Warren County Airport Glen Falls, NY 12801
PA-23-235, -23-250 (S/N 271 thru 27-7554172), PA-E23-250 (S/N 27-2505 thru 27-7554172), PA-23-250 (Model "F") (S/N 27-7654001 and up); T.C. 1A10	SA1126EA	Installation of DeVore vertical tail floodlights on upper surface of stabilator. Reissued 9/28/78.	SW	30002	DeVore Aviation Corporation Suite B 6104 Kircher Street Albuquerque, NM 87109
PA-23-235, 23-250, PA-F23-250; T.C. 1A10	SA1262SW	Mitchell automatic flight system FD282-242 consisting of flight director/autopilot, and automatic pitch trim. Issued 2/8/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1276SW	Mitchell automatic flight system AK332, consisting of Piper autoflite II and omni tracker system. Issued 3/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA1377SW	Mitchell automatic flight system AK340, consisting of Century I and optional tracker. Issued 10/14/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-E23-250; T.C. 1A10	SA2442WE	Installation of dual hydraulic pump (New Eastern Industries hydraulic pump 1233-FnG Type 311 on right engine; pump 1233-HnG Type 311 in lieu of existing pump on left engine). Amended 3/29/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, 23-250, PA-F23-250;	SA2445WE	Installation of recontoured inboard wing leading edge, stall fences, drooped ailerons in flaps down mode, rudder anti-servo tab system, and optional raked wing tips. Issued 11/16/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-23-235, -23-250, PA-E23-250; T.C. 1A10	SA3133SW-D	Mitchell automatic flight system AK599, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/7/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-235, 23-250, PA-F23-250; T.C. 1A10	SA3137SW-D	Mitchell automatic flight system AK611 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-235, -250; PA-24, -24-250, -260; PA-25, -25-235, -25-260; PA-28-150, -28-160, -28-180, -28-235; T.C. 1A10, 1A15, 2A8, 2A13	SA693CE	Replace existing engine induction air filter with AC Spark Plug Division filter.	GL	00750	AC Spark Plug Division General Motors Corporation Flint, MI 48556
PA-23-250: T.C. 1A10	SA11NE	Installation of laser sensor system. Issued 10/31/75.	NE	33485	Environmental Research and Technology, Inc. 696 Virginia Road Concord, MA 01742
PA-23-250: T.C. 1A10	SA39RM	Installation of freon air-conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
PA-23-250: T.C. 1A10	SA164CE	Installation of Hartzell HC-A3XK-2B/7636D-4 propellers and C-2513-2P spinners. Reissued 3/9/78.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-250: T.C. 1A10	SA179CE	Installation of the following: Lycoming IO-540-A1A5 or IO-540-G1A5 engines, Hartzell HC-A3XK-2C/8433-10 or HC-A3XK-2B/7636D-4 propellers. Reissued 3/9/79.	SO	47999	KWAD Company 4530 Jettridge Drive, NW Atlanta, GA 30327
PA-23-250: T.C. 1A10	SA205GL	Installation of Aerosonic totalize fuel flow indication system in lieu of fuel pressure gages. Issued 12/19/77.	GL	73190	Roger Smith Aircraft Sales, Inc. Aurora Municipal Airport Sugar Grove, IL 60554
PA-23-250: T.C. 1A10	SA335CE	Installation of Honeywell H-14 YG-391 autopilot. Amended 9/9/66.	GL	42250	Honeywell, Inc. East 70th & 34th Avenue South Wold-Chamberlain Field Minneapolis, MN 55450
PA-23-250, S/N 27-2000 and subsequent: T.C. 1A10	SA427GL	Installation of Tull microwave landing system airborne equipment. Issued 7/23/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
PA-23-250: T.C. 1A10	SA429SO	Installation of Bendix Model FCS-80 automatic flight control system with manual electric pitch trim and flight director indicator. Amended 6/2/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250: T.C. 1A10	SA441NW	Installation of 3-bladed propeller and Piper Navajo spinner. Amended 1/12/78.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
PA-23-250: T.C. 1A10	SA475GL	Install a Foster Airdata RNAV 612 area navigation system. Issued 11/25/80.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
PA-23-250: T.C. 1A10	SA480EA	Installation of photographic equipment.	NE	71400	James W. Sewall Company 147 Center Street Old Town, ME 04468
PA-23-250: T.C. 1A10	SA497SO	Installation of Bendix WLS-880 wings leveler system with and without Bendix FCS-810 automatic flight control system. Issued 11/8/71.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250: T.C. 1A10	SA590SO	Installation of M-4D automatic flight control system including optional manual electric pitch trim and optional flight director system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250: T.C. 1A10	SA591SO	Installation of Bendix RNS-3400 area navigation system. Issued May 1974.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250 (S/N 27-2505 and up): T.C. 1A10	SA621EA	Installation of a U.S. mail cargo kit. Amended 4/15/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-23-250 (Aztec C, D, E): T.C. 1A10	SA663CE	Installation of Goodyear ice-guard de-icing kit Nos. 320-642. Reissued 4/17/72.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250: T.C. 1A10	SA667CE	Installation of wing and empennage deicing boot. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-250; T.C. 1A10	SA668CE	Installation of wing and empennage deicing all weather antenna. Amended 1/12/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
PA-23-250; T.C. 1A10	SA688CE	Installation of propeller unfeathering system. Reissued 7/27/78.	GL	07503	AiResearch Aviation Company Capitol Airport Springfield, IL 62705
PA-23-250; T.C. 1A10	SA850EA	Installation of radome kit 4025KX. Amended 9/12/77.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250; T.C. 1A10	SA922SO	Installation of Piper PA-23-250 "E" model fuselage nose. Amended 6/30/77.	SO	41400	Hawthorne Aviation Municipal Airport P.O. Box 10005 Charleston, SC 29411
PA-23-250 (Aztec F) defined by item VI in TCDS 1A10; T.C. 1A10	SA952SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 8/18/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-23-250; T.C. 1A10	SA1022CE	Installation of King Model KGS-55 pictorial navigation system (compass), with optional KA-52 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1027CE	Installation of KCS-55 pictorial navigation system (compass), with optional KA-57 autopilot adapter. Issued June 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250 (Landplanes) (S/Ns 27-2505 thru 27-74-05471); T.C. 1A10	SA1063CE	installation of two Hartzell HC-E3YR-2AF/FC7663-2R propellers and C-3269A or 82D3273P spinners. Reissued August 1976.	SW	03034	AeroStol Company 5104 Rector Fort Worth, TX 76133
PA-23-250; T.C. 1A10	SA1102CE	Installation of AP-107, 2-axis autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250; T.C. 1A10	SA1103CE	Installation of AP-107 autopilot system and interface with Collins 329A-4V indicator. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-23-250; T.C. 1A10	SA1163CE	Installation of KFC-200 automatic flight control system. Amended 6/1/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1314SW	Fiberglass extended nose. Issued 5/26/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246
PA-23-250; T.C. 1A10	SA1390CE	Install 1/4-inch plywood flooring over existing floor, remove 4 passenger seats, install reinforcement tubing. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250; T.C. 1A10	SA1391CE	Cutting and reattaching the left and right lower engine cowling with AN 2700-4 cam locks. Amended 8/6/79.	CE	79430	Tribal Air/Communications, Inc. P.O. Box 370 Grant, NE 69140
PA-23-250 (S/N 27-2505 and up); T.C. 1A10	SA1444WE	Installation of Edo Model 679-4930 floats and addition of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663
PA-23-250; T.C. 1A10	SA1554CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-23-250; T.C. 1A10	SA1810WE	Installation of left-hand passenger entry door. Reissued 12/26/68.	NW	57700	Melridge Aviation Company P.O. Box 1508 Pearson Airpark Vancouver, WA 98663
PA-23-250; T.C. 1A10	SA3209SW-D	Mitchell automatic flight system, Piper altimatic X autopilot, AK684 or AK684FD, Piper altimatic X flight director autopilot with remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-250, Serial Nos. 27-2000 and up; T.C. 1A10	SA3823WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 4/28/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-23-250 (carbureted engine only); T.C. 1A10	SA4151WE	Installation of Silver Instruments fueltron IIIG-C or IIIP-C digital fuel flow and totalizer system. Issued 5/6/80.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-23-250 (S/Ns 27-2000 and up), -E23-250; T.C. 1A10	SA619EA	Installation of radome kit 3061X for Bendix RDR-100 or RDR-110. Amended 3/11/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-23-250, -E23-250, PA-31, -31-325, -31-350; T.C. 1A10	SA20GL	Installation of Woodward Type II electronic propeller synchronizer system. Amended 1/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA25GL	Installation of propeller unfeathering accumulator system on light twin-engine airplanes. Issued 6/26/73.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA51GL	Install Foster Airdata Systems, Inc. AD611/D area navigation system per STC. Reissued and amended 2/20/79.	GL	36520	Foster Airdata, Inc. 7020 Huntley Road Columbus, OH 43229
PA-23-250, -E23-250; T.C. 1A10	SA107GL	Conversion of oil lubricated de-ice pumps and related hardware to Airborne dry air pump 400 series. Issued 1/23/76.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 40355
PA-23-250, -E23-250 with counterweighted props, PA-31, PA-32-260, -31-325, -31-350, T.C. 1A10, A20SO, A3SO	SA300CE	Installation of Woodward propeller governors on single and twin engine airplanes. Amended 1/2/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-23-250, -E23-250; T.C. 1A10	SA430EA	Installtion of radome kit No. 3061X. Amended 11/12/76.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-23-250, S/N 27-2000 and up, -E23-250; T.C. 1A10	SA1162EA	Installation of Silver Instruments fueltron IIIG or IIID digital fuel flow and totalizer system. Amended 5/27/80.	WE	71780	Silver Instruments 2346 Stanwell Drive Concord, CA 94520
PA-23-250, -E23-250; T.C. 1A10	SW1524SW	Mitchell automatic flight system AK371 consisting of altimatic IIIB-1 autopilot with optional command/electric trim system with radio and glide slope couplers. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1571SW	Mitchell automatic flight system AK382 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 12/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA1653SW	Mitchell automatic flight system AK372 consisting of AutoFlite II with optional tracking system. Issued 5/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3002SW-D	Automatic flight system AK479 consisting of Piper altimatic IIIC autopilot with optional command/automatic electric elevator trim servo altimeter, radio coupler, and glide slope coupler. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3003SW-D	Automatic flight system AK477 and AK477FD consisting of Century IV autopilot and Century IV flight director autopilot with command/automatic electric trim, and optional annunciator panel and servoed altimeter. Issued 6/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-23-250, -E23-250; T.C. 1A10	SA3005SW-D	Automatic flight system AK508 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3006SW-D	Automatic flight system AK494 and AK494FD consisting of Century IV autopilot and Century IV director autopilot and command/automatic electric elevator trim and optional annuciator panel. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3007SW-D	Automatic flight system AK504 consisting of Piper altimatic IIIC autopilot with optional command/ automatic electronic pitch trim, radio coupler, glide slope coupler. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3027SW-D	Mitchell command/electric trim system AK562. Issued 10/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3104SW-D	Mitchell automatic flight system AK583, consisting of Century IIB autopilot with optional radio coupler. Issued 2/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-23-250, -E23-250; T.C. 1A10	SA3290WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 11/8/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA195EA	Installation of Goodrich Electrothermal propeller de-icing system kit 77-170. Amended 10/27/72.	GL	38500	B.F. Goodrich Aerospace and Defense Products Division of B.F. Goodrich Co. 500 South Main Street Akron, OH 44318
PA-23-250, -E23-250 (S/Ns 27-2505 and up); T.C. 1A10	SA840WE	Installation of Rajay Turbosupercharged Lycoming IO-540-C4B5 or -C4C5 engines. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-23 Series, PA-24 Series; T.C. 1A10, 1A15	SA230CE	Airspeed indicator landing gear warning system.	CE	74923	Standard Precision, Inc. 4105 West Pawnee Wichita, KS 67202
PA-23, PA-24, PA-28 Series; T.C. 1A10, 1A15, 2A13	SA148SW	Replacement of right front seat with stretcher. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72003
PA-23, PA-24, PA-28, PA-30; T.C. 1A10, 1A15, 2A13, A1EA	SA662WE	Hi-Lo sensitivity adaptor BI-400, and autopilot with NAV-1 navigation coupler and heading lock. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-23, PA-24, PA-30 Series; T.C. 1A10, 1A15, A1EA	SA1889SO	Flight control wheel.	SO	37086	Garcia Aviation Company 13010 SW 82nd Avenue Road Miami, FL 33156
PA-23, PA-25, PA-26 Series; T.C. 1A10, 1A15, 2A8, 2A10	SA4-1501	AB-6562 and AB-6563 brake blocks.	EA	46748	Johns-Manville Corporation 22 East 40th Street New York, NY 10001
PA-23, PA-30, PA-31, PA-34, PA-39 Series; T.C. 1A10, A1EA, A8EA, 1E10	SA1675WE	Installation of exhaust gas temperature monitoring systems EGT-2. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
PA-24 Series; T.C. 1A15	SA1-340	Oil-free vacuum pump PA-201.	GL	11880	Associated Aircraft Tool and Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
PA-24 Series; T.C. 1A15	SA1-544	External electrical power receptacle. Reissued 10/15/74.	EA	41500	R.H. Haynes, Inc. 62 Voorhis Lane Hackensack, NJ 07601
PA-24 Series; T.C. 1A15	SA3-309	I2-B autopilot with or without altitude control.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-24 Series; T.C. 1A15	SA3-315	Arcon B automatic rudder control. Amended 4/26/66.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA3-351	J-2B autopilot with optional altitude control and automatic approach coupler.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
PA-24 Series; T.C. 1A15	SA4-572	Autopilot and optional navigation coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA4-666	Grimes D-7080-1-12 rotating beacon.	NW	69226	H.M. Ruberg 1300 North 28th Street Springfield, OR 97477
PA-24 Series; T.C. 1A15	SA4-852	Full flow oil filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-24 Series; T.C. 1A15	SA4-955	Fiberglass vertical fin mount for either Grimes or Whelen WRM rotating beacons.	NW	85550	Art Whitaker Pearson Airpark Vancouver, WA 98660
PA-24 Series; T.C. 1A15	SA4-956	Three seat belts to accommodate three persons or rear seat.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-971	20-gallon auxiliary fuel tank in baggage compartment.	WE	77260	Symons Engineering P.O. Box 90002 Airport Station Los Angeles, CA 90009
PA-24 Series; T.C. 1A15	SA4-1032	Aerofilter 30409A full flow lube oil filter with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-24 Series; T.C. 1A15	SA4-1132	SP-3 autopilot, less altitude and navigation-hold features.	WE	74570	Sperry Phoenix Company 21111 19th Avenue Phoenix, AZ 85027
PA-24 Series; T.C. 1A15	SA4-1235	Installation of Brittain 15-gallon wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA4-1248	Fuel drain modified to incorporate a handle extending forward through front bulkhead.	WE	14960	Bates Aviation, Inc. 1026 East 120th Street Hawthorne, CA 90250
PA-24 Series; T.C. 1A15	SA4-1351	Installation of wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-24 Series; T.C. 1A15	SA2SO	Fifth passenger seat.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA18SO	Cockpit operated fuel drain valve.	SO	67008	Red Aircraft Service, Inc. International Airport Fort Lauderdale, FL 33300
PA-24 Series; T.C. 1A15	SA48WE	Belly-mounted rotating anti-collision light to supplement top fuselage-mounted standard rotating light.	WE	75250	Stits Aircraft Company P.O. Box 3084 Riverside, CA 92502
PA-24 Series; T.C. 1A15	SA59SW	Piper altimatic pilot AK089 or AK089R.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24 Series; T.C. 1A15	SA74SW	Quick door release mechanism.	SW	69207	Ross Aviation, Inc. R.F.D. 5, Riverside Airport Tulsa, OK 74101
PA-24 Series; T.C. 1A15	SA112CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155
PA-24 Series; T.C. 1A15	SA113CE	APU receptacle.	CE	39504	John O. Grimm 3648 Eminence Boulevard St. Louis County, MO 63155

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-24 Series; T.C. 1A15	SA160SW	Automatic pilot AK115, AK115E or AK115E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24 Series; T.C. 1A15	SA203SO	Fyr-Fyter 23-4, 2-1/2 pound, dry chemical, fire extinguisher.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-24 Series; T.C. 1A15	SA315SW	Fabrication and installation of split rear seat back.	SW	71365	Seven Bar Flying Service, Inc. 10001 Coors Road, NW Albuquerque, NM 87101
PA-24 Series; T.C. 1A15	SA341CE	SAGA (semi-automatic gear actuator) control system. Amended 9/6/66.	GL	43750	In-Flight Devices Corporation Port Columbus Int'l Airport Columbus, OH 43219
PA-24 Series; T.C. 1A15	SA362WE	Pneumatic pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA478EA	SAGA (semi-automatic gear actuator) system.	GL	43750	In-Flight Devices Corporatin 4885 Sawyer Road International Airport Columbus, OH 43219
PA-24 Series; T.C. 1A15	SA482WE	Plastic wing tips replaced with "Speedplates".	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
PA-24 Series; T.C. 1A15	SA510CE	Modify electrical system to combination 12/24 volt system for starting engine.	EA	12700	Avco Lycoming Division Avco Corporation Williamsport, PA 17701
PA-24 Series; T.C. 1A15	SA511WE	Lycoming O-540-B1B5 engine, Hartzell HC-A2XK-1/8433-7 propeller required.	WE	46790	Johnston Aircraft Service P.O. Box 757 Tulare, CA 93274
PA-24 Series; T.C. 1A15	SA553WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24 Series; T.C. 1A15	SA598EA	Installation electronic voltage alarm, Drawing No. 80107.	EA	53500	McKinley Engineering Corp. P.O. Box 275 Palisades Park, NJ 07650
PA-24 Series; T.C. 1A15	SA871WE	Fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-24 Series; T.C. 1A15	SA881EA	Installation of Grimes 30-0437-1 anti-collision strobe light kit, P/N 34-0200-1. Amended 5/2/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-24 Series; T.C. 1A15	SA891WE	Toe brakes.	RM	12540	Atlas AViation, Inc. 8505 Montview Boulevard Denver, CO 80202
PA-24 Series; T.C. 1A15	SA904WE	Hanlon and Wilson exhaust system, 637-129.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA928NW	Aeroquip high temperature hydraulic hoses and fittings between oil cooler and engine. Reissued 12/5/80.	NW	69229	Don Rudebaugh 409 N.E. 12th Avenue Vancouver, WA 98664
PA-24 Series; T.C. 1A15	SA1109WE	Hanlon and Wilson exhaust system.	WE	48230	"Slim" Kidwell Aviation Company Municipal Airport Torrance, CA 90510
PA-24 Series; T.C. 1A15	SA1605WE	Installation of Brittain B-4A flight control system. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24-180; T.C. 1A15	SA4-3151	Wing tip fuel tanks installed. Amended 1/10/69.	WE	17492	Brittain Industries, Inc. 2700 Skypark Drive Torrance, CA 90505
PA-24-180; T.C. 1A15	SA127EA	Installation of Monitair angle of attack system Model AA-2. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-24(-180), -24-250, -24-260, -24-400; T.C. 1A15	SA208GL	Installation of one piece windshield. Issued 1/23/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-24, PA-24-250, -260, -400: T.C. 1A15	SA270GL	Installation of forward windows, P/N's W-, W/T-, WG-2058-187 or -250 and W-, W/T-, W/G-2059-187 or -250. Issued 10/2/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-24, -24-250, S/N 24-2299 and above, PA-24-260, S/N 24-3642, 24-4000 thru 24-4802, PA-24-400, S/N 26-2 and above; T.C. 1A15	SA463GL	Install instrument panel and instruments. Issued 10/24/80.	GL	50470	Jerome E. Liebler 3182 Briar Hill Milford, MI 48042
PA-24, -24-250; T.C. 1A15	SA3074SW-D	Mitchell automatic flight system AK547 consisting of Century I autopilot with optional omni tracker. Issued 10/1/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, 24-250, -260; PA-28, 28-140, -150, -160, -180, -235; PA-30; PA-32-260, -300; T.C. 1A15, 2A13, A1EA, A3SO	SA808SW	Installation of Mitchell Model AK246 omni tracker. Applicable only to aircraft modified by STCs SA511SW, SA532SW, SA581SW, SA662SW, SA707SW.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -260, -400; T.C. 1A15	SA891SO	Remove existing windshield and install single piece windshield. Amended 4/27/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260; T.C. 1A15	SA1315CE	Chrome-plated brake disc installations. Issued June 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA1706SW	Portable solid oxygen system. Issued 7/27/73.	SW	74925	Stand-By Systems, Inc. 4907 Brookview Drive Dallas, TX 75220
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3070WE	Installation of single piece windshield. Issued 7/23/75.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-24, -24-250, -24-400; T.C. 1A15	SA2495WE	Installation of recontoured wing leading edge, stall fences, drooped ailerons in flaps-down mode, flap-actuated stabilator trim system, optional new wing tips, optional SC-100 stall warning system. Issued 3/27/72.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2619WE	Installation of Pathfinder Model P1( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; PA-28-180; T.C. 1A15, 2A13	SA2620WE	Installation of Pathfinder P2-( ) autopilot system. Amended 9/7/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250; PA-28-180; T.C. 1A15, 2A13	SA2654WE	Installation of Pathfinder P2A autopilot system. Reissued 5/31/74.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-24, -24-250, -260; T.C. 1A15	SA2653WE	Installation of engine crankcase, breather and vacuum pump air-oil separator. Amended 11/1/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24, -24-250, -260, PA-30; T.C. 1A15, A1EA	SA3045SW-D	Automatic flight system AK519 consisting of Century IIB autopilot with optional radio coupler. Issued 3/12/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, -24-250, -24-260, -24-400; T.C. 1A15	SA3565WE	Installation of single piece windshield. Issued 1/20/78.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-24, -24-250, -24-260; T.C. 1A15	SA3776WE	Installation of flexible stainless steel oil cooler hoses. Issued 11/1/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-24, -250, -260, -400; T.C. 1A15	SA4179WE	Installation of inflatable door seal. Issued 6/30/80.	WE	35320	Bob Fields Aerocessories 340 "E" East Santa Maria Street Santa Paula, CA 93060
PA-24-250: T.C. 1A15	SA5-27	Remove Lycoming O-540-A1A5 (250 hp) engine and install Lycoming O-540-B1B5 (235 hp) engine. Revised 3/3/62.	AL	63845	Peninsula Airways, Inc. P.O. Box 110 Naknek, AK 99633

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-24-250; T.C. 1A15	SA811WE	Installation of turbosupercharged Lycoming IO-540-C1B5 or C1C5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-250 (Normal Category): T.C. 1A15	SA3451WE	Installation of Hartzell HC-A3VK4/V7636D-0 or V7636N-0 constant speed propeller. Amended 5/27/80.	WE	06755	Aircraft Technical Service, Inc. 6701 Odessa Avenue Van Nuys, CA 91406
PA-24-250, -24-260; T.C. 1A15	SA3684WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
*PA-24-250, *-24-260; T.C. 1A15	SA3773WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79. *This installation limited to those aircraft with fuel injected engines.	WE	71740	Silver Instruments, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-24-250, 24-260, PA-30; T.C. 1A15, A1EA	SA1027SW	Manual electric pitch trim AK267.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA893SO	Installation of exhaust silencers. Issued 4/22/76.	SO	30704	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
PA-24-260 (S/Ns 24-4783 and 24-4804 and up): T.C. 1A15	SA1026SW	Piper automatic flight system Model AK186 consisting of altimatic IIIB autopilot, auto-flite, electric pitch trim, radio and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260 (S/N 24-4783, 24-4804 and up with IO-540 series normally aspirated engines; T.C. 1A15	SA1178EA	Installation of Silver Instruments fueltron IG digital fuel flow and totalizer system. Reissued 2/26/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-24-260; T.C. 1A15	SA1331SW	Mitchell automatic flight system AK326 consisting of Piper autoflite II and optional tracking system. Issued 6/22/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA1521SW	Mitchell automatic flight system AK393, consisting of Century I autopilot with optional omni tracker. Issued 10/17/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-260; T.C. 1A15	SA2062WE	Installation of Lycoming IO-540-R1A5 engine and Rajay turbosuperchargers.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-260, -24-400; T.C. 1A15	SA31NW	Installation of Madras wing tips. Issued 3/13/73.	NW	54000	Madras Air Service Route 2 Madras, OR 97741
PA-24-400; T.C. 1A15	SA2359WE	Installation of turbosupercharged Lycoming IO-720-A1A engine. Issued 6/1/71.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-24-400; T.C. 1A15	SA3134SW-D	Mitchell automatic flight system AK593 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24-400; T.C. 1A15	SA3135SW-D	Mitchell automatic flight system AK597 consisting of Century IIB autopilot with optional radio coupler. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral WElls, TX 76067
PA-24-400; T.C. 1A15	SA3136SW-D	Mitchell automatic flight system AK609 consisting of Century I autopilot with optional omni tracker. Issued 5/10/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-28; T.C. 1A15, 2A13	SA1485WE	Installation of Brittain B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-24, PA-30; T.C. 1A15, A1EA	SA313SW	Pitch trim system AK124.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-24, PA-30; T.C. 1A15, A1EA	SA331SO	External power supply plug.	SO	60120	Montgomery Aviation Corporation P.O. Box 92 Montgomery, AL 36100
PA-24, PA-30; T.C. 1A15, A1EA	SA466SW	Pitch trim system AK147.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA475SW	Pitch trim system AK152.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA524SW	Pitch trim system AK164.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA525SW	Piper autocontrol III, Mitchell AK161 autopilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA581SW	Stabilizer AK179.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A15EA	SA662SW	Automatic flight system 220.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-24, PA-30; T.C. 1A15, A1EA	SA756SW	AK236 automatic flight system with Century II autopilot, optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-25 Series; T.C. 2A8, 2A10	SA4-1592	Spray equipment.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA157SO	Air-oil type main landing gear shock absorber.	SO	64665	Piper Aircraft Corporation Vero Beach, FL 32960
PA-25 Series; T.C. 2A8, 2A10	SA168WE	Installation of Agavenco P/N 1826 15-gallon additional capacity cell to Piper fiberglass spray tank. Amended 3/18/68.	WE	03250	Agricultural Aviation Engineering Company McCarran Airport Las Vegas, NV 89109
PA-25 Series; T.C. 2A8, 2A10	SA185WE	Electrical spray control valve.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Crive Santa Clara, CA 95050
PA-25 Series; T.C. 2A8, 2A10	SA292SO	FrigiKing JC-1 air conditioner.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-25 Series; T.C. 2A8, 2A10	SA300SO	Auxiliary oil radiator.	SO	57750	Memphis Aero Corporation Municipal Airport Memphis, TN 38130
PA-25 Series; T.C. 2A8, 2A10	SA512SW	Metal ribs and metal covering of wings.	SW	60168	Luther W. Moore 1110 West 29th Street Plainview, TX 79072
PA-25 Series; T.C. 2A8, 2A10	SA829WE	Ceconite 101 covering of complete aircraft.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
PA-25, -25-235, -260; T.C. 2A10	SA915SO	Lower forward longeron reinforcement by adding tubing in trangle shape outboard between fore and aft wing spar root attach fittings and modifying wing root rib to fit over modified longeron. Issued 1/6/77.	SO	05966	Aircraft Service Center, Inc. Route 2, Tifton Airport Tifton, GA 31794
PA-25, -25-235, -260; T.C. 2A10	SA1180CE	Installation of smoke generator for Part 137, agricultural operations only. Amended 7/24/78.	CE	25750	Compro Aviation, Inc. P.O. Gox 508 Renner Field Goodland, KS 67735
PA-25, -25-235, -260; T.C. 2A10	SA1294WE	Installation of automatic flagman. Amended 4/17/72.	NW	03500	Air-Ag, Inc. Route 4 City County Airport Walla Walla, WA 99362

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-25, -25-235, -260; T.C. 2A10	SA1417WE	Installation of fiberglass wing tips. Amended 3/26/69.	NW	74750	Sportsman Airpark, Inc. P.O. Box 248 Newberg, OR 97132
PA-25-235; T.C. 2A8	SA41RM	Installation of freon air-conditioning system. Issued 1/9/75.	RM	45750	J B Systems, Inc. 120 South Bowen Circle Longmont, CO 80501
PA-25-235; T.C. 2A8, 2A10	SA521WE	Swathmaster dust and spray attachment.	WE	79250	Transland Aircraft, Inc. 2923 190th Street Redondo Beach, CA 90277
PA-25-235; T.C. 2A8, 2A10	SA710CE	Install Compro Aviation rudder horn extension.	CE	25750	Compro Aviation, Inc. Box 508 Goodland, KS 67735
PA-25-235; T.C. 2A8, 2A10	SA997WE	Installation of 180-gallon hopper tank. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton Avenue Harbor City, CA 90710
PA-25-235; T.C. 2A10	SA1399WE	Installation of Shell B1-Flon spray system. amended 7/19/68.	NW	71770	Simplex Manufacturing Company 4224 Northeast 42nd Avenue Portland, OR 97218
PA-25-235; T.C. 2A10	SA1630SW	Revised exhaust system. Issued 5/5/73.	SW	53784	Karl D. McWilliams d/b/a K & C Aircraft Service Municipal Building Airport Frederick, OK 73542
PA-25-235, -25-260; T.C. 2A8	SA1316CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-25-235, -25-260; T.C. 2A8	SA1892WE	Installation of hydraulic system. Reissued 1/16/75.	WE	79300	Transland, Inc. 24511 Frampton AVenue Harbor City, CA 90710
PA-25-235, -25-260; T.C. 2A8	SA368NW	Installation of outboard wing fuel tank with modified fuel pump system. Issued 10/19/76.	NW	03270	U.S.D.A. 3706 West Nob Hill Boulevard Yakima, WA 98902
PA-25, PA28-140, PA32-260; T.C. 2A8, 2A13, A3SO	SA693WE	Install AC induction air filter type AAF-104. Amended 4/26/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
PA-28 Series; T.C. 2A13	SA1-649	Lube oil filter PB55-1.	NE	36737	Fram Corporation 105 Pawtucket Avenue Providence, RI 02916
PA-28 Series; T.C. 2A13	SA8PC	Installation of baggage compartment kit IFC-BC-001 behind rear seats in the cabin.	PC	44810	Island Flight Center, Inc. 203 Lagoon Drive Honolulu, HI 96819
PA-28 Series; T.C. 2A13	SA100EA	AF-510, AF-512A or AF-512B autopilots.	EA	05950	Aircraft Radio Corporation Boonton, NJ 07005
PA-28 Series; T.C. 2A13	SA110SO	Electric pitch trim system.	SO	64665	Piper Aircraft Corporation Vero Beach, FL 32960
PA-28 Series; T.C. 2A13	SA180EA	Geared starter.	EA	79953	Turner Field, Inc. Prospectville, PA 19077
PA-28 Series; T.C. 2A13	SA164SW	Automatic pilot AK092E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA178WE	Full flow aerofilter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
PA-28 Series; T.C. 2A13	SA222SW	Hartzell HC-82XL-6N/7636D-4 propeller and cowl rework.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA224CE	A3000 main and NB1200 nose skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA236SW	Piper auto-control II automatic pilot AK085E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA246SW	Nose cowling modified.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28 Series; T.C. 2A13	SA263EA	Modification of engine mount to permit use of Lord mounting kit J-10778-4.	EA	12700	Lycoming Division Avco Corporation Williamsport, PA 17701
PA-28 Series; T.C. 2A13	SA319CE	Model 2500 wheel skis.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
PA-28 Series; T.C. 2A13	SA369SW	Automatic pilot AK129, pitch trim system AK130, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA481SW	Removal of door for parachute jumping.	SW	37055	Ervin J. Fusilier 9617 Fulton Street Houston, TX 77002
PA-28 Series; T.C. 2A13	SA511SW	Stabilizer AK153.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA530SW	Automatic pitch trim system AK166.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA556SW	Constant speed propeller.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
PA-28 Series; T.C. 2A13	SA601WE	Flight control system B-4 including pitch assist PC-1, altitude hold AH-1, and	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
PA-28 Series; T.C. 2A13	SA645WE	Autopilot and optional nav-coupler "add-on" BI-300, BI-301 or BI-304. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA646WE	Dynertial pitch assist PC-1 and optional altitude hold AH-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA707SW	AD127 automatic flight system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; T.C. 2A13	SA708SW	Plane booster safe flight wing tips 101-28.	SW	81250	Upper Valley Aviation, Inc. Harvey J. Ferguson McAllen, TX 78501
PA-28 Series; T.C. 2A13	SA880WE	New design fiberglass wing tips.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
PA-28 Series; T.C. 2A13	SA1191WE	Removal of baggage door for aerial photography operations.	RM	47725	Kelsey Ellis Air Service, Inc. Municipal Airport Salt Lake City, UT 84101
PA-28 Series; T.C. 2A13	SA1354WE	PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1469WE	Installation of Brittain Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28 Series; T.C. 2A13	SA1470WE	Installation of Brittain Model PAS-1 stability augmentation system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-29-140; T.C. 2A13	SA578EA	Installation of Monitair angle of attack/stall warning kit, P/N 9-92-1000. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140; T.C. 2A13	SA687SO	Installation of flight attitude alerting system. Amended 6/1/70.	SO	05350	Aircraft Instruments, Inc. 420 Lincoln Road, Suite 206 Miami Beach, FL 33139
PA-28-140; T.C. 2A13	SA913EA	Installation of Elano Corporation heater-muffler system. Issued 5/11/72.	GL	33200	Elano Corporation 2455 Dayton - Xenia Road Xenia, OH 45385
PA-28-140; T.C. 2A13	SA1189SW	Air circulator. Issued 9/15/70.	SW	83100	Ves-Kol 2805 National Drive Garland, TX 75040

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28-140; T.C. 2A13	SA1192EA	Instalation of Safe Flight (SFIC) SC-150 speed control system. Issued 4/15/80.	EA	69500	Safe Flight Instrument Corp. P.O. Box 550 White Plains, NY 10602
PA-28-140; T.C. 2A13	SA2052WE	Installation of Hartzell HC82XL-6F/8433-12 propeller (after conversion of engine to Lycoming O-320-E1A model).	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-140; T.C. 2A13	SA2325WE	Replacement of Station 140.6 vinyl bulkhead panel with fiberglass baggage compartment. Issued 3/19/71.	WE	21000	Chaffee Aircraft Service Corp. 2105 Valley Boulevard Colton, CA 92324
PA-28-140; T.C. 2A13	SA2706SW	Lycoming O-320-D3G engine. Issued 1/20/78.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-140; T.C. 2A13	SA2842WE	Installation of Novastar anti-collision lighting system. Issued 2/27/74.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28-140; T.C. 2A13	SA3071WE	Installation of Bendix P/N 480543 electric auxiliary fuel pump. Issued 8/7/75.	WE	29200	Harry R. Dellicker P.O. Box 746 Strathmore, CA 93267
PA-28-140 (Normal and utility category); T.C. 2A13	SA3415WE	Installation of Lycoming O-320-D2A engine and Sensenich M74DM6-0-60 propeller. Reissued 5/1/79.	NE	30310	Arthur M. D'Onofrio, Jr. 206 Winthrop Boulevard Cromwell, CT 06416
PA-28-140, -28-150 and PA-28-151 landplanes; T.C. 2A13	SA1331CE	Installation of 160 hp Lycoming engine and repitched Sensenich Amended 10/27/77.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
PA-28-140, -150, -160, -180, -235; T.C. 2A13	SA2NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 7/31/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
PA-28-140, -28-150, -28-160, -28-180, -28S-180, -28-235; T.C. 2A13	SA363EA	Installation of Monitair angle of attack and stall warning kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-28-140, -150, -160, -180; T.C. 2A13	SA549NW	Installation of Deemers wing tips. Issued 12/5/77.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
PA-28-140, -140B, -140C, -140D, -140E, -150, -160, -160B, -160C, -160D, -160E, -160F, -180, -232, -235B thru F, PA-32-260, -300, -32R-300; T.C. 2A13, A3SO	SA600NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. NOTE: Installation does not apply to those models with tapered wings. Issued 10/25/78.	NW	19830	Robert C. Cansdale Bob's Aircraft Supply Thun Field Puyallup, WA 98371
PA-28-140, -150, -151, -160; T.C. 2A13	SA793CE	Installation of Lycoming O-360-A1A engine and Hartzell HC-C2YK-1B/7666A-2 propeller. Amended 6/29/78.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
PA-28-140, -150, -160, -180, -235, 28-S-160, S-180, 28R-180, -200; T.C. 2A13	SA819EA	Alteration to replace standard anti-collision light with Grimes Series 550 single anti-collision red or white strobe kit, P/N 34-0001-1 or 34-0001-2. Amended 3/30/78.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-28-140, -150, -160, -180, -235, -S-160, -S-180, -R-180; T.C. 2A13	SA822SW	Mitchell automatic flight system AK217 consisting of Century III autopilot with optional automatic pitch trim, aileron stabilizer, and radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -200, PA-34-200; T.C. 2A13, A7SO	SA979EA	Installation of L/R wing tip transparent fairings and sensor mounting bracketry. Issued 4/5/74.	EA	68700	Rock Avionic Systems, Inc. 412 Avenue of the Americas New York, NY 10011
PA-28-140, -28-150, -28-160, -28-180, -28R-200 (S/N 28R-35001 thru 28R-7135329; T.C. 2A13	SA1072CE	Installation of wing leading edge cuffs and droop tips, dorsal fin and vertical stabilizer vortex Amended 5/1/80.	CE	42560	Horton Stol-Craft, Inc. Wellington Municipal Airport Wellington, KS 67152

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28-140, -150, -160, -180, -235, -28S-160, -28S-180, -28R-180, -28R-200, -28-151, -28-161, -28-181, -28R-201, -28R-201T, PA-32-260, -300, -32S-300, -32R-300; T.C. 2A13, A3SO	SA1123EA	Installation of Devore vertical tail floodlights on upper surface of horizontal stabilator. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1227CE	Installation of dorsal fin. Amended December 1976.	CE	44800	Isham Aircraft P.O. Box 12172 Wichita, KS 67212
PA-28-140, -28-150, -28-160, -28-180; T.C. 2A13	SA1228CE	Installation of wing tip extension. Amended June 1976.	CE	44800	Isham Aircraft 416 West Fourth Street Valley Center, KS 67147
PA-28-140, -150, -160, -180, -235; PA-28R-180; T.C. 2A13	SA1157SW	Mitchell flight system AK295 consisting of Piper AutoFlite II, automatic aileron stabilizer and optional tracking system. Issued 6/15/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, PA-28R-180, -235, -200; T.C. 2A13	SA1272SW	Automatic flight system AK307, consisting of Century I and omni tracker. Issued 3/9/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 3A12	SA1317CE	Chrome-plated brake disc installation. Amended 3/1/78.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Bouelvard Kansas City, KS 66103
PA-28-140, -150, -160, -180 (S/Ns 28-1 thru 28-4377), PA-28-235 (S/N 28-10003 thru 28-11039); T.C. 2A13	SA1373CE	Install third window. Amended 11/17/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1741WE	Installation of hand control for rudder system. Amended 6/13/73.	WE	16854	William Henry Blackwood Route 3, Box 744B3 Escondido, CA 92025
PA-28-140, -150, -160, -180, -235, -28R-180, -28R-200; T.C. 2A13	SA1898SW	Installation of wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-28-140, -150, -160, -180; T.C. 2A13	SA2179WE	Installation of leading edge cuff, drooped ailerons, wing stall fences, raked wing tips, fuselage flaps, stabilator trim-spring and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98007
PA-28-140, -150, -160, -180, PA-28R-180, -200, -235, PA-32-260, -300; T.C. 2A13	SA3026SW-D	Mitchell auto flight system AK463 consisting of Century IIB autopilot with optional radio coupler. Issued 10/25/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -160, -180, -28R-200, -235; T.C. 2A13	SA3165SW-D	Automatic flight system AK174 consisting of auto-control IIB autopilot with optional radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -160, -180, -235, -28R-180, -200; T.C. 2A13	SA3166SW-D	Automatic flight system AK295 consisting of Piper autoflite II. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-140, -150, -151, -160, -180, -181, -28R-180, -28R-200, -28-235; T.C. 2A13	SA3435WE	Installation of flexible oil hose assembly. Amended 1/11/79.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-28-140, -150, -160, -180, -151, -181, PA-28S-160, -180, PA-28R-180-200; T.C. 2A13	SA3687WE	Installation of an air/oil separator. Issued 7/19/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
PA-28-151; T.C. 2A13	SA228GL	Installation of Lycoming O-320-D3G engine in lieu of Lycoming O-320-E3D engine using original installation hardware and components. No installation data required. Issued 3/3/78.	EA	90108	W. Irvine Young 54 Atomic Avenue Toronto, Ontario M8Z-5L4 Canada

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28-151; T.C. 2A13	SA1716SW	Mitchell automatic flight system AK430 consisting of AutoFlite II with optional omni tracker. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA1717SW	Mitchell automatic flight system AK431 consisting of auto-control III with optional radio coupler. Issued 8/15/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151; T.C. 2A13	SA2969SW	Lycoming O-320-D3G engine. Issued 4/5/79.	SW	66300	RAM Aircraft Modifications P.O. Box 5219 Waco, TX 76708
PA-28-151; T.C. 2A13	SA3012WE	Installation of Pathfinder auto-pilot systems. Issued 4/24/75.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-151, -161, -181, PA-28R-200, -201, PA-28-235, -28R-201T; T.C. 2A13	SA1075SO	"Wing-Ding" door stop to be installed using existing screws (Piper P/N 415 309, MS27039-0809) on leading edge of right wing at inboard side of fuel cell (W.S. 57.00). Issued 5/18/79.	SO	65327	William J. Stephenson Pro-Flite of Vero, Inc. P.O. Box 998 Vero Beach, FL 32960
PA-28-151, -181; T.C. 2A13	SA3065SW-D	Mitchell automatic flight system AK431 consisting of autocontrol IIIB with optional radio coupler. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3066SW-D	Mitchell automatic flight system AK430 consisting of autoflite II with optional omni tracker. Issued 7/14/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3095SW-D	Mitchell automatic flight system AK575 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28-151, -181; T.C. 2A13	SA3096SW-D	Mitchell automatic flight system AK576 consisting of Century IIB autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Building Mineral Wells, TX 76067
PA28-160; T.C. 2A13	SA1971WE	Installation of Model ARB-3 automatic downed aircraft marker ("ADAM"). Amended 11/21/69.	RM	18500	Burton Instrumentation, Inc. 2050 Airway Avenue Box 822 Fort Collins, CO 80521
PA-28-160, -28-180, -28-235; T.C. 2A13	SA1484WE	Installation of Brittain Industries Model B2C flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-28-161, -181; T.C. 2A13	SA419GL	Installation of Tull microwave landing system airborne equipment. Issued 6/18/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
PA-28-161, -181, -201T, -236; T.C. 2A13	SA3352SW	Installation of Mitchell automatic flight system AK851 consisting of Century 21 autopilot. Issued 1/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TS 76067
PA-28-180; T.C. 2A13	SA1789WE	Installation of Brittain lateral stability augmentation system and super venturi. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-180; T.C. 2A13	SA1792WE	Installation of Morse protection system.	WE	60190	Morse Products Manufacturing 12960 Bradley Avenue Sylmar, CA 91342
PA-28-180; T.C. 2A13	SA2213WE	Conversion of Lycoming O-360-A3A engine to Model O-360-A1A engine and installation of Hartzell HC-C2YK1-B/7666A-0 propeller. Issued 9/8/70.	NW	65329	Propellers, Inc. 5802 South 228th Street Kent, WA 98031
PA-28-180; T.C. 2A13	SA3233WE	Installation of Symbolic Displays "Novastar" anti-collision light. Issued 7/22/76.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-28R-180; T.C. 2A13	SA962SW	Piper automatic flight system AK271 consisting of altimatic with optional automatic pitch trim, aileron stabilizer, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28R-180; T.C. 2A13	SA1237SW	Mitchell automatic flight system Model AK314 consisting of altimatic IIIB-1 with optional automatic pitch trim and radio coupler. Issued 12/16/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA1406SW	Mitchell flight system Model AK269 consisting of Piper autocontrol III autopilot with optional radio coupler. Issued 12/15/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180; -200; T.C. 2A13	SA2202WE	Installation of contoured leading edge, drooped ailerons, fuselage flap, stabilator trim spring, wing stall fences, raked wing tips, and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 15400 Sunset Highway Bellevue, WA 98004
PA-28R-180, -200; T.C. 2A13	SA2490SW	Wing tip extension and dorsal fin. Reissued 10/6/77.	CE	44800	Isham Aircraft P.O. Box 12172 Mid-Continent Airport Wichita, KS 67277
PA-28R-180, -200; T.C. 2A13	SA3004SW-D	Automatic flight system AK436 consisting of Piper autocontrol IIIB with optional radio coupler. Issued 6/13/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA3093SW-D	Mitchell automatic flight system AK577 consisting of Century I autopilot with optional omni tracker. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200; T.C. 2A13	SA3094SW-D	Mitchell automatic flight system AK578 consisting of Century IIB autopilot with optional radio coupler. Issued 12/30/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-180, -200, -201; T.C. 2A13	SA3841WE	Installation of SDI Model CFS-1000, -1001, or F1-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-28R-200; T.C. 2A13	SA194GL	Installation of Lycoming IO-360-C1C6 engine in lieu of Lycoming IO-360-C1C engine using original installation hardware and components. Issued 11/11/77.	GL	71517	Shelby Aircraft Engine Parts, Inc. P.O. Box 454 Shelbyville, IL 62565
PA-28R-200 (S/N 28R-7235001 and up), -28R-201T, -28R-201 (S/N 28R-7737002 and up); T.C. 2A13	SA1183CE	Installation of a two-axis King Model KFC200 flight control system with a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon indicator with a KC-292 mode controller. Amended 1/26/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-28R-201: T.C. 2A13	SA420GL	Installation of Tull microwave landing system airborne equipment. Issued 6/18/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
PA-28R-201, -201T; T.C. 2A13	SA3161SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -201T; T.C. 2A13	SA3162SW-D	Automatic flight system AK640 consisting of Piper autoflite II autopilot with optional omni tracker. Issued 11/29/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3194SW-D	Automatic flight system AK638 consisting of Piper altimatic IIIC autopilot with optional radio coupler and glide slope coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201, -28R-201T; T.C. 2A13	SA3195SW-D	Install automatic flight system AK652 consisting of Century III autopilot with optional radio coupler. Issued 3/24/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-200, -28R-201T; T.C. 2A13	SA3196SW-D	Install automatic flight system AK653 consisting of Century IIB autopilot with optional radio coupler. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-28R-200, -28R-201T; T.C. 2A13	SA3197SW-D	Install automatic flight system AK654 consisting of Century I autopilot with optional omni tracker. Issued 4/6/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28R-201T; T.C. 2A13	SA148RM	Install Model CFS-1000 fuel flow meter and related systems. Issued 8/15/78.	RM	77248	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-28R-201T; T.C. 2A13	SA1383CE	Installation of Edo-Aire propeller governor Model 34-828-014-12. Issued 10/28/77.	CE	32500	Edo-Aire Wichita Division 1326 South Walnut Street Wichita, KS 67213
PA-28R-201T; T.C. 2A13	SA3771WE	Installation of Fueltron IG digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-28RT-201, -28RT-201T; T.C. 2A13	SA1498CE	Installation of King KFC 200 automatic flight control system. Issued 6/18/79.	CE	48250	King Radio Corporation 400 NOrth Rogers Road Olathe, KS 66061
PA-28RT-201, -28RT-201T; T.C. 2A13	SA3323SW-D	Mitchell automatic flight system AK755 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 11/30/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3336SW-D	Mitchell automatic flight system AK777 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 3/21/79.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3359SW	Installation of Mitchell Century 41 autopilot/flight director AK863/FD. Issued 4/16/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28RT-201, -201T; T.C. 2A13	SA3360SW-D	Installation of Mitchell automatic flight system AK862 consisting of Century 21 autopilot. Issued 5/16/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-28-235; T.C. 2A13	SA1131EA	Installation of a radome pod SFPP-1001 or -1002 on right wing. Amended 3/28/80.	EA	08332	David L. Stanislaw d/b/a Airquip Horsham Road Ambler, PA 19002
PA-28-235; T.C. 2A13	SA2143WE	Installation of drooped leading edge, drooped ailerons, wing stall fences, fuselage flap, drooped wing tips and elevator trim spring. Amended 12/30/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
PA-28-235; T.C. 2A13	SA2147WE	Installation of Brittain Industries B-7 flight control system. Reissued 11/20/72.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-235; T.C. 2A13	SA3187WE	Modification of aileron control system by addition of aileron centering springs and installation of Pathfinder autopilot systems. Issued 5/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
PA-28-235; T.C. 2A13	SA4103SW	Installation of Brittain B-5 flight control system. Issued 3/20/80.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-28-235, PA-32-260, -300; T.C. A3SO, 2A13	SA1156EA	Installation of radome pod SERP-1021 or -1022 on right wing. Issued 6/26/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002
PA-28, PA-32; T.C. 2A13, A3SO	SA281AL	Installation of large nose gear fork and 8.00-6 nose gear tire. Amended 6/20/68.	AL	78487	Tibbetts-Herre Airmotive P.O. Box 110 Naknek, AK 99633
PA-28, PA-32; T.C. 2A13, A3SO	SA472SO	Installation of hand control for rudder pedal operation. Amended 6/27/74.	SO	85450	The Wheelchair Pilots Association 4211 Fourth Avenue South St. Petersburg, FL 33711
PA-28, PA-32; T.C. 2A13, A3SO	SA757SW	AK234 automatic flight system with Century II autopilot optional radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-28 Series; PA-32-260; T.C. 2A13, A3SO	SA788SW	Piper auto-control II automatic pilot AK172E.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-30 Series; T.C. A1EA	SA72RM	Installation of camera wells. Amended 12/9/76.	RM	42420	Horizons, Inc. P.O. Box 3134 Rapid City, SD 57701
PA-30 Series; T.C. A1EA	SA184EA	Installation of 13-quart alcohol propeller anti-icing kit utilizing either a Weldon pump (P/N 100B-6) or a Bendix pump (P/N 478360). Amended 10/15/71.	NE	86000	Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA225EA	Installation of Monitair angle of attack and stall warning system. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
PA-30 Series; T.C. A1EA	SA233EA	Reservoir-type pneumatic wing and tail deicing system. Amended 10/7/70.	NE	86000	R.W. Wiggins Airways, Inc. Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA282CE	GUARD System (Gear-up automatic response device).	GL	43750	In-Flight Devices, Inc. 1621 West Walnut Street Chicago, IL 60612
PA-30 Series; T.C. A1EA	SA343SW	Automatic pilot AK127, AK127E or AK127E-3, and lateral guidance radio coupler AK123.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA477EA	SAGA (semi-automatic gear actuating) system.	GL	43750	In-Flight Devices Corporation 4885 Sawyer Road International Airport Columbus, OH 43219
PA-30 Series; T.C. A1EA	SA520SO	Installation of Bendix FCS-810 (Piper Altimatic V/F/D) automatic flight control including manual electric trim and optional flight director indicator. Amended 8/13/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-30 Series; T.C. A1EA	SA531SW	Fifth seat.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive International Airport San Antonio, TX 78216
PA-30; T.C. A1EA	SA533NW	Installation of aileron trim. Issued 10/19/77.	NW	73160	Robert Smith Box 43 Okanagan Mission Kelowna, B.C., Canada
PA-30 Series; T.C. A1EA	SA534EA	Replacement of existing stall warning detector Safe Flight P/N C-52207 with pre-stall warning and speed control transducer, Safe Flight P/N 792 and speed control indicator, P/N 571.	EA	69500	Safe Flight Instruments Corp. New King Street White Plains, NY 10601
PA-30 Series; T.C. A1EA	SA559WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30 Series; T.C. A1EA	SA576SW	AK186 altimatic III autopilot, AK179 stabilizer, and AK189 automatic trim system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA591CE	Install Alco XW20101-PA-30-L windshield wiper system.	CE	08750	Alco Controls Corporation P.O. Box 12700 St. Louis, MO 63141
PA-30 Series; T.C. A1EA	SA727WE	Installation of Brittain Industries Model TT-5 wing tip fuel tanks. Reissued 2/2/71.	WE	62000	H.S. Osborne d/b/a Osborne Tank and Supply Star Route, Box 12 Oro Grande, CA 92368
PA-30 Series; T.C. A1EA	SA738CE	Install King Radio KNC 610 area navigation computer. Amended May 1974.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA766WE	Plastic wing tips replaced with "Speedplates" SP51463.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81501
PA-30 Series; T.C. A1EA	SA767WE	Modification to include three pair of seat belts on rear seat to accommodate three passengers.	WE	14960	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-30 Series; T.C. A1EA	SA776CE	Installation of King Radio KN-74 area navigation computer. Issued June 1971.	CE	48250	King Radio Corporation Box 106 400 North Rogers Road Olathe, KS 66061
PA-30 Series; T.C. A1EA	SA789CE	Install Woodward propeller unfeathering accumulator system. Issued July 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-30 Series; T.C. A1EA	SA1111SW	Outer wing integral auxiliary fuel tanks and increase gross weight of 180 pounds.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1112SW	Dorsal fin.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1113SW	Extended nose with baggage compartment.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1114SW	Nacelle baggage compartments.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1115SW	Dual brakes.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1151SW	Lycoming IO-360-C1C engines (200 hp) with Hartzell HC-C2YK-2/C7666A-4 propeller. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1152SW	One-piece windshield. Issued 6/8/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1153SW	Square wing tips with dual navigation lights. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1154SW	Rudder and aileron interconnect system. Issued 6/7/70.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30 Series; T.C. A1EA	SA1337SW	Pneumatic de-icing system. Issued 7/8/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246
PA-30; T.C. A1EA	SA1401CE	Install King Model KNS 80 digital area navigation system. Issued 2/16/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olather, KS 66061
PA-30 Series; T.C. A1EA	SA1935WE	Installation of Brittain flight control system Model B-5, NAV-2B, or B2C. Reissued 10/20/72.	SW	17400	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30; T.C. A1EA	SA3707WE	Installation of single piece windshield. Issued 8/7/78.	WE	14238	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-30; T.C. A1EA	SA3729WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-30; T.C. A1EA	SA4066WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 12/7/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-30, PA-39; T.C. A1EA	SA209GL	Installation of one piece windshield. Issued 1/23/78.	GL	39450	Great Lakes Aero Products 1021 North Chevrolet Avenue Flint, MI 48504
PA-30, PA-39; T.C. A1EA	SA673EA	Installation of radome kit 3058X. Amended 5/26/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-30, PA-39; T.C. A1EA	SA676EA	Installation of Norton Company radome kit 3058-B. Amended 3/24/71.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-30, PA-39; T.C. A1EA	SA787WE	Installation of turbosupercharged Lycoming IO-320-B1A, IO-320-C1A or LIO-320-C1A engines. Amended 3/10/70.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA848EA	Installation of pneumatic pump operated wing and tail de-icing boot system. Issued 10/22/70.	NE	86000	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-30, PA-39; T.C. A1EA	SA1239SW	Turbosupercharged Lycoming IO-360-C1C engines. Issued 1/4/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30, PA-39; T.C. A1EA	SA1254SW	Electrothermal propeller de-icing system. Issued 1/27/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78216
PA-30, PA-39; T.C. A1EA	SA1320CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-30, PA-39; T.C. A1EA	SA1341SW	Nose taxi light. Issued 7/20/71.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 International Airport San Antonio, TX 78246
PA-30, PA-39; T.C. A1EA	SA2312WE	Installation of leading edge cuffs, stall fences, stall strips drooped ailerons, flap actuated stabilator trim system, raked wing tips (optional) and dorsal fin. Amended 4/2/71.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98007
PA-30, PA-39; T.C. A1EA	SA2849WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-30, PA-39; T.C. A1EA	SA3128SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional command automatic trim, readio, and glide slope couplers. Issued 5/6/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA3336WE	Installation of single piece windshield. Issued 2/2/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406
PA-30, PA-39; T.C. A1EA	SA4189WE	Installation of DTL-1000, -1001 and/or -1002/3 autopilot adapters for the Edo-Aire Mitchell century III autopilot. Issued 7/29/80.	WE	47775	Douglas L. Kettler 1212 North Broadway, Apt. H Escondido, CA 92026
PA-31 (S/N 31-2 and up); T.C. A8EA	SA142RM	Install Model CFS-2000 fuel flow meter and related systems. Issued 5/12/78.	RM	77250	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar B Denver, CO 80220
PA-31; T.C. A8EA	SA191GL	Installation of microwave landing airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31 Series; T.C. A20SO	SA367GL	Installation of Norton radome kit No. 2032X Amended 10/24/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA529EA	Installation of kit for radar antenna.	GL	61750	Chamberlain Engineering Corp. A Subsidiary of Norton Company P.O. Box 1187 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA541CE	Installation of Hoskins Twilighter Mk III supplemental lighting system. Reissued 10/17/74.	WE	77250	Symbolic Displays,, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-31 Series; T.C. A8EA	SA546EA	Incorporation of opening in lower surface of fuselage aft of front spar.	NE	86000	E.W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31 Series; T.C. A8EA	SA613EA	Installation of nine seats. Amended 6/6/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31 Series; T.C. A8EA	SA622EA	Incorporation of camera hatch and mountings to accommodate Zeiss RMK A15/23 camera.	EA	12500	Atlantic Aviation Corporation P.O. Box 1709 Wilmington, DE 19899
PA-31 Series; T.C. A8EA	SA741EA	Installation of co-pilot door. Amended 11/3/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31 Series; T.C. A8EA	SA865EA	Installation of radome kit 2031KX. Amended 5/28/76.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-31 Series; T.C. A8EA	SA908SW	Air conditioner.	SW	64410	R.D. Philpot Industries, Inc. Box 47062 Dallas, TX 75247
PA-31 Series; T.C. A8EA	SA986SW	Baggage lockers in revised aft nacelle fairings.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1000SW	Nine place seating arrangement.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1054SW	Stretcher.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1055SW	Baggage retaining net.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1065SW	Mitchell flight director and autopilot Model 282-187 with slaved directional gyro. Issued 9/4/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA1120SO	Installation of single camera and camera aperature on starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31; T.C. A20SO	SA1121SO	Installation of supply dropping aperature and sliding shutter and antenna fairing. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31; T.C. A20SO	SA1123SO	Installation of navigation sight and transparent plastic dome on the lower fuselage station 128. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31 Series; T.C. A8EA	SA1155SW	Three-place couch. Reissued 6/20/78.	SO	28380	Cypress Aviation, Inc. 3840 Drone Field road Lakeland Airport Lakeland, FL 33803
PA-31 Series; T.C. A8EA	SA1204SW	Manual electric trim AK281. Issued 10/19/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31 Series; T.C. A8EA	SA1234SW	Mitchell automatic flight system FD/AP282-273, consisting of flight director /autopilot with optional automatic aileron stabilizer AK273. Issued 12/21/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31 Series; T.C. A8EA	SA1305SW	Auxiliary fuel tank. Issued 5/10/71.	SW	61500	Nayak Aviation Corporation 206 East Terminal Drive San Antonio, TX 78216
PA-31 Series; T.C. A8EA	SA1340SW	Four-place couch. Reissued April 1973.	SW	84600	Ward International Aircraft Services, Inc. Location 2 WEst, Meacham Field Fort Worth, TX 76106
PA-31 Series; T.C. A8EA	SA1569WP	Installation of windshield wiper system.	CE	08750	Alco Controls Corpporation Box 12700 St. Louis, MO 63141
PA-31 Series; T.C. A8EA	SA1651WP	Installation of ski carrying pod under fuselage at wing root.	NW	57700	Melridge Aviation Company 1901 East Fifth Street Vancouver, WA 98661

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31 Series; T.C. A8EA	SA2124WE	Installation of air conditioning system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
PA-31 Series; T.C. A8EA	SA3130SW-D	Mitchell automatic flight system AK589 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA1164SO	Installation of a Bendix FCS-870 automatic flight control system. Issued 7/2/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Launderdale, FL 33310
PA-31; T.C. A20SO	SA3355SW	Mitchell automatic flight system AK846/FD consisting of Century IV/flight director autopilot with optional remote annunciator. Issued 2/19/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31; T.C. A20SO	SA3768WE	Installation of Fueltron digital fuel flow and totalizer system. Issued 11/3/78.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-31, PA-31-300; T.C. A8EA	SA603EA	Addition of a 32-inch high door on L.H. side of fuselage between fuselage stations 244-261. Reissued 6/21/78.	SO	28380	Cypress Aviation, Inc. 3480 Drone Field Road Lakeland Airport Lakeland, FL 33803
PA-31, -300; T.C. A8EA	SA744EA	Modification of toilet seat hassock and installation of safety belt. Issued 4/4/69.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Reading, PA 19603
PA-31, -300; T.C. A8EA	SA1255SW	Mitchell automatic flight system Model AK324 consisting of Piper autoflite II and tracking system. Issued 1/25/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA1522SW	Mitchell automatic flight system AK394, consisting of Century I autopilot with optional omni tracker. Issued 10/18/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3008SW-D	Automatic flight system AK483 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim, radio, and glide slope couplers. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -300; T.C. A8EA	SA3009SW-D	Automatic flight system AK496 and AK496FD consisting of Century IV autopilot and Century IV flight director with command/automatic electric elevator pitch trim and optional annuciator panel. Issued 7/12/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -31-300; T.C. A8EA	SA3010SW-D	Automatic flight system YK491 consisting of yaw damper. Issued 7/10/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31, -31-300, -325, -350; T.C. A20SO	SA1010NW	Camera ports. Issued 8/18/80.	NW	42800	A.D. Howard Route 2, Box 4 Culdesac, ID 83524
PA-31, -31-300, -325, -350; T.C. A8EA	SA1318CE	Chrome-plated brake disc installation. Issued May 1977.	CE	33468	Engineering Plating and Processing, Inc. 641 Southwest Boulevard Kansas City, KS 66103
PA-31, -31-325, -31-350; T.C. A20SO	SA454GL	Installation of Shadin Co. 910502 or 910504 fuel flow indicating system. Issued 9/29/80.	GL	71503	Shadin Company Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
PA-31 (S/N 31-712 and up), PA-31-325, -350; T.C. A8EA	SA1529CE-D	Installation of King KAS 297 altitude selector option. Issued 2/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, -31-300, -31-325, -350; T.C. A20SO	SA1595CE	Installation of TSO'd stretcher. Issued 6/5/80.	CE	12777	Avicon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
PA-31, -31-300, -325, -350; T.C. A8EA	SA3401WE	Installation of single piece windshield. Issued 5/10/77.	WE	84650	Wayne Airframe, Inc. 16644 Roscoe Boulevard Van Nuys, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31, 31-300, PA-31P; T.C. A8EA	SA852EA	Installation of Grimes 555 Series three light strobe kit P/N 34-0100-1. Amended 5/10/71.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
PA-31, -31P, -31-325, -31-350; T.C. A8EA	SA437SO	Installation of Bendix FCS-810 automatic flight control system, including manual electric trim and optional flight director indicator. Amended 4/4/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31, -31P, -31T, -31-300, -325, -350, -31T1; T.C. A8EA	SA1008EA	Installation of single lamp logo light in horizontal tail. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Fircher Street, N.E. Albuquerque, NM 87109
PA-31, -31P, -31-300, -325, -350; T.C. A8EA	SA1187CE	Installation of King Model KCS 55A pictorial navigation (compass) with optional KS 52 autopilot adapter. Issued 12/10/75.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31-350, -31-325; T.C. A8EA	SA1166CE	Installation of King KFC-200, 2 axis (3 optional) flight control system, autopilot only or autopilot with flight director. Amended 1/4/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31, PA-31T; T.C. A8EA	SA578NW	Install redesigned 7th seat (toilet). Issued 5/12/78.	NW	70640	Seattle Flight Service, Inc. 7001 Perimeter Road Seattle, WA 98108
PA-31-300; T.C. A8EA	SA184GL	Installation of microwave landing system airborne equipment. Reissued 1/12/79.	CE	86150	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31-300, -310, -325, -350; T.C. A8CE	SA1136CE	Installation of Fiquench cabin fire extinguisher and engine fire extinguishant distribution system. Reissued 12/15/77.	CE	33471	Enk Aviation Corporation 1213 Horizon Drive Blue Springs, MO 64015
PA-31-325; T.C. A8EA	SA1085CE-D	Installation of Collins Radio Group AP-106, 3-axis autopilot system. Amended 6/25/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1086CE-D	Installation of Collins Radio Group AP-107, 3-axis autopilot system. Amended 6/26/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1087CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system. Amended 6/26/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA1088CE-D	Installation of Collins Radio Group yaw damper system. Amended 4/25/75.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
PA-31-325; T.C. A8EA	SA3017SW-D	Automatic flight system AK485 consisting of Piper altimatic IIIC autopilot with optional command/automatic electronic pitch trim system, radio, and glide slope couplers. Issued 9/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3021SW-D	Automatic flight system AK500 and AK500FD consisting of Century IV autopilot and Century IV flight director autopilot with electronic command/automatic pitch trim system and optional annuciator panel. Issued 10/4/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3129SW-D	Automatic flight system AK590 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 4/15/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-325; T.C. A8EA	SA3211SW-D	Mitchell automatic flight system AK686 or AK686FD, Piper altimatic X flight director autopilot with optional remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31-325, -31-350; T.C. A20SO	SA300CE	Installation of propeller governors on single and twin engine aircraft: P/N L210571 left engine, R210571 right engine. Issued 1/2/80. P/N L210721 left engine, R210721 right engine. Issued 2/2/80. P/N L210573 left engine, R210573 right engine. Issued 5/7/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
PA-31-325, PA-31-350 S/N 31-7405479 and up (S/N 31-5001 thru 7405478 when modified per Piper SL722); T.C. A20SO	SA4037WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel and totalizer system. Amended 3/13/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
PA-31-350: T.C. A8EA	SA8WE	Installation of Collins AP-107 2-axis or 3-axis autopilot including yaw damper system. Reissued 12/19/74.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, NE Cedar Rapids, IA 52406
PA-31-350; T.C. A20SO	SA295GL	Install Cleveland conversion kit, P/N 189-83. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
PA-31-350: T.C. A8EA	SA923SO	Installation of Bendix FCS-870 automatic flight control system. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31-350: T.C. A8EA	SA924SO	Installation of Bendix NP-2041A area navigation computer. Issued 2/17/77.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31-350; T.C. A20SO	SA1119SO	Installation of twin cameras and two camera aperatures on starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350: T.C. A20SO	SA1122SO	Installation of single camera and camera aperature on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350; T.C. A20SO	SA1124SO	Installation of a single camera and camera aperature and antenna fairing on the starboard side of the lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
PA-31-350: T.C. A20SO	SA1125SO	Installation of twin cameras and two camera aperatures plus camera sights on starboard side of lower fuselage. Issued 1/8/80.	SO	64665	Piper Aircraft Corporation Lakeland Division Lakeland, FL 33803
t) (					
PA-31-350: T.C. A8EA	SA1611SW	Mitchell automatic flight system AK413 consisting of altimatic IIIB-1 with optional automatic pitch trim, radio coupler, and glide slope couplers. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350: T.C. A8EA	SA1612SW	Mitchell automatic flight system AK416 consisting of autoflite II with optional tracking system. Issued 2/28/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-31-350: T.C. A8EA	SA1807SW	AP106 2-axis or 3-axis autopilot including yaw damper and FD-108 flight director. Issued 2/14/74.	SW	24252	Collins Radio Company Box 98 Addison, TX 75001
PA-31-350; T.C. A8EA	SA3015SW-D	Automatic flight system AK-498, cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio, and glide slope coupler. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3016SW-D	Automatic flight system AK499 and AK499FD cons. of Century IV flight director autopilot w/command automatic electric elevator pitch trim and opt. annunciator panel. Issued 8/16/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A8EA	SA3086SW-D	Automatic flight system AK560 cons. of Century III autopilot w/ opt. radio & glide slope couplers. Issued 11/27/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31-350; T.C. A8EA	SA3212SW-S	Mitchell automatic flight system Piper altimatic X autopilot, AK687 or AK687FD Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31-350; T.C. A20SO	SA4096WE	Installation of SDI model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 1/18/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-31P-425; T.C. A8EA	SA284GL	Install Cleveland conversion kit, P/N 199-83. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
PA-31P; T.C. A8EA	SA483SO	Installation of Bendix YD4 yaw damper system. Issued 12/23/71.	SO	15475	Bendix Avionics Division P.O. Box 8414 Ft. Lauderdale, FL 33310
PA-31P; T.C. A8EA	SA782CE	Installation of King Radio H-14 autopilot. Issued 6/71.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
PA-31P; T.C. A8EA	SA1265SW	Mitchell automatic flight system model AK323 cons. of Piper Autoflite II and Omni tracking system.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA1523SW	Mitchell automatic flight system AK395, cons. of Century autopilot w/opt. omni tracker. Issued 10/17/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3012SW-D	Automatic flight system AK484 cons. of Piper altimatic IIIC autopilot w/opt command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 8/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3013SW-D	Automatic flight system AK492 & AK492FD cons. of Century IV autopilot and Century IV flight director w/command automatic electric pitch trim and opt. annunciator panel. Issued 8/9/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3014SW-D	Automatic flight system YK493 cons. of yaw damper. Issued 8/8/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P; T.C. A8EA	SA3213SW-D	Mitchell automatic flight system Piper altimatic X autopilot, AK688 or AK688FD, Piper altimatic X flight director autopilot w/opt. remote annunciator. Issued 5/26/77.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-31P, -31T, -31T1; T.C. A8EA	SA1598CE	Installation of TSO'd stretcher. Issued 6/5/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street North Wichita, KS 67204
PA-31P, -31T, -31T1; T.C. A8EA	SA1617CE	Installation of cargo pod. Issued 12/2/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
PA-31T; T.C. A8EA	SA37NE	Installation of Global navigation GNS-500A series 2 VLF/Omega navigation system and associated components. Issued 11/17/80.	NE	74935	Stead Aviation Corporation Manchester Municipal Airport Manchester, NH 03103
PA-31T; T.C. A8EA	SA415GL	Installation of a Collins IPN 70 Omega navigation system. Issued 6/20/80.	GL	60568	Muncie Aviation Company P.O. Box 1169 Munci, IN 47305
PA-31T; T.C. A8EA	SA190GL	Install a J.E.T. DAC-2000 3-D RNAV system. Issued 8/16/77.	GL	46250	Jet Electronics and Technology, Inc. 5353 52nd Street N.E. Grand Rapids, MI 49508
PA-31T; T.C. A1EA	SA213GL	Installation of storm window in right hand cockpit window duplicating storm window now installed in left hand cockpit window. Issued 2/2/78.	GL	61629	Northern Airmotive, Inc. 3600 East 70th Street Minneapolis, MN 55450
PA-31T; T.C. A8EA	SA578SO	Instl. of a Bendix M-4D automatic flight control system, including optional manual electric pitch trim and flight director system. Amended 10/1/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-31T; T.C. A8EA	SA665NW	Installation of forward facing white lights, clear plastic wing tip tank nose cone. Issued 9/14/78.	NW	28850	Robert M. DeBorde 20645 S.W. Clarion Aloha, OR 97005
PA-31T; T.C. A8EA	SA1178SO	Installation of a Bendix FCS-8700 automatic flight control system including optional flight director. Issued 10/20/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FL 33310
PA-31T; T.C. A8EA	SA1188CE	Intallation of King KFC 300 automatic flight control system. Amended 4/15/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-31T; T.C. A8EA	SA4066SW	Auto-feather system 1. Issued 12/4/79.	EA	64665	Piper Aircraft Corporation 820 East Bald Eagle Drive Lockhaven, PA 17745
PA-31T, -31T1; T.C. A8EA	SA4016WE	Installation of SDI model CFS-2002, fuel flow indicating system. Amended 1/16/80.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
PA-31T1; T.C. A8EA	SA1053SO	Installation of FCS-870 automatic flight control system, including manual electric trim, optional yaw damper system, and optional flight director. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31T1; T.C. A8EA	SA1054SO	Installation of Bendix NP-2041A area navigation computer programmer. Issued 3/13/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-31T1; T.C. A8EA	SA1405CE	Install King KFC-250 autopilot/flight director. Amended 3/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32; T.C. A3SO	SA311NW	Installation of flap extension, spoiler L/E cuff and optional cambered wing tips. Issued 5/28/76.	NW	68500	Robertson Aircraft 839 W. Perimeter Road Renton, WA 98055
PA-32; T.C. A3SO	SA532SW	AK173 stabilizer.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32; T.C. A3SO	SA1523WE	Inst'l. of Brittain Model B-4A Flight Control System. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-32; T.C. A3SO	SA1607WE	Installation of Brittain Industries B-5 flight control system. Reissued 10/20/72.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
PA-32-260; T.C. A3SO	SA371EA	Zeiss aerial camera and intervalometer.	NE	71400	James W. Sewall Co. 147 Center Street Old Town, ME 00468
PA-32-260; T.C. A3SO	SA409GL	Installation of a Lycoming IO-540-K1A5 engine, Hartzell propeller and associated components. Issued 5/23/80.	GL	60179	Melvin C. Morkert 915 Montclair Drive Racine, WI 53402
PA-32-260; T.C. A3SO	SA533SW	Auto-Control III AK174.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA538SW	Piper Altimatic II autopilot and/or radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260; T.C. A3SO	SA1310SW	Stretcher in lieu of rear seats. Reissued 11/30/77.	SW	39320	Grand Prairie Flying Service Almyra Airport, Box 220 Almyra, TX 72203
PA-32-260; T.C. A3SO	SA1557WE	Installation of turbosupercharged Lycoming 0-540-E4B5 engine. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
PA-32-260, -32-300; T.C. A3SO	SA3NW	Installation of Van's Aircraft Model VA-1 fiberglass wheel fairings. Issued 8/1/72.	NW	82350	Van's Aircraft Route 2, Box 187 Forest Grove, OR 97116
PA-32-260, -32-300; T.C. A3SO	SA530CE	Install FluiDyne Model 4000 & 2500A skis.	GL	36060	FluiDyne Engr. Corp. 5900 Olson Memorial Hwy. Minneapolis, MN 55422
PA-32-260, -32-300; T.C. A3SO	SA939SW	Mitchell Manual Electric Pitch Trim System AK272.	SW	76067	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-32-260, -32-300; T.C. A3SO	SA1362CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-32-260, -32-300; T.C. A3SO	SA1568SW	Wing leading edge cuff, flow fences, optional wing tips and dorsal fin. Reissued 9/5/79.	CE	86195	Barbara or Bob Williams Box 431, 213 North Clark Udall, KS 67146
PA-32-260, -32-300; T.C. A3SO	SA2217WE	Installation of recontoured wing leading edge, raked wing tips, fuselage flap, stall fences, droop ailerons and dorsal fin (optional). Amended 1/27/71.	NW	68510	Charyl C. Robertson 1540 Sunset Highway Bellevue, WA 98007
PA-32-260, -32-300; T.C. A3SO	SA2933WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 Wardlow Road Long Beach, CA 90807
PA-32-260, -32-300; T.C. A3SO	SA3173SW-D	Automatic flight system AK174 cons. of Piper autocontrol IIIB autopilot w/opt radio coupler. Issued 12/20/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32S-300; T.C. A3SO	SA1172SW	Mitchell flight system AK304 cons. of Piper autoflite II with optional auto aileron stabilizer and tracking system. Issued 7/17/70.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32S-300; T.C. A3SO	SA1378SW	Mitchell automatic flight system AK320, cons. of Century I and opt. tracker. Issued 10/26/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300 -32S-300; T.C. A3SO	SA3011SW-D	Automatic flight system AK488 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electric elevator pitch trim, radio coupler, and glide slope coupler. Issued 7/22/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -32-300, -32S-300, -32-301, -301T; T.C. A3SO	SA3370SW-D	Mitchell automatic flight system, AK320, consisting of Century I and optional tracker. Issued 3/27/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-260, -300, -32R-300;	SA3736WE	Installation of an engine oil cooler hose. Issued 9/22/78.	WE	05550	Aircraft Metal Products Corp. 4206 Glencoe Avenue Venice, CA 90291
PA-32-260, -300, -32S-300, -32R-300; T.C. A3SO	SA3839WE	Installation of an air/oil separator. Issued 2/7/79.	WE	84396	Walker Engineering Company P.O. Box 8151 Van Nuys, CA 91409
PA-32-260, -300, -32R-300, -32RT-300, -32RT-300T; T.C. A3SO	SA364GL	For "T" tail configuration - installation of Norton radome kit No. 4229X. For conventional tail configuration - installation of Norton radome kit No. 4229XC. Amended 6/13/80.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Ceprations P.O. Box 350 Akron, OH 44309
PA-32-300: T.C. A3SO	SA893EA	Installation of 8-quart alcohol propeller anti-icing kit WAP-800A. Issued 12/15/71.	NE	86000	E. W. Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-32-300; T.C. A3SO	SA3305SW-D	Mitchell automatic flight system AK775 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 9/15/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300; T.C. A3SO	SA3306SW-D	Mitchell automatic flight system AK776, consisting of Century III autopilot with optional and glide slope couplers. Issued 9/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-300, -32R-300; T.C. A3SO	SA1154EA	Installation of radome pod SFRP-1011 or -1012 on right wing. Amended 12/6/79.	EA	08332	David L. Stanislaw d/b/a Airquip 1435 Horsham Road Ambler, PA 19002
PA-32-300, -32R-300; T.C. A3SO	SA3670WE	Installation of Silver Instruments Fueltron IG digital fuel flow indicating system. Issued 6/23/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-32-300, -32R-300, -32S-300, -32RT-300; T.C. A3SO	SA3774WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
PA-32-301, -301T; T.C. A3SO	SA3374SW-D	Mitchell automatic flight system AK872 consisting of command electric trim. Issued 6/16/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-301, -301T, -32R-301, -301T; T.C. A3SO	SA3361SW	Mitchell automatic flight system AK865 consisting of Century 41 autopilot or AK865FD consisting of flight director autopilot. Issued 5/9/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32-301, -301T, -32R-301, -301T; T.C. A3SO	SA3362SW-D	Mitchell automatic flight system AK864 consisting of Century 21 autopilot. Issued 5/22/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R; T.C. A3SO	SA21NE	Installation of Whelen A600-PR and A600-PG anti-collision strobe with forward and tail position light assemblies as replacements for wing tip lights. Issued 3/1/78.	NE	85500	Whelen Engineering Co., Inc. Winter Avenue Deep River, CT 06417
PA-32R-200; T.C. A3SO	SA3102SW-D	Mitchell AK591, consisting of Century IIB autopilot w/opt radio coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-200; T.C. A3SO	SA3103SW-D	Mitchell AK592 cons. of Century III autopilot w/opt. radio coupler and glide slope coupler. Issued 1/22/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA260GL	Install a Foster Airdata RNAV 511 area navigation system with 51ASA (Alpha) or 51DSA (Delta) steering adapter, or without either adapter. Amended 6/29/79.	GL	36520	Foster Airdata Systems, Inc. 7020 Huntley Road Columbus, OH 43229
PA-32R-300; T.C. A3SO	SA975SO	Installation of two 15-gallon auxiliary fuel tanks, one in each wing. Issued 4/5/78.	SO	28380	Cypress Aviation, Inc. 3480 Drane Field Road Lakeland Municipal Airport Lakeland, FL 33803
PA32R-300 S/N 32R-7680001 and up; T.C. A3SO	SA1201CE	Installation of King KFC 200, 2 axis, flight control system with a King KCS-55 (or -55A) compass and a King KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller. Amended 9/9/77.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32R-300; T.C. A3SO	SA3052SW-D	Mitchell automatic flight system AK529 cons. of Piper altimetric IIIC w/command/auto. elec. pitch trim, opt. radio coupler and glide slope coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3053SW-D	Installation of Mitchell automatic flight system AK530 cons. of Piper autocontrol IIIB autopilot with opt. radio coupler. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3054SW-D	Mitchell automatic flight system AK531 cons. of Piper autoflite II w/opt. omni tracker. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3055SW-D	Mitchell command/electric trim system Model AK532. Issued 5/21/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32R-300; T.C. A3SO	SA3513WE	Installation of Rajay turbocharged Lycoming IO-540-K1G5D engine. Issued 11/8/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
PA-32RT-300; T.C. A3SO	SA429GL	Installation of Edo-Aire Mitchell automatic flight system Model AK771 consisting of a Century IV autopilot. Issued 8/4/80.	GL	08364	Airtronics, Inc. P.O. Box 297 Clintonville, WI 54929
PA-32RT-300, -32RT-300T;	SA1159EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-32RT-300, PA-32RT-300T; T.C. A3SO	SA1430CE	Install King KFC-200 automatic flight control system. Issued 8/9/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-32RT-300; T.C. A3SO	SA3253SW-D	Mitchell automatic flight system AK677 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3254SW-D	Mitchell command electric trim system AK 678. Issued 2/13/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300; T.C. A3SO	SA3255SW-D	Mitchell automatic flight system AK 679 consisting of Century III autopilot with optional radio and glide slope couplers. Issued 1/5/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32RT-300T; T.C. A3SO	SA3309SW-D	Installation of Mitchell automatic flight system consisting of Century IV autopilot or AK771 consisting of flight director autopilot with optional remote annunciator. Issued 10/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-32S-300; T.C. A3SO	SA932EA	Installation of Pee Kay Model B3500 seaplane floats and Pee Kay Model 3500A amphibious floats. Issued 9/22/72.	EA	29998	Pee Kay DeVore Inc. 125 Mineola Avenue Roselyn Heights, NY 11577
PA-32S-300; T.C. A3SO	SA2253WE	Installation of Edo Model FD-3500-21 amphibious floats. Reissued 5/24/76.	NE	23370	T. M. Close Corporation Gardner Municipal Arpt. Box 464 Gardner, MA 01440
PA-32R-301, -32R-301T; T.C. A3SO	SA1522CE-D	Installation of King KFC 200 flight control system. Issued 12/17/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-34; T.C. A7SO	SA1363CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas City, KS 66103
PA-34; T.C. A7SO	SA2285SW	Camera and viewfinder installation. Issued 1/22/76.	SW	42825	A. D. Howard, Jr. 1911 Moulton Ct. Oklahoma City, OK 73127
PA-34-200; T.C. A7SO	SA154NW	Installation of full span flaps by removing aileron and changing deployment route of all flaps, spoilers mounted above flap, conical cambered wing tips, anti-balance rudder tab and optional dorsal fin. Issued 1/28/75.	NW	68500	Robertson Aircraft Corp. 839 W. Perimeter Road Renton, WA 98055
PA-34-200; T.C. A7SO	SA292NW	Installation of cooling louvers on top of both nacelle accessory sections. Issued 5/13/76.	NW	01530	Advanced Aviation 4911 S. 290th Place Auburn, WA 98002
PA-34-200; T.C. A7SO	SA493SO	Installation of Bendix FCS-810 (Piper altimatic V/FD) automatic flight control system including manual electric trim and optional flight director indicator. Issued 2/17/72.	SO	15475	Bendix Avionics Division P.O. Box 9414 Ft. Lauderdale, FI 33310
PA-34-200; T.C. A7SO	SA900EA	Installation of electrothermal propeller de-icer system. Amended 1/14/74.	GL	38500	B. F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200; T.C. A7SO	SA901EA	Installation of wing ice light kit. Amended 12/6/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200; T.C. A7SO	SA1321SW	Mitchell automatic flight system AK298 cons. of altimatic IIIB-1 autopilot w/opt automatic command electric pitch trim, radio coupler and glide slope coupler. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA1322SW	Mitchell automatic flight system Model AK335 cons. of Piper autocontrol III w/opt. radio coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-34-200; T.C. A7SO	SA1323SW	Mitchell command electric pitch trim Model AK321. Issued 6/2/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200; T.C. A7SO	SA2932WE	Installation of oxygen system. Amended 8/12/80.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA2937WE	Installation of turbosupercharged Lycoming IO/LIO-360-C1E6 engine. Amended 3/31/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
PA-34-200; T.C. A7SO	SA3002WE	Installation of wing tip fuel tanks of 17 gal capacity (each). Reissued [illegible]	WE	68501	Robertson Aircraft Corp. 2301 E. Utopia Rd. Phoenix, AZ 85024
PA-34-200, S/N 34-E4, S/N 34-7250001 and up; T.C. A7SO	SA903EA	Installation of B.F. Goodrich pneumatic de-icing system. Amended 11/1/72.	GL	38500	B.F. Goodrich Aerospace & Defense Products 500 S. Main Street Akron, OH 44318
PA-34-200, -34-200T; T.C. A7SO	SA50GL	Installation of Norton Radome Kit No. 40119K Amended 3/15/79.	GL	61750	Norton Company Plastics & Synthetics Div. Aero Product Division P.O. Box 350 Akron, OH 44309
PA-34-200, -34-200T; T.C. A7SO	SA510NW	Installation of Cessna fuel tank assembly. Issued 8/20/77.	NW	68500	Robertson Aircraft 839 West Perimeter Road Renton, WA 98055
PA-34-200, -34-200T; T.C. A7SO	SA3554WE	Installation of vertical tail floodlights on horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
PA-34-200T; T.C. A7SO	SA106RM	Installation of freon type air conditioning system. Reissued 1/31/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
PA-34-200T; T.C. A7SO	SA154RM	Install Symbolic Displays TSO'd Model CFS-2000 fuel flow meter and related systems. Issued 9/22/78.	RM	77280	Symbolic Displays, Inc. 8895 Montview Boulevard Hangar F Denver, CO 80220
PA-34-200T; T.C. A7SO	SA473GL	Installation of Airborne wing and empennage pneumatic deice kit, 711A or 711B. Reissued 1/12/81.	GL	62500	Parker Hannifin Corporation Airborne Division 711 Taylor Street Elyria, OH 44035
PA-34-200T; T.C. A7SO	SA968SO	Installation of Bendix FCS-870 automatic flight control system including manual electric pitch trim and optional flight director system. Issued 1/10/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7SO	SA969SO	Installation of NP-2041A area navigation computer programmer. Issued 1/9/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
PA-34-200T; T.C. A7SO	SA1118SO	Installation of Hartzell 3-bladed propellers, Models - PHC-C3YF-2( )UF/FC-7663-2R and PHC-C3YF-2L( )UF/FJC-7663-2R or PHC-C3YF--( )UF/FC-7663B-2R and PHC-C3YF-2L( )UF/FJC-7663B-2R. Issued 12/21/79.	GL	41000	Hartzell Propeller, Inc. 350 Washington Avenue Piqua, OH 45356
PA-34-200T; T.C. A7SO	SA1553CE-D	Installation of King KAS 297 altitude selector option. Issued 3/3/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-34-200T; T.C. A7SO	SA3023SW-D	Automatic flight system AK487 cons. of Piper altimatic IIIC autopilot w/opt. command/automatic electronic elevator pitch trim, radio, and glide coupler. Issued 9/6/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3028SW-D	Automatic flight system AK505 cons. of Piper auto-control IIIB auto-pilot w/opt. radio coupler. Issued 10/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3089SW-D	Mitchell automatic flight system AK561 cons. of Century III Auto-pilot w/opt radio coupler and glide slope coupler. Issued 12/29/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-34-200T; T.C. A7SO	SA3371SW-D	Installation of Mitchell automatic flight system AK881 consisting of Century 41 autopilot or AK881FD consisting of Century 41 flight director. Issued 1/6/81.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-34-200T; T.C. A7SO	SA3669WE	Installation of FUELTRON IIIG digital fuel flow indicating system. Issued 6/21/78.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
PA-34-200T; T.C. A7SO	SA4207WE	Installation of DTL-1000, -1001 and/or autopilot adapters for the Edo-Aire Mitchell Century III autopilot. Issued 8/8/80.	WE	47775	Douglas L. Fettler Apt. H 1212 North Broadway Escondido, CA 92026
PA-34-200T, -34-220T; T.C. A7SO	SA1147CE	Installation of King Model KFC 200 flight control system. Amended 1/19/81.	CE	48250	King Radio Corporation 400 N. Rogers Road Olathe, KS 66061
PA-34-200T, -34-220T; T.C. A7SO	SA3384SW-D	Installation of Mitchell flight system AK882 consisting of Century 21 autopilot. Issued 1/16/81.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-36; T.C. A9SO	SA277NW	Installation of automatic flagman. Issued 3/30/76.	NW	03500	Air Ag, Inc. City County Airport Walla Walla, WA 99362
PA-36; T.C. A9SO	SA1364CE	Chrome-plated brake disc installation. Issued 8/18/77.	CE	33468	Engineering Plating & Processing, Inc. 641 Southwest Blvd. Kansas Citym KS 66103
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	SA1291CE	Installation of Lycoming IO-720-A1B engine. Amended 4/17/79.	CE	11003	Mr. Clinton Anderson Nehawka, NB 68413
PA-36-285, -36-300 (Restricted Category); T.C. A10SO	SA3452WE	Installation of Lycoming IO-720-A1B engine and Hartzell HC-C3YR-1RF/F8475R constant speed propeller. Amended 2/5/79.	WE	46790	Johnston Aircraft Service, Inc. P.O. Box 1457 Tulare Municipal Airport Tulare, CA 93274
PA-36-285, -300, -375; T.C. A10SO	SA077GL	Installation of hopper gate positive metering device. Issued 11/26/80.	GL	50680	Eli Lilly and Company 740 South Alabama Street Indianapolis, IN 46285
PA-36-375; T.C. A10SO	SA3535WE	Installation of hydraulic system to power spray dispersal system. Issued 12/21/77.	WE	03290	Agrinautics 1333 Patrick Lane Las Vegas, NV 89119
PA-36-375; T.C. A10SO	SA3703WE	Installation of hydraulic power spray pump. Issued 7/27/78.	WE	03290	Agrinautics 1333 Patrick Lane Las Vegas, NV 89119
PA-39 Series; T.C. A1EA	SA816EA	Installation of 13 quart alcohol propeller anti-icing kit WAP-500B. Amended 10/15/71.	NE	86000	Wiggins Airways, Inc. Norwood Municipal Airport Norwood, MA 02062
PA-39 Series; T.C. A1EA	SA1342SW	Mitchell automatic flight system AK296 cons. of Piper altimatic IIIB-1 autopilot w/opt. automatic pitch trim, radio, and glide slope couplers. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1343SW	Mitchell automatic flight system AK325 cons. of Piper autoflite II w/opt. tracking system. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1344SW	Mitchell command electric trim AK267. Issued 7/20/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1386SW	Mitchell automatic flight system model AK339, cons. of Piper autocontrol III autopilot with optional radio coupler. Issued 11/16/71.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-39 Series; T.C. A1EA	SA1638SW	Mithcell automatic flight system AK355, consisting of Century I with omni tracker. Issued 4/9/73.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX ,76067

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
PA-40: T.C. A1FA	SA3028SW-D	Mitchell auto. flight system AK481, consisting of Piper altimatic IIIC autopilot with command automatic electric pitch trim system, optional radio, and glide slope couplers. Issued 10/28/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-40: T.C. A1FA	SA3036SW-D	Automatic flight system AK506 consisting of Piper autocontrol IIIB autopilot with optional radio coupler. Issued 12/31/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-44-180: T.C. A19SO	SA436GL	Installation of Tull microwave landing system airborne equipment. Issued 8/22/80.	GL	18320	Burlington Northern Airmotive 3600 East 70th Street Minneapolis, MN 55450
PA-44-180: T.C. A19SO	SA1158EA	Installation of DeVore "Tel-Tail" lights on lower surface of horizontal stabilator. Issued 7/17/79.	EA	29998	DeVore Aviation Corporation 206 Newtown Road Plainview, NY 11803
PA-44-180: T.C. A19SO	SA1504CE	Installation of King KFC 200 FCS (2 axis) with or without flight director. Issued 8/2/79.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
PA-44-180: T.C. A19SO	SA1628CE	Installation electronic rack provisions. Issued 1/6/81.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
PA-44-180: T.C. A19SO	SA3276SW-D	Installation of Mitchell automatic flight system AK 723 consisting of Piper autocontrol IIIB with optional radio couplers. Issued 4/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA44-180: T.C. A19SO	SA3277SW-D	Mitchell automatic flight system AK719 consisting of Piper altimatic IIIC autopilot with optional radio and glide slope couplers. Issued 4/7/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180: T.C. A19SO	SA3278SW-D	Mitchell command electric trim AK718.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180: T.C. A19SO	SA3287SW-D	Mitchell automatic flight system AK756 consisting of Century IIB autopilot with optional radio coupler. Issued 5/26/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180: T.C. A19SO	SA3288SW-D	Mitchell automatic flight system AK757 consisting of Century III autopilot with optional radio and and glide slope coupler. Issued 5/30/78.	SW	60000	Mitchell INdustries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180, -44-180T: T.C. A19SO	SA3375SW-D	Mitchell automatic flight system AK873 consisting of Century 41 autopilot or AK873FD. Issued 6/4/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180, -44-180T: T.C. A19SO	SA3376SW-D	Mitchell automatic flight system AK874 consisting of Century 21 autopilot. Issued 6/4/80.	SW	6000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
PA-44-180, -44-180T: T.C. A19SO	SA3377SW-D	Yaw damper system YK875. Issued 6/4/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
MISCELLANEOUS	SA788WE	Mixture monitor (exhaust gas temperature probe and gage). See FAA-approved eligibility list for models.	RM	39325	Grand Valley Aircraft, Inc. P.O. Box 158 Grand Junction, CO 81502

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

PIPER AIRCRAFT CORP., CALIFORNIA
Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
600; T.C. A17WE	SA1347SW	Alternate vent for fuel pressure gages. Issued 7/22/71.	SW	84250	Vought Aircraft Service Company Meacham Field Fort Worth, TX 76106
600; T.C. A17WE	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	M S Avionics 18145 Judy Street Castro Valley, CA 94546
600; T.C. A17WE	SA1675WE	Installation of M S Avionics EGT-2 exhaust gas monitoring system. Amended 8/28/74.	WE	48750	M S Avionics 18145 Judy Street Castro Valley, CA 94546
600 (S/N 60-0266-XX and up, and those aircraft with previously installed option #108); T.C. A17WE	SA3770WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 6/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
600, 601; T.C. A17WE	SA35GL	Install Cleveland Aircraft Products wheel and brake conversion kit, P/N 199-51. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
600, 601; T.C. A17WE	SA443SO	Instllation of Bendix RDR-110 weather radar system per Bendix drawing 4009700, Rev. B. Installation of Norton AD4059EX-5 radome approved per STC SA885EA. Issued 9/25/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601; T.C. A17WE	SA771CE	Installation of Woodward propeller unfeathering accumulator system. Issued June 1971.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601; T.C. A17WE	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
600, 601; T.C. A17WE	SA885EA	Installation of radome kit P/N 4059EX or 4059X. Reissued 9/29/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
600, 601; T.C. A17WE	SA1308SW	Addition of toilet provision. Issued 5/7/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1356SW	Fabricate and install rib-wing fairing-inboard (flap attachment bracket). Issued 8/13/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1362SW	Storage drawers under cabin seats. Issued 9/3/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76067
600, 601; T.C. A17WE	SA1363SW	Installation of pressure relief valves in fuel tanks. Issued 9/3/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1382SW	Modify two passenger seats to face aft. Issued 10/29/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1391SW	Dual hydrauic pump. Issued 11/12/71.	SW	84250	Vought Aircraft Services Company Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1452SW	Modfy Ted Smith control tube P/N A600128-3. Issued 3/30/72.	SW	84250	Vought Aircraft Services Compay Meacham Field Fort Worth, TX 76106
600, 601; T.C. A17WE	SA1797SW	Mitchell automatic flight system AK459 consisting of Century autopilot with optional omni tracker. Issued 1/30/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601; T.C. A17WE	SA2357WE	Installation of auxiliary hydraulic pump. Issued 5/28/71.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
600, 601; T.C. A17WE	SA3884WE	Installation of cabin door pneumatic spring counter-balance. Issued 4/5/79.	WE	64423	Physical Systems, Inc. 7049 Vineland Avenue North Hollywood, CA 91605
600, 601, 601P; T.C. A17WE	SA20GL	Installation of Woodward Type II electronic propeller synchronizer system. Amended 7/30/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601, 601P; T.C. A17WE	SA300CE	Installation of Woodward propeller governors on single and twin engine aircraft. Amended 7/30/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
600, 601, 601P; T.C. A17WE	SA444SO	Intallation of Bendix Model FCS 810 flight control system, including flight director indicator DH 841( ). Amended 6/3/76.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601, 601P; T.C. A17WE	SA980NW	Lycoming LTIO-, TIO-540-J2BD(MA) (modified by STC SE978NW), Hartzell HC-C3YR-2ULF/FJC-8468R-10Q and HC-C3YR-2UF/FC08468B-10Q propellers, aerodynamic performance package and associated systems. Issued 7/26/80.	NW	52625	Machen, Inc. South 3608 Davidson Boulevard Spokane, WA 99204
600, 601, 601P;	SA981NW	Installation of 35 amp batteries.	NW	52625	Machen, Inc. Spokane, WA 99204
600, 601, 601P; T.C. A17WE	SA982NW	Installation of an interior sound reduction package. Issued 7/16/80.	NW	52625	Machen, Inc. South 3608 Davidson Boulevard Spokane, WA 99204
600, 601, 601P; T.C. A17WE	SA983NW	Installation of a cabin air conditioner system. Issued 7/16/80.	NW	52625	Machen, Inc. South 3608 Davidson Boulevard Spokane, WA 99204
600, 601, 601P; T.C. A17WE	SA1089CE-D	Installation of Collins Radio Group AP-106 autopilot system and interface with Collins FD-112 flight director. Amended 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1090CE-D	Installation of Collins Radio Group AP-107 3-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1104CE-D	Installation of Collins Radio Group AP-107, 2-axis autopilot system and interface with Collins FD-112 flight director indicator. Issued 3/24/76.	CE	24250	Collins Radio Group Rockwell International Cedar Rapids, IA 52406
600, 601, 601P; T.C. A17WE	SA1139SO	Installation of a Bendix FCS-870 automatic flight control system. The following options are included: preselect altitude, yaw damper and flight director system. Issued 3/13/80.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
600, 601, 601P; T.C. A17WE	SA1174CE	Installation of Aero Space Controls Corp. 100 AMP alternator. Issued 10/31/75.	CE	02950	Aero Space controls Corporation 1050 North Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1175CE	Installation of Aero Space Controls Corp. air conditioning system. Issued 10/31/75.	CE	02950	Aero Space Controls Corporation 1050 Nort Mosley Wichita, KS 67214
600, 601, 601P; T.C. A17WE	SA1277CE	Installation of Avcon Industries TSO-C39a stretcher, P/N 4001-101 or 4001-102. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
600, 601, 601P; T.C. A17WE	SA1530CE-D	Installation of King KAS 297 altitude selector option. Issued 2/19/80.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
600, 601, 601P; T.C. A17WE	SA2336WE	Installation of Prestolite 70 amp alternators (Avco Lycoming P/N 78314) in lieu of existing 50 amp alternators. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA2367WE	Installaton of Prestolite 70 amp alternators (Avco Lycoming P/N 78314). Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
600, 601, 601P; T.C. A17WE	SA2655WE	Installation of auxiliary hydraulic pump option. Reissued 4/11/78.	WE	64666	Piper Aircraft corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
600, 601, 601P; T.C. A17WE	SA3029SW-D	Mitchell automatic flight system AK521 consisting of Century III autopilot with command automatic electric pitch trim system, radio, and glide slope couplers. Issued 11/27/74.	SW	60000	Mitchell Indusries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3030SW-D	Mitchell automatic flight system AK522 or AK522FD consisting of Century IV autopilot or Century IV flight director autopilot with command/automatic electronic pitch trim and optional annuciator panel. Issued 11/27/74.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3033SW-D	Automatic flight system AK455 consisting of Century I autopilot with optional omni tracker. Issued 1/9/75.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3343SW-D	Mitchell automatic flight system AK800/FD consisting of Century 41/flight director autopilot. Issued 6/27/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
600, 601, 601P (S/N 60-0266-XX and up and those aircraft with previously installed option #108); T.C. A17WE	SA3370WE	Installation of Silver Instruments fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 6/20/79.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
600, 601, 601P; T.C. A17WE	SA3372SW-D	Automatic flight system YK877 consisting of yaw damper system. Issued 6/27/80.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
600, 601, 601P; T.C. A17WE	SA3643WE	Installation of vertical tail floodlight. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
600, 601, 601P S/N 266 and up and aircraft with option 108 previously installed; T.C. A17WE	SA4029WE	Installation of SDI Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Issued 9/21/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
600, 601, 601P; T.C. A17WE	SA4144WE	Installation of 35 ampere-hour batteries. Issued 5/1/80	WE	74932	Starline Aircraft Company 3704 State Street, Suite 306 P.O. Box 6765 Santa Barbara, CA 93111
600, 601, 601P, 602P; T.C. A17WE	SA1184CE	Install King Model KFC-200 flight control system. Amended 1/6/81.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
600, 601, 601P, 602P; T.C. A17WE	SA2207WE	Installation of freon air conditioning system. Reissued 1/13/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
601; T.C. A17WE	SA2346WE	Installation of turbocharger overboost protection. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601; T.C. A17WE	SA2664WE	Modification of fuselage structure for pressurization to 3.20 psi operating pressure, and installation of pressurization system. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
601P; T.C. A17WE	SA61GL	Installation of radome kit P/N 4079RX or 4079X. Reissued 8/29/75.	GL	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 350 Akron, OH 44309

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

RAVEN INDUSTRIES, INC.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S-40A; T.C. A15CE	SB1WE	Replacement of Raven single burner system P/N 09645 with Raven two burner system P/N 10118 on Raven S-40 model balloon. Amended 10/2/75.	WE	70550	Scorpion Productions 246 Lomita Drive P.O. Box 1147 Perris, CA 92370
S-40A, S-50A, S-55A, RX-6; T.C. A15CE	SL163GL	Modification: Move the velcro 4 to 6 inches back away from the lip of the deflation port. Enlarge deflation panel. Amended 11/17/80.	GL	85870	Matt H. Wiederkehr 1604 Euclid Street St. Paul, MN 55106
S-40A, S-50A, S-60A; T.C. A15CE	SL575SO	Installation of ABP-181 automatic balloon pilot (automatic temperature control). Reissued 11/5/74.	SO	23345	J. Donald Cline 807 Larkwood Drive Greensboro, NC 27410
S-40A, -50A, -60A; T.C. A15CE	SL575SO	Installation of ABP-181 automatic balloon pilot (automatic temperature control). Reissued 11/5/74.	SO	23345	J. Donald Cline 807 Larkwood Drive Greensboro, NC 27410
S-40A, -50A, -60A; T.C. A15CE	SA1720SW	Install four burner can assembly. Issued 8/28/73.	SW	28308	Cutter Flying Service, Inc. P.O. Box 274 Albuquerque, NM 87108
S-40A, S-50A, S-55A, S-60A, RX-6; T.C. A15CE	SB4WE	Installation of digital readout balloon envelope temperature indicator. Issued 5/6/77.	WE	01450	Advanced Aircraft Components 1459 Irving Avenue Glendale, CA 91201
S-40A, -50A, -55A, -60A, RX-6, -7; T.C. A15CE	SB9WE	Installation of a digital readout balloon envelope temperature indicator. Issued 11/14/79.	WE	01450	Advanced Aircraft Components 1459 Irving Avenue Glendale, CA 91201
S-50A, S-55A, S-60A; T.C. A15CE	SL962SO	Installation of ball lock pins, MS 17985-545 or MS 17984-545. Amended 6/26/78.	SO	14285	Balloons, Inc. 1978 East Roxboro Road, N.E. Atlanta, GA 30324
S-55A; T.C. A15CE	SL211RM	Modification of suspension system and skirt of Raven S-55A hot air balloon envelope to achieve compatibility with Barnes Balloon Works gondola Models 4.0 and 4.5 and Model T3-017 burner system. Issued 2/18/81.	RM	66420	Raven Industries, Inc. P.O. Box 1007 Sioux Falls, SD 57117
S-60A; A15CE	SL164GL	Modification: Move the velcro 4 to 6 inches back away from the lip deflation panel. Issued 4/22/77.	GL	85870	Matt H. Wiederkehr 1604 Euclid Street St. Paul, MN 55106

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT

ROCKWELL INTERNATIONAL CORP., CALIFORNIA
Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265; T.C. A2WE	SA16GL	Incorporating AMF (Leland) inverters MGE 23-400. Reissued 11/17/78.	GL	50310	Leland Electrosystems, Inc. P.O. Box 128 Vandalia, OH 45377
NA-265; T.C. A2WE	SA687NW	Installation of Mark II system, increased take-off weight, wing modifications, modified A-O-A system, landing gear beef-up. Issued 11/15/78.	NW	66175	The Raisbeck Group 7777 Perimeter Road, South Seattle, WA 98108
NA-265 Series; T.C. A2WE	ST1031SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid type batteries. Issued 11/16/78.	SO	78053	Teledyne Battery Products 6520 Powers Ferry Road, N.W. Suite 200 Atlanta, GA 30339
NA-265; T.C. A2WE	SA1569SW	Battery temperature sensor warning system. Issued 12/14/72.	SW	84600	Ward Int'l Aircraft Services Location 2 West, Meacham Field Fort Worth, TX 76106
NA-265; T.C. A2WE	SA1854WE	Installation of aft ballast, optional large capacity batteries, heavy duty landing gear assemblies, and extended center of gravity limits. Reissued 7/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Capham Street El Segundo, CA 90245
NA-265, NA-265-20, -30, -40, -60, -70, -80; T.C. A2WE	SA1290CE	Installation of Avcon Industries TSO-C39a stretcher P/N 4006-103 and/or 4006-104. Amended 1/17/77.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street Wichita, KS 67204
NA-265, NA-265-20, -30, -40, -60, -70, -80; T.C. A2WE	SA3052WE	Installation of recognition light on horizontal stabilizer upper surfaces. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
NA-265-40; T.C. A2WE	SA139CE	General interior configuration, 7 place. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA140CE	Reclining passenger seat installation (Tpy). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA141CE	Swivel reclining passenger seat installation (Typ). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA142CE	Two place passenger couch installation. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA143CE	Crew and passenger oxygen system installation. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA171CE	General interior configuration, 8 place - version #2. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA172CE	Two place passenger seat installation (typ). Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA173CE	Electronics components package, version "A". Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA181CE	Two place passenger/baggage seat. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5501 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA204CE	General interior configuration, 9 place - version #4. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA205CE	Hand baggage rack installation, stations 147 - 206. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-40; T.C. A2WE	SA206CE	Auxiliary passenger seat installation, station 194. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA219CE	Electronics components package version E. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA220CE	Electronic components package version D. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA221CE	General interior configuration, 9 place version #5. Reissued 1/21/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA243CE	Electronics components package version G. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA244CE	Electronics components package version F. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA245CE	Auxiliary hand baggage rack installation, station 186. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA246CE	General interior configuration, 8 place - version #6. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA267GL	Installation of dual Marconi CMA-734 Omega navigation system. Amended 6/30/80.	GL	18752	Butler Aviation - O'Hare, Inc. P.O. Box 66139 Chicago, IL 60666
NA-265-40; T.C. A2WE	SA277CE	Electronic components package version H. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA314CE	Electronic components package version J. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA352CE	Engine vibration monitor installation, Airborne JT-12A6A engine. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA384CE	Electronic components package version K. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA401CE	Electronic components package version L. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA409CE	Electronics components package version M. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA431CE	Install Hoskins Twilighter Mk III supplemental lighting system. Reissued 5/4/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
NA-265-40; T.C. A2WE	SA449CE	Installation of H.F. transceiver, Sun Air Model 122-RA. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA450CE	Installation of electronics components package version N, Option A. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA475CE	Install 11 place interior, version #7. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA476CE	Passenger seat. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA477CE	Three place passenger seat. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-40; T.C. A2WE	SA509CE	Install ten-place interior, version #8. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA521CE	Installation of HF radio, SunAir Model ASB100. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA628CE	Installation of oxygen system pressure diluter demand, crew members - constant flow - passengers. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA637CE	Installation of electronics components package, version R. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA640CE	Installation of yaw damper control switch. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-40; T.C. A2WE	SA648CE	Installation of doppler/computer navigation system, Bendix DRA-12/CPA-24. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA699CE	Installation of electronic component package, version T. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA743CE	Installation of United Control Model F-542M flight data recorder system. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA846CE	Interior arrangement - installation of an aislewise divan. Issued August 1972.	CE	33580	EPM Corporation P.O. Box 5978 St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA860CE	Installation of electronics components package, version V. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA871CE	Electronic components package version W installation. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA875CE	Install eight-place interior, version #10. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA885CE	Installation of electronic components package, version Y. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA1057CE	Installation of electronic components package, version Z. Issued January 1975.	CE	68765	Sabreliner Division Rockwell International Lambert-St. Louis Int'l Airport St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA1460SW	Modification of 2-place aft couch installed under SA172CE to 3-place and add one oxygen dropout mask. Issued 5/5/72.	SW	29000	The Dee Howard Company P.O. Box 16216 San ANtonio, TX 78246
NA-265-40; T.C. A2WE	SA1232WE	Replacement of carbon pile voltage regulator for 30-volt DC generator with Leland Airborne Products Type CSV-11-5-2 solid state voltage regulator.	WE	13750	Aviation Power Supply, Inc. 3111 Kenwood Street Burbank, CA 91503
NA-265-40; T.C. A2WE	SA1374SW	Installation of avionics system. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40; T.C. A2WE	SA2596WE	Installation of Collins Model ALT-50 radio altimeter. Reissued 7/23/73.	WE	68770	North American Rockwell Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-40; T.C. A2WE	SA2597WE	Category II approval of airborne instruments and equipment when modified in accordance with STC SA860CE and SA2596WE. Reissued 7/23/73.	WE	68770	North American Rockwell Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-40, -40A; T.C. A2WE	SA1663SW	Teledyne avionics normalized angle of attack indicating system, P/N 112B600. Amended 8/27/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. P.O. Box 6400 Charlottesville, VA 22906
NA-265-40, -60; T.C. A2WE	SA67GI	Install B.F. Goodrich pneumatic de-icer system listed on Master Drawing List Report No. 74-04-047B, 11/6/74. Issued 11/22/74.	GL	38500	B.F. Goodrich Engineered Systems 500 South Main Street Akron, OH 44318
NA-265-40, -60; T.C. A2WE	SA718CE	Installation of hydraulic system fail audible warning system. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60; T.C. A2WE	SA859CE	Installation of twin Hamilton Standard R70-3W refrigeration unit. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60; T.C. A2WE	SA882CE	Installation of TRAMM BTI-600 battery temperature indicator and aircraft services division isolation system. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-365-40, -60; T.C. A2WE	SA926EA	Installation of Grimes three light strobe kit, P/N 34-0300-1, as supplemental lighting. Issued 7/7/72.	GL	39500	Grimes Manufacturing Company 515 NOrth Russell Street Urbana, OH 43078
NA-265-40, -60; T.C. A2WE	SA970CE	Installation of Sperry Model AA-220 radio altimeter. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60; T.C. A2WE	SA1013SW	Phoenix Aerospace, Inc. voltage regulator, VR-1010-24-1A. Issued 3/24/69.	SW	79650	Trio Aviation and Manufacturing Company, Inc. P.O. Box 20596 Dallas, TX 75220
NA-265-40, -60; T.C. A2WE	SA1266WE	Installation of rain repellant system. Amended 11/21/75.	WE	45500	Jay-Dee Aircraft Supply Co., Inc. 3021 Airport Avenue Santa Monica, CA 90405
NA-265-40, -60; T.C. A2WE	SA1365CE	Install compensated pitot static heads. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA265-40, -60; T.C. A2WE	SA1409CE	Rewire battery isolation relay system. Issued 4/14/78.	CE	84995	Wells Aircraft, Inc. Municipal Airport Hutichinson, KS 67501
NA265-40, -60; T.C. A2WE	SA1429CE	Removal of fuel jettisoning provisions. Issued 8/4/78.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60; T.C. A2WE	SA1725SW	Foxtronics/TRAMM BTI-600 nickel cadmium battery temperature indicator and optional TRAMM R-600 voltage control. Issued 11/7/73.	SW	36600	Foxtronics Box 7031 Dallas, TX 76901
NA-265-40, -60; T.C. A2WE	SA1726SW	Foxtronics/TRAMM SRL 66 battery isolation system. Issued 11/7/73.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
NA-265-40, -60; T.C. A2WE	SA1915SW	Emergency lighting. Issued 9/24/74.	SW	68768	Rockwell International Aviation Services Division 3300 Love Field Drive Dallas, TX 75235
NA-265-40, -60; T.C. A2WE	SA1960SW	Install engine oil pressure low caution light cutoff switches. Issued 3/24/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-40, -60; T.C. A2WE	SA2229SW	Foxtronics/TRAMM RG 100RF guard. Issued 8/8/75.	SW	36600	Foxtronics, Inc. P.O. Box 7031 Dallas, TX 75209

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-40, -60; T.C. A2WE	SA2787SW	Foxtronics external power overvoltage and control system. Issued 6/2/78	SW	36600	Foxtronics, Inc. P.O. Box 7031 Dallas, TX 75209
NA-265-40, -60; T.C. A2WE	SA3095WE	Installation of engine fuel drain sump tank. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
NA-265-40, -60; T.C. A2WE	SA4024SW	BKM anti-skid brake monitor system. Issued 7/27/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -65, -70, -80; T.C. A2WE	SA1545CE	Installation of protective cover No. DLC-2. Amended 3/10/80.	CE	44933	J & H Manufacturing Co., Inc. 511 East locus Carter Lake, IA 68110
NA-265-40, -60, -65, -70; T.C. A2WE	SA4223SW	Hydraulic fluid level warning and hydraulic pump run advisory system. Issued 10/31/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
t+1 NA-265-40, -60, -70; T.C. A2WE	SA756CE	Install Woodward engine synchronizer system. Amended 4/10/74.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
NA-265-40, -60, -70; T.C. A2WE	SA1162CE	Installation of P & D valve fuel reservoir. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60, -70; T.C. A2WE	SA1946SW	Engine fuel shut down system. Issued 1/17/75.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70; T.C. A2WE	SA1972SW	BKM 100-265 nose wheel steering control. Issued 4/9/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA265-40, -60, -70; T.C. A2WE	SA2789SW	Foxboro fuel management system. Issued 6/2/78.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70; T.C. A2WE	SA4096SW	Bleed air engine fuel manifold purge system. Issued 3/12/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70; T.C. A2WE	SA4137SW	Installation of engine starter inhibit circuit. Issued 6/10/80.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA746EA	Installation of Norton radome kit numbers, P/N 3090X-1, 3090X-10, 3090X-15, 3090X-20 or 3090X-30. Amended 5/18/79.	GL	61750	Norton Company Plastics & Synthetics Division Aero Products Operations P.O. Box 350 Akron, OH 44309
NA265-40, -60, -70, -80; T.C. A2WE	SA1338CE	Installation of Global GNS-500A VLF/Omega navigation system. Amended 6/23/80.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-40, -60, -70, -80; T.C. A2WE	SA1458CE	Installation of microwave landing system airborne equipment. Issued 11/7/78.	CE	86150	Wilcox Electric, Inc. 14th and Chestnut Kansas City, MO 64127
NA-265-40, -60, -70, -80; T.C. A2WE	SA1961SW	Entrance door counterbalance system. Issued 4/22/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2382SW	Change nose gear linkage and stop assembly to provide increased steering capability from 35 degrees to 45 degrees. Issued 11/16/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2388SW	Install diode across coil of hydraulic pump relay. Issued 11/24/76.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, 0-70, -80; T.C. A2WE	SA2701SW	Relocation of hydraulic pressure. Issued 12/22/77.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA265-40, -60, -70, -80; T.C. A2WE	SA2838SW	Installation of recognition lgihts. Issued 8/21/78.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209
NA-265-40, -60, -70, -80; T.C. A2WE	SA2933SW	BKM pitot heat monitor system. Issued 3/16/79.	SW	16850	The BKM Company P.O. Box 7001 Dallas, TX 75209

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-40, -60, -80; T.C. A2WE	ST996SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
NA-265-40, -60, -80; T.C. A2WE	SA1957SW	Additional hydraulic pressure switch. Issued 3/3/75.	SW	16850	The BKM Company Box 7001 Dallas, TX 75209
NA-265-60; T.C. A2WE	SA500CE	Installation of oxygen system. Amended 11/10/75.	CE	68765	Sabreliner Division Rockwell International St. Louis Int'l Airport 6161 Aviation Drive St. Louis, MO 63145
NA-265-60; T.C. A2WE	SA501CE	Installation of portable SunAir H.F. transceiver Model SA-14DA. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA502CE	Install a nine-place version No. 1 or version No. 1-3 or version No. 1-4 interior. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA503CE	Installation of electronic components package version A. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA522CE	Install 12-place interior. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA540CE	Installation of electronics components package version B. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA549CE	Installation of electronics components package version D. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA565CE	Install 8-place version 3 interior. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA596CE	Installation of electronics components package, version E. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA597CE	Installation of dual RCA AVQ-75 DME with hold feature. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA654CE	Installation of electronics components package, version F. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA685CE	Install a ten-place interior, version No. 4. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA705CE	Installation of electronics components package, version G. Reissued 1/10/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008
NA-265-60; T.C. A2WE	SA804CE	Installation of electronic components package, version H. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA817CE	Install aislewise divan.	CE	33580	EPM Corporation P.O. Box 5978 Lambert Field St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA818NW	Installation of Goodyear brake assembly, P/N 9550338-1. Issued 8/1/79.	NW	66175	The Raisbeck Group 7777 Perimeter Road South Seattle, WA 98108
NA-265-60; T.C. A2WE	SA839CE	Installation of ten-place interior, version No. 5. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-60; T.C. A2WE	SA896CE	Installation of electronic components package, version K. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA897CE	Installation of 9 place version No. 6. Amended 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA265-60; T.C. A2WE	SA958CE	Installation of 12-place interior Version No. 7. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA996CE	Installation of electronic components package, version L. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1012CE	Install interior, version No. 8. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1014CE	Cockpit voice and flight data recorder, altitude alerter system and encoding and weather radar. Amended November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1075CE	Aft lavatory auxiliary seat installation. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1078CE	Aft lavatory and auxiliary L.H. installation. Issued February 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1092CE	Installation of electronic components package, version M. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1139CE	Install aft facing forward L.H. seat installation. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1146CE	Interior installation, version No. 9. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1148CE	Installation of electronic components package, version N. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1149CE	Installation of electronic components package, version P. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1182CE	Auxiliary seat and baggage area installation. Issued 11/25/75.	CE	68765	Sabreliner Division Rockwell International 11101 Natural Bridge Road Bridgeton, MO 63044
NA-265-60; T.C. A2WE	SA1191CE	Aisle facing seat and baggage area. Issued 1/6/76.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1221CE	Install interior, version No. 10. Issued May 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1242CE	Install Collins ADF-60A automatic direction finding and Intercontinental Dynamics Corp. RAD/BAR with voice terrain advisory system. Amended September 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1247CE	Forward lavatory L.H. installation. Issued July 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-60; T.C. A2WE	SA1285SW	Installation of Collins 937R-1 weather radar antenna and WXR-80 weather radar system. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1339CE	Aft lavatory installation. Issued 7/6/77.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1349SW	Installation of a 3-place couch. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1367CE	Interior installation, Version No. 11. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1379CE	Install Collins FPC-75 GPWS, IDC SAT/TAS Collins ALT-55B radio altimeter and Wulfsberg Flitefone III provisions. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1385CE	Install electronic components package Version "R". Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1386CE	Install electronics components package Version "Q". Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60; T.C. A2WE	SA1392CE	Install Global GNS-500A VLF/OMEGA navigation system. Issued 12/29/77.	CE	59270	Midcoast Aviation Services, Inc. Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1421CE	Install convertible baggage, aisle facing seat. Issued 6/12/78.	CE	59270	Midcoast Aviation Services Lambert Field St. Louis, MO 63145
NA265-60; T.C. A2WE	SA1434CE	Interior installation Version No. 12. Issued 9/19/78.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63775
NA-265-60; T.C. A2WE	SA1476SW	Normalized angle of attack indicating system. Amended 8/27/76.	EA	78000	Teledyne Avionics Div. of Teledyne Industries, Inc. Box 6400 Charlottesville, VA 22906
NA-265-60; T.C. A2WE	SA1811WE	Installation of reinforced structure and certain components in partial provision for UCAR configuration. Reissued 7/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60; T.C. A2WE	SA1912WE	Installation of nose boom extension and/or doppler radome and fairing. Amended 5/8/69.	RM	81160	University Corporation for Atmospheric Research P.O. Box 1470 Boulder, CO 80302
NA-265-60; T.C. A2WE	SA2878SW	Install two two-place side facing couches. Issued 12/5/78.	SW	04540	Air Center, Inc. P.O. Box 32168 Oklahoma City, OK 73132
NA-265-60, Serial No. 306-23 and subsequent; T.C. A2WE	SA3042WE	Installation of engine fuel drain sump tank. Reissued 5/30/79.	WE	78490	Tiger Air Service Center, Inc. 3000 North Clybourn Avenue Burbank, CA 91505
NA-265-60, -70; T.C. A2WE	SA737CE	Installation of Solar APU Model T-62T-39 and T-62T-39Y. Reissued 6/23/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-60, -80; T.C. A2WE	SA1129CE	Installation of IFR delivery package. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-60, -80; T.C. A2WE	SA1479CE	Installation of forward auxiliary fuel cell (56 gallons). Amended 4/30/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-65; T.C. A2WE	SA1537CE	Installation of Solar Model T-62T-40C auxiliary power unit (APU). Issued 12/29/79.	CE	68765	Rockwell International Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-65; T.C. A2WE	SA1603CE	Installation of Collins FPC-75 ground proximity warning system. Issued 10/1/80.	CE	68765	Sabreliner Division Rockwell International Route 3 Perryville, MO 64105
NA-265-65; T.C. A2WE	SA1611CE	Modification to incorporate fuel management computer. Issued 10/6/80.	CE	24540	Colt Electronics Company 15301 West 109th Street Lenexa, KS 66219
NA-265-70; T.C. A2WE	SA816CE	H.F. antenna installation. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA824CE	Audible hydraulic pressure warning system. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA858CE	Installation of Tramm BTI-600 battery temperature indicator system. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA869CE	Installation of RCA AVQ-21 weather radar. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA870CE	Installation of Collins ALT-50 radio altimeter. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA939CE	Installation of 7-passenger interior arrangement. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA959CE	Installation of 7-passenger interior. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA969CE	Installation of 7-passenger interior. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA1248CE	Installation of Collins AP104/FD109H automatic flight control system. Issued November 1976.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-70; T.C. A2WE	SA2766WE	Replacement of existing engines with GE CF700-2D-2 fan jet engines. Issued 10/31/73.	WE	68770	Rockwell International Corp. Sabreliner Division 827 Lapham Street El Segundo, CA 90245
NA-265-80; T.C. A2WE	SA995CE	Install electronic components package, version A. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA997CE	Install interior, version No. 2. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1015CE	Installation of electronic components package Version "C". Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1026CE	Install interior, version No. 3. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1028CE	Installation of electronic components package, version B. Issued 1/20/75.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1043CE	Installation of electronic components package, version D. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-80; T.C. A2WE	SA1065CE	Installation of electronic components package, version E. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1066CE	Installation of Teledyne angle of attack indicating system SL112B1400. Issued December 1974.	CE	68765	Sabreliner Division Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1067CE	Auxiliary seat installation. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1074CE	Auxiliary seat installation. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1100CE	Interior installation No. 4. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1101CE	Installation of cockpit voice recorder and flight data recorder. Issued April 1975.	CE	68765	Sabreliner Division Rockwell International 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1132CE	Install aft lavatory auxiliary seat. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1133CE	Interior installation, FAA Airways Checker. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Rockwell International Corp. 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1142CE	Interior installation, version No. 5. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1249CE	Interior installation, version No. 6 (wide body). Issued August 1976.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1272CE	Interior installation, version No. 7.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1274CE	Installation of electronic components package, Version "F". Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1275CE	Interior installation, version No. 8.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1288CE	Interior installation, version No. 9. Issued November 1976.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1293CE	Commode installation - aft lavatory. Issued January 1977.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1323CE	Interior installation, No. 10. Issued May 1977.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1329CE	Installation of Collins NCS-31A navigation control system with dual control heads, HI-350 remote compass and Collins 728U-5 HF transceiver system. Issued 5/20/77.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1337CE	Installation of Intercontinental Dynamics cCorp. vertical navigation system. Issued 5/21/77.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
NA-265-80; T.C. A2WE	SA1342CE	Install electronics components package, Version "G". Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA1374CE	Installation of 800 VA and 2500 VA static inverters. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA265-80; T.C. A2WE	SA1387CE	Passenger compartment wiring provisions installation. Reissued 1/28/81.	CE	68765	Rockwell International Corp. Sabreliner Division 6161 Aviation Drive St. Louis, MO 63134
NA-265-80; T.C. A2WE	SA3974WE	Installation of Litton LTN-72R area navigation system. Issued 7/6/79.	WE	11620	Area Equipment Company, Inc. 7707-1/2 Woodley Avenue Building 901 Van Nuys, CA 91406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500, 111 Series; T.C. 6A1, A11SO	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
500, 520, 560 Series; T.C. 6A1, 2A4	SA1-64	Federal F-400 autopilot.	GL	04750	Aircraft Components, Inc. 755 Woodward Avenue Benton Harbor, MI 49023
500, 520, 560 Series; T.C. 6A1, 2A4	SA4-777	Aerofilter 30409A-12 or full flow filter 30409A with element 1A0235.	WE	86625	Winslow Aerofilter Corp. 4069 Hollis Street Oakland, CA 94608
500, 520, 560 Series; T.C. 6A1, 2A4	SA4-1414	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
500, 520, 560; T.C. 6A1	SA1629CE	Installation of Avcon stretcher. Issued 1/13/81.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
500, 520, 560, 680; T.C. 6A1, 2A4	SA1-385	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500, 520, 560, 680; T.C. 6A1, 2A4	SA3-259	Collins glide slope, VOR, navigation and VHF communications antenna; Aircraft Radio Corp. ADF antenna; and Grimes rotating beacons.	GL	59635	Minnesota Airmotive, Inc. Wold-Chamberlain Field Minneapolis, MN 55401
500, 520, 560, 680; T.C. 6A1, 2A4	SA3-721	Cabin temperature control system with Janitrol S-25 heater.	GL	82540	Vapor Heating Corp. 6444 West Howard Street Chicago, IL 60607
500, 520, 560, 680; T.C. 6A1, 2A4	SA102EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500, 520, 560, 680; T.C. 6A1, 2A4	SA133CE	Windshield wiper.	GL	27500	Marquette Division Curtiss-Wright Corporation 1145 Galewood Drive Cleveland, OH 44110
500, 520, 560, 680, 720; T.C. 6A1, 2A4	SA256WE	Control wheel replacement.	WE	34030	Executive Radio and Aircraft Service, Inc. 3011 Airport Avenue Santa Monica, CA 90406
500, 520, 560, 680, 720; T.C. 6A1, 2A4	SA260SW	Protective device in ground side of battery and external power relays.	SW	61623	Commander Service Center Airframe #2082 Aero Commander Division Bethany, OK 73008
500, 520, 560 Series; T.C. 6A1, 2A4	SA559SW	Aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
500, 520, 560, 680, 681, 720; T.C. 6A1, 2A4	SA798EA	Installation of Monitair exhaust gas combination monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
500, 560, 680; T.C. 6A1, 2A4	SA1-93	RCA AVQ-50 radar equipment and AVQ-50 antenna mounting bracket.	EA	67000	Reading Aviation Services, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
500, 560, 680; T.C. 6A1, 2A4	SA1-142	Modified ARC A13-B antenna.	GL	73884	Southern Ohio Aviation Company P.O. Box 367 Vandalia, OH 45377
500, 560, 680; T.C. 6A1, 2A4	SA1-445	ARC Type A13-B VHF navigational antenna on vertical fin.	GL	73884	Southern Ohio Aviation Company 10600 Springboro Pike Miamisburg, OH 45342
500, 560, 680; T.C. 6A1, 2A4	SA1-525	ARC A13-B antenna on vertical fin with rotating beacon.	EA	02273	Aero Industries P.O. Box T Byrd Airport Sandston, VA 23150
500, 560, 680; T.C. 6A1, 2A4	SA1-624	Oxygen system.	EA	35600	The Firewel Company, Inc. 3695 Broadway Buffalo, NY 14240

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500, 560, 680; T.C. 6A1, 2A4	SA13WE	M-4 autopilot. Amended 2/24/67.	SO	15475	The Bendix Corporation P.O. Box 9414 Fort Lauderdale, FL 33310
500, 560, 680; T.C. 6A1, 2A4	SA84SW	Automatic pilot.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500, 560, 680; T.C. 6A1, 2A4	SA114CE	Windshield anti-ice system.	GL	25390	Commander Aviation, Inc. Municipal Airport Pontiac, MI 48053
500, 560, 680; T.C. 6A1, 2A4	SA115EA	Pump type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
500, 560, 680; T.C. 6A1, 2A4	SA120CE	Windshield anti-ice system.	GL	38500	Commander Aviation, Inc. Municipal Airport Pontiac, MI 48053
500, 560, 680 Series; T.C. 6A1, 2A4	SA137CE	Lower window line in cabin area.	CE	47650	Kansas City Flying Service Municipal Airport Kansas City, MC 64108
500, 560, 680 Series; T.C. 6A1, 2A4	SA258SW	Camera and camera view finder opening in main cabin floor of 30" x 39" maximum dimension.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
500, 560, 680 Series; T.C. 6A1, 2A4	SA396SW	Automatic pilot AK118, lateral guidance radio coupler AK123, and pitch trim AD135.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
500, 560, 680 Series; T.C. 6A1, 2A4	SA491EA	Incorporation of B.F. Goodrich ice protection systems.	GL	38500	B.F. Goodrich Aerospace and Defense Products Div. of B.F. Goodrich Company 500 South Main Street Akron, OH 44318
500, 560, 680 Series; T.C. 6A1, 2A4	SA666SW	Forward cabin door.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, CK 73109
500, 560, 680 Series; T.C. 6A1, 2A4	SA1064SW	Wild RC-8 aerial survey camera. Issued 8/8/69.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
500, 560, 680 Series; T.C. 6A1, 2A4	SA1125SW	Aerial survey camera and navigation. Issued 3/2/70.	SW	47770	Kerr Aviation Services, Inc. P.O. Box 399 Bethany, CK 73008
500, 560, 560A, 560E, 680, 680E; T.C. 6A1, 2A4	SA4-454	Installation of fiberglass vertical stabilizer cap in lieu of metal; repositioning of rotating beacon mounting to leading edge; reduction of length of the two spar extensions to facilitate VHF antenna installation inside stabilizer cap area. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500, 560, 680, 720; T.C. 6A1, 2A4	SA4-443	Fiberglas wing tips. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500, 560, 680, 720; T.C. 6A1, 2A4	SA4-1234	Installation of electrical low fuel warning device to indicate last 25 gallons of useable fuel in main (center) tank. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
500, 600 Series; T.C. 6A1, 2A4	SA1454WE	Installation of Brittain Model B-4A flight control system.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
500, 600 Series; T.C. 6A1, 2A4	SA1580WE	Installation of Brittain Model B-5 flight control system.	SW	17490	Brittain Industries P.O. Box 51370 Tulsa, OK 74151
500, 680 Series; T.C. 6A1, 2A4	SA798SW	Radome nose extension. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130
500, 680 Series; T.C. 6A1, 2A4	SA863SW	Modified instrument panel. Reissued 2/14/75.	SO	34808	Federal Express Corporation P.O. Box 30167 - AMF Memphis, TN 38130

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
500, 600 Series; T.C. 6A1, 2A4	SA1182SW	Dual camera and navigation sight. Issued 8/19/70.	SW	47770	Kerr Aviation Services, Inc. P.O. Box 399 Bethany, OK 73008
500, 680, 720 Series; T.C. 6A1, 2A4	SA265EA	Installation of Chamberlain radome kit #2001K-B for use with Bendix radar RDR-100 or RDR-110. Amended 3/11/70.	GI	61750	Norton Company Plastics & Synthetics Division Aero Product Operations P.O. Box 1187 Akron, OH 44309
520; T.C. 6A1	SA315SO	Nose weather radar and radome.	SO	34010	Executive Aviation Peachtree-DeKalb Airport Chamblee, GA 30005
520; T.C. 6A1	SA2279WE	Removal of main cabin door. Issued 11/23/70.	RM	74760	Sportsman International, Ltd. 3559 Brighton Boulevard Denver, CO 80216
520, 560 Series; T.C. 6A1	SA50CE	C210310 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
520, 560 Series; T.C. 6A1	SA51CE	C210403 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
520, 560, 680 Series; T.C. 6A1, 2A4	SA3-118	ARC Type A-13B VHF navigational antenna.	GI	72252	Skymotive, Inc. FAA Repair Station 3712 P.O. Box 448 Park Ridge, IL 60068
520, 560, 680 Series; T.C. 6A1, 2A4	SA4-447	Fiberglass wing tips. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monica, CA 90405
560 Series; T.C. 6A1	SA1-46	Bendix A1313 Omni antenna on top of fuselage.	SO	78390	Tempo Design Company P.O. Box 456 Miami, FL 33148
560 Series; T.C. 6A1	SA1-92	Fuselage to accommodate aerial photographic equipment.	EA	67000	Reading Aviation Service, Inc. P.O. Box 1201 Municipal Airport Reading, PA 19603
560 Series; T.C. 6A1	SA1-342	Oil-free vacuum pump.	GI	11880	Associate Aircraft Tool & Manufacturing, Inc. 3660 Dixie Highway Hamilton, OH 45012
560 Series; T.C. 6A1	SA1-455	ANC-3A computer and ANC-C2 or ANC-D2 controller in conjunction with Lear L2C autopilot.	EA	30150	Dynavia Corporation 3021 West Clay Street Richmond, VA 23219
560 Series; T.C. 6A1	SA1-652	Dry vacuum pump and instrument vacuum system.	GI	03760	Airborne Mechanisms Division Randolph Manufacturing Company 13229 Shaw Avenue East Cleveland, OH 44112
560 Series; T.C. 6A1	SA118CE	Hydraulic unfeathering accumulators 210320 and new propeller governors.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
560 Series; T.C. 6A1	SA193SO	Turbocharged Lycoming GO-480C1B6 or GO-480-C1B6 engines, per STC SE124SO. Reissued 1/14/69.	WE	66250	Rajay Industries 2602 East Wardlow Road Long Beach, CA 90807
560 Series; T.C. 6A1	SA367EA	Opening in lower surface fuselage to accommodate cameras.	EA	52060	Long Island Airways, Inc. P.O. Box 248 Ronkonkoma, NY 11779
560 Series; T.C. 6A1	SA585SW	Nose cone. Amended 7/31/68.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78216
560, 560A; T.C. 6A1	SA136SO	Turbocharged Lycoming GO-480-D1A engine. Reissued 1/14/69.	WE	66250	Rajay Industries 2602 East Wardlow Road Long Beach, CA 90807
560, 680; T.C. 6A1, 2A4	SA1-653	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
560, 680; T.C. 6A1, 2A4	SA3-406	RCA AVQ-50 weather avoidance radar.	GL	72252	Skymotive, Inc. FAA Repair Station 3712 P.O. Box 448 Park Ridge, IL 60068

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
560, 680; T.C. 6A1, 2A4	SA4-1382	L2-C autopilot.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
560, 680; T.C. 6A1, 2A4	SA4-1442	AP-102 autopilot.	CE	24250	Collins Radio Company 855 34th Street, NE Cedar Rapids, IA 52401
560, 680; T.C. 6A1, 2A4	SA4-1579	Aerofilter 30690B full flow lube oil filter with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
560, 680 Series; T.C. 6A1, 2A4	SA29SW	Auxiliary outboard fuel tank.	SW	08235	Air-Mod Engineering Company P.O. Box 201-W Oklahoma City, OK 73125
560, 680 Series; T.C. 6A1, 2A4	SA38CE	B21043 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
560, 680 Series; T.C. 6A1, 2A4	SA199SW	Four auxiliary fuel cells in each outer wing panel between wing stations 127 and 163.	SW	08235	Air-Mod Engineering Company Hangar #2, Wiley Post Airport Bethany, CK 73008
560, 680 Series; T.C. 6A1, 2A4	SA231CE	Twin engine synchronizer.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
560, 680 Series; T.C. 6A1, 2A4	SA1512WE	Installation of exhaust gas temperature monitoring system, Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Vally, CA 94546
560, 680 Series; T.C. 6A1, 2A4	SA1675WE	Installation of KS Avionics EGT-2 monitorng system. Amended 8/28/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
560, 680 Series; T.C. 6A1, 2A4	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
560 Series, 680FL, FL(P); T.C. 6A1, 2A4	SA179EA	Installation of electrothermal propeller deicing system. Amended 3/24/67.	GL	38500	The B.F. Goodrich Company 500 South Main Street Akron, OH 44318
560, 680, 720; T.C. 6A1, 2A4	SA1-520	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
560, 680, 720; T.C. 6A1, 2A4	SA4-455	Hamilton Standard governors IM12-G5.	WE	34030	Executive Radio and Aircraft Service, Inc. 3011 Airport Avenue Santa Monica, CA 90406
560, 680, 720; T.C. 6A1, 2A4	SA4-989	Aerofiter 30690B full flow lube oil filter with element 1A0286.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
560, 680, 720; T.C. 6A1, 2A4	SA4-1655	Outer wing non-icing fuel tank vent fairings.	WE	06750	Aircraft Tank Service, Inc. 10201 Cohasset Street Burbank, CA 91504
560, 680, 720; T.C. 6A1, 2A4	SA91CE	Hoskins high intensity wing tip lights, tail light and high intensity fuselage lights.	GL	42626	Donald E. Hoskins 4980 Marine Drive Chicago, IL 60607
560, 680, 720; T.C. 6A1, 2A4	SA132EA	Electrothermal propeller deicing system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
560, 680, 720; T.C. 6A1, 2A4	SA600WE	Brittain flight control system B-4, incluing pitch assist PC-1, altitude hold AH-1, and navigation coupler NAV-1. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
560A, E, F, 680, E, F; T.C. 2A4, 6A1	SA584WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
560E; T.C. 6A1	SA1966WE	Removal of main cabin door.	RM	16780	Steve Biljanic Box 133 Midvale, UT 84047

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
560F; T.C. 2A4	SA1080CE	Installation of Collins Radio Group AP-107 autopilot system. Issued March 1975.	CE	24250	Collins Radio Group Rockwell International 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
560F; T.C. 2A4	SA1130CE	Installation of Collins Radio Group electric trim system. Issued April 1975.	CE	24250	Collins Radio Group 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
560-F, 680, 680-E, 680F, 720; T.C. 2A4	SA290GL	Install Cleveland conversion kit No. 199-74 on listed models which use MIL-H-5606 brake fluid (red oil) or kit No. 199-74A on listed models which use Skydrol brake fluid (nonpetroleum base). Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
560F, 680, 680F; T.C. 2A4	SA3405WE	Installation of fuselage fuel tank. Issued 5/24/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
560F, 680E, 680F, 680FL, 680FLP, 680W; T.C. 2A4	SA3477WE	Replacement installation of tail cone assembly. Issued 9/7/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
560F, 680, 680E, 680F, 680FL, 680FLP, 680W; T.C. 2A4	SA3493WE	Replacement installation of vertical tip assembly. Issued 10/3/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
560F, 680F; T.C. 2A4	SA3517WE	Installation of cockpit overhead windows. Issued 12/23/77.	WE	69220	Mr. R.P.M., Inc. Suite 321 7120 Hayvenhusrt Avenue Van Nuys, CA 91406
560F, 680F, 680FL, 680FL(P), 690, 690A; T.C. 2A4	SA497GL	Install aircraft wheel and brake conversion kit 199-80 (MIL-H-5606 system). Issued 1/23/81.	GL	62500	Parker Hannifin Corporation Aircraft Wheel & Brake Division Avon, OH 44011
600 Series; T.C. 2A4	SA1-83	Camera in fuselage tail section.	GL	73884	Southern Ohio Aviation Company P.O. Box 367 Vandalia, OH 45371
600, S2D; T.C. A3SW, A4SW	SA113NW	Installation of EAC 3D40-401 AG-100-2 propeller with 4M121-1 propeller governor. Issued 5/24/74.	NW	33000	Efficiency Aircraft P.O. Box 37 Kent, WA 98031
680 Series; T.C. 2A4	SA1-68	Dual Wilcox ADF radio loop antenna.	GL	61790	Ohio Aviation Company P.O. Box 305 Vandalia, OH 45377
680 Series; T.C. 2A4	SA1-231	Bendix fuel flow indicating system.	GL	37830	General Tire & Rubber Company 1708 Englewood Avenue Akron, OH 44309
680 Series;	SA1-249	Fuel flow indicating system.	NE	61240	National Lead Company P.O. Box 365 Stratford, CT 06497
680 Series; T.C. 2A4	SA1-300	Bendix fuel flow indicating system.	EA	12700	Lycoming Division Avco Manufacturing Company Service Hangar Montoursville, PA 17754
680 Series; T.C. 2A4	SA1-442	ANC-3A computer and ANO-C2 or ANC-D2 controller with Lear L2C autopilot.	EA	31050	Dynavia Corporation 3021 West Clay Street Richmond, VA 23219
680 Series; T.C. 2A4	SA1-476	SP-3 autopilot EB2597034.	EA	74574	Sperry Gyroscope Company Division of Sperry Rand Corp. MacArthur Field Ronkonkoma, NY 11779
680 Series; T.C. 2A4	SA1-552	Pesco 2 P-R400-BRD fuel pumps.	SW	28590	Island Service Division Dallas Airmotive, Inc. Galveston, TX 77550
680 Series; T.C. 2A4	SA3-32	AP-101 automatic pilot.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA3-112	Oil separators in vacuum pump outlet lines.	GL	16886	Bohling Aircraft Corporation 5324 West 63rd Street Chicago, IL 60607
680 Series; T.C. 2A4	SA3-120	Relocation of aircraft battery to hose station 8. Reissued 10/1/70.	SW	61623	North American Rockwell Corp. 5001 North Rockwell Avenue Bethany, OK 73008

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
680 Series; T.C. 2A4 t) (t+1	SA3-145	AP-101 automatic pilot.	GL	59635	Minnesota Airmotive, Inc. Wold-Chamberlain Field Minneapolis, MN 55450
680 Series; T.C. 2A4	SA3-301	Hand-operated hydraulic pump deactivated or removed and replaced with electric-driven equivalent.	GL	19850	Capitol Aviation, Inc. Capital Airport Springfield, II 62705
680 Series; T.C. 2A4	SA3-349	Bendix fuel flow indicator system.	GL	72252	Skymotive, Inc. P.O. Box 448 Park Ridge, II 60068
680 Series; T.C. 2A4	SA3-350	AP-11 automatic pilot.	SW	24252	Collins Radio Company P.O. Box 98 Addison, TX 75001
680 Series; T.C. 2A4	SA4-240	Electric hydraulic pump.	WE	61870	On Mark Engineering Company 7929 Hayvenhurst Avenue Van Nuys, CA 91408
680 Series; T.C. 2A4	SA4-530	Radio rack aft of baggage compartment.	RM	05940	Aircraft Radio and Accessory Company, Inc. Stapleton Airfield Denver, CO 80202
680 Series; T.C. 2A4	SA4-551	L-102B automatic pilot.	WE	49858	Lear, Inc. 3171 South Bundy Drive Santa Monica, CA 90406
680 Series; T.C. 2A4	SA65SW	Support and opening in bottom of fuselage for Aeropath camera.	EA	02700	Aero Service Corporation 210 East Courtland Street Philadelphia, PA 19104
680 Series; T.C. 2A4	SA164EA	Airborne profile recorder probe on nose of fuselage.	EA	02700	Aero Service Corporation 210 East Courtland Street Philadelphia, PA 19104
680 Series; T.C. 2A4	SA240CE	Unfeathering accumulator.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
680 Series; T.C. 2A4	SA290SW	RC-9 aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA391EA	Turbine bleed type pneumatic deicer system.	GL	38500	B.F. Goodrich Aerospace and Defense Products 500 South Main Street Akron, OH 44318
680 Series; T.C. 2A4	SA408SW	RC-8 aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA418SW	Seat-passenger lavatory combination.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA439SW	TC-8 aerial survey camera.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA439WE	Lycoming IGSO-480-A1D6 engines in lieu of original GSO-480-B1A6. Reissued 11/4/70.	WE	85135	Western Commander, Inc. 3011 Airport Avenue Santa Monca, CA 90405
680 Series; T.C. 2A4	SA455EA	Propeller deicing system.	NE	80385	United Aircraft Corporation Hamilton Standard Division Windsor Locks, CT 06096
680 Series; T.C. 2A4	SA473SW	AP-103E/FD108 automatic flight control system.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA478SW	RC-7, -9 aerial survey cameras.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109
680 Series; T.C. 2A4	SA520SW	Autopilot M-4C.	EA	16030	The Bendix Corporation Bendix Radio Division East Joppa Road Towson, MD 21204
680 Series; T.C. 2A4	SA523WE	Motorola L-2C autopilot with M-4 autopilot servo clutches and without approach coupler.	WE	70098	Santa Monica Aviation, Inc. 3011 Airport Avenue Santa Monica, CA 90405
680 Series; T.C. 2A4	SA577SW	Conversion of RC-8 camera to RMK-A-15/23.	SW	30530	Downtown Airpark, Inc. Box 94846 Oklahoma City, OK 73109

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
680 Series; T.C. 2A4	SA606SO	Installation of extended window L.H. and R.H. side of cabin. Amended 10/22/68.	SC	05580	Aircraft Modification Engineering Company P.O. Box 945 Vero Beach, FL 32960
680 Series; T.C. 2A4	SA633WE	Reroute powerplant and aileron control cables.	WE	70098	Santa Monica Aviation, Inc. 3011 Airport Avenue Santa Monica, CA 90405
680 Series; T.C. 2A4	SA662WE	Hi-Lo sensitivity adaptor BI-400 and autopilot with NAV-1 navigation coupler and heading lock. Reissued.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
680 Series; T.C. 2A4	SA665SW	deHavilland airborne profile recorder in aft fuselage.	EA	04515	Air Carrier Service Corp. 2233 Wisconsin Avenue, NW Washington, D.C. 20007
680 Series; T.C. 2A4	SA684SW	AP103F/FD-108 automatic flight control system.	CE	24250	Collins Radio Company 855 35th Street, N.E. Cedar Rapids, IA 52401
680 Series; T.C. 2A4	SA710SW	PT6A-20 engine.	SW	77110	Swearingen Aircraft P.O. Box 6904 San Antonio, TX 78209
680 Series; T.C. 2A4	SA1155WE	Camera.	NW	85123	Western Aerial Contractors, Inc. Route 1, Box 740 Eugene, OR 97401
680, 680E, 720; T.C. 2A4	SA660WE	Installation of HRD type fire extinguishing system. Amended 7/11/77.	WE	43190	HTL Industries, Inc. 373 South Fair Oaks Avenue Pasadena, CA 91105
680, 680-E, -F, -FL, -FL(P), T, V, W, 681, 685, 690, 720; T.C. 2A4	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Ic. 18145 Judy Street Castro Valley, CA 94546
680E; T.C. 2A4	SA450EA	Modification to lower surface of fuselage to accommodate Wild Camera Model RC5 or RC8. Amended 2/9/68.	EA	52060	Long Island Airways P.O. Box 828 Ronkonkoma, NY 11779
680E; T.C. 2A4	SA1782WE	Installation of drooped ailerons drooped wing leading edge, stall fence and rudder seal. Reissued 1/5/70.	NW	68500	Robertson Aircraft Corporation 15400 Sunset Highway Bellevue, WA 98004
680F; T.C. 2A4	SA278GL	Installation of Cleveland kit, No. 199-74. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
680F; T.C. 2A4	SA2691WE	Installation ofLycoming IO-720-BIB turbocharged engine. Reissued 7/22/74.	WE	69220	Mr. R P M Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680F; T.C. 2A4	SA3299SW-D	Mitchell automatic flight system AK772, consisting of Century III autopilot with optional radio and glide slope couplers. Issued 8/21/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F; T.C. 2A4	SA3300SW-D	Mitchell automatic flight system AK773, consisting of Century IV autopilot, consisting of Century IV flight director autopilot with optional remote annunciator. Issued 8/18/78.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Mineral Wells, TX 76067
680F, 680FL; T.C. 2A4	SA155CE	Intallation of Honeywell H-14 adaptive autopilot.	CE	48250	King Radio Corpratin 400 North Rogers Road Olathe, KS 66061
680FL; T.C. 2A4	SA2EU	Cargo door modification	EU	08440	ALAR-Empresa Iberica de Material Aeronautico Ld Lisbon, Portugal
680FL; T.C. 2A4	SA102GL	Installation of baggage compartment. Issued 12/29/75.	GL	31362	Eagle Aviation, Inc. Bishop Airport Flint, MI 48507
680FL; T.C. 2A4	SA929SW	Automatic flight system AK270 consisting of Century III autopilot with optional automatic pitch trim. radio and glide slope coupler.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
680FL; T.C. 2A4	SA1089SW	59-gallon wing auxiliary fuel tank.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
680FL; T.C. 2A4	SA1094SW	RC-8, RC-9, and RMK-A-15/23 camera.	SW	47770	Kerr Aviation Service, Inc. Box 399 Bethany, OK 73008
680FL; T.C. 2A4	SA1095SW	installation of Bendix ANA-12A.	SW	47770	Kerr Aviation Service,Inc. Box 399 Bethany, CK 73008
680FL; T.C. 2A4	SA1358SW	Dual or single camera installation and navigation sights. Issued 8/25/71.	SW	42825	A.D. Howard, Jr. 6817 Northwest 23rd Street Bethany, OK 73008
680FL; T.C. 2A4	SA2448SW	Extension of baggage area to F.S. 308, encompassing re-routing of powerplant and aileron control cables in baggage compartment area. Issued 4/7/77.	SW	25260	Harry B. Combs, Jr. P.O. Box 4580 Waco, TX 76101
680FL, FL(P); T.C. 2A4	SA806SW	Flap close-out strips.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
680FL, 680FL(P), 680(F); T.C. 2A4	SA2891WE	Installation of Lycoming IO-720-B1B turbocharged engine. Reissued 8/2/74.	WE	69220	Mr. RPM, Inc. Suite 321 7120 Hayvenhurst venue Van Nuys, CA 91406
680FL, 680FL(P); T.C. 2A4	SA2903SW	Installation of wing flap gap seals. Issued 1/25/79.	SW	69218	Mr. R.P.M., Inc. P.O. Box 40414 Everman Branch Fort Worth, TX 76140
680FL(P); T.C. 2A4	SA3322WE	Installation of cockpit overhead windows. Issued 1/18/77.	WE	69220	Mr. RPM, Inc. 7120 Hayvenhurst Avenue Van Nuys, CA 91406
680FL(P), T, V, W, 681; T.C. 2A4	SA1261SW	Camera installation. Issued 3/11/71.	SW	30530	Downtown Airpark, Inc. Box 94846 Bethany, CK 73109
680FL(P), 680T, V, W, 681, 690; T.C. 2A4	SA1584SW	Aerial survey camera. Issued 1/3/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK &#))*
680FL, 685; T.C. 2A4	SA1649SW	Camera installation. Issued 5/1/73.	SW	42825	A.D. Howard, Jr. 817 Northwest 43rd Street Bethany, CK 73008
680FL, 680FL(P), 680T, V, W, 681, 685A, 690, 690A; T.C. 2A4	SA1977SW	Modification of fuselage for installation of doppler antenna. Issued 5/6/75.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Oklahoma City, CK 73008
680T, V, W; T.C. 2A4	SA887SO	Installation of Teledyne P/N BB638/T- Series lead-acid replacement batteries. Amended 2/24/78.	WE	78050	Teledyne Battery Products P.O. Box 431 840 West Brockton Avenue Redlands, CA 92373
680T, 680V, 680W, 681; T.C. 2A4	SA895EA	Installation of Grimes three light strobe kit. Issued 1/20/72.	GL	39500	Grimes Manufacturing Company 515 North Russell Street Urbana, OH 43078
680T, V, W, 681; T.C. 2A4	SA1926SW	Fuel purge system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681; T.C. 2A4	SA1962SW	Generator over-voltage/over-current protection. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, V, W, 681, 690; T.C. 2A4	SA1705SW	Freon air conditioning system. Reissued 5/26/78.	SW	34000	Executive Aircraft Div. of Cooper Industries 7515 Lemmon Avenue Dallas, TX 75235
680T, 680W, 681, 685, 690; T.C. 2A4	SA1613CE	Stretcher installation. Issued 11/3/80.	CE	12777	Avcon Industries, Inc. 1006 West 53rd Street, North Wichita, KS 67204
680V, 680W, 681; T.C. 2A4	SA924NW	Hartzell HC-B3TN-5C/T-1078E-13Q propeller on TPE 331-43A and TPE 331-1-151K engines. Issued 4/16/80.	NW	62120	Pacific Propeller, Inc. Aero Air, Inc. P.O. Box 946 Kent, WA 98031
680V, W; T.C. 2A4	SA1529SW	Modification of hydraulic system and air conditioning pressurization system. Issued 7/25/73.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
680V, W; T.C. 2A4	SA1530SW	Modify existing 3000 psi hydraulic system to 1000 psi hydraulic system. Issued 12/23/72.	SW	42825	A.D. Howard, Jr. 6817 Northwest 43rd Street Bethany, OK 73008
680W; T.C. 2A4	SA3469WE	Installation of AiResearch TPE 331-6-252M engines. Amended 2/27/78.	WE	07502	AiResearch Manufacturing Co. of Arizona 402 South 36th Street P.O. Box 5217 Phoenix, AZ 85010
680, 720 Series; T.C. 2A4	SA37CE	C210403 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
680, 720 Series; T.C. 2A4	SA39CE	C210310 governor.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
681; T.C. 2A4	SA337GL-D	Installation of AiResearch TPE331-1-151-K engines. Amended 8/27/80.	GL	07499	AiResearch Aviation Company Capital Airport Springfield, IL 62705
681; T.C. 2A4	SA1005CE	Installation of IAD battery temperature monitor and over-temperature warning system. Issued March 1974.	CE	05250	Aircraft Instrument & Development, Inc. 317 East Lewis Wichita, KS 67202
685 Series; T.C. 2A4	SA17GL	Installation of Bendix FCS-810 autopilot. Issued 4/12/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
685 Series; T.C. 2A4	SA56GL	Install wheel assembly P/N 3-1174 and brake assembly P/N 2-993-1. Issued 7/23/74.	GL	38504	B.F. Goodrich Engineered Systems Company Division of B.F. Goodrich Co. P.O. Box 340 Troy, OH 45373
685; T.C. 2A4	SA155RM	Installation of Singer SKK-1000 doppler navigation system, SKQ-601 dead reckoning computer, and Sperry C-12 compass system. Issued 10/4/78.	RM	14127	Avionics Engineering of Denver 8895 Montview Boulevard Hangar B Denver, CO 80220
685 Series; T.C. 2A4	SA878SO	Installation of Silver Instruments Fueltron III, fuel flow gages. Issued 1/21/76.	SO	12493	Atlantic Aero, Inc. P.O. Box 8946 Grensboro, NC 27410
685; T.C. 2A4	SA3849WE	Installation of Fueltron IIIG or IIIP digital fuel flow and totalizer system. Issued 1/30/79.	WE	71740	Silver Instruments, Inc. 1896 National Avenue Hayward, CA 94545
690 Series; T.C. 2A4	SA26GL	Installation of Bendix M-4C autopilot. Issued 7/2/73.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O.Box 1060 Rockford, IL 61109
690 Series; T.C. 2A4	SA530SO	Installaton of manual electric trim system. Issued 2/28/73.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
690 Series; T.C. 2A4	SA2606WE	Installation of Lear AFC-70 autopilot. Amended 7/20/73.	WE	49850	LearAvia Corporation Avioncs Division 14505 Mt. Anderson Avenue Reno, NV 89510
690 Series; T.C. 2A6	SA2727WE	Installation of LearAvia electric pitch trim system. Issued 7/20/73.	WE	49850	LearAvia Corporation Avionics Division 14505 Mt. Anderson Avenue Reno, NV 89510
690, 690A; T.C. 2A4	SA74GL	Install wing tip recognition lights. Issued 3/21/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61109
690, 690A; T.C. 2A4	SA85SW	Installation of auxiliary bleed air shut-off and fuselage temperature monitoring system. Reissued 1/30/78.	SW	68768	Rockwell Aviation Service Division 3300 Love Field Drive Dallas, TX 75235
690, 690A; T.C. 2A4	SA250CE	Installation of Woodward electronic propeller synchrophaser system. Amended 7/12/76.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
690, 690A; T.C. 2A4	SA1059SO	Replace existing nickel-cadmium batteries with Teledyne Gill BB638/T series lead-acid batteries. Issued 3/29/79.	SO	78054	Teledyne Battery Products Suite 200 6520 Powers Ferry Road, NW Atlanta, GA 30339

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
690, 690A, 690B; T.C. 2A4	SA2577WE	Installation of flight FCS-105 flight control system. Amended 8/14/78.	CE	24250	Collins Radio Group Rockwell International 400 Collins Road, N.E. Cedar Rapids, IA 52406
690A; T.C. 2A4	SA79GL	Instal Bendix M4D autopilot system. Issued 4/18/75.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport P.O. Box 1060 Rockford, IL 61101
690A; T.C. 2A4	SA1009CE	Install Model KFC-300 automatic flight control system (autopilot and flight director). Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
690A; T.C. 2A4	SA1011CE	Install Model KVN-395 vertical navigation computer for operation with Model KFC-300 automatic flight control system. Issued May 1974.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
690A; T.C. 2A4	SA1873SW	Sperry SPZ-200/STARS IVC. Issued 5/1/74.	SW	30530	Downtown Airpark, Inc. P.O. Box 94846 Oklahoma City, OK 73109
690A; T.C. 2A4	SA1876SW	AP-106 autopilot and manual electric trim. Issued 4/29/74.	SW	24252	Collins Radio Company Addison Airport Addison, TX 75001
690A, 690B; T.C. 2A4	SA1024SO	Installation of AiResearch TPE331-5-252K engines in Model 690A replacing AiResearch TPE331-5-251K engines; installation of TPE331-5-252K engines in Model 690B. Amended 6/18/80.	SO	37087	The Garrett Corporation c/o AiResearch Aviation Company Bush Field Agusta, GA 30906
690C; T.C. 2A4	SA405GL	Installation of a Collins LRN 70 omega navigation system. Issued 5/13/80.	GL	33231	Electrosonics Division AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
695; T.C. 2A4	SA411GL	Installation of a Collins LRN 70 Omega navigation system. Issued 6/2/80.	GL	33231	Electrosonics Division AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
695; T.C. 2A4	SA418GL	Installation of a Collins LRN 70 Omega navigation system. Issued 6/20/80.	GL	33231	Electrosonics Division of AiRadio Corporation 4885 Sawyer Road Columbus, OH 43219
720; T.C. 2A4	SA1-553	Lightweight reservoir type pneumatic deicing system.	GL	38500	B.F. Goodrich Aerospace ad Defense Products 500 South Main Street Akron, OH 45373
720; T.C. 2A4	SA395SW	Four-place seating capacity.	SW	18000	Brown Aero Corporation P.O. Box 8 Addison, TX 75001
111, 112; T.C. A11SO, A12SO	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
111, 112; T.C. A11SO, A12SO	SA1502SW	Mitchell automatic flight system AK364 consisting of Century I autopilot with optional omni tracker. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1503SW	Mitchell automatic flight system AK 363 consisting of Century IIB autopilot with optional radio coupler. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1504SW	Mitchell automatic flight system AK362 consisting of Century III with optional command/electric pitch trim, radio, and glide slope couplers.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1505SW	Mitchell command/electric pitch trim. Issued 8/30/72.	SW	60000	Mitchell Industries, Inc. P.O Box 610 Municipal Airport Mineral Wells, TX 76067
111, 112; T.C. A11SO, A12SO	SA1728SW	Cabin air scoop. Issued 9/13/73.	SW	59500	J.W. Miller Aviation, Inc. P.O. Box 16203 San Antonio, TX 78246

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
112; T.C. A12SO	SA243NW	Installation of Lycoming IO-540 engine with 3-bladed Hoffman, 3-bladed Hartzell, or 2-bladed Hartzell propeller. Amended 5/26/78.	NW	52625	Machen, Inc. S. 3408 Davison Boulevard Spokane, WA 99204
112; T.C. A11SO, A12SO	SA2900WE	Installation of Pathfinder autopilots. Amended 11/13/74.	WE	12380	Astronautics Corp. of America 2416 Asler Street Torrance, CA 90505
112; T.C. A12SO	SA3155WE	Installation of Pathfinder autopilot systems and/or pitch trim systems. Issued 4/26/76.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torranc, CA 90505
112, 112B, 112TC, 112TCA, 114, 114A; T.C. A12SO	SA237GL	Install leading edge landing lights. Amended 1/24/80.	GL	37182	General Aviation, Inc. Lost Nation Airport Willoughby, OH 44094
112, 112B, 112TC, 112TCA, 114; T.C. A12SO	SA1229CE	Install King Model KFC-200 2-axis (3 optional) flight control system with KCS 55/55A compass and a KI-255 (or -256) flight command indicator or a KG-258 attitude horizon gyro with a KC-292 mode controller; or stand alone electric trim. Amended 1/18/78.	CE	48250	King Radio Corporation 400 North Rogers Road Olathe, KS 66061
112, 114; T.C. A12SO	SA3120SW-D	Automatic flight system AK572 consisting of Century I autopilot with optional omni tracker. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A12SO	SA3121SW-D	Automatic flight system AK573 consisting of Century IIB autopilot with optional radio coupler. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A12SO	SA3122SW-D	Automatic flight system AK574 consisting of Century III autopilot with optional radio and glide slope Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112, 114; T.C. A1SO	SA3123SW-D	Mitchel command electric trim AK582. Issued 3/19/76.	SW	60000	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
112B, 112TC, 112TCA, 114; T.C. A12SO	SA3778WE	Installation of retractable landing lights. Issued 11/8/78.	WE	47070	Fred W. Jones 2901 East Spring Street Long Beach, CA 90806
112TC, 112TCA; T.C. A12SO	SA3787WE	Installation of SDI Model CFS-1000, -1001, or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92705
112TC, 112TCA; T.C. A12SO	SA3920WE	Installation of fueltron IG or IP digital fuel flow and totalizer system. Amended 1/9/80.	WE	71740	Silver Instruments, Inc. 2346 Stanwell Drive Concord, CA 94520
114; T.C. A12SO	SA300CE	Installation of propeller governors on single and twin engine aircraft P/N J210345. Issued 5/7/80.	GL	87250	Woodward Governor Company 5001 North Second Street Rockford, IL 61101
114; T.C. A12SO	SA3727WE	Installation of SDI Model CFS-1000, -1001 or FT-100 fuel flow indicating system. Amended 3/9/79.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714
114; T.C. A12SO	SA3308WE	Modification of aileron control system by addition of aileron centering spring and installation of Pathfinder autopilot system and/or pitch trim systems. Issued 1/7/77.	WE	12380	Astronautics Corp. of America 2416 Amsler Street Torrance, CA 90505
114; T.C. A12SO	SA3727WE	Installation of SDI Model CFS-1000 fuel flow indicator. Issued 9/6/78.	WE	77250	Symbolic Displays, Inc. 1762 McGaw Avenue Irvine, CA 92714

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
S-64E; T.C. H6EA	SA3894WE	Installation of hoist pump (yoke type), P/N ACH60552L6. Issued 4/2/79.	WE	01770	Aero-Craft Hydraulics, Inc. 2428 West Carson Street Torrance, CA 90501
S-64E; T.C. H6EA	SA3895WE	Installation of auxiliary power unit (APU) starter motor, P/N ACH-3911-205SPCL. Issued 4/2/79.	WE	01770	Aero-Craft Hydraulics, Inc. 2428 West Carson Street Torrance, CA 90501
S-76A; T.C. H1NE	SH270WE	Installation of a Collins LRN-80 VLF/Omega navigation system as a means of navigation for enroute navigation within the 48 contiguous U.S. and D.C. Issued 4/4/80.	WE	24205	Collins General Aviation Division 3000 Airway Avenue Costa Mesa, AZ 92626
S-76A; T.C. H1NE	SH286GL	Install Norton Co. radome P/N AD-4082X-2 (Sikorsky P/N 76600-02110-101) or Norton radome P/N AD-4082X-10 (Sikorsky P/N 76600-02110-102). Amended 12/20/79.	GL	61750	Norton Company Plastics & Synthetics Division P.O. Box 350 Akron, OH 44309
S-76A; T.C. H1NE	SH399GL	Installation of Astronautics helicopter 3Q flight director system. Issued 3/20/80.	GL	12375	Astronautics Corp. of America P.O. Box 523 Milwaukee, WI 53201
S-76A; T.C. H1NE	SH435GL	Installation of Astronautics helicopter 2Q flight director system. Issued 8/23/80.	GL	12375	Astronautics Corp. of America 907 South First Street Milwaukee, WI 53201
S-76A; T.C. H1NE	SH4180SW	Sperry automatic flight control system for single pilot IFR certification. Issued 10/20/80.	SW	41780	Heliflight Systems, Inc. P.O. Box 128 Conroe, TX 77301
S-76A; T.C. H1NE	SH4184SW	SAFT Model 4076 battery. Issued 8/26/80.	SW	41780	Heliflights Systems, Inc. P.O. Box 128 Conroe, TX 77301

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

SOCIETE NATIONALE INDUSTRIELLE AEROSPATIALE (S.N.I.A.S)

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SE 3130 Alouette II; T.C. 7H1	SH1-175	American type rate of climb, altimeter, air speed and outside air temperature indicators.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-253	Goodyear floats and United States hardware.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-315	Modification of rotor swash plate.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-461	Engine air inlet duct screens.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-475	Purolator fuel filter element type EP-173 P/N 6656561 and gasket 6656574.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-504	Cabin heating system utilizing Stewart-Warner 940F24 heater.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-527	Transmission gears in transmission box assembly SE 3130 62-30-00; 81P740009 first stage sun gear, one; 81P740006 second stage sun gear, one; 81P740007 satellite gear, twelve.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-563	Tail light modification.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-592	American manufactured instrument panel and cabin dome lighting.	EA	67170	Republic Aviaiton Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-614	Anti-collision rotating beacon light.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-616	Marginal weather instrument group consisting of directional gyro, gyro horizon and turn-slip indicators.	EA	67170	Republic Aviation Corp. Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-617	Grimes eyebrow instrument lights.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-618	Shoulder harness for pilot and copilot.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH1-623	American type folding 3-man troop seat.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE 3130 Alouette II; T.C. 7H1	SH159EA	Raybestos-Manhatten Ray-Bond (R) R8001 adhesive as an alternate bond for bonding of Alouette.	EA	67170	Republic Aviation Corporation Helicopter Division Farmingdale, L.I., NY 11735
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. 7H1	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. 7H1	SH1870SW	Install 315A-22-11-200 protection assembly for tail drive shaft. Issued 4/17/74.	SW	84300	Vought Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. 7H1	SH1913SW	External cargo carrier. Reissued 8/31/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Irving, TX 75050
SE3130, SE313B, SA3180, SA318B, SA318C; T.C. H4EU, 7H1	SH4266SW	Alternate parts for installation of modification AM2195. Issued 2/13/81.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
SE.313 Series, SA318C; T.C. 7H1	SH437NW	Incorporation of a weighing system for external load operations. Amended 6/10/77.	NW	56890	Measurement Systems Inter'l 619 Riverside Drive Seattle, WA 98108

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA-318C; T.C. 7H1	SH130WE	Installation of Nightsun SX-16C searchlight. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
SA-318C; T.C. 7H1	SH406AL	Installation of L2700 SA 318 skis. Reivsed 2/2/71.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
SA318C; T.C. 7H1	SH440AL	Installation of cargo baskets. Issued 7/16/71.	AL	08500	Alaskan Sky-Craft Company P.O. Box 6206 Anchorage, AK 99502
SA-318C; T.C. 7H1	SH475AL	Installation of ASC-3 maintenance platform, -4 maintenance platform step, and -5 personnel step. Issued 4/3/72.	AL	08500	Alaskan Sky-Craft Company P.O. Box 6206 Anchorage, AK 99502
SA-318C; T.C. 7H1	SH540NW	Install onboard weighing system. Issued 1/9/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
SA-318C; T.C. 7H1	SH694NW	Installation of Model 2512 weighing system. Issued 12/14/78.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SA-318C; T.C. 7H1	SA1249SW	Eastern rotorcraft cargo hook 2A15E. Reissued 10/7/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-318C; T.C. 7H1	SH1253SW	S.E.B. 505 starter-generator to replace Labinal starter-generator. Reissued 9/30/77.	SW	84300	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-318C; T.C. 7H1	SH1277SW	Eastern Rotorcraft cargo hook and "H" frame 17080-1. Issued 3/17/71.	SW	84300	Vought Helicopter, Inc. 1701 West Marshall Drive Grand Prairie, TX 75050
SA-318C; T.C. 7H1	SH1384SW	Replace existing landing light and anti-collision light. Reissued 9/30/77.	SW	84300	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-318C; T.C. 7H1	SH1792SW	Foxtronics/Tramm BTI 600 nickel cadmium battery temperature system. Issued 1/29/74.	SW	36600	Foxtronics P.O. Box 7031 Dallas, TX 75209
SA330F, G, J; T.C. H4EU	SH2963SW	Seat belt assembly. Issued 3/23/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA330G; T.C. H4EU	SH1983SW	Utility interior arrangement. Reissued 11/8/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA330G; T.C. H4EU	SH1985SW	Supplementary strobe lights and replacement of existing power position lights on sponson. Reissued 11/8/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA330G; T.C. H4EU	SA1986SW	Fixed position retractable landing lights. Reissued 11/8/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH529AL	Installation of L2700 SA341HS skis. Amended 11/26/74.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
SA. 341G; T.C. H6EU	SH734NW	Installation of an Onboard Weighing System. Issued 3/21/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
SA.341G; T.C. H6EU	SH1621SW	Eastern Rotorcraft cargo hook. Reissued 6/30/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1654SW	Environmental control unit. Reissued 1/22/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1770SW	Modified cockpit instrument panel. Reissued 6/30/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1858SW	Tail rotor drive shaft cover. Issued 3/20/74.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA.341G; T.C. H6EU	SH1894SW	Grimes Manufacturing Co. landing light Model G-3600 A-3. Issued 7/22/74.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA.341G; T.C. H6EU	SA1903SW	Single/dual stowable litter kit. Reissued 6/7/77.	SW	03010	Aerospatiale Helicopter Corp. 1707 W. Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1956SW	Install 341-78-3D-036 hour meter kit. Reissued 3/5/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH1991SW	Installation of instruments. Issued 5/26/75.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2264SW	Alternate main gear box shaft input seal. Issued 10/17/75.	SW	84300	Vought Helicopter Corporation 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2272SW	Strobe lights. Issued 11/18/75.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2278SW	Installation of coffee bar. Issued 12/11/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA.341G; T.C. H6EU	SH2291SW	Motorola stereo Model TD204S. Issued 2/12/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2292SW	Flitephone III system. Issued 2/12/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G;	SH2306SW	Relocation of emergency float inflation bottles and quick removal provisions for emergency floats. Issued 4/28/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2347SW	Install Nightsun searchlight. Issued 8/12/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2371SW	Installation of main rotor head. Issued 10/21/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2379SW	Extend cabin section 200mm just forward of rear bulkhead. Issued 11/9/76.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2400SW	Installation of ATC SH1975 configurations -5, -6, IFR Category II certification. Issued 2/2/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA.341G; T.C. H6EU	SH2453SW	Installation of cabin floor extension. Issued 4/22/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75050
SA341G; T.C. H6EU	SH2472SW	Installation of exterior markings. Amended 4/24/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA341G; T.C. H6EU	SH2497SW	Structural provisions and installation of aft ballast. Issue 8/24/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA341G; T.C. H6EU	SH2664SW	Install right hand maintenance step. Issued 10/12/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-341G; T.C. H6EU	SH2931SW	Toe weights in skid gear. Issued 3/12/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
262A Series; T.C. A6EU	SA2367SW	Install complete interior including lavatory, galley and seating. Reissued 1/12/77.	SW	36700	Frakes AViation, Inc. Route 3, Box 229-B Cleburne, TX 76031
262A Series; T.C. A6EU	SA2369SW	Install P&W ACL PT6A-45A engine. Issued 10/19/76.	SW	36700	Frakes Aviation, Inc. Route 3, Box 229-B Cleburne, TX 76031
Nord 262A; T.C. A6EU	SA3596WE	Replace existing one-piece entry door with a two-piece door with integral steps in the lower half. Issued 3/15/78.	WE	10210	American Jet Industries, Inc. 7701 Woodley Avenue Van Nuys, CA 91406
262A-12; T.C. A6EU	SA370CE	MP-5 autostereo magnetic tape player unit.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
262A-12; T.C. A6EU	SA388CE	U.S. manufactured aircraft control cable substituted to AN standards.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
262A-12; T.C. A6EU	SA482CE	Installation of cockpit voice recorder.	GL	49300	Lake Central Airlines, Inc. Weir Cook Airport Indianapolis, IN 46241
262A-12; T.C. A6EU	SA987EA	Installation of forward facing modified double seat on right hand side of aircraft cabin at Station 503 including incorporation of associated seat supporting structure. Reissued 8/4/74.	EA	66390	Ransome Airlines North Philadelphia Airport Grant Avenue & Ashton Road Philadelphia, PA 19114
262A-12; T.C. A6EU	SA1351WE	Ceconite 101 material covering of aircraft surfaces. Amended 3/21/72.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Nord) 262 A-12; T.C. A6EU	SA2666WE	Ceconite 102 material covering of upper rudder. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
"Corvette" SN601; T.C. A37EU	SA2230SW	Interior and associated modifications. Reissued 6/22/76.	EU	73645	Societe Nationale Indus. Aerospatiale 37 Blvd. de Montrorency Paris 16, France
SA-360C; T.C. H8EU	SH2319SW	Seat modification. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2320SW	Installation of bar. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2321SW	Install folding table. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2322SW	Installation of coat closet. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2323SW	Installation of trash container. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. H8EU	SH2324SW	Inner-window assembly. Issued 6/4/76.	SW	84600	Ward Int'l Aircraft Service Location 2 West, Meacham Field Fort Worth, TX 76106
SA-360C; T.C. A8EU	SH2402SW	Emergency lighting system. Issued 2/3/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA360C; T.C. H8EU	SH2441SW	Soundproofing. Issued 3/29/77.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C; T.C. H8EU	SH2445SW	Installation of exterior markings. Amended 4/24/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C; T.C. H8EU	SH2708SW	Alternate anti-collision/strobe lights. Issued 1/23/78.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
SA-360C; T.C. H8EU	SH4019SW	Installation of RCA Primus 50 radar. Issued 7/18/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350, D, D-1; T.C. H9EU	SH2825SW	Air Cruisers Model D24724 emergency flotation gear. Issued 8/25/78.	SW	03010	Aerospatiale Helicopter 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2934SW	Supplemental strobe lights. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2935SW	Standard interior. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2936SW	Reversible dual bunch seat. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2937SW	Dual non-stowable litter kit. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
AS-350B; T.C. H9EU	SH2938SW	Electric gyro instruments. Issued 3/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2972SW	Net assemblies in side baggage compartment. Issued 4/11/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH2973SW	Minimum required external markings. Issued 4/11/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4016SW	Installation of hourmeter. Issued 7/13/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 76067
AS-350B; T.C. H9EU	SH4032SW	Air Cruisers Model D24724 emergency flotation gear. Issued 8/20/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4044SW	Patient supplemental oxygen supply. Issued 1/18/80.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4048SW	Installation of a storage pouch. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350B; T.C. H9EU	SH4138SW	TEDECO chip detector. Issued 6/13/80.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350B, AS-350C; T.C. H9EU	SH4258SW	Two inch diameter turn and slip indicator. Issued 1/6/81.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350B, AS-350C, AS-350D, AS-350D1; T.C. H9EU	SH183RM	Installation of electric driven air-conditioner system. Reissued 2/4/81.	RM	62500	Parker Hannifin Corporation Airborne Division P.O. Box 800 Longmont, CO 80501
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH189RM	Installation of belt driven air-conditioner system. Amended 1/10/80.	RM	01950	Aero Engineering Corporation 2678 Delta Drive Colorado Springs, CO 80910
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH1543CE	Installation of Collins APS-841H helicopter automatic flight control systems. Amended 2/4/81.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH2875SW	Electric turn and slip indicator. Issued 4/23/80.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH4086SW	Cabin ventilation system. Issued 2/27/80.	SW	03010	Aerospataile Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350B, -350C, -350D, -350D1; T.C. H9EU	SH4119SW	Installation of dual litters P/N 350A-82-1000-01. Issued 5/5/80.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH748NW	Installation of a weighing system. Issued 4/12/79.	NW	52685	McAllister Engineering Enterprises 9739 South 208th Street Kent, WA 98031
AS-350C; T.C. H9EU	SH2814SW	Chip detectors. Issued 7/14/78.	SW	03010	Aerospatiale Helicopters, Inc. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH2817SW	Install net assemblies in side baggage compartments. Issued 7/18/78.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C; T.C. H9EU	SH2819SW	Minimum required external markings. Issued 7/19/78.	SW	03010	Aerospatiale Helicopters, Inc. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-305C, D, D-1; T.C. H9EU	SH740NW	Installation of a weighing system. Issued 4/6/79.	NW	56890	Measurement Systems International 580 South Lucille Street Seattle, WA 98108
AS-350C, D, D-1; T.C. H9EU	SH771NW	Installation of a weighing system. Issued 5/15/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
AS-350C, D, D-1; T.C. H9EU	SH2866SW	Installation of hourmeter. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
AS-350C, D, D-1; T.C. H9EU	SH2886SW	Installation of supplemental strobe lights. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2895SW	Installation of standard interior. Amended 3/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2913SW	Installation of reversible dual bench seat. Issued 2/21/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9Eu	SH2914SW	Installation of dual non-stowable litter kit. Issued 2/21/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D1; T.C. H9EU	SH2915SW	Modify damping capacity accumulator, P/N 350A54.1006.00. Issued 2/22/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2917SW	Install electric gyro instruments. Issued 2/27/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH2929SW	Install TEDECO fuel flow chip detector. Issued 3/9/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4043SW	Patient supplemental oxygen supply. Issued 1/18/80.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4049SW	Installation of a storage pouch. Issued 10/5/79.	SW	03010	Aerospatiale Helicopter Corp. 1701 West Marshall Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4229SW	Optional powerplant rotor monitoring system. Issued 11/12/80.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350C, D, D-1; T.C. H9EU	SH4214SW	Installation of low engine oil indicator system. Issued 10/10/80.	SW	03010	Aerospatiale Helicopter Corp. 2701 Forum Drive Grand Prairie, TX 75051
AS-350D; T.C. H9EU	SH1543CE	Installation of Collins APS-841H helicopter automatic flight control systems. Amended 4/22/80.	CE	24250	Collins Avionic Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
AS-350D; T.C. H9EU	SH4228SW	Modification of electrical systems, install avionics and automatic flight control system for single pilot IFR. Issued 12/8/80.	SW	74570	Sperry Flight Systems Suite 313 1825 West Mockingbird Lane Dallas, TX 75235

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

STOL AMPHIBIAN CORP.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
RC-3; T.C. 769	SA1-18	Increasing the wing span 16 inches and incorporating wing tip spill plates.	NE	67725	Ned C. Rice 470 Silver Lane East Hartford, CT 06108
RC-3; T.C. 769	SA1-26	Six-volt battery in bow compartment.	EA	55740	The Glenn L. Martin Company Baltimore, MD 21233
RC-3; T.C. 769	SA3-28	J.F. Hamilton modified wing tips.	GL	47715	Archie Keith Route 3 Ottawa, IL 61350
RC-3; T.C. 769	SA3-30	Modified spray rail with four foot addition to wing span.	GL	59468	Miller Flying Service North Benton, OH 44449
RC-3; T.C. 769	SA3-88	Hartzell propeller HC-13X20-54 installation. Amended 1/7/75.	GL	14210	John E. Ayer 405 South Third Street Le Sueur, MN 56058
RC-3; T.C. 769	SA3-365	Republic RC-3 starter system.	GL	70925	Sentas Skyways Service City Airport Detroit, MI 48233
RC-3; T.C. 769	SA3-380	Fuel filler door assembly installation. Amended 1/7/75.	GL	14210	John E. Ayer 405 South Third Street Le Sueur, MN 56058
RC-3; T.C. 769	SA17CE	Extension of each wing tip 24-inches.	NW	47740	Kenmore Air Harbor, Inc. P.O. Box 64 Kenmore, WA 98028
RC-3; T.C. 769	SA215SO	Extended wing tips.	SO	39700	Gulf Airways, Inc. P.O. Box 1126 Fort Myers, FL 33902
RC-3; T.C. 769	SA282NW	Installation of Lycoming GO-480-B1D engine and Hartzell HC83X20-2CL propeller. Issued 4/13/76.	NW	74941	S.T.C. Bee 10900 Rainier Avenue, South Seattle, WA 98178
RC-3; T.C. 769	SA308EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
RC-3; T.C. A-769	SA374NW	Installation of S.T.C. Bee, Inc. Model 1-TP-1 model instrument panel kit. Issued 11/1/76.	NW	74942	S.T.C. Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA392NW	Installation of flush fuel fill. Issued 12/28/76.	NW	74942	S.T.C. Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA393NW	Rework of main step gusset. Issued 12/28/76.	NW	74942	S.T.C. Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA394NW	Installation of Model 2-DT droop wing tips. Issued 12/28/76.	NW	74942	S.T.C Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA195NW	Reshape rear cabin windows. Issued 12/28/76.	NW	79942	S.T.C. Bee, Inc. 10900 Raineer Avenue, South Seattle, WA 98178
RC-3; T.C. A-769	SA409EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
RC-3; T.C. A-769	SA575NW	Installation of longitudinal step kit. Issued 3/16/78.	NW	74942	S.T.C. Bee, Inc. 10900 Rainier Avenue Seattle, WA 98178
RC-3; T.C. A-769	SA576NW	Install disc brake system. Issued 3/14/78.	NW	74942	S.T.C. Bee, Inc. 10900 Rainier Avenue S. Seattle, WA 98178
RC-3; T.C. A-769	SA613NW	Install 28-volt electrical system. Issued 6/1/78.	NW	74942	S.T.C. Bee, Inc. 10900 Rainier Avenue S. Seattle, WA 98178
RC-3; T.C. A-769	SA615NW	Installation of Lycoming GO-435-C2B, GSO-IGSO-480, and GO-IGO-480 series engine with Hartzell HC-A2V20 and HC-A3VF series propellers with other miscellaneous models. Issued 12/28/77.	NW	71790	Simuflight, Seattle 6727 Perimeter Road, S. Seattle, WA 98108
RC-3; T.C. A-769	SA815NW	Installation of Cleveland disc type brakes. Issued 7/25/79.	NW	71790	Simuflight, Seattle 6727 Perimeter Road South Seattle, WA 98108
RC-3; T.C. A-769	SA821EA	Installation of Stol Aircraft Corporation fuel cell. Issued 5/19/70.	NE	75745	Stol Aircraft Corporation P.O. Box 175, Norwood Airport Norwood, MA 02062
RC-3; T.C. A-769	SA853EA	Installation of Stol Aircraft Corporation electric hydraulic pump system. Issued 11/19/70.	NE	75745	Stol Aircraft Corporation P.O. Box 175, Norwood Airport Norwood, MA 02062
RC-3; T.C. A-769	SA915NW	Installation of a South Wind Model 940 combustion heater.	NW	71790	Simuflight, Seattle 6727 Perimeter Road, South
RC-3; T.C. A-769	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
RC-3; T.C. A-769	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
RC-3; T.C. A-769	SA2386WE	Installation of Daubenspeck Model "D-1" fiberglass droop wing tips. Issued 7/28/71.	HW	28795	John A. Daubenspeck 11913 - 140th Place, N.E. Kirkland, WA 98033

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
AIRCRAFT
SWEARINGEN AVIATION CORP.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA26T; T.C. A5SW	SA418SO	Installation of low oil pressure warning lights. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C. A5SW	SA461SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation, each engine is limited to a maximum of 550 SHP. Reissued 11/21/73.	SW	29240	Delta Aviation, Inc. 404 Cities Service Building Tulsa, OK 74119
SA26T; T.C. A5SW	SA571SO	Installation of Pratt & Whitney PT6A-28 engines. For this installation each engine is limited to a maximum of 550 SHP. Issued 12/14/73.	SO	57770	Memphis Turbines, Inc. AMF Box 30255 Memphis International Airport Memphis, TN 38130
SA26T; T.C. A5SW	SA600WE	Install Hoskins Twilighter Mk IIIq supplemental lighting system with Model P wing tip and Model K tail light.	GL	42625	Hoskins, Inc. 34 North Bennett Geneva, II 60134
SA26T; T.C. A5SW	SA764SW	Bendix M4C autopilot flight control system.	SO	15475	The Bendix Corporation P.O. Box 23430 Fort Lauderdale, FI 33309
SA26T; T.C. A5SW	SA1464WE	Installation of supporting structure and placards only for avionic components in the aft compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26T; T.C. A5SW	SA1465WE	Installation of supporting structure and placards only for avionic components in forward compartment. Amended 10/1/68.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA26-T, SA26-AT, (Merlin II): T.C. A5SW	SA600CE	Install Hoskins Twilighter Mk III supplemental lighting system with Model P wing tip and Model K tail light. Reissued 4/10/70.	WE	77250	Symbolic Displays, Inc. 1188 North Batavia Orange, CA 92667
SA26-T, SA26-AT, (Merlin II); T.C. A5SW	SA3057WE	Installation of fuel tank boost pump. Issued 7/17/75.	WE	26725	Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA26-T, SA26-AT, Merlin II; T.C. A5SW	SA3465WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA26-T, 26-AT, 226-T, 226-AT; T.C. A5SW	SA2569WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
SA26-T, -AT, SA226-T, -AT, -T(B), SA226-TC; T.C. A5SW, A8SW	SA1021NW	Modification to the gear position indicator to allow the bulbs to be changed in the aircraft and to add a dimming device. Issued 9/17/80.	NW	10180	American Avionics, Inc. 7001 Perimeter Road, South Seattle, WA 98108
SA226T; T.C. A5SW	SA1078SO	Installation of Bendix FCS-8700 automatic flight control system. Issued 6/5/79.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FI 33310
SA226-T, SA226-AT; T.C. A5SW	SA254GL	Installation of emergency/continuous water-alcohol injection system. Amended 10/3/78.	GL	07503	AiResearch Aviation Company Capital Airport Springfield, II 62705
SA226-T, SA226-AT; T.C. A5SW	SA273GL	Installation of a Scenic exhaust assembly, P/N YR-12013 in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-T, SA226-AT; T.C. A5SW	SA613AL	Install nose wheel steering lock system. Issued 6/3/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA226-T, SA226-AT; T.C. A5SW	SA2909WE	Installation of fuel tank boost pump. Amended 8/12/75.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA226-T, SA226-AT; T.C. A5SW	SA3481WE	Installation of recognition light on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA226-T, SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA961NW	Landing/recognition forward facing white lights and clear plastic wing tip covers. Reissued 1/9/81.	NW	68265	R.M.D. Aircraft Lighting, Inc. 3648 S.E. Roancke Court Hillsboro, OR 97123
SA226-TC; T.C. A8SW	SA279GL	Installation of emergency/continuous water-alcohol injection system. Issued 11/1/78.	GL	07503	AiReserach Aviation Company Capital Airport Springfield, II 62705
SA226-TC; T.C. A8SW	SA189GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA615AL	Install nose wheel steering lock system. Issued 6/21/77.	AL	45790	Jet Accessories, Inc. 3600 Int'l Airport Road Anchorage, AK 99502
SA226-TC; T.C. A8SW	SA1068CE	Installation of Collins Radio Co. AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-TC; T.C. A8SW	SA1582CE	Installation of Collins FCS-150 automatic flight control system. Issued 4/2/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
SA226-TC; T.C. A8SW	SA2910WE	Installation of fuel tank boost pump. Issued 7/23/74.	WE	26725	The Crane Company Hydro-Aire Division 3000 Winona Avenue Burbank, CA 91504
SA226-TC; T.C. A8SW	SA3482WE	Installation of recognition light assembly on the horizontal stabilizer. Reissued 2/28/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
SA226T (S/N T-201 and up), SA226AT (S/N AT-001 and up); T.C. A5SW	SA972CE	Installation of AID battery temperature sensing and over temperature warning system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT; T.C. A5SW	SA188GL	Installation of radome kit 4159X. Issued 9/9/77.	GL	61750	Norton Company P. O. Box 350 Akron, OH 44309
SA226-TC; T.C. A8SW	SA274GL	Installation of a Scenic exhaust assembly, P/N YR-12013, in lieu of Swearingen exhaust assembly, P/N 27-62061-15, using original installation hardware and components. No installation data are required. Issued 10/3/78.	GL	70294	Scenic Aviation Services, Inc. c/o Smith-Morris Corporation 2615 Wolcott Ferndale, MI 48220
SA226-AT; T.C. A5SW	SA1051CE	Installation of Collins Radio Co. AP-106 autopilot system. Issued November 1974.	CE	24250	Collins Radio Company 5225 "C" Avenue, N.E. Cedar Rapids, IA 52406
SA226-AT; T.C. A5SW	SA1575SW	Battery isolation system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1576SW	Ray Electronics Model 7107 battery fault warning system. Issued 12/28/72.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1577SW	Collins FCS-105 automatic/flight director system with Sperry dual flight director system. Issued 1/26/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA1673SW	Battery isolation system. Issued 6/11/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-AT; T.C. A5SW	SA2344WE	Installation of Collins Radio Co. Model FCS-10583 autopilot flight flight director systems. Reissued 8/20/71.	CE	24250	Collins Radio Company 855 - 35th Street, N.E. Cedar Rapids, IA 52406

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
SA226-AT; T.C. A5SW	SA2860WE	Installation of AiResearch TPE 331-30-307G engines and propeller synchrophasing. Issued 3/21/74.	WE	07502	AiResearch Manufacturing Company of Arizona 402 South 36th Street Phoenix, AZ 85034
SA226-AT; T.C. A5SW	SA3075WE	Installation of Garrett AirNav 100 area navigation system. Issued 10/16/75.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T(B); T.C. A5SW	SA338GL-D	Installation of continuous water alcohol injection system. Amended 8/4/80.	GL	07499	AiResearch Aviation Company Capital Airport Springfield, II 62705
SA226-T(B); T.C. A5SW	SA1166EA	Installation of Litton LTN211 Omega navigation system. Amended 4/15/80.	EA	78412	Teterboro Aircraft Service, Inc. 401 Industrial Avenue Teterboro, NJ 07608
SA226-T(B); T.C. A5SW	SA1167EA	Installation of Collins ADS-80 air data system. Amended 4/15/80.	EA	78412	Teterboro Aircraft Service, Inc. 401 Industrial Avenue Teterboro, NJ 07608
SA226-T; T.C. A5SW	SA1238SW	Bendix M-4C automatic flight control system. Issued 12/22/70.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FI 33310
SA226-T; T.C. A5SW	SA1241SW	Installation of supporting structure, avionics components and systems. Issued 1/6/71.	WE	07500	AiResearch Aviaiton Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1271SW	Collins AP105 automatic flight control system. Issued 3/16/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1600SW	Battery isolation system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1601SW	Ray Electronics Model 7107 battery fault warning system. Issued 1/31/73.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA1602SW	Collins AP105 automatic flight control system with dual Sperry Stars flight directors. Issued 2/6/73.	WE	07500	AiResearch Aviation Company 6201 WEst Imperial Highway Los Angeles, CA 90045
SA226-T; T.C. A5SW	SA2864WE	Modification to install electrical and structural provisions for Texas Instrument, Inc. infra-red scanner system. Issued 4/25/74.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226-T, SA226-T(B); T.C. A5SW	SA804SO	Installation of Bendix M-4D automatic flight control system, including integration into the existing Swearingen pitch trim and yaw damping systems. Amended 12/14/78.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FI 33310
SA226T, SA226AT; T.C. A5SW	SA2428WE	Installation of Hoskins/SDI Twilighter MK III supplemental lighting system. Issued 10/50/71.	WE	07500	AiResearch Aviation Company 6201 West Imperial Highway Los Angeles, CA 90045
SA226TC (S/N TC-201 and up); T.C. A8SW	SA973CE	Installation of AID battery temperature sensing and over-temperature sensing system. Issued December 1973.	CE	05250	Aircraft Instrument and Development, Inc. 317 East Lewis Street Wichita, KS 67202
SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA821SO	Installation of Bendix M-4D automatic flight control system including optional flight director system and integration into existing Swearingen pitch trim system. Issued 1/29/75.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FL 33310
SA226-AT, SA226-TC; T.C. A5SW, A8SW	SA1247SW	Bendix M-4C autopilot. Reissued 8/2/74.	SO	15475	Bendix Avionics Division P.O. Box 9414 Fort Lauderdale, FI 33310

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

UNIVAIR AIRCRAFT CORP.

Revised 3/31/81

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
108 Series; T.C. 767	SA1-10	Replacement of wing fabric with 24 ST. alclad skin.	EA	05972	Aircraftsmen, Inc. Zahns Airport Lindenhurst, L.I., NY 11757
108 Series; T.C. 767	SA1-48	Edo 249-2870 floats.	EA	16857	James R. Blakely P.O. Box 53 Westchester Station Bronx, NY 10461
108 Series; T.C. 767	SA1-374	Installation of Fram lube oil filter Model PB55-1. Amended 9/11/67.	NE	36728	Fram Aerospace Division of Fram Corporation 750 School Street Pawtucket, RI 02860
108 Series; T.C. 767	SA1-258	Conversion of aileron covering from fabric to alclad panels.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047
108 Series; T.C. 767	SA3-27	Covering of wings .020-inch 24 ST. alclad.	GL	42860	Howard Aviation, Inc. P.O. Box 1287 Peoria, IL 61601
108 Series; T.C. 767	SA3-398	Fiberglass plastic covering of all fabric surfaces.	GL	34291	John H. Fallon 601 Woodward Heights Boulevard Ferndale, MI 48220
108 Series; T.C. 767	SA3-423	Model CT-3000 tail ski on airplanes equipped with Scott Model 3200 or 3400 tail wheels.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
108 Series; T.C. 767	SA3-606	Complete recover of all fabric surfaces with dacron fabric.	GL	30518	Downer Aircraft Industries, Inc. Alexandria, MN 56308
108 Series; T.C. 767	SA4-46	Lycoming O-435-1 engine, accessories, and Hartzell HC-12X20-8D propeller.	WE	71000	Serv-Aero Engineering, Inc. P.O. Box 96 Dos Palos, CA 93620
108 Series; T.C. 767	SA4-148	Conversion of aircraft electrical system to 24 volts and/or installation of Franklin 6A4-165-B3 engine. Reissued 10/5/79.	WE	18125	Dean D. Brubaker P.O. Box 84409 861 South Bringham Avenue Los Angeles, CA 90073
108 Series; T.C. 767	SA4-224	Application of fiberglass covering.	WE	85720	Whitehall Pacific Aviation, Inc. County Airport Oxnard, CA 93030
108 Series; T.C. 767	SA4-284	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
108 Series; T.C. 767	SA4-630	Eonite covering of wings, fuselage and ailerons.	WE	52090	William G. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
108 Series; T.C. 767	SA4-760	Ceconite 101 covering of wings, fuselage and ailerons.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
108 Series; T.C. 767	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage, and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
108 Series; T.C. 767	SA4-1195	Metalized wings.	WE	08223	Air-Mod 11379 Playa Street Culver City, CA 90230
108 Series; T.C. 767	SA4-1415	Autopilot. Reissued October 1973.	SW	17490	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
108 Series; T.C. 767	SA4-1484	Sheet metal on wings.	WE	33910	Robert B. Everitt 2134 Xavier Santa Clara, CA 95050
108 Series; T.C. 767	SA58EA	Conversion of airplane for parachute jumping and aerial photography operations.	NE	31368	East Coast Aviation Corp. Hanscom Field Lexington, MA 02173
108 Series; T.C. 767	SA124EA	Shur-Vent fuel tank filler cap.	EA	65332	Alfred R. Puccinelli 36 Bay Drive East Huntington, L.I., NY 11743

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
108 Series; T.C. 767	SA224SO	Removal of right door for parachute jumping and aerial photography operations.	SO	14760	Robert V. Barham 1984 Capri Drive Decatur, GA 30030
108 Series; T.C. 767	SA228WE	Removal of right cabin door for parachute jumping and aerial photography operations.	WE	40690	John C. Harrison 2535 Garfield Avenue Carmichael, CA 95608
108 Series; T.C. 767	SA327SO	Tricycle landing gear and Lycoming O-435 engine.	SO	68550	W.F. Robinson P.O. Box 241 Lanett, AL 36863
108 Series; T.C. 767	SA343WE	8:50X6 4-ply aircraft tires and 8:50X6 tubes.	NW	60172	Rex H. Morehouse 4922 Summers Lane Klamath Falls, OR 97601
108 Series; T.C. 767	SA463CE	Metal fuselage covering.	CE	84399	David Z. Walderer Flying W Ranch Fairdealing, MO 63939
108 Series; T.C. 767	SA515CE	Install metal wing covering.	CE	84399	David Z. Walderer Flying W Ranch Fairdealing, MO 63936
108 Series; T.C. A-767	SA666NW	Installation of Teflon control yoke bushings. Issued 10/2/78.	NW	46779	George O. Johnson 10015 South Meridian Puyallup, WA 98371
108 Series; T.C. A-767	SA906NW	Additional Harrison oil cooler. Issued 3/21/80.	NW	70620	Seaplane Flying, Inc. P.O. Box 61586 Vancouver, WA 98666
108 Series; T.C. 767	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
108 Series; T.C. 767	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm). Issued 2/9/70.	WE	48750	K S Avionics 18145 Judy Street Castro Valley, CA 94546
108, 108-1, -2, -3; T.C. 767	SA3-366	Installation of FluiDyne (Fli-lite) Model 3000 main skis and Model 1000 tail skis. Reissued 7/22/79.	GL	36060	FluiDyne Engineering Corp. 5900 Olson Memorial Highway Minneapolis, MN 55422
t+1 108, 108-1, -2, -3; T.C. 767	SA615SO	Surface fabric attachment clips. Reissued 4/22/75.	WE	11600	The Arbor Company P.O. Box 398 Columbia, CA 95310
108, 108-1, -2, -3; T.C. 767	SA859SO	Replacement of generator P/N 1101877 installed in Franklin 6A-150 and -165 engines with a modified Motorola RA12N550 alternator. Issued 10/20/75.	SO	15240	Stanley C. Bedford 2396 Santa Cruz Drive Clearwater, FL 33516
108, 108-1, -2, -3, -4, -5; T.C. A-767	SA800EA	Installation of aviation white anti-collision strobe lights, Whelen Models A429, A430, A434, A408W (white), A408R/W or A470R/W (red/white), A500, or A650 and associated power supplies or Model SA strobe light system. Amended 10/4/78.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
108 Series, 415C, 415CD, 415D, E, G; T.C. 767, 718, 787	SA4-1210	Installation of Eonnex cover on aircraft surfaces. Reissued 8/19/80.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
(Stinson) 108-1, -2, -3, -4, -5, (Erco, Alon) 415-C, -CD, 415-D, -E, -G; T.C. 767, 718, 787	SA2666WE	Ceconite 102 material covering of: 108 Series - wings, fuselage and ailerons; 415 Series - wings. 4/19/78	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
108, 108-1, -2, -3, -4, -5, 415C, -CD, 415-D, E, G; T.C. A-767, 718, 787	SA1351WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
108, 108-1, -2, -3, -5; T.C. 767	SA799WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheel assemblies in lieu of Firestone wheel assembly No. DFA 180. (DGA-2000 wheel approved under TSO-C26a.) Amended 12/27/78.	WE	16860	Malcolm E. Bodell 23804 Pennsylvania Avenue Torrance, CA 90501

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
108 Series, A-2, A-2A, 415D, E, G, F-1, F-1A, M-10; T.C. 767, A-787	SA798EA	Installation of Monitair exhaust gas combustion monitor kit. Reissued 2/14/72.	GL	69200	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, MN 55343
108 Series, 415; T.C. 767, 718, 787	SA1008WE	Poly-Fiber covering of left and right-hand aileron. Amended 2/1/67.	WE	75250	Stits Aircraft Corporation Box 3084 Riverside, CA 92502
108 Series, F-1, F-1A; T.C. 767, 787	SA1177WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Av Torrance, CA 90510
108 Series, 415C; T.C. 767, 718	SA1350WE	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with fiberglass cloth. Reissued 3/6/69.	WE	20250	Ceconite, Inc. 4677 Worth Street Los Angeles, CA 90063
108-1, -2, -3, 415C, -CD, F-1, F-1A, 415D, E, G, A-2, A-2A; T.C. 767, 718, 787	SA1716WE	Installation of exhaust gas temperature (EGT) system. Amended 3/20/70.	RM	40500	Hanna-Aero Corporation 5222 South HOlly Street Littleton, CO 80120
108, -1, -2, -3, -5, 415-C, -CD, A-2, A-2A, 415D, E, G, F-1, -1A, M10; T.C. 767, 718, 787	SA[illegible]	Installation of A.R.P. Industries, In[illegible] carburetor ice detection system 10[illegible] AP [illegible] single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6, and HA-6 series carburetors. Amended 11/20/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
108, -1, -2, -3, -5, 415-C, -CD, A-2, A-2A, 415D, E, G, F-1, -1A, M10; T.C. 767, 718, 787	SA489EA	Installation of A.R.P. Industries, Inc. carburetor ice detection system 107AP-12 or 107AP-24 in single and twin engine aircraft and single engine helicopters powered by Continental, Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 11/30/78.	EA	65332	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
108-1, -2; T.C. A-767	SA963NW	Lycoming O-360-A1A, Sensenich 76EM8-0-56 propeller cross over exhaust, modified carburetor inlet. Issued 7/23/80.	NW	09780	Alpine Aviation 62270 Powell Butt Road Bend, OR 97701
108-2, 108-3 (Landplane); T.C. 767	SA4-398	Installation of Lycoming O-435-C engine. Amended 7/10/75.	WE	71000	Serv-Aero Engineering, Inc. Municipal Airport Salinas, CA 93901
108-2, 108-3; Land and Seaplanes; T.C. A-767	SA1199WE	Installation of Continental O-470-A, -J, -K, -L or -R engine and McCauley 2A34C/90A or 2A36C/90M propellers; or O-470A, -J, -K, or -L engine and Hartzell HC-A2XF-1/8433 or BHC-A2XF-1/8433 propellers, or O-470-R engine and Hartzell BHC-C2Y/8468 propeller. Reissued 6/23/80.	NW	70620	Seaplane Flying, Inc. 1111 S.E. 5th Street Vancouver, WA 98661
108-3; T.C. A767	SA74NW	Install floats Edo. Issued October 1973.	NW	63500	PDX Aircraft Corporation 1906 Northeast Liberty Street Portland, OR 97211
108-3; T.C. A767	SA91NW	Installation of strobe light system with flashtube on rudder tip and power supply in fuselage. Amended 3/11/74.	NW	70384	R.J. Schroers 4479 139th Avenue SE Bellevue, WA 98006
108-3; T.C. A-767	SA238NW	Installation of Madras Air Service super tips. Issued 11/25/75.	NW	54000	Madras Air Service Route 2, Box 1225 Madras, OR 97741
108-3; T.C. A-767	SA313NW	Installation of Franklin 6A-350-C1 engine and Hartzell HC-C2YF-1BF/F8459-4 to -8 propeller; also, McCauley 2A31C21/8456.	NW	70620	Seaplane Flying, Inc. 1111 S. E. Fifth Street Vancouver, WA 98661
108-3; T.C. A-767	SA637NW	Installation of oil filter assembly OF-104A. Issued 7/13/78.	NW	70620	Seaplane Flying, Inc. P.O. Box 2164 Vancouver, WA 98661
415 Series; T.C. 718, 787	SA1-4	Metal covering of outer wing panels.	EA	72098	Skycraft Design Old Star Airport Langhorne, PA 19047

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
415 Series; T.C. 718, 787	SA1-78	Metal skin replacement on wing surfaces.	EA	78623	George Townson P.O. Box 541 Meadowbrook, PA 19046
415 Series; T.C. 718, 787	SA1-208	Two 4595 100-watt General Electric sealed beam landing lights in nose cowling.	EA	08340	Air Service, Inc. P.O. Box 189 New Castle, DE 19720
415 Series; T.C. 718, 787	SA1-336	Continental C-90-14F engine and McCauley 1B90-CM7152 propeller.	EA	84925	Richard W. Weitley Skyport, P.O. Box 1229 Harrisburg, PA 17105
415 Series; T.C. 718, 787	SA1-440	Continental C90-12F engine.	EA	84925	Richard W. Weitley Skyport, P.O. Box 1229 Harrisburg, PA 17105
415 Series; T.C. 718, 787	SA3-19	Steel tube and aluminum covered hatch doors fabricated with plexiglass windows.	GL	01865	Aerodyne Products 2004 South 29th Street Milwaukee, WI 53202
415 Series; T.C. 718, 787	SA3-342	Metal 0.020-inch 20 24 ST 3 or 20 24 ST 4 alclad aluminum.	CE	60174	John J. Morelli Route 6, Box 428 Parkville, MO
415 Series; T.C. 718, 787	SA3-512	Aluminum alloy skin.	GL	28565	Robert B. Dale 30030 Minglewood Lane Farmington, MI 48024
415 Series; T.C. 718, 787	SA3-598	Metal 0.020 24ST aluminum on wings.	GL	86202	Harvey A. Williams 1446 North Lockwood Avenue Chicago, IL 60607
415 Series: T.C. 787	SA4-73	Metal skins 0.020 24ST and/or 75ST aluminum alloy.	WE	29160	Vern Dell Aircraft Metal Work Co. P.O. Box 42 Chula Vista, CA 92010
415 Series; T.C. 718, 787	SA4-139	Glass cloth over old fabric.	WE	85720	Whitehall Pacific Aviation, Inc. P.O. Box 31174 Ventura, CA 93001
415 Series; T.C. 718, 787	SA4-179	Fabric covering replaced with metal 0.020 24ST and/or 75ST aluminum alloy covering.	WE	29160	Vern Dell Aircraft Metal Work Co. P.O. Box 42 Chula Vista, CA 92010
415 Series; T.C. 718, 787	SA4-285	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
415 Series; T.C. 718, 787	SA4-302	BN-1 propeller spinner.	WE	75252	Raymond M. Stits 3665 Bloomington Boulevard Riverside, CA 92502
415 Series; T.C. 718, 787	SA4-361	Aluminum alloy sheet on wings.	WE	19900	Carma Manufacturing Company P.O. Box 11312 Tucson, AZ 85700
415 Series; T.C. 718, 787	SA4-399	Metallizing of wings.	WE	77520	L.J. Tarnay 9314 Glasgow Place Los Angele, CA 90052
415 Series; T.C. 718, 787	SA4-441	New lower engine cowl made of fiberglass with Hetron #92 resin.	WE	78471	Wilbur Thompson 10617 South Prairie Avenue Inglewood, CA 90306
415 Series; T.C. 718, 787	SA4-448	New nose cowl made of fiberglass reinforced with Hetron #92 resin.	WE	78471	Wilbur Thompson 10617 South Prairie Avenue Inglewood, CA 90306
415 Series; T.C. 718, 787	SA4-729	Mounting brackets, flush window, and wiring to operate automotive type sealed-beam headlamp as a dual purpose landing and taxi light.	WE	01804	Aero Development Corporation P.O. Box 11201 Tucson, AZ 85706
415 Series; T.C. 718, 787	SA4-801	Ceconite 101 covering of wings.	WE	26240	Cooper Engineering Company P.O. Box 3428 Van Nuys, CA 91408
415 Series; T.C. 718, 787	SA4-839	Metal covering of wings.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series; T.C. 718, 787	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	WE	07690	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
415 Series; T.C. 718, 787	SA4-1652	Tapered roller bearing and plate on right-hand wheel half.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
415 Series; T.C. 718, 787	SA117WE	WECO carburetor temperature monitor.	WE	86550	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90510
415 Series; T.C. 718, 787	SA162SO	Aileron trim system.	SO	03122	Aerotronics, Inc. Miami Beach, FL 33139
415 Series; T.C. 718, 787	SA341WE	Engine mount to remove down thrust and change horizontal tail incident.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series; T.C. 718, 787	SA465WE	Continental C-90-12F engine and McCauley 1B90-CM propeller.	WE	22218	R.B. Christianson 10510-1/2 Mather Avenue Sunland, CA 91040
415 Series, F-1; T.C. 718, 787	SA4-638	Single arm nose wheel fork with conventional double arm fabricated fork U415-34090-1-A and B.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80011
415 Series, F-1, F-1A; T.C. 718, 787	SA4-1254	Main gear wheel fairings, nose gear wheel fairing.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90275
415 Series, F-1, -1A; T.C. 718, 787	SA4-1606	Wing root fillets change from aluminum 3S and 24ST3 to fiberglass.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series, F-1, -1A; T.C. 718, 787	SA1WF	Fiberglass tail cone.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415 Series, F-1, -1A; T.C. 718, 787	SA3WE	Fiberglass reinforced plastic engine cowl.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
415-C, 415-CD, S/N 813 and up; T.C. A-718	SA120GL	Install Cleveland Wheel and Brakes conversion kit, P/N 199-69. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
415-C, 415-CD; T.C. A-718	SA330GL	Installation of Skyport Model SMK-15, 9-cu.ft. baggage compartment. Issued 7/18/79.	GL	36566	Skyport Aircoupe Services Division Fox Engineering Company 1340 Francis Street Jackson, MI 49203
415C, S/N 113 thru 812; T.C. A-718	SA2185WE	Installation of main gear wheel fairings and/or nose gear wheel fairing (nose gear fork P/N 415-34096 required for latter installation). (These fairings eligible for installation separately or in conjunction.) Issued 6/9/70.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
415C, S/N 113 thru 812; T.C. A-718	SA3293WE	Installation of McCauley 1B90CM7351 propeller on aircraft equipped with Continental C-75-12 engine. Issued 11/15/76.	WE	39820	Ronald T. Hagerman
(Erco) 415-C, 415-CD; T.C. A-718	SA3502WE	Installation of fiberglass nose bowl. Issued 10/7/77.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
415C, -CD, -D, -E, -G, F-1, F-1A; T.C. A-718, A-787	SA319WE	Metal cover of wings in accordance with Air Fab Drawing No. 104, Rev. No. 1. Reissued 7/29/71.	RM	81000	Univair Aircraft Corporation Route 3, box 59 Aurora, CO 80010
415C, -CD, -D, -E, -G, F-1, F-1A; T.C. A-718, A-787	SA437WE	Installation of leading edge landing light in accordance with Air Fab Drawing No. 1011. Reissued 7/29/71.	RM	81000	Univair Aircraft Corporation Route 3, Box 59 Aurora, CO 80010
415C, 415CD, 415D, E, G; F-1, F-1A; A-2, A2-A, M10; T.C. A-718, A-787	SA2462WE	(1) Installation of main gear wheel fairings; (2) installation of nose gear wheel fairings. (These items eligible for installation separately or in conjunction with each other.) Issued 3/3/72.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
415D; T.C. A-787	SA5GL	Removal of fuselage fuel tank. Issued 10/3/72.	GL	28790	Norvel O. Dasher Route 1, Box 61 Elgin, IL 60120
415D; T.C. A787	SA381SO	Revised (1) brake handle per Drawing 9R, (2) seat belt anchor straps to seat per Drawing 10R, (3) rudder control system springs per Drawing 11R. Amended 3/14/68.	SO	68550	W.F. Robinson P.O. Box 241 Lanett, AL 36863

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
415D; T.C. A787	SA2628WE	Installation of Continental O-200-A engine, McCauley 1A101/DCM 6948 propeller, electric fuel transfer pump and associated changes. Amended 2/25/74.	WE	78624	Towns Aviation Service, Inc. 1800 West Deer Valley Road Phoenix, AZ 85027
415-D, E, G, (Erco) (Forney) F-1, F-1A; T.C. A-787	SA127GL	Install Cleveland Wheel and Brakes conversion kit, P/N 199-69. Reissued 10/28/80.	GL	62500	Aircraft Wheel & Brake Division Parker Hannifin Corporation 1160 Center Road Avon, OH 44011
415-D, E, G, F-1, F-1A; T.C. A-787	SA331GL	Install Skyport Model SMK-15, 9-cu.ft. baggage compartment. Issued 7/18/79.	GL	36566	Skyport Aircoupe Services Division Fox Engineering Company 1340 Francis Street Jackson, MI 49203
(Erco) 415-D, E, G, F-1, F-1A, A-2, A2-A, MI0; T.C. A-787 t+1	SA3503WE	Installation of fiberglass nose bowl.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
A-2; T.C. 787	SA1126WE	B2S autopilot.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
A-2; T.C. 787	SA1495WE	Installation of Brittain Model B2C flight control system.	EA	17500	Brittain Industries Div. Narco Scientific Industries Commerce Drive Fort Washington Industrial Park Fort Washington, PA 19034
A-2, A2-A, M-10; T.C. A-787	SA2230WE	Installation of main gear wheel fairings on models equipped with "spring gear" main landing gear assemblies; also installation of nose gear wheel fairings. (These items eligible for installation separately or in conjunction with each other.) Amended 3/17/72.	WE	47750	Kenney Engineering 4120 Via Solano Palos Verdes Estates, CA 90274
F-1, F-1A; T.C. 787	SA4-1590	Riveted fuel tanks changed to welded wing and nose tank assemblies and gauge from mechanical to electric float type.	WE	58500	Met-Co-Aire P.O. Box 2216 Fullerton, CA 92633
(Alon) A-2, A-2A, (Forney) F1, F-1A, (Mooney) M10; T.C. A-787	SA71GL	Install BA-4106 filter assembly. Reissued 9/22/79.	GL	17060	Brackett Aircraft Specialties Co. 9600 West 52nd Street Kenosha, WI 53140

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

AVCO CORP., LYCOMING DIV.

Revised 3/31/81

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
O-145, O-235, O-350, O-435, GO-435, O-290, O-320, O-340, VO-435, O-360, HO-360-A1A, VO-360, TO-360, LTO-360, VO-540-B & C, TVO-540-A1A, O-540 Series; T.C. 199, 210, 233, 227, 228, 229, 274, 277, 279, 286, 295, 1E1, E26EA, 304, 1E14	SE1-201	Installation of Richter B-4 or B-5 probes in Marvel-Schebler MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6, HA-9 and Bendix NA-S3B and NA-S3A1 carburetors. Amended 9/20/77.	EA	68000	Richter Aero Equipment, Inc. Essex, NY 12936
O-145-A; O-145-B, -C, GO-145; O-233-A1; O-235; O-290; O-320; IO-320; O-340; O-350; O-360, HO-360; IO-360; VO-360; O-435-1, -4, -5, -11, -13, O-435-2, GO-435, -6, -17; GSO-435, -B, -B2; VO-435, -21-23; TVO-435; GO-480; TSO-480-1, IGSO-480, -2; O-540; IO-540; IGO-540; IGSO-540; VO-540; TVO-540; GSO-580; SO-580, VSO-580; IO-720-A1a; T.C. 199, 210, 223, 229, 274, 1E12, 277, 227, 286, 1E10, 1E1, 228, 276, 279, 1E13, 275, 284, 295, 1E4, 1E11, 1E7, 304, 1E14, 256, 285, 1E15	SE44WE	Use of Kling Aviation Oil, Specifications KL-100, KL-200 and KL-300 in Continental and Lycoming engines.	WE	48530	Kling Oil Company 1492 Oddstad Drive Redwood City, CA 94063
O-235-L2C; T.C. E-223	SE792NW	Modification of engine to increase HP rating from 115 HP at 2700 rpm to a continuous 125 HP at 2800 rpm. Issued 6/28/79.	NW	16851	Ken Blackman 7305 97th Avenue, S.E. Snokomish, WA 98290
O-235, O-290, O-320 Series; T.C. 223, 229, 274	SE5CE	Prestolite ALK-5001 alternator.	GL	49650	Larsen Industries 7790 Rawsonville Road Belleville, MI 48111
O-235, O-290, O-320, O-540, O-360 Series; T.C. E-233, E-229, E-274, E-295, E-286 w/Marvel-Schebler MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6	SE208SO	Installation of ice indicator in the carburetor.	SC	71545	Charles B. Shivers, Jr. 8928 Valleybrock Road Birmingham, AL 35206
O-320 Series; T.C. 274	SE2-7	Carburetor air temperature bulb in Marvel-Schebler MA-4-5 carburetor.	GL	53125	Lynn McElroy Westervelt, IL 62574
O-320 Series; T.C. 274	SE508AL	Addition of crankcase release valve. Issued 11/12/73.	AL	75500	Stoddard Aero Service 2550 E. Fifth Avenue Anchorage, AK 99501
O-320 or O-320-A1A; T.C. 274	SE2392SW	Conversion to fuel injection configuration equivalent IO-320-E2A. Issued 12/10/76.	SW	77124	Swick Aircraft Corporation Route 3, Box 163B Lewisville, TX 75067
O-320-A, -B; T.C. 274	SE4-1638	Installation of one Rajay Turbocharger. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
O-320-A2B, -A2D, -E2A, -E2B, -2C, -E2D, -E2G, -E2D; T.C. E-274	SE1226CE	Modify engines for a 160 horsepower rating on 100/130 minimum grade fuel. Amended March 1977.	CE	63600	W.A. Pearce 120 North Old Manor Wichita, KS 67208
IO-320-A1A, -B1A, -B1B, -C1A; LIO-320-B1A, -C1A; T.C. 1E12	SE14WE	Installation of one Rajay Turbocharger P/N RJ 0325, RJ 0326, RJ 0326-1 or RJ 0326-2. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
IO-320-E2A, IO-320-E2B, IO-320-E1A; T.C. 1E12	SE7CE	Modification of oil sump in accordance with Champion Drawing No. 7-1312E. Amended 7/18/75.	GL	15405	Bellanca Aircraft Corporation Box 624, Municipal Airport Alexandria, MN 56308
O-360-A1A T.C. E-286	SE2887SW	Install Bendix PS-5C carburetor. Issued 12/14/78.	SW	77124	Swick Aircraft Route 3, Box 163B Lewisville, TX 75067
O-360-A1A, -A1D; T.C. 286	SE154SO	Installation of one Rajay Turbo-supercharger Model RJ 0325, RJ 0326, RJ 0326-1 or RJ 0326-2 Amended 2/20/69.	WE	66250	Rajay Corporation 2602 East Wardlow Road Long Beach, CA 90807
HO-360; T.C. 286	SE30WE	Conversion to Lycoming HIO-360-B1B engines.	WE	62080	Pacific Airmotive Corporation 3411 Tulare Avenue Burbank, CA 91502
HIO-360-E1AD, -E1BD; T.C. 1E10	SE100GL	Installation of Rajay 301E10-2 turbocharger. Amended 3/19/80.	GL	33475	Enstrom Helicopter Corporation P.O. Box 277 Menominee, MI 49858
HIO-360-F1AD; T.C. 1E10	SE484GL	Installation of Rajay Model 325E10-2, P/N RJ0332 turbocharger. Issued 12/31/80.	GL	33475	The Enstrom Helicopter Corp. P.O. Box 277 Menominee, MI 49858
IO-360-A1A, A1B, A1C, A2A, A2B, A2C, B1A, B1B, B1C, B1D, B1E, B1F, B2E, B2F, B4A, C1E6, C1A, C1B, C1C, D1A, E1A, AIO-360-A1A, A1B, A2A, A2B, B1B, LIO-360-C1E6; T.C. 1E10	SE32WE	Installation of one turbosuper-charger, Rajay turbocharger, P/N RJ 0325, RJ 0326, RJ 0326-1, RJ 032602 and RJ 0329. Amended 3/31/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
IO-360-A1D6D, IO-360-A3D6D; T.C. 1E10	SE90WE	Installation of Rajay Turbochargers Model 325E10-1, P/N RJ0331-1, on Lycoming engine models listed. Issued 12/22/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
GO-435-C2, -C2A, -C2B, -C2B1, C2B6; T.C. 288	SE579SO	Installation of Bendix magneto models S6LN-20 and S6LN-21. Issued 2/21/74.	SO	53790	Mack's Aircraft Engine Service P.O. Box 336 Wetumpka, AL 36092
GO-435 Series, GO-480 Series; T.C. E228, E-275	SE914NW	Replace propeller governor adapter with a combination adapter/valve to provide propeller reversing control. Issued 4/3/80.	NW	71790	Simuflight, Seattle 6727 Perimeter Road, South Seattle, WA 98108
VO-435 Series; T.C. 279	SE2-856	American Bosch Induction vibrator VJR24B56X.	SW	15350	Bell Helicopter Corporation P.O. Box 482 Fort Worth, TX 76101
VO-435-A1E, -A1F; T.C. E-279	SE959EA	Modification to higher compression ration. Reissued 3/16/76.	EA	03300	Agrotors, INC. Box 578 Gettysburg, PA 17325
VO-435-A1E, -A1F; T.C. 279	SE2733SW	Modification to higher compression ratio. Issued 3/21/78.	SW	26000	Continental Copters, Inc. P.O. Box 13284 Fort Worth, TX 76118
VO-435-A1F; T.C. E-279	SE144GL	Modify engine to increase compression ratio to 8.7:1. Amended 2/17/77.	GL	49320	Lake Line Helicopters, Inc. 13601 Pioneer Trail Eden Prairie, MN 55343
GO-480 Series; T.C. 275	SE124SO	Two Rajay turbochargers 315A10. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
t+1 GO-480 Series; T.C. 275	SE135SO	Two Rajay turbochargers 315A10. Reissued 1/14/69.	WE	66250	Rajay Industries 2602 E. Wardlow Road Long Beach, CA 90807
GO-[illegible] -C266, F[illegible] [illegible]3B6; T.	SE580SO	Installation of Bendix magneto models S6LN-20 and S6LN-21. Issued 2/21/74.	SO	53790	Mack's Aircraft Engine Service P.O. Box 336 Watumpka, AL 36092
GO-[illegible] T.[illegible]	SE18WE	Installation of AiResearch T-1112 turbosupercharger. Reissued 4/27/70.	WE	85135	Western Commander, Inc. 16300 Daily Drive Van Nuys, CA 91406
O-[illegible] T.C.	SE17WE	Turbosupercharger 406330.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
O-[illegible] T.C.	SE40WE	Installation of two Rajay Turbo-chargers. Reissued 1/14/69.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
IO-540 Series; T.C. 1E4	SE21WE	Turbosupercharger 406610-2.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
IO-540 Series; T.C. 1E4	SE22WE	Turbosupercharger 406610-2.	WE	07500	AiResearch Aviation Service Co. 6201 W. Imperial Highway Los Angeles, CA 90045
IO-540-A1A5; T.C. 1E4	SE201SO	Modification of engine oil dip stick to provide 10.5 quart useable oil capacity in lieu of 9.25 quart capacity.	SW	68145	Riley International Corporation 6211 W. Northwest Highway Dallas, TX 75225
IO-540-A1A5, B1A5, B1B5, B1C5, C1B5, C1C5, C2C, C4B5, C4C5, C2C, C4B5, C4C5, E1A5, E1B5, G1A5, G1B5, G1C5, G1D5, G1E5, J4A5, K1A5, K1B5, L1A5, M1A5, P1A5, K1C5; K1F5, S1A5, K1E5; T.C. 1E4	SE6WE	Installation of two Rajay turbochargers P/N 0080-100, or -102. Amended 10/7/74.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
IO-540-A1A5, B1A5, B1B5, B1C5, E1A5, E1B5, E1C5, G1A5, G1B5, G1C5, G1D5, G1E5, P1A5, G1F5, S1A5; T.C. 1E4	SE60WE	Installation of two Rajay turbochargers P/N RJ 0327-1 or -2 and and 9 lb. ± 1 sonic nozzle. Amended 9/19/73.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90807
IO-540-K1G5D; T.C. 1E4	SE85WE	Installation of two Rajay turbochargers Model 315F10-2, P/N RJ 0080-102, on Lycoming engine. Issued 11/8/77.	WE	66250	Rajay Industries, Inc. 2600 East Wardlow Road P.O. Box 207 Long Beach, CA 90801
IO-540-S1A5 T.C. 1E4	SE81WE	Installation of two Rajay turbochargers, Model 325EF80, P/N 0330-1 and -2, and 9 lb. ± 1 lb. sonic nozzle on Lycoming engine Model IO-540-S1A5. Reissued 4/11/78.	WE	64666	Piper Aircraft Corporation Santa Maria Division 2560 Skyway Drive Santa Maria, CA 93454
IGSO-540-A1A, -A1D; T.C. 1E7	SE442GL	Incorporation of a fuel flow transducer. Issued 9/15/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
LTIO-540-J2BD, TIO-540-J2BD; T.C. E14EA	SE978NW	Installation of an AiResearch T18A21 turbocharger and Machen intercooler. Issued 7/16/80.	NW	52625	Machen, Inc. S. 3608 Davison Boulevard Spokane, WA 99204
TIO-540-A1A, -A2A, -A1B, -A2B, -A1C, -A2C, -F2BD, -J2BD, LTIO-540-F2BD, -J2BD; T.C. E14EA	SE445GL	Incorporation of a fuel flow transducer. Issued 9/15/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
R-680-D6 (89-2000); T.C. 173	SA291SW	Revised cover plates.	SW	05752	Aircraft Parts 6037 Cameron Boulevard New Orleans, LA 64822
IO-720-A1A; T.C. 1E15	SE163SO	Two Rajay turbochargers 325E10.	SW	68145	Riley International Corporation 6211 W. Northwest Highway Dallas, TX 75225
IO-720-A1A; T.C. 1E15	SE205SO	Two Rajay turbochargers 325H10.	SW	68145	Riley International Corporation 6211 W. Northwest Highway Dallas, Texas 75225
t+1 IO-720-A1A, -A1B; T.C. 1E15	SE51WE	Installation of two (2) Rajay P/N RJ0326, RJ0326-1 or RJ0326-2 (or any combination thereof) turbochargers on Avco Lycoming Model IO-720-A1A and IO-720-A1B engines. Amended 1/18/74.	WE	66250	Rajay Industries, Inc. 2602 E. Wardlow Road Long Beach, CA 90801
IO-720-A1A, -A1B; T.C. 1E15	SE63WE	Installation of starter ring gear support assembly. Issued 12/12/73.	WE	01390	Neil J. Adler 2870 Sugarman Court La Jolla, CA 92037
IO-720-B1B; T.C. 1E15	SE62WE	Installation of two Rajay turbochargers, P/N RJ 0326 or -1 or -2. Amended 8/19/75.	WE	69220	Mr. RPM Suite 321 7120 Hayvenhurst Avenue Van Nuys, CA 91406

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

ENGINE

DETROIT DIESEL ALLISON DIV.

Revised 3/31/81

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
250-C20, -C20B; T.C. E4CE	SE769NW	Modification of fuel and pneumatic system on Bendix controlled Allison engines. Issued 7/26/79.	NW	73721	Soloy Conversions P.O. Box 60 Chehalis, WA 98532
250-C20B; T.C. E4CF	SE492GL	Incorporation of a fuel flow transducer. Issued 1/13/81.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Minneapolis, MN 55426
501-D13D, H; T.C. E-282	SE1161EA	Manufacture of magnetic plugs with self-closing valve. Issued 7/26/79.	EA	77590	Technical Development Corp. 24 East Glenolden Avenue Glenolden, PA 19036

SUMMARY OF
FEDERAL AVIATION ADMINISTRATION
SUPPLEMENTAL TYPE CERTIFICATES
ENGINE
TELEDYNE CONTINENTAL MOTORS

Revised 3/31/81

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
A-40, -2, -3, -4; A-40-5; A-50; A-65; A-70, -2; A-75; A-80; A-100; C-75, C-85; C-90; C-115, -125; C-145; E-165, E-185; E-225, -2, -4, -8, -9; O-200-A; O-300; GO-300-A thru F; IO-346-A, -B; IO-360-A thru D; O-470-4, -11, -11-C1, -13-13A, -15; O-470-A, B, E, G, H, J, K, L, M, N, P, R; GIO-470-A; IO-470-A, -C; O-470-D thru U; FSO-470-A, -2; TSIO-470-B, -C, -D; IO-520-A, -B, -C; FSO-526-A, -C; GSO-526-A; GTSIO-520-C; TSIO-520; ATC 72, 174, T.C. 190, 205, ATC 32, T.C. 213, 217, 241, 233, 236, 246, 252, 253, 267, 298, E3CE, E1CE, 269, 273, E2CE, 3E1, 281, 3E3, E5CE, 292, 303, E7CE, E8CE-2	SE44WE	Use of Kling Aviation oil, specifications KL-100, KL-200, and KL-300 in Continental and Lycoming engines.	WE	48530	Kling Oil Company 1492 Oddstad Drive Redwood City, CA 94063
A-50, A-65, A-70, A-80, C-85, C-90, O-200, C-75, C-115, C-125, C-145, O-300, E-165-2, E-185-2, O-470, GO-300; T.C. 190, 205, 213, 217, 233, 252, 236, 253, 246, 273, 298	SE1-201	Installation of Richter B-4 or B-5 probes in Marvel-Schebler carburetors MA-2, MA-3, MA-4, MA-4-5, MA-5, MA-6, HA-6 series and Bendix NA-S3B and NA-S3A1. Amended 9/20/77.	EA	68000	Richter Aero Equipment Essex, NY 12936
A-50, A-65, A-70, A-80, C-85, C-90, O-200, C-115, C-125, C-145, O-300, E-165, E-185, O-470, GO-300; T.C. 190, 205, 213, 217, 233, 252, 236,	SE208SO	Installation of ice indicator in the carburetor.	SO	71545	Charles B. Shivers, Jr. 8928 Valleybrook Road Birmingham, AL 35206
A-65 Series; T.C. E-205	SE64WE	Installation of oil screen and oil cooler adapter. Issued 5/24/74.	WE	42137	Laurence E. Hill 336 South Parish Place Burbank, CA 91506
A65, A75, C75, C85 Suffix "F" Series; T.C. 205, 213, 233	SE4CE	Motorola alternator A12NK451. Amended 1/20/78.	CE	15404	Steven E./Robert F. Bell R.R. #1, Box 5 Lawrence, KS 66044
A65, A75, C75, C85 Suffix "F" Series; T.C. 205, 213, 233	SE984SW	Delco 55A ampere alternator.	SW	84396	Lee A. Waldrop 7624 Palomar Fort Worth, TX 76118
A65, A75, C75, C85 Series; T.C. E-205, E-213, E-233	SE4247SW	Regrind crankshaft to .020 undersize on crankpin and main journals. Issued 12/17/80.	SW	28490	Daily Tubbs Aero, Inc. 141 Braniff San Antonio, TX 78216
C-85; T.C. 233	SE3CE	P-30-A alternator.	GL	67160	Kenneth J. Pepke 7788 Auburn Detroit, MI 48233
C-145, O-300 Series; T.C. 253	SE3-663	Install dry vacuum pump drive. Reissued 7/15/69.	GL	03750	Airborne Manufacturing Company 711 Taylor Street Elyria, OH 44035
E-165-2, E-185-1, -3, -8, -9, -11; T.C. E-246	SE416GL	Installation of a spin-on oil filter adapter and spin-on filter in lieu of original screen. Reissued 9/8/80.	GL	71920	S & K Engineering Rt #1, Box 417E Greeneville Municipal Airport Greeneville, TN 37743
D-185, E-225 Series; T.C. 246, 267	SE419SW	Full flow oil filter. Amended 3/1/67.	GL	77017	The Superior Flow Company Div. of A & E Manufacturing, Inc. 11300 Schaefer Highway Detroit, MI 48233

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
E-185 Series; T.C. 246	SE248EA	MOdification of Hartzell C-192-2 "T-Drive" for use with Airborne Mechanisms dry vacuum pump.	EA	85600	Edward J. White 207 Stephen Drive Cinnaminson, NJ 08077
E-185, E-225, O-470 Series; T.C. 246, 267, 269	SE23SW	R5-5BD1 fuel injection system.	GL	15500	Bendix Products Aerospace Div. 717 Bendix Drive South Bend, IN 46600
O-200 Series; T.C. E-252	SE2791SW	Revised starter clutch. Issued 6/6/78	SW	14214	B C & J Enterprises P.O. Box 19676 Oklahoma City, OK 73144
O-200-A; T.C. 252	SE8WE	Alternate oil sump.	WE	78476	Thorp Aircraft Company 909 East Magnolia Boulevard Burbank, CA 91500
O-200-A; T.C. E-252	SE82WE	Closing off of the oil outlet port of the main thrust bearing; installation of an O-200-B crankshaft; modifying the front oil seal slinger flange; machining an already existing molded pad on the crankshaft to receive a side mounted fuel pump. Issued 10/11/77.	WE	48527	Harvey J. Klein 1736 S. Bedford Street Los Angeles, CA 90035
O-200-A; T.C. 252	SE1396SW	Revise engine oil pick up system. Issued 11/24/71.	SW	74600	M.H. Spinks, Sr. P.O. Box 11099 Fort Worth, TX 76110
E-225; T.C. 267	SE3WE	T-1106 turbocharger.	WE	07500	AiResearch Aviation Service Co. 6201 West Imperial Highway Los Angeles, CA 90045
E-225-4, -8; T.C. E-267	SE417GL	Installation of a spin-on oil filter adapter and spin-on filter in lieu of original screen. Reissued 9/8/80.	GL	71920	S & K Engineering Rt #1, Box 417B Greeneville Municipal Airport Greeneville, TN 37743
O-300-A, -B, -C, -D, -E; IO-360-A, -B, -C, -D; IO-470-D thru -H, -J, -K, -L, -M, -P, -S, -U, -V; O-470-J, -P, IO-470-C; O-470-4, -11, -13, -15; IO-520-A, -D, -E, -F, -J, -K, -L; TSIO-520-C, -G, -H; GTSIO-520-C, -D, -F, -H; T.C. 253, E1CE, 3E1, 273, 269, E5CE, E8CE, E7CE	SE12GL	Installation of oil filler cap. Issued 7/11/73.	GL	85850	Ray Whyte Electric Products Co. 30201 Harper Avenue St. Clair Shores, MI 48083
IO-346 and IO-520; T.C. E3WE, E5CE	SE34WE	Installation of Electro-Coatings, Inc. piston rings P/N 252501 and 252509 on Continental piston 631475 for use in Channel-cromium plated Continental IO-346 and IO-520 engine cylinder.	WE	33219	Electro-Coatings, Inc. 1401 Park Avenue Emeryville, CA
IO-360-A, -B, -C, -D, -G, -H, -J, -K; T.C. E1CE	SE234GL	Installation of a steel pin in Continental fuel pump, P/N 638157. Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
IO-360-K; T.C. E1CE	SE1436CE	Modify engine to obtain 210 hp, 2800 rpm for 5 minutes at takeoff and 195 hp 2600 rpm continuous (new designation IO-360-KC/STC SE1436CE). Issued 10/6/78.	CE	44802	Brad E. Isham 416 West Fourth Street Valley Center, KS 67147
TSIO-360-A, -B, -C, -D, -E, -F, LTSIO-360-E; T.C. E9CE	SE235GL	Installation of a steel pin in Continental fuel pump P/N 634263 (TSIO-360-A, -B), 639508 (TSIO-360-C, -D, -E, -F), and 639508 (LTSIO-360-E). Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
O-470 Series; T.C. 273	SE1CE	PSA-5 fuel injection system.	GL	15500	Bendix Products Aerospace Div. 717 Bendix Drive South Bend, IN 46600
O-470 Series; T.C. 273	SE141SW	Rework crankcase in area of starter drive needle bearing.	SW	43500	Hutchinson Aircraft Service P.O. Box 524 Borger, TX 79006
O-470 Series; T.C. 273	SE616SO	Installation of O-470-R parts in lieu of normal O-470-M parts.	SO	61644	North Perry Aviation, Inc. 8000 West Pembroke Road Hollywood, FL 33023

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
O-470-11, -13; T.C. 269	SE264SW	Marvel-Schebler MA-4-5 carburetor. Reissued 11/18/80.	SW	32000	Ector Aircraft Company, Inc. 414 East Hillmont Road Odessa, TX 79762
O-470, IO-470 Series; T.C. 273	SE325SW	Full flow oil filter. Amended 3/1/67.	GI	77017	The Superior Flow Company Div. of A & E Manufacturing, Inc. 11300 Schaefer Highway Detroit, MI 48233
O-470, IO-470 Series; T.C. 273, 3E1	SE73SO	Continental GIO-470 engine oil sump assembly 628943 and oil pump suction tube assembly 628660.	SO	05580	Aircraft Modification Engineering Company P.O. Box 48-1314 Miami, FL 32960
O-470, IO-470, TSIO-470 Series; T.C. 269, 273, 3E1, 3E3	SE16WE	Bendix S-600 low tension ignition system.	WE	70055	Salinas Engine Works Municipal Airport Salinas, CA 93901
O-470, IO-470, TSIO-470 Series; T.C. 269, 273, 3E1, 3E3	SE26WE	Piston ring 250000, 250000+2W and 250000+10W on Continental F Series piston 534895, O-470 piston 534895, 626992 and 537883 and IO-470 piston 534895.	SW	21500	Electro-Coatings, Inc. Channelcromium Division P.O. Box 428 Grapevine, TX 76051
O-470-A, J, K, L, R, G-C1, IO-470-C, -J, -K; T.C. 273, 3E1	SE25WE	Installation of two Rajay turbochargers Model 315F10, P/N RJ0080-102. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
O-470-B, -G, -H, -K, -L, -M, -N, -S, -T, -U, O-470-B-C1, G-C1, K-C1, L-C1, M-C1, IO-470-A, -C; T.C. E-273	SE95WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
O-470-R, O-470-S; T.C. E-273	SE1597CE	Replace carburetor fuel system with fuel injection and install oil and system provisions for turbosupercharger. Amended 2/4/81.	CE	27303	C & S Industries P.O. Box 106B Viola, KS 67149
IO-470 Series; T.C. 273, 3E1	SE82SO	Engine sump reworked to provide 15 1/8-quart total oil capacity.	SO	68140	Riley Aeronautics Corporation 2100 Northwest 50th Street Fort Lauderdale, FL 33300
IO-470 Series; T.C. 273, 3E1	SE387SW	Modification of ring grooves on Continental Motors pistons 539814 (3 ring) and 627738 (4 ring).	SW	82250	Van Der Horst Corporation of America P.O. Box 428 Terrell, TX 75160
IO-470 Series; T.C. 3E1	SE2-984	Modification of Continental IO-470 piston 6277338 for piston ring used in Continental O-470 piston 537883.	SW	21500	Pennington Channelcromium Company Division of Electro-Coatings, Inc. 319 Dakota Street San Antonio, TX 78205
IO-470 Series; T.C. 3E1	SE94SW	Modification of Continental IO-470 pistons 627738 and 539814 compression ring grooves.	SW	22250	Chrome Plate, Inc. 2805 South Flores Street San Antonio, TX 78205
IO-470 Series; T.C. 3E1	SE152SO	Modification of throttle body location.	SO	37084	Gander Aircraft Corporation 3923 Northwest 24th Street Miami, FL 33142
IO-470-C; T.C. E273	SE994SO	Installation of fuel line filters into individual fuel injector lines. Issued 5/25/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-470-D, -E, -F, -H, -L, -M, -N, -S, -U, -V, -VO; T.C. 3E1	SE69WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	SO	50270	Lewis Leitee 11196 South Fowler Avenue Selma, CA 93662
IO-470-D, -E, -F, -G, -H, -L, -LO, -N, -P, -R, -S, -T, -U, -V, -VO, LIO-470-A; T.C. 3E1	SE92WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-470-D, E, M, N, S, U, V; T.C. 3E1	SE96SO	Installation of two (2) Rajay turbochargers Model 315F10, P/N RJ0080-102. Amended 2/6/79.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
IO-470-J, -K, -N, L; T.C. 3E1	SE992SO	Installation of fuel line filters into individual fuel injector lines. Amended 9/17/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
IO-470, IO-520, TSIO-520 Series; T.C. E-273, 3E1, 3E3, E5CE, E8CE	SE55WE	Modification of fuel injection manifold valve P/N 626547 to the P/N 631427 or P/N 636326 configuration. Issued 2/10/72.	NW	85165	Western Skyways, Inc. Portland-Troutdale Airport Troutdale, OR 97060
GIO-470-A; T.C. E2CE	SE70WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
TSIO-470 Series; T.C. 3E3	SE166SW	Modification of Continental TSIO-470 Series piston 629185 for piston rings used in Continental O-470 Series piston 537883.	SW	21500	Pennington Channelcromium Co. Div. of Electro-Coatings, Inc. 319 Dakota Street San Antonio, TX 78205
TSIO-470 Series; T.C. 3E3	SE271SW	Modification of Continental TSIO-470 piston 629185 compression ring grooves.	SW	22250	Chrome Plate, Inc. 2805 South Flores Street San Antonio, TX 78205
TSIO-470-B, -C, -D; T.C. 3E3	SE71WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
TSIO-470B, C, D; T.C. 3E3	SE93WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-520, TSIO-520 Series; T.C. E5CE	SE70RM	Installation of JB Systems compressor brackets P/N 21-052-19. Amended 6/8/79.	RM	45750	JB Systems, Inc. P.O. Box 800 Longmont, CO 80501
GTSIO-520-C, -D; T.C. E7CE	SE74WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-520-A, -B, -BA, -C, -D, -E, -F, -J, -K, -L, -M; T.C. E5CE	SE72WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662
IO-520-A, -B, -BA, -C, -D, -E, -F, -J, -K, -L, -M; T.C. E-273	SE94WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
IO-520-B, -BA; T.C. E5CE	SE282GL	Installation of a fuel flow transducer, Symbolic Displays P/N 201B. Issued 11/14/78.	GL	41050	Hartzog Aviation, Inc. Greater Rockford Airport Rockford, IL 61109
IO-520-B, -BA, -BB; T.C. E5CE	SE443GL	Incorporation of a fuel flow transducer. Issued 9/15/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
IO-520-B, -BA, C; T.C. E5CE	SE993SO	Installation of fuel line filters into the individual fuel injector lines. Amended 9/17/76.	SO	16505	Beryl D'Shannon Aviation Specialties, Inc. P.O. Box 76155 Atlanta, GA 30328
IO-520-C, -CB, -M, -MB; T.C. E5CE	SE487GL	Installation of a fuel flow transducer. Issued 1/13/81.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Minneapolis, MN 55426
IO-520-D; T.C. E5CE	SE75WE	Installation of emergency fuel system. Issued 9/9/75.	WE	59730	Mission Aviation Fellowship Box 2828 3519 West Commonwealth Fullerton, CA 92633
IO-520-E; T.C. E5CE	SE451SO	Installation of air compressor gear box drive. Amended 4/6/71.	SO	65333	Puerto Rico Int'l Airlines P.O. Box 1498 Bayamon, PR 00619
IO-520-F; T.C. E5CE	SE80WE	Installation of an emergency fuel system. Issued 9/13/77.	WE	59730	Mission Aviaiton Fellowship P.O. Box 2828 Fullerton, CA 92633
IO-520-G; T.C. E7CE	SE1004SW	Install alternator braces. Reissued 4/2/79.	SW	26230	Cooper Airmotive Aircraft Service 7515 Lemmon Avenue Dallas, TX 75209
TSIO-520-A, -B, -C, -D, -E, -G, -H, -J, -K, -L; T.C. E8CE	SE73WE	BG-341 spark plug as eligible for installation on listed Continental engines. Issued 1/28/75.	WE	50270	Lewis Leibee 11196 South Fowler Avenue Selma, CA 93662

ENGINE MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
TSIO-520-A, -B, -C, -D, -E, -F, -G, -H, -J, -K, -L, -M, -N, -P, -R; T.C. E8CE	SE96WE	Installation of oil fitting (AN-823-5D) in rocker box cover. Issued 6/14/78.	WE	84396	Walker Engineering Company 2240 Sawtelle Boulevard Los Angeles, CA 90064
TSIO-520-E, -EB; T.C. E8CE	SE444GL	Incorporation of a fuel flow transducer. Issued 9/15/80.	GL	71503	Shadin Company, Inc. Suite 206 6950 Wayzata Boulevard Minneapolis, MN 55426
TSIO-520-C, M; T.C. E8CE	SE88WE	Installation of emergency fuel system. Issued 2/7/78.	WE	59730	Mission Aviation Fellowship Box 2828 Fullerton, CA 92633
TSIO-520-D; T.C. E8CE	SE57WE	Installation of two (2) Rajay P/N RJ0080-100, -101 or -102 turbo-superchargers on Continental Teledyne engine. Amended 11/17/78.	WE	66250	Rajay Industries, Inc. 2602 East Wardlow Road Long Beach, CA 90807
TSIO-520-D; T.C. E8CE	SE233GL	Installation of a steel pin in Continental fuel pump P/N's 639508 and 632637. Issued 4/20/78.	GL	11450	Approved Aircraft Accessories, Inc. 29300 Goddard Road Romulus, MI 48174
TSIO-520-K; T.C. E5CE	SE1908SW	Conversion of TSIO-520-K to TSIO-520-J. Issued 8/29/74.	SW	68146	Jack M. Riley, Jr. 4307 Shady Glen Waco, TX 76708
TSIO-520-N; T.C. E8CE	SE2831SW	Bendix S6RN-1251 and S6RN-1255 magnetos. Issued 8/78.	SW	66300	RAM Aircraft Modifications, Inc. P.O. Box 5219 Waco, TX 76708
TSIO-520-T; T.C. E8CE	SE1462CE	Installation of SSP Products heater core and shroud. Issued 12/4/78.	CE	20625	Cessna Aircraft Company Pawnee Division 5800 East Pawnee Wichita, KS 67201
W-670-6A; T.C. E-162	SE4127SW	Install modified W-670-23 piston, P/N 4180, to replace W-670-6A piston, P/N 4177. Issued 5/21/80.	SW	39710	Gulf Coast Dusting Company 5334 Allison Road Houston, TX 77048
Miscellaneous	SE34WE	Installation of Electro-Coatings, Inc., piston rings on Continental pistons. Amended 3/14/68.	SW	21500	Electro-Coatings, Inc. Channelcromium Division P.O. Box 428 Grapevine, TX 76051
Miscellaneous	SE41WE	Installation of emergency fuel system.	WE	59730	Missionary Aviation Fellowship P.O. Box 2828 Fullerton, CA 92633
Miscellaneous	SE43WE	Installation of an additional dowel in crankshaft accessory gear.	WE	16853	Willard S. Blackinton 9333 Edgewood Drive La Mesa, CA 92041

SUMMARY OF

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

PROPELLER

HAMILTON STANDARD DIVISION
UNITED TECHNOLOGIES CORPORATION

Revised 3/31/81

PROPELLER MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
22D Series; T.C. 736	SP185SO	B.F. Goodrich electric deicers.	EA	25635	Commuter A/C Manufacturing Corp. Box 904, Broome County Airport Binghampton, NY 13902
2D30 Series; T.C. 736	SP790SW	Seal carrier and "O" ring seals.	SW	73880	Southern Aviation Corporation P.O. Box 7224 Shreveport, LA 71102
2B20-61359; T.C. P-255	SP250NW	Installation of Hamilton propeller 2B20 hub with 6135-9 blades modified by adding blade cuffs and EAC-20-204 seal to replace HSP P/Ns 50287, 50116, 50015.	NW	62120	Pacific Propeller P.O. Box 946 Kent, WA 98031
2D30, 12D40, 22D30, 22D40; T.C. 206, 257, 736, 719	SP7WE	Installation of AG-100-2 and AG-200-2 propeller blades in Hamilton Standard hub. Amended 7/6/73.	NW	33000	Efficiency Aircraft Components, Inc. 5802 S. 222 Street Kent, WA 98031
22D30/6531A-15/ 6533-21; T.C. 736	SA185SO	Installation of B.F. Goodrich electric de-icers. Reissued 9/11/79.	SO	08169	Air-Lift Associates, Inc. Raleigh-Durham Airport Box 173 Morrisville, NC 27560
2D30, AG-100-4S; T.C. P-206	SP245NW	Manufacture AG-100-4S blades and CF AG-100-4S blades with cooling fairing and use thereof in Hamilton 2D30 hubs of P&W R-985, 450 h.p. engine. Issued 12/23/75.	NW	62120	Pacific Propellers P.O. Box 946 Kent, WA 98031
2D30, 12D40, 22D30, 22D40, 23D40, 33D50, 24D50; T.C. P-206, P-257, P-736, P-719, P-749, P-784	SP362NW	Propeller blade chaffing ring.	NW	62120	Pacific Propeller P.O. Box 946 Kent, WA 98031
2D30/6101A-10S; T.C. P-206	SP829SO	Vibration approval for single engine tractor installations only, on P & W Model P985-AN-1, -AN-3, -AN-14B, -25, -27, -39A, T1B2 and T1B3 engines. Amended 2/20/76.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116
3D40, 23D40; T.C. P-719, 249	SP148NW	Installation of EAC propeller blades in Hamilton Standard hubs (blades AG100-OS and AG200-OS). Amended 2/28/75.	NW	33000	Efficiency Aircraft Components, Inc. 5802 S. 222 Street Kent, WA 98031
3D40; T.C. 249	SA195NW	Installation of "O" ring seals in place of Hamilton Standard leather seals. Issued 7/2/75.	NW	62120	Pacific Propeller, Inc. P.O. Box 946 5892 S. 228th Street Kent, WA 98031
22D30, 22D40; T.C. P-736	SP952NW	Extension shaft assembly. Issued 6/19/80.	NW	62120	Pacific Propellers, Inc. P.O. Box 946 Kent, WA 98031
23D40; T.C. P-719	SP161NW	Installation of rear spider seal (limited to Wright R-1300-1B engines). Issued 2/28/75.	NW	62120	Pacific Propeller, Inc. P.O. Box 946 5892 South 228th Street Kent, WA 98031
12D40; T.C. P-257	SP725NW	"O" ring seal in place of crush gasket or cylinder head. Issued 2/26/79.	NW	62120	Pacific Propellers, Inc. P.O. Box 946 Kent, WA 98031
12D40; T.C. P-257	SP755NW	Barrell support blocks for reworked propeller blades. Issued 4/19/79.	NW	62120	Pacific Propellers, Inc. P.O. Box 946 Kent, WA 98031
12D40/6101A-10S; T.C. P-257	SP830SO	Vibration approval for single engine tractor installation only, on P & W Model R1340-AN-1 (S3H1 or S1H1 commercial designation engines. Amended 2/20/76.	SO	58580	Metropolitan Propeller Repair, Inc. of Memphis 3053 Norbrook Drive Memphis, TN 38116

*U.S. GOVERNMENT PRINTING OFFICE : 1981 0-728-119/1775